Available from

NRC/GPO Sales Program

Superintendent of Documents Government Printing Office Washington, D. C. 20402

A year's subscription consists of 12 issues for this publication.

Single copies of this publication are available from National Technical Information Service, Springfield, VA 22161

Microfiche of single copies are available from NRC/GPO Sales Program Washington, D. C. 20555

Title List of Documents Made Publicly Available

March 1-31, 1984

Division of Technical Information and Document Control Office of Administration U.S. Nuclear Regulatory Commission Washington, D.C. 20555



CONTENTS

Preface	v
Arrangement of Items by Docket Number	ix
Alphabetic Arrangement of Docket Items by Facility Name	χV
Docketed Items	1
Low Level Radwaste Disposal Sites — Docket 27	i
Domestic Licensing of Source Material — Docket 40	1
Domestic Licensing of Production and Utilization Facilities — Docket 50	8
Domestic Licensing of Special Nuclear Material — Docket 70	418
Packaging of Radioactive Material for Transport and Transportation of	
Radioactive Material Under Certain Conditions — Docket 71	422
Nondocketed Items	425
10 CFR — Commission Meeting Records	425
ACRS — Advisory Committee on Reactor Safeguards	425
ADVCM — NRC Advisory Committees	428
COMMISSION — NRC Commissioners	428
CONTRACT — NRC Contracts and Modifications	430
FOIA — Freedom of Information Act Requests and Releases	434
GEN TECH IS — Generic Technical Issues	463
I&E — Inspection and Enforcement	465
MISC — Public Document Room Miscellaneous	468
NUREG — NUREG Reports and Related Correspondence	469
ORG — Correspondence with Other Organizations	485
PR — Proposed Rule	488
PRM — Petition for Rulemaking	490
PROJ — Projects - Predocket Licensing	490
PT21 — Noncompliance Reports and Related Correspondence	490
QA999 — Quality Assurance Inspections	493
REGGD — Regulatory Guides	498
RES — Research and Technical Assistance Reports	499
REVIEW GROUP — NRC Research Review Groups	499
SECY — Position Papers Before the Commission	500
STATE PROG — State Programs	501
TOPREP — Vendor Reports and Related Correspondence	502
WASH Regulatory Publications - Pre-Nureg Series	508
WASTE MGT — Nuclear Waste Management	508
XPORTLIC — Export and Import Licenses	511
Personal Author Index	517
Corporate Source Index	549
Report Number Index	579
Cross Reference of Enclosures to Principal Documents	581
Appendix A — Definitions of Docket 50 Categories	A-1
Appendix B — Definitions of Nondocketed Categories	

PREFACE

The Title List of Documents Made Publicly Available is a monthly publication. It contains descriptions of the information received and generated by the U.S. Nuclear Regulatory Commission (NRC). This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. As used here, docketed does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records. This series of documents is indexed by a Personal Author Index, a Corporate Source Index, and a Report Number Index.

The docketed information contained in the *Title List* includes the information formerly issued through the Department of Energy publication *Power Reactor Docket Information*, last published in January 1979. Microfiche of the docketed information listed in the *Title List* is available for sale on a subscription basis from the National Technical Information Service (NTIS). See NOTES at the end of the Preface for the complete NTIS address.

We encourage your comments, criticisms, and suggestions. In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data base. In so far as possible, we would like this document to be a valuable part of your reference material.

DOCKETED ITEMS

The listings within Docket 50 are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories are:

- A. Application/construction stage documents and correspondence
- B. Utility Preliminary Safety Analysis Report (PSAR), amendments
- C. Utility Environmental Report (ER), amendments and correspondence
- D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
- E. NRC Safety Evaluation Report (SER), supplements and correspondence
- F. Security, medical, emergency and fire-protection plans
- G. Adjudicatory correspondence
- H. General correspondence
- I. Financial information
- J. Insurance and indemnity information
- K. Utility Final Safety Analysis Report (FSAR) and amendments
- L. Limited work authorization and related correspondence
- M. Antitrust correspondence
- N. Antitrust hearing transcripts
 - O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
 - P. Operating license stage documents and correspondence
 - Q. Inspection reports, IE Bulletins and correspondence
 - R. Periodic operating reports and related correspondence
 - S. Reportable occurrences. LERs and related correspondence
 - T. Hearing transcripts on non-antitrust matters
 - U. Congressional/executive correspondence
 - V. Licensing operators and related correspondence

- W Decommissioning stage documents and correspondence
- X Onsite low-level wastes storage

Appendix A sets forth those categories and describes the materials available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report

The principal elements of the entries in the list are

P Operating license stage documents & correspondence

2
3
8203090028 Responds to 820201 ltr requesting documents re environ qualification of electrical equipment. All nonproprietary repts will be provided to Franklin Research
Ctr by 820408 Proprietary repts will be provided to NRC by 820510.

4 MILLS, L M (5) Tennessee Valley Authority. 6 82/03/04 VASSALLO, D B
Operating Reactors Branch 2 (8) 1p 1216:254 24XFiche 50-259, 82/03/04,

1 NRC/PDR Document category (see Appendix A)

- 2 NRC Accession Number (year, month, day, and sequence number of item).
- 3 Description of information contained in the document.
- 4 Personal author(s) An asterisk in this position indicates that there is no personal author
- 5 Corporate, agency or nonindividual source

8203090028

- 6. Date of document described
- 7 Recipient of document and NRC or corporate affiliation
- 8 Pages in this document
- 9 The NRC 48X microfiche designation for this document. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who have access to 48X microfiche files
- 10 This three-digit portion of this entry is the number of the frame on which this document starts.
- 11 The 24X Fiche designation consists of the docket number followed by the date of the document and the accession number for the document. This designation provides the information needed by subscribers to the National Technical Information Service docket microfiche to locate the document fiche.
- 12 If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale, "Available at NTIS"; or "Available at GPO."

The Docketed Items list is arranged sequentially by Docket Number, category, and then by date of principal items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal items. In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5

NONDOCKETED ITEMS

The nondocketed items are divided into the categories used for filing and searching in the NRC Public Document Room. These categories and their symbols are

10CFR — Commission Meeting Records
ACRS — Advisory Committee on Reactor Safeguards
COMMISSION — NRC Commissioners
CONTRACT — NRC Contracts and Modifications
DISC LOSURE — Financial Disclosure Information
FOIA — Freedom of Information Act Requests and Releases
GEN TECH IS — Generic Technical Issues

I&E — Inspection and Enforcement

MISC - Public Document Room Miscellaneous

NUREG - NUREG Reports and Related Correspondence

ORG — Correspondence with Other Organizations

PR — Proposed Rule

PRM — Petition for Rulemaking

PROJ — Projects—Predocket Licensing

PT21 — Noncomphance Reports and Related Correspondence

QA999 — Quality Assurance Inspections

REGGD -- Regulatory Guides

RES — Research and Technical Assistance Reports

REVIEW GRP - NRC Research Review Groups

RM — Rulemakings

SECY — Position Papers Before the Commission

STATE PROG — State Programs

TOPREP - Vendor Reports and Related Correspondence


WASH — Regulatory Publications—Pre-NUREG Series

WASTE MGT - Nuclear Waste Management

XPORTLIC — Export and Import Licenses

Appendix B sets forth these categories and describes the material available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the nondocketed items are:



- 1. Nondocketed category
- 2. NRC Accession Number (year, month, day, and sequence number of item)
- 3. NRC Report Number
- 4. Title and description of information contained in the document
- 5. Personal author(s). An asterisk in this position indicates that there is no personal author.
- 6. Corporate, agency or other nonindividual source.
- 7. Contract or financial (F1N) number (if any). If the document has a sceondary report number, it will appear following this entry.
- 8. Secondary report number assigned by originator.
- 9. Date of document described.
- 10. NRC organizational recipient.
- 11. Pages in document.
- 12. All NUREG-series documents are available for purchase at NRC. Information on ordering documents is given below. All NUREG-series documents are also available at NTIS. Information on ordering from NTIS is also given below.
- 13. Price for which NRC sells the document.

- 14. The NRC 48X microfiche designation for this document. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who have access to 48X microfiche files
- 15. This three-digit portion of this entry is the number of the frame on which this document starts

The Nondocketed Items list is arranged sequentially by Accession Number within category. Indented items preceded by a dash are enclosures to unindented items.

NOTES:

1. The address for NRC is

Director
Division of Technical Information and Document Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

To place orders, send check or money order, payable to the Superintendent of Documents. GPO Deposit Account holders may charge their orders by calling (301) 492-9530

2. The address for NTIS is:

National Technical Information Service Springfield, Virginia 22161

To place orders for or to obtain price information about NRC publications at NTIS, either write to NTIS or call the Sales Desk at (703) 557-4650. Specify the NRC report number and title when you place your order. Publications can be charged to American Express credit cards; supply the chargecard number when placing your order.

3. The address for the PDR is:

1717 H Street, N.W. Washington, D.C. 20555

To place orders, either write to the NRC PDR or call (202) 634-3274. When ordering documents listed in this publication, please identify the Document Accession Number for each citation.

Paper copy and microfiche of the documents listed in this title list may be purchased. Reproduction charges for duplication are as follows: (1) paper to paper is \$0.05 per page except for oversized documents and engineering drawings, which vary from \$0.50 to \$1.00 per square foot; (2) microform to paper is \$0.05 a page for pages on microfiche and is \$0.20 a square foot for a full-size print or \$0.25 for a reduced-size print (18" x 24") of a drawing on an aperture card; and (3) microform to microform is \$0.10 per microfiche and \$0.20 per aperture card. Orders completed for mailing or for a special delivery service will have an additional fee for the actual mailing, shipping, or delivery service rate. Unless a user requests special packing materials, there is no additional charge by the contractor for handling and wrapping inaterials.

Please acknowledge a willingness to assume charges for all orders but do not send payments. Orders will be processed and mailed with a bill from Literature Research Company. An account may be established with the Literature Research Company by calling (703)-941-8018.

ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Docket	Name	Page	Docket	Name	Page
Low Level Rad	lwaste Disposal Sites — Docket 27		40-8585	Wyoming Mineral Corp , Lakewood, CO	б
27-039	Sheffield, IL, US Ecology, Inc	1	40-8586	Kerr-McGee Nuclear Corp ,	6
27-047	Barnwell, SC, Chem-Nuclear Systems, Inc	1	40.0400	Oklahoma City, OK	,
27-048	Richland, WA, U S Ecology, Inc	1	40-8602	Silver King Mines, Inc., Casper, WY	6
Domestic Licen	sing of Source Material — Docket 40		40-8647	Kerr-McGee Nuclear Corp , Oklahoma City, OK	6
40-0299	Union Carbide Corp , Grand Junction, CO	1	40-8663	Nuclear Dynamics, Inc., Phoenix, AZ	6
40-0481	American Bearing Co., Indianapolis, IN	2	40-8674	Plateau Resources, Ltd., Grand Junction, CO	6
40-0672	Nuclear Metals, Inc., Concord, MA	2	40-8681	Energy Fuels Nuclear, Inc., Denver, CO	6
40-1162	Western Nuclear, Inc., Jeffrey City, WY	2	40-8684	Western Nuclear, Inc., Lakewood, CO	6
40-1341	Tennessee Valley Authority, Chattanooga, TN	2	40-8698	Plateau Resources, Ltd., Grand Junction, CO	6
40-1478	Spencer Chemical Co., Kansas City, MO	2	40-8727	Kerr-McGee Nuclear Corp , Oklahoma City, OK	7
40-2061	Kerr-McGee Chemical Corp , Oklahoma City, OK	2	40-8745	Ogle Petroleum, Inc., Casper, WY	7
40-2259	Pathfinder Mines Corp., Riverton, WY	3	40-8760	Ediow International Co , Washington, DC	7
40-3392	Allied Chemical Corp , Morristown, NJ	3	40-8768	Kerr-McGee Nuclear Corp , Oklahoma City, OK	7
40-3453	Atlas Minerals, Inc., Denver, CO	3	AO 0701	,	7
40-4492	Federal-American Partners, Riverton, WY	4	40-8781	Teton Exploration Drilling Co, Inc., Casper, WY	,
40-6329	Catholic Univ. of America, Washington, DC	4	40-8783	Uranerz USA, Inc , Casper, WY	7
40-6622	Pathfinder Mines Corp , Shirley Basin, WY	4	40-8786	Uranium Resources, Inc., Richardson, TX	7
40-6659	Getty Oil CoPetrotomics Co., Shirley Basin, WY	4	40-8820	AMAX Environmental Services, Inc., Golden, CO	7
40-6920	Automation Industires, Inc., Phoenixville, PA	4	40-8824	Target Research, Inc., Wharton, NJ	7
40-6940	Kawecki Berylco Industries, Inc.,	5	40-8829	Wyoming Fuel Co., Lakewood, CO	7
	Boyertown, PA		40-8830	Honeywell, Inc , Hopkins, MN	8
40-7455	Whittaker Metals, Los Angeles, CA	5		nsing of Production and Utilization Facilities—	
40-8027	Keri-McGee Nuclear Corp , Oklahoma City, OK	5	Docket 50	The Carlotte Broads Broads	8
40-8084	Rio Algom Corp., Moab, UT	5	50-2	Univ. of Michigan Research Reactor	8
40-8102	Exxon Co., USA, Houston, TX	5	50-3	Indian Point Station, Unit 1	
40-8107	Army, Dept. of, Sacramento, CA	5	50-5	Pennsylvania State Univ. Research Reactor	9
40-8452	Bear Creek Uranium Co., Casper, WY	5	50-10	Dresden Nuclear Power Station, Unit 1	
40-8502	Wyoming Mineral Corp., Lakewood, CO	5	50-13	Babcock & Wilcox Co. Critical Facility	10
40-8584	Minerals Exploration Co., Los Angeles, CA	6	50-18	Vallecitos Boiling Water Reactor	10

Docket	Name	Page	Docket	Name	Page
50-20	Massachusetts Institute of Technology Research Reactor	10	50-249	Dresden Nuclear Power Station, Unit 3	36
50-29	Yankee-Rowe Nuclear Power Station	10	50-250	Turkey Point Plant, Unit 3	39
50-30	Plum Brook Research Reactor Facility	11	50-251	Turkey Point Plant, Unit 4	41
50-54	Union Carbide Research Reactor	11	50-254	Quad-Cities Station, Unit 1	44
50-54	Univ of Virginia Research Reactor	12	50-255	Palisades Nuclear Plant	46
50-02	General Electric Test Reactor	12	50-259	Browns Ferry Nuclear Power Station, Unit 1	47
50-70	Univ of Utah Research Reactor	12	50-260	Browns Ferry Nuclear Power Station, Unit 2	52
50-72	General Electric Nuclear Test Reactor	12	50-261	H. B. Robinson Plant, Unit 2	55
50-83	Univ of Florida Training Reactor	12	50-262	Brigham Young Univ. Research Reactor	57
50-113	Univ. of Arizona Research Reactor	12	50-263	Monticello Nuclear Generating Plant	58
50-113	Univ of Missouri Research Reactor	13	50-264	Dow Chemical Co	59
50-123	Humboldt Bay Power Plant, Unit 3	13	50-265	Quad-Cities Station, Unit 2	59
50-133	•		50-266	Point Beach Nuclear Plant, Unit 1	61
50-139	Univ of Washington Research Reactor	14	50-267	Fort St Vrain Nuclear Generating Station	64
50-142	UCLA Training Reactor	14	50-269	Oconee Nuclear Station, Unit 1	67
50-146	Saxton Nuclear Experimental Facility Big Rock Point Nuclear Plant	15	50-270	Oconee Nuclear Station, Unit 2	69
	-	15	50-271	Vermont Yankee Nuclear Power Station	70
50-156	Univ of Wisconsin Research Reactor	17	50-272	Salem Nuclear Generating Station, Unit 1	72
50-166 50-170	Univ of Maryland Research Reactor	17	50-275	Diablo Canyon Nuclear Power Plant, Unit 1	74
50-170	National Naval Medical Center	17	50-277	Peach Bottom Atomic Power Station, Unit 2	81
50-171	Peach Bottom Atonue Power Station, Unit 1	17	50-278	Peach Bottom Atomic Power Station, Unit 3	83
50-185	Purdue Univ Research Reactor	17	50-280	Surry Power Station, Unit 1	85
	Plum Brook Reactor—Mock-up	17	50-281	Surry Power Station, Unit 2	88
50-201	West Valley Reprocessing Plant	17	50-282	Prairie Island Nuclear Station, Unit 1	91
50-206	San Onofre Nuclear Station, Unit 1	18	50-285	Fort Calhoun Station, Unit 1	93
50-213	Haddam Neck Plant	21	50-286	Indian Point Station, Unit 3	94
50-219	Oyster Creek Nuclear Power Plant	23	50-287	Oconee Nuclear Station, Unit 3	97
50-220	Nine Mile Point Nuclear Station, Unit 1	26	50-289	Three Mile Island Nuclear Station, Unit 1	99
50-223	Univ. of Lowell Research Reactor	28	50-293	Pilgrim Nuclear Power Station, Unit 1	105
50-224	Univ. of California Research Reactor	28	50-295	Zion Nuclear Power Station, Unit 1	108
50-225	RPI Critical Experiment	28	50-296	Browns Ferry Nuclear Power Station, Unit 3	110
50-237	Dresden Nuclear Power Station, Unit 2	28	50-298	Cooper Nuclear Station	114
50-238	Nuclear Ship Savannah	31	50-301	Point Beach Nuclear Plant, Unit 2	116
50-244	Robert Emmet Ginna Nuclear Plant, Unit I	31	50-302	Crystal River Nuclear Plant, Unit 3	118
50-245	Millstone Nuclear Power Station, Unit 1	32	50-304	Zion Nuclear Power Station, Unit 2	120
50-247	Indian Point Station, Unit 2	34			

Docket	Name	Page	Docket	Name	Page
50-305	Kewaunee Nuclear Power Plant	123	50-358	William H Zimmer Nuclear Station, Unit 1	235
50-306	Prairie Island Nuclear Station, Unit 2	125	50-361	San Onofre Nuclear Station, Unit 2	236
50-309	Maine Yankee Atomic Power Plant	126	50-362	San Onofre Nuclear Station, Unit 3	239
50-311	Salem Nuclear Generating Station, Unit 2	128	50-364	Joseph M Farley Nuclear Plant, Unit 2	242
50-312	Rancho Seco Nuclear Generating Station	130	50-366	Edwin I Hatch Nuclear Plant, Unit 2	245
50-313	Arkansas Nuclear One, Unit 1	133	50-368	Arkansas Nuclear One, Unit 2	248
50-315	Donald C. Cook Nuclear Power Plant, Unit 1	136	50-369	William B. McGuire Nuclear Station, Unit 1	251
50-316	Donald C Cook Nuclear Power Plant, Unit 2	139	50-370	William B. McGuire Nuclear Station, Unit 2	253
50-317	Calvert Cliffs Nuclear Power Plant, Unit 1	142	50-373	LaSalle County Station, Unit 1	255
50-318	Calvert Cliffs Nuclear Power Plant, Unit 2	144	50-374	LaSalle County Station, Unit 2	258
50-320	Three Mile Island Nuclear Station, Unit 2	147	50-382	Waterford Generating Station, Unit 3	261
50-321	Edwin I. Hatch Nuclear Plant, Unit 1	151	50-383	Waterford Generating Station, Unit 4	266
50-322	Shoreham Nuclear Power Station	153	50-387	Susquehanna Steam Electric Station, Unit 1	266
50-323	Diablo Canyon Nuclear Power Plant, Unit 2	164	50-388	Susquehanna Steam Electric Station, Unit 2	269
50-324	Brunswick Steam Electric Plant, Unit 2	169	50-389	St. Lucie Plant, Unit 2	272
50-325	Brunswick Steam Electric Plant, Unit 1	172	50-390	Watts Bar Nuclear Plant, Unit 1	275
50-327	Sequoyah Nuclear Plant, Unit 1	175	50-391	Watts Bar Nuclear Plant, Unit 2	278
50-328	Sequoyah Nuclear Plant, Unit 2	177	50-395	Virgil C. Summer Nuclear Station, Unit 1	281
50-329	Midland Plant, Unit 1	179	50-396	Univ. of Virginia Cavalier Reactor	283
50-330	Midland Plant, Unit 2	186	50-397	WPPSS Nuclear Project, Unit 2	283
50-331	Duane Arnold Energy Center	193	50-400	Shearon Harris Nuclear Power Plant, Unit I	286
50-333	James A. Fitzpatrick Nuclear Power Plant	195	50-401	Shearon Harris Nuclear Power Plant, Unit 2	294
50-334	Beaver Valley Power Station, Unit 1	197	50-402	Shearon Harris Nuclear Power Plant, Unit 3	299
50-335	St Lucie Plant, Unit 1	199	50-403	Shearon Harris Nuclear Power Plant, Unit 4	300
50-336	Millstone Nuclear Power Station, Unit 2	202	50-407	Univ. of Utah Research Reactor	300
50-338	North Anna Power Station, Unit 1	204	50-409	La Crosse Boiling Water Reactor	300
50-339	North Anna Power Station, Unit 2	207	50-410	Nine Mile Point Nuclear Station, Unit 2	302
50-341	Enrico Fermi Atomic Power Plant, Unit 2	210	50-412	Beaver Valley Power Station, Unit 2	303
50-344	Trojan Nuclear Plant	212	50-413	Catawba Nuclear Station, Unit 1	305
50-346	Davis-Besse Nuclear Power Station, Unit 1	214	50-414	Catawba Nuclear Station, Unit 2	312
50-348	Joseph M. Farley Nuclear Plant, Unit 1	217	50-416	Grand Gulf Nuclear Station, Unit 1	317
50-352	Limerick Generating Station, Unit 1	221	50-417	Grand Gulf Nuclear Station, Unit 2	323
50-353	Limerick Generating Station, Unit 2	227	50-423	Millstone Nuclear Power Station, Unit 3	326
50-354	Hope Creek Nuclear Station, Unit 1	232	50-424	Vogtle Electric Generating Plant	328
50-355	Hope Creek Nuclear Station, Unit 2	234	50-425	Vogtle Electric Generating Plant	331

Docket	Name	Page	Docket	Name	Page
STN-50-437	Floating Nuclear Plant	333	STN-50-498	South Texas Project, Unit 1	393
50-438	Beliefonte Nuclear Plant, Unit I	333	STN-50-499	South Texas Project, Unit 2	394
50-439	Beilefonte Nuclear Plant, Unit 2	336	50-500	Davis-Besse Nuclear Power Station, Unit 2	395
50-440	Perry Nuclear Power Plant, Unit 1	338	50-501	Davis-Besse Nuclear Power Station, Unit 3	395
50-441	Perry Nuclear Power Plant, Unit 2	342	STN-50-508	WPPSS Nuclear Project, Unit 3	395
50-443	Seabrook Nuclear Station, Unit 1	346	STN-50-509	WPPSS Nuclear Project, Unit 5	399
50-444	Seabrook Nuclear Station, Unit 2	349	50-513	WPPSS Nuclear Project, Unit 4	401
50-445	Comanche Peak Steam Electric Station, Unit 1	35 1	50-514	Pebble Springs Nuclear Plant, Unit 1	403
50-446	Comanche Peak Steam Electric Station,	356	50-515	Pebble Springs Nuclear Plant, Unit 2	403
JU- 44 0	Unit 2	350	STN-50-518	Hartsville Nuclear Plant, Unit 1	404
STN-50-447	GESSAR-238	361	STN-50-519	Hartsville Nuclear Plant, Unit 2	404
STN-50-454	Byron Station, Unit 1	361	STN-50-520	Hartsville Nuclear Plant, Unit 3	404
STN-50-455	Byron Station, Unit 2	365	STN-50-521	Hartsville Nuclear Plant, Unit 4	404
STN-50-456	Braidwood Station, Unit 1	368	50-522	Skagit Nuclear Power Project, Unit 1	404
STN-50-457	Braidwood Station, Unit 2	370	50-523	Skagit Nuclear Power Project, Unit 2	405
50-458	River Bend Station, Unit !	373	STN-50-528	Palo Verde Nuclear Station, Unit 1	406
50-459	River Bend Station, Unit 2	376	STN-50-529	Palo Verde Nuclear Station, Unit 2	409
50-460	WPPSS Nuclear Project, Unit 1	378	STN-50-530	Palo Verde Nuclear Station, Unit 3	412
50-461	Clinton Power Station, Unit 1	381	50-537	Clinch River Breeder Reactor	415
50-462	Clinton Power Station, Unit 2	383	50-538	Memphis State Univ. Research Reactor	415
50-463	Fulton Generating Station, Unit 1	383	STN-50-546	Marble Hill Nuclear Station, Unit 1	415
50-464	Fulton Generating Station, Unit 2	384	STN-50-547	Marble Hill Nuclear Station, Unit 2	416
50-466	Allens Creek Nuclear Station, Unit 1	384	STN-50-553	Phipps Bend Nuclear Station, Unit 1	417
50-467	Allens Creek Nuclear Station, Unit 2	384	STN-50-554	Phipps Bend Nuclear Station, Unit 2	417
STN-50-470	CESSAR System 80	384	STN-50-556	Black Fox Station, Unit 1	417
50-471	Pilgrim Nuclear Power Station, Unit 2	384	STN-50-557	Black Fox Station, Unit 2	417
STN-50-482	Wolf Creek Generating Station	384	STN-50-566	Yellow Creek Nuclear Plant, Unit 1	417
STN-50-483	Callaway Plant, Unit I	388	STN-50-567	Yellow Creek Nuclear Plant, Unit 2	418
STN-50-486	Callaway Plant, Unit 2	392	Domestic Licer	sing of Special Nuclear Material - Docket 70	
STN-50-488	Perkins Nuclear Station, Unit 1	392	70-0027	Babcock & Wilcox Co., Lynchburg, VA	418
STN-50-489	Perkins Nuclear Station, Unit 2	392	70-0036	Combustion Engineering, Inc., Windsor, CT	418
STN-50-490	Perkins Nuclear Station, Unit 3	392	70-0143	Nuclear Fuel Services, Inc , Erwin, TN	418
STN-50-493	Cherokee Nuclear Station, Unit 3	392	70-0152	Purdue Univ., West Lafayette, IN	419
50-496	Montague Nuclear Power Station, Unit 1	392	70-0190	Catholic Univ. of America, Washington, DC	419
50-497	Montague Nuclear Power Station, Unit 2	392	70-0371	UNC Naval Products, Inc., Uncasville, CT	419

Docket	Name	Page	Docket	Name	Page
70-0378	Army, Dept of, Adelphi, MD	419		Radioactive Material for Transport and	
70-0398	Commerce, Dept of, Washington, DC	419	Conditions –	on of Radioactive Material Under Certain – Docket 71	
70-0474	Upsala College, East Orange, NJ	419	71-0511	Deltak Corp	422
70-0553	Army, Dept of, Sacramento, CA	420	71-0513	Edlow International Co	422
70-0687	Union Carbide Corp , Tuxedo, NY	420	71-0514	North American Inspection	422
70-0712	Kerr-McGee Nuclear Corp, Okiahoma City, OK	420	71-5450	Model RCC -1, -2, -3, -4, Westinghouse Electric Corp	422
70-0734	GA Technologies, Inc., San Diego, CA	420	71-6206	Model B, Babcock & Wilcox Co	422
70-0824	Babcock & Wilcox Co , Lynchburg, VA	420	71-6406	Model None, Energy, Dept of	422
70-0920	Rensselaer Polytechnic Institute, Troy, NY	420	71-6601	Model. CNS 8-120, Chem-Nuclear	422
70-0925	Kerr-McGee Nuclear Corp., Oklahoma City, OK	420	71-9001	Systems, Inc. Model IF-300, General Electric Co	422
70-0984	Battelle Memorial Institute, Richland, WA	420	71-9009	Model: FL 10-1, General Electric Co.	423
70-1100	Combustion Engineering, Inc , Windsor, CT	420	71-9027	Model 741 & 741E, Technical Operations,	423
70-1113	General Electric Co , Wilmington, NC	421	T1 0014	Inc.	422
70-1143	Westinghouse Electric Corp , Pittsburgh, PA	421	71-9036	Model: C-1, Source Production & Equipment Co, Inc.	423
70-1151	Westinghouse Electric Corp., Pittsburgh, PA	421	71-9071	Model: AP-101, ANEFCO, Inc	423
70-1193	Kerr-McGee Nuclear Corp., Oklahoma City, OK	421	71-9079	Model: HN-100, Series 2 & 2A, Hittman Nuclear & Development Corp	423
70-1201	Babcock & Wilcox Co., Lynchburg, VA	421	71-9080	Model: HN-600, NUPAC 7-100 & CNS 7-100, Hittman Nuclear & Development	423
70-1257	Exxon Nuclear Co , Inc., Richland, WA	421		Corp	
70-1311	Air Force, Dept of, USAF, Academy, CO	421	71-9108	Model CNS 6-75, Chem-Nuclear Systems, Inc	423
70-1359	IRT Corp., San Diego, CA	421	71-9134	Model ETR, Exxon Nuclear Idaho Co	423
70-1621	Duquesne Light Co , Pittsburgh, PA	421	71-9134	Model: 20-VS & 40-VS, Gulf Nuclear, Inc	423
70-1717	Norwalk Hospital, Norwalk, CT	422	71-9161	Model R, Gulf Nuclear, Inc.	423
70-2199	Veterans Administration Medical Center, Washington, DC	422	71-9161	Model, GNM-20, Gulf Nuclear, Inc.	423
70-2946	Louisiana Power & Light Co,	422	71-9175	Model CNS6-80B Nuclear Packaging, Inc	423
/\/^29 4 U	New Orleans, LA	744	71-9173	Model: CASTOR V, Gesellschaft Fuer	423
70-2955	Edlow International Co., Washington, DC	422	11-3130	Nuklear Service, MBH	,
70-2988	Philadelphia Electric Co , Philadelphia, PA	422			

1
·
;
1 1 1

ALPHABETIC ARRANGEMENT OF DOCKET ITEMS BY FACILITY NAME

Name	Docket	Page	Name	Docket	Page
Low Level Radwaste Disposal Sites — Docket 2	27		Minerals Exploration Co , Los Angeles, CA	40-8584	6
Barnwell, SC, Chem-Nuclear Systems, Inc	27-047	l	Nuclear Dynamics, Inc , Phoenix, AZ	40-8663	6
Richland, WA, US Ecology, Inc	27-048	1	Nuclear Metals, Inc., Concord, MA	40-0672	2
Sheffield, IL, U.S Ecology, Inc	27-039	1	Ogle Petroleum, Inc , Casper, WY	40-8745	7
Domestic Licensing of Source Material — Dock	set 40		Pathfinder Mines Corp , Riverton, WY	40-2259	3
Allied Chemical Corp , Morristown, NJ	40-3392	3	Pathfinder Mines Corp , Shirley Basin, WY	40-6622	4
AMAX Environmental Services, Inc., Golden, CO	40-8820	7	Plateau Resources, Ltd , Grand Junction, CO	40-8674	6
American Bearing Co, Indianapolis, IN	40-0481	2	Plateau Resources, Ltd.,	40-8698	6
Army, Dept. of, Sacramento, CA	40-8107	5	Grand Junction, CO	10,0001	-
Atlas Minerals, Inc., Denver, CO	40-3453	3	Rio Algom Corp., Moab, UT	40-8084	5
Automation Industries, Inc., Phoenixville, PA	40-6920	4	Silver King Mines, Inc., Casper, WY	40-8602	6
Bear Creek Uranium Co., Casper, WY	40-8452	5	Spencer Chemical Co., Kansas City, MO	40-1478	2
Catholic Univ. of America, Washington, DC	40-6329	4	Target Research, Inc., Wharton, NJ	40-8824	7
Edlow International Co., Washington, DC	40-8760	7	Tennessee Valley Authority, Chattanooga, TN	40-1341	2
Energy Fuels Nuclear, Inc., Denver, CO	40-8681	6	Teton Exploration Drilling Co., Inc., Casper, WY	40-8781	7
Exxon Co., USA, Houston, TX	40-8102	5	Union Carbide Corp , Grand Junction, CO	40-0299	1
Federal-American Partners, Riverton, WY	40-4492	4	Uranerz USA, Inc., Casper, WY	40-8783	7
Getty Oil CoPetrotomics Co , Shirley Basin, WY	40-6659	4	Uranium Resources, Inc., Richardson, TX	40-8786	7
Honeywell, Inc., Hopkins, MN	40-8830	8	Western Nuclear, Inc., Jeffrey City, WY	40-1162	2
Kawecki Berylco Industries, Inc.,	40-6940	5	Western Nuclear, Inc., Lakewood, CO	40-8684	6
Boyertown, PA	10 0240	J	Whittaker Metals, Los Angeles, CA	40-7455	5
Kerr-McGee Chemical Corp., Oklahoma City, OK	40-2061	2	Wyoming Fuel Co., Lakewood, CO	40-8829	7
Kerr-McGee Nuclear Corp.,	40-8027	5	Wyoming Mineral Corp , Lakewood, CO	40-8502	5
Oklahoma City, OK	40-6027	5	Wyoming Mineral Corp., Lakewood, CO	40-8585	6
Kerr-McGee Nuclear Corp., Oklahoma City, OK	40-8586	6	Domestic Licensing of Production and Utilizati Docket 50	ion Facilities —	-
Kerr-McGee Nuclear Corp., Oklahoma City, OK	40-8647	6	Allens Creek Nuclear Station, Unit 1	50-466	384
Kerr-McGee Nuclear Corp.,	40-8727	7	Allens Creek Nuclear Station, Unit 2	50-467	384
Oklahoma City, OK	4U-0 <i>141</i>	,	Arkansas Nuclear One, Unit 1	50-313	133
Kerr-McGee Nuclear Corp , Oklahoma City, OK	40-8768	7	Arkansas Nuclear One, Unit 2	50-368	248

Name	Docket	Page	Name	Docket	Page
Babcock & Wilcox Co., Critical Facility	50-13	10	Davis-Besse Nuclear Power Station, Unit 2	50-500	395
Beaver Valley Power Station, Unit 1	50-334	197	Davis-Besse Nuclear Power Station, Unit 3	50-501	395
Beaver Valley Power Station, Unit 2	50-412	303	Diable Canyon Nuclear Power Plant, Unit 1	50-275	74
Bellefonte Nuclear Plant, Unit 1	50-438	333	Diablo Canyon Nuclear Power Plant, Unit 2	50-323	164
Bellefonte Nuclear Plant, Unit 2	50-439	336	Donald C Cook Nuclear Power Plant, Unit 1	50-315	136
Big Rock Point Nuclear Plant	50-155	15	Donald C. Cook Nuclear Power Plant, Unit 2	5 0-316	139
Black Fox Station, Unit 1	STN-50-556	417	Dow Chemical Co.	50-264	59
Black Fox Station, Unit 2	STN-50-557	417	Dresden Nuclear Power Station, Unit 1	50-10	9
Braidwood Station, Unit 1	STN-50-456	368	Dresden Nuclear Power Station, Unit 2	50-237	28
Braidwood Station, Unit 2	STN-50-457	370	Dresden Nuclear Power Station, Unit 3	50-249	36
Brigham Young Univ. Research Reactor	50-262	57	Duane Arnold Energy Center	50-331	193
Browns Ferry Nuclear Power Station, Unit 1	50-259	47	Edwin I Hatch Nuclear Plant, Unit I	50-321	151
Browns Ferry Nuclear Power Station, Unit 2	50-260	52	Edwin I. Hatch Nuclear Plant, Unit 2	50-366	245
Browns Ferry Nuclear Power Station, Unit 3	50-296	110	Enrico Fermi Atomic Power Plant, Unit 2	50-341	210
Brunswick Steam Electric Plant, Unit 1	50-325	172	Floating Nuclear Plant	STN-50-437	333
Brunswick Steam Electric Plant, Unit 2	50-324	169	Fort Calhoun Station, Unit 1	50-285	93
Byron Station, Unit 1	STN-50-454	361	Fort St. Vrain Nuclear Generating Station	50-267	64
Byron Station, Unit 2	STN-50-455	365	Fulton Generating Station, Unit 1	50-463	383
Callaway Plant, Unit 1	STN-50-483	388	Fulton Generating Station, Unit 2	50-464	384
Callaway Plant, Unit 2	STN-50-486	392	General Electric Nuclear Test Reactor	50-73	12
Calvert Cliffs Nuclear Power Plant, Unit I	50-317	142	General Electric Test Reactor	50-70	12
Calvert Cliffs Nuclear Power Plant, Unit 2	50-318	144	GESSAR-238	STN-50-447	361
Catawba Nuclear Station, Unit 1	50-413	305	Grand Gulf Nuclear Station, Unit 1	50-416	317
Catawba Nuclear Station, Unit 2	50-414	312	Grand Gulf Nuclear Station, Unit 2	50-417	323
CESSAR System 80	STN-50-470	384	H. B. Robinson Plant, Unit 2	50-261	55
Cherokee Nuclear Station, Unit 3	STN-50-493	392	Haddam Neck Plant	50-213	21
Clinch River Breeder Reactor	50-537	415	Hartsville Nuclear Plant, Unit 1	STN-50-518	404
Clinton Power Station, Unit 1	50-461	381	Hartsville Nuclear Plant, Unit 2	STN-50-519	404
Clinton Power Station, Unit 2	50-462	383	Hartsville Nuclear Plant, Unit 3	STN-50-520	404
Comanche Peak Steam Electric Station, Unit 1	50-445	351	Hartsville Nuclear Plant, Unit 4	STN-50-521	404
Comanche Peak Steam Electric Station,	50-446	356	Hope Creek Nuclear Station, Unit 1	50-354	232
Unit 2			Hope Creek Nuclear Station, Unit 2	50-355	234
Cooper Nuclear Station	50-298	114	Humboldt Bay Power Plant, Unit 3	50-133	13
Crystal River Nuclear Plant, Unit 3	50-302	118	Indian Point Station, Unit 1	50-3	8
Davis-Besse Nuclear Power Station, Unit 1	50-346	214	Indian Point Station, Unit 2	50-247	34

Name	Docket	Page	Name	Docket	Page
Indian Point Station, Unit 3	50-286	94	Palo Verde Nuclear Station, Unit 2	STN-50-529	409
James A Fitzpatrick Nuclear Power Plant	50-333	195	Palo Verde Nuclear Station, Unit 3	STN-50-530	412
Joseph M. Farley Nuclear Plant, Unit 1	50-348	217	Peach Bottom Atomic Power Station, Unit 1	50-171	17
Joseph M. Farley Nuclear Plant, Unit 2	50-364	242	Peach Bottom Atomic Power Station, Unit 2	50-277	81
Kewaunee Nuclear Power Plant	50-305	123	Peach Bottom Atomic Power Station, Unit 3	50-278	83
La Crosse Boiling Water Reactor	50-409	300	Pebble Springs Nuclear Plant, Unit 1	50-514	403
LaSalle County Station, Unit 1	50-373	255	Pebble Springs Nuclear Plant, Unit 2	50-515	403
LaSalle County Station, Unit 2	50-374	258	Pennsylvania State Univ. Research Reactor	50-5	9
Limerick Generating Station, Unit 1	50-352	221	Perkins Nuclear Station, Unit 1	STN-50-488	392
Limerick Generating Station, Unit 2	50-353	227	Perkins Nuclear Station, Unit 2	STN-50-489	392
Maine Yankee Atomic Power Plant	50-309	126	Perkins Nuclear Station, Unit 3	STN-50-490	392
Marble Hill Nuclear Station, Unit 1	STN-50-546	415	Perry Nuclear Power Plant, Unit 1	50-440	338
Marble Hill Nuclear Station, Unit 2	STN-50-547	416	Perry Nuclear Power Plant, Unit 2	50-441	342
Massachusetts Institute of Technology Research Reactor	50-20	10	Phipps Bend Nuclear Station, Unit 1	STN-50-553	417
Memphis State Univ. Research Reactor	50-538	415	Phipps Bend Nuclear Station, Unit 2	STN-50-554	417
Midland Plant, Unit 1	50-329	179	Pilgrim Nuclear Power Station, Unit 1	50-293	105
Midland Plant, Unit 2	50-330	186	Pilgrim Nuclear Power Station, Unit 2	50-471	384
Millstone Nuclear Power Station, Unit 1	50-245	32	Plum Brook ReactorMock-Up	50-185	17
Millstone Nuclear Power Station, Unit 2	50-336	202	Plum Brook Research Reactor Facility	50-30	11
Millstone Nuclear Power Station, Unit 3	50-423	326	Point Beach Nuclear Plant, Unit 1	50-266	61
Montague Nuclear Power Station, Unit 1	50-496	392	Point Beach Nuclear Plant, Unit 2	50-301	116
Montague Nuclear Power Station, Unit 2	50-497	392	Prairie Island Nuclear Station, Unit 1	50-282	91
Monticello Nuclear Generating Plant	50-263	58	Prairie Island Nuclear Station, Unit 2	50-306	125
National Naval Medical Center	50-170	17	Purdue Univ. Research Reactor	50-182	17
Nine Mile Point Nuclear Station, Unit 1	50-220	26	Quad-Cities Station, Unit 1	50-254	44
Nine Mile Point Nuclear Station, Unit 2	50-410	302	Quad-Cities Station, Unit 2	50-265	59
North Anna Power Station, Unit 1	50-338	204	Rancho Seco Nuclear Generating Station	50-312	130
North Anna Power Station, Unit 2	50-339	207	River Bend Station, Unit 1	50-458	373
Nuclear Ship Sayannah	50-238	31	River Bend Station, Unit 2	50-459	376
Oconee Nuclear Station, Unit 1	50-269	67	Robert Emmet Ginna Nuclear Plant, Unit 1	50-244	31
Oconee Nuclear Station, Unit 2	50-270	69	RPI Critical Experiment	50-225	28
Oconec Nuclear Station, Unit 3	50-287	97	Salem Nuclear Generating Station, Unit 1	50-272	72
Oyster Creek Nuclear Power Plant	50-267	23	Salem Nuclear Generating Station, Unit 2	50-311	128
Palisades Nuclear Plant	50-219	46	San Onofre Nuclear Station, Unit 1	50-206	18
Palo Verde Nuclear Station, Unit 1	50-255 STN-50-528	406	San Onofre Nuclear Station, Unit 2	50-361	236
and acide raciear pration, Oillt I	9111-7A-770	400			

Name	Docket	Page	Name	Docket	Page
San Onofre Nuclear Station, Unit 3	50-362	239	Univ of Utah Research Reactor	50-407	300
Saxton Nuclear Experimental Facility	50-146	15	Univ of Utah Research Reactor	50-72	12
Seabrook Nuclear Station, Unit 1	50-443	346	Univ of Virginia Cavalier Reactor	50-396	283
Seabrook Nuclear Station, Unit 2	50-444	349	Univ of Virginia Research Reactor	50-62	12
Sequoyah Nuclear Plant, Unit 1	50-327	175	Univ of Washington Research Reactor	50-139	14
Sequoyah Nuclear Plant, Unit 2	50-328	177	Univ. of Wisconsin Research Reactor	50-156	17
Shearon Harris Nuclear Power Plant, Unit 1	50-400	286	Vallectos Boiling Water Reactor	50-18	10
Shearon Harris Nuclear Power Plant, Unit 2	50-401	294	Vermont Yankee Nuclear Power Station	50-271	70
Shearon Harris Nuclear Power Plant, Unit 3	50-402	299	Virgil C Summer Nuclear Station, Unit 1	50-395	281
Shearon Harris Nuclear Power Plant, Unit 4	50-403	300	Vogtle Electric Generating Plant	50-424	328
Shoreham Nuclear Power Station	50-322	153	Vogtle Electric Generating Plant	50-425	331
Skagit Nuclear Power Project, Unit I	50-522	404	Waterford Generating Station, Unit 3	50-382	261
Skaga Nuclear Power Project, Unit 2	50-523	405	Waterford Generating Station, Unit 4	50-383	266
South Texas Project, Unit 1	STN-50-498	393	Watts Bar Nuclear Plant, Unit 1	50-390	275
South Texas Project, Unit 2	STN-50-499	394	Watts Bar Nuclear Plant, Unit 2	50-391	278
St Lucie Plant, Umt 1	50-335	199	West Valley Reprocessing Plant	50-201	17
St Lucie Plant, Unit 2	50-389	272	William B. McGuire Nuclear Station, Unit 1	50-369	251
Surry Power Station, Unit 1	50-280	85	William B McGuire Nuclear Station, Unit 2	50-370	253
Surry Power Station, Unit 2	50-281	88	William H. Zimmer Nuclear Station, Unit 1	50-358	235
Susquehanna Steam Electric Station, Unit 1	50-387	266	Wolf Creek Generating Station	STN-50-482	384
Susquehanna Steam Electric Station, Unit 2	50-388	269	WPPSS Nuclear Project, Unit 1	50-460	378
Three Mile Island Nuclear Station, Unit 1	50-289	99	WPPSS Nuclear Project, Unit 2	50-397	283
Three Mile Island Nuclear Station, Unit 2	50-320	147	WPPSS Nuclear Project, Unit 3	STN-50-508	395
Trojan Nuclear Plant	50-344	212	WPPSS Nuclear Project, Unit 4	50-513	401
Turkey Point Plant, Unit 3	50-250	39	WPPSS Nuclear Project, Unit 5	STN-50-509	399
Turkey Point Plant, Unit 4	50-251	41	Yankee-Rowe Nuclear Power Station	50-29	10
UCLA Training Reactor	50-142	14	Yellow Creek Nuclear Plant, Unit 1	STN-50-566	417
Union Carbide Research Reactor	50-54	11	Yellow Creek Nuclear Plant, Unit 2	STN-50-567	418
Univ. of Arizona Research Reactor	50-113	12	Zion Nuclear Power Station, Unit 1	50-295	108
Univ of California Research Reactor	50-224	28	Zion Nuclear Power Station, Unit 2	50-304	120
Univ of Florida Training Reactor	50-83	12	Domestic Licensing of Special Nuclear Material — Docket 70		
Univ. of Lowell Research Reactor	50-223	28	Air Force, Dept. of, USAF Academy, CO	70-1311	421
Univ of Maryland Research Reactor	50-166	17	Army, Dept of, Adelphi, MD	70-0378	419
Univ. of Michigan Research Reactor	50-2	8	Army, Dept. of, Sacramento, CA	70-0553	420
Univ of Missouri Research Reactor	50-123	13	Babcock & Wilcox Co., Lynchburg, VA	70-1201	421

Name	Docket	Page	Name	Docket	Page
Babcock & Wilcox Co , Lynchburg, VA	70-0027	418	Westinghouse Electric Corp , Pittsburgh, PA	70-1151	421
Babcock & Wilcox Co , Lynchburg, VA	70-0824	420	Packaging of Radioactive Material for Transpo		
Battelle Memorial Institute, Richland, WA	70-0984	420	Transportation of Radioactive Material Und Conditions — Docket 71	er Certain	
Catholic Univ of America, Washington, DC	70-0190	419	Deltak Corp	71-0511	_422
Combustion Engineering, Inc., Windsor, CT	70-0036	418	Edlow International Co	71-0513	422
Combustion Engineering, Inc., Windsor, CT	70-1100	420	Model. 20-VS & 40-VS, Gulf Nuclear, Inc	71-9160	423
Commerce, Dept of, Washington, DC	70-0398	419	Model 741 & 741E, Technical Operations, Inc	71-9027	423
Duquesne Light Co , Pittsburgh, PA	70-1621	421	Model: AP-101, ANEFCO, Inc	71-9071 71-6206	423 422
Edlow International Co., Washington, DC	70-2955	422	Model B, Babcock & Wilcox Co.		
Exxon Nuclear Co, Inc, Richland, WA	70-1257	421	Model: C-1, Source Production &	71-9036	423
GA Technologies, Inc., San Diego, CA	70-0734	420	Equipment Co , Inc	71-9030	423
General Electric Co , Wilmington, NC	70-1113	421	Model. CASTOR V, Gesellschaft Fuer Nuklear Service, MBH	71-9190	423
IRT Corp., San Diego, CA	70-1359	421	Model CNS 6-75, Chem-Nuclear Systems,	71-9108	423
Kerr-McGee Nuclear Corp ,	70-1193	421	Inc	71-7100	
Oklahoma City, OK Kerr-McGee Nuclear Corp., Oklahoma City, OK	70-0712	420	Model. CNS 8-120, Chem-Nuclear Systems, Inc	71-6601	422
Kerr-McGee Nuclear Corp.,	·	420	Model CNS6-80B, Nuclear Packaging, Inc	71-9175	423
Oklahoma City, OK	70-0323	420	Model ETR, Exxon Nuclear Idaho Co.	71-9134	423
Louisiana Power & Light Co., New Orleans, LA	70-2946	422	Model. FL 10-1, General Electric Co	71-9009	423
Norwalk Hospital, Norwalk, CT	70-1717	422	Model GNM-20, Gulf Nuclear, Inc.	71-9162	423
Nuclear Fuel Services, Inc., Erwin, TN	70-1717	418	Model HN-100, Series 2 & 2A, Hittman Nuclear & Development Corp.	71-9079	423
Philadelphia Electric Co., Philadelphia, PA	70-2988	422	Model: HN-600, NUPAC 7-100 & CNS	71-9080	423
Purdue Univ., West Lafayette, IN	70-2366	419	7-100, Hutman Nuclear & Development	71 7000	.,(25
Rensselaer Polytechnic Institute, Troy, NY	70-0132	420	Model: IF-300, General Electric Co	71-9001	422
UNC Naval Products, Inc., Uncasville, CT	70-0320	419	Model: None, Energy, Dept. of	71-6406	422
Union Carbide Corp., Tuxedo, NY	70-0371	420	Model: R, Gulf Nuclear, Inc	71-9161	423
Upsala College, East Orange, NJ			Model, RCC -1, -2, -3, -4, Westinghouse	71-5450	422
	70-0474	419	Electric Corp	11-2430	·T 44
Veterans Administration Medical Center, Washington, DC	70-2199	422	North American Inspection 71-		422
Westinghouse Electric Corp., Pittsburgh, PA	70-1143	421			

DOCKETED ITEMS

LOW LEVEL RADWASTE DISPOSAL SITES

DOCKET 27-039 SHEFFIELD, IL, U 8 ECOLOGY, INC

- 8403010344 Requests correction in distribution list to reflect J8 Goodie as assistant atty general GOODIE.J S Illinois. State of 84/02/10 Division of Waste Management. 1p 22449 353
- 8403160077 Trip rept of attendance at Sheffield Tritium Migration Study
 Steering Committee 840119 meeting re fiscal errangements,
 groundwater tracer study, temp surveys & addl date needs
 QUDDE.D. Gotechnical Branch (Post 831001) SHAFFNER, J A
 Law-Level Waste & Uranium Recovery Projects Branch 84/02/21
 H1301NBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch
 KNAPP.M. R Geotechnical Branch (Post 831001) 2pp 22662 284
- 8403200317 Forwards agenda for 840228-29 technical meetings at Bpringfield. IL to review existing monitoring programs & possible monitoring program after site closure LASH, T R Illinois, State of 84/02/21 Illinois, State of 3pp. 22709-144.
- 8403070380 Notification of contract execution, Mod 5, to "Evaluation of Locations & Rates of Groundwater Discharge from Sheffield Low level Waste Disposal Facility "Contractor USOS PAGE.M Technical Assistance Contracts Branch NRC-02-80-069 84/03/01. DAVIS, J Office of Nuclear Material Safety & Safeguards, Director GOODE, D J NRC No Detailed Affiliation Oiven 1p. 22367,041
- --8403070383 Mod 5, changing name of project officer, to "Evaluation of Locations & Rates of Groundwater Discharge from Sheffield Low Level Wasts Disposal Facility " * Interior, Dept of, Geological Burvey SMITH, P Division of Contracts NRC-02-80-069, 84/03/01. 1p 22567 042.
- 8403220218 Informs of establishment of task working group to formulate alternative strategies for transfer of Bheffield low level waste disposal facility to DDE Response requested by 840308 as to assignment of staff representatives.

 BROWNING, R. E. Division of Waste Management 84/03/09 KNAPP, M Geotechnical Branch (Post 831001) RUNTING, J Division of Waste Management. H1001NB0THAM: L. Low-Level Waste & Uranium Recovery Projects Branch 2pp 22721,357

DOCKET 27-047 BARNWELL, BC, CHEM-NUCLEAR SYSTEMS, INC.

8403150316 Forwids summary, in grams, of BNM disposed of at site during CVB3 under License 12-13336-01 BNM amounted to 195,104 37 g BTILL, J. Chem-Nuclear Bystems, Inc. 84/02/28 Division of Waste Management. 2pp. 22649:307.

DOCKET 27-040 RICHLAND, WA. U. B. ECOLDGY, INC.

- 8403020377 Forwards summary of technical update meeting on 840119 in USQB ofcs in Urbana, IL re tritium migration investigation at Sheffield low level waste disposal site, GAYNOR, R. U. B. Ecology, Inc. (formerly Nuclear Engineering, Inc.) 84/02/13 U.S. Ecology, Inc. (formerly Nuclear Engineering, Inc.), 3pp. 22492.187
- 8403010341 Forwards monthly SNM receipt & burial rept for Jan 1984 & rept of isotopic activity as required by State of WA W/o encls.

 WRIGHT, B. V. U. B. Ecology, Inc. (formerly Nuclear Engineering, Inc.)
 84/02/14. BROWNING, B. Low Level Waste Licensing Branch ip 22449: 354.

- 8403010349 Requests specific approval for one-time disposal of 5 Ci Pu-238 neutron source Info re source described in attached 831011 ltr WALLER,W K U S Ecology, Inc (formerly Nuclear Engineering, Inc) 84/02/14 SCHAFFNER,J NRC - No Detailed Affiliation Oiven 4pp 20409 388
- 8403150317 Forwards FR notice of issuance & negative declaration on license amend re SNM disposal for FR publication H1001NBOTHAM, L Low-Lavel Waste & Uranium Recovery Projects Branch 84/02/24 FELTON, J M Division of Rules and Records 4pp 22649 303
- 8403150283 Forwards Amend 4 to License 16-19204-01 Amend authorizes receipt & disposal of SNM at US Ecology, Inc low level radwaste burial facility in Hanford, HA HIGGINBOTHAM, L. Low Level Waste Licensing Branch 84/02/27, SCOVILLE, J. J. U. B. Ecology, Inc. (formerly Nuclear Engineering, Inc.) 2pp. 22662 001
- --8403130201 Amend 4 to Matl/Byproduct License 16-19204-01, reflecting waste manifest, waste form & classification requirements contained in 10CFR61 & 20 311 HIGGINEOTHAM, L Low-Level Waste & Uranium Recovery Projects Branch 84/02/16 25pp 22662 003
- 8403160094 Advises that App A of SNM license unchanged in order to maintain consistency w/App A of State of WA license, per Dec 1983 telcon re inconsistent sole-use vehicle limits & removable contamination limits
 BHAFFNER, J A Low-Level Waste & Uranium Recovery Projects Branch 84/02/27 THOMAS.B Region 5. Office of Director 1p. 22662 275
- B403220235 Responds to B40214 1tr requesting one-time approval of disposal of 5 Ci Pu-238 neutron source NRC needs data necessary to make independent determination of no significant environ impact due to disposal of package SHAFFNER.J A Lou-Level Waste & Uranium Recovery Projects Branch B4/03/05 WALLER.K U S Ecology, Inc (formerly Nuclear Engineering, Inc.) 2pp 22719 357

DOMESTIC LICENSING OF SOURCE MATERIAL

- DOCKET 40-0299 UNION CARBIDE CORP , GRAND JUNCTION, CO
- 8403010012 Requests reconsideration of classification of 830810 submittal to License SUA-648 re testing clay cap & cover mati for inactive tailings area as minor amend Submittal not request for amend LyONB, J. Union Carbide Corp 83/08/16 PETTINGILL, H.A. Uranium Recovery Field Office ip 82479 340
- 8403:50284 Water level evaluation rept for Jan 1984 Production from pumpback well improved compared to Dec. but remains below vol required for reversal of hydraulic gradient W/84013: ltr LYONS, J. Union Carbide Corp 84/01/3: PETTINGILL, H Uranium Recovery Field Office 17pp 22448 227
- 8403130210 Advises that review of expansion application & periodic revs temporarily suspended pending successful resolution of A-7 sespage problem ERICKBONJ Wyoming, State of 84/02/11 LYONS,P J Union Carbide Corp 2pp 22647.050
- 8403070266 Forwards payment for Enforcement Action 83-108 dtd 840210 NRC findings disputed SHORTRIDOE,E W. Union Carbide Corp 84/02/28. Director's Office, Office of Inspection and Enforcement 2pp 22547:316

- DOCKET 40-0481 AMERICAN BEARING CO . INDIANAPOLIS, IN
- 8403060490 Forwards Oak Ridge Associated Univs final rept on
- decontamination of American Bearing Corp facilities in Indianapolis: IN M/o encl CROM-W T Uranium Fuel Licensing Branch 84/02/27 Licensing Branch 1p 22552 209 Uranium Fuel
- DOCKET 40-0472 NUCLEAR METALS, INC . CONCORD, MA
- 8403000136 Ack receipt of 840115 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 40-0672/83-08 MARTIN-T T Division of Engineering & Technical Programs 84/02/24 VUMBACO,F J Nuclear Metals, Inc. 1p 22488 iii
- --8403050144 Responds to NRC 830805 ltr re Item 7 listed in Confirmatory Action Ltr 83-08 Descriptions of listed programs submitted for NRC review Addl info forwarded to Matl Licensing Branch, Div of Fuel Cycle & Matl Safety VUMBACD.F J Nuclear Ketals, Inc. 84/01/15 MARTIN.T T VUMBACO.F.J. Nuclear Metals. Inc. 84/01/15 MARTIN.T T Division of Engineering & Technical Programs 2pp. 2248 22468 112
- --8403050150 Forwards, for review, info for inclusion into renewal application for License SMB-179 based on request from Region 1 & documented in 830805 Confirmatory Action Ltr 83-08 VWSMACO,F J Nuclear Metals. Inc. 84041/15 WANG,J C Division of Fuel Cycle & Material Safety 53pp 22488 114
- --8403050156 "Rept of In Vivo Counting for Nuclear Metals, Inc. " Work performed on 820718-22 QUEHRING, J. S. Helgeson Nuclear Services, Inc. 83/10/05 53pp
- 8403220090 Ack receipt of 840217 ltr informing NRC of steps taken to correct violations noted in IE insp HARTIN.T T Division of Engineering & Technical Programs 84/03/09 TUFFIN.H B Nuclear Netals, Inc ip 22716 298
- --8403220092 Responds to NRC 840117 ltr re violations noted in IE insp Corrective actions radiological work audit program & format revised VUMBACO,F J Nuclear Metals, Inc. 84/02/17 MARTIN,T T Division of Engineering & Technical Programs 12pp 22716 299
- DOCKET 40-1162 WESTERN NUCLEAR, INC , JEFFREY CITY, WY
- 8403200343 Submits review of First Second & Third Quarter 1983 water quality sampling monitoring for Sglit Rock Mill Movement of contaminated waters datected KONMINSHI, CR. PETTENGILL, M. J. Uranium Recovery Field Office 84/02/09 Uranium Recovery Field Office 5pp 22709 114
- POCKET 40-1341 TENNESSEE VALLEY AUTHORITY, CHATTANOGGA, IN
- 6403220220 Forwards revised, "Edgemont Mill Decommissioning Project Mealth Physics Manual" in response to E Haukins concerns
 Revised info provided as clarification & elaboration of
 statements made in original manual
 MILLS: M Tennessee Valley Authority 84/01/16 SMIT
 Uranium Recovery Field Office 2pp 22721 236 84/01/16 SMITH-R D
- --8403220224 Rev | to "Edgemont Mill Decommissioning Health Physics Tennessee Valley Authority 84/01/31 110pp 22721 241
- 8403150237 Forwards rept for Nov 1783 on status of projects active under FIN A-9350
 KELLY, M J Dak Ridge National Laboratory FIN A-9350 83/12/14
 HANKINS,E F Uranium Recovery Field Office 4pp 22649 012
- 8403150229 Provides add1 info in response to concerns raised during NRC review of proposed Pond 10 mods Mods include const of new isolated elevated pand Weekly visual insp will be conducted for all Pond 10 dikes
 MILLS,L M Tennessee Valley Authority 84/01/04 SMITH,R D
 Uranium Recovery Field Office 3pp 22649 027
- 6403150230 Forwards status rept for Dec 1983 on projects active under FIN A-9350 FIN A-4330 KELLY,H J Oak Ridge National Laboratory FIN A-9350 B4/01/18 HAWKINB,E F Uranium Recovery Field Office App 22649 023

- 8403260102 Forwards IE Insp Rept 40-1341/84-01 on 840123 No violations HALL:RE Region 4. Office of Director 84 Tennessee Valley Authority 2pp 22758 245 84/02/22 DONOVAN, T K
- --8403260109 IE Insp Rept 40-1341/84-01 on 840123 No violations or deviations identified Major areas inspected organization & administration, radiation protection, respiratory protection & independent measurements
 SPITZBERO, D B , JJERREE, C C , EVERETT, R R Region 4, Office of Director 84/02/21 4pp 22758 247
- 8403200333 Amends Condition 31 to License SUA-816 Amend approves radiological safety plan & procedures in health physics manual as basis for implementing radiation safety programs SMITH-R D Uranium Recovery Field Office 84/02/27 Tennet Valley Authority 2pp 22709 124 Tennessee
- --8403200335 Safety evaluation re review of health physics manual for decommissioning Edgement Hill Manual acceptable HAMKINS.E F., JIERREE, C Uranium Recovery Field Office 84/02/23 opp 22709 126
- DOCKET 40-1478 SPENCER CHEMICAL CO : KANSAS CITY: MO
- B403260116 FDIA request for five categories of documents re facilities BARNES,C Affiliation Not Assigned 83/12/02 FELTON,J M Division of Rules and Records 1p 22763:333
- 8403260123 Partial response to FDIA request for five categories of documents to Kerr-McGae Dil Industries, Inc Forwards documents listed on app Review of addl documents subj to
- --8403260127 Repts 660207 explosion due to accumulation of hydrogen gas, killing operator & injuring two other employees Operation of thorium process line terminated WULLER.9 E Xerr-McGee Corp 66/03/03 PRICE.E R Atomic Energy Commission 2pp 22763 336
- --8403260136 Forwards investigation rept re 660207 explosion at facility Licenses evaluation of hazards involved in processing source math should be reviewed W/o stated ancis DUBINSMIL Atomic Energy Commission 66/08/02 PAGE, R G Atomic Energy Commission 4pp 22763 340
- --BA03260141 Confirms that Enforcement Branch will not communicate w/licensee re compliance investigation rept concerning explosion on 660207 No items of noncompliance noted during investigation PAGE.R O Atomic Energy Commission 66/08/17 Atomic Energy PAGE.R O Atomic Energy Commission 66/08/17 Commission 1p 22763 344 Atomic Energy
- --B403260148 Forwards Region IV 660727 memo re results of survey of licensee facility at Cushing,OK Licensee measurements, as reported in 660609 ltr, substantiated by Region IV findings ROV.M Atomic Energy Commission 66/08/08 NUSSBAUMER, D A Atomic Energy Commission 1p 22763 345
- --8403260153 Discusses certification of 660426 rept re disposition of SNM, per G Waller 660602 telcon Rept should indicate that contamination limits met in order for Commission to authorize transfer of facility NUSSBAUMER. D A Atomic Energy Commission 66/06/10 LAMBERTUB, H Kerr-McGee Corp 2pp 22763 348
- ---B40326015B Confirms 660207 chamical explosion at Cushing.DK thorium processing plants per 660207 telcon investigation complete.
 LAMBERTUS.H Kerr-McGee Corp 66/02/0B WALKER.N I Atomic Energy Commission 3pp 22763 352
- DOCKET 40-2061 KERR-MCGEE CHEMICAL CORP , DKLAHOMA CITY, OK
- 8403020130 Motion to change status of Chamber of Commerce of City of West Chicago to that of limited appearance Certificate of Svc encl FAHELL.T.W West Chicago, IL 84/02/2: Licensing Board Panel 4pp 22442 151 84/02/27 Atomic Safety and
- 8403130101 Forwards IE Insp Rept 40-2061/84-01 on 831011, i7, 1109, 18, 1212, 21, 840114, 18, 20, 27, 0202-03 & 07 No noncompliance identified PAPERIELLO.C J Region 3, Office of Director 84/02/27
 RAINEY, J.L. Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp) RAINEY, J L Ker 2pp 22614 261

- ---8403130117 IE Insp Rept 40-2061/84-01 on 831011,17,1109,18,1212,21,840116,18,20,27,0202-03 & 07 No noncompliance noted Major areas inspected incinerator installation, testing & readiness for operation

 JANUSKA, A 9, SCHUMACHER, M C Region 3, Office of Director 84/02/27 5m 22614 263
- 8403060118 People of State of IL revised statement of interest from 830707 petition for hearing & for leave to intervene HARRIGAN.N F Illinois, State of 84/02/29 Atomic Safety and Licensing Board Panel ip 22516 317
- --8403060124 People of State of IL revised Contention 2(a) Revincorporates deleted Contention 2(c) Certificate of Svcentl RAPKIN, A Illinois, State of 84/02/27 Atomic Safety and Licensing Board Panel 8pp 22516 319
- B403070027 Requests leave to revise statement of interest included in B30707 petition for hearing & for leave to intervene HARTIGAN.N F Illinois, State of 84/02/29 2pp 22541 200
- --8403070030 People of State of IL agreed revised contentions Proof of Byc encl RAPKIN,A Illinois, State of 84/02/29 Atomic Safety and Licensing Board Panel 8pp 22541 202
- B403090079 Order granting West Chicago Chamber of Commerce motion to make written limited appearance in proceeding FRYE.J H Atomic Safety and Licensing Board Panel 84/03/07 ip 22575 296
- B403090119 Memorandum & order admitting revised Contentions 2(a),(1), (n),(p) & (q) Contentions will be governed by B40224 prehearing conference order discovery schedule FRYE,JH Atomic Bafety and Licensing Board Panel 84/03/07 ip 22574 067
- 8403200327 Summary of B40301 meeting w/Dupont to discuss source matl licensing PAGE.R O Uranium Fuel Licensing Branch B4/03/08 DAVIB.J G Office of Nuclear Material Bafety & Bafeguards.Director 3pp 22709 140
- 8403200083 Motion for leave to file instanter revised Contentions 2(k).
 (u) & (w) Kerr-McGee & staff do not object to late filing of revised contentions Revised contentions encl RAPKIN.A Illinois, Btate of 84/03/14 Atomic Safsty and Licensing Board Fanel 1p 22685 288
- --8403200089 Revised Contentions 2(k), (u) & (w) Applicant chose West Chicago site solely for reasons of short-term economic convenience & benefit including avoidance of expenditures for transportation & land acquisition Proof of Bvc encl RAPKIN.A Illinois. State of 84/03/14 Atomic Safety and Licensing Board Panel 5pp 22685 289
- 8403210019 Notice of appearance in proceeding Certificate of Byc encl HEDGLON,M Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp) 84/03/19 7pp 22706.350
- 8403280028 Bubmits address change for Nuclear Licensing & Regulation Dapt. JC Stauter will serve as primary addressee for encl list of licensees 88HELLEY! W J Kerr-McGee Corp 84/03/21. SCHAEFFER.C NRC ~ No Detailed Affiliation Given 3pp 22777 060.
- B403290385 Notice of withdrawal of appearance in proceeding Certificate of Evc encl
 CHARNOFF. G Shaw, Pittman, Potts & Trowbridge DSB 187 84/03/27
 3pp 22814 251
- --8403290389 Response to State of IL Atty General 840314 proposed revised Contentions 2(k), 2(u) & 2(u) Revised Contention 2(k) w/o merit & licensee objects to admission of revised Contention 2(u) & 2(u) as repetitive. W/Certificate of Svc HEDOLON, M Kerr-McQee Corp. 84/03/27 Commissioners Spp 22814/254.
- B403300258 Motion for extension of time until 840417 to submit briefs in response to ASL8 840224 order Certificate of 8vc encl RAPKIN, A Illinois, State of DSB 216. 84/03/30 Commissioners 4pp 22824;074.

- DOCKET 40-2259 PATHFINDER MINES CORP , RIVERTON, WY
- 8403150342 "Semiannual Effluent Monitoring Rept.Jul-Dec 1983 "
 Documentation required by License Condition 25 Amend 16
 encl W/840228 ltr
 HARDGROVE.T W Pathfinder Mines Corp 83/12/31 WODLSEY.R T
 Uranium Recovery Field Office 16pp 22649 247
- 8403190443 Submits review of first 1983 semiannual rept of environ data & 1983 land use survey rept Site performance within acceptable limits w/exception of certain groundwater results
 WUDLSEY, R T , PETTENGILL, H J Uranium Recovery Field Office Spp 22679 357
- 8403120251 Requests accelerated approval to quarterly schedule for stack effluent monitoring Approval will allow quarterly schedule to be instituted prior to final approval of entire license renewal application NUGENT, E L Pathfinder Mines Corp 84/02/17 PETTENGILL, H Uranium Recovery Fiold Office ip 22519 207
- DOCKET 40-3392 ALLIED CHEMICAL CORP : MORRISTOWN, NJ
- 8403130083 Forwards IE Insp Rept 40-3392/84-01 on 840131-0202 No violations or deviations identified PAPERIELLO.C J Region 3, Office of Director 84/02/23 CIPOLLA:A J Allied Chemical Corp 2pp 22598 335
- --B403i30094 IE Insp Rept 40-3392/B4-01 on B40i3i-0202 No violations or deviations identified Major areas inspected radiation protection solid raduate mgt environ monitoring, safety committees & conduct of operations MILLER, D E , FRANCE, G M , GREGERL R Region J, Office of Director B4/02/22 6pp 22598 337
- 8403230077 Forwards corrected "Facility Effluent Rept.830701-840101" CIPOLLA:A J Allied Chemical Corp 84/02/27 Region 3, Office of Director 1p 22730 122
- --8403230100 Corrected "Facility Effluent Rept.830701-840101 " # Allied Chemical Corp 84/01/01 2pp 22730 123
- DOCKET 40-3453 ATLAS MINERALS, INC . DENVER. CO
- 8401120171 Forwards annual audit rept of Moab Mill radiation protection program Followup rept addressing action taken or to be taken for each item in audit encl BLUBAUGH.R E Atlas Minerals. Inc 83/07/16 WEAVER.R R Atlas Minerals. Inc 2pp 21805 020
- --8401120180 "ALARA Audit Rept of Atlas Minerals Corp Environ & Radiological Monitoring Program," executive summary SAVIGNAC.N Atlas Minerals, Inc. 83/07/30 37pp 21805 022
- 8403180264 "Bampling & Analysis Results of Environ Monitoring Program. Second Half 1983" per License Condition 42 & 43 W/840223 ltr EDWARDS.D L Atlas Minerals. Inc 83/12/31 SMITH.R D Uranium Recovery Field Office 125pp 22648 037
- B403060465 Issues Amend 14 to License SUA-917, adding Conditions 19(E) & 56 re potential impact of past disposal of metal drums containing vanadium wastes & disposal of wastes in tailings pond or beach respectively OARCIA, P.J., PETTENGILLH. J. Uranium Recovery Field Office 4pp 22549 327
- 8403070367 Issues Amend 14 to License 8UA-917, prohibiting disposal of wastes other than mill process or liquid sanitary wastes in tailings pond unless specifically authorized by NRC BMITH/R D Uranium Recovery Field Office 84/01/18 Atlas Minerals: Inc Rpp 22564 143
- 8403150280 Forwards clarification of storage/seepage terms in "Water Balancs Study,U Mill Tailings Impoundment," in response to 840118 request BLUBAUGH.R E Atlas Minerals, Inc. 84/02/14 PETTENGILL,H J Uranium Recovery Field Office 3pp 28646 359
- 8403200397 Submits review of technical evaluation performed by Dames & Moore of embankment performance for Moab Mill Embankment in excellent condition & functioning as designed GARCIA,P J. PETTENDILL,H J. Uranium Recovery Field Office 84/02/14 Uranium Recovery Field Office 2pp 22707 357

- 8403230267 Advises that License SUA-917 will be renewed & reduced monitoring program submitted in anticipation of increased sales market for U-308 concentrate BLUBAUGH.R E Atlas Minerals, Inc. 84/02/16 SMITH.R D Uranium Recovery Field Office ip 22741 356
- 8403150242 Informs of annual survey of land use within 2-mile area of mill Summary of differences in land use provided EDNAROS.D L. Atlas Minerals, Inc. 84/02/24 SMITH.D Uranium Recovery field Office 2pp 22649 010
- B403190431 Notifies of issuance of Amend 14 License SUA-917 Amend requires evaluation of possible impacts from waste other than mill tailings disposed in tailings pond or removal of wastes

 GARCIA.P J. PETTENGILL.H J. Uranium Recovery Field Office
 B4/03/01 MILLER.N O License Fee Management Branch 1p
 B2681 326

DOCKET 40-4492 FEDERAL-AMERICAN PARTNERS, RIVERTON, WY

- 8403200374 "Semiannual Rept on Radioactive Effluent Per 100FR40 65, Jul-Dec 1983 " One oversize map end Aperture card is available in PDR W/American Nuclear Corp 840227 ltr. * Federal American Partners 83/12/31 40pp 22707 285
- 8403190414 Ack receipt of 840203 request for approval of in-place reclamation of all existing tailings generated by Federal American Partners in Oas Hills area Review under way SMITN.R D Uranium Recovery Field Office 84/02/14 ANDRUS.N J American Nuclear Corp ip 22681 350
- 8403200323 Forwards portinent sections of draft DES re in-place reclamation of tailings pond Requests review of American Muclear Corp request & comments re concept of in-place reclamation of Tailings Pond I
 PETTERNSILL.H Uranium Recovery Field Office 84/02/23 RANDEN.L Hyoming. State of 2pp 22709 149
- --8403200325 Discusses status of preparing final reclamation plan for Tailings Pond 2 Requests assurance that Region IV approves concept of in-place reclamation for tailings existing at mill.

 ANDRUS.N J American Nuclear Corp 84/02/03 SMITH.R D Uranium Recovery Field Office 1p 22709 151
- --8403200528 Responds to 840203 request for NRC approval of in-place reclamation of existing tailings generated at mill operated in Gas Hill area of State of HY Situation currently under review SHITH,R D Uranium Recovery Field Office 84/02/14 ANDRUS,N J American Nuclear Corp 1p 22709 152
- 8403220045 Forwards Federal-American Partners, "Semiannual Rept on Radioactive Effluent-Per 10CFR40 65.Jul-Dec 1983 " ANDRUS N J American Nuclear Corp 84/02/27. Region 4, Office of Director 2pp 22715 122
- ---8403220054 "Semiannual Rept on Radioactive Effluent.Per 10CFR40. 55, Jul-Dec 1983 " Wione oversize figure Aperture card is available in PDR + Federal American Partners 83/12/31 38pp 22715 124

DOCKET 40-6329 CATHOLIC UNIV OF AMERICA, WASHINGTON, DC

- B403130422 Discusses IE insp of Licenses SNM-164,8UD-157 & 08-02075-03 on B40126-27 & forwards notice of violation MARTIN.T T Division of Engineering & Technical Programs 84/03/08 MURPHY.J J Catholic Univ of Americal Washington, DC 2pp
- --8403130433 Notice of violation from insp on 840126-27 Violations noted survey maters not calibr at proper intervals # Division of Engineering & Technical Programs 84/03/08 Ip 22613 142

DOCKET 40-6622 PATHFINDER MINES CORP , SHIRLEY BASIN, WY

8403190416 Reviews 830314 submittal of parameters for radiological assessment Parameters requiring clarification listed Response requested by 840321 PETTEMOILL.HJ Uranium Recovery Field Office 84/02/09 RUSSELL.JE Pathfinder Mines Corp 3pp 22681 347

- 8403200397 Reviews application for renewal of License SUA-442 Beveral areas identified needing add1 info Specific data requirements & appropriate section of renewal summerized PETTENGILL.H J Uranium Recovery Field Office 84/02/10 RUSSELL.JE Pathfinder Mines Corp 2pp 22707 361
- DOCKET 40-6659 GETTY OIL CO PETROTOMICS CO , SHIRLEY BASIN, WY
- 8403260242 Radionuclide liquid effluent rept for Jul-Dec 1983 List of particulates in form of stack gases released to unrestricted areas submitted.

 PFAFF.8 J Getty/Petrotomics Co 84/01/24 Region 4, Office of Director 1p 22754 326
- B403200377 Forwards review of First & Second Guarter 1983 environ munitoring data for Petrotomics Mill Levels of chlorides & sulphates decreasing KONNINGNI,O R., PETTENGILL, H. J. Uranium Recovery Field Office 84/02/22 Uranium Recovery Field Office 5pp 22708 337

DOCKET 40-6920 AUTOMATION INDUSTRIES, INC . PHOENIXVILLE, PA

- 8403010472 Discusses IE Insp Repts 40~6720/83-01 & 30~05998/83-01 on 830315.0607 & 0804 & IE Insp Repts 40~6720/83-02 k 30~05998/83-02 on 831017-18 & 1102-03 & forwards notice of violation MURLEY.T E Region i. Office of Director 84/02/16 DWIGHT, J. Automation Industries, Inc. 4pp 22438 270.
- --8403010483 Notice of violation & proposed imposition of civil penalty in amount of #5,625 Violations noted.failure to apply correction factor to meter readings previously identified during NRC insp & radioactive matls not suitably packaged MURLEY,TE Region 1. Office of Director 84/02/16 App. 22438 294
- 8403020331 Confirms 840229 telcon understanding of listed actions based on results of 840228 insp MARTIN.T Division of Engineering & Technical Programs 84/02/29 MGRELANO.F Automation Industries, Inc. 2pp 22439 213
- 8403120234 Forwards order to show cause & order temporarily suspending Licenses 37-00511-09 & 808-868 DEYDUNO.R C Director's Office Office of Inspection and Enforcement 84/03/02 DWIGHT.J Automation Industries, Inc 2pp 22619 241
- --8403120242 Order to show cause & order temporarily suspending Licenses SUB-868 & 37-00611-09 re apparent excess radiation exposure to thumb & fingernails of two radiation technicians working in restricted area DEYDUNG.R C Director's Office, Office of Inspection and Enforcement 84/03/02 Automation Industries, Inc 10pp 22249 243
- 8403210001 Responds to notice of violation & proposed imposition of civil penalties Third party being located to take over activities at Phoenixville,PA nuclear encapsulation facility

 BOWMAN,D C Automation Industries, Inc 84/03/14, Director's Office, Office of Inspection and Enforcement 3pp. 22707 052
- --8403210005 Responds to NRC 831227 ltr re violations noted in IE enforcement conference rept & insp of License 37-00611-09 Drawings for extension tubes used w/Model 8 source changer revised MRELAND, P E. Automation Industries, Inc 84/02/03 MARTIN, T T Division of Engineering & Technical Programs 7pp, 22707:055
- --8403210010 Forwards add1 technical info re discussions during 830928 enforcement conference concerning fractured secondary encapsulation on Co-60 source & evaluation of source connector. No disconnects observed during 12,000 cycles. MORELAND.P & Automation Industries, Inc. 84/01/30, ALLEN,J M Region 1, Office of Director 17pp 22707-062.
- B40330000B Responds to B40302 order to show cause & order temporarily suspending Licenses 37-00611-09 & BUB-868 Certain facts in Paragraphs II & III of order contested Hearing requested BDHMAN,D C Automation Industries, Inc. 84/03/26. Director's Office, Office of Inspection and Enforcement 2pp 22821 165

- DOCKET 40-6940 KAWECKI BERYLCO IND , INC , BOYERTOWN, PA
- 8403070317 Forwards submittals from Kawecki Berylco Industries re cause & extent of fluoride contamination in monitoring well 4 & background radiological parameters in West Swamp Creek WYNQARDEN, 8 D Uranium Fuel Licensing Branch 84/02/27 Uranium Fuel Licensing Branch 6pp 28564 321
- DOCKET 40-7455 WHITTAKER METALE, LOS ANGELES, CA
- 8403190310 Discusses IE insp of License SMA-1018 on 831101-02 No violations observed Insp limited to review of Whittaker Metals site in Greenville,PA MARTIN,T T Division of Engineering & Technical Programs 84/03/08 COLLINS,T J Desco Marine 1p 22673 274
- B403200327 Summary of B40301 meeting w/Dupont to discuss source matl licensing PAGE.R O Uranium Fuel Licensing Branch 84/03/08 DAVIS.J G Office of Nuclear Material Bafety & Safeguards.Director 3pp 22/09/140
- DOCKET 40-8027 KERR-MCGEE NUCLEAR CORP . OKLAHOMA CITY, OK
- 8403140215 Advises of issuance of Amend 24 to License SUB-1010 changing name of company to Sequevah Fuels Corp. Review encl
 PAGE R. G. Uranium Fuel Licensing Branch 83/12/14 SHELLEY
 - encl PAGE,R G Uranium Fuel Licensing Branch B3/12/16 SHELLEY,W J Sequoyah Fuels Corp ip 22637 331
- --8403140217 Review of 831021 application to amend License 8UB-1010 changing company name to Sequoyah Fuels Corp Amend should be issued KOBLA, B M , CROW, W T Uranium Fuel Licensing Branch 83/12/16 2pp 22637 332
- 8403010507 Issues Amend 26 to License SUB-1010, amending Conditions 5,6 & 7 re quantitative analyses for metals & specified isotopes, existing monitoring wells & surface water samples PAGE.R 0 Uranium Fuel Licensing Branch 84/02/16 SHELLEY, W J Kerr-McGee Corp 5pp 22438.310
- --8403010513 SER supporting issuance of Amend 26 to License 8UB-1010.

 amending Conditions 5,6 & 7 re quantitative analyses for

 metals & specified isotopes, existing monitoring wells &

 surface water samples

 RHODES, M. CROW, W. T. Uranium Fuel Licensing Branch 84/02/16

 17pp 22438 315
- 8403280028 Submits address change for Nuclear Licensing & Regulation Dept JC Stauter will serve as primary addresse for encl list of licensess SHELLEY, W. J. Kerr-McGee Corp. 84/03/21. SCHAEFFER, C. NRC No. Detailed Affiliation Given Spp. 22777 060
- DOCKET 40-8084 RIO ALGOM CORP , MOAB, UT
- 8403150208 "Bemiannual Environ Monitoring Rept for Jul-Dec 1983 " LAWTON, M D. Rio Algom, Ltd 83/12/31 34pp 22648 246
- 8403150274 Provides add1 info re annual yellowcake production before final assay adjustment from existing carbonate leach at Lisbon mill. PATTISHON R 8 Rio Algom, Ltd. 84/02/09. EMITH R D Uranium Recovery Field Office 2pp 22648 285
- B403190413 Forwards request for add1 info re principal parameters for radiological assessment Info needed to complete review of application to renew Bource Matl License BUA-1119 Response requested by B40316 PETTENOILL: M J. Uranium Recovery Field Office B4/02/15 LAWTON: M D Rio Algom. Ltd ip. 22681 351
- DOCKET 40-8102 EXXON CO., USA, HOUSTON, TX
- B403260138 Ack receipt of B31109 ltr informing NRC of steps taken to correct violations noted in IE insp of License SUA-1139 on B30906-0B Add1 info required re site security HALL.R.E. Region 4, Office of Director 84/01/18 BHANNON, J B Exxon Corp. 1p. 22758-158

- --8403260142 Responds to NRC 831014 ltr re violations noted in IE insp of License 8UA-1137 on 830706-08 Corrective action 5ection 5 4 of license renewal application modified to reflect current security practices
 SHANNON.J B Exxon Corp 83/11/09 HALL.R E Region 4. Office of Director 3pp 22758 159
- 8402140325 Ack receipt of 831109 & 840125 itrs informing NRC of steps taken to correct violations noted in IE insp of License 8UA-1139 on 830906-08
 HALLIR E Region 4. Office of Director 84/02/08 SHANNON, J B Exxon Corp ip 22228 237
- --8402140327 Responds to NRC 831014 ltr re violations noted in IE insp of License 8UA-1137 on 830706-08 Corrective actions product storage warehouse secured, limiting access to authorized personnel & continuous site security provided SHANNON, J B Exxon Corp 84/01/25 HALL, R E Region 4, Office of Director 2pp 22228 238
- 8403200380 Forwards summary of 840213 meeting between representatives of Exxon Minerals & U Recovery Field Offc to discuss comments on Exxon proposed decommissioning plans for Highland U operations
 PANOBURNIO C . PETTENGILL, H J Uranium Recovery Field Office 84/02/22 Uranium Recovery Field Office 5pp 22708 332
- DOCKET 40-8107 ARMY, DEPT OF, BACRAMENTO, CA
- 8403200107 IE Insp Findings & Licensee Ack dtd 840207 of License STB-1101 Insp findings no violations observed SKOV.D D Region 5. Office of Director 84/02/07 ip 22685 353
- DOCKET 40-8452 BEAR CREEK URANIUM CO , CASPER, MY
- 8403150235 Forwards 1983 reclamation bond calculations, including performance bond calculation & cost detail for mill site dismantling, decommissioning & reclamation activities MEDLOCK, R L Bearfoot Corp 83/09/20 SMITH, D , GARCIA, P Uranium Recovery Field Office 7pp 22649 016
- 8403150102 "Bear Creek U Co Semiannual Rept to NRC, Jul-Dec 1983, Environ Sampling " W/840309 ltr BLOSSOM, J N Bear Creek Uranium Co 83/12/31 21pp 22641 169
- B403150826 Water quality data for monitor wells & static levels for monitor well for Fourth Quarter 1983 per Condition 91(a) of License 8UA-1310 W/840222 ltr BLOSSOM.J N Bearfoot Corp 83/12/31 3pp 22649 032
- 8403190436 "Tailings Disposal Area 1983 Technical Evaluation " W/840131 ltr MEDLOCK:R L. Bear Creek Uranium Co. 83/12/31 SMITH.D. Uranium Recovery Field Office. 40pp. 22681 072
- 8403180245 Forwards design review of PMF channel per License Condition Sil-Amend 22 to Source Matl License SUA-1310 MEDLOCK,R L Bearfoot Corp 84/01/31 SMITH.D Uranium Recovery Field Office 3pp 22448 337
- 8400200350 Forwards review of monitoring data required by License Condition 51(a) of Source Matl License SUA-1310 PANGBURN, 0 C , PETTENGILL, H U Uranium Recovery Field Office 84/02/29 Uranium Recovery Field Office 3pp 22709 104
- DOCKET 40-8502 WYDMING MINERAL CORP , LAKEWOOD, CO
- 8403220182 Advises that review of proposed program for demonstrating restoration of alternative lixiviant test area at Irigaray Mine site will be completed by 840315 All well fields must be restored.

 HAWKINS, E.F. Uranium Recovery Field Office 84/02/22 DEASON, C. W. Malapai Resources Co. ip. 22723 282
- B403220196 Advises that review of proposed program for demonstrating restoration of alternative lixiviant test area at Irigaray Mine site will be completed by 840315 All well fields must be restored HAWKINB, E.F. Uranium Recovery Field Office 84/02/22 RUYLEDGE, C Wastinghouse Electric Corp. 1p. 22723 279

DOCKET 40-8584 MINERALS EXPLORATION CO . LOS ANGELES, CA

- B403150228 Submits responses to questions re Sept 1982 application for amend to Source Matl License SUA-1330 KLEIN.T J Minerals Exploration Co (subs of Union Oil Co of California) 83/08/02 PETTENSILL.H Uranium Recovery Field Office 2pp 22649 030
- 8403280099 Notifies that U processing suspended equipment decontaminated for suspension period & monitoring reduced Suspension will extend through & possibly beyond 5 grs HILLS Z Union Minerals 83/12/13 PETTEMOILL,H Uranium Recovery Field Office 2pp 22812 343
- 8403220068 Forwards summary of environ munitoring & meteorological canditions for Jul-Dec 1983, per License Conditions 34,43 & 48 Environ monitoring, as modified by Amend 12, implemented w/exception of addl air monitor downwind XLEIN.T J. Union 76 Minerals Exploration Co. 84/02/28 Region 4, Office of Director ip 22712 218
- --8403220071 Bummary of environ monitoring & meteorological conditions for Jul-Dec 1983 * Union 76 Minerals Exploration Co 83/12/31 74pp 22712 219
- 8403220117 Forwards summary of environ monitoring & mateorological conditions.per License 8UA-1850.Section 5 & Conditions 34.43 & 48 Station will be operable in First Quarter 1984 KLEIN T J Union Hinarals 84/02/28 Region 4. Office of Director 1p 22718 116
- --8403220124 Summary of environ monitoring & meteorological conditions for Third & Fourth Quarters 1983 * Union Minerals 83/12/31 74pp 22/18:117

DOCKET 40-8595 HYOMING MINERAL CORP : LAKEHOOD: CO

- 8403260213 "Semiannual Efficient Monitoring Rept.Jul-Dec 1983 " W/840227 ltr BERGOR E Westinghouse Electric Corp 83/12/31 2pp 22756 162
- DOCKET 40-8586 KERR-MCGEE NUCLEAR CORP , GKLAHGMA CITY, DK
- 8403150332 Forwards rapt re abandonment & plugging procedures for water well & monitor hole SHELLEY,W J. Kerr-HcGse Corp. 83/10/05 PETTENGILL,H. Uranium Recovery Field Office. Spp. 22649-271
- 8403280099 Forwards completed NRC Form 314 for license License will not be renewed at present LANDAGDRAM Kerr-McGee Corp 83/11/21 Division of Fuel Cycle & Material Bafety 1p. 22811 361
- --8403280103 Certificate of disposition of matls no matls procured by licenses under License SUA-1330, SHELLEY,W J. Kerr-McGee Corp 83/11/21 lp 22811 362

DOCKET 40-8602 SILVER KING MINES, INC., CASPER, WY

- 8403200370 "Annual Land Use Burvey Project Area Five Mile Radius, 1983 " N/840228 itr One oversize map encl Aperture card is available in FDR * Silver King Mines, Inc 83/12/31 PETTENDIAL, H J Uranium Recovery Field Office 12pp 22708 293
- 8403220210 Responds to 831122 request to extend license & defer further preoperational environ monitoring Approval of request would not be in keeping wintent of NRC regulations License ranewal application should be submitted PETTEMBILL.H J Uranium Recovery Field Office 84/02/23 WOLFF.C E Silver King Mines. Inc. 1p. 22783 265
- DOCKET 40-8647 KERR-HOGEE NUCLEAR CORP , OKLAHOMA CITY, OK
- 8403280028 Submits address change for Nuclear Licensing & Regulation Dept JC Stauter will serve as primery addresse for encl list of licensees SHELLEY, W.J. Kerr-McGee Corp. 84/03/21, SCHAEFFER, C. NRC No Datailed Affiliation Given. 3pp. 22777.060.

- DOCKET 40-8663 NUCLEAR DYNAMICS, INC , PHOENIX, AZ
- 8403150Ri2 Submits analysis of Ra-226 level in water immediately prior to discharge, supplementing 831109 request for permission to discharge water in evaporation ponds Application to amend License SUA-1331 under NRC consideration FRITZ.D M Western Water Consultants. Inc 84/01/13 WAGNER.J Hyaming. State of 4pp 22649,046
- DOCKET 40-8674 PLATEAU RESOURCES, LTD , GRAND JUNCTION, CO
- 8403220191 "Effluent Monitoring Rept.Jul-Dec 1983 " W/840227 ltr * Plateau Resources, Ltd 83/12/31 10pp 22717 036
- DOCKET 40-8681 ENERGY FUELS NUCLEAR, INC , DENVER, CO
- 8403170424 Forwards rept of 830830 ALARA audit Rept provides data & trands which enabled audit committee to make recommendations to reduce worker exposures & environ effluents Next rept scheduled for 840227 SMITH.D E Energy Fuels Nuclear. Inc 83/11/28 VINCELETTE, D Energy Fuels Nuclear, Inc 45pp 22700 179
- 8403260187 Lists corrective actions to be taken, per 840112 telcon re 831127 incident & measures to prevent recurrence of violations noted in IE insp on 840104-05 COLLINS, J T Region 4, Office of Director 84/01/13 SPARLING, D K Energy Fuels Nuclear, Inc 1p 22756 121
- 8403200360 Forwards review of semiannual ALARA rept for Energy Fuels Nuclear White Sand Mill for period ending 830630 Future repts should contain more detailed discussion of audit committee findings HILDENBRAND.F., HAMKINS.E F Uranium Recovery Field Office 84062/15 Uranium Recovery Field Office 7pp 22707 003
- 8403200389 Requests assistance in reviewing Union Carbide application for self-bonding SMITM,R D. Uranium Recovery Field Office 84/02/16 BROWNING,R E Division of Waste Management 2pp 22708 313
- --B403200394 Forwards proposed reclamation surety agreement, organizational chart & specific employee qualification for White Mesa U Mill near Blanding, UT DEMOLLANDER, O Union Carbide Corp 84/02/10 HILDENBRAND, P Uranium Recovery Field Office 17pp 22708 315
- 8403200363 Summary of 840209 meeting w/Union Carbids & Energy Fuels Nuclear in Denver.CO me submitted in support of Energy Fuels request to transfer Source Matl License SUA-1338 to Union Carbide HILDENBRAND, P. HAWKINS, E. F. Uranium Recovery Field Office 84/02/21 Uranium Recovery Field Office 3pp 22708 356
- B4D319O335 FN-84-014 on 84O316. notice of violation & proposed imposition of civil penalty in amount of \$6.000 issued to licansee Action based on violations involving radiological occurrence w/potential for radiation exposures FLACK.E. AXELRAD. Director's Office. Office of Inspection and Enfurcement. 84/O3/13 2pp 22675 027
- DOCKET 40-8684 WESTERN NUCLEAR, INC., LAKEWOOD, CO
- 8403i502i5 Forwards results of expanded study by In-Bitu, Inc of pump test specifically addressing issue of leakage from aquifers adjacent to production aquifer through confining layers.

 HOODEN.G Western Nuclear, Inc (subs of Phelps Dodge Corp)

 84/0/1/26 HILDEBRAND, P Uranium Recovery Field Office Bpp

 22649 035
- DOCKET 40-8698 PLATEAU REBOURCES, LTD , GRAND JUNCTION, CD
- B403150213 Confirms telcon re resignation of RJ Carr, effective B40131 JH Davis will assume RJ Carr duties, effective B40201 Resume of JN Davis encl GERDEMAN.F W Plateau Resources, Ltd. B4/01/16, SMITH.R.D Uranium Recovery Field Office. 3pp 22649.043
- 8403150249 Forwards resume of N Savignac per E Hawkins request Bavignac will conduct GC audits GERDEMAN.F W Plateau Resources, Ltd 84/02/02 SMITH.R.D. Uranium Recovery Field Office 6pp 22648.351.

J403220183 Forwards "Effluent Monitoring Rept, Jul-Dec 1983 " Results of Pb-210 analyses for fourth quarter high vol air samples will be available by 840305 GERDEMAN,F W Plateau Resources, Ltd 84/02/27 Region 4, Office of Director ip 22909 200

-8403220187 "Effluent Monitoring Rept.Jul-Dec 1983 "
* Plateau Resources, Ltd 83/12/31 3900 22909 201

DICKET 40-8727 KERR-MCGEE NUCLEAR CORP , OKLAHOMA CITY, DK

g03280028 Submits address change for Nuclear Licensing & Regulation Dept JC Stauter will serve as primary addressee for encl list of licensees SHELLEV, W J Kerr-McOee Corp 84/03/21 BCHAEFFER, C NRC - No Detailed Affiliation Given 3pp 82777 060

DCKET 40-8745 DQLE PETROLEUM, INC , CASPER, WY

403230136 Notifies of amend to License SUA-1396, deleting License Gondition Bit to Indicate radiation safety officer satisfactorily completed formalized intensive health physics training program SMITH.R D Uranium Recovery Field Office, 84/02/27 Ogle Petroleum, Inc. 1p 22743,354

-8403230137 Notifies that Ople Petroleum, Inc fulfilled requirements of License Condition 13 re radiation safety officer satisfactorily completing formalized intensive health physics training program HABTLER, B L , HAWKINS, E F Uranium Recovery Field Office 84/02/22. Uranium Recovery Field Office 19 22743 355

ICKET 40-8760 EDLOW INTERNATIONAL CO . WASHINGTON, DC

.03270086 Ack receipt of 840306 ltr informing NRC of steps taken to correct violations noted in IE insp of License SMC-1377 Requests evaluation to determine whether train accident could affect safe storage of natural UF6 HIND. J A Division of Radiological & Materials Safety Programs 84/03/22 EDLOW J Edlow International Co 3pp 22770 026

8403270094 Responds to NRC telcon w/J Edlow re violation noted in IE insp of License SMC-1377 Corrective actions UF6 will not be stored inside warehouse before license issued POIDHURST, B W Edlow International Co 84/03/06 ALEXSON, W L Region 3, Office of Director 1p 22770 028

CKET 40-8768 KERR-MCGEE NUCLEAR CORP , OKLAHOMA CITY, OK

O3010071 Forwards info sent to Btate of MY Dept of Environ Quality to be inserted into O-Band in situ project application.
FREEMAN.M D Sequoyah Fuels Corp 84/01/25 HILDENDRAND, P R,
LINEHAN.J J Uranium Recovery Field Office. 16pp 22480 008

D3R80127 Informs of issuance of amend to License SUA-1387 designating Bequoyah Fusis Corp as wholly owned subsidiary of Carr-McGes
MITH.R D Uranium Recovery Field Office 84/02/09 SHELLEY, W J Carr-McGes Corp 2pp 22811 080.

13200375 Bummary of 840221 meeting w/Western Nuclear Inc in Denver CO te concerns about Willow Creek R&D project discovered during sealage analysis of pump test data.

**ILDENBRAND P. HAMKINS E. Umanium Recovery Field Office 14/02/23. Uranium Recovery Field Office 2pp 22708 342

*3280028 Submits address change for Nuclear Licensing & Regulation Papt, JC Stauter will serve as primary addresses for encl 1st of licensees.
**HELLEY, W.J. Kerr-McGee Corp. 84/03/21 SCHAEFFER, C NRC - No lateiled Affiliation Given 3pp 22777.060

DOCKET 40-8781 TETON EXPLORATION DRILLING CO , INC , CASPER, WY

8403150205 Comments on encl quarterly rept for Oct-Dec 1983 Listed Changes suggested STAUB,W P Dak Ridge National Laboratory 84/01/16 WILLIAMS,R E Idaho, Univ of, Moscow, ID 2pp 22444 228

--8403150207 "Toton Exploration Drilling Co - Levenberger Project. Quarterly Rept for Oct-Dec 1983 " * Idaho: Univ of, Moscow, ID 83/12/31 33pp 22646 230

DOCKET 40-8783 URANERZ UBA, INC . CASPER, WY

8403190412 "Quarterly Operating Rept for Third Quarter 1983 " W/831101 ltr SDMERVILLE.K Q Uranerz USA, Inc 83/09/30 LINEHAN,J J Uranium Recovery Field Office 100pp 22681 106

8403190411 "Quarterly Operating Rept for Second Quarter 1983 " W/ 830901 ltr SOMERVILLE.K G Uranerz USA, Inc 83/06/30 LINEHAN.J J Uranium Recovery Field Office 99pp 22681 212

DOCKET 40-8786 URANIUM RESOURCES, INC., RICHARDSON, TX

8403130272 Informs of contamination of DJ Kindle wrine sample 14-11 taken on 831124 Source of contamination could not be identified Bloassay samples will be placed in locked, tamper proof receptacle to prevent contamination FREEMAN, M D. SINKE, Q J. Kerr-McGee Corp. 84/01/04 SMITH, R D. Uranium Recovery Field Office. Spp. 22648 280

8403150283 Comments on adequacy of pump test Test will yield most info requested Some data may require reanalysis MULLER.K Wyoming, State of 84/01/26 Wyoming, State of 3pp 22648 348

B403150260 Comments on Kerr-McGee responses to previous comments, excluding pump test comments Adequacy or remaining issue noted as appropriate MULLER, K. Wyoming, State of 84/01/26 Hyoming, State of 2pp 22648 346

B403150274 Forwards info sent to State of WY Dept of Environ Quality to be inserted in O Sand in-situ project application FREEMAN.M D Kerr-McGee Corp B4/01/31 LINEHAN,J J Uranium Recovery Field Office 16pp 22649 317

DOCKET 40-8820 AMAX ENVIRONMENTAL SERVICES, INC . GOLDEN, CO

8403070348 Issues Amend 1 to License BMB-1418, adding Condition 17 stating that rept required by Condition 17 must be submitted by 840315 PAGE.R G Uranium Fuel Licensing Branch 84/02/27 KERRIGAN.J E AMAX Environmental Services, Inc (subs of AMAX, Inc.) 1p 22564,126

DOCKET 40-8824 TARGET RESEARCH, INC., WHARTON, NJ

B403220170 Ack receipt of 840213 ltr informing NRC of steps taken to correct violations noted in IE insp of License 8UB-1421 MARTIN.T T Division of Engineering & Technical Programs 84/03/15 GUADAGNO.V Target Research, Inc ip 22707 176

--8403220173 Responds to NRC itr re violations noted in IE insp of License 8UB-1421 Corrective actions license amended to allow transport of mati to licensed recipient & to modify detection requirements

GUADAGNO, V Target Research, Inc 84/02/13 FRIEDMAN, L F Region 1. Defice of Director 2pp 22909, 197

DOCKET 40-0829 WYOMING FUEL CO , LAKEWDOD, CO

8403130319 Forwards responses to NRC questions re-solar evaporation pond design & State of NE questions re-Crow Butte U Project.

W/four oversize maps Aperture cards are available in PDR.

STOUT, D H Wyoming Fuel Co 83/10/21, LINEHAN, J Uranium Recovery Field Office 136pp. 22677.113

- ---8403150340 "Soils Engineering Rept. Hyoming Fuel Co Crow Butte Project Pilot Test Pand Area " FISHER.R. HARDEN.K C Fisher. Harden & Fisher 82/12/31 52pp 22677 197
- 8403130286 Comments on Wyoming Fuel Co response to request for addition to on "Guidelines for Groundwater Monitoring at In Situ U Solution Mines" Ltr to EPA 4t6 831205 outlining procedures for exempting aquifer encl HOFFAN. TE Hestern Nebreaka Resources Council 84/01/06 HAWKING, E.F. Uranium Recovery Field Office 7pp 22648 335
- 8403190415 Forwards draft rept of review of hydrology for Wyoming Fuel Co proposed Crow Butte R&B project Rept will be basis for hydrology section of EIA HAMKINS.E F Uranium Recovery Field Office 84/02/09 HABERMAN.C Nebraska, State of 32pp 22700 147
- 8403200372 Forwards review of waste storage ponds which should be included in environ assessment Pond & liner designs meet applicable criteria GILLEN.D M . JOHNSON.T L Engineering Branch (Post 831001) 84/02/15 WASTLER.S L Uranium Recovery Field Office 5pp 22708 345
- 8403170418 Forwards EIAs & licenses for Kerr-McGee & Uraner: R&D projects.per request M/a encl MANKINS.E F Uranium Recovery Field Office 84/02/17 HABERMAN,C Nebrasta, State of ip 22681 346
- 8403200320 Responds to comments & requests for addl info on groundwater restoration & potential for increased energy costs at U in situ leach project No impact evident on present rate payer or environ due to project HAWKINS, E. Uranium Recovery Field Office 84/02/22 HOFFMAN, T. Western Nebraska Resources Council 2pp 22709 162
- 8403220190 Forwards description of pump test by Myoming Fuel Co for proposed Crow Butte project & subsequent analyses of pump test data M/o encl
 HAMMINS E F Urenium Recovery Field Office 84/02/22 REILLY, F Interior. Dept of, Geological Survey ip 22723 281

DOCKET 40-8830 HONEYWELL, INC , HOPKINS, MN

- 8403060201 Forwards IE Insp Repts 40-8830/84-01 & 30-20529/84-01 on 840207-08 No noncompliance noted WIEDEMAN.D Q Region 3, Office of Director 84/03/01 FRAKES, J Honeywell, Inc. 1p 22517 176
- --8403060210 IE Insp Repts 40-8830/84-01 & 30-20529/84-01 on 840207-08 No noncompliance noted Major areas inspected organization, licensee audits, training, retraining & instructions to workers, radiological protection procedures & matls MADERA, J R . OSERG. C T . WIEDEMAN, D G . Region 3, Office of Director 84/08/29 ilpp. 22517 177

DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

DOCKET 50-2 UNIV OF MICHIGAN RESEARCH REACTOR

F Becurity, medical, emergency & fire protection plans

8403280205 Forwards senitized version of updated Feb 1984 route survey for shipment from Ann Arbor.MI to Bavannah River.80 to replace Aug 1983 version.per 10CFR73 21 Portions of 830825 ltr remain unchanged SHERR.T S Material Transfer Safeguards Licensing Branch 84/03/12 KERR.W Mithigen. Univ of. Ann Arbor. MI. 14pp 22808.214 24X Fichs 30-002.84/03/12,8403280220

DOCKET 50-3 INDIAN POINT STATION, UNIT 1

- F Security, medical, emergency & fire protection plans
- 8403070288 Public version of page changes to Book I personnel procedures & Book II emergency procedures, including Procedure IP-1007 re determination of magnitude of release & exposure rate M/831213 itr & JM Felton release memo O'TOOLE, J D Consolidated Edison Co of New York, Inc. 83/12/02 MURLEY, I E Region I, Office of Director 80pp 22592 220 24X Fiche 50-003,83/12/02,8403090288

- 8403190263 Notification of 840418 workshop in King of Prussia,PA to discuss lessons learned from recent App R fire protection safe shutdown insp & topics described in IE Info Notice 84-09 Agenda for workshop encl
 MURLEY,TE Region 1. Office of Director 84/03/09 0/100LE,JD Consolidate Edison Co of New York, Inc HEIDER,L H Yankse Atomic Electric Co COUNSIL,W G. Connecticut Yankse Atomic Power Co 35pp 22672 062 24% Fiche 50-000.84/03/09,8403190243
- 8403190069 Provides preliminary estimate of cost to upgrade present primary emergency operations facility to provide radiation protection factor of five O'TOOLE.J D Consolidated Edison Co of New York, Inc 84/03/14 EISENHUT.D G Division of Licensing 2pp 22666 132 24X Fiche 50-003.84/03/14.8403190069
- 8403290251 Advises that 831014 rev to physical security plan consistent w/provisions of 100FR50 54(p) & acceptable MARTIN.T T Division of Engineering & Technical Programs 84/03/21 D'TOOLE.J D Consolidated Edison Co of New York, Inc. 4pp 22800 001 24% Fiche 50-003.84/03/21.8403290251

G Inspection reports. IE Bulletins & correspondence

- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list enc!

 JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc. 115pp 22909 239 24X Fiche 50-000.84/02/28, 8401190072
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Nevs by DDT & NRC " Svc list encl GRACE.J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pg 82552 329 24X Fiche 50-000,84/03/02,8402090007
- B40209000B IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098. 24X Fiche 50-000,84/03/02,8402090008.
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases" 8vc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103), 84/03/02 Consolidated Edison Co of New York, Inc 119pp 22553 217 24X Fichs. 50-000, 84/03/02, 8402090009
- B402070011 IE Info Notice B4-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl
 JORDANIE L Division of Emergency Preparedness & Engineering
 Response (Post B30103) B4/03/05 Consolidated Edison Co. of New
 York, Inc 117pp 22553 336 24X Fiche. 50-000, 84/03/05, 8402070011
- 8402090024 IE Info Notice 84-09. Rev i. "Lessons Learned From Insps of Fire Protection Bafe Shutdown Sys " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07. Consolidated Edison Co. of New York, Inc 118pp 22635-049 24X Fiche 30-000, 84/03/07, 8402090024
- B40209002B IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Sys " Syc list encl.

 JORDAN-E L Division of Emergency Preparadness & Engineering Response (Post 830103) B4/03/07 Consolidated Edison Co of New York, Inc. 118pp 22584-186 24X Fiche. 50-000, 84/03/07, 8402090028
- 8402070031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys." Syc list encl
 DEYOUNG.R.C. Director's Office, Office of Inspection and
 Enforcement. 84/03/12 Consolidated Edison Co of New York, Inc
 134pp 67245 275 24X Fiche 50-000.84/03/12.8402070031.
- 8402070043 IE Info Notice 84-19. "Two Events Involving Unauthorized Entries into PWR Reactor Cavities." Bvc list encl. JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 123pp 22883 229. 24X Fiche 50-000,84/03/21,8402090043
- 8402070044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc list encl JURDANA: L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001, 24X Fiche: 50-000, 84/03/21, 8402070044
- R Pariodic operating reports & related correspondence
- 8403230135 "Personnel Whole Body Exposure for CY83." W/840301 ltr O'TOCLE.J.D Consolidated Edison Co. of New York, Inc. 83/12/31. MURLEY:T E Region 1, Office of Director. 3pp 22730:137. 24X Fiche:50-003,83/12/31.8403230135.

DOCKETED ITEMS

- 8403260120 "Efficient & Waste Disposal Semiannual Rept for Jul-Dec 1983 " W/840301 ltr D'TOCLE, J D Consolidated Edison Co of New York, Inc 83/12/31 MURLEY, T E Region 1, Office of Director 46pp 22758 086 24X Fichs 50-003
- 8. Reportable occurrences, LERs & related correspondence
- 8403250233 Forwards summary list of deficiencies identified per 100FR50 55(e), Part 21 & potential generic ltr repts for comments
 - ETAROBTECKI.R Division of Project & Resident Programs 84/02/28 Region 1. Office of Director 7pp 22736 065 24x Fichs 80-000,84/02/28,8403260233
- DOCKET 50-5 PENNSYLVANIA STATE UNIV RESEARCH REACTOR
- F. Becurity, medical, emergency & fire protection plans
- B403070360 Requests add1 info identified in encl NRC emergency plan review by 840430 Flan submitted on 821027 does not meet requirements or guidelines in Rev 1 to Reg Guide 2 & & ANBI/ANS-15 16-1982.

 THOMAS.C O Btandardization & Epscial Projects Branch 84/02/27 CUNNINGHAM, Q. Pennsylvania State Univ , University Park, PA 2pp 22564, 138 24X Fiche 50-005, 84/02/27, 8403070360
- ---B403070362 Evaluation of Pannsylvania State Univ research reactor emergency preparedness plan

 * Division of Emergency Preparedness & Engineering Response (Post B30103) 84/02/27 3pp 22564 140 24X Fiche 50-005.84/02/27, B403070360
- DOCKET 50-10 DRESDEN NUCLEAR POWER STATION, UNIT 1
- 8401170072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list
- encl. JDRDAN,E L Division of Emargency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc. 115pp. 22707 237 24X Fichs 50-000,84/02/28,8401170072
- F. Security, medical, emergency & fire protection plans
- 8403120053 Advises of 840323 regional workshop in Rosemont, IL w/all Region III licensess to discuss fire protection safe shutdown requirements of 10CFR50. App R Agenda encl 8PE88ARD.R L Division of Emergency Preparedness & Operational Bupport 84/03/06 REED, C Commonwealth Edison Co 3pp 22585:222 24X Fiche. 50-010, 84/03/06, 8403120083
- Q. Adjudicatory correspondence
- 8402220157 Order extending time until 840228 for Commission to act to review Director's Decision DD-83-14 CHILK, 8, J Office of the Secretary of the Commission 84/02/21 Commissioners 1p 22337 362 24X Fiche 50-000, 84/02/21. 8402220157
- 8403010238 Order extending time until 840305 for Commission to act to review Director's Decision DD-83-14 & 831029 decision denying request of Environ Policy Inst. CHILK.R J Office of the Secretary of the Commission 84/02/28 Commissioners ip. 22434-210. 24X Fiche 50-000,84/02/28, 8403010238
- 8403090049 Informs that Commission unanimously declined to review Director's Decision DD-83-14 Time provided by NRC regulations within which Commission may act to review expired Decision became final agency action on 840305 CHILK, B. J. Office of the Secretary of the Commission 84/03/08 CELEBREZZE, A. Ohio, Btate of, Rpp 22575.350 24X Fiche: 50-000, 84/03/08, 8403090069
- B403070074 Informs that Commission unanimously declined to review Director's Decision DD-83-14. Time provided by NRC regulations within which Commission may act to review expired. Decision became final agency action on 840305 CHILK, B. J. Diffice of the Secretary of the Commission 84/03/08 MILLAR, F. Environmental Policy Institute, 1p. 22575 292 24X Fiche: 50-000, 84/03/08, 8403070074.
- 8403090113 Informs of Commission decision not to review Director's Decision DD-83-14. Time for Commission to act expired on 840305. W/o encl CHILK: 8. J. Office of the Secretary of the Commission 84/03/08 REBNIKDFF.M. Bis

- P Operating license stage documents & correspondence
- 8403020037 Notification of contract execution "Dresden & Perry
 Simulator Leasing," awarded to 9E
 JESSUP, B Technical Assistance Contracts Branch FIN B-8713
 84702/17 HAVINS, O H Director's Office, Defice of Inspection and
 Enforcement 1p 22491 045 24X Fiche 50-000,84/02/17,8403020037
- ---B403020043 Contract "Dresden & Perry Simulator Leasing," award#6 to OE PIERCE,R L General Electric Co MDRTON,K V Division of Contracts FIN B-8713 84/02/17 38pp 22491 046 24X Ficho 50-000,84/02/17,8403020037
- B403130275 Generic Ltr 84-07 to all licensees of BWRs re procedural guidance for pips replacement at BWRs Svc list encl EISENHUT,D 0 Division of Licensing 84/03/14 Commonwealth Edison Co 20pp 22823 354 24% Fiche 30-000.84/03/14,B403150275
- @ Inspection reports: IE Bulletins & correspondence
- 8403050043 Forwards Rev O to "Corporate Regulatory Performance Improvement Plan" Plan designed to heighten employee awareness & strengthen corporate ability to improve regulatory performance
 THOMAB.B Commonwealth Edison Co 84/02/24 KEPPLER, J G Region G, Office of Director 3pp 22470 137 24X Fiche 50-000,84/02/24,84030300043
- --8403050046 Rev O to "Corporate Regulatory Performance Improvement Plan" * Commonwealth Edison Co 84/02/27 22pp 22490 142 24X Fiche 30-000,84/02/24,8403050043
- 8402070007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE.JN Division of QA, Safeguards & Inspection Programs (Post B30103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 327 24X Fiche 50-000,84/03/02,8402090007
- 8402070008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate "Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000.84/03/02.8402090008
- 8402070007 IE Info Notice 84-15, "Reporting of Radiological Releases" Byc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 119pp 22593 217 24X Fiche 80-000,84/03/02,8402070009
- B402070011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fishe 50-000,84/03/05,8402070011
- B402090024 IE Info Notice 84-07. Rev i, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN:E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York: Inc. 118pp 22635 049 24X Fiche 50-000:84/03/07:8402090024
- B402070028 IE Info Notice 84-18, "Btress Corrosion Cracking in PWR Bys." Svc list encl JORDAN,E L. Division of Emergency Preparadness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22584 186 24X Fiche. 50-000.84/03/07, 8402070028
- 8402070031 IE Bullstin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Bafety Sys " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and
 Enforcement 84/03/12 Consolidated Edison Co of New York, Inc
 134pp. 67245 275 24X Fiche 50-000,84/03/12,8402070031.
- B4032300BB Ack receipt of regulatory performance improvement plan
 Periodic meetings requested to discuss progress on program
 & provide feedback.
 KEPPLER.J G Region 3, Office of Director. B4/03/20 THDMAS.B
 Gammanuealth Edison Co ip 22730 161 24X Ficher 50-000, 84/03/20,
 B40323008B
- --B403230107 Forwards corporate regulatory performance improvament plan THOMAS.B Commonwealth Edison Co 84/02/24 XEFPLER.J Q. Region 3, Office of Director 3pp. 22730 162. 24X Fiche 50-000. B4/03/20.8403230088

- --8403230124 Rev O to "Corporate Regulatory Performance Improvement Plan For Dresden. Quad Cities, Zion & LaSalle Operating Nuclear Stations & Byron & Braidwood Project Operating Organizations " * Commonwealth Edison Co 84/02/29 22pp 22730 165 24X
 - * Commonwealth Edison Co 84/02/29 22pp 22730 165 24 Fiche 50-000,84/03/20,8403230088
- 8402070043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 123pp 22823-229 R4X Fiche 50-000,84/03/21,8402070043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21. Consolidated Edison Co of New York, Inc. (35pp. 22933 00) 24X Fiche 50-000.84/03/21.8402090044

R Periodic operating reports & related correspondence

- 8403060079 "Rept of Radioactive Effluents.Jul-Det 1983 " W/840215 ltr SCOTT.D J Commonwealth Edison Co 83/12/31 KEPPLER.J 9 Region 3. Office of Director 17pp 22506 245 24X Fiche 50-010.83/12/31. 8403060099
- B403080197 "Rept of Occupational Personnel Radiation Doses:1983"
 W/840227 ltr
 SCOTT.J S Commonwealth Edison Co 83/12/31 CASE,E @ Office
 Ruclear Reactor Regulation, Director 13pp 22559 099 24X
 Fiche 50-000,83/12/31,8403080197
- 8403220120 Annual whole body external exposures for 1983 W/840315 ltr RYBAK, B Commonwealth Edison Co 83/12/31 7pp. 22715 007 24X Fiche 50-000,83/12/31,8403220120.

DOCKET 50-13 BABCGCK & WILCOX CO CRITICAL FACILITY P Operating license stage documents & correspondence

8403020162 Responds to 831122 request for waiver on use of qualified reactor operators for fuel handling operations during period between time of CX-10 facility final shutdown & completion of fuel shipments Request denied THOMAS.C O Standardization & Epscial Projects Branch 84/02/17 (B.6EN.A F Babcock & Wilcox Co 3pp 22491 138 24X Fiche 50-013.84/02/17.8403020162

DOCKET 50-18 VALLECITOS BOILING MATER REACTOR

R Periodic operating reports & related correspondence

- 8403200244 "Annual Operating Rept 19 for Vallactios BLR (Deactivated) " W/840312 ltr * General Electric Co 83/12/31 DENTON, H R Defice of Nuclear Reactor Regulation, Director 5pp 22691, 115 24X Fiche 50-018,83/12/31,8403200244
- DOCKET 50-20 MASSACHUSETTS INST OF TECH RES. REACTOR
 F. Security, medical, emergency & fire protection plans
- 8402130347 Forwards Rev 30 to BAR for research reactor MJTR-11.

 affecting physical security plan Rev Withheld
 (ref 10CFR73 21).

 CLARK.L Massachusetts Institute of Technology, Cambridge, MA,

 84/02/07 THOMAS,C O Standardization & Special Projects Branch
 1p 28203 299 24X Fiche-50-020,84/02/07,8402130347
- 8403220034 Advises that Region I appraisal/insp of emergency preparedness program scheduled to begin 840403

 MARTIN.T T Division of Engineering & Technical Programs 84/03/13

 CLARK.L Massachusetts Institute of Technology, Cambridge, MA ip 22717 182 24X Fiche 50-020,84/03/13,8403220034
- O Inspection reports. IE Bulletins & correspondence
- B403220034 Advises that Region I appraisal/insp of emergency preparedness program scheduled to begin 840403 MARTIN.TT Division of Engineering & Technical Programs 84/03/13 CLARK.L Massachusetts Institute of Technology, Cambridge, MA ip 22717 182 24X Fiche, 50-020, 84/03/13, 8403220034

- DOCKET 50-29 VANKEE-ROWE NUCLEAR POWER STATION
- F Security, medical, emergency & fire protection plans
- 8403190243 Notification of 840418 workshop in King of Prussia, PA to discuss lessons learned from recent App R fire protection safe shuddown insp & topics described in IE Info Notice 84-09 Agenda for warkshop encl MURLEY, T E Region 1: Office of Director 84/03/09 D'TOOLE, J D Consolidated Edison Co of New York, Inc HEIDER, L H Yankse Atomic Electric Co COUNSIL. W G Connecticut Yankse Atomic Power Co 33pp 22672 062 24X Fiche 50-000,84/03/09,8403190243

J Insurance & indemnity information

- 8403140033 Forwards Endorsement 90 to MAELU Policy MF-26 & Endorsements 108 & 109 to MELIA Policy MF-76 SINISI,J M Marsh & McLennan, Inc. 84/03/05 SALTZMAN,J D Assistant Director for State & Licensee Relations 4pp 22634 155 24X Fiche 50-029,84/03/05,8403140033
- 8403270216 Submits info re nuclear property insurance coverage as of 840401 Coverage carried w/American Nuclear Insurance & Mutual Atomic Energy Reinsurance Pool KAY. J A Yenkee Atomic Electric Co 84/03/22 CRUTCHFIELD, D Operating Reactors Branch 5 priche 50-029.84/03/22,8403270216
- P Operating license stage documents & correspondence
- 8403080007 Forwards YAEC-1398, "Main Steam Line Break Analysis Addition of Boron Transport Model" Post-processor to RETRAN code developed to predict Yankee Nuclear Power Station transient buron concentrations

 KAY.J A Yankee Atomic Electric Co 84/03/02 CRUTCHFIELD, D Operating Reactors Branch 5 ip 22357 155 24X

 Fiche 30-029.84/03/02.8403080007
- --8403080009 "Yankee Nuclear Power Station Main Steam Line Break Analysis Addition of Boron Transport Model " KENDALL.J M., FUJITA, N., CHANDOLA, V. Yankee Atomic Electric Co YAEC-1398 84/02/29 115pp 22557 157 24X Fiche 50-029.84/03/02.8403080007
- 8403120123 Forwards proposed resolution of specific equipment environ qualification deficiencies identified in Franklin Research Ctr Technical Evaluation Rept TER-C5257-463
 KAY.J A Yankee Atomic Electric Co 84/03/03 EISENHUT.D 0
 Division of Licensing 35pp 22589 229 24X Fiche 50-029,84/03/05,8403120123
- 8403130287 Requests exemption from 10CFR50 44(c)(ii)(B), specifying requirements for containment penetrations designated for use as post-accident hydrogen recombiner, by 840405 KAY, J A Yankse Atomic Electric Co B4/03/06 CRUTCHFIELD, D Dperating Reactors Branch 5 3pp 22614 146 24X Fiche 50-029, 84/03/06,8403130287
- 8403190267 Notifies of assignment of EC Weinzinger as Chief, Reactor Projects Section IA.Div of Project & Resident Programs, effective immediately STAROSTECKI.R. Division of Project & Resident Programs 84/03/12 HEIDER.L. H. Vankee Atomic Electric Co. 2pp. 22671.299 24X Fiche 50-029,84/03/12,8403190267
- B403200284 Requests YAEC-1399P, "Determination of Decay Heat for LHR LOCA Analysis." be withheld (ref 10CFR2 790) KAY.J A Yankee Atomic Electric Co 84/03/19 CRUTCHFIELD.D Operating Reactors Branch 5 3pp 22676 246 24X Fiche 50-029.84/03/19.8403200284
- --8403200288 Requests exemption from 10CFR30. App K requirement re use of 1971 ANS std on decay heat for inifinite reactor operation w/120% uncertainty factor in alternative, proposes use of 1979 ANS std KAY. J. A Yankee Atomic Electric Co 84/03/09 Office of Nuclear Reactor Regulation. Director 3pp 22696 249. 24X Ficha 50-029.84/03/19.8403200284
- ---B403200290 "Executive Summary Rept on Justification of Modified Decay Heat Model for Yankee Nuclear Power Station " HARVEY, R C , HUSAIN, A Yankee Atomic Electric Co 84/03/09, 27pp 22696 232 24X Fiche 30-029, 84/03/19, 8403200284
- 8403270007 Responds to open item identified in util integrated assessment (NUREQ-0825). Topic III-10 A Util established criterion per Reg Quide 1 106 for thermal overload protection for motor operated valves
 KAY, J A Yankse Atomic Electric Co 84/03/22 CRUTCHFIELD, D Operating Reactors Branch 5 Spp 22769 350 24X
 Fiche 50-029,84/03/22,8403270007

DOCKETED ITEMS

- B403270003 Responds to open item identified in util integrated assessment (NUREG-0825), SEP Topic III-5 A Analysis performed per ANBI/ANS 58 2 to determine force imparted on electrical penetration Bilster 12E from break on Steam Generator 2 KAY, J A Yankee Atomic Electric Co 84/03/23 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 22767 346 24X Fiche 50-029, 84/03/23, 8403270003
- 8403300192 Forwards draft Rev 5 to Procedure IP-3838 re low voltage on Emergency Bus 1 or 6-3 480-volt bus draft Rev 5 to QP-3844 re low voltage on Emergency Bus 2 or 4-1 480-volt bus & draft Rev 5 to OP-3845 per BEF Topic VIII-1 a KAY, J A Yankee Atomic Electric Co 84/03/28 CRUTCHFIELD, D Operating Reactors Branch 5 12pp 22819 251 24X Fiche 50-029,84/03/28,8403300192
- Q Inspection reports, IE Bulletins & correspondence
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl.

 JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22709 239 24X Fiche 50-000.84/02/28.8401190072
- 8403010331 Advises that plan for exam of primary nozzles described in B40112 ltr satisfies conditions of 840103 relief requests from inservice insp requirements CRUTCHFIELD, D Operating Reactors Branch 5 84/02/29 KAY, J A Yankee Atomic Electric Co 2pp 22432 076 24X Fiche 80-029,84/02/29,8403010331
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl ORACE, J N Division of GA, Bafeguards & Inspection Programs (Post 830103). 84/03/02 Consolidated Edison Co of New York, Inc 130pp. 22552 329 24X Fiche 50-000,84/03/02,8402090007
- 8402070008 IE Info Notice 84-16. "Failure of Automatic Sprinkler 8ys Valves to Operate "Svc list encl JORDAN,E L Division of Emergency Preparadness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 122pp 22553 098 24X Fiche 50-000.84/03/02.8402070008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases" BVc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103), 84/03/02 Consolidated Edison Co of New York, Inc 119pp 22553 217 24X Fiche 50-000.84/03/02,8402090009
- B402090011 IE Info Notice 84-17. "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Tamp " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402070011
- 8402070024 IE Info Notice 84-09, Rev i, "Lessons Learned From Insps of Fire Protaction Safe Shutdown Sys" Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. i18pp 22635 049 24X Fiche 50-000, 84/03/07, 8402070024
- 8402070028 IE Info Notice 84-18. "Stress Corrosion Cracking in PWR Bys." Byc list encl JDRDAN: E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 196 24X Fiche 50-000.84/03/07.8402070028
- B402090031 IE Bulletin 84-02, "Failures of QE Type HFA Releys in Use in Class IE Bafety Sys " Svc list encl DEYOUNO, R. C. Director's Office, Office of Inspection and Enforcement, 84/03/12 Consolidated Edison Co. of New York, Inc 134pp. 22823-094 24X Fiche 30-000,84/03/12,8402090031
- E403290286 Forwards IE Insp Rept 50-029/84-02 on 840126-27 No violations noted MARTIN.T.T. Division of Engineering & Technical Programs 84/03/13 HEIDER.L H Yankee Atomic Electric Co 2pp 22800 031 24% Fiche 50-029, 84/03/13, 8403290286
- --8403290292 IE Insp Rept 50-029/84-02 on 840126-27 No violations noted Major areas inspected failure analysis & activities to replace 3/4-diameter. Schedule 80 vent line on steam generator Loop 1
 GRAY, E. H., DURR, J. P. Region 1, Office of Director 84/02/21
 3pp. 22800.033 24X Fiche 80-029.84/03/13.8403290286
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JORDAN.E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp. 22823 229, 24X Fiche 50-000.84/03/21.8402090043

- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys" Svc list encl
 JDRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 27933 001 24X Fiche 50-Q00,84/03/21,8402090044
- R Periodic operating reports & related correspondence
- B403020272 Personnel & man-rem by work & duty function rept,1983 W/ B40224 1tr ST LAURENT,N , HEIDER,L H Yankee Atemic Electric Co 83/12/31 HAYNES.R C Region 1. Office of Director 4pp 22440 227 24X Fiche 50-027,83/12/31
- 8403120181 "Semiannual Effluent Release Rept for Jul-Dec 1983 "
 W/840301 1th
 KAY, J A Yankse Atomic Electric Co 83/12/31 MURLEY, T E Region
 1. Dffice of Director 16pp 22589 135 24X Fiche 50-027,83/12/31,
 8403120181
- 8403210068 "1983 Annual Rept " W/840301 ltr HEIDER.L H Yankee Atomic Electric Co 63/12/31 MURLEY.T E Region I, Office of Director 9pp 22705 043 24X Fiche 30-027,83/12/31,8403210068
- 8403020072 Monthly operating rept for Jan 1984 W/840206 ltr WHIPPLE, S , HEIDER, L H Yankee Atomic Electric Co 84/01/31 App 22441 339 R4X Fiche 50-029,84/01/31,8403020072
- 8403300083 Monthly operating rept for Feb 1984 W/B40305 ltr WHIPPLE, S., HEIDER, L. H. Yankee Atomic Electric Co. 84/02/29 6pp 22821 181 24X Fiche 50-029,84/02/29,8403300083
- B Repartable occurrences, LERs & related correspondence
- 8211110598 Discusses failure of Westinghouse Type SC-1 1876-072 relays No further review should be conducted based on review of info ABHE,F Reactor Operations Analysis Branch 82/10/21 SEYFRIT,K V Reactor Operations Analysis Branch 3pp 22/75 235 24X Fiche 30-027,82/10/21,821110598
- B403090175 Forwards LER 84-001-00 ST LAURENT: N N Yankee Atomic Electric Co 84/02/23 MURLEY.T E Region 1. Dff;ice of Director 1p 22573 263 24X Fiche 50-029,84/02/23,8403090175
- 8403200215 LER 84-002-00 on 840214, during review for SEP Topic IV-10 A, surveillance procedure inadequacy discovered Tech Spec changes did not contain time requirement Procedure changed W/840315 ltr DRAMBRIDGE, 8 L , ST LAURENT, N N Yankee Atomic Electric Co 84/03/15 3pp 22679 320 24% Fiche 50-027, 84/03/15, 8403200215
- DOCKET 50-90 PLUM BROOK RESEARCH REACTOR FACILITY

 R Periodic operating reports & related correspondence
- 8403060405 Forwards "Annual Status Rept for 1983," per 810514 dismantling order RICHLEY.E A. BOITEL,E C. National Aeronautics & Space Admin 84/03/01 DENTON,H R. Office of Nuclear Reactor Regulation, Director 2pp 22518 292 24X Fiche 50-030.84/03/01.8403060405
- --8403060410 "Annual Status Rept for 1983 "

 * National Agronautics & Space Admin 84/02/06 8pp 22518 294
 24X Fiche 50-030,84/03/01,8403060405
- W Decommissioning Stage Documents & Correspondence
- 8403150214 EVALUATION OF NUCLEAR FACILITY DECOMMISSIONING PROJECTS Summary Report Plum Brook Reactor Facility DERGE, b +, MILLER, R L United Nuclear Corp FIN B-7568 NUREO/CR-3605 B4/02/29 Division of Engineering Technology 34pp Available at NRC 44 25 22649 032 24X Fiche 50-030,84/02/29,8403150214
- DOCKET 50-54 UNION CARBIDE RESEARCH REACTOR
 I Financial information
- 8403220043 Submits financial info re operation of facility.per 840302 request Cost estimate for decommissioning encl Annual Financial Rept.1982 forwarded MCGGVERN.J J Union Carbide Corp 84/03/15 THOMAS.C C Standardization & Special Projects Branch Spp 22712 146 24X Fiche 50-054.84/03/15.8403220043

P Operating license stage documents & correspondence

- B403130045 Application for amend to License R-B1.adding one add1 change to Tech Specs re experiment review & approval to more fully describe extent of nuclear safeguards committee responsibility RUZICKA. W G Union Carbide Corp 84/03/01 THOMAS. C D Standardization & Special Projects Branch 1p 22398 361 24X Fiche 50-054.84/03/01.8403130045
- --8403130052 Proposed Tach Spec change request re experiment review & approval

 * Union Carbide Corp 84/03/01 ip 22598 362 24X
 Fiche 50-054,84/03/01,8403130045
- 8403120294 Requests add) info re May 1980 application for license rangual re detailed estimates of total annual operating & decommissioning costs & detailed explanation of sources of funds to cover costs Info should be submitted by 840324 THOMAS.C O Standardization & Special Projects Branch 84/03/02 MCGGUVERNJ Union Carbide Corp 2pp 22596 36t 24X Fiche 50-054,84/03/02,8403120294
- 8403130178 Requests Geosciences Branch review geology & seismology sections of encl Union Carbide reactor SER for Union Carbide subsidiary company license renewal application HUMAS.C.O. Standardization & Special Projects Branch 84/03/05 JACKSON.R Geosciences Branch 31pp 22646 281 24X Fiche 50-054.84/03/05.8803150178
- 9 Inspection reports. IE Bulletins & correspondence
- 8403020278 Forwards IE Insp Rept 50-054/84-01 on 840104-06 No violations noted STAROSTECKI, R Division of Project & Resident Programs 84/02/16 MCGOVERN, J J Union Carbide Corp 2pp 22440 052 24X Fiche 50-054,84/02/16,8403020278
- --8403020305 IE Insp Rept 50-054/84-01 on 840104-06 No violations or deviations noted Major areas inspected licensee action on previous insp findings.facility reviews & audits.operator requalification training & surveillance activities MINNEY.H W. ROBERTSON.J A Region i. Office of Director ELSASSER.T C Division of Project & Resident Programs 84/02/03 10pp 22440 054 24X Fiche 50-054.84/02/16.8403020278
- R Periodic operating reports & related correspondence
- 8403270198 "Annual Rept for 1783" W/840320 ltr STRACK,R A Union Carbide Corp 83/12/31 STAROSTECKI,R Division of Project & Resident Programs 7pp 22772 014 24X Fichs 30-054.83/12/31.8403270198

DOCKET 50-62 UNIV OF VIRGINIA RESEARCH REACTOR

- F Security, medical, emergency & fire protection plans
- B403290328 Forwards updated spent nuclear fuel route from Univ of Virginia to Sayannah River.BC SHERR.T S Material Transfer Safeguards Licensing Branch 84/03/12 BENNECHE.F E Virginia. Univ of Charlottesville, VA 9pp 22822 229 24x Fiche 50-062,84/03/12,8403270328
- R Pariodic operating reports & related correspondence
- 8403010397 Annual operating rept for 1783 FARRAR, J P Virginia, Univ of, Charlottesville, VA 84/02/16 Bivision of Licensing 10pp 22433 093 24X Fiche 50-062,84/02/16, 8403010397

DOCKET 50-70 GENERAL ELECTRIC TEST REACTOR

- R Periodic operating reports & related correspondence
- 8403200242 "GE Test Reactor Annual Rept.Number 25" W/840312 ltr CUNNINGHAM, G E General Electric Co 83/12/36 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 22690 157 24X Fiche 30-070, 63/12/31, 8403200242

DOCKET 90-72 UNIV OF UTAH RESEARCH REACTOR

- F Security, medical, emergency & fire protection plans
- 8403200281 Forwards revised emergency plan, addl financial info & 1983 financial statement for Univ SANDOUIBT.O M Utah, Univ of, Balt Lake City, UT 84/03/14 THCMA8.C O Standardization & Special Projects Branch 1p 22696 281 24X Fiche 50-072,84/03/14,8403200281
- ---8403200293 Revised "Univ of Utah Emergency Plan for Training & Research Reactors " 9ANDGUIST.G M Utah, Univ of Salt Lake City, UT UTEC ME 84-0205 84/03/14 28pp 22696 282 24X Fiche 50-072,84/03/14, 8403200281
- ---8403200276 Univ of Utah operating budget 1983-84 * Utah, Univ of, Salt Lake City, UT 84/03/14 37pp 22696 310 24X Fiche: 50-072,84/03/14,8403200281
- I Financial information
- 8403200281 Forwards revised emergency plan, add1 financial info & 1983 financial statement for univ SANDGUIST.G M Utah. Univ of. Balt Lake City. UT 84/03/14 THOMAS.C O Standardization & Epscial Projects Branch ip 22496 281 24X Fiche 50~072,84/03/14.8403200281
- --8403200276 Univ of Utah operating budget 1983-84

 * Utah, Univ of, Salt Late City, UT 84/03/14 37pp
 22676 310 24% Fiche 50-072,84/03/14,8403200281
- DOCKET 50-73 GENERAL ELECTRIC NUCLEAR TEST REACTOR

 Periodic operating reports & related correspondence
- 8403150072 Annual Rept 24 of operation changes tests & experiments for OE nuclear test reactor W/840305 ltr REED.L L . CUNNINGHAM.G E General Electric Co 83/12/31 DENTON.H R Office of Nuclear Reactor Regulation, Director 7pp 22641 042 24X Fiche 50-073,83/12/31,8403150072

DOCKET 50-83 UNIV OF FLORIDA TRAINING REACTOR

- F Security, medical, emergency & fire protection plans
- 8403010247 Ack receipt of 831122 & 840201 ltrs transmitting Rev 7 to physical security plan Changes consistent w/provisions of 10CFRSD 54(p) & acceptable for inclusion into plan LEWIS.R C Division of Project & Resident Programs 84/02/24 DIAZ.N J Florida, Univ of, Gainesville, FL 2pp 22432 010 24X Fiche 50-083.84/02/24.8403010247
- P Operating license stage documents & correspondence
- B403280065 Forwards Amend 14 to License R-56 % safety evaluation Amend adds new Section 6 6 3. "Other Special Repts." to Tech Specs covering Level 1.2 or 3 personnel changes & changes in transient or accident analyses
 THOMAS.C O Standardization & Special Projects Branch 84/03/06
 DIAZ.N J Florida, Univ of, Gainesville, FL 2pp 22812 318 24X
 Fiche 50-083,84/03/06.8403280065
- --B403280068 Amend 14 to License R-56, adding new Section 6 4 3, "Other Special Repts." to Tech Specs covering Level 1,2 or 3 personnel changes & changes in transient or accident analyses
 THOMAS.C D Standardization & Special Projects Branch 55p 22812 320 24% Fiche 50-083,84/03/06.8403280065
- --8403280071 Safety evaluation supporting Amend 14 to License R-56 * Office of Nuclear Reactor Regulation, Director 84/03/06 ip 22812 325 24X Fiche 50-083,84/03/06,8403280065

DDCKET 50-113 UNIV OF ARIZONA RESEARCH REACTOR

- G Inspection reports, IE Bulletins & correspondence
- B403060165 Forwards IE Insp Rept 50-113/84-01 on 840109-10 No noncompliance identified. MENSLAWBKI.F A Region 5. Office of Director B4/02/03 GALLAGHER.R Arizona. Univ of Tucson, AZ 2pp 22517 004 24X Fiche 50-113.84/02/03.8403060165

--8403060172 IE Insp Rept 50-113/84-01 on 840109-10 No noncompliance identified Major areas inspected radiation control program. including posting & labeling, surveys & personnel radiation dosimetry SHERMAN, C I , WENBLAMBK I, F A Region 5, Office of Director 84/02/02 7pp 22517 006 24X Fiche 50-113.84/02/03.8403060165

DOCKET 50-123 UNIV OF MISSOURI RESEARCH REACTOR

G Inspection reports, IE Bulletins & correspondence

8403190085 Ack receipt of 840305 ltr informing NRC of schedule to revise & update radiation protection procedures per IE Insp Rapt 50-123/84-01
NORELIUB, C E Division of Project & Resident Programs 84/03/14
WARNER, D Missouri. Univ of, Rolla, MO ip 22669 325 24X
Fiche 50-123,84/03/14,8403190085

---8403190088 Responds to NRC 840216 ltr re violations noted in IE Insp. Rept 50-123/84-01 Corrective actions procedure changes to prevent detector from being left disconnected implemented & radiation procedures rewritten 801.0N.A E Missouri. Univ of Rolla. MO 84/03/05 NORELUS, C E Division of Project & Resident Programs 1p 22667-326 24X Fiche 50-123,84/03/14,8403190085

--8403190094 Forwards IE Insp Rept 50-123/84-01 on 840125 W/o App A describing noncompliance NORELIUB.C E Division of Project & Resident Programs 84/02/16 WARNER,D Missouri, Univ of Rolls, MO 2pp 22669 327 24X Fichs 50-123,84/03/14,8403190085

--8403190096 IE Insp Rept 50-123/84-01 on 840125 Noncompliance noted incomplete procedures re radiation protection RIDAMAY, K R, TAMBLING, T N Region 3, Office of Director 84/02/06 App 22669, 329 24X Fiche 30-123,84/03/14,840319085

DOCKET 50-133 HUMBOLDT BAY POWER PLANT, UNIT 3
F Security, medical, emergency & fire protection plans

8402230176 Forwards revised State of CA nuclear power plant emergency response plan MEDFORD, M O Southern California Edison Co 84/02/16 EIRENHUT. D Q Division of Licensing 2703pp 22353 001 24X Fichs 50-000,84/02/16,8402230176

--8403020117 Revised State of CA nuclear power plant emergency response plan. * California: State of S3/04/30. 2701pp 22353 003 24X Fiche 50-000,84/02/16.8402230176

8403270205 Discusses Southern California Edison submittal of 1783 revised State of CA emergency response plan on behalf of all State of CA plants, incorporating plan into Diablo Canyon Addl planning info will not be developed for Humboldt Bay SCHUYLER, J D Pacific Qas & Electric Co 84/03/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 22772.137 24X Fiche 50-000.84/03/22.8403270205

G Adjudicatory correspondence

B403270004 Discusses State of CA emergency response plan Plan incorporated into Diablo Camyon plan Addi planning will not be performed for Humboldt Bay per 1980 legislation Related correspondence BCHUYLER, J.D. Pacific Oas & Electric Co DBB 117 B4/03/22 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 1p 22769: 349. 24X Fiche. 50-000, 84/03/22, 8403270004

8403270037 Responds to IE Bulletin 83-07 re apparently fraudulent products sold by Ray Miller, Inc No subj matts incorporated in any safety-related sys. Related correspondence SCHUYLER, J O Pacific Gas Electric Co DSB 116 84/03/22 MARTIN, J B Region 5, Office of Director 2pp 22767 322 24x Fiche 80-133,84703/22,8403270037

I Financial information

BA03280051 Annual Financial Rept 1983 W/B40326 ltr MIELKE, F. W. BHACKELFORD, B . CRANE, P A Pacific Gas & Electric Co B3/12/31 50pp 22776 23Q. 24X Fiche 50-000, B3/12/31, B403280051

J Insurance & indemnity information

8403060178 Forwards Endorsements 101 & 102 to NELIA Policy NF-133 CRANE.P A Pacific Gas & Electric Co 84/02/28 SALTZMAN.J D Assistant Director for State & Licensee Relations 3pp 22518 345 24X Fiche 50-133.84/02/28.8403040178

P Operating license stage documents & correspondence

8403150275 Generic Ltr 84-07 to all licensees of BWRs re procedural guidance for pips replacement at BWRs Svc list encl EISENHUT.D G Division of Licensing 84/03/14 Commonwealth Edison Co 20pp 22823 354 24X Fiche 50-000,84/03/14.8403150275

@ Inspection reports, IE Bulletins & correspondence

8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York. Inc 115pp 22709 239 24X Fiche 50-000.84/02/28.8401190072

8402070007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOY & NRC " Svc list encl GRACE.J N Division of GA, Safeguards & Inspection Programs (Post 830103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000,84/03/02,8402090007

8402090008 IE Info Notice BA-16, "Failure of Automatic Sprinkler Bys Valves to Operate " Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008

8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases" Svc list encl
JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009

8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Caoling Components Below Nil Ductility Temp " Svc list encl JURBAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Conscil

B402090028 IE Info Notice B4-18, "Stress Corrosion Cracking in PWR Bys " Byc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028

8402070031 IE Bulletin 84-02, "Failures of GE Type HFA Relags in Use in Class IE Safety Bys " 8vc list encl DEYOUNG: R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000:84/03/12,8402070031

B402090043 IE Info Notice B4-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 227 24X Fiche 50-000.84/03/21,8402090043

8402090044 IE Info Notice 84-20. "Bvc Life of Relays in Safety-Related Bys " Svc list and! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp. 22933 001 24X Fiche 50-000.84/03/21, 8402090044

8403270037 Responds to IE Bulletin 83-07 re apparently fraudulent products sold by Ray Miller. Inc No subj matis incorporated in any safety-related sys Related correspondence SCHUYLER. J D Pacific Gas & Electric Co DSB 116 84/03/22 MARTIN. J B Region 5. Office of Director 2pp 22769, 322 24X Fiche. 50-133,84/03/22,8403270037

R. Periodic operating reports & related correspondence

8403020006 Monthly operating rept for Jan 1984 W/840203 ltr DERKB.P S , MEEKS.E D Pacific Gas & Electric Co 84/01/31 5p 22442 210 24X Fiche, 50-133, 84/01/31, 8403020006

8403300075 Monthly operating rept for Feb 1984 W/840305 ltr DERKS,P S , WEEKS,E D Pacific Gas & Electric Co 84/02/29 3pp 22821 302 24X Fiche 50-133,84/02/29,8403300075 DOCKET 50-139 UNIV OF MASHINGTON RESEARCH REACTOR

F Security, modical, emergency & fire protection plans

8403260340 Advises that emergency plan, submitted on 821104, does not meet requirements of App E to 10CFR30 or guidance criteria in Rev I to Reg Guide 2 & Addl info identified in Enclemergency plan review. Should be provided by 840430 THOMAS. C O Standardization & Special Projects Branch 84/03/07 ROBKIN M A Washington. Univ of Seattle. WA 5pp 22775 258 24X Fithe 50-137,84/03/07,8403260340

DOCKET 50-142 UCLA TRAINING REACTOR

- F Security, medical, emergency & fire protection plans
- 8403190010 Response opposing ABL9 840224 allegations of misrepresentation re Part 73 issues Representations accurate & no action per 10CFR2 713 should be taken HOODHEAD, C.P. Hearing Branch 4 84/03/09 Atomic Bafety and Licensing Board Panel 14pp 22665 133 24X Fiche 50-142.84/03/09, 8403170010
- --8403190015 Affidavit of CP Woodhead in response to ASLB 840224 memorandum & order re missepresentation WOODHEAD, CP Hearing Branch 4 84/03/09 33pp 22665 236 24X Fiche 50-142.84/03/09.8403190010
- --B403190022 Affidavit of JR Gray re CP Woodbead 830B15 filing Certificate of Svc encl GRAY.JR Kearing Branch 4 84/03/09 5pp 22665 26B 24X Fiche 50-142.84/03/09,8403190010

Q Adjudicatory correspondence

- 8403010248 Response to board 831223 order to respond to Committee to Bridge the Gap allegations of matl false statements Record evidence contradicts ellegations MCODHEAD, C P Hearing Branch 4 84/01/10 26pp 22432 124 24X Fiche 50-142.84/01/10.8403010248
- --B403010253 Affidavit of JR Miller in response to Committee to Bridge the Cap allegation that verification that reactor radiation was 100 rem/h at 3-ft.unshielded.was untrue HILLER, JR Operating Reactors Branch 3 B4/01/09 3pp 22432 150 24X Fiche 50-142.B4/01/10.8403010248
- --8403010255 Affidavit of RE Carter verifying that JR Miller & author performed calculations in early 1981 to assess radiation level of reactor core CARTER.R E Standardization & Special Projects Branch 84/01/09 6pp 22432
- --B403010260 Affidavit of DM Carlson showing that statement in 1979 meeting did not contradict truth of 810407 affidavit re necessity of sabotage protection at nonpower reactors CARLSON, D M NRC No Detailed Affiliation Given 84/01/10 Bpp 22432 159. 24X Fiche 50-142-84/01/10, 8403010248
- --8403010265 Affidavit of DM Carlson re areas requiring controlled access to comply w/iOCFR73 Security sys sufficient to comply w/IOCFR73 67 & no requirement exists for guard.metal or explosive detectors Centificate of Svc encl.
 CARLSON, D. M. Physical Security Licensing Dranch 81/04/17 18pp 22432 167 24X Fiche 50-142.84/01/10.8403010248
- --8403010266 Affidavit of GB Nelson to 830628 physical inventory of SNM NELSON, G B Region 5, Office of Director 84/01/09 20pp 22432 186 24x Fichs 50-142,84/01/10,8403010248
- 8403140064 Forwards entire record of saFeguards insp repts for 1975-1983 provided by Region V W/o enci.
 MODDHEAD.C Hearing Branch 4 B4/03/09 FRYE.J H. BRIGHT.G 0 .
 LEUBKE.R A Atomic Safety and Licensing Board Panel 1p 22633-084 24X Fiche.50-142,84/03/09,8403140064
- 8403140089 Response to ASLB B40224 order indicating concerns on security plan & security insp repts re sabotage matters raised by Contention XX & directing univ & staff to respond by 840309 Certificate of Svc encl.
 CORNIER.W H California. Univ of. Los Angeles. CA 84/03/09 Atomic Safety and Licensing Board Panel 130pp. 22623 175 24; Fiche 50-142.84/03/09.8403140089

- 8403170010 Response opposing ASLB 840224 allegations of misrepresentation re Part 73 issues Representations accurate & no action per 10CFR2 713 should be taken MODDHEAD.C P Hearing Branch 4 84/03/07 Atomic Safety and Licensing Buard Panel 14pp 22665 133 24x Fiche 50~142,84/03/07,8403190010
- --B403190014 Affidavit of DM Carlson in response to ABLB B40224 memorandum & order CARLBON,D M Division of Safeguerds 84/03/09 100pp 22665 147 24X Fiche 50-142,84/03/09,8403190010
- ~~8403190015 Affidavit of CP Woodhead in response to ASL8 840224 memorandum & order re misrepresentation WOODHEAD, C.P. Hearing Branch 4 84/03/09 33pp. 22665 236 24% Fiche 50-142,84/03/09,8403190010
- --8403190022 Affidavit of JR Gray re CP Woodhead 830815 filing Certificate of Svc encl GRAY, J R Hearing Branch 4 84/03/09 5pp 22665 268 24X Fiche: 50-142,84/03/09,8403190010
- 8403190157 Forwards IE itr sent to licensee re proposed renewal of DL W/o enci with the sent of DL W/o enci with the sent of Baranch 4 84/03/14 HIRSCH.D Affiliation Not Assigned ip 22468 354 24X Fiche 50~142,84/03/14.8403190137
- 8403200021 Summarizes 840309 press conference where CE Young announced that UCLA reactor shut down for repairs & would remain shut down through Dispairs & possibly thereafter BAY, J H. Committee to Bridge the Pap BAY, J H. Nuclear Law Center 84/03/14 FRYE, J H. BRIGHT, G O . LUEBKE, E A Atomic Safety and ilcensing Board Panel 3pp 22698 355 24X Fiche 50-142,84/03/14,8403200021
- B403190177 Requests notification of accuracy of Washington Post (140310 article indicating that reactor will close during Summer Olympics to avoid possibility of terrorist attack Article encl
 FRYE.J H Atomic Safety and Licensing Board Panel B4/03/15
 CORNIER.W H California, Univ of, Los Angeles, CA 2pp
 22671 165 24X Fiche 50-142.84/03/15,8403190177
- B403210027 Notifies of appraisal of DPc of IE re-protection against sabotage & IE Inep Rept 50-124/83-01 for Virginia Polytechnic Inst re-insp for radiological sabotage Related correspondence WOODMEAD.C P Hearing Branch 4 84/03/16 FRYE.J H , BRIGHT.O O . LUEBKE, F A Atomic Safety and Licensing Board Panel. 1p 22706 357 24X Fiche 50-142.84/03/16.8403210027
- B403260380 Responds to 840315 inquiry re info reported in 840310 Washington Post article Reactor will remain shut down until after Clympic Games Barricades & armed guards planned Related correspondence CORMIER.W H California, Univ of Los Angeles, CA. DBB 085 84/03/20 FRYE,J H, LUEBKE,E A, BRIGHT,G D Atomic Bafety and Licensing Board Panel 2pp 22760,140 24X Fiche:50-142,84/03/20.8403260380
- 8403240003 Memorandum & order ruling on Committee to Bridge the Oap objections to rebuttal testimony Served on 840323 LUESKE, E.A. BRIGHT, C.O., FRYE, J.H. Atomic Safety and Licensing Board Panel DSB 082 84/03/22 Committee to Bridge the Oap 31pp 22748 315. 24% Fiche 50-142,84/03/22,8403240003.
- 8403260365 Requests that review of SECY-83-500 re staff proposal to eliminate sabotage protection requirements for research reactors await completion of Ofc of Inspector & Auditor investigation W/o encls Related correspondence HIRSCH: D Government Accountability Project. DSB 105 84/03/23 PALLADINO, GILINEKY, ROBERTS Commissioners 2pp, 22760 077 24X Fiche 50-142,84/03/23,8403260365
- P Operating license stage documents & correspondence
- 8403070412 Forwards chronology of licensee activities, indicating relicensing, intervenor & hearing highlights
 BERNARD, H Standardization & Special Projects Branch. 84/03/01.
 THOMAS, C 0 Standardization & Special Projects Branch. 7pp.
 22567 013 24X Fiche 50-142,84/03/01,8403070412

DOCKET 50-146 BAXTON NUCLEAR EXPERIMENTAL FACILITY

J Insurance & indemnity information

8403280064 Forwards Endorsement 91 to Policy NF-164, Endorsements 71 & 74 to NELIA Policy NF-220, Endorsement 61 to MAELU Policy NF-107 HOFFMAN, J Marsh & McLennan, Inc 84/03/22 DIMITZ, I Assistant Director for State & Licensee Relations 7pp 22776 337 24X Fiche 50-146:84/03/22.8403280064

DOCKET 50-155 BIG ROCK POINT NUCLEAR PLANT

- F Security, medical, emergency & fire protection plans
- B403090229 Rev 42 to emergency plan implementing procedures, Vol 9A * Consumers Pawer Co 84/02/28 4pp 22571 240 24X Fiche 50-155,84/02/28,8403090229
- B403090ZiB Forwards evaluation rept of offsite radiological emergency preparedness exercise conducted on B30726 Deficiencies observed did not detract from overall demonstrated capability to protect public KRIMM.R W Federal Emergency Menagement Agency 84/03/06 JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) 7pp 22571 142 24X Fichs 50-155,84/03/06.8403090218
- --B403090221 Evaluation of State of MI.Charlevoix & Emmet Counties offsite radiological emergency preparedness exercise for Big Rock Point Nuclear Power Station * Federal Emergency Management Agency 83/07/26 43pp 22571 147 24X Fiche 50-155.84/03/06.8403090218
- 8403120097 Extends invitation to attend 840323 regional workshop in Rosemont. IL re 10CFR50. App R safe shutdown requirements. Horkshop will cover subjs described in IE Info Notice 84-09 & provide add1 guidance in safe shutdown analyses SPESBARD.R L. Division of Engineering 84/03/06 DEWITT.R B Consumers Power Co 3pp 22588.140 24X Fiche 50-135,84/03/06,8403120097
- 8403220021 Forwards exemption from requirements of Section III G 3 of App R to 10CFR50 re fire detection & fixed fire suppression sys in areas for which alternate shutdown capability provided, in reaponse to util 831020 ltr., CRUTCHFIELD, D., Operating Reactors Branch 5. 84/03/20 VANDEWALLE, D., J Consumers Power Co 3pp 22713,345 24X Fiche 50-155,84/03/20,8403220021
- ---8403220023 Exemption from requirements of Section III @ 3 of App R to iOCFR50 re fire detection & fixed fire suppression sys in areas for which alternate shutdown capability provided EISENNUT.D @ Division of Licensing. 84/03/20 Consumers Power Ca 4pp 22713 348 24X Fiche 50-155,84/03/20,8403220021

O Adjudicatory correspondence

- B403010203 Forwards licensee B40120 & 24 ltrs on Christa-Meria Bubcontention 7(3) which questions adherence to guidence of NUREO-0737 re radiation monitoring sys. Related correspondence, QALLO, J Isham, Lincoln & Beale GALLO, J Consumers Power Co B4/02/27 BLGCH, P B , PARIB, D H , SHON, F J Atomic Bafety and Licensing Board Panel 4pp 22435.283 24X Fiche: 50-155,84/02/27, B403010203
- 8403060188 Forwards replies to J O'Neill 840207 & 07 proposed findings on Contention II-D & issues other than aircraft contention FURBE, M.C. Isham, Lincoln & Beale FURBE, M.C. Consumers Power Co 84/03/01 BLOCH, P.B., PARIS, D.H., SHON, F.J. Atomic Safety and Licensing Board Panel. Ip. 22515 118 24X Fiche 50-155, 84/03/01, 8403060188.
- ~-8403060192 Reply opposing J D'Neill 840207 proposed findings of fact on O'Neill Contention II-D re aircraft hazards GALLO, J. COPELAND, V. Consumers Power Co. GALLO, J. Isham, Lincoln & Beale. 84703/01. 21pp 22515 117 24X Fichs. 50-155, 84/03/01, 8403060188.
- ---8403060202 Reply opposing J D'Neill proposed findings of fact on 'issues other than aircraft contention Findings lack merit & have no basis in record Certificate of Svc encl GALLO, J. FURBE, M C. Consumers Power Co. GALLO, J. Isham, Lincoln & Beale. 84/03/01 22pp 22515 140 24X Fiche.50-155,84/03/01,8403060188.

- 8403140076 Forwards NRC response to Intervenor J O'Neill proposed findings of fact on Contention IID re aircraft crashes, seismic crane & pool concrete integrity GUDDARD,R J Hearing Branch 3 84/03/01 BLOCH,P B, PARIS,O H, BHON,F J Atomic Safety and Licensing Board Panel 3pp 22621 338 24X Fiche 50-153,84/03/01,8403140076
- --8403140099 Response to Intervenor J D'Neill proposed findings of fact on pool concrete integrity, seismic crane & aircraft hazards contentions Proposed findings unfounded based on sample size & analysis completeness BACHMANN.R G Kearing Branch 1 GUDDARD,R J Hearing Branch 3 84/03/01 12pp 22621 341 24X Fiche 50-150,84/03/01.8403140096
- 8403120035 Notice of appearance in proceeding Certificate of Svc encl FURSE, M C Consumers Power Co 84/03/05 3pp 22589 267 24X Fiche 50-155, 84/03/05, 8403120035
- 8403080110 Memorandum & order reopening record on B-52 bomber crash probability Staff review of 1980 USAF analysis shall be filed by 840405
 BLOCH, P B , FARIS, O H , SHON, F J Atomic Safety and Licensing Board Panel 84/03/06 Office of the Executive Legal Director 6pp 22559 267 24X Fiche 50-155,84/03/06,8403080110
- 8403090132 Memorandum clarifying ABLB 840306 order (LBP 84-12A) reopening record on B-52 bumber crash probability Probability of crash on Bayshore Range or overflight of facility need not be calculated BLOCH, P B , PARIS, D H , SHON, F J Atomic Safety and Licensing Board Panel 84/03/08 3pp 22575 125 24X Fiche 50-155,84/03/08,84033090132
- B403190004 Forwards HMM Assoc. Inc revised rept. "Evacuation Time Estimates for Areas Near Big Rock Point" Related correspondence GALLO, J Isham, Lincoln & Beale GALLO, J Consumers Power Co B4/03/13 BLOCH, P B , PARIS, O H , BHON, F J Atomic Bafety and Licensing Board Panel 130pp 22665 001 24X Fiche 50-155, 84/03/13, 8403190004
- B403200130 Petition to reconsider & vacate 840306 & O7 orders & find Detourns testimony re 1780 risk analysis to be reliable & probative evidence Certificate of Svc encl GALLOJ Consumers Power Co GALLOJ Isham, Lincoln & Beale. B4/03/16 9pp. 22699 164 24X Fiche 50-155,84/03/16.8403200130
- B403260360 Response apposing licenses B40301 introduction & motion to strike Reasonable amount of time to supply more transcript citations requested if B40209 filing found deficient Related correspondence
 O'NEILL, J O'Neill, J DBB 0B4 84/03/16 Atomic Bafety and Licensing Board Panel 2pp 22760 262 24X Fiche 50-155,84/03/16.8403260360
- 8403280355 Response to licensee 840316 petition for reconsideration of ABLB unpublished 840306 memorandum & order respening hearing record on O'Meill Contention II-D Notice of appearance & Certificate of Svc enci PATTERSON,W F Hearing Branch 3 DSB 155 84/03/23 6pp 22787 204 24% Fiche, 50-155, 84/03/23, 8403280355

I Financial information

8403190071 Annual Financial Rept for 1983 W/840312 1tr BELBY, J D. FOLAHEE, J B. PERRY, P. A. Consumers Power Co. B3/12/31 OIAMBUSBO, A. Division of Licensing 34pp 22666, 136 24X Fichs. 50-000, B3/12/31, B403190071

P Operating license stage documents & correspondence

- 8403050005 Forwards notice of consideration of issuance of amend to License DPR-6 re radioactive iodine coolant concentration limits. CRUTCHFIELD,D Operating Reactors Branch 5. 84/02/22 VANDEMALLE,D.J Consumers Power Co 4pp 22490 065 24X Fiche 50-155,84/02/22,8403050005
- --B403050006 Notice of consideration of issuance of amend to License DPR-6 & proposed NBHC determination & apportunity for hearing based on 831216 request re radioactive fodine coolant concentration limits
 CRUTCHFIELD, D. Operating Reactors Branch 5 84/02/22 7pp 22490 069 24X Fiche, 50-155, 84/02/22, 8403050005
- 8403050121 Forwards notice of consideration of issuance of amend to License DPR-6, based on 811215 & revised 831216 applications Amend changes Tech Specs re stack gas monitoring sus CRUTCHFIELD, D. Operating Reactors Branch 5 84/02/22 VANDEWALLE, D. J. Consumers Power Co. 4pp. 22488 032 24X Fiche 50-155,84/02/22,8403050121

- 8403060039 Board Notification 84-041 forwards util 840202 updated proposed resolutions & commitments per integrated assessment of plant Several issues under litigation before ASLB reproposed expansion of spent fuel pool storage capacity MIRAGLIA:F J. Assistant Director for Safety Assessment 84/02/24 BLOCH.P B . PARIS, O H . SHON, F J. Atomic Safety and Litensing Board Panel 5pp 22548 283 24X Fiche 50-155,84/02/24,8403060039
- B402060356 Advises that justification of unlimited or limited use of purge sys during normal operations will not be pursued Sys will not be pursued Sys will only be operated during cold shotdown condition Info requested in NRC B40126 ltr no longer required JOHNSON. B D Consumers Power Co 84/03/01 CRUTCHFIELD. D Operating Reactors Branch 5 ip 22519 206 24X Fiche 50-135,84/03/01.8403060356
- 8403060321 Forwards request for add1 info re updated inservice testing program for pumps & valves described in B30121 ltr Conference call to discuss items requested CRUICHFIELD. D. Operating Reactors Branch 5 84/03/02 VANDEWALLE, D. J. Consumers Power Co. App. 22513 116 24X Fiche 50-155.84/03/02.8403060321
- B403090210 Advises that util B40220 proposed variance for high-range stark gas monitors unacceptable Sys should be modified to meet display guidance of NUREG-0737. Item II F 1(1), "Addi Accident Monitoring Instrumentation"

 CRUTCHFIELD.D Operating Reactors Branch 5 84/03/07 VANDEMALLE: D J Consumers Power Co 5pp 22574 358 24X Fiche 50-000.84/03/07.8403090210
- 8403i60122 Summary of 840222 meeting w/util in Bethesda, MD re 840202 submittal updating integrated assessment Conclusions on listed items provided EMCH.R L Operating Reactors Branch 5 84/03/13 Operating Reactors Branch 5 4pp 22652 020 24X Fiche 50-155, 84/03/13, 8403i60122
- 8403150275 Generic Ltr 84-07 to all licenses of BWRs re procedural guidance for pipe replacement at BWRs Svc list encl EISEXHUT.D G Division of Licensing 84/03/14 Commonwealth Edison Co 20pp 22823 354 24X Fiche 30-000,84/03/14,8403150275
- 8403300308 Board Notification 84-054 forwards NRC evaluation & conclusion re util variance from NVREG-0737 guidance concerning high range stack gas monitor (TMI Item II F 1 1)
 HIRAGLIA:F J Assistant Director for Safety Assessment 84/03/14
 BLOCM:P B . PARIB:O H . SHON:F J Atomic Safety and Licensing Board Panel 7pp 22844 282 24% Fiche 50-155,84/03/14.8403300308
- 8403190178 Forwards safety evaluation approving util response to NUREO-0737. Item 11 K 3 44, "Evaluation of Anticipated Transients W/Single Failure to Verify No Fuel Failure " Issue resolved CRUTCHFIELD.D Decrating Reactors Branch 5 84/03/15 VANDEMALLE, D J Consumers Power Co 6pp 22671 167 24X Fiche 50-155.84/03/15,8403190178
- B403200177 Forwards comparison of proposed radiological effluent Tech Specs (RETS) w/model BMR RETS & comparison of proposed offsite dose calculation menual w/NRC generic guidelines & NUREO-0133
 GRUTCHFJCLD.D Operating Reactors Branch 5 B4/03/15
 VANDEHALLE.D J Consumers Power Co 157pp 22697 206 24X
 Fiche 90-155.86/03/15.8403200177
- B403230143 Forwards corrected safety evaluation re NUREG-0737. Item II K 3 44, "Evaluation of Anticipated Transients ut/Single Failure to Verify No Fuel Failure " Item resolved for facility GRUTCHFIELD.D Operating Reactors Branch 5 84/03/22 VANDEMALLE.D J Consumers Power Co 5pp 22730 142 24X Fiche 50-155.84/03/22.8403230143
- 8403270104 Forwards SER for SEP outstanding hydrologic issues identified during review of integrated plant safety assessment rept (NURES-0828) Issues include local plant flooding from PMP t flood emergency plan CAUTCHFIELD D Operating Reactors Branch 5 84/03/22 VANDEWALLE D J Consumers Power Co 3pp 22774 032 24X Fiche 50-158,84/03/22.8403270106
- ~~8403270113 SER re SEP outstanding hydrologic issues PMP flooding would not cause failures of sys required for safe shutdown * Office of Nuclear Reactor Regulation, Director 84/03/22 6pp 22774 APR PAY No. 30-155,84/03/22:8402270106

- 8403280034 Summary of 840314 meeting w/util & INEL in Bethesde.MD reenviron equipment qualification (EEQ) for facility Util will submit enalyses regeneral profile & temp spike & addi info concerning EEG by 840304 Viewgraphs encl EMCH.R L. Operating Reactors Branch 5 84/03/26 Uperating Reactors Branch 5 21pp 22777 023 24X Fiche 50-155:84/03/26, 8403280074
- 8403290187 Responds to NRC request for graphic representation of info on revised Table 4-1. "Hydrostatic Yest Pressure/Temp Limits, Heatup Pressure Temp Limits & Cooldown/Temp Limits," per 831024 Tech Spec change request Graphs encl KRICH, R M Consumers Power Co 84/03/26 CRUTCHFIELD.D Operating Reactors Branch 5 4pp 22801 024 24X Fiche 50-155,84/03/26, 800220187
- 8403290249 Submits add1 info re containment water level & pressure monitoring sys.per 840312 request Power supply voltage variations effect negligible on overall sys accuracy XRICH.R M Consumers Power Co. 84/03/26 CRUTCHFIELD.D Operating Reactors Branch 5 1p. 22800 042 24X Fiche 50-155,84/03/26,
- Q Inspection reports, IE Bulletine & correspondence
- 8401190072 IE Info Notice 84-13. "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list enc!

 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22909 239 24X Fiche. 50-000.84/02/28, 8401190072
- 8403120131 Responds to IE Bulletin 83-07. "Apparently Fraudulent Products 801d by Ray Miller, Inc " Purchase order records for 1975-79 reviewed & 14 suspect purchase orders found No matis supplied on orders gurchased from Ray Miller, Inc JOHNBON, B D Consumers Power Co 84/03/01 KEPPLER, J Q Region 3, Diffice of Director 2pp 22588 238 24X Fiche 50-000,84/03/01, 8403120131
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl GRACE.J N Division of GA. Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York. Inc 130pp 22552 329 24X Fichs 50-000,84/03/02,8402090007
- 8402040008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 078 24X Fiche 50-000,84/03/02,8402090008
- 8402070009 IE Info Notice 84-15, "Reporting of Radiological Releases"
 Eve list encl
 JURDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc. 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8402090011 IE Info Notice 84-17. "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8402070024 IE Info Notice 84-07.Rev i, "Lossons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JURDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000.84/03/07, 8402090024
- 8402070028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Sys " Svc list and I JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22584 186 24X Ficha 50-000,84/03/07,8402090028
- 840207003) IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000,84/03/12,8402090031
- 8402090043 IE Info Notice 84-19. "Two Events Involving Unauthorized Entries into PHR Reactor Cavities" See list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York. Inc 123pp 22823 229. 24% Fiche 50-000.84/03/21.8402090043

- 8402070044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related
 - 4020V0044 IE Info Notice 84-20. "SVC Lite of Melays in Safety-Related Bys " SVc list encl JDRDAN.E L Division of Emergency Preparedness & Engineering Raspanse (Post 830103) 84/03/21 Consolidated Edison Co of Naw York. Inc 135pp 22733 001 24X Fiche 30-000.84/03/21.8402090044
- R Periodic operating reports & related correspondence
- 8403080131 "Semiannual Radioactive Effluent Release Rept.Jul-Dec 1983 " 903080131 "Semiannual Radioactive Erribent Release Rept, Jul-Dec 19 W/B40229 ltr KRICH,R M Consumers Power Co 83/12/31 KEPPLER,J G Region (Office of Director 12pp 22559 166 24X Fiche 50-155,83/12/31 8403080131 Region 3.
- 8403080141 "Annual Operating Rept Occupational Exposure, 1983 " W/840229 RICH,R M Consumers Power Co 83/12/31 KEPPLER, J Q Region Dffice of Director 4pp 22559 223 24X Fiche 50-155,83/12/31,8403080141
- 8403020088 Monthly operating rept for Jan 1984 W/840203 ltr BALCH.L L . HOFFMAN,D P Consumers Power Co 84/01/31 22442 292 24X Fiche 50-155,84/01/31,8403020088
- 8403300152 Corrected monthly operating rept for Feb 1984 W/840307 ltr BALCH.L., HOFFMAN.D P Consumers Power Co 84/02/29 2pp 22819 350 24X Fiche 50-155,84/02/29,8403300152
- B Reportable occurrences, LERs & related correspondence
- 8403080249 Confirmatory action ltr re problems w/Anchor-Darling valves used in reactor depressurization sys Caused by increased closing air pressure to 130 psig resulting in binding Addl ; air pressure to tab ,-.. testing required t.J G Region 3, Office of Director 84/03/02 REYNOLDS.J W mars Power Co 2pp 22556 291 24X Fiche 50-155.84/03/02. KEPPLER, J G Region : Consumers Power Co
- 8403120078 Updated PNO-III-84-020A three reactor depressurization sys valves failed Caused by binding of disc in seat resulting from increase in closing air pressure Reactor restarted & in situ testing conducted DEFAYETIER Region 3, Office of Director 84/03/06 1, 22586 305 24X Fiche 50-155,84/03/06,8403120078
- 8403270065 LER 84-001-00 on 840228, three of four reactor 403270066 LER 84-001-00 on 840228, three of four reactor depressurization sys isolation values failed to operate in open position Caused by increased air supply pressure to gate value Air pressure reduced W/840322 ltr CABTIGLIONE, L. KRICH, R M Consumers Power Co 84/03/22 22766.255 24X Fiche 80-155,84/03/22,8403270066

DOCKET 50-156 UNIV OF WIBCONSIN RESEARCH REACTOR

H General correspondence

- 8403200020 Informs that JA Franzen & GC Penn removed from appointments as reactor operators at facility
 MATUBENIC, B M Wisconsin, Univ of, Madison, WI 84/03/15
 Standardization & Special Projects Branch ip 22698 354 24X
 Fiche 50-156,84/03/15,8403200020
- DOCKET 50-166 UNIV OF MARYLAND RESEARCH REACTOR
- P. Operating license stage documents & correspondence
- 8403210124 Application for renewal of License R-70 All future 903210124 Application for renewal of License R-70 All future correspondence re license should be addressed to F Kerr. TOLL.J B Maryland. Univ of, College Park. MD 84/03/15 THOMAS.C O Btandardization & Special Projects Branch 1p. 22707:185 24X Fiche.50-164.84/03/15,8403210124
- --8403210126 Tech Specs for Univ of Maryland training reactor * Maryland, Univ of, College Park, MD 84/03/15 42pp 22707 186. 24X Fiche 50-166,84/03/15,8403210124.

DOCKET 50-170 NATIONAL NAVAL MEDICAL CENTER

Q Adjudicatory correspondence

8403190182 Order granting joint motion for approval of stipulation & withdrawal of intervenor, licensee & NRC motions for summary disposition Adjudicatory proceedings dismissed HOYT, H F Atomic Safety and Licensing Board Panel, 84/03/15 Office of the Executive Legal Director 3pp 22670 320 24X Fiche: 50-170,84/03/15,8403190182

- DOCKET 50-171 PEACH BOTTOM ATOMIC POWER STATION, UNIT 1 R Periodic operating reports & related correspondence
- B403230012 "Annual Decommission Rept.1983 " W/B40320 ltr FLEISCHMANN.R Philadelphia Electric Co 83/12/31 Operating Reactors Branch 4 2pp 22727 357 24X Fiche 50-171.83/12/31.8403230012 STOLZ, J F
- W Decommissioning Stage Documents & Correspondence
- B403230012 "Annual Decommission Rept.1983 " W/B40320 ltr FLEISCHMANN,R. Philadelphia Electric Co. 83/12/31 ! Operating Reactors Branch 4 2pp 22727 357 24X Fichs 50-171.83/12/31.8403230012 STOLZ, J F
- DOCKET 50-102 PURDUE UNIV RESEARCH REACTOR
- F Security, medical, emergency & fire protection plans
- 8403190211 Forwards IE Safeguards Insp Repts 50-182/84-01 & 70-0152/84-01 on 840216-17 No noncompliance identified AXELBON,W L Region 3, Office of Director 84/03/14 LYKQUDIS,P Purdue Univ , West Lafayette, IN 2pp 22671 109 24X Fiche 50-182,84/03/14,8403190211
- Q Inspection reports. IE Bulletins & correspondence
- 8403190211 Forwards IE Safeguards Insp Repts 50-182/84-01 & 70-0132/84-01 on 840216-17 No noncompliance identified AXELBON,W L. Region 3, Office of Director 84/03/14 LT Purdue Univ . West Lafagette. IN 2pp 22671 109 24X LYKOUDIS, P Fiche 50-182,84/03/14,8403190211
- DOCKET 50-185 PLUM BROOK REACTOR MOCK-UP
- R Periodic operating reports & related correspondence
- 8403060405 Forwards "Annual Status Rept for 1983," per 810516 NO30A040B Forwards Annual Gubert Recommend of the Admin Recommendation of the Recommenda
- --8403040410 "Annual Status Rept for 1983 " * National Aeronautics & Space Admin 84/02/06 8pp 22518 274 24X Fiche 50-030,84/03/01,8403060405

DOCKET 50-201 WEST VALLEY REPROCESSING PLANT

- Q Adjudicatory correspondence
- 8402220157 Order extending time until 840228 for Commission to act to review Director's Decision DD-83-14 CHILK.8 J Office of the Secretary of the Commission 84/02/21 Commissioners 1p 22337 362 24% Fiche 50-000,84/02/21. Commissioners 8402220157
- 8403010238 Order extending time until 840305 for Commission to act to review Director's Decision DD-83-14 & 831029 decision denuing request of Environ Policy Inst CHICK.8 J Office of the Secretary of the Commission 84/02/28 Commissioners ip 22434 210 24X Fiche 50-000,84/02/28. 8403010238
- 8403090069 Informs that Commission unanimously declined to review Director's Decision DD-83-14 Time provided by NRC regulations within which Commission may act to review expired Decision became final agency action on 840305 CHILK, 8 J Office of the Secretary of the Commission 84/03/06 CELEBREZZE, A J Chio, State of Egp 22575 350 24X Ficha 50-000,84/03/08,8403090069 84/03/08
- 8403090074 Informs that Commission unanimously declined to review Director's Decision DD-83-14 Time provided by NRC regulations within which Commission may act to review expired Decision became final agency action on 840305 CHILK, S J Office of the Secretary of the Commission 84/03/08 MILLAR, E Environmental Policy Institute 1p 22575 272 247 Fichs 50-000,84/03/08.8403090074 84/03/0B

- 8403090113 Informs of Commission decision not to review Director's Decision DD-83-14 Time for Commission to act expired on 840305 W/o encl
 CHILK,8 J Office of the Secretary of the Commission 84/03/08 RESNIKOFF, H Sierra Club 1p 22576 079 24X
 Fiche 50-000,84/03/08,8403090113
- DOCKET 50-206 SAN UNDERS NUCLEAR STATION, UNIT 1

 F. Security, medical, emergency & fire protection plans
- 8402030338 Forwards revised "Emergency Plan Implementing Procedures, San Dnofre Nuclear Generating Station, Units 1, 2 % 3 " CRDY, PA Southern California Edison Co 84/01/27 NRC - No Betailed Affiliation Given 1p 22064 013 24X Fiche 50-206, 84/01/27, 8402030338
- --8402030344 Revised "Emergency Plan Implementing Procedures, San Unofre Nuclear Generating Station, Units 1,2 & 3 " ANDERSON, C K , PATRISSI, O A Southern California Edison Co 84/01/27 525pp 22064 015 24X Fiche 50-206, 84/01/27, 8402030338
- 8403050148 Forwards "Evaulation of Southern California Edison
 Site-Specific Offsite Radiological Emergency Preparedness
 Prompt Alent & Notification Bys Evaluation " Bys adequate to
 alent & notify public in event of accident
 SPECM. B W Federal Emergency Management Agency 84/01/31
 DIRCKB.W J Office of the Executive Director for Operations ip
 22487 314 24X Fiche 50-206.84/01/31.8403050148
- --8403050172 "Evaluation of Bouthern California Edison Site-Specific Offsite Radiological Emergency Preparadness Prompt Alert & Notification Sys "

 * Federal Emergency Management Agency 84/01/05 6ipp 22487 315 24X Fiche 50-206.84/01/31.8403050148
- 8403130031 Ravs to emergency plan implementing procedures, including EPIP S0123-VIII-0 202, "Assignment of Emergency Response Personnel" & S023-VIII-1, "Recognition & Classification of Emergencies" MyB40227 ltr

 UENNETT, D D , PEACOR, D H , CROY, P A Southern California Edison Co 84/02/15 68pp. 22643 207 24X Fiche 50-206, 84/02/15, 8403150031
- 8402230176 Forwards revised State of CA nuclear power plant emergency response plan
 MEDFORD,M O Southern California Edison Co 84/02/16
 EISENHUT,D G Division of Licensing 383pp 22393 001 24X
 Fiche 50~000.84/02/16.8402230176
- --B403020117 Revised State of CA nuclear power plant emergency response glan * California, State of 83/04/30 2901pp 22353 003 24X Fiche 50-000,84/02/16,8402230176
- 8403050127 Forwards exemption from MOCFR50, App E. Bection IV F 1 re requirement for state & local participation in annual emergency plan exercise scheduled for 840229 EISENHUT, D G Division of Licensing 84/02/29 BASKIN, K P Southern California Edison Co 3pp 22489-165 24X Fiche 50-206,84/02/29,8403050127
- --8403050132 Exemption from IOCFR50, App E. Section IV F t re requirement for state & local participation in annual emergency plan exercise scheduled for 840229 MIRAGLIA F J Division of Licensing 84/02/29 Southern California Edison Co 3pp 22489 148 24X Fiche 50-206,84/02/29,8403050127
- 8403270236 Forwards Rev 12 to physical security plan Rev withheld (ref 10cFR73 21)
 HAYNES, J O. Southern Celifornia Edison Co. 84/03/07 MARTIN, J B
 Region 5. Office of Director 2pp 22772 031 24X
 Fiche 50~206.84/03/07.8403270254
- B403200097 Informs that emergency operations facility HVAC control logic mod & procedures necessary to implement HVAC isolation completed prior to B40227 commitment date MEDFORD, M O. Bouthern California Edison Co B4/03/14 EIBENNUT. B O Division of Licensing ip 22479 075 24X Fiche 50-208.84/03/14.8403200097.
- 8403220018 Forwards "Updated Fire Hazards Analysis, Vols 1-4,"

 BABKIN, K.P. Southern California Edison Co. 84/03/19 DENTON, H.R.
 Office of Nuclear Reactor Regulation, Director 10pp 22735 238

 24X Fiche 50-206/84/03/19,8403220018

- --B403220024 "Tests for Fire Protection for Complete Fire Engulfment of Cable Trays & Conduits Containing Grouped Electrical Conductors, Test Rept on Kaowool " CHAILLE, C E Bouthern California Edison Co 78/10/24 7pp 22735 248 24X Fiche 50-206.84/03/19.8403220018
- --8403220027 "Updated Fire Harards Analysis, Vols 1-4 "
 * Southern California Edison Co 84/03/19 1178pp 22735 341 24X Fireb 50-206, 84/03/19, 8403220018
- 8403270205 Discusses Bouthern California Edison submittal of 1983 ravised State of CA emergency response plan on behalf of all Btate of CA plants, incorporating plan into Diablo Canyon Addl planning info will not be developed for Humboldt Bay SCHUYLER, J O Pacific Gas & Electric Co 84/03/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 22772 137 24X Fiche 50-000,84/03/22,8403270205
- B403280030 Responds to NRC fire protection review of installed mods 3 two areas of nonconformance Corrective actions add1 fire stop installation expected to be complete prior to startup from present outage & pressure verification retested MEDFORD, M D Southern California Edison Co 84/03/26 CRUTCHFIELD, D Operating Reactors Branch 5, 2pp 22777 046 24X Fichs 50-206.84/03/26.8403280030
- 8403270122 Forwards examples of data output from technical support ctr accident monitoring sys computer supplementing 83:110 ltr re containment pressure, water level & hydrogen monitor instrumentation, per NRC request MEDFORD.M O Southern California Edison Co 84/03/27 CRUTCHFIELD.D Operating Reactors Branch 5 5pp 22806 357 24X Fiche 50-206.84/03/27.8403290122
- H General correspondence
- 840312003B Requests notification whether util committed in writing or orally to counter proposals or mods to integrated living schedule contained in Denton 84020B itr to Baskin BRONSKI.D , MCDDNALD.J E Sierra Club 84/03/05 CRUTCHFIELD.D Defice of Nuclear Reactor Regulation, Director ip 22590 317 24X Fiche 50-206,84/03/05.840312003B
- B403140043 Requests that HB Stoehr be removed from distribution list & that L Bernath be added HULSEY. S A San Diego Oas & Electric Co 84/03/12 EISENHUT. D G Division of Licensing ip 22455 083 24X Fiche 50-204. 84/03/12, 8403140043
- J Insurance & indemnity information
- B403040395 Forwards Endorsements 100 & 8B to NELIA Policy NF-146 & MAELV Policy MF-3B, respectively RDCCO, J Southern California Edison Co 84/02/29 DINITZ, I Office of Nuclear Reactor Regulation, Director 3pp 22518 152 24X Fiche 50-204, 84/02/29, 8403060395
- P Operating license stage documents & correspondence
- 8403020222 Notifies that Class III fee rather than Class II fee appropriate for review of Amend 72 to License DPR-13, since review involved consideration of single safety issue Remittance of addl sum requested DIGGS.R M License Fee Management Branch 84/02/27 RAY.H B Bouthern California Edison Co ip 22494 323 24X Fiche 50-206.84/02/27,8403020222
- 8403160078 Bummary of B40208 & 07 meetings w/util.Woodward/Clyde Consultants & Bachtel at site & in Los Angeles.CA, respectively.re BEP Topics II-4 F. "Settlement of Foundations & Buried Equipment" & III-6 CHENG.T M Systematic Evaluation Program Branch 84/02/27 GRIMES.C 1 Systematic Evaluation Program Branch 7pp 22662 268 24X Fiche 50-206.84/02/27.8403160078
- 8403050156 Notification of 840308 meeting w/util in Bethesda, MD to discuss licenses 840227 revised integrated living schedule MCKENNA.E Operating Reactors Branch 5 84703702 CRUTCHFIELD, D Operating Reactors Branch 5. 2pp 22513 355 24X Fiche 50-206,84/03/02,8403060156
- 8403070254 Notifies that info re BEP integrated assessment originally scheduled to be submitted by \$40305 will not be provided until \$40330 due to necessity of further review KRIEGER,R W Southern California Edison Co 84/03/02 CRUTCHFIELD.D Deprating Reactors Branch 5 1p 22547 274 24X Fithe \$0-206.84/03/02.8403070254

- 8403090195 Discusses seismic evaluation of structural elements, per 84020B ltr Yield displacement of steel beams should be used to calculate ductility factors instead of calculated plastic moment capacity of beams MIRAGLIA, F J Assistant Director for Safety Assessment 84/03/07 BASKIN, K Southern California Edison Co 4pp 22575 145 24X Fiche 50-206,84/03/07,8403090195
- B403130216 Forwards request for add1 info re Proposed Changes 76 & 126 to Tech Specs Info requested within 30 days of 1tr date CRUTCHFIELD.D Operating Reactors Branch 5 B4/03/09 BASKIN, K P Southern California Edison Co 5pp 22614 105 24X Fiche 50-206,84/03/09.8403130216
- 8403160013 Forwards "Evaluation of Natural Circulation Cooldown Test
 Performed at San Onofre Nuclear Generating Station " Rept
 provides evaluation of applicability of results to 8t Lucie
 Unit 2
 WILLIAMS.J W Florida Power & Light Co 84/03/13 EISENHUT.D Q
 Division of Licensing 1p 22652 179 24X Fiche 50-000,84/03/13,8803140013
- B40327035B Requests appropriate Class III fee for review of Proposed Change 123 to License DPR-13 dtd B30707 re purying & venting of containment MILLER.W O License Fee Management Branch B4/03/13 MEDFORD,M O Bouthern California Edison to 2pp 22787 346 24X Fishe 50-206.84/03/13.8403270358
- 8403160251 Notifies that add1 time required to process proposed Tech Spec changes re RCB heatup & cooldown curves Submittal expected by 840325

 KRIEGER,R W Southern California Edison Ca 84/03/14
 CRUTCHFIELD,D Operating Reactors Branch 5 1p 22660 123 24X
 Fiche 50-206,84/03/14,8403160251
- B403220001 Summary of B40308 meeting w/utils in Betheada, MD re licensee revised proposal for integrated living schedule submitted by B40227 ltr List of attenders & agenda encl MCKENNA, E Operating Reactors Branch 5 B4/03/20 Operating Reactors Branch 5 B4703/20, B40322001
- 840322012; Forwards revised pages to 831213 submittal of radiological effluent Tech Specs.per 840131 telcon Summary of changes listed MEDFORD.M O Southern California Edison Co 84/03/20 CRUTCHFIELD.D Operating Reactors Branch 5 2pp 22716 219 24X Fiche 50-206.84/03/20.8403220121
- --8403220125 Revised pages to radiological effluent Tech Bpecs re radioactive gaseous effluent monitoring instrumentation * Bouthern California Edison Co 84/03/20 5pp 22716 221 24) Fiche 50-206,84/03/20,8403220121
- 8403230070 Notification of 840328 meeting w/util in Bethesda, MD to discuss util proposed integrated living schedule MCKENNA,E M Operating Reactors Branch 5 84/03/20 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 22726 328 24X Fiche 30-206.84/03/20,8403230070
- 8403270182 Responds to 840216 ltr re operability of 6-inch butterfly valves used for containment venting Valves do not have to be closed when reactor not in cold shutdown or refueling mode

 MEDFORD, M O Bouthern California Edison Co 84/03/27
 CRUTCHIELD, D Operating Reactors Branch 5 3pp 22803 326, 24X Fiche 50-206, 84/03/27, 8403270182
- 8403290275 Provides justification why limiting use of 6-inch containment vent sys considered unnecessary Based on info provided, vent sys demonstrated capable of performing intended isolation function under transient conditions MEDFORD, M O Southern California Edison Co 84/03/27 CRUTCHFIELD, D Operating Reactors Branch 5 5pp 22800.037 24X Fiche. 50-204.84/03/27,8403270275
- G. Inspection reports, IE Bulletins & correspondence
- B403080408 F0IA request for repts of insp carried out under Condition 2 of Nuclear Energy Liability policies for facilities CALSOYAB, C D Affiliation Not Assigned 84/02/07 Region 5, Dffice of Director. 4pp 22567 341 24X Fiche: 50-000,84/02/07, 8403080408
- 8403060025 Forwards IE Insp Repts 50-206/83-28,50-361/83-43 & 50-362/83-42 on 831210-840121 No noncompliance noted BIBHOP, TW Division of Resident Reactor Project & Engineering Programs 84/02/09 BASKIN, K. P. Southern Callifornia Edison Co 2pp 22516,285 24X Fiche 50-206,84/02/09,8403060025

- --8403060029 IE Insp Repts 50-206/83-28,50-361/83-43 & 50-362/83-42 on 831210-840121 No noncompliance or deviations noted Major areas inspected operational safety verification, power ascension transient testing & maint activities CHAFFEE.A E , STEMART, J P , D'ANOELO, A Region 5, Office of Director 84/02/07 13pp 22516 287 24X Fiche 50-206,84/02/09,8403060025
- 8403060008 Forwards IE Insp Repts 30-206/84-02:50-361/84-02 & 50-362/84-02 on 840115-20 No noncompliance noted WENSLAMSKI.F A Region 3. Office of Director 84/02/16 BASKIN.K B Snuthern California Edison Co 2pp 22516 268 24X Fiche 50-206:84/02/16:840306008
- --B403040019 IE Insp Repts 50-204/B4-02.50-361/B4-02 & 50-362/B4-02 on B40115-20 No nuncompliance or deviations noted Major areas inspected radiation protection program, health physics & chemistry training & general emplayee training SHERMAN, C I , WENSLAMSKI, F A Region 5, Office of Director B4/02/15 | 15pp | 22516 270 | 24X Fiche 50-206.84/02/16,8403060008
- 8403080419 Responds to FDIA request for repts of insp carried out under Condition 2 to Nuclear Energy Liability policies for facilities NRC does not have repts FELTON.J M Division of Rules and Records 84/02/22 CALSOYAS.C D Affiliation Not Assigned 1p 22567 345 24X Fiche 50-000.84/02/22.8403080419
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22707 237 24X Fiche 50-000,84/02/28,8401170072
- 8403190367 Forwards IE Insp Repts 50-206/84-04.30-361/84-05 k 50-362/84-05 on 840123-27 No noncompliance noted WENSLAMSKI.F A Region 5. Office of Director 84/03/01 8ASKIN.K B Southern California Edison Co 2pp 22675 220 24X Fiche 50-206.84/03/01.8403190367
- --8403190373 IE Insp Repts 50-206/84-04.50-361/84-05 & 50-362/84-05 on 840123-27 No noncompliance noted Major areas inspected. radiological environ monitoring program & followup on licensee action re previous insp findings YUHAS.0 P. HENBLAHSKI,F A Region 5. Office of Director 84/03/01 &pp 22675 222 24X Fiche.50-206.84/03/01.8403190367
- 8402090007 IE Info Natice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE, J N Division of GA, Bafeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 327 24% Fiche 50-000:84/03/02,8402090007.
- B40207000B IE Info Notice B4-16, "Failure of Automatic Sprinkler Bys Valves to Operate " Syc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000,84/03/02,8402070008
- 8402090009 IE Info Notice 84-15, "Reporting of Rediological Releases "
 Bvc list encl
 JURDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc. 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitragen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN: E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402070011
- 8402090024 IE Info Notice 84-09,Rev i. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl.
 JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07. Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000.84/03/07.8402090024
- 8402090028 IE Info Notice 84-18. "Stress Corrosion Cracking in PWR Sys " Syc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc. 1189p 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8402070031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Syc list enc!
 DEYQUNO.R C Director's Office Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823,074 24X Fiche 50-000-84/03/12,8402070031

8402090039

- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 123pp 22823 229 24% Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Syc : JORDAN, E. L. Vork. Inc 135pp 22933 001 24X Fiche 50-000.84/03/21, 8402090044
- R Periodic operating reports & related correspondence
- 8403060438 "Annual Personnel Honstoring Rept, 1983 " W/840229 ltr MAYNES, J G Southern California Edison Co 83/12/31 4pp 22511 189 24% Fiche 50-206.83/12/31.8403060438
- 8403020218 Monthly operating rept for Jan 1984 W/840215 ltr MDRRIS.C A . HAYNES.J G Bouthern California Edison Co 6pp 22440 263 24X Fiche 50-206.84/01/31.8403020218 84/01/31
- 8403300003 Monthly operating rept for Feb 1784 W/840312 ltr MDRRIS.C A , HAYNES, J @ Southern California Edison Co B4/02/29 App 22822 119 24X Fiche 50-204.84/02/29.8403300003
- S Reportable occurrences, LERs & related correspondence
- 8403010451 Informs Commission of problems w/emergency diesel generators mfg by Transamerica Delaval Inc DIRCKE W J Office of the Executive Director for Operations SECY-83-034 84/01/25 4pp 22438 347 24X Fiche 50-000,84/01/25. 8403010451
- 8403010207 Forwards "Investigation of Types AF & AE Piston Skirts." per #USDUMENT FORWARDS "Investigation or types AF & AE Miston Stirts." Transamerica Belaval. Inc Dumers Group program commitments

 Rept evaluates cracks in AF piston skirts in Shoreham &
 Grand Gulf Nuclear Power Stations

 MUSELER. W J TDI (Transamerica Delaval, Inc.) Gumers Group
 MUSELER. W J Long Island Lighting Co. 84/02/27 DENTON. H R
 Office of Nuclear Reactor Regulation. Director 3pp. 22434 090
 24X Fiche 50-000,84/02/27,8403010207
- 8403140203 Forwards "Operating History Overview for Diesel Generators in Nuclear Svc," comparing Transamerica Delaval, Inc generators w/generators mfg by other vendors HEBDDN.F.J. Program Technology Oranch 84/02/27 BEALINGER.C H NRC No Detailed Affiliation Given ip 22638 319 24X Fiche 50-000.84/02/27,8403140203
- --8403140205 "Operating History Overview for Diesel Generators in Nuclear 8vr " # Director's Office 84/02/29 65pp 22638 320 24X Fishe 50-000, 84/02/27, 8403140203
- 8403010218 Forwards task descriptions for 16 known problems re Transamerica Delaval, Inc. omergency diesel generators MUSELER, W. J. IDI (Transamerica Delaval, Inc.) Owners Group MUSELER, W. J. Long Island Lighting Co. 84/02/28 DENTON, H. f. Office of Nuclear Reactor Regulation, Director. 42pp. 2243: 24X Fiche 50-000,84/02/28,8403010218 22435 177
- 8403060194 RO on B4011B.during 6-month fire detector surveillance.Zone 4 detector failed to actuate deluge sys in hydrogen seal oil unit area Caused by sticking deluge solenoid valve Fire watch established & valve repaired HAVNES.J G Southern California Edison Co 84/02/28 MARTIN,J B Region 5. Office of Director 19, 22517 354 24X Fachs 50-206.84/02/28.8403060194
- 8403020275 Responds to reliability survey questions re diesel generator startup & operation Responses to NRC request for addl info re Transamerica Delaval emergency diesel generators will be 22440 074 24X

int Evaluation,"

76 24X

- 8403050399 Provides add1 info re reactor coolant gas vent sys,per NUREO-0737. Item II B i Bys used to purge nitrogen accumulated in reactor vessel head on 831i18 RCS will be vented periodically to reduce nitrogen pressure MEDFORD. M D Bouthern California Edison Co 84/03/02 CRUTCHFIELD. D Operating Reactors Branch 5 3pp 22518 271 Fiche 50-206.84/03/02.8403060399 22518 271 24X
- 8403140048 Forwards "Grand Gulf Component Tracking Sys," "Shoreham Component Tracking Sys" & "Transamerico Delaval: Inc Diesel Generators Clumers Group Program Plan," to resolva concerns w/emergency diesel generators MUSELER, W J Long Island Lighting Co B4/03/02 DEI Office of Nuclear Reactor Regulation. Director 2pp 24X Fiche 30-000,84/03/02.8403140048 DENTON, H R
- --8403140095 "Transamerica Delaval, Inc Diesel Generators Comers Group Program Plan "

 * TD1 (Transamerica Delaval, Inc.) Owners Group 84/03/02
 261pp 22628 223 24X Fiche 50-000,84/03/02,8403140048
- 8402090039 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delaval. Inc (TDI) Owners Group Distribution list encl EISENHUT.D G Division of Licensing 84/03/12 PALLADING Commissioners 5pp 22708 001 24X Fiche 50-000,84/03/12,
- ---B403060536 Forwards summary of 840210 meeting w/Transamerica Delaval.
 Inc Owners Group in Bethesda. HD re problems w/emergency
 diesel generators
 CARUSO.R Licensing Branch 2 84/02/27 O'REILLY, J P NRC No
 Detailed Affiliation Given App 22708 006 24X
 Fiche 50-000.84/03/12.8402090039
- --B403060554 Transcript of 840210 meeting w/Transamerica Delaval.Inc Dwners Group in Bethesdo.MD re problems w/emergency diesel generators * NRC - No Detailed Affiliation Given 84/02/10 147pp 6/201 008 24% Fiche 50-000, 84/03/12.8402090039
- ---B403070409 Summary of B40216 meeting w/Transamerica Delaval, Inc Owners Group in Wading River, NY re program plan to establish reliability of diesel generators Agenda, meeting transcript & attendance list encl ER.M A Licensing Branch 4 84/02/27 Licensi 22708 161 24X Fiche 50-000,84/03/12,8402090039 MILLER, M A Licensing Branch 4
- --8403070423 Transcript of 840216 conference in Wading River,NY re Transamerica Delaval. Inc diesel generators Pp 1-82 * Commissioners 84/02/16 84pp 22708.169 24X Fiche 50-000,84/03/12,8402090039
- B403140050 Forwards "Design Review of Connecting Mod Bearing Shells for Transamerica Delaval Enterprise Engines" for Shoreham & Grand Gulf diesel generators MUSELER, W J Long Island Lighting Co 84/03/12 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22632 074 24X Fiche 50-000, 84/03/12, 8403140050
- B403150133 Forwards "Transamerica Delaval. Inc Diesel Generator Rocker Arm Capacrew Btress Analysis Rept " Capacrew design adequate for applicable engines & svc conditions MUSELER.W. J TDI (Transamerica Delaval. Inc.) Owners Group MUSELER.W. J Long Island Lighting Co. 84/03/13 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 22639 270 24X Fiche 50-000.84/03/13.8403150133
- --8403150154 "Emergency Diesel Generator Rocker Arm Capscrew Stress Analysis," prepared for Transamerica Delaval, Inc Duners Grava * Stone & Webster, Inc 84/03/31 27pp 22639 272 24X Fiche 50-000,84/03/13,8403150133
- 840319037A PNS-V-84-004 on 840314 licenses notified that results of chemical tests performed on contractor employees suspected of possession or use of controlled substances while onsite
- 8403200222 Responds to 840214 Requests for Info 1 & 2 re R-4 series engines List indicating engine number model & svc number. customer name & address, rating, date shipped & date started MATHEMB, C S. Transamerica Delaval, Inc. 84/03/16 EISENHUT, D, O Division of Licensing 20pp 22691 177 24X Fiche 30-000,84/03/16, 8403200222

- 8403210065 LER 84-001-00 on 840215 tear gas drifted onto site Plant to personnel precautions taken Cause unknown Investigation conducted by Marine Corps to determine whether gas came from training exercises at Camp Pendleton W/840316 ltr HAYNES, J G Bouthern California Edison Co 84/03/16 3pp 22704 357 24X Fiche 50-206.84/03/16.8403210065
- 8403270219 Part 21 rept rg broken contact carrier in control device of 7 5 kV-15 kV, 500-750 MVA, 5 kV 350-3, 000 & all HKV circuit breakers Initially reported on 830223 Addenda to installation & maint procedures sent to affected units DUVALL, D D Brown Boveri Corp (subs of Brown Boveri & Ca , Ltd) 84/03/19 Record Services Branch (Document Control Desk) 5pp 22772 114 24X Fiche 50-000,84/03/19,8403270219
- 8403270132 Forwards "Emergency Diesel Generator Air Start Valve Capscrew Dimension & Stress Analysis," prepared by S&W for Transamerica Delaval, Inc. (TDI) Diesel Generator Dumers Oroup MUSELER, W. J. TDI (Transamerica Delaval, Inc.) Owners Group MUSELER, W. J. Long Island Lighting Co. 84/03/23 DENTON, H.R. Defice of Nuclear Reactor Regulation. Director 2pp 22774 001
- B403270134 Requests meeting on B4041B to discuss short-term & long-term corrective actions & investigations re Transamerica
 Delayal dissel generators List of suggested meeting topics
 encl
 MCGAUGHY, J P TDI (Transamerica Delayal, Inc.) Owners Group
 MCGAUGHY, J P Mississippi Power & Light Co B4/03/23 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 4pp 22769 133
 24X Ficher 50-000, 84/03/23, 8403270134

T Hearing transcripts on non-antitrust matters

24X Fiche 50-000 84/03/23,8403270132

- B402090039 Spard Notification B4-052 forwards meeting summaries containing transcripts of B40210 & 16 meetings between NRC & Transamerica Delaval, Inc (TDI) Owners Group Distribution list encl.
 EISENHUT, D 9 Division of Licensing 84/03/12 PALLADING Commissioners 5pp 22708 001 24X Fiche 50-000, B4/03/12, 8400200039
- --8403060536 Forwards summary of 840210 meeting w/Transamerica Delaval.
 Inc Gungers Group in Bethesda, MD re problems w/emergency
 dissel generators
 CARUSO, R Licensing Branch 2 84/02/27 D'REILLY.J P NRC No
 Detailed Affiliation Given App 22708 006 24X
 Fiche 50-000, 84/03/12, 8402090039
- ---8403060554 Transcript of 840210 meeting w/Transamerica Delaval.Inc Owners Group in Bethesda,MD re problems w/emergency diesel generators * NRC - No Detailed Affiliation Given 84/02/10 147pp 67201 008. 24X Fiche 50-000,84/03/12,8402070039
- --8403070409 Summary of 840216 meeting w/Transamerica Delaval, Inc Dwners Group in Wading River, NY re program plan to establish reliability of diesel generators Agenda, meeting transcript & attendance list encl MILLER, M A Licensing Branch 4 84/02/27 Licensing Branch 4 8pp 22708 161 24X Fiche 50-000.84/03/12,8402090039
- --8403070423 Transcript of 840216 conference in Wading River, NY re Transamerica Delaval, Inc diesel generators Pp 1-82 * Commissioners 84/02/16 84pp 22708:169 24X Fiche 50-000,84/03/12,8402090039

X Onsite Storage of Low Level Waste

8403060363 Forwards program description for weste classification & form to be used to implement 10CFR61 & 10CFR20 311 requirements re land disposal of radwaste & stds for protection from radiation
MEDFORD, M D Southern California Edison Co 84/03/02
EISENHUT, D Q Division of Licensing Bpp 22518 207 24X
Fiche. 50-206,84/03/02,8403060363

DUCKET 50-213 HADDAM NECK PLANT

- F. Security, medical, emergency & fire protection plans
- 8403070289 Public version of Rev 12 to emergency plan. W/receipt form & JM Felton 840307 release memb DDNDFRID, M Connecticut Yantee Atomic Power Co. 83/12/15 EIBENHUT, D NGC No Detailed Affiliation Given 209pp 22596 134 24X Fiche 50-213, 83/12/15, 8403070289.

- B403260143 Forwards general position statement on Reg Quide 1 97. Rev 2 re justification of significant generic deviations, per NUREO-0737. Suppl 1 COUNSIL.W 9. SEARS.C F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNBIL.W 9 Connecticut Yankee Atomic Power Co B4702/27 MILLER.J R Operating Reactors Branch 3 CRUTCHFIELD, D Operating Reactors Branch 3 Jpp 22758 162 24X Fiche 50-000.84/02/27.8403260143
- --8403260151 General position statement on Reg Quide 1 97,Rev 2 reinstrumentation for assessing plant & environ conditions during & following accidents

 * Northeast Nuclear Energy Co (subs of Northeast Utilities) & Connecticut Yankee Atomic Power Co * Northeast Utilities 84/02/29 69pp 22758 165 24X Fiche 50-000.84/02/27.8403260143
- 8403190243 Notification of 840418 workshop in King of Prussia, PA to discuss lessons learned from recent App R fire protection safe shutdown insp & topics described in IE Info Notice 84-09 Agenda for workshop enc!

 MURLEY, T.E. Region 1. Office of Director 84/03/09 D'TOOLE, J D Gonsolidated Edison Co. of New York, Inc. HEIDER, L.H. Yankee Atomic Electric Co. COUNSIL, W. O. Connecticut Yankee Atomic Power Co. 35pp. 22672 062 24X Ficher 50-000, 84/03/09, 8403190243
- 8403260146 Forwards revised procedures for corporate organization for nuclear incidents procedure manual, including Procedure CONI re table of contents & CONI i 05 re corporate emergency operations ctr operations H/o encl COUNBIL, W Q , SEARS, C F Connecticut Yankee Atomic Power Co COUNBIL, W Q , Northeast Nuclear Energy Co (subs of Northeast Utilities) 84/03/07 EISENHUT, D Q Division of Licensing 2pp 22750 330 24X Fichs 50-000,84/03/09,8403260146
- 8403270068 Revised emergency plan implementing procedures, including Rev 21 to EPIP 1 5-2 re notification & communication, Rev 3 to EPIP 1 5-13 re personnel accountability & Rev 1 to EPIP 1 5-41 re core damage estimate procedure. W/840309 Itr COUNBIL, W G , SEARS, C F Connecticut Yankse Atomic Power Co 84/03/09 EISEMHUT, D Q Division of Licensing 55pp 22766 262 24X Fichs 50-213,84/03/09,8403270068
- 8403190151 Ack receipt of 840216 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-213/83-28 MARTIN T T Division of Engineering & Technical Programs. 84/03/13 COUNSIL.W G Connecticut Yankes Atomic Power Co 2pp. 22668 329 24X Fiche 50-213.84/03/13.8403190151
- --8403190155 Responds to NRC 840120 ltr re violations noted in IE Insp Rept 80-213/83-28 Corrective actions two employees who have not received proper training removed from emergency on-call schedule & will not be reassigned until trained CDUNSIL.W Q Connecticut Yankse Atomic Power Co 84/02/16 MARTIN.T T Division of Engineering & Technical Programs 3pp. 22668 331 24X Fichs 50-213,84/03/13,8403190151
- B403270008 Informs that util will provide info re planned deviations from Suppl i to NUREO-0737 by B40501 Pelay has no effect on achedules for implementation of Suppl 1 to NUREO-0737 COUNSIL.H 9 . SEARS, C F Connecticut Yankes Atomic Power Co COUNSIL.H 9 . Northeast Nuclear Energy Co (subs of Northeast Utilities) B4703/16 EIBENHUTD 0 Division of Licensing 2pp 22770 011 24X Fichs 50-000.84/03/16, B403270008

J Insurance & indomnity information

- 8403140092 Forwards Endorsements 1,2 & 3 to NELIA Certificate N-11 & Endorsements 1,2 & 3 to MAELU Certificate M-11 SINIBI, J M Marsh & McLennan, Inc 84/03/05 SALTIMAN, J D. Assistant Director for State & Licensee Relations 25pp 22623:306 24X Fiche 50-213,84/03/05.8403140092.
- 8403140116 Forwards Endorsement 70 to MAELU Policy MF-39 & Endorsements 79 & 80 to NELIA Policy NF-151 BINIBI, J M Connecticut Yankee Atomic Power Co 84/03/05. BALTZMAN, J D Assistant Director for State & Licensee Relations 4pp. 22620 334 24X Fiche 50-213.84/03/05.8403140116
- P Operating license stage documents & correspondence
- 8403010340 Corrects incorrect statement re problem associated w/drawing containment air sample using post-accident sampling sys per TMI Item II B 3, Valve is motor operated three-way valve COUNBIL.W.O Connecticut Yankee Atomic Power Co. 83/11/10. MURLEY.T E. Region 1. Office of Director. ip 22432 327. 24X Fiche 50-213,83/11/10,8403010340.
- B403010391 Bummarizes findings from audit of TMI action items during wk of B31024 Item II B 3: "Post-Accident Sempling Sys (PASS)," findings are of most concern Corrective actions listed CDUNBIL,W 0 . DPEKA.J F Connecticut Yankee Atomic Power Co. B3/11/23 MURLEY.T E Region i. Office of Director. 4pp 22434 068 24X Fichs 50-213,83/11/23,8403010391

- 84030A0325 Forwards HCAP-10433, "Determination of Copper Content of Longitudinal Meld Seams in Intermediate Shell Region of Haddam Nack Reactor Vessel," confirming past estimates of copper content & through-wall distribution COUNSIL.W G Connecticut Yankee Atomic Power Co 84/02/17 CRUTCHFIELD, D Operating Reactors Branch 5 ip 22513 320 24X Fichs 50-213,84/02/17,84030A0325
- --8403060326 "Determination of Copper Content of Longitudina) Held Seams in Intermediate Shell Region of Haddan Neck Reactor Vessel "
 80008.R S . YANICHKO.S E Westinghouse Electric Corp MCAP-10433
 83/11/30 11pp 22513 321 24X Fiche 50-213.84/02/17,
 8403060325
- 8403050105 Advises that operability testing of RCS vent valves will be performed per requirements of ASME. Section XI, Subsection IMV-3410, for Category B valves.per NNREG-0737. Item II B 1 COUNSIL. W G COUNSIL. W G COUNSIL. W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL. W G Northeast Utilities Set/02/21 MILLER. J R Operating Reactors Branch 3 CRUTCHFIELD, D Derating Reactors Branch 5 CPUTCHFIELD, D COUNSIL W G Northeast Utilities Set/02/21 MILLER. J R Operating Reactors Branch 5 CPUTCHFIELD, D COUNSIL W G Northeast Utilities Set/02/21 MILLER. J R Operating Reactors Branch 5 CPUTCHFIELD, D COUNSIL W G NORTH MILLER. J R OPERATING MILLER. J R OPERATING MILLER W G NORTH M G NORTH MILLER W G NORTH M G NORTH M
- B403070003 Requests, within 15 days, fee for 831024 application for amend to Tech Specs re operator staffing DIGGS.R M Licanse Fee Management Branch B4/02/24 CDUNSIL.W G Connecticut Yankee Atomic Power Co 1p 22862 352 24X Ficher 50-213.84/02/24,8403070003
- B403010384 Forwards SER for SEP Topic II-3 C, "UHS " Issue adequately resolved based on review of B31114 ltr Resolution will be incorporated in suppl to integrated plant safety assessment rept (NUREO-0826)
 CRUTCHFIELD.D Operating Reactors Branch 5 B4/02/28 COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) opp 22434 Odi 24% Fiche 50-213,84/02/28.8403010384
- 8403140014 Discusses review of post-TMI periodic testing program including containment atmosphere sampling portion of post-accident sampling sys.normal containment gas sampling sys in integrated test unnecessary COUNSIL.N O . SEARS.C F Connecticut Vankee Atomic Power Co 84/02/29 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 22633 288 24X Fiche 30-213.84/02/29.8403140014
- 8403130027 Informs that Amends 54.92 & 87 to Licenses DPR-61.DPR-21 & DPR-65.respectively, inadvertently eliminated reporting requirements for exceeding radiological limiting conditions for operation Corrective actions identified COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W G Connecticut Yankee Atomic Four Co COUNSIL.W G Northeast Utilities 84/03/01 MILLER.J R Operating Reactors Branch 3 CRUTCHFIELD, D Operating Reactors Branch 5 4pp 22615 107 24X Fishe 50-000.84/03/01.8403130027
- 8403150350 Notification of 840327 meeting w/util in Bethesda.MD to discuss integrated living schedule MINER.S Operating Reactors Branch 4 84/03/07 STOLZ.J F Operating Reactors Branch 4 2pp 22647 (OB 24X Fiche 50-213.84/03/07.8403150350
- 8403260162 Application to amend License DPR-61 based on granting relief from ASME Code volumetric requirements & visual inap of welds & internal surfaces of reactor coolant pumps Class III license amend fee encl
 COUNSIL.W G Connecticut Yankee Atomic Power Co 84/03/12 CRUTCHFIELD.D Operating Reactors Branch 5 4pp 22750 349 24X Fiche 50-213,84/03/12,8403260162
- 8403260200 Comments on Issue 3 of NUREG-0885, "NRC Policy & Planning Guidance, 1984" Seven themes identified represent important abjectives for industry COUNSIL, W G Northeast Utilities 84/03/12 DIRCKS, W J Office of the Executive Director for Operations 4pp 22756 204 24% Fiche 50-000,84/03/12,8403260200
- 8403260252 Maintains position that changes in Amend 57 to License DPR-51 re transmission rights-of-way, ministerial in nature, required as matter of law & therefore require no license amend fee COUNSIL.W G Connecticut Yanker Atomic Power Co 84/03/12 MILLERAW D License Fee Management Branch 2pp 22754 311 24X Fichs 50-213,84/03/12,8403260252
- 140329027B Responds to SEP Topic VIII-3 B re dc power sys bus voltage monitoring & annunciation Commitment to provide battery current indication in control room during 1984 refueling outage retracted COUNSIL.N G Connecticut Yankee Atomic Power Co 84/03/22 CRUTCHFIELD.D Operating Reactors Branch 5 2pp 22801 330 24X Ficha 50-213,84/03/22,840329027B

- G Inspection reports, IE Bulletims & correspondence
- 8403010399 Forwards IE Insp Rept 50-213/84-02 on 840103-31 No violations observed STAROBIECKI,R Division of Project & Resident Programs 84/02/16 CDUNSIL,W G Connecticut Yankee Atomic Power Co 2pp 22434 029 24X Fiche 50-213
- --8403010404 IE Insp Rept 50-213/84-02 on 840103-31 No violations identified Major areas inspected control room, turbine bldg, primary auxiliary bldg & auxiliary feed pump room, plant operations & surveillance testing program SMETLAND.P D. Region i, Office of Director ELSASSER.T C Division of Project & Resident Programs 84/02/16 15pp 22434 031 24X Fich, 50-213.84/02/16.8403010379
- 8401170072 IE Info Notice 84-13. "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22707 237 24X Fiche 50-000.84/02/28,8401170072
- 8403070137 Informs that util does not intend to perform mechanical snubbar functional testing referenced in ASME Code as part of inservice insp during refueling outage Testing will be performed upon equipment delivery COUNSIL.W 9 . DPEKA.J F Connecticut Yankee Atomic Power Co 84/02/28 CRUTCHFIELD.D Deperating Reactors Branch 5 2pp 22375 060 24X Fiche 50-213.84/02/28.8403070137
- B402090007 IE Info Notice 84-14. "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE.J N Division of GA, Safeguards & Inspection Programs (Post 830103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329. 24% Fiche 50-000.84/03/02.8402090007
- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list and J JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 122pp. 22553 098 24X Fiche 50-000.84/03/02.8402090008
- 8402090009 IE Info Notice 84-15. "Reporting of Radiological Releases" 8vc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 119pp 22583 217 24% Fichs 50-000,84/03/02,8402090009
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Delow Nil Ductility Temp " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fichs 50-000.84/03/05,8402090011
- B402070024 IE Info Nutice B4-09, Rev 1. "Lessons Learned From Insps of Fire Protection Bafe Shutdown Bys " Bvc list encl JORDAN,E L Division of Emergancy Preparedness & Engineering Response (Post B30103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000.84/03/07.8402070024
- B402090028 IE Info Notice 84-18, "Stress Carrosion Cracking in PWR Sys " Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 630103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8403230136 Amends 830510 response to IE Bulletin 82-02, Listed commitments, including visual exam of RCPB threaded fasteners, deleted due to overly-conservative interpretation of bullstin Future exams will be per ABME Section XI COUNSIL, W 0 , SEARB.C F Connecticut Yankes Atomic Power Co 84/03/079 MRLEY, T E Region 1, Office of Director 2pp 22730 140 24X Fichs 50-213,84/03/07,8403230136
- 8402070031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Glass IE Safety Bys " Byc list encl DEYGUNO,R C Director's Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24% Fiche 50-000.84/03/12,8402090031
- 8403260162 Application to amend License DPR-61 based on granting relief from ABME Code volumetric requirements & visual insport welds & internal surfaces of reactor coolant pumps Class III license amend fee encl COUNBIL.W G Connecticut Yankee Atomic Power Co 84/03/12. CRUTCHFIELD, D Derakting Reactors Branch 5 4pp 22750 349 24X Fiche: 50-213.84/03/12,8403260162

- 8403190151 Ack receipt of 840216 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-213/83-28
 MARTIN.T T Division of Engineering & Technical Programs 84/03/11
 COUNSIL, W O Connecticut Yankee Atomic Power Co 2pp 22668 329
 24% Fiche 50-213.84/03/13.8403190151
- --8403190155 Responds to NRC 840120 ltr re violations noted in IE Insp Rept 50-213/83-28 Corrective actions two employees who have not received proper training removed from emergency on-call schedule & will not be reassigned until trained CDUMSIL.W 0 Connecticut Yankee Atomic Power Co 84/02/16 MARTIN.T T Division of Engineering & Technical Programs 3pp 22668 331 24X Fiche 50-213,84/03/13.8403190151
- B403220136 Provides results of reevaluation of performance assessment, per util 831219 ltr addressing topics discussed at 831129 SALP mgt meeting Category 1 rating will be assigned to refusing area for Millstone 2 Explains Category 2 ratings MURCEY.TE Region 1, Office of Director 84/03/16 CDUNBIL.W 9 Northeast Nuclear Energy Co (subs of Northeast Utilities) 4pp 22716 047 24X Fiche 50-000,84/03/16,8403220136
- 8402070043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list and UNRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 227 24X Fiche 50-000.84/03/21,8402070043
- B402070044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc list anci JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp. 22933 001 24X Fiche 50-000,84/03/21,8402070044
- E403300144 Responds to IE Bulletin 83-09. "Electrical Circuit Breakers W/Undervoltage Trip Featurs in Use in Safety-Related Applications Other Than Reactor Trip Sys " Haddem Neck facility uses 31 Westinghouse-type DB breakers COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W G Connecticut Yankes Atomic Power Co COUNSIL.W G Northeast Utilities 84/03/21 NURLEY.T E Region 1, Office of Director 4pp 22820 068 24X Fiche 50-000.84/03/21, B403300144
- 8403300161 Ack receipt of 840301 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-213/83-26
 MARTIN.T T Division of Engineering & Technical Programs 84/03/23
 COUNSEL, W O Connecticut Yankee Atomic Power Co 2pp 22820 054
 24X Fiche 50-213,84/03/23,8403300161
- --8403300iá6 Responds to NRC 840i31 ltr re violations noted in IE Insp Rept 50-213/83-26 Corrective actions Procedure CHDR I B revised on 840224 to document alternative method of performing filtration & counting of filtration papers COUNSIL.N G. BEARS, C.F. Connecticut Yankee Atomic Power Co 84/03/01 MARTIN, T.T. Division of Engineering & Technical Programs 2pp 22820 056 24X Fiche 50-213,84/03/23,8403300161
- R. Periodic operating reports & related correspondence
- B403230022 "Haddam Neck Plant & Hillstone Station Units 1 & 2 Annual Rept.1983 " W/B40301 ltr COUNBIL.W 9. BEARB.C F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) COUNBIL.W G. Connecticut Yankee Atomic Power Co. B3/12/31 MURLEY.T E. Region 1, Office of Director. 348pp 22727 001 24X Fichs 50-000, B3/12/31, 8403230022
- E403020093 Monthly operating rept for Jan 1984 W/840215 ltr UNIKEWICZ,S , GRAVES,R H Connecticut Yankee Atomic Power Co 84/01/31. 10pp 22442.321 24X Fiche 50-213,84/01/31,8403020093
- B403130283 Forwards "Semiannual Radioective Effluent Release Rept, JulDec 1983 "Due to new computerized data hase mgt sys,
 calculations of meteorological joint frequency distributions
 & offsite dose estimates delayed until 840430
 COUNSIL.W G , BEARS.C F, Connecticut Vankee Atomic Power Co
 84/03/01 MWRLEY.T E Region I Office of Director 1p
 67207:324 24X Fiche, 50-213, 84/03/01, 8403130283
- ---8403130289 "Bemiannual Radioactive Effluents Release Rept, Jul-Dec 1983 " * Connacticut Yankee Atomic Power Co 83/12/31 15pp. 22608 002, 24X Fiche: 50-213,84/03/01,8403130283

- S Reportable occurrences. LERs & related correspondence
- 840302023B PND-II-84-020 labor contract w/Intl Brotherhood of Electrical Workes expires at midnight on 840287 Possibility exists that workers will reject contract & not rept to work on 840302 Supervisory personnel will continue operations GREEMMAN, E Region 2. Office of Director LIPINSKI, D Region 1. Office of Director 84/02/27 1p 22440 093 24X Fiche 50-213.84/02/27.8403020238
- DOCKET 50-219 OYSTER CREEK NUCLEAR POWER PLANT

 F Security, medical, emergency & fire protection plans
- B403130269 Forwards IE Insp Rept 50-219/83-26 on 831107-1231 & notice of violation STAROSTECKI.R Division of Project & Resident Programs 84/02/27 FIEDLER.P B General Public Utilities GPU Service Corp 2pp 22605 181 24X Fiche 50-219.84/02/27.8403130269
- --8403130272 Notice of violation from insp on 831107-1231 * Region I, Office of Director 84/02/27 ip 22605 183 24X Fiche 50-219.84/02/27.8403130269
- --8403130280 IE Insp Rept 50-219/83-26 on B31107-1231 Violation noted failure of Survaillance Procedure 645 6 012. "Fire Pump Functional Test" to incorparate Tech Spec change COMPCILL C. (CONNERS E. Region 1. Office of Director B4/02/15 11pp 22605 184 24% Fiche 50-219.84/02/27.8403130269
- B403190243 Notification of B40418 workshop in King of Prussia.PA to discuse lessons learned from recent App R fire protection safe shutdown insp & topics described in IE Info Notice 84-09 Agenda for workshop encl MURLEY.T E Region 1, Office of Director B4/03/09 D'TDQLE.J D Consolidated Edison Co of New York, Inc KOBER.R W Rochester Oas & Electric Corp KEMPER.J S Philadelphia Electric Corp XEMPER.J S Philadelphia Electric Co 35pp 22672 062 24X Fiche 50-000.84/03/09.8403190243
- 8403190063 Forwards 46 oversize drawings submitted in conjunction w/831216 submittal re fire hazards analysis rept & 10CFR50. App R.Section III 6. "Bafaty Shutdown Evaluation " Aperture cards are available in PDR FIEDLER.P B General Public Utilities GPU Service Corp 84/03/12 CRUTCHFIELD.D Operating Reactors Branch 5 ip 22673 080 24X Fiche 30-217.84/03/12.8403190063

H General correspondence

- 8403060231 Forwards ordinance prohibiting import of spent nuclear fuel or radwasts for storage within township & regulating storage of spent nuclear fuel & radwasts at facility NRC requested to meet w/township to discuss problem DELO, H A Lacey Township, NJ 84/03/01 DENTON, H R Dffice of Nuclear Reactor Regulation, Director 4pp 22516.161 24X Fichs 50-219,84/03/01,8403060231
- 8403270015 Requests that R Arnold be removed from NRC correspondence distribution list & PR Clark be added as president of OPU J Knubel should be deleted from "cc" listing as manager of BWR licensing Unly titles should be used in future THORPE, J R General Public Utilities GPU Service Corp. 84/03/26 CRUTCHFIELD, D. Operating Reactors Branch 5 2pp 22806, 205 24X Fiche 50-217,84/03/26,8403270015
- P Operating license stage documents & correspondence
- 8403140340 Summary of 831215 meeting w/GE & Mark I Owners Group in Bethesda.MD re Mark I containment wetwell-drywell vacuum breaker design methodology SIEOSL.B L. Operating Reactors Branch 2 84/02/21 Operating Reactors Branch 2 51pp 22635 198 24X Fiche 50-000.84/02/21. 8403140340
- 8403050070 Forwards Class III fee for Amend 70 to License DPR-14, per B40210 request THORPE, J.R. General Public Utilities - GPU Service Corp. 84/02/27 DIGOS, R.M. License Fee Management Branch 2pp. 22490 185 24X Fiche 50-217,84/02/27,8403050070
- 8403010290 Notification of 840307 meeting w/util in Bethesda.MD to discuss detailed control room design & review process LOMBARDO, J Deerating Reactors Branch 5 84/02/29 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 22434 R61 24X Fiche 50-219.84/02/29.8403010290

- 27 Forwards corrected Page 3 1-8 (Table 3 1 1) of Amend 71 to s DPR-16 Replacement corrects error in Table 3 i 1. ctive Instrumentation Requirements "
- treeve instrumentation Requirements "
 HFIELD,D Operating Reactors Branch 3 84/03/05 FIEDLER,P b
 -al Public Utilities 990 Service Corp 3pp 22516 006 24x
 50-219,84/03/05,8403060327
- 50328 Corrected Page 3 i-8 (Table 3 1 1) of Amend 71 to License -[6,correcting error in Table 3 1 i, "Protective rumentation Requirements"

 IRC No Detailed Affiliation Given 84/03/05 ip 22016 008
- : Fiche 50-219,84/03/05,8403040327
- 99 Forwards info in response to NRC B20630 ltr re NUREQ-0737. II B 3. "Fost-Accident Bampling Bys " W/three oversite 1gs Aperture cards are available in PDR R.P B Oeneral Public Utilities OPU Service Corp 84/03/06 HFIELD.D Operating Reactors Branch 5 35pp 22608 246 24X 50-219.84/03/06.8403130199

- 194 Forwards request for add1 info re full-term OL conversion on review Response requested by 840331 to be consistent
 version achedule One day site visit tentatively
 uled for first wk in Apr 1984
 HFIELD, D. Operating Reactors Branch 5 84/03/07 FIEDLER, P. B.
 val Public Utilities 098 Service Corp 5pp 22559 218 24X 50-219,84/03/07,8403080094
- 297 Approves proposed disposal methods for contaminated ete Evaluation complete
 HFIELD.D. Operating Reactors Branch 5 B4/03/08 FIEDLER.P B ral Public Utilities 0PU Service Corp 2pp 22572 204 24x 50-219.84/03/08.8403090297
- OB3 Forwards Rev I to expended safety parameter display sys) schedule Planned Cycle II refueling outage will rt completion of basic BPD9 in 1986 Remaining liation work to be completed during Cycle II refueling ER.P II General Public Utilities QPU Service Corp. 84/03/09 NHUT.D 0 Division of Licensing 3pp 22642 392 24X 50-219,84/03/09.8403150083
-)203 Forwards revised page of Tech Spec Change Request 103, 'parating 878 definition of hot shutdown condition into ing condition for operation action statement 'RT, M W General Public Utilities QPU Service Corp 84/ CMFIELD, D Operating Reactors Branch 5 to 22655 242 50-219,84/03/12,8403160203 64/03/12
- 160204 Revised Tach Specs incorporating STS definition of hot itdown condition into limiting condition for operation tion statement General Public Utilities GPU Service Corp 84/03/12 lp .55 243 24% Fiche 50-219.84/03/12.8403160203
- 0002 Forwards "Oyster Creek Nuclear Generating Station Generic sis of 4160-Volt Buitchgear & 460-Volt Unit Substation nets," in response to SEP Topic III-6, "Beismic Design idenations"
- iderations LER.P.D General Public Utilities - OPU Bervice Corp B4/ TCHFIELD,D Operating Reactors Branch 5 2pp 22713.001 a 50-219,84/03/13,8403220002 B4/03/13
- 220004 "Oyster Creek Nuclear Generating Station Seismic Analysis 4160-Volt Buitchgear & 460-Volt Unit Substation binets "
- binets 83/11/30 96pp 22713 003 MPR-794 MPR Associates, Inc. X Fiche, 50-217, 84/03/13, 8403220002
- 0152 Forwards "Turbine Bldg Tornado Evaluation, SEP Topic III-2 & Yornado Loadings," per request
 M.ER.P B General Public Utilities GPU Bervice Corp 84/03/1
 17CHFIELD D Operating Reactors Branch 5 1p 22714 001 24)
 s 50-219,84/03/13,8403220152 84/03/13
- 3220155 "Turbine Bldg Tornado Evaluation, SEP Topic 111-2 Wind &
- 50275 Qeneric Ltr 84-07 to all licenses of BWRs re procedural iance for pipe replacement at BWRs Bvc list encl NHUT, D 0 Bivision of Licensing 89/03/14. Commonwealth son Co 20pp 22823 354. 24X Fiche: 50-000; 84/03/14; 8403150275
 - 'fies that Class III fee rather than Class IV fee 'withdrawal of 810313 application for Tech core sgray chargers & piping, Refund
 - cense Fee Management Branch 84/03/15 FIEDL Utilities 0PU Service Corp 1p 22844.306 /03/15.8403300304. FIEDLER P B

- 8403220012 Forwards responses to listed 831207 requests for info re environ qualification of electrical equipment, including resolution of deficiencies & TMI action plan items (NURED-0737) to be installed at end of Cycle 10 outage FIEDLER.P 8 General Public Utilities OPU Service Corp 84/03/16 CRUTCHFIELD.D Operating Reactors Branch 5 18pp 22712 343 24: Fichs 30-219.84/03/16.8403220012
- 8403270165 Informs that provisions of Code Cases N-341 & N-356 re NDE personnel qualification will be adopted Time period for requalification increased to 5 yrs FIEDLER.P B General Public Utilities CPU Service Corp 84/0 EISENHUT.D G Division of Licensing ip 22774 146 24X Fiche 50-219,84/03/21.8403270165
- 8403280011 Forwards request for add1 info re spent fuel pool expansion Response requested within 15 days CRUTCHFIELD: D Operating Reactors Branch 5 84/03/26 FIEDLER, P B General Public Utilities GPU Service Corp 3pp 22777 079 24X Fiche 50-219,84/03/26,8403280011
- O Inspection reports, IE Bulletins & correspondence
- 8403130269 Forwards IE Insp Rept 50-219/83-26 on 831107-1231 & notice OSISOMOTO THE WORLD'S IN STREET AND ASSOCIATION OF VINIAL STREET AND ASSOCIATION OF Project & Resident Programs 84/02/27 FIEDLER, P B General Public Utilities - GPU Service Corp 2pp. 22605 181 24X Fiche 50-219,84/02/27,8403130269
- --8403130272 Notice of violation from insp on 831107-1231 * Region 1, Office of Director 84/02/27 1p 22605 183 24X Fishe 50-219,84/02/27,8403130269
- --8403130280 IE Insp Rept 50-219/83-26 on 831107-1231. Violation noted failure of Surveillance Procedure 645 6 012, "Fire Pump Functional Test" to incorporate Tech Spec change. CCMRILL. C. CONNER. E. L. Region i. Office of Director 84/02/15 11pp 22605 184 24X Fiche 50-219,84/02/27,8403130869
- 8401170072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Byo list Upprotes verve construction of Emergency Preparedness & Engineering JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp. 22709-237. 24X Fiche 50-000.84/02/28,8401170072
- 8403150012 Forwards IE Insp Rept 50-219/84-02 on 840116-20 No violations observed

 MARTIN T T Division of Engineering & Technical Programs. B4/03/01

 FIEDLER, P B General Public Utilities - GPU Service Corp 2pp

 22441 251 24X Fiche 50-219, 84/03/01,8403150012
- ~-B403150017 IE Insp Rept 50~219/84~02 on B40116~20 No violations identified Major areas inspected radiation protection program, including personnel selection, qualification & training & radiological control technician qualification DRAGDUN.T , BICEHOUSE.H , SHANBAKY.M Region 1, Office of Director B4/02/28 9pp 22641 253 24X Fichs 50~219,84/03/01,8403150012
- 8402090007 IR Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl GRACE, J N Division of GA: Bafeguards & Inspection Programs (Post B30103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000,84/03/02.8402090007
- 8402070008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Bya Valves to Operate " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 122pp 22553 078 24X Fiche 50-000,84/03/02,8402070008
- 8402070009 IE Info Notice 84-15. "Reporting of Radiological Releases " 102070009 16 anno haves - ... Byc list encl. JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 117pp 22353 217, 24X Fiche 50-000, 84/03/02, 8402090009.
- 8402070011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN, E. L. Division of Emergency Preparadness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co. of New York, Inc. 117pp 22553-336 24X Fiche 50-000,84/03/05,8402070011
- B403090070 Ack receipt of B40127 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-219/83-25.
 BELLAMY, R R. Division of Engineering & Technical Programs.
 B4/03/05 FIEDLER, P. B. General Public Utilities QPU Bervice Corp.
 10 22575 289 24% Fichs 50-219.84/03/05.8403090070

- --8403070073 Responds to NRC 831228 ltr re violations noted in IE Insp Rept 50-219/83-25 Corrective actions chemistry surveillance test program revised to ensure that chemistry surveillances listed & completed as scheduled FIEDLER,P B General Public Utilities - GPU Service Corp 84/01/27 MARTIN,T T Division of Engineering & Technical Programs 2pp 22575 290 24X Fiche 50-219,84/03/05,8403070070
- 8402090024 IE Info Notice 84-09, Rev 1. "Lessons Learned From Insps of Fire Protection Bafe Shutdown Sys " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Cansolideted Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000,84/03/07,8402090024
- 8402090028 IE Info Notice 84-18. "Stress Corrosion Cracking in PWR 89s " Bvc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584.186 24X Fiche 50-000,84/03/07,8402090028
- 8403160205 Ack receipt of 840224 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-219/83-27
 MARTIN,T.T Division of Engineering & Technical Programs 84/03/07
 FIEDLER.P 8 General Public Utilities OPU Service Corp 2pp
 22655 216 24X Fichs 50-219,84/03/07,8403160205
- --B40316020B Responds to NRC 840117 ltr re violations noted in IE Insp Rept 50-219/B3-27 Corrective actions supervisors instructed to verify drain plug integrity Temporary rev to Procedure 351 32 submitted for review FIEDLER, P B General Public Utilities - GPU Service Corp 84/02/24 MARTIN.T T Division of Engineering & Technical Programs 3pp 22655 218 24X Fiche 50-219,84/03/07,8403160203
- 8402070031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Bafety Sys." Svc list encl DEYGUNG.R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24% Fiche 50-000.84/03/12.8402090031
- 8403270099 Forwards IE Insp Rept 50-219/84-04 on 840207-10 No violations observed MARTIN.T T Division of Engineering & Technical Programs 84/03/13 FIEDLER.P B General Public Utilities OPU Service Corp 2pp 22806 350 24% Fiche 50-219.84/03/13.8403290099
- --8403290104 IE Insp Rept 50-219/84-04 on 840207-10 No violations identified Major areas inspected inservice insp program GRAY.E.H.: DURR.J.. Region 1. Office of Director. 84/03/07 4pp 22804 352 24X Fiche 50-219.84/03/13.8403290099
- 8403200056 Forwards Rev O to "Masonry Wall Failure Consequence Analysis" & "Oyster Creek Generating Station Containment Spray Bys Assessment re Postulated Collapse of Reactor Bldg Southeast Stairwall Masonry Walls," per IE Bulletin 80-11 FIEDLER,P.B General Public Utilities - GPU Service Corp 84/03/14 CRUTCHFIELD, D Operating Reactors Branch 5 1p 22687 001 24X Fiche 50-219,84/03/14,8403200056.
- --8403200062 Rev O to "Masonry Wall Failure Consequence Analysis"
 BALLARD, M F Impell Corp 02-0370-1132 ROQ 83/08/31 116p;
 22687 003 24X Fiche 50-219,84/03/14,8403200056
- ~-8403200067 Rev O to "Ouster Creek Nuclear Generating Station Containment Spray Sys Assessment re Postulated Collapse of Reactor Bidg Southeast Stairwell Masonry Walls " DE GRABSI.9 , MARANTER J Impsil Corp 02-0370-1137 ROO 83/10/31 49pp 22687 119 24X Fiche 50-219,84/03/14,8403200056
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 123pp. 22823, 229 24X Fiche 50-000, 84/03/21, 8402090043
- B402070044 IE Info Notice 84-20, "Svc Life of Relays in Bafety-Related Bys." Svc list ancl. JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 135pp. 22733 001 24X Fiche 50-000,84/03/21,8402070044
- 8403280005 Forwards evaluation rept re deferment of masonry well mods (IE Bulletin 80-11) Evaluation addresses only request for deferment of mods to certain walls, not ongoing staff review of IE Bulletin 80-11 responses
 CRUTCHFIELD.D. Operating Reactors Branch 5 84/03/27 FIEDLER.P B General Public Utilities OPU Service Corp 12pp 22777 159, 24: Fiche, 50-219, 84/03/27, 8403280005

- R Periodic operating reports & related correspondence
- 8403240074 "Semiannual Effluent Relmate Rept for June-Dec 1983 "
 W/840229 Itr
 PIEDLER.P B Qeneral Public Utilities GPU Bervice Corp 83/12/31
 170pp 22749 202 24X Fiche 50-219.83/12/31.8403240074
- 8403020128 Monthly operating rept for Jan 1984 W/840210 ltr BARAN,R , FIEDLER,P B General Public Utilities ~ GPU Service Corp 84/01/31 8pp 22442 088 24X Fiche 50-219, 84/01/31, 8403020128
- 8403010254 NPDEB noncompliance notification on 840123, discharge—intake temp difference of augment offgas—new radwaste sys cooling water exceeded permit limiting condition of 27 F Byc water pump & HX repaired FIEDLER.P B . DOUGLAB.M General Public Utilities GPU Service Corp 84/02/24 GABTON, J New Jersey, State of 5pp 22432 265 24X Fiche 50-219,84/02/24.8403010256
- --8403010261 "NPDES Discharge Monitoring Rept for Jan 1984 "
 FIEDLER,P B General Public Utilities GPU Service Corp
 84/01/31 5pp 22432 270 24X Fiche 50-219.84/02/24.8403010256
- 8403070203 Forwards summary rept of Woodborer Study Program from June 1975 through 1983, per 831108 agreement HEWARD, R W General Public Utilities - GPU Service Corp 84/02/28 LOMBARDD. J J NRC - No Detailed Affiliation Given 5pp 22538 35-24X Fiche 50-219,84/02/28,8403070203
- 8403160057 "NPDES Discharge Monitoring Rept.Feb 1784 " W/840309 ltr FIEDLER.P General Public Utilities - GPU Service Corp 84/02/29 0ASTON.J New Jersey, State of Bpp 22652:315 24X Ficha 30-219.84/02/27.8403160057
- B403230117 Forwards 1983 ecological studies rept for 1983 & results of fish kill monitoring program FIEDLER, P B General Public Utilities OPU Service Corp 84/02/29 MURLEY, T E Region 1. Office of Director. 1p 22/31 001 24X Fiche 50-219,84/02/29,8403230119
- --8403230122 "Winter Outage Fish Sampling Program Rept, Sept 1982 Aug 1983 "
 * General Public Utilities - GPU Service Corp 84/02/29 20pp 22731-002 24X Fiche 50-219, 84/02/29, 8403230119
- --8403230123 "Ecological Studies Progress Rept, Sept 1982 Aug 1983 "
 * Ecological Analysts, Inc 83/08/31 50pp 22731 022 24X
 Fichs 50-219, 84/02/29, 8403230119
- 8403300001 Monthly operating rept for Feb 1984 W/840313 ltr BARAN,R , FIEDLER,P B General Public Utilities - GPU Service Corp 84/02/29 8pp 22822 111 24X Fiche 50-219,84/02/29,8403300001
- 8403230110 Forwards "Study of Woodborer Populations Re Oyster Creek Generating Station 831021-840131," progress rept for 35th quarter FIEDLER,P B General Public Utilities - GPU Service Corp 84/03/16 MURLEY,T E Region 1, Office of Director 1p 22731 072 24X Fiche 50-217,84/03/16,8403230110
- --8403230112 "Study of Woodborer Populations Re Dyster Creek Generating Station,831021-840131," progress rept for 35th quarter HILLMAN,R E., BELHORE,C I Battelle Memorial Institute, Pacific Northwest Laboratories 84/01/31 24pp 22731 074 24X Fiche 50-219,84/03/16,8403230110
- S Reportable occurrences, LERs & related correspondence
- B305200133 Forwards Technical Review Rept AEQD/T312, "Failure of 5-kV Cable Terminations "Failure probably caused by nick in cable insulation CHIRAMAL.M Reactor Operations Analysis Branch B3/05/09 BEYFRIT.K V Reactor Operations Analysis Branch ip 22789 315 24X Fiche 50-219,83/05/09,8305200133.
- B4030102% NPDEB noncompliance notification temp difference of augment offgas-new radw water exceeded permit limiting condition r pump & HX repaired FIEDLER, P B . DOUGLAS M General Public Corp B4/02/24 GASTON, J New Jersey, 24X Fiche, 50-219, 84/02/24, 84030102%
- --8403010261 "NPDE8 Discharge M FIEDLER,P B General Publ: 84/01/31 %pp 22432 27C

- 403070236 Followup Part 21 rept re defective mechanical snubber capstan springs supplied by Pacific Scientific Affected utils listed Purchasers have been notified & advised to work directly w/Pacific Scientific in disposition HOVI.L NPS Industries. Inc 84/02/24 DEYGUNG, R C Director's 07°1cs, 0ffice of Inspection and Enforcement 2pp 22536-279 24X Fiche 50-000.84/02/24,8403070256
- 40313020B PNO-I-84-023 on 840305 worker repairing lights in turbine bidg sustained radioactive contamination on waist & head Incident investigated & critiqued Corrective actions being reviewed by specialist
 NIMITZR L SHANBAKY, M BELLAMY, R Region 1. Office of Director 64/03/07 1p 22605 056 24X Fiche 30-219, 64/03/07, 8403130208
- 403270008 PNG-1-84-027 on 840323, through-wall crack discovered on weld on condensate return line from south isolation condenser No repair or replacement plans formulated Facility currently shut down for refueling & mod TRIPP.L. KEINIG.R. Region i. Office of Director 84/03/23 ip 22803 282 24X Fiche 50-219,84/03/23.8403290008
- 3403300074 PNS-1-84-003 on 840324 male phoned Jersey Central Power & Light Customer Svc Ctr & notified that FFA will start demolishing plants Dyster Creek implemented emergency contingency plan & TMI increased security awareness MADDEN.W. JOYNER, J. Region 1. Office of Director 84/03/26 ip 22822 088 24X Fiche 50-000,84/03/26,8403300074

' Operator Examinations

- 140308023: Submits projected requests for site visits to conduct operator licensing grams through FV87.per 831221 request & Generic Ltr 83-40
 FIEDLER.P B General Public Utilities CPU Service Corp 84/03/01
 EISENHUT, D 0 Division of Licensing 2pp 22561-032. 24X
 Fiche 30-219.84/03/01,8403080231.
- i403270165 Informs that grovisions of Code Cases N-341 & N-356 re
 NDE personnel qualification will be adopted Time period
 for requalification increased to 5 yrs.
 FIEDLER,P B General Public Utilities OPU Service Corp. 84/03/21
 EISENBUT,D O Division of Licensing ip 22774 146 24X
 Fiche 50-219.84/03/21.8403270165
- DOCKET 50-220 NINE HILE POINT NUCLEAR STATION, UNIT 1
- 8403060036 Advises that NRC will not review emergency plans to delete privaty or proprietary info unless specifically requested by licensee.per Bio7079 Generic Ltr Bi-27 W/o request.entire plan will be placed in PDR VASSALLO.D B Operating Reactors Branch 2 B4/02/10 RHODE.G K Niagara Mohawk Power Corp. 2pp 22528 327 24X Fiche 50-220.84/02/10.8403060036
- 8403130496 Forwards comments on 830930 detailed control room design review program plan per Suppl 1 to NUREG-0737 Specific areas of plan not described in enough dotail to ensure that plan will meet requirements. In-progress audit suggested VASSALLO.D D Operating Reactors Branch 2 84/02/22 RHODE.G X Niagara Hohawk Power Corp 13pp 22619.348, 24X Fiche 50-220-84/02/22,6403130476
- B403130006 Forwards IE Insp Rept 50-220/83-30 on 831217-840131 No violations observed STAROBTECKI, R Division of Project & Resident Programs. 84/02/27 RHDDE, 0 K Niggara Mohauk Power Corp 2pp 22615 169 24X Fiche 50-220,84/02/27,8403130006
- --8403i3002i IE Insp Rept 50-220/83-30 on B3i2i9-840i3i No violations identified Hajor areas inspected licensee action on previous insp findings, operational safety verification, physical security, plant tours & surveillance testing HUDSON-8 B., COLLINS, S.J. Region S. Office of Director 84/02/22 12pp 22615 171 24X Fiche 50-220.84/02/27,8403i30006
- 8403060439 Forwards marked-up procedures generation package for implementing symptom-based emergency operating procedures, per Suppl 1 to NMREG-0737, for comment LEMFOCE. T E Niegara Mohawk Power Corp 84/03/01. VABBALLO, D B. Operating Reactors Branch 2 122pp 22508 143 24X
 - cted page rave to Issue 2. Rev O to security $\delta_{\rm c}$; lans, Pages withheld
 - awk Power Corp 84/03/01. MARTIN:T T t Technical Programs 1p 22575:354 24X 3090063.

- B403130386 Forwards response to B40112 request for add1 info re NUREQ-0737. Item II B 3, "Post-Accident Sampling Sys" Emergency Procedure EFP-7, "Determination of Core Damage Under Accident Conditions" also encl MANQAN, C V Niagara Mohawk Power Corp 84/03/08 VASSALLO.D B Operating Reactors Branch 2 15pp 22605 010 24X Fiche 50-220.84/03/08.8403130386
- --B403130391 Rev O to Emergency Procedure EPP-9, "Determination of Core Damage Under Accident Conditions" LEACH, E W. ROMAN, T W. Niagera Mohauk Power Corp. 84/03/31 27pp 22605 025 24x Fiche 50-R20.84/03/08,8403130386
- 8403190243 Notification of 840418 workshop in King of Prussia, PA to discuss lessons learned from recent App R fire protection safe shutdown insp & topics described in IE Info Notice 84-09 Agenda for workshop encil MURLEY, T E Region i. Office of Director 84/03/09 O'TOOLE, J D Consolidated Edison Co. of New York, Inc. KOBER, R W. Rochester Oas & Electric Corp. KEMPER, J S. Philadelphia Electric Co. 35pp 22672 062 24x Fiche 50-000, 84/03/09, 8403190243
- 840323011à Distusses calculated dose rates due to shine from reactor blog atmosphere to control room & security blog following design basis LDCA, per IE Insp Rept 50-220/83-15 Doses not expected to exceed 5 ram during first 8 h following DBA MANGAN, C V Niagara Mohawk Power Corp 84/03/19 VASSALLO, D B Operating Reactors Branch 2 2pp 22730 333 24X Fiche: 50-220, 84/03/19, 8403230116

1 Financial information

- 8403270177 Annual Financial Rept 1983 W/840322 1tr HAEHL,J G : DONLON:W J : LEMPOES:T E Niagara Mohawk Power Corp 83/12/31, 41pp 22800 319. 24X Fiche,50-220.83/12/31,8403270177
- J Insurance & indemnity information
- 8403280036 Forwards Endorsement 71 to MAELU Policy MF-46 RUBHMORE J W Niagara Mohawk Power Copp 84/03/22 8ALTZMAN, J Assistant Director for Btate & Licensee Relations 2pp 22777 02 24X Fiche 50-220, 84/03/22, 8403280036
- 8403280047 Forwards Endorsements 85 & 86 to NELIA Policy NF-161 RUBHMORE, J W Niagara Mohawk Power Corp 84/03/22 BALTZMAN, J Assistant Director for State & Licensee Relations 3pp 22776 359 24X Fiche 50-220, 84/03/22, 8403280047
- P. Operating license stage documents & correspondence
- 8403140340 Bummary of 831215 meeting w/GE & Mark I Owners Group in Bethesda.MD re Mark I containment wetwell-drywell vacuum bresker design methodology BIEGEL, B L Operating Reactors Branch 2 84/02/21 Operating Reactors Dranch 2 51pp 22635 198 24X Fiche: 50-000,84/02/21. 8403140340
- 8403040247 Forwards status plans & schedules per Generic Ltr B3-28, "Required Actions Based on Generic Implications of Salem ATMS Events" MANGAN, C V Niagara Mohawt Power Corp 84/02/29 VASSALLO, D B Operating Reactors Branch 2 App 22515 195 24X Fiche 50-220, 84/02/29, 8403040247.
- 8403090040 Remits fee for Tach Spec amend application dtd 840109, per 840126 request MANGAN, C V Niagara Mohawk Power Corp 84/02/29 DIGGS, R M License Fee Management Branch 2pp 22576 005 24X Fiche 50-220, 84/02/29, 8403090040
- 840306022; Forwards supplemental clarifying info re spent fuel pool mod, based on review of encls to NRC 84020; ltr providing Amend 54 to License DPR-63 Dose tracking sys will be implemented to maintain control of worker exposures MANGAN, C V Niagera Mohawk Power Corp 84/03/01 VASSALLO, D. B Operating Reactors Branch 2 5pp 22515 172. 24X Fichs, 50-220, 84/03/01, 8403060221
- 8403060446 Advises that offsite dose calculation manual will be submitted by 840307 MANGAN, C V Niagara Mohawk Power Corp 84/03/01 VASBALLO, D, B Operating Reactors Branch 2, 1p 22518, 130 24X Fichs, 50-220, 84/03/01,8403060446.
- 8403120224 Notification of 840315 meeting w/util in Bethesda MD to discuss environ qualification of equipment HERMANN.R A. Operating Reactors Branch 2 84/03/03 VASALLO,D 8. Operating Reactors Branch 2 19 22615.360 24X Fiche 50-220,84/03/03.8403120224.

- 8403090146 Withdraws 770116 & 0715 applications for amend to License DPR-63 Revised Tech Specs re diesel instrument satpoint logic & relief valves will be submitted by 840401 MANGAN.C V Niagara Mohawk Power Corp 84/03/05 VASSALLO, D 8 Operating Reactors Branch 2 1p 22375 048 24X Fiche 50-220,84/03/05,8403090146
- B403120059 Forwards results of safety evaluation of NUREG-0737, Item II K 3 18 concluding that eliminating high drywell pressure permissive could increase severity of loss of feedwater transient by actuating automatic depressurization sys MANGAN, C V Niagara Mohawk Power Corp 84/03/06 VASBALLO, D B Operating Reactors Breach 2 Spp 22586 285 24X Fiche 50-220,84/03/06,8403120059
- B403070240 Summary of B40216 meeting w/Northeast Nuclear Energy Co.
 Boston Edison Co.Vermont Yankoe Nuclear Power Co & Teledyne
 Engineering Svcs in Waltham.MA re add1 Mark I torus
 structural analysis List of attendees encl
 SMEA:JJ Operating Reactors Branch 5 BIEGEL.B Operating
 Reactors Branch 2 84/03/07 CRUTCHFIELD.D Operating Reactors
 Branch 5 4pp 22572 298 24X Fiche 50-000.84/03/07.8403090240
- 8403130340 Forwards offsite dose calculation manual, per proposed radiological effluent Tech Spec dtd 840201 Response to Franklin Research Ctr comments re 830301 offsite dose calculation manual also encl
 LEMPGES: T E Niagara Mohawk Power Corp 84/03/07 VASBALLO, D B Operating Reactors Branch 2 6pp 22607, 154 24x
 Ficher 50-220, 84/03/07, 8403130340
- --8403130347 "Dffsite Dose Calculation Manual "
 # Niagara Mohawk Power Corp 84/03/01 83pp 22607 160 24X Fiche. 50-220,84/03/07,8403130340.
- 8403130386 Forwards response to 840112 request for add1 info re NUREQ-0737, Item II B 3, "Post-Accident Sampling Bys" Emergency Procedure EPP-7, "Determination of Core Damage Under Accident Conditions" also encl MANQAN, C V Niagara Mohawk Power Corp 84/03/08 VASBALLO, D B Operating Reactors Branch 2 15pp. 22605 010 24X Fiche 80-220, 84/03/08,8403130386
- --8403130391 Rev O to Emergency Procedure EPP-9, "Determination of Core Damage Under Accident Conditions" LEACH, E W, ROMAN, T W Niagara Mohawk Power Corp 84/03/31 27pp 22605 025 24X Fiche 50-220,84/03/08.8403130386
- 8403130275 Generic Ltr 84-07 to all licensees of BWRs re procedural guidance for pips replacement at BWRs. 8vc list encl EIBENHUT, D O Division of Licensing 84/03/14 Commonwealth Edison Co 20pp 22823 334. 24% Fichs 50-000.84/03/14,8403150275
- 8403200002 Forwards list of items under review needed to support refueling outage & items not yet submitted by util MANGAN.C V Niagara Mohawk Power Corp 84/03/15 VASBALLO,D B Operating Reactors Branch 2 2pp 22683 361 24X Fiche 50-220,84/03/15,8403200002.
- 8403220129 Forwards Rev 1 to control room habitability summary rept, per 840131 ltr & TMI Action Plan Item III D 3 4 Main steam line break source term revised to correspond to Tech Spec concentration limit of 25 uCi total iodine per g of water LEMPOES: T E. Niagara Mohawk Power Corp 84/03/19 VABSALLO.D.B Operating Reactors Branch 2 App 22716 001 24X Ficha.50-220.84/03/19.8403220127.
- 8403220177 Responds to NRC request to explain operator action given draft emergency condenser Tech Spec change Operators will take into account plant condition & other indications, besides high radiation signal, before manually isolating sys. MANGAN, C V. Niagara Mohawk Power Corp. 84/03/19 VASSALLD, D. B. Operating Reactors Branch 2 2pp 22717.022 24X Fiche 50-220,84/03/19,8403220177
- 8403300241 Requests remittance of fee for review of 840113 proposed Tach Bpec changes re installation of protective relaying on outside of reactor protection & reactor trip bus motor generator set.

 DIGOS,R M License Fee Management Branch 84/03/19 RHODE,C K Niagara Mohawk Power Corp 1p. 22840 361 24X Fiche: 50-220,84/03/19,8403300241
- 8403230078 Provides add1 info re Type C testing of emergency cooling & reactor claenup inboard isolation valves & method for extrapolation of leakage test results from reduced pressure to accident pressure.per 831101 Tech Spec amend application MANGAN.C V Niagara Mohawk Power Corp 84/03/20 VASSALLO.D B Operating Reactors Branch 2 2pp 22726 333, 2qx Fiche 50-220,84/03/20,8403230078

- 8403270176 Advises that final status rept re equipment qualification program to be supplied to Commission by 840601.per 830520 aubmittal ANNOAN.C V Niagara Mohawk Power Corp 84/03/20 VASSALLO, D B Operating Reactors Branch 2 ip 22771 [32 24X Fiche 50-220,84/03/20,8403270176
- 8403300058 Forwards proposed mod to existing logic for automatic initiation of diesel generators upon loss of voltage & degraded voltage Proposed mod involves physical changes to undervoltage relaying circuits for Fowerboards 102 & 103 MANGAN.C V Niagara Mohawk Power Corp 84/03/27 VASSALLO.D D Operating Reactors Branch 2 9pc 22821 103 24X Fiche 50-220,84/03/27,8403300058
- G Inspection reports: IE Bulletins & correspondence
- B403130006 Forwards 1E Insp Rept 50-220/83-30 on B31219-840131 No violations observed STAROBTECK1.R Division of Project & Resident Programs 84/02/27 RHODE.0 K Niagara Mohauk Power Corp 2pp 22615,169 24X Fiche 50-220.84/02/27,8403130006
- --8403130021 IE Insp Rept 50-220/83-30 on 831219-840131 No violations identified Major areas inspected licensee action on previous insp findings, operational safety verification physical security, plant tours & surveillance testing HUBBON.8 D . COLLINS.8 J Region i. Office of Director 84/02/22 12pp 22615 171 24X Fichs 50-220.84/02/27.8403130006
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22707 237 24X Fiche 50-000,84/02/28,8401190072
- 8403260270 Responds to IE Bulletím 63-08 Westinghouse Type DB or DS breakers & GE Type AK-2 breakers, w/undervoltage trip attachments, not in use at facility LEMPGES, TE Niagara Mohawk Power Corp 84/03/01 DEYGUNG, R C Director's Office, Dffice of Inspection and Enforcement ip 22754 282 24X Fiche 50-220,84/03/01.8403260270
- B402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl QRACE.J N Division of QA. Sařeguards & Inspection Programs (Post B30103) B4/03/02 Consolidated Edison Co. of New York, Inc 130pp 22552 329 24X Fiche 80-000.B4/03/02.B402090007
- 8402090008 IE Info Notice 84-14. "Failure of Automatic Sprinkler Bys Valves to Operate " Svc list enci JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 078 24X Fiche 50-000.84/03/02.8402070008
- 8402090007 IE Info Notice 84-15, "Reporting of Radiological Releases"
 Svc list and
 JORDAN,E L Division of Emergency Preparadness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc. 117pp. 22553 217 24X Fichs 50~000,84/03/02,8402070007
- B402090011 IE Info Notice B4-17, "Problems W/Liquid Nitrogen Coaling Components Below Nil Ductility Temp " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000.84/03/05,8402090011
- 8402090024 IE Info Notice 84-09.Rev i, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York Inc 1189p 22635 049 24X Fichs 50-000.84/03/07.8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Sys " 8vc list enc! JDRDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07. Consolidated Edison Co. of New York: Inc. 118pp 22584 186 24X Fiche 30-000.84/03/07.8402090028
- B403120044 Forwards revised inservice insp program Program will incorporate portions of 1980 edition through Winter 1981 addends of Section XI of ABME Boiler & Pressure Vessel Code Personnel qualification per proposed Tech Specs smcl LEMPQES, T E Niagara Mohawk Power Corp. B4/03/07 VASBALLO, D B Operating Reactors Branch 2 1p 22590 289. 24X Fiche 50-220, 84/03/07, 8403120044
- --B403120050 Revised "Inservice Insp Program" ** Niagara Mohawk Power Corp 84/09/31 4pp 22590 270 24X Fiche 50-220,84/03/07,8403120044.

2070031 IE Bulletin 84-02. "Failures of GE Type HFA Relays in Use in lass IE Safety Sys " Svc list encl EYDUNG.R C Director's Office. Office of Inspection and nforcement 84/03/12 Consolidated Edison Co. of New York, Inc 34pp 22823 074 24x Fiche 50-000.84/03/12.8402090031

3300295 Requests remittance of fee for final review of 800502 ubmittal & 820730 rev re inservice insp program & requested alief from ASME Code insp requirements (IGGS, R M License Fee Management Branch 84/03/15 RHODE, 6 Kiagara Mohauk Power Corp ip 22844 318 24X iche 50-220,84/03/15,8403300295

G230116 Discusses calculated dose rates due to shine from reactor ldg atmosphere to control room & security bldg following esign basis LOCA,per IE Insp Rept 50-220/83-15 Doses not xpected to exceed 5 rem during first 8 h following DBA IANGAN.C V Niagara Mohawk Power Corp 84/03/19 VASSALLG,D B perating Reactors Branch 2 2pp 22730 333 24X iche 50-220,84/03/19,8403230114

2090043 IE info Notice 84-19, "Two Events Involving Unauthorized ntries into PWR Reactor Cavities " Svc list encl IDRDAN, E L Division of Emergency Preparedness & Engineering esponse (Post 830103), 84/03/21 Consolidated Edison Co of New ork, Inc. 123pp. 22823 229 24X Fiche 50-000-84/03/21,8402090043

2090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related ys " Svc list and ORDAN, & L. Division of Emergency Preparedness & Engineering esponse (Post 830103) 84/03/21. Consolidated Edison Co. of New ork, Inc. 135pp. 22733 001, 24X Fichs 50-000,84/03/21,8402090044

3300151 Responds to IE Bulletin 83-07 re felsification of matle ertifications by Ray Miller. Inc Util received no matls righnating from Ray Miller. Inc through any intermediaries isted in IE Bulletin 83-07. Suppl 1.

EMPOSS.TE Niagara Mohawk Power Corp 84/03/23 MURLEY. TE agion 1. Office of Director 2pp 22820 030. 24X iche 50-220.84/03/23.8403300151

Periodic operating reports & related correspondence

3070194 "Radioactive Effluent Release Semiannual Rept, Jul-Dec 983 " H/840301 ltr EMPOEB,T E Niagara Mohauk Power Corp 83/12/31 MURLEY,T E agion 1. Dffice of Director 52pp 22538 162 24X iche 50-220.83/12/31.8403070194

3150051 Monthly operating rept for Feb 1984 W/840310 ltr. CMAN, T W , LEMPGES, T E Niagara Mohawk Power Corp 84/02/29 5pp 22641.350 24X Fiche 50-220,84/02/29,8403150051

Reportable occurrences. LERs & related correspondence

3210043 Nonroutine radiological environ operating rept on 840217, horeline sediment samples collected in Nov 1983 indicated oncentrations of Cs-137 & Br-90 exceeding control sample sines Caused by effluent discharges W/840313 ltr EMPGES.T E Niagara Mohawk Power Corp 84/02/17 MURLEY.T E egion 1. Office of Director. 3pp 22707.039 24X 1che 50-220.84/02/17.8403210043

3140122 Part 21 rept re status update concerning abnormal wear on inear converters Test program underway Results of nestigation indicate excessive wear caused by hunting of ontrol circuitry (DBSON, J P Pacific Air Products Co 84/03/07 Director's effice, Office of Inspection and Enforcement 7pp 22624.068 247 iche 50-000,84/03/09,8403140122

3190135 PNS-I-84-002 on 840312, bomb threat received from nidentified caller Site emergency & safeguards contingency lan requirements implemented Public areas & site protected rea searched w/negative findings ADDEN, B , JOYNER, J Region 1, Office of Director 84/03/12 ip 2674-352 24% Fiche 50-220,84/03/12,8403190135.

3220075 EN-84-015 on B40320, notice of violation & proposed mposition of civil penalties in amount of \$180,000 will be ssued to licensee Action based on failure to maintain ontainment integrity & failure to conduct surveillance RAIQ.J. AXELRAD.J. Director's Office, Office of Inspection and nforcement 84/03/15 2pp 22712/308, 24X Fiche 50-220,84/03/15,403220075

DDCKET 50-223 UNIV. OF LOWELL RESEARCH REACTOR

- G Inspection reports, IE Bulletins & correspondence
- B403300165 Act receipt of B40307 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-223/83-02.
 STAROSTECKIR Division of Project & Resident Programs. 84/03/26
 BEGH1AN,L E Lowell. Univ of Lowell, MA ip 22820 050 24X
 Fiche: 50-223,84/03/26.8403300165
- --8403300169 Responds to NRC 840209 ltr re violations noted in IE Insp.
 Rept 50-223/83-02 Corrective actions automatic notification
 issued to committee members & tickler sys installed to
 measure control & regulating valve intervals
 BECHIAN, L. Lowell, Univ. of, Lowell, MA. 84/03/07
 BTAROSTECKI, R. Division of Project & Resident Programs 2pp
 22820 051 24X Fiche 50-223,84/03/26,8403300165

DOCKET 30-224 UNIV OF CALIFORNIA RESEARCH REACTOR

- R Pariodic operating reports & related correspondence
- B403150115 "Berkeley Research Reactor Annual Rept of Operations, 1983 "
 W/840309 ltr
 LIM.T H California, Univ. of, Berkeley, CA 83/12/31, MILLER, J A
 Standardization & Special Projects Branch 11pp 22640 048, 24X
 Fiche, 50-224,83/12/31,8403150115

DOCKET 50-225 RPI CRITICAL EXPERIMENT

- F Security, medical, emergency & fire protection plans
- 8403060204 Proposed emergency plan for License CX-22 W/840206 itr HICKS.F., HARRIS.D. Rensselaer Polytechnic Institute, Troy, NY 84/02/27 THOMAS.C O Standardization & Special Projects Branch 22pp 22517 154 24X Ficher 30-225:84/02/29.8403060204.
- R Periodic operating reports & related correspondence
- 8403200229 "Annual Rept of Tests & Experiments, Mar 1982 Feb 1983" WICKS: F. HARRIS, D.R. Rensselser Polytechnic Institute: Troy. NY 83/02/28 2pp 22690 164. 24X Fiche 50-225.83/02/28,8403200229
- 8403260156 "Annual Operating Rept, Mar 1783 Mar 1784 " WICKS.F. HARRIS,D R Rensselaer Polytechnic Institute, Troy, NY 84/03/01 Region 1, Office of Director, 4pp 22750 339 24X Fithe 50-228.84/03/01.8403260156

DOCKET 50-237 DRESDEN NUCLEAR POWER STATION, UNIT 2

- F Security, medical, emergency & fire protection plans
- 8403050004 Forwards FEMA 840206 ltr & final exercise evaluations on 830914 offsite emergency preparedness exercise. Recommendations from rept do not affect approval of plan PAPERIELLO.C J Region 3, Office of Director 84702/29 REED.C Commonwealth Edison Co 2pp 22490 240 24X Fiche, 50-237, 84/02/29, 84030500004
- 8403120053 Advises of 840323 regional workshop in Rosemont, IL w/all Region III licensees to discuss fire protection safe shutdown requirements of 10CFR50. App R Agenda encl, SPESSARD, R L. Division of Emergency Preparedness & Operational Support 84/03/06 REED.C Commonwealth Edison Co 3pp. 22585 222 24X Fiche 50-010,84/03/06,8403120053.
- 8403150092 Forwards results of in-progress audit of detailed control room design review Util pursuing course of review which NRC believes will satisfy requirements of Suppl 1 to NUREO-0737. CRUTCHFIELD, D. Operating Reactors Branch 5 84/03/14 FARRAR, D. C. Communication Communicati
- Q Adjudicatory correspondence
- 8402220157 Order extending time until 840228 for Commission to act to review Director's Decision DD-83-14 CHILK: 8 J Office of the Secretary of the Commission 84/02/21. Commissioners ip. 22337.362, 24X Fiche 80-000.84/02/21. 8402220157

- 8403010238 Order extending time until 840305 for Commission to act to review Director's Decision DD-83-14 & 831027 decision denying request of Environ Policy Inst CHILK, 8 J Dffice of the Sucretary of the Commission 84/02/28 Commissioners ip 22434 210 24X Fiche 50-000,84/02/28,
- 8403090069 Informs that Commission unanimously declined to review Director's Decision OD-83-14 Time provided by NRC regulations within which Commission may act to review expired Decision became final agency action on 840305 CHILK.S J Opfice of the Secretary of the Commission B4/03/08 CELEBREZZE, A J Ohio, State of 2pp 22575 350 24X Fiche 50-000.84/03/08.8403090069
- 8403090074 Informs that Commission unanimously declined to review Director's Decision DD-83-14 Time provided by NRC regulations within which Commission may act to review expired Decision became final agency action on 840305 CHILK: 8 J Office of the Secretary of the Commission 84/03/08 MILLAR; F. Environmental Policy Institute 1p 22575 272 24X Fiche 50-000,84/03/08,8403090074
- 8403090113 Informs of Commission decision not to review Director's Decision DD-83-14 Time for Commission to act expired on 840305 W/a encl
 CHILK, B. J. Office of the Becretary of the Commission 84/03/08 RESNIKOFF, M. Sierra Club ip 22576 079 24X
 Fiche 50-000, 84/03/08, 8403090113
- P Operating license stage documents & correspondence
- 8403090185 Resubmits response to SEP Topic VII-1 A. "Isolation of Reactor Protection Sys from Nonsafety Sys.Including Qualification of Isolation Devices" Page 2 omitted from original response RYSAK.B Commonwealth Edison Co 84/02/15 CHERY.D Division o Licensing ip 22568 319 24X Fiche 50-237.84/02/15.8403090185
- --8403070191 Responds to SEP Topic VII-1 A. "Isolation of Reactor Protection 8ys from Nonsafety Sys. Including Qualification of Isolation Devices " APRM inputs will have Class IE isolators rated at i meg-ohm w/separate power supplies RYBAK, B Commonwealth Edison Co 1378A 83/08/03 GILBERT, R Operating Reactors Branch 5 4pp 22548 320 24X Fiche 50-237,84/02/15,8403090185
- --8403090194 Forwards info re SEP Topic VII-1 A, "Isolation of Reactor Frotection Sys from Nonsafety Sys. Including Qualification of Isolation Devices," in response to 801022 request JANEGEK, R F Commonwealth Edison Co 81/01/21 LAINAS, G C Assistant Director for Safety Assessment. 22pp 22548, 324 24X Fiche 50-237, 84/02/15, 8403090185
- 8403020037 Notification of contract execution "Dresden & Perry Bimulator Leasing." Awarded to GE JESBUP.B Technical Assistance Contracts Branch FIN B-8713 84/02/17 HAVINS, O.H. Director's Office, Office of Inspection and Enforcement 1p. 22491 045 24X Fichs 50-000.84/02/17,8403020037
- --B403020043 Contract "Dresden & Perry Simulator Leasing." awarded to QE PIERCE,R L. General Electric Co MORTON,K V Division of Contracts FIN B-B713 B4/02/17 S8pp 22491 046 24X Fiche 50-000,84/02/17,8403020037
- 8403140340 Summary of 831215 meeting w/QE & Mark I Duners Group in Batheeda, MD re Mark I containment watwell-drywell vacuum breaker design methodology, SIEOEL, B L Operating Reactors Branch 2 84/02/21 Operating Reactors Branch 2, 51pp. 22635 198 24X Fiche 50-000,84/02/21, 8403140340
- B403050119 Forwards supplemental response to Generic Ltr 83-28, "Required Actions Based on Generic Implications of Balem ATHS Events"

 BARNES, FL Commonwealth Edison Co B4/02/29 DENTON, H R Office of Nuclear Reactor Regulation, Director 24pp 22486 084 24X Fiche: 50-000, 84/02/29, 8403050119.
- 8403130070 Forwards proposed resolution of environ qualification 8ER & Franklin Research Ctr technical evaluation rept open item deficiencies Final BER should be issued to indicate resolution of program deficiencies, RYBAK, B Commonwealth Edison Co 84/02/29, DENTON, H R. Office of Nuclear Reactor Regulation, Director. 44pp 22402'123 24X Fiche. 50-237, 84/02/29, 8403130070

- 8403130400 Forwards 840210 responses to Generic Ltr 83-35 clarifying TMI Itam II K 3 31 Util concurs w/NRC position Itam should be closed RYBAK.B Commonwealth Edison Co 84/03/02 EISENHUT, D 9 Division of Licensing 2pp 22613 143 24X Fiche 50-000,84/03/02, 84/03130400
- 8403130410 Application for amend to Licenses DPR-19 & DPR-25, revising Tech Spec Table 3 7 i to require min addition of four LPCI & two torus spray suction valves RYBAK, B Commonwealth Edison Co 84/03/05 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22616 051 24X Fiche 50-237,84/03/05,8403130410
- ---8403130418 Proposed changes to Tech Spec Table 3 7 1 to require min addition of four LPCI & two torus spray suction valves * Commonwealth Edison Co 84/03/05 10pp 22616 053 24X Fiche 30-237,84/03/05,8403130410
- 8403150040 Forwards request for additinfo to support conclusions recurrent design codes & criteria & load combinations in 820802 ltr per integrated plant safety assessment rept (NUREG-0823)
 CRUTCHFIELD.D Operating Reactors Branch 5 84/03/09 FARRAR.D L Commonwealth Edison Co 8pp 22643 084 24X Fiche 50-237.84/03/09.8403180040
- --8403130045 "Review of Licenses Response to Design Codes. Design Criteria & Loading Combinations. Dreaden Nuclear Power Station Unit 2." draft supplemental technical evaluation rept STILWELL, T C . DARWISH, M . WALLO, E W Franklin Institute/Franklin Research Center NRC-03-Bi-130 TER-C5506-425 83/11/15 PERBINKO, D NRC NO Betailed Affiliation Given 36pp 22443 092 24X Fiche 50-237.84/03/09.8403150040
- B403150275 Generic Ltr B4-07 to all licensees of BWRs re procedural guidance for pipe replacement at BWRs Svc list encl EISENHUT.D.G Division of Licensing 84/03/14 Commonwealth Edison Co 20pp 22823 354 24X Fiche 50-000.84/03/14.8403150275
- 8403220133 Application to amend Licenses DPR-17 & DPR-25, revising Tech Specs to update snubber tables to reflect additions, deletions & other changes RYBAK, B Commonwealth Edison Co 84/03/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 82715 338 24X Fiche 50-237,84/03/15,8403220153
- --B403220158 Proposed Tech Specs updating snubber tables to reflect additions.deletions & other changes * Commonwealth Edison Co B4/03/15 20pp 22715 341 24X Fiche.50-237.84/03/15.8403220153
- B403270130 Application for amend to License DPR-25, changing Tech Spect to extend certain MAPLHQR curves to 40,000 MWd/ST.
 RYBAK.8 Commonwealth Edison Co B4/03/19 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 22774 129 24X
 Fiche 50-000,84/03/19,8403270130
- ---B403270136 Errate & Addenda Bheet 9, replacing Page 4-14 to "LOCA Analysis Rept for Dresden Units 2 & 3 & Quad Cities 1 & 2 Nuclear Power Stations"

 ** General Electric Co NEOD-24146A ERR 09 83/01/31 2pp 22774 135 24X Fiche, 50-000, 84/03/19, 8403270130
- B403220047 Forwards corrected Page 45 to Amends 81 & 73 to Licenses DPR-19 & DPR-25, respectively, which failed to include Footnote it re verification of time delay setting between 3 & 9 s
 CRUTCHFIELD, D Operating Reactors Branch 5 84/03/20 FARRAR, D L Commonwealth Edison Co 4pp 22712 197 24X Fiche 50-237, 84/03/20
- G Inspection reports, IE Bulletins & correspondence
- 8403120134 Forwards IE Insp Repts 50-237/84-01, 50-249/84-01, 50-254/84-01, 50-254/84-01, 50-255/84-01, 50-257/84-01 & 50-304/84-01 on 840203-14 No noncompliance identified SHAFER, W D Region 3, Office of Director 84/02/23 REED, C, Commonwealth Edison Co 2pp 22590 090 24X Fichs 50-000, 84/02/23, 8403120134
- --8403120137 IE Insp Repts 50-237/84-01.50-249/84-01.50-254/84-01. 50-265/84-01.50-295/84-01 & 50-304/84-01 on 840203-14 No noncompliance or deviations identified Major areas inspected allegations of improper operation CHRISGOTINDS, N. TONOUE, T. HOLZMER, M. Region 3, Office of Director 84/02/21 4pp 22590 092 24X Fichs 50-000,84/02/23, 8403120134

- 8403050043 Forwards Rev O to Corporate Regulatory Performance Improvement Plan "Plan designed to heighten employee awareness & strengthen corporate ability to improve regulatory performance THOMAS.8 Commonwealth Edison Co 84/02/24 KEPPLER.J G Region 3. Office of Director 3pp 22490 139 24X Fiche 50-000,84/02/24.8403050043
- $\sim\!-8403050046$ Rev O to "Corporate Regulatory Performance Improvement Plan "
 - * Commonwealth Edison Co 84/02/29 22pp 22490 142 24X Fiche 50-000,84/02/24,8403050043
- 8403120070 Forwards IE Insp Rept 50-237/84-02 on 840110-26 & notice of violation
 NORELIUS.C E Division of Project & Resident Programs 84/02/24
 REED.C Commonwealth Edison Co 2pp 22591 133 24X
 Fiche 50-237.84/02/24.8403120070
- --8403120073 Notice of violation from insp on 840110-26 NORELIUS. C E Division of Project & Resident Programs 22p 22571 135 24x Fiche 50-237. 84/02/24, 8403120070
- --8403120079 IE Insp Rept 50-237/84-02 on 840110-26 Noncompliance noted failure to follow control rod sequence procedure & out-of-svc procedure, resulting in skipping 20 steps TONGUE, T M. STASEK, S. WALKER, R D. Region 3, Office of Director 84/02/22 Bpp 22591 137 24X Fiche 50-237,84/02/24,8403120070
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list
 - JORDAN. & L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22909 239 24X Fiche 50-000,84/02/28,8401190072
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE, J N Division of GA, 9afeguards & Inspection Programs (Post 630103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 327 24X Fiche 50-000.84/03/02,8402090007
- 8402090000 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases" Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 119pp 22553 217 24X Fiche 50-000.84/03/02, 8402090009
- 8402090011 iE Infa Natice 84-17. "Problems W/Liquid Nitragen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN. EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 334 24% Fiche 50-000.84/03/05,8402090011
- B402090024 IE Info Notice 84-09.Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22633 049 24X Fiche 50-000,84/03/07,8402090024
- 840209002B IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Bys " Svc list encl JORDAN,E t. Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22584 186 24X Fiche 30-000.84/03/07, 8402090028
- 8402070031 IE Bulletin 84-02, "Failures of GE Type HFA Roleys in Use in Class IE Safety Sys "Svc list encl DEYQUNG, R C Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 074 24X Fiche 50-000,84/03/12,8402070031
- 8403230088 Ack receipt of regulatory performance improvement glan Periodic meetings requested to discuss progress on program & provide feedback KEPPLER.J G Region J. Office of Director 84/03/20 THOMAS.B Commonwealth Edison Co ip 2273D 161 24X Fiche.50-000,84/03/20. 8403230088
- --B403230107 Forwards corporate regulatory performance improvement plan THOMAS.B Commonwealth Edison Co B4/02/24 KEPPLER.J O Region 3, Office of Director. 3pp 22730 162. 24% Fiche 50-000, B4/03/20.840323008B

18

- --840323012A Rev O to "Corporate Regulatory Performance Improvement Plan For Dresden, Quad Cities 21on & LaBalle Operating Nuclear Stations & Byron & Braidwood Project Operating Organizations " * Commonwealth Edison Co 84/02/29 22pp 22730 165 24X Fiche 50-000,84/03/20.840923008B
- 8403260196 Forwards responses to IE Bulietin 83-07. "Apparently Fraudulent Products Sold by Ray Miller. Inc " Guad Cities supplied w/piping matls from Ray Miller. Inc during const Evaluation encl Concerns of IE Bulletin 83-06 satisfied BARNES.P L. Commonwealth Edison Co. 84/03/20 KEPPLER.J Q. Region 3, Office of Director 19pp 22756 185 24X Fiche 50-000,84/03/20,84/03/20.
- 8402090043 IE Info Notice 84~19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 630103) 84/03/21 Consolidated Edison Co of New
 York, Inc 123pp 22823 229 244 Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84~20, "Svc Life of Relays in Safety-Related Sys " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Fost 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 135pp. 22923 001 24X Fiche 50-000,84/03/21,8402090044
- 8403270114 EN-83-076A on 840323, order imposing civil monetary penalties in amount of \$50,000 Action based on failure to classify torus-to-drywell vacuum breaker actuation arm shaft seals under App B Mitigation of 831115 penalty unwarranted MLINGLER.0 , AXELRAD.J Director's Office. Office of Inspection and Enforcement 84/03/23 ip 22774 051 24X Ficha 50-237.84/03/23, 8403270114.
- R Periodic operating reports & related correspondence
- 8403060099 "Rept of Radioactive Effluents, Jul-Dec 1983 " W/840215 ltr SCOTT.D J Commonwealth Edison Co 83/12/31 KEPPLER, J G Region 3, Office of Director 17pp 22506 245 24X Fichs 50~010, 83/12/31, 8403060099
- B4030B0197 "Rept of Occupational Personnel Radiation Doses,1983" W/B40227 ltr W/B40227 ltr SCOTT,U S Commonwealth Edison Co 83/12/31 CASE,E G Office of Nuclear Reactor Regulation, Director 13pp 22559 099 24X Fichs 50-000,83/12/31.8403080197.
- 8403220120 Annual whole body external exposures for 1983 W/840316 ltr RYBAK.B. Commonwealth Edison Co 83/12/31 7pp 22716 007 24X Fiche 50-000,83/12/31,8403220120
- B403130015 Munthly operating repts for Feb 1984 W/840301 ltr SCHRUEDER, B A , SCDTT, D J Commonwealth Edison Co 84/02/29 17pp 22614 344 24% Fiche 50-237,84/02/29,8403130015
- S Reportable occurrences. LERs & related correspondence
- 8403270089 Supplemental LER B3-080/03X-1 on B31124, offgas log rad monitor 2-1705-A delivered offgas high elarm & high alarm spited & drifted downscale Caused by burned out resistor Power supply installed & monitor calibr. WP40307 ltr WOJTULEWICZ, T., SCOTT, D. J. Commonwealth Edison Co. B3/12/20 KEPPLERJ G. Region 3. Offsice of Director 3pp. 22766 252, 24x Fiche 50-237,83/12/20,8403270089.
- 8403230096 Updated LER 83-012/01x-1 on 630210, while conducting routine mechanical snubber test main steam line mechanical snubbers 44,46,50,51 & 53 found inoperable Thorough investigation revealed no cause Enubbers replaced W/840302 ltr SCHROEDER, I MIROCHNA, R , SCOTT, D J Commonwealth Edison Co 84/03/02, KEPPLER, J G. Region 3, Office of Director 6pp. 22730 125 24X Fiche.50-237,84/03/02,8403230096
- 8403270056 Updated LER 83-084/03X-1 on B31230, during normal operation, primary containment oxygen sample from torus alarmed on low level sample flow Caused by sample line moisture Line drained & leads reconnected W/840314 tr BERGAN, G W , SCOTT. D. J Commonwealth Edison Co 84/03/14, KEPPLER, J Q Region 3, Office of Director 3pp. 22766:136 24X Fiche 50-237,04/03/14,8403270056
- 8403240240 LER 84-003-00 on 840221, core apray valve M02-1402-23A failed to operate from control room Caused by cracked bearing race & gear housing Work requests written to modify existing circuitry W/840319 ltr COYLE, L. SCOTT, D. J. Commonwealth Edison Co. 84/03/19 4pp 22754 359. 24X Fiche 50-237,84/03/19,8403240240

8403260223 LER 84-004-00 on 840222, during Core Spray Valve Operability Test DOS 1400-2, core spray suction valve MO-2-1402-3A failed to close from control room Caused by faulty auxiliary breaker contact Contacts replaced W/840320 ltr COYLE.L . 860TT, D J Commonwealth Edison Co 84/03/20 4pp 22756 086 24X Fiche 50-237,84/03/20,8403260223

DOCKET 50-238 NUCLEAR SHIP BAVANNAH

- R Periodic operating reports & related correspondence
- 8403050111 Forwards "Semiannual Survey Rept TLD Monitoring Rept, Direct Radiation Survey & Containment Survey Results & Environ Bample Analysis Rept.820916-831031"

 QUERRY, J E Commerce, Dept of, Maritime Administration NRC No Detailed Affiliation Given 2pp 22487 271

 Fiche 50-238,84/02/29,8403050111
- --8403050113 "Bemiennuel Burvey Rept TLD Monitoring Rept Direct Radiation Burvey & Containment Survey Results & Environ Sample Analysis Rept 820916-831031 " * Bouth Carolina, State of 83/10/31 27pp 22487 273 24X Fiche 50-238,84/02/29,8403050111

DOCKET 50-244 ROBERT EMMET GINNA NUCLEAR PLANT, UNIT 1

F Security, medical, emergency & fire protection plans

- 8403060270 Summary of 840222 meeting w/util & Hechtel re proposed App R exemption requests & alternative shutdown sys Meeting agenda & list of attendees encl DICK. GF Decrating Reactors Branch 5 84/02/27. Operating Reactors Branch 5 5pp 22519 163 24x Fiche 50-244, 84/02/29, 8403060290
- 8403190243 Notification of 840418 workshop in King of Prussia.PA to discuss lessons learned from recent App R fire protection safe shuddown insp & topics described in IE Info Notice 84-09 Agenda for workshop encl MURLEY.TE Region 1. Office of Director 84/03/09 D'TOOLE, J D Consolidated Edison Co of New York Inc POLLOCK.M S Long Island Lighting Co UDERITY Fublic Service Electric & Oas Co of New Jersey 33pp 22672 062 24X Fiche 50-000,84/03/09,8403190243
- 8403260243 Revised emergency plan implementing procedures, including Procedure SC-410 re insp of emergency equipment, Procedure SC-322 re maining emergency survey ctr & Procedure SC-312 re maining operation support ctr W/840320 ltr * Rochester Gas & Electric Corp 84/03/20 MURLEY, T E Region Office of Director 27pp 22754 327 24X Fichs 50-244, 84/03/20, 8403260243
- J Insurance & indemnity information
- B40314007B Forwards Endorsement 79 to MAELU Policy MF-47 & Endorsements 93 & 94 to NELIA Policy NF-170, SINIBL J M Marsh & McLennan, Inc 84/03/05 SALTZMAN, J D Assistant Director for State & Licensee Relations 4pp 22634 186 24X Fiche 30-244.84/03/05.8403140078
- D Advisory Committee on Reactor Safeguards reports & correspondence
- 8403290335 Summary of ACRE Bubcommittee on RE Ginna 831116 meeting w/
 Utils. Gilbert Assoc. Wastinghouse. KMC. Inc. Taylor Assoc &
 LeBosuf. Lamb. Leiby & MacRee in Washington, DC re application
 to convert provisional DL to full-term DL
 A ACRE Advisory Committee on Reactor Bafeguards. 84/02/10
 ACRE Advisory Committee on Reactor Bafeguards 20pp 22807.237
 24X Ficher 50-244, 84/02/10, 8403280335
- P Operating license stage documents & correspondence
- 8403060115 Forwards add1 info in support of 831110 Tech Spec change request re use of technical support ctr battery in place of one Class IE battery for brief period KOBER, R W Rochester Qas & Electric Copp 84/02/29 CRUTCHFIELD, D Operating Reactors Branch 5 2pp. 22518 086 24X Fiche 50-244.84/02/29, 8403060115
- --B403060126 Rev 2 to Procedure EWR 3378, "Design Criteria Ginna Station Technical Support Ctr Battery Vital Battery Intertie " W/two oversite drawings. Aperture cards are available in PDR BMITH.J H , ANDERBON, C R , DANIELS, G. M. Rochester Gas & Electric Corp 82/11/11. 11pp 22518, 088 24X Fiche 50-244, 84/02/29, 8403060115

- 8403160138 Notification of 840315 meeting w/util.Applied Research Assoc & Gilbert Assoc in Bethesda:MD to discuss site-specific tornado parameters & structural upgrade program PERSINKO.D Systematic Evaluation Program Branch 84/03/07 ORIMES.C I Bustematic Evaluation Program Branch ip 22662 266 24X Fiche 50-244.84/03/07,8403160158
- 8403280122 Summary of 840224 meeting w/Westinghouse Cwners Group in Bethesda-MD re proposed Westinghouse steam generator tube rupture generic program Attendee list & agenda encl NERSES V Licensing Branch 3 84/03/07 Licensing Branch 3 35pp 22811 131 24X Fiche 50-000.84/03/07.8403280122
- 8403130225 Advises of plan for resolving upper plenum injection issue involving ECCB models by Mestinghouse & Exxon for calculating ECCB performance of Westinghouse two-hop plants Response to upcoming SER due 90 days after issuance CRUTCHFIELD. D Operating Reactors Branch 5 84/03/09 KOBER. R W Rochester Oas & Electric Corp. 3pp. 22606 060 24X Fiche 90-244,84/03/09,8403130225
- 8403210135 Forwards notice of consideration of issuance of amend to License DPR-18 & proposed NSHC determination & opportunity for hearing on 831220 request for Tech Spec change re fuel design CRUTCHFIELD, D. Operating Reactors Branch 5 84/03/19 KOBER, R W Rochester Oas & Electric Corp. 2pp. 22707 238 24X Fiche 30-244,84/03/19,8403210135
- --8403210143 Notice of consideration of issuance of amend to license DPR-18 & proposed NSHC determination & opportunity for hearing re-proposed fuel design change CRUTCHFIELD, D. Operating Reactors Granch 5 84/03/15 lipp 22707 240 24X Fiche 50-244.64/03/19.8403210135
- 840326019B Forwards proprietary responses to NRC questions re util application for amend to Tech Specs dtd Dec 1983 & application for withholding info Info withheld (ref 100FRZ 790)
 KOBER: R W Rochester Gas & Electric Corp 84/03/19 CRUTCHFIELD, D Operating Reactors Branch 5 1p 22756 099 24X
 Fiche. 50-244, 84/03/19, 840326019B
- --8403260201 Application for withholding proprietary responses to questions re applications for amend to Tech Specs dtd Dec 1983 MIEBENANN, R A Westinghouse Electric Corp 84/03/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 11pp 22756 100 24% Fiche 50-244,84/03/19,8403260198
- 8403280049 Discusses installation & NDE of steam generator tubesheet steams Approval to install 10 add1 steams, based on inspresults, requested.

 KDDER, R Rochester Gas & Electric Corp 84/03/23 CRUTCHFIELD, R Operating Reactors Branch 5 5pp 22776 344 24X Fiche 50-244,84/03/23,8403280069
- 84032901B5 Forwards "Containment Vessel Tendons" & "Containment Vessel Tendons Stress Relaxation " completing response to Comments 8 & Haiper NRC 830308 ltr Response to Comment 10 expected by 840401 KDBER, R W Rochester Gas & Electric Corp 84/03/26 CRUTCHFIELD, D Dersting Reactors Branch 5 2pp 22801 028 24X Ficho 50~244,84/03/26,8403270185
- --B403270188 "Containment Vessel Tendons," 1983 surveillance final rept DEMGBB.G T , FULTON, J F , HERR, J C Gilbert Associates, Inc GAI 2512 84/01/31 96pp 22801 030 24% Fiche 50-244,84/03/26,
- --B4032701B9 "Containment Vessel Tendons Stress Relaxation Properties of Retensioned Wires " FULTON.J F. HBIEH:S B., HERR.J.C Oilbert Associatos, Inc GAI 2497 B3/12/31 120pp 22801 127 24X Fiche 50-244.84/03/26. 84032901B5
- G. Inspection reports: IE Bulletins & correspondence
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl.

 JORDAN-E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22707 237 24X Fiche 50-000.84/02/28.8401170072
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl. GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 327 24X Fiche 50-000,84/03/02,8402090007

- 8402070008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24% Fiche 50-000,84/03/02,8402090008
- 8402090009 IE Info Notice 84-15. "Reporting of Radiological Releases "
 Svt list encl
 JCRDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York: Inc 117pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8402070011 IE Info Notice 84-17. "Problems W/Liquid Nitrogen Coaling Components Below Nil Ductility Temp " Svc list enc!
 JDRDAN, E Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24% Fiche 50-000.84/03/05.8402070011
- B402070024 IR Info Notice B4-09, Rev 1, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list enc! JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000, B4/03/07, B402090024
- B402090028 IR Info Notice B4-18, "Stress Corresion Cracking in PMR
 Bys " Svc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/07 Consolidated Edison Co of New
 York, Inc 118pp 22584 186 24% Fithe 50-000.84/03/07, B408090028
- B402090031 IE Dulietim 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list ent!
 DEYDUNG.R C Director's Office Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000,84/03/12,8402090031
- 8403270150 Responds to IE Bulletin 83-08 re electrical circuit breakers w/undervoltage trip feature in use in safety-related applications other than reactor trip sys No subj circuit breakers in use at facility KOBER. R W Rochester Cas & Electric Corp 84/03/12 MURLEY. T E Region 1. Office of Director ip 22769 150 24% Fiche 50-244.84/03/12.8403270150
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JURDAN. C L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24% Fichs 50-000,84/03/21,8402090043
- 8402090044 JE Info Notice 84-20, "Svc Life of Relays in Safety-Related Bys " Svc list enc! JORDAN, L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22931 Obi 24X Fiche 50-000,84/03/21,8402070044
- 8403270152 Responds to 1E Bulletin 83-07 re apparently fraudulent products sold by Ray Millor. Inc Matts never received directly from Ray Millor & equipment never received from suppliers using Ray Miller matts
 KOBER, R. W. Rochester Oas & Electric Corp. 84/03/21 MURLEY, T. E. Region 1. Office of Director 1p. 22769 147 24X
 Fiche 50-244.84/03/21.8403270152
- 8403280069 Discusses installation & NDE of steam generator tubesheet sleeves Approval to install 10 adds sleeves based on inspresults.requested KOBER.R Rochester Cas & Electric Corp 84/03/23 CRUTCHFIELD.R Operating Reactors Branch 5 5pp 22776 344 24X Fiche 30-244.84/03/23.8403280069
- 8403300189 Ack receipt of B40127 ltr informing NRC of steps taken to correct violations noted in JE lnsp Ropt 50~244/83-23 STAROSTECKI, R Division of Project & Resident Programs B4/03/23 KOBER, R W Rochester Gas & Electric Corp 2pp 22819 284 24X Fische 30~244, 84/03/23, 8403300189
- --8403300171 Responds to NRC 831228 ltr re violations noted in IE lasp Rept 50-244/83-23 Corrective actions Procedure 8M-2606 5D approved for use on 821203 Training accomplished for all liaison engineers in plant administrative procedures MAIER.J E Rochester Gas & Electric Corp 84/01/27 MURLEY.T E Region i, Office of Director 6pp 22819 286 24X Fiche 50-244,84/03/23,8403300189
- R Periodic operating reports & related correspondence
- B403020202 Monthly operating rept for Jan 1984 W/840210 ltr MCNAMARA.A E , BNOW, B A Rochester Gas & Electric Corp B4/01/31 5pp 22440 231 24% Fiche 50-244, 84/01/31, 8403020202

- B403300081 Monthly operating rept for Feb 1984 W/840310 ltr DDDDE,R E , SNOW B A Rochester Gas & Electric Corp 84/02/29 App 22822 078 24X Fiche 50-244.84/02/27,8403300081
- B403i30i32 Forwards "Effluent & Maste Disposal Semiannual Rept,
 Jul-Dec 1983," "Std Rept of Personnel Whole Body Exposure
 (frem) by Exposure Groups, 1983" & "Std Rept of Personnel &
 Man-Rem by Work & Job Function.1983 "
 KOBER, R W Rochester Gas & Electric Corp 84/03/02 MURLEY, T E
 Region 1. Office of Director 1p 22600 033 24X
 Fiche 50-244,84/03/02,8403130132
- --8403130142 "Effluent & Waste Disposal Semiannual Rept, Jul-Dec 1983 "
 * Duke Power Ca 83/12/31 £2pp 22600 034 24X
 Fithe 50-244,84/03/02 £403130132
- --B403130149 "Std Rept of Personnel Whole Body Exposure (Rem) by Exposure Groups:1783 " * Duke Power Co 83/12/31 lp 22600 046 24X Fiche 30-244,84/03/02,8403130132
- --B403130137 "Std Rept of Personnel & Man-Rem by Work & Job Function for 1983 "

 * Duke Pawer Co 83/12/31 1p 22600 047 24X Fiche 50-244,84/03/02,8403130132
- 8 Reportable occurrences, LERs & related correspondence
- 8403240233 Forwards summary list of deficiencies identified per 10CRESO 55(e).Part 21 & potential generic ltr repts for comments

 BTARDSTECKI, R Division of Project & Resident Programs 84/02/28

 Region 1, Office of Director 7pp 22756:065 24X

 Fichs 50-000:84/02/28.8403260233.

V Operator Examinations

- 8403190425 Notification of Significant Licenses Meeting 84-23 on 840315 w/util in King of Prussia.PA to discuss Region I evaluation of licensed operator requalification program CGLLING.8 J Assistant Director for Operating Reactors 84/03/08 DIRCKS.W Office of the Executive Director for Operations DEYDUNO.R Director's Office, Office of Inspection and Enforcement EISENHUT.D Division of Licensing is 22681331 24X Fiche 50-244.84/03/08.8403190425
- DOCKET 50-245 MILLSTONE NUCLEAR POWER STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8403240175 Rev 41 to emergency plan implementing procedure index & Rev 1 to Procedure EPIF 4305A, "Meteorological Tower Emergency Operations Pacility Computer Terminal Operation " W/840309 ltr COUNSIL 40 . SEARS, C F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, M Q Northeast Utilities 84/02/15 EISENHUT, D Q Division of Licensing 14pp 22756-171 24X Fiche 50-245,84/02/15,8403240195
- B403260143 Forwards general position statement on Reg Guida 1 97, Rev 2 re justification of significant generic deviations.per NUREO-0737, Suppl 1 COUNSIL.W 0 SEARB.C F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W 0 Connecticut Yankee Atomic Fower Co 84/02/27 MILLER.J R Operating Reactors Branch 3. CRUICHFIELD.D Operating Reactors Branch 3. Fiche 50-000.84/02/29.8403260143
- --B403260151 General position statement on Reg Quide 1 97, Rev 2 reinstrumentation for assessing plant & environ conditions during & following accidents

 * Northeast Nuclear Energy Co (subs. of Northeast Utilities). *
 Connecticut Yankee Atomic Power Co * Northeast Utilities
 B4/02/29 69pp 22758 165 24X Fiche 50-000.B4/02/27, 8403260143
- 8403190243 Notification of 840418 workshop in King of Prussie, PA to discuss lessons learned from recent App R fire protection safe shutdown insp & topics described in IE Info Notice 84-07 Agenda for workshop enci MURLEY, TE Region 1, Office of Director. 84/03/09, O'TDOLE, J D Consolidated Edison Co of New York, Inc FOLLOCK, MB Long Island Lighting Co USERITZ Public Service Electric & Qes Co. of New Jersey 35pp 22672:062, 24X Fiche. 50-000, 84/03/09, 8403190243
- 8403230029 Forwards response to request for add1 info concerning Suppl 1 to NUREO-0737 re procedures generation package & Rev 1 to emergency procedures guidelines CDUN811.W 9, SEARS, C.F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) COUNBIL, W.Q. Northeast Utilities 84/03/09 CRUTCHFIELD, D. Operating Reactors Brench 5 46pp, 22728 210 24X Fiche 50-243,84/03/09,8403230029

- --8403230034 Rev 1 to. "Millstone Nuclear Power Station Unit 1, Emergency Procedures Guidelines" * Northeast Nuclear Energy Co (subs of Northeast Utilities) 84/03/31 56pp 22728 256 24X Fiche 50-245.84/03/09.8403230029
- 8403260146 Forwards revised procedures for corporate organization for nuclear incidents procedure manual including Procedure CONI re table of contents & CONI i 05 re corporate emergency operations thro perations M/o encl COUNSIL, W 0 . SEARS, C F Connecticut Yankee Atomic Power Co COUNSIL, W 0 . Northeast Nuclear Energy Co (subs of Northeast Utilities) 8/03/07 EISENHUT, D 0 Division of Licensing 2pp 22750 330 24X Fiche 50-000,84/03/07,8403260146
- 8403220136 Provides results of reevaluation of performance assessment, pur util 831219 ltr addressing topics discussed at 831129 8ALP mgt meeting Category i rating will be assigned to refueling area for Milistone 2 Explains Category 2 ratings MURLEY, T E Region 1. Office of Director 84/03/16. COUNSIL.W Q Northeast Nuclear Energy Co (subs of Northeast Utilities) 4pp 22716 047 24% Fichs 50-000,84/03/16,8403220136
- 840327000B Informs that util will provide info re planned deviations from Suppl 1 to NUREO-0737 by 840501 Delay has no effect on schedules for implementation of Suppl 1 to NUREO-0737 COUNSIL. W 0 FEARS, C F Connecticut Yankee Atomic Power Co CDUNGIL. W 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) 84/03/16. EJSENHUT, D 0 Division of Licensing 2pp 22770 011 24X Fiche 50-000, 84/03/16, 840327000B
- 8403300084 Advises that 831214 Rev 18 to security plan & 840110 Rev 2 to training & qualification plan consistent w/provisions of 10GFR90 54(p) & acceptable MARTIN, T T Division of Engineering & Technical Programs 84/03/26 COUNSIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 3pp 22822 014 24X Fiche 50-245,84/03/26,8403300084
- J Insurance & indemnity information
- 8403140031 Forwards Endorsement 92 to NELIA Policy NF-173 SINIBI.J M. Marsh & McLennan, Inc. 84/03/05 9ALTZMAN, J D. Assistant Director for State & Licensee Relations 2pp 22633 019 24X Fiche 50-245.84/03/05,8403140031
- P Operating license stage documents & correspondence
- B403200271 Affidavit of Q Sherwood requesting NEDE-20592-6F. "STR Bundle Submittal, Millstons-1 Segmented Test Rod Bundle, Suppl 6," dtd Jul 1982, be withheld from public disclosure SHERMODD, Q Q General Electric Co 83/06/02 3pp 22696 171 24X Ficha 50-245,83/06/02,8403200271.
- 8403060454 Forwards Amends 95 & 92 to Licenses DPR-21 & DPR-65, respectively Amends change Tech Specs to comply w/final rule on licensed operator staffing.
 CRUTCHFIELD,D Operating Reactors Branch 5, 84/02/16 CQUNBIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities), 3pp 22511.193 24X Fiche:30-245.84/02/16.8403060454
- --8403060459 Amends 95 & 92 to Licenses DPR-21 & DPR-65, respectively, changing Tech Specs to comply w/final rule on licensed operator staffing CRUTCHFIELD, D Operating Reactors Branch 5 84/02/16 14pp 22511 196. 24X Fiche 50-245,84/02/16,8403060454
- 8403140340 Summary of 831215 meeting w/OE & Mark I Duners Oroup in Bethesda,MD re Mark I containment wetwell-drywell vacuum breaker design methodology. SIEOEL,B.L. Operating Reactors Branch 2. 84/02/21 Operating Reactors Branch 2 51pp 22635 198 24X Fiche 50-000,84/02/21.
- 8403070304 Provides responses to three open items from NRC/BNL Yankee Atomic Electric Co & consultants Mark I containment program plant-unique smalusis rept 840216 review meeting CELIA.N S. Teledune Engineering Services 84/02/28 BIEGEL.B NRC No Detailed Affiliation Given 4pp 22546.171 24X Fiche.50-000.84/02/28.8403070304.
- 8403130027 Informs that Amends 54,92 & 87 to Licenses DPR-61, DPR-21 & DPR-65, respectively, inadvertently eliminated reporting requirements for exceeding radiological limiting conditions for operation, Corrective actions identified.

 COUNSIL.W 0 Northeast Nuclear Energy Co (subs. of Northeast Utilities) COUNSIL.W Q Connecticut Yankee Atomic Power Co COUNSIL.W.9 Northeast Utilities 84/03/01. MILLER, JR Operating Reactors Branch 3. CRUTCHFIELD, D. Operating Reactors Branch 3. CRUTCHFIELD, D. Operating Reactors Branch 54, CRUTCHFIELD, D. Operating Reactors Branch 55, CRUTCHFIELD, D. Operating Reactors Branch 56, CRUTCHFIELD, D. Operating Reactors Branch 57, CR

- 8403170048 Informs that util postponed ultrasonic test/insp of saferend.no.zle bore & blend regions of feedwater no.zle per NUREO-0619, due to installation of low flow feedwater controller COUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W O Northeast Utilities 84/03/05 CRUTCHFIELD.D Operating Reactors Branch 5 2pp 22666 251 24X Fiche 50-245.84/03/05.08/03/190048
- 8403090240 Bummary of 840216 meeting w/Northeast Nuclear Energy Co. Boston Edison Co. Vermont Yankee Nuclear Power Co & Teledyne Engineering Svcs in Waltham. MA re addl Mark I torus structural analysis List of attendess encl SHEA.J J Operating Reactors Branch 5 SIEGEL. B Operating Reactors Branch 5 SIEGEL. B Operating Reactors Branch 5 4pp 22572 298 24X Fiche 50-000.84/03/07.8403090240
- 8403260200 Comments on Issue 3 of NUREG-0885, "NRC Policy & Planning Ouidance, 1984 " Seven themes identified represent important objectives for industry CDUNSIL, N O Northeast Utilities 84/03/12 DIRCKS, N J Office of the Executive Director for Operations 4pp 22756 204 24X Fithe 50-000, 84/03/12, 8403280200
- 8403150275 Generic Ltr 84-07 to all licensees of BMRs re procedural guidance for pipe replacement at BMRs Bvc list encl EISENHUT, D 0 Division of Licensing 84/03/14 Commonwealth Edison Co 20pp 22823 354 24% Fiche 50-000, 84/03/14, 8403150275
- 8403170383 Notification of 840412 meeting w/util in Bethesda, MD to review addl justification for exemption from primary reactor containment leakage testing requirements re transversing in-core probe SHEA: J Operating Reactors Branch 5 84/03/14 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 22675 205 24X Fiche 50-245,84/03/14,8403190383
- 8403210070 Forwards Amends 96 & 93 to Licenses DPR-21 & DPR-65, respectively Amends consist of changes to Section 6 of Tech Specs re nuclear review board.reorganization & STS CRUTCHFIELD, D. Operating Reactors Branch 5 84/03/19 COUNSIL.H 9 Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 6pp 22705 089 24X Fiche 50-245,84/03/19,8403210070
- --8403210079 Amends 96 & 93 to Licenses DPR-21 & DPR-65, respectively, consisting of changes to Section 6 of Tech Specs re nuclear review board, reorganization & 918 CRUTCHFIELD, Operating Reactors Branch 5 84/03/19 23pp 22705 095 24X Fiche, 50-245, 84/03/19, 8403210070
- 8403230085 Forwards safety evaluation of BMR Clumers Group generic response to NUREO-0737. Item II K 3 45 re depressurization w/other than automatic depressurization sys (ADB) No mods to plant design to operation required CRUTCHFIELD, D Operating Reactors Branch 5 84/03/20 COUNSIL, W © Northeast Nuclear Energy Co (subs of Northeast Utilities) App 22726, 335 24X Fiche 50-245, 84/03/20, 8403230085
- O Inspection reports, IE Bulletins & correspondence
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Metor Operated Valve Control Circuits & Annunciation " Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22909 239 24X Fiche 50-000.84/02/28,8401190072
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC." Bvc list encl ORACE.J N Division of GA. Bafeguards & Inspection Programs (Post 830103). B4/03/02 Consolidated Edison Co. of New York. Inc 130pp. 22552 327 24X Fiche 50-000.84/03/02.8402070007
- 8402090008 IE Info Notice 84-16: "Failure of Automatic Sprinkler Sys Valves to Operate" Svc list encl JDRDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553.098 24X Fiche 50-000.84/03/02.8402090008
- 8402070007 IE Info Notice 84-15, "Reporting of Radiological Releases" Svc list encl. JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 117pp 22553 217 24X Fichs 50-000,84/03/02,8402070009
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list each JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York Inc 117pp 22553 334 24X Fiche 50-000,84/03/05,8402090011

- 8402070024 IE Info Notice B4~07.Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 Q49 24% Fiche 50-000.84/03/07.8402090024
- B40209002B IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Bys " Svc list and] JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 IBB 24X Fiche 50-000,84/03/07.8402090028
- 8402090031 IE Builetin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Bys " Svc list encl DEYQUNG.R C Director's Diffice. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24% Fiche 50-000.84/03/12.8402090031
- 8403190045 Notification of 840323 meeting w/util in Bethesda.MD to discuss BMR primary coolant recirculation piping inap & possible use of pipe clamps if cracks identified SHEA.J J Operating Reactors Branch 5 84/03/14 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 22666 175 24X Fiche 50-245,84/03/14,8403190045
- 8403220136 Provides results of reevaluation of performance assessment, per util 831219 ltr addressing topics discussed at 831129 SALP mgt meeting Category I rating will be assigned to refueling area for Milistone 2 Explains Category 2 ratings MURLEY.TE Region 1. Office of Director 84/03/16 COUNSIL,W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 4pp 22716 047 24x Fiche 50-000,84/03/16.8403220136
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries anto PWR Reactor Cavities" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 123pp 22823 229 24% Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Bys " Bvc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc. 135pp 22933 001 24X Fishe 50-000,84/03/21,8402090044
- 8403300144 Responds to IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Haddam Neck facility uses 31 Westinghouse-type DB breakers CDUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) CGUNSIL.W G Connecticut Yankee Atomic Power Co CDUNSIL.W G Northeast Utilities 84/03/21 MURLEY.T E Region 1. Office of Director 4pp 22820 068 24X Fiche 30-000,84/03/21. 6403300144
- B403300086 Ack receipt of 840224 ltr (informing NRC of steps taken to correct violations noted in JE Insp Repts 50-245/83-20 & 50-336/83-28
 - MARTIN.T T Division of Engineering & Technical Programs B4/03/2: COUNSIL,W J Northeast Nuclear Energy Cn (subs of Northeast Utilities) 2pp 22822 017 24X Fiche 30-243,84/03/23,8409300086
- --8403300092 Responds to NRC 840125 itr re violations noted in IE Insp Repts 50-245/83-20 & 50-336/83-28 Corrective actions Procedure CP 809A rewritten to include method of determining hi & hi-hi alarm setpoints COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Northeast Utilities 84/02/24 MURLEY, T E Region I. Office of Director 2pp 22822 019 24X Fiche 50-245,84/03/29.8403300086
- R Periodic operating reports & related correspondence
- 9403230022 "Haddam Neck Plant & Millstone Station Units 1 & 2 Annual Rept, 1983 " M/840301 ltr GDUNSIL, W G , BEARS, C F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Connecticut Yankee Atomic Power Co 83/12/31 MURLEY, T E Region 1, Office of Director 348pp R2727 001 24X Fiche 50-000, 83/12/31, 8403230022
- B403020055 Honthly operating rept for Jan 1784 W/840213 ltr HARRAN.G., MRGCZKA.E J., MRGCZKA.E J. Northeast Nuclear Energy Co (auba of Northeast Utilities). B4/01/31 5pp 22442 254 24X Fiche 50-245,84/01/31,8403020055
- 8403120135 Forwards "Semiannual Radioactive Effluents Release Rept.
 Jul-Dec 1983 " Offsite dose astimates not included due to
 estimate delays Complate rept will be resubmitted by 840430
 COUNSIL.N G. OPEKA.J F Northeast Nuclear Energy Ca (subs of
 Northeast Utilities) COUNSIL.N G Northeast Utilities 84/02/28
 MUNIEY, T E Region 1. Office of Director 1p 22590 094 24X
 Fiche 50-245.84/02/28.8403120135

- ---840312013B "Semiannual Radioactive Effluents Release Rept, Jul-Dec 1983 " * Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/12/31 42pp 22590 097 24X Fiche 50-245,84/02/28,8403120135
- 8403300135 Monthly operating rept for Feb 1984 W/B40313 ltr HARRAN, O. MRGCZKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) MRGCZKA, E. J. Northeast Utilities B4/02/29 7pp 22820 023 24X Fiche 30-245,84/02/29,8403300135
- 5 Reportable occurrences, LERs & related correspondence
- 8403260233 Forwards summary list of deficiencies identified per iOCFR50 55(e).Part 21 & potential generic ltr repts for comments

 9TAROSTECKI.R Division of Project & Resident Programs Region 1, Office of Director 7pp 22756 065 24X

 Ficha 50-000.84/02/28.8403260233
- 8403260284 LER 84-003-00 on 840213.gamma scan performed on two oysters indicated presence of Ag-110M w/concentration exceeding control stateion average activity No operational corrective actions necessary W/640316 ltr KANQLEY, JP , MROCZKA, E J Northeast Nuclear Energy Co (subs of Northeast Utilities) 84/03/16 4pp 22754 278 24X Fiche 50-245.84/03/16.8403260284
- DOCKET 50-247 INDIAN POINT STATION, UNIT 2
- F Security, medical, emergency & fire protection plans
- 8403090288 Public version of page changes to Book I personnel procedures & Book II emergency procedures, including Procedure IP-1007 re determination of magnitude of release & exposure rate W/831213 ltr & JM Fetton release memo O'TOOLE, J D Consolidated Edison Co of New York, Inc 83/12/02 MURLEY, T E Region 1. Office of Director 80pp 22592 220 24X Fichs 90-003,83/12/02,8403090288
- 8403020341 Forwards IE Insp Rept 50-247/84-01 on 840109-11 No violations noted MARTIN T Division of Engineering & Technical Programs 84/02/17 O'TRILE, J D Consolidated Edison Ca of New York, Inc 2pp 22439 296 24X Fiche 50-247,84/02/17,8403020341
- --8403020342 IE Insp Rept 50-247/84-01 on 840109-11 No violations noted Major areas inspected public prompt notification sys WOJNAS, E.J., CROCKEN, H. W. Region 1, Office of Director 84/02/14 Spp 22439 298 24% Fiche 50-247,84/02/17,8403020341
- 8402090006 Board Notification 84-034 forwards R Vollmer 840R06 memo to D Eisenhut re fire research results concerning fires in electrical cabinets in control room EISENHUT.D Q Division of Licensing 84/02/23 PALLADINO, GILINSKY, ROBERTS Commissioners 1p 22576 203, 24X Fiche 50-000,84/02/23,8402090006
- --8403080316 Recommends that info re fire research results concerning fires in electrical cabinets in control room be submitted for board natification.per NRR Ofc Ltr 19.dtd 821001 Further evaluation of test data required VOLLMER.R H Division of Engineering 84/02/06 EISENHUT.D 0 Division of Licensing 10pp 22576 204 24X Fiche 50-000,84/02/23,8402090006
- B403190243 Notification of B40418 workshop in King of Prussia,PA to discuss lessons learned from recent App R fire protection safe shutdown insp & topics described in IE Info Notice 84-09, Agenda for workshop encl MURLEY,TE Region 1, Office of Director 84/03/09 D'TOOLE,JD Consolidated Edison Co of New York, Inc LUNDVALL,A E. Baltimore Oas & Electric Co RANDAZZA,JB. Maine Yankee Atomic Power Co 35pp 22672 062 24X Fiche 50-000,84/03/09,8403190243
- 8403170355 Forwards revised schedule re safety assessment sys/safety parameter display sys per Suppl 1 to NUREG-0737 Assessment indicates contractor capable of completing Job 0'TOOLE.J D Consolidated Edison Co of New York, Inc 84/03/12. EIBENHUT.D G Division of Licensing 4pp 22675 176 24X Fiche 50-247,84/03/12.8403190355
- 8403190049 Provides preliminary estimate of cost to upgrade present primary emergency operations facility to provide radiation protection factor of five 0'TODLE.J D Consolidated Edison Co of New York, Inc 84/03/14. EISENHUT.D C Division of Licensing 2pp 22666 132 24X Fiche 50-003,84/03/14.8403190069

B40329025i Advises that B31014 rev to physical security plan consistent w/provisions of iOCFR50 54(p) & acceptable MARTIN,T T Division of Engineering & Technical Programs B4/03/2i O'TOGDE,JD Consolidated Edison Co of New York, Inc 4pp 22800 001 24X Fiche 50-003,84/03/21,840329025i

H General correspondence

- 8403010170 Forwards Resolution 76 authorizing County participation in four-county radiological planning task force & authorizing use of County employees for radiological emergency response preparedness Implementation requested W/Certificate of Svc BEIGERMAN, V K Rockland County, NY 84/02/15 PALLADINO, N Commissioners 3pp 22435 307 24X Fiche 50-247,84/02/15,84030170
- P Operating license stage documents & correspondence
- 8403010262 Further response to FOIA request for documents re Sandia Contract A-1123 & bibliography used by R Bernero Forwards App A documents FELTON, J M Division of Rules and Records FIN A-1123 83/12/20 RUTLEDGE, P Carolina Environmental Study Group 2pp 22444 069 24X Fiche 50-000,83/12/20,8403010262
- --8403010248 Forwards preliminary draft documents re Sandia Labs work in area of siting criteria development Repts represent work being done in expanding use of probabilistic analysis in regulatory work W/o encis
 DIRCKS:W J Office of the Executive Director for Operations
 82/04/24 GILINSKY Commissioners 5pp 22444,071 24X
 Fiche 50-000,83/12/20,8403010262
- B403270002 Final response to FOIA request for four categories of documents; tests, studies & analyses referencing or pertaining to NUREO-0103, "BTS for IBAW PUR " App A documents encl FELTON, J M Division of Rules and Records 84/01/13 MADDEN, T J Kaye, Scholer, Flerman, Hays & Hendler App 22816 127 24X Fiche 50-000:84/01/13.8403270002
- --8403270004 Speech entitled "RCPB Leakage Detection Bys "
 POMEROY, D.L. Atomic Energy Commission, Directorate of Regulatory
 Operations 84/01/13 5pp 22817 003 24X Fiche 50-000,
 84/01/13.8403270002
- 8403010186 Forwards Amend 86 to License DPR-26 & safety evaluation Amend changes Tech Specs to require that no movement of reactor fuel be made unless reactor subcritical for at least 131 h PEDERSEN, R L Operating Reactors Branch 1 84/02/21 O'TOOLE, J D Consolidated Edison Co of New York. Inc 2pp 22479 199 24X Fiche 50-247, 84/02/21,8403010186
- --8403010194 Amend 86 to License DPR-26, changing Tech Specs to require that no movement of reactor fuel be made unless reactor subcritical for at least 131 h VAR6A.B A Operating Reactors Branch 1 84/02/21 4pp 22479 201 24X Fiche 50-247,84/02/21,8403010186
- --8403010199 Bafety evaluation supporting Amend 86 to License DPR-26 * Office of Nuclear Reactor Regulation, Director 84/02/21 3pt 22479 206 24X Fiche 50-247.84/02/21.8403010186
- 840302017B Requests add1 info re Task Action Plan F 1 (f)(3) Forwards list of questions needed to complete review Responses expected within 30 days of 1tr receipt VARQA:8 A Operating Reactors Branch 1 84/02/22 O'TOOLE, J D Consolidated Edison Co. of New York, Inc. 4pp 22491 086 24X Fiche. 50-247, 84/02/22, 8403020178
- 8403090095 Forwards application to amend License DPR-26 consisting of proposed Tech Spec changes, incorporating requirements of Item II B i of NURED-0737, "Reactor Coolant Vent Sys "
 0'TOOLE, J D Consplidated Edison Co of New York, Inc 84/02/28 VARGA, S. A Operating Reactors Branch i 2pp 22576 007 24X Fiche 50-247,84/02/28,8403090095
- --B403090098 Application for amend to License DPR-26, revising Tech Specs to incorporate requirements for reactor coolant vent sys O'TOOLE, J D. Consolidated Edison Co. of New York, Inc 84/02/28 2pp 22576.009 24X Fiche 50-247.84/02/28,8403090095
- --8403090101 Proposed Tech Spec re RCS vents per NUREO-0737, Item II B 1 * Consolidated Edison Co. of New York, Inc 84/02/29 Spp 22576:011 24% Fiche 50-247,84/02/28,8403090095.

- 8403070394 Forwards Amend B7 to License DPR-26 & safety evaluation Amend modifies Tech Specs to require min of 23 ft of water above reactor vessel flange during fuel handling operations PEDERSEN.R L Derating Reactors Branch 1 84/02/29 0'TDDLE.J D Consolidated Edison Co of New York. Inc 3pp 22567 023 24X Fiche 30-247.84/02/29.8403070394
- ---B403070398 Amend 87 to License DPR-26.modifying Tech Specs to require min of 23 ft of water above reactor vessel flange during fuel handling operations
 VARQA.S A Operating Reactors Branch 1 84/02/29 4pp
 22567 026 24X Fiche 50-247.84/02/29.8403070394
- --8403070402 Safety evaluation supporting Amend 87 to License DPR-26 * Office of Nuclear Reactor Regulation, Director 84/02/29 2pp 22567 030 24X Fiche 50-247.84/02/29.8403070394
- 8403210197 Forwards Amend 88 to License DPR-26 Amend modifies Tech Specs by relocating requirements of reactor vessel surveillance program from miscellaneous insp Bection 4 2 to RCS limiting conditions for operation in Section 3 1 B VARGA.E A Operating Reactors Branch 1 84/03/07 0'TOOLE, J D Consolidated Edison Co of New York. Inc 6pp 22709 178 24X Fichs 50-247.84/03/07.04803210197
- --8403210200 Amend 88 to License DPR-26,modifying Tech Specs by relocating requirements of reactor vessel surveillance program from miscellaneous insp Section 4 2 to RCS limiting conditions for operation in Section 3 1 8 VARGA.8 A Operating Reactors Branch 1 84/03/07 8pp 22709 184 24X Fiche 50-247,84/03/07,8403210197
- 8403300231 Advises that goal for completion of technical reviews & implementation of all NURGO-0737 items.excluding Suppl 1.is Sept 1944 Requests to be advised of potential problems within 30 days VARGA-S A Operating Reactors Branch i 84/03/13 D'TDOLE, J D Consolidated Edison Co of New York, Inc 2pp 22844 358 24X Fiche 50-247.84/03/13.8403300231
- 8402090041 Board Notification 84-050 provides Commission policy statement 5 proposed rulemaking on environ qualifications EISENNUT.D Q Division of Licensing 84/03/14 Atomic Safety and Licensing Board Panel 10pp 22716 338 24X Fiche 50-000.84/03/14.8402090041
- 8403200124 Advises that schedule for submittal of detailed control room design review summary rept will be provided by 840731, per 830831 ltr O'TOOLE,JD Consolidated Edison Co of New York, Inc. 84/03/14 EIBENHUT,D 9 Division of Licensing 1p 22685 352 24X Fiche 50-247,84/03/14.8403200124
- 8403290170 Forwards review status of remaining Generic Ltr 83-28 items re required actions based on generic implication of Salem ATWB events Westinghouse conducting life-cycle testing of shunt & undervoltage trip attachments O'TODLE.J D Consolidated Edison Co of New York, Inc 84/03/15 EISEMINIT.D C Division of Licensing 7pp 22803 081 24X Fiche 50-247.84/03/15.8403290170
- 8403270193 Notifies that util will provide addl info re performance testing of relief & safety valves, per Item II D i of NUREQ-0737.by 840615, per 840308 agreement OTOOLE, J D Consolidated Edison Co of New York, Inc 84/03/16 VARQA: S A Operating Reactors Branch i p 22771 102 24X Fiche 50-247,84/03/16,8403270193
- G Inspection reports: IE Bulletins & correspondence
- B403020341 Forwards IE Insp Rept 50-247/B4-01 on 840109-11 No violations noted MARTIN:T T Division of Engineering & Technical Programs 84/02/17 D'TODLE:J D Consolidated Edison Co of New York, Inc 2pp 22439 276 24X Fiche 50-247:84/02/17:8403020341
- --8403020342 IE Insp Rept 50-247/84-01 on 840107-11 No violations noted Major areas inspected public prompt notification sys HOJNAB,E J , CROCKER,H H Region 1, Office of Director 84/02/14 5pp 2242 298 24% Fiche 50-247.84/02/17.8403020341
- 8403050014 Ack receipt of 840127 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-247/83-22 MARTIN,T T Division of Engineering & Technical Programs 0'TOOLE,J D Consolidated Edison Co of New York, Inc 22490 133 24% Fiche 50-247,84/02/24.8403050014

- --8403050015 Responds to NRC 831229 ltr re violations noted in IE Insp Rept 50-247/83-22 Corrective actions detailed avaluation of documentation & insp records of 40 maint work packages conducted Withdrawal of violation requested O'TOULE.J D Consolidated Edison Co of New York. Inc 84/01/27 MARTIN.T T Division of Engineering & Technical Programs 3pp 22490 135 24X Fiche 50-247,84/02/24,8403050014
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc. 1159p 22709 239 24X Fiche 50-000.84/02/28.8401190072
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list ønc] GRACE, J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fithe 50-000.84/03/02.8402090007
- 8402070008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list enc!

 JORDANIE L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24% Fiche 50-000.84/03/02.8402070008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases" Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 119pp 22553 217 24K Fiche 50-000,84/03/02,8402090009
- B402090011 IE info Notice 84-17, "Problems H/Liquid Nitrogen Cooling Camponents Below Nil Ductility Temp " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc. 117pp 22553 336 24X Fiche 50-000.84/03/05.8402090013
- 8402090024 IE Info Notice 84-09, Rev 1. "Lessons Learned From Insps of fire Protection Safe Shutdown Bys " Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000.84/03/07.8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corresion Cracking in PWR Sys " Syc list enc! JDRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000.84/03/07.8402090028
- 8403210197 Forwards Amend 88 to License DPR-26 Amend modifies Tech Specs by relocating requirements of reactor vessel surveillance program from miscellaneous insp Section 4 2 to RCS limiting conditions for operation in Section 3 1 B VARGA, 8 A Operating Reactors Branch i 84/03/07 0'TDDLE, J D Consolidated Edison Co of New York, Inc 6pp 22709 178 24X Fiche 50-247,84/03/07.8403210197
- --8403210200 Amend 88 to License DPR-26 modifying Tech Specs by relocating requirements of reactor vessel surveillance program from miscellaneous imap Section 4 2 to RCS limiting conditions for operation in Section 3 18 VARGA-S A Operating Reactors Branch 1 84/03/07 8pp 22709 184 24X fiche 50-247,84/03/07,8403210197
- 8403180029 Forwards request for schedular relief from ASME Boiler & Pressure Vessel Code Section XI.IWD-2410 (b) re implementation of sys pressure testing as part of inservice inap program until Cycle 7/8 refueling outage complete O'TOOLE. J D Consolidated Edison Co of New York, Inc 84/03/08 VARGA, B A Operating Reactors Branch 1 Spp 22641 001 24X Fiche 50-247.84/03/08.8403150029
- 8402070D31 IE Bulletin 84-02, "Failures of 02 Type HFA Relays in Use in Class IE Bafety Sys " Svc list enc!
 DEYUUNG.R C Director's Office, Office of Inspection and Enforcement B4/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fichs 50-000.84/03/12,8402090031
- B403270172 Forwards summary of analysis assuming failure of fast acting main feedwater regulating valve to close on demand in response to IE Bulletin 80-04 Containment pressure & core reactivity response within FSAR acceptance criteria.
 O'TOOLE,J D Consolidated Edison Co of New York, Inc 84/02/15 VARGA.S A Operating Reactors Branch 1 App 22803 355 24% Fiche 50-247.84/03/15,8403290172
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PMR Reactor Cavities" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp. 22823 229 24X Fiche 30-000,84/03/21,8402090043

- 8402070044 IE Info Notice 84-20. "Svc Life of Relays in Safety-Related Sys " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000.84/03/21,8402090044
- 8403270268 Forwards response to IE Bulletin 83-07. "Apparently Fraudulent Products Sold by Ray Miller, Inc " No subj matls received for use at facilities Evaluation of other matls received from vendor encl G'TODLE, J D Consolidated Edison Co of New York, Inc 84/03/22 DEYQUNG, R C Director's Office, Office of Inspection and Enforcement 9pp 22800 011 24% Fiche 50-247,84/03/22,8403270268
- R Periodic operating reports & related correspondence
- 8403230135 "Personnel Whole Body Exposure for CY83 " W/840301 ltr D'IDDLE.J D Gonsolidated Edison Co of New York, Inc 83/12/31 MURLEY.T E Region 1, Office of Director 3pp 22730.137 24X Fichs.50-003,83/12/31.8403230135
- B403260120 "Effluent & Waste Disposal Semiannual Rept for Jul-Dec 1983 " W/B40301 ltr O'TODLE, J D Consolidated Edison Co of New York, Inc 83/12/31 MURLEY,T E Region 1, Office of Director 46pp 22758 086 24X Fich 50-003.83/12/31.8403260120
- 8403020155 Monthly operating rept for Jan 1984 W/840215 ltr BLATT.M , O'TOOLE.J D Consolidated Edison Co of New York, Inc B4/01/31 MCDONALD.W O Office of Resource Management, Director. 6pp 22442 028 24% Fiche 50-247.84/01/31.8403020155
- 8403270186 Monthly operating rept for Feb 1984 W/840315 ltr BLATT,M , G'TODLE J D Consolidated Edison Co of New York, Inc 84/02/29 MCDONALD.H Q Distribution Services Branch 7pp 22771 324 24X Fichs 50-247.84/02/29.8403270186
- S Reportable occurrences, LERs & related correspondence
- B403210154 LER 84-001-00 on 840104, low pressure alarm on weld channel & containment penetration prossurization sys sounded in central control room Caused by Isakage past one or both containment purge axhaust valves W/840227 ltr
 BLATT, M., O'TOOLE, J.D. Consolidated Edison Co. of New York, Inc. B4/02/03 MURLEY, T.E. Region 1. Office of Director 4pp. 22707 098 24X Fichs 50-247,84/02/03,8403210154
- 8403130405 LER 84-002-00 on 840105, two of four MSIVs did not fully close within 5 s Tech Spec requirement Caused by dried out valve shaft lubrication Shaft & packing lubricated W/840227 ltr
 BLATT.M , 0'700LE, J D Consolidated Edison Co of New York, Inc 84/02/04 MURLEY.T E Region 1. Office of Director Spp 22613 147 24% Fishe 50-247,84/02/04,8403130405
- 8403150073 EN-84-012 on 840313 notice of violation & proposed imposition of civil penalty in amount of \$40,000 will be issued to license Action based on violation of Tech Specs re containment spray sys insperability CRAIO, J. AXERAD. J Director's Office. Office of Inspection and Enforcement 84/03/08 ip 22641 248 24X Fiche 50-247,84/03/08.
- 8403270204 LER 84-003-00 on 840205. Unit brought to hot shutdown due to RPI channel drift Caused by uncalibr analog-signal due to movement in voltage adjustment putentiometer on RPI power supply sola transformer W/840322 ltr 0*TODLE.J D Consolidated Edison Co of New York, Inc. 84/03/22. 4pp 22770 284 24% Fichs 50-247.84/03/22.8403270204
- T Hearing transcripts on non-antitrust matters
- 8403160004 Transcript of ACRS Subcommittees on Reliability & PRA & Indian Point Units 2 & 3 840314 meeting in Washington, DC Pp 1-60. Supporting documentation encl * ACRS Advisory Committee on Reactor Safeguards 84/03/14 61pp 22653.289 24X Fichs 50-247,84/03/14,8403160004
- DOCKET 50-249 DRESDEN NUCLEAR POWER STATION, UNIT 3

 F Security, medical, emergency & fire protection plans
- B403050004 Forwards FEMA B40206 ltr & final exercise evaluations on B30914 offsite emergency preparedness exercise. Recommendations from rept do not affect approval of plan. PAPERIELLO, C J Region 3, Office of Director 84/02/29. REED, C Commonwealth Edison Co 2pp 22490 240 24X Fiche 50-237.84/02/29.8403050004

- 8403120053 Advises of 840323 regional workshop in Rosemont, IL w/all Region III licensees to discuss fire protection safe shutdown requirements of iOCFR50, App R Agenda encl SPESSARD, R L Division of Emergency Preparedness & Operational Support 84/03/06 REED, C Commonwealth Edison Co 3pp 22585 222 24X Fiche 50-010, 84/03/06, 8403120053
- 8403150092 Forwards results of in-progress audit of detailed control room design review Util pursuing course of review which NRC believes will satisfy requirements of Suppl I to NVREG-0737 CRUTCHFIELD, D Operating Reactors Branch 5 84/03/14 FARRAR.D L CRUTCHFIELD, Bdjson Co 11pp 22643 002 24X Fiche 50-237, 84/03/14,8403150092

9 Adjudicatory correspondence

- 8402220137 Order extending time until 840228 for Commission to act to review Director's Decision DD-83-14 CHILK, B J Office of the Secretary of the Commission 84/02/21 Commissioners 1p 22337 362 24X Fiche 50-000,84/02/21.
- 8403010238 Order extending time until 840305 for Commission to act to review Director's Decision DD-83-14 & 831027 decision denying request of Environ Policy Inst CHILK, B J Office of the Secretary of the Commission 84/02/28 Commissioners ip 22434-210 24X Fiche 50-000,84/02/28,8403010238
- B403090069 Informs that Commission unanimously declined to review Director's Decision DD-63-14 Time provided by NRC regulations within which Commission may act to review expired Dacision became final agency action on 840305 CHILK, B J Office of the Secretary of the Commission 84/03/08 CELEBREZZE, A J Dhio, State of 2pp 22575 350 24X Fiche 50-000,84/03/08.8403090069
- 8403090074 Informs that Commission unanimously declined to review Director's Decision DD-83-14 Time provided by NRC regulations within which Commission may act to review expirate. Decision became final agency action on 840305 CHILK.B J Office of the Secretary of the Commission 84/03/08 MILLAR.F Environmental Policy Institute ip 22575 292 24X Fichs 50-000, 84/03/08, 8403090074
- B403070113 Informs of Commission decision not to review Director's Decision DD-83-14 Time for Commission to act expired on 840305 W/o sncl.
 GHTLK.B J Office of the Secretary of the Commission 94/03/08 REBNIKOFF,M. Bierra Club ip 22576 079 24X Fiche 50-000.84/03/08.0403070113

P. Operating license stage documents & correspondence

- B403020037 Notification of contract execution "Dresden & Perry
 Bimulator Leasing," awarded to GE
 JEBBUP,B Technical Assistance Contracts Branch FIN B-8713
 B4/02/17 HAVINS,O H Director's Office, Office of Inspection and
 Enforcement 1p 22491 045 24X Fiche 50-000,84/02/17,8403020037
- --8403020043 Contract "Dresden & Perry Simulator Leasing," awarded to QE PIERCE,R,L General Electric Co. FIN B-8713 84/02/17 38pp 22491.046 24X Fiche 50-000,84/02/17,8403020037
- B403140340 Summary of 831215 meeting w/GE & Mark I Dwners Group in Bethesda, MD re Mark I containment webwell-drywell vacuum breaker design methodology SIEGEL, B L Operating Reactors Branch 2 84/02/21 Operating Reactors Branch 2 51pp 22635 178 24X Fiche, 50-000, 64/02/21, 8803140340
- 8403050119 Forwards supplemental response to Generic Ltr 83-28,
 "Required Actions Based on Generic Implications of Salem
 ATMS Events."
 BARNES, P L. Commonwealth Edison Co. 84/02/29 DENTON, H R Office
 of Nuclear Reactor Regulation, Director 26pp 22488 084 24X
 Fichs. 50-000, 84/02/29, 8403050119
- 8403130070 Forwards proposed resolution of environ qualification SER & Franklin Research Ctr technical evaluation rept open item deficiencies Final SER should be issued to indicate resolution of program deficiencies RYBAK, B. Commonwealth Edison Co 84/02/27 DENTON, H R. Office of Nuclear Reactor Regulation, Director 46pp 22602 123 24X Ficher 50-237, 84/02/29, 8403130070

- 8403130400 Forwards 840210 responses to Generic Ltr 83-35 clarifying TMI Item II K 3 31 Util concurs w/NRC position Item should be closed RYBAK, B Commonwealth Edison Co 84/03/02 EISENHUT, D G Division of Licensing 2pp 22613 143 24X Fiche 50-000, 84/03/02, 8403130400
- 8403130410 Application for amend to Licenses DPR-19 & DPR-25, revising Tech Spec Table 3 7 1 to require min addition of four LPCI & two torus spray suction valves RYBAK, B Commonwealth Edison Co 84/03/05 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22616 031 24X Fiche 50-237,84/03/05,8403130410
- --8403i304iB Proposed changes to Tech Spec Table 3 7 1 to require min addition of four LPCI & two torus spray suction valves * Commonwealth Edison Co 84/03/05 10pp 22616 053 24X Fiche 50-237, B4/03/05, B403i30410
- 8403140133 Forwards Amend 74 to License DPR-23 & safety evaluation Amend changes Tech Specs to support Cycle 9 operation w/reload fuel supplied by & associated analyses performed by Exxon CRUTCHFIELD, D. Operating Reactors Branch 5 84/03/09 FARRAR, D. L. Commonwealth Edison Co. 4pp. 22620 189 24X Fiche 50-249, 84/03/09, 8403140133
- --8403140143 Amend 74 to License DPR-25 changing Tech Specs to support Cycle 9 operation w/reload fuel supplied by & associated analyses performed by Exxon CRUTCHFIELD, D Operating Reactors Branch 5 84/03/09 10pp 22620 193 24x Fiche 50-249,84/03/09,8403140133
- --8403140188 Safety evaluation supporting Amend 74 to License DPR-25 * Office of Nuclear Reactor Regulation, Director B4/03/09 12pp 22620 203 24X Fiche 50-249,84/03/09,8403140133
- B403150275 Generic Ltr 84-07 to all licensees of BMRs re procedural guidance for pipe replacement at BMRs 8vc list encl EIBENHUT.D G Division of Licensing 84/03/14 Commonwealth Edison Co 20pp 22823 354 24X Fiche 50-000,84/03/14.8403150275
- 8403220153 Application to amend Licenses DPR-19 & DPR-25, revising Tech Specs to update snubber tables to reflect additions, deletions & other changes RYBAK, Il Commonwealth Edison Co 84/03/15 DENTON, HR Office of Nuclear Reactor Regulation, Director 3pp 22715 338 24% Fichs 50-237,84/03/15,8403220153
- --8403220158 Proposed Tech Specs updating snubber tables to reflect additions deletions & other changes * Commonwealth Edison Co 84/03/15 20pp 22715 341 24X Fiche 50-237, 84/03/15,8403220153
- B403270130 Application for amend to License DPR-25, changing Yech Specs to extend certain MAPLHOR curves to 40,000 MHd/ST RYBAK,B Commonwealth Edison Co B4/03/19 DENTON,H R Office of Nuclear Reaction Regulation, Director 2pp 22774 129 24X Fiche 50-000,84/03/19,8403270130
- --B403270136 Errata & Addenda Sheet 9, replacing Page 4-14 to "LQCA Analysis Rept for Oresden Units 2 & 3 & Quad Cities 1 & 2 Nuclear Power Stations " # General Electric Co NEDO-24146A ERR 09 B3/01/31 2pp 22774 135 24X Fiche 50-000,84/03/19,8403270130
- --8403270144 Proposed Tech Bpecs re extension of certain MAPLHOR curves to 40.000 MHd/9T * Commonwealth Edison Co 84/03/19 Jpp 22774 137 24X Fiche 50-000,84/03/19,8403270130
- 8403220047 Forwards corrected Page 45 to Amends 81 & 73 to Licenses DPR-19 & DPR-25, respectively, which failed to include Footnote II re verification of time delay setting between 3 & 9 & CRUTCHFIELD, D. Operating Reactors Branch 5 84/03/20 FARRAR, D. L. Commonwealth Edison Co. 4pp. 22712 197 24X Fiche 50-237,84/03/20.8403220047
- Q Inspection reports, IE Bulletins & correspondence
- B403120134 Forwards IE Insp Repts 50-237/84-01.50-249/84-01. 50-254/84-01.50-265/84-01.50-295/84-01 & 50-304/84-01 on 840203-14 No noncompliance identified 9HAFER.W D Region 3, Office of Director 84/02/23 REED.C Commonwealth Edison Co 2pp 22590 090 24X Fiche 50-000.B4/02/23, 8403120134

- --8403120137 IE insp Repts 50-237/84-01.50-249/84-01.50-254/84-01. 50-265/84-01.50-295/84-01 & 50-304/84-01 on 840203-14 No noncompliance or deviations identified Major areas inspected aligations of improper operation CKRISSOTIMOS.R., TONOUE.T., HGLZMER.M. Region 3, Office of Director 84/02/21 4pp 22590 092 24X Fiche 50-000.84/02/23, 8403120134
- 8403050043 Forwards Rev O to "Corporate Regulatory Performance Improvement Plan" Plan designed to heighten employee awareness & strengthen corporate ability to improve regulatory performance THOMAS, B Commonwealth Edison Co 84/02/24 KEPPLER, J G Region 3, Office of Director 3pp 22470 137 24X Fiche 50-000, 84/02/24, 84035042
- --8403050046 Rev O to "Corporate Regulatory Performance Improvement Plan" + Commonwealth Edison Co 84/02/29 22pp 22490 142 24X Fiche 50-000.84/02/24.8403050043
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list enc!

 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc. 1155p 22909 238, 24X Fiche 50-000,84/02/28,8401190072
- 8402070807 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl GRACE. J N Division of GA. Safeguards & Inspection Programs (Post B30103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 327 24X Fichs: 50-000.84/03/02,8402090007
- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate" Svc list encl JORDAN E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York Inc 122pp 22553 098 24X Fiche 50-000.84/03/02,8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases" Svc list encl JORDAN E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 119pp 22553 217 24X Fiche 50-000.84/03/02,8402090009
- 8402090011 IE Info Notice B4-17, "Problems W/Liquid Nitrogen Cooling Components Below Ni1 Ductility Temp " Svc list enc)
 JORDAN,E C. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co. of New York, Inc. 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8403130370 Forwards summary of ulbrasonic insp & resultant repairs on stainless steel welds covered by 830826 order Summary lists overall insp scops welds not examined & table of welds w/indications of intergranular stress corrosion cracking RYBAK.8 Commonwealth Edison Co 84/03/05 DENTON, H R Defice of Nuclear Resultar Regulation, Director 51pp 22614 334 24X Fiche 50-249.84/03/05.8403130370
- 8402090024 IE Info Notice 84-09, Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000,84/03/07,8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Sys " SvC list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 184 24X Fiche 50-000,84/03/07,8402090028
- 8403190001 Commits to submit plans for insp.corrective actions &/or mods.including potential replacement of recirculation or other piping.at least 90 days prior to next refueling outage scheduled for Apr 1985 SCHROBDER.C W Commonwealth Edison Co 84/03/09 DENTON, H R DfPice of Nuclear Reactor Regulation, Director 2pp 22664 324 24% Fiche 50-249,84/03/09,8403190001
- 8402070031 IE Bulletin 84-02. "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl DEYDUNG: C Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 154pp 22823 094 24X Fiche: 50-000.84/03/12.8402070031
- 8403200196 Responds to 840307 telcon re mid-cycle insp results of sweepplet welds 22A-4 k 228-8 on recirculation symploging RYBAK.8 Commonwealth Edison Co 84/03/12 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22697 116 24X Fiche. 30-249, 84/03/12, 8403200196

- 8403190074 Forwards order reintergranular stress Corrosion cracking insp & repair at facility & SER CRUTCHFIELD D Operating Reactors Branch 5 84/03/15 FARRAR, D L Commonwealth Edison Co 2pp 22669 335 24X Fichs 50-249,84/03/15,8403/190074
- ~-8403190077 Order confirming util commitments re intergranular stress corresion cracking insp PURPLE,R A Division of Licensing 84/03/15 Commonwealth Edison Co 6pp 22669 337 24% Fiche 50-249,84/03/15,8403190074
- --B403190082 Safety evaluation re intergranular stress corrosion cracking insp & repair Plans for insp & mod of recirculation & other RCPB piping sys should be submitted for review 3 months before refueling outage

 * Office of Nuclear Reactor Regulation, Director 84/03/15
 15pp 22669 343 24X Fichs 50-249,84/03/15,8403190074
- 8403190107 Forwards safety evaluation supporting util 831209 plan for insp & repair of remaining welds covered in NRC 830826 intergranular stress corrosion cracking insp order confirming shutdown Plant may return to power operation DENTON, H R Office of Nuclear Reactor Regulation. Director 84/03/15 FARRAR, D L. Commonwealth Edison Co 3pp 22669 200 24X Fiche 50-249,84/03/15.8403190107
- --B403190113 Safety evaluation supporting util B31209 plan for insp & repair of remaining welds covered in NRC B30826 intergranular stress corrosion cracking insp order confirming shutdown Full power operation acceptable * Office of Nuclear Reactor Regulation. Director B4/03/15 15pp 22669 203 28% Fiche 90-249, B4/03/15, B403190107
- 8403230088 Ack receipt of regulatory performance improvement plan
 Periodic meetings requested to discuss progress on program
 & provide feedback
 KEPPLER, J Q Region 3, Office of Director 84/03/20 THOMAS, B
 Commonwealth Edison Co 1p 22730 161 24X Fiche 50-000, 84/03/20, 8403230088
- --8403230107 Forwards corporate regulatory performance improvement plan THOMAS: 8 Commonwealth Edison Co 84/02/24 KEPPLER: J 9 Region 3. Office of Director 3pp 22730 162 24X Fiche 50-000, 84/03/20, 8403230088
- --B403230124 Rev O to "Corporate Regulatory Performance Improvement Plan For Dresden, Quad Cities, Zion & LaBalle Operating Nuclear Stations & Byton & Braidwood Project Operating Organizations " * Commonwealth Edison Co B4/02/27 22pp 22730 165 24X Fiche 50-000, 84/03/20, 8403230088
- 8403260196 Forwards responses to IE Bulletin 83-07, "Apparently Fraudulent Products Bold by Ray Miller, Inc " Quad Cities supplied w/piping matis from Ray Miller, Inc during const Evaluation encl Concerns of IE Bulletin 83-06 satisfied BARNES, P L Commonwealth Edison Co 84/03/20 KEPPLER, J Q Ragion 3, Office of Director 19pp 22756 185 24X Fiche 30-000,84/03/20,8403260196
- B402090043 IE Info Notice B4-19, "Two Events Involving Unauthorized Entries into PHR Reactor Cavities" Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 630103) 84/03/21 Consolidated Edison Co of New
 York, Inc. 123pp 92823 229 24X Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Bys " Svc list enc! JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103), 84/03/21 Consolidated Edison Co of New York, Inc. 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044
- R Periodic operating reports & related correspondence
- 8403060099 "Rept of Radioactive Effluents.Jul-Dec 1983" W/840215 ltr SCOTT.D J Commonwealth Edison Ca 83/12/31 KEPPLER, J G. Region 3. Office of Director 17pp 22506 245 24X Fiche 50-010.83/12/31. 8403060099
- B4030B0197 "Rept of Occupational Personnel Radiation Doses, 1983."
 W/840227 ltr
 BCOTT.J & Commonwealth Edison Co 83/12/31 CASE, E Q Office of
 Nuclear Reactor Regulation, Director 13pp 22557 099 24X
 Fichs 50-000, 83/12/31, 8403080197
- 8403220120 Annual whole body external exposures for 1983 W/840316 ltr RVBAK: B Commonwealth Edison Co 83/12/31 7pp 22716 007 24X Fiche 50-000,83/12/31,8403220120

8403130015 Monthly operating repts for Feb 1984 H/840301 ltr 8CHROEDER, B A , SCOTT, D J Commonwealth Edison Co 84/02/29 17pp 22614 344 24X Fiche 50-237,84/02/29,8403130015

DOCKET 50-250 TURKEY POINT PLANT, UNIT 3

- F Security, medical, emergency & fire protection plans
- 8403280110 Public version of Emergency Plan Implementing Procedures 20103, "Classification of Emergencies" & 20104, "Emergency Roster" W/840123 ltr & JM Felton 840322 release memo BAKER.C , HILLIAMS, JW Fibrids Power & Light Co 84/01/17 O'REILLY, JP Region 2, Office of Director 31pp 22811 329 24) Fiche 80-280.84/01/17,8403280110
- B403020204 Forwards IE Insp Repts 50-250/83-43 & 50-251/83-42 on 831216 & notice of violation Notice of violation withheld (ref 10CFR2 790(d) & 10CFR2 791)
 LEWIS.R C Division of Project & Resident Programs 84/01/29 WILLIAMS, J W Florida Power & Light Co 2pp 22440 094 24X Fiche 30-250,64/01/25,8403020204
- --8403020241 IE Insp Repts 50-250/83-43 & 50-251/83-42 on 831214
 Noncompliance noted employee circumvented security access
 control sys Details withheld (ref 10CFR2 790 & 10CFR73 21)
 TILLMAN,A . BREWER,R Region 2. Office of Director MCGUIRE,D R
 Division of Emergency Preparedness & Materials Bafety 84/01/20
 1p 22440 096 24X Fiche 50-230.84/01/25,8403020204
- 8403060086 Approves state & local plans & preparedness for electing & protecting public in event of radiological emergency Approval conditional on verification of alert & notification sys per criteria of App 3 of NAREG-06534/FEMA-REP-1, Rev i BPECK.S W Federal Emergency Management Agency 84/02/15 DIRCKS.W J Office of the Executive Director for Operations ip 22516 300 24X Fiche 50~250,84/02/15,8403060086
- B403010173 Forwards order confirming licensee commitments to implement post-THI related items per Suppl 1 to NUREQ-0737 Schedular commitments reasonable, achievable & will provide timely upgrading of emergency response capability VARGA. S A Operating Reactors Branch 1 84/02/23 WILLIAMS, J J Florida Power & Light Co 4pp 22479 209 24X Fiche. 50-250:84/02/23.8403010173
- --8403010180 Order confirming licensee commitments to upgrade emergency response capability, per Suppl 1 to NUREG-0737 (Generic Ltr 82-33) EIEENHUT, D G Division of Licensing 84/02/23 Florida Power & Light Co &pp 22479 213 24X Fiche 50-250.84/02/23,8403010173
- B403020285 Ack receipt of B40215 ltr informing NRC of steps taken to correct violations noted in IE Safeguards lnsp Repts 50-230/83-42 LEWIB.R C Division of Project & Resident Programs B4/02/27 WILLIAMB.J W Fibrida Power & Light Co lp 22440 069 24X Fiche 50-250.84/02/27.8403020285
- --8403020288 Responds to NRC 840125 ltr re violations noted in IE Safeguards Insp Repts 50-250/83-43 & 50-251/83-42 Corrective actions withheld (ref 10CFR2 770 & 73 21) HILLIAMS, J.W. Florida Power & Light Co 84/02/15 D'REILLY, J.P. Region 2, Office of Director ip 22440 070 24X Fiche 50-250,84/02/29,8403020285
- 8403160254 Notifies of 840316 workshop to discuss 10CFR30.App R requirements & insp results to resolve misunderstandings refire protection Attendees should be limited to six due to size of conference room LEMIS.R C Division of Project & Resident Programs 84/03/02 WILLIAMS, J W Florida Power & Light Co 1p 22660 255 24x Fichs 50-000.84/03/02.8403160254
- 8403190429 Forwards regulatory effectiveness review (RER) rept.possible solutions to RER concerns & observations & vital areas definition rept.Encls withheld (ref 100FR73 21) VAROA:8 A Operating Reactors Branch 1 84/03/06 WILLIAMS, J W Florida Power & Light Co. 1p 22681 327 24X Fiche 50-250, 84/03/06,8403190429

O Adjudicatory correspondence

8403070135 Brief on conflict posed by legal requirement of timeliness & equitable considerations ASLB should issue ruling allowing patitioners contentions that address new fuel core design, changes in Tech Specs & reduction in safety margins HODDER.M H Center for Nuclear Responsibility 84/03/03 lipp 22538 265 24% Fiche 30~230,84/03/03,8403070135

- --8403070139 Motion for leave to file brief on conflict pased by legal requirements of timeliness & equitable considerations on B40303 instead of B40302 Certificate of Svc encil HODDER.M H Center for Nuclear Responsibility B4/03/03 Atomic Safety and Licensing Board Punel 2pp 22338 276 24X Fiche 50-280.84/03/03.8403070135
- --8403070143 Forwards applicant B30325 ltr w/encl fe util pressurized thermal shock & flux reduction program per B40228 request W/o ltr HODDER, M H HODDER, M H Center for Nuclear Responsibility 84/03/03 Atomic Safety and Licensing Board Panel 7pp 22538 278 24% Fiche 50-230,84/03/03.8403070135
- 8403140017 Response to NRC & util responses to amended petition to intervene NRC guilty of conducting business lawlessky via repeated OL amends ω/NSHC determination Certificate of Svc enci HODDER, M H Center for Nuclear Responsibility HODDER, M H Hodder, M H 84/03/07 Atomic Safety and Licensing Board Panel 20pp 22632 144 24% Fiche 50-250.84/03/07.8403140017
- ---B403140023 Motion for leave to file late, due to delays in typing & reproduction
 HODDER, M H Center for Nuclear Responsibility HODDER, M H
 Hodder, M H B4/03/07 Atomic Safety and Licensing Board Panel
 3pp 22632 164 24X Fiche 50-250.84/03/07, B403140017
- 8403130034 Order granting licensee motion for extension of time to 840314 for filing response to potitioner 840303 brief re consolidating consideration of two sets of license amends issued last yr LAZO.R M Atomic Safety and Licensing Board Panel 84/03/09 ip 22614 307 24X Fiche 50-230.84/03/09.8403130034
- 8403190062 Response to Ctr for Nuclear Responsibility & J Lorion 840303 brief on conflict posed by legal requirements of timeliness & equitable considerations ABLB should exclude any & all issues re 831209 Amends 92 & 98 Certificate of Svc encl WOODHEAD: C P Hearing Branch 4 84/03/14 12pp 22666 200 24x Fiche 50-250.84/03/14.8403190062
- 8403170171 Response to petitioners 840303 brief re consolidating two sets of license amends issued in late 1983 in support of new fuel assemblies ABLB should confine proceeding to 841007 amends
 841007 amends
 8AUSER, M A Florida Power & Light Co BAUSER, M A Newman & Holtzinger 84/03/14 Atomic Safety and Licensing Board Panel 15pp 22670 265 24% Fiche, 50-250, 84/03/14, 8403190171
- --B403190179 Affidavit of DC Poteralski on petitioners 840303 briaf re conflict posed by legal requirement of timeliness & equitable considerations Util 830720 amends not part of pressurized thermal shock program H/Certificate of Svc POTERALSKI.D C Florida Power & Light Co 84/03/09 17pp 22670 280 24X Fiche 50-250.84/03/14.8403190171
- 8403290277 Forwards WL Guthrie 840228 ltr to be served on parties
 Copy should be placed in PDR
 LAZO,R M Atomic Safety and Licensing Board Panel DSD 178
 84/03/27 CLEMENTS,W L Record Services Branch (Document Control
 Desk) ip 22801 336 24X Fiche 50~250.84/03/27,8403270297
- --B403290304 Forwards file presented to Dade County Citizens Review
 Committee objecting to DL issuance
 OUTHRIE.W L Affiliation Not Assigned B4/02/28 Atomic Bafety
 and Licensing Board Panel 57pp RRB01 337 24X
 Fiche 50-250

H General correspondence

- 8403280149 Responds to 840208 ltr requesting assistance in responding to J Paskavitch ltr requesting latest EIB on concentrations of Sr-90,Cs-137 & I-131 near plants Two annual repts entl W/o repts
 DIRCKS.W J Office of the Executive Director for Operations 84/03/07 CMILES.L Benate 4pp 22809 316 24X
 Fiche 50-000.84/03/07,8403280149
- --8403280156 Forwards constituent J Paskavitch itr requesting latest EIS on concentrations of Br-90.05-137 & I-131 near plants.

 Comments & views requested.

 CHILES.L. Senate 84/02/08 KAMMERER.C. Office of Congressional Affairs 8pp 82809 320 24X Fiche 50-000.84/03/07.8403280149

J Insurance & indemnity information

8403060332 Forwards Endorsement 70 to NELIA Policy NF-185 DUCK,J R Marsh & McLennan, Inc. 84/02/28 SALTZMAN, J Assistant Director for State & Licensee Relations 2pp 22516 011 24X Fiche 50-250.84/02/28.8403060332

- P Operating license stage documents & correspondence
- 8403010160 Forwards Amends 101 & 75 to Licenses DPR-31 & DPR-41, respectively & safety evaluation Amends revise Tech Specs to add motor operated valves 863-A & 863-B to existing valves required to have power removed MCDONALD, B G Operating Reactors Branch 1 B4/02/22 WILLIAMS, J W Florida Power & Light Co Opp 82479 232 24X Fishe 50-250,84/02/22,8403010160
- --8403010171 Amends 101 & 95 to Licenses DPR-31 & DPR-41, respectively. revising Tech Specs to add motor operated valves 863-A & 863-B to existing valves required to have power removed VAROA.S A Operating Reactors Branch 1 84/02/22 7pp 22477 235 24X Fiche 50-250,84/02/22,8403010140
- --B403010177 Safety evaluation supporting Amends JO1 & 95 to Licenses DPR-31 & DPR-41, respectively "Office of Nuclear Reactor Regulation, Director 84/02/22 7pp 22479 242 24X Fichs 50-250,84/02/22,8403010160
- 8403020184 Requests identification of any potential problems or items that cannot be met within time frame required to meet Sept 1984 goal for completion of NURSG-0737 items VARGA.8 A Operating Reactors Branch 1 84/02/22 HILLIAMS, J Florida Power & Light Co 2pp 22495 005 24X Fiche 50-230,84/02/22.8403020184
- 8403040168 Notifies that administrative program & procedures now in effect will be reviewed to confirm implementation of recommended guidelines in NUTAC rept.per Generic Ltr 83-28 WILLIAMS.J C Florida Power & Light Co 84/03/01 EISENHUT.D 0 Division of Licensing 1p 22518 336 24X Fiche 50-000, 84/03/01, 84030.0168
- 8403080020 Forwards integral neutron source data for evaluating & verifying flux reduction per 84117 request Data for Cycle 9 core octant time averaged relative power density.critical weld peaking factor & peripheral assembly pin power encl HILLIAMS.J W Florida Power & Light Co 84/03/01 VARQA.B A Operating Reactors Branch i. 10pp 22559 229 24X Fichm 50-250.84/03/01.8403080020
- 8403190150 Notifies of 840402-06 meeting & preimplementation audit at Turkey Point to discuss confirmatory items identified in safety evaluation of detailed control room design reviews for facilities

 VAROA:5 A Operating Reactors Branch 1. 84/03/07 WILLIAM, J W Florida Power & Light Co App 22681 311 24X

 Fiche 50~000.84/03/07.8403190150
- 8403200264 Application to amend Licenses DPR-31 & DPR-61, changing Tech Specs to expand spent fuel storage facilities to accommodate expected increase in inventory of spent fuel assemblies above capacity of existing storage facility WILLIAMS. JW Florida Power & Light Co 84/03/14 EIGENHUT, D 0 Division of Licensing 3pp 22687 263 24X Fiche 50-250, 84/03/14, 8403200264
- --8403200266 Proposed Tech Specs, expanding spent fuel storage facilities * Florida Power & Light Co 84/03/14 17pp 22687 266 24X Fiche 50-250,84/03/14,8403200264
- --8403200270 "Spent Fuel Storage Facility Mod. SAR"

 # Florida Power & Light Co 84/03/14 106pp 22687 283 24X
 Fiche 50-250, 84/03/14, 8403200264
- 8403300288 Requests remittance of fee for review of 840210 rept summartizing available reactor vessel matts data in response to pressurized thermal shock concerns DIGGS.R M. License Fee Management Branch 84/03/15 UHRIG.R.E Florida Power & Light Co. (p. 22844 329 24X Fiche 30-250. 84/03/15.8403300288
- B403260203 Advises that proposed license amend re spent fuel storage expansion submitted on B40314 forwarded to state designee for State of FL. in accordance w/10CFR50 91(b)(1)
 WILLIAMS.J W Florida Power & Light Co B4/03/16 EISENHUT.D 0
 Division of Licensing ip 22756 207 24% Fiche 50~250, 84/03/16,
- @ Inspection reports, IE Bulletins & correspondence
- 8403020204 Forwards IE Insp Repts 30-250/83-43 & 50-251/83-42 on B31216 & notice of violation Notice of violation withheld (ref 100FR2 790/d) & 100FR2 731)
 LEWIS,R C Division of Project & Resident Programs 84/01/25, WILLIAMS,J W. Florids Power & Light Co 2pp 22440 094 24; Fiche 50-250,84/01/25,8403020204.

- --B403020241 IE Insp Repts 50~250/83-43 & 50-251/83-42 on 831216 Noncompliance noted employee circumvented security access control sys Details withheld (ref 100FRZ 790 & 100FRZ) 21 TILLMAN.A. BREMER.R Region 2. Office of Director MCOUIRE, D R Division of Emergency Preparedness & Materials Safety 84/01/20 1p 22440 096 24% Fiche 30-250.84/01/25,8403020204
- 8403160306 Forwards IE Insp Repts 50-250/84-02 & 50-251/84-02 on 840121-31 No violations or deviations noted DANCE:H C Division of Project & Resident Programs 84/02/21 WILLIAMS,J W Fiorida Power & Light Co 2pp 28660 145 24X Fiche 50-250.84/02/21.8403160306
- --8403160316 IE Insp Repts 50-250/84-02 & 50-251/84-02 on 840121-31 No violations or deviations noted Major areas inspected plant operations, surveillance testing & plant tours KRU0,HE Region 2. Office of Director JAPE,F Division of Engineering & Operational Programs 84/02/14 8pp 22660 147 24% Fiche 50-250,84/02/21,8403160306
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York. Inc 115pp 22709 239 24X Fiche 50-000.84/02/28, 8401190072
- 8403020285 Ack receipt of 840215 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-250/83-43 & 50-251/83-42 LEMIB.R C Division of Project & Resident Programs 84/02/29 HILLIAMS.J W Fiorida Power & Light Co ip 22440 069 24X Fiche 80-250.844002/29.84030020285
- --840302028B Responds to NRC 840125 ltr re violations noted in IE Safeguards Insp Repts 50-250/83-43 & 50-251/83-42 Corrective actions withheld (ref 10CFR2 790 & 73 21) WILLIAMS, J W Florida Power & Light Co. 84/02/15 O'REILLY, J P Region 2, Office of Director 1p 22440 070 24X Fiche 50-250,84/02/29,8403020285
- B403060291 Requests 1-month exemption from 10CFR50 55a(g)(5)(ii) schedular requirements re inservice insp Due to recent revs to code boundary drawings, add1 time to review & incorporate changes required
 WILLIAMS.J W Florida Power & Light Co 84/03/01 EISENHUT, D G Division of Licensing 2pp 22519 086 24X Fiche 50-250,84/03/01,8403060291
- 8403140300 Discusses util request to update requirements for sys pressure tests & extend existing 10-year insp interval due to lengthy steam generator repair outages Extension unacceptable Update of test requirements acceptable VAROA:B. A Operating Reactors Branch 1 84703/01. WILLIAMB, J. W Fiorida Power & Light Co 5pp 22635 318 24X Fiche 50-250.84/03/01.6403140300
- --8403140306 Exemption from requirements of pressure test to 1980 Edition through Winter 1981 ASME Code, Section XI Requests to extend insp intervals to 840901 unacceptable EIBENHUT, D 9 Division of Licensing 84/03/01 Florida Power & Light Co 4pp 22635 323 24X Fiche 50-250,84/03/01,8403140300
- B402070007 IE Info Notice B4-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Evc list encl ORACE.J N Division of QA. Safeguards & Inspection Programs (Post B30103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 327 24X Fiche 50-000,84/03/02,8402070007
- 8402070008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl. JORBAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830183) 84/03/02. Consolidated Edison Co. of New York, Inc. 122pp 22553 078 24X Fiche 50-000.84/03/02.8402070008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases"
 Svc list encl
 JORDAN, E. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc. 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- B402090011 IE Info Notice B4-17, "Problems W/Liquid Nitrogen Cooling Components Below Ni1 Ductility Temp " Svc list encl JURDAN: E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/03/05 Consolidated Edison Co of New York, Inc. 117pp 22553 336 24X Fiche 50-000.84/03/05.8402090011
- 8402070024 IE Info Notice 84-09. Rev i. "Lessons Learned From Insps of Fire Protection Safe Shutdown Bys." Svc list encl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07. Consolidated Edison Co. of New York Inc. 118pp 22635:049 24X Fiche 50-000,84/03/07,8402070024

- 8402090028 IE Info Notice 84-18, "Stress Corrasion Cracking in PWR 8ys " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8403290123 Forwards response to Action Item 4 requested by IE Bulletin 82-02 re maint procedures for threaded fasteners in RCPB Response to Action Item 3 previously provided in 820802 ltr WILLIAMB, J W Floride Power & Light Co 84/03/09 O'REILLY, J P Region 2, Office of Director 3pp 22807 189 24X Fiche 50-250,84/03/09,8403290123
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Bafety Bys " Svc list encl DEYDUNG, R C Director's Office, Office of Inspection and Enforcement B4/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24x Fichs 50-000,84/03/12,8402090031
- 8403290315 Summarizes 840309 meeting w/util to discuss performance enhancement program current events & outstanding regulatory issues Meeting beneficial & provided better understanding of util plans
 O'REILLY,J P Region 2, Office of Director 84/03/16
 HUDIBURG,J J Florida Power & Light Co 1p 22802 095 24X
 Fiche 50-230,84/03/16.8403270315
- 8403290097 Summarizes 840315 meeting w/util at Region II ofc reperformence enhancement program current events & outstanding regulatory issues
 O'RETLLY.J P Region 2, Office of Director 84/03/19 ADDMAT.E A Florida Power & Light Co ip 22806 349 24X Fiche 50-250, 84/03/19.8403290097
- 8403290192 Confirms IE mgt meeting on 840322 in Region II ofc to discuss proposed revs to plant performance enhancement program, per 840313 telcon LEWIS, R.C. Division of Project & Resident Programs 84/03/20 WILLIAMS. J.W. Florida Power & Light Co. ip 22803 313 24X Fiche 50-250,84/03/20,8403290192
- 8402070043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 227 24X Fiche 50-000,84/03/21,8402070043
- B402090044 IE Info Notice B4-20, "Svc Life of Relays in Safety-Related Bys "Svc list and JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post B30103) B4/03/21 Consolidated Edison Co. of New York, Inc. 135pp. 22933 001 24X Fiche 50-000,84/03/21,8402090044

R Periodic operating reports & related correspondence

- 8403020033 Monthly operating repts for Jan 1984 W/840215 ltr GRANT, N W., WILLIAMS, J. W. Florida Power & Light Co 84/01/31 19pp 22442 235 24X Fiche 50-000, 84/01/31, 8403020033
- B403300173 Forwards monthly operating repts for Feb 1984 & corrected Page 1 of Bt Lucie Unit 2 monthly operating rept for Jan 1984
 WILLIAMS, J W Florida Power & Light Co 84/03/15 Office of Resource Management, Director 1p 22819 263, 24X
 Fiche 50-000,84/03/15,8403300173
- --8403300185 Monthly operating repts for Feb 1984 GRANT, N. W. Florida Power & Light Co. 84/03/15 16pp 22819 264 24X Fiche 50-000, 84/03/15, 8403300173
- --8403300193 Corrected Page 1 of monthly operating rept for Jan 1984 GRANT.N W. Florida Power & Light Co 84/02/15 1p 22819 280 24X Fiche 50-000,84/03/15,8403300173

S. Reportable occurrences, LERs & related correspondence

- 8402270125 LER 84-004-00 on 840104, auxiliary feedwater sys periodic test initiated & pump A failed to develop required flow.

 Caused by misposition of manual governor speed control knob Knob reset to max position, W/840222 ltr.

 ARIAB, J., WILLIAMB, J W Florida Power & Light Co 84/02/22 4pp 22389, 243 24X Fiche 50-250, 84/02/22, 8402270125
- 8403020248 PNO-II-84-018 on 840227 units shut down following failure of Blemens-Allis breaker to trip during functional test of 4-kV electrical breakers for nonsafety-related electrical bus 3C. Insp & repair underway DANCE-H.C., LEWIS.R C. Region 2. Office of Director. 84/02/28, 2pp. 22440-101 24% Fiche 50-250.84/02/28.8403020248

- 8403160058 LER 84-006-00 on 840212 reactor tripped Caused by electrical relay malfunction resulting in loss of power to nonsefety-related 4160-volt bus Design review & complete testing of automatic turbine governor initiated M/840313 ltr ROACH, P.A., WILLIAMS, J.W. Florida Power & Light Co. 84/03/13 3pp 22652 323 24X Fiche 50-250.84/03/13.8403160058
- 8403220104 LER 84-007-00 on 840216, while at steady operation, dual unit trip occurred from 100% power, resulting in loss of 4, 160-volt buses 3C & 4C Caused by bolt in breaker 4ACO1 cubicle door travel Doors checked for proper clearance W/840319 1tr ARIABJ, WILLIAMSJ W Florida Power & Light Co 84/03/19 6pp 22715 279 24X Fiche 50-250, 84/03/19,8403220104

T Hearing transcripts on non-antitrust matters

8403020249 Transcript of 840228 prehearing conference in Homestead,FL Pp 1-84 * Atomic Safety and Licensing Board Panel 84/02/28 86pp 22440 107 24% Fiche 50-250,84/02/28,8403020249

V Operator Examinations

B40302027B Forwards list of requested dates for NRC site visits to conduct operator licensing exams as requested in Generic Ltr B3-40 WILLIAMB. J W Florida Power & Light Co B4/02/29 EISENHUT.D G Division of Licensing 3pp 22440 071 24X Fiche 50-250.84/02/29,8403020278

DOCKET 50-251 TURKEY POINT PLANT, UNIT 4

- F Security, medical, emergency & fire protection plans
- B4032B0ii0 Public version of Emergency Plan Implementing Procedures 20103, "Classification of Emergencies" & 20104, "Emergency Roster" W/840123 ltr & JM Felton B40322 release memo BAKER.C., WILLIAMS, J W Florida Power & Light Co 84/01/17 O'RETILLY, J P Region 2, Office of Director 3ipp 22811 329 24X Fiche 50-250,84/01/17.8403280110
- 8403020204 Forwards IE Insp Repts 50-250/83-43 & 50-251/83-42 on B31216 & notice of violation Notice of violation withheld (ref 10CFR2 790(d) & 10CFR73 21)
 LEWIS, R C Division of Project & Resident Programs 84/01/25 WILLIAMS. J W Florida Power & Light Co 2pp 22440 094 24X Fichs 50-250.84/01/25.8403020204
- ---B403020241 IE Insp Repts 50-250/83-43 & 50-251/B3-42 on B31216 Noncompliance noted employed circumvented security access control sys Details withheld (ref 10CFR2 790 & 10CFR3 21) TILLMAN.A Region 2, Office of Director B4/01/20 ip 22440 096 24X Fiche 50-250,84/01/25,8403020204
- B403060086 Approves state & local plans & preparedness for electing protecting public in event of radiological emergency Approval conditional on verification of elect & notification sys per criteria of App 3 of NUREG-0654/FEMA-REP-1. Nev 1.

 BPECK, S W Federal Emergency Management Agency 84/02/15
 DIRCKS, W J Office of the Executive Director for Operations 1p
 22516 300 24X Fiche 50-250,84/02/15,8403060086
- B403010173 Forwards order confirming licensee commitments to implement post-TMI related items per Suppl 1 to NUREO-0737 Schedular commitments reasonable, achievable & will provide timely upgrading of emergency response capability VAROA.S A Operating Reactors Branch 1 84/02/23. WILLIAMS, J J Florida Power & Light Co 4pp 22479 209 24X Fiche 50-230.84/02/23.8403010173.
- ~-B403010180 Order confirming licensee commitments to upgrade emergency response capability, per Suppl 1 to NUREO-0737 (Generic Ltr B2-33).
 EIBENHUT. D @ Division of Licensing 84/02/23 Florida Power & Light Co 6pp 22477 213 24X Fiche 30-250.84/02/23.8403010173
- 8403020285 Ack receipt of 840215 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 30-290/83-49 & 50-251/83-42 LEMIB.R C Division of Project & Resident Programs 84/02/29 WILLIAMS, J W Florida Power & Light Co ip 22440 069. 24% Fiche 50-250,84/02/29,8403020285
- --B403020288 Responds to NRC 840125 ltr re violations noted in IE Safeguards Insp Repts 50-250/83-43 & 50-251/83-42 Corrective actions withheld (ref 10CFR2,790 & 73 21) WILLIAMS, J W Florida Power & Light Co 84/02/15 O'REILLY, J P Region 2, Office of Director ip 22440 070 24X Fichs 50-250,84/02/27,8403020285

- 8403160254 Notifies of 840316 workshop to discuss 10CFR50.App R requirements & insp results to resolve misunderstandings refire protection Attenders should be limited to six due to size of conference room LEWIS.R C Division of Project & Resident Programs 84/03/02 WILLIAMS.J W Florida Power & Light Co ip 22660 255 24X Fiche 50-000.84/03/02.8403160254
- 8403190429 Forwards regulatory effectiveness review (RER) rept, possible solutions to RER concerns & observations & vital areas definition rept Encls withheld (ref 100FR73 21) VARGA:S A Operating Reactors Branch 1 84/03/06 WILLIAMS, J W Florida Power & Light Co 1p 22681 327 24% Fiche 50~250, 84/03/06.8403190429

G Adjudicatory correspondence

- 8403070135 Brisf on conflict posed by legal requirement of timeliness & equitable considerations ASLB should issue ruling allowing petitioners contentions that address new fuel core design, changes in Tech Specs & reduction in safety margins. HODDER, M H Center for Nuclear Responsibility 84/03/03 11pp 22538 245 24x Fiche 50-250,84/03/03,8403070135
- --8403070139 Motion for leave to file brief on conflict posed by legal requirements of timeliness & equitable considerations on 840303 instead of 840302 Certificate of Svc enc) HODDER, M H Center for Nuclear Responsibility 84/03/03 Atomic 8afety and Licensing Board Panel 2pp 22538 276 24X Fiche 50-250.84/03/03.8403070135
- --8403070143 Forwards applicant 830325 ltr w/encl re util pressurized thermal shock & flux reduction program per 840228 request W/o ltr HODDER, M H HODDER, M H Center for Nuclear Responsibility 84/03/03 Atomic Safety and Licensing Board Panel 7pp 22538 278 24X Fiche 50-250.84/03/03.8403070135
- 8403140017 Response to NRC & util responses to amended petition to intervene NRC guilty of conducting business lawlessly via repeated OL amends w/NSHC determination Certificate of Svc encl HDDDER: M H Center for Nuclear Responsibility HDDDER: M H Hodder: M H 84/03/07 Atomic Safety and Licensing Board Panel 20pp 22632 144 24% Fiche 50-230,84/03/07.8403140017
- --B40314D023 Motion for leave to file late, due to delays in typing & reproduction
 MODDER, M H Center for Nuclear Responsibility HODDER, M H
 Hodder, M H B4/03/07 Atomic Safety and Licensing Board Pane)
 3pp 22632 164 24X Fiche 50-250,84/03/07,8403140017
- B403130034 Order granting licenses motion for extension of time to 840314 for filing response to petitioner 840303 brief re consolidating consideration of two sets of license amends issued last yr LAZO.R M Atomic Safety and Licensing Board Panel 84/03/09 lp 22414 307 24% Fiche 90-250,84/03/09.8403130034
- 8403170062 Response to Ctr for Nuclean Responsibility & J Lorion 840303 brief on conflict posed by legal requirements of timeliness & equitable considerations ASLB should exclude any & all issues re 831209 Amends 92 & 98 Certificate of Svc encl MODDMEAD.C P Hearing Branch 4 84/03/14 12pp 22666 200 24X Fiche 50-250.84/03/14.8403170062
- B403190171 Response to petitioners 840303 brief re consolidating two sets of license amends issued in late 1983 in support of new fuel assemblies ASLB should confine proceeding to 841007 amends
 BAUSER, M.A. Florida Power & Light Co. BAUSER, M.A. Newman & Holtringer 84/03/14 Atomic 8afety and Licensing Board Panel 15pp 22670 265 24% Fiche 50-250.84/03/14.8403190171
- ---0403190179 Affidavit of DC Poteralski on petitioners 840303 brief re conflict posed by legal requirement of timeliness & equitable considerations Util 830720 amends not part of pressurised thermal shock program W/Certificats of 8vc POTERALSKI.D C Florida Power & Light Co 84/03/09 17pp 22670 280 24X Fiche 50-250.84/03/14.8403190171
- 8403270277 Forwards WL Outhrie 840228 ltr to be served on parties
 Copy should be placed in PDR
 LAZOR M Atomic Safety and Licensing Board Panel BSB 17B
 84/03/27 CLEMENTS WL Record Services Branch (Document Control
 DBB) 17 22801-336 24X Fichs, 50-250, 84/03/27, 8403270299
- ~-8403290304 Forwards file presented to Dade County Citirens Review
 Committee objecting to OL issuance
 GUTHRIE:N L Affiliation Not Assigned 84/02/28 Atomic Safety
 and Litensing Board Panel 57pp 22801 337 24X
 Fiche 50~250,84/03/27.8403290299

H General correspondence

- B403280149 Responds to B40208 ltr requesting assistance in responding to J Paskavitch ltr requesting latest EIS on concentrations of Sr-90.Cs-137 & I-i31 near plants Two annual repts encl W/o repts
 DIRCKS.W J Office of the Executive Director for Operations
 B4/03/07 CHILES.L Senate 4pp 22809 316 24X
 Fiche 50-000.84/03/07.8403280149
- --8403280156 Forwards constituent J Paskavitch ltr requesting latest EIS on concentrations of 8r-90. Cs-137 & 1-131 near plants
 Comments & views requested
 CHILESLL Senate 84/02/08 KAMMERER.C Office of Congressional
 Affairs 8pp 22809 320 24X Fiche 50-000,84/03/07,8403280149

J Insurance & indemnity information

- 8403060332 Forwards Endorsement 70 to NELIA Policy NF-185 DUCK.JR Marsh & McLennan, Inc. 84/02/28 SALTZMAN,J Assistant Director for State & Licensee Relations 2pp 22516 011 24X Fiche 50-290,84/02/28-8403060332
- P Operating license stage documents & correspondence
- 8403010160 Forwards Amends 101 & 95 to Licenses DPR-31 & DPR-41, respectively & safety evaluation Amends revise Tech Specs to add motor operated valves 863-A & 863-B to existing valves required to have power removed MCDONALD.D @ Operating Reactors Branch 1 84/02/22 WILLIAMS, J W Florida Power & Light Co 3pp 22477 232 24X Fiche 50-250.84/02/22.8403010160
- --8403010171 Amends 101 & 95 to Licenses DPR-31 & DPR-41, respectively, revising Tech Specs to add motor operated valves 863-A & 863-B to existing valves required to have power removed VARGA, S A Depending Reactors Branch 1 84/02/22 7pp 22479 235 24X Fiche 50-250.84/02/22,8403010160
- --B403010177 Safety evaluation supporting Amends 101 & 95 to Licenses DPR-31 & DPR-41, respectively * Office of Nuclear Reactor Regulation, Director 84/02/22 7pp 22479 242 24X Fiche 50-250,84/02/22,8403010160
- 8403020184 Requests identification of any potential problems or items that cannot be met within time frame required to meet Sept 1984 goal for completion of NUREG-0737 items VARGA.8 A Operating Reactors Branch 1 84/02/22 WILLIAMS, J Florida Power & Light Co 2pp 22475 005 24X Fiche 50-250.84/02/22,8403020184
- B40306016B Notifies that administrative program & procedures now in effect will be reviewed to confirm implementation of recommended guidelines in NUTAC rept.per Generic Ltr 83-28 MILLIAMS.JC Florida Power & Light Co 84/03/01 EISENNUT.D 0 Division of Licensing 1p 22518 336 24X Fiche 50-000,84/03/01,8403060168
- B4030B0020 Forwards integral neutron source data for evaluating & verifying flux reduction per B4517 request Data for Cycle 9 core octant time averaged relative power density.critical weld peaking factor & peripheral assembly pin power and HILLIAMS.J W Florida Power & Light Co 84/03/01 VAROA.S A Operating Reactors Branch 1 10pp 22559 229 24X Fiche 50-250.84/03/01.8403080020
- 8403170150 Notifies of 840402-06 meeting & preimplementation audit at Turkey Point to discuss confirmatory items identified in safety evaluation of detailed control room design reviews for facilities VARCA, S.A. Operating Reactors Branch 1 84/03/07 WILLIAM, J.W. Florida Power & Light Co. 6pp. 22681 311 24X Fiche 50-000.84/03/07.8403190150
- 8403200264 Application to amend Licenses DPR-31 & DPR-41 changing Tech Specs to expand spent fuel storage facilities to accommodate expected increase in inventory of spent fuel assemblies above capacity of existing storage facility WILLIAMS. J W Florida Power & Light Co 84/03/14 EISENHUT, D O Division of Licensing Spp 22687 263 24% Fiche 50-250,84/03/14,8403200264
- --8403200266 Proposed Tech Specs, expanding spent fuel storage facilities * Florida Power & Light Co 84/03/14 17pp 22687·266 24X Fiche 50-250, 84/03/14.8403200264
- --B403200270 "Spent Fuel Storage Facility Mod.SAR" a Florida Power & Light Co B4/03/14 106pp 22687 283 24X Fithe 50-250,84/03/14,8403200264

- 8403300288 Requests remittance of fee for review of 840210 rept summarizing available reactor vessel matls data in response to pressurized thermal shock concerns DIGGS.R M License Fee Management Branch 84/03/15 UHRIO.R E Florida Power & Light Co ip 22844 329 24X Fiche 50-250. 84/03/15.8403300288
- B403260203 Advises that proposed license amend re spent fuel storage expansion submitted on B40314 forwarded to state designee for State of FL.in accordance w/10CFR50 91(b)(1) HILLIAMS, J W Florida Power & Light Co B4/03/16 EJSENHUT, D C Division of Licensing 1p 22756 207 24% Fiche 50-250, B4/03/16, 8403260203
- O Inspection reports, IE Bulletins & Correspondence
- 8403020204 Forwards IE Insp Repts 50-250/83-43 & 50-251/83-42 on 831216 & notice of violation Notice of violation withheld (ref iQCFR2 790(d) & iOCFR23 21) LEWIB,R C Division of Project & Resident Programs 84/01/25 WILLIAMBOJ W Florida Power & Light Co 2pp 22440 094 24) Fiche 50-250.840/01/25.4403020204
- --8403020241 IE Insp Repts 50-250/83-43 & 50-251/83-42 on 831216
 Noncompliance noted employee circumvented security access
 control sys Betails withheld (ref 10CFR2 790 & 10CFR73 21)
 TILLMAN, A. BREWER, R. Region 2, Office of Director MCGUIRE, D. R. Division of Emergency Preparedness & Materials Safety 84/01/20
 ip 22440 096 24X Fiche 50-250,84/01/25,8403020204
- 8403160306 Forwards IE Insp Repts 50-250/84-02 & 50-251/84-02 on 840121-31 No viplations or deviations noted DANCE.H C Division of Project & Resident Programs 84/02/21 HILLIAMS.J W Florida Power & Light Co 2pp 22660 145 24) Fiche 50-250,84/02/21.8403160306
- --B403160316 IE Insp Repts 50-250/B4-02 & 50-251/B4-02 on B40121-31 No violations or deviations noted Major areas inspected plant operations, surveillance testing & plant tours KRUG, H E Region 2, Office of Director JAPE, F Division of Engineering & Operational Programs 84/02/14 Bpp 22660 147 24X Fiche 50-250,84/02/21,8403160306
- 8401190072 IE Info Notice 84-13. "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22709 239 24X Fiche 50-000.84/02/28,8401190072
- 8403020285 Ack receipt of 840215 ltr informing NRC of steps taken to correct violations noted in IE Bafeguards Insp Repts 30-280/83-43 & 50-281/83-42 LENIS,R C. Division of Project & Resident Programs 84/02/29 WILLIAMS,J W Florida Power & Light Co ip 22440 069 24X Fiche 50-250,84/02/29.8403020285
- --8403020288 Responds to NRC 840125 ltr re violations noted in IE Bafeguards Insp Repts 50-250/83-43 & 50-251/83-42 Corrective actions withheld (ref 10CFR2 790 & 73 21) WILLIAMS.J W Florida Power & Light Co 84/02/15 O'REILLY.J P Region 2, Office of Director 1p 22440 070 24X Fithe 50-250, 84/02/27, 8403020285
- 8403060291 Requests i-month exemption from iOCFR30 35a(g)(5)(ii) schedular requirements re inservice insp Due to recent revs to code boundary drawings, add1 time to review & incorporate changes required HILLIAMS.J W Florida Power & Light Co 84/03/01 EISENHUT, D G Division of Licensing 2pp 22519.086 24X Fiche 50-250.84/03/01.8403060291
- 8403140300 Discusses util request to update requirements for syspressure tests & extend existing 10-year insp interval due to lengthy steem generator repair outages Extension unacceptable Update of test requirements acceptable VARQA.S A Operating Reactors Branch 1 84/03/01 WILLIAMS.J W Florida Power & Light Co 5pp 22635 318 24X Fiche 50-250.84/03/01,8403140300
- --8403140306 Exemption from requirements of pressure test to 1980 Edition through Winter 1981 ASME Code Section XI Requests to extend insp intervals to 840901 unacceptable. EIBENNUT.D.Q Division of Licensing 84/03/01 Florida Power & Light Co 4pp 22635 323 24X Fiche 50-250,84/03/01,8403140300
- B402090007 IE Info Notice B4-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Bvc list encl GRACE.J N. Division of GA. Safeguards & Inspection Programs (Post B30103) B403/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000,84/03/02,8402090007.

- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate" Svc list encl JORDAN: EL Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/02 Consolidated Edison Co of Naw York: Inc 122pp 22553 09B 24X Fiche 50-000.84/03/02,8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases "
 Svc list encl
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Fost 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc 119pp 22553 217 24X Fiche 50-000,84/03/02,8402070009
- 8402090D11 IE Info Notice 84-i7, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 630103) 84/03/05 Consolidated Edison Co. of New York, Inc. 117pp 22553 336 24X Fiche 50-000.84/03/08.8402090011
- 8402090024 IE Info Notice 84-09, Rev 1, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24% Fiche 50-000.84/03/07.8402090024
- 8402070028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Bys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 80103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24% Fiche 50-000,84/03/07,8402070028
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Bys " Byc list encl DEYGUNG.R C Director's Office. Office of Inspection and Enforcement B4/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24% Fiche 50-000.84/03/12.8402090031
- 8403290315 Summarizes 840309 meeting w/util to discuss performance enhancement program current events & outstanding regulatory issues Meeting beneficial & provided better understanding of util plans
 O'REILLY, J P Region 2. Office of Director B4/03/16
 HUDIBURG, J J Florida Power & Light Co ip 22802 095 24y
 Fiche 50-250,84/03/16,8403290315
- 8403290097 Summarizes 840315 meeting w/util at Region II ofc reperformance enhancement program.current events & outstanding regulatory issues
 O'REILLY, J.P. Region 2, Office of Director 84/03/19 ADDMAT, E.A. Florida Power & Light Co. 1p. 22806 349 24% Fiche 50-250.
 84/03/19.8403290097
- B403290192 Confirms IE mgt meeting on 840322 in Region II ofc to discuss proposed revs to plant performance enhancement program.per 840313 telcon
 LEWIS,R C Division of Project & Resident Programs 84/03/20
 WILLIAMS.J W Florida Power & Light Co 1p 22803 313 24X
 Ficha 30-250.84/03/20.8403290192
- 8402090043 IE Info Natice 84-19. "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Cansolidated Edison Co. of New York, Inc. 123pp. 22823 229 24X Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Bys " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 2293 001 24X Fiche 50-000.84/03/21.8402090044
- R Periodic operating reports & related correspondence
- B403020033 Monthly operating repts for Jan 1984 W/840215 1tr GRANT.N W : WILLIAMS.J W Florida Power & Light Co B4/01/31 19pp 22442 235 24X Fiche 50-000.84/01/31.8403020033
- B403300173 Forwards monthly operating repts for Feb 1984 & corrected Page 1 of St Lucie Unit 2 monthly operating rept for Jan 1984
 WILLIAMS, J.W. Florida Power & Light Co. 84/03/15 Office of Resource Management, Director 1p 22819 263 24X
 Fiche 50-000.88/03/15.8403300173
- --8403300185 Monthly operating repts for Feb 1984 GRANT.N W Florida Fower k Light Co 84/03/15 16pp 22819 264 24X Fiche 50-000,84/03/15.8403300173

- 5 Reportable occurrences. LERs & related correspondence
- 8403020248 PNO-II-84-018 on 840227, units shut down following failure of Siemons-Allis breaker to trip during functional test of 4-kV electrical breakers for nonsafety-related electrical bus 3C insp & repair underway
 DANCE, H C . LEWIS, R C Region 2. Office of Director 84/02/28
 2pp 22440 101 24X Fithe 50-250.84/02/28,8403020248
- 8403160038 LER 84-001-00 on 840212, reactor tripped Caused by electrical synchronism-check relay malfunction Design reviewed & automatic turbine governor runback logic circuitty tested satisfactorily W/840313 ltr RDACH.P A. WILLIAMS.J W Florida Power & Light Co 84/03/13 3pp 22655 136 24X Fiche 50-251.84/03/13.8403160038
- 8403160067 LER B4-002-00 on 840212 reactor trip occurred due to steam flow greater than feed flow coincident Caused by high steam flow reading on steam generator 4A Calibr check performed H/840313 ltr ARIAS.J. HILLIAMS.J W Florida Power & Light Co 84/03/13 3pp 22655 086 24% Fiche 50-251.84/03/13,8403160069
- T Hearing transcripts on non-antitrust matters
- 8403020249 Transcript of 840228 prehearing conference in Homestead.FL Pp 1-84 * Atomic Bafety and Licensing Board Panel 84/02/28 86pp 22440 107 24X Fiche 50-250,84/02/28.8403020249
- V Operator Examinations
- 8403020278 Forwards list of requested dates for NRC site visits to conduct operator licensing exams as requested in Generic Ltr 83-40 Williams, J W Florida Power & Light Co 84/02/29 EISENHUT, D G Division of Licensing 3pp 22440 071 24X Fiche 50-250, 84/02/27, 8403020278
- DOCKET 90-254 QUAD CITIES STATION. UNIT 1
- F Socurity, medical, emergency & fire protection plans
- 8403090294 Public version of revised emergency plan implementing procedures, including Procedures GEP 110-0 re station director & GEP 110-2 re acting station directory (shift engineer) WJM Felton release mano KOVAK, T.J., TIETZ, G., GERNER, L. Communuselth Edison Co. 89/11/03 43pp 22592 017 24X Fithe 50-254.83/11/03,8403090294
- B403040063 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee.per B10709 Generic Ltr B1-27 W/o request, entire plan will be placed in FDR VASSALLO.D B Operating Reactors Branch 2 84/02/10 FARRAR D L. Commonwealth Edison Co 2pp 22528 303 24X Fiche 50-234.84/02/10.8403040063
- 8403130155 Advises that state & local plans & preparedness for radiological amergencies adequate Approval conditional on FEMA verification of adequacy of alerting & notification system App 3 of Nev 1 to NUREO-0654/FEMA-REP-1 SPECK, 8 W Federal Emergency Hanagement Agency 84/03/02 DIRCKS, W J Office of the Executive Director for Operations 2pp 22608 227 24X Fiche 50-234,84/03/02.8403130155
- 8403120149 Notifies of 840323 regional workshop in Rosemont, IL w/all Region III licensees to discuss fire protection safe shutdown requirements Morkshop will provide addl guidance re 10CFR30, App R requirements Agenda encl SPESBARD, R L Division of Emergency Preparedness & Operational Support 84/03/06 RED, C Commonwealth Edison Co 3pp 22584 182 24X Fiche 50-234,84/03/06.8403120149
- P Operating license stage documents & correspondence
- 8403010087 Application to amend License DPR-27, changing Tech Specs re MAPLHOR curves for certain fuel types
 RYGAX,8 Commonwealth Edison Co. 84/02/21 DENTON,H R. Office of Nuclear Reactor Regulation. Director 2pp 22436
- --8403010073 Proposed changes to Tech Spec Figure 3 5-1, revising MAPLHGR curves
 # Commonwealth Edison Co 84/02/21 18pp 22436 080 24X
 Fiche 50-254,84/02/21,8403010089

- B403140340 Summary of B31215 meeting w/GE & Mark I Dwners Group in Bethesda.MD re Mark I containment wetwell-drywell vacuum breaker design methodology SIEGEL.B L. Operating Reactors Branch 2 84/02/21 Operating Reactors Branch 2 51pp 22635 198 24X Fiche 50-000, 84/02/21, 8403140340
- 8403060273 Application for amend to License DPR-29, changing Tech Spec Pages 3 1/4 1-B,-9,-10,-12,-13,-14,-2,-2a,-3,-7, 3 2/4 2-14 % 3 3/4 3-3 re scram discharge vol sys mods Class III fee encl RVBAK.8 Commonwealth Edison Co 84/02/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22517 050 24X Fiche 50-254, 89/02/28, 8403060273
- --8403060279 Proposed changes to Tech Spec Pages 3 1/4 1-8,-9,-10,-12,-13,-14,-2,-2a,-3,-7,3 2/4 2-14 & 3 3/4 3-3 re scram discharge vol sys mods * Commonwealth Edison Co 84/02/28 14pp 22517 052 24X Fiche 50-254,84/02/28,8403060273
- B403050119 Forwards supplemental response to Generic Ltr B3-2B,
 "Required Actions Dased on Generic Implications of Salem
 ATMS Events"

 BARNES,P L Commonwealth Edison Co 84/02/29 DENTON.H R Office
 of Nuclear Reactor Regulation, Director 26pp 22488 084 24X
 Fisho 30-000.B4/02/29, 8403050119
- 8403130353 Documents present resolution of SER open items & deficiencies noted in Franklin Research Ctr technical evaluation rept re environ qualification of safety-related electrical equipment

 RYBAK.B Commonwealth Edison Co 84/02/29 DENTON.H R Office of Nuclear Reactor Regulation. Director 40pp R2617 OBO 24X

 Fiche 50-234.84/02/29.8403130353
- B403130400 Forwards 840210 responses to Generic Ltr 83-35 clarifying TMI Item II K 3 31 Util concurs W/NRC position Item should be closed RYBAK, B Commonwealth Edison Co 84/03/02 RISENHUT, D 9 Division of Licensing 2pp 22613 143 24X Fiche 50-000, 84/03/02,
- B403150275 Generic Ltr B4-07 to all licensess of BWRs re procedural guidance for pipe replacement at BWRs Svc list encl EIBENHUT.D G Division of Licensing 84/03/14 Commonwealth Edison Co 20pp 22823 354 24% Fische 50-000,84/03/14,8403150275
- B403270130 Application for amend to License DPR-25 changing Tech Specs to extend certain MAPLHGR curves to 40.000 MHd/8T RYBAK.B Commonwealth Edison Co B4/03/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22774 129 24X Fiche 50-000.84/03/19.8403270130
- ~-8403270136 Errata & Addenda Sheet 9, replacing Page 4-14 to "LOCA Analysis Rept for Dresden Units 2 & 3 & Quad Cities 1 & 2 Nuclear Power Stations" * General Electric Co NEDU-24146A ERR 09 83/01/31 2pp 22774 135 24X Fiche 30-000.84/03/19,8403270130
- @ Inspection reports: IE Bulletins & correspondence
- B403120134 Forwards IE Insp Repts 50-237/84-01.50-249/84-01. 50-254/84-01.50-248/84-01.50-295/84-01 & 50-304/84-01 on 840203-14 No noncompliance identified SHAFER, U D Region 3. Office of Director 84/02/23 REED, C Commonwealth Edison Co 2pp 22590 090 24X Fichs 50-000.84/02/23.
- --8403120137 IE Insp Repts 50-237/84-01.50-249/84-01.50-254/84-01.
 50-265/84-01.50-295/84-01 & 50-304/84-01 on 840203-14. No noncompliance or deviations identified Major areas inspected allogations of improper operation CHRISSOTIMOS.N. TONOUE.T. HOLZMER.M. Region 3. Office of Director 84/02/21 App 22590 092 24X Fichs 50-000.84/02/23.8403120134
- 8403050002 Submits brief outline of regulatory improvement program Program implements basic changes in practices & structure of operation Summary of corrective actions taken in response to control rod insertion error encl
 THOMAS: B. Commonwealth Edison Co. 84/02/24 KEPPLER, J. G. Region
 3, Office of Director lipp 22470 226 24X Fiche 50-254,84/02/24,8403050002
- 8403050043 Forwards Rev O to "Corporate Regulatory Performance Improvement Plan " Plan designed to Aeighten employee awareness & strengthen corporate ability to improve regulatory performance THOMAS.B Commonwealth Edison Co 84/02/24 KEPPLER.J G Region 3. Office of Director 3pp 22470 137 24X Fiche 50-000,84/02/24.8403050043

- --8403050046 Rev Q to "Corporate Regulatory Performance Improvement
 - Plan "
 * Commonwealth Edison Co 84/02/29 22pp 22490 142 24X
 Fiche 30-000,84/02/24,8403050043
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Mator Operated Valve Control Circuits & Annunciation " Svc list
 - encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22909 239 24X Fiche 30-000.84/02/28,8401190072
- 8403050072 Forwards addendum to IE Insp Repts 50-254/83-21 & 50-265/83-19, comparing beta analyses of liquid sample split & gross beta results of spiked liquid sample Info will close Open Items 50-254/83-21-02 & 50-265/83-19-01 PAPERIELLO,C J Region 3, Office of Director 84/02/29 REED,C Commonwealth Edison Co ip 22490 014 24X Fiche 50-254,84/02/29,84030072
- --8403050074 Addendum to IE Insp Repts 50-254/83-21 & 50-245/83-19 re comparative beta analysis results of liquid sample split & gross beta results of spiked liquid sample * Region 3, Office of Director 84/02/29 ip 22470 015 24X Fichs 50-254,84/02/29,8403050072
- 8403190207 Forwards IE Insp Repts 50-254/83-24 & 50-265/83-23 on 830804-840202, No noncompliance identified LITTLE, W 8 Region 3, Office of Director 84/03/01 REED, C Commonwealth Edison Co 2pp 22671 072 24X Fiche 50-254,84/03/01,84033007
- --8403190208 IE Insp Repts 50-254/83-24 & 50-265/83-23 on 830804-840202 No noncompliance or deviations identified Major areas inspected review of inservice inspreactor water cleanup sys piping. IE bulletins & LERs CILIMBERO,R L , DANIELSON,D H , WARD,K D Region 3, Office of Director 84/03/01 26pp 22671 074 24X Fiche 50-284,84/03/01, 8403190207
- B402070007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE.J N Division of GA. Bafeguards & Inspection Programs (Post B30103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000,84/03/02,8402090007
- 8402070008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Bys Valves to Operate " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 122pp 22553 098 24X Fiche 50-000,84/03/02,8402070008
- 8402070007 IE info Notice 84-15, "Reporting of Radiological Releases" 8vc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc. 117pp 22553 217 24X Fiche 50-000,84/03/02,8402070007
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Evc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000.84/03/05.8402090011
- 8402090024 IE Info Notice 84-09, Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown 8gs " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000,84/03/07,8402090024
- B40209002B IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Sys " Syc list encl. JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24% Fiche 50-000,84/03/07,8402090028
- B403190075 Requests B01002 & B10107 confirmatory orders on IE Bullatin B0-17 re stram distherge mods be restinded & actions no longer applicable be removed &/or deleted RYBAK.B Commonwealth Edison Co 84/03/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 22669 358 24X Fiche 30-234,84/03/07.8403190075
- 8402070031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list enc! DEYCUNG.R C Director's Office, Office of Inspection and Enforcement B4/03/12 Consolidated Edison Co of New York, Inc 134pp R2823 074 24X Fiche 50-000.84/03/12,8402070031

- B403270175 Submits plan for insp & repair of intergranular stress corrosion cracking indications in stainless steel piping in drywell during refueling outage initiated on 840306 RYBAK. B Commonwealth Edison Co B4/03/19 DENTON, H R Office o Nuclear Reactor Regulation. Director 4pp 22771 133 24X Fiche 50-254,84/03/19,8403270175
- 8403230088 Ack receipt of regulatory performance improvement plan Periodic meetings requested to discuss progress on program & provide feedback KEPPLER.J G Region 3. Office of Director 84/03/20 THOMAS.B Commonwealth Edison Co ip 22730 141 24X Fiche 50-000.84/03/20. 8403230088
- --8403230107 Forwards corporate regulatory performance improvement plan THOMAS.8 Commonwealth Edison Co. 84/02/24 KEPPLER, J.O. Region 3, Office of Director 3pp 22730 162 24X Fiche 50-000, 84/03/20, 840230088
- --8403230126 Rev O to "Corporate Regulatory Performance Improvement Plan For Dresden, Quad Cities, Zion & LaSalle Operating Nuclear Stations & Byron & Braidwood Project Operating Organizations " * Commonwealth Edison Co 84/02/29 22pp 22730 165 24X Fiche 50-000, 84/03/20, 8403230088
- 8403260196 Forwards responses to IE Bulletin 83-07. "Apparently Fraudulent Products Sold by Ray Miller. Inc." Quad Cities supplied w/piping matls from Ray Miller. Inc during const Evaluation encl Concerns of IE Bulletin 83-06 satisfied BARNES.P L Commonwealth Edison Co. 84/03/20 KEPPLER.J.O. Region 3, Office of Director 19pp. 22796 185 24X Fiche 50-000.84/03/20.8403260196
- 8402090043 IE Info Notice 84-i9, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 123pp 22823 229 24X Fiche 50-000,84/03/21,8402090043
- B402090044 IE Info Notice 84-20, "Svr Life of Relays in Safety-Related Sys " Svr list and " JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 135pp 22733 001 24X Fiche 50-000,84/03/21,8402090044
- R Periodic operating reports & related correspondence
- B403080197 "Rept of Occupational Personnel Radiation Doses.1983 " W/840227 itr SCOTT.J S Commonwealth Edison Co 83/12/31 13pp 22559 099 24X Fiche 50-000.83/12/31.8403080197
- 8403220120 Annual whole body external exposures for 1983 W/840316 ltr RYBAK, B Commonwealth Edison Co 83/12/31 7pp 22/16 007 24X Fiche 50-000,83/12/31,8403220120
- 8403060113 Forwards Rev 1 to "Effluent & Waste Disposal Bemiannual Rept Jul-Dec 1982 " Errata for "Liquid Alpha Radioactivity, Jan-Jul 1983" & "Bolid Radwaste Summary, Jul-Dec 1983, " also encl KALIVIANAKIS, N Commonwealth Edison Co 84/02/07 KEPPLER, J 9 Region 3. Office of Director 1p 22518 252 24X Fiche 50-254, 84/02/07, 8403060113
- --B403060117 Rev 1 to "Effluent & Waste Disposal Semiannual Rept Jul-Dec 1982 " * Commonwealth Edison Co B3/05/31 7pp 22518 253 24X Fiche 30-254, B4/02/07, B403060113
- --8403040121 Errata for "Liquid Alpha Radioactivity Jan-Juns 1983" * Commonwealth Edison Co 83706/30 ip 28518 260 24X Fiche 50-254,84/02/07.8403060113
- 8403130382 Monthly operating repts for Feb 1984 W/B40308 ltr MIBAK.A , KALIVIANAKIS.N Commonwealth Edison Co 84/02/29 24pp 22616 295 24X Fiche 50-254.84/02/29.8403130382
- 8403150019 Listing of changes, tests & experiments completed during Feb 1984 Summary of safety evaluation reported per 10CFR50 59 enc. W/840308 ltr KALIVIANAKIS.N Commonwealth Edison Co 84/02/29 CASE.E 0 Defice of Nuclear Reactor Regulation. Director 3pp 22644 360 24X Fiche 50-254,84/02/29,8403150019

S Reportable occurrences, LERs & related correspondence

- 8403070256 Followup Part 21 rept re defective mechanical snubber capstan springs supplied by Pacific Scientific Affected utils listed Purchasers have been notified & advised to work directly w/Pacific Scientific in disposition KOVI.t. NP5 Industries. Inc 84/02/24 DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 2pp 22536 279 24X Fiche 50-000.84/02/24.8403070256
- 8403080011 Forwards response to Commissioner Gilinsky request for info on frequency of personnel errors at selected operating plants Summary of tabulated events re operator errors, personnel errors or procedural errors provided for CY83 DIRCKS.H J Office of the Executive Director for Operations 84/02/24 PALADING, GILINSKY, ROBERTS Commissioners 17pp 22584 142 24X Fiche 50-000,84/02/24,8403080011.
- 8403130235 PNO-111-84-023 on 840305 HPCI sys declared inogerable when surveillance test revealed ascessive leakage on main pump outboard bearing During test of automatic degressurization sys, electromatic relief valve E failed to open CHRISSOTIMSS N. SHAFER, W. Region 3, Diffice of Director 84/03/06 ip 22617 278 24x Fiche 50-254,84/03/04,8403130235

DOCKET 50-255 PALIBADES NUCLEAR PLANT

F Security, medical, emergency & fire protection plans

- 84030i0351 Summary of 840209 meeting w/util.Sciente Applications.Inc. MPR Assoc & MIT re NRC comments on detailed control room design review program plan, per requirements of Suppl 1 to NUREG-0737 Viewgraphs encl PAULSON.W A Operating Reactors Branch 5 84/02/29 Operating Reactors Branch 5 84/02/29, 84/02/
- 8403120115 Notifies of 840323 workshop on fire protection safe shutdown requirements of 10CFR50, App R in Rosemont, IL to discuss IE Info Notice 84-09 & provide addi shutdown analyses 8/or mod guidance Agenda entl
 SPESSARD, R L Division of Emergency Preparedness Coperational Support 84/03/04 DEMITT, R B Consumers Power Co 3pp 22588 235 24% Fiche 50~255.84/03/04,8403120115

I Financial information

- 8403190071 Annual Financial Rept for 1983 W/840312 ltr SELBY, J D . FOLAHER, J B . PERRY, P A Consumers Power Co 83/12/31 GIAMBUSSO. A Division of Licensing 34pp 22666 136 24X Fiche 50-000, 83/12/31.8403190071
- P Operating license stage documents & correspondence
- 8403010368 Forwards Amend 79 to License DPR-20 & safety evaluation Amend deletes capsule A-60 from reactor vessel surveillance capsule program & modifies coupon removal schedule PAULSON,W A Operating Reactors Branch 5 84/02/28 VANDEWALLE,D J Consumers Fower Co 2pp 22403 080 24X Fiche 50-255,84/02/28,8403010368
- --8403010372 Amend 79 to License DPR-20, deleting capsule A-60 from reactor vessel surveillance capsule program & modifying coupan removal schedule to provide option of removing equivalent capsule instead of primary capsule CRUTCHFIELD, D Operating Reactors Branch 5 84/02/28 4pp 22433 082 24X Fiche 50-255,84/02/28 8403010368
- --8403010373 Safety evaluation supporting Amend 79 to License DPR-20 * Office of Nuclear Reactor Regulation, Director 84/02/28 3pt 22433 086 24X Fiche 50-255,84/02/28,8403010368
- 8403220078 Advises that issue of justifying unlimited or limited use of purge sys during normal operations will not be pursued Sys will operate only during cold shutdown Tech Spec mod expected by 840420 Resubmitted due to error in original JGHN9DN.8 D Consumers Power Co 84/03/01 CRUTCHFIELD.D. Operating Reactors Branch 5 ip 22712 313 24X Fiche 50-255,84/03/01,8403220078
- B403080232 Summary of B40307 meeting w/util,NDE Technology, Westinghouse, Bechtel.C-E. Engineering Planning & Mgt & Newman & Holtzinger in Bethesda, MD re NDE program for steam generator tubes
 PAULSON.W A Operating Reactors Branch 5 84/03/07 Operating Reactors Branch 5 116pp 22561 034 24X Fiche 50-255,84/03/07.

- 8403090210 Advises that util 840220 proposed variance for high-range stack gas munitors unacceptable Sys should be modified to meet display guidance of NUREG-0737. Item II F i(1), "Addl Accident Monitoring Instrumentation "CRUTCHFIELD.D Operating Reactors Branch 5 84/03/07 VANDEMALLE, D J Consumers Power Co Spp 22574 358 24X Fichs 50-000.84/03/07.8403090210
- 8403150145 Ack receipt of NRC 840123 request for info re post-accident sampling sys (TMI Item II B 3) Plant-specific core damage estimate procedure & info demonstrating equipment operability & operator training will be provided by 840515 JUNNSON. N D Consumers Power Co 84/03/12 CRUTCHFIELD. D Operating Reactors Branch 5 1p 22639 362 24X Fiche 50-255.84/03/12.8403150145
- 8403230093 Application for Timend to License DPR-20, consisting of proposed Tech Spec change request to revise accident & transient analyses due to steam generator tube plugging Class III amend fee encl Heatup scheduled for 840908 JOHNSON, B D Consumers Power Co 84/03/16 CRUTCHFIELD, D Operating Reactors Branch 5 18pp 22731 099 24X Fiche 50-255,84/03/16,8403230093
- --8403230098 Proposed pages to Tech Bpsc change request, revising accident & transient analyses due to steam generator tube plugging # Consumers Power Co 84/03/16 3ipp 22731 117 24X Fiche 50-255,84/03/16.8403230093
- --8403230102 "Palisades Cycle & Setpoint Verification W/50% Steam Generator Tube Plugging "
 LINDGUIST, T R , NUTT, W T Exxon Nuclear Co , Inc (subs of Exxon Corp) XN-MF-84-14 84/03/07 43pp 22731 158 24X Fichs 50-255,84/03/16,8403230093
- --B403230106 "Plant Transient Analysis for Palisades Nuclear Power Plant W/50X Steam Generator Plugging"
 LINDGUIST.T R. NUTT, W T Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) XN-NF-84-18 84/03/09 150pp 22731 202 24X Fiche. 50-255, 84/03/16, 8403230093
- ---B403230111 "Palisades LOCA-ECCB Analysis for 2125 MWt Operation & 50% Steam Generator Tube Plugging."

 TANVILL.T Exxon Nuclear Co , Inc (subs of Exxon Corp)

 XN-NF-B4-24 84/03/09, 54pp 22731 353 24%

 Fiche 50-255,84/03/16.8403230093
- 8403260113 Requests extension to respond to Generic Ltr B3-28 to reflect extension of current refueling outage Work necessary to address remaining issues will commence 60 days after end of current refueling outage VANDEWALLE.D J Consumers Power Co 84/03/22 EISENHUT, D G Division of Licensing 2pp 22750 361, 24X Fiche 50-255,84/03/22,840326015
- 8403270166 Notification of 840405-06 meetings w/util in Van Buren County, MI to discuss proposed radiological effluent Tech Bpecs PAULSON: WA Operating Reactors Branch 5 84/03/23 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 22774 147. 24X Fiche 50-255.84/03/23.84003270166
- 8409300064 Notification of 840410 meeting u/util in Bethesda, MD to discuss steam generator repair PAULBON.N A Operating Reactors Branch 5 84/03/28 CRUTCHFIELD, D Operating Reactors Branch 5 4pp 22822 106 24X Fichs. 50-255

Q Inspection reports, IE Bulletins & correspondence

- 8403050223 Further response to FOIA request for records of named individuals, including repts, analyses, studies, test calculations, procedures & practices for measurement of RC8 lesiage Forwards App C documents Search continuing FELTON, J M Division of Rules and Records 84/02/07, MADDEN, T J. Kaye. 8choler, Flerman, Hays & Handler 3pp 22476-234 24X Fichs 50-000,84/02/07,8403050223.
- --B403050286 Notifies that independent measurements of identified & unidentified RCB leak rates for all PWRs in Region III performed per Procedures 617278 & 617288 Insp findings summarized.

 NORELIUS.C E Division of Engineering 82/03/08 JORDAN.E L Division of Engineering & Quality Assurance (Pre 830103) 2pp 22476 270 24X Fiche 50-000.84/02/07.8403050223
- 840ii90072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc 11st enc!

 JRROAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/28 Consolidated Edison Co of New York, Inc. 115pp. 22909 239 24X Fiche 50-000.84/02/28.8401190072

- 8403120131 Responds to IE Bulletin 83-07. "Apparently Fraudulent Products Sold by Ray Miller. Inc " Purchase order records for 1975-79 reviewed & 14 suspect purchase orders found No matis supplied on orders purchased from Ray Miller. Inc JOHNSON. 8 D Consumers Power Co 84/03/01 KEPPLER. J G Region 3. Office of Director 2pp 22588 238 24X Fiche 50-000.84/03/01. 8403120131
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE.J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fichs 50-000,84/03/02,8402090007
- 8402090008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN:E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 122pp 22553 098 24X Fichs 50-000,84/03/02,8402070008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8402070011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JURDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000.84/03/05,8402070011
- 8403070300 Responds to IE Bulletin 83-08. "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Subj circuit breakers not installed in safety-related sys WANDEWALLE, D J Consumers Power Co 84/03/03 KEPPLER, J Q Region 3, Office of Director 2pp 22546 360 24X Fiche 50-255.84/03/05, 8403070300
- 8402090024 IE Info Notice 84-09, Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22635 049 24X Fiche 50-000, 84/03/07, 8402090024
- 8402070028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Sys." Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc. 118pp 22584 186 24X Fiche 50-000,84/03/07,8402070028
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Bys " Svc list encl DEVOUNG, R C Director's Office, Office of Inspection and Enforcement \$4/03/12 Consolidated Edison Co of New York
- 8402090043 IE Info Notice 84-19. "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000,84/03/21,8402090043
- B402090044 IE Info Notice B4-20. "Svc Life of Relays in Safety-Related Bys." Bvc list encl
 JURDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) 84/03/21 Consolidated Edison Co of New
 York, Inc 135pp 22933 001 R4X Fiche 50-000,84/03/21,8402090044
- R Periodic operating reports & related correspondence
- 8403080184 "1983 Annual Operating Rept Occupational Exposure " W/ 840227 ltr JOHNBON.B D Consumers Power Co 83/12/31 KEPPLER, J Q Region 3, Office of Director 4pp 22557 202 24X Fiche 50-255,83/12/31,8403080184
- 8403080206 "Radigactive Effluent & Waste Disposal Semiannual Rept Jul-Dec 1983 " W/840229 ltr JUHNBON, B D Consumers Power Co 83/12/31 KEPPLER, J 9 Region 3, Office of Director 11pp 22360:008 24X Fiche 50-235,83/12/31, 8403080206
- 8403120041 "1983 10CFR50 49 Annuel Rept " W/840229 itr JUNNSON, B D Consumers Power Co 83/12/31 KEPPLER. J Q Region 3. Office of Director 5pp 22589 274 24% Fiche 50-255,83/12/31, 8403120041

- 8403120140 Monthly operating rept for Feb 1984 H/B40307 ltr CAVADAS.K J , VANDENBERG.D Consumers Power Co 84/02/29 5pp 22585 245 24X Fiche 50-255.84/02/29.8403120140
- S Reportable occurrences, LERs & related correspondence
- 8302020107 Forwards technical review rept. "Diesel Generator Load Sequencer Design Deficiency - LER 82-025/01T " CHIRAMAL.M Reactor Operations Analysis Branch 83/01/19 8EYFRIT.K V Reactor Operations Analysis Branch 1p 22808 306 24X Fiche 50-255.83/01/19.8302020109
- ---8403270350 "Diesel Generator Load Sequencer Design Deficiency LER 82-025/017." technical review rept * Reactor Operations Analysis Branch 83/01/19 3pp 22808 307 24% Fichs 50-255.83/01/19.8302020109
- 8403170101 Part 21 rept re apparent design deficiency in Siemens Allis Model MA-2058 stored energy circuit breaker. Breaker insp & hold down device orientation will be complete by 840401 Determination of permanent fix & implementation by 840401 JOHNSON, B D , VANDEWALLE, D J Consumers Power Co 84/02/27 KEPPLER, J G Region 3, Office of Director 5pp 22669 305 24X Fiche 50-255,84/02/27,8403190101
- 8403170091 PNO-III-84-026 on 840313 during insp to verify support plate integrity after tube-pulling activities damage observed to auxiliary feedwater sparger piping in both steam generators Damage may delay May 1984 startup DEFAVETTE.R. 10070.D Region 3. Office of Director 84/03/13 1p 22669 227 24X Fiche 50-255.84/03/13.8403190091
- B403230023 PND-III-84-027 on 840318, diver working on fuel assembly upender received radiation dose to right thigh of 4 5 rams Caused by licensee failure to identify localized high radiation field near upender QREGER, L R . PAPERIELLO. C Region 3. Dffice of Director 84/03/19 p 22726 318 24X Fiche 50-255,84/03/19,8403230023
- DOCKET 50-259 BROWNS FERRY NUCLEAR POWER STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8403060238 Emergency plan implementing procedures, including IP-2 re notification of unusual event. IP-3 re alert. IP-4 re site emergency & IP-6 re radiological emergency plan. activation at support ctr W/840228 ltr & list of effective pages MILLB.L M Tennessee Valley Authority 84/02/10 O'REILLY.J P Region 2. Office of Director 32pp 22516 098 24X Fichs 50-259.84/02/10.8403060238
- 8403060571 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee, per Bi0709 Generic Ltr Bi-27 W/o request, entire plan will be placed in FDR VABBALLO, D B Operating Reactors Branch 2 84/02/10 PARRIB, H G Tennessee Valley Authority 2pp 22552 261 24% Fiche 50-259.84/02/10.8403060571
- B403040235 Rev 5 to Procedure IP-9, "Muscle Shoals Emergency Ctr Implementing Procedures Document " W/B40213 ltr MAXWELL.R., SLIGER, E K Tennessee Valley Authority B4/02/13 63pp 22518 023 24X Fithe 50-000,84/02/13,8403060235
- 84030&0147 Forwards revised effective pages to Knoxville Emergency Ctr. Central Emergency Control Ctr. Div of Nuclear Power Emergency Ctr & Muscle Shoals Emergency Control Ctr emergency plan implementing procedures W/o Muscle Shoals pages MILLS.L M Tennessee Valley Authority 84/02/28 O'REILLY.J P Region 2. Office of Director 1p 22516 165 24x Fiche 50-000.84/02/28.8403060147
- --8403060163 Revised list of effective pages to Knoxville Emergency Ctr emergency plan implementing procedures # Tennessee Valley Authority 84/02/06 Bpp 22516 166 24X Fichs 50-000.84/02/28.8403060147
- --8403060189 Revised list of effective pages to Central Emergency Control Ctr emergency plan implementing procedures * Tennessee Valley Authority 84/02/06 8pp 22516 174 24X Fiche 30-000,84/02/28.8403060147
- ---8403060206 Revised list of effective pages to Div of Nuclear Power Emergency Ctr emergency plan implementing procedures * Tennessee Valley Authority 84/02/06 4pp 22516 182 24X Fichs 50-000,84/02/28.8403060147

- 8403160162 Ack receipt of 840222 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-57.
 50-260/83-57 & 50-256/83-57
 LEWIS, R C Division of Project & Resident Programs 84/02/29 PARRIS, H G Jannessee Valley Authority 1p 22655 273 24X Fiche 50-259,84/02/29,8403160162
- --840316017% Responds to NRC 840123 ltr re violations noted in IE Insp Repts 90-259/83-57, 90-240/83-57 % 50-296/83-57 Corrective actions policy statement issued to health physics technicians re high radistion area doors MILES.L M Tennessee Valley Authority 84/02/22 O'REILLY, J P Region 2, Office of Director 5pp 22655 274 24X Fiche 50-239,84/02/29,8403160162
- --8403140181 Notice of violation from insp on 831124-1225

 * Region 2. Office of Director 84/01/23 2pp 22655 281 24X
 Fiche 50-259,84/02/29.8403140162
- --8403160186 IE Insp Repts 50-259/83-57.50-260/83-57 & 50-276/83-57 on B31126-1225 Violations noted failure to lock high radiation area to follow special work permit & to have adequate fire protection maint procedure PAULK G L. Ragion 2. Office of Director 84/01/21 App 22655 283 24% Fiche 50-259.84/02/27.8403160162
- 840316021B Ack receipt of 840207 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-40, 50-259/83-40 & 50-259/83-40 & 50-259/83-40 & EWIS,R C. Division of Project & Resident Programs 84/03/01 PARRIS.H G. Tennessee Valley Authority 1p 22661 078 24X Fiche 50-259,84/03/01.8403160218
- --8403160223 Responds to NRC 840111 Itr re violations noted in IE Insp Repts 50-259/83-40,50-260/83-40 & 50-296/83-40 Corrective actions radiological emergency planning program reviewed & areas requiring rev identified MillS.L M Tennessee Valley Authority 84/02/09 D'REILLY,J P Region & Office of Director 6pp 22661 099 24X Fiche 50-259,84/03/01.8403160218
- --8403160230 Forwards IE Insp Repts 50-259/83-40,50-260/83-40 & 50-296/83-40 on 83(017-2) & 1122 & notice of violation LEMIS.R C Division of Project & Resident Programs 84/01/11 PARRIS.H O Tennessee Valley Authority 2pp 22661 105 24X Fiche 50-259,84/03/01.8403160218
- --8403160239 Notice of violation from insp on 831017-21 & 1122 * Region 2. Office of Director 84/01/11 3pp 22661 107 24X Fiche 5G-259,84/03/01.8403160218
- --8403160249 IE Insp Repts 50-259/83-40,50-260/83-40 & 50-296/83-40 on 831017-21 & 1122 Noncompliance noted failure to control documents properly train emergency personnel in protective action requirements & incorporate protective action DECKER T R Region 2. Office of Director 84/01/06 9pp 22661 110 24X Fiche 50-259,84/03/01.8403160818
- 8403160345 Extends invitation to attend region 840316 workshop at regional oft to discuss 10CFR50. App R requirements & recent results of insp to help resolve misunderstandings associated w/requirements

 LEWIS.R C Division of Project & Resident Programs 84/03/02

 PARRIS.H G Tennessee Valley Authority 2pp 22660 083 24X

 Fiche 50-000.84/03/02.8403160345
- 8403130485 Ack receipt of 840119 1tr transmitting Rev 7 to security personnel training & qualification plan Rev consistent U/provisions of 10CFR30 54(p) & acceptable LEHIS.R C Bivision of Project & Rosident Programs 84/03/08 PARRIS.H G Tennessee Valley Authority 2pp 22613 210 24X Fiche 50-259.84/03/08.8403130486
- 8403130484 Ack receipt of 840130 ltr transmitting rev to physical security plan Rev consistent w/provisions of 10CFR50 54(p) & acceptable LEMIS.R C Division of Project & Resident Programs 84/03/09 PARRIS.H G Tennessee Valley Authority 2pp 22613 197 24x Fiche 50-259.84/03/09,8403130484
- 8403160025 Advises that 840116 rev to physical security personnel training & qualification plan consistent u/provisions of 10CFR50 54(p) & acceptable LEWIS,R C Division of Project & Resident Programs 84/03/13 PARRIS,H G Tennessee Valley Authority 2pp 22650 358 24X Fiche 50-259,84/03/13,8403160025

- 8403170136 Ack receipt of 840221 & 0312 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-59.50-260/83-59 & 50-296/83-59 Responses meet 10CFR2 201 requirements LEWIS.R C Division of Project & Resident Programs 84/03/14 PARRIS.H 0 Tennessee Valley Authority ip 22670 314 24X Fiche 50-259.84/03/14.8403190136
- --8403190149 Supple response to NRC 840120 ltr re violations noted in IE Insp Repts 50-259/83-59, 50-260/83-59 & 50-296/83-59 Responses withheld (ref 10CFR73 21) MILLS.L M Tennessee Valley Authority 84/03/12 O'REILLY.J P. Region 2. Office of Director 1p 22670 315 24x Fiche 50-259.84/03/14.8403190136
- --8403190141 Responds to NRC 840120 ltr re violations noted in IE Insp Repts 30-259/83-59,50-260/83-59 & 50-296/83-59 Responses withheld (ref 100FR73 21) MILLB.L.M Tennessee Valley Authority 84/02/21 O'REILLY, J P Region 2. Office of Director ip 22670 316 24X Fiche 50-259,84/03/14,8403190136
- --8403190172 Forwards IE Insp Repts 50-259/83-59, 50-260/83-59 & 50-296/83-59 on 831216 & notice of violation Notice of violation withheld (ref 10CFR2 790 & 73 21)
 LEWIS,R C Division of Project & Resident Programs 84/01/20 PARRIS,H G Tennessee Valley Authority 2pp 22670 317 24X Fiche 50-259,84/03/14,8403190136
- --8403190188 IE Insp Repts 50-259/83-59.50-260/83-59 & 50-296/83-59 on 831216 Noncompliance noted security force member failed to control access to area Details withheld (ref 10CFR73 21 & 2 790)
 TILLHANA Region 2. Office of Director 84/01/19 lp 226/0 319 24X Fiche 50-259.84/03/14.8403190136
- B403290117 Forwards FEMA final rept for B31015-16 emergency exercise VERRELLI.D M Division of Project & Resident Programs 84/03/20 PARRIS.H G Tennessee Valley Authority 1p 22807 027 24X Fiche 50-259,84/03/20,8403290117
- G Adjudicatory correspondence
- 8403200059 Submits addl info on util initiatives in PRA, per response to 840227 ltr Effort to reduce number of violations & risks maintained FREEMAN.S D Tennessee Valley Authority 84/03/12 MARKEY, E.J. House of Rop., Interior & Insular Affairs 2pp 22685 033 24X Ficho 50-259,84/03/12,8403200059
- J Insurance & indemnity information
- 8403060334 Forwards Endorsement 73 to NELIA Policy NF-198 BUCK J R Marsh & McLennan, Inc. 84/02/28 SALTZMAN, J Assistant Director for State & Licensee Relations 2pp 22516 009 24X Fiche 50-289-84/02/28,8403060334
- P Operating license stage documents & correspondence
- 8403060076 Forwards request for add1 info re inservice testing of pumps & valvas.in order to complete review of 820831 & 830406 submittals Response requested within 45 days of 1tr receipt VASSALLO,D D Operating Reactors Branch 2 84/02/10 PARRIS.H G Tennessee Valley Authority 4pp 22528 288 24% Fiche.50-257.84/02/10,8403060076
- B403140340 Summary of B31215 meeting w/GE & Mark I Owners Group in Bethesda, MD re Mark I containment wetwell-drywell vacuum breaker design methodology BIEGEL, B. L. Operating Reactors Branch 2 84/02/21 Operating Reactors Branch 2 51pp 22635 198 24X Fiche 50-000,84/02/21, B403140340
- 8403010304 Application for amend to Licenses DPR-33, DPR-52 & DPR-48, changing Tech Specs to lower Group 1 isolation setpoint for reactor lower water level W/proprietary NEDE-30012, " MSIV Water Level " Rept withheld (ref 10CFR2,790) MILLS,L M Tennessee Valley Authority 84/02/22 DENTON,H R Office of Nuclear Reactor Regulation, Director 3pp 22433 042 24% Fiche 50-259,84/02/22,8403010306
- ---B403010313 Proposed changes to Tech Specs lowering Group 1 isolation setpoint for reactor lower water level W/affidavit * Tennesses Valley Authority B4/02/22 29pp 22433 045 24X Fiche 50-259, 84/02/22, 8403010304

1

ļ

DOCKETED ITEMS

- 8403150323 Forwards info re BNL dose reduction project plant visit info allows BNL personnel to better prepare for station visit, expedite paperwork & minimize impact on plant personnel VASSALLO, D B Operating Reactors Branch 2 84/02/28 PARRIS, H G Tennessee Valley Authority 46pp 22662 040 24% Fiche 50-259,84/02/28,8403150323
- 8403130007 Forwards response to Generic Ltr 83-36 re MUREG-0737 Tech Specs MILLB,L M Tennessee Vailey Authority 84/03/07 DENTON,H R Deffice of Nuclear Reactor Regulation, Director 3PP 22613 349 24X Fiche 50-259,84/03/07,8403130007
- 8403130025 Informs that add1 info requested on B31012 re reactor protection sys power monitoring sys design mods will be submitted by B40702 MILL9.L M Tennessee Valley Authority 84/03/07 DENTON.H R Office of Nuclear Reactor Regulation, Director 1p 22614 362 24X Fiche 50-259.84/03/07.8403130025
- 8403160247 Informs of 840327 meeting to discuss proposed responses to NRC questions on Rev 7 to topical QA program.per B40302 telcon
 LEWIS,R C Region 2. Office of Director 84/03/08 PARRIS,H 0
 Tennessee Valley Authority ip 22660 361 24X
 Fiche 50-000.84/03/08.8403160247
- 8403160373 Notifies of use of ABME Nuclear Components Code Case N32~4 for hydrostatic testing of Class 3 embedded piping NRC position re use of Code Case N32~4 requested MILLB.L M Tennessee Valley Authority 84/03/12 DENTON, H R. Office of Nuclear Reactor Regulation, Director ip 22660 014 24X Fichs 50-000.84/03/12.8403160373
- 8403150275 Generic Ltr 84-07 to all licensees of BWRs re procedural guidance for pipe replacement at BWRs SVc 11st encl EIBENHUT.D O Division of Licensing 84/03/14 Commonwealth Edison Ce 20pp 22823 354 24% Fiche 50-000.84/03/14.8403150275
- 8403200170 Forwards response to Item 4 5 of Generic Ltr 83-28,
 "Required Actions Based on Generic Implications of Balem
 ATMS Events" re reactor trip sys reliability Control rod
 tests check rod insertion times & hydraulic scram valves
 MILLS.L M Tennesse Valley Authority 84/03/15 DENTON,H R
 Office of Nuclear Reactor Regulation, Director 10pp 22700 024
 24X Fiche 50-259,84/03/15,8403200170
- 8403260229 Forwards addl info re test configuration & results of verification testing, per 840106 request re adequacy of station electric distribution sys voltages Test results indicated no unexpected voltage levels
 MILLB.L M Tennessee Valley Authority 84/03/19 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 26pp 22756 12/24X Fiche 50~259,84/03/19,8403260229

O Inspection reports, IE Bulletins & correspondence

- 8403070054 Responds to NRC 1tr re violations noted in IE Insp Repts 50-259/83-09.50-260/83-09 & 50-276/83-09 List of identified deficiencies & implementation schedule provided to senior NRC inspector on 830901 MILLS.L M Tennessee Valley Authority 83/09/15 O'REILLY, J P Region 2. Office of Director ip 22547 261 24X Fiche 50-259.83/09/15.8403070054
- 8403070237 Updates 830715 response to NRC 830616 ltr re violations noted in IE Insp Repts 50-259/83-19, 50-260/83-19 & 50-296/83-19 Operating instructions revised & Units 2 & 3 P8C charping sys operational MILLS.L M Tennessee Valley Authority 83/09/30, 0'REILLY, J P Ragion 2, 0ffice of Director ip 22541 361 24X Fiche 50-259, 83/09/30, 8403070237
- 8403070271 Supple B30830 response to NRC ltr re violations noted in IE Insp Repts 50-259/83-23,50-260/83-23 & 50-296/83-23 Boral test specimen installation will be delayed until 831028 due to late receipt of matis per 831012 telcon KAMMER.D S Tennessee Valley Authority 83/10/21 0'REILLY, J P Region 2. Office of Director 1p. 22546 356 24X Fiche 50-259,83/10/21,8403070271
- 8403070023 Responds to NRC ltr re violations noted in IE Insp Repts 50-259/83-27.50-260/83-27 & 50-296/83-27 Corrective actions compliance w/instructions will be achieved & corrective actions will be completed before Cycle 6 operation MILLB.L M Tennasses Valley Authority 83/10/27 O'REILLY, J P Region 2. Office of Director ip 22541 262 24X Fiche 50-259,83/10/27,8403070023

- 8403070067 Forwards IE Insp Repts 50-259/83-50, 50-260/83-50 & 50-276/83-50 on 830912-16 & 26-30 Unresolved item re possible high radiation doses measured by personnel dosimeters, discussed on 831028, considered closed O'REILLY, J P Region 2. Office of Director 84/01/11 PARRIS, H G Tennessee Valley Authority 2pp 22545 341 24X Fiche 50-259, 84/01/11, 8403070067
- --B403070072 IE Insp Repts 50-259/B3-50; 50-260/B3-50 & 50-296/B3-50 on B31028 No violations or deviations noted Major areas inspected TLD & multiple badging DEDS: B T Region 2, Office of Director B3/12/05 5pp 22845 343 24% Fiche 50-259; 84/01/11; 8403070067
- 8403160232 Forwards IE Insp Repts 50-259/84-04.50-260/84-04 & 50-276/84-04 on 840123-27 No violations or deviations noted VERRELLI.D M Division of Project & Resident Programs 84/02/16 PARRIB.H G Tennessee Valley Authority 2pp 22661 029 24X Fiche 50-259.84/02/16.8403160232
- --8403160238 IE Insp Repts 50-259/84-04, 50-260/84-04 & 50-276/84-04 on B40123-27 No violations or deviations noted Major areas inspected startup testing, new fuel receipt, plant tours & MBIV repair status

 DAVENPORT.K E Region 2, Office of Director JAPE, f Division of Engineering & Operational Programs B4/02/14 5pp 22661 031 24X Fiche 50-259, 84/02/16, 8403160232
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Ambunciation " Svc list enc!

 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/08/28 Consolidated Edison Co. of New York, Inc. 115pp 22707 239 24X Fiche 50~000.84/02/28, 8401190072
- B403160162 Ack receipt of 840222 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/B3-57, 50-260/B3-57 & 5
- --8403160171 Responds to NRC 840123 ltr re violations noted in IE Insp Repts 50-259/83-57, 50-260/83-57 & 50-296/83-57 Corrective actions policy statement issued to health physics technicians re high radiation area doors MILLS.L M Tennesse Valley Authority 84/02/22 O'REILLY, J P Region 2. Office of Director Spp 22655 274 24X Fiche 50-259,84/02/29,8403160162
- --8403160178 Forwards IE Insp Repts 50-259/83-57.50-260/83-57 & 50-276/83-57 on 831126-1225 & notice of violation LEWIG.R C Division of Project & Resident Programs 84/01/23 PARRIS.H G Tennessee Valley Authority 2pp 22655 279 24X Fiche 50-259,84/02/29,8403160162
- --8403160181 Notice of violation from insp on 831126-1225 * Region 2, Office of Director 84/01/23 2pp 22655 281 24X Fiche 50-259,84/02/29,8403160162
- --8403i60186 IE Insp Repts 50-259/83-57.50-260/83-57 & 50-296/83-57 on 831i26-1225 Violations noted feilure to lock high radiation area, to follow special work permit & to have adequate fire protection maint procedure PAULK.6 L Region 2. Office of Director CANTRELL, F B Division of Project & Resident Programs 84/01/21 App 22655 283 24X Fiche 50-259,84/02/29,8403160162
- 8403160218 Ack receipt of 840209 ltr informing NRC of steps taken to correct violations noted in 16 Insp Regts 20~259/83~40, 50~260/83-40 & 50~276/83-40 LEWIS,R C Division of Project & Resident Programs 84/03/01 PARRIS,H G Tennessee Valley Authority ip, 22861 098 24X Fiche 50~259,84/03/01,8403160218
- ~-8403160223 Responds to NRC 840111 ltr re violations noted in IE Insp. Repts 50-259/83-40, 50-260/83-40 & 50-276/83-40 Corrective actions radiological emergency planning program reviewed & areas requiring revidentified MILLS.L M Tennesses Valley Authority 84/02/09 0'REILLY.J P. Region 2. Office of Director App. 22661 099 24X Fiche 50-259,84/03/01.8403160218
- --8403160230 Forwards IE Insp Repts 50-259/83-40,50-260/83-40 & 50-276/83-40 on 831017-21 & 1122 & notice of violation LEMTS.R C Division of Project & Resident Programs 84/01/11 PARRIS.H G Tennessee Vallay Authority 2pp 22661 105 24X Fiche 50-259,84/03/01,8403160218
- ---8403160239 Notice of violation from insp on 831017-21 & 1122 * Region 2, Office of Director 84/01/11 3pp 22661 107 Ficha 50-259.84/03/01.8403160218

- --8403160244 IE Insp Repts 50-259/83-40, 50-260/83-40 & 50-296/83-40 on 831017-21 & 1122 Noncompliance noted failure to control documents properly train emergency personnel in protective action requirements & incorporate protective action BECKER.T R, STODDART.P G Region 2. Office of Director JENKINS,G R Division of Emergency Preparedness & Materials Safety 84/01/06 9pp 22661 110 24X Fiche 50-259,84/03/01,8403160218
- 8402090007 [E Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl ORACE, J N Division of OA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24% Fiche 50-000.84/03/02.8402090007
- 8402090008 IE Into Notice 84-16, "Failure of Automatic Sprinkler Sys-Valves to Operate " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008
- 8402090009 IE Info Notice 84-15. "Reporting of Radiological Releases."

 Bvc list ancl.

 JURDAN, E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02. Consolidated Edison Co. of New
 York, Inc. 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8403080213 EN-84-007 on B40307 matice of violation & proposed imposition of tivil penalties in amount of \$40,000 to be issued Action based on failure to control access into vital area due to guard leaving post ROSAND.R . AXELRAD.J Director's Office, Office of Inspection and Enforcement 84/03/02 lp 22560.021 24X Fiche.50-259.84/03/02.8408080213
- 8402090011 IE info Notice 84-17, "Problems W/Liquid Nitrogen Coaling Components Below Nil Ductility Temp " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co. of New York, Inc. 117pp 22553 336 24% Fiche 50-000,84/03/05,8402070011
- 84031&0308 Ack receipt of 840217 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-259/83-56 LEWIS:R C Division of Project & Resident Programs 84/03/05 PARRIS,H G Tennessee Valley Authority 1p 22660 085 24X Fiche 50-259.84/03/05.8403160308
- --8403160318 Responds to NRC 840117 ltr re violations noted in IE Insp Repts 50-259/83-56.50-260/83-56 & 50-296/83-56 Corrective actions 10% retest sample calculation made for all snubbers within Category/Group 3 Hill.Es.L. M. Tennessee Valley Authority 84/02/17 O'REILLY, J.P. Region 2. Office of Director 2pp 22660 086 24X Fishe 50-259.84/03/05.8403160308
- --8403160328 Forwards IE Insp Repts 50-259/83-56.50-260/83-56 & 50-276/83-56 on 831213-16 & notice of violation LEWIS.R C Division of Project & Resident Programs 84/01/17 PARTIS.H G Tennessee Valley Authority 2pp 22660 088 24) Fiche 50-259.84/03/05.8403160308
- --8403160332 Notice of violation from insp on 831213-16
 * Region 2. Office of Director 84/01/17 ip 22660 090 24x
 Fiche 50-259.84/03/05.8403160308
- --8403160339 IE lnsp Repts 50-259/83-56, 50-260/83-56 & 50-296/83-56 on 831213-16 Violation noted failure to test add1 10% sample for each shubber that failed functional test WHITENER.H L. Repion 2. Opfice of Director JAPE,F Division of Engineering & Operational Programs 84/01/10 8pp 22660 091 24% Fiche 50-239,84/03/05,8403160308
- 1403290237 Forwards IE Insp Repts 50-259/84-05, 50-260/84-05 & 50-296/84-05 on 840130-0201 No violations or deviations identified VERRELLI, D M Division of Project & Resident Programs 84/03/05 PARRIS, H G Tennessee Valley Authority 2pp 22800 229 24X Fiche 50-259, 84/03/05, 8403290237
- --8403290237 IE Insp Repts \$0-259/84-05, 50-260/84-05 & 50-296/84-05 on 840130-0201, No violations or deviations identified Major areas inspected followup of IE Bulletin 81-03, review of LERs re bulletin & procedures for flow reverification tests CUNNINOHANA L Region 2, Office of Director MONTOOMERY, D M Division of Engineering & Operational Programs 84/03/02 5pp 22800 231 24X Fiche 50-259,84/03/05,8403290237
- 8402090024 IE info Notice 84-09. Rev 1. "Lessons Learned From Insps of Fire Protection Bafe Shutdown Sys " Svc list encl UDBANE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24% Fiche 50-000,84/03/07,8402090024

- B40207002B IE Info Notice B4-18, "Stress Corrosion Cracking in PWR Bys " Svc list enc! JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New Yerk, Inc 118pp 22884 186 24X Fiche 50-000.84/03/07,8402070028
- B403160273 Forwards IE Enforcement Conference Repts 50-259/84-06, 50-260/84-06 & 50-296/84-06 on 840224 O'REILLY, J P Region 2, Office of Director 84/03/08 PARRIS, H Q Tennessee Valley Authority 2pp 22661 004 24X Fichs 50-259,84/03/08.8403160273
- --B403160282 IE Enforcement Conference Repts 50-259/84-06.50-260/84-06 & 50-276/84-06 on 840224 Major items discussed bypassing rod sequence control sys while shutting down & isolation of drywell to pool pressure instrument

 BUTCHER, R C Region 2, Office of Director CANTRELL.F S

 Division of Project & Resident Programs 84/02/29 4pp
 22661 006 24% Fiche 50-259.84/03/08.8403160273
- 8402070031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Syc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 074 24% Fichs 50-000.84/03/12,8402070031
- 8403190136 Ack receipt of 840221 & 0312 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-59, 50-260/83-59 & 50-296/83-59 Responses meet 10CFR2 201 requirements LEHIS,R C Division of Project & Resident Programs 84/03/14 PARIS,H 0 Tennessee Valley Authority 1p 22670 314 24X Fichs.50-259,84/03/14,8403190136
- --8403190149 Suppls response to NRC 840120 ltr re vibilations noted in IE Insp Repts 50-257/83-59, 50-260/83-59 & 50-276/83-59 Responses withheld (ref 100FR73 21) MILLS.L. M Tennessee Valley Authority 84/03/12 0'REILLY, J P Region 2, Opfice of Director 1p 22670 315 24X Fiche 50-259,84/03/14,8403190136
- --8403190161 Responds to NRC 840120 ltr re violations noted in IE Insp Repts 50-259/83-59.50-260/83-59 & 50-296/83-59 Responses withheld (ref 10CFR73 21) MILLS,L M Tennessee Valley Authority 84/02/21 D'REILLY, J P Region 2. Office of Director ip 22670 316 24X Fichs 50-259,84/03/14,8403190136
- --8403190172 Forwards IE Insp Repts 50-259/83-59,50-260/83-59 & 50-296/83-59 on 831216 & notice of viplation Notice of viplation withheld (ref 100FR2 790 & 73 21)
 LEHIS.R C Division of Project & Resident Programs 84/01/20
 PARRIS.H O Tennessee Valley Authority 2pp 22670 317 24X
 Fichs 50-259,84/03/14,8403190136
- --B4031901BB IE Insp Repts 50-259/83-59, 50-260/83-59 & 50-296/83-59 on 831216 Noncompliance noted security force mamber failed to control access to area Details withheld (ref 10CFR73 21 & 2 790)
 TILLMAN.A. PATTERSON,C Region 2, Office of Director MCGUIRE,D R Division of Emergency Preparedness & Materials Safety 84/01/19 ip 22670 319 24X Fiche 50-259,84/03/14,8403190136
- 8403270047 Summarizes 840312 meeting in Region II ofc re planned util organizational changes & regulatory performance improvement program for facility B'REILLY. J.P. Region 2. Office of Director 84/03/15 PARRIS. H. O Tennessee Valley Authority 1p 22806:271 24X Fiche 50-239, 84/03/15. 8403270047
- 8403290178 Ack receipt of 840217 ltr informing NRC of steps taken to correct violations noted in 1E Thep Repts 50-259/83-38, 50-280/83-88 & 50-294/83-38 LEMIS.R C Division of Project & Resident Programs 84/03/20 FARRIS.H G Tennessee Valley Authority ip 22800 278, 24X Fiche 50-259,84/03/20,8403290178
- --8403290183 Supply response to NRC 840119 ltr re violations noted in IE Insp Repts 50~259/83-38, 50~260/83-38 & 50~296/83-38 Corrective actions distribution of insp rept to health physics personnel initiated MILLS.L M Tennessee Valley Authority 84/02/17 D'REILLY, J P. Region 2. Office of Director 2pp 22800 279 24X Fiche 50~259,84/03/20,8403290178
- --B403290190 Ack receipt of 831209 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-3B, 50-260/83-38 & 50-254/83-3B
 O'REILLY.J P Region 2, Office of Director 84/01/19
 PARRIS.H O Tennessee Valley Authority 2pp 22800.281 24X
 Fichs 50-259,84/03/20,8403290178

- --8403270203 Ack receipt of 831209 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50~259/83-38, 50~266/83-38 & 50~296/83-38 LEWISR C Division of Project & Resident Programs 83/12/21 PARRISR O Tennessee Vailey Authority ip 22800 283 24X Ficha 50~259,84/03/20,8403270178
- --8403290207 Responds to NRC 831109 ltr re violations noted in IE Insp Repts 50-259/83-38,50-260/83-38 & 50-276/83-38 Corrective actions insp rept distributed to health physics personnel & RCI-5 revised to incorporate 10CFR49 changes MILLB,L M Tennessee Valley Authority B3/12/09 0'REILLY,JP Region 2. 04fice of Director 5pp 22800 284 24X Fiche 50-259,84/03/20,8403290178
- --8403290211 Forwards IE Insp Repts 50-259/83-38.50-260/83-38.\$
 50-296/83-38 on 830912-16.\$ notice of violation
 LENTS,R C Division of Project & Resident Programs 83/11/09
 PARRIS,H 0 Tennessee Valley Authority 2pp 22800 289 24X
 Fichs 50-259,84/03/20,8403290178
- --8403290214 Notice of violation from insp on 830912-16 * Region 2, Office of Director 83/11/09 2pp 22800 291 24X Fiche 50-259,84/03/20,8403290178
- --8403290220 IE Insp Repts 50-259/83-38, 50-260/83-38 & 50-296/83-38 on 830912-16 Violations noted 55-gallon drum reading 30 to 65 millirem per hour observed unlabeled & radiation control procedures not prepared or adhered to DE88,8 T Region 2, Office of Director BARR,K P Division of Engineering & Operational Programs 83/11/03 6pp 22800 293 24X Fiche 50-259,84/03/20,8403290178
- B402090043 IE Info Notice B4-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp. 22823 229 24X Fiche 50-000,84/03/21,8402090043
- B402090044 IE Info Notice 84-20, "Syc Life of Relays in Safety-Related Bys " Syc list enc!

 JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 84/03/21 Consolidated Edison Co of New York, Inc. 135pp. 22933 001 24X Fiche 50-000,84/03/21,8402090044

R Pariodic operating reports & related correspondence

- 84030R0103 Monthly operating repts for Jan 1984 W/8402[0 ltr CHAPMAN,M , THOM.T., JONES.O T. Tennessee Valley Authority 84/01/31. 41pp 22443 166 24X Fiche 50-257.84/01/31.8403020103
- 8403300133 Forwards monthly operating repts for Feb 1984 & corrected Jan 1984 monthly operating rept for Unit 1 JONES, 0 T Tennessee Valley Authority 84/03/09 Office of Resource Management, Director, 1p 22820 203 24X Fiche 50-259,84/03/09,8403300133
- --B403300136 Monthly operating repts for Feb 1984 THOM, T Tennessee Valley Authority 84/02/29 37pp 22820 204 24x Fichs 30-259,84/03/09,8403300133
- --B403300139 Corrected monthly operating rept for Jan 1984 CHAPMAN, M Tennessee Valley Authority B4/01/31 2p; 22820 243 24X Fiche 50-239, 84/03/09, 8403300133

8. Reportable occurrences, LERs & related correspondence

- 8403010226 Updated LER 83-016/03X-1 on 830309.offsite analysis of charcoal sample from control room emergency ventilation sysshowed methyl idoide removal efficiency less than required Caused by degradation of stored charcoal W/840215 ltr CLARK.J.R., JONES.O T Tennessee Valley Authority 84/02/15 O'REILLY,J.P. Region 2, Defice of Director. 5pp 22435, 238 24X Fiche, 50-259.84/02/15,8403010226.
- 8403020325 Updated LER 83-029/03L-1 on 830604, during standby gas treatment sys operability test, train B found inoperable Causad by erratic McDonnel & Milter Model AF-i flow switches Damper 0-65-503 adjusted, W/840221 ltr CARTER, S. D. JONES, O T Tennessee Valley Authority 84/02/21 D'REILLY, J P Region 2, Office of Director 3pp. 22439, 312 24X Fiche 50-259, 84/02/21, 8403020325
- 8403010371 LER 84-008-00 on 840127, during normal operation, one or more pressure differential transmitter instrumentation 1-25A through D failed in downscale direction.causing trouble alarm. Cause unknown, Instruments recalibr. W/840223 ltr MARKIN, K M, JONES, G T Tennessee Valley Authority 84/02/23. 4pp 22433:089 24X Fiche 50-259, 84/02/23.8403010371

- 8403060244 LRR 84-010-00 on 840203, operator observed hydrogen-oxygen analyzer B isolated Caused by faulty Group 6 isolation relay signal Signal reset & ht & low relays replaced W/840228 ltr MORKIN, K M , JONES, G T Tennesse Valley Authority 84/02/28 3pg 22515 178 24X Fiche 50-259,84/02/28,8403060244
- 8403260233 Forwards summary list of deficiencies identified per iOCFR30 55(e),Part 21 & potential generic ltr repts for comments
 8TAROSTECKI.R Division of Project & Resident Programs 84/02/28 Region i. Office of Director 7pp 22796 065 24X
 Fiche 50-000,84/02/28.8403260233
- 8403090085 LER 84-011-00 on 840209, during routine surveillance testing, automatic scram initiated Caused by failure of MSIV do solenoid Failure considered random event Solenoid coils checked weekly for operability W/840229 ltr BMITH, D L JONES, O T Tennessee Valley Authority 84/02/29 3pp 22575 317 24X Fiche 50-259,84/02/29.8403090085
- 8403090245 Followup LER 84-007-01 on 840127, operator observed decreasing pressure on control atmospheric dilution tanks Caused by two isolation valves being in closed position Operating instructions revised W/840302 ltr
 WALKER, J B , JONES, O T Tennessee Valley Authority 84/03/02 3pp 22573 253 24X Fiche 50-259,84/03/02.8403090245
- B403090253 LER 84-013-00 on B40213, air & vacuum release valves found underrated for surge check valve svc application Caused by misapplication of valve New valves. w/proper design & pressure rating, installed W/840302 ltr WALKER, J B , JONES, O T Tennessee Valley Authority 84/03/02 3pp 22573 256 24% Fiche 50-259, 84/03/02,8403090253
- B403130205 LER B4-012-00 on B40214.RHR valve FCV-1-74-48 feiled to open making normal method cold shutdown impossible to achieve Possibly caused by failure of Phase B motor winding Next rept will be submitted by 840901 W/840306 ltr R0ZEAR,C J. JUNES,C T Tennessee Valley Authority B4/03/06 3pp 22617 292 24X Fiche 50-259,84/03/06.B403130205
- 8403190371 LER 84-015-00 on 840221.during ongoing design review of plant sys.discovered that emergency equipment cooling water vacuum priming valve on north header underfessigned for sys pressure Cause not stated Valve isolated W/840309 ltr SMITH.D L . JONES.O T Tennessee Valley Authority 84/03/09 3pp 22675 304 24X Fiche 50-259.84/03/09.8403190371
- B403200213 Updated LER 83-066/03x-i on 831112, interlock that prevents bridge travel over core w/one rod withfrawn & foel grapple extended falled to operate, resulting in loss of rod block function Caused by improper adjustment W/840309 ltr HOLDER, E T , JONES, O T Tennessee Valley Authority B4/03/09 O'REILLY, J P. Region 2, Office of Director App 22699 314 24X Fichs 50-259, 84/03/09, 8403200213
- 8403190125 LER 84-014-00 on 840222 reactor scrammed when turbine high pressure first stage pressure exceeded 142 psig w/ turbine stop valves closed Caused by procedural error Derating instruction will be revised W/840313 ltr ROZEAR, C J , JUNES, O T Tennessee Valley Authority 84/03/13 3pp 22668 248 24X Fiche 50-259,84/03/13.8403190125
- B403220046 Updated LER 84-014-01 on 840222 reactor scrammed when turbine high pressure first stage pressure exceeded 142 psig w/turbine stop valves closed Caused by procedural error. Operating instruction revised W/840316 ltr RDZEAR, C J , JDMES, G T Tennesses Valley Authority B4/03/13 3pp 22712 194. 24X Fiche 50-259,84/03/13.8403220046

V Operator Examinations

- 8403160227 Confirms 840302 mesting in Atlanta, GA re 840319 operator requalification exam, per 840229 telcon
 LEMIBLE C Division of Project & Resident Programs 84/03/01
 PARRIE, H O Tennessee Valley Authority ip 22660 328 24X
 Fichs 50-259, 84/03/01, 8403160227
- 8403290322 Discusses 840117 ltr confirming arrangements for administration of requalification exams Random selection process used to determine identify of examinees for written & oral exams List of examinees encl LEMIS.R C Division of Project & Resident Programs 84/03/13 PARRIGH 0 Tennessee Valley Authority 3pp 22802 049 24X Fichs. 50-259, 84/03/13, 8403290322
- B403270213 Summarizes 840302 meeting w/util re 840323 requalification exam of licensed operator & senior operator personnel at facilities. Meeting provided better understanding of operator requalification training & exam programs
 LEMIS, R C Division of Project & Resident Programs 84/03/15
 PARRIS, H 9. Tennesses Valley Authority 3pp 22800 360 24X
 Fiche 50-237,84/03/15,8403270213

- DOCKET 50-260 BROWNS FERRY NUCLEAR POWER STATION, UNIT 2
 F Security, medical, emergency & fire protection plans
- 8403060238 Emergency plan implementing procedures, including IP-2 re notification of unusual event, IP-3 re alert, IP-4 re site emergency & IP-6 re radiological emergency plan activation at support ctr W/840228 tr & list of effective pages MILLS.L M Tennessee Valley Authority 84/02/10 0'REILLY.J P Region 2. Dffice of Director 52pp 22516 098 24X Fiche 50-259,84/02/10,8403060238
- 8403060571 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee, per 810709 Ceneric Ltr 81-27 W/o request.entire plan will be placed in PDR VASSALLO.D B Operating Reactors Branch 2 84/02/10 PARRIS.H G Tennessee Valley Authority. 2pp 82552 261 24X Fiche 50-259.84/02/10.8403060571
- 8403060235 Rev 5 to Procedure IP-9. "Muscle Shoals Emergency Ctr Implementing Procedures Document " W/840213 ltr MAXMELL.R . SLIGER.E K Tennesse Valley Authority B4/02/13 63pp 22518 023 24X Fiche 50-000,84/02/13,8403060235
- 8403060147 Forwards revised effective pages to Knozville Emergency Ctr. Central Emergency Control Ctr.Div of Nuclear Power Emergency Ctr. & Muscle Shoals Emergency Control Ctr Smergency plan implementing pracedures W/o Muscle Shoals pages HILLS.L M Tennessee Valley Authority 84/02/28 0'REILLY.J P Region 2. Office of Director 1p. 22516-165 24X Fiche 50-000.84/02/28.8403060147
- --8403060163 Revised list of effective pages to Knozville Emergency (tremergency plan implementing procedures
 * Tennesses Valley Authority 84/02/06 8pp 22516 166 24K
 Fiche 50-000,84/02/28,8403060147
- --8403050189 Revised list of effective pages to Central Emergency Control Ctr emergency plan implementing procedures * Tennessee Valley Authority 84/02/06 8pp 22516 174 24X Fiche 50-000.64/02/28.8403060147
- --8403050206 Revised list of effective pages to Div of Nuclear Power Emergency Ctr emergency plan implementing procedures
 * Tennessee Valley Authority 84/02/06 4pp 22916 182 24X Fichs 50-000,84/02/28.8403060147
- 8403140162 Ack receipt of B40222 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-57, 50-260/83-57 & 50-294/83-57 LEHIS,R C Division of Project & Resident Programs B4/02/29 PARRIS,H O Tennessee Valley Authority ip 22655 273 24X Fiche 50-259,84/02/29,8403160162
- --8403160171 Responds to NRC 840123 ltr re violations noted in IE Insp. Repts 50-259/83-57, 50-260/83-57 & 50-296/83-57 Corrective actions policy statement issued to health physics technicians re high radiation area doors HILLS.L.M. Tennessee Valley Authority 84/02/22 0'REILLY.J.P. Region 2, Office of Director Spp. 22655 274 24X Fiche 50-259,84/02/29,8403160162
- --8409160181 Natice of violation from insp on 831126-1225 * Region 2, Office of Director 84/01/23 2pp. 22655 281 24X Fiche 50-259, 84/02/29.8403160162
- --8403160186 IE Insp Repts 50-259/83-57, 50-260/83-57 & 50-296/83-57 on 831126-1225 Violations noted failure to lock high radiation area; to follow special work permit & to have adequate fire protection maint procedure.

 PAULK, G L. Region 2, Office of Director 84/01/21 App 22655 283 24X Fiche 50-259.84/02/29,8403160162
- 8403160218 Ack receipt of 840209 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-40, 50-260/83-40 & 50-296/83-40 & EHIS.R C Division of Project & Resident Programs 84/03/01 PARRIS.H O Tennessee Valley Authority Ip 22661 098 24% Fiche 50-259,84/03/01,8403160218
- --8403160223 Responds to NRC 840111 itr re violations noted in 1E Insp Repts 50-299/83-40,50-260/83-40 & 50-296/83-40 Corrective actions radiological emergency planning program reviewed & areas requiring revidentified MILLS,L.M Tennessee Valley Authority 84/02/09. D'REILLY, J P Region 2. Office of Director 6pp 22661 099 24X Fithe 50-259,84/03/01,8403160218

- --8403160230 Forwards 1E Insp Repts 50-259/83-40.50-260/83-40 & 50-296/83-40 on 831017-21 & 1122 & notice of Violation LEWIS.R C Division of Project & Resident Programs 84/01/11 PARRIS.H 0 Tennessee Valley Authority 2pp 22661 105 24) Fichs 50-259.84/03/01.840316021B
- --8403160239 Natice of violation from insp on 831017-21 & 1122 * Region 2. Office of Director 84/01/11 3pp 22661 107 24X Fiche 50-259,84/03/01,8403160218
- --8403160244 IE Insp Repts 50-259/83-40,50-260/83-40 & 50-296/83-40 on 831017-21 & 1122 Noncompliance noted failure to control documents, properly train emergency personnel in protective action requirements & incorporate protective action DECKER.TR Region 2, Office of Director 84/01/04 9pp 22661 110 24X Fiche 50-259,84/03/01,8403160218
- 8403160345 Extends invitation to attend region 840316 workshop at regional ofc to discuss 10CFR30.App R requirements & recent results of insp to help resolve misunderstandings associated w/requirements

 LEWIS.R C Division of Project & Resident Programs 84/03/02

 PARRIS.H 0 Tennesses Valley Authority 2pp 22660 083. 24X

 Fiche 50~000.84/03/02.8403160345
- 8403130485 Ack receipt of 840119 ltr transmitting Rev 7 to security personnel training & qualification plan Rev consistent W/provisions of 100FR50 54(p) & acceptable LEWIS.R C Division of Project & Resident Programs 84/03/08 PARRIS,H G Tennessee Valley Authority 2pp 22613 210 24X Fiche 50-259,84/03/08,8403130485
- 8403130484 Att receipt of 840130 ltr transmitting rev to physical security plan Rev consistent w/provisions of 10CFR50 54(p) to acceptable LEWIS,R C Division of Project to Resident Programs 84/03/09 PARRIS,H 0 Tennessee Valley Authority 2pp 22613 197. 24X Fiche 50-259,84/03/09,8403130484
- 8403160025 Advises that 840116 rev to physical security personnel training & qualification plan consistent w/provisions of 10CFR50 54(p) & acceptable
 LEWIS.R C Division of Project & Resident Programs 84/03/13 PARRIS.H 0 Tennessee Valley Authority 2pp 22653 358 24X Fiche 30~259,84/03/13,8403160025
- 8403190136 Ack receipt of 840221 & 0312 ltrs informing NRC of steps taken to correct violations noted in IE insp Repts 50-259/83-59, 50-260/83-59 & 50-276/83-59 Responses meet 10CFR2 201 requirements LEWIS.R C Division of Project & Resident Programs 84/03/14 PARRIS.H G Tennessee Valley Authority 1p 22670 314 24X Fiche 50-259.84/03/14,8403190136
- --8403170147 Supple response to NRC 840120 ltm re violations noted in IE Insp Repts 50-257/83-59, 50-260/83-59 & 50-296/83-59 Responses withheld (ref 100FR73 21). MILLS, L M Tennesses Valley Authority 84/03/12, 0'REILLY, J P Region 2, Office of Director ip. 22670 315 24x Fichs 50-259,84/03/14,8403170136
- --8403190161 Responds to NRC 840120 ltr re violations noted in IE Insp Repts 50-257/83-59, 30-260/83-59 & 50-296/83-59 Responses withheld (ref 100FR73 21) MILLS,L M Tennessee Valley Authority 84/02/21 O'REILLY, J P Region 2, Office of Director ip 22670 316 24X Fichs 50-259, 84/03/14, 8403190136
- --8403190172 Forwards IE Insp Repts 50-259/83-59, 50-260/83-59 & 50-276/83-59 on B31216 & notice of violation Notice of violation withheld (ref 100FR2 790 & 73 21)
 LEWIS,R C Division of Project & Resident Programs 84/01/20
 PARRIS,H Q Tennessee Valley Authority 2pp 22670 317 24X
 Fiche 50-259,84/03/14,8403190136
- --8403170188 IE Insp Repts 50-259/83-59, 50-260/83-59 & 50-296/83-59 on B31216 Noncompliance noted security force member failed to control access to area Details withheld (ref 100FR73 21 & 2 790)
 TILLMAN, A Region 2, Office of Director 84/01/19, 1p. 22670, 319 24% Fiche 50-259, 84/03/14,8403170136.
- 8403270117 Forwards FEMA final rept for 831015-16 emergency exercise. VERRELLI.D M Division of Project & Resident Programs 84/03/20 PARRIB.H. 0 Tennessee Valley Authority 1p 22807.027 24X Fichs 50-257, 84/03/20.6403270117.

Adjudicatory correspondence

8403200059 Submits add1 info on util initiatives in PRA, per response to 840327 ltr Effort to reduce number of violations & risks maintained FREEMAN.8 D Tennessee Valley Authority 84/03/12 MARKEY, E J House of Rep , Interior & Insular Affairs 2pp 22685 033 24X Fichs 50-239,84/03/12.8403200059

J. Insurance & indemnity information

- B403060334 Forwards Endorsement 73 to NELIA Policy NF-198 DUCK,JR Marsh & McLennan, Inc 84/02/28 SALTZMAN,J Assistant Director for State & Licensee Relations 2pp 22516 009 24X Fiche 50-289,84/02/28.8403060334
- P Operating license stage documents & correspondence
- 8403060076 Forwards request for add1 info re inservice testing of pumps & valves, in order to complete review of 820831 & 830406 submittals Response requested within 45 days of 1tr receipt VABSALLQ, D. B. Operating Reactors Branch 2 84/02/10 PARRIS. H Q Tennesses Valley Authority 4pp 22528 288 24X Fiche: 50-257, 84/02/10, 8403060076
- 8403140340 Summary of 831215 meeting w/GE & Mark I Owners Group in Bethesda,MD re Mark I containment wetwell-drywell vacuum breaker design methodology BEGGEL,B L Operating Reactors Branch 2 84/02/21 Operating Reactors Branch 2 51pp. 22635 198 24X Fiche 50-000,84/02/21, 8403140340.
- 8403010306 Application for amend to Licenses DPR-33, DPR-52 & DPR-48, changing Tech Specs to lower Group 1 isolation setpoint for reactor lower water level H/proprietary NEDE-30012, " .MSIV Water Level, "Rept withheld (ref 100FR2 790) MILLS-L M Tennessee Valley Authority 84/02/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 22433 042 24X Fiche 50-259, 84/02/22, 8403010306
- --8403010313 Proposed changes to Tech Specs lowering Group 1 isolation subpoint for reactor lower water level W/affidavit * Tennesses Valley Authority 84/02/22 29pp 22433,045 24X Fiche 50-259,84/02/22:8403010306
- B403150923 Forwards info re BNL dose reduction project plant visit Info allows BNL personnel to better prepare for station visit, expedite paperwork & minimize impact on plant personnel VASBALLO, D B Operating Reactors Branch 2 B4/02/28 PARRIS, H O Tennesses Valley Authority 46pp 22662 040 24x Fiche 50-259.84/02/28.8403150323
- B403130007 Forwards response to Generic Ltr B3-36 to NUREG-0737 Tech Bpecs MILLB.L.M. Tennessee Valley Authority B4/03/07 DENTON.H R Office of Nuclear Reactor Regulation, Director 3PP 22613 349 24X Fiche 50-259,84/03/07,8403130007
- 8403130025 Informs that add1 info requested on 831012 re reactor protection sys power monitoring sys design mods will be submitted by 840702
 MILLS.L.M. Tennessee Valley Authority. 84/03/07 DENTON.H R
 Office of Nuclear Reactor Regulation, Director ip 22614 362 24X
 Fisher 50-259, 84/03/07, 8403130025.
- B403160247 Informs of 840327 meeting to discuss proposed responses to NRC questions on Rev 7 to topical GA program per E40302 telcon LEWIS,R C Region 2. Office of Director 84/03/08 PARRIS,H G Tannessee Valley Authority ip 22660 361, 24X Fiche. 30-000.84/03/08.8403160247
- B403160373 Notifies of use of ABME Nuclear Components Code Case N32-4 for hydrostatic testing of Class 3 embedded piping NRC position re use of Code Case N32-4 requested MILLS.L. M Tennessee Valley Authority 84/03/12, DENTON, H R, Office of Nuclear Reactor Regulation, Director. ip 22660.014 24% Fiche: 50-000.84/03/12,8403160373
- 8403150275 Generic Ltr 84-07 to all licensess of BWRs re procedural guidence for pipe replacement at BWRs. Svc list encl EISENHUT, D. O Division of Licensing 84/03/14 Commonwealth Edison Co 20pp 22823,354. 24% Fiche: 50-000.84/03/14,8403150875
- 8403200170 Forwards response to Item 4 5 of Generic Ltr 83-28,

 "Required Actions Based on Generic Implications of Balem
 ATMS Events" re reactor trip sys reliability Control rod
 tests check rod insertion times & hydravlic screm valves

 MILLS.L. M Tennessee Valley Authority 84/03/15 DENTON.H R
 Office af Nuclear Reactor Regulation, Director 10pp 22700 024
 24X Fiche.50-259,84/03/15,8403200170

- 8403240229 Forwards addl info me test configuration & results of verification testing, per 840106 request re adequacy of station electric distribution sys voltages Test results indicated no unexpected voltage levels
 MILLS.L M Tennessee Valley Authority 84/03/19 DENTON, H R
 Office of Nuclear Reactor Regulation. Director 26pp 22796 124
 24X Fiche 50-259.84/03/19.8403260229
- Q Inspection reports, IE Bulletins & correspondence
- 8403070054 Responds to NRC ltr re violations noted in 1E Insp Repts 50-239/83-09,50-260/83-07 & 50-294/83-09 List of identified deficiencies & implementation schedule provided to senior NRC inspector on 830901 MILLS.L M Tennessee Valley Authority 83/09/15 0'REILLY,J P Region 2. Office of Director 1p 22347 261 24X Fiche 50-259,83/09/15,8403070054
- 8403070237 Updates 830715 response to NRC 830616 ltr re violations noted in IE Insp Repts 50-259/83-19.50-260/83-19 & 50-296/83-19 Operating instructions revised & Units 2 & 3 PBC charging sys operational MILLS.L M Tennessee Valley Authority 83/09/30 O'REILLY, J P Region 2, Office of Director. 1p 22541 361 24X Fiche 50-259,83/09/30,8403070237
- 8403070271 Supple 830830 response to NRC ltr re violations noted in IE Insp Repts 50-257/83-23,50-260/83-23 & 50-276/83-23 Boral test specimen installation will be delayed until 831028 due to late recvipt of matis per 831012 telcon KAMMER, D B Tennessee Valley Authority 83/10/21 0'REILLY, J P Region 2, Office of Director ip 82546 336 24% Fiche 50-259,83/10/21,8403070271
- 8403070023 Responds to NRC 1tr re violations noted in IE Insp Repts 50-259/83-27.50-260/83-27 & 50-296/83-27 Corrective actions compliance w/instructions will be achieved & corrective actions will be completed before Cycle & operation MILLS.L.M. Tennesse Valley Authority 83/10/27 O'REILLY, J. P. Region 2. Office of Director ip 22541 262 24X Fiche 50-259,83/10/27,8403070023
- 8403070067 Forwards IE Insp Repts 50-259/83-50,50-260/83-50 & 50-296/83-50 on 830912-16 & 26-30 Unresolved item repossible high radiation doses measured by personnel dosimeters; discussed on 831028; considered closed O'REILLY, J P. Region 2, Office of Director 84/01/11 PARRIS, H O Tannessee Valley Authority 2pp 22545 341 24X Fiche 50-259,84/01/11,8403070067
- --8403070072 IE Insp Repts 50-259/83-50.50-260/83-50 & 50-296/83-50 on 831028 No violations or deviations noted Major areas inspected TLD & multiple badging DEBS.B T Region 2. Office of Director 93/12/05 5pp 82545 343 24X Fiche 50-289.84/01/11.8403070067
- 8403160232 Forwards IR Insp Repts 50-259/84-04,50-260/84-04 & 50-296/84-04 on 840123-27 No violations or deviations noted VERRELLIID M Division of Project & Resident Programs 84/02/16 PARRIGH 0 Tennessee Valley Authority 2pp 22661 027 24x Fiche 50-259,84/02/16,8403160232
- --B40316023B IE Insp Repts 50-259/84-04, 50-260/84-04 & 50-296/84-04 on 840123-27 No violations or deviations noted Major areas inspected startup testing new fuel receipt plant tours & MBIV repair status

 DAVENPORT.K E Region 2, Office of Director JAPE.F Division of Engineering & Operational Programs 84/02/14 Spp 22661 031 24X Fiche 50-259,84/02/16,8403160232.
- 8401190072 IR Info Notice 84-13, "Potential Deficiency in Motor Operated Valva Control Circuits & Annunciation " Svc list ent!

 JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 113pp 22707 237 24X Fichs 50-000.84/02/28.8401170072
- 8403160162 Ack receipt of 840222 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-257/83-57, 50-260/83-57 & 50-296/83-57 b. 10-260/83-57 & 50-296/83-57 b. LEMIS.R C. Division of Project & Resident Programs, 84/02/29 PARRIS.H G. Tennessee Valley Authority ip. 22655 273 24X Fiche. 50-239, 84/02/29, 8403160162
- --8403160171 Responds to NRC 840123 ltr re violations nated in IE Insp Repts 50-259/83-57,50-260/83-57 & 50-296/83-57 Corrective actions policy statement issued to health physics technicians re high radiation area doors MILLS.L M Tennesses Valley Authority 84/02/22 O'REILLY, J P Region 2, Office of Director 5pp 22655 274 24X Fiche 50-259,84/02/29,8403160162

- --8403160178 Forwards IE Insp Repts 50-259/83-57, 50-260/83-57 & 50-296/83-57 on 831126-1225 & notice of violation LEHIS,R C Division of Project & Resident Programs 84/01/23 PARTIS,H G Tennessee Valley Authority 2pp 22655 279 24X Fichs 50-259,84/02/29,8403160162
- --8403160181 Notice of vialation from insp on 831126-1225 * Region 2. Office of Director 84/03/23 2pp 22655 281 24X Fiche 50-259,84/02/29,8403160162
- --8403i60186 IE Insp Repts 50-259/83-57.50-260/83-57 & 50-296/83-57 on 831126-1225 Violations noted failure to lock high radiation area to follow special work permit & to have adequate fire protection maint procedure PAULK.6 L Region 2. Office of Director CANTRELL.F 8 Division of Project & Resident Programs 84/01/21 6pp 22655 283 24X Fiche 50-259,84/02/29,8403160162
- 8403160219 Ack receipt of 840207 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-40, 50-280/83-40 & 50-280/83-40 LEWIGHR C Division of Project & Resident Programs 84/03/01 PARRIS.H G Tennessee Valley Authority ip 22661 098 24X Fichs-50-259,84/03/01.8403160218
- --8403160223 Responds to NRC 840111 ltr re violations noted in IE Insp Repts 50-259/83-40.50-260/83-40 & 50-276/83-40 Corrective actions radialogical energency planning program reviewed & areas requiring rev identified MILLS.L M Tennessee Valley Authority 84/02/09 O'REILLY, J P Region 2, Office of Director. App. 22661 077 24X Fiche 50-259.84/03/01.8403160218
- --8403160230 Forwards IE Insp Repts 50-299/83-40, 50-260/83-40 t 50-296/83-40 on B31017-21 t 1122 t notice of violation LEWIS:R C Division of Project & Resident Programs 84/01/11 PARTS:H Q Tennessee Valley Authority 2pp 22661 105 24X Fiche 50-259,84/03/01,8403160218
- --8403160237 Notice of violation from insp on 831017-21 & 1122 * Region 2. Office of Director 84/01/11 3pp 22661 107 24X Fiche 50-259,84/03/01,8403160218
- --8403160244 IE Insp Repts 50-259/83-40, 50-260/83-40 & 50-296/83-40 on 831017-21 & 1122 Noncompliance noted failure to control documents properly train emergency personnel in protective action requirements & incorporate protective action DECKER.T R. STODDART.P & Region 2, Office of Director JENKINS.G R Division of Emergency Preparedness & Materials Safety 84/01/04 9pp 22661 110 24% Fiche 50-259,84/03/01. 8403160218
- B402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE, J N Division of QA, Bafeguards & Inspection Programs (Post B30103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24% Fiche 50-000,84/03/02,8402090007
- 8402070008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list entl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22953 098 24X Fiche 50-000.84/03/02.8402070008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases." Byc list encl JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- B4030B02i3 EN-84-007 on B40307, notice of violation & proposed imposition of civil penalties in amount of 440,000 to be issued Action based on failure to control access into vital area due to guard leaving post ROSAND, R , AXELRAD, J Director's Office, Office of Inspection and Enforcement 84/03/02 ip 22540 021 24X Fiche 50-259,84/03/02,8403800213
- B402070011 IE Info Notice B4-17, "Problems W/Liquid Nitrogen Cooling Components Below N(1 Ductility Temp " Svc list encl JURDAN, E. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22593 336 24% Fich 50-000,84/03/05,8402070011
- 8403160308 Ack receipt of 840217 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 30-259/83-36 LEWIS,R C Division of Project & Resident Programs 84/03/05 PARRIS,N G Tennesses Valley Authority ip 22660 085 24X Fiche: 50-259, 84/03/05, 8403160308

- --8403160318 Responds to NRC 840117 ltr re violations noted in IE Insp Repts 50-259/83-56.50-260/83-36 & 50-296/83-56 Corrective actions 10% retest sample calculation made for all snubbers within Category/Group 3 MILLS.L M Tennessee Valley Authority 84/02/17 O'RETLLY.J P Region 2. Office of Director 2pp 22660 086 24x Fiche 50-259,84/03/05.8403160308
- --8403160328 Forwards IE Insp Repts 50-259/83-56, 50-260/83-56 & 50-296/83-56 on 831213-16 & notice of violation LEWIS:R C Division of Project & Resident Programs 84/01/17 PARTIS:H G Temnessee Valley Authority 2pp 22660 088 24X Ficha 50-259,84/03/05,8403160308
- --8403160339 IE Insp Repts 50-259/83-56, 50-260/83-56 & 50-296/83-56 on B31213-16 Violation noted failure to test add1 10% sample for each snubber that failed functional test HHITENER.H L. Region 2, Office of Director JAPE.F Division of Engineering & Operational Programs 84/01/10 8pp 22660 091 24% Fiche 50-239,84/03/05,8403160308
- 8403290237 Forwards IE Insp Repts 50-259/84-05.50-260/84-05 & 50-276/84-05 on 840130-0201 No violations or deviations identified.

 VERRELLI.D.M Division of Project & Resident Programs. 84/03/05 PARRIE, H 0 Tennessea Vailey Authority 2pp 22800 229 24X Fiche 50-259.84/03/05.8403290237
- --B403270239 IE Insp Repts 50-259/B4-05, 50-260/B4-05 & 50-296/B4-05 on 840130-0201 No violations or deviations identified Major areas inspected followup of IE Bulletin 81-03, review of LERs re bulletin & procedures for flow reverification tasts CUNNINGHAN, A L. Region 2, Office of Director. MONTODMERY, D M Division of Engineering & Operational Programs 84/03/02 5pp 22800 231 24X Fiche 50-259,84/03/05,8403270237
- 8402090024 IE Info Notice 84-09. Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl URDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049. 24% Fiche. 50-000.84/03/07, 8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR 8ys " Svc list enc! JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584.186 24X Fiche 50-000,84/03/07,8402090028
- B403160273 Forwards IE Enforcement Conference Repts 50-259/84-06, 50-260/84-06 & 50-296/84-06 on 840224 O'REILLY, J. P. Repton 2, Office of Director 84/03/08 PARRIS, H G Tennessee Valley Authority. 2pp 22661 004 24X Fichs 50-259, 84/03/08, 8403160273
- --8403160282 IE Enforcement Conference Repts 50-259/84-06, 50-260/84-06 & 50-296/84-06 on 840824 Major items discussed bypassing rod sequence control sys while shutting down & isolation of drywell to pool pressure instrument BUTCHER.R C Region 2, Office of Director CANTRELL, F 8 Division of Project & Resident Programs 84/02/29 4pp 22661 006 24X Fiche 50-257,84/03/08.8403160273
- 8402090031 IE Bulletin 84-02. "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Syc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823.094 24X Fiche: 50-000,84/03/12,8402090031
- 8403190136 Ack receipt of 840221 & 0312 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-59, 50-260/83-59 & 50-296/83-59 Responses meet 10CFR2 201 requirements LEWIS.R C Division of Project & Resident Programs 84/03/14 PARRIS.H 0 Tennessee Valley Authority 1p 22670 314 24X Fiche 50-259,84/03/14,8403190136.
- --8403190149 Supple response to NRC 840120 ltm re violations noted in IE Insp Repts 50-259/83-59, 30-260/83-59 & 50-296/83-59 Responses withheld (ref 10CFR73 21), MILLS, LM Tennessee Valley Authority 84/03/12 0'REILLY, J P. Region 2. Office of Director ip 22670 315 24% Fiche 50-259,84/03/14,8403190136
- ---8403190161 Responds to NRC 840120 ltr re violations noted in IE Insp Repts 50-259/83-59,30-260/83-59 & 50-296/83-59 Responses withheld (ref 10CFR73 21) MILLS,L M Tennessee Valley Authority 84/02/21 0'REILLY, J P Region 2, Defice of Director 1p. 22670 316 24X Fiche 50-259,84/03/14,8403190136

- --8403190172 Forwards IE Insp Repts 50-259/83-59, 50-260/83-59 & 50-296/83-59 on 831216 & notice of violation Notice of violation withheld (ref 10CFR2 790 & 73 21)
 LEWIS,R C Division of Project & Resident Programs 84/01/20
 PARRIS,H G Tannesses Valley Authority 2pp 22470 317 24)
 Fichs 50-259,84/03/14,8403190136
- --8403170188 IE Insp Repts 50-259/83-59, 50-260/83-59 & 50-296/83-59 on B31216 Noncompliance noted security force member failed to control access to area Details withheld (ref 100FR73 21 & 2 790)

 TILLMAN, A. PATTERSON, C. Region 2. Office of Director MCOUIRE, D.R. Division of Emergency Preparedness & Materials Bafety 84/01/19 ip 22670 317 24X Fiche 50-259, 84/03/14, 8403190136
- 8403270047 Summarizes 840312 meeting in Region II ofc re planned util organizational changes & regulatory performance improvement program for facility D'REILLY.JP Region 2. Office of Director 84/03/15 PARRIS.H Q Tannessee Valley Authority 1p 22806.271 24X Fiche 50-257,84/03/15,8403270047
- 8403290178 Ack receipt of 840217 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-297/83-38. 50-240/83-38 & 50-296/83-38 LEWIS,R C Division of Project & Resident Programs 84/03/20 PARRIB,H 9 Tennessee Valley Authority ip 22800 278 24X Fiche: 50-259,84/03/20,8403290178
- --8403290183 Suppls response to NRC 840119 ltr re violations notad in IE Insp Repts 50-259/83-38 50-260/83-38 & 50-296/83-38 Corrective actions distribution of insp rept to health physics personnel initiated MILLS.L M Tannessee Valley Authority 84/02/17 D'REILLY, J P Region 2, Office of Director Rpp 22800 279 24X Fiche 50-259,84/03/20,8403290178
- ---8403290190 Ack receipt of 831209 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-38, 50-260/83-38 & 50-296/83-38
 O'REILLY, J P Region 2, Office of Director 84/01/19
 PARRIS, H O, Tennesses Valley Authority 2pp 22800 281 24X
 Fichs 50-259,84/03/20,8403290178
- --8403290203 Ack receipt of 831209 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-38.
 50-260/83-38 & 50-296/83-38
 LEHIB.R C Division of Project & Resident Programs 83/12/21
 PARRIE.H O Tennessee Valley Authority 1p 22800 283 24X
 Fichs. 50-259, 84/03/20, 8403290178
- --B403290207 Responds to NRC B31109 ltr re violations noted in IE Insp Repts 50-259/83-38,50-260/83-38 & 50-294/83-38 Corrective actions insp rept distributed to health physics personnel & RCI-5 revised to incorporate lo
- --8403270211 Forwards IE Insp Repts 50-259/83-38, 50-260/83-38 & 50-276/83-38 on 830912-16 & notice of violation LEMIS.R C Division of Project & Resident Programs 83/11/09 PARTIS.H 0 Tennessee Valley Authority 2pp 22800.289 24) Fichs 50-259, 84/03/20, 8403270178
- --8403270214 Notice of violation from insp on 830712-16 * Region 2, Office of Director 89/11/09 2pp 22800 271 24X Fichs. 50-259, 84703/20.8403270178
- --8403290220 IE Insp Repts 50-259/83-38, 50-260/83-38 & 50-296/83-38 on 830912-16 Violations noted 55-gallon drum reading 30 to 65 millirem per hour observed unlabeled & radiation control procedures not prepared or adhered to DEBS, B T. Region 2, Office of Director BARR, K P Division of Engineering & Operational Programs 83/11/03 App. 22800 293 24X Fiche 50-259, 84/03/20, 8403290178
- 8402070043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000,84/03/21,8402090043
- B402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Bys." Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000, B4/03/21, 8402090044

- R Periodic operating reports & related correspondence
- B403020103 Monthly operating repts for Jan 1984 W/B40210 ltr CHAPMAN.M. THOM.T. JONES.O T Tennesses Valley Authority B4/01/31 41pp 22443 166 24X Fiche 50-259.84/01/31.B403020103
- 8403300133 Forwards monthly operating repts for Feb 1984 & corrected Jan 1984 monthly operating rept for Unit 1 JUNES.G T Tennessee Valley Authority 84/03/09 Office of Resource Management, Director 1p 22820 203 24X Fiche 50-259.84/03/09,8403300133
- --8403300136 Monthly operating repts for Feb 1984 THDM.T Tennessee Valley Authority 84/02/29 37pp 22820 204 24% Fiche 50-259,84/03/09,8403300133
- 8 Reportable occurrences, LERs & related correspondence
- 8403260233 Forwards summary list of deficiencies identified per iOCFR50 55(e).Part 21 & potential generic itr repts for comments
 STAROSTECKI.R Division of Project Resident Programs 84/02/28
 Region i. Office of Director 7pp 22756 065 24X
 Fiche 50-000.84/02/28,8403260233
- B403130181 LER B4-003-00 on B40212, routine survaillance testing stopped because operator unable to bring HPC1 turbine speed down to required 2,400 rpm Caused by erratic ramp generator/signal converter box adjustment W/840306 ltr
 SMITH.D L., JONES.G T Tannesses Valley Authority B4/03/06 3pp 22617 324 24X Fiche 50-260. B4/03/06, B403130181
- 8403200171 Followup LER 82-028/03X-3 on 810921, turbine reactor bldg Doors 237 & 238 opened simultaneously, breaching secondary containment Caused by failed Folger Adams interlock sys due to loose door latch screws Procedures revised W/840309 ltr CARTER, B., JONES, C.T. Tennessee Valley Authority 84/03/09 0'REILLY, J.P. Region 2, Office of Director 3pp 22699 353 24X Fiche 50-260,84/03/09,8403200171
- 8403220159 LER 84-004-00 on 840222 during startup, reactor scrammed Caused by high flux spike on channels C & F of intermediate range monitors Plant written procedures & nuclear engineer qualification program revised W/840315 ltr MORKIN, K M , JONES, G T Tennessee Valley Authority 84/03/15 3pg 22715 331 24X Fiche 50-260,84/03/15,8403220159
- V Operator Examinations
- 8403160227 Confirms 840302 meeting in Atlanta, CA re 840319 operator requalification exam.per 840227 telcon
 LEWID.R C Division of Project & Resident Programs 84/03/01
 PARRIS, H G Tennessee Valley Authority Ip 22660 328 24X
 Fiche 50-259.84/03/01,8403160227
- B403290322 Discusses B40J17 ltr confirming arrangements for administration of requalification exams. Random selection process used to determine identify of examinees for written & orel exams List of examinees encl
 LEWIG.R C Division of Project & Resident Programs B4/03/13 PARRIS, H O Tennessee Valley Authority 3pp 22802 049 24X Fichs 50-259,84/03/13,8403290322
- 8403270213 Summarises 840302 meeting w/util re 840323 requalification exam of licensed operator & senior operator personnel at facilities Meeting provided better understanding of operator requalification training & exam programs

 LEWIS.R C Division of Project & Resident Programs 84/03/15

 PARRIS,H G Tennessee Valley Authority 3pp 22800,340 24X

 Fiche:50-259.84/03/15,8403270213
- DOCKET 50-261 H B ROBINSON PLANT, UNIT 2
- F. Becurity, medical, emergency & fire protection plans
- 8403160385 IE Insp Rept 50-241/84-02 on 840111-0210 No violations or deviations identified Major areas inspected Tech Spec compliance, plant tour, operations performance. ROs. houseleeping, site security, surveillance & maint ectivities WEISE.5. MYERG.D Region 2. Office of Director BEMIS.P R Division of Project & Resident Programs 84/02/16 12pp 22660.002 24X Fiche 50-261.84/02/17.8403160382
- B403160382 Forwards IE Insp Rept 50-261/84-02 on B40111-0210 No violations or deviations identified VERRELLI,D M Division of Project & Resident Programs B4/02/17 UTLEY,E E Carolina Power & Light Co ip 22660-001 24X Fichs 50-261,84/02/17,8403160382

- 8403060508 Forwards order confirming util commitments to implement requirements of Suppl i to NUREC-0737 Order based on conmitments contained in util 840415 & 830824 responses to 821217 Generic Ltr 82-33 D&LEI/ GENERIC Ltr 82-33 VARGALS A Operating Reacturs Branch 1 84/02/21 UTLEY.E E Carolina Power & Light Co 3pp 22552 165 24X Fiche SC-261.84/02/21.8403060508
- --8403060510 Order confirming licensee commitments on emergency response capability, per Generic Ltr 82-33, Suppl 1 to NUREG-0737 EISENHUT, D © Division of Licensing 84/02/21 Carolina Power & Light Co 6pp 22552 168 24X Fiche 50-261, 84/02/21, 8403060508
- 8403140249 Ack receipt of 840217 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 30-261/83-35 Implementation of corrective actions will be examined during future insps LEWIS.R C Division of Project & Resident Programs E UTLEY.E E Carolina Power & Light Co 1p 22660 299 Fiche 30-261.84/02/29.8403160249
- --B403160262 Responds to NRC B40118 ltr re violations noted in IE Insp Rept 50-261/83-35 Corrective actions Emergency Procedure PEP-105 will be revised to implement recommendations of IE Info Notice B3-28 & NUREG-0654 MGRGAN: R E Carolina Power & Light Co B4/02/17 O'REILLY, J P Region 2. Opfice of Director 3pp 22660 300 24% Fiche 50-261:84/02/29.8403160249
- --B403160300 IE Insp Rept 50-261/B3-35 on B31205-09 Violation noted IE Info Notice 83-28 guidance not incorporated into Emergency Procedure PEP-105, "Emergency Control General Emergency " STODDART.P g Ragion 2, Office of Director JENKINS,0 R Division of Emergency Preparedness & Materials Safety 84/01/11 7pp. 22660 305 24X Fiche 50-261.84/02/29,8403160249
- 8403200245 Revised emergency implementing procedures, including Rev 1 to Procedure PEP-503, "Administration of Radioprotective Drugs" & Rev 1 to Procedure PEP-653, "Performance of Training, Exercises & Drills "W/840316 ltr MCRQAN.R E Carolina Pawer & Light Co 84/02/29 C'REILLY, J P Region 2. Office of Director 15pp 22691 120 24X Fichs 50-261,84/02/29,8403200245
- 8403160283 Advises of 840316 meeting in Region II ofc to discuss App R requirements & results of recent App R insps Attendance should be limited to six util employees LEHIS.R C Division of Project & Resident Programs 84/03/02 UTLEY, E E Carolina Power & Light Co ip 22660 109 24X Fiche 50-000.84/03/02.8403160283
- 8403070074 Supple 831025 request for exemption from requirements of 10CFR73 55 for portion of steam generator repair program Encl withhelf (ref 10CFR73 21) UTLEY: E E Carolina Power & Light Co 84/03/05 Operating Reactors Branch | 2pp 22571 114 24x Fiche 50-261:84/03/05:8403090094 84/03/05 VARGA, S A
- 1403230127 Revs 0 & 4 to Emergency Plan Implementing Procedure PEP-105 "Emergency Control General Emergency " W/840320 ltr MCRGAN.R E Carolina Power & Light Co 84/03/20 O'REILLY, J P Region 2. Office of Director 14pp 22730 193 24x Fiche 50-261.84/03/20.8403230127
- P Operating license stage documents & correspondence
- 8403060470 Discusses negotiations w/licensee on NUREO-0737 Items re emergency operating procedures.per 830601 & 0712 memos REGUA-6 Operating Reactors Branch i 83/07/07 EISENHUT, D Q Division of Licensing ip 22347 326 24X Fiche 50-261,83/09/09.
- 8403010230 Notification of 840228 meeting w/util in Bothesda.MD to discuss multi-plant actions.TMI action items & specific open items REGUA.0 Operating Reactors Branch 1 84/02/2 Operating Reactors Branch 1 2pp 22479 195 Fiche 50-261.84/02/21.8403010R30 84/02/21 79 195 24x VARGALE A
- 8403040005 Forwards Amend 77 to License DPR-23, ASLB order dismissing AUGURATION AREND // to Litense DPR-23,ASLB order dismi proceeding & notice of issuance Amend approves stwam generator repair program & provides licensing conditions re repair operation W/o ASLB order REGUA,O Operating Reactors Brench 1 84/02/28 UTLEY,E E Carolina Power & Light Co 3pp 22528 354, 24X Fiche 50-261,84/02/28,8403060005
- -8403060009 Amend 77 to License BPR-23, approving Steam generator repair program & providing license Opar-23 approving steam generator rep. program & providing licensing conditions re repair operation ETSENHUT.D O Division of Licensing 84/02/28 3pp 22528 357 24X Fiche 50-261,84/02/28.8403060005

- --8403060012 Notice of issuance & availability of Amend 77 to License DPR-23 VARQA,8 A Operating Reactors Branch 1 84/02/ 22528 360 24% Fiche 50-261,84/02/28.8403060005 84/02/2B 3cm
- 8403050R17 Forwards request for addl info re TMI Item II D 3 4, "Control Room Habitability " Response requested within 45
 - "Control Noom Masicability " Response requested within 45 days of receipt of ltr VARGA.8 A Operating Reactors Branch 1 84/02/29 UTLEY.E E Carolina Power & Light Co 4pp 22528 139 24X Fiche 50-261.84/02/29:8403050217
- 8403130093 Forwards util resolution of generic environ qualification of safety-related electrical equipment deficiencies discussed in 830105 8ER CUTTER, A B Carolina Power & Light Co 84/03/02 VARGA, 8 A Operating Reactors Branch i 46pp 22614 215 24X Fiche 80-261.84/03/02.8403130093
- 840315016: Application to amend License DPR-23, requesting blanket approval to transfer slightly contaminated sediment from settling pands to facility ash ponds using either hydrovacuum truck or direct piping/slutining method UTLEY.E E Carolina Power & Light Co 84/03/09, VAROA.8 A Operating Reactors Branch i 3pp. 22640 059 24X Fiche 50-261.84/03/09,8403150161
- --8403130163 "Transfer of Blightly Contaminated Bediment to Ash Pond via Ash Bluice Sys," SAR * Carolina Power & Light Co 83/01/19 27pp 22640 062 24X Fiche 50-261,84/03/09,8403150161
- 8403210093 Provides addl info re adequacy of electrical distribution voltage sys.per 840119 request Criteria used in selecting undervoltage & overvoltage alarm setpoints for 115-kV grid voltage discussed.

 CUTTER, A.D. Carolina Power & Light Co. 84/03/09 VARGA, 8 A Operating Reactors Branch 1 18pp 22705 339 24X Operating Reactors Branch 1 18 Fiche 50-261,84/03/09,8403210093
- 8403210116 Forwards addl info re power distributions as part of pressurized thermal shock program to effect flux reduction, per 830930 submittal, in response to 840301 telton ZIMMERMAN, BR Carolina Power & Light Co 84/03/12 VAROA, BA Operating Reactors Branch 1 3pp 22705 064 24X Fiche 50-261,84/03/12,8403210116
- 8403300225 Requests remittance of Class V fee for 820701 application for steam generator repair program EI8 prepared to assess major environ impact of occupational radiation exposures associated w/proposed repair of steam generator MILLER.W O License Fee Management Branch 84/03/14 JUNES, J. A Carrolina Power & Light Co 2pp 22845 037 24X Fiche 30~261.84/03/14.8403300225.
- 8403270235 Application for amend to License DPR-23 revising Tech Specs re immediate notification requirements for LER sys CUTTER, A B Carolina Power & Light Co 84/03/21 VAROA, S A Operating Reactors Branch 1 2pp 22772, 033 24X Fiche 50-261, 84/03/21, 8403270235
- --8403270239 Proposed Tech Specs re immediate notification requirements of LER sys * Carolina Power & Light Co B Fichs 50-261,84/03/21,8403270235 84/03/21 30pp 22772 035 24X
- G Inspection reports, IE Bulletins & correspondence
- 8402140187 Forwards IE Insp Rept 50-261/83-37 on 831215-16 No violations or deviations noted VERRELLI.D M Division of Project & Resident Programs 84. UTLEY, E.E. Carolina Power & Light Co. 2pp. 22228 355. 2: Fiche: 50-261 t Programs 84/01/10 22228 355. 24X
- --8402140193 IE Insp Rept 50-261/83-37 on 831215-16 No violations or deviations noted Major areas inspected RCS leak rate measurement measurement
 BURNETT:PT Region 2, Office of Director JAPE,F Division of
 Engineering & Operational Programs. 84/01/10 5pp. 22228:357
 24% Ficha:50-261,84/01/10,8402140189
- 8403160382 Forwards IE Insp Rept 50-261/84-02 on 840111-0210. No violations or deviations identified.

 VERRELLI, D. M. Division of Project & Resident Programs 84/0:

 UTLEY. E. E. Carolina Power & Light Co. 1p. 22660-001. 24X

 Fiche: 50-261,84/02/17.8403160382 84/02/17

- --8403160385 IE Insp Rept 50-261/84-02 on 840111-0210 No violations or deviations identified Major areas inspected Tech Spec compliance.plant tour.operations performance.ROs. housekeeping.site security.surveillance & maint activities HEISE.8 . MYRRS.D Region 2. Office of Director BEMIS.P.R Division of Project & Resident Programs 84/02/16 12pp 28660 002 24X Fiche 50-261.84/02/17.8403160382
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Syc list encl
 - enci JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22909 239 24X Fiche 50-000,84/02/28,8401190072
- 8403160249 Ack receipt of 840217 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-261/83-35 Implementation of corrective actions will be examined during future insps

 LEMIS.R C. Division of Project & Resident Programs 84/02/29 UTLEY.E E Carolina Power & Light Co 1p 22660 299 24X Fiche 30-261,84/02/29.8403160249
- --8403160262 Responds to NRC 840118 ltr re violations nated in IE Insp Rept 50-261/83-35 Corrective actions Emergency Procedure PEP-103 will be revised to implement recommendations of IE Info Notice 83-28 & NUREO-0654 MORGAN.R E Carolina Power & Light Co 84/02/17 O'REILLY, J P Region 2, Office of Director 3pp 22660 300 24X Fiche 50-261.84/02/29.8403160249
- --B403160275 Forwards IE Insp Rept 50-261/B3-35 on B31205-07 & notice of violation W/o notice of violation LEWIB.R C Division of Project & Resident Programs 64/01/18 UTLEY.E E Carolina Power & Light Co 2pp 22660 303 24X Fiche 50-261.84/02/29,8403160249
- --8403160300 IE Insp Rept 50-261/83-35 on 831205-09 Violation noted IE Info Notice 83-28 guidance not incorporated into Emergency Procedure PEP-0105, "Emergency Control General Emergency " BYODDART, P.O. Region 2, Office of Director JENKINS, O.R. Division of Emergency Preparedness & Materials Safety 84/01/11 7pp 22660 305 24% Fiche 50-261,04/02/29,8403160249
- B402070007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl QRACE, J N Division of GA, Bareguards & Inspection Programs (Post B30103) B403/02 Consolidated Edison Co of New York, Inc 130pp 22552,327 24X Fiche 50-000.84/03/02.8402070007
- 8402090008 IE Info Notice 84~16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000.84/03/02,8402090008
- B402090009 IE Info Notice 84-15. "Reporting of Radiological Releases"

 Byc list encl

 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc. 119pp 22553 217 24% Fiche 50-000.84/03/02.8402090009
- 8402070011 IE Info Notice 84-17, "Problems W/Liquid Nitragen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8402090024 IE Info Notice 84-09. Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown 8ys " Syc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24% Fichs 50-000,84/03/07,8402090024
- 8402090028 IE Info Notice 84~18, "Stress Corrosion Cracking in PWR Sys." Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584:186 24X Fiche 50~000:84/03/07,8402090028
- 8403160267 Forwards IE Enforcement Conference Repts 50-261/84-08 & 30-400/84-08 on 840223 of REILLY.J P. Region 2. Office of Director 84/03/09 UTLEY, E Carolina Power & Light Co. Rpp. 22660 275 24X Fichs 50-000, 84/03/09, 8403160267
- --B403160274 IE Enforcement Conference Repts 50-261/84-08 & 50-400/84-08 on 840223 Major areas discussed unauthorized entry into facility reactor cavity & GA programs re procurement of sycs & matts
 VERRELLI,D,M Division of Project & Resident Programs B4/03/06
 3pp 22660:277 24X Fiche 50-000.84/03/09,8403160227

- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl DEYOUNG.R C Director's Diffice. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York. Inc 134pp 22823 094 24X Fiche 50-000.84/03/12,8402090031
- B403300324 Discusses IE insp on B40221 & forwards notice of violation & proposed imposition of civil penalty O'REILLY, J P Region 2, Office of Director 84/03/13 UTLEY, E E Carolina Power & Light to 2pp 22842 312 24X Fiche 50-261.84/03/13.8403300224
- --8403300327 Notice of violation & graposed imposition of civil penalty in amount of \$30.000 Violation noted health physics technician failed to perform adequate surveys for licensed operator when untry made into reactor keyway sump O'REILLY, J.P. Region 2. Office of Director 84/03/13 4pp 22842 319 24X Fiche 50~261.84/03/13.8403300324
- 8402090043 IE Infa Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JURDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 227 24X Fiche 50-000,84/03/21,8402090043
- 8402070044 IE Info Notice 84-20. "Svc Life of Relays in Safety-Related Bys " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 139pp 22733 001 24X Fiche 50-000,84/03/21,8402070044
- $\ensuremath{\Re}$ Periodic operating reports & related correspondence
- 8403080135 Monthly operating rept for Jan 1984 W/B40302 ltr SCOTT.A E : NORRIS.H R : MORGAN.R E Carolina Power & Light Co 84/01/31 DEYQUNG.R C Director's Office. Office of Inspection and Enforcement 4pp 22559 279 24X Fiche 50-261.84/01/31.8403080135
- 8403080258 Monthly operating rept for Feb 1984 W/840302 ltr NCRRIS.H R. SCOTT.A E. MCROAN.R E. Carolina Power & Light Co 84/02/27 DEYOUNG.R C. Director's Office, Office of Inspection and Enforcement 4pp 22557 117 24X Fiche 50-261.84/02/29.8403080258
- S Reportable occurrences, LERs & related correspondence
- 8403150098 Special rept on 840131, six hose stations, seven non-Tech Spechose stations & two hydrants inoperable due to isolation of water loop for bldg const Addl support for rerouted fire water piping provided MORGAN, R E Carolina Power & Light Co 84/03/06 O'REILLY, J P Region 2, Office of Director ip 22640 362 24X Fiche 30-261.84/03/06.8403130098
- B403130445 EN-84-007 on B40312, notice of violation & proposed imposition of civil penalty in amount of \$30,000 will be issued based on failure of Tech Specs procedures re entry into locked high radiation area FLACK, E. AXELRAD, J. Director's Office, Office of Inspection and Enforcement B4/03/07 2pp 22613 138 24X Fiche 50-261,84/03/07,8403130445
- DOCKET 50-262 BRIGHAM YOUNG UNIV RESEARCH REACTOR

 O Inspection reports, 1E Bulletins & correspondence
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc. 115pp 22909 239 24X Fiche 50-000.84/02/28,8401190072
- B402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE, J N Division of GA, Safeguards & Inspection Programs (Post B30103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 327 RAX Fiche 50-000,84/03/02,8402090007
- 8402090008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 930109) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008
- B402090009 IE Info Notice 84-i5, "Reporting of Radiological Releases" Svc list encl
 JDRDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/02 Consolidated Edison Co of New York, Inc 119pp 22353 217 24X Fiche 50-000,84/03/02.8402090009

- 8402090011 IE Info Natice 84-17, "Problems W/Liquid Nitrogen Cooling Components Delow Nil Ductility Temp " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000.84/03/05.8402090011
- 8402090024 IE Info Notice 84-09, Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000,84/03/07,8402090024
- 8402090028 IE Info Notice 84-18. "Stress Corrosion Cracking in FWR Sys " Syc list enc! JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post B30103) B4/03/07 Consolidated Edison Co of New York, Inc. 118pp 22584 186 24X Fishe 50-000,84/03/07,8402090028
- 8402070031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Bafety Sys " Svc list encl BEYDUNG: R C Birector's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp. 22823 074 24X Fichs 50-000:84/03/12:8402070031
- 8402070043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PHR Reactor Cavities" Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000.84/03/21,8402090043
- 8402070044 IE into Notice 84-20, "Evo Life of Relays in Safety-Related Sys " Svot list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24% Fiche 50-000,84/03/21,8402070044

DOCKET 50-263 MONTICELLO NUCLEAR GENERATING PLANT

- F Security, medical, emergency & fire protection plans
- B403060041 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee, per Bi0709 Generic Ltr 81-27 W/o request, entire plan will be placed in PDR VASSALLO, D B Operating Reactors Branch 2 84/02/10 MUSOLF, D M Northern States Power Co 2pp 22528 325 24% Fiche 50-263,84/02/10,8403040041
- 8403060285 Rev 5 to Emergency Plan Implementing Procedure A 2-106. "Activation of Technical Support Ctr " H/84030; ltr & list of current pages BRURG, R L , SCHEINERT.R L , FEY.F L Northern States Power Co 84/02/28 8pp 22819 207 24X Fiche 50-263,84/02/28,8403060285
- 8403060185 Ack receipt of 840207 ltr transmitting Rev 14 to security plan Rev consistent w/provisions of 10CFR50 84(p) & acceptable
- plan New Consistent Exprovisions of Journal Step. & acceptable AXELBON.W L Region 3. Office of Director 84/03/01 MUSDLF, D M Northern States Power Co 2pp 22518 359 24X Fiche 50-263,84/03/01.8403060183
- 8403080238 Forwards "Monticello Nuclear Power Plant Site-Specific Offsite Radiological Emergency Preparadness Evaluation" & "Monticello Nuclear Power Plant Full-Scale Joint Emergency Eiserise on 830223, "fanal rept KRIMM, R W Federal Emergency Management Agency 84/03/05 Federal Emergency Management Agency 3pp 22560 127 24x Fiche 50-263,84/03/05,8403080238
- --8403080242 "Monticello Nuclear Power Plant Site-Specific Officite Radiological Emergency Preparedness, State of MN & Sherburne & Wright Counties, " regional directors evaluation * Federal Emergency Hanagement Agency 84/01/24 32pp 22540 130 24X Fichs 50-263.84/03/05,8403080238
- ~-8403080244 "Monticello Nuclear Power Plant Full-Scale Joint Emergency Exercise on 830223," final rept * Federal Emergency Management Agency 84/03/05 110pp 22560 255 24X Fiche 50-263,84/03/05.8403060238
- 8403130198 Forwards evaluation of State of MN & Shelburne & Wright Counties emergency preparedness plan for 830283 full-scale exercise identified deficiencies corrected KRIMMR & Federal Emergency Hanagement Agency 84/03/05 JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 7pp 22613 256 24X Fiche 50-263.84/03/05, 8403130198

- --8403130209 Evaluation of State of MN & Shelburne & Wright Counties emergency preparedness plan for 830223 full-scale exercise * Federal Emergency Management Agency 84/03/05 63pp 22613 263 24X Fiche 50-263,84/03/05,8403130198
- 8403120060 Extends invitation to attend regional workshop on fire protection safe shutdown requirements of 100FR50.App R & IE Info Notice 84-09 on 840323 in Rosemont, IL Proposed agenda enci for review SPESSARD.R L. Division of Engineering 84/03/06 LARSON, C E Northern States Power Co 3pp 22570 286 24X Fiche 30-263.84/03/06,8403120060

I Financial information

- B403290115 Suppl to Annual Finencial Rept 1983, consisting of finencial & statistical info W/840326 ltr BRUSVEN.A D Northern States Power Co 83/12/31 23pp 22806 18R 24X Fiche B0-000.83/12/31,8403290115
- P Operating license stage documents & correspondence
- B403140340 Summary of B31215 meeting w/GE & Mark I Dwners Group in Betheeda. MD re Mark I containment wetwell~drywell vacuum breaker design methodology SIE0EL. B L Operating Reactors Branch 2 84/02/21 Operating Reactors Branch 2 51pp 22635 178 24X Fiche 50-000, 84/02/21, 6403140340
- B403140185 Forwards SER on NURE9-0737, Item II D 1 re performance testing of BWR relief & safety valves Item satisfactor(ly resolved VASSALLO, D B Operating Reactors Branch 2 84/02/24 MUSDLF, D M Northern States Power Co 17pp 22638 004 24X Fiche 50-263, B4/02/24, 8403140185
- B403130079 Forwards "Effluent & Waste Disposal Semiannual Rept.Jul-Dec 1983, ""Offsite Radiation Dose Assessment, 1983" & Rev 4 to "Offsite Dose Calculation Manual" FEY.F. L Northern States Power Co 84/03/01 Region 3, Office of Director ip 22617 327 24X Fiche 50-263, 84/03/01, 8403130079
- ---8403130103 Rev 4 to "Offsite Dose Calculation Manual "

 * Northern States Power Co 84/02/23 12pp 22617 347 24X
 Fiche 50-263.84/03/01.8403130979
- 8403150275 Generic Ltr 84~07 to all licensees of BWRs re procedural guidance for pipe replacement at BWRs Svc list enc! EISENHUT, D G Division of Licensing 84/03/14 Commonwealth Edison Co 20pp 22823 354 24% Fiche 50-000, 84/03/14; 8403150275
- 8403300323 Notifies that Class III fee appropriate for review of 800515 application to amend License DPR-22 re definition of term operable DIQ85.R M License Fee Management Branch 84/03/15 MUSDLF, D W Northern States Power Co 1p 22842 319 24X Fishe 50-263, 84/03/15, 8403300323
- 8403270049 Provides info to aid NRC in review & approval of alternate shutdown sys design (ASSD) Drawings showing physical location of ASSD control & relay panels & P&IDs for RHR & reactor water cleanup sys will be provided MUSDLF.D Northern States Power Co 84/03/19 Office of Nuclear Reactor Regulation. Director 2pp 22769 344, 24X Ficha 50-263,84/03/19,8403270049

O Inspection reports, IE Bulletins & correspondence

- 8403120141 Forwards IE Insp Rept 50-263/84-01 on 840111-0201 No noncompliance identified 8HAFER, W D Region 3. Office of Director 84/02/23 LARSON, C. E. Northern States Power Co 23pp 22585 234 24X Fiche 50-263,84/02/23,8403120141
- --B403120145 IE Insp Rept 50-263/84-01 on 840111-0201 No noncompliance or deviations identified Major areas inspected operational safety. LERs, IE bulletins & circulars, preparation for refueling, onsite review committee & procedures BROWN, C H , OROBE, J A , EVANS, C D Region 3, Office of Director 84/02/21 8pp 22585 236 24% Fiche 50-263, 84/02/23, 8403120141

1

B4032002B7 Forwards IE Insp Rept 50-263/84-02 on B40206-10 No moncompliances identified PAPERIELLO,C J. Region 3. Office of Director B4/03/06. LARSON,C E Northern States Power Co. 1p. 22696 342 24X Fiche 50-263.84/03/06.84032002B7

- --B403200271 IE Insp Rept 50-263/84-02 on 840206-10 No noncompliance or deviation identified Major areas inspected organization & mgt control.audits, advance planning & preparation, training & qualifications & exposure control GRANT, W B, GREGER, L, R Region 3. Office of Director 84/03/05 7pp 28696 343 24X Fichs 50-263.84/03/06,8403200287
- 8403190064 Informs that investigation of vendor purchase orders indicated that facility received no fraudulent products sold by Ray Miller, Inc.per IE Bulletin 83-07 review LARSON, C E Northern States Power Co 84/03/12 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 2pp 22664 322 24X Fiche 50-263.84/03/12.8403190064
- A Periodic operating reports & related correspondence
- 8403020177 Monthly operating rept for Jan 1984 W/840210 ltr MYRABO,A L. MUSOLF.D Northern States Power Co 84/01/31 5pp 22440 237 24X Fiche 50-263,84/01/31,8403020177
- 8403300087 Monthly operating rept for Feb 1984 W/840306 ltr MYRABO,A L , MUSOLF,D Northern States Power Co 84/02/29 5pp 22822 G21 24X Fiche 50-263,84/02/29,8403300087
- 8403130079 Forwards "Effluent & Haste Disposal Semiannual Rept.Jul-Dec 1983." "Offsite Radiation Dose Assessment, 1983" & Ray 4 to "Offsite Dose Calculation Manual " FEY.F.L. Northern States Power Co. 84/03/01 Region 3, Office of Director 1p 22617 327 24X Fiche 50-263, 84/03/01, 8403130079
- --B4031300B7 "Effluent & Waste Disposal Semiannual Rept, Jul-Dec 1983 "
 * Northern States Power Co 83/12/31 15pp 22617 328. 24X
 Fiche 50-263,84/03/01,8403130079
- --B403130094 "Offsite Radiation Dose Assessment, 1983 "
 * Northern States Power Co B3/12/31 App 22617 343 24X
 Fiche 50-263,84/03/01,8403130079
- --8403130103 Rev 4 to "Offsite Dose Calculation Manual "
 * Northern States Power Co 84/02/23 12pp 22617 347 24x
 Fiche 50-263,84/03/01,8403130079
- 5 Reportable occurrences, LERs & related correspondence
- 8403010316 LER 84-006-00 on 840119 reactor bldg isolation & initiation of standby gas treatment occurred when radiation check source brought too close to refuel floor spent fuel pool monitor Area radiation monitor relocated M/840224 ltr
 MILLER.M L . MUSDLF.D Northern States Power Co 84/02/24 3pp
 22432.098 24X Fiche 50-263.84/02/24.8403010316
- B403080233 PND-III-84-017A several cracks discovered in stainless steel piping sections in LPCI sys & jet pump instrument seal Stainless steel sections & jet pump instrument seal lines will be replaced DEFAYETTE.R., CHRISGOTIMOB, N., SHAFER, W. Region 3, Office of Director. 84/03/01 ip 22560 125. 24X Fiche 50-263,84/03/01,8403080233
- 84Q3120088 LER 84-007-00 on 840204, reactor recirculation motor generator set drive motor breaker failed to open remotely Gaused by binding of rollers Rollers cleaned & repacked w/vendor approved lubricant W/840306 ltr PUDLICK, L., MUSOLF, D. Northern States Power Co. 84/03/05 3pp. 22588.243 24X Ficher 50-243,84/03/05,8403120088.
- 8403120033 LER 84-008-00. on 840207, operating recirculation pump (P) shutdown & associated pump set generator field breaker did not trip Caused by faulty field breaker Maint frequency increased & all bearings & rollers cleaned H/840307 ltr KELLER, M. MUSOLF, D. Northern States Power Co. 84/03/06, 4pp 22585 225 24X Fiche 50-263,84/03/06,8403120033
- 8403130365 LER 84-009-00 on 840207, EFT sys (control room HVAC) transferred to emergency mode due to toxic chemical detector tape break Gaussd by excessive friction between optics block & tape Bpring tension reduced & block replaced H/840308 ltr HAMMER, HF, MUSDLF, D Northern States Power Co 84/03/08 3pp 82616 270 24X Fiche: 50-863, 84/03/08, 8403130365
- 8403130423 PND-III-B4-0178 on 840308, during visual insp.four J nozzles on feedwater spargers of reactor vessel found cracked Decision on repair & replacement pending more detailed exam State of MN notified DEFAYETTE.R , WALKER.R , SHAFER.W Region 3, Office of Director 84/03/08 ip 22613 090 24X Fiche 50-263,84/03/08,8403130423

- 8403200255 LER 84-010-00 on B40217 emergency filtration train system troin to HVAC transferred to toxic chemical emergency mode Caused by release of chlorine into chlorine tank storage room W/840316 ltr IVER80N.0 N. MUSQLF.D. Northern States Power Co. B4/03/16 3pp 22691 108 24X Fiche 50-263,84/03/16.8403200255
- 8403220003 LER 84-011-00 on 840218 & 23.crack indications detected on loop jet pump 8 instrument seal & on loops A & B of RHR LPCI lines Caused by intergranular stress corrosion cracking Affected matis replaced W/840319 ltr KELLER.M. MUSDLF, D. Northern Btates Power Co 84/03/19 3pp 22713 342 24X Fiche 50-243.84/03/19.8403220003
- DOCKET 50-264 DOW CHEMICAL CO
- F Security, medical, emergency & fire protection plans
- 8401260161 Releases public version of request for 2-month extension for completion of revs to emergency plan FELTON, JM Division of Rules and Records 84/01/18 Document Management Branch ip 21959 397 24X Fiche 50-264,84/01/18,8401860161
- --8401260167 Submits public version of request for 2-month extension for completion of revs to emergency plan from 840103-0302 Extension period will be used to modify plan per final ANSI 15 11 (1982) std KOCHER.C W Dow Chemical Co 83/12/23 THOMAS, C O Standardization & Special Projects Branch 1p 21959 358 24X Fishe 50-244, 84/01/18, 8401260161
- B403050012 Forwards revised emergency plan KDCHER,C W Dow Chemical Co 84/03/01 THOMAS,C O Btandardization & Special Projects Branch ip 22490 077. 24X Fiche 30-264.84/03/01.8403050012
- --8403030013 Revised emergency plan * Dow Chemical Co 84/02/23 55pp 22490 078 24X Ficha 50-264,84/03/01,8403050012
- DOCKET 50-265 GUAD CITIES STATION, UNIT 2
- F Security, medical, emergency & fire protection plans
- B403090274 Public version of revised emergency plan implementing procedures, including Procedures QEP 110-0 re station director & GEP 110-2 re acting station directory (shift engineer) W/JM Felton release memo KOVAK, T J . TIETZ, 0 . GERNER, L Commonwealth Edison Co 43/11/03 43pp 22572 017 24X Fiche 50-254,83/11/03,8403070274
- 8403040063 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee.per Bi0709 Generic Ltr 81-27 M/o request, entire plan will be placed in PDR VABBALLO.D B Operating Reactors Branch 2 84/02/10 FARRAR.D L Commonwealth Edison Co. 2pp 22528 303 24% Fiche 50-254.84/02/10.8403040043
- B403130155 Advises that state & local plans & preparedness for radiological emergencies adequate Approval conditional on FEMA verification of adequacy of alerting & notification sys.per App 3 of Rev 1 to NUREG-0654/FEMA-REP-1
 BPECK, S W Faderal Emergency Management Agency B4/03/02
 DIRCKS, W J Office of the Executive Director for Operations 2pp 22408 229 24X Fiche 50-254,84/03/02.8403130155.
- 8403120149 Notifies of 840323 regional workshop in Rosemont. IL w/all Region III licensees to discuss fire protection safe shutdown requirements Horkshop will provide addl guidance re 10CFR50.App R requirements Agenda encl SPESBARD. R L. Division of Emergency Preparedness & Operational Suppart 84/03/06 REED. C Commonwealth Edison Co 3pp 22584 182 24X Fiche 50-254,84/03/06,8403120149
- P Operating license stage documents & correspondence
- 8403050337 Forwards order confirming util commitment re intergranular stress corrosion cracking insp & repair Order being filed w/dfc of FR for publication Safety evaluation also encl VABBALLO.D B Operating Reactors Branch 2 84/02/15 FARRAR.D L Commonwealth Edison Co 2pp 22501 344 24X Piche 50-265,84/02/15.8403050337

- --8403050341 Order confirming util commitment re intergranular stress corrosion cracking insp & repair RCS leakage will be limited to 2 gpm increase in unidentified leakage within any 24 h period EISENHUT.D O Division of Licensing 84/02/15 Communusalth Edison Co. 6pp. 22501 346 24X Fiche 50-265.84/02/15.8403050337
- --8403050345 Safety evaluation re intergranular stress corrosion cracking Insp & mod plans must be submitted to NRC at least 3 months prior to start of nest refueling outage # Office of Nuclear Reactor Regulation, Director 84/02/15 11pp 22501 352 24X Fiche 50-265.84/02/15.8403050337
- 8403050039 Forwards safety evaluation re util response to 830904 intergranular stress corrosion cracking into order confirming shutdown to inspect recirculation. RHR. core spray & reactor water cleanup sys Regulred actions satisfactory DENTON, H R Office of Nuclear Reactor Regulation. Director 84/02/15 FARRAR.D L Commonwealth Edison Co 2pp 22528 222 24% Fichs 50-265.84/02/15.8403060059
- B403140340 Summary of 831215 meeting w/GE & Hark I Dwners Group in Bethesda.MD re Mark I containment wetwell-drywell vacuum breaker design methodology SIEGEL, B L Operating Reactors Branch 2 84/02/21 Operating Reactors Branch 2. 51pp 22635 198 24X Fiche 50-000,84/02/21, 8403140340
- 8403130102 Submits info re Cycle 7 shutdown margin demonstration.per 840224 request Reloaded core in compliance w/Tech Specs & startup allowed to proceed RYBAK.B Commonwealth Edison Co 84/02/27 DENTON.H R Office o Nuclear Reactor Regulation. Director 12pp 22602 212 24X Fiche 50-268.84/08/27.8403130102
- B403050119 Forwards supplemental response to Generic Ltr 83-28, "Required Actions Based on Generic Implications of Salem ATMS Events"

 BARNES, P. L. Commonwealth Edison Co. 84/02/29, DENTON, M. R. Offic of Nuclear Reactor Regulation, Director 26pp. 22488 084 24X Fishe 50-000,84/02/29,8403050119
- 8403130353 Documents present resolution of SER open items & deficiencies noted in Franklin Research Ctr technical evaluation rept re environ qualification of safety-related electrical equipment RYBAK, B Commonwealth Edison Co 84/02/29 DENTON, H R Office of Nuclear Reactor Regulation, Director 40pp 22617 080 24X Fiche 50-254,84/02/29.8403130353
- 8403130400 Forwards 840210 responses to Generic Ltr 89-33 clarifying TMI Item II K 3 31 Util concurs w/NRC position Item should be clased RYBAK, B Commonwealth Edison Co 84/03/02 EISENHUT, D 0 Division of Licensing 2pp 22613 143 24X Fiche 50-000,84/03/02,8403130400
- 8403150275 Generic Ltr 84-07 to all licensees of BWRs re procedural guidance for pipe replacement at BWRs Svc list encl EISENVILT.B G Division of Licensing 84/03/14 Commonwealth Edison Co 20pp 22823 354 24X Fiche 50-000.84/03/14.8403150275
- 3403270130 Application for amend to License DPR-25, changing Tech Specs to extend certain MAPLHOR curves to 40.000 MWd/ST RYBAK.B Commonwealth Edison Co 84/03/19 DENTON, H R Office of Nuclear Reactor Application, Director 2pp 22774 129 24X Fiche 50-000.84/03/19.8403270130
- --8403270136 Errate & Addenda Sheet 9, replacing Page 4-14 to "LOCA Analysis Rept for Dresden Units 2 & 3 & Quad Cities 1 & 2 Nuclear Power Stations"

 * General Electric Co NEDD-24146A ERR 09 83/01/31 2pp 22774.135 24K Fiche 50-000.84/03/19,8403270130
- O Inspection reports. IE Bulletins & correspondence
- 8403050337 Forwards order confirming util commitment re intergranular stress corrosson cracking insp & repair Order being filed w/Ofc of FR for publication Safety evaluation also encl VASSALLO.D 0 Operating Reactors Branch 2 84/02/15 FARRAR.D L Commonwealth Edison Co 2pp 22501 344 24X Fiche 50-265.84/02/15.8403050337
- --BA03050341 Order confirming util commitment re intergranular stress corresion cracking insp & repair RCS leakage will be limited to 2 gpm increase in unidentified leakage within any 24 h period EISENHUT, D G. Division of Licensing 84/02/15 Commonwealth Edison Ca Opp 22501 346, 24X Ficher 50-265,84/02/15,8403050337

- --B403050345 Safety evaluation re intergranular stress corrosion cracking Insp & mod plans must be submitted to NRC at least 3 months prior to start of next refueling outage # Office of Nuclear Reactor Regulation, Director 84/02/15 11pp 22501 352 24X Fiche 90-245.84/02/15,8403050337
- B403060059 Forwards safety evaluation re util response to B30904 intergranular stress corresion cracking insporder confirming shutdown to inspect recirculation. RHR. core spray & reactor water cleanup sys Required actions satisfactory DENTON. H R Office of Nuclear Reactor Regulation. Director B4/02/15 FARRED L Commonwealth Edison Co 2pp 22528 222 24X Fiche 50-265.84/02/15.8403060059
- 8403120134 Forwards IE Insp Repts 50-237/84-01.50-249/84-01, 50-254/84-01.50-265/84-01.50-295/84-01 & 50-304/84-01 on 840203-14 No noncompliance identified SHAFER.W D Region 3. Office of Director 84/02/23 REED, C Commonwealth Edison Co 2pp 22590 090 24X Fiche 50-000,84/02/23, 840310324
- --8403120137 IE Insp Repts 50-237/84-01.50-249/84-01.50-254/84-01.
 50-265/84-01.50-275/84-01 & 50-304/84-01 on 840203-14 No noncompliance or deviations identified Major areas inspected allegations of improper operation CHRISBOTIMOS, N. WALKER.R D. Region 3, Office of Director 84/02/21 4pg 22590 092 24X Fichs 50-000.84/02/23.8403120134
- 8403050002 Submits brief outline of regulatory improvement program Program implements basic changes in practices & structure of operation Summary of corrective actions taken in response to control rod insertion error encl
 THOMAB.B. Commonwealth Edison Co. 84/02/24 KEPPLER, J. 0. Region
 3. Office of Director lipp 22490-226 24X Fichs.50-254,84/02/24,8403050002
- 8403050043 Forwards Rev O to "Corporate Regulatory Performance Improvement Plan "Plan designed to heighten employee awareness & strengthen corporate ability to improve regulatory performance THOMAS, B Commonwealth Edison Co 84/02/24 KEPPLER, J Q Region 3, Office of Director 3pp 22490 139 24X Fiche 50-000,84/02/24,8403050043
- --B403050046 Rev 0 to "Corporate Regulatory Performance Improvement Plan" * Commonwealth Edison Co 84/02/29 22pp 22490 142 24X Fiche 50-000, B4/02/24: 8403050043
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list enc!

 JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22709 237 24X Fiche 50-000.84/02/28,8401170072
- B403050072 Forwards addendum to IE Insp Repts 50-254/83-21 & 50-265/83-19, comparing beta analyses of liquid sample split & gross beta results of spiked liquid sample Info will close Open Items 50-254/83-21-02 & 50-265/83-19-01 PAPERIELLO.C J Region 3, Office of Director B4/02/29 REED, C Commonwealth Edison Co 1p 22490 014 24X Fiche 50-254.84/02/29, 8403050072
- --B403050074 Addendum to IE Insp Repts 50-254/83-21 & 50-265/83-19 re comparative beta analysis results of liquid sample split & gross buta results of spiked liquid sample * Region 3, Office of Director B4/02/29 ip. 22490 015 24X Fiche 50-254,84/02/29,8403050072
- 8403190207 Forwards IE Insp Repts 50-254/83-24 & 50-265/83-23 on 830804-840202 No noncompliance identified LITTLE.W 8 Region 3, Office of Director 84/03/01, REED.C Commonwealth Edison Co 2pp 22671 072 24X Fichs 50-254.84/03/01, 8403190207
- --8403190208 IC Imsp Repts 50-254/83-24 & 50-265/83-23 on 830804-840202 No noncompliance or deviations identified Hajor areas inspected review of inservice inspireactor water cleanup syspiping, IE bulletins & LERs CILIMBERG.R L , DANIELSON, D H , WARD, K D Region 3, Defice of Director 84/03/01 26pp 22671 074 24X Fiche, 50-254, 84/03/01, 8403190207
- B402070007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl GRACE, J N Division of QA, Safeguards & Inspection Programs (Post B30103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp 22532 329 24X Fiche 50-000.84/03/02,8402090007

- 8402070008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008
- 8402090009 IE Info Notice 84-15. "Reporting of Radiological Releases 8vc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 119pp 22553 217 24X Ficho 50-000,84/03/02,8402090009
- B402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8402070024 IE Info Notice 84-09, Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22435 049, 24X Fiche 50-000, 84/03/07, 8402090024
- B402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Sys " Syc list enc! JORDANAE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- B402090031 IE Bulletin 84-02, "Failures of GE Type HFF Relays in Use in Class IE Safety Sys " Svc list encl BEYOUNG, R C Director's Office, Office of Inspection and Enforcement B4/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000.84/03/12,8402090031
- 8403230088 Ack receipt of regulatory performance improvement plan Periodic meetings requested to discuss progress on program & provide feedback KEPPLER.J G Region 3. Office of Director 84/03/20 THOMAS.B Commonwealth Edison Co ip 22730 161 24X Fiche 50-000.84/03/20.8403230088
- --8403230107 Forwards corporate regulatory performance improvement plan THOMAS.B Commonwealth Edison Co 84/02/24 KEPPLER.J Q Region 3. Office of Director 3pp 22730 162 24X Fiche 50-000, 84/03/20,840323008B
- ---8403230126 Rev O to "Corporate Regulatory Performance Improvement Plan For Dresden, Guad Cities, Zion & LaSalle Operating Nuclear Stations & Byron & Braidwood Project Operating Organizations " ** Commonwealth Edison Co 84/02/29 22pp 22730 165 24X Fiche 50-000, 84/03/20,8403230088
- B403260196 Forwards responses to IE Bulletin 83-07, "Apparently Fraudulent Products Sold by Ray Miller, Inc." Quad Cities supplied w/piping matis from Ray Miller, Inc. during const Evaluation encl Concerns of IE Bulletin 83-06 satisfied BARNES, PL. Commonwealth Edison Co. 84/03/20 KEPPLER, J. G. Region 3, Office of Director, 19pp. 22756 185 24X Fiche 50-000,84/03/20,8403260196
- B402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl UGRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc i23pp 22823 229 24X Fichs 50-000.84/03/21,8402090043
- 8402070044 IE Info Notice 84-20, "Byc Life of Relays in Bafety-Related Bys " Byc list encl JGRDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp. 22933 001, 24X Fiche 50-000,84/03/21,8402090044
- R Periodic operating reports & related correspondence
- B403080197 "Rept of Occupational Personnel Radiation Doses,1983 " W/840227 ltr BCOTT.J B Commonwealth Edison Co 83/12/31 13pp, 22559 099 24X Fiche 50-000,83/12/31,8403080197
- 8403220120 Annual whole body external exposures for 1983 W/840316 ltr RYBAK, B Commonwealth Edison Co 83/12/31 7pp 22716 007 24X Fiche 50-000, 83/12/31, 8403220120

- 8403060i13 Forwards Rev 1 to "Effluent & Waste Disposal Semiannual Rept Jul-Dec 1982 " Errata for "Liquid Alpha Radinactivity, Jan-Jul 1983" & "Solid Radwaste Summary, Jul-Dec 1983, " also encl KALIVIANAKIB,N Commonwealth Edison Co 84/02/07 KEPPLER, J G Region 3, Office of Director ip 22518 252 24X Fichs 50-254,84/02/07,8403060113
- --8403060117 Rev 1 to "Effluent & Waste Disposal Semiannual Rept Jul-Dec 1982 "
 - * Commonwealth Edison Co 83/05/31 7pp 22518 253 24X Fiche 50-254,84/02/07,8403060113
- --8403060121 Errata for "Liquid Alpha Radioactivity Jan-June 1983 " * Commonwealth Edison Co 83706/30 ip 22518 260 24X Fiche 50-254,84/02/07, 8403060113
- B403130382 Monthly operating repts for Feb 1984 W/840308 ltr MISAK.A. KALIVIANAKIS,N Commonwealth Edison Co 84/02/27 24pp 22616 275 24X Fichs 50-294.84/02/27,8403130382
- 8403150019 Listing of changes, tests & experiments completed during Feb 1784 Summary of safety evaluation reported per 10CFR50 59 encl H/840308 ltr KALIVIANAKIS.N Commonwealth Edison Co 84/02/29 CA8E.E 9 Office of Nuclear Reactor Regulation Director 3pp 22644 360 24X Fiche 50-234.84/02/29.8403150019
- S Reportable occurrences. LERs & related correspondence
- 8403120107 Revised LER 83-020/017-3 on 831027.11 welds identified as having crack indications Caused by intergranular stress corrosion cracking Repair employed weld overlay or induction heat stress improvement W/840221 ltr CLARK.D . KALIVIANAKIB.N Commonwealth Edison Co 84/02/21 KEPPLER.J Region 3. Office of Director 7pp 22588 172 24X Fiche 50-265.84/02/21.8403120107
- 8403070256 Followup Part 21 rept re defective mechanical snubber capstan springs supplied by Pacific Scientific Affected utils listed Purchasers have been notified & advised to work directly w/Pacific Scientific in disposition
 HOVI.L NPS Industries, Inc 94/02/24 DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 2pp 22536 279 24X Fichs 50-000.84/02/24.8403070256
- 8403080011 Forwards response to Commissioner Gilinsky request for info on frequency of personnel errors at selected operating plants Summary of tabulated events re operator errors, personnel errors or procedural errors provided for CY83 DIRCKS,W J Office of the Executive Director for Operations 84/02/24 PALLADING, GILINSKY, ROBERTS Commissioners 17pp 22584 142 24X Fiche 50~000.84/02/24,8403080011
- 8403200106 Revised LER 83-021/01T-5 on 831028.ultrasonic exams of large bore stainless steel pipe welds identified il welds w/crack indications Caused by intergranular stress corrosion cracking Weld overlay performed W/840228 ltr CLARK.D. KALIVIANAKIS.N. Commonwealth Edison Co. 84/02/28 KEPPLER.J. Region 3. Office of Director 7pp 22685 318 24X Fiche 50-265.84/02/28.8403200106
- B403160027 LER 84-003-00 on 840211 main feed breaker to 480-volt easential svc bus 27 tripped Caused by overcurrent candition through crosstie Loads limited W/B40308 ltr CLARK D 0 . KALIVIANAKIS, N Commonwealth Edition Co 84/03/08 3pp 22655 165 24X Fiche 50-265,84/03/08,8403160027
- 8403200188 LER 84-004-00 on 840215, full scram received while reactor shut down Caused by faulty 10% closure limit switch on MSIV AD 2-203-2A Limit switch replaced W/840313 ltr KALIVIANAKIS,N Commonwealth Edison Co 84/03/13 2pp 22698 284 24X Fiche 50-265.84/03/13,8403200188
- DOCKET 50-266 POINT BEACH NUCLEAR PLANT, UNIT 1

 F Security, medical, smargency & fire protection plans
- B403050208 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee.per B10709 Generic Ltr B1-27 W/o request.entire plan will be placed in PDR MILLER.J R Operating Reactors Branch 3 84/02/16 FAY.C W Hisconsin Electric Power Co 2pp 22528 152 24X Fichm 50-266.84/02/16.8403050208

- 903120045 Notifies of 840323 workshop on fire protection safe shutdown requirements of 100FR30. App R in Rosemont, IL to discuss IE Info Notice 84-09 & provide add shutdown analyses &/or mod guidance Agenda encl SPEESARD. R L Division of Emergancy Preparedness & Operational Support 84/03/06 BWRSTEINS, Wisconsin Electric Power Co 3pp 22970 294 24% Fiche 50-266, B4/03/06, B403120045
- 403160080 Submits addl info on Generic Ltr 82-33 sthedule requirements for emergency response capabilities Vendor of new computer sys requested 1-yr delay to June 1785 for delivery affecting schedular commitments made to NRC FAY, C W Hisconsin Electric Power Co 84/03/08 DENTON, H R Office of Nuclear Reactor Regulation. Director 4pp 22652 327 24X Fiche 50-266,84/03/08,8403160080
- 403220093 Ack receipt of B40306 ltr informing NRC of corrective actions re deviation from commitment & resolution of revised emergency plan BER clarification items noted in IE Insp Repts 50-264/83-25 & 50-301/83-25
 PAPERIELLO,C J Region 3. Office of Director B4/03/19
 BURSTEIN.S Wisconsin Electric Power Co ip 22716 324 24X Fishe 50-266.84/03/19.8403220093
- -8403220099 Responds to NRC B40002 ltm forwarding revised emergency plan SER & request for clarification of listed items & deviation from commitment Corrective actions Procedure EP 50.
 "Organizational Control of Emergencies." revised FAY.C W Wisconsin Electric Power Co 84/03/06 KEPPLER.J 0. PAPERIELLO, C J Region 3. Defice of Director 9pp 22716 325 24X Fiche 50-266.84/03/19.8403220093

Adjudicatory correspondence

- 3402220157 Order extending time until 840228 for Commission to act to review Director's Decision DD-83-14 CHILK.S J Office of the Secretary of the Commission B4/02/21 Commissioners ip 22337 362 24% Fiche 50-000, 84/02/21. 8402220157
- 8403010238 Order extending time until 840305 for Commission to act to review Director's Decision DD-83-14 & 831029 decision denying request of Environ Policy Inst CHILK.8 J Office of the Secretary of the Commission 84/02/28 Commissioners ip 22434 210 24X Fiche 50-000,84/02/28,8403010233
- B403070069 Informs that Commission unanimously declined to review Director's Decision DD-83-14 Time provided by NRC regulations within which Commission may act to review expired Decision became final agency action on B40305 CHILK, S J Office of the Secretary of the Commission B4/03/08 CELEBREZIE, A J Ohio, State of 2pp 22575 350 24X Fiche 50-000,84/03/08.8403090069
- 8403090074 Informs that Commission unanimously declined to review Director's Decision DD-83-14 Time provided by NRC regulations within which Commission may act to review expired Decision became final agency action on 840305 CHILK, 9 J Office of the Secretary of the Commission 84/03/08 MILLAR, E Environmental Policy Institute ip 22975 292 24X Fiche 50-000.84/03/08.8403090074
- 8403090113 Informs of Commission decision not to review Director's Decision DD-83-14 Time for Commission to act expired on 840305 W/o enc!
 CHILK-8 J Office of the Secretary of the Commission 84/03/08 RESNIKOFF,M Sierra Club ip 22376 079 24X
 Fiche 30-000.84/03/08.8403090113
- P Operating license stage documents & correspondence
- 8403270002 Final response to FDIA request for four categories of documents, tests, studies & analyses referencing or pertaining to NURED-0103. "STB for IBAM PMR "App A documents encl FELTON, J M Division of Rules and Records B4/01/13 MADDEN, T J Kays, Scholer, Fierman, Mays & Handler. App 22816 127 24% Fiche 30-000-84/01/13.8403270002
- --8403290045 Discusses G Reed 730301 ltr to G Arlotto re RCPB leakage detection sys Method for detecting slow departure from normal indications of leakage detection sys provided in util monitoring charts
 FORSE. L Atomic Energy Commission Directorate of Regulatory Btandards 73/03/09 HICHMAN.K Atomic Energy Commission 2pp 22816 303 24% Fiche 50-000.84/01/13.8403290002
- --B403290049 Forwards info describing RCB leakage monitoring Related info encl REED, 0 A Hisconsin Electric Power Co 73/03/01 ARLUTTO, 0 Atomic Energy Commission - Directorate of Regulatory Standards 40pp 22817 330 24X Fiche 50-000, 84/01/13, 8403290002

- 8403070295 Application for amend to Licenses DPR-24 & DPR-27 Amend incorporates changes to Teth Specs re accident monitoring instrumentation to be installed per NUREG-0737 requirement FAV.C H Wisconsin Electric Power Co 84/02/29 DENTION, H. R Office of Nuclear Reactor Regulation, Director MILLER, J R. Operating Reactors Branch 5 4pp 22536.179. 24X Fiche 50-266.84/02/29,8403070255
- --8403070257 Proposed Tech Specs incorporating changes re accident monitoring instrumentation to be installed per NUREG-0737 requirement ** Wisconsin Electric Power Co 84/02/27 10pp 22536:183 24X Fiche 50-266,84/02/27,8403070255
- 8403040373 Informs that ancl notice of consideration of issuance of amend to Licenses DPR-24 & DPR-27 & proposed NBHC determination & opportunity for hearing sent to Dfc of FR for publication Amend concerns leak surveillance. W/o encl GCLBURN, T G Operating Reactors Branch 3 84/03/01 FAY, C. W Hisconsin Electric Power Co 1p 22552-255 24% Fiche 50-266.84/03/01.8403060575.
- 8403120237 Requests remittal of addl fee for review of 820527 application re-steam generator replacement in response to util 831205 denial that Class V fee applicable MILLER.W D License Fee Management Branch 84/03/01 FAY.C W. Wisconsin Electric Power Co 3pp 22619 238 24% Fiche 50-266.84/03/01.8403120237
- 8403220254 Forwards FR notice of consideration of issuance of amend to Licenses DPR-24 & DPR-27 & proposed NSHC & opportunity for hearing re 831223 application to revise surveillance interval for post-accident recovery sus outside containment COLBURN.T G. Operating Reactors Branch 3 84/03/01 FAY.C W Hisconsim Electric Power Co. 2pp. 22723 325 24X Fichs 50-266.84/03/01.8403220254
- --8403R20289 FR notice of consideration of issuance of amend to Licenses DFR-24 & DFR-27 & proposed NSHC & opportunity for hearing re 83123 application to revise surveillance interval for post-accident recovery sys outside containment MILLER.JR Operating Reactors Branch 3. 84/02/09. 8pp 22723 327 24X Fiche 50-266.84/03/01,8403R20254
- B403120157 Advises that, due to delays in delivery & installation of auxiliary safety instrumentation panels (ASIPs), installation of six accident monitors addressed in NUREG-0737, Items I; F i through I! F i & will not be completed by B40630. FAY,C W Wisconsin Electric Power Co 84/03/05. DENTON, H R Office of Nuclear Reactor Regulation. Director MILLER, J R Operating Reactors Branch 3 3pp 22586: 230 24X Fichs 50-266,84/03/05,8403120157
- 8403130005 Informs of plans to Cycle 12 reload core Startup of Cycle 12 expected in mid-Mar 1984 following steam generator replacement
 FAY.C W Wisconsin Electric Power Co 84/03/05 DENTON, H R
 Office of Nuclear Reactor Regulation, Director, MILLER, J R
 Operating Reactors Branch 3 3pp 28615 195 24X
 Fichs 50-266,84/03/05,8403130005
- 8403190419 Comments on B40207 ltr modifying 831025 request for amends to Tech Epecs re changes in conduct of containment integrated leak test rates No significant hazards consideration discussion required MILLER, J.R. Operating Reactors Branch 3 84/03/06 FAY, C.W. Hisconsin Electric Power Co. 2pp. 22681 344 24X Fiche 50-266,84/03/06,8403190419
- 8403160034 Submits evaluation procedure for reactor vessel outlet nozzlento-shell weld indication, per IWB-3122 4 of ASME Section XI Flaws acceptable Continued syc warranted based on avaluation results FAY.C W Wisconsin Electric Power Co 84/03/12 DENTON, H R Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3. 3pp 22654 360 24X Fiche 30-266.84/03/12.8403160034
- 8403210077 Responds to Generic Ltr 84-01 re use of terms important to safety & safety-related Widespread use of terms in NRC regulations considered unresolved Notification of meeting requested FAY.C W Wisconsin Electric Power Co 84/03/15. SISENHUT.D Q. Division of Licensing. TAYLOR.J M Director's Office. Office of Inspection and Enforcement 1p 22705 165. 24X Fiche 30-266:84/03/15.8403210077
- B403220162 Application to amend Licenses DPR-24 & DPR-27, changing Tech Bpecs to add add1 restrictions on heavy loads over spent fuel pool & making additions & deletions re safety-related snubbers, per IE Bulletin 79-14 & Item II D 1 FAY.C W Misconsin Electric Power Co. B4/03/16. DENTON, H R. Office of Nuclear Reactor Regulation, Director MILLER, T R Operating Reactors Branch D. 4pp 22718.057 24X Fiche 50-266,84/03/16,8403220162

- --8403220167 Proposed Tech Specs, adding addl restrictions on heavy loads over spent fuel pool making additions & deletions to list of safety-related snubbers & revising position titles within
- 8403270125 Submits balance of payment for Class V fee for license amend approval re steam generator replacement FAY.C W Wisconsin Electric Power Co 84/03/16 MILLER.W O License Fee Management Branch ip 22774 114 24X License Fee Management Branch : Fiche 50-266,84/03/16,8403270125
- 8403270098 Responds to request for Tech Spec change to limit amount of overtime worked by plant staff members performing safety-related functions Amend to Tech Specs delayed pending related functions Amend to Jech Specs delayed pending adoption of Commission proposed rule FAY.C W Wisconsin Electric Power Co 84/03/19 DENTON, H R Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch S 2pp 22766 339 24X Fiche 90-266,84/03/19,8403270098
- 8403270237 Discusses reactor vessel outlet nozzla-to-shell weld flaw indication evaluation Requirements of ABME Bection XI safisfied & reactor vessel confirmed for continued safisfied & reactor yessel continued to the control of the control
- Q Inspection reports. IE Bulletins & correspondence
- 8403050223 Further response to FOIA request for records of named \$0303223 Further response to FDIA request for records of named individuals:including repts, analyses, studies, test calculetions, procedures & practices for measurement of RCS leakags Forwards App C documents Search continuing FELTDN.J M Division of Rules and Records 84/02/07 MADDEN,T J Kaye, Scholer, Fierman, Hays & Handler 3pp 22476 234 24X Fiche: 50-000,84/02/07,8403050223
- --8403050296 Notifies that independent measurements of identified & unidentified RCS leak rates for all PMRs in Region III performed per Procedures 61727B & 61728B Insp findings summarized summarized
 MORRELIUS, C E Division of Engineering 82/03/08 JORDAI
 Division of Engineering & Guality Assurance (Pre 830103)
 22496 270 24X Fiche 50-000.84/02/07.8403050223 JORDAN, E L
- 8403060151 Forwards IE Insp Repts 50-266/83-21 & 50-301/83-20 on 831011-840111 & mgt meeting on 840104 & notice of violation SPESSARDR L Region 3, Office of Director 84/02/21 BURSTEIN, S Wisconsin Electric Power Co 3pp 22506 182 24X Fichs 50-266,84/02/21,8403060151
- --B403060162 Notice of violation from insp on 831011-840111 8PE5BARD,R L Region 3, Office of Director 84/02/21 6pp 22506.185 24X Fiche 50-266,84/02/21,8403060151
- --8403060176 IE Insp Repts 50-266/83-21 & 50-301/83-20 on 831011-840111 & mgt meeting on 840104 Violation noted failurs to maintain cleanliness control, provide & follow procedures, control documents & properly store records HASSE,R A. CHOULES,N C., JORDAN,M J. Region 3, Office of Director 84/02/13 34pp 22306 191 24X Fiche 50-266.84/02/21, 8403060151
- B403130002 Forwards IE Insp Repts 50-266/83-26 & 50-301/83-24 on 831201-840131 & notice of violation SHAFER: W D Region 3: Office of Director 84/02/22; BURSTEIN: S Wisconsin Electric Power Co 2pp 22615, 267 24X Fichs. 50-266: 84/02/22; 8403130002
- ---8403130011 Notice of violation from insp on 831201-840131 BHAFER, W D Region 3, Office of Director 84/02/22 : 22413 269 24X Fiche 50-266,84/02/22,8403130002
- --8403130023 IE Insp Repts 50-266/83-26 & 50-301/83-24 on 831201-840131 Moncompliance noted fire in containment resulted when welding slag landed on acetylene hose attached to acetylene bottle not in use & not moved to safer location HAGUE, R L , FITZPATRICK, B , JACKIW, I N Region 3, Office of Director 84/02/21 9pp 22615 271 24X Fiche 50-266,84/02/22,8403130002
- B401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) B4/02/28 Consolidated Edison Co of New York, Inc. 115pp 22709-239 24X Fiche 50-000,84/02/28,8401170072

- 8402070007 IE Info Notice 84-i4, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list enci GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp 22352 329 24X fiche 50-000,84/03/02,8402070007
- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate "Svc list encl
 JORDAN, E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co. of New
 York, Inc. 122pp 22553 078 24X Fiche 50-000.84/03/02.8402090008
- 8402090009 IE Info Notice 84-15. "Reporting of Radiological Releases " Svc list encl OVCINET Enci JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/02 Consolidated Edison Co. of New York, Inc. 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 334 24X Fiche 50-000,84/03/05,8402070011
- 8403190240 Forwards IE Insp Rept 50-266/83-20 on 831213-16 & 840110-13 to stock of violation
 LITTLE.W S Region 3. Office of Director 84/03/05 BURSTEIN.S
 Hisconsin Electric Power Co 2pp 22672 037 24X
 Fiche 30-264.84/03/05.8403170240
- --8403190244 Notice of violation from insp on 831213-16 & 840110-13 LITTLE.W 9 Region 3, Office of Director 84/03/02 2pp 22472 039 24X Fiche 50-244,84/03/05,8403190240
- --8403190247 IE Insp Rept 50-266/83-20 on 831213-16 & 840110-13 903190297 lt Insp Rept 50-266/83-20 on 831213-16 & 840110-13
 Nancampliance noted failure to follow steam generator
 replacement project procedures
 KLEINSORGE,W P Region 2, Office of Director BLAKE.J J
 Division of Engineering & Operational Programs 84/02/23 17pp
 22672 041 24X Fiche 50-266/84/03/05/8403190240
- 8402090024 IE Info Notice 84-09. Rev 1. "Lessons Learned From Insps of Fire Protection Eafe Shutdown Sys " Svc list encl JORDAN: E.L. Division of Emergency Preparedness & Engineering Response (Post E30103) B4/03/07 Consolidated Edison Co of New York: Inc 118pp 22635 049 24X Fiche 50-000, 84/03/07, 8402070024
- 8402090028 IE Info Notice 84-18, "Stress Corresion Cracking in PWR #02070028 It into Notice 84-18.

 Sys " Svc list encl
 JURDAN.E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/07 Consolidated Edison Co. of New
 York, Inc. 118pp 22584 186 24X Fiche 50-000,84/03/07,8402070028
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Bafety Bys " Svc list encl
 DEYOUNG.R C Director's Office. Office of Inspection and
 Enforcement B4/03/12 Consolidated Edison Co of New York, Inc
 134pp 22823 074 24X Fiche 30-000.84/03/12,8402090031
- 8403220093 Ack receipt of 840306 ltr informing NRC of corrective AUSZZOVS ACK receipt of B40300 for informing NRC of corrective actions re deviation from commitment & resolution of revised emergency plan SER clarification items noted in IE Insp. Repts 50-266/B3-25 & 50-301/83-25
 PAPERIELLO,C J. Region 3. Office of Director B4/03/19
 BURBTEIN,S Wisconsin Electric Power Co. ip 22716 324 24X Fiche 50-266,84/03/19,8403220093
- --8403220099 Responds to NRC 840202 itr forwarding revised emergency plan BER & request for clarification of listed items & deviation from commitment Corrective actions Procedure EP 5 0, "Organizational Control of Emergencies," revised FAY.C W Wisconsin Electric Power Co 84703/06 KEPPLER.J 0, PAPERIELLO, C.J. Region 3, Office of Director 9pp 22716 325 24X Fiche 50-266,84/03/19,8403220093
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 123pp 22823 229 24X Fiche 50-000, 84/03/21, 8402090043
- 8402070044 IE Info Notice 84-20, "Byo Life of Relays in Safety-Related 102070044 IE Info Notice 84-20; Byt Line of Notage 2. Second Sys "Syc List encl Bys " Syc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000,84/03/21,8402070044

- R Periodic operating reports & related correspondence
- B403060358 "Semiannual Honitoring Rept. Jul-Dec 1983 " W/840229 ltr FAY.C W Hisconsin Electric Power Co 83/12/31 DENTON. H R Diffice of Nuclear Reactor Regulation. Director 18pp 22817 026 24X Fiche 50-264.83/12/31.8403060358
- 8403120066 "Annual Results & Data Rept.1983 " W/840301 ltr FAY.C W Wisconsin Electric Power Co 83/12/31 KEPPLER.J G Region 3. Office of Director 57pp 22591 070 24X Fiche 50-266.83/12/31.8403120066
- 8403140139 Monthly operating repts for Feb 1984 M/840308 ltr FAY.C W Wisconsin Electric Power Co 84/02/29 lipp 22620 232 24X Fiche 50-266,84/02/29,8403140139
- S Reportable occurrences, LERs & related correspondence
- 8403130379 PND-III-84-022 in response to IE Info Notice 82-29, exam identified 67 of 74 control rod drive support pins withack indications Licensee & Westinghouse evaluating exam findings to determine required action

 JORDAN, M. JACKIH, I. SHAFER, N. Region 3, Office of Director 84/03/02 ip 22614 092 24x fichs 50-244,84/03/02,8403130379
- 8403260072 Forwards safety evaluation of damaged control rod guide tube support pins UT indictions on shank-to-collar not safety concern FAYs Wisconsin Electric Power Co. 84/03/17 DENTON H R. Office of Nuclear Reactor Regulation. Director MILLER, J. R. Operating Reactors Branch J. 17pp. 22746-323 24% Fishe 50-266.84/03/19,8403260072
- ~-8403260075 "Westinghouse Safety Evaluation Cracked Control Rod Quide Tube Support Pins " * Westinghouse Electric Corp 84/03/05 28pp 22746 340 24X Fiche 50-266.84/03/19.8403260072
- DOCKET 50-267 FORT BT VRAIN NUCLEAR GENERATING STATION
 F Becurity, medical, emergency & fire protection plans
- 8403240161 Forwards IE Insp Rept 50-267/83-32 on 831205-09 No violations or deviations identified JUNNSON,E H. Region 4. Diffice of Director 84/02/03 LEE,D R Public Service Co of Colorado 4pp 22750 345 24x Fiche 30-267,84/02/03,8403260161
- ~-8403260167 IE insp Rept 50~267/83~32 on 831205~09 No violations or deviations identified Major areas inspected security sys audit physical betriers-protected areas & vital area.testing & maint & alarm stations Details withheld (ref 100FR73 21) CALDVELL.R A , KELLY, J A F , HUNNICUTT, D M Region 4, Defice of Director 84/02/01 2pp 22750 347 24% Fiche 50~267, 84/02/03.
- 8403260100 Forwards IF Insp Rept 30-267/84-03 on 840116-20 No violations or deviations noted JOHNSON.E H Region 4. Office of Director 84/02/14 LEE.OR Public Service Co of Colorado 2pp 22798 251 24X Fiche 30-267.84/02/14.8403260100
- --B403260107 IE Insp Rept 50-267/84-03 on B40116-20 No violations or deviations noted Major areas inspected raduaste program, including organization & mgt controls training & qualifications & solid raduaste processing MILOURN.L. MURRAY, B. HUNNICUTT, D. M. Region 4, Office of Director B4/02/13 10pp 22758 253 24X Fiche 50-267,84/02/14,8403260100
- 8403130435 Requests exemption from requirements of Sections III 9,J.L & O to 10CFR30.App R Fire protection provisions believed adequate to protect health & safety of public in event of accidents involving fires Affidavit encl LEE.D R Public Service Co of Colorado 84/03/02 COLLINS,J T Region 4. Office of Director 9pp 22613 163 24X Fiche 50~267.84/03/02.8403130435
- B40322013B Forwards revised schedule for supplying info re emergency response capabilities requested by Generic Ltr 82-33,per B40223 telcon Reg Guide 1 97 rept will be completed by B5022B BREY. H L Public Service Co of Colorado 84/03/09 COLLINS, J F Region 4. Office of Director 3pp 22714 285 24x Fiche 50~247,84/03/09,840322013B

1 Financial information

- 8403270192 Annual Financial Rept 1983 W/B40323 Jtr PERSON,R T , WALKER,R F , WAREHBOURG, D Public Service Co of Colorado 83/12/31 BDYD,R S Office of Nuclear Reactor Regulation, Director 57pp 22770 073 24% Fiche 50-267,83/12/31, 8403270192
- P Operating license stage documents & correspondence
- B403020014 Partial response to FOIA request for seven categories of documents re NRC regionalization program App A documents in PDR Review of remaining documents incomplete FELTON.J M Division of Rules and Records B3/12/16 LOMENTHAL.J Nuclear Information & Resource Service Spp 22492 248 24% Fiche 50-000, B3/12/16, B403020014
- --B212080692 Forwards FR notice amending 10CFR30 4 informing public that communications & applications should be sent to Region 4 Ltr to Congressional committees enci DENTON-HR Defice of Nuclear Reactor Regulation, Director 82/12/01 FELTON-J H Division of Rules and Records 2pp 2493 309 24X Fiche 50-000.83/12/16.8403020014
- --8212380693 "Regional Licensing Program Fort St Vrain Generating Station," 10CFR50 final rule Amend delegates responsibility for implementing licensing program to regional administrator Draft Congressional ltrs encl DRCKS.N J Office of the Executive Director for Operations, 92/12/01 Spp 82493 311 24X Fichs 50-000, 93/12/16, 8403020014
- --B212130052 Summary of B211th meeting w/util onsite re delegation of licensing functions to Region 4 Uniqueness of Facility & need to treat aspacts differently from other LURs discussed. Draft delegation of authority memo prol for signature. DENTON, H R Office of Nuclear Reactor Regulation, Director B2/11/29 DFRCKB, W J Office of the Executive Director for Operations Spp 22473 286 24X Fiche 50-000, 83/12/16, 8403020014
- --B212160089 Forwards FR notice & amend to 10CFR50, reflecting delegation & assignment of certain licensing actions to Region 4 administrator DENTON, HR Office of Nuclear Reactor Regulation, Director 82/11/30 DIRCKB.W J Office of the Executive Director for Operations /pp 22473 302 24% Fiche 50-000, 83/12/16.
- --B3011404Db Describes selected approach for transfer & maint of facility official docket files & supporting documentation to Region 4 Region 4 will assume routine document distribution on B21101
 FUNCHER, J L Planning & Program Analysis Staff B2/10/18, EISCHRUT, D Q Division of Licensing 2pp 22492 353 24X Fichs 50-000, B3/12/16.8403020014
- --B301140490 Advises that Region 4 assumes reappnaibility for receipt & distribution of all Pacsiity documentation effective B21101 SCOTTAR B Document Management Branch, B2/10/20 Document Management Byanch 1p 22492 355 24% Fiche: 50-000, 83/12/16, B403020014
- ---B301140494 Advises that Region 4 assumes responsibility for receipt & dissemination of incoming licensee communications for facility, effective 821101 BC0TTR B Document Menagement Branch 82/10/27 QAGLIARDD. J E Division of Resident, Reactor Project & Engineering Programs 1p 22492 336 24X Fiche 50-000. B3/12/16. 8403020014.
- --B304260013 Forwards functional transfer checklist used to coordinate administrative aspects of transfers of NRC headquayters functions to regions Subjs to prepare checklists for listed STELLO. V Regional Operations & Generic Requirements B3/04/19 DENTON. H Office of Nuclear Reactor Regulation, Director DEYDUMO, R Director's Office, Office of Inspection and Enforcement DAVIS. J Dffice of Nuclear Haterial Safety & Safeguards, Director 3pp 22493 337 24X Fiche 50-000,83/12/16,8403020014
- --8403020029 Discusses delegation & Assignment to Region IV of certain licensing functions for facility DIRCKS.W J Diffice of the Executive Director for Operations DENTON.H R Diffice of Nuclear Reactor Regulation. Director 92/11/29 CGLLING.J T Region 4. Office of Director 92/2493 289 24X Fiche 50-000.83/12/16.8403020014
- --B403020032 Bummary of 820701 initial planning meeting w/NRR.OELD.EDD.
 Region IV & OFC of Administration re licensing transfer from
 NRR to Region IV Details encl Next meeting scheduled for
 B20915
 HEBSHAN, R Assistant Director for Safety Assessment B2/09/03.
 IPPOLITO, I A Assistant Director for Safety Assessment 27pp
 22492 267 24X Fiche 50-000.B3/12/16.8403020014

- --8403020041 Informs of forthcoming FR publication of encl amend to Commission rules in iOCFR50 re implementation of facility regionalization program Amend issued as final rule effective on 821201 M/o encl
 DENTON, HR Defice of Nuclear Reactor Regulation, Director 83/12/16 UDALL, MK House of Rep , Interior & Insular Affairs ip 22493 316 24X Fiche 50-000,83/12/16.8403020014
- ---8403020045 Informs of forthcoming FR publication of encl amend to Commission rules in 10CFR50 re implementation of facility regionalization program Amend issued as final rule effective on 821201 Wo encl
 DENTON.H R Office of Nuclear Reactor Regulation, Director 83/12/16 MOFFETT.T House of Rep. Government Operations 1, 22493 317 24% Fiche 50-000,83/12/16,8403020014
- --8403020046 Informs of forthcoming FR publication of encl amend to Commission rules in 10CFR50 re implementation of facility regionalization program Amend issued as final rule effective on 821201 W/o encl
 DENTON, HR Office of Nuclear Reactor Regulation, Director 83/12/16 OTTINGER.R. House of Rep., Energy & Commerce 1p 22493:318 24X Fiche 50-000,83/12/16,8403020014
- --8403020048 Informs of forthcoming FR publication of encl amend to Commission rules in 10CFR50 re implementation of facility regionalization program Amend issued as final rule effective on 821201.W/o encl
 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 83/12/16 SIMPSON, A Benate, Environment & Public Works 1p 22493 319 24X Fiche 50-000,83/12/16,8403020014
- B40125046B Forwards engineering evaluation rept. "Temporary Loss of All AC Power due to Relay Failures in Diesel Generator Load Bhedding Circuitry " Practice of running emergency power sources in parallel w/offsite power sys may be prevalent HELTEMES, C. J. Director's Office B4/01/06 DENTON, H. Office of Nuclear Reactor Regulation, Director Jpp 22437 349 24X Fiche: 50-267, 84/02/21, 8402270004
- --8401250456 Revisus 831215 schedule for NRC 840125 drill in preparation for 840306-08 federal field exercise Executive team members should be available for entire time DEYDUNG,R C Director's Office, Office of Inspection and Enforcement 84/01/10 PALLADING,N Commissioners 2pp 67130 048 24% Fiche 50-267.84/02/21,8402290004
- --B401250496 Forwards Engineering Evaluation E401. "Temporary Loss of All ac Power Due to Relay Failures in Diosel Generator Load Shedding Circuitry " Failures occurred while generator 18 operated in parallel w/plant distribution sys CHIRAMAL.M Director's Office B4/01/04 GEYFRIT, K V Reactor Operations Analysis Branch 1p 22437 350 24X Fichs: 50-267, 84/02/21, 8402290004
- --B401250510 "Temporary Loss of All ac Power due to Relay Failures in Diesel Generator Load Shedding Circuitry (LER 83-8) " CHIRAMAL.M Director's Office 84/01/04 7pp 22437.351 24X Fiche.50-247.84/02/21.8402270004
- 8403010101 Responds to request for add1 info re proposed amend to Limiting Condition for Operation 4 1 9 re average core temp during shutdown WAREMBOURQ, D.W. Public Service Co. of Colorado. 84/02/24, JOHNSON, E.H. Region 4, Office of Director. 3pp. 22436-038-24X Ficher 50-267,84/02/24,8403010101
- 8403130177 Advises that util will be utilizing respiratory protective equipment under provisions of 10CFR20 103, effective 840401, per 840228 telcon BORBT, F. J. Public Service Co. of Colorado. 84/02/28 COLLINS, J. T. Region 4, Office of Director. ip 22615 305 24X Fiche 50-267, 84/02/28, 8403130177
- B403160303 Provides radiological ET8 clarifications & changes based on Item 267/8403-01 in IE Insp Rept 50-267/84-03 HAREMBOURO, D. M. Public Service Co of Colorado 84/02/29 COLLING. J. T. Region 4, Office of Director 2pp. 22660 347 24X Fiche. 50-267,84/02/29.8403160303
- 8403130231 Requests FR publication of Amend 40 to License DPR-34, revising design feature Tech Specs to describe type of fuel elements to be utilized in upcoming & future reloads JOHNSON, E H Region 4, Office of Director 84/03/02 MILLER, J R Operating Reactors Branch 3 2pp 22617 268 24X Fiche: 50-267,84/03/02,8403130231
- 8403130251 Forwards Amend 40 to License DPR-34 & safety evaluation Amend revises Tech Spec design features to indicate approval for Type H-451 & H-327 graphite in future reload fuel elements
 HAGNER, P. C. Region 4, Office of Director 84/03/02 LEE, O.R. Public Service Co. of Colorado ip 22617 237 24X
 Fiche: 50-267,84/03/02,8403130251

- ---8403130257 Amend 40 to License DPR-34 revising Tech Spec design features to indicate approval for Type H-451 & H-327 graphite in future reload fuel elements
 JOHNBON E H Region 4. Office of Director 84/03/02 5pp
 22617 240 24X Fiche 50-267.84/03/02.8403130251
- --8403130263 Safety evaluation supporting Amend 40 to License DPR-34 * Region 4, Office of Director 84/03/02 10pp 22617 245 24% Fiche 50-267,84/03/02,8403130251
- 8403120081 Forwards safety evaluation re Sections 5 1 (& 5 3 of NUREG-0612. "Control of Heavy Loads at Nuclear Power Plants " Guidelines satisfied Phase I acceptable JOHNSON,E H Region 4, Office of Director 84/03/06 LEE.O R Public Service Co of Colorado 2pp 22570 168 24X Fiche 50-287,84/03/06.4403120081
- --B403120086 Safety evaluation re NUREG-0612. "Control of Heavy Loads."
 Phase I Guidelines satisfied
 * NRC No Detailed Affiliation Given 84/03/06 2pp
 22590 170 24X Fiche 50-267.84/03/06.8403120081
- --8402280725 "Control of Heavy Loads at Nuclear Power Plants, Fart St Vrain Nuclear Generating Station, Phase I," technical evaluation rept STICKLEY, T H EORG, Inc. FIN A-6487 EGG-HS-6274 RO3 84/01/31 NRC - No Detailed Affiliation Given 27pp 22590 172 24X Fiche 50-267, 84/03/06, 8403120081
- 8403190390 Forwards application for amend to License DPR-34, clarifying Tech Spec changes by revising reporting requirements of Sections 50 72 & 50 73 No license amend fee required per Generic Ltr 83-43

 LEE, D.R. Public Service Co. of Colorado. 84/03/06. COLLINS, J.T. Region 4. Office of Director. 2pp. 22673 293. 24X

 Fiche 50-267.84/03/06.8403190350
- --B403190357 Application to amend License DPR-34, clarifying Tech Spec changes by revising reporting requirements of Sections 50 72 & 50 73 LEE, O R Public Service Co of Colorado 84/03/06 2pp 22673 297 24X Fiche 50-267,84/03/06,8403190350
- --8403190339 Proposed Tech Specs revising reporting requirements of Sections 50 72 & 50 73 * Public Service Co of Coloredo 84/03/06 10pp 22673 299 24X Fiche 50-267.84/03/06.8403190350
- 8403130234 Disagrees w/util 840209 ltr concluding that no Tech Spec revs required to finalize NUREO-0737 items presented in Generic Ltrs 83-354 83-37 Changes needed for conformance to NUREO-0737 encl Commitments requested within 20 days JOHNSON,E H Region 4. Office of Director 84/03/08 LEE.O R Public Service Co of Colorado 3pp 22617 265 24X Fiche 50-267,84/03/08,8403130234
- 84031900B3 Forwards Amend 41 to License DPR-34 & safety evaluation Amend allows receipt, possession & use of radioactive instrument calibr sources containing up to 300 Ci Cs-137 MAGNER, P C Region 4, Office of Director 84/03/08 LEE, O R Public Service Co of Colorado 3pp 22674 213 24X Fiche 50-267,84/03/08,84031900B3
- ---8403190087 Amend 41 to License DPR-34, allowing receipt, possession & use of radioactive instrument calibr sources containing up to 300 Ci Cs-137 & 200 uCi Kr-85
 JOHNSON, E H Region 4, Office of Director 84/03/08 2pp 22674 216 24X Fiche 50-267,84/03/08,8403190083
- --8403190093 Safety evaluation supporting Amend 41 to License DPR-34
 * Office of Nuclear Reactor Regulation, Director 84/03/08 2pp
 22674 218 24X Fiche 50-267,84/03/08,8403190083
- 8403190320 Requests FR publication of notice of issuence of Amend 41 to License DPR-34 Amend allows possession & use of larger sized radioactive Cs-137 & Kr-85 instrumentation calibr sources
 JOHNSON, E H Region 4, Office of Director 84/03/08 MILLER, J R Operating Reactors Branch 3 2pp 22673 278 24X Fichs 50-267,84/03/08,8403190320
- 8403160229 Forwards Rev A to Work Spec WS-93-0004. "Reevaluation of Plant Protection Sys Setpoints." as result of 831027 agreement to revise previous application for amend to Tech Specs WAREMBOURG, D. Public Service Co. of Colorado. 84/03/07. COLLINS.J T. Region 4. Office of Director. 2pp. 22661:045—24: Fichs 50-267.84/03/09.8403160227

- ---8403160233 Rev A to Work Sper MS-93-0004, "Recvaluation of Plant Protection Sys Setpoints" FLUMER, M Public Service Co of Colorado 84/02/17 17pp 22661 047 24X Fichs 50-267.84/03/09.8403160229
- B403270187 Forwards application to amend License DPR-34, changing Tech Specs re limiting conditions for instrumentation & control sys.control room temp & area radiation monitoring LEE.D R Public Service Co of Colorado 84/03/14 COLLINS, J Y Region 4, Office of Director 4pp 22771 103 24X Fiche 50-267,88/03/14,8403270187
- --9403270191 Application for amend to License DPR-34, revising Tech Specs re limiting conditions for operation of instrumentation & control sys, control room temp & area radiation monitoring * Public Service Co of Colorado 84/03/14 Spp 22771 107 24X Fiche 50-267,84/03/14,8403270189
- ---8403270194 Proposed Tech Specs re limiting conditions for operation of instrumentation & control systematical room temp & area radiation monitoring

 * Public Service Co of Colorado 84/03/14 14pp 22771 i10 24X Fiche 50-267,84/03/14,8403270189
- @ Inspection reports. IE Bulletins & correspondence
- 8403i30122 Forwards IE Insp Rept 50-267/83-28 on 831128-1202 & notice of deviation
 JOHNSON, E H Region 4. Office of Director 84/01/25 LEE.O R
 Public Service Co of Colorado 2pp 22602 198 24X
 Fiche 50-267.84/01/25.8403130122
- --8403130135 Notice of deviation from insp on B31128-1202 * Region 4. Office of Director 84/01/25 2pp 22602 200 24X Fiche 50-267,84/01/25,8403130122
- --8403130148 IE Insp Rept 50-267/83-28 on 831128-1202 Deviation noted inadequate designation of person responsible for low level waste transportation & lack of switable plan for training & retraining re waste transportation CHANEY.H D , MURRAY.B , HUNNICUTT.D M Region 4, Office of Director 84/01/18 10pp 22602 202 24X Fiche 50-267.84/01/25,8403130122
- 8403260161 Forwards IE Insp Rept 50-267/83-32 on 831203-09 No violations or deviations identified JOHNSON,E K Region 4. Office of Director 84/02/03 LEE.D R Public Service Co of Colorada 4pp 22750 345 24X Fiche 50-267.84/02/03.8403260161
- --B403260167 IE Insp Rept 50-267/83-32 on 831205-07 No violations or deviations identified Major areas inspected security sysaudit.physical barriers-protected areas & vital area testing & maint & alarm stations Details withheld (ref 10CFR73 21) CALDWELL,R A . KELLY, J A F . HUNNICUTT, D M Region 4. Office of Director 84/02/01 2pp 22750 347 24X Fiche 50-267.84/02/03.8403260161
- 8403260100 Forwards IE Insp Rept 50-267/84-03 on 840116-20 No violations or deviations noted JOHNSON,E H Region 4. Office of Director 84/02/14 LEE.O R Public Service Co of Colorado 2pp 22758 251 24X Fiche 50-267.84/02/14.8403260100
- --B403260107 IE Insp Rept 50-267/84-03 on 840116-20 No violations or deviations noted Major areas inspected radwaste program, including organization it mgt controls, training & qualifications it solid radwaste processing WILBORNL L. MURRAY B., HUNNICUTY D. M. Region 4, Office of Director 84/02/13 10pp 22758 253 24X Fiche 50-267.84/02/14, 8403260100
- 8403010107 Submits schedule & program description for Segment 3 fuel element insps, per 840210 telcon Program will be performed upon request Fuel element cracks have no effect on fuel particle integrity
 WAREMEDURG.D W Public Service Co of Colorado 84/02/13
 COLLINS.J T Region 4. Office of Director 6pp 22436 057 24X
 Fiche 50-267.84/02/15.8403010107
- B403010304 Responds to IE Bulletin 79-14 re review of seismic piping redocumentation status Util will finalize design work in upcoming months & remaining mod will be completed prior to startup after fourth refueling outage BREY.H L Public Service Co of Colorado B4/02/17 COLLINS, J T Region 4. Office of Director 2pp 22432 122 24X Fiche 50-267.84/02/17.8403010304

- 8403050112 Responds to NRC 840125 ltr rp deviations noted in IE Insp Rept 50-267/83-28 Corrective actions Radiation Protection Administrative Procedure RPAP-4 will be revised to include administrative control section WAREMBOURGOD W Public Service Co of Colorado 84/02/22 COLLINS.J T Region 4, Office of Director 3pp 22487 303 24X Fiche 50-267,84/02/22,8403050112
- 8403050153 Ack receipt of 831128 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-267/83-26 No add response required to NRMCA certificate as error not germane to corrective action

 JOHNSON,E H Region 4. Diffice of Director 84/02/23 LEE,O R

 Public Service Co of Colorado ip 22485 060 24x

 Fiche 50-267,84/02/23.8403050153
- 8401190072 IE Info Notice 84-13. "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JCRDAN, & L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22909 239 24X Fiche: 50-000, 84/02/28, 8401190072
- 8403160303 Provides radiological ETS clarifications & changes based on Item 267/8403-01 in IE Insp Rept 50-267/84-03 MAREMBURGO, D W Public Service Co of Colorado 84/02/29 COLLINS, J T Region 4, Office of Director 2pp 22660 347 24X Fiche 50-267,84/02/29,8403160303
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl ORACE.J N Division of GA: Safeguards & Inspection Programs (Post B30103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 327 24X Fiche 50-000.84/03/02,8402090007
- B402090008 IE Info Notice B4-16, "Failure of Automatic Bprinkler Sys Valves to Operate" Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/03/02 Consolidated Edison Co. of New York Inc 122pp 22553 098 24X Fiche 50-000, 84/03/02, 8402090008
- 8402090009 IE Info Notice 84~15, "Reporting of Radiological Releases" 8vc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8402090D11 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Delow Nil Ductility Temp " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000.84/03/05,8402090011
- 8403260205 Forwards IE Insp Rept 50~267/84~04 on 840206~10 & notice of violation JOHNSON,E H. Region 4, Office of Director 84/03/05 LEE,O R Public Service Co. of Colorado 2pp 22756 210 24X Fiche 50~267.84/03/05.8403260205
- --B403260209 Notice of violation from insp on 840206-10 * Region 4, DFFice of Director 84/03/05 ip 22756 212 24X Fiche 30-267,84/03/05,8403260205
- --B403260211 IE Insp Rept 50-267/B4-04 on B40206-10 Violation noted maint worker proceeded toward work area w/anticontamination clothing surveyed indicating 400 counts per minute & clothes not stored for decay & rewashing WILBORN.L . MURRAY.B . HUNNICUTT.D M Region 4. Office of Director E4/03/05 10pp 22756 213 24X Fiche 50-267,84/03/05,8403260205
- B403160326 Documents B40305 talcon which advised NRC that photographs committed to in fuel element insp program underexposed Preparations to remove all Region 18 fuel elements from fuel storage wall to permit photographs of elements begun WAREMBUURO,D W Public Service Co of Colorado 84/03/06 COLLINS,J T Region 4, Office of Director 2pp 22660.039, 24X Fiche 50~267.84/03/06,8403160326
- 8402070024 IE Info Notice 84-07, Rev i. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc 118pp 22635 047. 24X Fichs 50-000, 84/03/07, 8402070024
- 8402070028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Bys " Syc list enci JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028

- 8403260174 Forwards IE Insp Rept 50-267/84-07 on 840213-16 No violations or deviations identified JOHNSON, E.H. Region 4, Office of Director 84/03/08 LEE, O.R. Public Service Co. of Colorado 2pp 22757 343 24X Fiche 50-267,84/03/08.8403260174
- --8403260177 IE Insp Rept 50-267/84-07 on 840213-16 No violations or deviations identified Major areas inspected QA procedures for installation of safety-related electrical equipment & qualification of QC electrical personnel BESS, J E , JAUDON, J P , HUNNICUTT, D M Region 4, Office of Director 84/03/08 7pp 22757 345 24X Fiche 50-267, 84/03/08.
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Bvc list encl
 DEYOUNG, R C Director's Office, Defice of Inspection and
 Enforcement 84/03/12 Consolidated Edison Co of New York
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Bafety-Related Sys " Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp. 22733 001 24X Fiche 50-000,84/03/21,8402090044
- R Periodic operating reports & related correspondence
- 8403060309 "Semiannual Effluent Rept. Jul-Dec 1983 " H/840202 ltr BORST.F J Public Service Co of Colorado 83/12/31 COLLINS, J T Region 4. Office of Director 17pp 22515 338 24X Fiche 50-267.83/12/31.8403060309
- 8403130374 "Environ Radiation Surveillance Program Summary Rept for Third & Fourth Quarters 1983 " W/840227 ltr JOHNSON.J E Colorado State Univ. Ft Collins. CO BREY.H L. Public Service Co of Colorado 83/12/31 COLLINS.J T Region 4. Office of Director 143pp 22604 207 24X Fiche 50-267, 83/12/31. 8403130394.
- 8403010118 "Annual Occupational Exposure Rept 1783 "
 BORST.F J Public Service Co of Colorado 84/02/21 COLLINS, J T
 Region 4, Defice of Director 1p 22496 034 24X
 Fichs.50-267,84/02/21,8403010118
- 8403190344 Monthly operating rept for Feb 1984 W/840313 ltr FULLER, C . WAREMBOURG, D Public Service Co of Colorado 84/02/29 9pp 22673 156 24% Fiche 50-267,84/02/29,8403190344
- B. Reportable occurrences, LERs & related correspondence
- B403010134 Forwards LERs 80~030/03X-2 & 81-068/03X-1 WAREMBOURO, D Public Service Co of Colorado 84/02/16. COLLINS, J T Region 4, Defice of Director ip 22435 347 24X Fiche 50-267,84/02/16,8403010134
- --B403010155 LER B0-030/03X-2 on 800604, steam generator penetration leakage appeared to be greater than 400 lb per day Caused by purified helium leakage internal to loop 2 penetration & occurring between interspace & cold reheat steam piping NOVACHEK, F., FRYE, D.L., MCBRIDE, L.M. Public Service Co. of Colorado 84/02/16 7pp 22435 350 24X Fiche 50-267,84/02/16,8403010134
- --B403010167 LER B1-068/03X-1 on B11024, loop 2 steam generator interspace leakage exceeded limits Caused by helium leakage internal to penetration interspace & occurring between interspace & cold reheat steam piping NOVACHEK, F., FRYE, D.L., MCBRIDE, L.M. Public Service Co. of Colorado B4/02/16 4pp 22435 357 24X Fiche 50-267, 84/02/16, 8403010134.
- 8403010116 LER 84-002-00 on 840123 during surveillance test, one of three bearing water pressure differential switches found inoperable Cause unknown Smitch replaced & calibr to instrument operating requirements W/840222 ltr. NOVACHEK, F. WAREMBOURG, D. Public Service Co. of Colorado 84/02/22 COLLINS, J. T. Region 4. Office of Director App 22436 ORB 24X Fiche 50-267,84/02/22.8403010116

- 8403120071 Requests initiation of new task interface agreement for review of lacensee 840120 submittal re steam generator tube leak Acceptable steam generator tube surveillance program should be established DENIBER.R P. Division of Resident, Reactor Project & Engineering Programs 84/03/06 EIBENNUT.D 0 Division of Licensing 2pp 22589 302 24X Fiche 50-267.84/03/06.8403120071
- B403220063 LER B4-003-00 on B40212, automatic plant protective sys reactor scram initiated by one of two logic trips involving nuclear startup channel II Caused by insertion of fuel block containing neutron startup source W/B40313 ltr NDVACHEK, F. MAREMBURR, D. Public Service Co. of Colorado 84/03/13 COLLINS, J. T. Region 4, Office of Director 7pp 22717 173 24X Fiche 50-267,84/03/13,8403220063
- DOCKET 50-269 OCONEE NUCLEAR STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8403090254 Public version of revised crisis mgt plan implementing procedures. Including Procedures 5 3 4 re scheduling/planning support group. 5 3 6 re radiological support group & 5 3 7 re technical support group W/831107 ltr & JM Felton memo TUCKER. H B Duke Power Co 83/10/31 DENTON. H R Office of Nuclear Reactor Regulation, Director 271pp 22595 055 24% Fiche 50-000.83/10/31.8403090254
- 8403060225 Rev ii to crisis mgt plan W/840224 ltr & public info pamphlet VAUGHN.T E. TUCKER.H B Duke Power Co 84/02/02 DENTON.H R Office of Nuclear Reactor Regulation. Director 66pp 22516 185 24X Fichs 50-000.84/02/02.8403860225
- 8403160134 Forwards IE Insp Repts 50-269/84-04.50-270/84-04 & 50-287/84-04 on 840801-02 No violations or deviations identified DANCE.H C Division of Project & Resident Programs 84/02/16 TUCKER.H B Duke Power Co 2pp 22655 336 24X Fiche 50-269,84/02/16.8403160134
- --B403160141 IE Insp Repts 50-269/84-04,50-270/84-04 & 50-287/84-04 on B40201-02 No violations identified Major areas inspected emergency preparedness areas of protective action decisionmaking CLINE.W E Region 2, Office of Director 84/02/15 4pp 22655 338 24X Fichs 50-269,84/02/16,9403160134
- B403090222 Forwards Rev 3 to training & qualification plan Rev withheld (ref 10CFR73 21)
 TUCKER, H B Duke Power Co B4/02/29 O'REILLY, J P Region 2,
 Office of Director 1p 22575 149 24X Fiche 50-269,84/02/29,
- B403160278 Extends invitation to attend 840316 workshop to discuss IOCFR30.App R requirements & results of recent insp to help resolve misunderstanding associated w/requirements LEWIB.R C Division of Project & Resident Programs B4/03/02 TUCKER.H B Duke Power Co Ip 22660 274 24X Fiche 30-000.84/03/02.8403160278
- B403160245 Forwards summary of 840228 meeting w/util in Atlanta, GA re 10CFR50 48 & 10CFR50. App R fire protection application Attendance list also encl LEWIS.R C Division of Project & Resident Programs 84/03/07 TUCKER.H B Duke Power Co 3pp 22660 312 24X Fiche 50-269, 84/03/07, 8403160245
- 8403120119 Advises that 840116 Rev 11 to physical security plan consistent w/provisions of 10CFR30 54(p) & acceptable LEWIS,R C Division of Project & Resident Programs 84/03/08 TUCKER,H B Duke Power Co 2pp 22587 219 24X Fiche 50-269,84/03/08,8403120119
- 8403270069 Ack receipt of 840208 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/83-36.
 50-270/83-37 & 50-287/83-36 Implementation of corrective actions will be examined during future insp DANCE.H C Division of Project & Resident Programs 84/03/20 TUCKER,H B DURE Power Co ip 22807 0il 24X Fiche 50-269,84/03/20,8403290069
- --8403270108 IE Insp Repts 50-269/83-34.50-270/83-37 & 50-287/83-36 on 83111-1210 Violation nated failure to follow Maint Procedure 270/83-37-01 re quality performed on Reactor Coolant Pump 202
 BRYANT, J Region 2. Office of Director 84/01/09 10pp 22807 017 24X Fiche 50-269.84/03/20.8403270069

- 8403270209 Forwards Rev 4 to util response to NUREG-0737. Suppl 1. including control room review implementation priority schedule
 - including control room 12.12

 schedule

 TUCKER, H B Duke Power Co B4/03/23 DENTON, H R Office of

 Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors

 Branch 4 9pp 22772 098 24X Fiche 50-269, 84/03/23, 8403270209
- P Operating license stage documents & correspondence
- B403060272 Submits response to NRC request for schedular info re SER of proposed inadequate core cooling instrumentation Final design description will be submitted by B50701 TUCKER. H B Duke Power Co B4/02/28 DENTON, H R Dffice of Nuclear Reactor Regulation, Director 5TDL7. J F Operating Reactors Branch 4 2pg 2251B 124 24X Fiche 50-269,84/02/28,8403060292
- 8403t50320 Forwards Amends 127, 127 & 124 to Licenses DPR-30, DPR-47 & DPR-50, respectively & safety evaluation Amends revise Tech Specs to implement limiting conditions for operation in event one startup transformer out of svc STGLZ-JF Operating Reactors Branch 4 84/03/02 TUCKER.H B Duke Power to 2pp 22649 274 24X Fiche 50-269, 84/03/02.
- --8403150335 Amends 127.127 & 124 to Licenses DPR-38, DPR-47 & DPR-55, respectively, revising Tech Specs to implement limiting conditions for operation in event one startup transformer out of svc BTDL7.JF Deprating Reactors Branch 4 84/03/02 21pp 22649 276 24X Fiche 50-269,84/03/02.8403150328
- --8403150344 Safety evaluation supporting Amends 127.127 % 124 to Licenses DPR-38.DPR-47 % DPR-55, respectively * Defice of Nuclear Reactor Regulation, Director 84/03/02 2pp 22649 297 24% Fiche 50-269.84/03/02.8403150328
- G Inspection reports. IE Bulletins & correspondence
- 8403070364 Forwards 1E Insp Repts 50-269/83-11.50-270/83-11 & 50-287/83-11 on 830317-28 Enforcement action addressed in NRC 830602 ltr LEMIS.R C Division of Project & Resident Programs 83/06/02 TUCKER.H B Duke Power Co 2pp 22546 025 24X Fiche 50-269.83706/02.403070364
- --8403070367 IE Imap Repts 50-249/83-11.50-270/83-11 & 50-287/83-11 on B30317-28 Violations noted loss of containment integrity on B30317 & 21 & failure to meet requirements of confirmatory order dtd 810710 re independent verification BRYANTJ. FALCONER.D Region 2. Office of Director IONATONIS, A Division of Project & Resident Programs 83/06/02 10pp 22546 027 24X Fiche 50-269.83/06/02.8403070364
- B403160134 Forwards IE lnsp Repts 50-269/84-04:50-270/84-04 & 50-287/84-04 on 840201-02 No violations or deviations identified DANCE-H C Division of Project & Resident Programs 84/02/16 TUCKER:H B Duke Power Co 2pp 22655 336 24X Fichs 50-269.84/02/16.8403160134
- ~-8403160141 IE Insp Repts 50-269/B4-04.50-270/B4-04 & 50-2B7/B4-04 on B40201-02 No violations identified Major areas inspected emergency preparedness areas of protective action decisionmaking CLINE.W E Region 2, Office of Director JENKINB.O R Division of Emergency Preparedness & Materials Safety B4/02/15 4pp 22655 338 24X Fiche 50-269/B4/02/16.8403160134
- B403010308 Forwards add1 info re B30815 request for relief from inservice insp requirements (Hydrostatic) of Section XI of ABHE Boiler & Pressure Vessel Code Valve 2LPBM-133 cannot be closed due to sheared hinge pins
 TUCKER. H B Duke Power Co B4/02/23 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 2pp 22432 102 24X Fiche 50-249,84/02/23,8403010308
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list enc]
 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22909 239 24X Fichs 50-000,84/02/28,8401190072
- B402070007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE, J N Division of GA. Safeguards & Inspection Programs (Post 830103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp 22592 327 24X Fiche 50-000.84/03/02,8402070007

- 8402070008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Bys Valves to Operate " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 122pp 22553 098 24X Fiche 50-000.84/03/02.8402070008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases Byo list entl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8402070011 IE Info Notice 84-17. "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 630103) 84/03/05 Consolidated Edison Co. of New York, Inc. 117pp 22593 336 24X Fiche 50-000,84/03/05,8402070011
- 8402070024 IE Info Notice 84-09. Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Bys " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc. 118pp 22635 049 24% Fiche 50-000, 84/03/07, 8402090024
- 8402070028 IE Info Notice 84-18, "Stress Corresion Cracking in PWR Sys " Svc list enc!
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402070028
- 8402070031 IE Bulletin 84-02, "Failures of QE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000.84/03/12.8402090031
- 8403270069 Ack receipt of 840208 ltr informing NRC of steps taken to correct violations noted in IE Insp. Repts 50-2269/83-36, 50-227/83-36 implementation of corrective actions will be examined during future insp. DANCE, H. C. Division of Project & Resident Programs 84/03/20 TUCKER, H. B. Duke Power Co. 1p. 22807 011 24X Fiche 50-269,84/03/20,8403270069
- --8403290082 Responds to NRC 840109 ltr re violations noted in IE Insp Repts 50-269/83-36.50-270/83-37 & 50-287/83-36 Corrective actions Unit 2 staging coil locations corrected & seal packages on Reactor Coolant Pump ROZ replaced TUCKER.H D Duke Power Co 84/02/08 D'REILLY, J P Region 2, Office of Director 2pp 22807.012 24X Fiche 50-269,84/03/20, 8403290069
- --B403290090 Forwards IE Insp Repts 50-269/83-36, 50-270/83-37 & 50-287/83-36 on 83111-1210 & notice of violation DANCE: H C Division of Project & Resident Programs 84/01/09 TUCKER.H B Duke Power Co 2pp 22807 014 24X Fiche 50-269, 84/03/20, 8403290069
- --8403290095 Notice of violation from insp on 831111-1210 * Region 2. Office of Director 84/01/09 ip 22807 016 24X Fiche: 50-269,84/03/20,8403290069
- --B403270108 IE Insp Repts 50-269/83-36, 50-270/83-37 & 50-287/83-36 on B3111-1210 Violation noted, failure to follow Maint Procedure 270/83-37-01 re quality performed on Reactor Coolant Pump 282 BRYANTJ J. FALCONER, D. Region 2. Office of Director BROWNLEE, V.L. Division of Project & Resident Programs 84/01/07 10pp 22807 017. 24% Fiche 50-269, 84/03/20, 8403270069
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PMR Reactor Cavities" Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21. Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000,84/03/21.8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc list encl.
 JORDAN,E' L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 135pp 22933 001 24% Fiche 50-000,84/03/21,8402090044
- R Pariodic operating reports & related correspondence
- B403200010 Monthly operating repts for Feb 1984 W/840315 ltr. REAVIS. J A . TUCKER. H B. Duke Power Co 84/02/29 17pp. 22685 185 24X Fiche 50-269,84/02/29,8403200010

V Operator Examinations

8403080239 Forwards operator licensing exam schedule through CYBB, in response to Generic Ltr 83-40-TUCKER, H B Duke Power Co 84/02/29 EISENHUT, D G Division of Licensing 2pp 22351 023 24X Fiche 50-269, 84/02/29, 8403080239

DOCKET 50-270 OCONEE NUCLEAR STATION, UNIT 2

F Security, medical, emergency & fire protection plans

- 8403090254 Public version of revised crisis mgt plan implementing procedures, including Procedures 5 3 4 re scheduling/planning support group, 5 3 6 re radiological support group, 8 3 7 re tachnical support group W/831107 ltr & JM Felton memo TUCKER, H B Duke Power Co 83/10/31 DENTON, H R Office of Nuclear Reactor Regulation, Director 271pp 32595 055 24X Fiche 50-000,83/10/31,8403090254
- B403060225 Rev 11 to crisis mgt plan W/B40224 ltr & public info pamphlet VAUGHN,T E , TUCKER.H B Duke Power Co B4/02/02 DENTON.H R Office of Nuclear Reactor Regulation. Director 66pp 22516 189 24X Fiche 50-000.B4/02/02.B4030460225
- 8403160134 Forwards IE Insp Repts 50-267/84-04,50-270/84-04 & 50-287/84-04 on 840201-02 No violations or deviations identified DANCE.H C Division of Project & Resident Programs 84/02/16 TUCKER,H B Duke Power Co 2pp 22635
- ---B403160141 IE Insp Repts 50-269/B4-04,50-270/B4-04 & 50-287/B4-04 on B40201-02 No violations identified Major areas inspected emergency preparedness areas of protective action decisionmaking CLINE.W E Region 2, Office of Director B4/02/15 4pp 22655 33B 24X Fiche 50-269,B4/02/16,B403160134
- 8403090222 Forwards Rev 3 to training & qualification plan Rev withheld (ref 10CFR73 21) TUCKER, H B Duke Power Co 84/02/29 O'REILLY, J P Region 2, Office of Director ip 22375 149 24X Fiche 50-269, 84/02/29, 8403090222
- B403160278 Extends invitation to attend 840316 workshop to discuss 10CPR50. App R requirements & results of recent insp to help resolve misunderstanding associated w/requirements LEWIG.R C Division of Project & Resident Programs 84/03/02 TUCKER.H B Duke Power Co ip 22660 274 24X Fiche 50-000.84/03/02.8403160278
- 8403160245 Forwards summary of 840228 meeting w/util in Atlanta, GA re 10CFR30 48 & 10CFR30.App R fire protection application Attendance list also encl LEWIS.R C Division of Project & Resident Programs 84/03/07 TUCKER.H B Duke Power Co 3pp 22660 312 24X Fiche 50-269,84/03/07.8403160245
- 8403120119 Advises that 840116 Rev 11 to physical security plan consistent w/provisions of 10CFR50 54(p) & acceptable LEWIG.R C Division of Project & Resident Programs 84/03/08 TUCKER.H B Duke Power Co 2pp. 22589 219 24X Fiche 50-269,84/03/08,8403120119
- 8403290069 Ack receipt of 840208 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-269/83-36. 50-270/83-37 & 50-287/83-36 implementation of corrective actions will be examined during future insp DANCE: H C Division of Project & Resident Programs 84/03/20 TUCKER; H B Duke Power Co ip 22807 Oli 24X Fiche 50-269, 84/03/20, 8403290069
- --8403270108 IE Insp Repts 50-269/83-36:50-270/83-37 & 50-287/83-36 an 83111-1210 Violation noted failure to follow Maint Procedure 270/83-37-01 re quality performed on Reactor Coolent Pump 282.

 BRYANT, J Region 2. Office of Director 84/01/09 10pp 22807 017 24X Fiche 50-269,84/03/20,8403290069
- B403270209 Forwards Rev 4 to util response to NUREQ-0737, Suppl i, including control room review implementation priority schedule
 TUCKER, H B Duke Power Co 84/03/23 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 7pp 22772 088 24X Fiche 50-269, 84/03/23, 8403270209

P Operating license stage documents & correspondence

- 8403040272 Submits response to NRC request for schedular info re SER of proposed inadequate core couling instrumentation Final design description will be submitted by 850701 TUCKER, H B Duke Power Co 84/02/28 DENTON, H R Office of Nuclear Reactor Regulation, Director STOL7, J F Operating Reactors Branch 4 2pp 22518 124 24X Fiche 50-269, 84/02/28, 8403040272
- 8403150328 Forwards Amends 127,127 & 124 to Licenses DPR-38,DPR-47 & DPR-55,respectively & safety evaluation Amends revise Tech Specs to implement limiting conditions for operation in event one startup transformer out of svc STOLZ,JF Operating Reactors Branch 4 84/03/02 TUCKER.H B Dute Power Co 2pp 22647 274 24X Fiche 50-269.84/03/02.8403150328
- --8403150335 Amends 127.127 & 124 to Licenses DPR-38.DPR-47 & DPR-55. respectively, revising Tech Specs to implement limiting conditions for operation in event one startup transformer out of svc STOL7.JF Operating Reactors Branch 4 84/03/02 2ipp 22649 276 24X Fiche 50-269,84/03/02.8403150328
- --8403150344 Safety evaluation supporting Amends 127,127 & 124 to Licenses DPR-3B, DPR-47 & DPR-55, respectively * Office of Nuclear Reactor Regulation, Director 84/03/02 2pp 22647 277 24X Fiche 5D-269,84/03/02,8403150328
- 8403290314 "Oconee 2 Cycle 7 Startup Testing Rept " W/840326 ltr ELDER.M L , PARSONS.C H Duke Power Co 84/03/26 DENTON.H,R Office of Nuclear Reactor Regulation, Director STOL2.J F Operating Reactors Branch 4 25pp 22802 070 24X Fiche.50-270.84/03/26.8403290314

Q Inspection reports, IE Bulletins & correspondence

- 8403070364 Forwards IE Insp Repts 50-269/83-11.50-270/83-11 & 50-287/83-11 on 830317-28 Enforcement action addressed in NRC 830602 ltr LEWIS.R C Division of Project & Resident Programs 83/06/0 TUCKER.H B Duke Power Co 2pp 22546 025 24X Fiche 50-269.83/06/02.8403070364
- --9403070369 IE Insp Repts 50-269/83-11.50-270/83-11 & 50-287/83-11 on 830317-28 Violations noted loss of containment integrity on 830317 & 21 & failure to meet requirements of confirmatory order dtd 810710 re independent verification BRYANT, J. FALCONER, D. Region 2. Office of Director IONATONIS, A Division of Project & Resident Programs 83/06/02 10pp 22544 027 24X Fiche 50-269,83/06/02.8403070364
- 8403160134 Forwards IE Insp Repts 50-269/84-04, 50-270/84-04 & 50-287/84-04 on 840201-02 No violations or deviations identified DANCE.H C Division of Project & Resident Programs 84/02/16 TUCKER.H B Duke Power Co 2pp 22655 336 24% Fiche 50-269, 84/02/16,8403160134
- --8403160141 IE Insp Repts 50-269/84-04.50-270/84-04 & 50-287/84-04 on 840201-02 No violations identified Major areas inspected emergency preparedness areas of protective action decisionmaking GLINE.W E Region 2, Office of Director JENKINB.O R Division of Emergency Preparedness & Materials Safety 84/02/15 App 22655 338 24X Fiche 50-269,84/02/16,8403160134
- 840301030B Forwards addi info re 830B15 request for relief from inservice insp requirements (Hydrostatic) of Section XI of ABME Boiler & Pressure Vessel Code Valve 2LPBH-133 cannot be closed due to researed hinge pins TUCKER.H B Duke Power Co 84/02/23 DENTON.H R Office of Nuclear Reactor Regulation. Director STOL7.JF Operating Reactors Branch 4 2pp 22432 102 24X Fiche 50-269.84/02/23,8403010308
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22709 237 24X Fiche 50-000,84/02/28,8401190072
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl GRACE.J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidate Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000.84/03/02,8402090007

- 840209000B IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys
 - Valves to Operate " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/02 Consolidated Edison Co of New York, Inc. 122pp 2253 098 24X Fire 50-000.84/03/02,8402090006
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases"
 - Svc list encl JORDAN.E L D Response (Post nci Division of Emergency Preparedness & Engineering Post 930103) B4/03/02 Consolidated Edison Co of New 119pp 22553 217 24X Fiche 50-000.84/03/02,8402090009
- 8402090011 IE info Notice 84-17. "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Syr list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402070011
- 8402070024 IE Info Notice 84-09. Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Bys " Evt list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc. 118pp 22635 049 24X Ficha 50-000.84/03/07.8402070024 110pp
- 8402090028 IE Impo Notice 84-18, "Stress Corrosion Cracking in PWR 102090020 IE into notice 1. ... Sys " 8ve list enc! JORDAN:E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc. 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8402070031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Syc list ent! DEYGUNG.R C Director's Office Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000.84/03/12.8402090031
- 8403290049 Ack receipt of 840208 ltr informing NRC of steps taken to correct violations noted in JE Insp Repts 50-249/83-36, 50-270/83-37 & 50-287/83-36 implementation of corrective actions will be examined during future insp DANCE-H C Division of Project & Resident Programs 84/03/20 TUCKER, H B Duke Power Co 1p 22807 011 24X Fiche 50-269, 84/03/20,8403290069
- --8403290082 Responds to NRC 840109 ltr re violations noted in IE Insp. Repts 50-269/83-36, 50-270/83-37 & 50-287/83-36 Corrective actions Unit 2 staging coil locations corrected & seal packages on Reactor Coolant Pump 282 replaced TUCKER, H B Duke Power Co 84/02/09 0'REILLY, J P Region 2, Office of Director 2pp 22807 012 24X Fiche 50-269, 84/03/20, 8403290067
- --B403290090 Forwards IE Insp Repts 50-269/B3-36, 50-270/B3-37 & 50-287/B3-36 on B31111-1210 & notice of vialation DANCE.H C Division of Project & Resident Programs B4/01/TUCKER.H B Duke Power Co 2pp 22807 014 24X Fiche 50-269, 84/03/20, 8403290069 84/01/09
- --8403290095 Notice of violation from insp on 831111-1210 * Region 2, Office of Director 84/01/09 ip 228 Fiche 50-269.84/03/20.8403290069 22807 016
- --8403290108 IE lnsp Repts 50-269/83-36,50-270/83-37 & 50-287/83-36 on 831111-1210 Violation noted failure to follow Maint Procedure 270/83-37-01 re quality performed on Reactor Collant Pump 2BR BRYANT, J. FALCDNER, D. Regian 2. Office of Director BROWNLEE, V L. Division of Project & Resident Programs 84/01/09 10pp 22807 017, 24X Fiche 30-269,84/03/20,8403290069
- 8402090043 IE Info Natice 84-19. "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JURDANIE L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Int. 123pp 22823 229 24X Fiche 50-000.84/03/21.8402090043
- B402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related 102094044 : A NEW STATE STATE
- R Periodic operating reports & related correspondence
- 8403200010 Monthly operating repts for Feb 1984 W/840315 ltr REAVIB.J A. TUCKER, H II Duke Power Co 84/02/29 17pp. 22685 185 24% Fiche 50-269,84/02/29,8403200010

V Operator Examinations

- 8403080239 Forwards operator licensing exam schedule through CY88, in TUCKER.H B Duke Power Co 84/02/27 EIBENHUT.D G Division of Licensing 2pp 22561 023 24X Fiche 50-269.84/02/29.8403080239
- DOCKET 50-271 VERMONT YANKEE NUCLEAR POWER STATION Security, medical, emergency & fire protection plans
- 8403060022 Advises that NRC will not review emergency plans to delete puluovek Advises that NRC will not review emergency plans to privacy or proprietary info unless specifically requested by licensee.per 810709 Generic Ltr 81-27 W/o request, entire plan will be placed in PDR VASSALLO,D B Operating Reactors Branch 2 84/02/21 BINC Vermont Yankee Nuclear Power Corp 2pp 22528 336 24X Fiche 50-271,84/02/21,8403060022 BINCLAIR, J B
- 8403140285 Informs that onsite & offsite emergency preparedness adequate & emergency plans upgraded per NUREG-0737. Item III A 2 i Reasonable assurance exists that prompt protective measures will be taken to protect public VASSALLO, B 8 Operating Reactors Branch 2 84702/22 BINCL/ Vermont Yanker Nuclear Power Corp 3pp. 22636:320 24X Fiche 50-271:84/02/22,8403140285 BINCLAIR, J B
- B403140270 Approves 83iii6 request to establish emergency operations facility (EGF) B 75 miles from plant ω/o providing backup EOF 84/02/27 EUSENHUT,D Q Division of Licensing 84/02/27 M Vermont Yankes Nuclear Power Corp 2pp 22636 318 MIRRHY, U.P. Fiche 50-271.84/02/27.8403140290
- B403190243 Notification of B40418 workshop in King of Prussia.PA to discuss lessons learned from recent App R fire protection safe shutdown insp & tupics described in IE Info Notice B4-09 Agenda for workshop ent!

 MRRLEY.T E Region I, Office of Director 94/03/09 O'TOOLE.J.I Consolidated Edison Co of New York. Inc LUNDVALL.A E Baltimos Cas & Electric Co RANDAZZA.JB Maine Yankee Atomic Power Co 35pp 22672 062 24X Fiche 50-000.84/03/09.8403190243 O'TOOLE, J D Baltimore
- 8403290064 Forwards IE Enforcement Conference Rept 50-271/83-26 on 840i10 Util has not provided NRC w/required fire protection features for certain equipment in reactor bldg to achieve & features for certain equipment in reactor only to be deficient and maintain safe shutdown
 MARTIN.T Division of Engineering & Technical Programs. 84/03/13
 MURPHY,W P Vermont Yankee Nuclear Power Corp 2pp 22806 283
 24X Fiche 50-271.84/03/13.8403270064
- --8403270071 IE Enforcement Conference Rept 50-271/83-26 on 840110 Major areas discussed potential violation of 10CFR50.App R refailure to provide fire protection for redundant safe shutdown equipment located primarily in reactor bldg PULLANT.S V. ANDERSON.C J. Region I. Office of Director 84/03/06 7pp 22806 285. 24X Fiche 50-271.84/03/13.8403290064
- 8403230063 Requests eight exemptions from IOCFR30. App R requirements re fire protection of safe shutdown capability Exemption request approval will negate need to provide alternate shutdown capability.per Section III G of App R HUPPHY.W P Vermont Yankee Nuclear Power Corp 84/03/14 DENTON.H R Office of Nuclear Reactor Regulation, Director 20pp 22735 022 24X Fiche 50-271,84/03/14,8403230063
- 8403200166 Forwards FEMA 820609 final post-exercise assessment for 403200146 Forwards FERM 820609 final pose-exercise assessme 820218 joint radiological emergency preparedness exercise Rept for 830921 exercise will be issued shortly MARTIN, T T Division of Engineering & Technical Programs MURPHY, H P Vermont Yankee Nuclear Power Corp 3pp 22 24X Fiche 50-271,84/03/15.8403200166 2249B 041
- P Operating license stage documents & correspondence
- 8403140340 Summary of 831215 meeting w/0E k Mark I Owners Group in Bethesda:MD re Mark I containment wetwell-drywell vacuum breaker design methodology SIEGEL.B L. Operating Reactors Branch 2 84/02/21 Operating Reactors Branch 2 51pp 22635 198 24X Fiche 50-000.84/02/21, 8403140340
- B403020247 Informs of completion of add1 analysis for frequency response of associated hydraulic control units (HCU) for scram sys HCU supports should be modified Installation of mods expected by end of yr MURPHY, WP Vermont Yankee Nuclear Power Corp 84/02/28 VASSALLO, D B Operating Reactors Branch 2 1p 22440 100, 24X Fiche 50-271,84/02/28,8403020247

- 8403070304 Provides responses to three open items from NRC/BNL Yankee Atomic Electric Co & consultants Mark I containment program plant-unique analysis rept 840216 review meeting CELIA, N S Teledyne Engineering Services 84/02/28 SIEGEL, 8 NRC No Detailed Affiliation Given 4pp 22546 171 24X Fiche 50-000.84/02/28.8403070304
- 8403120003 Forwards Rev O to "Vermont Yankee Nuclear Power Station Offsite Dose Calculation Manual" used to implement provisions of radiological efficent Tech Space SINCLAIR.J B Vermont Yankee Nuclear Power Corp 84/03/05 VASSALLO,D B Operating Reactors Branch 2 5pp 22589 304 24X Fiche 50-271,84/03/05,8403120003
- --B403120005 Rev O to, "Vermont Yankee Nuclear Power Station Offsite Dose Calculation Manual" * Vermont Yankee Nuclear Power Corp 84/03/05 108pp 22889 309 24X Fiche 50-271.84/03/05.8403120003
- 8403070240 Summary of 840216 meeting w/Northeast Nuclear Energy Co. Boston Edison Co.Vermont Yankee Nuclear Power Co & Teledyne Engineering Svcs in Waltham MA re add! Mark I torus structural analysis List of attendees encl SHEA: J J Operating Reactors Branch 5 SIEGEL, B Operating Reactors Branch 2 84/03/07 CRUTCHFIELD, D Operating Reactors Branch 5 4pp 22572 298 24X Fiche 50-000.84/03/07.8403090240
- 8403300268 Forwards request for addl info re operation of purge & vent valves Response requested within 60 days
 VABBALLO, D B Operating Reactors Branch 2 84/03/12 SINCLAIR, J B Vermont Yankee Nuclear Power Corp 3pp 22844 331 24X
 Fiche 50-271, 84/03/12, 8403300268
- B403150275 Generic Ltr B4-07 to all licensees of BWRs re procedural guidance for pipe replacement at BWRs Svc 11st encl EIBENHUT, D 0 Division of Licensing B4/03/14 Commonweelth Edison Co 20pp 22823 354 24% Fiche 50-000,84/03/14,8403150275
- 8403270190 Forwards supplemental info in response to Generic Ltr 83-28 re required actions based on generic implications of Salem ATWS events MURPHY, W P Vermont Yankee Nuclear Power Corp 84/03/23 VA8SALLO, D B Operating Reactors Branch 2 10pp 22772 171 24X Fiche 50-271, 84/03/23, 8403270190
- Q Inspection reports, IE Bulletins & correspondence
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JURDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22709 239 24X Fiche 50-000,84/02/28,8401190072
- B402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl GRACE.JN Division of QA, Safeguards & Inspection Programs (Post B30103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000,84/03/02,8402090007
- 8402070008 IE Info Notice 84-i6, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000,84/03/02,8402070008
- B402090009 IE Info Notice 84-i5, "Reporting of Radiological Releases"

 Bvc list encl

 JGRDAN.E L Division of Emergency Preparedness & Engineering

 Response (Post 830103) 84/03/02 Consolidated Edison Co of New

 York, Inc 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Balow Nil Ductility Temp " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/05, Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8402090024 IE Info Notice 84-09, Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys." Svc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc. 118pp 22635 049 24X Fiche 50-000, 84/03/07, 8402090024
- B402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Bys." Byt list entl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028

- B402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IC Safety Sys " Svc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York. Inc 134pp 22823 094 24X Fichs 50-000.84/03/12.8402090031
- 8403200274 Forwards "Recirculation & RHR Weld Joint Insp Program ~ 1984 Refueling Outage " Refueling scheduled to commence 840616 BINCLAIR.J B Vermont Yankee Nuclear Power Corp 84/03/13 VASSALLO, D B Operating Reactors Branch 2 2pp 22696 126 24X Fiche 50-271.84/03/13.8403200274
- --8403200277 "Recirculation & RHR Weld Joint Insp Program 1784 Refueling Outage " * Vermont Yankes Nuclear Power Corp 84/03/13 43pp 22696 128 24X Fiche 50-271.84/03/13.8403200274
- B403290064 Forwards IE Enforcement Conference Rept 50-271/83-26 on 840110 Util has not provided NRC w/required fire protection features for certain equipment in reactor blig to achieve & maintain safe shutduum MARTIN.T T Division of Engineering & Technical Programs 84/03/13 MURPHY. W P vermont Yankee Nuclear Power Corp 2pp 22806 283 24X Fiche 50-271.84/03/13.8403290064
- --B403270071 IE Enforcement Conference Rept 50-271/83-24 on 840110 Major areas discussed potential violation of 10CFR50. App R refailure to provide fire protection for redundant safe shutdown equipment located primarily in reactor bldg PULLANI, S V . ANDERSON, C J Region 1. Office of Director 84/03/06 7pp 22806 285 24x Fiche 50-271.84/03/13.8403290064
- 8403200156 Responds to IE Bulletin 80-11, "Masonry Wall Design"
 Reanalysis of 10 masonry walls completed Add1 time required
 to verify results Reanalysis program will be completed by
 June 1784
 MURPHY, W.P. Vermont Yankee Nuclear Power Corp. 84/03/15
 VASSALIO, D.B. Despating Reactors Branch 2 in 27496-362
- WURPHY, W P. Vermont Yankee Nuclear Power Corp. 84/03/15 VABBALLO, D. B. Operating Reactors Branch 2 1p. 22696-362 24X Fiche 50-271,84/03/15,8403200136
- 8402090043 IE Info Notice 84~19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000,84/03/21,8402090043
- 8402070044 IE Info Notice B4-20, "Svc Life of Relays in Safety-Related Sys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22733 001 24X Fiche 50-000.84/03/21,8402070044
- 8403300153 Responds to IE Bulletin 83-07 re apparently fraudulent products sold by Ray Miller. Inc No evidence found that subj math supplied directly or indirectly by Ray Miller. Inc for use at factlity MURPHY.W P Vermont Yankee Nuclear Power Corp 84/03/22 MURPHY.T E Region 1. Office of Director 2pp 22821 014 24X Fiche 50-271,84/03/22,8403300153
- B403300065 Ack receipt of 840302 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-271/83-33 MARTIN.T T Division of Engineering & Technical Programs 84/03/23 MURPHY.W P Vermont Yankee Nuclear Power Corp 2pp 22821 291 24X Fiche 50-271.84/03/23.8403300065
- --8403300071 Responds to NRC 840131 ltr re violations noted in IE Insp Rept 50-271/83-33 Corrective actions Procedure OP 0533, "Body Burden Counting," will be revised MURPHY, W P Vermont Yankee Nuclear Power Corp 84/03/02 MARTIN, T T Division of Engineering & Technical Programs 2pp 22821 293 24X Fiche, 50-271,84/03/23,8403300065
- 8403300142 Ack receipt of 840302 itr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-271/83-30 MARTIN T Division of Engineering & Technical Programs 84/03/23 MURPHY.W P Varmont Yankee Nuclear Power Corp 1p 22820 358 24X Fiche 50-271.84/03/23.8403300142
- ---B403300146 Responds to NRC B40201 itr re-violations noted in IE Insp. Rept 50-271/83-30 Corrective actions radiation surveys will be made using both Eberline R0-2 & E-520 instrumentation Health physics mgt approval will be required MURPHY.W P Vermont Yankee Nuclear Power Corp B4/03/02 MURLEY.T E Region 1. Office of Director App 22821 359 24% Fiche 50-271,84/03/23.8403300142

- R Periodic operating reports & related correspondence
- 8403130481 "Annual Operating Rept for 1983 " W/840305 ltm NOSLOGAR. J B Vermont Yantes Nuclear Power Corp 83/12/31
 NURLEY, T E Region 1, Office of Director 10pp 22613 199
 Fiche, 50-271, 83/12/31, 8403130481 24 Y
- 8403230140 Personnel exposure annual rept for 1783 W/840312 ltr SINCLAIR.J.B Vermont Yankee Nuclear Power Corp 83/12/31 MURLEY.T E Region 1. Office of Director 3pp 22730 231 24X Fiche 50-271.83/12/31.8403230140
- 8403190086 Monthly operating rept for Feb 1984 W/840309 ltr BURGER.F J , MURPHY.W P Vermont Yankee Nuclear Power Corp 84/02/29 7pp 22669 220 24% Fiche 50-271,84/02/29,8403190086
- 8 Reportable occurrences. LERs & related correspondence
- 8403050223 Further response to FDIA request for records of named individuals, including repts, analyses, studies, test calculations, procedures & practices for measurement of RGS leakage Forwards App C documents Search continuing FELTON, J M Division of Rules and Records 84/02/07 MADDEN, T J. Kaye, Scholer, Fierman, Hays & Handler 3pp 22496 234 24% Fiche 30-000,84/02/07,8403050223
- --8403050R41 Forwards potentially generic issue data sheet on 800611 event re failure of BWR drywell leakage detection sys to identify Significant leakage BRUNNER. J. Region 1. Philadelphia. Office of the Director 80/07/10 JORDAN.E L. Region 1. Philadelphia. Office of the Director LEWIS.R C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch HEISHMAN.R F. Region 3. Chicago, Reactor Operations Nuclear Support Branch 2pp 22496 257 24X Fiche 50-000,84/02/07,8403050223
- 8403020322 Forwards LERs 84-001-01 & 84-002-00 PELLETIER, J P Vermont Vanice Nuclear Power Corp & Record Services Branch (Document Control Desk) ip Fiche 50-271,84/02/27,8403020322 84/02/27 22439 307
- --B403020326 LER B4-001-01 on B40105 pressure transient generated, resulting in reactor trip Caused by instability in turbine controls sys Instruments which provide trip checked & one channel recalibr PELLETIER. J P. Vermont Yankee Nuclear Power Corp 84/02/27 22439 308 24X Fiche. 50-271, 84/02/27, 8403020322 84/02/27 200
- --8403020328 LER 84-002-00 on 840202; torus-reactor blig vacuum breaker sys found out of calibr Caused by setpoint drift Switch setpoints readjusted to Tech Spec requirements PELLETIER, J.P. Vermont Yankee Nuclear Power Corp. 84/02/27 2pp. 22439 310 24X Fiche 50-271,84/02/27.8403020322
- DOCKET 50-272 BALEM NUCLEAR GENERATING STATION, UNIT 1 F Security, medical, emergency & fire protection plans
- 8403160192 Forwards IE Insp Rept 50-272/83-37 on 831205-06 & 840116-20 Full compliance wifire protection features for safe shutdown apparently not achieved MARTIN.T T Division of Engineering & Technical Programs 84/0 UDERITZ.R A Public Service Electric & Gas Co of New Jersey 22655: 291 24X Fiche 50-272,84/03/02,8403160152 84/03/02
- --8403160157 lE losp Rept 50-272/83-37 on 831205-06 & 840116-20 Noncompliance noted failure to provide fire protection features required by App R.Section III G for safe shutdown in five areas of plant I.S. ANDERSON.C. Region 1. Office of Director 84/03/01 22655 294 24X Fiche 50-272,84/03/02,8403160152
- 8403190433 Responds to 821206 & 830718 ltrs re emergency operations facility (EOF) Request to establish primary EOF 7 5 miles from facility w/o providing backup EOF acceptable EISENHUT, D 0 Division of Licensing 84/03/05 LIDEN, E A Publisherice Electric & Gas Co of New Jersey, 1p 22681 325, 24% Fiche 50-272,84/03/05,8403190433 Public
- B403i30171 Forwards FEMA post-exercise assessment for 831024 joint exercise of State of DE & local radiological emergency preparedness plans for facility MARTIN.T T Division of Engineering & Technical Programs 84/03 UBERITZ.R A Public Service Electric & Gas Co of New Jersey 22599 223 24X Fiche 50-272,84/03/07.8403130171
- --8403130178 Evaluation of 831026 joint exercise of State of DE & local radiological emergency preparedness plans for facility.

 * Federal Emergency Management Agency 83/11/25 72pp 22597 226 24% Fiche 50-272,84/03/07,8403130171.

- 8403220006 Forwards IE Insp Repts 50-272/84-06 & 50-311/84-06 on 840206-10 No violations observed MARTIN, T T Division of Engineering & Technical Programs 84/03/08 UDERITZ.R A Public Service Electric & Oas Co of New Jersey 2pp 22716 174 24X Fiche 50-272.84/03/08.8403220006
- --B403220010 IE Insp Repts 50-272/B4-06 & 50-311/B4-06 on B40206-10 No violations noted Major areas inspected security organization, security program audit testing & maint, physical barriers, security sys power supply & assessment aids MADDEN.H J. BAILEY.R J. JOYNER.J H. Region 1. Office of Director B4/03/06 4pp 22716 176 24X Fiche 50-272, B4/03/08, B403220006
- B403170243 Notification of B40418 workshop in King of Prussia, PA to discuss lessons learned from recent App R fire protection safe shuddown insp & topics described in IE Info Notice B4-07 Agenda for workshop and MURLEY, TE Region 1. Office of Director Consolidated Edison Co of New York, Inc Power Authority of the State of New York 35pp 22672-062 24x Fiche 50-000.84/03/09,8403190243
- J Insurance & indemnity information
- 8403260197 Forwards Endorsament 48 to NELIA Policy NF-236, Endorsaments 69 & 72 to NELIA Policy NF-208, Endorsament 59 to MAELU Policy MF-77 & Endorsament 67 to NELIA Policy NF-230, OULDEN, M.P. Marsh & McLennan, Inc. 84/03/12 8ALTIMAN, J. Assistant Director for State & Licensee Relations, 6pp 22751 033 24X Fiche 50-000,84/03/12,8403260197
- B4032B005B Forwards Endorsements 68 & 69 to NELIA Policy NF-230 & Endorsements 54 & 55 to MAELU Policy MF-90 GOLDEN, M P Marsh & McLennan, Inc 84/03/21 SALTZMAN, J. Assistant Director for State & Licensee Relations 5pp 22776 24X Fiche 50-272, 84/03/21, 8403280058
- P Operating license stage documents & correspondence
- 8403090049 Submits details of vendor manual review program in response to 830504 order modifying licenses Commitment to Incorporate all vendor manuals for safety-related equipment into document control sys completed in 10EN, E.A. Public Service Electric & Qas. Co. of New Jersey. 84/02/22 KISTER.H B. Division of Project & Resignnt Programs 3pp 22575.345 24X Fiche. 50-272.84/02/22.8403090049
- 8403030119 Forwards supplemental response to Generic Ltr 83-28, "Required Actions Based on Generic Implications of Balem ATMS Events" BARNES, P.L. Commonwealth Edison Co. 84/02/29 DENTON, H.R. Def of Nuclear Reactor Regulation, Director 26pp. 22488 084 24x Fiche 50-000,84/02/29,8403050119 Defice
- 8403130017 Requests extension for updating inadequate core cooling instrumentation & reactor yessel level instrumentation sys status repts per TMI Item II F 2 & providing Mestinghouse proprietary info until 840402 LIDEN,E A Public Service Electric & Gas Co of New Jersey 84/03/02 VARGA,S A Operating Reactors Branch 1 ip 22614 361 24X Fiche 50-272.84/03/02.8403130017
- 8403250050 Requests identification of any potential problems or items re completion of NUREO-0737 items by Sept 1984 Response requested within 30 days of itr receipt VAROA, 8 A Operating Reactors Branch 1 84/03/02 UDERITZ, R A Public Bervice Electric & Gas Co of New Jersey. 3pp 22763 281 24% Fichs 50-278.84/03/02,8403260050
- B403140113 Forwards "Salem Generating Station 316(b) Demonstration," per 830623 request for addl info re review of OL application for Hope Creek
 MITTL.R L Public Service Electric & Qas Co of New Jarsey
 B4/03/05 SCHWENCER,A Licensing Branch 2 ip. 22629 124 24X
 Fichs.50-000.84/03/05,8403140113
- --8403140117 "Salem Generating Station 316(b) Demonstration "
 # Public Service Electric & Gas Co. of New Jersey 84/02/29, 647pp 22629, 125 24X Fichs 30-000.84/03/05.8403140113.
- B4032702B1 Forwards plant-specific info on reactor protection sys shunt trip mods in response to NRC B30810 ltr & Generic Ltr B3-2B Shunt trip mechanism will be installed during refueling outage. W/14 oversize drawings Aperture cards in PDR LIDEN.E A Public Service Electric & Gas Co of New Jersey B4/03/14 VARGALS A Operating Reactors Branch 1 14pp. 22800 200 24X Fiche 50-272.84/03/14.8403290281

- 8403300085 Requests extension to Jul 1984 for completion of post-maint operability testing of safety-related equipment based on revised interpretation of scope identified through discussion w/Region I personnel
 LIDEN.E A Public Service Electric & Gas Co of New Jersey
 84/03/23 VARGA.S A Operating Reactors Branch I 3pp 22822 073
 24X Fiche 50-272.84/03/23.8403300085
- Q Inspection reports, IE Bulletins & correspondence
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22909 239 24X Fiche 50-000,84/02/28,8401190072
- 8403070080 Submits supplemental response to IE Bulletin 83-06 re nonconforming maths supplied by Tube-Line Corp Remaining four suppliers confirmed that no subj maths supplied to Hope Creek Colt Industries info under review MARTIN.T J Public Service Electric & Gas Co of New Jersey 84/02/28 MURLEY.T E Region 1. Office of Director 2pp 22575 297 24% Fiche 50-000.84/02/28.8403090080
- 8403150068 Forwards IE Insp Repts 50~272/84~02 & 50-311/84-02 on B40116-19 No violations observed MARTIN.T T Division of Engineering & Technical Programs 84/02/28 UNDERITI.R A Public Service Electric & Gas Co. of New Jersey 2pp 22643 177 24X Fiche 50-272.84/02/28,8403150068
- --8403150078 IE Insp Repts 50-272/84~02 & 50-311/84-02 on 840116-19 No violations observed Major areas inspected nonradiological chemical measurements. GC program of analytical measurements & procedures & training ZIBULSKY, H, KITTAN, JJ, PASCIAK, WJ, Region 1, Dffice of Director 84/02/27 3pp 22643 179 24X Fiche 50-272.84/02/28, 8403190068
- B402090007 IE Info Notice B4-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl GRACE, J N Division of GA, Bareguards & Inspection Programs (Post B30103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000,84/03/02,8402090007
- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN, E L Division of Emergency Preparadness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases "
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8403160152 Forwards IE Insp Rept 50-272/83-37 on B31205-06 & B40116-20 Full compilance w/fire protection features for safe shutdown apparently not achieved MARTIN.T T Division of Engineering & Technical Programs 84/03/02 UDERITZ.R A Public Service Electric & Gas Co of New Jersey 3pp 22655 291 24X Fiche 50-272,84/03/02.8403160152
- --8403160157 IE Insp Rept 80-272/83-37 on 831205-06 & 840116-20 Noncompliance noted failure to provide fire protection features required by App R.Section III 0 for safe shutdown in five areas of plant PULANIS 6. ANDERSON. C Region 1. Office of Director 84/03/01 23pp 22655 294 24X Fichs 50-272,84/03/02,8403160152
- B402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp" 8vc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/05 Consolidated Edison Co of New York: Inc 117pp. 22553 336 24X Fiche 50-000,84/03/05. B402090011.
- 8403220105 Forwards IE Insp Repts 50-272/84-04 & 50-311/84-04 on 840111-0206 No violations observed STAROSTECKI, R Division of Project & Resident Programs 84/03/06 UDERITZ R A Public Service Electric & Gas Co of New Jersey 2p 22715 285 24x Fiche 50-272,84/03/06.8403220105
- ---B403220113 IE Insp Repts 50-272/B4-04 & 50-311/B4-04 on B40111-0206 No violations identified Major areas inspected status of previous insp items.review of periodic & special repts, LER review & operational safety verification LINVILLE, J C , SUMMERS, R J Region 1, Office of Director NORRHOLM, L J Division of Project & Resident Programs 84/02/27 17pp 22715 287 24X Fichs 50-272,84/03/06,8403220105

- 8402090024 IE Info Notice 84-09, Rev 1. 'Løssons Learned from Inaps of fire Protection Safe Shutdown Sys " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York: Inc 118pp 22635 049 24X Fiche 50-000, 84/03/07, 8402090024
- 8402070028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Sys " Svr list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24x Fiche 50-000,84/03/07,8402070028
- B403220006 Forwards IE Insp Repts 50-272/84-06 & 50-311/84-06 on B40206-10 No violations observed MARTIN.T T Division of Engineering & Technical Programs 84/03/08 UDERITZ.R A Public Service Electric & Gas Co of New Jersey 2pp 22716 174 24X Fiche 50-272,84/03/08.8403220006
- --BA03220010 lE Insp Repts 50-272/84-06 & 50-3i1/B4-06 on B40206-10 No violations noted Major areas inspected security organization, security program audit testing & maint, physical barriers security sys power supply & assessment aids MADDEN.W J , BAILEY,R J , JOYNER, J H Region 1, Office of Director 84/03/06 4pp 22716 176 24X Fiche 50-272,84/03/08,8403220006
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety 8ys " Svc list encl DEYQUNG.R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24% Fiche 50-000.84/03/12.8402090031
- 8403220036 Responds to IE Bulletin 83-07, "Apparently Fraudulent Products 801d By Ray Miller.Inc "Companies supplying matls or svcs to facilities listed No matl purchased from Ray Miller.Inc LIDEN,E A Public Service Electric & Oas Co of New Jersey 84/03/14 HURLEY.T E Region I. Office of Director App 22865 166 24x Fiche 50-272,84/03/14.8403220036
- B403270206 Forwards IE Mgt Meeting Repts 50-272/84-11 & 50-311/84-11 on 840201 Corrective actions taken for ALARA program deficiencies noted in IE Insp Repts 50-272/83-22 & 50-311/83-22 adequate MARTIN,T T Division of Engineering & Technical Programs 84/03/15 UDERITZ.R A Public Service Electric & Gas Co of New Jersey 2pp 22803 288 24X Fiche 50-272,84/03/15,8403270206
- --8403270210 IE Mgt Meeting Repts 50-272/84-ii & 50-311/84-11 on 840201
 Major areas discussed planned improvements in program to
 reduce personnel occupational radiation exposure to ALARA
 Corrective action acceptable
 NIMITZ.R L , SHANBAKY.N M Region i, Office of Director
 84/03/06 3pp 28803 270 24X Fiche 50-272,84/03/15,8403270206
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PMR Reactor Cavities" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000.84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc list enci JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000.84/03/21.8402090044
- 8403270135 Forwards IE Mgt Meeting Repts 50-272/84-12 & 50-311/84-12 on 840306 to discuss util action plan for improving nuclear dept operations STAROBTECKI, R Division of Project & Resident Programs 84/03/22 UDERITZ, R Public Service Electric & Gas Co of New Jersey 2pp 22807 107 24% Fichs 50-272,84/03/22.840(3290135
- --B403290139 IE Mgt Meeting Repts 50-272/84-12 & 50-311/84-12 on 840306 Areas discussed overview of status of action plan to improve nuclear dept operations LINVILLE, J C , NORRHOLM, L J Region 1, Office of Director 84/03/12 70pp 22807 109 24X Fiche. 50-272,84/03/22,8403270135
- B403300171 Ack receipt of 831128 & 840304 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-22/83-27 & 50-311/83-30 STAROSTECKI.R Division of Project & Resident Programs 84/03/23 UDERITZ.R A Public Service Electric & Gas Co of New Jersey 1p 82820,032 24% Fiche 50-272.84/03/23.8403300171

- -8403300177 Suppls 831128 response to NRC 831026 ltr re violations noted im IE Insp Repts 50-272/83-27 & 50-311/83-30 Corrective actions emergency instruction action requirement, re reactor coolant pump shaft revised LIDEN.E A Public Service Electric & Oas Co of New Jersey 84/03/06 STAROSTECKI, R Division of Project & Resident Programs 4pp 28820 033 24X Fiche 50-272,84/03/23,8403300171
- -9403300183 Responds to NRC 831026 ltr re violations noted in IE Insp Repts 50-272/83-27 & 50-311/83-30 Corrective actions emergency instruction revised to increase limits for vibration & decision made to remove action requirements LIBEN.E A Public Service Electric & Oas Co of New Jersey 83/11/28 STAROSTECKI, R Division of Project & Resident Programs 3pp 22820 037 24% Fiche 50-272.84/03/23.8403300171

Periodic operating reports & related correspondence

03070305 Personnel exposure rept for 1983 W/840223 itr MIDURA/H J Public Service Electric & Oas Co of New Jersey 83/12/3i MURLEY/T E Region 1. Office of Director 7pp 22546 335 24x Fiche 50-272,83/12/3i,8403070305

03070260 Forwards "Salem Nuclear Generating Station Semiannual Radioactive Effluent Release Rept. Juj-Dec 1983." interim rept Effluent data for Fourth Quarter 1983 incomplete Revised rept expected by 840415
LIDEN.E A Public Service Electric & Gas Co of New Jersey 84/03/29 NURLEY.T Region 1, Defice of Director 2pp 22546 232 24X Fiche 50-272.84/02/29,8403070260

B403070261 "Salem Nuclear Generating Station Semiannual Radioactive Effluent Release Rept.Jul-Dec 1983" interim rept * Public Service Electric & Gas Cm of New Jersey RERR-151 83/12/31 48pp 22546 234 24X Fiche 50-272.84/02/29,8403070260

33220174 Monthly operating rept for Feb 1984 W/840310 ltr MILLER, 1. K., ZUFKO, J. M. Public Service Electric & Gas Co. of New Jersey 84/02/29 13pp 22718 103 24X Fiche 50-272,84/02/29, 8403220174

Reportable occurrences. LERs & related correspondence

11150076 Discusses events involving loss of electrical inverters including attendant inverters to vital instrument buses Recommendations provided by Nuclear Safety Analysis Ctr are excellent in helping to reduce instrument failures
ASHE.F. Reactor Operations Analysis Branch 82/10/21 SEYFRIT.K V. Reactor Operations Analysis Branch 8pp 22775 223 24X
Fiche 50-000.82/10/21.8211150076

D2100196 LER 84-002-00 on 840107, inlet valve 13CN27 closed due to spurious high level in feedwater beater 15C Caused by heater typess ICM47 failing to open Bypass differential setpoint lowered & signal summator module replaced W/840206 itr RUFP, J. L. ZUPKD, J. M. Public Service Electric & Gas Co. of New Jersey 84/02/06 5pp 22313 001 24X Fiche 50-272,84/02/06,3402100176

33080013 Supplemental LER 81-059/01X-01 on 810616, during initial esting, auxiliary feedwater pump 23 turbing steam supply theck valves 21M946 & 23M846 found damaged internally Caused by steam flow sys oscillations H/840224 ltr
3 TUPKO, J M Fublic Service Electric & Gas Co of New Jersey 84/02/24 4pp 22559 239 24X Fiche 50-272,84/02/24,8403080013

13080252 Supplemental LER 79-068/03X-1 on 791018, safety injection ump motor 12 tripped on overcurrent Caused by impeller acknots improperly secured at meg facility Pumps reassembled using Locktote compound W/840224 ltr

14PP-J , ZUPKO, J & Public Service Electric & Gas Co of New Jersey 84/02/24 4pp 22557 100 24X Fiche 50-272, 84/02/24,8403080252

3270244 LER 84-005-00 on 840224, reactor trip occurred from 100% lower Caused by turbine generator tripping on generator leutral ground protection investigation into extent & cause f damage in progress W/840323 itr
[UPP.J L , ZUPKO.J M Public Service Electric & Gas Co of New Jersey 84/03/23 App 22771 312 24X Fithe 50-272, 84/03/23, 1403270244

U Congressional/Executive Correspondence

- B403150336 Responds to B40131 request for explanation of recent facility annual review Personnel mgt & organization attitudes affected low rating If performance unacceptable, immediate enforcement action will be taken DIRCKS.W J Office of the Executive Director for Operations 84/03/06 ROTH.W V Senate 2pp 22649 265 24X Fiche 50-272.84/03/06.8403150336
- --8403150341 Requests explanation of implications of rating of unsatisfactory in area of plant operations ROTH, W Senate 84/01/31 PALLADINO, N J Commissioners 3pp 22649 268 24X Fiche 50-272,84/03/06,8403150336

V Operator Examinations

8403060312 Responds to 840124 ltr re licensed operator requalification program Quitzes used to determine weaknesses & need for emphasis on subjectionsed operator training program Training Procedure TP-305 revised LIDEN.E A Fublic Service Electric & Gas Co of New Jersey 84/02/28 VARQALS A Assistant Director for Operating Reactors 2pp 22515 333 24X Fiche 50-272.84/02/28.8403060312

DOCKET 50-275 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 1

E NRC Safety Evaluation Report (SER), supple & correspondence

8403080085 FDIA request for SER & SSER 21 (NUREG-0675) re operation of facilities
GARDE, B P Government Accountability Project 84/01/09 Office of Administration 2pp 22584 074 24% Fiche 50-275,84/01/09, 8403080085

B403080076 Partial response to FOIA request for SER re operation of facilities Forwards documents listed on app Documents also placed in PDR Review of remaining documents continuing FELTON.J M Division of Rules and Records 84/01/23 GARDE, B P Government Accountability Project 2pp 22984 076 24X Fiche 50-275,84/01/23,8403080075

--8403080103 Allegations 51 & 52 re NRC concern that plant personnel reluctant to come forward w/safety concerns since candor endangers jubs * NRC - No Detailed Affiliation Given 84/01/23 2pp 22584 089 24X Fiche 50-275.84/01/23.8403080096

B403150147 Supple B40217 response to SSER Items 61 & 102 re design control process Design control process adequately controlled & const completed as specified SCHUYLER.J D Pacific Gas & Electric Co 84/02/25 MARTIN, J B Region 3. Office of Director 11pp 22639 351 24X Ficho 50-275,84/02/23,8403150147

8403060564 Forwards SSER 17 re util application for OLs, Suppl addresses NRC evaluation re breatwater & superstrut issues M/o enci KNIGHTON, G W Licensing Branch 3 84/02/27 SCHUYLER, J D Pacific Gas & Electric Co 4pp 22552 265 24X Fiche 50-275, 84/02/27, B403360564

84-03070104 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF DIABLO CANYON NUCLEAR POWER PLANT, UNITS 1 AND 2 Docket Nos 50-275 And 50-323 (Pacific Gas And Electric Company) 4 Division of Licensing NUREO-0675 817 84/02/27 22pp Available at NRC 43 00 22561 214 24X Fiche 50-275,84/02/27,884/0370164

8402090030 Buard Notification 84-035 updates allegation listed in SSER 21 & Board Notification 84-003 Public allegations not previously forwarded & characterizations of allegations from confidential sources encl EISENHUT.D G Division of Licensing 84/03/02 PALLADING, GILINSKY, ROBERTS Commissioners 11pp 22556 061 24X Fiche 50-275,84/03/02,8402090030

- --8312140347 Forwards Nuclear Svc Corp 1977 audit of Pullman Power Products work scope at facility, in response to 831004 ltr to Chairman Palladino Attention called to ASLAB 831024 denial of Joint Intervenor 831020 motion to reopen record DIRCKS.W J Office of the Executive Director for Operations 83/11/18 THOMAG.W M House of Rep 4pp 22556 080 24X Fiche 50-275,84/03/02,8402090030
- --B312140351 Forwards JR Reynolds 830921 ltr expressing concern on behalf of Joint Intervenors re deficient design & const of facility Nuclear Svc Corp 1977 audit encl THOMAS, W M House of Rep 83/10/04 PALLADINO, N Commissioners 4pp 22556 081 24X Fiche 50-275,84/03/02,8402090030

- --8403080281 "Audit Rept Pullman Power Products Work Scope at Diablo Canyon Site 770822-0920 " WEBERJ, J. LARSEN, G J., NEHMAN, T C Pacific Gas & Electric Co 77/09/20 42pp 22556 090 24% Fiche 50-275.84/03/02,8402090030
- --8312280099 Responds to 831021 ltr re rept of 1977 audit of Pullman Pawer Products Corp Motion filed before NRC for revocation or in alternative continuation of suspension of low power OL for facility Matter referred to NRC DIRCKS.W J Office of the Executive Director for Operations 83/11/18 PANETTA.L E House of Rep 4pp 22596 132 24X Fiche 50-275,84/03/02.8402090030
- --B312280102 Requests response to allegations made in Nuclear Svcs Corpenct audit rept re Pullman Power Products Corp const GA afforts
 PANETTA, L. E. House of Rep. B3/10/21 PALLADINO, N. Commissioners 1p. 24X Fiche 50-275, 84/03/02, 8402090030
- --8312280107 "Proposal for Independent Internal Audit of Pullman-Kellogy Efforts at Diablo Canyon " * Nuclear Services Corp 77/07/28 21pp 22556 134 24X Fiche 50-275, 84/03/02, 8402090030
- --8401040010 Forwards all ltrs which appeared in San Luis Obispo Talegram-Tribune between 831019-31 re emergenty planning response plan for facility Lack of public confidence in response plan discussed KRANZDORF.R Affiliation Not Assigned 83/11/04 PALLADINO,N Commissioners 17pp 22556 175 24X Fiche 50-275,84/03/02, 8402090030
- 8403080405 Further response to FOIA request for documents re SER related to operation of facilities Forwards App B documents App A & B documents available in PDR Review of remaining documents subj. to request in progress
 FELTON, J M Division of Rules and Records 84/03/02 GARDE, B P Government Accountability Project 4pp 22583 073 24X
 Fiche 50~275,84/03/02,8403080405
- --B403080431 Forwards SSER input re Allegation 68 Programmatic breakdown in Pullman Power Products GA program not indicated Installed hardware safety concerns not identified LIEBERMAN.J Office of the Executive Legal Director 83/12/27 EISENHUT,D Division of Licensing 4pp 22583 163 24X Fiche 50-275,84/03/02.8403080405
- B403220172 Forwards update of closeout status of SBER 20 Open Item 2 & followup Items 1 & 9 re Hertz cutoff emergency, auxiliary feedwater sys runout control sys test & overspeed setpoint change respectively SCHUYLER. J O Pacific Gas & Electric Co B4/03/19 KNIGHTON, G W Licensing Branch 3 2pp 22717 020 24X Fiche 50-275, 84/03/19, 8403220172
- 8403300078 Responds to 840315 request for info on Item 28 of SSER 21 re annulus structure reverification Visual insps of piping performed Insp identified need for support mods Mods reinspected at operating temps 8CHUYLER, J O Pacific Gas & Electric Co 84/03/23 KNIGHTON, G W Licensing Branch 3 1p 22822 087 24X Fiche 50-275, 84/03/23, 840330078
- 8403300148 Suppls util 840215 ltr providing justification for exclusion of auxiliary feedwater level control valve actuators from severe environ exposure list per SSER 27 followup Item 5 SCHUYLER.J D Pacific Oas & Electric Co 84/03/23 KNI6HTON.G W Licensing Branch 3 ip 22820 344 24x Fiche 50-275,84/03/23,8403300148
- 8403300300 BAFETY EVALUATION REPORT RELATED TO THE OPERATION OF DIABLO CANYON NUCLEAR POWER PLANT, Units 1 AND 2 Docket Nos 50~275 And 50~323 (Pacific Rat and Electric Company)

 * Division of Licensing NUREG~0675 S22 84/03/31 400pp Available at NRC, \$11 QO 22843 001 24X Fiche 50~275.84/03/31, 8403300300
- F Security, medical, emergency & fire protection plans
- B403280114 Public version of revised emergency plan implementing procedures, including Procedures EP DP-9 re loss of reactor coolant pump w/o reactor trip & EP G-2 re establishment of organization W/640103 & 0322 memos
 THOMBERG.R C , SCHUYLER.J O Pacific Gas & Electric Co 84/01/05 MARTIN.J B Region 5, Office of Director 33pp 22811 236 24X Fiche 50~275,84/01/05,8403280114

- 8403070355 Public version of emergency plan implementing procedures, including Procedure EP G-4 personnel accountability & assembly & EP RB-12 re mid & high-range plant vent radiation monitors W/840208 ltr & JM Felton B40302 release memo THOMBERG.R C , SCHUYLER, J O Pacific Gas & Electric Co 84/01/23 MARTIN, J B Region 5, Office of Director 120pp 22565 187 24X Fiche 50-275,84/01/23,8403070395
- B40306013B Forwards IE Insp Repts 50-275/83-39 & 50-323/83-27 on B31205-22 & notice of violation B15HOP.T W Division of Resident, Reactor Project & Engineering Programs B4/02/03 SCHUYLER, J O Pacific Qas & Electric Co 2pp 22506 334 24x Fiche 50-275,84/02/03,840306013B
- --8403060142 Notice of violation from insp on 831205-22 CANTER, H L Region 5, Office of Director 84/02/03 2pp 22506 336 24X Fiche 50-275,84/02/03,8403060138
- --8403060146 IE Insp Repts 50-275/83-39 & 50-323/83-27 on 831205-22 Noncompliance noted failure to properly implement fire loss prevention procedures & suppls SCONN, K , POLICH: T , CANTER, H L Region 5, Office of Director 84/01/24 18pp 22506 338 24X Fichs 50-275/84/02/03/8403060138
- 8403090172 Forwards Rev 11 to physical security plan Rev withheld (ref 100FR73 21)
 SCHUYLER, J O Pacific Oas & Electric Co 84/02/06 MARTIN, J B Region 5, Office of Director ip 22575 047 24X
 Fiche 50-275,84/02/06,8403090172
- 8402230176 Forwards revised State of CA nuclear power plant emergency response plan MEDFORD NO Southern California Edison Co 84/02/16 EISENHUT, D & Division of Licensing 383pp 22353 001 24X Fiche 50-000,84/02/16,8402230176
- --B403020117 Revised State of CA nuclear power plant emergency response plan * California, State of 83/04/30 2901pp 22353 003 24X Fiche 50-000,84/02/16,8402230176
- 8402090006 Board Notification 84-034 forwards R Voltmer 840206 memo to D Eisenhut re fire research results concerning fires in electrical cabinets in control room EISENHUT.D 9 Division of Licensing 84/02/23 PALLADING Commissioners ip 22576 203 24X Fiche 50-000,84/02/23,8402090006
- --84030B0314 Recommends that info re fire research results concerning fires in electrical cabinets in control room be submitted for board notification, per NRR Ofc Ltr 17, dtd 821001 Further evaluation of test data required VOLLMER.R H Division of Engineering B4/02/06 EIGENHUT, D Q Division of Licensing 10pp 22376 204 24X Fiche 50-000, 84/02/23. 8402070006
- 8403080405 Further response to FOIA request for documents re SER related to operation of facilities Forwards App B documents App A & B documents available in PDR Review of remaining documents subj to request in progress

 FELIGN, J M Division of Rules and Records 84/03/02 GARDE, B P Government Accountability Project 4pp 22583 073 24X

 Fichs 50-275.84/03/02.8403080405
- --B4030B0411 Forwards response to Allegation RV-B3-A-0034.per GW Knighton 831122 note Temporarily exempting licensee from maintaining physical security & safeguards contingency plans did not increase risk of radialogical sabotage MCORRLE.G W Power Reactor Safeguards Licensing Branch B3/12/01 THOMAS.C D Standardization & Bpecial Projects Branch 4pp 225B3 077 24X Fiche 50-275.84/03/02.84030B0405
- ---8403080417 Resubmits response to Allegation RV-83-A-0034, per GW
 Knighton 831103 memo Temporarily exempting licensee from
 meintaining physical security & safeguards contingency plans
 did not increase risk of radiological sabotage
 MCCORKLE, G W Power Reactor Bafeguards Licensing Branch
 83/12/05 THOMAS, C D Standardization & Special Projects Branch
 3pp 22583 081 24X Fiche 50-275.84/03/02,8403080405
- --8403080420 Forwards response to Allegation RV-83-A-0034, per OM Knighton 821122 note Temporarily exempting licensee from maintaining physical security & safeguards contingency plans did not increase risk of radiological sabotage BURNETT.R F Division of Safeguards 83/12/08 EISENHUT.D O Division of Licensing 3pp 22983 084 24X Fiche 50-275, 84/03/02.8403080403

- 403130082 Responds to NRC 840203 ltr re violations noted in IE Insp Rept 50-275/83-39 Corrective actions area permits for welding posted to identify generic requirements on area basis & util inspector assigned to assist fire marshall SCHUYLER.J Q Pacific Gas & Electric Co 84/03/05 MARTIN.J B Region 5. Office of Director 6pp 22646 013 24X Fiche 50-275.84/03/05.8403130082
- |403280001 Forwards safeguards info re changes to Rev i! to security plan Info withheld (ref 100FR73 21)
 | SCHUYLERJ D | Pacific Gas & Electric Co | 84/03/19 | MARTIN. J B | Region 5: Office of Director | p | 22777 151 | 24X | Fiche 50-275.84/03/19; 8403280001
- |403270205 Discusses Southern California Edison submittal of 1993 revised State of CA emergency response plan on behalf of all State of CA plants.incorporating plan into Diablo Canyon Addi planning info will not be developed for Humboldt Bay SCHUYLER.J O Pacific Gas & Electric Co 84/03/22 DENTON.H R Office of Nuclear Reactor Regulation. Director 1p 22772 137 24X Fiche 50-000.84/03/22,8403270205
- MO3290264 Advises that 840111 rev to physical security plan & drawings consistent w/provisions of 10CFR50 54(p) & acceptable SCHUSIER.M D Region 5. Office of Director 84/03/23 SCHUYLER.J O Pacific Oas & Electric Co 1p 22800 010 24X Fiche 50-275.84/03/23.8403290264

Adjudicatory correspondence

- 3402090012 Board Notification 84-045 forwards 840202 petition to defer decision re low power OL, made by Govt Accountability Project (GAP) on tehalf of Ban Luis Obispo Mothers for Peace Distribution list & app encl EISENHUT. D 0 Division of Licensing 84/02/29 MOORE. T G, JOHNSON, W R, BUCK. J H Atomic Safety and Licensing Appeal Panel 5pp 67218 074 24% Fichs 50-275.84/02/29.8402090012
- ---8403060303 Petition to defer decision re issuance of low power OL until listed actions complete
 DEVINE.T M. CLEWETT. J. Covernment Accountability Project
 DEVINE.T M. San Luis Obispo Mothers for Peace 84/02/02
 Commissioners 94ipp 22508 273 24X Fiche 50-275,84/02/29,
- 403070044 Motion for extension until 840317 to file response to Joint Intervenors 840222 motion to reapen record on const ga Certificate of Svc encl NORTON, B Pacific Gas & Electric Co NORTON, B Norton, Burke, Berry & French 84702/27 Atomic Safety and Licensing Appeal Panel 5pp 22541 250 24% Fiche 50-275, 84/02/27, 8403070044
- 3403140071 Forwards expurgated transcript of 840125 meeting between staff & C Stokes, per ASLAB 840223 order W/o encl RUTBERG, J Hearing Branch 2 84/02/29 MODRE, T S , BUCK, J H , JOHNBON, W R Atomic Safety and Licensing Appeal Panel 2pp 22434 184 24X Fiche 50-275,84/02/27,8403140071
- 1403060260 Response of Governor Deukmejian to util 840229 motion for extension of time to respond to Joint Intervenor 840222 motion to reopen & motion of Deukmejian for like extension of time to reply Certificate of Svc encl STRUMHASSER. California. State of 84/03/01 Atomic Safety and Licensing Appeal Panel 9pp 22517 132 24X Fiche 50-275.84/03/01.
- 3403080118 Suppl 1 to 840214 motion to augment or, in alternative, to reopen record Provides add1 explanantion of allegations redesign & design GA deficiencies from transcript of 840125 meeting Certificate of Bvc encl
 REYNOLDS, JR Joint Intervenors Diable Canyon REYNOLDS, JR Center for Law in the Public Interest 84/03/01 Atomic Safety and Licensing Appeal Panel 15pp 22559 182 24% Fiche 50-275.84/03/01, 9403080118
- 3403060179 Order granting applicant 840229 motion for extension of time to 840319 to respond to Joint Intervenors 840222 motion to respen record on const 9A TOMPKING, B A Atomic Safety and Licensing Appeal Panel 84/03/02
- 403070128 Suppl to 840222 motion to reopen record on issues of const GA & licensee character & competence Serious doubts re util competence to manage project raised M/Certificate of Svc REYNOLDS, J R Affiliation Not Assigned REYNOLDS, J R Center for Law in the Public Interest 84/03/02 Atomic Safety and Licensing Board Panel 23pp 22538 231 24X Fiche 50-275,84/03/02,840:037028

- 8403140179 Request for extension of time to 840315 to file response to Joint Intervenor motion to augment or reopen record Certificate of Svc encl RUTSERG, J Hearing Branch 2 84/03/02 Atomic Safety and Licensing Appeal Panel 4pp 22624 100 24X Fiche 50-275,84/03/02,8403140179
- 8403070188 Order requiring governor response to Joint Intervenor 840214 motion to reopen record on issue of design QA by 840308 SHQEMAKER, C. J. Atomic Safety and Licensing Appeal Panel 84/03/06 California, State of 1p 22541 362 24X Fiche 50-275,84/03/06. 8403070188
- B403120006 Answer opposing Joint Intervenors 840214 motion to augment or reopen record on design GA Motion should be denied in entirety Certificate of Svc enc!
 NORTON, B Pacific Gas & Electric Co NORTON, B Norton, Burke,
 Berry & French B4/03/06 Atomic Safety and Licensing Appeal
 Panel 23pp 22936 189 24X Fiche 50-275,84/03/06,8403120006
- --B403120010 Affidavit of FC Breismeister.DJ Curtis,MJ Jacobson,ME Leppke.QH Moore.RO Oman.LE Shipley & HH White re design GA BREISMEISTER.F. CURTIS.D J. JACOBSON,M J Pacific Ges & Electric Co B4/03/05 101pp 22586 331 24X Fiche 50-275,84/03/06,
- --BA03120012 Affidavit of M Tresler,R Oman & M Leppke re history of onsite angineering small bore piping program description TREBLER,M , DMAN.R , LEPPKE,M Pacific Gas & Electric Co B4/03/05 5Bpp 22587 070 24% Fiche: 50-275
- --B403120015 Affidavit of LB Mangoba re design verification & const of small bore pipe support sys
 MANGOBA.L B Bechtal Corp B4/03/04 5pp 22587 128, 24X
 Fiche.50-275,84/03/06.8403120006
- ---B403120017 Affidavit of A Shusterman re design QA & coverup of hanger recalculation SHUBTERMAN.A Bechtel Corp 84/03/04 4pp 22587 134 24X Fiche 50-275,84/03/06,8403120006
- --B403120018 Affidavit of RD Etzler re design QA & QC inspector qualifications
 ETZLER, R D Pacific Qas & Electric Co B4/03/06 4pp
 22587 138 24X Fiche 50-275,84/03/06,8403120006
- --8403120022 Affidavit of HB Friend re design GA & util/Bechtel contract FRIEND.H B Pacific Gas & Electric Co 84/03/05 2pp 22587 142 24X Fiche 50-275,84/03/06.8403120006
- --B403120023 Affidavit of DJ Curtis re design GA & small bore pipe support group drawing CURTIS.D J Bechtel Corp B4/03/05 2pp 22587 144 24X Fichs 50-275, 84/03/06, 8403120006
- --B403120029 Affidavit of JD Bhiffer.R Patterson.JM Gisclon.KC Doss. JB Hoch.RC Thornberry.RD Ettler.RK Rhodes & EM Burns re J Cooper B40:123 affidavit & Joint Intervenor B40214 motion on design GA SHIFFER.J D., PATTERSON.R., GILBCLON.J M. Pacific Qas & Electric Ca 84/03/05 234pp 225B7 146 24X Fiche 50-275,84/03/06, 8403120006
- E403130010 Summarises fears that Commission will discard terms of 1981 order & will surrender normal requirements of Atomic Energy Act by permitting facility to go critical in quality indeterminate state CLEWETT, J Covernment Accountability Project DEVINE.T., CLEWETT, J San Luis Ubispo Mothers for Peace 84/03/13 PALLADINO, N J, OILINGKY, V. ROBERTS.T Commissioners 22642, 326 24X Fiche 50-275, 84/03/13, 8403150010
- 8403160014 Order extending time until 840413 for Commission to act to review ALAB-756
 CHILK.S J Office of the Secretary of the Commission 84/03/13
 Commissioners ip 22652 362 24% Fiche 50-275,84/03/13.
 8403160014
- B403190011 Motion for leave to file reply to util answer in opposition to motion to reppen record Certificats of Svc encl REYNOLDS, J. R. Joint Intervenors Diablo Canyon REYNOLDS, J. R. Center for Law in the Public Interest 84/03/19 Atomic Safety and Licensing Appeal Panel 5pp 22665 273 24X Fiche 50-275.84/03/15.8403190011

- --8403190016 Reply to util answer in opposition to 840≥14 motion to augment or, in alternative, to reopen record Contentions in opposition cannot withstend scruting Certificate of Svc
 - REYNOLDS, J. R. Joint Intervenors Diablo Canyon REYNOLDS, J. R. Center for Law in the Public Interest 84/03/15 Atomic Safety and Licensing Appeal Panel 26pp 22665 278 24X Fiche 30-275,84/03/15,8403190011
- --8403170021 Statement of C Stokes rebutting util defenses of seismic design review
 STOKEB, C Joint Intervenors Diablo Canyon 84/03/14 26pp 22665 307 24X Fichs 30-275,84/03/15,8403170011
- 8403190100 Answer opposing Joint Intervenor 840214 motion to augment or, in alternative to reopen record on design GA issues Motion failed to justify either augmentation or reopening record Certificate of Svc encl
 RUTBERG. J. CHANDLER, L. J. Hearing Branch 2 MCGURREN, H. J. Hearing Branch 1 84/03/15 Atomic Safety and Licensing Appeal Panel
 ROPP 22667 215 24X Fiche 50-275.84/03/15.8403190100
- ~-8403170102 Affidavit of JP Knight re Joint Intervenors motion to augment or, in alternative, to reopen record KNIGHT, J P Division of Engineering 84/03/15 Atomic Safety and Licensing Appeal Panel 16pp 22667 244 24X Fiche 50~275,84/03/15,8403170100
- --8403190106 Affidavit of M Hartzman re Joint Intervenors motion to augment or, in alternative, to reopen record HARTZMAN, M Division of Engineering 84/03/15 22pp 22667 260 24% Fiche 30-275,84/03/15,8403190100
- --8403170110 Affidavit of SD Reynolds re Joint Intervenors 840214 motion to augment or, in alternative, to reopen record REYNOLDS, SD Region 1, Office of Director 84/03/15 Spp 22667 282 24X Fiche 50-275,84/03/15.8403190100
- --8403190114 Affidavit of TW Bishop re Joint Intervenors 840214 motion to augment or, in alternative, to reopen record BIBHOP, TW Region 5, Office of Director 84/03/08 4pp 22667 290 24X Fiche 50-275,84/03/15,8403190100
- --B403i901i6 Affidavit of JR Pair re Joint Intervenors 840214 motion to augment or, in alternative, to reopen record FAIR: J R Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/08 6pp 22667.294 24X Fiche 50-275,84/03/15.8403190100
- --8403190119 Affidavit of CY Liang re deficiencies in RHR sys design LIANG.C Y Division of Systems Integration (post 811005) 84/03/15 30pp 22667 300 24X Fiche 50-275.84/03/15.8403190100
- --8403190122 Affidavit of F Rosa re RHR sys ROBA,F Division of Systems Integration (post 811005) 84/03/15 17pp. 22667 330 24X Fiche 50-275,84/03/15,8403190100
- --B403190126 Affidavit of JL Crews re Joint Intervenors 840214 motion to augment or, in alternative, to reopen record GREWB. J L. Region 5. Office of Director 84/03/14 5pp 22667 347 24X Fiche 50-275,84/03/15.8403190100
- ---B403170130 Supplemental affidavit of JL Crews on add1 info re Joint Intervenors motion on GA deficiencies CREWS, JL Region 5, Office of Director 84/03/15 ip 2267.352 24X Fiche, 30-275, 84/03/15, 8403170100
- --8403190134 Affidavit of H Schierling re Joint Intervenors 840214 motion to augment or in alternative to reopen record Unexecuted affidavit of PJ Morrill encl SCHIERLING H Licensing Branch 3 84/03/15, 3pp 22667 353 24X Fiche 50-275,84/03/15,8403190100
- 8403210033 Request for extension of time until 840403 to file response to Joint Intervenors motion to reopen record on const GA Cartificate of Svc encl CHANDLER, L J Hearing Branch 2 84/03/16 Atomic Safety and Licensing Appeal Panel 4pp 22704, 330 24X Fiche 50~275, 84/03/16, 8403210033
- 8403210114 Forwards PJ Morrill signed & corrected affidavit as addendum to NRC 840315 response to Joint Intervenors motion to augment or respondence of Related correspondence CHANDLER.L J Hearing Branch 2 84/03/16 MODRE.T. 8 BUCK, J H Atomic Safety and Licensing Appeal Panel JOHNSON, W R Atomic Bafety and Licensing Board Panel. 2pp 22707 126 24X Fiche 50-275,84/03/16.8403210114

- --B403210119 Affidavit of PJ Morrill as addendum to NRC 840315 response to Joint Intervenors motion to augment or reopen design GA record Prof qualifications of JP Knight also encl MORRILL.P J Division of Resident Reactor Project & Engineering Programs 84/03/13 Atomic Safety and Licensing Board Panel 10pp 22707 128 24X Fiche 50-275.84/03/16.8403210114
- 8403200133 Discusses dispute between plant workers & util re slander suit Identification of relevant issues establishing accountability for inaccurate util statements & fixing hardware from 64 breakdown not yet possible DEVINE, T Government Accountability Project DEVINE, T San Luis Obispo Mothers for Peace 84/03/19 PALLADINO, N J , GILINSKY, V , ROBERTS. T Commissioners 20pp 22699 047 24x Ficha 50-275,84/03/19,8403200133
- B403210159 Decision ALAB-763 affirming LBP-82-70 granting authorization to operate facility.w/listed conditions SHUBMAKER.C J Atomic Safety and Licensing Appeal Panel DSB 021 B4/03/20 122pp 22710 144 24% Fiche 50-275.84/03/20.8403210159
- 8403220106 Forwards renewal of application for stay to permit completion of administrative review & opportunity for court review of Joint Intervenors emergency motion REYNOLDS, J R Center for Law in the Public Interest Joint Intervenors Diablo Canyon DSB 044 84/03/20 PALLADINO, N. GLINBKY, V. ROBERTS. T Commissioners 2pp 22715 304 24X Fiche 50-275,84/03/20,8403220106
- --8403220110 Renewal of application for stay to permit review of Joint Intervenors emergency motion Unexecuted affidavit of M Kaku & Certificate of Svc encl REYNOLDS.J R Joint Intervenors Diablo Canyon REYNOLDS.J R Center for Law in the Public Interest 84/03/20 Atomic Safety and Licensing Appeal Panel 25pp 22715 304 24x Fiche 50-275.84/03/20.8403220106
- 8403270063 Informs that plant scheduled to be ready for initial criticality on 840329 & for operation above 5% rated power on 840427 CRANE.P A Pacific Gas & Electric Co DSB 113 84/03/21 MOORE.T S Atomic Safety and Licensing Appeal Panel 1p 22766 103 24% Fiche 50-275.84/03/21.8403270063
- 8403270278 Comments on request for meeting to discuss issues raised by C Stokes on submission by util & staff re design GA Related correspondence CHANDLER, L J Hearing Branch 2 DSB 137 84/03/21 DEVINE, T Government Accountability Project 2pp. 22787 035 24X Fiche 50-275,84/03/21,8403270298
- 8403230191 Forwards Nekton, Inc paper, "Post-Miocene Compressional Tectonics Along Central State of CA Margin " Conclusion of paper will reviewed SCHUYLER, J O Pacific Gas & Electric Co DBB 074 84/03/22 PALLADINO, N J , ABSELBTINE, J K , BERNTHAL, F M Commissioners 20pp 22743, 072 24x Fiche 50-275, 84/03/22, 8403230191
- 8403260007 Order ruling on 840320 renewal of application for stay Commission currently considering lifting OL suspension Guestion of stay already before Commission Served on 840323 SHDEMAKER, C. J. Atomic Bafety and Licensing Appeal Panel DSB 08184/03/22 Joint Intervenors Diablo Canyon Spp 22747 358 24X Fiche 50-275.84/03/22.8403260007
- 8403260368 Forwards executed signature page for affidavit of M Kaku submitted as attachment to Joint Intervenors 840320 renewal of application for stay REYNOLDS.J R Center for Law in the Public Interest REYNOLDS.J R Joint Intervenors Diablo Canyon DSB 100 84/03/22 PALLADINO,N CILINSKY,V ROBERTS.T Commissioners 2pp 22760 133 24X Fiche 50-275,84/03/22,8403260368
- ---8403260369 Executed signature page of affidavit of M Kaku in support of 840320 renewal of application for stay KAKU.M Joint Intervenors Diablo Canyon 84/03/21 ip 22760 135 24X Fiche 50-275.84/03/22.8403260368
- 8403270004 Discusses State of CA emergency response plan Plan incorporated into Diablo Canyon plan Addl planning will not be performed for Humboldt Bay per 1980 legislation Related correspondence
 8CHUYLER, J O Pacific Gas & Electric Co DBB 117 84/03/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 1, 22769, 349 24X Fiche 50-000, 84/03/22, 8403270004
- 84032á0005 Requests that low power test license not be granted Discussion before licensing vote requested LEVY,B , SHARPE, C Affiliation Not Assigned DSB 079 84/03/23 PALLADING,N , ASSELSTINE,J K , BERNIHAL,F J Commissioners ip 22747 356 24X Fiche 50-275,84/03/23,8403260005

- B4032A0364 Forwards 12 add1 affidavits in support of B40301 patition to defer any futher licensing decisions until completion of comprehensive reinsp, mgt audit & audit of design verification M/o enc!

 DEVINE, T, CLEWETT, J Opvernment Accountability Project DEVINE, T San Luis Dispo Mothers for Peace DSB 101 B4/03/23 PALLADING, N J, OILINSMY, V, ROBERTS, T Commissioners 9pp 22760 065 24% Fiche 50-275,84/03/23,8403260364
- 8403270006 Informs that 12 add1 affidavits in support of Mothers for Peace 840301 petition to defer licensing submitted to Region V Related correspondence
 # Government Accountability Project DSB 115 84/03/23 PALLADING, N J Commissioners Ip 22770 007 24X Fiche 50-275.84/03/23,8403270005
- 8400270347 Telecopy itr expressing view that no low power license should be granted until all safety questions & allegations resolved G'CONNELL J California State of DSB 142 84/03/23 PALLADINO, N Commissioners ip 22789 005 24x Fiche 30-275.84/03/23,8403270347
- 8403270352 Telecopy ltr urging assurance that alleged safety hazards checked & thoroughly evaluated before granting license BRONZAN:B California, State of DSB 140 B4/03/23 PALLADIND,N Commissioners 1g 227B9 004 24X Fiche 50-275,84/03/23,8403270392
- 8403260375 Requests opportunity to discuss OL issuance Commission should not vote on low power testing LEVY, B. SHARRE, C. Affiliation Not Assigned DSB 093 84/03/26 PALLADING, N. OFLINSKY, V. ROBERTS, T. M. Commissioners ip 22760.138 24% Fiche 50-275,84/03/26,8403260375
- 8403260376 Requests that Commission not vote & authorization to operate not be given to facility LEVY.D. SHARRE, C. Affiliation Not Assigned DSB 092 84/03/26 ASSELSTINE, J. B. BERNTHALF J. Commissioners 1p 22760 136 24X Fiche 50-275,84/03/26,8403260378

H Ceneral correspondence

- 8403010525 Responds to 840112 request that NRC deny POLE any type of OLfor plant Validity of allegations re design & const being evaluated Commission will not recommend that ldw power license be fully reinstated until evaluation complete DENTON, HR Qffice of Nuclear Reactor Regulation, Director 64/02/15 KNUTSON, JA Affiliation Not Assigned 3pp 22443 282 24X Fiche 50-275, 84/02/15, 8403010525
- --B403010832 Expresses concern that plant poses grave danger to environ & public health of State of CA & urges NRC to deny util any type of OL due to continuing design flaws KNUTSON, JA Affiliation Not Assigned B4/01/12, DIRCKB, W NRC No Detailed Affiliation Given ip 22443 288 24% Fiche 50-275,84/02/15,8403010525

I Financial information

- 8403280051 Annual Financial Rept 1983 W/840326 ltr MIELKE,F W . SHACKELFORD.B . CRANE.P A Pacific Gas & Electric Co 83/12/31 50gp 22776 230 24X Fiche 50~000.83/12/31,8403280051
- J Insurance & indemnity information
- 8403280033 Forwards Endorsement 40 to NELIA Policy NF-228. CRANE.P A Pacific Qas & Electric Co 84/03/21 BALTZMAN.J D Assistant Director for State & Licensee Relations 2pp 22777 044 24X Fiche 50-275.64/03/21,8403260033
- O Advisory Committee on Reactor Bafeguards reports & correspondence
- 8403280307 Summary of ACRS Subcommittee on Extreme External Phenomena 831012 meeting u/util. Westinghouse. TERA & Univ of Illinois in Washington, DC re use of tan effect methodology in seismic design analysis at Diablo Canyon Agenda encl 4 ACRS Advisory Committee on Reactor Safeguards 83/11/25 ACRS Advisory Committee on Reactor Safeguards 16pp 22808 040 24X Fiche 50-275.83/11/25,8400280307
- B4032903B1 Notice of ACRS B40405-07 meetings in Washington, DC Agenda encl CHILK, S. J. Office of the Secretary of the Commission DSB 178 B4/03/RB 6pp 22814 081 24X Fiche 50-275,84/03/28,84032903B1

- P Operating license stage documents & correspondence
- 8403090027 FDIA request for records re 1977 Nuclear Svcs Corp audit of Pullman Power Products REYNDLDS, J. Center for Law in the Public Interest 84/01/20 Office of Administration 2pp 22592 329 24X Fiche 50-275,84/01/20
- 8403010501 Forwards Board Notification 84-022 which provides in camera transcript of NRC 840125 meeting w/recipient & C Stokes Requests specific identification of names & sections in rept to be withheld from public disclosure. W/o encl EISENHUT. D G Division of Licensing 84/02/14 DEVINE, T Government Accountability Project ip 22438 335 24X Fiche 50-275,84/02/14.8403010501
- 8402090004 Board Notification B4-037 forwards Chairman Palladino 840109 ltr transmitting rept on matters re GA Case Study C for plant Rept encis compare draft & final version of case study & include comments on draft version EISEMHUT.D C Division of Licenting 84/02/24 BUCK, J H, MODRE, T S , JOHNBTON, M R Atomic 88fety and Licensing Appeal Panel 3pp 22549 036 24X Fichs 50-275,84/02/24,8402090004
- 9402090017 Board Notification 84-038 forwards RJ Mattson 840123 memo to DG Eisenhut providing status update of NRC actions re Hestinghouse ECGS actuation logic EISENHUT, D G Division of Licensing 84/02/27 PALLADINO, OILINBWY, ROBERTS Commissioners 79p 22546-007 24X Ficha 50-000,84/02/27.8402090017
- --B40201080B Provides updated status of rev to Westinghouse designed PHR ECCS actuation logic Westinghouse plans completion of evaluation for submittal by mid-Mar 1984 MATTBON,R J Division of Bystems Integration (post 81005) 84/01/23 EISENHUT,D Division of Licensing 2pp 22546.007 24X Fiche 50-000,84/02/27,8402090017.
- B403150165 Requests add1 info explicitly addressing specific steps in 36CFR800 4(b),(c),or (d) re determination of effect of operation be maint activities on SLO-2 archaeological site KNIGHTUN, & W. Licensing Branch 3 B4/02/27 BCHUYLER, J. D. Pacific Gas & Electric Co. 4pp. 22646 345 24X Fiche 50-275,84/02/27, H403150165
- 8403070075 Forwards application to amend License DPR-76, changing Tech Boecs re testing requirements for HEPA filters & charcoel adsorbers, per Generic Ltr 83-13 BCRUYLER, J G Pacific Qas & Electric Co 84/02/29 DENTON, H R Office of Nuclear Reactor Regulation, Director ip 22341 220 24X Fiche 50-275,84/02/29.8403070075
- --8403070079 Application to amend License DPR~76, changing Tech Specs re testing requirements for HEPA filters & charcoal adsorbers, per Generic Ltr 83~13 Justification encl. SCHUYLER, J D Pacific Gas & Electric Co 84/02/29 App 22541 221 24X Fiche 50~275,84/02/29,8403070075
- --B403070083 Proposed Tech Specs re testing requirements for HEPA filters & charcoal adsorbers.per Generic Ltr B3-13
 * Pacific Gas & Electric Co 84/02/29 10pp 22541 225 24X
 Fichs 50-275.84/02/29.8403070075
- 8403070284 Forwards application to amend License DPR-76, consisting of Amend Request 84-02, changing Tech Specs to allow entry into Mode 3 for required surveillance testing of pressurizer code safety valves
 SCHUVLER, J O Pacific Gas & Electric Co 84/02/29 DENTON, H R, Office of Nuclear Reactor Regulation, Director ip 22547.071 24X Fiche 80-275, 84/02/29, 8403070284
- ---8403070288 Application to amend License DPR-76, consisting of Amend Request 84-02, revising Tech Specs to allow entry into Mode 3 for required surveillance testing of pressurizer code safety valves SCHUYLER, J. D. Pacific (TW) & Electric Co. 84/02/29, 2pp 22347 072 24X Fiche 50-275,84/02/29,8403070284
- ---8403070292 Proposed Tech Specs re surveillance testing of pressurizer code safety valves,

 + Pacific Cos & Electric Co 84/02/29 ip 22547 074. 24X Fiche 50-275,84/02/29,8403070284
- B4030B0413 Forwards License Amend Request B4-04 to License DPR-76, changing Tech Specs to update frequency of auxiliary feedwater pump surveillance to latest ABME std value.

 BCHUYLER.J.O. Pacific Oas & Electric Co. 84/02/29 DENTON, H.R. Dffice of Nuclear Reactor Regulation. Director 1p. 22556-242 24X Fiche 50-275,84/02/29,8403080413

- --8403080414 License Amend Request 84~04 to License DPR-76.changing Tech Spec Section 4 7 1 2 to base auxiliary feedwater pump surveillance on Tech Spec 4 0 5 8CHUYLER.J D Pacific Gas & Electric Co 84/02/29 ip 22556 243 24X Fiche 50-275.84/02/29.8403080413

Fiche 50-275, 84/02/29, 8403080413

- --8403080415 Proposed Tech Specs re auxiliary feedwater sys surveillance requirements
 * Pacific Gas & Electric Co 84/02/29 3pp 22554 244 24x
- 8403070028 Partial response to FOIA request for records re 1977 Nuclear Svcs Corp audit of Pullman Power Products Documents entirely withheld (ref FOIA Exemption 5) Review of remaining documents subj to request in progress FELTON.J M Division of Rules and Records 84/03/01 REYNOLDS, J Center for Law in the Public Interest 2pp 22592 331 24X Fiche 50-275,84/03/01,8403090028
- 8403080405 Further response to FOIA request for documents re BER related to operation of facilities Forwards App B documents App A & B documents available in PDR Review of remaining documents subj. to request in progress
 FELTON, J M Division of Rules and Records 84/03/02 QARDE, B P Government Accountability Project 4pp 22583 073 24X
 Fiche 50-275.84/03/02,8403080405
- --8312230254 Forwards responses to Allegations 7,9 & 48,per 831130 SPEIB.T P Division of Safety Technology 83/12/07 KNIGHTON, G Office of Nuclear Reactor Regulation, Director 12pp 22583 iii 24X Fiche 50-275,84/03/02,8403080405
- --8403080422 Forwards input on Allegations 51 & 52 Fuel loading addressed in 831108 Memorandum & Order CLI-83-27 No significant safety concerns mati to fuel loading & precriticality testing warrent continuation or suspension of activities BURNS: 8 Office of the Executive Legal Director 83/12/07 KNIGHTON:0 Office of Vuclear Reactor Regulation, Director 3pp 22583.108 24X Fichs 50-275,84/03/02.8403080405
- --8403080426 Forwards safety evaluations for Allegations 8.10, 11, 14, 15, 16, 17, 27, 28, 29, 31, 32, 33, 35, 36, 55, 85 & 86 Licensee approach for determining containment stability against tilting Acceptable
 VOLLMER,R H Division of Engineering 83/12/09 EISENHUT,D 0 Division of Licensing 31pp 2: Fiche 50-275, 84/03/02, 8403080405
- 8403220096 Forwards San Luis Obispo Mothers for Peace 840202 10CFR2 206 petition requesting Commission defer decision re reinstatement of low power license Written response addressing issues requested by 840327 W/o encl DENTON.H R Office of Nuclear Reactor Regulation, Director 84/03/02 SCHUYLER, J D Pacific Gas & Electric Co 3pp 22723 298 24X Fiche 50-275,84/03/02,8403220096
- 8403150011 Forwards summary of mods, repairs or equipment changes resulting from review of allegations performed since Sept 1983, per 830304 request SCHUYLER, J O Pacific Oas & Electric Co 84/03/06 MARTIN, J B Region 5. Office of Director 2pp 22641 247 24% Fiche. 50-275, 84/03/06, 8403150011
- B403120129 Forwards policy directive for protection & retention of records re design, const & operation activities for facility folicy supersedes instructions contained in 840215 ltr BCHUYLER, J O Pacific Gas & Electric Co 84/03/08 EISENHUT, D G Office of Nuclear Reactor Regulation, Director 2pp 22590 OB7 24X Fiche 50-275,84/03/08,8403120129
- B403200218 Forwards Rev 2 to Procedure EP OP-17, "Malfunction of RHR Sys," requested by ACRS Subcommittee on Diablo Canyon during B40210 meeting SCHUYLER, J. O Pacific Oas & Electric Co B4/03/12 KNIGHTON, G W Licensing Branch 3. 1p 22699 337. 24X Fichs 30-275, B4/03/12, B403200218
- --8403200220 Rev 2 to Procedure EP OP-17, "Melfunction of RHR Sys * Pacific Gas & Electric Co 82/02/19, 3pp 22699,338 2/ * Pacific Gas & Electric Co 82 Fiche 50-275,84/03/12,8403200218.
- 8402070041 Board Notification 84-050 provides Commission policy statement & proposed rulemaking on environ qualifications. EIBENHUT.D 9 Division of Licensing 84/03/14 Atomic Safety and Licensing Board Panel. 10pp 24X Fiche 50-000,84/03/14,8402070041
- 8403220035 Forwards tables providing detailed operating experience for licensed operating personnel & licensed & nonlicensed shift technical advisors SCHUYLER.J O Pacific Gas & Electric Co 84/03/16 DENTON,H R Office of Nuclear Reactor Regulation, Director 5pp 22718 208 24X Fiche: 50-275,84/03/16,8403220035

- 8403270053 Forwards corrected page to proposed Tech Spec Page 3/4 7-17 from 840229 License Amend Request 84-03 re testing requirements for HEPA filters & charcoal absorbers SCHUYLER.J O Pacific Gas & Electric Co 84/03/21 DENTON.H R Office of Nuclear Reactor Regulation, Director 1p 22769 312 24) Fiche 50-275.84/03/21.8403270053
- -8403270057 Corrected Page 3/4 7-17 to proposed Tech Specs revising & clarifying testing requirements for HEPA filters & charcoal absorbers
 # Pacific Gas & Electric Co 84/03/21 1p 22769 313 24% Fiche 50-275, 84/03/21, 8403270053
- 8403260176 Informs of plans to have shift advisors w/qualifications & training recommended by Near-Torm OL Util Group on staff prior to exceeding 5% power Advisors will be subj to final exam following training SCHUYLER-J O Pacific Cas & Electric Co 84/03/23 KNIOHTON.C W Licensing Branch 3 lp 22758 234 24% Fiche 50-275, 84/03/23, 8403260176
- B403270366 Requests that license not be granted until allegations by employees of plant resolved HAYDEN, T California. State of 84/03/23 PALLADIND, N Commissioners Ip 22789 001 24X Fiche 50-275,84/03/23,8403270366
- G Inspection reports, IE Bulletins & correspondence
- B40304013B Forwards IE Insp Repts 50-275/B3-39 & 50-323/B3-27 on B31205-22 & notice of violation BISHDP. TW Division of Resident, Reactor Project & Engineering Programs B4702703 SCHUYLER, J O Pacific Cas & Electric Co 2pp 22506 334 24X Fiche 50-275.84/02/03.8403060138
- ~~8403040142 Notice of violation from insp on 831209-22 CANTER:H L Region 5, Dffice of Director 84/02/03 22506 336 24X Fiche 50-275,84/02/03,8403060138
- --8403060146 IE Insp Repts 50-275/83-37 & 50-323/83-27 on 831205-22 Noncompliance noted failure to properly implement fire loss prevention procedures & suppls SCOUNTY, POLICH, T, CANTER, HL. Region 5. Office of Director 84/01/24 18pp 22504 338 24X Fiche 50-275.84/02/03.8403040138
- 8403060207 Forwards IE Insp Repts 50-275/84-01 & 50-323/84-01 on B40103-06 & notice of violation
 BISHOP.T W Division of Resident Reactor Project & Engineering
 Programs 84/02/17 SCHUYLER.J O Pacific Gas & Electric Co
 22517 145 24% Fiche 50-275.84/02/17.8403060207
- -8403060214 Notice of violation from insp on 840103-06 KIRBGH,D F Region 5, Office of Director 84/02/17 22517 147 24X Fiche 50-275,84/02/17,8403060R07 64/02/17 2pp
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list URDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22709 239 24% Fiche 50~000,84/02/28,8401170072
- 8403040131 Forwards IE Insp Repts 50-275/83-37 & 50-323/83-25 on HUSDONIST FORWARDS IE INSP REPTS DO-229/83-37 & DU-323/83-25 on B3114-18 & 1128-1209

 BIGHOP.T W Division of Resident. Reactor Project & Engineering Programs 84/02/27 BCHUYLER.J D Pacific Oas & Electric Co 22506: 273 24% Fiche 50-275.84/02/27, 8403060131
- --8403060143 Natice of violation from insp on 831114-18 % 1128-1209 GANTER.H L Region 5, Office of Director 84/02/29 2pp 2206 275 24% Fiche 50-275.84/02/29,8403060131
- --8403060149 IE Insp Repts 50-275/83-37 & 50-323/83-25 on 831114-18 & 1128-1209 Noncompliance noted failure to assure that welding inspectors qualified & cartified per procedural Inspectors qualified & certified per procedural requirements
 HERNANDEZ,G H , ROSS,T M , KIRSCH,D F Region 5, Office of Director B4/02/29 49pp 22506 277 24X Fiche 50-275,84/02/29,8403060131
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " 8vc list encl ORACE, J N Division of OA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 82552 329 24% Fiche 50-000,84/03/02,8402090007
- B40209000B IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl, JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post B30103) B4/03/02 Consolidated Edison Co of New York, Inc 122pp 2255 098 24X Fiche 50-000,84/03/02,8402090008

- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases
 - 1020940094 to Airco notice | Proposed National State | Division of Emergency Proparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 119pp 22553 217 24% Fiche 50-000,84/03/02,8402090009
- 8402070011 IE Info Notice 84-17. "Problems W/Liquid Nitrogen Coaling Components Below Nil Ductility Temp "Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05.8402090011
- B402090022 Board Notification B4-043 submits info re exams & measurements by Parameter. Inc of radiographs & field welds & delta ferrite measurements of selected wolds under Contract NRC-03-B2-249
 EISENHUT. D. G. Division of Licensing NRC-05-82-249 B4/03/6
 PALLADING, GILINSKY, ROBERTS Commissioners 3pp 22556 247 Fiche 50-275,84/03/05,8402090022
- --8403080193 Forwards "Project Quality Plan for Providing Assistance & Svcs to Support NRC/IE Region IV Personnel in NDE & Review of Radiographs." per Task Order \$4 of Contract NRC-05-82-249 LOFY, R A Parameter, Inc NRC-05-82-249 83/11/23 XIR8CH, D Region 5. Office of Director 1g 22556 250 24X Fiche 50-275, 84/03/05.8402090022
- ~-B403080197 "Project Guality Plan for Providing Assistance & Svcs to Support NRC/1E Region IV Personnel in NDE & Review of Radiographs at Diablo Camyon, Units 1 & 2 " FOLEY, H J , LOFY, R A Parameter, Inc NRC-05-82-249, PQP-124 83/11/22 NRC No Detailed Affiliation Given 25pp 22556 251 24X Fiche 50-275,84/03/05,84020900022
- 8403150082 Responds to NRC 840203 ltr re violations noted in IE Insp Rept 50-275/83-39 Corrective actions area permits for welding posted to identify generic requirements on area basis & util inspector assigned to assist fire marshall SCHUYLER, J O Pacific Gas & Electric Cq 84/03/05 M. Region 5. Office of Director 6pp 22646 013 24X Fiche 90-275,84/03/05 8403150082 MARTIN J B
- B403130006 Forwards description of program implemented to verify clearance between piping & penetrations in response to IE Bulletin 79-14

 SCHUYLER.JP Pacific Gas & Electric Cn 84/03/Q6 MARTIN.J B Region 5. Office of Director 39 28640 324 24X Fiche 50-275.84/03/06.8403150006
- 8402090024 IE Info Notice 84-09, Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JERDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22635 049 24X Fiche 30-000,84/03/07,8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR 102090028 IE Info Motice on
 Sys " Syz list enc!
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/07 Consolidated Edison Co of New
 York, Inc. 118pp 22584 186 24x Fiche 50-000,84/03/07,8402090028
- 8402070031 IE Bulletin 84-02. "Failures of GE Type HFA Relays in Use in Class IE Bafety Sys " Byo list end!
 DEYDUNG: R C Director's Office. Office of Inspection and Enforcement B4/03/12 Consolidated Edison Co of New York. Inc 134pp 22823 094 24% Fiche 50-000.84/03/12,8402090031
- 8402090043 IE Info Notice 84-19. "Two Events Involving Unauthorized Entries into PMR Reactor Cavities" Svc list end!

 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 123pp 22823 229 24% Fiche 50-000.84/03/21,8402090043
- 9402070044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys "Svc list encl
 JDRDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/21 Consolidated Edison Co of New
 York, Inc 135pp 22733 001 24X Fiche 50-000.84/03/21.8402070044
- 8403140244 Board Notification 84-066 forwards SECY-84-104 re NRC insp of Nuclear Sycs Corp audit of Pullman Power Products at site including draft IE Insp Rept 50-275/83-37 & 840229 site.including u.g.,
 final Tept
 EISENHUT, D C Division of Licensing 84/03/28 BUCK, J H ,
 MOGRE, T S , JOHNSON, W R Atomic Safety and Licensing Appeal Panel
 Spp 22947 070 24X Piche 50-275.84/03/28.8403140244

- -8403200301 Provides info to Commissioners re circumstances surrounding documentation of NRC insp of 1977 Nuclear Svcs Corp audit of Pullman Power Products Co
 DIRCKS.W J Office of the Executive Director for Operations
 B4/03/02 124pp 22747 073 24X Fiche 30-275,84/03/28.
- R Periodic operating reports & related correspondence
- 8403020004 Monthly operating rept for Jan 1784 W/840203 ltm KELLY,W J., THORNBERRY,R C Pacific Gas & Electric Co 5pp 22442 196 24x Ficha 50-275,84/01/31,8403020004
- 8403020443 Forwards monthly status rept of offsite emergency preparedness for OL reviews for Jan 1984 Changes in FEMA finding dates not caused by delay due to offsite emergency planning dissues
 DIRKIS W J Office of the Executive Director for Operations
 84/02/21 PALLADING Commissioners 9pp 22492 083 24X
 Fichs 50-000.84/02/21,8403020443
- B403230139 Forwards "Environ Investigations at Diablo Canyon, 1782 " WARRICK,J W Pacific Gas & Electric Co 84/02/20 Record Services Branch (Document Control Desk) 1p 22732 341, 24X Fiche 50-275.84/02/28,8403230139
- -8403230141 "Environ Investigations at Diablo Canyon,1782 " CAYOT,R F , BEHRENS,D W Pacific Gas & Electric Co 83. 760pp 22732 342 24X Fiche 50~275,84/02/28,8403230139 83/04/30
- 8403300141 Monthly operating rept for Feb 1984 W/840302 ltr KELLY, W J . THORNBERRY, R C Pacific Gas & Electric Co 84/02/29 6pp 22820 352 24X Fiche 50-275,84/02/29,8403300141
- S Reportable occurrences, LERs & related correspondence
- 8403150025 Special Rept 84-02 on 840123, fire water pump 1 declared inoperable after pump motor circuit breaker tripped Caused by frequent motor starts in short time period Surveillance test conducted & pump returned to svc SHIFFER.J D Pacific Gas & Electric Co 84/02/29 MARTIN.J B Region 5. Office of Director 1p 22639 029 24x Fiche 50-275,84/02/29.8403150025
- 8403080405 Further response to FDIA request for documents of SER related to operation of facilities Forwards App B documents App A & B documents available in FDR Review of remaining documents subj to request in progress FELTON.J M Division of Rules and Records 84/03/02 OARDE, B P. Government Accountability Project App 22583 073 24X Fiche 50-275.84/03/02.8403080405
- --B403080421 Requests assistance in addressing improper design activities re use of U-bolts & code break (code boundary) design, per affidavit re allegations
 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 83/11/27 EISENHUT, D G Division of Licensing 15pp 22583 093 24X fiche 50-275,84/03/02,8403080405
- 8403150121 PNG-V-84~013 on 840307 Bechtel laborer suffered heart KO3150121 PNO-V-84-013 on 840307. Bechtel laborer suffered heart attack while working in auxiliary blig Medical attention provided to individual at site Individual pronounced dead upon arrival at Sierra Vista Hosp DDDS9. T Region 5. Office of Director 84/03/07 ip 22640 218 24X Fiche 50-275,84/03/07,8403150121
- 8403220066 LER 84-006-00 on 840217, four 4 16 kV circuit breakers failed to remain closed Caused by excessive wear in Teflon coated fiberglass sleeve bearings used in mechanical actuator Breakers repaired W/640317 ltr
 KESBINGER.W H , SHIFFER, J D Pacific Gas & Electric Co 84/03/19, 3pp 22714 358 24X Fiche 50-275, 84/03/19, 8403220066
- T Hearing transcripts on non-antitrust matters
- 8402090032 Board Notification 84-048 forwards transcript of 840123 NOUTHOUSE BOORD NOTIFICATION BA-048 forwards transcript of 840 meeting re allegations concerning small bore piping Review & evaluation of allegations continuing EISENHUT, D 9 Division of Licensing 84/03/13 PALLADINO, GILINSKY, ROBERTS Commissioners 3pp 67217 046 24X Fiche 50-275,84/03/13,8402090032
- --8403150136 Forwards transcript of 840125 meeting re allegations concerning small bore piping Info excised to protect confidentiality of NRC sources & preclude compromising BISHOP, T W Region 5, Office of Director BTRUMMASSER, M California, State of 1p B4/02/23 STRUMWASSER, M Callfornia, State of Fiche 50-275,84/03/13,8402090032

- --8403150144 Forwards transcript of 840125 meeting re allegations concerning small bore piping Info excised to protect confidentiality of NRC sources & preclude compromising angoing insps
 BIBHOP.T W Region 5, Office of Director 84/02/23 REYNOLDS.J Center for Law in the Public Interest ip 22645 005 24X Fichs 50-275,84/03/13,8402070032
- --8403150152 Forwards transcript of 840125 meeting re allegations concerning small bore piping Info excised to protect confidentiality of NRC sources & preclude compromising ongoing insps
 BIBHOP.T W Region 5. Office of Director 84/02/23 CRANE.P A Pacific Gas & Electric Co 1p 22645 006 24X
 Fiche 50-275.84/03/13.84020970032
- --8403150159 Forwards transcript of 840125 meeting re allegations concerning small bore piping Info excised to protect confidentiality of NRC sources & preclude compromising ongoing insps
 BIGHOP.T W Region 5, Defice of Director 84/02/23 NORTON Norton, Burke, Berry & French 1p 22645 Q07 24X
 Fichs 50-275,84/03/13,8402090032
- --8403150162 Excised transcript of 840125 closed meeting w/C Stokes re allegations concerning small bore piping Pp 1-220 * NRC - No Datailed Affiliation Given 84/01/25 319pp 22445 008 24X Fiche 50-275.84/03/13.8402090032
- U Congressional/Executive Correspondence
- 8403260106 Provides current status of facility licensing process in response to 840126 ltr Since 840124 hearings.NRC has continued investigation.insp & evaluation of allegations, which will be resolved prior to low power authorization DENTON.H R Office of Nuclear Reactor Regulation, Director 84/03/09 MCCARTHY.L T California, State of 4pp 22761356, 24X Fiche 50-275,84/03/09,8403260106
- --8403260ii1 Expresses concern re possibility that facility will be licensed w/o meeting safety stds MCCARTHY,L T California, State of 84/01/26 PALLADINO,N Commissioners 1p 22761 359 24X Fiche 50-275,84/03/07,840326010A
- 8403270367 Telecopy itr expressing concerns re lifting of suspended low power license Commission should carefully weigh ABLAB conclusions & fulfill responsibility to require safe plant operation THOMAS,W M House of Rep DSB 143 84/03/26 PALLADIND,N Commissioners 2pp 22789 002 24X Fiche 50-275,84/03/26,840370367

V Operator Examinations

- B403220035 Forwards tables providing detailed operating experience for licensed operating personnel & licensed & nonlicensed shift technical advisors

 BCHUYLER.J O Pacific Gas & Electric Co 84/03/16 DENTON.H R Diffice of Nuclear Reactor Regulation. Director 5pp 22718 208 24X Fichs 50-275.84/03/16.8403220035
- 8403260176 Informs of plans to have shift advisors w/qualifications & training recommended by Near-Term OL Util Group on staff prior to exceeding 5% power Advisors will be subj to final sxam following training SGHUYLER.J O Pacific Gas & Electric Co 84/03/23 KNIGHTON.Q W Licemsing Branch 3 ip 22758 234 24% Fiche 50-275, 84/03/23, 8403260176
- DOCKET 50-277 PEACH BOTTOM ATOMIC POWER STATION, UNIT 2 F Security, medical, emergency & fire protection plans
- 8403090285 Public version of revised emergency plan implementing procedures, including Procedure EP-101 re classification of emergencies, EP-207C re first aid & EP-103 re alert response W/840210 ltr & JM Felton 840307 release memo COONEY, M J Philadelphia Electric Co 84/01/10 MURLEY, T E Region 1. Office of Director 93pp. 22593 228 24X Fiche 50-277, 84/01/10, 8403090055
- 8403010310 Forwards IE Insp Repts 50-277/83-37 & 50-278/83-35 on 831214-840112 & notice of violation BTARDSTECKI.R Division of Project & Resident Programs 84/02/16 DALTROFF.8 L Philadelphia Electric Co 2pp 22432 078 24X Fiche 50-277.84/02/16,8403010310

- --B403010322 IE Insp Repts 50-277/83-37 & 50-278/83-35 on B31214-840112 Violation noted requirements for requalification lecture attendance & supplementary training not met & adequacy of secondary containment door indicator maint unresolved BLOUGH.A R , WILLIAMS.J H , TRIPP.L E Region 1. Office of Director B4/01/19 17pp 22432 OB1 24X Fiche 50-277.84/02/16, 8403010310
- 8403190243 Notification of 840418 workshop in King of Prussia, PA to discuss lessons learned from recent App R fire protection safe shutdown insp 5 topics described in IE Info Natice 84-07 Agenda for workshop encl MURLEY, TE Region 1. Office of Director Consolidated Edison Co of New York, Inc 8RONS, J C , MCNEILL, C A Power Authority of the State of New York 35pp 22672 062 24% Fiche 50-000.84/03/09.8403190243
- 8403200371 Forwards list of applications submitted & applicable fees for fire protection reviews & approvals
 MILLER.W O License Fee Management Branch 84/03/09 BAUER,E G
 Philadelphia Electric Co 3pp 22708 310 24X
 Fiche 50-277.84/03/09,8403200391
- 8403220083 Notifies of error in numbering of second insp rept encl in 840127 ltr Number should be 30-278/83-29 instead of 83-19 Corrected version encl MARTIN.T T Division of Engineering & Technical Programs 84/03/12 DALTROFF, S.L. Philadelphia Electric Co 1p 22716 268 24X Fiche 50-277.84/03/12.8403220083
- --8403220085 Forwards corrected IE Insp Repts 50-277/83-31 & 50-278/83-29 on 831114-18 & notice of violation MARTIN, T T Division of Engineering & Technical Programs 84/01/27 DALTROFF, 8 L Philadelphia Electric Co 2pp 22714 269, 24% Fiche 50-277,84/03/12,8403220083
- --8403220087 Corrected notice of violation from insp on B31114-18 * Region 1, Office of Director 84/01/27 ip 22716 271 24x Fichs 50-277, 84/03/12, 8403220083
- --8403220091 Corrected IE Insp Repts 50-277/83-31 & 50-278/83-29 on 83114-18 Noncompliance noted failure to meet fire brigade training requirements PULLANIS V , ANDERSON, C J Region 1, Office of Director 84/01/03 10pp 22716 272 24X Fiche 50-277,84/03/12,8403220083
- 8403210045 Forwards application for amend to Licenses DPR-44 & DPR-56 re fire protection to reflect improvements in fire detection sys at to conform to STS BRADLEY,E J Philadelphia Electric Co 84/03/16 DENTON,H R Office of Nuclear Reactor Regulation, Director 1, 22707 042 24X Fiche 50-277,84/03/16,8403210045
- --B403210055 Application for amend to Licenses DPR-44 & DPR-56 modifying limiting condition for operation action statement for fire barriers to reflect guidance in STS for GE BWRs * Philadelphia Electric Co B4/03/16 bpp 22707 043 24X Fiche 50-277.84/03/16,8403210045
- --8403210063 Proposed Tech Specs modifying limiting condition for operation action statement for fire barriers to reflect guidance provided in STS for GE BHRs # Philadelphia Electric Co 84/03/16 3pp 22707 049 24X Fichs 50-277,84/03/16,8403210045
- B403270104 Requests extension until Oct 1984 for annual emergency preparedness exercise Extension would allow inclusion of offsite plans & use of proposed alternate emergency facility location
 DALTROFF, B L Philadelphia Electric Co 84/03/20 EISENHUT, D G Division of Licensing 6pp 22769 217 24% Fiche 50~277,84/03/20. B403270104
- J Insurance & indemnity information
- 8403260054 Forwards Endorsements 106 & 107 to NELIA Policy NF-140 & Endorsement 59 to MAELU Policy MF-67
 BRADLEY, E. J. Philadelphia Electric Co. 84/03/16 BALTZMAN, J. Assistant Director for State & Licensee Relations 4pp 22750 232 24X Fiche 50-277.84/03/16.8403260054
- P Operating license stage documents & correspondence
- 8403140340 Summary of 831215 meeting w/GE & Mark I Dwners Group in Bethesda:MD re Mark I containment wetwell-drywell vacuum breaker design methodology SIEGEL.B L Operating Reactors Branch 2 84/02/21 Operating Reactors Branch 2 51pp 22635:198 24X Fiche 50-000,84/02/21. 8403140340

- 8403070137 Forwards Amends 92 & 94 to Licenses DPR-44 & DPR-36, respectively & EIA Amends delete certain ETS re noise monitoring requirements & nonradiological water quality-related requirements
 STOLZ.J F Operating Reactors Branch 4 84/02/24 QAUER.E 6
 Philadelphia Blectric Co 3pp 92565 160 24X
 Fithe 50-277.84/02/24.8403070137
- --8403070141 Amends 92 & 94 to Liconses DPR-44 & DPR-56, respectively, deleting certain ETS re-noise monitoring requirements & nonradiological water quality-related requirements STOL7.J F Operating Reactors Branch 4 84/02/24 15pp 22565 163 24% Fiche 50-277.84/02/24.8403070137
- --8403070144 EIA supporting Amends 92 & 94 to Licenses DPR-44 & DPR-56, respectively * Office of Nuclear Reactor Regulation. Director 84/02/24 10pp 22355 179 24X Fiche 50-277.84/02/24,8403070137
- 8403150013 Forwards response to request for add1 info re Class IE electrical recessy supports Design supports have sufficient margin to assure that loss of single support will not cause loss of safety function SCHUYLER.JO Pacific Gas & Electric Co 84/03/07 MARTIN.JB Region 5. Office of Director 3pp 22640 327 24X Fishe 50-277.84/03/07.8403150013
- 8403150137 Forwards application to amend Licenses DPR-44 & DPR-56, revising Tech Specs to incorporate 10CFR50. App I requirements for radiological effluents DALTROFF.S L. Philadelphia Electric Co. 84/03/07 STOLZ.J F Operating Reactors Branch 4 2pp 22646 022 24X Fiche 50-277.84/03/07.8403150137
- ---8403150140 Application for amend to Licenses DPR-44 & DPR-56, revising Tech Specs to incorporate radiological effluent requirements of 10CFR50.App I BAUER.E 6. BRADLEY,E J. Philadelphia Electric Co. 84/03/07 12pp 22648
- --B403130143 Proposed Tech Spec changes, incorporating radiological effluent requirements of 10CFR30. App I * Philadelphia Electric Co 84/03/07 82pp 22646.036 24X Fiche 50-277, 84/03/07, 8403130137
- 8403150005 "Radiation Protection Program for Recirculate Piping Replacement" W/840308 ltr DALTROFF.S L Philadelphia Electric Co 84/03/08 STOLZ, J F Operating Reactors Branch 4 lipp 22441 339 24X Fiche 50-277.84/03/08.8403150005
- 8403270064 Forwards revised "Offsite Dose Calculation Manual." per NRC 830929 request re radiological effluent Tech Specs ULLRICH.W T Philadelphia Electric Co 84/03/08 PANDEY.S Franklin Institute/Franklin Research Center 1p 22766 106 24X Fiche 50-277.84/03/08.8403270064
- --8403270067 Revised 'Offsite Dose Calculation Manual "
 * Philadelphia Electric Co 84/03/08 41pp 22766 107 24X
 Fiche 50-277,84/03/08,8403270064
- 8403150275 Generic Ltr 84-07 to all licensess of BWRs re procedural guidance for pape replacement at 8WRs Svc list encl EISENHUT.D G Division of Licensing 84/03/14 Commonwealth Edison Co 20pp 22823 354 24X Fache 50-000,84/03/14,8403150275
- B4032i0045 Forwards application for amend to Licenses DPR-44 & DPR-56 re fire protection to reflect improvements in fire detection sig & to conform to ST8

 BRADLEY, E J Philadelphia Electric Co B4/03/16 DENTON, H R
 Office of Nuclear Reactor Regulation. Director ip 22707 042 24X
 Fiche 50-277.84/03/16.84032i0045
- --8403210055 Application for amend to Licenses DPR-44 & DPR-56 modifying limiting condition for operation action statement for fire barriers to reflect guidance in STS for GE BHRs * Philadelphia Electric Co 64/03/14 App 22707 043 24X Fiche 50-277,84/03/16.8403210045
- --BA03210063 Proposed Tech Specs modifying limiting condition for operation action statement for fire barriers to reflect guidance provided in STB for GE BMRs Philadelphis Electric Co 84/03/16 3pp 22707 049 24x Fichs 50-277.84/03/16.8403210045

- G Inspection reports, IE Bulletins & correspondence
- 8403010310 Forwards IE Insp Repts 50-277/83-37 & 50-278/83-35 on 831214-840112 & notice of violation STAROSTECKI.R Division of Project & Resident Programs 84/02/16 DALTROFF,5 & Philadelphia Electric Co 2pp 22432 078 24X Fiche 50-277.84/02/16.8403010310
- --8403010315 Notice of violation from insp on 831214-840112 * Region i, Office of Director 84/02/16 ip 22432 080 24X Fichs 50-277.84/02/16.8403010310
- --8403010322 IE Insp Repts 50-277/83-37 & 50-278/83-35 on 831214-840112 Violation noted requirements for requalification lecture attendance & supplementary training not met & adequacy of secondary containment door indicator maint unresolved 8LOUGH.A R. WILLIAMS.J H., TRIPP.L E. Region 1, Office of Director 84/01/19 17pp 22432 081 24X Fiche 50-277.84/02/16.8403010310
- 8403020306 Forwards IE Insp Repts 50-277/84-05 & 50-278/84-05 on 840130 No violations noted MARTIN,T T Division of Engineering & Technical Programs 84/02/17 DALTRUFF, S. Philadelphia Electric Co 2pp 22440 035 24X Fiche 50-277.84/02/17.8403020304
- ---8403020309 IE lnsp Repts 50-277/84-03 & 50-278/84-05 on 840130 No violations neted Major areas inspected Eastern Testing & Insp. Inc radiographs & licensee reinterpretation reader sheets

 KERCH: HW Region 1, Office of Director DURR, J P Division of Engineering & Technical Programs 84/02/16 3pp 22440 037 24) Fichs 50-277,84/02/17,8403020306
- B403070081 Forwards Suppl 4 to response to IE Bulletin 83-02, consisting of rept, "Recirculation, RHR Shutdown Cooling, Head Spray Line Reactor Info (Rev 2) "
 DALTROFF, 8 L Philadelphia Electric Co 84/02/21 MURLEY, T E Region 1, Office of Director 3pp 22575 153 24X
 Fiche 50-277,84/02/21.8403090081
- --8403090089 "Retirculation RHR Shutdown Cooling, Head Spray Line, Reactor Water Cleanup Line & Core Spray Line Piping Weld Info (Rev 2) " * Philadelphia Electric Co 84/02/29 61pp 22575 156 24X
 - * Philadelphia Electric Co 84/02/27 61pp 2257\$ 156 24X Ficha 50-277,84/02/21,84030900B1
- 8403070320 Forwards IE Insp Repts 30-277/84-04 & 50-278/84-04 on B40125-27 No violations noted MARTIN,T T Division of Engineering & Technical Programs 84/02/22 DALTROFF, B. Philadelphia Electric Co 2pp 22546 330 24X Fiche 50-277.84/02/22.8403070320
- --8403070322 IE Insp Rept 50-277/84-04 & 50-278/84-04 on 840125-27 No violations noted Major areas inspected licensee actions in response to torus mod requirements & IE Bulletin 78-11 NARRUN.L . DURR.J P Region 1. Office of Director 84/02/07 3pp 22546 332 24X Fiche 50-277.84/02/22.8403070320
- 8401190072 IE Info Natice 84-13. "Potential Deficiency in Mater Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Past 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22909 239 24X Fiche 50-000,84/02/28,8401190072
- 8403150054 Forwards IE Insp Repts 50-277/84-01 & 50-278/84-01 on B40105-20 Enforcement conference planned to discuss problem w/internal review process for identifying & evaluating potential unreviewed safety questions STAROSTECKI.R Division of Project & Resident Programs 84/02/27 DALTROFF.5 L Philadelphia Electric Co 2pp 22642 298 24X Fiche: 50-277.84/02/27.8403150054
- --8403150063 IE Insp Repts 50-277/84-01 & 50-278/84-01 on 840105-20. Approval of individual rod scram procedures in apparent violation of 10CFR50 59 Three examples of inadequate procedures noted BLOUGH.A R . WILLIAMS.J H . TRIPP.L E Region 1. Office of Director. 84/02/28 12pp 22642 300 24X Fiche.50-277,84/02/29,8403150054
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Eve list encl GRACE: J N Division of GA. Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 130pp 22552:329 24X Fiche 50-000.84/03/02.8402090007

- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 122pp 22553 098 24X Fiche 50-000.84/03/02.8402090008
- 8402090009 IE Info Notice 84-i5, "Reporting of Radiological Releases" 8vc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- Response (Post B30103) 84/03/02 Consolidated Edison Co of New York, Inc 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24% Fiche 50-000,84/03/05,8402090011
- 8403090131 Forwards description of plans for recirculation & RHR syspiping replacement during upcoming Unit 2 refuel outage per IE Bulletin 83-02 Mod/refueling outage work should be completed within 32 whs Two oversize drawings encl DALTROFF, 8 L Philadelphia Electric Co 84/03/04 STOLZ, J F Operating Reacture Branch 4 21pp 22548 275 24X Fiche. 30-277,84/03/06,8403090131
- 8402090024 IE Info Notice 84-09, Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys." Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22635 049 24X Fiche 50-000,84/03/07,8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Bys " Byc list enc! JORDAN,E L Division of Emergency Proparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Bafety Sys " Svc list encl DEYOUNG, R C Director's Defice, Office of Inspection and Enforcement B4/03/12 Consolidated Edison Co of New York, Inc 134pp. 22823 094 24X Fiche 50-000,84/03/12,8402090031
- 8403220083 Notifies of error in numbering of second insprept encl in 840127 ltr Number should be 50-278/83-29 instead of 83-17 Corrected version encl MARTIN, T T Division of Engineering & Technical Programs 84/03/12 DALTROFF, B L Philadelphia Electric Co ip 22716 268 24X Fichs 50-277,84/03/12,8403220083.
- --8403220085 Forwards corrected IE Insp Repts 50-277/83-31 & 50-278/83-29 on 83114-18 & notice of violation MRTIN.T T Division of Engineering & Technical Programs 84/01/27 DALTROFF.8 L Philadelphia Electric Co 2pp 22716:269 24X Fiche 50-277,84/03/12.8403220083
- --8403220087 Corrected notice of violation from insp on 831114-18 * Region 1, Office of Director 84/01/27 1p. 22716 271 24X Fiche 50-277,84/03/12,8403220083
- --840322007i Corrected IE Insp Repts 50-277/83-31 & 50-278/83-27 on 831114-18 Noncompliance noted failure to meet fire brigade training requirements PULCANI,8 V ANDERSON,C J Region 1, Office of Director 84/01/03, 10pp 22716-272 24X Fiche 50-277.84/03/12,8403220083
- 8402090043 IE Info Notice 84-19, "Two Eyents Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21. Consolidated Edison Co. of New York Inc. 123pp 22823 229, 24X Fichs 50-000.84/03/21,8402090043
- 8402090044 IE Info Notice B4-20, "Svc Life of Relays in Safety-Related Bys." Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/21 Consolidated Edison Co of New York, Inc 135pp 22923 001 24X Fiche 50-000,84/03/21,8402090044
- 8403270250 Forwards response to 840207 request for addl info re IE Bulletin 80-11, "Masonry Wall Design." Min reinforcement for all block walls exceeds requirements.

 DALTROFF, S.L. Philadelphia Electric Co. 84/03/21, STOLZ, J.F. Operating Reactors Branch 4. 8pp. 22772, 097. 24X Fiche. 50-277, 84/03/21, 8403270250

- R Periodic operating reports & related correspondence
- 8403050117 "Semiannual Effluent Releases Rept 16, JUI-Dec 1983 " W/ 840229 1tr ALDEN,W M Philadelphia Electric Co 83/12/31 MURLEY.T E Region 1. Office of Director 1Ppp 22488 016 24X Fiche 50-277.83/12/31. 8403050117
- 8403190198 Monthly operating repts for Feb 1984 W/840313 ltr ALDEN,W M , ULLRICH,W T Philadelphia Electric Co 84/02/29 10pp 22671 132 24X Fiche 50-277,84/02/29,8403190198
- 8 Reportable occurrences, LERs & related correspondence
- 8403010358 LER 84-001-00 on 840117, during surveillance testing of RHR B injection valve MO 2-101548, valve failed to reopen Caused by warping of Bakelite coil & core housing within motor control ctr Thermal overload device replaced W/840227 ltr CLARK.8 L . LOQUE.R H Philadelphia Electric Co 84/02/27 4pp 22433 009 24% Fiche 50-277,84/02/27,8403010358
- 8403120085 LER 84-003-00 on 840131 operator failed to take corrective action rapidly enough to contain reactor coolant temp, allowing heatup rate to reach 120 F Caused by personnel error Operator disciplined W/840301 ltr CLARK, 8 L , ULLRICH, W T Philadelphia Electric Co 84/03/01 4pp 22588 179 24X Fiche 50-277,84/03/01,8403120080
- B403200019 LER B4-004-00 on B40213 during local leak rate tests on RHR sys B valves, packing leak discovered on test line isolation valve MD2-10-34B Caused by loose packing Packing tightened & valve stroke tested W/B40314 ltr CLARK, B L , ULLRICH, W T Philadelphia Electric Co B4/03/14 4pp 22698 350 24X Fiche 50-277, B4/03/14, 8403200019
- DOCKET 50-278 PEACH BOTTOM ATOMIC POWER STATION, UNIT 3

 F Security, medical, emergency & fire protection plans
- 8403090285 Public version of revised emergency plan implementing procedures, including Procedure EP-101 re classification of emergencies, EP-207C re first aid & EP-103 re alert response W/B40210 ltr & JM Felton 840307 release memo CUDNEY, M J Philadelphia Electric Co 84/01/10 NURLEY, T E Region I, Office of Director 93pp 22593 228 24X Fiche 30-277.84/01/10.8403090285
- 8403010310 Forwards IE Insp Repts 50-277/83-37 & 50-278/83-35 on 831214-840112 & notice of violation STAROBIECKI.R Division of Project & Resident Programs 84/02/16 DALTROFF, B L Philadelphia Electric Co 2pp 22432 078 24X Fiche 50-277,84/02/16.8403010310
- --B403010322 IE Insp Repts 50-277/83-37 & 50-278/B3-35 on 831214-840112 Violation noted requirements for requalification lecture attendance & supplementary training not met & adequacy of secondary containment door indicator maint unresolved BLOUGH. A R Region i. Office of Director B4/01/19 17pp 22432 081 24X Fiche 50-277.84/02/16.8403010310
- 8403190243 Notification of 840418 workshop in King of Prussia.PA to discuss lessons learned from recent App R fire protection safe shutdown insp & topics described in IE Info Notice 84-09 Agenda for workshop encl MURLEY.T R Region 1. Office of Director 84/03/09 O'TODLE.J D Consolidated Edison Co of New York. Inc CAREY.J J Duquesne Light Co MARTIN.T J Public Service Electric & Gas Co of New Jersey 35pp. 22472 062 24X Fiche 50-000.84/03/09.8403190243
- B403200391 Forwards list of applications submitted & applicable fees for fire protection reviews & approvals
 MILLER.W O License Fee Management Branch 84/03/09 BAUER.E G
 Philadelphia Electric Co 3pp 22708 310 24X
 Fichs 50~277,84/03/09.8403200391
- 8403220083 Natifies of error in numbering of second insp rept encl in 840127 ltr Number should be 50-278/83-29 instead of 83-19 Corrected version encl.

 MARTIN.T T Division of Engineering & Technical Programs 84/03/12 DALTROFF, S.L. Philadelphia Electric Co ip R2714 268 24X Fiche 50-277,84/03/12,8403220083
- --B4032200B5 Forwards corrected IE Insp Repts 50-277/B3-31 & 50-278/B3-29 on B31114-1B & notice of violation MARTIN.Y T Division of Engineering & Technical Programs B4/01/27 DALTROFF.8 L Philadelphia Electric Co 2pp 22716

- --8403220087 Corrected notice of violation from insp on 831114-18 * Region 1, Office of Director 84/01/27 ip 22716 271 24X Fiche 50-277,84/03/12,8403220083
- --8403220091 Corrected IE Insp Repts 50~277/83-31 & 50-278/83-29 on B31114-18 Noncompliance noted failure to meet fire brigade training requirements PULLANI,S V Region 1, Dffice of Director 84/01/03 10pp 22716 272 24X Fichs 50-277,84/03/12,8403220083
- 8403210045 Forwards application for amend to Licenses DPR-44 & DPR-56 re Pire protection to reflect improvements in fire detection sys & to conform to STS BRADLEY, E J Philadelphia Electric Co. 84/03/16 DENTON. H R Office of Nuclear Reactor Regulation, Director ip 22707 042 24X Fiche 50-277.84/03/16.8403210045
- --B403210055 Application for amend to Licenses DPR-44 & DPR-56 modifying limiting condition for operation action statement for fire barriers to reflect guidance in STS for GE BHRs * Philadelphia Electric Co B4/03/16 App 22707 043 24X Fiche 50-277,84/03/16,8403210045
- --8403210063 Proposed Yech Specs modifying limiting conditions for operation action statement for fire barriers to reflect guidance provided in STB for GE BWRs * Philadelphia Electric Co 84/03/16 3pp 22707 049 24X Fiche 50-277,84/03/16.8403210045
- 8403270104 Requests extension until Oct 1984 for annual emergency preparedness exercise Extension would allow inclusion of offsite plans & use of proposed alternate emergency facility location DALTROFF, S. L. Philadelphia Electric Co. 84/03/20 EISENHUT, D. 9 Division of Licensing. App. 22749 217 24X Fiche: 50-277, 84/03/20, 8403270104
- J. Insurance & indemnity information
- B40326034 Forwards Endorsements 106 & 107 to NELIA Policy NF-140 & Endorsement 39 to MAELU Policy MF-67 BRADLEY,E J Philadelphia Electric Co 84/03/16 BALT2MAN,J Assistant Director For State & Licensee Relations 4pp 22750 232 24% Fiche 50-277.84/03/16.8403260054
- P Operating license stage documents & correspondence
- 8403140340 Summary of 631215 meeting w/GE & Mark I Owners Group in Bethesda: MD re Mark I containment wetwell-drywell vacuum breaker design methodology SIEGEL, B L Operating Reactors Branch 2 64/02/21 Operating Reactors Branch 2 51pp 22635 198 24X Fiche 50-000, 84/02/21, 8403140340
- B403070137 Forwards Amends 92 & 94 to Licenses DPR-44 & DPR-96, respectively & EIA Amends delete certain ETS re noise monitoring requirements & nonradiological water quality-related requirements STDLZ.J F Operating Reactors Branch 4 84/02/24 BAUER.E 0 Philadelphia Electric Co 3pp 22565 160 24X Fichs 50-277 84/02/24,8403070137
- --8403070141 Amends 92 & 94 to Licenses DPR-44 & DPR-36, respectively, deleting certain ETS re-noise monitoring requirements & nonradiological water quality-related requirements STOLZ.J F Operating Reactors Branch 4 84/20/24 15pp 22565 163 24% Fiche 50-277,84/02/24,8403070137
- --8403070144 EIA supporting Amends 92 & 94 to Licenses DPR-44 & DPR-36, respectively * Office of Nuclear Reactor Regulation. Director 84/02/24 10pp 22565 179 24X Fiche 50-277,84/02/24,8403070137
- 8403150137 Forwards application to amend Licenses DPR-44 & DPR-56, revising Tech Specs to incorporate 10CFR50, App I requirements for radiological effluents DALTROFF, S.L. Philadelphia Electric Co. 84/03/07 SYDLZ, J. F. Operating Reactors Branch 4. 2pp. 22646-022 24X Fiche 50-277, 84/03/07, 8403150137
- --8403150140 Application for amend to Licenses DPR-44 & DPR-56, revising Tech Specs to incorporate radiological effluent requirements of 10CFR50, App I. BAUER, E G. BRADLEY, E J. Philadelphia Electric Co. 84/03/07 12pp 22646 024 24% Fiche 50-277, 84/03/07, 8403150137.
- ~-8403150143 Proposed Tech Spec changes, incorporating radiological effluent requirements of IOCFR30.App I * Philadelphia Electric Co. 84/03/07 82pp 22646 036 24X Fichs 50-277.84/03/07.8403150137

- 8403270064 Forwards revised "Offsite Dose Calculation Manual," per NRC 830929 request re radiological effluent Tech Specs ULLRICH.H T Philadelphia Electric Co 84/03/08 PANDEY.8 Franklin Institute/Franklin Research Center 1p 22766 106 24X Fiche 50-277.84/03/08.8403270064
- --B403270067 Revised "Offsite Dose Calculation Manual "

 * Philadelphia Electric Co. B4/03/08 41pp 22766 107 24x
 Ficha 50-277,84/03/08,8403270064
- 8403150275 Generic Ltr 84-07 to all licensees of BWRs re procedural guidance for pipe replacement at BWRs Svc list encl EIBENNUT, D G Division of Licensing 84/03/14 Commonwealth Edison Co 20pp 22823 354 24X Fiche 50-000,84/03/14,8403150275
- 8403210045 Forwards application for amend to Licenses DPR-44 & DPR-56 re fire protection to reflect improvements in fire detection sys & to conform to STS BRADLEY.E J Philadelphia Electric Co 84/03/16 DENTON,H R Office of Nuclear Reactor Regulation, Director ip 22707.042 24X Fiche 50-277,84/03/16.8403210045.
- --B403210055 Application for amend to Licenses DPR-44 & DPR-56 modifying limiting condition for operation action statement for fire barriers to reflect guidance in STB for GE BMRs * Philadelphia Electric Co B4/03/16 App 22707 043 24X Fiche 50-277,84/03/16,8403210045
- --8403210063 Proposed Tech Specs modifying limiting condition for operation action statement for fire barriers to reflect guidance provided in STS for GE BMRs * Philadelphia Electric Co 84/03/16 3pp 22707 049 24X Fichs 50-277,84/03/16,8403210045
- Q Inspection reports, IE Bulletins & correspondence
- 8403010310 Forwards IE Insp Repts 50-277/83-37 & 50-278/83-35 on B31214-840112 & notice of violation STAROSTECKI, R Division of Project & Resident Programs 84/02/16 DALTRGFF, S L Philadelphia Elsectric Co 2pp 22432 078 24X Fichs 50-277,84/02/16,8403010310
- --8403010315 Notice of violation from insp on 831214-840112 * Region 1. Diffice of Director 84/02/16 ip 22432 080 24X Fiche 50-277.84/02/16.8403010310
- ---B403010322 IE Insp Repts 50-277/83-37 & 50-278/83-35 on 831214-840112
 Violation noted requirements for requalification lecture
 attendance & supplementary training not met & adequacy of
 secondary containment door indicator maint unresolved
 BLCUOH, A R , WILLIAMS, J H , TRIPP, L E Region 1. Office of
 Director 84/01/19 17pp 22432 081 24X Fiche 50-277,84/02/16,
 8403010310
- 8403020306 Forwards IE Insp Repts 50-277/84-05 & 50-278/84-05 on B40130 No violations noted MARTIN, T T Division of Engineering & Technical Programs. 84/02/17 DALTROFF, S L Philadelphia Electric Co 2pp 22440 035 24X Fiche 50-277,84/02/17,8403020304
- --8403020309 IE Insp Repts 30-277/84-05 & 50-278/84-05 on 840130 No violations noted Major areas inspected Eastern Testing & Insp.Inc radiographs & licensee reinterpretation reader sheets

 KERCH. H W Region 1. Office of Director DURR. J P Division of Engineering & Technical Programs 84/02/16 3pp 22440 037 24X Fiche 50-277.84/02/17.8403020306
- 8403070320 Forwards IE Insp Repts 50-277/84-04 & 50-278/84-04 on 840125-27 No violations noted MARTIN.T T Division of Engineering & Technical Programs. 84/02/22 DALTROFF,8 L Philadelphia Electric Co 2pp 22546 330 24X Fiche. 50-277, 84/02/22, 8403070320
- --8403070322 IE Insp Rept 50-277/84-04 & 50-278/84-04 on 840125-27 No violations noted Major areas inspected licensee actions in response to torus mod requirements & IE Bulletin 78-11 NARROM, L., DURR, J.P. Region 1. Office of Director 84/02/07 3pp 22546 332 24X Fiche. 50-277, 84/02/22, 8403070320.
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valva Control Circuits & Annunciation " Svc list and! JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 113pp 22909 239 24X Fiche 50-000,84/02/28,8401190072

- 8403150054 Forwards IE Insp Repts 50-277/84-01 & 50-278/84-01 on 840105-20 Enforcement conference planned to discuss problem w/internal review process for identifying & evaluating potential unreviewed safety questions STAROBTECKI.R Division of Project & Resident Programs 84/02/29 DALTROFF.S L Philadelphia Electric Co 2pp 22642 298 24X Fichs 50-277.84/02/29.8403150054
- --B403150063 IE Insp Repts S0-277/84-01 & 50-278/84-01 on 840105-20
 Approval of individual rod scram procedures in apparent
 violation of 10CFR50 57 Three examples of inadequate
 procedures noted
 BLOUGH.A R , HILLIAMS.J H , TRIPP.L E Region 1. Office of
 Director 84/02/28 12pp 22642 300 24X Fiche 50-277,84/02/27.
 B403150054
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl QRACE.J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fichs 50-000:84/03/02,8402090007
- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN.E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc 122pp 22553 098 24% Fiche 50-000, 84/03/02, 8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases"
 Svc list encl
 JORDAN, E.L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co. of New
 York, Inc 119pp 22593 217 24X Fiche 50-000,84/03/02,8402090009
- B402090011 IE Info Notice B4-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) B4/03/05 Consolidated Edison Co of New York, Inc. 117pp 22553 336 24% Fichs 50-000; B4/03/05, B402090011
- 8402090024 IE Info Notice 84-09, Rev 1: "Lessons Learned From Insps of Fire Protection Bafe Shutdown Sys " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp. 22635 049 24X Fiche 50-000, 84/03/07, 8402090024
- 8402090028 IE Info Notice 84-18, "Btress Corrosion Cracking in PWR 8ys." Svc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fichs 50-000,84/03/07,8402070028
- B402090031 IE Bullatin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl
 DEYQUNG.R C Director's Office. Office of Inspection and
 Enfoncement B4/03/12 Consolidated Edison Co of New York, Inc
 134pp 22823:094 24X Fiche 50-000.84/03/12.8402090031
- 8403220083 Notifies of error in numbering of second insp rept encl in 840127 ltr Number should be 50-278/83-29 instead of 83-19 Corrected version encl MARTIN,T.T Division of Engineering & Technical Programs 84/03/12 DALTROFF,8 L Philadelphia Electric Co ip 22714 268 24X Fiche, 50-277,84/03/12,8403220083
- ---8403220085 Forwards corrected IE Insp Repts 50-277/83-31 & 50-278/83-29 on 831114-18 & notice of violation MARTIN:T T Division of Engineering & Technical Programs 84/01/27. DALTROFF:8 L Philadelphia Electric Co 2pp 22716.289 24X Fiche 50-27:84/03/12:8403220083.
- --8403220087 Corrected notice of violation from insp on 831114-18 * Region 1, Office of Director 84/01/27 1p. 22716.271 24X Fiche 50-277.84/03/12,8403220083
- --8403220091 Corrected IE Insp Repts 50-277/83-31 & 50-278/83-29 on 831114-18 Noncompliance noted failure to meet fire brigade training requirements.
 PULIANI, 8 V , ANDERSON, C J Region 1, Office of Director 84/01/03 10pp 22716-272 24X Fiche 50-277,84/03/12,8403220083
- 8402070043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities." Syc list encl.
 JURDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229, 24X Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Bafety-Related 8ys." Svc list encl. JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/03/21 Consolidated Edison Co of New York, Inc. 135pp. 22933 001 24X Fiche 50-000,84/03/21,8402090044

- 8403270250 Forwards response to 840207 request for add1 info re IE Bulletin 80-11, "Masonry Wall Design " Min reinforcement for all block walls exceeds requirements DALTROFF, B L Philadelphia Electric Co 84/03/21 STDL2, J F Operating Reactors Branch 4 8pp 22772 097 24X Fiche 50-277.84/03/21.8403270250
- R Periodic operating reports & related correspondence
- 8403050117 "Semiannual Effluent Releases Rept 16, Jul-Dec 1983 " W/ 840229 Itr ALDEN, W M Philadelphia Electric Co 83/12/31 MURLEY, T E Region 1. Office of Director 12pp 22488 016 24X Fiche 50-277, 83/12/31, 8403050117
- 8403190198 Monthly operating repts for Feb 1984 W/B40313 ltr ALDEN.W M · ULLRICH.W T Philadelphia Electric Co 84/02/29 10pp 22671 132 24X Fiche 50-277.84/02/29.8403190198
- 8 Reportable occurrences. LERs & related correspondence
- 8403120175 LER 84-002-00 on 840124, during unit startup, calculational error resulted in reactor heatup rate of 111 F/h Caused by personnel error Heatup rate immediately reduced W/840223 ltr
 CLARK, B L . ULLRICH, W T Philadelphia Electric Co 84/02/23 4pp 22570 197 24X Fiche 50-278, 84/02/23, 8403120175
- B403120019 LER B4-004-00 on B40125, reactor coolant temp dropped below 120 F when feedwater inadvertently pumped into reactor vassel Caused by operator error Level restored to normal & main steam line drains opened H/B40301 ltr CLARK, B L , ULLRICH, W T Philadelphia Electric Co 84/03/01 4pp 22886 264 24x Fiche 50-278, B4/03/01, B403120019
- 8403130158 LER 84-005-00 on 840209, reactor auto scram on high neutron flux occurred due to runback & subsequent relay failure in main turbine electrohydraulic control sys Caused by faulty relay contact Ralay replaced W/840307 ltr CLARK.B L . ULLRICH.W T Philadelphia Electric Co 84/03/07 4pp 22599 152 24% Fiche 50-278,84/03/07,8403130158
- DOCKET 50-280 SURRY POWER STATION, UNIT 1
- F Becurity, medical, emergency & fire protection plans
- 8403070239 Forwards BALP Repts 50-280/83-33.50-281/83-35.50-338/83-33 & 50-339/83-33 for Oct 1782 Aug 1983 Evaluation will be discussed at 831208 meeting at North Anna site LEWIS.R C Division of Project & Resident Programs 83/11/25 STEWART.W L Virginia Electric & Power Co 2pp 22536 227 24% Fiche 50-000.83/11/25.8403070239
- --8403070246 SALP Repts 50-280/83-33.50-281/83-35.50-338/83-33 & 50-339/83-33 for Oct 1982 Aug 1983 Reliable performance w/improvement in most previously noted areas of weakness demonstrated * Region 2, Office of Director 83/11/25 42pp 22536 229 24x Fiche 50-000,83/11/25,8403070239
- 8401130314 Supplemental info to 801028 application to amend Licenses DPR-31 & DPR-37 re fire pump flow testing Justification for capability of fire pumps to provide adequate fire protection provided

 STEWART. H L Virginia Electric & Power Co 84/01/09 DENTON, H R Office of Nuclear Reactor Regulation, Director VARGA, 8 A Operating Reactors Branch 1 2pp 21798 313 24X Fichs 50-280,84/01/09,8401130314
- 8403280125 Public version of Rev 9 to Emergency Plan Implementing Procedure EPIP-1 01, "Emergency Manager Controlling Procedure " W/940123 ltr & JM Felton 840322 release memo. WILSON.J, GRADY.D. STEWART.W.L. Virginia Electric & Power Co 64/01/13 O'REILLY.J P Region 2, Office of Director 5pp 22811 082 24X Fiche.50-280,84/01/13,8403280125
- 8403070250 Forwards IE Insp Repts 50-280/83-37 % 50-281/83-39 on 831201-31 No violations or deviations identified DANCE, H C Division of Project & Resident Programs 84/02/10 STEMART W L Virginia Electric & Power Co Rep 22546 016 24X Fiche 50-280,84/02/10,8403070250
- --8403070253 IE Insp Repts 50-280/83-37 k 50-281/83-39 on 831201-31 No violations or deviations identified Major areas inspected operations, plant security, followup of events & LERs. performance appraisal insp findings & surveillance review BURKE, D J, DAVIB, M J Region 2, Office of Director ELROD, 6 Division of Project & Resident Programs 84/02/09 7pp 22546 018 24X Fiche 50-280,84/02/10,8403070250

- 8403090242 Rev 4 to Emergency Plan Implementing Procedure EPIP-4 23, "Post-Accident Sampling of Reactor Coolant " W/840302 ltr STEWART, W L Virginia Electric & Power Co 84/02/16 O'REJLLY, J P Region 2, Office of Director 22pp 22573 228 24% Fiche 50-280.84/02/16.8403090242
- 8403200114 Forwards changes to security personnel training qualification program Changes withheld (ref 19CFR73 21) STEMART,W L Virginia Electric & Power Co 84/02/17 O'REILLY,J P Region 2, Office of Director ip 22685 335 24X Fiche 50-280.84/02/17.8403200116
- 8403190263 Rev 1 to corporate emergency response plan W/840315 ltr STEWART, W L. Virginia Electric & Power Co. 84/02/24 O'REILLY, J P Region 2. Office of Director 105pp 22670 135 24X Fiche 50-000.84/02/24.8403190263
- 8403060397 Forwards correction to B30217 ltr re revised pages to amergency plan implementing procedures W/o encl SALYERS.E M Virginia Electric & Power Co 84/02/29 NRC No Detailed Affiliation Given 1p 22518 133 24X Fiche 50-280.84/02/29.8403060397
- 8403080264 Forwards "Control Room Design Review Program Flan for North Anna & Surry Power Stations," in response to Suppl 1 to NUREG-0737 Review expected to be completed by 850830 STEWART,W L Virginia Electric & Power Co 84/03/01 DENTON,H R Office of Nuclear Reactor Regulation, Director EISENHUT, D G Division of Licensing 2pp 22557 295 24X Fiche 50-000,84/03/01. 8403080264
- ---84030B0269 "Control Room Design Review Program Plan for North Anna & Surry Power Stations." in response to Suppl 1 to NUREO-0737
 Virginia Electric & Power Co 84/03/01 111pp 22557 299
 24v Fiche 90-000,84/03/01,8403080264
- B403210117 Rev 11 to Emergency Plan Implementing Procedure EPIP-1 01, "Emergency Manager Controlling Procedure" & Rev 6 to Procedure EPIP-2 01, "Notification of State & Local Govts " #//840316 1tr # Virginia Electric & Power Co 84/03/01 D'REILLY, J P Region Office of Director 8pp 22705 067 24X Fiche 50-280,84/03/01, B403210117
- 8403080091 Submits addl info in order to conduct detailed review of emergency response procedures generation package, per 840125 request Items i & 2 will be addressed by 840530 Item 3 should be addressed by Westinghouse Owners Group STEWART, W.L. Virginia Electric & Power Co. 84/03/02 DENTON, H.R. Opfice of Nuclear Reactor Regulation, Director EISENHUT, D.G. Division of Licensing 2pp. 22559 199 24X Fiche 50-000, 84/03/02, 8403080091
- 8403090151 Revised emergency plan implementing procedures, including Rev ii to EPIP-1 OI, "Emergency Manager Controlling Procedure" & Rev & to EPIP-2 Oi, "Notification of State & Local Govts " W/840302 Itr SALYERS,E M Virginia Electric & Power Co 84/03/02 App 22575 046 24X Fiche 50-280,84/03/02,8403090151
- 8403160276 Extends invitation to attend 840316 workshop at regional ofc to discuss 10CFR50. App R requirements & results of insps to help resolve misunderstandings associated w/requirements LEMIS. R C Division of Project & Resident Programs 84/03/02 STEMART. W L Virginia Electric & Power Co ip 22660 080 24x Fiche 50-000.84/03/02.8403160276
- 8403150099 Forwards IE Safeguards Insp Repts 50-280/84-06 & 50-281/84-06 on 840227-0302 No violations or deviations identified DANCE. H C Division of Project & Resident Programs 84/03/09 STEHART. W L Virginia Electric & Power Co 2pp 22639 300 24X Fiche 50-280.84/03/09.8403150099
- --8403150107 IE Safeguards lnsp Repts 50-280/84-06 & 50-281/84-06 on 840327-0302 No noncompliance noted Major areas inspected security organization/mgt, personnel response, records & repts & testing Details withheld (ref 10CFR73 21 & 2 790) ENNIS.J D. MCOUIRE.D.R. Region 2. Office of Director 84/03/09 ip 22639 302 24X Fiche 30-280,84/03/09,8403150097
- 8403190052 Informs that local emergency operations facilities at North Anna & Surry Power Stations will be functional except for data communications & display, by 850731, per NUREG-0737, Suppl 1 STEWART, W.L. Virginia Electric & Power Co. 84/03/14 DENTON, H.R.
 - 1
 STEWART.W.L. Virginia Electric & Power Co. B4/03/14 DENTON, H.R. Office of Nuclear Reactor Regulation, Director, EISENHUT, D. G. Division of Licensing 2pp. 22666-173 24X Fiche 50-000, B4/03/14, B4/03190032

- B403230146 Rev 7 to Emergency Plan Implementing Procedure EPIP-2 01. "Notification of State & Local Govts "W/840316 ltr SALYERS.E M Virginia Electric & Power Co 84/03/16 3pp 22730 228 24% Fiche 50-280,84/03/16,8403230146
- J Insurance & indemnity information
- 8403140065 Endorsement 55 to MAELU Policy MF-37 * Mutual Atomic Energy Liability Underwriters 83/12/14 ip 22634 183 24X Fiche 50-280.83/12/14.8403140065
- 8403140067 Endorsement 72 to NELIA Policy NF-186 + Nuclear Energy Liability Insurance Association 83/12/14 1p 22633 083 24X Fiche 50-280,83/12/14,8403140067
- 8403140054 Endorsement 35 to NELIA Policy NS-314 * Nuclear Energy Liability Insurance Association 84/03/01 ip 22633 064 24X Fiche 50-280,84/03/01,8403140054
- 8403140059 Endorsement 74 to NELIA Policy NF-186

 * Nuclear Energy Liability Insurance Association 84/03/01 1
 22634 182 24X Fiche 50-280,84/03/01,8403140059
- P. Operating license stage documents & correspondence
- 8401130314 Supplemental info to S01028 application to amend Licenses DPR-31 & DPR-37 re fire pump flow testing Justification for capability of fire pumps to provide adequate fire protection provided STEWART, W. Virginia Electric & Power Co. 84/01/09 DENTON, H.R. Office of Nuclear Reactor Regulation, Director VARGA, S.A. Operating Reactors Branch i 2pp 21798 313, 24% Fiche 30-280,84/01/09,8401130314
- B403050230 "Radionuclide Release Under Specific LWR Accident Conditions: "Vol V. "PWR-Large, Dry Containment (Surry Recalculations) " OIEBEKE, J.A., CYBULSKIS, P., DENNING, R. B. Battelle Memorial Institute, Columbus Laboratories 8403050230 84/01/12 Office of Nuclear Regulatory Research, Director 212pp 22502.001 24x Fiche 50-280.84/01/12,8403050230
- B403080339 Final response to FDIA request for documents re NRC investigation of industrial accident involving burst steam pipe at facility "VEPCO Investigative Board Preliminary Rept" on accident placed in PDR FELTON, J M Division of Rules and Records 84/01/20 QARDE, B P Government Accountability Project ip 22574 214 24X Fichs 50-280,84/01/20,8403080339
- 8403160269 Confirms 840208 telcon re functional testing of snubbers Addl functional testing of Unit i snubbers per Tech Spec 4 17 C 6 will be completed during Feb 1984 maint outage Unit 2 testing to be completed during Mar 1984 maint outage LEMIG.R C Division of Project & Resident Programs 84/02/13 STEWART.W L Virginia Electric & Power Co 1p 22660.334 24X Fiche 50-280.84/02/13.8403160269
- 8403020054 Forwards Amends 95 & 94 to Licenses DPR-32 & DPR-37, respectively & safety evaluation Amends revise Tech Specs to change min boron injection tank boron concentration from il 5% to 0%, NEIGHBORS, J D. Operating Reactors Branch i 84/02/24 STEWART, W. L. Virginia Electric & Power Co. 2pp. 22491 018 24% Fiche 50-280,84/02/24,8403020054
- --B40302005B Amends 95 & 94 to Licenses DPR-32 & DPR-37, respectively, revising Teck Spacs to change min boron injection tenk boron concentration from 19% to 0% & changing boric acid sys boron concentration from 11 5% to 7% VAROA, B A Dperating Reactors Branch 1 84/02/24 18pp 22491 020 24% Fiche 50-280, 84/02/24, 8403020054
- --840302006i Bafety evaluation supporting Amends 95 & 94 to Licenses DPR-32 & DPR-37. respectively * Office of Nuclear Reactor Regulation, Director 84/02/24, 7pp 22491 038 24% Fiche 50-280,84/02/24,8403020054,
- B403020195 Forwards add1 info to complete review of Topical Rept
 VEP-FRD-41, "VEPCO Reactor Sys Transient Analysis Using
 RETRAN Computer Gode," in response to NRC Nov 1982 informal
 request
 STEMART.W.L. Virginia Electric & Power Co. 84/02/27. DENTON,H R
 Office of Nuclear Reactor Regulation, Director EISENHUT,D G.
 Division of Licensing 14pp 22443 237 24X Ficha 50-000,84/02/27.
 B403020195

- 8403050229 Submits review of post-accident sampling sys. Item II B 3 Ten of 11 criteria met Remaining criterion re procedure for estimating extent of core damage based on radionuclide evaluation, acceptable on interim basis
 MILLER.J R Operating Reactors Branch 3 84/02/27 STEWART, W L Virginia Electric & Power Co 6pp 22528 001 24X
 Fiche 50-000,84/02/27.8403050229
- 8403260105 Supplemental application for amend to Licenses DPR-32 & DPR-37 Suppl reflects change in title of fire marshal to loss prevention supervisor & deletes NDE supervisor STEMART. W.L. Virginia Electric & Power Co. 84/03/22 DENTON, H.R. Dffice of Nuclear Reactor Regulation, Director VAROA, S.A. Operating Reactors Branch 1. 5pp. 22758 238 24X Fiche 50-280,84/03/22,8403260105
- --8403260110 Proposed Tech Spec, changing organization title of fire marshal to loss prevention supervisor & deleting NDE supervisor position
 * Virginia Electric & Power Co 84/03/22 2pp 22758 243 24X Fiche 50-280, 84/03/22, 8403260105
- Q Inspection reports, IE Bulletins & correspondence
- 8403070239 Forwards SALP Repts 50~280/B3-33,50-281/B3-35,50-338/B3-33 & 50~339/B3-33 for Oct 1982 Aug 1983 Evaluation will be discussed at 831208 meeting at North Anna site LEWIS,R C Division of Project & Resident Programs B3/11/25 STEWART,W L Virginia Electric & Power Co 2pp 22536 227 24X Fiche:50~000,B3/11/25,B403070239
- --8403070246 8ALP Repts 50-280/83-33,50-281/83-35,50-338/83-33 & 50-339/83-33 for Oct 1982 -- Aug 1983 Reliable performance w/improvement in most previously noted areas of weakness demonstrated +- Region 2, Office of Director 83/11/25 42pp 22536 229 24X Fiche 50-000,83/11/25,8403070239
- 8403080339 Final response to FOIA request for documents re NRC investigation of industrial accident involving burst steam pipe at facility "VEPCO Investigative Board Preliminary Rept" on accident placed in PDR FELTON, J M Division of Rules and Records 84/01/20 QARDE, B P Government Accountability Project ip 22576 214 24X Fiche 50~280,84/01/20,8403080339
- --8403080341 "VEPCO Investigative Board Preliminary Rept " W/o cover sheet * Virginia Electric & Power Co 84/01/20 29pp 22576,215 24X fiche 30-280,84/01/20,8403080339
- 8403070250 Forwards IE Insp Repts 50-280/83-37 & 50-281/83-39 on 831201-31 No violations or deviations identified DANCE.H.C Division of Project & Resident Programs 84/02/10 BTEMARTW L Virginia Electric & Power Co 2pp 22546 016 24: Fichs. 50-280, 84/02/10, 8403070250
- --8403070253 lE Insp Repts 50-280/83-37 & 50-281/83-39 on 831201-31. No violations or deviations identified Major areas inspected operations, plant security, followup of events & LERs, performance appraisal insp findings & surveillance review BURKE, D.J. DAVIS, M.J. Region 2. Office of Director ELROD, 8 Division of Project & Resident Programs 84/02/09. 7pp 22546 018 24X Fiche 50-280,84/02/10,8403070250
- B403070279 Discusses SALP evaluation Issuance of SALP rept approved No major Weaknesses identified during assessment period at North Anna One major weakness identified in area of radiological controls at Surry O'REILLY.J P Region 2. Office of Director B4/02/16 STEWART.W L Virginia Electric & Power Co. 2pp 22541 286 24X Fiche 50-000,84/02/16,8403070279
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Bvc list enc!

 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22709*239 24X Fiche. 50-000;84/02/28,8401170072
- 8403140199 Forwards FR notice & safety evaluations of granting of relief from ABME Section XI inservice requirements.per 790517 & 0928.801215.820325 & 0525.830107.0307.0407 & 1227 requests VAROA.S A Operating Reactors Branch 1. 84/02/28 STEWART.W L. Virginia Electric & Power Co 4pp 22638.073, 24X Fichs.50~280.84/02/28.8403140199
- --B403140200 Notice of granting of relief from ABME Section XI inservice insp requirements.

 VAR9A,8 A Operating Reactors Branch 1 B4/02/28 2pp 22638 077 24X Fiche:50-280,84/02/28,8403140199

- --8403140202 Safety evaluation accepting licenses 801215,820325 & 0525 requests for relief from ABME inservice insp requirements * Office of Nuclear Reactor Regulation. Director 84/02/28 16pp 22638 079 24% Fiche 50-280.84/02/28.8403140199
- --8403140204 Gafoty evaluation accepting licensee B30107,0307.0414 & 1227 requests for relief from ABME inservice insp requirements # Defice of Nuclear Reactor Regulation. Director 84/02/28 18pp 22638 095 24X Fiche 50-280.84/02/28.8403140199
- --8207030161 "Inservice Insp Program," technical evaluation rept * Science Applications, Inc. NRC-03-82-076 SAI-186-028-20 82/08/27 NRC - No Detailed Affiliation Given 44pp 22638 113 24X Fichs 50-280,84/02/28.8303140179
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE, J N Division of GA. Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000.84/03/02,84020900007
- 8402090008 IE Info Notice 84-14. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008
- 8402090009 IE Info Notice 84-15. "Reporting of Radiological Releases" Svc list encl
 JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York. Inc 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8403160154 Responds to 1E Bulletin 83-08 re electrical circuit breakers w/undervoltage trip feature in use in safety-related applications other than trip sys Only reactor trip breakers contain subj trip attachments
 STEWART.W L. Virginia Electric & Power Co. 84/03/02 O'REILLY.J P. Region 2. Office of Director 2pp. 22806 008 24X
 Fiche 50-000.84/03/02.8403160154
- 8402090011 IE Info Natice 84-17. "Problems W/Liquid Nitrogen Cooling Campanents Below Nil Ductility Temp " Svc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- B402090024 IE Info Notice 84-09. Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000,84/03/07.8402090024
- 8402090028 IE Info Notice 84~18, "Stress Corresion Cracking in PWR 8ys " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186. 24X Fiche 50~000,84/03/07,8402090028
- B403150099 Forwards IC Safeguards Insp Repts 50-280/84-06 & 50-281/84-06 on 840227-0302 No violations or deviations identified DANCE.H C Division of Project & Resident Programs 84/03/09 STEWART,W L Virginia Electric & Power Co 2pp 22639 300 24x Fiche 50-280, 84/03/09, 8403150099
- --8403150107 IE Safeguerds Insp Repts 50-280/84-04 & 50-281/84-06 on 840227-0302 No noncompliance noted Major areas inspected sacurity organization/mgt.personnel response records & repts & testing Details withheld (ref 10CFR73 21 & 2 790) ENNIBJ D . MCGUIRE.D R Region & Office of Director 84/03/07 1p 22637 302 24X Fiche 50-280,84/03/07,8403150099
- 8402090031 IE Builetin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list anc!
 DEYDUNG:R C Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 074 24X Fiche 50-000;84/03/12,8402090031
- 8403290274 Discusses 840210 meeting re util plans:current events, present organizational changes & outstanding regulatory issues. Meeting beneficial & provided better understanding of plans O'RETLLY, J.P. Region 2. Office of Director 84/03/19 FERGUSION. J H. Virginza Electric & Power Co. ip. 22814-079 24X Fiche: 50~280,84/03/19,8403290274
- B402070043 IE Info Notice B4-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Bvc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc. 123pp 22823 229 24X Fiche 50-000,84/03/21,8402070043

- 8402090044 IE Info Notice 84-20. "Svc Life of Relays in Safety-Related
- Sys " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/21 Consplidated Edison Co of New Yark, Inc. 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044
- 8403270021 Informs that due to addit review required re math supplied by Ray Miller: Incrutil unable to respond to IE Bulletin 83-07 until 840406

 STEMART, W. U. Virginia Electric & Power Co. 84/03/22 DEYGUNO, R. C. Director's Office. Office of Inspection and Enforcement ip 22770 068 24X Fishe 50-000.84/03/22.8403270021
- B403290197 Resubmits B40302 response to IE Bulletin B3-08, "Electrical Circuit Breaters W/Undervoltage Trip Feature in Use in Safety-Related Applications..." Affirmation inadvertently unitted from 840302 itr encl
 BTEWART.W. Virginia Electric & Power Co 84/03/27 D'REILLY, J P
 Region 2, Office of Director 2pp 22806 006 24X
 Fiche 50-000.84/03/27,8403270157

R Periodic operating reports & related correspondence

- 8403020053 Forwards operating repts for Jan 1784 & corrected pages of health physics repts for Jul-Dec 1983 STEWART. W L Virginia Electric & Power Co 84/02/14 HALLER, N M NRC NO Detailed Affiliation Given 1p 22447 129 24X Fiche 50-280,84/02/14,8403020053
- --8403020059 Monthly operating repts for Jan 1984 WILSON, J., JONES, V. H. Virginia Electric & Power Cp. 8 38pp 22447 130 24% Fiche 50-280,84/02/14,8403020053 84/01/31
- --8403020063 Corrected page to health physics rept for monthly operating rapts for Nov 1983
 * Virginia Electric & Power Co 83/11/30 ip. 22447 170 24X
 Fiche 50-280.84/02/14.8403020053
- --8403020066 Corrected page to health physics rept for monthly operating repts for Dec 1983

 * Virginia Electric & Power Co 83/12/31 1p 22447, 171 24X
 Fiche 50-280, 84/02/14: 8403020053
- --8403020071 Corrected page to health physics rept for monthly operating repts for Jul 1983 * Virginia Electric & Power Co 83/07/31 lp 22447 172 24X Fiche 50-280.84/02/14.8403020053
- --8403020074 Corrected page to health physics rept for monthly operating repts for Aug 1983 * Virginia Electric & Power Co 83/08/31 1p 22447-173 24X Fichs 50-280,84/02/14,8403020053
- --8403020085 Corrected page to health physics rept for monthly operating repts for Sept 1983

 * Virginia Electric & Power Co 83/09/30 ip 22447 174, 24x Fishe 50-280,84/02/14,8403020053
- --8403020090 Corrected page to health physics rept for monthly operating repts for Oct 1983

 * Virginia Electric & Power Co 83/10/31 1p. 22447·175 24x
 Fiche 50-280.84/02/14.8403020033
- 9403300060 Monthly operating repts for Feb 1984.W/840315 ltr WILSON, J. STEWART, V. Vyrginia Electric & Power Co 94/0 HALLER, N. M. Office of Resource Management, Director 44pp. 22821 113 24X Fiche 50-280,84/02/29,8403300060 84/02/29

5 Reportable occurrences. LERs & related correspondence

- 8403090223 RD SPR-84-2 on 840118, specific activity sample of reactor coolant showed peak dose equivalent I-131 level of 1 87 uCi.exceeding Tech Spec limit Caused by fuel element defects in reactor care Dose level monitored.
 WILSON, J L. Virginia Electric & Power Co. 84/02/17 O'REII Region 2. Office of Director 3pp 22575 150 24X Fiche: 50-280,64/02/17,8903090223 84/02/17 O'REILLY, J P
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines. Gimpel NPS-4 T&T valve, to close Enci itr (td 840203 sent to listed utils GE notified of affected units in BMR
- THERDUX.R R Terry Corp 64/02/22 WDODRUFF.R W Director's Office. Office of Inspection and Enforcement App. 22706 327 24x Fiche 50-000.64/02/22.6403210032

- 8403090280 RO SPR-84-003 on 840206, following trip from 100% power, specific activity sample of reactor coolant showed peak dose equivalent I-131 limit of less than or equal to 1 0 uCi Caused by fuel slement defects in reactor core WILSON, J. L. Virginia Electric & Power Co. 84/02/24 D'REILLY, Region 2. Office of Director 3pp. 22572 141 24X Fichs 50-280,84/02/24,8403090250 D'REILLY, J P
- 8403130424 LER 84-003-00 on 840206, reactor tripped due to low steam generator level w/steam flow/feed flow mismatch in steam generator A Caused by tripped feedwater breaker closing Breaker replaced W/840306 ltr ULSON, J W Virginia Electric & Power Co 84/03/06 G'REILLY, J P Region 2, Office of Director App 22613 131 24X Fiche 50-280,84/03/06,8403130424
- B403140122 Part 21 rept re status update concerning abnormal wear on linear converters Test program undermay Results of investigation indicate excessive wear caused by hunting of control circuitry

 DOBBON.J P Pacific Air Products Co 84/03/09 Director's

 Office, Office of Inspection and Enforcement 7pp 22624 068 24X

 Fiche 50-000.84/03/09.8403140122
- DOCKET 50-28; SURRY POWER STATION, UNIT 2
- F Security, medical, emergency & fire protection plans
- 8400070237 Forwards SALP Repts 50-280/83-33, 50-281/83-35, 50-338/83-33 & 50-339/83-33 for Oct 1982 Aug 1983 Evaluation will be discussed at 831208 meeting at North Anna site LEWIS, R C Division of Project & Resident Programs 83/11/25 STEMART. W L Virginia Electric & Power Co 2pp 22536 227. 24x Fiche 50-000,83/11/25,8403070239
- --B403070246 SALP Repts 50-280/83-33, 50-281/83-35, 50-338/83-33 k 50-339/83-39 for Oct 1982 Aug 1983 Reliable performance w/improvement in most previously noted areas of weakness demonstrated # Region 2, Office of Director 83/11/25 42pp 22536; 229, 24X Fiche 50-000, 83/11/25, 8403070239
- 8401130314 Supplemental info to 801028 application to amend Licenses DPR-31 & DPR-37 re fire pump flow testing Justification for capability of fire pumps to provide adequate fire protection STEWART, W 1. Virginia Electric & Power Co 84/01/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 21798 313 24X Ficha 50-280,84/01/09,8401130314
- 8403280125 Public version of Rev 7 to Emergency Plan Implementing Procedure EPIP-1 01, "Emergency Manager Controlling Procedure " W/B40123 itr & JM Felton 840322 release memo WILBON.J , ORADY.D , STEWART.W L Virginia Electric & Power Co 84/01/13 O'REILLY.J P Region 2, Office of Director 5pp 22811 082 24X Fiche 50-280,84/01/13,8403280125
- 8403070250 Forwards IE Imap Repts 50-280/83-37 & 50-281/83-39 on B31201-31 No violations or deviations identified

 DANCE: H C Division of Project & Resident Programs 84/02/10

 STEWART.W L Virginia Electric & Power Co 2pp 22546 016

 Fiche 50-280:84/02/10:8403070250
- -B403070253 IE Insp Rapts 50-280/B3-37 & 50-281/B3-37 on B31201-31 No violations or deviations identified Major areas inspected operations; plant security, followup of events & LERs, performance appraisal insp findings & surveillance review BURKE.D J Region 2, Office of Director B4/02/09 7pp 22546 018 24% Fiche 50-280,84/02/10.8403070250
- 8403090242 Rev 4 to Emergency Plan Implementing Procedure EPIP-4 23, "Post-Accident Sampling of Reactor Coolant " W/840302 ltr STEWART.W L Virginia Electric & Power Co 64/02/16 O'REILLY, J P Region 2, Office of Director 22pp 22573 228 24X Fiche 50-280,84/02/16.8403090242
- 8403200116 Forwards changes to security personnel training qualification program Changes withheld (ref 10CFR73 21). STEWART:N L. Virginia Electric & Power Co 84/02/17 (Region 2, Office of Director. 1p 22685 335 24X Fiche 50-280:84/02/17:8403200116 O'REILLY, J P
- 8403170263 Rev 1 to corporate emergency response plan W/840315 ltr STEWART, N L. Virginia Electric & Power Co. 84/02/24 O'REILLY, J P Ragion 2, Office of Director. 105pp. 22670'135 24X Fiche 50-000.84/02/24.8403170263.
- 8403060397 Forwards correction to 830217 ltr re revised pages to amergency plan implementing procedures. W/o encl SALYERS,E M Virginia Electric & Power Co. 84/02/29 NRC Detailed Affiliation Given ip 22518 133, 24X Fiche 50-280.84/02/29.8403060397 NRC - No

- B403080264 Forwards "Control Room Design Review Program Plan for North Anna & Burry Power Stations," in response to Suppl 1 to NUREO-0737 Review expected to be completed by 850830 STEMART, W.L. Virginia Electric & Power Co. 84/03/01 DENTON, H.R. Defice of Nuclear Reactor Regulation, Director EISENHUT, D.O. Division of Licensing 2pp. 22557. 295. 24X Fiche 50-000,84/03/01.8403080264
- --B403080269 "Control Room Design Review Program Plan for North Anna & Surry Power Stations," in response to Suppl 1 to NUREO-0737 * Virginia Electric & Power Co B4/03/01 111pp 22557 299 24% Fiche 50-000, 84/03/01.8403080264
- 8403210117 Rev 11 to Emergency Plan Implementing Procedure EPIP-1 01, "Emergency Manager Controlling Procedure" & Rev 6 to Procedure EPIP-2 01, "Notification of State & Local Covts " W/840316 ltr
 - #/040310 its * Virginia Electric & Power Co 84/03/01 O'REILLY, J P Region 2. 0ffice of Director 8pp 22705 067 24X Fiche 50-280,84/03/01. 8403210117
- B403080091 Submits addl info in order to conduct detailed review of emergency response procedures generation package.per B40125 request Items 1 & 2 will be addressed by B40530 Item 3 should be addressed by Westinghouse Course Group STEWART.W L. Virginia Electric & Power Co B4/03/02 DENTON.H R Office of Nuclear Reactor Regulation. Director EISENHUT.D 0 Division of Licensing 2pp 22559 199 24X Fiche 50-000.84/03/02.8403080091
- 8403070151 Revised emergency plan implementing procedures, including Rev 11 to EPIP-1 O1, "Emergency Manager Controlling Procedure" & Rev 6 to EPIP-2 O1, "Notification of State & Local Govts " W/840302 ltr 8ALYERB.E M Virginia Electric & Power Co 84/03/02 6pp 82575 066. 24X Fiche 50-280.84/03/02,8403090151
- 8403160276 Extends invitation to attend 840316 workshop at regional ofc to discuss 10CFR50, App R requirements & results of insps to help resolve misunderstandings associated w/requirements LEWIS, R C Division of Project & Resident Programs 84/03/02 BTEWART.W L. Virginia Electric & Power Co 1p 22660 080 24X Fiche: 50-000, 84/03/02, 8403160276.
- 8403150097 Forwards IE Safeguards Insp Repts 50-280/84-06 & 50-281/84-06 on 840227-0302 No violations or deviations identified DANCE.H C Division of Project & Resident Programs 84/03/09 STEWART.W L Vinginia Electric & Power Co 2pp 22639 300 24X Fichs 50-280,840/30/09.8403150099
- --B403150109 IE Safeguards Insp Repts 50-RB0/B4-06 & 50-281/B4-06 on 840227-0302. No noncompliance noted Major areas inspected security organization/mgt, personnel response records & repts & testing Details withheld (ref 10CFR73 21 & 2 770) ENNIS. J D Region 2, Dffice of Director B4/03/09 1p 22639:302 24X Fichs 30-280, B4/03/09.8403150099
- 8403190052 Informs that local emergency operations facilities at North Anna & Burry Power Stations will be functional, except for data communications & display, by 850731, per NUREG-0737, Suppl 1 BENEVARY, N. I. Vincipi
 - THEMART.W L. Virginia Electric & Power Co. 84/03/14 DENTON, H. R. Office of Nuclear Reactor Regulation, Director EISENHUT, D. O. Division of Licensing 2pp 22666-173 24X Fiche 50-000,84/03/14,8403190052
- 8403230146 Rev 7 to Emergency Plan Implementing Procedure EPIP-2 01. "Notification of State & Local Govts " W/840316 ltr BALYER8.E M Virginia Electric & Power Co 84/03/16 3pp 22730 228 24% Fichs 50-280.84/03/16.8403230146.
- P. Operating license stage documents & correspondence
- 8401130314 Bupplemental info to 801028 application to amend Licenses DRR-31 & DRR-37 re fire pump flow testing Justification for capebility of fire pumps to provide adequate fire protection provided.

 STEMART.W. L. Virginia Electric & Power Co. 84/01/09. DENTON, H.R. Office of Nuclear Reactor Regulation, Director VARGA, 8 A. Operating Reactors Branch 1 2pp 21798 313 24X Fiche. 50-280, 84/01/09, 8401130314
- 8403050230 "Radionuclide Release Under Specific LWR Accident Conditions," Vol V. "PWR-Large,Dry Containment (Surry Recalculations) " OIESEKE,J,A. CYBULSKIS,P., DENNING,R.S. Battelle Memorial Institute, Columbus Laboratories 8403050230 84/01/12 Office of Nuclear Regulatory Research, Diractor 212pp, 22502 001 24X Fiche 50-280,84/01/12,8403050230

- 84030B0339 Final response to FOIA request for documents re NRC investigation of industrial accident involving burst steam pipe at facility "VEPCO Investigative Board Preliminary Rept" on accident placed in PDR FELTON, J M Division of Rules and Records 84/01/20 GARDE, B P Government Accountability Project 1p 22576 214 24X Fiche 50-280,84/01/20,84030B0339
- 8403160269 Confirms 840208 telcon refunctional testing of snubbers Add1 functional testing of Unit 1 snubbers per Tech Spec 4 17 C 6 will be completed during Feb 1984 maint outage Unit 2 testing to be completed during Mar 1984 maint outage LEMIS.R C Division of Project & Resident Programs 84/02/13 STEMART.W L Virginia Electric & Power Co 1p 22660 334 24X Fiche 50-280.84/02/13.8403160269
- 8403020034 Forwards Amends 95 & 94 to Licenses DPR-32 & DPR-37, respectively & safety evaluation Amends revise Tech Specs to change min boron injection tank boron concentration from 11 5% to 0% NEIGHBORS, J D. Operating Reactors Branch 1 84/02/24 STEWART, W L Virginia Electric & Power Co. 2pp. 22491 018 24% Fiche 50-280,84/02/24,8403020054
- --B403020058 Amends 95 & 94 to Licenses DPR-32 & DPR-37, respectively, revising Tech Specs to change min boron injection tank boron concentration from 11 5% to 0% & changing boric acid sysboron concentration from 11 5% to 7% VARGA, S A Operating Reactors Branch 1 84/02/24 18pp 22491 020 24% Fiche 50~280,84/02/24,8403020054
- --8403020061 Safety evaluation supporting Amends 95 & 94 to Licenses DPR-32 & DPR-37, respectively * Office of Nuclear Reactor Regulation, Director 22491 038 24% Fiche 50-280,84/02/24,8403020054
- 8403020195 Forwards addl info to complete review of Topical Rept VEP-FRD-41. "VEPCO Reactor Sys Transient Analysis Using RETRAN Computer Code," in response to NRC Nov 1992 informal request STEWART, W.L. Virginia Electric & Power Co 84/02/27 DENTON, H.R. Office of Nuclear Reactor Regulation, Director EISENHUT, D.G. Division of Licensing 16pp 22443 257 24X Fiche 50-000,84/02/27,8403020195
- 8403050229 Submits review of post-accident sampling sys, Item II B 3 Ten of 11 criteria met Remaining criterion re procedure for estimating extent of core damage based on radionuclide evaluation, acceptable on interim basis
 MILLER.J R Operating Reactors Branch 3 B4/02/27 STEWART, W L Virginia Electric & Power Co 6pp 22528 001 24X
 Fichs 50-000,84/02/27,8403050229
- 8403260105 Supplemental application for amend to Licenses DPR-32 & DPR-37 Suppl reflects change in title of fire marshal to loss prevention supervisor & deletes NDE supervisor STEMART, N L Virginia Electric & Power Co 84/03/22 DENTON, H R Defice of Nuclear Reactor Regulation, Director VARGA, S A Operating Reactors Branch 1 5pp 22758 238 24% Fiche 50-280,84/03/22,8403260105
- --8403260110 Proposed Tech Spec.changing organization title of fire marshal to loss prevention supervisor & deleting NDE supervisor position

 * Virginia Electric & Power Co 84/03/22 2pp 22758 243 24X Fiche 50-280,84/03/22,8403260105
- @ Inspection reports, IE Bulletins & correspondence
- 8403070239 Forwards SALP Repts 50~280/83-33,50~281/83-35,50~338/83-33 & 50~339/83-33 for Oct 1982 Aug 1983 Evaluation will be discussed at 831208 meeting at North Anna site LEWIS,R C Division of Project & Resident Programs 83/11/25 STEWART,W L Virginia Electric & Power Co. 2pp 22536 227 24X Fiche 50~000,83/11/25,8403070239
- --B403070246 SALP Rept* 50-280/83-33,50-281/83-35,50-338/83-33 & 50-339/83-33 for Oct 1982 Aug 1983 Reliable performance w/improvement in most previously noted areas of weakness demonstrated * Region 2, Office of Director 83/11/25 42pp. 22536,229 24X Fiche 50-000,83/11/25,8403070239
- 8403080337 Final response to FOIA request for documents re NRC investigation of industrial accident involving burst steam pips at facility "VEPCO Investigative Board Preliminary Rept" on accident placed in FDR FELTON.J M Division of Rules and Records 84/01/20 GARDE.B P Government Accountability Project 1p 22576 214 24X Fishe 30-280,84/01/20.8403080337.

- --B4030B0341 "VEPCO Investigative Board Preliminary Rept " W/o cover sheet * Virginia Electric & Power Co B4/01/20 29pp 22576 215 24X Fiche 50-280,84/01/20,8403080339
- 8403070250 Forwards IE Insp Repts 50-280/83-37 & 50-281/83-39 on 831201-31 No violations or deviations identified DANCE.H C Division of Project & Resident Programs 84/02/10 STEWART.H L Virginia Electric & Fower Co 2pp 22546 016 24) Fiche 50-280,84/02/10.8403070250
- --B403070253 IE Insp Repts 50-280/83-37 % 50-281/83-39 on 83:201-31 No violations or deviations identified Major areas inspected operations, plant security, followup of events & LERs, performance appraisal insp findings & surveillance review BURKE.D J. DAVISH J. Region 2. Office of Director ELROD, S Division of Project & Resident Programs 84/02/09 7pp 22546 018 24X Fiche 50-280.84/02/10.8403070250
- 8403070279 Discusses SALP evaluation Issuance of SALP rept approved No major weaknesses identified during assessment period at North Anna Che major weakness identified in area of radiological controls at Surry O'REILLY, JP Region 2. Office of Director 84/02/16 STEWART, W L Virginia Electric & Power Co. 2pp 22541 286 24X Ficho 50-000.84/02/16.8403070279
- B403140197 Forwards FR notice & safety evaluations of granting of relief from ASME Section XI inservice requirements, per 790517 & 0928, 801215, 820325 & 0525, 830107, 0307, 0407 & 1227 requests VAROA, S A Operating Reactors Branch 1 84/02/28 STEWART, W L Virginia Electric & Power Co 4pp 22638 073 24X Fichs 50-280, 84/02/28, 8403140199
- --8403140200 Notice of granting of relief from ASME Section XI inservice insp requirements
 VARGA.8 A Operating Reactors Branch 1 84/02/28 2pp 22638 077 24X Fiche 50-280,84/02/28,8403140179.
- --8403140202 Safety evaluation accepting licenses 801215, 820325 & 0525 requests for relief from ABME inservice insp requirements * Uffice of Nuclear Reactor Regulation, Director 84/02/28 16pp 22638 077 24X Fichs 50-280.84/02/28, 8403140179
- --8403140204 Safety evaluation accepting licensee 830107.0307.0414 & 1227 requests for relief from ASME inservice insp requirements * Office of Nuclear Reactor Regulation, Director 84/02/28 18pp 22638 095 24X Fiche 50-280.84/02/28.8403140199
- --B209030161 "Inservice Insp Program," technical evaluation rept * Science Applications, Inc. NRC-03-B2-096 BAI-186-028-20 B2/08/27 NRC - No Detailed Affiliation Given 44pp 22636 113 24X Fiche 50-260.84/02/28.8403140199
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DGT & NRC " Svc list encl GRACE, J N Division of OA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000,84/03/02,8402090007
- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases" Svc list encl JORBAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 119pp 22853 217 24X Fiche 50-000, 84/03/02, 8402090009
- 8403160154 Responds to IE Bulletin 83-08 re electrical circuit breakers w/undervoltage trip feature in use in safety-related applications other than trip sys Only reactor trip breakers contain subj trip attachments SIEMART.W L Virginia Electric & Power Co 84/03/02 D'REILLY, J P Region 2. Office of Director 2pp 22804 008 24X Fichs 50-000.84/03/02.8403160154
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitragen Capling Components Below Nil Ductility Temp " Bvc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 64/03/05. Consolidated Edison Co of New York, Inc 117pp 22353 336 24X Fiche 50-000,84/03/05,8402090011
- 8402090024 IE Info Notice 84-09.Rev 1: "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York Inc 188pp 22635 049 24X Fiche 50-000,84/03/07,8402090024

- 8402070028 IE Info Notice 84-13, "Stress Corrosion Cracking in PWR Sys " Svc list enc! JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22884 186 24X Fiche 50-000,84/03/07,8402070028
- B403150079 Forwards IE Safeguards Insp Repts 30-280/84-04 & 50-281/84-06 on B40227-0302 No violations or deviations identified DANCE, H C Division of Project & Resident Programs B4/03/09 STEWART, W L Virginia Electric & Power Co 2pp 22639 300 24% Fiche 50-280,84/03/09. B403150099
- ---8403150109 IE Safeguards Insp Repts 50-280/84-06 & 50-281/84-06 on 840227-0302 No noncompliance noted Major areas inspected security organization/mgt, personnel response-records & repts & testing Details withheld (ref 100FR73 21 & 2 790) ENNIS, J D. MCOUIRE, D. R. Region 2. (Pfice of Director 84/03/09) tp 22639 302 24X Fiche 50-280,84/03/09,8403150099
- 8402070031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Syc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24% Fiche 50-000.84/03/12,8402090031
- B403270274 Discusses B40210 meeting re util plans, current events, present organizational changes & outstanding regulatory issues Meeting beneficial & provided better understanding of plans O'REILLY, J P Region 2, Office of Director 94/03/19 FERGUSON, J H Virginia Electric & Power Co ip 22814 079 24X Fiche 50-280.84/03/19,8403290274
- 8402090043 IE Info Notice 84-19. "Two Events Involving Unauthorized Entries into PHR Reactor Cavities " Svc list encl JURDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24% Fiche 50-000,84/03/21,8408090043
- 8402090044 IE Info Notice 84-20. "Svc Life of Relays in Safety-Related Sys " Svc list enc! JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 135pp 22933 001 24X Fiche 30-000,84/03/21,8402090044
- 8403270021 Informs that due to addl review required re mat1 supplied by Ray Miller. Inc. util unable to respond to IE Bulletin B3-07 until 1840406

 STEWART. W L Virginia Electric & Power Co 84/03/22 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 1p 22770 068 24% Fiche 80-000, 84/03/22, 8403270021
- 8403290157 Resubmits 840302 response to IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications "Affirmation inadvertently omitted from 840302 ltr encl
 STEWART.W L Virginia Electric & Power Co 84/03/29 O'REILLY, J P Region 2, Office of Director 2pp 22806 006, 24X
 Fiche 50-000.84/03/29,8403290157
- R Periodic operating reports & related correspondence
- B403020053 Forwards operating repts for Jan 1984 & corrected pages of health physics repts for Jul-Dec 1983 STEWART.W L. Virginia Electric & Power Co 84/02/14 HALLER,N M NRC - No Detailed Affiliation Olven ip. 22447 129 24X Fiche 50-280.84/02/14.8403020053
- --8403020059 Monthly operating repts for Jan 1984 WILSONJ, JONES, V H. Virginia Electric & Power Co. 84/01/31 38pp 22447 130 24X Fiche 50-280,84/02/14,8403020053
- --8403020063 Corrected page to health physics rept for monthly operating repts for Nov 1983 * Virginia Electric & Power Co 83/11/30 1p 22447 170 24X Fiche 50-280, 84/02/14,8403020053
- --8403020066 Corrected page to health physics rept for monthly operating repts for Dec 1983

 * Virginia Electric & Power Co. 83/12/31, 1p 22447-171 24X
 Fichs.50-280,84/02/14,8403020053
- --8403020071 Corrected page to health physics rept for monthly operating repts for Jul 1983

 * Virginia Electric & Power Co 83/07/31, 1p 22447 172 24X
 Fichs.50-280,84/02/14,8403020053

- --8403020074 Corrected page to health physics rept for monthly operating repts for Aug 1983 * Virginia Electric & Power Co 83/08/31 1p 22447 173 24X Fiche 50-280,84/02/14,8403020053
- ---B403020085 Corrected page to health physics rept for monthly operating repts for Sept 1983 * Virginia Electric & Power Co 83/09/30 ip 22447 174 24X Fiche 50-280.84/02/14.8403020053
- --8403020070 Corrected page to health physics rept for monthly operating repts for Oct 1983

 * Virginia Electric & Power Co 83/10/31 ip 22447 175 24X
 Fichs 50-280.84/02/14.8403020053
- B400300060 Monthly operating repts for Feb 1984 W/840315 1tr WILBON, J. STEWART, W.L. Virginia Electric & Power Co. B4/02/29 HALLER, N. M. Defice of Resource Management, Director App 28821 113 24X Fiche 50-280,84/02/29,8403300060
- & Reportable occurrences, LERs & related correspondence
- 8305160260 Forwards technical review of rod control urgent failurs on B20625 Caused by blown fuse & failed phase control card in 2 ac power cabinet No generic implications identified TREHAN, N K Reactor Operations Analysis Branch 83/05/05 SEYFRIT.K V Reactor Operations Analysis Branch 2pp 22809 285 24X Fiche 50-281,83/05/05,8305160260
- --8403280121 "Rod Control Urgent Failure on 830625 at Surry Unit 2." NOSEDIE: NO CONTROL OF STATE THE TREHAN, N Director's Office Sifiche.50-281,83/05/05.8305160260 83/05/05 ip 22809 286 24X
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines, Oimpel NPS-4 T&T valve, to close Encl ltr dtd 840203 sent to listed utils GE notified of affected units in BWR plants THEROUX, R R 84/02/22 WOODRUFF, R W THEROUX,R R Terry Corp 84/02/22 HOODRUFF Office, Office of Inspection and Enforcement Fiche 50-000,84/02/22,8403210032 брр 22706 327
- B403140122 Part 21 rept re status update concerning abnormal wear on linear converters Test program underway Results of investigation indicate excessive wear caused by hunting of Control circuitry,
 DOBBON, J.P. Pacific Air Products Co. 84/03/07 Director's
 Office, Office of Inspection and Enforcement 7pp. 22624 068
 Fiche 50-000.84/03/09/8403140122
- DOCKET 50-282 PRAIRIE ISLAND NUCLEAR STATION, UNIT 1
- F Security, medical, emergency & fire protection plans
- 9403090270 Public varsion of revised emergency response nlan t03090270 Public version of revised emargency response plan implementing procedures, including Procedure FG-2 reclassification of smergencies, F3-5 re emergency notification & F3-10 re personnel accountability W/631217 itr & memo MENDELE, DJ, JOHNSON, JM Northern States Power Co 83/10/28 168pp 22595 326 24X Fiche 50-282,83/10/28,8403090270.
- B403070207 Revised emergency implementing procedures, including Rev 25 to Procedure F3, "Table of Contents" & Rev 3 to Procedure F3-8, "Recommendations for Offsite Protective Actions " W/840302 1tr FEY, F.L. Northern States Power Co 24X Fiche 50-282,84/02/24,8403090207 84/02/24 28pp 22574 328
- 8403170020 Forwards IE Insp Repts 50-282/83-24 & 50-306/83-24 on 831211-840210, No noncompliance identified 8HAFER, W D Region 3. Diffice of Director, 84/03/01 LARSON, C. E Northern States Power Co 2pp 22666, 053 24X Fiche 50-282, 84/03/01, 8403190020
- --8403190042 IE Insp Repts 50-282/83-24 & 50-306/83-24 on 831211-840210 No noncompliance or deviations identified Major areas inspected mainti-ERs, emergency planning & surveillance, meetings w/state & local officials & IE bulletins HARD, J E , FEIERABEND, C D , HARTMANN, P L Region 3, Office of Director, 84/02/29 12pp. 22666 055 24X Fiche 50-282,84/03/01,8403190020
- 8403130163 Forwards final rept re small-scale offsite radiological amergency preparedness exercise on 821014 No deficiencies noted RRIMM,R W Federal Emergency Management Agency 84/03/05 JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 6pp 22579 307. 24X Fiche 50-282,84/03/05, 8403130163

- ---B403130172 Final rept of small-scale joint emergency exercise on **B21014** Federal Emergency Management Agency 82/12/1; 599 313 24x Fiche 50-282,84/03/05,8403130163 82/12/17
- 8403120106 Notifies of 840323 workshop on fire protection safe shutdown requirements of 10CFRDO.App R in Rosemont, IL to discuss IE Info Notice 84-09 & provide addl shutdown analyses %/or mod guidance Agenda encl SPESSARD.R L Division of Emergency Preparedness & Operational Support 84/03/06 LARBON.C E Northern States Power Co 3p 22588 169 24X Fiche 50-202.84/03/06.8403120106
- 8403300130 Revised emargency plan implementing procedures, including Procedure F3 re table of contents & F3-13 re offsite dose calculation W/840320 transmittal ltr
 MATTLE FEY.F 1. Northern States Power Cp 84/03/09 34pp 228
- I Financial information
- 8403290i15 Suppl to Annual Financial Rept 1983.consisting of financial & statistical info W/840326 ltr
 BRUSVEN,A D Northern States Fower Co 83/12/31 23pp 22806 182 24X Fiche 50-000,83/12/31,8403290115
- P Operating license stage documents & correspondence
- B40305023B Forwards Amends 68 & 62 to Licenses DFR-42 & DFR-60, respectively & safety evaluation Amends revise Tech Specs resemengency air treatment sys & electric hydrogen recombiners DIIANNI, D C Operating Reactors Branch 3 84/02/21 MUSGLF, D M Northern States Power Co 2pp 22527 188 24X Fiche 50-282,84/02/21,8403050238
- ---8403050243 Amends 48 % 42 to Licenses DPR-42 & DPR-60, respectively. NONDOUGHS Amends AB & A2 to Licenses unrang & unrand, respectively first pecture of the property of the second iners are treatment sys & electric hydrogen recombiners MILLER, JR Operating Reactors Branch 3 84/02/21 18pp 22527 190 24X Fiche 50-282, 84/02/21, 8403050238
- --8403050249 Safety evaluation supporting Amends 68 & 62 to Licenses DPR-42 & DPR-60 respectively * Office of Nuclear Reactor Regulation, Director 84/02/21 7; 22527 208 24X Fiche 50-282,84/02/21,8403050238
- 8403040428 Submits fees requested for 820630 exemption request, in response to NRC 840213 ltr MUSCLF.D Northern States Power Co 84/02/29 MILLER, W O Licens Fee Management Branch 2pp 22518 200 24% Fiche 50-282.84/02/29.84
- 8403130245 Forwards "Effluent & Waste Disposal Semiannual Rept. Jul-Dec 1931/0245 Forwards "Efficient waste Disposal Semiannual Rept. 1913" & Rev 4 to "Offsite Dose Calculation Dose Assessment, 1983" & Rev 4 to "Offsite Dose Calculation Manual "
 FEY,F L Northern States Power Co 84/03/01 Region 3, Offit Director 1p 22610 143 24X Fiche 50-282,84/03/01,8403130245 Region 3. Office of
- --8403130278 Rev 4 to "Offsite Dose Calculation Manual '
 BURENBON, J Northern States Power Co 84/11/14 1
 22610 157 24X Fiche 50-282,84/03/01.8403130245
- 8403150270 Forwards safety evaluation re error in COURA HITC/MIT computer code, previously accepted by NRC 830217 & 0324 ltrs, for use in analyzing fuel reloads Error does not create any substantial safety hazard MILLER, J R Operating Reactors Branch 3 84/03/06 MUSOLF, D M Northern States Power Co 1p 22647 333 24X Fiche 50-282, 84/03/06, 8403150270
- --B403150293 Bafety evaluation re error in COBRA IIIC/MIT computer code reload methodology rept NSPNAD-8102 Error has not affected initial findings or conclusions re acceptability of use of COBRA IIIC/MIT code * NRC - No Detailed Affiliation Given 84/03/06 22649 334 24X Fiche 50-282,84/03/06,8403150290
- 8403190397 Provides updated info re mods required by NUREG-0797. Item II D i 2 re safety & relief valve performance. Unit 1 piping & supports will be installed during next refueling outage a supports will de installed during that retreating of scheduled for 850105
 MUSDLF, D Northern States Power Co 84/03/14 0
 Reactor Regulation, Director 1p 22675 192 24X
 Fichs 50-282.84/03/14.8403190397

- 8403230031 Submits status of mods to improve adequacy of station distribution sys voltages, per util 810717 ltr & NRC 821029 SER All mods completed, w/exception of changes to station air compresser starting circuit.

 MUSDLF, D. Northern States Power Co. 84/03/16 Office of Nuclear Reactor Regulation, Director 2pp 22724 346 24X Fiche 50-282,84/03/16,8403230051
- G Inspection reports, IE Bulletins & correspondence
- 8403050223 Further response to FOIA request for records of named individuals, including repts, analyses, studies, test calculations, procedures & practices for measurement of RCB leakage Forwards App C documents Search continuing FELTON, J M Division of Rules and Records 84/02/07 MADDEN, T J Raye, Scholer, Fierman, Hays & Handler 3pp 22496 234 24X Fiche 50-000,84/02/07.8403050223
- --8403050256 Notifies that independent measurements of identified & unidentified RCS leak rates for all PMRs in Region III performed per Procedures 617278 & 617280 Insp findings summarized NORELIUS.C E Division of Engineering 82/03/00 JORDAN.E L Division of Engineering & Quality Assurance (Pre 830103) 2pp 22496:270 24X Fiche 50-000.84/02/07.8403050283.
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22907 239 24X Fiche 50-000.84/02/28,8401190072
- 8403190020 Forwards IE Insp Repts 50-282/83-24 & 50-306/83-24 on B31211-840210 No noncompliance identified SHAFER, W D Region 3, Dffice of Director, B4/03/01 LARSON, C E Northern States Power Co 2pp 22666 053 24X Fichs 50-282,84/03/01,8403190020
- --8403190042 IE Insp Repts 50-282/83-24 & 50-306/83-24 on 831211-840210 No noncompliance or deviations identified Major areas inspected maint. LERs. emergency planning & surveillance, meetings W/state & local officials & IE bulletins HARD. J E . FEIERABEND. C D . HARTMANN.P L Region G, Office of Director 84/02/29 12pp 22666 055 24X Fiche 50-282,84/03/01,8403190020
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE.J N Division of QA, Safeguards & Inspection Programs (Post 830103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fichs, 50-000,84/03/02,8402090007
- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24% Fiche 50-000,84/03/02,8402090008
- 8402090009 IE Info Notice B4-15. "Reporting of Radiological Releases" Svc list encl
 JORDAN, E. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc 119pp 22553 217 24X Fiche 90-000,84/03/02,8402090009
- 8402090011 IE Info Notice 84-17. "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp. 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 6402070024 IE Info Notice 84-09, Rev 1, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list enci JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24% Fiche 50-000, 84/03/07, 8402090024
- B402070028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR 8ys " Byc list enci, JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402070028
- B4031903BB Forwards summary of status of requests for relief from requirements of Section XI of ASME Boiler & Pressure Vessel Code for inservice (hep program & clarification of items that require add) review MUSQLF, D. Northern Btates Power Co. 84/03/09. Office of Nuclear Reactor Regulation, Director 9pp 22675.295 24X Fichs 50-282,84/03/09.8403190388

- 8402070031 IE Bulletin 84-02. "Failures of QE Type HFA Relays in Use in Class IE Safety Sys " Svc list uncl DEYGUNG.R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 28823 094 24% Fiche 50-000.84/03/12.8402090031
- 8403190200 Responds to IE Bulletin 83-07 re products supplied by Ray Miller, Inc Neither unit received products from Ray Miller. Inc & vendor not on approved util vendor 11st
 LARBUN-C E Northern States Power Co 84/03/12 DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 4pp 22671 105 24% Fiche 50-282,84/03/12,8403190200
- 8403300036 Forwards IE Insp Repts 50-282/84-02 & 50-306/84-02 on 840215-17 No noncompliance noted PAPERIELLD.C J Region 3. Office of Director 84/03/15 LARSON.C E Northern States Power Co 2pp. 22821 320 24X Fiche 50-282.84/03/15.8403300036
- --8403300040 IE Insp Repts 50-282/84-02 & 50-306/84-02 on 840215-17. No violations or deviations identified Major areas inspected, implementation of 10CFR20 & 60 requirements for disposal of low level radwastes, including mgt controls & 60 R0ZAK, S. DESTHANN, M.J. BCHUMACHER, M.C. Region 3, Office of Director 84/03/15 5pp. 22821.322 24X Fiche 50-282,84/03/15,8403300036
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" 8vc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 123pp 22823 229 24X Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys "Svc list encl JORDAN.E.L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001. 24X Fiche 50-000,84/03/21,8402090044
- B403270170 Forwards "Inservice Insp Exam Summary, 831204-23 " Rept identifies components examined, exam methods used, exam number & summarizes results Results indicated that integrity of sys maintained MUSCLF, D. Northern States Power Co. 84/03/23 Dffice of Nuclear Results indicated Power Regulation, Director 2pp 22771 144 24X Fiche 50-282,84/03/23,8403270170
- ---8403270181 "Inservice Insp Exam Summary.831204-23 "
 ANDERSON. H T , KRUMPOS, P J Northern States Power Co. 84/03/15
 150pp 22771 146 24X Fiche.50-282.84/03/23.8403270170
- R Pariodic operating reports & related correspondence
- 8403300095 Honthly operating repts for Feb 1984 M/840306 1tr DUGSTAD, D. HUSCLF, D. Northern States Power Co. 84/02/29 9pp 24047.060 24X Fichs 50-282,84/02/29,8403300095
- 8403130245 Forwards "Effluent & Waste Disposal Semiannual Rept, Jul-Dec 1983," "Offsite Radiation Bose Assessment, 1983" & Rey 4 to "Offsite Dose Calculation Manual " FEY,F.L. Northern States Power Co 84/03/01 Region 3, Office of Director ip 22610 143 24X Fiche 50-282, 84/03/01, 8403130245
- --8403130258 "Effluent & Waste Disposal Semiannual Rept, Jul-Dec 1983 "
 * Northern States Power Co 83/12/31 9pp 22610.144, 24X
 Fichs 50-282,84/03/01.8403130245
- ---8403130270 "Offsite Radiation Dose Assessment, 1983, "

 * Northern States Power Co 83/12/31 4pp 22410 153 24X Fiche 50-282, 84/03/01, 8403130245.
- --8403130278 Rev 4 to "Offsite Dose Calculation Manual " BORENSON.J Northern States Fower Co 84/11/14, 11pp. 22610 157. 24X Fiche 50-282,84/03/01.8403130245
- B Reportable occurrences, LERs & related correspondence
- 8211220029 Discusses problems associated w/diesel generator surveillance tests, as demonstrated in 820827 testing of diesel generator D-2 Mispositioning of auto/manual switch could render sys unable to perform design function CHIRAMAL, M. Reactor Operations Analysis Branch. 82/11/17. BEYFRIT. K.V. Reactor Operations Analysis Branch. 2pp. 22775 165 24X Fiche: 50-282, 82/11/17, 8211220029

;

- DOCKET 50-285 FORT CALHOUN STATION, UNIT 1
- F Security, medical, emergency & fire protection plans
- B403050099 Requests that transmittal sheets confirming receipt of revised emergency plan implementing procedures be returned within 5 days of receipt JONES. WC Comaha Public Power District B3/06/02 COLLINS, J T Region 4. Office of Director 1p 22485 241 24x fichs 50-285, 83/06/02, 8403050099
- B403280165 Forwards public version of revised emergency plan implementing procedures W/o procedures W/JM Felton 840322 implementing procedures W/o procedures W/on retion and service release memo JONES, W C Omaha Public Power District 84/01/10 COLLINS, J T Region 4, Office of Director 2pp 22809 290 24X Fichs 50-285, 84/01/10,8403280165
- 8403280193 Forwards public version of changes to radiological emergency response plan W/o changes W/JM Felton 840322 release memo JONES.W C Dmaha Public Power District 84/01/10 COLLINS.J T Region 4. Office of Director 2pp 22789:340 24X Fiche 50-285.84/01/10,8403280193
- 8403050138 Submits scenario for providing emergency preparedness info, per NRC 820114 ltr & revised emergency preparedness rule published 800819 COLLING.J.T. Region 4, Office of Director 84/02/09 JONES, W C Omaha Public Power District 2pp 22490 001 24X Fiche 50-285, 84/02/09, 8403050138
- B403060512 Forwards order confirming util commitments on emergency response capability, per Generic Ltr 82-33 Order based on commitment contained in util 830415 Itr W/o encl MILLER, J R Operating Reactors Branch 3 84/02/22 JONES, W C Omea Public Power District ip 22552 164 24X Fiche 50-285, 84/02/22, 8403060512
- 8403120062 Revs to emergency plan implementing procedures, including OBC-6. "General Emergency Actions," OBC-12, "Accidental Actuation of Early Warning Siren Sys" & OBC-14, "Emergency Duty Actions " W/840301 transmittal & receipt form # Omaha Public Power District 84/03/01 39pp 22591 031 24X Fiche 50-285,84/03/01,8403120062
- 8403170154 Forwards changes to emergency plan implementing procedures H/o encl

 JONES, W C. Omaha Public Power District 84/03/05 COLLINS, J T
 Region 4, Office of Director ip 22668 345 24X
 Fiche 50-285, 84/03/05, 8403190154
- B403070204 Revised radiological emergency response plan procedures; including Procedures R5, "Notification Methods & Procedures" & R2, "Radiological Exposure Control " W/840306 ltr JONES, W C Omaha Public Power District 84/03/06 COLLINS, J T Region 4, Office of Director 59pp 22572 227 24x Fiche 50-285,84/03/06.8403090234
- P Operating license stage documents & correspondence
- 8402170136 Forwards application for amend to License DPR-40, changing Tach Base Sections 1 1,1 3,2 1 1,2 1 2,2 3,2,10 2 & Tables 1-1,2-2,3-1 & 3-5, to eliminate requirement to inspect fuel elements removed from vessel each refueling a LaBosuf, Lamb, Leiby & MacRae * Omaha Public Power District 84/02/14, DENTON, H Office of Nuclear Reactor Regulation, Director 3pp. 22299:146 24X Fiche 50-285,84/02/14,8402170156
- --8402170166 Application for amend to License DPR-40, changing Tech Spec Bections 1 i.i.3, 2 i.i.2.i.2,2 3,2 10 2 & 2 10 4 & Tables i-1,2-2,3-1 & 3-5 to eliminate requirements to inspect fuel elements removed from vessel each refueling JONES W. C Ommha Public Power District 84/02/07 2pp 22299:149 24X Fiche 50-285,84/02/14,8402170156
- --8402170176 Proposed Tech Specs 1 1.1 3,2.1.1.2 1.2.2 3,2 10 2 & Tables 1-1,2-2,3-1 & 3-5. eliminating requirement to inspect fuel elements removed from vessel each refueling # Omeha Public Power District 84/02/09 140pp 22299 151 24X Fiche 50-285.84/02/14,8402170156
- B403010312 Forwards proprietary & nonproprietary add1 info restatistical combination of uncertainties rept, per 840213 request. Application for withholding & C-E affidavit encl Proprietary info withheld (ref 10CFR2 790)

 JONES, W. C. Omeha Public Power District 94/02/24 MILLER, Operating Reactors Branch 3 20pp. 22432 283 24X

 Fiche. 50-285, 84/02/24, 8403010312 24 MILLER, J R 24X

- 8403060396 Responds to Generic Ltr 84-01 re use of terms important to safety & safety-related Steering Committee of Util Safety Classification Group will represent util in further Classification or say 3...

 discussions

 JONES, W C Omaha Public Power District 84/02/29 TAYLOR, J M

 Director's Office, Office of Inspection and Enforcement ip

 22518 132 24X Fiche 50-285, 84/02/29, 8403040394
- 8403120183 Forwards application for amend to License DPR-40, revising Tech Specs to add limiting conditions for operation, surveillance requirements & administrative requirements, per
 - /REG-0737 LeBoguf, Lamb, Leiby & MacRae * Omaha Public Power District 1/03/09 DENTON.H Office of Nuclear Reactor Regulation, Director 3pp 22585 200 24% Fiche 50-285,84/03/09,8403120183 84/03/09
- --B403120192 Application for amend to License DPR-40, revising Tech Specs to add limiting conditions for operation, surveillance requirements & administrative requirements, per NUREG-0737 JUNEB. W C Dmaha Public Power District B4/03/08 2pp 22585 203 24% Fiche 50-285.84/03/09,8403120183
- --9403120195 Proposed Tech Speca re limiting conditions for operation, surveillance requirements & administrative requirements * Omaha Public Power District 84/03/09 14pp 22585 205 24X Ficha 50-285,84/03/09.8403120183
- 8403130458 Forwards schedule for addi submittal of radiological effluent Tech Specs based on results of 790330 assessment & manpower requirements for 1984 refeveling outage Next submittal will resoive remaining issues

 JONES.W C Omaha Public Power District 84/03/09 MILLER, J R Operating Reactors Branch 3 2pp 22613 332 24X

 Fithe 50-265.84/03/09.8403130458
- 8403280183 Forwards request for add1 info re 840214 request concerning Cycle 9 operation Response requested within 30 days of ltr receipt in order to maintain review schedule W/o encl MILLER, J R Operating Reactors Branch 3 84/03/12 JONES, W C Omaha Public Power District 1p 22809 289 24X Fiche 50~285,84/03/12,8403280183
- G Inspection reports, IE Bulletins & correspondence
- 8403260168 Forwards IE Insp Rept 50-285/83-36 on 831212-14 No violations or deviations noted 6AGLIARDD, J E Region 4. Office of Director 84/01/19 JONES, W C Omaha Public Power District 2pp 22757 336 24X Fiche 50-285,84/01/19,8403260168
- --8403260172 IE Insp Rept 50-285/83-36 on 831212-14 No violations or deviations noted Major areas inspected transportation & solid radwaste program including mgt controls selection of packages delivery of packages & records & repts HOLLEY, W. L., MURRAY, B., JOHNSON, W. D. Region 4. Office of Director 84/01/12 5pp 22757 338 24X Fiche 50-285.84/01/19,8403260168
- B402210338 Forwards SALP Rept 50-285/83-28 for Sept 1982 Aug 1983 Overall performance satisfactory COLLINS.J T Region 4, Office of Director 84/02/10 JONES.W C Omaha Public Power District 2pp 22346 238 24X Fichs 50-285.84/02/10.8402210338
- --8402210343 Forwards SALP Rept 50-285/83-28 for Sept 1982 Aug 1983 GAGLIARDD, J E Region 4. Office of Director B3/12/2 44 JONES, W C Omaha Public Power District 4pp 22346 24X Fiche 50-285, 84/02/10, 8402210338
- --B40221034B BALP Rept 50-285/B3-28 for Sept 1982 Aug 1983 No noncompliance noted Major areas inspected mgt involvement in assuring quality, approach to resolution of technical issues & responsiveness to NRC initiatives JOHNSON, W D , GAGLIARDD, J E Region 4, Office of Director B3/12/13 42pp 22346 244 24X Fiche 50-285.84/02/10,8402210338
- --8310060317 Forwards evaluation of LERs for Sept 1982 Aug 1983 Util LERs among best reviewed BEYFRIT.K V Reactor Operations Analysis Branch 83/09/28 SEIDLE.W C Division of Resident. Reactor Project & Engineering Programs 4pp 22346.286 24X Fiche 50-285.84/02/10.8402210338
- --8402210357 Forwards responses to SALP Rept 50-285/83-28 ALARA program under review to improve effectiveness Radwaste coordinator position will be created Internal audit program JONES, W C Omaha Public Power District 84/01/10 G Region 4, Office of Director 12pp 22344 290 24X Ficha 30-285,84/02/10,8402210338 GAGLIARDO, J E

- 8402170136 Forwards application for amend to License DFR-40, changing Tech Spec Sections i 1.1 3.2 1 1.2 1 2.2 3.2.10 2 & Tables i-1.2-2.3-1 & 3-5, to eliminate requirement to inspect fuel elements removed from vestel each refueling * LeBosuf, Lamb. Leiby & MacRae * Omaha Public Power District 64/02/14 DENTON, H Office of Nuclear Reactor Regulation. Director 3pp 22299 146 24X Fiche 50-285.84/02/14.8402170136
- --8402170166 Application for amend to License DPR-40 changing Tech Spec Sections 1 1.1 3.2 1 1.2 1 2.2 3.2 10 2 & 2 10 4 & Tables 1-1.2-2.3-1 & 3-5 to eliminate requirements to inspect fuel elements removed from vessel each refueling JONES. W C Omaha Public Power District 84/02/07 2pp. 22279 147 24X Fiche 50-285,84/02/14.8402170156
- --8402170176 Proposed Tech Specs 1 1.1 3.2 1 1.2 1 2.2 3.2 10 2 & Tables 1-1.2-2.3-1 & 3-5.eliminating requirement to inspect fuel elements removed from vessel each refueling * Omaha Public Power District 84/02/09 140pp 22299 151. 24X Fiche 50-285.84/02/14.8402170156
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list enc!

 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 1135p 22707 237 24X Fitchs 30-000.84/02/28, 8401190072
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Fransport Regulatory Revs by DOT & NRC." Svc list encl ORACE.J N Division of GA. Safeguards & Inspection Programs (Post 830103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000,84/03/02,8402090007.
- B402090008 IE info Notice 84-14, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl. JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Fost 830103) 84/03/02 Consolidated Edison Co. of New York: Inc. 122pp 22553 098 24X Fiche 50-000.84/03/02,8402090008
- B402090009 IE Info Notice B4-15. "Reporting of Radiological Releases" Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/02 Consolidated Edison Co of New York, Inc 119ρp 22953 217 24X Fiche 50-000,84/03/02.8402090009
- 8402070011 IE Info Notice 84-17. "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York. Inc 117pp 22553 336 24X Fiche 50-000.84/03/05.8402070011
- B403120147 Submits tabulation of comparative analysis results of unknown liquid sample Results will appear in next confirmatory measurements inspired Criteria for comparing analytical measurements enct GAGLIARDO.JE Region 4. Office of Director B4/03/06 JONES.W C Omaha Public Power District 3pp 22585 254 24X Fiche 50-285.84/03/06.8403120147
- 8402090024 IE Info Notice 84-09, flev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN, Et alvision of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp. 22635 049, 24X Fiche 50-000, 84/03/07, 8402090024
- 8402090028 IE Jnfo Notice 84-18. "Stress Corrosion Cracking in PWR Bys " Byc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402070028
- 8403190057 Ack receipt of 840203 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-285/83-31 Implementation of corrective actions will be reviewed during future insp GAGLIARDO. J E Region 4. Office of Director 84/03/08 JONES, W C Omaha Public Power District ip 22666 128 24% Fiche 50-285,84/03/08,8403190057
- --8403190061 Responds to NRC 840105 ltr re violations noted in IE Insp. Rept 50-285/83-31.Corrective actions weekly review of radiation work permits discontinued in Favor of deily, weekly, monthly & special surveys of radiological conditions JONES, W.C. Omaha Public Power District 84/02/03 DENIBE, R.P. Division of Resident, Reactor Project & Engineering Programs 3pp. 22666-127 24X Fiche 50-285,84/03/08,8403190057

- 8403130200 Forwards response to IE Bulletin 80-11, "Masonry Wall Design," per 840206 request Damping values of 2% for DBE & 4% SSE used for unreinforced masonry walls JUNES, W C Omaha Public Fower District 84/03/09 MILLER, J R Operating Reactors Branch 3 9pp 22613 079 24% Fiche 50-285,84/03/09,8403130200
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl DEYGUNG.R C Director's Office, Office of Inspection and Enforcement 84/03/12 Cansolidated Edison Co of New York, Inc 134pp 22823 094 24% Fichs 50-000.84/03/12.8402090031
- 8403190279 Ack receipt of 840214 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-285/83-30 GAGLIARDO.J E Region 4, Office of Director 84/03/13 JONES.W C Damaha Public Power District 1p Fiche 50-285.84/03/13.8403190279
- --8403170281 Responds to 840123 telcon re violations noted in IE Insp. Rept 50-285/83-30 Corrective actions. Engineering Evaluation/Assistance Request FC-84-08 initiated on 840116 to upgrade decontamination facility.including shower, stall & plumbing JONES.W. C. Omaha Public Power District 84/02/14 DENISE.R. P. Division of Resident, Reactor Project & Engineering Programs 2pp 22672 030 24X Fiche 50-285.84/03/13.8403190279
- 6403270249 Forwards replacement Pages 1.7.8.23.29 & 50 to 1983-1993 inservice insp program plan dtd 830926 Reasons & justification for changes & exemptions listed JONES.W C Omaha Public Power District 84/03/19 MILLER.J R Operating Reactors Granch 3 2pp 22772 105 24X Fiche 50-285.84/03/19.8403270249
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fichs 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044
- R Periodic operating reports & related correspondence
- B402050135 "Annual Rept for Tech Spec Section 5 9 1 0,1983" & "Bemiannual Rept for Tech Spec Section 5 9 4,Jul-Dec 1983," W/840301 ltr JONES, W C Omaha Public Power District 83/12/31 200pp 22489 172 24X Fichs 50-285,83/12/31,8403050135
- B403200176 Monthly operating rept for Feb 1984 W/840313 itr MATHEWRIT P , JONES W C Omaha Public Power District 84/02/27 DEYOUNG!R C Director's Office Office of Inspection and Enforcement 10pp 22699 327 24X Fiche 50-285,84/02/29,
- 8 Reportable occurrences, LERs & related correspondence
- 8403030124 LER 84-001-00 on 840122, crane supervisor left spent fuel pool area while key still in interlock bypass switch in hypassed position, contrary to Tech Spec 2 11(2) Caused by personnel error Event discussed w/Individual W/840222 ltr RICHARD, A W. JONES, W. C. Omaha Public Power District 84/02/22, 3pp 22489 162 24X Fichs 50-285, 84/02/22, 8403050124
- DOCKET 50-284 INDIAN POINT STATION, UNIT 3

 F Security, medical, emergency & fire protection plans
- B403020171 Forwards order confirming util commitments to implement requirements of Suppl 1 to NUREG-0737 Order based on B30418 & OB23 Itrs in response to Generic itr 82-33 VARGA.S A Operating Reactors Branch 1 B4/02/21 BAYNE, J P Power Authority of the State of New York 4pp 22491 091 24X Fiche 50-286.84/02/21.8403020171
- --8403020175 Order confirming licensee 830418 & 0823 commitments on emergency response capability per requirements of Suppl 1 to NUREO-0737 & Generic Ltr 83-33 EISENHUT, D G Division of Licensing 84/02/21 Power Authority of the State of New York 6pp 22491 095 24X Fiche 50-286,84/02/21,8403020171

95

DOCKETED ITEMS

- 8403020352 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee.per 810709 Generic Ltr 81-27 W/o request, entire plan will be placed in PDR POLK, PJ Operating Reactors Branch 1 84/02/21 BAYNE, JP Power
 - POLK,P J Operating Reactors Branch 1 84/02/21 BAYNE,J P Power Authority of the State of New York 3pp 22472 222 24X
 Fiche 50-286,84/02/21,8403020352
- 8403020333 Forwards IE Insp Rept 50-286/84-01 on 840109-11 No violations noted MARTIN, T T Division of Engineering & Technical Programs 84/02/21 BRONB, J C. Power Authority of the State of New York 2pp 22439 023 24X Ficha 50-286,84/02/21,8403020353
- --8403020357 IE Insp Rept 50-286/84-01 on 840109-11 No violations noted Major areas inspected public prompt notification sys MUJNAS,E J. CROCKER,H W Region 1. Defice of Director 84/02/17 Spp. 22439 025 24X Fiche 50-286,84/02/21,8403020353
- 8402090006 Board Notification 84-034 forwards R Vollmer 840206 memo to D Eisenhut re fire research results concerning fires in electrical cabinets in control room EIBENHUT. D.O Division of Licensing 84/02/23 PALLADING Commissioners ip 22576 203 24X Fiche 50-000,84/02/23, 88030-0000
- --8403080316 Recommends that info re fire research results concerning fires in electrical cabinets in control room be submitted for board motification, per NRR Ofc Ltr 19, dtd 821001 Further evaluation af test data required VOLLMER, R H Division of Engineering 84/02/06 EISENHUT, D 0 Division of Licensing 10pp 22576 204 24X Fiche 50-000,84/02/23,8402090006
- 84030902ii Revised emergency plan procedures, including Procedures IP-101i re offsite monitoring IP-102i re radiological medical emergency & IP-1063 re vehicle/equipment radiological check & decontamination W/840308 ltr power Authority of the State of New York 84/03/05 43pp 2275:001 24X Fiche 30-286,84/03/05.8403090211
- 8403130162 Forwards remaining fee for review of Rev 8 to physical security plan.per 10CFR170 22 Review interpreted as Class II fee Remittance paid under protest pending final determination of legality of fee schedule 8AYNE,JP Power Authority of the State of New York 84/03/05 B10GSR M License Fee Management Branch 2pp 22615 214 24) Fiche 30-286:84/03/05.8403130162
- B403190243 Notification of 840418 workshop in King of Prussia PA to discuss lessons learned from recent App R fire protection safe shutdown insp & topics described in IE Info Notice B4-07 Agenda for workshop encl.

 MURLEY, T. E. Region i, Office of Director 84/03/07 D'TOOLE, J D Consolidated Edison Co of New York. Inc CAREY, J J Duquesne Light Co. MARTIN, T J Public Service Electric & Gas Co of New Jersey 35pp 22672 062 24X Fiche 50-000, 84/03/09, 8403170243.
- 8403190258 Ack receipt of 840214 ltr informing NRC of steps taken to correct violations noted in 16 Emergency Preparedness Appraisal Rept 50-286/81-05
 MARTIN.T T. Division of Engineering & Technical Programs 84/03/13
 BRONS.J C Power Authority of the State of New York 2pp 22672 221 24% Fiche 50-286/84/03/13.8403190258
- --B403190263 Responds to NRC B11119 ltr re violations noted in IE Emergency Preparedness Appraisal Rept 50-286/81-05 Corrective actions post-accident instrumentation & sampling requirements per NUREG-0737 & Reg Quide 1.97 implemented BRONS, J C Power Authority of the State of New York B4/02/14 MARTIN, T T Division of Engineering & Technical Programs 2pp 22672 223. 24X Fiche, 50-286, 84/03/13, 8403190258
- 8403190276 Responds to 840208 request for info re emergency operations facility (EDF), specifically preliminary cost estimate for upgrade to overall radiation protection factor of five Existing EDF meets Suppl 1 to NUREG-0737 requirements BAYNE, J P Consolidated Edison Co of New York, Inc 84/03/14 VARGA'S, A. Operating Reactors Branch 1 2pp 22674 354 24X Fiche 50-286,84/03/14,8403190276

H General correspondence

8403010170 Forwards Resolution 76 authorizing County participation in four-county radiological planning task force & authorizing use of County employees for radiological emergency response pregaradness Implementation requested W/Certificate of Svc SEIGERMAN, V K Rockland County, NY 84/02/15 PALLADING, N Commissioners 3pp 22435 307 24% Fiche 50-247,84/02/15.

J Insurance & indemnity information

- 8403260197 Forwards Endorsement 4B to NELIA Policy NF-236, Endorsements 69 & 72 to NELIA Policy NF-20B, Endorsement 97 to MAELU Policy MF-77 & Endorsement 67 to NELIA Policy NF-230 GOLDEN, M P Marsh & McLennan, Inc B4/03/12 SALTZMAN, J Assistant Director for State & Licensee Relations 6pp 22751 033 24X Fiche 50-000,84/03/12.8403260197
- D Advisory Committee on Reactor Safeguards reports & correspondence
- B403050020 Responds to FDIA request for documents re PASNY submittal on sys interactions, repts evaluating submittal & list of repts/analyses from LLL evaluating PASNY sys interaction program Forwards App A documents
 FELTON, J M Division of Rules and Records 83/12/07 SHOLLY, 8 Union of Concerned Scientists App 22525 078 24x
 Fiche 50-000.83/12/07.8403080020
- --7912030323 Requests comments on 791012 ACRS ltr re sys interaction
 Plans inhouse merting for 791113
 SCHWENCER, A Operating Reactors Branch 1 (Pre 800428) 79/11/09
 HANAUER, S Assistant Director for Plant Systems ZECH, O
 Division of Operating Reactors GAMMILL, W Assistant Director for
 Operating Reactor Projects (Pre 791030) 1p 22527 146 24X
 Fiche 50-000,83/12/07,8403050020
- ~-B208070297 Provides status rept on NRC evaluation of licenses sys interaction study Initial guidance delayed pending further cost/benefit analysis Generic program review planned for Fall 1982 GOODWIN.E F Technical Support Branch B2/07/30 FRALEY.R F ACRS - Advisory Committee on Reactor Safeguards 2pp 22526 265 24X Fiche 50-000.83/12/07.8403050020
- --8403050034 Discusses 771115 meeting re ACRS ltr on Indian Point 3 sys interactions BCHWENCER: A Operating Reactors Branch i (Pre 800428) 79/12/05 EISENHUT: D G Division of Operating Reactors 2pp 22527 147 24X Fiche 50-
- P Operating license stage documents & correspondence
- 8403050017 F01A request for SECY-78-549.UCID-19310, "Review of PASNY Bys Interaction Study" & records of NNC staff & consultant review of PASNY sys interaction study on Indian Point Unit 3 SHOLLY, S C Union of Concerned Scientists 83/10/20 FELTON, J M Division of Rules and Records 1p 22525 097 24X Fiche 50-286.83/10/20.8403050017
- B403050020 Responds to FOIA request for documents re PASNY submittal on sys interactions, repts evaluating submittal & list of repts/analyses from LLL evaluating PASNY sys interaction program Forwards App A documents FELTON.J M Division of Rules and Records 83/12/07 BHOLLY, B Union of Concerned Sciencists App 22525 098 24% Fiche, 50-000, 83/12/07, 8403050020
- --Bi03040048 Discusses NRC requests for licensee sys interaction studies Forwards draft ltr to util documenting past advise & requesting meeting date when util can provide definition & realistic schedule for sys interaction program RUBENSTEIN.L S Assistant Director for Core & Containment Bystems Bi/02/10 NOWAK.T M Assistant Director for Operating Reactors Spp 22527 175 24X Fiche 50-000.83/12/07.8403050020
- --8104220881 Summary of 810402 meeting w/util,Ebasco,LLL & BNL re status of sys interaction study ROSS,W J Operating Reactors Branch i 81/04/09 Operating Reactors Branch i 4pp 22826 192 24X Fiche 50-000,83/12/07.
- --8303080270 "Preliminary Investigation of Interconnected Bys Interactions for Safety Injection Sys of Indian Point 3 " ALESBO, H P Lawrence Livermore Laboratory 83/03/04 NRC - No Detailed Affiliation Given 33pp 2526 137 24X Fiche 50-000, 83/12/07.8403050020
- --8305230119 Notification of 830311 meeting w/BNL & LLL in Bethesda.MD to discuss details of contract scope for application of sys interactions analysis methods to Indian Point 3 GOFFMAN.F NRC No Detailed Affiliation Given 83/05/03 THADANI.A Reliability & Risk Assessment Branch 23pp 22526 268 24X Fiche 50-000.83/12/07.8403050020
- --8307290506 Notification of 830809 follow-up meeting w/util in Beth#sda:MD to discuss sys interaction at facility POLK:P J Operating Reactors Branch i 83/07/22 VARGA, 5 A Operating Reactors Branch i 3pp 22525 248 24X Fiche 50-000,83/12/07,8403050020

- --8308040003 Forwards proposed text for ltr to PASNY requesting info for sys interaction methodology studies Timing for receipt of documents critical to plan for resolving Unresolved Safety Issue A-17 Expedited transmittal requested THADANSIA C Reliability & Risk Assessment Branch 83/06/14 VARGALS A Operating Reactors Branch 1 1p 22525 198 24X Fiche 50-000,83/12/07.8403050020
- --B310170712 Identifies info required by ELL from util for contract re sys interaction study covering off normal operating procedures & check-off procedures & lists MORRIS.C Reliability & Risk Assessment Branch FIN A-0445 83/09/29 POLK.P J NRC - No Detailed Affiliation Given 28pp 22525 327 24X Fiche 50-000.B3/12/07.B403050020
- --B403050023 "Diagraph-Matrix Application on Indian Point 3 for Sys Interactions." statement of work Related info encl * NRC - No Datailed Affiliation Given FIN A-0445 B3/12/07 35pp 22525 111 24X Fiche 50-000.B3/12/07.8403050020
- --8403050024 Draft "Evaluation of Indian Point 3 Sys Interaction Analysis Program" * NRC - No Detailed Affiliation Given 82/02/20 7pp 22525 104 24X Fiche 50-000,83/12/07.8403030020
- --8403050025 Informs that listed individuals will visit site during wk of 831017 Svcs requested & schedule provided Related info encl MCRRIS.C Division of Systems Integration (post 810005) FIN A-0455 83/10/04 COFFMAN.F D Division of Systems Integration (post 811005) 21pp 22526 034 24% Fiche 50-000,83/12/07, 8403050020
- --8403050027 Notification of 831121-23 sate visit to obtain info re sys interaction methodology study POLK,P J Operating Reactors Branch 1 83/10/31 VARQA,B A Operating Reactors Branch 1 2pp 22326 055 24X Fiche 50-000,83/12/07,8403050020
- --9403050029 SYSTEMS INTERACTION EVALUATION PROCEDURE FOR APPLICATION TO INDIAN POINT-3
 LIM J J , ALESSO H P , RICE T R Lawrence Livermore Laboratory
 FIN A-0405 NUREO/CR-2050 B1/04/30 NRC No Detailed
 Affiliation Given SOpp 22526 CB9 24% Fiche 50-000,83/12/07,8403050020
- --8403050035 "Review of PASNY Sys Interaction Study "
 ALE68D. H P Lawrence Livermore Laboratory KELLY, J E Science
 Applications, Inc 81/06/15 9pp 22526 196 24x
 Fiche 50-000, 83/12/07, 8403050020
- --8403050037 Discusses effect of control sys failures on plant safety STOLZ, J F Systems Interaction Branch 80/12/18 Systems Interaction Branch lp 22527 158 24X Fiche 50-000,83/12/07, 8403050020
- --8403050038 "Review of PASNY Sys Interaction Study "
 ALESSO, H P Lawrence Livermore Laboratory UCI0-19130 82/03/01
 7pp 22526 256 24% Fiche 50~000,83/12/07,8403050020
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of addl documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, S I Garvey, Schubert, Adams & Baper 7pp 22583 226 24X Fiche 50-000,84/02/13.8403080179
- 8403020864 Nutification of 840425 meeting w/util in Bethesda.MD to discuss resolution of outstanding issues re electrical aquipment environ qualification POLK.P J Operating Reactors Branch 1 84/02/24 VARGA.S A Operating Reactors Branch 1 2pp 22471194 24X Fiche 50-286.84/02/24.8403020064
- 8403030041 Notification of 840308 meeting w/util in Bethesda,MD to discuss sys interaction study submittal PDLK:F J Operating Reactors Branch 1 84/02/24 VAROA,S A Operating Reactors Branch 1 4pp 22527 324 24X Fiche 50-286,84/02/24,8403050041
- 8403050298 Notification of 840327-29 meetings w/util in Buchana,NY to discuss sys interaction study POLK:P J Operating Reactors Branch 1 84/02/24 VAROA,S A Operating Reactors Branch 1 3pp 22501 264. 24X Fiche:50-286,84/02/24,8403050298
- 8403060044 Forwards SER for NUREQ-0737. Item II 8 2 2 re plant shielding Actions taken or planned for post-accident vital area access satisfy requirements of ANREQ-0737 VARGALS A Operating Reactors Branch 1 84/02/28 BAYNE, J P Power Authority of the State of New York 6pp R2528 318 24X Fiche: 50-286, 84/02/28, 8403060044

- 8403090267 Forwards updated info re sys interaction study, per util 831130 itr Central control room review concerns resolved Twenty connected & 417 of 620 unconnected interactions closed Specific summary/status tables encl BAYNE, J P Power Authority of the State of New York 84/03/06 VARGA. S A Operating Reactors Branch 1 47pp 22572 149 24x Fiche 50-286.84/03/06.8403090267
- 8403160009 Forwards application for amend to License DPR-64, changing Tech Spec Sections 3 13.4 11 & 6 10 re snubber surveillance BAYNE, J P Power Authority of the State of New York 84/03/12 VARGA, B A Operating Reactors Branch 1 4pp 22654 325 24X Fiths 50-286,84/03/12,8403160009
- --B403160017 Application for amend to License DPR-64, changing Tech Spec Section 3 13,4 11 & 6 10 re snubber surveillance BAYNE.JP Pawer Authority of the State of New York B4/03/12 1p. 22654 327 24% Fiche 50-286,84/03/12,8403160009
- --8403160021 Proposed Tech Spec Sections 3 13.4 11 & 6 10 re snubber surveillance Bafety evaluation encl * Pawer Authority of the State of New York 84/03/12 16pp 22634 330 24X Fichs 50-286.84/03/12.8403160007
- B402090041 Board Notification 84-050 provides Commission policy statement & proposed rulemaking on environ qualifications EIBENHUT, D 0 Division of Licensing. 84/03/14 Atomic Safety and Licensing Board Panel 10pp 22716 338 24X Fiche 50-000,84/03/14,8402090041
- B403290100 Informs that util expects to complete commitment on NUREO-0737. Item II B 3 re post-accident sampling sys by June 1985
 BAYNE.J P Power Authority of the State of New York B4/03/23 VARGA.B A Operating Reactors Branch 1 ip 22806 356 24X Fiche 30-286.84/03/23.8403290100
- 8403290152 Submits paragraph inadvertently omitted from 831230 ltr providing status rept on makeup water resin retention filters BAYNE.J P Power Authority of the State of New York 84/03/23 VARGA.B A Derating Reactors Branch 1 lp 22803 321 24X Fiche 50-286.84/03/23.8403290152
- O Inspection reports. IE Bulletins & correspondence
- 8403020353 Forwards IE Insp Rept 50-286/84-01 on 840109-11 No violations noted MARTIN.T T Division of Engineering & Technical Programs 84/02/21 BRONS, J C Power Authority of the State of New York 2pp 22437 023 24X Fiche 50-286,84/02/21,8403020353
- --B403020357 IE Insp Rept 50-286/84-01 on 840109-11 No violations noted Major areas inspected public prompt notification sys WOJNAS,E J. (CRCKER,H W Region 1, Defice of Director 84/02/17 5pp 22439 025 24% Fiche 50-286,84/02/21,8403020353.
- 8401190072 IE Info Natice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunclation " Svc list enc1 JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Past 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22909 239 24X Fiche 50-000.84/02/28,8401190072
- 8403130146 Forwards IE Insp Rept 50-286/84-02 on 840116-0215 & notice of violation STAROSTECKI.R Division of Project & Resident Programs 84/03/01 BRONS, J C Power Authority of the State of New York 2pp 22643 027 24% Fiche 50-286.84/03/01,8403150146
- --8403150149 Notice of violation from inep on 840116-0215 * Region 1, Office of Director 84/03/01 lp 22643 029 24X Fiche 50-286,84/03/01,8403150146
- --8403150166 IE Insp Rept 50-286/84-02 on 840116-0215 Violation noted RM sys changes not delineated on sys print or sys checkoff list & safety evaluation not performed KENNY.T J. ROBSBACH.L W. Region 1. Office of Director NORRHOLH.L Division of Engineering & Technical Programs. 84/02/22 13pp 22643 030 24X Fiche 50-286.84/03/01.8403150146
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl ORACE, J N Division of GA. Safeguards & Inspection Programs (Post 830103) 84/03/02, Consolidated Edison Co of New York, Inc 130pp 22552:329 24X Fiche: 50-000,84/03/02,8402090007.

- 8402090008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JERDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008
- B402070009 IE Info Notice 84-15. "Reporting of Radiological Releases " Svc list encl
 - UDRDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York: Inc. 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8402090011 IE info Notice 84-17. "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " 8vc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50~000.84/03/05.8402090011
- 8402070024 IE Info Notice 84-07, Rev 1, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of Ne 24X Fiche 50-000,84/03/07,8402090024 22635 049 11800
- 8402090028 IE Info Notice 84-18. "Stress Corrosion Cracking in PWR
- Bys." Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Rasponse (Post 830103) 84/03/07 Consolidated Edison Co of New
 York, Inc 118pp 22884 186 24X Fiche 50-000.84/03/07,8402090028 York, Inc 118pp
- 8402070031 IE Bulletin 84-02. "Failures of GE Type HFA Relays in Use in Class IE Safety Bys " Svc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823-094. 24X Fichs 50-000.84/03/12,8402090031
- 8403170258 Ack receipt of 840214 ltr informing NRC of steps taken to correct violations noted in 1E Emergency Preparedness Appraisal Rept 50-286/81-05 MARTIN, T T Division of Engineering & Technical Programs 84/03/13 BRONS, J C Power Authority of the State of New York 2pp 22672 221 24X Fiche 50-286,84/03/13,8403170258
- --8403190265 Responds to NRC Billi9 ltr re violations noted in IE
 Emergency Preparedness Appraisal Rept 50-286/81-05
 Corrective actions post-accident instrumentation & sampling requirements per NUREO-0737 & Reg Guide 1 97 implemented BRONS, J C Power Authority of the State of New York 84/02/1 MARTIN.T T Division of Engineering & Technical Programs 2p 22672 223 24% Fiche 50-286.84/03/13,8403190258 84/02/14
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Byo list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 84/03/21 Consolidated Edison Co of New York, Inc 123pp. 22823'229 24X Fiche 50-000.84/03/21,8402090043
- 8402090044 IE Insp Notice 84-20, "Svc Life of Relays in Safety-Related 902094044 is tipe Notice 97-80, 55 min. 5 mi
- 8403300175 Forwards response to IE Bulletin 83-07, "Apparently Fraudulent Products Sold by Ray Miller, Inc." No subj matls provided or used at facility BRONS, J. C. Power Authority of the State of New York, 84/03/21 MURLEY, T. E. Region 1, Office of Director 2pp 22820 045 2: Fiche 50-286,84/03/21,8403300175
- R Periodic operating reports & related correspondence
- 8403210113 "Summary Rept of Personnel Radiation Exposure by Work & Job Function, 1983 " W/840229 ltr BRDN8.J.C Power Authority of the State of New York 83/12/31 MURLEY, T.E Region 1, Office of Director 2pp 22705 062. 24X Fiche 50-286, 83/12/31, 8403210113
- 8403130256 Forwards "Radioactive Effluent & Waste Disposal Semiannual Rept. Jul-Dec 1983" BRDNS.J.C Power Authority of the State of New York 84/02/27 MURLEY.T.E Region i. Office of Director 1p 22616 094 24: Fiche: 50-286.84/02/29.8403130256
- --B403130412 "Radioactive Effluent & Waste Disposal Semiannual Rept.Jul-Dec 1983 " * Power Authority of the State of New York B3/12/31 54pp 22616:095 24% Fiche 50-286.84/02/29.8403130256

- B403300159 Monthly operating rept for Feb 1984 W/840315 ltr KELLY,L . BRONS, J C Power Authority of the State of New York 84/02/29 7pp 22821 075 24X Fiche 50-286,84/02/29,8403300159
- S Reportable occurrences, LERs & related correspondence
- 8403150047 LER 84-001-00 on 840125, w/reactor in hot shutdown, code safety valve MS-45 on main steam header 34 opened momentarily Caused by high differential pressure lifting valve Valve reset & tested W/840224 ltr OUMBLE.F W , DRONS, J C Power Authority of the State of New York 84/02/24 MURLEY, T E Region 1, Office of Director 3pp 22643 138 24X Fiche 50-286,84/02/24,8403150047
- 8403150050 LER 84-003-00 on 840128, automatic safety injection signal actuated on high differential steam line pressure Caused by code safety valve MS-45 on main header 34 lifting momentarily Valve reset W/840224 ltr QUMBLE.F W. BRONS.J C Power Authority of the State of New York 84/02/24 MURLEY.T E Region 1. Office of Director Spp 22643 143 24% Fiche 50-286,84/02/24.8403150050
- 8403210049 LER 84-002-00 on 840128, w/reactor critical at zero power, 403210049 LER 84-002-00 on 840128 W/reactor critical at tero power, trip initiated by intermediate range nuclear instrumentation Caused by blown power supply fuse for Channel 32 Fuse replaced W/840224 ltr QUMBLE.F W , BRONS, J C Power Authority of the State of New York 84/02/24 MURLEY, T E Region i, Office of Director Jpp 22703 311 24% Fiche 50-286,84/02/24.8403210049
- 8403260233 Forwards summary list of deficiencies identified per 10CFR50 55(e), Part 21 & potential generic 1tr repts for Comments
 STAROSTECKI,R Division of Project & Resident Programs
 Region 1. Office of Director 7pp 22756 065 24X
 Fiche 50-000,84/02/28,8403260233 84/02/28
- 8403120152 LER 84-004-00 on 840209. reactor trip actuated on steam flow/feed flow mismatch for steam generator 32 Caused by loss of both heater drain pumps Associated instrument air lines blown down removing condensation H/840307 ltr QUMBLE.F W . BRONS.J C Power Authority of the State of New York 84/03/07 3pp 22586 178 24X Fiche 50-286.84/03/07.8403120/152
- BA03260091 LER BA-005-00 on BA0220, reactor trip initiated on steam flow/feed flow mismatch on steam generator 32 Caused by closure of main feed regulating valve due to failed trip solenoid Leads replaced W/B40320 ltr ANDERBON. J J , BRONS. J C Power Authority of the State of New York B4/03/20 3pp 22747 341 24X Fiche 50-286, B4/03/20, 8403260091
- 8403260257 LER 84-006-00 on 840307, during monthly reactor protection sys testing, turbine tripped Caused by inadvertent closure of cell switch associated w/reactor trip bypass breaker 52/BYB Catch realigned W/840320 ltr ANDERBON.J J. BRONS.J C Power Authority of the State of New York 84/03/20 3pp 22755 142 24X Fiche 50-286.84/03/20.8403260257
- T Hearing transcripts on non-antitrust matters
- 8403160004 Transcript of ACRS Subcommittees on Reliability & PRA & Indian Point Units 2 & 3 840314 meeting in Washington, DC Pp 1-60 Supporting documentation encl
 ** ACRS Advisory Committee on Reactor Safeguards, 84/03/14 61pp 22653 289 24X Fiche 50-247,84/03/14.8403160004
- V Operator Examinations
- 8401200078 Forwards operator licensing exam schedule for FY84-87 in response to Generic Ltr 83-40 NRC will be informed of BAYNE, J.P. Power Authority of the State of New York EISENHUT, D.O. Division of Licensing, App. 21862 35 Fiche 50-286,84/01/16,8401200078 changes BAYNE,J₽ New York 84/01/14 21862 357 24X
- DOCKET 50-287 OCONER NUCLEAR STATION, UNIT 3
- F Becurity, medical, emergency & fire protection plans
- B403090254 Public version of revised crisis mgt plan implementing procedures, including Procedures 5 3 4 re scheduling/planning support group, 5 3 6 re rediological support group & 5 3 7 re technical support group W/B31107 ltr & JM Felton memo TUCKER, H B Duke Power Co B3/10/31 DENTON, H R Office of Nuclear Reactor Regulation, Director 271pp 22595 055 24% Fiche 50-000, 83/10/31, 8403090254

- B403060225 Rev \$1 to crisis mgt plan W/B40224 ltr & public info pamphlet VAUGHN.T E., TUCKER.H B Duke Power Co 84/02/02 DENTON.H R Office of Nuclear Reactor Regulation. Director 66pp 22516 189 24X Fiche 50-000.84/02/02.8403060225
- 8403160134 Forwards IE Insp Repts 50-269/84-04, 50-270/84-04 & 50-287/84-04 on 840201-02 No violations or deviations identified DANCE.H C Division of Project & Resident Programs 84/02/16 TUCKER.H B Duke Power Co 2pp 22655
- --8403160141 IE Insp Repts 50-269/84-04.50-270/84-04 & 50-287/84-04 on 840201-02 No violations identified Major areas inspected emergency preparedness areas of protective action decisionmaking CLINE,W E Region 2. Office of Director 84/02/15 4pp 22655 338 24% Fiche 50-269.84/02/16.8403160134
- 8403090222 Forwards Rev 3 to training & qualification plan Rev withheld (ref 10CFR73 21) TUCKER, H B Duke Power Co 84/02/29 O'REILLY, J P Region 2, Office of Director 1p 22575 149 24X Fiche 50-269, 84/02/29, 8403090222
- 8403160278 Extends invitation to attend 840316 workshop to discuss IOCFR50.App R requirements & results of recent insp to help resolve misunderstanding associated whrequirements LEWIS.R C Division of Project & Resident Programs 84/03/02 TUCKER.H B Duke Power Co Ip 22660 274 24X Fiche 50-000.84/03/02.8403160278
- 8403160245 Forwards summary of 840228 meeting w/util in Atlanta.9A re 10CFR50 48 & 10CFR50.App R fire protection application Attendance list also encl LEWIS.R C Division of Project & Resident Programs 84/03/07 TUCKER.H B Duke Power Co 3pp 22660 312 24X Fiche 50-269.84/03/07.8403160245
- 8403120119 Advises that 840114 Rev 11 to physical security planconsistent u/provisions of 10CFR50 54(p) & acceptable LEWIS.R C Division of Project & Resident Programs 84/03/08 TUCKER.H B Duke Power Co 2pp. 22587 217 24X Fiche 50-269.84/03/08.8403120119
- 8403290069 Ack receipt of 840208 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/83-36. 50-270/83-37 & 50-287/83-36 Implementation of corrective actions will be examined during future insp DANCE. H C Division of Project & Resident Programs 84/03/20 TUCKER H B Duke Power Co 1p 22807 011 24% Fiche 50-269.84/03/20.8403290069
- --8403290108 IE Insp Repts 50-269/83-36.50-270/83-37 & 50-287/83-36 on 83111-1210 Violation noted failure to follow Maint Protedure 270/83-37-01 re quality performed on Reactor Coolant Pump 282 BYANTJ Region 2. Office of Director 84/01/09 10pp 22807 017 24% Fiche 50-269,84/03/20.8403290069
- B403270209 Forwards Rev 4 to util response to NUREO-0737, Suppl 1, including control room review implementation priority schedule TUCKER, M B Duke Power Co B4/03/23 DENTON, H R Office of Nuclear Reactor Regulation, Director STOL2, J F Operating Reactors Branch 4 9pp 22772 088 24X Ficher 50-2657, 84/03/23, 84003270209
- P Operating license stage documents & correspondence
- 8403060272 Submits response to NRC request for schedular info re SER of proposed inadequate core cooling instrumentation Final design description will be submitted by 850701 TUCKER.H D Duke Power Co B4/02/28 DENTON.H R Office of Nuclear Reactor Regulation, Director 8TOLZ.J F Operating Reactors Branch 4 2pp 22518 124 24X Fiche 50-269,84/02/28,8403060292
- 8403150328 Forwards Amends 127.127 & 124 to Licenses DPR-JB.DPR-47 & DPR-55, respectively & safety evaluation Amends revise Tech Specs to implement limiting conditions for operation in event one startup transformer out of syc STOLZ.J F Operating Reactors Branch 4 84/03/02 TUCKER.H B Duke Power Co 2pp 22649 274 24% Fiche 50-269.84/03/02.8403150328
- --8403150335 Amends 127,127 & 124 to Licenses DPR-38,DPR-47 & DPR-55, respectively, revising Tech Specs to implement limiting conditions for operation in event one startup transformer out of svc STDLZ, JF Operating Reactors Branch 4 84/03/02 2ipp 22649 276 24X Fiche 50-269,84/03/02.8403150328

- --B403150344 Safety evaluation supporting Amends 127,127 & 124 to Licenses DPR-36,DPR-47 & DPR-55,respectively * Office of Nuclear Reactor Regulation, Director B4/03/02 2pp 22649 297 24% Fichs 50-269,84/03/02,8403150328
- ⊕ Inspection reports. IE Bulletins & correspondence
- 8403070364 Forwards IE Insp Repts 50-269/83-11.50-270/83-11 & 50-287/83-11 on 830317-28 Enforcement action addressed in NRC 830402 ltr LEWIS:R C Division of Project & Resident Programs 83/06/02 TUCKER.H B Duke Power Co 2pp 22546 025 24X Fithe 50-269.83/06/02.8403070364
- ---B403070369 IE Insp Repts 50-269/83-11.50-270/83-11 & 50-287/83-11 on 830317-28 Violations noted loss of containment integrity on 830317-821 & failure to meet requirements of confirmatory order dtd 810710 re independent verification BRYANT, J. FALCONER, D. Region 2. Office of Director IGNATONIS, A Division of Project & Resident Programs 83/06/02 10pp 22546 027 24X Fiche 50-269, 83/06/02,8403070364
- B403160134 Forwards IE Insp Repts 50-269/84-04.50-270/84-04 & 50-287/84-04 on 840201-02 No violations or deviations identified DANCE, H C Division of Project & Resident Programs 84/02/16 TUCKER, H B Dute Power Co 2pp 22655 336 24% Fiche 50-269, 84/02/16.8403160134
- --B403160141 IE Insp Regts 50-269/84-04.50-270/84-04 & 50-287/84-04 on B40201-02 No violations identified Major areas inspected emorgancy preparedness areas of protective action decisionmaking CLINE.W E Region 2. Office of Director JENKINB.G R Division of Emergency Preparedness & Materials Safety B4/02/15 4pp 22655 338 24X Fiche 50-269,84/02/16.8403160134
- 8403010308 Forwards add1 info re 830815 request for relief from inservice insp requirements (Hydrostatic) of Bection XI of ASME Boiter & Pressure Vessel Code Valve 2LPSW-133 cannot be closed due to sheared hinge pins TUCKER, H B Duke Power Co 84/02/23 DENTON, H R Office of Nuclear Reactor Regulation, Director STOLZ, J F Operating Reactors Branch 4 2pp 22432 102 24% Fiche 50-269,84/02/23,8403010308
- 8401170072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc. 118pp 22707 237 24X Fiche 50-000.84/02/28,8401170072
- B402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl GRACE.J N Division of GA. Bafeguards & Inspection Programs (Post B30103) B4/03/02 Consolidated Edison Co of New York, Inc i30pp 22552 329 24X Fiche 50-000.84/03/02,8402090007
- 8402090000 IE Info Notice 84-16. "Failure of Automatic Sprinkler Bys Valves to Operate " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000.84/03/02.8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases" Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 119pp 22553 217 24X Fiche 50-000-84/03/02, 8402090009
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitragen Cooling Components Below Nil Ductility Temp " Bvc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc i17pp 22553 336 24X Fiche 50-000.84/03/05,8402090011
- B402090024 IE Info Notice B4-09, Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103). B4/03/07 Consolidated Edison Co of New York, Inc 118pp 22635.049 24X Fiche 50-000,84/03/07,8402090024
- 8402070028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Bys " Svc list and JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000.84/03/07,8402070028

- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sym " Svc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000.84/03/12.8402090031
- B403270069 Ack receipt of 840208 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/83-36, 50-270/83-37 & 30-287/83-36 Implementation of corrective actions will be examined during future insp DANCE.H C Division of Project & Resident Programs 84/03/20 TUCKER.H B Duke Power Co 1p 22807 011 24X Fishe 50-269, 84/03/20.8403270067
- --8403290082 Responds to NRC 840109 ltr re violations noted in IE Insp. Repts 50-269/83-36,50-270/83-37 & 30-287/83-36 Corrective actions Unit 2 staging coil locations corrected & seal packages on Reactor Coolant Pump 282 replaced TUCKER.H B Duke Power Co 84/02/08 O'REILLY.J P Region 2. Office of Director 2pp 22807 012 24X Fiche 50-269,84/03/20. 8803290060
- --8403270070 Forwards IE Insp Repts 50-249/83-34,50-270/83-37 & 50-287/83-36 on 831111-1210 & notice of violation DANCE.H C Division of Project & Resident Programs 84/01/07 TUCKER,H B Duke Power Co 2pp 22807 014 24X Fiche 50-269,84/03/20,8403270067
- --B40329010B IE Insp Repts 50-269/B3-36, 50-270/B3-37 & 30-287/B3-36 on B3111-1210 Violation noted failure to follow Maint Procedure 270/B3-37-01 re quality performed on Reactor Coolant Pump 2B2
 BRYANT, J. FALCONER, D. Region 2, Office of Director BROWNLEE, V. Division of Preject & Resident Programs B4/01/09 10pp 22807 017 24X Fiche 50-269,84/03/20,8403290069
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" 8vc list encl JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fishe 50-000.84/03/21,8402090043
- E402070044 IE Info Notice 84-20, "Svc Life of Relays in Gafety-Related Bys" Svc list and JORDAN, Et. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 135pp. 22733 Q01 24X Fiche 50-000,84/03/21,8402070044
- R Periodic operating reports & related correspondence
- B403200010 Monthly operating repts for Feb 1984 W/840315 ltr REAVIS.J A., TUCKER.H B Duke Power Co 84/02/29 17pp 22685 185 24X Fiche 50~269.84/02/29.8403200010
- V Operator Examinations
- DOCKET 50-289 THREE MILE ISLAND NUCLEAR STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- B403140088 Public version of temporary change notices to amergency plan implementing procedures, including Procedure 1004 8 recallout of onsite & offsite duty roster personnel H/JM Felton 840312 release memo BRADY, J A. PAULES, J., GRANGE, O. J. General Public Utilities GPU Bervice Corp. B3/10/27 35pp. 22637 142 24X Fiche, 50-289, 83/10/27, 8403140088
- 8402090006 Board Notification 84-034 forwards R Vollmer 840206 memo to D Eisenhut re fire research results concerning fires in electrical cabinets in control room EISENHUT, D Q Division of Licensing 84/02/23 PALLADING, QILINSKY, ROBERTS Commissioners 1p 22576 203 24X Fiche 50-000,84/02/23,8402090006
- --B4030B03i6 Recommends that info re fire research results concerning fires in electrical cabinets in control room be submitted for board notification, per NRR Dfc Ltr 17, dtd 821001 Further evaluation of test data required VOLLMER, R H Division of Engineering 84/02/06 EISENHUT, D 9 Division of Licensing 10pp 22576 204 24X Ficha 50-000, 84/02/23, 8402090006

- 8403010347 Forwards status & justification for nine listed NUREG-0737 *
 Reg Guide 1 97 Items, per 840222 request Analysis of safety
 parameter display sys will be submitted by \$40430
 HUKILL.H D General Public Utilities GPU Service Corp 84/02/27
 EISENHUT.D Q Division of Licensing 21pp 22433 018 24X
 Fiche 30-289,84/02/27.8403010347
- 8403050097 Revised emergency plan implementing procedures, including Procedure 1004 8 re callout of onsite & offsite duty roster personnel & Procedure 1004 21 re emergency repair/ operations

 * General Public Utilities GPU Service Corp 84/02/28 17pp 22488 047 24% Fiche 50-289,84/02/28,8403050097
- 8403060133 Forwards Rev 19 to security plan Rev restores portions of plan wording re TMI-2 security features modified in Revs 17 & 18 Rev withheld (ref 10CFR73 21)
 HUKILLH D General Public Utilities OPU Service Corp 84/02/29
 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp
 22506 332 24x Fiche 50-289,84/02/29,8403060133
- 8403120166 Revised emergency plan implementing procedures, including Procedure 1004 36 re warehouse muster, Procedure 1004 4 re general emergency & Procedure 1004 3 re site emergency # General Public Utilities GPU Service Corp 84/03/01 85pp 22590 319 24% Fiche 50-289,84/03/01,8403120166
- 8403120004 Reevaluates response to NUREG-0737. Item III D 3 4, "Control Room Habitability," based on PRA technique for onsite & offsite sources App R mods will assure adequate smoke detection in control room HUKILL-H D General Public Utilities GPU Service Corp 84/03/02 BTOLZ, J F Operating Reactors Branch 4 2pp 22586 306 24X Fiche 50-289.84/03/02.8403120004
- B403220141 Rev 9 to Procedure 1004 6. "Add1 Assistance & Notification "
 # General Public Utilities GPU Service Corp B4/03/06 21pp
 RR714 R8B 24X Fiche 50~289.84/03/06.8403220141
- 8403130286 Informs that annual emergency exercise scheduled for 841003, per 10CFR50. App E requirements Limited participation planned by Commonwealth of PA, five risk counties & local municipalities

 HUKILL-H D Oeneral Public Utilities GPU Service Corp 84/03/08

 Office of Nuclear Reactor Regulation, Director 1p 22605 180

 24X Fiche 50-289, 84/03/08, 8403130286
- 8403190243 Notification of 840418 workshop in King of Prussia.PA to discuss lessons learned from recent App R fire protection safe shutdown insp & topics described in IE Info Notice 84-09 Agenda for workshop encl MRLEY.TE Region 1. Office of Director 84/03/09 D'TOOLE.J D Consolidated Edison Co of New York. Inc CDUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) RHODE.O K Niagara Mohauk Power Corp 35pp 22672 062 24X Fichs 50-000.84/03/09.8403190243
- 8403270315 Advises that emergency plan.documented in NUREG-0746, "Emergency Preparedness Evaluation for TMI-1" & Suppl 1, NUREG-0737, Item III A 2 1, complete for facility STOLZ, J F Operating Reactors Branch 4 BA/03/09 HUKILL, H D General Public Utilities GPU Service Corp 5pp 22789 241 24X Fiche 50-289,84/03/09.8403270315
- 8403270232 Revised emergency plan implementing procedures, including Rev 10 to Procedure 1004 &, "Addl Assistance & Notification" & Rev 4 to Procedure 1004 &, "Offsite Emergency Response Directory "
 GIANGI.G J General Public Utilities -- GPU Service Corp 84/03/20 22pp 22771 354 24% Fiche 50-289.84/03/20.8403270232
- 8403300303 Notification of 840327 meeting w/util in Bethesda.MD to discuss detailed control room design review items relative to requirements of NUREG-0737. Suppl 1 SILVER.H Operating Reactors Assessment Branch. 84/03/20 STOLZ.J F Operating Reactors Branch 4 2pp 22844 307 24X Fiche 50~289.84/03/20,8403300303
- B403290005 Inquires as to whether NRC plans to take any action to correct deficiencies in emergency preparedness for facility identified by FEMA Details of NRC position requested WEISB.E R Harmon t Weiss 84/03/22 STQLZ.J F Operating Reactors Branch 4 19 22803 281 24X Fiche 50~289,84/03/22,8403290005

Q Adjudicatory correspondence

- B403010009 Requests substitution of Attachment I to 840206 filing w/ sncl & corrects statement re insp or licensee produced documents Driginal Attachment I should be returned CHURCHILL.B W Shaw, Pittman, Potts & Troubridge CHURCHILL.B W Metropolitan Edison Co. 84/02/13 WOLFE.S J. METRICK, D.L., LAMB.J.C. Atomic Safety and Licensing Board Panel 6pp. 22435-221-24X Fiche 50-289.84/02/13,8403010009
- BA03060084 Forwards listed unerpurgated ref documents & Topical Rept 003, Rev 3 W/o enti W/svc list Related correspondence CHURCHILLB W Shaw, Pittman, Potts & Troubridge CHURCHILL, B W Metropolitan Edison Co 84/03/01 DOROSHOW, J. BRADFORD, L. Three Mile Island Alert 2pp 22516 359 24X Fiche 50-287, 84/03/01.
- 8403050192 Memorandum & order denying TMI Alert 840125 motion for order compelling discovery & granting licensee 840206 mution for protective order MGLFE,S J Atomit Safety and Licensing Board Panel 84/03/02 Three Nile Island Alert 8pp 22518 350 24% Fiche 50-289, 84/03/02.8403040182
- 8403040243 Protective order that licensee shall not be compelled to respond to intervenor. THI Alert Document Request 22 set forth in 831230 request for production of documents WDLFE, 8 J Atomic Safety and Licensing Board Panel 84/03/02 Hetropolitan Edison Co 9pp 22515 181 24X Fiche 50-289,84/03/02,8403802243
- 8403070025 Notice forwarding info re recent resolution of proceeding in which Hat Ed was charged w/criminal activity re primary coolant leak rate testing Cortificate of Svc encl Related correspondence
 BLAKE.E L Metropolitan Edison Co BLAKE.E L Shaw, Pittman, Potts & Trowbridge 84/03/02 63pp 22548 043 24X
 Fiche 50-289,84/03/02.8403070025
- 8403070233 Informs parties that Commissioner Bernthal will tour facility on 840309 Notification of representatives of parties wishing to attend must be made no later than 840308 # Commissioners 84/03/06 lp 22541 308 24X Fiche 50-289.84/03/06.8403070233
- 8403080105 Errata for licenses motion for summary disposition of each of TMT Alert & Joint Intervenor contention Certificate of Svc encl
 TROWBRIDGE G F Metropolitan Edison Co Pittaan, Potts & Troubridge 84/03/06 Atomic Safety and Licensing Board Panel App 22559 178 24X Fiche 50-289,84/03/06.
- 8403090129 Notice forwarding transcript of 840228 & 29 proceedings & 840301 order by US District Court for Middle District of State of PA re resolution of leak rate test Related correspondence BLAKE.E L Metropolitan Edison Co 84/03/07 Atomic Safety and Licensing Board Panel 89pp 22576 089 24X Fiche 50-289.84/03/07.8403090129
- B403130013 Motion for reconsideration of ALAB-697 in view of new infore emergency planning for farmers ASLAB grossly erred in considering matter of emergency planning for farmers resolved Certificate of Svc encl
 AMMDDT.N O . AMMDDT.M M Aamodts 84/03/07 Atomic Safety and Licensing Appeal Panel 33pp 22615 128 24x Fiche 50-289, 84/03/07.8403130013
- 8403140111 Ack receipt of Joint Intervenors 840227 motion to file response to licensee second set of interrogatories out of time Motion viewed discovery between Joint Intervenors & licensee Staff does not intend to file orief on merits WAGNER. ME Hearing Branch 4 84/03/07 WOLFERS J. LAMB, J.C. HETRICK. D.L. Atomic Safety and Licensing Board Panel 1p 22623 357 24% Fiche 50-289,84/03/07.8403140111
- 8403130443 Forwards supplemental affidavit of FS Gracobbe clarifying B40223 affidavit Related correspondence CHURCHILL.B W Shaw, Pittman, Potts & Trowbridge CHURCHILL.B W Metropolitan Edison Co 84/03/08 WOLFE.S J. LAMB. J G. HETRICK.D L Atomic Safety and Licensing Board Panel 1p 22613
- --B403130451 Supplemental affidavit of FS Giacobbe, clarifying misleading statement in 840223 affidavit GIACOBBE, FS Metropolitan Edison Co 84/03/07 3pg 22613 173 24% Fiche 50-289,84/03/08.8403130443

- 8403130065 Motion for extention of time until 840330 to respond to licensee & NRC motions for summary disposition Certificate of Bvc encl Related correspondence DDROSHOW. J Three Mile Island Alert 84/03/10 Atomic Safety and Licensing Board Panel 5pp 22602 i18 24x Fiche 50-289.84/03/10, 8403130065
- 8403160015 Responds to RC DeYoung 840305 ltr re emergency info pamphlet on farm evacuation plans Suggestion that author initiate & negotiate plans w/Commonwealth of PA unacceptable LEE.J' Affiliation Not Assigned 84/03/12 PALLADINO, OILINBKY, ASSLSTINE Commissioners 3pp 22652 359 24X Fiche 50-289,84/03/12.8403160015
- 8403210137 Comments on need to resolve mgt integrity issue prior to NAC restart decision GODDLING. B House of Rep. 84/03/12 UDALL, M K House of Rep. Interior & Insular Affairs 2pp 22707 251 24x Fiche 50-289,84/03/12,8403210137
- B403200055 Forwards W Mashington 840313 memo detailing contacts w/
 Bradford on 840217 W Washington conscientious efforts to
 arrange to obtain documents promised & ordered by ASLB did
 not amount to harassment Related correspondence
 TROWBRIDGE, G F Shaw, Pittman, Potts & Trowbridge TROWBRIDGE, G F
 Matrogolithan Edison Co 84/03/14 DORSHDM, J Three Mile Island
 Alert lipp 22698 296 24X Fiche 50-289,84/03/14,8403200055
- 8403160007 Second supplemental answer to TMI Alert first set of interrogatories & request for production of documents Computer printout list of documents requested encl Staff objects to Production Request 2 Certificate of Svc encl WAGNER.W E Hearing Branch 4 84/03/15 23pp 22655.174 24X Fiche, 50-289, 84/03/15, 8403160007
- 8403160032 Responds to 831206 ltr re Commission consideration of applicant request for Commission approval of restart Final decision will be made in near future PALLADINO.NJ Commissioners 84/03/15 UDALL.M K House of Rep. Interior & Insulan Affairs 2pp 22655 141 24X Fiche 80-287.84/03/15.8403160032
- 8403190187 Forwards supplemental affidavit of CE McCracken & CS Wu re clarification to 840224 affidavit in support of staff motion for summary disposition of TMI Alert Contention 1 d WAGNER, ME Hearing Branch 4 84/03/15 WDLFF, B J, LAMB, J C, HETRICK, D L. Atomic Safety and Licensing Board Panel 1p 22670 357 24X Fiche 50-289,84/03/15,8403190187
- ---B403190189 Supplemental affidavit of CE McCracken & PC Wu clarifying Paragraph 9 of B40224 affidavit in support of staff motion for summary disposition of TMI Alert Contention 1 d MCCRACKEN.C E. MU.P.C Division of Engineering 84/03/14 2pp 22670 358 24X Fiche 50-289,84/03/15.8403190187
- 8403200066 Forwards licensee status rept on required actions from Feb 1983 BETA rept, interofc memo re shift monitor program & gress release announcing change in Nuclear Safety & Compliance Committee BAUSER. D B Shaw. Pittman. Potts & Troubridge BAUSER. D B Metropolitan Edison Co B4/03/15 EDLES. G J. BUCK. J H. KOML. C N Atomic Safety and Licensing Appeal Panel 51pp 22685 035 24% Fiche 50-289.84/03/15.8403200066
- 8403200120 Response supporting TMI Alert motion for extension of time Until 840330 for filing response to licensee & NRC motions for summary disposition Certificate of Svc encl Related Correspondence
 TROUBRIDGE OF Metropolitan Edison Co TROUBRIDGE OF Bhaw, Pittman Potts & Troubridge 84/03/15 Atomic Safety and Licensing Board Panel 5pp 22697 176 24X Fiche 50-287,84/03/15,840320120
- 8403200191 Responds to 831208 & 18 ltrs repossibility of restart decision prior to further evidentiary hearings on mgt competence & integrity ASLAB decision will be considered by Commission upon issuance PALLADINO,N J Commissioners 84/03/19 SPECTER, A Senate 2pp 22698.003 24% Fiche 50~289,84/03/19.8403200191
- ---8403200195 Forwards revised add1 views of Commissioner Bernthal per Commission 840127 memorandum re tentative views & plans for resolution of mpt integrity issues prior to restart CLEMENTS, N. L. Office of the Secretary of the Commission 84/02/13 Office of the Executive Legal Director. 4pp 22698 020 24X Fiche 50-289.84/03/19.8403200191

- --B40320019B Responds to 840124 ltr & 831216 position statement re funding of cleanup prerequisite for restart Commission does not have legal authority to condition restart of TMI-1 on funding solution for cleanup of TMI-2 PALLADIND.N.J Commissioners 84703/19 THORNBURGH,R Pennsylvania, Commonwealth of, 3pp 22698 024 24X Fichs 50-289,84703/19,8403200191
- --8403200200 Comments on rept that Commission recommended authorization to operate at 25% power w/commencement as early as Jan 1984 Authorization contradicts previous Commission assurances Evidentiary hearings recommended BPECTER.A Benate 83/12/08 PALLADINO,N J Commissioners 1p 22698.027 24% Fiche 50~289,84/03/19,8403200191
- ---8403200205 Responds to 831117 ltr re resolution of mgt competence & integrity issues prior to restart Questions about competence & integrity will be adequately resolved prior to restart decision

 PLAINE H. B. GREGE OF the General Counsel 93(1)(23 00F67F6 A

PLAINE.H H. Office of the General Counsel 83/11/23 SPECTER.A Senate. 2p.p. 22698 028 24X Fiche 50-289,84/03/19,8403200191

- --B4032002ii Advises Commission to hold necessary hearings to resolve outstanding issues discussed at 8312i6 hearing BPECTER, A Senate 83/12/18 PALLADINO, N Commissioners 2pp 22698 030. 24X Fiche 50-289,84/03/19,8403200191
- 84GS21GO14 UCB brief on Commission 840127 review of issues decided in ALAB-729 & ALAB-744 History of proceeding shows successive narrowing of issues until all unresolvable issues excluded W/Cartificate of 8vc WEI6B.E.R. Union of Concerned Scientists 84/03/19 44pp 22706/283. 24x Fiche 50-289/84/03/19.8403210014
- B403210024 Brief re Commission review of specific design issues in ALAB-727. Certificate of Svc encl
 QQLDBERQ, J R Hearing Branch 2 RAWBON, R J Hearing Branch 4
 B4/03/19. Commissioners 47pp 22706 00B 24K
 Fiche: 50-289, 84/03/19,8403210024
- B403210193 Brief on review of ALAB-7R7 & ALAB-744 Commission review areas should be affirmed
 BAXTER: T. A Metropolitan Edison Co BAXTER: T A Shaw: Pittman.
 Potts & Trowbridge DBS 020 84/03/19 Commissioners 68pp
 22710.001
- 8403220242 Response to both licenses & staff motion for summary disposition of Joint Intervenors contentions & motion to stay hearing. Certificate of Buc encil AAMODT.N O Aamodts LEE.J Joint Petitioners TMI 84/03/19 Atomic Befety and Licensing Board Penel 9pp. 22719 040, 24% Fiche. 80-289. 84/03/19.8403220242
- 8403210167 Response supporting licenses 840224 motion for summary disposition of each of TM1 Alert & Joint Intervenors contentions. Motion establishes that no genuine issues of fact be litigated.

 WAONER, M E. Hearing Branch 4 DSB 015 84/03/20. Atomic Safety and Licensing Board Panel Opp 22710 348, 24X Fichs, 80-287, 84/03/20.8403210169
- ---B403210173 Affidavit of CE McCracken & PC Wu in response to licenses motion for summary disposition of Joint Intervenors Contention 5. Certificate of Svc encl MCCRACKEN.C E., Wu.P C Division of Engineering 84/03/14 9pp 22710:354 24X Fiche: 50-289,84/03/20,8403210169
- 8403210175 Porwards HD Hukill 840222 & 27 ltrs re emergency feedwater sign flow instrumentation & NUREG-0737 selective item status, respectively. Svc list encl BAXTER, T.A. Shaw, Pittman. Potts & Trombridge BAXTER, T A Matropolitan Edison Co DSB 005 84/03/20 CHILK, S.J. Office of the Becretary of the Commission. 27pp. 22710 104 24X Fiche: 50-289, 84/03/20, 8403210175
- BAGG210187 Forwards H Hukill 840307 ltr to JF Stolz re reviews of tauching performance, ability & attitude of DD in 1983 & RR Clark 840228 ltr to RC Deyoung responding to 840203 notice of violation Certificate of Byc enc).

 BAUSER, D. B Shaw, Pittman, Potts & Troubridge BAUSER, D B Metropolitan Edison Co DBB 004 84/03/20 EDLER, C J, BUCK, J H, KOML, C.N. Atomic Safety and Licensing Appeal Panel 35pp.

 22710:289 24X Fiche:50-289,84/03/20,8403210187
- 8403260382 Inquires re intended plan to take action on FEMA identified deficiencies in emergency preparedness.
 WEIBB.E.R Harmon & Weiss WEIBB.E.R. Three Mile Island Alert Dag 099 84/03/22 STOLZ.J.F. Operating Reactors Branch 4 ip 22760:142, 24% Fiche 50-289.84/03/22.8403260382

- 8403270300 Informs that staff does not intend to respond to Aamodt B40307 motion for reconsideration of ALAB-697 unless requested by ASLAB GRAY, J. R. Hearing Branch 4 DSB 137 84/03/22 EDLES, G. J., QUARLES, L. R., BUCK, J. H. Atomic Safety and Licensing Appeal Panel Ip 22787 034 24X Fiche 50-289, 84/03/22, 8403270300
- 8403270304 Response to TMI Alert 840310 motion for extensions of time until 840330 to respond to licensee & staff motions for summary disposition Staff does not object to motion Certificate of Svc encl Related correspondence WAGNER/M R Hearing Branch 4 DBB 136 84/03/22 Atomic Safett and Licensing Board Panel 1 pp 22789 029 24x Fiche 50-289.84/03/22,8403270304
- 8403260332 Order granting Joint Intervenors 840227 motion to file out of time response to licensee second set of interrogatories Served on 840326 WOLFE.S J Atomic Safety and Licensing Board Panel DSB 089 84/03/23 Joint Petitioners TMI ip 22760 161 24X Fiche 50-289.84/03/23.8403260332
- 8403260337 Order granting extension of time until 840330 to respond to licensee & staff motions for summary disposition Served on 840326 WOLFE.8 J Atomic Safety and Licensing Board Panel DSB 088 84/03/23 Three Mile Island Alert ip 22750 164 24X Fiche 50-289, 88/03/23. 8403260337
- 8403260345 Response apposing Aamodt 840308 motion for reconsideration of ALA8-697 Motion advances no anguments not previously presented Certificate of Svc encl
 ZAHLER, R E Metropolitan Edison Co ZAHLER, R E Shaw, Pittman, Potts & Troubridge DSB 095 84/03/23 Atomic Safety and Licensing Appeal Panel 6pp 22760 184 24X Fiche 50-289, 84/03/23, 8403260345
- 8403270386 Amended response to UCS 840120 petition to show cause re emergency feedwater sys Amend necessary to reflect factual developments which have occurred since 840224 re licensee response Certificate of Svc encl BAXTER.T A General Public Utilities - QPU Service Corp BAXTER.T A Shaw. Pittman, Potts & Trowbridge DSB 195 0ffice of Nuclear Reactor Regulation, Director 24pp 22814 257 24X Fiche 50-289,84/03/26,8403270386
- 8403280343 Memorandum & Order CLI-84-3 on relevance of Board Notification 63-47 issues in proceeding Issues do not warrant reopening record Separate views of Commissioner Ollinsky and! CHILK:8 J Office of the Secretary of the Commission DSB 181 84/03/28 13pp 22787 (01 24x Fiche 50-289,84/03/28,8403280343
- 8403280332 Notifies that Commissioner Bernthal will tour plant on 840406 Served on 840328 * Commissioners DSB 159 84/03/28 1p 22787 172 24X Fiche 30-289.84/03/28.8403280352
- 8403300259 Notice of change in svc list Certificate of Svc encl WRISS,E R Harmon & Weiss DSD 211 84/03/30 3pp 22824-071 24X Fiche 50-289,84/03/30,6403300259

H General correspondence

- 8403160291 Expresses appreciation for receipt of missing page from Board Notification 84-002A E Blake admission of telling clients not to rept significant employment test rev to NRC is important item to investigate as part of mgt competency. LEWIS.M I Lewis. M 84/02/12 STOLZ.J F NRC No Detailed Affiliation Given 2pp 22660 143. 24x Fiche 30-289,84/02/12,8403160291.
- 8403060220 Urges NRC to grant immediate approval for restart of Undamaged reactor IMLER.R. Affiliation Not Assigned 84/02/27 NRC No Detailed Affiliation Given 1p 22515 177 24X Fiche 50-289:84/02/29, 8403060220
- B403130028 Urges NRC to put facility back in operation SHANCEY,R E Affiliation Not Assigned B4/03/05 NRC No Datailed Affiliation Given 2pp 22615 303 24X Fiche 50~289.84/03/05,8403130028
- 8403210141 Requests deletion of RC Arnold, former president of General Public Utils, from NRC mailings # General Public Utilities - GPU Service Corp 84/03/16 NRC -No Detailed Affiliation given 2pp 22707 280 24X Fichs 50~289,84/03/16.8403210141

- B403230001 Submits rev to distribution list & forwards personnel & title changes made to mailing labels
 HUKILL, H D General Public Utilities GPU Service Corp 84/03/20
 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp
 22726 350 24X Fiche 30-289,84/03/20,8403230001
- 8403270146 Requests Label 217087007114 for CW Smyth, licensing manager, be changed on NRC distribution of documents & correspondence Rev to enc lists, marked to reflect personnel & title changes for util smployees, also requested MUKILL, H D General Public Utilities GPU Service Corp 84/03/20 SCHAEFER, C NRC No Detailed Affiliation Given 6pp 22770 013 24X Fiche 50-289,84/03/20,8403270146
- J Insurance & indemnity information
- B403280010 Forwards Endorsements 72 & 73 to NELIA Policy NF-220 & Endorsements 62 & 63 to MAELU Policy MF-73 GERETY.H F General Public Utilities GPU Service Corp 84/03/22 SALTZMAN.J Défice of Nuclear Reactor Regulation. Director 5pp 22777 074 24X Fiche 50-289.84/03/22,8403280010
- P Operating license stage documents & correspondence
- 8403010010 FOIA request for documents re TMI-1 Restart Issues Task Force to be placed in PDR SMOLLY.5 C Union of Concerned Scientists 83/12/12 FELTON.J M Division of Rules and Records 1p. 22446 056 24X Fiche 50-289.83/12/12.8403010010
- 8403010014 Partial response to FOIA request for documents is TMI-1 Restart Issues Task Force Forwards documents listed on app Info also available in PDR FELTON, J M Division of Rules and Records 84/01/03 SHDLLY, 5 C Union of Concerned Scientists 2pp 22446 057 24X Fiche 50-287,84/01/03,8403010014
- --8305110054 Informs that reevaluation of Cycle 5 reload application, has identified two issues re nonconservative cladding swelling & rupture models & TAFY/TAGO penalty proposed by B&U that shoud be resolved prior to restart RUBENSTEIN, L S Assistant Director for Core & Plant Systems 83/05/02 LAINAS, C C Assistant Director for Operating Reactors 3pp 22446 212 24X Fich # 50-289, 84/01/03,8403010014
- --B403010020 Assigns recipients to THI-1 Restart Issues Task Force to verify that NRC requirements for restart torrectly identified & facility treated similar to all operating plants for other NRC requirements
 EISENHUT.D 0 Division of Licensing STAROSTECKI,R Division of Project & Resident Programs 83/04/15 JACOBS,R Region 1.
 Office of Director VAN VLIET,J , DIIANNI,D Division of Licensing 1p 22446 057 24% Fiche 50-287,84/01/03.8403010014
- --8403010023 Responds to 830415 memo & forwards "Rept of TMI-1 Restart Issues Task Force Members" Meeting requested to respond to questions
 HILLIAMS.M H TMI-1 Restart Issues Task Force 83/04/29
 EISENHUT.D O Division of Licensing STARGSTECKI,R Division of Project & Resident Programs | p 22446 060 24X
 Fiche 50-289.84/01/03.8403010014
- --B403010030 "Rept of TMI-1 Restart Issues Task Force Members "
 WILLIAMS, M., VAN VLIET, J., YOUNG, F. TMI-1 Restart Issues Task
 Force B3/04/29 150pp 22446 061 24X Fiche 50-289, 84/01/03.
- --8403010036 List of generic ltrs from 1978-1983 Related info encl * NRC - No Detailed Affiliation Given 84/01/03 27pp. 22446 247 24X Fiche 50-289,84/01/03.8403010014
- --B403010043 Forwards input to B30429 TMI-1 Restart Issues Tesk Force rept Info derived from ASLB partial initial decisions in restart proceedings Related info encl GOLDBERG. J R Office of the Executive Legal Director B4/01/03 WILLIAMS: M Division of Licensing 19pp 22446-274 24X Fiche: 50-289,84/01/03.8403010014
- 8403020392 FDIA request for Chilk 821019 memo to Dircks re postaccident sampling sys (NUREO-0737, Item II B 3) to be placed in PDR PEDRO, J NUS Corp 84/01/26 Division of Rules and Records 1: 22491 285 24X Fiche 50~289,84/01/26,8403020392
- 8403080393 Forwards DL Jensen 830517 1tr to N Palladino TP DDJ investigation of TM1 Document subj to Voigt 830526 FDIA request & 830919 appeal Document should be placed in FDR SMEENEY.M Office of the General Counsel 84/01/27 PDDL,MJ NRC No Detailed Affiliation Given ip 22567 354 24X Ficher 50-289,84/01/27,8403080393

- --B403080425 Responds to 830411 ltr re TMI-1 restart & DOJ investigation into allegations re mgt competence Investigation being pursued diligently but will not be completed by requested date

 JENSEN, D.L. Justice. Dept of 83/05/17 PALLADINO, N.J.

 Commissioners 4pp 22567 355 24X Fiche 50-289,84/01/27,
- 8403070053 Responds to 831214 ltr suggesting Commission refuse to restart Unit 1 until funding for Unit 2 cleanup in place Commission does not believe that Unit 1 restart & Unit 2 cleanup should be tied together PALLADINO.N J Commissioners 84/02/08 MORRIS, A E Advisory Council for Decontamination of TMM Unit 2 ip 22563 198 24x Fichs 50-287,84/02/08,8403070053
- 8403020169 Forwards table indicating review & insp status of TMI-1 restant certification items Current schedule calls for completion of all items not requiring hot functional testing by June 1984
 STOL7.J F Operating Reactors Branch 4 84/02/15 HUKILL, H D General Public Utilities OPU Service Corp 33pp 22491 101 24X Fiche 30-289,84/02/15,8403020169
- 8403020395 Responds to FOIA request for Chilk 821019 memo to Dircks re SECY-82-384 concerning status of TMI-1 NUREG-0737 items Forwards document Document also available in PDR FEELTON, J M Division of Rules and Records 84/02/15 PEDRO, J NUS Corg 19 22491 286 24X Fiche 90-289.84/02/15,8403020395
- 8403060222 Forwards application for amend to License DPR-50, changing Tech Specs to incorporate functional test program for reactor coolant pump snubbers to develop seal replacement program for hydraulic snubbers
 HUKILL,H D General Public Utilities GPU Service Corp 84/02/17
 FICHS 50-289,84/02/17,8403060222
- --8403060227 Application for amend to License DPR-50, changing Tech Spect to incorporate functional test program for reactor coolant pump snubbers & to develop seal replacement program for hydraulic snubbers Certificate of Svc encl HUKILL, HD General Public Utilities GPU Bervice Corp 84/02/17 2pp 22516 065 24% Fiche 50-289,84/02/17,8403060222
- --8403060236 Proposed Tech Spec changes re functional test program for reactor coolant pump snubbers & seal replacement program for hydraulic Snubbers * General Public Utilities GPU Service Corp 84/02/17 14pp 22516 066 24X Fiche 50-289,84/02/17,8403060222
- 8403040476 Requests expected response date for each TMI action item listed in encl within 10 days EISENHUT, D 0 Division of Licensing 84/02/21 HUMILL, H D General Public Utilities - OPU Service Corp 5pp 22552 320 24X Fiche 50-289, 84/02/21, 8403040476
- 8403010516 Summary of 840130-31 mmotings w/util at site in Dauphin County, PA re status, schedule & scope of implementation of selected NUREG-0737 action items Agenda & viewgraphs encl
 VAN VLIET, J Operating Reactors Branch 4 84/02/22 Operating Reactors Branch 4 130pp 22443 303 24X Fiche, 50-289, 84/02/22, 8403010516
- 8403040473 Requests expected completion dates for NUREG-0737 items & justification for proposed schedule for items that will not be completed by June 1984 by 840227 EIBENNUT.D 0 Division of Licensing 84/02/22 HUMILL,H D General Public Utilities OPU Service Corp 4pp 22552,325 24X Fiche 50-287.84/02/22,8403040473
- 8403120310 Forwards, for review, revised draft package of conditions from THI-1 restart proceedings for incorporation into OL Meeting proposed for Mar 1984 at THI-1 site to receive required add1 info & discuss comments on license conditions. STOLZ, J.F. Operating Reactors Branch 4 84/02/22 HUKILL, H.D. Oemeral Public Utilities OFU Service Corp. 14pp. 22615 306 24X Fiche 30-289,84/02/22,8403120310
- B40302041B Notification of 840309 meeting w/util in Middletown,PA to distuse draft package of license conditions assembled by NRC from TMI-1 restart proceeding decisions & forwarded to util by 840222 ltr
 VAN VLIET,J Operating Reactors Branch 4 84/02/24 STOLZ,JF. Operating Reactors Branch 4 3pp 22491 276 24X Fiche.50-289,84/02/24,840302041B

1

- 8403050472 Notification of 840308 meeting w/util in Bethesda. MD to discuss resolution of environ qualification deficiencies noted in Franklin Research Ctr technical evaluation rept & compliance w/10CFR50 40
 VAN VLIET.V Operating Reactors Branch 4 84/02/28 STOLZ. J F Operating Reactors Branch 4 2pp 22549 321 24X
 Fichs 50-289,84/02/28.8403060472
- B403060160 Forwards results of chemical analysis techniques performed on std test matrix solution as required by NUREG-0737. Action Item II B 3, per util 831122 ltr Response to Criterion 10 of draft BER complete
 HUKILL, H D General Public Utilities OPU Service Corp 84/02/29
 BTDLZ.J F Gperating Reactors Branch 4 5pp 22516 263 24X
 Fichs 50-289.84/02/29.8403060160
- B403060159 Forwards check to satisfy cost of 840126 OL Change Request 133 MUMILL, H D General Public Utilities GPU Service Corp 84/03/01 BTGLZ, J F Office of Nuclear Reactor Regulation, Director 1p 2316 361 24X Fiche 50-289,84/03/01,8403060159
- 8403060233 Forwards design info, instrument accuracy & response times to assist in post-implementation review of containment water level monitoring (NUREG-0737, Item II F 1), per 830719 request HUKILL, H D General Public Utilities GPU Service Corp 84/03/01 STOLZ, J F Operating Reactors Branch 4 opp 22517 317 24X Fiche 50-289, 84/03/01, 840306023
- 8403080039 Lists planned submittal dates for eight action items,per 840221 request HUKILL.H D General Public Utilities - GPU Service Corp 84/03/06 EIEEMHUT,D 0 Division of Licensing 2pp 22559 197 24X Fiche 50-289,84/03/02.8403080039
- 8403120004 Reevaluates response to NUREO-0737, Item III D 3 4, "Control Room Habitability." based on PRA technique for onsite & offsite sources App R mods will assure adequate smoke detection in control room HUMILL, H D General Public Utilities GPU Service Corp 84/03/02 STGLZ.J F Operating Reactors Branch 4 2pp 22586 306 24X Fichs 50-289,84/03/02,8403120004
- B403070125 Forwards list of draft license conditions considered complete, per B40222 request Conditions should be deleted Draft License Condition D 4 should specify Level I PRA & should be submitted by 840630 HUKILL, H D General Public Utilities GPU Service Corp. 84/03/05 BTOLTZ, J F Operating Resctors Branch 4 2pp 22576 061 24X Fiche 50-287, 84/03/05.8403070125
- B403220107 Forwards safety evaluation re TMI Item II K 2 17,
 "Potential for Voiding in RCS During Transients " Safety
 evaluation documenting completion of item and!
 BTOLZIJF Operating Reactors Branch 4 B4/03/05 HUKILL,H D
 General Public Utilities GPU Service Corp 4pp 22723, 288 24X
 Fiche 50-289.84/03/05.8403220107
- B403120056 Advises that B40305 ltr re draft license conditions contained incorrect data Correct completion date for Level 1 PRA is 860630.

 HUKILL.H D General Public Utilities GPU Service Corp B4/03/06 BT0LZ.J F Operating Reactors Branch 4 1p. 22586 281, 24X Fiche 50-289,84/03/06.8403120056
- 8403160006 Forwards summary of revised RM-A5 & RM-025 alarm setpoints to determine if setpoints could be lowered HUMILL.H D. General Public Utilities GPU Service Corp 84/03/12 GERUSKY.T Pennsylvanta. Commonwealth of, 2pp. 22654 320 24% Fiche 50-289,84/03/12,8403160006
- --8403160022 Forwards summary of condensor offgas radiation monitor responses to once-through steam generator leakage HUKILL.H D Gameral Public Utilities OPU Service Corp 84/03/12 BTOLZ, J F Operating Reactors Branch 4 Spp 22654,322 24X Fiche.50-289,84/03/12,8403160006
- 8403160024 Forwards summany of condensor offgas radiation monitor responses to once-through steam generator leakage
 HUMILL, HD General Public Utilities GPU Service Corp 84/03/12
 8TGLIZ, JF Operating Reactors Branch 4 3pp. 22653 355 24X
 Fiche 50-289,84/03/12,8403160024
- 8402070041 Board Notification 84-050: provides Commission policy statement & proposed rulemaking on environ qualifications EISENHUT, D @ Division of Licensing, 84/03/14. Atomic Bafety and Licensing Board Fanel 10pp 24X Fiche 50-000,84/03/14,8402070041

- 8403200099 Forwards schedule for implementation of activities for control of heavy loads, per NRC requests re NUREO-0612 Cask pit gate listing lugs will be modified by 841015.

 HUKILL.H D General Public Utilities OPU Service Corp 84/03/15 EIBENHUT, D Q Division of Licensing 3pp 22685 313 24X Fithe 50-289,84/03/15.8403200099
- 8403210014 UCS brief on Commission 840127 review of issues decided in ALAB-729 & ALAB-744 History of proceeding shows successive narrowing of issues until all unresolvable issues excluded W/Certificate of 8vc WEISS, ER Union of Concerned Scientists 84/03/19 44pp 22706 283 24X Fiche 50-289, 84/03/19, 8403210014
- 8403230040 Responds to NUREG-0737. Item II D i re relief & safety valve testing. per 840215 ltr Facility adequately represented by EPRI valve tests Precaution of 1.000 psig overly conservative HUKILL.H D General Public Utilities GPU Service Corp 84/03/20 BTOLZ.J F Operating Reactors Branch 4 1p 22724 331 24X Fiche. 50-289, 84/03/20. 8403230040
- B403230053 Notifies of assurances obtained from Design Date Labs re independent training auditor Lab meets requirements for independent auditor
 HUKILL.H D Oeneral Public Utilities GPU Service Corp STOLZ.J F Operating Reactors Branch 4 2pp 22724 340 24X Fiche 30-289, 84/03/20.8402330053
- @ Inspection reports, IE Bulletins & correspondence
- 8403080408 FOIA request for repts of insp carried out under Condition 2 of Nuclear Energy Liability policies for facilities CALBOYAS.C D Affiliation Not Assigned 84/02/07 Region 5, Dffice of Director 4pp 22567 341 24X Fiche 90-000,84/02/07, BA03080408
- 8403020169 Forwards table indicating review & insp status of TMI-1 restart certification items Current schedule calls for completion of all items not requiring but functional testing by June 1984
 STOL7.J F Operating Reactors Branch 4 84/02/15 HUKILL.H D General Public Utilities 0PU Service Corp 33pp 22491 101 24X Fiche 50-289,84/02/15.8403020169
- B403070282 Forwards IE Insp Rept 50-289/83-32 on B31101-840112 No violations noted STAROBTECKI, R Division of Project & Resident Programs. 84/02/21 HUKILL. H D Ceneral Public Utilities CPU Service Corp App 22547 079 24X Fichs 50-289:84/02/21.8403070282
- --8403070287 IE Insp Rept 50-289/83-32 on 831101-840112 No violations noted Major areas inspected actions on previous insp findings.plant operations (long-term shutdown). Tech Spec surveillence test program & update to NUREQ-0680, Suppl 4 YOUNG, F. BAUNACK, H., CONTE.R Region 1. Office of Director 84/02/06 15pp 22847 083 24X Fiche 30-289, 84/02/21, 8403070282
- B403080419 Responds to FDIA request for repts of insp carried out under Condition 2 to Nuclear Energy Liability policies for facilities NRC does not have repts FELTON. J M Division of Rules and Records B4/02/22 CALSOYAS. C D Affiliation Not Assigned 1p 22567 345 24X Fiche 50-000.84/02/22.8403080419
- 8403010363 EN-B4-005 on 840229, notice of violation & proposed imposition of civil penalties to be issued in amount of \$40,000 Action based on five violations re open containment isolation valves
 CRAIG.J. AXELRAD.J Director's Office, Office of Inspection and Enforcement 84/02/24 2pp 22433 013 24% Fiche 50-289,84/02/24.
- 8403090244 Responds to IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys "No safety-related applications of breakers identified at facility HUKILL,H D General Public Utilities 69U Service Corp. 84/02/27 MURLEY,T E Region i. 0ffice of Director ip 22572:226 24X Fiche 50-289,84/02/27,8403090244
- B401190072 IE Info Notice 84-13. "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation." Syc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp. 22909 239 24X Fiche 50-000,84/02/28,8401190072
- 8403080403 Discusses lE insp on 830824-1003 & forwards notice of violation & proposed imposition of civil penalty MURLEY.T & Region i, Office of Director 84/02/27 CLARK.F R general Public Utilities GPU Service Corp 4pp 22581 332 24% Fichs 50-289,84/02/27,8403080403

- --B4030B0407 Notice of violation & proposed imposition of civil penalty in amount of \$40,000 Violations noted written safety procedures not properly implemented & unidentified primary sys leaknate not classified as unusual event MURLEY, T & Region 1, Diffice of Director 84/02/29 App 22381 336 24% Fiche 50-289, 84/02/29, 84030804403
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list enc] ORACE J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24x Fiche 50-000.84/03/02,8402090007
- 8402090008 IE Info Notice 84~16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 122pp 22593 098 24% Fiche 50-000.84/03/02.8402090808
- 8402070009 IE Info Notice 84-15, "Reporting of Radiological Releases"
 Svc list encl
 JURDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc. 119pp 22553 217 24% Fiche 50-000,84/03/02,8402070009
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitragen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Past 830103) 84/03/05 Conselidated Edison Co of New York, Inc. 117pp 22553 336 24X Fishe 50-000,84/03/05,8402090011
- B402090024 IE Info Notice B4-09, Rev i, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys" Svc list encl JORDAN, E. L. Division of Emergency Proparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York Inc 118pp 22635 049 24X Fiche 50-000, 84/03/07, 8402070024
- 8402090028 IE Info Natice 84-18, "Stress Corrosion Cracking in PWR Sys " Syc list encl JURDANAEL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc. 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8402070031 IE Bulletin B4~02. "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50~000.84/03/12.8402090031
- 8403290186 Forwards IE Insp Rept 50-289/83-34 on 931212-30 No violations abserved MARTIN.T Division of Engineering & Technical Programs 84/03/13 HUMIEL.H D General Public Utilities OPU Service Corp 2pp 22803 305 24% Fiche 50-289,84/03/13,8403290186
- --8403290191 IE lasp Rept 50-289/83-34 on 831212-30 No violations identified Major areas inspected open items in areas of once-through steam generator repair, RCS requalification, PDRV.LERs & tast procedure review GRAY, E H . VITO.D . HEN.P Region 1, Office of Director 84/02/14 60pp 22803 307 24% Fiche 50-289, 84/03/13, 8403290186
- 8403210187 Forwards H Hukili 840307 ltr to JF Stolz re reviews of teaching performance, ability & attitude of UD in 1983 & RR Clark 840228 ltr to RC Deyoung responding to 840203 notice of Violation Certificate of Svc encl BAUSER, D B Shaw, Pittman, Potts & Troubridge DAUSER, D B Metropolitan Edison Co DS8 004 84/03/20 EDLES, G J, BUCK, J H, KOML, C N Atomic Safety and Licensing Appeal Panel 35pp 22710 289 24% Fiche 50-289,84/03/20,8403210187
- 8402070043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list enci JURDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/03/21. Consolidated Edison Co. of New York, Inc. 123pp 22823 229 24X Fiche 50-000,84/03/21,8402070043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Bafety-Related 8ys " 3vc list ene! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044

eports & related correspondence

pnnel exposure data.aircraft movement rport,leak reduction program safety valve challenges for

- 8403200068 Honthly operating rept for Feb 1984 W/840315 ltr MMYTH.C W, HUXILL, H D General Public Utilities - OPU Bervice Corp 84/02/29 MCDONALD.W C Office of Resource Management, Director 6pp 22685 096 24X Fiche 50-289.84/02/29,8403200068
- 8403210076 Forwards "Number of Personnel & Man Rems by Work & Job Function:0783" & "Aircraft Movements at Harrisburg Intl Airport:0783" HUNILL H.D General Public Utilities - QPU Service Corp 84/03/01 MURLEY.T E Region 1. Offsice of Director 2pp 22705 077 24X Fiche 50-289:04/03/01.8403210076
- --8403210088 "Aircraft Movements at Harrisburg Intl Airport.CY83 "
 # General Public Utilities GPU Service Corp 83/12/31 5pp
 22705 081 24% Fiche 50-289,84/03/01.8403210076
- B403210138 Forwards personnel exposure rept for 1983, including total count of personnel monitored & number of personnel in each whole body exposure range HUKILL, H D General Public Utilities GPU Service Corp 84/03/01 MURLEY, T E Region 1, Office of Director 1p 22707 088 24X Fiche 50-287,84/03/01,8403210138
- ~-8403210146 Personnel exposure rept For 1983 * General Public Utilities - GPU Service Corp 83/12/31 2ps 22707 089 24% Fiche 50~289,84/03/01.8403210138
- 8. Reportable occurrences, LERs & related correspondence
- 8403300074 PNB-I-84-003 on 840324, male phoned Jersey Central Power & Light Customer Svc Ctr & notified that FFA will start demolishing plants Ogster Creek implemented emergency contingency plan & TMI increased security awareness MADDEN, W. JOYNER, J. Region 1, Office of Director 84/03/26 ip 22822 088 24% Fiche 50-000, 84/03/26, 8403300074
- T Hearing transcripts on non-antitrust matters
- 8403150349 Transcript of 840215 public meeting in Middletown.PA to receive comments on draft suppl to programmatic EIS Pp i-101

 * Commissioners 84/02/15 102pp 22649 110 24X
 Fiche 50-289.84/02/15, 8403150349
- 8403050073 Transcript of 840301 telephone conference in Bethesda.MD resteam generator repair Pp 180-195

 * Atomic Bafety and Licensing Board Panel 84/03/01 19pp 22490 045 24X Fiche 50-289.84/03/01.8403050073
- 8403280153 Forwards documents for inclusion in Chairman 840223 testimony before Senate Subcommittee on Nuclear Regulation. Committee on Environ & Public Works # Office of Congressional Affairs 84/03/08 Record Services Branch (Document Control Desk) 1p 22809:274 24X Fiche 80-289.84/03/08.8403280153
- --8403280160 Statement of JK Asselstine on 840223 re Commission authority to issue temporary OL, review of NRC NBHC determination pertaining to steam generator repairs at TMT-1 & licensing reform legislation
 ASBELGTINE. J K Commissioners 84/02/23 8pp 22809 308 24X Fiche 50-289,84/03/08,8403280153
- B403270335 Transcript of Commission B40323 affirmation/discussion & vote in Mashington, DC re request for denial of renewal of Seabrook Unit 2 CP & SECY-84-48 concerning review of ALAB-724 in matter of Met Ed Pp 1-3 commissioners B4/03/23 dpp 22787-354 24x Fiche 50-000,84/03/23,8403270335
- U Congressional/Executive Correspondence
- 8402220291 Responds to 831209 ltr in opposition to restart until all outstanding issues resolved PALLADIND, N J Commissioners 84/01/31 HEINZ, J Senate 1p 22884 306 24X Fiche 50-289,84/01/31,8402220291.
- --8403090003 Responds to 831212 ltr expressing contern re-protracted time period for resolving TMI-1 restart issue Notice to parties issued on 840127 and W/o end!
 PALLADINO, N J Commissioners 84/01/31 KOLTER, J P. House of Rep. 1p. 22584 305 24X Fiche 50-289,84/01/31,8402220291

- --8403070004 Responds to 831212 ltr expressing concern re protracted time period for resolving TMI-1 restart issue Notice to parties issued on 840127 encl W/o encl PALLADINO, N J Commissioners 84/01/31 MURPHY, A J House of Rep 1p 22584 307 24X Fiche 50~289,84/01/31,8402220271
- --8403090005 Responds to 831212 ltr expressing concern re protracted time period for resolving TMI-1 restart issue Notice to parties issued on 840127 encl Wa encl PALLADINN, N J Commissioners 84/01/31 MURTHA, J P House of Rep 1p 22584 308 24X Fiche 50-269,84/01/31,8402220291
- --8403090007 Responds to 831212 ltr expressing concern re protracted time period for resolving TMI-1 restart issue Notice to parties issued on 840127 encl W/o encl PALLADINN, N J Commissioners 84/01/31 CLINGER, W F House of Rep 1p 22584 309 24X Fiche 50-289,84/01/31,8402220291
- --8403090008 Responds to 831212 ltr expressing concern re protracted time period for resolving TMI-1 restart issue Notice to parties issued on 840127 encl W/o encl PALLADINO, N J Commissioners 84/01/31 GAYDDS, J M. House of Rep 1p 22584 310 24X Fiche 50-289,84/01/31,8402220291
- --8403070007 Responds to 831212 ltr expressing concern re protracted time period for resolving TMI-1 restart issue Notice to parties issued on 840127 encl W/o encl PALLADINO.N J Commissioners 84/01/31 RITTER.D House of Rep ip. 22584 311 24X Fiche 50-289,84/01/31.8402220271
- --8403070010 Responds to 831212 ltr expressing concern re protracted time period for resolving TMI-1 restart issue Notice to parties issued on 840127 encl W/o encl PALLADING.N J Commissioners 84/01/31 HARRISON,F House of Rep. 1p 22584 312 24X Fiche 50-289.84/01/31,8402220291
- --B403070013 Expresses concern re-protracted time period for resolution of issues surrounding TMI-1 restart Commission should place primary emphasis on ability of util mgt to operate plant safely GAYDOS, J M , KOLTER, J P , MURPHY, A J House of Rep. 83/12/12 PALLADINO, N , OILLINBKY, V , ROBERTS, T Commissioners. 2pp 22584 331 24X Fiche 50-289,84/01/31,8402220291
- --8403090011 Expresses concern re protracted time period for resolution of issues surrounding TMI-1 restart Commission should place primary emphasis on ability of util mgt to operate plant safely HARRISON, F. House of Rep. 83/12/13 PALLADIND, N., GILINGKY, V. ROBERTS, T. Commissioners, 2pp. 22584 327 24% Fiche 50-289,84/01/31,8402220291
- 8403070053 Responds to 831214 ltr suggesting Commission refuse to restart Unit 1 until funding for Unit 2 cleanup in place Commission does not believe that Unit 1 restart & Unit 2 cleanup should be tied together PALLADINO.N J Commissioners. 84/02/08 MORRIS,A E Advisory Council for Decontamination of TMI Unit 2. 1p 22543 178 24X Fichs. 50-289,84/02/08,8403070053
- --8403070060 Responds to 831213 ltr re criminal indictment of Met Ed & cleanup of Unit 2 Commission does not believe delaying restart would accelerate Unit 2 cleanup Unit 1 restart & Unit 2 cleanup Unit 1 restart & Unit 2 cleanup Should not be tied together PALLADINO.N J Commissioners 84/02/08 MORRIB, A E. House of Rep. 1p 22563, 199 24X Fiche 50-289,84/02/08,8403070053
- --B403070069 Responds to B31207 ltr urging Commission not to authorize restart of Unit I Commission views on restart set forth in encl 840127 notice to parties Commission does not believe Unit I restart & Unit 2 cleanup related PALLADINO, N J Commissioners B4/02/08 QEKAB, O W House of Rep 1p 22563 200 24% Fiche 50-289.84/02/08.8403070053
- --8403070073 Urges Commission not to accept recommendation to restart Unit 1 in light of mpt integrity review & criminal proceedings & slow pace of Unit 2 cleanup GEKAB, 0 W. House of Rep. 83/12/07. PALLADINO.N.J. Commissioners ip 22563 217 24X Fiche 50-289,84/02/08.8403070053.
- --8403070076 Advises of convictions re Unit 1 restart. Due to criminal indictments & belief that Unit 1 revenue should go directly toward Unit 2 cleanup. recommends against restart WALKER, R. 8 House of Rep. 83/12/13 PALLADING, N , ASSELSTINE, J BERNTHAL, F. Commissioners ip 22563 218 24x Fiche: 50-289, 84/02/08, 8403070083
- 8402220288 Ack receipt of 840131 reaffirmation of Commission 840127 decision re-restart Further elaboration of decision basis requested.
 HEINZ, J Senate. 84/02/14 PALLADING, N J Commissioners 1p 22336:360. 24X Fiche 50-289,84/02/14,8402220288

- --8402220303 Submits opposition to further consideration of restart until all outstanding issues resulved HEINZ, J Senate 83/12/09 PALLADINO, N Commissioners to 22336 362 24X Fiche 50-289,84/02/14,8402220288
- 8403200191 Responds to 831208 & 18 ltrs re possibility of restart decision prior to further evidentiary hearings on mgt competence & integrity ASLAB decision will be considered by Commission upon issuance PALLADIND.N J Commissioners 84/03/19 SPECTER.A Senate 2pp 22698 003 24% Fiche 50-289,84/03/19,8403200191
- --8403200200 Comments on rept that Commission recommended authorization to operate at 25% power w/commencement as early as Jan 1984 Authorization contradicts previous Commission assurances Evidentiany hearings recommended SPECTER.A Benate 83/12/08 PALLADINO.N J Commissioners ip 22698 027 24% Fiche 50-289.84/03/19.8403200191
- --B403200205 Responds to B31117 ltr re resolution of mgt competence & integrity issues prior to restart Questions about competence & integrity will be adequately resolved prior to restart decision
 PLAINE.H Dffice of the General Counsel B3/11/23 SPECTER.A
 Senate 2pp 22698 028 24X Fiche 50-289.84/03/19.8403200191
- --8403200211 Advises Commission to hold necessary hearings to resolve outstanding issues discussed at 831216 hearing SPECTER, A Senate 83/12/18 PALLADINO, N Commissioners 2pp 22698 030 24X Fiche 50-289,84/03/19,8403200191

V Operator Examinations

8403120016 Submits list of dates on which individual DD teaching ability, attitude & willingness to cooperate monitored DD no longer licensed operator & no longer training licensed operators or trainees
HUKILL.H D General Public Utilities - GPU Service Corp 84/03/07
STOLZ.JF Operating Reactors Branch 4 1p 22586 263 24X
Fiche 50-289,84/03/07,8403120016

DOCKET 50-293 PILORIM NUCLEAR POWER STATION, UNIT i

F Security, medical, emergency & fire protection plans

- 8403060034 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee.per 810709 Generic Ltr 81-27 W/o request, entire plan will be placed in PDR VASBALLO. D B (perating Reactors Branch 2 84/02/10 HARRINGTON. M D Boston Edison Co 2pp 22328 331 24X Fichs 50~293,84/02/10,8403060034
- 8403120305 Responds to 830720 petition requesting that NRC take immediate action to remedy alleged serious deficiencies in offsite emergency response plans Request denied in part, based on encl interim Director's Decision 84-05 DEYOUNGAR C Director's Office. Office of Inspection and Enforcement 84/02/27 ERNSTAM D Massachusetts Public Interest Research Group 2pp 22619 101 24X Fiche 50-293,84/02/27,8403120305
- --8403120308 Interim Director's Decision DD-84-5 denying in part, Massachusetts PIRG 830730 2 206 petition, requesting NRC action to remedy allegations re deficiencies in offsite emergency response plans DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 84/02/27 31pp 22617 103 24X Fiche 50-293,84/02/27,8403120305
- --8403120311 Notice of issuance of Director's Decision DD-84-5 re 830720 2 206 petition re deficient emergency response plans DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 84/02/27 2pp 22619 134 24X Fiche 50-293,84/02/27,8403120305
- --8402020073 Requests further review of issue re evacuation time estimate.per NRC/FEMA 801104 MOU Evaluation of potential bottlenecks to evacuation of plume emergency planning zone identified in BER (NUREO-0022 Suppl 5), requested JORDAN: E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/01/20 KRIMM:R W Federal Emergency Management Agency 2pp 22619 136 24X Fiche 50-293.84/02/27, 8403120305
- 840314024B Responds to 840112 ltr submitting current status of facility safeguards info protection sys 8ys in accordance w/provisions of 10CFR73 21 & acceptable VASSALLO, D B Operating Reactors Branch 2 84/02/27 HARRINGTON.W D Boston Edison Co 3pp 22636 340 24X Fiche 80-293.84/02/27.840314024B

- 8403090147 Clarifies NRC 831102 safety evaluation for 10CFR50.App R. Items III G 3 & III L re number of fuses to be removed if fire occurs in cable spreading room of control room Correct number of fuses is 12.not six
 HARRINGTON.W D Boston Edison Co 84/03/05 VASSALLO.D B
 Operating Reactors Branch 2 ip 22575 128 24X
 Fiche 50-293.84/03/05.84/3090147
- 8403130255 Forwards Rev 6 to security force training & qualification plan re consolidation of similar crucial tasks, changes in conformance to physical changes to facility & verbiage mods Rev withheld (ref 10CFR2 790 & 73 21)
 HARRINGTON.W D Boston Edison Co 84/03/05 MURLEY, T E Region I. Office of Director 1p 22607 137 24X Fiche 50-293,84/03/05,840330255
- 8403300232 Forwards staff comments on detailed control room design review program plan.per NUREG-0737.Suppl 1 Some areas of plan require further description VASSALLO,D 0 Operating Reactors Branch 2 84/03/06 HARRINGTON.H D Boston Edison Co 18pp 22844 264 24X Fichs 50-293.84/03/06.8403300232
- 8403150018 Informs that FEMA will transmit.on or before 840402.proposal refurther review of issues concerning evacuation time estimates for population, including work program, estimate of resources & schedule for completion of major components KRIMH.R W Federal Emergency Management Agency 84/03/09 JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) ip 22640 330 24% Fiche 50-293.84/03/09, 8403150018
- 8403150177 Forwards Rev 1 pages to 820625 App R response, containing fire protection analyses & recommendations for facility W/six oversize drawings Aperture cards are available in PDR HARRINGTON W D Boston Edison Co 84/03/09 VASSALLO, D B Dperating Reactors Oranck 2 62pp 22643 299 24X Fiche 50-293,84/03/09,8403150177
- 8403190243 Notification of 840418 workshop in King of Prussia, PA to discuss lessons learned from recent App R fire protection safe shutdown insp ½ topics described in IE Info Notice 84-07 Agenda for workshop enci HURLEY. TE Region 1. Office of Director 84/03/09 D'TOCLE, J D Consolidated Edison Co of New York, Inc COUNSIL, W 9 Northeast Nuclear Energy Co (subs of Northeast Utilities) RHDDE, G K Niagara Mohawk Power Corp 35p 22672 062 R4X Fiche 50-000,84/03/09,8403190243
- 8403200098 Forwards final exercise rept prepared by FEMA for 830629 joint exercise of state & local radiological emergency preparedness plans MARTIN.T T Division of Engineering & Technical Programs 84/03/15 HARRINGTON, W D Boston Eduson Ca 3pp 22697 079 24X Fiche 50-293,84/03/15.8403200098
- G Adjudicatory correspondence
- 840326000) Order extending time until 840329 for Commission to act to review Director's Decision DD-84-5 Served on 840323 CHILKS J Uffice of the Secretary of the Commission DBB 080 84/03/23 Commissioners ip 22748 357 24X Fiche 50-293,84/03/23,8403260001
- 8403300002 Order extending time util 840405 for Commission to act to review Director's Decision DD-84-5 Served on 840329 CHILK.S J Office of the Secretary of the Commission DSB 207 84/03/29 Commissioners 1p 22822 105 24X Ficha 50-293.84/03/29,8403300002
- J Insurance & indemnity information
- B403i40029 Forwards Endorsement 65 to MAELU Policy MF-58 & Endorsements B1 & 86 to NELIA Policy NF-188 SINISI.J M Marsh & McLennan. Inc 84/03/05 SALTZMAN, J D Assistant Director for State & Licensee Relations 4pp 22633 015 24X Fiche 50-293,84/03/05,8403140029
- P Operating license stage documents & correspondence
- 840315000B Informs of actions taken re coordination of drywell activities for duration of Refueling Outage 6 & recirculation piping replacement project HARRINGTON. TE Boston Edison Co 84/02/08 MURLEY. TE Region 1, Office of Director 2pp 22643 297 24X Fiche 50-293, 84/02/08, 8403150008

- 8403140340 Summary of 831215 meeting w/0E & Mark I Owners Group in Bethesda: MD re Mark I containment wetwell-drywell vacuum breaker design methodology SIEGEL: B L. Operating Reactors Branch 2 84/02/21 Operating Reactors Branch 2 51pp 22635 198 24X Fichs 50-000.84/02/21, 8403140340
- 8403140272 Forwards corrected Page 22 for 830405 Amend 73 to License DPR-35 Change adds equal or less than symbols inadvertently left off 1.085 psig limiting safety sys setting for Tech Spec Section 2 2A LEECH.P H Operating Reactors Branch 2 84/02/22 HARRINGTON,W D Boston Edison Co 2pp 22636 329 24X Fiche 50-293,84/02/22.
- --8403140279 Corrected Page 22 to 830405 Amend 73 re 1,085 psig limiting safety sys setting for Tech Spec Section 2 2A e Boston Edison Co 83/04/05 1p 22636 331 24X Fiche 50-273,84/02/22.8403140272
- 8403010324 Forwards updated Rev 1 to "Inservice Testing Program," w/boundary coordinate info provided for locating valves & pumps on insp drawings HARRINGTON, W D Boston Edison Co 84/02/27 VASSALLO, D B Operating Reactors Branch 2 2pp 22432 014 24X Fiche 50-293.84702/27.8403010324
- ---8403010327 Updated Rev 1 to "Inservice Testing Program " # Boston Edison Co 84/02/27 40pp 22432 016 24X Fiche 50-293,84/02/27,8403010324
- B403090152 Forwards GE B40304 ltr supporting proposed change to control rod drive weekly surveillance Tech Specs.per P Leech B40203 telcon request HARRINGTON.W D Doston Edison Co B4/03/05 VASSALLO.D B Operating Reactors Branch 2 4pp 22575 127 24X Fiche 30-273.64/03/05.8403090152
- B403090240 Summary of B40216 meeting w/Northeast Nuclear Energy Co.
 Boston Edison Co.Vermont Yankee Nuclear Power Co & Teledyne
 Engineering Svcs in Waltham MA re addi Mark I torus
 structural analysis List of attendees encl
 SHEA: J Operating Reactors Branch 5 84/03/07 CRUTCHFIELD, D
 Operating Reactors Branch 5 49p 22572 298 24X
 Fiche 50-000.84/03/07.8403090240
- 8403140107 Forwards results of secondary containment leak rate Test B 7 3 performed on 831213 to verify integrity of containment at Refueling Dutage & prior to refuel Results satisfactory HARRINGION W D Boston Edison Co 84/03/07 Office of Nuclear Reactor Regulation, Director 4pp 22620 358 24X Fiche 80-293.84/03/07.8403140107
- B403130111 Responds to B31230 request that Section V(A) of NRC order issued to util on B2011B be terminated Based on improvements in organizational structure & methods of communicating status of safety-related activities, requirement terminated MMRLEV.T E Region 1. Office of Director B4/03/09 HARRINOTON.W D Boston Edison Co 2pp 22A40 214 24X Fiche 50-293.84/03/09.8403150111
- --8403150117 Requests that NRC B20118 order requiring that corporate onsite representative position be established to provided daily audit of plant operations be terminated Organizational changes have reduced need for onsite representative HARRINOTON, W D Boston Edison Co 83/12/30 MURLEY, T E Region 1, Office of Director 2pp 22640 216 24X Fiche 50-293, 84/03/09,8403150111
- 8403:50275 Generic Ltr 84-07 to all licensees of BMRs re procedural guidance for pipe replacement at BMRs Svc list encl EISENHVI.D Q Division of Licensing 84/03/14 Commonwealth Edison Co 20pp 22823 354 24X Fiche 50-000,84/03/14.8403150275
- B403270010 Application for amend to License DPR-35, consisting of Proposed Tech Spec Change 84-02 allowing increased core flow HARRINGTON, W D Boston Edison Co 84/03/20 VASSALLO, D B Operating Reactors Branch 2 3pp 22769
- ---9403270015 Proposed Tech Spec Change 84-02.ellowing increased core flow * Boston Edison Co 84/03/20 2pp 22769 168 24X Fiche 50-293.84/03/20.8403270010
- --9403270022 "Safety Review of Pilgrim Nuclear Power Station.Unit 1 at Core Flow Conditions Above Rated Flow Throughout Cycle 6 " FISCHER.D 1., ORIDLEY,R L General Electric Co NEDD-30242 83/08/31 34pp 22769 170 24X Fiche 50-293.84/03/20.8403270010

- --8403270024 Suppl 1 to "Safety Review of Pilgrim Nuclear Power Station Unit 1 at Core Flow Conditions Above Rated Flow for End-of-Cycle 6 " FISCHER, D L , GRIDLEY, K L General Electric Co NEDD-30242 S01 83/09/30 15pp 22769 201 24X Fiche 50-293.84/03/20,8403270010
- 8403270055 Application to amend License DPR-35, consisting of Proposed Change 84-01, changing Tech Specs to remove details of Section XI inservice insp program HARRINGTON, W D Boston Edison Co 84/03/20 VASSALLO, D B Operating Reactors Branch 2 4pp 22774 115 24X Fiche 50-293,84/03/20,8403270055
- -8403270143 Proposed Tech Spec changes, removing details of Section XI inservice insp program
 * Boston Edison Co 84/03/20 10pp 22774 119 24X Fiche 50-293,84/03/20,8403270055
- Q Inspection reports. IE Bulletins & correspondence
- 8403020262 Forwards IE Insp Rept 50-293/83-26 on 831212-16 No violations identified MARTIN,T T. Region I. Office of Director 84/02/09 HARRINGTON-W D 80ston Edison Co 2pp 22440 081 24X Fiche. 50-293,84/02/09.8403020262
- -8403020272 IE Insp Rept 50-293/83-26 on 831212-16 No violations odokuz/z iz insp rept 50-27/33-20 in dolziz-to No voicetions identified Major areas inspected procedural & personnel qualifications for ultrasonic exam of recirculation piping weld intergranular stress corrosion cracking NARROW.L : MCGREARTY.R A : MANOLY.K A Region 1: Office of Director 84/02/07 8pp 22440 083 24X fiche 50-293,84/02/09,8403020262
- 8403020315 Forwards IE Insp Rept 50-293/84-02 on 840103-05 & 09-13 No violations observed

 MARTING T Division of Engineering & Technical Programs

 HARRINOTON, W D Boston Editon Co 2pp 22437:007 24X

 Fichs 50-273,84/02/17,8403020315
- --8403020397 IE Insp Rept 50-293/84-02 on 840103-05 & 09-13 No violations identified Major areas inspected recirculation piping replacement program, including welding activities, plant maint program & ultrasonic test program GRAY,E H . MCSREARTY,R . SHAUB,T Region 1, Office of Director 84/02/09 11pp 22439 009 24X Fichs 50-273,84/02/17,8403020315
- B403010324 Forwards updated Rev 1 to "Inservice Testing Program." w/boundary coordinate info provided for locating velves & pumps on insp drawings
 HARRINGTON.W D Boston Edison Co B4/02/27 VABBALLO.D B
 Operating Reactors Branch 2 2pp 22432:014 24X
 Fithe 50-293,84/02/27,8403010324
- 8403090047 Responds to IE Bulletin 83-07, "Apparently Fraudulent Products Sold by Ray Miller, Inc " Suspect matl not supplied or used at facility DARRINGTON, W D Boston Edison Co 84/02/27 MURLEY, T E Regio Office of Director 2pp 22576 002 24% Fiche 50-293,84/02/27,8403090047
- 8401170072 IE Info Notice 84-13. "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list whet. JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/02/2B Consolidated Edison Co of New York, Inc. 115pp 22709 237 24X Fiche 50-000,84/02/28,8401170072
- B403070330 Ack receipt of B40213 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-293/83-23.
 STARDSTECKI,R Division of Project & Resident Programs 84/02/28 HARRINGTON W D Boston Edison Co 1p 22546 354 24X Fiche: 50-293,84/02/28,8403070330 ams 84/02/28 24X
- ---8403070341 Responds to NRC 831208 itr re violations noted in IE Insp. Rept 50-293/83-23 Corrective actions NOP raised mgt policy issues re-procurements which have taken longer than expected to resolve Completion expected by 840402
 HARRINGTON.H D Boston Editor Co 84/02/15 STAROSTECKI.R Division of Project & Resident Progrems. ip 22546-355 24X Fiche. 50-293,84/02/28,8403070330
- 8403150067 Forwards IE Insp Rept 50-293/84-01 on 840101-0206 No Viblations noted Concern identified re program for feedback of openating experiences BTARGETECHI, R Division of Project & Resident Programs 84/03/01 MARKINGTON:W D Boston Edison Co 2pp 22641 025 24X Fithe: 50-293,84/03/01,8403150067

- --B403150073 IE Insp Rept 50-293/B4-01 on B40101-0206 No violations noted Major areas inspected operational safety verification, plant event followop, surveillance & maint activity review & followop on insps required by IE Dulletin 84-01 JOHNSON, J. MCGRIDE, M., BDRCHARDT, R. Region 1, Office of Director 84/02/23 15pp 22641 027 24% Fiche 50-273,84/03/01,8403150067
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE, J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000,84/03/02,84020900007
- 8402090008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24% Fiche 50-000.84/03/02,8402090008
- 8402070009 IE Info Notice 84-15. "Reporting of Radiological Releases" JORDAN: EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 119pp 22553 217 24% Fiche 50-000.84/03/02.8402070007
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitragen Cooling Components Belaw Nil Ductility Tamp " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402070011
- B402090024 IE Info Notice 84-09, Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JURDAN: E.L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/07 Consolidated Edison Co of New York: Inc 118pp 22635 049 24X Fiche 50-000, 84/03/07, 8402070024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Bys " Svc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8403130212 Informs of recent plant developments MH McBride appointed resident inspector, effective 831211 Ultrasonic insps of stainless steel piping sections reported indications of cracking GE contacted to assist in managing pipe repairs. MURLEY.T E Region 1. Office of Director 84/03/08 Plymouth, MA 2pp 22605 063 24% Fiche 50-273,84/03/08.8403130212
- 8402090031 IE Bullstin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Bafety Sys " Syc list encl DEYOUNG,R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000.84/03/12,8402090031
- 8403260313 Ack receipt of 840301 ltr informing NRC of corrective & preventive actions taken re violations noted in IE Insp. Rept 50-293/83-24 HARRISTECKI.R Division of Project & Resident Programs HARRINGTON.W D Boston Edison Co 1p 22753 155 24 Fiche 50-293,84/03/20,8403260313
- --8403260317 Responds to NRC 840207 itr re violations noted in IE Insp Rept 50-293/83-24 Corrective actions personnel advised of importance of adherence to procedure re logging of temp during reactor heatups & cooldowns HARRINGTON, W D Boston Edison Co 84/03/01 BTARDSTECKI, R Division of Project & Resident Programs 2pp 22753 136 Fiche 50-293,84/03/20,8403260313
- 8403270055 Application to amend License DPR-35, consisting of Proposed Change 84-01, changing Tech Specs to remove details of Section XI inservice insp program HARRINOTON, W D Boston Edison Co 84/03/20 VASSALLO, D D Operating Reactors Branch 2 App 22774 115 24X Fiche 50-293,84/03/20,8403270055
- --8403270143 Proposed Tech Spec changes, removing details of Section XI Inservice insp program * Boston Editon Co 84/03/20 10pp 22774 119 24X Fichs 50-293,84/03/20,8403270055
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York Inc 123pp 22823 227 24% Fiche 50-000.84/03/21,8402090043

- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc list entl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 64/03/21 Consolidated Edison Co of New 22933 Q01 24x Fiche 50-000.84/03/21.8402090044 135pp
- R Periodic operating reports & related correspondence
- 8403120027 "Radioactive Effluent & Waste Disposal Rept Including Radiological Impact on Humans, Jul-Dec 1983 " W/840301 1tr BOWMAN.C E Boston Edison Co 83/12/31 MURLEY, T & Region 1, Office of Director 74pp 22588 047 24% Ficha 50-293.83/12/31. 8403120027
- 8403200164 Monthly operating rept for Feb 1984 W/840313 ltr. HAMILTON, P. HARRINGTON W. D. Boston Edison Co. 84/02/29. 7pp 22697 137 24X Fiche 30-293,84/02/29,8403200164
- S Reportable occurrences. LERs & related correspondence
- 8305040149 Forwards, "Condensate Demineralizer Resin Migretion Through Plant Vent & Standby Gas Treatment Sys," technical review rept No addl involvement necessary PELLET, J L Reactor Operations Analysis Branch. 83/04/19 SEYFRIT, K V Reactor Operations Analysis Branch 1p 22789 300 24% Fiche 50-293,83/04/19,8305040149
- --8305040155 "Condensate Demineralizer Resin Migration Through Plant Vent
- 8403260233 Forwards summary list of deficiencies identified per 10CFR50 55(e), Part 21 & potential generic ltr repts for Edmonts
 STAROSTECKI,R Division of Project & Resident Programs 84/02/28
 Region 1, Office of Director 7pp. 22754,065 24x
 Fiche 50-000,84/02/28,8403240233
- 8403070283 PND-1-84-021 on 840301. radiographer working at field site could not fully retract 24 i Ci Ir-192 to safe shielded position Caused by improperly connecting pigtail to guidetube Whole body dose read 40 mrem.

 ROWE, C., GLENN, J. Region 1, Office of Director 84/03/02 ip 82546 359 24X Fiche 50-293.84/03/02.8403070283
- DOCKET 50-295 ZION NUCLEAR POWER STATION, UNIT 1 F Security, medical, emergency & fire protection plans
- 8403140082 Public version of Rev 12 to Emergency Plan Implementing Procedure EPIP 700-1. "Emergency Phone List " W/831021 receipt form & JM Felton 840312 release memo NYKIRK, J W. PLIML, O Commonwealth Edison Co. 83/10/26 24x Fiche 50-299.83/10/26.8403140082
- 8403280117 Public version of Rev 7 to Emergency Plan Implementing Procedure EPIP 440-1, "Emergency Communications Sys & Operational Tests" W/840110 procedure change request form & JM Felton 840322 release memo FLIML-9 Commonwealth Edison Co. 84/01/04 DENTON: R NRC -84/01/04 DENTON, H R NRC - No 22811 167 24X PLIME, Gommonwealth colson to Detailed Affiliation Given 21pp Fiche 50-295,84/01/04,8403280119
- 8403020003 Revised emergency implementing procedures, including Rev 1 to Procedure EPIP 100-1, "Acting Station Director" W/840301 1tr * Commonwealth Edison Co 84/02/21 8pp 22442·187 24X Fiche,50-295,84/02/21,8403020003
- 8403120326 Notification of 840308 meeting w/util in Bathasda,MD to discuss status of implementation of fire protection mod & proposed interim compensatory measures NORRIS,J A Operating Reactors Branch 1 84/03/01 VARQA,S A Operating Reactors Branch 1, 2pp 22596 353 24% Fiche 50-295,84/03/01,8403120326
- 8403190314 Forwards IE Insp Repts 50-295/83-27 % 50-304/83-28 on 831122-1228 % 840202 % notice of violation Concerns re mgt control inadequacies.per TMI Action Plan Item II F []. "Noble Gas Effluent Monitor," sypressed MIND, J A Division of Radiological & Materials Safety Programs 84/03/01 RED, C Commonwealth Edison Co 2pp 22673 196 Fiche 50-295,84/03/01,8403190314
- --8403170321 Notice of violation from insp on 831122-840202 HIND, J A Division of Radiological & Materials Safety Programs 84/03/01 3pp 22673 198 24% Fiche 80-295,84/03/01,8403170314

- --8403190334 IE Insp Repts 50-275/83-27 & 50-304/83-28 on 831122-840202 Violation noted failure to follow plant procedures re source handling to evaluate radiological hazards & to control access to high radiation area LOVENDALE,P C , NICHOLSON,N , GREGER,L R Region 3. Defice of Director 84/02/29 14pp 22673 201 24X Fichs 50-295,84/03/01. Director 84/02/29 8403190314
- 8403130185 Discusses evaluation of State of IL & local plans & preparedness for facilities Plans adequate to protect health & safety of public Approval of public alert notification systemational on verification of criteria of NNREG-0659

 SPECK.S W Federal Emergency Management Agency 84/03/02

 DIRCKS.W J Office of the Executive Director for Operations ip 22613 316 24X Fiche 50-295,84/03/02,8403130185
- 8403120051 Notifies of 840323 workshop on fire protection safe NOTICE NOTITIES OF MAUSCA WORKSHOP ON THE PROTECTION SATE
 shutdown requirements of 10CFRSD, App R in Rosemont, IL to
 discuss IE Info Notice 84-09 & provide addl shutdown
 analyses 8/or mod guidance Agenda encl

 BPESBARD, R L Division of Emergency Preparedness & Operational
 BUSBARD, R L Division of Emergency Preparedness & Operational
 BUSBARD, R L B4/03/06 REED, C Commonwealth Edison Co 3pp
 22970 24X Fichs 50-295, 84/03/06, 8403120051
- B403210087 Revised Page 3 to Emergency Plan Implementing Procedura EPIP-180-1, "Rad/Chem Director" W/B40320 transmittal & receipt form PLIME, 0 Commonwealth Edison Co 84/03/07 2pp 22705 320 24X Fiche' 50-295,84/03/07,8403210089
- B403190193 Revised pages to Emergency Plan Implementing Procedures EPIP-180-1.adding rad/chem ofc to habitability checks W/840309 transmittal & receipt form. * Commonwealth Edison Co 84/03/09 5pp 22671 100 24X Fiche 50-295,84/03/09,8403190195
- 8403230124 Rev 4 to Emergency Plan Implementing Procedura EPIP-330-1, "Classification of GSEP Conditions" W/840322 transmittal
- G Adjudicatory correspondence
- 8403020134 Forwards util 840228 Itr to Denton requesting permission to withdraw application for license amends re containment leakage tests criteria Motion will be filed upon request. Certificate of Bvc enci BTEPTDE.P.P Isham, Lincoln & Beals STEPTDE.P.P Commonwealth Edison Co 84/02/28 LAZO.R M Atomic Safety and Licensing Board Panel 6pp 22441 345 24X Fiche 50-295,84/02/28,8403020134
- B40302014D Notice of appearance in proceeding Cartificate of Svc encl BTEPTOE,P P Commonwealth Edison Co STEPTOE,P P Isham, Lincoln & Beals 84/02/28 ip 22443 253 24X Fiche 50-275,84/02/28, 8403020140
- --8403020146 Notice of appearance in proceeding Certificate of Svc encl GILOMEN, B R Commonwealth Edison Co GILOMEN, B R. Isham, Lincoln & Beale 84/02/28 3pp 22443 254 24X Fiche, 50-295, 84/02/28, 8403020140
- 8403140134 Response to Citizens Against Nuclear Power (CANP) 840213 petition to intervene & request for hearing Request should be held in absyance pending action on util request to withdraw application Certificate of Svc encl PERLIS.R 9 Nearing Branch 3 84/03/05 Atomic Safety and Licensing Board Panel. 7pp 22624 205 24X Fiche 50-275,84/03/05, paggragation 34 B403140134
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8403050020 Responds to FOIA request for documents re PASNY submittal on response to the request for occuments to PASNY submittal state of repts/analyses from LLL evaluating PASNY sys interaction program Forwards App A documents PELTON, J M Division of Rules and Records 83/12/07, SHOLLY, S. Union of Concerned Scientists App 22525 098 24X Fiche 50-000,83/12/07,8403050020
- --8403050028 Discusses licensee proposed review plans addressing ACR8 recommendations re sys interaction study GDLLER.K R Assistant Director for Operating Reactor Projects (Pre 771030) 77/10/21 BENDER.M ACR5 Advisory Committee on Reactor Safeguards 2pp 22525 146 24X Fiche 50-000,83/12/07. 8403050020

P Operating license stage documents & correspondence

- 8403020131 Withdraws B30808 application for amend to Licenses DPR-39 & DPR-48, changing acceptance criteria for containment leak rate tests Evidentiary hearing in 1984 would distract technical & legal resources from higher priority tasks FARRAR, D Commonwealth Edison Co 84/02/28 DENYON, H R Office of Nuclear Reactor Regulation, Director 2pp 22443 243 24X Fichs, 50-295, 84/02/28, 8403020131
- 8403050117 Forwards supplemental response to Generic Ltr 83-28,
 "Required Actions Based on Generic Implications of Salem
 ATHS Events "
 BARNES! P L Commonwealth Edison Co 84/02/27 DENTON.H R Office
 of Nuclear Reactor Regulation. Director 26pp 22488 084 24X
 Fichs: 50-000,84/02/27,8403050117
- 8403070145 Requests submittal of documentation of NuREO-0737 items within 30 days to complete technical reviews & implementation, excluding Suppl 1.by Sept 1984.

 VAROA: B A Operating Reactors Branch 1 84/03/02 FARRAR, D L Commonwealth Edison Co 2pp 22592 307 24X Fichs 50-295,84/03/02,8403090145
- 8403280090 Forwards Amends 84 & 74 to Licenses DPR-39 & DPR-48, respectively, safety evaluation & notice of issuance & availability Amends allow performance of extensive preventive maint on shared diesel generator NORRIB, J. Operating Reactors Branch 1 84/03/12 FARRAR, D L Commonwealth Edison Co 3pp 22812 293 24X Fichs 50-295,84/03/12,8403280090
- ---B403280101 Amends 84 & 74 to Licenses DPR-39 & 48, respectively, allowing performance of extensive preventive maint on shared diesel generator VAROA.6 A Operating Reactors Branch 1 84/03/12 App 22812 296 24X Fiche 50-295, 84/03/12. 8403280090
- ---8403280106 Bafety evaluation supporting Amends 84 & 74 to Licenses DPR-37 & DPR-48, respectively. + Office of Nuclear Reactor Regulation, Director 84/03/12 9pp 22812.302 24X Fiche 50-275,84/03/12,8403280090
- ---B4032B010B Notice of issuance & availability of Amends 84 & 74 to Licenses DPR-39 & DPR-4B, respectively VARQA,8,A. Operating Reactors Branch 1 84/03/12 3pp 22812.311 24X Fiche,50-295,84/03/12.8403280090
- 8403260182 Clarifies NUREQ-0737. Item II K 3 31. in response to Generic Ltr 83-35 Westinghouse Owners Group authorized program to demonstrate conservatism of WFLASH small break LOCA analyses.per Item II K 3 30 BARNES, P. L. Commonwealth Edison Co. 84/03/21 EISENHUT, D. Q. Division of Licensing ip 22736 170 24X Fiche 50-000, 84/03/21. REGGRAGIEZ.
- O Inspection reports. IE Bulletins & correspondence
- 8403050223 Further response to FOIA request for records of named individuals, including repts, analyses, studies, test calculations, procedures & practices for measurement of RCB leakage Forwards App C documents, Bearch continuing FELTON, J.M. Division of Rules and Records, 84/02/07, MADDEN, T J Kayes, Bcholer, Flerman, Hays & Handler 3pp 22496-234, 24X Fiche: 50-000,84/02/07,8403050223
- --B403050236 Notifies that independent measurements of identified & unidentified RCB leak rates for all PMRs in Region III performed per Procedures 617278 & 61728B Insp findings summarized NORELIUS, C E Division of Engineering B2/03/08 JORDAN, E. L Division of Engineering & Quality Assurence (Pre 830103), 2pp 22496: 270. 24X Fiche 50-000. B4/02/07, 8403050223
- 8403120134 Forwards IE Insp Repts 50-237/84-01, 50-249/84-01, 50-254/84-01, 50-254/84-01, 50-254/84-01, 50-254/84-01 & 50-304/84-01 on 840203-14 No noncompliance identified BHAFER, W. D. Region 3, Office of Director 84/02/23 REED, C Commonwealth Edison Co. 2pp 22590:090 24X Fiche: 50-000, 84/02/23, 8403120134.
- --8403120137 IE Inep Repts 50-237/84-01, 50-249/84-01, 50-254/84-01, 50-254/84-01 & 50-265/84-01 on 840203-14 No noncompliance or deviations identified Major areas inspected:allegations of improper operation CHRISBOTIMOSN, WALKER, R D Region 3, Office of Director 84/02/21, 4pp. 22590 092, 24% Fiche 50-000/84/02/23, 8403120134

- 8403050043 Forwards Rev O to "Corporate Regulatory Performance Improvement Plan" Plan designed to heighten employee awareness & strengthen corporate ability to improve regulatory performance THDMAB, B Commonwealth Edison Co 84/02/24 KEPPLER, J G Region 3, Office of Director 3pp 22470 139 24X Fiche 50-000,84/02/24,8403050043
- --8403050046 Rev 0 to "Corporate Regulatory Performance Improvement Plan" * Commonwealth Edison Co 84/02/29 22pp 22490 142 24X Fiche 50-000.84/02/24.8403050043
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22909 239 24X Fiche 50-000,84/02/28,8401190072
- 8403190314 Forwards IE Insp Repts 50-299/83-27 & 50-304/83-28 on 831122-1228 & 840202 & notice of violation Concerns re mgt control inadequacies.per TMI Action Plan Item II F i I, "Noble Cas Efficient Monitor," expressed HIND.J A Division of Radiological & Materials Safety Programs 84/03/01 REED.C Commonwealth Edison Co 2pp 226/3 196 24X Fichs 50-295.84/03/01.8403190314
- --8403170321 Notice of violation from insp on 831122-840202 HIND, J A Division of Radiological & Materials Safety Programs 84/03/01 3pp 22673 198 24X Fiche 50-295.84/03/01.8403170314
- --8403190321 Notice of violation from insp on 831122-840202. HIND.J A Division of Radiological & Materials Safety Programs 84/03/01 3pp 22673 198 24X Fiche 50-275,84/03/01,8403190314
- --8403190334 IE Insp Repts 50-295/83-27 % 50-304/83-28 on 831122-840202 Viplation noted failure to follow plant procedures re source handling to evaluate radiological hazards % to control access to high radiation area LOVENDALE, P C, NICHOLSON, N, OREGER, L R Region 3, Office of Director 84/02/29 14pp 22673 201 24X Fiche 50-295,84/03/01,8403190314
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " 8vc list encl GRACE, J N Division of QA, Safeguards & Inspection Programs (Post B30103). 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552,329 24X Fiche 50-000,84/03/02.8402090007
- 8402090008 IE Info Notice 84-14, "Failure of Automatic Sprinkler 8ys Valves to Operate " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 800103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases"

 Svc list encl
 JURDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8402090011 IE Info Notice 84-17, "Problems H/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JDRDAN:E L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/05 Consolidated Edison Co. of New York: Inc 117pp 22553 336 24X Fiche 50-000;84/03/05,8402090011
- 8402090024 IE Info Notice 84-09. Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fichs. 50-000. 84/03/07. 8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Crecking in PWR 8ys." Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8403220161 Forwards IE Insp Repts 50-295/83-26 & 50-304/83-27 on 831221-840209 & notice of violation W/o notice of violation 8HAFER.W D Region 3. Office of Director 84/03/07 REED.C Commonwealth Edison Co 2pp 22717 188 24X Fiche 50-295,84/03/07, 8403220161

- --8403220165 IE Insp Repts 50-295/83-26 & 50-304/83-27 on B31221-840209 Noncompliance noted failure to comply w/approved written procedures.Paragraphs 5,6,11 & 14 resulting in reactor trips & LERs HOLZMER, M M , DUNAMAY, F R , BDYD, D C Region 3, Defice of Director 84/03/06 12pp 22717 190 24X Fiche 50-295,84/03/07,8403220161
- 8402070031 IE Bulletin 84-02, "Failures of GE Type MFA Relays in Use in Class IE Safety Sys " Syc list enc!
 DEVOUND, R C Director's Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24% Fiche 50-000,84/03/12,8402070031
- 8403230088 Ack receipt of regulatory performance improvement plan Periodic meetings requested to discuss progress on program 6 provide feedback KEPPLER.J C Region 3. Office of Director 84/03/20 THOMAS.B Commonwealth Edison Co 1p 22730 161 24X Fiche 50-000.84/03/20. 8403230088
- --8403230107 Forwards corporate regulatory performance improvement plan THOMAS.B Commonwealth Edison Co 84/02/24 KEPPLER.J & Region 3. Office of Director 3pp 22730 162 24X Fiche 50-000. 84/03/20.8403230088
- --8403230126 Rev O to "Corporate Regulatory Performance Improvement Plan For Dresden.Quad Cities, Zion & LaSalle Operating Nuclear Stations & Byron & Braidwood Project Operating Organizations" # Commonwealth Edison Co 84/02/29 22pg 22730 165 24X Fiche 50-000,84/03/20,8403230088
- 8403260196 Forwards responses to IE Bulletin 83-07, "Apparently Fraudulent Products Sold by Ray Miller. Inc " Quad Cities supplied w/piping matls from Ray Miller. Inc during const. Evaluation encl Concerns of IE Bulletin 83-05 satisfied BARNES.P L Commonwealth Edison Co 84/03/20 KEPPLER.J G Region 3, Office of Director 19pp 22754 185 24X Fiche 50-000.84/03/20.84/03/20.
- 8402070043 IE Info Nutice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000,84/03/21,8402070043
- 8402090044 IE Info Notice 84-20, "Syc Life of Relays in Safety-Related Sys " Syc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044
- R Periodic operating reports & related correspondence
- E403060217 "Effluent & Waste Disposal Semiannual Rept.Jul-Dec 1983 Gaseous Effluents Summation of all Releases " W/840210 ltr GRAESSER, K. L. Communumealth Edison Co. 83/12/31 KEPPLER, J. G Region 3, Office of Director 27pp 22511, 159 24X Fiche 50-295, 83/12/31, 8403060217
- 8403080197 "Rept of Occupational Personnel Radiation Doses,1983 " W/840227 ltr SCOTT.J S Commonwealth Edison Co 83/12/31 13pp 22559 099 24% Fiche 50-000,83/12/31,8403080197
- 8403220120 Annual whole body external exposures for 1983 H/840316 ltr RYBAK.B Commonwealth Edison Co 83/12/31 7pp 22716 007 24X Fiche 50-000.83/12/31.8403220120
- B403190156 Monthly operating repts for Feb 1984 W/B40309 ltr. AUSTIN.G., GRAESBER.K.L. Commonwealth Edison Co. 84/02/29 13pp 22669 163 24% Fich: 50-295.84/02/29.8403190156
- S Reportable occurrences, LERs & related correspondence
- B211150076 Discusses events involving loss of electrical inverters including attendant inverters to vital instrument buses.

 Recommendations provided by Nuclear Safety Analysis Ctr are excellent in helping to reduce instrument failures.

 ASHE: F Reactor Operations Analysis Branch B2/10/21 SEYFRIT, K V Reactor Operations Analysis Branch Bpp 22775 223 24X

 Fishe 30-000.82/10/21.8211150076
- 8403060249 LER 84-006-00 on 840203.RCS increased above 200 f on computer CRT display before energizing safeguards sys Caused by operator error Operators reminded to complete all necessary prerequisites before starting action W/840302 ltr CAMPBELL,E J. GRAESSER, K. L. Commonwealth Edison Co. 84/03/02 3pp 22517 076 24X Fiche 50-275.84/03/02.8403060249

- 8403070144 LER 83-055/03L-0 on 830413, containment purge radiation monitor 1RT-PR07C recorder found out of tolerance low Cause undetermined Recorder recallor to within tolerance Preventive maint program implemented W/840305 ltr RASSNER.0. GRAESSER.K L Commonwealth Edison Co 84/03/05 KEPPLER.J O Region 3, Office of Director 2pp 22575.135 24) Fiche 80-275,84/03/05,8403090164
- 8403270035 LER 84-009-00 on 840222.annunciators for steam generator feed flow mismatch.level deviation & local level alarmed & reactor tripped Cause of trip could not be determined Unit brought back on line on 840225 W/840322 ltr RATHSAM.R. GRAESER.K.L. Commonwealth Edison Co. 84/03/22 3pp 22769 324 24X Fiche 50-295.84/03/22.8403270035
- B403270109 LER B4-010-00 on B40224, faedwater pump C decreased to min speed, causing steam generator D low level coincident w/ steam flow-feed flow mismatch & reactor trip Caused by location of self-bleeding moisture trap W/B40323 ltr BEINECKE, PJ, GRAESSER, K L Commonwealth Edison Co B4/03/23 3pp 22774 026 24X Fiche, 50-295, 84/03/23, 8403270109
- B403270203 LER 84-007-00 on 840223 during unit startup control rod urgent failure received during rod withdrawal preventing rod motion Operator tripped reactor manually Alarm spurious Cause not determined 4/640323 ltr
 CHIN.R Y. GRAESER.K L Commonwealth Edison Co 84/03/23 3pp 22771 319 24% Fiche 50-295.84/03/23.8403270203
- 8403270265 LER 84-008-00 on 840223, loop D regulating valve failed to open & level in steam generator D fell Caused by supervisor inadvertently leaving instrument air supply valve closed while performing step 32(b) W/840323 ltr BEINECKE, P J . GRAESSER, K L Commonwealth Edison Co 84/03/23 3pp 22771 316 24x Fiche 50-295.84/03/23.8403270265
- DOCKET 50-294 DROWNS FERRY NUCLEAR POWER STATION, UNIT 3

 F. Security, medical, emergency & fire protection plans
- 840306023B Emergency plan implementing procedures, including IP-2 renotification of unusual event, IP-3 realert, IP-4 resite emergency & IP-4 readiological amergency plan, activation at support ctr W(940228 tr & list of effective pages MILLS.L M Tennessee Valley Authority 84/02/10 D'REILLY, J P Region 2. Defice of Director 52pp 22516 098 24X Fiche 50-259,84/02/10,8403060238
- B403060571 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee.per B10709 Generic Ltm B1-27 W/o request entire plan will be placed in PDR VABSALLO.D B Operating Reactors Brench 2 B4/02/10 PARRIS.H 9 Tennessee Valley Authority 2pp 22552 261 24X Fiche 50-259,84/02/10.8403060571
- 8403040235 Rev 5 to Procedure IP-9. "Muscle Shoals Emergency Ctr Implementing Procedures Document" H/840213 ltr HAXMELL, R. & SLIGER, E. K. Tennessee Valley Authority 84/02/13 63pp 22518 023 24X Fiche 50-000,84/02/13,8403040235.
- 8403040147 Forwards revised effective pages to Knoxville Emergency Ctr. Central Emergency Control Ctr. Div of Nuclear Power Emergency Ctr & Muscle Shoals Emergency Control Ctr emergency plan implementing procedures W/o Muscle Shoals pages
 MILLS.L. M Tennessee Valley Authority 84/02/28 D'REILLY.J P
 Region 2. Office of Director 1p 22516 165 24X
 Fiche 80-000.84/02/28,8403060147
- --B403060163 Revised list of effective pages to Knoxville Emergency Ct Emergency plan implementing procedures * Tennessee Valley Authority 84/02/06 8pp 22516:166 24X Fiche 50-000, 84/02/28.6403060147
- --8403060187 Revised list of effective pages to Central Emergency Control Ctr emergency plan implementing procedures * Tennesses Valley Authority 84/02/06 8pp 22516.174 24X Fichs 50-000,84/02/28.8403060147
- --B403060204 Revised list of effective pages to Div of Nuclear Power Emergency Ctr emergency plan implementing procedures * Tennessee Valley Authority B4/02/06 4pp. 22516:182 24X Fiche 50-000,84/02/28.8403060147
- 8403140162 Ack receipt of 840222 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-259/83-57, 50-260/83-57 & 50-276/83-57
 LEHIG: R C Division of Project & Resident Programs. 84/02/29 PARRIS

- --8403160171 Responds to NRC B40123 ltr re violations noted in IE Insp Repts 50-259/83-57, 50-260/83-57 & 50-296/83-57 Corrective actions policy statement issued to health physics technicians re high radiation area doors HILLB,L M Tannessee Valley Authority B4/02/22 0'REILLY, J P Region 2. Office of Director 5pp 22655 274 24X Fiche 50-259,84/02/29,8403160162
- >-8403160181 Notice of violation from Insp on 831126-1225 * Region 2, Office of Director 84/01/23 2pp 22655 281 24X Fiche 50-259,84/02/29,8403160162
- --B403160186 IE Insp Repts 50-259/83-57,50-260/83-57 & 50-296/83-57 on 831126-1225 Violations noted failure to lock high radiation area, to follow special work permit & to have adequate fire protection maint procedure PAULK, G. L. Region 2, Office of Director 84/01/21 App 22655 283 24X Fiche 50-259,84/02/29,8403160162
- @403160218 Ack receipt of 840209 ltr informing NRC of steps taten to correct violations noted in IE Insp Repts 50-239/83-40, 30-260/83-40 & 50-296/83-40 LEWIS, R C Division of Project & Resident Programs 84/03/01 PARRIS, H G Tennessee Valley Authority 1p 22661 098 24X Fiche 50-259, 84/03/01,8403160218
- --8403160R23 Responds to NRC 840111 ltr re violations noted in IE Insp Repts 50-259/83-40,50-260/83-40 & 50-296/83-40 Corrective actions radiological emergency planning program reviewed & areas requiring revidentified MILLS,L M Tennassee Valley Authority 84/02/09 O'REILLY,J P MILLS, L M Tennasses Valley Authority 84/02/09 O'REILLY, J P Region 2. Office of Director App 22661 099 24X Fiche. 50-259, 84/03/01/8403160218
- --8403160230 Forwards IE Insp Repts 50-259/83-40, 50-260/83-40 & 50-296/83-40 on 831017-21 & 1122 & notice of violation LENIG.R C Division of Project & Resident Programs 84/01/11 PARRIS.H G Tennessee Valley Authority 2pp 22661 105 24: Fiche 50-259, 84/03/01,8403160218
- --8403160239 Notice of violation from insp on 831017-21 & 1122 * Region 2, Office of Director 84/01/11 3pp 22661 107 Fiche: 50-259, 84/03/01, 8403160218
- --8403160244 [E Insp Repts 50-259/83-40, 50-260/83-40 & 50-296/83-40 on 831017-21 & 1122 Noncompliance noted failure to control documents, properly train emergency personnel in protective action requirements & incorporate protective action DECMER.TR Region 2, Office of Director 84/01/06 9pp 22661 110 24X Fichs 50-259,84/03/01,8403160218
- 3403160345 Extends invitation to attend region 840316 workshop at regional ofc to discuss 10CFR50. App R requirements & recent results of imap to help resolve misunderstandings associated W/requirements
 LEHIB.R.C Division of Project & Resident Programs 84/03/02
 PARRIB.H @ Tennessee Valley Authority 2pp 22660 083 24X
 Fiche 80-000,84/03/02,8403160345
- 1403130485 Ack receipt of 840119 ltr transmitting Rev 7 to security personnel training & qualification plan Rev consistent w/provisions of 10GFR50 54(p) & acceptable LEMIS.R C Division of Project & Resident Programs 84/03/08 PARRIS.H.O Tennesses Valley Authority 2pp 22613 210 24x Fiche 50-259,84/03/08,8403130485
- 403130484 Ack receipt of 840130 ltr transmitting rev to physical security plan Rev consistent w/provisions of 10CFR50 54(p) & acceptable LEMIS.R.C. Division of Project & Resident Programs 84/03/09 PARRIS.H Q Tennesses Valley Authority. 2pp 22613 177. 24X
- *ARRIS, H O Tennesses Valley Authority, 2pp 22613 197, 24X *iche 50-259,84/03/09,8403130484
- 403160025 Advises that 840116 rev to physical security personnel training & qualification plan consistent w/provisions of 10GFR50.54(p) & acceptable LEHIB.R C Division of Project & Resident Programs 84/03/13 PARRIG.H G Tennesse Valley Authority 2pp 22653 358 24x Fichs 50~259.84/03/13.8403160025
- 103190136 Ack receipt of 840221 & 0312 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 10-289/83-59.50-240/83-59 & 50-296/83-59 Responses meet TOPERSYSTEM OF THE PROPERTY OF

- --B403190149 Supply response to NRC B40120 ltm re violations noted in IE lnap Repts 50-239/83-59, 30-240/83-39 % 50-294/83-59 Responses withheld (ref 100FR73 21) MILLS, L M Tennesses Valley Authority 84/03/12 O'REILLY, J P Region 2, Office of Director 1p 22670 315 24% Fiche 50-259,84/03/14,8403190134
- --B403190161 Responds to NRC 840120 ltr re violations noted in IE Insp.
 Repts 50-259/83-59.50-260/83-59 & 50-296/83-59 Responses
 withheld (ref 10CFR73 21)
 MILLS.L M Tennessee Valley Authority 84/02/21 0'REILLY.J P
 Region 2. Office of Director 1p 82670 316 24X
 Fiche 50-259.84/03/14.8403190136
- --8403190172 Forwards IE Insp Repts 50-239/83-59, 50-260/83-59 & 50-296/83-59 on 831216 & notice of violation Notice of violation withheld (ref 100FR2 790 & 73 21)
 LEWIS.R C Division of Project & Resident Programs 84/01/20 PARRIS.H G Tennessee Valley Authority 2pp 22670 317 24)
 Fiche 50-259,84/03/14,8403190136
- --8403190188 IE Insp Repts 50-259/83-59.50-260/83-59 & 50-296/83-59 on 831216 Moncompliance noted security force member failed to control access to area Details withheld (ref (OCFR73 21 & 2 790) TILLMAN, A 22670 319 Region 2. Office of Director 84/01/19 24% Fiche 50~259.84/03/14.8403190136
- 8403270117 Forwards FEMA final rept for 831015-16 emergency exercise VERRELLI,D M Division of Project & Resident Programs 84/03/20 PARRISH H O Tennessee Valley Authority ip 22807 027 24X Fiche 50-259,84/03/20,8403270117
- 9 Adjudicatory correspondence
- 8403200059 Submits add1 info on util initiatives in PRA, per response to 840227 ltr Effort to reduce number of violations & risks maintained FREEMAN.S D Tennessee Valley Authority 84/03/12 MARKEY, E. J. House of Rep., Interior & Insular Affairs 2pp 22685 033 24X House of Rep , Interior & Insula Fiche 50-259,84/03/(2,8403200059
- J Insurance & indemnity information
- 8403040334 Forwards Endorsement 73 to NELIA Policy NF-198 DUCK.J R Marsh & McLennan, Inc 84/02/28 SALTZMAN, J Director for State & Licensee Relations 2pp 22516 009 Fiche 50-259.84/02/28.8403060334 Assistant
- P Operating license stage documents & correspondence
- 8403060076 Forwards request for add1 info re inservice testing of pumps & valves,in order to complete review of 820801 & 830406 submittals Response requested within 45 days of ltr receipt VASBALLO,D B Operating Reactors Branch 2 84/02/10 PARRIS.H G Tennesses Valley Authority 4pp 22328 288 24% Fiche 50-259.84/02/10.8403040076
- 8403140340 Summary of 831215 meeting w/GE & Mark 1 Duners Group in Bethesda, MD re Mark 1 containment wetwell-drywell vacuum breaker design methodology BIEGEL.B L Operating Reactors Branch 2 84/02/21 Operating Reactors Branch 2 Sipp 22635 178 24% Fiche 50-000.84/02/21.
- 8403010306 Application for amend to Licenses DPR-33, DPR-52 & DPR-68. volvious printation for amend to Literises brandishing a Unred to the changing fish Specs to lower Group I isolation subjoint for reactor lower water level W/proprietary NEDE-30012. "MSIV Water Level "Rept withheld (ref 100FR2 790) MILLS,L M Tennessee Valley Authority B4/02/22 DENYON,H R Office of Nuclear Reactor Regulation, Director 3pp 22433 042 24X Fiche 50-259.84/02/22.8403010306
- --8403010313 Proposed changes to Tech Specs lowering Group 1 isolation setpoint for reactor lower water level Waffidavit

 * Tennesses Valley Authority 84/02/22 29pp 22433 045 24X
 Fiche 50-259,84/02/22,8403010306
- 8403140276 Requests 840307 meeting w/TVA in Chattanooga.TN to discuss design of analog trip sys for Unit 3 in light of failure of analog transmitters experienced in Unit 1.per util 840123 request for license amena VASSALLO,D B Operating Reactors Branch 2 84/02/28 PARRIS.H G Tennessee Valley Authority 2pp 22606 027 24X Fiche 50-296,84/02/28,8403140276

- 8403150323 Forwards info re BNL dose reduction project plant visit Info allows BNL personnel to better prepare for station visit: expedite paperwork & minimize impact on plant personnel VASSALLO, D B Operating Reactors Branch 2 84/02/28 FARRIS, H G Tennessee Valley Authority 46pp 22662 040 24x Fithe 50-259.84/02/28.8403150323
- 8403130007 Forwards response to Generic Ltr 83~36 re NUREG-0737 Tech Specs MILLS,L M Tennessee Valley Authority 84/03/07 DENTON,H R Office of Nuclear Reactor Regulation, Director 3PP 22613 349 24X Fiche 50~259,84/03/07,8403130007
- 8403130025 Informs that add1 info requested on 831012 re reactor protection sys power monitoring sys design mods will be submitted by 840702 MILLS.L M Tennessee Valley Authority 84/03/07 DENYON.H R Office of Nuclear Reactor Regulation, Director ip 22614 362 24X Fiche 50-237.84/03/07.8403130025
- 8403160247 Informs of 840327 meeting to discuss proposed responses to NRC questions on Rev 7 to topical QA program.per 840302 telicon
 LENIBLE C Region 2. Office of Director 84/03/08 PARRIS.H 0 Tennessee Valley Authority 1p 22660 361 24X Fiche 50-000.84/03/08.8403160247
- 8403160373 Notifies of use of ASME Nuclear Components Code Case N32-4 for hydrostatic testing of Class 3 embedded piping NRC position re use of Code Case N32-4 requested MILLS.L M Tennessee Valley Authority 84/03/12 DENTON.H R Office of Nuclear Reactor Regulation. Director 1p 22660 014 24% Fiche 50-000.84/03/12.8403160373
- 8403180275 Ceneric Ltr 84-07 to all licensees of BWRs re procedural guidance for pipe replacement at BWRs 8vc 11st encl
 EISENHUT, D C Division of Licensing 84/03/14 Commonwealth Edison Co 20pp 22823 394 24X Fiche 50-000, 84/03/14,8403150275
- 8403200170 Forwards response to Item 4 5 of Generic Ltr 83-28, "Required Actions Based on Generic Implications of Salem ATMS Events" re reactor trip sys reliability Control rod tests check rod insertion times & hydraulic scram valves MILLS.L M Tennessee Valley Authority 84/03/15 DENTON.H R Office of Nuclear Reactor Regulation. Director 10pp 22700 024 24% Fiche 50-259.84/03/15.8403200170
- 8403260229 Forwards add1 info re test configuration & results of verification testing per 840106 request re adequacy of station electric distribution sys voltages Tast results indicated no unexpected voltage lovels
 MILLS.L. M Tennessee Valley Authority 84/03/19 DENTON.H R
 Defice of Nuclear Reactor Regulation. Director 26pp 22756 12:24X Fiche 50-259.84/03/19.8403260229

@ Inspection reports, IC Bulletins & correspondence

- B403070054 Responds to NRC ltr re violations noted in IE Insp Repts 50-259/83-09, 50-260/83-09 & 50-276/83-09 List of identified deficiencies & implementation schedule provided to senior NRC inspector on B30901 MILLS:L H Tennessee Valley Authority B3/09/15 O'REILLY, J P Region 2, Office of Director is 22547 261 24X Fiche 50-259, 83/09/15, 8403070054
- 8403070237 Updates 830715 response to NRC 830616 ltr re violations noted in IE Insp Repts 50-257/83-19.50-260/83-19 & 50-296/83-19 Operating instructions revised & Units 2 & 3 PSC charging sys operational MILLS: L M Tennessee Valley Authority 83/09/30 D'REILLY: J P Region 2. Defice of Director 1p 22541 361 24X Fiche 50-259.83/09/30.8403070237
- 840307027i Suppis 830830 response to NRC ltr re violations noted in IE Insp Repts 50-257/83-23.50-260/83-23 & 50-276/83-23 Borel test specimen installation will be delayed until 831028 due to late receipt of matis per 831012 telcon KAMMER.D S Tennessee Valley Authority 83/10/21 G'REILLY, J P Region 2. Dffice of Director 1p 22546 356 24% Fiche 50-259.83/10/21.8403070271
- 8403070023 Responds to NRC ltr re violations noted in IE Insp Repts 50-259/83-27,50-260/83-27 & 50-296/83-27 Corrective actions compliance w/instructions will be achieved & corrective actions will be completed before Cycle & aperation MILLS.L.M Tennessee Valley Authority 83/10/27 O'REILLY.J P Region 2. Office of Director ip 22541 262 24X Fiche 50-259,83/10/27,8403070023

- 8403070067 Forwards IE Insp Repts 50-259/83-50.50-260/83-50 & 50-276/83-50 on 830912-16 & 26-30 Unresolved item repossible high radiation doses measured by personnel desimpters discussed on 831028, considered closes O'REILLY.J P. Region 2. Office of Director 84/01/11 PARRIS.H & Tennassee Valley Authority 2pp 22545 341 24X Fiche 50-259.84/01/11.8403070067
- --8403070072 IE Insp Repts 50-259/83-50,50-260/83-50 & 50-296/83-50 on 831028 No violations or deviations noted Major areas inspected TLD & multiple badging DEBs,8 T Region 2, Office of Director 83/12/05 5pp 22545 343 24X Fiche 50-259.84/01/11.8403070067
- 8403160232 Forwards IE Insp Repts 50-259/84-04.30-260/84-04 & 50-276/84-04 on 840123-27 No violations or deviations noted VERRELLI.D M Division of Project & Resident Programs 84/02/16 PARRIS.H 0 Tonnesse Valley Authority 2pp 22661 029 24X Fiche 50-259.84/02/16,6403160232
- ---B40316023B IE Insp Repts 50-259/B4-04, 50-260/B4-04 & 50-296/B4-04 on B40123-27 No violations or deviations noted Major areas inspected startup testing, new fuel receipt plant tours & MBIV repair status DAVENPORT, K E Region 2, Office of Director JAPE, F Division of Engineering & Operational Programs B4/02/14 5pp 22661 031 24% Fiche 50-259, 84/02/16, 8403160232
- B401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list ancl URBAN, E. Divisson of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22909 239 24X Fiche 50-000.84/02/28.8401190072
- 8403160162 Ack receipt of 840222 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-57, 50-260/83-57 & 50-296/83-57 LEHIB,R C Division of Project & Resident Programs 84/02/29 PARRIS.H Q Tennessee Valley Authority ip 22655 273 24X Fichs 50-259.84/02/29,8403160162
- --8403160171 Responds to NRC 840123 ltr re violations noted in IE Insp Repts 50-259/83-57, 50-260/83-57 & 50-296/83-57 Corrective actions policy statement issued to health physics technicians re high radiation area doors MILLB.L M Tennesses Valley Authority 84/02/22 O'REILLY, J P Region 2, Office of Director Spp 22655-274 24X Fichs 50-259, 84/02/29, 8403160162
- --8403160178 Forwards IE Insp Repts 50-259/83-57, 50-260/83-57 & 50-296/83-57 on 831126-1225 & notice of violation LEWIS.R C Division of Project & Resident Programs 84/01/23 PARRIS.H 0 Tennessee Valley Authority 2pp 22655 279 24) Fiche 50-259,84/02/29,8403160162
- ~-8403160181 Notice of violation from insp on 831124-1225 * Region 2. Office of Director 84/01/23 2pp 22655 281 24X Fiche 30-259,84/02/29.8403160162
- ~-8403160186 IE Insp Repts 50-239/83-57, 50-260/83-57 & 50-296/83-57 on 831126-1225 Violations noted failure to lock high radiation area, to follow special work permit & to have adequate fire protection maint procedure PAULK, 0 L. Region 2. Office of Director CANTRELL, F. 8 Division of Project & Resident Programs 84/01/21 6pp 22655 283 24% Fiche 50-259,84/02/29,8403160162
- 8403160218 Ack receipt of 840209 ltr informing NRC of steps taken to correct violations noted in 1E Inap Repts 50-259/83-40, 50-260/83-40 & 50-296/83-40 LEMIS.R C Division of Project & Resident Programs 84/03/01 PARRIS.H 0 Tennessee Valley Authority ip 22661 098 24X Ficha 50-259.84/03/01.8403160218
- ---8403160223 Responds to NRC B40111 ltr re violations noted in IE Insp. Repts 50-259/83-40, 50-260/83-40 & 50-296/83-40 Corrective actions radiological emergency planning program reviewed & areas requiring revidentified MILLS:L M Tennessee Valley Authority 84/02/09 0'REILLY:J P. Region 2. Office of Director App 2264:099 24X Fiche 50-259,84/03/01.8403160218
- --8403160230 Forwards IE Insp Repts 50-259/83-40, 50-260/83-40 & 50-296/83-40 on 831017-21 & 1122 & notice of violation. LEWIS.R C Division of Project & Resident Programs 84/01/11 PARRIS.H G Tennessee Valley Authority 2pp. 22661, 105 24X Fiche 50-259, 84/03/01, 8403160218
- --8403160239 Notice of violation from insp on 831017-21 & 1122, * Region 2, Office of Director. 84/01/11 3pp 22661 107 24% Fiche 50-259,84/03/01,8403160218

- --8403160244 IE Insp Repts 50-259/83-40, 50-260/83-40 & 50-276/83-40 an 831017-21 & 1122 Noncompliance noted failure to control documents, properly train emergency personnel in protective action requirements & incorporate protective action DECKER, T.R., STODDART, P.G., Region 2, Diffice of Director JENKINS, G.R. Division of Emergency Preparedness & Materials Safety 84/01/06 9pp 28661 110 24X Fiche 50-259,84/03/01, 8403160218
- B402090007 IE Info Notice B4-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl ORACE, J N Division of GA, Bafeguards & Inspection Programs (Post B30103) B403702 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000,84/03/02,8402090007
- 8402090008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 122pp 22553 098 24X Fiche 50-000.84/03/02,8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases" 8vc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 119pp 22553 217 24X Fiche 50-000.84/03/02.8402090009
- 8403080213 EN-84-007 on 840307, notice of violation & proposed imposition of civil penalties in amount of \$40,000 to be issued Action based on Failure to control access into vital area dus to guard leaving post
 RDSAND,R Director's Defice, Office of Inspection and Enforcement 84/03/02 1p 22560 021 24X Fiche 50-259,84/03/02.8403080213
- B402090011 IE Info Notice 84-17. "Problems W/Liquid Nitrogen Cooling Components Below Ni; Ductility Temp " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 334 24X Fiche 50-000,84/03/05,8402090011
- 840316030B Ack receipt of 840217 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-259/83-56 LEWIS.R C Division of Project & Resident Programs 84/03/05 PARRIES.H O Tempessee Valley Authority 1p 22660 085. 24x Fichs 50-259.84/03/05.8403160308
- --B403160318 Responds to NRC 840117 ltr re violations noted in IE Insp Repts 50-259/83-56,50-260/83-96 & 50-296/83-56 Corrective actions 10% retest sample calculation made for all snubbers within Category/Group 3 MILLS.L M Tennessee Valley Authority 84/02/17 O'REILLY, J P Region 2, Office of Director 2pp 22660 086 24X Fiche 50-259,84/03/05,8403160308
- --8403160328 Forwards 1E Insp Repts 50-259/83-56.50-260/83-56 & 50-296/83-56 on 831213-16 & notice of violation LEWIS.R.C Division of Project & Resident Programs 84/01/17 PARRIB.H Q Tennesses Valley Authority 2pp 22660 088 24X Fichs 50-259.84/03/05.8403160308
- --8403160339 IE Insp Repts 50-259/83-56, 50-260/83-56 & 50-296/83-56 on 831213-16 Violation noted failure to test add1 10% sample for sach snubber that failed functional test HHITENER, H. L. Region 2, Office of Director JAPE, F Division of Engineering & Operational Programs 84/01/10 8pp 22660 091 24X Fichs. 50-259, 84/03/05, 8403160308
- 8403270237 Forwards IE Insp Repts 50-259/84-05, 50-260/84-05 & 50-276/84-05 on 840130-0201 No violations or deviations identified VERRELLI, D M Division of Project & Resident Programs 84/03/05 PARRIS, H. Q Tennessee Valley Authority 2pp 22800-227 24X Fiche: 50-259, 84/03/05, 8403270237
- --8403290239 IE Inap Repts 50-259/84-05, 50-260/84-05 & 50-296/84-05 on 840130-0201. No violations or deviations identified Major erass inspected followup of IE Bulletin 81-03, review of LERs re bulletin & procedures for flow reverification tests CUNNINOHAMA & Region 2, Office of Director MONTGOMERY, D M Division of Engineering & Operational Programs 84/03/02 5pp 20800 231 24% Fiche 50-259,84/03/05,8403270237
- B402090024 IE Info Notice 84-09, Rev 1, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07. Consolidated Edison Co of New York, Inc. 118pp 22635 049 24X Fiche 50-000, 84/03/07, 8402090024
- B402070028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Bys." Svc list ancl.

 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103), 84/03/07 Consolidated Edison Co of New York, Inc. 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028

- --8403160282 IE Enforcement Conference Repts 50-259/84-06.50-260/84-06 & 50-296/84-06 on 840224 Major items discussed bypassing rod sequence control sys while shutting down & isolation of drywell to pool pressure instrument BUTCHER.R C Region 2. Office of Director CANTRELL.F S Division of Project & Resident Programs 84/02/27 App 28661 006 24X Fiche 50-259.84/03/08.8403160273
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl DEYDUNG, R C Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24x Fiche 50-000.84/03/12,8402090031
- 8403190136 Ack receipt of 840221 & 0312 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-289/83-59, 50-260/83-59 & 50-296/83-59 Responses meet 10CFR2 201 requirements

 LEWIG.R C Division of Project & Resident Programs 84/03/14 PARRIS, H G Tennessee Valley Authority 1p 22670 314 24X Fiche 50-259,84/03/14,8403190136
- --8403190149 Suppls response to NRC 840120 ltr re violations noted in IE
 Insp Repts 50-259/83-59.50-260/83-59 & 50-296/83-59
 Responses withheld (ref 10CFR73 21)
 MILLB.L M Tennessee Valley Authority 84/03/12 D'REILLY.J P
 Region 2. Office of Director 1p 22670 315 24x
 Fichs 50-259.84/03/14,8403190136
- --8403190161 Responds to NRC 840120 ltr re violations noted in IE Insp Repts 50-259/83-59, 50-260/83-59 & 50-296/83-59 Responses withhold (ref 10CFR73 21) MILLS, L M Tennessee Valley Authority 84/02/21 G'REILLY, J P Region 2. Office of Director 1p 22670 316 24X Fiche 50-259, 84/03/14, 8403190136
- --8403190172 Forwards IE Insp Repts 50-259/83-59,50-260/83-59 & 50-296/83-59 on 831216 & notice of violation Notice of violation withheld (ref 10CFR2 790 & 73 21)
 LEWIS, R C Division of Project & Resident Programs 84/01/20
 PARRIS, H G Tennesse Valley Authority 2pp 22670 317 242
 Fichs 50-259,84/03/14,8403190136
- --B403170188 IE Insp Repts 50-257/83-57, 50-260/83-57 & 50-276/83-57 on 631216 Noncompliance noted security force member failed to control access to area Details withheld (ref 10CFR73 21 & 2790)

 TILLMAN, A. PATTERSON, C. Region 2, Office of Director MCQUIRE, D. R. Division of Emergency Preparadness & Materials Safety 84/01/19 ip 22670 319 24X Fiche 50-259,84/03/14,8403170136
- 8403290047 Summarizes 840312 meeting in Region II ofc re planned util organizational changes & regulatory performance improvement program for facility

 D'REILLY, J.P. Region 2, Office of Director 84/03/15 PARRIS, H. G. Tennessee Valley Authority ip 22806 271 24X

 Fiche 50-259,84/03/15,8403290047
- 8403290178 Ack receipt of 840217 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50~259/83-38. 50~260/83-38 & 50~294/83-38

 LEWIS,R C Division of Project & Resident Programs 84/03/20 PARRIS
- --8403290183 Suppls response to NRC 840119 ltr re violations noted in IE Insp Repts 50-259/83-38, 50-260/83-38 & 50-276/83-38 Corrective actions distribution of insp rept to health physics personnel initiated MILLS.L M Tennessee Valley Authority 84/02/17 O'REILLY.J P Region 2. Office of Director 2pp 22800 279 24X Fichs 50-259, 84/03/20, 8403290178
- --8403270170 Ack receipt of 831207 ltr informing NRC of steps taken to correct violations noted in 16 Insp Repts 50-257/83-38, 50-260/83-38 & 50-296/83-38 O'REILLY.JF Region 2. Office of Director 84/01/19 PARRIS.H 0 Tennessee Valley Authority 2pp 22800'281 24X Fiche 50-259,84/03/20.8403270178
- --8403290203 Ack receipt of 831209 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-38. S0-260/83-38 & 50-296/83-38 LEWIS,R C Division of Project & Resident Programs 83/12/21 PARRIS.H G Tennessee Valley Authority ip 22800 283 24x Fiche 50-259,84/03/20,8403290178

- --8403270207 Responds to NRC 831107)tr re violations noted in IE Insp Repts 50-259/83-38, 50-260/83-08 & 50-296/83-38 Corrective actions unsp rept distributed to health physics personnel & RCI-5 revised to incorporate 10cR647 changes MICLS.L M Tennessee Valley Authority 83/12/09 D'REILLY, J P Region 2, Office of Director 5pp 22800 284 24X Fishe 50-259,84/03/20,8403290178
- ---8403270211 Forwards IE Insp Repts 50-259/83-38.50-260/83-38.& 50-276/83-38 on 830712-16.& notice of violation LEWIS.R C Division of Project & Resident Programs 83/11/07 PARRIS.H Q Tennessee Valley Authority 2pp 22800 289 24X Fichs 50-259.84/03/20.8403270178
- --8403270214 Notice of violation from insp on 830912-16

 * Region 2, Office of Director 83/11/09 2pp 22800 291 24)
 Fiche 50-259, 84/03/20, 8403290178
- --B40329022D IE Insp Repts 50-299/B3-38, 50-260/B3-38 & 50-296/B3-38 on B30912-16 Violations noted 55-gallon drum reading 30 to 65 millires per hour observed unlabeled & radiation control procedures not prepared or adhered to DEBS.B T Region 2. Office of Director BARR.K P Division of Engineering & Operational Programs B3/11/03 6pp 22800 293 24X Fiche 50-259,84/03/20,8403290178
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PMR Reactor Cavities " Svc list encl JORDAN, & L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 123pp 22823 229 24X Fichs 50-000,84/03/21,8402090043
- 8402070044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc list enc! JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 135pp. 22733 001 24X Fiche 50-000,84/03/21,8402070044
- R Periodic operating reports & related correspondence
- 8403020103 Monthly operating repts for Jan 1984 W/840210 ltr CHAPMAN.M., THOM.T., JONES.O T. Tennessee Valley Authority 84/01/31 41pp 22443 166 24% Fiche 50-259.84/01/31.8403020103
- 8403300133 Forwards monthly operating repts for Feb 1984 & corrected Jan 1984 monthly operating rept for Unit 1
 JONES. 9 T Tennessee Valley Authority 84/03/09 Office of Resource Management. Strector 1p 22820 203 24X
 Fich
- --8403300136 Monthly operating repts for Feb 1984 THOM: T Tennessee Valley Authority 84/02/29 37pp 22820 204 24X Fiche 50-259, 84/03/09, 8403300133
- S Reportable occurrences, LERs & related correspondence
- 8403050051 Notification of 840307 meeting w/util in Chattanoga.TN to discuss design of analog trip sys in light of transmitter failures in Unit 1
 CLARK.R J Operating Reactors Branch 2 84/02/28 VASSALLO.D B Operating Reactors Branch 2 10 22527 318 24%
 Fiche 50-296.84/02/28.8403050051
- 8403260233 Forwards summary list of deficiencies identified per 10CFR50 55(e),Part 21 & potential generic ltr repts for comments
 STARDSTECKI.R Division of Project & Resident Programs 84/02/28 Region 1, Office of Director 7pp 22756 065 24X Fiche 50-000.84/02/28.840326023
- B403200087 LER B4-004-00 on 840228,RHR outboard Loop II isolation valve steam found broken Probably caused by averstress or extreme load Limitorque. Limitorque suitches & valve discs investigated W/B40314 ltr Followup rept by 840615 HALKER, J B . JONES, G T Tennessee Valley Authority 84/03/14 22699 092 24% Fiche 50-296.84/03/14.B403200087
- V Operator Examinations
- 8403160227 Confirms 840302 meeting in Atlanta. GA re 840319 operator requalification exam. per 840227 telcon
 LEWIS.R C Division of Project & Resident Programs 84/03/01
 PARRIS.H G Tennessee Valley Authority 1p 22660 328 24X
 Fiche 50-259.84/03/01.8403160227

- 8403270322 Discusses 840117 ltr confirming arrangements for administration of requalification exams Random selection process used to determine identify of examinees for written & oral exams List of examinees encl LEWIS.R C Division of Project & Resident Programs 84/03/13 PARRIS.H G Tennesses Valley Authority 3pp 22802 049 24X Fichs 50-259.84/03/13.8403270322
- 8403290213 Summarizes 840302 meeting w/util re 840323 requalification exam of licensed operator & senior operator personnel at facilities Meeting provided better understanding of operator requalification training & exam programs

 LEWIS.R C Division of Project & Resident Programs 84/03/15

 PARRIS.H O Tennessee Valley Authority 3pp 22800 360 24X

 Fiche 50-259.84/03/15.8403290213

DOCKET 50-298 COOPER NUCLEAR STATION

- F Security, medical, emergency & fire protection plans
- 8403050141 Provides scenario for submittal of proposed emergency preparedness info.per NRC 820114 ltr & 800817 revised emergency planning rule COLLINS, J T Region 4. Office of Director 84/02/09 PILANT, J M Nebraska Public Power District 2pp 22487 306 24X Ficha 30-298.84/02/09.8403050141
- 8403060471 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee.per 810709 Generic Ltr Bi-27, W/o request.entire plan will be placed in FDR VASSALLO, D B Operating Reactors Branch 2 84/02/10 FILANT. J M Nebraska Public Power District 2pp 22549 324 24X Fichs 50-298.84/02/10.8403060471
- 8403060346 Forwards smergency plan implementing procedures including Rev 2 to 5 7 5, "General Emergency Implementing Procedure." Rev 3 to 5 7 13, "Personnel Monitoring & Decontemination" & Rev 3 to 5 7 15, "Rescue & Reentry " W/o enc! PILANT, J M Nebraska Public Power District 84/02/13 COLLING, J T Region 4, Office of Director 1p 22518 223 24% Fichs 50-278, 84/02/13, 8403060346
- 8403260235 Forwards IE Insp Rept 50-298/83-28 on 831018-21 & notice of violation JOHKSON.E H Region 4. Office of Director 84/02/17 PILANT, J M Nebraska Public Power District 2pp 22755 158 24X Fiche 50-298.84/02/17.8403260235
- --8403260238 Notice of violation from insp on 831018-21 * Region 4, Office of Director 84/02/17 2pp 22755 160 24X Fiche 50-298,84/02/17.8403260235
- --B403260240 IE Insp Rept 50-29B/B3-2B on 831018-21 Violation noted licensee presented no evidence that physician assistant trained to identify aberrant behavior Details withheld (ref 10CFR73 21)
 CALDWELL: R A , KELL: J A F , HUNNICUTT, D M Region 4, Defice of Director B4/02/17 1p 22735 162 24X Fiche 50-298,84/02/17,8403260235
- 8403060239 Forwards Rev 3 to Emergency Plan Implementing Procedures 5 7 3, "Alert Implementing Procedure," 5 7 8, "Activation of OSCs" & 5 7 12, "Emergency Radiation Exposure Control "W/o encis
 PILANT, J M Nebraska Public Power District 84/02/21 COLLING, J T Region 4, Office of Director 1 p 22517 313 24X
 Ficha 50-298.84/02/21.8403060239
- 8403140252 Forwards order confirming licensee 830415,0711 & 28 & 1230 commitments to comply w/Bupp1 1 to NUREG-0737 re smargency response capability VASBALLO,D D Operating Reactors Branch 2 84/02/22 PILANT, J M Nebraska Public Power District 2pp 22636 332 24X Fichs 50-298,84/02/22,8403140252
- --8403140255 Order confirming licensee commitments to comply w/Buppl 1 to NUREO-0737 (Generic Ltr 82-33) re emergency response capability EISENHUT, D. G. Division of Licensing 84/02/22 Nebraska Public Power District 6pp. 22636:334, 24X Fiche 50-298,84/02/22,8403140252
- 8403090100 Application for amend to License DPR-16.changing Tech Specs re fire detection instruments to comply w/NUREG-0737 (Generic Ltr 83-36). Items II B i.II B 3.II F 1 & II D 3.4 KUNCL.L G Nebraska Public Power District 84/02/29 VASSALLO.D B Operating Reactors Branch 2 6pp 22571 116. 24X Fiche 50-278.84/02/29.8403090100

- --B403070114 Proposed radiological Tech Specs per NUREG-0737 (Generic Ltr 83-36) re fire detection instrumentation * Nebraska Public Power District 84/02/29 16pp 22571 122 24X Fiche 50-298.84/02/29,8403090100
- 8403190089 Revised emergency plan implementing procedures, including Procedure 5 7 16 re release rate determination 5 7 17 re dose assessment & 5 7 19 re onsite radiological monitoring W/840314 ltr
 THOMASON, P V , PILANT, J M Nebraska Public Power District
 84/02/27 COLLINS, J T, Region 4, Office of Director 72pp
 22669 229 24X Fiche 50-276,84/02/27,8403190089
- 8403060264 Forwards "Program Plan for Detailed Control Room Design Review." including proposed schedule for implementation, per NUREQ-0737, Suppl 1 requirements PILANT.J M Nebraska Public Power District 84/03/01 EIBENHUT.D 0 Division of Licensing 1p 22515 225 24X Fiche 30-278.84/03/01.8403060284
- --8403060274 "Program Plan for Detailed Control Room Design Review"

 * Nebraska Public Power District 84/02/29 65pp 22515 226
 24X Fiche 50-298,84/03/01,8403060264
- 8403040354 Forwards descriptions of Reg Guide 1 97 requirements & schedule for implementation of emergency response capability, per NUREG-0737, Buppl 1
 PilANT, J M. Nebraska Public Power District 84/03/01
 EIBENHUT. D. 9 Division of Licensing 19pp 82515 311 24X
 Fiche. 50-298. 84/03/01. 8403060354
- 8403080265 Forwards three repts re facility safety parameter display sys (8PD8) per requirements of Suppl 1 to NUREG-0737 BPD8 will be installed during upcoming recirculation piping replacement outage PILANT.J M Nebraska Public Power District 84/03/01 EISENHUT.D.O Division of Licensing 2pp 22558 050 24X Fichs 50-298.84/03/01.8403080265
- --B4030B0268 "Bafety Parameter Display Bys Bafety Analysis " LOBNER,P Beience Applications, Inc 503-8500000-76 84/03/01 72pp, 22558-052 24X Fiche 50-298.84/03/01.8403080265
- --8403080273 Procedure 503-8500000-51, "Verification & Validation Plan"
 THOMAS, N Science Applications, Inc 84/03/01 67pp 22558 125
 24X Fiche 50-298,84/03/01,8403080265
- --8403080306 Procedure 503-8500000-27, "Safety Parameter Display Sys Implementation Flan " LUBNER,P Science Applications, Inc 84/03/01 30pp 22558 193 24X Fiche, 50-278, 84/03/01, 8403080265
- 8403200167 Forwards Rev 5 to safeguards plan Rev withheld (ref 10CFR73 21 & 2 790) PILANT, J M Nebraska Public Power District 84/03/14 Record Bervices Branch (Document Control Desk). 1p 22696 354 24X Fiche, 50-298, 84/03/14, 8403200167
- 8403220055 Forwards revs to emergency plan implementing procedures, including Rev 5 to Procedure 5 7 16 re release rate determination, Rev 5 to 5 7 17 re dose assessment, Rev 0 to 5 7.17 t & Rev 3 to 5 7 19 re monitoring W/o encl PILANT, J M Nebraska Public Power District 84/03/14 COLLINS, J T Region 4. Office of Director 1p 22713 358 24X Fiche, 50-298, 84/03/14, 8403220055
- 8403270013 Revised Emergency Plan Implementing Procedures EPIP 5 7 6. "Notification," EPIP 5.7, 20, "Protective Action Quides" & EPIP 5.7, 21, "Emergency Equipment Inventory " W/840322 ltr WHITMAN, D., WINDHAM, R., PILANT, J.M. Nebraska Public Power District 84/03/15. COLLINB, J.T. Region 4, Office of Director 60pp 22766:028 24% Fiche 50-298,84/03/15,8403270013.
- 8403220031 Ack receipt of 831205 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-278/83-27 JOHNSON,E.H Region 4. Office of Director 84/03/19 PILANT,J M Nebreska Public Fower District 1p 22712 321 24X Fiche, 50-298, 84/03/19, 8403220031.
- ---8403220042 Responds to NRC 831108 ltr re violations noted in IE Insp Rept 80-298/83-27. Corrective actions adequacy of interfaces w/state & local govts on emergency preparedness will receive add1 attention PILANT, J M Nebraska Public Power District, 83/12/05 JOHNSON, E H. Region 4, Office of Director 3pp. 22712 322 24X Ficher 50-298, 84/03/17, 8403220031

- P Operating license stage documents & correspondence
- 8403140340 Summary of 831215 meeting w/GE & Mark I Dwners Group in Bethesda.MD re Mark I containment wetwell-drywell vacuum breaker design methodology SIEGEL.D L Operating Reactors Branch 2 84/02/21 Operating Reactors Branch 2 51pp 22635 178 24X Fiche 50-000,84/02/21,8603140340
- 8403090100 Application for amend to License DPR-14, changing Tech Specs re fire detection instruments to comply w/NUREG-0737 (Generic Ltr 83-36), Items II B 1.II B 3, II F 1 & II D 3 4 KUNCL, L Q Nebraska Public Power District 84/02/29 VASSALLO, D B Operating Reactors Branch 2 6pp 22571 116 24X Fiche 50-298, 84/02/29, 8403090100
- --8403070116 Proposed radiological Tech Specs per NUREG-0737 (Generic Ltr 83-36) re fire detection instrumentation * Nebraska Public Power District 84/02/27 16pp 22571 122 24X Fichs 30-298.84/02/27.8403070100
- 84031R0290 Requests remittal of addl fee for review of 840118 application for Tech Spec change re standby gas treatment & auxiliary electric sys, core & containment cooling sys & torus temp monitoring sys DIGOS,R M License Fee Management Branch 84/03/01 PILANT, J M Nebraska Public Power District 1p 22615 362 24X Fichs. 50-298,84/03/01,8403120290
- 8403150168 Application for amend to License DPR-46, consisting of Proposed Change 7 to radiological effluent Tech Specs W/
 "Offsite Dose Assessment Manual for Assessment of Gaseous & Liquid Effluents "No fee required PILANT, J M Nebraska Public Power District 84/03/07 VASSALLO, D B Operating Reactors Branch 2 1p 22642 074 24X Fiche 50-298.84/03/07.8403150168
- --8403150171 Proposed Change 7 to radiological effluent Tech 8pecs * Nebraska Public Power District 84/03/07 72pp 22642 095 24K Fiche 50-298.84/03/07.8403180168
- --B403150173 "Offsite Dase Assessment Manual for Assessment of Gaseous & Liquid Effluents " * Nebraska Public Power District 84/01/31 125pp 22642 166 24% Fiche 50-298,84/03/07,8403150168
- 8403200254 Forwards Class IV fee per 840301 ltr PILANT, J M Nebraska Public Power District 84/03/13 DIGGS,R M License Fee Management Branch 1p 22691 107 24X Fiche 50-278.84/03/13.8403200254
- 8403150275 Generic Ltr 84-07 to all licensees of BWRs re procedural guidance for pipe replacement at BWRs Svc list encl EISENHUT, D G Division of Licensing 84/03/14 Commonwealth Edison Co 20pp 22823 334 24X Fiche 50-000.84/03/14,8403150275
- Q Inspection reports. IE Bulletins & correspondence
- 8403260235 Forwards IE Insp Rept 50-298/83-28 on 831018-21 & notice of violation JUNNSON.E H Region 4, Office of Director 84/02/17 PILANT, J M Nebraska Public Power District 2pp 22755 158 24X Fiche 50-298.84/02/17.8403240235
- --8403260238 Natice of violation from insp on 831018-21 * Region 4, Office of Director 84/02/17 2pp 22755 160 24X Fiche 50-298,84/02/17,8403260235
- --8403260240 IE Insp Rept 50-298/83-28 on 831018-21 Violation noted licensee presented no evidence that physician assistant trained to identify aberrant behavior Details withheld (ref 100FR79 21).

 CALDHELL: A A , KELLY, J A F , HUNNICUTT, D H Region 4: Diffice of Director 84/02/17 ip 22755 142 24X Fiche 30-298, 84/02/17, 8403260235
- 8403030091 Ack receipt of 840110 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-278/83-25 JOHNBON, E H Region 4, Office of Director, 84/02/24 PILANT, J M Nebraska Public Power District, ip 22488 059 24X Fichs. 50-278.84/02/24,8403050091
- --8403050095 Responds to NRC 831208 ltr re violations noted in IE Insp Rept 50-298/83-25 Corrective actions responsibilities for transcribing & forwarding safety review & audit board minutes transferred to individual w/fewer duties PILANT.J M Nebraska Public Power District 84/01/10 JOHNBON,E H Region 4. Office of Director 5pp 22488 060 24X Fiche 50-278.84/02/24.8403050091

- B401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl
- enci JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New Yark, Inc. 115pp. 22909 239 24X Piche 50-000,84/02/28,8401190072
- B403060392 Forwards "Inservice Insp Plan for ASME Class 1,2 & 3 Components," per B31216 commitment PILANT.J M Nebraska Public Power District 84/03/01 VASBALLO.D.B Operating Reactors Branch 2 1p. 22518 134. 24X Fiche 50-298,84/03/01.8403060392
- --8403060393 "Inservice Insp Flan for ASME Class 1,2 & 3 Components "
 * General Electric Co 84/03/01 15pp 22518 135 24X
 Fiche 50-298,84/03/01,8403060392
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE, J N Division of GA, Safeguards & Inspection Programs (Post 8330103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24x Fiche 50-000.84/03/02,8402070007
- 8402090008 IE info Notice 84-16, "Failure of Automatic Sprinkler Bys Valves to Operate " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York Inc 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008
- Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008
- 402090009 IL Info Notice 84-15, Reputiting of Recognization and Social State and Social State State Social State State State State Social Social State State
- 8402090011 IE Info Natice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN.E. L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc. 117gp 22553 336 24% Fiche: 50-000.84/03/05,8402070011
- 8403130307 Provides results of comparative analysis of liquid unknown sample performed by Radiological & Environ Sciences Lab in connection w/NRC confirmatory measurements insp in Oct 1983 JOHNSON, E. H. Region 4, Office of Director 84/03/06 PILANT, J. M. Nabraska Public Power District 3pp 22608 036 24x Fiche 50-278.84/03/06.8403130307
- 8402090024 IE Info Notice 84-09 Rev i, "Lessons Learned From Insps of Fire Protection Safe Shutdown 8ys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Past 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 047 24X Fiche 50-000.84/03/07,8402090024
- 8402090028 IE Info Notice 84~18, "Stress Corrosion Cracking in PWR Bys " Syc list entl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22984 186 24X Fiche 50-000.84/03/07.8402090028
- 8402090031 IE Bulletin R4-02. "Failures of CE Type HFA Relays in Use in Class IE Bafety Sys " Svc list enc!
 DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000.84/03/12.8402090031
- 8403160235 Ack receipt of 840118 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-298/83-31 JOHNSON,E H Region 4, Office of Director 84/03/12 PILANT,J M Nebraska Public Power District ip 22660 327 24x Fiche 50-298,84/03/12.8403160255
- --8403160260 Responds to NRC 831223 ltr re violations noted in IE Insp Rept 50-298/83-31 Corrective actions operations supervisor required to meet every wk w/crew in training to discuss reactor operation PILANT.J M Nebraska Public Power District 84/01/18 JOHNSON:E Region 4. Office of Director 4pp 22660:330 24X Ficha 30-298.84/03/12.8403160255
- 8403220031 Ack receipt of 831205 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-298/83-27 JOHNBON: 6H Region 4, Office of Director 84/03/19 PILANT, J M Nabraska Public Power District ip. 22712 321 24X Fiche 50-298/84/03/19/8403220031

- --8403220042 Responds to NRC 831108 ltr re violations noted in IE Insp Rept 80-298/83-27 Corrective actions adequacy of interfaces w/state & local goots on emergency preparadness will receive add1 attention PILANT.J M Nebrasta Public Power District 83/12/05 JOHNSON,E H Region 4, Office of Director 3pp 22712 322 24X Fichs 50-298,84/03/19,8403220031
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24% Fiche 50-000.84/03/21,8402090043
- B402090044 IE Info Notice 84-20, "Byo Life of Relays in Sefety-Related Bys " Byo list encl JDRDANAE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044
- R Periodic operating reports & related correspondence
- 8403020083 Monthly operating rept for Jan 1984 W/840207 ltm BALLINGER.P L . THOMASON.F V Nebraska Public Power District 84/01/31 5pp 22441 211 24X Fiche 50-298,84/01/31,8403020083
- 8403300150 Monthly operating rept for Feb 1984 W/840307 ltr 84LLINGER,P L , THOMASON,P V Nebraska Public Power District 84/02/29 5pp 22817 352, 24X Fiche,50-298,84/02/29,8403300150
- B Reportable occurrences, LERs & related correspondence
- B310280186 Forwards Safety Engineering Evaluation AEOD/E319. "Loss of Drywell-Torus Pressure Differential During RHR Pump Flow Testing at Cooper Nuclear Station "Licensee corrective actions adequate RUBIN-8 D Reactor Operations Analysis Branch 83/09/08 SEYFRIT.K V Reactor Operations Analysis Branch 1p 22775 205 24X Fiche 50-298.83/09/08,8310280186
- --8310280188 "Loss of Drywell-Torus Pressure Differential During RHR Pump Flow Testing of Cooper Nuclear Btation " RUMIN.8 Director's Office 83/09/08 Fiche 50-278,83/09/08,8310280186
- DOCKET 50-301 POINT BEACH NUCLEAR PLANT, UNIT 2
- B401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list enc!

 JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/02/28 Consolidated Editor Co of New York, Inc 115pp 22709 237 24X Fiche 30-000.84/02/28. B401190072.
- F Security, medical, emergency & fire protection plans
- 8403050208 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licenser.per 810709 Generic Ltr 81-27 W/o request entire plan will be placed in PRR MILLER, J R Operating Reactors Branch 3 84/02/16, FAY, C W Wisconsin Electric Power Co 2pp 22528 152 24X Fiche 50-266,84/02/16,8403050208
- B403120045 Notifies of B40323 workshop on fire protection safe shutdown requirements of 10CFR50. App R in Rosemont, IL to discuss IE Info Notice 84-09 & provide add 1 shutdown analyses &/or mad guidance Agenda enci SPEBBARD. R L Division of Emergency Preparedness & Operational Support B4/03/06 BURSTEINS Wisconsin Electric Power Co Spp 22570 274 24X Fiche 50-266.84/03/06.8403120045
- 8403160080 Submits add1 info on Generic Ltr 82-33 schedule requirements for emergency response capabilities Vendor of new computer sys requested 1-yr delay to June 1985 for delivery, affecting schedular commitments made to NRC FAY.C W Hisconsin Electric Power Co 84/03/08 DENTON, H R Office of Nuclear Reactor Regulation. Director 4pp. 22652 327. 24X Fiche 50-266,84/03/08,8403160080
- 8403220093 Ack receipt of 840306 ltr informing NRC of corrective actions re deviation from commitment & resolution of revised emergency plan Ser clarification items noted in IE Insp Repts 50-266/83-25 & 50-301/83-25 PAPERIELLO.C J Region 3. Office of Director 84/03/19. BURSTEIN.S Wisconsin Electric Power Co. ip. 22716-324. 24X Fichs 50-266.84/03/19.8403220093

--8403220099 Responds to NRC 840202 itr forwarding revised emergency plan SER & request for clarification of listed items & deviation from commitment Corrective actions Procedure EP 5 0. "Organizational Control of Emergencies." revised FAV.C W Wisconsin Electric Power Co 84703/06 KEPPLER, J 0 Region 3. Office of Director 9pp 22716 325 24X Ficha 50-266,84703/19,8403220093

O. Adjudicatory correspondence

- B402220157 Order extending time until 840228 for Commission to act to review Director's Decision DD-83-14 GHILK, 8 J Office of the Secretary of the Commission B4/02/21 Commissioners ip 22337 362 24X Fiche 50-000.84/02/21,
- 840301023B Order extending time until 840305 for Commission to act to review Director's Decision DD-83-14 & 831029 decision denying request of Environ Policy Inst CHILM, 8 J Office of the Secretary of the Commission 84/02/28 Commissioners ip 22434 210 24X Fiche 50-000,84/02/28,
- 8403090069 Informs that Commission Unanimously declined to review Director's Decision DD-83-14 Time provided by NRC regulations within which Commission may act to review expired Decision became final agency action on 840305 CHILK, B J Office of the Secretary of the Commission 84/03/08 CELEBREZIE, A J Ohio, State of 2pp 22575,350 24x Fiche 50-000,84/03/08,8403090069
- 8403070074 Informs that Commission Unanimously declined to review Director's Dacision DD-83-14 Time provided by NRC regulations within which Commission may act to review sypired Decision became final agency action on 840305 CHILK.8 J Office of the Secretary of the Commission 84/03/08 MILLAR, F Environmental Policy Institute ip 22575 272 24X Fiche 50-000.84/03/08.8403070074
- 8403090113 Informs of Commission decision not to review Director's Decision DD-83-14 Time for Commission to act expired on 840305 W/o encl CHILK,6 J Office of the Secretary of the Commission 84/03/08 RESNIKUFF,M Sierra Club ip 22576 079 24X Fiche 50-000,84/03/08,8403090113

P. Operating license stage documents & correspondence

- 8403270002 Final response to FOIA request for four categories of documents, tests, studies & analyses referencing or pertaining to NUREG-0103, "BTB for B&W PWR " App A documents encl FELTON, J M Division of Rules and Records 84/01/13 MADDEN, T J Kaya, Scholer, Fierman, Hays & Handler 6pp 22816 127 24X Fiche, 50-000, 84/01/13, 8403270002
- --8403290045 Discusses O Reed 730301 ltr to Q Arlotto re RCPB leakage detection sys Method for detecting slow departure from normal indications of leakage detection sys provided in util monitoring charts
 PORSE.L. Atomic Energy Commission Directorate of Regulatory Standards 73/03/07 WICHMAN.K Atomic Energy Commission 2pp 22816.303 24X Ficher 50-000,84/01/13.8403270002
- ---8403290049 Forwards info describing RCS leakage monitoring Related info encl REED, 0 A Wisconsin Electric Power Co 73/03/01 ARLOTTO, 0 Atomic Energy Commission - Directorate of Regulatory Standards 40pp 22817:330, 24X Fiche:50-000,84/01/13.8403290002
- 8403070255 Application for amend to Licenses DPR-24 & DPR-27. Amend incorporates changes to Tech Specs re accident monitoring instrumentation to be installed per NUREO-0737 requirement FAY. 6. W Wisconsin Electric Power Co. 84/02/29 DENTON. H.R Office of Nuclear Reactor Regulation, Director. MILLER, J R Operating Reactors Branch 5 App. 22536:179. 24X Fiche: 50-264, 84/02/29, 8403070255
- ---B403070257 Proposed Tach Specs incorporating changes is accident monitoring instrumentation to be installed per NUREG-0737 requirement # Wisconsin Electric Power Co 84/02/27, 10pp 22536 183 24X Fiche 50-266,84/02/27,8403070255
- 8403060575 Informs that encl notice of consideration of issuance of amend to Licenses DPR-24 & DPR-27 & proposed NBHC determination & opportunity for hearing sent to Ofc of FR for publication, Amend concerns leak surveillance W/o encl COLBURN.T.9 Operating Reactors Breach 3 84/03/01 FAY.C W Wisconsin Electric Power Co. 1p 22552.255 24X Fiche: 50-266,84/03/01,8403060575

- 8403220254 Forwards FR notice of consideration of issuance of amend to Licenses DPR-24 & DPR-27 & proposed NSHC & opportunity for hearing re 831223 application to revise surveillance interval for post-accident recovery sys outside containment COLBURN.TO Operating Reactors Branch 3 84/03/01 FAY.C W Wisconsin Electric Power CO 2pp 22723 325 24X Fiche 50-266.84/03/01.8403220254
- --8403220259 FR notice of consideration of issuance of amend to Licenses DPR-24 & DPR-27 & proposed NBMC & opportunity for hearing re B31223 application to revise surveillance interval for post-accident recovery sys outside containment MILLER, J R Operating Reactors Branch 3 84/02/09 8pp 22723 327 24X Fiche 50-246.84/03/01.8403220254
- 8403120157 Advises that due to delays in delivery & installation of auxiliary safety instrumentation panels (ASIPs).installation of six accident monitors addressed in NUREG-0737. Items II F 1 i through II F 1 6 will not be completed by 840630 FAY.C W Wisconsin Electric Power Co 84/03/05 DENTON, H R Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3 Spp 22586 250 24X Fiche 50-266.84/03/05.8403120157
- 8403190419 Comments on 840207 ltr modifying 831025 request for amends to Tech Specs re changes in conduct of containment integrated leak test rates No significant hazards consideration discussion required MILLER, J R Operating Reactors Branch 3 84/03/04 FAY, C W Misconsin Electric Power Co 2pp 22681 344 24X Fiche 50-266,84/03/06,8403190419
- B403210077 Responds to Generic Ltr 84-01 re use of terms important to safety & safety-related Widespread use of terms in NRC regulations considered unresolved Notification of meeting requested FAY: C W Wisconsin Electric Power Co 84/03/15 EISENHUT, D G Division of Licensing TAYLOR. J M Director's Office, Office of Inspection and Enforcement ip 82705 165 24X Fiche, 50-266,84/03/15,8403210077
- B403220162 Application to amend Licenses DPR-24 & DPR-27, changing Tech Speck to add add1 restrictions on heavy loads over spent fuel pool & making additions & deletions re safety-related snubbars.per IE Bulletin 79-14 & Item II D 1 FAY.C W Wisconsin Electric Power Co 84/03/16 DENTON.H R Office of Nuclear Reactor Regulation, Director MILLER, T R. Operating Reactors Branch 3 4pp 22718 057 24X Fichs 50-266,84/03/16,8403220162
- --8403220167 Proposed Tech Specs, adding add1 restrictions on heavy loads over spont fuel pool, making additions & deletions to list of safety-related snubbers & revising position titles within administrative specs
 # Wisconsin Electric Power Co 84/03/16, 29pp, 22718 061 24X Fiche 50-266,84/03/16,8403220162
- 8403270078 Responds to request for Tech Spec change to limit amount of overtime worked by plant staff members performing safety-related functions Amend to Tech Specs delayed pending adoption of Commission proposed rule
 FAY.C.W Wisconsin Electric Power Co 84/03/17 DENTON, H.R. Office of Nuclear Reactor Regulation, Director MILLER, J.R. Operating Reactors Branch 3 2pp 22766 337 24X
 Fiche 50-266,84/03/17.8403270078
- Q Inspection reports, IE Bulletins & correspondence
- 8403050223 Further response to FOIA request for records of named individuals, including repts, analyses, studies, test calculations, procedures & practices for measurement of RCB leakage forwards App C documents Bearch continuing FELTON, J M Division of Rules and Records 84/02/07 MADDEN, T. J Kaye, Scholer, Fierman, Hays & Handler 3pp 22496 234 24X Fiche 50-000,84/02/07,8403050223
- --B403050256 Notifies that independent measurements of identified & unidentified RCS leak rates for all PWRs in Region III performed per Procedures 617278 & 617288 Insp findings summarized NORELIUS: C E Division of Engineering 82/03/08, JORDAN, E L Division of Engineering & Guality Assurence (Pre 630(03) 2pp 22496 270 24X Fiche. 50-000, 84/02/07, 8403050223
- 8403040151 Forwards JE Insp Repts 50-264/83-21 & 50-301/83-20 on 831011-840111 & mgt meeting on 840104 & notice of violation 8PE88ARD,R. L. Region 3: Dffice of Director. 84/02/2: BURETEIN.S Wisconsin Electric Power Co. 3pp. 22906 182 24X Fiche 50-266.84/02/21.8403060151
- --8403060162 Notice of violation from insp on 831011-840111 SPEBBARD,R L. Region 3, Office of Director 84/02/21. 6pp 22306 185 24X Fiche 50-266,84/02/21.8403060151

- --8403060176 IE Insp Repts 50-266/83-21 & 50-301/83-20 on 831011-840111 & mgt meeting on 840104 Viblation noted failure to maintain cleanliness control, provide & follow procedures, control documents & properly store records

 MASSE.R A. CHOULES.N.C. JORDAN.M.J. Region 3. Office of Director 84/02/13 54pp 22506 191 24X Fiche 50-266,84/02/21.
- B403130002 Forwards IE Insp Repts 50-266/83-26 & 50-301/83-24 on 831201-840131 & notice of violation 84APER.W D Region 3. Office of Director 84/02/22 BURSTEIN.S Wisconsin Electric Power Co 2pp 22615 267 24X Fiche 50-266.84/02/22.8403130002
- --8403130011 Notice of violation from insp on 831201-840131 SHAFER,W D Region 3. Office of Director 84/09/22 2pp 22615 269 24X Fiche 50-266,84/02/22,8403130002
- --8403130023 IE Insp Repts 50-266/83-26 & 50-301/83-24 on 831201-840131 Noncompliance noted fire in containment resulted when welding stag landed on acetylene hose attached to acetylene bottle not in use & not moved to safer location HAGUE, R L , FITZPATRICK, B , JACKIM, I N Region 3, Office of Director 84/02/21 9pp 22615 271 24X Fiche 50-266.84/02/22, 8403130002
- 8402070007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl QRACE.U N Division of QA. Safeguards & Inspection Programs (Post 830103) 84703/02 Consolidated Edison Co of New York. Inc. 130pp 22552 327 24X Fiche 50-000.84703/02.8402090007
- 8402070008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 122pp 22553 078 24X Fiche.50-000,84/03/02,8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases" Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/02 Consolidated Edison Co. of New York, Inc. 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 840209001; IE Info Notice 84-17, "Problems H/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000.84/03/05,8402090011
- 8402090024 IE Info Notice B4-09.Rev i. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24% Fiche 50-000.84/03/07.8402090024
- 8402090028 IC Info Notice 84-18, "Stress Corrosion Cracking in PWR Bys " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc. 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8402070031 IE Bulletin 84~02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl DEYCUNO, R C Director's Office of Defice of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York. Inc 134pp 22823 094 24X Fiche 50-000.84/03/12,8402090031
- 8403220093 Ack receipt of 840306 ltr informing NRC of corrective actions re deviation from commitment & resolution of revised emergency plan SER clarification items noted in IE Inap Repts 50-266/83-25 & 50-301/83-25 PAFERIELLO.C J. Region 3, Office of Director 94/03/19 BURSTEIN.S Hisconsin Electric Power Co. 1p. 22716 324 24% Fiche 50-266,84/03/19,8403220093
- --8403220079 Responds to NRC 840202 ltr forwarding revised emergency plan SER & request for clarification of listed items & deviation from commitment Corrective actions Procedure EP 5 0, "Organizational Control of Emergencies," revised, FAY,C W Wisconsin Electric Power Co 84/03/06 KEPPLER,J 0, PAPERIELLO,C J Region 3, Office of Director 9pp 22716,325 24% Fiche 50-266.84/03/19,8403220093
- 8402090043 IE Info Notice 84-19. "Two Events Involving Unauthorized Entries into PUR Reactor Cavities " Svc list ancl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). B4/03/21 Consolidated Edison Co of New York Inc 123pp 22823 229 24% Fiche 50-000,84/03/21,8402090043

- 8402070044 IE Info Notice 84~20, "Byc Life of Relays in Safety-Related Sys " Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22733 001 24X Fich 50-000.84/03/21,8402070044
- R Periodic operating reports & related correspondence
- 8403060338 "Bemiannual Monitoring Rept.Jul-Dec 1983" W/840229 ltr FAY,C W Misconsin Electric Power Co 83/12/31 DENTON.H R Office of Nuclear Reactor Regulation, Director 18pp 22517 026 24X Fiche 50-266.83/12/31,8403060338
- B403120066 "Annual Results & Data Rept.1983 " W/840301 ltr FAY,C W Wisconsin Electric Power Co B3/12/31 KEPPLER.J Q Region 3. Office of Director 59pp 22591 070 24X Fiche 50-266.83/12/31.8403120066
- 8403140139 Monthly operating repts for Feb 1984 W/840308 ltr FAY, C W Misconsin Electric Fower Co 84/02/27 11pp 22620, 252 24X Fiths 50-266, 84/02/29, 8403140139
- 8 Reportable occurrences, LERs & related correspondence
- 8403230068 LER BA-001-00 on B40223; pipe snubber ID 2HB-M75 removed for NUREO-0737 mod prior to obtaining Tech Spac change allowing removal Snubber reinstalled within 72 h Tech Spac change to delete snubber initiated W/840315 ltr
 FAY.C W Wisconsin Electric Power Co B4/03/15. KEPPLER: J Q. Region 3. Office of Director. 3pp 22726 324 24X
 Fiche 50-301.84/03/15.8403230068
- DOCKET 50-302 CRYBTAL RIVER NUCLEAR PLANT, UNIT 3

 F Security, medical, emergency & fire protection plans
- B403120394 Forwards order confirming licenses commitments to implement post-TMI-related items set forth in Suppl 1 to NUREO-0737, "Requirements for Emergency Response Capability " Order based on util responses to 821213 Generic Ltr 82-33 STOL7.J F Operating Reactors Branch 4 84/02/21 WILQUB.W 8 Florida Power Corp 3pp 22618 327 24X Fiche 50-302,84/02/21, 8403120354
- --8403120359 Order confirming licensee commitments on emergency response capability.per Suppl 1 to NUREO-0737 EIBENHUT.D 9 Division of Licensing 84/02/21 Florida Power Corp 6pp 22615 332 24X Fiche 50-302.84/02/21,8403120354
- 8403010072 Forwards modified amended security plan.Rev 4 Rev withheld (ref 10CFR73 21)
 HESTAPER.G R Florida Power Corp 84/02/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 22436 111 24X
 Fiche.50-302.84/02/23 8403010072
- 8403290262 Forwards IE Insp Rept 50-302/84-04 on 840206-07 No violations or deviations noted DANCE, H C Division of Project & Resident Programs, 84/03/0 NILOUS W 8 Florida Power Corp 2pp 22800 169 24X Ficho 50-302,84/03/01,8403290262
- --8403290266 IE Insp Rept 50-302/84-04 on 840206-07. No violations or deviations noted Major areas inspected amongency preparedness protective action recommendations HUFFHAN: ON Region 2. Diffice of Director JENKINB. C.R Division of Emergency Preparedness & Naturials Bafety 84/02/27 App 22800 171 24X Fiche 50-302,84/03/01.8403290262
- 8403140285 Notifies of 840314 workshop to discuss 10CFR50, App R requirements & results of insps to resolve misunderstandings re fire protection. Attendees should be limited to six due to conference room size

 LEWIS.R C Division of Project & Resident Programs 84/03/02 WILGUS W 8 Florida Power Corp ip 22640 272 24x

 Fichs 50-302.84/03/02.8403160285
- 8403160334 Ack receipt of 840209 ltr re emergency exercise scheduled during Apr 1984
 DANGE, H C Division of Project & Resident Progrems 84/03/02
 WILQUB, W S Florida Power Corp 2pp 22660, ORY 24X
 Fichs 50-302,84/03/02,8403160334
- 8403160335 Forwards IE Safeguards Insp Rept 50-302/84-05 on 840213-17 & notice of violation Notice of violation withheld (ref 10CFR2.790)
 LEWIS, R C Division of Project & Resident Programs 84/03/08
 Florida Power Corp. 2pp 22659 162 24X Fiche: 50-302,84/03/08,

- --8403160388 IE Bafeguards Insp Rept 50-302/84-05 on 840213-17 Violations noted Details withheld (ref 10CFR2 790 & 73 21)

 HALL.B L Region 2, Office of Director McGUIRE, D R Division of Emergency Preparadness & Materials Safety 84/03/02 1p 22659 164 24X Fiche 50-302,84/03/08,8403160335
- 8403130033 Ack receipt of 840123 ltr forwarding Rev 2 to physical security plan Changes consistent w/provisions of 10CFR50 54(p) & acceptable LEWIS.R.C Division of Project & Resident Programs 84/03/09 WILOUS.W B Florida Power Corp 3pp 22614 324 24X Fiche 50-302.84/03/09.8403130033

H General correspondence

- 8403280149 Responds to 840208 ltr requesting assistance in responding to J Paskavitch ltr requesting latest EIS on concentrations of 8r-90.Cs-137 & I-131 near plants Two annual repts encl W/o repts
 DIRCKS.W J. Office of the Executive Director for Operations
 84/03/07 CHILES.L Senate 4pp 2R809 316 24X
 Fiche 50-000.84/03/07.8403280149
- --8403280136 Forwards constituent J Paskavitch 1tr requesting latest EIS on concentrations of Sr-90,Cs-137 & I-131 near plants Comments & views requested CHILEG.L Senate 84/02/08 KAMMERER,C Office of Congressional Affairs 8pp 22809 320 24X Fiche 50-000,84/03/07,8403280149

J Insurance & indemnity information

8403060353 Forwards Endorsement 69 to NELIA Policy NF-175 DUCK.J.R. Marsh & McLennan, Inc 84/02/28 SALTZMAN, J Assistant Director for State & Licensee Relations 2pp 22519 071 24X Fiche 50-302,84/02/28,8403060353

P Operating license stage documents & correspondence

- B402060419 Application for amend to License DPR-72 consisting of Tech Bpsc Change Request 112 revising restrictions on steam generator operating level to be based on inventory instead of operating level alone MESTAFER, O.R. Florida Power Corp. 84/01/30 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 5pp. 22085 141 24X Fiche: 50-302,84/01/30,8402060419
- --8402060421 Proposed Tech Specs re steam generator operating levels # Florida Power Corp 84/01/30 14pp 22085 146 24X Fiche 50-302,84/01/30.8402060419
- 8403060359 Application for amend to License DPR-72 changing Tech Spect to allow increase in enrichment of fuel assemblies from 3 3 weight percent to 3 5 weight percent U-235 WESTAFER.O.R Florida Power Corp. 84/02/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 22511,208 24X Fiche: 30-302.84/02/24,8490360359
- --8403060362 Proposed Tech Specs allowing increase in enrichment of fuel assemblies from 3 3 weight percent to 3.5 weight percent U-235 NBHC determination enc! # Florida Power Corp. 84/02/24 3pp 22511 213 24X Fiche 50-302,84/02/24,8403060359
- ---8403060366 "Criticality Bafaty Analysis of Crystal River Bpent Fual Storage Rack " TURNER, 6. E., QURLEY, M.K., Florida Power Corp. 88-152 83/12/31 19pp 22511:216 24X Fiche:50-302:84/02/24,8403060359
- 8403060364 Revised application for amend to License DPR-72, changing Tach Specs to reflect addition of two independent, in-place hydrogen monitors. Certificate of Svc encl. WESTAFER, O.R. Florida Power Corp 84/02/24 DENTON, H R Office of Nuclear Reactor Regulation, Director Spp 22511 297 24X Fiche: 50-302, 84/02/24, 8403060364
- --B40306036B Proposed Tech Specs reflecting addition of two independent, in-place hydrogen monitors, in response to NUREG-0737, Item II F 1.

 * Florida Power Corp. B4/02/24 Ppp 22511 303 24X Fiche. 50-302, B4/02/24, 8403060364
- 84030£0343 Submits add1 info re emergency feedwater sys program Gilbert Assoc hired to investigate emergency feedwater turbine concern. Detailed rept will be available by 840630 WEBTAFER, 9 R Florida Power Gorp 84/02/29 BTOLZ, J F Operating Reactors Brench 4 2pp 22519 080 24X Fiche 50-302, 84/02/29, 8400360343

- B403160231 Summarizes B40214 mgt meeting w/util in Atlanta. QA re mgt activities & future plans Meeting beneficial Attendance list encl
 LEWIS.R C Division of Project & Resident Programs 84/02/29
 WILGUS.W S Florida Power Corp 3pg 22660 325 24X
 Fiche 50-302.84/02/29.8403160231
- 840312013D Comments on NUREG-0737. Item II II i, "RC8 Vents" Six listed items completed, per 830903 SER RC8 vent sys solenoid valves not susceptible to common mode failure No corrective action necessary
 WESTAFER, G.R. Fibrida Power Corp. 84/03/07 STGLZ, J.F. Operating Reactors Branch 4 3pp 22588 202 24X Fiche 50-302, 84/03/07, 8403120130
- B403190427 Notification of B40405 meeting w/util & General Physics Corp in Bethesda.MD to discuss NRC 840207 comments on control room design review program plan Agenda sncl HERNAN.R Operating Reactors Branch 4 84/03/09 STOLZ, J F Operating Reactors Branch 4 3pp 22681 328 24X Fiche 50-302,84/03/09,8403190427
- 8403160315 Application to amend License DPR-42, proposing supply power to circuit from 230 kV offsite transmission network through either CR-1 or CR-2 distribution sys in order to avoid shutdown during maint outage WESTAFER, G R Florida Power Corp 84/03/12 STQLZ, J F Operating Reactors Branch 4 2pp 22660 099 24X Fichs 50-302,84/03/12,8403160315
- --8403160320 Proposed Tech Spec depicting alternate paths for offsite power sources during maint outage
 * Florida Power Corp. 84/03/12 lp 22660 101 24X
 Fiche 50-302,84/03/12,8403160315
- 8403200038 Application for amend to License DPR-72, changing Tech Specs reclassifying accessibility on snubbers & requesting relief from requirement for visual insp WESTAFER, 0 R Florida Power Corp 84/03/12 DENYON, H R Office of Nuclear Reactor Regulation, Director 9pp 22698 327 24X Fiche 90-302,849/03/12,8403200038
- ---8403200044 Proposed Tech Specs, changing Accessibility on snubbers & requesting relief from visual insp requirements
 * Florida Power Corp 84/03/12 7pp 22678 336 24X
 Fiche 50-302, 84/03/12,8403200038
- 8403200265 Submits notes of conference from second quarterly progress meeting on 840202 re 316 Study.per NPDES permit reporting requirements HESTAFER.Q R Florida Power Corp 84/03/15 DENTON.H R Office of Nuclear Reactor Regulation, Director 9pp 22697 013 24% Fiche 50-302.84/03/15.8403200265
- 8403230014 Confirms info given in 840316 telcon re administative controls during paralleling 4160-volt busses while supplying facility cable from Unit 2 step-up transformer WEBTAFER, Q R Florida Power & Light Co 84/03/19 STOLZ, J F Operating Reactors Branch 4 2pp 22726 361 24X Fichs 50-302,84/03/19,8403230014
- 8403230062 Application to amend License DPR-72, consisting of Suppl | Lo Tech Spec Change Request ii2, to provide greater assurance that operation w/flooded assirating ports etrictly prohibited Certificate of Svc encl WESTAFER, O R Florida Power Corp 84/03/20 DENTON, H R Office of Nuclear Reactor Regulation, Director App 22726 319, 24% Fiche 50-302,84/03/20,8403230062
- --B403230067 Proposed Tech Spec Figure 3 4-5, "Max Allowable Steam Qenerator Level" # Florida Power Corp 84/03/20 1p 22726-323 24X Fichs 50-302,84/03/20,8403230062
- 8403270157 Application to amend License DPR-72, consisting of Tech Spac Change Request 36, Suppl 3 extending implementation of radiological effluent Tech Space to permit installation of oxygen & hydrogen analyzens Certificate of Svc anci MEBTAFER OR Florida Power Corp 84/03/22 DENTON: H R Office of Nuclear Reactor Regulation, Director 5pp 22806 063 24X Fiche 50-302.84/03/22,8403290159
- --8403270162 Proposed Tech Spec changes re radioactive gaseous effluent monitoring instrumentation surveillance requirements * Florida Power Corp 84/03/22 10pp 22806 068, 24X Fiche 50-302, 84/03/22, 8403270159

- O Inspection reports. 1E Bulletins & correspondence
- 8403290231 Forwards IE Insp Rept 50-302/84-01 on 840130-0203 No violations or deviations noted DANCE.** C Division of Project & Resident Programs 84/02/23 WILGUS, W & Florida Power Corp 2pp 22800 186. 24X Fiche 50-302,84/02/27,8403290231
- ---8403270234 IE Insp Rept 50-302/84-01 on 840130-0203 No violations or deviations noted Major areas inspected QA, training, posting & labeling, external exposure control, radiation insp. plant tours & outage preplanning.
 FRANKLIN-L A , BARR.K Region 2. Office of Director 84/02/23 5pp 28800 188 24X Fiche 50-302,84/02/27,8403270231
- B401190072 IE Info Notice B4-13. "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation." Svc list enci JORDANIE L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/02/28 Consolidated Edison Co. of New York: Inc. 110pp 22707 237 24X Fichs 50-000.84/02/28,8401190072
- 8403050402 Forwards Rev 0 to 04-5077-204. "Masonry Wall Reevaluation Program Including Response to NRC Guestions." in response to 831127 request for addl info re IE Bulletin 80-11 WESTAFER. G R Florida Power Corp. 84/02/29 BTGLZ, J F Operating Reactors Branch 4 2pp. 22511 235 24X Fiche 50-302,84/02/29, 8403050402
- ---8403060414 Rev O to 04-5079-204, "Masonry Wall Reevaluation Program Including Response to NRC Questions"
 * Oilbert Associates, Inc. 04-5079-204 ROO 84/02/10 40pp 22511 237 24% Fiche 50-302,84/02/29,8403040402
- B403290262 Forwards IE Insp Rept 50-302/B4-04 on B40206-07 No violations or deviations noted DANCE.H C Division of Project & Resident Programs B4/03/0 HILOUS, W S Florida Power Corp 2pp 22800 169 24X Fiche 30-302.84/03/01.8403290262
- --8403290266 IE Insp Rept 50-302/84-04 on 840206-07 No violations or deviations noted. Major areas inspected emergency preparedness protective action recommendations HUFFMAN, 8 N Region 2. Defice of Director JENKINS, 8 R Division of Emergency Preparedness & Materials Safety, 84/02/27 App 22800 171 24% Fiche 50-302.84/03/01.8403290262
- 2402090007 IE Info Notice 84-14. "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list ent! GRACE.J N Division of GA. Safeguards & Inspection Programs (Post B30103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 327 24x Fiche 50-000.84/03/02.8402090007
- '402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Bys Valves to Operate " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/02 Consolidated Edison Co. of New York, Inc. 122pp 22553 098 24X Fiche 50-000.84/03/02,8402090008
- 402070009 IE Info Notice 84-15, "Reporting of Radiological Releases" Svc 1/st encl
 JURDANN E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc 117pp 22553 217 24x Fiche 50-000.84/03/02,8402070007
- 402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp" Svc 11st encl JURDAN.E L. Division of Emergency Preparedness & Engineering Response (Post B30103) B4/03/05 Consolidated Edison Co of New York, Inc 117pp. 22553 336, 24X Fiche 50-000.84/03/05,8402090011
- 102090024 IE Info Notice 84-09.Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl.

 JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche: 50-000-84/03/07.8402090024
- 102090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Sys." Sec 11st encl
 JORDAN,E t. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/07. Consolidated Edison Co of New
 York, Inc. 118pp 22584:186 24X Fiche 50-000,84/03/07.8402090088
- O3160335 Forwards IE Bafeguards Insp Rept 50-302/84-05 on 840213-17 & notice of violation Notice of violation withheld (ref 100FR2 790)
 LEWIS, R.C. Division of Project & Resident Programs 84/03/08
 Florida Power Corp 2pp 22659 162 24X Fiche 50-302,84/03/08,8403160335

- --840316038B IE Bafeguards Insp Rept 50-302/84-05 on 840213-17 Violations noted Details withheld (ref 10CFR2 790 & 73 21) HALL,B L Region 2. Office of Director McOUIRE, D R Division of Emergency Preparedness & Materials B
- 8402070031 IE Bulletin 84-02. "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl.
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 074 24X Fiche 50-000.84/03/12.8402090031.
- 8403200038 Application for amend to License DPR-72, changing Tech Specs reclassifying accessibility on snubbers & requesting relief from requirement for visual insp.

 MESTAFER, Q.R. Florida Power Corp. 84/03/12 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 9pp. 22698-327. 24X

 Fiche. 50-302, 84/03/12, 8403200038
- --B403200044 Proposed Tech Specs, changing accessibility on snubbers & requesting relief from visual insp requirements.
 * Florida Power Corp 84/03/12 7pp. 22698:336 24X
 Fiche 50-302,84/03/12,8403200038
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JORDAN,E. L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York Inc. 123pp 22823 229 24X Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sqs " Svc list ancl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc. 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044
- R Periodic operating reports & related correspondence
- B403040283 Monthly operating rept for Jan 1984.W/840207 ltr GRAHAM.D., FIELDS.D., WESTAFER.Q R Florida Power Corp DEYQUNQ.R C Office of International Programs, Director. 5pp 22517 021 24% Ficha 80-302,B4/01/31,8403040283
- B403160036 Menthly operating rept for Feb 1984 W/840312 ltr CULVER.M W. ORAHAM.D. WEBTAFER.G R Florida Fower Corp DEYOUND.R C Director's Office. Office of Inspection and Enforcement 5pp. 22655:001 24X Fiche 50-302.84/02/29,8403160036
- S Reportable occurrences, LERs & related correspondence
- 8403020235 PND-II-84-019 on 840228, trip occurred, interrupting electric svc Caused by lightening arrestor failing on 230-kV line due to voltage transient sensed by reactor coolant pump power monitors Svc restored within 30 minutes
 ROGGE, JF., PANCIERA.V Region 2. Office of Director 84/02/28
 2pp. 22440 079, 24X Fiche 50-302,84/02/28,8403020235
- 8403090193 NPDES noncompliance notification forwards two ltrs in response to EPA 840206 ltr concerning exceeding temp limits & notification of antifouling paint use on cooling water inlet pipes & pits respectively

 WESTAFER 0 R Florida Power Corp. 84/03/06 DENTON, H R Office of Nuclear Reactor Regulation, Director. 6pp 22575 050 24X

 Fichs 50-302.84/03/06,8403090193
- 8403300111 Forwards EPA 840302 ltr informing of NPDES noncompliance notification Util failed to rept heavy metal concentrations for south ash pond discharge Serial Number 009 for Oct 1983 WESTAFER, O R Florida Power Corp. 84/03/26 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 22821 225, 24X Fiche 50-302,84/03/26,8403300111
- --8403300115 NPDEB noncompliance notification Advises that util failed to rept heavy metal concentrations for Discharge 009 as result of inadequate sampling procedures Sampling procedures modified

 HANCOCK, J. A. Florida Power Corp. 84/03/19 MCGARRY, P. T. Environmental Protection Agency Spp. 22821: 227 24X

 Fiche 50-302, 84/03/26, 8403300116

• 1

- DOCKET 50-304 ZION NUCLEAR POWER STATION, UNIT 2
- F Security, medical, emergency & fire protection plans
- BAOG1400B2 Public version of Rev 12 to Emergency Plan Implementing Procedure EPIP 700-1, "Emergency Phone List " W/831021 receipt form & JM Feiton B40312 release memo. NYXIRK JW , PLIML, 9 Commonwealth Edison Co 83/10/26, 16pp 22646 119 24X Fiche 50-275,83/10/26,8403140082.

- 8403280119 Public version of Rev 7 to Emergency Plan Implementing Procedure EPIP 440-1. "Emergency Communications Sys & Operational Tests: "M/640110 procedure change request form & JM Feiton 840322 release memo PLIML, O Commonwealth Edison Co 84/01/04 DENTON, H R NRC No Debatiled Affiliation Given 21pp Fiche 50-275.84/01/04.8403280119
- 8403020003 Revised emergency implementing procedures including Rev 1 to Procedure EPIP 100-1: "Acting Station Director" W/840301 ltr # Commonwealth Edison Co 84/02/21 8pp 22442 i87 24X Fiche 50-295,84/02/21:8403020003
- 8403120326 Notification of 84030B meeting w/util in Bethesda.MD to discuss status of implementation of fire protection mod & proposed interim compensatory measures
 NORRIS.J A Operating Reactors Branch i 84/03/01 VARGA.S A Operating Reactors Branch i 2pp 22596 353 24X
 Fiche 50-295,84/03/01.8403120326
- 8403190314 Forwards IE Insp Repts 50-295/83-27 & 50-304/83-28 on 831122-1228 & 840202 & notice of violation Concerns re mgt control inadequacies, per TMI Action Plan Item II F 1 i, "Noble Gas Effluent Monitor," expressed HIND, J A Division of Radiological & Materials Safety Programs 84/03/01 REED.C Commonwealth Edison Co 2pp 22673 196 24X Fiche 50-295.84/03/01.8403190314
- --8403190321 Notice of violation from insp on 831122-840202 HIND, J. A Division of Radiological & Materials Safety Programs 84/03/01, 3pp 22673 198 24X Fiche 50-295,84/03/01,8403190314
- --8403190334 IE Insp Repts 50-295/83-27 & 50-304/83-28 on 831122-840202 Violation noted, failure to follow plant procedures re source handling, to evaluate radiological hazards & to control access to high radiation area LOVENDALE.P C Region 3, Office of Director 84/02/27 14pp 22673, 201. 24% Fiche 50-295,84/03/01,8403190314
- 8403130185 Discusses evaluation of State of IL & local plans & preparedness for facilities Plans adequate to protect health & safety of public Approval of public alert notification systemational on verification of criteria of NUREO-0554 SPECK, 8 W Federal Emergency Management Agency 84/03/02 DIRCKS, W J Diffice of the Executive Director for Operations 1 22613:314 24X Fiche 50-293.84/03/02.8403130185
- 8403120051 Notifies of 840323 workshop on fire protection safe shutdown requirements of 10CFR50. App R in Rosemont, IL to discuss IE Info Notice 84-09 & provide add1 shutdown analyses &/or mod guidance Agenda enc! SPE88ARD.R L Division of Emergency Preparedness & Operational SUPPOPT 84/03/06 REED, C Commonwealth Edison Co 3pp 22590: 277. 24X Fiche' 50-295. 84/03/06. 8403120051
- 8403210089 Revised Page 3 to Emergency Plan Implementing Procedure EPIP-180-1, "Rad/Chem Director" W/840320 transmittal & receipt form PLIML.0 Commonwealth Edison Co 84/03/07 2pp 22705 320 24X Fiche 50-295.84/03/07.8403210089
- 8403190195 Revised pages to Emergency Plan Implementing Procedures EPIP-180-1.adding rad/chem ofc to habitability checks W/840309 transmittal & receipt form CO 84/03/09 5pp 22671 100 24X Fiche: 50-295, 84/03/09, 8403190195
- B403230124 Rev 4 to Emergency Plan Implementing Procedure EPIP-330-1, "Classification of GSEP Conditions " W/840322 transmittal 1tr. PLIML, @ Commonwealth Edison Co 84/03/22 6pp 22730 187 24X Fichs. 50-295, 84/03/22, 8403230124

9. Adjudicatory correspondence

- 8403020134 Forwards util 840R28 ltr to Denton requesting permission to withdraw application for license amends re containment leakage tests criteria Motion will be filed upon request Cartificate of Svc encl STEPTOE, P P Isham, Lincoln & Beale, STEPTOE, P P Commonwealth Edison Co 84/02/28 LAZD, R M Atomic Safety and Licensing Board Panel, App 22441 345 24X Fichs 50-295, 84/02/28,8403020134
- 8403020140 Notice of appearance in proceeding Certificate of Svc encl STEPTOE,P.P. Commonwealth Edison Co STEPTOE,P.P. Isham, Lincoln & Beale 84/02/28 ip. 22443 253 24X Fiche 50-275.84/02/28, BA03020140

- --B403020146 Notice of appearance in proceeding Certificate of Svc encl GILOMEN, B R Commonwealth Edison Co GILOMEN, B R Isham, Lincoln & Beals 84/02/28 3pp 22443 294 24x Fiche 30-295,84/02/28, B403020140
- B403140134 Response to Citizens Against Nuclear Power (CANP) 840213 petition to intervene & request for hearing Request should be held in abegance pending action on util request to withdraw application Certificate of Svc enc! PERLIS.R O Hearing Branch 3 B4703705 Atomic Safety and Licensing Board Panel 7pp 22624 205 24X Fiche 50-295.84703705. B403140124
- O Advisory Committee on Reactor Bafeguards reports & correspondence
- B403050020 Responds to FOIA request for documents re PASNY submittal on sys interactions repts evaluating submittal & list of repts/analyses from LLL evaluating PASNY sys interaction program Forwards App A documents FELTON, J M Division of Rules and Records 83/12/07 SHOLLY.8 Union of Concerned Scientists 6pp 22525 078 24X Fiche 50-000,83/12/07,8403050020
- --8403050028 Discusses licensee proposed review plans addressing ACR6 recommendations re sys interaction study QULLER, K.R. Assistant Director for Operating Reactor Projects (Pre 791030) 77/10/21 BENDER, M. ACR5 Advisory Committee on Reactor Safeguards 2pp 22525 146 24X Fiche 30-000, 83/12/07, 8403050020
- P Operating license stage documents & correspondence
- 8403020131 Withdraws 830808 application for amend to Licenses DPR-39 & DPR-48, changing acceptance criseria for containment leak rate tests Evidentiary hearing in 1984 would distract technical & legal resources from higher priority tasks FARRAR, D. Commonwealth Edison Co. 84/02/28 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp. 22443 243 24X Fiche 50-295,84/02/28,8403020131
- 8403050119 Forwards supplemental response to Generic Ltr 83-28,
 "Required Actions Based on Generic Implications of Salem
 ATMB Events "
 BARNES:P L Commonwealth Edison Co 84/02/29 DENTON.H R Office
 of Nuclear Reactor Regulation, Director 26pp 22488 084 24X
 Fiche 50-000.84/02/29.8403050119
- B403090145 Requests submittal of documentation re NUREO-0737 items within 30 days to complete technical reviews & implementation, excluding Suppl 1.by Sept 1.984 VAROA.B A Operating Reactors Branch 1 64/03/02 FARRAR.D L Commonwealth Edison Co 2pp 22592 309 24X Fichs 50-295,84/03/02.8403090145
- 8403280090 Forwards Amends 84 & 74 to Licenses DPR-37 & DPR-48, respectively, safety evaluation & notice of issuance & availability Amends allow performance of extensive preventive maint on shared diesel generator NORRIB. J Deprating Reactors Granch i 84/03/12 FARRAR.D L Commonwealth Edison Co 3pp 22812 293 24X Fiche 50-295.84/03/12.8403980090
- --8403280101 Amends 84 % 74 to Licenses DPR-39 % 48, respectively, allowing performance of extensive preventive maint on shared diesel generator VARGA,8 A Operating Reactors Branch & 84/03/12 App 22812 276 24X Fiche 50-275,84/03/12,8403280090
- --8403280106 Safety evaluation supporting Amends 84 & 74 to Licenses DPR-39 & DPR-48 respectively * Office of Nuclear Reactor Regulation. Director 84/03/12 9pp 22812 302 24% Fiche 50-295 84/03/12,8403280090
- ---8403280108 Notice of issuance & availability of Amends 84 & 74 to Licenses DPR-37 & DPR-48, respectively VAROA,S A Operating Reactors Branch 1 84/03/12 3pp 22812 311 24X Fiche 50-275,84/03/12,8403280090
- 8403260182 Clarifies NUREQ-0737, Item II K 3 31, in response to Generic Ltr 83-35 Westinghouse Owners Group authorized program to demonstrate conservatism of WFLASH small break LOCA analyses; per Item II K 3 30 BARNES, P L Commonwealth Edison Co 84/03/21 EISENHUT, D 9 Division of Licensing 1p 22756 170 24% Fiche 50-000, 84/03/21, 8403260182

Inspection reports, IE Bulletins & correspondence

- 3403050223 Further response to POIA request for records of named individuals, including repts, analyses, studies, test calculations, procedures & practices for measurement of RCS leakage Forwards App C documents Search continuing FELTON, J H Division of Rules and Records 84/02/07 MADDEN, T J Kaye, Scholer, Figeran, Hays & Handler 3pp 22476 234 24X Fiche 50-000,84/02/07,8403050223
- --8403050256 Notifies that independent measurements of identified & unidentified RCS leak rates for all PWRs in Region [[I] performed per Procedures 617278 & 617280 Insp findings summarized NORELIUS.C E Division of Engineering 92/03/09 JURDAN.E t. Division of Engineering & Quality Assurance (Pre 830103) 2pp 22476 270 24X Fishe 50-000,84/02/07.8403050223
- 3403080174 Informs of inservice insplactivities from 840327-0401 Activities will include volumetric surface & visual insps of ASME Class 1.2 & 3 components Detailed insp program will be available for review by second who of Mar 1784 GRAESSER.K L. Commonwealth Edison Co. 84/02/23 KEPPLER.J G Region 3. Office of Director 1p. 22559 143 24X Fiche 50-304.84/02/23.8403080174
- 3403120134 Forwards IE Insp Repts 50-R37/B4-01:50-249/B4-01: 50-254/B4-01:50-265/B4-01:50-295/B4-01:50-304/B4-01:on 840203-14 No noncompliance identified 8HAFER:W B Region J. Office of Director 84/02/23 REED:C Commonwealth Edison Co 2pp 22590 090 24X Fiche 30-000:84/02/23. 8403120134
- --B403120137 IE Insp Repts 50-237/84-01.50-249/84-01.50-254/84-01. 50-265/84-01.50-275/84-01 & 50-304/84-01 on 840203-14 No noncompliance or deviations identified Major areas inspected allegations of improper operation CHRISSOTIMOS,N Region 3. Office of Director 84/02/21 app 22570 072 24X Fiche 50-000,84/02/23.8403120134
- 8403090043 Forwards Rev O to "Corporate Regulatory Performance Improvement Plan" Plan designed to heighten employee awareness & strengthen corporate ability to improve regulatory performance THOMAS.B Commonwealth Edison Co 84/02/24 KEPPLER.J G Region 3. Office of Director 3pp 22490 139 24X Fiche 50-000.84/02/24.8403050043
- --8403050046 Rev 0 to "Corporate Regulatory Performance Improvement Plan " * Commonwealth Edison Co 84/02/29 22pp 22490 142 24X Fiche 50-000,84/02/24.8403050043
- 8401190072 IE info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Swc list enc! JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp. 22909 237 24X Fiche 50-000,84/02/28,8401190072
- 8403190314 Forwards IE Insp Repts 50-293/83-27 & 50-304/83-28 on 831122-1228 & 840202 & notice of violation Concerns re mgt control inadequaties, per TMI Action Plan Item II F 1 I. "Noble Gas Effluent Monitor." expressed HIND-J A Division of Radiological & Materials Bafety Programs 84/03/01 REED, C Commonwealth Edison Co 2pp 22673 196 24X Fiche 50-295.84/03/01.8403190314
- --8403190321 Notice of violation from insp on B31122-840202 HIND, J A Division of Radiological & Materials Safety Programs 84/03/01 3pp 22873 198 24% Fiche 50-295,84/03/01,8403190314
- --8403190334 IE Insp Repts 50-295/83-27 & 50-304/83-28 on 831122-840202 Violation noted fatiure to foliow plant procedures resource handling to evaluate radiological hazards & to control access to high radiation area LOVENDALE.P C . NICHOLSON.N . GREGER, L R Region 3, Office of Director 84/02/29 14pp 22673 201 24x Fiche 50-295.84/03/01.8403190314
- 8402090007 IE Info Notice 84-14. "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl ORACE. J N Division of GA. Safeguards & Inspection Programs (Post 830103) 84/03/02 Compolidated Edison Co of New York. Inc 130pp 22552 327 24x Fiche 50-000.84/03/02,8402090007
- B402090008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Syc list enc! JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4703/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 30-000,84/03/02,8402090008

- B402090009 IE Info Notice 84-15, "Reporting of Radiological Releases " Eve list enel JORDANNE L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/02 Consolidated Edison Co. of New York, Inc 119pp 22553 217 24X fichs 50-000,84/03/02,8402090009
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24% Fiche 50-000,84/03/05,8402090011
- 8402090024 IE info Notice 84-09, Rev 1, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24% Fiche 50-000,84/03/07,8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR 8ys " Syz list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24% Fichs 50-000,84/03/07,8402090028
- 8403220161 Forwards IE Insp Repts 50-295/83-26 & 50-304/83-27 on 831221-840209 & notice of violation W/o notice of violation SHAFER.W D Region 3. Office of Director 84/03/07 REED.C Commonwealth Edison Co 2pp 22717 188 24X Fiche 50-295.84/03/07.8403220161
- --8403220165 IE Insp Repts 50-295/83-26 & 50-304/83-27 on 831221-840209 Noncompliance noted failure to comply w/approved written procedures.Paragraphs 5.6.11 & 14.resulting in reactor trips & LERs
 HDL ZMER,M M , DUNAMAY.F R , DDYD,D C Region 3, Office of Director 84/03/04 12pp 22717 190 24X Fiche 50-295.84/03/07, 8403220161
- 8402090031 IE Builetin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Bys " Svc list encl DEYDUNO,R C Director's Office of Finanction and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 30-000.84/03/12,8402090031
- B40323008B Ack receipt of regulatory performance improvement plan Periodic meetings requested to discuss progress on program & provide feedback KEPPLER, J G Region 3, Office of Director 84/03/20 THOMAS, B Commanwealth Edison Co ip 22730 161 24X Fiche 30-000,84/03/20, 840323008B
- --8403230107 Forwards corporate regulatory performance improvement plan THOMAS.B Commonwealth Edison Co 84/02/24 KEPPLER.J Q Region 3. Office of Director 3pp 22730 162 24% Fiche 50-000. 84/03/20.8403230088
- --8403230126 Rev 0 to "Corporate Regulatory Performance Improvement Plan For Dresdon, Quad Cities, Zion & LaSalle Operating Nuclear Stations & Byron & Braidwood Project Operating Organizations" * Commonwealth Edison Co 84/02/29 22pp 22730 165 24X Fishe 50-000,84/03/20,8403230088
- 8403260176 Forwards responses to IE Bulletin B3-07, "Apparently Fraudulent Products Sold by Ray Miller, Inc." Guad Cities supplied w/piping matis from Ray Miller, Inc. during comet Evaluation and Concerns of IE Bulletin B3-06 satisfied BARNES,P L. Commonwealth Edison Co. 84/03/20 KEPPLER, J. Q. Ragion 3. Office of Director 19pp, 22756 185 24X Fiche 50-000.84/03/20, 8403260176
- 8402070043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc. 123pp 22823 229 24X Fiche 50-000,84/03/21,8402070043
- 8402090044 IC Info Notice 84-20, "Bvc Life of Relays in Safety-Related Bys "Bvc list enci JDRJDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22733 001 24X Fiche 50-000,84/03/21,8402070044
- R Periodic operating reports & related correspondence
- 8403060217 "Effluent & Waste Disposal Semiannual Rept.Jul-Dec 1983, Gaseous Effluents. Summation of all Releases " W/840210 ltr GRAESSER.K & Commonwealth Edison Co 33/12/31 KEPPLER.J G. Repien 3, Office of Director 27pp 22511 159 24X Fiche 50-295.83/12/31.8403060217

- 8403080197 "Rept of Occupational Personnel Radiation Doses, 1983 " W/B40227 ltr 868TT.J S Commonwealth Edison Co 83/12/31 13pp 22559 099 24X Fiche 50-000.83/12/31.8403080197
- 8403220120 Annual whole body external exposures for 1983 W/840316 ltr RYBAK.B Commonwealth Edison Co 83/12/31 7pp 22716 007 24X Fiche 50-000.83/12/31,8403220120
- 8403190156 Monthly operating repts for Feb 1984 W/840309 ltr AUBTIN.0 . GRAESSER.K L Commonwealth Edison Co 84/02/2 22669 163 24X Fiche 50-295.84/02/27.8403170156 84/02/29 1300
- 8 Reportable occurrences, LERs & related correspondence
- 8211150076 Discusses events involving loss of electrical inverters including attendant inverters to vital instrument buses Recommendations provided by Nuclear Safety Analysis Ctr are excellent in helping to reduce instrument failures ASHE.F Reactor Operations Analysis Branch 82/10/21 SEYFRIT, Reactor Operations Analysis Branch 8pp 22775 223 24X Fiche. 50-000, 82/10/21, 8211150076 SEYFRIT K V
- 8403090174 LER 83-037/03X-1 on 830915 during instrument mechanic surveillance testing of passive gas failure monitor RT-PRIS, no flow observed Caused by defective circuit breaker Breaker replaced W/840305 ltr KUBCHLE: C W / GRAESSER: K L Commonwealth Edison Co 84/03/05 KEPPLER: J Region 3, 07fice of Director 2pp 22575 143 24 Fichs 50-304,84/03/05,8403090174
- 8403200173 LER 84-005-00 on 840215 during maint instrument five valve test manifold for containment differential pressure transmitter found w/equalizing valve open Mod proposed to replace manifold w/single valve W/840312 ltr
 KELLY.T. GRAESEER.K L Commonwealth Edison Co. 84/03/12 3pp 22697.124, 24X Fiche 50-304.84/03/12.8403200173
- DOCKET 50-305 KEWAUNEE NUCLEAR POWER PLANT
- F Security, medical, emergency & fire protection plans
- 8403050125 Ack receipt of FEMA 840130 ltr & associated final exercise evaluations of Biliol emergency preparedness exercise No deficiencies affecting public health & safety identified based on performance of offsite agencies PAPERIELLO.C J. Region 3, Office of Director, B4/02/27 QIESLER.C.W Wisconsin Public Service Corp. 2pp. 22489 109 24X Fiche. 50-305, 84/02/29, 8403050125
- 8403150343 Forwards exemption from schedular requirements for alternative shutdown sys per 10CFR50 48(c)(4) & SER Exemption being forwarded to Ofc of FR for publication EISENHUT, D G Division of Licensing 84/02/27 OIESLER. C W Wisconsin Public Service Corp 2pp 82647 215 24X Fiche: 50-305,84/02/27,8403150343
- --B403150345 Examption from schedular requirements for alternative shutdown sys per 10CFR50 48(c)(4)

 DENTON, HR Office of Nuclear Reactor Regulation, Director 84/02/29 Wisconsin Public Service Corp 11pp 22647 217 24X Fiche, 50-305, 84/02/29, 8403150343
- --B403150347 Bafety evaluation supporting specific exemption from 10CFR50, 48(c)(4) re App R alternate shutdown schedule # Office of Nuclear Reactor Regulation, Director 84/02/29 19pp. 22649 228, 24X Fiche 50-305,84/02/29,8403150343
- 8403080088 Ack receipt of 840207 ltr transmitting changes to industrial security manual & security force training & qualification manual. Changes consistent w/provisions of 10CFR50 54(p) & manual onages consistent dyprovisions of tochoo Sty acceptable AXELBON.W.L. Region 3. Office of Director 84/03/02 Wisconsin Public Service Corp 2pp 22559 263 24X Fiche 30-305.84/03/02,8403080088 GIEBLER, C W
- 8403120048 Advises of 840323 regional workshop in Rosemont, L w/all Region III licensess to discuss fire protection sees shutdown requirements of 10CFR50. App R Agenda encl SPEBBARD, R.L Division of Emergency Preparedness & Operational Support 84/03/06 QIESLER, C W Wisconsin Public Service Corp 3pp. 22589 289 24X Fiche 50-305,84/03/06,8403120048

- J Insurance & indemnity information
- 8403160298 Forwards Endorsement 65 to NELIA Policy NF-204, Endorsement 14 to NELIA Policy NF-384 & Endorsement 8 to NELIA Master Policy 1 GIESLER, C W CTINIC E1/E0/48 OFIGILER, C W Hisconsin Public Service Corp 84/03/13 Office of Nuclear Reactor Regulation, Director 4pp 24X Fiche 50-305,84/03/13,8403160278 DINITZ, I
- P Operating license stage documents & correspondence
- 8403050223 Further response to FDIA request for records of named individuals, including repts, analyses, studies, test calculations, procedures & gractices for measurement of RCS leakage Forwards App C documents Search continuing FELTON, J M Division of Rules and Records 84/02/0/ MADDEN, Kaye, Scholet, Fierman, Hays & Handler 3pp 22476 234 24X Fiche 50-000,84/02/07,8403050823 MADDEN, T J
- ~-8403050235 Advises that certain aspects of facility Tech Spec novinuzed Advises that certain aspects of facility Tech Spec requirements governing RCS leakage appear to be inconsistent w/std nuclear industry practice Licensee should be requested to modify Tech Spacs Related info ancl NORELIUS.C E Region 3. Office of Director 82/03/10 EISENHUT.D g Division of Engineering lipp 22496 246 2 Fiche 50-000,84/02/07.8403090223
- 8403010066 Forwards safety evaluation re 821223 response to Generic Ltr 82-16 concerning NUREQ-0737 Tech Specs Two items closed Items I A I 1 3 k II E 4 i under consideration Response acceptable VARQA, S A Operating Reactors Branch I 84/02/10 GIFSLER, C W Wisconsin Public Service Corp 7pp 22480 GO1 24% Fichs 50-305,84/02/10,8403010066
- 8402170104 Forwards "Reload Safety Evaluation Cycle X," Feb 1984 Cycle X reload design assumes approval of proposed Amend 56 to Tech Specs GIEBLER/C W Wisconsin Public Service Corp 84/02/14 VARGA Operating Reactors Branch i 2pp 22301 009 24X
 Fiche 50-305.84/02/14.8402170104
- --8402170107 "Reload Safety Evaluation Cycle X," Feb 1984 HOLLY,J T . ROPSON:D J . WOZNIAK,S F Wisconsin Public Service Corp 84/02/06 66pp 22301 011 24X Fiche 50-305,84/02/14, Corp 84/0 8402170104
- 8403070321 Forwards corrected Tech Spec Page 6-26 to Amend 52 to License DPR-43 deleting Paragraph 6 14, "Environ Qualification " VARQA, S A Operating Reactors Branch 1 84/02/23 GIESLER, C W Wisconsin Public Service Corp 3pp 22544 317 24X Fiche 50-305,84/02/23,8403070321
- --8403070323 Corrected Tech Spec Page 4-26 deleting Paragraph 6 i4,
 "Environ Gualification"
 * Office of Nuclear Reactor Regulation, Director 84/02/23 ip
 28364 320 24% Fiche 50-305,84/02/23,8403070321
- 8403050504 Discusses site visit on 840228-29 & 0301-02 W/BNL NOSCOUGH Discusses site visit on BHOMEBLEY & VOIT-OM WIGHT representative to collect data on high radiation exposure jobs & dose reduction mods for studies being performed by NRC, per 840223 conference call VARGA, 8 A Operating Reactors Branch i B4/02/24 QIESI Wisconsin Public Service Corp. 3pp 22552 174 24X Fiche, 30-305, 84/02/24, 8403060504 GIESLER, C W
- 8403020295 Notifies that proposed Tech Spec for certain NUREG-0737 items per Generic Ltr 83-37 will be submitted by 840401 GIESLER.C W Wisconsin Public Service Corp. 84/02/28 EIBENHUT, D G Division of Licensing 2pp 22440 066 24X Fiche 50-305,84/02/28,8403020295
- B403140225 Notifies of plan for resolving upper plenum injection (UPI) issue Issue involves ECCS models by Westinghouse & Exxon for calculating ECCS performance of Hestinghouse two-loop plants Retention of interim penalty proposed VAROA.S A Operating Reactors Branch I B4/03/06 QIESLER.C W Hisconsin Public Service Corp. 3pp 22637.323 24X Fiche 50-305,84/03/06.8403140225
- 8403130188 Provides info to support review of proposed Amend 58 to License DPR-43 Attached table provides comparison of calculated voltages Agreement shown between calculated & measured voltages & currents GIESLER.C W Wisconsin Public Service Corp B4/03/08 DENTON.E Office of Nuclear Reactor Regulation, Director 2pp 22606 126 24X Fiche 50-305.84/03/08.8403130188 DENTON H R

- B403160327 Forwards revised Page 4 2 1 of proposed Amend 57 to Tech Specs re inservice insp & testing OIESLER.C W Hisconsin Public Service Corp 84/03/13 DENTON.H R Office of Nuclear Reactor Regulation, Director 1p 22660 155 24X Fiche 50-305.884/03/13.8803160327
- --8403160331 Revised Page 4 2 1 of proposed Amend 57 to Tech Specs re inservice insp & testing * Wisconsin Public Service Corp 84/03/13 1p 22660 156 24X Fiche 50-305, 84/03/13,8403160327
- 8403200154 Requests permanent exemption from requirements of App J to 10CFR50 ref air lock testing following periods during which containment integrity maintained GIESLER, C W Wisconsin Public Service Corp 84/03/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22686 361 24% Fiche 50-305,84/03/15,8403200154
- 8403270030 Discusses 840120 meeting re resolution of SER deficiencies, methodology of master list development all DBAs considered & Justification for continued operation Environ qualification plan encl OIESLER.C W Wisconsin Public Service Corp 84/03/16 VARQA,S A Operating Reactors Branch 1 9pp 22768 031 24X Fiche 50-305,84/03/16,8403270030
- --8403270032 "Resolution of SER for Environ Qualification of Electrical Equipment Important to Bafety at Kewaunee Nuclear Power Plant "

 * Wisconsin Public Service Corp 84/03/16 79pp 22768 040 24% Fiche 50-305,84/03/16,8403270030
- ---8403270038 "Kewaunee Nuclear Power Plant Environ Qualification Plan "
 # Wisconsin Public Service Corp 84/03/16 358pp 22768 124
 24X Fiche 50-305,84/03/16,8403270030
- B403280048 Forwards response to B31205 request for add1 info re NVREO-0737 Item II D 1. "Performance Testing of Relief & Safety Valves "Microfiche of RELAP5/ADLPIPE computer analyses encl OIEBLER, C W Wisconsin Public Service Corp B4/03/23 VAROA, S A Operating Reactors Branch I Sopp 22776 282 24X Fiche: 50-305, 84/03/23, 8403280048
- @ Inspection reports, IE Bulletins & correspondence
- B403050223 Further response to FOIA request for records of named individuals, including repts, analyses, studies, test calculations, procedures & practices for measurement of RCB leakage Forwards App C documents Search continuing FELTON, J M Division of Rules and Records 84/02/07 MADDEN, T J Kayes, 8choler, Fierman, Hays & Handler Jpp 22496 234 24X Fiche 50-000,84/02/07,8403050223
- --B403050256 Notifies that independent measurements of identified & unidentified RCS leak rates for all PMRs in Region III performed per Procedures 61727B & 6172BB Insp findings summarized
 NGRELIUS: C E Division of Engineering B2/03/08 JGRDAN.E L Division of Engineering & Quality Assurance (Pre 830103) 2pp 22476 270 24X Fiche 50-000.B4/02/07.8403050223
- 8403190379 Forwards IE Insp Rept 50-305/83-17 on 831216-840215 No noncompliance noted SHAFER.W D Region 3. Office of Director 84/02/27 QIESLER.C W Wisconsin Public Service Corp 2pp 22675 209 24X Fiche 50-305,84/02/27,8403190379
- ---8403170384 IE Insp Rept 50-305/83-17 on 831219-840215 No noncompliance noted Major areas inspected maint, surveillance, independent inspiregional requests & operational safety NELBON.R L. JACKIN.I N. Region 3, Office of Director 84/02/24 5pp. 22475 211 24X Ficher 50-305/84/02/27/8403190379
- 8401190072 IE Info Notice 84-13: "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation." Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28. Consolidated Edison Co of New York. Inc 115pp 22709 237 24X Fiche: 50-000.844/02/28.88401190072
- 8402090007 IE Info Notice 84-14. "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE, J N Division of GA. Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000,84/03/02,8402090007
- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Bys Valves to Operate." Svc list encl JORDAN,E L Division of Emergency Proparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24% Fiche 50-000,84/03/02,8402090008

- 8402070007 IE Info Notice 84-15, "Reporting of Radiological Releases"
 Svc list encl
 JORDAN, E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc 119pp 22553 217 24X Fiche 50-000,84/03/02,8402070007
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc. 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8402070024 IE Info Notice 84-07.Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc 118pp 22635 049 24X Fiche 50-000.84/03/07.8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PHR Bys " Svc list and I JORDAN, EL Division of Emergency Preparedness & Engineering Responsa (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8403220134 Forwards IE Insp Rept 50-305/84-01 on 840206-10, No noncompliance noted PAPERIELLO, C J. Region 3, Office of Director 84/03/08, GIESLER, C W. Wisconsin Public Service Corp. 2pp. 22716, 037, 24X Fiche, 50-305, 84/03/08, 8403220134.
- --B403R20140 IE Insp Rept 50-305/84-01 on 840206-10 No noncompliance noted Major areas inspected confirmatory measurements, including sampling, lab GC & comparison of licensee analyses w/Region III mobile lab.

 JANUSKA:A 0 , SLAMINSKI:N J , SCHUMACHER, M. C. Region 3, Office of Director 84/03/08 8pp 22716 039 24X Fiche 50-305,84/03/08,8403220134
- 8402070031 IE Dulletin 84-02. "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Syc list encl DEYOUNG.R C. Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fichs 50-000.84/03/12,8402090031.
- 8403200016 Responds to IE Bullatin 83-08 re electrical circuit breakers w/undervoltage trip feature No circuit breakers w/mechanical trip attachments similar to DB-50 breaker used in safety-related applications
 GIESLER.C W Wisconsin Public Service Corp. 84/03/12 KEPPLER, J. 9
 Region 3, Office of Director. 1p 22699, 181. 24X
 Fiche 50-305,84/03/12,8403200016
- B403160327 Forwards revised Page 4 2 1 of proposed Amend 57 to Tech Specs re inservice insp & testing GIEBLER.C W Wisconsin Public Service Corp 84/03/13 DENTON,H R Dffice of Nuclear Reactor Regulation, Director. 1p 22660 155 24X Fiche 50-305.84/03/13.8403160327
- --8403160331 Revised Page 4 2 1 of proposed Amend 57 to Tech Specs re inservice insp & testing * Wisconsin Public Service Corp 84/03/13 1p 22660 156 24X Fiche 50-305.84/03/13.8403160327
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/21 Consolidated Edison Co of New
 York, Inc 123pp. 22823 229 24X Fiche 50-000.84/03/21.8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044
- R Periodic operating reports & related correspondence
- B403060408 "Semiannual Effluent Release Rept, Jul-Dec 1783 " W/840229 itr OIEBLER, C W Wisconsin Public Service Corp 83/12/31 KEPPLER, J G Region 3, Office of Director 32pp. 22518 155 24X Fiche 50-305.83/12/31,8403060408
- B403070169 "Kewaunes Nuclear Power Plant Annual Operating Rept 1983," W/B40301 ltr * Wisconsin Public Service Corp 83/12/31 110pp 22539.001. 24X Fiche 50-305.83/12/31.8403070169
- 8403130147 Monthly operating rept for Feb 1984 W/B40309 ltr. RUITER, G H . 01E5LER, C W. Wisconsin Public Service Corp. 84/02/29 5pp 22608-220 24X Fiche 50-305,84/02/27,8409130147

- B Reportable occurrences, LERs & related correspondence
- 8403230178 Forwards Technical Review Rept AEOD/T313, "Capped Containment Pressure Sensing Lines," & proposed IE info notice Issue adequately resolved RUBIN,8 D Reactor Operations Analysis Branch 83/05/11 BEYFRIT.K V Reactor Operations Analysis Branch 1p 22759 286 24X Fiche 50-000,83/05/11.8403230178
- --8403230181 "Capped Containment Pressure Sensing Lines." technical review rept Condition caused by procedural inadequacy RUBIN.5 D Director's Office 83/05/11 App 22759 287 24X Fichs 50-000, 83/05/11,8403230178
- V Operator Examinations
- 84031303\$1 Requests encl ref matl for requalification program evaluation scheduled for wk of 840521 Matl required by 840316
 - BTREETER, J F Region 3, Office of Director 84/03/05 GIESLER, C W Wisconsin Public Bervice Corp 3pp 22418 354 24X Fiche 30-305,84/03/05,8403130351
- DOCKET 50-306 PRAIRIE ISLAND NUCLEAR STATION: UNIT 2
- F Security, medical, emergency & fire protection plans
- 8403070270 Public version of revised emergency response plan implementing procedures, including Procedure F3-2 re classification of emergencies, F3-5 re emergency notification & F3-10 re personnel accountability W/831219 ltr & memo MENDELE, D. J. JOHNSON, J. M. Northern States Power Co. 83/10/28 148pp 22575 326 24X Fiche 50-282,83/10/28,8403070270
- 8403070207 Revised emergency implementing procedures, including Rev 25 to Procedure F3, "Table of Contents" & Rev 3 to Procedure F3-8. "Recommendations for Offsite Protective Actions " W/840302 ltr
- FEY,F L Northern States Power Co 84/02/24 28pp 22574 328 24k Fichs 50-282,84/02/24,8403090207
- 8403190020 Forwards IE Insp Repts 50-282/83-24 & 50-306/83-24 on 831211-840210 No noncompliance identified 8HAFER, W D Region 3. Office of Director 84/03/01 LARSON, C E Northern States Power Co 2pp 22666 053 24X Fiche, 50-282, 84/03/01, 8403190020
- ---8403190042 IE Insp Repts 50-282/83-24 & 50-306/83-24 on 831211-840210
 No noncompliance or deviations identified Major areas
 inspaced.maint.LERs, emergency planning & surveillance,
 meetings w/state & local officials & IE bulletins
 HARD, J E : JACKIM, I N Region 3, Office of Director 84/02/29
 12pp 22666,035 24X Fiche 50-282,84/03/01,8403190020
- 8403130163 Forwards final rept re small-scale offsite radiological emergency preparedness exercise on 821014 No deficiencies
- ---8403130172 Final rept of small--scale joint emergency exercise on 821014 * Federal Emergency Management Agency 82/12/17 92pp 22599 313 24% Fiche 50-282,84/03/05,8403130163
- 8403120106 Notifies of 840323 workshop on fire protection safe shutdown requirements of 100FRSO.App R in Rosemont.IL to discuss IE Info Notice 84-09 & provide addi shutdown analyses &/or mod guidance.Apenda encl BPEBBARD.R.L Division of Emergency Preparedness & Operational Support 84/03/06 LARBON.C E Northern States Power Co 3pp 22388 169 24% Fiche 50-282,84/03/06.8403120106
- 8403300130 Revised emergency plan implementing procedures, including Procedure F3 re table of contents & F3-13 re offsite dose calculation W/840320 transmittel ltr WATT.E , FEY.F L Northern States Power Co 84/03/09 36pp 22820 255 24X Fiche 50-282,84/03/09,8403300130
- I. Financial information
- 8403270115 Suppl to Annual Financial Rept 1983.consisting of financial & statistical info W/840326 ltr BRUSVEN.A.D. Northern States Power Co 83/12/31 23pp 22806 182 24X Fiche 50-000.83/12/31,8403270115

- P Operating license stage documents & correspondence
- 8403050238 Forwards Amends 68 & 62 to Licenses DPR-42 & DPR-60, respectively & safety evaluation Amends revise Tech Specs resemengency air treatment sus & electric hydrogen recombiners DIIANNI.D C Operating Reactors Branch 3 84/02/21 MUSQLF, D M Northern States Power Co 2pp 22527 188 24X Fichs 50-282.84/02/21.8403050238
- --8403050243 Amends 68 & 62 to Licenses DPR-42 & DPR-60, respectively, revising Tech Specs re emergency air treatment sys & electric hydrogen recombiners
 MILLER.J R Operating Reactors Branch 3 84/02/21 1Bpp 22527 190 24X Fiche 50-282,84/02/21.8403050238
- ---8403050249 Safety evaluation supporting Amends 48 & 62 to Licenses DPR-42 & DPR-60, respectively * Office of Nuclear Reactor Regulation. Director 84/02/21 7pp 22527 208 24% Fiche 50-282,84/02/21,8403050238
- 8403040425 Submits fees requested for 820630 exemption request, in response to NRC 840213 ltr MUSQLF, D. Northern States Power Co. 84/02/27 MILLER, W.O. License Fee Management Branch 2pp 22518 200 24X Fiche 50-282, 84/02/27, 8403060425
- B403130245 Forwards "Effluent & Maste Disposal Semiannual Rept.Jul-Dec 1983." "Offsite Radiation Dose Assessment, 1983" & Rev 4 to "Offsite Dose Calculation Manual" FEY.F L Northern States Power Co B4/03/01 Region 3. Office of Director 1p 22610 143 24X Fiche 50-282, 84/03/01, 8403130245
- --8403130278 Rev 4 to "Offsite Dose Calculation Manual " SORENSON, J Northern States Power Co 84/11/14 11pp 22610 157 24X Fiche 50-282,84/03/01.8403130245
- 8403180290 Forwards safety evaluation re error in CDBRA IIIC/MIT computer code, previously accepted by NRC 830217 & 0324 ltrs, for use in analyzing fuel reloads Error does not create any substantial safety hazard MILLER, J R. Operating Reactors Branch 3 84/03/06 MUSOLF, D M Northern States Power Co ip 22649 333 24X Fiche 50-282, 84/03/06,8403150290
- --8403150293 Safety evaluation re error in COBRA IIIC/MIT computer code reload methodology rept NBPNAD-8102 Error has not affected initial findings or conclusions re acceptability of use of COBRA IIIC/MIT code. * NRC - No Detailed Affiliation Given 84/03/06 2pp 22649 334 244 Fiche 50-282,84/03/06.8403150290
- 8403190397 Provides updated info re mods required by NUREG-0737. Item
 II D 1 2 re safety & relief valve performance Unit i piping
 & supports will be installed during next refueling outage
 scheduled for 850105
 MUSQLF.D Northern States Power Co B4/03/14 Office of Nuclear
 Reactor Regulation, Director ip 22675 192 24X
 Fiche 50-282.84/03/14.8403190397
- 8403230051 Submits status of mods to improve adequacy of station distribution sys voltages.per util 810717 ltr & NRC 821027 SER All mods completed.w/exception of changes to station air compresser starting circuit MUBGLF.D Northern States Power Co 84/03/16 Office of Nuclear Reactor Regulation, Director 200 22724 346 24X Fiche 50-282.84/03/16.8403230051
- @ Inspection reports, IE Bulletins & correspondence
- 8403050823 Further response to FOIA request for records of named individuals, including repts, analyses, studies, test calculations, procedures & practices for measurement of RCB leakage Forwards App C documents Sparch continuing FELTON, J M Division of Rules and Records 84/02/07 MADDEN, T J Raye, Scholer, Fireman, Hays & Handler 3pp 22496 234 24X Fiche 50-000,84/02/07,8403050223
- --B403050256 Notifies that independent measurements of identified & unidentified RCS leak rates for all PWRs in Region III performed per Procedures 617278 & 617288 Insp findings summarized NORELIUS.C E Division of Engineering 82/0308 JURDAN.E L Division of Engineering & Quality Assurance (Pre 830103) 2pp 22476 270 24X Fiche 50-000.84/02/07.8403050223
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Bvc list enc!

 JCRDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc. 115pp 82909 239 24X Fiche. 50-000.84/02/28.8401190072

- 8403190020 Forwards IE Insp Repts 50-282/83-24 & 50-306/83-24 on B31211-840210 No noncompliance identified SHAFER.W D Region 3 Office of Director 84/03/01 LARSON,C E Northern States Pouer Co 2pp 2266 053 24X Fiche 50-282
- --8403190042 IE Insp Repts 50-282/83-24 & 50-306/83-24 on 631211-840210 No noncompliance or deviations identified Major areas inspected maint. LERs, emergency planning & surveillance, meetings w/state & local officials & IE bulletins HARD, J E. FEIERADEND, C D., HARTMANN, P L. Region 3, Office of Director 84/02/29 12pp 22666 055 24X Fiche 50-282,84/03/01,8403190020
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000.84/03/02.8402090007
- 840209000B IE Info Natice B4-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Syc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 078 24X Fiche 50-000.84/03/02,8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases " 8vc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84703702 Consolidated Edison Co of New York, Inc. 119pp 22553 217 24X Fishe 50-000.84703702, 8402090009
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Coaling Components Balow Nil Ductility Temp " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co. of New York, Inc. 117pp 22553 336 24% Fiche 50-000,84/03/05,8402090011
- 8402090024 IE Info Notice 84-09, Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 188pp 22635 049 24X Fiche 50-000,84/03/07,8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PHR Sys " Sv: list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84703/07 Consolidated Edison Co of New York, Inc 118pp 22584 i86 24% Fiche 50-000,84703/07,8402090028
- 8403190398 Forwards summary of status of requests for relief from requirements of Section XI of ASME Boiler & Pressure Vessel Code for inservice insp program & clarification of items that require add review MUSDLF,D Northern States Power Co 84/03/09 Office of Nuclear Reactor Regulation. Director 9pp 22675 295 24X Fiche 50-282.84/03/09,8403190388
- 8402090031 IE Bulletin 84-02. "Failures of GE Type HFA Relays in Use in Class IE Sefety Sys " Svc list enc!
 BEYDUNG.R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York. Inc 134pp 22823 094 24% Fiche 50-000.84/03/12.8402090031
- 8403190200 Responds to 1E Bulletin 83-07 re products supplied by Ray Miller.Inc Neither unit received products from Ray Miller. Inc & vendur not on approved util vendor list LARSON.C E Northern States Power Co R4/03/12 DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 4pp 22471 105 24X Fiche 50-282.84/03/12.8403190200
- 8403300036 Forwards IE Insp Repts 50-282/84-02 & 50-306/84-02 on 840215-17 No noncompliance noted PAPERIELLO: C.J. Region 3. Office of Director 84/03/15 LARSON: C.E. Northern States Power Co. 2pp. 22821 320 24X Fiche 50-282,84/03/15,8403300036
- --8403300040 IE Insp Repts 50-282/84-02 & 50-304/84-02 on 8402)5-17 No violations or deviations identified Major areas inspected implementation of 10CFR20 & 60 requirements for disposal of low level radwastes, including mgt controls & GC RDZAK, S. OESTMANN, M. J. SCHWMACHER, M.C. Region 3, Office of Director 84/03/15, 5pp 22821 322 24X Fiche 50-282,84/03/15,0403300034
- 8402070043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JORDAN-E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24% Fiche 50-000,84/03/21,8402090043

- B402090044 IE Info Notice 84-20, "Svc Life of Relays in Bafety-Related Sys" Svc list encl
 JORDANNE L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22733 001 24% Fiche 50-000,84/03/21,8402090044
- R Periodic operating reports & related correspondence
- 8403300095 Monthly operating repts for Feb 1984 W/840306 ltr DU08TAD.D . MUSCLF.D Northern States Power Co 84/02/29 9pp 24047 060 24x Fiche 30-282.84/02/29.8403300095
- 8403130245 Forwards "Effluent & Waste Disposal Semiannual Rept.Jul-Dec 1983," "Offsite Radiation Dose Assessment.1983" & Rev 4 to "Offsite Dose Calculation Manual" FEY.F L Northern States Power Co 84/03/01 Region 3, Office of Director ip 22410 143 24% Fiche 30~282,84/03/01,8403130245
- ~~8403130258 "Effluent & Waste Disposal Semiannual Rept, Jul-Dec 1983 "
 * Northern States Power Co 83/12/31 9pp 22610 144 24X
 Fiche 50-282,84/03/01.8403130245
- DOCKET 50-309 MAINE YANKEE ATOMIC POWER PLANT
- F Security, medical, emergency & fire protection plans
- 8403070278 Responds to 830713 ltr re changes to physical security plan Rev inconsistent w/provisions of 10CFR50 54(p) & unacceptable for reasons stated in encl Encl withhold (ref 10CFR73 21)
 MARTIN, T T Division of Engineering & Technical Programs 84/02/29
 RANDAZZA, J B Maine Yankee Atomic Power Co 3pp 22347 098 24X Fiche 50~309.84/02/29,8403070278
- E403220075 Forwards IE Insp Rept 50-309/83-20 on 831101-1231 & notice of violation STAROSTECKI,R Division of Project & Resident Programs 84/03/07 RANDAZZA,J B Maine Yanker Atomic Power Co 2pp 22715 163 24X Fiche 50-309.84/03/07.8403220095
- --B403220103 IE Insp Rept 50-309/B3-20 on B31101-1231 Violation identified plant shift superintendent did not check tags on Taging Order 2137-B3 HOLDEN.C . ARCHITZEL.R . SWETLAND.P Region 1. Defice of Director 84/03/06 13pp 22715 166 24X Fiche 50-309.84/03/07. 8403220095
- 8403190243 Notification of 840418 workshop in King of Prussia.PA to discuss lessons learned from recent App R fire protection safe shutdown insp & topics described in IE Info Notice 84-09 Agenda for workshop ent!

 MURLEY,T E Region 1. Office of Director 84/03/09 D'TOOLE,J D Consolidated Edison Co of New York, Inc KENYON,B D Pennsylvania Power & Light Co HARRISON.R J Public Service Co of New Hampshire 35pp 22672 062 24X Fiche 50-000,84/03/09,8403190243
- G Adjudicatory correspondence
- 8403130262 Order granting Sensible Maine Power & State of ME motions to withdraw contentions, granting util motion to withdraw portion of application & authorizing issuance of amend of DL

 LAZO.R M Atomic Safety and Licensing Board Panel 84/03/09 4pp 22606 050 24X Fiche 50-309.84/03/09, 8403130262
- H General correspondence
- 8403220119 Expresses concern re inexperienced & unskilled labor at facility Repair contract awarded to contractor w/little or no repair experience 0P Conleg 840215 ltr encl COSSAR.A @ Affiliation Not Assigned 84/03/17 DEYOUNG.R Director's Office Office of Inspection and Enforcement 2pp 22716 216 224X Fiche 50-309.84/03/17.8403220119
- ${\it P}$ Operating license stage documents & correspondence
- 8403020283 Forwards safety evaluation based on review of 830912,22 & 1102 responses re feedwater trip sys Feedwater trip sys design satisfies single failure requirements Requests completion of listed confirmatory items within 120 days MILLER, J R Operating Reactors Branch 3 84/02/14 GARRITY, J H Maine Yankee Atomic Power Co 10pp 22495 016 24X Fiche 50-309,84/02/14,8403020283

- 8403050380 Forwards request for add1 info re Cycle B reload to continue review of B40127 submittal MILLER, JR Operating Reactors Branch 3 84/02/17 GARRITY, J H Maine Yankee Atomic Power Co 3pp 22527 253 24X Fiche 30-309,84/02/17.8403050380
- 8403050355 Responds to 840106 ltr re radiological effluent Tech Specs (RET6) Program provides accountable sys to assure protection of public health & safety Schedule for submittal of proposed RETS & offsite dose calculation manual requested MILLER, J R Operating Reactors Branch 3 84/02/27 GARRITY, J H Maine Yankee Atomic Power Co 2pp 22501 335 24X Fiche 50-309.84/02/27,8403050355
- B403060094 Forwards Class III amend fee, per NRC 840116 ltr re Proposed Changes 81 & 92 concerning snubber surveillance & reactor protective sys channel & ESF actuation sys WHITTIER, 9 D Maine Yankee Atomic Power Co 84/02/29 DIGGS,R M License Fee Management Branch 1p 22516 362 24X Fiche 50-309,84/02/29,8403060094
- 8403150333 Requests info re analysis of high energy steam line break Info headed to complete review of 820913 submittal re environ conditions for expense outside containment Info requested within 30 days MILLER. J R Operating Reactors Branch 3 84/03/02 RANDAZZA, J B Maine Yankee Atomit Power Co 2pp 22649 269 24X Fiche 50-309,84/03/02,8403150333
- 8403150105 Informs of recent assignment of EC Wenzinger as Chief, Reactor Projects Section IA, effective immediately Responsibilities cover Maine Yankee, Yankee Rowe & Calvert Cliffs Nuclear Power Stations ETAROBTECKI, R. Region 1, Office of Director 84/03/08 RANDAZIA, J. B. Maine Yankee Atomic Power Co. 2pp. 22640 140 24x Fiche: 50~309, 84/03/08, 8403150105
- B403230036 Withdraws B1050; commitment to install add1 pressurizer sensor Contribution of purge sys isolation valves to radialogical consequences to DBA LOCA would be minimal WHITTIER.0 D Maine Yankee Atomic Power Co B4/03/16 MILLER, J R Operating Reactors Branch 3 19 22724 332 24X Fiche 50-309,84/03/16.8403230036
- B403220192 Forwards "Control of Heavy Loads, Phase II " Rept result of review of crane operation, design & maint, including analysis of load drop risk to safety-related equipment beneath travel paths Confirms defense-in depth, per NUREO-0612 HHITTIER, O D Maine Yankee Atomic Power Co B4/03/19 MILLER, J R Operating Reactors Branch 3 2pp 22717 048 24X Fiche 50-309, 84/03/19,8403220192
- ---8403220199 "Control of Heavy Loads, Phase II "
 # Maine Yankee Atomic Power Co 84/03/19 124pp 22717 050
 24X Fiche 50-309, 84/03/19, 8403220192
- B403230042 Informs that suppl to inservice testing program will be submitted by B40601 Inservice testing procedures specific to control & implementation of testing activities will be completed no later than B40515 WHITTIER: 0 D Maine Yankee Atomic Power Co B4/03/20 MILLER, J R Operating Reactors Branch 3 1p 2272B 354 24X Fiche 50-309,84/03/20,8403230042
- B403270138 Forwards revised Page 3 of Maine Yankee penetration test requirements, encl w/containment leak testing rept Isolation Valve PD-233 added to list of containment sump discharge valves inside containment
 HHITTIER, 9 D Maine Yankee Atomic Power Co B4/03/21 MILLER, J R
 Operating Reactors Branch 3 2pp 22769 141 24X
 Fichs. 50-309, 84/03/21, 8403270138
- G Inspection reports, IE Bulletins & correspondence
- B403210R0B Corrected notification of B40313 meeting w/util in Bethesda, MD to discuss (nap program for therma) shield in Cycle 7/8 outage. Time of meeting changed HEITNER, K L Operating Reactors Branch 3 B4/02/21 MILLER, J R Operating Reactors Branch 3 B2709 206 24X Fiche 50-309, 84/02/21, 8403210208
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Syc list encl.
 JORDAN, 5 L Division of Emergency Preparedness & Engineering Response (Post 830103), 84/02/28 Consolidated Edison Co of New York, Inc. 115pp 22709 239, 24X Fiche 50-000,84/02/28,8401190072
- B402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl QRACE.JN. Division of QA, Safeguards & Inspection Programs (Fost 830103) B4/03/02. Consolidated Edison Co of New York, Inc 130pp. 22552 329 24X Fiche 50-000.84/03/02.8402090007

- 8402070008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000,84/03/02,8402070008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases" 8vc list enc!
 JDRDAN.E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 117pp 22553 217 24X Fiche 50-000,84/03/02.84020900097
- 8402090024 IE Info Notice 84-09, Rev 1, "Lessons Learned From Insps of Fire Protection Safe Shutdown 8ys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22438 049 24X Fiche 50-000, 84/03/07, 8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR
 Sys "Svr list enc!

 JORDAN, E L Division of Emergency Proparedness & Engineering
 Response (Post 830103) 84/03/07 Consolidated Edison Co of New
 York, Inc 118pp 22584 186 24X Fishe 50-000, 84/03/07, 8402090028
- 8403220056 Forwards IE Insp Rept 50-309/84-03 on 840207-10 No violations noted MARTIN.T T Division of Engineering & Technical Programs 84/03/07 RANDAZZA.J B Maine Yankee Atomic Power Co 2pp 22714 339 24X Fiche 50-309.84/03/07.8403220056
- --8403220062 IE Insp Rept 50-309/84-03 on 840207-10 No violations noted Major areas inspected inservice insp program, including GA function & control of exam equipment MCBREARTY, RA , DURR, J P Region I, Office of Director 84/03/05 Spp 22714 341 24% Fiche 50-309,84/03/07,8403220056
- 8403220095 Forwards IE Insp Rept 50-309/83-20 on 83:101-123: & natice of violation STAROSTECKI.R Division of Project & Resident Programs 84/03/07 RANDAZZA.J 8 Mains Yanker Atomic Power Co 2pp 227:15 163 24X Fichs 50-307.84/03/07.8403220095
- --8403220078 Notice of violation from insp on 831101-1231 * Region 1, Office of Director 84/03/07 1p 22715 165 24X Fiche 50-309,84/03/07,8403220075
- --8403220103 IE Insp Rept 50-307/83-20 on 831101-1231 Violation identified plant shift superintendent did not check tags on Tagging Order 2137-83 HOLDEN,C . ARCHITZEL,R , SWETLAND,P Region I, Office of Director 84/03/06 13pp 22715 166 24X Fiche 50-309,84/03/07,8403220095
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Syc list encl DEYOUNG.R C Director's Office Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 30-000.84/03/12.8402090031
- B402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/03/21 Consolidated Edison Co of New York. Inc 123pp 22823 229 24X Fiche 50-000, 84/03/21, 8402090043
- 8402090044 IE Info Notice 84-20. "Svc Life of Relays in Safety-Related Sys " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 135pp 22933 001 24X Fiche 50-000.84/03/21.8402090044
- 8409300160 Responds to FE Bulletin 83-07 re apparently fraudulent products sold by Ray Miller, Inc Ray Miller, Inc flanges received from RECO Industries installed in safety-related sys Flanges will remain installed FRIZZLE, C D Maine Yankse Atomic Power Co 84/03/22 MURLEY, T E Region 1. Office of Director 4pp 22821 082 24% Fichs 50-309,84/03/22,84093300160
- R Periodic operating reports & related correspondence
- B403130047 "Effluent & Wasto Disposal Semiannual Rept.Jul-Dec 1983 " W/840302 ltr WHITTIER.G D Maine Yankse Atomic Power Co 83/12/31 MURLEY.T E Region 1. Office of Director lipp 22608 083 24X Fiche 50-309.83/12/31.8403130047
- 8403290256 "Annual Personnel Exposure Rept CY83 " W/840320 ltr WHITTIER.0 D Maine Yankee Atomic Power Co 83/12/31 MURLEY.T E Region 1, Office of Director 3pp 22800 075 24X Fiche 50-309.83/12/31.8403290256

- 8403020065 Monthly operating rept for Jan 1984 W/840208 ltr DIENTILLER, 9 , NCCUIBER, J T Maine Yankee Atomic Power Co 84/0 MARFFIELD, R A Management Information Branch 5pp 22442 287 24X Ficho 50-309,84/01/31,8803020065 84/01/31
- 8403300162 Monthly operating rept for Feb 1984 W/840308 ltr. SIEMILLER, 8 A. MCCUMBER, J T Maine Yankee Atomic Power Co B4/02/29 5pp 22821 086 24X Fiche 50~309,84/02/29,8403300162
- S Reportable occurrences. LERs & related correspondence
- DOCKET 50-311 SALEM NUCLEAR GENERATING STATION, UNIT 2 F Security, medical, emergency & fire protection plans
- 8403190433 Responds to 821206 & 830718 ltrs re emergency op-facility (EOF) Request to establish primary EOF 7 5 miles NOSIOGRAM Responds to 821206 & 830718 its se emergency operatio: facility (EOF) Request to establish primary EOF 75 miles from facility w/o providing backup EOF acceptable EJEENHUT, D.G. Division of Licensing 84/03/05 LIDEN, E.A. P. Service Electric & Gas Co. of New Jersey ip 22681 325 24X Fiche 50~272.84/03/05,8403190433
- 8403220006 Forwards IE Insp Repts 50-272/84-06 & 50-311/84-06 on 840206-10 No violations observed MARTIN.T T Division of Engineering & Technical Programs 84/03/08 UDERITZ.R A Public Service Electric & Gas Co of New Jersey 2pp 22716-174 24X Fiche 50-272.84/03/08.8403220006
- --8403220010 IE Insp Repts 50-272/84-06 & 50-311/84-06 on 840206-10 No violations noted Major areas inspected security organization, security program audit, testing & maint, physical barriers, security sys power supply & assessment aids MADDEN.W J Region I. Office of Director 84/03/06 App 22716 176 24% Fiche 50-272,84/03/08,8403220006
- 8403190243 Notification of 840418 workshop in King of Prussia.PA to discuss lessons learned from recent App & fire protection safe shutdown insp & topics described in IE Info Notice safe shutdown insp & topics described in IE inso Notice
 B4-07 Agenda for workshop encl
 MURLEY.T E Region L. Office of Director 84/03/09 d'TODLE.J D
 Consolidated Edison Co. of New York. Inc. KENYON.B D Fennsylvania
 Power & Light Co. HARRISON.R J Public Service Co. of New
 Hampshire 35pp 22672 062 24X Fiche 50-000.84/03/09.8403190243
- P Operating license stage documents & correspondence
- 8403090049 Submits details of vendor manual review program in response to 830504 order modifying licenses Commitment to incorporate all vendor manuals for safety-related equipment into dacument control sys campleted
 LIDEN,E A Public Service Electric % Cas Co of New Jersey
 84/08/22 KISTER.H B Division of Project & Resident Programs
 3pp 22975 345 24% Fiche 30-272.84/02/22,8403090049
- 8403030119 Forwards supplemental response to Generic Ltr 83-28, "Required Actions Dasad on Generic Implications of Salem
 - *Required wittings based on density implifactions of Salem ATMB Events "
 BARNEE, P. L. Commonwealth Edison Co. 84/02/27 DENTON, M.R. Off of Nuclear Reactur Regulation, Director 26pp 22488 084. 24X Fithe 50-000, 84/02/29, 8403050119
- 8403130017 Requests extension for updating inadequate core cooling instrumentation & reactor vessel level instrumentation sys status repts per TMI Item II F 2 & providing Westinghouse proprietary info until 840402 LIDEN.E A Public Service Electric & Gas Co of New Jersey 84703702 VARGA-8 A Operating Reactors Branch 1 ip. 22614-361 24X Fiche 50-272,84703702,8403130017
- 8403130108 Requests 4-month extension until June 1784 for submittal of technical rept on reactor vessel surveillance Capsule T LIBEN.E A Public Service Electric & Gas Co of New Jersey 84/03/02 VARGA.B A Operating Reactors Branch 1. 2pp 22600 259 24X Fiche 50-311.84/03/02.8403130108
- 8403260030 Requests identification of any potential problems or items re-completion of NUREG-0737 items by Sept 1984 Response requested within 30 days of itr receipt VARGA.S A Operating Reactors Branch 1 84/03/02 UDERITZ.R A Public Service Electric & Gas Co of New Jersey 3pp 22763 2F1 24X Fiche 50-272.84/03/02.8403260050

- E403140113 Forwards "Salem Generating Station 316(b) Demonstration," per 830623 request for add1 info re review of OL application for Hope Creet
 MITTL: R L Public Service Electric & Gas Co of New Jersey
 84/03/05 SCHWENCER: A Licensing Branch 2 ip 22627 124 24X
 Fiche 50-000.84/03/05.8403140113
- --8403140117 "Salem Generating Station 316(b) Demonstration "
 * Public Service Electric & Gas Co of New Jersey 84/0
 647pp 22627 125 24X Fiche 50-000,84/03/05,8403140113 84/02/29
- 840329028: Forwards plant-specific info on reactor protection sys shunt trip mods, in response to NRC 830810 ltr & Generic Ltr 83-28 Shunt trip mechanism will be installed during refueling autage W/14 oversize drawings Aperture cards in FDR LIDEN.E A Public Service Electric & Gas Co of New Jersey 84/03/14 VRQA.6 A Operating Reactors Branch i 14pp 22800 200 24X Fiche 50-272.84/03/14.8403290281
- 8403300085 Requests extension to Jul 1984 for completion of post-maint 103300085 Requests extension to Jul 1984 for completion of post-maint operability testing of safety-related moviment based on revised interpretation of scope identified through discussion w/Region I personnel LIDEN,E A Public Service Electric & Qas Co of New Jersey 84/03/23 VARQA,B A Operating Reactors Branch 1 3pp 22822 073 24X Fiche 30-272,84/03/23,8403300085
- G Inspection reports, IE Bulletins & correspondence
- 8401190072 IE Info Notice 84-13. "Potential Deficiency in Motor Operated Valva Control Circuits & Annunciation " Syc list URDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22707 237 24X Fiche 50-000,84/02/28,8401170072
- 8403070080 Submits supplemental response to IE Bulletin 83-06 re nonconforming matls supplied by Tube-Line Corp Remaining four suppliers confirmed that mo subj matls supplied to Hope Creek Colt Industries info under review MARTIN.T J Public Service Electric & Oas Co of New Jersey 84/02/28 MURLEY.T E Region 1. Office of Director 2pp 22575 297 R4X Fiche 50-000,84/02/28,8403070080
- 840315006B Forwards IE Insp Repts 50-272/84-02 & 50-311/84-02 on 840116-19 No violations observed MARTIN, T Division of Engineering & Technical Programs 84, UNDERITZ, R A Public Service Electric & Gas Co of New Jerset 2pp 22643 177 24X Fiche 50-272,84/02/28,840315006B 84/02/28
- --8403150078 IE Insp Repts 50-272/84-02 & 50-311/84-02 on 840116-19 No violations observed Major areas inspected nonradiciogical chemical measurements, QC program of analytical measurements X procedures & training XIBULSKY, H , KITTAN, J , PASCIAK, W J Region 1. Defice of Director B4/02/27 3pp 22643 179 24X Fiche 50-272,84/02/28-8403150068
- B402070007 IE Info Notice 64-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list and! GRACE, J N Division of GA, Bafeguards & Inspection Programs (Post B30103) B403/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fichs 30-000.84/03/02,8402070007
- 840207000B IE Info Notice 84-16, "Failure of Automatic Sprinklar Bys Valves to Operate " Svc list encl JORDAN,E L Division of Emergency Preparadness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24% Fiche 50-000,84/03/02,8402070008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases " NO2070007 IE INFO NOTICE BATIO, REPORTING OF REAL STATES AND STATE
- 8403220105 Forwards IE Insp Repts 50-272/84-04 & 50-311/84-04 on 840111-0206 No violations observed 8TAR08TECKI.R Division of Project & Resident Programs 84/03 UDERITY.R A Public Service Electric & Gas Co of New Jersey 22715.285 24X Fiche 50-272,84/03/06.8403220105 84/03/06
- --8403220115 IE Insp Repts 50-272/84-04 & 50-311/84-04 on 840111-0206 No NOSE20115 It Insp Repts 30-272/84-04 & 30-311/84-04 on 8401 violations identified Major areas inspected status of pravious insp items.review of pariodic & special repts. LER review & operational safety verification LINVILLE, J C , SUMMERS, R J Region i, Office of Director NORRHOLM, L J Division of Project & Resident Programs. 17pp 22715, 287 24% Fiche 50-272, 84/03/06, 8403220105 84/00/07

- 8402090024 IE Info Notice 84-09. Rev 1. "Leasons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York. Inc 118pp 22635 049 24X Fiche 50-000.84/03/07.8402090024
- 8402090028 IE Info Notice 84-18. "Stress Corrosion Cracking in PWR Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22584 186 24X Fiche 50-000.84/03/07.8402090028
- 8403220006 Forwards IE Insp Repts 50-272/84-06 & 50-311/84-06 on 840206-10 No violations observed MARTIN,T T Division of Engineering & Technical Programs 84/03/08 UDERITIZ,R A Public Service Electric & Gas Co of New Jersey 2pp 22716 174 24X Fichs 50-272,84/03/08,8403220006
- --B403220010 IE Insp Repts 50-272/84-06 & 50-311/84-06 on 840206-10 No violations noted Major areas inspected security organization, security program audit, testing & maint, physical barriers, security sys power supply & assessment aids MADDEN, W. J., BAILEY, R. J., JOYNER, J. H. Region 1, Office of Director 84/03/06 App 22716 176 24X Fiche 50-272,84/03/08, MADDEN, W J , BAILEY, R Director 84/03/06 8403220006
- 8402090031 IE Bulletin 84-02. "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Syc list encl DEYGUNO, R C Director's Office of Inspection and Enforcement B4703/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche: 50-000.84/03/12.8402090031
- 8403220036 Responds to IE Bulletin 83-07. "Apparently Fraudulent Products Sold By Ray Miller.Inc " Companies supplying matls or svcs to facilities listed No matl purchased from or syce to recliftle listed No mest portuesed from Ray Miller.Inc LIDEN.E A Public Service Electric & Gas Co of New Jersey 84/03/14 MURLEY.T E Region 1. Office of Director 4pp 22865,166 24X Fiche 50-272.84/03/14.8403220036
- 8403290206 Forwards IE Mgt Meeting Repts 50-272/84-11 & 50-311/84-11 on 840201 Corrective actions taken for ALARA program deficiencies noted in IE Insp Repts 50-272/83-22 & 50-311/83-22 adequate MARTIN, T T Division of Engineering & Technical Programs 84/03/15 UDERITIZ: R A Public Bervice Electric & Qas Co of New Jersey 2pp 22803-288 24X Fiche 50-272,84/03/15,8403290206
- --8403290210 IE Mgt Meeting Repts 50-272/84-11 & 50-311/84-11 on 840201
 Major areas discussed planned improvements in program to
 reduce personnel occupational radiation exposure to ALARA
 Corrective action acceptable
 NIMITZ.R L , SHANBAKY.M M Region 1, Office of Director
 84/03/04 3pp 22803 270 24X Fiche 50-272,84/03/15,8403290206
- 8402070043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JORDAN.E. L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc 123pp 22823 229 24X Fiche 50-000,84/03/21,8402070043
- 8402090044 IE Info Notice 84-20, "Syc Life of Relaus in Safetu-Related 102090044 IE Info Notice by A...
 Bys "Svc list encl,
 JORDAN: E. Division of Emergency Preparedness & Engineering
 Response (Post 830103) B4/03/21 Consolidated Edison Co of New
 York, Inc. 135pp. 22933 001 24X Fiche 50-000.84/03/21,8402090044
- 8403290135 Forwards IE Mgt Meeting Repts 50-272/84-12 & 50-311/84-12 on 840306 to discuss util action plan for improving nuclear dept operations.

 BTAROSTECKI, R Division of Project & Resident Programs 84/03/22.

 UDERITZ, R Public Service Electric & Qas Co of New Jersey 2pp 22807.107 24X Fichs.50-272.84/03/22.8403290135.
- --8403290139 IE Mgt Meeting Repts 50-272/84-12 & 50-311/84-12 on 840306 Areas discussed overview of status of action plan to improve nuclear dept operations. LINVILLE, J.C., NORRHOLM, L.J. Region 1, Office of Director. 84/03/12 70pp 22807 109. 24X Fiche 50-272,84/03/22,8403270135.
- 8403300171 Ack receipt of 831128 & 840306 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/83-27 & 50-311/83-30 SUPERITZ, R. D. SUPERITZ STATES STATE

- --8403300177 Suppls 831128 response to NRC B31026 ltr re violations noted in IE Insp Repts 50-272/83-27 & 50-311/83-30
 Corrective actions emergency instruction action requirement, re reactor coolant pump shaft revised
 LIDEN,E A Public Service Electric & Gas Co of New Jersey 84/03/04 STARROSTECKI.R Division of Project & Resident Programs 4pp 22820 033 24% Fiche 50-272.84/03/23.8403300171
- --B403300183 Responds to NRC 831026 ltr re violations noted in IE Insp Repts 50-272/83-27 & 50-311/83-30 Corrective actions emergency instruction revised to increase limits for vibration & decision made to remove action requirements LIDEN.E A Public Service Electric & Gas Co of New Jersey 83/11/28 STAROSTECKI, R Division of Project & Resident Programs 3pp 22820 037 24X Fiche 50-272.84/03/23.8403300171
- 8403300180 Ack receipt of 831026 & 840306 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-311/83-18
 - 50-311/83-18
 STAROSTECKI Division of Project & Resident Programs. 84/03/23
 UDERITY,R A Public Service Electric & Gas Co of New Jersey
 22819 331 24X Fiche 50-311,84/03/23,8403300180
- --8403300186 Responds to NRC 830926 ltr re violations noted in IE Insp Rept 50-311/83-18 Corrective actions shift supervisor counseled re actions Maint supervisors reinsturucted on keeping operating shift informed of plant status
 LIDEN.E A Public Service Electric & Gas Co of New Jersey
 84/03/06 MURLEY.T E Region 1. Office of Director 3pp
 22819 332 24% Fiche 50-311.84/03/23.8403300180
- ---8403300170 Responds to NRC 830726 ltr re violations noted in IE Insp 103300170 Responds to NRC B30726 irr re violations noted in lE Rept 90-311/83-18 Corrective actions bhift supervisor counseled re actions Maint supervisors reinsturucted on keeping operating shift informed of plant status UDERITZ.R A Public Service Electric & Gas Co of New Jersey 83/10/26 MURLEY.T E Region 1. Office of Director 3pp 22817 335 24X Fiche 50-311.84/03/23,8403200180
- R Periodic operating reports & related correspondence
- 8403070305 Personnel exposure rept for 1783 W/840223 ltr MIDURA,H J Public Service Electric & Gas Co of New Jersey 83/12/31 MURLEY,T E Region 1. Office of Director 7pp 22546 335 24% Fiche 50-272,83/12/31,8403070305
- 8403070260 Forwards "Salem Nuclear Generating Station Semiannual Radioactive Effluent Release Rept.Jul-Dec 1983," interim rept Effluent data for Fourth Guarter 1983 incomplete Revised rept expected by 840415
 LIDEN.E A Public Service Electric & Gas Co of New Jer84/02/29 HURLEY.T Region 1, Office of Director 2pp
 24X Fichs 50-272.84/02/29,8403070260
- ---8403070261 "Salem Nuclear Generating Station Semiannual Radioactive Effluent Release Rept, Jul-Dec 1983." Interim rept * Public Service Electric & Gas Co of New Jersey RERR-131 83/12/31 48pp 22346 234 24% Fiche 50-272.84/02/27,8403070260
- 8403220142 Monthly operating rept for Feb 1984 W/840310 1tr MILLER, L K , ZUPKO, J M Public Service Electric & Gas Co of Ne Jersey 84/02/29 8pp 22714 309 24X Fiche 50-311,84/02/29, 8403220142
- 8 Reportable occurrences, LERs & related correspondence
- 8211120256 Discusses 820307 & 0718 events re loss of vital bus 2A Design change request issued to install noise suppression circuitry in safeguard equipment control sys during Jan THES refueling outage
 CHIRAMAL, M Director's Office 82/11/09 SEYFRIT, K V Reactor
 Operations Analysis Branch 5pp 22775-247 24X
 Fiche 50-31182/11/09.8211120256
- B309260515 Forwards "Load Reduction Transient at Salem Nuclear Power Plant-Unit 2 on B20114," engineering evaluation Event was significant operacting experience which should be included in forthcoming issue of Power Reactor Events TREHAN,N.K. Reactor Operations Analysis Branch B3/09/0B BEYFRIT.K.V. Reactor Operations Analysis Branch ip 22743,001 24X Fiche 50-311,83/09/0B.8309260515
- --8309260510 "Load Reduction Transient at Salem Nuclear Power Plant. Unit 2 on 820114." engineering evaluation. TREHAN.N K Reactor Operations Analysis Branch 83/09/30 23pp 22743 002 24X Fiche 50-311.83/09/08.8309260515

- iO3130384 LER 84-002-00 on 840207.RHR common section valve 2RH1 inadvertently shot resulting in loss of RHR flow through RCS Caused by beiel covers not removed to reflect release of breaker tags W/840309 ltr RUPP.JL. ZUPKO.J M Public Service Electric & Qas Co of New Jersey 84/03/07 5pp 22604 357 24X fiche 50-311,84/03/07. B403130384
- IO3220039 LER 84-003-00 on 840215 pressurizer overpressure protection sys actuated due to induced pressure transient Caused by starting reactor coolant pump Operating Procedure GPII-1 3 4 amended W/840315 ltr
 RUPP, J L . ZUPKD, J M Public Service Electric & Gas Co of New Jersey 84/03/15 4pp 22712 140 24X Fiche 50-311,84/03/15,8403220037
- IO322015; LER 84-004-00 on 840214, diesel generator 28 failed to start Caused by fuel oil supply valves bring shut on 840212 due to fuel oil leak developing on one cylinder Procedures revised W/840315 ltr RUPP-J L. ZUPKO, J M Public Service Electric & Gas Co of New Jersey 84/03/15 4pp 22714 331 24% Fiche 50-311,84/03/15, 8403220191
- 03270099 LER 64-005-00 on 840222 generator output breaker tripped on overcurrent Caused by overcurrent relay not fully resetting following reactor coolant pump start Surveillance test run satisfactorily performed WF40023 1tr RUPP.J L 7UPKG.J M Public Service Electric & Oas Co of New Jersey B4/03/23 Spp 22766 351 24x Fiche 50-3(1,84/03/23) Jersey B 8403270079

Congressional/Executive Correspondence

- O3150336 Responds to 840131 request for explanation of recent facility annual review Personnelingt & organization attitudes affected low rating if performance unacceptable, immediate enforcement action will be taken DIRCKS.W J Defice of the Executive Director for Operations 84/03/06 R03H.W V Senate 2pp 22449 265 24X Fiche 50-272,84/03/06,8403150336
- 8403150341 Requests explanation of implications of rating of unsatisfactory in area of plant operations ROTH, W V Senate B4/01/31 PALLADIND, N J Cor 22649 268 24X Fichs 50-272, B4/03/04, 8403150336 Commissioners

Operator Examinations

- O3040312 Responds to B40124 ltr re licensed operator requalification program Quizzes used to determine weaknesses & need for amphasis on sudjs Licensed operator training program Training Procedure TP-305 revised

 JIEN.E A Public Service Electric & Gas Co of New Jersey
 B4/02/28 VARQA,S A Assistant Director for Operating Reactors
 2pp 22515 333 24X Fiche 50-272,84/02/28.8403060312
- CKET 50-312 RANCHO SECO NUCLEAR GENERATING STATION Security, medical, emergency & fire protection plans
- 02230176 Forwards revised State of CA nuclear power plant emergency Tesponse plan

 HEDFORD, M D Southern California Edison Co 84/02/16

 EJSENHUT.D G Division of Licensing J83pp 22J53 001 24X

 Fiche 50-000.84/02/16.84022J0176
- 3403020117 Revised State of CA nuclear power plant emergency response plan # California, State of 83/04/30 2901pp 22353 003 24X Fiche 50-000,84/02/16,8402230176
-)3120339 Forwards order confirming util commitments to implement post-THI-related items set forth in Suppl 1 to NUREG-0737, 'Requirements for Emergency Response Capability " Order passed on util 821217 response to Generic Ltr 82-33 TOLZ, JF Operating Reactors Branch 4 84/02/21 RODRIGUEZ, R J lacramento Municipal Utility District Spp 22615 320 24X Fiche. 50-312,84/02/21,8403120339
- .403120342 Order confirming licenses commitments on emergency response capability per Suppl 1 to NUREG-0737
 EISENRUT.D G Division of Licensing 84/02/21 Sacramento Municipal Utility District App 22615 323 24X
 Fiche 50-312,84/02/21,8403120339

- 8403040387 Informs that maths on order to support 1984 refueling outage to perform alternative shutdown panel mod Generic Ltr 84-09 factored into reevaluation efforts re App R compliance RODRIGUEZ, R J Sacramento Municipal Utility District 84/02/29 STGLZ, J F Operating Reactors Branch 4 2pp 22511 352 24X Fiche 50-312.84702/29.8403060387
- J. Insurance & indomnity information
- 8403060141 Forwards Enforsements 66 & 67 to NELIA Policy NF-212, Enforsement 4 to NELIA Policy N-49. Enforsements 56 & 57 to MAELU Policy MF-75 & Enforsement 4 to MAELU Policy M-49 LATHAM. W K Sacramento Municipal Utility District 84/02/28 SALTZMAN. J B NRC No Detailed Affiliation Given 7pp 225 24X Fiche 50-312.84/02/28.8403060141 22506 356
- 8403240124 Forwards Endorsements 58 & 68 to MAELU Policy MF-75 & NELIA NOGEDICAL FORWARDS ENDOYSMENTS DE & 68 to TABLU POLICY MF-75 & NELIA POLICY NF-212, respectively MATTIMDE, J J Sacramento Municipal Utility District 84/03/08 SALTZMAN, J B NRC - No Detailed Affiliation Given 3pp 22758 133 24X Fiche 50-312,84/03/08,8403260124
- P Operating license stage documents & correspondence
- 8403010119 FDIA request for studies performed by USGS & State of CA Div NOSIONITY FULLA request for studies performed by USGS of Mines & Geology re facility seismic design CALSUYAS,C D. Affiliation Not Assigned 83/11/14 Detailed Affiliation Given 4pp 22444 345, 24X Fichs 50-312.83/11/14.8403010117 NRC - No
- B403010123 Responds to FDIA request for studies performed by USOS to State of CA Div of Mines & Opology re facility seismic design Forwards App A documents Info also available in PDR FELTON. J M Division of Rules and Records B3/12/20 CALSOYAS Affiliation Nat Assigned 3pp 22444 349 24X Fiche 50-312,83/12/20,8403010123 CALEDYAS, C D
- --7906140545 Summary of telcon to provide response to 790413 ltr requesting info re seismic analysis GARNER.D Operating Reactors Branch 4 (Pre 790625) 79/04/ REID.R W Operating Reactors Branch 4 (Pre 790625) 1p 22444 352 24X Fiche 50-312.83/12/20.8403010123 79/04/23
- --790614054B Discusses review of plant earthquake design criteria & requests info re ceismic analysis

 DAVIS, J F California, State of 79/04/13 DENTON, H R Office
 of Nuclear Reactor Regulation, Director 2pp 22444 353 24X

 Fiche 50-312,83/12/20,8403010123
- ---7910260122 Summarizes view of recent fault data, NRC requirements & fact 910280122 Summarizes view or recent rault data.resc requirements & rethat FBAR considered only three faults active Recommends that new info on fault sys be assessed MINOOUE.R B Office of Standards Development, Director 79/10/01 DENTON.H R Office of Nuclear Reactor Regulation, Director 4pp 22444 359 24X Fiche 50-312.83/12/20.8403010123
- --7911120317 Forwards RB Minogue 791001 memo to HR Denton & evaluation of relevancy to proceedings before ASCB EISENHUT,D Q Division of Operating Reactors 79/10/19 SCOTT,S Distribution Services Branch 3pp 22444 355 24X Fiche 50-312.83/12/20,0403010123
- --7911120364 Forwards seismicity rept re Sacramento County, CR & portions of 680816 CA application & 730608 safety evaluation TISON, JC Commerce, Dept of, 68707705 PRICE, HL Atomic Energy Commission, Directorate of Regulatory Operations ip 22445 085 24X Fiche 50-312,83/12/20.8403010123
- --7911120370 Requests add1 info to complete review of initial site DEVOLVES CONTROL OF THE CONTROL OF T
- --7911120413 Responds to 760115 ltr re DL Kelleker 751217 concern about nuclear plant in Orville, CA vicinity No plant planned for area Discussed DBE re plant design DIRCKB, W J NRC No Detailed Affiliation Given 76/02/06 CRANSTON, A Benate 3pp 22445 041 24X Fiche 50-312,83/12/20,8403010123
- --8001290311 Forwards response to 771001 memo re geologic & seismic reassessment of facility No immediate hazard at site Licensee should undertake program to assemble & assess new info re geology & seismology of site region JACKBGN: E Goosciences Branch 79/12/21 OAMMILL. W P Assistant Director for Standard & Advanced Reactors 70p 22445 050 24X Fiche 50-312,83/12/20.8403010123

- --8009230342 Recommends meeting w/util to review progress of selsmic assessment study
 JACKBUN,R E Geosciences Branch 80/09/12 REID,R W Operating
 Reactors Branch 4 ip 22445 057 24X Fiche 50-912.83/12/20.
 8409010123
- --B009250345 Discusses util response to NRC request for seismic reassessment Seven listed areas of info should be directed to util to avoid delay in reviewing rept ALTERMAN.I B Geosciences Branch 80/09/12 JACKSON,R E Geosciences Branch 3pp 22445 03B 24X Fiche 50-312.83/12/20, 8403010123
- --8403010150 Forwards evaluation of Unit 2 initial site exam info data review Site safety members participating in review listed DENTON, H R Atomic Energy Commission, Directorate of Licensing 74/10/10 DEYOUNG, R C Atomic Energy Commission, Directorate of Licensing 4pp 22445 046 24X Fiche 50-312.83/12/20,8403010123
- 8403010117 Partial response to FDIA request for documents by named individuals re repts, analyses, studies, procedures & sys for measurement of RCS leakage App D documents placed in PDR App A documents already available in PDR Search continuing FELTON, J M Division of Rules and Records 84/01/25 MADDEN, T J Kaye, Scholer, Fierman, Hays & Handler 7pp 22480 026 24% Fiche 50-000,84/01/25,8403010117
- --B3iii504Bi Forwards results of review of RCS leak rate test procedures & calculational methods used in 1978 at two randomly selected BHR plants.per B30920 request Deficiencies discovered during trial use period corrected DEYOUNG.R C Director's Office, Office of Inspection and Enforcement B3/11/07 DIRCKS,W J Office of the Executive Director for Operations 22pp 22482 020 24x Fiche 50-000,84/01/25,8403010117
- --8403010233 Discusses RCS leak rate calculations, per 820504 telcon Mods to RCSLK7 computer program permit leak rate calculations for pressures between 1.900 & 2.100 psig w/temp between 260 F & 270 F Plant data encl MORRILL.P J Region 5. Office of Director 82/05/05 WOODRUFF,R W Reactor Engineering Branch 17pp 22481 362 24X Fiche 50-000, 84/01/25,8403010117
- 8403050223 Further response to FDIA request for records of named individuals, including repts, analyses, studies, test calculations, procedures & practices for measurement of RCS leakage Forwards App C documents Search continuing FELTON, J M Division of Rules and Records 84/02/07 MADDEN, T J Kaye, 8chdler, Fierman, Hays & Handler 3pp 22496 234 24% Fiche 50~000,84/02/07,8403050223
- --B403050250 Forwards plant-specific data cards for facilities re reactor coolant leakage calculations, per 810902 request Addl data cards for remaining plants will be sent shortly CREWS.J.L. Division of Resident, Reactor Projects & Engineering Inspection 81/09/16 BAER.R.L. Division of Resident & Regional Reactor Inspection 2pp 22496 248 24X Fiche 50-000, 84/02/07, 8403050223
- B403010494 Forwards request for add1 info re Vol 1 to Cycle 7 reload rept Schedule for response requested within 14 days of itr receipt STOLZ.J F Operating Reactors Branch 4 84/02/15 RODRIGUEZ.R Bacramento Municipal Utility District 3pp 22438 306 24X Fiche: 50-312.84/02/15,8403010494
- 8403010388 Responds to Generic Ltr 83-41 re fast cold starts of diesel generators Diesel generators A & B Fast started 15 times between 830201 & 840215 for surveillance testing Diesel vendor recommends idle start over fast-start & load RODRIGUEZ,R J Sacramento Municipal Utility District 84/02/21 EISENHUT,D 9 Division of Literasing ip 22434 047 24X Fiche 50-312,84/02/21,8403010388
- B403010374 Forwards Amend 53 to License DPR-54 & safety evaluation Amend implements requirements of App I to 10CFR50, establishes new limiting conditions for quarterty & annual release rates & revises environ monitoring program MINER. B Operating Reactors Branch 4 84/02/22 RODRIGUEZ, R J Sacramento Municipal Utility District 2pp 22449 011 24X Fiche 50-312.84/02/22,8403010374
- --8403010377 Amend 53 to License DPR-54 implementing requirements of App I to 10CFR50, establishing new limiting conditions for quarterly & annual release rates & revising environ monitoring program GTULZ.J F Operating Reactors Branch 4 84/02/22 101pp 22449 013 24X Fiche 50-312.84/02/22.8403010374
- --8403010378 Safety evaluation supporting Amend 33 to License DPR-54 * Office of Nuclear Reactor Regulation. Director 84/02/22 23pp 22449 114 24X Fiche 50-312,84/02/22,8403010374

- 8403020350 Responds to Generic Ltr 84-03 re use of terms important to safety & safety-related Accepts opportunity to discuss subj further Participation in discussion will be through steering committee of Util Safety Classification Group RODRIGUEZ.R J Sacramento Municipal Utility District 84/02/28 TAYLOR, JM Director's Office of Office of Inspection and Enforcement 1p 22439 022 24% Fiche 50-312,84/02/28,8403020350
- 8403050007 Application for Proposed Amend 103 to License DPR-54, changing quarterly callor requirements for area monitors R-15025, R-15026 & R-15027 LATHAM.N Sacramento Municipal Utility District 84/02/28 EIBENHUT, D G Division of Licensing 4pp 22470 190 24X Fiche 30-312.84/02/28,8403050007
- --8403050008 Proposed Tech Spec re change to quarterly calibr requirements for area monitors R-19025.R-15026 & R-15027 * Sacramento Municipal Utility District 84/02/28 1p 22490 194 24X Fiche 50-312.84/02/28.8403050007
- --8403050010 "Safety Evaluation to Support Changing Quarterly Calibr Requirement for Area Monitors R-15025.R-15026 & R-15027 " * TERA Corp 82/01/26 3pp 22490 195 24X Fiche 50-312,84/02/28.8403050007
- 8403120302 Requests remittal of Class III fee for review of 840123 application for Tech Spec changes re NUREO-0737 requirements DIGOS,R M License Fee Management Branch 84/03/01 RODRIGUEZ,R Sacramento Municipal Utility District ip 22576 360 24X Fiche 80-312,84/03/01,8403120302
- 8403130125 Forwards addl info re Cycle 7 reload rept,Vol 1,per 840215
 Itr Structural characteristics of racking & crushing
 failure modes illustrated
 RODRIGUEZ,R J Sacramento Municipal Utility District 84/03/06
 STDLZ,J F Operating Reactors Branch 4 3pp 22601 334 24X
 Fiche 50-312.84/03/06.8403130125
- 8403200001 Forwards fee payment to cover 840228 proposed Amend 103 to License DPR-54 CQLOMBO,R W Sacramento Municipal Utility District 84/03/14 MILLER,W O License Fee Management Branch 1p 22685 211 24X Fiche 50-312,84/03/14,8403200001
- 8403260215 Forwards Class III fee for proposed Amend 100 to License DPR-54,per 840123 ltr. in response to NRC 840301 request RODRIGUEZ,R J Sacramento Municipal Utility District 84/03/21 MILLER,W O License Fee Management Branch 1p 22756 161 24X Fiche 50-312.84/03/21.8403260215
- G Inspection reports, IE Bulletins & correspondence
- B4030B040B FDIA request for repts of insp carried out under Condition 2 of Nuclear Energy Liability policies for facilities CALBOYAS, C D Affiliation Not Assigned 84/02/07 Region 5, Office of Director 4pp 22567 341 24X Fiche 50-000,84/02/07, 8403080408
- B403060401 Forwards IE Insp Rept 50-312/83-37 on B31227-29 Insp performed re allegations concerning processing electrical cable pull cards B16HDF.T W Region 5. Office of Director B4/02/17 RDDRIGUEZ, R J Sacramento Municipal Utility District 2pp 22518 276 24X Fiche 50-312,84/02/17,8403060401
- --8403060406 IE Insp Rept 50-312/83-37 on 831227-29 Major areas inspected allegations re electrical cable pull card inadequacies Allegations substantiated BURDDIN, J F. KIRSCH, D F. Region 5, Office of Director 84/02/15 5pp 22518 278 24X Fiche 50-312,84/02/17,8403040401
- 8403130498 Forwards IF Performance Appraisal Rept 50-312/83-35 on 831107-18 & 28-1201 Requests response within 60 days reactions taken to improve mgt controls in areas of GA audits & plant operations
 PARTLON, J G Division of GA. Safeguards & Inspection Programs (Post 830103) 84/02/17 RODRIGUEZ/R Sacramento Municipal Utility District 6pp 22634 353 24X Fiche 50-312.84/02/17,8403130498
- --B403i30499 IE Performance Appraisal Rept 50-3i2/83-35 on 83i107-i8 & 28-120i Major areas inspected licensee mgt controls over selected licensed activities HINCKLEY.D G, WDESSNER.J D, FOSTER.L E Division of GA, Safeguards & Inspection Programs (Post 830103) B4/01/27 52pp 22634 359 24X Fiche 50-3i2,84/02/17,8403i30498
- 8403080061 Forwards IE Insp Rept 50-312/84-01 on 840116-20 & 26 & telcons on 840131,0202 & 20 No noncompliance noted MEMBLAMSKI, F A Region 5, Office of Director 84/02/21 RODRIGUEZ, R J Sacramento Municipal Utility District 19 22557 246 24X Fiche 50-312,84/02/21,8403080061

- --8403080075 IE lnsp Rept 50-312/84-01 on 840116-20 & 26 & telcons on 840131.0202 & 20 No noncompliance or deviations noted Major areas inspected items of noncompliance & radwaste audit of solid.llowed & gaseous radwaste processing NORTH-H S WENSLAMSKI.F A Region 5. Office of Director 84/02/21 10pp 22559 247. 24% Fiche 50-312.84/02/21.8403080061
- 3403080417 Responds to FOIA request for repts of insp carried out under Condition 2 to Nuclear Energy Liability policies for faction 2 to Nuclear Energy Liability policies for facilities NRC does not have repts FELTON.J M Division of Rules and Records 84/02/22 CALSDYAS.C D Affiliation Not Assigned. 1p 22567 345 24x Fiche 50-000.84/02/22.8403080419

- 1403080274 Forwards IE Insp Rept 50-312/83-36 on 831205-840110 & notice OF VIOLATION BISHOP, T W Region 5, Office of Director 84/02/23 F Sacramento Municipal Utility District 200 22557 277 RODRIGUEZ, R Fiche 50-312, 84/02/23, 8403080274
- --8403080274 Natice of violation from insp on 831205-840110 YOUNG.T Region 5, Office of Director 84/02/23 2pp 22557 279 24% Fiche 50-312,84/02/23,8403080274
- --8403080279 IE Insp Rept 50-312/83-36 on B31205-840110 Noncompliances noted failure to follow temporary change procedure t failure to comply w/surveillance procedure spec for operability of TO Comply w/surve;;;ance processie spec (or operative) or operative; level instruments CANTER,H L . PEREZ, 0 P . YOUNO, T Region 5, Office of Director 84/02/22 13pp 22357 281 24X Fiche 50-312,84/02/23,8403080274
- B401198072 IE Info Notice B4-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Syc 11st
 - enci JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/02/28 Consolidated Edison Co of New York, Inc. 115pp 22909 239 24X Fiche 50-000,84/02/28,8401190072
- B40R090007 IE Info Notice B4-14. "Highlights of Recent Transport Regulatory Revs by DOT & NRC." Svc list encl GRACE.J N Division of GA: Bafeguards & Inspection Programs (Post B30103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000.84/03/02.8402070007
- 3402070008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate" Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830102) 84/03/02 Consolidated Edison Co. of New York: Inc. 122pp 22353 098 24% Fiche 30-000.84/03/02.8402090008
- 3402090009 IE Info Notice 84-15. "Reporting of Radiological Releases ' Svc list encl
 JORDAN.E L Division of Emergency Preparadness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc. 119pp 22553 217 24X Fiche 50-000.84/03/02.8402090009
- 3402070011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Capling Components Below Nil Ductility Temp " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553.336 24X Fiche 50-000,84/03/05,8402070011
- 3402090024 IE Info Notice 84-09.Rev 1. "Lessons Learned From Insps of Fire Protection Bafe Shutdown Sys " Svr list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22695 049 24x Fiche 50-000.84/03/07,8402090024
- 3402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Sys " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Office (Post 800103) 84/03/07 Consolidated Edison Co of New York, Inc. 118pp 22584 186 24X Fiche 50-000, 84/03/07. 8402070028
- 1403130343 Confirms 840323 meeting in Walnut Creek.CA to discuss SALP rupt for Oct 1982 Nov 1983 Agenda encl BISHOP.T W Region 5. Office of Director 84/03/09. MATTIMOE,J J Bacramento Monicipal Utility District. 2pp 92617 196 24X Fichs 50-312.84/03/09.8403130343
- --8403130352 Notification of significant licenses meeting on 840323 in Walnut Creek.CA to discuss SALP rept for Oct 1982 Nov
 - sa Region 5, Office of Director 84/03/09. Region 5, Office of rector is. 22617 198. 24% Fiche 50-312,84/03/09,8403130343

1V 1983 34pp 22617 199 24X

- 8402090031 IE Builetin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " 8vc list enc!
 DEYOUND.R C Director's Office Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24% Fichs 50-000.84/03/12,8402090031
- 8403170275 Forwards "Anticipated Performance Behavior of Auxiliaru 1031902/3 Forwards "Anticipated Performance Behavior of Aux Feedwater Pumps Under Extreme Conditions W/Main Steam Line Brosk W/Both Nuclear Steam Generators at Atmospheric Pressure," per response to IE Bulletin 80-04 RUDRIGUEZ, R J Sacromento Municipal Utility District 84 STOLZ, J F Operating Reactors Branch 4 ip 22672 287 Fichs 80-312-84/03/19,8403190275
- --8403190282 "Anticipated Performance Behavior of Auxiliary Feedwater Pumps Under Extreme Conditions W/Main Steam Line Break W/ Both Nuclear Steam Generators at Atmospheric Pressure " MAKAY.E Energy Research & Consultants Corp ERCO-693 84/02/1 27pp 22672 288 24X Fiche 50-312,84/03/19,8403190275 -693 84/02/16
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Fost 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000,84/03/21,8402090043
- 8402090044 JE Info Notice 84-20, "Svc Life of Relays in Safety-Related Bys " Svc list enc! JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York Inc 135pp 22733 001 24X Fiche 50-000.84/03/21.8402070044
- R Periodic operating reports & related correspondence
- 8403200045 Monthly operating rept for Feb 1984 W/840304 ltr COLOMBO,R , RODRIGUEZ,R J Sacramento Municipal Utility District B4/02/27 7pp 22685 138 24% Fiche 50~312,84/02/29,8403200045
- B Reportable occurrences, LERs & related correspondence
- B40301045i Informs Commission of problems w/emergency diesel generators mfg by Transamerica Delaval. Inc DIRCKS, W J Office of the Executive Director for Operations SECY-83-034 B4/01/25 4pp 22438 347 24X Fiche 50-000.84/01/25.
- 8403230056 Part 21 rept re Westinghouse mechanically interlocked full voltage reversing starters not maintaining required relative positions Caused by assemblers incorrectly removing backing places RODRIGUEZ.R J Bacramento Municipal Utility District 84/02/15, MARTIN.J B Region 5, Office of Director 5pp 22726 345 24% Fiche 50-312.84/02/15,8403230054
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines, Gimpel NPS-4 T&T valve, to close Encl ltr dtd 840203 sent to listed utils GE notified of affected units in BWR plants
 THEROUX,R R Terry Corp 84/02/22 WOODRUFF,R W Director's
 Office, Office of Inspection and Enforcement App 22706 327
 Fiche 50-000,84/02/22,8403210032
- B403010207 Forwards "Investigation of Types AF & AE Piston Skirts," per Transaments Delaval, Inc Owners Group program commitments.
 Rept evaluates cracks in AF piston skirts in Shoreham &
 Grand Gulf Nuclear Power Stations
 MUSELER.H J TDI (Transamerica Delaval, Inc.) Guners Group
 84/02/27 DENTON, H R Office of Nuclear Reactor Regulation,
 Director 3pp 22434 090. 24X Fiche 50-000,84/02/27,8403010207
- 8403010218 Forwards task descriptions for 16 known problems re Transamerica Delaval, Inc. emergency diesel generators
 MUSELER.W J TDI (Transamerica Belaval, Inc.) Duners Group
 B4/02/28 DENTON, H R Office of Nuclear Reactor Regulation.
 Director 42pp 22435 177 24X Fiche 50-000, 84/02/28, 8403010218
- 8403260233 Forwards summary list of deficiencies identified per 10CFR50 55(e), Part 21 & potential generic ltr repts for comments Edinorities STAROSTECKI,R Division of Project & Resident Programs, 84/02/28 Region 1, Office of Director, 7pp 22756.065 24X Fiche 50-000,84/02/28,8403260233
- 8403060452 LER 84-004-00 on 840124, power supply for meteorological tower instrumentation failed Caused by temporary overhead feeder experiencing severe spikes & switching transients Power supply repaired M/840301 ltr COLOMBO.R W. MATTIMOE.J J Sacramento Municipal Utility District. 84/03/02 MATTIM.J B Region 5. Office of Director 3pp 22511 341 24X Fithe 50-312,84/03/02,8403040452

- 8403060467 LER 84~006-00 on 840131.plant mgt notified that for calendar training yr 1983,23 operators & 16 security personnel did not attend quarterly class training session Caused by scheduling problems W/840301 ltr COLOMBG.R W. MATTIMOS.J J Bacramento Municipal Utility District 84/03/02 MARTIN.J B Region 9. Office of Director 3pp 22807 COL 24X Fiche 50~312,84/03/02.8403060467
- 8403140048 Forwards "Grand Gulf Component Tracking Sys," "Shoreham Component Tracking Sys" & "Transamerica Delaval, Inc.

 Disasel Generators Cumers Group Program Plan," to resolve concerns w/smergency dissel generators

 MUSELER, W.J. Long Island Lighting Co. 84/03/02 DENTON, H.R.

 Office of Nuclear Reactor Regulation, Director 2pp 22626-062

 24X Fiche 50-000, 84/03/02, 8403140048
- ---8403140095 "Transamerica Delaval, Inc Diesel Generators Owners Group Frogram Fian " * TDI (Transamerica Delaval, Inc) Owners Group 84/03/02 261pp 22628-223 24X Fichs 50-000,84/03/02,8403140048
- 8403130112 Forwards tentative schedule for responding to NRC questions re Transamerica Delaval diesel generators, per 840131 ltr Delays or changes in owners group qualification program could change schedule RODRIGUEZ, R J Sacramento Municipal Utility District 84/03/05 8TGL.7.J F Operating Reactors Branch 4 3pp 22615 292 24% Fiche 30-312,84/03/05,8403130112
- E40R090039 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delaval, Inc (TDI) Owners Group Distribution list encl.

 EISENHUT, D Q Division of Licensing 84/03/12 PALLADIND Commissioners 5pp 22708 001 24X Fichs 50-000,84/03/12,8402090039
- --8403060536 Forwards summary of 840210 meeting w/Transamerica Delaval, Inc Owners Group in Bethesda, MD re problems w/emergency disset generators CARU90.R Licensing Branch 2 84/02/27 D'REILLY, J P NRC No Datailed Affiliation Given 6pp 22708 006. 24X Fiche 50-000, 84/03/12, 8402090039
- --8403060554 Transcript of 840210 meeting w/Transamerica Delaval.Inc Owners Group in Bethesda.MD re problems w/emergency diesel generators * NRC - No Detailed Affiliation Given 84/02/10 147pp 47201 008 24X Fiche 50-000.84/03/12.8402090039
- --8403070409 Summary of 840216 meeting w/Transamerica Delaval, Inc Dwners Group in Wading River.NY re program plan to establish reliability of diesel generators Agenda, meeting transcript & attendance list encl MILLER.M A Licensing Branch 4 84/02/27 Licensing Branch 4 8pp 22708 161 24X Fiche 50-000,84/03/12,8402090039
- --8403070423 Transcript of 840216 conference in Wading River:NY re Transamerica Delaval, Inc diesel generators Pp 1-82 * Commissioners 84/02/16 84pp 22708 169 24X Fiche: 50-000:84/03/12:8402090039
- 8403140050 Forwards "Design Review of Connecting Rod Bearing Shells for Transamerica Delaval Enterprise Engines" for Shoreham & Grand Gulf diesel generators MUBELER, W J Long Island Lighting Co 84/03/12 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22632 074 24% Fiche 50-000,84/03/12,8403140050
- B403150133 Forwards "Transamerica Delaval, Inc Diesel Generator Rocker Arm Capscrew Stress Analysis Rept." Capscrew design adequate for applicable engines & svc conditions MUSELER: W J TDI (Transamerica Delaval, Inc.) Cumers Group HUSELER: W J. Long Island Lighting Co 84/03/13 DENTON. H R Office of Nuclear Reactor Regulation, Director 2pp. 22639:270 24% Ficha 50-000,84/03/13.8403150133.
- 8403200184 Forwards procurement spec to which Transamerica Delaval standby diesel generators ordered in response to NRC 840131 request RODRIGUEZ.R.J Sacramento Municipal Utility District 84/03/15 8TOLZ, J F. Operating Reactors Branch 4 337pp 22686 001 24) Ficha, 50~312,84/03/15,8403200184
- B403200222 Responds to 840214 Requests for Info 1 & 2 re R-4 series engines List indicating engine number, model & svc number, customer name & address, rating, date shipped & date started encl.

 MATHEMB.C B. Transamerica Delayal, Inc 84/03/16 EISENHUT, D 0 Division of Licensing 20pp. 22691 179 24X Fiche 50-000,84/03/16,8403200222

- 8403230117 PND-V-84-016 on 840319 hydrogen explosion occurred in main generator Caused by circuit breaker trip shutting down hydrogen seal oil pump, resulting in hydrogen leak Manual safety injection to seal oil tank initiated NARBUT, P, ECKHARDT, J, Region 3, Office of Director 84/03/20 ip 22730 335 24X Fiche 50-312,84/03/20.8403230117
- 8403270132 Forwards "Emergency Diesel Generator Air Start Valve Capscrew Dimension & Stress Analysis," prepared by S&W for Transamerica Delaval, Inc (TDI) Diesel Generator Owners Group MUSELER, W J TDI (Transamerica Delaval, Inc.) Owners Group 84/03/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22774 001 24X Fiche 50-000, 84/03/23, 8403270132
- 8403270134 Requests meeting on 840418 to discuss short-term & long-term corrective actions & investigations re Transamerica
 Delaval diesel generators List of suggested meeting topics
 encl
 MCQAUGHY, J P TDI (Transamerica Delaval, Inc.) Clumers Group
 84/03/23 DENTON, H R Office of Nuclear Reactor Regulation,
 Director 4pp 22769 133 24X Fiche 50-000,84/03/23,8403270134

T Hearing transcripts on non-antitrust matters

- 8402070039 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamorica Delaval.Inc (TDI) Owners Group Distribution list encl
 EISENHUT.D G Division of Licensing 84/03/12 PALLADINO Commissioners 5pp 22708 001 24X Fiche \$0-000.84/03/12, 8402070039
- --B403060336 Forwards summary of B40210 meeting w/Transamerica Delaval.
 Inc Owners Oroup in Bethesda-MD re problems w/emergency
 dissel generators
 CARUSD.R Licensing Branch 2 84/02/27 D'REILLY, J.P. NRC No
 Detailed Affiliation Given 6pp 22708 006 24X
 Fiche 50-000.84/03/12.8402090039
- --8403060554 Transcript of 840210 meeting u/Transamerica Delaval.Inc Owners Group in Bethesda,MD re problems w/emergency diesel generators * NRC - No Detailed Affiliation Given 84/02/10 147pp 67201 008 24X Fiche 30-000.84/03/12.8402090039
- --8403070409 Summary of 840216 meeting w/Transamerica Delaval, Inc Owners Group in Wading River, NY re program plan to establish reliability of diesel generators Agendaimeeting transcript & attendance list encl
 MILLER, MA Licensing Branch 4 84/02/27 Licensing Branch 4
 8pp 22708 161 24X Fiche 50-000,84/03/12,8402090039.
- ~-8403070423 Transcript of 840216 conference in Wading River, NY re Transamerica Delaval. Inc diesel generators Pp 1~82 * Commissioners 84/02/16 84pp 22708 167 24X Fiche 50-000,84/03/12,8402070037

DOCKET 50-313 ARKANSAS NUCLEAR ONE, UNIT 1

- F Security, medical, emergency & fire protection plans
- 8403130437 Documents results of activities conducted during 831031-1104 IE insp to review open items re emergency planning Commitment status to resolve items provided Expeditious actions by NRC to remove items requested MARSHALL, J.R. Arkansas Power & Light Co. 83/12/09 COLLINS, J.T. Region 4, Office of Director 15pp 22613 233 24X Fiche 50-313,83/12/09,8403130437
- B403090301 Public Version of Rev 11 to Emergency Plan implementing Procedure 1903 10, "Emergency Action Level Response " W/ 831220 transmittal form & JM Felton release memo LEVINE, J M Arkansas Power & Light Co 83/12/17 4pp 22584 346 24X Fiche 50-313:83/12/17.8403090301
- 8403120011 Forwards Amend 10 to emergency plan W/o encl MARBHALL.J R Arkansas Power & Light Co 84/01/20 COLLINS.J T Region 4: Office of Director 1p 22585 221 24X Fiche 50-313.04/01/20.4403120011
- B403280074 Public version of Amend 10 to emergency plan W/840120 ltr & JM Felton B40322 release memo MARBHALL.J R Arkansas Power & Light Co B4/01/R0 COLLINS.J T Region 4. Office of Director 5pp 22812 288 24X Fichs 50-313.84/01/20.8403280074

- 8403130473 Submits response to Hakney request for addlinfo re emergency plan training for non-util employees Vandors & contractors w/unescorted access within protected area receive training commensurate w/job assignments MARSHALL JR Arkansas Power & Light Co 84/01/24 GAOLJARDO, JE Division of Resident, Reactor Project & Engineering Programs ip 22613 330 24x Fiche 50-313.84/01/24.8403130473
- 8403200174 Amend il to smergency plan W/B40314 ltr MARSHALL,J R Arkansas Power & Light Co 84/02/06 EISENNUT.D Q Defice of Nuclear Reactor Regulation, Director Spp 22689 312 24x Fiche 50-313.84/02/06.8403200174
- 8403050142 Notifies that NRC will provide inspectors to observe onsite aspects of periodic exercises for emergency preparedness Scenerio for submission of info listed CDLLNS.J T Region 4. Office of Director 84/02/09 GRIFFIN.J M Alabama Power Co 2pp 22487 308 24X Fiche 50-313.84/02/09. 8403050142
- 8403130395 Forwards IE Insp Repts 50-313/84-05 & 50-368/84-05 on B40126 No violations or deviations identified DAGLIARDO. J E Region 4. Office of Director 84/02/16 GRIFFIN. J M Arkansas Power & Light Co 2pp 22616 325 24X Fiche 50-313.84/02/16.8403130395
- --B403130402 IE Insp Repts 50-313/84-05 & 50-368/84-05 on B40126 No violations or deviations identified Major areas inspected status of REX-84 exercise scenario development HACKNEY, C A , BAIRD, J B , JOHNBON, W D Region 4. Office of Director B4/02/16 3pp 22616 327 24X fiche 50-313,84/02/16,8403130395
- 8403060350 Requests approval of mod to health physics network & emergency notification sys phones from handset to headset, to alleviate fatigue during continuous open-line communications maintained in emergencies

 MARSHALL, JR Arkansas Power & Light Co 84/02/17 DENISE, R P Division of Resident, Reactor Project & Engineering Programs 19 22519 065 24% Fiche 50-313.84/02/17,8403040350
- 8403060430 Provides preliminary estimates for emergency operations facility mods to raise radiation protection factor to greater than or equal to five per NUREG-0696. In response to NRC 840214 request Util will not implement mods MARSHALLJR Arkansas Power & Light Co. 84/02/29 STOLZ.JF Operating Reactors Branch 4 MILLER.JR Operating Reactors Branch 3 2pp 28518 192 24X Fiche 50-313.84/02/29.8403060430
- 8403060324 Forwards proprietary Rev 12 to Procedure 1903 10, "Emergency Action Level Response" & proprietary Procedure 1904 series (1904 01.02.03.06.07 & 08), "Offsite Dose Projections" Proprietary procedures withheld # Arkansas Power & Light Co. 84/03/01 NRC No Detailed Affiliation Given 2pp 22513 333 24X Fichs 50-313.84/03/01, 8403060324
- 8403070358 Public version of Rev 12 to Emergency Plan Implementing Procedure 1903 10. "Emergency Action Level Response " W/ 840209 transmittal form & JM Felton 840302 release memo LEVINE, J & Pennsylvania Power & Light Co 84703/01 68pp 22564 227 24x Fiche 50-313.84/03/01.8403070358
- 8403260070 Forwards 1E Insp Repts 50-313/84-04 & 50-368/84-04 on 840124-26 No violations or deviations identified GAGLIARDOJ JE Region 4. Office of Director 84/03/05 GRIFFIN.J M Arkansas Power & Light Co 2pp 22/58 271 24X Fiche 50-313.84/03/55,8403260070
- --8403260097 If Insp Repts 50-313/84-04 t 50-368/84-04 on 840124-26 No violations or deviations identified Hajor areas inspected security organization personnel per alleged compromise of safeguards info Details withheld (ref [OCFR73 21) KELLY, JA. HALL, R E. JUNNSON, W D. Region 4. Opfice of Director 84/03/02 ip 22758 273 24X Fichs 50-313,84/03/05,8403260090
- 8403230238 Advises that based on review of 831125 submittal of detailed control room design specific areas of program plan do not meet requirements of Buppl 1 to NUREG-0737 Meeting requested to reactive deficiencies
 BTOLZ.J F Operating Reactors Branch 4 B4/03/06 GRIFFIN.J M Arkansas Power & Light Co 2pp 22759 278 24X
 Fische 50-313.84/03/06.8403230238
- 8403190277 Notifies of error in 840216 ltr transmitting IE Insp Repts 50~313/84~03 k 50~368/84~03 ltr indicated rept numbers 30~313/83-03 k 50~368/83-03 Records should be changed accordingly GAGLIARDD. J E Region 4. Office of Director 84/03/08 GRIFFIN.J M Arkansas Power & Light Co 10 22673 190 24X Fiche 50~313.84/03/08.8403190277

- --8403190283 Forwards IE Insp Repts 50-313/84-03 & 50-368/84-03 on 840125 No violations or deviations noted GAGLIARDD.JE Region 4. Defice of Director 84/02/16 ORIFFIN.J M Arkansas Power & Light Co 2pp 22673 191 24X Fiche 50-313.84/03/08.8403190277
- ---8403190288 IE Insp Repts 50-313/84-03 & 50-368/84-03 on 840125 No violations or deviations noted Major areas inspected actions taken as result of discrepancy between public info brothure & Jan 1984 telephone directory for emergency planning zone HACKNEY, C A . BAIRD, J B . JOHNSON, H D . Region 4. Diffice of Director 84/02/16 3pp 22673 193 24X Fiche 50-313,84/03/08,8403190277
- 8403150113 Forwards exercise repts of 820519 & 830316 joint exercises of offsite radiological emergency preparedness plans for Arkansas Nuclear Cine Power Station Deficiencies observed at both exercises Approval under FEMA Rule 44CFR350 in effect KRIMM.R W Foderal Emergency Management Agency 84/03/09 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 2pp 22640 001 24X Fiche 50-313,84/03/09,840315013
- --8403150119 Exercise repts of 820519 & 830316 joint exercises of offsite radiological emergency preparedness plan for Arkansas Nuclear One Power Station KRIMM.R W Federal Emergency Management Agency 84/03/09 45pp 22640 003 24X Fiche 50-313,84/03/09.8403150113
- 8403200246 Forwards Amend 4 to nuclear contingency plan.Rev 4 to
 Nuclear Contingency Plan Procedures 1,2,3,7 % 9,Rev 3 to
 Procedures 5,6,8 % 11.Rev 2 to Procedures 4 % 13 % Rev 1 to
 Procedure 15
 MARSHALL,JR Arkansas Power & Light Co 84/03/14 EISENHUT,D 0
 Office of Nuclear Reactor Regulation, Director 1p 22688 027 24X
 Fiche 50-313.84/03/14.8403200246
- ---8403200251 Rev 4 to nuclear contingency plan * Arkansas Power & Light Co 84/02/06 47pp 22688 020 24% Fiche 50-313,84/03/14,8403200246
- --8403200258 Revs 4.3.2 & 1 to Nuclear Contingency Plan Implementing
 Procedures 1,2.7 & 9.5.4,8 & 11.4 & 13 & 15, respectively, re
 assignment of personnel to emergency response organization,
 notification & command & control

 * Ariansas Power & Light Co 84/03/15 143pp 22688 077 24X
 Fiche 50-313,84/03/14.8403200246
- 8403200179 Forwards Amend 11 to emergency plan & Amend 4 to nuclear contingency plan MARSHALLJR Arkansas Power & Light Co 84/03/15 GULLINS, J T Region 4. Office of Director 1p 22689 120 24X Fiche 50-313.84/03/15.8403200179
- --84032001B0 Amend 11 to emergency plan & Amend 4 to nuclear contingency plan * Arkansas Power & Light Co 84/02/06 57pp 22689 121 24X Fishe 50-313,84/03/15,8403200179
- --8403200181 Rev 4 to Nuclear Contingency Plan Implementing Procedure 1.

 "Assignment of Personnel to Emergency Response
 Dryanization "

 # Arkansas Power & Light Co 84/02/06 137pp 22689 177 24X
- Fiche 50-313, 84/03/15, 8403200179
- 8403220185 Responds to 840217 request for relocation of HPN telephone in emergency control ctr & for approval to add headsets Request forwarded to Telecommunications Branch Headset mod approved GAOLIARDO, J E Region 4. Diffice of Director 84/03/19 ORIFFIN.J M Arkansas Power & Light Co 1p 22717,035 24X Fiche 50-313,84/03/19,8403220185
- P Operating license stage documents & correspondence
- B403050179 Application for amend to License DPR-51, updating Figures 3 1 2-1,9 1 2-2 & 3 1 2-3 of Tech Spec Section 3 1 2 7 prior to reaching 6 EFPY of operation GRIFFIN.J M Arkansas Power & Light Co. 84/02/27 STOLZ, J F Operating Reactors Branch 4 App 22515 162 24X Fiche 50-313,84/02/27,8403060179
- --8403060205 Proposed Tech Spec changes, updating Figures 3.1 2-1.3 1.2-2 & 3.1 2-3 of Tech Spec Section 3 1 2 7, prior to reaching 6 EFPY of operation * Arkansas Power & Light Co 84/02/27 6pp 22515.165, 24X Fiche 50-313,84/02/27.8403060179

- 8403050158 Comments on SER in NRC 831219 ltr re degraded grid voltage Requested Tech Spec changes would preclude compliance w/loCFR50. App A GDC 17 MARBHALL. JR Arkansas Power & Light Co 84/02/28 STQLZ. JF Operating Reactors Branch 4 App 22489 055 24X Fiche 50-313.84/02/28.8403050158
- 8403070368 Comments on util interpretation of Tech Spec 3 7 2 refailure of single cell in one bank of batteries to meet surveillance procedure criteria Tech Specs should be amended for clarity
 EISEMHUT.D 0 Division of Licensing 84/02/28 DENISE.R P
 Division of Resident, Reactor Project & Engineering Programs 2p;
 22567 202 24X Fiche 50-313.84/02/28.8403070368
- 8403150037 Application for amend to License DPR-51, revising Tech Specs re low temp overpressure protection sys, per NRC 830826 & 1104 requests ORIFEIN.J M Arkensas Power & Light Co 84/02/29 STDLZ, J F Operating Reactors Dranch 4 App 22643 013 24x Fithe 50-313, 84/02/29, 8403150037
- --8403150041 Proposed Tech Specs re low temp overpressure protection sys * Arkanses Power & Light Co 84/02/29 3pp 22643 017 24X Fiche 50-313,84/02/29,8403150037
- B403230133 REVIEW OF THE ARKANBAB NUCLEAR ONE GENERATING STATION UNIT NO 1 EMERGENCY FEEDWATER SYSTEM RELIABILITY ANALYSIS YOUNOBLOOD, R. PAPAZOGLOU, I A Brookhaven National Laboratory NUREC/CR-3529 84/02/29 Division of Safety Technology 102pp 22739 130 24% Fichs 50-313,84/02/29,8403230133
- B403140299 Forwards request for addl info re control of heavy loads Response requested within 60 days MILLER, J R Operating Reactors Branch 3 B4/03/06 GRIFFIN, J M Arkansas Power & Light Co 2pp 22635 327 24X Ficha 50-313,84/03/06.8403140299
- 8403090179 Forwards supplemental info or core exit thermocouples (CET) for inadequate core cooling interim operation.per 840210 telcon CET sys complies w/most NUREQ-0737. Item II F 2 requirements MARSHALL.J R Arkansas Power & Light Co 84/03/07 STOLZ, J F Operating Reactors Brench 4 Spp 22573 267 24X Fiche 50-313, 84/03/07. 8403090179
- B403230091 Responds to B40125 request for add1 info on seismic qualification of emergency feedwater sys (EFW) re vent & drain lines, per Genetic Ltr B1-14 EFW trains could not be disabled by open vent or drain MARSHALL, J R Arkansas Power & Light Co B4/03/16 BTOLZ, J F Operating Reactors Branch 4 2pp 22724 343 24X Fiche 50-313,94/03/16,8403230091
- 8403260051 Application to amend Licenses DPR-51 & NPF-6, changing Tech Bpets re RCS vents, post-accident sampling, long-term auxiliary feedwater sys evaluation, noble gas monitor & iodine particulate sampling, per NURGO-0737 items ORIFFIN, J M Arkansas Power & Light Co 84/03/16 STOLZ, J F Operating Reactors Branch 4 MILLER, J R Operating Reactors Branch 3 9pp 22750-293 24X Fichs 50-313, 84/03/16, 8403260051
- --8403260197 Proposed Tech Spec changes re RCS vent post-accident sampling.long-term auxiliary feedwater sys evaluation.noble gas monitors, iodine particulate sampling & containment water level monitor # Arkansas Power & Light Co 84/03/16 27pp 22750 302 24X Fiche 80-313,84/03/16,8403260051
- G Inspection reports, IE Bulletins & correspondence
- 8403130437 Documents results of activities conducted during 831031-1104 IE insp to review open items re emergency planning Commitment status to resolve items provided Expeditious actions by NRC to remove items requested MARSHALL, J.R. Arkansas Power & Light Co. 83/12/09 COLLINS, J.T. Region 4. UPFice of Director. 15pp. 22613 233 24x Fiche: 50-313, 83/12/09, 8403130437
- 8403300046 Forwards IE Insp Repts 50-313/83-36 & 50-368/83-36 on B31217-21. No violations or deviations identified GAGLIARDO, J E Region 4. Office of Director 84/01/31 GRIFFIN, J. M. Arkansas Power & Light Co 2pp 22821 240 24X Fiche 50-313,84/01/31,8403300046
- --8403300000 IE Insp Repts 50-313/83-36 & 50-368/83-36 on 831219-21 No violations or deviations identified Major areas inspected QA plans, instructions & procedures for low level radwaste storage facility MILBORN, L., MURRAY, B., JOHNSON, W.D. Region 4, Office of Director 84/01/27 10pp 22821 242 24X Fiche 50-313,84/01/31,8403300046

- B403130395 Forwards IE insp Repts 50-313/84-05 & 50-368/84-05 on B40126 No violations or deviations identified GAGLIARDO, J E Region 4. Office of Director B4/02/16 GRIFFIN.J M Arkanass Power & Light Co 2pp 22616 325 24X Fiche 50-313,84/02/16.8403130395
- --8403130402 lE Insp Repts 50-313/84-05 & 50-368/84-05 on 840126 No violations or deviations identified Major areas inspected status of REX-84 exercise scenario development HACKNEY,C A. BAIRD.J B., JOHNSON.W D. Region 4, Office of Director 84/02/16 3pp 22616 327 24X Fiche 50-313,84/02/16,8403130375
- 8401190072 IE Info Notice 84~13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JURDAN, E. L. Division of Emergency Preparadness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22707 237 24X Fiche 50-000,84/02/28,8401190072
- 8403060198 Ack receipt of 840203 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-313/83-25 & 50-368/83-25 GAGLIARDO. J E Region 4. Office of Director 84/02/29 GRIFFIN. J M Arkansas Power & Light Co lp 22517 226 24X Fiche 50-313.84/02/27.8403060198
- --8403060203 Responds to NRC 831024 ltr re violations noted in IE Insp Repts 50-313/83-25 & 50-368/83-25 Corrective actions fire watch posted at Doors 267 & 340 until mods to eliminate excessive air gaps under doors completed MARGHALL, J. R. Arkansas Power & Light Co. 84/02/03 DENISE, R.P. Division of Resident, Reactor Project & Engineering Programs 3pp 22517 227 24% Fiche 50-313,84/02/29,8403060198
- 8403060122 Notification of significant licensee enforcement conference on 840309 w/util in Arlington.TX

 * Region 4. Office of Director 84/03/01 Region 4. Office of Director 1p 22516 328 24X Fiche 50-313.84/03/01.8403060122
- B402090007 IE Info Notice B4-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl GRACE, J N Division of QA. Safeguards & Inspection Programs (Post B30103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp 22352 329 24% Fiche 50-000,84/03/02.8402090007
- 8402070008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN: E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 078 24X Fiche 50-000.84/03/02.8402070008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases"

 Svc list encl

 JORDAN.E L Division of Emergency Preparedness & Engineering

 Response (Post 830103) 84/03/02 Consolidated Edison Co of New

 York, Inc 119pp 22553 217 24X Fiche 50-000.84/03/02.8402090009
- 8402070011 IE Info Notice 84-17. "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp "Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co. of New York, Inc 117pp 22553 334 24% Fiche 50-000,84/03/05.8402090011
- 8403260090 Forwards IE Insp Repts 50-313/84-04 & 50-368/84-04 on 840124-26 No violations or deviations identified GAOLIARDO, J E Region 4, Office of Director 84/03/05 GRIFFIN.J M Arkansas Power & Light Co 2pp 22758 271 24X Fiche 50-313,84/03/05,8403260090
- --8403260099 IE Insp Repts 50-313/84-04 & 50-368/84-04 on 840124-26 No violations or deviations identified Major areas inspected security organization personnel per alleged compromise of safeguards info Details withheld (ref 10CFR73 21) KELLY, J A. HALL, R E. JOHNBON, W D. Region 4, Office of Director 84/03/02 ip 22758 273 24% Fichs 50-313,84/03/05,8403260090
- B402090024 IE Info Notice B4-09.Rev i. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000.84/03/07.8402090024
- 8402070028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR 8ys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000.84/03/07,8402070028

- 8403130120 Informs that IE Insp Repts 50~313/83-12,50~368/83-12, 50~313/83-33 & 50~368/83-33 cancelled No insp repts will be issued for subj numbers GAGLIARDO.J E Region 4, Office of Director 84/03/08 GRIFFIN.J M Arkansas Pawer & Light Co 1p 22602 197 24X Fiche 50~313,84/03/08,8403130120
- 8403190277 Notifies of error in 840216 ltr transmitting IE Insp Repts 50-313/84-03 & 50-368/84-03 Ltr indicated rept numbers 50-313/83-03 & 50-368/83-03 Records should be changed accordingly GAGLIARDO. J E Region 4, Office of Director 84/03/08 GRIFFIN. J M Arkansas Power & Light Co ip 22673 190 24X Fiche 50-313.84/03/08.8403190227
- --8403190283 Forwards IE Insp Repts 30-313/84-03 & 50-348/84-03 on 840125 No violations or deviations noted GAGLIARDOLJ E Region 4. Office of Director 84/02/16 GRIFFIN.J M Arkansas Power & Light Co 2pp 22673 191 24X Fiche 50-313,84/03/08,8403190277
- --8403190288 JE Insp Repts 50-313/84-03 & 50-368/84-03 on 840125 No violations or deviations noted Major areas inspected actions taken as result of discrepancy between public info brochure & Jan 1984 telephone directory for emergency planning zone HACKNEY.C A , BAIRD.J B , JUHNSON.W D Region 4, Défice of Director 84/02/16 3pp 22673 193 24X Fiche 50-313,84/03/08,8403190277
- 8403260230 Forwards IE Insp Repts 50-313/84-06 & 50-368/84-06 on 840221-24 No violations or deviations noted GAGLIARDO, J E Region 4, Office of Director 84/03/08 ORIFFINJ M Arkansas Power & Light Co 2pp 22755 151 24X Fiche 50-313,84/03/08,8403260230
- --8403260232 IE Insp Repts 50-313/84-06 & 50-368/84-06 on 840221-24 No violations or deviations noted Hajor areas inspected maint program BOARDMAN.J R. JOHNSON.W.D. CROSSMAN.W.A. Region 4. Office of Director 84/03/08 5pp 22755 153 24X Fiche 50-313,84/03/08, 8403260230
- 8402070031 IE Bulletin 84~02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list enc! DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 074 24X Fiche 50~000.84/03/12.8402070031
- 8403200169 Forwards QA Program Insp Rept 97900784/83-02 Significance of reported findings should be evaluated to determine acceptability of product or svc provided by vendor H/o encl GAGLIARDD. J E Region 4. Office of Director 84/03/16 GRIFFIN. J M Arkansas Power & Light Co ip 22696 353 24X Fiche 50-313.84/03/16,403200169
- 8402090043 IE Info Notice 84-19. "Two Events Involving Unauthorized Entries into PHR Reactor Cavities " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000,84/03/21,8402090043
- 8402070044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Bys " Svc Liat encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22733 001 24X Fiche 50-000,84/03/21,8402070044
- R Periodic operating reports & related correspondence
- 840306030B "Annual Radiation Exposure Rept. 1983 " W/840229 ltr MARSHALL.J R Arkansas Power & Light Co 83/12/31 DEYOUNG.R C Director's Office Office of Inspection and Enforcement 3pp 22517 047 24X Fiche 50-313.83/12/31.840306030B
- 8403020075 Monthly operating rept for Jan 1984 W/840215 ltr MORTON, K L . MARSHALL, J R Ariansas Power & Light Co 84/01/31 7pp 22441 331 24X Fiche 50-313,84/01/31,8403020075
- B40330006B Monthly operating rept for Feb 1984 W/B40315 ltr MDRTDN.K L : MARSHALL, J R Arkansas Fower & Light Co B4/02/29 BASSETT.H S Office of Resource Management, Director 7pp 22821 295 24X Fiche 50-313,84/02/29,8403300068
- S Reportable occurrences. LERs & related correspondence
- 8403230178 Forwards Technical Review Rept AEOD/T313, "Capped Containment Pressure Sensing Lines," > proposed IE info notice Issue adequately resolved RUBIN-S D Reactor Operations Analysis Branch 83/05/11 SEVERIT.K V Reactor Operations Analysis Branch 1p 22757 286 24X Fiche 50-000.83/05/11.8403230178

- ---8403230181 "Capped Containment Pressure Sensing Lines," technical review rept Condition caused by procedural inadequacy RUBIN.8 D Director's Office 83/05/11 6pp 22759 287 24X Fiche 50-000,83/05/11.8403230178
- 8403280113 "Analysis of 800407 Loss of Dffsite Power Transient at Arkansas Nuclear One Unit 1 " DAVIS.C B EG&G. Inc FIN A-6270 EGG-BAAM-4381 B3/08/31 NRC - No Detailed Affiliation Given 61pp 22811 269 24X Fichs 50-313.83/08/31.8403280113
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines, Gimpel NPS-4 T&T valve, to close Encl ltr dtd 840203 sent to listed utils OE notified of affected units in BWR plants
 THEROUX, R.R. Terry Corp. B4/02/RR WODDRUFF, R.W. Director's Office, Office of Inspection and Enforcement 6pp 22706 327 24X Fiche 50-000. B4/02/22. 8403210032
- DOCKET 50-315 DONALD C COOK NUCLEAR POWER PLANT, UNIT 1
 F Security, medical, emergency & fire protection plans
- B403090281 Public version of reissue of Rev 9 to emergency plan procedures App A. "Telephone Numbers for Key Plant Personnel" W/831110 transmittal form & JM Felton B30307 release memo * Indiana & Michigan Power Co 83/11/03 17pp 22594 303 24X Fichs. 80-315.83/11/03.8403090281
- 8403070268 Public version of Rev 9 to emergency plan implementing procedures App A. "Telephone Numbers for Key Plant Personnel" #1/831109 transmittal form & JM Felton release mema # Indiana & Michigan Electric Co 83/11/09, 18pp 22592.346 24X F(cho 50-315.83/11/09.8403070268
- B403120021 Notifies of 840323 regional workshop in Rosemont, IL w/all Region III licensees to discuss fire protection safe shutdown requirements Horkshop will provide addl guidance re 10CFR50. App R requirements Agenda encl BPEBBARD, R L Division of Emergency Preparedness & Operational Support 84/03/06 DOLAN, J E American Electric Power Bervice Corp DOLAN, J E Indiana & Michigan Electric Co 3pp 22586:272 24X Fichs 30-315.84/03/06.8403120021
- B403130202 Explains & Justifies items in nonoutage work schedule which cannot be completed by B40620 Requests schedular exemption from iOCFR50.App R.Bections III G 2. III G 3 & III J extending compliance date to B41231

 ALEXICH.M P Indiana & Michigan Electric Co B4/03/09 DENTON.H R Office of Nuclear Reactor Regulation, Director Spp 22617 312 24X Fiche 50-315.84/03/08.8403130202.
- 8403130121 Rev 5 to Emergency Plan Implementing Procedure PMP ROBO EPP 008, "Initiating Manning of Emergency Response Factitities & Calling Off-Duty Plant Personnel " KRAUSELD B. BLINDA A . SMITH, W M Indiana & Michigan Electric Co. 84/03/09 14pp R2601.320, 24X Fiche 50-315.84/03/09.8403130121
- 8403150200 Forwards draft final exercise rept for 840125 joint radiological emergency preparedness exercise State of MI & Berrien County demonstrated capability to protect public in syent of radiological emergency KRIMM.R W Federal Emergency Management Agency. 84/03/09 JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 2pp 22642 001 24X Fiche 50-315,84/03/09.840310200
- --8403150203 Draft evaluation of util.8tate of MI & Berrien County 840125 joint exercise * Federal Emergency Management Agency 84/02/22, 42pp 22642 003 24X Fiche, 50-315,84/03/09.8403150200
- 8403300233 Forwards comments on detailed control room design review. Plan demonstrates commitment to meet requirements of Suppl 1 to NUREO-0737, however, add 1 info required Meeting should be held in Apr or May 1984 to discuss comments VARQA: A Operating Reactors Branch 1 84/03/13 DOLAN, J Indiana & Michigan Electric Co 12pp 22842:350, 24% Fiche 30-315,84/03/13,8403300233.
- 8403300042 Forwards IE Insp Repts 50-315/84-05 & 50-316/84-05 on 840213-17 & notice of violation PAPERIELLO,C J. Region 3, Office of Director 84/03/14 DOLAN,J E American Electric Power Bervice Corp DOLAN,J E, Indiana & Michigan Electric Co. 2pp. 22821 343 24X Fiche.50-315.84/03/14, 2402370042
- --8403300047 Notice of violation from insp on 840213-17
 PAPERIELLO.C. J Region 3, Office of Director. 84/03/14 2pp
 22821 345 24X Fiche 50-315,84/03/14,8403300042,

- --8403300051 IE Insp Repts 50-315/84-05 & 50-316/84-05 on 840213-17 NOSCOUGH IE imap Repres 300-3164-03 on 840213-Noncompliance identified failure to meet schedular emergency plan & procedure requirements SNELL.H Q . PHILLIPS.M P Region 3. Office of Director 84, 12pp 22821 348 24X Fiche 50-315,84/03/14.8403300042
 - 84/03/12
- $8403260178\ \mbox{Submits}$ add1 info re daily App R fire insp program per 840314 request Procedure detailing listed items will be
 - Indiana & Michigan Electric Co 84/03/16 Office of Nuclear Reactor Regulation, Director 2pp 22756 122 24X Fiche 50-315,84/03/16,8403260178
- 8403220050 Ack receipt of 840308 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-315/84-01 &
 - 90-316/84-01
 PAPERIELLO, C J Region 3, Office of Director 84/03/19 DOLAN, J E American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co ip 22714 351 24X Fiche 50-315, 84/03/19, 8403220050
- ---B403220060 Responds to NRC 840210 ltr re violations noted in IE Insp Repts 50-315/B4-01 & 30-316/B4-01 Corrective actions control room functional responsibilities transfer formalized in procedures & emergency plan implementing procedures revised ALEXICH M P Indiana & Michigan Electric Co 84/03/08 KEPPLER.J G Region 3. Office of Director 2pp 22714 35: Fiche 50-315,84/03/19,8403220050
- 8403270271 Emergency Plan Implementing Procedure PMP 2081 EPP 001. "Plant Manager Procedures Index " Procedure PMP 2081, EPP 007 Cancelled due to error
 WELCH.8 E Indiana & Michigan Electric Co 84/03/28 4pp
 22800 024 24X Fiche 50-315,84/03/28,8403290271
- P Operating license stage documents & correspondence
- 8403020190 Requests status of replacement, schedule for completion & copy of Acton Lab rept re DA Mercoid switches being replaced by DAW type VARQA, B A Operating Reactors Branch 1 84/02/21 DDLAN, J Indiana & Michigan Electric Co DDLAN, J American Electric Power Service Corp 2pp 22495 001 24X Fiche 50-315,84/02/21, 8403020190
- 8403060195 Forwards "Status Summary Rept on Adequacy of Distributed Ignition Bys for Hydrogen Control." in response to NRC 820429 ltr & commitments made during NRC 830913 meeting in Bethesdam MD,

 ALEXICH: M P Indiana & Michigan Electric Co 84/03/01 DENTON. P

 Defice of Nuclear Reactor Regulation. Director 2pp 22517 188

 24X Fiche 30-315.84/03/01.8403060195 DENTON, H. R.
- --B403060200 "Status Summary Rept on Adequacy of Distributed Ignition Sys for Hydrogen Control " * Indiana & Michigan Electric Co B4/03/01 36pp 22517 190 24% Fiche 50-315.84/03/01/8403060195
- 8403190450 Forwards "SER.Pump & Valve Inservice Testing Program.DC Cook Nuclear Plant.Units 1 & 2." identifying deficiencies requiring resolution Meeting to discuss deficiencies requested VAROA, B.A. Operating Reactors Branch 1 84/03/05 DOLAN, J Indiana & Michigan Electric Co DOLAN, J American Electric Power Service Corp. 2pp. 22680 340 24% Fiche 50-315,84/03/05.

8403170450

- --B403070390 Requests mesting w/util in Mar 1984 to resolve deficiencies in pump & valve inservice testing program Contractor rept encl enci BOSNAK,R.J Mechanical Engineering Branch 84/03/01 VAROA,8 A Operating Reactors Branch i 1p 22680 342 24X Operating Reactors Branch 1 1p Fiche 50-315,84/03/05,8403190450
- Plant/Units 1 & 2 "

 COOK, T L , ROCKHOLD, H C. EQ&Q, Inc. FIN A-625
 83/10/31 NRC - No Detailed Affiliation Qiven
 22680 343. 24X Fiche. 50-315, 84/03/05, 8403190450 23pp
- 8403140224 Interprets current Tech Specs as allowing control rod movement described in util 840130 ltr. Tech Specs require 23 ft of water over top of reactor vessel flamps during movement of fuel assemblies or control rods.

 VARQA: B A Operating Reactors Branch i 84/03/07 DOLAN. J. Indiana & Michigan Electric Co. DOLAN. J. American Electric Power Service Corp 4pp. 22637 326 24% Fiche 50-315,84/03/07, 8403140224,

- 8403300296 Advises that goal for completion of technical reviews & implementation of all NUREG-0737 items, excluding Suppl 1, is Sept 1984 Requests to be advised of potential problems within 30 days Within 30 days
 VARQA, 8 A Operating Reactors Branch 1 84/03/13 DOLAN, J
 Indiana & Michigan Electric Co DOLAN, J American Electric Power
 Service Corp 2pp 22844 316 24X Fiche 50-315,84/03/13.
- 8403200223 Application for amend to ticenses DPR-58 & DPR-74.revising Tech Specs re reactor coplant vent sys per TMI Item II II i Justification for NSHC provided in 840120 ltr still applicable ALEXICH, M P Indiana & Michigan Electric Co 84/03/15 DENTON, Parties 2pp 22690 170 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 24X Fiche 50-315.84/03/15.8403200223
- --8403200228 Revised proposed Tech Specs for reactor coolant vent sum per TMI Item II B 1 * Indiana & Michigan Electric Co 84/03/15 7pp 22690 192 24X Fiche 50-315,84/03/15,8403200223
- 8403300247 Notification of 840327 & 28 meetings w/util in Stevensyille.MI to discuss current preliminary review of inservice testing program for pumps & valves & forthcoming Inservice vecting ploying to proper to 10-up program WIGGINTON, D Operating Reactors Branch 1 84/ Operating Reactors Branch 1 2pp 22826 361 Fiche 50-315.84/03/15.8403300247 84/03/15 VARGA:S A
- B403260002 Requests approval for use of encl new peaking factor limit rept for Cycle 8 Rept presumes target band of greater than or equal to 5% target axial flux difference Rept withheld ALEXICH.H P Indiana & Michigan Electric Co 84/03/20 DENTON.H 1 Office of Nuclear Reactor Regulation. Director 2pp 22747 361 DENTON, H R 24X Fiche 50-315,84/03/20,8403260002
- O Inspection reports, IE Bulletins & correspondence
- 8403050223 Further response to FOIA request for records of named individuals including repts analyses studies, test individuals including repts analyses studies, test calculations procedures & practices for measurement of RCB leakage Forwands App C documents Search continuing FELTON.J M Division of Rules and Records 84/02/07 MAI Kaye, Echoler, Fierman, Hays & Handler 3pp 22496 234 Fichs 30-000.84/02/07,8403050223 MADDEN: T J
- --8403050256 Notifies that independent measurements of identified & unidentified RCS leak rates for all PWRs in Region III performed per Procedures 617278 & 617288 Insp findings NORELIUB.C E Division of Engineering 82/03/08 JORDAN.E L Division of Engineering & Quality Assurance (Pre 830103) 2pp 22496 270 24X Fichs 50-000.84/02/07.8403050223
- B4030B0277 Forwards IE Insp Repts 50-315/84-04 & 50-316/84-04 on B40207 No noncompliance identified LITTLE:W B Region 3. Office of Director 84/02/24 DOLAN.J E American Electric Fouer Service Corp DOLAN.J E Indiana & Michigan Electric Co 2pp 22557 272 24X Fiche 50-315.84/02/24.8403080297
- --8403080302 IE Insp Repts 50-315/84-04 & 50-316/84-04 on 840207 No noncompliance or deviations identified Major areas inspected documentation & walk-downs re equipment discussed in IE Info Ltr 81-14 inspected documentation of war...
 in IE Info Ltr Bi-14
 KEATING.D E , MUFFETT, J , DANIELSON, D H Region 3, Office of
 REATING.D E , MUFFETT, J , DANIELSON, D H Region 3, Office of
 Reating.D E , MUFFETT, J , DANIELSON, D H Region 3, Office of
 Reating.D H R Director 84/02/25 3pp 8403080299
- 8403120116 Forwards IE Mgt Meeting Repts 30-315/84-03 & 50-316/84-03 on KEPPLER, J G Regian 3, Office of Director 84/02/24 DOLAN, J. E American Electric Power Service Corp DOLAN, J. E Indiana & Michigan Electric Co 2pp 22389 209 24X Fiche 50-315,84/02/24,8403120116
- --B403120124 IE Mgt Meeting Repts 50-315/84-03 & 50-316/84-03 on 840131 Major areas discussed progress & status of licensee regulatory performance improvement progrem SHAFER, W D . NORELIUS, C E Region 3. Office of Director 84/02/21 3pp 22589 211 24X Fiche 50-315.84/02/24.8403120116
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22909 239 24X Fiche 50-000,84/02/28,8401190072

- 8403060305 Ack receipt of 840210 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-315/83-22 & 50-316/83-23 PAPERIELLO:C J Region 3. Office of Director 84/03/01 DDLAN.J
 - PAPERIELLO, C.J. Region 3. Defice of Director 84/03/01 DDLAN, J.E. American Electric Power Service Corp. DDLAN, J.E. Indiana & Michigan Electric Co. 1p. 22515-357 24X Fiche 50-315, B4/03/01, B403040305
- --B403060315 Responds to NRC B40111 itr re violations noted in IE Insp Repts 50-315/83-22 & 50-316/83-23 Corrective actions lab personnel refinstructed in properly logging analysis results ALEXICH.M P Indiana & Michigan Electric Co B4/02/10 KEPPLER.J G Region 3. Diffice of Director 4pp 22515 358 24X Fichs 50-315.84/03/01.88030603055
- 8402070007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOY & NRC " Svc list encl GRACE, J N Division of OA. Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000,84/03/02,8402070007
- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fithe 50-000,84/03/02,8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases " Svc list encl JORDONNE L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 119pp 22533 217 24X Fiche 50-000,84/03/02,8402090009
- 8402070011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDÁN, E. L. Bivision of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc. 117ap 22553 336 24% Fiche 50-000,84/03/05,8402090011
- 8403080208 Ack receipt of 8402)4 ltr providing add1 info re Section B 2 C. "Review of Tests or Experiments." of 840120 submittal in response to 831117 confirmatory action ltr Subj will be examined during subsequent insp KEPPLER. J G Region 3, Office of Director 84/03/05 DOLAN. J E American Electric Power Service Corp DOLAN. J E Indiana & Michigan Electric Co Ip 22500 019 24X Fiche 50-315.84/03/05,8403080208
- --8403080214 Submits addl info to 840120 ltr.in response to 831117 confirmatory action ltr.Section B 2 C. "Review of Tests or Experiments " Term "nonroutine tests or experiments" clarified ALEXICH.M P Indiana & Michigan Electric Co 84/02/14 KEPPLER.J G Region 3. Office of Director lp 22560 020 24X Fichs 30-315.84/03/05.8403080208
- B402090024 IE Info Notice 84-09. Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JURBANG E L Bivision of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc. 118pp 22635 049 24% Fiche 50-000. B4/03/07. 8402070024
- 8402090020 IE Info Notice 84-18, "Stress Corrosion Cracking in PMR Sys " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50~000,84/03/07,8402090028
- 8403:60034 Requests relief from provisions of ASME Section XI 1974, Table IMB-2500 exam Categories B-L-1 & B-L-2 for reactor coolant pump ALEXICH. M P Indiana & Michigan Electric Co 84/03/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 22654 357 24X Fiche 50-315, 64/03/08. 8403160034
- 840209031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sgs " Svc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000.84/03/12,8402090031
- 8403300042 Forwards IE Insp Repts 50-315/84-05 & 50-314/84-05 on 840213-17 & notice of violation PAPERIELLO,C J Region 3, Office of Director 84/03/14 DDLAN,J E American Electric Power Service Corp DDLAN,J E Indiana & Michigan Electric Co 2pp 22821 343 24X Fiche, 50-315, 84/03/14, 840330042
 - Notice of violation from insp on 840213-17 _O.C.J. Region 3. Office of Director 84/03/14, 2pp 5 24% Fiche 50-315,84/03/14.8403300042

- --B403300051 IE Imap Repts 50-315/B4-05 & 50-316/B4-05 on 840213-17
 Noncompliance identified failure to meet scheduler emergency
 plan & procedure requirements
 SNELL.W 0 , PHILLIPS, N P Region 3, Office of Director 84/03/12
 12pp 22821 348 24X Fiche 50-315,84/03/14,8403300042
- 8403200202 Requests relief from 10CFR80 55a(g) provisions to allow both facilities to begin second 10-yr insp interval on same date Same start date would allow more efficient & uniform use of personnel HERING/R F Indiana & Michigan Electric Co 84/03/15 DENTON, H R Office of Nuclear Reactor Rugulation, Director 3pp 22686 347 24X Fiche 50-315,84/03/15,8403200202
- B403220050 Ack receipt of B40308 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-315/84-01 & 50-316/84-01 PAPERIELLO: O Region 3, Office of Director 84/03/19 DDLAN.JE American Electric Power Service Corp DDLAN.JE Indiana & Michigan Electric Co Ip 22714 351 24X Fiche 50-315,84/03/19,8403220050
- --8403220060 Responds to NRC 840210 ltr re violations noted in IE Insp Repts 50-315/84-01 & 50-316/84-01 Corrective actions, control room functional responsibilities transfer formalized in procedures & emergency plan implementing procedures revised ALEXICH, M P Indiana & Michigan Electric Co 84/03/08, KEPFLER, J G Region J, Office of Director 2pp 22714, 352 24X Fiche, 50-315, 84/03/19, 8403220050
- B403230137 Ack receipt of B40210 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-315/83-19 Confirms understanding that functional logic diagrams under review & review diagrams unlib e available by mid-Apr NORELIUS.C E Division of Project & Resident Programs B4/03/19 DDLAN.J E American Electric Power Service Corp DDLAN.J E Indiana & Michigan Electric Co ip 22730 147 24x Fiche 50-315.84/03/19.8403230137
- --B40323013B Responds to NRC B3122B ir re violations noted in IE Insp Repts 50-315/83-19 & 50-316/83-20 Corrective actions valve restored to proper position upon discovery of error Sample gump restored to svc ALEXICH, MP Indiana & Michigan Electric Co 84/02/10 KEPPLER, J G Region 3, Office of Director 6pp. 22730.148 24X Fiche 50-315,84/03/19,8403230137
- 6402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Syc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 123pp 22823 229 24% Fiche 50-000,84/03/21,8402090043
- 8402070044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc list and! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22733 001 24X Fiche 50-000,84/03/21,8402070044
- 8403270047 Responds to IE Bulletin 83-07. "Apparently Fraudulent Products Sold by Ray Miller, Inc " Nuclear grade matis not purchased directly from Ray Miller, Inc Review of matis supplied by subvendors continuing
 ALEXICH, M P Indiana & Michigan Electric Co 84/03/22
 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 10pp 22769 299 24% Fiche 50-315,84/03/22,840327047
- R Periodic operating reports & related correspondence
- 8403130259 "Annual Operating Rept.1983" W/840229 ltr. STIETZEL.J F., SRENSSON.B A., SMITH.W G. Indiana & Michigan Electric Co. 83/12/31 KEPPLER.J G. Region 3. Office of Director 31pp 22606 017 24X Fiche 50-315,83/12/31,8403130259
- 8403020044 Monthly operating rept for Jan 1984 W/840213 ltr. OILLET, W T . SMITH, W G Indiana & Michigan Electric Co. 84/01/31 11pp 22441 188 24X Fiche 50-315,84/01/31,8403020044
- 8403300157 Monthly operating rept for Feb 1784 W/840308 ltr. GILLETT.W T , SMITH.W G Indiana & Michigan Electric Co. 84/02/27 10pp 22820 058 24X Fiche 50-315.84/02/27,8403300157
- 8403080169 Forwards "Radioactive Effluent Release Rept.Jul-Dec 1983," ALEXICH.M P Indiana & Michigan Electric Co 84/03/01 KEPPLER.J O Region 3. Office of Director ip 22618 001 24X Fiche 50-315.84/03/01.8403080169
- --B403i30420 "Semiannual Radioactive Effluent Release Rept. Jul-Dec 1983 "
 # Indiana & Michigan Electric Co B3/12/31 352pp 22618:002.
 24X Fiche 50-215.84/03/01.8403080169.

- 8 Reportable occurrences. LERs & related correspondence
- 8303170014 Forwards AEOD/T303, "Seat Degradation in Henry Pratt Butterfly Valves " Info appears to represent potential generic problem IE info notice or circular recommended BROWN,E J Reactor Operations Analysis Branch 83/03/02 SEYFRIT.K V Reactor Operations Analysis Branch 1p 22775 167 24X Fiche 50-315,83/03/02,8303170014
- --8303170017 "Beat Degradation in Henry Pratt Butterfly Valves."

 technical review rept

 BROWN, E.J. Director's Office 83/02/24 App 22775 169 24X
 Fiche 50~315,83/03/02,8303170014
- 8403200216 NPDES noncompliance notification on 840216.blowdown sample collected during heating boiler startup indicated 9 4 ppm iron.Caused by boiler inactivity W/840313 ltr MENGE,R C Indiana & Michigan Electric Co 84/02/17 ZUGGER.P D Michigan, State of KEPPLER.J G Region 3, Office of Director 2pp 22699 323 24X Fiche 50-315,84/02/17,8403200216
- 8403200283 Updated LER 82-061/03X-1 on 820726, discovered that alarm/ trip setpoint values in newly installed containment air gaseous & particulate monitors higher than Tech Specs Caused by personnel error Procedure revised WF400313 1tr DRAPER, D.M., SMITH, W.G. Indiana & Michigan Electric Co. 84/03/13 KEPPLER, J. G. Region 3, Office of Director 3pp 22697 100 24X Fiche 30-315,84/03/13,8403200283
- DOCKET 50-316 DONALD C COOK NUCLEAR POWER PLANT, UNIT 2
 F Sacurity, medical: smbrgency & fire protection plans
- B4030702B1 Public version of reissue of Rev 7 to emergency plan procedures App A: "Telephone Numbers for Key Plant Personnel" W/831i10 transmittal form & JM Felton 830307 release memo
 * Indiana & Michigan Power Co. B3/11/03 17pp 22594 303. 24X Fichs. 50-315, B3/11/03, B4030702B1
- 8403090268 Public version of Rev 9 to Emergency plan implementing procedures App A: "Telephone Numbers for Key Plant Personnel" H/831109 transmittal form & JM Felton release memo * Indiana & Michigan Electric Co 83/11/09 18pp 28592 346 24X Fiche. 50-315.83/11/09, 8403090268
- 8403120021 Notifies of 840323 regional workshop in Rosemont, IL w/all Region III licensees to discuss fire protection safe shutdown requirements Workshop will provide addl guidance residerE50. App R requirements Agenda encl SPESBARD.R L Division of Emergency Preparedness & Operational Support 84/03/06 DOLAN.J E American Electric Power Service Corp DOLAN.J.E Indiana & Michigan Electric Co 3pp 22586.272 24X Fiche 50-315.84/03/06.8403120021
- 8403130202 Explains & justifies items in nonoutage work schedule which cannot be completed by 840620 Requests schedular exemption from 10CFR30. App R. Bections III 0 2. III 9 3 & III J extending compliance date to 841231 ALEXICH, M P Indiana & Michigan Electric Co. 84/03/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 22617 312 24X Fiche. 50-315,84/03/08.8403130202
- B403130121 Rev 5 to Emergency Plan Implementing Procedure PMP 2080 EPP 008, "Initiating Menning of Emergency Response Facilities & Calling Off-Duty Plant Personnel" KRAVBE. D. BLIND, A A., SMITH, W Indiana & Michigan Electric Co 84/03/09 14pp 22601 320 24X Fiche 50-315,84/03/09,8403130121
- 8403150200 Forwards draft final exercise rept for 840125 joint radiological emergency preparedness exercise State of MI & Berrien County demonstrated capability to protect public in sevent of radiological emergency KRIMM.R.W. Federal Emergency Management Agency 84/03/09 JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830102) 2pp 22642 001 24X Fiche 50-315,84/03/09,8403150200
- --8403150203 Draft evaluation of util. State of MI & Berrien County 840125 joint exercise + Federal Emergency Management Agency 84/02/22 42pp 22642*003. 24X Fiche, 50-315, 84/03/07, 8403150200
- 8403300233 Forwards comments on detailed control room design review Plan demonstrates commitment to meet requirements of Suppl 1 to NUREQ-0737, however, addi info required Meeting should be held in Apr or May 1984 to discuss comments VAROA, S. A Operating Reactors Branch i 84/03/13 DDLAN, J Indiana & Michigan Electric Co 12pp 22842 350 24X Fiche 50-315,84/03/13,8403300233

- 8403300042 Forwards IE Insp Repts 50-315/84-05 & 50-316/84-05 on 840213-17 & notice of violation PAPERIELLO,C J Region 3. Office of Director 84/03/14 DDLAN, J E American Electric Power Service Corp 2pp 22821 343 24X Fiche 50-315.84/03/14.8403300042
- --8403300047 Notice of violation from insp on B40213-17 PAPERIELLD,C J Region 3, Office of Director B4/03/14 2pp 22821 345 24X Fiche 50-315,84/03/14,8403300042
- --840330005: IE Insp Repts 50-315/84-05 & 50-316/84-05 on 840213-i7
 Noncompliance identified failure to meet schedular emergency
 plan & procedure requirements
 SNELL W O Region 3. Office of Director 84/03/12 12pp
 22821 348 24X Fiche 50-315,84/03/14,8403300042
- 8403260178 Submits add1 info re daily App R fire insp program per 840314 request Procedure detailing listed items will be written ALEXICH.M P Indiana & Michigan Electric Co 84/03/16 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pg 22756 122 24X Fiche 50-315.84/03/16.8403280178
- 8403220050 Ack receipt of 840308 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-315/84-01 & 50-316/84-01 PAPERIELLO.C J Region 3, Office of Director 84/03/19 DOLAN, J E American Electric Power Service Corp 1p 22714 351 24X Fiche 50-315.84/03/19.8403220030
- ---8403220060 Responds to NRC 840210 ltr re violations noted in IE Insp Repts 50-315/84-01 & 50-316/84-01 Corrective actions control room functional responsibilities transfer formalized in procedures & emergency plan implementing procedures revised ALEXICH.M P Indiana & Michigan Electric Co 84/03/08 KEPPLER.J G Region 3, Office of Director 2pp 22714 352 24X Fiche 50-315,84/03/19,8403220050
- 8403270271 Emergency Plan Implementing Procedure PMP 2081 EPP 001, "Plant Manager Procedures Index " Procedure PMP 2081 EPP 007 cancelled due to error WELCH,8 E Indiana & Michigan Electric Co 84/03/28 App 22800 024 24X Fiche 50-315,84/03/28,8403270271
- P Operating license stage documents & correspondence
- B403020190 Requests status of replacement, schedule for completion & copy of Acton Lab rept re DA Mercold switches being replaced by DAM type VARGA. S A Operating Reactors Branch 1 84/02/21 DDLAN, J Indiana & Michigan Electric Co DOLAN, J American Electric Power Service Corp 2pp 22495 001 24X Fiche 50-315,84/02/21, B403020190
- 8403060191 Application for amend to License DPR-74, revising Tech Specs re Cycle 5 reload ALEXICH, M P Indiana & Michigan Electric Co 84/03/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 22518 001 24X Fiche 50-316,84/03/01,8403060191
- --8403060197 Proposed Tech Spec changes re Cycle 5 retoad * Indiana & Michigan Electric Co 84/03/01 15pp 22518 008 24X Fiche 50-314,84/03/01,8403040191
- 8403060195 Forwards "Status Summary Rept on Adequacy of Distributed Ignition 89s for Hydrogen Control," in response to NRC 820429 Itr & commitments made during NRC 830913 meeting in Bethesda, MD ALEXICH, MP Indiana & Michigan Electric Co 84/03/01 DENTON, HR Office of Nuclear Reactor Regulation, Director 2pp 22517 188 24X Fiche 50-315.84/03/01.8403060195
- --84030&0200 "Status Summary Rept on Adequacy of Distributed Ignition Sys for Hydrogen Control " * Indiana & Michigan Electric Co 84/03/01 36pp 22517 190 24X Fichs 50-315,84/03/01.8403060195
- B403080205 Forwards proprietary & nonproprietary info supporting application for Tech Spec changes for Cycle 5 reload Proprietary repts withheld CHANDLER, J C Exxon Nuclear Co., Inc. (subs of Exxon Corp.) 84/03/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 22558 224 24X Fiche 50-316,84/03/02,8403080205
- ---8403080210 Suppl i to "DC Cook Unit 2,Cycle 5 8AR "
 COPELAND,R A. STOUT,R B., WILLIAMSON.H E. Exxon Nuclear Co., Inc
 (subs of Exxon Corp.) XN-NF-83-85 801 84/02/23 15pp
 22588 227 24X Fiche 50-316,84/03/02,8403080205

B403190450

- --8403080216 Nonproprietary "DC Cook Unit 2 Cycle 9 5% Steam Generator Tube Plugging Limiting Break LOCA/ECCS Analysis " ADES,M J. BRAUN.D J. FAUSZ.N F. Exzon Nuclear Co., Inc. (subs of Exion Corp.) XN-NF-84-21 (NP) 84/03/01 65pp 22558 244 24X Fiche 50-316,84/03/02,8403080205
- --8403080220 "DC Cook Unit 2.Cycle 5 SAR " WIMPY.P D . SKOGEN.F B . WILLIAMSON.H E Exxon Nuclear Co . Inc (aubs of Exxon Corp) XN-NF-83-85 83/10/24 34pp 22558 310 24% Fiche 50-316.84/03/02.8403080205
- --8403080223 Nonproprietary Rev 2 to "Plant Transient Analysis for DC Cook Unit 2 Reactor at 3,425 MWT Operation W/5% Steam Generator Tube Plugging "

 ADAMS.F T , KAYSER.W V , CHANDLER.J C Exxon Nuclear Co , Inc (subs of Exion Corp) XN-WF-82-32 (NP) R02 84/03/03 114pp 22558 345 24% Fiche 50-316.84/03/02.8403080205
- 8403170450 Forwards "SER, Pump & Valve Inservice Testing Program, DC Cook Nuclear Plant, Units 1 & 2:" identifying deficiencies requiring resolution Meeting to discuss deficiencies requested VARQA. S A Operating Reactors Branch 1 84/03/05 DCLAN, J Indiana & Michigan Electric Co DCLAN, J American Electric Power Service Corp 2pp 22680 340 24X Fiche 50-315, 84/03/05, 84/03/90450
- --8403070390 Requests mosting w/util in Mar 1984 to resolve deficiencies in pump & valve inservice testing program Contractor rept
 - enc.) BOSNAK.R J Mechanical Engineering Branch 84/03/01 VAROA.S A Operating Reactors Branch 1 ip 22680 342 24% Fiche 50-315.84/03/05.8403190450
- --8403070395 "SER, Pump & Valve Inservice Testing Program, DC Cook Nuclear Plant.Units 1 & 2 "

 CDON.T L , ROCKHOLD.H C EG&G. Inc FIN A-6265 EGG-EA-6413

 B3/10/31 NRC - No Detailed Affiliation Given 23pp

 22680 343 24% Fiche 50-315.84/03/05.8403190480
- 8403140224 Interprets current Tech Specs as allowing control rod movement described in util 840130 ltr Tech Specs require 23 ft of water over top of reactor vessel flange during movement of fuel assemblies or control rods VARGALE A Operating Reactors Branch 1 84/03/07 DOLAN, J Indiana & Michigan Electric Co DOLAN, J American Electric Fower Service Corp 4pp 22637 326 24% Fiche 50-315,84/03/07, 8403140224
- E403150097 Forwards nonproprietary version of XN-NF-82-90(NP). Suppl 1:
 "Potential Radiological Consequences of Incidents Involving
 High Exposure Fuel:" which supports application for Tech
 Spec changes for Cycle 5 reload
 CHANDLER.J C Exron Nuclear Co. Inc (subs of Exron Corp.)
 B4/03/13 DENTON, H R Office of Nuclear Reactor Regulation,
 Director 6pp 22639 024 24X Fiche 50-316.84/03/13.8403150097
- --8403150104 "Potential Radiological Consequences of Incidents Involving High Exposure Fuel.DC Cook.Unit 2 "
 COPELAND.R A. KAYSER, W V. STOUT.R B Exxon Nuclear Co. Inc.
 (subs of Exxon Corp.) XN-NF-82-90 (NP) 801 84/03/31 24pp
 22639 030 24X Fiche 50-314.84/03/13.8403150097
- 8403300276 Advises that goal for completion of technical reviews & implementation of all NUREO-0737 Items.excluding Suppl 1.is Sept 1984 Requests to be advised of potential problems within 30 days VARGA, 5 A Operating Reactors Branch 1 84/03/13 DOLAN, J Indiana & Michigan Electric Co DOLAN, J American Electric Power Service Corp. 2pp. 22844 316 24X Fiche 50-315,84/03/13, B40330029A
- 8403200210 Application to amend License DPR-74.revising Tech Specs re flowrate for flow balance tost of safety injection pumps ALEXICH.M P Indiana & Michigan Electric Co 84/03/15 DENTON, H R Dffice of Nuclear Reactor Regulation, Director 7pp 22697 293 24X Fiche 50-316.84/03/15.8403200210
- --8403200214 Proposed Tech Specs re flowrate for flow balance test of
- 8403200223 Application for amend to Licenses DPR-38 & DPR-74, revising Tech Specs re reactor coolant vent sys per TMI Item II B i Justification for NSHC provided in 840120 ltr still applicable
 ALEXICH, M P Indiana & Michigan Electric Co
 - 84/03/15 DENTON, R R Office of Nuclear Reactor Regulation, Director 2pp 22690,190 24X Fiche 50-315.84/03/15.8403200223

- --8403200228 Revised proposed Tech Specs for reactor coolant vent sys per TMI Item II 8 : # Indiana & Michigan Electric Co 84/03/15 7pp 22690 192 24% Fiche 50-315,84/03/15,8403200223
- 8403300247 Notification of 840327 & 28 meetings w/util in Stevensville.MI to discuss current preliminary review of inservice testing program for pumps & valves & forthcoming Inservice testing program For pumps & Valves & Corell HogginTON,D Coperating Reactors Branch 1 B4/03/1: Operating Reactors Branch 1 2pp 22826 361 24X Fishs 30-315.B4/03/15.8403300247 84/03/15
- 8403200100 Forwards Rev i to XN-NF-83-85, Suppl 1, "DC Cook Unit 2, Cycle 5 BAR "
 CHANDLER, J C Exxon Nuclear Co , Inc (subs of Exxon Corp)
 84/03/16 DENTON. H R Office of Nuclear Reactor Regulation,
 Director 1p 22699 186 24X Fiche 50-316.84/03/16.8403200100
- --8403200101 Rev 1.8uppl 1.to "DC Cook Unit 2.Cycle 5 8AR "
 COPELAND.R A . HILLIAMSON.H E . STOUT.R B Exxon Nuclear Co . Inc
 (sube of Exxon Corp.) XN-NF-83-85 R01 84/03/15 12pp
 22697 187 24X Fiche 50-316.84/03/16.8403200100
- B403270110 Forwards responses to NRC questions re proposed B40301 & 15 Tech Spec change requests to flow rate for safety injection pump flow balance test info constitutes supplemental info for changes to Cycle 5 reload ALEXICH.M P Indiana & Michigan Electric Co B4/03/23 DENTON.H R Office of Nuclear Reactor Regulation, Director 7pp 22774 041 24X Fiche 50-316,84/03/23,8403270110
- G Inspection reports, IE Bulletins & correspondence
- 8403050223 Further response to FOIA request for records of named individuals, including repts, analyses, studies, test calculations, procedures & practices for measurement of RCS leakage Forwards App C documents Search continuing FELTON, J M Division of Rules and Records 84/02/07 MADDEN, T J Kaye, Scholer, Fierman, Hays & Handler 3pp 22496 234 24X Ficha 50-000,84/02/07.8403050223
- --8403050256 Notifies that independent measurements of identified & unidentified RCS leak rates for all PWRs in Region III performed per Procedures 617278 & 61728B Insp findings summarized
 NGRELIUS.C E Division of Engineering 82/03/08 JORD.
 Division of Engineering & Quality Assurance (Pre 830103)
 22496 270 24X Fiche 50-000.84/02/07.8403050223 JORDAN, E. L.
- 8403080299 Forwards IE Insp Repts 50-315/84-04 & 50-316/84-04 on 840207 No noncompliance identified LITILE W S Region 3, Office of Director 84/02/24 DDLAN, J E American Electric Power Service Corp DDLAN, J E Indiana & Michigan Electric Co 2pp 22557 272 24% Fiche 50-315,84/02/24,8403080299
- --8403080302 IE Insp Repts 50-315/84-04 & 50-314/84-04 on 840207 No noncompliance or deviations identified Major areas inspected documentation & walk-downs re equipment discussed in IE Info Ltr B1-14 REATING,D E , MUFFETT,J , DANIELSON,D H Region 3, Office of Director 84/02/25 3pp 22557 274 24X Fiche 50-315,84/02/24,8403080297
- 8403120116 Forwards IE Mgt Meeting Repts 50-315/84-03 & 50-316/84-03 on 840131 KEPPLER.J G Region 3, Office of Director. 84/02/24 DOLAN.J E American Electric Power Service Corp DOLAN.J E Indiana & Michigan Electric Co 2pp 22589 209 24% Fiche 50-315.84/02/24,8403120116
- --8403120124 IE Mgt Meeting Rapts 50-315/84-03 & 50-316/84-03 on 840131 Major areas discussed progress & status of licensee regulatory performance improvement program
 SHAFER, W D , NORELIUS, C E Region 3, Office of Director
 84/02/21 3pp 22589 211 24X Fiche 50-315,84/02/24,8403120116
- 8401190072 lE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103), 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22909 239 24X Fiche: 50-000,84/02/28,8401190072
- 8403050305 Ack receipt of 840210 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-315/83-22 & correct violations noted in IE Insp Repts 50-315/83-22 & 50-315/83-23 PAPERIELLO,C J Region 3, Office of Director 84/03/01 DOLAN, J American Electric Power Service Corp DOLAN, J E. Indiana & Michigan Electric Co 1p 22515:357 24X Fiche 50-315,84/03/01,840306305 DOLAN, J. E.

- --8403060315 Responds to NRC 840111 ltr re violations noted in IE Insp Repts 50-315/83-22 & 50-316/83-23 Corrective actions lab personnel reinstructed in properly logging analysis results ALEXICH, M P Indiana & Michigan Electric Co 84/02/10 KEPPLER, J Q Region 3, Office of Director 4pp 22515 358 24X Fiche 50-315, 84/03/01/8403060305
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE.J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000,84/03/02.8402090007
- 8402090008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 122pp 22553 098 24X Fiche 50-000.84/03/02.8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases"

 Evc list encl

 JORDAN, E.L. Division of Emergency Preparedness & Engineering

 Response (Post 830103) 84/03/02 Consolidated Edison Co. of New

 York, Inc. 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- B402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN: E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche.50-000:84/03/05,8402090011
- B4030B020B Ack receipt of B40214 ltr providing add1 info re Section B 2.C, "Review of Tests or Experiments." of B40120 submittal in response to B31117 confirmatory action ltr Bub, will be examined during subsequent insp KEPPLER. J Q Region 3, Office of Director B4/03/05 DOLAN. J E American Electric Pawer Service Corp DOLAN. J E Indiana & Michigan Electric Co 1p 22560 019 24X Fiche 50-315,84/03/05,8403080208
- --8403080214 Submits add1 info to 840120 ltr.in response to 831117 confirmatory action ltr.8ection B 2 C. "Review of Tests or Experiments " Term "nonroutine tests or experiments" clarified.

 ALEXICH.M P Indiana & Michigan Electric Co 84/02/14 KEPPLER.J Q. Region 3, Office of Director ip 22560 020 24X Fiche: 50-315, 84/03/03,8403080208
- B402090024 IE Info Notice B4-09, Rev 1. "Lessons Learned From Insps of Fire Protection Bafs Shutdown Bys " Svc list encl JORDAN.E. L Division of Emergency Preparedness & Enginearing Response (Post B30103) B4/03/07 Consolidated Edison Co of New York, Inc 118pp 22635: 049 24X Fiche. 50-000. B4/03/07. 8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Bys." Sve list encl JORDANAE L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche. 50-000,84/03/07,8402090028
- B403i60034 Requests relief from provisions of ASME Section XI 1974, Table IMB-2500 exam Categories B-L-1 & B-L-2 for reactor coolant pump ALEXICH, M P Indiana & Michigan Electric Co 84/03/08 DENTON, H R Dffice of Nuclear Reactor Regulation, Director 3pp 22654 357 24X Fiche 50-315,84/03/08,8403i60034
- 8402070031 IE Bulletin 84-02, "Failures of GE Type HFA Ralays in Use in Class IE Safety Sys " Svc list enc!

 DEYOUNG.R.C. Director's Office, Office of Inspection and Enforcement 84/03/12. Consolidated Edison Co of New York, Inc 134pp. 22823,094. 24X Fiche 50-000,84/03/12,8402090031
- 8403300042 Forwards IE Insp Repts 50-315/84-05 & 50-316/84-05 on 840213-17 & notice of violation PAPERIELLO,C.J. Region 3, Office of Director 84/03/14. DOLAN,J E American Electric Power Service Corp DOLAN,J E Indians & Michigan Electric Co 2pp 22821 343. 24X Fiche 50-315,84/03/14,8403300042.
- --8403300047 Notice of violation from insp on 840213-17 PAPERIELLD,C J Region 3, Office of Director 84/03/14 2pp 22821.345. 24% Fiche: 50-315,84/03/14,8403300042,
- --8403300051 IE Insp Repts 50-315/84-05 & 50-316/84-05 on 840213-17 Noncompliance identified failure to meet schedular emergency plan & procedure requirements SNELLIM 0., PHILLIPS, M.P. Repion 3, Office of Director 84/03/12 12pp 22821 348. 24X Fiche 50-315,84/03/14,8403300042

- 8403200202 Requests relief from 10CFR50 55a(g) provisions to allow both facilities to begin second 10-yr imap interval on same date Same start date would allow more efficient & uniform use of personnel
 HERING.R F Indiana & Michigan Electric Co 84/03/15 DENTON.H R
 Deffice of Nuclear Reactor Regulation. Director 3pp 22686 347
 24X Fiche 50-315,84/03/15,8403200202
- B403220050 Ack receipt of 84030B ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-315/84-01 & 50-316/84-01
 PAPERIELLO, C J Region 3, Office of Director B4/03/19 DDLAN, J E American Electric Power Service Corp DDLAN, J E Indiana & Michigan Electric Co ip 22714 351 24X Fiche 50-315/84/03/19, 8403290050
- --B403220060 Responds to NRC B40210 ltm re violations noted in IE Insp Repts 50-315/84-01 & 50-316/84-01 Corrective actions control room functional responsibilities transfer formalized in procedures & emergency plan implementing procedures revised ALEXICH.M P Indiana & Michigan Electric Co B4/03/08 KEPPLER.J O Region 3. Office of Director 2pp 22714 352 24X Fichs 50-315,84/03/19,8403220050
- 8403230137 Ack receipt of 840210 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-315/83-19 Confirms understanding that functional logic diagrams under review & revived diagrams will be available by mid-Apr NORELIUS.C E Division of Project & Resident Programs 84/03/19 DOLAN.J E American Electric Power Bervice Corp DOLAN.J E Indiana & Michigan Electric Co ip 22730 147 24X Fiche 50-315,84/03/19.8403230137
- --B40323013B Responds to NRC 83122B ir re violations noted in IE Insp Repts 50-315/83-19 & 50-316/83-20 Corrective actions valve restored to proper position upon discovery of error Sample pump restored to svc ALEXICH.M P Indiana & Michigan Electric Co 84/02/10 KEPPLER.J G Region 3, Office of Director App 22730 148 24X Fiche 50-315,84/03/19,8403230137
- 8402070043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Cansolidated Edison Co. of New York, Inc. 123pp 22823 229 24X Fiche 50-000,84/03/21,8402070043
- B402070044 IE Info Notice 84-20. "Svc Life of Relays in Safety-Related Bys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24% Fiche 50-000.84/03/21.8402090044
- 8403270047 Responds to IE Bulletin 83-07, "Apparently Fraudulent Products Sold by Ray Miller. Inc "Nuclear grade matls not purchased directly from Ray Miller. Inc Review of matls supplied by subvendors continuing ALEXICH M P Indiana & Michigan Electric Co 84/03/22 DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 10pp 22769 299 24X Fiche 50-315,84/03/22,840327047
- R Periodic operating reports & related correspondence
- 8403130259 "Annual Operating Rept.1983" W/840229 1tr STIETZEL, J F , SRENSSON.B A , SMITH.W 0 Indiana & Michigan Electric Co 83/12/31 KEPPLER.J 0 Region 3, Office of Director 31pp 22606 017 24% Fiche 50-315,83/12/31.8403130259
- B403300155 Monthly operating rept for Feb 1984 W/840308 ltr OILLETT W T , SMITH W Q Indiana & Michigan Electric Co 84/02/29 7pp. 22821 068 24% Fiche 50-316.84/02/29.8403300155
- 8403080169 Forwards "Radioactive Effluent Release Rept, Jul-Dec 1983 "
 ALEXICH, M P Indiana & Michigam Electric Co 84/03/01
 KEPPLER, J O Region 3, Office of Director 1p 22618 001 24X
 Fiche 50-315,84/03/01,8403080169
- --8403130420 "Semiannual Radioactive Effluent Release Rept.Jul-Dec 1983 " * Indiana & Michigan Electric Co 83/12/31 352pp 22618 002 24X Fiche 50-315,84/03/01,8403080169

- S Reportable occurrences. LERs & related correspondence
- B303170014 Forwards ACOD/T303, "Seat Degradation in Honry Pratt Butterfly Valves "Info appears to represent potential generic problem IE info notice or circular recommended BROWN.E.J. Reactor Operations Analysis Branch B3/03/02 SEYFRIT.K V Reactor Operations Analysis Branch ip 22775 167 24X Fiche 50-315,83/03/02,8303170014
- ---8303170017 "Seat Dagradation in Henry Pratt Butterfly Valves," technical review rept
 BROWN,E J Director's Office 83/02/24 4pp 22775 168 24X Fichs 50-315,83/03/02/28303170014
- B403200217 LER 84-002-00 on 840218 turbine/reactor trip occurred from full power while placing moisture separator reheater steam coils in svc Caused by operator failing to close main steam supply valves Procedure modified W/840316 ltr
 BAKER, K R . SMITH, W G Indiana & Michigan Electric Co 84/03/16
 3pp 22699 341 24X Fiche 50-316,8403/16,8403200217
- DOCKET 50-317 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1

 F Security, modical, emergency & fire protection plans
- 8403140228 Public version of Rev 2 to Emergency Plan Implementing Procedure ERPIP A 2. "Review/Approval." W/831214 ltr & JM Falton 840312 release memo RUSBELL.L B . USI.V Baltimore Gas & Electric Co 83/12/14 5p 22637 317 24X Fiche 50-317.83/12/14.8403140228
- 8403150091 Forwards safeguards info Info withheld (ref 10CFR73 21) JOLLEY, J. R. Baltimore Gas & Electric Co. 84/02/10 CLARK, R. A. Operating Reactors Branch 3 ip 22443 001 24x Fiche 50-317.84/02/10.8403150091.
- 8403020300 Rev 9 to emergency plab implementing Procedure ERPIP-5 0, "Preparation & Control of Emergency Response " W/840227 ltr USI.V , RUSSELL.L B Baltimore Gas & Electric Co 84/02/14 10p; 22440 042 24X Fiche 30-317.84/02/14/8403020300
- 8403010301 Responds to util 831024 request for changes to Rev 12 to security plan & Rev 2 to training & qualification plan Changes consistent w/provisions of 100FR50 54(p) & acceptable
 - MARTIN T T Division of Engineering & Technical Programs 84/02/23 BOWHAKER, N J Baltimore Oas & Electric Co. 4pp 22432 118 24X Fiche 50-317,84/02/23,8403010301
- 8403150155 Forwards Rev 9 to Emergency Response Plan Implementing Procedure ERPIP-5 O, "Preparation & Control of Emergency Response"

 USI.V Baltimore Qas & Electric Co 84/02/27 Director's Office. Depice of Inspection and Enforcement 1p 22642 288 24X Fiche 80-317.84/02/27.8403150155
- 8403020343 Forwards EALP rept for Oct 1982 Sept 1983 Maint of low personnel error rate merits continued attention.
 MURLEY, T. Region 1, Office of Director 84/02/27 LUNDVALL, A E Saltimore Gas & Electric Co. Spp. 22437 217 24X
 Fiche 80-317.84/02/27.8403020343
- --8403020345 8ALP rept for Oct 1982 Sept 1983 * Region 1, Office of Director 83/12/12 57pp 22439:220 24X Fiche 50-317,84/02/29,8403020343
- ---8403020347 Forwards SALP rept for discussion & review at 831220 meeting in Baltimore.ND Recent performance during 830914 emergency proparedness exercise & two Category III areas will be discussed STAROSTECKI, R Division of Project & Resident Programs 83/12/14 LUNDVALL.A E Baltimore Oas & Electric Co 1p 22439 287 24X Fiche 50-317.84/02/27.8403020343
- 8403150110 Rev 9 to Radiological Emergency Plan Implementing Procedure ERPIP-5 2: "Emergency Planning Unit Records " W/840306 ltr. USI.V Baltimore Qas & Ejectric Co 84/03/06 5pp. 22640 209 24% Fiche 50-317,84/03/06.8403150110
- 8403190243 Notification of 840418 workshop in King of Prussia PA to discuss lessons learned from recent App R fire protection safe shutdown insp & topics described in IE Info Notice 84-09 Agenda for workshop enci MURLEY.TE Region I. Office of Director 84/03/09 0'TODLE, J D Consolidated Edison Co op New York, Inc. HARRINOTON, W D Boston Edison Co MURPHY, N P. Vermont Yankee Nuclear Fower Corp 33pp. 22672'062 24X Fiche 30-000,84/03/09,8403190243

- 8403210006 Forwards IE Insp Repts 50-317/83-35 & 50-318/83-35 on 831212-16 No violetions observed MARTIN.T T Division of Engineering & Technical Programs 84/03/07 LUNDVALL, A E Baltimore Gas & Electric Co 2pp 22704 334 24X Fiche 50-317.84/03/07.8403210006
- ---8403210016 IE Insp Repts 50-317/83-35 & 50-318/83-35 on 831212-16 No violations identified Major areas inspected amergency preparedness activities outlined in IE insp procedures & review of emergency response plan COMEN.I. HAWXHURST.J.J. CROCKER.H W. Region 1. Office of Director 84/02/17 App 22704 336 24X Fichs 50-317.84/03/09, 8403210006
- 8403190018 Forwards Celvert Cliffs Instruction CCI-310, "Emergency Operating Procedure Writers Guide." implementation schedule.validation verification plan & training plan per Suppl 1 to NUREO-0737
 LUNDVALL.A E Baltimore Gas & Electric Co 84/03/14 MILLER, J, R Operating Reactors Branch 3 5pp 22666 001 24X
 Fiche 50-317,84/03/14.8403190018
- --8403190023 Calvert Cliffs Instruction CCI-310. "Emergency Operating Procedure Hriters Ouids" Emergency operating plan validation/verification plan & training plan encl * Baltimore Gas & Electric Co. 84/03/14 46pp 22666
- 8403220032 Requests exemption from specific requirements of Section III 6 2 of 10CR380, App R & approval of equivalent separation within Fire Areas 39, 40,42 & 43 LUNDVALL,A E Baltimore Gas & Electric Co 84/03/14 MILLER,J R. Operating Reactors Branch 3 4pp 22714 335 24X Fiche 30-317.84/03/14.8403220052
- B403200029 Forwards FEMA evaluation of Town of Lusby, Calvert County, MD post-exercise radiological emergency preparedness plans for facilities Behedule for corrective actions re offsite emergency preparedness deficiencies requested MARTIN, T T Division of Engineering & Technical Programs 84/03/15, LUNDVALL, A E Baltimore Cas & Electric Co 3pp 22699 234 24% Fiche 50-317,84/03/15,8403200029
- --8403200035 Evaluation of Town of Lusby, Calvert County, MD post-exercise radiological emergency preparedness plans for facilities

 * Federal Emergency Management Agency 83/10/13 36pp 22699 237 24X Fiche 30-317, 84/03/15, 8403200029
- 8403220080 Forwards list of local news media available for public broadcasting/notification List used in lieu of FR for exigent or emergency license amends LATHAM, D W Daltimore Gas & Electric Co 84/03/15 JAFFE, D H. Operating Reactors Branch 3 2pp 22716 263 24X Fiche 50-317,84/03/15,8403220080
- B4033001B2 Forwards safeguards info Info withheld (ref 10CFR73 21)

 JBLLEY, J R Baltimore Gas & Electric Co 84/03/21 MARTIN:T T

 Division of Engineering & Technical Progrems 1p 22820 044 24X

 Fiche 50-317:84/03/21:8403300182
- J Insurance & indemnity information
- B403140036 Forwards Endorsements 56 & 57 to NELIA Policy NF-216, Endorsement 45 to MAELU Policy MF-76 & Endorsement 23 to NELIA Policy NB-348

 OAMMIE, 0 B Baltimore Oas & Electric Co 84/03/07 DINITZ, I. Office of State Programs, Director 5pp 22633 124 24X Fiche, 50-317, 84/03/07, 8403140036
- P Operating license stage documents & correspondence
- 8403010117 Partial response to FOIA request for documents by named individuals re repts, analyses, studies, procedures & sys for measurement of RCB leakage App B documents placed in PDR. App A documents already available in PDR Search continuing FELTON, J M Division of Rules and Records 84/01/25 MADDEN, T J Kaye, Scholer, Fierman, Hays & Handler 7pp 22480 026, 24% Fiche 50-000,84/01/25,8403010117
- --B011070522 Bummarizes results of independent evaluations of primary sys leak rate & some considered extensions Extension of specific evaluations to all PWR facilities recommended Draft procedure re evaluations will be submitted by B00915 JORDAN.E.L. Division of Reactor Operations Inspections B0/08/21 MDSELEY.N C Division of Reactor Operations Inspections. 1ipp 22480 266 24X Fiche 50-000,84/01/25,8403010117

- 8403050305 Notification of 840316 meeting w/util & INEL in Bethesda. MD to discuss & resolve outstanding issues re qualification of electric equipment
 - electric equipment
 JAFFE,D H Operating Reactors Branch 3 84/02/27 MILLER,J R
 Deprating Reactors Branch 3 20p 22501 267 24X
 Fiche 50-317.84/02/27.8403050305
- 8403260236 Forwards "Summary of Startup Testing for Cycle 7 "
 LUNDVALL, A E Baltimore Gas & Electric Co 84/02/27 MURLEY, T E
 Region 1, Office of Director 1p 22754 317 24x
 Fiche 50-317,84/02/27,8403260236
- --8403260248 "Summary of Startup Testing for Cycle 7"

 * Baltimore Gas & Electric Co 84/02/27 8pp 22754 318 24X
 Fiche 50-317,84/02/27,8403260236
- 8403040263 Suppls response to Generic Ltr 83-26, "Required Actions Based on Generic Implications of Salem ATMS Event " Tabular assessment of status & scheduled date for completion of specific items encl LUNDVALL, A E Baltimore Gas & Electric Co 84/02/29 EISENHUT, D G Division of Licensing 32pp 22517 323 24X Fiche 50-317, 84/02/29, 8409060263
- 8403040400 Requests mad of 830314 order requiring installation of noble gas steam affluent monitor by 840301 Mod reflects commitment to install acceptable replacement for existing sys prior to 841231.in lieu of schedule proposed in util 840203 ltr LUNDVALL.A E Baltimore Gas & Electric Co 84/03/01 MILLER.J R Operating Reactors Branch 3 2pp 22518 274 24X Fiche.50-317.84/03/01.8403060400
- 8403080083 Forwards order modifying implementation date for TMI Action Item II F 1 1. "Noble Gas Steam Effluent Monitor." per NUREO-0737 Order provides new completion date of 841231 W/a encl MILLER, J R Operating Reactors Branch 3 84/03/02 LUNDVALL, A E Baltimore Gas & Electric Co 4pp 22584 075 24X Fichs 50-317.84/03/02.8403080083
- B403160040 Advises that work required to resolve concerns in Generic Ltr B1-14, "Seismic Qualification of Auxiliary Feedwater Bys," completed, per 820106 request Valves successfully qualified by analysis w/o need for mod LUNDVALL.A E Baltimore Gas & Electric Co 84/03/14 MILLER, J R Operating Reactors Branch 3 2pp 22655:132 24X Fiche 50-317.84/03/14,8403160040
- 8403220014 Informs of recent assignment of EC Wenzinger as chief.
 Reactor Projects Section 1A, effective immediately
 BTAROSTECKI:R Division of Project & Resident Programs 84/03/15
 LUNDVALL, A E Baltimore Gas & Electric Co 2pp 22712 341 24X
 Fiche 30-317,84/03/15,8403220014
- 8403300070 Responds to request for voluntary participation requestions raised in Generic Ltr 83-41 List of type of diesel generator starts & frequency of starting cycles based on surveillance testing & corrective maint activities; encl LUNDVALL, A.E. Baltimore Gas & Electric Co 84/03/20 EISENHUT, D.G. Division of Licensing 6pp 22822 099 24X Fiche 50-317,84/03/20,8403300070
- G Inspection reports: IE Bulletins & correspondence
- 8403050203 Forwards Structural & Geotechnical Engineering Branch request for add1 info for completion of review of IE BUlletin 80-11; "Masonny Wall Design " Response requested within 60 days of receipt of 1tr MILLER, J R Operating Reactors Branch 3 84/02/24, LUNDVALL, A E Baltimore Ges & Electric Co 7pp 22528 155 24X Fiche, 50-317, 84/02/24, 8403050203
- 8401170072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 113pp 22709-237 24X Fiche 50-000.84/02/28.8401170072
- 8403020343 Forwards BALP rept for Oct 1982 Sept 1983 Maint of low personnel error rate merits continued attention MURLEY.T E Region 1, Office of Director 84/02/29 LUNDVALL,A E Baltimare Gas & Electric Co 3pp. 22439 217 24X Fiche 50-317.84/02/29,8403020343
- ---8403020345 8ALP rept for Oct 1982 Bept 1983. # Region 1, Office of Director 83/12/12 57pp 22439.220 24X Fiche, 50-317, 84/02/29, 8403020343

- --8403020346 Forwards AE Lundvall 830916 & 1202 ltrs listing corrective actions retwo Category III areas on valve lineups & fuel oil day tank level addressed in SALP rept
 LUNDVALL. AE Daltimore Gas & Electric Co 84/01/06 MURLEY. TE Region I. Office of Director ip 22439 277 24X
 Fiche 50-317,84/02/29,8403020343
- --B403020347 Forwards SALP rept for discussion & review at B31220 meeting in Baltimore, MD Recent performance during 830914 emergency preparedness electies & two Category III areas will be discussed STAROSTECKI, R Division of Project & Resident Programs 83/12/14 LUNDVALLA E Baltimore Gas & Electric Co ip 22439 287 24X Fiche 50-317,84/02/29,8403020343
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list enc! GRACE, J N Division of GA. Safeguards & Inspection Programs (Post B30103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000, B4/03/02, 8402090007
- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate" Svr list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York Inc 122pp 2253 098 24X Fiche 50-000,84/03/02,8402090008
- B402090009 IE Info Notice B4-15, "Reporting of Radiological Releases" Syc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) B4/03/02 Consolidated Edison Co of New
 York, Inc 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8402070011 IE Info Notice 84-17. "Problems W/Liquid Nitrogen Cooling Companents Below Nil Ductility Temp " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co. of New York, Inc. 117pp 22553 336 24% Fiche 50-000,84/03/05,8402070011
- 8403150049 Proposes to extend Unit 1 inservice insp interval end date to 870401 to coincide w/Unit 2 to insure both programs updated to same up to addends of ASME Code. Section XI Exemption requested Class III amend fee remitted LUNDVALL.A E Baltimore Oas & Electric Co 84/03/06 MILLER.J R Operating Reactors Branch 3 2pp 22643 141 24X Fiche 50-317,84/03/06.8403150049
- B40317040B Forwards "Calvert Cliffs Unit i, Insp of Steam Generators 11 & 12," final rept LUNDVALL, A E Baltimore Gas & Electric Co 84/03/06 MURLEY, T E Region 1, Office of Director 2pp 22673 316 24X Fichs 50-317,84/03/06,840319040B
- --B403190409 "Calvert Cliffs Unit 1, Insp of Steam Generators 11 & 12," final rept EMERY.R 5 Zetec, Inc 83/10/31 127pp 22673 318 24% Fiche 50-317,84/03/06,8403190408
- 8402090024 IE Info Notice 84-09, Rev 1, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24% Fiche 50-000,84/03/07,8402090024
- 8402090028 IE Info Notice 84-18. "Stress Corrosion Cracking in PWR 8ys " Svc list enc! JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc. 118pp 22584 186 24X Fiche 50-000,84/03/07,8402070028
- 8403210006 Forwards IE Insp Repts 50-317/83-35 & 50-318/83-35 on B31212-16 No violations observed MARTIN,T T. Division of Engineering & Technical Programs 84/03/09 LUNDVALLA E Baltimore Qas & Electric Co 2pp 22704 334 24X Fiche 50-317.84/03/09.8403210006
- --B403210D16 IE Insp Repts 50-317/83-35 & 50-318/83-35 on 831212-16 No violations identified Major areas inspected emergency preparedness activities outlined in IE insp procedures & review of emergency response plan COHEN, I. HAWKHURST, J. J. CROCKER, H. W. Region 1. Diffice of Director 84/02/17 6pp 22704 336 24X Fiche 50-317,84/03/09,8403210006
- 840209003i IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl DEYGUNO.R C Director's Office Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Ficha 50-000.84/03/12.8402090031

- 8403260104 Ack receipt of 831201 request for NRC to reconsider issuance of noncompliance per IE Insp Repts 50-317/83-23 & 50-318/83-23 Viglations withdrawn Records will be adjusted attordingly MARTIN.T T Division of Engineering & Technical Programs 84/03/15 LUNDVALL.A E Baltimore Gas & Electric Co 2pp 22737 333 24X Fiche 50-317.84/03/15.8403260104
- --8403260112 Responds to NRC 831103 itr re violations noted in IE Insp Repts 50-317/83-23 & 50-318/83-23 Requests that NRC reconsider issuance of noncompliance Relevant info not discussed w/NRC during exit interview LUNDVALL.A E Baltimore Gas & Electric Co 83/12/01 MARTIN.T T Division of Engineering & Technical Programs 2pp 22787 355 24X Fithe 50-317,84/03/15.8403260104
- B402090043 IE Info Notice 84-j9, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000,84/03/21,8402090043
- B402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Bys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc. 135pp 22733 001 24X Fiche 50-000.84/03/21,8402090044
- R Periodic operating reports & related correspondence
- 8403200003 Monthly operating repts for Feb 1984 W/840315 ltr MEWLEY,E K Baltimore Qas & Electric Co B4/02/29 15pp 22485 273 24X Fiche 50-317,84/02/29,8403200003
- 8403130308 Forwards "Semiannual Effluent Release Rept," for Second Half 1983 & meteorological data for Jul-Sept 1983 & Oct-Dec 1983 LUNDVALL, A E Baltimore Gas & Electric Co 84/03/0! MURLEY.T E Region 1, Office of Director 1p 22607 276 24x Fiche 50-317.84/03/01.8403130305
- --8403130314 "Semiannual Effluent Release Rept," Second Half 1783 * Baltimore Gas & Electric Co B3/12/31 17pp 22607 277 24X Fiche 50-317,84/03/01,8403130305
- --B403130322 "Meteorological Data.Jul-Sept 1983 " * Baltimore Qas & Electric Co 83/09/30 66pp 22607 294 24X Fiche 50-317.B4/03/01.B403130305
- ---B403130334 "Meteorological Data, Dct-Dec 1983 "

 * Baltimore Qas & Electric Co B3/12/31 33pp 22607 327 24% Fiche 50-3(7,84/03/01,8403130305
- 5 Reportable occurrences, LERs & related correspondence
- 8403230125 Forwards Technical Review Rept AEOD/T315, "Events Involving Loss of or Perturbations in Single 120-Volt AC Vital Power Bupply Inverter & Attendant Distribution Bus Which Resulted in Inadvertent Actuations of Safety Sys "
 ASHE.F Reacter Operations Analysis Branch 83/05/24 SEYFRIT.K V Reactor Operations Analysis Branch ip 22741 347 24X
 Fiche 50-317.83/05/24,8403230125
- --8403230128 "Events Involving Loss of or Perturbations in Bingle 120° Volt AC Vital Power Supply Inverter & Attendant Distribution Bus Which Resulted in Inadvertent Actuation of Bafety Sys," technical review rept Rept should be provided to MRR ASHE,F Reactor Operations Analysis Branch 83/03/24 Bpp 22741 348 24% Fiche 50-317,83/05/24.8403230125
- 8403230171 Forwards Technical Review Rept AEOD/T314, "Improper Size of Inlet Piping to Primary Safety Valves "IMERO, E Reactor Operations Analysis Branch 83/05/24 SEYFRITA, V Reactor Operations Analysis Branch 1p, 22759 297 24X Fiche 50-000,83/05/24,8403230171
- --8403230175 "Improper Size of Inlet Piping to Primary Safety Valves." technical review rept. Reduced diameter inlet piping does not represent safety concern IMBRO, E V Director's Office 83/05/24 2pp 22759, 298 24X Fiche 50-000, 83/05/24, 8403230171
- 8403130356 LER 84-002-01 on 840127, reactor tripped & all eight reactor trip breakers opened simultaneously Root cause unknown Independent sys failure evaluation will be performed W/840215 ltr SALYAROS: E. RUSSELL, L. B. Baltimore Gas & Electric Co. 84/02/15 MURLEY. T. E. Region I. Office of Director. 4pp. 22616-254. 24X Fiche 30-317,84/02/15,8403130336

- 8403130299 LER 84-003-00 on 840123, technicians violated Tech Specs by opening containment isolation valves 1-8V-6840-0 & 1-8V-6807-6 during openational maint check New procedure written & Tech Spec amend submitted W/840222 ltr EMELMAN, E M, RUSSELL, L D Baltimore Gas & Electric Co 84/02/22 MURLEY, T E Region 1, Office of Director 4pp 22614 178 24X Fichs 50-317,84/02/22,8403130299
- 8403020343 Forwards SALP rept for Oct 1982 Sept 1983 Maint of low personnel error rate marits continued attention.
 MURLEY, T.E. Region i. Office of Director 84/02/29 LUNDVALL.A E Baltimore Gas & Electris Co. 3pp. 22439 217 24X
 Fiche 30-317.84/02/29.8403020343
- --B403020345 SALP rept for Oct 1982 Sept 1983 * Region i, Office of Director 83/12/12 57pp 22439 220 24X Fiche 50-317,84/02/29,8403020343
- B403130078 Updated LER 82-066/03X-1 on 821026.reactor protective systemmel B trip units for high power, thermal mergin/low pressure & axial shape index bypassed Caused by two oscillators producing noise M/840305 itr
 BYDNOR, R B . RUBSELL. L B Baltimore Gas & Electric Co 84/03/05
 3pp 22614 271. 24X Fische 50-317.84/03/05.8403130098
- 8403130252 Updated LER 81-032/03X-1 on 810420, reactor protective syschannel D bi power thermal margin/low pressure & axial shape index trig units bypassed for maint Caused by oscillator noise in transmitter H/840305 ltr SYDNOR, R B , RUSSELL, L B Baltimore Gas & Electric Co 84/03/05 2pp 22614 175. 24X Ficher 50-317,84/03/05,8403130252
- 8403130279 Updated LER 83-037/03X-1 on 830718, response time of trip circuit breakers 3 & 4 undervoltage trip devices slower than Tach Baper limits Caused by setpoint drift, Satpoints adjusted W/640305 ltr
 SYDNOR, R 8 , RUSSELL, L B Saltimore Oas & Electric Co 84/03/05 2ng 2264 138 24X Fiche 50-317, 84/03/05, 8403130279
- 8403130426 Updated LER 83-049/03X-1 on 830818, auxiliary feedwater pump 11 found inoperable Caused by stage & shaft piece-balance being bound up Parts replaced W/840305 ltr FARRELL, E V. RUSSELL, L B. Baltimore Gas & Electric Co. 84/03/05 2pp 22618 357 24X Fiche 50-317,84/03/05,8403130426
- 8403130295 Updated LER 83-034/03X-1 on 830525,ECC8 pump room cooler 12 taken out of svc Cause unknown Supply piping & strainers disassembled, inspected & cleaned New mechanical preventive maint procedures implemented H/840306 itr.
 BRANT.K T , RUSSELL, L B Baltimore Gas & Electric Co 84/03/06 2pp 22606 048 24X Fiche 50-317.84/03/06.8403130275
- 8403300100 LER 84-004-00 on 840228 charging pumps 12 & 13 removed from svc due to excessive packing leakage Caused by defective packing Evaluation of alternative packing matls underway 4/840328 ltr
 JENNINGS.R T , NAPIER, J J , RUSSELL, L B Baltimore Oas & Electric Co 84/03/28 3pp 22822 001 24% Fiche 50-317,84/03/28, 84/0330100
- DDCKET 50-318 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 2
 F Security, medical, emergency & fire protection plans
- B403140228 Public version of Rev 2 to Emergency Plan Implementing Procedure ERPIP A 2, "Review/Approval " W/831214 ltr & JM Felton 840312 release memo RUSBELL, i B , USI, V Baltimore Gas & Electric Co 83/12/14. 5pp 22637 317 24X Fich # 50-317,83/12/14,8403140228
- 8403:3007: Forwards safeguards info. Info withheld (ref 10CFR73 21)
 JOLLEY, J. R. Baltimore Gas & Electric Co. 84/02/10 CLARK, R. A.
 Operating Reactors Branch 3 10 22643 001 24X
 Fithe 50-317, 84/02/10, 8403150091
- B403020300 Rev 9 to emergency plan implementing Procedure ERPIP-5 O. "Preparation & Control of Emergency Response " W/840227 ltr USI/V , RUSSELL.I. B Baltimore Gas & Electric Co 84/02/14, 10pp 22440 042 24X Fiche 90-317,84/02/14,8403020300
- 8403010301 Responds to util 831024 request for changes to Rev 12 to security plan & Rev 2 to training & qualification plan Changes consistent w/provisions of 10CFR30 54(p) & acceptable MARTIN-T T Division of Engineering & Technical Programs 84/02/23 BOMMAKER,N J Baltimore Cas & Electric Co 4pp. 22432:118 24% Fichs 50-317,84/02/23,8403010301

- 8403150155 Forwards Rev 9 to Emergency Response Plan Implementing Procedure ERPIP-5 0. "Preparation & Control of Emergency Response"
 USIV Baltimore Gas & Electric Co 84/02/27 Director's Of Office of Inspection and Enforcement ip 22642 288 24X Fiche 50-317,84/02/27,8403150155
- 8403020343 Forwards SALP rept for Oct 1982 Bept 1983 Maint of low personnel error rate merits continued attention MURLEY, T E Region 1. Office of Director 84/02/29 LUNDVALL, A Baltimore Gas & Electric Co 3pp 22439 217 24X Fiche 50-317.84/02/29.8403020343 LUNDVALL, A E
- --8403020345 SALP rept for Qct 1982 Sept 1983 * Region 1, Office of Director 63/12/12 Fiche 50-317,84/02/29,8403020343 57pp 22439 220
- ---8403020347 Forwards BALP rept for discussion & review at 831220 meeting in Baltimore.MD Recent performance during 830914 emergency preparedness exercise & two Category III areas will be discussed discussed
 STAROSTECKI, R. Division of Project & Resident Programs 83/
 LUNDVALL, A E Baltimore Qas & Electric Co ip 22439 287
 Fichs 50-317,84/02/29,8403020343 83/12/14
- 8403150110 Rev 9 to Radiological Emergency Plan Implementing Procedure ERRIP-5 2, "Emergency Planning Unit Records " W/840306 ltr UBI.V Baltimore Oas & Electric Co B4/03/06 5pp 22640 209 24X Fiche 30-317,84/03/06,8403150110
- 8403210006 Forwards IE Insp Repts 50-317/83-35 & 50-318/83-35 on B31212-16.No violations observed MARTIN, T Division of Engineering & Technical Programs 84. LUNDVALL, A E Baltimore Gas & Electric Co 2pp 22704 334 Fiche 50-317,84/03/09,8403210006 84/03/09
- --8403210016 IE Insp Repts 50-317/83-35 & 50-318/83-35 on 831212-16 No violations identified Major areas inspected emergency preparedness activities outlined in IE insp procedures & review of emergency response plan
 COMEN.I Region 1. Office of Director. 84/02/1
 22704 336 24X Fiche 50-317.84/03/07.8403210006
- 8403190018 Forwards Calvert Cliffs Instruction CCI-310, "Emergency Operating Procedure Writers Guide," implementation scheduls validation verification plan & training plan per Suppl 1 to NUREO-0737 Bupp 1 to NOMES-U/3/ LUNDVALL.A E Baltimore Gas & Electric Co 84/03/14 MILLER, J R Operating Reactors Branch 3 5pp 22666 001 24X Fiche 50-317,84/03/14,8403190018
- --8403190023 Calvert Cliffs Instruction CCI-310, "Emergency Operating Procedure Writers Guide "Emergency operating plan validation/verification plan & braining plan encl # Baltimore Gas & Electric CO 84/03/14 46pp 22666 006 24X Fichs 50-317,84/03/14,8403190018
- 8403220032 Requests exemption from specific requirements of Section III 0 2 of 100FR50, App R & approval of equivalent separation within Fire Areas 39, 40, 42 & 43 LUNDVALL, A E Baltimore Gas & Electric Co 84/03/14 MILLER, J R Operating Reactors Branch 3 4pp 22714 335 24X Fiche: 30-317, 84/03/14, 8403220052
- 8403200029 Forwards FEMA evaluation of Town of Lusby, Calvert County, MD 84/03/15
- --8403200035 Evaluation of Town of Lusby.Calvert County.MD post-exercise radiological emergency preparedness plans for facilities # Federal Emergency Management Agency 83/10/13 56pp 22497.237 24X Fiche 50-317,84/03/15.8403200029
- 8403220080 Forwards list of local news media available for public ADSWARDOW FORWARDS ISS OF IOCAL News were available for public broadcasting/notification. List used in lieu of FR for exigent or emergency license amends LATHAM.D W Baltimor's Gas & Electric Co 84/03/15 JAFFE.D H Operating Reactors Branch 3. 2pp 22716.263, 24X Fichs: 50-317.84/03/15,8403220080
- B403300182 Forwards safeguards info Info withheld (ref 10CFR73 21) JOLLEY, J R. Baltimore Gas & Electric Co B4/03/21 MARTIN.T T. Division of Engineering & Technical Programs. 1p 22820.044 24X Fiche 50-317.84/03/21.8403300182

J Insurance & indemnity information

- 8403140036 Forwards Endorsements 56 & 57 to NELIA Policy NF-216, Endorsement 45 to MAELU Policy MF-76 & Endorsement 23 to NELIA Policy NS-348 84/03/07 DINITZ, I 22633 124 24X Raltimore Gas & Electric Co GAMMIE, G B Office of State Programs, Director Fiche 50-317,84/03/07.8403140036 Бρρ
- P Operating license stage documents & correspondence
- 8403010117 Partial response to FOIA request for documents by named individuals re repts analyses, studies, procedures & sys for measurement of RCB leakage App B documents placed in PDR App A documents already available in PDR Search continuing FELTON, J M Division of Rules and Records 84/01/25 MADDEN, T Rays, Scholer, Fierman, Hays & Handler 7pp 22480 026 24% Fiche 50-000.84/01/25,8403010187
- --8011070522 Summarizes results of independent evaluations of primary sys leak rate & some considered extensions Extension of specific evaluations to all PMR facilities recommended Draft procedure re evaluations will be submitted by 800715 UDRDAN,E L Division of Reactor Operations Inspections 80/08/21 HDSELEY,N C Division of Reactor Operations Inspections 11pp 22480 266 24X Fiche 50-000,84/01/25.8403010117
- 8403050305 Notification of 840316 meeting w/util & INEL in Bethesda.MD to discuss & resolve outstanding issues re qualification of JAFFE, D H Operating Reactors Branch 3 84/02/27 MILLER, J R Operating Reactors Branch 3 2pp 22501 247 24X Fisher 50-317, 84/02/27, 8403050309
- 840305009B Forwards "Rept on Task 0508B, Pressurizer Relief Valve Discharge Piping Qualification for Calvert Cliffs, Unit 2, "per TMI Item II D 1 LUNDVALL, A E Baltimore Qas & Electric Co 84/02/29 MILLER, J R Operating Reactors Branch 3 3pp 22484 167 24X Fiche 50-318,84/02/29,8403050098
- --8403050100 "Rept on Task 05088; Pressurizer Relief Valve Discharge Piping Qualification for Calvert Cliffs, Unit 2 " Approx mine of 84 existing pipe supports may experience stress PATEL.R B Bechtel Corp 64/02/14 162pp 22484 170 24X Fiche 50-318,84/02/29,8403050098
- --8403050103 Rev 2 to "Pressurizer Safety Valve Operability Rept * Combustion Engineering. Inc. CEN-248(8) R02 84/01/31 22484 332 24X Fiche 50-318.84/02/27.8403050078
- 8403060263 Suppls response to Generic Ltr 83-28, "Required Actions Based on Generic Implications of Balem ATWS Event " Tabular assessment of status & scheduled date for completion of specific items encl Specific rems ener LUNDVALL, A E Maltimore Oas & Electric Co 84/02/29 EISENHUT, D G Division of Licensing 32pp 22517 323 24% Fiche 50-317, 84/02/29,8403060263
- 8403060400 Requests mod of 830316 order requiring installation of noble gas steam effluent monitor by 840301 Mod reflects commitment to install acceptable replacement for existing sys prior to 841231, in lieu of schedule proposed in util 840203 itr LUNDVALL.A E Baltimore Gas & Electric Co 84/03/01 MILLER, J R Operating Reactors Brench 3 2pp 22518 274 24% Fiche 50-317,84/03/01,8403060460
- B4030B00B3 Forwards order modifying implementation date for TMI Action Item II F 1 1, "Noble Gas Bteam Effluent Monitor," per NUREG-0737 Order provides new completion date of 841231 W/o encl
 MILLER.J R Operating Reactors Branch 3 84/03/02 LUNDVALL, A E
 Baltimore Gas & Electric Co 4pp 22584.075 24X
 Fiche 50-317.84/03/02.8403080083
- 8403160040 Advises that work required to resolve concerns in Generic Ltr Bi-14, "Seismic Qualification of Auxiliary Feedwater Sys," completed, per 920106 request Valves successfully Sys." completed.per 920106 request Valves successful qualified by analysis w/o need for mod LUNDVALL.A E Baltimore Cas & Electric Co 84/03/1 Operating Reactors Branch 3 2pp 22655.132 24X Fiche 50-317.84/03/14.8403160040 84/03/14 MILLER. J R
- 8403220014 Informs of recent assignment of EC Wenzinger as chief, Reactor Projects Section IA: effective immediately BTAROSTECKI.R Division of Project & Resident Programs 64/03 LUNDVALL.A E Baltimore Gas & Electric Co 2pp 22712 341 B4/03/15 Fiche 50-317,84/03/15,8403220014

- B40330070 Responds to request for voluntary participation requestions raised in Generic Ltr B3-41 List of type of diesel generator starts & frequency of starting cycles, based on surveillance testing & corrective maint activities, encl LUNDVALL, A E Baltimore Cas & Electric Co B4/03/20 EIBENHUT, D O Division of Licensing 6pp 22822 097 24X Fiche 50-317,84/03/20,8403300070
- G Inspection reports, IE Bulletins & correspondence
- 8403050203 Forwards Structural & Geotechnical Engineering Branch request for add1 info for completion of review of IE Bulletin 80-11. "Masonry Wall Design " Response requested within 60 days of receipt of itr MILLER, J R Deprating Reactors Branch 3 84/02/24 LUNDVALL, A E Baltimore Gas & Electric Co 7pp 22528 155 24X Fiche 50-317,84/02/24,8403050203
- B401170072 IE Info Notice B4-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list enct JURDON, E L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/02/28 Consolidated Edison Co of New York, Inc. 115pp 22909 239 24% Fiche 50-000,84/02/28,8401190072
- 8403020343 Forwards SALP rept for Oct 1982 Sept 1983 Maint of low personnel error rate merits continued attention MURLEY.T E Region 1. Office of Director 84/02/29 LUNDVALL.A E Baltimore Gas & Electric Co 3pp 22439 217 24X Fiche 50-317.84/02/29.8403020343
- --8403020345 BALP rept for Oct 1982 Sept 1983 * Region 1. OPfice of Director 83/12/12 57pp 22439 220 24X fiche 50-317.84/02/29.8403020343
- --B403020346 Forwards AE Lundvail 930916 & 1202 ltrs listing corrective actions retwo Category III areas on valve lineups & fuel oil day tank leval addressed in BALF rept
 LUNDVALL, A E Baltimore Gas & Electric Co B4/01/06 MURLEY, T E Region 1, Office of Director ip 22439 277 24X
 Fiche 50-317,84/02/29,8403020343
- --B403020347 Forwards SALP rept for discussion & review at B31220 meeting in Baltimore.MD Recent performance during B30914 emergency preparedness exercise & two Category III areas will be discussed
 BTARDSTECKI,R Division of Project & Resident Programs B3/12/14
 LUNDVALL,A E Baltimore Qas & Electric Co 1p 22439 287 24X
 Fiche 50-317.84/02/29.8403020343
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl GRACE. J N Division of GA. Safeguards & Inspection Programs (Post B30103) B4/03/02 Consolidated Edison Co of New York. Inc 130pp 22552 327 24X Fiche 50-000.84/03/02.8402090007
- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Bys Valves to Operate" Svc list enci JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases"
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc. 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8402070011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402070011
- 8403150049 Proposes to extend Unit 1 inservice insp interval end date to 870401 to coincide w/Unit 2 to insure both programs updated to same yr & addenda of ASHE Code, Section XI Exemption requested Class III amend fee remitted LUNDVALL, A E Baltimore Gas & Electric Co. 84/03/06 MILLER, J R Operating Reactors Branch 3 2pp 22643 141 24X Fiche 50~317,84/03/06.8403150049
- 8402090024 IE Info Notice 84-07, Rev i, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl UORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc. 118pp 22635 049 24% Fiche 50-000, 84/03/07, 8402090024

- 8402070028 IE Info Notice 84-18. "Stress Corrosion Cracking in PWR Sys " Syc list enci JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New Yark, Inc 118pp 22584 186 24X Fiche 30-000.84/03/07.8402070028
- 8403210006 Forwards IE Insp Repts 50-317/83-35 & 50-318/83-35 on B31212-16 No violations observed MARTIN, T T Division of Engineering & Technical Programs 84/03/07 LUNDVALL, A E Baltimore Gas & Electric Co 2pp 22704 334 24X Fiche 50-317,84/03/09,8403210006
- --B403210016 IE Insp Repts 50-317/B3-35 to 50-318/B3-35 on B31212-16 No violations identified Major areas inspected emergency preparedness activities outlined in IE insp procedures to review of emergency response plan COHEN, I. HAWKURST, J. J. CROCKER, H. Region I. Office of Director B4/02/17 App 22704 336 24X Fiche 50-317,84/03/09, B403210006
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl BEYOUNG, R C Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co. of New York, Inc 134pp 22823 074 24X Fiche 50-000,84/03/12,8402090031
- 8403260104 Ack receipt of 831201 request for NRC to reconsider issuance of noncompliance per IE Insp Repts 50-317/83-23 & 50-318/83-23 Violations withdrawn Records will be adjusted accordingly MARTIN, T T Division of Engineering & Technical Programs 84/03/15 LUNDVALL, A. E. Baltimore Gas & Electric Co. 2pp. 22757 353 24% Fiche 50-317,84/03/15,8403260104
- --8403260112 Responds to NRC 831103 ltr re violations noted in IE Insp Rapts 50-317/83-23 & 50-318/83-23 Requests that NRC reconsider issuance of noncompliance Relevant info not discussed w/NRC during srit interview LUNDVALLA E Baltimore Gas & Electric Co 83/12/01 MARTIN, T Y Division of Engineering & Technical Programs 2pp 22757 355 24X Fiche 50-317, 84/03/15,8403240104
- 8402090043 IE info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103), 84/03/21 Consolidated Edison Co. of New York, Inc. 123pp 22823 829 24X Fiche 50-000.84/03/21,8402090043
- 8402090044 IE Info Notice 84-20. "Svc Life of Relays in Safety-Related Sys " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000.84/03/21.8402090044
- R Periodic operating reports & related correspondence
- 8403200003 Monthly operating repts for Feb 1984 W/840315 ltr BEWLEY, E K Baltimore Oas & Electric Co 84/02/29, 15pp 22685 273 24X Fiche 50-317,84/02/29,8403200003
- 8403130305 Forwards "Semiannual Effluent Release Rept," for Second Half 1983 & Meteorological data for Jul-Sept 1983 & Oct-Dec 1983 LUNDVALL.A E Baltimore Gas & Electric Co 84/03/01 MURLEY,T E Region 1, Office of Director ip 22607.276 24X Fiche 50-317,84/03/01.8403130305.
- --8403130314 "Semiannual Effluent Release Rept." Second Half 1983 * Baltimore Gas & Electric Co 83/12/31 17pp 22607 277 24X Fiche 50-317,84/03/01,8403130305.
- --8403130322 "Meteorological Data, Jul-Sept 1983 "
 # Baltimore Cas & Electric Co 83/09/30 66pp 22607:294 24%
 Fiche 50-317,84/03/01,8403130305
- --8403130334 "Meteorological Data, Oct-Dec 1783 " * Baltimore Cas & Electric Co 83/12/31 33pp 22607.327 24X Ficha 50-317, 84/03/01, 8403130305
- B Reportable occurrences, LERs & related correspondence
- 8403230125 Forwards Technical Review Rept AEOD/T315, "Events Involving Loss of or Perturbations in Single 120-Volt AC Vital Rower Supply Inverter & Attendant Distribution Bus Which Resulted in Inadvertent Actuations of Safety Sys "
 ABHE, F. Reactor Operations Analysis Branch. 83/05/24 BEYFRIT, K. V. Reactor Operations Analysis Branch. 1p 22741.347 24X
 Fiche 50-317,83/05/24.8403230125

- --8403230128 "Events Involving Loss of or Perturbations in Single 120-Voit AC Vital Power Supply Inverter & Attendant Distribution Bus Which Resulted in Inadvertent Actuation of Safety Sys," technical review rept Rept should be provided to MRR ASHE,F Reactor Operations Analysis Branch 83/05/24 Bpp 22741 348 24X Fichs 50-317,83/05/24,8403230125
- 8403230171 Forwards Technical Review Rept AEOD/T314, "Improper Size of Inlet Piping to Primary Safety Valves "
 IMBRO,E Reactor Operations Analysis Branch 83/05/24
 SEYFRIT, K V Reactor Operations Analysis Branch ip 22759 297
 24X Fiche 50-000.83/05/24,8403230171
- ---8403230175 "Improper Size of Inlet Piping to Primary Safety Valves," technical review rept Reduced diameter inlet piping does not represent Safety concern IMBRO.E V Director's Office 83/05/24 2pp 22759 298 24X Fiche 50
- 8311020249 Forwards engineering evaluation rept re PORV actuation resulting in safety injection actuation IMBRO,E V Reactor Operations Analysis Branch 83/07/08 SEYFRIT.K V. Reactor Operations Analysis Branch ip 22789 318 24X Fiche 50-318,83/09/08,8311020249
- --8311020253 "PORV Actuation Resulting in Safety Injection Actuation "
 IMBRO, E V Reactor Operations Analysis Branch 83/09/08. 7pp
 22789 319 24X Ficha 50-318,83/09/08.8311020249
- 8403020343 Forwards SALP rept for Oct 1982 Sept 1983 Maint of low personnel error rate merits continued attention MURLEY.T E. Region 1. Office of Director 84/02/29 LUNDVALL, A 8 Baltimore Gas & Electric Co 3pp 22439 217 24X Fiche 50-317.84/02/29,8403020343
- ---8403020345 SALP rept for Oct 1982 Sept 1983 * Region 1, Office of Director 63/12/12 57pp 22439 220 24X Fiche 50-317,84/02/29,8403020343
- 8403060109 LER 84-001-00 on 831005,1220 & 840203,ECC8 pump room ventilation sys exhaust fan discharge damper 21 would not open Caused by air supply to exhaust fan discharge damper isolated Air restored & sys returned to syc W/840301 ltr JUNGE, M , RUSSELL, L B Baltimore Gas & Electric Co 84/03/01 5pp 22518:305 24X Fiche 50-318,84/03/01,8403060109
- 8403130039 Updated LER 82-054/03X-1 on B21124, power lost to 24 4-kV bus, resulting in loss of saltwater pump 22 & low pressure safety injection pump 22 Caused by cracked printed circuit board No corrective actions planned W/840305 ltr BASBO, L. F. RUSBELL, L. B. Baltimore Gas & Electric Co. 84/03/05 2pp 22608.081 24X Fichs 50-518.84/03/05, B403130037
- B4031300B1 Updated LER 81-025/03X-1 on 810430 & 0514, reactor protective sys Channel B trip units 1,3,7,8 & 10 bypassed to investigate problem w/T-hot Channel B Caused by failure of two oscillators in transmitter circuitry, W/840305 ltr SYDNOR, R B , RUSSELL, L B Baltimore Oas & Electric Co 84/03/05, 2pp 22614 302 24X Fiche 50-318,84/03/05,8403130081
- 8403130413 Updated LER 63-036/03X-1 on 830719, response time for reactor trip circuit breakers 4 & 7 undervoltage devices indicated alower than Tech Spèc limits Caused by setpoint drift & worn front frame assembly mechanisms W/840305 ltr SYDNOR, R B , RUSSELL, L B Baltimore Cas & Electric Co 84/03/05 2pp. 22613 088 24X Fiche, 50-318, 84/03/05,8403130413
- B403130450 Updated LER 81-030/03X-1 on B10305, discovered temp transmitter 122HB out of tolerance in nonconservative direction. Caused two oscillators producing noise on transmitter output Transmitter replaced W/840305 ltr BYDNOR, R. B., RUSSELL, L B Baltimore Qes & Electric Co 84/03/05. 2pp. 22813 231 24X Fiche. 50-316. 84/03/05, 8403130450
- DOCKET 50-320 THREE MILE ISLAND NUCLEAR STATION, UNIT 2
 F. Becurity, medical, emergency & fire protection plans
- 8403090264 Public version of Rev 1-00 to Emergency Plan 4000-PLN-1300.01 H/JM Felton 840307 release memo BARTON, J M., CLARK, P. R. Oeneral Public Utilities - OPU Service Corp 84/02/01, 300pp 22894 005 24X Fiche 50-320,84/02/01,8403090264
- 8403130467 Forwards IE Insp Rept 50-320/84-02 on 840109-0213 No violations observed.

 BARRETT,L.H. TMI Program Office. 84/02/27 KAN9A:8 K General Public Utilities GPU Service Corp 3pp 22613 219 24X Fiche.50-320:84/02/27.8403130467

- --B40313047; IE Insp Rept 50-320/84-02 on 840109-0213 No violations identified Major areas inspected LERs previous insp findings radioactive mat1 shipments health physics & environ review & reactor bldg entries WIEHE J. MOSLAK.T. BELL. J TMI Program Office 84/02/22 7pp 22613 221 24X Fiche 50-320.84/02/27.8403130467
- 8403050151 Revised emergency implementing procedures, including Procedure 1054 1 re unusual event, Procedure 1054 2 re alert, Procedure 1054 3 re site emergency & Procedure 1054 4 re general emergency BAADY, J A General Public Utilities GPU Service Corp 84/02/28 113pp 22484 054 24X Fiche 50-320.84/02/28 8403050151
- B4030B017B Rev 5 to Emergency Plan Implementing Procedure 1054 3, "Bite Emergency"
 BRADY, J A : MILLER, A General Public Utilities GPU Service Corp B4/02/28 29pp 22559 114 24X Fiche 50-320,84/02/28,840308017B
- 8403060133 Forwards Rev 19 to security plan Rev restores portions of plan wording re TMI-2 security features modified in Revs 17 & 18 Rev withheld (ref 10CFR73 21)
 HUKILL, H D General Public Utilities GPU Service Corp 84/02/29
 DENTON, H R Diffice of Nuclear Reactor Regulation, Director 2pg 22506 332 24X Fiche 50-289,84/02/29,8403040133
- 8403130286 Informs that annual emergency exercise scheduled for 841003, per 10CFR50, App E requirements Limited participation planned by Commonwealth of PA, five risk countries & local municipalities
 HUKILL, H D General Public Utilities GPU Service Corp 84/03/08
 Office of Nuclear Reactor Regulation, Director 1p 22605 180
 24X Fiche 30-289, 84/03/08,8403130286
- 8403150118 Revs to Emergency Preparedness Administrative Procedure 1056. "Administration of TMI-2 Onsite & Offsite Emergency Duty Roster"

 REAVER.JR, ORANGE.GJ General Public Utilities GPU Service Corp 84/03/08 27pp 22639 305 24X Fiche 50-320,84/03/08,8403150118
- 8403190243 Notification of 840418 workshop in King of Prussia.PA to discuss lessons learned from recent App & first protection safe shutdown insp & topics described in IE Info Notice 84-03 Agenda for workshop encl MURLEY,TE Region 1. Office of Director 84/03/09 0'TOOLE.JD Consolidated Edison Co of New York, inc HARRINGTON,WD Boston Edison Co MURPHY,WP Yermont Yankee Nuclear Power Corp 35pp 22672 062 24X Fiche 50-000.84/03/09.8403190243
- 8403210047 Forwards IE Insp Rept 50-320/84-01 on 840109-12 & 17-20 No violations noted MARTIN.T T Division of Engineering & Technical Programs KANDA, B K General Public Utilities GPU Service Corp 2pp 22705 305 24X Fiche 50-320, 84/03/09, 8403210047
- --8403210054 IE Insp Rept 50-320/84-01 on 840109-12 & 17-20 No violations noted Major areas inspected IE Insp Procedures 82203, 82205, 82210 & 82211 re notifications & communications, shift staffing, audits & smergency work protection, respectively TERC, N M , WOLTNER, E , GORDON, C Z Region 1, Office of Director 84/02/16 4pp 22705 307 24X Ficher 50-320,84/03/09,8403910047
- 8403280243 Forwards list of mods to fire protection sys, based on review of 820615 fire hazards analysis Schedule for corrective actions for items not yet addressed requested within 30 days
 SNYDER, B.J. THI Program Office 84/03/13 KANOA, B.K. Qeneral Public Utilities GPU Service Corp. 4pp. 22808 202 24X
 Fiche 50-320, 84/03/13, 8403280243
- 8403270202 Forwards IE Safeguards Insp Rept 50-320/84-03 on 840213-i7
 No violations noted
 MARTIN.T T Division of Engineering & Technical Programs
 KANGA, B K General Public Utilities OPU Service Corp
 22801 001 24% Fiche 50-320.84/03/15.8403270202
- --B403270205 IE Bafeguards Insp Rept 50-320/84-03 on 840213-17 No violations noted Major areas inspected security organization, security program audit testing & maint, physical barriers, detection aids & communications
 DUNLAP, J M , JOYNER, J H Region 1, Office of Director, B4/03/15
 5pp 28801 003 24X Fiche. 50-320,84/03/15,8403290202
- 8403270073 Rev i to Emergency Plan Implementing Procedure 1054 21, "Emergency Repair/Operations" BRADY, J A, KOVACH, D. GRANGE, O General Public Utilities GPU Bervice Corp 84/03/20 4pp 22766 166 24X Fiche, 50-320, 84/03/20,8403270073

C Adjudicatory correspondence

- B403070370 Commission determination statement withholding transcript of closed B30921 meeting re-motion to quash Hartman subpoenas CHILK.S J. Office of the Secretary of the Commission 84/02/27 Public Document Branch 1p 22567 201 24X Fichs 50-320.84/02/27.800970370
- 8403160005 Advises that time for Commission to review Director's Decision DD-84-4 expired Commission declined review Decision became final agency action on 840313 CMILK/S J Office of the Secretary of the Commission 84/03/14 LEWIG, M Lewis, M 1p 22655 197 24X Fiche 50-320, 84/03/14, 8403160005
- 8403200191 Responds to 831208 & 18 ltrs re possibility of restart decision prior to further evidentiary hearings on mpt competence & integrity ASLAB decision will be considered by Commission upon issuance PALADINON J Commissioners 84/03/19 BPECTER, A Senate 2pp 22498 003 244 Fichs 50-289, 84/03/19, 8403200191
- ---8403200198 Responds to B40124 ltr & 831216 position statement re funding of cleanup prerequisite for restart Commission does not have legal authority to condition restart of TMI-1 on funding solution for cleanup of TMI-2 PALLADINO, N J Commissioners B4/03/19 THORNBURCH, R Fennsylvania, Commonwealth of, 3pp 22698.024 24X Fiche 50-289,84/03/19,8403200191

H General correspondence

- 8403060083 Requests that D Kennedy replace D Hess on mailing list for TMI matls KENNEDY.D Pennsylvania, Commonwealth of, B4/03/01 SNYDER, B J TMI Program Office ip 22517 014 24X Fiche: 50-320, 84/03/01, B403060083
- B403190056 Responds to constituent RE Burks 840123 request for info re accident Forwards "Population Dose & Health Impact of Accident at TM1 Station," (NUREG-0558) W/o enci DIRCKS,W J Office of the Executive Director for Operations B4/03/05 HEFLIN,H Senate 3pp 22681 317 24X Fiche 50-320,84/03/05,8403190056
- --8403190060 Requests comments on encl constituent RE Burks 840123 request for NRC rept on TMI accident HEFLIN.H Senate 84/02/10 KAMMERER.C Office of Congressional Affairs 3pp 22681 320 24X Fiche 50-320.84/03/08.8403190054
- B4032i0141 Requests deletion of RC Arnold, former president of Ganeral Public Utils, from NRC mailings * General Public Utilities - CPU Service Corp 84/03/16 NRC -No Detailed Affiliation Given 2pp 22707.280 24X Fiche 50-289.84/03/16.8403210141

J Insurance & indemnity information

- 8403280010 Forwards Endorsements 72 & 73 to NELIA Policy NF-220 & Endorsements 62 & 63 to MAELU Policy MF-73 GERETY, HF General Public Utilities GPU Service Corp 84/03/22 SALTIMAN.J Office of Nuclear Reactor Regulation, Director Spp 22777 074 24X Fiche 50-269,84/03/22,8403280010
- P Operating license stage documents & correspondence
- 8403200304 Forwards R Myers 820111 memo re statements made at 818221 meeting on info flow during TMI accident DIRCKS.W J Office of the Executive Director for Operations 82/01/13 PALLADING, OILINSKY, BRADFORD Commissioners Opp 22709 170 24X Fiche 50-320,82/01/13,8403200304
- E403200341 Forwards H Meyer 830308 memo re possibility of intentionally or willfully withholding info during accident NRC statements inconsistent DIRCKS, W J Office of the Executive Director for Operations 92/03/11 PALLADINO, GILINBKY, BRADFORD Commissioners 5pp. 22709 119 24X Fiche 50~320,82/03/11,8403200341.
- 8403080393 Forwards DL Jensen 830517 ltr to N Palladino re DGU investigation of TMI Document subj to Voigt 830526 FOIA request & 830919 appeal Document should be placed in PDR SHEENEY, M Office of the General Counsel 84/01/27 PDOL, M J NRC NO Detailed Affiliation Given ip 22567:354 24X Fiche: 30-287-84/01/27, 8403080393

- --8403080425 Responds to 830411 ltr re TMI-1 restart & DDJ investigation into allegations re mgt competence Investigation being pursued diligently but will not be completed by requested date

 JENSEN, D L. Justice. Dept of 83/05/17 PALLADINO, N J. Commissioners 4pp 22567 355 24X Fiche 50-289,84/01/27,8403080393
- 8403070053 Responds to 831214 ltr suggesting Commission refuse to restart Unit 1 until funding for Unit 2 cleanup in place Commission does not believe that Unit 1 restart & Unit 2 cleanup should be tied together PALLADING,N J Commissioners 84/02/08 NDRRIS,A E Advisory Council for Decontamination of TMI Unit 2 1p 22563 178 24X Fiche 50-289,84/02/08,8403070053
- 8403020318 Forwards annual update to "Recovery Program Sys Description, Auxiliary Bidg Emergency Liquid Cleanup Sys (EPICOR-II) "Chemical addition section no longer utilized in EPICOR II Sys KANOA.B K Ceneral Public Utilities OPU Service Corp 84/02/24 SYYDEA, B J TMI Program Office ip 22439 315 24X Fiche 50-320,84/02/24,8403020318
- --8403020383 "Recovery Program Sys Description, Auxiliary Bldg Emergency Liquid Cleanup Bys (EPICOR-II)" * Opneral Public Utilities - QPU Service Corp 84/02/29 81pp 22439 316 24X Fiche 50-320,84/02/24,8403020318
- 8403130159 Comments on EIB draft suppl re occupational radiation dose at TMI-2 Alternatives 1 & 2 unacceptable Alternative 3 acceptable Assed on reducing occupational exposure w/o delaying fuel removal HAGER, 8 W Maryland, State of 84/02/29 SNYDER, 8 J TMI Program Office 17pp 22608 147 24X Fiche 50-320,84/02/29,8403130159
- 8403020277 Submits comment on review of draft suppl to programmatic EIS re decontamination & disposal of radwaste resulting from 79028 accident at facility BLANCHARD.D Interior. Dept of 84/03/01 BNYDER, B J TMI Program Diffice ip 22440 040 24X Fiche 50-320,84/03/01. B403020277
- 8403080410 Responds to 840214 request for 30-day extension to comment on draft suppl to programmatic EIS Due date for comments extended to 840402 DENTON.H R Office of Nuclear Reactor Regulation, Director 84/03/01 MORRIS.A E Lancaster, PA 2pp 22581 328 24X Fithe: 50-320.84/03/01.8403080410
- --B4030B0412 Requests 30-day extension to comment on programmatic EI8 update
 HORRIB, A E Advisory Council for Decontamination of TMI Unit 2
 B4/02/14 PALLADING.N J Commissioners 2pp 22581 327 24X
 Fiche 50-320, 84/03/01.84030B0410
- 8403120261 Orants 840214 request for 30-day extension to submit comments on draft suppl to preliminary EIS Comments now required by 840402 Announcement of extension will be published in FR
 DENTON.H R. Office of Nuclear Reactor Regulation, Director 84/03/01 HORRIS, A E Advisory Council for Decontamination of TMI Unit 2 3pp 22619 140 24X Fiche 50-320,84/03/01,8403120261
- 8403080267 Forwards updated major milestone schedule for TMI-2 cleanup for 1984, in response to 840131 request KANGA.B K General Public Utilities - GPU Service Corp 84/03/02 SNYDER.B J TMI Program Office 7pp 22557 093 24X Fiche 50-320,84/03/02:8403080267
- 8403160041 Comments on NRC review of pyrophoric reactions of zirconium Experiments described in HR Denton 840R17 1tr may lead to uninformed or false conclusions GULBRANSEN,E A Pittsburgh, Univ of, Pittsburgh, PA 84/03/02 LEMIB.M Lewis, M ip. 22655 128 24X Fiche 50-320,84/03/02, 8403160041
- --B403160049 Submits petition for appeal of NRR Director's Decision DD-B4-4 on 840217 denying request to postpone headlift Decision ignores obvious dangers LEWIB.M I Lewis. M B4/03/11 FALLADINO. GILINSKY. ROBERTS Commissioners. 3pp 22455 127 24X Fiche 50-320,84/03/02, B403160041.
- 8403150311 Comments on 831230 ltr providing plan & schedule for recovering Tech Spec required sys & components Plan acceptable Requests notice on quarterly basis of status of progress in reinstating Tech Spec surveillance requirements SNYDER.B J TMI Program Office 84/03/07, KANOA,B K General Public Utilities OPU Service Corp 2pp 22649 314 24X Fiche 50-320.84/03/07,8403150311

- 8403130428 Forwards Rev 5 to "SER for Removal of TMI-2 Reactor Vessel Head" for review & approval KANGA.B K General Public Utilities GPU Service Corp 84/03/09 SNYDER, B J TMI Program Office 2pp 22608 303 24X Ficha:50-320.84/03/09,8403130428
- ---8403130439 Rev 5 to "EER for Removal of TMI-2 Reactor Vessel Head"

 * General Public Utilities GPU Service Corp 15737-2-607-102

 R05 84/02/29 181pp 22608 305 24X Fiche 50-320, 84/03/09, 8403130428
- 8403220175 Responds to 840201 request for info re sources of internal QPU funds available for facility cleanup in 1984 Financial forecast for 1984-86 re spending plans & cash generation will be provided GRAHAN, J Q General Public Utilities GPU Service Carp 84/03/09 BALTZMAN, J Office of Stats Programs, Director 3pp 22717 046 24% Fiche 50-320,84/03/09,8403220195
- 8403230240 Advises that since facility has average coolant temp of less than 200 F & is at zero power, cold Shutdown requirements of final rule on licensed operating staffing applicable SHYDER, B J TMI Program Office 84/03/09 KANGA.B K General Public Utilities GPU Service Corp 3pp 22759 275 24X Fiche 50-320.84/03/09,8403230240
- 8403200201 Forwards annual update to sys description for solid waste staging facility Primary mod deletes ref to completed EPICOR-II venting & shipping program Remaining changes reflect current plant status KANOA.B K Oeneral Public Utilities OPU Service Corp 84/03/15 SNYDER, B J TMI Program Office 1p 22678 263 24X Fiche 50-320,84/03/15,8403200201
- --B403200208 Annual update to "Recovery Program Bolid Waste Staging Facility Sys Description "

 * General Public Utilities GPU Service Corp B4/03/15 20pp 22698.264 24X Fiche 50-320.84/03/15.8403200201
- B403270123 Forwards application for amend to License DPR-73, consisting of Tech Spec Change Request 45, increasing max allowable boron concentration in RCB to å.000 ppm KINTER, E E General Public Utilities GPU Service Corp 84/03/22 SNYDER, B J THI Program Office ip 22774 140 24X Fiche. 50-320, 84/03/22, 8403270123
- --8403270127 Application for amend to License DPR-73, consisting of Tech Spec Change Request 45, increasing max allowable boron concentration in RCS to 6,000 ppm

 * Qeneral Public Utilities OPU Service Corp 84/03/22 4pp 22774 141 24X Fichs 50-320,84/03/22,8403270123
- --8403270127 Proposed Tech Specs increasing max allowable boron concentration in RCB to 6,000 ppm
 * Oeneral Public Utilities GPU Service Corp 84/03/22 ip 22774.145 24X Fiche 50~320,84/03/22,8403270123
- 8403270210 Application to amend License DPR-73, revising Tach Specs re boron concentration upper limit KANGA:B K General Public Utilities - GPU Service Corp 84/03/22 BARRETT,L.H TMI Program Office 2pp 22770.277 24X Ficha: 50-320,84/03/22.8403270210
- ---8403270212 Proposed Tech Spec changes re boron concentration upper limit. * General Public Utilities -- GPU Service Corp. 84/03/22, 3pp 22770 279. 24X Fiche 50-320,84/03/22,8403270210
- 8403300031 Forwards general & specific comments on Suppl 1 to programmatic EIS Statement should be added to Table 2 i. "Licansæe Goals for Dose Rate Reduction" to Indicate goals are for target values only.

 KANQA: B.K. General Public Utilities OPU Service Corp 84/03/26 BNVDER; B.J TMI Program Office. 12pp. 22821 327 24X Fiche: 50-320: 84/03/26: 8403300031.
- G Inspection reports: IE Bulletins & correspondence
- 8403080408 F01A request for repts of insp carried out under Condition 2 of Nuclear Energy Liability policies for facilities GALBOYAS, C.D. Affiliation Not Assigned 84/02/07 Region 5, 8403080408.

- B403080419 Responds to FOIA request for repts of insp tarried out under Condition 2 to Nuclear Energy Liability policies for facilities NRC does not have repts
 FELTON, J M Division of Rules and Records 84/02/22 CALSOYAS, C D Affiliation Not Assigned 1p 22567 345 24X
 Fiche 50-000.84/02/22,8403080419
- B403070036 Responds to IE Bulletin 83-07, "Apparently Fraudulent Products Bold by Ray Miller.Inc "Companies supplying matls or sycs to facility listed Ray Miller matl not installed in safety-related sys at facility KANGA.B K General Public Utilities - GPU Service Corp 84/02/23 MURLEY.T E Region 1, Office of Director 11pp 22576 038 24X Fichs 30-320,84/02/23,8403090036
- 8403130467 Forwards IE Insp Rept 50-320/84-02 on 840109-0213 No violations observed BARRETT,L H TMI Program Office 84/02/27 KANGA,D K General Public Utilities + GPU Service Corp 3pp 22613 217 24X Fiche 50-320,84/02/27,8403130467
- --8403130471 IE Insp Rept 50-320/84-02 on 840109-0213 No violations identified Major areas inspected LERs, previous insp findings, radioactive mati shipments, health physics & environ review & reactor bldg entries
 WIEHE, J. MUSLAK, T., BELL, J. TMI Program Office 84/02/22 7pp 22613 221 24% Fiche 50-320.84/02/27,8403130467
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl.
 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22909 239 24X Fiche 50-000,84/02/28,8401190072
- B403150125 Discusses IE insp on 831220-21 & forwards notice of violation
 MARTIN,T T Division of Engineering & Technical Programs B4/02/28
 EISENBUD.M New York Univ Medical Center, New York, NY 2pp
 22640-317 24X Fiche 50-320,84/02/28,8403150125
- --8403150132 Notice of violation from insp on 831220-21 Violation noted 5 8 mCi Ce-144 source transported to & possessed at facility not authorized by specific or general license * Region 1. Office of Director 84/02/28 ip 22640 319 24X Fiche 50-320,84/02/28,8403150125
- --8403190135 Discusses 831219 unauthorized use of 5 B mC1 Ce-144 source to aid in calibr of facility phoswitch detector Util personnel unaware of math until after source unloaded THONUS, L THI Program Office 83/12/23 GLENN, J NRC No Detailed Affiliation Given ip 22640 320 24X Fiche 50-320,84/02/28,8403150125
- 8402090007 IE Info Notice B4-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE, J M Division of GA, Bafeguards & Inspection Programs (Post B30103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fichs 50-000,84/03/02.8402090007
- B402090008 IE Info Notice B4-14. "Failure of Automatic Sprinkler Sys Valves to Operate " Syc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consulidated Edison Co of New York, Inc 122pp 22553 098. 24% Fiche 50-000.84/03/02, 8402090008
- B402090007 IE Info Notice B4-15: "Reporting of Radiological Releases"
 Bvc list encl
 JURDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) B4/03/02 Consulidated Edison Co. of New
 York, Inc. 119pp 22553 217 24X Fiche 30-000.84/03/02, 8402070009
- 8403120101 Ack receipt of 840201 ltr informing NRC of results of analyses of split sample of submerged demineralizer sys effluents per IE Insp Rept 50-320/83-18
 MARTIN, T, T Division of Engineering & Technical Programs. 84/03/02 KANOA, B K General Public Utilities GPU Service Corp 2pp 22588, 226 24X Fiche 50-320,84/03/02,8403120101
- --8403120102 Responds to NRC 831229 ltr & forwards results of analyses of split sample of submerged demineralizer sys, per IE Insp Rapt 50-320/83-18 Table encl KANGA.B & General Public Utilities GPU Service Corp. 84/02/01 MURLEY.T E. Region 1. Office of Director Jpp 22588 228 24X Fiche 50-320,84/03/02,8403120101
- 8402070011 IE Info Notice 84-17. "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp." Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co. of New York, Inc. 117pp 22553 336 24X Fiche 50-000,84/03/05,8402070011

- B402090024 IE Info Notice B4-09.Rev 1, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/07 Consolidated Edison Co. of New York. Inc. 119pp 22635 049 24X Fiche 50-000.84/03/07.8402090024
- 8402070028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR 9ys " Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fishe 50-000,84/03/07,8402070028
- 8403210047 Forwards IE Insp Rept 50-320/84-01 on 840109-12 & 17-20 No violations noted MARTIN.* T Division of Engineering & Technical Programs 84/03/07 KANOA, B K General Public Utilities GRU Service Corp 29p 22705 305 24X Fiche 50-320.84/03/09.8403210047
- --B403210054 1E Insp Rept 50-320/B4-01 on 840109-12 & 17-20 No violations noted Major areas inspected IE Insp Procedures 82203, 82205, 82215 re notifications & communications, shift staffing, audits & emergency work protection, respectively TERC, N M , WOLTNER, E , GORBON, C Z Region 1, Office of Director. 84/02/16 4pp 22705 307 24X Fiche 50-320, 84/03/09, 8403210047
- 8402070031 JE Bulletin 84-02. "Failures of GE Type HFA Relays in Use in Class IE Safety 8ys " Syc list encl
 DEYOUND: R C Director's Office: Office of Inspection and
 Enforcement B4703/12 Consolidated Edison Co. of New York
- B403190219 Ack receipt of 840223 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-320/83-14
 MARTIN.T T Division of Engineering & Technical Programs. 84/03/13
 KANOA.B K General Public Utilities 0PU Service Corp 1p
 22671 120 24x Fiche 50-320.84/03/13.8403190215
- --8403190217 Responds to NRC 840125 itr re violations noted in IE Insp Rept 50-320/83-14 Corrective actions effort made to ensure that lead engineer performing design work will not perform verification to procedure modified KANSA:B K General Public Utilities - GPU Service Corp 84/02/23 MURLEY,T E Region 1. Office of Director 2pp. 22671 121 24X Fiche 50-320,84/03/13,8403190215
- B403290202 Forwards IE Safeguards Insp Rept 50-320/84-03 on 840213-17 No violations noted MARTIN,T T Division of Engineering & Technical Programs 84/03/15 KANOA,B K General Public Utilities - GPU Service Corp 2pp 22801-001 24X Fiche 50-320.84/03/15.8403290202
- --8403270205 IE Safeguards Insp Rept 50-320/84-03 on 840213-17 No violations noted Major areas inspected security organization.security program audit.testing & maint.physical barriers, detection aids & communications
 DUNLAP.J M. JOYNER.J. H. Region 1. Office of Director 84/03/15
 5pp 22801 003 24X Fiche 50-320.84/03/15.8403290202
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PMR Reactor Cavities " Byo list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103), 84/03/21 Consolidated Edison Co of New York, Inc. 123pp 22823 229 24% Fiche 50-000.84/03/21.8402090043
- 8402090044 IE Info Notice 84-20, "Syr Life of Relays in Safety-Related Sys" Syr list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc. 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044
- R Periodic operating reports & related correspondence
- B403120334 Forwards TMI Program Oft weekly status rapt for wk of B4021B-25 BARRETT, L H TMI Program Office 84/02/27 DENTON, H R Office of Nuclear Reactor Regulation, Director BNYDER, B. J. TMI Program Office 10pp 22594 343, 24X Fiche 50-320.84/02/27.8403120334.
- 8403210059 Forwards "Aircraft Movements at Harrisburg Intl Airport, 1983" & "Number of Personnel & Man Rems by Work & Job Function, 1983 "
 KANGA, B K. General Public Utilities OPU Service Corp. 84/02/28
 MURLEY, T E. Region 1, Office of Director 2pp. 22704: 950 24X
 Fiche 50-320, 84/02/28, 8403210059
- --8403210064 "Aircraft Hovements at Harrisburg Intl Airport, 1983 "

 * General Public Utilities GPU Service Corp 83/12/31 ip.
 22704:352 24X Fiche 50-320,84/02/28,8403210059

- --840321007; "Number of Personnel & Man Rems by Work & Job Function, 1983 "

 * General Public Utilities - GPU Service Corp 84/02/16 ip 22704 333 24X Fiche 50-320.84/02/28.8403210059
- B403130475 Forwards "Quarterly Dose Assessment Rept, Fourth Quarter 1983" & "Semiannual Radioactive Effluent Release Rept, Jul-Dec 1983" KANGA.B K General Public Utilities - GPU Service Corp B4/02/29 MURLEY.T E Region 1. Office of Director 2pp 22614 064 24X Fiche 50-320.84/02/29,8403130475
- --8403130483 "Guarterly Dose Assessment Rept.Fourth Quarter 1983 "
 # General Public Utilities GPU Service Corp 83/12/31 4pp 22614 066 24X Fiche 50-320.84/02/29.8403130475
- --8403130489 "Semiannual Radioactive Effluent Release Rept.Jul-Dec 1983 "
 * General Public Utilities GPU Service Corp 83/12/31 25pp,
 22614 070 24X Fiche 50-320,84/02/29,8403130475
- B403210138 Forwards personnel exposure rept for 1783, including total count of personnel manitored & number of personnel in each whole body exposure range HUKILL, H D General Public Utilities GPU Service Corp 84/03/01 MURLEY, T E Region 1. Office of Director ip 22707 088 24X Fiche 50-287,84/03/01,8403210138
- --8403210146 Personnel exposure rept for 1983 * General Public Utilities - GPU Service Corp 83/12/31 2pp 22707 089 24X Fiche 50-289,84/03/01.8403210138
- 8403120233 Forwards TMI Program Ofc weekly status rept for wk of 840224-0303 BARRETT, L H TMI Program Office 84/03/05 DENTON, H R Office of Nuclear Reactor Regulation, Director SNYDER, B J TMI Program Office 12pp 22615 342 24X Fiche 50-320,84/03/05,8403120253
- 9 Reportable occurrences, LERs & related correspondence
- 8403060426 Forwards Figures 8-8 & 8-9 inadvertently omitted from 840208 response to NRC 840104-06 audit questions re auxiliary bldg underpinning MCONEY, J A Consumers Power Co 84/02/27 HARRIBON, J J Region 3, Office of Director 6pp 22518 194 24% Fiche 80-320,84/02/27, 8403060426
- 8403260233 Forwards summary list of deficiencies identified per 10CFR50 55(e).Part 21 & potential generic itr repts for comments BTAROBTECKI.R Division of Project & Resident Programs Region 1. Office of Director 7pp 22756 065 24X Fiche 50-000.84/02/28.8403260233
- 8403060103 PNO-TMI-84-002 licenses pleaded guilty to one count of using incorrect procedure to determine RCS water inventory & noic contenders on six of remaining 10 counts, subj to final acceptance by court on 840229 FABANO, A. JARRETT, L. TMI Program Office 84/02/29 ip 22517 018 24X Fiche 50-320,84/02/29,8403060103
- B403050110 PND-TMI-84-003 on B40227, load test of reactor bldg polar crane scheduled Load test will qualify crane to lift 170 ton reactor vessel head NRC plans to continue monitoring events MOSLAK,T , QASANO,A , BARRETT,L TMI Program Office, 84/02/27 ip 22518 310 24X Fiche 50-320,84/02/27,8403060110
- 8403060144 PNO-TMI-84-002A on B40227, court accepted licenses plea of guilty to one count of using incorrect procedure to determine RCS water inventory & plea of nolo contendere on six of remaining 10 counts.

 FASANO, A. BARRETT, L. TMI Program Office 84/02/29 1p 22513 350. 24X Fiche 50-320,84/02/29,8403060144
- 8403060435 PNO-TMI-84-003A on 840227, qualification load test of reactor bldg polar crans completed Load test qualified crans to lift 170 ton reactor vessel head scheduled for summer MOSLAK, T. FABAND, A. BARRETT, L. TMI Program Office 84/03/01 1p 22511 362. 24X Fichs 50-320,84/03/01,8403060435.
- 8403280006 LER 84-002-00 on 840216, determined that load test for polar crane procedure failed to incorporate adequate isolation requirements for nonborated water sources Tests from 840213-16 conducted in unanalyzed condition W/840314 ltr. GOULD.T.L. KANOA.B K General Public Utilities GPU Service Corp. 84403/14 MRLEY.T.E. Region 1. Office of Director. 2pp. 22777:171 24X Fiche 50-320,84/03/14.84032800006

- B403300074 PN8-I-84-003 on 840324, male phoned Jersey Central Power & Light Customer 8vc Ctr & notified that FFA will start demolishing plants Oyster Creek implemented emergency contingency plan & TMI increased security awareness MADDEN.W Region I. Office of Director 84/03/26 ip 22822 088 24X Fiche 50-000, 84/03/26,8403300074
- U Congressional/Executive Correspondence
- B403070053 Responds to 931214 ltr suggesting Commission refuse to restart Unit 1 until funding for Unit 2 cleanup in place Commission does not believe that Unit 1 restart & Unit 2 cleanup should be tied together PALLADINO.N J Commissioners 84/02/08 MORRIS.A E Advisory Council for Decontamination of TMI Unit 2 1p 22563 178 24x Fiche.50-289.84/02/08.8403070053
- --8403070069 Responds to 831207 ltr urging Commission not to authorize restart of Unit 1 Commission views on restart set forth in encl 840127 notice to parties Commission does not believe Unit 1 restart & Unit 2 cleanup related PALLADINO,N J Commissioners 84/02/08 GEKAS,C W House of Rep ip 22563,200 24X Fiche 50-289,84/02/08,8403070053
- --8403070073 Urges Commission not to accept recommendation to restart Unit 1 in light of mpt integrity review & criminal proceedings & slow pace of Unit 2 cleanup GEKAB, 0 H House of Rep B3/12/07 PALLADING, N J Commissioners. Ip 22563 217 24X Fiche 50-289,84/02/08,8403070053
- --8403070076 Advises of convictions re Unit 1 restart Due to criminal indictments & helief that Unit 1 revenue should go directly toward Unit 2 cleanup, recommends against restart HALKER, R 9 House of Rep 83/12/13 PALLADING, N, ASSELSTINE, J. BERNTHAL, F Gommissioners 19, 22563 218, 24X Fichs 30-289,84702/08.8403070053
- DOGKET 50-321 EDWIN I HATCH NUCLEAR PLANT, UNIT 1

 F Security, medical, emergency & fire protection plans
- B403090282 Public version of Rev O to Emergency Plan Implementing Procedure HNP-8161, "Eberline Model PCM-1 Portal Monitor" & Rev 17 to HNP-8008, "Radiation Work Permit" W/84018 1tr & JM Felton 830307 release memo.

 BCRRELL,E C , NIX.H. C. georgia Power Co 84/01/18 46pp 22593 321 24X Fiche.50-321,84/01/18.8403090282
- 8403300339 Public version of transmittal & title pages of deleted Emergency Plan Implementing Procedures HNP-8019, "Insp of Btesi Radwaste Shipping Drums" & HNP-8422, "Handling & Leading of Chem-Nuclear Cask " W/840119 1tr & 840322 memo BORRELL,E C , NIX,H C Georgia Power Co 84/01/25 App 22842 306 24X Fiche 50-321,84/01/25,8403300339
- 8403260261 Forwards order confirming licenses commitment to implement post-TMI-related itmes in NUREQ-0737. Suppl i (Generic Ltr 82-33), "Requirements for Emergency Response Capability," STOLZ, J. F. Operating Reactors Branch 4. 84/02/21 BECKHAM, J T Georgia Power Co. 3pp 22763 179, 24X Fiche. 50-321.84/02/21, 8403260261
- ---B403260265 Order confirming licensee commitments on emergency response capability requirements set forth in NUREQ-0737, Suppl 1 (Qeneric Ltr 82-33), EISENHUT, D. O. Division of Licensing 84/02/21 Qeorgia Power Co. 6pp. 22763 182 24X Fiche 50-321,84/02/21,8403260261.
- 8403090067 Forwards rev to physical security plan Rev withheld (ref 10CFR2.790 & 73 2i), Transmittal ack encl BECKHAM.J.T Georgia Fower Co 84/02/27 O'REILLY, J.P. Region 2. Office of Director. 2pp 22575 351 24X Fiche 50-321,84/02/27, 8403090067
- 8403130165 Revs 6 & 7 to Emergency Plan Implementing Procedures
 HNP-8006, Rev 9 to HNP-8007 & Rev 0 to HNP-8043 re
 decontamination & Rev 8 to HNP-4860; HP-4867, 4868 &
 4869 re reveiw & rev to emergency plan W/840306 ltr
 SORRELL, E C @eorgia Power Co. 84/03/02 124pp 22600, 132 24X
 Fiche: 50-321, 84/03/02, 8403130165

- B403130346 Advises that next annual emergency exercise scheduled for B40B02 State of GA & local govts do not plan to fully participate Exemption to 100FR90.App E necessary to proceed w/exercise Recpt requested if date & exercise acceptable BECKHAM.J T Georgia Power Co B4/03/02 DENTUN.H R Office of Nuclear Reactor Regulation, Director 1p 22607 149 24X Fiche 50-321.84/03/02.8403130346
- 8403160150 Notifies of 840316 workshop meeting to discuss 10CFR50, App R requirements & associated inspiresults to resolve fire protection misunderstandings Number of attendees should be limited to six due to conference room sixe

 LEWIS, R C Region 2. Office of Director 84/03/02 KELLY, R J Opengia Power Co ip 22655 317 24X Fiche 50-321,84/03/02.
- 8403130004 Transmittal & title pages of deleted emergency plan implementing procedures; including HNP-1-4205 re turbine lube oil reservoir oil fire & HNP-1-4206 re turbine lube oil conditioner & storage fire W/480306 ltr
 80RRELL,E C Georgia Power Co 84/03/06 12pp 22615 183 24% Fiche 50-321,84/03/06,8403130004
- B403260150 Revised emergency plan implementing procedures, including Procedure HNP-8033 re quantitative fit testing. Procedure HNP-8034 re alert emergency rally point leader & Procedure HNP-8010 re use & care of respirators W/840320 ltr BORRELL, E C Georgia Power Co 84/03/20 i14pp 22758 290 24X Fiche 50-321,84/03/20.8403260150
- 8403300143 Rev & to Emergency Plan Implementing Procedures HNP 4726 & 4626 & Rev 8 to Procedure HNP-8012 re general & site area penergency relly point leaders & radiation & contamination surveys H/840326 ltr
 80RRELL,E C Georgia Power Co 84/03/26 119pp 22820 083 24X Fiche 50-321.84/03/26.8403300143
- J. Insurance & indemnity information
- 8403060281 Forwards Endorsement 85 to NELIA Policy NF-215
 DUCK, J.R. Marsh & McLennan, Inc. 84/02/28 SALTZMAN, J. Assistant
 Director for State & Licenses Relations 2pp 22518-187 24X
 Fiche 50-321,84/02/28,8403060281
- 8403280038 Forwards Endorsements 86 & 87 to NELIA Policy NF-215 & Endorsements 70 & 71 to MAELU Policy MF-78
 DUCK, JR Marsh & McLennan, Inc 84/03/21 SALTZMAN, J Assistant Director for State & Licensee Relations 5pp 22777.010 24X
 Fiche 50-321,84/03/21,8403280038
- D Advisory Committee on Reactor Bafeguards reports & correspondence
- 8402270263 Responds to FOIA request for JC Mark 801204 memo to ACRB re hydrogen burn w/igniters & documents concerning generation, combustion or control of hydrogen in reactor accidents Forwards App A documents App B documents in FDR FELTON.J M Division of Rules and Records 84/01/30 HIATT.B L Ohio Cititens for Responsible Energy 7pp 22412.051 24X Fiche 50-000.84/01/30.4402270263
- --8402270314 Forwards summary of investigations re bydrogen recombiners & relay failures in HPCI sys
 ZUKOR,D J ACRS Advisory Committee on Reactor Safeguards
 80/10/30 MOELLER,D W ACRS Advisory Committee on Reactor
 8afeguards 4pp 22412 086 24X Fiche 50-000,84/01/30,
 8402270263
- P Operating license stage documents & correspondence
- B401120436 Notification of 840214 meeting w/GPU, Bechtel & Southern Sycs Co in Bethesda, MD to discuss equipment qualification RIVENBARK.0 W Operating Reactors Branch 4 84/01/09 STOLZ, J F Operating Reactors Branch 4 2pp 21804.101 24X Fiche 50-321,84/01/09,8401120456
- 8403090187 Application for amend to Licenses DPR-57 & NPF-5, revising Tach Specs re listed TMI Action Plan items, per Generic Ltr 83-36
 BECKHAM, J T Georgia Power Co 84/02/06 STOLZ, J F Operating Reactors Branch 4 Spp. 22573 276 24X Fiche 50-321,84/02/06,8403090187
- --8403090196 Proposed Tech Specs re instrumentation providing surveillance info.post-accident sampling & analysis & post-accident monitoring instrumentation * Georgia Power Co 84/02/06 | 18pp 22573 284 24X Fiche 50-321,84/02/06,8403090187

- 8403160226 Reviews 840112 meeting to discuss responses to 831004 request for add1 info needed to review QA program description List of meeting attendees ent1 LEWIS.R C Division of Project & Resident Programs 84/02/07 KELLY.R J Georgia Power Co 3pp 22661 064 24X Fiche 50-321,84/02/07,8403160226
- 8403050085 Discusses analyses on 22 safety relief valve (SRV) discharge lines per 821227 request to address questions re SRV test program per THI Item II D I Analyses indicate supports & piping geometry adequate GUCHA, L T Georgia Fouer Co 84/02/10 STOLZ, J F Operating Reactors Branch 4 2pp 22490 007 24X Fiche 50-321, 84/02/10, 8403050085
- 8403060436 Forwards notice of consideration of issuance of Amenda 97 & 34 to Licenses DPR-57 & NPF-5, respectively & proposed NSHC determination & apportunity for hearing re time requirements for scram discharge vol vent & drain valves RIVENBARK.O Operating Reactors Branch 4 84/03/21 BECKMAN.J T Georgia Power Co 3pp 22349 344 24X Fichs 50-321.84/02/21.8403060436
- --8403060440 Notice of consideration of issuance of Amenés 97 % 34 to Licenses DPR-57 & NPF-5, respectively & proposed NSHC determination & opportunity for hearing STOLZ.J F Operating Reactors Branch 4 84/02/21 8pp 22549 347 24X Fiche 50-321.84/02/21.8403040436
- 8403140340 Summary of 831215 merting w/CE & Mark 1 Comers Group in Bethesda,MD re Mark I containment wetwell-drywell vacuum breaker design methodology SIEGEL.D L Operating Reactors Brench 2 84/02/21 Operating Reactors Branch 2 51pp 22635 198 24X Fiche 50-000,84/02/21, 8403140340
- 8403010110 Forwards Amends 98 & 35 to Licenses DPR-57 & NPF-5, respectively & safety evaluation Amends revise Tech Specs to extend time allowed to restore thermal power scram & control rod block trip setpoints within Tech Spec limits RIVENBARK, O Operating Reactors Branch 4 84/02/22 BECKMAM, J 7 Georgia Power Co 2pp 22479 281 24X Fiche 50-321, 84/02/22, 8403010110
- --B403010124 Amends 9B & 35 to Lirenses DPR-57 & NPF-5, respectively, ravising Tech Specs to extend time allowed to restore thermal power scram & control rod block trip setpoints within Tech Specs limits
 STOLZ.J F Operating Reactors Branch 4 B4/02/22 15pp 22479 283 24X Fiche 50-321,84/02/22,8403010110
- --84030i0128 Safety evaluation supporting Amends 98 & 35 to Litenses DPR-57 & NPF-5 respectively * Office of Nuclear Reactor Regulation, Director 84/02/22 Spp 22479 298 24X Fiche 50-321.84/02/22,84030i0110
- B403070397 Forwards request for additinfo to complete review of proposed programs for inservice testing of pumps & valves submitted in 830812 ltr Info requested within 30 days

 BTOL7. J F Operating Reactors Branch 4 B4/02/23 BECKHAN. J T Georgia Power Co 4pp 22564 134 24X Fiche 50-321.84/02/23.8403070397
- 8403070251 Forwards update on facilities conformance & info re glans & schedules for any needed improvements & rept re vendor equipment technical info program by Nuclear Util Task Action Committee on Generic Ltr 83-28. Section 2 2 2 GUCMALL T Georgia Power Co 84/02/29 BTGLZ. J F Decrating Reactors Branch 4 24pp 22536 089 24X Fiche 50-321.84/02/29, 8403070251
- --8403070252 "Vendor Equipment Technical Info Program," per Generic Ltr 83-28. Section 2 2 2.final draft * Nuclear Utility Task Action Committee 84/02/29 63pp 22536 112 24X Fiche 50-321.84/02/29.8403070251
- 8403260045 Forwards Amend 99 to License DPR-57 Amend changes Tach Specs to delete drywell-to-torus differential pressure sys STOL7.J F Operating Reactors Branch 4 64/03/06, BECKHAM,J T Georgia Power Co 3pp 22763 284 24X Fiche 50-321.84/03/06, 8403260045
- --8403260048 Amend 97 to License DPR-57, changing Tsch Specs to delete drywell-to-torus differential pressure sys STOLZ.J F Operating Reactors Branch 4 84/03/06 9pp 22743 287 24X Fiche 50-321,84/03/06,8403260045
- B403200005 Responds to B40227 request for add1 action to verify aspects of overhead crane design at facility.per NUREG-0612 guidelines Crane safety & reliability satisfactory QUCWALL T Georgia Power Co B4/03/12 STOLZ.J F Operating Reactors Branch 4 2pp 22685 209 24X Fiche 50-321.84/03/12, B403200005

- 8403150275 Generic Ltr 84-07 to all licensees of BWRs re procedural guidance for pipe replacement at BWRs Svc list encl EISENHUT.D 0 Division of Licensing 84/03/14 Commonwealth Edison Ca 20pp 22823 354 24X Fiche 50-000.84/03/14.8403150275
- 0 Inspection reports, IE Bulletins & correspondence
- 8403160196 Forwards IE Insp Repts 50-321/84-04 & 50-366/84-04 on 840204-07 No violations or deviations identified DANCE: H C Division of Project & Resident Programs 84/02/24 KELLY: R T Gorgia Power Co 2pp 22655 351 24X Fichs 50-321,84/02/24,8403160196
- --8403160198 IE Insp Repts 30-321/84-04 & 30-366/84-04 on 840204-07 No violations or deviations identified Major areas inspected torus vent header cracking feedwater line ultrasonic indication & recirculation piping replacement CROWLEY, B R , BLAKE, J J Region 2, Office of Director. 84/02/23 dpp 22635 353 24X Fichs 50-321,84/02/24,8403160196.
- B401190072 IE Info Notice B4-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/02/28 Consolidated Edison Co of New York, Inc 115pp 22909 239 24X Fiche 50-000.84/02/28.8401190072
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Evc list encl GRACE.J N Division of GA. Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24x Fiche 50-000,84/03/02,8402090007
- 8402070008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 2255 098 24% Fiche 50-000.84/03/02,8402070008
- 8402070009 [E Info Notice 84-15, "Reporting of Radiological Releases" 8vc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 119pp. 22553 217 24X Fiche 50-000.84/03/02.8402090009
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Bvc list encl JORDAN.E i. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8402090024 IE Info Notice 84-07, Rev 1, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl, JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22635 049 24% Fiche 50-000,84/03/07,8402090024
- 8402070028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Sys " Syc list encl, JORDAN, El Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fichs 50-000,84/03/07,8402090028
- 8403160338 Ack receipt of 840206 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/83-32 & 50-366/83-34
 DANCE.H C Division of Project & Resident Programs. 84/03/09 KELLY.R J Georgia Power Co. 1p 22660 015 24X
 Fiche 50-321,84/03/09,8403160338
- --B403140349 Responds to NRC 840106 ltr re violations noted in IE Insp. Repts 50-321/83-32 & 50-366/83-34 Corrective actions: procedure revs drafted & undergoing review & approval process

 GUCHA, L. T. Georgia Power Co. 84/02/06 D'REILLY, J. P. Region 2, Diffice of Director 2pp 22660 016 24X Fiche 50-321, 84/03/09, 8403160338
- --8403160357 Forwards IE Insp Repts 50-321/83-32 & 50-366/83-34 on B31114-18 & notice of deviation DANCE,H C Division of Project & Resident Programs, 84/01/06. KELLY,R,J Georgia Power Co 2pp 22660:018 24X Fiche 50-321,84/03/09,8403160338
- --8403160365 Notice of deviation from insp on 831114-18 * Region 2, Office of Director 84/01/06 ip 22660 020, 24X Fiche 50-321,84/03/09,8403160338

- ---8403160372 IE Insp Repts 50-321/83-32 & 50-366/83-34 on B31114-18 Deviation noted failure to electronically calibr high range drywell radiation monitors, per NUREO-037. Item II F I HRAY, J R Region 2, Office of Director BARR, K P Division of Engineering & Operational Programs 84/01/04 7pp 22660, 021 24% Fiche 50-321, 84/03/09, 8403160338
- 8402070031 IE Bulletin 84-02. "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Syc list encl DEYOUNO, R C Director's Office of Inspection and Enforcement B4703/12 Consolidated Edison Co of New York, Inc 134pp 82823 094 24X Fithe 50-000.84/03/12.8402070031
- 8403290193 Ack receipt of 840301 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-366/83-26 LEWIS.R C. Division of Project & Resident Programs 84/03/15 KELLY.R J. Georgia Power Co 1p 22801 008 24x Fichs.50-366.84/03/15.8403290193
- --8403270194 Responds to NRC 840201 ltr re violations noted in IE Insp Repts 50-321/83-25 & 50-366/83-26 on 830721-0820 Corrective actions administrative controls to stress independent verification upgraded BECKHAN.J T Georgia Power Co 84/03/01 D'REILLY, J P Region 2, Office of Director 6pp 22801 009 24X Fiche 50-366, 84/03/15.8403290193
- --B403270175 Forwards IE Insp Repts 50-321/B3-25 & 50-366/B3-26 on B30721-0820 & notice of violation LEWIS.R.C Division of Project & Resident Programs 84/02/01 KELLY.R.J Georgia Power Co 2pp 22B01 015 24X Fiche, 50-366/B4/03/15, 8403290193
- --8403290197 IE Insp Repts 90-321/83-25 & 50-366/83-26 on 830721-0820 Violations noted safety-related equipment & sys not aligned & limiting condition for operation for main steam isolation leakage control sys not established CRLENJAKIR V., HOLMES-RAY,P., PANCIERA,V W. Region 2, Office of Director 84/01/28 Spp 22801 018 24X Fiche 50-366,84/03/15,8403290193
- 8403290208 Ack receipt of 840301 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-321/84-03 DANGE: H C Division of Project & Resident Programs, 84/03/19 KELLY, R J. Georgia Power Cb 1p 22800 302 24X Fichs 50-321,84/03/19,8403290208
- --8403270212 Responds to NRC 840210 ltr re violations noted in lE Insp. Repts 50-321/84-03 & 50-366/84-03 Corrective actions NDE personnel reminded of importance of proper & complete data recording.

 GUCHA, L. T. Georgia Power Co. 84/03/01 G'REILLY, J. F. Region 2: Office of Director. 2pp. 22800 303 24X Fiche 50-321; 84/03/17; 84/03909008
- --8403290215 Forwards IE Insp Repts 50-321/84-03 & 50-366/84-03 on 840124-27 & notice of vialation DANCE,H.C. Division of Project & Resident Programs 84/02/10 KELLY,R J. Georgia Power Co 2pp 22800 305 24X Fiche 50-321,84/03/19,8403270208
- ---B403290216 Notice of violation from insp on 840124-27

 * Region 2. Office of Director 84/02/10 ip 22800 307 24X
 Fichs.50-321,84/03/19.8403290208
- ----B403290219 IE Inso Repts 50-321/84-03 & 50-366/84-03 on B40124-27 Violation noted ultrasonic insp records for Fall 1982 insp of reactor vessel flange to Shell Weld C-1 did not show extent or location of area CROMLEY, B. R. Region 2, Office of Director BLAKE, J. J. Division of Emergency Preparedness & Materials Safety B4/02/09 11pp 22800 308. 24X Fiche: 50-321,84/03/19,8403290208
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103), 84/03/21. Consolidated Edison Co of New York, Inc. 123pp 22823 229 24X Fiche 50-000.84/03/21,8402090043
- 8402070044 IE Info Notice 84~20, "Svc Life of Relays in Safety-Related 84s." Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc. 135pp. 22933 001 24X Fiche 50-000.84/03/21,8402070044
- R. Periodic operating reports & related correspondence
- 8403130071 Monthly operating repts for Feb 1984 W/B40310 ltr RAFEEDIE, D P , NIX-H C Georgia Power Co B4/02/27 12pp 22443;191 24X Fiche 50-321,84/02/29,8403150071

- 8 Reportable occurrences, LERs & related correspondence
- 8403090228 Supplemental narrative summary to LER S0-321/1979-021. Rev 5 providing updated data re tritium levels in groundwater samples during Third Quarter 1983 presented in encl Table 1 W/840208 ltr NIX. H C Georgia Power Co 84/01/31 O'REILLY, J P Region 2, Office of Director 3pp 22571 237 24X Fiche 50-321, 84/01/31, 8403090228
- 8403010330 Forwards supplemental narrative summary to LER 50-321/79-021, Rev 5 Groundwater problems reviewed w/Region II personnel on 831219 Problems not environ concern in regulatory sense Rept closes LER NIX, H C Georgia Power Co 94/02/08 O'REILLY, J P Region 2, Office of Director 3pp 22432 079 24X Fiche 50-321, 84/02/08, 8403010330
- 8403160044 LER 84-001-00 on 840211, reactor scram followed high vibration turbine trip Caused by bucket & finger damage to both 13th stages of low pressure turbine A Stage 13 will be replaced at later date W/840309 ltr
 TIPPS.6 B , NIX.H C Georgia Power Co 84/03/09 4pp 22655.120 24X Fiche 50-321.84/03/09.8403160044
- 8403300104 Advises that program of periodic manual operation of safety relief valves will be discontinued, based on results of BWR Owners Group investigation Safety relief valve cycling caused valves to leak prematurely GUCHALL T Georgia Power Co 84/03/26 STOLZ, J F Operating Reactors Branch 4. 2pp 22821 216 24X Ficke 50-321,84/03/26,8403300104
- DOCKET 50-322 SHOREHAM NUCLEAR POWER STATION
- A Application/construction stage documents & correspondence
- 8403080363 FOIA request for documents re BWR Intergranular Stress Corrosion Cracking Duners Group meeting on or about 811028 HAFNER, B Suffolk Nuclear Study Group 83/11/26 Office of Administration 1g 22583 007 24X Fiche 50-322,83/11/26, Ad03080343
- B403020139 Provides justification for deletion of station blackout test & completion of program for training during low power testing.per Thi Item I G i.in response to Generic Ltr B3-24 MCCAFFREY.B R Long Island Lighting Co B4/02/16 DENTON.H R Office of Nuclear Reactor Regulation, Director Bpp 22443 245 24X Fiche 50-322.B4/02/16.B403020139
- 8403080367 Responds to FOIA request for documents re EHR Integrabular Stress Corrosion Cracking Dumers Group meeting on or about 811028 Forwards App A documents Recards also in PDR FELTON, J M Division of Rules and Records 84/02/28 HAFNER, B Suffalk Nuclear Study Group 2pp 22583 008 24X Fiche 30-000.84/02/28.8403080367
- --8309210434 Requests evaluation of Grand Gulf & Bhoreham 830817 & 23 responses, respectively re intergranular stress corrosion cracking in BHR piping Response requested by 630916 W/o encl EIBERHUT, D & Division of Licensing 83/09/06 VOLLMER, R Division of Engineering ip. 22583 010 24X Fithe 50-000.84/02/28.8403080367
- 840309001B Responds to FOIA request for documents re BNL background radiation survey DDE preparing Shoreham & BNL site repts When printed Shoreham nept will be available from NRC & BNL rept will be available from DDE FELTON.J M. Division of Rules and Records 84/03/02 GROBSMAN.K Island Closeup Naws Service. Eag Harbor, NY ip 22592 344 24X Fiche 50-322.84/03/02.8403096018
- B403140019 Clarifies Sept 1983 draft technical evaluation rept of Phase II submittal of control of heavy loads, per 840109 telcon Bafe load paths for reactor bldg closed loop cooling water pumps revised MCCAFFREY, B R Long Island Lighting Co 84/03/05 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 22633 218 24X Fiche 50-322, 84/03/05, 8403140019
- 8403140126 Forwards NRC Region I morning repts re facility emergency diesel generators for 840215-0301 GDD0ARD.R J Hearing Branch 3 84/03/05 BRENNER.L., FERGURGIN.G A. MORRIS.F A Atomic Safety and Licensing Board Panel 13pp 22620 341 24X Fiche 50-322.84/03/05.8403140126

- 8403200302 Forwards response to Generic Ltr 83-28, "Required Actions Based on Generic Implications of Salem ATHS Events" Encl addresses each NRC position & describes actions taten by util in response MCCAFFREY, B R Long Island Lighting Co 84/03/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 50pp 22696 177 24X Fiche 50-322,84/03/09,8403200302
- 8403200227 Responds to Generic Ltr 84-01 providing description of NRC position on regulatory jurisdiction involving terms important to safety & safety-related Util wishes to discuss subj further MCCAFFREY. B R Long Island Lighting Co 84/03/i3 DENTON. H Office of Nuclear Reactor Regulation. Director 2pp 22690-188 24X Fiche 50-322.84/03/13.8403200227
- 840209004) Board Notification 84-050 provides Commission policy statement & proposed rulemaking on environ qualifications EISENRUTE O Division of Licensing 84/03/14 Atomic Safety and Licensing Board Panel 10pp 24X Fiche 50-000.84/03/14,8402090041
- 8403270116 Forwards supplemental nuclear power plant experience tables for operating shiff positions Expected OL date is 840515.in response to addl questions in DF Schnell.Union Electric Co. ltr NOTARO, J A Long Island Lighting Co. 84/03/22 DENTON, H R Office of Nuclear Reactor Regulation, Director Spp. 22775 157 24% Fiche 50-322,84/03/22.8403270114
- 8403290248 Requests that Suffolk County, NY be notified in advance of any discussions or meetings w/util & be invited to participate County requests copies of documents re review of util 840320 supplemental motion for low power OL LANPHER, L C Kirkpatrick, Lockhart, Hill, Christopher & Phillips LANPHER, L C Suffolk County, NY 84/03/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22800 215 24X Fiche 50-322,84/03/23,8403290248
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8403020287 Forwards "Rept on Special Lifting Devices," per 831111 response to SER Open Item 59 Rept covers design, fabrication & initial acceptance testing of six special lifting devices listed in 7able 3 of 810717 itr MCCAFFREY, B R Long Island Lighting Co 84/02/21 DENTON, X R Office of Nuclear Reactor Regulation, Director 3pp 22441 268 24X Fiche 50-322,84/02/21,8403020287
- ~~8403020290 "Rept on Special Lifting Devices " * Stone & Webster Engineering Corp 11600 02 84/02/10 47pp 22441 271 24X Fiche 50-322.84/02/21.8403020287
- 8400270119 Forwards monthly status "List of Active Safety-Related Equipment at Qualification Level." per SER Issue 9 re dynamic qualification MCCAFFREY. B R tong Island Lighting Co 84/03/15 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 22774 062 24X Fiche 50-322.84/03/15.8400270119
- ~-8403270122 "Control Bldg Category | Equipment Balance-of-Plant Qualification Level:" monthly status rept * Etone & Webster Engineering Corp 84/02/27 50pp 22774 064 24X Fiche 50-322,84/03/15.8403270119
- F Security, medical, emergency & fire protection plans
- 8403290160 Forwards Rev 3 to local offsite radiological emergency response plan
 SMITH.J Long Island Lighting Co 83/12/21 DENTON.H R Office of Nuclear Reactor Regulation, Director 4pp 22804 001 24X Fiche 50-322.83/12/21.8403290160
- ~-8403270165 Rev 3 to local offsite radiological emergency response plan W/17 oversize Figures * Long Island Lighting Co 83/12/21 700pp 22804 021 24X Fiche 50-322,83/12/21,8403270160
- 8402090006 Board Notification 84-034 forwards R Vollmer 840206 memo to D Eisenhut re fire research results concerning fires in electrical cabinets in control room EISENHUT.D 9 Division of Licensing 84/02/23 PALLADING Commissioners ip 28574 203 24X Fiche 50-000-84/02/23. 8402090004
- --8403080316 Recommends that info re fire research results concerning fires in electrical cabinets in control room be submitted for board notification.per NRR OFC Ltr 19.dtd 821001 Further evaluation of test data required VOLLMER.R H Division of Engineering 84/02/06 EISENHUT.D G Division of Licensing 10pp 22576 204 24X Fiche 50-000.84/02/23,8402090006

- B403190243 Notification of 840418 workshop in King of Prussia.PA to discuss lessons learned from recent App R fire protection safe shutdown insp & topics described in IE Info Notice 84-09 Agends for workshop enc!

 MURLEY.TE Region 1. Office of Director 84/03/09 D'TOOLE.U D Consolidated Edison Co of New York. Inc DALTROFF.8 L. Philadelphia Electric Co HUKILL.H D General Public Utilities GPU Service Corp 35pp 22672 062 24x Fiche 50-000,84/03/09. 8403190243
- 8403270245 Forwards revised safeguard license condition resulting from review of Rev 2 to guard training & qualification plan Rev 2 changes acceptable MIRAGLIA: F J Assistant Director for Safety Assessment 84/03/09 NOVAK, T M Assistant Director for Eafety Assessment 92/03/09 Fiche 50-322.84/03/09.6403270245
- 8403190363 Forwards evaluation of LILCO transition plan per NUREG-0654/ FEMA-REP-1, Rev 1 Deficiencies noted SPECK, 5 W Federal Emergency Management Agency 84/03/15 pIRCKS, W J Office of the Executive Director for Operations 7ipp 22673 081 24X Fiche 50-322,84/03/15,8403190363
- B403260113 Forwards FEMA review of Rev 3 to util transition plan for offsite emergency preparedness, per NUREO-0654
 MARTIN, T T Division of Engineering & Technical Programs B4/03/20
 FOLLOCK, M S Long Island Lighting Co 3pp 22758 001 24X
 Fiche 50-322.84/03/20.8403260113
- --8403260117 Review of Rev 3 to util transition plan for offsite emergency preparedness.per NURE0-0654 * Federal Emergency Management Agency 84/02/10 66pp 22758 004 24X Fichs 50-322,84/03/20.8403260113
- 8403280029 Forwards Rev 7 to amended security plan Rev withheld (ref 10CFR73 21) MCCAFFREY,B R Long Island Lighting Co 84/03/22 DENTON.H R Office of Nuclear Reactor Regulation, Director 3pp 22777 048 24X Fishe 50-322,84/03/22,8403280029
- G Adjudicatory correspondence
- 8403280063 Util Bafety Classification Group brief amicus curiae objecting to ASLB distinction between regulatory terms important to safety % safety-related EARLEY, A F Utility Safety Classification Group 83/12/23 Atomic Safety and Licensing Appeal Panel 38pp 22813 001 24X Fiche 50-322,83/12/23,8403280063
- 8403010220 Revises svc list, adding BR McCaffrey & deleting JL Smith Certificate of Svc encl BRITT.L F Long Island Lighting Co 84/02/24 BRENNER, L. J. FERGUSDN, C A., MORRIS, P A. Atomic Safety and Licensing Board Panel 3pp 22435 235 24X Fiche 50-322.84/02/24.8403010220
- 8403010183 Motion opposing Suffolk County motion for extension of time to respond to DDE summary disposition motions Request untimely & unsupported by good cause Certificate of Svc encl Related correspondence
 MCCLESKEY.K E Long Island Lighting Co MCCLESKEY.K E Hunton & Williams 64/02/27 Atomic Sefety and Licensing Board Panel 5pp 22435 302 24% Fiche 50-322.84/02/27.8403010183
- B403010195 Motion for leave to file surrebuttal testimony on Contention 23 re shadow phenomenon in interest of allowing ASLB to hear clash among experts, testimony should be allowed Certificate of Svc encl Related correspondence CHRISTMAN.J N Long Island Lighting Co CHRISTMAN.J N Hunton & Williams B402/27 Atomic Safety and Licensing Board Panel. 7pp 22435 291 24X Fiche 50-322,84/02/27,8403010195
- 8403010234 Motion for extension of time until 840304 to respond to LILCO summary disposition motions on Contentions 24 B.33.45, 44 & 49 Related correspondence LETSCHE,K J Suffalk County, NY LETSCHE,K J Kirkpatrick, Lockhart. Hill. Christopher & Phillips 84/02/27 Atomic Safety and Licensing Board Panel 4pp 22434 184 24X Fiche 50-322,84/02/27,8403010234
- B40301023/ Motion for leave to file modified Contentions 16 & 18 reutil public educ brochure Motion should be granted Denial would constitute improper refusal to deal w/important issues raised by brochure

 LETSCHE, K J Suffolk County, NY LETSCHE, K J Kirkpatrick,
 Lockhart, Hill, Christopher & Phillips 84/02/27 Atomic Safety
 and Licensing Board Panel 19pp 22434;191 24x

 Fiche 50-322,84/02/27,8403010237

- B403010242 Interrogatories to Suffolk County & State of NY re identification of expert witnesses at trial concerning diesel generator contentions Certificate of Svc encl Related correspondence ELLIS.T S Long Island Lighting Co ELLIS.T S Hunton & Williams B4/02/27 Suffolk County, NY 5pp 22434 214 24X Fichs 50-322.84/02/27,8403010242
- 8403010249 Notice of TA Moore, A Bakshi, QD Eley, W Avery, R Anderson, P Meulangracht, B Christensen, M Goldsmith & R Hubbard depositions on 840307, 08, 09, 12, 13, 14, 15, 16 & 19, respectively Certificate of Svc encl Related correspondence ELLIB, T B. Long Tsland Lighting Co ELLIB, T S. Hunton & Williams B4/02/27 Bpp 82432 275 24X Fiche 50-322, 84/02/27, 8403010249
- 8403020123 Statement of Governor Cuomo in support of Buffolk County 840213 motion for leave to file new contentions re util offsite emergency preparedness training program Certificate of Svc encl CUOND.M. ZAHNLEUTER.R. J. New York. State of 84/02/27 4pp 22442 108 24X Fiche 50-322.84/02/27.8403020123
- 8403020233 Affidavit of D Axelrod opposing util motion to compel expedited production of documents by Btate fo NY Documents subj to executive privilege W/Certificate of Svc Related correspondence AXELROD, D. New York, State of 84/02/27 app 22440 269 24X Fichs 50-322.84/02/27,8403020233
- 8403010174 Order granting Suffolk County 840227 motion for 6-day extension of time within which to respond to LILCO summary disposition motions
 LAURENSON, J A Atomic Bafety and Licensing Board Panel 84/02/28 4pp 22435 227 24X Fiche 50-322,84/02/28.8403010174
- B403010215 Memorandum & order denying Suffolk County 840208 motion for leave to file reply to LILCO answer apposing Suffolk County motion for leave to file rebuttal testimony on Contention 23 LAURENBON, J A Atomic Safety and Licensing Board Penel 84/02/28 84/61k County, NY 10pp 22436 007 24X Fiche 50-322,84/02/28.8440310215
- 8403010225 Order granting in part LILCO 840206 motion to compet expedited production of documents by State of NY & denying LILCO 840206 motion to reply to State of NY LAURENSON, J A Atomic Bafety and Licensing Board Panel 84/02/28 Long Island Lighting Co 10pp 22435 243 24X Fiche 50-322,84/02/28,8403010225
- 8403010232 Order ruling on Suffolk County 840209 objections to 840203 memorandum & order ruling on intervenors proposed modified emergency planning contentions LAURENBON.J A Atomic Safety and Licensing Board Panel 84/02/28 8pp 22434 176 24X Fiche 50-322.84/02/28,8403010232
- 8403010269 Order granting util 840210 motion to compel expedited production of State of NY emergency preparedness plan State of NY directed to act expeditiously in complying w/order LAURENSON. J A Atomic Se/ety and Licensing Board Panel 84/02/28 5pp 22432 253 24% Fiche 50~322.84/02/28.8403010269
- B403020143 Notice of appearance in proceeding Certificate of Svc encl RDLFE,R,M Long Island Lighting Co RDLFE,R M Hunton & Williams 84/02/28 3pp 22441 360 24X Fiche 50-322,84/02/28,8403020143
- 8403020168 Motion for leave to make & suppl replies to State of NY B40223 & 27 discovery papers Certificate of Svc encl Related Correspondence IRWIN.D P Long Island Lighting Co 84/02/28 Atomic Safety and Licensing Board Panel 18pp 22443 207 24X Fiche 50-322.84/02/28.84/02/28.
- 8403140100 Forwards CH Cunningham 840228 memos re Transamerica Delaval emergency dissel generator contentions advanced by Buffolk Gounty, Hemos submitted per 840222 conference of counsel BORDENICK, B M. Hearing Branch 3 84/02/28 BRENNER, L, FERQUEON, O A, MORRIS, P A Atomic Safety and Licensing Board Panel 5pp 22421 353 24X Fiche 50-322,84/02/28,8403140100
- 8403140136 Response supporting util motions for summary disposition of Contentions 24. B. 33.45.46 & 49 No genuine facts to be litigated & applicant entitled to summary disposition of contentions. W/Certificate of Svc BORDENICK, B. M Hearing Branch 3 84/02/28 Atomic Safety and Licensing Board Panel 19pp 22620 169 24X Fiche 50-322,84/02/28. 8403140136

- 8403140141 Requests assistance in responding to ASLO inquiries re Transamerica Delaval emergency diesel generator contentions advanced by Suffaik County Summary of ASLO inquirity outlined CUNNINGHAM, O H Office of the Executive Legal Director 84/02/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22620 339 24x Fiche 50-322.84/02/28.8403140141
- B403140161 Response supporting Suffolk County 840213 motion for leave to file new contentions on offsite emergency preparedness training program Centificate of Svc enci BORDENICK. B M Hearing Branch 3 84/02/28 Atomic Safety and Licensing Board Panel lipp 22620 264 24X Fiche 50-322.84/02/28.8403140161
- 8403140182 Discusses inquiry at 840224 conference of counsel re Buffolk County Transamerica Delaval emergency diesal generator contentions Assistance requested for preparation of appropriate rept, CUNNINGHAM. G H Office of the Executive Legal Director 84/02/28 HAYES, B Office of Investigation 1p 22620 188 24X Fiche 50-322,84/02/28.8403140182
- 8403140195 Responds to proposal circulated at 840222 conference of counsel re possibility & feasibility of transmitting info electronically to & from displaywriters Proposal generally approved BORDENICK, B M Hearing Branch 3 84/02/29 BRENNER, L, FERGUSDN, G A , MORRIS, P A Atomic Safety and Licensing Board Panel 3pp 22621 398 248 Fiche 50-322, 84/02/29, 8403140195
- 8403060105 Forwards requests for production of documents, superseding 840217 requests Related correspondence RULFE, RM Hunton & Williams ROLFE, RM Long Island Lighting Co 94/03/01 DYNNER.AR Kirkpatrick, Lockhart, Hill, Christopher & Phillips PALAMINO,F G New York, State of 1p 22506 104 24X Fiche 50-322,84/03/01.8403060105
- --8403060107 Request for production of listed documents re Contentions I,
 11 & III Certificate of Svc encl Related correspondence
 ROLFE,R M Long Island Lighting Co ROLFE,R M Hunton &
 Williams 84/03/01 DYNNER.A R Suffolk County, NY DYNNER.A R
 Kirkpatrick, Lockhart, Hill, Christopher & Phillips 44pp
 22506 105 24X Fiche 50-322.84/03/01.8403060105
- 8403060265 Answer to Suffolk County 840227 motion to file modified public educ brochure contentions & objections to contentions Contentions clearly inadmissible & motion should be denied Certificate of Byc encl CHRISTMAN, J N Long Island Lighting Co 84/03/01 Atomic Safety and Licensing Board Panel 17pp 22517 112 24X Fiche 50-322,84/03/01,8403060265
- 8403040114 Order confirming schedule changes for Group II issues LAURENSIONJ A Abomic Bafety and Licensing Board Panel 84/03/02 Long Island Lighting Co 5pp 22516 329 24X Fiche 50-322,84/03/02,8403060114
- 8403060208 Objects to ASLB 840301 conference call involving counsel for util & State of NY re ruling on discovery dispute concerning util request for production of certain state documents Related correspondence

 LANPHER.L C Kirkpatrick, Lockhart, Hill, Christopher & Phillips

 LANPHER.L C Suffolk County, NY 84/03/02 LAURENSON, J A , XLINC, J R , SHON, F J Atomic Safety and Licensing Board Panel 2pp

 22516 086 24X Fiche 50-322,84/03/02,8403060208
- 8403060268 Brief in response to util B31223 brief on appeal from ASLB imposition of OL condition re term important to safety as pertaining to class of structures, sys & components Certificate of Swc encl
 LANPHER, L C Suffolk County, NY LANPHER, L C Kirkpatrick,
 Lockhart, Hill, Christopher & Phillips 84/03/02 18pp. 22515 207
 24% Fiche 50-322,84/03/02,8403060268
- B403130129 Reply brief re Contentions 7B on classification & sys interactions & 12-i5 on GA/GC Certificate of Syc encl REVELEY, W T Long Island Lighting Co REVELEY, W T Hunton & Williams 84/03/02 Atomic Safety and Licensing Appeal Panel 137pp 22601 337 24X Fiche 50-322,84/03/02,8403130129
- B403140081 Forwards Board Notification BN-84-33 re staff sys interactions program W/o encl RAMSDN:R J Hearing Branch 4, 84/03/02 ROSENTHAL,A B , EDLES,G J , WILBER,H A Atomic Safety and Licensing Appeal Panel 2pp 22633
- 84031401BB Advises that NRC staff will not respond to util motion for leave to make & suppl replies & reply & supplemental reply to State of NY 840223 & 27 discovery papers NRC not involved in dispute between parties
 BORDENICK, B M Hearing Branch 3 84/03/04 LAURENSON, J A ,
 8HON, F J , KLINE, J R Atomic Safety and Licensing Board Panel 2Pp 22620 235 24X Fiche 50-322,84/03/04/840314015B

- 8403130027 Memorandum opposing util summary disposition motions on Contentions 24 B.33,35,45,45 & 49 Statements of matl facts as to which there exist gonuine issues to be heard encl M/Certificate of Svc Related correspondence
 LETSCHE.K J Suffolk County, NY LETSCHE.K J Kirkpatrick.
 Lockhart. Hill. Christophen & Phillips 84/03/05 Atomic Safety and Licensing Board Panel 83pp 22615 023 24x
 Fiche 80-322,84/03/05,8403130029
- 8403140039 Forwards GW McCorkle 840228 memo re Rev 2 to guard training & qualification plan.for info BORDENICK.B M Hearing Branch 3 84/03/05 IRHIN.D P Hunton & Williams MilleR.M Kirkpatrick, Lockhart, Hill, Christopher & Phillips 3pp 22633 046 24% Fiche 50-322,84/03/05,8403140039
- 8403140126 Forwards NRC Region I morning repts re facility emergency diesel generators for 840215-0301 GUDDARD:R J Hearing Dranch 3 84/03/05 BRENNER.L., FERGUSON.O A. MORRIS,P A. Aktomic Safety and Licensing Board Panel 13pp 82620 341 24x Fithe 50-322.84/03/05,8403140126
- B403090093 Order ruling on util motions to compel production of documents & objections of Governor Coomo LAURENSON, J. A. Atomic Bafety and Licensing Board Panel 84/03/06/14pp 22575 303 24% Fiche 50-322,84/03/06,8403090083
- 8403130146 Reply to util response to Suffolk County motion to file new contentions re offsite emergency preparedness training program & util objections to preposed training contentions Certificate of Svc encl
 LANPHER.L C Suffolk County, NY LANPHER.L C Kirkpatrick,
 Lockhart Hill, Christopher & Phillips 84/03/07 Atomic Safety and Licensing Board Panel 47pp 22608 173 24X
 Fiche 50-322.84/03/07.8403130146
- B403140042 Advises that NRC has no objection to util B40227 motion for leave to file surrebuttal testimony on emergency planning Contention 23 REPKA,D A Hearing Branch 3 B4/03/07 LAURENSON,JA, SHON,FJ, KLINE,JR Atomic Safety and Licensing Board Panel 2pp 22633 049 24% Fiche 50-322, B4/03/07, 8403140042
- 8403140165 Response to Suffalk County 840227 motion for leave to fila modified Contentions 16 & 18 re public info brochure Contentions 16 L.16 M & 14 N should be denied Certificate of Svc encl
 REPKA, D A Hearing Blanch 3 84/03/07 Atomic Safety and Licensing Board Panel 7pp 22620 237 24X Fiche 50-322,84/03/07, 3403140165
- 8403070059 Advises oral arguments on panding appeals will be heard on 840327 in Bethesda, NO Board will issue order confirming hearing & detailing hearing time allotments SHOEMAKER.C J Atomic Safety and Licensing Appeal Panel 84/03/08 BORDENICK.B M Office of the Executive Legal Director BROWN.H H Kirkpatrick. Lockhart, Hill. Christopher & Phillips REVELEY.W T Junton & Williams 1p 22575 349 24X Fiche 50-322,84/03/08.
- 8403130085 Motion of Governor Cuomo to file rebuttal testimony on Contention 65 re evacuation time estimates Related correspondence ZAHNLEUTER, R J New York. State of 84/03/08 Atomic Safety and Licensing Board Panel 7pp 22614 274 24X Fiche 50-322.84/03/08, 8403130085
- --B403130091 Rebuttal testimony of DT Hartgen & FJ Bench re emergency planning Contention 66 on evacuation time estimates Certificate of Bvc encl HARTGEN D T , BEACH.F J New York, State of 84/03/08 20pp 22614 281 24X Fiche 50-322,84/03/08 8403130085
- 8403130003 Motion to strike testimony of JR Sears on behalf of NRC staff re emergency preparedness Contentions 26 A, 26 C & 26 D Testimony contains personal views Certificate of Svc encl Related correspondence

 LETSCHE, K J Suffolk County, NY LETSCHE, K J Kirkpatrick, Lockhart, Rill, Christopher & Phillips 84/03/09 Atomic Safety and Licensing Board Panel App 22615 198 24X

 Fiche 90-322,84/03/09,8403130003
- B403130012 Forwards listed motions to strike testimony Related correspondence FALZONE, R. R. Long Island Lighting Co. 84703709 LAURENSEN, J. A., KLINE, J. R., EHON, F. J. Atomic Safety and Licensing Board Panel. 2pp. 22600 048 24X Fiche 50~322,84703709,8403130012
- --8403130018 Motion to strike portions of PB Herr direct testimony on Contention 22 D re emergency planning rone Testimony unduly repetitious, cumulative & irrelevant Related correspondence MONAGHAN, J A Long Island Lighting Co MONAGHAN, J A Hunton & Williams 84/03/09 Atomic Safety and Licensing Board Panel 7pp 22600 050 24% Fiche 50-322,84/03/09,8403130012

- --8403130030 Motion to strike portions of D Harris & M Mayer testimony on Contentions 24 0 (agreements of ambulances) & 75 (capacity of relocation ctrs) Testimony does not address issues Related correspondence MCCLESKEY, K E Long Island Lighting Co MCCLESKEY, K E Hunton & Williams 84/03/09 Atomic Bafety and Licensing Board Panel 7pp 22600 057 24X Fiche 50-322,84/03/09,8403130012
- --8403130041 Motion to strike portions of deputy chief inspector RC Roberts, et al direct testimony on Contentions 24 T & 59 re notification to public by US Coast & Quard Objectionable portions are Phase I issues Related correspondence MONAGHAN, J A Long Island Lighting Co MONAGHAN, J A Hunton & Hilliams 84/03/09 Atomic Safety and Licensing Board Panel. 5pp 22600 064 24X Fiche 50-322,84/03/09,8403130012
- --8403130053 Motion to strike direct testimony on Suffolk County behalf re emergency planning Contention 26 Testimony predicated on arroneous assumptions, beyond scope of contention & w/o sufficient foundation Related correspondence MONAGHAN, J A Long Island Lighting Co MONAGHAN, J A Hunton & Williams 84/03/09 Atomic Safety and Licensing Board Panel 11pp 22600 069 24X Fiche 50-322,84/03/09,8403130012
- --8403130063 Motion to strike portions of direct testimony on Suffolk County behalf re emergency planning Contentions 28-32 & 34
 Testimony generally w/o factual basis & irrelevant Related correspondence
 MONAGHAN, J A Long Island Lighting Co MONAGHAN, J A Hunton & Williams 84/03/09 Atomic Safety and Licensing Board Panel 17pp 22600 080 24% Fiche 50-322,84/03/09,8403130012
- --8403130073 Motion to strike portions of direct testimony on Suffolk County behalf re emergency planning Contentions 55-58 Majority of testimony outside scope of contentions Related correspondence MONAGHAN, J. A. Hunton & Williams 84/03/09 Atomic Safety and Licensing Board Panel Bpp 22600 097 24X Fiche 50-322.84/03/09.8403130012
- --8403130082 Notion to strike portions of assistant chief inspector JL Monteith, et al testimony on emergency planning Contention & Testimony unduly repetitious, outside scope of contention & irrelevant Related correspondence ZEUOIN.L B Long Island Lighting Co ZEUOIN.L B Hunton & Williams 84/03/09 Atomic Safety and Licensing Board Panel 4pp 22600, 105 24X Fiche 50-322, 84/03/09, 8403130012
- --8403130090 Motion to strike portions of TB Gibbons direct testimony on amorgancy planning Contentions 66 D & 97 B re agreements for snow removal & evacuation during deep snow Testimony outside scope of contention Related correspondence CHRIBIMAN.J N Long Island Lighting Co CHRIBIMAN.J N Hunton & Williams 84/03/09 Atomic Safety and Licensing Board Panel 6pp 22600 109 24% Fiche 50-322.84/03/09.8403130012
- --B403130099 Motion to strike portions of WJ Acquario.et al testimony on emergency planning Contention 67 re evacuation of persons w/o access to automobiles Testimony outside scope of contention & irrelevant Related correspondence ZEUGIN.L B Long Island Lighting Co ZEUGIN.L B Hunton & Williams B4/03/07 Atomic Bafety and Licensing Board Panel 3pp 22600 115 24X Fichs 50-322.84/03/09.8403130012
- --8403130107 Motion to strike portions of WJ Aquario.RD Albertin & RC Knighton direct testimony on emergency planning Contention 73 re evacuation of handicapped persons not in special facilities Related correspondence FALZONE.R R Long Island Lighting Co FALZONE.R R Hunton & Williams 8403/09 Atomic Bafety and Licensing Board Panel. 6pp 22600 118 24X Fiche 50-322.84/03/09.8403130012.
- --8403130119 Motion to strike portions of 8 Sargent testimony on Suffolk County behalf on emergency planning Contention 73 A reevacuation of homebound Testimony argumentative, repetitious & irrelevant W/Certificate of Svc Related correspondence CHRISTMAN, J.N. Long Island Lighting Co. CHRISTMAN, J.N. Hunton & Williams 84/03/09 Atomic Safety and Licensing Board Pahel Spp. 22600 124 24% Fiche 50-322,84/03/09,8403130012.
- 8403130022 Provides schedule of clustering & order for litigation of remaining Group I & all Group II-A issues in hearings scheduled to resume on 840320 for ASLB approval Certificate of Svc encl. Related correspondence IRNIN.D P Hunton & Hilliams IRWIN.D P Long Island Lighting Co 84/03/09, LAURENSON.JA, KLINE,JR, SHON,FJ Atomic Bafety and Licensing Board Fanel 5pp 22615 123 24X Fiche 50-322,84/03/09, RADIATORCA

- B403130043 Motion of Oovernor Coomo to strike portions of MC Cordard & JA Heismantle testimony re Phase II emergency planning Contention 92 & statement supporting Buffolk County motion Certificate of 8vc encl Related correspondence ZAHNLEUTER, R J New York, State of B4/03/09 Atomic Safety and Licensing Board Panel 9pp 22598 346 24X Fiche 50-322,84/03/09, B403130043
- 8403130097 Order granting util 840227 motion for leave to file surrebuttal testimony on Contention 23 LAURENSON.J A Atomic Safety and Licensing Board Panel 84/03/09 2pp 22614 268 24X Fiche 50-382.84/03/09.8400130097
- 8403130107 Memorandum & order ruling on Suffolk County 840227 motion to file modified Contentions 16 & 18 re util public education brochure Contentions 16 J.16 K.16 L & 16 M allowed Contentions 16 N & 18 denied and Licensing Board Panel 84/03/07 LAURENSON.JA Atomic Safety and Licensing Board Panel 84/03/07 7pp. 22615 281 24x Fichs 50-322.84/03/07.8403130107
- B403130174 Motion to strike portions of util Group II-A testimony Testimony neither probative nor matl & unreliable Cartificate of Svc encl Related correspondence MILLER, M S Gréfolk County, NY MILLER, M S Kirkpatrick, Lockhart, Hill, Christopher & Phillips B4/03/09 Atomic Safety and Licensing Board Panel 3Bpp 22599 136 24X Fiche 50-322,84/03/09,8403130174
- 8403170124 Brief in apposition to Suffolk County brief in support of appeal of ASLB partial initial decision & LILCO brief on appeal Certificate of Svc encl BORDENICK, B M , REPKA, D A , Hearing Branch 3 RAWSON, R J Hearing Branch 4 84/03/07 Atomic Safety and Licensing Appeal Panel 145pp 22669,001 24X Fiche 50-322,84/03/07,8403170124
- 8403170127 Interim deficiency rept re failure of turbocharger on emergency standby diesel generator Temporary bypass valve around turbocharger prelube drip line orifice installed W/Certificats of Svc Related correspondence MCCAFFREY, B R Long Island Lighting Co 84/03/09 MURLEY, T E Region i, Office of Director 4pp 22668 252 24X Fiche 50-322,84/03/07,8403170127
- 8403140004 Order establishing schedule for oral argument on ASLS 830921 partial initial decision Arguments will be heard on 840327 in Bethesda, MD SHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel 84/03/12 Office of the Executive Legal Director 3pp 22633 264 24X Fiche 50-322,84/03/12,8403140004
- 8403140005 Order scheduling order of contentions at 840320 hearing re Group I & Group II-A issues Cross-examination plans on first two clusters of Group II-A due 840316 LAUREN8ON, J A Atomic Safety and Licensing Board Panel 84/03/12 Office of the Executive Legal Director 3pp 22633 227 24X Fiche 50-322,84/03/12,8403140005
- 8403150004 Capasition to Governor Cuomo 840308 motion for leave to file 403150004 Opposition to Governor Guomo 840308 motion for leave to rebuttal testimony on Contention 45 re evacuation time estimates Motion fails to establish good cause for filing of rebuttal Related correspondence
 ZEUGIN,L B. Long Island Lighting Co ZEUGIN,L B. Hunton & Williams 84/03/12 Atomic Safety and Licensing Board Panel 15pp 22641 324 24X Fiche 50-322,64/03/12,8403150004
- 8403150026 Response to LILCO & staff objections to Suffolk County
- B403170092 Recommends admittance of Hartgen & Beach rebuttal testimony accompanying State of NY 840309 motion re Contention 65 on evacuation time estimates if testimony found to be unique REPRA.D. A Hearing Branch 3 84/03/15 LAURENSON, J. A. SHON, F. J. KLINE, J. R. Atomic Safety and Licensing Board Panel 2pp 22867 300 24% Fiche 50-322, 84/03/15, 8403190092
- B403190131 Discusses findings & determinations on LILCO transition plan. Key to Regional Assistance Committee (RAC) 840210 review & consolidated RAC review and BPECK, S. W. Federal Emergency Management Agency 84/03/15 DIRCKB, W.J. Office of the Executive Director for Operations 70pp 22668:258 24X Fiche 50-322,84/03/15,8403190131

- 8403190169 Advises that EJ Reis & BM Bordenick will present staff oral arguments on appeals taken from ASLB 830921 Partial Initial Decision LBP-83-57 in proceeding BORDENICK, BM Hearing Branch 3 84/03/15 SHOEMAKER, CJ Atomic Safety and Licensing Appeal Panel 1p 22668 231 24X Fiche 50-322, 84/03/15, 8403190169
- B403200004 Informs of joint agreement w/Suffolk County to defer filing date for testimony on Contention 15 which will result in deferral of testimony on Contention 11 Deferred schedule proposed Related correspondence

 LANPHER, L.C. Kirkpatrick, Lockhart, Hill, Christopher & Phillips t.ANPHER, L.C. Long Island Lighting Co. 84/03/15 LAURENSON, J.A., KLINE, J.R., SHON, F.J. Atomic Safety and Licensing Board Panel 2pp 22685 136 24X Fiche 50-322.84/03/15.8403200004
- 8403200069 Opposition to Buffolk County 840314 request for delay in ABLB ruling on Contention 65. "Rebuttal " Requests either feckless or disingenuous Certificate of Svc encl IRWIN, D P Long Island Lighting Co IRWIN, D P Hunton & Williams TREIN, DP Long Island Lighting Co IRWIN, DP Hunton & 84/03/15 Atomic Safety and Licensing Board Panel App 22685 102 24% Fiche 50~322,84/03/15,8403200069 22695 102
- B403200128 Forwards Complaint 84~4615 filed by Suffolk County for declaratory Judgment concerning implementation of offsite Gerlaratory juagment concerning implementation or arrestee emergency plan Related correspondence
 LANPHER.L C Kirkpatrick, Lockhart, Hill, Christopher & Phillips
 LANPHER.L C Suffolk County, NY 84/03/15 LANRENSON, J.A.,
 KLINE, J.R., SHON, F.J. Atomit Safety and Licensing Soard Panel
 14pp 22699 078 24X Fiche 50-322,84/03/15,8403200128
- 8403200031 Response opposing Suffolk County & State of NY 840309 motions to strike portions of util Group II-A testimony Related correspondence CHRISTMAN, J N Long Island Lighting Co CHRISTMAN, J N Hunto Williams 84/03/16 Atomic Safety and Licensing Board Panel 71pp 22684 001 24X Fiche 50~322,84/03/16,8403200031
- --8403200037 Answer opposing Suffolk County motion to strike testimony of JR Sears Motion has no basis in NRC regulations or case law Certificate of Svc encl CHRISTMAN.J N Long Island Lighting Co CHRISTMAN,J N Hunton & Certificate of Svc encl CHRISTMAN, J N Long Island Lighting Co CHRISTMAN, J N Hunton & Williams 84/03/16 Atomic Safety and Licensing Board Panel 3pp 22684 073 24X Fiche 50-322.84/03/16.8403200031
- 8403200075 Order excluding Contentions ii &15 from Group II-B & amending 840302 order confirming schedule changes to reflect listed dates LAURENSON, J A Atomic Safety and Licensing Board Panel 84/03/16 Suffelk County, NY 2pp 22685 311 24% Fiche 50-322,84/03/16,8403200095
- 8403200131 Response opposing LILCO 840307 motion to strike portions of direct testimony of PB Herr on Contention 22 D re inadequacy of LILCO emergency planning zone Related correspondence MCMURRAY. C M Buffolk County, NY MCMURRAY. C M Kirkpatrick, Lockhart. Hil), Christopher & Phillips 84/03/16 Atomic Safety and Licensing Board Panel 5pp 22678 127 24% Fiche 50-322,84/03/16.8403200131
- --8403200134 Response opposing LILCO 840307 motion to strike direct testimony of RC Roberts, et al.on Contentions 24 T & 59 re ability of Coast Guard to notify public Related aprility of coast orders to notify positive Research
 MCMURRAY, C M Suffolk County, NY MCMURRAY, C M Kirkpatrick,
 Lockhart, Hill, Christopher & Phillips 84/03/16 Atomic Sa
 and Licensing Board Panel 7pp 22698 132 24X
 Fiche 50~322,84/03/16,8403200131
- --8403200136 Memorandum in opposition to LILCO 840309 motion to strike portions of testimony of D Harris & M Mayer on Contentions 24 0 & 75 Related correspondence LETSCHE, K J Suffolk County, NY LETSCHE, K J Kirkpatrick, Lockhart, Hill, Christopher & Phillips 84/03/16 Atomic Safet, and Licensing Board Panel 11pp 22698 139 24X Fiche 50-322,84/03/16,8403200131 Atomic Safetu
- ---8403200140 Response opposing LILCO 840309 motion to strike portions of direct testimony re emergency planning Contention 26 Related correspondence

 MILLER, M S Suffolk County, NY MILLER, M S Kirk,
 Lockhart, Hill, Christopher & Phillips 84/03/16
 and Licensing Board Panel 34pp 22678 150 24X
 Fiche 50-322.84/03/16.8403200131 Atomic Safety
- --8403200145 Response opposing LILCO 840307 motion to strike portions of direct testimony re emergency planning Contentions 28,27,30, 31,32 & 34 Related correspondence MILLER.M S Suffolk County, NY MILLER.M S Kirkpatrick, Lockhert, Hill. Christopher & Phillips 84/03/16 Atomic Safety and Licensing Board Panel 36pp 22698 184 24X Fichs 50-322,84/03/16,8403200131

- --8403200146 Response opposing LILCO 840309 motion to strike portions of direct testimony re emergency planning Contentions 55-38 Related correspondence MILLER, M.S. Suffolk County, NY MILLER, M.S. Kirkpatrick, Lockhart, Hill: Christopher & Phillips 84/03/16 Atomic Safety and Licensing Board Panel 26pp 22698 220 24X Fiche 50-322,84/03/16,8403200131
- --B403200151 Response opposing LILCO 840309 motion to strike portions of Suffolk County Police Dept witnesses testimony on emergency planning Contention 66 Related correspondence MCMURRAY.C M Suffolk County, NY MCMURRAY.C.M Kirkpatrick, Lockhart, Hill. Christopher & Phillips 84/03/16 Atomic Safety and Licensing Board Panel 6pp 22698 246 24X Fiche 50-322,84/03/16,8403200131
- --8403200155 Response opposing LILCO 840309 motion to strike portions of State of NY testimony on Contentions &6 D.67.73 & 97 B Related correspondence MCMURRAY.C M Suffolk County, NY MCMURRAY.C M Kirkpatrick, Lockhart, Hill, Christopher & Phillips 84/03/16 Atomic Safety and Licensing Board Panel 2pp 22478 252 24X Fiche 50-322,84/03/16,8403200131
- --8403200159 Memorandum in apposition to LILCO 840309 motion to strike portions of testimony of S Basgert on Contention 73 A Certificate of Svc enci Related correspondence LETSCHE,K Suffolk County, NY LETSCHE,K Kirkpatrick, Lockhart, Hill. Christopher & Phillips 84/03/16 9pp 22698 254 24X Fiche 50-322,84/03/16,8403200131
- B403210098 Forwards NRC Region I morning repts for 840302-16 re emergency diesel generators Related correspondence G00DARD:R J Hearing Branch 3 84/03/16 BRENNER,L . MORRIB.P A , FERGUSDN.G A Atomic Safety and Licensing Board Panel 36pp 22706 054 24% Fiche 50-322.84/03/16.8403210098
- 8403210100 Responses to applicant, Buffolk County & State of NY 840309 motions to strike portions of Group II-A testimony Certificate of Svc encil Related correspondence BORDENICK, B M , REPKA, D A Hearing Branch 3 84/03/16 Atomic Safety and Licensing Board Panel 17pp 22706 100 24x Fiche 50-322,84/03/16,8403210100
- B403210104 Response denying Suffolk County B40307 motion to strike testimony of JR Sears re emergency preparedness Contentions 26 A-26 C D 26 D Certificate of Svc encl Related correspondence REPKA, D A Hearing Branch 3 84/03/16 Atomic Bafety and Licensing Board Panel 7pp 22705 128 24X Fiche 30-322,84/03/16.
- 8403210150 Memorandum & order denying State of NY B40308 mption for leave to file rebuttal testimony on Contention 65 re evacuation time estimates LAURENBON, J A Atomic Safety and Licensing Board Panel 84/03/16 7pp 22707 091 24% Fische 50-322.84/03/16.8403210150
- 8403210179 Response of Governor Cuamo in opposition to util 840309 motion to strike portions of TD Gibbons direct testimony on Contentions GG D & 97 B Certificate of Svc encl Related correspondence
 ZAHNLEUTER, F. New York, State of DSB 008 84/03/16 Atomic Safety and Licensing Board Panel 7pp 22710 091 24X
 Fiche 50-322,84/03/16,8403210179
- 84032:0188 Response in opposition to LILCO 840309 motion to strike portions of direct testimony of MJ Aquario, RD Albertin & RO Knighton re Contention 73 Certificate of Svc encl Related correspondence
 ZAHNLEUTER, R J New York, State of DSG 007 84/03/16, Atomic Safety and Licensing Board Panel 7pp 22710 084 24X Fiche 50-322, 84/03/16,8403210188
- 8403210201 Response in opposition to util 840309 motion to strike portions of WJ Acquario, et al testimony on amergency planning Contention 67 W/Certificate of 8vc Related correspondence ZAWNLEUTER, R. J. New York, State of DSD 009 84/03/16 Atomic Safety and Licensing Board Panel 7pg 22710 072 24X Fiche 50-322,84/03/16,8403210201
- 8403210083 Order ruling on Suffolk County 840213 motion for leave to file new contentions re LILCO offsite emergency preparedness training program

 LAURENSON J A Atomic Safety and Licensing Board Panel 94/03/19
 Suffolk County, NY 20pp 22705 166 24X Fiche 50-322, 84/03/19, 8403210083

- B403210186 Informs that LC Lampher will present oral argument at B40327 appeal hearing KJ Letsche may also appear on behalf of Suffolk County Related correspondence LAMPHER, L C Kirkpatrick, Lockhart, Hill, Christopher & Phillips LAMPHER, L C Suffolk County, NY D88 022 B4/03/19 SHOEMAKER, C J Atomic Safety and Licensing Appeal Panel ip 22718 226 24X Fiche 50-322,84/03/19,8403210186
- 9403210177 Forwards supplemental motion for low power OL & supporting unsecuted affidavits EARLEY.A F Long Island Lighting Co 84/03/20 BRENNER.L. NORRIB.P A , FEROUSON,G A Atomic Safety and Licensing Board Panel 1p 22709 240 24X Fiche 50-322,84/03/20,8403210177
- --8403210181 Supplemental motion for low power OL Unexecuted affidavits of JA Notaro, MG Schiffmacher, GG Sherwood, AS Rao & EC Eckert enci Certificate of Svc also encl REVELEY, W T Lung Island Lighting Co REVELEY, W T Hunton & Williams 84/03/20 Atomic Bafety and Licensing Board Panel 108pp 22709 241 24X Fiche 50-322,84/03/20,8403210177
- 8403220250 Response opposing LilCO 840301 request for production of documentation Certificate of Svc encl Related correspondence DYNNER.A R Suffolk County, NY DYNNER.A R Kirkpatrick, Lockhart, Hill, Christopher & Phillips DSB 050 84/03/20 Atomic Safety and Licensing Board Panel 13pp 22719 097 24X Fiche 50-322,84/03/20,8403220250
- 8403230010 Forwards concerns raised in HH Brown 840301 ltr re design review/quality revalidation now under de facto control & direction of LLCO Design review should be stopped & genuinaly independent review instituted PALOMINO.F O New York, State of 84/03/21 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 22730 131 24X Fiche 50-322,84/03/21,8403230010
- B403230013 Forwards Certificate of SVC for listed testimony on emergency planning contentions Related correspondence NCCLEBKEY.K E Hunton & Williams MCCLEBKEY.K E Long Island Lighting Co DSS 061 84/03/21 LAURENSON.J A . KLINE, J R . SHON.F J Atomic Safety and Licensing Board Panel 5pp 22727 352 24X Fiche \$0-322.84/03/21.8403230013
- B403270074 Response to request for production of documents Certificate of Svc encl Related correspondence RDLFE.R M Long Island Lighting Co DBB 106 B4/03/21 Suffolk County, NY 54pp 22766 170 24X Fiche 50-322,84/03/21,8403270074
- 8403270197 Forwards supplemental motion for low power QL MCCAFFREY.B R Long Island Lighting Co 84/03/21 DENTON.H R Office of Nuclear Reactor Regulation. Director 1p 22770,293 24X Fiche 50-322.84/03/21,0400270197
- 8403280336 Notifies that proposed rulemaking re "Applicability of App A to App B" will be deleted from regulatory agenda Related correspondence REIB.E J Hearing Branch 3 DSB 154 B4/03/22 ROBENTHAL, A B, EDLES, G J, WILLIER, H A Atomic Bafety and Licensing Appeal Panel 3pp 22787 210 24x Fiche 50-322.84/03/22.8403280356
- 8403280340 Advises that staff may rely on ALAB-763 as corroborating certain NRC positions set forth in 840309 brief Relevant portions of brief to be further discussed at oral argument are Part II A & B & Part IV Related correspondence BORDENICK: B M Hearing Branch 3 DSB 153 84/03/23 SHOEMAKER: C J Atomic Baftly and Licensing Appeal Panel 1p 22787 099 24% Ficho 50-322,84/03/23,8403280340
- 8403280362 Advises that possibility of ASLB proposal to electronically transmit info & selected documents within context of proceeding re diosel generators still under consideration Related correspondence BORDENICK, B M Hearing Branch 3 DSB 152 84/03/23 BRENNER, L, FERCUBON, G A, MORRIS, P A Atomic Safety and Licensing Board Panel ip 22787 234 244 Fiche 50-322, 84/03/23, 8403280362.
- B403270292 Motion to strike direct testimony of CV Failla on behalf of NY State re Contention 24 F 2 Agreement re notice of & discovery on intended testimony not complied with Gertificate of Svc encl Related correspondence IRWIN.D P Long Island Lighting Co IRWIN.D P Hunton & Williams DBB 127 B4/03/24 Atomic Safety and Licensing Board Panel 13pp 22789 036 24X Fiche 50-322.84/03/24.8403270292
- 8403270275 Forwards BR McCaffrey 840313 itr to HR Denton & TS Ellis 840312 itr to Dircks re meaning of term important to safety in NRC regulations Related correspondence REIS.E J Hearing Branch 3 DSB 128 84/03/26 ROSENTHAL, A S . EDLES. 6 J . WILBER H A Atomic Safety and Licensing Appeal Panel 7pp 22787 047 24X Fiche, 50-322,84/03/26,8403270275

- B403280346 Motion to establish regular daily hearing schedule Hearing day from Yem to 5pm reasonable & sufficiently long Certificate of Svc encl LETSCHE, K J Kirkpatrick, LOCKhart, Hill, Christopher & Phillips DSB 163 84/03/26 Atomic Bafety and Licensing Board Panel 5pp 22787 122 24X Fiche 50-322,84/03/26,8403280346
- 8403280357 Forwards Suffolk County cross-examination plans for Cluster 3 & Cluster 4 M/o encl Related correspondence LETSCHE, K J Kirkpatrick, Lockhart, Hill, Christopher & Phillips LETBCHE, K J Buffolk County, NY DSB 156 84/03/26 LAURENBON, J A, KLINE, J R, SHON, F J Atomic Safety and Licensing Board Panel 1p 22787 213 24X Fiche 50-322,84/03/26.8403280357
- 8403280358 Preliminary views on scheduling re util 840320 supplemental motion for low power OL Motion entirely new & seeks to circumvent litigation on adequacy of emergency diesel generators Certificate of Svc encl 8CHEIDT, D J Suffolk County, NY SCHEIDT, D J Kirkpatrick, Lockhart, Hill, Christopher & Phillips DSB 164 84/03/26 15pp 22787 214 24X Fiche 50-322.84/03/26.8403280338
- 8403290179 Forwards LILCD plan for cross-examination of KJ Regensburg, RA Snow & VR Stile on Contentions 34 & 28-32 re communications among emergency response personnel W/o plan W/Certificate of Svc Related correspondence SISK, K D Hunton & Williams SISK, K D Long Island Lighting Co DBB 179 84/03/26 LAURENSON, J A, KLINE, J R, SHON, F J Atomic Safety and Licensing Board Panel 4pp 22803 322 24X Fichs 50-322,84/03/26,8403290179
- 8403280350 Order approving settlement of portion of Suffolk County Contention II re passive mechanical valve failure Served on 840327 BRENNER, L Atomic Safety and Licensing Board Panel DSB 149 84/03/27 Suffolk County, NY Zpp 22787 146 24X Fiche. 50-322, 84/03/27, 8403280350
- 8403290377 Supplemental memorandum opposing util summary disposition mutions on Contentions 24 B.33.45.46 & 49 Certificate of Svc snc1 Related correspondence LETSCHE,K J Suffolk Gounty, NV LETSCHE,K J Kirkpatrick, Lockhart, Hill, Christopher & Phillips DSB 196 B4/03/27 Atomic Safety and Licensing Board Panel 19pp 22814 123 24X Fiche 50-322.84/03/27,8403290377
- 8403290390 Motion to remove Contention 77 from Cluster 3 & to reinsert Contention 77 into hearing schedule at later date Certificate of 8vc encil LETBCHE.K Suffolk County, NY LETSCHE.K Kirkpatrick. Lockhart, Hill, Christopher & Phillips DBB 197 84/03/27 Atomic Safety and Licensing Board Panel 10pp 22814 312 24% Fiche.50-322.84/03/27.8403290390
- B403300256 Motion to strike portions of Group II-B testimony of Suffolk County Certificate of Svc encl Related correspondence CHRISTMAN, J N Long Island Lighting Co CHRISTMAN, J N Hunton & Williams DSB 214 B4/03/27 Atomic Safety and Licensing Board Panel 38pp 22824 078 24X Fiche 50-322, B4/03/27, B403300256
- B403300277 Suppl to motion for summary disposition of Contentions 24 B,33.45.46 & 49 No genuine issue of matl fact exists & util entitled to favorable decision W/Certificate of Svc Related correspondence MCCLESKEY, K E Long Island Lighting Co MCCLESKEY, K E Hunton & Hilliams DSB 224. 84/03/27 Atomic Safety and Licensing Board Panel lipp 22824 020 24X Fiche 50-322,84/03/27,8403300277
- 8403290373 Order confirming schedule for staff answer to LILCO 840320 supplemental motion for low power OL Courtesy notification and I.

 BRENNER,L Atomic Safety and Licensing Board Fanel DSB 185 84/03/28 Office of the Executive Legal Director 4pp 22814.087 24X Fichs 50-322.84/03/28.8403290373
- B403270383 Motion to strike portions of util Group II-B testimony as irrelevant nonprobetive & incompetent Certificate of Svc encl. Related correspondence LET9CHE, K J. Suffolk County, NY LETSCHE, K J. Kirkpetrick, Lockhart, Hill, Christopher & Phillips D58 168 B4/03/28 Atomic Safety and Licensing Board Fanel 76pp. 22814 164 24X Fiche 50-322,84/03/28,8403270383
- J. Insurance & indemnity information
- 8403140003 Forwards Endorsements 11 & 12 to NELIA Policy NF-269 ROBBING, J @ Marsh & McLennan, Inc 84/03/05 DINITZ, I Assistant Director for State & Licensee Relations 3pp 22633 232 24X Fichs 50-322,84/03/05,8403140003

- Q Inspection reports, IE Bulletins & correspondence
- 8403010381 Forwards IE Insp Rept 50-322/84-01 on 840102-13 & notice of violation STAROSTECKI.R Division of Project & Resident Programs 84/02/16 POLLOCK.M S Long Island Lighting Co 2pp 22434 072 24X Fiche 50-322,84/02/16,8403010381
- --8403010382 Notice of violation from insp on 840102-13 * Region 1, Office of Director 84/02/16 lp 22434 074 24X Fiche 50-322,84/02/16.8403010381
- --B403010370 IE Insp Rept 50-322/B4-01 on B40102-13 Violation noted reassembly of emergency diesel generator 101 nat prescribed by & accomplished in accordance w/appropriate procedure PETRONE.C Region 1. Office of Director MCCABE.E C Division of Project & Resident Programs B4/01/16 App 22434 075 24X Fiche 50-322, B4/02/16, B4030103B1
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Mator Operated Valve Control Circuits & Annunciation " Svc list enc! JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22909 239 24X Fiche 50-000.84/02/28.8401190072
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list enc! GRACE, J N Division of GA. Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24% Fiche 50-000.84/03/02.8402090007
- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Syc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fichs 50-000,84/03/02,8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases" Svc list encl
 JURDAN.E. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 94/03/02 Consolidated Edison Co of New
 York, Inc 119pp 22553 217 24X Fiche 50-000.84/03/02.8402090009
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Coaling Components Below Nij Ductility Temp " Svc list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402070011
- 8403220143 Forwards IE Insp Rept 50-322/84-02 on 840123-0226 No violations found STARDSTECKI.R Division of Project & Resident Programs 84/03/06 POLLOCK.M S Long Island Lighting Co 2pp 22714 317 24X Fiche 50-322.84/03/04.8403220143
- --8403220160 IE Insp Rept 50-322/84-02 on 840123-0226 No violations found Major areas inspected, IE Bulletin 80-07 (Betail 3).7MI action items, review of emergency diesel generator testing & previously identified insp findings PETRONE, C., SHEDLOSKY, T., MCCABE, E.C., Region 1, Office of Director 84/02/28 10pp 22714 319 24X Fiche 50-322,84/03/06,8403220143
- 8402090024 IE info Notice 84-09, Rev 1, "Lessons Learned From Insps of Fire Protection Safe Shutdown 8ys " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fichs 50-000, 84/03/07, 8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR 8ys " 8yc list encl JORDAN,E L Division of Embragency Preparedness & Engineering Response (Post 830103) 84/03/07 Consultdated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8402090031 IE Bulletin 84-02, "Failures of OE Type HFA Relays in Use in Class IE Safety Sys " Syc list encl
 DEYQUNOR C Director's Office Office of Inspection and
 Enforcement 84/03/12 Consolidated Edison Co of New York, Inc
 134pp 22823 094 24X Fiche 50-000,84/03/12,8402090031
- 8403290387 Forwards Tech Spec-related SALP input for Feb 1983 Feb 1984, in response to R Caruso 840305 memo Bařeguards-related input will be sent directly to R Caruso by Bařeguards Licensing Branch Category 2 assigned for mgt involvement. THOMAS, C O Standardization & Special Projects Branch 84/03/13 SCHMENCER. A Licensing Branch 2 4pp 22823 090 24X Fiche 50-322,84/03/13,8403290387

- 8403300072 Forwards IE Insp Rept 50-322/84-03 on 840118-20 & 0209-11 No
- violations noted
 MARTIN T T Division of Engineering & Technical Programs 84/03/16
 POLLOCK, M S Long Island Lighting Co 2pp 22822 092 24X
 Fichs 50-322.84/03/16.8403300072
- --B403300076 IE Insp Rept 50-322/84-03 on 840118-20 & 0209-11 No violations noted Major areas inspected licensee preliminary site activities in preparation for const of new emergency diesel generator bldg VARELA, A A . DURR. J P Region 1, Office of Director 84/03/07 Jpp 22822 094 24K Fichs 50-322-84/03/16-8403300072
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list ent! JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 123pp 22823 227 24X Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84-20. "Svc Life of Relays in Safety-Related Sys "Svc list encl JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 135pp 2293 001 24X Fiche 50-000,84/03/21,8402090044
- R Periodic operating reports & related correspondence
- 8403020443 Forwards monthly status rept of offsite emergency preparedness for OL reviews for Jan 1984 Changes in FEMA finding dates not caused by delay due to offsite emergency planning issues
 DIRCKS.W J Office of the Executive Director for Operations
 84/02/21 PALLADINO Commissioners 9pp 22492 083 24X
 Fiche 50-000.84/02/21.8403020443
- 8403270119 Forwards monthly status "List of Active Safety-Related Equipment at Qualification Level," per SER Issue 9 redynamic qualification
 MCCAFFREV. B R Long Island Lighting Co 84/03/15 DENTON.H R
 Office of Nuclear Reactor Regulation. Director 2pp 22774 068
 24X Piche 50-322.84/03/15.8403270119
- --8403270122 "Control Bidg Category I Equipment Balance-of-Plant Qualifacation Level." monthly status rept * Stone & Webster Engineering Corp 84/02/27 50pp 22774 064 24X Fiche 90-322.84/03/15.8403270119
- S Repartable occurrences. LERs & related correspondence
- 8403010451 Informs Commission of problems w/emergency diesel generators mfg by Transamerica Delaval. Inc Director for Operations SECY-83-034 84/01/25 4pp 22438 347 24X Fiche 30-000.84/01/25.8403010451
- 8403010207 Forwards "Investigation of Types AF & AE Piston Bkirts," per Transamerica Belaval. Inc Dwners Group program commitments Rept evaluates cracks in AF piston skirts in Shoreham & Grand Gulf Nuclear Power Stations MUSELER. H. J. TDI (Transamerica Delaval, Inc.) Dwners Group MUSELER. H. J. Long Island Lighting Co. 84/02/27 DENTON, H. R. Diffice of Nuclear Reactor Regulation. Director 3pp. 22434 070 24X Fiche 50-000,84/02/27.8403010207
- --8403010446 "Investigation of Types AF & AE Piston Skirts "
 * Failure Analysis Associates FAAA-84-2-14 84/02/27 83pp
 22434 093 24X Fiche 50-000.84/02/27.8403010207
- 8402090021 Board Notification 84-039 discusses NRC 840210 & 16 meetings w/Transamerica Delaval, Inc Emergency Diesel Generators Gumers Group Meeting scheduled on 840308 for finalization of generic program plan prior to NRC review ETSENHUT, D 0 Division of Licensing 84/02/28 PALLADING, GLLIESKY, ROBERTS Commissioners 5pp 22346 003 24X Fiche 50-000.84/02/28,8402090021
- 8403010218 Forwards task descriptions for 16 known problems re Transamerica Delaval. Inc. smorgency diesel generators MUSELER, H. J. TDI (Transamerica Delaval. Inc.) Owners Group 84/02/28 DENTON.H.R. Office of Nuclear Reactor Regulation, Director 42pp 22435 177 24X Fiche 50-000.84/02/28.8403010218
- 8403260233 Forwards summary list of deficiencies identified per 100FR50 55(e), Part 21 & patential generic ltr repts for comments
 STAROSTECKI.R Division of Project & Resident Programs 84/
 - conservs
 STARDSTECKI,R Division of Project & Resident Programs 84/02/28
 Region 1. Office of Director 7pp 22736 065 24x
 Fiche 50-000,84/02/28.8403260233

- B402090020 Board Notification B4-044 forwards Part 21 rept re Transamerica Delaval. Inc turbocharger thrust bearing lubrication defect resulting in angine nonavailability EIEENHUT.D 0 Division of Licensing 84/02/29 PALLADING, 01LINSKY, RODERTS Commissioners 4pp 22541 263 24X Fiche 50-000.84/02/29.8402090020
- 840306033B Advises of problem compromising integrity of design review/ quality revalidation of emergency diesel generators mfg by Transamerica Delaval. Inc Util involvement in review represents conflict of interest BROWN. H H Kirpatrick, Lockhart, Hill, Christopher & Phillips BROWN. H H Kirpatrick, Lockhart, Hill, Christopher & Phillips BROWN. H H Suffolk County, NY 84/03/01 DENTON. H R Office of Nuclear Reactor Regulation, Director opp 22519 088 24X Fiche 50-322,84/03/01.8403060388
- B40314004B Forwards "Grand Gulf Component Tracking Bys," "Shoreham Component Tracking Sys" & "Transamerica Delaval, Inc Diesel Generators Owners Group Program Plan," to resolve concerns w/emergency diesel generators MUSELER, H J Long Island Lighting Co 84/03/02, DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22626-062-24X Fiche 50-000,84/03/02,840314004B
- --B403140080 "Grand Gulf Component Tracking Sys " * Long Island Lighting Co. 84/02/29 B79pp 22626 064 24X Fiche 50-000, 84/03/02, 8403140048
- --8403140091 "Shoreham Component Tracking Sys "

 * Long Island Lighting Co 84/02/27, 516pp 22627.069 24X
 Fithe 50-009,64/03/02,8403140048
- --8403140095 "Transamerica Delaval, Inc Diesel Generators Owners Group Program Flam " * TDI (Transamerica Delaval, Inc) Owners Group 84/03/02 261pp 22628 223 24X Fiche 50-000.84/03/02.8403140048
- 8402090033 Board Notification 84-047 forwards Transamerica Delaval inc Owners Group piston stirt rept & task descriptions ETSENHUT, D.G. Division of Licensing 84703/07 PALLADINO, GTLINSHY, ROBERTS Commissioners 4pp 22674 221 24X Fiche 50-000,84/03/07,8402090033
- 8403190127 Interim deficiency rept re failure of turbocharger on amergency standby diesel generator Temporary bypass valve around turbocharger prelube drip line orifice installed W/Certificate of Svc Rolated correspondence MCCAFFREY.9 R Long Island Lighting Co 84/03/09 MURLEY.T E Region I, Office of Director 4pp 22669 252 24X Fiche 50-322.84/03/09.8403190127
- 8402070035 Board Notification 84-053 forwards "Emergency Dissel Generator Component Tracking Bys." Facility component data base for design review & quality revalidation effort of Transamerica Delaval Guners Group program plan CISENHUT.D 0 Division of Licensing 84/03/12 PALLADIND, GILINEKY, ROBERTS Commissioners 4pp 67218 079 24% Fiche 50-322.84/03/12.8402070035
- --8403190385 "Emergency Diesel Generator Component Tracking Bys "
 * TDI (Transamerica Delaya), Inc.) Guners Group 84/02/29, 515pp 22475-322 24% Fichs 50-322-84/03/12.8402090035
- B40207003B Board Notification B4-051 forwards "Trensamerica Delayal, inc (TDI) Diesel Generators Owners Group Program Plan " EIBENHUT.D G Division of Licensing B4/03/12 PALLADING, GILINGKY, RODERTS Commissioners 5pp 226BB 214 24X Fiche 50-000, B4/03/12, B40209003B
- --8403200143 "Transamerica Delaval (TDI) Diesel Generators Gwners Group Pregram Plan " * TDI (Transamerica Delaval, Inc.) Gwners Group 84/03/12 261pp 26688 219 24% Fiche 50-322,84/03/12,8402090038.
- 8402070037 Board Notification 84-032 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delaval.Inc (TDI) Duners Group Distribution list enci EISENHUT.D 0 Division of Licensing 84/03/12 PALLADING, GILINEKY, ROBERTS Commissioners 3pp 22708 001 24X Fiche 50-000.84/03/12.8402070037
- --8403060536 Forwards summary of 840210 meeting W/Transamerica Delaval.
 Inc Dumers Group in Bethesda.MD re problems w/emergency
 diesel generators
 CARUSG,R Licensing Branch 2 84/02/27 O'REILLY, J.P. NRC No
 Detailed Affiliation Given Opp 22708 006 24X
 Fichs 50-000,84/03/12,8402090039

- --8403060554 Transcript of 840210 meeting u/Transamerica Delaval.Inc Owners Group in Bethesda.MD re problems w/emergoncy diese1 generators NRC - No Detailed Affiliation Given 84/02/10 147pp 708 012 24X Fiche 50-000,84/03/12.8402090039 22708 012
- --8403070407 Summary of 840216 meeting w/Transamerica Delaval, Inc Owners Group in Wading River, NY re program plan to establish reliability of diesel generators Agenda, meeting transcript & attendance list encl
 MILLER, MA Licensing Branch 4 84/02/27 Licensing Branch 4
 8pp 22708 161 24X Fiche 50-000.84/03/12,8402090039
- --8403070423 Transcript of 840216 conference in Wading River, NY re Transamerica Delaval, Inc diesei generators Pp 1-82
 * Commissioners 84/02/16 84pp 22708 169 2:
 Fiche 50-000, 84/03/12, 8402090039
- B403140050 Forwards "Design Review of Connecting Rod Bearing Shells for Transamerica Delaval Enterprise Engines" for Shoreham & Grand Gulf diesel generators
 MUBELER,W J Long Island Lighting Co 84/03/12 DENTON,H R
 Office of Nuclear Reactor Regulation, Director 2pp 22632 074
 24X Fiche 50-000,84/03/12,8403140050
- --8403140086 "Design Review of Connecting Rod Bearing Shells for Transamerica Delaval Enterprise Engines " * Failure Analysis Associates PAO 7396, 84/03/12 51pp 22632 076 24X Fiche 50-000.84/03/12,8403140030
- B403150133 Forwards "Transamerica Delaval, Inc Diesel Generator Rocker Arm Capscrew Stress Analysis Rept " Capscrew design adequate for applicable angines & svc conditions MUSELER, W J TDI (Transamerica Delaval, Inc.) Owners Group MUSELER, W J Long Island Lighting Co 84/03/13 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 22639 270 24% Fichs 50-000,84/03/13,8403150133
- ---BA03150154 "Emergency Diesel Generator Rocker Arm Capscrew Stress Analysis," prapared for Transamerica Delayal, Inc Owners Group
 - Stone & Webster, Inc. 84/03/31 27pp 22639 272 24X Fiche 50-000, 84/03/13, 8403150133
- 8403190285 PNO-I-84-025 on 840313 licensee found crack in emergency diesal generator 103 engine block between cylinders 4 & 5 Grack being investigated through use of eddy current insp
 - Techniques
 PETRONE, C. . ESELGROTH, P. Region 1. Office of Director 84/03/14
 1p. 22672 278 24X Fiche 50-322.84/03/14.8403170285
- 8403200222 Responds to 840214 Requests for Info 1 & 2 re R-4 series engines List indicating engine number, model & syc number, customer name & address, rating, date shipped & date sterted
- MATHEMB, C S Transamerica Delaval, Inc 84/09/16 EISENHUT, D G Division of Licensing 20pp 22691 179 24X Fiche 50-000,84/03/16,
- 8403230094 PNO-1-84-026 on 840313, crack discovered in emergency dissel generator engine. Ultrasonic & eddy current exam indicated crack depth of 1 inch & length of 2 inches State of NY informed ONE,C , ESELOROTH, P 22724,345 24X Fic GROTH, P Region 1, Office of Director 84/03/20 24X Fiche 50-322,84/03/20,8403230094 PETRONE, C
- 8403270132 Forwards "Emergency Diesel Generator Air Start Valve Capscrew Dimension & Stress Analysis," prepared by S&W for Transamerica Delaval, Inc. (TDI) Diesel Generator Owners Prospective Services Control of C 22774 001
- --8403270157 "Emergency Dissel Generator Air Start Valve Capscrew Dimension & Stress Analysis," prepared for Transamerica Delaval. Inc (TDI) Dissel Generator Owners Group * Stone & Webster Engineering Corp 84/03/31 23pp 22774 003 24X Fiche 50-000.84/03/23,8403270132
- B403270134 Requests meeting on 840418 to discuss short-term & long-term corrective actions & investigations re Transamerica Delayal diesel generators List of suggested meeting topics MCGAUGHY, J.P. TDI (Transamerica Delaval, Inc.) Gwners Group MCGAUGHY, J.P. Mississippi Power & Light Co. 84/03/23 DENTON, H Office of Nuclear Reactor Regulation, Director 4pp. 22769, 133. DENTON: H R 24% Fiche 50-000,84/03/23,8403270134

- B403300170 Requests that Transamerica Delaval, Inc diesel review program AUSIONI/O Nequests that Transamerica Delaval, inc disselbe stopped promptly due to improper role of util in directing review New Independent review should be established, in consultation w/Suffolk County ONES, F Suffolk County, NY 84/03/23 DENTON, H R Nuclear Reactor Regulation. Director 20p 22820 047 Office of Fiche 50-322,84/03/23,8403300170
- T Hearing transcripts on non-antitrust matters
- 8403010244 Surrebuttal testimony of DS Mileti & JH Sorensen on Contention 23 re shadow phenomenon Related correspondence MILETI, D S , SORENSON, J H Suffolk County, NY 84/02/27 38pp 22404 219 24% Ficha 50-322,84/02/27,8403010244
- 8403060212 Forwards testimony on behalf on Governor Cuomo re Contentions 66 D.67.73 & 97 B Related correspondence ZAHNLEUTER: R J New York, State of 84/03/01 LAURENSON, J A KLINE, J R , SHON, F J Atomic Safety and Licensing Board Panel 22517 231 24x Fiche 50-322.84/03/01.8403060212 LAURENSON, J A
- --B403060226 Testimony of WJ Acquario.RD Albertin & RG Knighton re emergency planning Contention 67, "Evacuation of Persons W/o Access to Automobiles " Related correspondence ACGUARIO.W J. ALBERTIN.R D. KNIGHTON.R G. New York, Btate of B4/03/01 50pp 22517 232 24X Fiche 50-322,84/03/01.8403060212
- -B403060246 Testimony of MJ Acquario.RD Albertin & RO Knighton re emergency planning Contention 73. "Evacuation of Handicapped Persons Not in Special Facilities" Related correspondence ACQUARIO.M J . ALBERTIN.R D . KNIGHTON.R G New York. State of B4/03/01 13pp 22517 285 24X Fiche 50-322.84/03/01.8403060212 13рр
- --8403060252 Testimony of TD Gibbons re emergency planning Contention 66 D. "Agreements for Snow Removal" & emergency planning Contention 97 B. "Evacuation During Deep Snow " Certificate of Bvc encl Related correspondence GIBBONS,T D New York. State of 84/03/01 14pp 22517 298 24X Fiche 50-322,84/03/01,8403060212
- 8403060254 Forwards Suffolk County testimony on listed Group II contentions Remaining contentions will be addressed by cross-examination Contention 51 withdrawn Related correspondence COTTESPONGENCE
 LETBCHE, K J Kirkpatrick, Lockhart, Hill, Christopher & Phillips
 LETBCHE, K J Suffolk County, NY 84/03/02 LAURENSON, J A .
 KLINE, J R , SHON, F J Atomic Safety and Licensing Board Panel 1p
 22514 001 24X Fiche 50-522,84/03/02.8403040254
- ---8403060259 Direct testimony of PB Herr on emergency planning Contention 22 D re inadequacy of LILCO emergency planning zone Related correspondence
 HERR, P B Suffolk County, NY 84/03/02 21pp 22514 002 24X
 Fiche 50-322,84/03/02.8403060254
- --8403040266 Direct testimony of KJ Regensburg,RA Snow & VR Stile on emergency planning Contentions 20 & 55-58 re notification of public Related correspondence REGENSBURG,K J, SNOM,R A, STILE,V R Suffolk County, NY 84/03/02 28pp 22514 023 24X Fiche 50-322,84/03/02,8403060254
- --8403060270 Direct testimony of KJ Regensburg.RA Snow t VR Stile on emergency planning Contention 26 re notification of emergency response personnel Related correspondence REGENBBURG.K J. SNOM.R A. BITLE.V R. Buffolk County, NY 84/03/02 76pp 22514 051 24X Fiche 50-322.84/03/02.8403060254
- -8403060278 Direct testimony of KJ Regensburg.RA Bnow & VR Stile an emergency planning Contentions 28,29,30,31,32 & 34 re communications among emergency response personnel Related correspondence REGENSBURG, K. J. SNOW, R. A., STILE, V. R. Suffolk County, NY 84/03/02 45pp 22514 127 24X Fiche 50-322,84/03/02,8403060254
- --8403060289 Direct testimony of JL Monteith.RC Roberts.P McGuire. MJ Turano.EJ Michel & PB Herr on emergency planning Contention 27 re-mobilization of emergency response personnel Related correspondence MONTEITH.J L. ROBERTS,R C. MCGUIRE.P Suffolk County, NY 84/03/02 146pp 22514 172 24X Fiche 50-322,84/03/02, 8403060254
- -8403060295 Direct testimony of JL Monteith.RC Roberts,P McQuire. MJ Turano & E.J Michel on emergency planning Contention 66 rs removal of obstacles from roadway & provisions for fuel Related correspondence MONTETHIJL, ROBERTS, R.C., MCGUIRE, P. Suffolk County, NY 84/03/02 32pp 22514 318 24X Fiche 50-322,84/03/02,8403060254

- ---B403060301 Direct testimony of RC Roberts DA Hoffman & JJ Read on smargency planning Contentions 24 T & 59 re notification to public by US Coast Guard Related correspondence ROBERTS.R C , HOFFMAN D A . READ.J J Buffolk County NY B4/03/02 15pp 22514 350 24X Fiche 50-322.84/03/02 B403060254
- ---8403060307 Direct testimony of PB Herr & EJ Michel on Contentions 67 & 24 I re evacuation of persons w/o access to automobiles & lack of agreements w/transfer point owners Related correspondence
 HERR.P D : MICHEL E J : HERR.P B Suffolk County, NY 84/03/02
 47pp 22515 004 24X Fiche 50-322,84/03/02,8403060284
- --8403040310 Direct testimony of D Harris & M Mayer re Contentions 24 G. 24 K.24 P.73 & 75 Related correspondence HARRIS, D. MAYER.M Suffolk County, NY 84/03/02 33pp 22515 053 24% Fiche 50-322,84/03/02.8403040254
- --8403060314 Direct testimony of S Sangert on emergency planning Contention 73 A re evacuation of homobound Related correspondence SAEGERT, S Suffolk County, NY SAEGERT, S New York Univ. New York, NY 84/03/02 9pp 22515 086 24X Fiche 50-322,84/03/02, 8403060254
- ---8403060318 Direct testimony of RT Kreiling on Contention 24 O Related correspondence MREILING: R T Suffolk County, NY 84/09/02 3pp 22515 095 24X Fiche 50-322.84/03/02.8403060254
- --B403060319 Direct testimony of RC Roberts on emergency planning Contention 74 re inappropriate proximity of proposed relocation ctrs Related correspondence ROBERTS.R C Suffolk County, NY B4/03/02 App. 22515 098 24x Fache 50-322,84/03/02.8403060254
- --B403060322 Direct testimony of PF Cosgrove & JL Fakler on emergency planning Contention 24 S re lack of agreements on emergency response training of non-LILCO personnel Certificate of Bvc encl Related correspondence COSGROVE.P F , FAKLER.J L Suffolk County, NY 84/03/02 16pp 22515 102 24X fiche 50-322.84/03/02.8403060254
- B403070147 Forwards listed testimonies on emergency planning issues
 Related correspondence
 MCCLESKEY, K E Harmon & Weiss MCCLESKEY, K E Long Island Lighting
 Co B4/03/02 LAURENSON, J A, SHON, F J, KLINE, J R Atomic Safety
 and Licensing Board Panel 3p 22342 001 24X
 Fiche 50-322.84/03/02.8403070147
- --8409070150 Testimony of CA Clauson, MC Cordaro & CA Daverio on Phase II emergency planning Contention 20 re walk radio broadcasting at night CLAMSON, C A CORDARO, M C . DAVERIO, C A Long Island Lighting Co 84/03/02 49pp 22542 006 24% Fithe 90-322,84/03/02,8403070147
- --8403070154 Testimony of CA Clawson, NC Cordaro & CA Daverio on Phase II emergency planning Contentions 21 & 21 C re Spanish translation of public info CLAMSON, C A. CORDAROM C . DAVERID, C A. Long Island Lighting Co 84/03/02 45pp 22542 056 24X Fiche 50-322,84/03/02,8403070147
- --8403070158 Testimony of MC Cordaro, CA Daverio, EB Lieberman & JA Heismantis on Phase II emergency planning Contention 22 re expansion of emergency planning zone boundary CORDARO, M C , DAYERIO, C A , LIEBERMAN, E B Long Island Lighting Co 84/03/02 60pp 22542 103 24x Fiche 50-322, 84/03/02, 8403070147
- --8403070160 Testimony of MC Cordard, JA Weismanthe & ED Robinson on Phase II emergency planning Contentions 24 F.G.I.K.L.D.P.R. 8 & T re itrs of agreement CORDARD, C., WEISHANTLE, J.A., ROBINSON, E.D. Long Island Lighting Co. 84/03/02 385pp 22542 175 24X Fiche 50-322,84/03/02,8403070147
- --8403070165 Testimony of MC Cordaro, GA Daverio, NA Hobbs, WF Renz & MC Schiffmacher on Phase II emergency planning Contentions 26A, C, D & E CORDARO, M C , DAVERIO, C A , HOBBS, N A Long Island Lighting Co 84/03/02 58pp 22543 200 24X Fiche 50-322,84/03/02,8403070147
- ~~8403070171 Testimony of MC Cordaro, JA Weismantle, EB Liebermen & RA Variey on Phase II emergency planning Contention 27, CORDARO, M C . WEISMANTLE, J A , LIEBERMAN, E B Long Island Lighting Ca. 84/03/02 28pp 22943 256 24X Fiche. 50-322, 84/03/02, 8403070147
- --8403070178 Testimony of MC Cordaro, CA Daverio, NA Hobbs & WF Reni on Phase II emergency planning Contentions 28-32 & 34, CURPARO, M C , DAVERIO, C A , HOBBS, N A Long Island Lighting Co 84/03/02 50pp 22543 286 24% Fiche 50-322,84/03/02,8403070147

- --B403070iB3 Testimony of MC Cordaro, CA Daverio & ML Miele on Phase II emergency planning Contention Si re preselected dose sampling points CCMDARO, M C. DAVERIO, C A , MIELE, M L Long Island Lighting Co 84/03/02 2ipp 22543 337 24X Fiche 50-322,84/03/02,8403070147
- --8403070190 Testimony of MC Cordaro. NA Hobbs. WF Renx. WG Schiffmacher & JA Weismantle on Phase II emergency planning Contentions 55.56.57 & 59 CGRARO. M C . HOBBS. N A . RENZ. W F Long Island Lighting Co 84/03/02 37pp 22543 360 24X Fiche 50-322.84/03/02.8403070147
- --8403070195 Testimony of MC Cordaro, ED Robinson & JA Weismantle on Phase II emergency planning Contention 58 re notification to special facilities & bearing impaired persons at home CORDARO, M C . ROBINSON, E D . WEISMANTLE J A Long Island Lighting Co 84/03/02 70pp 22544 037 24% Fiche 50-322,84/03/02,8403070147
- --840307019B Testimony of MC Cordaro, JA Weismantle & EB Lieberman on Phase II emergency planning Contention && CORDARO, M C . WEISMANTLE, J A . LIESERMAN, E B Long Island Lighting Co 84/03/02 28pp 22544 112 24X Fiche 50-322.84/03/02.8403070147
- --B403070201 Testimony of MC Cordano, JA Weismantle & EB Lieberman on Phase II emergency planning Contention 67 CDRDARD.M C., WEISMANTLE.J A., LIEBERMAN.E.B Long Island Lighting Co B4/03/02 2Bpp 22544 142 24X Fiche 50-322,84/03/02.
- --8403070204 Testimony of CA Clawson, ED Robinson & JA Weismantle on Phase II emergency planning Contention 73 A representation of handicapped CLAWSON, CA, CORDARO, MC, ROBINSON, ED Long Island Lighting Co 84703702 33pp 22544 171 24% Fiche 50-322, 84/03/02, 8403070147
- --8403070207 Testimony of MC Cordaro, E8 Lieberman, ED Robinson & JA Weismantle on Phase II emergency planning Contention 73 B re notification & evacuation of handicapped at home CORDARO, M C , LIEBERMAN, E B , ROBINSON, E D Long Island Lighting Co 84/03/02 33pp 22544 206 24X Fichs 50-322,84/03/02,8403070147
- ~~8403070211 Testimony of MC Cordaro, JA Weismantle & ED Robinson on Phase II emergency planning Contention 74 re location of relocation ctrs CORDARO, M C., WEISMANTLE, J.A., ROBINSON, E.D. Long Island Lighting Co. 84/03/02 71pp 22544 241 24X Fiche 50-322,84/03/02, R403070147
- --B403070214 Testimony of MC Cordaro, JA Weismantle & ED Robinson on Phase II emergency planning Contentions 75 re capacity of relocation ctrs CORDARO, M C., WEISMANTLE, J A. ROBINSON, E.D. Long Island Lighting Co. B4/03/02 50pp 22544 302 24X Fichs 50~322,84/03/02. B403070147
- --8403070217 Testimony of MC Cordaro, CA Daverio & ML Miele on Phase II emergency planning Contention 77 re thyroid contamination equipment at relocation ctrs CGRDARO, M C, DAVERIO, C A, MIELE, M L Long Island Lighting Co
- ---B403070220 Testimony of MC Cordaro & JA Weismantle on Phase II
 emergency planning Contention 92 re state emergency plan
 CORDARO, M C , WEISMANTLE, J A Long Island Lighting Co 64/03/02
 t00pp 22545 006 24X Fiche 30-322
- --B403070222 Testimony of MC Cordaro, NA Hobbs, WF Renz, W9 Schiffmacher & JA Weismantle on Phase II emergency planning Contentions 93, 94 & 95 CCRPARO, M C , HOBBS, N A , RENZ, W F Long Island Lighting Co 84/03/02 32pp 22545 119, 24X Fiche 50-322,84/03/02,8403070147
- --8403070227 Testimony of MC Cordato.ED Robinson & JA Weismantls on Phase II emergency planning Contentions 96 A & 96 C re loss of offsite power CORDARD.m C . ROBINSON.E D . WEISMANTLE.J A Long Island Lighting Co 84/03/02 15pp 22545 153 24X Fiche 50-322.84/03/02.8403070147
- --B403070g3i Testimony of MC Cordaro, ML Miele & JA Weismantle on Phase !!
 emergency planning Contention 97 B re evacuation in severe
 snowstorm Prof qualifications of LILCO witnesses &
 Certificate of Svc encl
 CORDARD, M C , MIELE, M L , WEISMANTLE, J Long Island Lighting Co.
 B4/03/02 160pp 22545 169 24X Fiche 50-322,84/03/02,
 8403070147

- B403140045 Forwards testimony of JR Sears on behalf of NRC staff re emergency preparedness Contentions 26 A, 26 C & 26 D REPKA-D A Hearing Branch 3 B4/03/02 LAURENSON.J A SHON,F J . KLINELJ R Atomic Safety and Licensing Board Panel 13pp 22633 051 24X Fiche 50-322,84/03/02,8403140045
- B403130085 Motion of Governor Cuomo to file rebuttal testimony on Contention 65 re evacuation time estimates Related correspondence ZAHNLEUTER,R J New York, State of 84/03/08 Atomic Safety and Licensing Board Panel 7pp 22614 274 24X Fiche 50-322,84/03/08,8403130085
- --8403130091 Rebuttal testimony of DT Hartgen & FJ Bench re emergency planning Contention 65 on evacuation time estimates Certificate of 84c encl HARTGEN, D T , BEACH, F J New York, State of 84/03/08 20pp 22614 281 24X Fiche 50-322,84/03/08,8403130085
- B402070039 Board Notification 84-032 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delaval, Inc (TDI) Duners Group Distribution list and EISENHUT,D 9 Division of Licensing 84/03/12 PALLADIND Commissioners 5pp 22708 001 24X Fiche 50-000,84/03/12.8402090039
- --B403060536 Forwards summary of B40210 meeting w/Transamerica Delaval.
 Inc Owners Group in Rethesda, MD re problems w/emergency
 dissel generators
 CARUBOR Licensing Branch 2 B4/02/27 O'REILLY, J P NRC No
 Detailed Affiliation Given 6pp 22708 006 24X
 Fichs 50-000, B4/03/12, B402090039
- ---B403040554 Transcript of 840210 meeting w/Transamerica Delaval. Inc Gwners Group in Bethesda: MD re problems w/emergency diesel generators * NRC - No Detailed Affiliation Given 84/02/10 147pp 67201 008 24X Fiche 50-000,84/03/12.8402070039
- ---B403070409 Summary of B40216 meeting w/Transamerica Delaval, Inc Owners Oroup in Wading River, NY re program plan to establish reliability of diesel generators Agenda, meeting transcript & attendance list encl HILLER, MA Licensing Branch 4 84/02/27 Licensing Branch 4 8pp 22708 161 24X Fiche 50-000,84/03/12,8402090039
- --8403070423 Transcript of 840216 conference in Wading River.NY re Transamerica Delaval.Inc diesel generators Pp 1-82 * Commissioners 84/02/16 84pp. 22708 169 24X Fiche 50-000.04/03/12.8402090039
- 8403260224 Transcript of 840320 hearing in Hauppauge, NY re emergency planning proceeding Pp 3,890-4,069 Supporting documentation encl

 * Atomic Safety and Licensing Board Panel, 84/03/20 440pp 22756,236 24X Fiche 50-322,84/03/20,8403260224
- 8403220288 Forwards testimony on Oroup II B Contentions 24 E.24 F 2 & F 3,24 J.24 N.60,61,63,69,70,71,72,85 & 88 Testimony for Contentions 11 & 15 will be filed on B40330 Related correspondence
 LETSCHE,K J Kirkpatrick, Lockhart, Hill, Christopher & Phillips LETSCHE,K J Suffolk County, NY DBS 055 84/03/21
 LAURENSON,J A , KLINE,J R , SHON,F J Atomic Safety and Licensing Board Panel 19 22719.107 24X Fiche 50-322.84/03/21,8403220288
- --8403220292 Testimony of QJ Jeffers & AR Rossi re Contentions 24 E. 24 F. 61, C.69, 70 & 71 Related correspondence JEFFERB.0 J , ROSSI.A R Suffalk County, NY 84/03/21 16pp 22717 158 24X Fiche 50-322,84/03/21,8403220288
- --8403220297 Testimony of RW Petrilak re Contentions 24 E.24 N.61 C.69. 70 & 71 Related correspondence PETRILAK, R W Buffolk County, NY 84/03/21. 26pp 22719 174 24X Fichs. 50-322, 84/03/21, 8403220288
- --8403220302 Testimony of NJ Muto & JT Smith re Contentions 24 E,24 F, 24 N,61.C,69,70 & 71 Related correspondence MUTO,N J. SMITH,J T Suffolk County, NY 84/03/21 i3pp 22719,200 24% Fiche 50-322,84/03/21,8403220288
- --8403220305 Testimony of FC Finlayson.GC Minor & EP Radford re Contention 61 Related correspondence FINLAYBON.F C, MINOR.G C, RADFORD.E P Suffolk County, NY 84/03/21 33pp. 22719 213 24X Fiche 50-322.84/03/21,8403220288
- --8403220310 Testimony of D Harris & M Mayer re Contentions 24 J,24 N, 60,63 & 72 Related correspondence HARRIS,D. MAYER,M Suffolk County, NY 84/03/21 43pp 22719 246 24X Fiche 50-322,84/03/21.8403220288

- --8403220313 Testimony of GC Minar re Contentions 85 & 88 Certificate of Svc encl Related correspondence MINDR: 0 C Suffalk County, NY 84/03/21 17pp 22719 289 24X Fiche 50-322,84/03/21,8403220288
- B403230008 Testimony of RR Doremus on Contentions 24 E.24 F 2,24 F 3, 24 M.61 C & 69-71 re school emergency plans
 DOREMUS, RR Long Island Lighting Co DSD 062 84/03/21 3ipp
 22728 312 24% Fiche 50-322,84/03/21,8403230008
- 8403230016 Testimony of MC Cordaro.CA Daverio.ML Miele & RJ Watts on Contention 88 re dose criteria & cost-benefit analysis for reentry Related correspondence CORDARO.M C., DAVERIO.C A., MIELE.M L. Long Island Lighting Co. DSB 049 84/03/21 43pp 22728 001 24X Fiche 50-322.84/03/21, 8403230016
- 8403230020 festimony of MC Cordaro EB Lieberman, ML Miele ED Robinson & JA Weismantle re Contentions 24 E.24 F 2.24 F 3.24 M.61 C & 68-71 re schools Related correspondence CORDARO, M C . MIELE, M L Long Island Lighting Co LIFBERMAN, E B KLD Associates, Inc DSB 063 84/03/21 400pp 22725 001 24X Fiche 50-322.84/03/21,8403230020
- 8403230032 Testimony of MC Cordaro, CA Daverio, ML Miele, DS Mileti & RJ Watts re Contentions 60.61,63 & 64 on protective action recommendations Related correspondence CORDARO, M C., DAVERIO, C A., MIELE, M L. Long Island Lighting Co. DSB 065 84/03/21 197pp 22735 041 24X Fiche 50-322,84/03/21,8403230032
- B40323003B Testimony of MC Cordaro,D Glaser,ML Miele,ED Robinson, JA Weismantle & J Yedvab on Contention 24 J.N. 72 C,D & 76 B re planning for special facilisties Related correspondence CORDARO,M C : GLASSER.D : MIELE,M L Lang Island Lighting Co DSB 044 B4/03/21 294pp 22732 047 24X Fiche 50-382,84/03/21. 840323003B
- B403230048 Testimony of MC Cordard, CA Daverio, ML Miele, SW Porter on Contention B1 re ingestion pathway Related correspondence CORDARO, M C . DAVERIO, C A . MIELE, M L Long Island Lighting Co D58 067 84/03/21 200pp 22724 131 24X Fithe 50-322,84/03/21. 8403230048
- 8403230066 Testimony of MC Cordaro, JA Weismatle & EB Lieberman on Contentions 72 A & G re adequate evacuation time estimates Related correspondence CORDARO, M C . WEISMANTLE, J A . LIEBERMAN, E B Long Island Lighting Co.
- 8403230073 Testimony of MC Cordaro, CA Daverio, ML Miele & RJ Watts on Contention B5 re recovery & reentry Related correspondence CORDARO, M C , DAVERIO, C A , MIELE, M L Long Island Lighting Co D58 040 84/03/21 44pp 22726 230 24X Fiche 50-322,84/03/21, 8403230073
- 8403260012 Transcript of 840321 hearing in Hauppauge, NY re emergency planning proceeding Pp 4,070-4,268 * About Safety and Licensing Board Panel 84/03/21 200pp 22749 001 24X Fiche 50-322,84/03/21,8403260012
- 8403260338 Forwards direct testimony of CV Failla re Contention 24 F 2 Related correspondence ZAHNLEUTER, R J New York, State of D80 097 84/03/21 LAURENSON, J A , KLINEJ R , SHDN. F J Atomic Safety and Licensing Board Panel 1p 22760 165 24X Fichs 50-322,84/03/21.8403260338
- --8403260342 Direct testimony of CV Failla re Contention 24 F 2 on agreements w/bus companies in event of radiologica; accident FAILArC V New York, State of 84/03/21 13pp 22760 166 24X Fiche 50-322,84/03/21,8403260338
- 8403260377 Forwards util testimony on Contention 18 re adequacy of zone & route info Related correspondence FALZONE, R R Hunton & Hilliams FALZONE, R R Long Island Lighting Ca D88 096 84/03/22 LAURENSON J A , KLINE, J R , SHON, F J Atomic Safety and Licensing Board Panel ip 22760 001 24X Fiche 50-322,84/03/22,8403260377
- ---8403260379 Testimony of CA Clawson.MC Cordaro & CA Daverio on Contention 18 re adequacy of zone & route info Certificate of Svc encl CLAWBON.C A . CORDARO.M C . DAVERIO.C A Long Island Lighting Co 84/03/22 55pp 22760 002 24X Fiche 50-322.84/03/22.8403260377
- 8403270196 Transcript of 840322 hearing in Hauppauge.NY re emergency planning proceeding Pp 4,269-4,511 **Atomic Safety and Licensing Board Panel 84/03/22 328pp 22772 182 24X Fiche 50-322.84/03/22.8403270196.

8403290001 Transcript of 840327 oral argument in Bethesda.MD Pp 1-192 * Atomic Safety and Licensing Appeal Panel 84/03/27 193pp 22803 088 24X Fiche 50-322.84/03/27.8403270001

V Operator Examinations

- 8403270116 Forwards supplemental nuclear power plant experience tables for operating shift positions Expected QL date is 840513.in response to add1 questions in DF Schnell, Union Electric Co. 1tr
 NUTARQ, J A Long Island Lighting Co 84/03/22 DENTON, H & Office of Nuclear Reactor Regulation, Director 8pp 22775 137 24X Fiche 50-022, 84/03/22, 8403270116
- DOCKET 50-323 DIAGLO CANYON NUCLEAR POWER PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8403070027 FDIA request for records re 1977 Nuclear Sycs Corp audit of Pullman Power Products REYNOLDS.J Center for Law in the Public Interest 84/01/20 Office of Administration 2pp 82592 329 24X Fiche 50-275,84/01/20.8403090027
- 8403010501 Forwards Board Notification 84-022 which provides in camera transcript of NRC 840125 meeting w/recipient & C 8tokes Requests specific identification of names & sections in rept to be withheld from public disclosure W/o encl EISENHUT. D © Division of Licensing 84/02/14 DEVING.T Government Accountability Project ip 22438 335 24X Fiche 50-275,84/02/14.8403010501
- 8402090004 Board Notifiscation 84-037 forwards Chairman Pallacino 840109 ltr transmitting rept on matters to GA Case Study C for plant Rept encls compare draft & final version of case study & include comments on draft version
 EISENNUT.D 9 Division of Licensing 84/02/24 BUCK, J H , MODRE, T S , JOHNSTON, W R Atomic Safety and Licensing Appeal Panel 3pp 22547 036 24X Fiche 50-275,84/02/24,8402090004
- 8402090017 Board Notification 84-038 forwards RJ Mattson 840123 mamo to DG Eisenhut providing status update of NRC actions re Westinghouse ECGS actuation logic EISENHUT.D Q Division of Licensing 84/02/27 PALLADING, GILINSKY, ROBERTS Commissioners 7pp 22546 007 24% Fiche 50-000.84/02/27.8402090017
- B403190165 Requests add1 info explicitly addressing specific steps in 36(FRB00 4(b),(c),or (d) re determination of effect of operation be maint activities on SLD-2 archaeological site

 KNIGHTDN.G W Licensing Branch 3 B4/02/27 SCHUYLER.J D Pacific Gas & Electric Cq 4pp 22646 345 24% Fiche 50-275, 84/02/27, 8403150165
- 8403090028 Partial response to FDIA request for records re 1977 Nuclear Svcs Corp audit of Pullman Power Products Documents entirely withheld (ref FOIA Exemption 5) Review of remaining documents sub; to request in progress FELTON, J M Division of Rules and Records 84/03/01 REYNOLDS, J Center for Law in the Public Interest 2pp 22592 331 24X Fichs 50-275,84/03/01,8403090028
- 8403080405 Further response to FDIA request for documents re SER related to operation of facilities Forwards App B documents App A & B documents available in PDR Review of remaining documents tub; to request in progress FELTON, J M Division of Rules and Records 84/03/02 CARDE, B P Government Accountability Project 4pp 22583 073 24X Fiche 50-275, 84/03/02. 8403080405
- --B312230256 Forwards responses to Allegations 7,9 % 48,per 831130 request BFEIS.T P Division of Safety Technology B3/12/09 KNIGHTON,0 Office of Nuclear Reactor Regulation. Director 12pp 22083 111 24X Fiche 50-275,84/03/02,8403080405
- --B403080422 Forwards input on Allegations 51 & 52 Fuel loading addressed in 831108 Memorandum & Order CLI-83-27 No significant safety concerns math to fuel loading & precriticality testing warrant continuation or suspension of activities BURNES Office of the Executive Legal Director 83/12/09 KNIGHTON & Office of Nuclear Reactor Regulation, Director 3pp 22583.108 24X Fiche 50-275.84/03/02.8403080405
- --8403080426 Forwards safety evaluations for Allegations 8, 10, 11, 14, 15, 16, 17, 27, 28, 27, 31, 32, 33, 35, 35, 35, 85 & 86 ticensee approach for determining containment stability against tilting acceptable VOLLMER, R H, Division of Engineering 83/12/09 CISENHUT, D Q. Division of Licensing 31pp 22583 132 24X Fiche 30-275, 84/03/02, 8403080405

- 8403150013 Forwards response to request for add1 info re Class IE electrical raceway supports Design supports have sufficient margin to assure that loss of single support will not cause loss of safety function SCHUYLER: J D Pacific Gas & Electric Co 84/03/07 MARTIN. J B. Region 5. Defice of Director. 3pp 22640 327 24X Fiche 50-277.84/03/07.8403150013
- 8403200218 Forwards Rev 2 to Procedure EP DP-17. "Malfunction of RHR 8ys." requested by ACRS Bubcommittee on Diable Canyon during 840210 meeting 8CHUYLER.J D Pacific Oax & Electric Co 84/03/12 KNIGHTON.O W. Licensing Branch 3 lp 22699 337 24X Fiche 50-275, 84/03/12, 8403200218
- --B403200220 Rev 2 to Procedure EP OP-17, "Malfunction of RHR 8ys" * Pacific Gas & Electric Co 82/02/19 3pp 22499 338 24x Fiche 50-275,84/03/12,8403200218
- 8402070041 Board Notification 84~050 provides Commission policy statement & proposed rulemaking on environ qualifications EISENHUT.D 0 Division of Licensing 84/03/14 Atomic Safety and Licensing Board Panel 10pp 24X Fiche 50-000,84/03/14/8402090041
- 8403220035 Forwards tables providing detailed operating experience for licensed operating personnel & licensed & nonlicensed shift technical advisors BCHUYLER, J O Pacific Oas & Electric Co 84/03/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 22718 208 24X Fichs 50-275,84/03/16.8403220035
- B403260176 Informs of plans to have shift advisors w/qualifications & training recommended by Near-Term OL, Util Group on staff prior to exceeding 5% power Advisors will be subj to final exam following training

 SCHUYLER, J O Pacific Gas & Electric Co 84/03/23, KNIGHTON, Q W., Licensing Branch 3 ip 22758 234 24X Fiche 50-275, 84/03/23, 8403260176
- B403270366 Requests that license not be granted until allegations by employees of plant resolved HAYDEN. T California. State of 84/03/23 PALLADINO, N Commissioners 1p 22789 001 24X Fiche 50-275, 84/03/23, 8403270366
- E NRC Safety Evaluation Report (BER), supple & correspondence
- B403080085 FOIA request for SER & BBER 21 (NUREQ-0675) re operation of facilities
 OARDE-B.P. Quivernment Accountability Project 84/01/09, Office of Administration 2pp 22584 074 24% Fiche 50-275,84/01/09, 8403080085
- 8403080096 Partial response to FOIA request for BER re operation of facilities forwards documents listed on app Documents also placed in PDR, Review of remaining documents continuing FELYON, J M Division of Rules and Records 84/01/23 GARDE, B P. Obvernment Accountability Project 2pp 22584 076 24X Fiche 50-275,84/01/23,8403080096
- --8403080103 Allegations 51 % 52 re NRC concern that plant personnel reluctant to come forward w/safety concerns since candor endangers Jobs * NRC No Detailed Affiliation Given. 84/01/23 2pp 22584 089 24X Fiche 50-275,84/01/23,8403080096
- 8403060564 Forwards SBER 17 re util application for DLs Suppl addresses NRC availation re breakwater & superstrut issues W/o encl KNIGHTON:0 R Licensing Branch 3 84/02/27 8CHUYLER:J O Pacific Gas & Electric Co 4pp 22552 265 24X Ficha 50-275;84/02/27,8403060564
- 8403070104 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF DIABLE CANYON NUCLEAR POWER PLANT, UNITS 1 AND 2 Docket Nos 50-275 And 50-323 (Facific Cas And Electric Company) # Division of Licensing NUREG-0675 817, 84/02/29 22pp, Available at NRC. \$3 00. 22561 214 24X Fiche 50-275,84/02/29, 8403070104.
- B402070030 Board Notification B4-035 updates allegation listed in SGER 21 & Board Notification 84-003 Public allegations not previously forwarded & characteritations of allegations from confidential sources encl EIBENHUT, D G Division of Licensing 84/03/02 PALLADING, QTIINGKY, ROBERTS Commissioners 11pp. 22536,061 24X Fiche 50-275,84/03/02,8402070030

- --B312140347 Forwards Nuclear Svc Corp 1977 audit of Pullman Power Products work scape at Pacility in response to B31004 ltr to Chairman Palladino Attention called to ASLAB B31024 denial of Joint Intervenor B31020 motion to reopen record DIRCKS, M J. Office of the Executive Director for Operations 83/11/18 THOMAS, W M House of Rep 4pp 22556 080 24X Ficha 50-275,84/03/02,8402090030
- --8312140351 Forwards JR Reynolds 830921 ltr expressing concern, on behalf of Joint Intervenors re deficient design & const of facility Nuclear Svc Corp 1977 audit encl THOMAS, W M House of Rep 83/10/04 PALLADINO, N Commissioners 4pp 2255 081 24X Fiche 50-275,84/03/02,8402090030
- --8403080281 "Audit Rept Pullman Power Products Work Scope at Diablo Canyon Site 770822-0920 " WEBER, J , LARSEN, O J , NEWMAN-T C Pacific Gas & Electric Co 77/09/20 42pp 22556 090 24X Fiche 50-275,84/03/02,8402090030
- --8312280097 Responds to 831021 ltr re rept of 1977 audit of Pullman Fower Products Corp Motion filed before NRC for revocation or in alternative, continuation of suspension of low power QL for facility Matter referred to NRC DIRCKS, W J Office of the Executive Director for Operations 83/11/18 PANETTA, LE House of Rep 4pp 22554 132 24X Fiche 50-275,84/03/02,8402090030
- ---BG12280107 "Proposal for Independent Internal Audit of Pullman-Kellogg Efforts at Diablo Canuon " * Nuclear Services Corp 77/07/28 21pp 22556 134 24X Fichs 50-275,64/03/02.6402090030
- --8401040010 Forwards all ltrs which appeared in Ban Luis Obispo Telegram-Tribune between 831019-31 re emergency planning response plan for facility Lack of public confidence in response plan discussed KRANZDORF, R Affiliation Not Assigned 63/11/04 PALLADINO, N Commissioners 17pp 22556,175 24X Fiche 50-275,84/03/02, 8403090030
- 8403080405 Further response to FGIA request for documents re SER related to operation of facilities Forwards App B documents App A & B documents evailable in PDR Review of remaining documents subj. to request in progress
 FELTON, J.M. Division of Rules and Records 84/03/02, GARDE, B P Government Accountability Project. 4pp 22583 073 24X
 Fiche: 50-275, 64/03/02, 8403080405
- --B4030B0431 Forwards SBER input re Allegation 68 Programmatic breakdown in Pullman Power Products GA program not indicated Installed hardware safety concerns not identified.

 LIEBERMAN, J Office of the Executive Legal Director B3/12/27 EIBERNHUT, D Division of Licensing 4pp 22583 163 24X Fishe 50-275, 84/03/02,84030B0405
- 8403300300 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF DIABLO CANYON NUCLEAR POWER PLANT, Units 1 AND 2 Docket Nos 50-275 And 50-323. (Pacific Gas and Electric Company)

 # Division of Licensing NUREO-0475 822 84/03/31 400pp Available at NRC. \$11 00 22843 001 24X Fiche 50-275,84/03/31,8403300300
- F Becurity, medical, emergency & fire protection plans
- 8403280114 Public version of revised emergency plan implementing procedures including Procedures EP OP-9 reloss of reactor coolant pump w/o reactor trip & EP G-2 released inheart of organization W/840105 & 0322 memos
 THOMBERO, R.C., SCHUYLER, J.D. Pacific Gas & Electric Co. 84/01/05
 MARTIN.J.B. Region 5, Office of Director 33pp 22811 236 24X
 Fiche 50-275,84/01/05,8403280114
- 8403070355 Public version of emergency plan implementing procedures, including Procedure EP G-4 personnel accountability & assembly & EP RB-12 re mid & high-renge plant vent radiation monitors W/840208 ltr & JM Felton 840302 release memo THOMBERO,R.C., SCHUYLER,J.D., Pacific Gas & Electric Co 84/01/23 MARTIN,J.B. Region 5. Office of Director 120pp 22365 189 24X Fiche 50-275,84/01/23,8403070355
- 8403070172 Forwards Rev ii to physical security plan Rev withheld (ref 10CFR73.21), BCHUYLER, J D. Pacific Qas & Electric Co 84/02/06 MARTIN, J B Region 5, Office of Director 1p. 22575 049 24X Fiche: 50~275: 84/02/06
- B402230176 Forwards revised State of CA nuclear power plant emergency response plan MEDFORD, M O Southern California Edison Co. 84/02/16 EISENHUT, D Q. Division of Licensing 383pp 22333 001, 24X Fiche: 50-000, 84/02/16, 8402230176

- --8403020117 Revised State of CA nuclear power plant emergency response plan * California, State of 83/04/30 2901pp 22353 003 24X Fiche 50-000,84/02/16.8402230176
- 8402070006 Board Notification 84-034 forwards R Vollmer 840206 memo to D Eisenhut re fire research results concerning fires in electrical cabinets in control room EISENHUT. D 9 Division of Licensing 84/02/23 PALLADIND Commissioners ip 22576 203 24X Fiche 50-000.84/02/23, 8402070006
- --8403080316 Recommends that info re fire research results concerning fires in electrical cabinets in control room be submitted for board notification.per NRR Ofc Ltr 19, dtd 821001 Further evaluation of test data required VDLLMER.R H Division of Engineering 84/02/06 EISENHUT, D O Division of Licensing 10pp 22976 204 24X Fiche 50-000,84/02/23,8402090006
- 8403080405 Further response to FOIA request for documents re SER related to operation of facilities Forwards App B documents App A & B documents available in PDR Review of remaining documents subj. to request in progress FELTON.J M Division of Rules and Records 84/03/02 GARDE.B P Government Accountability Project 4pp 22583 073 24X Fiche \$0-275.84/03/02.8403080405
- --B4030B04ii Forwards response to Allegation RV-83-A-0034.per GW
 Knighton B3ii22 note Temporarily exempting licenses from
 maintaining physical security & safeguards contingency
 plans did not increase risk of radiological sabotage
 MCCORKLE.6 W Power Reactor Safeguards Licensing Branch
 B3/12/01 THOMAS.C O Standardization & Special Projects Branch
 4pp 22583 077 24X Fiche 50-275,84/03/02,840308040b
- --8403080417 Resubmits response to Allegation RV-83-A-0034, per GW Knighton 831103 memo Temporarily exempting licenses from maintaining physical security & safeguards contingency plans did not increase risk of radiological sabotage MCCORKLE.0 W Power Reactor Safeguards Licensing Branch 83/12/05 THUMAS.C 0 Standardization & Special Projects Branch 3pp 22583 081 24X Fiche 50-275.84/03/02.8403080405
- --B4030B0420 Forwards response to Allegation RV-83-A-0034.per GW Knighton B21122 note Temporarily exempting licenses from maintaining physical security & safeguards contingency plans did not increase risk of radiological sabotage BURNETT,R F Division of Bafeguards B3/12/08 EISENHUT,D G Division of Licensing 3pp 22583 084 24X Fiche 50-275, B4/03/02.84030B0405
- 8403280001 Forwards safeguards info re changes to Rev 11 to security plan Info withheld (ref 10CFR73 21)
 8CHUYLER, J D Pacific Qas & Electric Co 84/03/19 MARTIN, J B Region 5, Office of Director 1p 22777.151 24X Fiche 50-275,84/03/19,8403280001
- 8403270205 Discusses Southern California Edison submittal of 1983 revised State of CA emergency response plan on behalf of all State of CA plants, incorporating plan into Diablo Campon Addl planning info will not be developed for Humboldt Day SCHUYLER, J D Pacific Gas & Electric Co 84/03/22 DENTON, H R. Office of Nuclear Reactor Repulation, Director 1p 22772 137 24X Fiche 50-000,84/03/22,8403270205
- 8403270264 Advises that 840111 rev to physical security plan & drawings consistent w/provisions of 10CFR50 54(p) & acceptable BCHUBTER: M D Region 5. Office of Director 84/03/23 BCHUYLER: J O Pactfic Gas & Electric Co. ip 22800 010 24X Fiche: 50-275,84/03/23,8403270264
- Q. Adjudicatory correspondence
- 8402090012 Board Notification 84-045 forwards 840202 petition to defer decision re low power OL, made by Govt Accountability Project (GAP) on behalf of Ban Luis Obispo Mothers for Peace Distribution list & app encl EISENHUT, D 9 Division of Licensing 84/02/27 MOORE, T S, JOHNSON, W R, BUCK, J H, Atomic Safety and Licensing Appeal Panel 5pp 67218 074 24X Fiche 50-275,84/02/29,8402090012
- B403070044 Motion for extension until B40319 to file response to Joint Intervenors B40222 motion to reopen record on const QA Certificate of 8vc encl NORTON, B Pacific Gas & Electric Co NORTON, B. Norton, Burke, Berry & French B4/02/29 Atomic Bafety and Licensing Appeal Panel 5pp 22541 250 24X Fiche 50-275, B4/02/29, B403070044.

- 840314007L Forwards expurgated transcript of 840125 meeting between staff & C Stoles, per ASLAB 840223 order W/o encl RUTBERG, J Hearing Branch 2 84/02/29 HOORE, T S . BUCK, J H . JOHNSON W R Atomic Safety and Licensing Appeal Panel 2pp 22634 184 24X Fiche 50-275.84/02/29,8403140071
- 8403060260 Response of Governor Beukmejian to util 840229 motion for extension of time to respond to Joint Intervenor 840222 motion to reopen & motion of Beukmejian for like extension of time to reply Certificate of Svr entl
 STRUMWASSER,M California, State of 84/03/01 Atomic Safety and Licensing Appeal Panel 9pp 22517 132 24x Fiche 50-275,84/03/01,8403060260
- 8403080118 Supp) 1 to 840214 motion to augment or, in alternative, to reopen record Provides addl explanation of allegations redesign & design GA deficiencies from transcript of 840125 meeting Certificate of Svc encl REYNOLDS. J R Joint Intervenors Diablo Canyon REYNOLDS. J R Center for Law in the Public Interest 84/03/01 Atomic Safety and Licensing Appeal Panel 15pp 22559 182 24X Fiche 50-275.84/03/01.8403080118
- 8403060179 Order granting applicant 840227 motion for extension of time to 840319 to respond to Joint Intervenors 840222 motion to reopen record on const GA TOMPKINS.8 A Atomic Safety and Licensing Appeal Panel 84/03/02 2pp 22518 348 24% Fiche 50-275,84/03/02.8403060179
- 8403070128 Suppl to 840222 motion to reopen record on issues of const GA & licensee character & competence Serious doubts re util competence to manage project raised W/Certificate of Syr REYNDLDS, JR Affiliation Not Assigned REYNDLDS, JR Center for Law in the Public Interest 84/03/02 Atomic Safety and Licensing Board Pane: 23pp 22538 231 24% Fiche 50-275,84/03/02,8403070128
- B403140179 Request for extension of time to 840315 to file response to Jaint Intervenor motion to augment or reopen record Certificate of Svc encl RUIDERGJ Hearing Branch 2 84/03/02 Atomic Bafety and Licensing Appeal Panel 4pp 22624 100 24X Fiche 50-275, 84/03/02, 8403140179
- 8403070198 Order requiring governor response to Joint Intervenor 840214 motion to reopen record on issue of design GA by 840308 SHOEMAKER.C J Atomic Safety and Licensing Appeal Panel 84/03/05 California, State of 1p 22541 342 24x Fiche 50-275.84/03/06. 8403870188
- 8403120006 Answer opposing Joint Intervenors 840214 motion to augment or reopen record on design QA Motion should be denied in entirety Certificate of Svc encl
 NGRTON.B Pacific Gas & Electric Co NGRTON, B Norton, Burke,
 Serry & French 84/03/06 Atomic Safety and Licensing Appeal
 Panel 23pp 22956 189 24X Fiche 30-275.84/03/06.8403120006
- --8403120010 Affidavit of FC Breismeister, DJ Curtis, HJ Jacobson, HE Leppke, GH Moore, RG Oman, LE Shipley & WH White re design QA BREISMEISTER, F. CURTIS, D. J. JACOBSON, M. J. Pacific Gas & Electric Ca. 84/03/05 101pp 22586 331 24X Fiche 50-275, 84/03/06, 8403120006
- --8403120012 Affidavit of M Tresler.R Oman & M Leppke re history of onsite engineering small bore piping program description THESLER.M . OHAN.R . LEPPKE.M Pacifit Gas & Electric Co 84/03/05 58pp 22587 070 24% Fiche 50-275
- --8403120015 Affidavit of LB Mangoba re design verification & commt of small bore pipe support sys MANGOBALL B Bechtel Corp 84/03/04 App 22587 128, 24X Fichs 50-275,84/03/06,8403120006
- --8403120017 Affidavit of A Shusterman re design GA & coverup of hanger recalculation SHUSTERMAN, A Bechtel Corp 84/03/04 4pp 22587 134 24X Fiche 50-279,64/03/06,8403120006
- --840312001B Affidavit of RD Etzler re design GA & QC inspector qualifications ETZLER.R D Pacific Gas & Electric Co 84/03/06 4pp 22587 138 24X Fiche 30-275.84/03/06,8403120006
- --8403120022 Affidavit of HB Friend re design GA & util/Bechtel contract FRIEND, H B Pacífic Gas & Electric Co B4/03/05 2pp 22587 142 24% Fiche 50-275,84/03/06,8403120006
- --8403120023 Affidavit of DJ Curtis re design QA & small bore pipe support group drawing CURTIS.D J Bechtel Corp 94/03/05 2pp 22587 144 24X Fiche 50-273,84/03/06.8403120006

- --R403120029 Affidavit of JD Shiffer,R Patterson, JM Gisclon, KC Dois, JB Nach, RC Thornberry, RD Etzler, RX Rhodes & EM Burns re J Cooper B40123 affidavit & Joint Intervenor 840214 motion on design GA SHIFFER, JD., PATTERSON, R. OILSCLON, JM Pacific Oas & Electric Co B4/03/05 234pp 22587 146 24X Fiche 50-275,84/03/06, B403120066
- 8403150010 Summarizes fears that Commission will discard terms of 1981 order & will surrender normal requirements of Atomic Energy Act by permitting facility to go critical in quality indeterminate state CLEWETT. J Government Accountability Project DEVINE. T. CLEWETT. J San Luis Obigo Mothers for Peace 84/03/13 PALLADINO. N J , O'LLINGKY. V . ROBERTS. T Commissioners 22642 326 24X Fiche 50-275.84/03/13.8403150010
- 8403160014 Order extending time until 840413 for Commission to act to review ALAB-756 CHILK: J Uffice of the Secretary of the Commission 84/03/13 Commissioners ip 22652:362 24X Fiche 50-275,84/03/13, 8403140014
- 8403190011 Motion for leave to file reply to util answer in opposition to motion to reopen record Certificate of Svc encl REYNOLDS.J.R. Joint Intervenors Diablo Canyon REYNOLDS.J.R. Center for Law in the Public Interest 84/03/15 Atomic Safety and Licensing Appeal Panel Spp. 22665-273 24X Fiche 50-275,84/03/15.8403190011
- --8403190016 Reply to util answer in opposition to 840214 motion to augment or, in alternative, to reopen record Contentions in opposition cannot withstand scrutiny Certificate of 8vc encl REYNOLDS, J.R. Joint Intervenors -- Diablo Canyon REYNOLDS, J.R. Center for Law in the Public Interest 84/03/15. Atomic Safety and Licensing Appeal Panel, 26pp 22665 278, 24% Fiche 50-275,84/03/15.8403190011
- --8403190021 Statement of C Stokes rebutting util defenses of seismic design review STOKES:C Joint Intervenors - Diablo Canyon 84/03/14 2App. 22465 309 24X Fiche 50-275,84/03/15,8403190011
- 8403190100 Answer apposing Joint Intervenor 840214 motion to augment or, in alternative, to reopen record on design GA issues Action failed to justify either augmentation or reopening record Certificate of Svc encl RUTBERG. J. CHANDLER, L. J. Hearing Branch 2 MCGURREN, H. J. Hearing Branch 1 84/03/15 Atomic Safety and Liceusing Appeal Panel 29pp 22667 215 24X Fiche 50-275,84/03/15,8403190100
- --B403190102 Affidavit of JP Knight re Joint Intervenors motion to augment or, in alternative, to reopen record KNIGHT. JP Division of Engineering 84/03/15 Atomic Safety and Licensing Appeal Panel 16pp 22667 244 24X Fiche 50-275,84/03/15,8403190100
- --840319Di06 Affidavit of M Hartzman re Joint Intervenors motion to augment or, in alternative, to reopen record HARTZMAN, M Division of Englateering 84/03/15 22pp 22667 260 24% Fiche 50-275,84/03/15,8403190100
- --8403190110 Affidavit of SD Raynolds re Joint Intervenors 840214 motion to augment or, in alternative to reopen record REYNOLDS B. Region 1. Office of Director 84/03/15 8pp 22667 282 24X Fiche 50-275 84/03/15 8403190100
- --8403190114 Affidavit of TW Bishop re Joint Intervenors 840214 motion to augment or in alternative, to respen record BISHOP.T H Region 5, Office of Director 84/03/08 App 22667 290 24X Fiche 50-275,84/03/15,8403190100
- --8403190116 Affidavit of JR Fair re Joint Intervenors 840214 motion to augment or, in alternative, to reopen record FAIR, J R Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/08. App 22667, 294 24X Fishs 50-275, 84/03/15, 8403190100
- --B403190119 Affidavit of CY Liang re deficiencies in RHR sys design LIANG.C.Y Division of Systems Integration (post 811005) 84/03/15 30pp 22647:300 24X Fiche 50-275,84/03/15,8403190100
- --8403190122 Affidavit of F Rosa re RHR sys RGBA, F Division of Systems Integration (post 811005). 84/03/15 17pp 22657 330 247 Fiche 50-275.84/03/15.8403190100
- --8403190126 Affidavit of JL Crews re Joint Intervenors 840214 motion to augment or, in alternative to reopen record CREMB.J L Region 5. Office of Director 84/03/14 5pp 22667 347 24% Fiche 50-275.84/03/15.8403190100

- --8403170130 Supplemental affidavit of JL Crews on addl info re Joint Intervenors motion on GA deficiencies CREMS.J L Region 5. Office of Director 84/03/15 ip 22667 352 24% Fiche 30-279.84/03/15.8403170100
- --B403190134 Affidavit of H Schierling re Joint Intervenors 840214 motion to augment or, in alternative, to reopen record Unexecuted affidavit of PJ Morrill encl SCHIERLING.H Literaing Branch 3 84/03/15 3pp 22667 353 24X Fichs 50-275, 84/03/15, 8403190100
- 8403210033 Request for extension of time until 840403 to file response to Joint Intervenors motion to reopen record on const QA Certificate of 8vc encil CHANDLER.L J Hearing Branch 2 84/03/16 Atomic Safety and Licensing Appeal Panel 4pp 22704 330 24X Fiche 50-275,84/03/16. 8403210033
- B403210114 Forwards PJ Morrill signed & corrected affidavit as addendum to NRC 840315 response to Joint Intervenors motion to augment or response to Joint Intervenors motion to augment or response design GA record Related correspondence CHANDLER; L.J. Hearing Branch 2 84/03/16 MOGRE, T.S., BUCK, J.H. Atomic Bafety and Licensing Appsal Panel JOHNSON, W.R. Atomic Bafety and Licensing Board Panel 2pp 22707 126 24X Fiche. 50-275, 84/03/16, 8403210114
- --8403210119 Affidavit of PJ Morrill as addendum to NRC 840315 response to Joint Intervenors motion to augment or reopen design QA record. Prof qualifications of JP Knight also encl MORRILL.P J. Division of Resident Reactor Project & Engineering Programs 84/03/15 Atomic Bafety and Licensing Beard Panel 15pp. 22707 128 24X Fiche 50-275.84/03/16.8403210114
- B403200133 Discusses dispute between plant workers & util re slander suit Identification of relevant issues establishing accountability for inaccurate util statements & fixing hardware from GA breakdown not yet possible DEVINE, T Government Accountability Project DEVINE, T. San Luis Obispo Mothers for Peace B4/03/19 PALLADIND, N J . GILINSKY, V . ROBERTS, T. Commissioners 20pp 22699 047 24X Ficha: 50-275, 84/03/19, 8403200133
- 8403210157 Decision ALAB-763 affirming LBP-B2-70 granting authorization to operate facility, w/listed conditions BHOEMAKER.C J Atomic Safety and Licensing Appeal Panel DSB 021 84/03/20 122pp 22710 144 24X Fiche 50-275.84/03/20.8403210159
- 8403220106 Forwards renewal of application for stay to permit completion of administrative review & opportunity for court review of Joint Intervenors emergency motion REVNOLDS, J. R. Center for Law in the Public Interest REYNOLDS, J. F. Jaint Intervenors Diable Canyon DSB 044 84/03/20 PALLADINO, N. GILINSKY, V. ROBERTS, T. Commissioners 2pp. 22715 304 24X Fiche 50-275,84/03/20,8403220106
- --8403220110 Renewal of application for stay to permit review of Joint Intervenors emergency motion Unexecuted affidavit of M Kaku & Centificate of Bvc encl
 REYNOLDB, J.R Joint Intervenors Diablo Canyon REYNOLDB, J.R
 Center for Law in the Public Interest 84/03/20 Atomic Safety and Licensing Appeal Panel 25pp. 22715 306 24X
 Fiche 50-275,84/03/20,8403220106
- B403270278 Comments on request for meeting to discuss issues raised by C Stokes on submission by util & staff re design QA Related correspondence CHANDLER.L.J Hearing Branch 2 DBB 139 84/03/21 DEVINE.T Gavernment Accountability Project 2pp 22789 035 24X Fiche 50-275, 84/03/21.8400370278
- 8403270004 Discusses Btate of CA emergency response plan Plan incorporated into Diablo Canyon plan Addl planning will not be performed for Humboldt Bay per 1980 legislation Related correspondence BCHUYLER, J. Pacific Qas & Electric Co. DSB 117 B4/03/22 DENTON: R Office of Nuclear Reactor Regulation, Director 1p. 22769: 349 24X Ficher 50-000, 84/03/22, 8403270004
- 8403260005 Requests that low power test license not be granted. Discussion before licensing vote requested LEVY.B., SHARPE, C Affiliation Not Assigned DSB 077 84/03/23 PALLADING, N. ASSELBTINE, J. K. BERNITHAL, F. J. Commissioners. ip 22747: 356 24X Fiche 50-275, 84/03/23, 8403260005
- 8403260364 Forwards 12 add1 affidavits in support of 840301 petition to defer any futher licensing decisions until completion of comprehensive reinsp.mgt audit & audit of design verification. W/o encl.

 DEVINE.T., CLEWETT.J. Government Accountability Project. DEVINE.T Sen Luis Obispo Mothers for Peace DBB 101 84/03/23 PALLADINO.N.J. GILINBKY, V. ROBERTS.T. Commissioners 9pp 22740:065. 24X Fiche: 50-275, 84/03/23, 8403260364

- 8403270006 Informs that 12 add1 affidavits in support of Nothers for Peace 840301 petition to defer licensing submitted to Region V Related correspondence * Government Accountability Project DSB 115 B4/03/23 PALLADINO.N J Commissioners ip 22770 009 24X Fiche 50-275,84/03/23,8403270006
- B403270347 Telecopy ltr expressing view that no low power license should be granted until all safety questions & allegations resolved O'CONNELL, J California, State of DSS 142 84/03/23 PALLADING, N Commissioners 19 22789 005 24X Fiche 50-275. B44/03/23 4403270347
- 8403270352 Telecopy ltr urging assurance that alleged safety hazards checked & thoroughly evaluated before granting license BRDNZAN.B California, State of DSB 140 84/03/23 PALLADIND, N Commissioners 1p 22789 004 24X Fiche 50-275,84/03/23,
- B403240375 Requests opportunity to discuss OL issuance Commission should not vote on low power testing LEVY, B. SHARPE.C. Affiliation Not Assigned DSB 093 84/03/26 PALLADINO, N. GILINEKY, V. ROBERTS, T M. Commissioners 1p 22740 138 24X Fichs 50-275,84/03/26,8403240375
- 8403260378 Requests that Commission not vote & authorization to operate not be given to facility
 LEVY.B., SHARPE,C. Affiliation Not Assigned, DSB 092 84/03/26
 ASSELBTINE,J K., BERNTHAL,F.J. Commissioners 1p 22760 136 24;
 Fiche 50-275,84/03/26,8403260378
- H General correspondence
- 8403010525 Responds to 840112 request that NRC deny PO&E any type of OL for plant Validity of allegations re design & const being evaluated Commission will not recommend that low power license be fully reinstated until evaluation complete DENTON.H R Office of Nuclear Reactor Regulation, Director 84/02/15 KNUTBON.JA Affiliation Not Assigned 3pp 22443 282 24X Fiche 50-275,84/02/15.8403010525
- ---8403010532 Expresses concern that plant poses grave danger to environ & public health of State of CA & urges NRC to deny util any type of OL due to continuing design flaws
 KNUTBON: J A Affiliation Not Assigned 84/01/12 DIRCKS,W NRC
 -- No Detailed Affiliation Given ip 22443 285 24X
 Fiche 50-275,84/02/15,8403010525
- I Financial information
- 8403280051 Annual Financial Rept 1983 W/840326 ltr MIELKE,F W , GHACKELFORD,B , CRANE,P A Pacific Gas & Electric Co 83/12/31 50pp 22776 230 24X Fiche 50-000.83/12/31,8403280051
- J Insurance & indemnity information
- 8403280033 Forwards Endorsement 40 to NELIA Policy NF-228 GRANE,P A Pacific Cas & Electric Co 84/03/21 SALTZMAN,J D Assistant Director for State & Licensee Relations 2pp 22777 044 24% Fiche-30-275,84/03/21,8403280033
- O Advisory Committee on Reactor Safeguards reports & correspondence
- B4032B0307 Summary of ACRS Subcommittee on Extreme External Phenomena B31012 meeting w/util, Westinghouse, TERA & Univ of Illinois in Mashington, DC re use of tan effect methodology in sylsmic design analysis at Diablo Canyon Agenda encl * ACRS Advisory Committee on Reactor Bafeguards 83/11/25 ACRS Advisory Committee on Reactor Safeguards 16pp. 22808 040 24% Fiche: 50-275, 83/11/25. 8403280307
- 8403270381 Notice of ACRS 840405-07 mestings in Washington,DC Agenda ancl CHILK,S J Office of the Secretary of the Commission DSB 178 84/03/28 App 22814 OB1 24% Fichs 50-275,84/03/28,8403270381
- G Inspection reports, IE Bulletins & correspondence
- 8403060138 Forwards IE Insp Repts 50-275/83-39 & 50-323/83-27 on 831205-22 & notice of violation BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 84/02/03 SCHUYLER, J D Pacific Gas & Electric Co 2p 22506 334 24X Fiche 50-275, 84/02/03, 8403060138

- --8403060146 IE Insp Repts 50-275/83-37 & 50-323/83-27 on 831205-22 Noncompliance noted failure to properly implement fire loss prevention procedures & suppls SCDMN.K · POLICH. (. CANTER.H L Region 5, Office of Director 84/01/24 188p 22506 338 24X Fiche 50-275,84/02/03,8403060138
- B403060207 Forwards IE Insp Repts 50-275/84-01 & 50-323/84-01 on B40103-06 & notice of violation BESHOP, TW Division of Resident, Reactor Project & Engineering Programs B402/17 SCHUYLER, J O Pacific Gas & Elettric Co 2pp 22517 145 24X Fiche 50-275, 84/02/17, 8403060207
- --B403060223 IE Insp Repts 50-275/84-01 & 50-323/84-01 on B40103-06 Noncompliance noted failure to perform safety-related welding activities in area of structural steel welding activities BURDOIN, J.F., KIRSCH, D.F. Region 5, Défice of Director B4/02/17 4pg 22517 149 24X Fichs 50-323, B4/02/17, B403040207
- B40:190072 IE Info Notice B4-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN: E L Division of Emergency Preparadness & Engineering Response (Post B30103) B4/02/2B Consolidated Edison Co of New York, Inc. 115pp 22707 239 24X Fiche 50-000.84/02/2B, B401190072
- 8403040131 Forwards IE Insp Repts 50-275/83-37 & 50-323/83-25 on 831114-18 & 1128-1209 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 84/02/29 SCHUVLER.J D Pacific Gas & Electric Co 2pp 22506 273 24X Fithe 50-275,84/02/29,8403040131
- --8403060143 Notice of violation from insp on 831114-18 & 1128-1209 CANTER.H L Region 5. Office of Director 84/02/29 2pp 22506 275 24X Fiche 50-275.84/02/29.8403060131
- --8403060149 IE Insp Repts 50-275/83-37 & 50-323/83-25 on 831114-18 & 1128-1209 Noncompliance hoted failure to assure that welding inspectors qualified & certified per procedural requirements HERNANDEZ.0 H , ROSS, T M , KIRSCH.D F Region 5. Office of Director 84/02/29 49pp 22504 277 24X Fiche 50-275.84/02/29, 8403060131
- 8402090007 IE Info Notice 84-14. "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl GRACE, J N Division of QA: Bafeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York. Inc 130pp 22552 329 24x Fiche 50-000.84/03/02.8402090007
- 8402070008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 122pp 22553 078 24X Fiche 50-000,84/03/02,8402070008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases" Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/02 Consolidated Edison Co of New York, Inc 119pp 22553 217 24X Fiche 50-000.84/03/02,8402090009
- B402090011 IE Info Notice B4-17, "Problems H/Liquid Nitrogen Cooling Components Below Ni) Ductility Temp " Bvc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4703705 Consolidated Edison Co of New York, Inc 117pp 22553 336 24% Fiche 50~000,84/03/05,8402090011
- 8402090022 Board Notification 84-043 submits info re grams & measurements by Parameter, Inc of radiographs & field uslds & delta ferrite measurements of selected welds under Contract NRC-05-82-249
 EISENHUT, D 0 Division of Licensing NRC-05-82-249 84/03/05 PALLADINO, GILINSKY, ROBERTS Commissioners 3pp 22556 247 24X Fichar 50-275,84/03/05,8402090022
- --8403080193 Forwards "Project Quality Plan for Providing Assistance & Sves to Support NRC/IE Region IV Personnel in NDE & Review of Radiographs," per Task Order 55 of Contract NRC-05-82-249

 LOFY.R A Parameter, Inc. NRC-05-82-249 83/11/23 KIRECH, D Region 5, Office of Director ip 22556 250 24X

 Fiche 50-275,84/03/05,8402090022
- --8403080197 "Project Quality Plan for Providing Assistance & Svcs to Support NRC/IE Region IV Personnel in NDE & Review of Radingraphs at Diable Canyon, Units 1 & 2 "FULEY, H J . LOFY, R A Parameter, Inc NRC-05-82-247 PQP-124 B3/11/22 NRC No Detailed Affiliation Given 23pp 22356 251 24X Fichs 50-275,84/03/05,8402090022

- B402070024 IE Info Notice 84-09. Rev i, "Lessons Learned From Insps of Fire Protection Safe Shutdown Bys " Bvc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/07 Consolidated Edison Co of New York, Int 118pp 22635 049 24x Fiche 50-000,84/03/07.8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PHR Bys " Bvc list encl JORDANNE L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- B402070031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Bafety Sys " Svc list encl DEYQUNO, R C Director's Defice, Office of Inspection and Enforcement B4/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000,84/03/12,8402090031
- B402090043 IE Info Notice B4-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JURDAN E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/03/21 Consolidated Edison Co of New York, Inc 123pp. 22823 229 24X Fiche 50-000,84/03/21,8402090043
- 8402070044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22733 001 24X Fiche 50-000,84/03/21,8402079044
- 8403140244 Board Notification 84-066 forwards SECY-84-104 rs NRC inspos f Nuclear Svcs Corp audit of Pullman Power Products at site, including draft IE Imap Rept 50-275/83-37 & 840229 final rept EISENHUT, D O Division of Licensing 84/03/28 BUCK, J H , MODRE, T 8 , JOHNSON, H R Atomic Safety and Licensing Appeal Panel. 3pp 22947 070 24% Fichs 50-275,84/03/28,8403140244
- --8403200301 Provides info to Commissioners as circumstances surrounding documentation of NRC insp of 1977 Nuclear Svcs Corp audit of Pullman Power Products Co DIRCKS. M J Office of the Executive Director for Operations 84/03/02 124pp 22947 073 24X Fiche 50-275,84/03/28, 8403140244
- R Periodic operating reports & related correspondence
- 8403020443 Forwards monthly status rept of offsite emergency pregaredness for DL reviews for Jan 1984 Changes in FEMA finding dates not caused by delay due to offsite emergency planning issues
 DIRCKS,W J Office of the Executive Director for Operations.
 84/02/21 PALLADINO Commissioners 9pp 22492,083 24X Fiche 50-000.84/02/21.8403020443
- 8403230139 Forwards "Environ Investigations at Diable Cangon, 1982." WARRICK.J W. Pacific Gas & Electric Co. 84/02/28, Record Services Branch (Bocument Control Desk). 1p. 22732-341, 24X Fiche 50-275, 84/02/28, 8403230139
- --8403230141 "Environ Investigations at Diable Canyon.1982 "
 CAYOT.R F . BEHRENS.D W Pacific Gas & Electric Co 83/06/30
 760pp 22732 342 24X Fiche: 50-275.84/02/28,8403230139
- S Reportable occurrences, LERs & related correspondence
- 8403260233 Forwards summary list of deficiencies identified per iOCFR30 55(s).Part 21 & potential generic ltr repts for comments
 STAROSTECKI.R Division of Project & Resident Programs 84/02/28.
 Region i. Office of Director 7pp 22756:065 24X
 Fiche 50-000.84/02/28.8403260233
- 8403150048 Final deficiency rept re melfunction of valve operator mfg by Limitorque Initially reported on 830627 Existing screws will be replaced on affected valves prior to fuel load, Maint procedures modified SCHUYLER.J D Pacific Gas & Electric Co 84/03/01 MARTIN.J B. Region 5. Office of Director. ip 22641 014 24X Fiche 50-323.84/03/01.8403150048
- 8403080405 Further response to FOIA request for documents re BER related to operation of facilities Forwards App B documents. App A & B documents available in PDR Review of remaining documents subj to request in progress FELTON, J M Division of Rules and Records 84/03/02 QARDE, B P Government Accountability Project 4pp 22583:073 24X Fiche.50-275,84/03/02,8403080405

- --8403080421 Requests assistance in addressing improper design activities re use of U-bolts & code break (code boundary) design.per affidavit re allegations
 BISHOP.T W Division of Resident.Reactor Project & Engineering Programs 83/11/29 EISENHUT.D 0 Division of Licensing 15pp 22583 093 24X Fiche 50-275,84/03/02.8403080405
- 8403130121 PNO-V-84-013 on 840307. Bechtel laborer suffered heart attack while working in auxiliary bldg Medical attention provided to individual at site Individual pronounced dead upon arrival at Sierra Vista Hosp DODBS.R T Region 5. Office of Director 84/03/07 1p 22640 218 24% Fiche 50~275,84/03/07.8403130121

T. Hearing transcripts on non-antitrust matters

- E402070032 Board Notification E4-04B forwards transcript of 840125 ageting re allegations concerning small bore piping Review & swaluation of allegations continuing EIBENHUT.D G Division of Licensing 84/03/13 PALLADING. OILINSKY, ROBERTS Commissioners 3pp 67217 046, 24X Fiche 50-275.84/03/13.8402070032
- --8403150136 Forwards transcript of 840125 meeting re allegations concerning small bore piping Info excised to protect confidentiality of NRC sources & preclude compromising angoing insps
 #ISHOP.T W Region 5. Office of Director B4/02/23
 BTRUMMASSER.M California, State of 1p 22645 004 24X
 Fiche 50-275,84/03/13,8402070032
- --BAQ3150144 Forwards transcript of 840125 meeting re allegations concerning small bore piping Info excised to protect confidentiality of NRC sources & preclude compromising angoing inspa
 BIBHOP:T W Region 5, Office of Director 84/02/23 REYNOLDS, J
 Center for Law in the Public Interest 1p 22645 005 24X
 Fiche 50-275,84/03/13,8402090032
- --B403130132 Forwards transcript of 840125 meeting re allegations concerning small bore piping Info strised to protect confidentiality of NRC sources & preclude compromising ongoing insps
 BISHOP,T W Region 5. Office of Director. 84/02/23 CRANE,P A Pacific Gas & Electric Co ip 22645 006 24X
 Fichs 50-275,84/03/13,8402090032
- --8403150159 Forwards transcript of 840125 meeting re allegations concerning small bore piping Info excised to protect confidentiality of NRC sources & preclude compromising ongoing Insp.
 818HOP.T W Region 5, Office of Director 84/02/23 NORTON Norton. Burks, Berry & French 1p 22645 007 24X
 Fiche. 50-275, 84/03/13, 8402090032
- --8403150162 Excised transcript of 840125 closed meeting w/C Stokes re allegations concerning small bore piping Pp 1-220 # NRC - No Detailed Affiliation Given 84/01/25 319pp 22645 008 24X Fiche 50-275,84/03/13,8402090032

U. Congressional/Executive Correspondence

- 8403260106 Provides current status of facility licensing process in response to 840126 ltr. Since 840124 hearings. NRC has continued investigation, insp & evaluation of allegations, which will be resolved prior to low power authorization. DENTON, H R Dffice of Nuclear Reactor Regulation, Director 84/03/09 MCCARTHY, L T California, State of 4pp. 22761 356 24X Fiche: 50-275,84/03/09,8403260106.
- --840326011 Expresses concern re possibility that facility will be licensed w/o meeting safety stds HCCARTHY,L T. California, State of 84/01/26 PALLADIND,N Commissioners ip 22761 357 24X Fiche. 50-275,84/03/09,8403260106
- 8403270367 Telecopy ltr expressing concerns re lifting of suspended low power license. Commission should carefully weigh ABLAB conclusions & fulfill responsibility to require safe plant operation.

 THOMAS.W M. House of Rep. DSB 143, 84/03/26 PALLADINO, N Commissioners. 2pp 22789,002 24X Fiche 50-275,84/03/26.

V. Operator Examinations

B403220035 Forwards tables providing detailed operating experience for licensed operating personnel & licensed & nonlicensed shift technical advisors SCHUVLER, J. D. Pacific Gas & Electric Co 84/03/16 DENTON, H R Uffice of Nuclear Reactor Regulation, Director 5pp 22718 208, 24X Fiche: 50-275, 84/03/16, 8403220035

8403260176 Informs of plans to have shift advisors w/qualifications & training recommended by Near-Term DL Util Group on staff prior to exceeding 3% power Advisors will be subj to final exam following training SCHUYLER, J D Pacific Gas & Electric Co 84/03/23 KNIGHTUN, O W Licensing Branch 3 Ip 22758 234 24X Fiche 50-275,84/03/23,8403260176

DOCKET 50-324 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 2

F Security, medical, emergency & fire protection plans

- 8403060567 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee.per Bio709 Generic Ltr B1-27 W/o request.entire plan will be placed in PDR VASBALLO.D B Operating Reactors Branch 2 84/02/10 UTLEY, E E Carolina Power & Light Co 2pp 22552 263 24X Fiche 50-324.84/02/10,8403060567
- B403020118 Summary of 840202 meeting w/util in Bethesda, MD re exemptions from 10CFR50. App R requirements & plans concerning alternate shutdown capability to constitute acceptable level of fire protection MACKAY. B Operating Reactors Branch 2 84/02/21 Operating Reactors Branch 2 3pp 22491 174 24X Fiche 50-324, 84/02/21. 8403020118
- 8403020159 Notification of 840315 meeting w/util in Bethesda, MD to discuss progress rept on fire protection, alternate shutdown sys, IOCFR, App R exemptions & overall completion schedule MACKAY, S D Operating Reactors Branch 2 84/02/22 VASBALLO, D B Operating Reactors Branch 2 2pp 22471 141 24X Fiche 50-324,84/02/22,8403020159
- 8403090066 Forwards order confirming licenses commitments re emergency response capability Order based on 830415 % 1014 responses committing to specified action W/o encl VABBALLO, D B Operating Reactors Branch 2 84/02/22 UTLEY, E Carolina Power & Light Co ip 22575 353 24X Fiche: 50-324, 84/02/22, 8403090066
- 8403140236 Forwards order confirming licensee commitments on emergency response capability VASBALLO.D B Operating Reactors Branch 2 84/02/22 UTLEY, E E Carolina Power & Light Co 2pp 22636 353 24X Ficha 50~324.84/02/22,8403140236
- --8403140239 Order confirming licensee commitment on emergency response capability per Generic Ltr 82-33 (Buppl 1 to NUREG-0737)
 EIBENHUT, D Q Division of Licensing 84/02/22 Carolina Power & Light Co 5pp 22636 355 24% Fiche 50-324,84/02/22, 8403140236
- 8403060140 Forwards payment of Class III & Class I amend fees for B21213 & 830502 applications re radiological effluent Tech Specs & App R exemption requests respectively CUTTER.A B Carolina Power & Light Co 84/02/29 MILLER.W O License Fee Management Branch ip 22513 349 24X Fiche: 50-324, 84/02/29, 8403060140
- B403260089 Summary of B40216 meeting w/util in Bethesda.MD re util progress on alternate shutdown capability assessment & mods required by 100FR50.App R Agenda encl MACKAY.B Operating Reactors Branch 2 84/03/01 Operating Reactors Branch 2 84/03/01 B403260089
- B403160283 Advises of 840316 meeting in Region II ofc to discuss App R requirements & results of recent App R insps Attendance should be limited to six util employees

 LEMIS.R C Division of Project & Resident Programs 84/03/02

 UTLEY.E E Carolina Power & Light Co 1p 22660 107 24X

 Fiche 50-000.84/03/02.8403160283
- 8403290086 Forwards IE Insp Repts 50-324/84-04 & 50-325/84-04 on 840115-0215 No violations or deviations identified VERRELLI.D M Division of Project & Resident Programs 84/03/07 UTLEY; E E Carolina Power & Light Co 2pp 22806 328 24X Fiche 50-324.84/03/07.8403290086
- --8403270092 IE Insp Repts 50-324/84-04 & 50-325/84-04 on 840115-0215 No violations or deviations identified Major areas inspected surveillance, maint, operational safety verification. ESF syswalkdown, in-office LER reviews & fire protection MYERS; D O : OARNER, L W : PATTERSON, C Region 2, Office of Director 84/03/06 lipp 22806 330 24X Fiche 50-324,84/03/07,8403290086

- 8403200033 Rev i3 to emergency response plan.Vol XIII.Book 1 M/840315 transmittal form BOYER.L Carolina Power & Light Co 84/03/14 18pp 22685 167 24X Fiche 50-324.84/03/14.8403200033
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8402270263 Responds to FOIA request for JC Mark 801204 memo to ACRB re hydrogen burn w/igniters & documents concerning generation, combustion or control of hydrogen in reactor accidents Forwards App A documents App B documents in PDR FELTON, J M Division of Rules and Records 84/01/30 HIATT, B L Ohio Citizens for Responsible Energy 7pp 22412 051 24X Fiche 50-000.84/01/30.8402270263
- --8402270314 Forwards summary of investigations re hydrogen recombiners & relay failures in HPCI sys
 ZUKOR, D.J. ACRS Advisory Committee on Reactor Bafeguards
 B0/10/30 MCELLER, D.W. ACRS -- Advisory Committee on Reactor
 Safeguards 4pp 22412 OBA 24X Fiche 50-000,84/01/30.
- P Operating license stage documents & correspondence
- 8403060053 Forwards corrected Tech Spec Pages 3/4 3-42 & 3/4 6-2 to 403060053 Forwards corrected Tech Spec Pages 3/4 3-42 & 3/4 6-2 to Amend 39 to License DPR-71 & Amends 65 & 91 to Licenses DPR-72 & DPR-62, respectively VASSALLO, D B Operating Reactors Branch 2 84/02/10 UTLEY, E Carolina Power & Light Co. 2pp 22528 305 24X Fiche 50-324, 84/02/10, 8403060053
- --8403060056 Corrected Tech Spec Pages 3/4 3-42 & 3/4 6-2 to Amend 59 to License DPR-71 & Amends 65 & 91 to Licenses DPR-71 & DPR-62,
- 8403060067 Forwards request for addl info re util 820907 request for (03060067 Forwards request for add into relect 12070/ request for license amend to reflect miscellaneous Tech Spec revs Response requested within 60 days of ltr receipt VASSALLO.D B Operating Reactors Branch 2 84/02/10 UTLEY, E E Carolina Power & Light Co. 4pp 22528 299 24X Fichs 50-324.84/02/10.8403060067
- 8403060069 Forwards request for add1 info re inservice testing of pumps & valves in order to complete review of 831012 submittal Response requested within 45 days of itr receipt VASSALLO, D B Operating Reactors Branch 2 84/02/10 UTLEY, E Carolina Power & Light Co 3pp 22528 296 24X Fiche 50-324,84/02/10,8403060069
- 8403060073 Forwards request for add1 info re util 831121 request for approval to dispose of waste lubricating oflis containing trace amounts of licensed radicattive meth by onsite combustion Response requested within 60 days VASSALLO.9 B Operating Reactors Branch 2 84/02/15 UTLEY.E E Carolina Power & Light Co 3pp 22528 293 24X Fiche 50-324.84/02/15,8403060073
- 8403140340 Summary of 831215 meeting w/GE & Mark I Owners Group in Bethesda:MD re Mark I containment wetwell-drywell vacuum breaker design methodology SIEGEL, B L Operating Reactors Branch 2 84/02/21 Operating Reactors Branch 2 Sipp 22635 198 24X Fiche 50-000, 84/02/21, 8403140340
- 8403150124 Summary of 840202 meeting w/uti), INEL, Bechtel & Southern Svcs Co in Bethesda, MD re equipment environ qualifications Proposed schedule for implementation will be submitted by 840322 Agenda & attendance list encl GROTENHUIS.M Operating Reactors Branch 2 84/02/22 Operating Reactors Branch 2 5pp 22646 354 24x Fiche 50-324, 84/02/22, 8403150124 Operating
- 8403060300 Application for amend to Licenses DPR-71 & DPR-62, revising Tech Spec 4 i 2 a to clarify when reactivity anomaly surveillance performed Revs supplement & supersede changes in 831229 ltr HOME,P W Carolina Power & Light Co 84/02/28 V. Operating Reactors Branch 2 Jpp 22516 001 24X Fiche 50-324.84/02/28.8403060300 VASSALLO, D B
- --8403060302 Proposed changes to Tech Spec 4 i 2 a to clarify when reactivity anomaly surveillance performed

 • Carolina Power & Light Co 84/02/28 2pp 22514 004 24X
 Fiche 50-324,64/02/28,8403050300

- B403070157 Application supplementing B20316, B30623 & 0706 requests for amend to Licenses DPR-62 & DPR-71, consisting of Tech Spec changes for Item 9 re isolation of HPCI & RCIC mod (NUREO-0737, Action Item II K 3 15) & Generic Ltr B3-02 HOWE, P W Carolina Power & Light Co B4/02/28 VASSALLO, D B Decrating Reactors Branch 2 2pp 22538 316 24X Fichs 50-324, B4/02/28, B403070157
- --8403070162 Proposed Tech Spec changes for Item 9 re isolation of HPC1 & RCIC mod (NUREG-0737, Action Item II K 3 15) & Generic Ltr 63-02 84/02/28 31pp 22538 318, 24X * Carolina Power & Light Co 8 Fiche 50-324,84/02/28,8403070157
- B403060140 Forwards payment of Class III & Class I amend fees for 821213 & 830302 applications re-radiological effluent Tech Specs & App R exemption requests, respectively CUTTER. A B Carolina Power & Light Co 84/02/29 MILLER, W O, License Fee Management Brench 1p 22513 349 24X Fiche B0-324, B4/02/29, B403040140
- 8403060167 Advises that NUREG-0737, Action Items II K 3 30 & II K 3. 31 NUMBER OF Advises that NUREG-0737.Action Items II K 3 30 % II K 3. 31 considered complete based on 840104 telcon between NRC & GE Licensee need only identify to NRC ref on docket to GE Topical Rept NEDO-20566 or NEDO-20566P ZIMMERMAN, B R Carolina Power & Light Co 84/02/29 VASSALLO, D. B. Operating Reactors Branch 2 2pp 2251B 334. 24X Fiche 50-324.84/02/29,8403060167
- 8403060276 Forwards POBI-SEAL Intl.Inc. "LOCA & Seismic Analysis, Brunswick Steam Electric Plant," to demonstrate valve operability.in response to NRC 831201 request HUNE.P W Carolina Power & Light Co 84/02/27 VARGA,8 A Operating Reactors Branch i 3pp 22512 001 24X Fiche 80-324,84/02/27,8403060274
- --8403060304 "LDCA & Seismic Analysis Brunswick Steam Electric Plant "
 * Posi-Beal Valves International 325258L-001 84/02/15, 470pp
 22512 006 24X Fiche 50-324,84/02/27,8403060276
- B403|40287 Forwards evaluation of revised operator requalifications program Rev meets requirements specified in 10CFR50 55.App A & acceptable program KeV meets requirements spectred in 100rm30 55.App A & acceptable VABSALLO,D B Ogerating Reactors Branch 2 84/02/29 UTLEY,E E Carolina Power & Light Co 3pp 22695 360 24X Fiche 30-324.84/02/29.8403140287
- 8403090252 Application to amend Licenses DPR-71 & DPR-62, revising Tech Specs re accident monitoring instrumentation per NUREO-0737 & Generic Ltr 83-36 HOME,P W Carolina Power & Light Co 84/03/02 VASSALLO,D B Operating Reactors Branch 2 7pp 22571 192 24X Fiche, 50-324, 84/03/02, 8403090252.
- --8403090240 Proposed Tech Specs re limiting conditions for operation k surveillance requirements for accident monitoring instrumentation per NUREG-0737 & Generic Ltr 83-36 * Carolina Power & Light Co 84/03/02 21pp 22571 199 24% Fiche 3D-324,84/03/02,8403090252
- B403210041 Forwards response to 840202 request for add1 info re NUREG-0737. Items II F 1 4, "Containment Pressure Monitor Bys." II F 1 5, "Containment Water Level Monitor Sys" & II F 1 6, "Containment Hydrogen Monitor Sys." ZIMMERMAN, B R Carolina Power & Light Co 84/03/07 VABSALLO, D. B Operating Reactors Branch 2 20pp 22705 001 24X Fiche 30-324.84/03/09.8403210061
- 8403210129 Responds to 840202 request re TMI Action Item 11, X 3 18 903210129 Responds to 840202 request re TMI Action Item II.K 3 concerning automatic depressurization sys (ADS) logic mods. High drywell pressure permissive eliminated & manual inhibit switches to ADS logic added HOWE, P.W. Carolina Power & Light Co. 84/03/09 VASBALLO, D. B. Operating Reactors Branch 2. Ip. 22707 235 24X Fiche 50-324,84/03/09.8403210129
- B403:50275 Generic Ltr 84-07 to all licensees of BWRs re procedural guidance for pipe replacement at BWRs 8vc list encl EISENHUT.D 9 Division of Licensing 84/03/14 Commonwealth Edison Co 20pp 22823 334 24% Fichs 50-000:84/03/14,8403150275
- 8403300254 Notification of 840321 meeting w/util in Bethesda,MD to discuss status of battery review study GROTENHUIS.M Operating Reactors Branch 2 84/03/14 VASBALLO,D 8 Operating Reactors Dranch 2 1p 22844 352 24X Fiche 50-324.84/03/14.8403300254

- 8403210075 Forwards add1 info re BWR steady-state analysis methods.per NRC 840117 request Answers provided to 12 of 15 questions raised by NRC G2 will provide input to Questions 4.8 % 13 Add1 responses will be submitted by 840521

 IIMMERNAN,S R Carolina Power & Light Co 84/03/15 VASSALLO,D 8 Operating Reactors Branch 2 2pp 22705 122 24X
 Fiche 50-324,84/03/15,8403210075
- --8403210080 Amend 1 to "Verification of Carolina Power & Light Ref BWR Thermal-Hydraulic Methods Using FIBWR Code " KUNITA:R X Carolina Power & Light Co NF-1583 04-1 AO1 84/03/31 41pp 22705 124 24X Fiche 50-324.84/03/15.8403210075
- B403300299 Notifies that Class III & Class I fees for review of 830929 application re feedwater & main turbine trip/bypass sysbeing refunded due to withdrawai of application MILLER.W O License Fee Management Branch 84/03/15 JONES, J A Carolina Fower & Light Co 2pp 22844 309 24X Fiche 50-324, 84/03/15, 8403300299
- 8403270083 Responds to 840221 request for add1 info re control of heavy loads Initial load testing performed for head strongback, dryer separator sling & spent fuel cask yoke ZIMMERMAN, B R Carolina Power & Light Co 84/03/20 VASSALLO, D B Operating Reactors Branch 2 2pp 22806 325 24X Fiche.50-324, 84/03/20.8403270083
- Q Inspection reports. IE Bulletins & correspondence
- 8403070307 Forwards IE Insp Repts 50-324/83-42 & 50-325/83-42 on 831215-840115 No violations or deviations noted VERRELLI,D M Division of Project & Resident Programs 84/02/06 UTLEY,E E Carolina Power & Light Ca 2pp 22846 175 24X Ficha 50-324,84/02/06.8403070307
- --8403070310 IE Insp Repts 50-324/83-42 & 50-325/83-42 on 831215-840115 No violations or deviations noted Major areas inspected surveillance, maint, operational safety verification, ESF sys walkdown, LER review, independent insp & plant transients MYERS, D.D. QARNER, L.W. Region 2, Office of Director BEMIS, P.R. Bivision of Project & Resident Programs 84/02/03 Spp 22546 177 24X Fiche 50-324,84/02/06,8403070307
- B403140271 Forwards request for add1 info on IE Bulletin 80-11 re masonry wall design Response requested in 60 days VABBALLO,D B Operating Reactors Branch 2 84/02/21 UTLEY,E E Carolina Power & Light Co 13pp 22635 336 24X Fiche 50-324,84/02/21,8403140271
- 8403070200 Informs that start date for mid-cycle insp in response to NRC concerns re intergranular stress corrosion cracking should be changed to 841102 HOWE.P.W. Carolina Power & Light Co 84/02/27 DENTON, H R Office of Nuclear Reactor Regulation, Director ip 22538 353 24X Fiche.50-324,84/02/27,8403070200
- 84D1190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Syc list ancl.

 JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22909 239 24X Fiche. 50-000.84/02/28.8401190072
- B402090007 IE Info Notice B4-i4, "Highlights of Recent Transport Regulatory Revs by DUT & NRC " Svc list encl GRACE.J N Division of GA, Safeguards & Inspection Programs (Post B30103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000.84/03/02.8402090007
- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Bys Valves to Operate." Syc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 122pp. 28553 098 24X Fiche 50-000.84/03/02.8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases"

 Bvc 11st encl

 JURDANIE L. Division of Emergency Preparedness & Engineering

 Response (Post 830103) 84/03/02 Consolidated Edison Co of New

 York, Inc 119pp. 22553 217 24X Fiche 50-000,84/03/02.8402090009
- 8402070011 IE Info Notice 84-17. "Problems W/Liquid Nitragen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc. 117pp 22553 336 24% Fiche 50-000,84/03/05,8402070011
- 8402070024 IE Info Notice 84-07. Rev i, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN.E L Division of Emergency Preparadness & Engineering Response (Post 830103). 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000.84/03/07.8402090024

- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Sys " Svc list encl JORDAN, E L Division of Emergency Preparedness'& Engineering Response (Post 830103) 84/03/07 Consulidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8403290086 Forwards IE Insp Repts 50-324/84-04 & 50-325/84-04 on 840115-0215 No violations or deviations identified VERRELLI.D M Division of Project & Resident Programs 84/03/07 UTLEY, E E Carolina Power & Light Co 2pp 22806 328 24X Fiche 50-324,84/03/07,8403290086
- --8403270092 IE Insp Repts 50-324/84-04 & 50-325/84-04 on 840115-0215 No violations or deviations identified Major areas inspected surveillance, maint operational safety verification, ESF sys walkdown, in-office LER reviews & fire protection MYERB, D. D., GARNER, L. W., PATTERSON, C. Region 2, Office of Director 84/03/06 lipp 22806 330 24X Fiche 50-324,84/03/07,8403290084
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Syc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement E4/03/12 Consolidated Edison Co of New York. Inc 134pp 22823 094 24X Fiche 50-000.84/03/12,8402090031
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" 8vc list encl JORDAN, E.L. Division of Emeryency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24% Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info, Notice 84-20, "Svc Life of Relays in Safety-Related Bys "Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/21 Consolidated Edison Co of New York, Inc 135pp 22733 001 24X Fiche 50-000, B4/03/21, B402090044
- R Periodic operating reports & related correspondence
- 8403130333 Monthly operating repts for Feb 1984 W/840305 ltr HARRISON, F., DIETZ, C.R. Carolina Fower & Light Co. 84/02/29 DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement 18pp 22614 197 24X Fiche 50-324.84/02/29, 8403130333
- S Reportable occurrences, LERs & related correspondence
- 8305060337 Forwards technical rept "Air in Reactor Water Cleanup Sys Instrument Sensing Lines," detailing 821216 transmitter malfunction Engineering evaluation should be performed SALAH, 8 Reactor Operations Analysis Branch 83/04/25 SEYFRIT.H V Reactor Operations Analysis Branch 1p 22789 304 24X Fiche 50-324,83/04/25,8305060337
- --8305060342 "Air in Reactor Water Cleanup Sys Instrument Sensing Lines." describing 821216 transmitter malfunction
 * Reactor Operations Analysis Branch 83/04/25 4pp 22789 305 24X Fiche 50-324.83/04/25.835060337
- B403010135 Updated LER 80-113/03L-1 on B01211.primary containment atmospheric control inerting inlat isolation valve Z-CAC-V48 discovered w/dual open-close position indication Caused by defective limit switch W/840222 ltr
 ALLEN.M T . DIETZ. C R Carolina Power & Light Co 84/02/22 D'REILLY.J F Region 2. Office of Director 3pp 22436 001 24X Fiche 50-324.84/02/22,8403010135
- 8403010299 Updated LER 62-123/03L-4 on 821010, loss of 4,140-volt amergency bus E-3 occurred Caused by startup output & dissel generator output breakers failing to close when unit auxiliary transformer opened W/840222 ltr POULK, R. M., DIETZ, C. R. Carolina Power & Light Co. 84/02/22 O'REILLY, J. P. Region 2, Office of Director 4pp. 22432 113 24X Fichs 30-324,84/02/22,8403010299
- 8403090235 RO 2-83-1 on 840124,ECCS actuation instrument E41-L8-NoO3 found inoperable Caused by instrument venting line problem Investigation & evaluation incomplete Next rept will be submitted by 840316
 DIETZ.C R Carolina Power & Light Co 84/02/22 O'REILLY,J P Region 2. Office of Director ip 22572 292 24X
 Fiche 50-324,84/02/22.8403090235
- 8403010395 RO 2-8R-84-3 on 840110.Co-60 concentration in bottom sediment sample exceeded Tech Spec limit Surface water samples in intake & discharge canals & ocean showed no Co-60 activity Sample frequency increased DIETZ.C R Carolina Power & Light Co 84/02/24 O'REILLY, J P Region 2. Office of Director 2pp 22434 048 24X Fiche 50-324,84/02/24,8403010395

- 8403090023 RO 2-84-2 on 840127, while placing equipment clearance on emergency diesel generator 4. emergency ac bus E-4 inadvertently rendered inoperable Review of event incomplete Next rept will be submitted by 840309 DIETZ.C R Carolina Fower & Light Co 84/02/28 O'REILLY, J.P. Region 2. Office of Director 10 22575 353 24X Fiche 50-324.84/02/28.8403090023
- 8403130301 Followup RO 2-SR-B4-2 in Sept 1982.Co-60 detected in bottom sediments collected in stilling basin Increase in radioactivity probably caused by increased releases of Co-60 due to general decontamination effort DIETZ.C R Carolina Power & Light Co 84/02/29 O'REILLY, J P Region 2. Office of Director 9pp 22608 047 24X Fiche 50-324.84/02/29.8403130301
- 8403130152 LER 84-002-CO on 840129, diesel generator output breaker 125volt de normal control power breaker inadvertently deenergized Caused by auxiliary operator not adhering to procedures Breaker properly labeled W/840302 ltr PASTVA.M J. DIETZ.C R. Carolina Power & Light Co. 84/03/02 0'REILLY.J P. Region 2. Office of Director 4pp 22608 225 24X Fiche 50-324,84/03/02.8403130152
- 8403200324 Discusses failure of Battery 2A2 to pass required capacity test in Dec 1983 Incident may lead to further changes in Tech Specs.procedure rev or mods of battery electrical sys LAINAS.G C Assistant Director for Operating Reactors 84/03/05 RUBENSTEIN.L S Division of Engineering 2pp 22709 146 24X Fiche 50-324.84703/05.8403200324
- 8403150179 Forwards updated LER 82-123/03L-4 DIETZ.C R Carolina Power & Light Co 84/03/07 O'REILLY, J P Region 2. Office of Director 1p 22642 090 24x Fiche 50-324, 84/03/07, 8403150179
- 8403150186 Forwards updated LER 80-113/03L-1 DIETZ.C R Carolina Power & Light Co 84/03/07 O'REILLY, J P Region 2. Office of Director 2pp 22642 285 24X Fiche 50-324,84/03/07. 8403150186
- 8403130078 RD 2-84-01 re E41-LS-NO03 vent line problem Investigation & evaluation completed & event determined not reportable per 1002FR50 73
 DIETZ.C R Carolina Power & Light Co 84/03/09 O'REILLY, J P Region 2. Office of Director 1p 22614 304 24X
 Fiche 50-324.04/03/09.8403130078
- 8403130406 Special Rept 2-SR-84-4 on B40204, fire barrier limiting conditions for operation initiated to permit repair of inoperable Fire Door 108 Distortion of door upper hings prevented door from latching properly Door returned to svc DIETZ.C R Carolina Power & Light Co 84/03/09 D'REILLY.J P Region 2, Office of Director 1p 22616 049 24X Fiche 50-324.84/03/09.8403130406
- 8403150090 NPDES noncompliance notification on 840221, discovered one cooling water pump bay w/o screens Caused by repair work to damaged bearing on pump screen 2D & problems w/starting pump Outage scheduled for 840310 to replace pump FURR. B J Carolina Power & Light Co 84/03/12 WAKILD. C North Carolina, State of ip 22640 361 24% Fichs 50-324, 84/03/12, 8403150090
- 8403210123 Updated LER 83-018/03L-1 on 830930, traverse in-core probe (TIP) detector C would not fully retract from core, rendering TIP C guide tube primary containment isolation ball valve inoperable Caused by damaged connector W/830314 ltr PASTVA, M J. DIETI, C R. Carolina Power & Light Co. 84/03/14. O'REILLY, J.P. Region 2, Office of Director 2pp 22707 183 24x Fiche 50-324,84/03/14,8403210123
- 8403200273 LER B4-003-00 on 840214, normal power supply feeder emergency bus E-4 automatically opened due to bus undervoltage condition sensed by bus degraded voltage relay 27DV. Cause unknown W/840315 ltr PASTVA. M J. DIETZ. C R Carolina Power & Light Co 84/03/15 3pp 22876 123 24X Fiche 50-324.84/03/15.8403200273
- 8403200207 Forwards preliminary findings of investigation re LER 2-83-95 Failurs to recognize or correct mechanical seal penetration fire rating deficiency & summary of deficiencies discussed DIETZ, C R Carolina Power & Light Co 84/03/16 Record Services Branch (Document Control Dast) App. 22700,001 24X Fiche 50-324,84/03/16,8403200207
- 8403270266 LER 84-004-00 on 840222 while testing primary containment isolation sys of reactor low water level.logic channel NO254A-i. MBIV 821-F028D closed-resulting in reactor scram Cause6 by ack dc solenoid valves deenergized W/840323 ltr PASTVA.M J., DIETZ.C R Carolina Power & Light Co 84/03/23 4pp 22772 023 24X Fiche 50-324.84/03/23,8403270266

- DOCKET 50-325 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8403060567 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licenses, per 810709 Generic Ltr 81-27 W/o request, entire plan will be placed in PDR VASSALLO, D B Operating Reactors Branch 2 84/02/10 UTLEY, E E Carolina Power & Light Co 2pp 22952 263 24X Fiche 50-324.84/02/10.8403060567
- 8403020118 Summary of 840202 meeting w/util in Bethesda. MD re exemptions from 10CFR50. App R requirements & plans concerning alternate shutdown capability to constitute acceptable level of fire protection MACKAY. 8 Operating Reactors Branch 2 84/02/21 Operating Reactors Branch 2 3pp 22491 174 24X Fiche 50-324,84/02/21.
- 8403020159 Notification of 840315 meeting w/util in Bethesda, MD to discuss progress rept on fire protection, alternate shutdown sys. 10CFR. App R exemptions & overall completion schedule MACKAY. S D Operating Reactors Branch 2 84/02/22 VASSALLO, D B Operating Reactors Branch 2 2pp 2247i 141 24X Fiche 50-324, 84/02/22, 8403020159
- 8403090066 Forwards order confirming licenses commitments re emergency response capability Order based on 830415 & 1014 responses committing to specified action W/o encl VASSALLOD B Operating Reactors Branch 2 84/02/22 UTLEY, E Carolina Power & Light Co ip 22575 353 24X Fiche 50-324,84/02/22,8403090066
- 8403140236 Forwards order confirming licensee commitments on emergency response capability
 VASBALLO, D B Operating Reactors Branch 2 84/02/22 UTLEY, E E Carolina Power & Light Co 2pp 22636 353 R4X
 Fiche 50-324,84/02/22,8403140236
- --8403140239 Order confirming licensee commitment on emergency response capability per Generic Ltr 82-33 (Suppl 1 to NUREC-0737) EISENHUT.D G Division of Licensing 84/02/22 Carolina Power & Light Co 5pp 22636 355 24X Fiche 50-324,84/02/22, B403140236
- B403060140 Forwards payment of Class III & Class I amend fees for B21213 & B30502 applications re radiological effluent Tech Specs & App R exemption requests respectively CUTTER.A B Carolina Power & Light Co 84/02/29 MILLER.W D. License Fee Management Branch 12 22513 349 24X Fiche 50-324,84/02/29,8403060140
- 8403260089 Summary of 840216 meeting w/util in Bethesda, MD re util progress on alternate shutdown capability assessment & mods required by 10CFR50. App R Agenda encl MACKAY. S Operating Reactors Branch 2 84/03/01 Operating Reactors Branch 2 4pp 22763 228 24X Fiche 50-324,84/03/01,840326089
- B4031402B3 Advises of B40316 meeting in Region II ofc to discuss App R requirements & results of recent App R insps Attendance should be I inited to six util employees LEWIS:R C Division of Project & Resident Programs B4/03/02 UTLEY:E E Carolina Power & Light Co ip 22460 109 24X Fiche 50-000.84/03/02,84031402B3
- B403270086 Forwards IE Insp Repts 50-324/84-04 & 30-325/84-04 on 840115-0215 No violations or deviations identified VERRELLI, D Division of Project & Resident Programs B4/03/07 UTLEY, EE Carolina Power & Light Co 2pp 22806-328 24X Fiche 50-324.84/03/07,8403290086
- --8403290092 IE Insp Repts 50-324/84-04 & 50-325/84-04 on 840115-0215 No violations or deviations identified Major areas inspected, surveillance, maint, operational safety verification, ESF syswalkdown, in-office LER reviews & fire protection, MYERS,D O Ragion 2, Office of Director BEMIS,P R Division of Project & Resident Programs 84/03/06 iipp 22806:330 24x Fiche 50-324,84/03/07,8403270086
- 8403200033 Rev 13 to emergency response plan, Vol XIII, Book 1 W/840315 transmittal form BOYER.L Carolina Power & Light Co 84/03/14 18pp 22685: 167. 24X Fiche 50-324, 84/03/14, 8403200033

- D. Advisory Committee on Reactor Safeguards reports & correspondence
- 8402270263 Responds to FDIA request for JC Hark 801204 memo to ACRS re hydrogen burn w/igniters & documents concerning generation, combustion or control of hydrogen in reactor accidents Forwards App A documents App B documents in PDR FELTON, J M Division of Rules and Records 84/01/30 HIATT, S L Ohio Citizens for Responsible Energy 7pp 22412 051 24X Fichs 80-000,84/01/30,8402270263
- ---8402270314 Forwards summary of investigations re hydrogen recombiners & relay failures in HPCI sys
 ZUMOR, D. J. ACRE Advisory Committee on Reactor Safeguards
 80/10/30 MDELLER, D.W. ACRE Advisory Committee on Reactor
 8afeguards 4pp 22412 086 24X Fiche 50-000,84/01/30,
 8402270263
- P. Operating license stage documents & correspondence
- 8403230049 Application for amend to License DPR-71, changing Tech Spec description of reactor core fuel assemblies. HOME, P. W. Carolina Power & Light Co. 84/01/31 VASSALLD, D. B. Operating Reactors Branch 2 2pp 22724 348 24X Ficha: 50-325, 84/01/31, 8403230049
- --8403230054 Proposed Tech Spec change re description of reactor core fuel assemblies = Carolina Power & Light Co. 84/01/31, 3pp. 22724,350 24X Fiche 50-325,84/01/31,8403230049
- 8403040053 Forwards corrected Tech Spec Pages 3/4 3-42 & 3/4 6-2 to Amend 59 to License DPR-71 & Amends 65 & 91 to Licenses DPR-61 & DPR-62, respectively VASSALLO, D B Operating Reactors Branch 2. 84/02/10 UTLEY, E Carolina Power & Light Co 2pp. 22528 305 24% Fiche. 50-324, 84/02/10, 8403060053
- --8403060056 Corrected Tech Spec Pages 3/4 3-42 & 3/4 6-2 to Amend 59 to Licenses DPR-71 & Amends 65 & 91 to Licenses DPR-71 & DPR-62, respectively * NRC No Detailed Affiliation Given. 84/02/10 3pp 22528:307 24X Fiche 50-324,84/02/10,8403060053
- 84030600A7 Forwards request for addl info re util 820907 request for litenes amend to reflect miscellaneous Tech Spec revs Response requested within 60 days of itr receipt VASSALLO, D. B. Operating Reactors Branch 2 84/02/10 UTLEY, E. Carolina Power & Light Co 4pp. 22528 299. 24X Fiche 50-324,84/02/10.8403060067
- 8403060069 Forwards request for add1 info re inservice testing of pumps & valves, in order to complete review of 831012 submittal Response requested within 45 days of itr receipt. VASBALLO, D B Operating Reactors Branch 2 84/02/10 UTLEY, E E Carolina Power & Light Co. 3pp 22528 294 24% Fiche: 50-324,84/02/10.8403060069
- B403040073 Forwards request for add1 info re util B31121 request for approval to dispose of wasta lubricating oils containing trace amounts of licensed radioactive matl by onsite combustion Response requested within 60 days.

 VASBALLO, D B Operating Reactors Branch 2 B4/02/15 UTLEY, E E. Carolina Power & Light Co. 3pp 22528:293 24X

 Fiche, 50-324, 84/02/45, 8403040073.
- 8403140340 Summary of 831215 meeting w/GE & Mark I Owners Group in Betheada:MD re Mark I containment wetwell-drywell vacuum breaker design methodology. BIE00EL, B. L. Opereting Reactors Branch 2 84/02/21 Operating Reactors Branch 2, 51pp 22635.178 24X Fiche: 50-000, 84/02/21, 8403140340
- 8403150124 Summary of 840202 meeting w/util. INEL, Bechtel & Bouthern Bycs Co in Bethesda. MD re equipment environ qualifications Proposed schedule for implementation will be submitted by 840322. Agenda & attendance list encl.

 OROTENHUIS, M Operating Reactors Branch 2 84/02/22 Operating Reactors Branch 2. Spp. 22646.354 24X Fiche 50-324,84/02/22,8403150124.
- 8403060300 Application for amend to Licenses DPR-71 & DPR-62, revising Tech Spec 4 1 2 a to clarify when reactivity anomaly surveillance performed Rays supplement & supersede changes in 831227 ltr.
 HOWE, P. W. Carolina Power & Light Co. 84/02/28 VASSALLO, D.B. Operating Reactors Branch 2. 3pp 22516 001 24X Fiche. 50-324, 84/02/28, 8403060300
- ---B403060302 Proposed changes to Tech Spec 4 1,2 a to clarify when reactivity anomaly surveillance performed * Carolina Power & Light Co. 84/02/20 2pp. 22516.004 24X Fiche 30-324,84/02/28,8403060300.

- 8403070197 Application supplementing 820316,830623 & 0906 requests for amend to Licenses DPR-62 & DPR-71, consisting of Tech Spec changes For Item 9 re isolation of HPCI & RCIC mod (NUREG-0737, Action Item II K 3 15) & Generic Ltr 83-02 .

 HOWE, P W Carolina Power & Light Co 84/02/28 VASSALLO, D B Operating Reactors Branch 2 2pp 22538 316 24X Fiche 50-324,84/02/28,8403070157
- ~~8403070162 Proposed Yech Spec changes for Item 9 re isolation of HPCI & RCIC mod (NUREG-0737, Action Item II K 3 15) & Generic Ltr 83-02

 * Carolina Power & Light Co 84/02/28 31pp 22938 318 24X
 Fiche 50~324,84/02/28,8403070157
- 8403060140 Forwards payment of Class III & Class I amend fees for 821213 & 830502 applications re radiological effluent Tech Specs & App R exemption requests, respectively CUTTER.A B Carolina Power & Light Co. 84/02/29 MILLER,W O License Fee Management Branch 1p 22513 349 24X Fiche: 50-324,84/02/29,8403060140
- 8403060167 Advises that NUREO-0737, Action Items II K 3 30 & II K 3 31 considered complete, based on B40104 telcon between NRC & OE Licensee need only identify to NRC ref on docket to GE Topical Rept NEDO-20366 or NEDD-20366F
 ZIMMERMAN, S. R. Caroline Power & Light Co B4/02/29 VASSALLO, D B Operating Reactors Branch 2 2pp. 22518 334. 24X
 Fichs 50-324,84/02/29,8403060167
- 8403060276 Forwards POSI-SEAL Intl. Inc. "LOCA & Seismic Analysis. Brunswick Steam Electric Plant." to demonstrate valve operability. In response to NRC 831201 request HOME, P W Carolina Power & Light Co 84/02/29 VARGA, S A Operating Reactors Branch 1 5pp 22512 001 24X Fiche: 50-324.84/02/29,8403060276
- ---8403060304 "LOCA & Seismic Analysis, Brunswick Steam Electric Plant" * Posi-Seal Valves International 325258L-001 84/02/15 470pp 22512 006 24X Fiche 50-324,84/02/29,8403060296
- 8403130452 Application to amend License DPR-71, revising Tach Spec Bection 5 3 for fuel assemblies, changing 3 00 weight percent number to 2 99 weight percent to reflect enrichment level used in reload analysis HOME:P W Carolina Power & Light Co 84/02/29 VASSALLO, D B Operating Reactors Branch 2 ip 22613 331 24X Ficha 50-325,84/02/29,8403130452
- --8403130465 Revised Tach Spec Section 5 3 1, Pages 5-1 & 5-4 changing 3 00 weight percent to 2 99 weight percent to reflect enrichment level used in reload analysis * Carolina Power & Light Co 84/02/29 2pp 22613 332 24X Fiche 50-325,84/02/29.8403130452
- 8403140287 Forwards evaluation of revised operator requalifications program Rev meets requirements specified in 10CFR50 55, App A & acceptable VABSALLO, D. B. Operating Reactors Branch 2 84/02/29 UTLEY, E E Carolina Power & Light Co. 3pp 22635.360 24X Fichs 50-324,84/02/29.8403140287
- 8403090252 Application to amend Licenses DPR-71 & DPR-62 revising Tech Bpecs re accident monitoring instrumentation per NUREQ-0737 & Generic Ltr 83-36 HOME:P W Carolina Power & Light Co 84/03/02 VASSALLO, D B Operating Reactors Branch 2 7pp 22571 192 24X Fiche 50-324,84/03/02.8403090252.
- --8403090260 Proposed Tech Specs re limiting conditions for operation & surveillance requirements for accident monitoring instrumentation per NUREG-0737 & Generic Ltr 83-36 & Carolina Power & Light Co. 84/03/02 21pp 22571 199. 24X Fiche 50-324,84/03/02,8403090252.
- 8403210061 Forwards response to 84020R request for add1 info re
 NUREO-0737, Itsms II F 1 4, "Containment Pressure Monitor
 Bys." II F 1,5. "Containment Water Level Monitor Bys." &
 II,F.1 6, "Containment Hydrogen Monitor Bys."
 ZIMMERMAN,8 R Carolins Power & Light Co 84/03/09 VASSALLO,D B
 Operating Resctors Branch 2 20pp 22705 001 24X
 Fichs 50-324,84/03/09,8403210061
- B403210129 Responds to B40202 request re TMI Action Item II K 3,18 concerning automatic depressurization sys (ADS) logic mods. High drywell pressure permissive eliminated & manual inhibit switches to ADS logic added HOME,P W Caroline Power & Light Go E4/03/09 VASSALLO,D B Operating Reactors Branch 2 1p. 22707 235, 24X Fiche:50-324.84/03/09.8403210129

- 8403150275 Generic Ltr 84-07 to all licensees of BWRs re procedural guidance for pipe replacement at BWRs Svc list encl EESENHUT.D G Division of Licensing 84/03/14 Commonwealth Edison Co 20pp 22823 354 24X Fiche 50-000.84/03/14,8403150275
- 8403300254 Notification of 840321 meeting w/util in Bethesda.MD to discuss status of battery review study OROTENHUIS:M Operating Reactors Branch 2 84/03/14 VASSALLO.D B Operating Reactors Branch 2 1p 22844 352 24X Fiche 50~324,84/03/14,8403300254
- 8403210075 Forwards additinfoire BWR steady-state analysis methods.per NRC 840117 request Answers provided to 12 of 15 questions raised by NRC 86 will provide input to Questions 4,8 & 13 Addl responses will be submitted by 84081 ZIMMERMANS R Carolina Power & Light Co. 84/03/15 VASSALLO, D B Operating Reactors Branch 2 2pp 22705 122 24X Fiche 50-324,84/03/15,8403210075
- --8403210080 Amend 1 to "Verification of Carolina Power & Light Ref BHR Thormal-Hydraulic Methods Using FIBHR Code "

 KUNITA-R K Carolina Power & Light Co NF-1583 C4-1 A01

 B4/03/31 41pp 22705 124 24X Fiche, 50-324, 84/03/15, 8403210075
- B403300299 Notifies that Class III & Class I fees for review of 830929 application re feedwater & main turbine trip/bypass sysbeing refunded due to withdrawal of application MILLER.W O License Fee Management Branch 84/03/15 JONES.J A Carolina Power & Light Co 2pp 22844 309 24X Fichs 50-324.84/03/15,8403300299
- B4032900B3 Responds to 840221 request for add1 info re control of heavy loads Initial load testing performed for head strongback, dryer separator sling & spant fuel cask yake ZIMMERMAN, S.R. Carolina Power & Light Co. 84/03/20 VASSALLO, D.B. Operating Reactors Branch 2. 2pp. 22804 325 24X Fiche 50-324,84/03/20,8403270083
- G Inspection reports. IE Bulletins & correspondence
- 8403070307 Forwards IE Insp Repts 50-324/83-42 & 50-329/83-42 on 831215-840115 No violations or deviations noted VERRELLI.D.M Division of Project & Resident Programs 84/02/06 UTLEY.E E Carolina Power & Light Co 2pp 22546 175 24X Fiche 50-324,84/02/06,8403070307
- --8403070310 IE Insp Repts 50-324/83-42 & 50-325/83-42 on B31215-840115
 No violations or deviations noted Major areas inspected
 surveillance,maint, operational safety verification. ESF sys
 walkdown.LER review.independent insp & glant transients
 MYERB.D O , OARNER.L W Region 2, Office of Director BEMIS.P R
 Division of Project & Resident Programs 84/02/03 Bpp
 22546 177 24X Fiche 50-324.84/02/06.8403070307
- 8403140291 Forwards request for add1 info on IE Bulletin 80-11 re masoury wall design Response requested in 60 days VARSALLO, D B Deprating Reactors Branch 2 84/02/21 UTLEY, E Carolina Power & Light Co 15pp 22635 336 24X Fiche 50-324,84/02/21.8403140271
- 8403070200 Informs that start date for mid-cycle insp in response to NRC concerns re intergranular stress corresion cracking should be changed to 841102 HOME.P W Carolina Power & Light Co 84/02/27 DENION.H R Office of Nuclear Reactor Regulation, Director ip 22538 353, 24x Fiche 50-324.84/02/27.8403070200
- 8403070315 Forwards Rev O to "Design Rept for Recirculation Bys Weld Overlay Repairs at Brunswick Steam Electric Flant Unit 1:" in response to concerns raised by NRC re Oct 1963 intergranular stress corrosion cracking insp HOME, P W Carolina Power & Light Co 84/02/27 DENTON, H R Office of Nuclear Reactor Regulation, Director. 3pp 22547-001 24X Fiche 50-925,84/02/27,8403070315
- --840307031B Rev 0 to "Design Rept for Recirculation Sys Weld Overlay Repairs at Brunswick Steam Electric Plant Unit 1 " CHARNLEY, J E , SUND, H J , WENNER, T J. NUTECH Engineers, Inc CPL-13-103 ROO 83/11/04 50pp 22547:004. 24X Fiche 50-325,84/02/27,8403070315
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation." Svc list encl JDRDAN, E. L. Division of Emergency Preparedness & Engineering Response (Fost 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp. 22909 239 24X Fiche 50-000,84/02/28,8401190072

- 8402070007 IE Info Notice 84-14. "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl GRACE.J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 130pp 22532 327 24X Fiche 50-000.84/03/02.8402090007
- 8402070008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Bys Valves to Operate " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22953 098 24X Fiche 30-000.84/03/02.8402090008
- 8402070007 IE Info Notice 84-15, "Reporting of Radiological Releases"

 Svc list encl

 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 84020700ii IE Infa Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22853 336 24% Fiche 50-000,84/03/05,8402090011
- 8402090024 IE Info Notice 84-09. Rev 1, "Lessons Learned From Insps of Fire Protection Bafe Shutdown Sys " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp. 22435 049 24X Fiche 30-000,84/03/07,8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Bys " Syc list enel JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- B403290086 Forwards IE Insp Repts 50-324/84-04 & 50-325/84-04 on B40115-0215 No violations or deviations identified VERRELLI,D M Division of Project & Resident Programs 84/03/07, UTLEY,E E Carolina Power & Light Co 2pp 22806 328 24X Fiche 50-324,84/03/07,8403290086
- --8403270092 IE Insp Repts 50-324/84-04 & 50-325/84-04 on 840115-0215 No viulations or deviations identified Major areas inspected surveillance, maint, operational safety verification, ESF syswalkdown, in-office LER reviews & fire protection MYERS, D D . GARNER, L W . PATTERSON, C . Region 2, Office of Director 84/03/06 lipp 22806 330 24% Fiche 50-324,84/03/07,8403270086
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Bys " Syc list encl DEVOUNG.R C Director's Office of Inspection and Enforcement B4/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24% Fiche 50-000.84/03/12,8402090031
- 8402070043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000,84/03/21,8402090043
- 8402070044 IE Info Notice 84-20. "Syc Life of Relays in Safety-Related Sys." Syc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/21 Consolidated Edison Co of New
 York, Inc 135pp 22933 001 24X Fiche 50-000.84/03/21.8402090044
- R Periodic operating reports & related correspondence
- B403130333 Monthly operating repts for Feb 1984 W/840305 ltr HARRISON, F., DIETZ, C.R. Carolina Power & Light Co. 84/02/29, DEYQUNO, R.C. Director's Office, Office of Inspection and Enforcement 18pp 22614 197 24X Fiche: 50-324, 84/02/29, 8403130333
- B Reportable occurrences. LERs & related correspondence
- 8403240411 Forwards Technical Review Rept AEDD/T304, "Cause of Containment Isolation Valve F042A to Close "
 SALAH.B Reactor Operations Analysis Branch. 83/03/23
 8EYFRIT,K V Reactor Operations Analysis Branch. 1p. 22775 309.
 24X Fiche 50-325.83/03/23.8403260411
- --B403260414 "Cause of Containment Isolation Valve F042A to Close," AEDD/T304-0BIO technical review rept * Reactor Operations Analysis Branch 83/03/23 4pp 22775:310 24% Fiche 50-325,83/03/23.8403240411

- B403010133 Updated LER 83-057/03L-1 on 831119, during unit power performance temp recorder TR-1258 printed erratically Caused by dirty electrical contacts in control board timing relay Contacts cleaned & returned to svc W/840222 ltr PABTVA,M J. DIETZ,C R. Carolina Power & Light Co. 84/02/22 D'REILLY,J P. Region 2, Defice of Director 2pp 22435 340 24X Fiche: 50-325,84/02/22,8403010133
- 8403010202 Updated LER 83-063/03L-1 on 831203, reactor water cleanup systems (RMCS) differential flow indicator i-031-R615 showed erroneous indication On 831207, spurious RMCS alarm annunciated Caused by air in sensing lines M/840222 ltr PASTVA, M J. DIETZ, C R Carolina Power & Light Co 84/02/22 D'REILLY, J P Region 2, Office of Director 3pp 22435 288 24x Fiche 50-325, 84/02/22, 8403010202
- B403150035 Updated LER B3-063/03L-1 on B31203.during unit power operation.reactor water cleanup sys differential flow indicator 1-031-R615 showed erroneous indication Caused by entrapped air in sensing line Air removed W/940307 ltr PABTVA.M J. DIETZ.C R Carolina Power & Light Co 84/02/22 O'REILLY.J P. Region 2. Office of Director 3pp 22643 287 24X Fiche 50-325.84/02/22,8403150035
- 8403010395 RO 2-8R-84-3 on 840110.Co-60 concentration in bottom sediment sample exceeded Tech Spec limit Surface water samples in intake & discharge canals & ocean showed no Co-60 activity. Sample Frequency increased BIETZ.C R Carolina Power & Light Co 84/02/24 O'REILLY, J P Region 2. Office of Director 2pp 22434 048 24X Fichm 50-324,84/02/24,8403010395
- B403090205 Special Rept 1-SR-84-1 during replacement of equipment hatch fire barrier limiting condition for operation 7-day time frame exceeded Fire watches will be maintained until work completed DIETZ.C R Carolina Power & Light Co 84/02/27 O'REILLY, J P Region 2. Office of Director 1p 22574 325 24X Fiche 50-325,84/02/27,8403090205
- 8403130301 Followup RO 2-SR-84-2 in Sept 1982, Co-40 detected in bottom sediments collected in stilling basin Increase in radioactivity probably caused by increased releases of Co-60 due to general decontamination effort DIETZ, C R Carolina Power & Light Co 84/02/29 O'REILLY, J P Region 2. Office of Director 9pp 22608 047 24X Fiche 50-324.84/02/29,8403130301
- 8403130323 LER 84-002-00 on 840203, reactor scram occurred due to high reactor vessel pressure Caused by loss of electrohydraulic control sys fluid actuation supply pressure to valves closing main turbine bypass valves W/840302 ltr PABTVA: M J, DIETZ, C R Carolina Power & Light Co 84/03/02 0'REILLY. J P Region 2, Office of Director 4pp 22614 126 24X Fiche 50-325,84/03/02,8403130323
- 8403130049 LER 84-001-00 on 840119, during attempt to initiate suppression pool cooling using Loop A of RHR svc water sys. loop pumps A & C tripped on low suction pressure lockout Caused by air in header Air vented W/840309 ltr PABTVA, M J. DIETZ, C R Carelina Power & Light Co 84/03/09 3pp 22598 355 24X Fiche, 50-325, 84/03/09, 8403130049
- E403170302 LER 84-003-00 on 840217, speed control of HPCI turbine very erratic Caused by malfunction of electronic speed controller Controller unit replaced & HPCI sys satisfactorily tested & returned to svc W/840314 ltr PASTVA: M J. DIETZ.C R. Carolina Power & Light Co 84/03/14 2pp 22673-263 24X Fiche 50-325,84/03/14,8403170302
- 8403210137 Updated LER 82-119/03L-1 on 821120, during steady state plant operation, APRM F declared inoperatile due to erratic output signal from input LPRM 28-21C, Caused by loase connector Connector corrected. W/840314 ltr
 ALLEN, M T., DIETZ, C.R. Carolina Power & Light Co. 84/03/14
 0/RETLLY, J P., Region 2, Office of Director, 2pp. 22707 274 24X
 Fiche: 50-325,84/03/14,8403210139.
- DOCKET 50-327 SEQUOYAH NUCLEAR PLANT, UNIT 1
- F. Becurity, medical, emergency & fire protection plans
- 8403050235 Rev 5 to Procedure IP-9, "Muscle Shoels Emergency Ctr Implementing Procedures Document" W/840213 ltr MANWELL,R Tennesses Valley Authority. B4/02/13 63pp 22518 023 24X Fiche 50-000:84/02/13,8403060235
- 8403060391 Rev 7 to radiological emergency plan W/840229 ltr MILLS, L M Tennessee Valley Authority 84/02/24, O'REILLY, J P Region 2, Office of Director, Spp 22511 336 24X Fiche 50-327,84/02/24,8403060391

- B403010154 Ack receipt of B40210 & B31103 ltrs re changes to physical security plan Changes consistent w/provisions of .
 10CFR50 54(p) & acceptable
 LEWIG.R C Division of Project & Resident Programs B4/02/27
 PARRIS.H & Tennessee Valley Authority 2pp 22435 310 24X
 Fiche 30-327.84/02/27.8403010154
- 8403060147 Forwards revised effective pages to Knoxville Emergency Ctr. Central Emergency Control Ctr.Div of Nuclear Power Emergency Ctr & Muscle Bhoals Emergency Control Ctr emergency plan implementing procedures W/o Muscle Shoals pages MILLS.L M Tennessee Valley Authority 84/02/28 O'REILLY.J P Region 2. Office of Director 19 22516 165 24X Fiche 50-000.84/02/28.8403060147
- --8403060163 Revised list of effective pages to Knoxville Emergency Ctr emergency plan implementing procedures * Tennessee Valley Authority 84/02/06 8pg 22516 166 24X Fiche 50-000,84/02/28,8403060147
- --8403060189 Revised list of effective pages to Central Emergency Control Ctr emergency plan implementing procedures * Tennessee Valley Authority 84/02/06 8pp 22516 174 24X Fiche 50-000 84/02/28 8403060147
- --8403060206 Revised list of effective pages to Div of Nuclear Power Emergency Ctr emergency plan implementing procedures * Tennessee Valley Authority 84/02/06 4pp 22516 182 24X Fiche 50-000,84/02/28,8403060147
- 8403160345 Extends invitation to attend region 840316 workshop at regional ofe to discuss 10CFR30.App R requirements & recent results of insp to help resolve misunderstandings associated w/requirements

 LENIS.R C Division of Project & Resident Programs 84/03/02

 PARRIB.H G Tennessee Valley Authority 2pp 22660 083 24X

 Fiche 50-000.84/03/02.8403160345
- 8403190370 Rev 8 to radiological emergency plan.updating DOE agreement ltr in App E W/840315 ltr MILL8-1. M Tennessee Valley Authority 84/03/07 O'REILLY, J P Region 2. Office of Director Spp 22674 207 24X Fiche 50-327,84/03/07.8403190370
- 8403130377 Ack receipt of 840119 ltr transmitting Rev 7 to security personnel training & qualification plan Changes consistent w/provisions of 10CFR90 84(p) & acceptable for inclusion in plan LEWIS,R C Division of Project & Resident Programs 84/03/08 PARRIS,H G Tennessee Valley Authority 1p 22616 293 24X Fiche 50-327,84/03/08,8403130377
- 8403160035 Advises that 840116 rev to physical security plan consistent w/provisions of 10CFR50 54(p) & acceptable LEWIS.R C Division of Project & Resident Programs 84/03/13 PARRIS.H G Tennessee Valley Authority 2pp 22655 139 24X Fiche 50-327,88/03/13,8403160035
- 8403160139 Advises that B40101 rev to physical security plan consistent w/provisions of 10CFR50 54(p) & acceptable LEWIS.R C Division of Project & Resident Programs B4/03/13 PARRIS.H G Tennessee Valley Authority 2pp 22655 331 24X Fichs 50-327.84/03/13.8403160139
- 8403260277 Revised Emergency Plan Implementing Procedures BQN-IPD "Implementing Procedures Index" & SQN IP-5 "General Emergency " W/R40320 ltr NOBLES,L M CRAWLEY,D E , MILLS,L M Tennessee Valley Authority B4/03/16 D'REILLY,J P Region 2, Office of Director App 22753,028 24X Fiche 50-327,84/03/16,8403260277
- J Insurance & indemnity information
- 8403060224 Forwards Endorsement 40 to NELIA Policy NF-247 DUCK.JR Marsh & McLennan. Inc 84/02/28 SALTZMAN.J Assistant Director for State & Licensee Relations 2pp 22516 062 24X Fiche 50-327.84/02/28.8403060224
- 8403070175 Forwards Endorsement 34 to MAELU Policy MF-102.correcting policy number on Endorsement 33 from MF-77 to MF-102 DUCK.J R Marsh & McLennan, Inc 84/03/01 SALTZMAN, J Assistant Director for State & Licensee Relations 19 22538 351 24X Fiche 50-327.84/03/01.8403070175

P Operating license stage documents & correspondence

- 8403020313 Forwards add1 comments to Ouidelines 5a.7a & 7b of technical evaluation rept in response to NRC 820430 ltr re control of heavy loads.per generic i.tr 81-07 MILLS.L M Tennesses Valley Authority 84/02/28 ADENSAM.E Licensing Branch 4 (ipp 22439 190 24% Fiche: 50-327.84/02/28, 8403020313
- 8403160247 Informs of 840327 meeting to discuss proposed responses to NRC questions on Rev 7 to topical QA program.per 840302 telcon LEWIB.# C Region 2. Office of Director 84/03/08 PARRIS.H Q Tennessee Valley Authority ip 22660 361 24X Fiche 50-000.84/03/08.8403160247
- 8403290026 Forwards listing of Category IV components not to be replaced or relocated by end of second refueling cycle.per 10CFR30 49(h) & util 831114 ltr Requests extension of completion date to June 1985 for disposition of 164 items HILLS, L.M. Tennessee Valley Authority 84/03/23 ADENSAM, E. Licensing Branch 4 App. 22806 218 24% Fiche 50-327,84/03/23,8403290026
- 8403290038 Forwards revised responses to 831123 & 840109 itra re approval of proposed license amend re post-accident sampling for facilities. THI I tem II B 3 MILLS, L M Tennessee Valley Authority 84/03/23 ADENSAM, E Licensing Branch 4 9pp 22806 237 24% Fiche 50-327, 84/03/23, 8403290038

O Inspection reports. IE Bulletins & correspondence

- 8403160217 Forwards IE Insp Repts 50-327/84-03 & 50-328/84-03 on 840105-0205 No violations or deviations noted VERRELLI,D M Division of Project & Resident Programs 84/02/15 PARRIS,H G Tennessee Valley Authority 2pp 22661 091, 24X Fiche 50-327,84/02/15,8403160217
- --8403160225 IE Insp Repts 30-327/84-03 & 50-328/84-03 on B40106-0205 No violations or deviations noted Major areas inspected operation safety verification.LER review & independent inspectfort.ESF sys operability verification & TMI action plan FORDLE J. BUTLER.S D. Region 2. Office of Director JULIAN.C A Division of Project & Resident Programs 84/02/15 5pp 22661 093 24X Fiche 50-327.84/02/15.8403160217
- 8403060223 IE Insp Repts 50-275/64-01 & 50-323/84-01 on 840103-06 Noncompliance noted failure to perform tafety-related velding activities in area of structural steel welding activities BURDOIN.) F. KIRBCH.D F. Region 5. Office of Director 84/02/17 4pp. 22517 149. 24x Fiche 50-223.84/02/17.8403060207
- 8403070191 Ack receipt of 840208 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/83-27 & 50-328/83-29 O'REILLY, J.P. Region 2. Office of Director 84/02/27 PARRIB, H.Q. Tennessee Valley Authority 1p 22538 298 24X
- --B403070195 Responds to NRC 840110 itr re violations noted in IE Insp Repts 50-327/83-27 & 50-328/83-27 Corrective actions Wark Plan 10260 reworked per critical sys, structures & components requirements HILLS.L.M. Tennessee Valley Authority B4/02/08 ()'REILLY, J.P. Region 2, Office of Director 6pp 22538 277 24X Fiche 50-327, 84/02/27, 8403070151
- --8403070156 Forwards IE Insp Repts 30-327/B3-29 & 50-328/B3-29 on B31104-1205 & notice of violation O'REILLY, J.P. Region 2, Office of Director. B4/01/10 PARRIS.H 9 Tennessee Valley Authority 2pp 22538 305 24X Fiche 50-327,84/02/27,8403070151
- --8403070159 Notice of violation from insp on 631106-1205 * Region 2, Office of Director 64/01/10 3pp 22538 307 24% Fiche 50-327,84/02/27.8403070151
- --8403070163 IE Insp Repts 50-327/83-29 & 50-328/83-29 on 831104-1205 Violations noted failure to follow Sys Operating Instruction 14 3 for high crud tank B release & failure to inspect work per M&AI-12 requirements
 FORD.E J. BUTLER.B D Region 2. Office of Director JULIAN.C A Division of Project & Resident Programs 84/01/09. App 22538 310. 24X Fiche 50-327.84/02/27.8403070151

- B401190072 IE Info Notice B4-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN, C. L. Division of Emergency Preparedness & Engineering Response (Post B30103) 64/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22709 239 24X Fiche 50-000.84/02/28.8401190072
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by BOT & NRC " Byo list encl GRACE,J N Division of GA. Seregulards & Inspection Programs (Pest 830103) 84/03/02 Consolidated Edison Co of New Yerk, Inc 830pp 22532 329 24X Fiche 50-000,84/03/02,8402090007
- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinler Bys Valves to Operate " Svc list enc! JORDAN E L. Division of Emrgency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York Inc 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008
- B402090009 IE Info Notice 84-15, "Reporting of Radiological Releases"

 Byc list enc!

 JORDAN E L. Division of Emergency Preparedness & Engineering

 Response (Post B30103) 04/03/02 \ Consolidated Edison Co of His

 York, Inc. 119pp. 22853 217 24X Fichs 30-000,84/03/02,8402090002.
- O402090011 IE Info Notice 84-17. "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Bvc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc. 117pp 22353 336 24X Fiche 50-000,84/03/05,8402090011
- 8402090824 IE Info Notice 84-09, Rev i. "Lessons Learned From Insps of Fire Protection Bafe Bhutdown 8ys " Svc list encl. URBANKE L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc. 118pp 22635, 049 24X Fiche 50-000, 84/03/07, 8402090026
- 8402070028 IE Info Notice 84-18. "Stress Corrosion Cracking in FMR Bys." Svc list and J JORDAN E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 64/03/07 Consolidated Edison Co. of Rev York, Inc. 1189p 22584 186 24% Fiche 50-000.84/03/07.8402070028
- 0403130088 Forwards Rev 1 to "Inservice Insp Program"
 HILLG.L. M Tennessee Valley Authority 84/03/07 ADENBAN.E
 Licensing Branch 4 ip 22597 001 24X Fichs 50-327.84/03/07.
 0403130088
- --8403130100 Rev 1 to Procedure BI-114 1. "Inservice Insp Program" LEHBERGER.N Tennesse Valley Authority 84701/04, 425pp 22597 002. 24X Fichs: 50-327,84703/07,8403130088
- 8402090031 IE Bulletin 84-02, "Failures of QE Type HFA Relays in Use In Class IC Safety Bys." Bvc list encl
 DEYOUNG, R C Director's Office of Inspection and
 Enforcement 84/03/12 Consolidated Edison Co. of New York Int
 134pp. 22823 094 24X Fiche.50-000.84/03/12,8402090031
- B402090043 IE Info Notice 84-19. "Two Events Involving Unauthorised Entries into PWR Reactor Cavities" Bvc list encl JURDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edisor Co of New York, Inc 193pp 22823 229 24X Fiche: 50-000: 84/03/21. 8402090943
- 8402070044 IE Info Notice 84~20. "Bvc Life of Relays in Bafaty-Related Bys." Svc list enci JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21. Consolidated Edison Co of Nee York, Inc 135pp 22933-001 24X Fichs. 50~000, 84/03/21, 8402070945
- R Periodic operating reports & related correspondence
- B403020002 Monthly operating repts for Jan 1984. H/B40215 ltr HABON:C C Tempesse Valley Authority 84/01/31 30pp 22442 117 24X Fiche 50-027. 84/01/31. 8403020002
- 8403070275 "NPDE8 Discharge Monitoring Rept. Nov 1983 Jan 1984 * * Tennessee Valley Authority 84/01/31, 79pp 22545:092 24x Fiche 50-327,84/01/31,8403070295
- 8403300154 Montyly operating repts for Feb 1984, W/840315 1tr EDDINOS, M O , MASQN, C C Tennessee Valley Authority 84/02/29 51pp 22821 016 24x Fiche 50-327, 84/02/29, 8403300154.

- S Reportable occurrences, LERs & related correspondence
- 8403080011 Forwards response to Commissioner Gilinsky request for info on frequency of personnel errors at selected operating plants Summary of tabulated events re operator errors, personnel errors or procedural errors provided for CVB3 DIRCKS, WJ Office of the Executive Director for Operations 84/02/24 PALLADING, GILINSKY, ROBERTS Commissioners 17pp 22584 142 24X Fiche 50-000,84/02/24,8403080011
- 8403020147 LER 84-010-00 on 840128, high radiation alarm actuated, causing auxiliary bldg isolation to occur Caused by electromagnetic interference High radiation alarm reset & monitor returned to syc M/840227 ltr DUGOIN, 0 . MABON, C C Tennesser Valley Authority 84/02/27 3pp 22441 357 24% Fiche 50-327,84/02/27,8403020147
- 8403050080 LER 84-009-00 on 840128, high radiation alarm actuated, causing containment ventilation isolation to occur Caused by root valve on pressurizer leaking through packing Valve backseated W/840227 ltr DU001N,0. MASON,C C Tennessee Valley Authority 84/02/27 3pp 22490 016 24X Fiche 50-327,84/02/27,8403050080
- 8403140203 Forwards "Operating History Overview for Diasel Generators in Nuclear Svc," comparing Transamerica Delaval, Inc generators w/generators mfg by other vendors HEBDON,F J Program Technology Branch 84/02/27 BERLINGER,C H NRC - No Detailed Affiliation Given ip 22638,317 24X Fiche 50-000,84/02/27,8403140203
- --8403140205 "Operating History Overview for Diesel Generators in Nuclear Byc " * Director's Office 84/02/29 65pp, 22638 320 24X Fiche 50-000,84/02/27,8403140203
- 8403020244 LER 84-013-00 on 840130, turbine trip followed by reactor trip occurred Caused by high-high level in steam generator 4. Unit stabilized at 547 F W/840228 ltr KIRK.0 8 E . MASON.C C Tennessee Valley Authority 84/02/28 3pp 22440.097 24X Fiche 50-327,84/02/28,8403020244
- 8403150181 Forwards "Failures in Upper Head Injection Sys " Licensees taking action to resolve setpoint drift on Barton level transmitters No AEOD action recommended 2UKOR.D J Reactor Operations Analysis Branch 84/02/28 SEYFRIT.K V Reactor Operations Analysis Branch ip 22646 272 24X Fiche 50-000.84/02/28 8403150181
- --8403150183 "Failures in Upper Head Injection Sys." AEOD engineering evaluation rept ZUKOR, A Director's Office 84/02/28 8pp 22646 273 24X Fiche, 50-000, 84/02/28, 8403150181
- 8403060276 LER B4-012-00 on B40201, high radiation alarm actuated, causing containment ventilation isolation to occur. Caused by voltage spike as result of electromagnetic interference Alarm reset & monitor returned to svc W/840301 ltr DU001N.0. MABON.C C Tennessee Valley Authority B4/03/01 4pp 22519:066 24% Fiche 50-327,84/03/01.8403060276
- 8403150079 LER 84-014-00, on 840214, high radiation alarm actuated, causing containment ventilation isolation to occur Caused by voltage spike resulting in electromagnetic interference.

 Alarm reset & monitor returned to svc W/840309 ltr.

 DUGOIN, G , MASON, C C Tennessee Valley Authority 84/03/09 4pp 22643:203. 24% Fiche 90-327,84/03/09,8403150079
- 8403190121 LER 84-016-00. on 840225, high radiation elem actuated, causing auxiliary bldg isolation to occur Caused by contaminated vacuum cleaner removad from fuel transfer canal to radwaste area W/840316 ltr
 DUGGIN, 0, MASON.C C Tennesse Valley Authority. 84/03/16 3pp
 22668:245 24X Fiche 50-327,84/03/16,8403190121
- 8403190365 LER 84-015-00, on 840220, high radiation alarm actuated, causing auxiliary bldg isolation Caused by voltage spike due to electromagnetic interference breaker actuation Independent high radiation alarm reset W/B40316 ltr BU001N, 0, MASON: C C Tennessee Valley Authority 84/03/16 3pp 22675, 231 24X Fiche: 50-327, 84/03/16, 8403190365.
- 8403270219 Part 21 rept re broken contact carrier in control device of 7 5 kV-15 kV.500-750 MVA:5 kV 350-3,000 & all HKV circuit breakers. Initially reported on 830223 Addenda to installation & maint procedures sent to affected units DUVALLO D Brown Boveri Corp. (subs of Brown Boveri & Co., Ltd.) 84/03/19 Record Services Branch (Document Control Desk.) 5pp 22772: 114. 24x Fiche 50-000.84/03/19,8403270219

- B403260164 LER B4-018-00 on B40221 fire protection deludge valve found isolated w/o continuous fire watch in place Caused by spurious signal Shift groups reinstructed to establish fire watches W/840320 ltr KIRK. G B , MASON. C C Tennesses Valley Authority B4/03/20 3pp 22750 353 24% Firthe 50-327.84/03/20.8403260164
- 8403300073 LER 84-017-00 on 840227.high radiation alarm actuated.

 causing containment ventilation isolation to occur Caused by
 small quantity of airborne radiation escaping Radiation
 monitor reset W/840327 ltr
 DU061N.G . M460N.C C Tennessee Valley Authority 84/03/27 3pp
 22822 089 24x Fiche 50-327.84/03/27.8403300073
- B305230539 Forwards technical review rept, "Flow Blockage in Essential Raw Cooling Water Sys Due to Asiatic Clam Intrusion "
 IMBRO.E Reactor Operations Analysis Branch B3/03/28
 BEYFRIT.K V Reactor Operations Analysis Branch 1p 22789 281
 24X Fiche 30-327.84/03/28,8305230539
- 8305230546 "Flow Blockage in Essential Raw Cooling Water Bys due to Asiatic Clam Intrusion," technical review rept Bignificant infestations of aquatic organisms can remain undetected in svc water sys & cause flow blockages at inopportune times. * Reactor Operations Analysis Branch 83/03/28 3pp 22787 282 24X Fiche 50-327,84/03/28,8405230539
- DOCKET 50-328 SEQUOYAH NUCLEAR PLANT, UNIT 2

 F Security, medical, emergency & fire protection plans
- 8403060235 Rev 5 to Procedure 1P-9, "Muscle Shoals Emergency Ctr Implementing Procedures Document" W/840213 1tr MAXMELL.R Tennessee Valley Authority 84/02/13 63pp 22518 023 24X Fiche 50-000,84/02/13,8403060235
- 8403060391 Rev 7 to radiological emergency plan W/B40229 ltr MILLS.L M Tennessee Valley Authority B4/02/24 O'REILLY.J P Region 2. Office of Director 5pp 22511 336 24x Fiche 50-327.04/02/24.8403060391
- 8403010154 Ack receipt of 840210 & 831103 ltrs re changes to physical security plan Changes consistent w/provisions of 10CFR30 54(p) & acceptable LEWIS,R C Division of Project & Resident Programs 84/02/27 PARRIS,H G Tennesse Valley Authority 2pp 22435 310 24X Fiche 50-327,84/02/27,8403010154
- 8403060147 Forwards revised effective pages to Knoxville Emergency Ctr. Central Emergency Control Ctr.Div of Nuclear Power Emergency Ctr. Muscle Shoals Emergency Control Ctr emergency plan implementing procedures W/o Muscle Shoals pages MILLG.L M Tennessee Walley Authority 84/02/28 O'REILLY, J P Region 2. Office of Director 1p 22516 165 24X Fichs 50-000.84/02/28.8403060147
- --8403060163 Revised list of effective pages to Knoxville Emergency Ctr emergency plan implementing procedures * Tennesses Valley Authority 84/02/06 8pp 22516 166 24X Fichs 50-000.84/02/28.8403060147
- --8403060189 Revised list of effective pages to Central Emergency Control Ctr emergency plan implementing procedures * Tennessee Valley Authority 84/02/06 8pp 22516 174 24X Fiche 50-000.84/02/28.8403060147
- --8403060206 Revised list of effective pages to Div of Nuclear Power Emergency Ctr emergency plan implementing procedures * Tennessee Valley Authority 84/02/06 4pp 22516 182 24X Fiche 50-000,84/02/28,8403060147
- 8403160345 Extends invitation to attend region 840316 workshop at regional ofc to discuss 100FR50. App R requirements & recent results of insp to help resolve misunderstandings associated w/requirements
 LEMIB.R C Division of Project & Resident Programs 84/03/02
 PARRIS.H G Tennessee Valley Authority 2pp 22660 083 24X
 Fiche 50~000.84/03/02.8403160345
- 8403190370 Rev 8 to radiological emergency plan.updating DDE agreement ltr in App E W/840315 ltr MILLS.L.M Tennessee Valley Authority 84/03/07 O'REILLY, J P Region 2. Office of Director. App 22674 207 24X Fiche 50-327.84/03/07.8403190370

- 8403130377 Ack receipt of 840119 ltr transmitting Rev 7 to security personnel training & qualification plan Changes consistent w/provisions of 10CFR50 54(p) & acceptable for inclusion in plan
- plan LEMBB.R C Division of Project & Resident Programs 84/03/08 PARRIB.H G Tennessee Valley Authority 19 22616 293 24X Fiche 50-327.84/03/08.8403130377
- 8403160035 Advises that 840116 rev to physical security plan consistent u/provisions of 10CFR50 54(p) & acceptable LEWIS.R C Division of Project & Resident Programs 84/03/13 PARRIS.H G Tennessee Valley Authority 2pp 22655 139 243 Fiche 50-327.84/03/13.8403160035
- 8403140139 Advises that 840101 rev to physical security plan consistent w/provisions of 100FR50 54(p) & acceptable LEWIS.R C Division of Project & Resident Programs 84/03/13 PARRIS.H O Tennessee Valley Authority 2pp 22655 331 24X Fiche 50-327,84/03/13.8403160839
- B403260277 Revised Emergency Plan Implementing Procedures SQN-IPD "Implementing Procedures Index" & SGN IF-5 "General Emergency " W/840320 ltr NOBLES, L M . CRAMLEY, D E . MILLS, L M Tennessee Valley Authority B4/03/16 U REILLY, J P Region 2, Office of Director App 22753 02B 248 Fiche 50-327.84/03/16.8403260877
- J Insurance & indemnity information
- 8403060224 Forwards Endorsement 40 to NELIA Policy NF-247 BUCK-J R Marsh & Holennam, Inc. 84/02/28 SALTIMAN J Assistant Birector for State & Licensee Relations 2pp 22516-062 24X Fiche 50-327.84/02/28.8403050224
- 8403070175 Forwards Endorsement 34 to MAELU Policy MF-102, correcting policy number on Endorsement 33 from MF-77 to MF-102 BUCK-J R Harsh & McLennan, Int 84/03/01 SALTZMAN, J Assistant Director for State & Licensee Relations 1p 22538 351 24X Fiche 50-327.84/03/01.8403070175
- P Operating license stage documents & correspondence
- 8403020313 Forwards addl comments to Guidelines 5a.7a & 7b of technical evaluation rept in response to NRC 820630 ltr re control of heavy loads.per Generic Ltr 81-07 HILLS.L M Tennessee Valley Authority 84/02/28 ADENSAM.E Licensing Branch 4 lipp 22437 190 24X Fiche 30-327.84/02/28, 840-320313
- 8403140247 Informs of 840327 meeting to discuss proposed responses to NRC questions on Rey 7 to topical QA program.per 840302 teleon LEMIS.R C Region 2. Office of Director 84/03/08 PARRIS.H G Tannessee Valley Authority ip 22660-361 24x Fiche 50-000.84/03/08.8403160247
- 8403290038 Forwards revised responses to 831123 & 840109 ltrs re approval of proposed license amend re post-accident sampling for facilities.TM1 Item II B 3 MILLS.L M Tennessee Valley Authority 84/03/23 ADENBAM.E Licensing Branch 4 9pp 22808 237 24X Fiche 50-327,84/03/23, appropriate
- O Inspection reports. IE Bulletins & correspondence
- 8403160217 Forwards IE Insp Repts 50-327/84-03 & 50-328/84-03 on 840106-0205 No violations or deviations noted VERRELLI.D M Division of Project & Resident Programs 84/02/15 PARRISH G Tennessee Valley Authority 2pp 22661 091 24X Fiche 50-327.84/02/15.8403160217
- --- ### --- ##
- 8403070151 Ack receipt of 840208 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/83-29 & 50-326/83-29 O'REILLY, JF Region 2, Office of Director 84/02/27 PARRIS, H G Tennessee Valley Authority ip 22538 298 24X Fiche 50-327,84/02/27,8403070151

- --8403070195 Responds to NRC 840110 ltr re violations noted in IE lass Repts 50-327/83-29 & 50-328/83-29 Corrective actions Hork Plan 10260 reworked per critical sys, structures & components requirements HILLS, L.M. Tennessee Valley Authority 84/02/08 0'REILLY, J.P. Region 2. Office of Director App 22538 299 24X Fiche 50-327, 84/02/27,8403070151
- --B403070156 Forwards IE Insp Repts 50-327/83-29 & 50-328/83-29 on B31104-1205 & notice of violation O'REILLY, J P Region 2, Office of Director B4/01/10 PARRIS, H G Tennessee Valley Authority, 2pp 22538 305 24X Fiche 50-327,84/02/27,8403070151
- --8403070139 Notice of violation from insp on B31106-1205 * Region 2, Office of Director 84/01/10 3pp. 22538.307 24X Fichs 50-327.84/02/27.8403070151
- -- #403070163 IE Insp Repts 50-327/83-29 & 50-328/83-29 on 831104-1205 Violations noted failure to follow Sys Operating Instruction 14 3 for high crud tank B release & failure to inspect work per M&AI-12 requirements FDRD, E J. BUTLER, S D Region 2, Office of Director JULIAN, C A Division of Project & Resident Programs 84/01/09 App 22538 310 24% Fiche 50-327,84/02/27,8403070151
- B401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation," Bvc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22909 239 24% Fiche 50-000, 84/02/28, 8401190072
- 8402070007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC," Svc list encl, GRACE, J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc, 130pp 22552 329 24X Fiche 80-000,84/03/02,8402090007
- 840209000B IE Info Notice 84-16. "Failure of Automatic Sprinkler Bys Valves to Operate " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New Yerk, Inc 122pp 22553 098 24X Fiche 50-000.84/03/02.8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases"
 Svc list encl
 JCRDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co. of New
 York, Inc. 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- B402070011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Bvc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 80103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05.8402070011
- 8402090024 IE Info Notice 84-09. Rev 1, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list and URROAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000.84/03/07.8402090024
- 8402070028 IC Info Notice 84-18, "Stress Corrosion Cracking in PWR Sys " Syc list enc!

 JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24% Ficha 50-000,84/03/07,8402070028
- B402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 074 24% Fiche: 50-000,84/03/12,8402090031.
- 8402070043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000,84/03/21,8402090043
- 8402070044 IE Info Notice 84~20, "Svc Life of Relays in Safety-Related Sys " Svc list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc 135pp 22733 001 24% Fiche 50-000,84/03/21,8402070044

- R Periodic operating reports & related correspondence
- 8403020002 Monthly operating repts for Jan 1984 W/840215 ltr MABON.C C Tennessee Valley Authority 84/01/31 30pp 22442 157 24X Fichs 50-327.84/01/31.8403020002
- 8403070295 "NPDES Discharge Monitoring Rept.Nov 1983 Jan 1984 " * Tennessee Valley Authority 84/01/31 79pp 22546 092 24) Fiche 50-327,84/01/31,8403070295
- 8403300154 Montyly operating repts for Feb 1984 W/840315 ltr EDDINOS, M 0 , MASON, C C Tennessee Valley Authority 84/02/29 51pp 22821 016 24X Fiche 50-327.84/02/29,8403300154
- 8 Reportable occurrences, LERs & related correspondence
- B403080011 Forwards response to Commissioner Gilinsky request for info on frequency of personnel errors at selected operating plants Summary of tabulated events re operator errors, personnel errors or procedural errors provided for CYB3 DIRCKE, W J Office of the Executive Director for Operations B4/02/24 PALLADIND Commissioners 17pp 225B4 142 24X Fichs. 50-000, 84/02/24, 8403080011
- 8403150181 Forwards "Failures in Upper Head Injection Sys " Licensees taking action to resolve setpoint drift on Barton level transmitters No AEOD action recommended ZUKOR.D J Reactor Operations Analysis Branch 84/02/28 SEYFRIT.K V Reactor Operations Analysis Branch ip 22646 272 24X Fiche 50-000.84/02/28.8403150181
- --8403150183 "Failures in Upper Head Injection Sys." AEOD engineering evaluation rept ZUKOR:A Director's Office 84/02/28 8pp 22646 273 24X Fiche 50-000,84/02/28,8403150181
- 84032702i9 Part 21 rept re broken contact cerrier in control device of 7 ± kV-15 kV. 500-790 MVA, 5 kV 350-3.000 & all HKV circuit breakers Initially reported on 830223 Addenda to installation & maint procedures sent to affected units DUVALL.D D Brown Boveri Corp (subs of Brown Boveri & Co , Ltd) 84/03/19 Record Services Branch (Document Control Desk) 5pp 22772 114 24X Fiche 50-000.84/03/19.8403270219
- 8403300204 LER 84-003-00 on 840227.vital inverter failed Caused by blown fuse due to incorrect connection which caused containment ventilation isolation Containment ventilation isolation reset & inventer returned to svc W/840327 ltr DUGOIN.O , MASON.C C Tennessee Valley Authority 84/03/27. 3pp 22819 324 24% Fiche 50-328.84/03/27.8403300204

DOCKET 50-329 MIDLAND PLANT, UNIT 1

- A Application/construction stage documents & correspondence
- B403010192 FOIA request for records relevant to or generated in connection w/B31021 "Rept on Review of Diesel Generator Bidg at Midland"

 GRDE-B P Government Accountability Project B3/11/26 Office of Administration 2pp 22445 092 24X Fichs 50-329,83/11/26, B403010192
- 8403010178 Responds to FOIA request for records relevant to or generated in connection w/831021 "Rept on Review of Diesel Generator Bldg at Midland "Forwards App B documents App A documents available in FDR FELTON, J M Division of Rules and Records 83/12/14 GARDE, B P Government Accountability Project 4pp 22445 092 24X Fiche: 50-329, 83/12/14, 8403010198
- --B31031047i Forwards task group rept, "Rept on Review of Diesel Generator Bldg at Midland," Oct 1983 Large addl settlements not anticipated More accurate program to monitor cracks needed.

 KNO,P. Structural & Geotechnical Engineering Branch B3/10/21 KN19HT,J P Assistant Director for Comp & Structures Engineering (Post B30201) 2pp 22445 152 24X Fiche 30-329,83/12/14, 8403010198
- --8310310475 "Rept on Review of Diesel Generator Bldg at Midland " TAN.C P Structural & Gentechnical Engineering Branch 83/10/31 96pp 22445 154. 24X Fiche: 50-329, 83/12/14, 8403010198
- --B312010004 Forwards corrected Pages 9,17,20 & 4 to App 11 to rept on review of dissel generator bldg. KUGP Structurel & Gentechnical Engineering Branch 83/11/14 KNIOHT.JP Assistant Director for Comp & Structures Engineering (Post 830201), 5pp 22445 256. 24X Fiche 50-329,83/12/14, 8403010198

- --8312050628 Requests rept re adequacy of diesel generator bldg on expedited basis as imput to Congress re Landsman concerns EISENHUT.D G Division of Licensing 83/11/18 VOLLMER,R Division of Engineering 1p 22445 263 24X Fiche 50-329,83/12/14,8403010198
- --8312070022 Forwards Structural & Geotechnical Engineering Branch assessment of "Rept of Review of Diesel Generator Bldg at Midland," dtd 831021 per E Adensam & W Paton requests Meeting & possible reopening of hearing recommended LEAR, G Structural & Geotechnical Engineering Branch 83/11/22 VOLLMER, R H Division of Engineering 2pp 22445 268 24% Fiche 30-329,83/12/14,8403010198
- --8312070298 Discusses recommendation for suppl to Board Notifications 83-165 & 83-133 re diesel generator bldg Comments & recommendations of J Kane & F Rinaldi on task group rept & reopening of hearing provided HQDD,D & Licensing Branch 4 83/11/22 EISENHUT,D 9 Division of Licensing 4pp 22445 264 24X Fiche 50-329.83/12/14.
- --B3120B0134 Recommends PT Kuo B31114 mamo containing four corrected pages to rept re structural adequacy of diesel generator bldg be forwarded to Doard as supplemental notification to BN B3-165
 HOOD, D Licensing Branch 4 B3/11/17 EISENHUY, D Assistant Director for Licensing 1p 22445 261 24% Fiche 50-329, 83/12/14,8403010198
- --8403010204 Advises that info re plan to address Landsman concerns should be issued as Board Notification 83-109
 EIBENHUT.D G Division of Licensing 83/07/27 NOVAK,T Assistant Director for Licensing 1p 22445 098 24X
 Fiche 50-329,83/12/14,8403010198
- --B403010211 Advises that attached correspondence re new schedule for review of Landsman concerns should be issued as Board Notification 83-142 M/o encl ELBENHUT.D Q Division of Licensing 83/09/20 NDVAK.T Assistant Director for Licensing Ip 22445 099 24X Fiche 50-329,83/12/14,8403010198
- --8403010217 Draft rept, "Review of Diesel Generator Bidg at Midland Plant" MILLER,C A , COSTANTINO:C J Brookhaven National Laboratory 83/09/23 25pp 22445 100 24% Fiche 50-329, 83/12/14, 8403010198
- ---8403010223 Advises that encl JP Knight 830923 memo to RH Vollmer should be issued as Board Notification 83~153 W/o encl EIBENHUT, D @ Division of Licensing 83/10/05 NDVAK, Y Assistant Director for Licensing 1p 22445 125 24X Ficha 50-329, 83/12/14, 8403010198
- --8403010227 Forwards "Review of Diesel Generator Bldg at Midland Plant " REICH, M Brockhaven National Laboratory 83/10/17 KUO.P T Structural & Geotschnical Engineering Branch 1p 22445 126 24X Fiche 50-329.83/12/14,8403010198
- --8403010231 "Review of Diesel Generator Bldg at Midland Plant " MILLER: C A , COSTANTINO, C J Brookhaven National Laboratory 83/10/17 25pp 22445 127 24X Fiche 50-329,83/12/14,8403010198
- --8403010245 Requests that enci rept on review of diesel generator bldg & util analysis requested during review be issued as Board Notification 83-165 EISENHUT.D Q Division of Licensing 83/10/26 NOVAK.T Assistant Director for Licensing 69/22445 250 24X Ficha 50-329.83/12/14.8403010198
- --B403010273 Advises that supplemental info provided in PT Kuo 831114 memo to JP Knight will be transmitted to Midland Board as suppl to Board Notification 83-165 issue will be incorporated as Board Notification 83-165 w/a encl EIBENKUT, D 0 Division of Licensing 83/11/16 NDVAK, T Assistant Director for Licensing 1p 22445 262 24X Fiche 50-329,83/12/14,8403010198
- --8403010282 Forwards guidance for use in deciding whether to recommend that hearing be reopened Hearing should be reopened based on listed reasons VOLLMER.R H Division of Engineering 83/11/25 EISENHUT.D G Division of Licensing 3pp 22445 270 24X Fiche 50-329.83/12/14.8403010198
- --8403010285 Advises that Vollmer recommended reopening Midland hearing on diesel generator bldg structural adequacy issue, based on task group rept Vollmer memo encl M/o encl ADENSAMLE NRC No Detailed Affiliation Given 63/11/25 EISENHUT, D NRC No Detailed Affiliation Given 10 22445 273 24X Fiche 50-329, 83/12/14.8403010198

- 8403010488 Appeals denial of FOIA request for T Novak notes generated by or during visit to Gien Ellyn. IL to discuss Ofc of Special Cases findings re facilities from Bept 1982 to Dec
- GARDE, B P Government Accountability Project 84/01/17
 FELTON, J M Division of Rules and Records 19 22443 274 24X
 Fiche 50-329, 84/01/17, 8403010488
- 8403060486 Further response to FOIA request for documents re evaluation or seview of design constischeduling cost & licensing of facilities from 1977 to present Rept unavailable for Categories 1 & 2 Panel records on evaluations placed in PDR FELTON. J H Division of Rules and Records 84/01/24 ZACK. A M Barris. Sott. Denn & Driker 2pp 22552 232 24X Fiche 50-329,84/01/24,8403060486
- 84030A0370 Notifies of independent design & const verification program 840313 meeting w/NRC & util in Bethesda, MD to discuss details of completion of IDVP LEVIN. H A TERA Corp. 84/02/24 EISENHUT, D @ Division of Licensing KEPPLER, J @ Region 3, Office of Director COOK, J. H Consumers Power Co. 3pp. 22511 312 24X Fiche 50-329, 84/02/24, 8403060370
- 8403010276 Authorizes util to proceed w/remedial soils work activities scheduled for Mar 1984, per 840214 request for Work Authorization Procedure 102950125 HARRISON, J J Region J. Office of Director 84/02/28 QUAMME. D L Consumers Power Co 2pp 22432 104 24% Fiche 50-329, 84/02/28, 8403010296
- 8403010497 Responds to appeal re denial of FOIA request for records in possession of T Novak on visit to Glen Ellyn, IL to discuss fundings of Dfc of Special Cases re facilities NRC has no records sub, to request DIRCKS, W J Office of the Executive Director for Operations 84/02/28 04/08/EB 05 Government Accountability Project ip 22443 273 24X Fichs 50-329,84/02/28,8403010497
- B403080230 Lists unresolved items & audit finding repts, including MSA-B3-10-03U & MSA-B3-25-07F, respectively + Consumers Fower Co B4/02/28 Stone & Webster, Inc ip 23560 126 24% Fiche 50-329,84/02/28.8403080230
- 8403080241 Forwards 84022/ list of Bechtel personnel trained to accomplish status assessment a Consumers Power Co. 84/02/28 Stone & Webster, Inc. 3pp. 22561-013 24% Fiche 30-329,84/02/28.8403080241
- 8403080248 Forwards proposed list of remedial soits work for Nar 1984 & supplemental work activity list for Apr 1984 Review.comments & authorization requested OVAMME.D L Consumers Power Co 84/02/28 HARRISON, J J Region 3. Office of Director 13pp 22556 276 24% Fiche 50-329.84/02/28, 8403080248
- B403080260 Forwards summary of sixth meeting on confirmed items & findings on 84020t at Bechtel Ann Arbor.MI ofc relitems identified in independent design & const verification program monthly status rept dtd B40133 LEVIN.H A TERA Corp 84/02/28 KEPPLER, J G Region 3, Office of Director COOK, J W Consumers Power Co EISENHUT, D 9 Division of Licensing 14pp 22557 078 24X Fiche 50-329.84/02/28.8403080260
- 8403;3026; Notifies that GR Fotiades placed on controlled distribution of training plan manual.per 840224 request
 QUAMME.D L Consumers Power Co 84/02/28 BARANOW, S Stone & Webster, Inc ip 22617 134 24% Fitche 50-329;84/02/28.8403;3026)
- 8403220179 Forwards 840307 memo providing documentation to 5kM for const implementation overview * Consumers Power Co. 84/02/28 Stone & Webster, Inc. 4pp 22717 024 24X Fiche 50-329,84/02/28,8403220179
- 8403080262 Forwards weekly NSSS subcontract status rept for wix ending 840217 W/o enci 4 Consumers Power Co 84/02/29 Stone & Webster, Inc 1p 22557 112 24X Fiche 30-329.84/02/29.8403080262
- 8403130189 Provides list of documents sent to SSW on 840229 * Consumers Power Co 84/03/01 Stone & Webster, Inc 1p 22617 323 24X Fiche 50-329.84/03/01.8403130189
- 8403140021 Forwards Vol X to "Seismic Margin Review, Miscellaneous Subsystems & Components" COCK, J W Consumers Power Co 84/03/01 DENTON, H R Division of Licensing 3pp 22622 167 24X Fiche 50-327, 84/03/01, 8403140021

- --B403140026 "Seismic Margin Review, Miscellaneous Subsystems & Components "
 HESLEY, D.A., NARVER, R.B. Structural Mechanics Associates BMA 13701 05R003 VIO 84/02/29 200pp 22632 171 24X Fiche 50-329,84/03/018403140021
- B403130470 Discusses sampling insps of const training records for personnel noted in Correspondence CSC-7382 Personnel listed cleared to perform status assessment encl W/o encl KARR, J E Stone & Webster, Inc. B4/03/02 GUAME, D L Consumers Power Co 1p 22613 207 24X Fiche 50-327, B4/03/02, B403130470
- 8403150003 Forwards svc water pump structure crack survey rept NRC concurrence of mods to crack mapping program requested Saven oversize drawings encl Aperture cards are available in PDR MDDNEY, J. A. Consumers Power Co. 84/03/05 HARRISON, J. J. Region 3 Office of Director. 30pp. 22824 116 24X Fiche 50-329,84/03/05. 8403150003
- 8403130388 Forwards signed affidavit & resume for RE Horine assigned to const implementation staff at plant KARR.JE Stone & Hebster, Inc. 84/03/06. HARRISON.JJ Region 3, Office of Director 9pp 22605 001 24% Fiche 50-327,84/03/06. 8403130388
- 8403130482 Advises that listed remedial soils work activities presently scheduled for Apr 1984 identified as critical work activities Appropriate details of listed activities requested to assist NRC in review HARRISON, J. Region 3. Office of Director 84/03/04 QUAMME, D. L. Consumers Power Co. 4pp 22613 193 24X Fiche 50-329,84/03/06, 8403130482
- B403190098 Advises that PBACK eliminated from weekly distribution of summary of inspector training & personnel form printouts GUAMMED L Consumers Power Co 84/03/06 BARANCH.8 Stone & Webster Inc 2pp 22669 302 24X Fiche. 50-329, 84/03/06. 8403190098
- 8403230114 Provides add1 info on scope of work required to support turbine roll test milestone as part of const completion pragram implementation QUAMME.D.L. Consumers Power Co. 84/03/06 HARRISON, J. J. Region 3. Office of Director 9pp 22730 337 24X Fiche 50-327,84/03/06,8403230114
- 8403140032 Forwards "Plan to Conduct Independent Mgt Appraisal of Midland Nuclear Project." by Cresap. McCormick & Paget Appraisal will examine util approach for completing plant Certificate of Svc encl Related correspondence COOK. J W Consumers Power Co 84/03/07 KEPPLER. J O Region 3. Office of Director 4pp 22633 129 24X Fiche 50-329.84/03/07. 8403140032
- --840314003B "Flan to Conduct Independent Mgt Appraisal of Midland Nuclear Project " " Cresap, McCormick & Paget 84/03/07 73pp 22633:133 24X Fiche 50-329,84/03/07,8403140032
- 8403130153 Authorizes util to proceed w/Phase I const completion activities for listed plant modules.per 840215 & 0306 requests Partial sys approved for Phase I activities located in module areas also listed HARRISON.J J Region 3. Office of Director 84/03/08 QUAMME.D L Consumers Power Co 3pp R2601 R62 24X Fiche 50-329,84/03/08.8403130153
- --B403130168 Submits add1 info on scope of work required to support turbine roll test milestone, per 840215 ltr. Further definition of scope for seven G-listed sys & description of const completion program process provided QUAMME. D L. Consumers Power Co. 84/03/06 HARRISON, J. Region 3. Office of Director 9pp 22401 267 24X Ficher 50-329, 84/03/08,8403130153
- 8403200027 Requests authorization to proceed per work authorization procedures to excavate Lag Zones Y3 & Z3, install brace struts E10,E11,M10 & M11, install temporary support bracket at E1 & W1 & remove unacceptable backet11 & casing. MODNEY, J A Consumers Power Co 84/03/08 HARRIBON, J, J, Region 3 Office of Director. 1p 22679, 233 24X Fichs 50-329, 84/03/08, 84.0320027
- B403190180 Ack receipt of B40207 ltr indicating desire to discuss likely operation date Cost, generating capacity & extent to which costs attributable to reasons beyond control of licensee discussed KEPPLER, J G Region 3, Office of Director 84/03/09, BARAK, A J Michigan, State of. 2pp 22671 144 24X Fichs. 50-329, 84/03/09, 8403190180

- -8403170186 Discusses 831028 ltr recommending deferring further Caseload Forecast Panel meetings Earliest completion date for Unit 2 not expected until months after Second Guarter 1986 & Unit 1 expected 6-9 months thereafter NGWAK.T M Assistant Director for Licensing 83/12/20 CODK.J W Consumers Power Co 4pp 22671 146 24% Fiche 50-327,84/03/09,8403190180
- ---8403190192 Notifies that util seeking ratemaking treatment for plant Engineering consultants hired to prepare testimony re operation date.cost & generating capacity BARAK.A J Michigan, State of 84/02/07 KEPPLER.J G Region 3, Office of Director 2pp 22671 150 24X Fiche 50-329,84/03/09,8403190180
- 8403200039 Requests authorization to proceed w/excavation & repair of frozen giping & excavation & installation load of radesigned E-17 radesigned E-17 MDCNEY, J.A. Consumers Power Co. 84/03/09 HARRISON, J.J. Regi Office of Director, ip. 22698-315 24X Fiche 50-029,84/03/09, Region 3. P403200039
- 8403220025 Forwards 840305 memo re Unresolved Questions 47 & 48 from Memo DEB 330-83 for PQCI C-1 60.Rev 7
 8EAUDDIN DE Consumers Power Co 84/03/12 FOTIADES GR Stone & Wabster Inc 2pp 22717 180 24X Fiche 50-327.84/03/12.
- B402070041 Board Notification 84-050 provides Commission policy statement & proposed rulemaking on environ qualifications EISENHUT, D Q Division of Licensing 84/03/14 Atomic Safety and Licensing Board Panel 10pp 24X Fiche 50-000, 84/03/14, 8402090041
- 8403200084 Authorizes listed critical remedial soils work activities for Mar 1984 HARRISON.J J. Region 3, Office of Director 84/03/14 QUAMME,D Consumers Power Co. 2pp 22685 274 24% Fiche 50-329,84/03/14, 8403200084 QUAMME, D L
- B403220202 Forwards complete responses to tracked info Items 058,059 & tracked recommendation Item 060 re site auditing # Consumers Power Co. 84/03/14 Stone & Webster, Inc 11pp 22718:090 24X Fichs 50-329,84/03/14,8403220202
- 8403220082 Authorizes listed remedial soils work activity for Mar 1984 HARRIBON-J Region 3, Office of Director 84/03/15 GUAMME, D L Cansumers Power Co 2pp. 22716 265 24X Fiche 50-329,84/03/15, 8403220082
- 8403220113 Forwards summary of independent design & const verification program 840313 meeting w/util & Govt Accountability Project in Bethesda MD LEVIN.H A. TERA Corp 84/03/15 KEPPLER, J G Region 3, Office of Director CODK.J.H. Consumers Fower Co EISENHUT.D G. Division of Licensing 37pp 22716 226 24X Fiche 50-327,84/03/15,8403220113
- 8403270009 Forwards listing of GA mgt audits for tracked info Item
- 032 * Consumers Power Co 84/03/15 Stone & Heb 22769:353, 24% Fiche 50-329,84/03/15,8403270009 Stone & Webster, Inc. 2pp
- 8493270014 Forwards summary of quality verification program mgt review
- B30601 mesting
 PALMER.B. Consumers Power Co. 84/03/19 Stone & Webster, Inc
 14pp. 22770'029 24X Fichs 50-029:84/03/19.8403270014
- 840322010Q Notifies of eighth independent design & const verification program 840328 meeting w/uti, Isham.Lincoln & Beate.Govt Accountability Project & Midland Daily News to discuss status of confirmed items & findings
 LEVIN.H A TERA Corp 84/03/20 KEPPLER, J W Region 9, Diffice of Director FIBEMHUT, D Q Division of Licensing COOK, J W Consumers Power Co. Spp 22715-179 24X Fiche 50-329,84/03/20, e4/03/20100 8403220100
- 8403270159 Notifies of eighth OCR status review meeting on 840328 w/ util. B&W & B&W in Ann Arbor, MI to discuss confirmed items & findings of independent design const verification program findings of independent design construction of Agenda encl.
 LEVIN.H.A. TERA Corp. 84/03/20. EISENHUT, D. O. Division of Licensing KEPPLER, J. G. Region 3, Office of Director COOK, J W Consumers Power Co., 5pp. 22769 157 24% Fiche 50-329, 84/03/20.
- 8403300070 Forwards minutes of mgt review for const completion plan quality verification program 830427 meeting Agenda & supporting documentation encl FALNER, B. Consumers Power Co 84/03/20 Stone & Webster, Inc 46pp. 22822:026 24X Fichs 50-327,84/03/20,8403300070

- 8403220007 Requests authorization to proceed w/work authorization Procedure 202550205. "Excavate Around Manhole 10 "

 QUAMME, D L Consumers Power Co 84/03/22 HARR(50N, J J Region 3,
 Office of Director Ip 22713 362 24X Fiche 50-329, 84/03/22, 8403220007
- F Security, medical, emergency & fire protection plans
- 8402090006 Board Notification 84-034 forwards R Vollmer 840206 memo to D Eisenhut re fire research results concerning fires in electrical cabinets in control room electrical cabinets of Licensing 84/02/23 PALLADING Commissioners 1p 22576 203 24X Fiche 50-000,84/02/23,
- --8403080316 Recommends that info re fire research results concerning fires in electrical cabinets in control room be submitted for board notification, per NRR Ofc Ltr 19, dtd 821001 Further voluation of test data required.

 VOLUMER: R H Division of Engineering 84/02/06 EISENHUT, D G
 Division of Licensing 10pp 22576 204 24X
 Ficha 50-000, 84/02/23.8402090006
- B403120103 Notifies of 840323 workshop on fire protection safe shutdown requirements of 100FR90.App R in Rosemont. IL to discuss IE Info Notice B4-09 & provide addl shutdown analyses &/or mod guidance Agenda encl BPESSARD.R L Division of Emergency Preparedness & Operational Bupport B4/03/06 CDDK.J W Consumers Power Co 3pp 22588 223 Bupport 84/03/06 CDDK, J W Consumers Power Co 24X Fiche 50-329,84/03/06,8403120103
- O Adjudicatory correspondence
- 8403060093 Forwards list of audit repts dtd 840130-0202 Certificate of Syc ent Related correspondence
 BRUNNER, J R Consumers Power Co 84/02/29 BECHOFFER, C,
 HARBOUR, J, COWAN, F P Atomic Safety and Licensing Board Panel
 App 22516 334 24X Fiche 50-329, 84/02/29, 8403060093
- 8403140119 Contention on Transamerica Delaval diesel generators re Model DSRV 12 Model cannot be relied upon to perform requisite safety function STAMIRIS.8 Stamiris, B 84/03/04 Atomic Safety and Licensing Board Panel 3pp 22624 201 24X Fiche 50-327,84/03/04,8403140119
- 8403140075 Forwards DG Eisenhut 830810 ltr to BP Garde, per 830921 commitment W/o encl
 HASSELL,D F Hearing Branch 1 84/03/05 BECHHOEFER,C,
 COUNN,F P, HARBOUR,J Atomic Safety and Licensing Board Panel
 Epp 22630 081 24% Fiche 50-329.84/03/05.8403140075
- 8403140154 Forwards summaries of 820202-05 meeting & audit re auxiliary building underpinning.820316-17 meeting & audit re soils remedial action & 831004-07 audit & meeting re HVAC sys WILCOVE.M N Hearing Branch 2 84/03/05 BERNABEI, L Government Accountability Project 2pp 22621 361 24X Fichs 50-327,84/03/05,86210555 R403140154
- 8403150003 Forwards svc water pump structure crack survey rept Concurrence on mods to crack mapping program requested Details will be discussed at 840404 meeting Certificate of Svc encl Related correspondence MODNEY, J A Consumers Power Co 84/03/05 HARRISON, J J Region Office of Director 30pp, 22824 116 24X Fiche 50-329,84/03/05,8403150003
- 8403120039 Advises that entire fireline excavation backfilled after physical connections made to restore fire svc to portions of site 8vc list encl Related correspondence BRUNNER.J E Carolina Power & Light Co 84/03/07 BECHHOEFER.C. COWAN,F P. HARBOUR,J Atomic Safety and Licensing Board Panel 3pp. 22389 271 24X Fiche, 50-329, 84/03/07, 8403120039
- 8403130114 Order revising schedules for submittal of proposed findings & conclusions on GA/mgt attitude issues ASLB may issue separate partial initial decision on certain issues not ancompassed by proposed findings on issues
 BECHHOEFER.C. Atomic Safety and Licensing Board Panel 84/03/12
 2pp 22615 295 24X Fiche 50-329.84/03/12,8403130114.
- 8403190166 Forwards Bechtel quality action rept supporting D Lewis testimony re buried control room pressuritation pipe Corrosion caused by stray welding currents not item of concern Svc list encl Related correspondence BRUNNER. J E Consumers Power Co 84/03/12 BECHHDEFER.C. HARBOUR.J. COMAN.F P Atomic Safety and Licensing Board Panel 7pp 22669 184 24X Fiche 50-329,84/03/12.8403190166

- 8403230031 Requests approval for release of insplactivity per NAC rework disposition regardless of position of module action item Related correspondence Guarmer. D L. Consumers Power Co. DSB 072 84/03/13 HARRISON, J J Region 3, Office of Director 3pp 28724 335 24X Fiche 50-327 84/03/13.840323003!
- 6403200011 Proposes to defer response to Stamiris OL contention re Transamerica Delaval diesel generators until after receiving Stamiris ltr in support of timeliness of contention Proof of Svc encl QIQMEM B R Isham, Lincoln & Beale GILOMEN, B R Consumers Power Co B4/03/15 BECHMOEFER.C Atomic Safety and Liconsing Board Fanel 3pp 22663 358 24X Fiche 50~329,84/03/15.8403200011
- B403200139 Addendum to Stamiris contention on Transamerica Delaval. Inc diesel generators addressing late filling factors of 10CFR2 714 STAMIRIS B Stamiris, B 84/03/15 Commissioners 2pp 22699 156 24x Fiche 50-329. B4/03/15, B403200139
- B403270020 Proposes to defer response to Stamiris 840304 contention re Transamerica Delaval diesel generators Proof of Sv. enc.] GILDMEN.B R [4ham. Lincoln & Beale GILDMEN.B R Consumers Power Co DSB 110 84703/15 BECHMOEFER.C Atomic Safety and Licensing Board Panel 3pp 22766 360 24X Fiche 50-329.84/03/15.8403270020
- B403220246 Order setting time for responses to B Stamiris 840304 motion as if 840315 addendum was original filling date Served on 840322 BECHOEFER. C Atomic Safety and Licensing Board Panel DSB 059 84/03/21 Office of the Eiscutive Legal Director 2pp. 22719 049 24X Fiche 50-229.84/03/21.8403220246
- 8403280348 Urder extending time until 840425 for Commission to act to review Director's Decisions DD-63-16 & DD-64-2 Served on 840328 CHILK, 8 J Office of the Secretary of the Commission DSB 158 64/03/27 Commissioners ip 22787 143 24X Fichs 50-329,84/03/27,8403280348

I Financial information

- 8403190071 Annual Financial Rept for 1983 W/840312 ltr SELBY.J D. FOLAMEE.J B. PERRY.P.A. Consumers Power Co. 83/12/31 01AMBUSBD.A. Division of Licensing 34pp 22666 136 24x Fiche 30-000.83/12/31.8403190071
- G Inspection reports. 1€ Bulletins & correspondence
- 8401230630 Partial response to FOIA request for IE 800103 rept re review of matl false statement at facilities. #ssociated & supporting records to rept & repts prepared in response Forwards App A documents Review of addl records in progress FELTON. J M Division of Rules and Records 83/11/01 HINSLOW.R Wall Street Journal 2pp 21905 337 24X Fiche 50-327,83/11/01. B401230430
- 8403070229 Partial response to FOIA request for repts re NRC investigation of failure of reactor vessel holddown studs on Unit I reactor vessel Forwards App & & B Gocuments FELTON.J H Division of Rules and Records 84/02/23 PLATO, E D Kohl, Secrest, Wardle, Lynch, Clark & Hampton 6pp 22564 149 247 Fiche 30-329.84/02/23.8403070229
- --8403070343 Forwards IE Insp Repts 50-329/80-12 & 50-330/80-13 on 800301-31 No noncompliance noted Major areas inspected eram of procedures & representative records, observations & interviews w/personnel M/o encl FIORELLIA Region 3. Chicago, Office of the Director 80/05/19 HOWELLS H. Consumers Power Co. 2pp 22964 170 24X Fiche 50-329,84/02/23,8403070229
- --B403070351 Responds to 830901 Itr & forwards IE Investigation Repts 50-329/80-13 & 50-330/80-14 H/o enc1 LEWIS. 51 H Region 3. Office of Director 83/09/20. MYERS, T F Garan, Lucow, Hiller, Seward, Cooper & Becker 1p 225
- BA01190072 IE Info Notice BA-13. "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl URBAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/02/28 Consolidated Edison Co of New York Inc 115pp 22909 239 24X Fiche 50-000.84/02/28,8401190072
- BA03130297 Advises that const implementation overview performed sampling insp of const training records for personnel Results satisfactory MARRAJE Stone & Webster, Inc. B4/02/29 GUAMME, D.L. Consumers Power Co. 1p. 22417

- 84030A0385 Forwards IE Monthly Meeting Ropts 50-329/84-05 & 50-329/84-05 on 840809 WARNICK, R F. Region 3. Office of Director 84/03/01 COOK, J W Consumers Power Co. 2pp 22507 004 24X Fiche 50-329, 84/03/01, 84030A0385
- --8403060398 1E Monthly Meeting Repts 50-329/84-05 & 50-330/84-05 on 840209 Major topics discussed crack mapping EPA jacking loads & US Testing audit corrective action status GARDNER, R N, HARRISON, J J Region 3, Office of Director 84/02/29 5pg 22507 006 24X Fiche 50-329,84/03/01.8403060385
- --B403060407 Forwards minutes of Feb 1984 monthly third-party assessment meeting re underpinning & remedial soils work LUCKS.A S Stone & Webster. Inc. B4/02/21, HARRISON.J J Region 3. Office of Director 21pp 22507 011, 24X Fiche 50-329.84/03/01.8403060385.
- --8403060415 Forwards Independent Assessment of Underpinning Weskiy Rept 6B for 840101-07 LUCKS:A S Stone & Webster, Inc. 84/02/12 COOK.R NRC - No Detailed Affiliation Given 11pp 22507 032, 24X Fiche 50-327,84/03/01.8403060385
- --8403060420 Forwards Independent Assessment of Underpinning Weekly Rept 67 for 840108-14 LUCKS.A S Stone & Webster. Inc 84/01/17 CODK.R NRC - No Detailed Affiliation Given 15pp 22507 043 24X Fiche 50-329,84/03/01.8403060385
- --8403060423 Forwards Independent Assessment of Underpinning Weekly Rept 70 for 840115-21 LUCKS.A B Stone & Webster, Inc. 84/01/25 COOK.R NRC - No Detailed Affiliation Olven 14pp 22507 058 24X Fiche 50-329,84/03/01.8403060385
- --8403060428 Forwards Independent Assessment of Underpinning Weekly Rept 71 for 840122-28 LUCKS.A S Stone & Webster, Inc. 84/02/02 COOK.R NRC - No Detailed Affiliation Given 16pp 22507 072 24X Fiche 50-329,84/03/01,8403060385
- --8403060442 Forwards Const Implementation Overview Weekly Rept 31 for 840109-13 KARR.J E Stone & Webster, Inc 84/01/18 KEPPLER, J Q Region 3. Office of Director 17pp 22507 100 24X Fiche 50-329,84/03/01.8403060385
- --8403060444 Forwards Const Implementation Overview Weekly Rept 32 for 840116-20 KARR.J E Stone & Webster, Inc 84/01/27 KEPPLER, J O Region 3. Office of Director 20pp 22507 117 24X Fichs 50-329,84/03/01,8403060389
- --8403060445 Forwards Const Implementation Overview Weekly Rept 33 for 840123-27 KARR.J E Stone & Webster, Inc 84/02/01 KEPPLER, J G Region 3. Office of Director, 17pp 22507 137 24X Fiche 50-329,84/03/01,8403060385
- B402090007 IE Info Notice B4-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE, J N Division of GA, Safeguards & Inspection Programs (Post B30103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22352 329 24X Fiche 30-000.84/03/02,8402090007
- B402090008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Bys Valves to Operate." Svc list encl JDRDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 122pp 2253 078 24X Fiche 50-000,84/03/02,8402090008
- B402090009 IE Info Notice B4-15, "Reporting of Radiological Releases "
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc 117pp. 22553 217 24X Fiche 50-000.84/03/02,8402090009.
- B403060288 Authorizes util to Jack Piers CT: & CT:2 as long as auxiliary bldg differential movement controlled according to 840106 agreement documented in IE Insp Repts 50-329/84-01 & 50-330/84-01 HARRISON.J J Region 3, Office of Director 84/03/02 QUANME.D.L. Consumers Power Co ip 22519 168 24X Fichs 50-329,84/03/02,84030280
- 8403130254 Forwards RC Sember 8402R3 memo re MPGAD inep evaluation & Overinep Audit MBA-84-6 VOKAL.D J Consumers Power Co 84/03/02 Stone & Webster, Inc 2pp 22606 034 24% Fichs 50-329/84/03/02.8403130224

- 8402070011 IE Info Notice 84-17. "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc. 117pp 22553 336 24X Fiche 50-000.84703/05,8402070011
- 8402090024 IE Info Notice 84-09. Rev 1. "Lessons Learned From Insps of Fire Protection Bafe Shutdown Sys " Svc list encl JCRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000.84/03/07.8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR 8ys " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 1186p 22584 186 24X Fiche 50-000.84/03/07.8402090028
- B402090031 IE Builetin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety 8ys" 8vc list encl
 DEYOUNG.R C Director's Office, Office of Inspection and
 Enforcement 84/03/12 Consolidated Edison Co of New York, Inc
 134pp. 22823 094 24X Fiche 80-000,84/03/12,8402090031
- B403220016 Submits summary of Bechtel investigation & corrective actions to resolve issue of nonconforming matl supplied by Tube-Line Corp. in response to IE Bulletin 83-06 Final response expected by 840615 CODK, J W Consumers Power Co 84/03/12 KEPPLER, J G Region 3 Office of Director 2pp 22712 339 24X Fiche 50-329,84/03/12,8403220014
- 8403270179 Submits resolutions to concerns addressed in 840110 ltr re hanger reinsp program Computer listing of hangers evaluated against commodity list to determine base number of hangers in program submitted GUAHME.D L. Consumers Power Co 84/03/15 KARR.J E Stone & Wabster. Inc 2pp 22770 291 24X Fiche 50-329.84/03/15.8403270199
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000.84/03/21,8402090043
- 84D2090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc list and JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche.50~000.84/03/21,8402090044
- R. Periodic operating reports & related correspondence
- B403070008 Forwards monthly rept for Jan 1984, per ALAB-106, including Bechtel honconformance rept, Bechtel FSO nonconformance rept, Bechtel guality action requests, Bechtel mgt corrective action repts & Bechtel GA findings COCK, J W Consumers Power Co 84/02/25 DEYOUND, R C Director's Office, Office of Inspection and Enforcement 2530pp 22527 010 24X Fiche 50-329, 84/02/25, 8403070008
- 8403220013 Forwards monthly status rept for Feb 1784 Monthly OCR/finding status review meeting scheduled for 840328 in Ann Arbor, All LEVIN.H A TERA Corp 84/03/16 EISENHUT, D G Division of Licensing. KEPPLER, J G Region 3, Office of Director COOK, J W Consumers Power Co 3pp. 22713 285 24X Fiche 50-329, 84/03/16, 8403220013.
- --8403220022 "Midland Independent Design & Const Verification Program Monthly Status Rept Number 10 for Feb 1984 "
 DOUGHERTY.F A TERA Corp 84/03/16 54pp 22713 288 24X
 Fiche 50-329,84/03/16,8403220013
- 8403270062 Forwards "Const Implementation Overview (CIO)," Weekly Rept 39 For 840305-09 KARRJJE Stone & Webster, Inc 84/03/16 KEPPLER, J G Region 3. Dffice of Director. 17pp 22766 088 24% Fiche 50-329.84/03/16, 8403270062.
- B403230043 Forwards monthly status rept for Midland project for Feb 1984. WARNICK, R. F. Region 3: Office of Director 84/03/19 KEPPLER, J G Region 3: Office of Director 1p 22728, 351 24X Fiche: 50-329: 84/03/19: 8403230043.
- --8403230046 Forwards monthly status rept for Midland project for Feb 1984. COOK, H J Region 3, Office of Director 84/03/15 WARNICK, R F Region 3, Office of Director 2pp 22728 352 24X Fiche: 50-329,84/03/19,8403230043

- 8 Reportable occurrences, LERs & related correspondence
- 8401230430 Partial response to FOIA request for IE 800103 rept re review of matl false statement at facilities, associated & supporting records to rept & repts prepared in response Forwards App A documents Review of addl records in progress FELTON.J M Division of Rules and Records 83/11/01 WINSLOW, R Wall Street Journal 2pp 21505 337 24x Fiche 50-329,83/11/01,8401230630
- --8401230660 PNO-79-039 on 790305, investigation concluded that GA program for obtaining proper soil compaction of facility deficient excessive settlement observed w/diesel generator bldg & incorrect info re soil foundation contained in FSAR BHEWMAKER, R E , HENDERSON, J B , THORNBURG, H D Office of Inspection & Enforcement, Office of the Director 79/03/06 2pp 21705 352 24X Fiche 50-329,83/11/01.8401230630
- 8403070226 FOIA request for repts re results of investigation of failed reactor vessel holddown study on Unit 1 reactor vessel PLATD.E D Kohl, Secrest, Wardle, Lynch, Clark & Hampton 84/01/23 KEPPLER, J G Region 3, Office of Director 2pp 22564 147 24X Fichs 50-329,84/01/23,8403070224
- 8403010451 Informs Commission of problems w/emergency diesel generators mfg by Transamerica Delaval, Inc DiRCKB W J Office of the Executive Director for Operations 8ECY-83-034 84/01/25 4pp 22438 347 24X Fiche 50-000,84/01/25,8403010451
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines, Gimpel NPS-4 T&T valve, to close Encl ltr dtd 840203 sent to listed utils GE notified of affected units in DWR plants
 THERDUX.R R Terry Corp 84/02/22 WDDDRUFF, R W Director's Office, Office of Inspection and Enforcement 6pp 22706-327 24X Fiche 50-000.84/02/22.8403210032
- 8403060269 Interim deficiency rept re nonconservative design of embedments in concrete using shear lugs located in tension rones Next rept expected by 840601 COOK.J W Consumers Power Co 84/07/24 MEPPLER.J 9 Region 3, Dffice of Director App 22515 201 24X Fiche 50-329.84/07/23, 8403060269
- 8403070229 Partial response to FDIA request for repts re NRC investigation of fellure of reactor vessel holddown stude on Unit 1 reactor vessel Forwards App A & B documents FELTON, J M Division of Rules and Records 84/02/23 PLATO, E D Kohl. Secrest. Wardle, Lynch. Clark & Hampton 6pp 22564 149 24X Fiche 30-327,84/02/23,8403070229
- ---8403070340 Ack receipt of 771214 interim rept re braken anchor bolt in reactor vessel support skirt flange.
 FIDRELLI.G Region 3, Chicago, Office of the Director 77/12/26
 HGMELLI.G H Consumers Power Co 10pp 22564 158 24X
 Fiche 50~327,84/02/23.8403070227
- --8403070345 Recommends order be issued to util requiring action to correct unacceptable anchor bolts at facility Draft ltr & poder encl KEPPLER, J O Region 3, Chicago, Office of the Director 80/06/27 THOMPSON, D Executive Officer for Operations Support 3cpp 22544 172 24% Fiche 50-329,84/02/23,8403070229
- --8403070349 Forwards depositions re preservice failure of reactor vessel studs utilized at Unit 1 Related info encl LEWIB.5 H Region 3, Office of Director 84/01/06 BERKGUITZ.D M Office of the General Counsel 52pp 22564 264 24X Fiche 50-329,84/02/23,8403070229
- 8403060104 Interim deficiency rept re B&W steam generator auxiliary feedwater header design change Unit 2 changes should be completed by 840227 Work on Unit 1 suspended due to delays in startup detes
 COOK, J W Consumers Power Co 84/02/24 KEPPLER, J G Region 3, Office of Director 3pp 22517 015, 24X Fiche 50-329,84/02/24,8403040104
- 8403060272 Interim deficiency rept re nonconforming electrical raceway sys. Adverse effect of deficiencies on safety of elant operation unlikely Bechtel revised final Rept MCAR 70 encl Next rept will be submitted by 840608 CODK, J W Consumers Power Co 84/02/24. KEPPLER, J G. Region 3, Office of Director 7pp. 22517-066 24X Fiche. 50-329, 84/02/24. 8403060272
- 8403060411 Forwards signed affidavit & resume of Z Zitak assigned to const implementation overview staff
 KARR, J E Stone & Webster, Inc 84/02/24 HARRISON, J Region 3, Office of Director Spp 22511.347 24X Fiche 50-329, 84/02/24, 8403060411

- 8403080026 Forwards rept on 840210 exit meeting w/Bechtel & NRC re indiscriminate cable substitutions Consumers Power Co 84/02/24 Stone & Webster Engineering Corp 3pp 22559 243 24X Fiche 50-329.84/02/24.8403080026
- 8403010207 Forwards "Investigation of Types AF & AE Piston Skirts," per Transamerica Delaval. Inc Owners Group program commitments Rept evaluates cracks in AF piston skirts in Shoreham & Grand Gulf Nuclear Power Stations When with notice the stations MUSELER. M J TB! (Transamerica Dalaval, Inc) Duners Group B4/02/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 22434 090 24% Fiche 50-000, B4/02/27, 8403010207
- 8403080245 Confirms that listing of open nonconformance repts, sorted by issue date given to D Brown on 840221 GUAMMED L Consumers Power to 84/02/27 BARANGW 9 Stone & Webster, Inc. 3pp. 22561 006 24% Fiche 50-329,84/02/27.
- 8403130074 Forwards closed Honconformance Identification Rept NIR-018 re training record discrepancies not in tompliance w/requirements of FPC-2 000/Rev 7, "Training of Const Personnel "

 KARR, J E Stone & Webster, Inc 84/02/27 GUAMME, D L Consume

 Power Co 3pp 22615 219 24X Fiche 50-329,84/02/27,8403130074 Consumers
- 84020900R1 Board Notification 84-039 discusses NRC 840210 & 16 meetings
- NO20700R1 Board Notification 84-037 discusses NNC 840210 & 16 W/Transamerica Delaval, Inc Emergenty Diesel Generators Owners Group Meeting scheduled on 840308 for finalization of generic program plan prior to NRC review EISENHUT, D G Division of Licensing 84/02/28 PALLADINO, GILINSKY, ROBERTS Commissioners 5pp 22546 003 24X Fiche 50-000,84/02/28,8402090021
- 8403010218 Forwards task descriptions for 16 known problems re Transamerica Delaval, Inc emergency diesel generators MUSELER, W. J. TDI (Transamerica Delaval, Inc.) Owners Group 84/02/28 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 42pp 22435 177 24X Fiche 50-000.84/02/28,8403010218
- 8403080171 Forwards requested list of items determined to be ready for review & closure by NRC Items marked by asterist reviewed by Region III inspectors & will be removed from list when closed in inspirept CODK. J W Consumers Power Co 84/02/28 KEPPLER. J O Region 3. Office of Director 16pp 22559 278 24% Fithe 50-329.84/02/28, 2803380121 8403080171
- 8403080187 Forwards response to Tracked Info Item 054 requesting MTC QA manual, quality plan program manual, procedures & target list utilized at site & walkdown summaries issued to date * Consumers Power Co. 84/02/28 Stone & Mebster, Inc. 2pp 22559 112 24X Fiche 50-329,84/02/28,8403080187
- 8403080192 Advises that sampling insps of const training records of personnel complete Results of insp satisfactory & NIR-018 closed Personnel listed on encls cleared to perform status KARR, J E Stone & Webster, Inc 84/02/28 QUAMME, D L Consumers Power Co 1p 22559 201 24% Fiche 50~329, 84/02/28, 8403080192
- 8403080235 Lists audit finding repts.including MSA-83-7-04F, 01F & M01-403-03-02
- 8403130173 Forwards closed const implementation overview, Item 035 re dielectric isolation spacers for galvanic protection of copper pipe to galvanized steel pipe supports missing in
- some areas KARRIJ E Stone & Webster, Inc. 84/02/28 QUAMME.D L. Consumer-Power Co. 29pp. 22599 194 24X Fiche 50-329.84/02/28.8403130173
- 8402090020 Board Notification 84-044 forwards Part 21 rept re Transamerica Delaval.Inc turbocharger thrust bearing lubrication defect resulting in engine nonavailability EISENHUT, D 0 Division of Licensing 84/02/29 PALLADIND Commissioners 4pp 22541 243 24X Fithe 50-000,84/02/29, 8402090020
- B403080221 Forwards Nonconformance Identification Rept 019 On 840222, field deviation disposition list not revised to reflect changes for Specs M-1A & C-304 MARR.J E Stone & Webster, Inc. 84/02/29 GUAMME, D L Consumers Power Co 2pp 22560 022 24% Fiche 50-329,84/02/29,8403080221
- 8403080247 Forwards complete response to Const Implementation Overview Item 056 re inconsistencies noted during evaluation of training for POCI C-1 50 22561 019

\

- 8403080250 Forwards closed Const Implementation Overview Item 054 re Mark Technologies Corp GA & quality program plan manuals, procedures & target list MARR, J E Stone & Wabster, Inc 84/02/29 QUAMME, D L. Consumer Power Co 3pp 22561 016 24X Fiche 50-329, 84/02/29, 8403080250
- 8403080259 Forwards complete response to Const Implementation Overview Item 037 re trainer evaluation * Consumers Power Co 84/02/29 Stone & Webster, Inc 4pp 22557 113 24x Fiche 50-329,84/02/29,8403080259
- 8403130210 Forwards closed GAR RT-00021 which provides complete response to Nonconformance Identification Rept NIR-008 retraining matrix training matrix

 * Consumers Power Co B4/02/29 Stone & Webster, Inc 6pp
 22605.057 24% Fiche 50-329.84/02/29.8403130210
- 8403050385 Forwards IE Monthly Meeting Repts 50-329/84-05 & 8403060395
- --8403060407 Forwards minutes of Feb 1984 monthly third-party assessment menting to underpinning & remedial soils work LUCKB.A S Stone & Webster, Inc 84/02/21 HARRISON, J J Region 3. Office of Director 21pp 22507 011 24X Fichs 50-329,84/03/01,8403060385
- --8403060415 Forwards Independent Assessment of Underpinning Weekly Rept 68 for 840101-07 68 for 840101-07 LUCKB.A S Stone & Webster, Inc 84/02/12 CDOK,R NRC - No Detailed Affiliation Given 11pp 22507 032 24X Fiche 50-329,84/03/01.8403040385
- --8403060420 Forwards Independent Assessment of Underpinning Weekly Rept 40300420 Forwards Independent Assessment of Underpinning Weekly 67 for 840108-14 LUCKB,A S Stone & Webster, Inc 84/01/17 CDOK,R NRC - No Detailed Affiliation Given 15pp 22507 043 24X Fiche 30-329,84/03/01.8403060385
- --8403060423 Forwards Independent Assessment of Underpinning Weekly Rept 70 for 840115-21 TO for 840115-21 LUCKB:A S Stone & Webster, Inc 84/01/25 COOK,R NRC - No Detailed Affiliation Given 14pp 22507 058 24X Fiche 50-327;84/03/01;8403040385
- --8403040428 Forwards Independent Assessment of Underpinning Weakly Rept 71 for 840122-28 LUCKS,A S Stone & Webster, Inc 84/02/02 COOK,R NRC - No Detailed Affiliation Olven 16pp 22507 072 24X Fiche 50-329,84/03/01,8403060385
- --8403050442 Forwards Const Implementation Overview Weekly Rept 31 for KEPPLER, J Q Region
- --8403060444 Forwards Const Implementation Overview Weekly Rept 32 for 90300444 FORWARDS CONST IMPLEMENTATION OVERVIE B40116-20 KARR.J E Stame & Webster. Inc. 84/01/27 K 3. Office of Director 20pp. 22507 117 24X Fiche 30-327,84/03/01,8403060385 KEPPLER, J. Q. Region
- --8403060445 Forwards Const Implementation Overview Weekly Rept 33 for HAGIRJ-27

 KARR, J E Stone & Webster, Inc 84/02/01 KEPPLER, J Q. Region 3, Office of Director 17pp 22507 137 24X

 Fichs 50-329,84/03/01,8403060385
- 8403130175 Forwards closed const implementation overview Item 057 re training classes KARR.J E Stone & Webster, Inc 84/03/01 QUAMME.D L. Consumer Power Co 5pp 22617 307 24X Fiche: 50-327,84/03/01,8403130195
- B403080222 Interim deficiency rept re coordination of engineering holds & restrictions resulting in installation of unqualified Essex cables Cables will be replaced Interim or final rept expected by 840504 CODK, J W Consumers Power Co 84/03/02 KEPPLER, J C, Region 3, Office of Director &pp 22541025 R4X Fiche. 50-329, 84/03/02, 8403080222
- 8403130050 Forwards closed Audit Finding Repts MBA-83-25-02F, MSA-83-25-10F & MSA-83-25-03F & closed Unresolved Item Repts MSA-83-25-09U & MSA-83-25-07U VORAL, D J Consumers Power Co 84/03/02 Stone & Webster, Inc 12pp 22608.094 24X Fiche 50-327.84/03/02.8403130050.

- 8403:30184 Forwards Nonconformance Identification Rept 020 re unsigned
 - Change request forms

 KARR.J. E Stone & Webster, Inc 84/03/02 QUAMME.D L Consume

 Power Co 2pp 22617 234 24X Fiche 50-329,84/03/02,8403130184 Consumers
- 8403130292 Forwards Audit Rept MSA-83-39 W/o encl VOXAL, D J Consumers Power Co 84/03/02 Stone & 1p 22414 149 24X Fiche 50-329,84/03/02,8403130292 Stone & Webster, Inc
- 84031303R1 Forwards Const Implementation Overview Hold Point Notification Item Odl re subcontract document control for action. Recommends form be revised to provide signature &
- date space for racipient

 KARR.J E Stone & Webster, Inc 84/03/02 GUAMME.D L Consume

 Power Co 2pp 22614 130 24X Fiche 50-327,84/03/02,8403130321 Consumers
- 8403140048 Forwards "Grand Gulf Component Tracking Sys," "Shoreham Component Tracking Sys" & "Transamerica Delavel, Inc Diesel Generators Owners Group Program Plan," to resolve concerns w/smergency diesel generators MUSELER; W J Long Island Lighting Co 84/03/02 DENTON, H R D#fice of Nuclear Reactor Regulation, Director 2pp 22626 062 24X Fiche 50-000,84/03/02,8403140048
- --- 8403140095 "Transamerica Delaval.Inc Diesel Generators Owners Group
 - 403140070 ', m.,-... Program Plan " * TDI (Transamerica Delaval, Inc) Guners Group 84/03 941ab 22628 223 24X Fiche 50-000,84/03/02,8403140048 B4/03/02
- 8403130161 Forwards, for info,closed Quality Action Request GAR-RT-00020 used to track const implementation overview Nonconformance Identification Rept NIR-007

 * Consumers Power Co. 84/03/05 Stone & Webster, Inc. 10pp 22599:298 24X Fiche 50-329,84/03/05,8403130161
- B403130362 Forwards partial response to Tracked Action Item 043, consisting of pre- & post-stop work order activities, DDR implementation, site-wide distribution plan implementation schedule & corrective action plan W/o encis REICHEL.N I Consumers Power Co. B4/03/05, Stone & Webster, Inc 1p. 22616 269 24X Fiche 50-329, 84/03/05, 8403130362
- 8403130479 Forwards Const Implementation Overview, Item 048 re inconsistency between spec requirements on spacing between anchor bolts of different diameters Bechtel preparing spec change notice. KARR, J.E. Stone & Webster, Inc. 84/03/05 KEPPLER, J. Q. NRC - N. Detailed Affiliation Given. GUAMME, D.L., REICHELIN I Consumers Power Co. 3pp. 22613, 228, 24X Fiche 50-329, 84/03/05, 8403130479. NRC - No
- B40313023B Forwards Const Implementation Overview Item 062 re training classes Btatus assessment performed on pipe supports by personnel w/incomplete required training KARR. J. E. Stone & Webster, Inc. B4/03/06, KEPPLER, J. G. Region 3, Dffice of Director 3pp 22606 057 24X Fiche 50-329,84/03/06, B40310339
- B403130354 Forwards completed response to Tracked Action Item 04B consisting of Spec Change Notice 14001 to Spec C-306 regrouted anchor bolts REICHEL,N I Consumers Power Co 84/03/06 Stone & Webster. LIN I Consumers Power Co 84/03/06 Stone & Webster, Inc 22616 330 24X Fiche 50-329,84/03/06,8403130354
- 8403130491 Requests extension to 840309 for responding to Tracked Info Items 058 & 059 & Tracked Recommendation Item 060 REICHEL,N. I. Consumers Power Co 84/03/06 Stone & Wabster, Inc ip 22613 180, 24X Fiche 50-029, 84/03/06,8403130491
- 8402090033 Board Notification 84-047 forwards Transamerica Delayal, Inc Owners Group piston skirt rept & task descriptions EIBENHUT. D. O Division of Licensing 84703/07 PALLADIND, OILINSKY, ROBERTS Commissioners 4pp 22674, 221 24X Fiche: 50-000, 84/03/07, 8402090033
- 8403130271 Informs that response to Nonconformance Insp Rept 008 satisfactory Const implementation overview will continue to monitor training commitments w/emphasis on listed areas. MARR, J. E. Stone & Webster, Inc. 84/03/07 QUAMME,D L. Consumu Power Co. 1p 22614*175 24X Fiche: 50-329, 84/03/07, 8403130271
- 8403140122 Part 21 rept re status update concerning abnormal wear on linear converters. Test program underway Results of investigation indicate excessive wear caused by hunting of control circuitry.

 DOBSON. J P. Pacific Air Products Co 84/03/07 Director's Office. Defice of Inspection and Enforcement 7pp 22624'068 24 Fiche 50-000.84/03/09.8403140122 22624'068 24X

- 8403220072 Forwards listed documentation re post-weld heat treat thermocouples Bechtel in contact w/suppliers to obtain replacements W/o encl # Consumers Power Co # 84/03/09 SMITH A Stone & Webster, Inc ip 22712 310 24x Fiche 50-329,84/03/09,8403220072
- 8402090038 Board Notification 84-051 forwards "Transamerica Delaval, Inc. (TDI) Diesel Generators Owners Group Program Plan " EISENHUT,D G Division of Licensing 84/03/12 PALLADING, GILINSKY, ROBERTS Commissioners 5pp 22688 214 24X Fiche 50-000.84/03/12,8402070038
- 8402090039 Board Notification 84-032 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delaval, Inc (TDI) Owners Group Distribution list encl EISENHUT,D 9 Division of Licensing 84/03/12 PALLAD GILINSKY, ROBERTS Commissioners 5pp 22708 001 24X Fichs 50-000, 84/03/12,8402090039 PALLADINO,
- --8403060536 Forwards summary of 840210 meeting w/Transamerica Delaval, Inc Owners Group in Bethesda,MD re-problems w/emergency dissel generators
 CARUSO.R Licensing Branch 2 84/02/27 O'REILL)
 Detailed Affiliation Given 6pp 22708 006 24X
 Fiche 50-000,84/03/12,8402090037 O'REILLY, J P NRC - No
- --8403060554 Transcript of 840210 meeting w/Transamerica Delaval.inc Owners Group in Bethesda, MD re problems w/emergency diesel generators * NRC - No Detailed Affiliation Given 84/02/10 147pp 22708 012 24X Fiche 50-000,84/03/12,8402090039
- --8403070407 Summary of 840216 meeting w/Transamerica Delaval, Inc Owners Group in Wading River, NY re program plan to establish reliability of diesel generators Agenda, meeting transcript & attendance list encl
 MILLER, M A Licensing Branch 4 84/02/27 Licensing Branch 4 8pp 22708-161 24X Fiche 50-000,84/03/12,8402090039
- -8403070423 Transcript of 840216 conference in Wading River,NY re Transamerica Delaval, Inc diesel generators Pp 1-92 * Commissioners 84/02/16 84pp 22708 169 24X Fiche 50-000,84/03/12,8402090039
- 8403140050 Forwards "Besign Review of Connecting Rod Bearing Shells for Transamerica Delaval Enterprise Engines" for Shoreham & Orand Gulf diesel generators MUBELER, W. J. Long Island Lighting Co. 84/03/12 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 22632 074 24X Fiche 50-000,84/03/12,8403140050
- B403150133 Forwards "Transamerica Delaval, Inc Diesel Generator Rocker Arm Capscrew Stress Analysis Rept," Capscrew design adequate for applicable engines & svc conditions MUSELER, W J TDI (Transamerica Delaval, Inc.) Owners Group 84/03/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22639 270 24X Fiche 50-000, 84/03/13, 8403150133
- 8403270169 Forwards, for info, Quality Action Requests (QARs) RA-00134 & RA-00135 to assign action & track const implementation overview (CIO) NIRs 019 & 020 on MPQAD GUAIL, sys CIO will evaluate satisfactorily closed out QARs to close out NIRs # Consumers Power CO 84/03/14 Stone & Webster, Inc App 22771 138 24X Fiche 50-329.84/03/14.8403270169
- 8403270023 Informs that all G redline drawings incorporated.per Hold Point OOL Rept A * Consumers Power Co 84/03/15 Stone & Webster, Inc 2pp 22770 067 24% Fiche 50-329,84/03/15,8403270023
- B403270029 Forwards response to Tracked Info Item 055 re training matrix status assessment requirements + Consumers Power Co 84/03/15 Stone & Webster, Inc 11pp 22769 328 24% Fiche 50-329.84/03/15,8403270029
- 8403270227 Forwards open Const Implementation Overview Item 063 re status assessment in Module 1200 on 840313 using unmarked *tatus assessment.

 FSK prints

 KARR.J E Stone & Webster. Inc 84/03/15 KEPPLER.J 9 NRC - F

 KARR.J E Stone & Webster. REICHEL.N I , WELLS.R A Consumers

 Power Co 3pp 22772 0B1 24X Fiche 50-329, 84/03/15, 8403270227 NRC - No
- 8403200222 Responds to 840214 Requests for Info 1 & 2 re R-4 series angines List indicating engine number, model & svc number, customer name & address, rating, date shipped & date started MATHEMS, C.S. Transamerica Delaval, Inc. 84/03/16, EISENHUT, D.G. Division of Licensing 20pp 22691 179 24X Fiche 50-000,84/03/16,8403200222

- B403220067 Interim deficiency rept re low allow quenched & tempered bolting 1 5-inches & greater in support of safety-related sys Current status of Bechtel matl evaluation encl Next rept will be sent by B40727 COOK.J W Consumers Power Co B4/03/16 KEPPLER, J O Region 3. Diffice of Director 10pp 22716 150 24X Fiche 50-329,84/03/16. 8403220067
- 8403220108 Interim deficiency rept re defective capstan springs in mechanical shock arrestors supplied by Pacific Scientific Arrestors being evaluated & tested Nert rept by 840804 CDBK.J W. Consumers Power Co. 84/03/16 KEPPLER.J G. Region 3. Office of Director 17pp 22716 180 24X Fiche 50-327.84/03/16. 8403220108
- B403270062 Forwards "Const Implementation Overview (CIO)." Weekly Rept 39 for 840305-09 KARR.J E Stone 7, Webster, Inc 84/03/16 KEPPLER.J 0 Region 3, Defice of Director 17pp 22766 088 24% Fiche 50-329,84/03/16, 240327084
- 8403270076 Forwards const implementation overview for Items 064.065 & 066 re CW-1 00. "E-Series" PDCI's.Zack Procedure MB-FP-7C & Zack Procedure MB-FP-7B Welding insp requirements deleted & spec change natice recommended KARR, JE Stane & Webster. Inc 84/03/16 KEPPLER, J G NRC No Detailed Affiliation Given REICHEL, N I Consumers Power Co GUAMME.D L Stone & Webster. Inc 4pp 22766 356 24X Fishe 50-329, 84/03/16, 84/03270076
- 8403270093 Forwards Closed Const Implementation Overview Item 056/Hold Point Notification re Checklist MP-MIS-008E-0001 Review of items re impact on training requested KARR.J E Stone & Webster, Inc. 84/03/19 KEPPLER.J O NRC No Detailed Affiliation Given REICHEL.N 1 . QUAMME.D L Consumers Power Co 5pp 22769 358 24% Fiche 50-329.84/03/19.8403270093
- 8403270236 Forwards DF Ronk B40315 memo to JT Christy & attachments showing planned weekly menhour allocations for PGCI & areas for wks of 840323.30 & 0406 W/o encl RONK, DF Consumers Pawer Co. 84/03/19 BAUMGARTNER, T Stone & Webster, Inc. 10 22771 347 24X Fiche 50-329.84/03/19.8403270236
- 8403300006 Forwards Closed Const Implementation Overview Item 052 re Criterion XVIII site auditing KARR.JE Stone & Webster, Inc. 84/03/20 KEPPLER.J G NRC - No Detailed Affiliation Given GUAMME.D L . REICHEL.N 1 Consumers Power Co 3pp 22822 126 24X Fiche 50-329.84/03/20.8403300006
- 8403300035 Forwards proposed project records classification code list b mgt policy for review KARR.J E Stone & Webster Engineering Corp 84/03/20 GUAMME.D L Consumers Power Co 8pp 22824 312 24X Fiche 50-327, 84/03/20, 8403300035
- 8403270132 Forwards "Emergency Diesel Generator Air Btart Valve Capscrew Dimension & Stress Analysis," prepared by 58M for Transamerica Delaval. Inc (TDI) Diesel Generator Owners Group MUSELER.W J TDI (Transamerica Delaval, Inc.) Dumers Group B4/03/23 DENTON.H R Geffice of Nuclear Reactor Regulation. Director 2pp 22774 001 24X Fiche 50-000.84/03/23.8403270132
- 8403270134 Requests meeting on 840418 to discuss short-term & long-term corrective actions & investigations re Transamerica
 Delaval dissel generators List of suggested meeting topics
 enc!
 MCGAUGHY, J P | TDI (Transamerica Delaval, Inc.) Owners Group
 84/03/23 DENTON, H R Office of Nuclear Reactor Regulation,
 Director 4pp 22769 133 24X Fiche 50-000, 84/03/23, 8403270134
- T Hearing transcripts on non-antitrust matters
- B402090039 Board Notification B4-052 forwards meeting summaries containing transcripts of 840210 t 16 meetings between NRC transamerica Delaval, Inc. (TDI) Guners Group Distribution list encl.
 EISENHUT, D.G. Division of Licensing 84/03/12 PALADIND Commissioners 5pp 22708 001 24X Fiche 50-000, 84/03/12. 8402090039
- --8403060336 Forwards summary of 840210 meeting w/Transamerica Delaval, Inc Owners Group in Bethesda, MO re problems w/emergency diasel generators
 CARUBO, R Licensing Branch 2 84/02/27 O'REILLY, J P NRC No Detailed Affiliation Given App 22708 006 24X
 Fiche 50-000, 84/03/12, 8402090039
- --B403060554 Transcript of 840210 meeting w/Transamerica Delaval.Inc Owners Group in Bethesda.MD re problems w/emergency diesel generators * NRC - No Detailed Affiliation Given 84/02/10 147pp 67201 008 24X Fiche 50-000,84/03/12.8402090039

- --8403070409 Summary of 840216 meeting w/Transamerica Delaval.Inc Owners Group in Wading River.NY re program plan to establish reliability of diesel generators Agenda: meeting transcript & attendance list encl MILLER.M A Licensing Branch 4 84/02/27 Licensing Branch 4 Bpp 22708 161 24X Fiche 50-000.84/03/12.8402090039
- --B403070423 Transcript of B40216 conference in Wading River.RY re Transamerica Delaval.Inc diesel generators Pp 1-82 * Commissioners B4/02/16 B4pp 22708 167 24X Fiche 50-000.84/03/12,8402070037

DOCKET 50-330 MIDLAND PLANT, UNIT 2

- A Application/construction stage documents & correspondence
- B403010192 FOIA request for records relevant to or generated in connection w/831021 "Rept on Review of Diesel Generator Bidg at Midland"

 GARDE, B P Government Accountability Project 83/11/26 Office of Administration 2pp 22445 092 24X Fiche 50-329,83/11/26.
- 840301019B Responds to FOIA request for records relevant to or gonerated in connection w/831021 "Rept on Review of Diesel Generator Bldg at Midland " Forwards App B documents App A documents available in PDR FELTON, J M Division of Rules and Records 83/12/14 GARDE, B P Government Accountability Project 4pp 22445 092 24X Fiche 50-329,83/12/14,8403010198
- --8310310471 Forwards task group rept, "Rept on Review of Diesel Generator Bldg at Midland." Oct 1983 Large addl settlements not anticipated More accurate program to monitor cracks needed KUD.P Structural & Geotechnical Engineering Branch 83/10/21 KNIGHT.J P Assistant Director for Comp & Structures Engineering (Post 830201) 2pp 22445 152 24X Fiche 50-329,83/12/14. 8403010198
- --8310310475 "Rept on Review of Diesel Generator Bldg at Midland "
 TAN.C P Structural & Geotechnical Engineering Branch 83/10/31
 94pp 22445 154 24X Fiche 50-329.83/12/14.8403010198
- --B312010004 Forwards corrected Pages 9.17.20 & 4 to App 11 to rept on review of diesel generator bldg

 KUO.P Structural & Geobachnical Engineering Branch B3/11/14

 KNIGHT.J P Assistant Director for Comp & Btructures Engineering (Post B30201) 5pp 22445 296 24X Fiche 50-329,83/12/14.

 B403010198
- --8312050626 Requests rept re adequacy of diesel generator bldg on expedited basis as input to Congress re Landsman concerns EISENHUT.D G Division of Licensing 83/11/18 VOLLMER.R Division of Engineering 1p 22445 263 24X Fiche 50-327.83/12/14.8403010198
- --B312070022 Forwards Structural & Geotechnical Engineering Branch assessment of "Rept of Review of Diesel Generator Bldg at Midland." dtd B31021 per E Adensam & W Paton requests Maeting & possible reopening of hearing recommended LEAR.0 Structural & Geotechnical Engineering Branch B3/11/22 VOLLMER.R H Division of Engineering 2pp 22445 268 24X Fiche 50-329, 83/12/14, 8403010198
- --B312070298 Discusses recommendation for suppl to Board Notifications 83-165 & 83-153 re diesel generator bldg Comments & recommendations of J Kane & F Rinaldi on task group rapt & reopening of hearing provided HODD,D S Licensing Branch 4 83/ii/22 EISENHUT,D 0 Division of Licensing 4pp 22445 264 24X Fiche 50-329,83/12/14. 8403010198
- --8312080134 Recommends PT Kwo 831114 memo containing four corrected pages to rept re structural adequacy of diesel generator bldg be forwarded to Board as supplemental notification to BN 83-165
 HOOD, D Licensing Branch 4 83/11/17 EISENHUT, D Assistant Director for Licensing ip 22445 261 24X Fichs 50-329, 83/12/14,8403010198
- --8403010204 Advises that info re plan to address Landsman concerns should be issued as Board Notification 83-109 EISENHUT, D. G. Division of Licensing 83/07/27 NOVAK, T Assistant Director for Licensing ip 22445 098 24X Fiche 50-329, 83/12/14, 8403010198

- ---8403010211 Advises that attached correspondence re new schedule for review of Landsman concerns should be issued as Board Notification 83-142 W/o enci EISENHUT,D @ Division of Licensing 83/09/20 NOVAK,T Assistant Director for Licensing 1p 22445 099 24X Fiche 50-227,83/12/14,8403010198
- --B403010217 Draft rept. "Review of Diesel Generator Bldg at Midland Plant" MILLER, C A , COSTANTINO. C J Brookhaven National Laboratory B3/09/23 25pp 22445 100 24X Fiche 50-329, B3/12/14, B403010198
- --B403010223 Advises that encl JP Knight 830723 memo to RH Vollmer should be issued as Board Notification 83-153 W/o encl EIBENHUT, D G Division of Licensing 83/10/05 NOVAK, T Assistant Director for Licensing 1p 22445 125 24X Fichs 50-329, 83/12/14, 8403010198
- Fiche 50-329, 83/12/14, 8403010198

 --8403010227 Forwards "Review of Diesel Generator Bldg at Midland Plant "
 REICH, M Brookhaven National Laboratory B3/10/17 KUO, P T
 Structural & Geotechnical Engineering Granch ip 22445 126 24X
 Fiche 50-329, 83/12/14, 8403010198
- --B403010245 Requests that encl rept on review of diesel generator bldg & util analysis requested during review be issued as Board Notification 83-165 EISENHUT,D & Division of Licensing 83/10/26 NOVAK,T Assistant Director for Licensing 6pp 22445 250 24X Ficher 50-327,83/12/14,8403010198
- --B403010273 Advises that supplemental info provided in PT Kuo B31114 memo to JP Knight will be transmitted to Midland Board as suppl to Board Notification B3-165 Issue will be incorporated as Board Notification B3-169A W/o encl EISENHUT, D 0 Division of Licensing B3/11/16 NOVAK, T Assistant Director for Licensing 1p 22445 262 24X Fiche 50-329, B3/12/14, B40301019B
- --8403010282 Forwards guidance for use in deciding whether to recommend that hearing be reopened Hearing should be reopened based on listed reasons
 VOLLMER,R H Division of Engineering 83/11/25 EISENHUT,D G Division of Licensing 3pp 22445 270 24X Fiche 50-329, 83/12/14,8403010198
- --8403010285 Advises that Vollmer recommended reopening Midland hearing on diesel generator bldg structural adequacy issue, based on task group rept Vollmer memo enc! W/o enc! ADENSAM,E NRC No Detailed Affiliation Given 83/11/25 EIBENHUT,D NRC No Detailed Affiliation Given ip 22445 273 24X Fiche 50-327,83/12/14,8403010198
- 8403010488 Appeals denial of FDIA request for T Novak notes generated by or during visit to Olen Ellyn. IL to discuss Ofc of Bpecial Cases findings re facilities from Sept 1782 to Dec 1783 OARDE, B. P. Government Accountability Project 84/01/17 FELTON, J. M. Division of Rules and Records 1p 22443 274 24X Fiche 50-327, 84/01/17, 8403010488
- 8403050485 Further response to FDIA request for documents re evaluation or review of design.comst.scheduling.cost & licensing of facilities from 1977 to present Rept unavailable for Categories 1 & 2 Pauel records on evaluations placed in PDR FELTON, J M Division of Rules and Records 84/01/24 ZACK.A M Barris. Sott. Denn & Driker 2pp 22552 252 24X Fiche 50-329.84/01/24,8403050486
- B403060370 Notifies of independent design & const verification program 840313 meeting w/NRC & util in Bethesda.MD to discuss details of completion of IDVP LEVIN.H A TERA Corp 84/02/24 EISENHUT, D G Division of Licensing KEPPLER, J G Region 3, Office of Director CODK, J W Consumers Power Co 3pp 22511 312 24X Fiche 50-327, 84/02/24, 8403060370
- B403010276 Authorizes util to proceed w/remedial soils work activities scheduled for Mar 1984, per 840214 request for Work Authorization Procedure 102750125 HARRISON, J.J. Region 3. Office of Director 84/02/28 GUAMME, D. Consumers Power Co. 2pp 22432 104 24% Fiche 50-329, 84/02/28, 8403010276.

- 8403010497 Responds to appeal redenial of FDIA request for records in possession of T Novak on visit to Clen Ellyn. IL to discuss findings of Ofc of Special Cases refacilities NRC has no records subj to request DIRCKS.W J Office of the Executive Director for Operations 84/02/2B GARDE.B P Government Accountability Project ip 22443 273 24% Fiche 50-329, 84/02/2B.8403010497
- B4030B023D Lists unresolved items & audit finding repts, including MSA-B3-10-03U & MSA-B3-25-07F, respectively # Consumers Power Co B4/02/2B Stane & Hebster, Inc ip 22540 126 24X Fiche 50-329, 84/02/2B, 84030B0230
- 8403080241 Forwards 840227 list of Bethtel personnel trained to accomplish status assessment * Consumers Power Co 84/02/28 Stone & Webster, Inc 3pp 22541 013 24X Fiche 50-329,84/02/28.8403080241
- 8403080248 Forwards proposed list of remedial soils work for Mar 1984 * supplemental work activity list for Apr 1984 Review.comments & authorization requested QUAMME.D L Consumers Power Co 84/02/28 HARRISON.J J Region 3. Diffice of Director 13pp 22556 276 24X Fiche 50-329,84/02/28,8403080248
- B4030B0260 Forwards summary of sixth meeting on confirmed items & findings on 840201 at Bechtel Ann Arbor,MI ofc re items identified in independent design & const verification program monthly status rept dtd 840113
 LEVIN.H A TERA Corp 84/02/28 KEPPLER,J G Region 3, Office of Director COOK,J W Consumers Power Co EISENHUT,D G Division of Licensing 14pp 22557 078 24X Fichs 50-327,84/02/28.8403080260
- B403130261 Notifies that GR Fotiades placed on controlled distribution of training plan manual, per B40224 request QUAMME, D L Consumers Power Co 84/02/28 BARANDW, S Stone & Webster, Inc 1p 22617 134 24X Fiche 50-329,84/02/28,8403130261
- 8403220179 Forwards B40307 memo providing documentation to S&W for const implementation overview * Consumers Power Co 84/02/28 Stone & Webster, Inc App 22717 024 24X Fiche 50-329,84/02/28,8403220179
- B4030B0262 Forwards weekly NSSS subcontract status rept for wk ending 840217 W/o encl * Consumers Power Co 84/02/29 Stone & Webster, Inc 1p 22557 112 24X Fiche 50-329,84/02/29,8403080262
- 8403130189 Provides list of documents sent to S&W on 840229

 * Consumers Power Co 84/03/01 Stone & Webster, Inc 1, 22617 323 24X Fiche 50-329,84/03/01.8403130189
- B403140021 Forwards Vol X to "Seismic Margin Review,Miscellaneous Subsystems & Components " COOK,J W Consumers Fower Co B4/03/01 DENTON,H R Division of Licensing 3pp 22632 167 24X Fiche 50-329,84/03/01.8403140021
- --8403140026 "Seismic Margin Review, Miscellaneous Subsystems & Components "
 WESLEY, D A., NARVER, R B. Structural Mechanics Associates SMA 13701 09R003 VIO 84/02/29 200pp 22432 171 24X
 Fiche 50-329,84/03/01.8403140021
- 8403130470 Discusses sampling insps of const training records for personnel noted in Correspondence CSC-7382 Personnel listed cleared to perform status assessment enci M/o enci KARR, J E Stome & Webster, Inc 84/03/02 QUAMME.D t. Consumers Power Co ip 82613 809 24X Fiche 50-329,84/03/02.8403130470
- B403150003 Forwards svc water pump structure crack survey rept
 NRC concurrence of mods to crack mapping program requested
 Seven oversize drawings enci Aperture cards are available in
 PDR
 MOONEY, J A Consumers Power Co B4/03/05 HARRISON, J J Region 3,
 Office of Director 30pp 22824 116 24X Fiche 50-329,84/03/05.
- B4031303BB Forwards signed affidavit & resume for RE Horine assigned to const implementation staff at plant KARR.JE Stone & Webster, Inc B4/03/06 HARRISON.JJ Region 3. Office of Director 7pp 22605 001 24% Fiche 50-329.84/03/06.
- B403130482 Advises that listed remedial soils work activities presently scheduled for Apr 1984 identified as critical work activities Appropriate details of listed activities requested to assist NRC in review HARRISON. J J Region 3. Office of Director 84/03/06 QUAMME. D L Consumers Power Co 4pp 22613 193 24X Fiche 50-329, 84 03/06, B403130482

- 8403190098 Advises that PBACK eliminated from weekly distribution of summary of inspector training & personnel form printouts QUAMME.D L Consumers Pawer Co 84703/06 BARANOW.S Stone & Webster. Inc 2pp 22669 302 24X Piche 50-329.84/03/06.
- 8403230114 Provides addl info on scope of work required to support turbine roll test milestone as part of const completion program implementation CMAMME.D L. Consumers Power Co. 84/03/06 HARRISON, J. Region 3. Office of Director 9pp. 22730 337 24% Fiche 50-329.64/03/06. 8402330114
- 8403140032 Forwards "Plan to Conduct Independent Mgt Appraisal of Midland Nuclear Project," by Cresap, McCormick & Paget Appraisal will examine util approach for completing plant Certificate of Syc encl Related correspondence COOK, J.W. Consumers Power Co. 84/03/07 KEPPLER, J.Q. Region 3, Office of Director App. 22603 129 24% Fiche 50-329,84/03/07,8403140032
- --8403140038 "Plan to Conduct Independent Mgt Appraisal of Midland Nuclear Project" * Cresap, HcCormick & Paget 84/03/07 73pp 22633 133 24X Fichs 50-329, 84/03/07,8403140032
- 8403130193 Authorizes util to proceed w/Phase I const completion activities for listed plant modules, per 840215 & 0305 requests Partial sys approved for Phase I activities located in module areas also listed HARRISON, J J Region 3, Office of Director 84/03/08 QUAPME, p. C. Consumers Power Co. 3pp. 22601 262 24X Fiche 50-329,84/03/08, page 21215
- --B403130168 Submits addlinfo on scope of work required to support turbine roll test milestone, per 840215 ltr Further definition of scope for seven Q-listed sys & description of const completion program process provided QUAMME.D L. Gonsumers Power Co. B4/03/06 HARRISON, J. J. Region 3, Office of Director. 9pp. 22601 267 24X Ficher SO-329, 84/03/08,8403130153
- 8403200027 Requests authorization to proceed per work authorization procedures to excavate Lag Zones Y3 & Z3, install brace struts E10.E11,N10 & Will-install temporary support brackets at E16 & W1 & remove unacceptable backefill & casing MONEY, J A Consumers Power Co 84/03/08 HARRISON, J J Region 3 Office of Director ip 22699 233 24x Fiche 30-329,84/03/08,8402200027
- 8403190180 Ack receipt of 840207 ltr indicating desire to discuss likely operation date Cost.generating capacity & extent to which costs attributable to reasons beyond control of licensee discussed KEPPLER.J O Region 3. Diffice of Director 84/03/09 BARAK, A J Michigan. State of 2pp 22671 144 24X Fiche 50-329.84/03/09, 8403190180
- --8403190186 Discusses 831028 ltr recommending deferring further Caseload Forecast Panel meetings Earliest completion date for Unit 2 not expected until months after Second Quarter 1986 & Unit 1 expected 6-9 months thereafter NOVAK,7 M Assistant Director for Licensing 83/12/20 COOK,J W Consumers Power Co 4pp 22671 146 24x Fiche 50-329,84/03/09,8403190180
- --8403190192 Notifies that util seeking ratemaking treatment for plant Engineering consultants hired to prepare testimony re operation datg.cost & generating capacity BARAK.A J Hichigan, State of 84/02/07 KEPPLER.J 0 Region 3. Office of Director 2pp 22671 150 24X Fiche 50-329.84/03/07, 8403190180
- B40320039 Requests authorization to proceed w/excavation & repair of frozen piping & excavation & installation load of redesigned E-17 MODNEY, J A Consumers Power Co 84/03/09 HARRISON, J J Region 3, Office of Director Ip 22698 315 24X Fiche 50-329,84/03/09,840320039
- 8403220025 Forwards 840305 memo re Unitsolved Questions 47 & 48 from Memo DEB 330-83 for PQCI C-1 60.Rev 7 PEAUDOIN.D E Consumers Power Co 84/03/12 FOTIADES, C. R Btone 8 Hebster, Inc 2pp 22717 180 24X Fiche. 30-329, 84/03/12; 8403220025
- 8402090041 Board Notification 84-050 provides Commission policy statement & proposed relembing on environ qualifications EISENHUT, D G Division of Licensing 84/03/14 Atomic Safety and Licensing Board Panel 10pp 24% Fiche 50-000,84/03/14,8402090041

- 8403200084 Authorizes listed critical remedial soils work activities for Mar 1984 HARRIBON, J. Region 3, Office of Director 84/03/14 QUAPHE, D. L. Consumers Power Co. 2pp. 22685 294 24X Fiche 50-329, 84/03/14, 8403200084
- 8403220202 Forwards complete responses to tracked info Items 08B,039 & tracked recommendation Item 060 re site auditing # Consumers Power Co B4/03/14 Stone & Webster, Inc 11pp 22718 090 24X Fiche 50-329.84/03/14.8403220202
- 8403220082 Authorizes listed remedial soils work activity for Nar 1984 HARRISON.J J Region 3. Office of Director 84/03/15 GUANNE.D L Consumers Power Co 2pp 22716 265 24% Fiche 50-329,84/03/15, 8403220082
- 8403220113 Forwards summary of independent design & const verification program 840313 meeting w/util & Govt Accountability Project in Bethesda MD LEVIN.H A TERA Corp 84/03/15 KEPPLER.J & Region 3, Office of Director COOK.J H Consumers Power Co EISENHUT.D 0, Division of Licensing 37pp 22716 226 24X Fiche 50~329.84/03/15,840322013
- 8403270009 Forwards listing of QA mgt audits for tracked info Item 052 # Consumers Power Co 84/03/15 Stone & Hebster, Inc 2pp 22769 353 24X Fiche 50-329.84/03/15.8403270009
- 8403270014 Forwards summary of quality verification program mgt review 830501 meeting.

 PALMER, B. Consumers Power Co. 84/03/19. Stone & Webster, Inc. 14pp. 22770-029. 24X Fiche 50-329,84/03/19,8403270014.
- 8403220100 Notifies of eighth independent design & const verification program 840329 meeting w/util.Isham.Lincoln & Beale.Govt Accountability Project & Midland Daily News to discuss status of confirmed items & Findings

 LEVIN.H A TERA Corp 84/03/20 KEPPLER.J W Region 3, Office of Director EISENHUT.D 0 Division of Licensing COOK.J W. Consumers Power Co 5pp 22715 179 24X Fiche 50-329.84/03/20, 8403220100
- B403270159 Notifies of eighth OCR status review meeting on 840328 w/ util, B&W & 8&W in Ann Arbor, MI to discuss confirmed items & findings of independent design const verification program Agenda encl
 LEVIN.H A TERA Corp 84/03/20 EISENHUT, D @ Division of Licensing KEPPLER, J @ Region 3, Office of Director, COOK, J W Consumers Power Co 5pp. 22769 197 24% Fiche 50-329,84/03/20,840370199
- B403300070 Forwards minutes of mgt review for const completion plan quality verification program 830429 meeting Agenda & supporting documentation encl PALMER, IL Consumers Fower Co 84/03/20 Stone & Webster, Inc. 46pp 22822 026 24X Fiche 50-329,84/03/20.8403300090
- 8403220007 Requests authorization to proceed w/work authorization Procedure 202550205, "Excavate Around Manhole 10" QUAMMED L. Consumers Power Co. 84/03/22 HARRISON, J.J. Region 3, Office of Director ip 22713 362 24X Fiche 50-329,84/03/22, 8403220007
- F Security, medical, emergency & fire protection plans
- 8402090006 Board Notification 84-034 forwards R Vollmer 840206 meso to D Eisenhut re fire research results concerning fires in electrical cabinets in control room EISENHUT, D G Division of Licensing, 84/02/23 PALLADING Commissioners 1p 22576 203 24% Fichs 50-000,84/02/23,8402090004
- --8403080316 Recommends that info re fire research results conterning fires in electrical cabinets in control room be submitted for board notification. per NRN Ofc Ltr 19, dtd 821001 Further evaluation of tast data required VCLLMER.R H Division of Engineering 84/02/06 EISENHUT.D 9 Division of Licensing 10pp 28376 204 24X Fiche 90-000.84/02/23,8402090006
- 8403120103 Natifies of 840323 workshop on fire protection safe shutdown requirements of 10CFR50. App R in Rosemont IL to discuss IE Info Notice 84-07 & provide add1 shutdown analyses &/or mod quidance. Agenda encl SPESSARD. R L Division of Emergency Preparedness & Operational Support 84/03/06 COOK. J W. Consumers Power Co. 3pp 22388 223 24X Fiche 50-329,84/03/06,8403120103

@ Adjudicatory correspondence

- 8403060093 Forwards list of audit repts dtd 840130-0202 Certificate of Svc encl Related correspondence BRUNNER, J E Consumers Power Co 84/02/29 BECHDEFER, C, HARBOUR, J, COMAN, F P Atomic Safety and Licensing Board Panel 4pp 22516 334 24% Fiche 50-329,84/02/29,8403060093
- 8403140119 Contention on Transamerica Delaval diesel generators re Model DSRV 12 Model cannot be relied upon to perform requisite safety function STAMIRE, B Stamifris, B 84/03/04 Atomic Safety and Licensing Board Panel 3pp 22624 201 24X Fishe 50-329,84/03/04,8403140119
- B403140075 Forwards DG Eisenhut 830810 ltr to BP Oarde,per 830921 commitment W/o encl
 HASSELL,D F Hearing Branch 1 84/03/05 BECHHOEFER,C .
 COMAN,F P . HARBOUR.J Atomic Bafety and Licensing Board Panel
 2pp 22633 081 24X Fiche 50-329,84/03/05,8403140075
- B403140154 Forwards summaries of B20202-05 meeting & audit re auxiliary building underpinning. B20316-19 meeting & audit re soils remedial action & B31004-07 audit & meeting re HVAC sys WILCOVE, M N Hearing Branch 2 B4/03/05 BERNABEI, L Government Accountability Project 2pp 22621 361 24X Piche 50-329, 84/03/05, B403140154
- 8403150003 Forwards svc water pump structure crack survey rept Concurrence on mods to crack mapping program requested Details will be discussed at 840404 meeting Certificate of Bvc encl Related correspondence HOONEY, J.A., Consumers Power Co. 84/03/05 HARRIBON, J.J. Region 3, Office of Director 30pp 22824 116 24X Fiche 50-329,84/03/05,8403150003
- 8403120039 Advises that entire fireline excavation backfilled after physical connections made to restore fire svc to portions of site Svc list encl Related correspondence BRUNNER, J E Carolina Power & Light Co 84/03/07 BECHHOEFER, C. COMAN, F.P., HARBOUR, J. Atomic Safety and Licensing Board Panel 3pp 22589 271 24X Fiche 50-329,84/03/07,8403120039
- 8403130114 Order revising schedules for submittal of proposed findings & conclusions on GA/mgt attitude issues ASLB may issue separate partial initial decision on certain issues not encompassed by proposed findings on issues
 BECHHOEFER.C Atomic Safety and Licensing Board Panel 84/03/12
 2pp 22415 295 24X Fiche 50-329.84/03/12,8403130114
- 8403190166 Forwards Bechtel quality action rept supporting D Lewis testimony re buried control room pressurization pipe Conrosion caused by stray welding currents not item of concern. Svc list encl Related correspondence BRUNNER, J E Consumers Power Co 84/03/12 BECHHOEFER, C, HARBOUR, J, COMAN. F P Atomic Safety and Licensing Board Panel 7pp 22669 184 24X Fiche 50-329,84/03/12,8403190166
- 8403230031 Requests approval for release of insplactivity per NRC rework disposition regardless of position of module action item Related correspondence guamme. D L Consumers Power Co DSB 072 84/03/13 HARRISON. J Region 3. Office of Director 3pp 22724 335 24X Fichs 50-329.84/03/13.8403230031
- 8403200011 Proposes to defer response to Stamiris OL contention re Transamerica Delaval diesel generators until after receiving Stamiris Itr in support of timeliness of contention Proof of Svc encl OILGMEN, BR Isham, Lincoln & Beale GILDMEN, BR Consumers Power Co 84/03/15 BECHMOEFER, C Atomic Safety and Licensing Board Panel 3pp 22683 358 24X Fiche 50-329, 84/03/15,8403200011
- 8403200139 Addendum to Stamiris contention on Transamerica Delaval, Inc diesel generators addressing late filing factors of 10CFR2 714. 8TAMIRIB, B Stamiris, B 84/03/15 Commissioners 2pp 22699:156 24X Fiche 50-329,84/03/15,8403200139
- 8403270020 Proposes to defer response to Stamiris 840304 contention re Transamerice Delaval diesel generators Proof of Svc encl OlloMEN.B R Isham Lincoln & Beals GILOMEN.B R Consumers Power Co DSB ilo 84703/15 BECHMOEFER.C Atomic Bafety and Licensing Board Panel. 3pp 22766 360 24X Fiche 50-329.84/03/15,8403270020
- 8403220246 Order setting time for responses to 8 Stamiris 840304 motion as if 840315 addendum was original filing data Served on 840322.

 BECHHOEFER, C Atomic Safety and Licensing Board Panel DSS 039 84703/21. Office of the Executive Legal Director 2pp 22719 049, 24% Fichs 50-329,84/03/21,8403220246

8403280348 Order extending time until 840425 for Commission to act to review Director's Decisions DD-83-15 & DD-84-2 Served on 840328 GRILK-5 J Office of the Secretary of the Commission DSB 158 84/03/27 Commissioners 1p 22787 143 24X Fiche 50-329,84/03/27.8403280348

I Financial information

- 8403190071 Annual Financial Rept for 1983 W/840312 ltr SELBY.J D Consumers Power Co 83/12/31 34pp 22666 136 24X Fiche 50-000.83/12/31.8403190071
- O Inspection reports. IE Bulletins & correspondence
- 8401230630 Partial response to FOIA request for IE 800103 rept re review of mat1 false statement at facilities, associated & supporting records to rept & repts prepared in response. Forwards App A documents Review of add1 records in progress FELTON, J M Division of Rules and Records 83/11/01 WINSLOW, R Wall Street Journal 2pp 21705 337 24X Fiche 50-329,83/11/01,8401230630
- B403070229 Partial response to FOIA request for repts re NRC investigation of failure of reactor vessel holddown studs on Unit I reactor vessel FOFOWARD App A & B documents FELTON.J M Division of Rules and Records 84/02/23 PLATO, E D Kohl, Søcrest, Wardle, Lynch, Clark & Hampton 6pp 22364 149 24% Fiche 50-329,84/02/23,8403070229
- --8403070343 Forwards IE Insp Repts 50-329/80-12 & 50-330/80-13 on B00301-31 No noncompliance noted Major areas inspected exam of procedures & representative records observations & interviews w/personnel W/o enc! FIORELLI, 9 Region 3, Chicago, Office of the Director 80/05/19 HOMELLI, 9 H. Consumers Power Co. 2pp. 22564 170 24X Fiche 50-329, 84/02/23, 8403070229
- ~~8403070351 Responds to 830901 ltr & forwards IE Investigation Repts 50-329/80-13 & 50-330/80-14 W/o encl LEWIS.8 H Region 3. Office of Director 83/09/20 MYERB.T F Garan. Lucow, Miller, Seward, Cooper & Becker Ip 22544 263 24X Fiche 50-329.84/02/23.8403070229
- 8401190072 IE Info Notice 84-13, "Povential Deficiency in Motor Operated Volve Control Circuits & Annunciation " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22907 239 24X Fiche 50-000.84/02/28,8401190072
- 8403130297 Advises that const implementation overview performed sampling insp of const training records for personnel Results satisfactory KARR.J E Stone & Webster, Inc 84/02/29 GUAMME.D L Consumer: Power Co Ip 22617 233 24X Fiche 50-329,84/02/29,8403130297
- 8403060385 Forwards IE Monthly Meeting Repts 50-329/84-05 & 50-330/84-05 on 840209 MARNICK.R.F Region 3. Office of Director 64/03/01 COOK.J W Consumers Power Co 2pp 22507 004 24X Fiche 50-329.84/03/01.8403040385
- --B403060378 IE Monthly Meeting Repts 50-327/84-05 & 50-330/84-05 on 840209 Major topics discussed crack mapping, EPA jacking loads & US Testing audit corrective action status GARDNER, R N , HARRISON, J J Region 3, Office of Director 84/02/29 5pp 22507 006 24X Fiche 50-327.84/03/01.8403060365
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE, J N Division of GA, Safeguards & Inspection Programs (Fost 830103) B4/03/02 Consolidated Edison Go of New York, Inc 130pp 22552 329 24X Fiche 50-000.84/03/02.8408090007
- 8402090008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Syc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 122pp 22553 098 24X Fiche 50-000.84/03/02.8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases " 8vc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 119pp 22553 217 24X Fiche 50-000.84/03/02.8402090009

- 8403060288 Authorizes util to jack Piers CT1 & CT12 as long as auxiliary bldg differential movement controlled according to 840104 agreement documented in IE Insp Repts 50-329/84-01 & 50-330/84-01 HARRISON J J Region 3, Office of Director 84/03/02 QUAMME, D L Consumers Power Co 1p 22519 149 24X Fiche 50-329, 84/03/02, 84003/0399
- 8403130254 Forwards RC Sember 840223 memo re MPOAD insp evaluation & Overingp Audit MSA-84-6 VOKAL, D J Consumers Power Co 84/03/02 Stone & Webster, Inc 2pp 22606 054 24% Fiche 50-329,84/03/02,8403130254
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Coaling Components Below Nil Ductility Temp " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8402090024 IE Info Notice 84-09, Rev I, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc. 118pp 22635-049 24X Fiche 50-000,84/03/07,8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PMR Sys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc. 1
- 8402070031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Syc list encl DEYOUNG, R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24x Fishe 50-000.84/03/12.8402090031
- 8403220016 Submits summary of Bechtel investigation & corrective actions to resolve issue of monconforming matl supplied by Tube-Line Corp. in response to IE Bulletin 83-06 Final response espected by 840615
 CDOK.J W. Consumers Pawer Co. 84/03/12 KEPPLER.J O. Region 3. Office of Director 2pp. 22712 339 24X Fiche 50-329.84/03/12.
- 8403270177 Submits resolutions to concerns addressed in 840110 ltr re hanger reinsp grogram Computer listing of hangers evaluated against commodity list to determine base number of hangers in program submitted GUAMME. D L Consumers Power Co 84/03/15 KARR. J E Stone & Hobster, Inc. 2pp 22770 271 24X Fiche 50-329.84/03/15.
- B402090043 IE lnfo Natice B4-19, "Two Events involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Past B30103) B4/03/21 Consolidated Edison Co of New York, Inc 123pp 22623 227 24% Fiche 50-000,84/03/21,8402090043
- 8402070044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc. 135pp 22733 001 24X Fiche 50-000,84/03/21,8402070044
- R Periodic operating reports & related correspondence
- 9403020443 Forwards monthly status rept of offsite emergency preparedness for OL reviews for Jan 1984 Changes in FCMA finding dates not caused by delay due to offsite emergency planning issues
 DIRCKS.W J Offsice of the Executive Director for Operations 84/02/21 PALLADINO Commissioners 9pp 22492 083 24X Fiche 90-000.84/02/21.8403020443
- 8403070008 Forwards monthly rept for Jan 1984, per ALAB-106, including Bachtel nonconformance rept. Bechtel FSO nonconformance rept. Bechtel quality action requests, Bechtel mgt corrective action repts bechtel GA findings. CDCK, J W Consumers Power Co 84/02/25 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 2530pp 22529 010 24X Fichs 50-329, 84/02/25, 8403070008
- 8403220013 Forwards monthly status rept for Feb 1984 Monthly OCR/finding status review meeting scheduled for 840328 in Ann Arbor.MI LEVIN.H A TERA Corp 84/03/16 EISENHUT, D O Division of Licensing KEPPLER.J & Region 3. Office of Director COOK, J W Consumers Power Co 3pp 22713 285 24X Fiche 50-329, 84/03/16, 840322013

- --B403220022 "Midland Independent Design & Const Verification Programmenthly Status Rept Number 10 for Feb 1984 "
 DQUOHERTY: FA TERA Corp 84/03/16 54pp 22713 288 24X
 Fiche 50-329, 84/03/16, 8403220013
- 8403270062 Forwards "Const Implementation Overview (CIO)," Waekly Rept 39 for 840305-09 KARR, J E Stone & Webster, Inc 84/03/16 KEPPLER, J G Region 3, Office of Director 17pp 22766 088 24% Fiche 50-329,84/03/16, B403270062
- 8403230043 Forwards monthly status rept for Midland project for Feb 1984 WARNICK,R F Region 3, Office of Director 84/03/19 KEPPLER,J 0 Region 3, Office of Director 1p 22728 351 24X Fiche 50-329,84/03/19,8403230043
- ---8403230046 Forwards monthly status rept for Midland project for Feb 1984 COOK.R J Region 3. Office of Director 84/03/15 WARNICK.R F Region 3. Office of Director 2pp 22728 352 24X Fiche 50-329,84/03/19.8403230043
- S Reportable occurrences. LERs & related correspondence
- 8401230630 Partial response to FOIA request for IE 800103 rept re review of matl false statement at facilities, associated & supporting records to rept & repts prepared in response Forwards App A documents Review of addl records in progress FELTON.J M Division of Rules and Records 83/11/01 WINSLOW.R. Wall Street Journal 2pp 21905 337 24X Fiche 50-329,83/11/01.
- --8401230660 PNO-79-039 pn 790305 investigation concluded that QA pregras for obtaining proper soil compaction of facility deficient excessive settlement observed widesel generator bldg & incorrect info re soil foundation contained in FSAR SHEWHAKER, R E. HENDERSON, J B. THORNBURG, H D. Office of Inspection & Enforcement, Office of the Director 79/03/06 2pp 21905 352 24X Fiche 50-329,83/11/01,8401230630
- B403010451 Informs Commission of problems w/emergency diesel generators mfg by Transamerica Delaval. Inc DIRCKS.W J Office of the Executive Director for Operations SECY-83-034 84/01/25 App 22438 347 24X Fiche 30-000.84/01/23.8403010451
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines.08mpel NPS-4 T&T valve to close Encl ltr dtd 840203 sent to listed utils GE notified of affected units in BHR plants
 THERDUX.R R Terry Corp 84/02/22 WOODRUFF.R W Director's Office. Office of Inspection and Enforcement 6pp 22706 327 24% Fiche 50-000.84/02/22.8403210032
- 8403060269 Interim deficiency rept re nonconservative design of embedments in concrete using shear lugs located in tension zones Next rept expected by 840601 COOK.J W Consumers Power Co 84/02/24 KEPPLER.J G Region 3, Office of Director App 22515 201 24X Fiche 50-327,84/02/23.8403060269
- 8403070229 Partial response to FOIA request for repts re NRC investigation of failure of reactor vessel holddown studs on Unit I reactor vessel Forwards App A & B documents FELTON, JM Division of Rules and Records 84/02/23 PLATO, E D Kohl, Becrest, Wardle, Lynch, Clark & Hampton 6pp 22564, 149 241 Fiche 50~329,84/02/23,8403070229
- --B403070343 Recommends order be issued to util requiring action to correct unacceptable anchor bolts at facility Draft ltr & order enci
 KEPPLER.J O Region 3, Chicago, Office of the Director
 THOMPSGN.D Executive Officer for Operations Support. 36pp
 22564 172 24X Fiche 50-329,84/02/23,8403070229
- 8403060104 Interim deficiency rept re B&W steam generator auxiliary feedwater header design change Unit 2 changes should be completed by 840227 Work on Unit 1 suspended due to delays in startup dates
 CODK, J W Consumers Power Co 84/02/24 KEPPLER, J O Region 3. Office of Director 3pp 22517 015 24% Fiche 50-329,84/02/24, 8403060104
- BAD30A0272 interim deficiency rept re nonconforming electrical receway sys Adverse effect of deficiencies on safety of plant operation unlikely Bechtel revised final Rept MCAR 70 encl Next rept will be submitted by 840608 CDDK.J W Consumers Power Co B4/02/24 KEPPLER.J O Region 3. Office of Director 7pp 22517 066 24X Fiche 50-329.84/02/24. BAD30A0272

- 8403060411 Forwards signed affidavit & resume of Z Zirak assigned to const implementation overview staff MARR.J E Stone & Webster. Inc. 84/02/24 HARRISON, J J Region 3. Office of Director Spp. 22511 347 24X Fiche 50-329,84/02/24.
- B403080026 Forwards rept on 840210 exit meeting w/Bechtel & NRC re indiscriminate cable substitutions * Consumers Power Co. 84/02/24 Stone & Webster Engineering Corp 3pp 2259 243 24X Fiche 50-329,84/02/24,8403080026
- B403010207 Forwards "Investigation of Types AF & AE Piston Skirts." per Transamerica Delaval Inc Guners Group program commitments Rept evaluates cracks in AF piston skirts in Shoreham & Grand Gulf Nuclear Power Stations MUSELER.W. J. TDI (Transamerica Delaval, Inc.) Owners Group B4/02/27 DENTON.H R. Office of Nuclear Reactor Regulation, Birector 3pp 22434 090 24% Fiche 50-000.84/02/27,8403010207
- 8403060426 Forwards Figures 8-8 & 8-9 inedvertently omitted from 840208 response to NRC 840104-06 audit questions re auxiliary bldg response to NRC GAUTON-OB addit questions re addition plug underpinning MDQNEV.J A Consumers Power Co 84/02/27 HARRISON.J J Region 3. Office of Director 6pp 22518 194 24X Fiche 50-320.84/02/27, 8403060426
- 8403080245 Confirms that listing of open nonconformance repts.sorted by issue date.given to D Brown on 840221 GUANNE, D L. Consumers Power Co 84/02/27 BARANOW, S Stone & Webster, Inc 3pp 22561 006 24X Fichs 50-329, 84/02/27, 840:1080245
- 8403130074 Forwards closed Nonconformance Identification Rept NIR-018 rs training record discrepancies not in compliance w/requirements of FPG-2 000/Rev 7, "Training of Const RARR.J E Stone & Webster, Inc. 84/02/27 QUAMME.D L Consume Power Co 3pp 22615 219 24X Fiche 50-329,84/02/27,8403130074 Consumers
- B402090021 Board Notification B4-039 discusses NRC 840210 & 16 meetings W/Transamerica Delaval, Inc Emergency Diesel Generators
 W/Transamerica Delaval, Inc Emergency Diesel Generators
 Dunners Group Meeting scheduled on 840308 for finalization of
 generic program plan prior to NRC review
 EIBENHUT, D Q Division of Licensing 84/02/28 PALLADING,
 GILINSKY, ROBERTS Commissioners 5pp 22546 003 24X
 Fichar 50-000 84/02/28 8402090021
- 8403010218 Forwards task descriptions for 16 known problems re 903010218 Forwards task descriptions for 10 known problems re Transamerica Delaval, inc. emergency diesel generators MUSELER,W J TDI (Transamerica Delaval, Inc.) Owners Group 84/02/28 DENTON,H R Office of Nuclear Reactor Regulation, Director 42pp 22405 177 24% Fiche 50-000,84/02/28,8403010218
- 8403080171 Forwards requested list of items determined to be ready for raview & closure by NRC Items marked by asterisk reviewed by Region III inspectors & will be removed from list when closed in insp rept CGDKJ W Cansumers Power Co 84/02/28 KEPPLER, J G Region 3, Office of Director 16pp 22559 298 24X Fiche 50-329,84/02/28,
- 8403080187 Forwards response to Tracked Info Item 054 requesting MTC GA manuel, quality plan program manuel, procedures & target list utilized at site & walkdown summaries issued to date * Consumers Power Co 84/02/28 Stone & Webster, Inc 2pp 22559-112 24X Fiche 50-329,84/02/28,8403080187
- 8403080172 Advises that sampling insps of const training records of personnel complete Results of insp satisfactory & NIR-018 closed.Personnel listed on encls cleared to perform status assessment W/o encl MARRIJ.E Stone & Webster, Inc 84/02/28 GUAMME,D L Consum-Pawer Co :p 22559 201 24X Fiche 50-329,84/02/28,8403080192
- 8403080235 Lists audit finding repts, including MSA-83-7-04F, 01F & M01-603-03-02 * Consumers Power Co 84/02/28 Stone & Wabster, Inc 1p 22560:124 24X Fiche. 50-329:84/02/28,8403080235
- 8403130173 Forwards closed const implementation overview. Item 035 re dielectric isolation spacers for galvanic protection of copper pipe to galvanized steel pipe supports missing in
- 8402090020 Board Notification 84-044 forwards Part 21 rept re Transamerica Delaval. Inc turbocharger thrust bearing lubrication defect resulting in engine nonavailability EISCHNUT.D O Division of Licensing 84/02/29 PALLADING Commissioners 4pp 28341 263 24X Fiche 50-000,84/02/29. B402090020

- 8403080221 Forwards Nonconformance Identification Rept 019 On 840222. field deviation disposition list not revised to reflect changes for Specs M-1A & C-304
 KARR, J E Stone & Webster, Inc 84/02/29 GUAMME, D L Consumer Power Co 2pp 22560 022 24x Fiche 50-329 84/02/29,8403080221
- 8403080247 Forwards complete response to Const Implementation Overview Item 056 re inconsistencies noted during evaluation of training for PGCI C-1 50 * Consumors Pauer Co 84/02/29 Stone & Webster, Inc 4pp 22561 019 24X Fiche 50-329,84/02/29,8403080247
- 8403080250 Forwards closed Const Implementation Overview Item 054 re Mark Tochnologies Corp & & Quality program plan manuals, procedures & target list KARR.JE Stone & Webster, Inc. 84/02/29 GUAMME, D. L. Consumer Power Co. 3pp. 22561-014 24X Fiche 50-329, 84/02/29, 8403080250
- 8403080259 Forwards complete response to Const Implementation Overview Item 097 re trainer evaluation * Consumers Power Co 84/02/29 Stone & Webster, Inc 4pp 22557 ii3 24X Fichs 50-329,84/02/29,8403080259
- 8403130210 Forwards closed GAR RT-00021 which provides complete response to Nonconformance Identification Rept NIR-008 retraining matrix

 * Consumers Power Co 84/02/29 Stone & Webster, Inc
- * Consumers Power Co 84/02/29 Stone & Webster, Inc 6pp 22605 057 24X Fiche 50-329,84/02/29,8403130210
- noscopulato Forwards IE Monthly Meeting Repts 50-329/84-05 & 50-330/84-05 on 840209 WARNICK:R F Region 3, Office of Director 84/03/01 CODK, J W Consumers Power Co 2pp 22507 004 24x Fiche 50-329,84/03/01,8403060385 8403060385 Forwards IE Monthly Meeting Repts 50-329/84-05 &
- --B403060407 Forwards minutes of Feb 1984 monthly third-party assessment meeting re underpinning & remedial soils work LUCKB.A S Stone & Webster, Inc 84/02/21 HARRISON,J J Region 3, Office of Director 21pp 22507 011 24X Fiche 50-329,84/03/01,8403040385
- --8403060415 Forwards Independent Assessment of Underpinning Weekly Rept 48 for 840101-07 LUCKB.A S Stone & Webster, Inc 84/02/32 CODK,R NRC - No Detailed Affiliation given 11pp 22507 032 24X Fiche 50-329,84/03/01,8403060385
- $^{--84030\pm0420}$ Forwards Independent Assessment of Underginning Weekly Rept $49~\mathrm{for}~840108{^-14}$ AY 100 840108-14 LUCKS.A 8 Stone & Webster, Inc 84/01/17 CDOK,R NRC - No Detailed Affiliation Given 15pp 22507 043 24X Fiche 50-329,84/03/01,8403060385
- ---8403060423 Forwards Independent Assessment of Underpinning Weekly Rept 103064423 Formaros Independent Assessment or 70 for 840115-21 LUCKB.A S Stone & Webster, Inc 84/01/25 Detailed Affiliabion Olven 14pp 22507 05 Fiche 50-329,84/03/01.8403060385 inc 84/01/25 COOX,R NRC - No 14pp 22507 058 24Y 0385
- --8403060428 Forwards Independent Assessment of Underpinning Weekly Rept 71 for 840122-28
 LUCKB.A S Stone & Webster, Inc. 84/02/02 CDDM, R NRC - No Detailed Affiliation Given 16pp 22507 072 24x
 Fiche 50-327, 84/03/01.8403060385
- -8403060442 Forwards Const Implementation Overview Weekly Rept 31 for 840109-13 KARR J E Stane & Webster, Inc 84/01/18 K 3. Office of Director 17pp 22307 100 24X Fiche 50-329,84/03/01.8403040385 KEPPLER, J G Region
- --9403060444 Forwards Const Implementation Overview Weekly Rept 32 for 840116-20 KARR, J E Stone & Webster, Inc 84/01/27 KEPPLER, J G Region 3, Office of Director 20pp 22507 117 24X Fiche 30-329, 84/03/01, 8403060385
- --8403060445 Forwards Const Implementation Overview Weekly Rept 33 for 840123-27 KARR, J E Stone & Webster, Inc 84/02/01, KEPPLER, J G Region 3. Office of Director 17pp 22507 137 24X Fichs 50-329, 84/03/01,8403060385
- 8403130195 Forwards closed const implementation over: training classes
 KARR.J E Stone & Webster: Inc 84/03/01 QUAMME.
 Power Co 5pp 22617 307 24X Fiche 50-329.84/03

- 1080222 Interim deficiency rept to Coordination of engineering holds restrictions resulting in installation of unqualified sex cables Caples will be replaced interim or final rept spected by 840504 DEK.J W Consumers Power Co. 84/03/02 KEPPLEA.J G Region 3. fice of Director App. 22561-025 24X Fiche 30-329,84/03/02.
- 3130050 Forwards closed Audit Finding Repts MSA-83-25-02F, SA-83-25-10F & MSA-83-25-03F & closed Unresolved Item Repts SA-83-25-09V & MSA-83-25-07V OKAL, D.J. Consumers Power Co. 84/03/02 Stone & W. 20a 22608 094 24x Fiche 50-329, 84/03/02, 8403130050 Stone & Webster, Inc.
- 3130184 Forwards Nonconformance Identification Rept 020 re unsigned hange request forms ARR, J E Stone & Nebster, Inc. 84/03/02 GUAMME.D L Consumers ower Co 2pp. 22617 234 24X Fiche 50~329,84/03/02,8403130184
- 3130292 Forwards Audit Rept MSA-83-37 W/o encl /OKAL,D J Consumers Power Co 84/03/02 Stone & Webster, Inc p 22614 149 24X Fiche 50-329,84/03/02,8403130292
- 33130321 Forwards Const Implementation Overview Hold Point J3130321 Forwards Const Implementation DVFTVIEW Hold Haint Additionstion Item OSI re-subconfract document controls for action Recommends form be revised to provide signature & date space for recipient (ARR.) E Stone & Webster, Inc. 84/03/02 QUAMME.D t. Consume four Co. 2pp. 22414 130 24X Fiche, 50-329, 84/03/02, 8403130321
- O3i4004B Forwards "Grand Oulf Congonent Tracking Sys." "Shoreham Component Tracking Sys." & "Transamerica Delaval. Inc.
 Diess! Opporators Unners Group Program Plan: " to resolve concerns w/emergency diesel generators
 MUSELER.W J. Long Island Lighting Co. 84/03/02 DENTON, H.R.
 Office of Nuclear Reactor Regulation. Director Spp. 22626 062
 24X Fiche 50-000.84/03/02.8403140048
- 8403140095 "Transamerica Delaval, Inc Diesel Generators Duners Group
 - #03140075 "Transamerica Delaval. Inc) Umners Group 84/03/02 # TDI (Transamerica Delaval. Inc) Umners Group 84/03/02 261pp 22628 223 24% Fiche 50-000.84/03/02.8403140048
- 103130161 Forwards, for info.closed Guality Action Request GAR-RY-00020 used to track const implementation overview Nonconformance Identification Rept NIR-007

 **Conswmers Power to 84/03/05 Stone & Webster, Inc 10pp 22579 278 24X Fiche 50-327,84/03/05,8403130161
- 403130362 Forwards partial response to Tracked Action Item 043, consisting of pre- & post-stop work order activities.DDR implementation, site-wide distribution plan implementation schedule & corrective action plan W/o encls
 REICHEL.N I Consumers Power Co 84/03/05 Stone & Webster, Inc. 1p 22616 269 24% Fiche 50-329.84/03/05.8403130362
- 403130479 Forwards Const Implementation Overview Item 048 re inconsistency between spec requirements on spacing between anchor bolts of different diameters Bechtel preparing spec
- change notice KARR, J E St Change Notice
 KARR, J E Stone & Webster, Inc 84/03/05 KEPPLER, J G NRC - |
 Detailed Affiliation Given GUAMME, D L , REIGHEL, N I Consumers
 Pawer Co 3pp 22613 228 24% Fiche 50-329,84/03/05,8403130479
- 1403130238 Forwards Const Implementation Overview Item 062 re training classes Status assessment performed on pipe supports by personnel wincompiete required training XARR. J E Stone & Webster, Inc. 64/03/06 KEPPLER. J G Region 3. Defice of Director 3pp 22606 057 24X Fiche 50-029,84/03/06. 8403130238
- 8403130354 Forwards completed response to Tracked Action Item 048 consisting of Spec Change Notice 14001 to Spec C-306 re grouted anchor bolts REICHELIN I Consumers Power Co 84/03/06 Stone & Webster.
- rouses spenor polis ECKEL, N I Consumers Power Co 84/03/06 Stone & Webster, Inc 4pp 22616 330 24% Fiche 50-329,84/03/06,8403i30354
- 8403130491 Requests extension to 840309 for responding to Tracked Info Items 058 to 059 to Tracked Recommendation Item 060 REICHEL.N I Consumers Power Co 84/03/06 Stone t Webster, Inc 1p 22613 180 24K Fiche 50-329.84/03/06.8403130491
- 8402070033 Board Notification 84-047 forwards Transamerica Delayal, Inc Dwners Group piston skirt rept & task descriptions EISEMHUT, D 0 Division of Licensing 84/03/07. PALLADING, OILINSKY, ROBERTS Commissioners 4pp 22674 221 24X Fiche 50-000,84/03/07,8402070033

- 8403130271 Informs that response to Nunconformance Insp Rept 008 satisfactory Const implementation overview will continue to monitor training commitments w/emphasis on listed areas KARR. J.E. Stone & Webster: Inc. 84/03/07 (UMAMME.D.L. Consum Power Co. 1p. 22614 175 24X Fiche 50-329, 84/03/07, 8403130271
- 9403140122 Part 21 rept re status update concerning abnormal wear on linear converters Test program underway Results of investigation indicate excessive wear caused by hunting of control circuitry
 DDDSON, J P Pacific Air Products Co 84/03/09 DDDBON, J. Pacific Air Products Co 64/03/0 Office, Office of Inspection and Enforcement Fiche 50-900,84/03/09.8403140122
- B403220072 Forwards listed documentation re-post-weld heat treat thermocouples Bechtel in contact w/suppliers to obtain replacements W/o encl # Consumars Power Co B4/03/09 BMITH. A Stone & Webster, Inc ip 82718 310 24% Fiche 50-329,84/03/09,8403220072
- 8402070038 Reard Notification 84-051 forwards "Transamerica Delaval Inc (TDI) Diesel Generators Owners Group Program Plan " EISENHUTI O Division of Licensing B4/03/12 PALLADINO, GILINSKY, ROBERTS Commissioners Spp 22688 214. 24% Fiche, 50-000, 84/03/12, 8402090038
- 8402090039 Board Notification 84-082 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delayal, Inc. (TDI) Owners Group Distribution Transamerica Delaval, Inc. (IDI) Commission Commission
- ~8403060536 Forwards summary of 840210 meeting w/Transamerica Delaval,
 Inc Owners Group in Bethasda.MD re problems w/emergency
 diesel generators
 CARUSO.R Licensing Branch 2 84/02/27 D'REILLY, J P. NRC No
 Detailed Affiliation Given App 22708 006 24X
 Fiche 50-000,84/03/12,8402090039
- ~-BA03060554 Transcript of 840210 meeting u/Transamerica Delaval, Inc Owners Group in Bethrada: MD re problems u/emergency dissel generators * NRC ~ No Datailed Affiliation Given 64/02/10 147pp 22708 012 24X Fiche 50~000.84/03/12.8402090039
- ~-B403070409 Bummary of B40216 meeting w/Transamerica Delaval Inc Dwners Group in Wading River.NY re program plan to establish reliability of diesel generators Agenda.meeting transcript & attendance list encl MILLER.H A Licensing Branch 4 84/02/27 Licensing Branch 4 Bpp 22708 161 24X Fiche S0~000.84/03/12,8402070039.
- --8403070423 Transcript of 840216 conference in Wading River, Ny re Transamerica Delaval, Inc diesel generators, Pp 1-82 * Commissioners 84/02/16 84pp 22708 169 24X Fichs 50-000, 84/03/12, 8402090039
- 8403140050 Forwards "Design Review of Connecting Rod Bearing Shells for Transamerica Delaval Enterprise Engines" for Shoreham & Grand Gulf diesel generators MUSELER, W.J. Long Island Lighting Co. 84/03/12 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp 22602:074 24X Fiche 50~000,84/03/12.8403140050
- 8403150133 Forwards "Transamerica Delavol, Inc Diesel Generator Rocker Arm Capscrew Stress Analysis Rept " Capscrew design adequate for applicable engines & svc conditions MUSELER, W J TDI (Transamerica Delaval, Inc.) Gwhers Oroup 64/03/13 DENTON, H R Diffice of Nuclear Reactor Regulation, Director 2pp 22639 270 24% Fiche 50-000, 84/03/13, 8403150133
- 84032/0169 Forwards, for info, Quality Action Requests (GARs) RA-00134 & RA-00135 to assign action & track const implementation overview (CIO) WIRS 019 & 020 on MPGAD GUAIL sys CIO will evaluate satisfactorily closed out GARs to close out NIRS * Consumers Power Co 84/03/14. Stone & Webster, Inc 6pp 22771 138 24X Fiche 50-329, 84/03/14, 8403270169
- 8403270023 Informs that all G redline drawings incorporated, per Hold Point COI.Rept 6.

 * Consumers Power Co 84/03/15 Stone & Webster, Inc 2pp 22770 069 24X Fiche 50-329, 84/03/15, 8403270023.
- 8403270029 Forwards response to Tracked Info Item 055 re training matrix status assessment requirements

 # Consumers Power Co 84/03/15 Stone & Webster, Inc 11pp, 22769, 328 24X Fiche 50-329, 84/03/15, 8403270029.

- 8403270227 Forwards open Const Implementation Overview Item 063 re status assessment in Module 1200 on 840313 using unmarked FBK prints KARR, J E Stone & Webster, Inc 84/03/15 KEPPLER, J G NRC No Detailed Affiliation Givan REICHEL, N I : WELLS, R A Consumers Power Co 3pp 22772 081 24X Fichs 50-329, 84/03/15, 8403270227
- 8403200222 Responds to 840214 Requests for Info 1 & 2 re R-4 series engines List indicating engine number, model & svc number, customer name & address, rating, date shipped & date started MATHEMS.C S Transamerica Delaval, Inc 84/03/16 EISENHUT, D G Division of Licensing 20pp 22691 179 24X Fiche 50-000,84/03/16. 8403200222
- 8403220067 Interim deficiency rept re low alloy quenched & tempered bolting 1 5-inches & greater in support of mafety-related sys Current status of Bechtel matl evaluation encl Next rept will be sent by 840727 CODK.J W Consumers Power Co 84/03/16 KEPPLER, J & Region 3. Office of Director 10pp 22716 130 24X Fiche 50-329.84/03/16,8403220067
- B403220108 Interim deficiency rept re defective capstan springs in mechanical shock arrestors supplied by Pacific Scientific Arrestors being evaluated & tested Next rept by B40504 (CODK.), W Consumers Power Co. 84/03/16 KEPPLER, J. G. Region 3, Office of Director 17pp 22716 180 24X Fiche 50-329.84/03/16, 24003/16. 8403220108
- 8403270042 Forwards "Const Implementation Overview (CIO)." Heekly Rept 37 for 840305-09 KARR,J E Stone & Webster, Inc 84/03/16 KEPPLER,J 9 Region Office of Director 17pp 22766 088 24X Fiche 50-329,84/03/16, Region 3,
- 8403270096 Forwards const implementation overview for Items 064.065 & 066 re CW-1 00. "E-Beries" POCI's.Zack Procedure MB-FP-7C & Zack Procedure MB-FP-18 Welding insp requirements deleted & spec change notice recommended KARR, J.E. Stone & Hebster, Inc. 84/03/16 KEPPLER, J.G. NRC - No. Detailed Affiliation Given REICHEL, N.I. Consumers Power Co. GUAHME, D.L. Stone & Webster, Inc. 4pp. 22766 356 24X Fiche 50-329,84/03/16.8403270096
- 8403270093 Forwards Closed Const Implementation Overview Item 056/Hold Point Notification re Checklist MP-MIG-008E-0001 Review of items re impact on training requested KARR.J E Btone & Webster, Inc. 84/03/19 KEPPLER.J Q NRC No Detailed Affiliation Given REICHEL.N I . QUAMME.D i. Consumers Power Co. 5pp. 22769 358 24X Fiche 50-329,84/03/19,8403270093
- B403270236 Forwards DF Ronk B40315 memo to JT Christy & attachments showing planned weekly manhour allocations for PGCI & areas for wks of B40323:30 & 0406 W/o encl RDNK,D F Consumers Power Co B4703/19 BAUMGARTNER,T Btone & Habster, Inc. 1p 22771 347 24X Fiche 50-329.84/03/19.8403270236
- 8403300006 Forwards Closed Const Implementation Overview Item 052 re Criterion XVIII site auditing
 KARR, J E Stone & Webster, Inc 84/03/20 KEPPLER, J 9 NRC - ND
 Detailed Affiliation Given QUAMME, D L , REIGHEL, N I Consumers
 Power Co 3pp 22822 126 24X Fiche 50-327, B4/03/20, B403300006
- 8403300035 Forwards proposed project records classification code list & mgt policy for review.

 KARR.J E Btone & Webster Engineering Corp 84/03/20 GUAMME.D L.

 Consumers Power Co Spp. 28921 312 24X Fiche 50-329.84/03/20 8403300035
- 8403270132 Forwards "Emergency Diesel Generator Air Start Valve Capscrew Dimension & Stress Analysis," prepared by S&W for Transamerica Delaval, Inc (TDI) Diesel Generator Owners Oroup. MUBELER,W J MUSELER, W J TDI (Transamerica Delaval, Inc.) Owners Group. 84/03/23. DENTON, H R Office of Nuclear Reactor Regulation, Director, 2pp 22774 001 24X Fiche 50-000,84/03/23,8403270132
- 8403270134 Requests meeting on 840418 to discuss short-term & long-term corrective actions & investigations re Transamerica Delayal dieset generators List of suggested meeting topics enci MCOAUGHY, J.P. TDI (Transamerica Delayal, Inc.) Owners Group 84/03/23 DENTON, H.R. Office of Nuclear Reactor Regulation, Director App. 22769 133 R4X Fiche 50-000,84/03/23,8403270134

- T Hearing transcripts on non-antitrust matters
- 8402090039 Board Notification 84-052 forwards meeting summaries containing transcripts of B40210 & 16 meetings between NRC & Transamerica Delaval, Inc (TDI) Owners Group Distribution EISENHUT, D G Division of Licensing 84/03/12 PALLADING Commissioners 5pp 22708 001 24% Fiche 50-000,84/03/12,8402090039
- DOCKET 50-331 DUANE ARNOLD ENERGY CENTER F Security, medical, emergency & fire protection plans
- 8403200121 Revised emergency plan implementing procedures, including Rev I to EPIP 2 4. "Activation & Operation of Offsite Relocation & Assembly Area" & Rev 23 to rev control sheet W/840126 ltr & transmittal/ack memo dtd 840125 YOUNG.K. WILSON.D L. Iowa Electric Light & Power Ca 83/11/17 DENTON.H Office of Nuclear Reactor Regulation. Director 13pp 22697 023 24X Fiche 50-331,83/11/17,8403200121
- 8403200051 Revised emergency plan implementing procedures, including Rev & to EPIP 2 2 re technical support ctr activation. Rev 2 to EPIP 6 1 re maint of emergency preparedness & Rev 2 to EPIP 7 1 re coordinator duties W/840125 ltr WILSON, D.L. Igwa Electric Light & Power Co. 84/01/10 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 93pp. 22683 251 24X Fiche 50-33L 84/01/10/8403200051
- 8403200047 Rovised emergency plan implementing procedures, including Rev 4 to EPIP 1 1 re emergency action level determination & Rev 6 to EPIP 1 2 re notification of emergency response organization W/840126 ltr wILSON, D L Jowa Electric Light & Power Co 84/01/16 DENTON, H Office of Nuclear Reactor Regulation, Director 60pp 22685 212 24X Fiche 50-331.84/01/16.8403200047 DENTON: H R
- B4032001B3 Revised emergency implementing procedures, including Rev 1 to Procedure EPIP 2 5. "Control Room Emergency Response Operation" & Rev 5 to Procedure EPIP 3 3a. "Manual Dose Injections " W/840312 ltr MILBON, D.L. Iowa Electric Light & Power Co. 84/02/08 DENTON, H. Office of Nuclear Reactor Regulation, Director 68pp. 22697 144 24% Fiche 50-331,84/02/08,8403200183
- 8403060550 Advises that NRC will not review emergency plans to delete privacy or proprietary info whiess specifically requested by licensee.per 810709 Generic i.tr 81-27 M/o request.entire plan will be placed in PDR VASBALLO.D 0 Operating Reactors Branch 2 84/02/10 LIU.L Iowa Electric Light & Power Co 2pp 22952 293 24X Fiche 50-331.84/02/10.8403060550
- 8403060136 Forwards changes to security plan Changes withheld (ref 10CFR73 21) MCGAUCHY, R W Iowa Electric Light & Power Co 84/02/27 KEPPLER, J O Region 3, Office of Director ip 22516 Fiche 50-331,84/02/27,8403060136 2251A 085 24X
- 8403120057 Extends invitation to attend regional workshop on fire protection safe shutdown requirements of 10CFR50.App R & IE Info Notice 84-07 on 840323 in Rosemont, LL Proposed agenda encl for review SPESSARD.R L Division of Engineering 84/0 Electric Light & Power Co 3pp 22588 044 Fiche 30-331,84/03/04,8403120057 B4/03/06 LIU.L
- 8403130145 Ack receipt of 840227 ltr transmitting changes to security plan Changes consistent w/provisions of 100fR50 54(p) & accentable AXELSON, W.L. Region 3, Office of Director 84/03/08 LIV, L. lowe Electric Light & Power Co. 2pp. 22408 171 24X Fiche 50-331,84/03/08,8403130145
- 8403130478 Ack receipt of 840222 ltr re procedure distribution for radiation protection procedures Controlled distribution of emergency plan & implementing procedures acceptable PAPERIELLO, C. J. Region 3, Office of Director 84/03/08 MINECK, D. L. Iowa Electric Light & Power Co. Ip 22613 252 24 Ficha 50-331,84/03/08.8403130478 22613 252 24X
- --8403130488 Discusses revised procedures to simplify distribution of NOSISMABLE Discusses revised procedures to simplify distribution protection procedures from controlled copy to uncontrolled copy for info only MINECK.D.L. Iswa Electric Light & Power Co. 84/02/22 KEPPLER.J & Region 3. Office of Director ip 22613 Fichs 50-331,84/03/08.8403130478 22613 253

- 8403170236 Forwards IE Safeguards Insp Rept 50-331/83-19 on 831220-840119 & notice of violation & proposed imposition of civil penalty Notice withhold fore ioCFR73 21) KEPPLER. J G Region 3. Office of Director 84/03/13 LIU.L lowa Electric Light & Power Co 4pp 22672 281 24X Fiche 50-331.84/03/13,8403190232
- --B403190237 IE Bafeguards Insp Rept 50-331/83-19 on 831220-840119
 Noncompliance noted failure to provide adequate vital area
 barrier & security plan criteria not met for vital
 equipment Details withheld (ref 10CFR73 21)
 PIRTLE, G L . MADEDA, T J . CREED, J R Region 3, Office of Director
 84/02/01 2pp 22672 285 24X Fiche 50-331,84/03/13,8403190236

J Insurance & indemnity information

- 8403260062 Forwards Endorsements 62 & 63 to NELIA Policy NF-214 & Endorsements 51 & 52 to MAELU Policy MF-72 SHEA, K H Newman & Holtringer 84/03/14 SALTZMAN, J D Assistant Director for State & Licensee Relations 5pp 22750 240 24X Fiche 50-331,84/03/14,8403260062
- P Operating license stage documents & correspondence
- B403200192 "Offsite Dase Assessment Manual for Gaseous & Liquid Effluents " W/B40315 ltr MCGAUGHY.R W lowe Electric Light & Power Co B3/03/31 DENTON.H Office of Nuclear Reactor Regulation, Director 112pp 22700 034 24X Fiche 50-331,B3/03/31,8403200192
- B402140527 Forwards exemption from leakage test requirements of 10CFR30.App J, Section 50 54(a).per util 780829 request Exemption for core spray isolation valves & RCIC & HPCI condensate return isolation valves denied SER also encl EISENHUT.D 6 Division of Cicensing 84/01/17 LIU.L Iowa Electric Light & Power Co 2pp 22262 234 24X Fiche 50-331.84/01/17,8402140527
- --B402140536 Examption from leakage test requirements of 10CFR50.App J. Baction 50 B4(a) ie leak tight integrity of primary reactor containment & sys & companients which penetrate containment ETBENHUT.D G Division of Licensing B4/01/17 Jowa Electric Light & Power Co App 22262 236 24X Fiche 50-331,84/01/17,8402140527
- B403060050 Forwards request for add1 info re Mark I containment longterm program, plant-unique analysis rept loads evaluation Response requested within 45 days of ltr receipt Meeting or conference call recommended no later than B40221 VASBALLO.D B Operating Reactors Branch 2 84/02/07 LIU.L Iowa Electric Light & Power Co App 22528 310 24X Fiche 50-331,84/02/07,8403060050
- 8403140340 Summary of 831215 meeting w/OE & Mark I Owners Group in Bethesda, MD re Mark I containment wetwell-drywell vacuum breaker design methodology SIEGEL, D. L. Operating Reactors Granch 2 84/02/21 Operating Reactors Branch 2 Sipp 22435 198 24X Fiche 50-000,84/02/21, 8403140340
- BA03140313 Responds to BA0123 ltr concurring w/NRC determination of NSHC for amend request RTS-155 Addl amend requests received from licensee after 830506 published in FR include RTS-154.RTS-153 & RTS-74
 VASSALLO, D B Operating Reactors Branch 2 84/02/23 HOUVENAGLE, T Inwas State of Spp 22635303 24X Fiche 50-331,84/02/23,8403140313
- 840302010B Application for amend to License DPR-49.correcting typographical errors.clarifying existing text & updating old refs MCGAUGHY.R W Iows Electric Light & Power Co 84/02/27 DENTON.H Office of Nuclear Reactor Regulation. Director 2pp 22442 335 24X Fiche 50-331.84/02/27.840302010B
- --9403020111 Proposed Tech Specs correcting typographical errors, clarifying existing test & updating old refs 10wa Electric Light & Power Co 84/02/27 75pp 22442 337 24X Fiche 50-331.84/02/27.8403020108
- B403050233 Notifies that Class IV rather than Class III fee appropriate for review of 840127 application for amend to License DPR-47, changing Tech Specs re MUREO-0737 & min staffing requirements.

 DIGGS.R M License Fee Management Branch 84/02/29 ARNDLD, D Iowa Eiectric Light & Power Co ip 22527-337 24X Fiche 50-331.84/02/29,8403050233.

-1 -12 1

- 8403090262 Forwards supplemental response to Generic Ltr 83-28,
 "Required Actions Based on Generic Implications of Salem
 ATMS Events "Activities may be rescheduled during next
 update of integrated plan for mods
 MCGAUGHY, R W Iowa Electric Light & Power Co 84/02/29 DENTON, H
 Office of Nuclear Reactor Regulation, Director 284pp 22572 304
 24X Fiche 50-331.84/02/29,8403090262
- --8403090277 Rev O to Procedure 1410 8, "Post-Scram Review "
 SEDLACK, M B Illinois Power Co 84/02/23 App 22573 222 24X
 Fiche 50-331,84/02/29,8403090262
- 8403130144 Forwards response to NRC 840207 request for addl info re plant-unique analysis rept for Mark I torus mads MCGAUGHY, R W Iowa Electric Light & Power Co 84/03/02 DENTON, H Office of Nuclear Reactor Regulation, Director 24pp 22601 276 24X Fichs 50-331.84/03/02.8403130144
- 8403090088 Application to amend License DPR-49, changing Tech Specs to incorporate addl MAPLHOR limits MCGAUGHY, R W Iowa Electric Light & Power Co 84/03/05 DENTON, H Opfice of Nuclear Reactor Regulation, Director 2pp 22575 327 24X Fiche 50-331.84/03/05.8403090088
- --8403090092 Proposed Tach Spec changes extending MAPLHOR limits * Iowa Electric Light & Power Co 84/03/05 iipp 22575 329 24X Fiche 50-331.84/03/05.8403090088
- 8403150087 Forwards draft summary of status of equipment qualification program, including response summary of technical evaluation rept. accident description & equipment identification summary & qualification rept MCGAUGHY, R W Iowa Electric Light & Power Co 84/03/08 DENTON, R Defice of Nuclear Reactor Regulation, Director 106pp 22641 054 24x Fiche 50-331,84/03/08,8403150087
- B403190300 Forwards revised Page 3 2-23. Table 3 2-G of 840214 Amend 93 to License DPR-49, making administrative changes to Tach Spuce MCGAUGHY, R W Iowa Electric Light & Power Co 84/03/12 DENTON, H Office of Nuclear Reactor Regulation. Director Ip 28673 166 24) Ficho 80-331.84/03/12, 8403190300
- ---8403190306 Revised Page 3 2-23 to Tech Specs, reflecting administrative changes * lowa Electric Light & Power Co 84/03/12 ip 22673 167 24% Fiche 50-331,84/03/12,8403190300
- 8403190275 Generic Ltr 84-07 to all licensees of BHRs re procedural guidance for pipe replacement at BHRs Svc list encl EIGENHUT.D & Division of Licensing 84/03/14 Commonwealth Edison Co 20pp 22823 354 24X Fiche 50-000.84/03/14.8403150275
- 8403300279 Requests remittance of fee for action on 780829 application re exemption from certain App J test requirements MILLER, W O License Fee Management Branch 84/03/15 ARNOLD, D Towa Electric Light & Power Co 1p 22844 330 24X Fiche 50-331.84/03/15.8403300279
- B403230004 Application for mey to License DPR-46, changing Tech Specs ms primary containment leakage test requirements MCGAUGHV, R W Iowa Electric Light & Power Co 84/03/16 DENTON, HR Office of Nuclear Reactor Regulation, Director 4pp 22728 088 24X Fiche 50-331.84/03/16.8403230004
- ~-B403230007 Proposed Tech Spec Change RTB-112B.changing primary containment leakage test requirements * Iowa Electric Light & Power Co B4/03/16 19pp 22728.092 24X Fiche S0-331.84/03/16.8403230004
- 8403260208 Corrects erroneous statement from 830425 response to Generic Ltr 83-02, "NUREO-0737 Tech Bpecs," re Action Item II, E 4, 1, "Dedicated Hydrogen Penetration " Purge/repressurization sysused as backup for combustible gas control.

 MCGAUGHY.R W Iowa Electric Light & Power Co 84/03/20 DENTON, H Office of Nuclear Reactor Regulation, Director 1p. 22756: 166 24X Fiche 50-331:84/03/20,8403260208
- Q. Inspection reports, IE Bulletins & correspondence
- 8403140319 Forwards request for add1 info identified by Franklin Research Ctr re IE Bulletin 80-11 concerning masonry wall design in response to licensee 821010 submittal VASSALLO,D B Operating Reactors Branch 2 84/02/22. LIU.L. Iowa Electric Light & Power Co App 22635 283 24X Fiche 50-331,84/02/22,8403140319

- 8403120120 Forwards IE Insp Rept 50-331/84-02 on 840103-31 & notice
- of violation
 NORELIUS,C E Region 3, Office of Director 84/02/23 LIU,L Iowa
 Electric Light & Power Co 2pp 22588 206 24X
 Fiche 30-331.84/02/23.8403120120
- --8403120129 Notice of violation from insp on 840103-31 NORELIUS,C E Region 3. Office of Director 84/02 22588 208 24% Fiche 50-331.84/02/23,8403120120 84/02/23 In
- --B403120133 IE Insp Rept 50-331/84-02 on B40103-31 Noncompliance noted failure to follow procedures re connecting volt ohmmeter at step 4 1 instead of step 4 7, causing PS 4544 to Jumper closed & PSV-4401 to open CLARDY, L S. WALKER, D. Region 3, Office of Director B4/02 7pp 22588 207 24X Fiche 50-331,84/02/23,8403120120
- 8403230105 Forwards inservice insp/test results during Apr & Jul 1982 outages Procedure revised to resolve inconsistency re responsibility for reporting insp results MCOAUGHY, R W I Towa Electric Light & Power Co 84/02/27 KEPPLER, J G Region 3, Office of Director 7pp 22730 219 24X Fiche. 50-331,84/02/27,8403230105
- B401170072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation." Svc list enci. JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc. 115pp 22909 239 24X Fiche 50-000,84/02/28,8401190072
- B402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Evc list encl GRACE. J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22582 329 24X Fiche 50-000,84/03/02,8402090007.
- B402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp. 22553 098 24X Fiche 50-000.84/03/02.8402090008
- 8402090009 IF Info Notice 84-15. "Reporting of Radiological Releases 902090009 He into Notice 84-10, "Reporting of Readiological Releases" Byc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02. Consolidated Edison Co of New York, Inc. 119pp. 22553 217 24X Fiche 30-000.64/03/02.8402090009
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Coaling Components Below Nii Ductility Temp " Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co. of New 22553 334 24X Fiche 50-000,84/03/05,8402090011 117pp
- 24X Fiche 50-000,84/03/07,8402070024 22635 049 118pp
- 8402090028 IE Info Notice 84-18. "Stress Corrosion Cracking in PWR Bys "Byc list encl JORDAN,E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402070028
- 8402070031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Glass IE Bafety Sys " Byc list encl DEYOUNG,R. C Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823,094 24X Fiche 50-000,84/03/12,8402090031
- 8403170236 Forwards IE Bafeguards Insp Rept 50-331/83-17 on 831220-840117 & notice of violation & proposed imposition of civil penalty Notice withheld (ref 100FR73 21)
 KEPPLER, J. G., Region 3, Office of Director 84/03/13 LIU, L. Iowa Electric Light & Power Co. 4pp. 22672-281 24X
 Fiche. 50-331,84/03/13,8403190236
- --8403190239 IE Safeguards Insp Rept 50-331/83-19 on 831220-840119. 403190237 it Baregueros insp Rept 30-33/83-17 on 631220-640117.

 Noncompliance noted failure to provide adequate vital area
 barrier & security plan criteria not met for vital
 equipment Details withheld (ref 10CFR73 21)
 PIRTLE 0 L., MADEDA.T J. CREED.J.R. Region 3, Office of Director
 84/02/01. 2pp 22672 285. 24X Fiche 50-331,84/03/13,8403190236
- 8402090043 IE Info Natice 84-19, "Two Events Involving Unauthorized Entries into PHR Reactor Cavities " Svc list encl JURDAN.E L. Division of Emergency Preparadness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp. 22823 227 24X Fichs 50-000,84/03/21,8402090043

- 8402070044 IE Info Notice 84-20, "Syc Life of Relays in Safety-Related 102070044 lt info Notice - Sys " Svc list encl JDRDAN.E L. Division of Emergency Preparedness & Enginearing Response (Post B30103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000,84/03/21,8402070044
- R Periodic operating reports & related correspondence
- B403120042 "Annual Rept of Facility Changes.Tests.Experiments & Bafety & Relief Valve Failures & Challenges,1983 " W/840301 ltr MINECK,D L. Iowa Electric Light & Power Co. 83/12/31 KEPPLER.J G Region J. Office of Director 73pp 22591 145 24X Fiche 50-331.83/12/31,8403120042
- 8403220017 Monthly operating rept for Feb 1984 W/840315 1tr PUTNAM,K S . MINECK,D L | Jowa Electric Light & Power Co 7pp 22712 332 24X Fiche 50-331.84/02/27.8403220017 84/02/29
- 8 Reportable occurrences, LERs & related correspondence
- B403060145 LER 84-009-00 on B40131 during performance of LPCI surveillance test.RHR sys discharge piping pressure drapped to 0 psig Caused by equipment maladjustment Position indication on two valves in question adjusted W/840301 ltr KEITH.W R, MINECK,D L lowa Electric Light & Power Co B4/03/01 3pp 22313 346 24X Fiche 50-331.84/03/01.8403060145
- 8403120071 LER 84-010-00 on B40204, steam leak detection high differential temp. HPCI isolation trip signal annunciators alarmed & inboard HPCI steam supply isolation valve cycled closed Caused by electrical spike in HPCI H/840305 itr SMITH, J C . MINECK, D L lowa Electric Light & Power Co Gpp 22588 246 24x Fiche 50-331.84/03/05.8403120091 84/03/05
- 8403120139 LER 84-011-00 on 840205, auto-isolation of control bldg ventilation & initiation of intake standby filter unit 8 occured due to low inlet air temp Caused by Inadequate circulation through nonsafety-related coils W/840306 ltr HAMEL.D B., MINECK.D L. Iowa Electric Light & Power Co. 84/03, 3pp 22590 139 24X Fiche 50-331.84/03/06.8403120139 84/03/06
- 8403160051 EN-84-011 notice of violation & proposed imposition of civil penalty in amount of \$20,000 to be issued Action based on failure to control access to vital area RGSANO.R. AXELRAD.J Director's Office of Inspection and Enforcement 84/03/08 ip 22652 019 24X fiche 50-331,84/03/08.
- DOCKET 50-333 JAMES A FITZPATRICK NUCLEAR POWER PLANT F Security, medical, emergency & fire protection plans
- 8403060045 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee.per 810709 Generic Ltv 81-27 W/o request, entire plan will be placed in PDR VASSALLO, D B Operating Re VABBALLO,D B Operating Reactors Branch 2 84/02/10 BAYNE,JP Power Authority of the State of New York 2pp 22528 316 24X Fichs 50-333,84/02/10,8403060045
- 8403140246 Forwards comments on detailed control room design review program plan per Suppl 1 to NUREO-0737 Specific areas of plan not described in enough detail to provide assurance that applicable requirements will be met VABSALLO.D B Operating Reactors Branch 2 84/02/22 8AYNE.J.P. Power Authority of the State of New York 10pp 22636 343 24X Fiche 50-333.84/02/22.8403140246
- 8403070312 Forwards IE Insp Rept 50-333/84-01 on 840101-31 No violations observed STARDBTECKI.R Division of Project & Resident Programs 84 MCNEILL.C A Power Authority of the State of New York 2pp 22546 185 24X Fiche 50-333.84/02/23.8403070312 B4/02/23
- --8403070316 IE Insp Rept 50-333/84-01 on 840101-31 No violations noted Major areas inspected licensee action on previous insp findings.LER review.operational safety verification, surveillance observations & fire protection program DOERFLEIN.L T Region i. Office of Director COLLINS.B J Division of Project & Resident Programs 84/02/21 11pp 22546 187 24% Fichs 50-333,84/02/23,8403070312
- 8403020327 Requests that completion date of emergency operations 403020327 Requests that completion date of emergency operations facility be extended from 850201 to 850628, par 830415 & 0824 ltrs & NUREG-0737, Suppl 1 Completion date does not cover safety parameter display sys installation BAYNE, J P Power Authority of the State of New York 84/02/29 YASSALLO, D B Operating Reactors Branch 2 2pp 22439, 205 fiche 50-333,84/02/29,8403020327

- 8403190243 Notification of 840418 workshop in King of Prussia, PA to discuss lessons learned from recent App R fire protection safe shutdown insp & topics described in IE Info Notice 84-09 Agenda for workshop enci MURLEY. TE Region 1. Office of Director 84/03/09 D/TOOLE. J D Consolidated Edison Co of New York. Inc DALTROFF, BL Philadelphia Electric Co HUKILL, H D General Public Utilities OPU Service Corp 3Spp 22672 062 24X Fichs 50-000, 84/03/09, 8403190243
- 8403270185 Requests extension to 840831 for completion of third annual emergency preparedness exercise, based on interpretation of Section IV F.App E to 10CFR50
 BAYNE.J P Power Authority of the State of New York 84/03/21
 VASSALLO,D B Operating Reactors Branch 2 2pp 22771 121 24)
 Fiche 50-333.84/03/21.8403270185
- P Operating license stage documents & correspondence
- 8403120024 Submits progress rept for drawing update program, including schedule for balance of update work & description of program for continued maint of as-built drawings, per 830408 request BAYNE.J P Power Authority of the State of New York \$4/02/10 Region 1, Office of Director 4pp \$22586 275 24X Fiche 50-333,84/02/10,8403120024
- 8403140304 Informs that add1 info necessary to review 830513 request for amend to License DPR-59.changing Tech Specs re process plping penetrating primary containment info should be submitted within 60 days of ltr receipt VASSALLD.D B Operating Reactors Branch 2 84/02/21 BAYNE, J P Power Authority of the State of New York 2pp 22635 315 24X Ficha 50-333.84/02/21.8403140304
- B403140340 Summary of B31215 meeting w/GE & Mark I Gumers Group in Bethesds.ND re Mark I containment wetwell-drywell vacuum breaker design methodology SIEGEL.O L Operating Reactors Branch 2 84/02/21 Operating Reactors Branch 2 Sipp 22635 178 24X Fiche 50-000.84/02/21, B403140340
- 8403020351 Advises that util will continue to operate vent & purge valves for inspecting RCPB, in response to NRC 840113 ltr Vant & purge valve data encl BAYNE, J P Power Authority of the State of New York 84/02/24 VASSAL
- 8403090240 Summary of 840216 meeting w/Northeast Nuclear Energy Co. Boston Edison Co. Vermont Yankee Nuclear Power Co & Teledyne Engineering Svcs in Waltham An re addl Mark I torus structural analysis List of attendees encl SHEA. J Operating Reactors Branch 5 84/03/07 CRUTCHFIELD.D Operating Reactors Branch 5 402 22572 278 24X Fiche 50-000.84/03/07.8403090240
- 8403300266 Informs of review of data & evaluations re crack in heat affected zone of recurculation sys weld Continued operation acceptable
 VASSALLO, D B Operating Reactors Branch 2 84/03/12 BAYNE, J P
 Power Authority of the State of New York 2pp 22844 334 24X
 Fiche 50-333,84/03/12,8403300266
- B403150275 Generic Ltr 84-07 to all licensees of BMRs re procedural guidance for pipe replacement at BMRs Svc list encl EISENHUT D O Division of Licensing 84/03/14 Commonwealth Edison Co 20pp 22623 354 24% Fiche 50-000,84/03/14,8403150275
- 8409300250 Notification of 840330 meeting w/util in Bethosda.MD to discuss environ qualification of equipment ABELSON.H J Operating Reactors Branch 2 84/03/14 VASSALLO.D B Operating Reactors Branch 2 2pp 22844 354 24X Fiche 50-333.84/03/14.8403300250
- 8403300252 Notification of B40322 meeting w/util in Dethesda, MD to discuss licensee exemption request re staffing rule ABELSON.H I Operating Reactors Branch 2 84/03/14 VASSALLO, D 8 Operating Reactors Branch 2 ip 22844 356 24% Fiche 50-333,84/03/14,8403300252
- B403200094 Forwards response to request for info re licensed matl disposal procedures, per 100FR20 302 & util 830808 ltr Oil burn rate & stack volumetric flow rate for mor & average boiler operation presented in Table 1 BAYNE. J P fower Authority of the State of New York 84/03/15 VASSALLO.D B Operating Reactors Branch 2 4pp 22685 301 24: Fiche 50-333.84/03/15.8403200094
- --8403200096 Revised "Proposed Disposal Procedures for Radioactively Contaminated Fuel O.1 "
 * Power Authority of the State of New York 84/02/29 App 22665 305 24X Fiche 30-33184/03/15.8403200099

- 8403260171 Withdraws E30513 application to amend License DPR-59, changing Tech Spec Table 3 7-1 re process piping penetrating primary containmentias complete update of Table 3 7-1 will be submitted by 840627 BAYNE.J P Power Authority of the State of New York 84/03/20 VASSALO.D B Dperating Reactors Branch 2 2pp 22750 359 24X Fiche 50-333,84/03/20,8403260171
- G Inspection reports, IE Bulletins & correspondence
- B403070312 Forwards IE Insp Rept 50-333/84-01 on 840101-31 No violations observed STARDSTECKI, R Division of Project & Resident Programs 84/02/23 MCNEILL, C A Power Authority of the State of New York 2pp 22546 185 24% Fichs 50-333.84/02/23.8403070312
- --8403070316 le Insp Rept 50-333/84-01 on 840101-31 No violations noted Major areas inspected licensee action on previous insp findings.LER review.operational safety verification, surveillance observations & fire protection program DOERFLEIN.L T Region 1. Office of Director COLLINS.S J Division of Project & Resident Program 84/02/21 11pp 22546 187 24X Fiche 50-333.84/02/23.8403070312
- B403020331 Advises that util will continue to operate vent & purge valves for inspecting RCPB in response to NRC B40113 ltr Vent & purge valve data encl
 B4YNE.J P Power Authority of the State of New York B4/02/24
 VASSALLO,D B Operating Reactors Branch 2 4pp 22439 030 24X
 Fiche 50-333.84/02/24.8403020331
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list uncl
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consalidated Edison Co of New York, Inc 118pp 22907 239 24X Fiche 50-000,84/02/28,8401190072
- 8402090007 IE Info Notice 84-14. "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl GRACE, J N Division of GA: Bafeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000,84/03/02.8402090007
- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Bys Valves to Operate " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 630103) 84/03/02 Consolidated Edison Co of New York, Inc 122pg 22553 098 24X Fiche 50-000,84/03/02,8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases" Byo list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8402090011 IE Info Notice B4-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN: E.L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 334 24X Fiche 50-000,84/03/05,8402090011
- 8402090024 IE Info Notice 84-09, Rev 1, "Lessons Learned From Insps of Fire Protection Bafe Shutdown Sys " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000.84/03/07.8402090024
- 8402070028 IR Info Notice 84-18, "Stress Corrosion Cracking in PWR 8ys " Svc list enc! JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/07 Consolidated Edison Co of New York, Inc. 118pp 22584 186 24X Fiche 50~000,84/03/07,8402070028
- 8403130466 Advises that during preinduction heating stress improvement ultrasonic insp.flaw identified in heat affected zone of one weld in recirculation pump suction line Evaluation concluded flaw acceptable for one fuel cycle w/o repair BAYNE.J P Power Authority of the State of New York 84/03/09. VASSALLO.D B Operating Reactors Branch 2 2pp 22613 234 24% Fiche 50-333.84/03/09.8403130466
- 8402070031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Sefety Sys "Svc list encl DEYQUNG, RC Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24% Fichs 50-000,84/03/12,8402070031

- B403220079 Ack receipt of 840228 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-333/83-28 STARDSTECKI.R Division of Project & Resident Programs MCNEILL.C A Power Authority of the State of New York 1p 22716 334 24X Fiche 50-333, 84/03/15, 8403220079
- --84032200Bi Responds to NRC 840117 ltr re violations noted in IE Insp Rept 50-333/83-28 Corrective actions review of safetyrelated work for period of time from start of commercial operation to 780131 will be completed by 840909 MCNEILL.C A Power Authority of the State of New York 8TAROSTECKI.R Division of Project & Resident Programs 2pp 22716 335 24X Fiche 50-333.84/03/15,8403220079
- B402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JORDAN,E L Division of Emergency Proparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 90-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044
- R Periodic operating reports & related correspondence
- B403010413 "Personnel Radiation Monitoring Rept for 1983 " W/B40201 ltr MCNEILL.C A Power Authority of the State of New York 83/12/31 COLLING.D Radiological Assessment Branch 2pp 22434 024 24X Fiche 50-333.83/12/31.8403010413
- 8403010420 "Personnel Radiation Exposure Summary for 1983 " W/840201 1tr MCNEILL,C A Power Authority of the State of New York 83/12/31 HAYNES,R C Region 1, Office of Director 7pp 22434 050 24X Fiche 30-333,83/12/31.8403010420
- B403130137 "Effluent & Waste Disposal Semiannual Rept Jul-Dec 1983 "
 W/B40227 Itr
 MONEILL.C A Power Authority of the State of New York 83/12/31
 MURLEY.T E Region 1, Office of Director 55pp 22601 062 24X
 Fiche 50-333,83/12/31,8403130137
- B403130350 Monthly operating rept for Feb 1984 W/B4030B ltr CODK.J, MCNEILL,C A Power Authority of the State of New York B4/02/27 11pp 22616 258 24X Fiche 50-333,84/02/27,8403130350
- 9. Reportable occurrences, LERs & related correspondence
- 8403010365 LER 84-001-00, on 840118, during surveillance testing for inoperative B side suppression pool cooling & spray isolation valve. RHR svc water pump C failed Caused by worn impeller collet Valve repaired W/840202 ltr.

 LIBEND.R. MCNEILL.C A Power Authority of the State of New York B4/02/02 MURLEY.T Region 1, Dffice of Director 3pp. 22433 015 24X Fiche 50-333.84/02/02.8403010365
- 8403010241 Updated LER 83-060/03X-1 on 831130, incorrect motor actuator installed on RHR suppression pool outboard isolation valve during maint activities Cause not stated Replacement actuator installed on 840119 W/840203 ltr
 8AKER.R. MCNEILL.C A Power Authority of the State of New York 84/02/03 MRLEY.T E Region 1, Office of Director 3pp 22434:211 24X Fiche 50-333.84/02/03.8403010241
- B403260233 Forwards summary list of deficiencies identified per iOCFRSO 55(e),Part 21 & potential generic ltr repts for comments

 STARUBTECKI.R Division of Project & Resident Programs 84/02/28 Region 1. Defice of Director. 7pp 22756 065 24X Fiche: 50-000.84/02/28.8403260233
- B403060193 LER 84-004-00 on 840210, dc ground occurred on station battery A. During ground isolation procedure, dc control power to RCIC inverter momentarily interrupted Caused by procedure not stating manual reset required. W/840229 ltr LINDERY, D. J. RONEILL, CA Power Authority of the State of New York 84/02/29, 2pp, 22917-357 24X Fiche. 50-333,84/02/29,8403060193
- 8403090025 LER 84-003-00 on 840207, while HPCI intentionally out of svc for maint & mod.RCIC sys declared inoperable Caused by personnal error Personnal counseled & training program implemented W/840305 ltr
 KEITH, H N , MCNEILL, C A Power Authority of the State of New York 84/03/05 3pp 22576 181 24X Fiche 50-333,84/03/05,8403090025

- 8403200231 LER 84-006-00 on 840213 reactor water indicating switch found out of Tech Spec limits Caused by excessive internal mechanical friction Gurveillance of equipment will be performed & manufacturer contacted W/840314 ltr KEITH.H N . MCMEILL.C A Fower Authority of the State of New York 84/03/14 4pp 22696 117 24X Fiche 50-333.84/03/14.8403200231
- 8403290246 LER 84-005-00 on 840225 primary containment atmosphere monitoring instrumentation analyzers A & 8 out of svc for 5 h Caused by zero point calibr & sample flow vacuum pump problems Sys mods implemented W/840326 ltr KEITH.H N . MCNEILL.C A Power Authority of the State of New York 84/03/26 3pp 22800 195 24X Fiche 50-333.84/03/26.8403290246
- DOCKET 50-334 BEAVER VALLEY POWER STATION, UNIT I
- 8403200040 Emergency Preparedness Plan EPP/IP 1 2.Attachments 6 & 7 MILLER, D J Duquesne Light Co 84/03/02 6pp 22698 316 24X Fiche 50-334,84/03/02.8403200040
- 8403190243 Notification of 840418 workshop in King of Prussia,PA to discuss lessons learned from recent App R fire protection safe shutdawn insp & topics described in IE Info Notice 84-03 Agenda for workshop encl MURLEY,TE Region I. Office of Director 84/03/09 O'TOOLE,J D Consolidated Edison Co of New York, Inc MANGA,B K General Public Utilities GPU Service Corp WODLEVER, EJ Duquesne Light Co 35pp 22672 062 24X Fiche 50-000,84/03/09,8403190243
- 8403200233 Revised emergency plan implementing procedures, including Procedure EPP/IP 3 2 re personnel accountability, Procedure EPP/IP 3 4 re emergency respiratory protection & Procedure EPP/IP 3 5 re traffic & access control W/840227 ltr SIEBER; J D Duquesne Light Co 84/03/09 241pp 22690 208 24X Fiche 50-334,84/03/09,8403200233
- 8403210097 Forwards IE Insp Rept 50-334/84-03 on 840131-0203 No violations noted MARTIN T T Division of Engineering & Technical Programs 84/03/09 CAREY,J J Duquesne Light Co 2pp 22705 357 24X Fiche 50-334,84/03/09,8403210097
- --8403210105 IE Insp Rept 50-334/84-03 on 840131-0203 No violations noted Major areas inspected emergency preparedness of areas described in IE Insp Procedures 82203,82204,82205,82206,82206,82207,82210 & 82211
 SMITH.R H , MOLINER.E Region 1. Office of Director CROCKER,H W Division of Engineering & Technical Programs 84/03/08 4pp 22705 359 24X Fiche 50-334,84/03/09.8403210097
- 8403260166 Forwards IE Insp Rept 50-334/84-04 on 840201-29 No violations found STAROBTECKI.R Division of Project & Resident Programs 84/03/12 CAREY, J J Duquesne Light Co 2pp 22757 320 24X Fiche 50-334,84/03/12,8403260166
- --8403260173 IE Insp Rept 50-334/84-04 on 840201-27 No significant safety issues identified Major areas inspected plant operations, housekeeping, fire protection, radiological controls, physical security & surveillance program TRDSKDSKI,W M., JOHNSON,D., TRIPP,L. Region 1. Office of Director B4/03/12 14pp 22757 322 24X Fiche 50-334,84/03/12, 8403260166
- B403270215 Provides followup to 840228 telcon re Suppl 1 to NUREO-0737.
 "Development of Emergency Operating Procedures." From generic Westinghouse emergency response guidelines
 Development will continue as described.
 CAREY, J. J. Duquesne Light Co. 84/03/14 VARGA.S A. Operating
 Reactors Branch 1 3pp 22770 270 24X Fiche 50-334.84/03/14.
 B403270215
- B4032B0017 Forwards Rev i to physical security plan.Part I, "Base Plan " Rev withheld (ref 10CFR73 21 & 2 790) CAREY, J J Duquesne Light Co B4/03/15 MURLEY, T E Region i, Office of Director 2pp 22777 082 24X Fiche 50-334,84/03/15, B4032B0017
- P Operating license stage documents & correspondence
- 8403070387 Forwards Amend 76 to License DPR-66 & safety evaluation Amend changes Tach Specs by adding six hydraulic snubbers to surveillance list.Table 3 7-4a TAM.P Operating Reactors Branch 1 84/02/27 CAREY, J. J. Duquesno Light Co. 3pp 22567 032 24X Fiche 50-334.84/02/27,8403070387.

R403090153

8403260274

- --8403070389 Amend 76 to License DPR-66 changing Tech Specs by adding six hydraulic snubbers to surveillance list.Table 3 7-4a VARGA.5 A Operating Reactors Branch 1 84/02/27 4pp 22567 025 24% Fiche 50-334,84/02/27.8403070
- --8403070391 Safety evaluation supporting Amend 76 to License DPR-66
 * Office of Nuclear Reactor Regulation, Director 84/02/27 2pp
 22567 039 24X Fiche 50-334/84/02/27,8403070387
- 8403070133 Notifies that goal for completion of technical reviews & implementation of NUREG-0737 items.excluding Suppl 1.is Sept 1984 All required documents must be provided & Tech Specs in place to meet goal VAROAS A Operating Reactors Dranch 1 84/03/02 CAREY. J J Duquesne Light G 3pp 22584 358 24X Fiche 50-334.84/03/02.
- 3403160061 Summary of 840301 meeting w/util re upgrading core exit thermocouples (TMI Action Item II F 2) List of attendees
- enc.: TAM.P S Operating Reactors Branch 1 84/03/07 Operating Reactors Branch 1 App 22662 310 24x Fiche 50-334,84/03/07. 84/3314/064
- 3403260294 Forwards request for add1 info re 821221 request for relief from ASHE Code, Section XI inservice testing requirements for pumps & valves Response requested within 45 days of ltr receipt VAROA.S A Operating Reactors Branch 1 84/03/08 CAREY.J J Duquesne Light Co App 22761337 24X fiche 50-334.84/03/08.
- 1403280325 Forwards comments on proposed Tech Spec changes per 830714 & 0922 ltrs Addl info on bypasses to block trip instruments requested
- requested VARGA:S.A Operating Reactors Branch 1 84/03/13 CAREY, J.J. Duqueene Light Co 17pp 22807 305 24X Fiche 50-334:84/03/13-840328025
- Inspection reports, IE Bulletins & correspondence
- 401190072 IE Info Natice 84-13, "Potential Deficiency in Mator Operated Valve Control Circuits & Annunciation " Svc list encl
- encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22909 239 24X Fiche 50-000,84/02/28,8401190072
- |03070342 Ack receipt of 840214 Itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-334/83-29 STAROSTECKI.R Division of Project & Resident Programs 84/02/28 CAREY, J Duquesne Light Co 1p R2546, 288 24X Fiche 50-334,84/02/28-8403070342
- -8403070344 Responds to NRC 940116 ltr re violations noted in IE Insp Rept 50-334/83-29 Corrective actions.valves TV-CC-107A:B & C added to valve table for stroke testing & procedures for testing & calibr of relays revised CAREY.J J Duquesne Light Co B4/O2/14 STARGSTECKI:R Division of Project & Resident Programs 4pp 22546 289 24X Fichs 50-334, 84/02/28, 8403070342
- 102090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl GRACE.U.N Division of OA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Consoligated Edison Co of New York, Inc 130pp 22552 329 24x Fiche 50-000.84/03/02,8402090007
- | IO209000B IE Info Notice 84-14, "Failure of Automatic Sprinkler Sys | Valves to Operate " Svc list encl | JORDANNEL Division of Emergency Preparedness & Engineering | Response (Post 830103) | 84/03/02 | Consolidated Edison Co of New | York Inc | 122pp | 22553 098 | 24X Fiche 50-000,84/03/02,8402090008
- 02070007 IE Info Notice 84-15, "Reporting of Radiological Releases" Svc list encl
 JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 11799 22553 217 24% Fiche 50-000,84/03/02,8402070009
- 02090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JDRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/03/05 Consolidated Edison Co of New York: Inc 117pp 22553 334 24X Fiche 50-000.84/03/05.8402090011
- 03120170 Ack receipt of 840206 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-334/83-17 & 50-334/83-23 & IE Enforcement Conference Rept 50-334/83-27 STAROSTECKI, R Division of Project & Resident Programs 84/03/05 CAREY, J Duquesne Light Co 2pp 22590:160 24X Ciche 50-334,84/03/05,8403120170

- --8403120172 Responds to NRC 840106 ltr re violations noted in IE Enforcement Conference Rept 50-334/83-27 Corrective actions operations personnel responsibility review program instituted CAREY. J Duquesne Light Co 84/02/06 MURLEY. T E Region 1, Office of Director 6pp 22590 162 24X Fiche 50-334, 84/03/05.
- 8402090024 IE Info Notice 84-09. Rev 1, "Lessons Learned From Insps of Fire Protection Bafe Shutdown Sys " Syc list and JURDAN.E L Division of Emergency Preparedness & Engineering Response (Past 830103) 84/03/07 Consolidated Edison Co of New York, Inc 188p 22635 049 24X Fiche. 50-000, 84/03/07, 8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking im PWR Sys " Svc list enc! JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- B403210097 Forwards IE Insp Rept 50-334/84-03 on 840131-0203 No violations noted MARTIN.T T Division of Engineering & Technical Programs 84/03/09 CAREY.J J Duquesne Light Ca 2pp 22705 357 24X Fiche: 50-334, 84/03/09, 8403210097
- 8402090031 IE Bulletin 84-02, "Failures of QE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000.84/03/12,8402090031
- 8403260166 Forwards IE Insp Rept 50-334/84-04 on 840201-29 No violations found STAROSTECKI,R Division of Project & Resident Programs. 84/03/12 CAREY, J Duquesne Light Co 2pp 22757-320 24X Fichs 50-334:84/03/12:8403260166
- --8403260173 IE Insp Rept 50-334/84-04 on 840201-29 No significant safety issues identified Major areas inspected plant operations, housekeeping, fire protection, radiological controls, physical security k surveillance program
 TROSKOSKI, W M , JOHNSON, D , TRIPP, L Region 1, Office of Director 84/03/12 14pp 22757 322. 24X Fiche 50-334,84/03/12, 8403260166
- B403270053 Forwards IE Insp Rept 50-334/84-02 on 840116-20 & notice of violation MARTIN.T T Division of Engineering & Technical Programs 84/03/13 CAREY, J Duquesne Light Co 2pp 22806.272 24X Fiche 50-334.84/03/13.8403290053
- --8403270057 Notice of violation from insp on 840116-20 * Region 1. Office of Director 84/03/13 1p 22804 274. 24X Fiche 50-334,84/03/13,8403270053.
- ---8403290062 IE Insp Rept 50-334/84-02 on B40116-20 Violation noted.

 10-yr inservice insp plan in use not distributed in controlled manner or reviewed or approved by authorized personnel GRAY.E H , MCBREARTY,R A , DURR.J P Region 1, Office of Director B4/02/28 5pp. 22806 275 24X Fiche 50-334,84/03/13,8403290053
- 8402090043 IE Info Notice 84-19. "Two Events Involving Unauthorized Entries into PMR Reactor Cavities" Svc list encl.
 JORDANJE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc 123pp 22823 229 24X Fiche 30-000.84/03/21.8402090043
- 8402070044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc 135pp 22933 001 24X Fiche.50-000,84/03/21,8402070044
- R Periodic operating reports & related correspondence
- 8403260160 Annual rept of challenges to pressurizer safety & PORVs No challenges occured during 1983 M/840223 ltr CAREY, J J Duquesne Light Co 83/12/31. MURLEY, T E Region 1. Office of Director 2pp 22750-343 24X Fiche: 50-334, 83/12/31. 8403240160

- 8403010126 NPDES discharge monitoring rept for Jan 1984 W/840224 ltr FEITKNECHT.C Duquesne Light Co 84/01/31 REID.R W Operating Reactors Branch 4 16pp 22435 324 24X Fiche 50-334.84/01/31. 8403010126
- B403020086 Monthly operating rept for Jan 1984 W/840209 ltr HOLTZ, J J. CAREY, J J Duquesne Light Co B4/01/31 12pp 22441 199 24X Fiche 50-334,84/01/31.8403020086
- 8403070269 Forwards annual rept of personnel receiving greater than 100 mrem & associated mrem exposure by work function for CY83.

 CAREY, J J Duquesne Light Co 84/02/15 MURLEY, T E Region 1, Office of Director 1p 22541 272 24X Fiche 50-334, 84/02/15, 8403070269
- --B403070366 Annual rept of personnel receiving greater than 100 mrem & associated mrem exposure by work function for CYE3

 * Duquesne Light Co 83/12/31 1p 22541 273 24X
 Fichs 50-334, B4/02/15, B403070269
- 8403070243 Forwards "Effluent & Waste Disposal Semiannual Rept, Jul-Dec 1983 " Ventilation vent radiation monitor RM-V8-101A/8 declared inaperable on 831130 CAREY, J J Duquesne Light Co 84/02/22 Region 1, Office of Director 2pp 22536 020 24X Fiche 50-334,84/02/22,8403070243,
- --8403070244 "Effluent & Waste Disposal Semiannual Rept, Jul-Dec 1983 " * Duquesne Light Co 83/12/31 59pp 22536 022 24X Fiche 50-334,84/02/22,8403070243
- 8403300181 Monthly operating rept for Feb 1984 W/840308 ltr HDLTZ,J L , CAREY,J J Duquesme Light Co 84/02/29 5pp 22820.333 24X Fiche 50-334,84/02/29,8403300181
- B403190276 Forwards corrected forwarding ltr dtd B40222 & page to "Bemlannual Effluent Rept. Second Half 1983," due to typographical errors CAREY, J J Duquesne Light Co 84/03/05 Region 1, Office of Director. 1p 22673 240 24X Fiche. 50-334, 84/03/05, 8403190276
- --8403190319 Corrected ltr forwarding "Semiannual Effluent Rept.Becond Half 1983" CAREY.J J Duquesne Light Co 84/02/22 Region 1, Office of Director 1p 22673-242 24X Fiche 50-334.84/03/05.8403190276
- --8403190324 Corrected "Effluent & Waste Disposel Semiannual Rept, Second Half 1983" " B Duquesne Light Co 83/12/31 1p 22673 243 24X Fiche 50-334,84/03/05,8403190276
- Reportable occurrences, LERs & related correspondence
- B403260013 Discusses loss of RHR for approx 5 h on 800321 Caused by weld in ataching line to common header of RHR pumps
 Bafety significance minimal No further AEOD action planned.
 LANNING: W D Director's Office 80/08/04 Director's Office 1p. 22763 331 24X Fiche. 50-334.80/08/04.8403260013
- 8403010016 Further response to FDIA request for 16 categories of documents. Forwards HJ Dircks 811219 ltr re 810606 sabotage event & special rept to Commonwealth of PA Info partially withheld (ref FDIA Exemption 3)
 FELTON.J.M. Division of Rules and Records 84/01/04 SHOLLY, S C Union of Concerned Scientists 2pp 22479 076 24X
 Fiche 50-334,84/01/04,8403010016
- ---B403010032 Responds to Bi1021 & 1104 requests for info re B10606 sabotage event at facility. Details withheld (ref 10CFR73, 21)
 DIRCKB,W.J. Office of the Executive Director for Operations S1/12/19. TAYLOR,F.R. Pennsylvania, Commonwealth of, 2pp 22479.080. 24X Fiche 50-334,84/01/04,8403010016
- --B403010061 "Response to Apparent Act of Sabotage at Beaver Valley, Unit 1, " Info partially deleted (ref 10CFR2 790(d) & 10CFR73, 21) + NRC - No Detailed Affiliation Given 84/01/04 App 22479; 112 24X Fiche 50~334,84/01/04,8403010016
- 8403060134 RO on 840215, high radiation slarms e/normal activity present received constantly for Channels 7 & 9 of special particulate indine, noble gas monitor Cause could not be determined Vendor will assist in investigation

 LACEY.M. 8. Duquesne Light Co 84/02/29 Record Services Branch (Document Control Desk). 2pp 22517.002 24X Fiche: 50-334.

 84/02/29,8403040134

8403270219 Part 21 rept re broken contact carrier in control dey 7 5 kV-15 kV.500-750 MVA,5 kV 350-3 000 & all HKV circuit breakers Initially reported on 830223 Addenda to installation & maint procedures sent to affected units DUVALL,D D Brown Bover: Corp (subs of Brown Bover; & Co. 84/03/19 Record Services Branch (Document Control Desk) 22772 114 24X Fiche 50-000,84/03/19.8403270219

V Operator Examinations

8403060297 Lists concerns re operator license exam review process Proper security measures can be taken to prevent dissemination of questions to license applicants during exam Requests NRC reconsider new guidance.per NUREO-1021 CAREV.J J Duquesne Light Co 84/02/24 DENTON.H R Office Nuclear Reactar Regulation. Director 2pp 22511 134 24X Fiche 50-334,84/02/24,8403060297

DOCKET 50-335 ST LUCIE PLANT, UNIT 1

- F Security, medical, emergency & fire protection plans
- B403090280 Public version of Rev 13 to radiological emergency pla B40124 ltr & JM Felton B40307 release memo WILLIAMS, J W Florida Power & Light Co B4/01/04 O'REILLY, \ Region 2. Defice of Director 227pp 22593 001 24X Fiche 50-335.84/01/04.8403090280
- 8403060340 Revised emergency implementing plan procedures, includi Procedures 2-0030140 re blackout operation,2-0030143 re total loss of ac power, 2-0120042 re LOCA & 2-1010030 re loss of instrument air W/840229 ltr 8A0ER,D A . WETHY.C N Florida Power & Light Co 84/01/23 ' 22519 094 24X Fiche 50-335.84/01/23.8403040340
- 8403070140 Forwards IE insp Repts 50-335/84-03 & 50-389/84-04 on B40118-20 No violations or deviations noted DANCE.H C Division of Project & Resident Programs 84/02/13, HILLIAMS.J W Florida Power & Light Co 2pp 22538 285 24) Fichs 50-335,84/02/13,8403070140
- --B403070145 IE Insp Repts 50-335/84-03 & 50-389/84-04 on B40118-violations or deviations noted Major areas inspected emergency preparedness to assess on-shift prompt emergency classification & protective action recommendations DECKER.TR Region 2. Office of Director JENKINS.CR Div of Emergency Preparedness & Materials Safety B4/02/10 4pp 22538 287 24X Fiche 50-335,84/02/13,8403070140
- 8403190386 Rev 12 to Emergency Plan Implementing Procedure 310002 "Natural Emergencies " W/840307 ltr WILLIAMB, J W Florida Power & Light Co 84/02/29, D'REILLY, Region 2. Office of Director 12pp 22675 270 24X Fiche 50-335,84/02/29,8403190386
- 8403060112 Forwards "Safety Parameter Display Bys Parameter Belec Evaluation & Implementation Plan," per Generic Ltr 82-33, "Buppl 1 to NUREG-0737 Requirements for Emergency Response Capability "
 WILLIAMS, J W Florida Power & Light Co 84/03/01 EISENHUT, Division of Licensing ip 22518 322 24X Fiche 50-335,84/03 E403060112
- --8403050116 "Safety Parameter Display Bys Parameter Selection Ev & Implementation Plan " * Florida Power & Light Co 84/03/01 10pp 22518 323 " Fiche 50-335,84/03/01,8403050112
- B403160254 Notifies of 840316 workshop to discuss 10CFR50, App R requirements & insp results to resolve misunderstandings refire protection Attenders should be limited to six due to sixe of conference room LEWIGIR C Division of Project & Resident Programs 84/03/02. HILLIAMS.J W Florida Power & Light Co ip 22660 255 24X Fiche 50-000.84/03/02,8403160254
- 8403290181 Expresses appreciation for cooperation throughout 10-m period of planning & developing federal full field exercise Exercise provided planning focus & field experience for complating radialogical emergency response planning O'REILLY.U P Region 2, Office of Director 84/03/15 ADOMAT Florida Power & Light Co Rpp 28802 208 24X Fiche 50-335,84/03/15,8403290181
- 8403290109 Ack receipt of 840309 ltr informing NRC of steps taken correct violations noted in IE Insp Repts 50-335/83-43 & 50-389/83-71

 BANCE.H C Division of Project & Resident Programs 84/03/19, HILLIAMS.J W Florida Power & Light Co ip 22807 001 24X Fiche 50-335,84/03/19,8403290109

- --8403290132 IE Insp Repts 50-335/63-43 & 50-387/83-71 on B31211-840130 Violation identified failure to maintain control room procedures in areas of administration operation emergency & off-normal B188.H E Region 2. Office of Director ELROD.S Division of Project & Resident Programs 64/02/08 App 22807 007 24X Fiche 50-335,84/03/19.8403290109
- 8403270247 Notifies that one pressurizer level transmitter W/radiant energy shield.will be separated.per App R.Section III G 2 F Fire detector will also be installed at each pump in intake cooling water pump area WILLIAMS, J W Florida Power & Light Co 84/03/21 EISENHUT D G Division of Licensing ip 22772 113 24X Fiche 50-335.84/03/21, 8403270247

H General correspondence

- 8403280149 Responds to 840208 ltr requesting assistance in responding to J Paskavitch ltr requesting latest EIS on concentrations of Sr-90.Cs-137 & I-131 near plants Two annual repts encl W/o repts
 DIRCKS.W J Office of the Executive Director for Derations 84/03/07 CHILES.L Senate. 4pp 22809 316 24X
 Fiche 90-000.84/03/07.8403280149
- --B403280156 Forwards constituent J Paskavitch itr requesting latest EIS on concentrations of Sr-90.Cs-137 & I-131 near plants Comments & views requested CHILES, L Senate B4/02/OB KAMMERER, C Office of Congressional Affairs 8pp 22809 320 24X Fiche 50-000.B4/03/07.8403280149

J Insurance & indemnity information

- 8403060234 Forwards Endorsement 52 to NELIA Policy NF-227 DUCK.J R Marsh & McLennan. Inc 84/02/28 SALTZMAN, J Assistant Director for State & Licensee Relations 2pp 22517 315 24X Fiche 50-335.84/02/28.8403060234
- P Operating license stage documents & correspondence
- 8401130296 Application to amend License DPR-67, deleting radiological effluent Tech Specs from App 8, environ protection plan HILLIAMS, J W Florida Power & Light Co 84/01/10 EIBENHUT, D G Division of Licensing 5pp 21801 135 24X Fiche 50-335,84/01/10,8401130296
- 8402210294 Forwards request for add1 info re reactor coolant pump seized rotor & loss of all nonemergency ac power accidents Apparent conflicts found in clarifying info W/o encl HILLER.J R Operating Reactors Branch 3 84/02/13 WILLIAMS.J W Florida Power & Light Co 1p 22323 360 24% Fiche 50-335. 84/02/13,8402210274
- 8403060077 Forwards Amends 62 & 5 to Licenses DPR-67 & NPF-16, respectively & safety evaluation Amends change personnel titles & revise shift technical advisor function SELLS.D E Operating Reactors Branch 3 84/02/24 WILLIAMS.J W Florida Power & Light Co 2pp 22549 020 24X Fiche 50-335.84/02/24.8403060077
- --B403060080 Amends 62 & 5 to Licenses DPR-67 & NPF-16, respectively, changing personnel titles & revising shift technical advisor functions
 MILLER, J R Operating Reactors Branch 3 B4/02/24 12pp
 22549 022 24X Fiche 50-335
- --8403060527 Safety evaluation supporting Amends 62 & 5 to Licenses PPR-67 & NPF-16 respectively * Office of Nuclear Reactor Regulation. Director 22549 034 24% Fiche 50-335,84/02/24.8403060077
- 8403050354 Requests requalification of electrical equipment at higher beta doses Completion of action within 60 days or submittal of proposed completion date within 15 days requested MILLER, J R Operating Reactors Branch 3 84/02/27 WILLIAMS, J W. Florida Power & Light Co 2pp 22501 333 24X Fiche 50-335,84/02/27,8403050354
- 8403040168 Notifies that administrative program & procedures now in effect will be reviewed to confirm implementation of recommended guidelines in NUTAC rept.per Generic Ltr 83-28 WILLIAMS, J C Florida Power & Light Co 84/03/01 EISENHUT, D G. Division of Licensing 19 22518 336 24X Fiche 50-000, 84/03/01, 8403040168

- B403120214 Forwards Amend 63 to License DPR-67 & safety evaluation Amend revises Tech Specs to change shutdown margin requirements, moderator temp coefficient limits & deletes flux peaking augumentation curve for Cycle 6 MILLER, J R Operating Reactors Branch 3 B4/03/01 WILLIAMS, J W Florida Power & Light Co 3pp 22619 253 24X Fiche 50-335,84/03/01.8403120214
- --8403120217 Amend 63 to License DPR-67, revising Tech Specs to change shutdown margin requirements, moderate temp coefficient limits 5 deleting flux peaking augumentation curve for Cycle 6 MILLER, J R Operating Reactors Branch 3 84/03/01 24pp 22619 256 24X Fichs 50-335,84/03/01,8403120214
- --8403120219 Safety evaluation supporting Amend 63 to License DPR-67 * Office of Nuclear Reactor Regulation, Director 84/03/01 30pp 22619 280 24X Fichs 50-335,84/03/01,8403120214
- 8403190150 Notifies of 840402-06 meeting & preimplementation audit at Turkey Point to discuss confirmatory items identified in safety evaluation of detailed control room design reviews for facilities VARGA.B A Operating Reactors Branch i 84/03/07 WILLIAM.J W Florida Power & Light Co 6pp 22681 311 24X Fiche 50-000.84/03/07.8403190150.
- 8403130066 Advises that request to revise Tech Bpecs to provide requirements for overtime limits & reporting of relief & safety valve failures will be submitted per Generic Ltr 82-16 (NUREG-0737) by 840515
 WILLIAMS, J W Florida Power & Light Co 84/03/08 MILLER, J R Operating Reactors Branch 3 ip 22601 252 24X
 Fichs 50-335,84/03/08,8403130066
- G Inspection reports. IE Bulletins & correspondence
- B403070034 Provides status of efforts in development of inservice insecretaries manual & plans for issuance.per IE Insert properties of 50-335/83-08 Manual should be in effect by 840315 WILLIAMB, J W Florida Power & Light Co 83/12/21 O'REILLY, J P Region 2. Defice of Director 3pp 22541 278 24% Fiche 50-335,83/12/21,8403070034
- 8403070140 Forwards IE Insp Repts 50-339/84-03 & 50-389/84-04 on 840118-20 No violations or deviations nated DANCE.H C Division of Project & Resident Programs 84/02/13 HILLIAMS.J W Florida Power & Light Co 2pp 22538 285 24) Fiche 50-335.84/02/13.8403070140
- --B403070145 lE Insp Repts 50-335/84-03 & 50-389/84-04 on 840118-20 No violations or deviations noted Major areas inspected emergency preparedness to assess on-shift prompt emergency classification & protective action recommendations DECKER.TR Region 2. Office of Director JENKINS.OR Division of Emergency Preparedness & Materials Safety 84/02/10 App 22538 287 24X Fiche 50-335.84/02/13.8403070140
- 8403160206 Forwards IE Insp Repts 50-335/84-04 & 50-389/84-05 on 840201-03 No violations or deviations noted DANCE.H C Division of Project & Resident Programs. 84/02/21 MILLIAMS.J W Florida Power & Light Co 2pp 22655 233 24X Fichs 50-335.84/02/21.8403160206
- --8403160210 IE Insp Repts 50-335/84-04 & 50-389/84-05 on 840201-03 No violations or devistions noted Major areas inspected maint & surveillance observation: plant operations: preoperational testing, procedures & low power testing KRUO, H E Region 2. Office of Director JAPE, F Division of Engineering & Operational Programs 84/02/13 4pp 22655 235. 24X Fiche 50-335,84/02/21.8403160206
- B403160264 Forwards IE Inso Repts 50-335/83-42 & 50-389/83-70 on 831101-1210 No violations or deviations noted DANCE.H C Division of Project & Resident Programs. 84/02/24 WILLIAMS.J W Florida Power & Light Co 2pp 22660 335. 24X Fiche 50-335.84/02/24.8403160264
- --8403160268 IE Insp Repts 50-335/83-42 & 50-389/83-70 on B31111-1210 No violations or deviations noted Major areas inspected; maint & surveillance observation, plant operations, LERs & IE info notices
 BIBB, H E Region 2, Office of Director ELROD, B A Division of Project & Resident Programs B4/02/23 10pp 22660, 337, 24X Fichs 50-335, 84/02/24, 8403160264
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22707 237 24X Fiche 50-000,84/02/28,8401190072

- B403120240 Forwards request for add1 info re util responses to IE Bullatin 80-i1, "Masonry Wall Design," in order to complete review Response requested by 840409 Technical evaluation rapts also encl MILLER, J R Operating Reactors Branch 3 B4/02/29 WILLIAMS, J W Florida Power & Light Co 7pp 22619 208 24X Fiche. 50-335,84/02/29,8403120240
- --8403120244 "Use of Joint Reinforcement in Block Masonry Walls," technical rept HAMID.A A. HARRIS,H G. Draxel Univ., Philadelphia, PA BECICA,I.J. Franklin Institute/Franklin Research Center 84/03/31 12pp 22619 215 24X Fiche 50-335,84/02/29,8403120240
- --B403120252 "Evaluation of Arching Theory in Unreinforced Masonry Walls in Nuclear Fower Plants " HAMID.A.A., HARRIB.H G Drexel Univ , Philadelphia, PA CON,V Franklin Institute/Franklin Research Center 83/06/30 5pp 22619
- 8403270317 Forwards IE Insp Repts 50-335/84-03 & 50-389/84-07 on 840206-10 No violations or deviations noted DANCE, H. C. Division of Project & Resident Programs 84/02/29 HILLIAMB, J. W. Florida Power & Light Co. 2pp. 22802 052 24: Fiche 50-335,84/02/29,8403290317
- --B403290320 IE Insp Repts 50-335/84-05 & 50-389/84-07 on 840204-10 No violations or deviations noted Major areas inspected health physics instrumentation, action on NUREQ-0737 Items. ALARA activities & followup on previous items HRAY, J. R. Region 2, Office of Director BARR, K.P. Division of Engineering & Operational Programs 84/02/22 Bpp 22802.054 24X Fiche 50-335,84/02/29,8403270317
- B402090007 IE Info Notice 84-i4, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list enci QRACE.J N Division of QA, Bafeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp. 22552 327 24X Fiche 50-000.84/03/02,8402090007
- 8402090008 IE Info Notice 84-14: "Failure of Automatic Sprinkler 8ys Valves to Derate" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000.84/03/02,8402090008
- B402090009 IE Info Notice 84-15, "Reporting of Radiological Releases " Svc list encl JDRDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York Inc 119pp 22553-217 24X Fichs 50-000,84/03/02,8402070009
- B403270174 Forwards IE Insp Repts 50-335/84-02 & 50-389/84-03 on B40111-0210 No violations or deviations noted. DANCE: H. C. Division of Project & Resident Programs 84/03/02 WILLIAMS: J W Florida Power & Light Co. 2pp 22803 076. 24X Fiche: 50-335:84/03/02:8403290174.
- ---8403270180 IE Insp Repts 50-335/84-02 & 50-389/84-03 on 840111-0210 No violations or deviations noted Major areas inspected maint observation, surveillance observation, plant operations & TMI Action Itsm III B 4 2.8 followup FEIERABEND.C , BIBB.M E Region 2. Office of Director. ELROD.8 A Division of Project & Resident Programs. 84/01/02 2pp 22803-078. 24X Fiche-50-335,84/03/02,8403290174
- B402090011 IE Info Notice B4-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Bvc list encl. JURDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/05 Consolidated Edison Co of New York, Inc. 117pp 22553 336 24X Fiche 50-000, 84/03/05, 8402090011
- 8402090024 IE Info Notice 84-09, Rev 1, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys." Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103), 84/03/07. Consolidated Edison Co. of New York, Inc. 118pp 22635:049 24X Fiche 50-000,84/03/07,8402090024
- B402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Bys." Svc list encl. JORDAN,E.L., Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22584-186. 24X Fiche 50-000;84/03/07,8402090028
- 840209003i IE Bulletin 84-02, "Failures of OE Type HFA Relays in Use in Class IE Safety Sys " Syc list enc! DEYDUNG, R C Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp. 22823-094. 24X Fiche. 50-000, 84/03/12, 8402090031

- 8403290109 Ack receipt of 840309 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-335/83-43 & 50-397/83-71

 DANCE, H C Division of Project & Resident Programs 84/03/19

 WILLIAMS, J W Florida Power & Light Co 1p 22807 001 24X

 Fiche 50-335,84/03/19,8403290109
- --8403290114 Responds to NRC 840202 ltr re violations noted in IE Insp Repts 50-335/83-43 & 50-389/83-71 Corrective actions all indexes reviewed against master copies & procedures in control room verified against indexes WILLIAMS, J W Florida Power & Light Co 84/03/09 O'REILLY, J P Region 2, Defice of Director 2pp 22807 002 24X Fiche 50-335, 84/03/19, 8403290109
- --8403270124 Forwards IE Insp Repts 50~335/83-43 & 50~369/83-71 on 831211-840110 & notice of violation DANCE.H C Division of Project & Resident Programs 84/02/10 WILLIAMS.JW Florida Power & Light Co 2pp 22807 004 24X Fiche 50~335.84/03/19.8403270109
- --8403290126 Notice of violation from insp on 831211-840110 * Region 2. Office of Director B4/02/10 ip 22807 006 24X Fiche 50-339, 84/03/19.8403290107
- --8403270132 IE Insp Repts 50-335/83-43 & 50-387/83-71 on 831211-840110 Violation identified failure to maintain control room procedures in areas of administration, operation, emergency & off-normal BIBB, H E Region 2. Office of Director ELRDD, 6 Division of Project & Resident Programs 84/02/08 4pp 22807/007 24X Fiche 50-335, 84/03/19,8403270109
- B402070043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Cunsolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Bys " Bvc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22733 001 24X Fiche 50-000,84/03/21,8402070044
- R Periodic operating reports & related correspondence
- B403020033 Monthly operating repts for Jan 1984 W/840215 1tr GRANT.N.W., WILLIAMS.J.W. Florida Power & Light Co. 84/01/31 19pp. 22442 235 24X Fiche 50-000.84/01/31.8403020033
- B403300173 Forwards monthly operating repts for Feb 1984 & corrected Page 1 of St Lucie Unit 2 monthly operating rept for Jan 1984
 HILLIAMS, J W Florida Power & Light Co 84/03/15 Office of Resource Management, Director 1p 22819 263 24X
 Fiche 50-000,84/03/15,8403300173
- --8403300185 Monthly operating repts for Feb 1984 GRANT,N.W Florida Power & Light Co 84/03/15 16pp 22819 264 24X Fiche 50-000,84/03/15,8403300173
- 8 Reportable occurrences, LERs & related correspondence
- B104220046 Forwards brief description of 801130 event at facility
 Licensees of operating C-E PWRs should be informed of
 concern re inadequacy in reactor protection sys test
 procedures
 MICHELSON, C Director's Office 81/04/15 JORDAN, E L Director's
 Office 3pp 22789 297 24X Fiche 50-335, 81/04/15, 8104220046
- 8210120303 Discusses ticensee actions re 811219 dual MSIV closures & pressurizer safety valve actuations Cause unidentified Proper corrective action implemented CINTULA,T C Reactor Operations Analysis Branch 82/09/24 SEYFRIT.K V Reactor Operations Analysis Branch 6pp 22789 309 24X Fiche 50-335,82/09/24,8210120303
- 8403220070 Updated LER 81-039/03L-1.on 810802.during power operation, PDRV block valve MVI403 would not close Caused by loose electrical connection on valve limit switch Connection tightened during Oct 1981 refueling W/840319 1tr ROTELLA.T.8. WILLIAMS.J W Florida Power & Light Co 84/03/19 2pp 22712 304 24X Fiche 50-335.84/03/19.8403220070

V Operator Examinations

8403080164 Forwards request for site visits to conduct operator licensing exams requested in Generic Ltr 83-40 MILLIAMS, J W Florida Power & Light Co 84/03/01 EISENHUT, D G Division of icensing 5pp 22559 293 24X Fiche 50-335.84/03/01.8403080164

DOCKET 50-336 MILLSTONE NUCLEAR POWER STATION, UNIT 2

F Security, medical, emergency & fire protection plans

- 8403260195 Rev 41 to emergency plan implementing procedure index & Rev 1 to Procedure EPIP 4305A. "Meteorological Tower Emergency Operations Facility Computer Terminal Operation " W/340309 ltr COUNSIL.W G , SEARS.C F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W G Northeast Utilities 84/02/15 EIESNHUT.D G Division of Licensing 14pp 22756 171 24% Fiche 50-245.84/02/15,8403260195
- 8403260143 Forwards general position statement on Reg Guide 1 97, Rev 2 re justification of significant generic deviations, per NUREC-0737, Suppl 1 COUNSIL, W G . SEARS, C F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Connecticut Yankee Atomic Power Co 84/02/29 MILLER, JR Operating Reactors Branch 3 CRUICHFIELD, D Operating Reactors Branch 3 Fiche 50-000,84/02/29,8403260143
- --8403260151 General position statement on Reg Guide 1 97.Rev 2 re instrumentation for assessing plant & environ conditions during & following accidents * Northeast Nuclear Energy Co (subs of Northeast Utilities) * Connecticut Yankee Atomic Power Co * Northeast Utilities 84/02/27 69pp 22758 165 24X Fiche 50-000,84/02/29,8403260143
- 8403150106 Forwards FEMA final exercise rept for 820319 joint exercise of state & local radiological emergency preparedness plans for facility Rept of 831005 exercise will be forwarded MARTIN.T T Pivision of Engineering & Technical Programs 84/03/09 COUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 22640 142 24X Fiche 50-336.84/03/09.8403150106
- B403190243 Notification of B40418 workshop in King of Prussia.PA to discuss lessons learned from recent App R fire protection safe shutdown insp & topics described in IE Info Notice 84-09 Agenda far workshop ent!

 HURLEY.TE Region I. Office of Director 84/03/09 O'TOULE.JD Consolidated Edison Co of New York. Inc KANDA.BK General Public Utilities GPU Service Corp MODLEVER.E J Duquesne Light Co 35pp 22672 062 24X Fiche 50-000.84/03/09.8403190243
- B403260146 Forwards revised procedures for corporate organization for nuclear incidents procedure manual, including Procedure CONI 1 of recorporate emergency operations ctr operations W/o encl COUNSIL.H G . SEARS.CF Connecticut Yankee Atomic Power Co CQUNSIL.H G . Northeast Nuclear Energy Co (subs of Northeast Utilities) 84/03/09 EISENHUT.D G Division of Licensing 2pp 22750 330 24x Fiche 50-000.84/03/09.84032260146
- 8403220136 Provides results of reevaluation of performance assessment, per util 831219 ltr addressing topics discussed at 831129 SALP mgt meeting Category 1 rating will be assigned to refueling area for Millstone 2 Explains Category 2 ratings MURLEY.TE Region 1. Office of Director 84/03/16 COUNBIL.W 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) 4pp 22716 047 24X Fiche 30-000.84/03/16.8403220136
- 8403270009 Informs that util will provide info re planned deviations from Suppl 1 to NUREC-0737 by 840501 Delay has no effect on schedules for implementation of Suppl 1 to NUREG-0737 COUNSIL.W 0 SEARS.CF Connecticut Yankee Atomic Power Co COUNSIL.W 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) 84/03/16 EISEN,EUT.D 0 Division of Licensing, 2pp 22770 011 24X Fithe 50-000.84/03/16.8403270008
- 8403300084 Advises that 831214 Rev 18 to security plan & 840110 Rev 2 to training & qualification plan consistent w/provisions of 10CFR50 54(p) & acceptable MARTIN:T T Division of Engineering & Technical Programs 84/03/26 CDUNSIL:M G Northeast Nuclear Energy Co (subs of Northeast Utilities) 3pp 28822 014 24X Fiche 50-245:84/03/26:8403300084

- P Operating license stage documents & correspondence
- 8403080344 FOIA request for documents re proposed NSHC determination on license amends for Millstone 2 & entry into operational mode for conducting final tests of pressurizer safety valves at Trojan ADATO, M. Union of Concerned Scientists 84/02/02 FELTON, J. M. Division of Rules and Records ip 22583 038 24X Fiche 30-000.84/02/02.8403080344
- B403060494 Forwards Amends 75 & 72 to Licenses DPR-21 & DPR-45, respectively Amends change Tech Specs to comply w/final rule on licensed operator staffing CRUTCHFIELD.D Operating Reactors Branch 5 84/02/16 CQUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 3pp 22511 193 24x Fichs 50-245.84/02/16.8403060494
- --8403060459 Amends 95 & 92 to Licenses DPR-21 & DPR-65, respectively, changing Tech Specs to comply w/final rule on licensed operator staffing GRUTCHFIELD. Deperating Reactors Branch 5 84/02/16 14pp 22511 196 24X Fiche 50-245,84/02/16,8403060454
- 8403010235 Submits info re NUREC-0737. Items II E 1 2. "Bafety Grade Auxiliary Feedwater Bys Initiation & Flow Indication" & II K 3 3. "Reporting of Bafety & Relief Valve Failures & Challenges." per util 81230 ltr & Generic Ltr 82-16 COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) OCUNSIL.W G Northeast Utilities 84/02/21 MILLER, JR. Operating Reactors Branch 3 3pp 22434 188 24X Fiche 50-336.84/02/21.8403010235
- 8403050105 Advises that operability testing of RCS vent valves will be performed per requirements of ABME, Section XI, Subsection IW-3410, for Category B valves, per NUREO-0737. Item II B 1 CDUMBIL. W G CONNESTL. W G CONNESTL. W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNBIL. W G Northeast Utilities B4/02/21 MILLER, J R Operating Reactors Branch 3 CRUTCHFIELD, D Operating Reactors Branch 3 CRUTCHFIELD, D Operating Reactors Branch 5 2Pp 22488 043 24X Fiche 50-000, 84/02/21, 8403050105
- 8403090257 Advises that GE Cask IF-300 will be utilized for disposal of thermal shield Three shipments to Barnwell, BC disposal site in spent fuel railroad transportation cask planned COUNSIL, W 0, OPEKA, J F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) COUNBIL, W 0 Northeast Utilities, 84/02/24 MILLER, J R Operating Reactors Branch 3 2pp 22573 257, 24X Fiche 50-336,84/02/24,8403090257
- 8403090272 Notifies that submittal date for STS addressing NUREG-0737 items.per Coneric Ltr 83-37.rescheduled for 840305 CDUNBIL.W 0 Connecticut Yankse Atomic Power Co CDUNBIL.W 0, Northeast Nuclear Energy Co (subs of Northeast Utilities) CDUNBIL.W 0 Northeast Utilities. 84/02/24 EISEN-NUT.D 0 Division of Licensing 2pp 22572 176 24X Fiche 50-336,84/02/24,8403090272
- B403070304 Provides responses to three open items from NRC/BNL Yankee Atomic Electric Co & consultants Mark I containment program plant-unique analysis rept B40216 review meeting CELIA:N S Teledyne Engineering Services B4/02/28 SIEGEL, B NRC No Detailed Affiliation Given 4pp 22546 171, 24X Fiche 30-000.84/02/28.8403070304
- B403130027 Informs that Amends 54.92 & 87 to Licenses DPR-61, DPR-21 & DPR-65, respectively, inadvertently eliminated reporting requirements for exceeding radiological limiting conditions for operation Corrective actions identified COUNSIL.9 On Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNBIL.9 G Connecticut Yankee Atomic Power Co COUNBIL.9 On Northeast Utilities 84/03/01 MILLER.9.R Operating Reactors Branch 3 CRUTCHFIELD.D Operating Reactors Branch 5.
- 8403080347 Partial response to FDIA request for documents re proposed NBMG determinations for Millstone 2 & entry into operational mode for conducting final tests of pressurizer safety valves at Trojan Forwards App B documents FELTON. J M Division of Rules and Records 84/03/02 ADATO, M Union of Concerned Ecienchists 4pp 22583 037 24X Fiche 50-000,84/03/02,8403080347
- --B312230261 Evaluates util B31102 arguments to support validity of previous LOCA analyses for removal of thermal shield from core barrel Reanalysis of small break LOCAs not required Restart approved subj to confirmation of peak clad temp. HOUSTON,R W Assistant Director for Reactor Safety, B3/12/13 LAINAS,G C Assistant Director for Operating Reactors. 2pp. 22583 040 24X Fiche 50-000,84/03/02,8403080347.

- --8403080352 Returns request for publication in FR of notice of consideration of issuance of amend to QL & proposed NSHC determination re Tech Spec changes resulting from Cycle & refueling considerations Revs requested W/o enc!

 RDTHSCHILD,M U Office of the Executive Legal Director CLARK.R A Operating Reactors Branch 3 ip 22583 059 24X Fiche 50-000,84/03/02,8403080347
- 8403140222 Notifies that Class III fee appropriate for review of 831012 proposed Tech Spec changes re mod of pressurizer level band DIGGS.R M License Fee Management Branch 84/03/07 COUNSIL.W C Northeast Nuclear Energy Co (subs of Northeast Utilities) 1p 22637 330 24X Fiche 30-336,84/03/07.8403140222
- B403260200 Comments on Issue 3 of NUREG-0885, "NRC Policy & Planning Guidance, 1984" Seven themes identified represent important objectives for industry GUNBIL.N G Northeast Utilities 84/03/12 DIRCKS, W J Office of the Executive Director for Operations 4pp 22756 204 24X Fiche 50-000, 84/03/12,8403260200
- B403260145 Submits details of followup actions on Amend 90 to License DPR-65 Adequate Justification provided to demonstrate applicability of current large break LOCA evaluation for operation w/o thermal shield COUNSIL.W O. Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W O. Northeast Utilities B4/03/13 MILLER, J. R. Operating Reactors Branch 3 2pp 22750 328 24X Fiche 50-336.84/03/13,8403260145
- 8403270081 Forwards response to NRC concerns re 840104 application to amend Tech Specs, revising pressure-temp limits & max heat-up rate for RCS & reactor vessel matl radiation specimen withdrawal schedule CDUNBIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNBIL.W G Northeast Utilities 84/03/16 MILLER, JR Operating Reactors Branch 3 10pp 22769 232 24X Fichs 50-336,84/03/16,8403270081.
- 8403210070 Forwards Amends 96 & 93 to Licenses DPR-21 & DPR-65, respectively Amends consist of changes to Section 6 of Tech Specs re nuclear review board, reorganization & STS CRUTCHFIELD, D. Operating Reactors Branch 5 84/03/19 COUNBIL, W.G. Northeast Nuclear Energy Co. (subs of Northeast Utilities) &pp 22705 089 24X Fiche 50-245,84/03/19,8403210070
- --8403210079 Amends 96 & 93 to Licenses DPR-21 & DPR-65, respectively, consisting of changes to Section 6 of Tech Specs re nuclear review board, reorganization & STB CRUTCHFIELD, D Operating Reactors Branch 5 84/03/19 23pp 22705 095 24X Fichs 50-245,84/03/19,8403210070
- 8403290230 Forwards Class III fee for 831012 Tech Spec change request, in response to NRC 840307 request COUNSIL.H.G Northeast Nuclear Energy Co. (subs of Northeast Utilities) COUNSIL.H.G Northeast Utilities 84/03/22 DIO
- Q Inspection reports, IE Bulletins & correspondence
- B403050352 Forwards request for add1 info re IE Bulletin B0-11,
 "Masonry Wall Design " Info required within 60 days of
 1tr receipt
 MILLER, J R. Operating Reactors Branch 3 84/02/24, COUNSIL, W G
 Northeast Nuclear Energy Co (subs of Northeast Utilities) 7pp
 22519 243 24X Fiche 50-336,84/02/24,8403050352
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JURDAN, E. L. Division of Emergency Presentations & Engineering
 - JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc. 115pp 22707 239. 24X Fichs 50-000,84/02/28,8401170072
- B402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE, N Division of QA, Safeguards & Inspection Programs (Post 830103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp. 22552,329 24X Fichs 50-000,84/03/02,8402090007
- 8402070008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate." Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York: Inc 122pp 22553 098 24X Ficha 50-000.84/03/02,8402070008
- B402070007 IE Info Notice 84-15. "Reporting of Radiological Releases."

 Byc list encl

 JORDAN EL Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York Inc 119pp 22553 217 24X Fiche 50-000, 84/03/02, 8402070007

- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co. of New York, Inc. 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8402090024 IE Info Nutice 84-09, Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000,84/03/07,8402090024
- 8402070028 IE Info Notice 84-i8, "Stress Corrosion Cracking in PWR 8ys " Svc list enc] JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc. 118pp 22584 186 24X Fiche 30~000,84/03/07,8402070028
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 074 24X Fiche 50-000.84/03/12.8402090031
- 8403220136 Provides results of reevaluation of performance assessment, per util 831219 ltr addressing topics discussed at 831129 SALP mgt meeting Category I rating will be assigned to refueling area for Millstone 2 Explains Category 2 ratings MURLEY.T E Region 1, Office of Director 84/03/16 COUNSIL,W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 4pp 22716 047 24X Fiche 50-000,84/03/16.8403220136
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 2282 229 248 Fiche 50-000.84/03/21,8402090043
- 8402070044 IE Info Notice 84-20. "Svc Life of Relays in Safety-Related Sys " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22733 001 24X Fiche 50-000,84/03/21,8402070044
- 8403300144 Responds to IE Bulletin 83-08. "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Sys " Haddam Nock facility uses 31 Westinghouse-type DB breakers COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W G Connecticut Yankee Atomic Power Co COUNSIL, W G Northeast Utilities 84/03/21 MURLEY, T E Region 1. Office of Director 4pp 22820 048 24X Fiche 50-000,84/03/21.
- 8409300086 Ack receipt of 840224 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-245/83-20 & 30-336/83-28 MARTIN,T T Division of Engineering & Technical Programs 84/03/23 COUNBILL W J Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 28822 017 24X Fichs 50-245/84/03/23/8403300086
- --8403300072 Responds to NRC B40125 ltr re violations noted in IE Insp Repts 50-245/83-20 & 50-336/83-28 Corrective actions Procedure CP B97A rewritten to include method of determining hi & hi-hi alarm setpoints COUNSIL.W G Northeast Nuclear Frency Co (subs of Northeast Utilities) COUNSIL.W G Northeast Utilities B4/02/24 MURLEY.T E Region 1. Office of Director 2pp 22822 017 24X Fichs 50-245,84/03/23,840330088
- R Periodic operating reports & related correspondence
- 8403230022 "Haddam Neck Plant & Milistone Station Units 1 & 2 Annual Rept.1983 " W/840301 ltr COUNBIL.W 0 . BEARS.C F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNBIL.W 0 Connecticut Yankee Atomic Power Co 83/12/31 MURLEY.T.E Region 1. Office of Director 34Bpp 22727 001 24X Fiche 50-000.83/12/31.8403230022
- 8403020133 Monthly operating rept for Jan 1984 W/840213 ltr 91880N.J., MROCZKA,E.J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) MROCZKA,E.J. Northeast Utilities 84/01/31 6pp 22441 351 24X Fiche 50-336,84/01/31,8403020133
- 8403120135 Forwards "Semiannual Radioactive Effluents Release Rept.
 Jul-Dec 1983" Offsite dose estimates not included due to
 estimate delays Complete rept will be resubmitted by 840430
 GOUNBIL.W G. OPEKA, J F. Northeast Nuclear Energy Co. (subs of
 Northeast Utilities) COUNBIL.W G. Northeast Utilities. 84/02/28
 MURLEY, T E. Region 1, Office of Director 1p 22590 076 24X
 Fiche 50-245,84/02/28,8403120135

- --8403120138 "Semiannual Radioartive Effluents Release Rept. Jul-Dec 1783 " • Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/12/31 42pp 22590 097 24% Fiche 50-245.84/02/28.8403120135
- 8403300080 Monthly operating rept for Feb 1984 W/840313 ltr GIBSON, J. MRGCZKA, E. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) MRGCZKA, E. J. Northeast Utilities 84/02/29 App. 22821 175 24X Fiche 50-336
- S Reportable occurrences. LERs & related correspondence
- 8211150076 Discusses events involving loss of electrical inverters including attendant inverters to vital instrument buses. Recommendations provided by Nuclear Safety Analysis Ctr are excellent in helping to reduce instrument failures. ASHLF Reactor Operations Analysis Branch 82/10/21 SEYFRIT. K V Reactor Operations Analysis Branch 8pp 22775 223 24X Fiche 50-000.82/10/21.8211150076
- 8403230171 Forwards Technical Review Rept AEOD/T314, "Improper Size of Inlet Piping to Primary Safety Valves"
 IMBRULE Reactor Operations Analysis Branch 83/05/24
 SEYPRIT.K V Reactor Operations Analysis Branch 1p 22759 297
 24X Fiche 50~000.83/05/24.8403230171
- --8403230175 "Improper Size of Inlet Piping to Primary Safety Valves," technical review rept Reduced diameter inlet piping does not represent safety concern IMBRO.E V Director's Diffice 83/05/24 Rpp 22759 298 24X Fiche 50-000,83/05/24,8403230171
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines. Gampal NPS-4 T&T valve to close Encl ltr dtd 840203 sent to listed utils GS notified of affected units in BHR plants

 THERROYS. R Terry Corp 84/02/22 WOODRUFF. R W Director's Office of Inspection and Enforcement App 22704 327 24% Fiche 50-000.84/02/22.8403210032
- 8403010219 LER 84-005-00 on 840128, during Type 8 & C containment penetration local leak rate test-combined leakage rates exceeded Tech Spec 3 & 1 2 b limits Caused by mechanical deficiencies Isolation valves repaired W/840227 ltm FOSTER. E R . MROCZKA. E J Northeast Nuclear Energy Ca (subs of Northeast Utilities) MRGCZKA. E J Northeast Utilities 84/02/27 3pp 22436 019 24X Fiche 50-336,84/02/27,8403010219
- 8403200113 LER 84-006-00 on 840213.12 of 16 primary coolant loop RTDs exceeded Tech Spec Limit of B s or less during respose time testing Caused by time constant for element installation in thermousl E sensor thermousl mismatch W940314 Ltr BRIMMMAN.5. HERBERT.R J. HROCZWALE J Northeast Nuclear Energy Co (subs of Northeast Utilities) 84/03/14 5pp 22697 111 24X Fichs 50-336.84/03/14.8403200113
- DOCKET 50-338 NORTH ARNA POWER STATION, UNIT 1
- F Security, medical, emergency & fire protection plans
- 8403070239 Forwards SALP Repts 50~280/83-33.50-281/83-35,50-338/83-33 & 50-339/83-33 for Oct 1982 Aug 1983 Evaluation will be discussed at 831208 meeting at North Anna site LEWIS, R C Division of Project & Resident Programs 83/11/25 STEMART, W L Virginia Electric & Power Co 2pp 22536 227 24X Fiche 50-000,83/11/25,8403070239
- --8403070246 SALP Repts 50-280/83-33.50-281/83-33.50-239/83-33 & 50-239/83-83 for Oct 1982 Aug 1983 Reliable performance Wimprovement in most previously noted areas of weakness demonstrated * Region 2, Office of Director 83/11/25 42pp 22536 229 24 Fiche 50-000,83/11/25,8403070239
- 8403050462 Grants 831031 request for examption from requirements of App R to 10CFR50.Section III G 3 b re installing fixed fire suppression sys in control room Exemption encl MILLER. J R Operating Reactors Branch 3 84/02/23 STEWART. W L Virginia Electric & Power Co ip 22549 331 24X Fiche 50-338.84/02/23.8403060462
- --8403060466 Etemption from requirements of App R to 10CFR50. Bection III G 3 b re installing fixed fire suppression sys in control room EISENHUT.D.O Division of Licensing 84/02/23 Virginia Electric & Power Co 4pp 22547 332 24X Fiche 50-338.84/02/23.

- 8403190263 Rev 1 to corporate emergency response plan W/840315 ltr STEMART.W L. Virginia Electric & Power Co. 84/02/24 O'REILLY, J P Region 2. Office of Director 105pp 22670 135 24x Fiche 50-000.84/02/24.8403190263
- 8403050198 Forwards Amends 51 & 35 to Licenses NPF-4 & NPF-7, respectively & safety evaluation Amends revise Tech Specs to reflect addition & installation of new fire protection sys M/o encl
 ENGLE.L B Operating Reactors Branch 3 84/02/28 STEWART.W L Virginia Electric & Power Co 1p 22528 184 24X
 Fiche 50-338.84/02/28.8403050198
- 8403080264 Forwards "Control Ruom Design Review Program Plan for North Anna & Surry Power Stations." in response to Suppl I to NUREG-0737 Review expected to be completed by 850830 STEMART.W L Virginia Electric & Power Co 84/03/01 DENTON, H R Office of Nuclear Reactor Regulation, Director EISENHUT, D o Division of Licensing 2pp 22557 295 24% Fiche 50-000,84/03/01, 8403080264
- --8403080269 "Control Room Design Review Program Plan for North Anna & Surry Power Stations," in response to Suppl 1 to NUREQ-0737 = Virginia Electric & Power Co 84/03/01 111pp 22557 279 24X Fiche 50-000.84/03/01.8403080264
- 840308009; Submits add1 info in order to conduct detailed review of penergency response procedures generation package.per 840125 request Items : & 2 will be addressed by 840930 Item 3 should be addressed by Westinghouse Cuners Group STEWARTW L Virginia Electric & Power Co 84/03/02 DENTON, H R. Office of Nuclear Reactor Regulation, Director EISENHUT, D. 0. Division of Licensing 2pp 22559 199 24X Fiche 50-000,84/03/02,8403080091
- 8403160276 Extends invitation to attend 840316 workshop at regional ofc to discuss iOCFR90. App R requirements & results of insps to help resolve misunderstandings associated w/requirements LEMIS.R C Division of Project & Resident Programs 84/03/02 STEMART.W L Virginia Electric & Power Co ip 2R660 OBO. 24X Fiche 50-000.84/03/02.8403160276
- 8403260273 Forwards corrected Tech Spec pages for Amends 51 & 35 to Licenses NPF-4 & NPF-7, respectively, covering axial power distribution monitoring sys, penetration fire barriers & fire detection instrumentation ENOLE-L B Operating Reactors Branch 3 84/03/06 STEMART, W L Virginia Electric & Power Co ip 22761 343 24x Fiche 50-338.84/03/06.8403260273
- ~-84032602Bl Corrected Tech Spec pages to Amends 51 & 35 to Licenses NPF-4 & NPF-7, respectively, covering axial power distribution monitoring sys, penetration fine barriers & fire detection instrumentation

 # Operating Reactors Branch 3 84/03/06 15pp 22761:344, 24x Fiche 50-338,84703/06,8403260273
- 8403190052 Informs that local emergency operations facilities at North Anna & Surry Power Stations will be functional, except for data communications & display. by 850731, per NUREO-0737, Suppl
- STEWARY, W.L. Virginia Electric & Power Co. 84/03/14, DENTON, H.R. Office of Nuclear Reactor Regulation, Director EISENHUT, D. G. Division of Licensing 2pp 22666-173 24% Ficher \$0-000, 84/03/14, 8403170052
- 8403290250 Ack receipt of 840306 ltr informing NRC of steps taken to correct violations noted in 16 Insp Repts 50-338/83-31 & 50-339/83-31 & LEWIS.R C Division of Project & Resident Programs 84/03/16 STEWART.W L Virginia Electric & Power Co ip 82802 032 24X Fiche 80-338,84/03/16,8403290250
- ~-8403290260 Responds to NRC 840207 ltr re violations noted in 1E Insp. Repts 50-338/83-31 & 50-339/83-31 Corrective actions: wall classified as fire barrier & cubicles reclassified as seperate Fire areas Procedure revised to include insp. STEMART.W. Uriginia Electric & Power Co. 84/03/06 O'REILLY.J.P. Region 2. Office of Director. 3pp. 22802-033 24X Fichs 50-338,84/03/16,8403290250
- ~-8403270267 Forwards IE Insp Repts 50-338/83-31 & 50-339/83-31 on 831206-840105 & notice of violation LEHIBA C Division of Project & Resident Programs 84/02/07. BIEMART, H L Virginia Electric & Power Co 2pp. 22802:036 24x Fiche 50-338,84/03/16,8403290250
- ~-B403270280 Notice of violation from insp on 831206-840105. * Region 2, Office of Director 84/02/07 2pp. 22802:038 24% Fichs 50-338,84/03/16,8403290250

- --B403270271 IE Insp Repts 50-338/83-31 & 50-339/83-31 on B31206-B40105 Noncompliance noted failure to maintain procedures re insp of wall & failure to inspect fire barriers LUEHMAN.J G Region 2, Office of Director ELROD.S Division of Project & Resident Programs B4/02/06 9pp 22802 040 24X Fiche 50-338,84/03/16.B403290250
- 8403290184 Forwards FEMA final rept for 830618 emergency exercise DANCE:H C Division of Project & Resident Programs 84/03/19 STEWART.W L Virginia Electric & Power Co ip 22802 174 24) Fiche 50-338,84/03/19.8403290184
- J Insurance & indemnity information
- 8403140047 Endorsement 47 to NELIA Policy NF-240 * Nuclear Energy Liability Insurance Association 84/03/01 ip 22634 164 24X Fiche 50-338,84/03/01,8403140047
- P Operating license stage documents & correspondence
- B403080179 Fourth pertial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of addl documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, S I Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000,84/02/13.8403080179
- B403070001 Notifies that Class III & Class I fees submitted w/820608 application for amend will be refunded, based on B40123 withdrawal of application MILLER, W D License Fee Management Branch B4/02/24 STEWART, W L Virginia Electric & Fower Co ip 22562 343 24X Fiche 50-338,84/02/24,8403070001
- 8403020195 Forwards add1 info to complete review of Topical Rept
 VEP-FRD-41: "VEPCO Reactor Sys Transient Analysis Using
 RETRAN Computer Code." in response to NRC Nov 1982 informal
 request
 STEWART.W L Virginia Electric & Power Co 84/02/27 DENTON,H R
 Office of Nuclear Reactor Regulation, Director EISENHUT.D.Q
 Division of Licensing 16pp 22443 257 24X Fiche 50-000,84/02/27,
- 8403050227 Bubmits review of post-accident sampling sys, Item II.8 3 Ten of 11 criteria met Remaining criterion re procedure for estimating extent of core damage based on radionuclide evaluation; acceptable on interim basis
 MILLER, J R Operating Reactors Branch 3 84/02/27 STEWART, W L Virginia Electric & Power Co. 6pp 22528 001 24X
 Fiche. 50-000, 84/02/27, 8403050229
- 8403020001 Requests interim approval of inservice insp & testing requirements for pumps & valves Approval would increase scope of insp & testing & enhance safety Implementation of revised inservice testing programs expected by 840315 STEWART,W L Virginia Electric & Power Co 84/02/28 DENTON,H R Office of Nuclear Reactor Regulation, Director MILLER,J R Operating Reactors Branch 3 2pp 22442:155 24X Fiche 50-338,84/02/28,8403020001
- 8403020042 Forwards revs to inservice testing program for pumps & valves.clarifying previous submittals
 STEMART.W L. Virginia Electric & Power Co 84/02/28 DENTON,H R
 Office of Nuclear Reactor Regulation, Director Miller, J R
 Operating Reactors Branch 3 15pp 82442 272 24X
 Fiche 30-938.84/02/28,8403020042
- 8403050198 Forwards Amends 51 & 35 to Licenses NPF-4 & NPF-7, respectively & safety evaluation Amends revise Tech Specs to reflect addition & installation of new fire protection sys W/o encl ENCLE, L B Operating Reactors Branch 3 84/02/28 STEWART, W. L Virginia Electric & Power Co. 1p 22528 184, 24x Fiche, 50-338, 84/02/28, 8403050178
- 8403120176 Advises that 11 6% permit responsibility transferred to Old Dominion Electric Cooperative on 831221, per 840131 ltr Requests NPDES permit & 401 certificate dtd 720211 be modified to reflect transfer W/o stated shcl TAYLOR, J.A. Virginia Electric & Power Co. 84/03/01 BURTON, R.M. Virginia, Commonwealth of, 1p. 22590 203. 24% Fiche 50-338,84/03/01,8403120176
- 8403210203 Forwards Amends 52 & 36 to Licenses NPF-4 & NPF-7, respectively Amends clarify testing requirements in Tech Spec Table 3 6-1 re containment isolation valves.
 ENGLE, L. B. Operating Reactors Branch 3 84/03/06 STEWART, W. L. Virginia Electric & Power Co. 3pp. 22709 192 24X
 Fiche: 50-338, 84/03/06, 8403210203

- --B403210206 Amends 52 & 36 to Licenses NPF-4 & NPF-7, respectively, clarifying testing requirements in Yech Spec Table 3 6-1 re containment isolation valves MILLER, JR Operating Reactors Branch 3 B4/03/06 9pp 22709 195 24X Fiche 50-338,84/03/06,8403210203
- 8403220208 Forwards Amend 53 to License NPF-4 & safety evaluation Amend revises Tech Spec Table 4 3-2 by removing requirement for surveillance in Mode 4 for auxiliary feedwater pump actuation signals ENGLE.L B Operating Reactors Branch 3 84/03/06 STEWART, W L Virginia Electric & Power Co 2pp 22723 266 24X Fiche 50-338.84/03/06.8403220208
- --8403220212 Amend 53 to License NPF-4.revising Tech Spec Table 4 3-2 by removing requirement for surveillance in Mode 4 for auxiliary feedwater pump actuation signals MILLER.J R Operating Reactors Branch 3 84/03/06 5pp 22723 268 24% Fiche 50-338.84/03/06.8403220208
- B403260273 Forwards corrected Tech Spec pages for Amends 51 & 35 to Licenses NPF-4 & NPF-7, respectively, covering axial power distribution monitoring sys, penetration fire barriers & fire dataction instrumentation ENGLE.L B Operating Reactors Branch 3 84/03/06 STEWART, W L Virginia Electric & Power Co | Ip 22761 343 24X Fiche 50-338,84/03/06,8403260273
- --8403260281 Corrected Tech Spec pages to Amends 51 & 35 to Licenses NPF-4 & NPF-7, respectively, covering axial power distribution monitoring sys, penetration fire barriers & fire detection instrumentation # Operating Reactors Branch 3 84/03/06 15pp 22761 344 24X Fiche 50-338,84/03/06.8403260273
- B403130298 Provides implementation ltr rept for reactor vessel level instrumentation sys.per NRC 640116 ltr & TMI Action item II F 2 Requests NRC approve use of installed reactor vessel level instrumentation based on previous acceptance STEMART.W.L. Virginia Electric & Power Co. 84/03/07 DENTON.H R Office of Nuclear Reactor Regulation, Director EISENHUT.D 0 Division of Licensing 3pp 22607 360 24% Fiche 50-338,84/03/07,84/0310298
- 8403190377 Application for amend to Licenses NPF-4 & NPF-7, changing Tach Specs to delete requirements for min & max temp limits for A36 & A572 beams in steam generator supports & determination of beam temps

 STEWART, W L Virginia Electric & Power Co 84/03/15 DENTON, H R Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3 3pp 22675 237 24x

 Fiche 50-338.84/03/15,8403190377
- --8403190381 Proposed Tech Specs deleting requirements for min & max temp limits for A36 & A572 beams in steam generator supports & determination of beam temps Request for removal of steam generator support heaters & insulating tent encl * Virginia Electric & Power Co 84/03/15 30pp 22675 240 24% Fiche 50-338,84/03/15,8403190377
- 8403220028 Application for amend to Licenses NPF-4 & NPF-7, revising Tech Specs to reflect new LER sus, per 10CFR50, 73 & immediate notification requirements, per 10CFR50 72 STEMART.W L Virginia Electric & Power Co 84/03/16, DENTON, H R Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3 4pp 22713 128 24x Fiche 50-338,84/03/16,8403220028
- --8403220032 Proposed Tech Spacs reflecting new LER sys & immediate notification requirements

 * Virginia Electric & Power Co 84/03/16 85pp 22713 132 24X Fiche 30-338,84/03/16,8403220028
- 8403220077 Requests exemption from 10CFR50 44(c) (3) (iii) requirements, Operability of reactor vessel head vents should be varified during proposed outages & procedures & training implemented whrevised swergency operating procedures GTEWART, W.L. Virginia Electric & Power Co. 84/03/16. DENTON, H.R. Office of Nuclear Reactor Regulation, Director MILLER, J.R. Operating Reactors Branch 3. 2pp. 22712 311 24X Fiche 50-338,84/03/16.8403220077
- B40327020B Forwards voucher check for required license amend fees omitted from B40315 ltr STEWART,W L Virginia Electric & Power Co 84/03/23 DENTON,H R Office of Nuclear Reactor Regulation. Director MILLER.J R Operating Reactors Branch 3 ip 22772 084 24X Fichs 50-338,84/03/23,8403270208

- 8403300028 Forwards response to 840116 request for add) info re core exit thermocouple (CETC) & subcooling margin monitoring sys, per 840430 commitment CETC add) info deferred until after 840801 due to sys replacement.per Reg Guide 1 97 STEWART.W L Virginia Electric & Power Co. 84/03/23 DENTON.H R Office of Nuclear Reactor Regulation, Director EISENNUT.D C Division of Licensing 4pp 28821 307 24X Fiche 50-338.84/03/23.8403300028
- 8403300005 Informs that independent testing lab conducting overvoltage tests on motor control ctr contactor coils Current schedule for completing tests is May 1984 Resolution & related schedule will be submitted by Jul 1984 STEWART. W. L. Virginia Electric & Power Co. 84/03/26 DENTON. H R Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3 ip 22822 125 24X Fiche 50-338.84/03/26.8403300005
- Q Inspection reports. IE Bulletins & correspondence
- 8403070239 Forwards SALP Repts 50-280/83-33, 50-281/83-35, 50-338/83-33 & 50-339/83-33 for Oct 1982 Aug 1983 Evaluation will be discussed at 831208 meeting at North Anna site LEMIS.R C Division of Project & Resident Programs 83/11/25 STEWART.W L Virginia Electric & Power Co 2pp 22536 227 24X Fiche 50-000,83/11/25.8403070239
- --8403070246 SALF Repts 50-280/83-33, 50-281/83-35, 50-338/83-33 & 50-339/83-33 for Oct 1982 Avg 1983 Reliable performance w/improvement in most previously noted areas of weakness demonstrated * Region 2, Office of Director 83/11/25 42pp 22534 229 24% Fiche 50-000, 83/11/25, 8403070239
- 8403070279 Discusses SALP evaluation Issuance of SALP rept approved No major weaknesses identified during assessment period at North Anna One major weakness identified in area of radiological controls at Surry O'REILLY, JP Region 2, Office of Director 84/02/16 STEWART, W L Virginia Electric & Power Co 2pp 22541 286 24X Fithe 50-000,84/02/16,8403070279
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc. 115pp 22707 237 24% Fiche 50-000,84/02/28,8401190072
- 8403020001 Requests interim approval of inservice insp & testing requirements for pumps & valves Approval would increase scope of insp & testing & enhance safety implementation of revised inservice testing programs expected by 840315 STEWART.W. L. Virginia Electric & Power Co. 84/02/28 DENTON, H R Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3 2pp 22442 155 24X Fiche 50-338.84/02/28.8403020001
- 8402090007 IE Info Notice 84-14. "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE.J N Division of GA. Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fische 50-000.84/03/02.8402090007
- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list enc! JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 122pp 2253 098 24% Fiche 50-000.84/03/02,8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases"
 Bvc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc. 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8403160154 Responds to IE Bulletin 83-08 re electrical circuit breakers w/undervoltage trip feature in use in safety-related applications other than trip sys Unity reactor trip breakers contain subj trip attachments
 BTEWART.W L Virginia Electric & Power Co 84/03/02 O'REILLY, J P Region 2. Office of Birector 2pp 22806 008 24X
 Fiche 50-000.84/03/02.8403160154
- 8402090011 IE info Notice 84-17. "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp "Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117gp 22583 336 24X Fiche 50-000,84/03/05,8402090011

- 8403270287 Forwards IE Insp Repts 50-338/84-01 & 50-339/84-01 on 840106-0205 No violations or deviations identified DANCE.H C Division of Project & Resident Programs 84/03/05 STEHART.H L Virginia Electric & Power Co 2pp 22800 048 24X Fichs 50-338.84/03/05.8403270289
- --8403290294 IE Insp Repts 50-338/84-01 & 50-339/84-01 on 840106-0205 No violations or deviations identified Major areas inspected onsite areas of surveillance & maint activities, previous insp findings & identified items & safety sys walkdowns BRANCH, M W . LUEHMAN, J G Region 2. Office of Director ELROD, B Division of Project & Resident Programs 84/03/02 lOpp 22800 050 24X Fiche 50-328,84/03/03,8403290289
- 8402090024 IE Info Notice 84-09. Rev i. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Bvc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc. 118pp 22635 049 24% Fiche 50-000, 84/03/07, 8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Bys " Svc list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl DEYQUNG, RC Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24% Fiche 50-000,84/03/12,8402090031
- 8403270250 Ack receipt of 840306 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-338/83-31 & 50-339/83-31 LEHIB,R C Division of Project & Resident Programs 84/03/16 STEWART.W L Virginia Electric & Power Co 1p 22802,032. 24X Fichs 50-338,84/03/16.8403270250
- --8403270260 Responds to NRC 840207 ltr re violations noted in IE Insp Repts 50-348/83-31 & 50-339/83-31 Corrective actions wall classified as fire barrier & cubicles reclassified as seperate fire areas Procedure revised to include insp. STEWART.W L Virginia Electric & Power Co 84/03/06 O'REILLY.J P Region 2. Office of Director 3pp 22802.033 24X Fiche 50-338,84/03/16,8403270200
- --8403270269 Forwards IE Insp Repts 50-338/83-31 & 50-339/83-31 on 831206-840105 & notice of violation LEWIS.R C Division of Project & Resident Programs 84/02/07 STEMART.W L Vinginia Electric & Power Co 2pp 22802 036 24) Fiche 50-338,84/03/16,8403290250
- --8403290280 Notice of violation from insp on 831206-840105 * Region 2. Office of Director 84/02/07 2pp 22802 038 24X Fiche 50-338,84/03/16,8403270250
- --8403290291 IE Insp Repts 50-338/83-31 & 50-339/83-31 on 831206-840105 Noncompliance noted failure to maintain procedures re insp of wall & failure to inspect fire barriers LUEHMAN.J G Region 2. Office of Director ELROD.8 Division of Project & Resident Programs 84/02/06 9pp 22802,040, 24X Fiche 50-338,84/03/16,8403290250
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Bvc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 28823 229 24X Fiche 50-000,84/03/21,8402090043
- B402070044 IE info Notice 84-20, "Svc Life of Relays in Bafety-Related Bys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engingering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22733 001, 24X Fiche 50-900,84/03/21,8402070044
- B403270021 Informs that due to add1 review required re mat1 supplied by Ray Miller, Inc. util unable to respond to IE Bulletin 83-07 until B40406 STEMART, W.L. Virginia Electric & Power Co. 84/03/22 DEYDUNG, R. C. Director's Office, Office of Inspection and Enforcement. ip. 22770 068 24X Fiche 50-000,84/03/22,8403270021.
- 8403270157 Resubmits 840302 response to 1E Builetin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications "Affirmation inadvertently omitted from 840302 ltr encl STEWART. W L Virginia Electric & Power Co 84/03/29 O'REILLY, J P. Region 2, Office of Director 2pp 22806 006 24X Fiche 50-000,84/03/29,8403290157

- R Periodic operating reports & related correspondence
- B403020122 Monthly operating repts for Jan 1784 W/840214 ltr LEE,J N , STEWART,W L Vinginia Electric & Power Co 84/01/31 HALLER:N M NRC - No Detailed Affiliation Given 23pp 22442 066 24X Fiche 50-338.84/01/31.8403020122
- 8403300055 Monthly operating repts for Feb 1984 W/840314 ltr LEE,J N . BTEWART.W L Virginia Electric & Power Co 84/02/29 HALLER,N M Office of Resource Management, Director 16pp 22821 270 24X Fiche 50-338,84/02/29,84033000055
- Reportable occurrences. LERs & related correspondence
- 8305270031 Forwards technical review rept. "Blocking of Automatic Safety Injection (SI) Signals "LERs should be included in forthcoming power reactor events issue to alert other Westinghouse PIR operators CHIRAMALIM Reactor Operations Analysis Branch 83/04/25 SEYRIT,K V Reactor Operations Analysis Branch ip 22789 272 24X Fiche 50-000.83/04/25,8305270051
- --8305270056 "Blocking of Automatic Safety Injection (SI) Signal," technical review rept * Director's Office 83/04/25 4pp 22789 293 24X Ficha 50-000,83/04/25,830527005i
- 8403280332 Forwards preliminary results of natural circulation analyses for 811111 transient at McGuire & 800605 natural circulation low power test at North Anna CHARLTON.TR EG&O, Inc 83/09/22 LITTENEKER.P E Energy, Dept of, Idaho Operations Office 29pp 22807,259. 24X Fiche 50-000.83/09/22,8403280332
- 8403060153 Updated LER 83-061/03X-1 on 830921, both high head safety injection pumps removed from svc Caused by maint & high thrust bearing vibrations First pump tested satisfactorily & returned to svc W/840229 itr HARRELL,E W Virginia Electric & Power Co 84/02/29 4pp 28513:357 24X Fiche 50-338,84/02/29,8403060153
- B403070213 NPDES noncompliance notification re 840213 oil spill Caused by lube oil associated w/overflow of bearing cooling tower makeup reservoir Oil contained by floating boom & removed w/absorbent matls
 TAYLOR, J A Virginia Electric & Power Co 84/02/27 VOLTAGGIO, T Environmental Protection Agency. 7pp 22575 078 24X
 Fiche 50-338,84/02/29,8403090213
- B403140010 LER 84-003-00 on 840208, turbine trip-reactor trip occurred due to spurious electro-hydraulic control fluid reservoir law level turbine trip signal Caused by pump vibration due to unloader malfunction Unloaders readjusted M/840307 ltr MARRELL,E W. Virginia Electric & Power Co 84/03/07 3pp 22632 141 24X Fiche 50-338,84/03/07,8403140010
- B403170376 Forwards completed Dil Spill Questionnaire VA-84-093 for B40215 eccurrence TAYLOR, J A Virginia Electric & Power Co B4/03/07 VOLTAGGIO, T Environmental Protection Agency 7pp R2675 193 24X Fiche 50-338,84/03/07,8403190396
- 8403190080 NPDEB noncompliance notification on 840214, lubricating oil splited into Lake Anna, Caused by crack on intake screen of drive chain lubricant reservoir Completed spill Questionnairs VA-84-092 and TAYLOR, J. A. Virginia Electric & Power Co. 84/03/08 VOLTAGGIO, T Environmental Protection Agency 7pp 22668 334 24X Fiche 50-338,84/03/08,8403190080
- 8403140122 Part 21 rept re status update concerning abnormal wear on linear converters. Test program underway Results of investigation indicate excessive wear caused by hunting of control circuitry
 DODSON, J.P. Pacific Air Products Co. 84/03/09 Director's Office, Office of Inspection and Enforcement 7pp. 22624.068 24X Fiche. 50-000,84/03/09,8403140122.

DOCKET 50-339 NORTH ANNA POWER STATION, UNIT 2

- A. Application/construction stage documents & correspondence
- 8403080179 Fourth partial response to FOIA request for six categories of documents re Pacilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5). Review of addl documents subj to request continuing FELTON. J M Division of Rules and Records 84/02/13 ANDERBON. 8 I Garvey, Schubert, Adams & Barer 7pp. 22583 226 24% Fiche: 50-000.84/02/13.8403080179

- F Security, medical, emergency & fire protection plans
- 8403070239 Forwards SALP Repts 50-280/83-33,50-281/83-35,50-338/83-33 & 50-339/83-33 for Oct 1982 Aug 1983 Evaluation will be discussed at 831208 meeting at North Anna site.

 LEWIS, R. C. Division of Project & Resident Programs 83/11/25 STEMART.N L. Virginia Electric & Power Co. 2pp. 22536 227 24x

 Fiche 50-000,83/11/25,8403070239
- --8403070246 SALP Repts 50-280/83-33.50-281/83-35.50-338/83-33 & 50-339/83-33 for Oct 1982 Aug 1983 Reliable performance Urimprovement in most previously noted areas of weakness demonstrated # Region 2. Office of Director 83/11/25 42pp 22536 229 24X Fiche 50-000.83/11/25.8403070239
- 8403060462 Grants 831031 request for exemption from requirements of App R to 10CFR30, Section III 0 3 b re installing fixed fire suppression sys in control room Exemption encl MILLER, J R Operating Reactors Branch 3 84/02/23 STEWART, W L Virginia Electric & Power Co ip 22549-331 24% Fiche 50-338,84/02/23,8403060462
- --8403040466 Examption from requirements of App R to 10CFR30, Section III 0 3 b ra installing fixed fire suppression sys in control room.

 EIBENHUT, D 9 Division of Licensing 84/02/23 Virginia Electric & Power Co 4pp 22547 332 24X Fiche 50-338, 64/02/23. 8403040462
- 8403190263 Rev 1 to corporate emergency response plan W/840315 ltr STEWART.W L Virginia Electric & Power Co 84/02/24 105pp 22670 135 24X Fiche 50-000.84/02/24.8403190263
- 8403030178 Forwards Amends 51 & 35 to Licenses NFF-4 & NPF-7, respectively & safety evaluation Amends revise Tech Bpccs to reflect addition & installation of new fire protection sys W/o encl ENGLE, L B Operating Reactors Branch 3. 84/02/28 STEMART, W L Virginia Electric & Power Co ip 22528 184 24X Fiche 50-338,84/02/28,8403050178
- 8403080264 Forwards "Control Room Design Review Program Plan for North Anna & Burry Power Stations," in response to Suppl 1 to NUREO-0737 Review expected to be completed by 850830 STEWART, M. Virginia Electric & Power Co. 84/03/01 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp 22557 295 24X Fiche 80-000,84/03/01.8403080264
- --B403080269 "Control Room Design Review Program Plan for North Anna & Burry Rower Btations:" in response to Suppl 1 to NUREO-0737 * Virginia Electric & Power Co 84/03/01 111pp 22557 279 24X Fiche 50-000:84/03/01,8403080264
- B403080091 Bubmits add1 info in order to conduct detailed review of emergency response procedures generation package.per B40125 request Items 1 & 2 w[1] be addressed by B40530 Item 3 should be addressed by Mestinghouse Owners Group STEMART.W L Virginia Electric & Power Co. B4/03/02 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 22559 199 24X Fiche: 50-000,84/03/02,8403080091
- 8403160276 Extends invitation to attend 840316 workshop at regional ofc to discuss 100FR50, App R requirements & results of inspato his results of inspaton his results of inspaton his results and requirements LEWIG, R C Division of Project & Resident Programs B4/03/02 BTEWARY, W L Virginia Electric & Power Co 1p 22660 080 24X Fiche 50-000, 88/03/02, 8403160276
- 8403260273 Forwards corrected Tech Spec pages for Amends 51 & 35 to Licenses NPF-4 & NPF-7, respectively, covering exial power distribution monitoring sys, penetration fire barriers & fire detection instrumentation ENGLE, L B Operating Reactors Branch 3 84/03/06 STEHART, H L, Virginia Electic & Power Co ip 22761 343 24X Fiche 50-338:84/03/06.8403260273
- --8403260281 Corrected Tech Spec pages to Amends 51 & 35 to Licenses NPF-4 & NPF-7, respectively, covering axial power distribution monitoring sys, penetration fire barriers & fire detection instrumentation # Operating Reactors Branch 3 84/03/06. 15pp. 22761 344 24X Fiche 50-388, 84/03/06. 8403260273
- B403190052 Informs that local emergency operations facilities at North Anna & Sury Power Stations will be functional, except for data communications & display, by B50731, per NUREG-0737, Suppl i.
 STEWART, W.L. Virginia Electric & Power Co. 84/03/14 DENTON, H.R. Deffice of Nuclear Reactor Regulation, Director 2pp 22666:173 24X Fichs. 50-000, 84/03/14, 8403190052

Эрр. 22802 033 24%

- 3403290250 Ack receipt of B40306 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-338/83-31 & 50-338/83-31 & 50-334763-3: LEMIS, R C Division of Project & Resident Programs 84/03. BTEWART,W L Virginia Electric & Power Co ip 22802 032 Fiche 50-338,84/03/16.8403290250
- --B403290260 Responds to NRC 840207 ltr re violations noted in IE Insp Repts 50-338/83-31 & 50-339/83-31 Corrective actions until classified as fire barrier & cubicles reclassified as seperate fire areas. Procedure revised to include insp BTEWART, W L Virginia Electric & Power Co 84/03/06 O'REILLY, J P. Region 2, Office of Director 3pp. 22802 033 243 Fiche. 50-338.84/03/16.8403290250
- -8403270267 Forwards IE Insp Repts 50-338/83-31 & 50-339/83-31 on 831206-840105 & notice of violation LEWIS.R C. Division of Project & Resident Programs 84/02/07 STEWART.W L Virginia Electric & Power Co 2pp 22802 036 24X Fiche 50-338,84/03/16,8403290250
- ~~8403290280 Notice of violation from insp on 831204-840105 * Region 2, Office of Director 84/02/07. 2pp 22802:038 24X Fiche 50-338,84/03/16,8403270250
- --8403270291 IE Insp Repts 50-338/83-31 & 50-339/83-31 on 831206-840105 Anneamylance noted failure to maintain procedures re insp of wall & failure to inspect fire barriers LUEHMAN, J 0 Region 2. Office of Director 84/02/06 9p. 22802 040 24X Fiche 50-338,84/03/16,8403290230
- P Operating license stage documents & correspondence
- B403070001 Notifies that Class III & Class I fees submitted w/820608 application for amend will be refunded based on 840123 withdrawal of application.
 MILLER.W O License Fee Management Branch 84/02/24 STEWART.W L Virginia Electric & Power Co ip R2562-343 24X Fiche 50-338,84/02/24,8403070001 84/02/24 STEWART, W L
- 8403020195 Forwards add1 info to complete review of Topical Rept VEP-FRD-41. "VEPCO Reactor Sys Transient Analysis Using RETRAN Computer Code," in response to NRC 1982 informal TEQUEST TEQUES TO THE PROPERTY OF THE PROPERTY
- 8403050227 Submits review of post-accident sampling sys. Item II B 3 Ton of il criteria met Remaining criterion re procedure for estimating extent of core damage based on radionuclide evaluation. acceptable on interim basis.

 MILLER, JR Operating Reactors Branch 3 84/02/27 STEWART, H L Virginia Electric & Power Co 6pp 22528 001 24x Fiche 50-000.84/02/27.8403050227
- B403020001 Requests interim approval of inservice inap & testing requirements for pumps & valves. Approval would increase scope of insp & testing & menance safety Implementation of revised inservice tasting programs expected by 940315 BIEWART: N L Virginia Electric & Power Co 84/02/28 DENTON. Office of Nuclear Reactor Regulation. Director 2pp 22442 IE 24X Fiche 50-338;84/02/28,8403020001 DENTON H R 22442 155
- 8403020042 Forwards revs to inservice testing program for pumps & valves, clarifying previous submittals
 STEWART, N. Unginia Electric & Power Co 84/02/28 DENTON, HR Office of Nuclear Reactor Regulation, Director MILLER, JR Operating Reactors Branch 3 15pp 22442 272 24x
 Fichs. 80-338,84/02/28,8403020042
- 8403030198 Forwards Amends 51 & 35 to Licenses NPF-4 & NPF-7, respectively & safety evaluation Amends revise Tech Specs to reflect addition & installation of new fire protection sys reflect addition & installation of the Market William and B4/02/28 BTEWART, William Electric & Power Co. ip 22528 184, 24X Fiche 50-938,84/02/28,8403050198.
- B4031R0176 Advises that i1.6% permit responsibility transferred to Old Dominion Electric Cooperative on 831R21, per 840131 ltr Requests NPDES permit & 401 certificate dtd 720211 be modified to reflect transfer W/o Stated encl TAYLOR.J A. Virginia Electric & Power Co. 84/03/01. BURTON.R.M Virginia. CommonWealth of. ip 22590, 203 24X Fiche 50-338,84/03/01,8403120176

- 8403080071 Informs NRC that submittal date for low pressure turbine disc cracking rept delayed until 840330 due to delay in Southwest Research receipt of dissected disc. STEMART.H L. Virginia Electric & Power Co. 84/03/02 DENTON, H R Office of Nuclear Reactor Regulation, Director MILLER, J R Operating Reactors Branch 3 ip 22560 024, 24X Fiche 50-339,84/03/02,8403080071
- 8403210203 Forwards Amends 52 & 36 to Licenses NFF-4 & NFF-7, respectively Amends clarify testing requirements in Tech Spec Table 3 6-1 re containment isolation valves ENOLE: LB Operating Reactors Branch 3 84/03/06. STEWART, W. L Virginia Electric & Power Co 3pp 22709 192 24X Fiche: 50-338,84/03/06,8403210203
- --8403210206 Amends 52 & 36 to Licenses NPF-4 & NPF-7, respectively, clarifying testing requirements in Tech Spec Table 3 6-1 recontainment isolation valves MILLER, J R Operating Reactors Branch 3 84/03/06 9pp. 22709 195 24X Fiche 50-338,84/03/06.8403210203.
- B403260273 Porwards corrected Tech Bpec pages for Amends 51 & 35 to Licenses NPF-4 & NPF-7, respectively, covaring axial power distribution monitoring sys, penetration fire barriers & fire detection instrumentation.
 ENGLE.L B Dearating Reactors Branch 3 84/03/06. STEHART, W L Virginia Electric & Power Co ip 22761:343 24X
 Fichs 50-338.84/03/06,8403260273
- --8403250281 Corrected Tech Spec pages to Amends 51 & 35 to Licenses NPF-4 & NPF-7, respectively, covering exial power distribution monitoring sys, penetration fire barriers & fire detection instrumentation ** Operating Reactors Branch 3 84/03/06 13pp 22761:344 24X Fiche 50-338,84/03/06,8403260273
- 8403130298 Provides implementation itr rept for reactor vessel level instrumentation sys, per NRC 840116 itr & TMI Action Item II F 2. Requests NRC approve use of installed reactor vessel level instrumentation based on previous acceptance.

 STEMART.W L. Virginia Electric & Power Co. 84/03/07. DENTON, H R Office of Nuclear Reactor Regulation. Director. EIBENHUT, D Q. Division of Licensing 3pp 22407.360. 24X Fiche 50-338,84/03/07,840310988 B403130298
- 8403190201 Application for amend to License NPF-7, changing Tech Specs to delate Surveillance Requirement 4 8 1, 1 2 c, 6 re simulated loss of diesel generator w/offsite power unavailable.per Generic Ltr 83-30 STEMART.W L Virginia Electric & Power Co 84/03/15 DENTON, H.R. Office of Nuclear Reactor Regulation. Director MILLER, J R. Operating Reactors Branch 3 3pp 22671.123 24X Fiche 50-339,84/03/15,8403190201
- ~-B403190204 Proposed Tech Bpec changes reflecting deletion of Burvaillance Requirement 4 B 1. i. 2. c. 6 re minulated loss of diesel generator w/offsite power unavailable.

 * Virginia Electric & Power Co B4/03/15 Spp 22671 12: Fiche 30-339, B4/03/15, 8403190201 5pp 22671'127, 24X
- 8403190377 Application for amend to Licenses NPF-4 & NPF-7.changing Tech Bpecs to delete requirements for min & max temp limits for A36 & A372 beams in steam generator supports & determination of beam temps STEWART. H L Virginia Electric & Power Co 84/03/15 DENTON, H.F. Office of Nuclear Reactor Regulation, Director HILLER, J.R. Operating Reactors Branch 3 3pp. 22675.237. 24X Fiche 50-338,84/03/15,8403190377. 84/03/15 DENTON, H. R.
- --8403190381 Proposed Tech Specs deleting requirements for min & max temp limits for A36 & A572 beams in steam generator supports & determination of beam temps. Request for removal of steam generator support heaters & insulating tent encl # Virginia Electric & Power Co. 84/03/15, 30pp. 22675.240 24X Fiche 50-338,84/03/15,8403190377
- 8403220028 Application for amend to Licenses NPF-4 & NPF-7, revising Tech Specs to reflect new LER sys.per 10CFR50.73 & immediate notification requirements.per 10CFR50.72.

 STEWART.W.L. Virginia Electric & Power Co. 84/03/16. DENTON, H.R. Office of Nuclear Reactor Regulation. Director MILLER, J.R. Operating Reactors Branch 3. 4pp. 22713.128 24X
 Fiche 50-338,84/03/16,8403220028.
- --8403220032 Proposed Tech Spacs reflecting new LER sys & immediate notification requirements.

 * Virginia Electric & Power Co 84/03/16. 85pp. 22713:132. 24X Fichs: 30-338,84/03/16.8403220028.

- 8403220077 Requests exemption from 10CFR50 44(c) (3) (iii) requirements Operability of reactor vessel head vents should be verified during proposed outages & procedures & training implemented W/revised emergency operating procedures STEWART, W.L. Virginia Electric & Power Co. 84/03/16 DENTON, H.R. Office of Nuclear Reactor Regulation, Director MILLER, J.R. Operating Reactors Branch 3. 2pp. 22712 311 24X Fiche. 50-338, 84/03/16, 8403220077
- 8403270208 Forwards voucher check for required license emend fees omitted from 840315 ltr
 8TEWART.W L Virginia Electric & Power Co 84/03/23 DENTON.H R
 Office of Nuclear Reactor Regulation, Director MILLER, J R
 Operating Reactors Branch 3, 1p, 22772 084 24X
 Fiche. 50-338, 84/03/23, 8403270208
- 8403270248 Forwards fee for 840315 proposed Tech Spec change.

 BTEWART, H. L. Virginia Electric & Power Co 84/03/23 DENTON, H R
 Office of Nuclear Reactor Regulation, Director MILLER, J R
 Operating Reactors Branch 3 1p 22771 311 24X
 Fiche. 50-339, 84/03/23, 8403270248.
- 8403300028 Forwards response to 840116 request for add1 info re core exit thermocouple (CETC) & subcooling margin monitoring sys, per 840130 commitment CETC add1 info deferred until after 840801 due to sys replacement, per Reg Guide 1 97.

 BTEWART, H L Virginia Electric & Power Co 84/03/23 DENTON, H R Office of Nuclear Reactor Regulation, Director EISENHUT, D. 0 Division of Licensing 4pp 22821, 307 24X Fiche 50-338, 84/03/23, 8403300028.
- B403300005 Informs that independent testing lab conducting overvoltage tasts on motor control ctr contactor coils Current schedule for completing tests is May 1984 Resolution & related schedule will be submitted by Jul 1984 BTEHART.W L. Virginia Electric & Power Co 84/03/26 DENTON.H R Office of Nuclear Reactor Regulation, Director MILLER, J. R Operating Reactors Branch 3. 19 22822:125 24X Fiche: 50-338,84/03/26,8403300005
- O Inspection reports. IE Bulletins & correspondence
- 8403070239 Forwards SALP Repts 50-280/83-33,50-281/83-35,50-338/83-33 & 50-339/83-33 for Oct 1982 Aug 1983 Evaluation will be discussed at 831208 meeting at North Anna site LEWIS, R. C. Division of Project & Resident Programs 83/11/25 STEWART, W L. Virginia Electric & Power Co 2pp 22536 227 24X Fiche: 50-000,83/11/25,8403070239.
- --8403070246 8ALP Repts 50-280/83-33,50-281/83-35,50-338/83-33 & 50-339/83-33 for Oct 1982 Aug 1983 Reliable performance w/improvement in most previously noted areas of weakness demonstrated. * Region 2, Office of Director 83/11/25 42pp. 22536,229, 24X Fichs: 50-000,83/11/25,8403070239
- 8403070279 Discusses BALP evaluation Issuence of BALP rept approved No major weaknesses identified during assessment period at 1 North Anna. One major weakness identified in area of radiological controls at Burry O'REILLY, J P Region 2, Office of Director, 84/02/16 BTEHART, W L Virginia Electric & Power Co 2pp. 22541-286 24X Fiche: 50-000,84/02/16,8403070279
- 8401170072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/28. Consolidated Edison Co. of New York, Inc. 115pp. 22909.239 24X Fiche.30-000;84/02/28,8401170072
- 8403020001 Requests interim approval of inservice insp & testing requirements for pumps & valves Approval would increase scope of insp & testing & enhance safety Implementation of revised inservice testing programs expected by 840315.

 SIEMART.W L. Virginta Electric & Power Co 84/02/28. DENTON, H R Office of Nuclear Reactor Regulation, Director. NILLER, J. R. Operating Reactors Branch 3. 2pp 22442 155. 24X Fichs: 50-338,84/02/28,8403020001.
- B402070007 IE Info Notice B4-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC." Svc list encl GRACE, N. Division of QA, Safeguards & Inspection Programs (Post B30103). B4/03/02 Consolidated Edison Co. of New York, Inc 130pp. 22552:327. 24X Fiche: 50~000,84/03/02,8402090007.
- B40207000B IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valvas to Operate." Svc 11st encl. JDRDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/03/02. Consolidated Edison Co. of New York, Inc. 122pp. 22553.098 24X Fiche.50-000,84/03/02,8402070008

- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases" 8vc list encl JURDANA E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02, Consolidated Edison Co of New York, Inc 119pp 22553 217 24X Fiche 50-00b,84/03/02,8402090009
- 8403160154 Responds to IE Bulletin 83-0B re electrical circuit breakers W/undervoltage trip feature in use in safety-related applications other than trip sys Unly reactor trip breakers contain subj trip attachments

 BTEWART,W L Virginia Electric & Power Co 84/03/02 O'REILLY,J P
 Region 2. Office of Director 2pp 22806 008 24X
 Fiche 50-000.84/03/02.8403160154
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8403290289 Forwards IE Insp Repts 50-338/84-01 & 50-339/84-01 on 840106-0205 No violations or deviations identified DANCE: H C Division of Project & Resident Programs 84/03/05 8TEMART: H L Virginia Electric & Power Co. 2pp 22800,048, 24X Fiche 50-338,84/03/05,8403290289
- --8403290274 IE Insp Repts 50-338/84-01 & 50-339/84-01 on 840106-0205 No violations or deviations identified Major areas inspected, onsite areas of surveillance & maint activities, previous insp findings & identified items & safety sys walkdowns BRANCH-M W , LUEHMAN. J Q. Region 2, Office of Director ELROD, S Division of Project & Resident Programs 84/03/02, 10pp 22800 050 24X Fichs 50-338,84/03/05,8403270289
- 8402090024 IE Info Notice 84-09, Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24% Fiche 50-000, 84/03/07, 8402090024
- 8402070028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Bys." Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/03/07 Consolidated Edison Co of New York, Inc. 118pp. 22584 186 24X Fichs 50-000,84/03/07,8402070028
- 8402070031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Syc list encl DEYDUNG, R C Director's Office, Office of Inspection and Enforcement B4/03/12 Consolidated Edison Co of New York, Inc 134pp. 22823 094 24X Fiche 50-000,84/03/12,8402070031
- 8403270230 Ack receipt of 840306 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-338/83-31 & 30-339/83-31 & LEWIS,R.C Division of Project & Resident Programs 84/03/16 BTEWART,W L. Virginia Electric & Power Co, 1p 22802 032 24% Fiche 50-338.84/03/16,8403290250
- --8403290260 Responds to NRC 840207 ltr re violations noted in IE Insp Repts 50-338/83-31 & 50-339/83-31 Corrective actions wall classified as fire barrier & cubicles reclassified as seperate fire areas Procedure revised to include insp STEMART.W.L. Virginia Electric & Power Co. 84/03/06 O'REILLY.J P Region 2, Office of Director 3pp. 22802.033 24X Fiche 50-338,84/03/16,8403290250
- --8403270267 Forwards IE Insp Repts 50-338/83-31 & 50-339/83-31 on B31206-840105 & notice of violation LEMIS.R.C. Division of Project & Resident Programs 84/02/07 8TEMART.H.L. Virginia Electric & Power Co. 2pp. 22802.036 24X Fiche. 50-338,84/03/16,8403270250
- --8403270280 Notice of violation from insp on 831206-840105. * Region 2, Office of Director. 84/02/07 2pp 22802 038 24X Fiche.50-338,84/03/16,8403270250.
- --8403270291 IE insp Repts 50-338/83-31 & 50-339/83-31 on 831206-840105 Noncompliance noted failure to maintain procedures re insp of wall & failure to inspect fire barriers LUEHMAN.J Q. Region 2. Office of Director ELROD, S. Division of Project & Resident Programs. 84/02/06 7pp 22802 040 24X Fiche 50-338,84/03/16,8403290250
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PHR Reactor Cavities " Syc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/03/21. Consolidated Edison Co of New York, Inc. 123pp. 22823-229 24X Fichs.50-000.84/03/21,8402090043

- 8402070044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc list encl JORDAN: E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 135pp 22933 001 24X Fiche 50-000,84/03/21,8402070044
- 8403270021 Informs that due to add1 review required re mat1 supplied by Ray Miller, Inc.uti3 unable to respond to IE Bulletin 83-07 until 840406 STEWART.N L. Virginia Electric & Power Co. 84/03/22. DEYOUNG,R C. Director's Office. Office of Inspection and Enforcement. Ip 22770-048 24% Fiche 50-000,84/03/22,8403270021
- 8403270157 Resubmits 840302 response to IE Bulletin 83-08, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in 84 Sety-Related Applications ." Affirmation inadvertently omitted from 840302 ltr encl STEWART, W.L. Virginia Electric & Power Co. 84/03/27. O'REILLY, J.P. Region 2. Office of Director 2pp. 22806 006. 24% Fiche 50-000.84/03/29,8403290157
- . Periodic operating reports & related correspondence
- 8403020122 Monthly operating repts for Jan 1984 N/840214 ltr LEE,J N , STEWART.H L Virginta Electric & Power Co 84/01/31 HALLER.N H NRC No Detailed Affiliation Given. 23pp 22442 24X Fiche 50-338.84/01/31.8403020122 22442.066
- B403300055 Monthly operating repts for Feb 1984 H/840314 ltr LEE,J N , BTEWART.H L Virginia Electric & Power Co 84/02/29 HALLER,N M Office of Resource Management, Director 16pp 22821 270 24% Fiche 30-338,84/02/29,8403300055
 - Reportable occurrences, LERs & related correspondence
- 8403280332 Forwards preliminary results of natural circulation analyses for 811111 transient at McQuire & 800605 natural circulation low power test at North Anna CHARLTON,T R 2040, Inc 93/09/22 LITTENEKER,P E Energy, Dept of, Idaho Operations Office 29pp 22807 257 24X Fiche 80-900,83/09/22,8403280332
- 9403090213 NPDES noncompliance notification re 840213 oil spill Caused by lube oil associated w/overflow of bearing cooling tower makeup reservoir Oil contained by floating boom & removed makeup reservoir of the work o Environmental Protection Agency 7sp Fiche 50-338.84/02/29.8403090213
- 340319039å Forwards completed Oil Spill Guestionnaire VA-84-093 for B40213 occurrence TAYLOR, J. A. Virginia Electric & Power Co. 84/03/07 Environmental Protection Agency. 7pp 22675 193 24X Fiche 50-338, B4/03/07, 8403190376. VOI-TARRETO, T
- 3903190080 NPDES noncompliance notification on 840214, lubricating oil spilled into Lake Anna Caused by crack on intake screen of drive chain lubricant reservoir Completed spill
- GUSSEIONNAINS VA-84-092 encl
 TAYLOR.J A Virginia Electric & Power Co 84/03.
 Environmental Protection Agency 7pp 22668 334
 Fiche 50-338.84/03/08.8403190080 84/03/08 VOLTAQGIO,T 68 334 24X
- DCKET 50-341 ENRIGO FERMI ATOMIC POWER PLANT, UNIT 2
- . Application/construction stage documents & correspondence
- 3403140340 Summary of 831215 meeting w/GE & Marx I Owners Group in Bethesda. NO re Mark I containment wetwell-drywell vacuum breaker dasign methodology SIEGEL, B.L. Operating Reactors Branch 2 84/02/21 Operating Reactors Branch 2 51pp 22635 198 24X Fiche 50-000, 84/02/21, 8403140340,
- 3403020164 Submits request for addl info re postulated failure of HPCI stam line w/o isolation.
 YOUNOBLOOD.B.J Licensing Branch 1 84/02/22, JENS,W Detroit Edison Co. 3pp. 22491-135 24X Fiche-30-341,84/02/22,8403020164
- 3403020121 Responde to 840105 Generic Ltr 84-01 re NRC use of terms important to safety & safety-related. Bubj will be discussed further through steering committee & chairman of Util Bafety Classification group JEMS.W H Detroit Edison Co 84/02/24. TAYLOR, J M. Director's Office, Office of Inspection and Enforcement. Ip 22442-065, 24X Fiche 50-341,84/02/24,8403020121

- 8403090247 Advises that util will adopt all applicable provisions associated w/8 h Type A test detailed in Rev 1 to BN-TOP-1.
 "Testing Criteria for Integrated Leakage Rate Testing of Primary Containment Structures for Nuclear Plants"

 JENBI W H Detroit Edison Co 84/03/05 YOUNDELOOD, B J Licen
 Branch 1 1p 22572 201 24X Fiche 50-341,84/03/05,8403090847
- 8403130009 Forwards Certificate of 8vc for Amend 53 to amended & substituted application for licenses
 HATHAWAY, O H Detroit Edison Co 84/03/09 Office of Nuclear
 Reactor Regulation Director. 3pp 22615 166 24X Reactor Regulation, Director. 3 Fiche 80-341.84/03/09,8403130000
- 8403130044 Forwards Amend 54 to amended & substituted application for licenses, consisting of Amend 54 to FSAR LANDGRAF, L C LeBoeuf, Lamb, Leiby & MacRae LANDGRAF, L C Detroit Edison Co 84/03/09 DENTON, H Office of Nuclear Reactor Regulation, Director 1p 22610 168 24X Fiche 50-341,84/03/09,8403130044
- --8403130051 Amend 54 to amended & substituted application for licenses, consisting of Amend 54 to FBAR
 * Duquesne Light Co 84/02/22 ip 22610 169 24X
 Fichs 50-341,84/03/07,8403130044
- 8403200185 Affirms resolution of TMI Action Plan Item II K 3 31 resmall break LOCA analysis No further action necessary
 JENS. H H Detroit Edison Co 84/03/14 YOUNGBLOOD, B. J Licensing
 Branch I 2pp 22686 338 24X Fiche, 50-341, 84/03/14, 8403200185.
- B40321004B Requests issuance of proof & review version of Tech Specs Resources to support effort available & impact of obtaining add! test data minimal JENS.W H Detroit Edison Co 84/03/14 YOUNOBLOOD, B J Licensi Branch I 1p 22706 339, 24X Fiche 50-341.84/03/14,840321004B
- 8403210074 Forwards "Environ Qualification of Safety-Related Mechanical Equipment for Harsh Environ." per 831201 meeting JENS, H H Detroit Edison Co. 84/03/14, YDUNGBLOOD, B J Licensing Branch i ip 22706 140 24% Fiche 50-341,84/03/14,8403210074
- --8403210078 "Environ Qualification of Safety-Related Machanical Equipment for Harsh Environ " * Detroit Edison Co 84/03/31 150pp 22706 141, 24X Fichs. 50-341,84/03/14,8403210074
- 8403230019 Forwards revised NRC licensed operator training requalification program administrative guids incorporating addressed comments contained in 831219 ltr UENS.W H Detroit Edison Co 84/03/14 YOUNGBLOOD, B J. Licen. Branch I ip 22726 178 248 Fichs. 50-341.84/03/14.8403230018
- --B403230021 NRC licensed operator training requalification program-administrator guide * Detroit Edison Co. B4/01/31 50pp. 22726 179 24X Fiche 50-341.B4/03/14.8403230018
- 8403280237 Discusses MV Lipton qualification review.per 840119 response to request for addl info Lipton qualified as radiation protection manager.per Reg Guidæ 1 8 YOUN0818000.B J Licensing Branch i 84/03/14 JENS, W. Detroit Edison Co 2pp 22808.210. 24% Fiche 50-341.84/03/14.8403280237
- 8403270043 Informs that ultrasonic test exams of blend redii area & magnetic particle exam conducted by vessel mfg to determine degree of conformance to NUREQ-0619 No recordable indications found utilizing either technique JENS.W H Detroit Edison Co 84/03/21. YOUNOBLOOD, B. J. Licens: Branch 1 1p 22769.315 24X Fiche: 50-341,84/03/21,8403270043
- 8403300138 Forwards Certificate of Svc indicating appropriate parties served w/Amend 54 to amended & substituted application for HATHAWAY, O H. Detroit Edison Co. 84/03/26 Office of Nuclear Reactor Regulation, Director. 3pp 22820,349 24X
 Fichs: 50-341,84/03/26,8403300138
- F Security, medical, emergency & fire protection plans
- 8403120049 Extends invitation to attend regional workshop on fire protection safe shutdown requirements of 10CFR50.App R on 840323 in Rosemont, IL Proposed agenda encl for review SPESSARD.R L Division of Emergency Preparedness & Operational Support 84/03/06 HeLLS.D.A Detroit Edison Co. 3pp. 22589:292 24X Fiche. 30-341.84/03/06.8403120049.

H General correspondence

- 8403280045 Responds to 840217 inquiry re plants not considered for insp of vent header cracks in torus Insp inapplicable because Fermi & Hope Creek still in const stage BENTON.H R. Office of Nuclear Reactor Regulation, Director 84/03/12 WESTOVER, A T Monroe County, MI ip 22812 358 24X Fiche: 80-000.84/03/12.8403280045
- --B403280054 Requests explanation as to why facility not considered for insp for cracks in vant header similar to crack found at Match.

 WEBTOVER, A. J. Monroe County, MI 84/02/17 Office of Nuclear Reactor Regulation, Director 2pp. 22812 359 24X Fiche. 50-000, 84/03/12:8403280045

K Utility Final Safety Analysis Report (FSAR) & amends

- 8403130044 Forwards Amend 54 to amended & substituted application for licenses, consisting of Amend 54 to FBAR LANDQRAF,L C LeBoeuf, Lamb, Leiby & MacRae, LANDQRAF,L C. Detroit Edison Co 84/03/09 DENTON,H Office of Nuclear Reactor Regulation, Director 1p, 22610 168 24X Fiche, 50-341,84/03/09,8403130044,
- ---8403130051 Amend 54 to amended & substituted application for licenses, consisting of Amend 54 to FBAR.

 ** Duquesne Light Co. 84/02/22 1p 22610.169 24X Fichs.80-341,84/03/09,8403130044
- ---8403130060 Amend 54 to FSAR Twenty-eight oversize drawings encl. Drawings available in PDR * Detroit Edison Co 84/03/31 789pp 22610.170 24X Fich= 50-341.84/03/09.8403130044

G. Inspection reports, IE Bulletins & correspondence

- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation." Svc list encl.
 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp. 22709:239. 24X Fiche 50-000,84/02/28,8401190072
- 8403060170 Ack receipt of 840217 itr informing NRC of steps taken to correct noncompliance noted in IE Insp Rept 50-341/83-29 KNOP,R C. Region 3, Office of Director. 84/03/01 WELLB,D.A Detroit Edison Co. 1p. 22518 337 24X Fiche: 50-341,84/03/01,84030.6170
- --8403060173 Resubmits 840123 response to NRC 831222 ltr re noncompliance noted in IE Insp Rept 50-341/83-29.

 WELLS.D.A Detroit Edison Co. 84/02/17 KNOP.R C. Region 3. Office of Director 1p. 22518.338 24X Fiche 50-341.84/03/01. 8403060170.
- --8403060177 Responds to NRC 831222 ltr re noncompliance noted in IE Insp Rept 50-341/83-29 Corrective actions.Plant Operation Manual 12.000 revised damaged unistrut scrapped & satellite storage areas marked & roped off MELLS:D.A., ALESSI.T.A Detroit Edison Co. 84/01/23. KNDP.R C Region 3. Office of Director 5pp 22518:339. 24X Fichs.50-341,84/03/01,8403060170
- B403170307 Forwards IE Inep Rept 50-341/84-03 on 840131 & 0201-02. No noncompliance noted. PAPERIELLO,C.J. Region 3. Office of Director. B4/03/01 WELLB,D / Detroit Edison Co. 2pp. 22673'168 24X Fiche. 50-341.84/03/01, 8403190309.
- --B403190313 IE Insp Rept 50-341/84-03 on B40131 & 0201-02 No noncompliance noted, Major areas inspected; preoperational radiological environ monitoring program, including mpt controls & program implementation & results DESTMANN.M.J., SLAMINGKI.M.J., SCHUMACHER.M.C Region 3, Office of Director. B4/02/29, 9pp 22673:170. 24X Fiche.50-341,84/03/01,8403190309.
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC." Svc list encl. ORACE., N. Division of GA, Bafeguards & Inspection Programs (Post 830103), 84/03/02, Consolidated Edison Co. of New York, Inc 130pp. 22552:329. 24X Fiche: 50-000.84/03/02,8402090007
- 8402070008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate." Syc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103), 84/03/02, Consolidated Edison Co. of New York, Inc. 122pp. 22553:098, 24X Fiche: 50-000,84/03/02,8402070008

- 8402090009 IE InPo Notice 84-15, "Reporting of Radiological Releases"
 Evc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc 119pp 22553 217 24X Fichs 50-000,84/03/02,8402090009
- 8402090011 IE Into Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list enc! JURDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05. Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8403220107 Forwards IE Insp Rept 50-341/83-30 on 831201-840131 & notice of violation KNDP:R C Region 3. Office of Director 84/03/05 WELLS,D A Detroit Edison Co 2pp 22716 197 24X Fiche 50-341.84/03/05, 8403220109
- --8403220111 Notice of violation from insp on 831201-840131 KNDP,R C Region 3, Office of Director 84/03/05 2pp 22716 199 24X Fiche 50-341,84/03/05,8403220109
- --8403820114 IE Insp Rept 50-341/83-30 on 831201-840131 Noncomplience identified HPCI sys test procedure not reviewed for campleteness & adequacy & RCIC sys did not incorporate all valve timing requirements in FSAR BYRON, P M , PARKER, M E , KONKLIN, J E Region 3, Office of Director 84/03/02 15pp 22716 201 24X Fiche 50-341,84/03/05,8403220109
- B402090024 IE Info Notice 84~09.Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Bys " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Cansolidated Edison Co of New York, Inc 118pp. 22635 049 24X Fiche 50-000,84/03/07,8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR 8ys " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8402090031 IE Bulletin 84-02, "Failures of OE Type HFA Relays in Use in Class IE Safety Sys " Syc list encl
 DEYOUNO,R C Director's Office, Office of Inspection and Enforcement B4/03/12 Consolidated Edison Co. of New York, Inc. 134pp 22823 074 24X Fiche: 50-000,84/03/12,8402090031
- B403260127 Responds to IE Bulletin B3-OB re failures & problems w/possible improper operation of circuit breakers w/undervoltage trip attachments Field mod requests issued to remove undervoltage device from breakers
 WELLB.D A Detroit Edison Co B4/O3/14 KEPFLER, J C Region 3
 Office of Director 4pp 22758 143 24X Fiche 50-341,84/O3/14,84
- 8403300033 Forwards IE Insp Rept 50-341/84-01 on 840114-0217 No noncompliance noted BTREETERJ F Region 3. Office of Director, 84/03/15 WELLB, D A Detroit Edison Co ip 22821 253 24X Fiche 50-341,84/03/15, 8403300083
- --B403300057 IE Insp Rept 50-341/B4-01 on 840114-0217 No noncompliance or deviations noted Major areas inspected previous insp findings, preoperational test program procedure review & verification, result review & test witnessing DUPONT. 8.0 , LANKSBURY, R D. REYES. L. A Region 3, Office of Director. B4/03/15 10pp. 22821 254 24X Fiche 50-341.84/03/15, 8403300053
- B402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities." Svc list encl JORDAN.E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21. Consolidated Edison Co. of New York, Inc. 123pp 22823 229. 24X Fiche 50-000.84/03/21.8402090043
- B402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Bys " Svc list encl JDRDAN,E.L Division of Emergency Preparedness & Engineering Response (Post 830103), 84/03/21 Consolidated Edison Co of New York, Inc. 135pp. 22933 001, 24X Fichs.50-000.84/03/21,8402090044
- R. Periodic operating reports & related correspondence
- 8403020443 Forwards monthly status rept of offsite emergency preparedness for OL reviews for Jan 1984. Changes in FEMA finding dates not caused by delay due to offsite emergency planning issues.

 DIRCKS.W.J Defice of the Executive Director for Operations 84/02/21 PALLADINO Commissioners. 9pp 22492 083 24X Fiche 50-000.84/02/21,8403020443.

S Reportable occurrences, LERs & related correspondence

- 8403120009 Interim deficiency rept. Item 35 re defective spot usids & Power-Strut support matl Initially reported an 820211 Evaluation for spot useld members for overload conditions continuing Addl use of members discontinued WELLS.D.A. Detroit Edison Co. 84/02/23 KEPPLER.J.G. Region 3. Office of Director 2pp 22588 029 24% Fiche 50-341.84/02/23, 8403120007
- B403120160 Deficiency rept. Item 113 re linear indications in seam of ASTM A500 GR B tube steel Initially reported in 840124 telcon Further evaluation pending completion of visual insporf electrical cable tray supports

 WELLB.D A Detroit Edison Co 84/02/23 KEPPLER.J Q Region 3, 840120160 Percent 2pp 22590-142 24X Fiche 50-341,84/02/23,8403120160
- 8403120155 Deficiency rept, Item 115 re possible impingement of essential piping during pipe break Initially reported on 840124 Sueep paths & jet impingement rones will be reevaluated & pipe break locations reassessed HELLS D A Detroit Edison Co 84/02/25 KEPPLER. J G Region 3. Office of Director 2pp 22586 248 24X Fiche 50-341,84/02/25,8403120155
- 840312006B Interim deficiency rept. Item 116 re potential for freezing of buried fire protection sys giping to RHR bldg Initially reported on 840631 Water will be passed through line once per shift during freezing weather RELLS:DA Detroit Edison Co 84/02/29 REPPLER, J. G. Region 3, 84/0312006B
- 8403190079 Interim deficiency rept. Item 114 re possible overpressurization of north RHR MX (PIS E11-01-8001A) Initially reported on 840124 Leakage observed coming through insulation in MX shell flange Na piping damage found WELLS.D A Detroit Edison Co 84/03/07 KEPPLER.J G Region 3. Office of Director 2pp 22668 341 24X Fiche 50-341.84/03/07, 8403190079

T Hearing transcripts on non-antitrust matters

8402090039 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delaval. Inc (TDI) Dumers Group Distribution list enci EISENHUT.D 0 Division of Licenting 84/03/12 PALLADING Commissioners 5pp 22708 001 24X Fiche 50-000. 84/03/12, 8402090039

V Operator Examinations

- 8403090188 forwards updated info re operator licensing exams Submittal includes estimate of need for operator licensing exams for remainder of FY84 & FY85 through FY87.

 JENS.N H Detroit Edison Co 84/03/05 YDUNOBLOOD, B Licensing Branch 1 2pp 22573 302 24X Fiche 50-341.84/03/05.8403090188
- Branch i 2pp 22573 302 24% Fiche 50-341.84/03/05,8403090188
- B403150021 Forwards individual operating shift experience status; per DF Schnell request Util will use shift advisors to satisfy hot participation experience requirements Licensed classroom training & exam conducted

 JENS.W H Detroit Edison Co B4/03/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 22pp 22643 043 24X Fiche 30-341.84/03/09.8403150021
- B403230018 Forwards revised NRC licensed operator training requalification program, administrative guide, incorporating addressed comments contained in B31219 ltr JENS.4 H Betroit Edison Co. B4/03/14 YOUNGBLOOD, B J Licensing Branch 1 1p 22726·178 24X Fiche 50-341,84/03/14,8403230018
- --8403230021 NRC licensed operator training requalification program, administrator guide

 * Detroit Edison Co 84/01/31 50pp. 22726 179. 24X Fichs 50-341.84/03/14.8403230018

OCKET 50-344 TROJAN NUCLEAR PLANT

- F Security, medical, emergency & fire protection plans
- 8403130381 Ack receipt of 831128 ltr transmitting changes to security plan Changes consistent w/provisions of iOCFR50.54(p) & acceptable acceptable SCHUSTER.M D Region 5, Office of Director. 84/01/20 WITHERB.B.D Portland General Electric Co 2pp 22616,276 24X Fiche 80-344,84/01/20,8403130381.

- B403060341 Forwards IE Insp Rept 50-344/83-34 on 831128-1230. No noncompliance identified BISHOP.T.W Region 5. Office of Director 83/02/07 WITHERB.B.D Portland General Electric Co 2pp 22519.073 24X Fiche.50-344.84/02/07.8403060341
- --8403060344 IE Insp Rept 50-344/83-34 on 831128-1230.No noncompliance or deviations identified Major areas inspected plant operations, security, maint, surveillance testing, cold weather preparation & plant review board JOHNSTON, G W., RICHARDS, S A., DODDS, R T. Region 5, Office of Director 84/02/03 4pp 22519 075 24X Fiche; 50-344,84/02/07,8403060341
- 8403120379 Forwards rept of results of in-progress audit for facility detailed control room design review per Suppl 1 to NUREO-0737 conducted on 831212-16 MILLER, J.R. Operating Reactors Branch 3. 84/02/29, WITHERS, B. D. Portland General Electric Co. 73pp 22619 008 24X Fiche 50-344,84/02/29,8403120379
- 8403190378 Revised emergency plan implementing procedures, including Procedure EP-1 re emergency classification EP-7 re operation of technical support ctr & EP 8.6 re communications staff W/840314 ltr.

 * Portland General Electric Co 84/03/05 CLARK, R. A Office of Nuclear Resctor Regulation, Director. 72pp 22671;001 24X Fichs 50-344,84/03/05,8403190378
- 8403260302 Forwards exemption from 10CFR50 48 & App R to 10CFR50 refire protection for reactor coolant pump lubricating oil. Exemption conditioned on implementing fire protection improvements by plant startup MILLER.J.R Operating Reactors Branch 3 84/03/05 WITHERS, B D Portland General Electric Co 1p 22759.349 24X Fiche 30-344.84/03/05.8403260302
- --8403260304 Forwards exemption from 10CFR50: App R fire protection requirements for FR publication
 * Division of Licensing 84/03/05 Docketing & Services
 Branch, 2pp 22759.350. 24X Fiche.50-344.84/03/05:8403260302.
- --B403260306 Exemption from 10CFR50 48 & App R to 10CFR50 requirements refire protection for reactor coolant pump lubricating oil.
 EIBENHUT, D 0 Division of Licensing 84/03/05 Portland
 General Electric Co 4pp 22759-352 24X Fiche 50-344,84/03/05,8403260302
- 8403270240 Advises that 840112 rev to physical security plan consistent u/provisions of 10CFR50, 54(p) & acceptable 8CHUBTER, M D Region 5, Office of Director 84/03/22 WITHERB, B D. Portland General Electric Co 2pp 22800, 253, 24X Fiche: 50-344, 84/03/22, 8403290240

O Adjudicatory correspondence

- B403220247 Response to Coalition for Safe Power & Btate of OR B40305 contentions Certificate of Bvc encl JOHNSON,R W Portland General Electric Co DBB 056, 84/03/20, Atomic Safety and Licensing Board Penel 46pp 22719.051 24X Fiche, 50-344, 84/03/20, 8403220247
- 8403300272 Forwards notices of appearance in proceeding of M Axelrad & BA Goldberg Certificate of Byc encl.
 AXELRAD.H Portland General Electric Co AXELRAD.H Newman & Holtringer DB 215. 84/03/27 App. 22824.033 24X
 Fiche:50-344,84/03/27,8403300272

H General correspondence

- 8403060384 Advises that correspondence & pleadings should be directed to RW Johnson at listed address
 JOHNSON.R.W Portland General Electric Co. 84/02/29. SCHAEFER, K
 NRC No Detailed Affiliation Given. ip 22518:131 24X
 Fiche: 30-344:84/02/29:8403050384.
- J Insurance & indemnity information
- 8403200197 Forwards listing of present levels of property insurance & sources of insurance for facility. Info represents max amount of insurance coverage available for nuclear generating plants.

 WITHERS, B D portland General Electric Co 84/03/16. MILLER, J. R. Operating Reactors Branch 3, 2pp. 22699:356 24X

 Fiche 50-344,84/03/16,8403200197
- 8403280022 Forwards Endorsement 8 to NELIA Policy EB-57.
 HIECHMANN, S M Portland General Electric Go. 84/03/20. BALTZMAN, J.
 Assistant Director for State & Licensee Relations 3pp. 22777. 084.
 24X Fichs. 50-344, 84/03/20, 8403280022

- 8403280041 Forwards Endorsement 54 to MAELU Policy MF-86 & Endorsements 64 & 65 to NELIA Policy NF-225
 WIECHMANN, B M Portland General Electric Co 84/03/20 SALTZMAN, J
 Office of State Programs, Director App 22777 006 24X
 Fichs, 50-344, 84/03/20, 8403280041
- P. Operating license stage documents & correspondence
- 8403010117 Partial response to FDIA request for documents by named individuals re repts, analyses, studies, procedures & sys for measurement of RCB leakage App 8 documents placed in PDR App A documents already available in PDR Search continuing FELTON. J M Division of Rules and Records 84/01/25 MAPDEN. T J Kaye, 8choler, Fierman, Hays & Handler 7pp 22480,026 24X Fiche. 50-000.84/01/25.8403010117
- --8403010175 Rev 6 to Procedure POT-1-3, "Periodic Operating Test RCS Leakage Evaluation." LAMOUREAUX.T. H Portland General Electric Co 78/06/19 9pp 22481.184 24X Fiche 50-000.84/01/25.8403010117
- ---8403010233 Discusses RCS leak rate calculations, per 820504 telcon Mods to RCSLK7 computer program parmit leak rate calculations for pressures between 1,900 & 2,100 psig w/temp between 260 F & 270 F Plant data encl.

 MORRILL, F J. Region 5, Office of Director 82/05/05

 WODDUFF, R W Reactor Engineering Branch 17pp. 22481.362 24X
 Fiche: 50-000, 84/01/25, 8403010117
- 8403080344 FOIA request for documents re proposed NBHC determination on license amends for Millstone 2 & entry into operational mode for conducting final tests of pressurizer safety valves at Trojan.

 ADATD. M. Union of Concerned Scientists 84/02/02. FELTON, J. M. Division of Rules and Records ip 22583.038 24X Fiche 50-000,84/02/02,8403080344
- 8403050223 Further response to FOIA request for records of named individuals, including repts, analyses, studies, test calculations, procedures & practices for measurement of RCB leakage Forwards App C documents. Search continuing. FELTON, J. M Division of Rules and Records 84/02/07 MADDEN, T J Kaye, 8choler, Fierman, Hays & Handler 3pp 22496 234 24X Fiche 50-000, 84/02/07, 8403050223
- ---8403050250 Forwards plant-specific data cards for facilities re reactor coolent leakage calculations, per 810702 request, Add1 data cards for remaining plants will be sent shortly CREMB, J. L. Division of Resident, Reactor Projects & Engineering Inspection 81/09/16. BAER, R.L. Division of Resident & Regional Reactor Inspection 2pp. 22476 268 24X Fiche 50-000, 84/02/07, 8403050223
- 8403080179 Fourth partial (**sponse to FOIA request for six categories of documents re facilities. Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of add1 documents subj to request continuing FELTON, J M. Division of Rules and Records. 84/02/13 ANDERBON'S I Garvey, Schubert, Adams & Baper. 7pp 22583 226. 24X Fichs. 50-000, 84/02/13, 8403080179
- --B009090737 Forwards airworthiness alert re corrosive & abrasive characteristics of volcanic ash which has fallen in Pacific Northwest. Questions re ash amount, chemistry & size distribution will be forwarded to licensees. W/a encl JACKSON, R E. Gensciences Branch B0/06/12, VOLLMER, R H Division of Engineering, 2pp. 22583, 258, 24X Fiche: 50-000, 84/02/13, 8403080179.
- 8403010112 Grants 831123 & 1230 requests that Nuclear Energy Sycs. Inc rack design drawings be withheld from public disclosure (ref 10CFR2, 790). MILLER, J. R. Operating Reactors Branch 3, 84/02/21. WITHERS, B. D. Portland General Electric Co. 3pp 22479:278. 24X Fiche: 50-344, 84/02/21, 8403010112
- 8403060447 Forwards rev to 830314 order, changing completion dates for NUREQ-0737, Items II.F. 1 i, "Noble Gas Effluent Monitors" a II.F.1.2, "Iodine Monitors," from 831231 to startup for fuel Cycle 7.
 MILLER, U.R. Operating Reactors Brench 3 84/02/21. WITHERS, B. D. Portland General Electric Co 3pp 22552: 023. 24X Fiche: 80-344,84/02/21,8403060447
- --8403060449 Rev to B30314 order extending completion date for Items II.F.1:1 & II F.1:2 from B31231 to startup for 1984 refueling outsigs.

 EIBENHUT.D.Q Division of Licensing. B4/02/21 Portland General Electric Co. 4pp. 22552:026. 24X Fiche 50-344,84/02/21,8403060447.

- 8403050226 Notifies that issuance of FR notice will be delayed until supplemental info received for 840127 license change application Issuance of amend unnecessary to remove reactor vessel surveillance capsule X MILLER, J R Operating Reactors Branch 3 84/02/29 WITHERS, B D Fortland General Electric Co. 1p 22527 359 24X Fiche 50-344,84/02/29,8403050226
- 8403060382 Notifies that monthly milk sample could not be obtained during Feb 1984, because dairy animals (goats) at Location 17A not producing milk Monthly milk sample expected to be attainable for Mar 1984 HITHERS B D Portland General Electric Co 84/03/02 MILLER, J R Operating Reactors Branch 3 ip 22518 189 24X Fiche 50-344,84/03/02.8403060382
- 84030B0347 Partial response to FDIA request for documents re proposed NBHC determinations for Millstone 2 & entry into operational mode for conducting final bests of pressurizer safety valves at Trojan Forumer's App B documents.

 FELTON, J M Division of Rules and Records 84/03/02 ADATO, M Union of Concerned Scientists 40pp 22583 039 24x Fiche 50-000,84/03/02,8403080347.
- --8307180403 Initial NSHC determination & noticing action re util 830524 application to amend License NPF-1.clarifying purpose of auxiliary hoist & testing of hoist & manipulator crane TRAMMELL.C NRC No Detailed Affiliation Given 83/06/27 2pp 22583 043 24X Fiche 50-000.84/03/02.8403080347
- --8307180414 Requests FR publication of notice of consideration of issuance of amend to License NPF-1 & proposed NBHC determination & opportunity for hearing re 830524 request to heat up to hot standby mode CLARK,R A Operating Reactors Branch 3 B3/07/06 KREUTZER,P M Operating Reactors Branch 3 3pp 22583 045 24% Fiche 50-000,84/03/02.8403080347
- 8403R60071 Forwards seismology questions re WPPS-3 site, accepted NRC research proposal on subduction jone undertaken by US93 & current safety evaluation of Trojan MILLER, J R Operating Reactors Branch 3. 84/03/05 WITHERS, B D Portland General Electric Co 2pp 22757 300 24X Fiche 50-000,84/03/05,8403R60071
- --8403260077 Forwards request for add1 info re WPPS-3 site seismology, based on review of FBAR
 JACKBON,R E Geosciences Branch 83/04/28 KNIGHTON,O W
 Licensing Branch 3 9pp 22759 302 24X Fichs 50-000,84/03/05,8403260071
- --8403240083 Forwards draft BER input re WPPS-3 site geology & seismology Open items include possibility of large earthquake on subduction gone beneath site & possibility of unrecognized low angle thrust faults in site vicinity KNIOHT.J P Assistant Director for Comp. & Structures Engineering (Post 830201) 83/11/01 NDVAK.T M Assistant Director for Licensing. 18pp 22759 311 24X Ficha 50-000,84/03/05,8403260071
- --B40326008B "Northwest US Subduction Zone Seismic Risk Assessment," proposal to USOS research program for NRC.
 HEATON,T H California Institute of Tachnology, Pasadena, CA
 B4/03/26 20pp 22789 329 24X Fichs 50-000, B4/03/05, B403260071
- B403190325 Informs that requested info re core exit thermocouples & subcooling mergin monitors per NUREG-0737 & Generic Ltr 82-28 will be provided by 841231 WITHERS. BD Portland General Electric Co 84/03/12 EISENHUT, D O Division of Licensing. ip 22673 239 24X Fiche 50-344,84/03/12,8403190325
- 8403300168 Responds to 840105 Generic Ltr 84-01 re NRC use of terms important to safety & safety-related Recommends that NRC refrain from any rule changes or other regulatory process Present rules & definitions adequate MITHERS B, D. Portland General Electric Co. 84/03/27 EISENHUT, D C Division of Licensing 2pp 22821 099 24X Fiche 50-344,84/03/27,840330148
- @ Inspection reports, IE Bullatins & correspondence
- 8403060341 Forwards IE Insp Rept 50-344/83-34 on 831128-1230 No noncompliance identified BISHOP, T.W. Region 5. Office of Director. 83/02/07, WITHERS, B.D. Portland General Electric Co. 2pp. 22519 073. 24X Fiche: 50-344,84/02/07,8403060341

- --8403050344 IE Insp Rept 50-344/83-34 on 831128-1230 No noncompliance or deviations identified Major areas inspected plant operations, security, maints surveillance testing, cold weather preparation & plant review board JOHNSTON.0 W., RICHARDS, B.A., DODDS, R.T., Region 5, Office of Director 84/02/03 4pp 22519 075 24X Fiche:50-344,84/02/07,8403060341.
- 8403080408 FOIA request for repts of insp carried out under Condition 2 of Nuclear Energy Liability policies for facilities CALSOVASIC D Affiliation Not Assigned 84/02/07 Region 5, Diffice of Director, 4pp 22547 341. 24X Fiche 50-000.84/02/07, B403080408
- 8403080419 Responds to FOIA request for repts of inspicarried out under Condition 2 to Nuclear Energy Liability policies for facilities. NRC does not have repts FELTON.J M Division of Rules and Records 84/02/22 CALSOYAB, C D Affiliation Not Assigned 1p 22567 345 24% Fiche 50-000,84/02/22,8403080419
- 8403060456 Provides suppl to NRC 831219 ltr granting relief from certain inservice insp requirements of Section XI of ASME Boiler & Pressure Vessel Code Datails of reactor vessel cladding inadvertently omitted from 831219 ltr MILLER, J R Operating Reactors Branch 3 84/02/24 WITHERS, B, D Portland General Electric Co 2pp 22550 001 24X Fiche 50-344.84/02/24,8403060456
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Velve Control Circuits & Annunciation." Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/28. Consolidated Edison Co. of New York, Inc. 115pp 22909 237 24X Fiche 50-000,84/02/28,8401190072
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl. GRACE.J N. Division of GA, Safeguards & Inspection Programs (Post 830103). 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552:327 24X Fichs 50-000.84/03/02,8402090007
- 8402090008 IE Info Notice 84-i6. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl. JORDAN,E L Division of Emergency Preparadness & Engineering Response (Post 830103) 84/03/02 Consolidate Edison Co. of New York, Inc 122pp 22553.098 24X Fiche 50-000,84/03/02,8402090008
- 8402090009 IE Info Notice 84-15. "Reporting of Radiological Releases "
 Svc list encl
 JCROAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc 119pp 22553-217 24X Fiche 50-000.84/03/02.8402090009
- 8402070011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Past 830103) 84/03/05 Consolidate Edison Co of New York, Inc 117pp. 22553:336 24X Fiche: 50-000,84/03/05,8402070011
- 8402090024 IE Info Notice 84-09.Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Bys " Svc list encl.

 JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc. 118pp 22635-049 24X Fichs.50-000.84/03/07.8402090024.
- 8402090028 IE Info Notice 84-18, "Btress Corrosion Cracking in PWR Bys " Byc list enci. JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22584.186 24X Fiche: 50-000,84/03/07,8402090028
- B403200141 Discusses evaluation of BALP for Bapt 1982 Aug 1983, forwarded by NRC 831130 ltr
 WITHERS: 8 D. Portland General Electric Co. 84/03/07 MARTIN.J. 8 Region 5. Office of Director 19. 22698-361 24X
 Fiche: 50-344,84/03/07,8403200141
- 8402090031 IE Bulletin 84-02. "Failures of QE Type HFA Relays in Use in Class IE 8efety Sys " Syc list encl. DEYQUNG.R C. Director's Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp. 22823-094 24X Fiche: 50-000.84/03/12.8402090031
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PMR Reactor Cavities " Svc list enci JORDAN E. L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21, Consolidated Edison Co. of New York, Inc 123pp. 22823 227 24% Fiche 50-000,84/03/21,8402090043

- 8402090044 IE Info Notice 84~20, "Svc Life of Relays in Sefety-Related Sys " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc. 135pp 22933 001 24X Fiche 50-000,84/03/21,8402099044
- R Pariodic operating reports & related correspondence
- 8403020050 Monthly operating rapt for Jan 1984, W/840203 ltr NICHOLBON, W D , YUNDI, C P Portland General Electric Co 84/01/31 5pp 22442 001 24% Fiche 50-344,84/01/31,8403020050
- 8403300106 Monthly operating rept for Fsb 1984 W/840316 1tr PETERBON.L B . YUNDT, C P Portland General Electric Co 84/02/29 3pp 28821 218 24% Fichs 50-344, 84/02/29, 8403300106
- B Reportable occurrences, LERs & related correspondence
- 8305270051 Forwards technical review rept. "Blocking of Automatic Safety Injection (SI) Signals "LERs should be included in forthcoming power reactor events issue to alart other Westinghouse PRR operators
 CHIRAMALIM Reactor Operations Analysis Branch 83/04/25,
 SEYFRIT.K V Reactor Operations Analysis Branch 1p 22789, 292, 24X Fiche 50-000,83/04/25,8305270051
- --8305270036 "Blocking of Automatic Safety Injection (SI) Signal," technical review rept * Director's Office 83/04/25. App. 22789:293 24X Fiche 50-000:83/04/25.8305270051.
- 8403230178 Forwards Technical Review Rept AEOD/T313, "Capped Containment Pressure Sensing Lines." & proposed IE info notice Issue adequately resolved RUBIN.S D Reactor Operations Analysis Branch 83/05/11 SEYFRIT.K V Reactor Operations Analysis Branch 19 22759.286. 24X Fiche 30-000,83/05/11,8403230178.
- --8403230181 "Capped Containment Pressure Bensing Lines," technical review rept Condition caused by procedural inadequacy, RUBIN, 6 D. Director's Office. 83/05/11 opp 22759 287 24X Fichs 50-000,83/05/11.8403230178
- 8403010117 Partial response to FOIA request for documents by named individuals re repts. analyses, studies, procedures & sys for measurement of RCS leakage App B documents placed in PPR App A documents already available in PPR Search continuing. FELTON. J M Division of Rules and Records 84/01/25 MADDEN, T J Kaye, 8choler, Fierman, Hays & Handler 7pp 22480 026. 24X Fichs 50-000.84/01/25,8403010117.
- 8403010355 LER 84-002-00 on 840127, train B safety injection pump oil cooler inspected & found packed w/sediment Caused by throttled valve in cooler discharge line 8vc water side of cooler flushed W/840227 ltr
 BAIR: 0 . YUNDT, C P Portland General Electric Co 84/02/27 4pp 22433.005 24% Fiche 50-344,84/02/27,8403010355
- 8403260216 LER 84-003-00 on 840218 during periodic surveillance test, containment atmosphere sampling valve 8V-5643 failed to open Operator removed wrong fuse causing short circuit & reactor trip Wiring will be relocated W/840316 ltr BAIR.0., YUNDT.C P Portland General Electric Co 84/03/16 4pp 22756.157, 24X Fiche 50-344,84/03/16.8403260216.
- DOCKET 50-344 DAVIB-BESSE NUCLEAR POWER STATION, UNIT 1
 F Security, medical, emergency & fire protection plans
- 8403150243 Forwards order confirming commitments to implement post-THI-related items set forth in Suppl 1 to NUREQ-0737, "Requirements for Emergency Response Capability," based on util 821217 response to Generic Ltr 82-33, STOLZ.JF. Operating Reactors Branch 4, 84/02/21 CROWSE,R P Toledo Edison Co 1p 22649.001. 24X Fiche 50-346,84/02/21, 8403150243
- --8403150246 Forwards order confirming licenses commitments re emergency response capability for transmittel to Ofc of FR for publication.

 * Operating Reactors Branch 4. 84/02/21. Docketing & Services Branch. 2pp 22449.002 24X Fiche 50-346.84/02/21,8403150243.
- --8403150250 Order confirming licenses commitments on emergency response capability, per requirements set forth in Suppl 1 to NUREO-0737. "Requirements for Emergency Response Capability " EISENHUT, D 0 Division of Licensing 84/02/21. Toledo Edison Co 6pp 22649:003 24X Fithe 50-346,84/02/21.8403150243

- 8403130276 Rev 11 to Administrative Procedure AD 1827 12, "Protective Action Guidelinas." W/B40305 ltr MURRAY.T.D, Toledo Edison Co 84/02/24 25pp 22614.150 24X Fiths 50-346.84/02/244.8403130276
- 8403240394 Notification of 840321 meeting w/util in Bethesda.MD to review status for resolution of fire protection deficiencies

 DE AGAZIO.A Operating Reactors Branch 4 84/02/28 STOLZ, J F Operating Reactors Branch 4 2pp. 22775 252 24X

 Fiche 50-346.84/02/28,8403260396
- 8403050107 Forwards "Abnormal Transient Operating Ouidelines.Part I Procedurel Quidelines." Part II-Vol 1 Fundamentals of Reactor Control " & " Part II-Vol 2 ," per 830415 schedule for completing Suppl 1 to NUREO-0737 requirements CROUSE.R.P. Telede Edison Co. 84/03/01 EIBENHUT.D 0 Division of Licensing 35pp 22523 221 24X Fiche 50-046.84/03/01.8403050107
- --8403050110 Procedure 74-1125531-00, "Abnormal Transient Operating Ouidelines.Part I Procedural Quidelines "

 * Babcock & Wilcox Co. 82/10/12 86pp 22523-236 24X Fiche 80-346,84/03/01,8403050107
- --B403050114 Procedure 74-1125531-00, "Abnormal Transient Operating Quidelines.Part II-Vol 1 Fundamental of Reactor Control for Abnormal Transients"
 ** Babcock & Wilcox Co. 82/07/06 245pp 22523 342. 24X Fiche 50-346,84/03/01,8403050107.
- --8403030118 Procedure 74-1125331-00, "Abnormal Transient Operating Quidelines.Part II-Vol 2 Discussion of Selected Transients " # Babtock & Wilcox Co. 82/07/06 230pp 22524 227 24X Fichs.50-346,84/03/01,8403050107
- 8403120100 Extends invitation to attend 840323 regional workshop in Rosemont, IL re 10CFR50, App R safe shutdown requirements Workshop will cover subje described in IE Info Notice 84-07 & provide add guidance in safe shutdown analyses BPEBBARD, R L Division of Engineering 84/03/06 CROUSE, R. P Toledo Edison Co. Spp 22588 166 24X Fichs. 50-346, 84/03/06, 8403120100.
- 8403170311 Revs to emergency plan supporting procedures, consisting of Rev 204 to "Emergency Plan Supporting Procedures Rev Index" & Rev 13 to Administrative Memorandum 38-13, "First Aid Response." W/840309 transmittal & receipt form # Toledo Edison Co. 84/03/09, 4pp 22673 179 24X Fiche: 50-346.84/03/09.8403190311
- 8403260019 Forwards IE Safeguards Insp Rept 50-346/84-03 on 840221-24 & notice of violation Notice of violation & insp rept details withheld (ref 10CFR73 21) AXELSON, N. L. Ragion 3, Office of Director, 84/03/16 CROUBE, R P Toledo Edison Co. 2pp. 22747.352 24X Fiche 50-346,84/03/16,8403340019
- ~~8403260023 IE Safeguards Insp Rept 50-346/84-03 on 840221-24.
 Noncompliance noted intrusion alarms did not mest security
 plan criteria in vital & protected areas Details withheld
 (ref 10CFR73 21).
 PIRTLE: 0, L., GREED, J. R. Region 3, Office of Director 84/03/15
 2pp. 22747:354 24X Fichs. 50-346/84/03/16.8403260019.
- B403230009 Ack receipt of 840221 order confirming commitments to implement post-TMI-related items in Suppl 1 to NUREG-0737 re emergency response capability status for completing each basis requirement submitted CROUSE, R.P. Toledo Edison Cp. 84/03/20 EIBENHUT, D. Q Division of Licensing 4pp 22730/133 24X Fiche. 50-346, 84/03/20, 8403230009
- 8403270167 Temporary Change T-7803 to Emergency Plan Implementing Procedure EI 1300.0B. "Redictogical Testing Lab Equipment List." Rev 37 to revised index & 840320 transmittal ltr encl DURDEL, R. R., MURRAY, T. D. Toledo Edison Co. 84/03/20 7pp 22803:348. 24X Fiche, 50-346, 84/03/20.8403290167
- J Insurance & indemnity information
- 8403260197 Forwards Endorsement 48 to NELIA Policy NF-236, Endorsements 69 & 72 to NELIA Policy NF-208, Endorsement 59 to MAELU Policy MF-77 & Endorsement 67 to NELIA Policy NF-230. GOLDEN, M P Marsh & McLennan, Inc. 84/03/12, SALTZMAN, J. Assistant Director for State & Licensee Relations 6pp. 22751:033. 24X Fiche. 50-000, 84/03/12, 8403260197

8403300178 Submits list of insurers; policy numbers & coverage limits, in response to 10CFR50 54(w)(4) re reporting of proporty insurance coverage for facility CROUSE.R P Toledo Edison Co 84/03/26 STOLZ, J F Operating Reactors Branch 4 1p 22819-362 24X Fiche 50-346, 84/03/26, 8402300178

M Antitrust correspondence

- 8403050194 Responds to Antitrust Div request for NRC imposition of civil penalties re alleged willful failure to comply fully w/Antitrust License Condition 3 Commission believes imposition of civil penalties inappropriate PALLADINO.N J Commissioners 84/01/31 CUTLER, M S . MCGRATH, J P Justice. Dept of, Attorney General, Office of 2pp 22528.187 24X Fichs 50-000.84/01/31,8403050174
- P Operating license stage documents & correspondence
- 8403010117 Partial response to FQIA request for documents by named individuals re repts.analyses, studies, procedures & sys for measurement of RCS leakage App B documents placed in FDR App A documents already available in FDR Search tontinuing FELTON, J M Division of Rules and Records 84/01/25 MADDEN, T J Kaye. Scholer. Fierman, Hays & Handler 7pp 22480 026 24% Fichs 80-000,84/01/25,8403010117
- --B311150481 Forwards results of review of RCS leak rate test procedures & calculational methods used in 1978 at two randomly selected BWR plants, per 830920 request Dafficiencies discovered during trial use period corrected DEYOUNG.R C. Director's Office, Office of Inspection and Enforcement B3/11/07 DIRCKS.W J. Dffice of the Executive Director for Operations 22pp 22482 020 24x Fiche 50-000,84/01/25,8403010117
- 8403050053 Summary of 840203 meeting w/util at site re-review of NUREO-0737 items Agenda, attendance list & handouts encl VISBING.0 8 Operating Reactors Branch 4 84/02/23 Operating Reactors Branch 4. 24pp 22527 332 24X Fiche: 50-344, 84/02/23, 8403050053
- 8403150263 Forwards mod of order confirming licenses commitments on post-TMI-related issues Proposed implementation schedule for Items II.F i 1 & II F i 2 acceptable STOLZ, J.F. Operating Reactors Branch 4 84/02/27 CROUSE.R P Toledo Edison Co 2pp 22649 340 24X Fichs 50-346,84/02/27,8403150263
- --8403180298 Mod of order confirming licenses commitments on post-TMIrelated issues Order revised to extend completion date for Items II F. i 1 & II F i 2 from 831231 to 840331. EIBENHUT.D Q. Division of Licensing 84/02/27 Toledo Edison Ca 7pp. 22649:342 24X Fichs 50-346.84/02/27,8403150263
- 8403130133 Forwards application for amend to License NPF-3, changing Tech Spec Tables 3 3-10 & 4.3-10 to delete containment recirculating sys from post-accident monitoring requirement CROUSE, R. P. Toledo Edison Co 84/02/28 8TOLZ, J. F. Operating Reactors Branch 4. 1p 22608 164 24X Fiche 50-346,84/02/28.8403130133
- --B403130143 Application for amend to License NPF-3, changing Tech Spec Tables 3 3-10 & 4 3-10 to delete containment recirculating sys from pott-accident monitoring requirement * Toledo Edison Co 84/02/28 4pp 22608.165, 24X Fiche 50-344,84/02/28,8403130133
- --8403130154 Proposes changes to Tech Spec Tables 3 3-10 & 4 3-10 to delete containment recirculating sys from post-accident monitoring requirement.

 * Toledo Edison Co 84/02/28, 2pp 22608 169, 24X Fichs. 50-346, 84/02/28, 8403130133
- 840313042? Responds to 830706 ltr re instrumentation to detect inadequate core cooling. Detailed analysis of measurement errors for coolant inventory in hot legs & reactor vessel provided CROUSE.R. P Toledo Edison Co 84/03/09 STOLZ. J F Operating Reactors Branch 4 App 22613 127 24X Fiche 50-346.84/03/09.8403130429
- 8403150085 Forwards "B&W 177 Fuel Assembly Owners Group Bafe End Task Force Rapt on Generic Investigation of HFI/MU Nozile Cracking," summarizing util involvement in cracking program CROUSE.R.P. Toledo Edison Co 84/03/09 BTOLZ, J.F. Operating Reactors Branch 4 2pp. 22639 055 24X Fiche 50-346,84/03/09.8403150085

- 8403200046 Application to amend License NPF-3, revising Tech Specs re radiological plant effluents, offsite dose calculation manual & process control manual GROUSE, R.P. Toledo Edison Co. 84/03/15 STOLZ, J.F. Operating Reactors Branch 4. Spp. 22684 078 24x Fiche SD-346, 84/03/15, 8403200046
- --8403200052 Proposed Tech Specs re radiological plant effluents, offsite dose calculation manual & process control manual * Toledo Edison Co 84/03/15 66pp 22684 083 24X Fiche 50-346,84/03/15,8403200046
- --8403200058 "Solid Radwaste Process Control Program, Davis-Besse Nuclear Power Station " * Toledo Edison Co 84/03/31 5pp 22684 150 24X Fiche 50-346,84/03/15.6403200046
- --8403200063 "Offsite Dose Calculation Manual for Davis-Besse Nuclear Fewer Station" * Toledo Edison Co 64/03/31 186pp 22684 155 24X Fithe 50-346,84/03/15.8403200046
- 8403300149 Forwards application for amend to License NFF-3-revising Tech Spers to reflect changes in post-accident sampling sys & post-accident instrumentation for in-core thermocouple.per NURG-0737 & Generic Ltr 83-37 CROUSE.R P Toledo Edison Co 84/03/22 STOLZ.J F Operating Reactors Branch 4 3pp 22821 002 24x Fiche 50-346.84/03/22, 8403300149
- --8403300156 Application for amend to License NPF-3, revising Tech Specs to reflect changes in post-accident sampling sys & post-accident instrumentation for in-core thermocouple & reactor coolant hot leg level CROUSE.R P Tolefo Edison Co 84/03/22 7pp 22821 004. 24X Fishe 50-346,84/03/22,8403300149
- --8403300158 Proposed Tech Specs.consisting of changes to Section 6 8 4 & Tables 4 3-10 & 3 3-10 re post-accident monitoring instrumentation surveillance requirements * Toledo Edison Co 84/03/22 3pp 22821 011 24X Fiche 50-346,84/03/22,8403300149
- B403300163 Submits add1 info in support of 831202 request for exemption from requirements of IOCFR3D 54(m)(iii) re licensed operator staffing.per 840313 telcon w/NRC Responsibilities of senior reactor operator changed CRCUSE.R P Toledo Edison Co 84/03/23 STOLZ.J F Operating Reactors Branch 4 ip 22821 091 24X Fiche 50~346.84/03/23.
- O Inspection reports. IE Bulletins & correspondence
- 8403050223 Further response to FOIA request for records of named individuals, including repts, analyses, studies, test calculations, procedures & practices for measurement of RCS leakage Forwards App C documents Search continuing FELTON, J M Division of Rules and Records 84/02/07 MADDEN.T J Kayes, Scholer, Fierman, Hays & Handler 3pp 22496 234 24X Fiche 50-000, 84/02/07, 8403050223
- --B403050256 Notifies that independent measurements of identifies & unidentified RCS leek rates for all PWRs in Region III performed per Procedures 617278 & 61728B Insp findings summarized NORELIUS.C E Division of Engineering 82/03/08 JORDAN.E L Division of Engineering 82/03/08 JORDAN.E L Division of Engineering & Quality Assurance (Pre B30103) 2pp 22476 270 24X Fiche 50-000,84/02/07.8403050223
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation." Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 118pp 22909 239 24X Fiche 50-000.84/02/28,8401190072
- 8403050067 Forwards addendum to 1E Insp Rept 50-346/83-02.including confirmatory measurements program data involving comparison of gross beta analyses on spikes liquid sample Info closes Open Item 50-346/83-02-01 PAPERIELLO.C J. Region 3, Office of Director 84/02/29 CROUSE, R P Toled Edison Co. ip. 22470.180 24X Fiche 50-346.84/02/29.8403050067
- ~~8403050069 Addendum to 1E Insp Rept 50~346/83~02 re confirmatory measurements program data involving comparison of gross beta analysis on spiked liquid sample * Region 3, Office of Director 84/02/29 ip 22490 181 24X Fiche 50~346,84/02/29,8403050067

- B402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Evc list encl ORACE.J N Division of GA Safeguards & Inspection Programs (Post 830103) B4703/02 Consolidated Edison Co of New York, Inc. 130pp 22552 329 24X Fiche 50-000.84/03/02.8402090007
- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Bys Valves to Operate " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008
- B402090009 IE Info Notice 84-15. "Reporting of Radiological Releases"

 Svc list encl

 JORDAN E L Division of Emergency Preparedness & Engineering
 Response (Post 830103), 84/03/02 Consolidated Edison Co. of New
 York, Inc 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc. 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8402070024 IE Info Notice 84-09. Rev i. "Lessons Learned From Insps of Fire Protection Safe Shutdown Bys " Byc list encl UNDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc 118pp 22635 049 24X Fiche 50-000.84/03/07.8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Bys " Byc list and J JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8402090031 IE Bulletin 84-02. "Failures of GE Type HFA Relays in Use in Class IE Safety Sys." Byc list encl DEYDUND.R C Director's Defice. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co. of New York, Inc. 134pp 22823 094 24X Fiche 50-000.84/03/12.8402090031.
- 8403200008 Forwards response to IE Bulletin 83-07 re apparently fraudulent products sold by Ray Miller, Inc Bix Reco Industries. Inc flanges installed in nonsefety-related boric acid storage tanks
 CROUSE, R P Toledo Edison Co. 84/03/12 KEPPLER, J Q Region 3: Office of Director App 22685 203 24X Fiche. 50-346, 84/03/12, 840320008
- 8403260019 Forwards IE Safeguards Insp Rept 30-346/84-03 on 840221-24 & notice of violation Notice of violation & insp rept details withheld (ref 10CFR73 21)

 AXELEDNAW L Region 3. Office of Director 84/03/16 CRDUSE,R P Toledo Edison Co Rpp. 22747,352 24X Fiche: 50-346,84/03/16,8403280019.
- --8403260023 IE Bafeguards Insp Rspt 50-346/84-03 on 840221-24 Noncompliance noted intrusion alarms did not meet security plan criteria in vital & protected Areas Datails withheld (ref 10CFR73 21) PIRTLE, 0 L., CREED, J. R. Region 3, Office of Director 2pp 22747 354 24X Fiche 50-346/84/03/16.8403260017
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103), 84/03/21 Consolidated Edison Co. of New York, Inc. 123pp 22823,229 24X Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Bys." Svc list enc! JURDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21. Consolidated Edison Co. of New York, Inc. 135pp 22933 001. 24X Fiche: 50-000,84/03/21,8402090044.
- R Periodic operating reports & related correspondence
- 8403090251 Rev 1 to monthly operating rept for Bept 1983 U/840222 ltr. BARSQUR, B. HURRAY, T.D. Toledo Edison Co. 83/09/30. HALLER, N. Uffice of Resource Management, Director 2pp. 22572 202. 24X Fiche 50-346, 83/09/30, 8403090251
- 8403020078 Monthly operating rapt for Jan 1984.W/840207 ltr.
 8ARSUN.B., MURRAY.T D. Toledo Edison Co 84/01/31 HALLER, N.
 Division of Data Automation & Management Information. 6pp.
 22441 325 24X Fiche 30-346,84/01/31.8403020078

- 8403190109 "NPDES Discharge Monitoring Rept for Feb 1984 " W/840313 ltr MURRAY.T D Toledo Edison Co 84/02/29 10pp 22666 253 24X Fiche 50-346,84/02/29.8403190109
- 8403190213 Wastewater rept for Feb 1984 W/840313 ltr MURRAY, T D. Toledo Edison Co 84/02/29 9pp 22671 111 24X Fiche: 50-346, 84/02/29, 8403190213
- 8403300184 Monthly operating rept for Feb 1984 W/840309 ltr SARSQUR.B., MURRAY.T D Toledo Edison Co 84/02/29 HALLER, N Office of Resource Management, Director 6pp 22820 338 24X Fiche 50-346,84/02/29,8403300184
- B Reportable occurrences, LERs & related correspondence
- 8403210095 Part 21 rept re nonconformance of metal hose assemblies for ABME, Section III, Class 2 & 3 svc. Status of nonconforming items shipped encl All customers notified LALIKOS, J.M. Titeflex Corp 83/12/16 Director's Office, Office of Inspection and Enforcement 4pp 22704, 324, 24X Fichs 50-000, 83/12/16, 8403210095
- B401160250 Revised LER 83-040/03X-1 on 830725 auxiliary feed pump 1-1 failed to respond to speed change signals from automatic & manual control. Caused by design deficiency in clutch mechanism New design slip clutch installed W/831229 ltr THOMPBON.T. MURRAY.T D Toledo Edison Co 83/12/29. KEPPLER, J G. Region 3. Office of Director 4pp 21814-197 24X Fiche 50-346.83/12/29.8401160250
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines, Gimpel NPS-4 T&T valve, to close Enci ltr dtd 840203 sent to listed utils GE notified of affected units in BWR plants.

 THERDUX.R R Terry Corp 84/02/22 WOODRUFF, R W Director's Office, Office of Inspection and Enforcement 6pp 22706 327 24X Fiche 50-000, 84/02/22, 8403210032.
- 8403070256 Followup Part 21 rept re defective mechanical snubber capstan springs supplied by Facific Ecientific Affected utils listed Purchasers have been notified & advised to work directly w/Pacific Scientific in disposition HOVI,L. NPS Industries, Inc. 84/02/24 DEYOUNO,R C Director's Defice, Office of Inspection and Enforcement 2pp 22536 279 24X Fiche: 50-000,84/02/24.8403070256
- B403130275 PNO-III-84-021: on B40302, MBIV closure tripped reactor Cause unknown. Bafety valve stuck open following pressure reduction Incident response ctr in standby mode. JACKIM, I., B09D, D. Region 3, Office of Director 84/03/02 ip. 22607.139, 24X Fiche: 50-346, 84/03/02, 8403130275
- 8403130380 Confirmatory action ltr re 840302 unusual event following reactor trip Prior to restart, transient will be reviewed & effect of transient on Steem Generator 2 will be assessed Cause of MBIV closure will be determined KEPPLER, J. G. Region 3, Office of Director 84/03/03 CROUSE, R. P. Toledo Edison Co. 2pp. 22616.281. 24X Fiche. 50-346,84/03/03, 8403133880
- 8403130336 PNO-III-84-021A, on 840303, MSIV replaced & steam generator 2 refilled following 840302 reactor trip. Generator isolated during refilling to protect against release of radioactivity in event of steam generator tube failure

 JACKIH, I , BDYD, D. Region 3, Office of Director. 84/03/03. 2pp 22407-243 24X Fiche: 50-346, 84/03/05, 8403130336
- 8403190341 Ack receipt of 840306 ltr informing NRC of steps taken to address items contained in 840303 confirmatory action ltr KEPPLER, J. 9. Region 3, Office of Director. 84/03/14. CROUSE, R P Toledo Edison Co. ip. 22675
- --B403170349 Responds to NRC 840303 confirmatory action ltr re 840302 plant trip due to failure of main steam sefety valve to fully close.

 CROUSE: R P. Toledo Edison Co. 84/03/06. KEPPLER: J. G. Region 3: Dffice of Director 10pp. 22675: 034 24X Fiche: 50-346.84/03/14: 8403190341.
- DOCKET 30-348 JOSEPH M. FARLEY NUCLEAR PLANT, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8403140212 Public version of Rev 28 to Emergency Plan Implementing Procedure FNP-0-EIP-008, "Svc Bldg Telephone Directory " W/B30706 ltr & JM Felton 840312 release memo. HUDBPETH, J. B. Alabama Power Co. 83/07/01 77pp. 22638 137. 24X Fiche: 50-348, 83/07/01, 8403140212.

- 8403140210 Public version of Rev 4 to Emergency Plan Implementing Procedure 9D-EIP-111, "Corporate Activation & Notification Procedures " W/831025 ltr & JM Felton 840312 release memo CLAYTON;F L , MCGOWAN, J W Alabama Power Co 83/10/25 82pp 22638 237 24X Fiche 50-348/83/10/25.8403140210
- 8403090303 Public version of duty roster for First Quarter 1984; reflecting nuclear generation dept on call emergency positions & public info site coordination position W/ JM Felton release memo GIBSIN, M O Alabama Power Co 83/12/22 4pp 22584 342 24X Fiche 50-348.83/12/22, 8403090303
- 8403280198 Public version of 1984 emergency on-call coverage schedules, as part of Emergency Plan Implementing Procedure GO-EIP-111 W/840106 ltr & M Felton release memo ROBERTS.R O Alabame Power Co 83/12/29 15pp 22808 228 24X Fiche 50-348.83/12/29.8403280198
- 8403280109 Public version of temporary change notices for emergency plan implementing procedures, including Procedure 90-EIP-101 re nuclear generation dept corporate emergency operation. H/ 840126 ltr & JM Felton 840322 release memo 01880N.M O . MUDD.C H Alabama Power Co 84/01/26 20pp 22812 001 24X Fichs 50-348,84/01/26,8403280109
- 8402130400 Forwards IE Safeguards Insp Repts 50-348/84-02 & 50-364/84-02 on 840116-20 No violations noted VERRELLI.D M Division of Project & Resident Programs 84/02/08, MCDONALD,R F Alabama Fower Co 2pp 22203,251 24X Fiche 50-348,84/02/08,8402130400
- --8402130404 IE Safeguards Insp Repts 50-348/84-02 & 50-364/84-02 on 840116-20. No violations noted Major areas inspected security organization, testing & maint & physical barriers Details withheld (ref 10CFR2 790 & 73 21) MODRE, D E Region 2, Office of Director MCGUIRE, D R Division of Emergency Preparedness & Materials Safety 84/02/02 ip 22203 253 24X Fiche 50-348,84/02/08,8402130400
- 8403160142 Forwards IE Insp Repts 50-348/84-01 & 50-364/84-01 on 840118-19 No violations or deviations identified VERRELLI.D M Division of Project & Resident Programs 84/02/15 MCDDNALD.R P Alabama Fower Co 2pp 22655 325 24X Fichs 50-348/84/02/15/8403160142
- --8403160146 IE Insp Repts 50-348/84-01 & 50-364/84-01 on 840118-19 No violations or deviations noted Major areas inspected emergency preparedness area of protective action decisionmaking CLINE.W Region 2. Office of Director. JENKINB.O.R Division of Emergency Preparedness & Materials Safety 84/02/15 4pp. 22655 327 24X Fiche: 50-348,84/02/15,8403160142.
- 8403270019 Forwards IE Insp Repts 50-348/84-04 & 50-364/84-04 on 840131-0202 No violations or deviations noted VERRELLI,D M Division of Project & Resident Programs 84/02/29. MCDDNALD,R P Alabame Power Co 2pp 22806.209, 24X Fiche 50-348,84/02/29,8403290019
- --8403270027 IE Insp Repts 50-348/84-04 & 50-364/84-04 on 840131-0202, No violations or deviations noted Major areas inspected emergency exercise.

 DECKER, T.R. Region 2. Office of Director JENKINS, O.R. Division of Emergency Preparadness & Materials Bafety. 84/02/27 7pp 22806 211 24% Fiche: 50-348.84/02/29, 8403270019
- 8403080077 Forwards add1 fees for applications for fire protection reviews & approvals.

 CLAYTON.F L. Alabama Power Co. 84/03/01. MILLER.W.O. License Fee Management Branch. 1p. 22559.257. 24X Fiche 50-348.84/03/01. 840880077
- 8403160354 Notifies of fire protection workshop on 840316 in Region II ofc to discuss questions re App R requirements & results of recent App R insps.

 LEWIS, R C, Division of Project & Resident Programs 84/03/02 MCDONALD, R P Alabama Fower Co ip 22660, 192 24X Fiche 50-348, 84/03/02, 8403160354.
- 8403280329 Forwards comments on detailed control room design review program plan.per 831031 submittal Plan does not comply fully w/8uppl 1 to NUREQ-0737 requirements. Recommends meeting in Mar or Apr 1984.

 VARQA.8 A Operating Reactors Branch 1 84/03/09, CLAYTON,F L Alabama Power Co 17pp. 22807 288 24X Ficher 50-348,84/03/09, 8403280329

- 8403290078 Ack receipt of 840308 ltr informing NRC of steps taken to correct violations noted in IE insp Repts 50-348/84-03 &
- COTTREE VIOLENTE CONTROL OF Project & Resident Programs
 VERRELLID H Division of Project & Resident Programs
 Alabama Power Co. 1p 22806 311 24x MCDONALD, R P Alabama Power Co 1p 22806 311 Fiche 50-348, 84/03/14, 8403290078
- --8403290103 IE Insp Repts 50-348/84-03 & 50-364/84-03 on 840111-0205 Violation found failure to implement procedures for control
 - Violation found failure so impacts of maint activities

 Af maint activities

 BRADFIRDN H : RULAND; H Region 2. Office of Director

 CANTRELL, F S Division of Project & Resident Programs. 84/02/15

 Bpp 22806 317 24% Fiche 50-348,84/03/14,8403290078

J Insurance & indemnity information

- 8403060448 Forwards Endorsement 58 to NELIA Policy NF-238 DUCK, J.R. Harsh & McLennan, Inc. 84/02/28 SALTZMAN, J Director for State & Licensee Relations 2pp. 22518 220 Fichs 50-348.84/02/28.8403060448 Assistant
- 8403140044 Forwards Endorsement 4 to NELIA Certificate N-13 correcting name of insured on Endorsements 2 & 3 DUCK, J.R. Harsh & McLennan, Inc. 84/03/05 SALTZMAN, J. Assistant Director for State & Licensee Relations 2pp 22634 162 24X Fiche 50-348,84/03/05,8403140044
- 8403280053 Forwards Endorsements 49 & 50 to MAELU Policy MF-93 & Endorsements 59 & 60 to NELIA Policy NF-238 DUCK-JR March & McLennan Inc 84/03/20 SALTZMAN, J Assistant Director for State & Licenses Relations 5pp 22777 001 24X Fiche 50-348,84/03/20,8403280053
- P Operating license stage documents & correspondence
- 8401120594 Forwards Amends 37 & 27 to Licenses NPF-2 & NPF-8. Williador's retriands 37 & 27 to Licenses NFF-2 & NFF-6; respectively & BER Amends allow operation w/slightly positive moderator temp coefficient at low power levels & increased hot channel factor limit below full power REEVES.E A Operating Reactors Branch 1 83/12/30 CLAYTON.F Alabama Power Co 2pp 21796.274 24X Fichs 50-348.83/12/30.8401120594
- --8401120597 Amends 37 & 27 to Licenses NPF-2 & NPF-8, respectively, allowing operation w/slightly positive moderator temp coefficient at low power levels & increased hot channel factor limit below full power VARDA: 8 A Operating Reactors Branch 1 83/12/30 18pp 21796 276 24X Fiche 50-348.83/12/30,8401120594
- --8401120600 Safety evaluation supporting Amends 37 & 27 to Licenses NPF-2 & NPF-B, respectively * Office or Nuclear Reactor Regulation, Director 83/12/30 4pp 21796 294 24X Fiche 50-348.83/12/30,8401120594
- 8403010117 Partial response to FOIA request for documents by named individuals re repts, analyses, studies, procedures & sys for measurement of RCS leakage App B documents placed in PDR App A documents elready evailable in PDR Search continuing. FELTON J. M Division of Rules and Records 84/01/25 MADDEN, T Kays. Beholer, Fishman, Hays & Handler 7pp. 22480 026 24X Fiche 50-000,84/01/25,8403010117 MADDEN T J
- --B011070522 Summarizes results of independent evaluations of primary sys leak rate & some considered extensions Extension of specific evaluations to all PHR facilities recommended Draft procedure re evaluations will be submitted by B00915 JORDANNE L. Division of Reactor Operations Inspections B0/08/21 HOSELEY, N. C. Division of Reactor Operations Inspections 11pp 22480 266 24X Fiche 50-000,84/01/25,8403010117
- --8403010129 Table of "Pressurizer Design Data " Related info encl * Alabama Power Co 84/01/25 46pp 22480 033 24X Fiche 50-000, 84/01/25, 8403010117
- --8403010137 Ray 2 to Surveillance Test Procedure FNP-1-BTP-9 0. "RCS Leakage Tast " Related info encl POCLE: D L Alabama Power Co 79/03/25 22pp. 22480.079 24X Fiche: 50-000, 84/01/25, 8403010117
- --8403010141 Rev 2 to Instrument Haint Procedure FNP-1-IMP-202 B. "Vol Control Tank Level LT-112." Related info encl. HCGRACKEN.K.W. Alabema fower Co. 78/03/07 24pp 22480.101 24k Fichs. 50-000.84/01/25,8403010117
- --8403010146 Rev 2 to Instrument Haint Procedure FNP-1-IMP-201 22.
 "Pressurizer Level Control.LC-459F."
 * Alabama Power Co 78/06/17. 30pp 22480 125. 24X
 Fiche 50-000,84/01/25,8403010117

- --B403010152 Rev 1 to Instrument Haint Procedure FNP-1-IMP-202 9, "Vol Control Tank Level LT-115" THOMAS, J Alabama Power Co 78/08/02 22pp 22480 156 24X Fichs 50-000, 84/01/25, 8403010117
- --8403010156 Rev 2 to Instrument Maint Procedure FNP-1-IMP-201 28, "Pressurizer Relief Tank Level LT-470 "
 THOMAS, J Alabama Power Co 78/08/92 26pp 22480 178 24X Fichs 50-000,84/01/25,8403010117
- --8403010163 Rev 1 to Instrument Maint Procedure FNP-1-1MP-224 2, "Reactor Coolant Drain Tank Level, LT-1003 " Related info enci SHIPMAN,W B Alabama Power Co 80/01/25 62pp 22480 204 24X Fiche 50-000,84/01/25,8403010117
- 8403020156 Responds to util 830113 request for exemption from 10CFR20 re protection factors for respirators Exemption would allow credit for radioiodine protection factor while employing MSA 466220 ORR-1 canister Review continuing VARGA. S A Deprating Reactors Branch 1 84/02/17 CLAYTON.F L Alabama Power Co 3pp 22471 150 24X Fiche 50-348,84/02/17, 8403020156
- 8403010210 Notification of 840228 meeting w/util in Bethesde.MD to review changes to licensing amend schedules for 1984. REEVES,E Operating Reactors Branch 1 84/02/22 VARGA.S A Operating Reactors Branch 1 2pp 22479 197 24X Fiche 50-348.84/02/22.8403010210
- 8403070359 Notification of cancellation of 840220 meeting w/util in Bethesda, MD to discuss proposed changes to licensing amend schedules for 1984 REEVES, E. Operating Reactors Branch 1. 84/02/22 VARQA, B. A. Operating Reactors Branch 1. 2pp. 22564 145 24X Fiche 50-348,84/02/22,8403070359
- 8403020440 Notification of 840308 meeting w/vtil in Sethesda. MD to discuss proposed changes to licensing amend schedules for 1996. REEVEG.E Operating Reactors Branch 1 84/02/28 VARQA.S.A Operating Reactors Branch 1 4pp 22491 200 24X Fiche 50-348.84/02/28.8403020440
- 8403070379 Forwards Amend 43 to License NPF-2 & safety evaluation Amend consists of administrative changes to safety-related snubber Table 3 7-4a re addition of steam generator REEVES,E A Operating Reactors Branch i 84/02/27 CLAYTON, 6 Alabama Power Co 3pp 22567 043 24X Fiche 50-348,84/02/27,8403070379 CLAYTON F. L.
- --8403070382 Amend 43 to License NPF-2, consisting of administrative changes to safety-related shubber. Table 3 7-4a re addition of steam generator hydraulic shubbers VAROA, S A Operating Reactors Branch 4 84/02/29 42pp 22567 046 24% Fiche: 50-348,84/02/29,8403070379
- ---8403070384 Safety evaluation supporting Amend 43 to License NPF-2

 * Office of Nuclear Reactor Regulation, Director 84/02/29 : 22567 088 24% Fiche 50-348:84/02/29.8403070379
- 8403090255 Forwards "Analysis of Capsule U From Alabama Power Co JM Farley Unit 1 Reactor Vessel Radiation Surveillance Program " Parties Unit 1 Mactor Vessel Radiation Surveillence Program " CLAYTON F L Alabama Power Co 84/03/01 VARQA,S A Office of Nuclear Reactor Regulation, Director 2pp 22568 201 24X Fiche 50-348,84/03/01.8403070255
- --B403090259 "Analysis of Capsule U From Alabama Power Co JM Farley Unit 1 Reactor Vessel Radiation Burveillance Program " B0005:R 8 , YANICHKO, B E , CHENEY.C A Westinghouse Electric Corp WCAP-10474 84/02/29 70pp 22568 204 24X Fiche 50-348,84/03/01.8403090255
- 8403130031 Supplemental application for amend to Licenses NPF-2 & NPF-8, changing Tech Speca 3/4 7.7 & 3/4 7.8 re control room emergency ventilation sys & penetration room filtration sys, respectively & deleting 3/4 7.14 re bypass piping CLAYTON,F L Alabama Power Co 84/03/01 VAR9A,B A Office of Nuclear Reactor Regulation, Director 8pp 22615 001 24X Fiche 80-348,84/03/01,8403130031. -MRVA,8 Å Office of 22615 001 247
- --8403130038 Proposed Tech Specs 3/4 7.7 & 3/4 7.8 re control room amergency ventilation sys & penetration room filtration sys, respectively * Alabama Power Co. 84/03/01 14pp. 22615'009. 24X Ficha 50-348,84/03/01,8403130031.

- 8403130455 Application for amend to Licenses NPF-2 & NPF-8, making Tech Bpecs administrative changes NSHC determination requested CLAYTON,F L Alabama Power Co 84/03/01 VARGA, S A Office of Nuclear Reactor Regulation, Director 2pp 28613 336 24X Fiche 50-348,84/03/01,8403130455
- --8403i30463 Proposed Tech Specs.providing administrative changes * Alabama Power Co 84/03/01 10pp 22613 338 24X Fiche 50-348,84/03/01,8403130455
- B403080081 Forwards corrections to Tech Spec pages for moderator temp coefficient at low power levels submitted B31013 which contained typographical errors CLAYTON.F L Alabema Power Co 84/03/02 VARGA, S.A. Office of Nuclear Reactor Regulation, Director 1p 2R359 258 24% Fiche. 50-348, 84/03/02, 8403080081
- --8403080086 Corrected Tech Spec pages for moderator temp coefficient at low power levels * A labama Power Co 84/03/02 4pp 22559 259 24X Fiche 50-348,84/03/02,8403080081
- B4030B014B Forwards response to NRC B40104 request for add1 info re util B31230 application for change to diesal generator/river water Tech Specs CLAYTON.F.L Alabama Power Co 84/03/02 VARGA, 8 A Operating Reactors Branch 1 8pp 22559 283 24X Fiche. 50-348, 84/03/02, 84/03/0148
- 8403080138 Application for amend to Licenses NPF-2 & NPF-8, revising Tech Specs re meteorological monitoring instrumentation Change includes air temp difference to conform w/STS CLAYTON,F L Alabama Power Co 84/03/02 VARGA,8 A Office of Nuclear Reactor Regulation, Director 2pp 22539 145, 24X Fiche 50-348,84/03/02,8403080158
- --8403080195 Proposed changes to Tech Specs re meteorological monitoring instrumentation Change includes air temp difference to conform w/BTB # Alabama Power Co 84/03/02 5pp 22559 147 24X Fichs 50-348,84/03/02,8403080158
- B403210175 Requests identification of any potential problems in completing NUREO-0737 items by Sept 1984 Response requested within 30 days of ltr receipt VAROA.B.A. Operating Reactors Branch 1 B4/03/02 CLAYTON.F t. Alabama Power Co 2pp 22707.176 24X Fiche 50-348,84/03/02,8403210195
- 8403080272 Informs of delay in responding to 840217 request for add1 info re indine filter respiratory protection exemption request Reprioritization of request to 100FR20, App A, footnote (c) to 5-month interval requested CLAYTON.F L Alabama Power Co 84/03/05 VANVA.B.A Office of Nuclear Rescriberton. Director 1p 22557 294 24X Fiche 50-348,84/03/05,8403080272.
- 8403260326 Forwards corrected Tech Spec pages re reactor trip system trumentation setpoints contained in Amends 37 & 27 to Licenses NFF-2 & NFF-8, respectively, issued on 831230 REEVES, E A Operating Reactors Branch 1 84/03/08 CLAYTON, F L Alabama Power Co. 2pp 22775, 276. 24X Fichs 50-348, 84/03/08, 8403260326
- ~-8403260329 Corrected Tech Spec pages to Amends 37 & 27 to Licenses NPF-2 & NPF-8, respectively, represent trip sys instrumentation setpoints * NRC - No Detailed Affiliation Given 84/03/08 4pp 22773,298. 24X Fiche 30-348,84/03/08,8403260326
- 8403230134 Requests relief from hydrostatic testing of feedwater reducers during current refueling outage Reducers replaced after ultresonic exams found cracks in weld ereas. Radiographic & visual exams performed per IE Bulletin 79-13 CLAYTON.F.L. Alabame Power Co. 84/03/19. VAROA.8.A. Office of Nuclear Reactor Regulation, Director 4pp. 22730.207 24X Fiche 50-348.84/03/19.8403230134
- 8403260227 Application to amend Licenses NPF-2 & NPF-8, consisting of corrected Tech Specs incorporating positive moderator temp coefficient at low power levels & increased enthalpy hot channel factor limit below full power.per 831013 submittel CLAYTON.F L Alabama Power Co. 84/03/22 VARGA.S.A Office of Nuclear Reactor Regulation, Director 1p 22756 072 24X Fiche. 50-348,84/03/22,8403260227.
- ---B403260234 Corrected proposed Tech Specs, incorporating moderator temp coefficient at low power levels & increased enthalpy hot channel factor limit below full power ** Alabama Power Co. 84/03/22 10pp. 22756.073 24X Fiche.50-348,84/03/22,8403260227

- 8403280037 Application for amend to Licenses NPF-2 & NPF-8, changing Tech Specs 3 6 1 7 & 4 6 1 7 2 re containment venting Valves will be used for safety-related applications of containment pressure & radiological control CLAYTON,F L Alabama Power Co 84/03/23 VARGA,S A NRC No Detailed Affiliation Given 2pp 22777 015 24X Fiche 50-348,84/03/23,8403280037
- --8403280044 Proposed changes to Tech Specs 3 6 1 7 & 4 6 1 7 2 re containment venting * Alabama Power Co 84/03/23 4pp 22777 017 24X Fichs 50-348,84/03/23,8403280037
- 8403300077 Forwards suppl to 840319 hydrostatic testing relief request re replacement of feedwater to steam generator notals reducers Amend includes welding necessary to complete realignment of feedwater Line C CLAYTON, F L Alabama Power Co 84/03/26 VARGA, 8 A Office of Nuclear Reactor Regulation. Director 3pp 22822 084 24% Fiche 50-348.84/03/26.8403300077
- G Inspection reports, IE Bulletins & correspondence
- 8402130400 Forwards IE Safeguards Insp Repts 50-348/84-02 & 50-364/84-02 on 840116-20 No violations noted VERRELLI,D M Division of Project & Resident Programs 84/02/08 MCDDNALD,R P Alabama Power Co 2pp 22203 251 24X Fiche 50-348,84/02/08,8402130400
- --8402130404 IE Safeguards Insp Repts 50-348/84-02 & 50-364/84-02 on 840116-20 No violations noted Major areas inspected security organization, testing & maint & physical barriers Details withheld (ref 10CFR2 790 & 73 21)

 MUDRE, D E. Region 2, Office of Director MCQUIRE, D R Division of Emergency Preparedness & Materials Safety 84/02/02 ip 22203 253 24X Fiche 50-348.84/02/08.8402130400
- 8403160142 Forwards IE Insp Repts 50-348/84-01 & 50-364/84-01 on 840118-19 Np violations or deviations identified VERRELLI.D M Division of Project & Resident Programs 84/02/15 MCDONALD.R P Alabama Power Co 2pp 22655 325 24X Fiche 50-348/84/02/15/8403160142
- --B903160146 fE Insp Repts 50~348/84~01 & 50~364/84~01 on 840118-19 No violations or deviations noted Major areas inspected emergency preparedness area of protective action decisionmaking CLINE, W Region 2, Office of Director JENKINS, G R Division of Emergency Preparedness & Materials Safety 84/02/13 4pp 22695 327 24X Fiche 50~349.84/02/15.8403160142
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list enc!

 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 110pp 22909 239 24X Fiche 50-000.84/02/28.8401190072
- B403060125 Forwards summary of identified technical evaluation rept deficiencies re environ qualification of safety-related electrical equipment, defined by IE Bulletin 79-015 & NUREO-0588, respectively Encl withheld (ref 10CFR2 790) CLAYTON.F L Alabama Power Co 84/02/29 VARGA, 5 A Office of Nuclear Reactor Regulation, Director 4pp 22519 036 24X Fiche 50-348,84/02/29,8403040125
- 8403290019 Forwards IE Insp Repts 50-348/84-04 & 50-364/84-04 on 840131-0202 No violations or deviations noted VERRELLI.D M Division of Project & Resident Programs 84/02/29 MCDUNALD.R P Alabama Power Co 2pp 22806 209 24X Fiche 50-348:84/02/29.8403290019
- --8403290027 IE Insp Repts 50-348/84-04 & 50-364/84-04 on 840131-0202 No violations or deviations noted Major areas inspected emergency overcise

 DECKER, T R Region 2. Office of Director JENKINS, 0 R Division of Emergency Preparedness & Materials Safety 84/02/27 7pp
 22806 211 24X Fichs 50-348.84/02/29,8403270017
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE, J N Division of GA. Bafeguards & Inspection Programs (Post 830103) 8403/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000,84/03/02,8402090007
- 8402070008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Syc list enci JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 122pp. 22553:078 24X Fiche 50-000,84/03/02,8402070008

- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases" 402090009 IB Info notice of A-Svc list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 119pp 22853 217 24X Fiche 30-000,84/03/02,8402070009
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitragen Cooling Components Below Nil Ductility Temp " Svc list encl.

 JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co. of New York, Inc. 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8403150055 Responds to 840209 request for add1 info re IE Bulletin 80-ii concerning masonry walls. Block walls qualified by energy balance methods listed CLAYTON.F L Alabama Power Co 84/03/05. VARGA.8 A Office of Nuclear Reactor Regulation, Director. 3pp 22641 161 24X Fiche 50-348,84/03/05.8403150055
- 8403160257 Ack receipt of 840228 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-348/83-33 & 50-364/83-31 LEWIS,R C Division of Project & Resident Programs MCDONALD,R.P Alabama Power Co. ip 22660 280 £ Fiche 50-348,84/03/05,8403160257 84/03/05
- --8403160265 Responds to NRC 840203 ltr re violations noted in IE Insp Repts 50-348/83-33 & 50-344/83-31 Corrective actions personnel counseled on importance of adhering to procedures CLAYTON,F L Alabama Power Co 84/02/28 LEHIS,R C Region 2, Office of Director 4pp 22660 281 24% Fiche 50-348,84/03/05, 8403160257
- ~-8403160272 Forwards IE Insp Repts 50-348/83-33 & 50-364/83-31 on 831112-840110 & notice of violation LEMIB.R C Division of Project & Resident Programs 84/02/03 MCDONALD.R P Alabama Power Co 2pp 22660 205 24X Fiche 50-348,84/03/05,8403160257
- --8403160277 Notice of violation from Insp on 831211-840110 + Region 2. Office of Director 84/03/05 2pp 22660 287 24X Fiche 50-348.84/03/05,8403160257
- --B403i602B4 IE Insp Repts 50-34B/63-33 & 50-364/83-3i on B3121i-B401i0 Noncompliance noted failure to follow procedures & failure to establish corrective measures to insure syc water value MOV 336 remained open to supply Train B BRADFORD, W H . RULAND, W H . Region 2, Office of Director CANTRELL, F S Division of Project & Resident Programs B4/01/30 10pp 22660 289 24X Fiche 50-34B, 84/03/05, 8403160257
- 8402070024 IE Info Natice 84-07, Rev 1: "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " 8vc list encl URDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22635 049 24X Fiche 50-000,84/03/07,8402070024
- 8402090028 IE Info Notice 84-18. "Stress Corrosion Cracking in PWR Bys "Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22584 186 24X Fichs 50-000.84/03/07.8402090028
- B403290319 Responds to IE Bulletin B3-07. "Apparently Fraudulent Products Sold by Ray Miller, Inc " Results of review showed only Westinghouse supplied equipment utiliting Ray Miller components List of 30 vendors contacted encl CLAYTON.F L Alabama Power Co 84/03/09 O'REILLY, J.P. Region Office of Director 3pp 22802 067 24X Fiche 50-349,84/03/09.8403290319
- 3402090031 IE Bulletin 84-02. "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " 8vc list encl DEYOUNG!R C Director's Defice. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp. 22823 094. 24X Fiche 50-000.84/03/12.8402090031
- 3403290078 Ack receipt of 840308 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-348/84-03 & 50-344/84-03 VERRELLI, D M Division of Project & Resident Programs 84/03/14 MCDDNALD, R P Alabama Power Co ip. 22806 311, 24X Fiche: 50-348,84/03/14,8403290078
- -8403290084 Responds to NRC 840215 ltr re violations noted in IE Insp Repts 50-344/84-03 & 50-344/84-03 Corrective actions
- Repts 30-348/94-03 & 30-364/94-03 Corrective actions responsible personnel instructed to implement procedures for control of maint activities
 CLAYTON.F.L Alabama Power Co B4/03/08 VERRELLI, D M, R 2, Office of Director 2pp 22806 312 24X Fiche: 50-348, 84/03/14, 8403290078.

- --8403270087 Forwards IE Insp Repts 50-348/84-03 & 50-344/84-03 on 840111-0205 & notice of violation VERRELLI.D.M Division of Project & Resident Programs 84/02/ MCDDNALD.R P Alabama Fower Co 2pp 22806, 314 24X Fichs 50-348,84/03/14,8403290078
- --8403290076 Notice of violation from insp on 840111-0205. * Region 2, Office of Director, 84/02/15 ip 22806:316. 24x Fich: 50-348.84/03/14.8403270078
- -8403290103 IE Insp Repts 50-348/84-03 & 50-364/84-03 on 840111-0205 Violation found failure to implement procedures for control Violation found failure to implement procedures for control of maint activities

 BRADFORD.W H : RULAND.W H : Region 2, Office of Director.

 CANTRELL.F S Division of Project & Resident Progress 84/02/15

 Bpp 22806:317 24X Fiche 30-348,84/03/14,8403290078.
- 8403230134 Requests relief from hydrostatic testing of feedwater reducers during current refueling outage. Reducers replaced after ultresonic exams found cracks in weld areas Radiographic & visual sxams performed per IE Bulletin 79-13 CLAYTON.F.L Alabama Power Co. 84/03/19 VAR9A.S A Office of Nuclear Reactor Repulation, Director 4pp 22730, 207 24X Fiche. 50-348, 84/03/19, 8403230134
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PMR Reactor Cavities" 8vc list encl.

 JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21. Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Byc Life of Relays in Safety-Related Bys "Svc list enci JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc. 135pp 22933-001 24X Fiche 50-000,84/03/21,8402090044.
- R Periodic operating reports & related correspondence
- 8 Reportable occurrences. LERs & related correspondence
- 8403260233 Forwards summary list of deficiencies identified per 10CFR50 55(e), Part 21 & potential generic ltr repts for comments
 STAROSTECKI,R Division of Project & Resident Programs 84/02/28.
 Region i Office of Director, 7pp 22756 065 24X
 Fichs: 50-000, 84/02/28, 8403260233.
- 8403070263 PNG-11-84-020 on 840301, radioagraphic tests confirmed NGGO/U263 PMU-II-84-020 on 84001; racinagraphic tasts co feedwater norzie crack indications on all three steam generators Component replacements under active consideration IE & NRR informed SLAKE, J. J. BUTCHER, R. C. Region 2, Office of Director 2pp 22547:298 24X Fiche 50-348,84/03/02,8403070263 B4/03/02
- 8403090243 LER 84-002-00 on 840210; reactor tripped from approx 10X power due to intermediate range high flux signal Caused by overly conservative trip setpoints New trip setpoints inputed M/840306 ltr.
 HAIRSTUN.W 0. CLAYTON.F.L. Alabama Power Co. 84/03/06 3pp. 22573 250 24X Fiche 50-348.84/03/06.8403090243
- 8403150084 LER 84-003-00 on 840218 detensioning of reactor vessel head stude begun w/RCS boron concentration greater than Tech Spec limits Caused by misinterpretation of Tech Specs. Personnel counseled M/840307 ltr counseled. W/840309 ltr HAIRBIDN, W 0 : CLAYTON, F L Alebams Power Co 84/03/09. 3pp 22642:355. 24x Fichs:50~348,84/03/09,8403180084.
- 8403260017 Forwards LERs 84-006-00,84-007-00,84-004-00 & 84-005-00. CLAYTON, F L. Alabama Power Co. 84/03/21 Record Services Branch (Document Control Desk). 2pp 22748-348, 24% Fiche: 50-348, 84/03/21,8403260017
- ---8403260032 LER 84-007-00 on 840220 during troubleshooting, automatic actuation portion of diesel bldg cardox fire supression sys deemed inoperable Caused by wiring error. Wiring error HAIRBION, N Q Alabama Power Co 84/03/21 11pp, 22748.350, 24X Fiche.50-348.84/03/21,8403260017
- --8403250040 LER 84-004-00: on 840227, during plenned maint on MSIVs, surface indications in operator side packing bland area discovered on three of six shafts Investigation ongoing. All six shafts will be replaced HAIRSTON.W 9. Alabama Power Co 84/03/21. 2pp 22748 352, 24X Ficha 50-348,84/03/21,8403260017.

- ~-8403260046 LER 84-005-00 on 840229, during planned ultrasonic exam of feedwater piping, indications found in feedwater reducer to steam generator nozzle welds Repairs will be completed during current outage HAIRBIDN:W O Alabama Power Co 84/03/23 3pp 22748 354. 24x Fiche 50-348.84/03/21.8403260017
- 8403260026 LER 84-006-00 on 840223, w/unit in Mode 6, both containment personnel airlock doors opened simultaneously for 30 s Cause undetermined inner door immediately closed HAIRSTON, N © Alabama Power Co 84/03/21 2pp 22748 348 24X Fiche. 50-348, 84/03/21, 9003260017
- DUCKET 50-352 LIMERICK GENERATING STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8402090003 Responds to FOIA request for const completion dates for nuclear plants currently under const & analyses containing astimates based on inclusion of Caseload Forecast Panel meetings. Forwards App A, B & C documents
 FELTON.J M Division of Rules and Records 83/10/31
 ROSENBAUM.D M Technical Analysis Corp 19pp 22193 292. 24X
 Fichs 50-000.83/10/31.8402090003
- --8402070183 Handwritten notes & calculations re const activities & fuel load preparation.

 * NRC No Detailed Affiliation Given. 79/07/24 5pp 22195:057 24X Ficha 50-000:83/10/31:8402090003
- 8401240207 Forwards add1 info re stress-assisted corrosion cracking of primary sys comments & potential main cooling tower failure modes & consequences in response to ACRB 631018 1th KEMPER, J 8 Philadelphia Electric Co 84/01/18 ECHWENCER, A Licensing Branch 2 3pp. 21908 148 24X Fiche 50-352,84/01/18,8401240207
- --B401240211 "Rept on Effects of Postulated Failure of Cooling Tower"

 W/three oversize drawings Aperture cards are available in
 POR.

 * Philadelphia Electric Co P-281/2 83/12/31 15pp
 21908 151 24X Fiche: 50-352,84/01/18,8401240207
- 8403020104 Forwards magnetic tape containing hour by hour meteorological data for Oct 1983 Jan 1984, per 831013 ltr Data from primary meteorological tower & satellite tower & tape formats described KEMPER, J 8, Philadelphia Electric Co 84/02/27 SCHWENCER, A Licensing Branch 2 3pp 22443.240 24X Fiche 50-352, 84/02/27, 8403020104.
- B403020257 Forwards application for amend to CPPR-106 & CPPR-107 (filed in Category A), Rev 17 to environ rept OL stage (filed in Category C) & Rev 29 to FSAR (filed in Category K).

 BRADLEY, E J Philadelphia Electric Co. 84/02/29 DENTON, H R

 Office of Nuclear Reactor Regulation, Director 2pp 22495 026
 24X Fiche 50-352,84/02/29,8403020257
- --8403020266 Application for amend to CPPR-106 & CPPR-107. Certificate of Byc encl KEMPER, J S Philadelphia Electric Co 84/02/27 App 22495 028 24X Fiche: 50-352, 84/02/29, 8403020257
- 8403150262 Forwards request for add1 info re standby gas treatment sys Info needed to evaluate FSAR, Section 6 5. Rev 25. BCHMENGER, A. Licensing Branch 2. 84/02/29. BAUER, E. G. Philadelphia Electric Co. 4pp. 22648 342 24X Fiche. 50-352, 84/02/29, 8403150262
- 8403160189 Notification of 840314.15 & 16 mestings w/util in Philadelphia/PA & Montgomery County.PA respectively.to discuss NRC audit of environ qualification files & installed equipment.

 KINTNER, L Licensing Branch 1, 84/03/05 BCHWENCER, A. Licensing Branch 2, 4pp 22662/259 24X Fiche 50-352,84/03/05.8403160189
- 8403160192 Advises of errors made in wind direction frequencies for GRAC2 calculation. Revised calculations for severe accident risk assessment expected to change predicted latent cancer fatalities.

 KEMPER. J. 8 Philadelphia Electric Co 84/03/13, 8CHWENCER, A Licensing Branch 2, 2pp 22655 244, 24% Fiche 50-352, 84/03/13, 8403160192.
- B403190197 Forwards Rev C to Anchor/Darling Valve Co Drawing 93-14182, correspondence re HPCI,RCIC & reactor water cleanup containment isolation valve closure capabilities & Rev 23 to Matl Requisition 8031-P-104.per 840202 telcon.

 KEMPER.J. B Philadelphia Electric Co. 84/03/13. BCHWENCER.A. Licensing Branch 2 134pp 22670 001. 24X Fiche 50-352,84/03/13. 8403190197.

- 8402090041 Board Notification 84-050 provides Commission policy statement & proposed rulemaking on environ qualifications EISENHUT.D & Division of Licensing 84/03/14 Atomic Safety and Licensing Board Panel 10pp 24X Fiche 50-000.84/03/14,8402090041
- 8403270172 Informs that 840801 is current const completion date; per 810811 request for quarterly updates Possibility of advancing date being reviewed, per util 831227 ltr Svc list enc!

 KEMPER, J 8 Philadelphia Electric Co 84/03/22 E(SENHUT, D 0 Division of Licensing 2pp 22771 309 24X Fiche 50-352, 84/03/22, 8403270172
- C Utility Environmental Report (ER). amends & correspondence
- 8403020257 Forwards Rev 17 to environ rept OL stage BRADLEY,E J Philadelphia Electric Co 84/02/27 DENTON,H R Defice of Nuclear Reactor Regulation, Director 2pp 22495 026 24X Fiche 50-352,84/02/29,8403020257
- --8403020270 Rev 17 to environ rept OL stage * Philadelphia Electric Co 84/02/29 20pp 22495 034 24x Fiche 50-352,84/02/29,8403020257
- B403150036 Forwards Affidavit of Svc re distribution of Rev 29 to FBAR & Rev 17 to environ rept, per DO Eisenhut 810706 request BRADLEY,E J Philadelphia Electric Co 84/03/12 DENTON,H R Office of Nuclear Reactor Regulation, Director 5pp 22643 270 24X Fiche 50-352,84/03/12,8403150036
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- 8403160026 Notifies that Natl Ctr for Devices & Radiological Health has no comment re postulated plant accidents described in DES (NUREO-0974)

 VILLFORTH, J C Food & Drug Administration 84/02/10 SCHHENCER, A Licensing Branch 2 1p 22634 346 24X Fiche 50-352, 84/02/10, 840316026
- E NRC Safety Evaluation Report (BER), suppls & correspondence
- 84030i0144 Forwards draft FPER pages containing info to close BER Open Issue 15 re electrical cable & cable tray & fire areas having high concentrations of cables Info in draft FPER will be incorporated into Rev 5 scheduled for Mar 1984 BOYER.V 8 Philadelphia Electric Co 84/02/16 SCHMENCER.A Licensing Branch 2 9pp 22435 313 24X Fiche 50-352.84/02/16.8403010144
- 8403050161 Forwards "Structural Steel Survivability Evaluation." in response to 840209 request for addl info (RAI 280 26). per SER Open Item 14
 KEMPER. J. 8 Philadelphia Electric Co 84/02/29 SCHWENCER, A Licensing Branch 2 3pp 22483 037 24x Fiche 50-352,84/02/29,8403050161
- --8403050163 "Structural Steel Survivability Evaluation " Rev 1 to "Comparison of Philadelphia Electric Co Heat Balance Model w/NVREO/CR-3192" encl * Philadelphia Electric Co 84/02/24 372pp 22483 040, 24X Fiche 30-352,84/02/29,8403050161
- B403260249 Forwards "UHS Extreme Hind Hazard Analysis." in response to B3080B ltr re SSER Open Issue 2 KEMPER, J B Philadelphia Electric Co B4/03/22 SCHWENCER, A Licensing Branch 2 2pp 22755 001 24X Fiche 50~352,84/03/22,
- --8403260253 "UHS Extreme Wind Hazard Analysis"
 BITOWF.TB: PARRY.G.W NUS Corp NUS-4507 84/03/31 134pp
 22755 004 24X Fiche 50-352.84/03/22.8403260249
- F Becurity, medical, emergency & fire protection plans
- 8403070361 Public version of revised emergency plan implementing procedures, including Procedure EP-201 rs technical support ctr activation: EP-210 rs dose assessment team & EP-222 rs field survey group W/831212, 840215 ltrs & 840302 memo DALTROFF, S L. Philadelphia Electric Co. 83/11/30 MURLEY, T E Ragion 1, Office of Director. SCHMENCER, A. Licensing Branch 2 165pp 22564 061 24x Fichs. 50-352, 83/11/30, 8403070361.
- 8403090290 Public version of Rev O to emergency plan implementing procedures including Procedure EP-110 re personnel assembly, EP-221 re personnel dosimetry & EP-208 re security team activation W/831212 ltr & JM Felton release memo DALTROFF, St. Philadelphia Electric Co. 83/11/30 SCHWENCER, A Licensing Branch 2, 80pp. 22592 062 24X Ficha 50-352,83/11/30,8403070290

- 8403010144 Forwards draft FPER pages containing info to close SER Open Issue 15 re electrical cable & cable tray & fire areas having high concentrations of cables Info in draft FPER will be incorporated into Rev 5 scheduled for Mar 1984 BOYER.V S Philadelphia Electric Co 84/02/16 SCHMENCER.A Licensing Branch 2 9pp 22435 313 24X Fiche 50-352,84/02/16,8403010144
- 8402090006 Board Notification 84-034 forwards R Vollmer 840206 memo to D Eisenhut re fire research results concerning fires in electrical cabinets in control room EISENHUT, D G Division of Licensing 84/02/23 FALLADING Commissioners ip 22576 203 R4X Fiche 50-000.84/02/23, 8402090006
- --8403080316 Recommends that info re fire research results concerning fires in electrical cabinets in control room be submitted for board notification per NRR Ofc Ltr 19,6td 821001 Further evaluation of test deta required VOLLMER,R H Division of Engineering. 84/02/06 EISENHUT,D 9 Division of Licensing 10pp 22576 204 24X Fiche 50-000,84/02/23.8402090006
- 8403190243 Notification of 840418 workshop in King of Prussia.PA to discuss lessons learned from recent App R fire protection safe shutdown insp & topics described in IE Info Notice 84-03 Agenda for workshop encl MURLEY.TE Region 1. Diffice of Director 84/03/09 0'TODLE, J D Consolidated Edison Co of New York. Inc. FIEDLER.P D General Public Utilities OPU Service Corp. 33pp 22672-062 24X Fiche 50-000.84/03/09.8403190243
- 8403290144 Forwards IE Insp Rept 50-352/84-08 on 840205-09 No violations noted MARTIN:T T Division of Engineering & Technical Programs 84/03/13 KEMPER:J S Philadelphia Electric Co 2pp 22806 096 24X Fiche 50-352/84/03/13/8403290144
- --8403290:50 IE Insp Rept 50-352/84-08 on 840206-09 No violations noted Major areas inspected onsite/offsite safety committee activity, operational staff training & fuel receipt & storage programs PRELL JA & BISSETT, P. GLIVEIRA: W. Region 1, Office of Director 84/03/07 8pp 22806 098 24% Fichs 50-352,84/03/13,8403290144
- 8403210028 Forwards response to NRC 840306 & 08 requests for add1 info re emergency action levels, specifically, containment radiation levels Braft changes to emergency plan will be incorporated as stated in encl
 DALTROFF, S L Philadelphia Electric Co 84/03/16 BCHWENCER, A Licensing Branch 2 80pp 22708 255 24X Fiche 50-352,84/03/16,8403210028

G Adjudicatory correspondence

- 840301027: Forwards reply to applicant & staff response to City of Philadelphia issues
 SMOLEN, H Philadelphia, PA 84/02/28 Docketing & Services
 Branch ip 22432 207 24X fiche 50-352,84/02/28,840301027:
- --B403010275 Reply to applicant & staff responses to City of Philadelphia issues to emergency response plan State plan does not contain & is not based upon standardized protective action guidance for exposure from feefstuffs & water SMOLEN:H Philadelphia: PA 84702/28 Atomic Safety and Licensing Board Panel 43pp 22432 208 24X Fiche 50-352,84702/28,8403010271
- 8403020099 Forwards answer to City of Philadelphia interrogatories on sys interaction, designated Discovery 28 W/exception of three listed documents, documentary mati responsive to request will be made available for insp Related correspondence WETTERHAHN, H J Conner & Wetterhahn 84/02/29 BUSH, M W Philadelphia, PA 6pp 22443 048 24% Fiche 50-352,84/02/29,8403020099
- --B403020105 Answers City of Philadelphia interrogetories on sys interaction contention Certificate of Svc encl.Related correspondence BOVER.V S Philadelphia Electric Go 84/02/27, 65pp 22443 054 24X Fiche 50-352,84/02/29,8403020099.
- 8403020125 Transmittal of math supporting applicant 840228 revised testimony re ability of safety-related structures to withstand effects of postulated detonation from pigeline ruptures Certificate of Svc encl Related correspondence. WETTERHAHN.M J Philadelphia Electric Co WETTERHAHN.M J Conner Metterhahn. 84/02/29 4pp 22442 143 24X Fiche 50-352,84/02/29,8403020125

- 8403020163 Response opposing new contention proposed by Air & Water Pollution Patrol re discharge of asbestos fibers Contention lacks basis & specificity required by 10CFR2 714(b) Ceptificate of Evc encl METTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn B4/02/27 Atomic Safety and Licensing Board Panel lipp 22442 006 24X Fichs 50-352,84/02/29,8403020163
- B403060129 Forwards Certificate of Svc for reply to applicant & staff responses to City of Philadelphia issues SMOLEN, H Philadelphia. PA 84/02/29 Docketing & Services Branch 3pp 22506-327 24X Fiche 30-352, 84/02/29, 8403040129
- B403060081 Response opposing Friends of the Earth 840224 motion to strike applicant & staff structural analysis testimony Motion fails to establish testimony as unreliable Cartificate of Bvc encl Related correspondence WETTERHAHN, M Philadelphia Electric Co METTERHAHN, M Conner & Wetterhahn 84/03/01 Atomic Safety and Licensing Board Panel Opp 22516 339 24X Fiche 30-352,84/03/01,8403060081
- 8403060248 Amswer to new contentions proposed by Friends of the Earth on onsite storage of unirradiated fuel & transmittal of related correspondence Proposed late contentions should be denied Certificate of 80c encl
 METTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 84/03/01 Atomic Safety and Licensing Board Panel 33pp 22517 079 24X Fiche 50-332,84/03/01,8403040248
- 8403140118 Forwards cross-examination plans for structural analysis hearing on blast overpressures.per ASLB 840120 order W/o enc!

 VOGLER.B H Hearing Branch 2. 84/03/01 BRENNER.L., COLE.R F, MORRIS.P A Atomic Safety and Licensing Board Panel 2pp 22623 338 24X Fiche 50-252,84/03/01.8403140118
- 8403060097 Memorandum & order denying intervenor Lewis 831224 motions based on newly received info Lewis discovery rights not abridged per Contention 1-62 W/Centificate of 8vc BRENNER.L., CDLE.R.F., MORRIS.P.A. Atomic Safety and Licensing Board Panel 84/03/02 Lewis, M. 11pp 22506-262 24X Fichs 50-332.8403/02.8403060097
- 8403070142 Response opposing Air & Water Pollution Patrol 840221 request for extension of discovery period for Contention VI-1 Certificate of Svc encl Related correspondence HETTERHAHN.M J Philadelphia Electric Co HETTERHAHN.M J Conner & Wetterhahn 84/03/02 Air and Water Pollution Patrol 7pp 22538 291 24% Fiche 50-352,84/03/02.8403070142
- 8403070236 Response to Air & Water Pollution Patrol mation to compel discovery Applicant denies that answer to interrogatory evasive Related correspondence WETTERHAHN, H J Philadelphia Electric Co WETTERHAHN, H J Conner & Wetterhahn 84/03/02 Atomic Safety and Licensing Board Fanel 3pp 22536 217, 24X Fiche 50-352,84/03/02,8403070236
- --840307023B Response opposing Air & Water Pollution Patrol request for depositions re Contention VI-1 No reason given why depositions necessary W/Certificate of Byc WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 84/03/02 Atomic Safety and Licensing Board Panel Opp 22536 221 24X Fichs 50-352,84/03/02.8403070236
- 8403140085 Response opposing Friends of the Earth 840223 application to file contention based on new matter re fuel storage Certificate of Svc encl WILCOVE.M N Hearing Branch 2 84/03/02 Atomic Safety and Licensing Board Panel 14pp 22633.235 24X Fiche 50-352.84/03/02.8403140085
- 8403140115 Response to Limerick Ecology Action & City of Philadelphia contentions filed on 840214 re environ assessment of severe accidents as set forth in DES, Suppl 1 Certificate of Svc encl VOCLER. B H. HOPODON, A P. Hearing Branch 2 84/03/03 Atomic Bafety and Licensing Board Panel. 17pp 22623,340 24X Fichs 30-332,84/03/03.8403140115
- 8403120001 Notice of withdrawal of offsite emergency planning issue re evacuation time estimate study Applicant 840824 representation addresses issues W/Certificate of Syc FERKIN, 7 G Pennsylvania, Commonwealth of, 84/03/05 5pp 22588.036 24X Fiche 50-352,84/03/05,8403120001
- B403140105 Response opposing Air & Mater Pollution Patrol (AWPP) 840215 motion filing new info contention. AWPP fails to meet stds for laterfiled contentions Certificate of Byc encl WRIGHT, NA Hearing Branch 2 84/03/05 Atomic Safety and Licensing Board Panel 8pp 22623.330 24X Fiche 50-352,84/03/05,8403140105

- B403130411 Forwards notice of change of address & firm name Certificate of Svc encl
 SUGARMAN,R J Bugarman & Denworth SUGARMAN,R J Del-Aware
 Unlimited, Inc 84/03/07 Docketing & Services Branch 6pp
 22414 319 24% Fiche 50-352,84/03/07,8403130411
- 8403140110 Findings of fact & conclusions of law in form of partial initial decision on Air & Water Pollution Patrol Contention V-4 re carburator icing Certificate of Svc encl HODOPONA P Hearing Branch 2 84/03/07 25pp 22624 075 24x Fichs 50-352,84/03/07,8403140110
- B403150024 Reply findings of fact & conclusions of law re Contention V-4 in response to Air & Water Pollution Patrol (AWPP) B40224 proposed findings AWPP findings should be rejected Certificate of Svc encl METTERHAHN M J , NICHOLS, N N Philadelphia Electric Co WETTERHAHN M J Conner & Wetterhahn 84/03/12 9pp 22641 282 24X Fiche 50-352,84/03/12,8403150024
- 8403190007 Responses to util interrogatories on Contention I-42 Gentificate of Svc encl Related correspondence * Philadelphia PA. 84/03/12 Philadelphia Electric Co 15pp 22665 337 24x Fiche 50-352.84/03/12.8403190007
- 8403160010 Forwards affidavit of LB Pyrih & PS Stansbury re hypothetical accidents involving unirradiated fuel to be stored at plant No credible potential for violating regulations identified Related correspondence WETTERHAHN, M J Philadelphia Electric Co. WETTERHAHN, M, J Conner & Wetterhahn 84/03/13 ip 22662 164 24X Fichs 50-352.84/03/13, 8403160010
- --8403i60187 Affidavit of LB Pyrih re storage of Unirradiated fuel No potential for violating provisions of 10CFR20 as result of credible accidents affecting new fuel assemblies stored at plant Certificate of Svc encl
 PYRIH.L B Philadelphia Electric Co 84/03/13 22pp 22662 165 24X Fiche 50-352,84/03/13,8403i60010
- --8403160188 Affidavit of PS Stansbury re calculation of exposure rates in various assumed configurations of specified quantities of U enriched to 1 85% in isotope U-235 STANSBURY: P 8 General Electric Co 84/03/12 9pp 22662 186 24% Fiche 30-352.84/03/13.8403160010
- 8403190132 Appeal opposing dismissal of Anthony/Friends of the Earth contention on util application to store nuclear fuel outdoors & ASLB denial of immediate stay on moving fuel ANTHONY, R L ANTHONY, R L Friends of the Earth 84/03/13 Atomic Safety and Licensing Appeal Panel ip 22666-306 24X Fiche. 50-352, 84/03/13, 8403190132
- --B403190138 Application to file contention re util application to store fuel outdoors Fuel storage is hazard to community due to question of whether bldgs can withstand overpressures & impacts from offsite accidents.

 ANTHONY.R L ANTHONY.R L Friends of the Earth B4/02/23 Atomic Bafety and Licensing Board Fanel 1p 22666 307 24X Fiche. 50-352,84/03/13,8403190132
- 8403170160 Affidavit of N Ketrlach re possibility of radiological releases from fuel assemblies in shipping containers in violation of NRC regulations Centificate of Svc encl KETILACH.N Uranium Fuel Licensing Branch 84/03/13 5pp 22668.358. 24X Fiche 50-352.84/03/13,8403170160
- 8403190173 Forwards ND Romney 840313 memo to G Lear re results of 840306 conference call from applicant. VOOLER, B H Hearing Branch 2 84703/13 BRENNER, L, MORRIS, P A, COLE, R F Atomic 8afety and Licensing Board Panel 4pp 2267; 158 24X Fichs 50-352,84/03/13,8403190173
- 8403200090 Forwards 840313 ltr documenting discovery of errors in predicted consequences reported in severe accident risk assessment Consideration of admissibility of contentions should proceed as scheduled, Related correspondence HETTERHAHN, M J Conner & Wetterhahn WETTERHAHN, M J Philadelphia Electric Co. 84/03/13 BRENNER, L. , MORRIB, P A., COLE, R F Atomic Safety and Licensing Board Panel. 3pp 22685, 278 24X Fiche: 50-352, 84/03/13, 8403200090
- 8403200144 Forwards listed add1 info re HPCI isolation valves.per NRC Equipment Qualification Branch 840202 telcon request W/o encl. Related correspondence
 KEMPER, J 8 Philadelphia Electric Co 84/03/13 BCHWENGER, A Licensing Branch 2 2pp 22699:159 24X Fiche 50~352,84/03/13, 8403200144.

- 8403190038 Motion for new contention based on IE Notice 84~17 reproblems w/liquid nitragen cooling components below nil ductility temp Facility design deficient because liquid nitrogen can cool vital components below temp.

 LEWIS, M I Lewis, M 84/03/14 Atomic Safety and Licensing Board Panel 4pp 22666 235 24X Fiche 50-352, 84/03/14, 8403190038
- 8403170040 Order directing parties to hold settlement conferences for onsite emergency planning contentions Courtesy notification encl
 BRENNER, L. Atomic Safety and Licensing Board Panel 84/03/15
 Office of the Executive Legal Director 5pp 22666 240 24X
 Fiche 50-352.84/03/15.8403190040
- 8403190140 Supplemental info on Limerick Ecology Action offsite emergency planning Contentions 3,4,13,17,20 & 28 requested at pre-hearing conference Certificate of Svc encl * Limerick Ecology Action 84/03/15 Atomic Bafety and Licensing Board Panel 34pp 22666 316 24X Fiche 50-352,84/03/15,8403190140
- 8403190153 Order confirming miscellaneous oral rulings made at hearing held during wk of 840305 Testimony & hearing schedules listed Courtesy notification encl.

 BRENNER, L. Atomic Bafety and Licensing Board Panel 84/03/15

 Office of the Executive Legal Director. 8pp. 22668,346 24X

 Fiche 50-352.84/03/15.8403190153
- 8403200015 Forwards revised radiological emergency response plan for Pennhurst Mental Retardation Ctr to ASLB, intervenors & City of Philadelphia W/o encl Related correspondence BELSER, A L Pennsylvania, Commonwealth of, 84/03/15 BRENNER, L MORRIB, P A , COLE, R F Atomic Safety and Licensing Board Panel 2pp 22698:344 24X Fiche 50-332,84/03/15,8403200015
- 8403200060 Forwards "Protective Order on SNM Security Plan Info" & "Affidavit of Non-Disclosure" re storage of irradiated fuel Certificate of Bvc encl Related correspondence. METTERHAHN.M J Canner & Wetterhahn WETTERHAHN.M J Philadelphia Electric Co 84/03/16 BRENNER.L, COLE.R F. MORRIS.P A Atomic Bafety and Licensing Board Panel 14pp 22684 342 24X Fiche 50-352.84/03/16.8403200060
- 8403200070 Memorandum & order on Friends of the Earth contentions & Limerick Ecology Action petition re Part 70 application to store new fuel BRENNER.L. MORRIS.P A Atomic Safety and Licensing Board Panel 84/03/16 30pp. 22685-106 24X fiche.50-352.84/03/16.8403200070
- 8403200110 Requests that encl AS Joffe 840311 ltr re assestos piping be served to parties in proceeding LANE,V.M. Atomic Sefety and Licensing Board Penel. 84/03/14 CLEMENTS, W.L. Office of the Secretary of the Commission 2pp 22697-043 24X Fiche 50-352,84/03/14,8403200110
- 8403210067 Forwards Commission statement of policy re challenge to elimination of financial qualification review requirements Related correspondence WRIGHT,N A Hearing Branch 2 84/03/16, BRENNER,L, MORRIS,P A, COLE,R F, Atomic Sefety and Licensing Board Panel 4pp 22705 052 24X Fiche. 50-352,84/03/16,8403210067
- 8403210096 Forwards Transportation Certification Branch 840312 memo & Certificate of Compliance mentioned in 840313 affidavit of N Ketzlach, Related correspondence WRIGHT, N A Hearing Branch & 84/03/16 BRENNER, L , MORRIS, P A , COLE, R F Atomic Safety and Licensing Board Panel 7pp 22706 001 24X Fiche 50-352,84/03/16,8403210096.
- 8403210128 Forwards Delaware River Basin Commission Aug 1980 final environ assessment for Neshaminy Water Supply Bys & 800825 negative declaration.per ASLAB 840315 telcon request W/o enc! Related correspondence
 HDD000N.A P Hearing Branch 2 84/03/16 NGHL.C N . EDLES.0 J . 60TCHY.R L Atomic Safety and Licensing Board Panel 2pp 22707-242 24X Fiche 50-352,84/03/16,8403210128
- 8403280354 Memorandum & order on Friends of the Earth contentions & Limerick Ecology Action petition based on 100FR70 application to store new fuel Berved on 840327 BRENNER.L. MORRIS.P A Atomic Safety and Licensing Board Panel D88 147 84/03/16 Friends of the Earth 30pp 22787 174 24x Fiche 50-352-84/03/16,8403280354
- 8403210092 Answer to Limerick Ecology Action (LEA) supplemental info on LEA offsite emergency planning contentions Proposed contentions should be denied Certificate of Syc encl CONNER.T B Philadelphia Electric Co. CONNER.T B Conner & Wetterhahn 84/03/19 17pp. 22705 322 24X Fiche 50-352,84/03/19,8403210092

- 8403210103 Motion to delete specific instances in support of Contention VI~i advanced by Air & Water Pollution Patrol as unseleted to welding or uselding (A activities Certificate of Svc encl HETTERHAKN, M J Philadelphia Electric Co METTERHAKN, M J Conner & Wetterhahn BA/O3/19 Atomic Safety and Licensing Board Panel 10pp 22706 118 24X Fiche 30-352.84/03/19,8403210103
- 8403210167 Forwards Commission "Statement of Policy on Environ Qualification" & proposed rule, "Environ Qualification of Electric Equipment, Removel of B20630 Deadline " Related correspondence HODGDDN.A P Hearing Branch 2 DSB 017 84/03/19 BRENNER,L, COLE.R F, MORRIS,P A Atomic Safety and Licensing Board Panel 11pp 22710 133 24X Fiche 50-352,84/03/19,8403210167
- 8403220226 forwards request for reconsideration of asbestos contention & motion requiring further depositions re Contention VI-I ROMANG, F.R. Air and Water Pollution Patrol DBB 046 B4/03/19 BRENNER, L., MORRIS, P. COLE, R. Atomic Safety and Licensing Board Panel ip 22719 007 24X Fishe 50-332, 84/03/19,8403220226
- ---8403220227 Request for reconsideration of asbestos contention Board did not adequately address hazard to public ROMAND.FR Air and Water Pollution Patrol 84/03/19 BRENNER,L. MORRIS.P. COLE.R. Atomic Safety and Licensing Board Panel 2pp 22719 008 24% Fiche 50-352,84/03/19,8403220226
- --9403220234 Motion to require further depositions re Contention VI-I concerning 760601 broomstick deficient welding affair RDMAND.F Air and Water Pollution Patrol 84/03/19 BRENNER.L., COLE,R Atomic Safety and Licensing Board Fanel 2pp. 22719 010 24X Fiche 50-352,84/03/19,8403220226
- 8403270065 Protective order on SNM security plan info Served on B40326 BRENNER.L. Atomic Safety and Licensing Board Panel DSB 123 84/03/19 Limerick Ecology Action 3pp 22766 149 24X Fiche 50~352.84/03/19,8403270065
- --8403270069 Affidavit on nondisclosure for CW Elliott ELLIOTT, CW Limerick Ecology Action 84/03/16 4pp 22766 i52 24x Fiche 50-352,84/03/19,8403270065
- 8403270378 Request for reconsideration of Air & Water Pollution Patrol asbestos contention ROMAND.F R Air and Water Pollution Patrol DSB 186 84/03/19 Atomic Safety and Licensing Board Panel 2pp 22814 142 24x Fiche 50~352
- 8403270017 Supplemental responses to info requests of City of Philadelphia Related correspondence SOYER.V S Philadelphia Electric Co DSB 112. 84/03/21 12pg 22770 056 24X Fiche 50-352.84/03/21.8403270017
- 8403280336 Forwards complaint of util vs Bouth Coventry Township filed on 840309, memorandum of law in opposition to petition for Preliminary Injunction 84-01645 & order of court dissolving injunction against Township Related correspondence 21TZER.P Limerick Ecology Action DSB 145 84/03/21 BRENNER, L MDRRIS.P A. COLE.R F. Atomic Safety and Licensing Soard Panel 32pp. 22787 065 24% Fiche 50-352,84/03/21,8403280336
- B403230005 Order delegating authority to exercise raview functions over Part 70 issues raised in proceeding to Appeal Board Served on B40322 CHILK.S J Office of the Secretary of the Commission DSG 070 B4703/22 Atomic Safety and Licensing Appeal Panel 202726 359 24X Fiche 50-352.84/03/22.8403230005
- 8403230278 Order confirming briefing schedule for Friends of the Earth appeal of ASLB 840316 memorandum & order & for staff to provide Part 70 application SHOEMAKER.C J Atomic Safety and Licensing Appeal Panel DSB 077 84/03/22 Office of the Executive Legal Director 2pp 22743 094 24% Fiche 50-352, 84/03/22, 8403230278
- B403260333 Forwards supplemental correspondence & documents re emergency planning. Matl suppls earlier ltrs & covers period B40206-0315 W/o encis Related correspondence BRADLEY, E J Philadelphia Electric Co DSB 09B 84/03/22 7172ER:P Limerick Ecology Action 2pp 22760 162 24X Fiche 50-352,84/03/22.8403260333
- 8403270012 Informs that applicant will suppl 840217 responses to Info Requests 6.7:11 & 12 Related correspondence WEYTERHAHN.M J Conner & Wetterhahn WEYTERHAHN,M J Philadelphia Electric Co DSB 109 84/03/22 BUSH.M W Philadelphia, PA 2pp 22769 336 24X Fiche, 50-352, 84/03/22, 8403270012

- 840327007: Informs that feasibility of 84080: as current const completion date will be reviewed for possible advancement Related correspondence
 KEMPER. J 8 Philadelphia Electric Co D88 108 84/03/22
 EIBENHUT, D 0 Division of Licensing 2pp 22766 164 24X
 Fiche 50-332.84/03/22.8403270071
- 8403270301 Informs that monthly repts for Nov 1983 Feb 1984 re Contract NRC-03-83-092 being sent by express mail Related correspondence RUTBERQ.J Hearing Branch 2 DSB 135 84/03/22 ELLIOTT.C W Brase & Poswistillo 2pp, 22789 032 24X Fiche 50-352,84/03/22, 8403270301
- 8403280333 Forwards rept, "UHS Extreme Wind Hazard Analysis." W/o encl Related correspondence KEMPER, J S Philadelphia Electric Co DSB 160 84/03/22 SCHWENCER, A Licensing Branch 2 1p 22787 173 24X Fiche 50-352,84/03/22,8403280353
- B403Z60349 Notion to dismiss particular onsite emergency planning contentions for which discovery not provided or no litigable basis shown Certificate of Svc anci CONNER. T B Philadelphia Electric Co CONNER. T B Conner & Wetterhahn DBB 094 84/03/23 Atomic Bafety and Licensing Board Panel 16pp 22760 243 24% Fiche 50-352.84/03/23,8403260349.
- 8403300122 Response to Limerick Ecology Action (LEA) supplemental info on LEA offsita emergency planning contentions Certificate of Svc enci FERKIN, Z Q Pennsylvania, Commonwealth of, DSB 203 84/03/23 7pp 22820 303 24X Fiche 50-352.84/03/23.8403300122
- B403290375 Forwards response to applicant motion to delete specific instances in support of Contantion VI-I as unrelated to walding or welding-related GA activities Certificate of Bvc yncl
 ROMANO, F.R. Air and Water Pollution Patrol DBB 201 84/03/25
 Atomic Bafety and Licensing Board Panel ip 22814 326 24X
 Fichs 50-352,84/03/25,8403290395
- --8403270397 Response to applicant motion to delete specific instances in support of Contention VI-I advanced by Air & Water Pollution Patrol as unrelated to welding or welding-related GA activities

 RUMANO:FR Air and Water Pollution Patrol 84/03/24 Atomic Safety and Licensing Board Panel 11pp 22814 327 24x

 Fiche 50-352,84/03/25,8403270395
- 8403270027 Notice of ASLB constitution L Brenner, chairman & RF Cols & PA Morris, members Served on 840326 CDTTER, B P Atomic Safety and Licensing Board Panel DBB 125, 84/03/26 2pp 22769 337 24% Fiche 50-352.84/03/26, 8403270027.
- 8403270060 Stipulation re storage of unirradiated fuel WETTERHANN M J Philadelphia Electric Co. ELLIOTT.C W Limerick Ecology Action DSB 122 B4/03/26 2pp 22766.162 24X Fiche 50-352.84/03/26.8403270060
- B403280331 Memorandum & order confirming 840321 oral ruling on affidavits re radiation releases from unirradiated new fuel rods Served on 840327
 BRENNER.L Atomic Safety and Licensing Board Panel. DSB 148
 84/03/26 Office of the Executive Legal Director. 2pp 22787.049 24X Fiche 50-352,84/03/26,8403280331
- 8403280359 Order imposing temporary stay of ASLB 840316 memorandum & order pending receipt of Friends of the Earth appeal of order Berved on 840328 SHGEMAKER, C J Atomic Safety and Licensing Appeal Panel DSB 161. 84/03/27 Rpp 22787 229 24X Fiche 50~352,84/03/27,8403280359
- 8403300129 Joint rept on status of negotiations re onsite emergency planning contentions & Limerick Ecology Action dismissal of particular contentions. Certificate of Svc encl RADER, R M Philadelphia Electric Co RADER, R M Conner & Heterhahn ELLIOTT, C W Limerick Ecology Action DBB 206 84/03/27 6pp. 22820 008 24% Fithe 50-352,84/03/27,8403300129
- 8403300271 Forwards QA audits re Colt Industries Fairbanks Morse Engine Div.dissel generators W/o encl.Related correspondence WETTERHANN.M J Philadelphia Electric Co WETTERHANN,M J Conner & Wetterhahn DSB 212 84/03/27, 3pp 22824 037 24X Fiche 50-352,84/03/27,8403300271
- --B403300274 Response to Air & Water Pollution Patrol (AMPP) 840319 motion to require further depositions re Contention VI-1. AMPP failed to support request for relief & motion should be denied W/Certificate of Svc Related correspondence WETTERHAHN, M. J. Pilladelphia Electric Co WETTERHAHN, M. J. Affiliation Not Assigned 84/03/27 Atomic Safety and Licensing Board Panel 7pg 22824:040 24% Fiche: 50-352,84/03/27, 840300271

- 8403290374 Forwards portions of transcripts re ABLB 840320 ruling on admissibility of Limerick Ecology Action contentions & City of Philadelphia issues on facility DES, Suppl 1 Related correspondence MODODON, A P Hearing Branch 2 DSB 197 84/03/28 ELLIOTT, C W Brose & Poswistilla BUSH, M W Bush, M W FERKIN, Z G Pennsylvania, Commanwealth of. 31pp 22814 091 24X Fiche 50-352,84/03/28,8403290374
- 8403270384 Brief in opposition to intervenor Friends of the Earth for stay of onsite storage of unirradiated fuel Btay request falls to demonstrate any conceivable harm as result of fuel storage Certificate of Svc encl
 HETTERHAHN.M J Philadelphia Electric Co HETTERHAHN.M J Conner & Wetterhahn DBE 190 84/03/28 11pp. 22814 240 24X
 Fiche 50-352,84/03/28,8403270384
- 8403290393 Memorandum & order confirming denial of Air & Water Pollution Patrol motion for further dispositions re Contention VI-1 Certificate of Svc encl BRENNER,L Atomic Safety and Licensing Board Panel DSB 187 84/03/28 4pp 22814 322 24X Fiche 50-352,84/03/28,8403290393
- 8403270379 Forwards staff 840320 response to Limerick Ecology Action supplementary info.

 VDGLER.B H Hearing Branch 2 DSB 200 84/03/28 BRENNER.L, MORRIS.P A . COLE.R F Atomic Safety and Licensing Board Panel 2pp 22814 338. 24% Fiche. 50-352,84/03/28,8403290397
- --8403290400 Response to Limerick Ecology Action 840313 supplementary info on offsite emergency planning contentions Staff position remains unchanged Certificate of 8vc encl VOQLER, B. H. Hearing Branch 2 84/03/20 2pp. 22814 340 24X Fiche. 50-352, 84/03/28, 8403290399
- 8403300127 Transmittal of refs & errata to applicant 840321 testimony of WJ Boyer, DJ Thompson, DA Klins, L. Stanley, EF Sproat, WH Bowers, TE Shannon & J Doering on Contention I-42 Related correspondence HETTERHAHN, M J Philadelphia Electric Co HETTERHAHN, M J Conner & Hetterhahn DSB 204 84/03/28 7pp 22820 245 24X Fiche 50-352, 84/03/28, 8403300127.
- 8403300128 Response opposing M Lewis 840314 motion for new contention based on IE Info Notice 84-17 cooling of vital components by liquid nitrogen. Certificate of Svc encl METTERHAHN, M. J. Philadelphia Electric Co. METTERHAHN, M. J. Conner & Matterhahn DSB 205 84/03/28 Atomic Safety and Licensing Board Panel. 12pp. 22820 291 24X Fiche 50-352,84/03/28,8403300128
- 8403300287 Forwards PH Patery 840315 ltr re questions concerning fission products Ltr should be forwarded to appropriate NRC individual for response & response served in proceeding 8erved on 840330 LANE, V.M. Atomic 8efety and Licensing Board Panel, D88 218 84/03/29, VOQLER, B.H. Hearing Branch 2, 2pp 22824:016 24X Fichs. 50-352, 84/03/29, 8403300287
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8403020257 Forwards Rev 27 to FBAR BRADLEY,E.J. Philadelphia Electric Co 84/02/29 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 22495.026 24% Fichs. 50-552, 84/02/29, 8403020257.
- --8403020273 Rev 29 to F8AR * Philadelphia Electric Co 84/02/29, 538pp 22495 056 24X Ficha: 50-352,84/02/29,8403020257.
- 8403150036 Forwards Affidavit of Bvc re distribution of Rev 29 to FBAR k Rev 17 to environ rept, per DQ Eisenhut 810706 request.

 BRADLEY,E.J Philadelphia Electric Co 84/03/12 DENTON, H, R
 Office of Nuclear Reactor Regulation, Director 5pp 22643 270
 24X Fiche 50-352,84/03/12,8403150036
- G. Inspection reports, IE Bullstins & correspondence
- 8403010307 Forwards IE Insp Rept 50-352/84-02 on 840105-06. No violations observed.

 MARTIN, T T. Division of Engineering & Technical Programs, 84/02/16 KEMPER, J. B. Philadelphia Electric Co. 2pp. 22433 074 24X Fiche, 50-352, 84/02/16, 8403010307.
- ---8403010314 IE Insp Rept 50-352/84-02 on 840105-06, No violations identified Major areas inspected, chemistry & radioactive effluent control programs, MOTTAN, J, J, ZIBULSKY, H, PABCIAK, W J Region 1, Office of Director 84/02/14, 4pp. 22433:076 24X Fiche: 50-352, 84/02/16, 8403010307.

- 8403070055 Responds to IE Bulletin 83-06, "Nonconforming Matla Supplied by Tube-Line Corp Facilities "Disposition of subj matl supplied by Guyon Alloys. Inc described Ten 6-inch 45 degree elbows & one 4-inch 5 R 70 degree elbow quanantined GALLAGHER. J Philadelphia Electric Co 84/02/16 MURLEY.TE Region 1. Office of Director 10pp 22576 051 24X Fiche 50-352.84/02/16.8403070055
- 8403070314 Forwards IE Insp Repts 50-352/84-01 & 50-353/84-02 on 840103-31 No violations noted STAROBTECKI.R plvision of Project & Resident Programs 84/02/22 KEMPER.J 8 Philadelphia Electric Co 4pp 22546 204 24X Fiche 50-352,84/02/22,8403070314
- --B403070319 IE Insp Repts 50-352/84-01 & 50-353/84-02 on B40103-31 No violations noted Major areas inspected followup on previous insp findings, plant tour, followup on IE bulletins & Nuclear Review Board Charter
 WIGGINS, J T, CHAUDHARY, S K, CONNER, E L Region 1, Dffice of Director 84/02/17 16pp 22544 208 24X Fiche 50-352,84/02/22,8403070314
- 8401170072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN.E L. Division of Emergancy Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp. 22707 237 24X Fiche 50-000.84/02/28,8401170072
- 840302034B Advises of consideration on use of plant-specific PRA & severe accident risk assessments (SARA) to assist NRC in evaluating sampling insp program Requests meeting in Mar 1984 to obtain insights from performing PRA & SARA STAROBTECKIR Division of Project & Resident Programs 84/02/28 KEMPERJ 38 Philadelphia Electric Co 2pp 22439 020 24X Fiche 50-352.84/02/28.8403020348
- 8403070276 Ack receipt of 831222 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-32783-12 Response not in accordance w/1007R2 201 Add 1 info requested MARTIN T T Division of Engineering & Technical Programs 84/02/28 KEMPER. J B Philadelphia Electric Co 2pp. 22546 302 24X Fiche 30-332.84/02/28.8403070276
- --8403070281 Responds to NRC 831122 ltr re violations noted in IE Insp Rept 50-352/83-12 Corrective actions field insp of MCC power panel performed & results being evaluated Actions to prevent recurrence will be completed by 840301 KEMPER.J 8 Philadelphia Electric Co 83/12/22 MURLEY.T E Division of Engineering & Technical Programs 3pp 22346 304 24X Fiche 50-352,84/02/28.8403070276
- 8402070007 IE Info Notice 84-i4, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl, GRACE.J N Division of GA, Bafeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22592 327 24X Fiche 50-000,84/03/02,8402070007.
- 8402090008 IE Info Notice 84-14, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN.E L Division of Energency Preparedness & Engineering Response (Post 830103). 84/03/02 Consolidated Edison Co. of New York, Inc 122pp 2253 098 24X Fiche 50-000,84/03/02,8402090008
- 8402070009 IE Info Notice 84-15, "Reporting of Radiological Releases" Syc list and JDRDAN,E L. Division of Emergency Preparedness & Engineering Response (Fost 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 117pp 22553 217 24X Fiche 50-000,84/03/02,8402070009
- 8403160241 Forwards IE Insp Repts 50-352/84-03 & 50-353/84-01 on 840109-10 & 12-13 No violations noted MARTIN T T Division of Engineering & Technical Programs 84/03/02 KEMPER, J & Philadelphia Electric Ca 2pp 22661 036. 24X Fichs 50-352.84/03/02,8403160241
- ---840314024B IE Insp Repts 50-352/84-03 & 50-353/84-01 on 840109-10 & 12-13 No violations noted, Mejor areas inspected preoperational radiological environ monitoring program, mgt controls, program for GC for analytical measurements

 BTRUCKMEYER, R, PASCIAK, W, J. Region 1, Office of Director, 84/02/23 5pp 22661 038 24X Fichs 50-352,84/03/02,8403160241
- B402090011 IE Info Notice B4-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/05. Consolidated Edison Co. of New York, Inc. 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011

- 8402070024 IE Info Notice B4-09-Rsv 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Fost 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24% Fiche 50-000.84/03/07.8402070024
- 8402070028 IE Info Notice 84-18. "Stress Corrosion Cracking in PWR Sgs " Svc list encl JORDAN.E L Division of Emergancy Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402070028
- 8402070031 IE Bulletin 84-02. "Failures of GE Type HFA Relays in Use in Class IE Safety Sus " Svc list encl DEYOUND.R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823.074 24X Fiche 30-000.84/03/12.8402070031
- 8403290144 Forwards IE Insp Rept 50-352/84-08 on 840206-09. No violations noted MARTIN.T T Division of Engineering & Technical Programs 84/03/13 KEMPER.J S Philadelphia Electric Co 2pp 22806 096 24X Fiche 50-352.84/03/13.8403290144
- --8403290150 IE Insp Rept 50-352/84-08 on 840204-09. No violations noted Major areas inspected onsite/offsite safety committee activity, operational staff training & fuel receipt & storage programs
 PRELL.J A. BISSETT, P. (LIVEIRA, W. Region 1, Office of Director 84/03/07 8pp. 22806 098 24X Fiche 50-352,84/03/13,8403290144
- 8402090043 IE Info Notice 84-19. "Two Events Involving Unauthorized Entries into FWR Reactor Cavities." Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/03/21 Consolidated Edison Co of New York, Inc. 123pp 22823 229 24X Fithe 50-000.84/03/21, 8402090043
- 8402090044 IE Info Notice 84~20, "Bvc Life of Relays in Bafety-Related Sys " Svc list and JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 135pp. 22933 001 24X Fiche 50~000.84/03/21,8402090044
- R. Periodic operating reports & related correspondence
- 8403020443 Forwards monthly status rept of offsite emergency preparedness for OL reviews for Jan 1984 Changes in FEMA finding dates not caused by delay due to offsite emergency planning issues
 DIRCKS.W J Office of the Executive Director for Operations
 84/02/21 PALLADINO Commissioners 9pp 22492 083 24X
 Fiche 50-000.88/02/21.8403020443
- S Reportable occurrences, LERs & related correspondence
- 8403130084 Final Significant Deficiency Rept 127 re Agastat CR0075 relay socket failures Defective sockets replaced w/Agastat CR002 sockets, correcting any adverse safety implications induced by socket failure KEMPER. J. 8 Philadelphia Electric Co. 84/02/17. MURLEY. T. E. Region 1, Office of Director 3pp 22598:343 24% Fiche 50-352.84/02/17.8403130084.
- 8403260233 Forwards summary list of deficiencies identified per 100FR5D 55(e).Part 21 & potential generic ltr repts for comments
 STAROSTECKIR Division of Project & Resident Programs. 84/02/28
 Region 1. Office of Director 7pp 22756 065 24X
 Fiche 50-000.84/02/28.8403260223
- 8403270219 Part 21 rept re broken contact carrier in control device of 7 5 kV-15 kV 500-750 MVA, 5 kV 350-3,000 & all HKV circuit breakers. Initially reported on 830223 Addenda to installation & maint procedures sent to affected units DUVALL, D D Brown Boveri Corp (subs of Brown Boveri & Co., Ltd.) 84/03/19 Record Services Branch (Document Control Desk). 5pp 22772 114 24X Fiche: 50-000, 84/03/19, 8403270219.
- T Hearing transcripts on non-antitrust matters
- 8403020129 Forwards revised testimony re ability of safety-related structures to dithitand affects of postulated detonation resulting from assumed ruptures of Arco & Columbia gas transmission pipelines Related correspondence METTERHAHN, M J Conner & Wetterhahn, WETTERHAHN, M J, Philadelphia Electric Co 84/02/29 BRENNER, L Atomic Safety and Licensing Board Panel 2pp. 22442.112. 24X Fiche: 50-352.84/02/28,8403020129

- --8403020136 Revised testimony of Philadelphia Electic Co re ability of safety-related structures to withstand effects of postulated detonation due to ruptures of transmission pipelines W/Certificate of Bvc Related correspondence # Philadelphia Electric Co 84/02/28 27pp 22442,114 24X Fiche 50-352,84/02/28,8403020127
- B403080235 Transcript of 840305 hearing in Philadelphia, PA Pp 7.565-7.496 * Commissioners 84/03/05 131pp. 22556.306 24x Fiche 50-352,84/03/05,8403080255.
- B403120092 Transcript of B40306 hearing in Philadelphia, Pa. Pp 7, 696-7, 942 * Commissioners 84/03/06 246pp. 22588 249 24X Fiche 50-352,84/03/06,8403120092
- 8403120151 Transcript of 840307 hearing in Philadelphia,PA Pp 7,943-8,158 * Atomic Safety and Licensing Board Fanel 94/03/07 216pp 22585 263 24X Fiche 50-352,84/03/07,8403120151
- B403130040 Transcript of 840308 hearing in Philadelphia, PA Pp 8, 159-8, 383.

 * Atomic Safety and Licensing Board Panel 84/03/08 268pp 22598 067 24% Fiche 50-352,84/03/08,8403130040
- 8403130113 Transcript of 840309 hearing in Philadelphia, PA Pp 8,384-8,505 * Atomic Safety and Licensing Board Panel 84/03/09 22pp 22601 001 24% Fiche 50-352,84/03/09,8403130113
- 8403220145 Transcript of 840319 hearing in Philadelphia, PA Pp 8,506-8,647

 * Atomic Safety and Licensing Board Panel, 84/03/19 150pp, 22714 142 24% Fiche 50-352,84/03/19,8403220145
- B403260254 Transcript of 840320 hearing in Philadelphia, PA Pp 8,647-B,842 Supporting documentation encl Acomic Sefety and Licensing Board Panel 84/03/20 202pp 22755 208 24X Fiche 50-352.84/03/20,8403260254
- 8403260015 Transcript of 840321 hearing in Philadelphia, PA Pp 8,843-9.059 Supporting documentation encl * Atomic Safety and Licensing Board Panel 84/03/21 283pp 22746-001, 24X Fiche 50-352,84/03/21,8403260015.
- B403260334 Transcript of Commission 840321 affirmation/discussion & vote in Washington, DC re proposed order delegating authority to ABLB to hear Part 70 issues raised in Limerick proceeding Pp 1-3 = Commissioners 84/03/21 6pp 22775.281 24X Fichs 30-352.84/03/21.8403260334
- B403270042 Transmittal of testimony re Contention I-42, "Environ dualification of Electrical Equipment" Related Correspondence WETTERHAHN, M. J. Philadelphia Electric Go WETTERHAHN, M. J. Conner & Wetterhahn DBB 120 84/03/21 2pp 22769:242 24X Fiche 50-352,84/03/21,8403270042
- --8403270048 Testimony of MJ Boyer, DJ Thompson, DA Kline, L Stanley, EF Bproat: MM Boyers, TE Shannon & J Doering re Contention I-42, "Environ Qualification of Electrical Equipment" Certificate of Svc encl BOYER, M J , THOMPSON, D J , KLINE, D A Philadelphia Electric Co 84/03/21 55pp 22769 244 24X Fiche 50-352,84/03/21,8403270042.
- B403270296 Testimony of A Masciantonio on Limerick Ecology Action Contention I-42 re electrical environ qualification. Related correspondence MABCIANTONIO, A Equipment Gualification Branch, DBB 138 B4/03/21, 10pp 22789:037. 24X Fiche: 50-352; B4/03/21; 8403270296
- 8403270171 Transcript of 840322 hearing in Philadelphia, PA Pp 9,060-9,266

 * Atomic Safety and Licensing Board Panel, 84/03/22 210pp. 22773:150, 24X Fiche:50-352,84/03/22,8403270171.
- 8403270160 Transcript of 840323 hearing in Philadelphia,PA.Pp 9,267-9,401, # Atomic Safety and Licensing Board Panel. 84/03/23, 137pp. 22764-233, 24% Fiche-30-352,84/03/23,8403270160
- 8403300009 Memorandum serving transcript pages re 840323 prefiled testimony on Limerick Ecology Action Contention 1-42 concerning environ qualification. Served on 840329 BRENNER, L. Atomic Safety and Licensing Board Panel DBB 209, 84/03/29 ip 22822 131 24X Fiche: 50-352,84/03/29,8403300009.

- --8403300014 Transcript Pp 9.270-9.274 of 840323 testimony on Limerick Ecology Action Contention I-42 re environ qualification * Office of the Executive Legal Director * Philadelphia Electric Co * Limerick Ecology Action 84/03/29 5pp 22822 132 24X Fiche 50-352.84/03/29.8403300009
- DOCKET 50-353 LIMERICK GENERATING STATION, UNIT 2
- A. Application/construction stage documents & correspondence
- 8402090003 Responds to FOIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Panel mastings Forwards App A, B & C documents
 FELYON, J. M. Division of Rules and Records, 83/10/31
 ROSENBAUM, D M. Technical Analysis Corp. 17pp. 22193 292 24x
 Fiche: 50-000,83/10/31,8402090003
- --B402090189 Handwritten notes & calculations re const activities & fuel load preparation
 + NRC No Detailed Affiliation Given 79/07/24 5pp 22195.057 24X Fiche 50-000,83/10/31,8402090003
- 8401240207 Forwards add1 info re stress-assisted corrosion cracking of primery sys comments & potential main cooling tower failure modes & consequences.in response to ACR8 831018 ltr KEMPER, J S. Philadelphia Electric Co 84/01/18 BCHWENCER, A. Licensing Branch 2. 3pp 21908 148 24X Fiche 50-352,84/01/18,8401240207
- --B401240211 "Rept on Effects of Postulated Failure of Gooling Towar"
 W/three oversize drawings Aperture cerds are available in
 PDR.
 # Philadelphia Electric Co P-281/2 83/12/31 15pp
 21908 151 24X Fiche 50-352,84/01/18,8401240207
- 8403020104 Forwards magnetic tape containing hour by hour meteorological data for Oct 1983 Jan 1984, per 8310/3 ltr. Data from primary meteorological tower & satellite tower & tape formats described KEMPER, J S. Philadelphia Electric Co 84/02/27 BCHWENCER, A Litensing Branch 2 3pp. 22443, 240 24X Fiche 50-352,84/02/27,8403020104,
- 8403020237 Forwards application for amend to CPPR-106 & CPPR-107 (filed in Category A). Rev 17 to environ rept OL stage (filed in Category C) & Rev 29 to FBAR (filed in Category K)

 BRADLEY,E J Philadelphia Electric Co. 84/02/29 DENTON, H. R.

 Office of Nuclear Reactor Regulation, Director 2pp 22495.026

 24X Fiche: 50-352,84/02/29,8403020257
- ---8403020266 Application for smend to CPPR-106 & CPPR-107 Certificate of 8vc sncl. KEMPER, J S. Philadelphia Electric Co 84/02/27 6pp 22495 028 24X Fiche 50-352,84/02/27,8403020257
- 8403150262 Forwards request for add1 info re standby gas treatment sys Info meeded to evaluate FSAR, Section 6 5, Rev 25 BCHWENCER, A Licensing Branch 2 84/02/27 BAUER, E, O Philadelphia Electric Co 4pp 22648 342, 24X Fiche: 50-352, 84/02/27, 8403150262
- B403160189 Notification of B40314:15 & 16 meetings w/util in Philadelphia:PA & Montgomery County:PA:respectively:to discuss NRC audit of environ qualification files & installed equipment.

 KINTNER:L. Licensing Branch 1 B4/03/05 SCHWENCER:A. Licensing Branch 2, 4pp. 22662,299, 24X Fiche 50-352:84/03/05 8403160189
- 8403150192 Advises of errors made in wind direction frequencies for CRAC2 calculation Revised calculations for severe accident risk assessment expected to change predicted latent cancer fatalities.

 KEMPER, J. B. Philadelphia Electric Co. 84/03/13 BCHWENGER, A. Licensing Branch 2, 2pp. 22655 244 24X Fiche 30-352,84/03/13,8403360192.
- 8403190197 Forwards Rev C to Anchor/Darling Valve Co Drawing 93-14182. correspondence re HPCI.RCIC & reactor water cleanup containment isolation valve closure capabilities & Rev 23 co Matl Requisition 8031-P-104.per 840202 telcon. KEMPER. J. B. Philadelphia Electric Co. 84/03/13 SCHWENCER, A Licensing Branch 2, 134pp. 22670.001. 24X Fiche 50-352.84/03/13, 8403190197
- B402090041 Board Notification B4-050.provides Commission policy statement & proposed rulemaking on environ qualifications EIBENHUT, D. O Division of Licensing. 84/03/14. Atomic Bafety and Licensing Board Panel. 10pp. 24X Fiche. 50-000.84/03/14.8402090041

- C Utility Environmental Report (ER), amends & correspondence
- 8403020257 Forwards Rev 17 to environ rept OL stage HRADLEY,E J Philadelphia Electric Co 84/02/29 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 22495 026 24X Fiche 50-352.84/02/29.8403020257
- --8403020270 Rev 17 to environ rept OL stage * Philadelphia Electric Co 84/02/27 20pp 22495 034 24X Fiche 50-392,84/02/29,8403020257
- B403150036 Forwards Affidavit of Svc re distribution of Rev 29 to FSAR & Rev 17 to environ rept,per DG Eisenhut 810706 request.

 BRADLEY, E J Philadelphia Electric Co 84/03/12 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 5pp 22643 290
 24X Fiche 50-352:84/03/12.8403150036
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- 8403160026 Notifies that Natl Ctr for Devices & Radiological Health has no comment re postulated plant accidents described in DEB (NUREG-0974)

 VILLFORTH, J C Food & Drug Administration, 84/02/10 SCHWENCER, A Licensing Branch 2 1p 22654 346 24X Fiche: 50-352, 84/02/10, 8403160026
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8403010144 Forwards draft FPER pages containing info to close BER Open Issue 15 re electrical cable & cable tray & fire areas having high concentrations of cables Info in draft FPER will be incorporated into Rev 5 scheduled for Mar 1984 BOYER, V 8 Philadelphia Electric Co 84/02/16 SCHMENCER, A Licensing Branch 2 9pp 22435 313 24X Fiche: 50-352, 84/02/16, 8403010144
- B403050161 Forwards "Structural Steel Eurvivability Evaluation," in response to B40209 request for addl info (RAI 280 26), per EER Open Item 14 KEMPER, J B Philadelphia Electric Co 84/02/29 SCHWENCER, A Licensing Branch 2 3pp 22483 037 24X Fiche 50-352,84/02/29, 8403080161
- 8403260249 Forwards "UHS Extreme Wind Hazard Analysis," in response to 830808 ltr re 85ER Open Issue 2 KEMPER, J 8 Philadelphia Electric Co 84/03/22 SCHWENGER, A Licensing Branch 2 2pp 22755 001 24X Fiche 50-352,84/03/22,
- --8403260253 "UHB Extreme Wind Hazard Analysis " BITOMF:T B., PARRY:0 W NUS Corp. NUS-4507 84/03/31 134pp 22755 004 24% Fiche 50-352.84/03/22.8403260249
- F. Becurity: medical, emergency & fire protection plans
- 8403070361 Public version of revised emergency plan implementing procedures, including Procedure EP-201 re technical support ctr activation, EP-210 re dose assessment team & EP-222 re field survey group W/831212, 840215 ltrs & 840302 memo DALTROFF, 8 L Philadelphia Electric Co 83/11/30 MURLEY, T E Region 1. Office of Director 8CHWENCER, A Licensing Branch 2 165pp. 22366 061 24% Fichs 30-352, 83/11/30, 8403070361
- 8403090290 Public version of Rev O to emergency plan implementing procedures, including Procedure EP-110 re personnel assembly, EP-221 re personnel dosimstry & EP-206 re security team activation W/831212 ltr & JM Felton release memo DALTROFF, S L Philadelphia Electric Co 83/11/30 BCHMENCER, A Licensing Branch 2. 80pp. 22592 062 24X Fiche. 50-352, 83/11/30, 8403090290
- B403010144 Forwards draft FPER pages containing info to close BER Open Issue 15 re electrical cable & cable tray & fire areas having high concentrations of cables Info in draft FPER will be incorporated into Rev 5 scheduled for Mar 1784 BDYER, V 8 Philadelphia Electric Co 84/02/16 SCHMENCER, A Licensing Branch 2 9pp 22435 313 24X Fiche: 50-352,84/02/16,8403010144
- 8402090006 Board Notification 84-034 forwards R Vollmer 840206 memo to D Eisenhut re fire research results concerning fires in electrical cabinets in control room EISENHUT, D 0. Division of Licensing. 84/02/23 PALLADING Commissioners, ip. 22576-203 24X Fiche 50-000, 84/02/23, 8402090006

- --B4030803ió Recommends that info re fire research results concerning fires in electrical cabinets in control room be submitted for board notification, per NRR Ofc Ltr 19, dtd 821001 Further evaluation of test data required VOLLMER.R H Division of Engineering 84/02/06 EISENHUT, D 0 Division of Licensing 10pp 22576 204 24X Fiche 50-000.84/02/23,8402090006
- 8403190243 Notification of 840418 workshop in King of Prussia.PA to discuss lessons learned from recent App R fire protection safe shutdown insp & topics described in IE Info Notice 84-09 Agenda for workshop encl MURLEY.T E Region 1. Office of Director 84/03/09 O'TOOLE.J D Consolidated Edison Co of New York. Inc FIEDLER.P B General Public Utilities OPU Service Corp 35pp 22672 062 24X Fiche 50-000.84/03/09.8403190243
- 8403210028 Forwards response to NRC 840306 & 08 requests for add1 info re smergency action levels, specifically, containment radiation levels Draft changes to smergency plan will be incorporated as stated in enc! DALTROFF, S.L. Philadelphia Electric Co. 84/03/16 SCHWENCER, A Licensing Branch 2 80pp 22708 255 24X Fiche 50-352.84/03/16, 8403210028

O Adjudicatory correspondence

- 8403010271 Forwards reply to applicant & staff response to City of Philadelphia issues
 SMOLEN, H Philadelphia PA 84/02/28 Docketing & Services
 Branch lp 22432 207 24X Fiche 50-352.84/02/28.8403010271
- ---8403010275 Reply to applicant & staff responses to City of Philadelphia issues re emergency response plan Btate plan does not contain & is not based upon standardized protective action guidance for exposure from feedstuffs & water SMOLEN.H Philadelphia. PA 84/02/28 Atomic Safety and Licensing Board Panel 43pp 22432 208 24X Fiche 50-352,84/02/28,8403010871
- 8403020099 Forwards answer to City of Philadelphia interrogatories on sys interaction, designated Discovery 28 W/esception of three listed documents, documentary matl responsive to request will be made available for insp Related correspondence WETTERHAHN, M J. Conner & Wetterhahn 84/02/29 BUSH, M W Philadelphia, PA App. 22443 048 24% Fiche 50-352,84/02/29, 8403020099
- --8403020103 Answers City of Philadelphia interrogatories on sys interaction contention Certificate of 8vc encl Related correspondence IDVER.V S Philadelphia Electric Co 84/02/27 65pp 22443 054 24X Fiche 50-352,84/02/29,8403020099
- B403020125 Transmittal of matl supporting applicant B4022B revised testimony re ability of safety-related structures to withstand effects of postulated detonation from pipeline ruptures Certificate of Svc enci Related carrespondence WETTERHAHN M J Philadelphia Electric Co WETTERHAHN N J Conner & Hetterhahn B4/02/29 4pp 22442 143 24% Fiche 50-352,84/02/29,8403020125
- 8403020163 Response apposing new contention proposed by Air & Water Pollution Patrol re discharge of asbestos fibers Contention lacks basis & specificity required by IOCFR2 714(b)
 Certificate of Byc encl
 WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn 84/02/29 Atomic Safety and Licensing Board Panel 11pp 22442 006 24X Fiche 50-352.84/02/29.8403020163
- 8403060129 Forwards Certificate of Bvc for reply to applicant & staff responses to City of Philadelphia issues
 SMOLEN:H Philadelphia: PA B4/02/29 Ducketing & Services
 Branch Spp 22506 327 24X Fichs 50-352:84/02/29,8403060129
- 8403060081 Response opposing Friends of the Earth 840224 motion to strike applicant & staff structural analysis testimony Motion fails to establish testimony as unreliable Certificate of Svc encl.Related correspondence METTERHANN,M Philadelphia Electric Co METTERHANN,M Conner & Metterhahn 84/03/01 Atomic Bafety and Licensing Board Panel. 6pp. 22516 339 24X Fiche 50-352,84/03/01,84030600091
- 8403060248 Amswer to new contentions proposed by Friends of the Earth on onsite storage of unirradiated fuel & transmittel of related correspondence Proposed late contentions should be denied Certificate of Svc encl WETTERHANN, M J Philadelphia Electric Co WETTERHANN, M J Conner & Wetterhahn 84/03/01 Atomic Safety and Licensing Board Panel 33pp 22517 079 24X Fiche 50-352,84/03/01.8403060248

- B403140118 Forwards cross-examination plans for structural analysis hearing on blast overpressures.per ABLB B40120 order W/o enc!

 VG0LER, B H Hearing Branch 2 B4/03/01 BRENNER, L., COLE, R.F., MORRIS, P.A. Atomic Safety and Licensing Board Panel 2pp 22623 33B 24X Fiche 50-352, 84/03/01, 8403140119
- 8403060097 Hemorandum & order denying intervenor Lewis 831224 motions based on newly received info Lewis discovery rights not abridged per Contention I-62 W/Certificate of Bvc BRENNER, L., COLE, R. F., MORRIS, P. A. Atomic Befety and Licensing Board Panel 84/03/02 Lewis, M. 11pp 22506 262 24X Fiche 80-332,84/03/02,8403080097
- 8403070142 Response opposing Air & Mater Pollution Patrol 840221 request for extension of discovery period for Contention VI-1 Cartificate of Bvc encl Related correspondence WETTERHAMN.M J Philadelphia Electric Co WETTERHAMN.M J Conner & Wetterhahn 84/03/02 Air and Mater Pollution Patrol 7pp 22538 271 24% Fiche 50-352,84/03/02,8403070142
- 8403070236 Response to Air & Water Pollution Patrol motion to compel discovery Applicant denies that answer to interrogatory evasive Related correspondence
 WETTERHAHN.M J Philadelphia Electric Co HETTERHAHN.M J Conner & Wetterhahn 84/03/02 Atomic Bafety and Licensing Board Panel 3pp 22536 217 24X Fiche 50-352: 84/03/02.8403070236
- --8403070238 Response opposing Air & Water Pollution Patrol request for depositions re Contention VI-1 No reason given why depositions necessary W/Certificate of Svc HETTERHAHN.M J Philadelphia Electric Co HETTERHAHN.M J Conner & Wetterhahn. 84/03/02 Atomic Safety and Licensing Board Panel 6pp 22536 221 24X Fiche 50-352,84/03/02,8403070236
- 8403140085 Response opposing Friends of the Earth 840223 application to file contention based on new matter refuel storage Certificate of Svc encl HILCOVE, M N. Hearing Branch 2 84/03/02 Atomic Bafety and Licensing Board Panel 14pp 22633 235 24X Fiche, 50-352, 84/03/02, 8403140085
- 8403140115 Response to Limerick Ecology Action & City of Philadelphia contentions filed on 840214 re environ assessment of severe accidents as set forth in DES. Suppl 1 Certificate of Byc encl VOLER, B H . HODODON, A P Hearing Branch 2 84/03/03 Atomic Bafety and Licensing Board Panel 17pp 22623 340 24X Fiche 50-352.84/03/03.8403140115
- 8403120001 Notice of withdrawal of offsite emergency planning issue re evacuation time estimate study Applicant 840224 representation addresses issues W/Certificate of Svc FERKIN, 2 9 Pennsylvania, Commonwealth of, 84/03/05 3pp 22588 036 24X Fiche 50-352:84/03/05,8403120001
- B403140105 Response opposing Air & Water Pollution Patrol (AWPP) 840215 motion filing new info contention AWPP fails to meet stds for laterfiled contentions Certificate of Bvc encl WRIGHT,N A Hearing Branch 2 84/03/05 Atomic Bafety and Licensing Board Panel Bpp 22623 330 24X Fichs 50-352,84/03/05,8403140105
- 8403130411 Forwards notice of change of address & firm name Certificate of Svc enc1 8U0ARMAN.R J Bugarman & Denworth SUQARMAN.R J Del-Aware Unlimited, Inc. 84/03/07 Docketing & Services Branch App 22616:319 24X Fiche 50-352,84/03/07,8403130411.
- 8403140110 Findings of Pact & conclusions of law in form of partial initial decision on Air & Water Pollution Patrol Contention V-4 re carburator icing Cartificate of Bvc encl HODODON, A F Hearing Branch 2 84/03/07 25pp 22624.075 24X Fiche, 50-352, 84/03/07, 8403140110
- 8403130024 Reply findings of fact & conclusions of law re Contention V-4 in response to Air & Mater Pollution Patrol (AMPP) 840224 proposed findings AMPP findings should be rejected Certificate of Bvc encl WETTERHAHNM J , NICHOLS, N. N Philadelphia Electric Co. WETTERHAHNM J Conner & Watterhahn 84/03/12 9pp 22641:282 24X Fichs 50-332,84/03/12,8403150024
- 8403190007 Responses to util interrogatories on Contention 1-42 Certificate of Svc encl.Related correspondence * Philadelphia, PA 84703/12 Philadelphia Electric Co. 15pp 22665.337 24X Fichs 50-352,84/03/12,8403190007

- 8403160010 Forwards affidavit of LB Pyrih & PS Stansbury re hypothetical accidents involving unirradiated fuel to be stored at plant No credible potential for violating regulations identified Related correspondence WETTERHAHN.M J Philadelphia Electric Co WETTERHAHN.M J Conner & Wetterhahn. 84/03/13 1p 22662 164 24X Fiche 50-352,84/03/13, 8403160010
- --B403160187 Affidavit of LB Pyrih re storage of unirradiated fuel No potential for violating provisions of 10CFR20 as result of credible accidents affecting new fuel assemblies stored at plant Certificate of Svc encl
 PYRINL B Philadelphia Electric Co 84/03/13 22pp 22662 165
 24% Fiche 50-352,84/03/13,8403160010
- --8403160188 Affidavit of PS Stansbury re calculation of exposure rates in various assumed configurations of specified quantities of U enriched to 1 85% in isotope U-235 STANSBURY, P. 9. General Electric Co. 84/03/12 9pp 22662 186 24% Fiche. 50-352, 84/03/13, 8403160010
- B403170132 Appeal opposing dismissal of Anthony/Friends of the Earth contention on util application to store nuclear fuel outdoors & ASLB denial of immediate stay on moving fuel ANTHONY/R L. Anthony, R L. ANTHONY/R L. Friends of the Earth B4/03/13 Atomic Bafety and Licensing Appeal Panel ip 22666 306 24X Fiche 50-352, B4/03/13, B403170132
- ---840319013B Application to file contention re util application to store fuel optdoors Fuel storage is hazard to community due to question of whether bldgs can uithstand overpressures & impacts from offsite accidents
 ANTHONY.R.L. Anthony. R.L. ANTHONY.R.L. Friends of the Earth 84/02/23. Atomic 8afety and Licensing Board Panel ip 22666:307 24X Fiche:50-352,84/03/13,8403190132
- --8403190142 Addition to application for contention re util application to move & store 764 bundles of fuel Util plans to move highly dangerous fuel onto site in Mar 1984 & store fuel in especially vulnerable location for 4 months ANTHONY, R L Friends of the Earth 84/02/28 Atomic Bafety and Licensing Board Panel 2pp, 22666 308 24X Fiche 50-353,84/03/13,8403190132
- 8403190160 Affidavit of N Ketrlach Te possibility of radiological Teleases from fuel assemblies in shipping containers in violation of NRC regulations. Certificate of Svc encl KETZLACH.N Unanum Fuel Licensing Branch. 84703/13 5pp 22668.358 24X Fiche 50-352.84703/13.8403190160.
- 8403190173 Forwards ND Romney 840313 memo to 0 Lear re results of 840306 conference call from applicant VOOLER,8 H Hearing Branch 2 84/03/13 BRENNER,L, MORRIS,P A, COLE,R,F. Atomic Safety and Licensing Board Panel 4pp 22671 158 24X Fiche 50-352,84/03/13,8403190173
- B403200090 Forwards B40313 ltr documenting discovery of errors in predicted consequences reported in savere accident risk assassment Consideration of admissibility of contentions should proceed as scheduled Related correspondence HETTERHAHN, M J Conner & Watterhahn WETTERHAHN, M J Philadelphia Electric Co B4/03/13, BRENNER, L . MORRIS, P A . COLE, R F Atomic Bafaty and Licensing Board Panel 3pp 22685 298 24X Fiche 50-352,84/03/13,8403200090
- 8403200144 Forwards listed add1 info re HPCI isolation valves, per NRC Equipment Qualification Branch 840202 telcon request W/o encl. Related correspondence KEMPER, J. 8. Philadelphia Electric Co 84/03/13 SCHWENCER, A Licensing Branch 2 2pp. 22699:159. 24X Fiche: 50-352, 84/03/13, 8403200144.
- 940317003B Motion for new contention based on IE Notice 84-17 reproblems w/liquid nitrogen cooling components below nil ductility temp Facility design deficient because liquid nitrogen can cool vital components below temp LEMER, M I Lewis, M, 84/03/14 Atomic Bafety and Licensing Board Panel, 4pp. 22666,235 24X Fiche 50-352,84/03/14,8403170038
- B403190040 Order directing parties to hold settlement conferences for onsite emergency planning contentions Courtesy notification encl.

 BRENNER, L. Atomic Safety and Licensing Board Panel 84/03/15 Office of the Executive Legal Director. 5pp. 22666, 240 24X Fiche. 50-352, 84/03/15, 8403190040
- 8403190140 Supplemental info on Limerick Ecology Action offsite samergency planning Contentions 3,4,13,17,20 & 28 requested at pre-hearing conference Certificate of Svc encl.
 + Limerick Ecology Action 84/03/15 Atomic Safety and Licensing Board Panel 34pp 22666:316 24X Fiche, 50-352,84/03/15,8403190140

- 8403190153 Order confirming miscellaneous oral rulings made at hearing held during wk of 840305 Testimony & hearing schedules listed Courtesy notification encl BRENNER, L. Atomic Safety and Licensing Board Panel 84/03/15 Office of the Executive Legal Director 8pp 22668 346 24X Fiche 50-352.84/03/15-8403190183
- 8403200015 Forwards revised radiological emergency response plan for Pennhurst Mental Retardation Ctr to ASLB, intervenors & City of Philadelphia W/o encl Related correspondence BELSER, A L. Pennsylvania. Commonwealth of, 84/03/13 BRENNER, L., MORRIS, P. A., COLE, R. F. Atomic Safety and Licensing Board Panel 2pp 22698 344 24% Fichs 50-352,84/03/15,8403200015
- 8403200060 Forwards "Protective Order on BNM Security Plan Info" &
 "Affidavit of Non-Disclosure" re storage of irradiated fuel
 Centificate of Evc encl Related correspondence
 WETTERHAHN, M J Conner & Wetterhahn WETTERHAHN, M J Philadelphia
 Electric Co 84/03/16 BRENNER, L, COLE, R F, MORRIS, P A Atomic
 Sefety and Licensing Board Panel 14pp 22684 342 24X
 Fiche 50-352,84/03/16,8403200060
- 8403200070 Memorandum & order on Friends of the Earth contentions & Limerick Ecology Action petition re Part 70 application to store new fuel BRENNER.L. MORRIB,P A Atomic Safety and Licensing Board Panel 84/03/16 30pp 22685 106 24X Fiche 50-352,84/03/16,8403200070
- 8403200110 Requests that encl AS Joffe 840311 ltr rs asbestos piping be served to parties in proceeding
 LANE,V M Atomic Safety and Licensing Board Panel 84/03/16
 CLEMENTS.W L Office of the Secretary of the Commission 2pp
 22699 043 24x Fiche 50-352,84/03/16,8403200110
- 8403210047 Forwards Commission statement of policy re challenge to elimination of financial qualification review requirements Related correspondence WRIOHT, N A Hearing Branch 2 84/03/16 BRENNER, L. MDRRIB, P. A., COLE, R. F. Atomic Safety and Licensing Board Panel 4pp. 22705 052 24X Fiche 50-352,84/03/16,8403210047
- 8403210076 Forwards Transportation Certification Branch 840312 memo & Certificate of Compliance mentioned in 840313 affidavit of N Ketzlach Related correspondence WRIGHT: A Hearing Branch 2 84/03/16 BRENNER, L. MORRIS, P. A. CULE, R. F. Atomic Bafety and Licensing Board Panel 7pp 22706 001 24X Fiche 30-352,84/03/16,8403210076
- 8403210128 Forwards Delaware River Basin Commission Aug 1980 final environ assessment for Neshaming Hater Supply Sys & 800825 negative declaration,per ABLAB 840315 telcon request W/a encl Related correspondance HDD60DN:A P Hearing Branch 2 84/03/16 KOHL:C N . EDLEB, O J . OTTCHY.R.L Atomic Bafety and Licensing Board Panel 2pp 22707 262 24X Fiche 50-352,84/03/16,8403210128
- 8403280354 Memorandum & order on Friends of the Earth contentions & Limerick Ecology Action petition based on IOCFR70 application to store new fuel Berved on 840327 BRENNER, L., MORRIS, P.A. Atomic Safety and Licensing Board Panel DSB 147 84/03/14 Friends of the Earth, 30pp 22787 174 24X Fiche: 50-352,84/03/14,8403280354
- 8403210092 Answer to Limerick Ecology Action (LEA) supplemental info on LEA offsite amergency planning contentions Proposed contentions should be denied Certificate of Svc encl CONNER.T B Philadelphia Electric Co CONNER.T B Conner & Wetterhahn 84/03/19 17pp 22705:322 24X Fiche 50-352,84/03/19.840321092
- 8403210103 Motion to delete specific instances in support of Contention VI-1 advanced by Air & Water Pollution Patrol as unrelated to walding or walding GA activities Certificate of Svc enci. WETTERHAHN.M J Philadelphia Electric Co WETTERHAHN.M.J Conner & Wetterhahn 84/03/19 Atomic Bafety and Licensing Board Panel 10pp 22706 118 24% Fiche 50-352,84/03/19,8403210103
- 8403210167 Forwards Commission "Btatement of Policy on Environ Gualification" & proposed rule: "Environ Gualification of Electric Equipment: Removal of 820630 Deadline." Related correspondence
 HODODON: A P. Hearing Branch 2 DSB 017 84/03/19 BRENNER, L, CDLE, R. F., MORRIS, P. A. Atomic Safety and Licensing Board Panel 1pp. 22710 133 24X Fiche 50-352-84/03/19,8403210167
- 8403220226 Forwards request for reconsideration of assestos contention & motion requiring further depositions re Contention VI-I ROMANG, F. R. Air and Water Pollution Patrol DSB 046 84/03/17 8RENNER, L., MORRIS, P., COLE, R. Atomic Safety and Licensing Board Panel 1p 22717-007 24X Fiche, 50-352,84/03/19,8403220226

- --B403220229 Request for reconsideration of asbestos contention Board did not adequately address hazard to public ROMAND.FR Air and Mater Pollution Patrol B4/03/19 BRENNER.L. HORRIS.P. COLE.R Atomic Safety and Licensing Board Panel 2pp 22719 008 24X Fiche 50-352.84/03/19.8403220226
- --8403220234 Hotion to require further depositions re Contention VI-I concerning 760601 broomstick deficient welding affair ROMAND.F Air and Water Pollution Patrol 84/03/19 BRENNER.L., COLE.R Atomic 84f8ty and Licensing Board Panel 2pp 22719 010 24X Fiche 50-352.84/03/19.8403220226
- B403270065 Protective order on SNM security plan info Served on B40326 BREKNER.L Atomic Sefety and Licensing Board Panel DSB 123 B4/03/19 Limerick Ecology Action Spp 22766 149 24X Fiche 30-352, 84/03/19, 8403270065
- --8403270069 Affidavit on mondisclosure for CW Elliott ELLIOTT:C W Limerick Ecology Action 84/03/16 4pp 22766 152 24X Fiche 50-352.84/03/19,8403270065
- 8403290379 Request for reconsideration of Air & Water Pollution Patrol asbestos contention ROMANO.F R Air and Water Pollution Patrol DSB 186 84/03/19 Atomic Safety and Licensing Board Panel 2pp 22814 142 24X Fiche 50-352.84/03/19.8403290378
- 8403270017 Supplemental responses to info requests of City of Philadelphia Related correspondence BOYER, V S Philadelphia Electric Co DSS 112 84/03/21 12pp 22770:056 24X Fiche 50-352,84/03/21,8403270017
- 8403280336 Forwards complaint of util vs South Coventry Township filed on 840309, memorandum of law in opposition to petition for Preliminary Injunction 84-01643 & order of court dissolving injunction against Township Related correspondence ZITZER.P Limerick Ecology Action DSB 145 84/03/21 BRENNER, L, MORRIS.P A. COLE.R F Atomic Safety and Licensing Board Panel 32pp 22787 065 24X Fiche 50-352.84/03/21.8403280336
- 8403230005 Order delegating authority to exercise review functions over Part 70 issues raised in proceeding to Appeal Board Served on 840322
 CHILK.5 J Office of the Secretary of the Commission DSB 070 B4/03/22 Atomic Safety and Licensing Appeal Panel 2pp 22726 359 24X Fiche 50-352, 84/03/22, 8403230005
- 8403230278 Order confirming briefing schedule for Friends of the Earth appeal of ASLB 840316 memorandum & order & for staff to provide Part 70 application SHOEMAKER,C J Atomic Safety and Licensing Appeal Panel DBB 077 84/03/22 Office of the Executive Legal Director 2pp 22743 074 24X Fiche 50-352.84/03/22.8403230278
- 8403260333 Forwards supplemental correspondence & documents re amargancy planning Math supplemental torrespondence 840206-0315 M/o encls Related correspondence BRADLEY,E J Philadelphia Electric Co DSB 098 84/03/22 ZITZER,P Limerick Ecology Action 2pp 22760 162 24X Fiche. 50-352,84/03/22,8403260333
- 8403270012 Informs that applicant will suppl 840217 responses to Info Requests 6.7.11 & 12 Related correspondence WETTERHAMN M J Conner & Wetterhahn METTERHAMN, M J Philadelphia Electric Co DSB 109 84/03/22 BUSH, M W Philadelphia, PA 2pp 22769:356 24X Fiche 50-352.84/03/22,8403270012
- 8403270301 Informs that monthly repts for Nov 1983 Feb 1984 re Contract NGC-03-83-092 being sent by express mail Related correspondence RUTBERGOJ Hearing Branch 2 DSB 135 84/03/22 ELLIOTT, C W Bross & Poswistillo 2pp 22789 032 24X Fiche 50-352,84/03/22, 8403270301
- 8403280353 Forwards regt, "UHS Extreme Wind Hazard Analysis " W/o encl Related correspondence KEMPER.J S Philadelphia Electric Co DBB 160 84/03/22 SCHWENCER.A Licensing Branch 2 1p 22787 173 24X Fiche 50-352,84/03/22,8403280353
- 8403260349 Notion to dismiss particular onsite emergency planning contentions for which discovery not provided or no litigable basis shown Certificate of Svc encl CONNER.T B Philadelphia Electric Co CONNER.T B Conner & Matterhahn DSB 094, 84/03/23 Atomic Safety and Licensing Board Panel. 16pp 22760,243 24X Fiche 50-352,84/03/23,8403260349
- 8403300122 Response to Limerick Ecology Action (LEA) supplemental info on LEA offsite emergency planning contentions Certificate of Svc encl FERKIN, Z O Pennsylvania, Commonwealth of, DSB 203 84/03/23 7pp 22820 303 24% Fiche 50-352,84/03/23,8403300122

- 8403290395 Forwards response to applicant motion to delete specific instances in support of Contention VI-I as unrelated to walding or walding-related GA activities Certificate of Svc encl RDMANO,FR Air and Water Pollution Patrol DSB 201 84/03/25. Atomic Safety and Licensing Board Panel 1p 22814 326, 24X Fichs 50-352,84/03/25,8403290395
- --B403270397 Response to applicant motion to delete specific instances in support of Contention VI-I advanced by Air & Water Pollution Patrol as unrelated to welding or welding-related GA activities. ROMAND.F R Air and Water Pollution Patrol B4/03/24 Atomic Safety and Licensing Board Panel 11pp 22814 327 24X Fiche 50-352,84/03/25,8403290395
- 8403270027 Notice of ASLB constitution L Brenner, chairman & RF Cole & PA Morris, members Served on 840326 COTTER, B P Atomic Sefety and Licensing Board Panel. DBB 125. B4/03/26 2pp 22769 339 24X Fiche 50-352,84/03/26,8403270027.
- 8403270060 Stipulation re storage of unirradiated fuel METTERHAHN.M J Philadelphia Electric Co ELLIOTT.C.W Limerick Ecology Action DSB 12R 84/03/26 2pp 22766 162 24X Fishs 55-352.84/03/26.8403270060
- 8403280331 Memorandum & order confirming 840321 oral ruling on affidavits re radiation releases from unitradiated new fuel rods Served on 840327 BRENNER.L Atomic Safety and Licensing Board Panel DSB 148 84/03/26 Office of the Executive Legal Director 2pp 22787 049 24X Fiche 50-352,84/03/26.8403280331
- 8403280357 Order imposing temporary stay of ABLB 840316 memorandum & order pending receipt of Friends of the Earth appeal of order Served on 840328 SHOEMAKER.C J. Atomic Safety and Licensing Appeal Panel. DSS 161 84/03/27
- 8403300127 Joint rept on status of negotiations re unsite emergency planning contentions & Limerick Ecology Action dismissal of particular contentions Certificate of Svc encl RADER.R M Philadelphia Electric Go RADER.R M Conner & Wetterhahn ELLIOTT.C W Limerick Ecology Action. DBB 206, 84/03/27 6pp 22820 008 24X Fichs 50-352,84/03/27,8403300129
- 8403300271 Forwards GA audits re Colt Industries Fairbanks Morse Engine Div.diesel generators W/o encl.Related correspondence WETTERHAMN, M J. Philadelphia Electric Co. WETTERHAMN, M J. Conner & Hatterhahn DSB 212 84/03/27 3pp 22824 037 24X Fiche 50-352.84/03/27.8403300271
- --B403300274 Response to Air & Water Pollution Patrol (AWPP) B40319 motion to require further depositions re Contention VI-1 AMPP failed to support request for relief & motion should be denied W/Certificate of Svc Related correspondence WETTERHAHN.M J Philadelphia Electric Co. WETTERHAHN.M J Affiliation Not Assigned 84/03/27 Atomic Safety and Licensing Board Pahel 7pp. 22824 040. 24X Fiche 50-352.84/03/27.
- 8403290374 Forwards portions of transcripts re ABLB 840320 ruling on admissibility of Limerick Ecology Action contentions & City of Philadelphia issues on Pacility DEB, Suppl 1 Related correspondence
 HODODONA P Hearing Branch 2 DBB 199 84/03/28, ELLIOYT, C W. Brose & Poswistillo BUSH, M W. Bush, M W. FERKIN, Z Q. Pennsylvania, Commonwealth of. 31pp 22814 091 24X
 Fiche 50-352,84/03/28,8403290374
- 8403270384 Brief in opposition to intervenor Friends of the Earth for stay of onsite storage of unirradiated fuel. Stay request fails to demonstrate any conceivable harm as result of fuel storage Certificate of Svc encl.

 METTERHANN.M J. Philadelphia Electric Co. HETTERHANN.M J. Conner & Hetterhahn D88 170 84/03/28 11pp 22814.240 24X

 Fiche 50-352.84/03/28.8403270384
- 8403290393 Hemorandum & order confirming denial of Air & Water Foliution Patrol motion for further dispositions re Contention VI-1 Certificate of Buc encl BRENNER. L Atomic Safety and Licensing Board Panel. D88 187. 8403290393 4pp 22814 322 24X Fiche 50-352,84/03/28,8403290393.
- 8403290399 Forwards staff 840320 response to Limerick Ecology Action supplementary info VOLER, 8 H Hearing Brench 2. D88 200 84/03/28 BRENNER, L., MORRIS, P A , COLE, R, F Atomic Safety and Licensing Board Panel, 2pp 22814 338 24X Fiche. 50-352,84/03/28,8403290399

- --B403290400 Response to Limerick Ecology Action 840313 supplementary info on offsite emergency planning contentions Staff position remains unchanged Certificate of Svc encl VOLER, B H Hearing Branch 2 B4/03/20 2pp 22814 340 24X Fichs 50-352,84/03/28,8403290399
- B403300127 Transmittal of rafs & errata to applicant B40321 testimony of MJ Boyer, DJ Thompson, DA Kline, L Stanley, EF Sproat, MW Bowers, TE Shannon & J Poering on Contention I-42 Related correspondence METTERHANN, M J Philadelphia Electric Co WETTERHANN, M J Conner & Metterhann DSB 204 84/03/28 7pp 22820 245 24X Fiche, 50-352, 84/03/28, 8403300127
- 8403300128 Response opposing M Lewis 840314 motion for new contention based on IE Info Notice 84-17 cooling of vital components by liquid nitrogen. Certificate of Svc encl WETTERHAHN. M J. Philadelphia Electric Co. WETTERHAHN. M J. Conner & Wetterhahn DSB 205 84/03/28 Atomic Safety and Licensing Board Panel. 12pp 22820.291 24X Fiche 50-352.84/03/28,8403300128
- 8403300287 Forwards PH Pazery 840315 ltr re questions concerning fission products Ltr should be forwarded to appropriate NRC individual for response & response served in proceeding Served on 840330.

 LANE, V. M. Atomic Befety and Licensing Board Penel DBB 218 84703/27, VOQLER, B H. Hearing Branch 2. 2pp 22824 016, R4X Fiche 50-352,84/03/29,8403300287
- K. Utility Final Safety Analysis Report (FBAR) & amends
- 8403020257 Forwards Rev 29 to FSAR. BRADLEY,E J Philadelphia Electric Co 84/02/29 DENTON,H R. Defice of Nuclear Reactor Regulation, Director 2pp 22495 026 24% Fiche: 50-352,84/02/29,8403020257
- --8403020273 Rav 29 to FSAR. * Philadelphia Electric Co 84/02/29 538pp 22495:056 24X Fiche: 50-352:84/02/29:8403020257
- 8403150036 Forwards Affidavit of Byc re distribution of Rev 29 to FSAR & Rev 17 to environ mept, per D9 Eisenhut 810706 request.

 BRADLEY, E. J. Philadelphia Electric Co 84/03/12 DENTON, H R CONTINUE OF Nuclear Reactor Regulation, Director, 5pp 22643,290 24X Fiche; 50-352,84/03/12,8403150036
- G. Inspection reports: IE Bulletins & correspondence
- 8403070055 Responds to IE Bulletin B3-06, "Nonconforming Matls Supplied by Tube-Line Corp Facilities. ." Disposition of subj matl supplied by Guyon Alloys, Inc described Ten 6-inch 45 degree elbows & one 4-inch S R. 70 degree elbow quarantined OALLAOHER, J Philadelphia Electric Co. 84/02/16 MURLEY, T E Region 1, Office of Director. 10pp 22576:051 24X Fiche. 50-352,84/02/16,8403070055
- --8403070319 IE Insp Repts 50-352/84-01 & 50-353/84-02 on 840103-31 No violations noted. Major areas inspected followup on previous insp findings, plant tour, followup on IE bulletins & Nuclear Review Board Charter.

 WIGGINE, J T., CHAUDHARY, B K., CONNER, E. L., Region 1, Office of Director. 84/02/17, 16pp 22546.208 24X Fiche.50-352,84/02/22,8403070314.
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation." Svc list encl URDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidate Edison Co. of New York, Inc 115pp 22709:239 24X Fichs 50-000,84/02/28,8401190072
- 8403020348 Advises of consideration on use of plant-specific PRA & severe accident risk assessments (SARA) to assist NRC in evaluating sempling insp program Requests meeting in Har 1984, to obtain insights from performing PRA & SARA STAROSTECKIR. Division of Project & Resident Programs 84/02/28 KEMPER, J. S. Philadelphia Electric Go 2pp 22439:020 24X Fiche: 50-352,84/02/28,8403020348.
- 8402090007 IE Info Notice 84-i4, "Highlights of Recent Transport Regulatory Revs by DOT & NRC." Syc list encl. GRACE.J.N Division of QA, Bedeguards & Inspection Programs (Post 830103). 84/03/02 Consolidated Edison Co. of New York, Inc. 130pp. 22552:329. 24X Fiche 50-000.84/03/02.8402090007.

- 8402070008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000.84/03/02.8402070008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases" Byo list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Past 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8403160241 Forwards IE Insp Repts 50-352/84-03 & 50-353/84-01 on 840109-10 & 12-13 No violations noted MARTIN.T T Division of Engineering & Technical Programs 84/03/02 KEMPER.J S Philadelphia Electric Co 2pp 22661 036 24X Fiche 50-352.84/03/02,8403160241
- --8403160248 IE Insp Repts 50-352/84-03 & 50-353/84-01 on 840109-10 & 12-13. No violations noted Major areas inspected preoperational radiological environ monitoring program, mgt controls, program for 9C for analytical measurements STRUCKMEYER, R. . PABCIAK, W. J. Region 1, Office of Director 84/02/23 dpp. 22661 038, 24% Fiche 50-352,84/03/02,8403160241
- 8402090011 IE Info Natice 84-17. "Problems W/Liquid Nitrogen Cooling Components Below Nit Ductility Temp " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Ca of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402070011
- 8402090024 IE Info Notice 84-09.Rev 1. "Lessons Learned From Insps of Fire Protection Bafe Shutdown Sys " Svc list encl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22635 049 24X Fiche 50-000,84/03/07.8402090024
- 8402070028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Sys " 8vc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186, 24X Fiche 50-000,84/03/07,8402070028
- 8402090031 IE Bullatin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Bys " 8vc list encl DEYOUNG: R C Director's Office Office of Inspection and Enforcement 94/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000.84/03/12.8402090031
- 8402070043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84703/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000,84/03/21,8402070043
- 8402090044 IE Info Notice 84-20, "Evo Life of Relays in Safety-Related Sys " Byo list enc!
 JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044
- 8. Reportable occurrences, LERs & related correspondence
- B403130084 Final Bignificant Deficiency Rept 129 re Agastat CR0095 relay socket failures. Defective sockets replaced w/Agastat CR002 sockets, correcting any adverse safety implications induced by socket failure KEMPER, J 8 Philadelphia Electric Co 84/02/17 MURLEY, T E Region 1, Office of Director, 3pp 22598 343 24X Fiche 50-352,84/02/17,8403130084
- 8403270219 Part 21 rept re broken contact carrier in control device of 7 5 kV-15 kV,500-750 MVA,5 kV 350-3,000 & all HKV circuit breakers Initially reported on 830223 Addenda to installation & maint procedures sent to affected units DUVALL,D D Brown Boveri Corp (subs of Brown Boveri & Co , Ltd) 84/03/19 Record Services Branch (Document Control Desk) 5pp 22772,114 24X Fiche: 50-000,84/03/19,8403270219.
- T Hearing transcripts on non-antitrust matters
- B403020129 Forwards revised testimony re ability of safety-related structures to withstand effects of postulated detonation resulting from assumed ruptures of Arca & Columbia gas transmission pipelines Related correspondence WETTERHAHN, M. J. Conner & Wetterhahn. WETTERHAHN, M. J. Philadelphia Electric Co. 84/02/28 BRENNER, L. Atomic Safety and Licensing Board Panel 2pp 22442, 112 24X Fichs. 50-352, 84/02/28, 8403020129

- --8403020136 Revised testimony of Philadelphia Electic Co re ability of safety-related structures to withstand effects of postulated detonation due to ruptures of transmission pipelines W/Certificate of Svc Related correspondence

 Philadelphia Electric Co 84/02/28 29pp 22442 114 24X Fiche 50-352,84/02/28,8403020129
- 8403080255 Transcript of 840305 hearing in Philadelphia,PA Pp 7.565-7.696 * Commissioners 84/03/05 [31pp 22556 306 24x Fiche 50-352,84/03/05,8403080285
- 9403120092 Transcript of 840305 hearing in Philadelphia, Pa Pp 7, 696-* Commissioners 84/03/06 24 Fiche 50-352,84/03/06,8403120092 246pp 22588 249 24x
- 8403:20151 Transcript of 840307 hearing in Philadelphia.PA Pp 7.943-8.138 * Atomic Safety and Licensing Buard Panel 84/03/07 216pp 22585 263 24X Fiche 50-352.84/03/07.8403120151
- 9403130040 Transcript of 840308 hearing in Philadelphia, PA Pp 8, 159-8,383 ** Atomic Bafety and Licensing Board Panel 84/03/08 268pp 22598 067 24% Fiche 50-352,84/03/08,8403130040
- 8403130113 Transcript of 840309 hearing in Philadelphia.PA Pp 8,394-8,505 B.334-8.505 * Atomic Safety and Licensing Board Panel 84/03/09 22pp 22601 001 24X Fichs 50-352.84/03/07.8403130113
- 8403220145 Transcript of 840319 hearing in Philadelphia, PA Pp 8,506-8.647 * Atomic Safety and Licensing Board Panel 84/03/19 150pp 22714 142 24X Fiche 50-352.84/03/19.8403220145
- 8403260254 Transcript of 840320 hearing in Philadelphia.PA Pp 8.647-8,842 Supporting documentation encil

 Atomic Bafety and Licensing Board Panel 84/03/20 202pp
 22755 208 24X Fiche 50-352,84/03/20,8403260254
- 8403260015 Transcript of 840321 hearing in Philadelphia, PA Pp 8,843-9.039 Supporting documentation encl * Atomic Safety and Licensing Board Panel 84/03/21 283pp 22746 001 24X Fiche 30-332,84/03/21,8403260015.
- 8403260334 Transcript of Commission 840321 affirmation/discussion & vote in Washington, DC re-proposed order delegation/discuss: vote in Washington, DC re-proposed order delegating authority to ASLB to hear Part 70 issues raised in Limerick proceeding Pp 1-3

 **Commissioners 84/03/21 6pp, 22775 281 24X

 Fithe 50-352:84/03/21.8403260334
- 8403270042 Transmittal of testimony re Contention I-42, "Environ Qualification of Electrical Equipment" Related Correspondence
 WETTERHAHN, M. J. Philadelphia Electric Co. WETTERHAHN, M. J. Conner & Wetterhahn D89 120 84/03/21 2pp 22769 242 24X
 Fiche 50-352, 84/03/21, 8403270042
- ---8403270048 Testimony of HJ Boyer, DJ Thompson, DA Kline, L Stanley, EF Sproat, HW Boyers, TE Shannon & J Doering re Contention I-42, "Environ Qualification of Electrical Equipment" Certificate Of Svc encl
 BDYER, W J , THOMPSON, D J , KLINE, D A Philadelphia Electric Co
 84/03/21 55pp 22769 244 24X Fiche 50-352,84/03/21,8403270042
- 8403270296 Testimony of A Masciantonio on Limerick Ecology Action Contention I-42 re electrical environ qualification Related Correspondence
 Correspondence
 MASCIANTONIO.A Equipment Qualification Branch DSB 138 84/03/21
 10sb 22789 037 24X Fiche 50-352,84/03/21,8403270296
- 8403270171 Transcript of 840322 hearing in Philadelphia, PA. Pp 9,060-7.400 * Atomic Safety and Licensing Board Panel 84/03/22 210pp. 22773 150. 24% Ficha 50-352,84/03/22,8403270171
- 8403270160 Transcript of 840323 hearing in Philadelphia, PA. Pp 9, 267-* Atomic Safety and Licensing Board Panel 84/03/23 137pp. 22764, 233 24X Fiche 50-352, 84/03/23, 8403270160
- 8403300009 Memorandum serving transcript pages re 840323 prefiled testimony on Limerick Ecology Action Contention I-42 concerning environ qualification Served on 840329 BRENNER: L Atomic Safety and Licensing Board Panel. DBB 209. 84/03/29 1p. 22822 131 24% Fiche 50-352.84/03/29.8403300009

- --B403300014 Transcript Pp 9,270-9,274 of B40323 testimony on Limerick Ecology Action Contention I-42 re environ qualification * Office of the Executive Legal Director * Philadelphia Electric Co * Limerick Ecology Action 84/03/29 5pp 22822 132 24X Fiche 50-352,84/03/29,8403300009
- DOCKET SO-354 HOPE CREEK NUCLEAR STATION: UNIT 1
- A Application/construction stage documents & correspondence
- B403140340 Summary of B31215 meeting w/GE & Mark I Dwners Group in Bethesda.MD re Mark I containment wetwell-drywsll vacuum breaker design methodology SIEGEL B L Dpracting Reactors Branch 2 B4/02/21 Operating Reactors Branch 2 51pp 22635 198 24X Fiche 50-000.84/02/21.
- 8403060552 Summary of 840110-12 meetings w/util, Bechtsl, NUTECH, Impall, FDM & Dames & Moore in San Francisco, CA re structural & geotechnical engineering design audit. Supporting gocumentation encl WAGNER, D. Licensing Branch 2 84/02/27 Licensing Branch 2 15pp 22552 276 24X Fiche 50-354.84/02/27.8403060552 documentation encl
- 8403140113 Forwards "Salem Generating Station 316(b) Demonstration." Housevolts converge "Salem Generating Station 316(b) Demonstration," per 830623 request for addl info re review of OL application for Hope Creek
 MITTL.R L Public Service Electric & Gas Co of New Jersey
 84/03/05 SCHHENCER.A Licensing Branch 2 ip 22629 124 24X
 Fichs 50-000.84/03/05.8403140113
- --8403140117 "Salem Generating Station 316(b) Demonstration "
 * Public Service Electric & Oas Co of New Jarsey, 84/0:
 647pp 22629 125 24X Fiche 50-000,84/03/05,8403140113 84/02/29
- 8403150259 Notification of 840301 meeting w/util in Artificial Island. NJ to discuss GA program
 WAGNER, D H Licensing Branch 2 84/03/05 SCHWENCER, A. Licens
 Branch 2 3pp 22649 349 24X Fiche 50-354,84/03/05,8403150259
- 8403210036 Forwards tabulation on FSAR commitments for Feb 1984 & Corresponding resolutions on rank commitments for Feb 1704 & corresponding resolutions MITTL.R L. Public Service Electric & Gas Co of New Jersey. 84/03/05 SCHHENCER.A Licensing Branch 2 4pp 22707 001 24X Fiche 50-354.84/03/05.8403210036
- 8403140007 Forwards data sheets reflecting current & proposed experience levels for licensed operators at Pacility 8ALVESEN,R 8 Public Service Electric & Gas Co of New Jersey 84/03/12 DENTON,H Défice of Nuclear Reactor Régulation, Director 11pp 22632 130 24X Fichs 50-354,84/03/12,8403140007.
- 8403290302 Forwards "Qualification Test Repts, EMI Tests" & "Qualification Test Rept, Burge Withstand Capability Tests," per agreement reached at 84012 meeting on Control Bys Branch Question 421-49 MITTL.R L Public Service Electric & Qas Co of New Jarsey, 84/03/16 SCHMENCER, A Licensing Branch 2 ip 22802 099, 24X Fiche 50-354,84/03/16.8403290302.
- --8403270305 "Qualification Test Rept.EMI Tests "
 * Validyne Engineering Corp QTR-82-010 82/06/17 63pp.
 22802 100 24% Fiche 50-354,84/03/16,8403290302
- --8403270308 "Gualification Test Rept. Burge Withstand Capability."

 * Validyne Engineering Corp GTR 82-003 83/04/21, 7pp
 22802 165 24X Fiche. 50-354, 84/03/16, 8403270302
- C Utility Environmental Report (ER), amends & correspondence
- 840323004i Advises that "Salem Generating Station 316(b) Demonstration" being forwarded directly to GRNL.per H Adams request during NRC 840215 site visit w/ORNL.Rept should facilitate environ rept review
 MITTL:R L Public Bervice Electric & Gas Co. of New Jersey
 84/03/08 8CHWENCER: A Licensing Branch 2 ip 22728 355 24X
 Fiche 50-354:84/03/08:840323004i
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8403220308 Forwards draft SER identifying unresolved issues as open items:per NRC safety review of docketed application & amends SER issuance scheduled for 841012 Schedule for meetings to regulve open items requested SCHMENCER: A Licensing Branch 2 84/03/05 MITTL,R,L Public Service Electric & Oas Co. of New Jersey 624pp. 22722.001. 24X Fiche 50-354,84/03/05,8403220308.

F Security, medical, emergency & fire protection plans

- 8403030369 Summary of 840202 meeting w/util,HTI.Essex & Bechtel in Bethesda.MD re control room design review.per Suppl i to NUREG-0737 Further clarification required in task analysis area.Viewgraphs encl HAGNER.D H Licensing Branch 2 84/02/24 Licensing Branch 2 25pp 22527 284 24X Fiche 50-354.84/02/24,8403050369
- 8403220084 Forwards IE Insp Rept 50-354/84-02 on 840109-0220 No violations noted BTAROSTECKI.R Division of Project & Resident Programs 84/03/04 MARTIN.T J Public Service Electric & Gas Co of New Jersey 2pp 22716 288 24X Fiche 50-354,84/03/06,8403220086
- --B403220089 IE Insp Rept 50-354/84-02 on 840109-0220 No violations moted. Major areas inspected documentation packages on piping sys rupture discs & licensee action on const deficiency repts.torus mod & fire protection BATEMAN.W H. MCCABE.E. C. Region 1, Dffice of Director 84/03/05 Bpp. 22716-290 24X Fiche-50-354,84/03/06,8403220086
- 8403190243 Notification of 840418 workshop in King of Prussia, PA to discuss lessons learned from recent App R fire protection safe shutdown insp & topics described in IE Info Notice 84-09 Agenda for workshop encl.

 MURLEY.T E Region i, Office of Director 84/03/09 D'TODLE. J D Consolidated Edison Co. of New York, Inc. 35pp 22672 062 24X Fiche 50-000, 84/03/09, 8403190243

Q. Adjudicatory correspondence

- 8403020141 Conveys agreement w/State of NJ Public Advocate re consent to util motion to dismiss Contention IV on environ impact of cooling tower N/o encl
 DELANEY,C.E. Delaware, State of 84/02/27 MILLER,M E Atomic Safety and Licensing Board Panel 2pp 22439 005 24X
 Fiche. 50-354,84/02/27,8403020141.
- 8403140028 Advises that time for Commission to review ALAB-759 expired Commission declined review Decision became final agency action on 84038 GMILK:8 J Office of the Secretary of the Commission 84/03/13 Atomic Safety and Licensing Board Panel 1p 22633.214 24X Fiche 50-334.84/03/13.8403140028
- 8403150020 Response upposing public advocate 840227 motion to vacate applicant 840222 notice of deposition & for protective order in form of declaratory ruling Related correspondence. CONNERT. I.B. Public Service Electric & Qas Co of New Jersey CONNERT. I.B. Conner & Wetterhahn 84/03/13 Atomic Safety and Licensing Board Panel 16pp 22641,262 24X Fiche: 50-354,84/03/13.8403150020.
- --B403150022 Application for subposes to JH Rodriguez on 840330 in Newark, NJ. Centificate of Syc encl CONNER. T. B. Public Service Electric & Gas Co of New Jerssy CONNER, T. B. Conner & Wetterhahn 84/03/13, Atomic Safety and Licensing Board Panel 3pp 22641 277 24X Fiche 50-354, 84/03/13,8403150020
- BACG190164 Response supporting Dept of Public Advocate of State of NJ BACG27 motion for protective order Applicant has not indicated what specific knowledge re adjudication of contentions Rodriguez believed to have DEWEY, L. B Hearing Branch 3. B4/CG/14 Atomic Safety and Licensing Board Panel. 7pp 22669 177 24X Fiche 50-354,84/CG/14,84CG190164
- 8403210087 Subpoems commanding JH Rodrigue: to appear on 840330 in Newark,NJ Affidavit encl. Related correspondence MILLER H E. Atomic Safety and Licensing Board Panel 84/03/15 Commissioners, 6pp 22705-314, 24X Fichs, 50-354, 84/03/15, 8403210087.
- 8403200102 Notifies of taking of deposition of JH Rodriguez Subpoena encl
 GONNER.T.B. Conner & Wetterhahn
 Electric & Gas Co. of New Jersey.
 the Executive Legal Director ip
 Fiche 50-354,84/03/16,8403200102
- ---8403200108 Subpoena directing UH Rodrigue: to appear on 840330 at Ofc of General Solicitor in Newark.NJ for disposition.

 MILLER.M.E Atomic Safety and Licensing Board Panel 84/03/15 RODRIGUEZ.VJ. H. New Jersey, State of ip 22685;317. 24X Fiche: 50-354, 84/03/16, 8403200102.
- B403210163 Notice of ABLB reconstitution ME Miller, chairman & PA Morris & DR Schink, members Served on 840321. COTTERS.P. Atomic Safety and Licensing Board Panel DBS 018 B4/03/20. 2pp. 22718 224. 24X Fiche 50-354, 84/03/20, 8403210163.

- 8403300270 Answer to Public Advocate of State of NJ motion to quash supposens requiring attendance & testimony of JH Rodrigues Motion does not satisfy stay criteria W/Certificate of Svc Related correspondence CONNER.T B Public Service Electric & Oas Co of New Jersey CONNER.T B Conner & Wetterhahn DSB 217 84/03/29 Atomic Bafety and Licensing Appeal Panel 12pp 22824 047 24X Fiche 50-354-84/03/29,8403300270
- 8403300278 Order queshing ABLB 840315 subpoena directed to intervenor JH Rodrigue: Subpoena moot Served on 840330 SHORMAKER.C J Atomic Safety and Licensing Appeal Panel DSB 225 84/03/29 2pp 22824 018 24% Fichs 50-354.64/03/29.8403300278

H Ganeral correspondence

- 8403280045 Responds to 840217 inquiry re plants not considered for insp of vent header cracks in torus Insp inapplicable because Fermi & Hope Creek still in const stage DENTON, HR Office of Nuclear Reactor Regulation, Director 84/03/12 MESTOVER, A T Monros County, MI ip 22812 358, 24X Fichs 50-000.84/03/12.8403280045
- --B403280054 Requests explanation as to why facility not considered for insp for cracks in vent header similar to crack found at Hatch HEBIOVER.A J Monroe County, MI 84/02/17 Office of Nuclear Reactor Regulation, Director 2pp 22812 359 24X Fiche 50-000,84/03/12:8403280045
- Q Inspection reports, IE Bulletins & correspondence
- B403070037 Forwards IE Imap Rept 50-354/84-01 on 840110-13 & notice of violation
 MARTIN, T T Division of Engineering & Technical Programs 84/02/22
 MARTIN, T J Public Service Electric & Gas Co of New Jersey 2pp
 22576 020 24X Fiche 50-354,84/02/22,8403070037
- ---B403070037 Notice of violation from insp on 840110-13
 * Region 1, Office of Director. 84/02/22 ip 22576 022 24X
 Fiche 50-354,84/02/22,8403090037
- --8403070043 IE Insp Rept 50-354/84-01 on 840110-13 Violations noted heat not restored to alternators of four diesels as required by Litton Industries maint manual & licensee maint instructions FINKEL, A. PAULITZ, F., ANDERSON, C. J. Region 1, Office of Director 84/02/07 App 22074 023 24X Fiche 50-354,84/02/22,8403070037
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22907 237 24X Fiche 50-000.84/02/28.8401190072
- 8403070080 Submits supplemental response to IE Bulletin 83-06 re nonconforming matts supplied by Tube-Line Corp Remaining four suppliers confirmed that no subj matts supplied to Hope Creek Colt Industries info under review MARTIN. T J Public Service Electric & Oas Co of New Jersey 84/02/28 MRALEY. T E Region 1. Office of Director 2pp 22575 297 24X Fiche 50-000.84/02/28.8403090080
- 8402090007 IE Info Natice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Evc list encl GRACE.J N Division of OA, Safeguards & Inspection Programs (Post 830103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329, 24X Fiche 50-000.84/03/02.8402090007.
- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Bys Valves to Operate "Svc list encl.

 JORDAN, E. L. Division of Emergency Preparadness & Engineering Response (Poet 830103) 84/03/02 Consolidate Edison Co. of New York, Inc. 122pp. 22553 078 24X Fiche 50-000,84/03/02,8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases "
 Svc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02. Consolidated Edison Co of New
 York, Inc 119pp 22553 217 24X Fiche.50-000.84/03/02.8402090009
- 8402070011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/03/05 Consolidated Edison Co of New York, Inc 117pp. 22553 336 24% Fiche 50-000.84/03/05,8402070011

- 8403220086 Forwards IE Insp Rept 50-354/84-02 on 840109-0220 No violations noted STARDSTECKI.R Division of Project & Resident Programs 84/03/06 MARTIN.T J Public Service Electric & Gas Co of New Jersey 2pp 22716 288 24% Fiche \$0-354.84/03/06.8403220086
- --8403220087 IE Insp Rept 50-354/84-02 on 840107-0220 No violations noted Major areas inspected documentation packages on piping sys rupture discs & licensee action on const deficiency repts.torus mod & fire protection BATEMAN, H H, MCCABE, E C Region 1. Office of Director 84/03/0 Bpp. 22716 270. 24X Fichs.50-354.84/03/06.8403220086
- 8402090024 IE Info Notice 84-09. Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutfown Sys " Svc list encl JORDAN. E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000. 84/03/07. 840209024
- B40209002B IE info Notice 84-18, "Stress Corrosion Cracking in PWR Sys " Svc list enc!
 JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc. 118pp 22584 186 24X Ficher 50-000, 84/03/07, 8402070028
- B403i30009 Ack receipt of 840210 ltr informing NRC of steps taken to correct violations noted in IE Inep Rept 50-354/83-14
 MARTIN.T T. Division of Engineering & Technical Programs B4/03/07
 MARTIN.T J Public Service Electrick Qas Co of New Jersey lp
 22615 161 24x Fiche 50-354.84/03/07.8403130009
- ---B403130014 Responds to NRC 840110 ltr re violations noted in IE Insp Rept 50-354/83-14 Corrective actions reinsp of all safetyrelated electrical wall mounted supports performed to determine extent of connections exceeding criteria MARTIN.T J Public Service Electric & Cas Co. of New Jersey 84/02/10 HURLEY.T E Region to Office of Director 4gp 22615 162 24X Fiche 50-354,84/03/07,8403130009
- B403130355 Act receipt of 840228 ltr informing NRC of steps taken to correct violations noted in IE lnsp Rept 50~354/83-18
 BIAROSTECKI/R Division of Project & Resident Programs B4/03/08
 MARTINIT J Public Service Electric & Qas Co of New Jersey 1p
 22616 250 24X Fiche 50~354,84/03/08.8403130355
- --8403130372 Responds to NRC 840130 ltr re violations noted in IE Insp Rept 50-334/83-18 Corrective actions seven nonconforming hangers will be reworked to obtain required depth of weld penetration at skewed T-joints MARTIN.T J Public Service Electric & Oas Co of New Jersey 84/02/28 MURLEY.T R Region to Office of Director App 22616 251 24X Fiche 50-354,84/03/08,8403130355
- 8402090031 IE Bulletin 84-02. "Failures of GE Type HFA Relays in Use in Class IE Befety Sys " Svc list encl DEYOUNG, R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York. Inc 134pp 22823 094 24% Fiche 50-000.84/03/12,8402090031
- 8403300098 Forwards IE Insp Rept 50-354/84-03 on 840120 No violations observed MARTIN.T T Division of Engineering & Technical Programs 84/03/16 MARTIN.T J Public Service Electric & Gas Co of New Jersey 2pp 22822 004 24X Fiche 50-354,84/03/16,8403300098
- --8403300103 TE Insp Rept 50-354/84-03 on 840120 No violation identified Major areas inspected discrepancies identified in original selemic analysis of auxiliary bldg MANOLY, K . DURR, J P Region 1. Office of Director 84/03/07 App 22822 006 24% Fiche 50-354,84/03/16,8403300098
- 8402090043 IE Info Notice 84-19: "Two Events Involving Unauthorized Entries into PMR Reactor Cavities" Svc list entl JURDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc. 123pp 22823.229 24X Fiche 50-000.84/03/21.8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc list enc! JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/21 Consolidated Edison Co of New York: Inc 135pp 22933 001 24X Fiche 50-000.84/03/21.8402090044
- 8403300121 Responds to IR Bulletin 83-07. "Apparently Fraudulent Products Sold by Ray Miller, Inc." Bechtel investigating suppliers not responding to request of whether fraudulent matls shipped.

 MARTIN, T T Public Service Electric & Oas Co of New Jersey 84/03/21 MURLEY, T E Region 1. Office of Director 2pp 22820 345 24% Fiche 30-354,84/03/21,8403300121

- S Reportable occurrences. LERs & related correspondence
- B403210118 Interim deficiency rept re failure of QE Type AKR-30 circuit breakers Initially reported on B31223 Breakers reinspected. Next rept will be submitted by 840514 MARTIN.T J Public Service Electric & Oas Co of New Jersey B4702/24 MURLEY.T E Region 1. Office of Director 2pp. 22705 G75 24X Fiche 50-334.84702/24.8403210118
- 8403260233 Forwards summary list of deficiencies identified per iOCFR00 55(e),Part 21 & potential generic itr repts for comments

 STAROSTECKI,R Division of Project & Resident Programs Region 1, Office of Director 7pp 22756 065 24X Fiche 50-000.84708/28 4803260233
- 8403150108 Potentially significant const deficiency rept re defective capstan springs in ITT Grinnel shock arrestors Initially reported on 831024 Condition does not warrant coming offline to replace springs Next rept by 840429 MARTIN.T J Public Service Electric & Gas Co of New Jarsey, 84706279 MAREV.T E Region 1, Office of Director 2pp. 22640 207 24X Fiche 50-354.84702/29,8403150108.
- 8403270219 Part 21 rept re broken contact carrier in control device of 7.5 tV-15 kV.500-750 MVA,5 kV 350-3,000 & all HKV circuit breakers Initially reported on 830223 Addenda to installation & maint procedures sent to affected units.

 BUVALL.D D. Brown Boveri Corp (subs of Brown Boveri & Co , Ltd) 84/03/19 Record Services Branch (Document Control Desk) 5pp 22772 114 24X Fiche 50-000,84/03/19,8403270219.
- DOCKET 50-355 HOPE CREEK NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8403140340 Summary of 831215 meeting w/OE & Mark I Dwners Group in Bethesda.ND re Mark I containment wetwell-drywell vacuum breaker design methodology BIEGEL.B L Operating Reactors Branch 2 84/02/21 Operating Reactors Br
- F Security, medical, emergency & fire protection plans
- B403190243 Notification of B40418 workshop in King of Prussia.PA to discuss lessons learned from recent App R fire protection safe shutdown insp & topics described in IE Info Notice 84-09 Agenda for workshop enci MURLEY.TE Region 1. Office of Director 84/03/09, O'TDDLE.J D Consolidated Edison Co. of New York. Inc. 35pp. 22672 062. 24X Fiche 50-000.84/03/09.8403190243
- H General correspondence
- 8403280045 Responds to 840217 inquiry re plants not considered for insp of vent header cracks in torus Insp inapplicable because Fermi & Hope Creek still in const stage DENTON, H.R. Office of Nuclear Reactor Regulation, Director 84/03/12 WESTOVER, A.T. Monros County, MI. ip 22812 358 24X Fiche 30-000.84/03/12.8403280045
- --8403280054 Requests explanation as to why facility not considered for insp for cracks in vent header similar to crack found at Hatch Hatch HESTOVER.A J. Honroe County, MI 84/02/17, Office of Nuclear Reactor Regulation, Director 2pp 22812,357 24X Fiche 50-000,84/03/12,8403280045
- G Inspection reports. IE Bulletins & correspondence
- 8403090080 Submits supplemental response to IE Bulletin 83-04 re nonconforming matls supplied by Tube-Line Corp Remaining four suppliers confirmed that no subj matls supplied to Hope Creek Colt Industries info under review MARTIN, T J Public Service Electric & Qas Co of New Jersey. 84/02/28 MURLEY, T E Region 1, Office of Director 2pp 22575 297 24% Fiche 50-000, 84/02/28, 8403090080.
- 8403300121 Responds to IE Bulletin 83-07. "Apparently Fraudulent Products Sold by Ray Miller, Inc "Bechtel investigating suppliers not responding to request of whether fraudulent matis shipped MARTIN.T T Public Service Electric & Oas Co of New Jersey 84/03/21 MURLEY,T E Region 1, Office of Director. 2pp 22820 345 24X Fiche 50-354,84/03/21,8403300121.

S Reportable occurrences, LERs & related correspondence

- B403240233 Forwards summary list of deficiencies identified per 10CFR30 55(e).Part 21 & potential generic ltr repts for comments
 - ETAROBTECKI.R Division of Project & Resident Programs 84/02/28 Region i. Office of Director 7pp 22756 065 24X Fiche 50-000.84/02/28.8403260233
- 8403180108 Potentially significant const deficiency rept re defective capstan springs in ITT Orinnel shock arrestors Initially reported on 831024 Condition does not warrent coming offline to replace springs Next rept by 840427 MARTIN.T J Public Service Electric & Oas Co of New Jersey 84402279 MARLEY,T E Region 1. Office of Director 2pp 22640 207 24X Fiche 50-354,84/02/27,8403150108
- 8403270219 Part 21 rept re broken contact carrier in control device of 7 5 kV-15 kV.500-750 MVA, 5 kV 350-3.000 & all HKV circuit breakers Initially reported on 830223 Addenda to installation & maint procedures sent to affected units DUVALL, D.D. Brown Boveri Corp. (subs of Brown Boveri & Co., itd) 84/03/19 Record Services Branch (Bocument Control Desk) 5pp 22772 114 24X Fiche 50-000.84/03/19,8403270219
- DOCKET 50-358 WILLIAM H ZIMMER MUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8403130288 Forwards Natl Board of Boiler & Pressure Vessel Inspectors 840227 it to State of OH re util abandonment of facility as nuclear unit & board willingness to provide support should plant be reinstated.

 MARRISON.8 F. National Board of Boiler & Pressure Vessel Inspectors 84/03/05 DIRKES W Office of the Executive Director for Operations 17pp 22608 017 24X Fiche 50-358.84/03/05.8403130288
- 8402090041 Board Notification 84-050 provides Commission policy statement & proposed rulemaking on environ qualifications EISENHUT, D 0 Division of Licensing 84/03/14 Atomic Safety and Licensing Board Panel 10pp 24% Fiche 50-000/84/03/14,8402090041
- 8403260065 Responds to 831128 1tr clarifying role in work performed for HJ Kaiser Co during Apr-Sept 1983 Reevaluation personnel verification program recommended KEPPLER.J G. Region 3. Office of Director 84/03/20 ROBERTS.J Cugha Energy Services 7pp 22750 245. 24X Fiche 50-358,84/03/20, R603260065
- ${\bf F}$ -Becurity, medical, emergency & fire protection plans
- 8402090006 Board Notification 84-034 forwards R Vollmer 840206 memo to D Eisenhut re fire research results concerning fires in electrical cabinets in control room EISENHUT, D Q. Division of Licensing, 84/02/23 PALLADINO Commissioners ip 22576-203 24X Fiche 80-000,84/02/23,8402090006
- --84030B0316 Recommends that info re fire research results concerning fires in electrical cabinets in control room be submitted for board notification, per NAR DFC Ltr 17, dtd 821001 Further evaluation of test data required VOLLMER:R M. Division of Engineering 84/02/06 EISENHUT, D Q Division of Licensing 10pp 22576 204 24X Fiche, 50-000, 84/02/23, 8402070006
- B403120093 Extends invitation to attend B40323 regional workshop in Rosemont. It re 10GFR50. App R safe shutdown requirements Workshop will cover subje described in IE info Notice 84-09 & provide add1 guidance in safe shutdown analyses BFE68ARD.R L Division of Engineering 84/03/06 WAGNER.E J Cincinnati Qas & Electric Co 3pp 22588 191. 24X Fiche: 50-358.84/03/06.8403120093.
- Adjudicatory correspondence
- 8403050066 Order extending time until further order for Commission to act to review Director's Decisions DD-83-19 & DD-84-3 CHILK: 8 J. Office of the Secretary of the Commission 84/02/29 Commissioners 1p. 22490 182 24X Fichs 50-358.84/02/29, 8403050066.
- 8403210178 Motion requesting issuance of order authorizing withdrawal of application Plant will be used as part of new fossil fuel-fired electric generating plant Certificate of Syc ancl.

 CONNER, T.B. Cincinnati Gas & Electric Co CONNER, T B Conner & Hetterhahn D8B 024 84/03/20 Atomic Safety and Licensing Board Panel Bpp. 22710 098 24% Fiche. 50-358, 84/03/20, 8403210178

- G Inspection reports, IE Bulletins & correspondence
- 9403230104 Requests add1 60 days to accomplish review of work performed by Reactor Controls. Inc. in response to NRC 831017 draft info notice Extension required due to physical walkdown of selected sys
 HILLIAMS. J Cincinnati Gas & Electric Go 83/11/22 KEPPLER, J G Region 3. Office of Director 2pp 22730 226 24X
 Fiche 50-358,83/11/22.8403230104
- 8401190072 IE Info Natice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22909 239 24X Fiche 50-000,84/02/28,8401190072
- 8403190315 Forwards IE Insp Rept 50-358/84-01 on 840107-0213 No noncompliance identified WARNICK.R F Region 3, Office of Director 84/02/29 WAGNER.E J Cincinnati Qas & Electric Co 2pp 22673 215 24X Fiche 50-358,84/02/29,8403190315
- --8403190323 IE Insp Rept 50-358/84-01 on 840107-0213 No noncompliance identified Major areas inspected previous insp findings, quality confirmation program nonconformance rept review & personnel indoctrination program GHYNN.T.P , NIGHTINOALE,E , HILL.W M Region 3, Office of Director 84/02/28 19pp 22673 217 24X Fiche 50-358,84/02/29,8403190315
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC." Svc list encl ORACE.J N Division of OA, Bafeguards & Inspection Programs (Post B30103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000,84/03/02,8402090007
- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008
- B402090009 IE Info Notice 84-15, "Reporting of Radiological Releases" Svc list encl JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 119pp 22553 217 24% Fiche 50-000,84/03/02.8402090009
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Bvc list encl JORDAN E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New Yark, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8402090024 IE Info Notice 84-09, Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown 8ys " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 82835 049 24% Fiche 50-000,84/03/07,8402070024
- 8402090028 IE Info Notice 84-18. "Stress Corrosion Cracking in PWR Sys " Syc list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Syc list encl DEYOUNG.R C Director's Office Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000,84/03/12,8402090031
- 8402070043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 123pp 22823 229 24X Fiche 50-000.84/03/21,8402070043
- B402070044 IE Info Notice 84-20: "Syc Life of Relays in Safety-Related Bys." Syc list and JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22733 001 24X Fiche 50-000:84/03/21,8402070044

- 9 Reportable occurrences, LERs & related correspondence
- 8403270219 Part 21 rept re broken contact carrier in control device of 7 5 kV-15 kV.500-750 MVA.5 kV 350-3.000 & all HXV circuit breakers Initially reported on B30223 Addenda to installation & maint procedures sent to affected units DUVALL.D D Brown Boveri Corp. (subs. of Brown Boveri & Co., Ltd.) 84403/19 Record Services Branch (Document Control Desk.) 5pp 22772 114 24X Fichs 50-000.84/03/19.8403270219
- U Congressional/Executive Correspondence
- 8402130393 Responds to 840111 request for development of facility public safety oversight committee Herits of committee not judged due to util intention not to complete project as nuclear plant PALLADINO.N J Commissioners 84/01/31 COLLINS.M L Kentucky, Commonwealth of, 1p 22662 250 24X Fiche 50-358,84/01/31,8402130393
- --B402130399 Responds to B31212 request for development of facility public safety oversight committee Herits of committee not Judged due to util intention not to complete project as nuclear plant PALLADINO, N. J. Commissioners 84/01/31 BORTZ, A. Cincinnati. CH. Ip 22662 251 24X Fiche 50-356,84/01/31,8402130393
- --8402130390 Responds to 831221 request for development of facility public safety oversight committee Merits of committee not judged due to util intention not to complete project as nuclear plant PALLADING.N J Commissioners 84/01/31 METZENBAUH.H M Senate. Energy & Natural Resources 1p 22662 232 24X Fichs 50-358,84/01/31,8402130393
- --8402130333 Responds to 831215 request for development of facility public safety oversight committee Merits of committee not judged due to util intention not to complete project as nuclear plant PALLADIND.N J Commissioners 84/01/31 CELESTE, R Ohio, State of 4pp 22662 253 24X Fiche 50-338.84/01/31.8402130393
- --8402130395 Requests development of proposed facility public oversight committee Committee establishment would inspire public confidence COLLING.M L Kentucky. Commonwealth of. 84/01/11 PALLADING.N Commissioners ip 22662 254 24X Fiche 30-358.84/01/31, 8402130393
- --8402130392 Requests development of public oversight committee to review facility safety-related problems NRC & util credibility questioned as public witness cost overrums & safety flaws. METZENBAUM, H M Senate, Energy & Natural Resources 83/12/21 PALLABINO.N J Commissioners 1p 22662 257 24X Fiche 50-358,84/01/31,8402130393
- --8402130360 Requests changes in proposed facility oversight committee Changes needed to inspire public confidence in oversight process CELESTE, R F Ohio, State of 83/12/15 PALLADINO, N Commissioners ip 22662 258 24% Fiche 50-359,84/01/31, 8402130393
- DOCKET 50-361 SAN DNOFRE NUCLEAR STATION, UNIT 2
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8403020333 Forwards "Evaluation of Natural Circulation Cooldown Test Performed at San Onofre Nuclear Generating Station " Boron mixing tests in lieu of natural circulation test accepted by updated SER & SSER 5 COOK.K W Louisiana Power & Light Co 84/02/27. KNIGHTON.G W Licensing Branch 3 ip 22439.035 24X Fiche 50-000.84/02/29, 8403020333
- F Security, medical, emergency & fire protection plans
- 8402030338 Forwards revised "Emergency Plan Implementing Procedures. Ban Onofre Nuclear Generating Station-Units 1.2 & 3 " CRDY, P. A. Bouthern California Editon Co. 84/01/27 NRC - No. Detailed Affiliation Given 1p. 22064 013 24X Fiche 30-206.84/01/27,8402030338
- --B402030344 Revised "Emergency Plan Implementing Procedures, San Unofre Nuclear Generating Station, Units 1,2 & 3 " ANDERSON, C K , PATRISSI, O A Southern California Edison Co 84/01/27 523pp 22064:015 24X Fiche: 50-206. 84/01/27, 8402030338

- 8403050148 Forwards "Evaulation of Southern California Edison Site-Specific Offsite Radiological Emergency Preparedness Prompt Alert & Notification Sys Evaluation " Sys adequate to alert & notify public in event of accident SPECK, S W Federal Emergency Management Agency 84/01/31, DIRCKS W J Office of the Executive Director for Operations 1: 22487 314 24X Fiche 50-206,84/01/31,8403050148
- --8403080172 "Evaluation of Southern California Edison Site-Specific Offsite Radiological Emergency Preparedness Prompt Alert & Notification Sys "
 * Federal Emergency Management Agency. 84/01/05 61pp 22487 315 24X Fiche 50-206.84/01/31,8403050148
- 8403130031 Revs to emergency plan implementing procedures including EPIP S0123-VIII-0 202: "Assignment of Emergency Response Personnel" & B023-VIII-1; "Recognition & Classification of Emergencies " W/840227 ltr BENNETT.D D. PEACOR.D H., CROY.P A Bouthern California Edison Co 84/02/15 68pp 22643 207 24X Fiche 50-206,84/02/15,8403150031
- B402230176 Forwards revised State of CA nuclear power plant emergency response plan MEDFORD.M O Southern California Edison Co 84/02/16 E16EN-MUT.D G Division of Licensing. 2703pp. 22353 001 24X Fiche 50-000:84/02/16.8402230176
- --8403020117 Revised State of CA nuclear power plant emergency response plan * California, State of 83/04/30 2901pp 22353,003 24X Fiche 50-000,84/02/16,8402230176
- 8403050127 Forwards examption from 10CFR50, App E. Bection IV. F. 1 re requirement for state & local participation in annual emergency plan exercise scheduled for 840229 EISENHUT, D. 0 Division of Licensing 84/02/29 BASKIN, K.P. Bouthern California Edison Co. 3pp 22489 165 24X Fiche 50-206.84/02/29,8403050127
- --8493050132 Exemption from 10CFR50. App E. Section IV F 1 re-requirement for state & local participation in annual emergency plan exercise scheduled for 840229 MIRAOLIA.F J Division of Licensing 84/02/27. Southern California Edison Co 3pp 22489 168 24X Fiche, 50-206, 84/02/29, 8403050127
- 8403120184 Forwards IE Safeguards Insp Repts 50-361/84-03 & 50-362/84-03 on 840124-25 No noncompliance noted NORDERHAUG.L R Region 5. Office of Director 84/03/06 MCCARTHY.C B Sauthern California Edison Co 2pp 22586,255. 24X Fichs 50-361,84/03/06,8403120184
- --B403120185 IE Safeguards Insp Repts 50-361/84-03 & 50-362/84-03 on 840124-25 No noncompliance or deviations noted Major areas inspected organization, operation, shipping & receiving &
- 8403270256 Forwards Rev 12 to physical security plan Rev withheld (ref 100FR73 21) HAVNEB, J G. Bouthern California Edison Go 84/03/07 MARTIN, J. E Region 5. Diffice of Director 2pp 22772 031 24X Fiche 50-206.84/03/07.8403270256
- 8403200097 Informs that emergency operations facility HVAC control logic mod & procedures necessary to implement HVAC isolation completed prior to 840229 commitment date MEDFORD.N O Southern California Edison Co 84/03/14 EISENHUT.D O Division of Licensing 1p 22699 095 24X Fiche 50-206.84/03/14.8403200097
- 8403220018 Forwards "Updated Fire Hazards Analysis, Vols 1-4."

 BABKIN, K P Southern California Edison Co 84/03/19 DENTON, H R
 Office of Nuclear Reactor Regulation, Director. 10pp 22735:238

 24X Fichs 50-206, 84/03/19, 8403220018
- --8403220027 "Updated Fire Hazards Analysis: Vols 1-4 "
 # Southern California Edison Co 84/03/19 1178pp 22735:341.
 24X Fiche 50-206:84/03/19:8403220018
- 8403270205 Discusses Southern California Edison submittal of 1983 revised State of CA emergency response plan on behalf of all State of CA plants, incorporating plan into Diablo Canyon Addl planning info will not be developed for Humboldt Bay. SCHUYLER, J O Pacific Qas & Electric Co. 84/03/22 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p 22772.137, 24% Fiche 50-000, 84/03/22, 8403270205.

H. General correspondence

B403160063 Requests that HB Stockr be removed from distribution list & that L Sernath be added HULBEY. B A San Diego Cas & Electric Co 84/03/12. EISENHUT, D G Division of Licensing ip 22655 083 24X Fichs 50-206,84/03/12.

J Insurance & indemnity information

8403060375 Forwards Endorsements 100 & 88 to NELIA Policy NF-146 & MAELU Policy NF-38, respectively ROCCO, J Bouthern California Edison Co 84/02/29 DINITZ, I Défice of Nuclear Reactor Regulation, Director 3pp 22518 152 24X Fiche. 50-206, 84/02/29, 8403060375

P. Operating license stage documents & correspondence

- 8403010117 Partial response to FOIA request for documents by named individuals re repts, analyses, studies, procedures & sys for measurement of RCS leakage App 8 documents placed in PDR App A documents already available in PDR, Search continuing FELTON, J M Division of Rules and Records 84/01/25 MADDEN, T J. Kaye, 8choler, Fierman, Hays & Handler 7pp 22480 026 24X Fiche: 50-000, 84/01/25, 8403010117
- --8403010233 Discusses RCS leak rate calculations,per 820504 telcon Mods to RCSLK7 computer program permit leak rate calculations for pressures between 1,700 & 2,100 psig w/temp between 260 F & 270 F Plant data encl MCRRILL,P J. Region 5, Office of Director 82/05/05. MCODRUFF,R.W. Reactor Engineering Branch 17pp 22481 362 24X Fichs 50-000,84/01/25,8403010117
- 8403020092 Application for amend to Licanses NPF-10 & NPF-15, changing Tech Spec Table 3 3-2. "Reactor Protective Instrumentation Response Times," to incorporate penalty factor MEDFORD.M O Southern California Edison Co 84/02/29 KNIGHTON.O H. Licansing Branch 3. 7pp. 22442 299. 24X Fiche: 50-361.84/02/24:8403020072
- ---8403020098 Proposed Tech Specs, changing Table 3 3-2, "Reactor Protective Instrumentation Response Times." # Southern California Edison Co 84/02/29, 15pp 22442 306 24X Fiche. 30-361, 84/02/29, 8403020092
- 8403020335 "Evaluation of Natural Circulation Cooldown Test Performed at San Onofre Nuclear Generating Station."

 * Combustion Engineering, Inc. CEN-259 84/01/31. 134pp. 22439:036 24X Fiche: 50-000, 84/02/27, 8403020333
- 8403040424 Application for amend to Licenses NPF-10 & NPF-15, revising Tech Specs re radiation & radioactive effluent monitoring instrumentation & radiological environ monitoring program HEDEFORD, M.O. Southern California Edison Co. 840/3/02 Office of Nuclear Reactor Regulation, Director. KNIGHTON, O.W. Licensing Branch 3. 3pp. 22507 154. 24X Fiche: 50-361, 84/03/02, 8403060424
- ---8403060427 Proposed Tech Specs revising radiation & radioactive effluent monitoring instrumentation & radiological environ monitoring program + Bouthern California Edison Co. 84/03/02, 256pp. 22507·157 24X Fichs 50-361
- 8403090177 Forwards application for Amend 24 to License NPF-10 & Amend 10 to License NPF-15. Amends revise Tech Spac 4. 8. 1. 1. 2. C re level of insolubles in diesel fuel oil & Section 6 re organizational changes BABKIN, K.P. Southern California Edison Co. 84/03/07 DENTON, H R Office of Nuclear Reactor Regulation, Director. 2pp. 22571.247. 24X Fiche. 50-361.84/03/07.8403090177.
- --8403090227 Application for Amend 10 to License NPF-15, revising Tech Spac 4.8.1.1.2.C to determine operability of diesel generator should diesel fuel oil fail to meet test for insolubles & revising Bection 6 re organization changes.

 BARKIN.K.P. Southern California Edison Co. 84/03/07 10pp 22571:249. 24X Fiche: 50-361,84/03/07.8403090177
- --8403090230 Proposed revs to Tech Spec 4.8 i 1.2 C to determine operability of diesel generator should diesel fuel oil fail to meet test for insolubles & proposed revs to Section 6 re organizational changes.

 # Bouthern California Edison Co. 84/03/07, iippp 22571.259 24X Fiche: 50-361, 84/03/07, 8403090177.

- ~-8403090233 Application for Amend 24 to License NPF-10, revising Tech Spec 4 8 i 1 2 C to determine operability of diesel generator should diesel fuel oil fail to meet test for insolubles & revising Section 6 re organizational changes BABKIN,K P Southern California Edison Co 84/03/07 10pp 22572 014 24X Fiche 50-361, 84/03/07, 8403090177
- --840309023B Proposed revs to Tuch Spec 4 B i 1 2 C to determine operability of diesel generator should diesel fuel oil fail to meet test for insolubles & proposed revs to Bection 6 re organizational changes
 BASKIN.K P Southern California Edison Co 84/03/07 i17pp 22372 024 24X Fiche 50-361.84/03/07.8403090177
- 8403270370 Notification of 840308 meeting w/util in Bethesda, MD to discuss turbing missile probabilities & turbine overspeed protection Tech Spec Agenda encl ROOD: H Licensing Branch 3 84/03/07 KNIGHTON, 0 W Licensing Branch 3 4pp 22787 331 24X Fiche 50-361:84/03/07,8403270370
- 8403270331 Informs that NUREO-0737. Item II K 2 17, "Voiding in RCS During Transients" complete, based on util endorsement of CEN-197, "Effects of Vessel Head Voiding During "KNIOHTON,O W Licensing Branch 3. 84/03/08 BASKIN,K P. Southern California Edison Co HOLCOMBE, J C San Diago Gas & Electric Co 9pp. 22822 220 24X Fiche 50-361,84/03/08,8403290331
- 8403130134 Informs that equipment requiring environ qualification reviewed for potential age-related degradation.per NRC 820830 ltr & replacement schedules incorporated into maint program MEDFORD.M O Southern California Edison Co 84/03/09 KNIGHTON.0 W Licensing Branch 3 ip 22601.023 24X Fiche 50-361.84/03/09.8403130134
- 8403160013 Forwards "Evaluation of Natural Circulation Cooldown Test Performed at Ban Onofre Nuclear Generating Station " Rept provides evaluation of applicability of results to 8t Lucia Unit 2 HILLIAMB.J W Florida Power & Light Co 84/03/13 EISENHUT.D C Division of Licensing ip 22652:179 24X Fiche 50-000.84/03/13, 8403160013
- 8403170345 Forwards clarification of previous responses to NRC Questions 8,9,12 % i3 re discharge piping sys % "EPRI PWR Bafety & Relief Valve Test Program Quide " Info satisfies requirements of TMI Item II. D 1. MEDFORD.M O Southern California Edison Co 84/03/14 MNIOHTON, G W Licensing Branch 3 11pp 22675 079 24X Fichs. 50-361,84/03/14,8403190345
- --9403170351 Rev 1 to "EPRI PHR Safety & Relief Valve Test Program Guide for Application of Valve Test Program Results to Plant-Specific Evaluations " * MPR Associates, Inc. 82/03/31 86pp 22675 090 24X Ficha 50-361,84/03/14,8403190345
- 8403290217 Requests exemption from 10CFR70 24 requiring maint of accidental criticality radiation monitoring sys Evaluations determined potential for criticality for new k spent fuel monexistent based on geometric spacing MEDFORD.M D. Southern California Edison Co. 84/03/27 KNIGHTON.G, W. Licensing Branch 3. 4pp. 22803 284 24X Fiche 50-361,84/03/27,8403290217.
- G Inspection reports: IE Bulletins & correspondence
- B40308040B FDIA request for repts of insp carried out under Condition 2 of Nuclear Energy Liebility policies for facilities, CALBOYAB.C D. Affiliation Not Assigned 84/02/07 Region 5, Office of Director 4pp 22567.341 24X Fithe.50-000.84/02/07, 840308040B
- 8403060025 Forwards IE Insp Repts 50-206/83-28,50-361/83-43 & 50-362/83-42 on 831210-840121 No noncompliance noted BISHOP, T W. Division of Resident Reactor Project & Engineering Programs 84/02/079 BARKIN, K. P. Southern California Edison Co 2pp 22516:285 24X Fiche 50-206.84/02/07,8403060025
- ---B403060029 IE Imap Repts 30-206/83-28,50-361/83-43 & 50-362/83-42 on 831210-840121 No noncompliance or deviations noted Major areas inspected operational safety verification, power accession transient testing & maint activities.

 CHAFFEE,A E , STEWART, J. P , D'ANGELO, A Region 5, Office of Director 84/02/07 13pp. 22516-287 24X Fiche 50-206,84/02/09,8403060025
- 8403060008 Forwards IE Insp Repts 50-206/84-02, 30-361/84-02 & 30-362/84-02 on 840115-20. No noncompliance noted MENBLAWSKI, F.A. Region 5. Office of Director 84/02/16. BASKIN, K. B. Southern California Edizon Co. 2pp 22516 268 24X Fichs: 50-206, 84/02/16, 8403060008

- --8403060019 IE Insp Repts SC-206/84-02.50-361/84-02 & 50-362/84-02 on 840115-20 No noncompliance or deviations noted Major areas inspected radiation protection program.health physics & chemistry training & general employee training SHERMAN,C I , MEMSLAMSKI,F A Region 5. Office of Director 84/02/15 | 15pp | 22316-270 | 24X Fiche 50-206.84/02/16.840306000B
- 8403080419 Responds to FOIA request for repts of insp carried out under Condition 2 to Nuclear Energy Liability policies for facilities NRC does not have repts FELTON.J M Division of Rules and Records 84/02/22 CALSOYAS.C D Affiliation Not Assigned 1p 22567 345 24K Fiche 50-000.84/02/22.8403080419
- B401190072 IE Info Notice B4-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Bvc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) B4/02/28 Consolidated Edison Co of New York, Inc 115pp 22707 237 24X Fichs 50-000,84/02/28.8401190072
- 8403190367 Forwards IE Insp Repts 50-206/84-04.50-361/84-05 & 50-362/84-03 on 840123-27 No noncompliance noted. WENSLAMBKI.F A Region 5. Office of Director 84/03/01 BASKIN,K B Southern California Edison Co 2pp 22673 220 24X Fiche 50-204.84/03/01.8403190367
- --8403170373 IE Insp Repts 50-206/84-04.50-361/84-05 & 50-362/84-05 on 840123-27 No noncompliance noted Major areas inspected radiological environ monitoring program & followup on licensee action re previous insp findings YUNAS.6 P. WENELAHSKI.F A Region 5. Diffice of Director 84/03/01 6pp 22675.222 24X Fiche 50-206.84/03/01.8403190367
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE. J N Division of OA. Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000,84/03/02,8402090007
- 8402070008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Bys Valves to Operate " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidate Edison Co of New York. Inc 122pp 2253 098 24X Fiche 50-000.84/03/02.8402070008
- B402090009 IE info Notice B4-15. "Reporting of Radiological Releases " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 119pp 22553 217 24X Fishe 50-000,84/03/02,8402090009
- 8402070011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductifity Temp " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fishe 50-000.84/03/05,8402070011
- 8403120184 Forwards IE Safaguards Insp Repts 50-361/84-03 & 30-362/84-03 on 840124-25 No noncompliance noted. NCRDERHAUG.L R Region 5. Office of Director 84/03/06 NCCARTHY.C B Southern California Edison Co 2pp 22586 255 24X Fiche 50-361.84/03/06.8403120184
- --8403120185 IE Safeguards Insp Repts 50-361/84-03 & 50-362/84-03 on 840124-25 No noncompliance or deviations noted Major areas inspected organization, operation, shipping & receiving & records & repts, Details withheld (ref 10CFR2 790).
 HIEDER: A. V. NORDERHAUG, L. Region 5, Office of Director 84/03/05 1p. 22586-257 24X Fiche 50-361.84/03/06,8403120184.
- 8402090024 IE Info Notice 84-09.Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Syc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 G49 24% Fiche 50-000.84/03/07,8402090024
- 8402070028 IE Info Notice 84-18, "Stress Corrosion Crecking in PMR Sys." Sve list encl JCRDANNE L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc. 118pp. 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8403090127 Responds to IE Bullatin 83-08 re electrical circuit breakers w/undervoltage trip feature used in applications other than reactor trip sys No circuit breakers utilized in safety-related applications Bulletin inapplicable.
 MEDFORD-M O Southern California Edison Co 84/03/07 MARTIN.J B Region 5. Office of Director 1p 22575 340 24X Fiche 50-361.84/03/07.8403090127

- B402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list ancl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823-094. 24X Fiche 50-000.84/03/12.8402090031
- 8402070043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PHR Reactor Cavities" Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidate Edison Co of New York, Inc. 123pp 22823 229 24X Fiche 50-000,84/03/21,8402070043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Bys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103), 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22733 001 24X Fiche 50-000,84/03/21,8402090044
- 8403230118 Responds to Items 1 & 4 of IE Bulletin 83-07, "Apparently Fraudulent Products Bold by Ray Miller.Inc." No evidence found to indicate that any vendor matts provided to or used at facilities KRIEGER.R W Southern California Edison Co 84/03/21 MARTIN.J B Region 3, Diffice of Director 2pp 22730 159 24X Fiche 50-361.84/03/21.8403230118
- R Periodic operating reports & related correspondence
- 8403060438 "Annual Personnel Monitoring Rept, 1983 " W/840229 1tr HAYNES, J G Southern California Edison Co 83/12/31 4pp 22511 189 24X Fiche 50-206, 83/12/31, 8403060438
- 8403020010 Monthly operating repts for Jan 1984, W/840215 ltr MORRIB.C A , HAYNEB.J Q Bouthern California Edison Co 84/01/31 12pp 22442 223 24X Fiche 50-341, 84/01/31, 8403020010
- 8403020040 Forwards auxiliary feedwater sys monthly outage rept for 831216-840115, per License Condition 2 C(26) MEDFORD.M D Bouthern California Edison Co 84/02/27, KNICHTON. & W. Licensing Branch 3 3pp 22442 267 24X Fiche 50-361.84/02/29.8403020040
- B403200053 Forwards monthly operating repts for Feb 1984 & revised monthly operating repts for Aug 1983 Jan 1984. Revs reflect values reserved from beginning of commercial operation, per NUREG-0020.

 HAYNEG, J O Southern California Edison Co B4/03/15 Office of Resource Management. Director 1p 22685 001 24X Fishe 50-361.84/03/15.8403200053
- --B403200057 Monthly operating repts for Feb 1984 MORRIS, C A Bouthern California Edison Co B4/02/29 10pp. 22685 002 24X Fiche 50-361,84/03/15,8403200053
- --B403200074 Revised monthly operating repts for Jan 1984. MORRIS.C A Southern California Edison Co. 84/01/31. 4pp 22685 012 24X Fiche 50-361,84/03/15,8403200053
- --8403200077 Revised monthly operating rept for Dec 1983 MORRIS, C A Southern California Edison Co 83/12/31 3pp. 22685 016 24X Fiche:50-361,84/03/15,8403200053
- --8403200082 Revised monthly operating rept for Nov 1983 MORRIS.C A Bouthern California Edison Co 83/11/30 3pp 22685 019 24X Fiche 50~361,84/03/15,8403200053
- --8403200086 Revised monthly operating rept for Oct 1983. MORRIS, C A Southern California Edison Co 83/10/31 3pp 22685 022 24X Fichs. 50-361,84/03/15,8403200053
- --8403200088 Revised monthly operating rept for Sept 1983 HORRIS, C A Southern California Edison Co 83/09/30. 3pp 22485 025 24X Fiche 50-341,84/03/15,8403200053
- --8403200091 Revised monthly operating rept for Aug 1783 MORRIS, C A Southern California Edison Co 83/08/31, 3pp. 22685-028 24% Fiche 50-361,84/03/15,8403200053,
- B403230074 Forwards auxiliary feedwater sys monthly outage rept for B40116-0215.including B40112.14 & 15 outages.omitted from last months rept, per License Condition 2, C(26) Next rept will cover period 840216-0315.
 MEDFORD, M O Southern California Edison Co. 84/03/20 KNIGHTON, O W Licensing Branch 3 3pp 22726-330 24X Fiche 50-361:84/03/20,8403230074

- S Reportable occurrences, LERs & related correspondence
- 8212010501 Discusses 820314 loss of shutdown cooling when low pressure safety injection (LPSI) pumps became nitrogen bound IE info notice re gas binding of LPSI pumps while backflushing purification filter should be issued CINTULA, T C Reactor Operations Analysis Branch 82/11/24 BEYFRIT, K V Reactor Operations Analysis Branch 9pp 22775 238 24% Fiche 50-361,82/11/24,8212010501
- 8403010451 Informs Commission of problems w/emergency diesel generators mfg by Transamerica Delaval. Inc DIRCKB.W.J Office of the Executive Director for Operations SECY-83-034 84/01/25 4pp 22438 347 24X Fiche 50-000.84/01/25.8403010451
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines. Gimpel NPS-4 T&T valve to close Encl ltr d&d 840203 sent to listed utils. GE notified of affected units in BWR plants
 THERDUX.R R Terry Corp 84/02/22 WOODRUFF.R W Director's Office, Office of Inspection and Enforcement 6pp 22706 327 24X Fichs 50-000.84/02/22.8403210032
- 8403150074 Revised special rept.on 830712. Channels 1.7 % 12 discovered inoperable during 31-day channel functional testing per Surveillance Procedure 8028-II i 13 Gaused by sensor probes becoming detached from reactor vessel bottom HAYNES. J 0 Southern California Edison Co 84/02/23 MARTIN, J B Region 5. Office of Director 2pp 22641 049 24X Fiche. 50-361, 84/02/23, 8403150074
- 8403050003 LER 84-002-00 on 840130-0203, containment purge isolation system spuriously actuated Caused by electrical noise spike on train 8 containment sirborne monitor 2RT7807 Use of addl suppression circuit being investigated W/840228 ltr HAYNES, J 9 Southern California Edison Co 84/02/28 3pp 22490 237 24X Fiche 50-361,84/02/28,84030500003
- 8403060378 LER 84-006-00 on 840103, spurious toxic gas isolation sys actuations occurred Caused by toxic gas isolation sys setpoint set at threshold level of detection Tech Specs revised to raise setpoint raquirements. H/840228 ltr HAYNEB, J G Southern California Edison Co 84/02/28 3pp 22511,327. 24% Fichs. 50-361,84/02/28,8403060378
- 8403060403 LER 84-001-00, on 840111, preparation of updated fire hazards analysis resulted in 91 nonconformance repts (NCR) re fire protection program deficiencies Compensatory measures established NCR dispositions planned W/840228 ltr HAYNEB, J Q Bouthern California Edison Co 84/02/28 9pp 22518, 283 24X Fichs 50-361, 84/02/28, 8403060403
- 8403150033 LER 83-143/09L-0 on 830316, snubber on 8-inch demineralized water makeup & transfer line between condensate storage tanks discovered frozen Caused by internal damage, Snubber replaced on 840328 W/840228 ltr.

 HAYNES, J O Southern California Edison Co 84/02/28 MARTIN, J B Region 5, Office of Director, App 22641 006 24X Ficher 50-361, 84/02/28, 8403150033.
- 8403060215 PNO-V-84-011 on 840221, reactor trip breaker 8 undervoltage device inoperable Caused by metal shavings in one control room manual reactor trip pushbutton. On 840228, four leads in plant protection sys cabinets found disconnected CANTER, H Region 5, Office of Director. 84/02/29 ip. 22517 230 24% Fiche.50-361,84/02/29,8403060215
- 8403150057 LER 84-005-00 on 840127, while in Mode 5, w/purge/vent stack wide-range monitor GRY-7865 & flow rate monitor out of syc for installation of noise suppression circuit, flow rate estimates not performed as required W/840301 ltr HAYNES, J Q. Southern California Edison Co 84/03/01 3pp 22641:359 24X Fiche. 50-361,84/03/01,8403150057
- 8403120063 Updated PND-V-84-011A discovered manual pushbutton not inoperable as result of metal shavings in contacts Only operability of undervoltage trip on RTB-8 affected Source of metal flakes undetermined DDDBB,R T. Region 5, Office of Director 84/03/05 1p. 22586 288 24X Fiche. 50-361, 84/03/05, 8403120063.
- 8403120064 LER 84-007-00 on 840203 & OA, Train A & B main steam isolation sys spuriously actuated on low pressure signal from E-088 Caused by voltage fluctuation resulting from electrical realignments testing & maint W/840305 ltr MAYNEB, J G. Bouthern California Edison Co 84/03/05. Spp 22586, 267 24X Fiche 50-361, 84/03/05, 8403120064

- B403190376 PNS-V-84-004 on B40314, licensee notified that results of chemical tests performed on contractor employees suspected of possession or use of controlled substances while onsite indicated positive in two of four tests SCHHAN, C A, NORDERHAUG, L R Region 3, Office of Director 84/03/15 ip 22675 218 24X Fiche 50-206, B4/03/15, 8403190376
- 8403200194 LER 84-009-00 on 840214 analysis of startup test data established calculated thermal power calculated by core protection calculators may become decalibr relative to secondary calorimetric power Procedure changed W/B40315 ltr HAYNES, J G Southern California Edison Co 84/03/13 3pp 22686 336 24X Fiche 30-36184/03/13.8403200194
- 8403270219 Part 21 rept re broken contact carrier in control device of 7 5 kV-15 kV,500-750 MVA,5 kV 350-3,000 & all HKV circuit breakers Initially reported on B30223 Addenda to installation & maint procedures sent to affected units DUVALL,D D Srown Boveri Corp (subs. of Brown Boveri & Co , Ltd) 84/03/19 Record Services Branch (Document Control Desk) 5pp 22772 114 24X Fiche 50-000,84/03/19,8403270219
- 8403280002 LER 84-011-00 on 840225, containment purge isolation sys actuated when containment airborne monitor 2RE-7804 gaseous Channel C failed Caused by water in gaseous detector cell, short circuiting pre-amp Water removed W/840322 ltr HAYNES, J G Bouthern California Edison Co 84/03/22 3pp 22777 152 24X Fiche 50-361,84/03/22,8403280002
- X Onsite Storage of Low Level Waste
- 8403040343 Forwards program description for waste classification & form to be used to implement 100FR41 & 100FR20 311 requirements re land disposal of radwaste & stds for protection from radiation MEDFORD, M O Southern California Edison Co 84/03/02 EISENHUT, D G Division of Licensing 8pp 22518 207 24X Fiche 50-206, 84/03/02, 8403060363
- DOCKET 50-342 SAN ONOFRE NUCLEAR STATION, UNIT 3
- F. Becurity, medical, emergency & fire protection plans
- 840203033B Forwards revised "Emergency Plan Implementing Procedures. San Onofre Nuclear Generating Station, Units 1,2 & 3 " CROY, P A Guthern California Edison Co 84/01/27 NRC - No Datailed Affiliation Given 1p 22064 013 24X Fiche 50-206,84/01/27,8402030338
- --8402030344 Revised "Emergency Plan Implementing Procedures, San Onofre Nuclear Generating Station, Units 1/2 & 3 " ANDERSON, C K , PATRISSI, G A Southern California Edison Co 84/01/27 525pp 22064 015 24X Fiche 50-206,84/01/27, 8402030338
- 8403050148 Forwards "Evaulation of Southern California Edison Site-Specific Offsite Radiological Emergency Preparedness Prompt Alert & Notification Sys Evaluation "Sys adequate to alert & notify public in event of accident SPECK.S W Federal Emergency Management Agency. 84/01/31 DIRCKS, W J Office of the Executive Director for Operations 1p 22487:314 24X Fiche 50-206,84/01/31,8403050148
- --8403050172 "Evaluation of Southern California Edison Sits-Specific Offsite Radiological Emergency Preparedness Prompt Alert & Notification Sys " * Federal Emergency Management Agency 84/01/05 61pp 22487 315 24X Fiche 50-206/84/01/31/8403050148
- B403150031 Revs to emergency plan implementing procedures, including EPIP B0123-VIII-0 202, "Assignment of Emergency Response Personnel" & 9023-VIII-1, "Recognition & Classification of Emergencies " W/B40227 ltr BENNETT, D D., PEACOR, D H., CROY, P A. Bouthern California Edison Co B4/02/15 48pp. 22443 207 24X Fiche 50-204,84/02/15,8403150031
- 8402230174 Forwards revised State of CA nuclear power plant emergency response plan MEDFORD, M.O. Southern California Edison Co. 84/02/16 EISENHUT, D.G. Division of Licensing 2903pp. 22383 001 24X Fiche 50-000,84/02/16.8402230174
- --8403020117 Revised State of CA nuclear power plant emergency response plan * California, State of 83/04/30 2701pp 22353 003 24X Fiche 50-000,84/02/16,8402230176

- 8403030127 Forwards exemption from IOCFR30, App E.Section IV F I re requirement for state & local participation in annual smergency plan exercise scheduled for 840229 EISENHUT, D 0 Division of Licensing 84/02/29 BASKIN. K P Bouthern California Edison Co 3pp 22489 165 24x Fiche 50-206,84/02/29,8403050127
- --8403050132 Exemption from 19CFR50. App E. Section IV F 1 re requirement for state & local participation in annual emergency plan exercise scheduled for 840229 MRAQLIA.F J Division of Licensing 84/02/29 Southern California Edison Co 3pp 22489 168 24x Fiche 50-206.84/02/29. 8403090127
- 8403120194 Forwards IE Safeguards Insp Repts 50-361/84-03 & 50-362/84-03 on 840124-25 No noncompliance noted NGRDERHAUG. R Region 5, Office of Director 84/03/06 NGCARTHY.C B Bouthern California Edison Co 2pp 22586 255 24X Fichs 50-361,84/03/06,8403120184
- --8403120385 IE Safeguards Inep Repts 50-361/84-03 & 50-362/84-03 on 840124-25 No noncompliance or deviations noted Major areas inspected organization, operation, shipping & receiving & records & repts Details withheld (ref 10CFR2 790)
 WIEDER, A V Region 5, Office of Director 84/03/05 ip 22586 257 24X Fiche 50-361,84/03/06,8403120184
- B403270256 Forwards Rev 12 to physical security plan Rev withheld (ref 10CFR73 21)
 HAYNES, J G Southern California Edison Co B4/03/07 MARTIN, J B
 Region 5. Dffite of Director 2pp 22772 031. 24X
 Fithe 50-206/84/03/07/8403270256
- 8403200097 Informs that emergency operations facility HVAC control logic mod & procedures necessary to implement HVAC isolation completed prior to 840229 commitment date MEDFORD, M O Southern California Edison Co 84/03/14 EISENHUT. D O Division of Licensing Ip 22699 095 24X Fiche 50-206,84/03/14.8403200097
- 8403220018 Forwards "Updated Fire Hexards Analysis, Vols 1-4" BABKIN, K.P. Southern California Edison Co. B4/03/19 DENIGN, H.R. Office of Nuclear Reactor Regulation, Director 10pp 22735 238 24X Fiche 50-206, 84/03/19, 8403220018
- --8403220027 "Updated Fire Herards Analysis, Vols 1-4" * Bouthern California Edison Co. 84/03/19 1178pp 22735 341 24% Fiche 50-206, 84/03/19, 8403220018
- 8403270205 Discusses Southern California Edison submittal of 1983 revised State of CA emergency response plan on behalf of all State of CA plants, incorporating plan into Diablo Canyon Addl planning info will not be developed for Humboldt Bay SCHUYLER, J O Pacific Oas & Electric Co 84/03/22 DENTON, H R Office of Nuclear Reactor Regulation, Director ip 22772 137 24% Fiche. 50-000. 84/03/22, 8403270205

H General correspondence

- 8403140063 Requests that HB Stockr be removed from distribution list & that L Bernath be added HULSEY.S A San Diego Gas & Electric Co 84/03/12 EISENHUT, D G Division of Licensing 1p 22655 083 24X Fiche 50-206,84/03/12,8403160063
 - Insurance & indemnity information
- 1403040395 Forwards Endorsements 100 & 88 to NELIA Policy NF-146 & MAELU Policy MF-38, respectively ROCCO.J Southern California Edison Co 84/02/29 DINITZ. I Office of Nuclear Reactor Regulation, Director 3pp 22518 152 24% Fiche 50-204.84/02/29,8403060395
- Operating license stage documents & correspondence
- 403010117 Partial response to FOIA request for documents by named individuals re repts.analyses.studies.procedures & sys for measurement of RGB leakage App B documents placed in PDR App A documents already available in PDR Search continuing FELTON.J M Division of Rules and Records 84/01/25 MADDEN.T J Kaye, Scholer, Fierman, Hays & Handler 7pp 22480 026 24X Fiche 50-000.84/01/25.8403010117
- -8403010233 Discusses RCS leak rate calculations per \$20504 telcon Mods to RCSLK7 computer program permit leak rate calculations for pressures between 1,700 % 2,100 psig w/tamp between 260 F % 270 F Plant data enci MDRRILL.F J Region 5, Office of Director 82/05/05 WDODRUFF.R W Reactor Engineering Branch 17pp 22481 362 24X Fiche 50-009,84/01/25,8403010117

- B403020072 Application for amend to Licenses NPF-10 & NPF-15, changing Tech Spec Table 3 3-2, "Reactor Protective Instrumentation Response Times," to incorporate penalty factor MEDFORD, M O Bouthern California Edison Co 84/02/29 XNIGHTON, O W Licensing Branch 3 7pp 22442 299 24X Fische 50-361, 84/02/29, 8403020072
- --8403020098 Proposed Tech Specs, changing Table 3 3-2, "Reactor Protective Instrumentation Response Times" # Southern California Edison Co 84/02/29 15pp 22442 306 24X Fiche 50-361.84/02/29,8403020092
- 8403060424 Application for amend to Litenses NPF-10 & NPF-15, revising Tech Specs to radiation & radioactive effluent monitoring instrumentation & radiological snviron monitoring program MEDFORD, M O. Bouthern California Edison Co 84/03/02 Office of Nuclear Reactor Regulation, Director KN10HTON, O W Licensing Branch 3 3pp 22507 154 24X Fiche 30-361.84/03/02.8403060424
- --8403060427 Proposed Tech Specs revising radiation & radioactive effluent monitoring instrumentation & radiological environ monitoring program * Bouthern California Edison Co 84/03/02 256pp 22507.157 24X Fiche 50-361.84/03/02.8403060424
- 8403070177 Forwards application for Amend 24 to License NPF-10 & Amend 10 to License NPF-15. Amends revise Tech Spec 4.8 1 i 2 C re level of insolubles in diesel fuel oil & Bection 6 re organizational changes BASKIN: K P Bouthern California Edison Co 84/03/07. DENTON: H R Office of Nuclear Reactor Regulation: Director 2pp 22571:247, 24X Fiche 50-361.84/03/07. 8403090177
- --8403090227 Application for Amend 10 to License NPF-15, revising Tech Spec 4 B : 1 2 C to determine operability of dissel generator should dissel furl oil fail to meet test for insolubles & revising Section 6 re organization changes BASKIN.K P Southern California Edison Co 84/03/07 10pp 22571 R49 24X Fiche: 50-361,84/03/07,8403090177.
- --B403090230 Proposed ravs to Tech Spec 4 B 1 1 2 C to determine operability of diexal generator should diexal fuel oil fail to meet test for insolubles & proposed ravs to Section 6 re organizational changes # Southern California Edison Co 84/03/07 115pp 22571 259 24X Fichs 50-361,84/03/07,8403090177
- 8403270370 Notification of B40308 meeting w/util in Bethesda.MD to discuss turbine missile probabilities & turbine overspeed protection Tech Spec. Agenda encl RODD.H & Licensing Branch 3 84/03/07 KNIGHTON, G W Licensing Branch 3 4pp 22787 331 24X Fiche 50-361,84/03/07,8403270370
- 8403290331 Informs that NUREQ-0737. Item II K 2.17. "Voiding in RCB During Transients" complete, based on util andorsement of CEN-199. "Effects of Vessel Head Voiding During."

 CEN-199. "Effects of Vessel Head Voiding During."

 SHOHTON, O W Licensing Branch 3 84/03/08 BASKIN, K P. Southern California Edison Co HOLCOMBE. J. C San Diego Qas & Electric Co. 9pp 22822 220 24% Fiche 50-361.84/03/08.8403290331
- 8403:30134 Informs that equipment requiring environ qualification reviewed for potential age-related degradation.per NRC 820830 ltr & replacement schedules incorporated into maint program MEDFORD.M O Southern California Edison Co 84/03/09 KNIGHTON.O W Licensing Branch 3 1p 22601 023 24X Fiche 50-361.84/03/09,8403:30134
- 8403160013 Forwards "Evaluation of Natural Circulation Cooldown Test Performed at San Unoffe Nuclear Generating Station " Rept provides evaluation of applicability of results to St Lucie Unit 2

 WILLIAMS, J.W. Florida Power & Light Co. 84/03/13 EISENHUT, D.O. Division of Licensing ip 22652 179 24X Fiche 50-000, 84/03/13, 8403140013
- 8403190345 Forwards clarification of previous responses to NRC Questions 8,9,12 & 13 re discharge piping sys & "EPRI PWR Bafety & Reliaf Valve Test Program Guide " Info satisfies requirements of TMI Item II D : MEDFORD, M O Southern California Edison Co. 84/03/14 KNIGHTON,0 W Licensing Branch 3 11pp. 22675-079, 24X Fiche 50-361,84/03/14,8403190345.
- B403290217 Requests exemption from 10CFR70 24 requiring maint of accidental criticality radiation monitoring sys. Evaluations determined potential for criticality for new & spent fuel nonexistent, based on geometric spacing.

 MEDFORD.N D Bouthern California Edison Co 84/03/27.

 KNIOHTON, O. W. Licensing Rranch 3 4pp. 22803 284 24X

 Fiche 50-361,84/03/27,8403290217

- 0 Inspection reports, IE Builetins & correspondence
- 8403080408 FOIA request for repts of insp carried out under Condition 2 of Nuclear Energy Liability policies for facilities CALSOVAS:C D Affiliation Not Assigned 84/02/07 Region 5, Office of Director 4pp 22567 341 24X Fiche 50-000,84/02/07,8403080408.
- 8403040025 Forwards IE Insp Repts 50-204/83-28, 50-361/83-43 & 50-362/83-42 on 831210-840121 No noncompliance noted BISHOP.T W Division of Resident Reactor Project & Engineering Programs 84/02/09 BABKIN.K P Southern Callfornia Edison Co 2pp. 22516-285 24X Fiche 50-206.84/02/09,8403060025
- ---B403060027 IE Insp Repts 50-206/83-28,50-361/83-43 & 50-362/83-42 on 831210-840121, No noncompliance or deviations noted Major areas inspected operational safety verification, power ascension transient testing & maint activities CHAFFEE, A E , BTEWART, J P , D'ANGELO, A Region 5, Office of Director 84/02/07 13pp 22516 287 24X Fiche 50-206,84/02/09,8403060025
- --8403060019 IE Insp Repts 50-204/84-02, 50-361/84-02 & 50-362/84-02 on 840115-20 No noncompliance or deviations noted Major areas inspected radiation protection program, health physics & chemistry training & general employee training BHERMAN, C. I., WENBLAMBKI, F.A. Region 5. Office of Director 84/02/15, 15pp 22516, 270 24% Fiche 50-206, 84/02/16, 8403060008
- 8403080419 Responds to FOIA request for repts of insp carried out under Condition 2 to Nuclear Energy Liability policies for facilities NRC does not have repts FELTONIJ, M. Division of Rules and Records 84/02/22 CALSOYAS, C.D. Affiliation Not Assigned 1p 22367 345 24X Fiche 50-000,84/02/22,8403080419
- 8401170072 IE Info Notice 84-13, "Potential Deficiency in Mater Operated Valve Control Circuits & Annunciation " Svc list enc!

 JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103), 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22707 237 24X Fiche 50-000.84/02/28,8401190072
- 8403190367 Forwards IE Insp Repts 50-206/84-04.50-361/84-05 & 50-362/84-05 on 840123-27 No noncompliance noted MEMSLAMBKI.F A. Region 5. Office of Director 84/03/01 BABKIN.K B Bouthern California Edison Co 2pp 22675 220 24X Fiche 50-206.84/03/01.8403190367
- ---8403190373 IE Insp Repts 50-206/84-04, 50-361/84-05 & 50-362/84-05 on 840123-27 No noncompliance noted Major areas inspected radiological environ monitoring program & followup on licensee action re-previous insp findings YUHAB.0 P , WENSLAWSKI,F A Region 5, Office of Director 84/03/01 6pp 22675:222 24X Fichs 50-206,84/03/01,8403190367
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDY & NRC." Svc list encl GRACE.JN. Division of QA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc 130pp. 22552 329 24X Ficher 50-000/84/03/02,8402090007.
- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate." Svc list encl.

 JORDAN: E L Division of Emergency Preparedness & Engineering Response (Post 830103) "84/03/02 Consolidated Edison Co of New York. Inc 122pp 22553:098 24X Fiche: 50-000:84/03/02.8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases "
 Bvc list encl.
 JURDAN, E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc 119pp. 22553 217 24X Fiche. 50-000, 84/03/02, 8402090009
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JURDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103), 84/03/05 Consolidated Edison Co. of New York, Inc. 117pp 22553 336 24X Fiche: 50-000, 84/03/05, 8402090011
- 8403120184 Forwards IE Bafeguards Insp Repts 50-361/84-03 & 50-362/84-03 on 840124-25 No noncompliance noted NORDERHAUO, L. R. Region 5. Office of Director 84/03/06 MCCARTHY.C. B. Bouthern California Edison Co 2pp 22586, 255 24X Fiche: 50-361, 84/03/06, 8403120184.

- --8403120185 IE Safeguards Insp Repts 50-361/84-03 & 50-362/84-03 on 840124-25 No noncompliance or deviations noted Major areas inspected organization operation shipping & receiving & records & repts Details withheld (ref 10CFR2 790) HIEDER, A V , NORDERHAUG, L Region 5. Office of Director 84/03/05 ip 22586 257 24X Fiche 50-361/84/03/06.8403120184
- 8402090024 IE Info Natice 84-09. Rev 1. "Lessons Learned From Insps of Fire Protection Bafe Shutdown Sys " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York Inc liBpp 22635 049 24X Fiche 50-000:84/03/07.8402090024
- 8402070028 IE Info Notice 84-18. "Stress Corresion Cracking in PWR 8ys " Syc list enc1 JORDAN, E L Division of Emergency Preparadness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fichs 50-000.84/03/07.8402070028
- 8403090127 Responds to IE Bulletin 83-08 re electrical circuit breakers w/undervoltage trip feature used in applications other than reactor trip sys No circuit breakers utilized in safety-related applications Bulletin inapplicable MEDFORD.M O Southern California Edison Co 84/03/07 MARTIN, J B Region 5, Office of Director ip 22575 340 24X Fiche 50-361.84/03/07.8403090127
- 8402090031 IE Bulletin 84-02, "Failures of QE Type HFA Relays in Use in Class IE Safety Sys." Syc list encl
 DEYQUNQ.R C Director's Office. Office of Inspection and Enforcement Br403/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24% Fiche 50-000.84/03/12,8402090031
- 8402090043 IE Infa Notice 84-19, "Two Events Involving Unauthorized Entries into PMR Reactor Cavities " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Cansolidated Edison Co. of New York, Inc. 123pp 22823 229 24X Fiche 50-000.84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related 8ys " Svc list and JungAhn EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044
- 8403230118 Responds to Items 1 & 4 of IR Bulletin 83-07, "Apparently Fraudulent Products Sold by Ray Miller, Inc " No evidence found to indicate that any vendor matls provided to or used at facilities KRIEGER, R W Southern California Edison Co. 84/03/21 MARTIN, J B Region 5. Defice of Director 2pp 22730 159 24X Fiche 50-361,84/03/21,8403230118
- R Periodic operating reports & related correspondence
- 8403060438 "Annual Personnel Monitoring Rept, 1783 " W/840227 ltr MAYNES, J C Southern California Edison Co 83/12/31 App 22511 189 24X Fiche 50-206, 83/12/31, 8403060438
- 8403020010 Monthly operating repts for Jan 1984 W/840213 ltr MORRIS. C A. HAYNES, J G Southern California Edison Co 84/01/31 12pp. 22442 223 24X Fiche 50-361.84/01/31.8403020010
- B403020040 Forwards auxiliary feedwater sys monthly outage rept for B31216-840115, per License Condition 2 C(26) MEDFORD, M D Southern California Edison Co B4/02/29 KNIOHTON, O W Licensing Branch 3 3pp 22442 269 24X Fiche 50-361,84/02/29,8403020040
- 8403200053 Forwards monthly operating repts for Feb 1984 & revised monthly operating repts for Aug 1983 Jan 1984 Revs reflect values rezeroed from beginning of commercial operation.per NUREQ-0020 HAYNES. J G Southern California Edison Co 84/03/15 Office of Resource Management, Director 1p 22685 001 24% Fiche: 50-361.84/03/15.8403200053
- --8403200057 Monthly operating repts for Feb 1984.
 MORRIB.C A Southern California Edison Co 84/02/29 10pp 22685 002 24% Fiche 50-361,84/03/15,8403200053
- --8403200074 Revised monthly operating repts for Jan 1984 MORRIS.C A Southern California Edison Co 84/01/31 App 22685 012 24X Ficha 50-361,84/03/15,8403200053

- 8403230074 Forwards auriliary feedwater sys monthly outage rept for B40116-0215. including 840112.14 & 15 autages, omitted from last months reptiper License Condition 2 C(26) Next reptivitl tover period 840216-0315 HEDFORD.M D Southern California Edison Co 84/03/20 KNIGHTON.G W Litensing Branch 3 3pp 22726 330 24% Fiche 30~361.84/03/20,8403230074
- S Reportable occurrences, LERs & related correspondence
- 8403010451 Informs Commission of problems w/emergency diesel generators mfg by Transamerica Dalaval, Inc DIRCKS.W J Office of the Executive Director for Operations SECV-83-034 84/01/25 4pp 22438 347 24X Fichs 50-000.84/01/25, 8403010451
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines, Gimpel NPS-4 TMT valve to close Encl 1tr dtd 840203 sent to listed utils GE notified of affected units in BMR plants
 THERRUX.R R Terry Corp 84/02/22 WOODRUFF, R W Director's Office, Office of Inspection and Enforcement 6pp 22706 327 24X Fiche 90-000.84/02/22.8403210032
- 8403060215 PND-V-84-031 on 840221 reactor trip breaker 8 undervoltage device inoperable Caused by metal shavings in one control room manual reactor trip pushbutton On 840228 four leads in plant protection sys cabinets found disconnected CANTER, H Region 5, Office of Director 84/02/29 ip 22517 230 24% Fiche 50-361.84/02/29.8403060215
- 8403200175 Discusses 840217 immediate notification that ESF actuated, per 10CFR50 72(b)(2)(ii) Power supply failure did not result in smargency feedwater actuation sys channel trips No LER rept written, per NUREO-1022

 HAYNES, J G Southern California Edison Co 84/03/12 Record Services Branch (Document Control Desk) 2pp 22699 325 24X

 Fiche 50-362.84/03/12.8403200175
- 8403190374 PNS-V-84-004 on 840314, licensee notified that results of chemical tests performed un contractor employees suspected of possession or use of controlled substances while onsite indicated positive in two of four tests 8CHMAN.C A Region 5, 0ffice of Director 84/03/15 ip 22675 216 24% Fiche 50-206.84/03/15, 8403190376
- 8403270219 Part 21 rept re broken contact carrier in control device of 7 5 kV-15 kV,500-750 MVA:5 kV 390-3,000 & all HKV circuit breaters initially reported on 830223 Addenda to installation & maint procedures sent to affected units DUVALL:D D Brown Boveri Corp (subs of Brown Boveri & Co. Ltd.) 84/03/19 Record Services Branch (Document Control Desk) 5pp 22772 114 24X Fiche 50-000,84/03/19,8403270219
- 8403270164 LER 84-004-00 on 840222; three safety injection pumps started & injected 150 gallons of water into RCE Caused by dirty contacts on relay hold pushbutton Contacts cleaned H/840322 ltr. HAYKES, J D Bouthern California Edison Co 84/03/22 Jpp 22766 025 24x Fiche 50-362,84/03/22,8403270164
- X Onsite Storage of Low Level Waste
- 3403040363 Forwards program description for waste classification & form to be used to implement 10CFR61 & 10CFR20 311 requirements re land disposal of radwaste & stds for protection from radiation
 MEDFORD:N O Southern California Edison Co 84/03/02
 EISENHUT, D 0 Division of Licensing Bpp 22518 207 24X
 Fiche 50-206:84/03/02:8403060363
- DOCKET 50-344 JOSEPH M FARLEY NUCLEAR PLANT, UNIT 2 F Security, medical, emergency & fire protection plans
- 8403140212 Public version of Ray 28 to Emergency Plan Implementing Procedure PNP-O-EIP-OO8, "Syc Bldg Telephone Directory "W/830706 itr & JM Felton 840312 release memo HUBSPETH, J B Alabama Power Co 83/07/01 77pp 22638 157 24X Fiche 50-348,83/07/01.8403140212
- 8403140210 Public version of Rev 4 to Emergency Plan Implementing Procedure GO-EIP-111, "Corporate Activation & Notification Procedures" "W631025 ltr & JM Felton 840312 release memo CLAYTON-F.L. MCGOMAN.J W ALABAMA Power Co 83/10/25, 82pp 22638 237 24X Fiche 50-348.83/10/25,8403140210.

- 8403090303 Public version of duty roster for First Guarter 1984, reflecting nuclear generation dept on call emergency positions & public info site coordination position W/ JM Felton release memo 01850N/M O Alabama Power Co 83/12/22 4pp 22584 342 24X Fiche 50-348,83/12/22,8403090303
- 84032B0198 Public version of 1984 emergency on-call coverage schedules, as part of Emergency Plan Implementing Procedure 90-EIP-111 W/840106 itr & JM Felton release memo ROBERTS R & Alabama Power Co 83/12/29 15pp 22808 228 24X Fiche 50-348,83/12/29,84032B0198
- 8403280107 Public version of temporary change notices for emergency plan implementing procedures, including Procedure GD-EIP-101 re nuclear generation dept corporate emergency operation M/ 840126 ltr & JM Felton 840322 release memo 01B80N.M 0 , HUOD.C H Alabama Power Co 84/01/26 20pp 22812 001 24X Fiche 50-346,84/01/26,8403280109
- 8402130400 Forwards IE Safeguards Insp Repts 50-348/84-02 & 50-364/84-02 on 840116-20 No violations noted VERRELLI.D M Division of Project & Resident Programs 84/02/08 MCDDNALD.R P Alabama Power Co 2pp 22203 251 24X Fiche 50-348,84/02/08,8402130400
- ~-B402130404 IE Safeguards Insp Repts 50-348/84-02 & 50-364/84-02 on B40116-20 No violations noted Major areas inspected security organization, tasting & maint & physical barriers Details withheld (ref 10CFR2 790 & 73 21) MORRE, D. E. Region 2, Dffice of Director B4/02/02 ip 22203 253 24X Fiche 50-348,84/02/08,8402130400
- 8403160142 Forwards IE Insp Repts 50-348/84-01 & 50-364/84-01 on 840118-19 No violations or deviations identified VERRELLI,D M Division of Project & Resident Programs 84/02/15 MCDDNALD,R P Alabama Power Co 2pp 22655 325 24% Fiche 50-348.84/02/15.8403160142
- --8403160146 IE Insp Repts 50-348/84-01 & 50-364/84-01 on 840118-19 No violations or deviations noted Major areas inspected emergency preparedness area of protective action decisionmaking CLINE, W Region 2, Office of Director 84/02/15, 4pp 22695 327 24X Fiche 50-348,84/02/15,8403160142
- B403290019 Forwards IE Insp Repts 50-348/84-04 & 50-364/84-04 on B40131-0202 No violations or deviations noted VERRELLI.D M Division of Project & Resident Programs 84/02/29 MCDDNALD.R P Alabams Power Co 2pp 22806 209 24X Fiche 50-348,84/02/29,8403290019
- --B403290027 IE Insp Repts 50-348/B4-04 & 50-344/B4-04 on 840131-0202 No violations or deviations noted Major areas inspected emergency exercise DECKER.T R. Region 2, Office of Director 84/02/27 7pp 22806 211 24X Fiche 50-348.84/02/29,8403290019
- 8403080077 Forwards add1 fees for applications for fire protection reviews & approvals
 CLAYTON.F L. Alabama Power Co. 84/03/01 MILLER.W.O. License Fee Management Branch ip 22557 257 24X Fiche 50-348,84/03/01.
 8403080077
- 8403160354 Notifies of fire protection workshop on 840316 in Region II ofc to discuss questions he App R requirements & results of recent App R insps
 LEWIS.R C Division of Project & Resident Programs 84/03/02 HCDDNALD.R P Alabama Power Co ip 22660 192 24X Fiche 50-348.84/03/02.8403160354
- 8403280329 Forwards comments on detailed control room design review program plan, per 831031 submittal Plan does not comply fully w/8uppl 1 to NUREQ-0737 requirements. Recommends meeting in Mar or Apr 1964 VAROA: 8 A Operating Reactors Branch 1 84/03/09. CLAYTON, F. L. Alabama Power Go 17pp 22807 R88 24X Fichs 50~348,84/03/09. 8403280329
- 8403290078 Ack receipt of 840308 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-348/84-03 & 50-364/84-03
 VERRELLI,D M Division of Project & Resident Programs 84/03/14
 MCDONALD,R P Alabama Power Co ip 22806:311 24X
 Fiche'50-348,84/03/14,8403290078
- --8403290103 IE Insp Repts 50-348/84-03 & 50-364/84-03 on 840111-0205 Violation found failure to implement procedures for control of maint activities BRADFORD.H H Region 2, Dffice of Director. 84/02/15 8pp. 22806 317 24X Fiche 50-348/84/03/14/8403290078

J Insurance & indemnity information

- 8403060448 Forwards Endorsement 58 to NELIA Policy NF-238 DUCK, J R Marsh & McLennan, Inc 84/02/28 SALTZMAN, J Director for State & Licensee Relations 2pp 22518 220 Fichs 50-348,84/02/28.8403060448 Assistant
- 6403140044 Forwards Endorsement 4 to NELIA Certificate N~13 correcting 03140044 Forwards Endorsement 4 to NELIA Certificate N-13 correcting name of insured on Endorsements 2 & 3 DUCK.JR Marsh & McLennan, Inc 84/03/05 SALTZMAN,J Assistant Director for State & Licensee Relations 2pp 22634 162 24X Fiche 50-348,84/03/05.8403140044
- 8403280053 Forwards Endorsements 47 & 30 to MAELU Policy MF-93 & Endorsements 59 & 60 to MELIA Policy NF-238 DUCK, J R Marsh & McLennan, Inc. 84/03/20 SALTZMAN, J Assistant Director for State & Licensee Relations 5pp 22777 001 24X Fiche 50-348,84/03/20.8403280053
- P Operating license stage documents & correspondence
- 8401120394 Forwards Amends 37 & 27 to Licenses NPF-2 & NPF-8, respectively & SER Amends allow operation w/slightly positive moderator temp coefficient at low power levels & increased hot channel factor limit below full power. REEVES.E A Operating Reactors Branch 1 83/12/30. CLAYTON.F L Alabama Power Co 2pp. 21796.274 24X Fiche 50-348.83/12/30. 8401120594
- --B401120597 Amends 37 & 27 to Licenses NPF-2 & NPF-8, respectively, allowing operation w/slightly positive moderator temp coefficient at low power levels & increased hot channel factor limit below full power VARDA,8 A Operating Reactors Branch 1 83/12/30 18pp 21796 276 24X Fiche 50-348,83/12/30,8401120594
- --8401120600 Safety evaluation supporting Amends 37 & 27 to Licenses NPF-2 & NPF-B. respectively * Office of Nuclear Reactor Regulation, Director. 83/12/30 4pp 21776 274 24X Fichs 50-348.83/12/30,8401120594
- 8403010117 Partial response to FOIA request for documents by named individuals re-repts, analyses, studies, procedures & sys for measurement of RCS leakage App B documents placed in PDR App A documents already available in PDR Search continuing FELTON, J M Division of Rules and Records 84/01/25 MA Kage, Scholer, Fierman, Hays & Handler 7pp 22480 026 Fiche 50-000,84/01/25,8403010117 MADDEN, T J
- --B011070522 Summarizes results of independent evaluations of primary sys lask rate & some considered extensions Extension of specific evaluations to all FWR facilities recommended Draft procedure re evaluations will be submitted by 800715 JORDAN.E L Division of Reactor Operations Inspections 80/08/21 MOSELEY.N C Division of Reactor Operations Inspections 11pp 22480 266 24X Fichs 50-000,84/01/25.8403010117
- --8403010127 Table of "Pressuriter Design Data " Related info encl # Alabama Power Co 84/01/25 46pp 22480 033 24X Fich# 50-000,84/01/25,8403010117
- 8403020186 Responds to util 830113 request for exemption from 10CFR20 re-protection factors for respirators Exemption would allow credit for radioiodine protection factor while employing MBA 466220 GMR-1 canister Review continuing VARQA:B A Operating Reactors Branch 1 84/02/17 CLAYTON.F L Alabama Power Co 5pp. 22491 150 24X Fiche 50-348,84/02/17, B40302015A
- B403010210 Notification of B40228 meeting w/util in Bethesda.MD to review changes to licensing amend schedules for 1984 REEVES, E Operating Reactors Branch i B4702/22 VAROA, B A Operating Reactors Branch i 2pp 22479 197 24X Fiche: 50-348,84/02/22,8403010210
- 8403070359 Notification of cancellation of 840228 meeting w/wtil in Bathesda MD to discuss proposed changes to licensing amend sethedules for 1784.
 REEWEB.E. Operating Reactors Branch 1 84/02/22 VARGA, B A Operating Reactors Branch 1 2p 22564 145 24X
 Fichs.50-348,84/02/22,8403070357
- 8403020440 Notification of 840308 meeting w/util in Bethesda.MD to discuss proposed changes to licensing amend schedules for 28 VARQA, 8 A 24X REEVES, E Operating Reactors Branch 1 84/02/28 Operating Reactors Branch 1 4pp 22491,200 24 Fiche.50-348,84/02/28,8403020440

- 8403130031 Supplemental application for amend to Licenses NPF-2 & NPF-B. changing Tech Specs 3/4 7 7 & 3/4 7 8 re control room emergency ventilation sys & penetration room filtration sys. respectively & deleting 3/4 9 14 re bypass piping CLAYTON.F L Alabama Power Co 84/03/01 VAROA.8 A Office of Nuclear Reactor Regulation. Director 8pp 22615 00; 24X Fiche 50-348,84/03/01,8403130031
- --8403130038 Proposed Tech Specs 3/4 7 % 3/4 7 8 re control room emergency ventilation sys. & penetration room filtration sys. respectively ...pec.vivesy * Alabama Power Co 84/03/01 14pp 22615 009 24X Fiche 30-348,84/03/01,8403130031
- B403130455 Application for amend to Licenses NPF-2 & NPF-8, making Tech Specs administrative changes NSHC determination requested CLAYTON.F L. Alabama Power Co. 84/03/01 VARCA,8 A. Office of Nuclear Reactor Regulation, Director 2pp 22613 336 24X Fiche 50-348,84/03/01.8403130455
- --8403130463 Proposed Tech Epecs, providing administrative changes * Alabama Power Co 84/03/01 10pp 22613 338 24X Fiche 50-348, 84/03/01, 8403130455
- B4030B00B1 Forwards corrections to Tech Spec pages for moderator temp coefficient at low power levels submitted B31013 which contained typographical errors CLAYTON; F. A. Alabama Power Co. 84/03/02 VARGA, S.A. Office of Nuclear Reactor Regulation, Director ip 28559 258 24X Nuclear Reactor Regulation, Direction 50~348,84/03/02,8403080081
- --8403080086 Corrected Tech Spec pages for moderator temp coefficient at House on the series and the series of the se
- 8403080148 Forwards response to NRC 840104 request for addl info re util 831230 application for change to diesel generator/river water Tech Specs
 CLAYTON, F L Alabama Power Co 84/03/02 VARGA, S A Operating
 Reactors Branch 1 8pp 22559 283 24% Fiche 50-348, 84/03/02. B4030B014B
- B4030B019B Application for amend to Licenses NPF-2 & NPF-8, revising Tech Specs re meteorological monitoring instrumentation Change includes air temp difference to conform w/STS CLAYTON.F L Alebama Power Co 84/03/02 VARGA, 8 A Office of Nuclear Reactor Regulation. Director 2pp 22557 145 24X Fiche 50-348,84/03/02,8403080158
- -8403080195 Proposed changes to Tech Specs re meteorological monitoring instrumentation Change includes air temp difference to * Alabama Power Co 84/03/02 5pp 22559 147 24X Fiche 50-348,84/03/02,8403080158
- B403210195 Requests identification of any potential problems in completing NUREG-0737 items by Bept 1984 Response requested within 30 days of ltr receipt VARGA.8 A Operating Reactors Branch 1 84/03/02 CLAYTON.F L Alabama Power Co 2pp 22709 176 24X Fiche 50-348,84/03/02.
- 8403080272 Informs of delay in responding to 840217 request for addition of iddine filter respiratory protection exemption request Reprioritization of request to 10CFR2O, App A, footnote (c) to 6-month interval requested CLAYTON.F L. Alabama Power Co. 84/03/05 VAROA, 8 A. Office of Nuclear Reactor Regulation, Director 1p. 22537 274 24X Fichs 50-348,84/03/05,8403080272
- 8403260326 Forwards corrected Tech Spec pages re reactor trip sys instrumentation setpoints contained in Amends 37 & 27 to Licenses NPF-2 & NPF-B, respectively, issued on 831230 REEVEB. E A Operating Reactors Branch 1 84/03/08 CLAYTON,F Alabama Power Co 2pp 22775 296 24X Fithe 50-348,84/03/08, CLAYTON, F L 8403260326
- --B403260327 Corrected Tech Spec pages to Amends 37 & 27 to Licenses NPF-2 & NPF-B, respectively, re reactor trip sys instrumentation setpoints * NRC No Detailed Affiliation Given 84/03/08 4pp 22775 278 24X Fiche. 50-348,84/03/08.8403260326
- B403260227 Application to amend Licenses NPF-2 & NPF-8, consisting of corrected Tech Specs incorporating positive moderator temp coefficient at low power levels & increased enthalpy hot channel factor limit below full power-per B31013 submittal CLAYTON, F L Alabama Power Co 84/03/22 VARGA, S A Office of Nuclear Reactor Regulation, Director | p 22756 072 24X Fiche 50-348.84/03/22,8403260227

- --8403260234 Corrected proposed Tech Specs.incorporating moderator temp coefficient at low power levels & increased enthalpy hot channel factor limit below full power # Alabama Power Co 84703/22 10pp 22756 073 24X Fiche 50-348,84703/22,8403260227
- B403280037 Application for amend to Licenses NPF-2 & NPF-8, changing Tech 8pecs 3 & 1 7 & 4 & 1 7 2 re containment venting Valves will be used for safety-related applications of containment pressure & radiological control CLAYFON.F L Alabama Power Co 84/03/23 VARGA.8 A NRC No DataLied Affiliation Oliven 2pp 22777 015 24X Fiche 50-348.84/03/23,8403280037
- --8403280044 Proposed changes to Tech Specs 3 & 1 7 & 4 & 1 7 2 re containment venting * Alabama Power Co 84/03/23 4pp 22777 017 24X Fiche 50-348,84/03/23.8403280037
- 8403300077 Furwards suppl to 840319 hydrostatic testing relief request re replacement of feedwater to steam generator noisle reducers Amend includes welding necessary to complete realignment of feedwater Line C CLAYTON: F L Alabama Power Co 84/03/26 VARGA, S A Office of Nuclear Reactor Regulation. Director 3pp 22822 084 24X Fiche 50-348,84/03/26,8403300077
- O Inspection reports. IE Bulletins & correspondence
- 8402130400 Forwards IE Safeguards Insp Repts 50-348/84-02 & 50-344/84-02 on 840116-20 No violations noted VERRELLI.D M Division of Project & Resident Programs 84/02/08 MCD6NALD.R P Alabama Power Co 2pp 22203 251 24X Fiche 50-348.84/02/08.8402130400
- --8402130404 IE Safeguards Insp Repts 50-348/84-02 & 50-364/84-02 on 840116-20 No violations noted Major areas inspected security organization, testing & maint & physical barriers Details withheld (ref 10CFR2 770 & 73 21) MORE, D E Region 2, Office of Director MCGUIRE, D R Division of Emergency Preparedness & Materials Safety 84/02/02 ip 2203 253 24% Fiche 50-348.84/02/08.8402130400
- 8403160142 Forwards IE Insp Repts 50-348/84-01 & 50-364/84-01 on 840118-19 No violations or deviations identified VERRELLI,D M Division of Project & Resident Programs 84/02/15 MCDDMALD-R P Alabama Power Co 2pp 22655 325 24X Fiche 50-348,84/02/15,8403160142
- --8403160146 lE Insp Repts 50-348/84-01 & 50-364/84-01 on 840118-19 No violations or deviations noted Major areas inspected emergency preparedness area of protective action decisionmaking CLINE: W Region 2. Office of Director JENKINS, G R Division of Emergency Preparedness & Materials Safety 84/02/15 4pp 22655 327 24X Fiche 50-348/84/02/15/8403160142
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Mater Operated Valve Control Circuits & Annunciation " Syc list entl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22909 239 24X Fiche 50-000-84/02/28,8401190072
- B403060125 Forwards summary of identified technical evaluation rept deficiencies re environ qualification of safety-related electrical equipment defined by IE Bulletin 79-01B & NUREG-058B, respectively Encl withheld (ref 10CFR2 790) CLAYTON, Ft. Alabama Power Co. B4/02/29 VARGA, S.A. Office of Nuclear Reactor Regulation, Director 4pp 22519 036 24% Fiche 50-348.84/02/29,8403060125
- 8403290019 Forwards IE Insp Repts 50-349/84-04 & 50-364/84-04 on 840131-0202 No violations or deviations noted VERRELLI.D M Division of Project & Resident Programs 84/02/29 MCDONALD.R P Alabama Power Co 2pp 22806 209 24X Fiche 50-348.84/02/29,8403290019
- -8403290027 IE Insp Repts 50-348/84-04 & 50-364/84-04 on B40131-0202 No violations or deviations noted Major areas inspected emergency exercise

 DECKER.T R Region 2. Office of Director JENKINS, G R. Division of Emergency Preparedness & Materials Safety B4/02/27 7pp 22806 211 24% Fiche 50-348.84/02/29.8403290019

- 8402090008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JDRDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02. Consolidated Edison Co of New York, Inc. 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008
- 8402090009 IE Info Notice 84-15. "Reporting of Radiological Releases"

 Bvc list encl

 JDRDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co. of Naw
 York, Inc. 119pp 22553 217 24X Ficha 50-000,84/03/02,8402090009
- 8402090011 IE Info Notice 84-17. "Problems W/Liquid Nitrogen Cooling Components Delow Nil Ductility Temp " Svc list encl URDAN; E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 30-000,84/03/05,8402090011
- 8403160237 Ack receipt of 840228 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-348/83-33 & 50-344/83-31 LEHIS.R C Division of Project & Resident Programs 84/03/05, MCDONALD.R P Alabama Power Co ip 22660 280 24x Fiche 50-348,84/03/05.8403160237
- --8403160265 Responds to NRC 840203 ltr re violations noted in IE Insp Repts 50-348/83-33 & 50-364/83-31 Corrective actions personnel counseled on importance of adhering to procedures CLAYTON.F L Alabama Power Co 84/02/28 LEWIS,R C Region 2, Office of Director 4pp 22660 281 24X Fiche 50-348,84/03/05, 8403160257
- --8403160272 Forwards IE Insp Repts 50-348/83-33 & 50-364/83-31 on 831112-840110 & notice of violation LEHTS.R C Division of Project & Resident Programs 84/02/03, MCDONALD, R P Alabama Power Co 2pp 22660 295 24X Fiche 50-348,84/03/05,8403160257
- --8403160277 Notice of violation from insp on 831211-840110. * Region 2, Office of Director 84/03/05 2pp 22660 287 24X Fichs 50-348,84/03/05,8403160257.
- --8403i60284 IE Insp Repts 50-348/83-33 & 50-364/83-31 on 831211-840110 Noncompliance noted failure to follow procedures & failure to establish corrective measures to insure svc water valve MGV 536 remained open to supply Train 8 BRADFORD, W H . RULAND, W H . Region 2. Office of Director CANTRELL.F S Division of Project & Resident Programs 84/01/30 10pp 22660.287 24X Fiche.50-348,84/03/05.8403160257.
- 8402070024 IE Info Notice 84-09, Rev i. "Lessons Learned From Insps of Fire Protection Safe Shutdown Bys " Svc list encl JORDAN. E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc. 118pp 22635 049 24X Fiche 50-000,84/03/07,8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR 8ys " Bvc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- B403270317 Responds to IE Bulletin 83-07, "Apparently Fraudulent Products Sold by Ray Miller, Inc." Results of review showed only Westinghouse supplied equipment utilizing Ray Miller components List of 30 vendors contacted encl.
 CLAYTON,F L. Alabama Power Co. 84/03/09 O'REILLY, J. P. Region 2, Office of Director Spp. 22802 047 24X Fiche 50-348,84/03/09,8403290319
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HPA Relays in Use in Class IE Safety Sys," Svc list encl.
 DEVOUND.R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000.84/03/12.8402090031
- 8403270078 Act receipt of 840308 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-348/84-03 & 50-346/84-03 VERRELLI,D N Division of Project & Resident Programs, 84/03/14 MCDDNALD,R P Alabama Power Co ip 22806 311 24X Fiche 50-348.84/03/14,8403270078.
- --8403270084 Responds to NRC 840215 ltr re violations noted in IE Insp Repts 50-348/84-03 & 50-364/84-03 Corrective actions responsible personnel instructed to implement procedures for control of maint activities CLAYION.F.L Alabama Power Co 84/03/08 VERRELLI, D M Region 2, Office of Director 2pp 22806:312 24X Fiche 50-348, 84/03/14,8403290078

- --8403270087 Forwards IE Insp Repts 50-348/84-03 & 50-364/84-03 on 840111-0208 & notice of violation VERRELLI, D M Division of Project & Resident Programs 84/02/15 MCDDNALD,R P Alabama Power Co 2pp 22806 314 24X Fiche 50-348,84/03/14,8403290078
- --8403290096 Notice of violation from insp on 840111-0205 * Region 2, Office of Director 84/02/15 1p 22806 316 24X Fiche 50-348,84/03/14,8403290078
- --B403290103 IE Insp Repts 50-348/84-03 & 50-364/84-03 on 840111-0205 Violation found failure to implement procedures for control of maint activities BRADFORD, W H , RULAND, W H Region 2. Office of Director CANTRELL, F S Division of Project & Resident Programs 84/02/15 Spp 22806 317 24X Fiche 50-348,84/03/14,8403290078
- B402090043 IE info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" 8vc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000,84/03/21,8402090043
- B402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Bys " Bvc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/03/21 Consolidated Edison Co of New York Inc 135pp. 22733 001 24X Fichs 50-000.84/03/21,8402090044
- R. Periodic operating reports & related correspondence
- 8403300134 Monthly operating rept for Feb 1984 W/840314 ltr HAIRBTON,W 0 , CLAYTON,F L Alabama Power Co 84/02/29. 7pp 22820.001 24X Fiche 50-364,84/02/29,8403300134
- 8 Reportable occurrences, LERs & related correspondence
- B403010417 Forwards revised LER 84-002-01 & LER 84-003-00 CLAYTON,F L Alabama Power Co 84/02/27 Record Services Branch (Document Control Desk) 1p 22434 019 24X Fiche 50-364,84/02/27,8403010417
- --8403010422 LER 64-003-00 on 840130 reactor tripped due to low-low level in steam generator 20 Caused by closure of main feedwater regulating valve 20 due to instrumentation channel spiking low NLP card replaced HAIRBTON. H G. Alabama Power Co 84/02/27 2pp 22434 020 24X Fiche 50-364.84/02/27.8403010417
- --8403010428 Revised LER 84-002-01 on 840124, hourly firewatch patrol in train B auxiliary bldg battery charger room not performed at specified times Caused by personnel error Personnel counseled & firewatch patrol immediately performed HAIRSTON.W.O Alabama Power Co 84/02/27 2pp 22434 022 24X Fiche 50-364,84/02/27,8403010417
- B403260233 Forwards summary list of deficiencies identified per 100FR90 55(a), Part 21 & potential generic ltr repts for comments
 BTAR0STECKI:R Division of Project & Resident Programs. 84/02/28
 Region 1, Office of Director. 7pp 22756 065 24X
 Fiche 50-000,84/02/28,8403260233
- DOCKET 50-366 EDWIN I HATCH NUCLEAR PLANT, UNIT 2

 F Security, medical, emergency & fire protection plans
- B403090282 Public version of Rev O to Emergency Plan Implementing Procedure HNP-8161, "Eberline Model PCM-1 Portal Monitor" & Rev 17 to HNP-8008, "Radiation Work Permit " W/840118 ltr & JM Felton B30307 release memo BORRELL,E C., NIX,H C. Georgia Power Co. 84/01/18 46pp 225793:321 24% Fiche.50-321,88/01/18,8403070282
- 8403300339 Public version of transmittal & title pages of deleted Emergency Plan Implementing Procedures HNP-8019, "Insp of Steel Radwaste Shipping Drums" & HNP-8422, "Handling & Loading of Chem-Nuclear Cask " W/840119 ltr & 840322 memo BORRELL, E.C., NIX, H.C., Oeorgia Power Co 84/01/25 App 22842:306 24X Fiche, 50-321, 84/01/25, 8403300339
- 8403260261 Forwards order confirming licensee commitment to implement post-TMI-melated itnes in NUREO-0737. Suppl 1 (Generic Ltr 82-33); "Requirements for Emergency Response Capability" STOLZ, J. F. Operating Reactors Branch 4 84/02/21 BECKHAM, J. T Georgia Power Co 3pp. 22763 179, 24X Fiche 50-321,84/02/21. 8403260261

- --8403260265 Order confirming licensee commitments on emergency response capability requirements set forth in NUREG-0737, Suppl 1 (Generic Ltr 62-33) EISENHUT, D 0 Division of Licensing 84/02/21 Georgia Power Ca 6pp 22763
- B403090067 Forwards rev to physical security plan Rev withheld (ref 10CFR2 790 & 73 21) Transmittal ack encl BECKHAH.J T Georgia Power Co 84/02/27 O'REILLY, J P Region 2. Office of Director 2pp 22575 351 24X Fiche 50-321.84/02/27. B403090067
- 8403130165 Revs & & 7 to Emergency Plan Implementing Procedures
 HNP-8006, Rev 9 to HNP-8007 & Rev 0 to HNP-8043 re
 decontamination & Rev 8 to HNP-4860, HP-4891, HP-4867, 4868 &
 4869 re reveiu & rev to emergency plan W/040306 ltr
 SDRRELL, E C Georgia Power Co 84/03/02 124pp 22600 132 24x
 Fiche 50-321,84/03/02,8403130165
- 8403130346 Advises that next annual emergency exercise scheduled for B40B02 State of GA & local govts do not plan to fully participate Exemption to 10CFR50.App E necessary to proceed w/exercise Reply requested if date & exercise acceptable BECKHAM.JT Georgia Power Co B4/03/02 DENTUN.HR Office of Nuclear Reactor Regulation, Director 1p 22607 149 24X Fiche 50-321.84/03/02.8403130346
- B403140190 Notifies of 840316 workshop meeting to discuss 10CFR50, App R raquirements & associated inspiresults to resolve fire protection misunderstandings. Number of attendees should be limited to six due to conference room size LEWIS, R C Region 2. Office of Director 84/03/02 KELLY, R J Georgia Power Co 1p 22655 317 24X Fiche 50-321, 84/03/02, 8403160150
- 8403130004 Transmittal & title pages of deleted emergency plan implementing procedures, including HNP-1-4205 re turbine lube oil reservoir oil fire & HNP-1-4206 re turbine lube oil conditioner & storage fire W/840306 ltr
 SORRELLE C Georgia Power Co 84/03/06 12pp 22615 183 24X Fiche 50-321,84/03/06,8403130004
- 8403260150 Revised emergency plan implementing procedures, including Procedure HNP-8033 re quantitative fit testing, Procedure HNP-8526 re alert emergency rally point leader & Procedure HNP-8010 re use & care of respirators W/840320 ltr SORRELL.E C Georgia Power Co 84/03/20 114pp 22758: 270 24X Fiche 50-321,84/03/20,8403260150
- 8403300143 Rev 6 to Emergency Plan Implementing Procedures HNP 4726 & 4626 & Rev 8 to Procedure HNP-8012 re general & site area amergency rally point leaders & radiation & contamination surveys W/840326 1 tr
 SORRELL.E C Georgia Power Co 84/03/26 119pp 22820 083 24X Fichs 30-321,84/03/26.8403300143
- J Insurance & indemnity information
- 8403060281 Forwards Endorsement 85 to NELIA Policy NF-215
 DUCK,J R Marsh & McLennan, Inc 84/02/28 SALTZMAN,J Assistant
 Director for State & Licensee Relations 2pp 22518 187 24X
 Fiche 50-321.84/02/28,8403060281
- 840328003B Forwards Endorsements 86 & B7 to NELIA Folicy NF-215 & Endorsements 70 & 71 to MAELU Policy MF-78
 DUCK, JR Marsh & McLennan, Inc. 84/03/21 SALTZMAN, J. Assistant Director for Btate & Licensee Relations 5pp 22777 010 24X
 Fiche 50-321.84/03/21.8403280038
- O Advisory Committee on Reactor Bafeguards reports & correspondence
- 8402270263 Responds to FOIA request for JC Mark 801204 memo to ACRS re hydrogen burn w/igniters & documents concerning generation. combustion or control of hydrogen in reactor accidents Forwards App A documents App B documents in PDR FELTON.J M Division of Rules and Records 84/01/30 HIATT, 8 L Ohio Citizens for Responsible Energy 7ap 22412 051 24X Fiche 50-000.84/01/30.8408270263
- --8402270314 Forwards summary of investigations re hydrogen recombiners & relay failures in HPCI sys
 ZUKOR:D J ACRS Advisory Committee on Reactor Safeguards,
 80/10/30 MOELLER:D W ACRS Advisory Committee on Reactor
 8

P Operating license stage documents & correspondence

- 8401120436 Notification of 840214 meeting w/GPU, Bechtel & Southern Sycs Co in Bethesda, MD to discuss equipment qualification RIVENBARK.G W Operating Reactors Branch 4 84/01/09 STOLZ, J F Operating Reactors Branch 4 2pg 21804 101 24X Fiche 50-321,84/01/09,8401120436
- 8403090187 Application for amend to Licenses DPR-57 & NPF-5, revising Tech Specs re listed TMI Action Plan items, per Generic Ltr B3-36
 BECKHAN, J T Georgia Power Co 84/02/06 STOLZ, J F Operating Reactors Branch 4 8pp 22573 276 24X Fiche 50-321, B4/02/06, B403090187
- --8403090196 Proposed Tech Specs re instrumentation providing surveillance info.post-accident sampling & analysis & post-accident monitoring instrumentation # Goorgia Payer Co 84/02/06 18pp 22573 284 24X Fiche 50-321.84/02/06.8403090887
- 8403160226 Reviews 840112 meeting to discuss responses to 831004 request for add1 info needed to review GA program description List of meeting attendees enc1 LEHIB.R C Division of Project & Resident Programs 84/02/09 KELLY.R J Georgia Pawer Co 3pg 22661 064 24X Fiche 50-321,84/02/09.8403160226
- B403050085 Discusses analyses on 22 safety relief valve (SRV) discharge lines per 821229 request to address questions re SRV test program per THI Item II D 1 Analyses indicate supports & paping geometry adequate GUCHA:L T Georgia Power Co 84/02/10 STGLZ, J.F. Operating Reactors Branch 4 2pp 22490 007 24X Fiche 50-321,84/02/10, B403050085
- 8403080179 Fourth partial response to FOIA request for aix categories of documents re facilities Forwards App A documents App B documents entirely withheld (ref FOIA Exemption 3) Review of addl documents subj to request continuing FELTON.J M Division of Rules and Records 84/02/13 ANDERSON.S I Garvey, Schübert. Adams & Barer 7pp 22583 226 24X Fiche 50-000,84/02/13,8403080179
- 8403060436 Forwards notice of consideration of issuance of Amends 97 & 34 to Licenses DPR-57 & NPF-5, respectively & proposed NSHC determination & opportunity for hearing re time requirements for scram discharge vol vent & drain valves RIVENBARK, 0 Operating Reactors Branch 4 84/02/21 BECKMAN, J T Georgia Power Co 3pp 22549 344 24X Fiche 50-321,84/02/21,8403060436
- --B403040440 Notice of consideration of issuance of Amends 97 & 34 to Licenses DPR-57 & NPF-5, respectively & proposed NSHC determination & opportunity for hearing STOLZ.JF Operating Reactors Branch 4 84/02/21 Spp 22549 347. 24X Fiche 50-321,84/02/21,8403060436
- 8403140340 Summary of 831215 meeting w/GE & Mark I Owners Group in Bethesda.MD re Mark I containment wetwell-drywell vacuum breaker design methodology BIEGEL.B L Operating Reactors Branch 2 84/02/21 Operating Reactors Branch 2 51pp 22635 178 24X Fiche 50-000,84/02/21, 8403140340
- 8403010110 Forwards Amends 98 % 35 to Licenses OPR-57 % NPF-5, respectively & safety evaluation Amends revise Tech Specs to extend time allowed to restore thermal power scram & control rod block trip setpoints within Tech Spec limits RIVENBARK.9 Operating Reactors Branch 4 84/02/22 BECKHAM.J T Georgia Power Co 2pp 22477 281 R4X Fiche 50-321,84/02/22,8403010110
- --8403010124 Amends 98 & 35 to Licenses DPR-57 & NPF-5, respectively, revising Tech Specs to extend time allowed to restore thermal gower scram & control rod block trip setpoints within Tech Specs limits
 STDLZ, J F Operating Reactors Branch 4 84/02/22 15pp 22479 283 24X Fiche 50-321.84/02/22,8403010110
- --8403010128 Safety evaluation supporting Amends 98 & 35 to Licenses DPR-57 & NPF-5, respectively * Office of Nuclear Reactor Regulation, Director 84/02/22 3pp 22479 298 24% Fiche. 50-321,84/02/22,8403010110
- 8403070357 Forwards request for add1 info to complete review of proposed programs for inservice testing of pumps & valves submitted in B30812 ltr Info requested within 30 days STDLZ.J F Operating Reactors Branch 4 84/02/23 BECKHAM.J T Opergia Power Co 4pp 22564-134 24X Fiche 50-321,84/02/23,8403070357

- 8403070251 Forwards update on facilities conformance & info re plans & schedules for any needed improvements & rept re vendor equipment technical info program by Nuclear Util Task Action Committee on Generic Ltr 83-28, Section 2 2 GUCMA, L T Georgia Power Co 84/02/27 STOLZ, J F Operating Reactors Branch 4 24pp 22536 087 24X Fiche 50-321,84/02/27,8403070251
- --8403070252 "Vendor Equipment Technical Info Program," per Generic Ltr 83-28. Section 2 2 2. final draft * Nuclear Utility Task Action Committee 84/02/29 63pp 22535 112 24X Fiche 50-321.84/02/29.8403070251
- 8403200005 Responds to 840229 request for add1 action to verify aspects of overhead crane design at facility.per NUREG-0612 guidelines Crane safety & reliability satisfactory GUCMA-L T Georgia Power Co 84/03/12 STGLZ.J F Operating Reactors Branch 4 2pp 22685 209 24X Fiche 50-321,84/03/12, B80320005
- 8403200262 Forwards GE repts on metallographic exam of metal samples taken from cracked vent header, per NRC 840206 meeting w/ util. BHR Regulatory Responsa Group & GE Vent header cracking brittle fracture caused by injection of cold nitrogen QUCHA-L T Georgia Power Co 84703/13 STOLZ, J F Operating Reactors Branch 4 5pp 22671 102 24X Fiche 50-366.84/03/13, 8403200262
- B403150275 Generic Ltr 84-07 to all licensees of BWRs re procedural guidance for pipe replacement at BWRs 8vc list encl EISENHUT, D 0 Division of Licensing B4/03/14 Commonwealth Edison Co 20pp 22823 334 24X Fichs 50-000.84/03/14,8403150275
- O Inspection reports, IE Bulletins & correspondence
- 8403160176 Forwards IE Insp Repts 50-321/84-04 & 50-366/84-04 on B40204-07 No violations or deviations identified DANCE.H C Division of Project & Resident Programs B4/02/24 KELLY.R T Georgia Power Co Zpp 22655 351 24X Fiche 50-321,84/02/24,8403160196
- --8403160198 IE Insp Repts 50-321/84-04 & 50-366/84-04 on 840204-07 No violations or deviations identified Major areas inspected torus vent header cracking feedwater line ultrasonic indication & recirculation piping replacement CROWLEY, B R , DLAKE, J J Region 2, Office of Director, 84/02/23 6pp 22655 353 24X Fiche 50-321,84/02/24,8403160196
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JCROBAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22909 239 24x Fiche 50-000,84/02/28,8401190072
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list ancl GRACE, J. N Division of GA: Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 327 24X Fiche 30-000,84/03/02,8402090007
- 8402070008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103), 84/03/02 Consolidated Edison Co. of New York, Inc. 122pp 22553 098 24X Fichs 50-000.84/03/02,8402070008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases" Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl.

 JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co. of New York, Inc 117pp. 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8402090024 IE Info Notice 84-09, Rev i, "Lessons Learned From Insps of Fire Protection Bafe Shutdown Sys " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103), 84/03/07. Consolidated Edison Co. of New York, Inc 118pp 22635 049 24% Fiche 50-000, 84/03/07, 8402090024
- B402090028 IE Info Notice 84-19. "Stress Corrosion Cracking in PHR Bys " Svc list encl JDRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584:186 24X Fiche 30-000,84/03/07,8402090028

- 8403140338 Ack receipt of 840206 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/83-32 & 50-346/83-34
 - 00-386/83-34 DANCE.H C Division of Project & Resident Programs 84/03/09 KELLY.R J Georgia Power Co ip 22660 015 24X Fiche 50-321.84/03/09.8403160338
- ---8403140349 Responds to NRC 840106 itr re violations noted in IE Insp Repts 50-321/83-32 & 50-366/83-34 Corrective actions procedure revs drafted & undergoing review & approval process GUCMA,L Y Georgia Power Co 84/02/06 Q'REILLY, J P. Region 2, Qeffice of Director 2pp 22660 016 24X Fiche 50-321,84/03/09,
- --8403160359 Forwards IE Insp Repts 50-321/83-32 & 50-366/83-34 on 831114-18 & notice of deviation DANCE, H C Division of Project & Resident Programs 84/01/06 KELLY, R J @eorgia Power Co 2pp 22660 018 24X Fichs 50-321,84/03/09,8403160338

840314033B

- --8403140345 Notice of deviation from insp on 831114-18 # Region 2. Office of Director 84/01/06 ip 22640.020 24X Fiche 50-321,84/03/09,8403160338
- ---8403160372 IE Insp Repts 50-321/83-32 & 50-366/83-34 on 831114-18 Deviation noted failure to electronically calibr high range drywell radiation monitors, per NNREO-0737. Item II F 1 MRAY. J R Region 2. Office of Director BARR. K P Division of Engineering & Operational Programs 84/01/04 7pp 22660 021 24X Fiche 50-321.94/03/09,8403160338
- 8402070031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Syc list encl DEYOUNO, R C Director's Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp. 22823 074 24X Fiche 50-000,84/03/12,8402090031
- 8403270193 Ack receipt of 840301 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-366/83-26 LEWIS:R C Division of Project & Resident Programs 84/03/15 KELLY:R J Georgia Power Co. 1p 22801 008 24X Fiche. 50-366.84/03/15.8403290193
- ---8403270194 Responds to NRC 840201 ltr re violations noted in IE Insp Repts 50-321/83-25 & 30-366/83-26 on 830721-0820. Corrective actions administrative controls to stress independent verification upgraded BECKHAMJ T Georgia Power Co 84/03/01 O'REILLY, J P Region 2, Office of Director 6pp 22801 009 24X Fiche 50-366, 84/03/15.8400390193
- --B403290195 Forwards IE Insp Repts 50-321/83-25 & 50-366/83-26 on B30721-0820 & notice of violation LEWIB,R C Division of Project & Resident Programs 84/02/01 KELLY,R J Georgia Power Co. Zpp 22801 015 24X Fichs 50-366,84/03/15,8403290193
- --8403290196 Natice of violation from insp on 830721-0820. * Region 2, Office of Director. 84/02/01 2pp 22801:017 24% Fiche.50-366,84/03/15,8403290193
- --8403290197 IE Insp Repts 50-321/83-25 & 50-366/83-26 on 830721-0820 Violations noted safety-related equipment & sys not aligned & limiting condition for operation for main steam isolation laskage control sys not established CRLENJAK,R V , HOLMEG-RAY,P., PANCIERA,V W Region 2, Office of Director 84/01/28 5pp 22801 018 24X Fiche 50-366,84/03/15.8403270193
- 8403290208 Ack receipt of 840301 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-321/84-03, DANCE, H. C. Division of Project & Resident Programs, 84/03/19 KELLY, R. J. Georgia Power Co. 1
- --8403290212 Responds to NRC 840210 ltr re violations noted in IE Insp Repts 50-321/84-03 & 50-366/84-03 Corrective actions.NDE personnel reminded of importance of proper & complete data recording QUCHA/L.T. Georgia Power Co 84/03/01 0'REILLY, J P Region 2, Office of Director 2pp 22800 303. 24X Fiche 50-321,84/03/19, 8403290208.
- --B403290215 Forwards IE Insp Repts 50-321/84-03 & 50-366/84-03 on 840124-27 & notice of violation.

 DANCE,H C. Division of Project & Resident Programs B4/02/10 KELLYR,J Georgia Power Co 2pp 22800,305 24X Fiche 50-321,84/03/19,8403290208

- --8403270219 IE Insp Repts 50-321/84-03 & 50-366/84-03 on 840124-27 Violation noted ultrasonic insp records for Fall 1982 insp of reactor vessel flange to Shell Wold C-1 did not show extent or location of area CROWLEY.B R Region 2, Office of Director. DLAKE, J J Division of Emergency Preparedness & Materials Safety 84/02/09 11pp 22800 308 24X Fiche 50-321,84/03/19,8403290208
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svr list encl JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post E30103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000.84/03/21,8402090043
- 8402090044 IE Info Notice 84-20. "Svc Life of Relays in Safety-Related Sys " Svc list enc!

 JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000.84/03/21.8402090044
- R Periodic operating reports & related correspondence
- 8403150071 Monthly operating repts for Feb 1984 W/840310 ltr RAFEEDIE.D P , NIX.H C Georgia Power Co 84/02/27 12pp 22643 191 24X Fiche 50-321.84/02/29.8403150071
- 8 Reportable occurrences, LERs & related correspondence
- 8304270367 Forwards for review, technical review rept on method of detaction used in 800726 failure of scram discharge vol level switches PELLET. J L Reactor Operations Analysis Branch 83/04/13 SEYFRIT. K V Reactor Operations Analysis Branch 1p 22808 314 24X Fiche 50-366/83/04/13/8304270367
- --8403280077 "Scram Discharge Vol Level Switch Failure," technical review rept Caused by crushed floats Piping mods made to alleviate high differential pressure across float chamber during scram reset
 PELLET.J Reactor Operations Analysis Branch 83/04/13 3pp 22808 313 24% Fiche 30-366.83/04/13.8304270367
- 8403260233 Forwards summary list of deficiencies identified per 10CFR50 53(e). Part 21 & potential generic ltr repts for comments
 STAROSTECKI.R Division of Project & Resident Programs 84/02/28 Region 1. Office of Director 7pp 22756 065 24X Fiche 50-000.84/02/28.8403260233
- 8403050284 Summary of 840223 meeting w/BWR Regulatory Response Group in Bethesda.MD re industry response to vent header cracking incident Presentation outline.info request.GE svc info ltr & meeting attendance list encl
 TREMBLAY.P Operating Reactors Assessment Branch 84/02/29 HOLOMAN.G M Operating Reactors Assessment Branch 18pp 22501:188 24X Fiche 50-366.84/02/27.8403050284
- B403120031 LER B4-001-00 on B40203, personnel detected fracture in 66-inch vent header in bay 3 Caused by brittle facture of vent header mat! Vent header will be repaired & addl changes or sys mod will be made to improve sys W/840304 ltr TIPPS,8 B , NIX.H C Georgia Power Co 84/03/04 5pp 22588 020 24X Fiche 50-366,84/03/04,8403120031
- 8403160031 Updated LER 83-040/03X-1 on 830709 & 14, control rod drive low pressure or high level alarm received for HCV 2011-26-31 & 02-27 Caused by leaking EP-111 nitrogen charping valves Valves replaced & HCVs returned to svc W/840312 tr TIPPB, 8 B, NIX,H,C Georgia Power Co 84/03/12 0'REILLY, J P Region 2, 0FFice of Director 8pp 22654 349 24X Ficha 50-366,84/03/12.8403160031
- 8403160039 PNO-II-84-021.crack indications identified in all 14 12-inch riser elbous in replacement recirculation piping scheduled to be installed Caused by improper forming temps used during bending process BLAKE, J. J., ROGGE, J. F. Region 2, Office of Director 84/03/12, 2pp. 22655 134 24X Fiche 50-366.84/03/12.8403160039
- 8403190026 Updated LER 83-040/03X-1 on 830728, control rad drive low pressure or high level alarm received for hydraulic control units 2C11-26-31 & 02-19. Caused by leaking EP-111 nitrogen charging valves Valves replaced W/840312 ltr TIPPS, S B, NIX,H C Georgia Power Co 84/03/12 D'REILLY, J P Region 2, Office of Director Bpp 22666 105 24X Fiche 50-366,84/03/12,8403190026

- B403190284 PNO-II-84-022 circumferential crack found on one of four feedwater nuzzles during exam of feedwater nuzzles per NURCO-0691 Corrective action being evaluated Inspectors monitoring licensea work on regular basis CRUMLEY.B R. PANCIERA.V Region 2. Office of Director B4/03/14 pp 22672 279 24X Fiche 50-366/84/03/14/8403190284
- 8403260086 Updated LER 62-123/03X-1 on 821030, reed switch position indicators for control rods 14-07 & 34-43 found inoperable Caused by component failure Control rod drivers 2011-34-43 & 2011-14-07 repaired W480319 ltr TIPPS 8 B , NIX.H C Georgia Power Co 84/03/19 O'REILLY, J P Region 2, Office of Director 4pp 22748 358 24X Fiche 50-366, 84/03/19, 8403260086
- B403260191 LER 84-002-00 on B40220, five main steam safety relief valves failed to lift in 1/2 tolerance range required by Tech Specs Caused by corrosion buildup on pilot assembly Safety relief valves calibr W/840320 ltr TIPPS.S B , NIX.H C Georgia Power Co 84/03/20 5pp 22756 116 24X Fichs 50-366.84/03/20.8403260191
- B403290013 Confirms IE mgt meeting on 840323 at Region II oft to discuss crack found in feedwater notale & future corrective action.per 840316 telecon
 LEHIS.R C Division of Project & Resident Programs 84/03/20 KELLV.R J Georgia Power Co ip 22803 283 24X Fiche 50-366.84/03/20.8403270013
- 8403260119 Revised LER 94-001-01 on 840203.plant personnel detected fracture in 66-inch vent header in Bay 5 Caused by brittle fracture of vent header matl Vent header will be repaired prior to startup. W/840321 ltr
 TIPPS, S B , NIX,H C Georgia Power Co 84/03/21 6pp 22757 397 24X Fiche 50-386.84/03/21.8403260119
- 8403300104 Advises that program of periodic manual operation of safety relief valves will be discontinued based on results of BMR Gumers Group investigation Safety relief valve cycling caused valves to leak prematurely OVCHAL T Georgia Power Co 84/03/26 STOLZ, J F Operating Reactors Branch 4 2pp 22821 216 24X Fiche 50-321,84/03/26.

DOCKET 50-368 ARKANSAS NUCLEAR ONE, UNIT 2

F Security, medical, emergency & fire protection plans

- 8403130437 Documents results of activities conducted during 831031-1104 IE insp to review open items re emergency planning Commitment status to resolve items provided Expeditious actions by NRC to remove items requested MARSHALL. J. R. Arkansas Power & Light Co. 83/12/09 COLLINS, J.T. Region 4. Office of Director 15pp. 22613 233 24X Ficho 50-213,83/12/09,8403130437
- 8403120011 Forwards Amend 10 to emergency plan W/o encl MARSHALL.J R Arkansas Power & Light Co B4/01/20 COLLINS,J T Region 4. Office of Director Ip 22085 221 24X Fiche 50-313,84/01/20,8403120011
- 8403280074 Public version of Amend 10 to emergency plan #/840120 ltr & JM Felton 840322 release memo MARSHALL.J R Arkansas Power & Light Co 84/01/20 COLLINS:J T Region 4. Office of Director Spp 22812 288 24X Fiche 50-313.84/01/20.8403280094
- B403130473 Submits response to Hakney request for add1 info re emergency plan training for non-util employees Vendors & contractors w/unextorted access within protected area receive training commensurate w/30b assignments MARSHALLJR Arkansas Power & Light Co B4/01/24 GAGLIARDO, J E Division of Resident, Reactor Project & Engineering Programs ip 22613 330 24X Fiche 50-313,84/01/24,8403130473
- 8403050142 Notifies that NRC will provide inspectors to observe ensite aspects of periodic ejercises for amergency preparedness Scenario for submission of info listed COLLINB, J.T. Region 4. Office of Director 84/02/09 GRIFFIN, J.M. Alabama Power Co. 2pp. 22487, 308 24% Ficher 50-313, 84/02/09, 340/330142
- 8403130395 Forwards IE Insp Repts 50~313/84-05 & 50~368/84-05 on 840126 No violations or deviations identified 840126 No violations or deviations identified 94/02/16

- --8403130402 IE Insp Repts 50-313/84-05 & 50-368/84-05 on 840126 No violations or deviations identified Major areas inspected status of REX-84 exercise scenario development HACKNEY, C A Region 4, Office of Director 84/02/16 3pp 22616 327 24X Fiche 50-313,84/02/16,8403130395
- B403060350 Requests approval of mod to health physics network & emergency notification sys phones from handset to headset, to alleviate fatigue during continuous open-line communications maintained in emergencies

 MARSHALLJ R Arkansas Power & Light Co 84/02/17 DENISE, R P
 Division of Resident, Reactor Project & Engineering Programs 1p
 22519 085 24X Fiche 50-313.84/02/17,8403060350
- 8403060198 Ack receipt of 840203 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/83-25 & 50-368/83-25 GAGLIARDOJE Region 4. Office of Director 84/02/29 ORIFFIN.J M Arkansas Power & Light Co ip 22517 226 24X Fiche 50-313.84/02/29.8403060198
- --8403060203 Responds to NRC 831024 itr re violations noted in IE Insp Repts 50-313/83-25 & 50-368/83-25 Corrective actions fire watch posted at Doors 267 & 340 until mods to eliminate excessive air gaps under doors completed MARSHALL.JR Arkansas Power & Light Co 84/02/03 DENISE,R P Division of Resident, Reactor Project & Engineering Programs 3pp 22517 227 24X Fiche 50-313,84/02/29,8403060198
- 8403040430 Provides preliminary estimates for emergency operations facility mods to raise radiation protection factor to greater than or equal to five,per NUREO-0694.in response to NRC 840214 request Util will not implement mods MARBHALL.JR Arkansas Power & Light Co. 84/02/29 STOLZ,JF Operating Reactors Branch 4 MILLER.JR Operating Reactors Branch 3 2pp 22518.192 24X Fichs.50-313.84/02/29.8403060430
- 8403060324 Forwards proprietary Rev 12 to frocedure 1903 10, "Emergency Action Level Response" & proprietary Procedure 1904 series (1904 01: 02: 03: 04: 07: 08), "Offsite Dose Projections " Proprietary procedures withheld # Arkansas Power & Light Co 84/03/01 NRC No Detailed Affiliation Given 2pp 22513 333 24X Fiche 50-313, 84/03/01, 8403060324
- 8403070358 Public version of Rev 12 to Emergency Plan Implementing Procedure 1903 10, "Emergency Action Level Response" W/840209 transmittal form & JM Felton 840302 release memo LEVINE, J M Pennsylvania Power & Light Co 8403/01. 68pp. 22866 227 24X Fiche 50-313,84/03/01.8403070358
- 8403260070 Forwards IE Insp Repts 50-313/84-04 & 50-368/84-04 on 840124-26 No violations or deviations identified OAGLIARDD.J E Region 4. Office of Director 84/03/05 ORIFFIN.J M Arkansas Power & Light Co 2pp 22758 271 24X Fiche 50-313,84/03/05,8403260070
- ~-8403260099 IE Imsp Repts 50~313/84~04 & 50~368/84~04 on 840124~26 No violations or deviations identified Major areas inspected, security organization personnel per alleged compromise of safeguards info Details withheld (ref 10CFR73 21) KELLY, J A Region 4, Office of Director 84/03/02 ip 22758:273 24X Fiche 50~313,84/03/05,8403260090
- 8403230238 Advises that based on review of 831125 submittal of detailed control from design, specific areas of program plan do not meet requirements of Suppl 1 to NUREG-0737 Meeting requested to resolve deficiencies
 STOLZ.J F Operating Reactors Branch 4 84/03/06 ORIFFIN, J M Arkansas Power & Light Co 2pp 22759 278 24X
 Fiche 50-313.84/03/06.8403230238
- B403190277 Notifies of error in 840216 ltr transmitting IE Insp Repts 50-313/B4-03 & 50-368/B4-03 ltr indicated rept numbers 50-313/B3-03 & 50-368/B3-03 Records should be changed accordingly GAGLIARDGUJ E Region 4, Office of Director 84/03/08 GRIFFIN, J M Arkansas Power & Light Co 1p 22673 170 24X Fiche 50-313,84/03/08,8403190277
- --8403190283 Forwards IE Insp Repts 50-313/84-03 & 50-368/84-03 on 840125 No violations or deviations noted GACLIARDOLJE Region 4. Office of Director 84/02/16. GRIFFIN.JM Arkensas Power & Light Co 2pp 22673'191. 24X Fiche 50-313,84/03/08,8403190277
- --8403170288 IE Insp Repts 50-313/84-03 & 50-368/84-03 on 840125 No violetions or deviations noted Major areas inspected actions taken as result of discrepancy between public info brochure & Jan 1984 telephone directory for emergency planning zone HACKNEY.C. A Region 4. Office of Director 84/02/16 Spp 22673 193 24X Fiche 50-313,84/03/08.6403190277.

- 8403150113 Forwards exercise repts of 820519 & 830316 joint exercises of offsite radiological emergency preparedness plans for Artansas Nuclear One Power Station Deficiencies observed at both exercises Approval under FEMA Rule 4405R330 in effect KRIMM.R W Federal Emergency Management Agency 84/03/09 JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Fost 830103) 2pp 22640 001 24X Fichs 50-313,84/03/09,8403150113
- --8403150117 Exercise repts of 820517 & 830316 joint exercises of offsite radiological emergency preparadness plan for Arkansas Nuclear One Power Station KRIMM.R W Faderal Emergency Managament Agency 84/03/07 45pp 22640 003 24X Fiche 50-313,84/03/09.8403150113
- 8403200246 Forwards Amend 4 to nuclear contingency plan. Rev 4 to Nuclear Contingency Plan Procedures 1,2,3,7 & 9,Rev 3 to Procedures 5,6,8 & 11,Rev 2 to Procedures 4 & 13 & Rev 1 to Procedure 15

 MARSHALL.J R Arkansas Power & Light Co 84/03/14 EISENHUT, D Q Office of Nuclear Reactor Regulation. Director 1p 22688 027 24X Fichs, 50-313,84/03/14,8403200246
- --8403200251 Rev 4 to nuclear contingency plan * Arkansas Power & Light Co 84/02/06 49pp 22688 028 24X Fichs 50-313,84/03/14,8403200246
- --8403200258 Revs 4,3,2 & 1 to Nuclear Contingency Flan Implementing Procedures 1,2,7 & 7,5,6,8 & 11,4 & 13 & 15, respectively, reassignment of personnel to emergency response organization, notification & command & control # Arkansas Power & Light Co 84/03/15 143pp 22688 077, 24X Fiche 50-313,84/03/14,8403200246
- ©403200179 Forwards Amend 11 to emergency plan & Amend 4 to nuclear contingency plan. MARSHALLUJ R Arkenses Power & Light Co 84/03/15 COLLINS, J T Region 4, Defice of Director 1p 22689 120, 24X Fiche 50-313,84/03/15,8403200179
- ---8403200180 Amend i1 to emergency plan & Amend 4 to nuclear contingency plan.

 * Arkansas Power & Light Co 84/02/06 57pp 22689 121 24X
 Fiche 30-313,84/03/15,8403200179
- --8403200181 Rev 4 to Nuclear Contingency Plan Implementing Procedure 1, "Assignment of Personnel to Emergency Response Organization"

 * Arkansas Power & Light Co 84/02/06 137pp. 22689,177 24X Fiche: 50-319,84/03/15,8403200179.
- 8403220185 Responds to 840217 request for relocation of HPN telephone in emergency control ctr & for approval to add headsets. Request forwarded to Telecommunications Branch Headset mod approved GAOLIARDO.J E. Region 4, Office of Director 84/03/19 GRIFFIN.J.M. Arkansas Power & Light Co 1p 22717 035 24X Fichs. 50-313,84/03/19.8403220185.
- P. Operating license stage documents & correspondence
- B4D3060551 Forwards safety evaluation re adequacy of fuel assembly shoulder gaps for Cycle 4 operation Requests exam plan & related acceptance criteria be submitted 2 months before plant shutdown for next refueling. W/o encl HILLER, J R. Operating Reactors Branch 3 84/02/24 GRIFFIN, J M Arkaneas Power & Light Co 2pp. 22552 291 24X Fiche: 50-368,84/02/24,8403060551
- 83403120082 Requests rev or withdrawal of 830927 amend application to delete remote shutdown monitoring instrument measurement ranges Min instrument measurement ranges should be specified MILLER, J. R. Operating Reactors Branch 3 84/02/29 GRIFFIN, J M Arkaneas Powers & Light Co Spp. 22619-343 24X Fichs 50-368,84/02/29,8403120082.
- 8403140299 Forwards request for add1 info re control of heavy loads.
 Response requested within 60 days.
 MILLER, J. R. Operating Reactors Branch 3 84/03/06, GRIFFIN, J M
 Arkanses Power & Light Co 2pp 22635 327 24X
 Fiche. 50-313,84/03/06,8403140299

- 8403260031 Application to amend Licenses DPR-51 & NPF-6, changing Tech Specs re RCS vents.post-accident sampling.long-term auxiliary feedwater sys evaluation.noble gas monitor & iodine particulate sampling.per NUREG-0737 items GRIFFIN.J M Arkansas Power & Light Co 84/03/16 STOLZ,J F Operating Reactors Branch 4 MILLER.J R Operating Reactors Branch 3 9pp 22750 293 24X Fiche 50~313,84/03/16,8403260051
- --8403260157 Proposed Tech Spec changes re RCS vent post-accident sampling.long-term auxiliary feedwater sys evaluation, noble gas monitors, iodine particulate sampling & containment water level monitor

 * Arkansas Power & Light Co 84/03/16 27pp 22750 302 24X Fiche. 50-313,84/03/16,8403260051
- O Inspection reports, IE Bulletins & correspondence
- 8403130437 Documents results of activities conducted during 83103i-1104 IE insp to review open items re emergency planning Commitment status to resolve items provided Expeditious actions by NRC to remove items requested MARSHALL.JR Arkansas Power & Light Co 83/12/09 COLLINS,JT Region 4. Office of Director 15pp. 22613 233 24X Fiche 50-313.83/12/09.8403130437
- 8403300046 Forwards IE Insp Repts 50-313/83-36 & 50-368/83-36 on 831219-21 No violations or deviations identified QAQLIARDO, J E Region 4, Office of Director. B4/01/31 QRIFFIN, J M Arkenses Power & Light Co 2pp 22821 240 24X Fiche 50-313,84/01/31,8403300046
- --B403300050 IE Insp Repts 50-313/83-36 & 50-368/83-36 on 831219-21 No Violations or deviations identified Major areas inspected GA plans, instructions & procedures for low level radwaste storage facility
 HILBORN,L , MURRAY.B , JOHNBON.W D. Region 4, Office of Director 84/01/27 10pp 22821 242 24X Fiche 50-313.84/01/31,8403300046
- 8403130395 Forwards IE Insp Repts 50-313/84-05 & 50-368/84-05 on 840126 No violations or deviations identified GAOLIARDO.J.E. Region 4. Office of Director 84/02/16 ORIFFIN.J M. Arkansas Power & Light Co. 2pp. 22616 325 24X Fiche 50-313.84/02/16.8403130395
- --B403130402 IE Insp Repts 50-313/84-05 & 50-368/84-05 on 840126 No violations or deviations identified Major areas inspected, status of REX-84 exercise scenario development HACKNEY.C A , BAIRD.J B , JOHNSON, H. D. Region 4, Office of Director 84/02/16 3pp 22616 327 24X Fiche 50-313,84/02/16,8403130375
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list ancl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22909 239 24X Fiche 80-000.84/02/28,8401190072
- 8403040198 Ack receipt of 840203 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/83-25 & 50-348/83-25 GAGLIARDO.J E Region 4. Office of Director 84/02/29 GRIFFIN.J M Arkansas Power & Light Co ip 22517 226 24X Fiche 50-313.84/02/29.8403040198
- --8403040203 Responds to NRC 831024 ltr re violations noted in IE Insp Repts 50-313/83-25 & 50-368/83-25. Corrective actions fire watch posted at Doors 267 & 340 until mods to eliminate excessive air gaps under doors completed MARSHALL, J. R. Arkansas Power & Light Co. 84/02/03 DENISE, R.P. Division of Resident, Reactor Project & Engineering Programs 3pp 22517 227 24X Fiche 50-313,84/02/29,8403060198
- 8403240137 Forwards results of steam generator tube inservice insp parformed during 2RS refueling outage Minor tube wall degradation indications observed during data analysis for Steam Generator A & B in both hot & cold leg sides. MARSHALL.J R Arkansas Fower & Light Co 84/02/29 COLLINS, J Y Region 4. Office of Director 8pp 22758 150 24X Fiche 30-368.84/02/29,8403260137
- 8403060122 Notification of significant licensee anforcement conference on 840309 w/util in Arlington TX * Region 4, Office of Director 84/03/01 Region 4, Office of Director 1p 22316 328 24X Fiche 50-313,84/03/01.8403060122
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " 8vc list encl. GRACE J.N Division of CA, Bafeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fichs 50-000,84/03/02,8402090007

- 8402070008 [E Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fishe 50-000,84/03/02,8402090008
- 8402090007 IE Info Notice 84-15, "Reporting of Radiological Releases" Svc list ench JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 119pp 22553 217 24X Fichs 50-000,84/03/02,8402090009
- 84020900i1 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl URBAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidate Edison Co of New York, Inc 117pp 22553 336 24% Fiche 50-000,84/03/05,8402070011
- B403260090 Forwards IE Insp Repts 50-313/B4-04 & 50-368/B4-04 on B40124-26 No violations or deviations identified GAGLIARDD.J E Region 4. Office of Director 84/03/05 GRIFFIN.J N. Arlansas Power & Light Co 2pp 22758 271 24X Fiche 50-313:84/03/05.8403260090
- --B403260099 IE Insp Repts 50-313/84-04 & 50-368/84-04 on 840124-26 No violations or deviations identified Major areas inspected security organization personnel per alleged compromise of safeguards info Details withheld (ref 10CFR73 21)
 KELLY, J.A., HALL, R.E., JOHNSON, W.D. Region 4, Office of Director 84/03/02 ip 22758 273 24X Fiche-50-313,84/03/05.8403260090
- 8402090024 IE Info Notice 84-09, Rev i. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consol
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PUR 9ys" Syc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering Response (Fost 830103) 84/03/07 Consolidated Edison Co of New York, Inc. 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8403130120 Informs that IE Insp Repts 50-313/83-12, 50-318/83-12, 50-313/83-33 & 50-369/83-33 cancelled No insp repts will be issued for subj.numbers GAGLIARDD, J.E. Region 4. Office of Director B4/03/08 GRIFFIN.J M. Arkansas Ppwer & Light Co. 1p. 22602 197 24X Fiche 50-313,84/03/08,8403130120
- B403190277 Notifies of error in 840216 ltr transmitting IE Insp Repts 50-313/84-03 & 50-368/84-03 Ltr indicated rept numbers 50-313/83-03 & 50-368/83-03 Records should be changed accordingly 8AGLIARDO, J E Region 4, Office of Director 84/03/08 GRIFFIN, J M Arkansas Power & Light Co 1p 22673 190 24X Fiche 50-313,84/03/08,8403190277
- --8403190283 Forwards IE Insp Repts 50-313/84-03 & 50-368/84-03 on 840125 No violations or deviations noted GAGLIARDD.J E. Region 4, Office of Director 84/02/16 GRIFFIN.J M. Ankaneas Power & Light Co. 2pp 22673 191 24X Fiche 50-313.84/03/08.8403190277
- --8403190288 IE Insp Repts 50-313/84-03 & 50-368/84-03 on 840125 No violations or deviations noted. Major areas inspected actions taken as result of discrepancy between public info brochure & Jan 1984 telephone directory for emergency planning zone HACKNEY, C A , BAIRD, J B , JOHNSON W D Region 4, Office of Birector 84/02/14 3pp 22673 193 24X Fiche 50-313,84/03/08,8403190277
- 8403260230 Forwards IE Insp Repts 50-313/84-06 & 50-368/84-06 on 840221-24 No violations or deviations noted. OAGLIARDD.JE Region 4. Diffice of Director 84/03/08 GRIFFIN.J M Arkensas Power & Light Co 2pp 22755 151 24X Fiche 50-313,84/03/08,8403260220
- --8403260232 IE Insp Repts 50-313/84-06 & 50-368/84-06 on 840221-24 No violations or deviations noted Major areas inspected maint program BOARDMAN, J R. JOHNSON, H D., CROSSMAN, H A. Region 4. Dffice of Director 84/03/08 5pp. 22785 153 24X Fichs 50-313,84/03/08.8403260230
- 8402070031 IE Bulletin 84-02. "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl.

 DEYOUNG, R C Director's Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co. of New York, Inc 134pp. 22823 074 24% Fiche 50-000.84/03/12.8402070031

- 8403200169 Forwards QA Program Insp Rept 99900786/83-02 Significance of reported findings should be evaluated to determine acceptability of product or svc provided by vendor W/o encl GAGLTARDO, J E Region 4. Office of Director 84/03/16. ORIFFIN, J M Arkansas Power & Light Co ip 22696 353 24X Fiche 50-313.84/03/16.8403200169
- B402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Byc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 R4X Fishs 50-000,84/03/21,8402090043
- B402090044 IE Info Notice B4-20, "Svc Life of Relays in Safety-Related Bys " Bvc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York: Inc 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044
- R Periodic operating reports & related correspondence
- B403060308 "Annual Radiation Exposure Rept.1983 " W/B40229 ltr HARSHALL.JR Arkanaes Power & Light Co B3/12/31 DEYOUNO.R C Director's Office of Office of Inspection and Enforcement 3pp. 22517 047 24% Fiche 50-313,83/12/31.8403060308
- 8403020081 Monthly operating rept for Jan 1984 W/840215 ltr BRAMLETTLE 8 , MAREHALL J R Arkansas Power & Light Co 84/01/31 BASSET, H 8 Division of Data Automation & Management Information 6pp 22441 318 24% Fichs 50-365 84/01/31,8403020081
- B403300164 Monthly operating rept for Feb 1984 W/840315 ltr BRAMLETT.L 8 , MARSHALL,J R Arkansas Power & Light Co 84/02/29 BASSETT.H B Division of Data Automation & Management Information 7pp 22821 092 24% Fiche 50-368,84/02/29,8403300164
- S Reportable occurrences, LERs & related correspondence
- B403280117 "Analysis of 800624 Loss of Offsite Power Transient at Arkansas Nuclear One Unit 2 " BAYLESS.P D EG&G, Inc FIN A-6234 EGG-NTAP-6309 83/09/30 NRC No Detailed Affiliation Given 46pp 22811 189 24X Fiche 50-358.
- B403280124 "Analysis of 800129 Turbine Trip at Arkansas Nuclear One Unit 2 " BAYLES9,P D E080, Inc FIN A-6234 E00-8AAM-6415 B3/09/30 NRC - No Detailed Affiliation Given 43pp 22811,087 24X Fiche 50-368,83/09/30.8403280124
- B403210032 Part 21 rept re failure of suxiliary feedwater pump drive turbines; Ginpel NPS-4 T&T valve, to close Encl 1tr dtd 840203 sent to listed utils OE notified of affected units in BWR plants
 THEROUX.R R Terry Corp 84/02/22 WGGDRUFF, R W Director's Office, Office of Inspection and Enforcement 6pp. 22706 327 24: Fiche 90-000.84/02/22.8403210032
- 8403090139 LER 84-001-00 on 840128, unit tripped during low power physics testing Caused by one pin peaking factor limit being exceeded due to control element assembly position during testing Procedures modified W/840229 ltr ROGERS, P., MARSHALL, J.R. Arkansas Power & Light Co. 84/02/29, 3pp 22575 045 24X Fiche, 50-368, 84/02/29, 8403090139.
- B403130347 LER 84-002-00 on 840129, during routine surveillances of core protection calculator sys, operations personnel observed that valves of addressable constants did not agree w/valves for Cycle 4 Caused by reactor trip on 840128 W/840302 ltr RUGERS.P., MARBHALL, J.R. Arkansas Power & Light Co. 84/03/02, 4pp. 22607 150 24X Fiche 50-368,84/03/02,8403130347.
- 8403130024 LER 84-003-00 on 840130, unit tripped on low steam generator pressure w/concurrent main steam isolation sys ectuation. Caused by leaking boric acid addition flow control valve 2CV-4926 Valve repaired W/840305 ltr. ROGERS, P., MARSHALL, J.R. Arkanses Power & Light Co. 84/03/05 3pp. 22615:111 24X Fiche 50-368,84/03/05,8403130024.
- B403130324 LER B4-004-00 on 840131, reactor tripped from approx 10X full power Caused by low steam generator level in steam generator B due to manual level control difficulties W/840305 ltr ROMERS, P. MARSHALL, J. R. Arkansas Power & Light Co. 84/03/05 3pp. 22607 140 24X Fiche 50-368,84/03/05.8403130324

- 8403270258 LER 93-050/99X-0 on 831109, diesel generator 2 exhibited erratic performance Caused by bad contacts on droop relay in conjunction w/less than optimum tuning of governor controls Droop relay replaced W/840307 itr
 ROGERS.P. MARSHALL.J R Arkansas Power & Light Co B4/03/07
 DENIBER.P Division of Resident. Reactor Project & Engineering
 Programs 3pp 22772 027 24X Fiche 50-368.84/03/07.8403270258
- B403220020 LER 84-005-00 on 840210 output of Channel A ex-core detector subchannels appeared to saturate at 50 7% power Preamp assembly & filter replaced Testing confirmed proper functioning of subchannels W/840311 ltr RODERS F MARSHALL, JR Arkansas Power & Light Co 84/03/11 3pp 22713 352 24X Fiche 50-368.84/03/11.8403220020
- 8403290127 LER 84-004-00 on 840221 operations personnel recognized that addressable constant updated for core protection calculator Channel C still in progress when Channel D prepared for monthly surveillance testing Procedure changed W/840320 ltr ROQERS P . MARSHALL J R Arkansas Power & Light Co 84/03/20 3pp 22807:078 24X Fiche 50-368.84/03/20,8403290127
- DOCKET 50-369 WILLIAM B MCGUIRE NUCLEAR STATION, UNIT 1

 E NRC Safety Evaluation Report (SER), supple & correspondence
- 8403020317 Forwards Rev 10 to "Analysis of Hydrogen Control Measures at McGuire Nuclear Station," per SSER 7 (NUREG-0422)
 TUCKER H B Duke Power Co 84/02/27 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4 2pp 22441;216 24X Fiche 50-000,84/02/29,8403020317
- --8403020321 Rev 10 to "Analysis of Hydrogen Control Measures at McGuire Nuclear Btation" * Duke Power Co 84/02/29 50pp 22441 218 24X Ficha 50-000, 84/02/29, 8403020317
- F Security, medical, emergency & fire protection plans
- 8403090254 Public version of revised crisis mgt plan implamenting procedures, including Procedures 5 3 4 re scheduling/plan. In gupport group, 5,3,6 re radiological support group & 5,3,7 re technical support group, W/B3/107 ltr & UM Felton memo TUCKER, H B Duke Power Co 83/10/31 271pp 22595:055 24X Fiche 50-000.83/10/31,8403070254
- 8403140231 Public version of revised emergency plan implementing procedures, including Procedures PT/D/A/4600/06 re exercise & drills.RP/D/A/5700/02 re alert & RP/D/A/5700/03 re site area emergency W/831213 ltr & W Felton 840312 release memo GLOVER, M 8 . SAMPLE, M . TUCKER, H 8. Duke Power Co 83/11/28 DENTON, H R. Dffice of Nuclear Reactor Regulation, Director ADENSAM. E Q. Licensing Branch 4 141pp 22637 177 24X Fiche. 50-369, 83/11/28, 8403140231.
- 8403070276 Public version of revised emergency plan implementing procedures, including Procedure RP/0/A/5700/01 re notification of unusual event. EP/0/A/5700/02 re alert & RP/0/A/5700/02 re site emergency W/640123 itr & 840307 memo GLDVER, M.S., GILBERT, Q.D., TUCKER, H.B. Duke Power Co. 84/01/05 DENTON. H.R. Office of Nuclear Reactor Regulation, Director ADENSAM. E. Q. Licensing Branch 4. 102pp 22594 321 24X Fiche 50-369, 84/01/05,8403090276
- 8403070352 Public version of revised emergency plan implementing procedures, including Procedure HP/0/B/1009/05 re first response evaluation of reactor coolant leak & PY/0/A/4600/06 re exercises & drills W/B40210 ltr & UM Felton B40302 memo. FOSTER, J. MCCONNELL, T., TUCKER, H. B. Duke Power Co. 84/01/18 ADENBAM, E. 0. Licensing Branch 4 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 84pp 22565 319 24x Fiche: 50-369, 84/01/19, 8403070352
- B403060225 Rev 11 to crisis mgt plan W/840224 ltr & public info pamphlet. VAU0HN: T.E. Duke Power Co 84/02/02 66pp 22516 189 24X Fiche, 50-000, 84/02/02, 8403060225.
- 8403060106 Changes 0-2 to Emergency Plan Implementing Procedure PT/0/A/4600/11, "Function Check of Emergency Vehicle at Equipment." W/840224 ltr. KGDDNALD.B.A., FGBTER.J., TUCKER.H.S Duke Power Co 84/02/10 DENTON.H R. Office of Nuclear Reactor Regulation, Director AUENSAM.E O. Licensing Branch 4. 32pp 22506.149 24X Fiche: 50-369,84/02/10,8403060106
- 8403160101 Forwards JE Insp Repts 50-369/84-03 & 50-370/84-03 on 840130-31 No violations or deviations identified DANCE.H C Division of Project & Resident Programs 84/02/16. TUCKER.H. B. Duke Power Co 2pp. 22652;341 24X Fiche: 50-369,84/02/16.8403160101

- --B403160111 IE Insp Repts 50-369/84-03 & 50-370/84-03 on B40130-31 No Violations or deviations identified Major areas inspected emergency preparedness area of protective action decisionmaking CLINE, W E Region 2, Office of Director JENKINS, Q R Division of Emergency Preparedness & Materials Safety 64/02/15 3pp 22652 343 24X Fiche 50-369.84/02/16.8403160101
- 8403020254 Ack receipt of 840125 & 831010 ltrs transmitting Revs & & 5 to guard training & qualification plan.respectively Revs consistent w/100FRSO 54(p) & acceptable LEWIS.R C Division of Project & Resident Programs 84/02/29 TUCKER, HB Duke Power Co 2pp 22439 003 24X Fiche 50-369.84/02/29,8403020254
- 8403290275 Forwards IE Insp Repts 50-369/84-02 & 50-370/84-02 on 840213-17 No violations or deviations identified DANCE.H C Division of Project & Resident Programs 84/03/01 TUCKER.H B Duke Power Co 2pp 22800 083 24X Fiche 50-369.84/03/01.8403290275
- --8403290290 IE Insp Repts 50-369/84-02 & 50-370/84-02 on 840213-17 No violations or deviations identified Major areas inspected energency preparedness STODDART, P O Region 2. Office of Director JENKINB, O R Division of Emergency Preparedness & Materials Safety 84/02/29 7pp 22800 085 24% Fiche 50-369,84/03/01,8403290275
- 8403160278 Extends invitation to attend 840316 workshop to discuss 10CFR50. App R requirements & results of recent insp to help resolve misunderstanding associated w/requirements LEWIS.R C Division of Project & Resident Programs 84/03/02 TUCKER, H B Duke Power Co 1p 22660 274 24X Fiche 50-000.84/03/02.8403160278
- 8403120110 Advises that 840116 Rev 16 to physical security plan consistent w/provisions of 10CFR50 54(p) & acceptable LEWIB.R C Division of Project & Resident Programs 84/03/08 TUCKER.H B Duke Power Co 2pp 22588 200 24X Fiche 50-369.84/03/08.8403120110
- 8403270230 Forwards Rev 19 to security plan Rev withheld (ref 10CFR3 21) TUCKER, H B Duke Power Go 84/03/16 O'REILLY, J P Region 2, Office of Director 1p 22772 129 24X Fiche 30-369,84/03/16, 8403270230
- 8403300022 Advises that 831122 Rev 17 to physical secruity plan consistent w/provisions of 10CFR50 54(p) & acceptable LEWIS.R C Division of Project & Resident Programs 84/03/26 TUCKER, H B Duke Power Co 3pp 22822 179 24X Fiche 50-369,84/03/26.8403300022
- P. Operating license stage documents & correspondence
- 8403120210 Forwards Amends 29 & 10 to Licenses NPF-9 & NPF-17, respectively & safety evaluation Amends change Tech Specs re response time for steam line isolation & surveillance requirements for sprinkler sys valves
 ADENBAM.E G Licensing Branch 4 84/02/27 TUCKER,H B Duke Power Co 3pp 22619 310 24X Fiche 50-369,84/02/29,8403120210
- --84031R0213 Amends 29 & 10 to Licenses NPF-9 & NPF-17, respectively, changing Tech Specs re response time for steamline isolation, delating mechanical snubbers & surveillance requirements for sprinkler sys valves ADENSAM, E G Licensing Branch 4 84/02/29 27pp 22619 312 24% Fiche 50-369, 84/02/29, 8403120210
- 8403190257 Forwards "Steam Pressure Suppression Characteristics of Water-Soluble Plastic Hembrane Shielded Ice for Ice Condenser Containment Nuclear Power Plants "
 TUCKER, H B Duke Power Co 84/03/07 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E O Licensing Branch 4 7pp. 22672,102 24% Fiche 50-000,84/03/07.8403190257
- --8403190261 "Steam Pressure Suppression Characteristics of Water-Soluble Plastic Membrane Shielded Ica for Ice Condenser Containment Nuclear Power Plants " Supporting documentation encl SCRABIS.C M Wastinghouse Electric Corp. 83/06/30 125pp 22672 109 24X Fiche 50-000,84/03/07.8403190257

- 8403150156 Forwards proprietary info to support NRC review of proposed amends to Licenses NPF-9 & NPF-17 Info changes operating limitations affected by optimized fuel assembly design for Unit 1/Cycle 2 reload Info withheld (ref 10CFR2 790) TUCKER.H B Dute Power Co 84/03/09 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENBAM.E G Licensing Branch 4 5pp 22643 020 24X Fiche 50-369,84/03/09,8403150156
- 8403290148 Forwards Rev 6 to "McGuire Unit 1 Pump & Valve Inservice Testing Program" & Rev 2 to "McGuire Unit 2 Pump & Valve Inservice Testing Program"

 TUCKER, H B Duke Power Co 84/03/16 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENBAM, E. 0 Licensing Branch 4 1p 22806 036 24% Fiche 50-369, 84/03/16, 8403290148
- --8403290154 Rev & to "McGuire Unit 1 Pump & Valve Inservice Testing Program " * Duke Power Co 84/03/16 13pp 22806 037 24X Fiche 50-369,84/03/16,8403290148
- --8403290164 Rev 2 to "McGuire Unit 2 Pump & Valve Inservice Testing ngram . Duke Power Co = 84/03/16 | 13pp | 22806-050 | 24%
 - Fiche 50-369, 84/03/16, 8403290148
- 840322003B Forwards "Spent Fuel Pools Remark Mod, Safety & Environ Analysis " Analysis supple info to enable detailed safety evaluation of 840217 license amend request TUCKER. H B Duke Power Co 84/03/20 DENTON. H R Office of Nuclear Reactor Regulation, Director ADENSAM. E 9 Licensing Branch 4 ip. 22715 001 24X Fiche 50-369, 84/03/20, 8403220038
- --B403220044 "Spent Fuel Pools Rerack Mod.Bafety & Environ Analysis "
 W/Z6 oversize drawings Aperture cards are available in PDR
 + Duke Power Co 84/03/20 120pp 22715 002 24X
 Fiche 50-369, 84/03/20, 8403220038
- 8403270243 Forwards addi documentation of acceptability of "clear & bright" test proposed in Tech Spec change submitted by 831118 ltr Demonstrations revealed that "clear & bright" more sensitive than "water & sediment" test
 TUCKER.H B Dute Power Co 84/03/20. DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAM.E O Licensing Branch 4 2pp 82772 021 24X Fiche: 50-369, 84/03/20.8403270243.
- 8403290267 Rev to BG1212 application for amend to Licenses NPF-9 & NPF-12 changing listed Tech Spec bases, per Y Hsii & MS Dumenfeld 840315 & i6 telcoms.respectively Mestinghouse proprietary info withheld (ref 10GFR2 790) TUCKER.H B Duke Power Co 84/03/23 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENBAM, E G Licensing Branch 4 3pp 22800 092. 24X Fiche 50-369.84/03/23.8403290267
- --8403270273 Revised proposed Tech Bpecs clarifying & correcting 831212 amends to operating conditions for reactor core, radial peaking factor rept & special repts # Buke Power Co 84/03/23 5pp 22800.075 24X Fiche 50-369,84/03/23,8403270267
- --8403270279 Requests withholding of proprietary info requested by util from public disclosure (ref 100FR2 770) Affidavit AN-76-60 dtd 761202 encl ito /61202 encl JIESEMANN.R A Westinghouse Electric Corp 84/03/14. DENTON.H R Office of Nuclear Reactor Regulation. Director 10pp 22800 100 24% Fiche 50-369.84/03/23.8403290267. WIESEMANN R A
 - 9403270282 Nonproprietary info reflecting use of Rosemount resistance temp detector = Westinghouse Electric Corp | Fiche 50-369,84/03/23,8403270267 84/03/23 59pp 22800 110. 24X
 - Inspection reports, IE Bulletins & correspondence
- 403160110 Forwards IE Insp Repts 50-369/84-01 & 50-370/84-01 on 840123-27 No violations or deviations identified DANCE: H C Division of Project & Resident Programs 84/02/15 TUCKER: H B Duke Power Co 2pp 22652 346 24X Fiche: 50-369, 84/02/15, 8403160110.
- 8403160120 IE Insp Repts 50-369/84-D1 & 50-370/84-D1 on 840123-27 No violations or deviations identified Major areas inspected plant water chemistry & inservice testing of pumps & valves. ROSS.W J Region 2, Office of Director BLAKE, J. J Division of Engineering & Operational Programs 84/02/10. 11pp 22652-348 24% Fiche 50-369.84/02/15,8403160110
- 8403160101 Forwards IE Insp Repts 50-369/84-03 & 50-370/84-03 on B40130-31 No violations or deviations identified. DANCE H C Division of Project & Resident Programs 84/02/16. TUCKER, H B. Duke Power Co 2pp 22652 341 24X Fichs 50-369,84/02/16,8403160101

- --B403160111 IE Insp Repts 50-369/84-03 & 50-370/84-03 on 840130-31 No violations or deviations identified Major areas inspected emergency preparedness area of protective action emergency preparedness area or proceeding Services and decisionmaking CLINE.W E Region 2. Office of Director JENKINS, 0 R Division of Emergency Preparedness & Materials Safety 84/02/15 3pp 22652 343 24X Fiche 50-369.84/02/16.8403160101
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Syc list JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22909 239 24X Fiche 50-000,84/02/28,8401190072
- 8403270275 Forwards IE Insp Repts 50-369/84-02 & 50-370/84-02 on B40213-17 No violations or deviations identified DANCE.H C Division of Project & Resident Programs 84/03/01. TUCKER.H B Duke Power Co 2pp 22800 083 24X fiche 50-369.84/03/01.8403290275 B4/03/01.
- --8403270270 IE Insp Repts 50-349/84-02 & 50-370/84-02 on 840213-17 No violations or deviations identified Major areas inspected: violations of deviations identified in Jo. acres 1...pec-acres managency preparedness and Director JENKINB, G. R. Division of Emergency Preparedness & Materials Safety. 84/02/29 7pp. 22800:085 24% Fiche 50-369,84/03/01,8403290275.
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC," Svc list encl. ORACE.J N. Division of QA, Bafeguards & Inspection Programs (Post B30103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche: 50-000,84/03/02,8402090007
- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 2253 098. 24X Fiche. 50-000.84/03/02,8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases," 102090009 IE Info Notice 84-10, "Repursing or Regionogical Research, Byo list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 119pp 22553 217. 24X Fiche 30-000,84/03/02,8402090009
- 8402070011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl.

 JURDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co. of New York, Inc. 117pp 22553:336 24X Fiche 50-000.84/03/05,8402070011
- 8402070024 IE Info Notice 84-09, Rev 1. "Lessons Learned From Insps of Fire Protection Bafe Shutdown Bys." Svc list encl.
 JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/03/07 Consolidate Edison Co. of New York, Inc. 118pp 22635 049. 24X Fiche 50-000, 84/03/07, 8402070024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PHR Bys " Svc list encl
 JDRDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) 84/03/07 Consolidated Edison Co of New
 York, Inc 118pp. 22584 186. 24X Fichel 50-000.84/03/07.8402070028.
- 8403160297 Ack receipt of 840203 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-369/83-45 % Correct Violations noted in 16 they hepes of 55.55 to 50.50 To 50.
- --8403160304 Ack receipt of 840203 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-369/83-45 & 50-370/83-52, Util will be informed of acceptability of corrective actions at later date LEHIB,R C Division of Project & Resident Programs 84/02/21. TUCKER,H B. Duke Power Co 1p 22660:043, 24X Fichs 30-369,84/03/07,8403160277.
- -8403160313 Responds to NRC 840104 ltr re violations noted in IE Insp Repts 50-369/83-45 & 50-370/83-52 Violation disputed, Bteps involved in surveys of airborne efficient hezards listed. TUCKER, H B Duke Power Co 84/02/03 O'REILLY, J.P. Region 2, Office of Director. 3pp 22660'044 24X Fiche 50-369, 84/03/07, 8403160297
- --8403160317 Forwards IE Insp Repts 50-369/83-45 & 50-370/83-52 on 831206-09 & notice of violation LEMES.R. C. Division of Project & Resident Programs, 84/01/04 TUCKER.H B Duke Power Co 2pp 22660.047. 24X Fiche 50-369.84/03/07.8403160297

- --8403160322 Notice of violation from insp on 831206-07 * Region 2, Office of Director 84/01/04 ip 22660 049 24X Fichs 50-369,84/03/07,8403160297
- --8403160329 IE Insp Repts 50-369/83-45 & 50-370/83-52 on 831206-09 Violation noted failure to peform adequate surveys for release of airborne effluents to unrestricted areas KUZO, 0 B Region 2. Office of Director MONTOUMERY, D N Division of Engineering & Operational Programs 83/12/30 idpp 22660:050. 24X Fichs 50-369.84/03/07.8403160297
- 8402090031 IE Bulletin 84-02. "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Syc list encl DEYGUNG, R C Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000.84/03/12,8402090031
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fichs 50-000,84/03/21,8402090043
- B402070044 IE Info Notice B4-20, "Svt Life of Relays in Safety-Related Bys "Svt list entl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/21 Consolidated Edison Co of New York, Inc 135pp 22733 001 24X Fiche 50-000,84/03/21,8402070044
- R Periodic operating reports & related correspondence
- 8402210130 Monthly operating repts for Jan 1984 W/840215 ltr REAVIS.J.A. TUCKER.H B. Dute Power Co 84/01/31 8pp 22316 347 24X Fiche, 50-369, 84/01/31, 8402210150
- 8403200123 Monthly operating repts for Feb 1784 W/840315 ltr REAVIB, T A., TUCKER, H B Duke Power Co 84/02/29 Bpp 22697 103 24X Fichs 50-369,84/02/29,8403200123
- B. Reportable occurrences, LERs & related correspondence
- 82:1110314 Forwards evaluation of 8:10825 overpressurization of suction lines to turbine driven auxiliary feedwater pump Relief capability may be needed for check valves ZUKOR, D J. Reactor Operations Analysis Branch. 82/11/02 MICHEL8ON.C Director's Office 4pp 22775 231 24% Fiche: 50-369,82/11/02,8211110514
- 8403280332 Forwards preliminary results of natural circulation analyses for 811111 transient at McGuire & 800605 natural circulation low power test at North Anna CHARLTON,T R EG&O, Inc 83/09/22 LITTENEKER,P E Energy, Dept of, Idaho Operations Office 29pp. 22807 259 24X Fiche 50-000,83/09/22,8403280332
- 8403150181 Forwards "Failures in Upper Head Injection Bys " Licensees taking action to resolve setpoint drift on Barton level transmitters No AEOD action recommended ZUKOR, D. J. Reactor Operations Analysis Branch, 84/02/28.
 BEYFRIT, K. V. Reactor Operations Analysis Branch ip 22646, 272
 24X Fiche; 50-000, 84/02/28, 8403150181
- --8403150183 "Failures in Upper Head Injection Sys," AEOD engineering evaluation rept.
 ZUKOR.A Director's Office 84/02/28, Spp. 22646 273 24X
 Fiche 80-000,64/02/28,8403150181
- 8403130332 LER 84-002-00 on 840130, reactor protection sys initiated trip following voltage spike in loop C Caused by failure of loop C lead/lag card of process control sys Faulty card replaced H/840229 ltr.
 NARDDCI, P.B., TUCKER, H.B. Duke Power Co. 84/02/29 3pp 22607:146 24X Fiche. 50-369, 84/02/29, 8403130332
- DOCKET 50-370 WILLIAM B MCQUIRE NUCLEAR STATION, UNIT 2
- E. NRC Bafety Evaluation Report (BER), suppls & correspondence
- 8403020317 Forwards Rev 10 to "Analysis of Hydrogen Control Measures at McQuire Nuclear Station," per SSER 7 (NUREG-0422) TUCKER, H. B. Duke Power Co 84/02/29. DENTON, H. R Office of Nuclear Reactor Regulation, Director ADENSAN, E 9 Licensing Branch 4. 2pp. 22441 216 24X Fiche. 50-000, 84/02/29, 8403020317.

- F Security, medical, emergency & fire protection plans
- 8403090254 Public version of revised crisis mgt plan implamenting procedures including Procedures 5 3 4 re scheduling/planning support group, 5 3 6 re radiological support group 5 3 7 re technical support group W/831107 ltr & UM Felton memo TUCKER, H B Duke Power Co 83/10/31 271pp 22595 085 24X Fiche 50-000.83/10/318403090254
- 8403140231 Public version of revised emergency plan implementing procedures, including Procedures PT/D/A/4600/06 re exercise & drills.RP/D/A/5700/02 re alert & RP/D/A/5700/03 re site area emergency W/831213 ltr & JM Felton 840312 release memo QLQVER.M 8 . SAMPLE.M . TUCKER.H B Duke Power Co B3/11/28 DENTON.H R Office of Nuclear Reactor Regulation. Director ADENSAM.E 0 Licensing Branch 4 141pp 22637 177 24X Fiche 50-369.83/11/28.8403140231
- 8403090276 Public version of revised emergency plan implementing procedures, including Procedure RP/O/A/5700/01 re notification of unusual event. EP/O/A/5700/02 re alert & RP/O/A/5700/03 re site emergency W/B40123 ltr & B40307 memo QLOVER, M 8 , OILBERT, O D , TUCKER, H B Duke Power Co 84/01/05 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENBAM, E G Licensing Branch 4 102pp 22594 321 24X Fichs 50-369,84/01/05,8403090276
- 8403070352 Public version of revised smargency plan implementing procedures, including Procedure HP/0/B/1009/05 re first response evaluation of reactor coolant leak & PT/0/A/4600/06 re exercises & drills W1840210 ltr & UM Felton B40302 memo FOBTER, J. MCCONNELL.T.; TUCKER.H B Duke Power Co 84/01/18 ADENSAM,E Q Licensing Branch 4 DENTON.H R Office of Nuclear Reactor Regulation, Director 84pp 22565 319 24X Fiche 50-369,84/01/18,8403070352
- B403060225 Rev 11 to crisis mgt plan W/840224 ltr & public info pamphlet VAU0HN:T E Duke Power Co 84/02/02 66pp 22516 189 24X Fiche 50-000.84/02/02;8403060225
- 8403060106 Changes 0-2 to Emergency Plan Implementing Procedure PT/0/A/4600/11. "Function Check of Emergency Vehicle at Equipment " W/840224 ltr HCD0NALD.B A, FOBTER.J., TUCKER.H B Duke Power Co 84/02/10 BENTON.H.R Office of Nuclear Reactor Regulation. Director ADENSAM.E G Licemaing Branch 4 32pp 22506 149 24X Fiche 50-369,84/02/10,8403060106
- 8403160101 Forwards IE Insp Repts 50-369/84-03 & 50-370/84-03 on 840130-31 No violations or deviations identified DANCE: H C Division of Project & Resident Programs 84/02/16 TUCKER, H B Duke Power Co 2pp 22652 341 24X Fiche 50-369,84/02/16,8403160101
- --8403160111 IE Insp Repts 50-369/84-03 & 50-370/84-03 on 840130-31 No violations or deviations identified Major areas inspected emergency preparedness area of protective action decisionmaking CLINE, W E Region 2, Office of Director 84/02/15 3pp. 22652 343 24X Fiche 50-369,84/02/16,8403160101
- 8403020254 Ack receipt of 840125 & 831010 itrs transmitting Revs 6 & 5 to guard training & qualification plan, respectively Revs consistent w/10CFR50 54(p) & acceptable LEHIS,R C Division of Project & Resident Programs 84/02/29 TUCKEN,H B Duke Power Co 2pp 22439 003 24X Fichm 50-369,84/02/29,8403020254.
- 8403290275 Forwards IE Insp Repts 50-369/84-02 & 50-370/84-02 on 840213-17 No violations or deviations identified DANCE.H C Division of Project & Resident Programs 84/03/01 TUCKER.H.B DUKE Power Co 2pp 22800 083 24X Fiche 50-369, 84/03/01,8403290275
- --8403290290 IE Insp Repts 50-349/84-02 & 50-370/84-02 on 840213-17 No violations or deviations identified Major areas inspected emergency preparedness STDDDART,P G. Region 2. Office of Director 84/02/29 7pp 22800.085 24X Fiche 50-369,84/03/01.8403290275
- 8403160278 Extends invitation to attend 840316 workshop to discuss 10CFR50. App R requirements & results of recent insp to help resolve misunderstanding associated w/requirements LEWIG.R C Division of Project & Resident Programs 84/03/02 TUCKER.H.B Duke Power Co 1p 22660 274 24X Fiche. 50-000.84/03/02.8403160278
- 8403i20110 Advises that 840116 Rev 16 to physical security plan consistent w/provisions of 10CFR50 54(p) & acceptable LEWIS,R C Division of Project & Resident Programs 84/03/08 TUCKER,H B DUK Power Co 2pp 22588 200 24X Fiche 50-369,84/03/08,8403120110

- 8403270230 Forwards Rev 19 to security plan Rev withheld (ref 100FR73 21) TUCKER.H B Dute Power Co 84/03/16 O'REILLY, J P Region 2, Office of Director 1p 22772 129 24X Fiche 50-349,84/03/16, 8403270230
- 8403300022 Advises that 831122 Rev 17 to physical secruity plan consistent w/provisions of 10CPR50 54(p) & acceptable LEMIS.R C Division of Project & Resident Programs 84/03/26 TUCKER.H B Dute Power Co 3pp 22822 179 24X Fiche 50-369.84/03/26.8403300022
- P Operating license stage documents & correspondence
- 8403130341 Forwards "McGuire Nuclear Station Unit 2 Startup Rept," addressing results of startup testing from initial fuel loading through testing at 90% full power Supplementary repts will be submitted every 3 months until operation TUCKER.H B Duke Power Co 84/02/08 O'REILLY.J F Region 2, Office of Director 1p 22606 129 24X Fithe 50-370,84/02/08,8403130341
- --8403130344 "McGuire Nuclear Station Unit 2 Startup Rept "

 Dute Power Co 84/02/08 352pp 22606 130 24X
 Fiche 50-370,84/02/08,8403130341
- B403120210 Forwards Amends 29 & 10 to Licenses NPF-9 & NPF-17, respectively & safety evaluation Amends change Tech Spect re response time for steam line isolation & surveillance requirements for sprinkler sys valves ADENSAM, E G Licensing Branch 4 B4/02/29 TUCKER, H B Duke Power Co 3pp 22619 310 24X Fiche 50-369.84/02/29.8403120210
- --B403120213 Amends 29 & 10 to Licenses NPF-9 & NPF-17, respectively, changing Tech Specs re response time for steamline isolation deleting mechanical snubbers & surveillance requirements for sprinkler sys valves ADENSAME G Licensing Branch 4 84/02/29 27pp 22619 312 24X Fichs 50-369,84/02/29,8403120210
- --8403120216 Safety evaluation supporting Amends 27 & 10 to Licenses NPF-9 & NPF-17.respectively 9 Office of Muclear Reactor Regulation, Director 84/02/29 4pp 22619 339 24X Fithe 50-369,84/02/29,8403120210
- B403190237 Forwards "Steam Pressure Suppression Characteristics of Water-Soluble Plastic Membrane Shielded Ice for Ice Condenser Containment Nuclear Power Plants "
 TUCKER, H B Duke Power Co 84/03/07 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAH, E Q Licensing Branch 4 7pp 22672 102 24% Fiche 50-000, 84/03/07, 8403190257
- 8403150156 Forwards proprietary info to support NRC review of proposed amends to Licenses NPF-9 & NPF-17 Info changes operating limitations affected by optimized fuel assembly design for Unit i/Cycle 2 reload info withheld (ref 10CFR2 790) TUCKER.H B Duke Power Co. 84/03/09 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAM.E G Licensing Branch 4 5pp 22643 020 24X Fishe 50-369,84/03/09.8403150156
- 8403290148 Forwards Rev 6 to "McGuire Unit 1 Pump & Valve Inservice
 Testing Program" & Rev 2 to "McGuire Unit 2 Pump & Valve
 Inservice Testing Program "
 TUCKER: H B Duke Power Co 84/03/16 DENTON, H R Office of
 Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch
 4 ip 22806 036 24% Fiche 50-369,84/03/16,8403290148
- --8403290164 Rev 2 to "McGuire Unit 2 Pump & Valve Inservice Testing Program" * Dute Power Co 84/03/16 13pp 22806 050 24X Fiche 50-369,84/03/16,8403290148
- 840322003B Forwards "Spent Furl Pools Rerack Mod.Safety & Environ Analysis " Analysis suppls info to enable detailed safety evaluation of 840217 license amend request TUCKER, H B Duke Power Co 84/03/20 DENTON, H R Office of Nuclear Reactor Regulation, Director ADEMSAN, E G Licensing Branch 1p 22715 001 24% Fiche.50-349,84/03/20,8403220038
- --8403220044 "Spent Fuel Pools Rerack Mod, Bafety & Environ Analysis "
 #/26 oversize drawings Aperture cards are available in PDR
 # Dute Power Co 84/03/20 120pp 22715 002 24X
 Fiche 50-369,84/03/20,8403220038
- 8403270243 Forwards addl documentation of acceptability of "clear & bright" test proposed in Tech Spec change submitted by 831118 ltr Demonstrations revealed that "clear & bright" more sensitive than "water & sediment" test
 TUCKER.H B Duke Power Co 84/03/20. DENYON.H R Defice of Nuclear Reactor Regulation. Director ADENSAM.E O Licensing Branch 4 2pp 22772 021 24% Fiche 50-369.84/03/20.8403270243

- 8403290267 Rev to 831212 application for amend to Licenses NPF-9 & NPF-12, changing listed Tech Spec bases, per Y Hsii & MS Dunenfeld 840315 & 16 telcons, respectively Westinghouse proprietary info withheld (ref 10CFR2 790)
 TUCKER, H B Duke Power Co 84/03/23 DENTON, H R Qpfice of Nuclear Reactor Regulation, Director ADENBAM, E C Licensing Branch 4 3pp 22800 092 24X Fiche 50-369, 84/03/23, 8403290267
- --8403270273 Revised proposed Tech Specs charifying & correcting 831212 amends to operating conditions for reactor core, radial peaking factor rept & special repts * Duke Power Co 84/03/23 3pp 22800 095 24X Fiche 50-369,84/03/23.8403270267
- --B403290279 Requests withholding of proprietary info requested by util from public disclosure (ref 10GFR2 770) Affidavit AW-76-60 dtd 761202 eurl
 HIESEMANN,R A Westinghouse Electric Corp B4/03/14 DENTON,H R
 Office of Nuclear Reactor Regulation, Director 10pp 22800 100 24X Fiche: 30-369, 84/03/23,8403290267
- Q Inspection reports, IE Bulletins & correspondence
- 8403140110 Forwards IE Insp Repts 50-369/84-01 & 50-370/84-01 on 840123-27 No violations or deviations identified DANCE.H C Division of Project & Resident Programs 84/02/15 TUCKER.H B Duke Power Co 2pp 22652 346 24X Fiche 50-369,84/02/15,8403160110
- --B403160120 IE Insp Repts 50-369/84-01 & 50-370/84-01 on 840123-27. No violations or deviations identified Major areas inspected plant water chemistry & inservice testing of pumps & valves ROBS. W. J. Region 2. Office of Director BLAKE, J. J. Division of Engineering & Operational Programs 84/02/10 11pp 22652.348 24% Fichs 50-369,84/02/15.8403160110
- 8403140101 Forwards IE Insp Repts 50-367/84-03 & 50-370/84-03 on 840130-31 No violations or deviations identified DANCE.H C Division of Project & Resident Programs 84/02/16 TUCKER,H B Duke Power Co 2pp 22452 341 24X Fiche 50-369.84/02/16.8403160101
- --8403160111 IE Insp Repts 50-369/84-03 & 50-370/84-03 on 840130-31 No violations or deviations identified Mayor areas inspected, emergency preparedness area of protective action decisionmaking CLINE.W E Region 2, Office of Director JENKINS, Q R Division of Emergency Preparedness & Materials Safety, 84/02/15 3pp. 22652 343 24X Fiche 50-369,84/02/16,8403160101
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN, E Division of Emergency Preparedness & Engineering Response (Post 630103) 84/02/28 Consolidated Edison Co of New York, Inc. 115pp 22909 239 24X Fiche 50-000,84/02/28,8401190072
- 8403290275 Forwards 1E Insp Repts 50-349/84-02 & 50-370/84-02 on 840213-17 No violations or deviations identified DANCE.H C Division of Project & Resident Programs 84/03/01 TUCKER.H B Duke Power Co 2pp 22800 083 24X Fichs 50-369.84/03/01.8403290275
- --B403290290 IE Insp Repts 30-369/84-02 t 50-370/84-02 on B40R13-17. No violations or deviations identified, Major areas inspected: emergency preparedness
 STODDART, P. O. Region 2, Office of Director JENKINS, O. R. Division of Emergency Preparedness & Materials Safety, B4/02/29, 7pp 22800 085 24X Fichs 50-369,84/03/01.8403290275
- 8402090007 IE Info Natice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE, J N Division of GA, 6afeguards & Inspection Programs (Post B30103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24% Fiche 50-000.84/03/02.8402090007.
- B402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Bys Valves to Operate " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 122pp 22553 098, 24X Fiche 50-000,84/03/02,8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases," Svc list encl
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103). 84/03/02 Consolidated Edison Co. of New
 York, Inc. 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009

- 8402070011 IE Info Notice 84-17, "Problems H/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl, JORDAN E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Cansolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000.84/03/05, 8402090011
- 8402090024 IE Info Notice 84-09. Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown 8ys " Svc list encl JORDAN: E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York. Inc 118pp 22635 049 24X Fiche 50-000.84/03/07.8402090024
- 8402090028 IE Info Notice 84-18. "Stress Corrosion Cracking in PWR Sys " Syc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8403160297 Ack receipt of 840203 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-369/83-45 & 50-370/83-52 LEWIS.R C Division of Project & Resident Programs 84/03/07. TUCKER, H B Duke Power Co 2pp 22660 041 24X Fiche 50-369.84/03/07.
- --8403160304 Ack receipt of 840203 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-369/83-45 & 50-370/83-52 Util will be informed of acceptability of corrective actions at later date

 LEHTS.R C Division of Project & Resident Programs 84/02/21 TUCKER.H B Duke Power Co 1p 22660:043 24X Fiche 50-369,84/03/07.8403160297
- --9403i603i3 Responds to NRC 840104 ltr re violations noted in IE Insp Repts 30-369/83-45 & 30-370/83-52 Violation disputed Staps involved in surveys of airborne effluent hazards listed. TUCKER.H B Duts Power Co. 84/02/03. O'REILLY, J P Region 2, Office of Director 3pp 22660 044 24x Fiche 50-369, 84/03/07, 8403160297
- --8403160317 Forwards IE Insp Repts 50-349/83-45 & 50-370/83-52 on 831204-09 & notice of violation.
 LENIB,R C Division of Project & Resident Programs 84/01/04 TUCKER,H B Duke Power Co 2pp 22660 047 24X Fiche: 50-349,84/03/07,8403160297
- --84031603R2 Notice of violation from insp on 831206-09
 * Ragion 2, Office of Director 84/01/04 ip 22660 049 24X
 Fiche, 50-369, 84/03/07, 8403160297
- --8403160329 IE Insp Repts 50-369/83-45 & 50-370/83-52 on 831206-09 Violation noted failure to peform adequate surveys for release of airborne effluents to unrestricted areas. RUZO, G B Region 2, Office of Director MONTGOMERY, D M Division of Engineering & Operational Programs 83/12/30 16pp. 22660 050 24X Fichs 50-369,84/03/07.8403160297
- B402070031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Syc list encl DEVOUNG.R C Director's Office of Inspection and Enforcement 84/03/12, Consolidated Edison Co. of New York, Inc 134pp. 22823 094 24X Fichs 50-000.84/03/12.8402090031
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PMR Reactor Cavities " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc. 123pp 22823 229 24X Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84~20, "Svc Life of Relays in Safety-Related 8ys " Svc list encl JORDANIE L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche. 50-000, 84/03/21, 8402090044
- R Periodic operating reports & related correspondence
- 8402210150 Monthly operating repts for Jan 1984 W/840215 ltr REAVIS, J A., TUCKER, H. B. Duke Power Co. 84/01/31 8pp 22316 349. 24X Fiche: 50-369.84/01/31,8402210150
- 8403200123 Monthly operating repts for Feb 1984 W/840315 ltr. REAVIS.T.A., TUCKER.H B Dute Fower Co 84/02/29, 8pp 22697.103 24% Fiche: 50-369.84/02/29.8403200123

- S Reportable occurrences, LERs & related correspondence
- 8403280332 Forwards preliminary results of natural circulation analyses for Billil transient at McGuire & 800605 natural circulation low power test at North Anna CHARLTON, T R 60%0, Inc 83/09/22 LITTENEKER, P E Energy, Dept of. Idaho Operations Office 29pp 22807 259 24X Fiche: 50-000,83/09/22,8403280332
- 8403060232 LER 84-003-00 on 840122, during RCS leak test, reactor trip occurred Caused by personnel error Pressure monitored from instrument independent of trip logic Test procedure revised W/840221 ltr
 NARDOCI, P B. TUCKER. H B Duke Power Co 84/02/21 4pp 22516 094 24X Fiche 50-370.84/02/21,8403060232
- 8403130181 Forwards "Failures in Upper Head Injection Sys " Licensees taking action to resolve setpoint drift on Barton level transmitters No AEOD action recommended ZUKOR, D J Reactor Operations Analysis Branch 84/02/28.

 SEYPRIT.K V Reactor Operations Analysis Branch 1p 22646 272 24X Fiche 30-000,84/02/28,8403130181
- --8403150183 "Failures in Upper Head Injection Sys," AEOD engineering syaluation rept ZUKGRA Director's Office 84/02/28 Spp 22646 273 24X Fiche 50-000,84/02/28,8403150181
- 8403120173 LER 84-002-00 on 840115.both ND trains declared inoperable when breakers for valves 2ND-18 & 2NB-2A closed Caused by personnel error, Procedures revised & personnel counseled W/840229 ltr
 NARDDCI.P B. TUCKER.H B Duke Power Co 84/02/29 4pp 22589.175 24X Fiche, 50-370, 84/02/29, 8403120173.
- 8403130167 LER 84-004-00 on 840115, chemical & vol control pump 2A ran approx 19 minutes w/o suction Caused by val control tank autiet isolation valve inadvertently closing & by personnel error Pump repaired Personnel counseled W/840229 ltr NARDOCI, P B., TUCKER, H B. Duke Power Co. 84/02/29 4pp 22608 112 24X Fiche 50-370,84/02/29,8403130167.
- B403120150 LER 84-006-00 on B40203.digital RPI sys failed, resulting in manual reactor trip Caused by failure of central control card & display card Cards replaced W/B40305 ltr
 NARDDCI, P B . TUCKER, H B Duke Power Co 84/03/05 3pp
 22585 240 24X Fiche 50-370.84/03/05.8403120150
- 8403150138 LER 84-005-00 on 840202, reactor trip initiated, Caused by personnel mistakenly pushing TRIP button Unit stabilized & fast recovery initiated Personnel counseled H/840305 ltr NARDOCI, P B, TUCKER, H B Duke Power Co 84/03/05 4pp 22639, 333 24X Fiche 50-370,84/03/05,8403150138
- 8403190303 Updated RD 370/83-57 shutdown capability never jeopardized & unit could be shut down given fire in annulus w/sprinker isolation valve closed Cause unknown Figure illustrating cable separation encl
 TUCKER.H B Duke Power Co 84/03/07 O'REILLY, J.P. Region 2, Office of Director, 3pp 22673 183 24% Fiche 50-370,84/03/07,8403190303
- DOCKET 50-373 LABALLE COUNTY STATION, UNIT 1
- F Security, medical, emergency & fire protection plans
- 8403200041 Forwards Rev 17 to physical security plan, responding to NRC comments re Rev 14 to plan & addressing measures to secure openings allowing potential access to vital areas Rev withheld (ref 10CFR2.790 & 73 21).

 FARRAR, D L Commonwealth Edison Co B4/02/16 Region 3, Office of Director 1p. 22698 343 24X Fiche 50-373,84/02/16,8403200041
- 8403020207 Forwards order confirming licenses commitments on emergency response capability, based on info provided in util 830414 & 0825 responses to Generic Ltr 82-33. Suppl 1 to NUREG-0737 SCHMENGER, A Licensing Branch 2 84/02/21 FARRAR, D. L. Commonwealth Edison Co 2pp 22494 324 24X Ficher 50-373, 84/02/21, 840302007
- --8403020221 Order confirming licensee 830414 & 0825 commitments on emergency response capability, per Generic Ltr 82-33, Suppl 1 to NUREG-0737 EISENHUT, D G Division of Licensing 84/02/21 Commonwealth Edison Co 7pp 22494 326 247 Fiche 30-373, 84/02/21; 8403020207

- 8403050063 Advises that fire protection sys analysis re RCIC ~ RHR high/low pressure interface completed Analysis process described, including failure mode, acceptance criteria, evaluation results & mods to be performed SCHROEDER.C & Commonwealth Edison Co 84/03/01 DENTON.H R Defice of Nuclear Reactor Regulation, Director 39pp 22487 232 24X Fiche 50-373,84/03/01,8403050063
- 8403120128 Rev 23 to Procedure LAP 820-3, "Offsite Procedure" * Commonwealth Edison Co 84/03/05 24pp 22590 062 24) Fiche 50-373,84/03/05,8403120128
- 8403120025 Notifies of 840323 regional workshop in Rosemont, IL w/all Region III licensees to discuss fire protection safe shutdown requirements Workshop will provide addl guidance r. iOCRR50.App R requirements Agenda encl SPESSARD.R L Division of Emergency Preparedness & Operational Support 84/03/06 REED.C Commonwealth Edison Ce 3pp 22589 264 24% Fiche 50-373,84/03/06.8403120025
- B403140175 Forwards final Interim Repts 1.2 & 3 re fire detection sysper 831423 request & IE Imap Repts 50-373/83-44 & 50-374/83-48 Detector installations meet intent of NFPA & require no compensatory measures
 SCHROEDER.C W Commonwealth Edison Co 84/03/09 DENTON.H R
 OFFice of Nuclear Reactor Regulation. Director App 22625 171
 24X Fiche 50-373.84/03/09.8403140175
- --8403140180 Analysis of fire detector locations at Lasalle County Station, final Interim Rept 1 JOHNSON, W A. SCHULTZ, G R., DALDASBARRA, C. Schirmer Engineering Corp 84/02/21 75pp 22425 193 24% Fiche 50-373,84/03/09, 8403140175
- --8403140183 Analysis of fire detector locations at Lasaile County Station.final Interim Rept 2 BREZINSKI.M B. JDHNSON.W A. SCHULTZ.O R. Schirmer Engineering Corp 84/03/06 65pp 22625 298 24X Fiche 50-373,84/03/09. 8403140175
- --8403140184 Analysis of fire detector locations at Lasalle County Station, final Interim Rept 3
 JOHNBON, W. A., BCHULTZ, O. R., BALDASSARRA, C. Schirmer Engineering Corp. 84/03/08 45pp 22626 012 24X Fiche 50-373,84/03/09,8403140175
- 8403200256 Forwards info & Rev 1 to Protedure LTS-1000-36, "Fire Damper Visual Insp." per NRC request & IE Insp Repts 50-373/83-44 & 50-374/83-48 SCHROEDER.C & Commonwealth Edison Co 84/03/13 DENTON.H R Office of Nuclear Reactor Regulation. Director 3pp 22697 022 24X Fiche 50-373,84/03/13.8403200256
- --8403200263 Rev i to Procedure LT6-1000-36. "Fire Damper Visual Insp "
 * Commonwealth Edison Co 84/03/05 49pp 22697 027 24X
 Fiche 50-373,84/03/13,8403200256
- B403300244 Forwards NRC position re-certain items being appealed by util in fire protection area per B40127 ltr
 SCHWENCER, A Licensing Branch 2 B4/03/14 FARRAR, b L
 Commonwealth Edison Co 7pp 22840 352 24X Fiche 50-373,84/03/14,
 R403300244
- 8403220123 Forwards Rev O to Procedure LTS-1900-35, "Fire Damper Operability Test"
 SCHROEDER, C W Commonwealth Edison Co 84/03/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22716.085 24X Fiche 80-373,84/03/15,8403260123
- ---8403220127 Ray 0 to Procedure LTS-1000-35, "Fire Damper Operability Test"

 * Commonwealth Edison Co 84/03/15 85pp 22716 087 24X
 Fiche 50-373,84/03/15,8403220123
- 8903230075 Ack receipt of 831213 & 22 ltrs describing interim fire prevention/protection compensatory measures, per IE Insp. Repts 50-373/803-44 & 30-374/803-48 SPESSARD.R L. Division of Emergency Preparedness & Operational Support 84/03/19 REED.C Commonwealth Edison Co. ip. 22724 293 24X Fiche 50-173.84/03/19.8403230075
- ~~8403230081 Revises B31123 & 1213 commitment re fire watch training situations addressed in NFPA 516.per IE Insp Repts 50-373/83-44 & 50-274/83-48 ECHROEDER.C.W Commonwealth Edison Co 83/12/22 KEPPLER.J G Region 3. Office of Director. 2pp. 22726 274 24X Fiche 50-373,84/03/19.8403230075

- --8403230087 Responds to NRC 831212 ltr re violations noted in IE Insp Repts 50-373/83-44 & 50-374/83-48 Corrective actions continuous fire watch posted on refuel floor & cable spreading rooms & roving fire watch established SCHROEDER, C.W. Commonwealth Edition Co. 83/12/13 KEPPLER, J.Q. Region 3, Office of birector 3pp. 22726-276 24X Fiche 50-373,84/03/19,8403230075
- 8403200204 Revised emergency plan implementing procedures, including L7P index & Rev 3 to Procedure LZP-1550-6. "Operational Support Ctr Quarterly Surveillance" & Commonwealth Edison Co 84/03/22 13pp 22700 007 24X Fiche 50-373.84/03/22.8403200206

G Adjudicatory correspondence

- 8403260368 Forwards executed signature page for affidavit of M Kaku submitted as attachment to Joint Intervenors 840320 renewal of application for stay REYNOLDS.J R Center for Law in the Public Interest REYNOLDS.J R Joint Intervenors Diablo Canyon DSB 100 84/03/22 PALLADINO,N . GILINSKY,V . ROBERTS.T Commissioners 2pp. 22760 133 24X Fichs 50-275.84/03/22,8403260368
- --8403260369 Executed signature page of affidavit of M Kaku in support of 840320 renewal of application for stay KAKU, M Joint Intervenors Diablo Canyon 84/03/21. ip 22760 i35 24X Fichs 50~275,84/03/22,8403260368
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8403210085 Forwards Amend 64 to FBAR BCHROEDER,C W. Commonwealth Edison Co. 94/03/15 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 22701 001 24X Fiche 50-373,84/03/15.8403210085
- --8403210091 Amend 64 to FSAR Twenty-five oversized drawings enci Aperture cards available in FDR + Commonwealth Edison Co B4/03/31 481pp 22701 003 24X Fiche 50-373,84/03/15,8403210085
- P Operating license stage documents & correspondence
- 8403050119 Forwards supplemental response to Generic Ltr 83-28,
 "Required Actions Based on Generic Implications of Salem
 ATHS Events "
 BARNES, P.L. Commonwealth Edison Co. 84/02/29 DENTON, H.R. Office
 of Nuclear Reactor Regulation, Director 26pp. 22488:084 24X
 Fiche 50-000,84/02/29,8403050119
- 8403130400 Forwards 840210 responses to Generic Ltr 83-35 clarifying TMI Item II K 3 31 Util concurs w/NRC position Item should be closed RYBAK, B Commonwealth Edison Co 84/03/02. EISENMUT, D. Q Division of Licensing 2pp. 22613 143 24X Fichs 50-000, 84/03/02, 8403130400
- 8403200013 Discusses 840308 telcon w/A Bournia re RHR & RCIC high/low pressure interface boundary Lists reasons that full open on valve 2E12-F051A would not be detrimental to low pressure piping SCHRDEDER.C M Commonwealth Edison Co 84/03/13 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp, 22683:358. 24X Fiche 50-373,84/03/13,84/03200013
- 8403150275 Generic Ltr 84-07 to all licenses of BWRs re procedural guidance for pipe replacement at BWRs 8vc list encl EISENHUT.D Q Division of Licensing 84/03/14. Commonwealth Edison Co 20pp 22823 334 24X Fiche 50-000.84/03/14.8403150273
- 8403260122 Discusses differences in Tech Specs per rays to BTS,generic 1trs,NRR requirements & grammatical corrections,Differences between two Tech Specs do not affect adequacy of current Unit 1 Tech Specs SCHROEDER,C M. Commonwealth Edison Co 84/03/21 DENTON,H R. Office of Nuclear Reactor Regulation, Director 1p 22758/132 24% Fiche 50-373,84/03/21,8403260122
- O Inspection reports, IE Bulletins & correspondence
- 8403080114 Forwards IE Insp Repts 50-373/84-04 & 50-374/84-03 on 840131-0203 No noncompliance Identified LITTLE, W S Region 3, Office of Director 84/02/23, REED, C Commonwealth Edison Co 2pp. 22559.273 24X Fichs: 50-373, 84/02/23, 8403080114

- --8403080125 IE Insp Repts 50-373/84-04 & 50-374/84-03 on 840131-0203 No noncompliance identified Major areas inspected licenses action on previous insp findings & 100FRSD 55(e) repts CHRISTNOT.E., WILLIAMS, C C Region 3, Office of Director 84/02/23 3pp 22559 275 24X Fichs 50-373,84/02/23.8403080114
- 8403030043 Forwards Rev O to "Corporate Regulatory Performance Improvement Plan " Plan designed to heighten employee awareness & strengthen corporate ability to improve regulatory performance THOMAS, B Commonwealth Edison Co 84/02/24 KEPPLER, J G Region 3, Office of Director 3pp 22470 139 24X Fiche 50-000,84/02/24,8403050043.
- --8403050044 Rev 0 to "Corporate Regulatory Performance Improvement Plan" * Commonwealth Edison Co 84/02/29 22pp 22490 142 24X Fiche 50-000,84/02/24,8403050043
- 8403030168 Ack receipt of 840120 & 0207 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 30-373/83-41 & 50-374/83-42 STREETER:JF Region 3, Office of Director 84/02/27 REED, C Cammonwealth Edison Co 1p 22489 067 24X Fiche 50-373,84/02/27, page 2016
- --8403050171 Responds to NRC 931207 ltr re violations noted in IE Insp Repts 50-373/83-41 & 50-374/83-42 on 930908,28-29,1020 & 110 Future changes to inboard feedwater check valves will be conducted per GP 3-51 FARRAR, D.L. Commonwealth Edison Co 84/01/20. KEPPLER, J G Region 3. Office of Director 3pp 22489 068 24X Fiche 50-373,84/02/27,8403050168
- --8403050174 Suppls 840120 response to NRC 831207 ltr re violations noted in IE Insp Repts 50-373/83-41 & 50-374/84-42 Corrective actions mod approval ltr checklist & safety-related/ABME code change procedure will be revised FARRAR, D.L. Commonwealth Edison Co 84/02/09 KEPPLER, J 9 Region 3, Office of Director 4pp. 22489 072 24X Fiche 50-373, 84/02/27, 8403050168.
- 8401170072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103), 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22707:237 24X Fiche, 50-000, 84/02/28, 8401170072
- 8403190290 Forwards IE Insp Repts 50-373/83-54 & 50-374/83-57 on B31219-840210 & notice of violation.

 STRECTER, J. F. Region 3, Dffice of Director, 84/02/29 REED, C Commonwealth Edison Co. 2pp 22675 064 24X Fiche 50-373,84/02/29,8403190290
- --8403190293 Notice of violation from insp on 831219-840210 BTREETER.J.F Region 3, Office of Director 84/02/29 2pp 22675.066, 24X Fiche.50-373,84/02/29,8403190290
- --B403190299 IE Insp Repts 50-373/B3-54 & 50-374/B3-57 on B31219-B40210 Noncompliance identified, temp gauge utilized in calculating LPCB pump total dynamic head did not have unique number LANKBBURY.R D , WRIGHT, G , MAURA,F A Region 3, Office of Director. B4/02/27, 10pp. 22675 068, 24X Fiche 50-373,84/02/29, B403190290.
- B402070007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Bvc list encl QRACE.J.N Division of QA. Safeguards & Inspection Programs (Post 830103). B403/02 Consolidated Edison Co of New York, Inc 130pp. 22552 327. 24X Fichs 50-000.84/03/02,8402070007
- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate." Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Rasponse (Post 830103), 84/03/02, Consolidated Edison Co of New York, Inc 122pp 22553: 098 24X Fiche 50-000,84/03/02,8402090008
- B402090009 IE Info Notice 84-15. "Reporting of Radiological Releases" Byc list encl.
 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02. Consolidated Edison Co. of New York. Inc. 119pp. 22553 217. 24X Fiche, 50-000, 84/03/02. 8402090009
- 840319006B Forwards IE Insp Repts 50-373/84-02 & 50-374/84-01 on 840116-0210 & notice of violation.

 SHAFER.W.D. Ragion 3, Office of Director 84/03/02, REED, C Commonwealth Edison Co 2pp, 22671 173 24X Fiche 50-373,84/03/02,840319006B.

- --8403190072 Notice of violation from inep on 840116-0210 SMAFER,W D Region 3, Office of Director 84/03/02 2p 22671 175 24X Fiche 50-373,84/03/02,8403190068
- --B403190076 IE Insp Repts 50-373/84-02 & 50-374/B4-01 on 840116-0210 Noncompliance noted 673 ft elevation of reactor bldg contaminated to level in excess required for posting as controlled area & six valves found unlocked GULDEMOND.W G . GUTHRIE.B C . EVANS.C D Region 3, Office of Director B4/02/27 29pp 22671 177 24X Fiche 50-373,84/03/02,8403190068
- 8402090011 IE Info Notice 84-i7. "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 840313034B Ack receipt of 840215 ltr informing NRC of steps taken to correct violations noted in IE Insp. Repts 50-373/83-44 & 50-374/83-4B Add1 response to 840215 ltr will be submitted following completion of actions on 840127 appeal BPESBARD.R L Division of Engineering 84/03/06 REED.C Commonwealth Edison Co. ip 28616 223 24X Fiche 50-373,84/03/06,840313034B
- --8403130357 Responds to NRC 831212 ltr re violations noted in IE Insp Repts 50-373/83-44 & 50-374/83-48 Corrective actions procedures written to require periodic surveillance of lights Same items should not be categorized as violations REED, C Commonwealth Edison Co 84/02/15 KEPPLER, J Q Region 3, Office of Director 20pp 22616 224 24X Fiche 50-373,84/03/06.8403130348
- 8402090024 IE Info Notice 84-09.Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York. Inc 18pp 22635 049 24X Fiche 50-000.84/03/07.8402090024
- 8402070028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Bys " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000.84/03/07,8402070028
- 8403140175 Forwards final Interim Repts 1.2 & 3 re fire detection sys, per 831123 request & IE Insp Repts 50-373/83-44 & 50-374/83-48 Detector installations meet intent of NFPA & require no compensatory measures
 8CHROEDER, C W Commonwealth Edison Co 84/03/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 22625 191 24X Fiche 50-373.84/03/09.8403140175
- B402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Bafety Bys " Syc list encl
 DEYOUNG:R C Director's Diffice. Office of Inspection and
 Enforcement B4/03/12 Consolidated Edison Co of New York, Inc
 134pp 22823 094 24X Fiche 50-000:B4/03/12:B402090031
- 8403190084 Ack receipt of 840229 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/83-53 & 50-374/83-58 SHAFER, W D Region 3, Office of Director 84/03/13 REED, C Commonwealth Edison Co ip 22669 319 24X Fiche 50-373.84/03/13.840319084
- --B403190090 Responds to NRC B40130 ltr re violations noted in IE Insp. Repts 50-373/83-53 & 30-374/83-58 Corrective actions.control room tag board updated to reflect current status, burned out bulbs replaced & refresher training program developed FARRAR, D. L. Commonwealth Edison Co. B4/02/29. KEPPLER, J. 9 Region 3, Office of Director 5pp. 22669 320 24X Fiche 50-373,84/03/13,8403190084.
- B403200256 Forwards info & Rev 1 to Procedure LTB-1000-36, "Fire Damper Visual Insp," per NRC request & IE Insp Repts 50-373/83-44 & 50-374/83-48 SCHROEDER,C M. Commonwealth Edison Co B4/03/13 DENTON.H R Office of Nuclear Reactor Regulation. Director 5pp 22697 022 24X Fiche 50-373,84/03/13,8403200256
- --8403200263 Rev 1 to Procedure LTB-1000-36, "Fire Damper Visual Insp "
 * Commonwealth Edison Co 84/03/05 48pp 22697 027 24X
 Fiche. 50-373, 84/03/13, 8403200256.
- 8403260225 Documents 840314 distribution of GJ Diederich 840313 memo to RD Walker & W Guldemond in response to 831128 confirmatory action ltr re integrity of discs & valves 8CHROEDER, C. W. Commonwealth Edison Go 84/03/16 KEPPLER, J G Region 3, Office of Director. 4pp 22757 316 24X Fichs 50-373,84/03/16,8403260225

- 8403230075 Ack receipt of 831213 & 22 ltrs describing interim fire prevention/protection compensatory measures.per IE Insp Repts 50-374/803-44 & 50-374/803-48 BPESSARO.R L Division of Emergency Preparedness & Operational Support 84/03/19 REED. Commonwealth Edison Co ip 22726 293 24X Fiche 50-373,84/03/19,8403230075
- ~-B4032300B1 Revises 831123 & 1213 commitment re fire watch training situations addressed in NFPA 516.per JE Insp Repts 50~373/83~44 & 50~374/83~48 SCHRDEDER.C W Commonwealth Edison Co 83/12/22 KEFPLER.J O Region 3. Office of Director 2pp 22726 274 24X Fichs 50~373.84/03/19.8403230075
- --8403230087 Responds to NRC 831212 ltr re violations noted in IE Insp Repts 50-373/83-44 & 50-374/83-48 Corrective actions continuous fire watch posted on refuel floor & cable spreading rooms & roving fire watch established SCHROGER, C W Commonwealth Edison Co 83/12/13 KEPPLER, J 0 Region 3. Office of Director 3pp 22726 296 24X Fiche 50-373,84/03/19,8403230075
- B40323008B Ack receipt of regulatory performance improvement plan
 Periodic meetings requested to discuss progress on program
 & provide feedback
 XEPPLER.J G Region 3. Office of Director 84/03/20 THDMAS, B
 Commonwealth Edison Co ip 22730 161 24X Fiche 50-000, 84/03/20.
- --9403230107 Forwards corporate regulatory performance improvement plan THDMAS,B Commonwealth Edison Co 84/02/24 KEPPLER,J & Region 3. Office of Director 3pp 22730 162 24X Fiche 80-000. 84/03/20,8403230088
- --B403230126 Rev O to "Corporate Regulatory Performance Improvement Plan For Dresdem.Quad Cities.Zion & LaGalle Operating Nuclear Stations & Byron & Braidwood Project Operating Organizations "

 " Commonwealth Edison Co B4/02/29 22pp 22730 165 24X Fiche 50-000.84/03/20,840323008
- 8403260196 Forwards responses to IE Bulletin B3-07. "Apparently Fraudulent Products Sold by Ray Miller. Inc " Guad Cities supplied w/piping matis from Ray Miller. Inc during const Evaluation encl Concerns of IE Bulletin 83-06 satisfied BARNES.P L Commonwealth Edison Co 84/03/20 KEPPLER.J G Region 3. Office of Director. 19pp 22756 185 24X Fiche 50-000.84/03/20.8403/20.
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Past 830103) 84/03/21 Consolidate Edison Co of New York. Inc 123pp 22823 227 24% Fiche 50-000.84/03/21.8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Bys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044
- R Periodic operating reports & related correspondence
- 8403060150 Rev 0 to "Rept of Radioactive Effluents, Jul-Dec 1983 " W/ 840116 ltr +. DIEDERICH, G J Commonwealth Edison Co 83/12/31 KEPPLER, J G Region 3, Office of Director 9pp 22513 337 24X Fiche 50-373, 83/12/31, 8403060150
- 8403080197 "Rept of Occupational Personnel Radiation Doses,1983 "
 W/840227 ltr
 SCOTT.J S Commonwealth Edison Co 83/12/31 13pp 22559:099
 24% Fiche 50-000,83/12/31,8403080197
- 8403220120 Annual whole body external exposures for 1983 W/840316 1tr RYBAK, B Commonwealth Edison Co 83/12/31 7pp 22714 007 24X Fiche 50-000,83/12/31,8403220120
- 8403020138 Monthly operating rept for Jan 1984 W/840215 ltr L1N,D L , DIEDERICH.Q J Commonwealth Edison Co 84/01/31, 31pp 22442 034 24X Fiche 50-373,84/01/31,8403020138
- 8403140261 Monthly operating rept for Feb 1984 W/840309 ltr LIN.D. DIEDERICH.G.J. Commonwealth Edison Co. 84/02/29 16pp 22660 256 24x Fiche 50-973.84/02/29.8403160261

- S Reportable occurrences. LERs & related correspondence
- 8403120080 Updated LER 83-129/03X-1 on 831018.LIS-RR-1 calibr exceeded critical date by 1 day Frequency changed from 18 months to 3 months & not entered on computer Caused by personnel error Surveillance completed W/840210 ltr PRESLEY.K E , DIEDERICH.G J Commonwealth Edison Co 84/02/06 KEPPLER, J G Region 3, 04fice of Director 3pp 22590 301 24X Fiche 50-373.84/02/06.8403120080
- 8403120054 LER 83-048/03X-1 on 830510, mechanical snubber locked between hot & cold settings. Caused by excessive heat in upper drywell Failed snubbers replaced, stroke test performed & temp sys & monitoring plan initiated W/840214 ltr SPENCER D A DIEDERICH G J Commonwealth Edison Co 84/02/14 KEPPLER J G Region 3. Office of Director 3pp 22588 041 24% Fichs 50-373,84/02/14,8403120054
- 8403120095 Updated LER 83-117/03X-1 on 830920 & 30 RHR HX B outlet valve limit suitches temporarily changed, allowing wedge travel to stop W/840215 ltr
 PETERS, M A , DIEDERICH, Q J Commonwealth Edison Co. 84/02/14
 KEPPLER J Q Region 3, Office of Director. 3pp 22585 231, 24X
 Fichs 50-373,84/02/14,8403120095
- 8403010380 Confirms 840228 enforcement conference at Region III ofc to discuss ESF reset function deficiencies, per 840222 discussion Meeting notice encl NORELIUS,C E Division of Project & Resident Programs 84/02/28 REED.C Commonwealth Edison Co 2pp 22434 059 24X Fiche 50-373,84/02/28,8403010380
- 8403120020 LER 84-007-00 on B40203, during surveillance, RCIC initiated while reactor at B9% power Caused by improperly placed ohmaeter Water level & pressure quickly brought under control Technician involved disciplined, H/840301 ltr HESTPHAL, BS, DIEDERICH, GJ Commonwealth Edison Co 84/03/02 App 22586 268 24X Fiche, 50-373, 84/03/02, 8403120020
- 8403230015 LER 84-009-00. on 840219, noncoincident scram occurred from upscale trip on intermediate range monitor (IRM) iA Caused by personnel bumping into IRM IA cable Scram reset & personnel counseled re sensitivity of cables W/840315 ltr BAKER.P E . DIEDERICH, G J Commonwealth Edison Co 84/03/13 3pp 22727 349 24X Fiche 50-373,84/03/13,8403230015
- 8403230017 LER 84-008-00. on B40218, noncoincident scram occurred from upscale trip on intermediate range monitor E Gaused by maint personnel inadvertently bumping cable Scram reset & personnel notified W/B40315 ltr BAKER, P E . DIEDERICH, G J Commonwealth Edison Co 84/03/13 3pp 22726 336 24X Fiche 50-373, 84/03/13, 8403230017
- 8403230027 LER 84-010-00 on 840219, noncoincident scram occurred from upscale trip on intermediate range monitor (IRM) A Caused by inadvertant bumping of IRM by maint personnel Personnel notified of sensitivity of IRM cables W/840315 ltr BAKER, F E . DIEDERICH, G J Commonwealth Edison Co 84/03/13 Gpp 22730 330 24X Fiche 50-373,84/03/13,8403230027.
- 8403190117 LER 84-011-00 on 840213 scram resulted when turbine generator tripped from loss of condenser vacuum Caused by expansion joint in low pressure heater extraction steam line 14A failure New joints installed W/840314 ltr WESTPHAL.8 S. DIEDERICH, C.J. Commonwealth Edison Co. 84/03/14 5pp 22666 268 24X Fiche 50-373.84/03/14,8403190117
- 8403R00032 LER 84-013-00 on 840214 nine of 16 main steam high flow switches found out of spec, in violation of Tech Spec limits Caused by increase in follower drag on Barton 288A switch Instruments recalibr W/840315 ltr REISJ B. DIEDERICH, G. J. Commonwealth Edison Co. 84/03/15. 6pp 22697 118 24X Fiche: 50-373,84/03/15,8403200032
- 8403280204 LER 84-012-00 on 840214.containment leakage limit exceeded Tech Spec limits Caused by misalignment problem Valve realigned M/840315 ltr.
 DUS.R 8., DIEDERICH.O J Commonwealth Edison Co 84/03/15 4pp 22696 350 24X Fiche.50-373.84/03/15.8403200204
- DOCKET 50-374 LASALLE COUNTY STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8403260194 Responds to D9 Eisenhut 840308 ltm to C Reed me BWR 8TB certification Tech Specs accurately reflect plant & FSAR. REED,C Commonwealth Edison Co 84/03/21 DENTON,H R. Office of Nuclear Reactor Regulation, Director 3pp 22756,167 24X Fiche 50-374,84/03/21,8403260194

- F Security, medical, emergency & fire protection plans
- B403200041 Forwards Rev 17 to physical security plan, responding to NRC comments re Rev 14 to plan & addressing measures to secure openings allowing potential access to vital areas Rev withheld (ref 10CFR2 790 & 73 21)
 FARRAR, D. L. Commonwealth Edison Co 84/02/16 Region 3, Office of Director 1p 22678 343 24X Fiche 50-373,84/02/16,8403200041
- 8403080063 Advises that fire protection sys analysis re RCIC RHR high/low pressure interface completed Analysis process described including failure mode acceptance criteria, evaluation results & mods to be performed SCHROEDER.C W Commonwealth Edison Co 84/03/01 DENTON.H R Office of Nuclear Reactor Regulation. Director 37pp 22487 232 24X Fiche 50-373.84/03/01.8403050063
- 8403120128 Rev 23 to Procedure LAP 820-3, "Offsite Procedure," # Commonwealth Edison Co 84/03/05 24pp 22590 062 24X Ficha 50-373,84/03/05,8403120128.
- B403120025 Notifies of 840323 regional workshop in Rosemont, IL w/all Region III licensees to discuss fine protection safe shutdown requirements Workshop will provide addl guidance re incefraco, App R requirements Agenda enci SPESSARD, R. L. Division of Emergency Preparedness & Operational Support. 84/03/06 REED, C. Commonwealth Edison Co. 3pp 22589;264 24X Fiche 50-373,84/03/06,8403120025
- B403140350 Notification of 840312 appeal meeting w/util & Region III in BetheadarMD to discuss fire protection positions Agenda Mnc1 BOURNIA:A Licensing Branch 2 84/03/06 BCHWENCER:A Licensing Branch 2 4pp 22635 194 24X Fiche 50-374, 84/03/06, 8403140350
- B403140175 Forwards final Interim Repts 1.2 & 3 re fire detection syspen 831123 request & IE Insp Repts 50-373/83-44 & 50-374/83-48 Detector installations meet intent of NFPA & require no compensatory measures.

 BCHROEDER.C W. Commonwealth Edison Co 84/03/09 DENTON.H R Office of Nuclear Reactor Regulation, Director, 4pp 22625 191 24X Fiche 50-373,84/03/09,8403140175
- --8403140180 Analysis of fire detector locations at Lasalle County Station final Interim Rept 1 JOHNBON W.A., SCHULTZ, Q R , BALDASSARRA, C Schirmer Engineering Corp 84/02/21 75pp 22625 195 24X Fiche 50-373,84/03/09. 8403140175.
- --8403140183 Analysis of fire detector locations at Lasalle County Btation.final Interim Rept 2 BREZINBXI.M S , JOHNSON.W A , BCHULTZ, G.R. Schirmer Engineering Corp. 84/03/06 65pp 22625 298 24X Fich# 50-373.84/03/09. 8403140175
- --8403140184 Analysis of fire detector locations at Lasalle County Station final Interim Rept 3. JOHNBON W. A., SCHULTZ, G.R., BALDASSARRA, C. Schirmer Engineering Corp. 84/03/08 45pp 22626 012. 24X Fiche 50-373,84/03/09, 8403140175
- 8403200236 Forwards info & Rev 1 to Procedure LT8-1000-36, "Fire Damper Visual Insp." per NRC request & IE Insp Repts 50-373/83-44 & 50-374/83-48 SCHROEDER,C.M. Commonwealth Edison Co 84/03/13 DENYON,H R Office of Nuclear Reactor Regulation, Director. 5pp 22697 022 24X Fiche 50-373,84/03/13,8403200256.
- --8403200263 Rev 1 to Procedure LTS-1000-36, "Fire Damper Visual Insp "
 * Commonwealth Edison Co 94/03/05 48pp. 22697,027 24X
 Fiche: 50-373,84/03/13,8403200256.
- 8403300244 Forwards NRC position re certain items being appealed by util in fire protection area per 840127 itr 8CHMENCER.A. Licensing Branch 2. 84/03/14 FARRAR.D L. Commonwealth Edison Co. 7pp. 22840 352. 24X Fiche 50-373.84/03/14.8403300244
- 8403220123 Forwards Rev O to Procedure LTS-1000-35, "Fire Damper Dperability Test." BCHROEDER, C. M. Commonwealth Edison Co. 84/03/15. DENTON, H R Dffice of Nuclear Reactor Regulation, Director 2pp 22716,085 24X Fiche. 50-373,84/03/15,8403220123

- 8403230075 Ack receipt of 831213 % 22 ltrs describing interim fire prevention/protection compensatory measures, per IE Insp. Repts 50-373/83-44 % 30-374/83-49 BPESSARD.R L Division of Emergency Preparedness & Operational Support 84/03/19 REED.C Commonwealth Edition Co. 1p 22726 293 24X Fiche 50-373.84/03/19.8403230075
- --B403230081 Revises 831123 & 1213 commitment re fire watch training situations addressed in NPPA 516.per JE Insp Repts 50-373/83-44 & 50-374/83-48 BGHRGEDER.C W Commonwealth Edison Co 83/12/22 KEPPLER.J G Region 3. Office of Director 2pp 22726 294 24x Fiche 50-373.84/03/19.8403230075
- --8403230087 Responds to NRC B31212 ltr re violations noted in IE Insp Repts 50-373/83-44 & 50-374/83-48 Corrective actions continuous fire watch posted on refuel floor & cable spreading rooms & roving fire watch established BCHROEDER.C W Commonwealth Edison Co B3/12/13 KEPPLER.J G Region 3. Office of Director 3pp 22726 296 24X Fiche 50-373,84/03/19,8403230075
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8403210085 Forwards Amend 64 to FSAR BCHROEDER,C W Commonwealth Edison Co 84/03/15 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 22701 00: 24X Fiche 50-373,84/03/15,8403210085
- --8403210091 Amend 64 to FSAR Twenty-five oversized drawings encl Aperture cards available in PDR * Commonwealth Edison Co 84/03/31 481pp 22701 003 24X Fiche 30-373, 84/03/15, 8403210085
- P Operating license stage documents & correspondence
- 8403050119 Forwards supplemental response to Generic Ltr B3-2B, "Required Actions Based on Generic Implications of Salem ATWB Events"

 BARNES, P. L. Commonwealth Edison Co. B4/02/29 DENTON, H. R. Offic of Nuclear Reactor Regulation, Director Z6pp 2248B, 084 24X Fiche 50-000, 84/02/29, 8403050119
- 8403060250 Confirms 840229 plans for 840302 meeting in Glan Ellyn, IL to discuss questions raised by autside concerns re facility const NGRELIUS, C E Division of Project & Resident Programs 84/03/01 REED, C Commonwealth Edison Co Ip 22516 160 24X Fiche 50-374, 84/03/01.8403060250
- B403130400 Forwards 840210 responses to Generic Ltr 83-35 clarifying TMI Item II K 3 31 Util concurs w/NRC position Item should be clased RYBAK.B Commonwealth Edison Co. 84/03/02 EISENBUT, D & Division of Licensing 2pp 28613 143 24X Fiche 50-000.84/03/02.
- 8403280287 Requests certification that Tech Specs accurately reflect plant, FBAR, SER analyses & other documentation within 10 days Proposed changes should be identified EIBENHUT, D O Division of Licensing 84/03/08 REED, C Commonwealth Edison Co 2pp 22808 056 24X Fiche 50-374,84/03/08,844030787
- 8403300224 Notification of 840314 meeting w/util in LaSalle County, IL to conduct NRC mgt review of licensee readiness for full power operation Agenda encl BOURNIA.A. Licensing Branch 2 84/03/08 BCHWENCER, A Licensing Branch 2 4pp 22845 031 24X Fiche 50-374, 84/03/08, 8403300226
- 8403200013 Discusses 840308 telcon w/A Bournia Te RHR & RCIC high/low pressure interface boundary Lists reasons that full open on valve 2E12-F051A would not be detrimental to low pressure piping SCHROEDER.C W Commonwealth Edison GO 84/03/13, DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 22683 355 24X Fiche 50-373,84/03/13.8403200013
- 8403260122 Discusses differences in Tech Specs per revs to STS, generic Itrs, NRR requirements & grammatical corrections Differences between two Tech Specs do not affect adequacy of current Unit 1 Tech Specs.

 8CHROEDER, C W Commonwealth Edison Co 84/03/21 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 22758, 132. 24X Ficher 50-373, 84/03/21, 8403260122

Q Inspection reports. IE Bulletins & correspondence

- 8403080114 Forwards IE Insp Repts 50-373/84-04 & 50-374/84-03 on BA0131-02203 No noncompliance identified LITTLE.N S Region 3. Office of Director 84/02/23 REED.C Commonwealth Edison CO 2pp 22559 273 24% Fiche 50-373.84/02/23.
- --9403080125 lE Insp Repts 50-373/84-04 & 50-374/84-03 on 840131-0203 No noncompliance identified Major areas inspected licensee action on previous insp findings & 10CFR50 55(e) repts CHRISTNDT.E. WILLIAMS.C C Region 3. Office of Director 84/02/23 3pp 22559 275 24X Fiche 50-373.64/02/23.8403080114
- 8403050043 Forwards Rev O to "Corporate Regulatory Performance Improvement Plan " Plan designed to heighten employee awareness & strengthen corporate ability to improve Awareness a strength.

 regulatory performance
 THOMAS.B Commonwealth Edison Co 84/02/24 KEPPLER, J & Region
 3. Office of Director 3pp 22490 139 24X Fiche 50-000.84/02/24.
- --8403050046 Rev G to "Corporate Regulatory Performance Improvement
 - # Commonwealth Edison Co 84/02/29 22pp 22490 142 24X Fiche 30-000,84/02/24,8403050043
- B403050148
- --8403050171 Responds to NRC 831207 ltr re violations noted in IE Insp Repts 50-373/83-41 & 50-374/83-42 on 830908, 28-29, 1020 & 1110 Future changes to inboard feedwater check valves will be conducted per QP 3-51 FARRAR, D L Commonwealth Edison Co 84/01/20 KEPPLER, J Q Region 3, Office of Director 3pp 22489 068 24X Fiche 50-373, 84/02/27, 8403050168
- --8403050174 Supple B40120 response to NRC 831207 ltr re violations noted in IE Insp Repts 80-373/83-41 & 50-374/84-42 Corrective actions mod approval ltr checklist & safety-related/ASME code change procedure will be revised FARRAR. B L. Commonwealth Edison Co. 84/02/09 KEPPLER. J G. Region 3. Office of Director 4pp 22489 072 24X Fishe 50-373,84/02/27.8403050168
- 8401170072 IE Info Notice 84~13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl. JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc. 115pp 22707 237 24X Fiche 50-000,84/02/28,8401190072
- 8403190290 Forwards IE Insp Repts 50-373/83-54 & 50-374/83-57 on 831219-840210 & notice of violation STREETER.J F Region 3. Diffice of Director 84/02/29 REED.C Commonwealth Edison Co. 2pp 22675 064 24X Fichs 50-373,84/02/29.8403190290
- --8403190293 Notice of violation from insp on 831217-840210 STREETER, J. F. Region 3, Office of Director 84/02/29 22675 066 24% Fiche 50-373,84/02/29,8403190290
- ---8403190299 IE Insp Repts 50-373/83-54 & 50-374/83-57 on 831219-840210 Noncompliance identified temp gauge utilized in calculating LPCB pump total dynamic head did not have unique number LANKSBURY, R D . HRIGHT, G , MAURA, F A Region 3, Office of Director 84/02/27 10pp. 22675 068 24X Fiche 50-373,84/02/29,8403190290
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC." Svc list encl GRACE.J N Division of GA, Safeguards & Inspection Programs (Post 830103) B4/03/02 Consolidated Edison Co. of New York, Inc 130pp 22552 329 24X Fiche 50-000,84/03/02,8402090007.
- 8402090008 IE Info Notice 84-15, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22593 098 24X Fiche 50-000,84/03/02,8402090008
- 8402070007 IE Info Notice 84-15, "Reporting of Radiological Releases " Svc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc. 119pp 22553, 217 24X Fiche 50-000,84/03/02,8402090009

- 8403190068 Forwards IE Insp Repts 50-373/84-02 & 50-374/84-01 on 840116-0210 & notice of violation SHAFER.H D Region 3. Office of Director 84/03/02 REED,C Commonwealth Edison Co 2pp 22671 173 24X Fiche 50-373,84/03/02.
- --8403190072 Notice of violation from insp on 840116-0210 SHAFER,W D Region 3. Office of Director 84/03/02 2pp 22671 175 24X Fichs 50-373.84/03/02.8403190068
- ~-8403170076 IE Insp Repts 50-373/84-02 & 50-374/84-01 on 840116-0210 Noncompliance noted 673 ft elevation of reactor bldg contaminated to level in excess required for posting as controlled area & six valves found unlocked GULDEMOND.W G . GUTHRIE, S C . EVANS, C D Region 3, Office of Director 84/02/27 29pp 22671 177 24X Fiche 50-373,84/03/02,8403190068
- 8402090011 IE Info Notice 84-17. "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8403130348 Ack receipt of 840215 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/83-44 & 50-374/83-48 Add1 response to 840215 ltr will be submitted following completion of actions on 840127 appeal SPESSARD.R L Division of Engineering 84/03/06 REED.C Commonwealth Edison Co ip 22616 223 24X Fiche: 50-373,84/03/06,8403130348
- --8403130359 Responds to NRC 831212 ltr re violations noted in IE Insp Repts 80-373/83-44 & 50-374/83-48 Corrective actions procedures written to require periodic surveillance of lights 8ome items should not be categorized as violations. REED, C. Commonweelth Edison Co. 84/02/15 KEPPLER, J. & Region 3. Office of Director. 20pp 22616 224 24X Fiche 30-373,84/03/06,8403130348
- 8402090024 IE Info Natice 84-09, Rev 1. "Lessons Learned From Insps of Fire Protection Sefe Shutdown Sys " Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 047 24X Fiche 50-000,84/03/07,8402090024
- 840209002B IE Info Notice 84-18. "Stress Corrosion Cracking in PWR 40209002B IE info Notice Barlo, Constitution of Sys " Svc list encl.
 JORDAN E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/07 Consolidated Edison Co. of New
 York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8403140175 Forwards final Interim Repts 1.2 % 3 re fire detection sysper 831123 request % IE Insp Repts 50-373/83-44 % 50-374/83-48 Detector installations meet intent of NFFA & require no compensatory measures SCHROEDER,C W Commonwealth Edison Co 84/03/09. DENTON,H R. Office of Nuclear Reactor Regulation, Director App 22625:191 24X Ficha 50-373,84/03/09.8403140175
- B402070031 IE Builetin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Befety Bys " Svc list encl
 DEYDUNG: C Director's Office Office of Inspection and Enforcement B4/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000,84/03/12,8402090031.
- 8403190084 Ack receipt of 840229 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/83-53 & 50-374/83-58
 SHAFER.W D Region 3. Office of Director. 84/03/13 REED.C Commonwealth Edison Co ip 22669 319 24X Fiche: 50-373.84/03/13.8403190084
- --8403190090 Responds to NRC 840130 ltr re-violations noted in IE Insp. Repts 50-373/83-33 & 50-374/83-58 Corrective actions control room tag board updated to reflect current status, burned out bulbs replaced & refresher training program developed, FARRAR,D L. Commonwealth Edison Co 84/02/27 KEPPLER,J 9, Region 3. Office of Director 50p. 22669 320 24X Fiche 50-373,84/03/13,8403190084
- B403200256 Forwards info & Rev i to Procedure LTS-1000-36, "Fire Damper Visual Insp," per NRC request & IE Insp Repts 50-373/83-44 & 50-374/83-49 SCHRUEDER, C. W. Commonwealth Edison Co. 94/03/13 DENTON, H.R. Dffice of Nuclear Reactor Regulation, Director 5pp 22697.03 24X Fiche: 50-373, 84/03/13, 8403200256 22497-022

- 8403260225 Documents 840314 distribution of GJ Diederich 840313 memo to RD Halter & W Guldemond in response to 831128 confirmatory action ltr re integrity of discs & valves 8CHRGEDER: C W Commonwealth Edison Co 84/03/16 KEPPLER: J G Region 3. Office of Director 4pp 22757 316 24X Fichs 50-373.84/03/16.8403260225
- 8403230075 Ack receipt of 831213 & 22 ltrs describing interim fire prevention/protection compensatory measures, per IE Insp. Repts 50-373/83-44 & 50-374/83-48 SPESSARD, R L Division of Emergency Preparedness & Operational Support 84/03/19 REED, C Commonwealth Edison Co 1p 22726 293 24X Fiche 50-373,84/03/19,8403230075
- --8403230081 Revises 831123 & 1213 commitment re fire watch training situations addressed in NFPA 516.per IE Insp Repts 50-373/83-44 & 50-374/83-48 BCHROEDER, C W Commonwealth Edison Co 83/12/22 KEPPLER, J G Region 3. Office of Director 2pp 22726 274 24X Ficha: 50-373,84/03/19,8403230075
- --8403230087 Responds to NRC 831212 ltr re violations noted in IE Insp Repts 50-373/83-44 & 50-374/83-48 Corrective actions continuous fire watch posted on refuel filoro & cable spreading rooms & rowing fire watch established BCHROEDER.C W Commonwealth Edison Co 83/12/13 KEPPLER.J O Regton 3. Office of Director 3pp R2726 296 24X Fiche 50-373,84/03/19,8403230075
- 8403230088 Ack receipt of regulatory performance improvement plan
 Peniodic meetings requested to discuss progress on program
 & provide feedback
 KEPPLER.J. O. Region 9. Office of Director 84/03/20 THOMAS, B
 Commonwealth Edison Co 1p 22730 161 24X Fiche 50-000, 84/03/20,
 8403230088
- --8403230107 Forwards corporate regulatory performance improvement plan THOMAB.B. Commonwealth Edison Co 84/02/24 KEPPLER, J 9 Region 3. Office of Director 3pp 22730 162 24X Fiche 50-000, 84/03/20,8403230088
- --8403230126 Rev O to "Corporate Regulatory Performance Improvement Plan For Dresden, Quad Cities, Zion & LaSalle Operating Nuclear Stations & Byron & Braidwood Project Operating Organizations " * Commonwealth Edison Co 84/02/29 22pp 22730 165 24X Fiche, 50-000, 84/03/20, 8403230088.
- B403260196 Forwards responses to IE Bulletin B3-07, "Apparently Fraudulent Products Sold by Ray Miller. Inc " Guad Cities supplied w/piping matls from Ray Miller. Inc during const Evaluation encl Concerns of IE Bulletin B3-06 satisfied BARNES. P L. Commonwealth Edison Ca B4/03/20 KEPPLER. J Q Region 3, Office of Director 19pp 22754 185 24X Fiche 30-000.84/03/20.84093260196
- B402070043 IE Info Notice 84-17, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Syc list encl JORDAN. E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/21 Consolidated Edison Co. of New York, Inc. 123pp. 22823:229 24X Fiche. 50-000. 84/03/21, 8402070043
- 8402070044 IE Info Notice 84-20. "Svc Life of Relays in Bafety-Related Bys " Svc list'encl. JRDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc. 135pp 22733:001, 24X Fiche 50-000,84/03/21,8402070044
- 8 Periodic operating reports & related correspondence
- 8403060150 Rev O to "Rept of Radioactive Effluents, Jul-Dec 1983 " W/ 840116 ltr #: DIEDERICH.O.J Commonwealth Edison Co 83/12/31 KEPPLER, J O Region 3, Office of Director 9pp. 22513 337. 24X Fichs. 50-373,83/12/31.8403060150
- 8403080197 "Rept of Occupational Personnel Radiation Doses, 1983 " W/840227 ltr BCOTT.J.B. Commonwealth Edison Co 83/12/31 13pp 22559 099. 24X Fiche: 50-000.83/12/31.8403080197
- 8403220120 Annual whole body external exposures for 1983 W/840316 ltr RYBAK, B. Commonwealth Edison Co. 83/12/31, 7pp 22716 007 24X Fiche: 50-000,83/12/31,8403220120

S Reportable occurrences, LERs & related correspondence

- 8403120047 LER 84-003-00 on 840202, intended trig on sys auxiliary transformer feed breaker failed to occur Caused by breaker plunger being too short Addl washers installed on plunger assembly W/840302 ltr
 HIETALA, J. J. DIEDERICH, G. J. Commonwealth Edison Co. 84/03/01
 3pp 22589 286 24% Fiche 50-374, 84/03/01, 8403120047
- 8403160266 LER 84-004-00 on 840212. Div 2 isolation signal received, causing secondary containment isolation & standby gas treatment sys to start Caused by blown electrical fuse Fuse replaced W/840306 ltr KDEN19. R. DIEDERICH, 0 J Commonwealth Edison Co 84/03/06 3pp 22661 001 24X Fiche 50-374.84/03/06.8403160266
- 8403190013 PNO-III-84-025 on 840310, unit achieved initial criticality Agreement observed between actual conditions & predicted conditions HALKER, R., SHAFER, W. Region 3, Office of Director 84/03/12 ip 82665-353 24% Fiche 50-374,84/03/12.8403190013
- 8403200212 LER 84-005-00 on B40215, during performance of HPCS inservice testing, pump breaker failed to reclose second time Caused by failure of breaker position switch (33),5218 to close in second cycle Breaker reracked W/840315 ltr KOEN16,R. DIEDERICH,G J Commonwealth Edison Co 84/03/15 3pp 22479 344 24X Fiche 50-374,84/03/15,8403200212
- 8403280023 LER 84-007-00 on 840218, reactor water cleanup isolated on Pump Room A high differential temp Caused by difference in room temp due to misconfiguration of area ventilation sys. Review for corrective actions in progress W/840322 ltr REIS-J 0 . DIEDERICH-0 J Commonwealth Edison Co 84/03/21 9pp 22777 051 24X Fiche 50-374,84/03/21,8403280023
- B403280073 LER B4-006-00 on 840223, reactor water cleanup sys isolated on Pump Room C ventilation differential temp high Caused by normal operating temp gradient across pump rooms due to cold reactor bldg air blasting inlet temp W/840322 ltr REISIJB, DIEDERICH, 0 J Commonwealth Edison Co 84/03/22 Bpp 22777 063 24X Fiche 50-374,84/03/22,8403280073
- T Hearing transcripts on non-antitrust matters
- 8403270320 Transcript of Commission 840323 discussion/possible vote in Washington DC re fuil power DL for La8alle Unit 2 Pp 1-76
 8 Supporting documentation encl
 4 Commissioners 84/03/23 849p 22789 153 24X
 Fiche 80-374,84/03/23,8403270320
- DOCKET 50-382 WATERFORD GENERATING STATION, UNIT 3
- A Application/construction stage documents & correspondence
- B403010262 Further response to FOIA request for documents re Sandia Contract A-1123 & bibliography used by R Bernaro Forwards App A documents FELTON.J M Division of Rules and Records FIN A-1123 83/12/20 RUTLEDGE.P Carolina Environmental Study Group 2pp 22444 069 24X Fiche 50-0006.83/12/20.8403010262
- --8301280380 Responds to 821108 ltr & newspaper article, clarifying distorted & incomplete picture of nuclear accident probabilities & consequences & modeling uncertainties presented in article DIRCKS,W J Office of the Executive Director for Operations 82/12/27 B0008,L House of Rep 4pp 22444.078 24X Fiche 50-000,83/12/20,8403010262
- 8403050269 Notification of cancellation of 840228 meeting w/util & Ebasco in Bethesda, MD to discuss emergency feedwater control sys HILSON, J H Licensing Branch 3 B4/02/16 KNIOHTON, O W Licensing Branch 3, 3pp 22501·106 24X Fiche 50-382,84/02/16,8403050269.
- 8403020205 Forwards info re corrective actions identified during control room design review. Lighting survey results, color code convention & results of control room liveability review encl Lighting mods complete CODK.K W Louisiana Power & Light Co 84/02/28 KNICHTON, O W Licensing Branch 3 12pp. 22440,242 24X Fiche 50-382,84/02/28, 240020205
- B403020333 Forwards "Evaluation of Natural Circulation Cooldown Test Parformed at San Dnofre Nuclear Generating Station." Boron mixing tests in lieu of natural circulation test accepted by updated BER & BBER 5 GOOK, K W Louisiana Power & Light Co B4/02/29 KNIGHTON, G. W Licensing Branch 3 1p 22439:035 24X Fiche 50-000, 84/02/29, 8403020333

- ~-8403020333 "Evaluation of Natural Circulation Cooldown Test Performed at San Onofre Nuclear Generating Station "
 * Combustion Engineering. Inc CEN-259 84/01/31 136pp
 22439 036 24X Fiche 50-000.84/02/29.8403020333
- 8403090032 Final response to FOIA request for five categories of documents re facility Forwards addit documents listed on App A FELTON, J M Division of Rules and Records 84/03/02 LYON, V F Lyon & Kur: 2pp 22592 333, 24X Fiche 50-382,84/03/02,8403090032
- ~-8403070038 Lists areas of contern at facility requiring investigation Ebasco & util failed to address & resolve deficiencies identified by many personnel, including QA documentation reviewers
 # Louisiana Power & Light Co 84/03/02 NRC No Detailed Affiliation Given 2pp 22592 336 24X Fiche SO-382,84/03/02,8403090032
- 8403130446 Confirms that all SQRT files closed Info adequate to close out seismic qualification issue CODK.K W Louisiane Power & Light Co 84/03/02 KNIGHTON.G W Licensing Branch 3 1p 22613 181 24X Fiche 50-382, 84/03/02, 8403130446
- 8403120169 Advises that listed procedures & Tech Specs reviewed, per Generic Ltr 83-28 re post-maint testing of reactor trip sys components Check of vendor & engineering recommendations concluded test guidance incorporated into procedures GGGK-K H Louisiana Power & Light Co 84/03/05 KNIOHTON. Q H Licensing Branch 3 6pp 22590 154 24X Fiche: 50-382, 84/03/05, 8403120169
- 8403120168 Discusses activities & commitments to be completed prior to fuel load Listed open items will be completed prior to 840430 COOK.X W Louisiana Power & Light Co. 84/03/08 KNICHTON, W Licensing Branch 3 6pp 22590 148 24X Fiche 50-382,84/03/08,8403120168
- 8403130170 Responds to Generic Ltr 83-28. Item 4 5 3 re reactor trip sys reliability (sys functional testing) Util participating in C-E Owners Group evaluation Results due by 841203 GOK.K W Louisiana Power & Light Co 84703/08 XNIGHTON, OW Licensing Branch 3 1p 22608 111 24X Fiche 50-382,84703/08. 840330170
- 8403150046 Responds to Item 4 2 of Generic Ltr 83-28 re reactor trip sys reliability (preventative maint & surveillance program for reactor trip breakers) Breaker opening time will be trended monthly to forecast breaker degradation COOK.K W Louisiana Power & Light Co 84/03/08 KNIGHTON.Q W Licensing Branch 3 2pp 22643 136 24X Fiche 50-382.84/03/08, 8403150046
- 8403280062 Notification of 840315 meeting w/util & Ebasco in Bethesda. MD to discuss Tech Specs prior to licensing WILSON, J H Licensing Branch 3 84/03/08 KNIGHTON, G W Licensing Branch 3 3pp 22812 335 24X Fiche 50-382,84/03/08,8403280062
- 8403160020 Informs that facility will employ 17 1 psid setpoint for containment isolation as reflected in current draft Tech Specs, per Item 11 E 4 2 of NUREO-0737 Item should be closed in next SSER COOK, K H Louisiana Power & Light Co 84/03/12 KNIOHTON, G W Licensing Branch 3 2pp 22653 351. 24X Fiche 50-382,84/03/12.
- B40320016B Advises that commitment for vendor review of emergency operating procedures fulfilled, based on meeting TMI Action Item I C 7 requirements COOK, K W Louisiana Power & Light Co 84/03/12 KNIGHTON, O W Licensing Branch 3 1p 22699.351 24X Fiche 50-382, 84/03/12, 840320016B
- 8403200209 Provides justification for interim operation pending complete environ qualification of ex-core neutron flux detectors mfg by Westinghouse COOK: K W Louisians Power & Light Co 84/03/13. KNIOHTON: Q W. Licansing Branch 3 2pp 22686 354 24x Fiche 50-382,84/03/13. 8403200209
- 8402090041 Board Notification 84-050 provides Commission policy statement & proposed rulemaking on environ qualifications EISEMHUT.D & Division of Licensing 84/03/14 Atomic Bafety and Licensing Board Panel 10pp 24X Fichs 50-000.84/03/14.8402090041

- B403210030 Forwards justification for exemption from Type C leak testing, list of isolation valves within essential sys & penetration isometric drawings re finalization of Tech Bpecs in preparation for DL COOK, K W Louisiana Power & Light Co B4/03/16 KNIGHTON, OW, Licensing Branch 3 17pp 22707 016 24X Fiche 50-382,84/03/16,840321030
- 8403270154 Replaces ltr previously issued as M3P84-0431 re activities a commitments to be completed prior to fuel load due to missing page from attachment All open items to be completed by 840430 Anticipates receipt of OL on same date CUOK, K H Louisiana Power & Light Co 84/03/20 KNIGHTON, Q, H Licensing Branch 3 6pp 22770 019 24X Fiche 50-382,84/03/20,8403270154
- 8403260134 Forwards completed operating shift experience forms BARKHURST.R P Louisians Power & Light Co 84/03/22 DENTON, H Office of Nuclear Reactor Regulation, Director 8pp 22756 226 24X Fiche 50-382,84/03/22,8403260154
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- B403050065 Submits info in response to SER Open Item 7 1,2(2), par IE Bulletin 79-27, "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation " Info should enable closeout of SER Item COCK, K W Louisiana Power & Light Co 84/02/27 KNIGHTON, C. W. Licensing Branch 3 2pp 22490 183 24X Fiche 50-382,84/02/27,8403050065
- 8403060306 Supplements add1 info provided in 830805 ltr justifying use of analysis in resolving aging & operability issue to qualify Rosemount 1153A transmitter use at facility.per SBER 5
 COOK, K. N. Louisiana Power & Light Co. 84/03/01 KNIGHTON, O. H. Licensing Branch 3 2pp 22515 355 24X Fiche 50-382,84/03/01,8403050306
- 8403060293 Forwards post-accident sampling sys status rapt per BBER 2. containing updated info on actions & plans COOK. K W Louisiana Power & Light Co 84/03/02 KNIGHTON. 9 W Licensing Branch 3 3pp 22518.126. 24X Fiche. 50-382.84/03/02. 8403060293.
- 8403060337 Advises that SEER 5 provides incorrect listings of CPC penalty factors resulting from rod bow penalty Requests that corrected table of penalty factors be included in next SEER COOK, K M Louisiana Power & Light Co B4/03/02 KNICHTON.O W Licensing Branch 3 1p 22513 336 24X Fiche 50-382, 84/03/02, 840300337
- 8403120186 Requests that NUREO-0737, Item II E 4 2 re containment pressure setpoint be closed in next SSER Facility will employ 1/ 1 psia setpoint, per Tech Specs COCK, K W Louisiana Power & Light Co 84/03/05 KNIGHTON, O W Licensing Branch 3 ip 22585 001 24X Fiche, 50-382, 84/03/05, 8403120186
- B403160020 Informs that facility will employ 17.1 psid setpoint for containment isolation as reflected in current draft Tech Specs, per Item II E 4 2 of NUREO-0737 Item should be closed in next SSER COOK, X W Louisiana Power & Light Co B4/03/12 KNIOHTON, 9 W Licensing Branch 3 2pp 22633.351 24X Fiche: 50-382,84/03/12.
- F Security, medical, emergency & fire protection plans
- 8403130434 "Louisiana Power & Light Co. Waterford 3 Emergency Preparedness Exercise May 25,1983 " * Louisiana Power & Light Co. 83/05/25 378pp. 22609,125. 24x Fiche 50-382,83/05/25,8403130434.
- B403120014 Forwards changes & revs to emergency plan implementing procedures, including EP-2-050 re offeite dose assessment & EP-2-060 re radiological field monitoring M/o encl DRUMHOND:F J Louisiana Power & Light Co B3/08/08 COLLINS, J. T. Region 4, Office of Director 2pp. 22388,034 24X Fiche. 50-382,83/08/08.8403120014.
- B403:30105 Responds to emergancy preparedness appraisal items noted in IR Emergancy Preparedness Appraisal Rept 50-382/83-08. Burvey of site public address sys performed In-plant paging sys reviewed for possible mods CODK.K W Louisians Power & Light Co B3/12/28. JOHNBON.E Region 4, Office of Director ip 22601:300 24X Fiche 50-382, B3/12/28.

- 8403130131 Forwards IE Insp Rept 50-382/83-34 on 831001-1130 No violations or deviations noted JOHNSON, E H Region 4, Office of Director 84/01/18 LEDDICK, R S Louisiana Power & Light Co 2pp 22401 054 24X Fiche 50-382.84/01/18.8403130131
- --8403130140 IE Insp Rept 50-382/B3-34 on 831001-1130 No violations or deviations noted Major areas inspected preoperational test procedure review & test witnessing, MPSI pump performance restest & emergency operating procedure review CONSTABLE.0 L , FLIPPO.T A , CROSSMAN, W A Region 4, Office of Director 84/01/12 opp 22601 056 24X Fiche 50-382,84/01/18,8403130131
- 840303024B Forwards public version of Rev 6 to emergency plan & Rev 3 to emergency plan implementing procedures, including Procedures EP-1-001 re recognition & classification of emergency conditions & EP-1-020 re alert W/840301 memo LEDDICK.R B Louisiana Power & Light Co 84/01/30 Office of Nuclear Reactor Regulation. Director 7pp 22519 283 24X Fiche 50-382,84/01/30,8403050248
- --8403050251 Public version of Rev & to emergency plan * Louisiana Power & Light Co 84/01/30 535pp 22519 290. 24x Fiche 50-382,84/01/30,8403050248.
- --8403050253 Public version of revised amergency plan implementing pracedures, including Procedure EP-1-001 re recognition & classification of emergency conditions, EP-1-020 re alert & EP-1-010 re unusual event ALLENMANS A , BARKHURST, R P Louisiana Power & Light Co 84/01/26 836pp 22521 105 24X Fiche 50-382,84/01/30,8403050248.
- 8403130331 Supple 830727 & 1018 responses to IE Emergency Preparadness Appraisal Rept 50-382/83-08, providing current status of action on emergency preparadness appraisal open items COOK, K. W. Louisiana Power & Light Co. 84/02/01 JOHNSON, E. Region 4, Office of Director Spp. 22614 114 24X Fiche 50-382,84/02/01,8403130331
- 8403050137 Notifies that NRC will provide inspectors to observe ensite aspects of periodic exercises for emergency preparedness Scenario for submission of info listed COLLINB.J T Region 4, Defice of Director 84/02/09 LEDDICA.R S Louisiane Power & Light Co 2pp 22489 100 24X Fiche 50-382,84/02/09,8403050137
- 8403060561 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee, per 8107079 Generic Ltr 81-27 W/o request, entire glan will be placed in PDR KNIGHTON, 0 W Licensing Branch 3 84/02/20 LEDDICK, R 8 Louisiana Power & Light Co 3pp 22552, 269 24X Fiche 50-382,84/02/20,8403060561
- 8402090006 Board Notification 84-034 forwards R Vollmer 840206 memo to D Eisenhut re fire research results concerning fires in electrical cabinets in control room EISENHUT. D 9 Division of Licensing 84/02/23 PALLADING Commissioners 1p 22576 203 24X Fiche 50-000,84/02/23,8402090006
- --8403080316 Recommends that info re fire research results concerning fires in electrical cabinets in control room be submitted for board notification.per NRR Dfc Ltr 19, dtd 821001 Further evaluation of test data required VOLLMER.R.H. Division of Engineering. 84/02/06 EISENHUT.D 0 Division of Licensing 10pp 22376-204. 24X Fiche 50-000.84/02/23.8402090006
- 8403260078 Forwards IE Insp Rept 50-382/84-05 on 840123-27 No violations or deviations identified Status of actions taken re-previously identified insp findings examined JOHNSON, E. H. Region 4. Office of Director 84/02/27 LEDDICK, R 8 Louisiana Power & Light Co. 2pp 22758 274 24X Fiche, 50-382, 84/02/27, 8403260078.
- --8403260087 IE Insp Rept 50-382/84-05 on 840123-27 No violations or deviations identified Major areas inspected radiation protection program & implementing actions for NUREO-0737 action items

 CHAMEY, H. D., MURRAY, B., CROSSMAN, W. A. Region 4, Office of Director, 84/02/27 13pp 22758 276 24X Fiche 50-382,84/02/27,8403260078.
- 8403140191 Forwards technical guidelines required by NUREO-0737, Buppl 1, including guidence on station blackout conditions (Unresolved Bafety Issue A-44), to be considered as response to Generic Ltr 81-04 COOK, K. W. Louistana Power & Light Co. 84/03/05 KNIGHTON, G. W. Licensing Branch 3 337pp. 22621 001 24X Fiche 50-382,84/03/05, 8403140191

- 8403120164 Forwards marked-up corrections to emergency plan implementing procedures per undated Ltr W3F84-0029 & marked-up reve to emergency plan LEDDICK.R S Louisiana Power & Light Co 84/03/08 Office of Nuclear Reactor Regulation, Director 4pp 22589 186 24X Fiche 30-382,84/03/08,8403120164
- --8403120165 Marked-up Rev & to emergency plan implementing procedure, per undated Ltr W3F84-0029 * Louisiana Power & Light Co 84/03/08 7pp 22587 190 24X Fiche 50-382,84/03/08,8403120164
- 8403150075 Forwards 13 ltrs of agreement from chemical industries within 5 miles of facility re toxic chemicals.per emergency plan COOK, K W Louisiana Power & Light Co 84/03/08 KNIGHTON, C W Licensing Branch 3 15pp 22642 333 24X Fiche 50-382.84/03/08, RA0310028
- 8403200161 Lists items addressed by training program.per L Bender request including coordinated training of plant fire brigade & local fire dept.operational precautions & training for mitigating core damage COOK, K W Louisiana Power & Light Co 84/03/15 KNIGHTON, G W Licensing Branch 3 1p 22699 349 24X Fiche 50-382, 84/03/15, 8403200161
- 8403300048 Forwards "Alert/Notification Sys "
 COOK, K W Louisiana Power & Light Co 84/03/28 KNIGHTON, G W
 Licensing Branch 3 3pp 22825 049 24X Fiche 50-382,84/03/28,
- --8403300049 "Alert/Notification Sys " W/four oversized drawings Drawings available in PDR * Louisiana Power & Light Co 84/03/31 3copp 22825 052 24X Fiche 50-382, 84/03/28, 840330048
- G Adjudicatory correspondence
- B403010187 Advises that NRC request for extension of time to B40413 to respond to Joint Intervenors B31212 motion to reopen record unopposed Target fuel load set for 840430 Certificate of Bvc encl CHURCHILL, B W Shaw, Pittman, Potts & Trowbridge CHURCHILL, B W Louisiana Power & Light Co B4/02/28 KOHL, CN, WILBER, HA, JOHNSON, W R Atomic Safety and Licensing Appeal Panel 4pp 22435 298 248 Fiche 50-382, B4/02/28, 8403010187
- 8403080130 Requests G Hill 840110-11 statement re QA deficiencies be forwarded to Q Groesch & author BURBTEIN,C H Joint Intervenors Waterford 84/02/29 PALLADINO,N Commissioners ip 22359 278 24X Fiche: 50-382, 84/02/29, 8403080130
- B4032101B0 Order extending time until 840427 for Commission to act to review ALAB-753 Berved on 840321 CHILK.8 J Office of the Becretary of the Commission DSB 017 84/03/20 PALLADING.N J. QILINSKY.V. ROBERTS.T M Commissioners 1p 2271B 227 24X Fiche 50-382,84/03/20.8403210180
- Q Inspection reports, IE Bulletins & correspondence
- 8403130105 Responds to emergency preparedness appraisal items noted in IE Emergency Preparedness Appraisal Rept 50-382/83-08 Survey of site public address sys performed In-plant paging sys reviewed for possible mods COOK. K W Louisiana Power & Light Co 83/12/28 XXHNSON, E Region 4. Office of Director 1p 22401 300 24X Fiche 50-382, 83/12/28.
- 8403130131 Forwards IE Insp Rept 50-382/83-34 on 831001-1130. No violations or deviations noted JOHNSON, E H Region 4, Office of Director 84/01/18 LEDDICK, R 8 Louisiana Power & Light Co 2pp 22601 054 24X Fiche. 50-382,84/01/18,8403130131
- --B403130140 IE Insp Rept 50-382/B3-34 on B31001-1130 No violations or deviations noted Major areas inspected preoperational test procedure review & test witnessing. HBBI pump performance retest & emergency operating procedure review CONSTABLE.0 L , FLIPPO.T A , CROSSMAN.W A Region 4, Office of Director B4/01/12 App 22601 054 24X Fiche 50-382,84/01/18,8403130131

- 8403130331 Supple 830727 & 1018 responses to IE Emergency Preparedness Appraisal Rept 50-382/83-08. providing current status of action on emergency preparedness appraisal open items COUK.X W Louisiana Power & Light Co 84/02/01 JOHNSON, E Region 4. Office of Director 5pp 22614 114 24X Fiche 50-382, 84/02/01. 84/03130331
- 8403260245 Forwards IE Insp Rept 50-382/84-06 on 840116-20 No violations or deviations identified Concern re lack of comprehensive calibr program for effluent monitors raised JOHNSON, E Region 4, Office of Director 84/02/14 LEDDICK, R 8 Louisiana Power & Light Co 2pp 22756 050 24x Fiche 50-382,84/02/14,8403260245
- --8403260250 IE Insp Rept 50-382/84-06 on 840116-20 No violations or deviations identified Major areas inspected radwaste program & transportation activities, including organization, training & qualifications 8AER.R E . HOLLEY, W L . HURRAY. B Region 4. Office of Director 84/02/14 11pp 22756 052 24X Fiche 50-382.84/02/14.8403260245
- 8403050065 Submits info in response to SER Open Item 7 i 2(2), per IE Bulletin 79-27. "Loss of Non-Class IE Instrumentation & Control Power Sys Bus During Operation " Info should enable cluseout of SER item COOK, K W Louisiana Power & Light Co 84/02/27 KNIGHTON, O W Licensing Branch 3 2pp 22490 183 24X Fiche 50-382,84/02/27,8403050045
- 8403260078 Forwards IE Insp Rept 50-382/84-05 on 840123-27. No violations or deviations identified Status of actions taken re previously identified insp findings examined.

 JDHNSUN, E H Region 4. Office of Director 84/02/27 LEDDICK.R S Louisiana Power & Light Co 2pp 22758 274 24X

 Ficho 50-382.84/02/27.8403260078
- --84032600B7 IE Insp Rept 50-382/B4-05 on 840123-27 No violations or deviations identified Major areas inspected radiation protection program & implementing actions for NUREG-0737 action (tems
 CHANEY, H D, MURRAY, B, CRDBSMAN, W A Region 4, Office of Director 84/02/27 13pp 22758 276 24X Fiche 50-382,84/02/27,8403260078
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list enc!

 JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York. Inc. 115pp 22707 237 24X Fishe 50-000-84/02/28.8401190072
- B402090007 IE Info Notice B4-i4, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list enc! GRACE.J N Division of GA. Bafeguards & Inspection Programs (Post 830103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp. 22552,327 24X Fiche 50-000:84/03/02:8402090007
- 8402070008 IE Info Notice 84-16, "Failure of Automatic Sprinkler 8ys Valves to Operate " Svc list and! JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 122pp 22553 098 24X Fiche 50-000,84/03/02,8402070008
- 402090009 IE Info Notice 84-15. "Reporting of Radiological Releases" Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc. 119pp 22553:217 24X Fiche 50-000;84/03/02;8402090009
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 64/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000.84/03/05.8402090011
- 3402090024 IE Info Notice 84-09, Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22635 049 24X Fiche 50-000, 84/03/07, 8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Sys " Syc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028

- B403190271 Ack receipt of 831207 & 840209 supplemental ltrs informing NRC of steps taken to correct violations noted in IE Insp. Rept 50-382/83-17 implementation of corrective actions will be reviewed during future insp.

 JOHNSON.E H. Region 4, Office of Director B4/03/09 LEDDICK, R 8 Louisiana Power & Light Co. 1p. 22671 301 24X

 Fiche 50-382, 84/03/08, 8403190271
- --B403190272 Responds to NRC B30606 ltr re violations noted in IE Insp. Rept 50-382/83-17 Corrective actions Ebasco Nonconformance Rept 3594 initiated due to lack of info available re erection of structural steel for missile protection GERRETS.T F Louisiane Power & Light Co. 84/02/09 JOHNSON.E Region 4. Office of Director. 3pp. 22671 302 24X Fiche 50-382,84/03/08,8403190271
- 8402070031 IE Bulletin 84-02. "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Byc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 074 24X Fiche: 50-000.84/03/12.8402070031
- 8403160242 Forwards vendor insp repts identifying concerns found by Vendor Program Branch during insp of vendor activities Evaluation of findings re quality & acceptability of product or svc by vendors requested JOHNSON.E H Region 4. Defice of Director 84/03/13. LEDDICK.R S Louisiana Power & Light Co 3pp 22661 026 24% Fiche 50~382.84/03/13.8403160242
- 8403200247 Forwards vendor insp repts identifying concerns noted by Vendor Program Branch during insps of vendor activities Bignificance of reported findings re acceptability of product or svc provided by vendor requested W/o sncl JOHNSON: E H Region 4. Office of Director 84/03/16 LEDDICK, R S Louisiana Power & Light Co 3pp 22696 350 24X Fichs 50-382.84/03/16.8403200247
- 8402070043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PHR Reactor Cavities" Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229. 24X Fiche 50-000,84/03/21,8402070043
- 8402090044 IE Info Notice 84-20. "Bvc Life of Relays in Safety-Related Bys " Bvc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044
- R Periodic operating reports & related correspondence
- 8403020443 Forwards monthly status rept of offsite emergency preparedness for OL reviews for Jan 1984 Changes in FEMA finding dates not caused by delay due to offsite emergency planning issues

 BIRCKB.W J Office of the Executive Director for Operations
 84/02/21 PALLADINO Commissioners 9pp 22492.083 24X

 Fiche 50-000.84/02/21.84030R0443
- 8 Reportable occurrences, LERs & related correspondence
- 8403010069 Second interim significant Const Deficiency Rept 93 re charging & letdown containment isolation valve defect Initially reported on 831202. Corrective action complete. Further testing required Next rept expected by 840701 GERRETS, T.F. Louisians Power & Light Co. 84/02/20. COLLINS, J.T. Region 4. Office of Director. 20p 22435 219 24X Fiche 50-382-84/02/20.8403010069
- B403210032 Part 21 rept re failure of auxiliary faedwater pump drive turbines:0impel NPS-4 T&T valvesto close Encl ltr dtc 840203 sent to listed utils OE notified of affected units in BMR plants
 THEROUX,R R Terry Corp 84/02/22 MODRUFF,R W Director's Office, Office of Inspection and Enforcement opp 22706.327. 24% Fiche 50-000.84/02/22,8403210032
- 8403060196 Fourth interim rept re significant Const Deficiency 92 concerning HP8I sys performance Review of supporting documentation scheduled to be complete by 840309 Final rept will be submitted on 840316
 OERRETS, T.F. Louisiana Power & Light Co. 84/02/24 CDLLINB, J.T. Region 4, Office of Director 2pp 22517 355 24X
 Fiche. 50-382, 84/02/24, 8403060196.
- 8403060258 Final rept of significant Const Deficiency 42-R1 re defect in GE Type HMA auxiliary relays mfg between 1978 & June 1981. Nonconformance Rept H3-3381 initiated, GERRETS, T F Louisians Power & Light Co 84/02/24 COLLINS, J T. Region 4, Office of Director 4pp. 22517.141. 24X Fichs'50-382.84/02/24,8403060258

- 8403060339 Becond interim significant const Deficiency Rept 95 re HPSI pumps A/AB failing to start on safety injection actuation signal final rept will be submitted by 840330 GERRETS.TF Louisians Power & Light Co 84/02/24 COLLINS.JT Region 4. Office of Director 2pp 22517 043 24X Fichs 50-382.84/02/24.8403060339
- B403130311 Final Significant Const Deficiency Rept B8 re overstrassed refueling water storage pool liner/nozzle Initially reported on 831213 Restraints added to condensate storage pool to reduce pipe forces transmitted to liner GERRETS.TF Louisiana Power & Light Co 84/02/27 COLLINS.JT Region 4. Defice of Director 4pp 22408 059 24X Fiche 50-382.84/02/27.8403130311
- 8403130267 Final deficiency rept, Item 151 re hydraulic transient, sheared support/restraint on line Initially reported on 840213 Further investigation indicated condition not reportable per 10CFR50 55(e)
 GERRETS.T F Louisiana Power & Light Co 84/02/28 COLLINS.J T Region 4. Office of Director 2pp 22605 054 24X Fiche 50-382,84/02/28,8403130267
- 8403130303 Final deficiency rept. Item 147 re potential failure of safety injection valve actuators Initially reported on B40202 Valves not yet fully qualified for operational use Incident not reportable per 10CFR50 35(e) GERRETS, T. F. Louisians Power & Light Co. B4/02/29 COLLINS, J T Region 4. Office of Director 2pp 22614 191 24% Fiche: 50-382, 84/02/29, 8403130303
- B403130427 First interim Significant Const Deficiency Rept 99 re safety injection tank isolation valve mechanically binding causing valve motor to trip on overload Valve actuator inspected, repaired & tested Final rept by 8404046

 GERRETS.T F Louisiana Power & Light Co 84/02/29 COLLINS, J T Repion 4. Office of Director 3pp 22614 097 24X

 Fiche 50-382.84/02/29.8403130427
- B403130436 Final Potential Deficiency Rept 149 re sheared velve stems in component cooling water sys Caused by excessive force used to close valves in order to prevent leakage Item not reportable per 10CFR50 55(e)

 OERRETS, T. F. Louisiana Power & Light Co. B4/02/29 COLLING, J T Region 4, Office of Director 2pp 22613 161 24X
 Fiche 50-382,84/02/29,8403130436
- 8403130339 Second interim Significant Const Deficiency Rept 97 re diesel generator B turbocharger failure Official response from Cooper Energy Sycs re cause to be completed by late Mar 1984 Final rept will be submitted on 840406 GERRETB: T F Louisiana Power & Light Co 84/03/01 COLLINB: J T Repion 4. Office of Director 2pp 22617 120 24X Fiche: 50-382, 84/03/01, 8403130339
- 8403190253 Final significant const deficiency rept. Item 32 re stress analysis for welded pipe support attachments not performed prior to fabrication Bergen-Paterson analysis identified 85 supports requiring rev & rework.

 OERRETS: T. F. Louisians Power & Light Co. 84/03/01 COLLINS; J T Region 4, Office of Director. 3pp. 22671 295 24X Fiche. 50-382; 84/03/01; 8403190253
- 8403190368 Second interim Bignificant Const Deficiency Rept 94 rechemical vol control sys heat trace temp drift Corrective action & documentation review scheduled for completion by late Mar 1984, Final rept will be submitted by 840406 OERRETS.T F. Louisiane Power & Light Co 84/03/01 COLLINS, J T Region 4, Office of Director 2pp. 22675 200 24X Fiche: 50-382, 84/03/01, 8403190368
- 8403190262 Final Significant Const Deficiency Rept 83 re heat tracing design defects identified during hot functional testing Capacitors added to high temp cutout modules to prevent spurious or false tripping of device GERRETB.T F Louisiana Power & Light Co 84/03/02, COLLINS.J T Region 4, Office of Director 3pp 22672 059. 24X Fiche: 50-382,84/03/02,8403190262
- 8403190250 Final Potentially Reportable Deficiency Rept 150 rs problem W/alarm setpoints for low temp protection sys Initially reported on 840210. Condition not reportable per 10CFR50 55(s) 9680 Power & Light Co 84/03/09 COLLINS, J. T Region 4. Office of Director. 2pp. 22671:293 24X Fiche: 50-382,84/03/09,8403190250
- B403200022 Interim Significant Const Deficiency Rept. Item 102 re failure to install dowels & shear blocks on emergency feedwater pumps. Initially reported on 840216, Final rept expected by 840406 GERRETS, T.F. Louisiana Power & Light Co. B4/03/09 COLLINS, J. T. Region 4, Office of Director. 3pp. 22698 358, 24X Fiche: 50-382, 84/03/09, 8403200022.

- 8403200267 Second interim rept re Significant Const Deficiency 96, failure of chemical & vol control sys pump Train A to start on safety injection actuation signal Final rept will be submitted by 840330 GERRETS, T F Louisiana Power & Light Co 84/03/07 COLLINS, J T Region 4, Office of Director 2pp 22676 121 24X Ficher 50-382,84/03/09,8403200267
- 8403200276 First interim rept re Significant Const Deficiency 101, traceability of stainless steel instrumentation tubing Insp & tests underway to determine if tubing installed to code requirements Final rept expected by 8404046 GERRETS.T F Louisiana Power & Light Co 84/03/09 COLLINS, J T Region 4. Office of Director 3pp 22697 097 24X Fiche 50-382.84/03/09.8403200276
- 8403270102 Final Deficiency Rept 148 re ASCO solenoids & NAMCO limit suitches Initially reported on 840206 Bolenoids will be replaced to provide tracembility & documentation OERRETB,T F Louisiana Power & Light Co 84/03/09 COLLINS,J T Region 4. Office of Director 2pp 22766 349 24X Fiche 50-382,84/03/09.8403270102
- 8403270206 Seventh interim Significant Const Deficiency Rept 78 re American Bridge Corp structural steel defects Corrective action remains on two nonconformance repts Completion scheduled for Mar 1984 Next rept by 840406 GERRETB, T F Louisians Power & Light Co 84/03/09 COLLINS, J T Region 4. Defice of Director 2pp 22770 282 24X Fiche 50-382.84/03/09,8403270206
- B403270059 Interim significant const deficiency rept, Item 100 reterminations to Knox fuse blocks OE 4,160 kV switchgear All Knox fuse block terminations reinspected Next rept will be submitted by 840406 Also reported per Part 21 OERRETS.TF Louisians Power & Light Co 84/03/12 COLLINS, J T Region 4. Office of Director 3pp 22766 159 24X Fiche 50-382,84/03/12.8403270059
- 8403270202 Final Bignificant Const Deficiency Rept 75 re station battery equalizing charge voltage exceeding coil ratings Initially reported on 840120 Class IE dc equipment evaluated during equalizing charge voltage of 137 8 volt dc GERRETB, T F Louisiana Power & Light Co 84/03/14 COLLINS, J T Region 4. Office of Director 3pp 22770 288 24X Fiche 50-382,84/03/14,8403270202
- 8403270046 Fourth interim Significant Const Deficiency Rept 80 re unsatisfactory stroking of emergency feedwater turbing steam shutoff valves Further testing during post-core hot functional testing required Next rept by 840713 GERRETS, T.F. Louisiana Fower & Light Co. 84/03/15 COLLINS, J. T. Region 4. Office of Director 2pp 22769 342 24X Fiche 30-382,84/03/15,8403270046
- 8403270075 Final Deficiency Rept 146 re A-490 bolts for framing above steam generators Initially reported on 840203 Condition determined not reportable per 10CFR50 55(e) GERETS,TF Louisiana Power & Light Co 84/03/15 COLLINS,J T Region 4. Office of Director 3pp 22766 336 24X Fiche 50-382,84/03/15,8403270095
- 8403270040 First interim Significant Const Deficiency Rept 103 re RADFLEX wall penetrations installed by 8&B Insulation. Inc Insp procedures initiated All RB-B seals installed in wall penetrations will be included in rept Next rept by B40420 OERRETS, T F Louisiana Power & Light Co 84703/16 COLLINS, J T Region 4, Office of Director 5pp 22769 316 24X Fiche 50-382.84/03/16.8403270040
- B403270161 Final rept of Significant Const Deficiency 9B re measuring & test equipment proprem Evaluation process to determine impact of out-of-tolerance condition on safety-related testing completed GERRETS.TF Louisiana Power & Light Co 84/03/16 COLLINS, J T Region 4, Office of Director Spp. 22769 162 24X Fiche 50-382.04/03/16.8403270161

U Congressional/Executive Correspondence

- 8403140204 Responds to 840201 ltr re economic penalties accruing from delays in achieving commercial operation Const Assessment Team conducting insp to determine if completed work in accord w/design documents
 DIRCKS.W J Office of the Executive Director for Operations
 84/03/04 TAUZIN.8 House of Rep 4pp 22637 336 24X
 Ficher 50-382,84/03/06,8403140206
- --8403140208 Requests warliest consideration of util licensing requests
 Delay will be at customers expense
 TAUZIN:8 House of Rep 84/02/01 XENT:8 Office of
 Congressional Affairs. 6pp 22637 360 24X Fiche 50-382;
 84/03/06:8403140206

V Operator Examinations

8403260134 Forwards completed operating shift experience forms BARKHURST, R.P. Louisiana Power & Light Co. 84/03/22 DENTON, H Office of Nuclear Reactor Regulation. Director 8pp 22756 226 24X Fich 50-382,84/03/22,8407260154

DOCKET 50-383 WATERFORD GENERATING STATION, UNIT 4

- A Application/construction stage documents & correspondence
- 840201050B Provides updated status of rev to Westinghouse designed PWR ECGS actuation logic Westinghouse plans completion of evaluation for submittal by mid-Mar 1984 MATTSON.R J Division of Systems Integration (post 811005) 84/01/23 EISENMUT, D Division of Licensing 2pp 22546 007 24X Fichs: 50-000,84/02/27,8402070017

DOCKET 50-387 BUSQUEHANNA STEAM ELECTRIC STATION, UNIT 1

- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8403080179 Fourth partial response to FDIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FDIA Exemption 5) Review of add1 documents subj to request continuing FELTON.J H Division of Rules and Records 84/02/13 ANDERSON.S I Garvey. Schubert. Adams & Barer 7pp 22583 224 24X Fichs 50-000.84/02/13.8403080179.
- --B005130793 Provides status of SER inputs & acceptance reviews for DL & CP applications Schedule should be met
 BURKE, N C Effluent Treatment Systems Branch 80/02/06
 KREGER. W E Assistant Director for Bite Analysis ip 22583 235
 24X Fiche 50-000, 84/02/13, 8403080179
- F Security, medical, emergency & fire protection plans
- 8403090209 Rev 4 to Emergency Plan Implementing Procedure EP-IP-045, "Action Step Emergency Director OSC Coordinator TSC Coordinator." including Rev 37 to table of contents.Rev 16 to forms index & B4030B transmittal W/B40229 ltr # Pennsylvania Power & Light Co 84/02/28 26pp. 22575 089 24X Fiche 30-387.84/02/28.8403090209
- 8403050090 Revised emergency plan implementing procedures, including Rev 37 to table of contents, Rev 16 to forms index & Rev 4 to Procedure EP-IP-043 re PASS 14 7 ml gas sample W/840229 transmittal ltr
 MILLER, D W Pennsylvania Power & Light Co 84/02/29 SCHWENCER, A Licensing Branch 2 25pp 22490 019 24X Fiche 50-387, 84/02/29.
- 8403070231 Responds to 831026 ltr re Change B amended to security training & qualification plan & Changes N & O amended to physical security plan Changes consistent w/10CFR50 54(p) & acceptable MARTIN. T Division of Engineering & Technical Programs 84/02/25 KENYON.B D Fennsylvania Power & Light Co 3pp 22371 244 24X Fiche 50-387.84/02/27,8403070231
- |403050116 Forwards proposed change to physical security plan & proposed Amend 37 to License NPF-14 Amend revises physical security plan & License Condition 2 D Plan change withheld (ref 10CFR2 790)

 CURTIS N W Pennsylvania Power & Light Co B4/03/01 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 22489 159 24X Fiche 50-387.84/03/01.8403050114
- -8403050122 Application for proposed Amend 37 to License NPF-14 revising physical security plan & License Condition 2 D CURTIS:N W Pennsylvania Power & Light Co 84/03/01 1p 22489-141 24X Fiche 50-387.84/03/01.8403050116
- O3140296 Forwards evaluation of 830627 request for approval of Change P to physical security plan Change acceptable SCHMENCER:A Licensing Branch 2 84/03/02 CURTIS,N W Pennsylvania Power & Light Co 4pp 22635 329 24X Fiche 50-387,84/03/02,8403140296
- ### 1403130020 Rev 3 to Emergency Plan Implementing Procedure EP-1P-043 W/B40308 transmittal & receipt form
 ### Pennsylvania Power & Light Co B4/03/07 SCHWENGER, A NRC No Detailed Affiliation Given 3pp 22615 104 24X
 ### Fiche 50-387,84/03/07.8403130020

- 8403130126 Revs to Emergency Plan Implementing Procedures EP-IP-001, EP-IP-002, EP-IP-003, EP-IP-006, EP-IP-007 & EP-IP-008 re smergency classification mgt notification & mgt responsibilities W/840309 tr eponsibilities W/840309 tr e Pennsylvania Power & Light Co 84/03/09 SCHWENCER, A NRC No Detailed Affiliation Given 95pp 22640 219 24X Fiche 80-387,84/03/09,8403150126
- B403190243 Notification of B40418 workshop in King of Prussia.PA to discuss lessons learned from recent App R fire protection safe shutdown insp & topics described in IE Info Notice 84-07 Agenda for workshop enci MURLEY.TE Region 1. Office of Director 84/03/09 0'T00LE.J B Consolidated Edison Co of New York, Inc 35pp 22672'062 24X Fiche 50-000.84/03/09.8403190243
- 8403200292 Forwards Change C to security training & qualification plan Changes do not decrease safeguards effectiveness & can be made w/o prior Commission approval Change withheld (ref 10CFR73 21)

 KENYON. B D Pennsylvania Power & Light Co 84/03/12 MURLEY, T E, Region 1. Office of Director 1p 22696 176 24X

 Fiche 30-387.84/03/12.8403200292
- B403190242 Rev 3 to Emergency Plan Implementation Procedure EP-IP-002
 "Emergency Mgt Notifications " Table of contents, forms
 index & B40313 transmittal ltr encl
 # Pennsylvania Power & Light Co B4/03/13 SCHWENCER, A NRC No
 Detailed Affiliation Glyen 78pp 22671:213 24X
 Fiche B0-387,84/03/13,803190242
- 8403200103 Clarifies cover ltr to Rev 7 to emergency plan (PLA-1940)
 Details provided for manning emergency operation facility
 (EGF) & activation of backup EOF Unit 2 fuel load scheduled
 for 840024 Expeditious approval requested
 CURTIS,N W Pennsylvania Power & Light Co 84/03/13 8CHMENCER.A
 Licensing Branch 2 3pp 22699 096 24X Fiche 50-387,84/03/13,
 8403200103
- 8403200250 Notifies of issuance of Changes P.Q & R to physical security plan Ambiguities in vital equipment list noted in Change P corrected in Changes Q & R KENYON.B D Pennsylvania Power & Light Co 84/03/13 MURLEY, T E Region 1. Office of Director 1p 22691 113 24X Fiche 50-387.84/03/13.8403200250
- 8403190232 Updates schedules for completing safety parameter display systems pency operating procedures & emergency facilities, per Generic Ltr B2-33 Updated emergency procedures will be implemented in Dec 1985 CURTIS.N W Pennsylvania Power & Light Co 84/03/14 SCHWENCER.A Licensing Branch 2 Rpp 22672 032 24X Fiche 50-387,84/03/14, 8403190232
- 8403190346 Advises that Commonwealth of PA will not participate in util emergency exercise during CV84, due to involvement w/other fixed nuclear facilities State will participate in CV85 exercise

 TAYLOR, D. F. Pennsylvania, Commonwealth of, 84/03/15, CRUTCHFIELD Operating Reactors Branch 5 ip 22673 155 24X

 Fiche 50-387,84/03/15,8403190346
- 8403230120 Notifies that State of FA eligible for biennial frequency for participation in radiological emergency preparedness exercise Change from annual exercise requirement would be supported if requested by util KRIMM.R W Federal Emergency Hanagement Agency 84/03/15 JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) ip 22730 336 24X Fiche 50-987,84/03/15,840320120
- I Financial information
- 8403270195 Annual Financial Rept 1983 W/840322 ltr CAMPBELL.R K , CURTIS:N W Pennsylvania Power & Light Co 83/12/31 DENTON:H R Office of Nuclear Reactor Regulation, Director. 53pp 22771 049 24X Fiche 50-387.83/12/31,8403270195
- J Insurance & indemnity information
- 8403060437 Provides present level of onsite property damage insurance for facilities
 CURTIS. NW Pennsylvania Power & Light Co 84/02/29 SALTZMAN, J D
 Assistant Director for State & Licensee Relations 1p. 22518 222
 24X Fiche 50-387,84/02/29,8403060437

K Utility Final Safety Analysis Report (FSAR) & amends

- B403210072 Forwards Amend 56 to application for Class 103 OL.consisting of Rev 34 to FBAR CURTIS,N W Pennsylvania Power & Light Co 84/03/07 SCHWENCER, A Licensing Branch 2 App 22702 278 24X Fiche 50-387, 84/03/07, 8403210072
- ---9403210081 Amend 56 to application for Class 103 DL.consisting of Rev 34 to FBAR CURTIEN W Pennsylvania Fower & Light Co 84/03/09 1p 22702 283 24% Fiche 50-387,84/03/09,8403210072
- --8403210090 Rev 34 to FSAR Twenty-eight oversized drawings encl Drawings available in PDR # Pennsylvania Power & Light Co 84/02/29 760pp 22702 284 24% Fiche 50-367, 84/03/09, 8403210072

P Operating license stage documents & correspondence

- B403010254 Notification of B40222 mesting w/util in Bethesda, MD to discuss proposed changes to standby gas treatment sys Tech Specs PERCH.R Licensing Branch 2 84/02/21 SCHWENCER, A Licensing Branch 2, 3pp 22449 356 24X Fiche 50-387, 84/02/21, 8403010254
- 8403020327 Responds to request for schedule for completion of Reg Quide 1.97 requirements Exceptions to 811113 ltr re equipment replacement will be addressed in May 1984, in response to Generic Ltr 82-33 CURTIB, N W Pennsylvania Power & Light Co. 84/02/29 SCHHENCER, A Licensing Branch 2 ip 22437 207 24X Fiche 50-387,84/02/29. 8403020327
- B403050108 Forwards revised response to Generic Ltr 83-28, "Required Actions Based on Generic Implications of Balem ATMS Events." reflecting updates to Items 1 2 2.2 1.2 4 5 CURTISIN W Pennsylvania Power & Light Co B4/03/01 EISENHUT, D © Division of Licensing 61pp 22485 242 24X Fiche 50-387, 84/03/01,8403050108
- 8403030116 Forwards proposed change to physical security plan & proposed Amend 37 to License NPF-14 Amend revises physical security plan & License Condition 2 D Plan change withheld (ref 19CFR2 790)
 CURTIS,N.W. Pennsylvania Power & Light Co. 84/03/01 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 22489 159 24X Piche, 50-087.84/03/01,8403050116
- --8403050122 Application for proposed Amend 37 to License NPF-14 revising physical security plan & License Condition 2 D CURTIS, N W Pennsylvenia Power & Light Co 94/03/01 1p 22487 161 24X Fiche 50-087.84/03/01.8403050116
- 8403150232 Notification of 840312 meeting w/util in Bethesda.MD to discuss NRC evaluation of detailed control room design review rept PERCH.R L Licensing Branch 2 84/03/05 8CHWENCER.A Licensing Branch R 3pp 22648 360 24X Fiche 50-387.84/03/05,8403150232
- 8403130111 Informs that util will provide supplemental rept to detailed control room design review summary rept by 840301.control implementation schedule for resolution of outstanding issues

 CURTIS, N W Pennsylvania Power & Light Co 84/03/08, SCHWENCER, A Licensing Branch 2 1p 22615 271 24X Fiche 50-387, 84/03/08, 8403130111.
- 8403210072 Forwards Amend 56 to application for Class 103 OL. consisting of Rev 34 to FBAR. CURTIB.N. W Pennsylvania Power & Light Co. 84/03/09 8CHHENCER.A Licensing Branch 2 6pp 22702 278 24X Fiche 50-387,84/03/09. 8403210072
- --8403210081 Amend 56 to application for Class 103 OL.consisting of Rev 34 to FBAR CURTIS,N W Pennsylvania Power & Light Co 84/03/09 ip 22702.283 24X Fiche.50-387,84/03/09,8403210072
- 8403150070 Responds to B31230 requests for response to items identified in EQ&Q technical evaluation rept on conformance to Reg Ouide 1 97 & comments on any assumptions that surpass util B11113 submittal CURTIS,N W. Pennsylvania Power & Light Co 84/03/13 ECHWENCER,A Licensing Branch 2 Epp. 22643 183 24X Fiche 30-387,84/03/13,86013/0070
- 8403150275 Generic Ltr 84-07 to all licensees of BWRs re procedural guidance for pipe replacement at BWRs Svc list encl EISENHUT.D Q. Division of Licensing 84/03/14 Commonwealth Edison Co 20pp. 22823,354 24X Fiche 50-000,84/03/14,8403150275

- 8403190375 Forwards proprietary "Analysis of Feedwater Containment Isolation Valves Following Postulated Pipe Rupture," in response to NRC 830831 request for add1 info Affidavit and1 Rept withheld (ref 100FR2 790) CURTIS,N W Pennsylvania Power & Light Co 84/03/15 8CHWENCER,A Licensing Branch 2 4pp 22674 083 24X Fiche 50-387,84/03/15,8403190395
- 8403200073 Requests that further action on BMR core thermal hydraulic stability be deferred, due to lack of time to review new info presented at 840308 meeting w/NRC CURITE.N W Pennsylvania Power & Light Co 84/03/15 SCHWENCER.A Licensing Branch 2 ip 22699 147 24% Fiche 50-387,84/03/15,840320093
- 8403220102 Forwards revs to FSAR Chapters 6.7 & 1B Revs update containment isolation provisions for facilities & will be incorporated in annual FSAR update in Jul 1984 CURTIE.N W Pennsylvania Power & Light Co 84/03/16 SCHWENCER, A Licensing Branch 2 95pp 22715 184 24X Fiche 50-387,84/03/16. 8403220102
- 8403220137 Rev 3 to Procedure EP-1P-046, "PABS Iodine/Particulate Sample " W/840319 transmittal ltr
 * Pennsylvania Power & Light Co. B4/03/16 SCHWENCER, A NRC No Detailed Affiliation Given 3pp 22716 OBZ 24X Fiche 50-387.84/03/16.8403220137

Q Inspection reports, IE Bulletins & correspondence

- 8403070240 Forwards IE Insp Ropts 50-387/84-06 & 50-388/84-05 on 840124-27 No violations noted MARTIN, T T Division of Engineering & Technical Programs 84/02/17 KENYON, B D Pennsylvania Power & Light Co 2pp 22547 318 24X Fiche 50-387,84/02/17,8403070240
- ---8403070242 IE Insp Repts 50-387/84-06 & 50-388/84-05 on 840124-27 No violation noted Major areas inspected licensee action in closing electrical insp rept findings FINKEL, A , AMPERBON, C J Region i. Office of Director. B4/02/16 5pp 22547 320 24% Fiche 50-387,84/02/17,8403070240
- 8403070301 Forwards IE Insp Repts 50~387/84~02 & 50~388/84-02 on 840116~20 No violations observed Steps taken to correct violation noted in 830827 Itr verified MARTIN.T T Division of Engineering & Technical Programs 84/02/21 KENYON.B D Pennsylvania Power & Light Co 2pp 22546 342 24X Fiche 50-387,84/02/21,8403070301
- --8403070306 IE Insp Repts 50-387/84-02 & 50-388/84-02 on 840116-20 No violations identified Hajor areas inspected radiation protection program & preoperational testing, including licenses action on previous finding & training NIMITZ.R L , SHANBAKY, M Region I, Office of Director 84/02/13 10pp 22546 344 24X Fiche 50-387.84/02/21.8403070301
- 8403060175 Responds to IE Bulletin 83-08 Circuit breakers w/
 undervoltage trip attachments not used in safety-related
 applications in Unit 1 Subj attachments installed in Unit 2
 will be removed from safety-related applications
 CURTIS,N W Pennsylvania Power & Light Co 84/02/27 MURLEY,T E
 Region 1, Office of Director 2pp 22518 267 24X
 Fiche. 50-387,84/02/27,8403040175
- 8401170072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/20 Consolidated Edison Co of New York Inc 115pp 22907 239 24X Fiche 50-000.04/02/28.8401170072
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl GRACE, J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison CO of New York, Inc 130pp 22552 329 24% Fiche 50-000,84/03/02,8402090007.
- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Bys Valves to Operate" Svc list encl JURDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. J22pp 22553 098 24X Fiche 50-000,84/03/02,8402090008
- 8402090009 IE Info Notice 84~15, "Reporting of Radiological Releases" Byc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 119pp 22553 217 24X Fiche 50-000 84/03/02 8402090009

- 8402090011 IE Info Natice 84~17, "Problems W/Liquid Nitrogen Coaling Components Below Nil Ductility Temp " Svc list encl JURDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000.84/03/05.8402090011
- 8402090024 IE Info Notice 84-09, Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Bys." Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22635 049 24% Fiche 50-000.84/03/07.8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Sys " Syc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/07 Consolidated Edison Co of New York, Inc. 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8403150053 Forwards IE Insp Rept 50-387/84-11 Enforcement conference scheduled for 840313 to discuss inoperability of MPCI & RCIC sys on 940126 resulting in overflow of condensate storage tank
 STARGSTECKI, R Division of Project & Resident Programs 64/03/08
 KENYON, 8 D Pennsylvania Power & Light Co 2pp 22641 015 24X
 Ficks 50-387/84/03/08.8403150053
- --8403130060 IE Imsp Rept 50-387/84-11 on 840221-24 Major areas inspected sys lineup problems resulting in HPCI sys & RCIC sys insperability PLISCOLL COMPILE, C., JACOBS, R. Region 1, Office of Director 84/03/08 App. 22641 017 24X Fichs. 50-387, 84/03/08.8403150053
- 8402090031 IE Bulletin 84-02. "Failures of GE Type HFA Relays in Use in Glass IE Safety Bys " 8vc list encl.
 DEYOUND, R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp. 22823 094 24X Fiche 30-000/84/03/12/8402090031
- 8403190360 Ack receipt of 840225 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-387/83-31 & 50-388/82-31

 MARTIN.T T Division of Engineering & Technical Programs 84/03/13 KENYON.II D Pennsylvania Power & Light Co ip 22673 312 24X Fiche 50-387,84/03/13.8403190360.
- --8403170366 Responds to NRC 840127 itr re violations noted in IE Insp Repts 50-387/83-31 & 50-388/83-31 Corrective actions status repts for Nonconformance Repts 83-779 & 83-1190 received by GC supervisor on 840201 & 0131, respectively MENYON, B D Pennsylvania Power & Light Co 84/02/25 MARTIN, T T Division of Engineering & Technical Programs 3pp 22673 313 24X Fiche 50-387,84/03/13,8403190360
- 8403220128 Act receipt of 840225 ltm informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-387/83-30 & 50-388/93-25
- MARTIN, T T Division of Engineering & Technical Programs 84/03/13 KENVON, B D Pennsylvania Power & Light Co ip 22716 014 24X Fiche. 50-387, 84/03/13, 8403220128
- --8403220135 Responds to NRC 840126 ltr re violations noted in IE Insp Repts 50-387/63-30 & 50-388/83-25 Corrective actions Temporary Setpoint Changes 82-028T & 82-029T made into germanent setpoint changes KENYON.8 D Pennsylvania Power & Light Co 84/02/25 HARTIN.T T Division of Engineering & Technical Programs 4pp 22716-015 24x Fiche 50-387.84/03/13.8403220128
- 8403290116 Forwards IE Insy Repts 50-387/84-05 & 50-388/84-06 on 840130-0203 & notice of violation MARTIN,T T. Division of Engineering & Technical Programs 84/03/13 KENYON,B D Pennsylvania Power & Light Co 2pp 22806 292, 24X Fiche 50-387,84/03/13,8403290116
- --B403290119 Notice of violation from insp on B40130-0203 * Region 1, Dffice of Director. B4/03/13 1p 22806 294, 24X Fiche 50-387.84/03/13,B402290116
- --8403270120 IE Insp Repts 50-387/84-05 & 50-388/84-06 on 840130-0203 Noncompliance noted failure to follow GC procedure for radiochemistry to determine instrument operating voltage KOTTAN.J J. ZIBULSKY.H., HOPAN.R. Region 1. Office of Director 84/03/07 Bpp. 22806 295. 24X Fiche 50-387,84/03/13,8403270116
- 8403270140 Forwards IE Insp Repts 50~387/83-29 & 50~388/83-32 on 831219-840130 & notices of violation & deviation, Uncorrected repetitive trips of standby gas treatment fans during Unit 2 Gold Functional Test P200 18 noted STAROSTECKI.R Division of Project & Resident Programs 84/03/14 KENYON, B D Fennsulvania Power & Light Co 2pp. 22806 011 24% Fiche. 50-387.84/03/14, 8403290140

- ~-8403290142 Notice of violation from insp on 831219-840130 # Region I. Office of Director 84/03/14 1p 22806 013. 24x Fiche 50-387,84/03/14,8403290140
- --8403290149 Notice of deviation from insp on 831219-840130 * Region I. Office of Director 84/03/14 ip 22806 O14 24x Fiche 50-387,84/03/14,8403290140
- --B403290155 IE Insp Repts 50-387/83-29 & 50-388/83-32 on 831219-840130 Violation identified conditions adverse to quality not promptly identified & corrected Deviation identified failure to ment FSAR commitment for automatic depressurization sys JACOB5:R , PLISCO, L. Region 1, Office of Director MCCABE.E C Division of Project & Resident Programs 84/02/24 21pp, 22804 015 24X Fiche, 50-387,84/03/14,8403270140
- B403220033 Ack receipt of 840301 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-387/83-23 STAROSTECKI, R Division of Project & Resident Programs, 84/03/15 KENYON, B D Pennsylvanis Power & Light Co ip 22712 325 24X Fichs 50-387,84/03/15,8403220033
- --B403220041 Responds to NRC 840104 ltr re violations noted in IE Insp.
 Rept 50-387/83-23 Corrective actions total responsibility
 assumed for design change process & program for processing
 FSAR change requests adopted
 KENYON.B D Pennsylvania Power & Light Co 84/03/01
 STAROSTECKI.R Division of Project & Resident Programs Jpp
 22712 326 24X Fiche 50-387,84/03/15,8403220033
- 8403220069 Completes response to IE Bulletin 83-07, "Apparently Fraudulant Products Sold by Ray Miller, Inc" & two suppls No Ray Miller Inc mati installed Nuclear Energy Svc.inc supplied ultrasonic calibr blocks CURTIS:N W Pennsylvania Power & Light Co B4/03/16 MURLEY, T.E. Region 1: Office of Director 99p 22712 275 24x Fiche 50-387,84/03/16,8403220069,
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl, JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc 123pp 22823 229 24X Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc list ent! JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000.84/03/21.8402090044
- 8403300043 Ack receipt of 840309 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-387/83-27 & 50-389/83-24 MARTIN.T T Division of Engineering & Technical Programs 84/03/2 KENYON.B D Pennsylvania Power & Light Co 2pp 22821 286 24% Fiche 50-387,84/03/21,8403300063
- --8403300069 Responds to NRC 840208 itr ra violations noted in IE Insp. Repts 50-387/83-27 & 50-388/83-26 Corrective actions min requirements for satisfactory calibr of monitor established & added as acceptance criteria to surveillance procedure. KENYON, 8 D. Pennsulvania Power & Light Co 84/03/09 MARTIN, T T Division of Engineering & Technical Programs 3pp 22821.288 24X Fiche 50-387,84/03/21.8403300063
- R Periodic operating reports & related correspondence
- 8403130039 "Bemiannual Effluent & Waste Disposal Rept.Jul-Dac 1983."
 W/840301 ltr
 WIDNER.T E. KENYON.B D., DOTY.R L. Pennsylvania Power & Light Co
 83/12/31 MURLEY.T E. Region 1. Office of Director 13ipp
 22601 119 24X Fiche 50-387.83/12/31.8403130059
- 8403210112 "Annual Personne) Exposure Rept for CY83 " W/840227 ltr KENYON.B D Pennsylvania Power & Light Co 63/12/31 MURLEY.T.E. Region 1. Office of Director. 2pp. 22705 060 24X Fiche.50-387,83/12/31,8403210112
- B403020036 Monthly operating rept for Jan 1984 W/840214 ltr. KUCYYNSKI, L A . KENYON, B D Pennsylvania Power & Light Co 84/01/31 BEEBE, M R Management Information Branch 3pp 22442 259 24% Fiche 50-387.84/01/31,8403020036
- 8403300147 Monthly operating rept for Feb 1984 M/840313 ltr KUCZYNBKI, L A., KEMYON, B D Pennsylvania Power & Light Co. 84/02/29 BEEBE, M. Management Information Branch, 6pp 22820 077 24X Fiche 50-387, 84/02/29, 8403300147

- 8403090232 NPDEB noncompliance notification sewage treatment plant Outfall 079 failed to meet required 85% reduction in total suspended solids for Jan 1984 FIELDB.J 8 Pennsylvania Power & Light Co 84/03/06. Pennsylvania. Commonwealth of. 2pp 22572 213 24% Fiche.50-087.84/03/06.8403090232
- --8403090239 "NPDES Discharge Monitoring Rept for Jan 1984 "
 # Pennsylvania Power & Light Co 84/03/01 9pp 22572 215 24X
 Fichs 50-387, 84/03/06, 8403090232

8 Reportable occurrences, LERs & related correspondence

- 8403020253 LER 84-002-01 on 840104, emergency svc water B1 spray risers would not pump down due to spray network inlet valve leaking past seat Caused by minimal thread engagement between distribution arm coupling & riser nipple. W/840228 ltr KUCZYMSKI,L A., KEISER,H W. Pennsylvania Power & Light Co 84/02/28 4pp 22440 103. 24X Fiche 50-387,84/02/28,8403020253
- B403020319 Updated LER 83-148/03X-i on B31209, microprocessor analyting flow rate data failed & word normal printed for channel output during each daily survaillance Microprocessor replaced M/B40228 ltr WILKB: B L., KEISER, H W Pennsylvania Power & Light Co 84/02/28 4pg 22439*201 24X Fiche. 50-387, 84/02/28, 8403020319.
- B40306010B RD carbon dioxide fire suppression sys declared inoperable, due to design deficiency. Fire watch posted & mod initiated to remove enough penetration seals to permit proper carbon dioxide discharge
 KEIBER, H M. Pennsylvania Power & Light Co 84/03/01, Record Bervices Branch (Document Control Desk) 1p 22506 181. 24X Fiche:50-387.84/03/01:8403060108.
- 8403060253 LER 84-007-00: on 840202, shear valve explosive cartridge unexpectedly fired during surveillance testing, shearing transversing in-core probe detector cable Cause unknown. New detector & cable installed Procedure changed W/840302 ltr WILMS B.L., KEISER: H W Pennsylvania Power & Light Co 94/03/02 3pp 22515, i91. 24X Fiche. 50-387, 84/03/02, 8403060253
- B403090224 PNO-I-B4-022 on B40303 reactor scrammed from 74% power. Caused by fast closure of main turbine control valve during surveillance on hydraulic detector Suspect relays in detector test instrumentation replaced JACOBB.R : KELLY.E Region 1. Office of Director 84/03/05. ip 22575 077. 24% Fiche 50-387,84/03/05,8403070224.
- 3403090232 NPDES noncompliance notification.sewage treatment plant Outfall 079 failed to meet required 85% reduction in total suspended solids for Jan 1984 FIELDS, J.S. Pennsylvania Power & Light Co., 84/03/06 Pennsylvania, Commonwealth of, 2pp 22572.213 24% Fiche: 50-387,84/03/06,8403090232
- ~8403090239 "NPDES Discharge Monitoring Rept for Jan 1984." * Pennsylvania Power & Light Co 84/03/01 9pp 22572-215. 24X Fiche: 50-387,84/03/06,8403090232.
- 403140011 LER 84-008-00, on 840209, during outage RHR seel water coolers discovered improperly designed Coolers replaced Teledyne Engineering Svc conducting independent review M/840309 ltr HOOD, D. C., KETBER, H. W. Pennsylvania Power & Light Co. 84/03/09. 3pp 22633-226, 24X Fiche, 50-387, 84/03/09, 8403140011.
- 403140018 Updated LER 83-164/01X-1 on 83:221, test results indicated that 3-way clamps on control rod drive insert & withdrawal lines may not be able to withstand worst case axial water hammer loads Plant mods completed W/840309 ltr. W00D, D. C., KEISER, H. W. Pennsylvania Power & Light Co 84/03/09, MURLEY, T.E. Region i, Office of Director 3pp. 22633:222, 24X Fiche 50-387,84/03/09,8403140018.
- 103160199 Special rept.fire barrier damper inoperable longer than Tach Spec limits.Caused by damper being physically blocked open. Flod performed to install access hatch in ductwork Damper reset.
- REIBER, H W. Pennsylvania Power & Light Co 84/03/12. Record Bervicas Branch (Document Control Desk). 1p 22655,350 24X Fiche: 50-387,84/03/12,8403160199.
- O3260226 LER 84-009-00 on 84022i, during restart. HPCI steam supply line pressure indicator did not respond to warm up & reactor pressure exceeded 150 psig. Checkoff list & operating procedure revised. W/840320 ltr WOOD, D.C., KEISER, H. W. Pennsylvania Power & Light Co. 84/03/20 Gpp. 22756:083, 24% Fiche: 50-387, 84/03/20, 8403260226

- DOCKET 50-388 SUBGUEHANNA STEAM ELECTRIC STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8403010254 Notification of 840222 meeting w/util in 8ethesds.MD to discuss proposed changes to standby gas treatment sys Tech Spacs PERCH,R Licensing Branch 2 84/02/21 SCHWENGER.A Licensing Branch 2 3pp 22449 356 24X Fiche 50~387.84/02/21,8403010254
- 8403020329 Responds to request for schedule for completion of Reg Guide 1 97 requirements Exceptions to Billi3 ltr re equipment replacement will be addressed in May 1984, in response to Generic Ltr 82-33 GURTIS.N W Pennsylvania Power & Light Co 84/02/29 GCHWENCER, A Licensing Branch 2 ip 22439 207 24X Fiche 50-387, 84/02/29, 8403020329
- 8403050108 Forwards revised response to Generic Ltr 83-28, "Required Actions Based on Generic Implications of Balem ATWS Events," reflecting updates to Items 1 2 2,2 1,2 2 2 4 5 CURTIS,N W Pennsylvania Power & Light Co 84/03/01 EISENHUT,D 0 Division of Licensing 61pp 22485 242 24X Fiche 50-387, 84/03/01,8403050108
- 8403150321 Notification of 840308 meeting w/util in Luserne County,PA to perform site visit re readiness of facility for licensing. PERCH.R L Licensing Branch 2. 84/03/01 SCHWENCER,A Licensing Branch 2 4pp 22649 299 24X Fiche'50-388,84/03/01.8403150321
- 8403180232 Notification of 840312 meeting w/util in Bethesda, MD to discuss NRG evaluation of detailed control room design review rept PERCH.R.L Licensing Branch 2 84/03/05 SCHWENCER, A. Licensin Branch 2 3pp 22648 360 24X Fichs 50-387, 84/03/05, 8403150232
- 840315026B Requests review of encl final draft Tech Specs & amend to application confirming that draft accurately reflects plant. FBAR & BER analyses Results should be submitted under each or affirmation. H/o encl statement of the submitted under each or affirmation. H/o encl statement of the submitted under each or affirmation. H/o encl should be submitted under each or affirmation to each or submitted under each of the submitted under each of t
- 8403120026 Forwards "Reactor Containment Bidg Integrated Leakage Rate Test, Unit 2. Final Rept." KENYON, B. D. Pennsylvania Power & Light Co. 84/03/07. Office of Nuclear Reactor Regulation, Director ip 22590 227 24x Fichs: 50-388.84/03/07.8403120026.
- --8403120030 "Reactor Containment Bldg Integrated Leakage Rate Test, Unit 2.Final Rept " # Bechtel Corp 83/11/30, 56pp 22590-228 24X Fiche, 50-388, 84/03/07, 8403120026.
- 8403130111 Informs that util will provide supplemental rept to detailed control room design review summary rept by 840301, containing implementation schedule for resolution of outstanding issues
 CURTIS, N W Pennsylvania Power & Light Co 84/03/08 9CHWENCER, A Licensing Branch 2 ip 22615,291. 24X Fiche 50-387,84/03/08, 8403130111
- 8403210072 Forwards Amend 54 to application for Class 103 OL, consisting of Rev 34 to FBAR.

 CURTIEN M. Pennsylvania Power & Light Co 84/03/09 SCHWENCER, A Licensing Branch 2. 6pp 22702'278 24X Fight 50-387, 84/03/09, 8403210072.
- --8403210081 Amend 56 to application for Class 103 DL, consisting of Rev 34 to FSAR GURTIS, N W Pennsylvania Power & Light Co 84/03/07 Ip 22702 283 24X Fiche, 50-387, 84/03/07, 8403210072
- 8403150070 Responds to 831230 requests for response to items identified in EG&G technical evaluation rept on conformance to Reg Ouide 1 97 & comments on any assumptions that surpass util Billia submittal.

 CURTIS.N W Pennsylvania Power & Light Co 84/03/13 SCHMENCER, A Licensing Branch 2. Spp 22643.183 24X Fiche 50-387,84/03/13. B403150070
- 8403190395 Forwards proprietary "Analysis of Feedwater Containment Isolation Valves Following Postulated Pipe Rupture," in response to NRC 830831 request for add1 info Affidavit encl. Rept withheld (ref 100FRZ, 790).

 GURTIS, N W Pennsylvania Power & Light Co 84/03/15 SCHMENCER, A Licensing Branch 2. 4pp. 22674:085 24X Fiche 50-387,84/03/15, 8403190375

- 8403200006 Documents discussions w/R Perch re status of dynamic qualification of listed items including Valcor control rod drive solenoid valves & condensate storage tank CURTIS.N W Pennsylvania Power & Light Co 84/03/15 SCHWENCER.A Licensing Branch 2 2pp 22685 207 24X Fiche 50-388,84/03/15,8403200006
- 8403200093 Requests that further action on BWR core thermal hydraulic stability be deferred due to lack of time to review new info presented at 840308 meeting w/NRC CURTIS.N W Pennsylvania Power & Light Co 84/03/15 SCHWENCER, A Licensing Branch 2 lp 22699 147 24X Fiche: 50-387, 84/03/15.8403200093
- B403220040 Notifies of const completion & assurance that plant conforms w/design intent & regulatory requirements Comprehensive GA program in place through-out life of project Util has not allowed contractor to function independently CURTIS,N W Pennsylvania Pawer & Light Co B4/03/16 DENTON,H R Office of Nuclear Reactor Regulation, Director. 2pp 22712 144 24X Fiche 50-388,84/03/16,8403220040.
- 8403220102 Forwards revs to FBAR Chapters 6.7 & 18 Revs update containment isolation provisions for facilities & will be incorporated in annual FSAR update in Jul 1984 CURIIS.N M Pennsylvania Power & Light Co 84/03/16 8CHHENCER.A Licensing Branch 2 95pp 22715 184 24X Fichs 50-387.84/03/16. 8403220102
- B403260305 Forwards draft NUREG-1042, "Tech Specs.Susquehanna Steam Electric Station "CURTIS,N H Pennsylvania Power & Light Co B4/03/20 DENTON.H R Office of Nuclear Reactor Regulation, Director 480pp 22753 158 24X Fiche 50-388,84/03/20.8403260305
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- B403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FDIA Exemption 5) Review of addl documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, S I Garvey, Schubert, Adams & Barer 7pp 22583 226 24% Fiche, 50-000, 84/02/13, 8403080179
- --B005130793 Provides status of SER inputs & acceptance reviews for OL & CP applications Schedule should be met
 BURKE, N C Effluent Treatment Systems Branch 80/02/06
 KREGER, N E Assistant Director for Site Analysis ip 22583 235
 24X Fiche 50-000, 84/02/13, 8403080179
- B403010274 Forwards Rev 2 to Rept 02-0160-1102, "Review of Unit 2 Control Sys Failures. Final Rept.Unit 2 Control Sys Power Supply & Sensor Malfunctions "Rept submitted per SER CURTIS, N M Pennsylvania Power & Light Co B4702/27 BCHWENCER, A Licensing Branch 2 1p 22432 304 24% Fiche 50-36B, 84/02/27, 8403010274
- --8403010303 Rev 2 to Rept 02-0160-1102. "Review of Unit 2 Control Bys Failures.Final Rept.Unit 2 Control Bys Power Bupply & Bensor Halfunctions" SHAMABIAN.R L. KEREKES.W A Impell Corp 02-0160-1102 R02 84/02/27 19pp 22432 304 24X Fiche 50-388.84/02/27.8403010294
- 8403200071 Confirms that 42 human engineering discrepancies generated from preliminary design assessment & NRC control room audit of Unit 1 incorporated into Unit 2 control room.per App F to SSER 5 CURTIS: N W Pennsylvania Power & Light Co 84/03/15 SCHWENCER.A Licensing Branch 2 1p 22684 341 24% Fiche 50-388,84/03/15,8403200071
- F Security, medical, emergency & fire protection plans
- B403090209 Rev 4 to Emergency Plan Implementing Procedure EP-IP-045.

 "Action Step Emergency Director QSC Coordinator YSC Coordinator:" including Rev 37 to table of contents.Rev 16 to forms index & 840308 transmittal W/840229 ltr # Pennsylvania Power & Light Co 84/02/28 26pp 22575 089 24X Fiche 50-387.84/02/28,8403090209
- 8403050070 Revised emergency plan implementing procedures, including Rev 37 to table of contents. Rev 16 to forms index & Rev 4 to Procedure EP-IP-045 re PASS 14 7 ml gas sample W/B40229 transmittal 1tr MILLER, D.W. Pennsylvania Power & Light Co. 84/02/29 SCHWENCER, A Licensing Branch 2 25pp 22470 019 24X Fichs 50-387,84/02/29,8403050090

- 8403140276 Forwards evaluation of 830627 request for approval of Change P to physical security plan Change acceptable SCHMENCER, A Licensing Branch 2 84/03/02 CURTIS, N W Pennsylvania Pouer & Light Co 4pp 22635 327 24X Fiche 50-387,84/03/02,8403140296
- 8403150126 Revs to Emergency Plan Implementing Procedures EP-1P-001, EP-IP-002, EP-IP-006, EP-IP-007 & EP-IP-008 resembled to the state of the state
- 8403190243 Notification of 840418 workshop in King of Prussia.PA to discuss lessons learned from recent App R fire protection safe shutdown insp. & topics described in IE Info Notice 84-07 Agenda for workshop encl MURLEY.TE Region I. Office of Director 84/03/09 D'TDOLE.J b Consolidated Edison Co. of New York. Inc. 35pp. 22672 062 24X Fiche 50-000.84/03/09.8403190243
- 8403190242 Rev 3 to Emergency Plan Implementation Procedure EP-IP-002 "Emergency Mgt Notifications " Table of contents, forms index & 840313 transmittal ltr encl # Pennsylvania Power & Light Co 84/03/13 8CHMENCER, A NRC No Detailed Affiliation Given 78pp 22671 213 24X Fiche 50-387,84/03/13,8403190242
- B403200103 Clarifies cover ltr to Rev 7 to emergency plan (PLA-1940)
 Details provided for manning emergency operation facility
 (EOF) & activation of backup EOF Unit 2 fuel load scheduled
 for 840326 Expeditious approval requested
 CURTIS:N W Pennsylvania Power & Light Co 84/03/13 SCHWENCER:A
 Licensing Branch 2 3pp 22697 096 24X Fiche 50-387:84/03/13,
 8803200103
- 8403170232 Updates schedules for completing safety parameter display sys.emergency operating procedures & emergency facilities, per Generic Ltr 82-33 Updated emergency procedures will be implemented in Dec 1785 CURTIS, N W Pennsylvania Power & Light Co 84/03/14 BCHWENCER, A Licensing Branch 2 2pp 22672 032 24X Fiche 50-387, 84/03/14, 8403190232
- B403170346 Advises that Commonwealth of PA will not participate in util smergency exercise during CVB4, due to involvement w/dther fixed nuclear facilities State will participate in CYB5 exercise

 TAYLOR, D.F. Pennsylvania, Commonwealth of, 84/03/15 CRUTCHFIELD Operating Reactors Branch 5 1p 22673 135 24X

 Fiche 50-387.84/03/15.8403190346
- 8403230120 Notifies that State of PA eligible for biennial frequency for participation in radiological emergency preparedness exercise Change from annual exercise requirement would be supported if requested by util KRIMNR W Federal Emergency Hanagement Agency 84/03/15. UGRDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) ip 22730 336 24X Fiche 50-387.84/03/15-8403230120

I Financial information

- B403270195 Annual Financial Rept 1985 W/840322 ltr CAMPBELL,R K , CURTIS N W Pennsylvania Power & Light Co 83/12/31 DENTON H R Office of Nuclear Reactor Regulation, Director 33pp 22771 049 24X Fiche 50-387.83/12/31.8403270195
- J Insurance & indemnity information
- 8403060437 Provides present level of onsite property damage insurance for facilities CURTIE.N W Pennsylvania Power & Light Co. 84/02/29 SALTZMAN.J D Assistant Director for State & Licensee Relations, ip 22518 222 24X Fiche 50-387.84/02/29.8403060437
- K Utility Final Safety Analysis Report (FSAR) & amends
- B403210072 Forwards Amend 56 to application for Class 103 OL, consisting of Rev 34 to FSAR.

 CURTIS, NW Pennsylvania Power & Light Co 84/03/09, 8CHWENGER A Licensing Branch 2 6pp 22702 278, 24X Fiche 50-387, 84/03/09, 8403210072
- ---B403210081 Amend 56 to application for Class 103 OL, consisting of Nev 34 to FSAR CURTIS,N W Pennsylvania Power & Light Co 84/03/09. 1p 22702 283 24X Fiche 50-387,84/03/09.8403210072

- --8403210090 Rev 34 to FBAR Twenty-right oversized drawings encl Drawings available in PDR avassele in PPR * Pennsylvania Power & Light Co 84/02/29 760pp 22702 284 24X Fiche 50-387,84/03/09,8403210072
- G Inspection reports, IE Bulletins & correspondence
- 8403020214 Forwards IE Insp Rept 50-388/84-03 on 840109-13 No
- 40302224 Forwards It Insp Rept 50-386/84-03 on 640109-13 No violations observed MARTIN, T T Division of Engineering & Technical Programs 84/02/17 KENYON, B D Pennsylvania Power & Light Co 2pp 22440 254 24X Fiche 30-388,84/02/17,8403020214 84/02/17
- --B403020220 IE Insp Rept 50-368/84-03 on 840109-13 No violations or deviations identified Major areas inspected preoperational testing GA.preoperational test records & GA for startup test
 - testing unipreparation programs
 NAPUDA, Q: PRELL, J Ragion 1: Office of Director QUDY, A T Division of Engineering & Technical Programs 84/02/16 7p 22440 256 24X Fiche 50-388,84/02/17,8403020214
- 8403070240 Forwards IE Insp Rapts 50-387/84-06 & 50-388/84-05 on 840124-27 No violations noted MARTIN, T T Division of Engineering & Technical Programs 84, KENYON, B D. Pennsylvania Power & Light Co 2pp 22547-318 Fiche: 50-387,84/02/17,8403070240
- -8403070242 IE Insp Repts 50-387/84-06 & 50-388/84-05 on 840124-27 No violation noted Major areas inspected licensee action in closing electrical insp rept findings FINNEL.A . ANDERSON, C J Region 1, Office of Director 84/02/16 5pp 22547 320 24X Fiche 50-387.84/02/17.8403070240
- 8403070301 Forwards IE Insp Repts 50-387/84-02 & 50-388/84-02 on 840116-20 No violations observed Steps taken to correct violation noted in 830829 ltr verified MARTIN.T T Division of Engineering & Technical Programs 84. KENYON.B D Pennsylvania Power & Light Co 2pp 22546 342 Fiche 50-387.84/02/21.8403070301 84/02/21
- --8403070304 IE Insp Repts 50-387/84-02 & 50-388/84-02 on 840116-20 No violations identified Major areas inspected, radiation protection program & preoperational testing, including licensee action on previous finding & training NIMITIZ, R L, SHANBAKY, M M Region 1, Office of Director 84/02/13
- 8403040175 Responds to IE Bulletin 83-08 Circuit breakers w/
 undervoltage trip attachments not used in safety-related
 applications in Unit 1 8ub; attachments installed in Unit 2
 will be removed from safety-related applications
 CURTIE:N W Pennsylvania Power & Light Co 84/02/27 MURL
 Region i, Office of Director. Zpp 22518 267 24X
 Fiche 80-387.84/02/27.8403060175
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list
- encl. JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc. 115pp 22709 239 24X Fiche 50-000,84/02/28,8401190072
- 8403150027 Forwards IE Insp Rept 50-388/83-19 on 831017-28 & notice of
- Violation

 MARTIN.T.T. Division of Engineering & Technical Programs 8:
 KENYON, B.D. Pennsylvania Power & Light Co 2pp 22645 327
 Fiche: 50-388:84/02/28:8403150027. 84/02/28
- --8403150030 Notice of violation from insp on 831017-28 Assessment of * Region 1, Office of Director. 84/02/28 3pp 22645 329 24X Fiche; 50-388, 84/02/28, 8403150027
- --8403150034 IE Insp Rept 50-388/83-19 on 831017-28 Violations noted: inadequate preparation of weld for ultrasonic insp & small bore piping flex leg not installed per engineering design calculation
 - BETTENHAUBEN, L., CAMPBELL, R.M., HARRIS, R.H. Region 1: Office of Director. 84/02/27 36pp. 22645-392. 24X Fichs 50-388,84/02/28,8403150027
- B402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl ORACE, J. N. Division of GA, Bafeguards & Inspection Programs (Post 830103). 84/03/02. Consolidated Edison Go of New York, Inc. 130pp 22552;329 24X Fichs. 50-000, 84/03/02, 8402090007
- 8402070008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate." Svc list encl JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553.098 24X Fiche 50-000,84/03/02,8402070008

- 8402070007 IE Info Notice 84-15. "Reporting of Radiological Releases "
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8402090024 IE Info Natice 64-09. Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000.84/03/07.8402090024
- 8402070028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR 102090028 IE Info Notice of ...

 Sys " Svc list and!

 JGRDAN.E L Division of Emergency Preparedness & Engineering

 Response (Post 830103) 84/03/07 Consolidated Edison Co of New

 York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " 8vc list encl DEYOUNG.R C Director's Office. Defice of Inspection and Enforcement B4/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 074 24X Fiche 50-000.84/03/12,8402090031
- 8403190360 Ack receipt of 840223 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-387/83-31 & 50-388/83-31 50-388/83-31
 MARTIN, T Y Division of Engineering & Technical Programs 84
 KENYON, B D Pennsylvania Power & Light Co ip 22673 312
 Fiche 50-387,84/03/13,8403190360 84/03/13
- --8403190366 Responds to NRC 840127 ltr re violations noted in IE Insp Repts 50-387/83-31 & 50-388/83-31 Corrective actions status repts for Nonconformance Repts 83-779 & 83-190 received by GC supervisor on 840201 & 0131. respectively KENYON.B D Pennsylvania Power & Light Co 84/02/25 MARTIN.T T Division of Engineering & Technical Programs 3pp 22673 313 24X Fiche 50-387,84/03/13,8403190360
- 8403220128 Ack receipt of 840225 ltr informing NRC of steps taken to correct violations noted in 18 lmsp Repts 50-387/83-30 & SO-388/83-25
 MARTIN.T T Division of Engineering & Technical Programs
 KENYON.B D Pennsylvania Power & Light Co ip 22716 O
 Fiche 50-387.84/03/13.8403220128 84/03/13 22716 014
- --8403220135 Responds to NRC 840126 ltr re violations noted in IE Insp Repts 30-387/83-30 & 50-388/83-25 Corrective actions Temporary Setpoint Changes 82-028T & 82-029T made into permanent setpoint changes KENYON,8 D Pennsylvania Power & Light Co 84/02/25 MARTIN,T T Division of Engineering & Technical Programs 4pp 22716 015 24X Fiche 50-387,84/03/13,8403220128
- 8403290116 Forwards IE Insp Repts 50-387/84-05 & 50-388/84-06 on 840130-0203 & notice of violation MARTIN, T T Division of Engineering & Technical Programs 84/03/15 KENYON, B D Pennsylvania Power & Light Co 2pp 22806 292 24X Fiche 50-387,84/03/13,8403290116
- --8403270120 IE Insp Repts 50-387/84-05 & 50-388/84-06 on 840130-0203 Noncompliance noted failure to follow GC procedure for radiochemistry to determine instrument operating voltage KOTTANIJ J. ZIBULSKY, H. HOGAN.R. Region 1. Office of Director 84/03/07 Bpp. 22806 275 24X Fiche 50-387,84/03/13,8403270116
- 8403270140 Forwards IE Insp Repts 50-387/83-27 & 50-388/83-32 on 831219-840130 & notices of violation & deviation Uncorrected repetitive trips of standby gas treatment fans during Unit 2 Cold Functional Test P200 IB noted STAROBTECKI.R Division of Project & Resident Programs 84/0: KENYON, B D Fennsylvania Power & Light Co 2pp 22806 011 Fiche: 50-387,84/03/14,8403270140
- --8403270142 Notice of violation from insp on 831219-840130 * Region i, Office of Director 84/03/14 lp 22806 013 Fiche 50-387, 84/03/14, 8403270140
- --B403290149 Notice of deviation from insp on B31217-B40130 * Region 1, Office of Director 84/03/14 ip 22806 014 Fiche. 50-387, 84/03/14, 8403290140.

- --8403290155 IE Insp Repts 50-387/83-29 & 50-388/83-32 on 831219-840130 Violation identified conditions adverse to quality not promptly identified & corrected Deviation identified failure to meet F8AR commitment for automatic depressurization sys JACOBS.R. PLISCO.L. Region i, Office of Director MCCABE.E.C. Division of Project & Resident Programs 84/02/24 21pp 22806 015 24X Fiche 50-387,84/03/14.8403290140
- 8403220069 Completes response to IE Bulletin 83-07. "Apparently Fraudulent Products Sold by Ray Miller.Inc" & two suppls No Ray Miller, Inc matl installed Muclear Energy Svc.Inc supplied ultrasonic calibration blocks CURTIS.N W Pennsylvania Power & Light Co 84/03/16 MURLEY.T E Region I. Office of Director 9pp 22712 295 24X Fiche 50-387.84/03/16.8403220069
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PHR Reactor Cavities " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York. Inc 123pp 22823 229 24X Fiche 50-000.84/03/21.8402090043
- 8402070044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 133pp 22733 001 24X Fiche 50-000,84/03/21.8402070044
- 8403300063 Ack receipt of 840309 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-387/83-27 & 50-388/83-26
 MARTIN T T Division of Engineering & Technical Programs 84/03/2 KENYON B D Pennsylvania Power & Light Co 2pp 22821 286, 24X Fichs 50-387,84/03/21.8403300063
- --B403300069 Responds to NRC B4020B ltr re violations noted in IE Insp Repts 50-387/B3-27 & 50-388/B3-26 Corrective actions min requirements for satisfactory calibr of monitor established & added as acceptance criteria to surveillance procedure KENYON.B D. Pennsylvania Power & Light Co 84/03/07 MARTIN.T T Division of Engineering & Technical Programs 3pp 22821 288 24X Ficha 50-387.84/03/21.8403300063
- R Periodic operating reports & related correspondence
- 8403070232 NPDES noncompliance notification sewage treatment plant Outfall 079 failed to meet required 85% reduction in total suspended solids for Jan 1984 FIELDS.J S Ponnsylvania Power & Light Co 84/03/06 Pennsylvania. Commonwealth of. 2pp 22572 213 24% Fiche 50-387,84/03/06.8403090232
- --8403090239 "NPDES Discharge Monitoring Rept for Jan 1984" * Pennsylvania Power & Light Co B4/03/01 9pp 22572 215 24X Fiche 50-387, 84/03/06, 8403090232
- S Reportable occurrences, LERs & related correspondence
- 8403210145 Final deficiency & Part 21 repts re safety parameter display sys Technology Energy Corp Model 156 isolators Initially reported on 840106 Non-IE power supply will be provided for isolator prior to end of first refueling CURTIS.N W Pennsylvania Power & Light Co 84/02/27 MURLEY, T E Region 1. Office of Director 4pp 22707 281 24X Ficha 30-388,84/02/27,8403210145
- 8403260233 Forwards summary list of deficiencies identified per 10GFR50 55(e).Part 21 & patential generic ltr repts for comments

 STAROSTECKI,R Division of Project & Resident Programs 84/02/28
 Region I. Office of Director 7pp 22756 065 24X
 Fiche 50-000.84/02/28,8403260233
- 8403230095 Second interim deficiency rept re improper relief valve setting design pressures & design temp within several sys Initially reported on 83111B Bpec M-179 revised & code data repts amended Also reported per Part 21 CURTIB-N W Pennsylvania Power & Light Co 84/03/02 MURLEY,T E Region 1, Office of Director 14pp 22726 277 24X Fiche 50-388,84/03/02.8403230095
- 8403090232 NPDES noncompliance notification sewage treatment plant Outfall 077 failed to meet required 85% reduction in total suspended solids for Jan 1984 FIELDS J S Pennsylvania Power & Light Co 84/03/06 Pennsylvania Commonwealth of, 2pp 22572 213 24% Fiche 50-387,84/03/06,8403090232

- 8403210125 Final deficiency rept re cavitation of jet pumps due to induction heating stress improvement cooling Initially reported on 831206 No erosion found Also reportable per Part 21 Item not reportable per 10CFR50.55(*)
 CURTIB.N W Pennsylvania Power & Light Co G4/03/04 MURLEY.T E Region 1. Dffice of Director 4pp 22707 228 24X
 Fiche 50-388.84/03/04.8403210125
- V Operator Examinations
- 8403130150 Forwards nuclear power plant experience tables for operating shift position forms for senior reactor operators & reactor operators Licensed classroom training & exam conducted fuel load expected on 840326 CURTIS.N W Fennsylvania Power & Light Co 84/03/09 DENTON.H R Office of Nuclear Reactor Regulation. Director 5pp 22608 106 24X Fiche 50-388.84/03/09.8403130150
- DOCKET 50-389 ST LUCIE PLANT, UNIT 2
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8401130319 Informs that redundant boron dilution sys alarm installed & declared operational on 840106, per 821029 & 1104 ltrs & SSER 3

 WILLIAMS.J W Florida Power & Light Co 84/01/10 EISENHUT.D G
 Division of Licensing 1p 21798 305 24X Fiche 50-389, 84/01/10, 8401130319
- F Security, medical, emergency & fire protection plans
- 8403070249 Responds to NRC 831123 ltr re violations noted in IE Insp Rept 30-389/83-57 Corrective actions detectors will be moved to ceiling Rereview of 10CFR50.App R commitments conducted Full compilance will be achieved by 840630 WILLIAMS, J W Florida Power & Light Co 83/12/20 D'REILLY, J P Region 2, Office of Director 2pp 22536 271 24X Fiche 50-389.83/12/20,8403070249
- 8403070280 Public version of Rev 13 to radiological emergency plan W/ B40124 ltr & JM Felton 840307 release memo WILLIAMS, JW Fibrida Power & Light Co B4/01/04 O'REILLY, J P Region 2. Office of Director 227pp 22593 001 24X Fiche. 50-335, 84/01/04, 8403090280
- 8403060340 Revised emergency implementing plan procedures, including Procedures 2-0030140 re blackout operation: 2-0030143 re total loss of ac power: R-0120042 re LCCA & 2-1010030 re loss of instrument air H/B40229 ltr
 SAGER, D.A., HETHY, C.N. Florida Power & Light Co. 84/01/23 A9pp 22519 074 24X Fiche 50-335,84/01/23,8403040340
- B403070140 Forwards IE Insp Repts 50-335/84-03 & 50-389/84-04 on B40118-20 No violations or deviations noted. DANCE, H C Division of Project & Resident Programs 84/02/13. HILLTAMS.J W Florida Power & Light Co. 2pp 22538 285 24X Fiche 50-335,84/02/13,8403070140
- --8403070145 IE Insp Repts 50-335/84-03 & 50-389/84-04 on 840118-20 No violations or deviations noted Hajor areas inspected emergency preparadness to assess on-shift prompt emergency classification & protective action recommendations DECKER.T R Region 2, Office of Director 84/02/10 App 22538 287 24X Fichs 50-335.84/02/13.8403070140
- 8403190386 Rev 12 to Emergency Pian Implementing Procedure 3100024E, "Natural Emergencies " W/840307 ltr WILLIAMS, J W Florida Power & Light Co 84/02/29 D'REILLY, J, P Region 2, Office of Director 12pp 22675 270 24X Fiche 50-335,84/02/29,8403190386
- 8403060186 Forwards safety parameter display sys implementation plan & parameter selection rept.per 830415 commitment Rept meets requirements of Generic Ltr 82-33 re Suppl 1 to NUREQ-0737 WILLIAMS.J W Florida Power & Light Co 84/03/01 EISENHUT.D G Division of Licensing 11pp 22517 001 24X Fiche 50-389,84/03/01,8403060186
- 8403160254 Notifies of 840316 workshop to discuss 10CFR50.App R requirements & insp results to resolve misunderstandings refire protection Attendees should be limited to six due to size of conference room LEWIG.R C Division of Project & Resident Programs 84/03/02. HILLIAMS.J W Florids Power & Light Co 1p 22660 255. 24X Fichs 50-000.84/03/02.8403160254.

- 8403290181 Expresses appreciation for cooperation throughout 10-month period of planning & developing federal full field exercise Exercise provided planning focus & field experience for completing radiological emergency response planning O'REILLY, J P Region 2. Dffice of Director 84/03/15 ADOMAT, E A Floride Power & Light Co 2pp 22802 208 24X Fiche 50-335,84/03/15,8403290181
- B403270107 Ack receipt of 840307 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-335/83-43 & 50-389/83-71 DANCE.H C Division of Project & Resident Programs WILLIAMB.J W Florida Power & Light Co 1p 22807 Fiche 50-335.84/03/19.8403290109 84/03/19 22807 001
- --8403290126 Notice of violation from insp on 831211-840110 * Region 2, Office of Director 84/02/10 ip 22807 006 24X Fiche 50-335,84/03/19,8403290109
- --8403290132 IE Insp Repts 50-335/83-43 & 50-389/83-71 on 831211-840110 Violation identified failure to maintain control room procedures in areas of administration, operation, emergency & procedures in eres of Communication of Phonomeal.
 BIBB.H E Region 2. Office of Director 84/02/02/02807 007 24X Fiche 50-335,84/03/19.8403290109

H General correspondence

- 8403280149 Responds to 840208 ltr requesting assistance in responding to J Paskavitch ltr requesting latest EIB on concentrations of Sr-90.Cs-137 & I-131 near plants Two annual repts encl W/o repts DIRCKB, W J Dffice of the Executive Director for Operations 84/03/07 CHILES L Senate 4pp 22809 316 24X Fiche 50-000,84/03/07,8403280149
- --8403280156 Forwards constituent J Paskavitch ltr requesting latest EIB on concentrations of Br-90.Cs-137 & I-131 near plants Comments & views requested
 CHILES, L Senate 84/02/08 KAMMERER, C Office of Congressional
 Affairs Spp 22809 320 24X Fiche 50-000,84/03/07,8403280149

J Insurance & indemnity information

- 8403040234 Forwards Endorsement 52 to NELIA Policy NF-227 DUCK, J. R. Marsh & McLennan, Inc. 84/02/28 8ALTZMAN, J. Director for State & Licensee Relations 2pp 22517 315 Fiche: 50-335,84/02/28,8403060234
- P. Operating license stage documents & correspondence
- 8401130182 Suppl to 831222 application for amend to License NPF-16, changing Tech Specs for axial shape index to achieve consistency between Unit 1 & Unit 2 Tech Specs MILLIAMS.J.W. Florida Power & Light Co. 84/01/10. EISENHUT, D Q Division of Licensing lp 21802 054 24X Fiche 50-389,84/01/10. B401130182.
- 8401130319 Informs that redundant boron dilution sys alarm installed & declared operational on 840106,per 821029 & 1104 ltrs & Baser G. WILLIAMS, J W Florida Power & Light Co 84/01/10 EISENHUT, D Q Division of Licensing ip 21798 305 24X Ficha. 50-389, 84/01/10, 8401130319.
- 8403010297 Application for amend to License NPF-16, modifying Tech Specs
- --8403010302 Proposed Tech Specs re initial inservice insp of two WECHANICAL Snubbers on containment spray sys WILLIAMS, J W Florida Power & Light Co 84/02/24 3pp. 22432.110. 24X Fiche 50-389,84/02/24,8403010297.
- B403060077 Forwards Amends 62 & 5 to Licenses DPR-67 & NPF-46, respectively & safety evaluation. Amends change personnel titles & revise shift technical advisor function.

 BELLB, D. E. Operating Reactors Branch 3 84/02/24 WILLIAMB, J W Florida Power & Light Co. 2pp. 22549 020 24X Fiche: 50-335, 84/02/24, 8403060077.
- ==8403040080 Amends 42 & 3 to Licenses DPR-47 & NPF-14, respectively, changing personnel titles & revising shift technical advisor functions MILLER, J. R Operating Reactors Branch 3 84/02 22549: 022, 24X Fichs. 50~335, 84/02/24, 8403040077

- --8403040527 Safety evaluation supporting Amends 62 % 5 to Licenses DPR-67 & NPF-16, respectively * Office of Nuclear Reactor Regulation, Director 84/02/24 2pp 22349 034 24% Fithe 50-335,84/02/24,8403060077
- 8403010400 Bubmits info re pressurizer heater transformer barrier design.per License Condition 2 C 9 Missile protection structure will be seismically anchored on concrete floor MILLIAMS, J W Florida Power & Light Co 84/02/27 EISENHUT, D 0 Division of Licensing Jpp 22434 026 24% Fiche 50-389, 84/02/27, 8403010400
- 8403040241 Requests exemption from requirement to submit entirely reprinted & updated FSAR by 850406 Requests update be submitted as Amend 15 to original FSAR MILLIAMS.J W Florida Power & Light Co 84/02/28 EISENHUT, D Q Division of Licensing 1p 22515 190 24% Fiche 50-389.84/02/28,
- 8403060168 Notifies that administrative program & procedures now in affect will be reviewed to confirm implementation of recommended guidelines in NUTAC rept.per Generic Ltr 83-28 HILLIAMS, J C Florida Power & Light Co 84/03/01 EIBENHUT, D G Division of Licensing ip 22518 336 24% Fiche 50-000, 84/03/01, 8403080168
- 8403120040 Requests NRC approval of proposed license amend dtd 840224 by 840413, to permit initial visual insp of safety-related snubbers between 4 & 10 months after commencing power operation on 830413 WILLIAMS, J W Flori WILLIAMS, J W Florida Power & Light Co 84/03/07 EISENHUT, D Q Division of Licensing 1p 22570 318 24X Fiche, 50-387, 84/03/07, 8403120040
- 8403120087 Requests that environ protection plan study re evaluation &/ or mitigation of turtle entrapment at intake structure be presented during wk of 840408 Draft results expected by early Mar 1984 Rept will be discussed w/listed agencies HILLIAMS, J W Florida Power & Light Co 84/03/07 EISENHUT, D Q Division of Licensing 2pp 22588 194 24X Fiche 50-389,84/03/07,8403120869
- 8403190150 Notifies of 840402-06 meeting & preimplementation audit at Turkey Point to discuss confirmatory items identified in safety evaluation of detailed control room design reviews for facilities
 VARQA:B A Operating Reactors Branch 1 84/03/07 WILLIAM, J W Florida Power & Light Co App 22691 311 24X
 Fiche 50-000.84/03/07.8403190150
- 8403130066 Advises that request to revise Tech Specs to provide requirements for overtime limits & reporting of relief & safety valve failures will be submitted per General Ltr 82-16 (NUREG-0737) by 840515 MILLIAMB.J W Florida Power & Light Co 84/03/08 MILLER.J R Operating Reactors Branch 3 ip 22601.252 24X Fiche 50-335,84/03/08.8403130066
- 8403270371 Requests appropriate fee to continue review of 830707 proposed changes to License Condition 2 C 7 re natural circulation cooldown & boron mixing test MILLER, W O License Fee Management Branch 84/03/12 UHRIO, Florida Power & Light Co 1p 22787 330 24X Fiche 50-387, 84/03/12,8403270371 UHRIO, RE
- 8403160013 Forwards "Evaluation of Natural Circulation Cooldown Test Performed at San Unoffe Nuclear Generating Station " Rept provides evaluation of applicability of results to St Lucie Unit 2. WILLIAMS, J W Florida Power & Light Co B4/03/13 EIBENHUT, D G Division of Licensing 1p 22652 179 24X Fiche 50-000,84/03/13, B403160013
- 8403190227 Application to amend License NPF-16, changing Tech Specs to permit revacting of spent fuel pool to ensure sufficient storage capacity, Approval requested by 840901.
 WILLIAMB, JW Florida Fouer & Light Co 84/03/13 EISENHUT, D C Division of Licensing 3pp 22671 305 24X Fichs 50-389,84/03/13,
- --8403190228 Proposed Tech Spec changes re reracking of spent fuel pool NBHC & BAR encl * Florida Power & Light Co 84/03/13 78pp. 22671 308 24X Fiche, 50-389, 84/03/13, 8403190227

- Q Inspection reports, IE Bulletins & correspondence
- B403070249 Responds to NRC 831123 ltr re violations noted in IE Insp Rept 50-389/83-57 Corrective actions detectors will be moved to ceiling Rereview of 10CFR50, App R commitments conducted Full compliance will be achieved by 840630 WILLIAMS.JW Florida Power & Light Co 83/12/20 0'REILLY.JP Ragion 2. Office of Director 2pp 22536 271 24X Fiche 50-389.83/12/20.8403070249
- 8403070140 Forwards IE Insp Repts 50-335/84-03 & 50-389/84-04 on 840118-20 No violations or deviations noted DANCE:H C Division of Project & Resident Programs 84/02/13 WILLIAMS.J W Florida Power & Light Co 2pp 22538 285 24) Fiche 50-335/84/02/13/8403070140
- --B403070145 IE Insp Repts 50-335/B4-03 & 50-389/B4-04 on 840118-20 No violations or deviations noted Major areas inspected emergency preparedness to assess on-shift prompt emergency classification & protective action recommendations DECKER, T R Region 2. Office of Director JENKING.0 R Division of Emergency Preparedness & Materials Safety B4/02/10 4pp 22538 287 24X Fichs 50-335.84/02/13.8403070140
- 8403160206 Forwards IE Insp Repts 50-335/84-04 & 50-387/84-05 on 840201-03 No violations or deviations noted DANCE:H C Division of Project & Resident Programs 84/02/21 HILLIAMS.J W Florida Power & Light Co 2pp 22655 233 24X Fiche 50-335/84/02/21,8403160206
- --8403140210 IE Insp Repts 50-335/84-04 & 50-389/84-05 on 840201-03 No violations or deviations noted Major areas inspected maint & surveillance observation.plant operations.preoperational testing procedures & low power testing KRUG.H E Region 2. Diffice of Director JAPE.F Division of Engineering & Operational Programs 84/02/13 4pp 22655 235 24X Fiche 50-335,84/02/21.8403160206
- B403010297 Application for amend to License NPF-16, modifying Tech Specs to delay initial inservice insp for two mechanical snubbers on containment spray sys until first refueing outage HILLIANS.J W Florida Power & Light Co 84/02/24 EISENHUT, D G Division of Licensing 3pp 22432 107 24% Fiche 50-389,84/02/24,8403010297
- --B403010302 Proposed Tech Specs re initial inservice insp of two mechanical snubbers on containment spray sys WILLIAMS.J H Florida Power & Light Co 84/02/24 3pp 22432 110 24X Fiche 50-389.84/02/24.8403010297
- 8403160264 Forwards IE Insp Repts 50-335/83-42 & 50-389/83-70 on 831101-1210 No violations or deviations noted DANCE.H C Division of Project & Resident Programs 84/02/24 HILLIAMS.J W Florida Power & Light Co 2pp 22660 335 24X Fiche 50-335.84/02/24.8403160264
- --8403160268 IE Insp Repts 50-335/63-42 & 50-389/83-70 on 831111-1210 No violations or deviations noted Major great inspected maint & surveillance observation, plant operations, LERs & IE info notices
 - notices
 BIBB.H E Region 2. Office of Director ELROD, S.A. Division of
 Project & Resident Programs 84/02/23 10pp 22660 337 24X
 Fiche 30-335.84/02/24,8403160264
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list and JDRDAN.E L. Division of Emergency Preparedness & Engineering
- enci JDRDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc. 115pp 22907 239 24X Fiche 50-000,84/02/28,8401190072
- 8403270317 Forwards IE Insp Repts 50-335/84-05 & 50-389/84-07 on 840204-10 No violations or deviations noted DANCE:H C Division of Project & Resident Programs 84/02/29 WILLIAMS.J W Florida Power & Light Ca 2pp 22802 052 24) Fiche 50-335,84/02/29,8403290317
- ~~8403290320 IE Insp Repts 50-335/84-05 & 50-389/84-07 on 840206-10 No violations or deviations noted Major areas inspected health physics instrumentation, action on NUREG-0737 items, ALARA activities & followop on previous items WRAY.JR Region 2. Office of Director BARR.KP Division of Engineering & Derational Programs 84/02/22 8pp 22802 054 24X Fiche 50-335,84/02/29,8403290317
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Reys by DOT & NRC " Eyr list encl GRACE.J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 327 24X Fiche 50-000,84/03/02,8402090007

4

- 840209000B IE Info Notice 84-16, "Failure of Automatic Sprinkler Bys Valves to Operate " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 09B 24X Fiche 50-000,84/03/02,8402090008
- 8402090009 IE Info Notice 84-i5, "Reporting of Radiological Releases" Svc list encl
 JORDAN.E L. Division of Emergency Preparadness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc 119pp 22553 217 24X Fiche 50-000.84/03/02, 8402090009
- 8403270174 Forwards IE Insp Repts 50-335/84-02 & 50-389/84-03 on 840111-0210 No violations or deviations noted DANCE.H C Division of Project & Resident Programs 84/03/02 WILLIAMS, J W Florida Power & Light Co 2pp 22803 076 24) Fiche 50-335.84/03/02,8403270174
- --8403270180 IE Insp Repts 50-335/84-02 & 50-387/84-03 on 840111-0210 No violations or deviations noted Major areas inspected maint observation, surveillance observation, plant operations & TMI Action Item III B 4 2 B followup FEIERABEND.C., BIBB.H E Region 2. Office of Director ELROD, 8 A Division of Project & Resident Programs 84/01/02 2pp 22803 078 24X Fiche 50-335,84/03/02,8403270174
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nii Ductility Temp " Svc list encl JDRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24x Fiche 30-000.84/03/05.8402090011
- B402090024 IE Info Notice 84-09, Rev i. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000, 84/03/07, 8402090024
- 8402090028 IE Info Notice 84-iB, "Stress Corrosion Cracking in PWR Sys " Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402070028
- 8403120040 Requests NRC approval of proposed license amend dtd 840224 by 840413, to permit initial visual insp of safety-related snubbers between 4 & 10 months after commencing power operation on 830613
 WILLIAMS, J W Florida Power & Light Co 84/03/07 EISENHUT, D Q Division of Licensing ip 22570 318 24X Fiche 50-389, 84/03/07, 8403120040
- 8402090031 IE Bulletin 84-02. "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24% Fiche 50-000,84/03/12,8402090031
- 8403270107 Ack receipt of 840307 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-335/83-43 & 50-397/83-71

 DANCE,H C Division of Project & Resident Programs 84/03/17

 WILLIAMS,J W Florida Power & Light Co ip 22807 001 24X

 Fiche 50-335,84/03/19,8403290107
- --8403290114 Responds to NRC 840202 ltr re violations noted in IE Insp Repts 50-335/83-43 & 50-389/83-71 Corrective actions, all indexes reviewed against master copies & procedures in control room verified against indexes WILLIAMS, J W Florida Power & Light Co 84/03/09, D'REILLY, J P Region 2, Office of Director 2pp 22807 002, 24X Fiche 50-335,84/03/19,8403290109
- --8403270124 Forwards IE Insp Repts 50-335/63-43 & 50-389/83-71 on 831211-840110 & notice of violation DANCE, H C Division of Project & Resident Programs 84/02/10. HILLIAMS.J W Florida Power & Light Co 2pp 22807 004 24X Fiche 50-335,84/03/17,8403270109
- --8403290126 Notice of violation from inep on 831211-840110 * Region 2, Office of Director 84/02/10 1p 22807.006, 24X Fiche 50-335, 84/03/19, 8403290109
- --8403270132 IE Insp Repts 50-335/83-43 & 50-389/83-71 on 831211-840110 Violation identified failure to maintain control room procedures in areas of administration operation emergency & off-normal BIBB: HE. Region 2. Office of Director ELROD, 8 Division of Project & Resident Programs 84/02/08 4pp 22807 007 24X Fichs 50-335,84/03/19,8403290109

- 8402090043 IE Info Notice 84-19. "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000,84/03/21,8402090043
- B402090044 IE Info Notice B4-20, "Svc Life of Relays in Safety-Related Bys " Svc list encl JORDAN, E, L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000.84/03/21,8402070044

R Periodic operating reports & related correspondence

- 8403020033 Monthly operating repts for Jan 1984 W/840215 ltr GRANT, N W Florida Power & Light Co 84/01/31 17pp 22442 235 24X Fiche 50-000.84/01/31,8403020033
- B403300173 Forwards monthly operating repts for Feb 1784 & corrected Page I of St Lucis Unit 2 monthly operating rept for Jan 1784
 HILLIAMS, J W Florida Power & Light Co 84/03/15 Office of Resource Management, Director 1p 22819·263 24X
 Fiche 30-000,84/03/15,8403300173
- --8403300185 Monthly operating repts for Feb 1984 GRANT,N W Florida Power & Light Co 84/03/15 16pp 22819 264 24X Fiche 50-000,84/03/15,8403300173
- --8403300193 Corrected Page 1 of monthly operating rept for Jan 1984 GRANT, N. W Florida Power & Light Co 84/02/15 1p 22817 280 24X Fiche: 50-600, 84/03/15, 8403300173

8 Reportable occurrences, LERs & related correspondence

- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines. Ginps1 NPS-4 T&T valves to close. Encl 1tr dtd 840203 sent to listed utils OE notified of affected units in BWR plants.

 THEROUX.R.R. Terry Corp 84/02/22. WOODRUFF, R W Director's Office of Inspection and Enforcement 6pp 22706 327 24X Fiche 50-000,84/02/22,8403210032
- 8403020258 LER 84-003-00 on 840129, hi-hi steam generator level turbine trip occurred, resulting in reactor trip Caused by leakage through main feed regulating valve A Reactor started & plant returned to svc W/840228 ltr.

 WALLING, 0 E , WILLIAMS, J W Florida Power & Light Co 84/02/28, 2pp. 22440 091 24X Fiche, 50-389, 84/02/28, 8403020258
- 8403060390 LER 84-002-00 on 840130, hydrogen analyzer 28 % control room air conditioner HVA-3A unavailable for mode changes as required by Tech Specs. Caused by improper review & recordkeeping Personnel reinstructed W/840301. ltr HCLAUOHLINL, WILLIAMS, W Florida Power & Light Co 84/02/29 3pp. 22511 354. 24X Fiche 50-389.84/02/29,8403060390
- B403230028 Followup Part 21 rept re nuclear valve/actuator stroking time possibly lengthened beyond 15 s when using hydrocarbon-based lubricants. Ltrs to affected utils encl. WILBON, A. K. Henry Pratt Co B4/03/08 KEPPLER, J O Region S. Office of Director. 6pp 22790 306 24X Fiche 50-000,84/03/08,8403230028.
- 8403130035 LER 84-004-00 on 840209, while at 100% power, main feedwater pump tripped due to low suction pressure. Cause not determined Auxiliary feedwater pump 2C tripped due to transients on power supply. Nut pin replaced W/840309 ltr PARKS. 8 , WILLIAMS. J W Florida Power & Light Co. 84/03/09 2pp 22614 305 24% Fiche'50-389,84/03/09,8403130035

V. Operator Examinations

8403080164 Forwards request for site visits to conduct operator licensing exams requested in Generic Ltr 83-40.
WILLIAMB, J W Florida Power & Light Co 84/03/01 EIBENHUT, D G Division of Licensing 5pp 22559.293 24X Fiche 50-335,84/03/01. 8403080164

DOCKET 50-390 WATTS BAR NUCLEAR PLANT, UNIT 1

- A. Application/construction stage documents & correspondence
- 8403060534 Notification of 840315-16 meetings w/util in Sweetwater, TN to conduct confirmatory site visit par Section 13 6 of BRP (NUREO-0800).

 KENYON, T. J., Licensing Branch 4 84/02/28 ADENSAM, E 9 Licensing Branch 4. 3pp 22552 317. 24X Fiche 80-390, 84/02/28, 8403060534

- 8403160247 Informs of 840327 meeting to discuss proposed responses to NRC questions on Rev 7 to topical QA program.per 840302 telcon

 LEMIS.R C Region 2. Office of Director 84/03/08 PARRIS.H Q
 Tennesses Valley Authority ip 22660 361 24X
 Fiche 50-000.84/03/08.8403160247
- 8403160373 Notifies of use of ASME Nuclear Components Code Case N32-4 for hydrostatic testing of Class 3 embedded piping NRC position re use of Code Case N32-4 requested MILLS,L M Tennesses Valley Authority 84/03/12 DENTON,H R Office of Nuclear Reactor Regulation. Director 1p 22660 014 24 Fichs 50-000.84/03/12.8403160373
- 8403200225 Advises that similarity of Unit 1 & 2 175-ton polar crane verified by noting that cranes purchased under same contract w/same vendor, using identical procurement specs, per NUREG-0612 & 840223 telcon MILLB, L M Tennessee Valley Authority 84/03/14 ADENSAM, E Licensing Branch 4 2pp 22679 361 24X Fiche 30-390,84/03/14,8403200225
- 8403260212 Forwards revised info re monorail paths, updating util 840206 ltr responding to Generic Ltr 81-07 concerning NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants " Field investigation will be provided 1 month prior to fuel load MILLB, L M Tennessee Valley Authority 84/03/20 ADENBAM, E Licensing Branch 4 2pp 22754 164 24X Fiche 50-390,84/03/20, 84020212
- B403260218 Forwards shift experience info.in response to Util Group on Operating Bhift Experience request MILLS,L M Tennessee Valley Authority 84/03/20 DENTON,H R Office of Nuclear Reactor Regulation. Director 8pp 22756 091 24X Fiche 50-390,84/03/20.8403260218

E NRC Safety Evaluation Report (SER), supple & correspondence

- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document antirely withheld (ref FOIA Exemption 5) Review of add1 documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, S 1 Garvey, Schubert, Adams & Barer 7pp 22583 224 24X Fiche 50-000,84/02/13,8403080179.
- --B005130793 Provides status of SER inputs & acceptance reviews for DL & CP applications Schedule should be met BURKE.W C Effluent Treatment Systems Branch 80/02/04 KREGER,W E Assistant Director for Site Analysis Ip 22583 235 24% Fiche.50-000.84/02/13,8403080179
- B403120179 Forwards info supporting util position that implementation of add1 insp criteria provides no add1 increase in safety.

 per BER (NUREG-0847)

 MILLB,L M Tennessee Valley Authority B4/03/07 ADENSAM, E

 Licensing Branch 4 3pp 22590 205 24X Fiche 50-390, 84/03/07, 8403120179
- 840330003B Forwards responses to NRC 840214-16 audit findings re util equipment qualification program per NVREG-0847 (SER) W/P4 oversite drawings Aperture cards are available in PDR MILLG.L.M Tennessee Valley Authority 84/03/20 ADENSAM.E Licensing Branch 4 138pp 22824 146 24X Fiche 50-390,84/03/20.8403300038
- 8403270218 Forwards add1 info re qualification of diesel generator auxiliary sys piping (SER Open Item 13), in response to NRC B40112 request Diesel engine auxiliary sys acceptable, based on QDC 1 requirements MILLS,L M Tennesses Valley Authority B4/03/21 ADENBAM,E, Licensing Branch 4 6pp 22770 259 24X Fiche 50-370,84/03/21,8403270218

F Becurity, medical, emergency & fire protection plans

- 8403070092 Submits second supplemental response to NRC ltr reviolations noted in IE Insp Repts 50-390/82-20 & 50-391/82-20 Corrective actions fire protection actions will be complete by 840131 KAMMER, D S Tennesses Valley Authority 83/11/29 O'REILLY, J P Region 2, Office of Director ip 22541 219 24X Fiche: 50-390,83/11/29,8403070092
- 8402090380 Forwards Rev 2 to Procedure IP-10, "Medical Emergency Procedure" & Rev 3 to radiological emergency plan MILLS,L M. Tennessee Valley Authority 84/02/06 ADENSAM,E Licensing Branch 4 2pp 22161.136, 24X Fiche 50-390,84/02/06,8402090380

-)2090384 Rev 2 to Procedure IP-10, "Medical Emergency Procedure HILLER,W A Tennessee Valley Authority 83/11/08 4pp 22161 138 24X Fiche 50-390.84/02/06.8402090380
- 040295 Rev 5 to Protedure IP-9. "Muscle Shoals Emergency Ctr Dlementing Protedures Datument " M/840213 ltr GMELL, R Tannessee Valley Authority 84/02/13 63pp 22518 023 X Fitch 50-000,84/02/13.8403060235
-)20334 Forwards response to informal questions re calculation of tical temp gradients, per Radiological Emergency Planning nch request Backup procedures will be limited to times n radiological emergency program procedures activated .LS.L M Tennessee Valley Authority 84/02/27 ADENSAM, E:ensing Branch 4 4pp 22439 288 24X Fiche 50-390.84/02/27,)3020334
-)20236 Forwards Rev 4 to physical security plan Rev withheld f 10CF873 21)
 LS.L M Tennessee Valley Authority 84/02/28 DENTON, H R tee of Nuclear Reactor Regulation, Director 1p 22440 041 24x: the 50-390,84/02/28,8403020234
- 160147 Forwards revised effective pages to Xnoxville Emergency Ctr. stral Emergency Control Ctr.DIV of Nuclear Power Emergency & Muscle Shoals Emergency Control Ctr emergency plan ilementing procedures W/o Muscle Shoals pages L.S.L M Tennessee Valley Authority 84/02/28 G'REILLY, J Pion 2. Diffice of Director ip 22516 165 24X he 50-000.84/02/28.8403060147
- 13060163 Revised list of effective pages to Knozville Emergency Ctr mergency plan implementing procedures Tennessee Valley Authority 84/02/06 Bpp 22516 166 24Y iche 50-000.84/02/28.8403060147
- MO60189 Revised list of effective pages to Central Emergency ontrol Ctr emergency plan implementing procedures
 Tennessee Valley Authority B4/02/06 Bpp 22516 174 24X
 Fiche 50-000.84/02/28.8403060147
- 33040206 Revised list of affective pages to Div of Nuclear Power Imergency Ctr emergency plan implementing procedures Tennessee Valley Authority 84/02/06 4pp 22516 182 24X Fiche 50-000.84/02/28.8403060147
- .60209 Act receipt of 831230 ltr re emergency exercise scheduled June 1984 Scenario will be reviewed & any addl comments details of exercise will be made by telephone to B Marks RRELLI.D M Division of Project & Resident Frograms 84/03/02 RRIS.H G Tennessee Valley Authority 1p 22659 232 24X the 50-390.84/03/02.8403160209
- .60345 Extends invitation to attend region B40316 workshop at ional ofc to discuss 10CFR50. App R requirements & recent iults of insp to help resolve misunderstandings associated requirements
 **RS.R.C. Division of Project & Resident Programs 84/03/02 RRIB.H.G. Tennesse Valley Authority 2pp 22660 083 24X :he 50-000:84/03/02.8403160345
- :60008 Forwards 1E Insp Rept 50-390/84-17 on 840221-23 No Hations or deviations identified RELLID M Division of Project & Resident Programs 84/03/13 RRIS: M G Tennessee Valley Authority 2pp 82655 171 24X the 50-390,84/03/13,8403160008
- 33160016 IE Insp Rept 50-390/B4-17 on B40221-23 No violations noted Major areas inspected implementation status of security plan commitments Details withheld (ref 10CFR2 790 73 21)
- 'ODIN.W Region 2: Office of Director MCGUIRE.D.R Division of margency Preparedness & Materials Safety 84/03/12 1p 12655-173 24% Fiche 50-390:84/03/13:8403160008
- PO145 Rev 5 to radiological emergency plan updating agreement 1tr UEx.correcting filing error for agreement ltr U/Rhea inty Ambulance Svc W/84021 ltr.
 LB.L M Tennessee Valley Authority B4/03/21 ADENSAM.E ensing Branch 4 11pp 22767 122 24X Fiche 50-370.84/03/21. d270145
- surance & indemnity information
- 60277 Forwards Endorsement 23 to NELIA Policy NF-236 K.J.R. Marsh & McLennan. Inc. 84/02/28 SALTZMAN, J. Assistant ector for State & Licensee Relations 2pp 22517 045 24x he 50-390.84/02/28.8403060277

- Q Inspection reports, IE Bulletins & correspondence
- 8403070230 Supple response to NRC 820707 ltr re violations noted in IE Insp Repts 30-390/82-18 & 50-391/82-15 Corrective actions operational GA evaluator resources increased by 50% MILLS,L M Tennessee Valley Authority 83/09/09 0'REILLY,J P Region 2, Defice of Director 4pp 22541 304 24% Fiche 50-390.83/09/09,8403070230
- 8403070235 Suppls response to NRC 820827 ltr re deviations noted in IE Insp Repts 50-390/82-29 & 50-391/82-26 Corrective actions piping drawings of reactor & auxiliary bldgs completed 830901
- NILLS.L M Tennessee Valley Authority 83/10/19 D'REILLY.J P Region 2. Office of Director 1p 22541 309 24X Fiche 50-370.83/10/19.8403070235
- 8403070245 Suppls response to NRC 821109 ltr re violations noted in IE Imap Repts 50-390/82-05 & 50-391/82-03 Corrective actions will be completed by 831212 for Unit 1 & 840109 for Unit 2 HILLS:L M Tennessee Valley Authority 83/11/01 D'REILLY:J P Region 2. Office of Director 1p 22547 295 24X Fiche 50-390.83/11/01.8403070245
- 8403070092 Submits second supplemental response to NRC ltr reviolations noted in IE Insp Repts 50-390/82-20 & 50-391/82-20 Corrective actions fire protection actions will be complete by 840131 KAMMER, D S Tennessee Valley Authority 83/11/29 O'REILLY, J P Region 2. Office of Director ip. 22541 219 24X Fiche 50-390,83/11/29,8403070092
- 8403160201 Forwards IE Insp Repts 50-390/84-04 & 50-391/84-04 on 840123-25 No violations or deviations identified VERRELLI.D M Division of Project & Resident Programs 84/02/14, PARRIS.H & Tennessee Valley Authority 2pp 22659 342 24X Fiche 50-390,84/02/14,8403160201
- --8403160202 IE Insp Repts 50-390/84-04 & 50-391/84-04 on 840123-25 No violations or deviations identified Major areas inspected preoperational radiological effluent & environ monitoring programs; program mgt & administrative controls CUNNINGHAMA L. Region 2. Office of Director MONTGOMERY, D M Division of Engineering & Operational Programs 84/02/10 5pp 22655 344 24X Fichs 50-390,84/02/14,8403160201
- 8403160214 Forwards IE Insp Repts 50-390/83-56 & 50-391/83-44 on 831225-840120 No violations or deviations identified VERRELLI.D M Division of Project & Resident Programs 84/02/17 PARRISH & Tennessee Valley Authority 2pp 22661 047. 24X Fiche 50-390-84/02/17.8403160214
- --B403160222 IE Imp Repts 50-390/83-56 & 50-391/83-44 on B31225-840120 No violation or deviations identified Major areas inspected, action on previous enforcement matters & insplitment on licensee identified items & verification of as-builts.

 SHYMLOCK M B , BUAN W B , HOLLAND W E Region 2, Office of Director B4/02/16 9pp 22661 069 24X Fiche 50-390,84/02/17,8403160214
- B403160237 Forwards IE Insp Rept 30-390/84-09 on 840130-0203 No violations or deviations noted VERRELLI, D M Division of Project & Resident Programs 84/02/27 PARRIB, H O Tennessee Valley Authority 2pp 22660 315 24X Fiche-50-390,84/02/27,8403160237
- --B403i60240 IE Insp Rept 50-390/84-09 on 840i30-0203 No violations or deviations noted Major areas inspected const status & as-built configuration for radioactive resin transfer sys & preoperational testing of radwasts sys.
 HDEEY.C M. Region 2. Office of Director BARR,K.P. Division of Engineering & Operational Programs 84/02/23 Bpp 22660.317
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl.

 JURDAN, E L. Division of Emergency Preparadness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22909 239 24% Fiche 50-000.84/02/28.8401190072
- 8403290201 Forwards IE Insp Repts 50-390/84-06 & 50-391/84-06 on BA0130-0203 No violations or deviations identified VERRELLI,D M Division of Project & Resident Programs 84/03/01, PARRISH 0 Tennessee Valley Authority 2pp 22803,294 24X Fiche 50-390,84/03/01,8403290201

- ---8403270207 IE insp Repts 30-370/84-06 & 30-391/84-06 on 840130-0203 No violations or deviations noted Major areas inspected preoperational test program, test program implementation & licenses action on previous enforcement matters THOMAS, M. Region 2, Office of Director JAPE, F. Division of Engineering & Operational Programs 84/02/27 5pp 22803 276 24X Fichs 30-390,84/03/01.8403290201
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl GRACE, J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp. 22552 329 24X Fiche 50-000,84/03/02,8402090007
- 8402070008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN: E L Division of Emergency Preparedness & Engineering Response (Past 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008
- B402070007 IE Info Notice B4-15, "Reporting of Radiological Releases"
 Byc list encl
 JDRDAN, EL Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc 119pp. 22553 217. 24X Fiche 50-000.84/03/02,8402090009
- B402090011 IE Info Notice 84-17. "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JURDAN: E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York: Inc 117pp 22553 336 24X Fiche 50-000.84/03/05.8402090011
- 8403160350 Ack receipt of 840222 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/84-01 & 50-391/84-01 VERRELLI, D M Division of Project & Resident Programs. 84/03/05 PARRIGH 6. Tennessee Vallay Authority, 1p 22660 166 24X Fichs 50-390,84/03/05,8403160350
- --8403160364 Responds to NRC 840123 ltr re violations noted in IE Insp Repts 50-390/84-01 & 50-391/84-01 Corrective actions deficiencies documented in Nonconformance Rept 5307 which require rework per design drawings & vendor catalogs MILLB,L M Tennessee Valley Authority 84/02/22 O'REILLY, J P Region 2. Office of Director. 3pp 22660 167 24X Fiche 50-390,84/03/05,8403160350
- --8403160374 Forwards IE Insp Repts 50-390/84-01 & 50-391/84-01 on 840103-06 & notice of violation VERRELLID M Division of Project & Resident Programs 84/01/23 PARTE: H G Tennessee Valley Authority 2pp 22660 169 24X Fich
- --8403160378 Notice of violation from insp on 840103-06 * Region 2, Office of Director 84/01/19 ip 22660 171 24X Fiche 50-390,84/03/05,8403160350
- --B4031603B3 IE Insp Repts 50-390/84-01 & 50-391/84-01 on 840103-06 Violation noted failure to follow procedures for hanger insp. LIU-W C Region 2, Office of Director BLAKE, J J Division o Engineering & Operational Programs 84/01/19 5pp 22660 172 24X Fichs 50-390,84/03/05,8403160350
- 8403290042 Forwards IE Insp Rept 50-390/84-10 on 840206-10 No viblations or deviations noted VERRELLI, D M Division of Project & Resident Programs 84/03/06 PARRIES HO Tennessee Valley Authority 2pp 22806 252. 24X Fiche. 50-390, 84/03/06, 8403290042
- ~~B403290050 IE Insp Rept 50-390/84-10 on 840206-10 No violations or deviations noted. Major areas inspected review of lab GC program.review of procedures & instructions, facilities, equipment & capability tests.
 TROUP.0 L. Region 2. Defice of Director MONTGOMERY.D Division of Engineering & Operational Programs 84/02/27 11pp 22806:254 24X Fiche 50-390.84/03/04.8403290042
- 8402090024 IE Info Notice 84-09. Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl UDRDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07. Consolidated Edison Co. of New York. Inc. 118pp 22635.049 24X Fichs. 30-000.84/03/07. 840209002A
- B402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Bys." Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584:186 24X Fiche 50-000,84/03/07,8402090028

- 8402090031 IE Bulletin 84-02. "Failures of GE Type HFA Relays in Use Class IE Bafety Sys " Svc list encl DEYOUNG.R C Director's Defice Office of Inspection and Enforcement 84/03/12 Consolidated Edison'Co of New York, Inc 134pp 22823 094 24X Fiche 50-000.84/03/12.8402090031
- 8403160008 Forwards IE Insp Rept 50-390/84-17 on 840221-23 No violations or deviations identified VERRELLI.D N Division of Project & Resident Programs 84/03/13 PARRIS.H C Tennessee Valley Authority 2pp 22655 171 24X Fiche 50-390,84/03/13,8403160008
- --8403160016 IE Insp Rept 50-390/84-17 on 840221-23 No violations noted Major areas inspected implementation status of security plan commitments Details withheld (ref 100FR2 790 & 73 21)
 TOBIN.W Region 2. Office of Director MCGUIRE.D R Division of Emergency Preparedness & Materials Safety 84/03/12 1p 22653 173 24X Fiche 50-390.84/03/13,8403160008
- 8403160271 Forwards IE Insp Rpets 50-390/84-03 & 50-391/84-03 on 840117-20 & 24-27 No violations or deviations identified VERRELLI.D M Division of Project Resident Programs 84/03/15 PARRIS.H 9 Tennessee Valley Authority 2pp 22660 351. 24X Fichs 50-390/84/03/15/8403160271
- --8403160279 IE Imap Repts 50-390/84-03 & 50-391/84-03 on 840117-20 & 24-27 No violations or deviations identified Major areas inspected independent imap effort & followup on licensee identified items. unresolved items & IE bullatins COLEY. J L Region 2. Office of Birector BLAKE, J J Division of Engineering & Operational Programs 84/02/13 Bpp 22660 353 24X Fiche 50-390,84/03/15,8403160271
- B402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl. JORDAN.E L Division of Emergency Preparadness & Engineering Response (Post B30103) B4/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000.84/03/21.8402070043
- 8402090044 IE Info Notice 84-20. "Byc Life of Relays in Safety-Related Sys " Syc list enc! JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044
- R Periodic operating reports & related correspondence
- 8403020443 Forwards monthly status rept of offsite emergency preparedness for OL reviews for Jan 1984 Changes in FEMA finding dates not caused by delay due to offsite emergency planning issues
 DIRCKS, W. J. Office of the Executive Director for Operations 84/02/21 PALLADINO Commissioners 9pp 22492 083 24X Fiche 50-000.84/02/21.8403020443
- S Reportable occurrences. LERs & related correspondence
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines. Gimpel NPS-4 T&T valve, to close Encl ltr dtd 840203 sent to listed utils GE notified of affected units in BWR plants.
 THEROXX.R R Terry Corp 84/02/22 MOODRUFF.R W Director's Office. Office of Inspection and Enforcement App 22704.327 24X Fiche 50-000.84/02/22.8403210032
- 8403010339 Second interim deficiency rept re environ qualification of mechanical equipment Initially reported on 831109 Condition not reportable per 10CFR50 55(e) Next rept to be submitted by 840330 MILLS.L.M. Tennessee Valley Authority 84/02/23 D'REILLY, J P Region 2, Office of Director 3pp 22432 321 24X Fiche 50-390,84/02/23.8403010339
- 8403070050 Final deficiency rept re live loads not considered in concrete partition wall design Initially reported on 831213 Program established to determine walls requiring structural restraints Typical support drawings revised MILLS,L M Tennesse Valley Authority 84/02/28, 0'REILLY,J P Region 2, 0fftc of Director 3pp 22575 360 24X Fiche.50-370,84/02/28,8403070050
- B403070206 First interim deficiency rept re improper design loads for base plates & anchor bolts Initially reported on B40131 Two supports under evaluation using flexible plate analysis Next rept will be submitted by 840416
 MILLS.L M Tennessee Valley Authority 84/02/28 O'REILLY, J P Region 2, Office of Director 2pp 22574 326 24X
 Fiche 50-390.84/02/28.8403090206

- 8403070174 Second interim deficiency rept re alteration of fire doors & frames w/o engineering design approval Initially reported on 841114 Altered fire-rated doors replaced or repaired Next rept expected by 840413 MILLS.L M Tennessee Valley Authority 84/02/27 O'REILLY.J P Region 2. Office of Director 2pp 22538 349 24X Piche 50-390.84/02/29.8403070174
- 8403070286 Final deficiency rept re Parsons-Peebles emergency diesel generator 28-B rear bearing problem Initially reported on B30627 Generator repaired to be used as spare Also reported per Part 21
 MILLS:L M Tennessee Valley Authority 84/02/29 O'REILLY:J P Region 2, Dffice of Director 4pp 22546 224 24x
 Fiche 50-390.84/02/27,8403070286
- 8403150127 Final deficiency rept to temp of Class IE madium voltage cables in cable trays Initially reported on 840118 Conditions not reportable per 10CFR50 53(e) MILLS:L M Tennessee Valley Authority 84/03/05 O'REILLY,J P Region 2. Office of Director 2pp 22640 315 24% Fiche 50-390.84/03/05.8403150127
- 8403190054 Final deficiency rept re loading on diesel generator for LOCA & blackout causing unacceptable frequency transient Initially reported on 831107. Mods made to all four diesel generator load sequences increasing sequence time MILLS.L M Tennessee Valley Authority 84/03/08 0'REILLY.J P Region 2. Dffice of Director 3pp 22666 125 24X Fiche 30-390.84/03/08.8403190054
- 8403190099 Suppls info to 831017 final deficiency rept re supports not designed or modified as required by engineering change notice Initially reported on 830118 Design & subsequent const will be completed by 840517 MILLS.L. M Tennessee Valley Authority 84/03/08 D'REILLY, J P Region 2. Office of Director. 19 22669 304 24X Fiche 50-390.84/03/08.8403190099
- 8403190338 First interim deficiency rept re installed supports not in agreement w/Westinghouse requirements Initially reported on 840210 Pressurizer surge line support designs updated Investigation in progress Next rept by 840420 MILLS.L M Tennessee Valley Authority 84/03/08 p'REILLY, J P Region 2. Office of Director 2pp 22673 310 24X Fichs 50-390.84/03/08,8403190358
- 8403210086 Final deficiency rept re fire damper fusible links Initially reported on 840214 All existing fusible links will be replaced w/higher temp fusible links that can withstand temps occurring during high energy line break MILLS.L M Tennessee Valley Authority 84/03/13 D'REILLY, J P Region 2. Office of Director 2pp 22705 087 24X Fiche 50-390.84/03/13,8403210086
- 8403210037 Final deficiency rept re operating conditions used in giping amalysis Initially reported on 820518 Pipe stresses for test runs within ASME Code allowables Flanges, nozzles & supports qualified Documentation will be completed by 860131 MiLLSI. M Tennessee Valley Authority 84703/15 O'REILLY, J P Region 2, Office of Director App 22707 005 24x Fiche 50-390,84/03/15,8403210037
- 8403210066 First interim deficiency rept re Target Rock solenoid valves on post-accident sampling facility not meeting backpressure requirements Initially reported on 840215 Engineering change notices being issued Next rept by 840423
 MILLS.L M Tennessee Valley Authority 84/03/15 D'REILLY, J P Region 2. Office of Director 2pp 22704 355 24X
 Fiche. 50-390.84/03/15.8403210066
- 8403300109 First interim deficiency mapt be new defects in Berton pressure transmitters supplied by Westinghouse Initially reported on 840223 Westinghouse will define corrective action by 840331 Also reportable under Part 21.
 MILLS.L M Tennessee Valley Authority 84/03/22 D'REILLY, J P Region 2. Office of Director 2pp 22821 223 24X
 Fiche 50-390.84/03/22.8403300109

V Operator Examinations

8403260218 Forwards shift experience info.in response to Util Group on Operating Shift Experience request MILLS.L M Tennessee Valley Authority 84/03/20 DENTON,H R Office of Nuclear Reactor Regulation. Director 8pp 22756 091 24X Fiche 50-370.84/03/20.8403260218

- DOCKET 50-391 WATTS BAR NUCLEAR PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8403060534 Notification of 840315-16 meetings w/util in Sweetwater.TN to conduct confirmatory site visit per Section 13 6 of BRP (NUMEG-0800)
 KENYON,T J Licensing Branch 4 84/02/28 ADENSAM,E 0 Licensing Branch 4 3so 22552
- 8403160247 Informs of 840327 meeting to discuss proposed responses to NRC questions on Rev 7 to topical GA program per 840302 telcon
 LEMIB.R C Region 2. Office of Director 84/03/08 PARRIS.H G
 Tennessee Valley Authority 1p 22660 361 24X
 Fiche 30-000.84/03/08.8403160247
- 8403140373 Notifies of use of ASME Nuclear Components Code Case N32-4 for hydrostatic testing of Class 3 embedded piping NRC position re use of Code Case N32-4 requested MILLS,L M Tennessee Valley Authority 84/03/12 DENTON,H R Office of Nuclear Reactor Regulation, Director 1p 22660 014 24X Ficha 50-000.84/03/12.8403160373
- 8403200225 Advises that similarity of Unit i & 2 175-ton polar crane verified by noting that cranes purchased under same contract w/same vendor, using identical procurement specs, per NUREO-0612 & 840223 telcon MILLS.L M Tennessee Valley Authority 84/03/14 ADENSAM.E Licensing Branch 4 2pp 22699 361 24X Fiche 50-390,84/03/14,8403200225
- 8403260212 Forwards revised info re monorail paths.updating util 840206 itr responding to Generic Ltr 81-07 concerning NUREO-0612.
 "Control of Heavy Loads at Nuclear Power Plants " Field investigation will be provided i month prior to fuel load MILLS.L M Tennessee Valley Authority 84/03/20 ADENSAM.E Licensing Branch 4 2pp 22756 164 24X Fiche 50-390.84/03/20, 8403260212
- 8403260218 Forwards shift experience info, in response to Util Group on Operating Shift Experience request MILLS.L M Tennessee Valley Authority 84/03/20 DENTON, H R Dffice of Nuclear Reactor Regulation. Director Spp 22786 091 24X Fiche 50-390.84/03/20.8403260218
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8403080179 Fourth partial response to FOIA request for six categories of documents refacilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of addl documents subj to request continuing FELTON, J H Division of Rules and Records 84/02/13 ANDERSON, B: Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000,84/02/13,8403080179
- --8005130793 Provides status of SER inputs & acceptance reviews for OL & CP applications Schedule should be met BURKE.W C Effluent Treatment Systems Branch B0/02/06 KREGER.W E Assistant Director for Site Analysis 1p 22583 235 24X Fiche 50-000.84/02/13,8403080179
- B403120179 Forwards info supporting util position that implementation of add1 insp criteria provides no add1 increase in safety, pur SER (NUREG-0847)
 MILLS,L M Tennessee Valley Authority B4/03/07 ADENSAM,E Licensing Branch 4 3pp 22590 205 24X Fiche 50-390,84/03/07, B403120179
- 8403300038 Forwards responses to NRC 840214-16 audit findings re util squipment qualification program.per NUREQ-0847 (SER) H/84 oversize drawings Aperture cards are available in PDR MILLS.L M Tennessee Valley Authority. 84/03/20 ADENSAM.E, Licensing Branch 4 138pp 22824 146 24X Fiche 50-390,84/03/20,8403300038
- 8403270218 Forwards add1 info re qualification of diesel generator auxiliary sys piping (SER Open Item 13).in response to NRC 840112 request Diesel engine auxiliary sys acceptable, based on ODC i requirements
 MILLG.L M Tennessee Valley Authority 84/03/21 ADENBAM.E Licensing Branch 4 App 22770 259 24X Fiche 50-390.84/03/21, 8403270218

F Security, medical, emergency & fire protection plans

- 840:3070092 Submits second supplemental response to NRC ltr reviolations noted in IE Insp Repts 50-390/82-20 & 50-391/82-20 Corrective actions fire protection actions will be complete by 840:131 KAMMER.D B Tennessee Valley Authority 83/11/29 O'REILLY, JP Region 2, Office of Director 1p 22541 219 24X Fiche 50-390.83/11/29.8403070092
- 8402070380 Forwards Rev 2 to Procedure 1P-10. "Medical Emergency Procedure" & Rev 3 to radiological emergency plan MILLS:L M Tennessee Valley Authority 84/02/06 ADENSAM.E Licensing Branch 4 2pp 22161 136 24% Fiche 50-390,84/02/06. 8402070380
- --8402070384 Rev 2 to Procedure IP-10. "Medical Emergency Procedure "
 MILLER, W A Tennessee Valley Authority 83/11/08 4pp
 22161 138 24X Fiche 50-390,84/02/06,8402070380
- 8403060235 Rev 5 to Procedure IP-9. "Muscle Shoals Emergency Ctr Implementing Procedures Document " W/B40213 ltr MAXWELL.R Tennessee Valley Authority 84/02/13 63pp. 22518 023 24X Fichs 50-000,84/02/13,8403060235
- 8403020334 Forwards response to informal questions re calculation of vertical temp gradients, per Radiological Emergency Planning Branch raquest Backup procedures will be limited to times when radiological emergency program procedures activated, MILLS, L M Tennessee Valley Authority 84/02/27 ADENBAM.E Licensing Branch 4 4pp. 22439 288 24X Fiche 50-390,84/02/27, 8403020334
- 8403020236 Forwards Rev 4 to physical security plan Rev withheld (ref 10CFR73 21) MILLBIL M Tennessee Valley Authority 84/02/28 DENTON; H R Office of Nuclear Reactor Regulation; Director 1p 22440 041 24X Fiche: 50-390, 84/02/28, 8403020236
- 8403060147 Forwards revised effective pages to Knoxville Emergency Ctr, Central Emergency Control Ctr, Div of Nuclear Power Emergency Gtr & Muscle Shoals Emergency Control Ctr emergency plan implementing procedures W/o Muscle Shoals pages MILLS,L K Tennessee Valley Authority 84/02/28 O'REILLY, J P Region 2. Office of Director 1p 22516 165 24X Fiche 50-000,84/02/28,8403060147
- --2403060163 Revised list of effective pages to Knoxville Emergency Ctr emergency plan implementing procedures a Tannessee Valley Authority 84/02/06 8pp 22516 166 24X Fiche 30-000.84/02/28,8403060447
- ---8403060189 Revised list of effective pages to Central Emergency Control Ctr emergency plan implementing procedures * Tennessee Valley Authority 84/02/06 8pp 22516 174 24X Fich* 50-000,84/02/28,8403040147
- --B403060206 Revised list of effective pages to Div of Nuclear Power Emergency Ctr emergency plan implementing procedures # Tennesses Valley Authority B4/02/06 4pp 22516.182 24X Fiche 30-000.84/02/28.8403060147
- 8403160209 Ack receipt of 831230 ltr re emergency exercise acheduled for June 1984 Scenario will be reviewed & any addl comments on datails of exercise will be made by telephone to B Marks VERRELLI,D M Division of Project & Resident Programs B4/03/02 PARRIS:H 0 Tennesses Valley Authority ip 22655:232 24X Fiche: 50-390,84/03/02,8403160209
- 8403160345 Extends invitation to attend region 840316 workshop at regional ofc to discuss 100FR50.App R requirements & recent results of insp to help resolve misunderstandings associated w/requirements

 LEMIBLE C Division of Project & Resident Programs 84/03/02 FARRIS, H 9 Tennessee Valley Authority 2pp 22660 083 24X Fiche. 50-000.84/03/02.8403160345
- 8403270145 Rev 5 to radiological emergency plan updating agreement ltr w/DoE.correcting filing error for agreement ltr w/Rhea County Ambulance Svc W/840321 ltr.
 MILLØr. M Tennessee Valley Authority 84/03/21 ADENSAM, E.
 Licensing Branch 4, 11pp 22767 122 24X Fiche 50-370.84/03/21,
 8403270145

J Insurance & indemnity information

B4030A0277 Forwards Endorsement 25 to NELIA Policy NF-256
BUCK, J R Marsh & McLennan, Inc 84/02/28 SALTZMAN, J Assistant
Director for State & Licenses Relations 2pp 22517 045
Fichs 30-390,84/02/28,84030A0277

Q Inspection reports. IE Bulletins & correspondence

- 8403070230 Supply response to NRC 820707 ltr re violations noted in IE Insp Repts 50-390/82-18 & 50-391/82-15 Corrective actions operational GA evaluator resources increased by 50% MILLS:L M Tennessee Valley Authority 83/09/09 0'ÆILLY.J P Region 2. Office of Director 4pp 22541 304 24% Fichs 50-390.83/09/09.8403070230
- 8403070239 Suppls response to NRC 820927 ltr re deviations noted in IF Insp Repts 50-390/82-27 & 50-391/82-26 Corrective actions plping drawings of reactor b auxiliary bldgs completed 830701 MILLS.L M Tennessee Valley Authority 83/10/19 O'REILLY.J F Region 2. Office of Director 1p 22541 309 24X Fiche 50-390.83/10/19.8403070235
- B403070245 Suppls response to NRC 521109 ltr re violations noted in IE Insp Repts 50-390/82-05 & 50-391/82-03 Corrective actions will be completed by 831212 for Unit I & 840109 for Unit 2
 MILLB.L M. Tennessee Valley Authority B3/11/01 O'REILLY, J P Region 2. Office of Director ip 22547 275 24X
 Fiche 50-370.83/11/01.8403070245
- 8403070092 Bubmits second supplemental response to NRC ltr reviolations noted in IE lmsp Repts 50-390/82-20 & 50-391/82-20 Corrective actions fire protection actions will be complete by 840131 MAMMER, D S Tennessee Valley Authority 83/11/29 O'REILLY, J P Region 2. Office of Director 1p 22541 219 24X Fiche 50-390.83/11/29.8403070092
- B403160201 Forwards IE Insp Repts 50-390/84-04 & 50-391/84-04 on B40123-25 No violations or deviations identified VERRELLI.D M Division of Project & Resident Programs 84/02/14 PARRIS.H G Tennessee Valley Authority 2pp 22655 342 24X Fiche 50-370.84/02/14.8403160201
- --8403160202 IE Insp Repts 50-370/84-04 & 50-371/84-04 on 840123-25 No violations or deviations identified Major areas inspected prespectational radiological effluent & environ monitoring programs.program mpt & administrative controls CUNNINGHAM. L. Region 2. Office of Director MONTGDMERY.D M Division of Engineering & Operational Programs 84/02/10 5pp 22655 344 24X Fiche 50-390,84/02/14,8403160201
- 8403160214 Forwards IE Insp Repts 50-390/B3-56 & 50-391/B3-44 on B31225-B40120 No violations or deviations identified VERRELLI,D M Division of Project & Resident Programs B4/02/17 PARRIS,H O Tennessee Valley Authority 2pp 22661 067 24X Fiche 50-390,84/02/17,8403160214
- --B403160222 IE Inap Repts 50-390/B3-56 & 50-391/B3-44 on B31225-B40120 No violation or deviations identified Major areas inspected action on previous enforcement matters & insplictments, followup on licenses identified items & verification of as-builts SHYMLOCK. M B . SHAN. W B . HOLLAND. W E . Region 2. Office of Director B4/02/16 9pp 22661 069 24X Fichs 50-390.84/02/17. B403160214
- 8401170072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc. 115pp 22707 237 24% Fiche 50-000.84/02/28,8401170072
- 8403290201 Forwards IE Insp Repts 50-390/84-06 & 50-391/84-06 on 840130-0203 No violations or deviations identified VERRELLI.D M Division of Project & Resident Programs 84/03/01 PARRIB.H O Tennessee Valley Authority 2pp 22803 294 24X Fiche 50-390,84/03/01.8403290201
- --8403270207 IE Insp Repts 50-390/84-06 & 50-391/84-06 on 840130-0203 No violations or deviations noted Major areas inspected preoperational test program, test program implementation & licensee action on previous enforcement matters THOMAS, M. Region 2. Office of Director JAPE, F. Division of Engineering & Operational Programs 84/02/27 5pp 22803 276 24X Fiche 50-370,84/03/01,8403270201
- B402070007 IE Info Notice B4-14, "Highlights of Recent Transport Regulatory Reve by DOT & NRC " Svc list encl GRACE.J N Division of GA. Safeguards & Inspection Programs (Post B30103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 327. 24X Fiche 50-000.84/03/02.8402090007
- B402090008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate" Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/02 Consolidated Edison Co of New York, Inc. 122pp 22533 098 24X Fiche 50-000,84/03/02.8402090008

- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases" 10209009 IE into motive some Section of Emergency Preparedness & Engineering JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post E30103) 84/03/02 Consolidated Edison Co. of New York, Inc. 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- B402090011 IE Info Notice B4-17, "Problems W/Liquid Nitrogen Caoling Companents Below Nil Ductility Temp " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000.84/03/05,8402090011
- 8403160350 Ack receipt of 840222 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-390/84-01 & 50-391/84-01
 - & 30-391/84-01 VERRELLI,D M Division of Project & Resident Programs 64/03/05 PARRIS. H O Tennessee Valley Authority ip 22660 166 24X Fiche, 50-390, 84/03/05, 8403160350
- --8403160364 Responds to NRC 840123 ltr re violations noted in [E Insp Repts 50-390/84-01 & 50-391/84-01 Corrective actions deficiencies documented in Nonconformance Rept 5307, require rework per design drawings & vendor catalogs MILLB.L M Tennesses Valley Authority 84/02/22 (Region 2, Office of Director 3pp. 22460 167 24X Fiche 50-370,84/03/05,8403160350 O'REILLY, JP
- --B403160374 Forwards IE Imsp Repts 50-390/84-01 & 50-391/84-01 on B40103-05 & notice of violation VERRELLID N Division of Project & Resident Programs B PARRIS.H 0 Tennessee Valley Authority 2pp 22660 169 Fich 8 30-370, 84/03/05, 8403160350 84/01/23
- --B403160378 Notice of violation from insp on 840103-06 * Region 2, Office of Director 84/01/19 lp 22660 171 24X Fithe 50-390,84/03/05,8403160350
- --8403160383 IE Insp Repts 50-370/84-01 & 50-371/84-01 on 840103-06 Violation noted failure to follow procedures for hanger insp LIU.W C Region 2. Office of Director BLAKE, J J Division of Engineering & Operational Programs 84/01/19 5pp 22660 172 24% Fiche 50-390,84/03/05,8403160350
- 8402070024 IE Info Notice 84-07.Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc. 18pp 22635 049 24X Fiche 50-000,84/03/07,8402070024
- 8402090028 IE Info Notice 84-18: "Stress Corrosion Cracking in PWR Bys "Svc list end JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc. 118pg 22384 186 24X Fichs 50-000,84/03/07,8402090028
- 8402070031 IE Bulletin 84-02, "Failures of QE Type HFA Relays in Use in Class IE Safety Sys " 8vc list enc!

 BEYOUND, R C Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc i34pp 22823,094 24X Fiche 50-000.84/03/12,8402090031
- 8403160271 Forwards IE Insp Rpets 50-390/84-03 & 50-391/84-03 on 840117-20 & 24-27 No violations or deviations identified VERRELLI.D M Division of Project & Resident Programs 84/03/19ARRIGH 0 Tennessee Valley Authority 2pp 28660 351 24X Fiche 50-390.84/03/15.8403160271 84/03/15
- --8403160279 IE Insp Repts 50-390/84-03 & 50-391/84-03 on 840117-20 & 24-27 No violations or deviations identified Major areas inspected independent insp effort & followup on licensee identified items, unreasolved items & IE bulleting COLEY, JL Region 2. Office of Director BLAKE, JJ Division of Engineering & Operational Programs 84/02/13 Bpp 22660-353 24X Fiche 50-390, 84/03/15, 8403160271
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PMR Reactor Cavities " Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24% Fiche.50-000,84/03/21,8402090043
- B402090044 IE Info Notice B4-20. "Svc Life of Relays in Safety-Related Sys " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp. 22933 001 24X Fiche 50-000.84/03/21, 8402090044

- S Reportable occurrences, LERs & related correspondence
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines, Gimpel NPE4 T&T valve, to close Encl 1tr dtd 840203 sent to listed utils GE notified of affected units in BMR THEROUX,R R Terry Corp 84/02/22 WOODRUFF,R W Director's Office of Inspection and Enforcement 5pp 22706 327. 24X Fiche 50-000.84/02/22.8403210032
- B403010337 Second interim deficiency mept me environ qualification of mechancial equipment Initially meponted on 831107 Condition not reportable per 10CFR50 55(e) Next mept to be submitted by 840330.
 MILLS.L M Tennessee Valley Authority 84/02/23 0'REILLY, J P Region 2. Office of Director 3pp 22432 321 24X Fiche 50~390,84/02/23.8403010339
- 8403090050 Final deficiency rept re live loads not considered in concrete partition wall design Initially reported on 831213 Program established to determine walls requiring structural restraints Typical support drawings revised.
 MILLS.L M Tennesse Valley Authority 84/02/28 0'REILLY, J. Region 2. Office of Director 3pp 22575 360 24X Fiche 50-390,84/02/28,8403090050 D'RETLLY, J. P
- 8403090206 First interim deficiency rept re improper design loads for base plates & anchor bolts Initially reported on 840131 Two supports under evaluation using flexible plate analysis. Next rept will be submitted by 840416 MILLS.L M Tennessee Valley Authority 84/02/28 O'REILLY, J P Region P. Office of Director 2pp 22574 326 24X Fichs 30-390.84/02/28.8403090206
- 8403070174 Second interim deficiency rept re alteration of fire doors & frames w/o engineering design approval Initially reported on 841114 Altered fire-rated doors replaced or repaired Next rept expected by 840413 MILLS.L M Tennessee Valley Authority 84/02/29 O'REILLY.J P Region 2. Office of Director 2pp 22538 349 24X Fiche 50-370.84/02/29.8403070174
- 8403070286 Final deficiency rept re Parsuns-Peebles emergency diesel generator 28-8 rear bearing problem Initially reported on 830627 Generator repaired to be used as spare Also reported par Part 21 MILLS:L M Tennessee Valley Authority 84/02/27 D'REILLY, J P Region 2. Office of Director App 22546.224 24X Fichs 50-390,84/02/29,8403070286
- 8403150127 Final deficiency rept re temp of Class IE medium voltage cables in cable trays Initially reported on 840118 Conditions not reportable per IOCFR50 55(e) MILLS.L M Tennessee Valley Authority 84/03/05. O'REILLY, J P Region 2. Office of Director 2pp 22640 315 24X Fiche 50-390,84/03/05.8403150127
- 8403190054 Final deficiency rept re loading on diesel generator for LOCA & blackout causing unacceptable frequency transient. Initially reported on 831107, Mods made to all four diesel generator load sequences increasing sequence time MILLS.L M Tennesse Valley Authority 84/03/08 O'REILLY, J P Region P. Office of Director 3pp 22666 125 24X Fiche 50-390.84/03/08.8403170054
- 8403190358 First interim deficiency rept re installed supports not in appeament w/Hestinghouse requirements Initially reported on 840210 Pressurizer surge line support designs updated Investigation in progress Next rept by 840420 MILLS.L M Tennessee Valley Authority 84/03/08 O'REILLY, J P Region 2. Office of Director 2pp 226/3 310. 24X Fiche 50-390,84/03/08,8403190358
- 8403210086 Final deficiency rept re fire damper fusible links Initially reported on 840214 All existing fusible links will be replaced whigher temp fusible links that can withstand temps occurring during high energy line break.
 MILLS.L M Tennessee Valley Authority. 84/03/13 O'REILLY, J P. Region P. Office of Director. 2pp 22705 087 24X
 Fichs 50-390.84/03/13,8403210086
- 8403210037 Final deficiency rept re operating conditions used in piping analysis initially reported on 920518. Pipe stresses for test runs within ASME Code allowables Flanges, no.21es & supports qualified Documentation will be completed by 860131 MILLS.L. H. Tennesses Valley Authority 84/03/15 O'REILLY, J. P. Region 9. Office of Director 4pp 22707 005, 24X Fichs. 50-390, 84/03/15, 8403210037

- B403210066 First interim deficiency rept re Target Rock solenoid valves on post-accident sampling facility not meeting backpressure requirements Initially reported on 840215 Engineering change notices being issued Next rept by 840423
 MILLB.L M Tennessee Valley Authority 84/03/15 D'REILLY, J P Region 2, Office of Director 2pp 22704 355 24X
 Fiche 50~390.84/03/15,8403210066
- 8403300109 First interim deficiency rept re new defects in Barton pressure transmitters supplied by Westinghouse Initially reported on 840223 Westinghouse will define corrective action by 840331 Also reportable under Part 21 MILLB:L M Tennessee Valley Authority 84/03/22 O'REILLY.J P. Region 2. Office of Director 2pp 22821 223 24X Fiche. 50-370. 84/03/22. 8403300109

V. Operator Examinations

- 8403260218 Forwards shift experience info.in response to Util Group on Operating Shift Experience request
 MILLB.L M Tennesses Valley Authority 84/03/20 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 8pp 22756 091
 24X Fichs. 30-390, 84/03/20, 8403260218
- DOCKET 50-395 VIRGIL C SUMMER NUCLEAR STATION, UNIT 1 F. Security, medical, emergency & fire protection plans
- B403130397 Rev 10 to Emergency Plan Procedure EPP-002, "Communication & Notifications," W/840308 ltr & revised table of contents CDUNTS, M. BRADHAM, O B. DIXON, O W. Bouth Carolina Electric & Gas Co. 84/02/03 DENTON, H R D
- 8403070085 Forwards IE Insp Rept 50-375/84-03 on 840110-13 No violations or deviations noted.

 VERRELLI, D. M. Division of Project & Resident Programs. 84/02/07

 DIXON, D W South Carolina Electric & Gas Co 2pp 22541 210 Ficha 50-395,84/02/07,8403070085
- --8403070088 IE Insp Rept 50-975/84-03 on 840110-13 No violations or deviations noted Major areas inspected operational safety verification, maint & surveillance activities, physical protection, Tech Spec compliance & LER followup IGNATUNIS.A. J. Region 2. Office of Director CANTRELL.F & Division of Project & Resident Programs 84702/06 7pp 22541 212 24X Fiche 50-375,84/02/07,8403070085
- B403070007 Forwards IE Insp Rept 50-395/84-02 on 840116-20 No violations or deviations identified VERRELLI.D.M Division of Project & Resident Programs 84/02, DIXON,W.O South Carolina Electric & Gas Co 2pp. 22547 337 Fichs:50-395,84/02/10,8403070007 84/02/10
- --8403070013 IE Insp Rept 50-395/84-02 on 840116-20 No violations or deviations identified Major areas inspected emergency preparedness stodpart, P. G., KREN, J. L., JENKINS, Q. R. Region 2, Office of Director 84/02/09 8pp 22547 339 24X Fiche 50-395,84/02/10,8403070007
- B403160296 Notifies of B40316 workshop to discuss 10CFR50.App R requirements for fire protection results of recent App R insp to help resolve any misunderstandings associated W/requirements
- LEWIS.R C Division of Project & Resident Programs. 84/03/02 DIXON.O W South Carolina Electric & Gas Co ip 22660 079. 24X Fiche. 50-395, 84/03/02, 8403160296

Insurance & indemnity information

- 3403140015 Forwards Endorsement 31 to NELIA Policy NF-252 HOFFMAN.J Marsh & McLennan, Inc. 84/03/06 DINITZ.I Assistant Director for State & Licensee Reletions 2pp 22620 167 24X Fiche:50-375,84/03/06.8403140015
- . Operating license stage documents & correspondence
- 1403020297 Advises that util plans to follow general guidelines set forth by equipment vendor Technical info program rept, providing program description required by Section 2 2 2 of Generic Ltr 83-28, will be provided by 840430 DIXON, 0 H. South Carolina Electric & Qas Co. 94/02/29, DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22440:064 24X Fiche 50-395,84/02/29,8403020297.

- 8403060128 Application for amend to License NPF-12, revising Tech Spec requirement to rept new cracks of svc water intaka DENTON H R
 - structure
 DIXON.O W Gouth Carolina Electric & Gas Co* 84/02/29 DENTON.I
 Office of Nuclear Reactor Regulation, Director 2pp 22518 302
 24X Fiche 50-395.84/02/29.8403060128
- --8403060130 Proposed Tech Spec.changing monitoring program on stability of west embankment & effects on intake structure

 * Bouth Carolina Electric & Gas Co 84/02/29 ip 22518 304 24X Fichs 30-399,84/02/29.8403060128
- 8403220101 Notification of 840313 meeting w/util in Bethesda, MD to discuss 840123 spent fuel pool rerack submittal HOPKINS, J B Licensing Branch 4 84/03/02 ADENSAM, E G. Licensing Branch 4 3pp 22723 295 24X Fiche 50-395, 84/03/02, 8403220101
- 8403090271 Submits addl info re high density spent fuel storage racks, per 840217 request Combination of matls in support leg highly resistant to galling & provide desirable matl properties for boric acid environs
 DIXON.O W South Carolina Electric & Oas Co 84/03/06 DENTON.H R
 Office of Nuclear Reactor Regulation, Director 3pp 22574 165
 24X Fiche 50-395,84/03/06.8403090271
- 8403270183 Forwards portion of combustible gas control Tech Spec surveillance requirement inadvertently omitted from util 840118 response to Generic Ltr 83-37, "NUREO-0737 Tech Specs" Specs "
 DIXON,O W South Carolina Electric & Gas Co 84/03/22 DENTON, POFfice of Nuclear Reactor Regulation, Director 2pp 22771 123 24X Fiche 50-395,84/03/22,8403270183 DENTON, H R
- --8403270188 Proposed change to Tech Spec 4 6 5 1 re combustible gas control hydrogen monitors * Bouth Carolina Electric & Gas Co B4/03/22 1p 22771 125 24X Fiche 50-395,84/03/22,8403270183
- 8403270223 Application for amend to License NPF-12 requesting rev to Tech Spec Table 3 8-2, "Motor Operated Valves Thermal Overload Protection &/or Bypass Devices"
 DIXON.O W South Carolina Electric & Gas Co 84/03/22 DENTUN.H
 Office of Nuclear Reactor Regulation, Director 2pp 22770 265
 24X Fiche 50-375,84/03/22,8403270223
- *8403270225 Proposed Tech Spec rev to Table 3 8-2, "Motor Operated Valves Thermal Overload Protection &/or Bypass Devices " * South Carolina Electric & Oas Co. 84/03/22 2pp 22770 267 24X Fishe 50-375, 84/03/22, 8403270223
- G. Inspection reports, IE Bulletins & correspondence
- 8403070040 Submits followup rept re violation addressed in IE Insp Rept 50-393/83-01.detailing progress & completion schedule on development of master cross-reference program for identification of Tech Spec components
 DIXON.O W South Carolina Electric & Gas Co B3/09/15
 D'REILLLY.J P Region 2. Office of Director 2pp 22541 260 24X
 Fiche 50-395.83/09/15,8403070040
- 8403070085 Forwards IE Insp Rept 50-395/84-03 on 840110-13 No violations or deviations noted. VERRELLI.D M Division of Project & Resident Programs 84/02/ DIXON.O W South Carolina Electric & Qas Co 2pp 22541 210 Fiche 50-395.84/02/07.8403070085
- --B403070088 IE Insp Rept 50-395/84-03 on B40110-13 No violations or deviations noted Major areas inspected operational safety verification maint & surveillance activities; physical protection. Tech Spec compliance & LER followup IGNATONIS: A J Region 2. Office of Director CANTRELL. F B Division of Project & Resident Programs 84/02/06 7pp 22541.212 24X Fiche 50-395,84/02/07,8403070085
- 8403070007 Forwards IE Insp Rept 50-395/84-02 on 840116-20 No violations or deviations identified VERRELLI.D M Division of Project & Resident Programs 84/02/10 DIXON/W O South Carolina Electric & Oas Co 2pp 22547 337. 24X Fiche 50-395/84/02/10/8403070007
- --8403070013 IE Insp Rept 50-395/84-02 on 840116-20 No violations or deviations identified Major areas inspected emergency preparedness STODDART.P G , KREN.J L , JENKINS.Q.R. Region 2. Office of Director 84/02/09 8pp 22547 339 24X Fiche 50-395.84/02/10. 8403070007
- 8403160305 Forwards IE Insp Rept 50-395/84-01 on 840116-19 No violations or deviations noted

 VERRELLI,D M Division of Project & Resident Programs 84/02/15

 DIXON,O H South Carolina Electric & Gas Co 2pp 22660 066, 24X Fiche 50-395, 84/02/15, 8403160305

- --8403160307 IE Insp Rept 50-395/84-01 on B40116-19 No violations or deviations noted Major areas inspetted lab GC program, chemical & radiochemical procedures, airborne effluent sampling methodology & results of split samples KUZO, 0 B . TROUP, G L Region P. Office of Director MONTGOMERY, D H Division of Engineering & Operational Programs 94/02/13 11pp 22660 068 24X Fiche 50-395,84/02/15,8403160305
- 8403070125 Ack receipt of 840110 ltr informing NRC of steps taken to correct violations noted in IE lnsp Rept 50-395/83-38 LEWIS.R C Division of Project & Resident Programs 84/02/24 DIXON/D W South Carolina Electric & Gas Co ip 22538 214 24% Fiche 50-395/84/02/24-8403070125
- --8403070129 Responds to NRC 840111 ltr re violations noted in IE Insp Rept 50-395/83-38 Corrective actions testing satisfactorily performed on both diesel generator breakers while escalating in Mode 2 Valves LCV-115 B & D satisfactorily tested DIXON, O W South Carolina Electric & Gas Co 84/01/10 D'REILLY, J P. Region 2. Office of Director 5pp 22538 215 24X Fiche 30-395,84/02/24,8403070125
- --8403070131 Forwards IE Insp Rept 50-395/83-38 on 831212-15 & notice of violation LEWIS.R C Division of Project & Resident Programs 84/01/11 DIXON.D W South Carolina Electric & Gas Co 2pp 22838 220 24X Fichs 50-395.84/02/24.8403070125
- --8403070133 Notice of violation from insp on 831212-15 * Region 2, Office of Director 84/01/11 ip 22538 222 24X Fiche 50-395.84/02/24.8403070125
- --8403070136 IE Insp Rept 50-395/83-38 on 831212-15 Noncompliance noted failure to perform slave relay to actuated device continuity tests & operational modes changed w/diesel generators inoperable BUTCHER.R C . HEHL.C W Region 2. Office of Director CANTRELL.F S Division of Project & Resident Programs 84/01/10 Bpp 22538 223 24X Fiche 50-395.84/02/24.8403070125
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Volve Control Circuits & Annunciation " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York Inc 115pp 22909 237 24X Fiche 50-000.84/02/28,8401190072
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl GRACE.J N Division of GA: Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 327 24X Fiche 50-000:84/03/02.8402090007
- 8402090008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 122pp 2253 098 24X Fiche 50-000,84/03/02,8402090008
- 8402090009 IE Info Notice 84-25. "Reporting of Radiological Releases" Svc list encl
 JORDAN.E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc. 117pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8402090011 IE Info Notice 84-17. "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp" Svc list encl JERDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc. 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8402090024 IE info Notice 84-09.Rev i. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JURDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York. Inc 118pp 22635 049 24X Fiche 50-000.84/03/07,8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR
 Sys " Svc list encl
 JURDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/07 Consolidated Edison Co of New
 York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8402090031 IE Builetin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Syr list encl DEYDUNO, R C Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of Naw York, Inc 134pp 22823 094 24% Fiche 50-000,84/03/12,8402090031

- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 227 24X Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84~20. "Svc Life of Relays in Safety-Related Sys " Svc List enc!

 JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 2293 001 24X Fiche 50-000,84/03/21,8402070044
- R Periodic operating reports & related correspondence
- 8403020039 Monthly operating rept for Jan 1984 W/840213 ltr LDIGNON.G A . DIXON.D W South Carolina Electric & Gas Co 84/01/31 5pp 22442 264 24X Fiche 50-395,84/01/31,8403020039
- 8403300145 Monthly operating rept for Feb 1984 W/840314 ltr LOIGNON.0 A . DIXON.0 W South Carolina Electric & Gas Co 84/02/29 BARRY,L W Office of Resource Management, Director 5pp 22820 072 24X Fiche 50-395.84/02/29.8403300145
- S Reportable occurrences, LERs & related correspondence
- 840321003R Part 21 rept re failure of auxiliary feedwater pump drive turbines. Gimpel NPS-4 TXT valve. to close Encl ltr dtd 840203 sent to listed utils GE notified of affected units in BWR plants
 THERDUX. R Terry Corp 84/02/22 WOODRUFF. R W Director's Office. Office of Inspection and Enforcement 6pp 22706 327 24X Fichs 50-000.84/02/22,8403210032
- B403070337 Special Rept SPR 84-002 on 840131, fire-rated wall in Room 63-t5, control bldg, 463-ft elevation, degraded by hole approx 2-inch in diameter from chair pushed against wall Damaged area not repaired until 840216, due to personnel error DIXON.O W South Carolina Electric & Gas Co 84/02/29 O'REILLY.J P. Region 2, Office of Director 2pp 22546 307 24X Fiche 50-395,84/02/29,8403070337
- 8403060242 LER 84-006-00 on 840131, noted that overcurrent protection devices for plant paging sys not included in Tech Spec 3 B 4 Rev to Tech Spec will be submitted adding acceptable fuses W/840301 ltr KGON A R . DIXON.O W South Carolina Electric & Oas Co 84/03/01 2pp 22516 155 24X Fiche 50-395,84/03/01.8403060242
- 8403060351 LER 84-007-00 on 840227, potential bomb threat received via talcon Cause unknown Search of 412 ft elevation of control bldg conducted w/negative results Plant returned to security condition green W/840302 ltr KODNA R , DIXONO W South Carolina Electric & Gas Co 84/03/02 2pp 22517 082 24X Fiche 50-375,84/03/02,8403060351
- B4030B0153 LER 84-010-00 on 840209, reactor manully tripped at 8% power plant experienced problems w/main turbine speed control Cause unknown Reactor coolant pumps restarted Operating procedure revised W/840305 ltr
 KDDN.A R. DIXON.O W South Carolina Electric & Gas Co 2pp 22559 291 24% Fiche 50-395,84/03/05,8403080153
- 8403090052 LER 84-008-00 on 840207.low-low level in steam generator B tripped reactor Caused by electronic card FCY-488 control circuitry failure partially closing main feedwater regulating valve Post-trip review conducted W/840305 ltr KOON.A R. DIXON.O W South Carolina Electric & Gas Co 84/03/05 2pp 22575 358 24X Fiche 50-375.84/03/05.8403090052
- B403090249 LER 84-009-00 on B4020B.unit tripped on low-low steam generator level in steam generator C Caused by low feedwater temp Plans made to restart reactor W/840305 ltr KOON, A R., DIXON, O W. South Carolina Electric & Cas Co. 84/03/05 2pp. 22572 224 24X Fiche 50-395,84/03/05.8403090249
- B403130260 Special Rept SPR 84-003 on B40125, seismic instrument IVM-1783 removed from svc to verify calibr Caused by damaged integrated circuit chip Mod change, reinstallation & testing in progress
 DIXON.O W South Carolina Electric & Gas Co 84/03/05
 O'REILLY, J P. Region 2, Office of Director Rpp 22614 176 24X Fiche 50-395,84/03/05,8403130260
- 8403130371 LER 84-011-00 on 840210, reactor tripped due to turbine trip on low discharge pressure of shaft-driven oil pump Caused by procedural inadequacy in not verifying motor suction pump operation prior to restart W/840308 ltr KCON.A R. DIXON.D W South Carolina Electric & Gas Co 84/03/08 3pp 22413 150 24X Fiche 50-395,84/03/08,8403130371

- B403190248 Supplemental Part 21 rept re failed engine thrust bearing Plugs properly installed in both units Units free of potential defect MDRIARTY.J M Colt Industries. Inc 84/03/08 KEPPLER.J G Regi
 - MDRIARTY.J M Colt Industries. Inc 84/03/08 KEPPLER.J G Region 3. Office of Director 1p 22675 045 24X Fiche 50-000.84/03/08.8403190248
- 8403150042 LER 84-012-00 on 840214, leak rate test not performed on reactor bldg emergency escape hatch within 72 h following closure Caused by personnel error Special instruction issued W/840312 ltr
 KCON.A R. DIXON.O W South Carolina Electric & Gas Co 84/03/12 2pp. 22643 128 24% Fiche 50-375.84/03/12,8403150042

V Operator Examinations

- 8403290284 Forwards summary of 840202-03 operator & senior operator requalification exams Requalification program meets 10CFR55, App A requirements to maintain continued qualification of licensed personnel VERRELLI.D M Division of Project & Resident Programs 84/03/19 DIXON,O W South Carolina Electric & Gas Co 4pp 22800 060 24% Fiche 50-395,84/03/19,8403290284
- DOCKET 50-394 UNIV OF VIRGINIA CAVALIER REACTOR
- R Periodic operating reports & related correspondence
- 8403010397 Annual operating rept for 1983 FARRAR.J P Virginia, Univ of Charlottesville, VA 84/02/16 Division of Licensing 10pp 22433 093 24X Fiche 50-062,84/02/16, 8403010397
- DOCKET 50-397 WPPSS NUCLEAR PROJECT, UNIT 2
- A Application/construction stage documents & correspondence
- B403010050 Third partial response to FOIA request for six categories of documents re facility Forwards App A documents App A documents also placed in FOR App B documents will be placed in FOR upon request Review continuing FELTON. J M Division of Rules and Records B4/01/17 ANDERSON, S I Garvey, Schubert, Adams & Barer App 22446 293 24X Fiche 50-000,84/01/17,8403010050
- --B308100483 Discusses status of OL applications Review of encl WPPSS B30712 ltr requested in order to determine present status of Unit 3 for billing purposes W/A encl MILLER.W O License Fee Management Branch B3/08/05 FONNER.R L Regulations Division 2pp 22446 326 24X Fiche 50-000, 84/01/17.8403010050
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B documents entirely withheld (ref FOIA Exemption 5) Review of add1 documents subj to request continuing FELTON. J H Division of Rules and Records 84/02/13 ANDERSON. 8 I Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000,84/02/13,8403080179
- --8009090737 Forwards airworthiness alert re corrosive & abrasive characteristics of volcanic ash which has fallen in Pacific Northwest Questions re ash amount chemistry & size distribution will be forwarded to licensees W/o ancl JACKBON.R E Geosciences Branch 80/06/12 VOLLMER.R H Division of Engineering 2pp 22583 258 24X Fiche: 80-000, 84/02/13,8403080179
- --B101060767 Notifies of findings of possible capable fault near facility JACKBON.R E Geosciences Branch 80/10/27 ROUSE.L C Advanced Fusl & Spent Fuel Licensing Branch 1p 22583 267 24X Fiche 50-000.84/02/13.8403080179
- --8104300020 Responds to 810414 memo re util request for clarification in use of ABME code cases Util use of code cases w/o prior NRC approval is inadvisable due to potential hardship for user BUSNAK, R J Hechanical Engineering Branch 81/04/21 YOUNOBLOOD, B J Licensing Branch 1 ip 22583 280 24X Fiche 50-000, 84/02/13, 8403080179
- --Biii200219 Informs of receipt of telcon from Yakamar Indian Nation requesting that tribe be given full rights in facilities proceedings
 TEDEBCO.R L. Assistant Director for Licensing Bi/10/21
 KETCHEN.E Hearings Division 1p 22583 310 24X
 Fiche 50-000,84/02/13,8403080179

- --8303100476 Forwards Util 830223 submittal in response to telcon during which remaining Phase I open items of "Control of Heavy Loads Case Reviews," were discussed W/o encl CLEMENSON.F Auxiliary Systems Branch NRC-20-18-388 83/02/28 STICKLEY.TH EG&O. Inc ip 22583 360 24X Fiche 50-000,84/02/13,8403080179
- --B304060577 Requests search for documents re govt litigation w/util on five specific issues BLAGOIE,E L Office of the General Counsel 83/03/23 DIRCKS,W J Office of the Executive Director for Operations ip 22583 361 24X Fiche 50-000.84/02/13.8403080179
- --B304070113 Recommends that radiation exposure records be retained for 1 yr prior to disposal Ref Murphy to Varga 801222 CONOBL.F J Radiological Assessment Branch B3/04/01 SCHMENCER.A Licensing Branch 2 1p 22583 327 24X Fiche 50-000,84/02/13,8403080179
- 8403050288 Fifth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App A & 8 documents also available in PDR Documents listed on App C & D located in Central Files & not available publicly FELTON.J M Division of Rules and Records 84/02/17 ANDERSON.S I Garvey, Schubert, Adams & Barer 9pp 22501 289 24X Fichs 50-397.84/02/17.8403050288
- --7908010232 Responds to 790405 Region 3 comments re Revision 4 to NPPSS-0A-004, "Operational GA Program Description "
 Expresses intent to request util to delete Section 3 3 6 entirely
 HAASS.W P Quality Assurance Branth 79/05/01 BRYAN, S E
 Division of Reactor Operations Inspections 1p 22501 305 24X
 Fiche 50-377,84/02/17.8403050288
- --Bli0190051 Responds to Bl0923 FOIA Bl-378 request for QA documents for WPPSB All documents re evaluation of licensee QA programs are in FDR HAASS, W P Quality Assurance Branch Bl/10/05 WILSDN.V H Management Analysis Branch 2pp 22501 310 24X Fiche 50-397, 84/02/17,8403050288
- --8201300236 Forwards data for fee assessment re GA Branch review of HPP68-QA-004, "Operational GA Program Description"
 HAABS, W P quality Assurance Branch 82/01/14 DERKOW, H N Management Analysis Branch 2pp 22501 314 24X
 Fiche 50-397,84/02/17,8403050288
- C Utility Environmental Report (ER), amends & correspondence
- 84030B0179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of addl documents subj to request continuing FELTON.J M Division of Rules and Records 84/02/13 ANDERSON, 8 1 Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000.84/02/13,84030B0179
- --B203100370 Recommends environ rept be accepted Addl questions re external appearance, plant layout & socioeconomics of single unit operation will be submitted REGAN.W H Siting Analysis Branch 82/02/25 ADENSAM.E O Licensing Branch 4 ip 22583 328 24X Fiche 50-000, 84/02/13, 8403080179
- D NAC Draft/Final Environmental Statements, supply & correspondence
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of addl documents subj to request continuing FELTON. J M Division of Rules and Records 84/02/13 ANDERSON, 6 I Garvey, Schubert. Adams & Barer 7pp 22583 226 24X Fiche 50-000,84/02/13,8403080179
- --8003250477 Forwards hydrologic engineering questions re proposed waste treatment sys Response will supply necessary info re design basis for seepage & flooding. Also forwards generic questions re floodplains Info will assist NRC environ review SELLS, D. E. Environmental Projects Branch 2 80/03/07 RENBERGER, D. L. Washington Public Power Supply System 5pp 22583 253 24X Fiche 50-000.84/02/13,8403080179
- --8003270142 Discusses suspension of facility prooperational aquatic monitoring program Suspension approved Operational monitoring program results should not be affected by suspension

 8AMMORTHAR 8 Environmental Specialists Branch 80/02/29

 8ELLS.D E Environmental Projects Branch 2 2pp 22583 237 24X
 Fiche 50-000,84/02/13.8403080179

- 8403160228 Forwards State of HA Dept of Fisheries response to EIS Response received after state response forwarded to NRC Enci should be attached to other state agency ltrs SDRL[E: 0 Hashington, State of 84/03/16 KNIGHTON NRC No Detailed Affiliation Given 2pp 22660 121 24x Fiche 30-397.84/03/16.8403160228
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8403080179 Fourth partial response to FDIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FQIA Exemption 5) Review of add documents subj to request continuing FELTON.J M Division of Rules and Records 84/02/13 ANDERSON.5 I Garvey. Schobert. Adams & Barer 7pp 22593 226 24X Fiche 50-000.84/02/13.8403080179
- --B005130793 Provides status of SER inputs & acceptance reviews for DL & CP applications Schedule should be met BURKE.W C Effluent Treatment Systems Branch B0/02/06 RREGER,W E Assistant Director for Site Analysis 1p 22583 235 24% Fiche 50-000.84/02/13.8403080179
- --BIO3040052 Forwards short & long-term OL & CP review schedules, in response to 801216 meeting w/USOS List of OL plant reviews for which NRC tentatively plans to seek USOS assistance is provided JACKSON.R E Geosciences Branch NRC-03-80-113 BI/01/21 DEVINE.J F Interior. Dept of Geological Survey 5pp 22583 272 24x Fiche 50-000.84/02/13.8403080179
- 8403090121 Advises that 24 h humidity test of three safety-related components per SSER 4 (NUREO-0892) satisfactorily completed SDRENSEN.O C Hashington Public Power Supply System 84/03/01 SCHHENGER.A Licensing Branch 2 ip 22576 066 24X Fiche 50-397.84/03/01.8403090121
- B403130227 Forwards into re shift experience,per DF Schnpl1 840301 itr & SER (MVREG-0892) Licensed classroom training & exam conducted SDRENSEN.0 C Mashington Public Power Supply System 84/03/09 DENION.H R Office of Nuclear Reactor Regulation. Director 7p. 22608 231 24x Fitche 50-397,04/03/09.8403130227
- 8403260006 Informs that functional training for personnel necessary to staff requirements per Table B-I of JARREO-0654 & staff key emergency program positions not included in Table B-I complete.per License Condition 24 & SSER 4
 SURENSEN.6 C Washington Fublic Power Supply System 84/03/19
 SCHMENGER.A Licensing Branch 2 ip 22747 357 24X
 Fiche 30-397.84/03/19.8403260006
- 8403270220 Advises that equipment qualification program & RCIC sys reviewed.per NUREQ-0892. SER Outstanding Issue 1 7(7).mods to automatic depressurization sys RCIC valves required for containment isolation remain in qualification program SGRENERN.G C Washington Public Power Supply System 84/03/22 SGMENER.A Licensing Branch 2 ip 22770 269 24% Fiche 50-997.84/03/22.8403270220
- F Security, medical, emergency & fire protection plans
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of additionwants sub; to request continuing FELTON-J M Division of Rules and Records 84/02/13 ANDERSON, S I Garvey, Schubert. Adams & Barer 7pp 22583 226 24% Fiche 50-000.84/02/13.8403080179
- --8231190297 Forwards Central Files version of "Description of Early Warning Sys for MPPSS Nuclear Plants 1,2 & 4," in response to NRC 810720 ltr re prompt notification in event of emergency Sys will be in place prior to OL issuance BOUCHEY. O D Washington Public Power Supply System 82/01/11 TEDESCO.R L Assistant Director for Licensing in 22583 321, 24X Fiche 30-000,84/02/13,8403080179
- --B208120240 Forwards Central Files version of revised page to Revision 2 of emergency plan adding local fire depts within 20 miles of facility to backup fire protection svcs BOUCHEY. O D Mashington Public Power Supply System B2/08/05 SCHMENCER. A Licensing Branch 2 2pp 22383 348 24X Fiche 30-000.84/02/13,8403080179
- --8208120248 Central Files version of revised page to Revision 2 of emergency plan re provision of backup fire protection svcs s Washington Public Power Supply System 82/08/05 ip 22583 350 24X Fiche 50-000.84/02/13.8403080179

- 8403130318 Application for amend to License NPP-21, consisting of listed administrative & technical Tech Spec changes No significant hazards or unreviewed safety questions will result from thanges SCREMSEN.g C Washington Public Power Supply System 84/03/09 SCHWENCER, A Licensing Branch 2 Spp 22407 248 24X Fiche 30-397.84/03/09.8403130318
- --B403130330 Proposed Tech Spec changes re fire detection instrumentation s Washington Public Power Supply System 84/03/09 20pp 2207 253 24X Fiche 50-397,84/03/09,8403130318
- B403260006 Informs that functional training for personnel necessary to staff requirements per Table B-1 of NOREO-0554 & staff key emergency program positions not included in Table B-1 complete.per License Condition 24 & USER 4
 SDRENSEN.0 C Washington Public Power Supply System. B4/03/19 BCHMENCER.A Licensing Branch 2 ip 22747 357 24X
 Fiche 50-397.84/03/19.8403260006
- 8403270141 Discusses updated status of Licensing Condition (16) re amergency response capability Transient Data Acquisition Sys & Graphics Display Sys computers now functional. SCRENSEN,O C Washington Public Power Supply System 84/03/22, SCHMENCER,A Licensing Branch 2 2pp. 22769:143. 24X Fiche 50-397.84/03/22,8403270141.

Q Adjudicatory correspondence

- B403010050 Third partial response to FOIA request for six categories of documents re facility Forwards App A documents App A documents also placed in PDR App B documents will be placed in PDR upon request Review continuing FELTON.J M Division of Rules and Records 84/01/17 ANDERBON, S I Garvey, Schubert, Adams & Barer 4pp 22446.273 24X Fiche 50-000.84/01/17,8403010050
- --8304060552 Requests search for relevant documents re govt litigation w/util Response due by 830408 GRIMBLEY, D H NRC No Detailed Affiliation Given 83/03/27 FITTI, C Atomic Safety and Licensing Board Panel. ip 22446 314 24X Fiche 50-000,84/01/17,8403010050
- J Insurance & Indemnity information
- 8403040377 Forwards Endorsement 8 to MAELU Policy MF-110 & Endorsements 13 & 14 to NELIA Policy NF-270 ASHBURN.D J Harsh & McLennan, Inc 84/02/28 BALTZMAN, J Assistant Director for State & Licensee Relations 4pp. 22511:323 24X Fichs 50-397,84/02/28,8403060377
- 8403270207 Submits annual rept of insurance coverages for facility SCRENSEN.g C. Washington Public Power Supply System 84/03/R3. SCHMENCER.A Licensing Branch 2. ip 22772 170 24X Fiche 50-377.84/03/23.8403270207.
- P Operating license stage documents & correspondence
- 8403050292 Notification of 840301 meeting w/util in Richland, WA to discuss licensee readiness for full-power operation. Agenda encl
 AULIUCK, R Licensing Branch 2 84/02/23 SCHWENCER, A Licensing Branch 2 4pp 22501 207 24X Fichs: 50-397, 84/02/23, 8403050292.
- B403020330 Forwards operating experience survey in response to Generic Ltr 84-02. "Notice of Meeting re Facility Staffing "
 SURENBEN, O C Washington Public Power Supply System 84/02/24.
 SCHMENCER, A Licensing Branch 2 3pp 22439.208. 24X
 Fiche 50-397,84/02/24,8403020330
- 8403090236 Application for amend to License NPF-21, revising License Condition 13 repost-accident sampling. Class II amend fee enci SORENSEN. G C Washington Public Power Supply System 84/03/01. SCHWENCER. A Licensing Branch 2 5pp. 22572-293 24X Fichs. 50-397, 84/03/01, 8403090236
- 8403130480 Advises of effort to determine effect of dead leg piping attending into secondary containment; per NUREQ-0737, Item II B 2 & util 830916 Itr re environ quelification of safeky-related equipment SOREMSEN, 0 C. Washington Public Power Supply System, 84/03/05. SCHEMSEN, 6 Licensing Branch 2 2pp. 22619, 214, 24X Fiche 50-397, 84/03/05, 8403130480

- 8403280283 Requests certification that Tech Specs accurately reflect plant.FSAR.SER analysis & other documentation within 10 days Proposed changes should be identified EISENHUT.D G Division of Licensing 84/03/08 MAZUR.D W Washington Public Power Supply System 2pp 22808 061 24X Fiche 50-397.84/03/08.8403280283
- 8403130318 Application for amend to License NPF-21, consisting of listed administrative & technical Tech Spec changes No significant hazards or unreviewed safety questions will result from changes SORENSEN. O C Washington Public Power Supply System 84/03/09 BCHMENCER. A Licensing Branch 2 Spp 22607 248 24X Fiche 50-397,84/03/09,8403130318
- --8403130330 Proposed Tech Spec changes re fire detection instrumentation * Washington Public Power Supply System 84/03/09 20p 22607 253 24X Fiche 50-397,84/03/09.8403130318
- 8403200236 Application to amend License NPF-21.revising Tech Specs to correct time during which battery capable of supplying & maintaining actual emergency loads in operable status from B h to 2 h SOREMBEN.O C Washington Public Power Supply System 84/03/13 SCHWENGER.A Licensing Branch 2 Spp 22690 201 24X Fiche.50-397,84/03/13.8403200236
- --8403200241 Proposed Tech Specs changing time during which battery capable of supplying & maintaining actual emergency loads in operable status from 8 h to 2 h # Washington Public Power Supply System 84/03/13 3pp. 22690
- 8403200261 Advises that control equipment for air operators CSP-AD-5. CSP-AD-6 & CSP-AD-9, listed on Table B of 10CFR50, 49 justification for interim operation revised to not qualified Status to be upgraded by 850331 commitment date SORENSEN.9 C Washington Public Power Supply System 84/03/14 BCHURCER, A Licensing Branch 2 2pp 22670 179 24X Fiche, 50-397, 84/03/14, 8403200261
- 8403220061 Discusses completion of const mods re pipe supports Plant mods physically completed & final as-built configuration satisfies technical requirements SORENSEN, O C Washington Public Power Supply System 84/03/16 SCHMENCER, A Licensing Branch 2 2pp 22718 101 24X Fiche, 80-397, 84/03/16, 8403220061
- 8403260165 Advises that human engineering deficiencies identified in Licensing Condition 16.Attachment 2.Item 2 corrected Deficiency D-1 30.identified in B31004 audit rept.also complete
 80RENSEN, 0 C Washington Public Power Supply System 84/03/17 8CHWENCER, A Licensing Branch 2 1p 22750 354 24X Fiche: 50-397.84/03/19.8403260165.
- 8403260274 Forwards outline of Tech Spec preparation & review to insure accurate reflection of FSAR & BER analyses
 MAZUR,D W Washington Public Power Supply System 84/03/17
 SCHIERGER,A Licensing Branch 2 5pp 22753 150 24X
 Fiche,50-397,84/03/19,8403260274
- B403260292 Retracts B40301 request for amend to License NPF-21, deferring demonstration of dissolved gas analysis capability for post-accident sample sys Mod can be completed w/o impact on power ascension program BORENBEN.9 C Washington Public Power Supply Bystem 84/03/19 BCHMENGER.A Licensing Branch 2 ip 22751.081 24X Fiche: 50-397, 84/03/19, 8403260292
- G Inspection reports, IE Bulletins & correspondence
- 8403080266 Forwards IE Insp Rept 50-397/83-60 on 831205-31 & notice of violation W/o notice of violation BISHOP.T W Division of Resident.Reactor Project & Engineering Programs. 84/02/22 SORENSEN, 6 C Washington Public Power Supply Bystom 2pp 22557 121 24X Fiche 50-397.84/02/22,8403080266
- --8403080270 IE Insp Rept 50-397/83-60 on 831205-31. Noncompliance identified failure to complete maint corrective actions, per leakage surveillance program TOTH.A.D. HAITE.R.S. D. DDDS.R.T. Region 5. Dffice of Director 84/02/08 32pp. 22557.123. 24X Ficha 50-397.84/02/22.8403080266
- 840119007Z IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list and! JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York: Inc 115pp 22909 239 24X Fiche 50-000.84/02/28,8401190072

- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE.J N Division of GA. Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22592 329 24X Fiche 50-000.84/03/02.8402090007
- B40209000B IE Info Notice B4~16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post B30103) B4/03/02 Consolidated Edison Co of New York, Inc. 122pp 22553 09B 24X Fiche 50~000.84/03/02,8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases" Svc list enc! JURDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8402090011 IE Info Notice 84-17. "Problems H/Liquid Nitrogen Cooling Camponents 8-low Nil Ductility Temp " Svc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/05 Consolidated Edison Co of New York: Inc 117pp 22553 336 24X Fiche 50-000:84/03/05,8402090011
- B402070024 IE Info Notice B4-09.Rev 1, "Lessons Learned From Insps of Fire Protection Bafe Shutdown Sys " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000.84/03/07,8402070024
- 8402070028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Sys " Svc list enc! JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000, 84/03/07, 8402070028
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " 8vc list encl
 DEYCKUNG.R C Director's Office Office of Inspection and
 Enforcement B4/03/12 Consolidated Edison Co of New York
- 8403270118 Requests approval to use portions of later addenda of ASME Section XI requirements resulction & exam of Class 2 piping (Category CF only) for inservice insp program Proposed code case encl SURENBEN.9 C Washington Public Power Supply System 84/03/20 SCHMENGER.A Licensing Branch 2 7pp 22774 055 24X Fiche 50-397.84/03/20.8403270118
- 8402070043 IE Info Notice 84-19. "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 227 24X Fiche 50-000,84/03/21,8402070043
- 8402070044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044
- R Periodic operating reports & related correspondence
- 8403020077 Monthly operating rept for Jan 1984 W/840207 ltr COWAN, K D , MARTIN, J D Washington Public Power Supply System 84/01/31 4pp 22442 331 24X Fiche 50-397,84/01/31,8403020097
- 8403020443 Forwards monthly status rept of offsite emergency preparedness for OL reviews for Jan 1984 Changes in FEMA finding dates not caused by delay due to offsite emergency planning issues
 DIRCKS,W J. Office of the Executive Director for Operations
 84/02/21 PALLADINO Commissioners 9pp 22492 083, 24X
 Fiche 50-000,84/02/21,8403020443
- 8403300056 Monthly operating rept for Feb 1984 W/840308 ltr COWAN,K D : MARTIN.J D Washington Public Power Supply System 84/02/29, 4pp 22821,266 24X Fiche 50-397.84/02/29.8403300056
- B Reportable occurrences. LERs & related correspondence
- 8403260233 Forwards summary list of deficiencies identified per 100FR30 55(e).Part 21 & potential generic ltr repts for comments STAROSTECKI.R Division of Project & Resident Programs 84/02/28 Region 1. Office of Director 7pp 22756 065 24X Fiche 50-000.84/02/28.8403260233

)3070187 LER 84-007-00 on 840207 k 09. standby diesel generators 1 k 2 surveillances performed w/o prelobe/warmup Caused by recent changes to Tech Specs not requiring warmup Tech Specs changed b/or codified W/840229 ltr (ASSAKATIS), L D . MARTIN, J D . Mashington Public Power Supply System 34/02/27 3pp 22547 291 24X Fiche 50-397, 84/02/27, 8403070187

J3130337 LER 84-010-00 on 840213, four excess flow check valves failed surveillance testing Caused by installation error Valves lesigned for water see but installed in gas see line Valves removed & replaced W/840307 ltr
(ABSAKATIS.L D . MARTIN.J D Washington Public Power Supply System 4/03/07 3pp 22614 111 24X Fichs 50-397,84/03/07,8403130337

03200105 LER 84-013-00 on 840213 during shutdown conditions, both 10st-LOCA hydrogen recombiner (CAC-HR-1A & 1B) motors tripped on electrical overload Caused by differences between nameplate date & design Fuses resized H/840312 ltr (ABSAKATIS, L B. MARTIN, J P. Hashington Public Power Supply System 34/03/12 3p 22685 360 24X Fiche, 50-397, 84/03/12, 8403200105

03200239 LER 84-014-00 on 840217 reactor protection sys (RPS) trip occurred Caused by water rejection flow from reactor ressure vessel isolated w/o reducing water injected Power to RPS buses A or B will not be transferred W/840314 ltr (ASSAKATIS.L D. MARTIN.J D. Washington Public Power Supply System 84/03/14 3pp 22690 i54 24% Fiche 50-397.84/03/14,8403200237

03260025 LER 84-012-00 on 840221.24 & 0302.diesel generator fuel oil tank chemistry results not received in required time, violating Tech Spec 4 B l 1 2 d.3 Caused by misunderstanding letween util 2 lab W/840319 ltr (ASBANATIGL D. MARTIN.) D Washington Public Power Supply System 34/03/19 3pp 22751 026 24X Fiche 30-397.84/03/19.8403260025

03280003 LER 84-011-00 on 840302 during intermediate range monitor surveillance test reactor protection sys (RPS) actuation occurred when only 1/2 scram anticipated Caused by loose connection in RPS trip sys A scram circuitry W/840321 ltr (ABBAKATIS, L D. MARTIN, J D. Washington Public Power Supply System 34/03/21 4pp 22777 155 24X Fiche 50-397,84/03/21,8403280003

33280007 LER 84-015-00 on 840307.dc input circuit breaker & fuse tripped due to loss of power Caused by inverter static witch transferring to inverter source Fuse replaced & inverter returned to svc H/840321 ltr. (ASSAKATISL D. HARTIN.J D. Hashington Public Power Supply System 34/03/21 Spp. 22777 071 24X Fiche 50-397.84/03/21.8403280007

Congressional/Executive Correspondence

J30B0179 Fourth partial response to FDIA request for six categories of documents re facilities Forwards App A documents App B locument entirely withheld (ref FOIA Exemption 5) Review of iddl documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, S 1 Garvey, Schubert, Adams & Barer 7pp 22583 226, 24X Fichs 50-000-84/02/13.8403080179

8009110203 Responds to B00702 ltr re E Borhek concern about ultimate responsibility for civil penalities proposed against util Civil penalities are imposed as enforcement action State agencies should be contacted re responsibility for payment DIRCKS,W J Office of the Executive Director for Operations 80/08/24 JACKSON.H M Senate 4pp 22593 260 24X Fiche 50-000.84/02/13.8403080179

BOIR160351 Forwards 800625 ltr from constituent E Borhek for response Requests that duplicate rept be forwarded to 802 United Btates Counthouse, Seathle, NA 98104 JACKSON.H M Senate. Energy & Natural Resources 80/07/21 KAMMERER, C C Office of Congressional Affairs 20p 22583 264 24X Fichs 50-000.84/02/13/8403080179.

Operator Examinations

>3130227 Forwards info re shift experience.ger DF Schnell 840301 ltr & SER (NUREQ-0892).Licensed classroom training & exam conducted SORENSEN.O C Washington Public Power Supply System 84/03/07 DENTON.H R Office of Nuclear Reactor Regulation, Director 7p 22608 231 24% Fiche 50-397.84/03/09.8403130227

- DOCKET 50-400 SHEARON HARRIS NUCLEAR POWER PLANT. UNIT 1

 A Application/construction stage documents & correspondence
- 8402230207 Further response to FDIA request for documents re const flaws at facility Forwards documents listed in App A Documents also being placed in PDR & LPDR Review continuing FELTON, J M Division of Rules and Records 83/12/02 VADEN, T News & Observer/Raleigh Times, Raleigh, NC 3pp 22378 299 24X Fiche 50-400,63/12/02,8402230207
- --8402230226 Forwards Dfc of Inspector & Auditor "Inquiry into Alleged Omission of Line Inspector Views from CP Hearing " No further distribution should be made outside of ofc Rept under Commission review GOSSICK.L V Office of the Executive Director for Operations 78/11/15 DENION Office of Nuclear Reactor Regulation, Director SHAPAR Office of the Executive Legal Director DAVIS Office of Inspection & Enforcement, Office of the Director. 1p 22378 305 24x Fiche 50-400, 83/12/02,8402230207
- --8402230237 Forwards Apps A.B.C & D to be included w/questions for Panel III re facility testimony Related info encl MURPHY.C.E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/11/16 REIS.E J Office of the Executive Legal Director Sipp 22378 308 24X Fiche 50-400,83/12/02,8402230207
- --B402230246 Ack 820510 conversation re allegations by facility employee D Jarvis.per Regional Ofc Instruction 2R51.Rev 2.Paragraph 2 C (3) Case file ancl MAXHELL.0 Region 2. Office of Director 82/05/10 VORSE.J NRC -- No Detailed Affiliation Given 2pp 22379 032 24X Fiche 50-400.B3/12/02.B402230207
- --8402230248 Requests that Region II civil inspire sonnel investigate allegations by unidentified individual re-coatings during next routine inspirat site Case chronology encl MAXWELL.0 F Region 2, Office of Director 82/07/07 VORSE, J NRC No Detailed Affiliation Given 2pp 22379.034 24X Fiche 50-400,83/12/02,8402230207
- --B40223025; Hatl maint requirements for Procedure AP-XIII-07,
 "In-Storage Insp & Maint " Equipment purchase order form
 encl
 + Carolina Power & Light Co B3/12/02 9pp 22379 040 24X
 Fiche 50-400,83/12/02,8402230207
- 8403160330 Informs that design & const GA program transmitted by 830509 ltr acceptable LENIS.R C Division of Project & Resident Programs 84/02/24 UTLEY.E E Carolina Power & Light Co 1p 22660 102 24X Fiche 50-400.84/02/24.8403160330
- 8402090017 Board Notification 84-038 forwards RJ Mattson 840123 memo to DG Eisenhut providing status update of NRC actions re-Heatinghouse ECCS actuation logic EISENHUT.D 0 Division of Licensing 84/02/27 PALLADIND Commissioners 7pp 22546 007 24x Fiche 50-000,84/02/27,8402090017
- 8403280070 Notification of 840321 meeting w/util in Bethesda.MD to discuss util qualification program, including both environ & seismic considerations
 BUCKLEY.B C Licensing Branch 3 84/03/01 KNIGHTON, 9 W Licensing Branch 3 4pp 22812.314 24X Fiche 50-400,84/03/01,8403280070
- 8403280122 Summary of 840224 meeting w/Hestinghouse Owners Oroup in Bethesda, MD re proposed Mestinghouse steam generator tube rupture generic program Attendee list & agenda encl MERSEB, V Licensing Branch 3 84/03/07 Licensing Branch 3 35pp. 22811 131 24X Fiche 50-000,84/03/07,8403280122
- 8403210131 Application to amend CPPR-159 to reflect latest date for const completion as 860301, per 10CFR50 55(h) Extension results from delays in projected inservice date & corresponding fuel load date, per util 821014 ltr MCDUFFIE.M A Carolina Power & Light Co 84/03/16 DENTON, H R Office of Nuclear Reactor Regulation, Director. 2pp. 22707 244 24X Fiche 50-400,84/03/16,8403210131
- E NRC Safety Evaluation Report (SER). suppls & correspondence
- 8403030061 FDIA request for extant drafts of sections or portions of SER for plant & documents showing dissenting opinions of staff revisuers

 EDDLEMAN, H Eddleman, H 84/01/12 FELTON, J Division of Rules and Records 1p 22476 346 24X Ficher 50-400,84/01/12,8403050061.

- B403050064 Partial response to FOIA request for extant drafts of sections of SER for plant & documents showing dissenting opinions of staff reviewers Forwards App A documents Documents also in PDR Search for addl documents in progress FELTON.J M Division of Rules and Records B4/02/07 EDDLEMAN.W Eddleman. N 4pp 22496 347 24% Fiche 50-400.84/02/07.8403050064
- ---8205120076 Forwards request for add1 info re organic matls & spent fuel pool cleanup sys FSAR sections BENAROYA,V Chemical Engineering Branch 82/04/27 MIRAGLIA,F Licensing Branch 3 4pp 22496 351 24X Fiche 50-400, 84/02/07, 8403050064
- --8203270420 Forwards request for add1 info re fire protection program needed to complete review Info needed by 821102
 BENARDYA, V Chemical Engineering Branch 82/03/17 MIRAGLIA, F
 Licensing Branch 3 7pp 22497 015 24X Fiche 50-400, 84/02/07, 8403050064
- --8207140072 Submits branch input for draft SER Input assumes that plant meets design objective of App I

 9AMMILL.W P Mateorology & Effluent Treatment Branch 82/06/25

 MIRAQLIA.F J Licensing Branch 3 57pp 22501 007 24X

 Fichs 50-400.84/02/07.8403050064.
- --8211090008 Forwards draft SER input re SRP Sections 2 5 1 on basic geology & ssiemic info, 2 5 2 on seismology & 2 5 2 3 on SBE. No capable faults exist at or around site SSE & OBE adequate KNIGHT.J P Assistant Director for Comp & Structures Engineering (Pre B30201) B2/10/20 NGVAK.T M Assistant Director for Operating Reactors 21pp 22476 355 24X Fiche 50-400.84/02/07.
- --8211110461 Advises that applicant has not responded to request for info re BER items concerning oil collection sys for reactor coolant pump, alternate shutdown tapability, fire protection for safe shutdown & NOREO-0800 BENARDYA, V. Chemical Engineering Branch 82/10/28 KNIOHTON, 9 Licensing Branch 3 ip 22497 088 24X Fiche 50-400, 84/02/07, 8403050064.
- ---8211160112 Forwards draft SER input re FSAR Sections 2 3 4 2 5 6
 Request for addl info also encl Site visit necessary before
 end of yr to observe as-built conditions & implementation of
 dam safety monitoring plans
 LEAR.O. E Hydrologic & Geotechnical Engineering Branch B2/11/09
 KERRIOAN.J D Licensing Branch 3 40pp 22497 260 24X
 Fiche 50-400.84/02/07.8403050064
- --8211170249 Forwards draft SER input based on Auxiliary Sys Branch review of FSAR Unresolved items listed RUBENBTEINLL S Assistant Director for Core & Plant Systems 82/11/04 NDVAK,T M. Assistant Director for Licensing 165pp 22497 089 24X Fiche 50-400.84/02/07.8403050064
- --8211300017 Forwards Chemical Engineering Branch draft SER input re listed sections of FBAR through Amend 2 & 820802 htr.based on SRP (NURG-O800) & NURG-0737. Item II B 3 Addl info needed to complete review of post-accident sampling sys. JOHNSTON W V. Assistant Director for Matis & Qual Engineering (Pre 830201) 82/11/17 NOVAK.T Assistant Director for Licensing 21pp 22497 300 24X Fiche 30-400,84/02/07. 8403050064.
- --8212160163 Forwards Structural Engineering Branch summary of FSAR review & draft BER input.
 KNIOHT.J P. Assistant Director for Comp. & Structures Engineering (Pre 830201) 82/12/06 NOVAK.T M. Assistant Director for Licensing 16pp. 22497 346 24X Fiche 50-400.84/02/07.
 8403030064
- ~~8212160220 Forwards revised Hydrologic Engineering Section SER input Revised input superscales previous submittal transmitted by 821014 mamo.

 LEAR. 0.E. Hydrologic & Geotschnical Engineering Branch 82/12/03 KNIOHTON. 0, Licensing Branch 3 25pp 22497:321 24X Fichs. 30-400, 84/02/07, 8403050064.
- ~ 8212300403 Forwards draft revised SER input to BRP Sections 2 5 1, 2 5.2 & 2.5 3 re geology & seismology Revision includes applicant commitment to install & operate free-field accelerometers

 KNIGHT.J P Assistant Director for Comp & Structures Engineering (Pre 830201), 82/12/21 LAINAS.G C Assistant Director for Licensing 24pp 22497 362 24X Fiche 50-400,84/02/07, 8403050064,

- --8301060211 Forwards draft SER input including one open item re
 possible shipments of toxic metls past plant site
 MULLER, DR Assistant Director for Environmental Technology (Pre
 830201) 82/12/22 NOVAK, TM Assistant Director for Licensing
 9pp 22498 024 24X Fithe 50-400, 84/02/07, 8403050064
- --8301140474 Forwards Equipment Qualification Branch input for SER Suppl 5 re environ qualification of mechanical & electrical equipment JDHNSTON:W V Assistant Director for Matls & Qual Engineering (Pre 830201) 83/01/10 NDVAK:T M Assistant Director for Licensing 3pp 22498 033 24X Fiche 50-400.84/02/07.84030500044
- --8301240034 Forwards Meteorology & Effluent Treatment Branch input to draft SER Assumption that draft meets 10CFR30.App I objectives will be verified when Fluidize bed dryer effluents calculated NUREO-0737.Item III D i i incomplete HDUSTON.R W Assistant Director for Radiation Protection 83/01/06 NOVAK.T M Assistant Director for Licensing 58pp 22500 310 24X Fiche 50-400.84/02/07.8403050064
- --8309060390 Forwards Equipment Qualification Branch SER input for environ qualification of equipment important to safety KNIGHT.JP Assistant Director for Comp & Structures Engineering (Flost 830201). B3/08/26 NGVAK.T M Assistant Director for Licensing 5pp 22498 036 24X Fiche 50-400.84/02/07.8403050064
- --B309200478 Forwards Geotschnical Engineering Section input to SER Input based on FBAR through Amend 9 Stability of 400-ft long retaining wall still open issue LEAR.0 Structural & Geotschnical Engineering Branch 83/09/02 KNIGHTON.G Licensing Branch 3 76pp. 22498 IBB 24X Fichs 50-400,84/02/07,8403050064
- --8309210098 Forwards Power Sys Branch SER for Chapters 8-10 of FSAR Issues requiring resolution include containment electrical penetrations.use of load sequencer w/offsite power & frequency of testing of turbine valves RUBENBTEIN.L 8 Assistant Director for Core & Plant Systems 83/08/31 NOVAN.T M Assistant Director for Licensing 80pp 22498 041 24X Fiche 50-400,84/02/07,8403050064
- --8309210116 Forwards SER input for FSAR Sections 4 2.4 3.4 4.15 4 1. 15 4 2.15 4 3.15 4 7 & 15 4 8 Confirmatory & open issues identified listed RUBENSTEIN.L 8 Assistant Director for Core & Plant Systems 83/09/01 NDVAK.T N Assistant Director for Licensing 69pp 22498 119 24X Fichs 50-400,84/02/07.8403050064
- --8309220302 Forwards hydrologic engineering input to SER One open item exists re potential for intense local precipitation to flood safety-related structures Tech Spec defining anti-sediment deposit procedure required JOHNSTON, IV Assistant Director for Matls, Chem & Environ Technology (Post 830201) 83/09/14 NOVAK, TH Assistant Director for Licensing 24pp 22499 188 24X Fiche 30-400, 84/02/07,8403050064
- --8309260018 Forwards SER supporting geology & seismology at facility KNIGHT, J P Assistant Director for Cump & Structures Engineering (Post 830201) 83/09/08 NOVAK, T M Assistant Director for Licensing 44pp 22498 264 24% Fiche 50-400,84/02/07,8403050064
- --BJ09260421 Forwards structural engineering SER sections based on review of FSAR through Amend 9 Three open & one confirmatory items remain Resolution of open/confirmatory items will be addressed in subsequent SSER KNIGHT. J P Assistant Director for Comp & Structures Engineering (Post BJ0201) BJ/09/15 NDVAK.T M Assistant Director for Licensing 16pp 22499 212 24% Fiche 50-400,84/02/07, B403030064
- --8309260482 Forwards Auxiliary Sys Branch SER input based on review of all amends to FSAR up to Amend 9 & applicants 830418.0603, 30.0705.15 & 0812 responses Summary of unresolved issues to be used as basis for meeting Wapplicant also enci RUBERNSTEIN, L S Assistant Director for Core & Plant Systems 83/09/14 NOVAK, T M Assistant Director for Licensing, 251pp 22498 308 24X Fiche 50-400,84/02/07.8403050064
- --8309290412 Forwards Effluent Treatment Sys Section input to SER reflecting changes in status of open items based on 830924 meeting MULLER, D.R. Assistant Director for Radiation Protection 83/09/14 NDVAK, T.M. Assistant Director for Operating Reactors 60pp 22500 190 24X Fichs 50-400,84/02/07,8403050064

- --8309290474 Forwards SER on plant personnel training Util training programs for licensed reactor operators acceptable Util inadequately addressed training of shift technical advisor (STA) when STA absent from STA duties RUSSELL, W Division of Human Factors Safety 83/09/21 NOVAK, TASSISTANT DIRECTOR FOR Licensing 21pp 22499 228 24X Fiche 50-400,84/02/07,8403050064
- --8310130378 forwards branch SER input re status of unresolved issues.In response to ALAB-444 decision Issues A-45 & A-47 listed as confirmatory items rather than open items W/o encls KNIELL K Generic Issues Branch 83/10/04 KNIGHTON,0 Licensing Branch 3 26pp 22499-249 24X Fiche 50-400.84/02/07.8403050064
- --8310170095 Forwards Chemical Engineering Branch proposed license condition to TMI Item II B 3. "Post-Accident Sampling Sys "Contents of draft SER should be used for SER JUHNSTON. W Assistant Director for Matls. Chem & Environ Technology (Post B30201) 83/10/06 NOVAK. TM Assistant Director for Licensing 3pp 22499 279 24X Ficho 50-400.84/02/07.8403050064
- ~-8310190067 Forwards aerial maps as input to 821222 draft SER Item re shipment of toric matls past plant site not resolved JOHNSTON.H V Assistant Director for Matls, Chem & Environ Technology (Post 830201) B3/10/11 NOVAK,T M Assistant Director for Licensing App 22497 331 24X Fichs. 30-400.84/02/07,8403050064
- --8310200096 Forwards SER input on pump & valve operability assurance program & seismic & dynamic qualification of seismic Category I mechanical & electrical equipment AddI info needed for TMI Items IE & 4.2 & II.D I re reliability KNIGHT.J P Assistant Director for Comp & Structures Engineering (Post B30201) B3710/06 NOVAK.T M Assistant Director for Licensing 4pp. 22479 275 24% Fiche 50-400.84/02/07.8403050064
- --B310310445 Forwards results of review of Sections 5 2 2.5 4 7.6 3 % 15 through Amend 10 of FSAR Open issues which will be summarized in later SER suppl listed HOUSTON.R U Assistant Director for Reactor Safety NOVAK,T M Assistant Director for Licensing 49pp 2247 Fishe 50-400.84/02/07.8403050064
- --B311100049 Informs that applicant is to submit calculation of ultimate strength capacity of containment bldg under internal pressure as resolution of BER outstanding confirmatory structural item Marked-up BER input encl

 LEAR. G Structural & Geotechnical Engineering Branch 83/10/28 KN19H1GN.0 Licensing Branch 3 3pp 22500 024 24X Fiche 50-400.84/02/07.8403050044
- --B3iiii0263 informs of closmout of listed sections of B30914 SER based on new info Updated sections encl Closeout of addl open items, including NUREO-0612 info.will take place as acceptable info made available RUBENSTEIN.L B Assistant Director for Core & Plant Systems B3/10/2B NOVAK,T M Assistant Director for ticensing 49pp 22499 337 24X Fiche 50-400, B4/02/07, B403030064
- --83:1140004 Advises that, due to need to coordinate effort w/Auxiliary Sys Branch, revised SER to be submitted on 83:127 will still contain listed fire protection open items
 JOHNSTON, W V Assistant Director for Matls, Chem & Environ Technology (Post 830201) 83/11/03 NGVAK, T Assistant Director for Licensing 2pp 22500 030 24X Fiche 50-400,84/02/07,8403000064
- --8311160283 Forwards revised SER input on confirmatory item re ultimate strength capacity of concrete containment bldg Item resolved LEAR.0 Structural & Geotechnical Engineering Branch 83/11/14 KNIGHTON.6 Licensing Branch 3 Spp 22500 047 24X Fiche 50-400.84/02/07.8403050064
- --8311160367 Informs that draft SER Section 17 acceptable except in area of items subj to 100FR50. App B. GA program during operations phase Info re current status & acceptability of GA program encl
 PARTLON. J G Division of GA, Safeguards & Inspection Programs (Post 830103) 83/11/07 YOUNGBLOOD B J Licensing Branch 1
 3pp 22500 027 24X Fiche 50-400. 84/02/07.8403050064
- --8311270301 Forwards revised Hydrologic Engineering input to SER New Tech Spec requirement developed re watertight doors for safety-related bldgs JOHNSTON.W V Division of Engineering Technology 89/11/10 NOVAK.T M Assistant Director for Licensing 15pp 22500 032 24X Fiche 50-400,84/02/07.8403050064

- --8311270352 Updates BER re stability of retaining wall west of fuel handling bidg Based on applicant 830719 submittals, stability cannot be assured due to lack of listed info Final BER update encl
 LEAR.O E Hudrologic & Geotechnical Engineering Branch 83/11/18
 KNIOHTON.O Licensing Branch 3 5pp 22501 049 24X
 Fiche: 50-400,84/02/07,8403050064
- --B312020063 Forwards SBER resolving open item on toxic gas shipments past site Concurs w/findings & considers item closed UDHNSTON, W V Assistant Director for Matls, Chem & Environ Technology (Post 830201) B3/11/18 NOVAK, T M Assistant Director for Licensing 2pp 22301 054 24X Fiche 50-400,84/02/07,8403050064
- ---B3120801B8 Forwards efficient treatment sys section input to SER Open items include method for determining releases of noble gases from mechanical vacuum pumps & radioactivity monitor on discharge from svc water sys MULLER:D R Assistant Director for Radiation Protection B3/1/1/8 NOVAK:T M Assistant Director for Licensing 51pp 22500 139. 24X Fiche 50-400.84/02/07.8403050064
- --8312120002 Lists closed out open items in SER forwarded on 830914 & sections w/remaining open items RUBENSTEIN:L B Assistant Director for Core & Plant Systems 83/1/17 NOVAK:T M Division of Licensing 88pp 22500 050 24X Fiche 50-400,84/02/07.8403050064
- --8312120445 Forwards input to SER.consisting of emergency plan evaluation rept & responses to NUREO-0737. Items
 III.A 1 i.III A 1 2 & III A 2 re wheregency preparedness
 MATTHEMS.D B Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/11/30 KNIGHTON.G Licensing Branch
 3 36pp 22501 058 24X Fiche 50-400.84/02/07.8403050064.
- --8312140429 Submits review of draft SER response to Open Item 47 on RCS vents Proposed design conforms w/criteria gutlined in NUREO-0737 clarification pertaining to electrical power supplies to vent valves SRINIVABAN.M Fower Systems Branch 83/11/23 SHERON, B Reactor Systems Branch 2pp 22501 036 24X Fiche 50-400, 84/02/07, 8403030064
- --8312230278 Forwards revised SBER re fire protection Listed items remain open JOHNSTON.W V Assistant Director for Matls, Chem & Environ Technology (Post 830201) 83/12/14 NOVAK.T Assistant Director for Licensing 12pp 22501 094 24X Fiche 50-400,84/02/07, 8403050064
- B403130062 Forwards add1 info re fuel handling bldg reteining wall design, in response to SER Open Item 1 from Structural & Geotechnical Engineering Branch HCDUFFIE, HA Carolina Power & Light Co 84/03/07 DENTON, H, R Office of Nuclear Reactor Regulation, Director Spp 22601.234 24X Fiche 50~400,84/03/07,8403130062
- 8403140174 Forwards Rev O to Inservice Insp Procedura ISI-201, "ABME Preservice Insp Program Plan (Except Reactor Vessel)," in response to Matls Engineering Branch SER Open Item 6 MCDUFFIE,M A Carolina Power & Light Co 84/03/07 DENTON,H R. Office of Nuclear Reactor Regulation, Director 2pp 22620.090 24X Fiche 50-400,84/03/07,8403140174
- --B40314017B Rev 0 to Inservice Insp Procedure ISI-201, "ASME Preservice Insp Program Plan (Except Reactor Vessel)," W/45 aperture cards Aperture cards are available in PDR * Carolina Power & Light Co. 84/02/03 74pp 22620 092 24X Fiche 50-400,84/03/07,8403140174
- 8403140120 Forwards Rev 2 to smergency plan.per SER Changes reflect cancellation of Unit 2, interfaces w/State of NC radiological smergency response plan & evacuation time study results. MCDUFFIE.M A Carolina Power & Light Co 84/03/08 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp. 22624,271. 24X Fichs 50-400,84/03/08,8403140120
- --8403140125 Rev 2 to emergency plan, plant operating manual, Vol 1, Part 2 Related info encl HILLER, J L Carolina Power & Light Co 84/02/29 173pp. 22624 273 24X Fiche, 50-400, 84/03/08, 8403140120.
- B403270134 Forwards add1 info re svc water sys effluent monitoring, in response to SER Open Item 11 from Meteorology & Effluent Treatment Branch.

 MCDUFFIE:M A Caroline Power & Light Co 84/03/22. DENTON-H R Office of Nuclear Reactor Regulation, Director. Spp 22807:101. 24X Fichs 50-400,84/03/22.8403270134

- F Security, medical, emergency & fire protection plans
- 8403160283 Advises of 840316 meeting in Region II ofc to discuss App R requirements & results of recent App R insps Attendance should be limited to six util employees
 LEWIS.R C Division of Project & Resident Programs 84/03/02
 UTLEY,E E Carolina Power & Light Co ip 22640 109 24X
 Fiche 50-000,84/03/02,8403160283
- 8403140120 Forwards Rev 2 to emergency plan.per SER Changes reflect cancellation of Unit 2.interfaces w/State of NC radiological emergency response plan & evacuation time study results MCDUFFIE,M A Carolina Power & Light Co 84/03/08 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 22624 271 24X Fiche 50-400.84/03/08.8403140120
- --8403140125 Rev 2 to emergency plan, plant operating manual, Vol 1, Part 2 Related info encl MILLER, J.L. Carolina Power & Light Co. 84/02/29 173pp 22624 273 24X Fiche 50-400,84/03/08,8403140120
- 8403190065 Forwards State of NC & Chatham Harnett, Lee & Wake Counties emergency response plan Plan forwarded to ASLAB for use in hearings by separate ltr dtd 840228 MCDUFFIE, M A Carolina Power & Light Co 84/03/12 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 22663 130 24X Fiche 50-400, 84/03/12, 8403190065
- --8403190067 Emergency response plan * North Carolina, State of 84/02/29 454pp 22663 131 24X Ficha 50-400,84/03/12,8403190065
- Q Adjudicatory correspondence
- 8402230207 Further response to FOIA request for documents re const flaws at facility Forwards documents listed in App A Documents also being placed in PDR & LPDR Review continuing FELTON.J M Division of Rules and Records 83/12/02 VADEN.T Naws & Observer/Raleigh Times, Raleigh, NC 3pp 22378 299 24: Fichs, 50-400, 83/12/02, 8402230207
- --Bi04210125 Discusses implications of Ofc of Inspector & Auditor 781012 interview w/facility ASLB Dfc of Inspector & Auditor attempted to probe thought processes of & require justification from Board re action taken in adjudication YORE, J. R. Atomic Safety and Licensing Board Panel 78/10/19 HENDRIE, J. M. Commissioners 3pp 22378.302 24X Ficher 50-400, 83/12/02, 8402230207
- --8402230237 Discusses investigation by Ofc of Inspector & Auditor (GIA) re facility proceeding ABLAB unwilling to be interrogated by OIA Hany questions in OIA interrogation of members of ABLB manifestly improper ROBENTHALA, B. Atomic Safety and Licensing Appeal Panel. 78/10/20 HENDRIE Commissioners 2pp 22378 306 24X Fichs 50-400.83/12/02.8402230207
- 8402070054 Forwards corrected copy of Page 10 of NRC 840130 response in opposition to Eddleman proffered Contentions 169,170.

 171 & 172 re safety parameter display sys
 MOUREJ E Hearing Branch 1 84/01/31 KELLEY, J L ,
 CARPENTER, J H , BRIGHT, O, O Atomic Safety and Licensing Board Panel
 1p 22102 361 24X Fiche 50-400,84/01/31,8402070054
- --8402070057 Corrected Page 10 of response opposing Eddleman proffered Contentions 169, 170, 171 & 172 re safety parameter display sys # Hearing Branch 1 84/01/30 Atomic Safety and Licensing Board Fanel 1p 22102 362. 24X Fiche 50-400,84/01/31, 8402070054
- 8402290081 Amended Certificate of 8vc for applicant 840224 motion for reconsideration or clarification of ASLB memorandum & order on health effects contentions Certificate of 8vc encl BAXTER, T.A. Caroline Power & Light Co
- 8403020182 Motion for summary disposition of Joint Intervenor Contention V re continuous air monitors & portable air samples. No genuine issue of mati fact exists & applicant entitled to favorable decision. Related correspondence ANDERBON.P H Carolina Power & Light Co ANDERBON.P H Shaw, Pittman, Potts & Trowbridge 84/02/27 Atomic Safety and Licensing Board Panel 14pp 22440 193 24X Fiche 30-400.84/02/27.8403020182

- --8403020188 Statement of matl facts as to which there is no genuine issue to be heard on Joint Contention V Related correspondence
 ANDERSON.P H Carolina Power & Light Co ANDERSON.P H Shaw, Pittman. Potts & Troubridge 84/02/27 Atomic Safety and Licensing Board Panel 3pp 22440 207 24X Fiche 50-400. 84/02/27,8403020182
- --8403020192 Affidavit of WH Wilkie in support of applicant motion for summary disposition of Joint Intervenors Contention V Certificate of Svc enci Related correspondence WILLE.W H. Carolina Power & Light Co. 84/02/24 17pp 22440 210 24X Fiche 50-400.84/02/27.8403020182
- 8403010263 Response opposing W Eddleman motion to admit Contention SB(2d) on financial qualifications of co-applicants ASLB has no basis or authority to reconsider original ruling on contention & motion must be denied Certificate of Svc encl O'NEILL.JH Carolina Power & Light Co O'NEILL.JH Shaw, Pittman, Potts & Trowbridge 84/02/28 Atomic Safety and Licensing Board Panol 7pp 22432 258 24X Fiche 50-400,84/02/28,8403010263
- 8403070051 Forwards emergency response plan in support of facility
 Plan encompasses state plan & plans of Chatham Harnett, Lee.
 & Wake Counties W/o encl Related correspondence
 HOLLAR D E Carolina Power & Light Co 84/02/28 KELLEY, J L ,
 BRIGHT, G O , CARPENTER J H Atomic Safety and Licensing Board Panel
 2pp 22541 276 24X Fiche 50-400,84/02/28,8403070051
- B403070055 Motion for summary disposition of Eddleman Contention 15AA re capacity factor No genuine issue of matl fact exists
 Relaked correspondence
 HOLLAR.D E Carolina Power & Light Co B4/02/28 Atomic Safety
 and Licensing Board Panel 15pp 22541 123 24X
 Fiche 50-400.84/02/28,8403070055
- --B40307005B Statement of matl facts as to which there is no genuine issue HDLLAR.D E Carolina Power & Light Co B4/02/28 Atomic Safety and Licensing Board Panel 3pp 22541 138 24X Fiche 50-400.84/02/28.8403070055
- --B403070059 Affidavit of RH Koppe in support of applicant motion for summary disposition of Eddleman Contention 15AA Certificate of Svc encl Related correspondence KDCPE,R H Carolina Power & Light Co 84/02/27 24pp 22541 141 24X Fiche 50-400,84/02/28.8403070055
- 8403140102 Policy statement on environ qualification of safety-related electrical equipment Commission will conduct notice & comment rulemaking proceeding to delete formally 820630 compliance deadline Certificate of Bvc encl CHILK, 8 J Office of the Secretary of the Commission 84/03/01 37pp 22624 144 24X Fiche 50-400.84/03/01.8403140102
- 8403070134 Amend to 840113 motion for protective order preventing public disclosure of employee info sought by discovery request of W Eddleman Order issued by ASLB appropriate & necessary Certificate of Svc encl Related correspondence BAXTER: TA Carolina Power & Light Co BAXTER: TA Shaw, Pittman, Potts & Trowbridge 84/03/02. Atomic Safety and Licensing Board Panel 11pp. 22538 254 24X Fiche 50-400,84/03/02,8403070134
- 8403070225 Requests questions re Contention 41 requiring discovery responses be filed before 840315 Second round discovery will be given if protective order issue not resolved before 840315 M/Certificate of Svc Related correspondence BAXTER.T A Shaw, Pittman, Potts & Troubridge BAXTER.T A Caralina Power & Light Co 84/03/02 EDDLEMAN.W Eddleman. W 4pp 22541 300 24X Fiche 50-400.84/03/02.8403070225
- 8403140157 Response opposing W Eddleman 840213 motion for admission of Contention 5B (2D) re financial qualifications Eddleman argument inaccurate W/NRC 840227 statement of policy MODRE, J E Hearing Branch 2 84/03/05 Atomic Safety and Licensing Board Panel 5pp 22624 001 24% Fiche 50-400,84/03/05,8403140159
- --8403140163 Response in support of applicant 840207 motion for summary disposition of Eddleman Contention 83/848 on grounds that there is no genuine issue of matl fact to be litigated MODRE, J E Hearing Branch 2 84/03/05 Atomic Safety and Licensing Board Panel 10pp 22624 006 24X Fiche 50-400,84/03/05,8403140159
- --8403140168 Affidavit of JC Lehr supporting NF motion for summary disposition of Eddleman 83/488 Applicant assessment consistent w/NF FES W/Centificate of Syc LEMR, J C Environmental & Hydrologic Engine 84/03/05 11pp 22624 016 24% Fiche 50-

- 8403120002 Supplemental answer to applicant interrogatories & requests for production of documents on Joint Contentions I & VII Certificate of Svc encl Related correspondence.

 PAYNE M T Kudiu Alliance PAYNE M T & Efelstein & Payne PAYNE M T Joint Intervenors Sharon Harris 84/03/07 4pp 22589 298 24X Fiche 50-400.84/03/07,8403120002
- B403130001 Reply to applicant & staff on SER contentions & motion to continue deferral of parts of Eddleman Contention 107 Contentions on SER & Contention 107 should be admitted EDDLEMAN.W Eddleman.W 84/03/07 Atomic Bafety and Licensing Board Panel 9pp 22615 204 24X Fiche 50-400,84/03/07.8403130001
- 8403130186 Hotson to declare applicant 840228 motion for summary disposition on Contention 15-AA untimaly Twenty-day extension should be granted to respond to motion in alternative Related correspondence EDDLEMAN, W Eddleman, W 84/03/07 Atomic Safety and Licensing Board Panel 4pp 22634 220 24X Fiche 50~400,84/03/07.8403130186
- --8403130196 Motion to allow filing of affidavit of JD Blackburn re W Eddleman tOCFR2 758 patition & affidavits Related correspondence EDDLEMANN Eddleman, W 84/03/07 Atomic Safety and Licensing Board Panel 1p 22634 224 24% Fiche 50-400,84/03/07, 8403130186
- ~-8403130207 Affidavit of JØ Blackburn in support of W Eddleman IOCFR2 738 potition & affidavits BLACKBURN, J O Affiliation Not Assigned 84/02/14 Jep 22634 225 24% Fiche 50~400.84/03/07,8403130186
- --8403130R20 Answer to staff on summary disposition of Eddleman Contention 65 & applicant 840214 answer to Contention 65. Summary disposition lethal weapon not to be faced unarmed Related correspondence EDDLEMAN R Eddleman R 84/03/07 Atomic Safety and Licensing Board Panel 2pp 22634 228 24X Fiche 50-400.84/03/07, 8403130186
- --8403130230 Response to applicant interrogatories re Contentions 9,11 & 132(C)(2) Related correspondence
 EDDLEMAN W Eddleman W 64/03/07 Atomic Safety and Licensing
 Board Panel 20pp 22634 230 24X Fiche 50-400.84/03/07,
 8403130186
- 8403130156 Hotion for summary disposition of Joint Intervanor Contention VI re monitoring sys. No genuine issue of matlifact exists & applicant entitled to favorable decision Related correspondence ANDERSON.P H Carolina Fower & Light Co ANDERSON.P H Shaw. Fittman. Potts & Trowbridge 84/03/09 Atomic Safety and Licensing Board Panel 18pp 22599 003 24X Fiche 50~400.84/03/09.8403130156
- --8403130164 Affidavit of WH Wilkie & RL Shearin in support of applicant motion for summary disposition of Joint Intervenor Contention VI Certificate of Svc enc! WILKIE, W H , SHEARIN, R V Carolina Power & Light Co 84/03/08 122pp 22599 021 24% Fiche 50-400,84/03/09,8403130156
- 8403(30447 Response to W Eddleman 840307 mption to declare util 840228 motion untimely Eddleman motion frivolous insulting & unfounded Related correspondence D'NEILL, J H. Carolina Power & Light Co. D'NEILL, J H. Shaw, Pittman, Potts & Trowbridge 84/03/09 Atomic Safety and Licensing Board Panel Spp. 22613 182 24X Fiche, 50-400, 84/03/09, 8403130447
- ---8403130459 Response opposing W Eddleman 840307 motion to allow filing of affidavit of JO Blackburn Good cause undemonstrated Certificate of Svc anc.

 D'NEILL, JH Carolina Power & Light Co D'NEILL, JH Shaw, Pittman, Potts & Troubridge 84/03/09 Abomic Safety and Licensing Board Panel. Gpp 22613 187 24X Piche: 50-400, 84/03/09,8403130447
- 8403160018 Memorializes 840313 telcon extending time for discovery requests on safety contentions & for response to applicant motion for summary disposition Certificate of Svc encl 8AXTER,T A Shaw, Pittman, Potts & Troubridge BAXTER,T A Carolina Power & Light Co 84/03/13 EDDLEMAN,W. Eddleman, W 4pp 22653 360 24X Fiche 50-400,84/03/13,8403160018
- 8403220222 Supplemental document listing on discovery Related correspondence EDDLEMAN.W Eddleman, W DSB 052 84/03/13 Carolina Power & Light Co 29p 22719 001 24X Fiche. 50-400, 84/03/13, 8403220222

- 8403230270 Joint Intervenors second suppl to answers to applicant interregatories on Joint I re mpt incapability Certificate of Svc encl Related correspondences
 EDDLEMAN.W Eddleman. W EDDLEMAN.W Joint Intervenors Shear
- 8403190137 Forwards applicant & NRC joint motion to withdraw Contentions 2,3 & 4 re security plan Agreement exchanged resolving issues FLYNN.8 F Carolina Power & Light Co 84/03/14 KELLEY, J L , BRIGHT, G D . CARPENTER, J H Atomic Safety and Licensing Board Panel 2pp 22664 310 24X Fiche 50-400.84/03/14,8403190137
- --8403190141 Joint motion to withdraw security plan Contentions 2,3 % 6 Certificate of Svc encl RUNKLE.J D Joint Intervenors - Shearon Harris FLYNN, 8 F Carolina Power & Light Co BARTH, C A Hearing Branch 1 84/03/14 Atomic Safety and Licensing Board Panel 3pp 82666 312 24X Fiche 50-400,84/03/14.8403190137
- 8403200030 Supplemental responses to W Eddleman general interrogatories & interrogatories on Contentions 41 & 65 Certificate of Svc entl Related correspondence
 BAXTER.T A Carolina Power & Light Co BAXTER.T A Shaw. Pitlagn. Potts & Troubridge 84/03/14 Eddleman. W 7pp 22683,345 248
 Fiche 50-400.84/03/14.8403200030
- 8403190025 Memorandum & order reaffirming rulings on response to B40129 order re health effects SRIGHT.0 0. CAPPENTER.J H., KELLEY.J L. Atomic Safety and Licensing Board Panel 84/03/15 Office of the Executive Legal Director 20pp 22666 085 24X Fiche 50-400.84/03/15,8403190025.
- 8403190053 Interrogatory to Joint Intervenors re Jaint Contention VII Response in writing required by 840403 BARTH/C A Hearing Branch 1 84/03/15 Joint Intervenors -Shearon Harris ip 22666 188 24X Fichs 50-400,84/03/15,
- --B40319005B Interrogatories to W Eddleman re Eddleman Contentions (1.4) 67 & 116 Response in writing required by 840403 Certificate of Svc and BARTH. C A Hearing Branch 1 84/03/15 EDDLEMAN, W Eddleman, W Bpp 22564 189 24X Fiche 50-400.84/03/15.8403190093
- 8403200054 Interragator(es to applicant on admitted security contention Encl withheld (ref 10CFR73 21) W/Certificate of Bvc Related correspondence RUNKLE. J Joint Intervenors Shearon Harris 84/03/15 Carolina Power & Light Co 3pp 22698 273 24X Fiche 50-400.84/03/15, Recordors
- 8403200117 Interrogatories & request for production of documents on W Eddleman Contention 1320(II) second set Certificate of Svc encl Related correspondence CARROW, H Carolina Power & Light Co 84/03/15 Eddleman, W 8pp 22685 334 24X Fithe 50-400,84/03/15,8403200117
- 8403200135 Notice of ER Bleacher & JR Maples depositions on \$40329 in Raleigh.NC Certificate of Svc encl Related correspondence CARROW, H Carolina Power & Light Co CARROW, H Shaw, Pittman, Potts & Trowbridge 84/03/15 3pp 22699 161 24% Fiche 50-400,84/03/15,8403200135
- B403210120 Informs that part of transcript of B40308 telcon reidentification of persons in room at time of call missing BARTH.C A Hearing Branch 1 84/03/16 KELLEY, J. L. BRIGHT.Q O. CARPENTER, J. H. Atomic Safety and Licensing Board Panel ip 22707 179 24% Fiche 50-400,84/03/16.8403210120
- 8403200048 Provides corrections to statements of scheduling egreements par 840313 ltr Extension to 840403 for Eddleman 41 applies only to second round questions not based on welder info Related correspondence EDDLEMAN.W Eddleman, W 84/03/17 BAXTER.T Shaw, Pittman, Potts & Trowbridge 1p 22679 185 24X Fiche 30-400,84/03/17,8403200048
- 8403210051 Order approving joint motion to withdraw security plan Contentions 2,3 & 6 Cooperation commended KELLEY.J L . CARPENTER.J H., BRIGHT.O D Atomic Safety and Litansins Board Panel 84/03/19 Office of the Executive Legal Director 2pp 22704 342 24X Fichs 50-400.84/03/19,8403210051
- 8403220223 Motion to quash applicant notice to take deposition of Bleacher & Maples. Unlikely applicants can meet even threshhold showing of good cause Certificate of Bvc encl. Related correspondence BUNKLE, J Joint Intervenors Shearon Harris DBB 045. 84/03/19 Atomic Safety and Licensing Board Panel App 22719 003 24% Fiche 50-400.84/03/19,8403220223

1

- 8403220227 Responds to 840313 response to Eddleman 41 Related correspondence EDDLEMAN.W Eddleman. W DSB 051 84/03/17 BAXTER,T Shaw, Pittman. Potts & Trowbridge 2pp 22717 012 24X Fichs 30-400.84/03/19.8403220227
- B403220261 Interrogetories & request for production of documents to Joint Intervenors (seventh set) Certificate of Svc encl Related correspondence O'MEILL, JH Carolina Power & Light Co O'NEILL, JH Shaw, Pittman, Potts & Trowbridge DSB 058 84/03/19 Joint Intervenors Shearon Harris 21pp 22719 110 24X Fiche 50-400,84/03/19,8403220261
- 8403220265 Jaint Intervenor general interrogatories & interrogatories on Contention 7 (first set) Related correspondence EDDLEMAN.W Eddleman.W EDDLEMAN.W Joant Intervenors Shearon Hanris D88 030 84/03/19 Carolina Power & Light Co 24pp 22719 131 24% Fiche 50-400,84/03/19,8403220265
- 8403280361 Clarification of Joint Intervenors position re J Cofman Gofman absolutely unwilling to appear as intervenor witness EDDLEMAN.W Joint Intervenors Shearon Harris EDDLEMAN.W Eddleman. W DSB 175 84/03/20 2pp 22787 232 24X Fiche 50-400,84/03/20,8403280361
- 8403260327 Interrogatories & request for production of documents re Eddleman Contentions 9 & 11 (second set) Certificate of Bvc encl Related correspondence BWIGER, M A Carolina Power & Light Co SWIGER, M A Shaw, Pittman, Potts & Trawbridge DSB 104 84/03/23 Eddleman, W 14pp 22760 149 24X Fiche 50-400,88/03/23,8403260327
- B403260328 Responds to 840317 & 19 ltrs re extension to file discovery requests, welder info confidentiality & interrogatory answers, Svc list encl Related correspondence
 BAXTER, T A Shaw, Pittman, Potts & Troubridge BAXTER, T A Carolina Power & Light Co DSB 103 84/03/23 EDDLEMAN, W Eddleman, W 4pp 22760 137 24X Fiche 30-400, 84/03/23, 8403260328
- 8403260348 Responses to general interrogatories & interrogatories on Contention 65 (seventh set) Related correspondence

 BAXTER, T A Carolina Power & Light Co BAXTER, T A Shaw, Pittman, Potts & Troubridge D88 102 84/03/23 Eddleman, W 47pp

 22760 190 24X Fiche 50-400, 84/03/23, 8403260348
- --8403260354 Response to request for production of documents (Contention 65) Certificate of Svc encl BAXTER.TA Carolina Power & Light Co BAXTER.TA Shaw, Pittman, Potts & Trowbridge 84/03/23 Eddleman, W 6p 22760 237 24X Fiche 50-400,84/03/23,8403260348
- 8403270319 Response opposing W Eddleman 840307 motion to allow filing of affidavit of JO Blackburn Affidavit is untimely suppl to petition re need for power & alternative energy sources Ceptificate of Svc encl MODRE J.E. Hearing Branch 1 DSB 133 84/03/23 5pp 22787 023 24X Fiche 50~400,84/03/23,8403270319
- 8403270321 Clarification of staff response in support of applicant motion for summary disposition of Joint Intervenors Contention IV of TLDs BARTHLO A Hearing Branch 1 DSB 130 84/03/23 Atomic Safety
- Contention by reside BARTH, C.A. Hearing Branch 1 DSB 130 84/03/23 Atomic Safety and Licensing Board Panel 3pp 22789 020 24X Fiche 50-400,84/03/23,8403270321
- 8403270333 Response in support of applicant 840227 motion for summary disposition of Joint Intervenors Contention V re calibr of air monitors Related correspondence
 BARTH.C A Hearing Branch 1 D88 129 84/03/23 Atomic Safety and Licensing Board Panel. 2pp 22789 004 24X
 Fiche 80-400,84/03/23,8403270333
- --8403270338 Affidavit of 8 Block in support of summary disposition of Joint Contention V. Centificate of Bvc encl BLOCK, 9 Division of Systams Integration (post B11005) 84/03/15 Bp 22789:008 24% Fiche 50-400,84/03/23,8403270333
- 8403280344 Response to applicant interrogatories re Eddleman 116 Related correspondence. EDDLEMAN: W Eddleman. W DSB 177 84/03/23 Carplina Power & Light Co App 22787.116 24X Fiche 50-400.84/03/23.8403280344
- 8403280349 Notifies of inability of copy ctrs to copy new filings due 840323, Notion made for extension of time to ensure duplication Related correspondence EDDLEMAN, H. Eddleman, W. D88 176 84/03/23 KELLEY, J. Atomic Bafety and Licensing Roard Panel BAXTER, T. Shaw, Pittman, Potts & Trowbridge, 2pp. 22787 144 24X Fichs 50-400,84/03/23,8403280349

- B403280351 Eddleman general interrogatories & interrogatories on Contentions 9,11,41,45,116 & 132(c)(2) to applicant (eighth set) Cortificate of Svc encl Related correspondence EDDLEMAN.W Eddleman, W DSB 166 B4/03/23 Carolina Power & Light Co 24pp 22787 148 24X Fiche 50-400,84/03/23,8403280351
- 8403280360 Response to util motion for summary disposition on 83/848 t motion for licensing conditions No Cape Fear River water should be used by util for cooling Related correspondence EDDLEMAN, W Eddleman, W DSB 174 84/03/23 Atomic Bafety and Licensing Board Panel 1p 22787 231 24% Fiche 50-400.84/03/23, 8403280360
- 8403270327 Advises that term job experience used in 840314 discovery responses, includes only welding experience Related correspondence BAXTER.T A Shaw, Pittman, Potts & Trowbridge BAXTER.T A Carolina Power & Light Co DSB 144 84/03/26 EDDLEMAN, W Eddleman, W 3pp 22789 016 24X Fiche 50-400,84/03/26,8403270327
- 8403280347 Eddleman & Joint Intervenors interrogatories to NRC staff (third set) Related correspondence EDDLEMAN, W Eddleman, W DBB 165 84/03/26 Dffice of the Executive Legal Director 16pp 22787 127 24X Fiche 50-400.84/03/26.8403280347
- M Antitrust correspondence
- 8403020076 Notification of 840224 meeting w/util in Bethesda.MD to discuss antitrust matters
 BUCKLEY, BC Licensing Branch 3 84/02/17 KNIGHTON, & W
 Licensing Branch 3. 4pp 22491 179 24X Fiche 50-400,84/02/17.
 AACHDONG
- 8403020084 Notification of change in date & time for 840302 meeting w/util in Bethesda, MD to discuss antitrust matters BUCKLEY, B C Licensing Branch 3 84/02/27 KNIGHTON, G W Licensing Branch 3 4pp 22491 184 24X Fiche 50-400, 84/02/27, 8403020084
- B4032B0024 Forwards MA McDuffie 840216 response to B30119 request for add1 antitrust info to continue review of OL application.per Rag Guide 9 3 Recipient inadvertently omitted from list ZIMMERMAN.S R Carolina Power & Light Co B4/03/19 VOQLER, B NRC No Detailed Affiliation Given ip R2777 087 24x Fiche 30-400.B4/03/19, 84032B0024
- 8403260007 Forwards responses to questions raised in 840302 meeting reantitrust review MCDUFFIE.M A Carolina Power & Light Co 84/03/20 TOALSTON, A L Biting Analysis Branch 70pp 22750 155 24X Fiche 50-400, 84/03/20,8403260007
- O Advisory Committee on Reactor Bafeguards reports & correspondence
- 8403140302 Discusses seismology issues in OL review Extremely conservative values established for OBE & SSE Plant site is as as aserly aseismic as any site in eastern US MAXWELL. J C Maxwell. J C MAXWELL. J C ACRS Advisory Committee on Reactor Safeguards 84/01/05 KERR. W ACRS Advisory Committee on Reactor Safeguards ip 22635 317 24X Fiche 50-400.84/01/05, 8403140302
- 8403160085 Comments on 840103-04 site visit & OL hearing in Apex.NC Requests opportunity to view final control room & new simulator PEARSON,R @ North Carolina State Univ. Raleigh, NC PEARSON,R @ ACR8 Advisory Committee on Reactor Safeguards 84/01/05 KERR.W ACRS Advisory Committee on Reactor Safeguards MAJOR.R. North Carolina State Univ., Raleigh, NC 3pp 22662 278 24% Fiche 30-400.84/01/05,8403160085
- 8401300121 Summarizes ACRS 285th meeting on 840112-14 re review of GL application.control room design & tube degradation Investigation of allegations re GA requested EBERBULE, J C ACRS Advisory Committee on Reactor Safeguards 84/01/16 PALLADINO, N J Commissioners 3pp 22044-023 24X Fiche 30-400,84/01/16,8401300121
- Q Inspection reports. IE Bulletins & correspondence
- 8403070179 Ack receipt of 840208 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-400/83-34
 Implementation of corrective actions will be examined during future insps
 VERRELLI.D M Division of Project & Resident Programs 84/02/22
 UTLEY.E E Carolina Power & Light Co 1p 22547 276 24X
 Fiche 30-400.84/02/22.8403070179

- --B403070184 Responds to NRC B40110 ltr re violations noted in IE Insp Rept 50-400/83-36 Corrective actions transformer replaced Full compliance will be achieved on 840220 PARSDNS,R H Carolina Power & Light Co 84/02/08 O'REILLY, J P Region 2. Office of Director 2pp 22547 277 24X Fiche 50-400,84/02/22.8403070179
- --8403070193 Forwards IE Insp Repts 50-400/B3-36 & 50-401/B3-36 on B31120 & 1220 & notice of violation VERRELLI.D M Division of Project & Resident Programs 84/01/10 UTLEY/EE Carolina Power & Light Co 2pp 22547 279 24X Fiche 50-400,84/02/22,8403070179
- --8403070197 Notice of violation from insp on 831120-1220 * Region 2. Office of Director 84/01/10 lp 22947 281 24X Fiche 50-400,84/02/22.8403070179
- --8403070199 IE Insp Repts 50-400/83-36 & 50-401/83-36 on 831120-1220 Violation noted failure to protect equipment from rainwater entering reactor auxiliary bldg from roof MAXWELL.0 F, PREVATTE.R L Region 2. Office of Director BEMIS.P R Division of Project & Resident Programs 84/01/09 9pp 22547 282 24X Fiche 50-400.84/02/22,8403070179
- 8403070074 Ack receipt of 840118 & 27 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-400/63-35 VERRELLI.D M Division of Project & Resident Programs 84/02/23 UTLEY.E E Caralina Power & Light Co 1p 22545 348 24X Fiche 50-400.84/02/23.8403070094
- --8403070095 Clarifies response to NRC 831220 ltr re violations noted in IE Insp Rept 50-400/83-35 Corrective actions sock-o-let restanged w/correct number on fitting on 840111 PARSONS,R M Carolina Power & Light Co. 84/01/27 O'REILLY, J P Region 2. Office of Director 2pp 22545 349 24X Fiche 50-400,84/02/23,8403070094
- --B403070094 Responds to NRC 831220 ltr re violations noted in IE Insp Rept 50-400/83-35 Corrective actions sock-o-let restamped W/correct number on fitting on B40111 PARSONS.R M Carolina Power & Light Co B4/01/1B D'REILLY.J P Region 2. Office of Director 2pp 22545 351 24X Fiche 50-400,84/02/23.8403070074
- --8403070100 Forwards IE Insp Repts 50-400/83-35 & 50-401/83-35 on 831129-1202 & notice of violation VERRELLI.D M Division of Project & Resident Programs 83/12/20 UTLEY.E E Carolina Power & Light Co 2pp 22545 353 24X Fiche 50-400,84/02/23,8403070094
- --8403070102 Notice of violation from insp on B31129-1202 * Region 2, Office of Director B3/12/20 ip 22545 355 24X Fiche 50-400, 84/02/23, 8403070094
- --B403070105 IE Insp Repts 50-400/B3-35 & 50-401/B3-35 on B31129-1202 Violation noted failure of as-built drawings to reflect actual piping configuration KLEINSORGE, Wp Region 2. Office of Director BLAKE, J J Division of Engineering & Operational Programs 83/12/13 9pp 22545.336 24X Fiche 50-400,B4/02/23,8403070094
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Syc list
 - enci. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) B4/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22909 239 24X Fiche 50-000,84/02/28,8401190072
- 8403160194 Ack receipt of 840207 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-400/83-25 LEWIS.R C Division of Project & Resident Programs 84/03/01 UTLEY.E E Carolina Power & Light Co ip 22655 359 24X Fich# 50-400.84/03/01.8403160194
- 8402090007 IE info Notice B4-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC." Svc list enc! ORACE.J N Division of QA. Bafeguards & Inspection Programs (Post 830103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 327 24X Fiche 50-000,84/03/02.8402090007
- 8402090008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate." Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 078 24X Fiche 50-000.84/03/02.8402090008
- B40209009 IE Info Notice B4-i5, "Reporting of Radiological Releases"
 Svc 11st encl
 JOHDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) 84/03/02 Consolidated Edison Co of New
 York, Inc 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009

- B402090011 IE Info Notice 84-17, "Problems W/Liquid Nitragen Canling Components Belaw Nil Ductility Temp " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New Yark, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- --8403290199 IE Insp Rept 50-400/84-04 on 840214-17 No violations noted Major areas inspected structural concrete, structural backfill, previously identified enforcement items & previously identified inspector followup items HARRIS, J R, CONLON.T E Region 2, Office of Director 84/03/05 5pp 22803 316 24X Fiche 50-400,84/03/06,8403290198
- 8402090824 IE Info Notice 84-09.Rev i, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Past 630103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000,84/03/07,8402090024
- 8402070028 IE Info Notice 84-18. "Stress Corrosion Cracking in PMR 8ys " Svc list encl JURDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07.8402070028
- B403140174 Forwards Rev O to Inservice Insp Procedure ISI-201, "ABME Preservice Insp Program Plan (Except Reactor Vessel)," in response to Matis Engineering Branch SER Open Item 6 MCDUFFIE,M A Carolina Power & Light Co 84/03/07 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 22620 090 24X Fiche 50-400,84/03/07,8403140174
- --B40314017B Rev O to Inservice Insp Procedure ISI-201, "AGME Preservice Insp Program Plan (Except Reactor Vessel) " W/45 aperture cards Aperture cards are available in PDR * Carolina Power & Light Co B4/02/03 74pp 22620 092 24X Fiche 50-400,84/03/07.8403140174
- B403160267 Forwards IE Enforcement Conference Repts 50-261/B4-0B & 50-400/B4-0B on 840223 O'REILLY, J P Region 2. Office of Director 84/03/09 UTLEY, E E Carolina Power & Light Co 2pp 22660 275 24X Fiche 50-000, 84/03/09, 8403160267
- --8403160274 IE Enforcement Conference Repts 50-261/84-08 & 50-400/84-08 on 840223 Major areas discussed unauthorized entry into facility reactor cavity & 0A programs re procurement of sycs & matls
 VERRELLI, D. H. Division of Project & Resident Programs 84/03/06 3pp 22660 277 24X Fiche 50-000,84/03/09,8403160267
- 8402090031 IE Bulletin 84-02. "Failures of GE Type HFA Relays in Use in Class IE Bafety Sys " Svc list enc! DEYDUNG.R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000.84/03/12.8402090031
- 8403290163 Ack receipt of B40307 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-400/84-03
 Implementation of corrective actions will be examined during future insp
 VERRELLI.D.M Division of Project & Resident Programs 84/03/20
 UTLEV.E E Carplina Power & Light Co 1p 22803 327, 24x
 Fiche 50-400.84/03/20.8403290163
- --B403290164 Responds to NRC 840213 ltr re violations noted in IE Insp Rept 50-400/84-03 Corrective actions Weld Joint 1-BI-130-FM-536 documentation changed to show correct Heat Number M 2945 for welded end of Spool 1-RC-134-1 PARSONS.R M Caroline Power & Light Co 84/03/09 O'REILLY, J. P Region 2. Office of Director 2pp 22803 330 24X Fiche 50-400,84/03/20.8403290163
- --8403290169 Forwards IE Insp Rept 50-400/84-03 on 840124-27 & notice of violation
 VERRELLI,D M Division of Project & Resident Programs. 84/02/13
 UTLEY,E E Carolina Power & Light Co 2pp 22809-332. 24X
 Fiche 50-400,84/03/20,8403290163
- --8403290171 Notice of violation from insp on 840124-27 * Region 2, Office of Director 84/02/13 ip 22803.334 24X Fiche 50-400,84/03/20,8403290163

- ~-8403290173 IE Insp Rept 50-400/84-03 on 840124-27 Violation noted failurs to provide adequate procedures for heat number verification

 KLEINSORGE N P Region 2. Office of Director BLAKE, J J Division of Engineering & Operational Programs 84/02/08 13pp 22803 335 24X Fiche 50-400.84/03/20,8403290163
- 8402070043 IE Info Notice 84-19: "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Syc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 123pp 22823 229 24X Fiche 50-000.84/03/21.8402070043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys." Bvc list entl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22733 001 24X Fiche 50-000,84/03/21.8402090044

R Periodic operating reports & related correspondence

- 8403020443 Forwards monthly status rept of offsite emergency preparedness for OL reviews for Jan 1984 Changes in FEMA finding dates not caused by delay due to offsite emergency planning issues
 DIRCKS.W J Office of the Executive Director for Operations 84/02/21 PALLADINO Commissioners 9pp 22492 083 24X Fiche 50-000.84/02/21.8403020443
- B Reportable occurrences, LERs & related correspondence
- 8403010451 Informs Commission of problems w/emergency diesel generators mfg by Transamerica Delaval. Inc DIRCKS. W. J. Office of the Executive Director for Operations 8ECY-83-034 84/01/25 4pp 22438 347 24X Fichs 50-000,84/01/25.8403010451
- 8402270274 Third interim deficiency rept. Item 111 re seismic qualification test failure of Transamerica Delaval. Inc starting air check for emergency diesel engine generator sets Also reportable per Part 21 Next rept by 840525 PARBONS,R M Carolina Power & Light Co 84/02/15 0'REILLY, J P Region 2. Office of Director App 22391 304 24X Fiche 50-400.84/02/15.8402270274
- 8403010350 Interim deficiency rept, Item 158 re Pullman Const Industries/Ebasco design interface HVAC ductwork Differences impacting seismic qualification may exist between design & fabrication documents Also reportable per Part 21 PARSONE, R M Carolina Power & Light Ca 84/02/17 0'REILLY, J F Region 2, Office of Director 1p 22432 328 24X Fiche 50-400,84/02/17,8403010350
- 8403010394 Deficiency & Part 21 repts. Item 157 re Ruskin Mfg Co supplied actuators failing to meet functional test requirements of GH Bettis Co Initially reported on 631221 Next rept will be submitted by 840323 PARSONE: R M Carolina Pawer & Light Co 84/09/17 0'REILLY, J P Region 2. Office of Director 1p. 22434 046 24X Fiche 50-400:84/02/17,8403010394
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines. 91mpel.NPS-4 T&T valve.to close Encl ltr dtd 840203 sent to listed utils GE notified of affected units in BHR plants.
 THERGUX.R R Terry Gorp 84/02/22 WOODRUFF.R.W Director's Office. Office of Inspection and Enforcement 6pp 22706.327 24X Fiche.50-000.84/02/22.8403210032
- 8403070290 Fourth interim deficiency rept, Item 77 re seismic Class I cable tray, conduit & HYAC hangers supplied by Peden Steel Initially reported on 820802 Component reinsp in progress Next rept by 840701. Also reported per Part 21 PARBONS, R M Carolina Power & Light Co 84/02/24 D'REILLY, J P Region 2. Office of Director 4pp 22547 067 24X Fiche 50-400,84/02/24,8403070290
- 8403070082 Fourth interim & Part 21 repts, Item 101 re defective governor drive coupling supplied by Transamerica Delaval. Initially reported on 820707 Couplings to be replaced, Final rept by 840525.

 PAREGNER, R. M. Carolina Power & Light Co. 84/02/24 O'REILLY, J. P. Region 2, Office of Director App. 22575 279 24X Fiche. 50~400, 84/02/24, 8403070082
- 8403010207 Forwards "Investigation of Types AF & AE Piston Skirts," per Transamerica Delaval. Inc Owners Group program commitments Rept evaluates cracks in AF piston skirts in Shoreham & Grand Oulf Nuclear Power Stations MUSELER, W J. TDI (Transamerica Delaval, Inc.) Owners Group 84/02/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 22434 090 24X Fiche. 50-000, 84/02/27, 8403010207

- 8403010218 Forwards task descriptions for 16 known problems re Transamerica Delaval, Inc. emergency diesel generators MUSELER, W. J. TDI (Transamerica Delaval, Inc.) Owners Group 84/02/28 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 42pp 22435 177 24X Fiche 50-000,84/02/28,8403010218
- 8403070285 Fifth interim deficiency & Part 21 repts, Item 117 re welding defects on Class IE 6 9 kV circuit breakers Initially reported on 830211 All Class IE breakers at site returned to Siemens-Allis Final rept expected by 840331 PARSONS: R M Carolina Power & Light Co 84/02/29 D'REILLY, J P Region 2. Office of Director 4pp 22547 075 24X Fichs. 50-400. 84/02/29, 8403070285
- 8403130378 Fifth interim deficiency rept. Item 53 re potential for Westinghouse mfg gate valves failing to fully close/open under design conditions Also reportable per Part 21 Hardware changes completed Final rept expected by 840415 PARSUNS.R. M Carolina Power & Light Co 84/03/01 0'REILLY, J P Region 2, Office of Director 10pp 22616 283 24X Ficha 50-400.84/03/01.8403130398
- 8403130237 Interim deficiency & Part 21 repts, Item 159 re flexible coupling drive shaft in overspeed governor & fuel transfer pump drive of standby diesel generator initially reported on 840206 Final rept will be submitted by 840416 PARSONS.R M Carolina Power & Light Co 84/03/02 O'REILLY, J P Region 2, Uffice of Director ip 22617 277 24X Fiche 50-400.84/03/02.8403130237
- 8403140048 Forwards "Grand Gulf Component Tracking Sys." "Shoreham Component Tracking Sys" & "Transamerica Dalaval Inc Diesel Generators Owners Group Program Plan." to resolve concerns w/emergency diesel generators MUSELER.W J Long Island Lighting Co 84/03/02 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 22626 062 24% Fiche 50-000,84/03/02,8403140048
- ---8403140095 "Transamerica Delaval, Inc Diesel Generators Chuners Group Program Plan " * TD1 (Transamerica Delaval, Inc.) Owners Group 84/03/02 261pp 2262B 223 24% Fichs 50-000,84/03/02,8403140048
- 8403120084 Interim deficiency rept. Item 148 re nondeterminate quality characteristics of 99 of 235 pipe hangers Hanger program revised & 97 hangers reinspected Next rept will be submitted by 840307 PARSONS:R M Carolina Pawer & Light Co 84/03/05 D'REILLY, J P Region 2, Office of Director 1p 22588 183 24X Fiche 50-400.84/03/05.8403120084
- B403200203 Interim deficiency rept. Item 101 & Part 21 rept re defective governor drive coupling Correct ltr date is 840224, hot B30224 PARBUNS, R M Carolina Power & Light Co 84/03/09 O'REILLY, J P Region 2, Office of Director 1p 22699 347 24X Fiche 50-400.84/03/09.8403200203
- 8402070037 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delaval, Inc (YDI) Queers Group Distribution list encl EISENHUT, D & Division of Licensing 84/03/12 PALLADINO Commissioners 5pp 22708 001 24X Fiche 50-000,84/03/12,8402070037
- --8403060536 Forwards summary of 840210 meeting w/Transamerica Delaval.
 Inc Owners Group in Bethesda, MD re problems w/emergency
 diesel generators
 CARUBO, R Licensing Branch 2 84/02/27 D'REILLY, J P NRC No
 Detailed Affiliation Given 6pp 22708 006 24X
 Fiche 50-000,84/03/12,8402090039
- --B403060554 Transcript of B40210 meeting w/Transamerica Delaval: Inc Owners Group in Bethesda, MD re problems w/emergency diesel generators * NRC - No Detailed Affiliation Given 84/02/10 147pp 67201 008 24X Fiche 50-000, 84/03/12,8402090039
- --8403070409 Summary of B40216 meeting w/Transamerica Delaval, Inc Owners Oroup in Wading River, NY re program plan to establish reliability of diesel generators Agenda, meeting transcript & attendance list encl
 MILLER, KA Licensing Branch 4 84/02/27 Licensing Branch 4
 8pp 22708 161 24X Fiche 50-000,84/03/12,8402090039
- --8403070423 Transcript of 840216 conference in Wading River, NY re Transamerica Delaval, Inc diesel generators Pp 1-82 * Commissioners 84/02/16 84pp 22708 169 24X Fiche 80-000,84/03/12,8402090039

- 8403140050 Forwards "Design Review of Connecting Rod Bearing Shells for Transamerica Delaval Enterprise Engines" for Shoreham & Orand Gulf diesel generators MUSELER,W J Long Island Lighting Co 84/03/12 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 22632 074 24X Fiche 50-000,84/03/12,8403140050
- B403150133 Forwards "Transamerica Delaval, Inc Diesel Cenerator Rocker Arm Capstrew Stress Analysis Rept " Capstrew design adequate for applicable engines & svc conditions MUSELER.H J TDI (Transamerica Delaval, Inc.) Gwners Group B4/03/13 DENTON.H R Dffice of Nuclear Reactor Regulation, Director 2pp 22639 270 24X Fiche 50-000,84/03/13,8403150133
- 8403200222 Responds to 840214 Requests for Info 1 & 2 re R-4 series engines List indicating engine number, model & svc number, customer name & address, rating, date shipped & date started encl
 MATHEMS, C S Transamerica Delaval, Inc 84/03/16 EISENHUT, D G
 Division of Licensing 20pp 22691 179 24X Fiche 90-000,84/03/16,8403200222
- 840327009; Interim deficiency rept we seismic HVAC duckwork by Pullman Const Industries not meeting design specs Initially reported on 840120 To date, 63% of suspected ductwork evaluated & datermined acceptable Next rept by 840620 PARSONS, RM Carolina Power & Light Co 84/03/20 D'REILLY, J P Region 2. Office of Director ip 22766 332 24% Fiche 50-400,84/03/20,8403270091
- 8403300043 Third interim deficiency rept. Item 95 re shop welding defects in Seismic I pipe hangers supplied by Bengen-Patterson & Item 72 re understred skewed ter fillet weld on hangers Final rept by 841201 Also reported per Part 21 PARSUNS.R M Carolina Power & Light Co 84/03/21 D'REILLY, J P Region 2. Office of Director 5pp 22819 315 24X Fiche 50~400.84/03/21.8403300043
- 8403270132 Forwards "Emergency Diesel Generator Air Start Valve Capacrew Dimension & Stress Analysis." prepared by SAW for Transamerica Delaval.Inc (TDI) Diesel Generator Dumers Group MUSELER.W J TDI (Transamerica Delaval, Inc.) Gwners Group 84/03/23 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 22774 001 24X Fiche 50-000.84/03/23.8403270132
- 8403270134 Requests meeting on 840418 to discuss short-term & long-term corrective actions & investigations re Transamerica
 Delaval diesel generators List of suggested meeting topics encl
 MCGAUGHY, J P TDI (Transamerica Delaval, Inc.) Eumers Group
 84/03/23 DENTON.H R Office of Nuclear Reactor Regulation,
 Director 4p 22769 133 24X Fiche 50-000,84/03/23,8403270134
- 8403300034 Interim deficiency rept. Item 157 re GH Bettis aperators on Ruskin-supplied HVAC dampers failing to meet functional test requirements Initially reported on 831221 Required info unavailable Next rept by 840321 Also reported per Part 21 PARSONS.R M Carolina Power & Light Co 84/03/23 D'REILLY, J P Region 2. Office of Director 1p 22821 311 24X Fiche 50-400.84/03/23.8403300034
- T Hearing transcripts on non-antitrust matters
- 6403120121 Transcript of B40308 telephone conference in Bethesda.MD Pp 751-807 * Commissioners 84/03/08 58pp 22586 117 24X Fiche 50-400.84/03/08.8403120121
- B402070039 Board Notification B4-052 forwards masting summaries containing transcripts of B40210 & 16 meetings between NRC & Transamerica Delaval, Inc. (TDI) Comers Group Distribution list encl
 EISENHUT, D.G. Division of Licensing B4/03/12 PALLADING Commissioners 5pp 2270B 001 24X Fiche 50-000, 84/03/12, 840209039
- --8403060536 Forwards summary of 840210 meeting w/Transamerica Delaval.
 Inc Owners Group in Bethesda, MD re problems w/emergency
 diesel generators
 CARUSO, R Licensing Branch 2 84/02/27 G'REILLY, J P NRC No
 Detailed Affiliation Given 6pg 22708 006 24X
 Fiche 50-000, 84/03/12, 8402090039
- ---8403060554 Transcript of 840210 meeting w/Transamerica Delaval.Inc Owners Group in Bethesda,MD re problems w/emergency diesel generators * NRC - No Detailed Affiliation Given 84/02/10 147pp 67201 008 24X Fichs 50-000.84/03/12.8402090039

- --8403070409 Summary of 840216 meeting w/Transamerica Delaval, Inc Duners Group in Wading River,NY re program plan to establish reliability of diesel generators Agenda-meeting transcript & attendance list encl MILLER,M A Licensing Branch 4 84/02/27 Licensing Branch 4 Bpp 22708 161 24X Fiche 50-000.84/03/12.8402090039
- --B403070423 Transcript of B40216 conference in Wading River, NY re Transamerica Delaval. Inc diesel generators Pp 1-82 • Commissioners B4/02/16 B4pp 22708 169 24X Fichs 50-000, B4/03/12, B402070037

V Operator Exeminations

- 8403120074 Forwards tables listing nuclear plant operating experience Tables detail experience as of 840305 & experience expected by fuel load Shift advisors, if utilized, will be from within util UTLEY, E Carolina Power & Light Co 84/03/06 DENTON, H R
- UTLEY.E E Carolina Power & Light Co 84/03/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 19pp 22590 208 24% Fiche 50-400, 84/03/06, 8403120076
- DOCKET 50-401 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8402230207 Further response to FOIA request for documents re const flaws at facility Forwards documents listed in App A Documents also being placed in PDR & LPDR Review continuing FELTON.J M Division of Rules and Records 83/12/02 VADEN,T News & Observer/Releigh Times, Raleigh, NC 3pp 22378 299 24) Fichs 50-400.83/12/02.8402230207
- --B402230226 Forwards Ofc of Inspector & Auditor "Inquiry into Alleged Omission of Line Inspector Views from CP Hearing " No further distribution should be made outside of ofc Rept under Commission review GOBBICK:L V Office of the Executive Director for Operations 79/11/15 DENTON Office of Nuclear Reactor Regulation, Director BHAPAR Office of the Executive Legal Director DAVIS Office of Inspection & Enforcement, Office of the Director 1p 22378 305 24X Fichs 30-400, 83/12/02, 8402230207
- --8402230239 Furwards Apps A.B.C & D to be included w/questions for Panel III re facility testimony Related info encl HURPHY.C E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch 79/11/16 REIS.E J. Office of the Executive Legal Director Sipp 2237B 30B 24X Ficha 50-400.83/12/02.8402230207
- --8402230246 Ack 820510 conversation re allegations by facility employee D Jarvis, per Regional Ofc Instruction 2231, Rev 2, Paragraph 2 C (3) Case file encl MAXWELL: 6 Region 2, Office of Director 82/05/10 VORSE. J NRC -- No Detailed Affiliation Given 2pp 22379 032 24X Fiche 50-400, 83/12/02, 8402230207
- --B40223024B Requests that Region II civil insp personnel investigate allegations by unidentified individual re coatings during next routine insp at site Case chronology encl MAXHELL, 0 F Region 2, Office of Director B2/07/07 VORSE, J NRC No Detailed Affiliation Given 2pp 22379 034 24X Fiche 50-400, 83/12/02, 8402230207
- --8402230251 Mat1 maint requirements for Procedure AP-XIII-07,
 "In-Storage Insp & Maint " Equipment purchase order form
 enc!
 # Carolina Power & Light Co 83/12/02 9pp 22379.040 24X
 Fiche 50-400.83/12/02.8402230207
- B403160330 Informs that design & const QA program transmitted by 830509 1tr acceptable LEMIS,R C Division of Project & Resident Programs 84/02/24 UTLEY.E E Carolina Power & Light Co ip 22660 102 24X Fichs 50-400.84/02/24,8403160330
- B402070017 Board Notification 84-038 forwards RJ Mattson 840123 memo to DG Eisenhut providing status update of NRC actions re Westinghouse ECGS actuation logic EIBENHUT, D 0 Division of Licensing 84/02/27 PALLADINO Commissioners 7pp 22546:007 24X Fiche.50-000.84/02/27, 8407208017
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8403050061 FOIA request for extent drafts of sections or portions of SER for plant & documents showing dissenting opinions of staff reviewers EDDLEMAN.W Eddleman.W 84/01/12 FELTON,J Division of Rules and Records 1p 22476 346 24% Fiche.50-400.84/01/12.8403050061

- 8403050064 Partial response to FOIA request for extant drafts of sections of BER for plant & documents showing dissenting opinions of Staff reviewers Forwards App A documents Documents also in PDR Search for addl documents in progress FELTON.J M Division of Rules and Records 84/02/07 EDDLEMAN.W Eddleman, W 4pp 22496 347 24X Fiche 50-400,84/02/07.8403050064
- --8205120076 Forwards request for addi info re organic matls & spent fuel pool cleanup sys FSAR sections BENARDYALV Chemical Engineering Branch 82/04/27 MIRAGLIA, F Licensing Branch 3 4pp 22496 351 24X Fiche 50-400, 84/02/07, 8403050064
- --8205270420 Forwards request for addl info re fire protection program needed to complete review Info needed by 82:102

 BENAROYA, V Chemical Engineering Branch 82:/05/17 MIRAGLIA, F
 Licensing Branch 3 7pp 22497 015 24X Fiche 50-400, 84/02/07, 8403050064
- --8207140072 Submits branch input for draft SER Input assumes that plant meets design objective of App I OAMMILL,W P Meteorology & Effluent Treatment Branch B2/04/25 MIRAQLIA.F J Licensing Branch 3 57pp 22501 007 24X Fiche.50-400.84/02/07.8403050064
- --8211090008 Forwards draft SER input re SRP Sections 2 5 1 on basic geology & seismic info, 2 5 2 on seismology & 2 5 2 3 on SSE No capable faults exist at or around site SRE & OBE adequate KNIOHT, J P Assistant Director for Comp & Structures Engineering (Pre 830201) 82/10/20 NOVAK, T M Assistant Director for Operating Reactors 21pp 22476 355 24X Fiche 50-400,84/02/07,8403050064
- --8211090035 Submits Core Performance Branch input to draft SER Confirmatory & open issues listed RUBENSYEIN.L B Assistant Director for Core & Plant Systems 82/10/21 NUVAK.T M Assistant Director for Licensing 2pp 22497.022 24X Fiche 50-400.84/02/07.8403050064
- --8211110461 Advises that applicant has not responded to request for inform SER items concerning oil collection sys for reactor coolant pump, alternate shutdown capability, fire protection for safe shutdown & NUREG-0800

 BENARDYA, V Chemical Engineering Branch 82/10/28 KNIGHTON, G Licensing Branch 3 ip 22497 088 24X Fiche 50-400,84/02/07,8403050064
- ~-8211160112 Forwards draft BER input re FBAR Sections 2 5 4 2 5 6
 Request for add1 info also encl Site visit necessary before
 end of yr to observe as-built conditions & implementation of
 dam safety monitoring plans
 LEAR.0 E Hydrologic & Geotechnical Engineering Branch 82/11/07
 KERRIGAN.J D Licensing Branch 3 40pp 22497 260 24X
 Fiche 50-400,84/02/07,8403050064
- --8211170249 Forwards draft SER input based on Auxiliary Sys Branch review of FSAR Unresolved items listed RUBENSTEIN, L S Assistant Director for Core & Plant Systems, 82/11/04 NOVAK, T M Assistant Director for Licensing 165pp 22497 089 24X Fiche 50-400,84/02/07,8403050064
- --8211300017 Forwards Chemical Engineering Branch draft SER input re listed sections of FSAR through Amend 2 & 820802 lit., based on SRP (NUREG-0800) & NUREG-0737, Item II. B 3 Addl info needed to complete review of post-accident sampling sys JOHNSTON.W V Assistant Director for Matls & Gual Engineering (Pre 830201) 82/11/17 NOWAW.T Assistant Director for Licensing 21pp 22497 300. 24X Fiche 30-400,84/02/07, 8403050064
- --8212160163 Forwards Structural Engineering Branch summary of FSAR review & draft SER input
 KNIGHT.JP Assistant Director for Comp & Structures Engineering
 (Pre 830201) 82/12/06. NOVAK.T M Assistant Director for
 Licensing 16pp 22497 346. 24X Fiche 50-400.84/02/07.
 8403050064
- --8212160220 Forwards revised Hydrologic Engineering Section SER input Revised input superscedes previous submittal transmitted by 821014 memo LEAR.0 E Hydrologic & Geotechnical Engineering Branch 82/12/03 KNIGHTON,0 Licensing Branch 3. 25pp 22497,321 24X Fiche 50-400,84/02/07.8403050064.
- --8212300403 Forwards draft revised SER input to SRP Sections 2 5 1.
 2 5 2 & 2 5 3 re geology & seismology. Revision includes applicant commitment to install & operate free-field accelerometers

 KNIGHT.J P Assistant Director for Comp & Structures Engineering (Pre 830201) 82/12/21 LAINAS.G C Assistant Director for Licensing. 24pp 22497 362, 24X Fiche 30-400, 84/02/07.
 8403050064

- --8301140474 Forwards Equipment Qualification Branch input for SER Suppl 5 rs environ qualification of mechanical & electrical equipment JOHNSTON. W Assistant Director for Matls & Qual Engineering (Pre 830201) 83/01/10 NOVAK.T M Assistant Director for Licensing 3pp 22498 033 24% Fiche 30-400.84/02/07,8403050064
- ~~8301260036 Forwards Meteorology & Effluent Treatment Branch input to draft SER Assumption that draft meets 10CFR50.App 1 objectives will be verified when fluidize bed dryer effluents calculated NUREG-0737. Item III D i i incomplete HOUSTON.R W Assistant Director for Radiation Protection 83/01/06 NOUAW.T M Assistant Director for Licensing 58pp 22500 310 24X Fiche 50-400.84/02/07.8403050064
- --8309060390 Forwards Equipment Qualification Branch SER input for anviron qualification of equipment important to safety KNZOHT.JP Assistant Director for Comp & Structures Engineering (Post 830201) 83/09/26 NOVAK.TM Assistant Director for Licensing Spp 22498 036 24X Fiche 50-400.84/02/07.8403050064
- --8309200478 Forwards Geotechnical Engineering Section input to SER Input based on FSAR through Amend 9 Stability of 400-ft long retaining wall still open issue LEAR.0 Structural & Geotechnical Engineering Branch 83/09/02 KNIOHTON, Q Licensing Branch 3 76pp 22498 188 24X Fiche 50-400,84/02/07.8403050064
- --8309210078 Forwards Power Sys Branch SER for Chapters 8-10 of FSAR Issues requiring resolution include containment electrical penetrations, use of load sequence w/offsite power & frequency of testing of turbine valves RUBENSTEIN.L 8 Assistant Director for Core & Plant Systems 83/08/31 NOVAK, T M Assistant Director for Licensing 80pp 22498 041 24X Fiche 50-400.84/02/07.8403050064
- --8309210116 Forwards SER input for F9AR Sections 4 2,4 3,4 4,15 4 1, 15 4 2, 15 4 3,15 4 7 & 15 4 8 Confirmatory & open issues identified listed RUBENSTEIN.L S Assistant Director for Cure & Plant Systems 83/09/01 NOVAK.T M Assistant Director for Licensing & 9pp 22498 119 24% Fiche 50-400,84/02/07.8403080064
- --8309220302 Forwards hydrologic engineering input to BER One open item exists re potential for intense local precipitation to flood safety-related structures Tech Spec defining anti-sediment deposit procedure required JOHNSTON: W V Assistant Director for Matls, Chem & Environ Technology (Post 830201) 83/09/14 NOVAK: T M Assistant Director for Licensing 24pp 22479 188 24X Fiche 50-400.84/02/07.8403050064
- --8309240018 Forwards SER supporting geology & seismology at facility KNIGHT.J P Assistant Director for Comp & Structures Engineering (Post 830201) 83/09/08 NOVAK.T M Assistant Director for Licensing 44pp 22478 264 24X Fiche 50-400.84/02/07, 8403050064
- --8309260421 Forwards structural engineering BER sections based on review of FBAR through Amend 9. Three open & one confirmatory items remain Resolution of open/confirmatory items will be addressed in subsequent BBER KNIGHT.JP Assistant Director for Comp & Structures Engineering (Post 830201) 83/09/15 NOVAK.T M Assistant Director for Licensing 16pp 22479 212 24X Fiche 50-400,84/02/07,8402050064
- ---8309260482 Forwards Auxiliary Sys Branch SER input based on review of all amends to FSAR up to Amend 9 & applicants 830418.0603, 30.0705.15 & 0812 responses Bummary of unresolved issues to be used as basis for meeting w/applicant also encl RUBENBTEIN.L S Assistant Director for Core & Flant Systems 83/09/14 NOVAK.T M Assistant Director for Licensing 281pp 22498 308 24X Fiche 50-400,84/02/07.8403050064
- --8309290412 Forwards Effluent Treatment Sys Section input to SER reflecting changes in status of open items based on 830824 meeting HULLER, D.R. Assistant Director for Radiation Protection 83/09/14. NDVAK, T.M. Assistant Director for Operating Reactors 60pp 22500 190 24X Fiche 50-400,84/02/07.8403050064
- -~8309290474 Forwards SER on plant personnel training Util training programs for licensed reactor operators acceptable Util inadequately addressed training of shift technical advisor (STA) when STA absent from STA duties RUSSELL, W Division of Human Factors Safety 83/09/21. NOVAK, 1 Assistant Director for Licensing 21pp 22499 228 24X Fiche 50-400,84/02/07,8403050064

- --8310130378 Forwards branch SER input re status of unresolved issues in response to ALAB-444 decision issues A-45 & A-47 listed as confirmatory items rather than open items W/o encis KNIEL.K Generic Issues Branch 83/10/04 KNIGHTON, 6 Licensing Branch 3 26pp 22499 249 24X Fiche 50-400.84/02/07.8403050064
- --B310170099 Forwards Chemical Engineering Branch proposed license condition re TMI Item II B 3. "Post-Accident Sampling Sys "Contents of draft SER should be used for SER JONNBTON, W V Assistant Director for Matls. Chem & Environ Technology (Post B30201) B3/10/06 NOVAK, T M Assistant Director for Licensing 3pp 22499 279 24X Fiche 50-400, B4/02/07, B403050064
- --B310310445 Forwards results of review of Sections 5 2 2.5 4 7.6 3 % 15 through Amend 10 of FSAR Open issues which will be summarized in later SER suppl listed HUUSTON.R W Assistant Director for Reactor Safety R3/10/07 NOVAX.T M Assistant Director for Licensing 49pp 22479 282 2478 Fiche 50-400.84/02/07.8403050064
- --83ii100049 Informs that applicant is to submit calculation of ultimate strength capacity of containment bldg under internal pressure as resolution of SER outstanding confirmatory structural item Marked-up SER input encl
 LEAR. O Structural & Geotechnical Engineering Branch 83/10/28 KNIGHTON, 6 Licensing Branch 3 3pp 22500 024 24X Fiche 50-400,84/02/07,8403050044
- --B311110263 Informs of closeout of listed sections of 830714 SER based on new info Updated sections encl Closeout of addl open items.including NUREG-0612 info, wall take place as acceptable info made available RUBENSTEIN.L S Assistant Director for Core & Plant Systems B3/10/28 NOVAK.T M Assistant Director for Licensing 49pp 22499 337 24X Fiche 50-400.84/02/07.8403050064
- --B311140004 Advises that, due to need to coordinate effort w/Auxiliary Sys Branch: revised SER to be submitted on 831127 will still contain listed fire protection open items JOHNSTON.N V Assistant Director for Matls, Chem & Environ Technology (Post B30201) B3/11/03 NOVAK, T Assistant Director for Licensing 2pp 22500 030 24X Fiche 50-400.84/02/07, 8403050064
- --8311160283 Forwards revised SER input on confirmatory item re ultimate strength capacity of concrete containment bldg Item resolved
 LEAR. G Structural & Geotechnical Engineering Branch 83/11/14
 KNIGHTON.O Licensing Branch 3 3pp 22500 047 24X
 Fiche 50-400.84/02/07.8403050064
- ~-B311160367 Informs that draft SER Section 17 acceptable except in area of items subj to 10CFR50. App B.OA program during operations phase Info re current status & acceptability of GA program encl
 PARTLOW, J O Division of GA, Safeguards & Inspection Programs (Post B30103) 83/11/09 YOUNGBLOOD, B J Licensing Branch 1 3pp 22500 027 24% Fichs 50-400, 84/02/07, 8403030064
- --8311290301 Forwards revised Hydrologic Engineering input to SER New Tech Spec requirement developed re watertight doors for safety-related bldgs
 JOHNSTON, W V Division of Engineering Technology 83/11/10
 NOVAY, T M Assistant Director for Licensing 15pp 22500 032
 24X Fiche 50-400,84/02/07,8403050064
- --8311270352 Updates SER re stability of retaining wall west of fuel handling bldg Based on applicant 830919 submittals, stability cannot be assured due to lack of listed info Final SER update enci

 LEAR, G E Hydrologic & Geotechnical Engineering Branch 83/11/18

 KNIGHTON. G Licensing Branch 3 5pp 22501 049 24X

 Fiche 50-400, 84/02/07.8403050064
- --B3120B01BB Forwards effluent treatment sys section input to SER Oper items include method for determining releases of mobile gases from mechanical vacuum pumps & radioactivity monitor on discharge from sec water sys.

 MULLER:D R Assistant Director for Radiation Protection 83/11/1B NUQAK:T M Assistant Director for Licensing 51pp 22500 139 24% Fiche 50-400,84/02/07.8403050064
- --8312120002 Lists closed out open items in SER forwarded on 830914 & sections w/remaining open items
 RUBENSTEIN.L S Assistant Director for Core & Plant Systems
 83/11/17 NOVAK.T M Division of Licensing 88pp 22500 050
 24X Fiche 50-400.84/02/07.8403050064

- --B312120445 Forwards input to SER, consisting of emergency plan evaluation rept & responses to NUREG-0737. Items III A 1 1.III A 1 2 & III A 2 re emergency preparedness MATTHEWS, D B Division of Emergency Preparedness & Engineering Response (Past B30103) B3/11/30 KNIGHTON, O Licensing Branch 3 36pp 22501 038 24X Fiche 50-400,84/02/07.8403050064
- --8312140429 Submits review of draft SER response to Open Item 47 on RCS vents Proposed design conforms w/criteria outlined in NUREO-0737 clarification pertaining to electrical power supplies to vent valves SRINIVASAN.M Power Systems Branch 83/11/23 SHERON, B Reactor Systems Branch 2pp 22501 036 24X Fiche 50-400.84/02/07, 8403030064
- --B312230278 Forwards revised SEER re fire protection Listed items remain open JOHNSTON,W V Assistant Director for Matls, Chem & Environ Technology (Post 830201) 83/12/14 NOVAK,T Assistant Director for Licensing 12pp 22501 094 24X Fiche 50-400,84/02/07, R403030064
- F Security, medical, emergency & fire protection plans
- 8403160283 Advises of 840316 meeting in Region II ofc to discuss App R requirements & results of recent App R insps Attendance should be limited to six util employees LEWIS:R C Division of Project & Resident Programs 84/03/02 UTLEV.E E Carolina Power & Light Co ip 22660 109 24X Fiche: 50-000, 84/03/02, 8403160283
- G Adjudicatory correspondence
- B402230207 Further response to FDIA request for documents re const flaws at facility Forwards documents listed in App A Documents also being placed in PDR & LPDR Review continuing FELTON, J M Division of Rules and Records 83/12/02 VADEN, T News & Observer/Raleigh Times, Raleigh, NC 3pp 22378 279 24X Fiche 50-400.83/12/02.8402230207
- --Bi04210125 Discusses implications of Ofc of Inspector & Auditor 781012 interview w/facility ASLB Ofc of Inspector & Auditor attempted to probe thought processes of & require justification from Board re action taken in adjudication YORE, J R Atomic Safety and Licensing Board Panel 78/10/19 HENDRIE, J M Commissioners 3pp 22378 302 24x Fiche 30-400, 83/12/02, 8402230207
- --B402230237 Discusses investigation by Ofc of Inspector & Auditor (01A) re facility proceeding ABLAB unwilling to be interrogated by OIA Hany questions in OIA interrogation of members of ABLB manifestly improper ROSENTHALLA 5 Atomic Safety and Licensing Appeal Panel 78/10/20 HENDRIE Commissioners 2pp 22378 306 24X Fiche 50-400,83/12/02,8402230207
- 8402070054 Forwards corrected copy of Page 10 of NRC B40130 response in opposition to Eddlemen proffered Contentions 169,170. 171 & 172 re safety parameter display sys MOORE. J E Hearing Branch 1 84/01/31 KELLEY, J L , CARPENTER, J H , BRIGHT, G O Atomic Safety and Licensing Board Panel 1p 22102 361 24X Fiche 50-400,84/01/31,8402070054
- --8402070037 Corrected Page 10 of response opposing Eddleman proffered Contentions 169,170,171 & 172 re safety parameter display sys

 # Hearing Branch 1 84/01/30 Atomic Safety and Licensing Board Panel ip 22102 362 24X Fiche 50-400,84/01/31,
- B40229008i Amended Certificate of Svc for applicant B40224 motion for reconsideration or clarification of ASLB memorandum & order on health effects contentions Certificate of Svc encl BAXTER, T A Carolina Power & Light Co
- 8403020182 Motion for summary disposition of Joint Intervenor Contention V re continuous air monitors & portable air samples No genuine issue of matl fact exists & applicant entitled to favorable decision Related correspondence ANDERSON, P H Carolina Power & Light Co ANDERSON, P H Shaw, Pittmen, Potts & Troubridge B4/02/27 Atomic Safety and Licensing Board Panel 14pp. 22440 193 24X Fiche 50-400,84/02/27,8403020182
- --B403020188 Statement of mati facts as to which there is no genuine issue to be heard on Joint Contention V Related correspondence ANDERSON.P H. Carolina Power & Light Co ANDERSON.P H. Shaw, Pittman, Potts & Trowbridge 84/02/27 Atomic Safety and Licensing Board Panel 3pp 22440 207 24X Fiche 50-400, B4/02/27, 8403020182

- --8403020192 Affidavit of WH Wilkle in support of applicant motion for summary disposition of Joint Intervenors Contention V Certificate of Svc encl Related correspondence WILMIE.W H Carolina Power & Light Co 84/02/24 19pp 22440 210 24X Fiche 50-400,84/02/27,8403020182
- 8403010263 Response opposing W Eddleman motion to admit Contention 5842d) on financial qualifications of co-applicants ASLB has no basis or authority to reconsider original ruling on contention & motion must be denied Certificate of Svc encl O'NEILL,J H Carolina Power & Light Co O'NEILL,J H Shaw. Pittman, Potts & Trowbridge 84/02/28 Atomic Safety and Licensing Board Panel 7pp 22432 258 24X Fiche SO-400.84/02/28.
- 8403070051 Forwards emergency response plan in support of facility Plan encompasses state plan to plans of Chatham, Harnett, Lee, to Wake Counties W/o encl Related correspondence HOLLAR, D.E. Carolina Power & Light Co. 84/02/28 KELLEY, J.L., BRIOHT, G.O., CARPENTER, J.H. Atomic Safety and Licensing Board Panel 2pp. 22541 276. 24X Fiche 50~400,84/02/28,8403070051
- B403070055 Motion for summary disposition of Eddleman Contention 15AA re capacity factor No genuine issue of matl fact exists Related correspondence HOLLAR.D E Carolina Power & Light Co 84/02/28 Atomic Safety and Licensing Board Panel 15pp 22541 123 24x Fiche 50-400,84/02/28,8403070055
- --8403070058 Statement of matl facts as to which there is no genuine issue
 HOLLAR,D E Carolina Power & Light Co 84/02/28 Atomic Safety
 and Licensing Board Panel 3pp 22541 138 24X
 Fiche 50-400,84/02/28,8403070055
- --B403070059 Affidavit of RH Koppe in support of applicant motion for summary disposition of Eddleman Contention 15AA Certificate of SVc encl Related correspondence KDDPE.R H Carolina Power & Light Co 84/02/27 24pp 22541
- B403140102 Policy statement on environ qualification of safety-related electrical equipment Commission will conduct notice & comment rulemaking proceeding to delete formally B20630 compliance deadline Certificate of Svc encl CHILK. B. J. Office of the Secretary of the Commission B4/03/01 37pp. 22624 164 24X Fiche 50-400,84/03/01,8403140102
- 8403070134 Amend to 840113 motion for protective order preventing public disclosure of employee info sought by discovery request of W Eddleman Order issued by ABLB appropriate & necessary, Certificate of Svc encl Related correspondence BAXTER, T A Carolina Power & Light Co BAXTER, T A Shaw, Pittman, Potts & Troubridge 84/03/02 Atomic Bafety and Licensing Board Panel 11pp 22538 254 24X Fiche 50-400,84/03/02,8403070134
- B403070225 Requests questions re Contention 41 requiring discovery responses be filed before 840315 Second round discovery will be given if protective order issue not resolved before 840315 W/Certificate of Svc Related correspondence BAXTER. TA Shaw. Pittman. Potts & Troubridge BAXTER. TA Carolina Power & Light Co 84/03/02 EDDLEMAN.W Eddleman. W 4pp 22541 300 24X Fiche 50-400.84/03/02.8403070225
- B403140159 Response opposing W Eddleman B40213 motion for admission of Contention 58 (20) re financial qualifications Eddleman argument inaccurate W/NRC B40227 statement of policy MODRE. J E Hearing Branch 2 B4/03/05 Atomic Safety and Licensing Board Panel 5pp 22624 001 24X Fiche 50-400, B4/03/05, 84/03/40159
- --8403140163 Response in support of applicant 840207 motion for summary disposition of Eddleman Contention 83/848 on grounds that there is no genuine issue of matl fact to be litigated MODRE, J E Hearing Branch 2 84/03/05 Atomic Safety and Licensing Board Panel 10pp 22624 006 24X Fiche 50-400, 84/03/05, 8403140159
- --8403140168 Affidavit of JC Lehr supporting NRC response to applicant motion for summary disposition of Eddleman Contention 83/848 Applicant assessment consistent w/NRC conclusion in FES. W/Certificate of 8vc LEHR. J C Environmental & Hydrologic Engineering Branch 84/03/05 11pp 22624 016 24X Fiche 50-400,84/03/05,8403140159
- 8403120002 Supplemental ensuer to applicant interrogatories & requests for production of documents on Joint Contentions I & VII Certificate of Syc encl Related correspondence PAYNE:M T Kudzu Alliance PAYNE:M T Edelstein & Payne PAYNE:M T. Joint Intervenors Shearon Harris 84/03/07 4pp 22589: 278 24X Fiche 50-400,84/03/07,8403120002

- B403130136 Motion for summary disposition of Joint Intervenor Contention VI re monitoring sys No genuine issue of matlifact exists & applicant entitled to favorable declision Related correspondence ANDERSON.P H Carolina Power & Light Co ANDERSON.P H Shaw. Pittman. Potts & Trowbridge B4/03/09 Atomic Safety and Licensing Board Panel 18pp 22599 003 24X Fiche 50-400.84/03/09.8403130156
- --0403130164 Affidavit of WH Wilkie & RL Shearin in support of applicant motion for summery disposition of Joint Intervenor Contention VI Certificate of Svc encl HILLIE, W H., SHEARIN, R V Carolina Power & Light Co 84/03/08 122pp 22599 021 24X Fiche 50-400,84/03/09,8403130156
- B403130447 Response to W Eddleman B40307 motion to declare util 840228 motion untimely Eddleman motion frivolous, insulting & unfounded Related correspondence O'NEILL, J H Garolina Power & Light Co O'NEILL, J H Shaw, Pittman, Potts & Trowbridge 84/03/09 Atomic Safety and Licensing Board Panel 5pp 22613 182 24X Fiche 50-400, B4/03/09, B403130447
- --B403130457 Response opposing W Eddleman 840307 motion to allow filing of affidavit of JO Blackburn Good cause undemonstrated Cartificate of Eyc encil D'MEILL, J H Carolina Power & Light Co Pittman, Potts & Trowbridge 84/03/09 Atomic Safety and Licensing Board Panel 6pp 22613 187 24X Fiche 50-400, 84/03/09.8403130447
- B403160018 Memorializes 840313 telcon extending time for discovery requests on safety contentions & for response to applicant motion for summary disposition Certificate of Svc encl BAXTER, T A Shaw, Pittman, Potts & Troubridge BAXTER, T A Carelina Power & Light Co 84/03/13 EDDLEMAN, W Eddleman, W 4pp 22653 360 24X Fiche 50-400-84/03/13,8403160018
- 8403190137 Forwards applicant & NRC joint motion to withdraw Contentions 2,3 & 6 re security plan Agreement exchanged resolving issues
 FLYNN,8 F Carolina Power & Light Co B4/03/14 KELLEY, J L ,
 BRIGHT,0 D , CARPENTER.J H Atomic Safety and Licensing Board Panel 2pp. 22666 310 24% Fiche 50-400,88/03/14,8803190137
- --8403170141 Joint motion to withdraw security plan Contentions 2.3 % 6 Certificate of Svc encl RUNKLE.J D Joint Intervenors - Shearon Harris FLYNN, S F Careline Power & Light Co BARTH.C A Hearing Branch 1 84/03/14 Atomic Safety and Licensing Board Panel 3pp 22666 312 24X Fiche 50-400,84/03/14,8403170137
- B403200030 Supplemental responses to W Eddleman general interrogatories & interrogatories on Contentions 41 & 65 Certificate of Svc encl. Related correspondence
 BAXTER.T A Carolina Power & Light Co BAXTER.T A Shaw, Pittman, Potts & Troubridge B4/03/14 Eddleman, W 7pp 22683 345 24X
 Fichs 50-400.84/03/14,8403200030
- 8403190025 Memorandum & order reaffirming rulings on response to 840127 order re health effects
 BRIGHT.G O. CARPENTER.J H. KELLEY.J L. Atomic Safety and Licensing Board Panel B4/03/15 Office of the Executive Legal Director 20pp 22666 085 24X Fiche 50-400.84/03/15.8403190025
- 8403190033 Interrogatory to Joint Intervenors re Joint Contention VII Response in writing required by 840403 BARTH, C A Hearing Branch i 84/03/15 Joint Intervenors Shearon Harris ip 22666 188 24X Fichs 50-400,84/03/15,
- --B40319005B Interrogatories to W Eddleman re Eddleman Contentions 11.45. 67 & iió Response in writing required by 840403 Certificate of Svc encl BARTH,C A Hearing Branch 1 84/03/15 EDDLEMAN,W Eddleman, W Spp 22666 189 24X Fiche 50-400.84/03/15.8403190053
- 8403200054 Interrogatories to applicant on admitted security contention Encl withheld (ref 10CFR73 21) W/Certificate of Svc Related correspondence RVNKLE, J Joint Intervenors Shearon Harris 84/03/15 Carolina Power & Light Co 3pp 22698 273 24X Fiche 50-400, 84/03/15, 8403200054
- B403200117 Interrogatories & request for production of documents on W Eddleman Contention 132C(II) second set Certificate of Eve entl Related correspondence CARROW.H Carolina Power & Light Co 84/03/15 Eddleman, W Bpp 22685

- |403200135 Notice of ER Bleachar & JR Haples depositions on 840329 in Raleigh.NC Certificate of Svc encl Related correspondence CARROW.H Carolina Power & Light Co CARROW.H Shaw, Pittman, Potts & Trowbridge 84/03/15 3pp 22699 161 24X Fiche 50-400.84/03/15.8403200135
- 1403210120 Informs that part of transcript of 840308 telcon reidentification of persons in room at time of call missing BARTH.C A Hearing Branch (84/03/16 KELLEY.J L , BRIGHT.O , CARPENTER.J H Atomic Safety and Liconsing Board Panel. 1p 22707 179 24X Fiche 50-400,84/03/16,8403210120
- 403210051 Order approving joint motion to withdraw security plan Contentions 2.3 & 6 Cooperation commended KELLEY.J L. CARPENTER.J H. BRIGHT.O O. Atomic Safety and Licensing Board Panel. 84/03/19 Office of the Esecutive Legal Director. 2pp 22704 342 24X Fiche 50-400/84/03/19,8403210051
- 403220223 Motion to quash applicant notice to take deposition of Bleacher & Maples Unlikely applicants can meet even threshhold showing of good cause Certificate of Svc and Related correspondence RUNKLE, J. Joint Intervenors Sheeron Harris BSD 045 84/03/19. Atomic Bafety and Licensing Board Panel 4pp 22719 003 24X Fiche 50~400.84/03/19.8403220223
- 403220261 Interrogatories & request for production of documents to Joint Intervenors (seventh set) Certificate of Svc enci Related correspondence 0'NEILL, J H Carolina Power & Light Co O'NEILL, J H Shaw, Pittman, Potts & Trowbridge. DSB 058 84/03/19 Joint Intervenors Shearon Harris 21pp 22719 110 24X Fiche 50-400,84/03/19,8403220261
- 103260327 Interrogatories & request for production of documents re Eddleman Contentions 9 & 11 (second set) Certificate of Syc enci Related correspondence SVC ent; Related correspondence SWIGER, M A Carolina Power & Light Co SWIGER, M A Shaw, Pittman, Potts & Troubridge DBB 104 84/03/23 Eddleman, W 14pp 22760.143 24% Fiche 50-400.84/03/23,8403260327
- O3240328 Responds to 840317 & 17 ltrs re estension to file discovery requests, welder info confidentiality & interrogatory answers Svc list encl Related correspondance.

 BAXTER.T A Shaw. Pittman. Potts & Troubridge BAXTER.T. A Carolina Power & Light Co DS9 103 84/03/23 EDDLEHAN. W Eddleman. W 4pp 22760 157 24X Fiche 50-400.84/03/23.8403260328
- O3260348 Responses to general interrogatories & interrogatories on Contention 65 (seventh set) Related correspondence BAXTER: T A Carolina Power & Light Co BAXTER: T A Shaw, Pittman, Potts & Troubridge DSB 102 84/O3/23 Eddieman, H 47pp. 22760 190 24X Fiche 50-400.84/O3/23.8403260348
- 8403250354 Response to request for production of documents NOSCOUST RESPONSE TO REQUEST FOR PRODUCTION OF BOCUMENTS (Contention 65) Certificate of Svc encl BAXTER.T A Carolina Power & Light Co BAXTER.T A Sh Pittman. Potts & Troubridge 84/03/23 Eddleman, W 22760 237 24% Fiche 50-400,84/03/23:8403280348
- 03270319 Response opposing W Eddleman 840307 motion to allow filing P affidavit of JO Blackburn Affidavit is untimely suppl to settion re need for power & alternative energy sources
- Pertificate of Svc encl 100RE.J E Hearing Branch 1 DSB 133 84/03/23 5pp 22789-023 4X Fiche 50-400,84/03/23,8403270319
- 13270321 Clarification of staff response in support of applicant action for summary disposition of Joint Intervenors Contention IV re TLDs
 1ARTH.C A Hearing Branch i DSB 130 84/03/23 Atomic Bafe nd Licensing Board Panel 3pp 22789.020 24X
 Tiche: 50-400.84/03/23,8403270321 Atomic Rafetu
- 13270333 Response in support of applicant 840227 motion for summary isposition of Joint Intervenors Contention V re callbr of ir munitors Related correspondence
 ARTH.C A Hearing Branch 1 DSB 127 84/03/23 Atomic Safety and Licensing Board Panel 2pp. 22789 006 24X iche 50-400.84/03/23,8403270333
- |403270338| Affidavit of 8 Block in support of summary disposition of Joint Contention V Certificate of Svc encl BLOCK. 8 Division of Systems Integration (post 811005) 84/03/15 8pp 22789 008 24X Fichs 50-400.84/03/23,8403270333.
- 3270327 Advises that term job experience, used in 840314 discovery esponses, includes only welding experience Related esponses, includes only welding experience releases orrespondence
 AXTER, T.A. Shaw, Pittman, Potts & Trowbridge BAXTER, T.A.
 arcline Power & Light Co. DSB 144 84/03/26 EDDLEMAN, H.
 ddleman, W. 3pp 22787 016 24X Fishe 50-400,84/03/26,8403270327

- Advisory Committee on Reactor Bafesuards reports & correspondence
- 8403140302 Discusses seismology (saues in OL review Extremely conservative values established for OBE & SSE, Plant site is as nearly assismic as any site in eastern US.

 MAXWELL, J C. Maxwell, J C MAXWELL, J C ACRS Advisory Committee on Reactor Safeguards 84/01/05, KERR, W ACRS Advisory Committee on Reactor Safeguards 1p. 22635-317. 24X Fiche 50-400,84/01/05,
- B401300121 Summarizes ACRS 285th meating on 840112-14 re review of OL application: control room design & tube degradation Investigation of allegations re GA requested EBERBOLE, J C ACRS Advisory Committee on Reactor Safeguards 84/01/16 PALLADIND, N J. Commissioners 3pp. 22044 023 24X Fiche 50-400, 84/01/16,8401300121
- Q Inspection reports, IE Bulletins & correspondence
- 8403070179 Ack receipt of 840208 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-400/83-36, Implementation of corrective actions will be examined during Figure 1 insps VERRELLI,D M Division of Project & Resident Programs B4//
 VERRELLI,D M Division of Project & Resident Programs B4//
 VTLEY,E Carolina Power & Light Co ip, 22347-276, 24X
 Fiche 50-400,84/02/22,8403070179.
- ---8403070193 Forwards IE Insp Repts 50-400/83-36 & 50-401/83-36 on 831120 & 1220 & notice of violation VERRELLI,D M. Division of Project & Resident Programs 84/01/10, UTLEY,E E Carolina Power & Light Co 2pp 22547-279 24X Fiche 50-400,84/02/22,8403070179
- --8403070199 IE Insp Repts 50-400/83-36 & 50-401/83-36 on 831120-1220 Violation noted: failure to protect squipment from rainwater entering reactor auxiliary bldg from roof MAXHELL.0 F , PREVATTE, R. L. Region 2, Office of Director BEMIS.P R Division of Project & Resident Programs 84/01/09. 9pp 22547 282 24% Fiche 50-400/84/02/22,8403070179.
- 8403070074 Ack receipt of 840118 & 27 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-400/83-35 VERRELLI,D M Division of Project & Resident Programs 84/02/23, UTLEY,E E. Carolina Power & Light Co. ip. 22545 348, 24X Fiche 50-400,84/02/23,8403070094.
- --B403070100 Forwards IE Insp Repts 50-400/83-35 & 50-401/83-35 on 831129-1202 & notice of violation VERRELLI, D M Division of Project & Resident Programs 83/12/20, UTLEY, E E Caroline Power & Light Co. 2pp 22545,353. 24X Fiche: 50-400,84/02/23,8403070094.
- --8403070105 IE Insp Repts 50-400/83-35 & 50-401/83-35 on B31129-1202 Violation noted failure of as-built drawings to reflect violation noted railure of amounts to reflect actual piping configuration
 KLEINSORGE, P Region 2. Office of Director BLAKE, J J.
 Division of Engineering & Operational Programs. 83/12/13. 9pp
 22945-356 24% Fiche 50-400.84/02/23.8403070094
- S Reportable occurrences. LERs & related correspondence
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines. Gimpel NPS-4 T&T valve, to close Encl ltr dtd 840203 sent to listed utils GE notified of affected units in BMR THEROUX, R R Terry Corp. 84/02/22 WOODRUFF, R W. Director's Office, Office of Inspection and Enforcement 6pp. 22706:327 24x Fiche: 50-000,84/02/22,8403210032
- 8403010207 Forwards "Investigation of Types AF & AE Piston Skirts," per Transamerica Delaval, inc Owners Group program commitments. Rept evaluates cracks in AF piston skirts in Shoreham & Grand Gulf Nuclear Power Stations MUSELER, W J TDI (Transamerica Delaval, Inc.) Owners Group 84/02/27 DENTON, HR Office of Nuclear Reactor Regulation, Director 3pp 22434,090 24X Fiche 50-000,84/02/27,8403010207.
- 8403010218 Forwards task descriptions for 16 known problems re Transamerica Delaval, Inc. emergency diesel generators, MUSELER, W. J. TDI (Transamerica Delaval, Inc.) Owners Group 84/02/28 DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 42pp. 22435, 177. 24X Fiche: 50-000, 84/02/28, 8403010218
- 8403140048 Forwards "Grand Gulf Component Tracking Sys," "Shoreham Component Tracking Sys" & "Transamerica Delaval Inc Diesel Generators Owners Group Program Plan," to resolve Concerns W/emergency dissel generators

 HUSELER, W J. Long Island Lighting Co. 84/03/02 DENTON, H. R.

 Office of Nuclear Reactor Regulation, Director. 2pp 22626:062

 24X Ficha 30-000, 84/03/02, 8403140048

- --8403140095 "Transamerica Delaval, Inc Diesel Generators Owners Group
- 8402090039 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delaval, Inc (TDI) Owners Group Distribution list enci.
 EIBENHUT, D. G. Division of Licensing 84/03/12 PALLADING
 Commissioners 5pp 22708 001 24X Fiche 50-000, 84/03/12. 8402070037
- --8403060336 Forwards summary of 840210 meeting w/Transamerica Delaval. Inc Owners Group in Bethesda,MD re problems w/emergency diesel generators
 CARUSO,R. Licensing Branch 2 84/02/27 O'REILLY, J P NRC - No Detailed Affiliation Given App 22708 006 24X
 Fiche: 50-000, 84/03/12, 8402090039
- --8403060554 Trenscript of 840210 meeting w/Transamerica Delaval, Inc Owners Group in Bethesda, MD re problems w/emergency diesel generators * NRC No Detailed Affiliation Given 84/02/10 147pp 67201,008 24% Fiche 50-000,84/03/12,8402090039
- --8403070409 Summary of 840216 meeting w/Transamerica Delayal, Inc Owners Group in Wading River, NY re program plan to establish reliability of dissel generators Agenda, meeting transcript & attendance list encl
 MILLER, M A Licensing Branch 4 84/02/27 Licensing Branch 4
 8pp. 22708 161 24X Fiche 50-000,84/03/12,8402090039
- --8403070423 Transcript of 840216 conference in Wading River, NY re Transamerica Delaval, Inc diesel generators Pp 1-82 * Commissioners 84/02/16. 84pp 22708 169 24X Fiche, 30-000, 84/03/12. 8402090037.
- B403140050 Forwards "Design Review of Connecting Rod Bearing Shells for Transamerica Delaval Enterprise Engines" for Shoreham & Grand Gulf diesel generators.

 MUSELER, W. J. Long Island Lighting Co 84/03/12 DENTON, H R. Office of Nuclear Reactor Regulation, Director 2pp 22632,074 24X Fiche: 50-000,84/03/12,8403140050.
- B403150133 Forwards "Transamerica Delaval, Inc Diesel Generator Rocker Arm Capscrew Btress Analysis Rept " Capscrew design adequate for applicable angines & svc conditions MUSELER, W. J. TDI (Transamerica Delaval, Inc.) Cuners Group B4/03/13, DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp 22639-270 24X Fiche 50~000, 84/03/13, 8403150133
- 8403200222 Responds to 840214 Requests for Info 1 & 2 re R-4 series engines List indicating engine number, model & svc number, customer name & address, rating, data shipped & data started MATHEMB.C S. Transamerica Delaval, Inc. 84/03/16 EISENHUT, D G Division of Licensing 20pp. 22691;179 24X Fiche 50-000,84/03/16, 8403200222
- 8403270132 Forwards "Emergency Dissel Generator Air Start Valva Capacrew Dimension & Stress Analysis," prepared by S&W for Transamerica Delaval, Inc. (TDI) Dissel Generator Owners MUSELER, W. J. TDI (Transamerica Delaval, Inc.) Owners Group, 84/03/23, DENTON, H.R. Office of Nuclear Reactor Regulation, Director, 2pp. 22774,001, 24X Fiche 50-000,84/03/23,8403270132
- 8403270134 Requests meeting on 840418 to discuss short-term & long-term corrective actions & investigations re Transamerica Delayal diesel generators List of suggested meeting topics
- MCGAUGHY, J. P. TDI (Transamerica Delaval, Inc.) Dwnert Group 84/03/23 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 4pp 22769:133, 24X Fiche 50-000,84/03/23,8403270134
- T. Hearing transcripts on non-antitrust matters
- 8403120121 Transcript of 840308 telephone conference in Bethesda, MD
 - Pp 751-807 * Commissioners 84/03/08 58 Fiche: 50-400, 84/03/08, 8403120121 58pp 22586:119 24X
- 8402090039 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delayal, Inc (TDI) Guners Group Distribution list encl EIBENHUT, D G. Division of Licensing 84/03/12 PALLADIND Commissioners, 3pp 22708.001 24X Fiche: 30-000,84/03/12,8402070037

- --8403060536 Forwards summary of 840210 meeting w/Transamerica Delaval.
 Inc Owners Group in Bethesda.MD re problems w/emergency
 diesel generators
 CARUSO,R Licensing Branch 2 84/02/27 O'REILLY, J.P. NRC No
 Detailed Affiliation Given 6pp 22708 006 24X
 Fiche 80-000,84/03/12,8402090039
- --B403060554 Transcript of B40210 meeting w/Transamerics Delaval. Inc Qwners Group in Bethesda.MD re problems w/emergency diesel generators * NRC No Detailed Affiliation Qiven B4/02/10 147pp 67201 008 24% Fiche 50-000.84/03/12.8402090039
- --8403070409 Summary of B40216 meeting w/Transamerica Delaval, Inc Owners Group in Wading River, NY re program plan to establish reliability of diesel generators Agenda, meeting transcript & attendance list enci MILLER, M.A. Licensing Branch 4 84/02/27 Licensi Bpp. 22708 161. 24% Fiche 50-000,84/03/12,8402090039 Licensing Branch 4
- --8403070423 Transcript of 840216 conference in Wading River, NY re Transamerica Delaval, Inc diesel generators Pp 1-82 * Commissioners 84/02/16 84pp 22708 169 2: Fiche 50-000,84/03/12,8402090039
- DOCKET 50-402 SHEARON HARRIS NUCLEAR POWER PLANT: UNIT 3 A Application/construction stage documents & correspondence
- 8402230207 Further response to FOIA request for documents re const flaws at facility. Forwards documents listed in App A Documents also being placed in PDR & LPDR Review continuing FELTON, J M Division of Rules and Records 83/12/02 VADEN, T News & Observer/Raleigh Times, Raleigh, NC 3pp 22378 279 24 Fiche 50-400.83/12/02,8402230207
- --B402230226 Forwards Ofc of Inspector & Auditor "Inquiry into Alleged Omission of Line Inspector Views from CP Hearing " No further distribution should be made outside of ofc Rept under Cammission review GOSSICK, L V Office of the Executive Director for Operations 79/11/19 DENTON Office of Nuclear Reactor Regulation, Director ip. 22378 305 24X Fiche 50-400,83/12/02.8402230207
- --8402230239 Forwards Apps A.B.C & D to be included w/questions for Panel III re facility testimony Related info encl MURPHY, C E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 78/11/16 REIS, E. J. Office of the Executive Legal Director. Sipp 22378 308 24X Fiche 50-400, 83/12/02, 8402230207
- --8402230231 Matl maint requirements for Procedure AP-XIII-07, "In-Storage Insp & Maint " Equipment purchase order form ** Carolina Power & Light Co 83/12/02 7pp 22379 040 24X Fiche 50-400:83/12/02:8402230207.
- E NRC Bafety Evaluation Report (SER), supple & correspondence
- 8205270420 Forwards request for add1 info re fire protection program needed to complete review Info needed by 821102
 BENARDYA, V Chemical Engineering Branch 82/05/17 MIRAQLIA,F Licensing Branch 3 7pp 22497 015 24X Fiche 50-402,84/02/07,8403050064.
- O Adjudicatory correspondence
- 8402230207 Further response to FDIA request for documents me const flaws at facility. Forwards documents listed in App A Documents also being placed in PDR & LPDR Review continuing FELTON, J M Division of Rules and Records 83/12/02 VADEN. T News & Observer/Releigh Times, Raleigh, NC 3pp 22378 299 24 Fiche 50~400.83/12/02.8402230207
- --Bi04210125 Discusses implications of Ofc of Inspector & Auditor 781012 interview w/facility ABLB Ofc of Inspector & Auditor attempted to probe thought processes of & require justification from Board re action taken in adjudication. YORE.J.R. Atomic Safety and Licensing Board Panel 78/10/19 HENDRIE.J M Commissioners 3pp 22378 302. 24X Fiche 50-400.83/12/02.8402230207.
- --8402230237 Discusses investigation by Ofc of Inspector & Auditor (OIA) re facility proceeding ABLAB unwilling to be interrogated by DIA Many questions in OIA interrogation of members of ABLB manifestly improper ROBENTHAL, A. B. Atomic Safety and Licensing Appeal Panel 78/16/20 HENDRIE Commissioners 2pp 22378 306 24% Fiche 50-400, 83/12/02, 8402230207

- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8401300121 Summarizes ACRS 285th meeting on 840112-14 re review of OL application, control room design & tube degradation investigation of allegations re GA requested EBERSQLE.J C ACRS Advisory Committee on Reactur Safeguards. 84/01/16 PALLADINO,N J Commissioners 3pp 22044 023 24X Fiche 30-400,84/01/16.8401300121.
- DOCKET 50-403 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 4
- A Application/construction stage documents & correspondence
- 8402230207 Further response to FOIA request for documents re const flaws at facility Forwards documents listed in App A Documents also being placed in FOR & LPDR Review continuing FELTON, J M Division of Rules and Records 83/12/02 VADEN, T News & Observer/Releagh Times, Raleigh, NC 3pp 22378 297 24 Fiche 50-400.83/12/02.8402230207
- --8402230239 Forwards Apps A,B,C & D to be included w/questions for Panel III re facility testimony Related info encl.

 NURPHY,C E Région 2. Atlanta. Reactor Construction & Engineering Support Branch 76/11/16 REIB.E J Office of the Executive Legal Director Bipp 22378 308 24X Fiche. 50-400, 83/12/02, 8402230207
- --8402230251 Math maint requirements for Procedure AP-XIII-07,
 "In-Storage Insp & Maint " Equipment purchase order form
 encl .

 * Carolina Power & Light Co 83/12/02 9pp 22379 040 24X
 Fichs 50-400.83/12/02,8402230207
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8205270420 Forwards request for add1 info re first protection program needed to complete review Info needed by 821102
 BENAROYA-V. Chemical Engineering Branch 82/05/17 MIRAGLIA,F
 Licensing Branch 3 7pp 22497-015 24X Fiche 50-402,84/02/07,
 8403050064
- G Adjudicatory correspondence
- 8402230207 Further response to FOIA request for documents re const flaws at facility Forwards documents listed in App A. Documents also being placed in PDR & LPDR Review continuing FELTON. J M Division of Rules and Records 83/12/02 VADEN. T News & Observer/Raleigh Times, Raleigh, NC 3pp 22378 299, 24x Fiche 50-400.63/12/02.8402230207.
- --8104210125 Discusses implications of Ofc of Inspector & Auditor 781012 interview w/facility ASLB Ofc of Inspector & Auditor attempted to probe thought processes of & require justification from Board re action taken in adjudication YORE, J R Atomic Safety and Licensing Board Panel 78/10/19 HENRIE, J M Commissioners Spp. 22378 302 24X Fiche 50-400,83/12/02,8402230207
- --8402230237 Discusses investigation by Ofc of Inspector & Auditor (OIA) re facility proceeding ASLAB unwilling to be interrogated by OIA Many questions in OIA interrogation of members of ASLB manifestly improper ROSENTHALLA & Atomic Safety and Litensing Appeal Panel 78/10/20 HENDRIE Commissioners 2pp 22378 306 24X Ficha 50-400,83/12/02,8402230207.
- Advisory Committee on Reactor Safeguards reports & correspondence
- 8401300121 Summarizes ACRS 285th meeting on 840112-14 re review of QL application, control room design & tube degradation Investigation of allegations re GA requested. EBERGOLE: J.C. ACRS Advisory Committee on Reactor Befeguards 84/01/16 PALLADIND:N.J. Commissioners 3pp. 22044 023. 24X Fiche 50-400,84/01/16,8401300121.

- DOCKET 50-407 UNIV OF UTAH RESEARCH REACTOR
- F Security, medical, emergency & fire protection plans
- 8403140145 Forwards Rev i to physical security plan Rev withheld BANDOUIST,O Utah. Univ of Balt Lake City. UT 84/09/12 NRC -No Detailed Affiliation Given ip 22620 331 24X Fiche.50-407.84/03/12,8403140145
- 8403200281 Forwards revised emergency plan, add1 financial info & 1983 financial statement for univ SANDQUIST.O B Utah, Univ of, Salt Lake City, UT 84/03/14 THOMAS, C Standardistation & Special Projects Branch 1p 22496 281 24X Fiche 50-072,84/03/14,8403200281
- --8403200293 Revised "Univ of Utah Emergency Plan for Training & Research Reactors " BANDGUIST, O M Utah, Univ. of, Salt Lake City, UT UTEC ME 84-0205 84/03/14 28pp 22696 282 24X Fiche 50-072,84/03/14, 8403200281.
- I Financial information
- 8403200281 Forwards revised emergency plan, add1 financial info & 1983 financial statement for univ SANDOUTST. 8.M Utah, Univ of, Salt Lake City, UT 84/03/14 THOMAS. C Standardization & Special Projects Branch 1p 22676 281 24X Fiche. 90-072, 84/03/14, 8403200281
- --8403200274 Univ of Utah operating budget 1783-84 * Utah, Univ of, Salt Lake City, UT 84/03/14 37pp 22694 310 24X Fiche 50-072,84/03/14,8403200281.
- DOCKET 50-409 LA CROSSE BOILING WATER REACTOR
- F Becurity, medical, emergency & fire protection plans
- 8403120074 Extends invitation to attend 840323 regional workshop in Rosemont. IL re 10CFR50, App R safe shutdown requirements Workshop will cover subjs described in IE Info Notice 84-09 & provide addl guidance in safe shutdown analyses SPEBSARD.R L Division of Engineering. 84/03/06 LINDER.F W Dairylland Fouer Cooperative. 3pp 22588:240 24X Fiche: 50-409.84/03/06.8403120074
- 8403160047 Revs to emergency plan implementing procedures, including Procedures EPP-2, "Organization & Operations During Emergencies." EPP-3, "Communications Sys," & EPP-5, "Estimate of Offsite Dase" #/840310 ltm LINDER, F Dairyland Power Cooperative. 84/03/10 CRUTCHFIELD, D Operating Reactors Branch 5 75pp 22655.006 24X Fiche: 50-409, 84/03/10, 8403160047.
- 8403200107 Ack receipt of 840307 request for attendance at 840322 meeting in LaCrosse.WI to discuss ecope & objectives of 840417 emergency preparedness exercise NRC unable to attend meeting.

 PAPERIELLO, C. J. Region 3, Office of Director 84/03/16
 LINDER, F. W. Dairyland Power Cooperative ip 22685 325 24X
 Fiche 30-409.84/03/16.8403200109
- --8403200112 Requests attendance at 840322 meeting in LaCrosse, WI to discuss scope & objectives for 840619 amergency preparedness exercise Objectives must be submitted for review by 840406 MARQBE.R. Dairyland Power Cooperative 84/03/09 PHILLIPS, M Region 3, Office of Director ip 22685;326. 24X Fiche 50-409,84/03/16,8403200109
- P Operating license stage documents & correspondence
- 8403030009 Forwards request for add1 info re NUREG-0737, Item I1. B. 3, "Post-Accident Sampling Sys," to complete review. Requests response within 45 days of itr receipt CRUTCHFIELD, D. Operating Reactors Branch 5 84/02/29, LINDER, F. Dairyland Power Cooperative 3pp. 22490 id7 24X Fiche 50-409,84/02/29,8403050009.
- 8403130270 Forwards response to Section 4 of NUREO-0827, BEP Topic II-3 C, "Safety-Related Water Supply (UHS) " Submittal of applicable Tech Spec changes rescheduled for 840401. LINDER, F. Dairyland Power Cooperative. 84/03/08 CRUTCHFIELD, D Operating Reactors Branch 5 5pp. 22608:034 24X Fiche: 50-409, 84/03/08, 8403130290.
- 8403150275 Generic Ltr 84-07 to all licensees of BWRs re procedural guidance for pipe replacement at BWRs, 8vc list encl EISENHUT, D G. Division of Licensing 84/05/14 Commonwealth Edison Co 20pp 22823 354 24X Fiche, 50-000, 84/03/14, 8403150275

- 8403140074 Forwards acceleration time histories for Nodes 13 & 19 of EGRO seismic analysis of containment bldg Time histories provided in all three model global directions ORINES.C. I Operating Reactors Assessment Branch 84/03/14 LINDER.F Dairyland Power Cooperative 14pp 22655 089 24X Ficher 50-409.84/03/14.8403160074
- 8403300089 Application to amend License DPR-45, changing Tech Specs to revise reporting requirements to improve accessibility LIMDER.F. Dairyland Power Cooperative 84/03/20 CRUTCHFIELD, D Operating Reactors Branch 5 4pp 22821 187 24X Ficha 50-409,84/03/20,8403300089
- --8403300093 Proposed Tech Spec changes, modifying reporting requirements to improve accessibility * Dairylend Power Cooperative. 84/03/20. 21pp 22821 191 24X Fichs: 50-409, 84/03/20, 8403300089
- 8403290283 Application for amend to License DPR-45, revising Tech Spect rs min requirements for alternate cooling water source to be used during loss of UHS event LINDER, F. Dairyland Power Cooperative 84/03/21 CRUTCHFIELD, D. Operating Reactors Branch 5. 3pp. 22800:079. 24X Fiche 80-409,84/03/21,8403290283
- --8403290287 Proposed Tech Space re min requirements for alternate cooling water source to be used during loss of UHS event. * Dairyland Power Cooperative 84/03/21 1p 22800:082 24X Fiche: 50-409.84/03/21,8403290283
- 8403280066 Forwards safety evaluation re NUREO-0737.TMI Action Item II K.3.44, "Evaluation of Anticipated Transients W/Bingle Failures." Facility in conformance w/NUREO-0737 position & evaluation acceptable.
 CRUTCHFIELD.D. Operating Reactors Branch 5. 84/03/26 LINDER,F Dairyland Power Cooperative 5pp. 22776.349 24X Fiche.50-409.84/03/26.8403280066
- G. Inspection reports, IE Bullstins & correspondence
- 8403120083 Responds to IE Bulletin 76-26.Rev 1.Item 4 6 re results of addy current exams of absorber tubes.Encl lists absorber tube segments unfit for addy current insp due to bending. List showing major indications also encl LINDER.F. Dairyland Power Cooperative 84/02/24 KEPPLER.J 9 Region 3. Office of Director 4pp 22588:185 24X Fiche:50-409.84/02/24.8403120083
- B401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuite & Annunciation." Sec list and UDDAN. E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/28 Consolidated Edison Co. of New York, Inc. 113pp. 22909:239 24X Fichs. 50-000:84/02/28. 8401190072
- B402090007 IE Info Notice B4-14, "Mighlights of Recent Transport Regulatory Revs by DOT & NRC." Evolist ancl. ORACE, N Division of GA, Safeguards & Inspection Programs (Post B30103) B4/03/02. Consolidated Edison Co. of New York, Inc 130pp. 22552:329. 24X Fiche: 50-000,84/03/02,8402090007
- B40209000B IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl. JORDANIE L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02. Consolidated Edison Co. of New York, Inc. 122pp. 22553:098 24X Fiche:50-000.84/03/02.8402090008
- 8402090009 IE Info Notice 84-15. "Reporting of Radiological Releases" Byc list encl. JURDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 119pp. 22553:217. 24X Fiche 50-000:84/03/02:8402090009
- 84020700ii IE Info Notice 84-17, "Problems W/Liquid Nitragen Cooling Components Below Nil Ductility Temp," Syc list encl. JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/03/05 Consolidated Edison Co of New York, Inc. 117pp. 22553.336 24X Fiche 50-000.84/03/05,8402070011
- 8403130326 Ack receipt of 840222 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-409/83-22, Add1 response required by 840320 re stop watch calibr & static trip device test set; per commitment.

 8HAFER, W. D. Region 3. Office of Director 84/03/05 LINDER, F W Dairyland Fower Cooperative. ip 22607; 143, 24X Fiche: 30-409, 84/03/05, 8403190326.

- --8403130335 Responds to NRC 840125 ltr re violations noted in IE Insp. Rept 50-409/83-22 Corrective actions static trip device test set satisfactorily tested & placed on instrument calor equipment list for scheduled periodic retesting LINDER: F Dairyland Fower Coperative 84/02/22 KEPPLER, J O Region 3, Office of Director 2pp 22607 144 24X Fiche 50-409.84/03/05.8403130326
- 8402090024 IE Info Notice 84-09.Rev i. "Lessons Learned From Insps of Fire Protection Bafe Shutdown Sys " Svc list encl JORDAN.E L Division of Emergency Preparadness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000,84/03/07,8402090024
- 8402090028 IE Info Notice 84-18, "Btress Corrosion Cracking in PWR Bys " Byc list encl JBRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000.84/03/07.8402090028
- 8403270233 Forwards IE Insp Rept 50-407/84-03 on 840204-10 & notice of violation HIND, J A Division of Radiological & Materials Safety Programs 84/03/09 LINDER, F W Dairyland Power Cooperative 2pp 22771.335 24X Ficha 50-407.84/03/09.8403270233.
- ---840327023B Notice of violation from insp on 840206-10 HIND, J. A Division of Radiological & Materials Safety Programs 84/03/09 2pp 22771 337 24X Fiche 50-409.84/03/09.8403270233
- --8403270242 IE Insp Rept 50-409/84-03 on 840206-10 Noncompliance noted failure to adhere to radiological control procedures & to properly control high radiation area PAUL, R A . GREGERIL R. Region 3, Office of Director 84/03/09 8pp 22771 339 24X Fiche 50-409,84/03/09,8403270233
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl DEYOUNG:R C Director's Office Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000:84/03/12,8402090031
- 8402070043 IE Info Notice 84-17. "Two Events Involving Unauthorized Entries into PWR Reactor Cavities." Svc list encl JURDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc. 123pp 22823 229 24X Fiche 50-000,84/03/21,8402070043
- B402070044 IE Info Notice B4-20, "Bvc Life of Relays in Safety-Related Sys " Bvc list and JUNEANNEL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 135pp. 22733 001 24X Fiche. 80-000, 84/03/21, 8402070044
- R Periodic operating reports & related correspondence
- 8403080031 "Personnel Whole Body Exposures for CY83 " W/840227 ltr LINDER, F Dairyland Power Cooperative 83/12/31, 2pp 22557 227 24X Fiche 50-409.83/12/31,8403080031
- 8403080236 "Radioactive Effluent Rept & Radiological Environ Monitoring Rept, 1983 " W/840227 ltr LINDER, F Dairyland Power Gooperative 83/12/31 KEPPLER, J Q Region 3, Office of Diractor 99pp 22560:025 24X Fiche 50-409, 83/12/31, 8403080234
- 8403230002 "Radioactive Effluent Rept & Radiological Environ Monitoring Rept for 1983 " W/840227 ltr LINDER, F Dairyland Power Cooperative 83/12/31 KEPPLER, J. G Region 3. Office of Director. 99pp. 22728 111 24X Fiche: 50-409, 83/12/31, 8403230002
- 8403020161 Monthly operating rept for Jan 1784 W/840207 ltr. GOODMAN.L B., LINDER,F Dairyland Power Cooperative 84/01/31 11pp 22442:017 24X Fiche. 50-409, 84/01/31, 8403020161.
- 8403300131 Monthly operating rept for Feb 1984 W/840306 ltr QODDHAN, L. S., LINDER Dairyland Power Cooperative 84/02/27 9pp 22820. Q14 24% Fiche: 50-409, 84/02/27, 8403300131
- S Reportable occurrences. LERs & related correspondence
- 8403200163 LER 84-003-00 on 840220, erroneous high containment bldg pressure alarm received. Caused by fuse failure Fuse replaced.cleering high pressure signal Sys restored to normal W/840312 ltr GDDDMAN, L S , LINDER, F Dairyland Power Cooperative 84/03/12 3pp 22697 134. 24X Fiche, 50-409, 84/03/12, 8403200163

- DOCKET 50-410 NINE HILE POINT NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8403010298 Notification of 840326.27 & 28 meetings w/util in Scriba.NY to review const progress & obtain info for assessing projected fuel load date Supporting documentation encl HAUGHEY.NF Licensing Branch 2 84/02/17 SCHWENCER.A Licensing Branch 2 8pp 22479 174 24X Fiche 50-410.84/02/17,8403010298
- 8403050370 Requests review of documentation submitted in instrumentation & control area & confirmation that documentation reflects actual plant design Changes should be submitted as amends to FSAR in timely manner SCHHENGER.A Licensing Branch 2 84/02/29 RHODE.G K Niagara Mohawk Power Corp 2pp 22527 261 24X Fiche 50-410,84/02/29, 8403030370
- --B403050371 Summary of 840118 & 0207-08 meetings w/util in Bethesda.MD & Cherry Hill.NJ.respectively.re instrumentation & controls List of discrepancies within & between licensing documents encl HAUGHEY.M F Licensing Branch 2 B4/02/27 Licensing Branch 2 20pp 22327 243 24X Fichs 50-410.84/02/29.8403050370
- 8403060539 Summary of 840118 & 0207-08 meetings w/util.GE & StW in Bethesda.HD re instrumentation & controls Supporting documentation encl
 HAUGHEY.H F Licensing Branch 2 84/02/29 Licensing Branch 2 22pp 22552 295 24X Fiche 50-410.84/02/29.8403060539.
- 8403070240 Summary of 840216 meeting w/Northeast Nuclear Energy Co, Boston Edison Co.Verment Yankee Nuclear Power Co & Teledyne Engineering Svcs in Haltham, MA re addl Mark I torus structural analysis List of attendees encl SHEA.J J Operating Reactors Branch 5 84/03/07 CRUTCHFIELD, D Operating Reactors Branch 5 4pp 22572 298 24X Fiche 50-000.84/03/07.8403090240
- 8403270374 Notification of 840404 & 03 meetings w/util, QE & S&W in San Jose-CA to discuss instrumentation & control HAUGHEY, MF F. Licensing Branch 2 84/03/08 SCHMENCER. A Licensin. Branch 2 3pp 22822 291 24% Fichs 50-410,84/03/08.8403290394
- 8403200232 Forwards "Evaluation of Angled Screen Fish Diversion Sys at Oswego Steam Station, Unit 6," "Nine Mile 2 Volney 345 kV Transmission Facility" & "Environ Mgt & Const Plan Name Mile 2 Volney 345 kV Transmission Facility "HANGAN. C V Niagara Mohawk Power Corp 84/03/15 EISENHUT, D G Division of Licensing 1p 22694 221 24X Fiche 50-410,84/03/15,8403200232
- --8403200240 "Evaluation of Angled Screen Fish Diversion Sys at Oswego Steam Station Unit 6 " * Lawler. Matusky & Skelly Engineers 84/01/31 118pp 22694 223 24X Fiche 50-410.84/03/15.8403200232
- --8403200243 "Environ Mgt & Const Plan Nine Mile 2 Volney 345 kV
 Transmission Facility "
 * Niægara Mohauk Power Corp 83/09/30 146pp 22694 341 24X
 Fiche 50-410.84/03/15.8403200232
- --8403200248 "Nine Hile 2 Volney 345 kV Transmission Facility "
 W/three oversize maps Aperture cards are available in PDR
 * Niagara Hohauk Power Corp 82/04/30 350pp 22695:127 24X
 Fiche 50-410,84/03/15,8403200232
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8403210213 Summary of 840224 meeting w/util re administrative matters concerning closing out draft SER open items
 ** Licensing Branch 2 84/03/05 Licensing Branch 2 32pp 22709 208 24X Fiche 50-410.84/03/05.8403210213
- 8403270314 Forwards request for add1 info to complete review of draft SER re pressure-temp limit curves to comply w/explicit closure flangs mat1 temp requirements of 10CFR, App 0 Info should be submitted as FSAR amend no later than 840515 SCHMENCER. A Licensing Branch 2 84/03/06 RHODE.0 K, Niagara Hohawk Power Corp 4pp 22789 246 24X Fiche 50-410,84/03/06,
- 8403220301 Forwards interim draft SER (NUREQ-1047) identifying unresolved issues as open items Complete draft SER expected to be reissued in May 1984 Detailed agenda eimed at resolving open items requested SCHMENCER: A Licensing Branch 2 84/03/08 RHODE.0 K Niagara Nohawat Power Corp 456pp 22720 001 24% Fiche 50-410.84/03/08, 8403220301

- B403280236 Forwards list of issues to be discussed at Mechanical Engineering SER review during wk of 840604 at 9&M ofcs in Cherry Hill.NJ SCHMENCER.A Licensing Branch 2 84/03/12 RHODE.G K Niagara Mohawk Power Corp 15pp 22789 326 24X Fiche 50-410.84/03/12.8403280236
- F Security, medical, emergency & fire protection plans
- 8403190243 Notification of 840418 workshop in King of Prussie, PA to discuss lessons learned from recent App R fire protection safe shutdown insp & topics described in IE Info Notice 84-07 Agenda for workshop encl MURLEY. T. E Region I. Office of Director 84/03/07 O'TOOLE, J D Consolidated Edison Co of New York, Inc 35pp 22672.062. 24X Fiche 50-000,84/03/09.8403190243
- G Adjudicatory correspondence
- 84030B0136 Resolution submitted by Legislature of Erie County requesting FERC & NRC intevene to half util withdrawal from project & State of NY Public Evc Commission investigate util actions
 SWARTS D J Buffalo, NY 84/03/01 2pp 22561 150 24X Fiche 50~410.84/03/01,84030B0136
- I Financial information
- 8403290177 Annual Financial Rept 1983 W/840322 ltr HAEHL,J G , DONLON,W J , LEMPGES.T E Niagara Hohawk Power Corp. 83/12/31. 41pp 22800 319 24X Fiche 50-220.83/12/31,8403290177.
- Q Inspection reports, IE Bulletins & correspondence
- 8403010006'Notification of Significant Licensee Meeting 84-18 on 840222 in King of Prussia,PA to discuss const appraisal team & BALP findings
 COLLING:S J Division of Project & Resident Programs 84/02/17 Division of Project & Resident Programs 19 22479 339. 24X
 Ficha 50-410.84/02/17.8403010006
- B401190072 IE Info Notice B4-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN.E L. Division of Emergency Preparadness & Engineering Response (Post 830103) B4/02/2B Consolidated Edison Co of New York, Inc. 115pp 22709 237 24X Fiche 50-000,84/02/2B,8401190072
- 8403150076 Forwards IE Insp Rept 50-410/83-17 on 831205-840120. No violations observed STAROSTECKI.R Division of Project & Resident Programs. 84/03/01 RHDDE:0 K Niagara Mohawk Power Corp 2pp 22643 146 24X Fiche 50-410,84/03/01.8403150076
- --B403150101 IE Insp Rept 50-410/B3-17 on B31205-B40120 No violations identified Hajor areas inspected work activities, procedures & records re reactor pressure vessel storage & hydraulic control unit installation GRAMM.R. A, LAZARUS, W J, COLLING, B J, Region 1, Office of Director B4/02/27 lipp 22643 148, 24X Fiche 50-410,84/03/01.8403150096
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list enc! GRACE.J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc 130pp 22532 329 24X Fiche 50-000.84/03/02.8402090007.
- 8402090008 IE Info Notice 84-16. "Pailure of Automatic Sprinkler Bys Valves to Operate " Svc list encl JORDAN.EL Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/02 Consolidated Edison Co of New York, Inc. 122pp 22053 098 24X Fiche 50-000,84/03/02,8402090000
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases." Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 119pp, 22553 217 24X Fiche: 50-000, 84/03/02, 8402090009
- 8402090011 IE Info Notice 84-17. "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl. JORDAN, E L. Division of Emergency Preparadness & Engineering Response (Post 830103). 84/03/05 Consolidated Edison Co. of New York, Inc. 117pp 22553'336 24X Fiche. 50-000, 84/03/05, 8402090011

- B402090024 IE Info Notice 84-09. Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000.84/03/07.8402090024
- 8402070028 IE Info Notice 84-18, "Stress Corrosion Cracking in PHR Sys " Syc list and I JDRDAN,E L Division of Emergency Proparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000/84/03/07,8402070028
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl DEVOUNG, R. C. Director's Office Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 074 24X Fiche 50-000, B4/03/12, B402090031
- B402090043 IE Info Notice 84-19. "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/03/21 Consolidated Edison Co. of New York: Inc 123pp. 22823 227 24X Fiche 50-000.84/03/21,8402070043
- 8402090044 IE Info Notice 84-20. "Svc Life of Relays in Safety-Related Sys " Svc list and! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000.84/03/21,8402090044
- R Pariodic operating reports & related correspondence
- 8403020443 Forwards monthly status rept of offsite emergency preparedness for OL reviews for Jan 1984 Changes in FEMA finding dates not caused by delay due to offsite emergency planning issues.

 DIRCKS.W.J. Office of the Executive Director for Operations 84/02/21 PALLADING Commissioners 9pp 22492 083 24X Fiche 50-000.84/02/21.8403020443
- S. Reportable occurrences, LERs & related correspondence
- B403090078 Deficiency rept re items supplied by Tube-Line Corp Final rept delayed until 840430 per 840213 telcon RHODE, G K Niagara Mohauk Power Corp 84/02/15 STAROBTECKI, R Division of Project & Resident Programs ip 22576 048 24X Ficha, 50-410, 84/02/15, 8403090078
- B403210136 Interim deficiency rept re Anchor Darling HPCS sys valve vibration loosening anti-rotational set screws Initially reported on 840127 & reported by GE per Part 21 Investigation in progress Final rept by B40723 MANGAN.C V Niagara Mohawk Power Corp 84/02/27 STAROSTECKI,R Division of Project & Resident Programs 2pp 22707 272 24X Fiche 50-410.84/02/27.8403210136
- 8403260233 Forwards summary list of deficiencies identified per 100FR50.55(e).Part 21 & potential generic ltr repts for comments
 874R0STEGKI,R Division of Project & Resident Programs 84/02/28
 Region 1, Office of Director. 7pp 22756.065 24X
 Fiche 50-000.84/02/28.8403260233
- 8403130363 Interim deficiency rept re hydrostatic uplift pressure not considered in reactor bldg mat design Initially reported on 840130. Final rept will be submitted by 840518 MANGAN, C. V Niagara Mohawk Power Corp 84/02/27 STAROSTECKI, R Division of Project & Resident Frograms 2pp 22616 248 24X Fiche 50-410,84/02/27,8403130363
- 8403140122 Part 2: rept re status update concerning abnormal wear on linear converters. Test program underway Results of investigation indicate excessive wear caused by hunting of control circuitry.

 BODBON, J.P. Parific Air Products Co. 84/03/09 Director's Office, Office of Inspection and Enforcement 7pp 22624 068 24X Fiche. 50-000: 84/03/09: 8403140122.
- 8403190135 PNS-I-84-002 on 840312, bomb threat received from unidentified caller Site emergency & safeguards contingency plan requirements implemented, Public areas & site protected area searched w/negative findings MADDEN.B., JOYNER.J., Region 1, Office of Director 84/03/12 ip 22674-352 24X Fiche 50-220,84/03/12,8403190135.
- 8403220075 EN-84-015 on 840320, notice of violation & proposed imposition of civil penalties in amount of \$180,000 will be issued to licensee Action based on failure to maintain containment integrity & failure to conduct surveillance CRAIQ.U., AXELRAD.U. Director's Office of Inspection and Enforcement, 84/03/15, 2pp 22712 308, 24X Fiche, 50-220, 84/03/15, 8403220075

V Operator Examinations

8403130124 Forwards nuclear power plant experience for operating shift positions as requested in 840301 ltr
LEMPGES, T E Niagara Mohawk Power Corp 84/03/05 DENTON, H
Dffice of Nuclear Reactor Regulation, Director 5pp 22603 237
24X Fiche 50-410.84/03/05.8403130124

DOCKET 50-412 BEAVER VALLEY POWER STATION, UNIT 2

A Application/construction stage documents & correspondence

- 8403010050 Third partial response to #OIA request for six categories of documents re facility Forwards App A documents App A documents also placed in PDR App B documents will be placed in PDR upon request Review continuing FELTON, J M Division of Rules and Records 84/01/17 ANDERSON, S I Garvey, Schubert, Adams & Barer 4pp 22446 293 24X Fiche 50~000,84/01/17,8403010050
- ~~8i12020204 Forwards new format for nuclear power plants ~ const status rept.NUREG-0030 (yellow book) New format should be used to provide next update info for planned Nov 1981 publication (data as of Sept 30.1981) due 8ii120 W/o encl HARTFIELD.R A Office of Management and Program Analysis 81/10/30 DUNN.C N Duquesne Light Ca 9pp 22446 305 24X Fiche 50-000,84/01/17,8403010050
- 8403010387 Requests delay in submitting add1 info per Accident Evaluation Branch 831202 request Response to Questions E450 1 & 2 will be submitted on 840323 MODILEVER: E J Duquesne Light Co 84/02/24 KN19HTON.G W. Licensing Branch 3 ip 22434 067 24X Fiche 50-412,84/02/24,8403010387
- B403270369 Notification of 840403-05 meetings w/S&W & util in Boston, MA to discuss NRC questions re mechanical engineering portions of FERR & perform detailed design documentation audit on facility LAZO, L Licensing Branch 9 B4/03/01 KNIOHTON, O W Licensing Branch 9 APP 22787 335 24X Fiche 50-412, B4/03/01, B403270369
- 8403280056 Notification of 840321 meeting w/util in Bethesda.MD to discuss Environ & Hydrological Engineering Branch Questions 240 01 & 240 08 LAZO.L Licensing Branch 3 84/03/02 KNIOHTON.G W Licensing Branch 3 App 22812 350 24X Fichs 50~412,84/03/02,8403280056.
- B403190152 Responds to 840123 ltr re use of Rockbestos Co cable at facility Vendor stated in writing that cable fully suitable for safety-related use WOOLEVER, E. J. Duquesne Light Co. 84/03/06 POTAPOVS, U. Region 4. Office of Director. 2pp. 22668 343 24X Fiche, 50-412,84/03/06,8403190152
- 8403280067 Notification of 840313 meeting w/util in Bethesda, MD to discuss Chemical Engineering Branch, Chemical Yechnology Section, questions & open items LAZD. L. Licensing Branch 3 84/03/07 KNIGHTON, 6 W Licensing Branch 3 4pp 22812 331 24X Fiche 50-412,84/03/07,8403280067
- 8403280122 Summary of 840224 meeting w/Westinghouse Duners Group in Bethesda MD re proposed Westinghouse steam generator tube rupture generic program Attendes list & agenda encl NERBEG, V Licensing Branch 3 84/03/07 Licensing Branch 3 35pp \$2811 131. 24X Fiche 50-000.84/03/07.8403280122
- 8403280040 Notification of 840403 meeting w/util in Shippingport,PA to visit specific points of interest within branch environ raview scope LAZO,L Licensing Branch 3 84/03/08 KNIOHTON,C W Licensing Branch 3 3pp 22812.338 24X Fiche 50-412.84/03/08.8403280040
- 8403160090 Forwards SMECO 7703, "Missile-Barrier Interaction," submitted per 840227 response to Action Item 18 of structural design audit HOOLEVER: E J Duquesne Light Ca 84/03/09 KNIGHTON, G W Licensing Branch 3 lp 22653 001 24X Fiche 50-412,84/03/09,84031640090
- --8403160076 "Missile-Barrier Interaction"
 JANKOV, Z D, SHANAHAN, J A, WHITE, M P. Stone & Webster Engineering
 Corp. SHECO 7703 77/09/30 223pp 22653 002 24X
 Fiche 50-412,84/03/09,8403160090

- B403160190 Forwards minutes from B31205-08 meeting w/Instrumentation & Control Sys Branch re discussion of B30919 request for add1 info Items listed as closed imply that info requested by NRC has been provided WOOLEVER, E J Duquesne Light Co B4/03/09 KNIGHTON, G W Licansing Branch J 21pp 22655 246 24X Fiche 50-412, B4/03/09,
- 8403200234 Forwards responses to Procedures & Sys Review Branch questions re nuclear engineering dept organization & administrative procedures, forwarded in 840106 ltr Responses will be included in FSAR Amend 6 MODLEVER. E J Duquesne Light Co 84/03/16 KNIGHTON, O W Licensing Branch 3 13pp 22691 089 24X Fiche 50-412.84/03/16.8403200234
- 8403300062 Forwards operating shift experience tables Util does not plan to use shift advisors CAREY, J. Duquesne Light Co. 84/03/26 DENTON, H. Défice of Nuclear Reactor Regulation, Director App. 22821 167 24X Fiche 50-412
- C Utility Environmental Report (ER). amends & correspondence
- 8403270372 Requests addl info re environ site visit scheduled for wk of 830926 to review environ rept OL stage KNIGHTON G W Licensing Branch 3 84/03/02 WODLEVER, E J Duquesne Light Co 4pp 22787 326 24X Fiche 50-412,84/03/02,8403270372
- B403150095 Forwards Affidavits of Svc certifying distribution of Amend 4 to environ rept & Amend 5 to FSAR WOOLEVER:E J Duquesne Light Co. B4/03/09 DENTON H R Office of Nuclear Reactor Regulation. Director 5pp 22641 164 24X Fich# 50-412,84/03/09,8403150095
- B403290145 Forwards Amend 5 to environ rept OL stage Amend consists of responses to Questions E451 5.E450 1 & E450 2.per QN Knighton 831020 & 1202 ltrs & various technical & editorial changes.

 HOOLEYER: E J Duquesne Light Co 84/03/19 BENTON, H R Office of Nuclear Reactor Regulation. Director 5pp 22801 244 24X Fiche: 50-412, 84/03/19, 8403290145
- 8403260059 Forwards responses to Accident Evaluation Branch 831202 questions re environ rept Revised environ rept. Section 7 1 also encl WDDLEVER, E. J. Duquesne Light Co. 84/03/22 KNIGHTON, O. W. Licensing Branch 3 23pp 22751 003 24X Fiche 50-412.84/03/22.8403260059
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- B403140197 Forwards draft SER (NUREC-1057) re operation Proposed schedule for submittal of written response to open items should be provided by B40330 KNIOHTON, G W Licensing Branch 3 B4/03/01 WOOLEVER, E J. Duquesne Light Co 311pp 22636 001 24X Fiche, 50-412,84/03/01,8403140197
- F Security, medical, emergency & fire protection plans
- 8403270357 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee.per 810709 Generic Ltr 81-27 W/o request, entire plan will be placed in PDR KNIGHTON.9 W Licensing Branch 3 84/03/01 WOOLEVER, E J Buquesne Light Co 4pp 22787 348 24X Fiche 50-412, 84/03/01, 8403270357
- 8403200040 Emergency Preparedness Plan EPP/IP 1 2.Attachments 6 & 7 MILLER, D J Duquesne Light Co 84/03/02. App 22478: 316 24X Fiche 80-334,84/03/02,8403200040
- 8403190243 Notification of 840418 workshop in King of Prussia.PA to discuss lessons learned from recent App R fire protection safe shutdown insp & topics described in IE Info Notice 84-09 Agenda for workshop encl MURLEY.T E Region i, Office of Director 84/03/09 O'TOOLE,J D Consolidated Edison Co of New York, Inc 35pp 22672 062, 24% Fiche 50-000.84/03/09.8403190243

- K Utility Final Bafety Analysis Report (FBAR) & amends
- 8403150075 Forwards Affidevits of Svc certifying distribution of Amend 4 to environ rept & Amend 5 to FSAR MODLEVER: 6 J Duquesne Light 60 84/03/07 DENTON H R Office of Nuclear Reactor Regulation, Director 5pp 22641 164 24X Fiche 50-412,84/03/09,8403150095
- Q Inspection reports, IE Bulletins & correspondence
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103), 84/02/28 Consolidated Edison Co. of New York Inc 115pp 22709 237 24X Fiche 50-000,84/02/28,8401190072
- 8403070303 Ack receipt of 840112 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-412/83-15 STAROSTECKI.R Division of Project & Resident Programs 84/02/28 HOULEVER.E J Duquesse Light Co 2pp 22546 282 24X Fiche 50-412.84/02/28.8403070303
- --8403070308 Responds to NRC 831212 ltr re violations noted in IE Insp Rept 50-412/83-15 Corrective actions engineering in process of analyzing all KH applications to confirm acceptability of judgment made in response to Request for Info RI-0383-9C MODLEVER.E.J. Duquesne Light Co. 84/01/12. BYAROSTECKI.R Division of Project & Resident Programs 4pp 22346:284 24X Ficha 50-412.84/02/28.8403070303
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl GRACE, J N. Division of GA. Bafeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 130pp 22552 329 24X Fiche 50-000,84/03/02,8402090007
- B402090008 JE Info Notice B4-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN E L Division of Emergency Preparadness & Engineering Response (Post B30103) B4/03/02 Consolidated Edison Co. of New York, Inc 122pp 22553 098 24X Fiche 50-000.84/03/02,8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases" 8vc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 117pp 22553:217 24X Fiche: 50-000,84/03/02,8402090009
- 8402070011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Tamp " Svc list encl.

 JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York Inc. 117pp 22553-336 24X Fiche 50-000,84/03/05,8402070011
- 8402090024 IE Info Notice 84-09, Rev 1, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN,E L. Division of Emergency Preparadness & Engineering Response (Post 830103) 84/03/07 Candolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche, 50-000, 84/03/07, 8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR 8ys " 8vc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07. Consolidated Edison Co. of New York, Inc. 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- B403220131 Forwards IE Insp Rept 50-412/84-01 on 840117-0221 No violations observed STAROSTECKI,R Division of Project & Resident Programs 84/03/08 WOOLEVER,E J Duquesne Light Co 2pp 22716 019 24X Fiche 50-412,84/03/08.8403220131
- --B403220139 IE Insp Rept 50-412/B4-01 on 840117-0221 No violations observed Major areas inspected, previously identified items. FBAR descriptions, post-weld heat treatment, storage requirements & procedure review of piping installation. MALTON.G A Region 1. Office of Director TRIPP, L.E. Division of Project & Resident Programs. B4/03/07 Bpp. 22716 021, 24X Fiche 50-412,84/03/08,8403220131
- B402070031 IE Bulletin 84-02, "Failures of QE Type HFA Relays in Use in Class IE Safety Sys " Syc list encl.

 DEYOUNG.R C. Director's Office. Office of Inspection and Enforcement. B4/03/12 Consolidated Edison Co. of New York. Inc 134pp 22823,074 24X Ficher 50-000.84/03/12,8402070031.

- 8402070043 IE Info Notice 84-19. "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Piche 50-000,84/03/21,8402070043
- 8402090044 IE Info Notice 84-20, "Syc Life of Relays in Safety-Related Svc list encl JURDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 135pp 22933 001 24X Fiche 50-000.84/03/21.8402090044
- 8403270200 Ack receipt of 840302 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-412/83-13 Corrective actions will be examined during future insp BTAROSTECKI.R Division of Project & Resident Programs 84/03/22 MODILEVER,E J Duquesne Light Co 1p 22803 293 24X Fiche: 50-412,84/03/22,8403270200
- -8403270204 Responds to NRC 831110 ltr re violations noted in IE Insp Rept 50-412/83-13 Engineering evaluation confirmed ATSM A325 bolts maintain required min bolt preload No add1 action required required
 MCGLEYER, E J Duquesne Light Co 84/03/02 STARGSTECKI, R
 Division of Project & Resident Programs 4pp 22803 301
 Fiche: 50-412,84/03/22,8403290200
- B403300200 Forwards summary of actions taken, per IE Bulletin 83-07, "Apparently Fraudulent Products Sold by Ray Miller, Inc "Pittsburgh-Des Moines Steel & Joseph Oat Corp received matls from Ray Miller, Inc Matls not fraudulent MODLEVER; E. J. Duquesne Light Co. 84/03/22 MURLEY, T. E. Region 1. Office of Director 3pp. 22819 321 24X Fiche 50-412,84/03/22, BA03200000 B403300200,
- 8 Reportable occurrences, LERs & related correspondence
- 8403070298 Interim significant Deficiency Rept 84-01 re clamp anchor assemblies w/undersized welds Vendor surveillance group will perform sample insp to establish effectiveness of vendor GC Next rept by 840501 WOOLEVER, E J Duquesne Light Co 84/02/16 MVRLEY, T E Region 1. Office of Director 4pp 22541 272 24X Fiche 50-412,84/02/16,8403070298
- B403130374 Interim Bignificant Deficiency Rept 84-02 re poor wiring workmanship on two Gould 480-volt motor control ctrs Random insps conducted Evaluation underway Next rept will be submitted by 850701 HOOLEVER, E. J. Duquesne Light Co. 84/02/21 MURLEY, T. E. Region Office of Director. Spp. 22616 278 24X Fiche 50-412.84/02/21, 8403130374.
- 8403210130 Interim Bignificant Deficiency Rept 84-03 re GE Type HEA lock-out relays Initially reported on 840127 Field test procedure developed to test relays Defective relays will be replaced Next rept by 840615

 HOOLEVER, E. J. Duquesne Light Co. 84/02/28 MURLEY, T. E. Region

 Office of Director 4pp 22707, 266 24X Fiche 50-412,84/02/28,8403210130 Region 1
- B403260233 Forwards summary list of deficiencies identified per 10CFR50 55(e), Part 21 & potential generic ltr repts for
- 8403210058 Final Significant Deficiency Rept 83-02 re GC acceptance of nonconforming cable pulling conditions Initially reported on 840227. GC section reorganized Continued sampling of GC inspector activities implemented MDOLEVER.E J Duquesne Light Co 84/02/29 MURLEY, T E Region i. Office of Director. 4pp 22704 346 24X Fiche 50-412,84/02/27,8403210058. 8403210058.
- 8403270219 Part 21 rept re broken contect carrier in control device of 7 5 kV-15 kV.500-750 MVA.5 kV 350-3.000 & all HKV circuit breakers initially reported on 830223 Addenda to oreasers initially reported on Blocks Addends to initialization & maint procedures sent to affected units DUVALL, D D Brown Boveri Corp. (subs of Brown Boveri & Co., Ltd.) 84/03/19 Record Services Branch (Document Control Desk). Spp. 22772: 114. 24% Fiche 50-000, 84/03/19, 8403270219

V Operator Examinations

8403300062 Forwards operating shift experience tables Util does not Plan to use shift advisors.
GAREY, J. J Duquesne Light Co 84/03/26 DENTON, H Office of Nuclear Reactor Regulation, Director. App 22821 167 24X Fiche: 50-412, 84/03/26, 8403300062

- DOCKET 50-413 CATAWA NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & corresonnance
- 8403080196 FDIA request for documents re WR McAfee allegations involving facility from Mar 1977 Mar 1979,NRC open conference at site in Nov 1979 & review of util topical QA MANUAL OF SECTION NOV 1977 & Period of Section Indicated and Manual GARDE, B P , ANSELL.E Covernment Accountability Project 83/11/21 Office of Administration 2pp 22584 162 24X Fiche 50-413,83/11/21.8403080196
- 8403060477 Notification of 840313 meeting w/util in York County, SC to conduct confirmatory site visit per Section 13 6 of SRP (NUREG-0800) JABBOUR, K N Licensing Branch 4 84/02/24 ADENSAM, E 6 Licensin Branch 4 3pp 22549
 - 24X Fiche 50-413,84/02/24,8403060477 Эрр
- 8402090017 Board Notification 84-038 forwards RJ Mattson 840123 memo to DG Eisenhut providing status update of NRC actions re Westinghouse ECCS actuation logic EISENHUT.D Q Division of Licensing 84/02/27 PALLADIND Commissioners 7pp 22546 007 24X Fiche 50-000.84/02/27, 840209017 8402090017
- 8403020230 Notifies that Class II fee appropriate for review of 840123 application requesting extension of const completion date to 84101 License Fee Management Branch 84/02/27 TUCK Co ip 22494 319 24% Fiche 50-413,84/02/27, DIGOS.R M Duke Pawer Co 8403020230
- 840:3070189 Forwards equipment data sheets for SGRT & pump & valve operability review team onsite audits Qualification of components complete W/five oversize drawings Aperture cards are available in FDR
 TUCKER, H B Duke Pawer Co 84/02/28 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENBAM, E 9 Licensing Branch 4 601pp 22536 281 24X Fiche 50-413,84/02/28,8403070185
- --8403070202 Rev 10 to Procedure CNS-1390 01-00-0073, "Installation Spec Manual Mechanical Installation Procedure for Electrical Penetration Types B.C.D.F.O.H.J.K.L. & M" * Duke Power Co 83/08/24 34pp 22537 087 24X Fiche 50-413,84/02/28,8403070185
- --8403070219 Rev B to Procedure CNB-1390 01-00-0071, "Procedure for Installation of Type A (6.900 Volt) Electric Penetration Assemblies ' DOVER, R P Duke Power Co 83/0 Fiche 50-413, 84/02/28, 8403070185 83/03/07 350pp 22537 167 24X
- 8402090016 Board Notification 84-031 informs that Commission received affidavit from former util employee alleging that util deliberately undermined QA program at facilities Investigation in progress
 NDVAK,T M Assistant Director for Licensing, 84/02/29, KELL'
 PURDDM,P, FOBTER,R Atomic Safety and Licensing Board Panel
 67217 043 24% Fiche 50-413,84/02/29,8402090016 KELLY, J ,
- 8403170374 Forwards nonproprietary & proprietary "Technical Basis for Eliminating Pressurizor Burge Line Ruptures as Structural Design Basis for Catawba: Units i & 2 " Revised FSAR pages also encl Proprietary rept withheld (ref 100FR2 790) TUCKER.H B Duke Power Co 84/02/29 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENBAME C Licensing Brant 4 3pp 22674 089 24X Fiche 50-413.84/02/29.8403190374 Licensing Branch
- ---8403190399 Application for withholding proprietary rept HCAP-10487,
 "Technical Basis for Eliminating Pressurizer Surge Line
 Ruptures as Btructural Design Basis "
 HIEBEMANN, A Hestinghouse Electric Corp 84/02/15 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 9pp 22474:092 24X Fiche, 50-413, 84/02/29, 8403190394
- ---8403190404 Nonproprietary "Technical Basis for Eliminating Pressurizer Surge Line Ruptures as Structural Design Basis for Catawba Units 1 & 2 " SHAMY, 8 A , YANG, C Y , SANE. A D Westinghouse Electric Corp WCAP-10488 (NP) 84/02/10 107pp 22674 101 24X Fiche 50-413,84/02/29,8403190394
- 8403040422 Provides second suppl to 831118 submittal & addl info on positive aspects of elimination of arbitrary intermediate pips breaks from facilities
 TUCKER, H B Duke Power Co 84/03/01 DENTUN:H R Office of Nuclear Reactor Regulation. Director ADENSAM, E G. Licensing Branch 4 2pp. 22511 359 24X Fiche.50-413.84/03/01.8403060422

- 8403130086 Forwards fee for review of 840123 request for extension of const completion date to 841101 TUCKER, H B Duke Power Co 84/03/02 DIGGS, R M License Fee Management Branch 1p 22614 270 24X Fiche 50-413,84/03/02,840
- 8403160028 Advises that all refs to three (N-1) loop operation should be deleted in proof & review Tech Specs issued 840302 Plant will operate only w/four loops in operation during at-power modes, in response to FSAR Guestion 440 5B
 TUCKER, H B Duke Power Co 84703707 DENTON, H R Office of Nuclear Reactor Regulation. Director ADENSAN, E G Licensing Branch 4. 2pp 22654 347 24X Fiche 50-413, 84703/07, 8403160028
- 8403190257 Forwards "Steam Pressure Suppression Characteristics of Water-Soluble Plastic Membrane Shielded Ice for Ice Condenser Containment Nuclear Power Plants "TUCKER.H B Duke Power Co 84/03/07 DENTON.H R Office of Nuclear Reactor Regulation. Director ADENSAM, E.G. Licensing Branch 4 7pp 22672 102 24% Fiche 50-000.84/03/07.8403190257.
- B403280122 Summary of 840224 meating w/Westinghouse Owners Group in Bathssda,MD re proposed Westinghouse steam generator tube rupture generic program Attendee list & agenda encl NERSES:V Licensing Branch 3 84/03/07 Licensing Branch 3 35pp 28811 131 24X Fiche 50-000.84/03/07.8403280122
- 8403130104 Provides ciarification of third paragraph of 840229 ltr repressibility of welded piping attachments being located in close proximity to eliminated arbitrary intermediate breaks TUCKER, H B Dute Power Co 84/03/08 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAN, E 9 Licensing Branch 2 2pp. 22500 256 24X Fiche 50-413,84/03/08,8403130104
- B403160197 Forwards responses to EQ Adensam 820401 request for qualification documentation re operability of containment purge & vent valves in Modes 1-4 per Tech Spec 3 & 1 9 TUCKER, H B Duke Power Co 94/03/12 DENTON, H R Office of Mutlear Reactor Regulation, Director ADENSAM, E O Licensing Branch 4 333pp 22658 185 24X Fiche 50-413,84/03/12,8403160197
- 8402090041 Board Notification 84-050 provides Commission policy statement & proposed rulemaking on environ qualifications EIGENHUT.D G Division of Licensing 84/03/14 Atomic Safety and Licensing Board Panel 10pp 24% Ficha 50-000.84/03/14.8402090041
- 8403200165 Forwards summary of experience for operations personnel to be licensed on Unit 1.per 840114 & 0226 commitments Based on operating shift experience requirements, sufficient experience available to startup & operate Unit 1 TUCKER.H B Duke Power Co E4/03/14 DENTON.H R Office of NUCKER.H B Duke Town Turector ADENSAN,E G Licensing Branch 4 12pg. 22697 001 24X Fiche 50-413,84/03/14,8403200165
- 8403220074 Requests that snubber Tech Specs be written to reflect inspon unit basis instead of current sys basis Conclusions from review of J Sapir 740301 ltr re Tech Specs for snubber operability & surveillance listed
 TUCKER.H B Duke Power Co 84/03/15 DENTON, HR Office of Nuclear Reactor Regulation, Director ABENSAM.E Q Licensing Branch 4 2pp 22712 306 24x Fiche 50-413.84/03/15.8403220074
- 8403250034 Forwards proposed amends for proof & review Tech Specs
 Amends change surveillance requirements for diesel fuel oil
 Bupporting justification & analysis encl
 TUCKER.H B Duke Power Co 84/03/15 DENTON.H R Office of
 Nuclear Reactor Regulation, Director ADENSAM.E G Licensing Branch
 4 2pp 22750 260 24X Fiche 50-413,84/03/15,8403260034
- --8403250137 Proposed amends to proof & review Tech Specs, changing diesel furl oil surveillance requirements * Duke Power Co 84/03/15 9pp 22750 252 24X Fiche 50-413,84/03/15.8403260034
- 8403270213 Forwards response to followup questions from 840207 meeting re-environ qualification of 80 Obrian electrical penetrations Tests verify adequacy of Type K module for plant applications
 TUCKER: H B Duke Power Co 84/09/16 DENTON: H R Office of Nuclear Reactor Regulation, Director, ADENSAN, E G Licensing Branch 4 4pp 22770 273 24X Fiche 50-413.84/03/16.8403270213
- 8403260073 Forwards proposed amends to proof & review Tech Specs reverlification of position of inaccessible fire suppression & sprinkler sys valves, high radiation area & radiological environ monitoring program TUCKER.H.B. Duke Power Co. 84/03/20 DENTON.H.R. Office of Nuclear Reactor Regulation, Director ADENSAM.E.G. Licensing Branch 4. 1p 22745 284 24% Fiche 50-413.84/03/20,8403260073

- --8403260080 Proposed amends to proof & review Tech Specs re Action Statements & b & 19 b on position verification of inaccessible fire suppression & sprinkler sys valves, high radiation area & radialogical environ monitoring program * Duke Power Co 84/03/20 38pp 22746 285 24% Fiche 50-413,84/03/20.8403260073
- 8403270103 Ferwards test exemptions required to perform NUREO-0737,
 Item I Q 1, "Natural Circulation Testing "Exemptions need
 to be included in Tech Specs
 TUCKER.H B Duke Power Co 84/03/21 DENTON,H R Defice of
 Nuclear Reactor Regulation, Director ADENBAM.E Q Licensing Branch
 4 Spp 22766 341 24X Fiche 50-413,84/03/21.8403270103
- 8403300188 Provides plant-specific info & generic info omitted from Westinghouse Duners Group 831201 & 840312 ltrs.in response to Generic Ltr 83-10C Issues re reactor coolant pump trip resolved TUCKER.H B Duke Power Co 84/03/26 DENTON.H R Office of Nuclear Reactor Regulation, Director EISENHUT.D 9 Division of Licensing 3pp 22819 292 24X Fiche 50-413.84/03/26,8403300188
- B403300107 Forwards proprietary & honproprietary varsions of:
 "Methodology for Addressing Superheated Steam Releases to
 Ice Condenser Containments "Proprietary version withheld
 (raf 10CFR2 790)
 TUCKER. H B Duke Power Co 84/03/28 DENTON, H R Office of
 Nuclear Reactor Regulation, Director ADENGAM, E Q Licensing Branch
 4 2pp 22819 001 24% Fiche 50-413,84/03/28.8403300107
- --8403300116 Requests proprietary "Methodology for Addressing Superheated Steam Releases to Ice Condenser Containments," be withheld from public disclosure per 10CFR2 790 HIESEMANN.R A Hestinghouse Electric Corp 84/03/26 Denton, H R Deffice of Nuclear Reactor Regulation, Director 8pp 22819 003 24X Fiche 50-413,84/03/28,8403300107
- --B403300119'Nonproprietary, "Methodology for Addressing Superheated Steam Releases to Ice Condensor Containments" * Westinghouse Electric Corp 84/03/28 240pp 22819 011 24X Fishs 50-410,84/03/28.8403300107
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8403120153 Forwards revised Procedures SD-DP-003, "Process Control Program ." SD-DP-042. "Assembly & Disassembly Procedure " & 8D-DP-39, "Operating Procedure for Mobile Coment " per FSAR Question 460 11 & SER Section 11 4 1 TUCKER.H B Duke Power Co 83/10/28 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E O Licensing Branch 4 2pp 22586 185 24X Fiche 50-413,83/10/28.8403120153
- ---8403120154 Rev M to Procedure SD-DP-003, "Process Control for Chem-Nuclear Sys. Inc Cament Solidification Units "
 # Chem-Nuclear Systems, Inc 83/05/20 20pp 22586 187 24X
 Fichs 30-413,83/10/28.8403120153
- ---8403120158 Rev A to Procedure 8D-OP-042, "Assembly & Disassembly Procedure for Mobile Cement Solidification Unit 121 (MSU-C-121) "
 # Chem-Nuclear Systems, Inc 82/10/22 14pp 22586, 207 24X Fiche 50-413, 83/10/28, 8403120153
- --8403120161 Rev D to Procedure SD-UP-039, "Operating Procedure for Hobile Cement Solidification Unit 121 (M8U-C-121) " * Chem-Nuclear Systems, Inc 83/11/17 27pp 22586 221 24X Fichs 50-413, B3/10/28, 8403120153
- 8403010335 Discusses mods to emergency response guidelines in response to SER & NUREO-0737. Suppl 1
 TUCKER. H B Duke Power Co 84/02/22 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E 0 Licensing Branch 4 2pp 82432 324 24X Fiche 50-413, 84/02/22, 8403010335.
- 8403050377 Notification of 840306-08 site visit & meeting w/util in Charlotte,NC & York County,8C to audit equipment environ qualification (SER Outstanding Issue 4b)
 JABBOUR,K N Licensing Branch 4. 84/02/24. ADENSAM,E 0 Licensing Branch 4 3pp 22527 258 24X Fichs 50-413,84/02/24,8403050377
- 8403070422 Notification of 840312 meeting w/util & Westinghouse in Bethesda, ND to discuss resolution of main steam line break analysis (BER Confirmatory Issue 12) JABBOUR, K N Licensing Branch 4 84/02/24 ADENSAM, E. Q Licensing Branch 4 3pp 22566 300. 24X Fiche. 50-413, 84/02/24, 8403070422
- 8403020317 Forwards Rev 10 to "Analysis of Hydrogen Control Measures at McGuire Nuclear Station," per 88ER 7 (NUREG-0422).
 TUCKER, H B Duke Power Co 84/02/27 DENTION H R Office of Nuclear Reactor Regulation, Director ADENSAM, E Q. Licensing Branch 4 2pg. 22441:216 24X Fiche. 50-000, 84/02/29, 8403020317

- --8403020321 Rev 10 to "Analysis of Hydrogen Control Measures at McGuire Nuclear Station " * Duka Power Co 84/02/27 SOpp 22441 218 24X Fiche 50-000,84/02/29,8403020317
- 8403200078 Advises that all essential equipment cooled by nuclear syc water sys requalified for 100 F,per 831013 ltr re SER Open Item 2 TUCKER.H B Duke Power Co 84/03/13 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAM,E Q Licensing Brand 4, 1p 22699 155 24X Fiche 50-413,84/03/13,8403200078
 - Licensing Branch
- 8403200221 Requests NRC approval of proposed fire brigade organization
- 103200221 Regularia of The Regulation of Harmon, H. R. Office of TUCKER, H. B. Duke Power Co. 84/03/14 DENTON, H. R. Office of Nuclear Reactor Regulation, Director ADENSAM, E. Q. Licensing Branch 4 220 22700 022 24X Fiche, 50-413, 84/03/14, 8403200221
- 8403300077 Discusses redundant emergency lighting per SER Open Item 15 Lighting unnecessary in areas not manned during transient or accident conditions. Lighting available for maint in listed
 - areas TUCKER: H B. Duke Power Co 84/03/23 DENTON: H R Office of Nuclear Reactor Regulation, Director ADENBAH: E O Licensing 4. 2pp 22821 173. 24X Fiche 50-413,84/03/23,8403300079 Licensing Branch
- F. Security, medical, emergency & fire protection plans
- B403090254 Public version of revised crisis mgt plan implementing 903090x34 Public Version of revised crisis mgt plan implement procedures, including Procedures 5 3.4 re scheduling/planning support group, 5 3.4 re radiological support group & 5 3.7 re tachnical support group. W/831107 ltr & JM Felton memo TUCKER, H B. Duke Power Co. 83/10/31 271pp 22575 055 ; Fiche, 50-000,83/10/31,8403090254 22575 055 24X
- 8403060336 Revised emergency implementing procedures, including Procedures RP/O/A/5000/01 re classification of emergency, RP/O/A/5000/02 re notification of unusual event & RP/O/A/5000/03 re alert W/840227 ltr
 TUCKER.H B Duke Power Co 83/12/08 DENTON.H R Office of Nuclear Reactor Regulation, Director ADENSAM.E 0 Licensing 4. 198pp 22513 122 24X Fiche 50-413,83/12/08,8403040334 Licensing Branch
- 8403060225 Rev 11 to crisis mgt plan W/840224 ltr & public info pamphiet. VAUGHN: T E Duke Power Co 84/02/02 66pp 22516 189 24X Fiche 50-000,84/02/02,8403040225
- 8403280102 Public versian of revised emergency plan implementing procedures, including Procedure RP/0/A/5000/02 re notification of unusual event & RP/D/A/5000/03 re alert H/B40312 ltr & JH Felton 840321 release memo BDLGH, H.E., COX, J W, TUCKER, H.B. Duke Power Co. 84/02/06. DENTON: H R. Office of Nuclear Reactor Regulation, Director ADENSAM, E.O. Licensing Branch 4 267pp 22812 021 24X Fiche: 50-413,84/02/06,8403280102
- 84030i0335 Discusses mods to emergency response guidelines in response to SER & NUREG-0737.8uppl 1 TUCKER.H B. Duke Power Co 84/02/22 DENYDN.H.R Office of Nuclear Reactor Regulation, Director ADENSAM,E G Licensing Branch 4. 2pp. 22432-324 24X Fiche 30-413.84/02/22.8403010335.
- 8402090006 Board Notification 84-034. forwards R Voltmer 840206 memo to D Eisenhut re fire research results concerning fires in electrical cabinats in control room.
 EISENHUT.D 0 Division of Licensing 84/02/23 PALLADINO Commissioners. ip 22576 203 24X Fiche 50-000,84/02/23,8807090006. 8402090006.
- --B4030B0316 Recommends that info re fire research results concerning fires in electrical cabinets in control room be submitted for board notification per NRR Ofc Ltr 19, dtd B21001 Further evaluation of test data required.
 VOLLMER.R.H. Division of Engineering 84/02/.
 Division of Licensing. 10pp. 22376 204 24X
 Fiche: 50-000, 84/02/23.8402090006. 84/02/06. EISENHUT, D @
- 8403160086 Forwards IE Insp Repts 50-413/84-11 & 50-414/84-07 on 840131-0203. No violations or deviations identified DANCE: H C. Division of Project & Resident Programs, 84/02/27 TUCKER, H. B. Duke Power Co 2pp 22655:103 24X Fiche: 50-413, 84/02/27, 8403160086.
- -8403160092 IE Insp Repts 50-413/84-11 & 50-414/84-07 on 840131-0203 No violations or deviations identified Major areas inspected fire protection/prevention. MILLER, M.H. Region 2, Office of Director CONLON, T E. Division of Engineering & Operational Programs. 84/02/21 9pp 22655 10: 24X Fiche: 50-413, 84/02/27, 8403160086.

- 8403060419 Responds to EG Adensam 840120 ltr transmitting summary of fire protection site audit on 831101704 Fire protection sys valves will be locked in appropriate position since related circuitry not supervised per NFPA 72D TUCKER.H B Duke Pawer Co 84/02/29 DENTON,H R Office of NUCLER Reactor Regulation, Director ADENSAH,E O Licensing Branch 4 2pp 22518 190 24% Fiche 50-413.84/02/29,8403060419
- 8403050177 Forwards IE Insp Rept 50-413/84-24 on 840221-24 Noviolations or deviations identified DANCE. H C Division of Project & Resident Programs 84/03/01 TUCKER. H B Duke Power Co 2pp 22487 062 24X TUCKER, H B Duke Power Co 2pp 22487 062 Fiche 50-413,84/03/01,8403050177
- --B403050178 IE Insp Rept 50-413/B4-24 on B40221-24 No violations or deviations identified Major areas inspected review of preoperational activities re protected & vital area physical barriers Details withheld (ref 10CFR73 21) MOORE.D E Region 2. Office of Director MCGUIRE.D R Division of Emergency Preparedness & Materials Safety 84/03/01 ip 22489 064 24X Fiche 50-413,84/03/01,8403050177
- 8403160278 Extends invitation to attend 840316 workshop to discuss 9031602/B Extends invitation to attend \$40316 workshop to discus 10CFR50, App R requirements & results of recent insp to help resolve misunderstanding associated w/requirements LEHIS:R C Division of Project & Resident Programs 84/03/02 TUCKER.H B Duke Power Co 1p 22660 274 24X Fiche 50-000:84/03/02:8403160278
- 8403200221 Requests NRC approval of proposed fire brigade organization in SBER Duke Power Co 84/03/14 DENTON, HR Office of TUCKER, H B Duke Power Co 84/03/14 DENTON, HR Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 2pp 22700 022 24% Fichs 50-413,84/03/14.8403200221
- 8403260073 Forwards proposed amends to proof & review Tech Specs re verification of position of inaccessible fire suppression & sprinkler sys valves, high radiation area & radiological environ monitoring program
 TUCKER: H B Duke Power Co 84/03/20 DENTON, H R Office of
 Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch
 4 Ip 22746 284 24X Fiche 50-413,84/03/20,8403260073
- ~-8403260080 Proposed amends to proof & review Tech Specs re Action Statements 6 b & 17 b on position verification of inaccessible fire suppression & sprinkler sys valves, high radiation area & radiological environ monitoring program # Duke Power Co 84/03/20 38pp 22746 285 24% Fiche 50-413,84/03/20,8403260073
- G Adjudicatory correspondence
- 8403010207 Motion for extension of time Until 840323 to submit views on ASLB referral to ASLAD re rejection of Palmetto Ailiance contention on reliability of Transamerica Delaval diesel generators
 JCHNBQN.0 E Hearing Branch 4 84/02/29 Atomic Safety and
 Licensing Appeal Panel 5pp 22436 004 24% Fiche 50-413,84/02/29,
 8403010209
- 8403070033 Forwards joint proposed findings of fact & conclusions of law on Contentions PA44/CESG18 re reactor embrittlement & joint Contention DES17 re adverse weather RILEY, J Carolina Environmental Study Group RILEY, J Palmetto Alliance 84/02/27 KELLEY, J, FOSTER.R., PURDOM, P Atomic Safety and Licensing Board Panel 1p 22541 165 24X Ficha 50-413.84/02/27,8403070033
- --8403070037 Proposed findings of fact & conclusions of law in form of partial initial decision on Contentions PA44CES0 is reactor embrittlement & Contention DES17 re adverse weather reactor embrittiement & Contention DBS1 re adverse weather Certificate of Stv ancl.
 RILEY, J.L. Carolina Environmental Study Oroup GUILD, R. Palmett Alliance GUILD, G. Quild, R. 84/02/29 34pp 22541 166 24X Fiche 50-415,84/02/29,8403070033
- 8403140123 Forwards NRC insp repts & accompanying violation notices re facility QA Encl repts & notices issued after close of Dec 1983 hearings Palmetto Alliance served w/notices & util responses JOHNSUN, O E Hearing Branch 4 84/02/27 KELLEY, J L , PURDOM, P W , FOSTER, R F Atomic Safety and Licensing Board Panel 28pp 22624,040 24X Fiche 50-413,84/02/29,8403140123
- 8403070050 Order granting staff request for extension to & including 840323 of time within which to submit views re A8L8 830823 referral order in proceeding 8HOEMAKER, C J Atomic Safety and Licensing Appeal Panel 84/03/01 Office of the Executive Legal Director 2pp 22541 274. 24X Fiche 50-413,84/03/01,8403070050

- 8403060240 Forwards exercise evaluator document used in conjunction w/840215-16 emergency mgt exercise.NUREC-0654.Rev 1 & portion of community issues survey dealing w/emergency planning W/o encis
 SHEARIN.R V Duke Power Co 84/03/02 GUILD.R Palmetto Alliance RILEY.J L Affiliation Not Assigned 2pp 22516 197 24X
 Fiche 50-413.84/03/02.8403060240
- 840307004B Response opposing Carolina Environ Study Group 840214 offer of proof re reactor vessel technology, fatigue at high temp, strain gauge technology & structural integrity or LHR components Certificate of Svc smcl MCQARRY, J M Duke Power Co MCOARRY, J M Bishop, Liberman, Cook, Purcell & Reynolds 84/03/02 Atomic Safety and Licensing Board Panel 14pp 22541 235 24X Fiche 50-413,84/03/02,840307004B
- B403140043 Forwards J Smercak affidavit of nondisclosure for assistance in preparation of staff proposed findings W/o encl JUHNBON.G E Hearing Branch 4. B4/03/02 KELLEY.J L Atomic Safety and Licensing Board Panel ip 22633
- 8403090112 Forwards suppl to Palmetto Alliance proposed findings of fact & conclusions of law in form of partial initial decision Part V on honeycombing omitted due to in camera matl matley. Guild, R GUILD, R Palmetto Alliance 84/03/06 KELLEY, J. L. FOSTER, R F., PURDAM, P W Atomic Safety and Licensing Board Panel 38pp 22575 218 24X Fiche 50-413,84/03/06,840.030012
- --8403090ii5 Suppl to proposed findings of fact & conclusions of law in form of partial initial decision Certificate of Syc encl GUILD.R Palmetto Alliance GUILD.R Guild, R 84/03/06, 36pp. 22575 235 24% Fiche 50-413,84/03/06,8403090ii2
- 8403140124 Response opposing Carolina Environ Study Group 840216 motion to reopen record on reactor embrittlement Offer of proof as to matis acceptable Certificate of Svc encl JOHNSON.0 E Hearing Branch 4. 84/03/07. Atomic Safety and Licensing Board Panel 9pp 22620 288 24X Fiche:50-413.84/03/07.8403140124
- 8403140150 Notifies of 840313 enforcement conference in Atlanta, QA to inform licensee of welder 8 issue so corrective action may be commenced Meeting summary will be forwarded to ABLB & parties to proceeding
 JOHNSON, GE Hearing Branch 4 84/03/07 KELLEY, JL, FOSTER, RF, PURDON, PW Atomic Safety and Licensing Board Panel 1p
 22620 338 24X Fiche 50-413,84/03/07,8403140150
- B403140169 Informs of improper svc of Carolina Environ Study Group/ Palmetto Alliance proposed findings of fact & conclusions of law re adverse weather & nonreceipt of proposed findings on Contention 16 JOHNSON, O'E Hearing Branch 4. 84/03/07 KELLEY, J L , FOSTER, R F , PURDON, P W Atomic Safety and Licensing Board Panel ip 22620 333 24X Fiche 50-413,84/03/07,8403140169
- B403140046 Proposed findings of fact & conclusions of law in form of partial initial decision on Contention 6. Palmetto Alliance Contentions 16 & 44 & DES Contention 17 Certificate of Svc encl
 JDHNSUN.O.E Hearing Branch 4 84/03/08 210pp 22633.309 24X
 Fiche 50-413,84/03/08.8403140046
- 8403130071 Forwards applicant interrogatories & request to produce documents re diasel generator contention, per 840223 order Related correspondence CARR.A V. Duke Power Co 84/03/11 RILEY, J. Carolina Environmental Study Group GUILD.R Guild, R ip 22602 169 24X Fiche 50-413,84/03/11,8403130071
- --B403130077 Interrogatories & requests to produce documents on diesel generator contention to Carolina Environ Study Group & Palmetto Alliance Certificate of Svc encl Related correspondence Carthology Correspondence CARR.A V. Duke Power Co. 84/03/11 Carolina Environmental Study Group 27pp. 22602 170 24X Fichet30-413,84/03/11,8403130071
- 8403160027 Reply to intervenors & NRC staff proposed findings of fact & conclusions of law Certificate of Svc encl.
 MCGARRY. J. M. Duke Power Co. MCGARRY. L. M. Biskop, Liberman, Cook, Purcell & Reynolds 84/03/15 177pp 22654 123 24X
 Fiche: 50-413,84/03/15,8403160029.
- 8403190073 Forwards questions for FEMA witnesses to assist in preparation of testimony on offsite emergency planning contentions All testimony will be required to be filed on 840406 & 07 Hearing will commence on 840424. W/o encl MGOURREN.H J Hearing Branch 3 84/03/15 PERRY, 8 Federal Emergency Management Agency, ip 22666:135 24% Fiche. 90-413, 84/03/15, 8403190073

- 8403190174 Forwards "NRC Staff Supplemental Proposed Findings of Fact in Form of Partial Initial Decision on In Camera Issues re Contention & (8A)." per 840337 telcon W/o encl JOHNSON, O.E. Hearing Branch 4 84/03/15 KELLEY, J.L., FOSTER, R.F., PURDOM, P.W. Atomic Safety and Licensing Board Panel Ip 22671:162 287 Fiche 50-413,84/03/15.8403190174
- 8403200042 Memorandum & order danying motion to defer further action on two pending OL diesel generator contentions until after BSER issuance FOSTER.R F., PURDOM,P W., KELLEY, J L. Atomic Safety and Licensing Board Panel 84/03/16 Palmetto Alliance 3pp 22699 182 24X fiche 50-413,84/03/16.8403200042
- 8403200007 Interrogetories & requests to produce documents to Carolina Environ Study Group & Palmetto Alliance on ASLB contention re diesel generator reliability Certificate of Svc encl Related correspondence CARR.A V Duke Power Co CARR.A V Bishop, Liberman, Cook, Purcell & Reynolds 84/03/19 Carolina Environmental Study Group 21pp 22699 202. 24% Fiche 50-413,84/03/19,8403200007.
- 8403220237 Supplemental interrogatories to util re emergency diesel contentions admitted by ABLB Certificate of Svc encl Related correspondence
 RILEY.J L Carolina Environmental Study Oroup DBB 047 84/03/19
 Duke Power Co 5pp 22719.034 24X Fiche 50-413,84/03/19,840320237
- 8403220233 Interrogatories & requests to produce documents re diesel generator contentions to applicant & NRC staff Certificate of 8vc encl. Related correspondence GUILD.R Palmetto Alliance GUILD.R Carolina Environmental Study Group. GUILD.R Ouild.R DSB 047 84/03/22 Duke Power Co 20pp. 22719 014 24X Fiche 50-413.84/03/22,8403220233
- 8403270011 Notifies that svc list amended to reflect appointment of separate board for emergency planning Shearin 840302 ltr to Guild & Riley,840312 ltr to Guild & supplemental answers to interrogatories encl M/a encl Related correspondence SHEARIN.R V Duke Power Co DSB 114 84/03/22 MARQULIES,M B , LAZO,R M , HODPER,F F Atomic Safety and Licensing Board Panel 1p 22769 355 24X Fiche 50-413,84/03/22,8403270011
- 8403260367 Response to ASLB questions re whether memorandum referred to concerning diesel generators should be accepted & how ASLB should decide posed issues Referral request fails to satisfy interlocutory review test. Certificate of Buc enci. MCGARRY, J M Duke Power Co MCGARRY, J M Bishop, Liberman, Cook, Purcell & Reynolds DSB 083 84/03/23 55pp 22760 077 24X Fiche 50-413,84/03/23,8403260367
- 8403270322 Vigus on ABLB 840223 referral of 840217 rejection of generic aspects of intervenors dissel generator contention Certificate of Svc enci
 JOHNSON.0 E Hearing Branch 4. D88 132 84/03/23 84pp
 82787 069 24X Fiche 50-413.84/03/23.8403270322
- 8403270382 Motion to amené & suppl diesel generator contentions, or in alternative, motion for admission of new diesel generator contention ASLB urged to grant motion & admit recasted contention GUILD, R Palmetto Alliance DSB 192 84/03/23 Atomic 8afaty and Licensing Board Panel 11pp 22814 153 24x Fiche 50-413,84/03/23,8403270382
- 8403290388 Memorandum on emergency diesel generator questions referred per 100RR2,730 Acceptance of referral urged Certificate of svc encl
 QUILD.R Pelmetto Alliance QUILD.R Carolina Environmental Study
 Qroup QUILD.R Quild. R. D88 194
 84/03/23 29pp. 22814 283
 24X Fichs 50-413.84/03/23,8403290388.
- B403290379 Responses to util interrogatories & request to produce documents on dissel generator contention Certificate of Byc encl Related correspondence QUILD: R Palmetto Alliance QUILD: R Quild: R + Carolina Environmental Study Group DEB 191 B4/03/25 9pp 22814-144 24X Fiche. 50-413. B4/03/25, B403290379.

J Insurance & indomnity information

B403140037 Forwards Endorsement 9 to NELIA Policy NF-281, ROBBINS, J. G. Marsh & McLennan, Inc. B4/03/05 DINITZ, I Assistant Director for State & Licensee Relations, 2pp 22633:122, 24X Fiche 50-413,84/03/05,8403140037

M Antitrust correspondence

- B403080278 Forwards notice of finding of no significant antitrust changes & time for filing requests for reevaluation for transmittal to Ofc of FR for filing & publication REGAN: W H Site Analysis Branch 84/02/29 STUCKY. S W Docketing & Services Branch 1p 22584 062 24X Fiche 50-419,84/02/29. 8403080278
- --8403080283 Notice of finding of no significant antitrust changes & time for filling requests for reevaluation REGAN,W H Bite Analysis Branch 84/02/29 3pp 22584 063 24x Fichs 50-413.84/02/29.8403080278
- G Inspection reports, IE Bulletins & correspondence
- B4030B0203 Responds to FDIA request for documents from Mar 1977 Mar 1977 rs WR McAfae allegations Forwards App A documents Info also available in PDR FELTON, J.M Division of Rules and Records 84/01/24 GARDE, B P Government Accountability Project 2pp 22584 164 24X Fiche: 50-413, 84/01/24, 84030B0203
- --8403080212 Discusses 79:113-16 interviews w/craftsmen Interviewess selected by principal inspector, per TI 25:2/4 criteria Related info ancl.

 MURPHY.C E Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/12/04 THORNSURG, H D Director's Office, Office of Inspection and Enforcement 9pp 22584 166 24X Fichs.50-413,84/01/24,8403080203
- 8403070012 Forwards IE Insp Rept 50-413/84-05 on 840109-13 No violations or deviations noted DANCE: H C Division of Project & Resident Programs 84/02/13 TUCKER: H. B Duke Power Co 2pp 22529,001 24X Fiche 50-413,84/02/13,8403070012
- --8403070017 IE Insp Rept 50-413/84-05 on 840107-13 No violations or deviations noted Major areas inspected containment structural intergrity test & containment integrated leak rate test
 LENAMAN.J J., WHITENER.H L., JAPE.F Region 2, Office of Director 84/02/07, 7pp 22529 003 24X Fiche 50-413,84/02/13,8403070012
- 8403160343 Forwards IE Insp Repts 50-413/84-03 & 50-414/84-03 on 840103-06 & 11-13 No violations or deviations noted DANCE. H C Division of Project & Resident Programs 84/02/17 TUCKER H B Duke Power Co 2pp 22660 177 24X Fiche: 50-413, 84/02/17, 8403160343
- ---8403160356 Forwards IE Insp Repts 50-413/84-03 & 50-414/84-03 on 840103-06 & 11-13 No violations or deviations noted Proprietary review of document waived by util to assure distribution to parties in licensing proceeding DANCE, H C. Division of Project & Resident Programs 84/01/20 CARR, A V Duke Power Co 1p 22660 179 24X Fiche 50-413,84/02/17,8403160343
- --8403i60363 IE Insp Repts 50-413/84-03 & 50-414/84-03 on 840103-06 & it-13 No violations or deviations noted Major areas inspected containment spray-welding welding matl control & radiographic exam ECONOMOS, N. Region 2. Diffice of Director. BLAKE, J. J. Division of Engineering & Operational Programs 84/01/20 9pp 22660 180 24X Fiche 50-413,84/02/17,8403160343
- 8403070327 Ack receipt of 840120 itr informing NRC of steps taken to correct deviations noted in IE Insp Rept 50-413/83-45 DANCE: H C. Division of Project & Resident Programs. 84/02/22 TUCKER, H B Duke Power Co 1p 22546,315 24X Fiche: 50-413,84/02/22,8403070327
- --8403070331 Responds to NRC 831222 ltr re deviations noted in IE Insp. Rept 50-413/83-45 Corrective actions complete retest of ABME Code piping thermal expansion will be performed during precritical heatup of plant sys.

 THIEB, A C Duke Power Co 84/01/20 D'REILLY, J P Region 2, Dffice of Director 3pp 22546;316 24X Fiche 50-413,84/02/22,8403070327
- --8403070334 Forwards IE Insp Rept 50-413/83-45 on 831115-18 & notice of deviation DANCE, H.C Division of Project & Resident Programs 83/12/22 TUCKER, H.B Duke Power Co. 2pp. 22546 319 24X Fiche: 50-413, 84/02/22, 8403070327
- --8403070335 Notice of deviation from insp on 831115-18 * Region 2, Office of Director. 83/12/22 1p 22546:321 24X Fiche:50-413,84/02/22,8403070327

- --8403070338 IE Insp Rept 50-413/83-45 on 831115-18 Deviation identified failure to comply w/FBAR commitments for thermal expansion preoperational testing WHITENER, H L Region 2, Office of Director JAPE, F Division of Engineering & Operational Programs 83/12/20 6pp 22546-322 24X Fichs 50-413.84/02/22.8403070327
- B403070205 Ack receipt of B40123 ltr supplementing B3090B response informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/83-17 & 50-414/83-16 DANCE.H C Division of Project & Resident Programs 84/02/24 TUCKER.H B Duke Power Co ip 22538 359 24X Fiche 50-413.84/02/24,8403070205
- --8403070210 Forwards revised response to NRC 1tr re violations noted in IE Insp Repts 50-413/83-17 & 50-414/83-16 Corrective actions GA Procedure GA-140: "Inspector Cartification," will be revised TUCKER.H D Duke Power Co 84/01/23 O'REILLY, J P Region 2, Office of Director 2pp 22538 360 24X Fiche 50-413,84/02/24, 8403070205
- 8403160253 Informs that no circuit breakers w/undervoltage trip attachments in use in safety-related application other than reactor trip sys.in response to IE Bulletin 83-09 TUCKER, H B Duke Power Co 84702/24 O'REILLYJ P Region 2. Defice of Director Ip 22660 142 24X Fiche 50-413,84702/24.
- 8403i40360 Forwards IE Insp Rept 50-413/84-16 on 840206-10. No violations or deviations noted DANCE.H C Division of Project & Resident Programs 84/02/24 TUCKER,H B Duke Power Co 2pp 22660 193 24X Fiche: 50-413, 84/02/24, 8403160360
- --B403160370 IE Insp Rept 50-413/B4-16 on B40206-10 No violations or deviations noted Major areas inspected preoperational test results evaluation, reactor protection sys functional test procedure & engineered safeguard functional test TAYLOR.P A Region 2, Office of Director JAPE.F Division of Engineering & Operational Programs. B4/02/23 4pp 22660 175 24X Fiche 50-413.84/02/24.8403160360
- 8403160086 Forwards IE Insp Repts 50-413/84-11 & 50-414/84-07 on B40131-0203 No violations or deviations identified DANCE: H C Division of Project & Resident Programs 84/02/27 TUCKER H B Duke Power Co 2pp. 22655 103 24X Fiche. 50-413, 84/02/27, 8403160086
- --8403140092 IE Insp Repts 50-413/84-11 & 50-414/84-07 on 840131-0203 No violations or deviations identified Major areas inspected fire protection/prevention MILLER, W H Region 2. Office of Director CONLON, T E Division of Engineering & Operational Programs 84/02/21 9pp 22655 105 24X Fichs 50-413,84/02/27,8403140084
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list enc!

 JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22909 239 24X Fiche 50-000,84/02/28,8401190072
- 8403290143 Forwards IE Insp Rept 50-413/84-14 on 840204-09 No violations or deviations noted. DANCE.H C Division of Project & Resident Programs 84/02/28 TUCKER H B. Duke Power Co 2pp 22806-079 24X Fiche 50-413,84/02/28,8403290143
- --8403290i47 IE Insp Rept 30-4i3/84-14 on 840206-09 No violations or deviations noted Major areas inspected QC for chemistry & radiochemistry, including QC programs, chemistry lab & counting room facilities
 KUZO, 9 B Region 2, Office of Director, MONTGOMERY, D M Division of Engineering & Operational Programs 84/02/24 4pp 22806 081 24X Fiche 50-413,84/02/28,8403290143
- B403140123 Forwards NRC insp repts & accompanying violation notices refactiity GA Encl repts & notices issued after close of Dec 1983 hearings Palmetto Alliance served w/notices & util responses
 JOHNSON, O E Hearing Branch 4. 84/02/27 KELLEY, J L , PURDON, P W , FOSTER, R. F Atomic Safety and Licensing Board Panel 28pp 22624-040 24X Fiche 50-413,84/02/27,8403140123
- 8403160143 Forwards final response to IE Bulletin 77-14, Rev i Suppl 2 re GA program for seismic analysis of Beismic Catagory 1 piping sys
 TUCKER.H B Duke Power Co 84/02/27 O'REILLY, J P Region 2,
 Office of Director App 22655 3R1 24X Fiche 50-413, 84/02/29,

- 8403030177 Forwards 1E Insp Rept 30-413/84-24 on 840221-24 No violations or deviations identified DANCE, H C Division of Project & Resident Programs 84/03/01 TUCKER, H B Duke Power Co 2pp 22489 062 24X Fiche 50-413.84/03/01.8403050177
- --8403050178 IE Insp Rept 50-413/84-24 on 840221-24 No violations or deviations identified Major areas inspected review of preoperational activities re-protected & vital area physical barriers Details withheld (ref 10CFR79 21)
 MODRE-D E Region 2. Defice of Director MCGUIRE, D R Division of Emergency Preparedness & Makerials Safety 84/03/01 19
 22489 064 24x Fiche 50-413,84/03/01.8403050177
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Reve by DOT & NRC " Svc list encl GRACE.J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 327 24X Fiche 50-000,84/03/02,8402090007
- 8402090008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp. 22553 098 24X Fiche 50-000.84/03/02.8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases" Svc list encl JORDANAE L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/02 Consolidated Edison Co of New York, Inc 117pp 22553 217 24X Fiche 50-000.84/03/02.8402090009
- 8402090011 IE Info Notice 84-17, "Problems H/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 630103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22593 336 24X Fiche 50-000,84/03/05,8402090011
- 8403160211 Ack receipt of 840127 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-413/83-48 LEMIS.R C Division of Project & Resident Programs 84/03/05 TUCKER.H B Duke Power Co ip 22661 078 24X Fiche 50-413-84/03/05.8403160211
- --8403160216 Responds to NRC B31230 ltr re violations noted in IE Insp Rept 50-413/83-48 Violations denied Review of acceptance criteria statements in preoperational test procedures will be conducted TUCKER.H B Dute Power Co 84/01/27 O'REILLY,J P Region 2, Office of Director 3pp 22661 079 24X Fiche 50-413,84/03/05, 8403160211
- --B403160220 Forwards IE Insp Rept 50-413/B3-4B on B31116-21 & notice of violation LEMIS,R C Division of Project & Resident Programs B3/12/30 TUCKER, H B Duke Power Co 2pp 22661 0B2 24X Fiche 30-413, B4/03/05, B403160211
- --8403160221 Notice of violation from impp on 831116-21 * Region 2. Office of Director 83/12/30 ip 22661.084 24X Fiche 50-413,84/03/05.8403160211
- --8403160224 IE Insp Rept 50-413/B3-4B on 831116-21 Violation noted failure to provide adequate acceptance criteria for preoperational pressurizer dynamic response functional tast
 TAYLOR, P A Region 2, Office of Director. JAPE, F Division of Engineering & Operational Programs 83/12/19 App 22661 085 24X Fiche 50-413,84/03/05,8403160211
- 8402070024 IE Info Notice 84-09, Rev 1. "Lessons Leerned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 30-000, 84/03/07, 8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Bys " Svc list enel JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc (18pp 22584 186, 24X Fiche 50-000,84/03/07,8402090028
- 8403160273 Ack receipt of 840215 ltr informing NRC of steps taken to correct violations noted in IE Insp Regts 50-413/83-52 & 50-414/83-39 LEMIS:R C Division of Project & Resident Programs 84/03/08 TUCKER:H B Duke Power Co 1p. 22660/124 24X Fichs:50-413:84/03/08:8403160293

L., 18

- --8403160299 Responds to NRC 840117 ltr re violations noted in IE Insp. Repts 50-413/83-52 & 50-414/83-39 Corrective actions GA. Procedure GA-130 revised to assure that util written qualifications for auditors in full compliance w/codes. TUCKER.H B. Duke Power Co. 84/02/15 O'REILLY, J.P. Region 2. Office of Director 2pp. 22660 125 24X Fichs 50-413, 84/03/08, 8803160293
- --8403160307 Forwards IE Insp Repts 50-413/83-52 & 50-414/83-39 on 831212-16 & notice of violation LEWIB.R C Division of Project & Resident Programs 84/01/17 TUCKER.H B Duke Power Co 2pp 22660 127 24X Fiche 50-413.84/03/08:8403160293
- --8403160314 Notice of violation from insp on 831212-16 * Region 2, Office of Director 84/01/17 ip 22660 i29 24X Fiche 50-413,84/03/08,8403160293
- --8403160319 IE Insp Repts 50-413/83-52 & 50-414/83-39 on 831212-16 Violation noted failure to establish personnel qualifications for auditors BELISTE,0 A , FOSTER,L , SMITH,C Region 2, Office of Director 84/01/13 12pp 22660 130 24X Fiche 50-413,84/03/08,8403160293.
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl DEYGUNG.R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp. 22823 094 24% Ficha 50-000.84/03/12:8402090031
- 8403270270 Ack receipt of 840305 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/83-21 & 50-414/83-22 LEWIS.R.C Division of Project & Resident Programs 84/03/15 TUCKER.H B Duke Power Co 1p 22800 020 24X Fiche 50-413.84/03/15,8403270270
- --B403270276 Responds to NRC B30912 ltr re violations noted in IE Insp Repts 50-413/83-21 & 50-414/83-22. Corrective actions QC insp criteria for cable pulling revised to clarify insps of cable bending radius & Unsupported length during routing TUCKER.H D Duke Power Co B4/03/05 O'REILLY, J P Region 2, Office of Director 3pp 22800 021 24X Fiche 50-413,84/03/15, 8403270270
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities." Svc list encl, JRBDAN,E L Division of Emrgency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Sefety-Related Sys " Svc list enc! JÜRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22733 001 24X Ficha 50-000,84/03/21,8402090044
- R Periodic operating reports & related correspondence
- 8403020443 Forwards monthly status rept of offsite emergency preparathess for OL reviews for Jan 1984 Changes in FEMA finding dates not caused by delay due to offsite emergency planning issues
 DIRCKB:W J Office of the Executive Director for Operations 84/02/21 PALLADINO Commissioners 9pp. 22492 083 24X Fiche 50-000,84/02/21,8403020443.
- 9. Reportable occurrences, LERs & related correspondence
- B403010451 Informs Commission of problems w/amergency diesel generators mfg by Transamerica Delaval, Inc DIRCKB.W J Office of the Executive Director for Operations BECY-83-034 84/01/25 4pp 2243B 347 24X Fiche, 50-000, 84/01/25, 8403010451
- 84D3010140 Significant Deficiency Rept 8D 413-414/84-02 reunconsidered effects of superheated steam possibly resulting in increased lower containment temp Meeting on 840312 requested TUCKER, H B Duke Power Co. 84/02/17 D'REILLY, J. P. Region 2, Office of Director. 2pp 22435 322 24X Fiche: 50-413, 84/02/17, 8403010140
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines, Gimpel NPB-4 T&T valve.to close, Encl 1tr dtd 840203 sent to listed utils OE notified of affected units in BWR plants
 THERGUX, R R Terry Corp 84/02/22. WOODRUFF, R. W Director's Office, Office of Inspection and Enforcement 6pp 22706:327. 24X Fiche 50-000, 84/02/22, 8403210032

- 8403090226 Bignificant Deficiency Rept 413-414/82-04 amending corrective actions to previously submitted rept Reinap of inaccessible deficient supports may be waived if documented evaluation of design analysis provided TUCKER, H B Duke Power Co 84/02/24 O'REILLY, J P Region 2, Office of Director 2pp 22373 261 24X Fiche 50-413,84/02/24,84030902026
- 8403010207 Forwards "Investigation of Types AF & AE Piston Skirts," per Transamerica Delaval. Inc Owners Group program commitments Rept evaluates cracks in AF piston skirts in Shoreham & Orand Oulf Nuclear Power Stations MUSELER, W J TDI (Transamerica Delaval, Inc) Gwners Group 84/02/27 DENTON. H R Defice of Nuclear Reactor Regulation, Director 3pp 28434 090 24X Fiche 50-000, 84/02/27, 8403010207
- 8403070241 Interim Significant Deficiency Repts SD-413/82-27 & SD-414/82-27 re cracked cell containers Six cracked cells returned to Nife for investigation & resolution Site personnel will conduct weekly battery insp TUCKER, H B Duke Power Co 84/02/27 O'REILLY, J P Region 2, Office of Director 2pp 22572 302 24X Fiche 50-413,84/02/27,8403090241
- B402090021 Board Notification 84-039 discusses NRC 840210 & 16 meetings W/Transamerica Delaval.Inc Emergency Diesel Generators Owners Group Meeting scheduled on 840308 for finalization of generic program plan prior to NRC review EISENHUT.D.9 Division of Licensing 84/02/28 PALLADING Commissioners 5pp 22946 003 24X Fiche 50-000,84/02/28, 8402090021
- 8403010218 Forwards task descriptions for 16 known problems re Transamerica Delaval, Inc emergency diesel generators MUSELER, W J TDI (Transamerica Delaval, Inc) Owners Group 84/02/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 42pp 22435 177 24X Fichs 50-000,84/02/28,8403010218
- 8402070020 Board Notification 84-044 forwards Part 21 rept re Transamerica Delaval.Inc turbocharger thrust bearing lubrication defect resulting in engine nonavailability EISENHUT.D G Division of Licensing 84/02/29 PALLADINU. OLLINSKY, ROBERTS Commissioners 4pp 22541 263 24X Fiche 50-000.84/02/29.8402070020
- 8403140048 Forwards "Grand Gulf Component Tracking Sys," "Shoreham Component Tracking Sys" & "Transamerica Delaval, Inc Diesel Generators Gwners Group Program Plan," to resolve concerns w/emergency diesel generators MUSELER, W J Long Island Lighting Co 84/03/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22626 062 24X Fichs 30-000,84/03/02,8403140048
- --8403140095 "Transamerica Delaval, Inc Digsel Generators Clumers Group Frogram Plan "
 * TDI (Transamerica Delaval, Inc.) Clumers Group, 84/03/02 261pp 22628 223 24X Fiche 50-000,84/03/02,8403140048
- 8403190128 Update of Significant Deficiency Rept 414/82-25 Item should be renumbered 413-414/82-25 All necessary actions completed TUCKER.H B Duke Power Co 84/03/02 O'REILLY, J P Region 2, Office of Director 1p 22639.332. 24X Fiche 50-413,84/03/02, 8403150128
- 8403150065 Final Significant Deficiency Rept SD 413/83-07 re vent/drain valve installation & insp GA inspectors retrained Vent/drains inspected prior to 830713 reinspected to verify that intent of Design Drawing CN-1680-47 met TUCKER H B Duke Power Co. 84/03/05 O'REILLY, J P Region 2, Office of Director Spp 22646 019 24X Fiche 50-413,84/03/05,8403150065
- 8402090033 Board Notification 84-047 forwards Transamerica Delaval, Inc Bumars Group piston skirt rept & task descriptions. EIEENHUT. D G Division of Licensing, 84/03/07 PALLADING Commissioners App 22674 221 24X Fichs 50-000,84/03/07, 8402090033
- 8403140122 Part 21 rept re status update concerning abnormal wear on linear converters Test program underway Results of investigation indicate excessive wear caused by hunting of control circuitry

 BODSON: J P Facific Air Products Co B4/03/09. Director's Office, Office of Inspection and Enforcement 7pp 22624 068 24X Fichs 50-000, 84/03/09, 8403140122.
- 8402090038 Board Notification 84-051 forwards "Transamerica Delaval, Inc (TDI) Diesel Generators Owners Group Program Plan " EIBENHUT, D G Division of Licensing 84/03/12 PALLADINO Commissioners 5pp. 22488 214 24X Fiche 50-000,84/03/12, 8402090038.

- 8402090039 Board Notification 84-032 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delaval.Inc (TDI) Comers Group Distribution list encl EISENHUT.D 0 Division of Licensing 84/03/12 PALLADIND Commissioners 5pp 22708 001 24X Fiche 30-000,84/03/12,8402090039
- --8403050536 Forwards summary of 840210 meeting w/Transamerica Delavat. Inc Dumers Group in Bethesda, MD re problems w/emergency diesel generators
 CARUSO.R Licensing Branch 2 84/02/27 O'REILLY, J P NRC No Detailed Affiliation Given 6pp 28708 006 24X
 Fiche 50-000,84/03/12,8402090039
- --8403060554 Transcript of B40210 meeting w/Transamerica Delaval, Inc Owners Group in Bothesda, MD re problems w/emergency diesel generators * NRC - No Detailed Affiliation Given 84/02/10 147pp 67201 008 24X Fiche 50-000,84/03/12,8402090039
- --8403070409 Summary of 840216 meeting w/Transamerica Delaval, Inc Owners Group in Wading River, NY re program plan to establish reliability of diesel generators Agenda, meeting transcript & attendance list encl.
 MILLER, M.A. Licensing Branch 4 84/02/27 Licensing Branch 4 8pp 22708 161 24% Fiche 50-000,84/03/12,8402090039
- --8403070423 Transcript of 840216 conference in Wading River,NY re Transamerica Delaval, Inc diesel generators Pp 1-82 * Commissioners 84/02/16 84pp 22708 169 24X Fiche 50-000,84/03/12,8402070039
- 8403140050 Forwards "Design Review of Connecting Rod Bearing Shells for Transamerica Dalaval Enterprise Engines" for Shoreham & Grand Gulf dissel generators MUSELER.W J Long Island Lighting Co 84/03/12 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 22632 074 24% Fiche 50-000, 84/03/12, 8403140050
- 8403130133 Forwards "Transamerica Delaval, Inq Diesel Generator Rocker Arm Capscrew Stress Analysis Rept " Capscrew design adequate for applicable engines & svc conditions MUSELER, W J TDI (Transamerica Delaval, Inc.) Owners Group 84/03/13 DENTON.H R Office of Nurlear Reactor Regulation, Director 2pp 22639 270 24% Fiche 50-000,84/03/13,8403150133
- B403270244 Final Significant Deficiency Rept 5D 413-414/83-14 re seal conduit connection to safety-related equipment located in harsh environs Initially reported on B31102 Util continuing to evaluate alternative sealing methods
 TUCKER. H B Duke Power Co B4/03/15 O'REILLY, J P Region 2, Office of Director 3pp 28800 224 24X Fiche 50-413,84/03/15,8403270244
- 8403200222 Responds to 840214 Requests for Info 1 & 2 re R-4 series engines List indicating engine number, model & svc number, customer name & address, rating, date shipped & data started encl
 MATHEMS, C S Transamerica Delaval, Inc 84/03/16 EISENHUT, D G Division of Licensing 20pp 22671 179 24X Fiche 50-000,84/03/16, 8403200222
- 8403300126 Final Significant Deficiency Rept 413/82-07 re overtorquing of ITT-Philips concrete expansion anchors to close excessive plate to concrete gaps on pipe support Initially reported on 820210 Anchors will be retorqued TUCKER, H B. Duke Power Co 84/03/16 O'REILLY, J P Region 2, Defice of Director. Spp 22819 357 24% Fiche 50-413,84/03/16, 8403300126
- 8403270132 Forwards "Emergency Diesel Generator Air Start Valve Capscrew Dimension & Stress Analysis," prepared by S&W for Transamerica Delaval. Inc (TDI) Diesel Generator Owners Group MUSELER.N J TDI (Transamerica Delaval, Inc.) Owners Group 84/03/23 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 22774 001 24X Fiche 50-000.84/03/23,8403270132
- 8403270134 Requests meeting on 840418 to discuss short-term & long-term corrective actions & investigations re Transamerica Delaval diesel generators List of suggested meeting topics encl.

 MCGAUGHY, J. P TDI (Transamerica Delaval, Inc.) Owners Group 84/03/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 22769 133 24X Fiche 50-000,84/03/23,8403270134

T Hearing transcripts on non-antitrust matters

- B402090039 Board Notification B4-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delaval, Inc (TDI) Duners Group Distribution list encl.

 EISENHUT, D G Division of Licensing 84/03/12 PALLADING Commissioners 5pp 22708 001, 24X Fiche 50-000, B4/03/12, 8402090039
- --B403060536 Forwards summary of 840210 meeting w/Transamerica Delaval.
 Inc Duners Group in Bethesda.HD re problems w/emergency
 dises! generators
 CARUSO.R Licensing Branch 2 84/02/27 D'REILLY, J P NRC No
 Detailed Affiliation Given 6pp 22708 006 24X
 Fiche 50-000,84/03/12.8402070037
- --8403060554 Transcript of 840210 meeting w/Transamerica Deleval. Inc Owners Group in Bethesda. HD re problems w/emergency diesel generators * NRC - No Detailed Affiliation Given 84/02/10 147pp 67201.008 24X Fiche 50-000,84/03/12.8402090039
- --8403070409 Summary of 840216 meeting w/Transamerica Delaval, Inc Dumers Group in Wading River,NY re program plan to establish reliability of diesel generators Agenda,meeting transcript & attendance list encl MILLER,M A Licensing Branch 4 84/02/27 Licensing Branch 4 Bpp 22708 161 24% Fiche 50-000,84/03/12,8402090039
- --8403070423 Transcript of B40216 conference in Wading River,NY re Transamerica Delayal, Inc diesel generators Pp 1-82 * Commissioners 84/02/16 84pp 22708 169 24X Fiche 30-000,84/03/12,8402090039
- 8403140236 Transcript of 840314 telcon re facility Pp 12,580-12,624 * Atomic Safety and Licensing Board Panel 84/03/14, 45pp. 22660 208 24x Fiche 50-413,84/03/14,8403160236
- 8403260251 Transcript of 840321 talephons conference in Bethesda.MD Pp 1-24 * Atomic Safety and Licensing Board Panel 84/03/21 28pp 22754 283 24X Fiche 50-413.84/03/21,8403260251
- DOCKET 50-414 CATANBA NUCLEAR STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8403080196 FDIA request for documents re WR McAfee allegations involving facility from Mar 1977 ~ Mar 1979, NRC open conference at site in Nov 1979 & review of wtil topical QA manual QARDE, B P , ANSELL, E Government Accountability Project 83/11/21 Diffice of Administration 2pp 2284 162 24X Fiche 30-413.83/11/21.8403080196
- 8403050477 Notification of 840313 meeting w/util in York County, SC to conduct confirmatory site visit per Section 13 & of SRP (NVREG-0800) JABBORN, K N Licensing Branch 4 84/02/24 ADENSAM, E O Licensing Branch 4 3pp 22547 340 24X Fiche 50-413,84/02/24,8403060477
- 8402070017 Board Notification 84-038 forwards RJ Mattson 840123 memo to BO Eisenbut providing status update of NRC actions re Hestinghouse ECCS actuation logic EISENUTY.D 0 Division of Licensing 84/02/27 PALLADIND Commissioners 7pp 22346 007. 24X Fichs 50-000,84/02/27,
- 8403070185 Forwards equipment data sheets for SORT & pump & valve operability review team onsite audits Qualification of components complete Wiftve oversize drawings Aperture cards are available in PDR TUCKER, H B DUR Power Co. 84/02/28 BENTON-H R. Office of Nuclear Reactor Regulation, Director ADENSAM.E. Q. Licensing Branch 4 601pp 22536 281 24% Fiche 50-413,84/02/28,8403070185.
- ---8403070202 Rev 10 to Procedure CNS-1390 01-00-0073, "Installation Spec Manual Mechanical Installation Procedure for Electrical Penatration Types B.C. D.F. G.H. J. K.L. & H " & Duke Power Co 83/08/24 36pp 22537 087 24X Fiche 50-413,84/02/28,8403070185
- --8403070219 Rev B to Procedure CNS-1390 01-00-0071, "Procedure for Installation of Type A (6,900 Volt) Electric Penetration Assemblies "
 DDVER:R P Dute Power Co. 83/03/07 350pp 22537-167. 24X Fiche: 50-413,84/02/28,8403070185

- 8402090016 Board Natification 84-031 informs that Commission received affidavit from former util employee alleging that util deliberately undermined GA program at facilities Investigation in programs.

 NOVAK.T M Assistant Director for Licensing 84/02/29 KELLYNJ, PURDOM.P. FOSTER.R Atomic Safety and Licensing Board Panel 3pp 67217 043 24X Fiche 50-413,84/02/29,8402090016
- 8403190394 Forwards nonproprietary & proprietary "Technical Basis for Eliminating Pressurizer Surge Line Ruptures as Structural Design Basis for Catawba, Units 1 & 2 " Revised FBAR pages also encl Proprietary rept withheld (ref 100FR2 790)
 TUCKER.H B Duke Power Co 84/02/29 DENTON.H R Office of Nuclear Reactor Regulation, Director ADEMSANE 0 Licensing Brench 4 Jpp 22674 089 24X Fiche 50-413.84/02/29,8403190394
- --8403190399 Application for withholding proprietary rept HCAP-10487,
 "Technical Basis for Eliminating Pressurizer Surge Line
 Ruptures as Structural Design Basis "
 MIESEMANN.R A Westinghouse Electric Corp 84/02/15. DENTON.H R

 Office of Nuclear Reactor Regulation Director. 9pp 22674:092
 24X Fiche 50-413.84/02/29,8403190394
- --8403170404 Nonproprietary "Technical Basis for Eliminating Pressuritar Surge Line Ruptures as Structural Dasign Basis for Catamba Units 1 & 2" SHAMY, 8 A , YANG, C Y. SANE, A D. Wastinghouse Electric Gorp HCAP-10488 (NP) 84/02/10 107pp 22674.101. 24X Ficha 50-413,84/02/29,8403170374
- 8403060422 Provides second suppl to 831118 submittal & addl info on positive aspects of elimination of arbitrary intermediate pipe breaks from facilities
 TUCKER, H. B. Duke Power Co. 84/03/01. DENTON, H.R. Office of Nuclear Reactor Regulation, Director ADENSAN, E. Q. Licensing Branch
 4 29p 28511 357 24X Ficher 50~413,84/03/01,8403060422
- 8403190257 Forwards "Steam Prassure Suppression Characteristics of Water-Soluble Plastic Membrane Shielded Ice for Ice Condenser Containment Nuclear Power Plants "TUCKER, H.B. Duke Power Co. 84/03/07 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 7pp. 22672 102 24X Fiche 50-000,84/03/07,8403190257
- 8403280122 Summary of 840224 meeting w/Hestinghouse Owners Oroup in Bethesda, MD re proposed Hestinghouse steam generator tube rupture generic program Attendee list & agenda encl NERSES, V Licensing Branch 3, 84/03/07 Licensing Branch 3 35pp 22811 131 24X Fiche 50-000,84/03/07,8403280122.
- 8403130104 Provides clarification of third paragraph of 840229 ltr repossibility of welded piping attachments being located include proximity to eliminated arbitrary intermediate breaks TUCKER: H B Duke Power Co 84/03/08 DENTON: H R Office of Nuclear Reactor Regulation: Director ADEMSAN: E 9. Licensing Branch 4 2pp 28200 256 24K Fichs 50-413,84/03/08.8403130140
- B403i60197 Forwards responses to EQ Adensem 820401 request for qualification documentation re operability of containment purge & vent valves in Modes i -4 per Tech Spec 3 6.1 9
 TUCKER.H B Duke Power Co. 84/03/12 DENTON.H.R GPFice of Nuclear Reactor Regulation, Director ADENSAH,E.@ Licensing Branch 4 333pp 22638 185 24X Fiche 50-410,84/03/12,8403160197
- 8402070041 Board Notification 84-050 provides Commission policy statement & proposed rulemaking on environ qualifications FISENHUT, D G Division of Licensing 84/03/14 Atomic Safety and Licensing Board Fanel 10pp 24% Fiche 50-000;84/03/14;8402070041.
- 8403200165 Forwards summary of experience for operations personnel to be licensed on Unit 1.per 840114 & 0226 commitments Based on operating shift experience requirements sufficient experience available to startup & operate Unit 1 TUCKER.H.B. Duke Power Co. 84/03/14. DENTON.H.R. Office of Nuclear Resctor Regulation, Director ADENSAH.E.O. Licensing Branch 4 120p 22697 001. 24X Fiche.50-413.84/03/14.8403200165
- 8403220074 Requests that snubber Tech Specs be written to reflect insponunt basis instead of current sys basis. Conclusions from review of J Sapir 740301 ltr re Tech Specs for snubber operability & surveillance listed TUCKER.H B Duke Power Co 84/03/15 DENTON.H.R. Office of Nuclear Reactor Regulation. Director ADENSAM.E 0. Licensing Branch 2pp 22712-306 24X Fichs: 50-413,84/03/15,8403220074.
- 8403270213 Forwards response to followup questions from 840209 meeting re environ qualification of DO Obrian electrical penetrations Tests verify adequacy of Type K module for plant applications.

 TUCKER: H B Duke Power Co. 84/03/16, DENTON, H. R. Office of Nuclear Reactor Regulations Director. ADENSAM, E. O. Licensing Branch 4 4pp. 22770:273 24X Fichs 50-413.84/03/16,8403270213.

- 8403300188 Provides plant-specific info & generic info omitted from Hestinghouse Owners Group 831201 & 840312 ltrs.in response to Generic Ltr 83-10C Issues re reactor coolant pump trip resolved
 - resolved
 TUCKER, H B Duks Power Co 84/03/26 DENTON, H R. Office of
 Nuclear Reactor Regulation, Director EISENHUT, D G Division of
 Licensing 3pp 22819 292 24X Fiche 50-413,84/03/26,8403300188
- 8403300107 Forwards proprietary & nonproprietary versions of,
 "Methodology for Addressing Superheated Steam Releases to
 Ice Condenser Containments " Proprietary version withhold
 (ref 10CFR2 790)
 TUCKER, H. B Duke Power Co 64/03/28 DENTON, H R Office of
 Nuclear Reactor Regulation, Director ADENSAM.E 0 Licensing Branch
 4 2pp. 22817 001 24X Fiche 50-413,84/03/28.8403300107
- --8403300116 Requests proprietary "Methodology for Addressing Superheated Steam Releases to Ice Condenser Containments," be withheld from public disclosure per IOCFR2 790
 WIESEMANN,R.A. Westinghouse Electric Corp. 84/03/26. DENTON,H.R.
 Office of Nuclear Reactor Regulation, Director. 8pp. 22819 003
 24X Fiche: 50-413,84/03/28,8403300107
- --8403300117 Nonproprietary, "Methodology for Addressing Superheated Steam Releases to Ice Condenser Containments" # Westinghouse Electric Corp 84/03/28 240pp 22819.011. 24X Fiche.50-413,84/03/28.8403300107
- E NRC Safety Evaluation Report (SER); suppls & correspondence
- 8403120133 Forwards revised Procedures SD-DP-003, "Process Control Program ," SD-DP-042, "Assembly & Disassembly Procedure " & SD-DP-042, "Operating Procedure for Mobile Comments. " per FSAR Question 460 11 & SER Section 11.4 1. TUCKER, H. B. Duke Power Co 83/10/28, DENTON, H.R. Diffice of Nuclear Reactor Regulation, Director ADENSAME 0, Licensing Branch 4 2pp. 22586 185. 24X Fiche 50-413,83/10/28,8403120153
- B403010335 Discusses mode to emergency response guidelines in response to SER & NUREG-0737. Suppl i TUCKER. H. B. Duke Power Co B4/02/22 DENTON, H R. Office of Nuclear Reactor Regulation, Director 2pp 22432 324. 24X Fiche: 50-413, 84/02/22, 8403010335
- 8403050377 Notification of 840306-08 site visit & meeting w/util in Charlotte.NC & York County.80 to audit equipment environ qualification (SER Outstanding Issue 4b)
 JABBOUR, K N. Licensing Branch 4. 84/02/24 ADENBAM, E G. Licensing Branch 4. 3pp. 22527.258 24X Ficha 50-413,84/02/24,8403050377
- 8403070422 Notification of 840312 meeting w/util & Westinghouse in Bethasda.MD to discuss resolution of main steam line break analysis (SER Confirmatory Issue 12) JABBOUR,K.N. Licensing Branch 4 84702/24, ADENSAM, E 9 Licensing Branch 4. 3pp. 22566:300 24X Fichs:50-413.84/02/24, 8403070422
- 8403020317 Forwards Rev 10 to "Analysis of Hydrogen Control Measures at McQuire Nuclear Station," per SSER 7 (NUREQ-0422) TUCKER, H B Duke Power Co. 84/02/29 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp. 22441 216 24X Fiche: 50-000,84/02/29,8403020317
- --B403020321 Rev 10 to "Analysis of Hydrogen Control Measures at McGuire Nuclear Station," * Duke Power Co. B4/02/29, 50pp 22441.218 24X Fiche: 50-000,84/02/29,8403020317
- 840320907B Advises that all essential equipment cooled by nuclear svc water sys requalified for 100 F,ppr 831013 ltr re SER Open Item 2.
 TUCKER,H.B. Duke Power Co., 84/03/13 DENTON,H.R. Defice of Nuclear Reactor Regulation, Director ADENBAM,E 0 Licensing Branch 4. 1p. 22699,155, 24X Fiche 50-413,84/03/13,8403200078
- 8403200221 Requests NRC approval of proposed fire brigade organization in SBER. TUCKER, H B. Duke Power Co. 84/03/14. DENTON, H R. Office of Nuclear Reactor Regulation, Director 2pp 22700, Q22. 24X Fiche, 50~413,84/03/14,8403200221.
- 8403300079 Discusses redundant emergency lighting per SER Open Item 15
 Lighting unnecessary in areas not manned during transfent or
 accident conditions Lighting available for maint in listed
 areas.
 TUCKER H. B. Duke Power Co. 84/03/29 DENTON.H.R Office of
 Nuclear Reactor Regulation, Director ADENSAM.E.Q Licensing Branch
 4. 2pp 22821:173 24X Fiche 50-413,84/03/23,84033000079

- F Security, medical, emergency & fire protection plans
- 8403070254 Public version of revised crisis mgt plan implementing procedures: including Procedures 5 3 4 re scheduling/planning support group, 5 3 6 re radiological support group & 5 3 7 re technical support group W/831107 ltr & JM Felton memo TUCKER, H B Duke Power Co 83/10/31 271pp 22595 055 24x Fiche 50-000.83/10/31.8403090254
- 8403060336 Revised emergency implementing procedures.including Procedures RP/0/A/5000/01 re classification of emergency. RP/0/A/5000/02 re matification of unusual event & RP/0/A/5000/03 re alort W/840227 ltr
 TUCKER.H B Duke Power Co 83/12/08 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENBAN,E G Licensing Branch 4 198pp. 22513 122 24% Fiche 50-413,83/12/08,8403040336
- 8403060225 Rev 11 to crisis mgt plan W/840224 ltr & public info pamphlet VAUGHN.T E Duke Power Co 84/02/02 66pp 22516 189. 24X Fiche 50-000,84/02/02,8403060225
- 8403280102 Public version of revised emergency plan implementing procedures, including Procedure RP/D/A/5000/02 resulting procedures and procedures are represented by the second resulting to the second resulting and resulting and resulting and resulting and resulting are resulting as a second resulting and resulting are resulting as a second resulting and resulting procedures are resulting as a second resulting and resulting are resulting as a second resulting and resulting are resulting as a second resulting are resulting as a second resulting as a second resulting and resulting are resulting as a second resulting are resulting as a second resulting are resulting as a second resulting as a seco
- 8403010335 Discusses mods to emergency response guidelines in response to SER & NUREG-0737. Suppl 1
 TUCKER. H B Duke Power Co 84/02/22 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 2pp. 22432: 324 24X Fiche 50-413.84/02/22.8403010335
- 8402070004 Board Notification 84-034 forwards R Vollmer 840206 memo to D Eisenhut re fire research results concerning fires in electrical cabinets in control room EISENHUT. D G. Division of Licensing 84/02/23 PALLADING Commissioners Ip 22576 203 24X Fiche 50-000, 84/02/23. 8402070006
- --8403080316 Recommends that info re fire research results concerning fires in electrical cabinets in control room be submitted for board notification.per NRR Ofc Ltr 19,4td 821001 Further evaluation of test data required VOLLMER, R H Division of Engineering 84/02/06 EISENHUT, D G Division of Licensing 10pp 22576 204 24X Fiche 50-000,84/02/23,8402090006
- 8403160086 Forwards IE Insp Repts 50-413/84-11 & 50-414/84-07 on 840131-0203 No violations or deviations identified DANCE: H C Division of Project & Resident Programs 84/02/27 TUCKER: H B Duke Power Co 2pp 22655 103 24X Fiche 50-413.84/02/27.8403160086
- --8403160092 IE Insp Repts 50-413/84-11 & 50-414/84-07 on 840131-0203 No violations or deviations identified Major areas inspected firm protection/prevention MILLER.M.H. Region 2. Office of Director 84/02/21 9pp 22655-105 24X Fiche 50-413,84/02/27,8403160086
- 8403040419 Responds to EO Adensam 840120 ltr transmitting summary of fire protection site audit on 831101-04 Fire protection sys valves will be locked in appropriate position since related circuitry not supervised per NFPA 72D TUCKER, H.B. Duke Power Co. 84/02/29 DENTON, H.R. Office of Nuclear Reactor Regulation, Director ADENSAM, E.G. Licensing Branch 4 2pp 22518:170 24X Fiche 50-413,84/02/29,8403040419
- 8403160278 Extends invitation to attend 840316 workshop to discuss 10CFR50. App R requirements & results of recent insp to help resolve misunderstanding associated whrequirements LEWISHR.C Division of Project & Resident Programs 84/03/02 TUCKER.H B. Duke Power Co. 19 22660 274 24X Ficher 50-000.84/03/02.8403160278
- 8403200221 Requests NRC approval of proposed fire brigade organization in SBER. TUCKER, H.B. Duke Power Co. 84/03/14 DENTON, H.R. Office of Nuclear Reactor Regulation, Director ADENBAM, E.G. Licensing Branch 4 2pp. 22700

G Adjudicatory correspondence

- B403010209 Mution for extension of time until 640323 to submit views on ASLB referral to ASLAB re rejection of Palmetto Alliance contention on reliability of Transamerica Delaval diesel generators

 JOHNSON, 0 E Hearing Spanch 4 84/02/29 Atomic 8afety and Licensing Appeal Panel 5pp 22436 004 24X Fiche 50-413-84/02/29, 8403010209
- 8403070033 Forwards joint proposed findings of fact & conclusions of law on Contentions PA44/CES91B re reactor embrittlement & joint Contention DES17 re adverse weather RILEY. J Carolina Environmental Study Group RILEY. J Palmetto Alliance 84/02/29 KELLEY. J, FOSTER. R, PURDOM, P Atomic Safety and Licensing Board Panel 1p 22541 165 24X Fiche 50-413.84/02/29,8403070033
- --8403070037 Proposed findings of fact & conclusions of law in form of partial initial decision on Contentions PA44/CES9 18 re reactor embrittlement & Contention DES17 re adverse weather Certificate of Svc encl
 RILEY, J L Carolina Environmental Study Group GUILD, R Palmetto Alliance GUILD, R Quild, R 84/02/29 34pp 22541 146 24X Fichs 50-413,84/02/29,8403070033
- 8403140123 Forwards NRC inspirepts & accompanying violation notices refacility GA Enclirepts & notices issued after close of Dec 1983 hearings Palmetto Alliance served w/notices & util responses

 JOHNSON, O E Hearing Branch 4 84/02/27 KELLEY, JL., PURDOM, P.W., FOSTER, R.F. Atomic Safety and Licensing Board Panel 28pp.

 22624 040 24x Fiche 50-413,84/02/27,8403140123
- 8403070030 Order granting staff request for extension to & including 840323 of time within which to submit views re ASLB 830223 referral order in proceeding SHOEMAKER.C J Atomic Safety and Licensing Appeal Panel 84/03/03 Office of the Executive Legal Director 2pp 22541 274 24X Fichs 50-443.84/03/01.8403070030
- 8403060240 Forwards exercise evaluator document used in conjunction w/840215-16 smergency mgt exercise. NUREO-0654. Rev 1 & portion of community issues survey dealing w/emergency planning W/O encis SHEARIN. R V Duke Power Co 84/03/02 GUILD. R Palmetto Alliance RILEY. J. Affiliation Not Assigned 2pp 22516 137 24X Fiche 50-413.84/03/02.8403060240
- 8403070048 Response opposing Carolina Environ Study Group 840214 offer of proof re reactor vessel technology, fatigue at high temp, strain gauge technology & structural integrity or LAR components Certificate of Svc encl MCOARRY, J M Bishop, Liberman, Cook, Purcell & Roynolds 84/03/02 Atomic Bafety and Licensing Board Panel 14pp 22541 235 24X Fiche 50-413,84/03/02,8403070048
- 8403140043 Forwards J Smercak affidavit of nondisclosure for assistance in preparation of staff proposed findings W/o encl JOHNBON, G E Hearing Branch 4 BA/03/02 KELLEY, J L Atomic Safety and Licensing Board Panel 1p 22633 119 24x Fiche 50-413,84/03/02,8403140043
- 8403090112 Forwards suppl to Palmetto Alliance proposed findings of fact & conclusions of law in form of partial initial decision Part V on honeycombing unitted dus to in camera matl GUILD.R Guild. R GUILD.R. Palmetto Alliance 84/03/06 KELLEY, J L. FOSTER.R F., PURDAM.P W Atomic Safety and Licensing Board Panel 38pp 22375 218 24% Fiche 50-413,84/03/06,84/03/90112
- --8403090(1) Suppl to proposed findings of fact & conclusions of law in form of partial initial decision Certificate of Svc encl. OUILD:R Palmetto Alliance OUILD:R Ouild:R 84/03/06 36pp 22575 256 24X Fiche 50-413.84/03/06.8403090112
- 8403140124 Response opposing Carolina Environ Study Group 840216 motion to reopen record on reactor embrittlement Offer of proof as to matis acceptable Certificate of Svc encl
 JOHNSON, O E Hearing Dranch 4 84/03/07 Atomic Safety and Licensing Board Panel 7pp 22620 288 24X Fiche.50-413,84/03/07, 8403140124
- 8403140150 Notifies of 840313 enforcement conference in Atlanta, GA to inform licensee of welder 8 issue so corrective action may be commenced Heeting summary will be forwarded to ASL8 & parties to proceeding

 JOHNSON, O.E. Hearing Branch 4 84/03/07 MELLEY, J. L. FOSTER, R.F., PURDON, P.W. Atomic Safety and Licensing Board Panel 1p

 22620,338 24x Fiche 50-413,94/03/07,8403140150

B403140169 Informs of improper svc of Carolina Environ Study Group/
Palmetto Alliance proposed findings of fact & conclusions of
law re adverse weather & nonreceipt of proposed findings on
Contention 16
JOHNSON O E Hearing Branch 4 84/03/07 KELLEY, J L , FOBTER, R F ,
PURDOM P W Atomic Safety and Licensing Board Panel ip
22620 333 24X Fiche 50-413,84/03/07,8403140169

1

- 8403140046 Proposed findings of fact & conclusions of law in form of partial initial decision on Contention 6. Palmetto Alliance Contentions 16 & 44 & DEB Contention 17 Certificate of Svc encl
 JOHNSON, G E Hearing Branch 4 84/03/08 210pp, 22633:309 24x
 Fiche 30-413-84/03/08.8403140046
- B403130071 Forwards applicant interrogatories & request to produce documents re diesel generator contention, per 840223 order Related correspondence CARR.A V Duke Power Ca B4/C3/11 RILEY.J L Carolina Environmental Study Group. GUILD.R Guild, R 1p 22602 169, 24x Fiche 50-413.84/C3/11.8403130071
- --B403130077 Interrogatories & requests to produce documents on dissel generator contention to Carolina Environ Study Group & Palmetto Alliance Certificate of Svc encl Related correspondence
 CARR. A V Duke Power Co 84/03/11 Carolina Environmental Study Group 27pp 22402 170 24X Fiche 50-413,84/03/11.
 B403130071
- 8403160027 Reply to intervenors & NRC staff proposed findings of fact & conclusions of law Certificate of Svc encl HCOARRY, J M Duke Power Co MCOARRY, L, M Bishop, Liberman, Cook, Purcell & Reynolds 84/03/15 197pp 22654 123 24X Ficke 50-413.84/03/15.8403160029
- 8403190073 Forwards questions for FEMA witnesses to assist in preparation of testimony on offsite emergency planning contentions All testimony will be required to be filed on 840404 by O Hearing will commence on 840424 W
- 8403190174 Forwards "NRC Staff Supplemental Proposed Findings of Fact in Form of Partial Initial Decision on In Camera Issues re Contention 6 (GA)." per 840307 telcon Wo encl JOHNSON.G.E Hearing Branch 4 84/03/15 KELLEY.J L., FOSTER.R F, PURDDM.P W Atomic Safety and Licensing Board Panel 1p 22671 162 24X Fichs 50-413,84/03/15,8403190174
- 8403200042 Memorandum & order denying motion to defer further action on two pending CL dissel generator contentions until after SSER issuance FOSTER.R F. PURDON,P W. KELLEY.J L. Atomic Safety and Licensing Board Fane) 84/03/16 Palmetto Alliance 3pp 22699,182. 24X Fichs 50-413,84/03/16,8403200042
- 8403200007 Interrogatories & requests to produce documents to Carolina Environ Study Graup & Palmetto Alliance on ASLB contention re diesel generator reliability Certificate of Svc encl Related correspondence CARR, A V Bushop, Liberman, Cook, Purcell & Reynolds 84/03/19 Carolina Environmental Study Group 21pp 22699.202 24X Fiche 50-413,84/03/19,8403200007
- 8403220237 Supplemental interrogatories to util re amergency diesel contentions admitted by ASLB Certificate of Svc encl Related correspondence
 RILEY. J. L. Carolina Environmental Study Group DSB 047. 84/03/19
 Duke Power Co 5pp 22719 034 24X Fichs 50-413,84/03/19,
- 8403220233 Interrogatories & requests to produce documents re diesel generator contentions to applicant & NRC staff Certificate of Svc encl Related correspondence QUILD,R Palmetto Alliance QUILD,R Carolina Environmental Btudy Group QUILD,R Quild, R DSS 049 84/03/22 Duke Power Co. 20pp 22719 014 24X Fiche 50-413,84/03/22,8403220233.
- 8403270011 Notifies that svc list amended to reflect appointment of separate board for smergency planning Shearin 840302 ltr to Ouild & Riley, 840312 ltr to Guild & supplemental answers to interrogatories encl W/o encl. Related correspondence SHEARIN, R V Duke Power Co DSB 114 84/03/22, MAROULIES, M B LAZO, R M . HODPER, F F Atomic Safety and Licensing Board Panel. 19 22749 355 24X Fiche 50-413, 84/03/22, 8403270011

- 8403260367 Response to ASLB questions re whether memorandum referred to concerning diesel generators should be accepted & how ASLB should decide posed issues Referral request fails to satisfy interlocutory review test Certificate of Svc encl MCGARRY, J M Duke Power Co MCGARRY, J M Bishop, Liberman, Cook, Purcell & Reynolds DSB 0B3 84/03/23 55pp 22760 079 24X Fichm 50-413,84/03/23,8403260367
- B409270922 Views on ASLB 840223 referral of 840217 rejection of generic aspects of intervenors diesel generator contention Certificate of Svc encl JOHNSON, G E Hearing Branch 4 DSB i32 B4/03/23 84pp 22789 069 24X Fiche 50-413.84/03/23.8403270322
- 8403270382 Motion to amend & suppl dissel generator contentions, or in alternative, motion for admission of new dissel generator contention ASLB urged to grant motion & admit recasted contention GUILD, R Palmetto Alliance DSB 192 84/03/23 Atomic Safety and Licensing Board Panel 11pp 22814 153 24X Fichs 50-413,84/03/23,8403290382
- 8403290388 Memorandum on emergency diesel generator questions referred per 10GFR2 730 Acceptance of referral urged Certificate of svc encl.

 QUILD,R Pelmetto Alliance QUILD,R Carolina Environmental Study Oroup. QUILD,R, Quild, R DSS 194 84/03/23 29pp 22814-283, 24X Fiche-50-413,84/03/23,8403290388
- 8403290379 Responses to util interrogatories & request to produce documents on diesel generator contention Certificate of Svc encI Related correspondence
 QUILD,R Palmetto Alliance GUILD,R Guild, R * Carolina Environmental Study Group DSB 191 84/03/25 9pp 22814 144 24X Fichs 50-413,84/03/25,8403290379
- J Insurance & indemnity information
- 8403140037 Forwards Endorsement 9 to NELIA Policy NF-201 ROBBINS, J G Marsh & McLennan, Inc 84/03/05 DINITZ, I Assistant Director for State & Licensee Relations 2pp 22633 122 24X Fiche: 50-413, 84/03/05, 8403140037
- G Inspection reports, IE Bulletins & correspondence
- 8403080203 Responds to FOIA request for documents from Mar 1977 Mar 1977 rs WR McAfee allegations Forwards App A documents Info also available in PDR.
 FELTON, J M Division of Rules and Records. 84/01/24 GARDE, B. P. Gavennment Accountability Project. 2pp 22584 164 24X Fiche: 50-413, 84/01/24, 8403080203
- ---8403080212 Discusses 791113-16 interviews w/craftsmen Interviewes selected by principal inspector, per TI 2512/4 criteria Related info anci MURPHY.C E Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/12/04 THORNBURG.H D Director's Office, Office of Inspection and Enforcement 7pp 22584 166 24X Fiche: 50-413, 84/01/24, 8403080203
- 8403160343 Forwards IE Insp Repts 50-413/84-03 & 50-414/84-03 on 840103-06 & 11-13 No violations or deviations noted BANCE. H. C Division of Project & Resident Programs 84/02/17 TUCKER. H B Duke Power Co. 2p 22660 177 24X Fiche: 50-413,84/02/17,8403160343
- --8403160356 Forwards IE Insp Repts 50-413/84-03 & 50-414/84-03 on 840103-06 & 11-13. No violations or deviations noted Proprietary review of document waived by util to assure distribution to parties in licensing proceeding DANCE, H. C. Division of Project & Resident Programs 84/01/20. CARR. A. V. Duke Power Co. 1p 22660 179 24X Ficha 50-413,84/02/17,8403160343
- --8403160363 IE Insp Repts 50-413/84-03 & 50-414/84-03 on 840103-06 & 11-13. No violations or deviations noted Major areas inspected containment spray-welding welding matl control & radiagraphic exam
 ECONOMOS N Region 2. Office of Director BLAKE, J. J Division of Engineering & Operational Programs. 84/01/20 9pp 22660 180. 24X Fiche: 50-413,84/02/17,8403160343
- B403070205 Ack receipt of B40123 ltr supplementing B30908 response informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/83-17 & 50-414/83-16 DANCE, H. G. Division of Project & Resident Programs B4/02/24 TUCKER, H. B. Duke Power Co. ip 22538,359, 24X Fiche: 50-413,84/02/24,8403070205

- --8403070210 Forwards revised response to NRC 1tr re violations noted in IE Insp Repts 50-413/83-17 & 50-414/83-16 Corrective actions GA Procedure GA-140, "Inspector Certification," will be revised TUCKER.H B Duke Power Co 84/01/23 O'REILLY, J.P. Region 2, Office of Director 2pp 22538 360 24X Fiche 50-413,84/02/24, 8403070205
- B403160253 Informs that no circuit breakers w/undervoltage trip attachments in use in safety-related application other than reactor trip sys, in response to IE Bulletin 83-00 TUCKER, H B Duke Power Co B4/02/24 D'REILLY, J P Region 2, Office of Director Ip 22660 142 24X Fiche 50-413,84/02/24,8403140253
- 8403160086 Forwards IE Insp Repts 50-413/84-11 & 50-414/84-07 on 840131-0203 No violations or deviations identified DANCE.H C Division of Project & Resident Programs 84/02/27 TUCKER H B Duke Power Ca 2pp 22655 103 24X Fiche: 50-413, 84/02/27, 8403160086
- --8403160092 IE Insp Repts 50-413/84-11 & 50-414/84-07 on B40131-0203 No violations or deviations identified Major areas inspected fire protection/prevention
 MILLER.W H Region 2. Office of Director CONLON.T E Division of Engineering & Operational Programs 84/02/21 9pp 22655 105 24X Fichs 50-413.84/02/27.8403160086
- 8401170072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list enti JGRDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22707 237 24X Fiche 50-000.84/02/28.8401170072
- 8403140123 Forwards NRC insp repts & accompanying violation notices re facility QA Encl repts & notices issued after close of Dec 1983 fearings Pelmetto Alliance served w/notices & util responses. JOHNSON, Q E Hearing Branch 4 84/02/29. KELLEY, J L Atomic Safety and Licensing Board Panel 28pp 22624 040 24X Fiche 50-413,84/02/29,8403140123
- B403160143 Forwards final response to IE Bulletin 79-14, Rev 1, Suppl 2 re GA program for seismic analysis of Seismic Category 1 piping sys
 TUCKER.H B Duke Power Co 84/02/29 GREILLY, J.P. Region 2,
 Office of Director 4pp 22655 321 24X Fiche 50-413, 84/02/29,
 8403160143
- B402090007 IE Info Notice B4-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE. J. N Division of GA. Bafeguards & Inspection Programs (Post B30103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 327 24X Fichs 50-000,84/03/02,8402090007
- 8402090008 IE Info Natice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 078 24X Fiche 50-000.84/03/02.8402090008
- 8402070007 IE Info Notice 84-15, "Reporting of Radiological Releases" Svc list encl
 JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc 119pp 22553 217 24X Fiche 50-000,84/03/02,8402070007
- 84020900ii IE Info Notice 84-17. "Problems W/Liquid Nitrogen Gooling Components Below Nil Ductility Temp " Svc list encl. JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp. 22553 336 24% Fiche 30-000.84/03/05.8402090011
- 8402090024 IE Info Notice 84-09, Rev 1. "Lessons Learned From Insps of Fire Protection Bafe Shutdown Sys " Svc list encl. JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22635 049 24X Fiche 50-000,84/03/07.8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Gracking in PHR Sys " Syc list and I JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07. Consolidated Edison Co of New York, Inc. 118pp 22584 186 24X Fiche 50-000,84/03/07.8402090028
- 8403160293 Ack receipt of 840215 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/83-52 & 50-414/83-39 LEWIS.R C Division of Project & Resident Programs 84/03/08 TUCKER.H B Duke Power Co 1p 22660 124 24X Fiche.50-413.84/03/08.8403160293

- --8403160299 Responds to NRC 840117 ltr re-violations noted in IE Insp. Repts 30-413/83-52 & 50-414/83-39 Corrective actions QA Procedure QA-130 revised to assure that util written qualifications for auditors in full compliance wicodes TUCKER, H B Duke Power Co 84/02/15 O'REILLY, J P Region 2, QFfice of Director 2pp 22660 125 24% Fiche 50-413, 84/03/08, 8403160293
- --8403160307 Forwards IE Insp Repts 50-413/83-52 & 50-414/83-39 on 831212-16 & notice of violation LENIS,R C Division of Project & Resident Progress 84/01/17 TUCKER.H B. Duke Power Co. 2pp 22660 127 24X Fichs 50-413,84/03/08,8403160293
- --8403140314 Notice of violation from thep on 831212-16 * Region 2. Office of Director 84/01/17 lp. 22640 129 24X Fichs 50-413,84/03/08,8403140273.
- --8403160319 IE Imsp Repts 50-413/83-32 & 50-414/83-39 on 831212-16 Violation noted failure to establish personnel qualifications for auditors BELISLE, G. A., FOBTER, L., SMITH, C., Region 2. Office of Director 84/01/13 12pp 22660 130. 24X Fiche. 50-413, 84/03/08, 8403160293
- 8402070031 [E Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Bys " Svc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 074 24X Fiche. 50-000.84/03/12,8402070031
- B403270270 Ack receipt of 840305 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-413/83-21 & 50-414/83-22 LEWIS.R C Division of Project & Resident Programs 84/03/15 TUCKER.H B Dute Power Co ip 22800 020 24X Fiche 50-413.84/03/15.8403270270
- ---B403270276 Responds to NRC 830912 ltr re violations noted in IE Insp Repts 50-413/83-2: & 50-414/83-22 Corrective actions QC insp criteria for cable pulling revised to clarify insps of cable bending radius & unsupported length during routing. TUCKER.H B Duke Power Co 84/03/05 O'REILLY, J P Region 2, Office of Director 3pp 22800 021 24% Fiche 50-413,84/03/15, 8403290270
- B402090043 IE Info Notice B4-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities." Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/03/21 Consolidated Edison Co of New York, Inc 123pp. 22823 229 24X Fiche 50-000.84/03/21.8402090043
- B402090044 IE Info Notice B4-20, "Svc Life of Relays in Safety-Related Bys " Bvc list encl JORRONN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044
- 8 Reportable occurrences, LERs & related correspondence
- B403010451 Informs Commission of problems w/emergency diesel generators mfg by Transamerica Delaval, Inc DIRCKB,W J Office of the Executive Director for Operations BECY-B3-034 84/01/25 4pp 22438 347 24X Fiche 50-000,84/01/25,8403010451
- B403010140 Significant Deficiency Rept 8D 413-414/84-02 reunconsidered effects of superheated steam possibly resulting in increased lower containment temp freeting on B40312 requested TUCKER.H B Duke Power Co 84/02/17 O'REILLY, J P Region 2, Office of Director 2pp 22435 322 24X Fiche 50-413.84/02/17, 8403010140
- B403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines, Gimpel NPB-4 T&T valve, to close Encl 1tr dtd 840203 sent to listed utils GE notified of effected units in BWR plants
 THEROUX, R Terry Corp B4/02/22 MOODRUFF, R W Director's Office. Office of Inspection and Enforcement 6pp. 22706 327 24X Fiche 50-000.84/02/22.8403210032.
- 8403090226 Significant Deficiency Rept 413-414/82-04 amending corrective actions to previously submitted rept.Reinsp of inaccessible deficient supports may be walved if documented evaluation of design analysis provided. TUCKER, H B. Duke Power Co. 84/02/24 D'REILLY, J P. Region 2. Defice of Director 2pg 225/3.261 24X Fiche 50-413,84/02/24,84034090294

- B403010207 Forwards "Investigation of Tupes AF & AE Piston Bkirts," per Transamerica Delaval, Inc Owners Oroup program commitments.

 Rept evaluates cracks in AF piston stirts in Shoreham & Orand Gulf Nuclear Power Stations

 MUSELER, W J DI (Transamerica Delaval, Inc) Owners Oroup, B4/02/27 DENTON.H R Office of Nuclear Reactor Regulation, Director 3pp 22434 090 24X Fiche.50-000, B4/02/27, B403010207
- 840309024i Interim Gignificant Deficiency Repts 8D-413/82-27 & 8D-414/82-27 re cracked cell containers Six cracked cells returned to Nife for investigation & resolution Bite personnel will conduct weekly battery insp TUCKER.H B Duke Power Co 84/02/27 D'REILLY, J P Region 2, Office of Director 2pp 22572 302 24X Fiche. 50-413,84/02/27,8403090241.
- 8402090021 Board Notification 84-039 discusses NRC 840210 & 15 mestings w/Transamerica Delaval. Inc Emergency Diesel Generators Duhers Group Meeting scheduled on 840308 for finalization of generic program plan prior to NRC review EISEMHUT.D 0 Division of Licensing 84/02/28 PALLADINO Commissioners. 5pp 22546 003 24X Fiche: 50-000, 84/02/28, 8402090021.
- 8403010218 Forwards task descriptions for 16 known problems re Transamerica Delaval, Inc. emergency diesel generators MUBELER. W. J. DIJ (Transamerica Delaval, Inc.) Owners Group, 84/02/28 DENTON, H. R. Office of Nuclear Reactor Regulation, Director, 42pp. 22435 177 24X Fiche: 50-000,84/02/28,8403010218
- 8402090020 Board Notification 84-044 forwards Part 21 rept re Transamerica Delaval Inc turbdcharger thrust bearing Inbrication defect resulting in engine nonavailability EISENHUT, D. 9 Division of Licensing 84/02/27 PALLADING Commissioners 4pp 22541 263 24X Fiche 50-000, 84/02/27, 840000000
- 8403140048 Forwards "Grand Gulf Component Tracking Bys." "Shoreham Component Tracking Bys" & "Transamerica Delavel. Inc Diesel Generators Cumers Group Program Plan." to resolve concerns w/emergency diesel generators MUSELER.W. J. Long Island Lighting Co. 84/03/02 DENTON.H R Office of Nuclear Reactor Regulation, Director. 2pp. 22626-062-24X Fiche 50-000,84/03/02,8403140048
- --8403140095 "Transamerica Delaval, Inc Diesel Generators Dwners Group Program Plan," * TDI (Transamerica Delaval, Inc.) Gwners Group 84/03/02. 261pp 22628 223, 24X Fiche 50-000,84/03/02,8403140048.
- 8403150128 Update of Significant Deficiency Rept 414/82-25. Item should be renumbered 413-414/82-25 All necessary actions completed TUCKER, H B Duke Power Co. 84/03/02 O'REILLY, J. P. Region 2: Office of Director ip 22639:332 24X Fiche. 50-413, 84/03/02:8403150128
- 8402070033 Board Notification 84-047, forwards Transamerica Dalavel, inc Owners Group piston skirt rept & task descriptions EISENHUT, D 0 Division of Licensing 84/03/07 PALLADIND Commissioners 4pp 22674 221 24X Fiche 50-000, 84/03/07, 84002090033
- B403140122 Part 21 rept re status update concerning abnormal wear on linear converters. Test program underway Results of investigation indicate excessive wear caused by hunting of control circuitry.

 DUDSON, J P. Pacific Air Products Co. 84/03/09 Director's Office, Office of Inspection and Enforcement, 7pp 22624;068. 24X Fiche: 50-000.84/03/09.8403140122.
- 8402090038 Board Notification 84-051.forwards "Transamerica Delaval, Inc (TD1) Diesel Generators Owners Group Program Plan " EISENHUT, D. Q. Division of Licensing 84/03/12, PALLADING Commissioners 5pp 22688.214 24X Fiche.50-000,84/03/12,
- B402090039 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delaval, Inc (TDI) Duners Group, Distribution list encl.
 EISENHUT, D. G. Division of Licensing 84/03/12 PALLADING Commissioners, 5pp. 22708,001. 24X Fiche 50-000, 84/03/12, 2400207029
- --8403060536 Forwards summary of 840210 meeting w/Transamerica Delaval.
 Inc Cumers Group in Bethesda, MD re problems w/smergency
 diesel generators.
 CARUBO, R Licensing Branch 2 84/02/27. D'REILLY, J. P. NAC No
 Detailed Affiliation Given. 6pp 22708'006. 24X
 Fiche: 50-000, 84/03/12, 8402090039.

- --B403080554 Transcript of B40210 meeting w/Transamerica Delaval, Inc Owners Group in Bathasda, MD re problems w/smergency diesel generators * NRC - No Detailed Affiliation Given B4/02/10 147pp 67201 008 24% Fiche 50-000, 84/03/12, B402090039
- --8403070409 Summary of 840216 meeting w/Transamerica Delaval, Inc Owners Oroup in Wading River, NY re program plan to establish reliability of diesel generators Agenda, meeting transcript & attendance list encl
 MILLER, M A Licensing Branch 4 84/02/27 Licensing Branch 4
 8pp 22708 161 24X Fiche 50-000,84/03/12,8402090039
- --8403070423 Transcript of 840216 conference in Wading River,NY re Transamerica Delaval, Inc diesel generators Pp 1-82 * Commissioners 84/02/16. 84pp R2708 169 24X Fiche, 50-000,84/03/12,8402070037
- 8403140050 Forwards "Design Review of Connecting Rod Bearing Shells for Transamerica Delaval Enterprise Engines" for Shoreham & Grand Guif diesel generators
 MUSELER, W J Long Island Lighting Co 84/03/12 DENTON: H R
 Defice of Nuclear Reactor Regulation. Director 2pp 22632 074
 24% Fichs 50-000,84/03/12,8403140050
- 8403150133 Forwards "Transamerica Delaval, Inc Diesel Generator Rocker Arm Capscrew Stress Analysis Rept " Capscrew design adequate for applicable angines & svc conditions MUBELER, W J TDI (Transamerica Delaval, Inc.) Owners Group 84/03/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22639, 270 24X Ficha. 50-000, 84/03/13, 8403150133
- 8403290244 Final Significant Deficiency Rept 8D 413-414/83-14 re seal conduit connection to safety-related equipment located in harsh anvirons. Initially reported on 831102 Util continuing to evaluate alternative sealing methods
 TUCKER, H B Duke Power Co 84/03/15 O'REILLY, J P Region 2, Office of Director 3pp 22800, 224 24X Fiche 50-413,84/03/15,8403290244
- 8403200222 Responds to 840214 Requests for Info 1 & 2 re R-4 series engines. List indicating engine number, model & svc number, customer name & address, rating, date shipped & date started and I.

 MATHEWB, C. S. Transamerica Delaval. Inc. 84/03/16 EISENHUT, D.G. Division of Licensing 20pp. 22691.179 24X Fithe. 50-000, 84/03/16, 84/03/0022
- 8403270132 Forwards "Emergency Diesel Generator Air Start Valve Capterew Dimension & Strass Analysis." prepared by 8kW for Transamerice Delaval. Inc (TDI) Diesel Generator Quners Group HUBELER, W. J. TDI (Transamerica Delaval. Inc.) Owners Group B4/03/23. DENTON.H R. Office of Nuclear Reactor Regulation. Director. 2pp 22774.001 24X Fiche 50-000.84/03/23.8403270132
- 8403270134 Requests meeting on 840418 to discuss short-term & longterm corrective actions & investigations re Transamerica Delaval diesel generators List of suggested meeting topics encl. MCGAUGHY, J. P. TDI (Transamerica Delaval, Inc.) Duners Group.
 - MCGAUGHY, J. P. TDI (Transamerica Delaval, Inc.) Dwners Group, 84/03/23. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 4pp 22769 133, 24X Ficha 50-000,84/03/23,8403270134
- T. Hearing transcripts on non-antitrust matters
- 8402070039 Board Notification 84-052 forwards maeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delaval, Inc (TDI) Gwners Group Distribution list encl EIBENHUT, D Q. Division of Licensing. 84/03/12 PALLADIND Commissioners. 5pp. 22708;001. 24X Fiche 50-000,84/03/12,8402070039
- --8403060536 Forwards summary of 840210 meeting w/Transamerica Delaval.
 Inc Owners Group in Bethesda.MD re-problems w/emergency
 dissel generators
 CARUSO.R. Licensing Branch 2 84/02/27 O'REILLY, J. P. NRC No
 Detailed Affiliation Given. 6pp 22708-006. 24X
 Fichs. 50-000, 84/03/12, 8402070037
- --B403060554 Transcript of 840210 meeting w/Transamerica Delaval, Inc Owners Group in Bethesda, MD re problems w/emergency diesel generators. * NRC - No Detailed Affiliation Given 84/02/10 147pp 67201:008, 24X Fiche, 50-000, 84/03/12, 8402090039
- --B403070409 Bummary of B40216 meeting w/Transamerics Delaval, Inc Owners Oroup in Wading River, NY re program plan to establish reliability of diesel generators. Agenda, meeting transcript & attendance list encl.

 HILLER: M A. Licensing Branch 4. B4/02/27. Licensing Branch 4. Bpp. 22708:161 24X Fiche: 50-000: 84/03/12,8402090039

- --8403070423 Transcript of 840216 conference in Wading River, NY re Transamerica Delaval. Inc diesel generators Pp 1-82 * Commissioners 84/02/16 84pp 22708 169 24X Fiche 50-000.84/03/12,8402090039
- 8403160236 Transcript of 840314 telcon re facility Pp 12.580-12.624 * Atomic Safety and Licensing Board Panel 84/03/14 45pp 82660 208 24X Fiche 50-413.84/03/14.4403160236
- 8403260251 Transcript of 840321 telephone conference in Bethesda.MD Pp 1-24

 * Atomic Safety and Licensing Board Panel 84/03/21 28pp 22754 283 24X Fiche 50-413.84/03/21,8403260251
- DOCKET 50-416 GRAND GULF NUCLEAR STATION, UNIT 1
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 840308D179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withhold (ref FOIA Exemption 5) Review of add1 documents subj to request continuing FELTON.J M Division of Rules and Records 84/02/13 ANDERSON, S J Garvey, Schubert, Adams & Barer 7pp 22883 226 24X Fiche 50-000, 84/02/13, 8403080179
- --8005130793 Provides status of SER inputs & acceptance reviews for OL & CP applications Schedule should be met BURKE.W C Effluent Treatment Bystems Branch 80/02/06 KREOGER.W E Assistant Director for Site Analysis 1p 22583 235 24% Fiche 50-000.84/02/13.8403080179
- 8403210140 Forwards confirmation of Lonergan safety relief valve qualification & operability testing of reclassified valves, per util 821108 & 18 ltrs & 8868 4

 DALE-L F Mississippi Power & Light Co 84/03/13 DENTON:H R
 Office of Nuclear Reactor Regulation. Director 4pp 22707 276
 24X Fiche 50-416.84/03/13.8403210140
- F Security, medical, emergency & fire protection plans
- 8403210115 Forwards SALP Repts 50-416/83-55 & 50-417/83-09 for Sept 1982 - Sept 1983 LEWISIR C Division of Project & Resident Programs 84/01/11 RICHARD, J B Mississippi Power & Light Co 2pp 22707 144 24X Fiche: 50-416, 84/01/11, 8403210115
- --8403210122 BALP Repts 50-416/83-55 & 50-417/83-09 for Sept 1982 -Sept 1983 + Region 2, Office of Director 84/01/11 32pp 22707 146 24X Fichs 50-416,84/01/11,8403210115
- 8403160281 Notifies of 840316 workshop to discuss 10CFR30.App R requirements & inspiresults to resolve misunderstandings refire protection Attendees should be limited to six due to size of conference roam LEWIS.R C Division of Project & Resident Programs 84/03/02 RICHARD.J B Mississippi Power & Light Co 1p 22660 350 24X Fiche: 50-416.84/03/02.8403160281.
- 8403160336 Discusses util 840224 ltr re 1984 emergency exercise
 Exercise objectives reviewed & comments provided to
 P Benedict, corporate emergency preparedness coordinator
 VERRELLI.D M Division of Project & Resident Programs 84/03/05
 RICHARD, J B Mississippi Power & Light Co ip 22660 031 24%
 Fiche 50-416.84/03/05.8403160336
- 8403150052 Forwards State of LA 831227 request for exemption from full participation at 840410 annual radiological emergency preparedness exercise. FEMA supports exemption based on State of LA full participation in Materford exercise KRIMM.R W. Federal Emergency Management Agency 84/03/09 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 3pp. 22641 355 24X Fiche 50-416,84/03/09,8403150052
- O Adjudicatory correspondence
- 8403060102 Order allowing NRC & applicant until 840319 to respond to petitioner renumbered Contentions 1.2 & 3 & allowing petitioner 10 days after svc for response GROBSMAN.H Atomic Safety and Licensing Board Panel 84/03/02 2pp. 22517.019 24X Fiche 80-416.84/03/02.8403060102
- 8403190219 Forwards emergency planning contentions as modified & forwarded to ABLP GODDARD, R. J. Hearing Branch 3 84/03/16 SNELL, W. Region 3, Office of Director 1p 22674; 199 24% Fiche 50-416, 84/03/16, 8403190219

- --8403190220 Summarizes 840228-29 meetings u/util.Prairie Alliance & FEMA iπ Champaign. IL re mod & deletion of portions of Contention i on emergency planning Proposed mods encl Submits schedule for parties to further settle issues GODDARD.R J Hearing Branch 3 84/03/05 CLARK,H K , PARIS.O H , FERGUSON.G A Atomic Safety and Licensing Board Panel 3pp 22674 200 24X Fiche 50-416.84/03/16.8403190219
- 8403200018 Response to first order following prehearing conference modifying briefing schedule ASLB should deny admission of Paragraphs 6.7 & B as well as Contentions 1.2 & 3 & dismiss proceeding Certificate of Svc enc!

 CONNER.T B Hississippi Power & Light Go CONNER.T B Conner & Wetterhahn 84/03/16 Atomic Safety and Licensing Board Panel 22pp 22699 001 24X Fiche 50-416,64/03/16,8403200018
- 8403210165 Response to Jacksonians United for Livable Energy Policies renumbered Contentions 1,2 & 3 Admission of renumbered contentions acceptable Certificate of Svc encl HACMER.M E Hearing Branch 4 DSB 016 84/03/19 Atomic Safety and Licensing Board Panel 7pp 22718 217 24X Fichs 50-416.84/03/19.8403210165
- 8403270318 Forwards staff 830319 response to petitioner renumbered Contentions 1.2 & 3.per request W/o encl WAGNER, M E Hearing Branch 4 DSB 131 84/03/22 STEWART, C Affiliation Not Assigned 1p 22789 028 24X Fiche 50-416.

H General correspondence

- 8403270211 Expresses concern on safety of facility NRC should not allow operation before plant meets safety criteria WIENER, J.L. Affiliation Not Assigned 84/03/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22772 144 24X Fiche 50-416,84/03/22,8403270211
- J Insurance & indemnity information
- 8403140121 Forwards Endorsement 29 to NELIA Policy NF-257 & Endorsement 11 to MAELU Policy MF-106 DALEIL F Mississippi Power & Light Co 84/03/02 KERR, G W Office of State Programs. Director 4pp 22620 284 24X Fiche 50-416,84/03/02.8403140121
- P Operating license stage documents & correspondence
- 8403070325 Forwards info re shift advisors, including job description MCGAUCHY, J.P. Mississippi Power & Light Co. 84/02/20 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 6pp 22546 198 24X Fiche 50-416, 84/02/20, 8403070325
- 8403010136 Forwards Amend 12 to License NPF-13 & safety evaluation Amend corrects administrative & technical deficiencies in Tech Byces re low-low set function, source range monitors & Div 2 batteries

 SCHWENCER, A Licensing Branch 2 84/02/21 MCGAUGHY, J P Mississippi Power & Light Co 4pp 22479 257 24X

 Fiche 50-416,84/02/21,8403010136
- --8403010143 Amené 12 to License NPF-13 correcting administrative & technical deficiencies in Tech Specs re low-low set function, source range monitors & Div 2 batteries SCHMENCER.A Operating Reactors Branch 2 84/02/21 12pp 22479 261 24X Fiche 50-416.84/02/21.8403010136
- ~~B403010147 Safety evaluation supporting Amend 12 to License NPF-13 * NRC - No Detailed Affiliation Given 84/02/21 4pp 22479 273 24X Fiche 50-416,84/02/21.8403010136
- 8403280009 Forwards new problem sheets, problem sheets w/supporting documents & uncontrolled Tech Specs w/punchlist numbers on tops of pages where inconsistencies identified STARLING. J Mississippl Power & Light Co 84/02/21 KINTNER, L NRC No Detailed Affiliation Olven 1.453pp 22782 349 24X Fiche 50-416,84/02/21,8403280009
- --8403280014 Proposed Tech Specs w/inconsistencies identified * Hississippi Power & Light Co 84/02/21 575pp 22785 053 24X Fiche 50-416,84/02/21,8403280009
- --B40328001B Rev O to "Offsite Dose Calculation Manual"

 MCKAY, L R Mississippi Power & Light Co 82/08/31 35pp

 22786 268 24X Fiche 50-416.84/02/21.8403280009
- --8409280025 Ray 1 to "Offsite Dose Calculation Manual" SMITH, G D , MCKAY, L R Mississippi Power & Light Co 83/07/31 35pp 22786 327 24X Ficha 50-416,84/02/21,8403280009

- B403070354 Requests review of amended Tech Specs & certification that Tech Spacs reflect plant FSAR & SER analyses within 10 days of ltr receipt EIBENHUT, D G Division of Licensing 84/02/24 RICHARD, J B Hississippi Power & Light Co 2pp 22564 132 24X Fiche 50-416.84/02/24.8403370354
- 8403080367 Responds to FOIA request for documents re BWR Integranular Stress Corrosion Cracking Owners Group meeting on or about 811028 Forwards App A documents Records also in PDR. FELTON.J M Division of Rules and Records 84/02/28 HAFNER.D Suffolk Nuclear Study Group 2pp 22583 008 24X Fichs 50-000.84/02/28.8403080367
- --8309210434 Requests evaluation of Orand Gulf & Shoreham 830817 & 23 responses, respectively re intergranular stress corrosion cracking in BHR piping. Response requested by 830916 W/o ancl EISEMHUT, D Q Division of Licensing 83/09/06, VOLLMER, R Division of Engineering 1p 22583:010 24X Fiche 50-000, 84/02/28, 8403080367
- 8403050236 Forwards detailed breakdown of approx 200 Tech Bpec changes requested by licensee & categorized in Dircks 840202 memo DIRCKS.W J Office of the Executive Director for Operations. 84/02/29 PALLADINO. 91LINSKY. ROBERTS Commissioners 36pp. 22527 215 24X Fichs 50-416.84/02/29.8403050236
- 8403230273 Notification of 840307 meeting w/util in Bethesda, MD to review program for Tech Bpecs.
 HOUSTON.M D Licensing Branch 2 84/03/05 8CHWENCER, A. Licensing Branch 2, 3pp 22759 282 24X Fiche: 50-416, 84/03/05, 8403230273
- 8403300251 Summary of 840221 meeting w/util in Bethesda, MD re datails of util proposed onsite/offsite electrical power reliability program for Transamerica Delaval, Inc diesel generators Attendance list & viewgraphs encl.
 HOUSTON, MD Licensing Branch 2 84/03/06. Licensing Branch 2 21pp 22845 001 24X Fiche 50-416,84/03/06,8403300251
- 8403090215 Forwards results of analysis performed showing relationship between ECCB reliability & Agastat relay test intervals. Analysis withheld (ref 10CFR2.790). DALELL F Mississippi Power & Light Co 84/03/07 DENTON, H. R. Office of Nuclear Reactor Regulation. Director. 6pp. 22572:286. 24X Fiche 50-416.84/03/07,8403090215
- 8403120037 Forwards requested info re experience levels of util operating shift personnel & expresses support of position taken by Industry Working Oroup on Operating Shift experience on 840224

 DALE: L F Mississippi Power & Light Co B4/03/08. DENTON, H R Office of Nuclear Reactor Regulation, Director 13pp 22590-304. 24X Fiche 50-416.84/03/08.8403120037
- 8403210109 Submits interim response to 840224 ltr requesting certification re Tech Specs & FSAR Review & certification program in progress Meeting scheduled for 840309 to discuss program scape, review criteria & schedule

 DALE-L F Missispipi Power & Light Co 84/03/08 DENTON, H R.

 Office of Nuclear Reactor Regulation, Director 2pp 22704-360
 24X Fiche 50-416,84/03/08,8403210109
- 8403210053 Endorses 8H Hobbs Feb 1984 Ltr HON-015 to HR Denton in response to NRC 831208 request for add1 info re Hydrogen Control Owners Group (HCDG) test program Questions to be answered by HCDG & util.respectively.listed DALE.L F Mississippi Power & Light Co. 84/03/09 DENTON.H.R. Office of Nuclear Reactor Regulation, Director 2pp 22704:344 24X Fiche 50-416.84/03/09,8403210053
- 8403150275 Generic Ltr 84-07 to all licensees of BWRs re procedural guidance for pipe replacement at BWRs Bvc list encl EISENHUT.D 0 Division of Licensing. 84/03/14. Commonwealth Edison Co 20pp 22823 354 24X Fiche.50-000,84/03/14,8403150275.
- 8403270074 Forwards updated info on operating shift experience to supersede previous submittal.including chart of experience levels of five proposed operating shifts
 DALE-LF Missispip Power & Light Co. 84/03/16. DENTON, H.R. Office of Nuclear Reactor Regulation. Director Spp 22806:341. 24X Fiche 50-416.84/03/16.8403270074
- 8403210057 Forwards description of Tech Spec review program, per 840224 request Program estimated to end on 840406 Formal response stated by 840409 Hississippi Power & Light Co 84/03/18 DENTON, H R. Office of Nuclear Reactor Regulation, Director 2pp 22705:021 24X Fiche 50-416,84/03/18,8403210057
- --8403210062 "Tech Spec Review Program Description "
 * Mississippi Power & Light Co 84/03/31, 20pp 22705:023 24X
 Fiche 50-416.84/03/18.8403210057

- 8403300305 Notification of 840322.28.0404 & 11 meetings w/util in Bethesda.MD to review program for processing Tech Spec change requests KINTNER, L L Licensing Branch 1 84/03/19 ADENSAM, E 0 Licensing Branch 4 3pp 22844 303 24X Fiche 50-416.84/03/19,8403300305
- 8403230084 Forwards application for amend to License NPF-13, changing Tech Specs re automatic depressurization sys valve operability requirements to achieve consistency between Tech Specs & design & accident analyses MCQAUGHY. J P Mississippi Power & Light Co 84/03/20 DENTON, H R Office of Nuclear Reactor Regulation. Director 2pp 22726 299 24X Fiche 50-416, 84/03/20, 8403230084
- ---8403230087 Application for amend to Licanse NPF-13, changing Tech Specs re automatic depressurization sys valva operability requirements to achieve consistency between Tech Specs & design & accident analysis MCGAUGHY.J.P Mississippi Power & Light Co 84/03/20 ip 22726-301 24X Fiche.50-416,84/03/20,8403230084
- ---8403230092 Proposed Tech Spacs changing automatic depressurization systalve operability requirements & min operable channels per trip systo one for standby liquid control systinitiation reactor water cleanup isolation function

 * Hississippi Power & Light Co 84/03/20 lipp 22726 302 24X
 Fiche 50-416,84/03/20,8403230084
- B403300097 Transmits fee for proposed amend to License NFF-13.

 DALE, L.F. Mississippi Power & Light Co 84/03/27 DENTON, H.R.
 Office of Nuclear Reactor Regulation, Director 2pp. 22821 212
 24X Fiche: 50-416, 84/03/27, 8403300097
- 8403260335 "Grand Gulf Nuclear Power Plant Audit of Nuclear Plant Tech Specs." FEHRINGER, J M., ROCKHOLD, H. C., COOK, T. L. EQ&O, Inc. FIN A-6816 EQO-EA-6542. 84/03/31 DONOHEW, J H., MEYER, Q C. Division of Licensing, 18pp 22775: 263, 24X Fiche 50~416,84/03/31,8403260335
- G. Inspection reports, IE Bulletins & correspondence
- 8403070057 Forwards rept describing generic problems discovered during surveillance program review effort & corrective actions implemented to correct surveillance deficiencies.per IE Insp Rept 50-416/82-67

 DALE: L.F. Mississippi Power & Light Co. 83/12/01. D'REILLY, J. P Region 2, Office of Director 27pp 22547 348 24X
 Fiche 90-416,83/12/01.8403070057
- 8403070268 Responds to questions raised during special safety insp on 830322-25 re IE Bulletin 80-11 that three montar cube compression tests did not meet min compressive strength requirements. Structural integrity unimpaired DALE. F. Mississippi Power & Light Co 83/12/30 O'REILLY, J P Region 2, Office of Director. 6pp 22544 086. 24X Fiche: 50-416, 83/12/30, 8403070268
- B403210115 Forwards SALP Repts 50-416/83-55 & 50-417/83-09 for Bept 1982 - Sept 1983, LEWIS.R.C Division of Project & Resident Programs 84/01/11, RICHARD.J B Mississippi Power & Light Co. 2pp. 22707 144 24X Fiche.50-416.84/01/11.8403210115
- --8403210122 BALP Repts 50-416/83-55 & 50-417/83-09 for Sept 1982 Sept 1983, * Region 2. Office of Director. 84/01/11. 32pp 22707.146. 24X Fiche 50-416,84/01/11,8403210115.
- 8403070247 Forwards IE Insp Rept 30-416/84-03 on 840116-19 No violations or deviations identified VERRELLI,D M. Division of Project & Resident Programs 84/02/09 RICHARD,J.B. Mississippi Power & Light Co 2pp. 22536 081, 24X Fiche: 50-416, 84/02/09, 8403070247.
- --B403070248 IE Insp Rept 50-416/84-03 on 840116-19. No violetions or deviations identified Major areas inspected, radioactive gassous & liquid effluents, raduaste organization; mods, procedures; audits & solidification KAHLE, J. B. Region 2, Office of Director BARR, K.P. Division of Engineering & Operational Programs, 84/02/02 6pp 22536:083 24X Fiche 50-416:84/02/09,8403070247.
- 8403160100 Forwards IE Insp Rept 50-416/84-04 on 840130-0202 No violations or deviations identified.

 VERRELLI, D. M. Division of Project & Resident Programs 84/02/15 RICHARD.J. B. Mississippi Power & Light Co. 2pp 22632-334. 24: Fiche: 50-416,84/02/15,8403160100

- --B40316010B IE Insp Rept 50-416/84-04 on 840130-0202 No violations or deviations identified Major areas inspected review of startup test procedures review of completed startup tests & closeout of outstanding items
 BURNETT.P T Region 2, Office of Director JAPE,F Division of Engineering & Operational Programs 84/02/10 5pp 22652 336 248 Fiche 50-416.84/02/15,8403160100
- 8403070168 Ack receipt of 840213 ltr informing NRC of steps taken to correct violations & deviations noted in IE Insp Rept 50-416/83-50 VERRELLI,D M Division of Project & Resident Programs 84/02/22 RICHARD, J B Mississippi Power & Light Co ip 22536 193 24X Fiche 50-416,84/02/22,8403070168
- ~-B403070173 Responds to NRC 840112 ltr re violations & deviations noted in IE Insp Rept 50-416/83-50 Corrective actions training superintendent given written reprimend & importance of attention to detail stressed DALE.L F Mississippi Power & Light Co 84/02/13 O'REILLY.J P Region 2. Office of Director 3pp 22536 174 24X Fichs 50-416,84/02/22.8403070168
- --8403070176 Responds to NRC B31115 ltr re violations noted in IE Insp. Rept 50-416/83-50 Requests compliance due date be extended until B40120 DALE; LF Mississippi Power & Light Co 84/01/13 G/REILLY, J P. Rejion 2. Office of Director ip 22536 197 24X Fichs 50-416,84/02/22,8403070168
- --B403070180 Responds to NRC 831115 ltr re violations noted in IE Insp Rept 30-416/83-50 Corrective actions change to Tech Specs prepared, balancing degree of detail portrayed in table DALE, L F Hississippi Power & Light Co 83/12/15 O'REILLY, J P Region 2. Office of Director 2pp 22536 198 24X Fichs 50-416,84/02/22,8403070168
- ---8403070186 Ack receipt of 831215 & 21 ltrs informing NRC of steps taken to correct violations & deviations noted in IE Imap Rept 50-416/83-50 Specific programmatic controls to be implemented should be provided VERRELLIID M Division of Project & Resident Programs 84/01/12 RICHARD, J B. Mississippi Power & Light Co 2pp 22536 200 24x Fichs 50-416,84/02/22,8403070168
- --8403070189 Responds to NRC 831115 ltr re deviation noted in IE Insp Rapt 50-416/83-50 Corrective actions add1 15 design changes being reviewed to determine if training required DALE, L.F. Mississippi Power & Light Co. 83/12/21 D'REILLY, J.P. Region 2, Office of Director 2pp 22536 202 24X Fiche: 50-416,84/02/22,8403070168
- --8403070206 Forwards IE Insp Rept 50-416/83-50 on 830926-1014 & notices of violation & deviation VERRELLI, D M Division of Project & Resident Programs 83/11/15 RICHARD, J B Mississippi Power & Light Co 2pp 22536 206 24X Fiche: 50-416, 84/02/22, 8403070168
- --8403070208 Notice of violation from insp on 830926-1014. # Region 2, Office of Director. 83/11/15 ip 22536 208 24X Fiche 50-416,84/02/22,8403070168
- --8403070209 Notice of deviation from Insp on 830924-1014 * Region 2, Office of Director 83/11/15 19 22536 207 24X Fiche 50-416,84/02/22,8403070168
- --B4030702id IE Insp Rept 50-416/83-50 on 830926-1014 Violation noted failure to meet Tech Bpec organization chart. Deviation noted failure to provide operator training on design changes to plant

 MAONER: A G Region 2. Office of Director JULIAN.C A. Division of Project & Resident Programs 83/11/13 7pp 22536 210 24X Fiche 50-416,84/02/22,8403070168
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Syc list encl
 - JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp. 22909 239 24X Fiche. 50-000, 84/02/28, 8401190072
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE, J N Division of QA, Bafegurards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552,329 24X Fiche 50-000,84/03/02,8402090007
- 8402090008 IE Info Notice 84-14, "Failure of Automatic Sprinkler Sys Valves to Operate" Svc 1ist encl. JORDAN, E L Division of Emergency Preparadness & Engineering Response (Past 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp. 22553:098 24X Fiche 50-000,84/03/02,8402090008

- 8402090009 IE Info Notice 84 15. "Reporting of Radiological Releases "
- Svc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consultdated Edison Co of New
 York, Inc 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8403120034 Staff requirements memo re 840929 briefing in Hashington.DC re SALP review of areas prior to issuance of full-power recommendation & document interpreting LER rept CHILK, S J Office of the Secretary of the Commission 84/03/02 DIRCKS.W J Office of the Executive Director for Operations 1p 22617 346 24x Fiche 50-416.84/03/02.8403120034
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Coaling Components Below Nil Ductility Temp " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8403290151 Forwards IE Insp Rept 50-416/84-02 on 840116-20 No violations or deviations noted VERRELLI.D M Division of Project & Resident Programs 84/03/05. RICHARD.J B Mississippi Power & Light Co 2pp 22806 001 24) Fiche 50-416/84/03/05.8403290151
- --8403290156 IE Insp Rept 50-416/84-02 on 840116-20 No violations or deviations noted Major areas inspected electrical preventive & corrective maint activities maint records & training of maint personnel OIBBONS.T D Region 2. Office of Director CONLON.T E Division of Engineering & Operational Programs 84/02/22 3pp 22806 003 24% Fiche 30-416.84/03/05.8403290151
- 8402090024 IE Info Notice 84-09.Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84703/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000.84/03/07.8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Sys " Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24% Fiche 50-000,84/03/07,8402090028
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000,84/03/12,8402090031
- 8403270030 Provides interim response to IE Bulletin 83-07. "Apparently Fraudulent Products Sold by Ray Miller: Inc." Results of investigation to date indicate no Ray Miller products supplied to facilities Final response expected by 840325 MCGAUGHY. J.P. Mississippi Power & Light Co. 84/03/13 O'REILLY, J.P. Region 2, Office of Director. 3pp. 22806-224 24X Fiche 50-416.84/03/13,8403270030
- 8403290306 Requests addl delay in submittal of inservice insp program until 840801 Justification provided DALE.L F Mississipp Power & Light Co 84/03/16 DENTON, H R Office of Nuclear Regulation, Director 2pp 22802 172 24X Fiche 50~416,84/03/16,8403290306
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Bvc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 800103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Ficha 50-000,84/03/21,8402090043
- B402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24% Fiche 50-000,84/03/21,8402090044
- R Periodic operating reports & related correspondence
- 8403020047 Monthly operating rept for Jan 1984 W/840215 ltr CESARE, J G . DALE, L. F Mississippi Power & Light Co 84/01/31 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 12pp. 22441 175 24X Fiche 50-416,84/01/31, 8403020047
- B403020443 Forwards monthly status rept of offsite emergency preparedness for OL reviews for Jan 1984 Changes in FEMA finding dates not caused by delay due to offsite emergency planning issues
 DIRCKS, W. J. Office of the Executive Director for Operations 84/02/21 PALLADINO Commissioners 9pp 22492 083 24X Fichs 50-000,84/02/21,8403020443

- 8403220147 Monthly operating rept for Feb 1984 W/840315 1tr CEBARE.J 9, DALE.L F Mississippi Power & Light Co 84/0R/29 DEYOUNG.R C Director's Office. Defice of Inspection and Enforcement App 22716 051 24X Fiche 50-416,84/02/29,8403220147
- 9 Reportable occurrences, LERs & related correspondence
- 840323014B Forwards Technical Review Rept AEOD/T332, "Reactor Vessel Drainage"
 SALAH-S Reactor Operations Analysis Branch 83/10/07
 SEYFRIT,K V Reactor Operations Analysis Branch 1p 22743 358.
 24X Fiche 50-416,83/10/07:8403230148.
- ---B403230150 "Reactor Vessel Drainage," technical review rept.No further evaluation necessary SALAH,8 Director's Office 83/10/07, 3pp 22743 357 24X Fiche 30-416,83/10/07,8403230148
- B403010451 Informs Commission of problems w/emergency diesel generators mfg by Transamerica Delaval. Inc DIRCKS.W J Office of the Executive Director for Operations, BECY-83-034 84/01/25 4pp 22438 347 24X Fiche 50-000,84/01/25,8403010451
- 8403010121 Updated LER 83-181/03X-1.on 831110, channel C as-found setpoints for undervoltage trip were 116 2-volt ac Cause unknown Voltage adjusted within desired range. W840221 1tr PARKER, J. DALE, L. F. Hississippi Power & Light Co. 84/02/21 0'REILLY, J. P. Region 2, Office of Director, 3pp. 22436:035, 24X Fiche 50-416,84/02/21,8403010121
- 8403020406 Advises that draft "Final Rept on Div I & II Transamerica Delaval, Inc Diesel Generators: "forwarded to NRC on 840216 will be submitted in final form on 840221. HOUSTON.M D Licensing Branch 2 84/02/21. Licensing Branch 2 3pp 22492 104 24X Fiche 50-416.84/02/21,8403020406
- ~~8403020410 Draft "Final Rept on Div I & II Transamerica Delaval, Inc Dissel Generators " * Mississippi Power & Light Co 84/02/15 74pp, 22492.107, 24X Fichs 50-416,84/02/21,8403020406
- 8403060453 Discusses deficiencies discovered in Delaval emergency diesel generators Written submittal requested giving details of snhancement program to justify interim operation EISENHUT.D G Division of Licensing 84/02/24. RICHARD. J B. Hississippi Power & Light Co 4pp 22550.003. 24X Fiche 50-416.84/02/24.8403060453.
- 8403080011 Forwards response to Commissioner Gilinsky request for info on frequency of personnel errors at selected operating plants. Summary of tabulated events re operator errors, personnel errors or procedural errors provided for CVB3 DIRCKS: W J Office of the Executive Director for Operations. 84/02/24 PALLADINO Commissioners 17pp 22584.142. 24X Fiche 50-000.84/02/24,8403080011.
- 8403090091 LER 84-006-00 on 840120 during drywell high pressure channel A functional test, indicator light failed to illuminate Caused by failure of test procedure to properly instruct technicians Procedure being revised W1840224 ltr. BYRD.R.W. DALE-L.F. Mississippi Power & Light Co. 84/02/24 3pp 22576.035 24X Fiche 50-416.84/02/24,8403090091.
- 8403090192 Final RO 84-006/O on 840118, Fire Doors 1A312, 0C414, 0C103 & 1A314 taken out of syc for maint Caused by demage as result of heavy use Fire watches established until doors restored, DALE/L F Mississippi Power & Light Co 84/02/24 0'REILLY, J. P Region 2. Office of Director. 2pp 22573 307. 24X Fiche. 50-416, 84/02/24, 8403090192
- 8403010207 Forwards "Investigation of Types AF & AE Piston Bkirts," per Transamerica Delaval, Inc Owners Group program commitments. Rept evaluates cracks in AF piston skirts in Shoreham & Grand Gulf Nuclear Power Stations.

 MUSELER, W. J. TDI (Transamerica Delaval, Inc.) Owners Group, MUSELER, W. J. Long Island Lighting Co. 84/02/27 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 3pp. 22434-090, 24X Fiche: 30-000, 84/02/27, 8403010207
- --B403010446 "Investigation of Types AF & AE Piston Skints."

 * Failurs Analysis Associates FAAA-84-2-14. B4/02/27. B3pp. 22434 093. 24X Fiche 50-000.84/02/27.8403010207
- 8403140203 Forwards "Operating History Overview for Diesel Generators in Nuclear Syc," comparing Transamerica Delaval, Inc generators w/generators mfg by other vendors HEBDON, F.J. Program Technology Branch. 84/02/27. BERLINGER, C. H. NRC No Detailed Affiliation Given. 1p 22638:319. 24% Fiche 50-000,84/02/27,8403140203.

- ---8403140205 "Operating History Overview for Diesel Generators in Nuclear Svc "
 - Bvc " * Director's Office 84/02/27 65pp 22637 001 24x Fiche 50-000.84/02/27.8403140203
- 8403010218 Forwards task descriptions for 16 known problems re Transamerica Delaval, inc emergency diesel generators MUSELER, W J TDI (Transamerica Delaval, Inc.) Gwners Group MUSELER, W J Long Island Lighting Co 84/02/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 42pp 22435 177 24% Fiche 50-000,84/02/28,8403010218
- 8403240233 Forwards summary list of deficiencies identified per 10CFR50 55(e), Part 21 & potential generic ltr repts for comments
 8TAR08TECKI, R Division of Project & Resident Programs 84/02/28
 - STAROSTECKI, R Division of Project & Resident Programs 84/02/28 Region 1, Office of Director 7pp 22756 065 24X Fiche 50-000.84/02/28.8403260233
- 8402090020 Board Notification 84-044 forwards Part 21 rept re Transamerica Delaval. Inc turbocharger thrust bearing Lubrication defect resulting in angine nonavailability EISENHUT, D G. Division of Licensing 84/02/29 PALLADINO, GILINSKY, ROBERTS Commissioners 4pp 22541 263 24X Fiche 50-000,84/02/29.8402090020
- B403070265 Final Deficiency Rept PRD B3/08 re inability to maintain pressurized water supply to RHR pumps & discharge piping supplied by Bechtel Initially reported on 830415 Handware mods implemented Also reportable per Part 21 MCQAU0HY, J.P. Mississippi Power & Light Co 84/03/02 O'REILLY, J.P. Region 2. Office of Director 4pp 22572 144 24x Fiche.50-416,84/03/02,8403090265.
- 8403120148 LER 84~007-00 on 840128, discovered Halon sys control panel for computer & control panel room w/missing fuses Cause unknown Fuses replaced W/840302 ltr PARKER, J. DALE, L.F. Mississippi Power & Light Co. 84/03/02 3pp 22585:257 24X Fiche: 50-416,84/03/02,8403120148
- 9403120159 Special Rept B4-007/0 on 840131 & 0210, bolts securing Div i standby diesel generator left bank turbocharger failed during 100 h test runs No noticeable effect on Engine performance noted LER 83-107 will be updated DALE, LF Mississippi Power & Light Co. 84/03/02 0'REILLY, JP Region 2, Office of Director 2pp 22586'253 24X Fiche. 50-416.84/03/02.8403120159
- 8403130075 Updated RD 83-088/1 on 830704, control room temp reached 80 F.exceeding limit of 77 F No immediate disqualification of affected equipment occurred Worst case effect is reduction of equipment qualified life.

 BALE, L F Mississippi Power & Light Co 84/03/02 O'REILLY, J P Region 2, Office of Director 2pp 22579, 001, 24X Fiche 50-416,84/03/02,8403130075
- 8403130192 Updated LER 83-185/03X-1 on 831201, while in cold shutdown, breaker 552-2105 tripped, causing loss of power to DIv 1 ESF bus & all balance of plant loads Caused by two shorted wires in breaker hand switch Wires altered W/840302 itr BYRD,R., DALE,L.F Mississippi Power & Light Co 84/03/02 0'REILLY,J P Region 2, Office of Director, 3pp 22617.295 24X Fichs.50-416,84/03/02,8403130192.
- B403130274 Updated LER B3-154/03X-1: on B31003, capscrew securing starting air manifold to support plats on left bank cylinder B found broken inside plats Cause undetermined Capscrew replaced W/B40302 ltr.
 BYRD.R., DALE,L.F. Mississippi Power & Light Co B4/03/02 0'/RELLY,J.P. Region 2, Office of Director 3pp. 22617-130 24% Fiche 50-414,84/03/02,8403130274.
- 8403140048 Forwards "Grand Gulf Component Tracking Sys," "Shoreham Component Tracking Sys" & "Transamerica Delaval, Inc Diesel Generators Guners Group Program Plan," to resolve concerns w/emergency diesel generators MUSELER, W J. Long Island Lighting Co 84/03/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22626 062 24% Fiche: 50-000, 84/03/02, 8403140048
- --8403140080 "Orand Oulf Component Tracking Sys " # Long Island Lighting Co. 84/02/29 879pp 22626.064. 24X Fiche, 50-000, 84/03/02, 8403140048.
- --B403140095 "Transamerica Delaval, Inc Diesel Generators Dwners Group Program Plan." * TDI (Transamerica Dalaval, Inc.) Owners Group 84/03/02 261pp 22628: 223. 24X Fiche: 50-000. 84/03/02, 8403140048

- 8403130248 RO 84-008/O on 840124, fire barriers located in U720 control room floor modules LA59-LO1 & LA39-LO4 opened to implement design change package Fire watch established Work task will be completed by 840416

 DALE, L F Mississippi Power & Light Co 84/03/05 O'REILLY, J P Region 2, Defice of Director 2pp 22617 237 24X Fiche 50-416,84/03/05,8403130248
- 8403130253 Special Rept 84-009/0 on 840121, smoke detector in Zone 2-4 covered for planned maint activities Caused by welding in piping room Fire watch established Zone reset & restored to operability on 840206
 DALE, L.F. Mississippi Power & Light Co. 84/03/05 O'REILLY, J.P. Region 2. Office of Director 2pp 22617 135 24V
 Fiche 50-416,84/03/05,8403130253
- 8403190059 LER 84-008-00 on 840202 during cold shutdown control power to HPCS pump last Caused by incorrect info on electrical lineup sheet of sys operating instruction Instructions changed to correct breaker info W/840305 ltr PARKER, J. DALE, L. F. Mississippi Power & Light Co. 84/03/05 3pp 22666 197 24X Fiche 50-416,84/03/05,8403190059
- 8403190115 Special Rept 84-005/0 on 840201, HPCS diesel generator tripped on low lube oil pressure during routine surveillance Caused by failed relay Agastat relay replaced w/identical component & similar type relays calibr DALE.L F Mississippi Power & Light Co 84/03/05. D'REILLY, J P Region 2. Office of Director 2pp 22666 264 24X Fiche 80-416, 84/03/05, 8403190115
- B403300251 Summary of 840221 meeting w/util in Bethesda, MD re details of util proposed onsite/offsite electrical power reliability program for Transamerica Delaval. Inc diesel generators Attendance list & viewgraphs encl
 HOUBTON, M D Licensing Branch 2 84/03/06 Licensing Branch 2 21pp 22845 001 24X Fiche 50-416.84/03/06.8403300251
- 8403120196 Part 21 rept re Westinghouse Type SA-1 DBR or DBRV standby diesel generator differential relay defect Relay problem reported in 840215 Suppl 1 to IE Info Notice 83-63 RTE Delta requested to review defect & recommend correction BDYER.R E Transamerica Delaval, Inc. 84/03/07 Director's Office, Office of Inspection and Enforcement 2pp 22585 219 24X Fiche 50-416,84/03/07,8403120136
- B403130464 LER B4-003-00 on B40210, while power removed from control room fresh air unit chloring detector B.per maint work order, unit started up automatically in isolation mode Caused by personnel error Personnel counseled W/840308 ltr PARKER, J. DALE, L.F. Mississippi Power & Light Co B4/03/08 3pp 22613 249 24% Fiche 50-416,84/03/08,8403130464
- 8403190033 Updated LER 83-126/01X-1 on 830904, Div 1 diesel generator fuel line ruptured, causing fire near left bank turbocharger Caused by fatigue crack propagation Fuel line support added to Div 1 & 2 diesel generators W/840308 ltr BYRD,R, DALE,LF Mississippi Power & Light Co 84/03/08 D'REILLY,J P. Region 2, Office of Director 7pp 22666 115 24X Fiche 50-416,84/03/08,8403190033
- B403200064 Updated LER 83-i79/03x-1. on 83i105. Div II diesel generator shut down upon discovery of fuel oil return line leak After repair during restart, generator tripped due to isolation of fuel supply valve F016B W/840308 ltr.
 BYRD,R W , DALE,L F Mississippi Power & Light Co 84/03/08 U'REILLY,J P Region 2, Office of Director 4pp 22684 357 24X Fichs 50-416,84/03/08,8403200064.
- 8403190043 Special Rept 84-013/0 on 840127, smoke detectors in Zone 2-10 alarmed & would not reset Fire watches established per Tech Spec 3.3 7 9, Caused by accumulation of dust particles on ionization detector Detectors cleaned & reset DALE, L.F. Mississippi Power & Light Co. 84/03/09 Q'REILLY, J.P. Region 2, Office of Director 2pp. 22666 246 24X Fiche 50-416,84/03/09,8403190043
- B403190331 Special Rept 84-012/0 on 840201, special fire door insp reyealed 147 doors in auxiliary & control bldgs not in compliance w/spec requirements Updated rept expected by 840831. DALEL F Mississippi Power & Light Co 84/03/09 O'REILLY, J P Region 2, Office of Director 2pp 22673, 280 24X Fiche 80-416, 84/03/09, 8403190331
- B402090039 Board Notification 84-052 forwards meeting summaries containing transcripts of B40210 & 16 meetings between NRC & Transamerica Delayal, Inc (TDI) Owners Group Distribution list encl EISENHUT, D @ Division of Licensing 84/03/12 PALLADING Commissioners 5pp 22708:001 24x Fiche 50-000,84/03/12, B402090039

- 3060536 Forwards summary of 840210 meeting w/Transamerica Delavaling Clumers Group in Bethesda.HD re problems w/emergency issel generators
 ARUBOLR Literaing Branch 2 84/02/27 D'REILLY, J P NRC No
- ARUBD R Licensing Branch 2 84/02/27 0'REILLY, J P NRC No etailed Affiliation Given 6pp 22708 006 24X iche 50-000,84/03/12,8402090039
- 2060554 Transcript of S40210 meeting w/Transamerica Delaval.Inc uners Group in Bethesda.MD re problems w/emergency diesel enerators
- ons No Detailed Affiliation Given 84/02/10. 147pp 008 24% Fishe 50-000.84/03/12,8402090039
- 3070409 Summary of 840216 meeting w/Transamerica belaval, Int Owners roup in Hading River.NY re-program plan to establish silability of dissel generators Agenda meeting transcript & ttendance list encl aance 11ss enct R.M.A. Licensing Branch 4 B4/02/27 Licensi 2270B 161. 24% Fiche 50-000,84/03/12,8402090039 Licensing Branch 4
- 1070423 Transcript of B40214 conference in Wading River, NY re 'ansamerica Belaval, Inc diesel generators Pp 1-82 Commissioners 84/02/16 84pp 2270B 169. 24X chs 50-000, 84/03/12, 8402070037
- i0050 Forwards "Design Review of Connecting Rod Bearing Shells for isamerica Delaval Enterprise Engines" For Shoreham \$,d Gulf diesel generators
 LER,W J Long Island Lighting Co 84/03/12. DENTON.H R ce of Nuclear Reactor Regulation. Director 2pp 22632 074
 Fiche 50-000,84/03/12,8403140050
- 1140086 "Design Review of Connecting Rod Bearing Shells for ansamerica Delaval Enterprise Engines " Failure Analysis Associates PAO 7396 84/03/12 5ipp 632 076 24% Fiche 50-000.84/03/12.8403140050
- 0216 Special Rept 84-010/0 on 840210, diesel generator 12 failed tart on manuel initiation signal from control room ed by erroneous step in procedure resulting in improper stment of lifters during pushrod replacement. L. F. Mississippi Power & Light Ca 84/03/12 0/REILLY, J. P. on 2. Office of Director 2pp 22670 246 24% e 50-416.84/03/12.8403190216
- 0292 Special Rept B4-014/0.on B40204, listed fire doors blocked to support planned maint activities. Fire watches blished per Tech Spec S. 7.7 until doors restored .L.F. Mississippi Power & Light Co. 84/03/12 0'REILLY, J. P. on 2. Office of Director 2pp 22674 359 24X e 50-416.84/03/12.8403190292
- 0017 Updated LER 83-189/03X-i on B31207 & 840201, breaker 152-1704 iv 3 EBF bus tripped Caused by broken current limiter stor socket for breaker position indicating light tat relay 7012 replaced W/B40312 ltr .R . DALE.L F Mississippi Power & Light Co B4/03/12 ILLY.J P Region 2. Office of Director 4pp 22698 346 24X e 50-416.84/03/12.8403200017
-)133 Forwards "Transamerica Delaval, Inc Diesel Generator Rocker Capscrew Stress Analysis Rept " Capscrew design adequate applicable engines & syc conditions LER, W J TDI (Transamerica Delaval, Inc.) Dwners Group 3/13 DENTON, H R Office of Nuclear Reactor Repulation, ctor 2pp 22/39, 270 24X Fiche: 50-000, 84/03/13, 8403150133 DENTON. H R OFF 2pp 22537.270
- Ol4 Special Rept B4-015/O on 040229, GA identified failure to orm monthly verification per Item 2 C(28) requiring fuel pool coolers to be isolated from standby svc sys Temporary change notice initiated LF Mssissippi Power & Light Co. 04/03/13. 0'REILLY, J P n 2. Office of Director 3pp 22403 353 24X > 50-414,84/03/13,8403200014
- 1192 Final deficiency rept re anti-rotational satscrews in Anchoring glove valves Initially reported on B40219. Setscrew and & stem collar threads staked using ctr punch reported per Part 21 for Unit 1, IGHY, J.P. Mississippi Power & Light Co. 84/03/14 LLY, J.P. Region 2, Office of Director. 5pp. 22707, 257—24X 50-416, 84/03/14, 8403210192.
- 222 Responds to 840214 Requests for Info 1 & 2 re A-4 series es List indicating engine number, madel & syc number, mer name & address, rating, date shipped & date started
- WS,C 8 Transamerica Delaval, Inc 84/03/16 EIGENHUT,D 0 ion of Licensing 20pp. 22691 179 24X Fiche,50-000,84/03/16. 00222

- 8403240244 Updated LER 83-171/03x-1 on 831028, fuel oil leak & broken connector sushred discovered Caused by crack in oil tubing & difficulty in welding pushrod Tubing & pushrod replaced H/040314 1tr MYGNOTH IV BYRD.R : DALE,L F Mississippi Power & Light Co 84/03/16 O'REILLY,J P Region 2: Office of Director 4pp 22/54,355 24X Fiche 50-416.84/03/16.8403260244
- 8403300114 Special Rept 84-011/0 broadleaf vegetation samples unavailable for collection in Feb 1984 due to unseasonable weather conditions Required sampling will resume when vegetation recovered from harsh weather conditions DALE: L F Mississippi Power & Light Co 84/03/20 O'REILI Region 2. Office of Director ip. 22821 236 24% Fiche 90-416.84/03/20,8403300114 ens /20 o'REILLY,JP 24x
- 8403300007 Updated Special Rept 84-003/i on 840i12.standby diesel generator 12 tripped on reverse power while running parallel w/offsite power Gaussé by faulty control rectifier diode Reactifier replaced DALG: LF Hississippi Power & Light Co 84/03/21 O'REILLY, J Region 2. Office of Director 2pp 22822 127 24X Fiche 50-416.84/03/21.8403300007
- 8403300027 Updated LER 83-122/01X-1 on 830908, valve P64F467 which supplies operating pressure to CO2 fire protection master selector valve found closed Cause Unknown Valve now locked open W/840321 itr
 BYRD.R. DALE,L.F. Mississippi Power & Light Co 84/03/21
 0'REILLY,J.P. Region 2, Office of Director 4pp 22822 184
 Fiche 50-416,84/03/21,8403300027
- 8403300037 Updated LER 83-169/03X-1 on 831023, nitrogen pressure in control rod scram accumulators 40-53 & 24-29 fell below 1,520 psig Caused by normal leakage Pressure switch & gauge tested W/840321 ltr
 BYRD.R., DALE.L. F Mississippi Power & Light Co 84/03/21
 O'REILLY.J P Region 2, Office of Director 3pp 22821 237 24X
 Fiche 50-416,84/03/21,8403300037
- 840.3300082 Updated Special Rept 84-111/1 on 830328.fire penetration CE-519D in computer room opened under maint work order (NNO) to install conduits Caused by design closure datail being omitted from MND Programmatic control implemented. DALE, L.F. Mississippi Power & Light Co. 84/03/21 D'REILLY, J.P. Region 2. OFfice of Director 2pp 22822 076 24X Fiche 50-416,84/03/21,8403300082
- 8403300113 Update LER 82-080/01X-4 on 821004, capscrew on Div 2 standby diesel generator securing rear crankcase cover to engine block cracked Caused by fatigue due to engine operation Capacreus raplaced. M/840321 ltr BYRD.R., DALE.L.F. Mississippi Power & Light Co. B4/03/21 D'REILLY, J.P. Region 2, Office of Director 5pp 22821 231 24X Fiche 50-416.84/03/21,8403300113
- 8403300117 Updated LER B3-18B/03X-1 on 831201, reactor protection sys Bus B & shutdown cooling lost when power supply breaker tripped Caused by isolation valve on suction of pump closing Time delay setting increased to 3 5 s W840321 ltr BYRD:R, DALE,L F Mississippi Power & Light Co 84/03/21, D'REILLY,J P Region 2, Office of Director 3pp 22820:252, 24X Fiche 30-416,84/03/21,8403300117
- 8403300118 Updated LER 83-190/03x-1 on 831214. Div 2 isolation occurred, causing loss of shutdown cooling when pump suction valve F007 isolated Caused by temporary outage restoration procedure error. Procedure retired W/840321 itr PARKER, J. DALE, L.F. Mississippi Power & Light Co. 84/03/21 O'REILLY, J.P. Region 2. Office of Director 3pp. 22820: 310 24X Fichs 50-416,84/03/21.8403200118
- 8403300124 Updated Special Rept 84-110/1 on 831213/Fire Door 1A320 NOSCOURT Updates Special Rept 84-1071 on Galls/Fire Nor 18320 blocked open to support planned maint & testing activities Fire watches established until door restored on 840306 DALE, L.F. Mississippi Fower & Light Co. 84/03/21 0'REILLY, J.P. Region 2. Diffice of Director ip 22821 101. 24X Fithe 50-416.84/03/21,8403300124
- 8403270132 Forwards "Emergency Diesel Generator Air Start Valve Capscrew Dimension & Stress Analysis," prepared by S&W for Transamerica Delaval, Inc (TDI) Diesel Generator Owners Oroup MUBELER, H.J. TOI (Transamerica Delaval, Inc.) Owners Group. MUBELER, H.J. Long Island Lighting Co. 84/03/23 DENTON. H.R. Office of Nuclear Reactor Regulation, Director 2pp. 22774-024X Fiche 50-000.84/03/23.8403270132

- B403270134 Requests meeting on 840418 to discuss short-term & long-term corrective actions & investigations re Transamerica Delaval diesel generators List of suggested meeting topics encl MCGAUGHY, J P TDI (Transamerica Delaval, Inc.) Owners Group MCGAUGHY, J P Mississippi Power & Light Co 84/03/23 DENTON, H R Dffice of Nuclear Reactor Regulation, Director 4pp 22769 133 24X Fiche 50-000, 84/03/23, 8403270134
- T Hearing transcripts on non-antitrust matters
- B40306008B Transcript of 840227 hearing in Vicksburg, MS Pp 1-95
 * Atomic Safety and Licensing Board Panel 84/02/29 103pp
 22306,001 24x Fiche 50-416.044/02/29,440306008B
- 8403070378 Transcript of Commission 840229 briefing in Washington, DC re status of util progress toward obtaining full power OL Pp 1-93 Bupporting documentation and Commissioners 8402/29 101pp 22567 090 24X Fiche 50-416
- B402070039 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delaval, Inc (TDI) Owners Group Distribution list encl EIGENHUT.D 0 Division of Licensing 84/03/12 PALLADING Commissioners 5pp 22708 001 24X Fichs 50-000,84/03/12,8802000039
- --8403060536 Forwards summary of 840210 meeting w/Transamerica Delaval, Inc Owners Group in Bethesda, MD we problems w/emergency diesel generators CARUBO, R Licensing Branch 2 84/02/27 O'REILLY, J P NRC No Datailed Affiliation Given App 22708 006 24X Fiche 50-000, 84/03/12, 8402090039
- --B403060554 Transcript of B40210 meeting w/Transamerica Delaval, Inc Owners Oroup in Bethesda, MD re problems w/emergency diesel generators * NRC - No Detailed Affiliation Given 84/02/10 147pp 67201 008 24X Fiche 50-000,84/03/12,8402090039
- ~-8403070407 Summary of 840216 meeting w/Transamerica Delaval, Inc Owners Oroup in Wading River, NY re program plan to establish reliability of diesel generators Agenda, meeting transcript & attendance list encl.
 MILLER, M A Licensing Branch 4 84/02/27 Licensing Branch 4 8pp 22708 161. 24X Fichs 50-000.84/03/12,8402090039
- ---8403070423 Transcript of 840216 conference in Wading River, NY re Transamerica Delaval, Inc diesel generators Pp 1-82 * Commissioners 84/02/16 84pp 22708 169 24X Fichs 30-000,84/03/12,8402070037
- 8403230195 Transcript of 840320 brisfing in Washington,DC re Tech Spec requirements Pp 1-74 Supporting documentation encl * Commissioners 84/03/20. 8599 22759 178 24X Fichs.50-4i6.84/03/20.8403230195

V Operator Examinations

- 8403270074 Forwards updated info on operating shift experience to supersede previous submittal, including chart of experience levels of five proposed operating shifts.

 DALE, L. F. Mississippi Power & Light Co. 84/03/16 DENTON. H. R. Office of Nuclear Reactor Regulation. Director 8pp 22806 341 24X Fiche 50-416.84/03/16.8403270074.
- X Onsite Storage of Low Level Waste
- 8403220136 Informs of plans for meeting classification & waste form requirements of 100FR61. Contractor currently dewatering resins w/approved procedures to ensure no free standing water sxists

 DALE, L. F. Mississippi Power & Light Co 84/03/16 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 3pp 22715 335
 24X Fiche: 50-416, 84/03/16, 8403220136
- DOCKET 30-417 GRAND GULF NUCLEAR STATION, UNIT 2

 A. Application/construction stage documents & correspondence
- B4031A0232 Forwards request for add1 info re const GA program to complete evaluation of changes to program LEWIG.R.C Division of Project & Resident Programs 84/02/13 RICHARD.J B Mississippi Power & Light Co 3pp 22660 115 24 Fiche: 50-417, 84/02/13, 8403160252

- B403070325 Forwards info re shift advisors, including job description MCGAUGHY. JP Mississipp: Power & Light Co 84/02/20 DENTON.H R Office of Nuclear Reactor Regulation, Director App 22546 198 24X Fiche 50-416. B4/02/20, B403070325
- 8403080367 Responds to FDIA request for documents re BMR Integranular Stress Corrosion Cracking Duners Oroup meeting on or about 811029 Forwards App A documents Records also in PDR FELTON, J M Division of Rules and Records 84/02/28 HAFNER, B 8uffolk Nuclear Study Group 2pp 22583 008 24X Fiche 50-000,84/02/28.8403080367
- --8309210434 Requests evaluation of Grand Gulf & Shoreham 830817 & 23 responses, respectively re intergranular stress corresion cracking in BWR piping Response requested by 830916 W/o encl
 EISENHUT.D & Division of Licensing 83/09/06 VOLLMER.R Division of Engineering ip 22583 010 24X Fiche 50-000,84/02/28,8403080367
- 8403050236 Forwards detailed breakdown of approx 200 Tech Spec changes requested by licensee & categorized in Dircks 840202 memo DIRCKS, W J Office of the Executive Director for Operations 84/02/29 PALLADIND, OIL INSKY, ROBERTS Commissioners 36pp , 22527 215 24x Fiche 50-416.84/02/29,8403050236
- 8403210109 Bubmits interim response to B40224 ltr requesting certification re Tech Specs & FBAR Review & certification program in progress Meeting scheduled for B40309 to discuss program scape, review criteria & schedule DALE/L F Mississippi Power & Light Co B4/03/08 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22704 360 24X Fiche 50-416.84/03/08,8403210109
- B403210053 Endorses SH Hobbs Feb 1984 Ltr HGN-015 to HR Denton in response to NRC B31208 request for add1 into re Hydrogen Control Owners Group (HCG6) test program Questions to be answered by HCDG & util.respectively, listed DALE, L F Mississipp: Power & Light Co 84/03/09 DENTON, H R Office of Nuclear Reactor Regulation. Director 2pp 22704 344 24X Fiche 50-416,84/03/09,8403210053
- 8403210057 Forwards description of Teth Spec review program, per 840224 request Program estimated to end on 840406 Formal response expected by 840409 MCGAUGHY, J P Mississippi Power & Light Co 84/03/18 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22705 021 24X Fiche 50-416.84/03/18.8403210057
- --BA03210062 "Tech Spec Review Program Description " * Mississippi Power & Light Co 84/03/31 20pp 22705 023 24X Fiche 50-416,84/03/18,8403210057
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B dacument entirely withheld (ref FOIA Exemption 5) Review of addl documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, S I Garvey, Schubert, Adams & Bener 7pp 22583 226 24X Fichs 50-000,84/02/13,8403080179
- --8005130793 Provides status of SER inputs & acceptance reviews for OL & CP applications Schedule should be met
 BURKE.N C Effluent Treatment Systems Branch 80/02/06
 KREGER.W E Assistant Director for Site Analysis 1p 22583 235
 24X Fiche 50-000.84/02/13.8403080179
- 8403210140 Forwards confirmation of Lonergan safety relief valve qualification & operability testing of reclassified valves, per util 821108 & 18 trs & 85ER 4

 DALE, L F Mississippi Power & Light Co 84/03/13 DENTON, H R

 Office of Nuclear Reactor Regulation, Director 4pp 22707 276

 24X Fiche 50-416,84/03/13,8403210140
- F Security, medical, emergency & fire protection plans
- 8403210115 Forwards 8ALP Repts 50-416/83-55 & 50-417/83-09 for Sept 1982 - Sept 1983 LEWIS,R C Division of Project & Resident Programs 84/01/11 RICHARD. J B Mississippi Power & Light Co 2pp 22707 144 24X Fiche 50-416,84/01/11,8403210115
- --8403210122 BALP Repts 50-416/83-55 & 50-417/83-09 for Sept 1983 * Region 2, Office of Director 84/01/11 32pp 22707 146 24X Fiche 50-416,84/01/11,8403210115

- 8403160281 Notifies of 840316 workshop to discuss 10CFR50.App R requirements & insp results to resolve misunderstandings refire protection Attendees should be limited to six due to size of conference room LEWIS.R C Division of Project & Resident Programs 84/03/02 RICHARD.J B Mississippi Power & Light Co ip 22660 350 24X Fiche 50-416.84/03/02,8403160281
- 8403160336 Discusses util 840224 ltr re 1984 emergency exercise Exercise objectives reviewed & comments provided to P Benedact, corporate emergency preparedness coordinator VERRELLI, D M Division of Project & Resident Programs 84/03 RICHARD, J B Mississippi Power & Light Co 1p 22660 031 Fiche 50-416,84/03/05.8403160336 84/03/05
- 8403150052 Forwards State of LA 831227 request for exemption from full participation at 840410 annual radiological emergency preparedness exercise FEMA supports exemption, based on State of LA full participation in Waterford exercise KRIMM.R W Federal Emergency Management Agency 84/03/09 JGRDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 3pp 22641 355 24X Fiche 50-416,84/03/09,
- G Adjudicatory correspondence

P403150052

- 8403210165 Response to Jacksonians United for Livable Energy Policies renumbered Contentions 1.2 & 3 Admission of renumbered contentions acceptable Certificate of Svc encl WAGNER, M E Hearing Branch 4 DSB 016 84/03/19 Atomic Safety and Licensing Board Panel 7pp 22718 217 24X Fiche: 50-416, 84/03/19, 8403210165 Atomic Safetu
- 8403270318 Forwards staff 830319 response to petitioner renumbered Contentions 1,2 & 3,per request W/o enci WAGNER, M E Hearing Branch 4 DSB 131 84/03/22 STEWART, C Affiliation Not Assigned 19 22787 028 24X Fiche 50-416, 84/03/22,8403270318
- H General correspondence
- B403270211 Expresses concern on safety of facility NRC should not allow operation before plant meets safety criteria HIENER, J. L. Affiliation Not Assigned B4/03/22 DENTON, H R Office of Nuclear Reactor Regulation. Director 2pp 22772 144 24X Fiche 50-416,84/03/22,8403270211
- J Insurance & indemnity information
- 8403140121 Forwards Endorsement 29 to NELIA Policy NF-257 & Endorsement 103140141 FORMATOS ENGOSEMENT 27 TO NELIA FOLICY NI-237 & ENG 11 to MAELU Policy NF-106 DALE.L F Mississippi Power & Light Co 84/03/02 KERR, 0. W Office of State Programs, Director 4pp 22680 284 24X Fiche 50-416.84/03/02,8803140121
- Q Inspection reports, IE Bulletins & correspondence
- 8403070268 Responds to questions raised during special safety insp on 830322-25 re IE Bulletin 80-11 that three morter cube compression tests did not meet min compressive strength requirements Structural integrity unimpaired, DALE, L. F. Mississippi Power & Light Co. 83/12/30 O'REILLY, J. P. Regian 2. Office of Director App. 22546 086 24X Fichs 50-416,83/12/30,8403070268
- 8403210115 Forwards SALP Repts 50-414/B3-55 & 30-417/B3-09 for Sept 1982 Sept 1983 LEWIS,R. C Division of Project & Resident Programs 84/01/11 RICHARD, J B Mississippi Power & Light Co 2pp 22707-144 Fiche 50-416,84/01/11,8403210115
- ~-8403210122 SALP Repts 50-416/83-55 & 50-417/83-09 for Sept 1982 -Rept 1953

 * Region 2. Office of Director 84/01/11 32pp 22707 146 24X
 Fiche: 50-416, 84/01/11, 8403210115
 - 1190072 IE Info Notice 84-13, "Potential Deficiency in Motor perated Valve Control Circuits & Annunciation " Svc list JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22909 239 24X Fiche 50-000,84/02/28,8401190072
- B402090007 IE Info Notice 84-14. "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list enc! GRACE.J N Division of GA. Bafeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp. 22552 329 24X Fiche 50-000.84/03/02.8402090007

- B402090008 IE Info Notice B4-16, "Failure of Automatic Sprinkler Bys Valves to Operate " Svr list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/02 Consolidated Edison Co of N Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 078, 24X Fiche 50-000,84/03/02,8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases " Svc list encl UVC 11st encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02. Consolidated Edison Co. of New York, Inc. 119pp 22553,217 24X Fiche 50-000,84/03/02,8402090009
- 8403120034 Staff requirements memo re 840229 briefing in Washington, DC re BALP review of areas prior to issuance of full-power recommendation & document interpreting LER rept CHILK, B J Office of the Secretary of the Commission 84/03/02 DIRCKS, W J Office of the Executive Director for Operations ip 22617 346 24X Fiche 50-416,84/03/02,8403120034
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000.84/03/05,8402090011
- 8402070024 IE Info Notice 84-09. Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Bys " Byc list encl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York Inc 118pp 22635 049 24X Ficha 50-000.84/03/07.8402070024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR 02090028 in introduction of Emergency Preparedness & Engineering
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/07 Consolidated Edison Co of New
 York, Inc 118pp 22584 186 24X Fiche 50-000.84/03/07,8402090028
- 8402090031 IE Bulletin 84-02, "Failures of QE Type HFA Relays in Use in Class IE Safety Sys " Syc list encl DEYOUND.R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000.84/03/12.8402090031.
- 8403290030 Provides interim response to IE Bulletin 83-07, "Apparently Fraudulent Products Bold by Ray Miller, Inc " Results of investigation to date indicate no Ray Miller products supplied to facilities Final response expected by 840325 MCGAUGHY, J P Mississippi Power & Light Co 84/03/13, 0'REILLY, J P. Repion 2, Office of Director, Spp 22806 224, 24X Fichs 50-416.84/03/13.8403290030.
- B402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl.

 JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc. 123pp 22823 227 24X Fichs 50-000,84/03/21,8402090043
- 8402090044 IF Into Notice 84-20, "Byc Life of Relays in Safety-Related Sys "Syc 1 JORDAN, E L ORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001, 24X Fiche 50-000,84/03/21,8402090044
- R Periodic operating reports & related correspondence
- 8403020443 Forwards monthly status rept of offsite emergency preparedness for OL reviews for Jan 1984 Changes in FEMA finding dates not caused by delay due to offsite emergency planning issues
 DIRKER, W J Office of the Executive Director for Operations
 84/02/21 PALLADINO Commissioners 9pp 22492,083 24X
 Fichs 50-000,84/02/21,8403020443
- 8 Reportable occurrences, LERs & related correspondence
- B403010451 Informs Commission of problems w/emergency diesel generators mfg by Transamerica Delaval, Inc DIRCKS, W J Effice of the Executive Director for Operations, SECY-83-034 84/01/25, 4pp, 22438 347, 24X Fichs 50-000,84/01/25, 8403010451
- 8403010207 Forwards "Investigation of Types AF & AE Piston Skirts," per 403010207 Forwards "Investigation of Tupes AF & AE Piston Skirts,"
 Transamerica Delaval, Inc Owners Group program commitments.
 Rept evaluates cracks in AF piston skirts in Shoreham &
 Grand Gulf Nuclear Power Stations
 MUBELER, W. J. TDI (Transamerica Delaval, Inc.) Owners Group,
 84/02/27 DENTON, H.R. Office of Nuclear Reactor Regulation,
 Diractor 3pp 22434.090 24X Fiche 50-000,84/02/27,8403010207

- --8403010446 "Investigation of Types AF & AE Piston Skirts "
 # Failure Analysis Associates FAAA-84-2-14 84/02/27 83pp
 22434 093 24X Fiche 50-000.84/02/27.8403010207
- 8403140203 Forwards "Operating History Overview for Diesel Generators in Nuclear Svc," comparing Transamerica Delaval: Inc generators w/generators mfg by other vendors HEBDON: FJ Program Technology Branch 84/02/27 BERLINGER, CH NRC - No Detailed Affiliation Given 1p 22638 319 24X Fichs 50-000,84/02/27,8403140203
- --8403140205 "Operating History Overview for Diesel Generators in Nuclear Bvc." * Director's Office 84/02/27 65pp 22639 001 24X Fiche 50-000,84/02/27,8403140203
- 8403010218 Forwards task descriptions for 16 known problems re Transamerica Delaval. Inc. amorgoncy diesel generators MUSELER.W. J. TDI (Transamerica Delaval. Inc.) Dwners Group MUSELER.W. J. Long Island Lighting Co. 84/02/28 DENTON. H. R. Office of Nuclear Reactor Regulation. Director 42pp 22435 177 24X Fiche 50-000.84/02/28,8403010218
- 8403260233 Forwards summary list of deficiencies identified per 10CFR50 35(e), Part 21 & potential generic ltr repts for comments
 STAROSTECKI.R Division of Project & Resident Programs. 84/02/28 Region 1. Office of Director. 7pp 22756 065 24X Fiche. 50-000, 84/02/28 8403260233.
- 8403090265 Final Deficiency Rept PRD 83/08 re inability to maintain pressurized water supply to RHR pumps & discharge piping supplied by Bechtel Initially reported on 830415 Hardware mods implemented Also reportable per Part 21 MCGAUGHY, J.P. Mississippi Power & Light Co 84/03/02 C'REILLY, J.P. Region 2, Office of Director 4pp 22572 144 24X Fiche. 50-416, 84/03/02, 8403090265
- 840314004B Forwards "Grand Gulf Component Tracking Sys," "Shoreham Component Tracking Sys" & "Transamerica Delaval. Inc Diessl Generators Owners Group Program Plan." to resolve concerns w/emergency diessl generators MUSELER.W J Long Island Lighting Co 84/03/02 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 22626-062 24X Fiche 30-000.84/03/02.840314004B
- --8403140080 "Grand Oulf Component Tracking Sys "

 * Long Island Lighting Co. 84/02/27 879pp 22626 064 24X
 Fiche: 50-000, 84/03/02, 8403140048
- --8403140095 "Transamerica Delaval, Inc Diesel Generators Owners Group Program Plan." * TDI (Transamerica Delaval, Inc.) Owners Group, 84/03/02 261pp 22628:223, 24X Fiche 50-000.84/03/02.8403140048
- 8403120136 Part 21 rept re Westinghouse Type 8A-1 DSR or DBRV standby diesel generator differential relay defect Relay problem reported in 840215 Suppl 1 to IE Info Notice 83-63 RTE Delta requested to review defect & recommend correction.

 80YER:R E Transamerica Delaval, Inc 84/03/07 Director's Office. Office of Inspection and Enforcement. 2pp 22585:219 24x Fiche:50-416,84/03/07,8403120136
- 8402070039 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transmerica Delaval, Inc (TDI) Dwners Group Distribution list encl EIBENNUT.D.O. Division of Licensing 84/03/12 PALLADING Commissioners, 5pp. 22708.001 24X Fiche 50-000,84/03/12,8402070039
- ---B403060536 Forwards summary of 840210 meeting w/Transamerica Delaval, Inc Owners Group in Bethesda, MD re problems w/emergency diesel generatore CARUBO, R. Licensing Branch 2 84/02/27 O'REILLY, J P. NRC No Detailed Affiliation Given. App 22708:006 24X Fiche. 50-000, 84/03/12, 8402090039
- --8403060554 Transcript of 840210 meeting w/Transamerica Delaval, Inc Owners Group in Bethesda, MD re problems w/emergency diesel generators * NRC - No Detailed Affiliation Given, 84/02/10 147pp 67201-008, 24X Fiche-50-000,84/03/12,8402090039,
- --8403070409 Summary of 840216 meeting w/Transamerica Delaval, Inc Owners Group in Wading River, NY re program plan to establish reliability of diesel generators. Agenda, meeting transcript & attendance list encl.
 MILLER, M. A. Licensing Branch 4. 84/02/27 Licensing Branch 4
 Bpp 22708-161 24X Fiche 50-000.84/03/12,8402090039

- --8403070423 Transcript of 840216 conference in Wading River, NY re Transamerica Delaval, Inc diesel generators Pp 1-82 * Commissioners 84/02/16 84pp 22708 169 24x Fiche 30-000, 84/03/12, 8402090039
- 8403140050 Forwards "Design Review of Connecting Rod Bearing Shells for Transamerica Delaval Enterprise Engines" for Shoreham & Orand Oulf diesel generators
 HUSELER.W. J. Long Island Lighting Co. 84/03/12 DENTON.H R
 Office of Nuclear Reactor Regulation. Director 2pp 22632 074
 24X Fichs 30-000.84/03/12,8403140050
- ~-8403140086 "Design Review of Connecting Rod Bearing Shells for Transamerica Delaval Enterprise Engines " * Failure Analysis Associates PAQ 7396 84/03/12 51pp 22632 076 24X Fiche 50~000,84/03/12,8403140050
- 8403130133 Forwards "Transamerica Delaval, Inc Diesel Generator Rocker Arm Capscrew Stress Analysis Rept " Capscrew detign adequate for applicable engines & syc conditions MUSELER, H J TDI (Transamerica Delaval, Inc) Owners Group 84/03/13, DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 22639 270 24X Fiche 50-000.84/03/13,8403150133
- 8403210192 Final deficiency rept re anti-rotational setscrews in Anchor Darling glove valves Initially reported on 840213 Setscrew tightened & stem collar threads staked using ctr punch Also reported per Part 21 for Unit 1 MCGAUGHY. JP Mississippi Power & Light Co 84/03/14 O'REILLY. JP Region 2. Office of Director 5pp 22707 257 24X Fiche 50-416,84/03/14.8403210192
- 840321004i Final deficiency rapt re incorrect operation of Div I & II diesel generator load shedding sequencing sys panels Initially reported on 83092l Circuit cards & card racks returned for mod Reinstallation expected by 840427 MCGAUGHY. JP Mississippi Power & Light Co 84/03/15 O'REILLY. JP Region 2. Office of Director 5pp 22707 032 24X Fiche 50-417.84/03/15,840321004i
- 8403200222 Responds to 840214 Requests for Info i & 2 re R-4 series engines List indicating engine number model & svc number customer name & address, rating, date shipped & date started enci
 MATHEWS C S Transamerica Delaval, Inc 84/03/16 EIBENHUT, D G
 Division of Licensing 20pp 22491 179 24% Fiche 50-000, 84/03/16, 8403200222
- 8403270132 Forwards "Emergency Diesel Generator Air Start Valve Capscrew Dimension & Stress Analysis," prepared by S&W for Transamerica Delaval, Inc (TDI) Diesel Generator Dwners Group MUBELER.W J TDI (Transamerica Delaval, Inc) Owners Group 84/03/23 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 22774 001 24X Fiche 50-000.84/03/23,8403270132
- 8403270134 Requests meeting on 840418 to discuss short-term & long-term corrective actions & investigations re Transamerica
 Delaval dissel generators List of suggested meeting topics
 anci
 MCGAUGHY, J P TDI (Transamerica Delaval, Inc.) Owners Oroup
 84/03/23 DENYON, H R Office of Nuclear Reactor Regulation,
 Director 4pp 22769 133 24X Fiche 50-000,84/03/23,8403270134

T Hearing transcripts on non-antitrust matters

- 8403070378 Transcript of Commission 840227 briefing in Washington.DC re-status of util progress toward obtaining full power GL Pp 1-93 Supporting documentation ent1 & Commissioners 84/02/27 101pp 22567 090 24X Fiche 50-416,84/02/29,8403070378
- 8402090039 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transsamerica Delaval. Inc (TDI) Duners Group Distribution list ancl EIBENHUT.D G. Division of Licensing 84/03/12 PALLADINO Commissioners 5pp 22708.001. 24X Fiche 50-000.84/03/12.8402090039.
- --8403060536 Forwards summary of 840210 meeting w/Transametica Delaval, Inc Owners Group in Bethesda.MD re problems w/smergency diesel generators GARU80,R Licensing Branch 2. 84/02/27 O'REILLY.JP NRC No Detailed Affiliation Given 6pp 22708:006 24X Fichs 50-000.84/03/12.8402070037
- --8403060554 Transcript of 840210 meeting w/Transamerica Delaval. Inc Owner's Group in Bethesda, MD re problems w/emergency diesel generators * NRC - No Detailed Affiliation Given. 84/02/10 147pp 67201:008 24X Fichs 50~000.84/03/12.8402070039

- --8403070409 Summary of 840216 meeting w/Transamerica Delaval. Inc Cumers Group in Wading River, NY re program plan to establish reliability of diesel generators Agenda, meeting transcript & attendance list encl MILLER, MA Licensing Branch 4 84/02/27 Licensing Branch 4 8pp 22708 161 24X Fiche 50-000/84/03/12,8402090039
- --8403070423 Transcript of 840214 conference in Wading River.NY re Transamerica Delaval.Inc diesel generators Pp 1-82 * Commissioners 84/02/16 84pp 22708 169 24X Fiche 50-000,84/03/12.8402070039
- DOCKET 50-423 MILLSTONE NUCLEAR POWER STATION, UNIT 3
- A Application/construction stage documents & correspondence
- 8401120455 Notification of B40117-19 meetings w/util in Bethesda.
 MD to discuss applicant responses to Mcchanical Engineering
 Branch safety review Questions 210 B to 210 49
 DOOLITTLESE L Licensing Branch 1 84/01/05 YOUNOBLOOD, B J
 Licensing Branch 1 3pp 21804 104 24X Fiche 50-423.84/01/05.
 8401120455
- 8403070299 Forwards proprietary response to Question 492 4 re measurement of RC9 flow Response withheld (ref 10CFR2 790) COUNSIL.W 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W 0 Northeast Utilities 84/02/16 YOUNDBLOOD.B J Licensing Branch 1 2pp 22547 054 24X Fiche 50-423.84/02/16.8403070299
- --8403070302 Requests withholding proprietary info re response to Question 492 4 concerning RCE flow measurement uncertainty (ref 10CFR2 790)
 HIESEMANN.R A Westinghouse Electric Corp 83/08/18
 YUUNGBLOOD.B J Licensing Branch I 8pp 22547 036 24X
 Fithe 50-423.84/02/16.8403070279
- 8403020158 forwards requests for add1 info to complete evaluation of environ & safety portions of application for CL Response requested by 840315
 YOUNGBLOOD, B J Licensing Branch 1 84/02/17 COUNBIL, H O Northeast Nuclear Energy Co (subs of Northeast Utilities) 7pp 22471 142 24X Fiche 50-423,84/02/17,9403020158
- B403070304 Provides responses to three open items from NRC/BNL Yankee Atomic Electric Co & consultants Mark I containment program plant-unique analysis rept 840216 review meeting CELIA.N S Teledyne Engineering Services 84/02/28 SIEGEL.B NRC No Detailed Affiliation Given 4pp 22546 171 24X Fiche 50-000.84/02/28,8403070304
- 8403120320 Responds to 831228 ltr advising that rept, "Beismology & Geophysical Studies Miramichi Area.New Brunswick & Central NH." Vols I & II.no longer proprietary YOUNGBLOOD: B J Licensing Branch 1 84/03/01 CDUNSIL.W Q Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 22596 355 24X Fiche 50-423.84/03/01.8403120320
- B403200182 Forwards Topical Rept 7703 on missile barrier interaction W/o rept

 EMERSON,W F Stone & Webster Engineering Corp 84/03/06

 PDOLITTLE,E L Licensing Branch i 1p 22686 340 24X

 Fiche 30-423,84/03/06,8403200182.
- 8403280122 Summary of 840224 meeting w/Mestinghouse Gwners Group in Bethesda.MD re proposed Westinghouse steam generator tube rupture generic program Attendee list & agenda encl NERSEB.V Licensing Branch 3 84/03/07 Licensing Branch 3 35pp 22811 131 24X Fiche 50-000.84/03/07,8403280122
- 8403260299 Forwards request for add1 info to complete evaluation of safety portion of OL application resulting from 840105 meeting re util response to Question 230 & Response by 840515 requested YQUNOELOOD B J Licensing Branch 1 84/03/09 COUNCIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 5pp 22759 356 24X Fiche 50-423,84/03/09.8403260299
- B403260200 Comments on Issue 3 of NUREO-0885, "NRC Policy & Planning Guidance, 1984 " Seven themes identified represent important objectives for industry COUNSIL.W 6 Northeast Utilities 84/03/12 DIRCKS,W J Office of the Executive Director for Operations 4pp 22756 204 24X Fiche 50-000, 84/03/12, 8403260200.
- 8403200149 Forwards "Saismic Fragilities of Structures & Components at Milistone 3 Nuclear Power Station," per 840306 meeting commitment CDUNSIL.W 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W.G Northeast Utilities 84/03/13 YOUNGBLOOD.8 J Licensing Branch 1 1p 22689 320 24X Fiche 30-423.84/03/13.8403200149.

- --8403200152 "Beismic Fragilities of Structures & Components at Millstone 3 Nuclear Power Station " WESLEY,D A , CAMPBELL.R D , HASHIMOTO,P 8 Structural Mechanics Associates SMA 20601 01-R1-0 84/03/31 193pp 22689 321 24X Fichs 50-423,84/03/13,8403200149
- 8403260181 Forwards six marked-up oversized P&IDs showing RCB pressure isolation valves, in response to Mechanical Engineering Branch Guestion 210 42 Aperture cards are available in PDR COUNSIL.W G Northeast Nuclear Energy CO (subs of Northeast Utilities) COUNSIL.W G Northeast Utilities 84/03/13, YDUNBELOOD, B J Licensing Branch 1 2pp 22796, 048 24X Fiche 50-423, 84/03/13, 8403260181
- 8403270112 Forwards completed operating shift experience survey Survey reflects shift experience base at present & projected shift experience base at time of fuel load Shift advisors will not be used Proposal ancl COUNBIL, W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNBIL, W O Northeast Utilities 84/03/19 THOMPSON, H L Division of Human Factors Safety Bpp 22806 303 24X Fiche 50-423,84/03/19,8403270112
- 8403300187 Forwards proposed agenda for second corporate IE mgt meeting on 840403 to discuss const phase to preoperational & startup test phases & fire protection & security programs STAROSTECKI.R Division of Project & Resident Programs 84/03/27 COUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 3pp 22819 281 24X Fiche 50-423.84/03/27.8403300187
- C Utility Environmental Report (ER), amonds & correspondence
- 8403130360 Forwards "Effluent Toxicity Testing at Millstone Nuclear Power Station Using Sheepshead Minnow During 1981-82" & "Development of Long-Term Effluent Toxicity Testing Procedure ," in response to environ rept question COUNSIL, W g Northeast Utilities Service Co (subs of Northeast Utilities) COUNSIL, W g Northeast Utilities 84/02/03 YOUNDELOUD, B J Licensing Branch i 2pp 22617 023 24X Fiche 50-423,84/02/03,8403130360
- --8403130367 "Effluent Toxicity Testing at Millstone Nuclear Power Station Using Sheepshead Minnow (Cyprinodon Variegatus) During 1981-82 "

 Northeast Utilities 83/07/31 31pp 22617 025 24X fiche 50-423,84/02/03,8403130360
- --B403130376 "Development of Long-Term Effluent Toxicity Testing Procedure W/Bay Mysid (Mysidopsis bahia) & Preliminary Tasting Results at Millstone Nuclear Power Btation " * Northeast Utilities 83/07/31 24pp 22617 056 24X Fiche 50-423,84/02/03,8403130360
- 8403070273 Forwards Amend & to environ rept OL stage, revising seismit risk assessment curves Transmittal & receipt forms encl COUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W Q , BEARS.C F Northeast Utilities 84/03/01 YOUNGBLOOD.B J Licensing Branch I 4pp 22346 293 24X Fichs 50-423.84/03/01.8403070273
- ---B403070275 Amend & to anviron rept OL stage # Northeast Nuclear Energy Co (subs of Northeast Utilities) 84/03/31 5pp 22546 297 24X Fiche 50-423,84/03/01,8403070273
- D NRC Draft/Final Environmental Statements, supple & correspondence
- 8403080001 Discusses issuance of DES on 840417 Revised seismic fragilities data developed & effect on overall risk curves will be completed shortly Expresses concern that NRC unable to support issuance of DES on time COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W G Northeast Utilities 84/02/21 YOUNDBLOOD, B J Licensing Branch 1 2pp 22490 063 24X Fiche 50-423,84/02/21,8403030001
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- B403070130 Forwards sections of draft SER not transmitted in B31230 Itr Requests review of info & written response to open items prior to 840515 in order to accommodate schedule for issuance of final SER on 840716 YOUNOBLOOD, B J Licensing Branch 1 84/02/24 COUNBIL, W Q Northeast Nuclear Energy Co (subs of Northeast Utilities). 120pp. 22564-001 24X Fiche 50-423,84/02/24,8403070130
- B403160292 Forwards response to SER questions contained in NRC 831205 ltr & discussed at Mechanical Engineering Branch 840117-19 meetings COUNSIL.W G . SEARS, C F Northeast Nuclear Energy Co (subs. of Northeast Utilities) COUNSIL.W G Northeast Utilities. 84/03/01 YOUNGBLOOD, B J Licensing Branch 1 100pp 22661.119, 24X Fichs 50-423.84/03/01.8403160292

- 8403220148 Forwards status of draft SER open items re fire protection, per 840216 meeting w/Chemical Engineering Branch All ventilation sys penetrating fire barriers verified, per Branch Technical Position CMEB 9 5-1
 COUNSILW 0 , SEARS, CF Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSILW 0 Northeast Utilities 84/03/09 YOUNGBLOOD, B J Licensing Branch 1 23pp 22716 058 24X Fiche 50-423,84/03/09,8403220148
- 8403280286 Notification of Instrumentation & Contol Sys Branch (ICSB) 840313 meeting w/util in Bethesda, MD to discuss applicant responses to ICSB unresolved items re draft SER. Section 7 ROOLITILE, E. L. Licensing Branch 1 84/03/13 YOUNGBLOOD, B J Licensing Branch 1 3pp 22808 058 24X Fiche 50-423,84/03/13,
- 8403260149 Forwards response to Core Performance Branch draft SER Open Item 228 re rod bow analysis COUNSIL.W G. SEARS.C F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) COUNBIL.W G. Northeast Utilities 84/03/16 YOUNOBLOOD.B J. Licensing Branch 1 Spp. 22750.332 24X Fiche 50-423.84/03/16.8403260149
- F Security, medical, emergency & fire protection plans
- B403190243 Notification of 840418 workshop in King of Prussia, PA to discuss lessons learned from recent App R fire protection safe shutdown insp & topics described in IE Info Notice 84-09 Agenda for workshop encl MURLEY, T E Region 1, Office of Director 84/03/09 O'TOOLE, J D Consolidated Edison Co of New York, Inc 35pp 226/2 062 24X Fichs 50-000,84/03/09,8403190243
- 8403220148 Forwards status of draft SER open items re fire protection, per 840216 mesting w/Chemical Engineering Branch All ventilation sys penetrating fire barriers verified, per Branch Technical Postition CMEB 9 5-1 COUNBIL, H 0 , SEARS, C F Northeast Nuclear Energy Cn (subs of Northeast Utilities) COUNBIL, W 0 Northeast Utilities. 84/03/09 YOUNOBLOOD, D J Licensing Branch 1 23pp 22716 058 24X Ficher 50-423, 84/03/09, 8403220148
- B403270008 Informs that util will provide info re planned deviations from Suppl 1 to NUREO-0737 by 840501 Delay has no effect on schedules for implamentation of Suppl 1 to NUREO-0737 COUNSIL, H O Connecticut Vankes Atomic Power Co SEARS, C F Northeast Nuclear Energy Co, (subs of Northeast Utilities) COUNSIL, W O Northeast Utilities 84/03/16 EIBEN-HUT, D O Division of Licensing 2pp 22770 011 24X Fiche 50-000, 84/03/16, B403270008
- 8403300187 Forwards proposed agenda for second corporate 1E mgt meeting on 840403 to discuss const phase to preoperational & startup test phases & fire protection & security programs BTAROSTECKI.R Division of Project & Resident Programs B4/03/27 COUNBIL,N 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) 3pp, 22819 281 24X Fiche 50-423,84/03/27,8403300187
- % Utility Final Bafety Analysis Report (FBAR) & amends
- --8403140109 Amend 7 to FBAR

 * Northeast Nuclear Energy Co. (subs of Northeast Utilities)
 84/03/31 526pp 22622.009 24X Fiche 50-423,84/03/09,
 8403140101
- Q Inspection reports: IE Bulletins & correspondence
- 8403010427 Forwards IE Insp Rept 50-423/84-01 on 840116-20 No violations observed PARTLON,J G. Division of GA, Bafeguards & Inspection Programs (Post 830103) 84/02/02 COUNSIL-N.G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp. 22449 323 24X Fiche.50-423.84/02/02.8403010427
- --8403010430 IE Insp Rept 50-429/84-01 on 840116-20 No violations identified Major areas inspected implementation of GA program w/respect to Bahnson Co.implementation of GA program for sample of matl suppliers & HVAG equipment.

 MERSCHOFF,E W. NORMAN, D. Region 4. Diffice of Director BAKER, E. Director's Office of Fispection and Enforcement 84/01/31 8pp. 22449 325 24X Fiche 50-423,84/02/02,84/03/010427

- B401190072 IE Info Notice 84-13. "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/02/28 Consolidated Edison Co of New York, Inc 115pp 22909 239 24X Fiche 50~000.84/02/28, B401190072
- B403070333 Ack receipt of B40209 ltr informing NRC of steps taken to correct deviations noted in IE Insp Rept 50-423/83-i8 MARTIN, T Division of Engineering & Technical Programs 84/02/28 COUNSIL.W Q Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 22546 309 24% Fiche 50-423,84/02/28,8403070333
- --8403070336 Responds to NRC 840110 ltr re deviation noted in IE Insp Rept 50-423/83-18 Util will continue to allow use of table splices when justified by analysis Rev to FSAR will be submitted by 840515 to clarify position COUNSIL.W Q , SEARS.C F Northeast Nuclear Energy Co. (subs of Northeast Utilities) COUNSIL.W Q Northeast Utilities 84/02/09 MARTIN.T T Division of Engineering & Technical Programs 2pp 22546 311 24X Fishe 50-423.84/02/28.8403070333
- 8403210011 Requests extension until B40401 to respond to IE Bulletin B3-06, "Noncomforming Maths Supplied by Tube-Line Corp " Evaluation by S&M incomplete COUNSIL.W G. SEARG.C F. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) COUNSIL.W G. Northeast Utilities 84/02/27 MRRLEY.T E. Region 1, Office of Director. 3pp. 22706 341. 24% Fiche 50-423.84/02/29.8403210011
- 8402070007 IE Info Notice 84-i4. "Highlights of Recent Transport Regulatory Revs by DOT & NRC "Svc list enci GRACE. J N Division of GA. Bafeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22532 327 24X Fiche 50-000,84/03/02,8402070007
- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fichs 50-000.84/03/02.8402070008
- 8402090009 IG Info Notice 84-15, "Reporting of Radiological Releases" Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 119pp 22553 217 24X Fiche 50-000.84/03/02.8402090009
- B402070011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/05 Consolidated Edison Co. of New York, Inc. 117pp 22953 336 24X Fishe 30-000.84/03/05,8402090011
- 8402070024 IE Info Notice 84-07.Rev i. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (flost 8300103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 047 24X Fiche 50-000.84/03/07, 8402070024
- 8402090028 IE Info Notice 84-18, "Stress Corresion Cracking in PWR Bys " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103), B4/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24% Fiche 50-000.84/03/07,8402090028
- 8402070031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Bafety Sys " Svc list encl DEYOUNG.R C Director's Office. Dffice of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823-094 24X Fiche 50-000.84/03/12.8402070031.
- 8403220136 Provides results of reevaluation of performance assessment, per util 831219 ltr addressing topics discussed at 831129 SALP mgt meeting Category 1 rating will be assigned to refueling area for Millstone 2 Explains Category 2 ratings MURLEY.T E Region 1. Office of Director 84/03/16 COUNBIL.W 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) 4pp 22716:047 24X Fiche 50-000.84/03/16.8403220136
- 8403230033 Forwards revised Class 1 & Class 2 portions of Rev 2 to FSI 2,01. "Preservice Insp Manual" COUNSIL,W G . SEARB,C.F . Northeast Nuclear Energy Co (subs. of Northeast Utilities) COUNSIL,W G . Northeast Utilities 84/03/20 YOUNOBLOOD,B J Licensing Branch 1 2pp 22744 001 24X Fiche 50-423.84/03/20,8403230033
- --B403230037 Revised Class I & Class 2 portions of Rev 2 to PSI 2 01,
 "Preservice Insp Manual"

 * Northeast Nuclear Energy Co (subs of Northeast Utilities)
 B4/03/20 714pp 22744 003 24X Fiche 50-423,84/03/20,
 B403230033

- B402090043 IE Info Notice B4-19, "Two Events Involving Unauthorized Entries into PUR Reactor Cavities" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc. 123pp 22823 229 24X Fiche 50-000, 84/03/21, 8402090043
- 8402070044 IE Info Notice 84-20, "Svc Life of Relays in Bafety-Related Sys " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 135pp 22933.001 24X Fiche 50-000,84/03/21,8402070044
- B403300144 Responds to IE Bulletin B3-OB, "Electrical Circuit Breakers W/Undervoltage Trip Feature in Use in Safety-Related Applications Other Than Reactor Trip Bys " Haddam Nack facility uses 31 Westinghouse-type DB breakers COUNSIL.N G Northeast Nuclear Energy Co (subs of Northeast Utilities) B4/03/21. MURLEY, TE Region 1. Office of Director 4pp 22820 068 24% Fiche 50-000,84/03/21.8403300144
- R Periodic operating reports & related correspondence
- 8403020443 Forwards monthly status rept of offsite emergency preparedness for OL reviews for Jan 1984 Changes in FEMA finding dates not caused by delay due to offsite emergency planning issues
 DIRCKS, W J Office of the Executive Director for Operations
 84/02/21 PALLABING Commissioners 7pp 22492 083 24X
 Fiche 30-000,84/02/21,8403020443
- 8 Reportable occurrences. LERs & related correspondence
- 8403210095 Part 21 rept re nonconformance of metal hose assemblies for ABME. Bection III. Class 2 & 3 svc Status of nonconforming items shipped ancl All customers notified LALIKOS. J M Titeflex Corp B3/12/16 Director's Office. Office of Inspection and Enforcement 4pp 22704 324 24X Fiche: 50-000.83/12/16.8403210095
- B403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines, Oinpel NPS-4 T&T valve, to close Encl ltr dtd 840203 sent to listed utils GE notified of affected units in BHR plants
 THEROUX.R R Terry Corp 84/02/22 WODDRUFF, R W Director's Office, Office of Inspection and Enforcement 4pp 22706 327 24X Fiche 50-000, 84/02/22, 8403210032
- 8403070256 Followup Part 21 rept re defective mechanical snubber capatam springs supplied by Pacific Scientific Affected utils listed Purchasers have been notified & advised to work directly w/Pacific Scientific in disposition HDVI.L NPS Industries: Inc 84/02/24 DEYOUNO,R C Director's Office, Office of Inspection and Enforcement 2pp 22536 279 24 Fiche 50-000,84/02/24,8403070256.
- 8403260233 Forwards summary list of deficiencies identified per 100FR30 55(e).Part 21 & potential generic ltr repts for comments
 8TAROSTECKI.R Division of Project & Resident Programs 84/02/28 Region 1. Office of Director 7pp 22756 065 24X Fiche:50-000.84/02/28.4403260233
- 8403130213 Potential Significant Deficiency Rept 80-51 re design & const of NAMCO Model EA-180 limit switches provided as accessories on valves supplied by Pacific Valves Initially reported on 840131 Discussions w/vendor initiated COUNSIL, N 9, SEARS, C. F. Northeast Utilities 84/03/01 MURLEY, T E. Region 1, Office of Director 2pp 22617 320 24X Fiche 50-423, 84/03/01, 8408130213.
- 8403210161 Bignificant Deficiency Rept BD-48 re defective design & const of main control board lug wires supplied by Reliance Electric Co Initially reported on 831110 Insp & repair program initiated. Next rept by Nov 1984 COUNBIL.W 0. SEARS.C.F Northeast Utilities 84/03/01 MURLEY.T E. Region 1. Office of Director 2pp 22707.110 24X Fiche 50-423.84/03/01.8403210161.

V Operator Examinations

8403290112 Forwards completed operating shift experience survey Burvey reflects shift experience base at present & projected shift experience base at time of fuel load Shift advisors will not be used Proposal encl COUNBIL. W.O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNBIL. W.O Northeast Utilities 84/03/19 THOMPSON, H.L. Division of Human Factors Safety 8pp. 22806-303, 24% Fiche 50-423,84/03/19,8403290112

- DOCKET 50-424 VOOTLE ELECTRIC GENERATING PLANT
- A Application/construction stage documents & correspondence
- B403030311 Notification of B40306-07 meetings w/util in Waynesboro QA to facilitate NRC review through site visits
 MILLER, M A Licensing Branch 4 84/02/23 ADENSAM, E Q Licensing Branch 4 3pp 22501 272 24X Fichs 50-424, B4/02/23, B403050311.
- 8403010319 Amend 4 to application for OLs.consisting of Amend 4 to FBAR
 FOSTER, D D Georgia Power Co 84/02/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22433, 111 24X
 Fichs 50-424,84/02/24,8403010319
- C Utility Environmental Report (ER), amends & correspondence
- 8403090189 Comments on saviron rept OL stage, per Ofc of Environ Project Review Dec 1983 memo Two unresolved equatic issues should be addressed as special study conditions of OL MCBAV.L G Interior, Dept of, Fish & Wildlife Bervice 84/01/20 FARLEY, J G Southern Co. Services, Inc. 3pp 22573 304. 24X Fiche 50-242.84/01/20.8403090189.
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents. App B document entirely withheld (ref FOIA Exemption 5) Review of add1 documents subj to request continuing FELTON. J M Division of Rules and Records 84/02/13, ANDERSON. B I Garvey, Schubert, Adams & Barer. 7pp 22583:226. 24X Fiche 50-000,84/02/13,8403080179.
- --Bi03040052 Forwards short & long-term OL & CP review schedules, in response to B01216 meeting w/USOS List of OL plant reviews for which NRC tentatively plans to seek USOS assistance is provided.

 JACKSON, R E Geosciences Branch NRC-03-80-113 81/01/21 DEVINE, J F Interior, Dept. of, Geological Survey. 5pp. 22583 272 24X Fiche 50-000,84/02/13,8403080179
- Q Adjudicatory correspondence
- 8403020126 Response opposing applicant answer to petitions for leave to intervene & requests for hearing Request for hearings to be held in Atlanta, OA reiterated Certificate of Bvc encl. TEPER, D C Georgians Against Nuclear Energy 84/02/24 Atomic Bafety and Licensing Board Panel 4pp 22442:147, 24X Ficha 50-424,84/02/24,8403020126.
- 8403140114 Reiterates staff 840215 response to Campaign for Prosperous Ocorgia 840224 request that hearings be held in Atlanta, GA Site of hearings question does not need resolution at present BORDENICK, B M Hearing Branch 3. 84/02/29, MARQULIES, M B , LINENBERGER, O , PARIS, O H Atomic Sefety and Licensing Board Panel 2pp 22623 357 24% Fiche 50-424, 84/02/29, 8403140114.
- B403060090 Applicant response to Campaign for Prosperous Georgia (CPG) 840224 memorandum re location of hearing CPG has no reason for departing from NRC policy & ignores fact that project ofc moved from Atlanta to site W/Certificate of 8vc TROWRRIDGE.0.F. Georgia Power Co TROWRRIDGE.0.F. Shaw. Pittman. Potts & Trowbridge 84/03/01 8pp 22516:301 24X Fiche 50-424.84/03/01.8403060090
- 8403130457 Requests that hearings on DL application be held in State of GA to afford state officials & constituents opportunity to attend & monitor proceedings.

 LOVETY.B Georgia, State of 84/03/07 Office of the Secretary of the Commission ip 22613-348 24X Fichs: 50-424,84/03/07, 8403130457
- 8403130374 Memorandum & order scheduling 840530 special prehearing conference in Augusta. 6A to identify key issues to consider all intervention petitions & to establish schedule for further action MARQULIES: M B , LINENBERGER, Ø , PARIS, O H Atomic Safety and Licensing Board Panel 84/03/09. 10pp 22616*081. 24X Fichs. 50-424, 84/03/09, 8403130394
- B403230279 Requests that hearings be located in Waynesborg, QA. PARRISH, B O Waynesborg, QA. D8B 078 B4/03/19. Office of the Becretary of the Commission ip 22743.093 24X Fiche, 50-424, 84/03/19, 8403230279

H General correspondence

- 8403150023 Advises of change to correspondence distribution adding JE Joiner & RE Conway, deleting DE Dutton & changing addresses of DO Foster & RA Thomas FOBTER, D O Georgia Power Co 84/03/08 ADENBAM, E Q Licensing Branch 4 2pp 22441 280 24X Fiche 50-424,84/03/08.8403150023
 - 2pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- B403010319 Amend 4 to application for OLs.consisting of Amend 4 to FBAR
 FOBTER, D O Georgia Power Co 84/02/24 DENTON, H R Office of
 Nuclear Reactor Regulation. Director 2pp 22433 iii 24X
 Ficha 50-424.84/02/24.8403010319
- --8403010325 Amend 4 to FSAR # Oborgie Power Co 84/02/24 184pp 22433 113 Fichs 50-424,84/02/24,8403010319
- G Inspection reports, IE Bulletins & correspondence
- 8403080370 Appeals denial of FDIA request for draft IE Insp Repts 50-424/83-13 & 50-425/83-13 50-424/83-13 & 50-425/83-13
 DOMBY, A H Troutman, Sanders, Lockerman & Ashmore 83/11/14
 Defice of the Executive Director for Operations 2pp 22576
 24X Fiche 50-424,83/11/14,8403080370 22576 244
- 8403080372 Responds to appeal re denial of FOIA request for draft IE Insp Repts 50-424/83-13 & 50-425/83-13 Forwards documents FELTON, J M Division of Rules and Records 84/01/31 DOMBY, A H Troutman, Banders, Lockerman & Ashmore 1p 22576 246 24X Fiche 50-424,84/01/31,8403080372
- --8403080377 Forwards IE Insp Repts 50-424/83-13 & 50-425/83-13 on 830621-0720 & notice of violation LEWIS,R C Division of Project & Resident Programs B3/10/14 KELLEY,R J Georgia Power Co 2pp 22576 247 24X Fiche 50-424,84/01/31,8403080372
- --8403080381 Notice of violation from insp on 830621-0720 * Region 2, Office of Director 83/10/14 3pp 22576 249 24X Fiche 50-424,84/01/31,8403080372
- --8403080384 IE Insp Repts 50-424/B3-i3 & 50-425/B3-i3 on B30621-0720 Violations noted, failure to implement pipe support control documents & provide appropriate concrete expansion anchor & structural steel acceptance criteria BROWNLEF, V L., BANDERB, W F., JACKBON, L H. Region 2, Office of Director B3/10/11 34pp. 22574 252 24X Fiche 50-424, 84/01/31, B403080372
- 8403070018 Forwards IE Insp Repts 50-424/83-23 & 50-425/83-23 on B31111-840116 No violations or deviations noted. DANCE.H.C Division of Project & Resident Programs 84/02/10 KELLY.R.J Georgia Power Co. 2pp 22547.327, 24X Ficher 50-424, 84/02/10, 8403070018.
- --8403070024 IE Insp Repts 50-424/83-23 & 50-425/83-23 on 831111-840116
 No violations or deviations noted Major areas inspected
 installation of electrical cabinets-reactor vessel closure
 head cladding repair.weld matl control & rebar & forms
 BANDERS W F. Region 2, Office of Director PANGIERA: V Division
 of Project & Resident Programs 84/02/09 4pp 22547 328 24X
 Fiche. 50-424, 84/02/10, 8403070018
- 8403160207 Forwards IE Insp Repts 50-424/84-02 & 50-425/84-02 on 840130-0203 No violations or deviations identified DANCE: H C Division of Project & Resident Programs 84/02/23 KELLYR. J Georgia Power Co. 2pp 22655.221 24X Fiche: 50-424, 84/02/23, 8403160207.
- --8403160212 IE Insp Repts 50-424/84-02 & 50-425/84-02 on 840130-0203 No violations or deviations identified Major areas inspected electrical cable installation, cable termination, GA procedures, insulation resistance testing & training MERRIWEATHER, N. CONLON, T E Region 2. Office of Director 84/02/21. 8pp. 22655.223. 24X Fichs 50-424,84/02/23,8403160207
- B401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list ancl. JDRDAN,E.L Division of Emergancy Preparadness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc. 115pp 22707 237, 24X Ficher 50-000,84/02/28,8401170072

- 8402090007 IE Info Notice 84~14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE. J N Division of GA, Safeguards & Inspection Programs (Post B30103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50~000,84/03/02.8402090007
- 8402090008 IE Info Notice 84-16. "Fallure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008
- 8402070007 IE Info Notice 84-15, "Reporting of Radiological Releases"
- 8402090011 IE Info Notice 84-17. "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Evc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Conselidated Edison Co of New York, Inc. 117pp 22053 336 24X Fiche 50-000,84/03/05.8402090011
- B402070024 IE Info Notice B4-09.Rev 1, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN,E L. Division of Emergency Preparadness & Engineering Response (Post B30103) B4/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000.84/03/07, 8402090024
- 8402070028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Bys "Syc list and JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co 22584 186 24X Fiche 50-000,84/03/07,8402090028 118pp
- 8402090031 IE Builetin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000.84/03/12,8402090031
- 8403270037 Provides interim response to IE Bulletin 83-07, "Apparently Fraudulent Products Sold by Ray Miller, Inc " Matls supplied by primary suppliers listed Investigation of subtier suppliers in progress Final rept expected by 840624 FUSTER, D O Georgia Power Co 84/03/12 O'REILLY, J P Region 2, Office of Director 5pp 22806 232 24X Fiche 50-424,84/03/12,8409270037
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000,84/03/21,8402090047 123рр
- 8402090044 IE Info Notice 84-20, "Syc Life of Relays in Safety-Related Bys " Byc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co 135pp 22933 001 24% Fiche 50-000,84/03/21,8402090044
- S Reportable occurrences, LERs & related correspondence
- 8403010451 Informs Commission of problems w/emergency diesel generators mfg by Transamerica Delaval. Inc DIRCKS.W J. Office of the Executive Director for Operations BECY-83-034, 84/01/25 4pp 22438 347 24X Fiche 50-000. 24X Fiche 50-000, 84/01/25,
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines, Gimpal NPB-4 T&T valve, to close Encl ltr dtd 840203 sent to listed utils GE notified of affected units in BHR plants plants
 THEROUX,R R Terry Corp 84/02/22 WOODRUFF,R W Director's
 Office, Office of Inspection and Enforcement App 22704 327 24X
 Fiche, 50-000, 84/02/22, 8403210032
- 8403010354 Interim deficiency rept re broken capstan spring tangs on Pacific-Scientific shock arrestors Initially reported on 840126. Metallurgical analysis indicates cracking due to stress induced by spring forming Next rept by 840518 FOSTER.D O Georgia Power Co 84/02/23 D'REILLY, J P Region 2. Office of Director 2pp 22433 003 24X Fiche 50-424.84/02/23, 8403010354 Region 2,

- 8403090097 Final deficiency rept re Pullman Const Industries undersized shop filet welds on corner details of stiffener angles for HVAC ducts Condition not reportable per IOCFR50 55(e) or IOCFR21 FOSTER.D O Georgia Power Co 84/02/24 O'REILLY, J.P. Region 2. Office of Director 1p 22576 004 24X Fiche 50-424,84/02/24. 8403090097
- 8403010207 Forwards 'Investigation of Types AF & AE Piston Skirts." per Transamerica Delaval. Inc Ouners Group program commitments Rept evaluates cracks in AF piston skirts in Shoreham & Grand Gulf Nuclear Power Stations MUSELER.W J TDI (Transamerica Delaval, Inc.) Dumers Group 84/02/27 DENTON.H R Office of Nuclear Reactor Regulation, Director 3pp 22434 090 24X Fiche 50-000.84/02/27,8403010207
- B40301021B Forwards task descriptions for 16 known problems re Transamerica Delaval.Inc emergency diesel generators MUSELER.W J TDI (Transamerica Delaval. Inc.) Duners Group 84/02/28 DENTON.H R Office of Nuclear Reactor Regulation, Director 42pp 22435 177 24X Fiche 50-000,84/02/28,8403010218
- 8403260233 Forwards summary list of deficiencies identified per 10CFR50 55(e), Part 21 & potential generic ltr repts for comments
- Comments
 STAROSTECKI.R Division of Project & Resident Programs 84/02/28
 Region i. Office of Director 7pp 22756 065 24x
 Fiche 50-000.84/02/28.8403260233
- B403120146 Interim deficiency rept re HVAC duct support weld defects found during reinsp program Initially reported on 840131 AddI investigation underway Interim rept will be submitted by 840910 FOSTER. D O Georgia Power Co 84/03/02 O'REILLY, J P Region 2. Office of Director 2pp 22585 252 24X Fiche 50-424,84/03/02.
- 840314004B Forwards "Grand Gulf Component Tracking Sys," "Shoreham Component Tracking Sys" & "Transamerica Delawal, Inc Diesel Generators Guners Group Program Plan." to resolve concerns w/emergency diesel generators MUSELER, H J Long Island Lighting Co 84/03/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22626 062 24X Fiche 50-000, 84/03/02, 8403140048
- --8403140095 "Transamerica Delaval. Inc Diesel Generators Dwners Group Program Plan "
 * TDI (Transamerica Delaval. Inc.) Owners Group 84/03/02 26ipp 22628 223 24X Fiche 50-000.84/03/02.8403140048
- 8403150043 Interim deficiency rept re cracks in containment penetration welds initially reported on 840209 All welds repaired per ASHE Code-Section III. Subsection NC FOSTER. D O Georgia Power Co 84/03/07 O'REILLY, J P Region 2, Office of Director 4pp 22641 010 24x Fiche 50-424,84/03/07, 8403150043
- 8403150069 Final deficiency rept re unverified computer code in design of main feedwater pipe supports Review & evaluation complete Event not reportable per 10CFR50 55(e) & Part 21 Unverified valve computer subroutine replaced by Bechtel FOSTER.D O Georgia Power Co 84/03/07 O'REILLY.J P Region 2, Office of Director ip 22643 182 24X Fichs 50-424,84/03/07, 8403150069
- 8403190105 Deficiency rept re Pullman Power Products febrication shop spool piece welds Initially reported on 831021 Spools containing reported defects reworked or repaired & presently in acceptable condition FOSTER.D D Georgia Power Co 84/03/09 O'REILLY, J P Region 2, Office of Director 7pp 22669 312 24X Fiche 50-424.84/03/09, 8403190105
- 8402090039 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delawal. Inc (TDI) Dwners Group Distribution list encl EISENHUT.D © Division of Licensing 84/03/12 PALLADINO Commissioners 5pp 22708 001 24X Fiche 50-000.84/03/12.
- --8403060336 Forwards summary of 840210 meeting w/Transamerica Delaval, Inc Owners Group in Bethesda. MD re problems w/emergency diesel generators GRUSD.R Licensing Branch 2 84/02/27 D'REILLY, J P NRC No Detailed Affiliation Given 6pp 22708 006 24X Fiche 50-000, 84/03/12, 8402090039
- --8403060534 Transcript of 840210 meeting w/Transamerica Delaval, Inc Owners Group in Bethesda, HD re problems w/emergency diesel generators = NRC - No Detailed Affiliation Given 84/02/10 147pp 67201 008 24X Fiche 50-000.84/03/12.8402090039

- --8403070409 Summary of 840216 meeting w/Transamerica Delaval, Inc Owners Group in Wading River, NY re-program plan to establish reliability of diesel generators Agenda, meeting transcript & attendance list encl
 MTLLER, M A Licensing Branch 4 84/02/27 Licensing Branch 4 8pp 22708 161 24X Fiche 50-000,84/03/12,8402070037
- --8403070423 Transcript of 840216 conference in Wading River,NY re Transametica Delaval, Inc dissel generators Pp 1-82, * Commissioners 84/02/16 84pp 22708 169 24X Ficha 50-000,84/03/12,8402090039
- 8403140050 Forwards "Design Review of Connecting Rod Baaring Shalls for Transamerica Delaval Enterprise Engines" for Shoreham & Grand Gulf diesel generators MUSELER, W.J. Long Island Lighting Co. 84/03/12 DENTON, H.R. Office of Nuclear Reactor Regulation: Director 2pp 22632 074 24X Fiche 50-000,84/03/12,8403140050
- 8403150133 Forwards "Transamerica Delaval, Inc Diesel Generator Rocker Arm Capscrew Stress Analysis Rept " Capscrew design adequate for applicable engines & svc conditions MUSELER, W J TDI (Transamerica Delaval, Inc.) Owners Group. 84/03/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22637,270 24X Fiche 50-000, 84/03/13, 8403150133
- 8403200222 Responds to 840214 Requests for Info 1 & 2 re R-4 series engines List indicating engine number, model & svc number, customer name & address, rating, date shipped & date started encl
 MATHEWS, C S Transamerica Delaval, Inc. 84/03/16. EIBENHUT, D Q Division of Licensing 20pp 22691 179, 24x Fiche 50-000,84/03/16,8403200222
- 8403270219 Part 21 rept re broken contact carrier in control device of 7 5 kV-15 JV.300-750 MVA:5 kV 350-3,000 & all HAV circuit breakers Initially reported on 830223. Addenda to installation & maint procedures sent to affected units DUVALL, D D Brown Boveri Corp (subs q 0 Brown Boveri & Co., Ltd.). 84/03/17 Record Services Branch (Document Control Desk). 5pp 22772 114 24X Fiche: 50-000,84/03/19,8403270219.
- B403270132 Forwards "Emergency Diesel Generator Air Start Valve Capscrew Dimension & Stress Analysis," prepared by B&W for Transamerica Delaval, Inc (TDI) Diesel Generator Owners Group MUSELER, W J TDI (Transamerica Delaval, Inc) Owners Group B4/03/23 DENTON, HR Office of Nuclear Reactor Regulation, Director 2pp 22774, 001 24X Fiche, 50-000, 84/03/23, 8403270132,
- 8403270134 Requests meeting on 840418 to discuss short-term & long-term corrective actions & investigations re Transamerica Delaval diesel generators List of suggested meeting topics and MCOAUGHY, J P TDI (Transamerica Delaval, Inc.) Owners Group, 84/03/23 DENTON.H R Defice of Nuclear Reactor Regulation, Director 4pp 22769 133 24X Fiche 50-000,84/03/23,8403270134
- T Hearing transcripts on non-antitrust matters
- 8402070037 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delawal, Inc (TDI) Owners Group Distribution list encl EIBENHUT, D.G. Division of Licensing 84/03/12 FALLADINO Commissioners 5pp 22708 001 24X Fichs. 50-000, 84/03/12, 8402070037
- --8403060536 Forwards summary of 840210 meeting w/Transamerica Delaval, Inc Owners Group in Bethesda, MD re problems w/emergency diesal generators
 CARUSO, R Licensing Branch 2 84/02/27 O'REILLY, J P. NRC No Detailed Affiliation Given 6pp 22708 006. 24X
 Fiche 50-000, 84/03/12, 8402090039
- --8403060534 Transcript of 840210 meeting w/Transamerica Delaval, Inc Guners Group in Bethesda, MD re problems w/emergency diesel generators * NRC - No Detailed Affiliation Given, 84/02/10, 147pp, 67201 008 24X Fiche, 50-000, 84/03/12, 8402090039
- --8403070409 Summary of 840216 meeting w/Transamerica Delayal, Inc Owners Group in Wading River.NY re program plan to establish reliability of diesel generators Agenda, meeting transcript & attendance list ancl MILLER.M A Licensing Branch 4 84/02/27 Licensing Branch 4 8pp 22708 161 24X Fiche: 50-000,84/03/12,8402090039
- --8403070423 Transcript of 840216 conference in Wading River, NY re Transamerica Delaval, Inc diesel generators, Pp 1-82 * Commissioners 84/02/16 84pp 22708 169, 24X Fiche: 50-000, 84/03/12, 8402090039

V Operator Examinations

840315003B Forwards operating shift experience tables for shift supervisors, senior reactor operators, reactor operator & shift technical advisor Licensed classroom training & exam conducted FOBYER. D O Georgia Power Co 84/03/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 14pp 22643 068 24X Fiche 50-424, 84/03/09, 8403150038

DOCKET 50-425 VOOTLE ELECTRIC GENERATING PLANT

A Application/construction stage documents & correspondence

B403050311 Notification of B40306-09 meetings w/util in Waynesbord, GA to facilitate NRC review through site visits
MILLER, M A Licensing Branch 4 B4/02/23 ADENBAH, E 0 Licensing Branch 4 3pp 22501 272 24X Fiche 50-424, B4/02/23, B403050311

8403010319 Amend 4 to application for OLs, consisting of Amend 4 to FSAR
FOSTER, D O Georgia Power Co 84/02/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22433 111 24X
Fiche, 50-424, 84/02/24, 8403010319

C Utility Environmental Report (ER), amends & correspondence

B403090189 Comments on environ rept — DL stage per Ofc of Environ Project Review Dec 1983 memo. Two unresolved equatic issues should be addressed as special study conditions of DL MCBAY.L 0 Interior, Dept of, Fish & Wildlife Service B4/01/20 FARLEY.J 0. Bouthern Co Services, Inc 3pp 22573, 304, 24X Fiche. 50-424, 84/01/20, 8403090189

Q Adjudicatory correspondence

8403020126 Response opposing applicant answer to patitions for leave to intervene & requests for hearing Request for hearings to be held in Atlanta, GA resterated Certificate of Svc encl
TEPER, D. C Georgians Against Nuclear Energy 84/02/24 Atomic Bafety and Licensing Board Panel 4pp 82442 147 24X Fiche. 50-424, 84/02/24, 8403020126

8403140114 Reiterates staff 840215 response to Campaign for Prosperous Georgia 840224 request that hearings be held in Atlanta, 0A Bite of hearings question does not need resolution at present BORDENICK, B M Hearing Branch 3 84/02/29 MARQULIES, M B . LINENSERGER, G , PARIB, O H Atomic Safety and Licensing Board Panel 2pp 22623 357. 24X Fiche 50-424, 84/02/29, 8403140114

8403060090 Applicant response to Campaign for Prosperous Georgia (CPG) 840224 memorandum re location of hearing CPG has no reason for departing from NRC policy & ignores fact that project off moved from Atlanta to site W/Centificate of Svc TRGWBRIDGE, G. F. Georgia Power Co. TRGWBRIDGE, G. F. Shaw, Pittman, Potts & Troubridge 84/03/01 8pp 22516.301 24X Fiche: 50-424,84/03/01,8403060090

B403130457 Requests that hearings on OL application be held in State of QA to afford state officials & constituents opportunity to attend & monitor proceedings LOVETT, B. Georgia, State of B4/03/07 Office of the Secretary of the Commission 1p. 22613 348 24X Fiche 50-424, 84/03/07, 8403130457

B403130394 Memorandum & order scheduling 840530 special prehearing conference in Augusta, GA to identify key issues to consider all intervention petitions & to establish schedule for further action MARQULIES M B, LINENBERGER, Q, PARIS, O H Atomic Bafety and Licensing Board Panel 84/03/09 10pp 22616:081 24X Fiche 50-424,84/03/09,8403130394.

8403230279 Requests that hearings be located in Waynesboro. QA. PARTIEN. 8 9. Waynesboro. QA DSB 078 84/03/19 Office of the Secretary of the Commission 1p. 22743 093 24X Fiche. 50-424, 84/03/19, 8403230279.

H. General correspondence

B403150023 Advises of change to correspondence distribution, adding JE Joiner & RE Comway deleting DE Dutton & changing addresses of DO Foster & RA Thomas. FOSTER, D. C. georgia Power Co 84/03/08 ADENSAM. E. G. Licensing Branch 4 2pp. 22641 280 24X Fiche. 50-424, 84/03/08, 8403150023

K Utility Final Safety Analysis Report (FSAR) & amends

8403010319 Amend 4 to application for DLs, consisting of Amend 4 to FBAR
FOSTER, D O Georgia Power Co 84/02/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22433 111 24X
Fichs 50-424,84/02/24,8403010319

--8403010325 Amend 4 to FSAR * Georgia Power Co 84/02/24 184pp 22433 113 24X Fiche 50-424,84/02/24,8403010319

G Inspection reports, IE Bulletins & correspondence

8403080370 Appeals denial of FOIA request for draft IE Insp Repts 50-424/83-13 & 50-425/83-13 IDMBY.A H Troutman. Sanders, Lockerman & Ashmore 83/11/14 Office of the Carcutive Director for Operations 2pp 22576 244 24X Fiche 50-425,83/11/14,8403080370

8403080372 Responds to appeal re denial of FOIA request for draft IE Insp Repts 50-424/83-13 & 50-425/83-13 Forwards documents FELYON, J M Division of Rules and Records 84/01/31 DOMBY, A H Troutman, Sanders, Lockerman & Ashmore 1p 22576 246 24X Fiche 50-424.84/01/31.8403080372

--8403080377 Forwards IE Insp Repts 30-424/83-13 & 50-425/83-13 on 830621-0720 & notice of violation LEMIS.R C Division of Project & Resident Programs 83/10/14 KELLEY.R J Georgia Power Co 2pp 22576 247 24X Fiche 30-424,84/01/31,8403080372

--8403080381 Notice of violation from this on 830621-0720 * Region 2. Office of Director 89/10/14 3pp 22576 249 24x Fiche 50-424, 84/01/31, 8403080372

--8403080384 IE Insp Repts 50-424/83-13 & 50-425/83-13 on 830621-0720 Violations noted failure to implement pipe support control documents & provide appropriate concrete expansion anchor & structural steel acceptance criteria BROWNLEE, V L , LIU, W , RUFF, A D Region 2, Office of Director 83/10/11 36pp 22576 252 24X Fiche 50-424,84/01/31,8403080372

8403070018 Forwards IE Insp Repts 50-424/83-23 & 50-425/83-23 on B31111-840116 No violations or deviations noted DANCE.H C Division of Project & Resident Programs 84/02/10 KELLY.R J Georgia Power Co 2pp 22547 327 24X Fiche 30-424.84/02/10.8403070018

--8403070024 IE Insp Repts 50-424/83-23 & 50-425/83-23 on 831111-840116 No violations or deviations noted Major areas inspected installation of electrical cabinets.reactor vessel closure head cladding repair.weld matl control & rebar & forms SANDERS.W F Region 2, Office of Director PANCIERA,V Division of Project & Resident Programs 84/02/09 App 22547 328 24X Fiche 50-424,84/02/10,8403070018

8403160207 Forwards IE Insp Repts 50-424/84-02 & 50-425/84-02 on B40130-0203 No violations or deviations identified DANCE.H C Division of Project & Resident Programs 84/02/23 KELLY,R J Georgia Power Co 2pp 22655 221 24X Fiche 50-424.84/02/23.8403160207

--8403160212 IE Insp Repts 50-424/84-02 & 50-425/84-02 on 840130-0203 No violations or deviations identified Major areas inspected electrical cable installation, cable termination. GA procedures, insulation resistance testing & training MERRIWEATHER, N. CONLON, T E Region 2. Office of Director 84/02/21 Bpp 22655 223 24X Fiche 50-424,84/02/23,8403160207

8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22909 239 24X Fiche 50-000,84/02/28,8401190072

8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list enc! GRACE, J N Division of QA, Safeguards & Inspection Programs (Post B30103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000,84/03/02,8402090007

8402090008 IE Info Notice 84-14, "Failure of Automatic Sprinkler Sys Valves to Operate " Syc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008

- 8402070007 IE Info Natice 84-15, "Reporting of Radiological Releases" Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 119pp 22553 217 24X Fiche 50-000.84/03/02.8402070009
- 8402070011 IE Info Notice B4-17. "Problems H/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 810103) B4/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000.84/03/05.8402070011
- 8402070024 IE Info Notice 84-07, Rev 1, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 047 24X Fichw 50-000 84/03/07, 8402070024
- B40209002B IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Sys " Syc list encl JORDANNEL Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- B402070031 IE Bulietin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys" Syc list encl
 DEYGUNG, RC Director's Office, Office of Inspection and
 Enforcement B4/03/12 Consolidated Edison Co of New York, Inc
 134pp 22823 094 24X Fiche 50-000,84/03/12,8402090031
- 8403270037 Provides interim response to IE Builetin 83-07, "Apparently Fraudulent Products Sold by Ray Miller. Inc." Matle supplied by primary suppliers listed Investigation of subtler suppliers in progress Final rept expected by 840624 FOSTER. D. O. Georgia Power Co. 84/03/12 D'REILLY, J.P. Region 2. Office of Director 5pp 22806 232 24X Fiche 50-424.84/03/12, 8403290037
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Into Notice 84-20, "Svc Life of Relays in Safety-Related Bys " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 GO1 24X Fiche 50-000.84/03/21,8402090044
- S Reportable occurrences, LERs & related correspondence
- 8403010451 Informs Commission of problems w/emergency diesel generators mfg by Transamerica Delaval. Inc DIRCKS.W J Office of the Executive Director for Operations SECY-83-034 84/01/25 4pp 22438 347 24X Fiche 50-000.84/01/25, 8403010451
- 8403210032 Part Qi rept re failure of auxiliary feedwater pump drive turbines. Gimpel NP8-4 T&T valve to close Enci itr did 840203 sent to listed utils OE notified of affected units in BMR plants
 THEROUX, R R Terry Corp 84/02/22 WOODRUFF, R W Director's Office, Office of Inspection and Enforcement 6pp 22706 327 24X Fiche 50-000,84/02/22.8403210032
- 8403010354 Interim deficiency rept re broken capstan spring tangs on Pacific-Scientific shock arrestors Initially reported on 840126 Metallurgical analysis indicates cracking due to stress induced by spring forming Next rept by 840518 FOSTER. D O Georgia Power Co 84/02/23, D'REILLY, J P Region 2. Office of Director 2pp 22433 003 24X Fiche 50-424,84/02/23,8403010354
- 8403090097 Final deficiency rept re Pullman Const Industries undersized shop filet welds on corner details of stiffener angles for HVAC ducts Condition not reportable per 10CFR30 53(e) or 10CFR21 FGSTER.D D Georgia Power Co 84/02/24 D'REILLY, J P Region 2. Office of Director ip 22576 004 24x Fiche 50-424, 84/02/24,
- B403010207 Forwards "Investigation of Types AF & AE Piston Skirts," per Transamerica Delaval. Inc Guners Group program commitments Rept evaluates cracks in AF piston skirts in Shoreham & Grand Gulf Nuclear Power Stations.

 MUSELER.W J TOI (Transamerica Delaval. Inc.) Guners Group B4/02/27 DENTON.M R Office of Nuclear Reactor Regulation, Director 3pp 22434 090 24% Fiche 50-000, 84/02/27, 8403010207

- 8403010218 Forwards task descriptions for 16 known problems re Transamerica Delaval. Inc emergency diesel generators MUSELER. W. J. TDI (Transamerica Delaval, Inc.) Owners Group 84/02/28 DENTION, H. R. Diffice of Nuclear Reactor Regulation, Director 42pp 22435 177 24X Ficha 50-000.84/02/28,8403010218
- 8403260233 Forwards summary list of deficiencies identified per 100FR50 55(e), Part 21 & potential generic ltr repts for comments
 8TAROSTECKI.R Division of Project & Resident Programs 84/02/28
 Region 1. Office of Director 7pp 22756 065 24X
 Fiche 50-000,84/02/28,8403260233
- 8403120146 Interim deficiency rept re HVAC duct support weld defects found during reinsp program Initially reported on 840131 Add1 investigation underway Interim rept will be submitted by 840910 FOSTER, D.O. Georgia Power Co. 84/03/02 O'REILLY, J.P. Region 2, Office of Director 2pp. 22585 252 24x Fiche 50-424, 84/03/02, 8403120146
- 840314004B Forwards "Grand Gulf Component Tracking Sys," "Shoreham Component Tracking Sys" & "Transamerica Delaval, Inc Diesel Generators Duners Group Program Flan: "to resolve concerns w/emergency diesel generators MUSELER, W.J. Long Island Lighting Co. 84/03/02. DENTON, H.R. Office of Nuclear Reactor Regulation. Director 2pp 22626 062 24X Fiche 50-000, 84/03/02, 840314004B
- --8403140095 "Transamerica Delaval, Inc Diesel Generators Clumers Group Program Plan "
 * TDI (Transamerica Delaval, Inc) Clumers Group 84/03/02 26ipp 22628 223 24X Fiche 50-000, 84/03/02, 8403140048
- 8403130043 Interim deficiency rept re cracks in containment penetration welds Initially reported on 840209 All welds repaired per ABME Code-Section III, Subsection NC FOSTER, D. D. Ceorgia Power Co. 84/03/07 O'REILLY, J. P. Region 2, Office of Director App. 22641 010 24X Fichs 50-424, 84/03/07, 8403130043
- 8403130069 Final deficiency rept re unverified computer code in design of main feedwater pipe supports Review & evaluation complete Event not reportable per 100FR30, 55(e) & Part 21 Unverified valve computer subroutine replaced by Bechtel FOSTER, D.D. Georgia Power Co. 84/03/07 D'REILLY, J.P. Region 2, Defice of Director ip 22643 182 24x Fiche 50-424, 84/03/07, 8403130069
- 8403190105 Deficiency rept re Pullman Power Products fabrication shop spool piece welds Initially reported on 831021 Spools containing reported defects reworked or repaired & presently in acceptable condition FOSTER.D O Georgia Power Co 84/03/09 O'REILLY, J.P. Region 2, Office of Director 7pp 22669 312 24X Fiche 30-424,84/03/09,8400190105
- B402070039 Board Notification B4-052 forwards meating summaries containing transcripts of B40210 & 16 meetings between NRC & Transamerica Delaval, Inc (TDI) Owners Group, Distribution list ancl EIBENHUT, D 0 Division of Licensing 84/03/12 PALLADING Commissioners 5pp 22708.001 24X Fichs 50-000, B4/03/12, 8402070039
- --8403060536 Forwards summary of 840210 meeting w/Transamerica Delaval, Inc Guners Group in Bethesda.MD re problems w/emergency diesel generators CARUSO.R Licensing Branch 2 84/02/27 0'REILLY.J P NRC No Detailed Affiliation Given 6pp 22708.006 24X Fiche 50-000,84/03/12,8402090039
- ---8403060554 Transcript of 840210 meeting w/Transamerica Delaval, Inc Owners Group in Rethesda, MD re problems w/emergency diesel generators * NRC - No Detailed Affiliation Given 84/02/10 147pp 67201 008 24X Fiche 50-000,84/03/12,8402070039
- --8403070409 Summary of 840216 meeting w/Transamerica Delayal, Inc Owners Group in Mading River.NY re program plan to establish reliability of diesel generators Agenda, meeting transcript & attendance list encl
 MILLER.M A Licensing Branch 4 84/02/27 Licensing Branch 4 8pp 22708.161 24% Fiche.50-000.84/03/12,8402090039.
- --8403070423 Transcript of 840216 conference in Wading River, NY re Transamerica Delaval. Inc diesel generators Pp 1-82 * Commissioners 84/02/16 84pp 22708:169 24X Fiche 50-000,84/03/12,8402070039

- 8403140050 Forwards "Design Review of Connecting Rod Bearing Shells for Transamerica Delaval Enterprise Engines" for Shoreham & Grand Gulf diesel generators
 MUSELER, W. J. Long Island Lighting Co. 94/03/12 DENTON, H.R.
 Office of Nuclear Reactor Regulation, Director 2pp 22632 074
 L'Y Fiche 50-000,84/03/12,8403140050
- 8403150133 Forwards "Transamerica Delaval.Inc Diesel Generator Rocker Arm Capacrew Btress Analysis Rept " Capacrew design adequate for applicable engines & svc conditions MUSELER,W J TDI (Transamerica Delaval, Inc.) Owners Group 84/03/13 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 22639 270 24X Fiche 50-000,84/03/13,8403150133
- 8403200222 Responds to 840214 Requests for Info 1 & 2 re R-4 series angines List indicating engine number, model & svc number, customar name & address, rating, date shipped & date started encl.

 MATHEMS,C B Transamerica Delaval: Inc 84/03/16 EISENHUT.D 0

 Division of Licensing 20pp 22691 179 24X Fiche 50-000,84/03/16,8403200222
- 8403270219 Part 21 rept re broken contact carrier in control device of 7.5 kV-15 kV.500-750 MVA, 5 kV 350-3,000 & all HKV circuit breakers initially reported on 830223 Addenda to installation & maint procedures sent to affected units DUVALL,D.D. Brown Boveri Corp (subs of Brown Boveri & Co., Ltd.) 84/03/19 Record Services Branch (Document Control Desk) 5pp 22772:114 24X Fiche 50-000.84/03/19,8403270219
- 8403270132 Forwards "Emergency Diesel Generator Air Start Valva Capscrew Dimension & Stress Analysis," prepared by B&W for Transamerica Delaval, Inc (TDI) Diesel Generator Owners Group.

 MUSELER, W J TDI (Transamerica Delaval, Inc.) Dwners Group

 84/03/23 DENTON, H R Office of Nuclear Reactor Regulation,

 Director 2pp 22774 001. 24X Fiche 50-000,84/03/23,8403270132
- 8403270134 Requests meeting on 840418 to discuss short-term & long-term corrective actions & investigations re Transamerica Delaval dissel generators List of suggested meeting topics
- encl MCGAUGHY, J P enci MCOAUCHY, J P TDI (Transamerica Delaval, Inc.) Cumers Group 84/03/23 DENTON, H R Office of Nuclear Reactor Regulation, Director App 22769 133 24X Fiche 50-000,84/03/23,8403270134
- T. Hearing transcripts on non-antitrust matters
- 8402070039 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delayal.Inc (TDI) Owners Group Distribution EISENHUT,D Q Division of Licensing 84/03/12 PALLADING Commissioners 5pp 22708 001 24% Fiche 50-000,84/03/12.
- ---B403060536 Forwards summary of B40210 meeting w/Transamerica Delaval, Inc Owners Group in Bethesda, MD re problems w/emergency diesel generators
 CARUSO,R Licensing Branch 2 84/02/27 O'REILLY, J P NRC No Detailed Affiliation Given 6pp 22708 006 24X
 Fiche 50-000, 84/03/12, 8402070037
- ---84030A0554 Transcript of 840210 meeting w/Transamerica Delayal, Inc. Owners Group in Bathesda, MD re problems w/emergency diesel generators **NRC - No Detailed Affiliation Given 84/02/10 147pp. 67201.008 24X Fiche 50-000,84/03/12,8402090039
- --B403070409 Summary of 840216 meeting w/Transamerica Delaval, Inc Owners Group in Wading River, NY re program plan to establish reliability of diesel generators Agenda, meeting transcript & attendance list encl.
 MILLER.M A Licensing Branch 4 84/02/27. Licensing Branch 4 8pp. 22708:161 24X Fiche 50-000.84/03/12,8402090039
- --8403070423 Transcript of 840216 conference in Wading River, NY re Transamerica Delayal. Inc diesel generators Pp 1-82 * Commissioners 84/02/16 B4pp 22708·169. 24X Fiche. 50-000. 84/03/12, 8402070039.
- V. Operator Examinations
- 8403150038 Forwards operating shift experience tables for shift supervisors senior reactor operators reactor operator & shift technical advisor Licensed classroom training & sxam FOSTER, D. O Georgia Power Co 84/03/09 DENTON, H R Nuclear Reactor Regulation, Director 14pp Fiche: 50-424, 84/03/09, 8403150038 22443 DAR. 24Y

- DOCKET STN-50-437 FLOATING NUCLEAR PLANT
- O Inspection reports: IE Bulletins & correspondence
- 840i190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Syc list JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22707 237 24X Fiche 50~000.84/02/28,8401170072
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl ORACE.J N Division of QA. Safeguards & Inspection Programs (Post B30103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 327 24X Fichs 50-000.84/03/02.8402090007
- 8402090008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDÁN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases"

 Byc list entl
 JCRDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc 119pp 22553 217 24X Fiche 50-000.84/03/02, 8402070009
- B402090011 IE Info Notice B4-17. "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN:E L. Division of Emergency Preparedness & Engineering Response (Post B30103) B4/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000.84/03/05,8402090011
- 8402090024 IE Info Notice 84-09.Rev i, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22605 049 24X Fiche 50-000,84/03/07,8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Bvc list encl JORDAN, E. L. Division of Emergancy Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22584 186 24X Fiche 50-000.84/03/07.840299028
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Bafety Bys " Svc list encl DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp. 22823 094 24X Fiche 50-000.84/03/12,8402090031
- 8402090043 IE Info Notice 84-19. "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 123pp 22823 229 24X Fichs 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84-20: "Syr Life of Relays in Safety-Related Bys " Byc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21, Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044
- DOCKET 50-43B BELLEFONTE NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8403160247 Informs of 840327 meeting to discuss proposed responses to NRC questions on Rev 7 to topical GA program.per 840302 telcon
 LEWIS.R C Region 2. Office of Director 84/03/08 PARRIS.H Q Tennessee Valley Authority 1p 22660 361 24X
 Fiche 50-000.84/03/08.8403160247
- 8403140373 Notifies of use of ABME Nuclear Components Code Case N32-4 403160373 Notifies of use of ABML Nuclear Components Code Case N32-4 for hydrostatic testing of Class 3 embedded piping NRC position re use of Code Case N32-4 requested.

 MILLB.L.M Tennesses Valley Authority 84/03/12 DENTON.H R Office of Nuclear Reactor Regulation. Director 1p 22660 014 24X Fiche.50-000:84/03/12,8403160373

- F Security, medical, emergency & fire protection plans
- 8403160345 Extends invitation to attend region 840316 workship at regional ofc to discuss 10CFR50. App R requirements & recent results of insp to help resolve misunderstandings associated w/requirements LEWIS: R C Division of Project & Resident Programs 84/03/02
- wrequirements
 LEMIS.R C Division of Project & Resident Programs 84/03/02
 PARRIB.H G Tennessee Valley Authority 2pp 22660 003 24%
 Fiche 50-000.84/03/02.8403160345
- J Insurance & indemnity information
- 8403060413 Forwards Endorsement 23 to NELIA Policy NF-258 DUCK.J R March & McLennan, Inc. B4/02/28 SALTZMAN.J Assistant Director for State & Licenses Relations 2pp 22518 269 24X Fichs 30-438.84/02/28.8403060413
- @ Inspection reports: IE Bulletins & correspondence
- 8403070241 Supple response to NRC 1tr re violations noted in 1E Insp Repts 50-438/83-20 & 50-437/83-20 No actions by vendor necessary to prevent recurrence of abrasion of condensate pot piping MILLS, L M Tennessee Valley Authority 83/12/05 O'REILLY, J P Region 2: Office of Director 2pp 22547 325 24X Fiche 50-438.83/12/05.8403070241
- 8403070066 Responds to NRC 811208 ltr re violations noted in IE Insp Repts 50-438/81-29 & 50-439/81-29 Corrective actions repair plan for letdown cooler supports revised Campletion dates expected by 840601 for Unit 1 & 850131 for Unit 2 HILLS,L M Tennessee Valley Authority 83/12/07 B'REILLY,J P Region 2. Office of Director 1p 22545 340 24X Fiche 50-438,83/12/07,8403070066
- 8403070089 Revises 831103 response to NRC B31005 ltr re violations noted in IE Insp Rept 50-438/83-23 Corrective actions craft GA training revised to include training for ironworkers on HVAC dutuwork supports Training complete MILLS.L M Tennessee Valley Authority 83/12/13 G'REILLY,JP Region 2. Office of Director 2pp 22541 281 24X Fiche 50-438,83/12/13,8403070089
- 8403070218 Ack receipt of 840125 supplemental ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-438/81-33 & 50-439/81-33 Co-439/81-33 Co-439/81-33 Co-439/81-32 Concurs w/dental of violation VERRELLI,D M Division of Project & Resident Programs 84/02/23 PARRIS.H G Tennessee Valley Authority 1p 22541 294 24X Fiche 50-438,84/02/23,8403070218
- --B403070224 Submits second revised response to NRC 820126 ltr re violations nated in IE Insp Repts 50-438/81-33 & 50-439/81-31 Violation re piping being cold sprung due to installation of seismic supports denied MILLG.L M Tennessee Valley Authority 84/01/25 0'REILLY, J P Region 2, Office of Director 3pp 22541 297 24X Fiche 50-438,84/02/23,8403070218
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of Now York, Inc 115pp 22909 239 24X Fiche 50-000.84/02/28, 8401190072
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE.J.N Division of GA, Bafeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000,84/03/02,8402090007
- 8402090008 IE Info Notice B4-16, "Failure of Automatic Sprinkler Sys Valves to Operate" Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008
- B402090009 lE Info Notice B4-15, "Reporting of Radiological Releases" Syc list and JURDAN, Et. Division of Emergency Preparadness & Engineering Response (Post B30103) B4/03/02 Consolidated Edison Co of New York, Inc. 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8403160140 Ack receipt of 831103 & 1213 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/83-23 & 50-439/83-23 Concurs w/denial of Factors 2 & 3 of item 8 LEWIS:R C Division of Project & Resident Programs 84/03/02 PARRIS:R W Tennessee Valley Authority 2pp 22655 333 24X Fiche 50-438.84/03/02.8403160140

- 8402070011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl UDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22583 336 24X Fiche 50-000,84/03/05,8402070011
- 8402090024 IE Info Natice 84-09, Rev 1, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of Naw York, Inc. 118pp 22635 049 24X Fiche 50-000,84/03/07,8402090024
- 8402090028 IE Info Natice 84-18, "Stress Corrosion Cracking in PWR Sys " Svc list enc! JURDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fishs 50-000 84/03/07, 8402090028
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Glass IE Safety Sys " Svc list encl DEYOUNG.R C Director's Office. Office of Inspection and Enforcement B4/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche. 50-000.84/03/12,8402090031
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823,229 24X Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Releys in Safety-Related Sys " Svc list encl JURDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044
- S Reportable occurrences. LERs & related correspondence
- B403010451 Informs Commission of problems w/emergency diesel generators mfg by Transamerica Delaval. Inc DIRCKS. W J Office of the Executive Director for Operations SECY-83-034 84/01/25 4pp 22438 347 24X Fiche 50-000.84/01/25.8403010451
- 8403010376 Final deficiency rept re welds on assemblies supplied by Transamerica Delaval & IIE Imperial not meeting QA requirements Initially reported on 830615 Condition not reportable per 100FR50 55(e) MTLLSI.L M Tennessee Valley Authority 84/02/22 O'REILLY, J P Region 2. Office of Director 2pp 22434 057 24X Fiche 30-438.84/02/22.8403010376
- 8403010073 Third interim deficiency rept re manual adjustment of diesel generator setpoints Initially reported on 830307 Util will install automatic voltage regulator reset package Next rept will be submitted by 840824 MILLS.L M Tennessee Valley Authority 84/02/23 D'REILLY, J P Region 2, Defice of Director 2pp 22435 361 24X Fiche 50-438,84/02/23.8403010099
- 8403010207 Forwards "Investigation of Tupes AF & AE Piston Skirts," per Transamerica Delaval, Inc Duners Group program commitments Rept evaluates cracks in AF piston skirts in Shoreham & Grand Gulf Nuclear Power Stations MUSELER, W J TDI (Transamerica Delaval, Inc) Owners Group 84/08/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 22434 090 24X Fiche 50-000.84/02/27,8403010207
- 8403070163 First interim deficiency rept re carbon steel pipe supports top coated u/Carboline 305 paint in contact u/stainless steel piping Instructions issued to remove paint from surfaces where contact exceeds 140 F Next rept by 840822, MILGs.L M Tennessee Valley Authority 84/02/27 O'REILLY, J P Negion 2, Office of Director 2pp 22575 133 24X Fiche 50-438.84/02/27.8403090163
- 840309018: Twelfth interim deficiency rept re main steam line failure due to main feedwater overfill Initially reported on 800319. Field change package submitted by B&W Next rept by 840622. Also reportable per Part 2! MILLER.LM Tennessee Valley Authority 84/02/27 O'REILLY, J.P. Region 2. Office of Director. Spp 22573.272. 24X Fiche 50-438,84/02/27,8403090181
- B403010218 Forwards tesk descriptions for 16 known problems re Transamerica Delaval, Inc emergency dissel generators MUSELER, M J TDI (Transamerica Delaval, Inc.) Dwners Group B4/02/28 DENTON, H R. Office of Nuclear Reactor Regulation, Director 42pp 22435 177 24X Ficha 50-000, B4/02/28, B403010218.

- 8403070024 Revised final deficiency rept re defective attachments of pipe supports to 6-inch strip plates Initially reported on Bi1231 Engineering Change Notice 1572 written to accomplish required mods
 MILLS,L M Tennessee Valley Authority 84/02/28 D'REILLY,J P Region 2, Office of Director 2pp 22576 027 24x
 Fiche 50-438,84/02/28,8403090024
- 8403070277 First interim deficiency rept re numerous deficiencies on E-max panels Initially reported on 840131 Incorrect connected wires will be repaired Next rept by 840607 Also reportable per Part 21 MILLS.L M Tennessee Valley Authority 84/02/29 O'REILLY, J P Region 2. Office of Director 2pp 22546 357 24X Fiche 50-438.84/02/29.8403070297
- 8403070329 First interim deficiency rept re adaptor keyway on 8-inch Borg-Warner globe valves Initially reported on 840131 Vendor will provide corrective action & identify addl valves requiring mods Also reportable per Part 21 MILLS.L M Tennessee Valley Authority 84/02/29 0'REILLY, J P Region 2. Office of Director 2pp 22546 313 24X Fiche 50-438.84/02/29,8403070329
- B403070274 Second interim deficiency rept re carbon steel dowel pin found in HPI pump Initially reported on B31107 Pin removed & wet cloth test performed to verify no residual rust remains Next rept expected by 840822 MILLS.L M Tennessee Valley Authority B4/03/01 O'REILLY,J P Region 2. Office of Director 2pp 22541 290 24X Fiche 50-438,84/03/01,8403070274
- 8403120105 First interim deficiency rept re loose drive hubs on overspeed governor drive shaft on Transamerica Delaval, Inc diesels Initially reported on 840203 Svc info memo being reviewed for approval Also reportable per Part 21 MILLS.L M Tennessee Valley Authority 84703/01 O'REILLY, J P Region 2. Defice of Director 2pp 22585 227 24X Fiche 50-000,84/03/01,8403120105
- 8403120163 First interim deficiency rept re setting of shutdown voltage for vital inverters by Intl Power Machines Initially reported on 840209 Corrective action requested from vendor Next rept by 840522 Also reported per Part 21 MILLS.L M Tennessee Valley Authority 84/03/01 O'REILLY.J P Region 2. Office of Director 29p 22589 207 24% Fichs 50-438.84/03/01.8403120163
- 8403140048 Forwards "Grand Oulf Component Tracking Sys," "Shoreham Component Tracking Sys" & "Transamerica Delaval, Inc Diesel Generators Duners Group Program Plan," to resolve concerns w/emergency diesel generators MUSELER.W J Long Island Lighting Co 84/03/02 DENTON, H R Office of Nuclear Reactor Regulation. Director 2pp 22626 062 24X Fichs. 50-000, 84/03/02, 8403140048
- --8403140095 "Transamerica Delaval, Inc Diesel Generators Owners Group Program Plan " * TDI (Transamerica Delaval, Inc) Owners Group 84/03/02 261pp 22628 223 24X Fiche 50-000,84/03/02,8403140048
- B403150059 Revised final Deficiency Rept NCR 2053 re cable bend radii for diesel generator control cabinets Initially reported on B21206 BbJ not considered nonconforming condition Records amended deleting nonconformance as 10CFRSD 55(s) item MILLS.L N Tennessee Valley Authority B4/03/05 O'REILLY, J P Region 2, Office of Director 2pp 22641 023 24X Fiche 50-438,84/03/05,8403150059
- 8403160042 First interim deficiency rept re ITT Orinnel pipe supports designed w/sway struts instead of required gaps Initially reported on 840108 Alternate analysis load tables will be revised Also reportable per Part 21 Next rept by 840828 MILGS.L M Tennesses Valley Authority 84/03/06 O'REILLY, J P Region 2, Office of Director 2pp 28655 126 24X Fiche.50-438.84/03/06.8403160042
- 8402090039 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delayal, Inc (TDI) Owners Group Distribution list encl EIBENNUT.D 0. Division of Licensing 84/03/12 PALLADING Commissioners 5pp 22708 001 24X Ficha.50-000.84/03/12, 8402090039
- --8403060536 Forwards summary of 840210 meeting w/Transamerica Delaval.
 Inc Gunere Group in Bethesda.MD re problems w/emergency
 diesel generators
 CARUSO.R Licensing Branch 2 84/02/27 O'REILLY, J P NRC No
 Detailed Affiliation Given 6pp 22708 006 24X
 Fiche 50-000.84/03/12.8402090039

- --8403060534 Transcript of 840210 meeting w/Transamerica Delaval.Inc Clumers Group in Bethesda.MD re problems w/emergency diesel generators * NRC - No Detailed Affiliation Civen 84/02/10 147pp 67201 008 24X Fiche 50-000.84/03/12.8402070037
- --8403070409 Summary of 840216 meeting w/Transamerica Delaval, Inc Owners Group in Wading River.NY re program plan to establish reliability of diesel generators Agenda, meeting transcript & attendance list encl MILLER.M A Licensing Branch 4 B4/02/27 Licensing Branch 4 Bpp 22708 161 24% Fiche 50-000.84/03/12.8402095039
- --8403070423 Transcript of 840216 conference in Wading River,NY re Transamerica Delaval,Inc diesel generators Pp 1-82 * Commissioners 84/02/16 B4pp 22708 169 24X Fiche 50-000,84/03/12.8402090009
- 8403140090 Forwards "Design Review of Connecting Rod Bearing Shells for Transamerica Delaval Enterprise Engines" for Shoreham & Grand Gulf diesel generators MUSELER.W J Long Island Lighting Co 84/03/12 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 22632 074 24X Fiche 50-000.84/03/12.8403140090
- 8403190297 Third interim Deficiency Rept NCR 2393 re Bingham-Willamette makeup/HPI pump vibration Initially reported on 830622 Next rept expected by 840723 Item also reportable under Part 21 MILLS.L M Tennessee Valley Authority 84/03/12 O'REILLY.J P Region 2. Office of Director 3pp 22672 275 24X Fiche 30-438,84/03/12,8403190287
- 8403150133 Forwards "Transamerica Delaval, Inc Diesel Generator Rocker Arm Capscrew Stress Analysis Rept " Capscrew design adequate for applicable engines & svc conditions MUSELER, W J TDI (Transamerica Delaval, Inc.) Owners Group 84/03/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22639 270 24X Fiche 50-000, 84/03/13, 8403150133
- 8403210046 First interim deficiency rept re ITT Grinnel pipe supports designed w/sway struts instead of required caps Initially reported on 840216 Next rept by 850213 Also reportable per Part 21
 MILLS.L M Tennessee Valley Authority 84/03/13 O'REILLY, J P Region 3, Office of Director 2pp 22704 328 24X
 Fiche 50~438,84/03/13,8403210046
- 8403210042 First interim deficiency rept re incorrect insulation weights for intake pumping station piping Initially reported on 840221 Util will perform document insulation weight calculations for ERCW sys MILLS, L. M. Tennessee Valley Authority 84/03/14 0'REILLY, J. P. Region 2, Office of Director 2pp 22707 037 24X Fiche 50-438,84/03/14,8403210042
- 8403210132 First interim deficiency rept re defects in reactor pressure vessel (RPV) stud holes Initially reported on 840216 for Unit I Maint insp requirements revised to include vendor requirements for insp of RPV stud bolt holes MILLS.L M Tennessee Valley Authority 84/03/14 D'REILLY, J P Region 2. Office of Director 2pp 22707 270 24X Fiche 50-438,84/03/14.8403210132
- 8403200222 Responds to 840214 Requests for Info 1 & 2 re R-4 series angines List indicating engine number, model & svc number, customer name & address, rating, date shipped & date started enci
 MATHEWS, C S Transamerica Delaval, Inc 84/03/16 EISENHUT, D G Division of Licensing 20pp 22691 179 24X Fiche 30-000, 84/03/16, 8403200222
- 8403300021 Supplemental deficiency rept re incorrect insulation weights for intake pumping station piping Initially reported on 840221 First interim rept dtd 840314 inadvertently omitted fact that next rept would be submitted on 841130 MILLS, i. M Tennessee Valley Authority 84/03/21 O'REILLY, J P Region 2. Office of Director ip 22822 178 24X Fiche 30-438,84/03/21.8403300021
- 8403300039 Supplemental deficiency rept re defects in reactor pressure vessel stud holes Initially reported on 840216 for Unit 1 Next rept will be submitted by 840716 MILLS.L M Tennessee Valley Authority 84/03/21 O'REILLY.J P Region 2. Office of Director 1p 22821 339 24X Fiche 30-438,84/03/21,8403300039
- 8403300004 Final deficiency rept re incorrect modeling of problems in TPIPE program Initially reported on 820801 Item not considered reportable under 10CFR50 35(e) Records amended to delete subj.nonconformance
 MILLS.L M Tennessee Valley Authority 84/03/22 O'REILLY, J P Region 2. Office of Director 2pp 22819 295 24X
 Fiche 30-438,84/03/22,8403300004

- 8403300054 Fifth interim deficiency rept re defects in raw cooling water chiller unit flow control valves mfg by Metrex Valve Corp Initially reported on 821126 Investigation in progress Next rept by 890421 Also reportable per Part 21 MILLS.L M Tennessee Valley Authority 84/03/22 O'REILLY.J P Region 2. Office of Director 2pp 22821 264 24X Fiche 50-438.84/03/22.8403300054
- 8403270132 Forwards "Emergency Diesel Generator Air Start Valve Capscrew Dimension & Stress Analysis." prepared by SSM for Transamerica Delaval.Inc (TDI) Diesel Generator Owners Group MUBELER.W J TDI (Transamerica Delaval. Inc.) Owners Group B4/03/23 DENTON.H R Diffice of Nuclear Reactor Regulation. Director 2pp 22774 001 24% Fiche 50-000.84/03/23.8403270132
- 8403270134 Requests meeting on 840418 to discuss short-term & long-term corrective actions & investigations re Transamerica
 Delaval diesel generators List of suggested meeting topics
 enc!
 MC6AUGHY, J P TDI (Transamerica Delaval, Inc.) Owners Group
 84/03/23 DENTON.H R Office of Nuclear Reactor Regulation.
 Director 4pp 22769 133 24K Fiche 50-000.64/03/23.8403270134
- T Hearing transcripts on non-antitrust matters
- 8402090039 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delaval.Inc (TDI) Owners Group Distribution list encl EISENHUT, D 0 Division of Licensing 84/03/12 PALLADIND Commissioners 5pp 22708 001 24X Fiche 50-000.84/03/12.0400300003
- --8403060536 Forwards summary of B40210 meeting w/Transamerica Delaval.
 Inc Owners Group in Bethosda.MD re problems w/emergency
 dissel generators
 CARUBO.R Licensing Branch 2 84/02/27 O'REILLY, J P NRC No
 Detailed Affiliation Given 6pp 22708 006 24X
 Fiche 50-000,84/03/12,8402090039
- --8403060554 Transcript of 840210 meeting w/Transamerica Delaval.Inc Owners Group in Bethesda.MD re problems w/emergency diesel generators * NRC - No Detailed Affiliation Given 84/02/10 147pp 67201 008 24X Fiche 50-000.84/03/12.8402070039
- --8403070409 Summary of 840214 meeting w/Transamerica Delaval, Inc Duners Group in Wading River,NY to program plan to establish reliability of diesel generators Agenda, meeting transcript & attendance list encl MILLER,M A Licensing Dranch 4 84/02/27 Licensing Branch 4 8pp 22708 161 24% Fisch 50-000,84/03/12,8402090037
- --8403070423 Transcript of 840216 conference in Wading River, NY re Transamerica Delaval, Inc. diesel generators Pp. 1-82 * Commissioners 84/02/16 84pp. 22708 169 24X Fiche 50-000, 84/03/12, 8402090039
- DOCKET 50-439 BELLEFONTE NUCLEAR PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 8403160247 Informs of 840327 meeting to discuss proposed responses to NRC questions on Rev 7 to topical GA program, per 840302 telcon

 LEWIS.R C Region 2, Office of Director 84/03/08 PARRIS.H O Tennessee Valley Authority 1p 22660 361. 24X

 Fiche 50-000.894/03/08.8403160247
- 8403160373 Notifies of use of ASHE Nuclear Components Code Case N32-4 for hydrostatic testing of Class 3 embedded piping ARC position re use of Code Case N32-4 requested.

 MILLS.L. M. Tennessee Valley Authority 84/03/12 DENTON; H.R. Office of Nuclear Reactor Regulation, Director 1p 22660 014 24X Fiche 50-000,84/03/12,8403160373
- F Security, medical, emergency & fire protection plans

8403160345 Extends invitation to attend region 840316 workshop at regional off to discuss 100FR50.App R requirements & recent results of insp to help resolve misunderstandings associated w/requirements

LEWIS.R C Division of Project & Resident Programs 84/03/02

PARRIS.H G Tennessee Valley Authority 2pp 22660 083 24X

Fichm 50-000.84/03/02.8403160345

- O Inspection reports. IE Bulletins & correspondence
- 8403070241 Supple response to NRC ltr re violations noted in IE Insp. Repts 50-438/83-20 & 50-439/83-20 No actions by vendor necessary to prevent recurrence of abrasion of condensate pot piping MILLS-L M Tennessee Valley Authority 83/12/05 O'REILLY, J P Region 2. Office of Director 2pp 22547 325 24X Fiche 50-438,83/12/05,8403070241
- 8403070046 Responds to NRC 811208 ltm re violations noted in IE Insp Repts 50-438/81-29 & 50-439/81-27 Corrective actions repair plan for letdown cooler supports revised Completion dates aspected by 840601 for Unit i & 850131 for Unit 2 MILLS.L M Tennessee Valley Authority 83/12/07 O'REILLY, J P Region 2. Office of Director 1p 22545 340 24X Fiche 50-438.83/12/07.8403070066
- 8403070218 Ack receipt of 840125 supplemental ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/81-33 & 50-439/81-33 Concurs w/dental of violation, VERRELLI,D M Division of Project & Resident Programs 84/02/23 PARRIB,K G Tennessee Valley Authority. 1p 22541 276 24X Fiche 50-438,84/02/23,8403070218
- ---8403070224 Submits second revised response to NRC 820126 ltr re
 violations noted in IE Insp Repts 50-439/81-33 &
 50-439/81-31 Violation re piping being cold sprung due to
 installation of seismic supports denied
 MILLS.L M Tennessee Valley Authority 84/01/25 O'REILLY.J P
 Region 2. Office of Director 3pp 22541 277 24X
 Fiche 50-438,84/02/23,8403070218
- B401190072 lE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunclation." Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22707 237 24X Fiche 50-000,84/02/28,8401190072
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list enc! GRACE. J N Division of GA, Bafeguards & Inspection Programs (Post B30103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 28552 329 24% Fiche 50-000.84/03/02.8402090007.
- 8402070008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JOHDANLE L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008
- B402090009 IE info Notice B4-15, "Reporting of Radiological Releases"
 Bvc list encl
 JURDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) B4/03/02 Consolidated Edison Co of New
 York, Inc 119pp 22553 217 24X Fichs 50-000.84/03/02.8402090009
- 8402090011 FE Info Notice 84-17, "Problems W/Liquid Nitragen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fichs 50-000,84/03/05,8402090011
- 8402070024 IE Info Notice 84-07.Rev 1, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Syc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22635 047 24X Fiche 50-000,84/03/07,8402070024
- 8402090028 [E Info Notice 84-18, "Stress Corrosion Cracking in PWR Sys " Svc list and I JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22584,186 24X Fiche.50-000,84/03/07,8402090028
- 8402070031 IE Bulletin 84-02, "Failures of QE Type HFA Relays in Use in Class IE Bafety Sys " Svc list encl DEYDUNG:R C Director's Office, Diffice of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000,84/03/12,8402070031
- 8402070043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JORDAN'E L. Division of Energency Preparedness & Engineering Response (Post 830103) 84/03/21. Consolidated Edison Co of New York, Inc 123pp 22823 227 24X Fiche 50-000,84/03/21,8402070043

- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc list and!
 JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24% Fiche 50-000.84/03/21,8402090044
- S Reportable occurrences, LERs & related correspondence
- 8403010207 Forwards "Investigation of Types AF & AE Piston Skirts," per Transamerica Delaval. Inc Owners Group program commitments Rept evaluates cracks in AF piston skirts in Shoreham & Grand Gulf Nuclear Power Stations MUSELER, W J TDI (Transamerica Delaval, Inc.) Owners Group 84/02/27 DENTON. HR B Office of Nuclear Reactor Regulation, Director 3pp 22434 090 24X Fiche 50-000.84/02/27,8403010207
- 8403010451 Informs Commission of problems w/smergency diesel generators mfg by Transamerica Delaval Inc DIRCKS.W J Office of the Executive Director for Operations SECY-83-034 84/01/25 4pp 22438 347 24X Fiche 50-000.84/01/25.8403010451
- 8403010376 Final deficiency rept re welds on assemblies supplied by Transamerica Delaval & IIE Imperial not meeting GA requirements Initially reported on 830615 Condition not reportable per iOCFRSO 55(e) MILLS:L M Tennessee Valley Authority 84/02/22 O'REILLY,J P Region 2. Office of Director 2pp 22434 057 24X Fichs 50-438:84/02/22.8403010376
- 8403010075 Third interim deficiency rept re manual adjustment of diesel generator setpoints Initially reported on 830307 Util will install automatic Voltage regulator reset package Next rept will be submitted by 840824 MILLS.L M Tennessee Valley Authority 84/02/23 O'REILLY.J P Region 2, Office of Director 2pp 22435 361 24X Fiche 50-438.84/02/23,8403010075
- 8403090163 First interim deficiency rept re carbon steel pipe supports top costed w/Carboline 305 paint in contact w/stainless steel piping Instructions issued to remove paint from surfaces where contact exceeds 140 F Next rept by 840822 MILES.L M Tennessee Valley Authority 84/02/27 0'REILLY, J P Region 2, Office of Director 2pp 22575 133 24X Fiche.50-438.84/02/27.8403090163
- B4030901Bi Twelfth interim deficiency rept re main steam line failure due to main feedwater overfill Initially reported on 800319 Field change package submitted by B&W Next rept by 840622 Also reportable per Part 21 MILLB.L.M. Tennessee Valley Authority 84/02/27 D'REILLY, J.P. Region 2. Office of Director 3pp 22573 272. 24X Fiche: 50-438, 84/02/27, 8403090181
- 8403010218 Forwards task descriptions for 16 known problems re Transamerica Delaval, Inc emergancy diesel generators MUSELER, M. J. TDI (Transamerica Delaval, Inc.) Owners Group 84/02/28 DENYON, H.R. Office of Nuclear Reactor Regulation, Director 42pp 22435 177 24X Fiche 50-000,84/02/28,8403010218
- 8403090024 Revised final deficiency rept re defective attachments of pipe supports to 6-inch strip plates Initially reported on 811231 Engineering Change Notice 1572 written to accomplish required mods
 MILLBIL M Tennessa Valley Authority 84/02/28 D'REILLY, J P Region R. Office of Director 2pp 22576 029 24X
 Fiche 50-438,84/02/28,8403090024
- 8403070297 First interim deficiency rept re numerous deficiencies on E-max panels, Initially reported on 840131 Incorrect connected wires will be repaired Next rept by 840607 Also reportable per Part 21 MILLS,L.M Tennessee Valley Authority 84/02/29 D'REILLY,J P Region 2, Defice of Director 2pp 22546 357, 24X Fiche: 50-438,84/02/29,8403070297
- 8403070329 First interim deficiency rept re adaptor keyway on 8-inch Borg-Marner globe valves Initially reported on 840131 Vendor will provide corrective action & identify add1 valves requiring mods. Also reportable per Part 21 MILLB.L M. Tennessee Valley Authority 84/02/27 O'REILLY.J P Region 2. Office of Director 2pp 22546 313 24X Fiche 50-438.84/02/29,8403070329
- 8403070294 Second interim deficiency rept re carbon steel dowel pin' found in HPI pump Initially reported on 831109. Pin removed & wet cloth test performed to verify no residual rust remains. Next rept expected by 840822
 MILLS.L M Tennessee Valley Authority 84/03/01 O'REILLY, J P Region 2. Office of Director 2pp 22541.290 24X
 Fiche: 30-438,84/03/01,8403070294

- B403120105 First interim deficiency rept re loose drive hubs on overspeed governor drive shaft on Transamerica Delaval.Inc diesels Initially reported on B40203 Svc info memo being reviewed for approval Also reportable per Part 21 MILLS.L M Tennessee Valley Authority B4/03/01 O'REILLY,J P Region 2. Office of Director 2pp 22985 229 24X Fiche 50-000.84/03/01.8403120105
- 8403140048 Forwards "Grand Gulf Component Tracking Sys," "Bhorsham Component Tracking Sys" & "Transamerica Delayal, Inc Diesel Generators Dumers Group Program Plan: "to resolve concerns w/emergency diesel generators MUSELER.W J Long Island Lighting Co 84/03/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22626 062 24X Fiche 50-000,84/03/02,8403140048
- --8403140095 "Transamerica Delaval, Inc Diesel Generators Owners Group Program Plan " * TDI (Transamerica Delaval, Inc.) Owners Group 84/03/02 261pp 22628 223 24X Fiche 50-000,84/03/02,8403140048
- B403i50007 First interim deficiency rept re failure of dc isolation amplifiers in safety-related panels mfg by El-Te, resulting in erroneous control room indications on 125-volt dc sys Initially reported on B402i4 Next rept by B40706 MILLS.L M Tennessee Valley Authority B4/03/05 0'REILLY, J P Region 2. Office of Director 2pp 22643 295 24X Fichs 50-439.84/03/05.8403150007
- 8403160042 First interim deficiency rept re ITT Orinnel pipe supports designed W/sway struts instead of required gaps Initially reported on 840108 Alternate analysis load tables will be revised Also reportable per Part 21 Next rept by 840828 MILLG.L M Tennessee Valley Authority 84/03/06 O'REILLY, J P Region 2. Office of Director 2pp 22655 126 24X Fiche 50-438,84/03/06.8403160042
- 8402090039 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delaval. Inc (TDI) Duners Group Distribution list encl EISENHUT.D G Division of Licensing 84/03/12 PALLADING Commissioners 5pp 22708 001 24X Fiche 50-000,84/03/12,8402090039
- --B403060534 Forwards summary of B40210 meeting w/Transamerica Delaval, Inc Dumbers Group in Bethesda,MD re problems w/emergency diessi generators CARUSO.R Licensing Branch 2 84/02/27 O'REILLY.J P NRC No Detailed Affiliation Given App 22708,006 24X Fiche 50-000,84/03/12.8402070037
- --8403060554 Transcript of 840210 meeting w/Transamerica Delaval, Inc Owners Group in Bethesda, MD re problems w/emergency diesel generators. * NRC - No Detailed Affiliation Given 84/02/10 147pp 67201 008 24X Fiche 50-000,84/03/12,8408090039
- --8403070409 Summary of 840216 meeting w/Transamerica Delaval. Inc Owners Oroup in Mading River,NY re program plan to establish reliability of diesel generators Agenda.meeting transcript & attendance list enci MILLER,M A Licensing Branch 4 84/02/27 Licensing Branch 4 8pp 22708 161 24% Fiche 80-000:84/03/12,8402090039
- --8403070423 Transcript of 840216 conference in Wading River, NY re Transamerica Delaval, Inc diesel generators Pp 1-82 * Commissioners. 84/02/16 8epp 22708 169 24X Fichs 50-000, 84/03/12, 8402090039
- B403140050 Forwards "Design Review of Connecting Rod Bearing Shells for Transamerica Delaval Enterprise Engines" for Shoreham & Grand Gulf dissel generaturs MUBELER.W J Long Island Lighting Co 84/03/12 DENTON, H R. Office of Nuclear Reactor Regulation. Director 2pg 22632.074 24X Fiche 50-000.84/03/12.8403140050
- 8403150133 Forwards "Transamerica Delaval, Inc Diesel Generator Rocker Arm Capscrew Stress Analysis Rept " Capscrew design adequate for applicable engines & svc conditions MUSELER, W J TDI (Transamerica Delaval, Inc.) Owners Group 84/03/13 DENTON: H R Office of Nuclear Reactor Regulation, Director 2pp 22639 270 24X Fiche 50-000,84/03/13,8403150133
- 8403210046 First interim deficiency rept re ITT Grinnel pipe supports designed w/sway struts instead of required caps Initially reported on 840216 Next rept by 850213 Also reportable per Part 21
 MILLS, L.M. Tennessee Valley Authority 84/03/13 D'REILLY, J.P. Region 3. Office of Director 2pp 22704 328 24X
 Fiche 50-438.84/03/13.8403210046

- 8403210042 First interim deficiency rept re incorrect insulation weights for intake pumping station piping Initially reported on 840221 Util util perform document insulation weight calculations for ERCM system MILLS.L M Tennessee Valies Authority 84/03/14 0'REILLY,J P Region 2. Defice of Director 2pp 22707 037 24X Fiche 50-438.84/03/14.8403210042
- 8403210132 first interim deficiency rept re defects in reactor pressure vessel (RPV) stud holes Initially reported on 840216 for Unit i Maint insp requirements revised to include vendor requirements for insp of RPV stud bolt holes HILLS.L & Tennessee Valley Authority 84/03/14 O'REILLY.J P Region 2. Office of Director 2pp 22707 270 24X Fiche 50-438.84/03/14.8403210132
- 8403200222 Responds to 840214 Requests for Info 1 & 2 re R-4 series engines List indicating engine number model & svc number, customer name & address rating date shipped & date started encl
 MATHEMS, C S Transamerica Delaval. Inc 84/03/16 EISENHUT, D Q
 Division of Licensing 20pp 22691 179 24X Fiche 50-000,84/03/16, 8403200222
- 8403300021 Supplemental deficiency rept re incorrect insulation weights for intake pumping station piping Initially reported on 840221 First interim rept dtd 840314 inadvertently omitted fact that met rept would be submitted on 841230 MILLS.L M Tennessee Valley Authority 84/03/21 O'REILLY, J P Region 2. Office of Director ip 22822 178 24% Fiche 50-438.84/03/21.8403300021
- 8403300039 Supplemental deficiency rept re defects in reactor pressure vassel stud holes Initially reported on B40216 for Unit 1 Next rept will be submitted by 840716 MILLS.L M Tennessee Valley Authority 84/03/21 O'REILLY.J P Region 2. Office of Director ip 22821 339 24x Fiche 80-438.84/03/21,8403300039
- 8403300004 Final deficiency rept re incorrect modeling of problems in TPIPE program Initially reported on 830801 Item not considered reportable ender 10CFR50 55(s) Records amended to delate subj nunconformance
 MILLS.L M Tennessee Valley Authority 84/03/22 O'REILLY.J P
 Region 2. Office of Director 2pp 22819 295 24X
 Ficher 50-438,84/03/22,8403300004
- B403270132 Forwards "Emergency Diesel Generator Air Start Valve
 Capscrew Dimension & Stress Analysis," grepared by S&W for
 Transamerica Delaval.Inc (TDI) Diesel Generator Gwmers
 Group
 MUSELER.W J TDI (Transamerica Delaval, Inc.) Gwmers Group
 B4/03/23 DENTON.H R Office of Nuclear Reactor Regulation,
 Director 2pp 22774 OOI 24% Fiche 50-000,84/03/23,8403270132
- 8403270134 Requests meeting on 840410 to discuss short-term & long-term carrective actions & investigations re Transamerica
 Delaval diesel generators List of suggested meeting topics
 encl
 MCOAUGHY, J P TDJ (Transamerica Delaval, Inc.) Owners Group
 84/03/23 DENTON, H R Office of Nuclear Reactor Regulation,
 Director 4pp 22769 133 24X Fiche 50-000,84/03/23,8403270134
- T Hearing transcripts on non-antitrust matters
- B403060413 Forwards Endorsement 23 to NELTA Policy NF-258 DUCK, J. R. Marsh & McLennan, Inc. B4/02/28 GALTZMAN, J. Assistant Director for State & Licensee Relations 2pp 22518 267 24X Fiche 50-438.84/02/28,8403060413
- 8402090039 Board Notification 84~052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delaval, inc (TDI) Owners Group Distribution list encl EISENHUT.D G Division of Licensing 84/03/12 PALLADIND Commissioners 5pp 22708 001 24% Fichs 50~000,84/03/12,8402090039
- --8403060536 Forwards summary of 840210 meeting w/Transamerica Delaval, Inc Owners Group in Bethesda, MD re problems w/emergency diesel generators

 CARUSO.R Licensing Branch 2 84/02/27 O'REILLY, J P NRC No Detailed Affiliation Given 6pp. 22708 006 24X

 Fiche 50-000,84/03/12,8402070039
- --8403060554 Transcript of 840210 meeting w/Transamerica Delaval, Inc Owners Group in Bethesda, MD re problems w/emergency diesel generators * NRC - No Detailed Affiliation Given 84/02/10 147pp 47201 008 24% Fiche 50-000,84/03/12,8402090039

- --8403070409 Summary of 840214 meeting w/Transamerica Delaval. Inc Owners Group in Wading River.NY re program plan to establish reliability of diesel generators Agenda.meeting transcript & attendance list encl MILLER.M A Licensing Branch 4 84/02/27 Licensing Branch 4 8pp 22708 141 24% Fiche 50-000.84/03/12.8402090039
- --8403070423 Transcript of B40216 conference in Wading River,NY re Transamerica Delaval, Inc diesel generators Pp 1-82 * Commissioners 84/02/16 84pp 22708 169 24X Fichs 30-000,84/03/12,8402090039
- DOCKET 50-440 PERRY NUCLEAR POWER PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8403070213 FOIA request for documents re 830719 meeting to discuss steam erosion issue in facility proceeding & TM Novak 830825 memo on steam erosion issue HIATT-S L Dhio Citizens for Responsible Energy 83/12/08 FELTON-J M Division of Rules and Records ip 22563 219 247 Fichs 50-440-83/12/08.8403070213
- 8403070215 Responds to FDIA request for documents re B30919 meeting to discuss steam prosion issue in facility proceeding & TM Novak B30825 memo on subj Forwards App A documents Documents 4 & 5 withheld (ref FDIA Exemption 5) FELTON, J M Division of Rules and Records B4/01/23 HIATT, S Ohio Citizens for Responsible Energy 3pp 22563 220 24X Fichs 50-440,84/01/23.8403070215
- --8306220210 Forwards draft staff position on Contention 15 re steam erosion Applicant has not demonstrated capability to prevent or discover effects of steam erosion Comments requested PARR, D.D. Auxiliany Systems Branch 83/06/14 LIAW, B Machanical Engineering Branch 1p 22563 226 24X Fiche 50-440,84/01/23,8403070215
- --8403070221 Requests confirmation on lead responsibilities for finalizing NRC position re-steam erosion contention issue Responsibility should be shared by Mechanical Engineering Branch & Meteorology & Effluent Treatment Branch NVAK.T M Assistant Director for Licensing 83/08/25 KNIGHT.J P Assistant Director for Comp & Structures Engineering (Post 830201) JOHNSTON, W V Assistant Director for Matls, Chem & Environ Technology (Post 830201) 2pp 22563 224 24X Fiche 50-440.84/01/23.8403070215
- 8403010246 Notification of 840417 meeting w/util, BNL & Gilbert Assoc in Bethesda: MD to discuss NRC preliminary findings re LOCA-related pool dynamic loads STEFANOLJ J Licensing Branch 1 84/02/17 YOUNOBLOOD, B. J Licensing Branch 1 3pp 22449 359 24X Fiche 50-440,84/02/17, 8403010246
- 8403020037 Notification of contract execution "Dresden & Perry Simulator Leasing," awarded to GE
 JESSUP, B Technical Assistance Contracts Branch FIN 8-8713
 84/02/17 HAVINS, O H Director's Office, Office of Inspection and
- --8403020043 Contract "Dresden & Perry Simulator Leasing," awarded to GE PIERCE,R L. General Electric Co FIN B-8713 84/02/17 38pp 22491 046 24X Fiche 50-000,84/02/17,8403020037
- 8403020435 Further response to FDIA request for documents re const assessment team visit to plant in Aug & Bept 1983 Forwards listed documents
 FELTON, J M Division of Rules and Records 84/02/22 HIATT, S, L Ohio Citizens for Responsible Energy 1p 22491 203 24X
 Ficha 50-440,84/02/22,8403020435
- --B403020441 Submits outline re const assessment team visit Related info ancl # NRC - No Detailed Affiliation Given B3/09/27 ROHRBACHER, R Director's Office, Office of Inspection and Enforcement, 58pp 22491 204 244 Fiche 30-440, 84/02/22, 8405020435
- 8403060181 Responds to Generic Ltr 84-01 re use of terms important to safety & safety-related Further discussion w/Util Classification Group & AIF Subcommittee on Safety Classification recommended EDELMAN, M.R. Gleveland Electric Illuminating Co. 84/02/29. TAYLOR, J. M. Director's Office. Office of Inspection and Enforcement 1p. 22518 251 24X Fiche 50-440,84/02/29,8403060181.

- 8403130092 Forwards responses to NRC 840214 ltr re environ equipment qualification audit Response to exception taken by NRC in generic evaluation of Rev 1 to NEDE-24326-F will be submitted by 840423 EDELMAN.M R Cleveland Electric Illuminating Co 84/03/07 YOUNGBLOOD, B J Licensing Branch 1 374pp 22602 225 24X Fiche 50-440,84/03/07,8403130092
- --8403130106 Rev 0 to "Sys Component Evaluation Worksheet for Class IE Equipment in Harsh Environ " GOSCH.C., THOMAS.E B. MATHENY,K A. Cleveland Electric Illuminating Co. CC-74-133 ROO. 84/02/06 6pp. 22603 192 24X Fiche 50-440,84/03/07.8403130092
- ---8403:30118 Rev B to "Sys Component Evaluation Horksheet for Class IE Equipment in Harsh Environ" GOSCH: C. THOMAS: B. MATHENY, K.A. Cleveland Electric Illuminating Co. 68-1000 RB 84/02/06 6pp 22603 198 24X Fiche 50-440,84/03/07,8403130072
- --8403130128 Rev A to "Sys Component Evaluation Worksheet for Class IE Equipment in Harsh Environ"
 OORCH.C. THOMAS.E B. MATHENY.K A Cleveland Electric Illuminating Co 108025 RA 84/02/06 20pp 22603 204 24X Fiche 50-440.84/03/07.8403130072
- --8403i30i38 Rev B to "Sys Component Evaluation Workshop for Class IE Equipment in Harsh Environ " QOBCH, C. THOMAS, E B., MATHENY, K. A. Cleveland Electric Illuminating Co. 548-8654-2 RB. B4/02/06. 13pp. 22603 224. 24x Fiche 50-440,84/03/07.8403130092
- 8403190375 Informs that GA plan for operations phase, per Chapter 17 2 of FBAR.approved to expedite development of procedures & instructions during preoperational testing phase EDELMAN.M R Claveland Electric Illuminating Co 84/03/08 KEPPLER.J G Region 3, Office of Director ip 22675 217 24X Fichs 50-440,84/03/08,8403190375
- 8403190391 Forwards tables reflecting nuclear power plant experience for operating shift positions, including current staffing experience levels & level projected at time of fuel load EDELMAN.M R Cleveland Electric Illuminating Co 84/03/09 DENTON.H R Office of Nuclear Reactor Regulation, Director 13pp 22675 282 24X Fiche 50-440,84/03/09,8403190391
- 8402090041 Board Notification 84-050 provides Commission policy statement & proposed rulemaking on environ qualifications EISENHUT, D G Division of Licensing 84/03/14 Atomic Safety and Licensing Board Panel 10pp 24X Fiche 50-000.84/03/14.8402090041
- 8403230047 Advises that completion of final field wiring for diesel generator extended to 840515 EDELMAN.M R. Cleveland Electric Illuminating Co 84/03/15 KEPPLER.J G Region 3, Office of Director ip 22728 350 24X Fichs. 50~440,84/03/15,8403230047
- E NRC Bafety Evaluation Report (SER), suppls & correspondence
- 8403290337 Requests add1 copies of proposed inservice testing program for pumps & valves submitted in response to SER Gutstanding Issue 3 Relief requests should be granted, pending completion of staff review YOUNGBLOOD, B J Licensing Branch 1 84/03/14 EDELMAN, M R Cleveland Electric 11/uminating Co 3pp 22822 263 24X Fiche: 50-440, 84/03/14, 8403290357
- F. Security, medical, emergency & fire protection plans
- 8402090006 Board Notification 84-034 forwards R Vollmer 840206 memo to D Eisenhut re-fire research results concerning fires in electrical cabinets in control room EISENHUT, D G Division of Licensing 84/02/23 PALLADING Commissioners 1p 22576, 203 24X Fiche 50-000, 84/02/23, 8402090006.
- --B403080316 Recommends that info re fire research results concerning fires in electrical cabinets in control room be submitted for board uptification, per NRR Dfc Ltr 19, dtd 821001, Further evaluation of test data required.

 VOLLMER,R. H. Division of Engineering 84/02/06 EIBENHUT, D. G Division of Licensing 10pp 22376, 204 24X Fiche, 50-000, 84/02/23, 8402090006

- 8403070363 Forwards FEMA comments on Draft 2 of public info brochure, for review & consideration
 YOUNGBLOOD, B J Licensing Branch 1 84/02/27 EDELMAN, M R
 Cleveland Electric Illuminating Co 3pp 22567 205 24X
 Fiche 50-440,64/02/29,8403070363
- B403130194 Responds to NRC comments on detailed control room design review program plan.per 831223 ltr Control room inventory requirements will be satisfied.per Suppl 1 to NUREQ-0737 & Generic Ltr 83-16 during Apr 1984 task analysis review EDELMAN.M R Cleveland Electric Illuminating Co 84/02/29 YDUNGBLOOD, B J Licensing Branch 1 7pp 22617 300 24X Fiche 50-440.84/02/29,8403130194
- 8403030128 Forwards "Perry Nuclear Power Station Offsite Radiological Emergency Planning." Interim rept Exercise to test plans scheduled for 841128 KRIMM.R W Federal Emergency Management Agency 84/03/01 JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 1p 22488 223 24X Fiche 50-440,84/03/01,8403050128
- --8403050131 "Perry Nuclear Power Station Radiological Emergency Planning." interim rept # Federal Emergency Management Agency 84/01/10 192pp 22488 224 24X Fiche 50-440.84/03/01/8403050128
- B403120112 Forwards agenda for B40323 regional workshop in Rosemont.IL w/all Region III licensees to discuss fire protection safe shutdown requirements of 10CFR50.App R Workshop will provide guidance to licensees SPESBARD.R L. Division of Engineering 84/03/06 EDELMAN.M R Cleveland Electric Illuminating Co. 3pp. 22588 232 24X Fiche 50-440.84/03/06.8403120112

G Adjudicatory correspondence

- 8403020106 Answer to Sunflower Alliance, Inc 840214 motion to readmit Issue 2 re financial qualifications contention Motion should be denied based on 1982 financial qualifications rule Certificate of 8vc encl SILBERG, J C Cloveland Electric Illuminating Co SILBERG, J E Shaw, Pittman, Potts & Trowbridge 84/02/27 Atomic Safety and Licensing Board Panel 7pp 22442 101 24X Fiche 50-440.84/02/29, 8403020106
- 8403060275 Forwards supplemental answers to interrogatories on Issues 6.8 & 15 W/o affidavits Related correspondence GLASSPIEGEL.H Shaw. Pittman. Potts & Trowbridge GLASSPIEGEL,H Claveland Electric Illuminating Co 84/02/29 HIATT,S Ohio Citizens for Responsible Energy 2pp 22519 040 24x Fiche 90-440,84/02/29,8403060275
- --8403060280 Supplemental answers to interrogatories on Issues 6.8 & 15 Certificate of Svc encl Related correspondence QLASSPIEGEL, H Cleveland Electric Illuminating Co 84/02/29 24pp 22519 042 24X Fiche 50-440,84/02/29,8403060275
- B403060297 Forwards affidevits to accompany applicant supplemental answers to interrogatories on Issues 6.8 & 15 Certificate of Svc encl Related correspondence GLASBFIGEL.H Shaw Pittman. Potts & Traubridge GLASSPIEGEL.H Cleveland Electric Illuminating Co 84/03/01 HIATT, 8 Ohio Citizons for Responsible Energy 5pp 22516 255 24X Fiche 50~440.84/03/01.8403060257
- 8403140176 Response to Sunflower Alliance 840214 motion to readmit Contention 2 re applicant financial qualifications ASLB should hold in abeyance motion until further guidance provided by NRC Certificate of Evc encl WODDHEAD.C P Hearing Branch 4 84/03/05 Atomic 8afety and Licensing Board Panel 7pp 22624 104 24X Fiche 50-440,84/03/05.8403140176
- 8403130010 Answer to Ohio Citizens for Responsible Energy eleventh set of interrogatories to applicant re Issue 16 Certificate of Svc encl Related correspondence SWIGER, M A Cleveland Electric Illuminating Co SWIGER, M A Shaw, Pittman, Potts & Troubridge 84/03/08 17pp 22614 327 24X Fiche 50-440,84/03/08,8403130010
- B403130139 Interrogatories & request for production of documents to Ohio Citizens for Responsible Energy re reliability of Transmerica Delaval standby diesel generators W/Certificate of Svc Related correspondence
 BWIGER, M.A. Claveland Electric Illuminating Co. BWIGER, M.A. Shaw, Pittman, Potts & Trombridge 84/03/09 Ohio Citizens for Responsible Energy 28pp 22601 024 24X Fiche 50-440,84/03/09,8403130139

- 8403130403 Updates applicant 840208 response to Dhio Citizens for Responsible Energy interrogatory 10-2 re consultants used on Issue 16 concerning reliability of standby diesel generators Related correspondence SHIGER.M A Shaw. Pittman. Potts & Trowbridge SHIGER.M A Cleveland Electric Illuminating Co 84/03/09 HIATT.S L Chio Citizens for Responsible Energy 3pp 22616 045 24X Fiche 50-440.84/03/09.8403130403
- 8403150007 Response to ABLB 830330 order for affidavit supporting contention that polymer degradation would not create unsafe conditions Electrical equipment in Zone DW-2 acceptable Related correspondence SWIGER, M A Cleveland Electric Illuminating Co SWIGER, M A Bhaw, Pittman, Potts & Trombridge 84/03/09 5pp 22642 312 24X Fiche 50-440,84/03/09.8403150009
- --8403150014 Affidavit of 8 Kasturi in response to ASLB 830330 order re summary disposition of Issue 9 Certificate of Svc encl KASTURI.S Impell Corp 84/03/08 9pp 22642 317 24X Fithe 30-440,84/03/09.8403150009
- 8403150001 Forwards original affidavit of EJ Christiansen to replace photocopy attached to applicant 840308 answers to Ohio Citizens for Responsible Energy eleventh set of interrogatories Related correspondence SMIGER, M A Shaw, Pittman, Potts & Trowbridge SMIGER, M A Cleveland Electric Illuminating Co 84/03/12 Office of the Secretary of the Commission Opp 22641 291 24X Fiche 50-440, 84/03/12, 8403150001
- B403190066 Forwards recent insp repts re facilities to ABLB & parties WOODHEAD.C P Hearing Branch 4 B4/03/14, BLOCH.P B , KLINE, J R , BRIGHT, G O Atomic Safety and Licensing Board Panel 97pp 22664 225 24x Fichs 50-440,84/03/14,8403190066
- 8403270075 Brief in support of exceptions to partial initial decision re GA issue Cartificate of Svc encl LODGE. T J Sunflower Alliance DBs 107 84/03/20 Atomic Safety and Litensing Appeal Panel 21pp 22766 224 24x Fiche 50-440.84/03/20,8403270075
- 8403300262 Order denying Ohio Citizens for Responsible Energy 831014 motion to reconsider summary disposition re turbine missile Served on 840330 BLOCH.PB, KLINE, JR, BRIGHT, GO Atomic Safety and Licensing Board Panel DBB 226 84/03/29 Ohio Citizens for Responsible Energy 2pp 22824 014 24X Fiche 50-440,84/03/29,8403300262

H General correspondence

8403050350 Ack receipt of 840210 ltr re NRC actions on use of stiff pipe clamps IE Info Notice 83-80 issued identifying potential problem Evaluation of addl info will be documented in fluture SER STEFANO.J J Licensing Branch i 84/02/27 HIATT.S Onio Citizens for Responsible Energy 3pp 22501 323 24X Fiche 50-440.84/02/27, 8403050350

M Antitrust correspondence

- 8403050194 Responds to Antitrust Div request for NRC imposition of civil penalties re alleged willful Fallure to comply fully w/Antitrust License Condition 3 Commission Believes imposition of civil penalties inappropriate PALLADIND: N J Commissioners 84/01/31 CUTLER: M S , MCGRATH, J P Justice, Dept of, Attorney General. Office of 2pp 22528 187 24% Fiche. 50-000,84/01/31,8403050194
- B403080140 Responds to City of Cleveland B40206 motion for clarification & correction of finding of Director of NRR re OL antitrust review NRR should reaffirm findings of no significant change & deny City of Cleveland motion.

 ZAMLER.R E Shaw, Pittman, Potts & Trowbridge ZAMLER.R.E Cleveland Electric Illuminating Co B4/03/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 42pp. 22559 327, 24X Fiche 50-440.84/03/06.8403080140

• Inspection reports: IE Bulletins & correspondence

- B401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JGRDAN, Et. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp. 22909 239 24X Fiche 50-000,84/02/28,8401190072
- 3403190348 Forwards IE Insp Repts 50-440/84-01 & 50-441/84-01 on 840130-0203 No noncompliance noted LITELE, W S Region 3. Office of Director. 84/02/28 EDELMAN, M R Cleveland Electric Illuminating Co 2pp 22673, 286 24X Ficke: 50-440,84/02/28,8403190348

- --8403190354 IE Insp Repts 90-440/84-01 & 50-441/84-01 on 840130-0203 No noncompliance or deviations noted Major areas inspected procedures, work activities & quality records review for safety-related piping CILIMBERG.R L . KAUFMAN.P D . DANIELBON,D H Region 3. Office.of Director 84/02/27 7pp 22673 288 24X Fichs 50-440,84/02/28,8403190348
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE,J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000:84/03/02,8402090007
- B402070008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Syc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/02 Consolidated Edison Co of Naw York, Inc 122pp 22553 098 24X Fiche 50-000.84/03/02,8402090008
- 8402090009 IE Info Notice 84~15. "Reporting of Radiological Releases "
 Svc list encl
 JDRDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc 119pp 22553 217 24X Fiche 50-000.84/03/02,8402090009.
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JURDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05. Consolidated Edison Co of New York, Inc. 117pp 2255 336 24X Fiche 50-000.84/03/05,8402090011
- 8403120122 Ack receipt of 840824 ltr informing NRC of steps taten to correct noncompliance noted in IE lnsp Repts 50-440/83-37 & 50-441/83-35 LITTLE: W B Region 3, Office of Director 84/03/06 EDELMAN, M R Cleveland Electric Illuminating Co ip 22589 281, 24X Fichs. 50-440.84/03/06, 8403120122
- --8403120126 Responds to NRC 940127 ltr re violations noted in IE Insp. Repts 50-440/83-37 & 50-441/83-35 Corrective actions training & reevaluation of candidate performed per LK Comstock Procedure 4 14
 EDELMAN, MR Cleveland Electric Illuminating Co 84/02/24
 LITTLE, W B Division of Engineering 7pp 22589 222 24X
 Fiche 50-440,84/03/06,8403120122
- B402090024 IE Info Notice 84-09, Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Eys" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/07. Consolidated Edison Co. of New York, Inc. 118pp 22635 049 24% Fiche 50-000.84/03/07.8402070024
- 8402070028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR 8ys " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402070028
- 8403130204 Confirms 840410 meeting in Region III ofc in Olen Ellun, IL to discuss SALP NORTH IN THE PROPERTY BAYON OF Project & Resident Programs 84/03/09 EDELMAN, M R Cleveland Electric Illuminating Co 1p 22417.319 24X Fiche 50-440,84/03/09,8403130204
- 8402090031 IE Bulletin 84-02. "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 30-000.84/03/12.8402090031
- 8403190066 Forwards recent insp repts re facilities to ABLB & parties WOODMEAD.C P. Hearing Branch 4 84/03/14 BLOCH.P.B . KLINE,JR . BRIGHT.O O Atomic Safety and Licensing Board Panel. 97pp 22664 225 24% Fiche 50-440.84/03/14.8403190066
- 8403270224 Responds to Suppls 1 & 2 to IE Bulletin 83-07 re apparently fraudulent Ray Miller, Inc products Initial contact w/vendors indicates one application of product in nonsefety-related sys Completion of investigation expected by Dec 1984 EDELMAN.M R Cleveland Electric Illuminating Co. 84/03/16 KEPPLERIJ. 9 Region 3, Office of Director 1p 22772.085 24X Fiche: 50-440,84/03/16,8403270224.
- 8402070043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PHR Reactor Cavities " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000,84/03/21,8402070043

- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc list enc! JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044
- R Periodic operating reports & related correspondence
- 8403020443 Forwards monthly status rept of offsite emergency preparedness for OL reviews for Jan 1984 Changes in FEMA finding dates not caused by delay due to offsite emergency planning issues
 DIRCKB, W J Defice of the Executive Director for Operations
 8402221 PALLADINU Commissioners 9pp 22492 083 24X
 Fiche 50-000,84/02/21,8403020443
- 8 Reportable occurrences, LERs & related correspondence
- 8403010451 Informs Commission of problems w/emergency diesel generators mfg by Transamerica Delaval, Inc DIRCKB.W J Office of the Executive Director for Operations SECY-83-034 84/01/25 4pp 22438 347 24X Fiche 50-000,84/01/25,8403010451.
- 8402290274 Interim deficiency rept re loose flexible coupling drive hubs on components supplied by Transamerica Delavel.inc Initially reported on 840120 Next rept by 840531 Also reported per Part 21 EDELMAN.M R Cleveland Electric Illuminating Co. 84/02/17 KEPPLER.J & Region 3, Office of Director 2pp 22426 279 24X Fiche 50-440,84/02/17,8402290274
- 8403010207 Forwards "Investigation of Types AF & AE Piston Skirts," per Transamerica Deleval, Inc Owners Group program commitments Rept evaluates cracks in AF piston skirts in Shoreham & Grand Gulf Nuclear Power Stations. HUSELER,W J TDI (Transamerica Delaval, Inc.) Owners Group 84/02/27 DENTON, HR Office of Nuclear Reactor Regulation, Director 3pp 22434:090 24X Fiche 50-000,84/02/27,8403010207
- 8402070021 Board Notification 84-037 discusses NRC 840210 & 16 meetings w/Transamerica Delaval, Inc Emergency Diesel Generators Duners Group Heeting scheduled on 840308 for Finalization of generic program plan prior to NRC review EISENHUT, D 0 Division of Licensing 84/02/28 PALLADING Commissioners 5pp. 22546 003 24X Fiche 50-000,84/02/28, 8402070021
- 8403010218 Forwards task descriptions for 16 known problems re Transamerica Delayal, Inc. emergency diesel generators MUSELER, W. J. TDI (Transamerica Delayal, Inc.) Owners Group 84/02/28 DENTON, H. R. Dffice of Nuclear Reactor Regulation, Director 42pp. 22495 177. 24X Fiche 50-000,84/02/28,8403010218
- 840326023 Forwards summary list of deficiencies identified per 10CFR50 55(e), Part 21 & potential generic ltr repts for commants 8TARGSTECKI, R. Division of Project & Resident Programs 84/02/28 Region 1. Office of Director, 7pp. 22756 065 24X Fiche, 50-000, 84/02/28, 8403260233
- B402070020 Board Notification 84-044 forwards Part 21 rept re Transamerica Delayal. Inc. turbocharger thrust bearing lubrication defect resulting in engine nonavailability EIBENHUT, D. G. Division of Licensing 84/02/29 PALLADING Commissioners 4pp 22541, 263. 24X Fichs 50-000, 84/02/29, 8402090020
- 8403120076 Supplemental final deficiency rept re Bailey 720 station devices supplied by QE in Power Generation control complex panels (RDC 32(81)) Due to repair delays, three stations not returned Corrective action will be completed by 840501 EDELMANN R. Cleveland Electric Illuminating G 84/03/01 KEPPLER, J. Q. Region 3, Office of Director 1p 22588, 189 24X Fiche: 50-440, 84/03/01, 8403120076
- B403120052 Interim deficiency rept re cracks on actuator mounting brackets for motor operated exhaust louvers (RDC 93(84)). Initially reported on B40203. Nonconformance repts issued by M. C. C. Powers, Final rept will be submitted by B40427 EDELMAN.M.R. Cleveland Electric Illuminating Co 84/03/02 KEPFLER.J Q. Region 3, Office of Director 2pp 22586.277 24X Ficher 90-440,84/03/02,84/03120052
- B40314004B Forwards "Orand Quif Component Tracking Sys," "Shoreham Component Tracking Sys" & "Transamerica Delaval, Inc Diesel Generators Chuners Group Program Plan:" to resolve concerns w/gmergency diesel generators.

 MUSELER:W J Long Island Lighting Co. 84/03/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp. 22626 062 24X Fichs 50-000,84/03/02.8403140048

- --B403140075 "Transamerica Delaval, Inc Diesel Generators Owners Group Program Plan " * TDI (Transamerica Delaval, Inc) Dwners Group B4/03/02 261pp 22628 223 24% Fichs 50-000.84/03/02.8403140049
- 8402070033 Board Notification 84-047 forwards Transamerica Delaval.Inc Owners Group piston skirt rept & task descriptions EISENHUT.D 0 Division of Licensing 84/03/07 PALLADING Commissioners 4pp 22674 221 24X Fiche 50-000,84/03/07, 0440300032
- B403140122 Part 21 rept re status update concerning abnormal wear on linear converters Test program underway Results of investigation indicate excessive wear caused by hunting of control circuitry DDD80N. J P Parific Air Products Co 84/03/09 Director's Office Office of Inspection and Enforcement 7pp 22624:068 24X Fiche 50-000.84/03/09/8403140122
- 8403190051 Interim deficiency rept re failure of linear converters on multi-blade dampers supplied by Pacific Air Products.Co utilized in safety-related HVAC sys Initially reported on 840216 Final rept by 840710 Also reported per Part 21 EDELMAN.M R Cleveland Electric Illuminating Co 84/03/07 KEPPLER.J G Region 3, Office of Director 2pp 22666 186 24% Fiche 50-440,84/03/09,8403190051
- B40207003B Board Notification 84-051 forwards "Transamerica Delaval Inc (TDI) Diesel Generators Quners Group Program Flan " EISENHUT, D O Division of Licensing 84/03/12 PALLADINO Commissioners 5pp 22688 214 24X Fiche 50-000, 84/03/12, 8807070738
- 8402070039 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delaval.Inc (TDI) Owners Group Distribution list encl EISENHUT, D © Division of Licensing 84/03/12 PALLADING Commissioners 5pp 22708 001 24X Fiche 50-000, 84/03/12, 8402090039
- --8403060536 Forwards summary of 840210 meeting w/Trensamerica Delaval.
 Inc Owners Group in Bethesda, MD re problems w/emergency
 diesel generators
 GARUSD, R Licensing Branch 2 84/02/27 D'REILLY, J P NRC ~ No
 Detailed Affiliation Given 6pp 22708 006, 24X
 Fiche 50-000, 84/03/12, 8402070037
- --8403060854 Transcript of 840210 meeting w/Transamerica Delaval, Inc Quiners Group in Bathesda.MD re problems w/emergency diesel generators * NRC - No Detailed Affiliation Given 84/02/10 147pp 67201 008. 24X Fiche 50-000.84/03/12.8402090039
- --8403070409 Summary of B40216 meeting w/Transamprica Delaval, Inc Owners Group in Wading River,NY re program plan to establish reliability of diasel generators Agenda,meeting transcript & attendance list encl MILLER,M A Licensing Branch 4 84/02/27 Licensing Branch 4 8pp 22708 161 24X Fiche 50-000.84/03/12.8402090039
- ---8403070423 Transcript of 840216 conference in Wading River, NY re Transamerica Delaval, Inc diesel generators Pp 1-82 w Commissioners. 84/02/16 8pp 22708.167 24X Fiche 50-000,84/03/12.8402090039
- 8403140050 Forwards "Design Review of Connecting Rod Bearing Shells for Transamerica Delaval Enterprise Engines" for Shoreham & Grand Gulf diesel generators MUSELER, W. J. Long Island Lighting Co. 84/03/12 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 22632 074 24X Fiche 50-000,84/03/12.8403140050
- 8403150133 Forwards "Trensamerica Dejaval, Inc Diesel Generator Rocker Arm Capscrew Biress Analysis Rept " Capscrew design adequate for applicable engines & svc conditions MUSELER, W J TDI (Transamerica Belaval, Inc.) Owners Group 84/03/13 DENTON: H R Office of Nuclear Reactor Regulation, Director 2pp 22639; 270 24% Fiche 50~000, 84/03/13, 8403150133
- B403200222 Responds to B40214 Requests for Info 1 & 2 re R-4 series engines List indicating engine number, model & svc number, customer name & address, rating, data shipped & data started and MATHEMB, C & Transamerica Delaval, Inc. 84/03/16 & EIBENHUT, D Q Division of Licensing 20pp 22691 179 24X Fiche: 50-000, 84/03/16.

- 8403230011 Interim deficiency rept re synchronization between standby diesel generator & alternate preferred power source Initially reported on 840216 Evaluation of as-designed condition underway Nest rept by 840430 EDELMAN.M R Cleveland Electric Illuminating Co 84/03/16 KEPPLER, J G Region 3, Office of Director 2pg 22727 359 24X Fiche 50-440.84/03/16.8403830011
- 8403230045 Interim deficiency rept re design of diesel generator logic inconsistent w/FSAR Initially reported on 840216 Gilbert Associant investigating possible safety implications of identified discrepancies Next rept expected by 840430 EDELMAN, M.R. Claveland Electric Illuminating Co. 84/03/16 KEPPLER, J.G. Region S. Defice of Director 2pp 22727 361 24% Fiche 50-440,84/03/16,8403230045
- 8403230083 Interim deficiency rept re defects in design of MPC8 interfaces to suppression pool cleanup sys Gilbert Assoc.Inc avaluating as-designed condition & associated logic to determine if design change necessary Next rept by 840430 EDELMAN.M R Cleveland Electric Illuminating Co 84/03/16 KEPPLER Region 3. Office of Director 2pp 22724 291 24X Fiche 50-440.84/03/14.8403230083
- 8403230101 Interim deficiency rept re design of valve coordination for HPCS sys initially reported on 840216 AE currently investigating as-designed condition of valves & associated logic Next rept experted by 840430 EDELMAN, MR Cleveland Electric Illuminating Co 84/03/16 KEPPLER, J G Region 3, Office of Director 2pp 22726 341 24% Fiche 50-440-84/03/16,8403230101
- 8403260247 Final deficiency rept re lack of power monitor downstream of fuses in HPCS safety-related control circuits Oilbert Associanc evaluating as-designed condition of sys to make appropriate design changes Changes wapeted by 840501 EDELMAN.M R Cleveland Electric Illuminating Co 84/03/16 KEPPLER, J O Region 3. Office of Director 2pp 22756 063 24% Fiche 50-440.84/03/16.8403260247
- 8403270132 Forwards "Emergency Diesel Generator Air Start Valve
 Capscrew Dimension & Stress Analysis." prepared by S&W for
 Transamerica Delaval, Inc (TDI) Diesel Generator Dwners
 Group
 MUSELER.W J TDI (Transamerica Delaval, Inc) Dwners Group
 84/03/23 DENTON.H R Office of Nuclear Reactor Regulation,
 Director 2pp 22774 001 24% Fiche 50-000.84/03/23.8403270132
- 8403270134 Requests meeting on 840418 to discuss short-term & long-term corrective actions & investigations re Transamerica
 Delaval diesel generators List of suggested meeting topics
 enc!
 MCGAUGHY, J P TDI (Transamerica Delaval, Inc.) Owners Group
 84/03/23 DENTON, H R Office of Nuclear Reactor Regulation.
 Director 4pp 22769 133 24% Fiche 50-000, 84/03/23, 8403270134

V Operator Examinations

- 8403190391 Forwards tables reflecting nuclear power plant experience for operating shift positions, including current staffing experience levels & level projected at time of fuel load EDELMAN.M R Cleveland Electric Illuminating Co 84/03/07 DENTON.H R Office of Nuclear Reactor Regulation. Director 13pp 22675 282 24X Fiche 50-440.84/03/07.8403170391
- DOCKET 50-441 PERRY NUCLEAR POWER PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8403070213 FOIA request for documents re 830919 meeting to discuss steam erosion issue in facility proceeding & TM Novak 830825 memo on steam erosion issue HIATT 8 L. Ohio Citizens for Responsible Energy 83/12/08 FELTON, J M Division of Rules and Records 1p 28563 219 24X Fiche 50-440.83/12/08.8403070213
- B403070215 Responds to FDIA request for documents ro 830919 meeting to discuss steam erosion issue in facility proceeding & TM Novak 830825 memo on subj Forwards App A documents Documents 4 & 5 withheld (ref FOIA Exemption 5) FELTON,J M Division of Rules and Records 84/01/23, HIATT, 8 Ohio Citizens for Responsible Energy 3pp 22563 220 24X Fiche 50-440,84/01/23,8403070215

position on Contention 15 re steam
yestrated capability to prevent
brosion Comments requested
branch 857/05/14 LIAW, B
1p 22563-226 24X

- --B403070221 Requests confirmation on lead responsibilities for finalizing NRC position re steam erosion contention issue Responsibility should be shared by Mechanical Engineering Branch & Meteorology & Effluent Treatment Branch NDVAK,T M Assistant Director for Licensing B3/08/25, KNIGHT,J P Assistant Director for Comp & Structures Engineering (Post 830201) DNNSTON,W V Assistant Director for Matls. Chem & Environ Technology (Post 830201) 2pp 22563 224 24X Fiche 50-440,84/01/23,8403070215
- 8403010246 Notification of 840417 meeting w/util.BNL & Gilbert Assoc in Sethesda.MD to discuse NRC preliminary findings re LOCA-related pool dynamic loads STEFANO,J J Licensing Branch i 84/02/17 YOUNOBLOOD,B J Licensing Branch i 3pp 22449 359 24X Fiche 50-440,84/02/17, 8403010246
- B403020037 Natification of contract execution "Dresden & Parry Simulator Leasing," awarded to GE
 JESSUP.8 Technical Assistance Contracts Branch FIN B-0713
 84/02/17 HAVING.O H Director's Office. Office of Inspection and Enforcement ip 22491 045 24X Fiche 50-000.84/02/17,8403020037
- --8403020043 Contract "Dresden & Perry Bimulator Leasing," awarded to GE PIERCE,R L General Electric Co FIN 8-8713 84/02/17, 38pp 22471 046 24X Fiche 50-000,84/02/17,8403020037
- 8403020435 Further response to FOIA request for documents re const assessment team visit to plant in Aug & Sept 1983 Forwards listed documents FELTON, J M Division of Rules and Records 84/02/22 HIATT, 8 L Ohio Citizens for Responsible Energy 1p 22491 203 24X Fiche: 50-440, 84/02/22, 8403020435
- 8403040181 Responds to Generic Ltr 84-01 re use of terms important to safety & safety-related Further discussion w/Util Classification Group & AIF Bubcommittee on Safety Classification recommended EDELMAN.M R Cleveland Electric Illuminating Co 84/02/29 TAYLOR, J M Director's Office Office of Inspection and Enforcement 1p 22518 251 24X Fiche 50-440.84/02/29,8403040181
- 8403130092 Forwards responses to NRC 840214 ltr re environ equipment qualification audit Response to exception taken by NRC in generic evaluation of Rev I to NEDE-24326-P will be submitted by 840423 EDELMAN, M R Cleveland Electric Illuminating Co 84/03/07 YOUNOBLOOD, B J Licensing Branch i 374pp 22602 223 24X Fiche 50-440,84/03/07,8403130092
- --8403130106 Rev O to "Bys Component Evaluation Worksheet for Class IE Equipment in Harsh Environ" ODSCH. C. THOMAS. B. MATHENY, K. A. Clayeland Electric Illuminating Co. CC-74-133 ROO. 84/02/06 6pp. 22603 192 24X Fiche 50-440,84/03/07,8403130092
- --840313011B Rev B to "Bys Component Evaluation Worksheet for Class IE Equipment in Harsh Environ " ODBCH.C., THOMAB.E B., MATHENY.K A. Cleveland Electric Illuminating Co. ES-1000 RB 84/02/06 App. 22603:178 24X Fiche 50-440,84/03/07,8403130072
- --8403130128 Rev A to "Bys Component Evaluation Worksheet for Class IE Equipment in Harsh Environ " GOBCH. C. THOMABLE B. MATHENY.K A Cleveland Electric Illuminating Co 108028 RA 84/02/06 20pp. 22603:R04 24X Fichs 50-440.84/03/07.8403130092
- --8403130138 Rev B to "By* Component Evaluation Horkshop for Class IE Equipment in Harsh Environ " GDBCH.C: THGMA8.E B , MATHENY,K A Claveland Electric Illuminating Co 548-8854-2 RB 84/02/06 13pp 22603:224, 24X Fiche 50-440.84/03/07.8403130092
- 8403190375 Informs that GA plan for operations phase; per Chapter 17 2 of FEAR, approved to expedite development of procedures & instructions during preoperational testing phase. EDELMAN, M R Cleveland Electric Illuminating Co 84/03/08, KEPPLER. J 9 Region 3, Diffice of Director. ip. 22675:217 24X Fiche 50-440,84/03/08,8403190375

- 8403190391 Forwards tables reflecting nuclear power plant experience for operating shift positions, including current staffing experience levels & level projected at time of fuel load EDELMAN,M R Cleveland Electric Illuminating Co 84/03/09 DENTON,H R Office of Nuclear Reactor Regulation. Director 13pp 22675-282 24X Fiche 50-440.84/03/09.8403190391
- 8402090041 Board Notification 84-030 provides Commission policy statement & proposed rulemaking on environ qualifications EISENHUT, D 0 Division of Licensing 84/03/14 Atomic Safety and Licensing Board Panel 10pp 24X Fithe 50-000.84/03/14,8402090041
- 8403230047 Advises that completion of final field wiring for diesel generator extended to 840515
 EDBLMAN.M R Cleveland Electric Illuminating Co 84/03/15
 KEPPLER.J O Region 3, Office of Director 1p 22728 350 24X
 Fiche: 50-440,84/03/15,8403230047
- E NRC Bafety Evaluation Report (SER), suppls & correspondence
- 8403080179 Fourth partial response to FDIA request for six categories of documents re facilities Forwards App A documents App B documents the published (ref FDIA Exemption 5) Review of addl documents subj to request continuing FELTON, J M Division of Rules and Records. 84/02/13 ANDERSON, S I Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 30-000,84/02/13,8403080179
- --8103040052 Forwards short & long-term OL & CP review schedules, in response to 801216 meeting w/U808 List of DL plant reviews for which NRC tentatively plans to seek US08 assistance is provided.

 JACKBON, R E Geosciences Branch NRC-03-80-113 81/01/21 DEVINE, J F Interior, Dept of, Geological Survey 5pp 22583, 272 24X Fiche 50-000, 84/02/13, 8403080179
- 8403010017 Forwards SSER 4 (NUREO-0887) re operation of facilities W/o encl.
 YDUNGBLOOD, B J. Licensing Branch 1 84/02/17 EDELMAN, M P Cleveland Electric Illuminating Co 3pp 22479 341 24X Fichs. 50-440, 84/02/17, 8403010017
- 8403290357 Requests add1 copies of proposed inservice testing program for pumps & valves submitted in response to SER Outstanding Issue 5 Relief requests should be granted, pending completion of staff review YOUNGBLOOD, B J Licensing Brench i 84/03/14 EDELMAN, M R Clevelend Electric Illuminating Co 3pp 22822, 263 24X Fiche: 50-440, 84/03/14, 8403270357
- F Becurity, medical, emergency & fire protection plans
- B402090006 Board Notification 84-034 forwards R Vollmer 840206 memo to D Eisenhut re fire research results concerning fires in alectrical cabinets in control room EIBERNHUT.D 0 Division of Licensing 84/02/23 PALLADIND Commissioners ip 22576 203 24X Fiche 50-000,84/02/23,84090006
- --B403080316 Recommends that info re fire research results concerning fires in electrical cabinets in control room be submitted for board notification, per NRR Ofc Ltr 19, dtd 821001 Further evaluation of test data required VOLLMER.R H Division of Engineering 84/02/06 EIBENHUT, D G Division of Licensing 10pp. 22576 204 24% Fiche 50-000,84/02/23,8402090006
- 8403070363 Forwards FEMA comments on Draft 2 of public info brochure, for review & consideration.
 YOUNGBLODD, B. J. Licensing Branch 1 84/02/29 EDELMAN, M. R.
 Cleveland Electric Illuminating Co
 Fiche. 50-440.84/02/29,8403070363
- 8403130194 Responds to NRC comments on detailed control room design review program plan, per 831223 ltr Control room inventory requirements will be satisfied, per Suppl i to NUREO-0737 & Generic Ltr 83-18 during Apr 1984 task analysis review EDELMAN.M.R. Cleveland Electric Illuminating Co 84/02/29 YOUNDBLOOD, B.J. Licensing Brench 1 7pp 22617 300 24X Fiche: 50-440, 84/02/29, 8403130194
- 8403050128 Forwards "Perry Nuclear Power Station Offsite Radiological Emergency Planning," interim rept Exercise to test plans scheduled for 84128. KRIMM, R.W. Federal Emergency Management Agency 84/03/01 JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 1p 22488'223 24X Fiche 50-440,84/03/01.840305128

- --8403050131 "Perry Nuclear Power Station Radiological Emergency Planning," interim rept * Federal Emergency Management Agency 84/01/10 192pp 22488 224 24% Fiche 50-440,84/03/01.8403050128
- 8403120112 Forwards agenda for 840323 regional workshop in Rosemont, IL w/all Region III licensees to discuss fire protection safe shutdown requirements of 10CFR50, App R Workshop will provide guidance to licensees

 SPESSARD, R L Division of Engineering 84/03/06 EDELMAN, M R Cleveland Electric Illuminating Co 3pp 22588 232 24X

 Fiche 50-440,84/03/06,8403120112
- G Adjudicatory correspondence
- 8403020106 Answer to Sunflower Alliance. Inc 840214 motion to readmit Issue 2 rs financial qualifications contention Motion should be denied based on 1982 financial qualifications rule Certificate of Svc encl SILBERO. J E Cleveland Electric Illuminating Co SILBERO. J E Shaw. Pittman. Potts & Trombridge 84/02/29 Atomic Safety and Licensing Board Panel 7pp 22442 101 24% Fiche 50-440,84/02/29.8403020106
- 8403040275 Forwards supplemental answers to interrogatories on Issues 4,8 % 15 W/o affidavits Related correspondence OLASSPIEGEL.H Shaw, Pittman, Potts & Troubridge GLASSPIEGEL,H Cleveland Electric Illuminating Co 84/02/29 HIATT,8 Ohio Citizens for Responsible Energy 2pp 22519 040 24X Fiche 50-440,84/02/29,8403060275
- --8403040280 Supplemental answers to interrogatories on Issues 6,8 & 15 Certificate of Svc encl Related correspondence GLASSPIEGEL, H Cleveland Electric Illuminating Co 84/02/29 24pp 22519 042 24% Fiche 30-440.84/02/29,8403060275
- 8403060257 Forwards affidavits to accompany applicant supplemental answers to interrogatories on Issues 6.8 & 15 Certificate of Svc encl Related correspondence GLASSPIEGEL, H Bhaw. Pittman. Potts & Trowbridge GLASSPIEGEL, H Cleveland Electric Illuminating Co 84/03/01 HIATT. S Ohio Citirens for Responsible Energy 5pp 22516 235 24X Fiche 50-440,84/03/01.8403060257
- 8403140176 Response to Sunflower Alliance 840214 motion to readmit Contention 2 re applicant Pinancial qualifications ASLB should hold in abeyance motion until further guidance provided by NRC Certificate of Svc encl WOOD
- 8403130010 Answer to Ohio Citizens for Responsible Energy eleventh set of interrogatories to applicant re Issue 16 Certificate of Svc encl Related correspondence SWIGER, M A Cleveland Electric Illuminating Co SWIGER, M A Shaw. Pittman. Potts & Trowbridge 84/03/08 17pp 22614 327 24X Fiche 50~440,84/03/08,8403130010
- 8403130139 Interrogatories & request for production of &ocuments to Ohio Citizens for Responsible Energy re reliability of Transamerica Delawal standby diesel generators W/Certificate of Svc Related correspondence SWIGER, M A Cleveland Electric Illuminating Co SWIGER, M A Shaw, Pittman, Potts & Troubridge 84/03/09 Ohio Citizens for Responsible Energy 28pp 22601 024 24X Fiche 50-440.84/03/09, 8403130139
- 8403i30403 Updates applicant 840208 response to Ohio Citizens for Responsible Energy Interrogatory 10-2 re consultants used on Issue 16 concerning reliability of standby diesel generators Related correspondence SWIGER, M A Shaw, Pittman, Potts & Troubridge SWIGER, M A Cleveland Electric Illuminating Co 84/03/07 HIATT, S L Qhio Citizens for Responsible Energy 3pp 22616 045 24X Fiche 50-440,84/03/07,8403130403
- 8403130009 Response to ASLB 830330 order for affidavit supporting contention that polymer degradation would not create unsafe conditions Electrical equipment in Zone DW-2 acceptable Related correspondence SWIGER, M.A. Claveland Electric Illuminating Co. SWIGER, M.A. Shaw, Pittman, Potts & Troubridge, 84/03/09 3pp 22642 312 24X Fiche: 50~440,84/03/09,8403150009
- --B403130014 Affidavit of B Kasturi in response to ASLB B30330 order re summary disposition of Issue 9 Certificate of Syc encl KABTURI.S Impell Corp B4/03/08 9pp 22642 317 24X Fiche 50-440.84/03/09.8403150009

- 8403150001 Forwards original affidavit of EJ Christiansen to replace photocopy attached to applicant 840308 answers to Chio Citizens for Responsible Energy eleventh set of interrogatories Related correspondence SHIGER.M A Shaw Pittman Potts & Trowbridge Cleveland Electric Illuminating Co 84/03/12 Gffice of the Secretary of the Commission 3pp 22641 271 24X Fiche 50-440.84/03/12,8403150001
- 8403190066 Forwards recent insp repts re facilities to ABLB & parties HODDHEAD,C P Hearing Branch 4 84/03/14 BLDCH.P B . KLINE.J R . BRIGHT, 0 O Atomic Bafety and Licensing Board Panel 97pp 22664 225 24x Fiche 30-440.84/03/14.8403190066
- 8403270075 Brief in support of exceptions to partial initial decision re QA issue Certificate of Svc encl LODGE.T J Sunflower Alliance DSB 107 B4/03/20 Atomic Safety and Licensing Appeal Panel 21pp 22766 224 24X Fiche 50-440.84/03/20,8403270075
- 8403300262 Order denying Ohio Citizens for Responsible Energy 831014 motion to reconsider summary disposition re turbine missile Served on 840330 BLOCH,P B , KLINE, J R , BRIGHT,O O Atomic Safety and Licensing Brand Panel. DSB 226 84/03/29 Ohio Citizens for Responsible Energy 2pp 22824 014 24% Fiche 50-440.84/03/27,8403300262

H General correspondence

8403050350 Ack receipt of 840210 ltr re NRC actions on use of stiff pipe clamps IE Info Notice 83-80 issued identifying potential problem Evaluation of add1 info will be documented in future SER STEFANO.J J Licensing Branch 1 84/02/27 HIATT,8 Ohio Citizens for Responsible Energy 3pp 22501 323 24X Fiche 50-440.84/02/27.8403050350

M Antitrust correspondence

- 8403050194 Responds to Antitrust Div request for NRC imposition of civil penalties re alleged willful failure to comply fully u/Antitrust License Condition 3 Commission believes imposition of civil penalties inappropriate PALLADIND, N J Commissioners 84/01/31 CUTLER, M S , MCGRATH, J P Justice, Dept of, Attorney General, Office of 2pp 22528 187 24X Fiche 50-000,84/01/31.6403050194
- 8403080140 Responds to City of Cleveland B40206 motion for clarification & correction of finding of Director of NRR re DL antitrust review NRR should reaffirm findings of no significant change & deny City of Cleveland motion IAHLER, R E Shaw, Pittman, Potts & Trowbridge. ZAPLER, R E Cleveland Electric Illuminating Co 84/03/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 42pp. 22559 327 24X Fiche 50-440,84/03/06,8403080140

Q Inspection reports, IE Bulletins & correspondence

- 8401190072 IE Info Notice 84-13. "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN.E. Division of Emergency Preparedness & Engineering Response (Post 830103) B4/02/28 Consolidated Edison Co of New York, Inc 115pp 22909 239 24X Fiche 50-000.84/02/28,8401190072
- 8403190348 Forwards IE Insp Repts 50-440/84-01 & 50-441/84-01 on 840130-0203 No noncompliance noted LITTLE.W S Region 3. Office of Director 84/02/28 EDELMAN, M R Claveland Electric Illuminating Co 2pp 22673 286 24X Fiche 50-440,84/02/28,8403190348
- --8403190354 IE Insp Repts 50-440/84-01 & 30-441/84-01 on 840130-0203 No noncompliance or deviations noted Major areas inspected procedures work activities & quality records review for safety-related piping
 CILIMEER, R L . KAUFMAN, P D . DANIELSON, D H Region 3, Office of Director 84/02/27, 7pp. 22673 288 24X Fiche 50-440,84/02/28, 8403190348
- 8402090007 IE Info Notice 84-14. "Highlights of Recent Transport Regulatory Revs by DUT & NRC "Svc list encl GRACE, J N Division of GA: Bafeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York: Inc 130pp 22552 329 24X Fiche 50-000.84/03/02, 8402090007
- 840209000B IE Info Notice 84-16, "Failure of Automatic Sprinkler Bys Valves to Operate " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008

- 8402090009 IE Info Notice 84-15. "Reporting of Radiological Releases "
 8vc list encl
 JORDAN.E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co. of New
 York. Inc. 1179p 22553 217 24X Fiche 50-000.84/03/02.8402070009
- 8402090011 IE Info Natice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of Naw York, Inc 117pp 22553 336 24X Fichs 50-000,84/03/05.8402090011
- 8403120122 Ack receipt of 840224 ltr informing NRC of steps taken to correct noncompliance noted in IE Insp Repts 50-440/83-37 & 50-441/83-35 LITTLE.W S Region 3. Office of Director 84/03/06 EDELMAN.W R Cleveland Electric Illuminating Co ip 22589:221 24X Fichs 50-440.84/03/06.8403120122.
- --8403120126 Responds to NRC 840127 ltr re violations noted in IE Insp. Repts 50-440/83-37 & 50-441/83-35 Corrective actions training & reevaluation of candidate performed per LK Comstock Procedure 4 14.
 EDELMAN.M R Cleveland Electric Illuminating Co 84/02/24.
 LITTLE W 8 Division of Engineering 7pp 22589 222. 24X Fiche 50-440,84/03/06,8403120122.
- 8402070024 IE Info Notice 84-09, Rev 1, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl, JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07. Consolidated Edison Co. of New York, Inc. 118pp 22635 049 24X Fiche 50-000, 84/03/07, 8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PHR Sys " Svc list encl Junnah. Et Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 30-000,84/03/07,8402090028
- 8403130204 Confirms 840410 meeting in Region III ofc in Olen Ellyn, It. to discuss SALP NORELIUS, C E Division of Project & Resident Programs 84/03/09 EDELMAN, M R Cleveland Electric Illuminating Co 1p 22617 319 24X Fiche 50-440,84/03/09,8403130204
- 8402090031 IE Bulletin 84~02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl.

 DEYDUNO, R C Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co. of New York, Inc 134pp 22823 094 24X Fiche 50-000.84/03/12,8402090031
- 8403170066 Forwards recent insp repts to facilities to ABLB & parties. WOODHEAD, C P. Hearing Branch 4 84/03/14 BLUCH, P B. Atomic Safety and Licensing Board Panel 77pp 22664, 225 24X Fishs 50-440, 84/03/14, 8403170066
- B403270224 Responds to Suppls 1 & 2 to IE Bulletin 83-07 re apparently fraudulent Ray Miller-Inc products Initial contact w/vendors indicates one application of product in nonsafety-related sys Completion of investigation expected by Dec 1984 EDELMAN.M R Cleveland Electric Illuminating Co. 84/03/16 KEPPLER.J G Region 3. DPice of Director 1p 22772.085 24X Fiche 50-440,84/03/16,8403270224
- B402070043 IE Info Notice B4-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/21 Consolidated Edison Co. of New York, Inc. 123pp 22823 227 24X Fiche, 80-000, 84/03/21, 8402070043.
- B402090044 IE Info Notice B4-20, "Svc Life of Relays in Bafety-Related Bys " Bvc list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/03/21 Consolidated Edison Co. of New York, Inc 135pp. 22733 001 24X Fiche 50-000,84/03/21,8402090044.
- 8 Reportable occurrences. LERs & related correspondence
- 8403010451 Informs Commission of problems w/emergency diesel generators mfg by Transamerica Delaval, Inc.
 DIRCKS:H J Office of the Executive Director for Operations SECY-83-034 84/01/25 App 22438:347. 24X Fiche.50-000.84/01/25.8403010451
- 8402290274 Interim deficiency rept re loose flexible coupling drive hubs on components supplied by Transamarica Delaval, Inc. Initially reported on 840120 Next rept by 840531. Also reported per Part 21
 EDELMAN.M R Cleveland Electric Illuminating Co 84/02/17
 KEPPLER, J O Region 3, Office of Director 2pp 22426:299, 24X
 Fiche 50-440.84/02/17.8402290274

- B403010207 Forwards "Investigation of Types AF & AE Piston Skirts," per Transamerica Delaval. Inc Dumers Group program commitments Rept evaluates cracks in AF piston skirts in Shoreham & Grand Gulf Nuclear Power Stations MUSELER.W J TDI (Transamerica Delaval, Inc.) Gumers Group B4/02/27 DENTON: HR Office of Nuclear Reactor Regulation, Director 3pp 22434 090 24X Fiche 50-000.84/02/27.8403010207
- 8402070021 Board Notification 84-037 discusses NRC 840210 & 16 meetings w/Transamerica Delavel, Inc Emergency Diesel Generators Gumers Group Meeting scheduled on 840308 for finalization of generic program plan prior to NRC review EIEENHUT.D 9 Division of Licensing 84/02/28 PALLADINO Commissioners 5pp 22546 003 24X Fiche 50-000.84/02/28, 8402070021
- B40301021B Forwards task descriptions for 16 known problems re Transamerica Delaval, Inc emergency diesal generators MUSELER:N J TDI (Transamerica Delaval, Inc.) Owners Group. B4/02/2B DENTON, HR Office of Nuclear Reactor Regulation. Director 42pp 22435 177 24X Fiche 50-000,84/02/28,8403010218
- 8403260233 Forwards summary list of deficiencies identified per 10CFR50, 55(e), Part 21 & potential generic ltr repts for comments.

 BTAROSTECKI,R. Division of Project & Resident Programs 84/02/28 Region 1. Office of Director 7pp 22756 065 24X Fiche. 50-000, 84/02/28, 8403260233
- B402090020 Board Notification 84-044 forwards Part 21 rept re Transamerica Delaval, Inc turbocharger thrust bearing lubrication defect resulting in engine nonevailability EISENHUT, D O Division of Licensing. B4/02/27 PALLADIND Commissioners, 4pp 22541 263 24X Fiche 30-000, 84/02/27, 8402090020.
- 8403120076 Supplemental final deficiency rept re Bailey 720 station devices supplied by OE in Power Generation control complex panels (RDC 32(81)) Due to repair delays, three stations not returned Corrective action will be completed by 840501 EDELMAN.M.R. Cleveland Electric Illuminating Co. 84/03/01 MEPPLER.J Q. Region 3, Office of Director ip 22588 189 24X Ficha 50-440,84/03/01,8403120096
- 8403120032 Interim deficiency rept re cracks on actuator mounting brackets for motor operated exhaust louvers (RDC 93(84)). Initially reported on 840203 Nonconformance repts Issued by M C C. Powers Final rept will be submitted by 840427. EDELMAN, M, R. Cleveland Electric Illuminating Co. 84/03/02 KEPPLER, J O. Region 3, Office of Director 2pp 22586 279 24X Fiche 30-440,84/03/02,8403120052.
- 840314004B Forwards "Grand Gulf Component Tracking Sys," "Shoreham Component Tracking Bys" & "Transamerica Delaval, Inc Diesel Generators Owners Group Program Plan." to resolve concerns w/emergency diesel generators MUBELER.W J Long Island Lighting Co S4/03/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22626 062 24X Fiche 50-000.84/03/02.8403140048
- 8402070033 Board Notification 84-047 forwards Transamerica Delayal, Inc Owners Group piston skirt rept & task descriptions ETBENHUT, D. 9. Division of Licensing 84/03/07. PALLADIND Gommissioners App. 22674 221 24X Fiche, 50-000, 84/03/07, 8402070033
- B403140122 Part 21 rept re status update concerning abnormal wear on linear converters Test program underway Results of investigation indicate excessive wear caused by hunting of control circuitry BODBON, J.P. Pacific Air Products Co. 84/03/09 Director's Office, Office of Inspection and Enforcement 7pp 22624,068 24X Fiche: 50-000,84/03/07,8403140122.
- 840319005: Interim deficiency rept re failure of linear converters on multi-blade dampers supplied by Pacific Air Products, Co utilized in safety-related HVAC sys Initially reported on 840216. Final rept by 840710 Also reported per Part 2: EDELMAN, M.R. Cleveland Electric Illuminating Co 84/03/09 KEPPLER, J. Q. Region 3, Office of Director 2pp 22666:186 24X Ficha: 50-440,84/03/09,8403190051
- 8402090038 Board Notification 84-051 forwards "Transamerica Delaval, Inc (TDI) Diesel Generators Cuners Group Program Plan."
 EISENHUT.D G. Division of Licensing 84/03/12 PALLADINO Commissioners 5pp. 22688 214. 24X Fichs 50-000,84/03/12,8402090038.

- B402070039 Board Notification B4-052 forwards meeting summaries containing transcripts of B40210 & 16 meetings between NRC & Transamerica Delaval. Inc (TDI) Owners Group Distribution list encl
 EISENHUT.D G Division of Licensing B4/03/12 PALLADINO Commissioners 5pp 22708 001 24X Fiche 50-000.84/03/12.8402070039
- --8403060536 Forwards summary of 840210 meeting w/Transamerica Delaval.
 Inc Owners Oroup in Bethesda,MD re problems w/emergency
 diesel generators
 CARUSO,R Licensing Branch 2 84/02/27 O'REILLY,J P NRC No
 Detailed Affiliation Given 6pp 22708 006 24X
 Fiche 50-000,84/03/12,8402090039
- ---B403060554 Transcript of 840210 meeting w/Transamerica Delaval. Inc Owners Group in Bethesda, MD re problems w/emergency diesel generators * NRC - No Detailed Affiliation Given B4/02/10 147pp 67201 008 24X Fiche 50-000, 84/03/12, 8402090039
- --8403070409 Summary of 840216 meeting w/Trensamerica Delaval.Inc Owners
 Group in Wading River.NY re program plan to establish
 reliability of diesel generators Agenda.meeting transcript &
 attendance list encl
 MILLER.M A Licensing Branch 4 84/02/27 Licensing Branch 4
 Bpp 22708 161 24X Fiche 50-000.84/03/12.8402090039
- --8403070423 Transcript of B40216 conference in Wading River,NY re Transamerica Delaval,Inc diesel generators Pp 1-82 * Commissioners 84/02/16 84pp 22708 167 24X Fiche 50-000,84/03/12.8402090039
- B403140050 Forwards "Design Review of Connecting Rod Bearing Shells for Transamerica Delaval Enterprise Engines" for Shoreham & Grand Gulf diesel generators MUSELER, W J Long Island Lighting Co 84/03/12 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22632 074 24X Fiche 50-000,84/03/12,8403140050
- B403150133 Forwards "Transamerica Delaval.Inc Diesel Generator Rocker Arm Capscrew Stress Analysis Rept " Capscrew design adequate for applicable engines & svc conditions MUSELER.W J TDI (Transamerica Delaval, Inc.) Owners Group B4/03/13 DENTON.H R. Office of Nuclear Reactor Regulation, Director 2pp 22637 270 24X Fiche 50-000.84/03/13.8403150133
- B403200222 Responds to 840214 Requests for Info i & 2 re R-4 series angines List indicating engine number, model & svc number, customer name & address, rating, data shipped & data started encl
 MATHEMS.C S Transamerica Delaval, Inc 84/03/16 EISENHUT, D C Division of Licensing 20pp 22671 179 24X Fiche 50~000, 84/03/16.
- 8403230011 Interim deficiency rept re synchronization between standby diesel generator & alternate preferred power source Initially reported on 840216 Evaluation of as-designed condition underway Next rept by 840430 EDELMAN, M R Cleveland Electric Illuminating Co 84/03/16 KEPPLER. J O Region 3, Office of Director 2pp 22727:359 24X Fiche 50-440,84/03/16,8403230011
- 8403230045 Interim deficiency rept re design of diesel generator logic inconsistent w/FBAR Initially reported on 840216 Gibert Assoc, Inc investigating possible safety implications of identified discrepancies Next rept expected by 840430 EDELMAN, M.R. Cleveland Electric Illuminating Co. 84/03/16 KEPPLER, J.G. Region 3, Office of Director 2pp 22727 361 24X Fiche 50-440,84/03/16,8403230045
- 8403230083 Interim deficiency rept re defects in design of HPCS interfaces to suppression pool cleanup sys Gilbert Assoc. Inc evaluating as-designed condition & associated logic to determine if design change necessary Next rept by 840430 EDELMAN, M R Cleveland Electric Illuminating Co 84/03/16 KEPPLER Region 3, Office of Director 2pp. 22726 291 24X Fiche. 50-440,84/03/16,8403230083
- B403230101 Interim deficiency rept re design of valve coordination for HPCS sys Initially reported on B40216 AE currently investigating as-designed condition of valves & associated logic Next rept expected by B40430 EDELMAN, M. R. Cleveland Electric Illuminating Co. B4/03/16 KEPPLER, J. O., Region 3, Office of Director 2pp 22726 341 24X Fiche 50-440,84/03/16,8403230101
- 8403260247 Final deficiency rept re lack of power monitor downstream of fuses in HPCS safety-related control circuits Gilbert Assoc. Inc evaluating as-designed condition of sys to make appropriate design changes. Changes expected by 840501 EDELMAN, K R Cleveland Electric Illuminating Co 84/03/16 KEPPLER.J O Region 3, Office of Director 2pp 22756.063 24X Fiche 50-440,84/03/16,8403260247

- 8403270132 Forwards "Emergency Diesel Generator Air Start Valve Capscrew Dimension & Stress Analysis," prepared by S&W for Transamerica Delavel, Inc. (TDI) Diesel Generator Owners Oroun
- Group MUSELER, W. J. TDI (Transamerica Delaval, Inc.) Duners Group 84/03/23 DENTON: H. R. Defice of Nuclear Reactor Regulation. Director 2pp 22774 001 24X Fiche 50-000,84/03/23,8403270132
- 8403270134 Requests meeting on 840418 to discuss short-term & long-term corrective actions & investigations re Transamerica
 Belaval dissel generators List of suggested meeting topics
 ancl
 KCGAUGHY, JP TDI (Transamerica Belaval, Inc.) Owners Group
 84/03/23 DENYON-H R Office of Nuclear Reactor Regulation,
 Director App 22769 133 24K Fiche 50-000 84/03/23, 8403270134

T Hearing transcripts on non-antitrust matters

- B402090039 Board Notification B4-052 forwards meeting summaries containing transcripts of B40210 & 16 meetings between NRC & Transmerica Delaval, Inc (TDI) Guners Group Distribution list and:

 EISENHUT, D. G. Division of Licensing B4/03/12 PALLADING Commissioners 5pp 22708 001 24x Fiche 30-000.84/03/12,
- --B403060836 Forwards summary of B40210 meeting w/Transamerica Delaval, Inc Guners Group in Bethesda,MD re problems w/emergency diesel generators
 CARUSO,R Licensing Branch 2 B4/02/27 O'REILLY,JP NRC No Detailed Affiliation Given 6pp 22708 006 24X
 Fiche 80-000,84/03/12,8402090039
- --8403060554 Transcript of 840210 meeting w/Transamerica Delaval,inc fluners Group in Bethesda,MD re problems w/emergency diesel generators * NRC - No Detailed Affil(ation Given 84/02/10 147pp 67201 008 24X Fiche 50-000.84/03/12.8402090039
- --8403070407 Summary of B40216 meeting w/Transamerica Delaval, Inc Owners Group in Wading River,NY re program plan to establish reliability of diesel generators Agenda, meeting transcript & attendance list encl MILLER,NA A Licensing Branch 4 84/02/27 Licensing Branch 4 8pp 22708 161 24X Fiche-50-000,84/03/12.8402090039
- --8403070423 Transcript of 840216 conference in Mading River,NY re Transamerica Delaval, Inc diesel generators Pp 1-82 * Commissioners 84/02/16 84pp 22708 169 24X Fiche 50-000,84/03/12,8402070039

V Operator Examinations

8403190391 Forwards tables reflecting nuclear power plant experience for operating shift positions including current staffing experience levels & level projected at time of fuel load EDELMAN.M R Cleveland Electric Illuminating Co 84/03/09 DENTON.H R Office of Nuclear Reactor Regulation, Director 13pp 22675 282 24X Fiche 50-440.84/03/09.8403190391

DOCKET 50-443 SEABROOK NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

- 8402070003 Responds to FOIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Panel meetings Forwards App ArB & C documents.

 FELTON, J K Division of Rules and Records 83/10/31

 ROBENEADM, D M Technical Analysis Corp 19pp 22193 292 24X

 Fiche 50-000.83/10/31.8402090003
- --B402090186 Handwritten calculations & graphs re const activities & preoperational & acceptance testing Related info enc1
 * NRC No Batailed Affiliation Given Bi/09/16 dpp
 22194,191 24X Fiche 50-000,83/10/31,8402090003
- 8402090017 Board Notification 84-038 forwards RJ Mattson 840123 memo to DG Eisenhut providing status update of NRC actions re Westinghouse ECCS actuation logic EIBENHUT.D.O Division of Licensing 84/02/27 FALLADINO Commissioners 7pp 22546-007 24X Fiche:50-000,84/02/27,8402090017.
- 8403150080 Requests correction to Amend 5 to CPPR-135 & CPPR-136 to indicate that Washington Electric Cooperative. Inc never became joint owner or licensee of project RITSHER, J.A. Ropes & Gray RITSHER, J.A. Public Service Co. of New Hampshire 84703/07 Division of Licensing 2pp 22641 Q51. 24X Fiche: 50-443: 84/03/07, 8403150080

- 8403280122 Summary of 840224 meeting w/Westinghouse Owners Group in Bethesda.MD re proposed Westinghouse steam generator tube rupture generic program Attendes list & agenda encl NERSES, V Licensing Branch 3 84/03/07 Licensing Branch 3 35pp 22811 131 24X Fiche.50-000.84/03/07.8403280122
- 8402090041 Board Notification 84-050 provides Commission policy statement & proposed rulemaking on environ qualifications EISENHUT.D Q Division of Licensing 84/03/14 Atomic Safety and Licensing Board Panel 10pp 24X Fiche 50-000.84/03/14.8402090041
- 8403210097 Forwards news release re joint owners 840301 meeting, notification of A818 & syc list Estimated date for initial operation of Unit 1 is Jul 1986
 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 84/03/14 KNIGHTON, G W Licensing Branch 3 9pg 22705 090 24X Fiche 50-443,84/03/14,8403210099
- --8403210101 Advises of new interim schedule for fuel load at facility Estimated fuel load date for Units 1 & 2 are 851231 & 900731 respectively GAD,R K Ropes & Gray GAD,R K Public Service Co of New Hampshire B4/03/01 HOYT,H HARBOUR,J LUEBKE,E A Atomic Safety and Licensing Board Panel 1p 22706 099 24X Fiche 50-443,84/03/14,8403210099
- 8403210142 Requests approval to implement Paragraphs NF-3324 5,1983 edition & NF-4427,1980 edition through Winter 1982 of ASHE Section III Code for linear-type piping supports DEVINCENTIS. J Public Service Co of New Hampshire 84/03/15 KNIGHTUN,0 W Licensing Branch 3 14pp 22707 112 24X Fiche 50-443,84/03/15,8403210142
- 8403270121 Forwards operator shift experience tables, per DF Schnelt request First set of tables identifies experience levels as of B40430 Second set projects experience levels to Dec 1785, scheduled fuel lead date Shift advisors will not be used DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire B4/03/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 18pp 22775 139, 24X Fiche 50-443,84/03/20,8403270121
- 8403230061 Forwards Caseload Forecast Panel data package presented to Panel representatives during 840313 & 14 visit to plant Data package prepared in response to encl panel agenda DEVINCENTIS. J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 84/03/21 KNIGHTON, 6 W Licensing Branch 3 139pp 22726 041 24X Fiche 50-443.84/03/21.8403230061

F Security, medical, emergency & fire protection plans

- 8403060557 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by license.per 810707 Generic Ltr 81-27 W/o request, entire plan will be placed in PDR KNIGHTON.9 W Licensing Branch 3 84/02/20 HARRISON.R J Public Service Co of New Hampshire 4pp 22552 272 24X Fiche 50-443,84/02/20,8403060559
- 8402070006 Board Notification 84-034 forwards R Vollmer 840206 memo to D Eisenhut re fire research results concerning fires in electrical cabinets in control room EISENHUT, D G Division of Licensing 84/02/23 PALLADING Commissioners ip 22576 203 24% Fiche 50-000,84/02/23,8402070006
- --B4030B0316 Recommends that info re fire research results concerning fires in electrical cabinets in control room be submitted for board notification, per NRR Ofc Ltr 19. dtd 821001. Further evaluation of test data required VOLLMER, R H Division of Engineering 84/02/06 EISENHUT, D Q Division of Licensing 10pp 22576 204 24X Fiche 50-000, 84/02/23, 8402090006
- 8403090143 Summarizes B31219 meeting w/util at Region I ofc reemergency telecommunications at facility Summary enci Locations for emergency notification sys adequate for NRC emergency response MARTIN.T.T Division of Engineering & Technical Programs, 84/03/02 HARRISON,R J Public Service Co of New Hampshire 4pp 22575 062 24% Fiche 50~443,84/03/02.8403090143.
- 8403190243 Notification of 840418 workshop in King of Prussia,PA to discuss lessons learned from recent App R fire protection safe shutdown insp & topics described in IE Info Notice 84-09 Agenda for workshop encl MURLEY,T E Region i, Office of Director, 84/03/09 0'TOOLE,J p. Consolidated Edison Co of New York, Inc. 35pp 22672'062 24X Fiche 50-000.84/03/09,8403190243

ı

DOCKETED ITEMS

- 8403160236 Forwards Finalized updated App A to radiological emergency plan describing emergency classification & action Rev will be included in future amend to OL application DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Bervice Co of New Hampshire B4/03/14 KNIGHTON.G W Licensing Branch 3 ip 22661 010 24X Fiche 50-443,84/03/14,8403160256
- --8403160263 Updated App A to radiological emergency plan, consisting of emergency classification sys & emergency action levels

 * Public Service Co of New Hampshire B3/05/31 15pp
 22661 011 24X Fiche 50-443,64/03/14.8403160256

O Adjudicatory correspondence

- 8403070042 Suppl to 840224 answer to Beacoast Anti-Pollution League (SAPL) 840210 motion for reconsideration of denial of BAPL supplemental Contention 5 Certificate of Svc encl GAD,R K Public Bervice Co of New Hampshire GAD,R K Ropes & Gray 84/02/28 Atomic Safety and Licensing Board Panel 5pp. 22541 255 24X Fiche 50-443,84/02/28,8403070042
- 8403020173 New England Coalition on Nuclear Pollution Contention VII re financial qualifications of util to operate & decommission facility Certificate of Svc encl CURRAN, D New England Coalition on Nuclear Pollution CURRAN, D, JORDAN, W 8 Harmon & Weiss 84/02/27 Abomic Safety and Licensing Board Panel 15pp 22443 225 24X Fiche 50-443,84/02/29,8403020173
- 8403070020 Forwards supplemental responses to Atty General Belloti interrogatories. Related correspondence GABSIDY. B P Federal Emergency Management Agency 84/02/29 Docketing & Services Branch 2pp 22545 329 24X Fichs 50-443,84/02/29,8403070020
- --8403070022 Supplemental response to Atty General Belloti interrogatories re number of persons for which State of NH must assure medical sycs.per 10CFR50 47 W/Certificate of Byc. Related correspondence SWIREN.B J Federal Emergency Management Agency 84/02/29 9pp 22545 331 24X Fiche 50-443,84/02/29,8403070020
- 8403140051 Response to Seacoast Anti-Pollution League (SAPL) 840210 motion for reconsideration of denial of SAPL 830913 supplemental Contention 5 re util financial qualifications. Motion should be denied W/Certificate of 8vc PERLIBIR G Hearing Branch 3 84/03/01 Atomic Safety and Liferesting Board Panel 7pp 22633 112 24X Fiche 30-443,84/03/01,8403140051
- 8403070232 Informs that as result of correspondence & discussion \u03c4/
 counsel for applicant New England Coalition on Nuclear
 Pollution will withdraw Contention III 3 w/ASLB approval
 CURRAN,D Harmon & Weiss CURRAN,D New England Coalition on
 Nuclear Pollution 84/03/05 HOYT.H F, LUEBKE,E A, HARBDUR, J.
 Atomic Safety and Licensing Board Panel 1p 22538 362 24X
 Fiche: 50-443,84/03/05,8403070232
- 8403080142 Response to Seacoast Anti-Pollution League (SAPL) 840217 appeal of dental of motion to dismiss application for Unit 2.ASLAB decision not erroneous & should be affirmed SAPL motion should be denied W/Gertificate of Svc DIGNAN.T 0, QAD.R K Public Service Co of New Hampshire DIGNAN.T Q Ropes & Gray 84/03/05 Atomic Safety and Licensing Appeal Panel 1ipp 22559, 207 24X Fichs 50-443,84/03/05,8403080142.
- 8403090093 Response to New England Coalition on Nuclear Pollution (NECNP) Contention VII re financial qualification of util to operate & decommission facility NECNP Contention VII should be excluded Certificate of Svc encl DIGNAN, TO Public Bervice Co of New Hampshire DIGNAN, TO Ropes & Gray 84/03/05. Atomic Safety and Licensing Board Panel 4pp 22576:031 24X Fiche 50-443,84/03/05,8403090093
- 8403070124 Forwards util response to Beacoast Anti-Poblution League appeal of denial of motion to dismiss application for Unit 2 W/o encl Related corespondence DIONAN.T O Ropes & Gray DIGNAN.T O Public Bervice Co of New Hampshire 84/03/05 Public Document Branch ip 22574 063. 24X Fiche. 50-443.84/03/05.8403070124
- B403140025 Notice of withdrawal of appearance in proceeding ZIYBER, B, B Connecticut, State of 84/03/06 2pp 22633 215 24X Fiche: 50-443, 84/03/06, 8403140025
- 8403070107 Order accepting New England Coalition on Nuclear Pollution 840305 decision to withdraw Contention III 3 re training of unit shift supervisors HDYT-H F Atomic Safety and Licensing Board Panel 84/03/07 ip 22376

- 8403090062 Advises that time for Commission to review ALAB-758 expired Commission declined review Decision became final agency action on 840305 CHILK, 8 J Office of the Secretary of the Commission 84/03/08 Atomic Safety and Licensing Appeal Panel ip 22576 049 24X Fiche 50-443,84/03/08.8403090062
- 8403140082 Response in opposition to Seacoast Anti-Pollution League appeal of denial of motion to dismiss application Appeal failed to meet requirements for directed certification Certificate of Svc encl PATTERBON.W F Hearing Branch 3 84/03/08 Atomic Safety and Licensing Appeal Panel 20pp 22633 093 24X Fichs 50-443, 84/03/08,8403140052
- 8403190129 Memorandum & order denying motion for directed certification of ASLB 840113 memorandum & order SHOEMAKER.C J Atomic Safety and Licensing Appeal Panel 84/03/16 Seacoast Anti-Pollution League 9pp 22669 191 24X Fiche 50-443.84/03/16.8403190129
- 8403210176 Response opposing New England Coalition on Nuclear Pollution (NECNP) Contention VII re financial qualifications of util to operate & decommission facility Certificate of Svc encl PERLIB.R 0 Hearing Branch 3 DSB 013 84/03/20 Atomic Safety and Licensing Board Panel 5pp 22710 079 24X Fitchs 50-443.84/03/20.8403210196
- 84032301BO Response opposing New England Coalition Against Nuclear Power motion to file supplemental contention on state & local emergency response plans Probabilistic safety assessment summary rept encl W/Certificate of Svc QAD.R K Public Service Co of New Hampshire QAD.R K Ropus & Gray DS8 075 84/03/20 Atomic Safety and Licensing Board Panel 36pp 22743 025 24X Fiche 50-443,84/03/20,8403230180
- 8403270002 Second petition for leave to intervene in proceedings Certificate of Svc encl DHERTY.JF Doberty, JF DSB 111 84/03/22 Atomic Safety and Licensing Board Panel Bpg 22770 001 24x Fiche 50-443.84/03/22, 8403270002
- 8403260343 Order denying & rejecting Seacoast Anti-Pollution League motion for reconsideration & New England Coalition on Nuclear Pollution proffered Contention 5, respectively Served on 840326 HOYT.H F Office of the Secretary of the Commission DBB 087. 84/03/23 Seacoast Anti-Pollution League 5pp 22760 179 24) Fichs 50-443, 64/03/23, 6403260343
- B403300269 Response opposing JF Doherty B40328 second petition for leave to intervene Petition falls to show good cause for late filing Certificate of Svc encl
 GAD.R K. DIONAN.T G Public Service Co of New Hampshire GAD.R X. Ropes & Gray DSB 213 B4/03/28 Atomic Safety and Licensing Board Panel 9pp 22824 059 24X Fiche 50-443.84/03/28.8403300269
- 8403300263 Notice of change in address in svc list Certificate of Svc encl CURRAN, D Harmon & Weiss DSB 227 84/03/30 3pp 22824 068 24X Fiche 50-443,84/03/30,8403300263
- Q Inspection reports, IE Bulletins & correspondence
- 8403020282 Forwards IE Insp Repts 50-443/83-22 & 50-444/83-15 on 831206-840120 & notice of violation STAROBTECKIR Division of Project & Resident Programs 84/02/17 HARRIBON.R J Public Service Co of New Hampshire 2pp 22439 172 24X Fichs 50-443,84/02/17,8403020282
- --8403020301 Notice of Viglation from insp on 831206-840120 * Region i, Office of Director 84/02/17 2pp 22439:174 24X Fiche 50-443,84/02/17.8403020282
- --8403020308 IE Insp Repts 50-443/83-22 & 50-444/83-15 on 831206-840120 Violations noted recurrent electrical const violation which may be indicative of interface problem between AE & electrical contractor GERNE, A C . MESCOTT, H M Region 1, Office of Director OALLO, R M Division of Project & Resident Programs 84/02/09 12pp 22409 176 24% Fiche 50-443,84/02/17,8403020282
- 8403150100 Final deficiency rept & final response to IE Bulletin 83-06
 "Nonconforming Matia Supplied by Tube-Line Corp " Additesting performed Tube-Line matiacceptable Item not reportable per 100FR50 55(e)
 DEVINCENTIS.J. Yankee Atomic Electric Co DEVINCENTIS.J. Public Service Co of New Hampshire 84/02/22 MURLEY.T C Region 1.
 Office of Director 3pp 22643 159 24X Fiche 50-443,84/02/22,8403150100

- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list
 - encl JORDAN.E L Division of Emergency Proparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc. 115pp 22709 239 24% Fiche 50-000.84/02/28,8401190072
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC." Svc list encl ORACE J.N Division of OA, Safeguards & Inspection Programs (Post 830103). 84/03/02 Consolidated Edson Co of New York, Inc 130pp 22552 329 24X Fiche 50-000,84/03/02,8402090007
- 840209000B IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 122pp. 22553 098 24X Ficha 50-000.84/03/02.8402090008
- 8402070007 IE Info Notice 84-15. "Reporting of Radiological Releases"
 Byc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02. Consolidated Edison Co of New
 York, Inc 117pp 22553 217 24X Fiche 50-000.84/03/02.8402070007
- 8402070011 IE Info Notice 84-17, "Problems W/Liquid Nitragen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05. Consolidated Edison Co of New York, Inc 117pp 22553 336. 24X Fiche 50-000.84/03/05.8402090011.
- 8402070024 IE Info Notice 84-07. Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys." Syc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22635 049. 24X Fichs 50-000.84/03/07,8402070024
- 8402090028 IE-Info Notice 84-18, "Stress Corrosion Cracking in PWR Bys " Byt list encl. JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103), B4/03/07 Consolidates Edison Co of New York, Inc. 118pp 22584 186. 24X Fiche 50-000,84/03/07,8402090028
- B402070031 IE Bulletin 84-02, "Failures of QE Type HFA Relays in Use in Class IE Safety Sys " Bvc list encl DEYQUNO,R C Director's Office, Office of Inspection and Enforcement B4/03/12 Consolidated Edison Co of New York, Inc 134pp 22823-094 24X Fiche 50-000,84/03/12,8402090031
- B402070043 IE Info Notice 84-19. "Two Events Involving Unauthorized Entries into PMR Reactor Cavities " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/21 Consolidated Edison Co of New York: Inc 123pp 22823 227 24X Fiche 50-000.84/03/21.8402090043
- B402090044 IE Info Notice 84-20. "Svc Life of Relays in Sefety-Related Sys " Svc list enc!

 JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22733 GO1. 24X Fiche 50-000.84/03/21.8402070044
- R Periodic operating reports & related correspondence
- 8403020443 Forwards monthly status rept of offsite emergency preparedness for OL reviews for Jan 1984. Changes in FEMA finding dates not caused by delay due to offsite emergency planning issues
 DIRCKS.W J Office of the Executive Director for Operations
 84/02/21 PALLADINO Commissioners. 9pp 22492 083 24X
 Fiche 50-000-84/02/21.8403020443
- B Reportable occurrences. LERs & related correspondence
- 8403210075 Part 21 rept re honconformance of metal hose assemblies for ASME. Section III. Class 2 & 3 svc Status of nanconforming items skipped encl All customers notified LALIKOB, J M Titefler Corp 83/12/16. Director's Office, Office of Inspection and Enforcement. 4pp. 22704 324 24x Fiche 50-000.83/12/16.8403210095.
- B403130468 Interim deficiency rept re cracked & broken puffer piston rods in Brown Boveri Type SHK breakers Initially reported on 840119. All Unit 1 breakers will be inspected during next scheduled maint in Mar 1984.

 DEVINCENTIS.J Public Service Co of New Hampshire. 84/02/14 81AROSTECKI.R Division of Project & Resident Programs 3pp. 22619 216 24% Fiche 50-443.84/02/14.8403130468

- 8403150100 Final deficiency rept & final response to IE Bulletin 83-06
 "Nonconforming Matle Supplied by Tube-Line Corp " Add1
 testing performed Tube-Line met1 acceptable Item not
 reportable per 10CFR30. 55(e)
 DEVINCENTIS.J Yankee Atomic Electric Co. DEVINCENTIS.J Public
 Service Co of New Hampshire 84/02/22 MURLEY.T. C Region 1, .
 Office of Director 3pp 82643 159. 24X Fiche 50-443,84/02/22,
 8403180100
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines. (Rimpel NPS-4 T&T valve to close Encl ltr dtd 840203 sent to listed utils GE notified of affected units in BHR plants.

 THEROUX.R R Terry Corp 84/02/22 WODDRUFF.R W Director's Office. Office of Inspection and Enforcement 6pp 22706 327 24X Fiche 50-000.84/02/22.8403210032
- 8403060311 Part 21 final design rept re inadequecy of syc water & circulating water pump house structure Analysis completed. Repair const activities in progress.

 XREIDER: H Q United Engineers & Constructors, Inc (subs. of Raytheon Co) 84/02/28 Director's Office. Office of Inspection and Enforcement 3pp 22515-335 24X Fiche 50-443,84/02/28,
- 8403220150 Interim deficiency rept re cracked mechanical shock arrestor capstan springs supplied by Pacific Scientific. Initially reported on 831024, All 48 arrestors returned to vendor for exam & will be replaced if necessary. Next rept by 840530.

 DEVINCENTIS, J. Yankes Atomic Electric Co. DEVINCENTIS, J. Public Service Co. of New Hampshire 84/02/28, 8TAROSTECKI, R. Division of Project & Resident Programs. 2pp. 22715, 361, 24X

 Fichs. 50-443, 84/02/28, 8403220150
- 8403260233 Forwards summary list of deficiencies identified per 10CR50 55(e), Part 21 & potential generic ltr repts for comments.

 STAROBTECKIR Division of Project & Resident Programs 84/02/28, Region i, Office of Director, 7pp 22756:065 24X Fiche: 50-000.84/02/28,8403260233
- B403220005 Interim deficiency rept re isolated incident of violation of spec for assembly & erection of piping & mechanical equipment initially reported on B2110. Investigation underway. Hork will be completed by 840601.

 DEVINCENTIS.J Yankes Atomic Electric Co. DEVINCENTIS.J Public Bervice Co. of New Hampshire. B4/03/02. STARDBIECKI.R. Division of Project & Resident Programs 2pp. 22712-361. 24X Fiche: 50-443.84/03/02.8403220005.
- B403220164 Interim deficiency rept re possible jamming of Gould combination reversing motor starters. Initially reported on 840210.00uld replacing all defective combination reversing motor starters. Next rept will be provided by 840430 DEVINCENTIS, J. Yankee Atomic Electric Co DEVINCENTIS, J. Public Bervice Co. of New Hampshire, 84/03/05 STAROBTECKI, R Division of Project & Resident Programs 3pp. 22718 054 24X Fichs 50-443,84/03/05,8403220164.
- B40319024B Supplemental Part 21 rept re failed engine thrust bearing. Plugs properly installed in both units. Units free of potential defect.

 MORIARTY, J M Colt Industries, Inc. 84/03/08 KEPPLER, J. Q. Region 3, Office of Director ip 22675.045 24X Fiche. 50-000, 84/03/08, 8403190248
- 8403190374 Part 21 rept re failed engine thrust bearing. Initially reported on 800502 Field insp of Colt-Pielstick Type PC-2 dises generator sets completed using revised drawings Unit in compliance w/insp procedure & free of potential defect MORIARTY, J. M. Colt Industries, Inc. 84/03/08 KEPPLER, J. Q. Region 3, Office of Director ip. 22674.353. 24X Fiche: 50-443,84/03/08,8403190374
- B403270219 Part 21 rept re broken contect carrier in control device of 7 5 kV-15 kV.500-750 MVA.5 kV 350-3.000 & all HKV circuit breakers Initially reported on B30223 Addenda to installation & maint procedures sent to affected units.

 DUVALL.D D Brown Boveri Corp. (subs. of Brown Boveri & Co., Ltd.).

 B4/032719 Record Sarvices Branch (Document Control Desk). 5pp.

 22772:114 24X Fiche 50-000.84/03/19.8403270219.
- Y. Operator Examinations
- 8403270121 Forwards operator shift experience tables, per DF Schnell request First set of tables identifies experience levels as of 840430 Second set projects experience levels to Dec 1985, scheduled fuel load date. Shift advisors will not be used. DEVINCENTIS, J. Yankes Atomic Electric Co. DEVINCENTIS, J. Public Service Co. of New Hampshirs. 84/03/20 DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 18pp 22775; 139. 24X Fiche: 30-443, 84/03/20, 8403270121

- DOCKET 50-444 SEABROOK NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- B402070003 Responds to FDIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Panel meetings Forwards App A, B & C documents
 FELTON, J M Division of Rules and Records 83/10/31
 RDBENBAUM, D.M Technical Analysis Corp 17pp 22173 272 24X
 Fiche 50-000,83/10/31,8402070003
- --8402090186 Handwritten calculations & graphs re const activities & preoperational & acceptance testing Related info encl * NRC No Detailed Affiliation Given 81/09/16 6pp 22196 191 24X Fiche 50-000,83/10/31,8402090003
- 8402090017 Board Notification 84-038 forwards RJ Mattson 840123 memo to DG Eisenhut providing status update of NRC actions re Hestinghouse ECCB actuation logic EISENHUT.D G Division of Licensing 84/02/27. PALLADING Commissioners 7pp 22546 007 24X Fichs 50-000,84/02/27,8402090017
- B4031500B0 Requests correction to Amend 5 to CPPR-135 & CPPR-136 to indicate that Washington Electric Cooperative, Inc haver became joint owner or licensee of project RITSHER, J A Ropes & Gray RITSHER, J A Public Bervice Co of New Hampshire 84/03/07 Division of Licensing 2pp 22641.051 24X Fiche 50-443,84/03/07,8403150080
- 8403280122 Summary of 840224 meeting w/Westinghouse Comers Group in Bethesda, MD re proposed Westinghouse steam generator tube rupture generic program Attendee list & agenda ench NERBESB, V Licensing Branch 3 84/03/07 Licensing Branch 3 35pp. 22811 131 24X Fiche 50-000,84/03/07,8403280122
- 8402070041 Board Notification 84-050 provides Commission policy statement & proposed rulemaking on environ qualifications EIBENMUT,D G Division of Licensing 84/03/14. Atomic Bafety and Licensing Board Panel 10pp 24X Fiche 50-000,84/03/14,8402090041
- 8403210099 Forwards naws release re joint numers 840301 meeting, notification of ASLB & svc list Estimated date for initial operation of Unit 1 is Jul 1986 DEVINCENTIS.J. Yankse Atomic Electric Co. DEVINCENTIS.J. Public Service Co. of New Hampshire 84/03/14 KNIOHTON.O W. Licensing Branch 3 9pp 22706 090 24X Fichs 50-443.84/03/14,8403210099
- --8403210101 Advises of new interim schedule for fuel load at facility Estimated fuel load date for Units 1 & 2 are 851231 & 700731, respectively GAD.R K Ropes & Gray. GAD.R K Public Service Co of New Hampshire. 84703/01 HOYT,H , HARBOUR,J , LUEBKE,E A Atumic Safety and Licensing Board Panel 1p. 22706:099 24X Fiche 50-443,84/03/14,8403210099
- B403210142 Requests approval to implement Paragraphs NF-3324 5,1983 edition & NF-4427,1980 edition through Winter 1982 of ASME Section III Gade for linear-type piping supports DEVINCENTIS, J. Yankee Atomic Electric Co DEVINCENTIS, J. Public Bervice Co of New Hampshire B4/03/15 KNIGHTON, OW Licensing Branch 3 14pp 22707 112 24X Fiche 50-443,84/03/15,8403210142.
- BA03270121 Forwards operator shift experience tables, per DF Schnell request, First set of tables identifies experience levels as of 840430 Second set projects experience levels to Dec 1985, scheduled fuel load date. Shift advisors will not be used DEVINCENTIS, J. Yankee Atomic Electric Co DEVINCENTIS, J. Public Barvice Co. of New Hampshire 84/03/20 DENTON, H. Office of Nuclear Reactor Regulation, Director 18pp 22775 139 24X Fiche. 50-443, 84/03/20, 8403270121
- 8403230061 Forwards Caseload Forecast Panel data package presented to Panel representatives during 840313 & 14 visit to plant
 Data package prepared in response to encl panel agenda
 DEVINCENTIS, J. Yankee Atomic Electric Co. DEVINCENTIS, J. Public
 Service Co of New Hampshire. 84/03/21. KNIGHTON, O W Licensing
 Branch 3 i39pp 22726:041, 24X Fiche. 50-443, 84/03/21, 8403230061
- F Becurity, medical, emergency & fire protection plans
- 8403060539 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licemsee, per 810709 Generic Ltr 81-27 W/o request, entire plan will be placed in PDR. KNIGHTON.0 W. Licensing Branch 3 84/02/20. HARRISON.R J Public Service Co. of New Hampshire. App 22552-272 24X Fiche. 50-443,84/02/20,8403060559

- 8402090006 Board Notification 84-034 forwards R Vollmer 840206 memo to D Eisenhut re fire research results concerning fires in electrical cabinets in control room EISENHUT.D G Division of Licensing 84/02/23 PALLADINO Commissioners ip 22576 203 24X Fiche 50-000.84/02/23, 84002090006
- --8403080316 Recommends that info re fire research results concerning fires in electrical cabinets in control roum be submitted for board notification, per NRR OPF Ltr 17,0td 821001 Further evaluation of test data required VOLLMER.R H Division of Engineering 84/02/06 EISENHUT,D 6 Division of Licensing 10pp 22076 204 24X Fithe 50-000.84/02/23,8402070006
- 8403090143 Summarizes 831219 meeting w/util at Region I ofc re emergency telecommunications at facility Summary encl Locations for emergency notification sys adequate for NRC emergency response MARTIN.T T Division of Engineering & Technical Programs 84/03/02 HARRISON.R J Public Service Co of New Hampshire. 4pp 22575 062 24X Fiche 50-443.84/03/02.8403090143
- B403190243 Natification of B40418 workshop in King of Prussia,PA to discuss lessons learned from recent App R fire protection safe shutdown insp & topict described in IE Info Notice B4-09 Agenda for workshop enci MURLEY,T E Region i. Office of Director B4/03/09 D'TOOLE,J D Consolidated Edison Co of New York Inc 35pp 22472 062 24X Fiche 50-000.84/03/09.8403190243
- 8403160256 Forwards finalized updated App A to radiological emergency plan describing emergency classification & action Rev will be included in future amend to OL application DEVINCENTIS. J Yankee Atomic Electric Co DEVINCENTIS, J Public Bervice Co of New Hampshire 84/03/14 KNIGHTON. 6 W Licensing Branch 3 1p 22661 010 24X Fiche 50-443.84/03/14.8403160256
- --8403160263 Updated App A to radiological emergency plan, consisting of emergency classification sys & emergency action levels * Public Service Ca of New Hampshire 83/05/31 15pp 22661 011 24x Fiche 50-443,84/03/14,8403160256
- Q Adjudicatory correspondence
- 8403070042 Suppl to 840224 answer to Seacoast Anti-Pollution League (SAPL) 840210 motion for reconsideration of denial of SAPL supplemental Contention 5 Certificate of Syc encl GAD.R.K Public Service Co of New Hampshire OAD.R.K Ropas & Gray 84/02/28 Atomic Safety and Licensing Board Panel 5pp 22541 255 24X Fiche 50-443,84/02/28,8403070042
- 8403020173 New England Coalition on Nuclear Pollution Contention VII re financial qualifications of util to operate & decommission facility Certificate of Svc encl CURRAN.D New England Coalition on Nuclear Pollution CURRAN,D, JORDAN,W S Harmon & Weiss 84/02/29 Atomic Safety and Licensing Board Panel 15pp 22443 225 24X Fiche 50-443,84/02/29,8403020173
- B403070020 Forwards supplemental responses to Atty General Helloti interrogatories Related correspondence GABSIDY,B P Federal Emergency Management Agency 84/02/29 Docketing & Services Branch. 2pp 22345 327 24x Fiche 50-443,84/02/29,8403070020
- --8403070022 Supplemental response to Atty General Belioti
 interrogatories re number of persons for which State of NH
 must assure medical svcs, per 100FR50 47 W/Certificate of
 Svc Related correspondence
 BWIREN.B J Federal Emergency Management Agency 84/02/29 9pp
 22545;331 24X Ficha 50~443,84/02/29,8403070020
- B40314003; Response to Beaccast Anti-Pollution League (SAPL) 840210 motion for reconsideration of denial of SAPL 830913 supplemental Contention 5 re util financial qualifications Motion should be denied W/Certificate of Svc. PERLIB.R 0. Hearing Branch 3 84/03/01 Atomic Bafety and Licensing Board Panel 7pp 22633 112 24X Fiche: 50-443,84/03/01.8403140051.
- B403070232 Informs that as result of correspondence & discussion w/coursel for applicant. New England Coalition on Nuclear Pollution will utthdraw Contention III 3 w/ASLB approval CURRAN. D Harmon & Weiss CURRAN. D New England Coalition on Nuclear Pollution 84/03/05 HOYT. HF, LUEBKE. E, A, HARBOUR, J Atomic Safety and Licensing Board Panel. ip 22538 342 24X Fiche 50-443.84/03/05.8403070232

1080142 Response to Seacoast Anti-Pollution League (SAPL) 840217 speal of denial of motion to dismiss application for Unit ASLAB decision not erroneous & should be affirmed SAPL tion should be denied M/Certificate of Svc IONAN. TO G. GADR X Public SErvice Co of New Hampshire QNAN. TO Ropes & Gray 84/03/05 Atomic Safety and Licensing speal Pane) 11pp 22559 207 24X Fiche 50-443,84/03/05,103080142

1

- 1090093 Response to New England Combition on Nuclear Pollution (ECNP) Contention VII re financial qualification of util operate & decommission facility NECNP Contention VII ould be excluded Certificate of Svc encl ONAN, TO Public Service Co of New Hampshire DIGNAN, TO Ropes Oray 84/03/05 Atomic Safety and Licensing Board Panel 4pp 1976 031 24% Fiche 50-443,84/03/05,8403090093
- 090124 Forwards util response to Beacoast Anti-Pollution League peal of denial of motion to dismiss application for Unit W/o encl Related corespondence GNAN, T G Ropes & Gray DIGNAN, T G Public Service Co of New myshire 84/03/05 Public Document Branch in 22576 063 X Fiche 50-443,84/03/05,8403090124
- 140025 Notice of withdrawal of appearance in proceeding. TSER.B S Connecticut. State of B4/03/06 2pp 22633 215. 24X che 50-443,84/03/06.8403140025
- Oponor Order accepting New England Coalition on Nuclear Pollution 1305 decision to withdraw Contention III 3 re training of t shift supervisors "T.H F Atomic Safety and Licensing Board Panel 84/03/07 1p 176 080 24X Fiche 50-443,84/03/07,8403090107
- 190062 Advises that time for Commission to review ALAB-758 sired Commission decilined review Decision became final new action on 840305 LK.S J Office of the Secretary of the Commission 84/03/08 mic Safety and Licensing Appeal Panel 1p 22576 049 24% has 30-443-84/03/08.8403090062
- 40052 Response in apposition to Seacoast Anti-Poliution League eal of denial of motion to dismiss application Appeal led to meet requirements for directed certification tificate of Svc encl
 TERSON W F Hearing Branch 3 84/03/08 Atomic Safety and ensing Appeal Panel 20pp 22633 093 24X Fithe 50-443, 03/08.8403140052
- 90129 Memorandum & order denying motion for directed certification ASLB 840113 memorandum & order HARRER C J Atomic Safety and Licensing Appeal Panel 84/03/16 sacoast Anti-Pollution League 9pp 22669 191 24X to 50-443.84/03/16.8403190129
- l0176 Response opposing New England Coalition on Nuclear Pollution NP) Contention VII re financial qualifications of util sperate & decommission facility Certificate of Svc uncl 15.R & Hearing Branch 3 D5B 013 84/03/20 Atomic Safety Licensing Board Panel 5pp 22710 077 24X s 50-443.84/03/20.8403210196
- OldO Response apposing New England Coalition Against Nuclear, motion to file supplemental contention on state & 1 emergency response plans Probabilistic safety sement summary rept enci W/Certificate of Syc K Public Service Co of New Hampshire GAD.R.K Ropes & DSB 075 B4/03/20 Atomic Safety and Licensing Board 1 36pp 22743 025 24x Fiche 50-443.84/03/20,8403230180.
- 1002 Second petition for leave to intervene in proceedings. ificate of Svc entl
 TY, U.F. Doherty, J.F. DSG 111 84/03/22 Atomic Safety and bring Board Panet 8pp 22770 001 24% Fiche 50-443,84/03/22,270002
-)343 Order denying & rejecting Seacoast Anti-Pollution League in for reconsideration & New England Coalition on Par Pollution proffered Contention 5, respectively Served 0326
- -ar rolletion provided Secretary of the Commission DSB 087 HF Office of the Secretary of the Commission DSB 087 1/23, Semcoast Anti-Pollution League 5pp 22760·179 24X .50-443.84/03/23,8403260343
- 2269 Response opposing JF Doherty B40328 second petition for to intervene Fetition fails to show good cause for filing Certificate of Svc encl. K., DIGNAN,T O Public Service Co of New Hampshire GAD,R K s & Gray D8B 213 B4/03/28 Atomic Safety and Licensing Panel 9pp 22824 059 24X Fichs 50-445, 84/03/28, 8403300269

- 8403300019 Order denying State of CT Div of Consumer Counsel petition to intervent in CP renewal proceeding & declaring Seaccast Anti-Pollution League motion for joinder most Served on 840329 CHILK,8 J Office of the Secretary of the Commission DSB 208 84/03/29 Seaccast Anti-Pollution League opp 22822.165 24X Fiche 80-444.84/03/29.8403300019
- 8403300263 Notice of change in address in svc list Certificate of Svc encl CURRAN-D Harmon & Heiss DSB 227 84/03/30 3pp 22824*068 24X Fiche 50-443:84/03/30:8403300263
- Q Inspection reports, IE Bulletins & correspondence
- 8403020282 Forwards IE Insp Repts 50-443/83-22 & 50-444/83-15 on B31206-840120 & notice of violation BTAROBIECKI, R Division of Project & Resident Programs B4/02/17. HARRIEGON, R J Public Service Co of New Hampshire, 2pp 22439 172 24X Fichs 50-443,84/02/17,8403020282
- --B403020308 IE Insp Repts 50-443/83-22 & 50-444/83-15 on 831206-840120 Violations noted recurrent electrical const violation which may be indicative of interface problem between AE & electrical contractor CERNEIA C . WESCOTT. H M Region 1. Office of Director. QALLO.R. H Division of Project & Resident Programs 84/02/09 12pp 22437 176 24X Fiche 50-443,84/02/17,8403020282
- 8403150100 Final deficiency rept & final response to IE Bulletin 83-06 "Nonconforming Matls Supplied by Tube-Line Corp." Additesting performed Tube-Line matl acceptable Item not reportable per 100FR50 55(a)
 DEVINCENTIS.J Yankee Atomic Electric Co 84/02/22. MURLEY, T C Region 1. Office of Director 3pp 22643 159 24X
 Fiche 50-443.84/02/22,8403150100
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp. 22909-239 24X Fiche 50-000,84/02/28,8401190072
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE, J N Division of GA: Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Ficher 50-000;84/03/02,8402090007.
- 8402090008 IE info Notice 84~16, "Failure of Automatic Sprinkler Siys Valves to Operate " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Rasponee (Post 830103) 84/03/02 Consolidated Edison Co of New York: Inc 122pp 22553 098 24X Fiche 50~000,84/03/02,8402090008.
- 8402070007 IE Info Notice 84-15, "Reporting of Radiological Releases "
 Svc list encl
 JDRDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc 117pp 22553 217 24X Fiche 50-000,84/03/02,8402090009.
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl. JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co. of New York, Inc. 117pp. 22553 336 24X Fiche 50-000.84/03/05, 8402099011
- 8402090024 IE Info Notice 84-09, Rev 1, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys." Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York. Inc 118pp 22635 049 24X Fichs; 50-000, 84/03/07, 8402099024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PMR Sys " Syc list enc! JORDAN,E L Division of Emergency Preparadness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 184 24X Fichs 50-000,84/03/07,8402090028
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Sefety Sys " Byc list encl.
 DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co. of New York, Inc 134pp 22823; 094 24% Fiche 50-000.84/03/12.8402090031
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JORDAN, E. L. Division of Emergency Preparadness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 123pp 22823 229 24X Fiche, 50-000, 84/03/21, 8402090043

- 8402070044 IE Info Notice 84-20. "Syc Life of Relays in Safety-Related
 - 102070044 IE info moses b. ... Bys " Byc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/21 Consolidated Edison Co of New York, Inc. 135pp 22933 001 24% Fiche 50-000,84/03/21,8402090044
- B Reportable occurrences. LERs & related correspondence
- 8403130468 Interim deficiency rept re cracked & broken puffer piston rods in Brown Boveri Type 5HK breakers Initially reported on 840119 All Unit I breakers will be inspected during next scheduled maint in Mar 1984
 DEVINCENTIS.J Public Service Co of New Hampshire 84/02/14
 STARDSTECKIR Division of Project & Resident Programs. 3pp 22613 216 24X Fiche 50-443.84/02/14.8403130468
- 8403180100 Final deficiency rept & final response to IE Bulletin 83-06
 "Nonconforming Matis Supplied by Tube-Line Corp " Add1
 testing performed Tube-Line matl acceptable Item not
 reportable per 10GFR80 55(e)
 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public reportable per 10GFRSU 53(e)
 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Publi
 Service Co. of New Hampshire 84/02/22 MURLEY, T C Region 1.
 Dffice of Director 3pp 22643 159 24X Fiche 50-443,84/02/22. B403150100
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines. Gimpel NPS-4 T&T valve, to close Encl ltr dtd 840203 sent to listed utils GE notified of affected units in BHR plants.
 THEROUX R R Terry Corp 84/02/22 WDODRUFI
 Office, Office of Inspection and Enforcement
 Fichs 50-000,84/02/22,8403210032 84/02/22 WDGDRUFF, R. W Director's 6pp 22706 327 24x
- 8403060311 Part 21 final design rept re inadequacy of svc water & circulating water pump house structure Analysis completed Repair const activities in progress KREIDER, H Q United Engineers & Constructors, Inc (subs of Raytheon Co) 84/02/28 Director's Office, Office of Inspection and Enforcement 3pp 22515 335 24X Fiche 50-443,84/02/28, 8403060311.
- 8403220150 Interim deficiency rept to cracked mechanical shock arrestor capatam springs supplied by Pacific Scientific Initially reported on 831024 All 48 arrestors returned to vendor for exam & will be replaced if nucessary Next rept by 840330 DEVINCENTIS. J Yankee Atomic Electric Go DEVINCENTIS. J Public Service Co of New Hampshire 84/02/28 STAROSTECKI, R Division of Project & Resident Programs 2pp 22715 361 24X Fiche 50-443,84/02/28,8403220150
- 3403240233 Forwards summary list of deficiencies identified per 10CFR50 55(e).Part 21 & potential generic ltr repts for
 - STARDSTECKI,R Division of Project & Resident Programs. 84/02/28 Region to Office of Director. 7pp 22756.065 24% Fiche 50-000.84/02/28.8403260233
- H03220005 Interim deficiency rept re isolated incident of violation of spec for assembly & srection of piping & mechanical equipment Initially reported on 82110 Investigation underway Work will be completed by 840601 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire. 84/03/02 STARDSTECKI, R. Division of Project & Resident Programs 2pp 22712-361 24X Fiche 50-443,84/03/02,8403220005
- 403220i64 Interim deficiency rept re possible jamming of Gould combination reversing motor starters Initially reported on 8402i0 Gould replacing all defective combination reversing motor starters Next rept will be provided by 840430 DEVINCENTIS, J Yankse Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 84/03/05 BTARDSTECKI, R Division of Project & Resident Programs. 3pp 22718 054 24X Fiche: 50-443,84/03/05.8403220164
- 403270219 Part 21 rept re broken contect carrier in control device of 7.5 kV-15 kV,500-750 MVA,5 kV 350-3,000 & all HKV circuit breakers, Initially reported on 830223 Addenda to installation & maint procedures sent to affected units DUVALL.D.D. Brown Boveri Corp (subs of Brown Boveri & Co , Ltd) 84/03/19 Record Bervices Branch (Document Control Desk) 5pp 22772:114. 24X Fichs 50-000,84/03/19,8403270219
- Hearing transcripts on non-antitrust matters
- 103270335 Transcript of Commission B40323 affirmation/discussion & vote in Washington, DC re request for denial of renewal of Beabrook Unit 2 CP & BECY-84-48 concerning review of ALAB-724 in matter of Mat Ed Pp 1-3 ** Commissioners. B4/03/23 6pp. 22787:356 24X Fiche. 50-000:84/03/23,8403270335

- V Operator Examinations
- 8403270121 Forwards operator shift experience tables, per DF Schnell request First set of tables identifies experience levels as of 840430 Second set projects experience levels to Dec 1985, scheduled fuel load date Shift advisors will not be used DEVINCENTIS, J Yantes Atomic Electric Co 84/03/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 18pp 22775 139 24X Fiche 50-443,84/03/20,8403270121
- DOCKET 50-445 COMANCHE PEAK STEAM ELECTRIC STA . UNIT 1 A Application/construction stage documents & correspondence
- B401120425 Forwards Amend 7 to CPPR-126 & CPPR-127, safety evaluation & notice of issuance & availability Amend reflects change in ownership of facilities
 EISENHUT, D G Division of Licensing 83/12/30 GARY, R J Texas ownership of facilities
 EISENHUT, D G Division of Licensing 83/12/30 QARY, R J Tex.
 Utilities Electric Co (formerly Texas Utilities Generating Co)
 3pp R2210 343 24X Fiche 50-445,83/12/30,8401120425
- --8401120428 Amend 7 to CPPR-126 & CPPR-127, reflecting change in NALEUMED AMEND / to CPPR-128 & CPPR-127, reflecting change in dumbriship of facilities
 EISENRUT, D & Division of Licensing 83/12/30 4pp 21804 341 24X Fiche 50-445,83/12/30,8401120425
- --8401120433 Gafety evaluation supporting Amend 7 to CPPR-124 & CPPR-127
 * Office of Nuclear Reactor Regulation, Director 83/12/29 3pp
 21804 338 24% Fiche 50-445,83/12/30,8401120425
- ~~BA01120437 Notice of issuance & availability of Amend 7 to CPPR-126 & CPPR-127 CMMK-12/ YOUNGBLOOD, B J Licensing Branch 1 83/12/27 3pp 21804 348 24% Fithe 50-445,83/12/30,8401120425
- 8403060155 Requests exemption from provisions of GDC 4 requiring protection of structure.sys & components against certain dynamic effects associated w/postulated breaks in RCS primary loop.per Generic Ltr B4-04 OARY,R J Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/02/17 YOUNGBLOOD.B J Licensing Branch i 4pp 22513 351 24X Fichs 30-445.84/02/17.8403060155
- 840302014B Forwards, for review, draft environ protection plan proposed OGGETTED FORWARDS: FOR TWEEN, GRAFT STORM PROPOSED FOR APP & OF TAPP & TO PER OF THE PROPOSED FOR THE PROPOS
- --B403020152 Environ protection plan (nonradiological) for facility. App B to OLs.draft

 * NRC - No Detailed Affiliation Given 84/02/21 15pp
 22491 159 24% Fiche.50-445.84/02/21.8403020148
- 8402090017 Board Notification 84-038 forwards RJ Mattson 840123 memo 10209001/ Moard Notification 84-030 forwards No matten 84012 to DO Eisenhut providing status update of NRC actions re Westinghouse ECCS actuation logic EIBENHUT, D G Division of Licensing 84/02/27 PALLADINO Commissioners 7pp 22546 007 24x Fichs 50-000,84/02/27,8402090017
- 8403050273 Requests provision of alternative surveillance to replace requirement presently in Tech Specs re turbine overspeed protection Proposed alternative maint, calibr & testing program should assure that protection sus operable YOUNGBLOOD, B. J. Licensing Branch 1 84/02/27 GARY, R. J. Texas Utilities Electric Co. (formerly Texas Utilities Chectric Co. (formerly Texas Utilities Chectric Co.)
 4pp. 22501 109 24X Fiche 50-445,84/02/29,8403050273
- 8403060299 Informs NRC that Nuclear Util Task Action Committee completed final draft of rept defining appropriate vendor interface program discussed in Generic Ltr 83-28 Final rept scheduled to be released by Apr 1984
 SCHMIDT, N C Texas Utilities Electric Co (formerly Texas Utilities Generating Ca.) 84/02/29 EISENHUT, D G Office of Nuclear Reactor Regulation, Director ip 22515 362 24X Fiche 50-445,84/02/29, 8403060299
- 8403070308 Forwards request for add1 info re leak-before-break analysis & fracture toughness of piping matls under thermal aging conditions Submittal date requested within 5 days of ltr receipt
 receipt
 YOUNGBLOOD, D J Licensing Branch I 84/03/02 GARY, R J Texa
 Utilities Electric Co. (formerly Texas Utilities Generating Co.)
 4pp. 22584 338. 24% Fiche 50-445, 84/03/02, 8403070308
- B403160079 Forwards Buppl 1 to "Human Factors Control Room Design Review," final rept GARY.R J Texas Utilities Electric Co (formerly Texas Utilities Generating Co) B4/03/08 Y0UNOBLOOD.B J Licensing Branch 1 1p 22654 001 24X Fiche 50-445.84/03/08.8403160079

- --8403160083 Suppl 1 to "Human Factors Control Room Design Review." final reps + Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/03/31 122pp 22654.002 24X Fiche 50-445.84/03/08.8403160079
- 8402090041 Board Notification 84-030 provides Commission policy statement & proposed rulemaking on environ qualifications EISENHUT, D C Division of Licensing 84/03/14 Atomic Safety and Licensing Board Panel 10pp 24X Fiche 50-000,84/03/14,8402090041
- 8403300249 Notification of Caseload Forecast Team 840319-21 meetings & site visit w/util in Arlington & Glen Rose TX to discuss const completion schedule Agenda encl
 BURMELL.S B Licensing Branch 1 84/03/15 YOUNGBLOOD B J
 Licensing Branch 1 9pp 22845 022 24X Fiche 50-445.84/03/15.
 8403300249
- E NRC Safety Evaluation Report (BER), suppls & correspondence
- 8403080179 Fourth partial response to FOIA request for six categories of documents re-facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of addl documents subj to request continuing
 FELTON, J.M. Division of Rules and Records 84/02/13 ANDERSON, S. T. Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000:84/02/13,8403080179
- ~-B005130793 Provides status of SER inputs & acceptance reviews for OL & CP applications Schedule should be met BURKE.W C Effluent Treatment Systems Branch 80/02/06 KREGER.W E Assistant Director for Site Analysis 1p 22583 235 24X Fiche 50-000.84/02/13.8403080179
- 8403020289 Forwards resolution of SER Confirmatory Issue ii re util 830218 & 0316 submittals concerning TMI Action Items I C 2 & YOUNGBLOOD, B. J. Licensing Branch 1 84/02/21 QARY, R. J. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.) Spp. 22492 241 24% Fiche 50-445,84/02/21,8403020289
- 8403260069 Forwards evaluation of 830718 request for deletion of steam electric station license condition re low-pressure turbine disc insp NRC maintains position in SER (NRREG-0797) that insp must be conducted YOUNGHLOOD, B Licensing Branch 1 84/02/28 GARY.R.J Terms Utilities Electric Co (formerly Terms Utilities Generating Co) 2pp 22763 235 24X Fiche 50-445,84/02/28.8403260069
- 8403140288 Forwards SSER re TMI Action Plan Items I C 1 & I C 8 of SER Confirmatory Issue 3 concerning guidance for evaluation & development of procedures for transients & accidents YOUNGBLOOD, B J. Licensing Branch 1 84/03/06 GARY, R. J. Texa Utilities Generating Co 1 App. 22636 312 24X Fiche 50-445,84/03/06,8403140288
- 8403140293 Provides clerification of NRC favorable findings re SER Confirmatory Issue 11 for TMI Action Plan Item I G i Util should either commit to perform natural circulation boron mixing test or ref boron mixing test at Diablo Canyon YOUNGBLOOD, B J Licensing Branch 1 84/03/06. GARY, R J Teras VOUNGELOOD, B. J. Licensing Branch 1 84/03/06. GARY, R. J. Tara Utilities Electric Co. (formerly Teras Utilities Generating Co.) 3pp 22635 333 24X Ficha 50-445,84/03/06,8403140293
- 8403270345 Requests schedule for responding to SER Dutstanding Issue 3 re environ qualification of safety-related mechanical equipment in harsh environs & Issue 4 re alternate safe YOUNGBLOOD B J Licensing Branch 1 84/03/13. GARY,R J Texa Utilities Electric Co (formerly Texas Utilities Generating Co) App 22787 352 24X Fiche 50-445,84/03/13,8403270345
- F Security, medical, emergency & fire protection plans
- 8403130116 Forwards proposed guidelines & Rev i to proposed objectives TOUSIONIE FORWARDS PROPOSED GUIDELINES & Rev 1 to proposed objective for 1983 emergency preparedness field exercise, for revisew Exercise scheduled for 831214 Comments requested by 830923 JONES.R A Texas Utilities Electric Co (formarly Texas Utilities Glectric Co) (formarly Texas Utilities Glectric Co) 93/09/13 AMDSEN.O L Region 4. Office of Director 2pp 22601-301, 24X Fiche 50-445, 83/09/13, 8403130116

- --8403130126 Proposed guidelines for 1983 emergency preparedness field exercise scheduled for B31214 * Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 83/09/13 3pp 22601 303 24X Fiche 50-445,83/09/13,8403130116
- --8403130136 Rev 1 to proposed objectives for 1983 emergency preparedness field exercise

 * Teras Utilities Electric Co (formerly Taxas Utilities

 Oenerating Co) 83/04/12 14pp 22601 306 24X

 Ficha 30-445,83/09/13.8403130116
- 8403130313 Forwards "NRC Emergency Preparedness Appraisal Items Status Tracking Rept." to aid NRC in preparations for upcoming appraisal Emergency preparadness planning project organization chart & list of responsibilities also encl JONESR A Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 83/09/13 MADSEN, 2 L. Region 4, Office of Director 6pp 22605 095 24X Fiche 50-445,83/09/13,8403130313
- --B403130317 "NRC Emergency Preparedness Appraisal Item Status Tracking * Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 83/09/11 79pp 22605 101 24X Fiche 50-445,83/09/13,8403130313
- 8403260206 Forwards IE Insp Rept 50-445/83-43 on 831114-18 No violations or deviations noted

 JOHNSON, E H Region 4, Office of Director 84/02/03 QARY, R. J

 Teras Utilities Electric Co (formorly Texas Utilities Generating

 Co) 2pp 22735 223 24x Fiche 50-445,84/02/03,8403260206
- --8403260214 IE Insp Rept 50-445/83-43 on 831114-18 No violations or deviations noted Major areas inspected protected area;
 physical barriers - vital area testing & maint & security
 sys power supply Details withheld (ref 10CFR73 21).
 CALDHELL,R A, KELLY,J, HUNNICUTT,D M Region 4, Office of
 Director 84/02/02 ip 22756 225 24X Fiche 50-445,84/02/03.
 84003260206
- 8403030146 Submits scenario for providing info re emergency preparadness exercise COLLINS.JT Region 4. Office of Director 84/02/09 QARY,R J Texas Utilities Senarating Co) 2pp 22487 312 24X Ficha 50-445,84/02/09,8403050146.
- 8403130442 Forwards IE Insp Rept 50-445/83-51 on 831201-840131 No deviations or violations identified UPRNSON.E H Region 4. Office of Director. 84/02/22 ORRY.R Texas Utilities Electric Co (formerly Texas Utilities Cenerati GARY.R J
- --8403130453 IE Insp Rept 50-445/83-51 on 831201-840131 No violations or deviations identified Major areas inspected initial startup procedures review fuel receipt emergency drill & IE bulletin followup TOTION TO THE PROPERTY OF T
- 8402090006 Board Notification 84-034 forwards R Vollmer 840206 memo to Octorous source notification of the source in values of the source of th
- --B4030B0316 Recommends that info re fire research results concerning fires in electrical cabinets in control room be submitted for board notification, per NRR OFC Ltr 19: dtd 821001 Further evaluation of tast data required VOLLKER.R H Division of Engineering 84/02/06. EISENHUT.D Q Division of Licensing 10pp 22576 204 24X Fiche 50-000,84/02/23,8402090006

O Adjudicatory correspondence

- 8403070177 Motion re summary of cross-examination areas supplied to CVONA on 840222 Applicants have used thin wall pipe & many instances of min pipe wall I violations exist W/M Walsh affidavit Related corespondence ELLISJ Citizens Association for Sound Energy 84/02/27. Atc Safety and Licensing Board Panel 4pp 22841-326, 24X Fiche 50-445,84/02/27,8403070177 Atomic
- ~-8403070181 Affidavit of W Walsh re thin wall pipe Pipe fittings larger than nominal wall thickness assumed by piping designars will increase thermal expansion loads on piping supports & HALSHIM Citizens Association for Sound Energy 84/02/28 22541 330 24X Fiche 50-445,84/02/29,8403070177, 4рр

- --8403070102 Forwards M Walsh affidevit Certificate of 8vc encl ELLIB, J Citizens Association for Sound Energy 84/02/29 Docketing & Services Branch 3pp 22541 352 24X Fichs 50-445,84/02/29,8403070177
- 8403070191 Notifies that no conflict of interest exists in dual representation of Brown & Root & Hutchinson re investigation of CYGNA matter
 CHARNOFF, G. Shaw, Pittman, Potts & Trowbridge CHARNOFF, G. Texa
 Utilities Electric Co. (formerly Texas Utilities Generating Co.)
 84/03/01 BLOCH, P. Atomic Safety and Licensing Board Panel 3pp
 22347 273 24X Fiche 50-449,84/03/01,8403070191
- 8403090126 Notice of appearance in proceeding Certificate of Svc encl PIGDTT, D Cygna Energy Services PIGOTT, D Orrick, Herrington & Subcliffe 84/03/05 4pp 22575 341 24X Fiche 50-445,84/03/05, 8403090126
- 8403070128 Answer urging rejection of util 840203 plan to respond to ASL8 memorandum & order re GA for design ASL8 should require 190% reinspidesign verification & mgt audit Certificate of 8vc encl.

 Fil.18.J Citizens Association for Sound Energy 84/03/05 Atom

SVC encl.

ELLIB, J Citizens Association for Sound Energy 84/03/05 Atomi

Safety and Licensing Board Panel. 19pp 22571 021 24X

Fiche. 50-445.84/03/05.8403090128.

- 8403070079 Memorandum requesting Ofc of Investigations file target dates for completion & release of rept re facility investigations & policy for filing completed repts w/ASLB subj to protective order BLOCH.P B. Atomic Bafety and Licensing Board Panel 84/03/08 ip 22576.001 24X Fiche 50-445,84/03/08.8403070097
- 8403140055 Comments on util plan to respond to 840203 memorandum & order re GA for design Plan supported in part Certificate of Bvc encl HIZUND, 0 S Hearing Branch 1 84/03/09. 17pp 22634 165 24X Fiche 50-445,84/03/09,8403140055
- 8403140034 Forwards response to 840305 comments on generic problems & cross-examination questions Exhibits 920-925,906 & 891-901 encl Certificate of Svc encl.Related correspondence ELLIB.J. Citizens Association for Sound Energy 84/03/10 HILLIAMS.N H Cygna Energy Services 25pp 22633 021 24X Fiche: 50-445,84/03/10,8403140034
- B403140013 Confirms agreement to preserve any matls informally requested on discovery re electrical inspectors Related correspondence HORIN.W A Bishop, Liberman, Cook, Purcell & Reynolds HORIN.W A Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.) 84/03/12 BLOCH.P B, MCCOLLOM.K A, JORDAN.W H. Atomic Bafsty and Licensing Board Panel ip 22633 225 24X Fichs: 50-445, 84/03/12, 8403140013
- 8403140020 Answer to Citizens Assoc for Sound Energy (CASE) 840229 motion re cross-examination areas supplied to CYONA CASE matters inappropriate & irrelevant in context of CYCNA rept. W/Certificate of Svc.Related correspondence REVNOLDS, N.S., HORIN, W.A. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.) REYNOLDS, N.S. Bishop, Liberman. Cook, Purcell & Reynolds. 84/03/12. Atomic Safety and Licensing Board Panel 11pp. 22633 290 24X Fiche. 50-445,84/03/12, Beant 40020.
- 8403190024 Seventeenth set of interrogatories & requests to produce to applicants Certificate of Svc snc1 Related correspondence ELLIS-J. Citizens Association for Sound Energy. 84/03/12. Texas Utilities Electric Co. (Formerly Texas Utilities Generating Co.) 9pp. 22666-076 24X Ficher 50~445.84/03/12.8403190024
- B403190032 Motion for discovery re T-shirt incident, Incident falls under heading of new & significant info re intimidation matters & desmed discoverable Certificate of Svc encl Related correspondence ELLIB.J. Citizens Association for Sound Energy B4/03/12 Atomic Safety and Licensing Board Panel 9pp. 22666 067. 24X Fichs. 50-445.84/03/12,8403190032
- B403150032 Suppl to applicant 840203 plan to respond to memorandum & order re GA for design, discussing ABLB 840224 comments on Walsh/Doyle issues re compliance w/Criteria I & XVI. Certificats of Bvc encl Related correspondence REYNOLDB, N B Texas Utilities Electric Co (formerly Texas Utilities Gamerating Co.). REYNOLDB, N S. Bishop, Liberman, Cook, Purcell & Reynolds 84/03/13 12pp 22643 275. 24X Fiths. 50-445, 84/03/13, 8403150032

- B403190006 Informs that Insp Rept B3-52, particularly app, Page 6, Items B & C re allegations of undue pressure & restriction & threatening w/firing will be used for cross-examination during hearing Cartificate of 8 for encl
 ELLIG.J Citizens Association for Sound Energy B4/03/13
 BLOCH.P B , MCCOLLOM.K A , JORDAN.W H Atomic Safety and Licensing Board Panel 9pp 22664 352 24X Fiche 50-445.84/03/13,8403190006
- 8403190148 Forwards Investigation Repts 4-83-001 & 4-83-013 dtd 830824 & 1103 respectively Complete & redacted versions encl TREBY-6 A Hearing Branch I 84/03/13 BLOCH P B , JORDAN, W H , MCCOLLOM, K A Atomic Safety and Licensing Board Panel 200pp 22667-001 24X Fiche 50-445,84/03/13.8403190148
- B403190111 Notice of appearance in proceeding Certificate of Svc encl BACHMANN.R 0 Hearing Branch 1 84/03/14 3pp 22666 263 24X Fiche. 50-445, 84/03/14, 8403190111
- 8403190118 Forwards NRC Insp Repts 99700330/84-01 & 50-445/83-52 of CYONA Energy Svcs OA program used during Unit 1 independent assessment program No application to withhold rept received TREBY, 8 A Hearing Branch 1 84/03/14 8LOCH, P B , JORDAN, W H , MCCOLLOM, K A Atomic Safety and Licensing Board Panel 23pp 22666 273 24X Fichs 50-445,84/03/14,8403190118
- 8403200026 Eighteenth set of interrogatories & requests to produce to applicants re issue of intimidation.harassment & threatening of GC inspectors & other employees Certificate of Svc encl. Related correspondence ELLIG.J Citizens Association for Sound Energy 84/03/14 Texast Utilities Electric Co (formerly Texas Utilities Coencrating Co) 5pp 22699 228 24% Fiche 50-445.84/03/14.8403200026
- 8403200126 Nineteenth set of interrogatories & requests to produce to applicant Certificate of Svc encl Related correspondence ELLI9, J Citizens Association for Sound Energy 84/03/14. Ilpp 22697 067 24X Fiche 50-445,84/03/14,8403200126
- 8403170002 Memorandum clarifying open listed issues re GA program BLDCH,PB: JDRDAN,H H; MCCDLLDM,K A Atomic Safety and Licensing Board Panel 84/03/15 21pp 22664 326 24X Fithe 50-445, 84/03/15,8403170002
- 8403190028 Memorandum ordering Ofc of Investigations to file-by B40329, affidavits responsive to ASLP concerns re observation of interviewees Applicants should file affidavits stating' results of investigation by 840411
 BLOCH.P B Atomic Safety and Licensing Board Panel 84/03/13 2pp 22665 360 24X Fiche 50-445,84/03/15.8403190028
- 8403200009 Requests to be informed about requested supplementation of answers to interrogatories & requests to produce Related correspondence ELLIG. J. Citizens Association for Sound Energy 84/03/15 REYNOLDS:N S. Bishop, Liberman, Cook, Purcell & Reynolds 1p 22685 202 244 Fiche 50-445:84/03/15.8403200009
- 8403200012 Advises that listed documents will be used in crossexamination of NRC staff witnesses on welding Related correspondence ELLIS. J Citizens Association for Sound Energy 84/03/15 TREBY. S., MIZUNG. O. B. Office of the Executive Legal Director in 22483 357 24X Fiche 50~445,84/03/15,8403200012
- 8403200025 Forwards further responses from Waish re Cygna 840313 responses to Citizens Assoc for Sound Energy Cartificate of Svc encl Related correspondence ELLIS, J Citizens Association for Sound Energy 84/03/15 FIGOTT, D R. Orrick. Herrington & Sutcliffe 5pp 22699 223 24X Fiche 50-445.84/03/15,8403200025
- 8403200047 Requests ABLB advise if motion for admission of enc1 two pages re nonconformance repts concerning handwritten/ typewritten discrepancies would be entertained at present Related correspondence ELLIS.J Citizens Association for Sound Energy 84/03/15 BLOCH.P B , MCCOLLOM.K A , JORDAN.W.H Atomic Safety and Licensing Board Panel 4pp 22698 287 24X Fiche 50-445.84/03/15.8403200047
- 8403200073 Requests listed documents for 18th & 20th sets of interrogationies Certificate of Svc encl Related correspondence ELLIS, J. Citizens Association for Sound Energy 84/03/15 REYNOLDS, N.S., HORIN, B. Bishop, Liberman, Cook, Purcell & Reynolds 1p. 22684-362 24X Fiche 30-445,84/03/15,8403200073
- B403200114 Discusses supplementation of answers to interrogatories & requests to produce re T-shirt incident Applicants have history of being uncooperative re discovery matters Related correspondence ELLIB.J. Citizens Association for Sound Energy 84/03/15 BLOCH.P.B. JURDAN.W H. MCCOLLOM.K A. Atomic Safety and Licensing Board Panel Spp. 22685-327 24X Fiche 50-445.84/03/15.8403200114

- B403200118 Twentieth set of interrogatories & request to produce to applicant Certificate of Svc encl Related correspondence ELLIS, J Citizens Association for Bound Energy B4/03/15 Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 8pp 22683 344 24X Fiche 50-445, B4/03/15, B40320011B
- B403200147 Forwards Citizens Assoc for Sound Energy Exhibit 927,
 "Formulas for Stress & Strain," omitted from 840313 ltr
 H/o encl Related correspondence
 ELLIS.J Citizens Association for Sound Energy. 84/03/15
 P10017.D R Orrick, Herrington & Sutcliffe ip 22499 158 24X
 Fiche 50-445.84/03/15.8403200147
- 8403210102 Forwards IE Insp Repts 50-445/83-47 & 50-446/83-22 W/o encis Related correspondence
 TREBY, S.A. Hearing Branch I 84/03/16 BLOCH, P.B., JDRDAN, W.H.,
 MCCOLLOM, K.A. Atomic Safety and Licensing Board Penel 19
 22706 117 24X Fiche 50-443,84/03/16.8403210102
- 8408200065 Notice that evidentiary hearing scheduled for 840423-27 rescheduled for 840424-27 in Fort Worth.TX BLOCH.PB Atomic Safety and Licensing Board Panel 84/03/19. 1p 22684 361 24X Fiche 50-445.84/03/19.8403200065
- 8403270031 Requests that MD Spence be substituted for RJ Gary on svc list Related correspondence REYNOLDS.N S Bishop. Liberman. Cook. Purcell & Reynolds REYNOLDS.N S Texas Utilities Electric Co (formerly Texas Utilities Generating Co) DSB 18 84703/19 CLEMENTS.W L Dacketing & Services Branch. 1p 22769 327 24X Fiche 50-445.84/03/19.
- 8403280337 Responds to ASLB 840308 memorandum re-schedule & policy of OFC of Investigation Policy re-release of repts to ASLB includes review of rept & deletions to protect identity of confidential sources

 HAVES.B B Office of Investigation DSB 157 84/03/21

 MCCDLLOM.K A . BLUCH.P B . JORDAN.W H Atomic Safety and Licensing Board Fanel . 2pp 22787 097 24X Fiche 50-445.84/03/21.8403280339
- 8403280342 Memorandum & order releasing transcript of 840221 in camera tessions & applicant memo re release of transcript as part of public record of proceeding BLOCH.P B Atomic Safety and Licensing Board Panel DSB 150 84
- H General correspondence

ŝ

- 8403270173 Requests that name be placed on mailing list for matls issued in facility OL & IE monitoring process GARDE.B P Government Accountability Project 84/03/19 SURWELL, S Office of Nuclear Reactor Regulation, Director ip 22771 137 24X Fichm 50-445,84/03/19,8403270173
- B403230059 Designates MD Spence as recipient of official correspondence pertaining to facilities CLEMENTS BR Texas Utilities Electric Co (formerly Texas Utilities Generating Co). B4/03/20 DENTON, HR Dffice of Nuclear Reactor Regulation, Director ip 22726 229 24X Fiche 50-445, 84/03/20, 8400320059
- G Inspection reports: IE Bulletins & correspondence
- B403080324 F01A request for documents considered by NRC in preparation of notice of violation & proposed imposition of civil penalty, 831222 ltr transmitting violation & rept of investigation re intimidation of GA personnel HARTMAN.S L. Debevoise & Liberman 83/12/30 FELTON, J.M. Division of Rules and Records 2pp 22583 169 24X Fiche 50-445, 83/12/30, 8403080324.
- 8403080325 Partial response to FOIA request for documents considered by NRC in preparation of three categories of documents concerning facilities Forwards documents listed on App A FELTON, J M Division of Rules and Records 84/01/20 HARTMAN, B L Debevoise & Liberman 2pp 22583 171 24X Fiche 50-445, 84/01/20, 8403080325
- --8403080327 Rev 27 to Procedure GI-OP-11 4-5 re visual defects insp & dry film thickness Related info encl # Texas Utilities Electric Co (formerly Texas Utilities Generating Co 1. 83/11/08. 6pp 22583 173 24X Fiche 50-445.84/01/20.8403080325
- --8403080332 Describes commitments made to NRC in RJ Gary 830928 response to notice of violation & proposed imposition of civil penalty CLEMENTS, B R Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 83/11/29 COLLINS, J T Region 4, Office of Director 11pp 22583 182 24X Fiche 50-445,84/01/20,8403080325

- --B4030B0333 Notification of significant licensee meeting on B3i212 w/
 util in Arlington.TX to discuss potential enforcement action
 re intimidation of employees by H Williams
 * Region 4, Office of Director B3/12/08 Region 4, Office of
 Director ip 22583 193 24X Fiche 50-445,84/01/20.84030B0325
- --8403080335 Forwards rept re investigation into allegations made by WA Dunham & concerns related to protective coatings Related documents encl GARY, R. J. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.) 83/12/13 COLLING, J. Region 4, Office of Director 22pp 22583 204 24X Fichs 50-445,84/01/20,8403080325
- 8403260206 Forwards IE Insp Rept 50-445/83-43 on 831114-18 No violations or deviations noted JOHNSON.E H Region 4. Office of Director 84/02/03 QARY,R J Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 2pp 22756 223 24X Fiche 50-445.84/02/03.8403260206
- --8403260214 IE Insp Rept 50-445/83-43 on 831114-18 No violations or deviations noted Major areas inspected protected area, physical barriers vital area, testing & maint & security sys power supply Details withheld (ref 100PR73, 21) CALDWELL R A , KELLY, J , HUNNICUTT, D, M Region 4, Office of Director 84/02/02 ip 22756 225. 24X Fichs 50-445,84/02/03,8403260206
- 8403040180 Forwards IE Insp Rept 50-445/84-01 on 840123-27 No violations or deviations identified JOHNBON.E H Region 4. Office of Director 84/02/17 QARY,R J Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 2pp 22519 012 24X Fiche 50-445,84/02/17,8403040180.
- --B403060184 IE Insp Rept 50-445/84-01 on 840123-27. No violations or deviations identified Major areas inspected licensee chemistry/radiochemistry program: including primary chemistry program: callbr & GC & corporate GA program. NICHOLAS. J B . WISC. R . MURRAY. B Region 4. Office of Director B4/02/17 20pp 22519.014 24% Fiche 50-445.84/02/17.8403060180
- B403060371 Forwards IE Insp Rept 50-443/83-52 on B31220-840130 No violations or deviations noted JOHNSON, E H Region 4, Office of Director 84/02/21 QARY,R J Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 2pp 22511 315 24X Fiche 50-445.84/02/21.8403060371
- --8403060373 IE Insp Rept 50-445/83-52 on 831220-840130 Major areas inspected alleged poor electrical cable tray clamping gractices Concerns re poor const practices unsubstantiated, OBERO, C R, HUNNICUTI, D M, Region 4, Office of Director, 84/02/17 6pp 22511 317 24X Fiche 50-445,84/02/21,8403060371
- 8403130442 Forwards IE Insp Rept 50-445/83-51 on 831201-840131. No deviations or violations identified JDHN80N.E H Region 4. Office of Director 84/02/22 QARY,R J Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 2pp 22613 153 24X Fiche 50-445,84/02/22,8403130442.
- --8403130453 IE Insp Rept 50-445/83-51 on 831201-840131 No violations or deviations identified Major areas inspected initial startup procedures review, fuel receipt emergency drill & IE bulletin followup KELLEY, D. L., SMITH, W. F., HUNNICUTT, D. M. Region 4, Office of Director 84/02/22 6pp 22613 155 24% Fiche 50-445,84/02/22, 8403130442
- 8403050431 Requests add1 info re ultrasonic exam of cast stainless steel piping in RCPB as part of preservice insp program Response requested within 5 days of ltr receipt YOUNGBLOOD, B. J. Licensing Branch i 84/02/24 QARY, R. J. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.). 3pp 22552 047 24X Fiche 50-445,84/02/24,8403060431
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list enc!

 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22909 239 24X Fachs 50-000,84/02/28,8401190072.
- 8403130183 Forwards IE Insp Repts 50-445/83-47 & 50-446/83-22 on 830801-840117 No violations or deviations noted JDHNSDN.E H Region 4. Office of Director 84/02/28. QARY, R. J. Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 2pp 22607 129 24X Fiche: 50-445, 84/02/28, 8403130183
- --8403130219 IE Insp Repts 50-445/83-47 & 50-446/83-22 on 830801-840117
 No violations or deviations noted Major areas inspected:
 issues before ABLB hearing board
 TAYLOR.R G , HUNNICUTI.D M Region 4, Office of Director,
 84/02/28 6pp 22607 131 24X Fiche 50-445,84/02/28,8403130183

- 8403260069 Forwards avaluation of 830718 request for deletion of steam electric station license condition re low-pressure turbine disc insp NRC maintains position in SER (NUREG-0797) that insp must be conducted YOUNGELOOD. B J Licensing Branch 1 84/02/28 GARY, R J Texas Utilities Electric Ca (formerly Texas Utilities Generating Co) 2pp 22763 235 24X Fiche 50-445, 84/02/28, 8403260069
- --8403240081 Evaluation of util 830718 request to delete turbine disc insp license condition UT insps required at first refueling & every subsequent refueling outage + NRC - No Detailed Affiliation Given 84/02/28 19pp 22763 237 24X Fiche 50-445,84/02/28,8403260069
- 8402070007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Evc list encl GRACE. J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22352 329 24X Fiche 50-000.84/03/02.8402070007
- 840209000B IE Info Notice B4-16, "Failure of Automatic Sprinkler Sys Valvas to Operate" Syc list encl JORDAN, E L Division of Emergency Preparadness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008
- B402090009 IE Info Notice 84-15, "Reporting of Radiological Releases "
 Svc list encl
 JORDAN, E. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc 119pp 22553 217 24X Fiche. 30-000, 84/03/02, 8402090009
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc. 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8402070024 IE Info Notice 94-09, Rev 1, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list enc? JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000, 84/03/07, 8402070024
- B402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Bys " Byc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc. 118pp. 22584 186 24X Fiche 50-000, B4/03/07, B402090028
- 8403190406 Informs that no insp repts will be issued for Rept Numbers 50-445/83-41 & 50-446/83-25

 JOHNSON,E H Region 4, Office of Director 84/03/07 GARY,R J Texas Utilities Electric Co (formerly Texas Utilities Generating Co.) ip 22674 337 24% Fiche 50-445,84/03/09,8403190406
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Bafety Bys " Syc list enc! DEYOUNG, R C. Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000.84/03/12,8402090031
- 8403190118 Forwards NRC Insp Repts 99900330/84-01 & 50-445/83-52 of GVONA Energy Svcs GA program used during Unit 1 independent assessment program No application to withhold rept received TREBY, B A Hearing Branch 1 84/03/14 BLOCH, P B , JURDAN, W H , MCCOLLOM, K. A Atomic Safety and Licensing Board Panel 23pp 22666:273 24X Fichs 50-445,84/03/14,8403190118
- B403200125 Forwards vendor insp repts for info & action Repts identify concerns found by Vendor Program Branch during insps of vendor activities Ack of itr receipt requested JOHNBON.E H Region 4. Defice of Director 84/03/16 GARY,R J Texas Utilities Electric Co (formarly Texas Utilities Generating Co). 3pp 22699 173 24X Fiche.50-445,84/03/16,8403200125
- 8402090043 IE Info Notice 84-19. "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50-000.84/03/21.8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Bys " Bvc list encl JDRDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 135pp 22733 001 24X Fiche 50-000,84/03/21,8402090044

- R Periodic operating reports & related correspondence
- 8403020443 Forwards monthly status rept of offsite emergency preparedness for OL reviews for Jan 1984 Changes in FEMA finding dates not caused by delay due to offsite emergency planning issues
 DIRCKS.W J Office of the Executive Director for Operations 84/02/21 PALLADINO Commissioners 9pp 22492 083 24X Fiche 50-000.84/02/21.8403020443
- S Reportable occurrences, LERs & related correspondence
- 8403010451 Informs Commission of problems w/emergency diesel generators meg by Transamerica Delaval.Inc DIRCKG.W J Office of the Executive Director for Operations SECY-83-034 84/01/25 4pp 22438 347 24X Fiche 50-000,84/01/25.
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines. Gimpel NPS-4 T&T valve. to close Encl itr dtd 840203 sent to listed utils GE notified of affected units in BWR plants
 THERDUX.R R Terry Carp 84/02/22 WODDRUFF.R W Director's Office, Office of Inspection and Enforcement App 22706 327 24X Fiche 50-000.84/02/22.8403210032
- 8403070256 Followup Part 21 rept re defective mechanical snubber capstan springs supplied by Pacific Scientific Affected utils listed Purchasers have been notified & advised to work directly w/Pacific Scientific in disposition HOUI,L NPS Industries, Inc. 84/02/24 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 2pp 22536 279 247 Fiche 50-000.84/02/24.8403070256
- 840/3010/207 Forwards "Investigation of Types AF & AE Piston Skirts," por Transamerica Delaval, Inc. Quiners Group program commitments Rept evaluates cracks in AF piston skirts in Shoreham & Grand Gulf Nuclear Power Stations
 MUSELER, W J TDI (Transamerica Delaval, Inc.) Quiners Group
 84/02/27 DENTON, H.R. Office of Nuclear Reactor Regulation,
 Director 3pp 22434 090 24X fiche 50-000, 84/02/27, 8403010207
- 8402090021 Board Notification 84-039 discusses NRC 840210 & 14 meetings w/Transamerica Delaval, Inc Emergency Diesel Generators Characteris schedules on 840308 for finalization of generic progrem plan prior to NRC review EIBENHUT, D & Division of Licensing 84/02/28 PALLADINO Commissioners 5pp 22546 003 24% Fiche 50-000,84/02/28, 8402090021
- 8403010218 Forwards task descriptions for 14 known problems re Transamerica Delaval, Inc emergency diese) generators MUSELER, W J TDI (Transamerica Delaval, Inc.) Owners Group 84/02/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 42pp 22435 177 24X Fiche 50-000.84/02/28.8403010218
- 8402070020 Board Notification 84-044 forwards Part 21 rept re Transamerica Delaval. Inc turbocharger thrust bearing Intercation defect resulting in engine monavailability EISENHUT.D G Division of Licensing 84/02/29 FALLADIND Commissioners 4pp 22541 243 24X Fiche 50-000,84/02/27, 84020902020
- 840314004B Forwards "Orand Oulf Component Tracking Sys," "Shoreham Component Tracking Sys" & "Transamerica Delaval.Inc Dissel Generators Gumers Group Program Plan," to resolve concerns w/emergency diesel generators MUSELER.W J Long Island Lighting Co 84/03/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22626 062 24X Fiche 50-000.84/03/02,8403140048
- --8403140095 "Transamerica Delayal, Inc Diesel Generators Guners Group Program Plan " * TDI (Transamerica Delayal, Inc.) Guners Group 84/03/02 261pp 22628 223 24X Fiche.50-000.84/03/02.8403140048
- 8403160213 Interim Deficiency Rept BDAR-125 re laminations & delaminations in cable tray support column in cable spread room. Initially reported on 840111 Evaluation continuing Completion expected by 840515 GARY.R J Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/03/04 J0HNSON.E H Region 4, Office of Director ip 22658 231 24X Fiche. 50-445, 84/03/06, 8403160213
- 8402070033 Board Notification 84-047 forwards Transamerica Delaval.inc Owners Group piston skirt rept & task descriptions EIBENHUT,D 9 Division of Licensing 84/03/07 PALLADINO Commissioners 4pp 22674 221. 24X Fiche 50-000,84/03/07, 8402070033

- 8402090038 Board Notification 84-051 forwards "Transamerica Delaval Inc (TDI) Diesel generators Owners Group Program Plan " EISENHUT.D O Division of Licensing 84/03/12 PALLADINO Commissioners 5pp 22688 214 24% Fichs 50-000:84/03/12. 8402090038
- 8402090039 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delaval, Inc. (TDI) Owners Group Distribution tist encl EISENHUT: D 0 Division of Licensing 84/03/12 PALLADINO Commissioners 5pp 22708 001 24% Fiche 50-000, 84/03/12, 8402090037
- --8403060536 Forwards summary of 840210 meeting w/Transamerica Delaval. Inc Owners Group in Bethesda.MD re problems w/emergency diesel generators CARUSO/R Licens olesel generators CARUSD.R Licensing Branch 2 84/02/27 O'REILLY, J P NRC - No Detailed Affiliation Given 6pp 22708 006 24X Fiche 50-000,84/03/12.8402090039
- --8403060554 Transcript of 840210 meeting w/Transamerica Delaval.Inc Owners Group in Bethesda.MD re problems w/emergency diesel generators nerators NRC - No Detailed Affiliation Given 84/02/10 147pp 201 COB 24X Fiche 50-000/84/03/12/8402090039 67201 008
- --8403070409 Summary of B40216 meeting w/Transemerica Delaval, Inc Cumers Group in Wading River, NY re program plan to establish reliability of diesel generators Agenda, meeting transcript & attendance list encl MILLER, M A Licensing Branch 4 84/02/27 Licensing Branch 4 8pp 22708 161 24X Fiche 50-000,84/03/12,8402090039
- --8403070423 Transcript of 840216 conference in Wading River.NY re Transamerica Belaval. Inc diesel generators Pp 1-82 * Commissioners 84/02/16 84pp 22708 167 24X Ficha 50-000,84/03/12.8402090039
- 8403140050 Forwards "Design Review of Connecting Rod Bearing Shells for NUCLEMOND FORWARDS TO RESIGN REVIEW OF Connecting Rod Bearing Shell: Transamerica Delaval Enterprise Engines" for Shoreham & Grand Gulf diesel generators
 MUSELER, W. J. Long Island Lighting Cv B4/03/12 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 226/32 074
 24X Fiche 50-000/84/03/12.8403140050
- 8403150133 Forwards "Transamerica Delaval.Inc Diesel Generator Rocker Arm Capscrew Stress Analysis Rept " Capscrew design adequate for applicable engines & svc conditions HUSELER.H J TOI (Transamerica Delava). Inc) Owners Group 84/03/13 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 22639 270 24X Fiche 50-000.84/03/13.8403130133
- 8403200222 Responds to 840214 Requests for Info i & 2 re R-4 series engines List indicating engine number, model & syc number, customer name & address, rating, date shipped & date started enct
 mathews C S Transamerica Delaval, Inc 84/03/16 EISENHUT, D Q
 Division of Licensing 20pp 22691 179 24X Fichs 50-000,84/03/16,
- 8403270132 Forwards "Emergency Diesel Generator Air Start Valve Capscrew Dimension & Stress Analysis," prepared by S&W for Transamerica Delaval, Inc (TDI) Diesel Generator Owners Group MUSELER, H J TDI (Transamerica Delaval, Inc.) Owners Group 84/03/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22774 001 24% Fiche 50-000, 84/03/23, 8403270132
- 8403270134 Requests meeting on 840418 to discuss short-term & long-term corrective actions & investigations re Transamerica Delayal diesel generators List of suggested meeting topics en∈1 MCCAUGHY.J P TDI (Transamerica Delaval, Inc.) Owners Group 84/03/23 DENTON,H R Office of Nuclear Reactor Regulation, Director 4pp. 22769 133 24X Fiche 50-000,84/03/23,8403270134
- T. Hearing transcripts on non-antitrust matters
- 8403020145 Transcript of \$40828 telephone conference in Bethesda, MD Pp 10,350-10,383 * Abomic Safety and Licensing Board Panel, 84/02/28 35pp 22440 275 24X Fiche 50-445,84/02/28,8403020145.
- 8403090104 Forwards correction to J Doyle 840222 testimony Related 40349144 Forwards Lorrection of Tourist Burnd Energy 84/03/05 correspondence ELLIS,J Citizens Association for Sound Energy 84/03/05 BLDCH,P 8 . JORDON,W H . MCCOLLOM,K A Atomic Safety and Licensing Board Panel 1p 22376 081 24X Fiche 50-445,84/03/05,8403070104

- --8403090108 Affidavit of J Doyle correcting 840222 testimony during cross-examination of CYGNA Certificate of 8vc encl DOYLE, J Citizens Association for Sound Energy 84/03/03 7pp 22376 082 24X Fiche 50-445.84/03/05.8403090104
- B402090039 Board Notification B4-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delaval.Inc (TDI) Owners Group Distribution EISENHUT, D G Division of Licensing 84/03/12 PALLADING Commissioners 5pp 22708 DOI 24% Fiche 50-000,84/03/12,8402090039
- --8403060536 Forwards summary of 840210 meeting w/Transamerica Delaval, Inc Owners Group in Bethesda, MD re problems w/emergency diesel generators

 CARUSO,R Licensing Branch 2 84/02/27 O'REILLY, J P NRC No Detailed Affiliation Given App 22708 006 24X

 Fiche 50-000,84/03/12,8402090039
- -8403060554 Transcript of 840210 meeting w/Transamerica Delaval.Inc Owners Group in Sethesda.MD re problems w/emergency diesel enerators

 * NRC - No Detailed Affiliation Given 84/02/10, 147pp 67201 00B 24X Fiche 50-000,84/03/12,8402090039
- --8403070409 Summary of 840216 meeting w/Transamerica Delaval.Inc Owners Group in Wading River.NY re program plan to establish reliability of diesel generators Agenda.meeting transcript & attendance list encl MILLER.M A Licensing Branch 4 84/02/27 Licensing Branch 4 8pp 22708 161 24X Fiche 50-000.84/03/12.8402040037
- ---8403070423 Transcript of 840216 conference in Wading River,NY re Transamerica Delaval, Inc diesel generators Pp 1-82 * Commissioners 84/02/16. 84pp 22708 169 24X Fiche 50-000,84/03/12.8402090039
- 8403260008 Transcript of 840319 hearing in Fort Worth, TX Pp 10.384-, 113 Atomic Safety and Licensing Board Panel 84/03/19 340pp 747 001 24% Fiche 50-445,64/03/19,8403260008 22747 001
- 8403270167 Transcript of 840321 hearing in Fort Worth, TX Pp 11.019-11.318 B4/03/21 349pp
 - * Atomic Safety and Licensing Board Panel 84/ 22774 150 24X Fiche 50-445,84/03/21,8403270167
- 8403270082 Transcript of 840322 hearing in Fort Worth, TX Pp 11,337-11.710. 7.5. Atomic Safety and Licensing Board Panel 84/03/22 373pp 765 007 24% Fiche 50-445.84/03/22,8403270082
- 8403280021 Transcript of 840323 hearing in Fort Worth, TX Pp 11.711-* Atomic Safety and Licensing Board Fanel 84/03/23 300pp 22777 173 24X Fiche 50-445,84/03/23,8403280021

V Operator Examinations

- B403130160 Forwards nuclear plant experience tables for shift advisors, shift supervisors, assistant shift supervisors, reactor operators & shift technical advisors Expected OL & fuel load dates are 840701
 GLEMENTB, B R Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/03/08 DENTON, H.R Office of Nuclear Reactor Regulation, Director Spp 22608 238 24X Fithe 50-445, 84/03/08, 8403130160
- DOCKET 50-446 COMANCHE PEAK STEAM ELECTRIC STA , UNIT 2 A Application/construction stage documents & correspondence
- 8401120425 Forwards Amend 7 to CPPR-126 & CPPR-127. safety evaluation & notice of issuance & availability Amend reflects change in ownership of facilities
 EISENHUT, D Q Division of Licensing 83/12/30 QARY, R, J Texas
 Utilities Electric Co (formerly Texas Utilities Generating Co).
 3pp 22210 343 24X Fiche 50-445, 83/12/30, 8401120425
- --8401120428 Amend 7 to CPPR-126 & CPPR-127, reflecting change in 00120428 Amend / to upra-120 a occasion, restricting change an ownership of facilities EISENHUT D Q Division of Licensing, 83/12/30 4pp. 21804 341 24X Fichs 50-445,83/12/30,8401120425
- --8401120433 Bafety evaluation supporting Amend 7 to CPPR-126 & CPPR-127.

 * Office of Nuclear Reactor Regulation, Director 83/12/29. 3pp. 21804 338 24% Fiche 50-445,83/12/30,8401120425

- --8401120437 Notice of issuance & availability of Amend 7 to CPPR-126 & CPPR-197 CPPR-12/ YOUNOBLODD.B J Licensing Branch 1 83/12/29 3pp 21804 348 24X Fiche 50-445,83/12/30,8401120425
- 8403060155 Requests exemption from provisions of GDC 4 requiring protection of structure, sys & components against certain dynamic effects associated w/postulated breaks in RCS primary loop.per Generic Ltr 84-04 GARY, R. J. Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/02/17 YDUNGBLOOD, B. J. Licensing Branch 1 4pp 22513 351 24X fichs 50-445.84/02/17,8403040155
- 8403020148 Forwards, for review, draft environ protection plan proposed for App 8 to plant OLs
 YOUNOBLOOD, B. J. Licensing Branch 1 84/02/21 GARY, R. J. Texas
 Utilities Electric Co. (formerly Texas Utilities Generating Co.)
 2pp 22491 157 24X Fiche 50-445,84/02/21,8403020148
- --8403020152 Environ protection plan (nonradiological) for facility. App B
 - 40 OLs, draft

 # NRC ~ No Datailed Affiliation Given 84/02/21 15pp
 22491 159 24X Fiche 50-445,84/02/21,8403020148
- B403050273 Requests provision of alternative surveillance to replace requirement presently in Tech Specs re turbine overspeed protection Proposed alternative maint, calibr & testing protection reposed alternative mailur callor & testing program should assure that protection sys operable YOUNOBLOOD B J Licensing Branch 1 84/02/27 QARY,R J Texa Utilities Electric Co (formerly Texas Utilities Cenerating Co) 4pp. 22501 107 24X Fiche 50-445.84/02/27.8403050273
- 8403060299 Informs NRC that Nuclear Util Task Action Committee completed final draft of rept defining appropriate vendor interface program discussed in Generic Ltr 83-28 Final rept scheduled to be released by Apr 1984 BCHMIDT,H C Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/02/29 EISENNUT.D 0 Office of Nuclear Reactor Regulation: Director 1p 22515,362 24X Fiche.50-445,84/02/29,8403060299
- 8403090308 Forwards request for add1 info re leak-before-break analysis & fracture toughness of piping matls under thermal aging conditions Submittal date requested within 5 days of ltr receist YOUNGBLOOD, B J Licensing Branch 1 84/03/02 GARV.R J Utilities Electric Co (formerly Texas Utilities Generating Co)
 4pp. 22584 338 24% Fiche 50-445,84/03/02,8403090308
- 8403160079 Forwards Suppl 1 to "Human Factors Control Room Design Review," final rept OARY,R.J Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/03/08 YOUNOBLOOD,B J Licensing Branch 1 1p. 22634 001 24X Fiche 50-445,84/03/08,8403160079
- --8403140083 Suppl 1 to "Human Factors Control Room Design Review," final rapt.
 # Taxas Utilities Electric Co (formerly Taxas Utilities Generating Co). 84/03/31 122pp 22654 002 24X Fiche 30-445,84/03/08,8403160079
- 8402090041 Board Notification 84-050 provides Commission policy statement & proposed rulemaking on environ qualifications EISENHUT,D 0 Division of Licensing 84/03/14 Atomic Safety and Licensing Board Panel 10pp 24% Fiche 50-000,84/03/14,8402090041
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents. App B document entirely withheld (ref FOIA Exemption 5) Review of addl documents subj to request continuing FELTON. J M Division of Rules and Records 84/02/13 ANDERSON. S 1 Qarvay, Schubert, Adams & Barer 7pp 22583 226 24X Fiche: 50-000, 84/02/13, 8403080179.
- --8005130793 Provides status of BER inputs & acceptance reviews for UL & CP applications. Schedule should be mst, BURKE, W C. Effluent Treatment Systems Branch 80/02/06 KREGER. W E. Assistant Director for Site Analysis ip 22583 235 24X Fiche. 50-000,84/02/13,8403080179.
- 8403020289 Forwards resolution of SER Confirmatory Issue 11 re 830218 & 0316 submittals concerning TMI Action Items I.C.2 & YOUNGBLOOD, B. J. Licensing Branch 1 84/02/21 YDUNGBLOOD, B. J Licensing Branch 1 84/02/21 GARY, R J Texas Utilities Electric Co (formerly Texas Utilities Generating Co) Spp. 22492 241 24X Fiche 50-445.84/02/21,8403020289

- 8403260069 Forwards evaluation of 830718 request for deletion of steam electric station license condition re low-pressure turbine disc insp NRC maintains position in SER (NUREG-0797) that insp must be conducted YOUNOBLOOD, B J Licensing Branch 1 84/02/28 GARY, R J Texa Utilities Electric Co (formerly Texas Utilities Generating Co) 2pp 22763 233 24X Fichs 50-445.84/02/28,8403260069
- 8403140288 Forwards SSER re TM1 Action Plan Items I C 1 & 1 C 8 of SER Confirmatory Issue 5 concerning guidance for evaluation & development of procedures for transients & accidents YOUNGBLOOD.B J Licensing Branch 1 84/03/06 GARY,R J Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 6pp 22636-312 24X Fiche 50-445.84/03/06,8403140288
- 8403140293 Provides clarification of NRC favorable findings re SER Confirmatory Issue 11 for TMI Action Plan Item I G 1 Util should wither commit to perform natural circulation boron mixing test or ref boron mixing test at Diablo Canyon YOUNOBLOOD, B J Licensing Branch 1 84/03/06 GARY, R J Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 3pp 22635 333 R4X Fiche 50-445.84/03/06.8403140293
- 8403270345 Requests schedule for responding to SER Outstanding Issue 3 re environ qualification of safety-related mechanical aquipment in harsh environs & Issue 4 re alternate safe snotedam YOUNOBLOD, B J Licensing Branch 1 84/03/13 GARY, R J Texa Utilities Electric Co (formerly Texas Utilities Generating Co) 4pp 22787 352 24X Fichs 50-445,84/03/13,8403270345
- F Security, medical, emergency & fire protection plans
- 8403130114 Forwards proposed guidelines & Rev 1 to proposed objectives qualifull Forwards proposed guidelines & Rev 1 to proposed objective for 1982 emergency preparedness field exercise, for review Exercise scheduled for 831214 Comments requested by 830923 JUNES, R A Texas Utilities Electric Co (formenly Texas Utilities Quenerating Co) 93/09/13 MADBEN, O L Region 4, Office of Director 2pp 22601.301 24X Fiche 50-445.83/09/13,8403130116
- --8403130126 Proposed guidelines for 1983 emergency preparedness field exercise scheduled for 831214 * Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 83/09/13 3pp 22401 303 24X Fiche 50-445,83/09/13.8403130116
- --8403130136 Rev 1 to proposed objectives for 1983 emergency preparedness field exercise

 * Texas Utilities Electric Co (formerly Texas Utilities
 Ownerating Co) 83/04/12 14pp 22601 306 24X
 Fiche 50-445,83/09/13,8403130116
- 8403130313 Forwards "NRC Emergency Preparedness Appraisal Items Status Tracking Rept," to aid NRC in preparations for upcoming appraisal Emergency preparedness planning project organization chart & list of responsibilities also encl. JONES, R A Texas Utilities Electric Co (formerly Texas Utilities Commentaring Co) 83/09/13 MADEEN, C L Region 4, Office of Director 6pp 22605.095 24X Fiche 50-445.83/09/13.8403130313
- --8403130319 "NRC Emergency Preparedness Appraisal Item Status Tracking Rept "

 * Texas Utilities Electric Co (formerly Texas Utilities
 Generating Co) 83/09/11 77pp 22605 101 24%
 Fiche 50-445,83/09/13,8403130313
- 8403050146 Submits scenario for providing info re emergency preparedness exercise
 COLLINGS.J T Region 4. Office of Director B4/02/09 QARY.R J
 Texas Utilities Electric Co (formerly Texas Utilities Generating
 Co) 2pp 22487 312 24X Fiche 50-445,84/02/09,8403050144
- 8402070006 Board Notification 84-034 forwards R Vollmer 840206 memo to D Elsenhut re fire research results concerning fires in electrical cabinets in control room EISENHUT.D & Division of Licensing 84/02/23 PALLADING Commissioners ip. 22574 203 24X Fiche 50-000,84/02/23,
- --8403080316 Recommends that info re fire research results concerning roscosio recommendo that into pertite research results that fire in electrical cabinets in control room be submitted for board notification.per NRR Off Ltr 19.dtd 821001 Further evaluation of test data required VOLLMER.R H Division of Engineering 84/02/06 EISENHUT, Division of Licensing 10pp 22576 204 24X Fichs 50-000,64/02/23,8402090006 84/02/06 EISENHUT, D. G

Q Adjudicatory correspondence

- 8403070177 Motion re summary of cross-examination areas supplied to CYONA on 840222 Applicants have used thin wall pipe & many instances of min pipe wall violations exist. W/M Walsh affidavit Related corespondence ELLIS. J Citizens Association for Sound Energy 84/02/29 Atomic Safety and Licensing Board Panel App 22541 326 24X Fiche: 50-445, 84/02/29, 8403070177
- --B4030701B1 Affidavit of W Walsh re thin wall pipe.Pipe fittings larger than nominal wall thickness assumed by piping designers will increase thermal expansion loads on piping supports & nozzles
 WALEH,M Citizens Association for Sound Energy. 84/02/28 4pp 22541 330 24X Fichs 50-445,84/02/29,8403070177
- --B4030701B2 Forwards M Walsh affidavit Certificate of Svc and ELLIS.J Citizens Association for Sound Energy 84/02/29 Docketing & Services Branch 3pp 82541 352 24X Ficha 50-445.84/02/29.8403070177
- 8403070191 Notifies that no conflict of interest exists in dual representation of Brown & Root & Hutchinson re investigation of CYONA matter
 CHARNOFF, G Shaw, Pittman, Potts & Trowbridge CHARNOFF, G Teras
 Utilities Electric Co (formerly Teras Utilities Generating Co).
 84703/01 BLOCH, P Atomic Safety and Licensing Board Panel 3pp
 22547.273 24X Fiche 50-445,84703/01.8403070191
- 8403070126 Notice of appearance in proceeding Certificate of Syc encl PIGOTT.D Cygna Energy Services PIGOTT.D. Orrick, Herrington & Subcliffe 84/03/05 4pp 22575 341 24X Fiche 50-445,84/03/05, 8403090196.
- 8403090128 Answer urging rejection of util 840203 plan to respond to ASLB memorandum & order re GA for design. ASLB should require 100% reinsp. design verification & mgt audit Certificate of Syc encl
 - Syc encl ELLIB, J Citizens Association for Sound Energy 84/03/05 Atomic Safety and Licensing Board Panel 19pp 22571 021 24X Fiche 50-445.84/03/05.8403090128
- 8403090099 Memorandum requesting Ofc of Investigations file target dates for completion & release of rept re facility investigations & policy for filing completed repts w/ASLB subj to protective order BLOCKIP B Atomic Safety and Licensing Board Panel 84/03/08 1p 22576 001 24X Fiche 50-445.84/03/08.8403090099
- 8403140055 Comments on util plan to respond to 840203 memorandum & order re GA for design Plan supported in part Certificate of Svc enc1
 MIZUNO.G B Hearing Branch I 84/03/09 17pp 22634 165 24X
 Fithe 50-445.84/03/09.8403140055
- 8403140034 Forwards response to 840305 comments on generic problems & cross-examination questions Exhibits 920-925.906 & 891-901 encl Certificate of Svc encl Related correspondence ELLIS.J Citizens Association for Sound Energy 84/03/10 WILLIAMS.N H Cygna Energy Services 25pp 22633.021 24X Fiche 50-445.84/03/10.8403140034
- 8403140013 Confirms agreement to preserve any maths informally requested on discovery re electrical inspectors Related correspondence HORIN.W A Bishop. Liberman. Cook, Purcell & Reymolds HORIN.W A Texas Utilities Electric Co (formerly Texas Utilities Qenerating Co) 84/03/12 BLDCH.P B, MCCOLLOM.K A, JORDAN.W H Atomic Safety and Licensing Board Panel 1p 22633 225 24X Fiche 50-448,84/03/12.8403140013
- 8403140020 Answer to Citizens Assoc for Sound Energy (CASE) 840229 motion re cross-examination areas supplied to CYGNA CASE matters inappropriate & irrelevant in context of CYGNA rept W/Certificate of Evc Related correspondence REYNOLDS, N.S., HORIN, W.A. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.) REYNOLDS, N.S. Bishop, Liberman, if & Reynolds. 84/03/12. Atomic Safety and Licensing ilpp. 22633 290. 24X Fiche 50-445,84/03/12.
 - eventeenth set of interrogatories & requests to produce to Certificate of Byc and Related correspondence itizent Association for Sound Energy 84/03/12 Texas lectric Co. (formerly Texas Utilities Generating Co.), 076 24X Ficher 50-445;84/03/12,8403190024

- 8403190032 Motion for discovery re T-shirt incident Incident falls under heading of new & significant info re intimidation matters & deemed discoverable. Certificate of Svc encl Related correspondence
 ELLIS.J Citizens Association for Sound Energy 84/03/12 Atomic Safety and Licensing Board Panel 9pp 22666 067 24X
 Fichs 50-445,84/03/12,8403190032
- 8403150032 Suppl to applicant 840203 plan to respond to memorandum & order re GA for design discussing ASLB 840224 comments on Halsh/Doyle issues re compliance w/Criteria I & XVI Certificate of Svc encl Related correspondence REYNOLDS.N S Teras Utilities Electric Co (formerly Texas Utilities Generating Co) REYNOLDS.N S Bishop. Liberman, Cook. Purcell & Reynolds 84/03/13 12pp 22643 275 24X Fiche 50-445.84/03/13.8403150032
- 8403190006 Informs that Insp Rept 83-52, particularly app, Page 6, Items B & C re allegations of undue pressure & restriction & threatening w/firing will be used for cross-examination during hearing Certificate of Svc encl
 ELLIS.J Citizens Association for Sound Energy 84/03/13
 BLOCH.P B . MCGOLLOM.K A . JORDAN.W H Atomic Safety and Licensing Board Panel 9pp 22664 352 24X Fiche 50-445,84/03/13,8403190006
- 8403190148 Forwards Investigation Repts 4-83-001 & 4-83-013 dtd 830824 & 1103, respectively Complete & redacted versions encl TREBY, B A Hearing Branch 1 84/03/13 BLOCH, P B , JORDAN, W H , MCCOLLOH, K A Atomic Safety and Licensing Board Panel 200pp 22667.001 24X Fichs 50-445,84/03/13,8403190148
- 8403170111 Notice of appearance in proceeding Certificate of 8vc encl BACHMANN,R 9 Hearing Branch 1 84/03/14 3pp 22666 263 24% Fiche: 50-445,84/03/14,8403170111
- 8403190118 Forwards NRC Insp Repts 99900530/84-01 & 50-445/83-52 of CYGNA Energy Bycs GA program used during Unit 1 independent assessment program No application to withhold rept received TREBY.8 A Hearing Branch 1 84/03/14 BLOCH.P B., JORDAN.W H. MCCOLLOM.K A Atomic Safety and Licensing Board Panel 23pp 22666 273 24X Fiche 50-445.84/03/14.8403190118
- B403200026 Eighteenth set of interrogatories & requests to produce to applicants re issue of intimidation, harassment & threatening of GC inspectors & other employees Certificate of Bvc encl Related correspondence ELLIS, J. Citizens Association for Bound Energy B4/03/14. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.) 5pp 22699 228 24% Fiche 30-445,84/03/14,8403200026
- B403200126 Nineteenth set of interrogatories & requests to produce to applicant Certificate of Svc encl Related correspondence ELLIS, J Citizens Association for Sound Energy 84/03/14 11pp 22699. 067 24x Fiche 50-445, 84/03/14, 8403200126
- 8403190002 Memorandum clarifying open listed issues re GA program BLOCH P B . JORDAN W H . MCCOLLOM K A Atomic Bafety and Licensing Board Panel 84/03/15 21pp 22664 326 24X Fiche 50-445, 84/03/15.8403190002
- 8403170028 Memorandum ordering Ofc of Investigations to file, by 840329, affidavits responsive to ABLP concerns re observation of interviewee Applicants should file affidavits stating results of investigation by 840411
 BLOCH.P.B Atomic Safety and Licensing Board Panel 84/03/15 2pp 22665 360 24X Fiche 50-445.84/03/15,8403170028
- 8403200009 Requests to be informed about requested supplementation of answers to interrogatories & requests to produce Related correspondence ELLIS, J Citizens Association for Sound Energy 84/03/15 REYNOLDS,N S Bishop, Liberman, Cook, Purcell & Reynolds 1p. 22685 202 24x Fiche 50~445,84/03/15,8403200009
- 8403200012 Advises that listed documents will be used in cross-examination of NRC staff witnesses on welding Related correspondence
 ELLIS.J Citizens Association for Bound Energy 84/03/15
 TREBY.S , MIZUND.Q S Office of the Executive Legal Director. 1p
 82683:357 24X Fiche 50~445,84/03/15,8403200012
- 8403200025 Forwards further responses from Walsh re Cygna 840313 responses to Citizens Assoc for Sound Energy Certificate of Svc encl Related correspondence ELLIB.J Citizens Association for Sound Energy 84/03/15 PIGOTT, D R Orrick, Herrington & Sutcliffs, 5pp, 22699, 223. 24X Fichs 50-445, 84/03/15, 8403200025

- 8403200049 Requests ASLB advise if motion for admission of encl two pages re nonconformance repts concerning handwritten/
 typewritten discrepancies would be entertained at present
 Related correspondence
 ELLIB.J Citizens Association for Sound Energy 84/03/15
 BLOCH.P B . MCCOLLOM, K A . JORDAN, W H Atomic Safety and Licensing
 Board Panel 4pp 22698 287 24X Fiche 50-445.84/03/15,8403200049
- 8403200073 Requests listed documents for 18th & 20th sats of interrogatories Certificate of Svc encl Related correspondence ELLIG. J. Citizens Association for Sound Energy 84/03/15 REYNOLDS.N S. HORIN.B Bishop. Liberman. Coak. Purcell & Reynolds ip 22684 362 24X Fiche 50-445.84/03/15.8403200073
- 8403200114 Discusses supplementation of answers to interrogatories & requests to produce re T-shirt incident Applicants have history of being uncooperative re discovery matters Related correspondence ELLIS.J. Citizens Association for Sound Energy 84/03/15 BLOCH.P.B., JORDAN.W.H., MCCOLLOM.K.A. Atomic Safety and Licensing Board Panel 8pp 22685-327 24X Fiche 50-445,84/03/15.8403200114
- 8403200118 Twentieth set of interrogatories & request to produce to applicant Certificate of Svc encl Related correspondence ELLIB.J Citizens Association for Sound Energy 84/03/15 Texa: Utilities Electric Co (formerly Texas Utilities Generating Co) 8pp 82685 344 24X Fiche 50-445-84/03/15.8403200118
- 8403200147 Forwards Citizens Assoc for Sound Energy Exhibit 927.
 "Formulas for Stress & Strain." omitted from 840313 ltr
 W/o encl. Related correspondence
 ELLIS.J Citizens Association for Sound Energy 84/03/15
 FIGOTT, D.R Orrick, Herrington & Sutcliffe 1p 22699 158 24X
 Fiche 50-445,64/03/15,8403200147
- 8403210102 Forwards IE Insp Repts 50-445/83-47 & 50-446/83-22 W/o encis. Related correspondence
 TREBY.8 A. Hearing Branch 1 84/03/16 BLOCH, P B., JORDAN, W H .
 MCCOLLOM, K A. Atomic Safety and Licensing Board Panel 1p
 22706-117 24X Fiche 50-445,84/03/16,8403210102
- 8403200065 Notice that evidentiary hearing scheduled for 840423-27 reschaduled for 840424-27 in Fort Worth.TX BLOCH.P B Atomic Safety and Licensing Board Panel 84/03/19 1p 22684 361 24X Fiche 50-445,84/03/19,8403200065
- 8403270031 Requests that MD Spence be substituted for RJ Oary on svc list Related correspondence REYNOLDS.N S Bishop, Liberman. Cook, Purcell & Reynolds REYNOLDS,N S Texas Utilities Electric Co (formerly Texas Utilities Generating Co) DSB 118 84/03/19 CLEMENTS.W L Docketing & Services Branch. 1p 22769 327 R4X Fiche 50-445,84/03/19, 8403270031
- 8403280337 Responds to ABLB 840308 memorandum re schedule & policy of Ofc of Investigation Policy re release of repts to ASLB includes review of rept & deletions to protect identity of confidential sources

 HAYES. B B Office of Investigation DBB 157 84/03/21

 MCCOLLOM, K A , BLOCH, P B , JORDAN, W H Atomic Safety and Licensing Board Panel 2pp 22787 097 24X Fiche 50-445,84/03/21,8403280339
- 8403280342 Memorandum & order releasing transcript of 840221 in camera sessions & applicant memo re release of transcript as part of public record of proceeding BLCCH.P B Atomic Safety and Licensing Board Panel DSB 150 84/03/26 ip 22787 100 24X Fiche 50-445.84/03/26,8403280342
- H General correspondence
- 8403270173 Requests that name be placed on mailing list for matls issued in facility OL & IE monitoring process.

 OARDE, B. P. Government Accountability Project 84/03/19 BURWELL, S
 Office of Nuclear Reactor Regulation. Director ip 22771 137
 24X Fiche 50-445,84/03/19,8403270173
- 8403230059 Designates MD Spence as recipient of official correspondence pertaining to facilities CLEMENTG. B.R. Texas Utilities Electric Co (formerly Texas Utilities Generating Co) B4/03/20 DENTON. H.R. Office of Nuclear Reactor Regulation, Director 1p 22726 229 24X Fiche 50-445,84/03/20, B403230059.

G Inspection reports, IE Bulletina & correspondence

- 8403080324 FOIA request for documents considered by NRC in preparation of notice of violation & proposed imposition of civil penalty, 831222 ltr transmitting violation & rept of investigation re intimidation of 9A personnel HARTHAN, S.L. Debevoise & Liberman 83/12/30 FELTON, J.M. Division of Release and Records 2pp 22583 149 24% Fiche 50-445, 83/12/30, 8403080324
- 8403080325 Partial response to FOIA request for documents considered by NRC in preparation of three categories of documents concerning facilities Forwards documents listed on App A FELTON, J M Division of Rules and Records 84/01/20 HARTMAN.S L Debevoise & Liberman 2pp 22583 171 24X Fiche 50-445,84/01/20.8403080325
- --8403080327 Rev 27 to Procedure QI-QP-11 4-5 re visual defects insp & dry film thickness Related info encl

 * Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84711/08 6pp 28583 173 24X
 Fiche 50-445,84/01/20,8403080325
- --8403080332 Describes commitments made to NRC in RJ Gary 830928 response to notice of violation & proposed imposition of civil penalty CLEMENTS.B R Texas Utilities Electric Co (formerly Taxas Utilities Generating Co) 83/11/29 CCLLINS,J T Region 4. Dffice of Director 11pp 22583 182 24X Fiche 50-445,84/01/20,8403080335
- --8403080335 Forwards rept re investigation into allegations made by WA Dunham & concerns related to protective coatings Related documents oncl
 GARY, R J Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 83/12/13 CDLLINS, J Region 4, Office of Director 22pp 22583 204 24% Fiche 30-445,84/01/20,8403080325
- B403060431 Requests add1 info re ultrasonic exam of cast stainless steel piping in RCPB as part of preservice insp program Response requested within 5 days of ltr receipt YOUNGBLODD B J Licensing Branch 1 B4/02/24 GARY, R J Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 3pp 22552 047 248 Fitche 50-445.84/02/24.8403060431
- 8401190072 IE Info Notice 84-13. "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22909 239 24X Fiche 50-000.84/02/28.8401190072
- 8403130183 Forwards IE Inap Repts 50-445/83-47 & 50-446/83-22 on B30801-840117 No violations or deviations noted JOHNSON, E H Region 4, Office of Director 84/02/28 GARY, R J Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 2pp 22607 129 24x Fiche 50-445,84/02/28,8403130183
- --8403130217 IE Insp Repts 50-445/83-47 & 50-446/83-22 on 830801-840117 No violations or deviations noted Major areas inspected issues before ASLB hearing board TAYLOR.R G , HUNNICUTT,D M Region 4, Office of Director 84/02/28 4pp 22607 131 24X Fiche 50-445/84/02/28/8403130183
- 8403260069 Forwards evaluation of 8307i8 request for deletion of steam electric station license condition re low-pressure turbine disc insp NRC maintains position in SER (NUREG-0797) that insp must be conducted YOUNGBLOOD, B. J. Licensing Branch 1 84/02/28 OARY, R. J. Texas Utilities Electric Co. (formerly Texas Utilities Generating Co.) 2pp 22763 235 24% Fiche 50-445.84/02/28,8403260067
- --8403260081 Evaluation of util 830718 request to delete turbine disc insp license condition UT insps required at first refueling & every subsequent refueling outage * NRC - No Detailed Affiliation Given 84/02/28 17pp 22763 237 24% Fiche 50-445.84/02/28,8403260069
- 8402070007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list enc! GRACE, J N Division of GA, Enfequends & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22592;327 24X Fiche 50-000.84/03/02.8402070007
- 8402070008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list enc! JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008

- 8402090009 JE Info Notice 84-15. "Reporting of Radiological Releases "
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 1176p 22553 336 24X Fiche 50-000.84/03/05.8402090011
- 8402070024 IE Info Notice 84-09. Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list entl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New 24X Fiche 50-000.84/03/07.8402090024 York, Inc 118pp 22635 049
- 8402090028 IE Info Notice 84-18. "Stress Corrosion Cracking in PWR 102090028 It Info Notice 84-10: Street Commission Commission Sys " Svc list and I Sys " Svc list and I Sys " Svc list and I Sys " Sys " Svc list and I Sys " Sys "
- 8403190406 Informs that no insp repts will be issued for Rept Numbers 30-445/83-41 & 50-446/83-25 UDHNSON,E H Region 4, Office of Director 84/03/09 GARY,R J Texas Utilities Electric Co (formerly Texas Utilities Constraing Co) 1p 22674 357 24X Fiche 50-445.84/03/09.8403190406
- 8402070031 IE Bulletin 84-02. "Failures of OE Type MFA Relays in Use in Class IE Safety Sys " Svc list enc! DEYOUNG:R C Director's Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc i34pp 22823 094 24X Fiche 50-000.84/03/12,8402090031
- B40319011B Forwards NRC Insp Repts 99900530/B4-01 & 50-445/B3-52 of CYGNA Energy Svcs GA program used during Unit 1 independent assessment program No application to withhold rept received TREBY, S A Hearing Branch i B4/03/14 BLOCH, P B Atomic Safety and Licensing Board Panel 23pp 22666 273 24X Fiche 50-445.84/03/14,8403190118
- 8403200125 Forwards vendor insp repts for info & action Repts identify concerns found by Vendor Program Branch during insps of vendor activities Ack of itr receipt requested JOHNSON.E H Region 4. Office of Director 84/03/16 GARY,R J Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 3pp 22697 173 24X Fiche 50~445.84/03/16.8403200123
- 8402090043 IE Info Notice 84-19. "Two Events Involving Unauthorized Entries into PMR Reactor Cavities" Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 123pp 82823 229 24X Fiche 50-000,84/03/21,8402090043
- 8402070044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related POSTUDENT INTO NOTICE OF SOLUTION OF SUBJECT OF SUBJECT
- S Reportable occurrences, LERs & related correspondence
- 8403010451 Informs Commission of problems w/emergency diesel generators mfg by Transamerica Delaval. Inc DIRCKS,W J Office of the Executive Director for Operations SECY-83-034 84/01/25 4pp 22438 347 24X Fiche 50-000.84/01/25.
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines.Gimpel NPS-4 T&T valve.to close Enc1 ltr dtd 840203 sent to listed utils GE notified of affected units in AWR plants
 THERMUX.R R Terry Corp 84/02/22. WOODRUFF.R W Director's
 Office. Office of Inspection and Enforcement 6pp 22706 027 24X
 Fiche 50-006.84/02/22.8403210032
- 8403070256 Followup Part 21 rept re defective mechanical snubber capstan springs supplied by Pacific Scientific Affected utils listed Purchasers have been notified & advised to work directly w/Pacific Scientific in disposition HOVIrL NPS Industries, Inc 84/02/24 DEYOUNG, R C Direct Office, Office of Inspection and Enforcement 2pp 22536 279 Fiche: 50-000, 84/02/24, 8403070256.

- 8403010207 Forwards "Investigation of Types AF & AE Piston Skirts," per 0301020/ Forwards "Investigation of (upes AF & AE Piston Wirts," Transamenica Delaval, Inc. Umners Group program commitments Rept evaluates cracks in AF piston skirts in Bhoreham & Grand Qulf Nuclear Power Stations MUSELER.W J TDI (Transamerica Delaval, Inc.) Owners Group 84/02/27 DENTON, HR Office of Nuclear Reactor Regulation, Director 3pp 22434 090 24X Fiche 50-000, 84/02/27, 8403010207.
- 8402090021 Board Notification 84-039 discusses NRC 840210 & 16 meetings w/Transamerica Belaval, Inc Emergency Diesel Generators Dumers Group Meeting scheduled on 840308 for finalization of generic program plan prior to NRC review ETBENHUT, D G Division of Licensing 84/02/28 PALLADING Commissioners 5pp 22546 003 24X Fiche 50-000,84/02/28, 240000031
- 8403010218 Forwards task descriptions for 16 known problems re 40301021B Forwards task descriptions for 16 known problems re
 Transamerica Delaval, inc emergency diesel generators
 MUSELER, W J TDI (Transamerica Delaval, Inc.) Gwners Group
 84/02/28 DENTON, H R Office of Nuclear Reactor Regulation,
 Director 42pp 22435 177. 24% Fiche 30-000.84/02/28.8403010218
- 8408090020 Board Notification 84-044 forwards Part 21 rept re Transamerica Delaval. Inc turbocharger thrust bearing lubrication defect resulting in engine nonavailability EISENHUIT.D @ Division of Licensing 84/02/29 PALLADING Commissioners 4pp 22541: 263 24X Fiche 50-000,84/02/29. 8402090020
- 8403140048 Forwards "Grand Gulf Component Tracking Sys," "Shoreham Component Tracking Sys" & "Transamerica Delaval, Inc Diesel Generators Unders Group Program Plan," to resolve concerns w/smergency diesel generators MUSELER. W J Long Island Lighting Co 84/03/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22626,062 24X Fiche 50-000,84/03/02,8403140048
- -8403140095 "Transamerica Delaval, Inc Diesel Generators Cwners Group Program Plan "
 * TDI (Transamerica Delaval, Inc.) Owners Group 84/03
 261pp 22628:223 24% Fiche 50-000,84/03/02,8403140048
- 8403160213 Interim Deficiency Rept SDAR-125 re laminations & delaminations in cable tray support column in cable spread room Initially reported on 840111 Evaluation continuing Completion expected by 840515

 GARY.R J Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/03/06 JOHNSON.E H Region 4, Office of Director 1p 22655 231 24X Fiche 50-445,84/03/06,8403160213
- 8402090033 Board Notification 84-047 forwards Transamerica Dalaval, Inc. Owners Group piston skirt rept & task descriptions
 EISENHUT, D 0 Division of Licensing 84/03/07 PALLADING
 Commissioners 4pp 22674 221. 24% Fiche 50-000,84/03/07.
- 8402090038 Board Notification 84-051 forwards "Transamerica Delaval.Inc (TDI) Diesel Generators Owners Group Program Flan " EISEMHUT.D 6 Division of Licensing 84/03/12 PALLADINO Commissioners 5pp 22688 214 24X Fiche 50-000,84/03/12, 8402090038
- 8402090039 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delaval Inc (TDI) Owners Group Distribution EISENHUT, D @ Division of Licensing 84/03/12. PALLADINO Commissioners 5pp 22708 001 24% Fiche 50~000,84/03/12. 8402070039
- --B403060536 Forwards summary of B40210 meeting w/Transamerica Delaval.
 Inc Guners Group in Bethesda, MD re problems w/emergency
 diesel generators
 CARUSO.R Licensing Branch 2 B4/02/27 G'REILLY, J P NRG No
 Detailed Affiliation Given 6pp 22708 006 24X
 Fiche 50-000, B4/03/12: B402090039
- ---8403060554 Transcript of 840210 meeting w/Transamerica Deleval Inc Owners Group in Bethesda MD re problems w/emergency diesel generators

 * NRC - No Detailed Affiliation Given 84/02/10 147pp. 24X Fiche, 50-000, 84/03/12, 8402090039 47201 OOR
- --8403070409 Summary of 840216 meeting w/Transamerica belayel.inc Owners nosovorum summany or sauzia meeting w/fransamerica Delaval Inc Group in Wading River, NY re program plan to establish reliability of diesel generators Agenda, meeting transcript & attendance list encl MILLER, M A Licensing Branch 4 84/02/27. Licensing Bran Bpp. 22708-161 24X Fiche 50-000,84/03/12,8402090039 Licensing Branch 4.

- --8403070423 Transcript of 840214 conference in Wading River, NY re Transamerica Delaval. Inc diesel generators Pp 1-82 * Commissioners 84/02/16 84pp 22708 169 2 Fiche 50-000,84/03/12,8402090039
- 8403140050 Forwards "Design Review of Connecting Rod Bearing Shells for Fransamerica Delaval Enterprise Engines" for Shoreham & Grand Gulf diesel generators
 MUSELER,N J Long Island Lighting Co 84/03/12 DENTON,H R
 Office of Nuclear Reactor Regulation, Director 2pp 22632 074
 24% Fiche 50-000,84/03/12,8403140050
- 8403150133 Forwards "Transamerica Delaval.Inc Diesel Generator Rocker Arm Capscrew Stress Analysis Rept " Capscrew design adequate for applicable engines & svc conditions MUBELER.W J TDI (Transamerica Delaval. Inc.) Owners Group MUBELER.W J TDI (Transamerica Delaval, Inc.) Owners Group 84/03/13 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 22639 270 24X Fiche 50-000,84/03/13,8403150133
- 8403200222 Responds to 840214 Requests for Info 1 & 2 re R-4 series engines List indicating engine number model & svc number, customer name & address rating, date shipped & date started WATHEWS.C S Transamerica Delaval, Inc. 84/03/16 EISENHUT,D G Division of Licensing 20pp 22691 179 24X Fiche 50-000,84/03/16, 8403200222
- 8403270132 Forwards "Emergency Diesel Generator Air Start Valve Capscrew Dimension & Stress Analysis." prepared by S&W for Transamerica Delaval, Inc (TDI) Diesel Generator Owners Group MUSELER,W J TDI (Transamerica Delaval, Inc.) Owners Group. 84/03/23 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp. 22774 001 24X Ficha 50-000.84/03/23,8403270132
- 8403270134 Requests meeting on 840418 to discuss short-term & long-term corrective actions & investigations re Transamerica Delaval diesel generators List of suggested meeting topics encl MCGAUGHY, J P MCGAUGHY, J P TDI (Transamerica Delaval, Inc.) Owners Group 84/03/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 22769 133 24X Fiche 50-000, 84/03/23, 8403270134
- T. Hearing transcripts on non-antitrust matters
- 8403020145 Transcript of 840228 telephone conference in Bethesda. MD Pp 10, 350-10, 383 * Atomic Safety and Licensing Board Panel 84/-22440 275 24% Fiche 50-445,84/02/28,8403020145 84/02/28 35pp
- 8403090104 Forwards correction to J Doyle 840222 testimonu Related correspondence

 ELLIB.J. Citizens Association for Sound Energy 84/03/05

 BLQCH.P B. JORDON,W H. MCCOLLOM.K A Atomic Safety and Licensing
 Bloand Panel 1p 22376 081 24X Fiche 50-445.84/03/05.8403090104
- --B403090108 Affidavit of J Doyle, correcting 840222 testimony during cross-examination of CYGNA Certificate of Evc encl DOYLE, J Citizens Association for Sound Energy 84/03/03 7pp 22876 082 24% Fiche 50-445.84/03/05.8403090104
- 8402090039 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 14 meetings between NRC & Transamerica Delayal, Inc (TDI) Owners Group Distribution list encl
 EISENHUT.D.9 Division of Licensing 84/03/12 PALLADIND
 Commissioners 5pp 22708.001 24X Fiche 50-000.84/03/12,
 84/02070037
- --B403060536 Forwards summary of 840210 meeting w/Transamerica Delaval, Inc Owners Group in Bethesda,MD re problems w/emergency diesel generators CARUBO.R Licensing Branch 2 84/02/27. D'REILLY,J.P. NRC No CARUBO.R Licensing Branch 2 84/02/27. O'REILLY, J. P. NRC - No Datailed Affiliation Given. App 22708 006 24X Fichs; 50-000, 84/03/12, 8402090039
- --B403060554 Transcript of 840210 mesting w/Transamerica Delayal, Inc Owners Group in Bethesda, MD re problems w/emergency diesel generators No Detailed Affiliation Given 84/02/10 147pp. 8. 24% Fiche 50-000,84/03/12,8402090039 67201 008.
- ~-8403070407 Summary of 840216 meeting w/Transamerica Delaval. Inc Owners Group in Wading River, NY re program plan to establish reliability of diesel generators Agenda. meeting transcript & attendance list encl
 MILLER, M.A. Licensing Branch 4 84/02/27 Licensing Branch 4 8pp 22708:161 24X Fichs 50-000,84/03/12,8402070037

- --8403070423 Transcript of 840216 conference in Wading River, NY re Transamerica Delaval. Inc diesel generators Pp 1-82
 * Commissioners 84/02/16 84pp 2270B 169 2:
 Fiche 50-000, 84/03/12, 8402090039
- 8403260008 Transcript of 840319 hearing in Fort Worth, TX Pp 10,384-10.715 # Atomic Safety and Licensing Board Panel 84/03/19 340pp 22747 001 24X Fiche 50-445,84/03/19,8403260008
- 8403270167 Transcript of 840321 hearing in Fort Worth, TX Pp 11,019-11,318 .314 Atomic Safety and Licensing Board Panel 84/03/21 349pp 774 150 24X Fiche 50-445.84/03/21.8403270167
- 8403270082 Transcript of 840322 hearing in Fort Worth, TX Pp 11,337-11,710 * Atomic Safety and Licensing Board Panel 84/03/22 373pp 22745 009 24X Fiche 50-445.84/03/22.8403270082
- 8403280021 Transcript of 840323 hearing in Fort Worth.TX Po 11.711~ * Atomic Safety and Licensing Board Panel 84/03/23 300pp 22777 173 24X Fiche 50-445,84/03/23,8403280021
- V Operator Examinations
- 8403130160 Forwards nuclear plant experience tables for shift advisors, shift supervisors, assistant shift supervisors, reactor operators & shift technical advisors Expected OL & fuel load dates are 840701 CLEMENTS. B R Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 84/03/08 DENTON. H. R Office of Nuclear Reactor Regulation, Director 8pp 22608 238 24% Fishe 50-445, 84/03/08. 8403130160
- DOCKET STN-50-447 GESSAR-238
- A Application/construction stage documents & correspondence
- 8403010013 Further response to FDIA request for documents re PRA & evacuation time estimates Forwards "Review & Evaluation of OEBSAR-II PRA-Containment Failure Modes & Fission Froduct Release " Rept partially withheld (ref FDIA Exemption 4) FELTON, J M Division of Rules and Records 84/01/03 HIATT, 9 Ohio Citizens For Responsible Energy 4pp 22445 276 24X Fiche 50-447, 84/01/03, 8403010013
- --8308170191 "Review & Evaluation of GESSAR-II Probabilistic Risk Assessment Containment Failure Modes & Fission Product Release," itr rept * Brookhaven National Laboratory Systems Integration (post 811005) Fiche 50-447,84/01/03/8403010013 83/07/27 Divis 180pp 66922 190
- 8403300216 Notification of 840320 meeting w/GE & BNL in Bethesda.MD to discuss source term reanalysis & results of sensitivity studies on parameters affecting fission product release SCALETTI.D Standardization & Special Projects Branch 84/03/15 THOMAS, C O Standardization & Special Projects Dranch 3pp 22845 045 24% Fiche 50-447,84/03/15,8403300216
- S Reportable occurrences, LERs & related correspondence
- 8403260233 Forwards summary list of deficiencies identified per 10CFR50 55(e), Part 21 & potential generic ltr repts for camments comments
 STAROSTECKI,R Division of Project & Resident Programs 84/02/28
 Region 1, Office of Director 7pp 22754 065 24X
 Fiche 50-000.84/02/28,8403260233
- DOCKET SYN-50-454 BYRON STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8403010106 Forwards addl info re design of Category 1 masonry walls Rept identifies all cracks & explains why cracks do not compromise structural integrity of walls TRAMM.TR Commonwealth Edison Co 84/02/22 DENTON.HR Offic of Nuclear Reactor Regulation, Director 16pp 22436 041 24X Fiche 50-000.84/02/22.8403010106 Office
- 8402090017 Board Notification 84-039 forwards RJ Mattson 840123 memo to DO Eisenhut providing status update of NRC actions re Wastinghouse ECCB actuation logic EISENHUT.D G Division of Licensing 84/02/27 PALLADING Commissioners 7pp 22546 007 24X Fiche 50-000,84/02/27. 8402090017

- 8403050245 Forwards revised info re preservice exam & testing of snubbers at facilities Enct testing program supercedes program provided in 820319 ltr & accepted in SSER 12 TRAMM.T R Communication Co. 84/02/28 DENTON.H R O. of Nuclear Reactor Regulation. Director 1p 22516 013 24X Fiche: 50-000.84/02/28.8403060245 ER 12 DENTON H R OF Office
- ~~8403060267 Rev 1 to "Preservice Testing (Preservice Insp) Program Plan for Snubbers " # Commonwealth Edison Co 83/10/21 47pp 22516 014 24X Ficha 50-000.84/02/28,8403060245
- 8403060374 Advises of changes to schedules for initial fuel loading of facilities Requests NRC resources be allocated to support fuel load after resolution of pending license appeal REED.C Commonwealth Edison Co 84/02/29 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 22518 150 24X Fiche. 50-000.84/02/28.8403060374 Office of
- 8403050117 Forwards supplemental response to Generic Ltr 83-28.

 "Required Actions Based on Generic Implications of Salem
 ATMS Events "
 BARNES.P.L Commonwealth Edison Co 84/02/27 DENTON.H R Ofof Nuclear Reactor Regulation. Director 26pp 22486 084. 24X
 Fiche 50-000.84/02/27,8403050117 Office
- 8403260018 Trip rept of B31107-09 site visit to conduct second seismic qualification review team audit Appropriate seismic & dynamic qualification program defined to assurance that equipment will function properly LEE, A Equipment Qualification Branch 84/03/05 NOONAN, V S Equipment Qualification Branch 5pp 22763 306 24X Fiche 50-454,84/03/05.8403260018
- --8403260022 Forwards review comments in SSERs for second seismic qualification review team audit Addendum rept includes some resolutions based on applicant 840103 submittal SUBUDHIAN Brookhaven National Laboratory, 84/01/31 NOONAN Equipment Qualification Branch 20pp 22763.311 24X Fiche 50-454,84/03/05,8403260018 NOONAN, V.
- 8403260057 Trip rept of 821113-17 site visit to conduct seismic qualification review team audit w/BNL personnel Appropriate seismic & dynamic qualification program defined to assure equipment operation during & after SBE LEE, A Equipment Qualification Branch B4/03/05 NOONAN, V S Equipment Qualification Branch 5pp 22763 256 24X Fiche 50-454.84/03/05.8403260057
- --B403260061 Forwards review comments on SSERs for second seismic qualification review beam audit Based on audit findings.
 equipment qualification status at plant satisfactory SUBUDHI, M Brookhaven National Laboratory 84/01/31 NDONAN Equipment qualification Branch ,20pp 22763 261 24X Fiche 50-454,84/03/05,8403260057 NOONAN, V S
- 8402090041 Board Notification 84-050 provides Commission policy statement & proposed rulemaking on environ qualifications FIBENHUT. DO Division of Licensing 84/02/14 Atomic Safety and Licensing Board Panel 10pp 24X Fiche 50-000.84/03/14.8402090041
- 8403220133 Forwards info re experience level of individuals assigned to shift operating positions, in response to request Tabulation showing experience of shift engineer, shift foreman station control room engineer & operator enci TRAMM-T R Commonwealth Edison Co 84/03/19 DEMTON, H R Office of Nuclear Reactor Ragulation, Director 7pp 22716 030 24X Fiche: 50-454.84/03/19.8403220133
- 8403260182 Charifies NUREG-0737, Item II K 3 31.in response to Generic Ltr 83-35 Westinghouse Owners Group authorized program to demonstrate conservatism of WFLASH small break LOCA analyses.per Item II K 3 30 BARNEG.P L Commonwealth Edison Co 84/03/21 EISENHUT.D G Division of Licensing 1p 22756 170 24X Fiche 50-000.84/03/21, 8403260182
- E. NRC Safety Evaluation Report (SER), supply & correspondence
- 8403080179 Fourth partial response to FOIA request for aix categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Examption 5). Review of add1 documents subj to request continuing FELTON.J M Division of Rules and Records 84/02/13 ANDERSON,S I Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000.84/02/13,8403080179
- --8005130793 Provides status of SER inputs & acceptance reviews for OL & CP applications Schedule should be met
 BURKE.W C Effluent Treatment Systems Branch 80/02/06.
 KREGER.W E Assistant Director for Site Analysis ip. 22583 235
 24X Fiche 50-000.84/02/13.8403080179

- 8403010120 Forwards addl info to 831230 submittal re NUREO-0737. Item III D 1 1. "Primary Coolant Outside Containment " Rev identifies portions of sys not to be tested & responds to NRC comments Info should close SER Confirmatory I sake 20 TRAMM.T R Commonwealth Edison Co 84/02/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 8pp 22432 002 24X Fiche 50-000.84/02/22.8403010120 Office
- 8403010286 Provides addl info re effects of local intense precipitation at facilities Info resolvas Confirmatory Issua A 2 identified in SER Reinforced concrete curbs provided at exterior grade floor level doors FRAMM. T R Commonwealth Edison Co 84/02/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22434 257 24X Fiche 50-000.84/02/22.8403010286
- 8403260132 Submits add! info re design of hydrogen recombiners per Section 6 2 5 of SER Hydrogen recombiners operate in parallel utilizing same suction & exhaust piping for each containment Diagram encl containment Diagram encl containment Diagram encl containment Diagram encl dison Co 84/02/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22758:147. 24X Fiche: 50-000, 84/02/22, 8403260132 Office
- 8403060345 Forwards "Rept Qeatechnical Svcs Seismic Crasshole Survey & Dynamic Soil Properties at River Screenhouse, Byron Station Units 1 & 2 " Info closes out SER Confirmatory Issue 1 & responds to two FEAR questions

 TRAPM, T R Commonwealth Edison Co 84/02/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 22511 136 24X Fiche 50-454,84/02/28,8403060345
- --8403060347 "Rept Geotechnical Svcs Beismic Crosshole Survey & Dynamic Soil Properties at River Screenhouse, Byron Station Units 1 & 2 " 1 & 2 " * Dames & Moore 84/02/06 22pp 22511,137 24X Fichs 50-454,84/02/28,8403060345
- 8403260018 Trip rept of 831107-09 site visit to conduct second seismic qualification review team audit Appropriate seismic & dynamic qualification program defined to assurance that equipment will function properly LEE, A Equipment Qualification Branch 84/03/05 NOONAN, V 8 Equipment Qualification Branch Spp 22763 306 24X Fiche 50-454,84/03/05,8403260018
- --8403260022 Forwards review comments in SSERs for second seismic 003260022 Forwards review comments in SSERs for second saism qualification review team audit Addendum rept includes some resolutions based on applicant 840103 submittal SUBUDHI,M Brookhaven National Laboratory, 84/01/31 NOO Equipment Qualification Branch 20pp 22763 311 24X Fiche 50-454,84/03/05,8403260018 NOONAN, V
- 8403260057 Trip rept of 82i1i3-i7 site visit to conduct seismic qualification review team audit w/BNL personnel Appropriate seismic & dynamic qualification program defined to assure equipment operation during & after 85E

 LEE, A Equipment Qualification Branch 84/03/05 NODNAN, V S Equipment Qualification Branch 5pp 22763, 256 24X

 Fichs 50-454,84/03/05,8403260057
- --8403260061 Forwards review comments on SSERs for second seismic qualification review team audit Based on audit findings, equipment qualification status at plant satisfactory SUBUDHI.M Brookhaven National Laboratory 84/01/31 NDONAN Equipment Qualification Branch 20pp 22763.261, 24X Fiche. 50-454,84/03/05,8403260057 NOONAN, V. S
- F Security, medical, emergency & fire protection plans
- 9403070347 Public version of revised emergency plan implementing procedure index W/840215 transmittal form & JM Felton 840302 release memo * Commonwealth Edison Co 84/01/20 18pp 22566 041. 24% Fiche 50-454, 84/01/20, 8403070347
- 8403010403 Rev O to Procedure BZP 500-Ti. "Checklist-Communication * Commonwealth Edison Co 84/02 Fiche 50-454,84/02/18,8403010403 84/02/18 7pp, 22433-104 24X
- 8403020198 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licenses, per BiO709 Generic Ltr 81-27 W/o request, entire plan will be placed in PDR YOUNOBLOOD:B J Licensing Branch 1 84/02/21 FARRAR,D L Commonwealth Edison Co 2pp 22474 360 24X Fiche 50-000,84/02/21.840300198

- 8402070006 Board Notification 84-034 forwards R Vollmer 840206 memo to D Eisenhut re fire research results concerning fires in electrical cabinets in control room EISENHUT, D G Division of Licensing 84/02/23 PALLADIND Commissioners ip 22576 203 24% Fiche 50-000,84/02/23,8400900004
- --8403080316 Recommends that info re fire research results concerning fires in electrical cabinets in control room be submitted for board notification.per NRR Dfc Ltr 19, dtd 821001 Further evaluation of test data required VOLLMER.R H Division of Engineering 84/02/06 EISENHUT.D G Division of Licensing 10pp 22576 204 24X Fiche 50-000,84/02/23.8402090006
- 8403010336 Forwards IE Safeguards Insp Rept 50-454/84-12 on 840208-10 No noncompliance noted AKELSON,W L Region 3, Office of Director 84/02/28 REED.C Commonwealth Edison Co 2pp 22433 039 24X Fiche 50-454,84/02/28. B403010336
- --B40301034B IE Safeguards Insp Rept 50-454/84-12 on B40208-10 No noncompliance noted Major areas inspected organization & operation measurement & controls & storage & internal controls Details withheld (ref 10CFR2 790) MADEDA, T J, CREED, J R Region 3, Office of Director 84/02/28 2pp 22433 041 24X Fiche 50-454,84/02/28,8403010336
- 8403120162 Rev 0 to Procedure BIP 500-1. "Operation Checks of Communications Sys " W/840320 transmittal & receipt form # Communealth Edison Co 84/02/28 4pp 22590 144 24x Fiche 50-454.84/02/28.8403120162
- 8403050162 Forwards FEMA 840201 ltr, final exercise evaluations on 831115 offsite emergency preparedness exercise & interim finding recommendations rate offsite emergency response plan for area around facility No deficiencies identified PAPERIELLO, C. J. Region 3, Office of Director 84/02/29 REED, C. Commonwealth Edison Co. 2pp. 22483 061 24X Fiche 50-434,84/02/29,8403050162
- 8403120109 Notifies of 840323 workshop on fire protection safe shutdown requirements of 10CFR50.App R in Rosemont. IL to discuss IE Info Notice 84-09 & provide add1 shutdown analyses &/or mod guidance Agenda encl
 SPE88ARD.R L Division of Emergency Preparedness & Operational Support 84/03/06 REED, C Commonwealth Edison Co 3pp 22588 163. 24% Fiche 50-454.84/03/06.8403120109
- 8403150044 Rev 1 to Procedure BZP 380-7. "Estimation of Offsite Dose From Unplanned Release of Radioactive Effluents " W/B30310 transmittal form # Commonwealth Edison Co 84/03/07 App 22643 130 24X Fiche 50-454.84/03/07.8403150044
- 8403190308 Rev 2 to Procedure BZP-600-A3 "Station Directory & Mgt Personnel Home Phone List " W/840312 transmittal ltr # Commonwealth Edison Co 84/03/12 9pp 22673 265 24X Fiche: 50-454.84/03/12.8403190308
- 8403260346 Rev 1 to Emergency Plan Implementing Procedure BZP 380-3. "Post-Accident Stack Sampling of Wide-Range Gas Monitor (WRGM)" + Commonwealth Edison Co 84/03/15 5pp 22751 055 24X Fiche: 50-000.84/03/15.8403260346
- 8403140190 Emergency plan implementing procedures index H/840329 transmittal & receipt form # Commonwealth Edison Co 84/01/20 17pp 22620 216 24X Fiche 50-454.84/03/27.8403140190
- Q. Adjudicatory correspondence
- 8403140035 Requests reconsideration of decision to bar facility from starting up Util most experienced w/nuclear plants & revs will result in corrective actions HOPKINSR. Affiliation Not Assigned 84/02/20 NRC No Detailed Affiliation Given 2pp 22634 159 24X Fiche 50-454,84/02/20, P8403140035.
- 8403020181 Forwards "Rept on Byron QC Inspector Reinspection Program" BIELAWSKI, A P Isham, Lincoln & Beale DIELAWSKI, A P Commonwealth Edison Co 84/02/27 ROSENTHAL A S. GOTCHY, R L , KOHL, C W Atomic Bafsty and Licensing Appeal Panel 224pp 22440 311 24X Fichs 80-454,84/02/27,8403020181
- 8403060079 Advises of issues to be addressed in 840312 brief, per 840127 request. WHICHER, J M Businessmen for the Public Interest 84/03/01 ROSENTHAL, A S , KOHL, C W , GOTCHY, R L Atomic Safety and Licensing Appeal Fanel 1p 22516 338 24X Fiche 50-454,84/03/01,8403060079

- 8403140129 Advises that staff unable to accelerate schedule for filing of appellate brief on GA, need for power & alternative energy sources, financial qualifications & seismology Brief will be filed by 840330 RAWSON, RJ Hearing Branch 4 84/03/06 ROBENTHAL, AS, KOHL, CN, ODTCHY, RL. Atomic Safety and Licensing Appeal Panel 1p 22624 204 24X Fiche 50-454.84/03/06.8403140129
- B403140146 Forwards Paperiello 840229 ltr to C Reed forwarding FEMA interim finding on offsite radiological emergency planning NRC will address interim finding in SSER RAWBON.R J Hearing Branch 4 B4/03/06 ROSENTHAL, A S. ODTCHY, R L. KCHL.C N Atomic Safety and Licensing Appeal Panel 22pp 22624 212 24X Fiche 50-454.84/03/06.8403140146
- 8403140068 Forwards potentially relevant documents & matl to matters pending before ASLAB W/o encis RAWSON.R J Hearing Branch 4 84/03/07 ROSENTHAL, A S , KOHL, C N , GOTCHY.R L Atomic Safety and Licensing Appeal Panel 2pp 22633 079 24X Fiche 50-454.84/03/07.8403140088
- 8403140148 Forwards IE Insp Repts 50-454/83-61,50-455/83-41,50-454/84-02,50-455/84-02,50-455/83-83,50-455/83-43,50-454/84-05,50-455/84-04,50-454/84-06 & 50-455/84-05 per requirements of ALAR-143 RAWSON,R J Hearing Branch 4 84/03/07 ROSENTHAL,A S, GUTCHY,R L, KOML,C N Atomic Safety and Licensing Appeal Panel 74pp 22625 086 24X Fiche 50-454,84/03/07,8403140148
- 8403070102 Memorandum scheduling B40417 oral argument in Bethesda.MD repending appeal Formal argument will be issued in early Apr SHOEMAKER.C J Abonic Safety and Liconsing Appeal Panel 84/03/08 2pp 22975 356 24% Fires 50-454,84/03/08.8403090102
- 8403160002 Response opposing applicant alternative motion to reopen record & vacate ASLB denial of DL Motion would be considered acceptable under single issue of reinspection program Centificate of Svc encl HHICHER, J M DEKAID Area Alliance for Responsible Energy WHICHER, J M Whicher, J M 84/03/12 Atomic Safety and Licensing Appeal Panel 11pp 22655 198 24X Fiche 50-454,84/03/12,8403140002
- 8403160019 Brief in response to applicant appeal of ASLB 840113 initial decision denying DL application ASLB properly denied DL HHICHER.J M. ACASEL.D W. Dekalb Area Alliance for Responsible Energy WHICHER.J M. Whicher. J.M. 84/03/12. Atomic Safety and Licensing Appeal Panel 64pp 22653 225 24x Fichs 50-454. 84/03/12.8403160019
- 8403140041 Memorandum changing proposed date for oral argument of pending appeal from 840417 to 0419 SHOEMAKER.C J Atomic Safety and Licensing Appeal Panel 84/03/13 ip 22634 ldi 24% Fichs 50-454.84/03/13.8403140041
- 8403200122 Discusses util 840218 & 0314 nonconformance repts rediscrepant welds in cable pan hangers supplied by System Control Corp Earlier nonconformance repts rematter issued in 1977 at Ugron Related correspondence MILLER, M I Isham, Lincoln & Beale MILLER, M I Commonwealth Edison Co 84/03/14 KOHL, C W. GOTCHY, R L. ROSENTHAL, A S Atomic Safety and Licensing Appeal Panel 2pp 22699 045 24% Fiche 50-454,84/03/14,8403200122
- 8403240351 Forwards listing of errata in 840312 brief HHICKER, J M Businessmen for the Public Interest WHICKER, J M Whicher, J M D5B 070 84/03/22 KCHL, C N, GOTCHY, R L, ROSENTHAL, A S Atomic Safety and Licensing Appeal Panel 3pp 22760 257 24X Fiche 50~454.84/03/22.8403260351
- M Antitrust correspondence
- 8403270376 Forwards staff significant change analysis W/o enci Related correspondence VOGLER: B H Hearing Branch 2 DSB 180 84/03/28 LIEBERMAN, M Affiliation Not Assigned ip 22814 122 24X Fiche 50-454. 84/03/28,8403270376
- Q Inspection reports, IE Bulletins & correspondence
- 8403010130 Revises & supple preservice insp program plan, in response to NRC comments & suggestions Addl info re exam of cast stainless steel components provided Revised Relief Request NR-14 & Note 8 and I for NRC approval TRAMM.TR Commonwealth Edison Co 84/02/17 DENTON, HR Office of Nuclear Reactor Regulation. Director 5pp 22435 342 24X Fiche 50-454,84/02/17,8403010130
- 8403010083 Forwards final rept on Byron GA inspector reinsp program DELOEORGE.L O Commonwealth Edison Co 84/02/24 KEPPLER, J G Region 3. Office of Director ip 22434 268 24X Fiche 50-454,84/02/24,8403010083

- ---8403010087 Final "Rept on Byron Inspector Reinsp Program"
 4 Commonwealth Edison Co 84/02/29 283pp 22434-270 24x
 Fiche 50-454,84/02/24,8403010083
- 8403050043 Forwards Rev O to "Corporate Regulatory Performance Improvement Plan "Plan designed to heighten employee awareness & strengthen corporate ability to improve regulatory performance THOMAS, B Commonwealth Edison Co 84/02/24 KEPPLER, J G Region 3, Office of Director 3pp 22490 139 24X Fiche 50-000,84/02/24,8403050043
- 8403020181 Forwards "Rept on Byron QC Inspector Reinspection
 Program"
 BIELAHSKI,A P Isham, Lincoln & Beale BIELAHSKI,A P. Commonwealth
 Edison Co 84/02/27 ROSENTHAL,A S., GOYCHY,R L., KÜHL,C W Atomic
 Safety and Licensing Appeal Panel 224pp 22440 311 24X
 Fiche 50~454,84/02/27.8403020181
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22909 239 24X Fiche 50-000.84/02/28,8401190072
- 8403010336 Forwards IE Safeguards Insp Rept 50-454/84-12 on 840208-10 No noncompliance noted AXELSON, W. L. Region 3, Office of Director 84/02/28 REED, C Commonwealth Edison Co 2pp 22433 039 24X Fichs 50-454.84/02/28. 8403010334
- --8403010348 IE Safeguards Insp Rept 50-454/84-12 on 840208-10 No noncompliance noted Major areas inspected organization & operation measurement & controls & storage & internal controls Details withheld (ref 10CFR2 790) MADEDA: T J CREED. J R Region 3, Office of Director 84/02/28 2pp 22433 041 24X Fiche 50-454:84/02/28,8403010336
- 8403060245 Forwards revised info re preservice exam & testing of snubbers at facilities Encl testing program supercedes grogram provided in 820319 ltr & accepted in 85ER 12 FRAMH, T.R. Commonwealth Edison Co. 84/02/28 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 1p. 22516-013 24X Ficher 50-000, 84/02/28, 8403040245
- --8403060267 Rev 1 to "Preservice Testing (Preservice Insp) Program Plan for Snubbers " * Gammonwealth Edison Co 83/10/21 47pp 22516 014 24X Ficks 50-000,84/02/28.8403060245
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list enc! GRACE. J N Division of GA. Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Ca of New York, Inc 130pp 22552 329 24x Fiche 50-000.84/03/02.8402090007
- 8402090008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York Inc 122pp 22953 098 24X Fiche 50-000,84/03/02,8402090008
- 8402070007 IE Info Notice 84-15. "Reporting of Radiological Releases Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 119pp 22553 217 24X Fiche 50-000,84/03/02,8402070009
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp." Svc list encl JURDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co. of New York, Inc. 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8403190297 Forwards IE insp Repts 50~454/84~04 & 50~455/84~03 on 840123~26 No noncompliance identified.
 LITLE, W 8 Region 3, Office of Director 84/03/05 REED, C Commonwealth Edison Co 2pp 22673 255 24% Fiche 50~454,84/03/05,8403190297.
- --8403190305 IE Insp Repts 50-454/84-04 & 50-455/84-03 on 840123-26 No noncompliance or deviations identified Major areas inspected closeout of open items & deficiency items & as-built walldown of structural steel framing & supports XEATING.D E , DANIELSON.D H Region 3, Office of Director 84/03/05 6pp 22673 257 24X Fiche 50-454.84/03/05,8403190297

- 8403200295 Forwards IE Insp Rept 50-454/83-60 on 831212-16 & 27 & notice of violation SPESSARD.R L. Division of Emergency Preparedness & Operational Support 84/03/06 REED, C. Commonwealth Edison Co. 2pp 22696 234 24% Fiche 50-454,84/03/06.8403200295
- --8403200277 Notice of violation from insp on 831212-16 & 27 8FESBARD,R L Division of Emergency Preparedness & Operational Support 84/03/06. 1p 22676 236 24X Fiche 50-454,84/03/06. 8403200295
- --B403200300 IE Insp Rept 50-494/83-60 on 831212-16 & 29 Noncompliance noted sensing line connections to safety-related instruments ILT-0329,39 & 49 installed contrary to Sargent & Lundy Drawing Beries M-2036 requirements MENDEZ.R. WILLIAMB.C.C. Region 3, Office of Director 84/02/27 9pp 22696 237 24% Fiche 50-454,84/03/06,8403200295
- 8402090024 IE Info Notice 84-09. Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " 8vc list encl JORDAN,E 1. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York. Inc 118pp 22635 049. 24X Fiche 50-000.84/03/07.8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PMR Sys " Svt list entl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8403220074 Forwards IE Insp Repts 50-454/84-10 & 30-455/84-08 on B40131.0201-03 & 07-10 No noncompliance noted PAPERIELLO,C J Region 3, Office of Director 84/03/07 REED,C Commonwealth Edison Co 2pp 22716 311 24X Fiche 50-454.84/03/07. RA01320094
- --8403220097 IE Insp Repts 50-454/84-10 & 50-455/84-08 on 840131,0201-03 & 07-10 No moncompliance noted Major areas inspected preoperational radiation protection program including organization, staffing, training & NUREG-0737 items HUCTER.L. J. ORROER,L. R. Region 3. Office of Director 84/03/07 ilpp 22716 313 24X Fiche 50-454,84/03/07,8403220094
- 8403190268 Ack receipt of 840223 ltr informing NRC of steps taken to correct violations re steam generator snubber qualification tests noted in IE Insp. Repts 50-454/84-08 & 50-455/84-06 LITTLE.W S Region 3. Office of Director 84/03/08 REED.C Commonwealth Edison Co ip 22672 226 24% Fiche 50-454.84/03/08.8403190268
- --8403190274 Responds to NRC 840206 ltr re violations noted in IE Insp Repts 30-454/84-08 & 50-455/84-06 Corrective actions leak on snubber repaired & quasi-static structural test combined w/fluid stiffness calculation performed SWARTZ.E D Commonwealth Edison Co 84/02/23 KEPPLER.J O Region 3. Defice of Director Spp 22672 227 24X Fiche 50-454,84/03/08.8403190268
- --8403190278 Preliminary Spec 120, "Testing Sycs for Steem Generators." * Sargent & Lundy, Inc 84/02/22 38pp 22672 232 24X Fiche 50-454,84/03/08,8403190268
- 8403220245 Ack receipt of 831230 response to IE Insp Rept 50-454/83-23 Add1 insp of internal flooding & postulated cracks & breaks in high-energy & moderate-energy lines will be conducted during wk of 840317
 DEYGUND.R C Director's Office. Office of Inspection and Enforcement 84/03/09 REED.C Commonwealth Edison Co 3pp 22723-336 24X Fiche 50-454.84/03/09.8403220245
- 840209003f IE Builetin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl PEYOUNG.R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24% Fiche 50-000.84/03/12.8402070031.
- 8403300017 Forwards IE Insp Rept 50-454/84-07 on 840123-0225 & notice of violation STRETER.JF Region 3, Office of Director 84/03/13 REED.C R Commonwealth Edison Co 2pp 22822 148 24% Fiche 50-454,84/03/13,8403300017

- --8403300023 Notice of violation from inep on 840123-0225 BTREETER, J F Region 3. Office of Director 84/03/13 2pp 22022 150 24X Fiche 50-454,84/03/13,8403300017
- --B403300030 IE Insp Rept 50-454/84-07 on 840123-0225 Noncompliance noted failure to adequately evaluate preoperational test procedure regults & failure to adequately document personnel instruction corrective actions RINO, M. WILLIAMS, D. VANDENBUROH, C. Region 3, Office of Director 84/03/12 13pp 22822 152 24% Fiche 50-454,84/03/13,8403300017
- 8403230088 Ack receipt of regulatory performance improvement plan Periodic meetings requested to discuss progress on program & provide feedback KEPPLER, J G Region 3, Office of Director 84/03/20 THOMAS, B Commonwealth Edison Co ip 22730 161 24% Fiche 50-000,84/03/20, 8403230088
- --B403230126 Rev O to "Corporate Regulatory Performance Improvement Plan For Dresden, Quad Cities, Zion & LaBalle Operating Nuclear Stations & Byron & Braidwood Project Operating Organizations " # Commonwealth Edison Co 84/02/27 22pp 22730 165 24X Ficher 30-000,84/03/20,8403230088
- 84032&019& Forwards responses to IE Bulletin 83-07, "Apparently Fraudulant Products Sold by Ray Milter, Inc " Quad Cities supplied w/piping matis from Ray Miller, Inc during const Evaluation encl Concerns of IE Bulletin 83-05 actisfied. BARNES, P L Commonwealth Edison Co 84/03/20 KEPPLER, J, Q Region 3, Dffice of Director, 19pp. 22756 185 24% Fiche 50-000,84/03/20,8403260196.
- B403270111 Forwards response to IE Bulletin 80-15, "Emergency Notification Bys (ENS) Power Bupplies " ENS tested & found functional during preoperational testing BARNES, F.L. Commonwealth Edison Co 84/03/20 KEPPLER. J Q Region 3, Office of Director 3pp 22774 048 24X Fichs. 50-454,84/03/20, B403270111
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103), 84/03/21 Consolidated Edison Co of New York, Inc 123pp. 22823 229 24X Fiche 50-000.84/03/21.8402090043
- B402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys." Byc list encl.
 JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Fost 830103), 84/03/21 Consolidated Edison Co. of New York
- 8403260226 Ack receipt of 840227 ltr informing NRC of steps taken to correct noncompliance noted in IE Insp Rept 50-454/83-54.

 LITTLE, W B. Region 3, Office of Director 84/03/21 REED, C Commonwealth Edison Co 2pp 22755:145 24X Fiche 50-454,84/03/21.
 8403260228.
- --8403260237 Responds to NRC B31212 ltr re violations noted in IE Insp Rept 50-454/83-54. Corrective actions. Conduit C1A51A6 seatlight fitting loosened & rotated to attain separation from Conduits C1A4102 & C1A51E4 FARRAR, D. L. Commonwealth Edison Co. 84/02/27 KEPPLER, J G Region 3, Office of Director. 4pp 22755, 147 24X Fiche: 50-454, 84/03/21, 8403260228
- 8403270246 Forwards SALP Repts 30-454/B3-22, 30-455/B3-18, 30-456/B3-06 & 30-457/B3-06 for 1982 Increased emphasis required in areas of HVAC & electrical system (EPPLER, J G. Region 3, Office of Director E4/03/22 REED, C Commonwealth Edison Co 7pp 22770 135. 24X Fiche. 50-000, 84/03/22, 8403270246
- ~-B403270252 BALP Repts 50~454/83-22 & 50~455/83-18 for 1982. * Region 3, Office of Director 84/03/22, 29pp. 22770,142, 24X Fiche 50~000,84/03/22,8403270246
- --8403270255 Forwards significant SALP rept findings which will be discussed at 830613 meeting HIND; J.A. Region 3, Office of Director 83/06/08. REED, C. Commonwealth Edison Co 4pp. 22770 171 24x Piche: 50-000; 84/03/22, 8403270246.

- --8403270260 SALP Repts 50-456/83-06 & 50-457/83-06 for 1982 Category 2 assigned in areas of piping sys & supports & electrical power supply & distribution * Region 3. Office of Director 84/03/22 25pp 22770 203 24% Ficha 50-000.84/03/22.8403270246
- --8403270263 Forwards summary of significant findings for SALP rept which will be discussed at 830613 meeting
 HIND, J A Region 3, Office of Director 83/06/08 REED,C
 Commonwealth Edison Co 3pp 22770 228 24X
 Fiche 30-000.84/03/22.8403270246
- R Periodic operating reports & related correspondence
- 8403220120 Annual whole body external exposures for 1983 H/840316 ltr RYBAK, B Commonwealth Edison Co 83/12/31 7pp 22716 007 24X Fiche 50-000.83/12/31.8403220120
- B4030R0443 Forwards monthly status rept of offsite emergency preparadness for OL reviews for Jan 1984 Changes in FEMA finding dates not caused by delay due to offsite emergency planning issues
 BIRCKS,W J Offsic of the Executive Director for Operations, 84/02/21 PALLADIND Commissioners 9pp 22492 083 24X Fiche 50-000,84/02/21.8403020443
- S Reportable occurrences, LERs & related correspondence
- 8403140122 Part 21 rept re status update concerning abnormal wear on linear converters Test program underway Results of investigation indicate excessive wear caused by hunting of control circuitry

 DDBON, J P Pacific Air Products Co 84/03/09 Director's

 Office, Dffice of Inspection and Enforcement 7pp 22624 068 24X Fiche 50-000, 84/03/09, 8403140122
- U Congressional/Executive Correspondence
- B403200043 Provides add1 remarks on NRC exceptions to accuracy of statements in recent Congressional testimony re failure of NRC to inform ABLB promptly of problems at facility Problem can be cured by eliminating NRC role in hearings OLLINEKY.V Commissioners 84/03/16 UDALL MK House of Rep , Interior & Insular Affairs 5pp 22698 322 24X Fiche 50-454,84/03/16.8403200043
- B403200075 Submits addl comments to remark made at recent NRC budget hearing & forwards Dircks memo re comments Role of NRC as full party in licensing hearings should be eliminated GILINEKY, V Commissioners 84/03/16 BIMPSON, A Senate, Environment & Public Works 5pp 22699 036 24X Fiche: 50-454,64/03/16,8403200075

V Operator Examinations

B403220133 Forwards info re experience lavel of individuals assigned to shift operating positions, in response to request Tabulation showing experience of shift engineers shift foreman, station control room engineer & operator encl TRAMM, T.R. Commonwealth Edison Co. 84/03/19 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 7pp 22716 030 24X Ficho. 50-454.84/03/19,8403220133

DOCKET STN-50-455 BYRON STATION, UNIT 2

- A Application/construction stage documents & correspondence
- 84030i0106 Forwards addl info re design of Category 1 masonry walls Rept identifies all cracks & explains why cracks do not compromise structural integrity of walls TRAMM.T.R Commonwealth Edison Go 84/02/22 DENTON.H R. Office of Nuclear Reactor Regulation, Director 15pp 22436 041 24X Fiche 50-000.84/02/22.8403010f06
- B402090017 Board Notification 84-038 forwards RJ Mattson 840123 memo to Do Eisenhut providing status update of NRC actions re Hestinghouse ECCS actuation logic. EISENHUT, D o Division of Licensing 84/02/27 PALLADINO Commissioners 7pp 22546 007. 24X Fiche 50-000,84/02/27. 8402090017
- 8403060245 Forwards revised info re preservice exam & testing of snubbers at facilities Encl testing program supercedes program provided in 820319 ltr & accepted in SEER 12 TRAMM.TR Commonwealth Edison Co 84/02/28 DENTON,H R Office of Nuclear Reactor Regulation, Director 1p 22516 013 24X Fiche 50-000,84/02/28.8403060245

- --B403060267 Rev) to "Preservice Testing (Preservice Insp) Program Plan for Snubbers
 - * Commonwealth Edison Co 83/10/21 47pp 22516 014 24X Fiche 50-000,84/02/28,8403060245
- B403060394 Advises of changes to schedules for initial fuel loading of facilities Requests NRC resources be allocated to support fuel load after resolution of pending license appeal REED. C Commonwealth Edison Co 84/02/28 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 22518 150 24% Fiche 50-000,84/02/28,8403060394
- 8403050119 Forwards supplemental response to Generic Ltr B3-28,
 "Required Actions Based on Generic Implications of Salem
 ATHS Events"
 BARNES, Pt. Commonwealth Edison Co. 84/02/29 DENTON, H. Office
 of Nuclear Reactor Regulation, Director. 26pp. 22488 084 24X
 Fiche 50-000,84/02/29,8403050119
- 8402090041 Board Notification 84-050 provides Commission policy statement & proposed rulemaking on environ qualifications EISENHUT.D G Division of Licensing 84/03/14 Atomic Safety and Licensing Board Panel 10pp 24X Fiche 50-000.84/03/14.8402090041
- 8403220133 Forwards into re experience level of individuals assigned to shift operating positions in response to request Tabulation showing experience of shift engineer. shift foreman, station control room engineer & operator end; TRAMM. T. R. Commonwealth Edison Co. 84/03/19 DENTON. H. R. Office of Nuclear Reactor Regulation. Director 7pp 22716 030 24X Fiche 50-454,84/03/19.8403220133 Office
- 6403260182 Clarifies NUREQ-0737, Item II K 3 31, in response to Generic #USEABLE Clarifies KUNEG-0/3/, ITEM II N 3 31.11 response to Generic Ltr B3-05 Westinghouse Dumers Group authorized program to demonstrate conservation of WFLASH small break LOCA analyses, per Item II K 3 30

 BARNEG, P L Commonwealth Edison Co 84/03/21 EISENHUT, D G

 Division of Licensing Ip 22756 170 24X Fiche 50-000, 84/03/21, 8405280182
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Ruvisw of addl documents subj to request continuing FELTON J M Division of Rules and Records 84/02/13 ANDERSON, S I Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000,84/02/13,8403080179
- --8005130773 Provides status of SER inputs & acceptance reviews for OL & CP applications Schedule should be met BURKE. W C Effluent Treatment Systems Branch 80/02/06 KREGER. W E Assistant Director for Site Analysis 1p 22583 235 24X Fiche 50-000.84/02/13.8403090179
- 8403010120 Forwards add1 info to 831230 submittal re NUREG-0737. Item III D 1 i. "Primary Coolant Outside Containment " Revidentifies portions of sys not to be tested & responds to NRC comments Info should close SER Confirmatory Issue 28 TRAMM.T R Commonwealth Edison Co. 84/02/22 DENTON, H.R. Office of Nuclear Reactor Regulation. Director 8pp. 22432 002 24X Fiche 50-000.84/02/22.8403010120
- 8403010286 Provides addl info re effects of local intense precipitation at facilities Info resolves Confirmatory Issue A 2 identified in SER Reinforced concrete Curbs provided at exterior grade floor level doors TRAMM.T R Commonwealth Edison Co 84/02/22 DENTON.H R Office of Nuclear Reactor Regulation. Director 20p 22434 257 24X Fiche 50-000,84/02/22,8403010286
- 8403260132 Submits add1 info re design of hydrogen recombiners per Section 6 2 5 of SER Hydrogen recombiners operate in parallel.vitilizing same suction & exhaust piping for each containment Diagram encl TRAMM.T R Commonwealth Edison Co 84/02/22 DENTON, H R Office of Nuclear Reactor Regulation. Director 2pp 22758 147 24X Fiche 50-000,84/02/22,8403260132
- 8403060345 Forwards "Rept Geotechnical Sycs Seismic Crosshole Survey & Dynamic Soil Properties at River Screenhouse, Byron Station Units 1 & 2 " Info closes out SER Confirmatory Issue 1 & Onits 1 & 2 " Into closes out accountinatory 1990e 1 a responds to two FSAR questions
 TRAMM.T R Commonwealth Edison Co B4/02/28 DENTON, H R D
 of Nuclear Reactor Regulation, Director 1p 22511 196 24X
 Fiche 50-454,84/02/28 Defice
- --8403060347 "Rept Geotechnical Sycs Seismic Crosshole Survey & Dynamic Soil Properties at River Screenhouse, Byron Station Units 1 & 2 "
 - * Dames & Moore 84/02/06 22pg 22511 137 24X Fichs 50-454,84/02/28,8403060345

- F Security, medical, emergency & fire protection plans
- 8403070347 Public version of revised emergency plan implementing procedure index W/840215 transmittal form & JM Felton 840302 release memo Commonwealth Edison Co 84/01/20 18pp 22564 041
 - Fithe 50-454, 84/01/20, 8403070347
- B403010403 Rev O to Procedure BZP 500-T1, "Checklist-Communication
- Commonwealth Edison Co 84/02/18 7pp 22433 104 24X Fiche 50-454,84/02/18,8403010403
- 840302019B Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee, per Bi0709 Generic Ltr Bi-27 W/o request entire plan will be placed in PDR YOUNOBLOOD, B J Licensing Branch i B4/02/21 FARRAR, D L Commonwealth Edison Co 2pp 22494 350 24X Fiche 50-000,84/02/21, B403020198
- B402090006 Board Notification 84-034 forwards R Vollmer 840206 memo to D Eisenhut re fire research results concerning fires in electrical cabinets in control room EISENHUT.D 9 Division of Licensing 84/02/23 PALLADING Commissioners 1p 22576 203 24X Fiche 50-000,84/02/23, https://doi.org/10.1007/0007/84/02/23
- --8403080316 Recommends that info re fire research results concerning fires in electrical cabinets in control room be submitted for board notification per NRR Ofc Ltr 19, dtd 821001 Further evaluation of test data required VOLLMER.R H Division of Engineering 84/02/06. EISENHUT, D 0 Division of Licensing 10pp 22076 204 24X Fichs 50-000,84/02/23.8402090006
- 8403120142 Rev O to Procedure BZP 500-1, "Operation Checks of Communications Bys." W/840320 transmittal & receipt form * Communealth Edison Co. 84/02/28 4pp 22570 144 24X Fiche 50-454, 84/02/28, 8403120142
- B403050162 Forwards FEMA B40201 ltr.final exercise evaluations on B31115 offsite emergency preparadness exercise & interim finding recommendations re offsite emergency response plan for area around facility No deficiencies identified PAPERIELLO.C J Region 3. Office of Director 84/02/29 REED.C Commonwealth Edison Co 2pp 22485 061 24X Fichs 50-454.84/02/29, 8403050162
- 8403120107 Notifies of 840323 workshop on fire protection safe shutdown requirements of IOCFRSO.App R in Rosemont, IL to discuss IE Info Notice 84-07 % provide addl shutdown analyses &/or mod guidance Agenda encl SPESSARD.R.i. Division of Emergency Preparedness & Operational Support 84/03/06 REED,C Commonwealth Edison Co Spp 22588 163 24X Fiche 50-454,84/03/06.8403120107
- Fiche 50-454,84/03/07,8403150044
- 8403260346 Rev 1 to Emergency Plan Implementing Procedure BZP 380-3, "Past-Accident Stack Bampling of Wide-Range Gas Monitor (WROM)" * Commonwealth Edison Co 84/03 Fiche 50-000,84/03/15,8403260346 84/03/15 5pp 22751,055 24x
- 8403140190 Emergency plan implementing procedures index W/840329 transmittal & receipt form * Camonumealth Edison Co 84/01/20 17pp 22620.216 24X Fiche 50-454,84/03/29,8403140190

9 Adjudicatory correspondence

- 8403i40035 Requests reconsideration of decision to bar facility from starting up Util most experienced w/nuclear plants & revs util result in corrective actions HOPKING:R. Affiliation Not Assigned 84/02/20 NRC No Detai Affiliation Given 2pp 22634.159. 24X Fiche 50-454,84/02/20. NRC - No Detailed 8403140035
- 8403020181 Forwards "Rept on Byron GC Inspector Reinspection Program Program "
 BIELAMSKI.A.P Isham, Lincoln & Beale BIELAMSKI.A.P Comm.
 Edison Co 84/02/27 ROSENTHAL.A 8, QDTCHY,R L., KOHL.C.W.
 Bafety and Licensing Appeal Panel 224pp 22440 311 24X
 Fichs 50-454,84/02/27,8403020181 Commonwealth

- 8403060079 Advises of issues to be addressed in 840312 brief,per 840127 request HHICHER,J M Businessmen for the Public Interest 84/03/01 ROSENTHAL,A S , KOHL,C W , GOTCHY,R L Atomic Safety and Licensing Appeal Panel ip 22516 338 24X Fiche 50-454,84/03/01,8403040079
- 8403140129 Advises that staff unable to accelerate schedule for filing of appellate brief on QA. need for power & alternative energy sources, financial qualifications & seismology Brief will be filed by 840330

 RAMSON.R J Hearing Branch 4 84/03/06 ROBENTHAL, A 8 , KOHL, C N , GOTCHY, R L Atomic Safety and Licensing Appeal Parel 1p 22624 204 24X Fiche 50-454, 84/03/06, 8403140129
- B403140146 Forwards Paperiello B40229 ltr to C Reed forwarding FEMA interim finding on offsite radiological emergency planning NRC will address interim finding in SSER RAMBON.R J Hearing Branch 4 84/03/06 ROSENTHAL.A B . Q
- 840314006B Forwards potentially relevant documents & matl to matters pending before ASLAG W/o encis
 RAMSON.R J Hearing Branch 4 84/03/07 ROSENTHAL, A S . KOHL, C N .
 OUTCHY.R L Atomic Sefety and Licensing Appeal Panel 2pp
 22633 079 24X Fiche 50-454,84/03/07.840314006B
- 8403140148 Forwards IE Insp Repts 50-454/83-61; 50-455/83-41; 50-454/84-02; 50-455/84-02; 50-455/83-43; 50-455/84-05; 50-455/84-04; 50-455/84-05; 50-455/84-05; 50-455/84-05; 50-455/84-05; 50-455/84-05; 50-456/84-
- 8403090102 Mamorandum scheduling 840417 oral argument in Bethesda.MD re pending appeal Formal argument will be issued in early Apr BHOEMAKER.C J Atomic Safety and Licensing Appeal Panel 84/03/08 2pp 22575 356 24X Fiche 50-454.84/03/08.8403090102
- 8403160002 Response opposing applicant alternative motion to reopen record & vacate ABLB denial of OL Motion would be considered acceptable Under single issue of reinspection program Cartificate of Svc encl WHICHER.J M DeKalb Area Alliance for Responsible Energy WHICHER.J M Whicher. J M 84/03/12 Atomic Safety and Licensing Appeal Panel 11pp 22655 198 24X Fiche 50-454,84/03/12,8403160002
- 8403160019 Brief in response to applicant appeal of ABLB 840113 initial decision denying OL application ABLB properly denied BL HHICHER, J M. CASBEL, D W DeKalb Area Allience for Responsible Energy WHICHER, J M. Whicher, J M. 84/03/12 Atomic Safety and Licensing Appeal Panel 64pp. 22653 225 24X Fiche 50-454, 84/03/12, 8403160019
- 8403140041 Memorandum changing proposed date for oral argument of panding appeal from 840417 to 0419
 8HOEMAKER,C J. Atomic Safety and Licensing Appeal Panel 84/03/13
 1p 22634 161 24% Fich* 50-454, 84/03/13, 8403140041
- 8403200122 Discusses util 840218 & 0314 nonconformance repts re discrepant welds in cable pan hangers supplied by Sys Control Corp Earlier nonconformance repts re matter issued in 1977 at Byron, Related correspondence MILLER, M I Isham, Lincoln & Beale MILLER, M I. Commonwealth Edison Co 84/03/14 KDHL, C W, GUICHY, R L, ROSENTHAL, A S Atomic Safety and Licensing Appeal Panel 2pp. 22477.045 24X Fiche, 50-454,84/03/14,8403200122.
- 8403260351 Forwards listing of errata in 840312 brief, WHICHER, J M Businessmen for the Public Interest WHICHER, J M Whicher, J M DBB 070 84/03/22 KOHL, C N., GOTCHY, R.L., ROSENTHAL, A.S. Atomic Eafety and Licensing Appe
- O Inspection reports, IE Bulletins & correspondence
- 8403010083 Forwards final rept on Byron QA inspector reinsp program DELGEOROE, L. O. Commonwealth Edison Co. 84/02/24 KEPPLER, J O Region 3. Office of Director 1p. 22434 268 24X Fichs: 50-454, 84/02/24, 8403010083.
- --8403010087 Final "Rept on Byron Inspector Reinsp Program." * Commonwealth Edison Co. 84/02/29 223pp 22434 270 24X Fiche 50-454,84/02/24,8403010083

- B403030043 Forwards Rev 0 to "Corporate Regulatory Performance Improvement Plan "Plan designed to heighten employee awareness & strengthen corporate ability to improve regulatory performance THDMAS, B Commonwealth Edison Co B4/02/24 KEPPLER, J G Region 3, Office of Director 3pp 22490 139 24% Fiche 50-000,84/02/24. B403050043
- --8403050046 Rev 0 to "Corporate Regulatory Performance Improvement Plan" * Commonwealth Edison Co 84/02/27 22pp 22490 142 24X Fiche 50-000, 84/02/24, 8403050043
- 8403020181 Forwards "Rept on Byron GC Inspector Reinspection Program" BIELAMBKI.A P Isham, Lincoln & Beale 84/02/27 ROSENTHAL, A S Atomic Safety and Licensing Appeal Panel 224pp 22440 311 24x Fiche 50-454,84/02/27,8403020181
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Mator Operated Valve Control Circuits & Annunciation " 8vc list enc1 JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 930103) B4/02/28 Consolidated Edison Co. of New York: Inc. 115pp. 22909 239 24X Fiche.50-000.84/02/28,8401190072
- 8403060245 Forwards revised info re preservice exam & testing of snubbers at facilities Encl testing program supercedes program provided in 820319 ltr & accepted in 85ER 12 TRAMM, T R Commonwealth Edison Co 84/02/28 DENTON, H, R Office of Nuclear Reactor Regulation, Director ip 22516 013 24X Fiche 30-000,84/02/28,8403060245
- --8403060267 Rev 1 to "Preservice Testing (Preservice Insp) Program Plan for Shubbers " * Commonwealth Edison Co 83/10/21 47pp 22516 014 24X Fichs 50-000, 84/02/28, 8403060245
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE.J N Division of GA. Safegwards & Inspection Programs (Post B30103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fi-he 50-000-84/03/02-8402090007
- 8402090008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Fost B30103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000.84/03/02.8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases" Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 119pp 22553 217 24X Fiche 50-000.84/03/02,8402090009
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitragen Cooling Components Below Nil Ductility Temp " Svc list encl, JORDÁN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8403190297 Forwards IE lnsp Repts 30-454/84-04 & 50-455/84-03 on 640123-26 No noncumpliance identified LITTLE: W S Region 3. Office of Director 84/03/05 REED.C. Commonwealth Edison Co 2pp 82673 255 24X Fiche 30-454,84/03/05,8403190297
- --B403190305 IE Insp Repts 50-454/84-04 & 50-455/84-03 on B40123-26 No noncompliance or deviations identified Major areas inspected closeout of open items & deficiency items & as-built walkdown of structural steel framing & supports KEATING.D E . DANIELSON.D H Region 3. Office of Director B4/03/05 &pp 22673 257 24X Fichs 50-454:84/03/05.8403190297
- 8402070024 IE Info Notice 84-09, Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24% Fiche, 50-000, 84/03/07, 8402090024
- ## 8402070028 IE Info Notice ## 84-18, "Stress Corrosion Cracking in PWR 84s." Svc list enc!

 JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post ## 830103) ## 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22584 186 24X Fiche 50-000, ## 84/03/07, ## 8402070028

- 8403140148 Forwards IE Insp Repts 50-454/83-61.50-455/83-41.50-454/84-02.50-455/84-02.50-454/83-58.50-455/83-43.50-494/84-05.
 50-455/84-04.50-454/84-06 & 50-455/84-05 per requirements of ALAB-143
 RAWSON.R J Hearing Branch 4 84/03/07 ROBENTHAL.A S Atomic Safety and Licensing Appeal Panel 76pg 22625.086 24X
 Fiche 50-454.84/03/07.8403140188
- B403220094 Forwards IE Insp Repts 50-454/84-10 & 50-455/84-08 on 840131.0201-03 & 07-10 No noncompliance noted PAPERIELLO, C J Region 3. Office of Director 84/03/07 REED.C Commonwealth Edison Co 2pp 22716 311 24% Fichs 50-454.84/03/07. B403220094
- --B403220097 IE insp Repts 50-454/B4-10 & 50-455/B4-0B on B40131,0201-03 & 07-10 No noncompliance noted Major areas inspected preoperational radiation protection program including organization, staffing, training & NUREC-0737 items HUETER: L J. GREGER: R Region 3, Office of Director B4/03/07 11pp 22716 313 24X Fiche 50-454,84/03/07,8403220094
- 8403190268 Ack receipt of 840223 ltr informing NRC of steps taken to correct violations re steam generator snubber qualification tests noted in IE Insp. Repts 30-454/84-08 & 50-455/84-06 LITTLE.W S Region 3. Office of Director 84/03/08 REED.C Comnonwealth Edison Co ip 22672 226 24x Fichs 50-454.84/03/08.8403190268
- --B403190274 Responds to NRC B40204 ltr re violations noted in IE Insp Repts 50-454/84-08 & 50-435/84-06 Corrective actions leak on snubber repaired & quasi-static structural test combined w/fluid stiffness calculation performed SWARTZ.E D Commonwealth Edison Co B4/02/23 KEPPLER.J O Region 3. Office of Director. Spp. 22472 227 24X Fiche 50-454.84/03/08.8403190248
- --8403170278 Preliminary Spet 120, "Testing Svcs for Steam Generators"

 * Sargent & Lundy, Inc 84/02/22 38pp 22672 232 24X
 Fiche 50-454,84/03/08,8403190268
- 8402090031 IE Bulletin 84-02. "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Syc list encl.

 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000,84/03/12.8402090031.
- 8403230088 Ack receipt of regulatory performance improvement plan Periodic meetings requested to discuss progress on program & provide feedback KEPPLER.J O Region 3, Office of Director 84/03/20 THOMAS, 8 Commonwealth Edison Co 1p 22730 141 24X Fiche:50-000,84/03/20,840323088
- --8403230107 Forwards corporate regulatory performance improvement plan THOMAS.B Commonwealth Edison Co 84/02/24 KEPPLER, J 0 Region 3. Office of Director 3pp 22730 162 24X Fiche 50-000, 84/03/20,8403230088
- --B403230126 Rev O to "Corporate Regulatory Performence Improvement Plan For Dresden.Quad Cities, Zion & LaSalle Operating Nuclear Stations & Byron & Braidwood Project Operating Organizations" * Commonwealth Edison Co 84/02/29 22pp 22730 165 24X Fiche 50-000,84/03/20.8403230088
- B403260196 Forwards responses to IE Bulletin 83-07, "Apparently Fraudulent Products Sold by Ray Miller. Inc " Guad Cities supplied w/piping matts from Ray Miller. Inc during const Evaluation encl Concerns of IE Bulletin 83-06 satisfied BARNES, P L Commonwealth Edison Co 84/03/20 KEPPLER, J Q Region 3. Office of Director 19pp 22756 185 24X Fiche 50-000,84/03/20,8403260196
- B403270iii Forwards response to IE Bulletin 80~15, "Emergency Notification Sys (EMS) Power Supplies "ENS tested & found functional during presperational testing BARNES.P.L Commonwealth Edison Co 84/03/20 KEPPLER, J Q Region 3, Office of Director Spp 22774 048 24% Fiche 50-454,84/03/20, 8403270111
- B402090043 IE lnfo Notice 84-17, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl.
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823,227. 24X Fiche 50-000,84/03/21,8402090043
- B402090044 IE Info Notice 84-20, "Syc Life of Relays in Safety-Related Sys." Syc list encl JORDAN,E,L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001. 24X Fiche 50-000,84/03/21.8402090044

- 8403270246 Forwards BALP Repts 50-454/83-22.50-455/83-18,50-456/83-06 & 50-457/83-06 for 1982 Increased emphasis required in areas of HVAC & electrical sys KEPPLER.J 9. Region 3. Office of Director 84/03/22 REED.C Commonwealth Edison Co. 7pp 22770 135 24X Fichs 50-000.84/03/22.8403270246
- --8403270252 BALP Repts 50-454/83-22 & 50-455/83-18 for 1982 * Region 3. Office of Director 84/03/22 29pp. 22770 142 24X Fiche 50-000, 84/03/22, 8403270246
- --8403270285 Forwards significant BALP rept findings which will be discussed at 830613 meeting HINDs J A Region 3, Office of Director 83/06/08, REED, C. Cumnonwealth Edison CO 4pp. 22770-171 24X Fiche 50-000, 84/03/22,8403270246
- R Periodic operating reports & related correspondence
- 8403220120 Annual whole body external exposures for 1983 W/840316 ltr RYBAK.B Commonwrelth Edison Co. 83/12/31 7pp 22716.007 24X Fiche.50-000.83/12/31.8403220120
- S Reportable occurrences, LERs & related correspondence
- 8403140122 Part 21 rept re status update concerning abnormal wear on linear converters Test program underway Results of investigation indicate excessive wear caused by hunting of control circuitry DDB30N.J P Pacific Air Products Co 84/03/09 Director's Office, Office of Inspection and Enforcement 7pp. 22624.068, 24X Fiche 50-000.84/03/09.8403140122
- U Congressional/Executive Correspondence
- 8403200043 Provides add1 remarks on NRC exceptions to accuracy of statements in recent Congressional testimony re failure of NRC to inform ARLB promptly of problems at facility Problem cam be cured by eliminating NRC role in hearings OILINGKY. V Commissioners 84/03/16 UDALL, M.K. House of Rep., Interior & Insular Affairs 5p. 22678 322, 24% Fiche 50-454,84/03/16,8403200043,
- 8403200075 Submits addl comments to remark made at recent NRC budget hearing & forwards Dircks memo re comments Role of NRC as full party in licensing hearings should be eliminated OILINSKY,V Commissioners 84/03/16 SIMPBON,A Senate, Environment & Public Works 5pp 22697 036 24X Fiche. 50-454,84/03/16.8403200075
- V Operator Examinations
- 8403220133 Forwards info re experience level of individuals assigned to shift operating positions in response to request.

 Tabulation showing experience of shift engineer shift foreman station control room engineer & operator encl TRANNIT R Commonwealth Edison Co 84/03/19 DENTON, H.R Office of Nuclear Reactor Regulation, Director 7pp 22716 030 24% Fiche 50-454,84/03/19,8403220133
- DOCKET STN-50-456 BRAIDWOOD STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8403010106 Forwards addl info re design of Category 1 mesonry walls. Rept identifies all cracks & explains why cracks do not compromise structural integrity of walls TRAMM.TR Commonwealth Edison Co 84/02/22, DENTON, HR Office of Nuclear Reactor Regulation, Director 16pp 22436-041, 24X Fiche 50-000.84/02/22,8403010106
- 8403060245 Forwards revised info re preservice exam % tasting of snubbers at facilities Encl testing program supercedes program provided in 820319 ltr & accepted in 88ER 12 TRAMM.T R Commonwealth Edison Co 84/02/28 DENTON.H R. Office of Nuclear Reactor Regulation, Director 1p. 22316 019, 24X Fiche 50-000,84/02/28,8403060245
- --8403060267 Rev 1 to "Preservice Testing (Preservice Insp) Program Plant for Bnubbers "

 " Commonwealth Edison Co. 63/10/21 47pp. 22516-014, 24X Fiche 30-000.84/02/28.8403060245.
- 8403060394 Advises of changes to schedules for initial fuel loading of facilities, Requests NRC resources be allocated to support fuel load after resolution of pending license appeal, REED, C Commonwealth Edison Co 84/02/28, DENTON.H.R Office of Nuclear Reactor Regulation, Director 2pp. 22518 150, 24X Fichs 50-000,84/02/28,8403060394

- Office
- #403260182 Clarifies NUREG-0737. Item II K 3 31, in response to Generic Ltr 83-35 Westinghouse Dwners Group authorized program to demonstrate conservatism of WFLASH small break LOCA analyses, per Item II K 3 30

 BARNES, F L Commonwealth Edison Co 84/03/21 EISENHUT, D Q Division of Licensing 1p 22736 170 24% Fiche 50-000, 84/03/21, 840320182 8403240182
- D NRC Draft/Final Environmental Statements, supple & correspondence
- ed 403130037 Ack receipt of DEB Meeting tenatively scheduled for 840222 for consideration by Governmental Svcs Committee # Illinois, State of. 84/02/02 BTEVENS, J A Division of Licensing lpp 22613 362 24X Fiche 50-456,84/02/02,8403130037
- 2403080227 Lists concerns on proposed water supply sys discussed in Dec 1983 DES (NUREG-1026), including degradation of water quality from cooling water discharge to Kankakee River GALLACHER, JR Will County, IL 84/03/02 Division of Licensi p 22561 031, 24X Fiche 50-456,84/03/02,8403080227 Division of Licensing
- #3403130474 Forwards comments on DEG re operation of facilities Major environ concerns identified during 1970s & appropriate mitigating actions to alleviate concerns adequately reflected Hore data re aquatic impact should be referenced
 KENNEY, D Illinois, State of 84/03/08 Division of Licenting
 App. 22613 357 24X Fiche 50-456,84/03/08,8403130474
- #3403140001 Forwards comments on DES (NUREO-1024) Comments submitted for consideration by Commission per 10CFR51.

 MCDUNOUGH, C. L. Commonwealth Edition Co. 84/03/12 Division of Licensing 13pp 22633:251. 24X Fiche. 30-456. 84/03/12, 8403140001
- 83403200104 Discusses review of DES. Facility will employ two PWRs to produce up to 6850 MMt No major objections to proposed operation FE8 should provide addl radwasts treatment sys Environmental Protection Agency 84/03/12. B J Licensing Branch I 3pp. 22685:357 VOUNCELOOD, B J Licensing Branch 1 Fiche 50-456, 84/03/12, 8403200104
- 在。 NRC Befety Evaluation Report (BER), supple & correspondence
- ### 403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of ### 4dd documents subj. to request continuing.

 FELTON.J.M. Division of Rules and Records ### 84/02/13 ANDERSON, S I Garvey. Schubert, Adams & Barer 7pp 22583 226 24%

 Fiche: 50-000, 84/02/13, 8403080179
- B005130793 Provides status of BER inputs & acceptance reviews for OL & CP applications Schedule should be met BURKE.M.C. Effluent Treatment Systems Branch 80/02/06 KREGER.W.E. Assistant Director for Site Analysis. 1p 22583:235 24X Fiche 50-000,84/02/13,8403080179
- © O O O 10120 Forwards add1 info to 831230 submittal re NUREG-0737. Item
 III, D. 1 1. "Primary Coolant Outside Containment " Rav
 identifies portions of sys not to be tested & responds to
 NRC comments Info should close SER Confirmatory Issue 28
 TRAMH.T.R. Commonwealth Edison Co. 84/02/22 DENTON.H R Office
 Of Nuclear Reactor Regulation, Director 8pp. 22432 002 24X
 Fichs: 50-000, 84/02/22, 8403010120 Office
- OBC010286 Provides add1 info re effects of local intense precipitation at facilities Info resolves Confirmatory Issue A. 2
 identified in BER. Reinforced concrete curbs provided at exterior grade floor level doors.
 TRAMM.T.R. Commonwealth Edison Co. 84/02/22 DENTON. H.R. Office of Nuclear Reactor Regulation. Director 2pp 22434 257. 24X
 Fiche: 50-000.84/02/22,8403010286

- 8403260132 Submits addi info re design of hydrogen recombiners per Section 6 2 5 of SER Hydrogen recombiners operate in parallel.utilizing same suction & exhaust piping for each containment Diagram encl TRAHM.T R Commonwealth Edison Co 84/02/22 DENTON, H R Offi of Nuclear Reactor Regulation, Director 2pp 22758 147 24X Office TRAMM, T R Commonwealth Edison Co 44/ of Nuclear Reactor Regulation, Director Fichs 50-000,84/02/22,8403260132
- F Security, medical, emergency & fire protection plans
- 8403020198 Advises that NRC will not review emergency plans to delete 403020198 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee.per 810709 Generic Ltr 81-27 W/o request entire plan will be placed in PDR YOUNGBLOOD, B. J. Licensing Branch 1 84/02/21 FARRAR.D L Commonwealth Edison Co 2pp 22494 360 24X Fiche 50-000,84/02/21,
- 840312000B Advises of 840323 regional workshop in Rosemont IL w/all Region III licensees to discuss fire protection safe shutdown requirements of 100FR50.App R Agenda encl SPESBARD, R L Division of Emergency Preparedness & Operational Support 84/03/06 REED, C Commonwealth Edison Co 3pp 22584 260 24X Fiche 50-456.84/03/06.840312000B
- 8403260346 Rev 1 to Emergency Plan Implementing Procedure BZP 380-3, "Post-Accident Stack Sampling of Wide-Range Gas Monitor Commonwealth Edison Co. 84/03/15 5pp 22751 055 24x Fiche 50-000,84/03/15,8403260346
- G Adjudicatory correspondence
- 8403140040 Comments of JF Doherty on DES (NUREG-1026) Statement must 403140040 Comments of JP Donerty on Des (NOMEG-1042) Statement must clarify if in analysis of environ impacts of postulated accidents any credit given for applicant compliance w/any TMI-related requirements Related correspondence DOHERTY.JF Affiliation Not Assigned 84/03/07 STEVENB.J A Division of Licensing 2pp 22633 120 24% Fiche 50-456.84/03/07.8403140040
- 840316001) Forwards C Reed 840228 ltr re schedule for fuel loading dates & notice of appearance W/o notice of appearance Related correspondence GALLO, J Isham, Lincoln & Beale GALLO, J Commonwealth Edison Co 84/03/13 MILLER, M E , CALLIHAN, A D , COLE, R F Atomic Safety and Licensing Board Panel 3pp 22655 168 24X Fiche 50-456,84/03/13,8403160011
- B403160023 Notice of appearance in proceeding Certificate of Svc encl
 OAULO.J Commonwealth Edison Co OAULO.J Isham, Lincoln & Beale
 B4/03/13 2pp 22653 353 24X Fiche 50-456.84/03/13,8403160023
- 8403260361 Notice of appearance in proceeding. Certificate of Syt encl BLODM, J G Commonwealth Edison Co BLODM, J O Isham, Lincoln & Beale DSD 086 84/03/22 3pp 22760 074 24X Fiche 50-455,88/03/22.8403260361
- Q Inspection reports, IE Bulletins & correspondence
- 8403050043 Forwards Rev O to "Corporate Regulatory Performance Improvement Plan " Plan designed to heighten employee awareness & strengthen corporate ability to improve regulatory performance THDMAB,B Commonwealth Edison Co 84/02/24 KEPPLER,J & Region 3, Office of Director 3pp 22490 139 24x Fiche 50-000.84/02/24. 8403050043
- --8403050046 Rev O to "Corporate Regulatory Performance Improvement Plan" Commonwealth Edison Co 84/02/29 22pp 22490 142 24% Fiche: 50-000, 84/02/24, 8403050043
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation." Svc list encl JORDANIE L UORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc. 115pp 22907 239 24X Fiche 80-000.84/02/28,8401190072
- 8403060245 Forwards revised info re preservice exam & testing of snubbers at facilities Enc: testing program supercedes program provided in 820319 ltr & accepted in 88ER 12 TRAMM.T R Commonwealth Edison Co 84/02/28 DENTON,H R O of Nuclear Reactor Regulation, Director 1p. 22516 0:3 24X Fiche: 50-000,84/02/28,8403060245 ER 12 DENTON H R OF Office
- -8403060267 Rey 1 to "Preservice Testing (Preservice Insp) Program Plan

- 84020700007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list enc! GRACE., N Division of GA. Safeguards & Inspection Programs (Post 830103) B4/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000.84/03/02.8402070007
- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000,84/03/02.8402090008
- 8402070007 IE Info Notice 84-15, "Reporting of Radiological Releases"
 Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc 119
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitragen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000.84/03/05,8402090011
- 8402070024 IE Info Notice 84-07.Rev i. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22633 049 24X Fiche 50-000.84/03/07.8402070024
- 840209028 IE Info Natice 84-18, "Stress Corrosion Cracking in PWR
 Sys " Syc list encl
 JURDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/07 Consolidated Edison Co of New
 York, Inc 118pp 22584 186 24X Fiche 50-000.84/03/07.8402090028
- 8402090031 IE Bulletin 84-02. "Failures of GE Type HFA Relays in Use in Class IE Safety 89s " Svc list encl DEYDUNO, R C Director's Diffice. Office of Inspection and Enforcement 8403/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000.84/03/12.8402090031
- 8403300026 Forwards IE Insp Repts 50-496/84-03 & 50-457/84-03 on 840228-0302 No noncompliance noted PAPERIELLO, C J Region 3, Office of Director 84/03/16 REED, C Componwealth Edison Co 2pp 22819 297 24X Fiche 50-456.84/03/16.8403300026
- --8403300033 IE Insp Repts 50~456/84-03 & 50-457/84-03 on B40228-0302 No violations or deviations identified Major areas inspected mgt controls.94.chemistry program & procedures.actions taken re previous items of noncomplicance & open items CESTMANN.M J . SLAWINSKI.W J . SCHUMACHER,M C . Region 3. Office of Director 84/03/15 . Bpp 22819 297 24% Fiche 50-456.84/03/16. B403300026
- 8403230088 Ack receipt of regulatory performance improvement plan
 Periodic meetings requested to discuss progress on program
 & provide feedback
 KEPPLER.U 9 Region 3. Office of Director 84/03/20 YHOMAS.B
 Commonwealth Edison Co ip 22730 161 24X Fiche 50-000.84/03/20.
- --B403230107 Forwards corporate regulatory performance improvement plan THOMAS.B Commonwealth Edison Co B4/02/24 KEPPLER.J Q Region G. Office of Director 3pp 22730 162 24% Fiche 50-000. 84/03/20.8403230088
- --8403230126 Rev O to "Corporate Regulatory Performance Improvement Plan For Dresden, Quad Cities, Zion & LaSalle Operating Nuclear Stations & Byron & Braidwood Project Operating Organizations " * Commonwealth Edison Co 84/02/29 22pp 22730 165, 24X Fiche 50-000, 84/03/20, 8403230088
- 8403260196 Forwards responses to IE Bulletin B3-07. "Apparently Fraudulent Products Sold by Ray Miller.Inc " Guad Cities supplied w/piping matis from Ray Miller.Inc during const Evaluation encl Concerns of IE Bulletin B3-06 satisfied BARNES.P L Commonwealth Edison Co 84/03/20 KEPPLER.J 9 Region 3. Office of Director 19pp 22756 185 24X Fiche 50-000.84/03/20. 84003260196
- 8402090043 IE Info Notice 84-i9, "Two Events Involving Unauthorized Entries into PHR Reactor Cavities " Svc list encl.
 JORDAN, E L Division of Emergency Preparedness & Engineering 830103) 84/03/21 Consolidated Edison Co of New 3pp 22823 229 24X Fiche 50-000,84/03/21,8402090043

- 8402090044 IE Info Notice 84-20. "Svc Life of Relays in Safety-Related Bys "Svc list encl JURDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50~000,84/03/21,8402090044
- 8403270245 Forwards SALP Repts 50~454/83-22.50~455/83-18.50~456/83-06 & 50~457/83-06 for 1982 Increased emphasis required in areas of HVAC & electrical system of HVAC & electrical system of EAC & Region 3. Office of Director 84/03/22 REED.C Commonwealth Edison Co. 7pp. 22770 135 24X Fichs 50~000.84/03/22, 8403270246
- --8403270260 GALP Repts 50-456/83-06 & 50-457/83-06 for 1982 Category 2 assigned in areas of piping sys & supports & electrical power supply & distribution * Repion 3, Office of Director 84/03/22 25pp 22770 203 24x Fichs 50-000,84/03/22,8403270246
- --B403270263 Forwards summary of significant findings for SALP rept which will be discussed at B30613 meeting
 HIND. J A Region 3. Office of Director 83/06/08 REED, C
 Commonwealth Edison Co 3pp 22770 228 24X
 Fiche 50-000,84/03/22,8403270246
- R Periodic operating reports & related correspondence
- B403220120 Annual whole body external exposures for 1983 W/840316 ltr RYBAK.B Commonwealth Edison Co B3/12/31 7pp 22716 007 24X Fiche 50-000.B3/12/31,B403220120
- 8403020443 Forwards monthly status rept of offsite emergency preparedness for OL reviews for Jan 1984 Changes in FEMA finding dates not caused by delay due to offsite emergency planning issues
 DIRCKSI N J Office of the Executive Director for Operations
 84/02/21 PALLADINO Commissioners 7pp 22492 083, 24X
 Fiche 50~000,84/02/21,8403020443
- S Reportable occurrences, LERs & related correspondence
- 8403120013 Interim Deficiency Rept 84-01 re need to improve LK Comstock documentation filing sys Initially reported on 840131 LK Comstock provided three level review to prevent incomplete or unacceptable filing final rept by 840501 SWARTZ, C D Commonwealth Edison Co 84/03/02 KEPPLER, J Q Region 3, Office of Director 3pp 22588 031 24X Fichs 50-456,84/03/02,8403120013
- 8403140122 Part 21 rept re status update concerning abnormal wear on linear converters Test program Underway Results of investigation indicate excessive wear caused by hunting of control circuitry DDDSON.J P Pacific Air Products Co 84/03/09 Director's Office, Office of Inspection and Enforcement 7pp 22624.068. 24% Fiche 50-000.84/03/09.8403140122
- 8403190193 Final Deficiency Rept 84-02 re incorrectly wired distribution panel IDCOSE Initially reported on 840207, Internal wiring revised to meet approved design drawings Revs to be completed by June 1984 SWARTZ, E D Commonwealth Edison Co 84/03/12 KEPPLER, J. Q. Region 3, Office of Director 2pp 22674 205 24X Fiche 50-456, 84/03/12, 8403190193
- T Hearing transcripts on non-antitrust matters
- 8403130222 Transcript of ACRS Subcommittee on Braidwood Station 840308 meeting in Joliet, IL Pp 1-163 Viewpraphs enci
 * ACRS Advisory Committee on Reactor Safeguards 84/03/08,
 185pp 22605 195 24X Fiche 50-456.84/03/08,8403130222.
- 8403140008 Transcript of ACRB Subcommittee on Braidwood Station B40309 meeting in Joliet IL Pp 164-283 Supporting documentation encl

 * ACRB ~ Advisory Committee on Reactor Bafeguards 84/03/09, 379pp 22631 055 24X Fiche 50-456.84/03/09, 8403140008.
- DUCKET STN-50-457 BRAIDWOOD STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8403010106 Forwards add1 info re design of Category 1 masonry walls.
 Rept identifies all cracks & explains why cracks do not
 compromise structural integrity of walls
 TRAMM-TR Commonwealth Edison Co 84/02/22 DENTON, HR Office
 of Nuclear Reactor Regulation, Director 16pp. 22436-041 24X
 Fiche 50-000,84/02/22,8403010106

- ### 403060245 Forwards revised info re preservice exam & testing of snubbers at facilities Encl testing program supercedes program provided in #80319 ltr & accepted in SSER 12

 TRAMM.T R Commonwealth Edison Co ### DENTON.H R Office of Nuclear Reactor Regulation. Director 1p 22516 013 24X Fichs 80-000.84/02/28, 40306024.
- --8403060267 Rev 1 to "Preservice Testing (Preservice Insp) Program Plan for Shubbers " * Commonwealth Edison Co 83/10/21 47pp 22516 014 24X Fiche 50-000,84/02/28,8403060245
- \$403060394 Advises of changes to schedules for initial fuel leading of facilities Requests NRC resources be allocated to support fuel load after resolution of pending license appeal REED.C Commonwealth Edison Co 84/02/28 DENTUN,H R Office of Nuclear Reactor Regulation, Director 2pp 22518 130 24X Fiche.50~000.84/02/28,8403060394
- 1403050119 Forwards supplemental response to Generic Ltr 83-28, "Required Actions Based on Generic Implications of Balem ATMS Events "
 - BARNES:PL Commonwealth Edison Co 84/02/29 DENTON,H R Office of Nuclear Reactor Regulation, Director 26pp 22488 084 24X Fichs.50-000:84/02/27,8403050119
- 403260182 Clarifies NUREQ-0737. Item II K 3 31, in response to Generic Ltr 83-35 Westinghouse Dwners Group authorized program to demonstrate conservation of WFLAGH small break LOCA analyses, per Item II K 3 30 BARNES, P L Commonwealth Edison Co. 84/03/21 EISENHUT, D C Division of Licensing 1p 22756 170 24X Fiche 50-000, 84/03/21. 8403240182
- NRC Draft/Final Environmental Statements, supple & correspondence
- 403130037 Ack receipt of DES Meeting tenatively scheduled for 840222 for consideration by Governmental Svcs Committee * Illinois, State of 84/02/02 STEVENS, J A Division of Licensing lpp 22613 362 24X Fiche 50-456,84/02/02,8403130037
- ‡03060313 Provides comments on DES (NUREG-1026) Justification for not providing design analysis of seismic event requested ETCHI80N,D lilinois, State of, Dept Nuc Bafety (formerly Dept Public Health) 84/02/22. Division of Licensing. 3pp. 22515 330 24X Fichs 50-456,84/02/22,8403060313
- I-O3080227 Lists concerns on proposed water supply sys discussed in Dec 1983 DES (NUREG-1026), including degradation of water quality from cooling water discharge to Kankakee River QALLAGHER, J R Will County, IL 84/03/02 Division of Licensing ip. 2256: 031 24X Fiche 50-456,84/03/02,8403080227
- O3130057 Comments on DES (NUREO-1026) for facility DES does must completely describe fuel cycle impact & should contain a tatement re range of nonfatal cancer injuries & birth defects induced by fuel cycle Rn-222
 DOHERTY, J.F. Doherty, J.F. B4/03/07 STEVENS, J. A. Division of Licensing, 2pp 22601 117 24X Fiche: 50-456, 84/03/07.8403130057
- O3130474 Forwards comments on DES re operation of facilities Major environ concerns identified during 1970s & appropriate matigating actions to alleviate concerns adequately reflected. More data re aquatic impact should be referenced SENNEY, D Illinois, Btate of 84/03/08 Division of Licensing App. 22613:357. 24% Fiche 50-456.84/03/08.8403130474.
- PGR200104 Discusses review of DEB. Facility will employ two PWRs population provide addless to proposed in eration PES should provide addless treatment system. Provide addless treatment system. Provide addless treatment system. Provide addless provide ad
- NRC Safety Evaluation Report (SER), supplie & correspondence
- SOB0179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B caument entirely withheld (ref FOIA Exemption 5) Review of Gidl documents subj to request continuing ELTON, J K Division of Rules and Records 84/02/13 ANDERSON, S I Dervey, Schubert Adams & Barer 7pp 22583 226, 24X ichs: 50-000, 84/02/13, 8403080179

- --8005130793 Provides status of SER inputs & acceptance reviews for GL & CP applications Schedule should be met BURKE, W C Effluent Treatment Systems Branch 90/02/06 KREGER, W E Assistant Director for Site Analysis ip 22583 235 24% Fiche 50-000. 84/02/13, 8403080179
- 8403010120 Forwards add1 info to B31230 submittal re NUREG-0737. Item III D 1 i, "Primary Coolant Outside Containment " Rev identifies portions of sys not to be tested & responds to NRC comments Info should close SER Confirmatory Issue 28 TRAMM.T R Commonwealth Edison Co 84/02/22 DENTON, H R Office of Nuclear Reactor Regulation, Director Bpp 22432 002 24X Fiche 30-000.84/02/22.8403010120
- 8403010284 Provides add1 info re effects of local intense precipitation at facilities Info resolves Confirmatory Issue A 2 identified in SER Reinforced concrete curbs provided at exterior grade floor level doors

 IRAMM.T R Commonwealth Edison Co 84/02/22 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 22434 257 24X Fiche 50-000-84/02/22-8403010286
- 8403260132 Submits add1 info re design of hydrogen recombiners per Section 6 2 5 of SER Hydrogen recombiners operate in parallel, utilizing same suction & exhaust piping for each containment Diagram encl TRAMM.T R Commonwealth Edison Co 84/02/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22758 147 24X Fiche 50-000,84/02/22,8403260132
- F Security, medical, emergency & fire protection plans
- 8403020198 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by licensee, per 810709 Generic Ltr 81-27 W/o request, entire plan will be placed in FDR YOUNGBLODD, B J Licensing Branch 1 84/02/21 FARRAR, D L Comnonwealth Edison Co 2pp 22474 360 24X Fiche 50-000, 84/02/21, 8403020198
- 8403120008 Advises of 840323 regional workshop in Rosemont. IL w/all Region III litensees to discuss fire protection safe shutdown requirements of 10CFR50. App R Agenda encl SPESSARD. R L Division of Emergency Preparedness & Operational Support 84/03/06 REED, C Commonwealth Edison Co 3pp 22386 260 24X Fichs 50-495.84/03/06.8403120008
- 8403260346 Rev 1 to Emergency Plan Implementing Procedure 9ZP 380-3, "Post-Accident Stack Sampling of Wide-Range Gas Monitor (WRGM)" * Commonwealth Edison Co 84/03/15 5pp 22751 035 24X Fiche 50-000,84/03/15,8403260346

G Adjudicatory correspondence

- B403140040 Comments of JF Doberty on DES (NUREG-1026) Statement must clarify if in analysis of environ impacts of postulated accidents, any credit given for applicant compliance w/any TMT-related requirements Related correspondence DOHERT, JF Affiliation Not Assigned 84/03/07 STEVENS, JA Division of Licensing 2pp 22633 120 24% Fiche 50-456.84/03/07.8403140040
- 8403160011 Forwards C Reed 840228 ltr re schedule for fuel loading dates & notice of appearance W/o notice of appearance Related correspondence GALLO.J Isham Lincoln & Beale GALLO.J Commonwealth Edison Co 84/03/13 MILLER.M E . CALLIHAN.A D . CDLE.R F Atomic Safety and Licensing Board Panel 3pp 22655 id8 24X Fiche 50-456,84/03/13.8403160011
- 8403140023 Notice of appearance in proceeding Certificate of Syc encl GALLO, J Commonwealth Edison Co GALLO, J Isham, Lincoln & Beale 84/03/13 2pp 22453 353 24X Fiche 50-456,84/03/13,8403140023
- B403260361 Notice of appearance in proceeding Certificate of Svc encl BLDOM, J & Commonwealth Edison Co BLOOM, J @ Isham, Lincoln & Beale DSB 086 84/03/22 3pp 22760 074 24X Fiche 50-496.84/03/22.8403260361
- Q Inspection reports. IE Bulletins & correspondence
- 8403050043 Forwards Rev O to "Corporate Regulatory Performance Improvement Plan" Plan designed to heighten employee awareness & strengthen corporate ability to improve regulatory performance THOMAS.B Commonwealth Edison Co 84/02/24 KEPPLER.J. Q Region 3. Office of Director 3pp 22490 139 24% Fiche 50-000,84/02/24. 8403050043

- --8403050046 Rev 0 to "Corporate Regulatory Performance Improvement Plan "
 - * Commonwealth Edison Co 84/02/29 22pp 22490 142 24x Fiche 50~000:84/02/24,8403050043
- 8401190078 IE Info Notice 84-13. "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list
 - JGRDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York. Inc. 113pp 22909 239 24X Fiche 50-000,84/02/28,8401190072
- 8403050245 Forwards revised info re preservice exam & testing of snubbers at facilities Enci testing program supercedes program provided in 820319 ltr & accepted in SSER 12 TRAMM.T R Commonwealth Edison Co 84/02/28 DENTON, H R Office of Nuclear Reactor Regulation. Director ip 22516 013 24X Fiche 50-000.84/02/28.8403060285
- --8403060267 Rev 1 to "Preservice Testing (Preservice Insp.) Program Plen for Enubbers "

 * Commonwealth Edison Co 83/10/21 47pp 22516 014 24X Fiche 30-008,84/02/28,8403040245
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl ORACE.J N Division of QA. Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000,84/03/02,8402090007
- 8402090009 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc 11st encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New Yark, Inc 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008
- 8402090009 IF Info Notice 84-15, "Reporting of Radiological Releases" Evr list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8402090024 IE Info Notice 84-09, Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 32635 049 24X Fiche 50-000,84/03/07,8402090024
- B402090028 IE Info Notice B4-18, "Stress Corrosion Cracking in PWR Sys " Svc list encl JDRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc. 118pp 22584 186 24X Fiche 50-000.84/03/07,8402090028
- 8402090031 IE Bulletin B4-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl DEYGUNG.R C Director's Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000.84/03/12.8402070031
- 8403300026 Forwards IE Insp Repts 50-456/84-03 & 50-457/84-03 on 840228-0302 No noncompliance noted PAPERIELLOC J Region 3, Office of Director 84/03/16 REED, C Commonwealth Edison Co. 2pp 22819 297 24X Fiche 50-456/84/03/16.
- --B403300033 IE Insp Repts 50-456/84-03 & 50-457/84-03 on 840228-0302 No violations or deviations identified Major areas inspected mgt controls (A. chemistry program & procedures, actions taken re-previous items of noncomplicance & open items OESTMANN.M J. SLAWINSKI.W J. SCHUMACHER.M C Region 3, Office of Director B4/03/15 8pp 22819 299 24X Fiche 50-456,84/03/16.
- 8403230088 Ack receipt of regulatory performance improvement plan
 Periodic meetings requested to discuss progress on program
 5 provide feedback
 KEPPLER.J G Region 3, Office of Director 84/03/20 THOMAS.B
 Commonwealth Edison Co ip 22730 161 24X Fiche 50-000,84/03/20.
- --8403230107 Forwards corporate regulatory performance improvement plan THOMAS. B Commonwealth Edison Co 84/02/24 KEPPLER. J 0 Region 3, Office of Director 3pp 22730 162 24X Fiche 50-000, 84/03/20,8403230089

- --B403230126 Rev O to "Corporate Regulatory Performance Improvement Plan For Dresden. Guad Cities, Zion & LaSalle Operating Nuclear Stations & Byron & Braidwood Project Operating Organizations " * Commonwealth Edison Co B4/02/29 22pp 22790 165 24X Fiche 50-000, 84/03/20, 8403230088
- 8403260196 Forwards responses to IE Bulletin 83-07. "Apparently Fraudulent Products Sold by Ray Miller. Inc " Quad Cities supplied w/piping matls from Ray Miller, Inc during const Evaluation encl Concerns of IE Bulletin 83-06 satisfied BARNES,P L Commonwealth Edison Co 84/03/20 KEPPLER,J Q Region 3, Office of Director 19pp 22756 185 24X Fichs 50-000,84/03/20.8403260196
- 8402090043 IE Info Notice 84-19. "Two Events Involving Unauthorizad Entries into PWR Reactor Cavities" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc. 123pp 22823 229 24% Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys "Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24% Fithe 50-000, 84/03/21,1402090044
- 8403270246 Forwards SALP Repts 50-454/83-22, 50-455/83-18, 50-456/83-06 & 50-457/83-06 for 1982 Increased emphasis required in areas of HVAC & electrical says KEPPLER, J O Region 3: Office of Director 84/03/22 REED, C Commonwealth Edison Co 7pp 22770 135 24X Fiche 50-000, 84/03/22, 8403270244
- --8403270263 Forwards summary of significant findings for BALP rept which will be discussed at 830613 meeting
 HIND.J A Region 3. Office of Director 83/06/08 REED, C
 Commonwealth Edison Co 3pp 22770 228 24X
 Fiche 50-000,84/03/22.8403270246
- R Periodic operating reports & related correspondence
- 8403220120 Annual whole body external exposures for 1983 H/B40316 ltr RYBAK, B Commonwealth Edison Co B3/12/31, 7pp 22716 007 24X Fiche 50-000, B3/12/31, B403220120
- 8 Reportable occurrences, LERs & related correspondence
- 8403120013 Interim Deficiency Rept 84-01 re need to improve LK Comstock documentation filing sys Initially reported on 840131 LK Comstock provided three level review to prevent incomplete or unacceptable filing Final rept by 840501 SWARTZ. E D Commonwealth Edison Co 84/03/02 KEPPLER, J Q Region 3, Office of Director 3pp 22588 031 24X Fiche 50-456,84/03/02, 8403120013
- 8403190193 Final Deficiency Rept 84-02 re incorrectly wired distribution panel IDCOSE Initially reported on 840207. Internal wiring revised to meet approved design drawings Revs to be completed by June 1984 SWARTZ.E D Commonwealth Edison Co 84/03/12 KEPPLER, J. Q Region 3, Office of Director 2pp 22674 205 24X Fiche 50-454,84/03/12,8403190193
- T Hearing transcripts on non-antitrust matters
- 8403130222 Transcript of ACRS Subcommittee on Braidwood Station 840308 meeting in Joliet IL Pp 1-163 Viewgraphs encl
 * ACRS Advisory Committee on Reactor Safeguards 84/03/08 185pp 22605 195 24X Fithe 50-456.84/03/08.8403130222
- 8403140008 Transcript of ACRS Subcommittee on Braidwood Station 840309 meeting in Joliet, IL Pp 164-283 Supporting documentation encl

 # ACRS Advisory Committee on Reactor Safeguards 84/03/09 379pp 22631 055 24X Fiche 50-456,84/03/09,8403140008

- DOCKET 50-458 RIVER BEND STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8403070061 Forwards responses to Containment Sys Branch Questions 480 7 & 480 16 re PRV & major components & suppression pool bypass leakage & FEAR revs to be included in next amend BOOKER, J E Quif States Utilities Co 84/02/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 16pp 22541 310 24X Fiche: 50-458,84/02/17,8403070061
- 8403080378 Forwards responses to NRC 840106 questions re FSAR revs. including info re training staff qualifications 0A staff qualifications. (A staff qualifications, fire protection training & conformance to Reg Guide 8 13 Proposed revs to FSAR also encl BOOKER. J E Gulf States Utilities Co 84/02/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 42pp 22356 200 24X Fiche 50-458, 84/02/17, 8403080378
- 8403070350 Forwards request for add1 info re spent fuel rack welding details & structural design.based on review of application for OL SCHWENCER.A. Licensing Branch 2 84/02/23 CAHILL.W J. BOOKER.J E Gulf States Utilities Co Spp 22564 127 24X Fichs 50-458,84/02/23,8403070350
- 8403010321 Notifies that structures adjacent to Unit 2 excavation area under analysis for effects of excavation ponding per revised design basis flood analysis Ponding will not produce significant add1 structural loads BODKER, J. E. Quif States Utilities Co. 84/02/27 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 1p 22432.101 24X Fichs. 50-458, 84/02/27, 8403010321
- 8403070052 Forwards clarifications to Procedures & Sys Review Branch questions. Changes to FSAR will be incorporated in next amend BOOKER, J E Quif States Utilities Co 84/02/27 DENTON, H R Office of Nuclear Reactor Regulation. Director 21pp 22541 102 24X Fiche: 50-458, 64/02/27, 6403070052
- 8403020274 Provides info re status of generic & plant-specific work concerning containment issues raised by Humphreys, per util 830815 commitment Status rept will be provided by 840731 BOCKER, J E Oulf States Utilities Co. 84/02/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 22440, 048 24% Ficher 50-458, 84/02/28, 8403020294
- 840305007B Forwards "Historical & Archaeological Investigation of Ruins of Nineteenth Century Sugar Mill (16WF-36) in West Feliciana Parish.LA " Determination re Natl Register #ligibility requested BOOKER, J E Gulf States Utilities Co 84/03/01 DEBLIEUX.R.B Louisiana, State of 1p 22485 152 24X Fiche 50-458,84/03/01.
- --8403050081 "Historical & Archaeological Investigation of Ruins of Nineteenth Century Sugar Mill (16WF-36) in West Feliciana Parigh.LA " BHUMAN, M K Affiliation Not Assigned ORBER, C E Louisians Stat Univ 84/02/10 56pp 22485 153 24X Fichs 50-458,84/03/01, 8403050078
- 8403070010 Forwards calculated methodology for source terms & source distribution pathways based on design basis LOCA for equipment qualification radiation environs BOOKER, J. E. Quif States Utilities Co. 84/03/01 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 5pp 22547 332 24X Fiche 50~458,84/03/01,8403070010
- 8403130190 Forwards response to NRC 801222 request for review of controls for handling heavy loads as committed to in 830809 ltr Response to items in Section 2 1 of 801222 ltr also encl
 BODKER, J E. Oulf States Utilities Co 84/03/01 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 63pp 22606.063
 24X Fiche 50-458,84/03/01,8403130190
- 8403210069 Forwards responses to Power Sys Branch request for add1 info re mat1 contained in 831230 & 840210 correspondence, including diesel generator operations training & fuel oil storage tank Changes will be incorporated in FSAR amend BOOKER, J E Gulf States Utilities Co. 84/03/05 DENTON, H R Office of Nuclear Reactor Regulation, Director 150pp 22702 124 24X Fiche 50~458,84/03/05.8403210069
- 8403260180 Forwards operating shift experience tables.per DF Bchnsll request
 ODELL.W H. Gulf States Utilities Co. 84/03/06 THOMPSON,H
 Division of Human Factors Safety 9pp 22751 046 24X
 Fichs. 50-458, 84/03/06, 8403260180

- 8403300292 Summary of 840215 meeting w/util in Bethesda, MD re Power Bys Branch review items Topics discussed re mechanical & electrical areas identified Attendee list encl WEINKAM.E J Licensing Branch 2 84/03/06 Licensing Branch 2 5pp. 22844 321 24X Fichs 50-458.84/03/06.8403300292
- 8403200034 Forwards response to Power Sys Branch request for addlessed info re communications sys, lighting sys & circuit configuration curves Written changes to FSAR text, including table & figures, also encl BODKER, J E Gulf States Utilities Co 84/03/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 22pp 22685 145 24X Fiche 50-488,84/03/07,8403200034
- 8403260291 Forwards organization charts re corporate structure.plant administrative structure & project mgt structure Changes will be supplied in form of FSAR text rev in future submittal & FSAR amend BOOKER.J E Gulf States Utilities Co 84/03/16 DENTON.H R Office of Nuclear Reactor Regulation. Director ip 22751 070 Fiche 50-458.84/03/16.8403260291
- 8403220209 Forwards Army Corps of Engineers 831127 ltr re Old River Control project in response to NRC request Damage sustained by low sill structure in 1973 resolved W/four oversize brochures Aperture cards are available in FDR BOOKER. J E Oulf States Utilities Co 84/03/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 15pp 22718 193 24X Fiche 50-458,84/03/19,8403220209
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8403070062 Forwards supplemental responses to requests for addl info draft SER open items, identified by Mechanical Engineering Branch in 831229 ltr Where indicated, responses will be provided in future amend to FSAR BOOKER, J E Oulf States Utilities Co 84/02/21 DENTON, H R Office of Nuclear Reactor Regulation, Director 27pp 22548 014 24X Fiche 50~458,84/02/21.8403070062
- 8403130067 Forwards responses to open items in Auxiliary Sys Branch draft SER & NRC 810805 & 1231 requests for add1 info Responses supplement util 831201.30 & 840802 submittals BOOKER.J E Oulf States Utilities Co 84703/06 DENTON.H R Office of Nuclear Reactor Regulation, Director 25pp 22615-222 247 Fiche 50-458,84703/06,8403130067
- B403190017 Forwards response to NRC B40123 position re drywsll/containment purge sys Discussions held on 840131 w/Containment Sys Branch clarified bases for position to detailed util responses for input to SER
 BOOKER, J E Oulf States Utilities Co 84/03/13 DENTON, H R
 Office of Nuclear Reactor Regulation, Director Opp 22665 354
 24X Fiche 50-458,84/03/13,8403190017
- F Security, medical, emergency & fire protection plans
- 840326060 Forwards IE Coordination Meeting Rept 50~438/83-18 on 831003 No violations or deviations identified JOHNSON,E H. Region 4, Office of Director 84/01/12 CAHILL,W J Gulf States Utilities Co. 2pp. 22746 360 24X Fiche 50~458.84/01/12.8403260060
- --8403260068 IE Coordination Meeting Rept 50-458/83-18 on 831003 No violations or deviations identified Details withheld (ref 10CFR2 790). KELLY,J A. HALL,R E. CROSSMAN,W A. Region 4, Office of Director 83/12/30 ip 22746 362 24X Fiche 80-458.84/01/12.8403260060
- 8403260217 Forwards IE Insp Rept 50-458/84-03 on 840109-13 No violations or deviations noted JOHNSON, E H Region 4, Office of Director 84/02/06 CAHILL, W Gulf States Utilities Co 2pp 22756 154 24% Fiche, 50-458, 84/02/06, 8403260217
- --8403260220 IE Insp Rept 50-458/84-03 on 840107-13 No violations or deviations noted Major areas inspected physical security plan & implementing procedures Details withheld (ref 100FR73 21)

 EVANS.C A. KELLY.J A. CROBSMAN.W A Region 4. Office of Director 84/02/06 ip 22756 156 24X Fiche 50-458.84/02/06, 8403260217
- B403030143 Notifies that NRC will provide inspectors to observe onsite aspects of periodic exercises for emergency preparedness Scenario for submission of info listed COLLINB.J T. Region A. Office of Director B4/02/09 CAHILL.W.J. Quif States Utilities Co. 2pp. 22487 310 24X Fiche 50-458.84/02/09.8403050145

- 8403080378 Forwards responses to NRC 840106 questions re FSAR revs, including info re training staff qualifications. 8A staff qualifications, fire protection training & conformance to Reg Guide B i3 Proposed revs to FSAR also enti 800KER, J E Guif States Utilities Co 84/02/17 DENTON, H R Office of Nuclear Reactor Regulation. Director 42pp 22556 200 24X Fiche 50-458,84/02/17,8403080378
- 8403130486 Forwards add1 info re Generic Ltr 82-33. "Suppl 1 to NUREO-0737 Requirements for Emergency Response Capability "
 Info suppls emergency operating procedures generation
 package submitted 830831
 BOUKER, J E Gulf States Utilities Co 84/02/27 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 4pp 22614 009
 24X Fiche 30-458.84/02/27.8403130486
- --8403130487 Rev 1 to Procedure ADM-0003, "Development, Control & Use of Procedures " HAMMON, E Gulf States Utilities Co 84/02/13 38pp 22614 013 24X Fiche 50-458,84/02/27,8403130486
- B403140196 Notification of 840314 meeting w/util & S&W in Bethesda.MD to discuss design of control room w/respect to fire protection alternate & safe shutdom WEINKAM,E J Licensing Branch 2 84/03/02 SCHWENCER.A Licensin Branch 2 3pp 22637 352 24X Fiche 50-458,84/03/02,8403140196
- 8403130373 Forwards Rev 2 to physical security plan & explanation of major changes to facilitate review Rev & explanation withheld (ref 10CFR2 790) CAMILL, W J Gulf States Utilities Co 84/03/07 DENTON, H R Dffice of Nuclear Reactor Regulation, Director 1p 22616 273 24X Fiche 50-458,84/03/07.8403130393
- G Adjudicatory correspondence
- B403140009 Forwards offsite emergency planning Contentions i-12 WATKINS, L B Watkins, L B 84/03/09 Atomic Safety and Licensing Board Panel ip 22633 267 24% Fiche 50-458,84/03/09,8403140009
- --8403140012 Proposed emergency planning Contentions 1-12, identifying major flaws in emergency plan Certificate of Syc encl IRVING.8 M. WATKING.L B. PIERGE.J W. Joint Intervenors River Bend 84/03/13 Atomic Safety and Licensing Board Panel 20pt 22633 248 24X Fiche 50-458.84/03/09.8403140009
- 8403270372 Answer opposing Joint Intervenors 840307 contentions re offsite emergency planning No contention meets basis & specificity requirements of 10CFR2 714 W/svc list WETTERHAHN, M J Gulf States Utilities Co WETTERHAHN, M J Conner & Wetterhahn DSB 193 84/03/26 Atomic Safety and Licensing Board Panel 38pp 22814 342 24% Fiche 50-458,84/03/26,8403270372
- 8403300025 Order establishing purpose of 840418 prehearing conference Berved on 840329 COTTER.B P Atomic Safety and Licensing Board Panel 84/03/28 3pp 22822 882 24X Fiche 50-458,84/03/28,8403300025

M Antitrust correspondence

- 8403220271 Requests clarification t/or comments on listed items or documents as result of review of updated responses to Reg Ouide 9 3.per antitrust review Response requested within 14 days from 1tr date REGAN, H Site Analysis Branch 84/03/12 CAHILL, H J Guif States Utilities Co 3pp 22723 319 24% Fiche 50-458.84/03/12, 840320271
- B403280161 Ack receipt of B30915 & 840203 ltrs responding to NRC request for add1 info re antitrust review Listed add1 info requested within 14 days of ltr receipt & prior to setting up meeting to resolve issues
 REGAN,W H Site Analysis Branch 84/03/12 SPIECEL, G Spiegel, C 2pp 22809 292 24X Fichs 50-458, 84/03/12, 8403280161
- 8403280032 Forwards response to 840312 request for add1 info re antitrust review & draft proposed reliability coordination agreement Draft agreement prepared by Middle South Utils unacceptable CAHILL.W J Gulf States Utilities Co 84/03/23 REGAN.W H Siting Analysis Branch. 1,673pp 22778 116 24X Fiche 50-458,84/03/23,84032800032
- 8403270176 Forwards addit matts requested in NRC 840312 ltr retartivest review Util attempting to lock St Martinville into renewad long-term commitment GUTTHAN, D. Spiegel & McDiarmid 84/03/26 REGAN, W. Site Analysis Branch 226pp 22802 210 24X Fiche 50-458,84/03/26,8403270176

- 9 Inspection reports, IE Bulletins & correspondence
- 8403260060 Forwards IE Coordination Meeting Rept 50-458/83-18 on 831003 No violations or deviations identified JOHNSON.E H Region 4, Office of Director 84/0i/12 CAHILL.W J Gulf States Utilities Co 2pp 22746 360 24X Fiche 50-458.84/01/12.8403260060
- --8403260068 IE Coordination Meeting Rept 50-458/83-18 on 831003 No violations or deviations identified Details withheld (ref 10CFR2 790)
 KELLY,J A, HALL,R E, CROBSMAN,W A Region 4, Office of Director 83/12/30 ip 22746 362 24X Fiche 50-458,84/01/12,8403260060
- 8403260217 Forwards IE Insp Rept 50-458/84-03 on 840109-13. No violations or deviations noted JOHNSON, E H Region 4, Office of Director 84/02/06 CAHILL, W Oulf States Utilities Co 2pp 22756 154 24X Fiche 50-458,84/02/06.8403260217
- --8403260220 IE Insp Rept 50-458/84-03 on 840109-13 No violations or deviations noted Major areas inspected physical security plan & implementing procedures Details withheld (ref 100FR73 21)
 EVANS, C A / KELLY, J A / CROSSMAN, W A Region 4, Office of Director 84/02/06 1p 22756 136 24X Fiche 50-458,84/02/06,8403260217
- 8403050127 Forwards IE Insp Rept 50-458/83-21 on 831118-840120. No violations or deviations noted JOHNSON.E H Region 4. Office of Director. 84/02/14 CAHILL, W J Quif States Utilities Co 2pp 22487 102 24X Fiche 50-458.84/02/14.8403050127
- --B403050134 IE Insp Rept 50-45B/B3-Q1 on B3111B-840120 No violations or deviations noted Major areas inspected site tour.licensee identified deficiency rept.safety-related piping & hanger installation & electrical cable & raceway installation. FARRELL R E , CROSBMAN, M A Region 4, Office of Director 84/02/14 5pp 22489 104 24X Fiche 50-45B.84/02/14.8403050129
- B403120065 Forwards IE Insp Rept 50-458/83-22 on 831201-840131 & notice of violation
 JOHNSON, E H Region 4, Office of Director 84/02/22 CAHILL, W J, Gulf States Utilities Co 2pp 22586 272 24X
 Fiche 30-458,84/02/22,8403120065
- --8403120067 Notice of violation from insp on 831201-840131. * Region 4, Office of Director 84/02/22 3pp 22586 294 24X Ficha 50-458,84/02/22,8403120065
- --8403120072 IE Insp Rept 50-458/83-22 nn 831201-840131 Violation identified failure of followup action in audit program & records of activities affecting quality not identifiable or retrievable.

 CHAMBERLAIN, D., CROSSMAN, W. A. Region 4. Office of Director 84/02/21 5pp 22586 297 24X Fiche 50-458,84/02/22,8403120065
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22909 239 24X Fiche 50-000,84/02/28,8401190072
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl GRACE, J N Division of GA: Bafeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edieon Co. of New York, Inc. 130pp 22552:329 24X Fichs 50-000:84/03/02,8402090007.
- 8402070008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 122pp 22553 098 24X Fiche.50-000,84/03/02,8402070008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases" 8vc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JDRDAN,E L Division of Emergency Preparadness & Engineering Response (Post 830103) 84/03/03. Consolidated Edison Co. of New York, Inc 117pp 22553 336 24X Fiche.50-000,84/03/03,8402090011

- 8402070024 IE Info Notice 84-07.Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22638 049 24X Fiche 50-000,84/03/07,8402090024
- 8402090026 IE Info Natice 84-18, "Stress Carrosion Cracking in PWR Bys " Svc list encl JORDANNE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Cansolidated Edison Co of New York, Inc 118pp 22584 184 24X Fiche 50-000,84/03/07,8402090028
- 8403130438 Ack receipt of 840206 ltr informing NRC of steps taken to torrect violations noted in IE Insp Rept 50-458/83-20 JOHNSDN,E H Region 4, Office of Director 84/03/08 CAHILL,W J Oulf 8 tates Utilities Co 1p. 82613 318 24X Fiche 50-458, 84/03/08.8403130438
- --8403130448 Responds to NRC 840105 ltr re violations noted in IE Insp. Rept 50-488/83-20 Corrective actions FSAR changed per Change Notice F8 3 9:Rev i, to accurately reflect loading calculation
 CAHILL.M.J. Gulf States Utilities Co. 84/02/06 COLLINS, J T. Region 4, Office of Director 4pp. \$22613 319 24X Fiche 50-459,84/03/08,8403130438
- 8402090031 IE Bulletin 84-02. "Failures of GE Type HFA Relays in Use in Class IE Bafety 8ys " 8vc list encl DEVOUNG, R C. Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823,094 24X Fiche 50-000.84/03/12,8402090031.
- 8403160235 Forwards vendor insp repts identifying concerns found by Vendor Program Branch during insp of vendor activities Evaluation of significance of findings re quality & acceptability of product or svc requested JDHNSON,E H Region 4, Office of Director 84/03/13 CAHILL,W 8 Quif States Velilities Co 2pp 22661 043 24X Fiche 50-458,84/03/13,8403160235
- B402070043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PHR Reactor Cavities " Evo]ist encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Reseases (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 123pp 22823 229, 24X Fiche, 50-000, 84/03/21, 8402070043
- 8402070044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Bys " Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044
- 8403270070 Ack receipt of 840217 ltr informing NRC of steps taken to correct violations noted in JE Insp Rept 30-458/83-19 JOHNBON,E.H Region 4. Office of Director. 84/03/23 CAHILL,H J Oulf States Utilities Co ip 22766 327 24X fiche 80-458, 84/03/23,8403270070.
- --8403270076 Responds to NRC 840120 ltr re violations noted in IE Insp Rept 50-458/83-19 Corrective actions Process Requirement Bheet (PRS) 2 re socket welds revised & Insp personnel retrained to requirements of GAI 10-1 & PRS-02, Rev 7. CAHILL.M. J. Quif States Utilities Co. 84/02/17 COLLINS, J.T. Region 4, Office of Director. 4pp 22766:328 24X Fishe 50-458,84/03/23,8403270070.
- R. Periodic operating reports & related correspondence
- B403020443 Forwards monthly status rept of offsite emergency preparedness for OL reviews for Jan 1984 Changes in FEMA finding dates not caused by delay due to offsite emergency planning issues.

 DIRCKS.W.J. Office of the Executive Director for Operations B4/02/21. PALLADINO Commissioners 9pp 22492.083, 24X Fiche.50-000.84/02/21.8403020443
- 😝. Reportable occurrences, LERs & related correspondence
- 8403010451 Informs Commission of problems w/emergency diesel generators mfg by Trensemerica Delaval, Inc DIRCKS: M. J. Office of the Executive Director for Operations 8ECY-03-034 84/01/25 4pp. 22438 347 24X Fiche 50-000,84/01/25,8403010451.
- **B403010073 Interim Deficiency Rept DR-147 re end attachment of pipe support component supplied by Bergen-Paterson, Investigation continuing, Next rept expected by B40403 BOOKER, J.E. Gulf Btates Utilities Co. 84/02/23 COLLINS, J. T. Region 4, Office of Director. 1p. 22432-001, 24X Fiche: 50-458, 84/02/23, 8403010073.

- 8403010228 Interim Deficiency Rept DR-134 re four lines located at outlet of each RHR sys HX shell Investigation incomplete
 Nert status rept will be submitted by 840425
 BODKER, J E Oulf States Utilities Co 84/02/23 COLLINS, J T
 Region 4. Office of Director 1p 22435 176 24X
 Fiche 50-458,84/02/23.8403010228
- B403010379 Interim Deficiency Rept DR-162 re ASOL10 trip coils supplie by Gould Investigation incomplete Next rept will be submittd by B40430 BOCKER, J E Gulf States Utilities Co B4/02/23 COLLINS, J T Region 4. Office of Director 1p 22434 OS1 24x Fiche 50~458, B4/02/23, 8403010379
- B403010207 Forwards "Investigation of Types AF & AE Piston Skirts," per Transamerica Delaval, Inc. Owners Group program commitments Rept evaluates cracks in AF piston skirts in Shoreham & Orand Gulf Nuclear Power Stations
 MUSELER. & J TDI (Transamerica Delaval, Inc.) Owners Group
 B4/02/27 DENTON. H R Office of Nuclear Reactor Regulation,
 Director 3pp 22434 090 24% Fiche 50-000, 84/02/27, 8403010207
- 8403010218 Forwards task descriptions for 16 known problems re Transamerica Delaval, Inc emergency diesel geherators MUSELER, W J TDI (Transamerica Delaval, Inc.) Owners Group 84/02/28 DENTON, H R Office of Nuclear Reactor Regulation, Director 42pp 22435 177 24X Fiche 50-000,84/02/28,8403010218
- 8403060320 Final Deficiency Rept DR-92 re Category I stainless steel thermowells supplied by PYCO, Inc Condition not reportable per 10CFR50 55(e)
 BDUKER, J E Qulf States Utilities Co 84/02/28 COLLING, J T Region 4. Office of Director ip 22517 362 24X Fiche 50-458,84/02/28,8403060320
- B403130264 Interim Deficiency Rept DR-127 re Agastat relays w/CR0095 bases supplied by GE Investigation incomplete Next rept will be submitted by B40427
 BDGKER. JE Quif States Utilities Co B4/02/28 CGLLINS, J T Region 4. Office of Director 1p 22607 138 24X
 Fiche 50-458,84/02/28,8403130264
- 8403130175 Interim Deficiency Rept DR~163 re set screw over key on drive hub for overspeed governor fuel transfer pump drive in standby diesel generator A supplied by Transamerica Delaval. Inc Investigation incomplete Next rept by 840430 BOXER, JE Gulf States Utilities Co. 84/03/02 COLLINS. J T Region 4. Office of Director 1p. 22615 298 24X Fiche 50-458.84/03/02,8403130175
- 8403140048 Forwards "Grand Gulf Component Tracking Sys," "Shoreham Component Tracking Sys" & "Transamerica Delaval, Inc Diesel Generators Owners Group Program Plan," to resolve concerns w/emergency diesel generators MUSELER.W J Long Island Lighting Co 84/03/02 DENTON, H R Office of Nuclear Reactor Regulation. Director 2pp 22626 062 24X Fiche 50-000.84/03/02.8403140048
- --8403140095 "Transamerica Delaval.Inc Diesel Generatora Gunera Group Program Plan " # TDI (Transamerica Delaval. Inc.) Gunera Group 84/03/02 261pp 22628 223 24X Fiche 50-000.84/03/02.8403140048
- 8403160310 Interim Deficiency Rept DR-164 re intermixed electrodes Investigation incomplete Next rept by 840425 BODKER, J E Guif States Utilities Co 84/03/07 CDLLING. J T Region 4. Office of Director 1p 22660 273 24X Fiche 50-458,84/03/07.8403160310
- 8402090039 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 14 meetings between NRC & Transamerica Delaval.Inc (TDI) Owners Group. Distribution list encl EISENHUT.D G Division of Licensing 84/03/12 PALLADING Commissioners 5pp 22708 001 24X Fichs 50-000.84/03/12, 840200039
- --8403060536 Forwards summary of 840210 meeting w/Transmerica Delaval.
 Inc Dumers Group in Bethesda, MD re problems w/emergency
 diese) generators
 CARUSD.R. Licensing Branch 2 84/02/27 O'REILLY, J P. NRC No
 Detailed Affiliation Oiven 6pp 22708 006. 24X
 Fiche: 30-000, 84/03/12, 8402090039
- --8403060554 Transcript of B40210 meeting w/Transamerica Delaval.Inc Owners Group in Bethesda, MD re problems w/amergency diesel generators * NRC - No Datailed Affiliation Given 84/02/10, 147pp 67201 GOB 24X Ficha 50-000,84/03/12,8402090039

- --8403070409 Summary of 840216 meeting w/Transamerica Delaval, Inc Owners Group in Wading River,NY re program plan to establish raliability of diesel generators Agenda,meeting transcript & attendance list encl MILLER,H A Licensing Branch 4 84/02/27 Licensing Branch 4 Bpp 2270B 161 24X Fiche 50-000.84/03/12.8402090039
- --B403070423 Transcript of B40216 conference in Hading River,NY re Transamerica Delaval.Inc diesel generators Pp I-B2 * Commissioners 84/02/16 B4pp 22708 169 24X Fiche 50-000,84/03/12.8402070039
- B403140050 Forwards "Design Review of Connecting Rod Bearing Shells for Transamerica Delaval Enterprise Engines" for Shoreham & Grand Gulf diesel generators MUSELER.W J Long Island Lighting Co 84/03/12 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 22632 074 24X Fiche 50-000.84/03/12.8403140050
- B403150133 Forwards "Transamerica Delavai, Inc Diesel Generator Rocker Arm Capscrew Stress Analysis Rept " Capscrew design adequate for applicable engines & svc conditions MUSELER,W J TDI (Transamerica Delaval, Inc) Owners Group 84/03/13 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 22639 270 24X Fiche 50-000,84/03/13,8403150133
- B403270039 Interim Deficiency Rept DR-166 re location of terminal blocks investigation incomplete Interim or final rept will be provided by 840511 BOOKER, J E Oulf States Utilities Co 84/03/15 COLLINS, J T Region 4, Office of Director ip 22769 321 24X Fiche 50-458,84/03/15,8403270039
- 8403270201 Interim Deficiency Rept DR-165 re copper bus bars supplied by Southern Metals Corp & Gulf Coast Supply Investigation incomplete Next rept will be provided by 840515 BODKER. J. E. Gulf States Utilities Co. 84/03/15 COLLINS, J. T. Region 4, Office of Director ip 22772 138 24X Fiche 50-458.84/03/15,8403270201
- B403200222 Responds to B40214 Requests for Info 1 & 2 re R-4 series engines List indicating engine number, model & svc number: customer name & address: rating, date shipped & date started encl MATHEMS.C S Transamerica Delaval. Inc 84/03/16 EISENHUT.D Q Division of Licensing 20pp 22691 179 24X Fiche 50-000.84/03/16.8403200222
- 8403270026 Interim Deficiency Rept DR-152 re wire terminations in 480-volt standby motor control ctrs supplied by Gould Brown Boveri Investigation incomplete Interim or final rept expected by 840514 BODKER, J E Gulf States Utilities Co 84/03/16 COLLINS, J T Region 4. Dffice of Director ip 22769 341 24X Fiche 50-458,84/03/16.8403270026
- 8403270045 Interim Deficiency Rept DR-112 re Class IE battery chargers supplied by Power Conversion Products Investigation incomplete Interim or final rept to be submitted by 840413 HODKER. J E Gulf States Utilities Co 84/03/16 COLLINS. J T Region 4. Office of Director ip 22769 314 24% Fiche 80-458.84/03/16.8403270045
- B403270132 Forwards "Emergency Diesel Generator Air Start Valve Capscrew Dimension & Stress Analysis." prepared by S&W for Transamerica Delaval. Inc (TDI) Diesel Generator Duners Group MUSELER.W J TDI (Transamerica Delaval. Inc.) Comers Group B4/03/23 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 22774 001 24% Fiche 50-000,84/03/23,8403270132
- 8403270134 Requests meeting on 840418 to discuss short-term & long-term corrective actions & investigations re Transamerica
 Delaval diesel generators List of suggested meeting topics encl
 HCGAUGHY, J P TDI (Transamerica Delaval, In.) Owners Group
 84/03/23 DENTON.H R Office of Nuclear Reactor Regulation,
 Director 4pp 22769 133 24X Fiche 50-000,84/03/23,8403270134

T Hearing transcripts on non-antitrust matters

8402070039 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delaval, Inc (TDI) Owners Group, Distribution list encl.
EISENHUT, D 9 Division of Licensing 84/03/12 PALLADINO Commissioners 5pp 22708,001 24X Fiche, 50-000, 84/03/12, 8402090039

- --8403060536 Forwards summary of 840210 meeting w/Transamerica Delaval,
 Inc Owners Group in Bethesda, MD re problems w/emergency
 diesel generators
 CARUSO.R Licensing Branch 2 84/02/27 O'REILLY, J P NRC No
 Detailed Affiliation Given 6pp 22708 006 24X
 Fiche 50-000,84/03/12,8402090039
- --B403060554 Transcript of B40210 meeting w/Transamerica Delaval, Inc Dwners Group in Bethesda, MD re problems w/emergency diesel generators * NRC - No Detailed Affiliation Given 84/02/10, 147pp 67201 008 24X Fiche 50-000, 84/03/12, 8402090039
- --8403070409 Bummary of 840216 meeting w/Trensamerica Delaval. Inc Owners Group in Wading River, NY re program plan to establish reliability of dissel generators Agenda, meeting transcript & attendance list encl MILLER, M A Licensing Branch 4 84/02/27. Licensing Branch 4. 8pp. 22708 161 24X Fichs. 50-000.84/03/12.8402090037.
- --8403070423 Transcript of 840216 conference in Wading River, NY re Transamerica Delaval. Inc diesel generators Pp 1-82. # Commissioners. 84/02/16 84pp 22708.169 24X Fiche 50-000,84/03/12.8402090037

V Operator Examinations

B403260180 Forwards operating shift experience tables,per DF Schnell request UDELL.W H Gulf States Utilities Co 84/03/06 THOMPSON,H Division of Human Factors Safety 9pp. 22751.046 24X Fiche 50-458.84/03/06.8403260180

DOCKET 50-459 RIVER BEND STATION, UNIT 2

- A Application/construction stage documents & correspondence
- 8403070061 Forwards responses to Containment Sys Branch Guestions 480 7 & 480 16 re PRV & major components & suppression pool bypass leakage & F6AR revs to be included in next amend.
 BODKER.J E Oulf States Utilities Co 84/02/17. DENTON.H R
 Office of Nuclear Reactor Regulation. Director. 16pp 22541 310
 24X Fichs 50-456.84/02/17.8403070061
- 8403080378 Forwards responses to NRC 840106 questions re FSAR revs. including info re training staff qualifications, GA staff qualifications, fire protection training & conformance to Rag Quide B 13 Proposed revs to FSAR also encl.

 BOOKER, J E Gulf States Utilities Co 84/02/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 42pp. 22556, 200 24% Fiche 50-458, 84/02/17, 8403080378
- 8403010321 Notifies that structures adjacent to Unit 2 excavation area under analysis for effects of excavation ponding per revised design basis flood analysis Ponding will not produce significant addl structural loads

 BONKER, J E Oulf States Utilities Co 84/02/27, DENTON, H R Office of Nuclear Reactor Regulation, Director 1p. 22432 101, 24X Fiche 50-458,84/02/27,8403010321
- 8403070052 Forwards clarifications to Procedures & Sys Review Branch questions Changes to FSAR will be incorporated in next amend BOUKER, JE Qulf States Utilities Co 84/02/27 DENTON, H R. Office of Nuclear Reactor Regulation, Director 21pp. 22541:102, 24X Fiche 50-458,84/02/27,8403070052
- 8403050078 Forwards "Historical & Archaeological Investigation of Ruins of Nineteenth Century Sugar Mill (16WF-36) in West Feliciana Parish LA "Determination re Natl Register sligibility requested BOOKER. J E Gulf States Utilities Co. 84/03/01 DEBLIEUX. R. B. Louisiana. State of 1p 22485 152 24X Fiche 50-458,84/03/01,8403050078.
- --84030500Bi "Historical & Archaeological Investigation of Ruins of Nineteenth Century Sugar Hill (16MF-36) in West Feliciana Parish, LA " BHUMAN, M K Affiliation Not Assigned DRBER, C. E. Louisiana State Univ 84/02/10 56pp. 22485:153 24X Fiche. 50-458, 84/02/01, 8403050078
- 8403220209 Forwards Army Corps of Engineers 831127 ltr re Old River Control project, in response to NRC request Damage sustained by low sill structure in 1973 resolved W/four oversize brochures Aperture cards are available in PDR BOOKER, J E Quif States Utilities Co 84/03/19 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 15pp. 22718:193. 24X Fiche 50-458,84/03/19,84032202009

- E. NRC Safety Evaluation Report (SER), suppls & correspondence
- ### AC3D70062 Forwards supplemental responses to requests for add1 info & freft EER open items.identified by Mechanical Engineering

 Branch in B31229 ltr Where indicated.responses will be provided in future emend to FBAR

 BOOKER.JE Gulf States Utilities Co 84/02/21 DENTON, H R

 Office of Nuclear Reactor Regulation. Director 29pp 22548 014

 24X Fiche 50-458.84/02/21,8403070062
- □ 403170017 Forwards response to NRC 840123 position re drywell/

 containment purpe sys Discussions held on 840131 w/

 Containment Sys Branch clarified bases for position &

 detailed util responses for input to SER,

 B DOKER, J E Gulf States Utilities Co 84/03/13 DENTON, H R

 Diffice of Nuclear Reactor Regulation, Director 6pp 22665 354.

 24X Fiche 50-458,84/03/13,8403190017
- F. Becurity, medical, emergency & fire protection plans
- el403130486 Forwards add1 info re Ceneric Ltr 82-33. "Buppl 1 to NUREGO 737 Requirements for Emergency Response Capability "
 Info suppls emergency operating procedures generation package submitted 830831
 BOOKER, J E Gulf States Utilities Co 84/02/27 DENTON, H R Office of Nuclear Reactor Regulation, Director. 4pp. 22614 009 24X Fiche 50-458,84/02/27,8403130486
- Adjudicatory correspondence
- B40314009 Forwards offsite emergency planning Contentions 1-12
 WATKINS.L.S Watkins. L.B 84/03/09 Atomic Safety and Licensing
 Board Panel. 1p 22633 267 24X Fiche 50-458.84/03/09.8403140009
- B403290392 Answer opposing Joint Intervenors 840309 contentions re offsite emergency planning, No contention meets basis & specificity requirements of IOCFR2.714 W/svc list WEITERHAHN/M J Gulf States Utilities Co WEITERHAHN/M, J Conner & Weiterhahn DBB 193. 84/03/26 Atomic Safety and Licensing Board Panel 38pp 22814 342 24X Fiche 50-488.84/03/26,8403290392.
- 용403300025 Order establishing purpose of 840418 prehearing conference Berved on 840329. CDTTER, B P. Atomic Safety and Licensing Board Panel 84/03/28 작pp. 22822.182. 24X Fiche: 50-458,84/03/28,8403300025
- Amspection reports, IE Bulletins & correspondence
- ORDANIE.L. Division of Emergency Preparedness & Engineering
 - CORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp. 22707:237 24X Fiche: 50-000, 84/02/28, 8401170072
- 340 2090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC." Svc list encl. GRACE, JN. Division of QA. Bafeguards & Inspection Programs (Post B30103). 84/03/02 Consolidated Edison Co of New York, Inc. \$30pp. 22552:329. 24X Fiche:50-000,84/03/02,8402090007
- PACRO90008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate." Svc list encl
 JORDAN E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103). 84/03/02 Consolidated Edison Co. of New York, Inc. 122pp 22553:098, 24X Fiche 50-000,84/03/02,8402090008
- *ORO90009 IE Info Notice 84-15, "Reporting of Radiological Releases"
 Byc 11st encl.
 JORDAN,E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co. of New
 York, Inc. 119pp. 22553:217 24X Fiche: 50-000,84/03/02,8402090009

- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc. 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8402070024 IE Info Notice 84-09.Rev i. "Lessons Learned From Inaps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN: E L Division of Emergancy Preparedness & Engineering Response (Post 820103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22435 049 24% Fiche 50-000.84/03/07,8402070024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Sys " Bvc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 30-000.84/03/07.8402090028
- 8402090031 IE Bulletin 84-02. "Failures of GE Type RFA Relays in Use in Class IE Safety Sys " Svc list encl
 DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc
 134pp 22823,094 24X Fiche 50-000,84/03/12,8402090031
- 8402070043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list and JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 123pp 22823 229 24X Fiche 50-000,84/03/21,8402070043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Bys " Bvc list end: Division of Emergency Preparedness & Engineering JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044
- S Reportable occurrences. LERs & related correspondence
- 8403010207 Forwards "Investigation of Types AF & AE Piston Skirts," per Transamerica Dalawal, Inc Owners Group program commitments Rept evaluates cracks in AF piston skirts in Shoreham & Grand Gulf Nuclear Power Stations

 MUSELER. W. J. TDI (Transamerica Dalawal, Inc.) Duners Group 84/02/27 DENTON. H.R. Office of Nuclear Reactor Regulation, Director 3pp 22434 090 24X Fiche 50-000,84/02/27,8403010207
- 840301021B Forwards task descriptions for 16 known problems re Transamerica Delaval. Inc emergency diesel generators MUSELER.W J TDI (Transamerica Delaval. Inc.) Owners Group 84/02/2B DETON.H R Office of Nuclear Reactor Regulation, Director 42pp 22435 177 24% Fichs 50-000.84/02/28.8403010218
- 840314004B Forwards "Grand Gulf Component Tracking Bys," "Shoreham Component Tracking Bys" & "Transamerica Delaval.inc Diesel Generators Owners Oroup Program Plan." to resolve concerns w/emergency diesel generators MUSELER, W J. Long Island Lighting Co. 84/03/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp. 22426 062 24X Fiche 50-000,84/03/02,8403140048
- --8403140095 "Transamerica Delaval, Inc Diesel Generators Owners Group Program Plan " * TDI (Transamerica Delaval, Inc.) Owners Group 84/03/02 261pp 22628:223 24X Fichs 50-000,84/03/02,8403140048
- 8402070039 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 14 meetings between NRC & Transamerica Delaval. Inc (TDI) Dwners Oroup Distribution list encl
 EISENHUT.D G Division of Licensing 84/03/12 PALLADING Commissioners 5pp 22708 O01 24X Fiche 50-000,84/03/12,8402070039.
- --8403060536 Forwards summary of 840210 meeting w/Transamerica Delaval.
 Inc Dumers Group in Bethesda.MD re problems w/emergency
 diesel generators
 CARUSO.R Licensing Branch 2 84/02/27 G'REILLY, J P NRC No
 Detailed Affiliation Given 6pp 22708 006 24X
 Fiche. 50-000.84/03/12.8402090039
- --8403060554 Transcript of 840210 meeting w/Transamerica Delaval, Inc Owners Group in Bethesda, MD re problems w/emergency diesel generators * NRC - No Detailed Affiliation Given 84/02/10 £47pp. 67201 008 24X Fiche 50-000,84/03/12,8402090039
- --8403070409 Summary of 840216 meeting w/Transamerica Delaval.Inc Owners Group in Wading River, NY re program plan to establish reliability of diesel generators Agenda, meeting transcript & attendance list encl.
 MILLER, M A Licensing Branch 4. 84/02/27 Licensing Branch 4
 8pp 22708 161 24% Fiche 50-000,84/03/12,8402090039

- --8403070423 Transcript of 840216 conference in Wading River.NY re Transamerica Delaval.Inc diesel generators Pp 1-82 * Commissioners 84/02/16 84pp 22708 169 24X Fiche 50-000.84/03/12.8402090039
- B403140030 Forwards "Design Review of Connecting Rod Bearing Shells for Transamerica Delaval Entergrise Engines" for Shoreham & Grand Gulf diesel generators MUSELER, W.J. Long Island Lighting Co. B4/03/12 DENTON, H.R. O
- B403150133 Forwards "Transamerica Delaval.Inc Diesel Generator Rocker Arm Capscrew Stress Analysis Rept " Capscrew design adequate for applicable engines & syc conditions MUSELER, W J TDI (Transamerica Delaval, Inc) Owners Group 84/03/13 DENTON, H R Diffice of Nuclear Reactor Regulation, Director 2pp 22637 270 24% Fiche 50-000,84/03/13,8403150133
- 8403200222 Responds to 840214 Requests for Info 1 & 2 re R-4 series engines List indicating engine number, model & svc number, customer name & address, rating, date shipped & date started enc!

 MATHEMS.C S Transamerica Delaval, Inc 84/03/16 EIBENHUT, D 0
 Division of Licensing 20pp 22691 179 24X Fiche 50-000, 84/03/16, page-200022
- 8403270132 Forwards "Emergency Diesel Generator Air Start Valve Capscrew Dimension & Stress Analysis." prepared by 8&M for Transamerica Delaval. Inc (TDI) Diesel Generator Owners Group MUSELER, M. J. TDI (Transamerica Delaval. Inc.) Owners Group 84/03/23 DENTGM: H. Office of Nuclear Reactor Regulation, Director 2pp 22774'001 24X Fiche 50-000.84/03/23,8403270132
- 8403270134 Requests meeting on 840418 to discuss short-term & long-term corrective actions & investigations re Transamerica
 Delaval dissel generators List of suggested maeting topics enc!
 KCGAUGHY, J P TDI (Transamerica Delaval, Inc.) Guners Group
 84/03/23 DENTON, H R Office of Nuclear Reactor Regulation,
 Director 4pp 22769 133 24X Fiche 50-000,84/03/23,8403270134
- T Hearing transcripts on non-antitrust matters
- B402090039 Board Notification 84-052 forwards meeting summaries containing transcripts of B40210 & 16 meetings between NRC & Transamerica Delaval.Inc (TDI) Dwners Group Distribution list encl
 EISENHUT, D G Division of Licensing 84/03/12 PALLADING Commissioners 5pp 22708 001 24X Fiche 50-000, B4/03/12,
- --8403060936 Forwards summary of 840210 meeting w/Transamerica Delaval, Inc Owners Group in Bethesda, MD re problems w/emergency diesel generators
 CARUSO, R Licensing Branch 2 84/02/27 O'REILLY, J P NRC No Detailed Affiliation Given 6pp 22708 006 24X
 Fiche 50-000, 84/03/12, 8402090037
- --B403060554 Transcript of 840210 meeting w/Transamerica Delaval.Inc Owners Group in Bethesda.MD re problems w/emergency diesel generators * NRC - No Detailed Affiliation Given B4/02/10 147pp 67201 008 24X Fiche 50-000.84/03/12.8402090039
- --8403070409 Summary of B40216 meeting w/Transamerica Delaval. Inc Owners Group in Wading River.NY re program plan to establish reliability of diesel generators Agenda.meeting transcript & attendance list encl MILLER.H A Licensing Branch 4 84/02/27 Licensing Branch 4 8pp 22708 161 24X Fiche 50-000.84/03/12.8402090039
- --B403070423 Transcript of 840216 conference in Wading River,NY re Transamerica Delaval,Inc diesel generators Pp 1-82 * Commissioners 84/02/16 84pp 22708 169 24X Fiche 50-000,84/03/12,8402090039
- DUCKET 50-460 WPPSS NUCLEAR PROJECT, UNIT 1
- A Application/construction stage documents & correspondence
- B403010050 Third partial response to FOIA request for six categories of documents me facility Forwards App A documents App A documents also placed in PDR App B documents will be placed in PDR upon request Review continuing FELTON, J M Division of Rubes and Records B4/01/17. ANDERSON, S 1 Garvey, Schubert, Adams & Barer 4pp 22446 293 24% Fiche 50-000,84/01/17,8403010050

- --8308100483 Discusses status of DL applications Review of encl WPP88 830712 ltr requested in order to determine present status of Unit 3 for billing purposes W/o encl MILLER,W O License Fee Management Branch 83/08/05 FONNER R L Regulations Division 2pp 22446 326 24X Fiche 50-000, 84/01/17.840310050
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of addl documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, S I Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000,84/02/13,8403080179
- --8001140316 Notifies that NRC has amended regulations re implementation of resident insp program Expresses gratitude for assistance rendered Forwards final rule W/o encl BTELLD,V Office of Inspection & Enforcement, Office of the Director 79/11/19 D'STRAND,N Washington Public Power Supply System 1p 22583 234, 24X Fiche 50-000,84/02/13,8403080179
- --8009070737 Forwards airworthiness alert re currosive & abrasive characteristics of volcanic ash which has fallen in Pacific Northwest Questions re ash amount, chemistry & size distribution will be forwarded to licensees W/o encl JACKBON, R E Geosciences Branch 80/06/12 VOLLMER, R. H. Division of Engineering 2pp 22583 258 24X Fiche 50-000,84/02/13,8403080177
- --B010070260 Discusses review of applicant 800B14 request for approval of proposal to substitute in-plant tosts w/scale model recirculation sump tests Response to requests deferred pending NRC review of program SPEIS.T Reactor Systems Branch B0/09/26 YOUNDELOOD.B.J Licensing Branch 1 ip 225B3 266 24X Fiche 50-000,84/02/13,8403080179
- --8104220327 Concludes that Table 3 2-2 of PSAR, re safety-related structures, sys & components, is incomplete from Geotechnical Engineering Branch viewpoint LEAR, G E Hydrologic & Geotechnical Engineering Branch. 81/04/08 HAASS.W P Quality Assurance Branch 2pp 22583 278 24X Fichs 50-000, 84/02/13, 8403080179
- --8104300020 Responds to 810414 momo re util request for clarification in use of ASME code cases Util use of code cases w/o prior NRC approval is inadvisable due to potential hardship for user BUSNAK.R J Mechanical Engineering Branch 81/04/21, YOUNGBLOOD.B J Licensing Branch 1 ip 22583 280 24X Fiche 50-000,84/02/13,8403080179
- --Bi05010554 Advises that Mechanical Engineering Branch completed review of util request for authorization to use ASME Code Cases N-219 & N-287 for application in design of concrete containments Code cases acceptable KNIGHT. J P Assistant Director for Comp & Structures Engineering (Fre 80201) 81/04/29 TEDESCU.R L Assistant Director for Licensing Ip 22583 281, 24X Fiche, 50-000,84/02/13,8403080179
- ---B105140106 Advises that info provided on 810213 & 0403 re air intake arrangements for diesel generators reviewed Diesel generator combustion air supply arrangement meets acceptance criteria in Section II of SRP a 5 B Bys acceptable as designed UNOARO, A R Power Systems Branch 81/05/01 YOUNGBLOOD, B J Licensing Branch 1 ip 22583 282 24X Fiche 50-000, 84/02/13, 8403080179
- --8105180436 Forwards ltr from util requesting concurrence by NRC to omit Subsections 2 5 1-2 5 3 of FBAR Review & comments requested by 810622 ADENSAM, E G Assistant Director for Licensing 81/05/12, JACKSON, R E Geosciences Branch ip 22583 283 24X Fiche 50-000,84/02/13,8403080179
- --Bi05210109 Concurs w/licensee proposal to ref Sections 2 5 1-2 5 1-2 5 3 of MPPS-2 FSAR in WPPS-1/4 FSAR since both projects located in close proximity Mods listed JACKBON, R E Geosciences Branch 81/05/15 ADENSAM, E Q. Licensing Branch 4 2pp 22883 286 24X Fiche, 50-000, 84/02/13, 8403080179
- --8107280171 Notification of 810729 meeting w/util & B&W in Bethesda, MD to discuss method util intends to use to fulfill requirments of NUREO-0737 Item II F 2 (inadequate core cooling instrumentation)
 HERNAN, R W Licensing Branch 4 81/07/21 ADENBAM, E 9
 Licensing Branch 4 2pp 22583 305 24X Fiche: 50-000, 84/02/13, 8403080179

- --8108110038 Notification of 810820 meeting w/util in Bethesda, MD to discuss proposed independent design review programs HERNAN, R W Licensing Branch 4 91/07/30 ADENBAM, E Q Licensing Branch 4 3pp. 22583 302 24X Fiche 50-000, 84/02/13, 8403080179
- --8110080612 Discusses proposal to use IDRs in licensing process IDRs may be useful in certain areas, but clarification of role needed, TEDEBCO.R L Assistant Director for Licensing 81/09/23 EIBENHUT.D 0 Division of Licensing 1p 22583 307 24X Fiche 50-000,84/02/13,8403080179
- --B1110B0697 Notifies of util intention of sending technical team to present FSAR to review staff during wk of 811130 Reviewers should complete attached form & confirm attendance HERNAN,R W Licensing Branch 4 81/10/23 Licensing Branch 4 4pp 22583 311 24X Fiche 50-000.84/02/13.8403080179
- --Biiii30007 Submits names of D Gupa & G Stalley as technical reviewers for facility FBAR per 811023 memo LEAR, G Hydrologic & Geotechnical Engineering Branch Bi/10/30 ADENBAM, E. Licensing Branch 4 ip 22583 315 24X Fichs. 50-000, 84/02/13, 8403080179
- --Biii2002i9 Informs of receipt of telcon from Yakamar Indian Nation requesting that tribe be given full rights in facilities proceedings TEDESCO, R L Assistant Director for Licensing, 81/10/21 KETCHEN, E Hearings Division ip 22583 310, 24X Fiche 50-000,84/02/13,8403080179
- --8112300305 Notification of B11211 meeting w/util in Bethesda, MD to discuss FBAR w/technical review staff at time OL application is tendered HERNAN, R W Licansing Branch 4 B1/11/23 ADENSAM, E O Licensing Branch 4 3pp 22583 318 24X Ficha 50-000, 84/02/13, 8403080179
- --B304060577 Requests search for documents re govt litigation w/util on five specific issues SLA00IE.E L Office of the General Counsel 83/03/23 DIRCKB.W.J Office of the Executive Director for Operations. ip 22583.361 24X Fiche 50-000.84/02/13.8403080179
- --B304070113 Recommends that radiation exposure records be retained for 1 yr prior to disposal Ref Murphy to Varga 801222 GONGEL, F. J. Radiological Assessment Branch 83/04/01 BCHMENOER, A. Licensing Branch 2 ip 22583 327 24X Fichs: 50-000, 84/02/13, 8403080179
- 8403050288 Fifth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App A & B documents also available in PDR Documents listed on App C & D located in Central Files & not available publicly FELTON, J.M. Division of Rules and Records 84/02/17 ANDERSON, 8 I Garvey, Schubert, Adams & Barer 9pp 22501.289 24X Fiche: 50-397.84/02/17,8403050288
- --7908010232 Responds to 790405 Region 5 comments re Revision 4 to NPP88-GA-OO4, "Operational GA Program Description " Expresses intent to request util to delete Section 3 3 & entirely HAA88, W.P. Quality Assurance Branch 79/05/01, BRYAN, S E Division of Reactor Operations Inspections 1p 22501, 305 24X Fichs 50-397, 84/02/17, 8403050288
- --8110190031 Responds to 810923 FOIA 81-378 request for GA documents for WPFSS, All documents re evaluation of licenses GA programs are in PDR.
 HAASS.W.P. Quality Assurance Branch. 81/10/05 WILSON, V.H.
 Management Analysis Branch. 2pp 22501;310 24X
 Fiche: 50-397.84/02/17.8403050288
- --8110210316 Informs of receipt of Bouchey/Adensam 810722 Itr containing util current GA program description for design & const of facilities GA program description acceptable HAABB, W.P. Quality Assurance Branch 81/10/14 TEDEBCO, R.L. Assistant Director for Licensing ip 22501 312 24X Fichs: 50-440, 84/02/17, 8403050288
- --8201300234 Forwards data for fee assessment re QA Branch review of WPPSS-QA-004, "Operational QA Program Description "HAASS,W P. Quality Assurance Branch. 82/01/14 BERKOW.H N. Management Analysis Branch. 2pp 22501 314 24X Fiche 50-397,64/02/17.8403050268

- 8403050219 Forwards listing of board notifications issued since 920716, per 840127 inquiry re failure to provide ASLB & parties w/notifications DENTON, H R Office of Nuclear Reactor Regulation, Director 84/02/28 B&LLN Coalition for Safe Power 25pp 22700 222 24 Fiche 50-460,84/02/28,8403050219
- B403070014 Explains why two recent board notifications re environ qualification of equipment not received tist of all board notifications issued since 820716 docketing of Unit 1 encl DENTON, H R Office of Nuclear Reactor Regulation, Director B4/02/28 BELL, N Coalition for Safe Power 25pp 22563 166 24) Fiche 50-460,84/02/28,8403070014
- C Utility Environmental Report (ER), amends & correspondence
- B4030B0179 Fourth partial response to FDIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FDIA Exemption 5) Review of addl documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, S 1, 0arvey, Schubert, Adams & Barer 7pp 22593.226 24X Fiche 50-000,84/02/13,8403080179
- --8202260171 Requests assistance in performing acceptance review of environ rept for OL application Unly portions applicable to Unit 1 need be considered since Unit 4 cancelled on BRO122 ADEMBAM, E G Licensing Branch 4 82/02/10 JACKSON.R E Geosciences Branch 1p 22583 324 24X Fiche 50-000,84/02/13.8403080179
- ---B203100570 Recommends environ rept be accepted Add1 questions reexternal appearance, plant layout & socioeconomics of single unit operation will be submitted REGAN, W H Siting Analysis Branch S2/02/25 ADENSAM, E Q Licensing Branch 4 ip 22583 328 24X Fiche 50-000, 84/02/13, 8403080179
- --8203150028 Forwards add1 info requirements for review of ER for GL application per 820210 request
 BALLARD.R L Environmental Engineering Branch 82/03/02
 ADENBAM.E Q Licensing Branch 4 3pp 22583 327 24X
 Ficher 50-000.84/02/13.8403080179
- --8203180004 Advises that environ rept is acceptable re radiological impacts HDUSTON,R W Assistant Director for Radiation Protection 82/03/02 TEDESCO,R L Assistant Director for Licensing 1p 22883 332 24X Fiche 50-000,84/02/13.84030801/9
- ---8204070097 Informs that sufficient info provided to begin meteorology review Inappropriate models & diffusion parameters used in Section 6 1 3 2 & accident evaluations HULMAN, L O Accident Evaluation Branch 82/03/16 ADENBAM, E Licensing Branch 4 2pp 22583 336 24X Fiche 50-000, 84/02/13, 840380177
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of addl documents subj to request continuing FELTON.J M Division of Rules and Records 84/02/13 ANDERSON.9 I Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000,84/02/13,8403080179
- --B003230477 Forwards hydrologic engineering questions re proposed waste treatment sys Response will supply necessary info re design basis for seepage & flooding Also forwards generic questions re floodplains Info will assist NRC environ review SELLS.D E Environmental Projects Branch 2 B0/03/07 RENBERGER.D L Washington Public Fower Supply System Spp 22583 253 24X Fiche 50-000.84/02/13.8403080179
- ---8003270142 Discusses suspension of facility preoperational aquatic monitoring program Buspension approved Operational manitoring program results should not be affected by suspension SAHKORTHAR B. Environmental Specialists Branch 80/02/29 SELLS, D E Environmental Projects Branch 2 2pp 22563 239 24X Fiche 50-000,84/02/13,8403080179
- E NRC Bafety Evaluation Report (SER), suppls & correspondence
- 8403080179 Fourth partial response to FDIA request for six categories of documents are facilities. Forwards App A documents App B document entirely withheld (ref FDIA Exemption 5) Review of addl documents subj to request continuing FELTON.J.M Division of Rules and Records 84/02/13 ANDERSON.S I Garvey, Schubert, Adams & Barer 7pp 22583 226 24% Fichs 50-000.84/02/13.8403080179

- --8103040052 Forwards short & long-term DL & CP review schedules, in response to 801216 meeting w/USOS List of DL plant reviews for which NRC tentatively plans to seek USOS assistance is provided JACKBON, R E Geosciences Branch NRC-03-80-113 81/01/21 DEVINE, J F Interior, Dept of Geological Survey 5pp 22583 272 24X Fiche 50-000,84/02/13,8403080179
- --Biiii20935 Forwards form which identifies Power Bys Branch electrical & mechanical reviewers for project in accordance w/Bii023 memo Requests established review schedule dates when available
 UNGARD.A Power Bystems Branch Bi/11/02 HERNAN.R W Licensing Branch 4 2pp 22583 316 24X Fiche 30-000:84/02/13:8403080179
- F Security, medical, emergency & fire protection plans
- B403080177 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of addl documents subj to request continuing FELTON.J M Division of Rules and Records 84/02/13 ANDERSON.8 I Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 30-000,84/02/13.8403080177
- --8201170277 Forwards Central Files version of "Description of Early Warning Sys for WPPSS Nuclear Plants 1,2 & 4," in response to NRC 810720 Ltr re prompt notification in event of emergency Sys will be in place prior to OL issuance BOUCHEY, 0 D. Washington Public Power Supply System 92/01/11 TEDESCO, R L. Assistant Director for Licensing 1p 22583 321 24X Fiche 50-000,84/02/13.8403080179
- --8202180456 Requests that Fire Protection Section perform acceptance level review of facilities' revised fire protection program prior to docketing of GL application Util aware that App R to 10CFR50 will apply ADENBAM.E G Licensing Branch 4 82/01/29 BENAROYA.V Chemical Engineering Branch 1p 22583 322 24X Fiche. 50-000.84/02/13, 8403080179
- --8203020139 Advises that listed info needed to perform acceptance review of fire protection program for conformance w/NUREO-0800, Section 9 5-1
 BENARDYA-V Chemical Engineering Branch 82/02/09 ADENSAM, E G Licensing Branch 4 1p 22593 323 24X Fiche 50-000,84/02/13,8403080179
- --8205070088 Forwards list of sys to be added to Q-list Bys provides ongoing knowledge of changes in radiation environ & ability to deal effectively w/wnosually high radiation & radioactivity levels
 CONGEL.F J Radiological Assessment Branch 82/03/23. HAASS.W P Quality Assurance Branch 2pp 22583 338 24X
 Fiche 50-000.84/02/13.8403080179
- --820B12024O Forwards Central Files version of revised gage to Revision 2 of emergency plan adding local fire depts within 20 miles of facility to backup fire protection svcs
 80UCHEY,0 D Hashington Public Power Supply System 82/08/05
 8CHMENCER.A Licensing Branch 2 2pp 22583 348 24X
 Fiche 50-000,84/02/13,8403080179
- --8208120248 Central Files version of revised page to Revision 2 of emergency glan re provision of backup fire protection svcs * Mashington Public Power Supply System 82/08/05 1p 22883 350 24X Fiche 50-000.84/02/13.8403080179
- B403050288 Fifth partial response to FDIA request for six categories of documents re facilities Forwards App A documents App A & B documents also available in PDR Documents listed on App C & D located in Central Files & not available publicly FELTON, J. M Division of Rules and Records B4/02/17 ANDERSON, S. I Carvey, Schubert, Adams & Barer 9pp 22501 289 24X Fiche: 50-508,84/02/17,8403050288
 - on program description & related
 h 79/05/10 PARR,O D. Ligh.
 1 309 24X

x categories A laced ANDERSON, S. I

- --8304050532 Requests search for relevant documents re govt litigation w/util Response due by 83040B
 GRIMBLEY, D H NRC No Detailed Affiliation Given 83/03/29
 FITTI, C Atomic Safety and Licensing Board Panel 1p. 22446-314
 24X Fiche 50-000.84/01/17.8403010050
- 8403220049 Appeal of ASLB 840202 order granting applicant & staff motions for summary disposition on Coalition for Safe Power Contention 2 Certificate of 8vc encl BELLIN Coalition for Safe Power DBS 025 84/03/19 Atomic Safety and Licensing Appeal Panel. 15pp 22712.202 24X Fiche 50-460.84/03/19.8403220049
- J Insurance & indemnity information
- 8403060377 Forwards Endorsement B to MAELU Policy MF-110 & Endorsements 13 & 14 to NELIA Policy NF-270 ABHBURN. D J Marsh & McLennan, Inc. 84/02/28 SALTIMAN, J. Assistant Director for State & Licensee Relations. 4pp. 22511-323 24X Fichs 50-397.84/02/28.8403060377
- O Inspection reports: IE Bullstins & correspondence
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents. App B document entirely withheld (ref FOIA Exemption 5) Review of addi documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, 8, I Garvey, Schubert, Adams & Barer 7pp 22583:226 24X Fiche 50-000.84/02/13,8403080179
- ---8207280165 Forwards Cycle 3 systematic appraisal of licensee performance input for BiO701 through 820730 in response to Region 5 820625 request Strong mgt svident. Resolution of technical issues, responsiveness & staffing satisfactory HERNAN: R W Licensing Branch 4 82/09/15 EISENHUT.D.Q. Division of Licensing 6pp 22583.351 24X Fiche 50-000, 84/02/19, 8403080179
- 8 Reportable occurrences, LERs & related correspondence
- 8403010451 Informs Commission of problems w/emergency diesel generators mfg by Transamerica Delaval, Inc DIRCKS, W J Office of the Executive Director for Operations. SECY-83-034 84/01/25 App 22438 347 24X Fiche 50-000.84/01/25, 8403010451
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents. App B document entirely withheld (ref FOIA Exemption 3) Review of add1 documents subj to request continuing.

 FELTON, J M Division of Rules and Records 84/02/13 ANDERBON, 8 I Garvey, Schubert, Adams & Barer 7pp. 22383, 226, 24X Fiche: 50-000, 84/02/13, 8403080179
- --B203100419 Discusses Part 21 rept re UE&C design of structural steel at facility Generic implications appear to be nonexistent since no similar design concept used at other facilities. Two oversize drawings encl Aperture cards in Central Files BHEWHAKER.R E Division of Engineering & Quality Assurance (Pre B30103) B2/02/24 DROMERICK.A W Division of Engineering & Quality Assurance (Pre B30103) 2pp 22583 325. 24X Fiche 50-000,84/02/13.8403080179
- 8403210032 Part 21 rept re failure of auxiliary feadwater pump drive turbines, 0impel NPS-4 T&T valve, to close Encl 1tr d&d 840203 sent to listed utils GE notified of affected units in BWR plants
 THEROUX, R.R. Terry Corp. 84/02/22. WOODRUFF, R.W. Director's Dffice, Office of Inspection and Enforcement 6pp. 22706.327. 24X Fichs 50-000.84/02/22.8403210032
- 8403010207 Forwards "Investigation of Types AF & AE Piston Skirts," per Transamerica Delaval, Inc Owners Group program commitments. Rept evaluates cracks in AF piston skirts in Shoreham & Orand Guif Nuclear Power Stations
 MUSELER, W J TDI (Transamerica Delaval, Inc.) Owners Group.
 84/02/27 DENTON.H, R Office of Nuclear Reactor Regulation,
 Director 3pp 22434 090 24X Fichs 50-000,84/02/27,8403010207.
- 8403010218 Forwards task descriptions for 16 known problems re Transamerica Delaval, Inc emergency diesel generators, HUSELER,W J TDI (Transamerica Delaval, Inc.) Owners Group, 84/02/28 DENTON, H R. Office of Nuclear Reactor Regulation, Director 42pp 22435 177. 24X Fiche.50-000.84/02/28.8403010218.

- 8403140048 Forwards "Grand Gulf Component Tracking Sys," "Shoreham Component Tracking Sys" & "Transamerica Delaval, Inc Diessi Generators Owners Group Program Plan: " to resolve concerns w/wemergency diessi generators MUSELER.W J Long Island Lighting Co. 84/03/02 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 22626 062 24X Fiche 30-000,84/03/02.8403140048
- --8403140092 "Transamerica Delaval, Inc Diesel Generators Dumers Group Program Plan " * TDI (Transamerica Delaval, Inc.) Owners Group 84/03/02 261pp 22628 223 24X Fichs 50-000,84/03/02,8403140048
- 8402070039 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Deleval, Inc (TDI) Duners Group Distribution list encl EIBENHUT,D 0 Division of Licensing 84/03/12 PALLADING Commissioners 5pp 22708 OO1 24X Fiche 50-000,84/03/12.8402090039
- --8403060536 Forwards summary of 840210 meeting w/Transamerica Delaval, Inc Owners Group in Bethesda, MD re problems w/mmergency diesel generators CARUBO, R Licensing Branch & 84/02/27 O'REILLY, J. P NRC No Detailed Affiliation Given 6p, 22708 006 24X Fiche 50-000, 84/03/12, 8402090039
- --8403060554 Transcript of 840210 meeting u/Transamerica Delaval. Inc Owners Group in Bethesda. MD re problems u/emergency diesel generators * NRC - No Datailed Affiliation Given 84/02/10. 147pp 67201 OOB 24X Fiche 50-000.84/03/12.8402090039.
- --8403070409 Summary of 840216 meeting w/Transamerica Delaval.Inc Owners Oroup in Wading River.NY re program plan to establish reliability of diesel generators Agenda.meeting transcript & attendance list encl MILLER,M.A Licensing Branch 4 84/02/27 Licensing Branch 4 8pp 22708 161. 24X Fiche.50-000.84/03/12.8402070039
- ---8403070423 Transcript of 840216 conference in Wading River, NY re Transamerica Delaval. Inc diesel generators Pp 1-82 # Commissioners 84/02/16, 84pp 22708 169 24X Fiche: 50-000, 84/03/12, 8402070039
- 8403140050 Forwards "Design Review of Connecting Rod Bearing Shells for Transamerica Delaval Enterprise Engines" for Shoreham & Grand Gulf diesel generators MUSELER, W J Long Island Lighting Co 84/03/12 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22632 074 24X Fiche 50-000,84/03/12,8403140050
- 8403130133 Forwards "Transamerica Delaval. Inc Diesel Generator Rocker Arm Capscrew Strees Analysis Rept " Capscrew design adequate for applicable engines & svc conditions MUSELER, W J TDI (Transamerica Delaval, Inc.) Owners Group 84/03/13 DENTON. H R Office of Nuclear Reactor Regulation, Director 2pp 22639-270 24X Fichs 50-000,84/03/13,8403150133
- 8403200222 Responds to 840214 Requests for Info 1 & 2 re R-4 series engines List indicating engine number model & svc number. customer name & address rating date shipped & date started enc!

 MATHEWS, C S Transamerica Delaval, Inc. 84/03/16 EISENHUT, D. 0 Division of Licensing 20pp 22691:179 24X Fiche 50-000,84/03/16,8403200222.
- 8403270219 Part 21 rept re broken contact carrier in control device of 7 5 kV-15 kV.500-750 MVA.5 kV 350-3.000 & all HKV circuit breakers. Initially reported on 830223 Addenda to installation & maint procedures sent to affected units DUVALL.D D Brown Boveri Corp (subs of Brown Boveri & Co., Ltd) 84/03/19. Record Services Branch (Document Control Desk). Spp 22772:114 24X Fiche 50-000.84/03/19.8403270219
- 8403270132 Forwards "Emergency Diexel Generator Air Start Valve Capacrew Dimension & Stress Analysis," prepared by 8kW for Transemerica Deleval, Inc (TDI) Diesel Generator Guners Group MUGELER, W. J. TDI (Transemerica Delaval, Inc.) Owners Group 84/03/23 DENTON.H R. Office of Nuclear Reactor Regulation, Director. 2pp 22774-001. 24X Fiche: 50-000,84/03/23,8403270132
- 8403270134 Requests meeting on 840418 to discuss short-term & long-term corrective actions & investigations re Transamerica Delaval diesel generators List of suggested meeting topics enc!

 MCGAUGHY, J.P. TDI (Transamerica Delaval, Inc.) Owners Group 84/03/23. DENTON, H.R. Office of Nuclear Reactor Regulation, Director 4pp 22769:133 24X Fishs 50-000.84/03/23.8403270134

T Hearing transcripts on non-antitrust matters

- 8402090039 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delaval. Inc (TDI) Dwners Group Distribution list encl EISENHUT.D Q Division of Licensing 84/03/12 PALLADIND Commissioners 5pp 22708 001 24% Fiche 50-000,84/03/12.8402090039
- --8403060536 Forwards summary of 840210 meeting w/Transamerica Delaval.
 Inc Duners Group in Bethesda.MD re problems w/emergency
 diesel generators
 CARUSO.R Licensing Branch 2 84/02/27 D'REILLY.J P NRC No
 Detailed Affiliation Given 6pp 22708 006 24X
 Fiche 50-000,84/03/12,8402090037
- --B403060554 Transcript of 840210 meeting w/Transamerica Delaval. Inc Owners Group in Bethesda. MD re problems w/emergency diesel generators * NRC - No Datailed Affiliation Given 84/02/10 147pp 67201 00B 24X Fiche 50-000,84/03/12,8402090037
- --8403070407 Summary of 840216 meeting w/Transamerica Delaval.Inc Owners Group in Wading River.NY re program plan to establish reliability of diesel generators Agenda.meeting transcript & attendance list encl
 MILLER,M A Licensing Branch 4 84/02/27 Licensing Branch 4
 8pp 22708 161 24X Fiche 50-000.84/03/12.8402090039
- --8403070423 Transcript of 840216 conference in Hading River, NY re Transamerica Delaval, Inc diesel generators Pp 1-82 * Commissioners 84/02/16 84pp 22708 169 24X Fiche 50-000, 84/03/12,8402070039

U Congressional/Executive Correspondence

- 84030B0179 Fourth partial response to FDIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FDIA Exemption 5) Review of add1 documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, 5 1 Garvey, Schubert, Adems & Blarer 7pp 22583 226 24X Fiche 50-000, 84/02/13, 8403080179
- --B009110203 Responds to B00702 itr re E Borhek concern about ultimate responsibility for civil penalities proposed against util Civil penalities are imposed as enforcement action State agencies should be contacted re responsibility for payment DIRGKS.H J Office of the Executive Director for Operations B0/08/26 JACKSUN.H M Senate 4pp 22583 260 24% Fiche 50-000,84/02/13,8403080177
- --B012160551 Forwards B00625 ltr from constituent E Borhek for response Requests that duplicate rept be forwarded to 802 United Btates Courthouse, Beattle, WA 98104 JACKBON,H M Benate, Energy & Natural Resources 80/07/21 KAMMERER, C C Office of Congressional Affairs 2pp 22583-264 24X Fiche 50-000,84/02/13.8403080179

DUCKET 50-461 CLINTON POWER STATION, UNIT 1

- A Application/construction stage documents & correspondence
- 8403130193 Responds to Generic Ltr 83-28 re generic implication of Salem ATWS events Util using methodologies developed by Industry groups Behedule for info submittal ulil be provided within 45 days after receipt of owners group rept. HERBORN.D I Illinois Power Co 84/03/02 EISENHUT,D 9 Division of Licensing 2pp 22617 298 24X Fiche 50-461.84/03/02, 8403130193
- 8403290346 Notification of 840405 meeting w/util in Dethesda. MD to discuss safety parameter display sys HARRISON.6 Licensing Branch 2 84/03/08 SCHWENCER, A Licensing Branch 2 3pp 22822 253 24X Fiche 50-461, 84/03/08, 8403290346
- 8403190398 Forwards tabulated results ra review of operating shift experience for facility HALL, DP Illinois Power Co 84/03/09. DENTON, HR. Office of Nuclear Reactor Regulation, Director App 22675 058 24X Fiche 50-461.84/03/09.8403190398.
- 8403150089 Forwards responses to Mechanical Engineering Branch Questions 210 05 % 210.06 re HVAC duct work Stress limits for duct work & duct supports will be included in FSAR Buckled portions of ducts will be replaced HERBORN,D I Illinois Power Co 84/03/12 8CHWENCER,A. Licensing Branch 2 5pp 22642 358 24X Fiche 50-461.84/03/12,8403150089

- B402090041 Board Notification 84-050 provides Commission policy statement & proposed rulemaking on environ qualifications EISENHUT, D @ Division of Licensing B4/03/14 Atomic Safety and Licensing Board Panel 10pp 24X Fiche 50-000 84/03/14 8402090041
- B403200170 Act receipt of B40307 request for concurrence in modifying program for pulling Class IE cable Installation of cable will not preclude insp of cable tray hangers Concurrence granted KEPPLER, J @ Region 3, Office of Director B4/03/16 GERSTNER, W C Illinois Power Co 1p 22686 341 24X Fiche 50-461, B4/03/16, B403200190
- --8403200193 Submits proposed mods to prerequisites for pulling Class IE cable previously modified in 840103 ltr Prior to Class IE cable pull, cable tray in pull path will be field inspected & accepted by Baldwin Assocs Quality & Technical Svcs HALL, D.P. Illinois Power Co. 84/03/07 KEPPLER, J.Q. Region 3, Office of Director 5pp. 22686 342 24X Ficbs 50-461, 84/03/16, 84003/00190
- F Security, medical, emergency & fire protection plans
- 8402090006 Board Notification 84-034 forwards R Vollmer 840206 memo to D Eisenhut re fire research results concerning fires in electrical cabinets in control room EISENHUT, D 0 Division of Licensing 84/02/23 PALLADINO Commissioners 1p 22576 203 24X Fiche 50-000,84/02/23, 8402090006
- --8403080316 Recommends that info re fire research results concerning fires in electrical cabinets in control room be submitted for board notification, ser NRR Ofc Ltr 19, dtd 821001 Further svaluation of test data required VOLLMER.R H Division of Engineering 84/02/06 EISENHUT, D Q Division of Licensing 10pp 22976 204 24X Fichs 50-000,84/02/23,8402090006
- B403120077 Notifies of 840323 workshop on fire protection safe shutdown revirements of 10CFR30.App R in Rosemont IL to discuss IE Info Notice 84-09 & provide addl shutdown analyses &/or mod guidance Agenda encl SPESSARD, R L Division of Emergency Preparedness & Operational Support B4/03/06 GERSTMER.W C Illinois Power Co Spp 22586 302 24X Fiche 30-461.84/03/06.8403120077
- B4033002B9 Notification of B40403 meeting w/util in Bethesda.MD to discuss emergency planning HARRISON, G Licensing Branch 2 B4/03/08 SCHWENCER, A Licensing Branch 2 3pp 22B44 326 24X Fiche 50-461,84/03/08,84033002B9
- 8403270177 Forwards IE Mgt Meeting Rept 30-461/84-06 on 840228-29 PAPERIELLO, C J Region 3, Office of Director 84/03/09 GERSTNER, C J Illinais Power Co 2pp 22771 126 24X Fiche 50-461,84/03/09.8402270177
- --8403270180 IE Mgt Meeting Rept 50-461/84-06 on 840228-29 Major areas discussed progress of emergency preparedness program & hearing board contentions re emergency preparedness SNELLW C . PHILLIPS.M P Region 3, Office of Director 84/03/08 3pp 22771 128 24X Fishe 50-461.84/03/09.8403270177

G Adjudicatory correspondence

- B403070120 Notice of filing of joint stipulation in OL hearing FOX.C D Illinois Power Co FOX.C D Schiff, Hardin & Haite B4/03/02 CLARK.H K. FERGUSON.G A. PARIS.O H. Atomic Safety and Licensing Board Panel 2pp 22547 262 24X fiche 50-461.84/03/02.8403070120
- --8403070123 Joint stipulation that Paragraphs f,g,h,i & J of Contention III hereby withdrawn in entirety Certificate of Svc encl.

 ODDDARD.R NRC No Detailed Affiliation Given FOY.J M Prairie Alliance AREL., SA Illinois Power Co. 84/03/01. 3pp
 22547 264 24X Fiche 50-461.84/03/02.8403070120
- 8403140037 Forwards proposed mod of Contention 1 re emergency planning discussed w/applicant, Prairie Alliance, FEMA & NRC at 840228-29 meetings in Champaign, IL Schedule to further settle remaining smergency planning issues listed GCDDARD, R J Hearing Branch 3 84/03/05 CLARK, H K , PARIS, O H , FERGUSBON, O A Atomic 84.6 ty and Licensing Board Panel 6pp 22633 085 24X Fiche 50-461,84/03/05,8403140057.
- --8403140060 Requests notice of dates of licensing hearings in Clinton.
 IL in order to make necessary arrangements
 STITES.8 J Clinton, IL 84/02/24 GODDARD.R J Hearing Branch
 3 ip 22633 092 24X Fiche 50-461.84/03/05.8403140057

- B403140135 Forwards util submittal providing functional description of safety parameter display sys W/o encl. GUDDARD, R J Hearing Branch 3 84/03/05 WILLMAN,P L Illinois. State of 1p 22620 297 24x Fiche 50-461.84/03/05,8403140135
- 8403140106 Forwards emergency planning contentions as modified at recent meeting w/intervenor & transmittal ltr to ASLB GODDARD.R U Hearing Branch 3 84/03/06 PERRY.S Federal Emergency Management Agency 9pp 22620 275, 24X Fiche 50-461.84/03/06.8403140106
- B403140142 Forwards modified emergency planning contention as amended on B40227 by party agreement GUDDARD.R J Hearing Branch 3 84/03/07 FOY.J Prairie Alliance 5pp 22624 035 24% Fiche 50-461,84/03/07,8403140142.

1 Financial information

- 8403290093 Forwards util Annual Financial Rept 1983, Soyland Power Cooperative, Inc Annual Financial Rept 1982 & Western Illinois Power Cooperative, Inc Annual Financial Rept 1983, HERBORN, DI Illinois Power Co. 84/03/23 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 1p 22806 106 24X Ficha 50-461,84/03/23,8403290093
- --8403270098 Annual Financial Rept 1983 KELLEY,W J Illinois Power Co 83/12/31 38pp 22806·127 24) Fiche 30-461.84/03/23,8403270093
- --8403290102 Annual Financial Rept 1982 FERGUSON, C E , WILLIAMS, E H Soyland Power Cooperative, Inc 82/12/31 22pp 22806 107 24X Fiche 50-461,84/03/23,8403290093
- ---8403290107 Annual Financial Rept 1983 GANT.R E Western Illinois Power Cooperative, Inc. 83/12/31 16pp 22806 167 24X Fiche 50-461,84/03/23,8403290093
- G Inspection reports, IE Bulletins & correspondence
- 8403130416 Forwards IE Insp Rept 50-461/83-17 on B31101-B40111 & notice of violation NNOP,R. C. Region 3. Office of Director. 84/02/21 GERBINER,W C Illinois Power Co 2pp 22613.091. 24x Fiche 50-461,84/02/21. 8403130416
- --8403130421 Notice of violation from insp on 831101-840111 * Region 3, Office of Director 84/02/21. 2pp 22613,093. 24X Fiche 50-461,84/02/21,8403130416
- --B403130430 IE Insp Rept 50-461/83-19 on B31101-B40111 Violations noted deviation repts not dispositioned par Baldwin Assoc Rev 2 to Procedure BAP 1 0 1 & acceptance criteria not established for dispositioning nonconformance repts JABLONBKI, F J., HAYES, D W Region 3, Office of Director 84/02/21 32pp 22613 095 24X Ficher 50-461,84/02/21,8403130416
- 8403080176 Forwards IE Insp Rept 50-461/84-02 on 840118-20 & 24-27. No noncompliance identified STREETER. J F Region 3, Office of Director 84/02/23 GERSTNER. W C Illinois Power Co. 2pp 22559 314 24X Fiche 50-461.84/02/23.8403080176.
- --8403080188 IE Insp Rept 50-461/84-02 on 840118-20 & 24-27. No noncompliance or deviations identified Major areas inspected review of previous noncompliance, unresolved & open items in IE Insp Repts 50-461/82-18 & 50-461/83-15. GA & GC. CHOULES.N C . SCHULZ.R D . HUNTER.D R. Region 3, Office of Director 84/02/17 lipp 22559 316 24X Fiche 50-461,84/02/23, 8403080176
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN, E. Division of Emergency Preparadness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc 115pp 22909 239 24% Fiche 50-000,84/02/28,8401190078.
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl. GRACE, J N Division of QA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 130pp. 22552 327 24X Fiche, 50-000, 84/03/02, 8402090007.
- 8402070008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Velves to Operate," Svc list encl.
 JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 122pp 22553 098, 24X Fiche 50-000,84/03/02,8402090008.

- 8402070009 IE Info Notice 84-15, "Reporting of Radiological Releases"
 - Bvc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Past 830103). 84/03/02 Consolidated Edison Co of New
 York, Inc 119p 22553 217 24X Fichs 50-000,84/03/02,8402070009
- 8402090011 IE Info Notice 84-17. "Problems W.L. (quid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JURDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Constituted Edison Co. of New York Inc. 117pp 22553-336 24X Fiche 50-000.84/03/05,8402090011
- 8402090024 IE Info Notice 84-09, Rev 1. "Lessons Learned From Insps of Fire Protection Sefe Shutdown Sys " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07. Consolidated Edison Co of New York, Inc 118pp 22635 049 24% Fiche 50-000,84/03/07,8402090024
- B402090028 IE Info Natice 84-18, "Stress Corrosion Cracking in PHR Bys." Syc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22584 186 24X Fiche 50-000, 84/03/07, 8402090028
- B403270177 Forwards IE Mgt Meeting Rept 50-461/84-06 on 840228-29 PAPERIELLG.C.J. Region 3. Office of Director 84/03/09. GERSTNER.C.J. Illinois Power Co 2pp 22771.126 24X Fiche: 50-461.64/03/09.8403270177.
- --B403270180 IE Mgt Heeting Rept 50-461/84-06 on 840228-29 Major areas discussed progress of emergency preparedness program & hearing board contentions re emergency preparedness BNELL, W C. PHILLIPS, M P. Region 3, Office of Director. 84/03/08. 3pp 22771-128 24X Fiche 50-461,84/03/09,8403270177.
- 8402090031 IE Bullatin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Bys " Svc list encl DEYOUNG.R C. Director's Office, Office of Inspection and Enforcement. 84/03/12 Consolidated Edison Co of New York, Inc 134pp. 22823.094 24X Fiche 50-000:84/03/12,8402090031
- 8403190170 Ack receipt of 840305 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-461/83-23 BPESSARD, R L Division of Emergency Preparedness & Operational Support. 84/03/14 GRSTNER, W C Illinois Power Co 1p 22671.152 24X Fiche.50-461.84/03/14.8403190170.
- --8403190175 Responds to NRC 840117 ltr re violations noted in IE Insp. Rept 50-461/83-23 Corrective actions Procedure BAP 3.3.2 revised to incorporate directive requirements for seismic Category I cable tray cable installation HALL, D.P. Illinois Power Co. 84/03/05 KEPPLER, J.O. Region 3. Office of Director Spp. 22671.153 24X Fichs: 50-461, 84/03/14, 8403190170
- 8403190329 Forwards Vendor Program Insp Repts 99700231/83-01 k 99900231/84-01 on 831115-17 & 840116-20, respectively, closing out Part 21 rept re seepage of oil from Okonite cables. POTAPOVS,U Region 4, Office of Director 84/03/15, NORELIUS,C E Division of Project & Resident Programs ip 22675 026 24X Fichs:50-461/84/03/15,8403190329.
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PHR Reactor Cavities." Syc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/03/21 Consolidated Edison Co. of New York, Inc. 123pp. 22823 229. 24X Fiche: 50-000:84/03/21, 8402090043.
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Bys." Svc list encl. JORDAN,E.L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/03/21. Consolidated Edison Co. of New York, Inc. 135pp. 22933 001. 24X Fiche 50-000,84/03/21,8402090044
- R. Periodic operating reports & related correspondence
- 8403020443 Forwards monthly status rept of offsite emergency preparedness for OL reviews for Jan 1984. Changes in FEMA finding dates not caused by delay due to offsite emergency planning issues
 DIRCKS,W J. Office of the Executive Director for Operations.
 84/02/21. PALLADINO Commissioners. 9pp 22492,083. 24X Fiche: 30-000, 84/02/21. 8403020443.

- S Reportable occurrences, LERA & related correspondence
- 8403080240 Part 21 rept re failure of Pacific Air Products linear converter Initially reported on 840117 Failure due to excessive wear of brass shaft guides on input & output shafts Investigation underway HALL.DP Illinois Power Co 84/02/29 KEPPLER, J Q Region 9, Office of Director 2pp 22556 287 24X Fiche 50-461,84/02/29, 240380240
- 8403260255 Interim Deficiency Rept 55-83-06 re weld defects on structural steal members supplied by Rockwell Engineering. Initially reported on 830427 Repairs initiated & vendors notified of 0A responsibility HALL, D.P. Illinois Power Co. 84/03/15 KEPPLER, J.O. Region 3, Office of Director 4pp 22754 313 24X Fiche 50-461,84/03/15,8403260255
- V Operator Examinations
- 8403190398 Forwards tabulated results to review of operating shift experience for facility HALL.D P Illinois Power Co 84/03/09 DENTON.H.R Office of Nuclear Reactor Regulation, Director 5pp 22675:058 24X Fiche 30-461.84/03/09.8403190398
- DOCKET 50-462 CLINTON POWER STATION, UNIT 2

 F Security, medical, emergency & fire protection plans
- 8403120077 Notifies of 840323 workshop on fire protection safe shutdown reutraments of 10CFR50. App R in Rosemont, IL to discuss IE Info Notice 84-09 & provide add1 shutdown analyses &/or mod guidance Agenda enci SPESBARD, R L Division of Emergency Preparadness & Operational Support. 84/03/06 GERSTNER, W C Illinois Power Co 3pp. 22586 302 24X Fiche 30-461,84/03/06.8403120077
- G. Inspection reports, IE Bulletins & correspondence
- 8403170327 Forwards Vendor Program Insp Repts 97900231/83-01 & 99900231/84-01 on 831115-17 & 840116-20, respectively, closing out Part 21 rept re seepage of oil from Okonite cables.

 POTAPOVE, V. Region 4. Office of Director 84/03/15, NORELIUB.C E Division of Project & Resident Programs ip 22675 026. 24X Fiche: 50-461.84/03/15.8403190329.
- 8 Reportable occurrences, LERs & related correspondence
- 8403140122 Part 21 rept re status update concerning abnormal wear on linear converters Test program underway Results of investigation indicate excessive wear caused by hunting of control circuitry

 DDDSON.J P Pacific Air Products Co 84/03/09 Director's Office, Dffice of Inspection and Enforcement 7pp, 22624 068 24X Fiche, 50-000, 84/03/09, 8403140122
- DOCKET 50-463 FULTON GENERATING STATION, UNIT 1
- Q Adjudicatory correspondence
- 8403010221 Forwards brisf on issues re liability for fees & expenses. Related correspondence IRWIN.D P Hunton & Williams IRWIN.D P Philadelphia Ejectric Co 84/02/27 CDYTER.B P., LINENBERGER.C., DEBYLVA.D.P. Atomic Bafety and Licensing Board Panel. ip 22435/132 24X Fiche: 50-463.84/02/27.840301022i
- --8403010229 Brief on issues re liability for fees & expenses Certificate of 8vc entl. Related correspondence IRWIN.D.P. Humton & Williams. 84/02/27 Atomic Safety and Licensing Board Panel 41pp. 22435 133. 24X Fiche 50-463.84/02/27.8403010221
- T. Hearing transcripts on mon-antitrust matters
- 8403050071 Transcript of 840227 hearing in Philadelphia, PA, Fp 1-83 # Atomic Bafety and Licensing Board Panel 84/02/29 83pp 22490 284 24X Fiche 50-463,84/02/29,8403050071

DOCKET 50-464 FULTON GENERATING STATION, UNIT 2

G Adjudicatory correspondence

B403010221 Forwards brief on issues re liability for fees & expenses Related correspondence IRWIN, D P Hunton & Williams IRWIN, D P Philadelphia Electric Co B4/02/27 COTTER, B P , LINENBERGER, G , DESYLVA, D P Atomic Safety and Licensing Board Panel 1p 22435 132 24X Fiche 50-463, 84/02/27, 8403010221

--8403010229 Brief on issues re liability for fees & expenses Certificate of Svc encl Related correspondence IRWIN.D P Philadelphia Electric Co IRWIN.D P Hunton & Williams 84/02/27 Atomic Safety and Licensing Board Panel 41pp 22435 133 24X Fiche 50-463,84/02/27,8403010221

T Hearing transcripts on non-antitrust matters

8403050071 Transcript of 840229 hearing in Philadelphia, PA Pp 1-83 * Atomic Safety and Licensing Board Panel 84/02/29 83pp 22490 284 24X Fiche 50-463,84/02/29,8403050071

DOCKET 50-466 ALLENS CREEK NUCLEAR STATION, UNIT 1

A Application/construction stage documents & correspondence

B403080179 Fourth partial response to FOIA request for six categories of documents re facilities forwards App A documents App B document estimaly withheld (ref FDIA Exemption 5) Review of add1 documents subj to request continuing FELTON.J M Division of Rules and Records 84/02/13 ANDERSON.S I Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000.84/02/13.B403080179

--8102200029 Forwards action plan for resolution of non-TMI issues for pending CP/mfg license applications.per DPc of Nuclear Reactor Regulation approach to resumption of licensing Safety evaluation inputs should be provided by 810401 EISENHUT.D Q Division of Licensing 80/12/31 VOLLMER.R Division of Engineering 1p 22583 277 24% Fiche 50-000,84/02/13.8403080179

DOCKET 50-467 ALLENS CREEK NUCLEAR STATION, UNIT 2

Application/construction stage documents & correspondence

9403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of add1 documents subj to request continuing FELTON. J M Division of Rules and Records 84/02/13 ANDERSON, B I Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000.84/02/13.8403080179

--Bi02200029 Forwards action plan for resolution of non-TMI issues for pending CP/mfg license applications.per Ofc of Nuclear Reactor Regulation approach to resumption of licensing Safety evaluation inputs should be provided by Bi0601 EISENHUT.D Q Division of Licensing 80/12/31 VOLLMER.R Division of Engineering ip 22583 277 24X Fiche 50-000.B4/02/13.8403080179

DOCKET STN-50-470 CESSAR SYSTEM 60

NRC Safety Evaluation Report (SER), suppls & correspondence

3403010276 Forwards interface requirements re block valves on atmospheric dump valves to close out Confirmatory Item 2 of SSER 2 re steam generator tube rupture analysis SCHERER. A E Combustion Engineering Inc 84/02/24 EISENHUT, D 0 Division of Licensing 3pp 22435 173 24X Fiche 50-470,84/02/24,8403010276

3403270107 Forwards interface requirement re shutdown cooling analysis of reactor coolant gas vent sys per SSER 2 Confirmatory item closed SCHERER, A E Combustion Engineering, Inc. 84/03/22 EISENHUT, D © Division of Licensing 2pp 22766 347 24X Fichs 50-470, 84/03/22, 8403270107

K Utility Final Safety Analysis Report (FSAR) & amends

84032000B1 Forwards for review, Amend 9 to C-E std SAR Major changes result from response to confirmatory items & NRC questions SCHERER. A E Combustion Engineering, Inc. 84/03/16 EISENHUT, D O Division of Licensing 2pp 22682 001 24X Fiche 50-470,84/03/16,840320081

--8403200085 Amend 9 to C-E std SAR WEBT.J H Combustion Engineering: Inc 84/02/29 524pp 22662 003 24X Fiche 50-470,84/03/16.8403200081

DUCKET 50-471 PILORIM NUCLEAR POWER STATION, UNIT 2

A Application/construction stage documents & correspondence

8403080179 Fourth pertial response to FOIA request for six categories of documents re facilities Forwards App A documents App B documents neitrely withheld (ref FOIA Exemption 5) Review of addl documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, S 1 Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000.84/02/13.8403080179

--8102200029 Forwards action plan for resolution of non-TMI issues for pending CP/mfg license applications.cer Ofc of Nuclear Reactor Regulation approach to resumption of licensing Safety evaluation inputs should be provided by \$10601 EISENHUT, D 0 Division of Licensing 80/12/31 VOLLMER, R Division of Engineering 1p 22583 277 24X Fiche 50-000,84/02/13,8403080179

5 Reportable occurrences, LERs & related correspondence

8403260233 Forwards summary list of deficiencies identified per IOCFR30 55(e).Part 21 & potential generic ltr repts for comments

8TAROSTECKI.R Division of Project & Resident Programs 84/02/28.
Region I. Office of Director 7pp 22756 065 24X
Fiche 50-000.84/02/28.8403260233

DOCKET STN-50-482 WOLF CREEK GENERATING STATION

A Application/construction stage documents & correspondence

8402090302 Notifies that Rev 2 to "Rept of Independent Review of Environ Qualification Programs to NUREO-0588" not complete reissue.per 840201 ltr Several rept apps had no changes PETRICK.N A Standardized Nuclear Unit Power Plant Bystem 84/02/07 DENTON.H R Office of Nuclear Reactor Regulation, Director 1p 22160 174 24X Fiche 50-000,84/02/07.8402090302

8402090017 Board Notification 84-038 forwards RJ Mattson 840123 memo to D9 Eisenhut providing status update of NRC actions re Hestinghouse ECCS actuation logic EISENHUT.D G Division of Licensing 84/02/27 PALLADIND Commissioners 7pp 22546 007 24X Fiche 50-000.84/02/27, 8402070017

8403010406 Forwards listed addl info re slave relay testing Tech Spec requirements for ESF actuation sys.per 840217 request Meeting w/Instrumentation & Control Sys Branch requested during wk of 840227 PETRICK.N A Standardized Nuclear Unit Power Plant Bystem 84/02/27 DETOIN.H R Office of Nuclear Reactor Regulation, Director 82pp 22433 297 24X Fiche. 50-000, 84/02/27, 8403010406.

8403020274 Forwards response to Generic Ltr 83-28 re required actions based on generic implications of Balem ATMS events. Withree oversize drawings Aperture can'ds are available in PDR KOESTER, G L. Kansas Cas & Electric Co. 84/02/29 DENTON, H.R. Office of Nuclear Reactor Regulation. Director 48pp 22482 042 24X Fiche 50-482,84/02/29,8403020274

B403120315 Forwards comments & request for add1 info to complete review of facility procedures generation package. Info requested within 30 days of ltr receipt YOUNOBLOOD, B J Licensing Branch 1 84/02/29, KOESTER, P. L Kansas Gas & Electric Co 7pp 22619 001 24X Fiche. 50-482, 84/02/29,

8403120363 Forwards request for add1 info to complete symbols of Instrumentation & Control Bys Branch site audit Info should be submitted by 840420 YOUNGBLOOD, B J Licensing Branch 1 84/02/29 KOESTER, G.L. Kansas Gas & Electric Co GCHNELL, D F Union Electric Co 4pp 22615 354 24X Fichs 50-000,84/02/29,8403120363.

- B403140283 Ack receipt of util B40202 request to withhold proprietary version of "SNUPPS Steam Generator Tube Plugging Margin Evaluation" from public disclosure Based on listed reasons, submitted info will be withheld (ref 10CFR2 790) YOUNOBLOOD, B Licensing Branch 1 84/03/01 WIESEMANN, R A Westinghouse Electric Corp 4pp 2696.323 24X Fiche 50-000,84/03/01,8403140283
- 8403060278 Forwards equipment qualification data package for HE-1 to support justifications for interim operation Odd-numbered pages mistakenly not copied EGDP-HE-1 substitutes info in previous package
 PETRICK, N A Standardized Nuclear Unit Power Plant System 84/03/05 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 22518 099. 24x Fichs 50-000,84/03/05,8403060298
- 8403i30342 Forwards justification for interim operation (JIO) for listed programs & draft Mestinghouse Class 3 topical repts Final resolution of issues for listed JIOs expected by 830331 PETRICK, N.A. Standardized Nuclear Unit Power Plant System, 84/03/06, DENTON, H.R. Office of Nuclear Reactor Regulation, Director, 4pp. 22616:147 24X Fiche 50-000,84/03/06,8403130342
- --B403130358 Draft "Equipment Qualification Data Package," Rev 4 to EQDP-EBE-13, "Process Protection Bys" RAHE, E P Westinghouse Electric Corp WCAP-8587 R4E8E-13D B3/06/30 22pp 22616 153 24X Fiche 50-482,84/03/06,8403130342
- --8403130389 Draft "Equipment Gualification Data Fackage," Rev O to EGDP-HE-108, "Head Vent Sys -- Electronic Control Module (HE-108) "
 RAHE: E. P. Hestinghouse Electric Corp. WCAP-8587 ROHE-108 D
 83/10/31 28pp 22616.195 24X Fiche: 50-482,84/03/06.8403130342
- 8403190421 Notifies of Caseload Forecast Panel 840320-22 site visit to obtain info re const status Info will be used to better allocate NRC resources during license review List of info requested and YOUNO8LOOD, B J Licensing Branch I 84/03/07 KDESTER, Q.L Kansas Oas & Electric Co 6pp 22681:336 24X Fiche.50-482,84/03/07,8403190421
- B403270283 Notification of Caseload Forecast Panel 840320-22 site visits w/util to review const progress & assess projected fuel load datas Agenda encl O'CONNOR, P. W. Licensing Branch 1 84/03/07 YOUNGBLOOD, B. J. Licensing Branch 1 7pp 22789 254 24X Fiche 50-482,84/03/07,8409370283.
- 8403270331 Notification of cancellation of Caseload Forecast Panel 840321 site visit & 840320 & 22 public meetings O'CONNOR:P # Licensing Branch 1 84/03/07 YOUNGDLOOD, B J Licensing Branch 1 7pp. 22822 236 24X Fiche 50-482,84/03/07. 8403270331
- B403270240 Summary of 840217 meeting w/utils:Bechtel & Hestinghouse re slave relay testing frequency & SER open items on loss of instrument bus & boron dilution control HOLONICH.J J, O'CONNOR.P W. Licensing Branch 1 B4/03/08 Licensing Branch 1 6pp. 22789.275 24X Fiche 50-000:84/03/08,8403270240
- 8403130197 Forwards addl info re design process used in constructing facility, per 840104 request Attachment discusses meanly identical design of Caliaway & Wolf Creek & minor design features unique to Wolf Creek
 KCESTER. O L Kansas Gas & Electric Co 84/03/09 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 30pp 22605:065
 24X Fiche: 50-482,84/03/09,8403130197
- 8403150064 Forwards experience tables for shift consultant for hot participation requirements of plan proposed by util group on operating shift experience.

 KDESTER, O. L. Kenses Cas & Electric Co. 84/03/12 DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 3pp. 22643-065-24X Fiche: 50-482, 84/03/12, 8403150064
- 3403190225 Ack receipt of 840217 ltr responding to NRC 830525 request High school verification diploma verification process acceptable GAGLIARDD.J E. Region 4. Office of Director. 84/03/13. MOESTER, G L. Kansas Gas & Electric Co. 1p 22672 097. 24X Fichs: 50-482, 88/03/13. 8403190225.

- ~-B403190229 Responds to NRC B30511 & 25 ltrs verifying that employees in positions requiring high school diploma have graduated from high school Background investigation contractor will routinely verify highest education itr KOESTER. O L Kansas Oas & Electric Co B4/02/17 GAGLIARDO, J & Region 4, Office of Director ip 22672 098 24X Fiche 50~482,84/03/13,8403190225
- 8402090041 Board Notification 84-050 provides Commission policy statement & proposed rulemaking on environ qualifications EISENHUT.D 0 Division of Licensing 84/03/14 Atomic Safety and Licensing Board Panel 10pp 22714 338 24X Fiche 50-000,84/03/14.8402090041
- 8403210073 Informs that facility fuel load scheduled for 840923 Commercial operation planned for Spring 1985, w/plant scheduling activities retaining target for going commercial during Feb 1785 KDESTER.9 L Kansas Cas & Electric Co 84/03/15, DENTON, H R Defice of Nucleur Reactor Regulation, Director ip 22704 362 24X Fiche 50-482,84/03/15,8403210073
- 8403200252 Forwards Rev 1 to "Review of Boron Dilution Transients at Wolf Creek" & proof & review pages of Tech Specs deleting boron dilution mitigation sys W/two oversize drawings Aperture cards are available in FDR KOESTER, 0 L Kansas Qas & Electric Co 84/03/16 DENTON, H R Office of Nuclear Reactor Regulation, Director. 5pp 22687 170 24X Fiche 50-482,84/03/16,8403200252
- --8403200260 Proof & review pages of Tech Specs deleting boron dilution mitigation sys.

 * Kansas Gas & Electric Co 84/03/16 4pp 22687 175 24X
 Fiche 50-482,84/03/16.8403200252
- --8403200269 Rev 1 to "Review of Boron Dilution Transients at Wolf Creek " RUBIN,A . UNIONE,A Impell Corp STEWART,N Kansas Gas & Electric Co 01-0780-1269 R01 84/03/31 83pp 22687 180 24 Fiche 50-482,84/03/16,8403200252
- B403220019 Forwards add1 info re equipment & seismic qualification & pump & valve operability issues identified by NRC
 PETRICK,N A Standardized Nuclear Unit Power Plant System
 B4/03/16 DENTON.H R Office of Nuclear Reactor Regulation,
 Director 3pp 22713 355 24X Fiche 50-000,84/03/16,8403220019
- 8403220029 Responds to three NRC questions re analysis of steam generator tube rupture event, contained in FSAR Util reanalyzing condition using operator times from actual events & ANS Draft Std S8 8 Rept expected by 840630 PETRICK, N A Brandardized Nuclear Unit Power Plant System 84/03/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp, 22712 318 24% Fiche 50-000,84/03/16,8403220029
- B403220026 Forwards requested changes to final draft Tech Specs List of Tach Specs discussed widescription of status & action required also encl PETRICK, N A Standardized Nuclear Unit Power Plant System. B4/03/20, DENTON: H R Office of Nuclear Reactor Regulation, Director 67pp 22713 215 24X Fiche 50-000:84/03/20.8403R20026
- 8403220184 Forwards implementation schedule for resolutions of supplementary survey & auxiliary shutdown panel review findings & list of addl commitments made during NRC audit Human factors items considered closed PETRICK, N A Standardized Nuclear Unit Power Plant System 84/03/21 DENTON, H R. Office of Nuclear Reactor Regulation, Director 7pp 22717 028 24X Fiche 30-000.84/03/21.8403220184
- B4032602B2 Forwards addl info documenting environ qualification of mechanical equipment program completion per SSER 4 for Wolf Creek PETRICK, N A Btandardized Nuclear Unit Power Plant System 84/03/21 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 116pp 22753 034 24x Fichs 50-000, B4/03/21, B4032602B2
- E NRC Bafety Evaluation Report (SER), supple & correspondence
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of addl documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, S I Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000,84/02/13,8403080179.

- --BIO3040052 Forwards short & long-term OL & CP review schedules, in response to 801216 masting w/USOS List of OL plant reviews for which NRC tentatively plans to seek USOS assistance is provided USOSN.R E Geosciences Branch NRC-03-BO-113 81/01/21 DEVINE, J F Interior, Dept of, Geological Survey Jpp 22583 272 24X Fiche 50-000,84/02/13,8403080179.
- B403270240 Bummary of B40217 meeting w/utils, Bechtel & Westinghouse ra slave relay testing frequency & SER open items on loss of instrument bus & boron dilution control HDLONICH, J. J. ("CONNOR! P W Licensing Branch 1 84/03/08 Licensing Branch 1 App 22789 275 24x Fiche 50-000,84/03/08, B403270240
- B403200050 Advises that containment pressure-high-1 setpoint complies w/TMI Action Item II E. 4 2, "Containment Isolation Dependability" & SER requirements PETRICK.N A Btandardized Nuclear Unit Power Plant Bystem 84/03/15 DENTON.H R Dffice of Nuclear Reactor Regulation, Director 2pp 22698 291 24% Fiche 50-000.84/03/15,8403200050
- 8403200257 Forwards updated response to request for add1 info remonitoring & evaluating seepage at downstream toe of main dam (SER Confirmatory Item A-2) Info incorporated in OL application
 KUEBTER, Q L. Kansas Gas & Electric Co. 84/03/16 DENTONH, H.R. Office of Nuclear Reactor Regulation, Director 3pp. 22696-359-24X Fiche 50-482:84/03/16,8403200257
- 8403240282 Forwards add1 info documenting environ quelification of mechanical equipment program completion per SBER 4 for Wolf Creek PETRICK.N A Standardized Nuclear Unit Power Plant System 84/03/21. DENTON: HR Office of Nuclear Reactor Regulation. Director 116pp 22753 034. 24% Fiche 50-000.84/03/21.8403260282
- F Security, medical, emergency & fire protection plans
- 8403050152 Submits scenario for submittal of info re smergency preparedness & upgrade & maint necessary to ensure proper review & coordination w/all participant organizations COLLINS. J T Region 4, Defice of Director 84/02/09 KOESTER, C L Kanass Gas & Electric Co 2pp 22485 233 24X Fiche 50-482.84/02/09.8403050152
- 8402090006 Board Notification 84-034 forwards R Vollmer 840206 memo to D Eisenhut re fire research results concerning fires in slectrical cabinets in control room EISENHUT, D G Division of Licensing 84/02/23 PALLADING Commissioners ip 22576 203 24X Fiche 50-000, 84/02/23, 8402090004
- --8403080316 Recommends that info re fire research results concerning fires in electrical cabinets in control room be submitted for board motification.per NRR Ofc Ltr 19, dtd 821001 Further evaluation of test data required VOLLMER, R M Division of Engineering 84/02/06 EISENHUT, D. Q Division of Licensing. 10pp 22576.204. 24X Fiche 50-000, 84/02/23, 8402090006
- B403010270 Advises of design changes instituted as result of NRC fire protection review Add1 sprinkler heads will be installed in auxiliary bldg west corridors at 2.000 ft & 1,974 ft elevations
 PETRICKIN A Standardized Nuclear Unit Power Plant System 84/02/24. DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 22432 251 24% Fichs 50-000,84/02/24,8403010270
- 8403200253 Clarifies FSAR statement re fire protection review of seismic design of ail collection devices to maintain functional integrity during postulated SSE Sys pressure boundary will remain intact PETRICK.N A Standardized Nuclear Unit Power Plant System 84/03/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 22690-207 24X Fiche 50-000,84/03/14.8403200253
- G Adjudicatory correspondence
- B403090053 Patition of Nuclear Awareness Network for leave to intervene & request for hearing Certificate of Syc & affidavits encl JOHNSON, A R Nuclear Awareness Network 84/03/06 Commissioners 14pp 22576 187 24X Fiche, 50-482, 84/03/06, 8403090053
- 8403140061 Response to applicant 840203 & staff 840208 responses to Nuclear Awareness Network 840119 petition to intervene & request for hearing. Requests for late-filed intervenor status should be granted. Certificate of Svc encl JOHNSON.A R Nuclear Awareness Network 84/03/06 Commissioners 14pp 22633.065 24X Fiche 50-482,84/03/06.8403140061

- 8403140002 Memorandum memorialiring 840312 conference call re Nuclear Awareness Network. Inc 840221 % 0306 motions WOLFE, B J Atomic Safety and Licensing Board Panel. 84/03/13 2pp 22632 127 24% Fiche 50-482, 84/03/18.8403140002
- B403140030 Order granting B40221 motion for time extension of addl 15 days to file reply & affidavits per 840209 order WOLFE, B J Atomic Safety and Licensing Board Panel 84/03/13, 1p. 22633 213 24% Fiche 50-482,84/03/13
- 8403190158 Notifies of Caseload Forecast Panel 840320-22 meetings at site to review const progress & obtain add1 info for assessing projected fuel load dates KARHAN. H Hearing Branch 1 84/03/13, HOLFE, B J , PAXTON, H C , ANDERSON, O C Atomic Sefety and Licensing Board Panel 1p 27688 355 24X Fichs 50-482, 84/03/15, 8403190158.
- 8403190123 Informs that Caseload Forecast Panel 840320-22 meetings cancelled ASLB & parties will be notified upon rescheduling KARMAN, M Hearing Branch 1 84/03/14 WOLFE, S. J., ANDERSON, G. C. PAXTON, H. G. Atomic Safety and Licensing Board Panel 1p. 22669 219 24X Fiche 50-482, 84/03/14, 8403190123
- 8403170035 Bubmits best estimate dates, per 830412 conference call Completion of const scheduled for 840923, fuel load scheduled for 840923 & commercial operation scheduled for 8pring 1985 Certificate of 8vc encl Related correspondence SILBERG, J.E. Shaw, Pittman, Potts & Trowbridge SILBERG, J.E. Kansas Gas & Electric Co. 84/03/15 WOLFE, S. J., ANDERSON, G.C., PAXTON, H.C. Atomic Safety and Licensing Board Panel 3pp 22666 212 24X Fiche 50-482, 84/03/15,8403190035.
- 8403260325 Proposed findings of fact.conclusions of law & brief in form of proposed initial decision Certificate of 8vc encl SILBERG, J E Kansas Cas & Electric Co SILBERG, J, E Shaw, Pittman, Potts & Troubsidge DSB 091 84/03/20, 275pp. 22760-264, 24X Fiche 50-482,84/03/20,8403260325
- 8403270326 Advises of Caseload Forecast Panel meeting scheduled for 840410-12 Related correspondence. KARMAN.M Hearing Branch 1 DBB 134 84/03/22. MOLFE,S J., PAXTON.H C. ANDERSON,G C. Atomic Safety and Licensing Board Panel. 1p 22787 019 24X Fiche, 50-482,84/03/22,8403270326.
- 8403280334 Memorandum & order denying petition for leave to intervene & request for hearing Served on 840327 WOLFE,S J Atomic Safety and Licensing Board Fanel D88 146, 84/03/26 Nuclear Awareness Network, 14pp 22767.051, 24X Fiche 50-482,84/03/26,8403280334
- K Utility Final Safety Analysis Report (FBAR) & amends
- 8403200187 Forwards Rev 14 to FSAR Rev will be incorporated into applications of listed dockets by amends submitted by Kansas Oss & Electric Co & Union Electric Co PETRICK, N A Standardized Nuclear Unit Power Plant System.

 84/03/14 DENTON: H R Office of Nuclear Reactor Regulation.

 Director 3pp 22691 i99 224X Fichs 50-000.84/03/14.8403200187
- --B403200189 Rev 14 to FSAR * Standardized Nuclear Unit Power Plant System, 84/03/31 1099pp 22691 202 24X Fiche 50-000,84/03/14,8403200187
- G. Inspection reports: IE Bulletins & correspondence
- B403280211 FOIA request for documents re falsification of QA/QC records by M Annas at facility BELL: N Nuclear Information & Resource Bervice. 84/01/05. Office of Administration 2pp 22779: 326 24X Fiche. 50-482. 84/01/05, 8403280211.
- 8403130250 Ack receipt of 831130 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-482/83-20 Listed info re experience & training of radiation protection technicians due in 30 days GAGLIARDO
- 8403050179 Forwards IE Insp Rept 50~482/83-36 on 831114-18 & 1128-1201 & notices of violation & deviation GAGLIARDD, J E Region 4. Office of Director 84/02/14. KDESTER: Q.L. Kansas Qas & Electric Co 2pp 22485; 120. 24X Fiche: 50~482,84/02/14. 8403050179
- --8403050180 Notice of violation from insp on 831114-18 & 1128-1201 * Region 4, Office of Director. 84/02/14 5pp 22485-122, 24% Fiche 50-482,84/02/14,8403050179

- --8403050182 Notice of deviation from insp on 831114-18 & 1128-1201 * Region 4. Office of Director 84/02/14 ip 22485 127 24X Fiche 50-482,84/02/14,8403050179
- --8403050186 IE Insp Rept 50-482/83-36 on 831114-18 & 1128-1201
 Violations noted failure to have steel erection & audit
 procedures Deviation noted failure to comply w/FSAR
 commitment to ANBI N45 2 12-1977
 BOARDMAN.J.R., SMITH.W.F., JOHNSON.W.D. Region 4, Dffice of
 Director 84/02/14 21pp 22485 128 24X Fiche 50-482.84/02/14.
 8403050179
- 8403010213 Provides data supporting preservice inspiralized request re random component & piping welds.per util 840118 ltr Listed welds require partial relief from Section XI volumetric exam requirements

 BETKEN. 8 J Standardized Nuclear Unit Power Plant Bystem 84/02/2*

 DENTON, HR Office of Nuclear Reactor Regulation, Director 4pp 22435 231 24X Fiche 50~000.84/02/24.8403010213
- 8401170072 IE Info Notice 84-13. "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl.

 JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc. 115pp 22709 237 24X Fichs 50-000.84/02/28.8401170072
- 8402090007 IE Info Natice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE.J N Division of GA, Bafeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp. 22552-329 24X Fichs 50-000.84/03/02,8402090007
- 840207000B IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22593 098 24X Fiche 50-000,84/03/02,8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases"

 8vc list sncl
 JURDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc 119pp 22553 217 24X Fiche 50-000.84/03/02.8402090009
- 8492090011 IE Info Notice 84-17. "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X fiche 50-000.84/03/05.8402090011
- 8402070024 IE Info Notice 84-07 Rev 1. "Lessons Learned From Insps of Firm Protection Bafe Shutdown Sys " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07. Consolidated Edison Co. of New York, Inc. 118pp 22635,047 24X Fiche 50-000,84/03/07.8402070024
- 8402070028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Bys " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402070028
- 8403280216 Partial response to FDIA request for documents refalsification of GA/GC records by M Annas at facility Forwards App A documents Documentation also available in PDR FELTON, J. M Division of Rules and Records 84/03/07 8ELL, N Nuclear Information & Resource Service 2pp 22799 328 24X Fichs 50-482,84/03/07.8403280216
- --8403280225 Discusses review of closed & open files re alleged falsification of traveler records A Gauthier "spread sheet" shows Files 82-10 & 82-13 as closed & assigned to J Sinclair. Region IV had nothing in files BOWERB, H Office of Inspector & Auditor 83/03/16 CUMMINGS, J J Office of Inspector & Auditor 1p 22797. 330 24X Fiche: 50-482, 84/03/07, 8403280216
- --8403280229 Forwards 18 investigation rept re facility; per telcon request W/o encl CUMMINOS, J J Office of Inspector & Auditor 82/01/12. MORRIBSETTE, K Justice, Dept of 1p 22799.331 24X Fiche: 50-482,84/03/07,8403280216
- ~-8403280235 Responds to Region IV 810722 & IE 811016 memos re improper duplication of safety-related pipe hanger DOJ contacted & advised that no objection raised to IE issuing investigation rept BCHMEBELEN, A Office of Inspector & Auditor 81/12/23, THOMPBON, D. Enforcement & Investigation Staff (Pre 820201) ip 22797:332 24% Fiche 50-482,84/03/07.8403280216

- ~-8403280240 Discusses improper duplication of safety-related pipe hanger K Morrissette. DDJ. apprised on 811208 of contents of Region IV investigation rept refabrication of safety-related pipe hanger DDJ had no objections to rept issuance SINCLAIR. J R Office of Inspector & Auditor 81/12/23 Office of Inspector & Auditor 81/12/23 Office 84/03/07.8403280216
- 8403130320 Ack receipt of 840217 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 30-482/83-30 GAGLIARDD, J E Region 4, Office of Director 84/03/08 KDESTER, 0 L Kansas Oas & Electric Go 2pp 22607 273 24X Fiche 50-482,84/03/08,8403130320
- --8403130345 Revises response to NRC 831125 ltr re violations noted in IE Insp Rept 50-482/83-30 Corrective actions procedure revised to require quality inspector to complete tool mat) equipment & personal property written records KDESTER.6 L Kansas Qas & Electric Co 84/02/17 9AQLIARDO, J E Region 4, Office of Director ip 22607 275 24% Fiche 50-482, 84/03/08.8403130320
- 8403130390 Ack receipt of 840222 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-482/83-39 GAGLIARDO, J E Region 4. Office of Director 84/03/08 KDESTER: G L Kaness Osa & Electric Co 1p 22616 001 24X Fiche 50-482,84/03/08,8403130390
- --8403130397 Responds to NRC 840123 ltr re violations noted in IE Insp. Rept 50-482/83-39 Corrective actions two boric acid transfer pumps reinstalled & bent frame on Pump PBG02A reworked Sys flushed & hydrostatically tested KOESTER, 0 L Kansas Qas & Electric Co 84/02/22 GAGLIARDD, J E Repien 4, Office of Director 3pp 22616 002 24X Fiche 50-482,84/03/08,8403130390
- 8402070031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Bvc list encl
 DEYQUNG:R C Director's Office Office of Inspection and
 Enforcement 84/03/12 Consolidated Edison Co of New York, Inc
 134pp 22823 094 24X Fiche 50-000.84/03/12.8402090031
- 8403160119 Forwards vendor insp repts identifying concerns based on Vendor Program Branch insps of vendor activities Significance of findings re quality & acceptability of product or svc provided by vendor should be evaluated GAGLIARDOJ E Region 4, Office of Director B4/03/13 KDESTER, O L Kansas Gas & Electric Co 2pp 22655.116 24x Fiche 50-482.84/03/13.8403160119
- 8403200178 Forwards vendor insp repts indentifying concerns found during insps of vendor activities Evaluation of significance of reported findings re quality & acceptability of product or svc provided by vendors requested W/o encl repts GAGLIARDO, J & Region 4, Office of Director 84/03/16 KDGSTER, G L Mansas Gas & Electric Co 4pp 22697 127 24X Fiche 50-482,84/03/16,8403200178
- 8402090043 IE info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 123pp 22823 229 24X Fiche 50-000.84/03/21.8402090043
- 8402070044 IE Info Notice 84-20, "Svc Life of Relays in Gafety-Related Bys " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22733 001 24X Fiche 50-000,84/03/21,8402070044
- 8403270128 Suppls 840224 request for relief from ASME Section XI preservice exam requirements for component & piping sys welds, per 840308 telcon Relief requested for reactor pressure vessel weld SEIKEN, S J Standardized Nurlear Unit Power Plant System 84/03/26 DENTON, H R Office of Nuclear Reactor Regulation Director 2pp. 22807 192 24X Fiche 50-000.84/03/26.8403270128
- R Periodic operating reports & related correspondence
- 8403020443 Forwards monthly status rept of offsite emergency preparedness for OL reviews for Jan 1984 Changes in FEMA finding dates not caused by delay due to offsite emergency planning issues
 DIRCKS,W J Office of the Executive Director for Operations 84/02/21 PALLADINO Commissioners 9pp 22492 083 24X Fiche. 50-000. 84/02/21. 8403020443

- S Reportable occurrences, LERs & related correspondence
- 84030i0145 Final deficiency rept re Bergen-Paterson weld beam attachment laminations Initially reported on B30617 Item determined not reportable per 10CFR50 55(e) KOESTER, G L Kansas Gas & Electric Co 84/02/22 GAGLIARDO, J E Region 4. Office of Director ip 22435 312 24X Fiche 50-482,84/02/22,8403010145
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines. Gimpel NPS-4 T&T valve, to close Encl 1tr dtd 840203 sent to listed utils GE notified of affected units in BWR plants
 THEROUX,R R Terry Corp 84/02/22 WOODRUFF,R W Director's
 Office, Office of Inspection and Enforcement 6pp 22706 327
 Fiche 50-000,84/02/22,8402210032
- 8403130215 Interim potential deficiency rept re water damaged Limitorque operators Initially reported on 840203 Investigation indicated water may mave entered actuator bores through installed flexible conduit KÜESTER. G L Kansas Gas & Electric Co 84/03/01 GAGLIARDO, J E Region 4, Office of Director 1p 22614 110 24X Fiche 50-482,84/03/01,8403130215
- 8403190036 Interim deficiency & Part 21 repts re status on open items KOESTER.G L Kansas Gas & Electric Co 84/03/05 GAGLIARDO, J & Region 4, Office of Director 18pp 22666 215 24X Fiche 50-482.84/03/05.8403190036
- 8403270105 Final deficiency rept re exposed threads on seal welded connections on Class 2 threaded pipe connections Initially reported on 831012 Connections reworked & dye penetrant KDESTER, G L Region 4. Office of Director 1p 22766 346 24x
 Fiche 30-482.84/03/16,8403270105
- 8403270191 Withdraws deficiency rept re cracked card edge connector receptacles in Westinghouse 7300 process sys Initially reported on 831025 Uti) determined no adverse affect on safety operations Item not reportable per 10CFRSO 55(e) KDESTER G L Kansas Gas & Electric Co 84/03/16 GAGLIARDO, J E Region 4. Office of Director 1p 22769 148 24X Fiche 50~482.84/03/16.8403270151
- 8403270163 Withdraws deficiency rept re welds on Bergen-Paterson sway struts Initially reported on 830224 Welds should not have adversely affected safety of operations if gone uncorrected item not reportable per iOCFR50 35(e) KOESTER.G L Kansas Gas & Electric Co 84/03/16 GAGLIARDD, J E REGION 4. Office of Director 1p 22764 024 24% Fiche 50~482.84/03/16.8403270163
- 8403270179 Deficiency rept re interpretation of code welding subsection classification Initially reported on 831208 Welds dye penetrant tested & found acceptable Condition determined not reportable per 100FRSO 35(e)
 KDESTER.G L Kansas Gas & Electric Co B4/03/16 GAGLIARDD.J E
 Region 4. Office of Director 1p 22771 131 24X
 Fithe 30-482.84/03/16.8403270179
- 8403270268 Withdraws deficiency rept re pulsation dampeners for positive displacement charging pump Initially reported on 831222 Util determined conditions would not affect safety of operations Item not reportable per 10CFRSO 55(e) MOESTER.G L. Kansas Gas & Electric Co. 84/03/16 GAGLIARDO, J E Region 4, Office of Director 1p 22770 134 24X Fiche 50-482.84/03/16.8403270268
- 8403230108 Part 21 rept re design deficiency in field-run cables to Valcor solenoid valves Initially reported on 840319 Approx 50 valves affected at each facility Mgt corrective action
- meyers. B L Bechtel Corp 84/03/19 Office of Inspection and Enforcement Fiche 30-000.84/03/19,8403230108 DEYOUNG, R Director's Office. 2pp 22730 234 24X

V Operator Examinations

8403090225 Forwards operating shift experience tables for shift supervisors, senior reactor operators & control room operators, per Util Group on Operating Shift Experience 840224 meeting KOESTER. G L. Kansas Gas & Electric Co 84/03/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 24X Fishe 50-482,84/03/06,8403090225 . 5pp

DOCKET SIN-50-483 CALLANAY PLANT, UNIT 1

A Application/construction stage documents & correspondence

- 8402090302 Notifies that Rev 2 to "Rept of Independent Review of Environ Gualification Programs to NUREG-0588" not complete raissue.per 840201 itr Several rept apps had no changes PETRICK, N A Standardized Nuclear Unit Power Plant System 84/02/07 DENTON. H R Office of Nuclear Reactor Regulation, Director 1p 22160 174 24X Fiche 50-000,84/02/07,8402090302
- B402090017 Board Notification 84-038 forwards RJ Mattson 840123 memo to D3 Elsenhut providing status update of NRC actions re Hestinghouse ECC8 actuation logic EISENHUT,D G Division of Licensing 84/02/27 PALLADING, GILINSKY, ROBERTS Commissioners 7pp 22546.007 24X Fiche 50-000,84/02/27.8402090017
- --B40201050B Provides updated status of rev to Westinghouse designed PWR ECCS actuation logic Westinghouse plans completion of evaluation for submittal by mid-Mar 1984 MATTSON, R. J. Division of Systems Integration (post 811005) 84/01/23 EISENHUT, D. Division of Licensing 2pp 22546 007 24X Fiche 50-000,84/02/27,8402090017
- 8403010406 Forwards listed addl info re slave relay testing Tech Spec requirements for ESF actuation sys.per 840217 request Meeting w/Instrumentation & Control Sys Branch requested during wk of 840227 PETRICK, N A Standardized Nuclear Unit Power Plant System 84/02/27 DENTON.H R Office of Nuclear Reactor Regulation, Director 820p 22433 297 24X Fiche 50-000,84/02/27,8403010406
- 8403050383 Requests specific wording of proposed change to Tech Spec 3 6 1 7 b & technical bases for acceptability of change re 500 h mini purge limit Changes requested within 7 days of 1tr receipt YOUNOBLOOD, N J Licensing Branch 1 84/02/27 8CMNELL, D. F. Union Electric Co 3pp 22501 330 24% Fithe 50-483, 84/02/27, 8403050353
- 8403120182 Revised "Process Control Program" W/840308 ltr HAMILTON:0 W, SCHNELL:D F Union Electric Co 84/02/28 DENTON:H R Office of Nuclear Reactor Regulation, Director 22587 151 24% Fiche 50-483;84/02/28;8403120182
- 8403120363 Forwards request for addl info to complete evaluation of Instrumentation & Control Sys Branch site audit Info should be submitted by 840420 YOUNGILODD B J Licensing Branch 1 84/02/29 KOESTER, G. L. Kansas Gas & Electric Co SCHNELL, D F Union Electric Co 4pp 22615 354 24X Fiche 50-000,84/02/29,8403120363
- 8403120249 Forwards comments he review of process control program
 Revised version, incorporating comments, requested no later
 than 14 days from ltr date
 YOUNGBLOOD, B J Licensing Branch 1 84/03/01 SCHNELL, D F Union
 Electric Co 4pp 22619 145 24X Fiche 50-483,84/03/01,8403120249
- 8403140283 Ack receipt of util 840202 request to withhold proprietary version of "SNUPPS Steam Generator Tube Plugging Margin Evaluation" from public disclosure Based on listed reasons, submitted info will be withheld (ref 10CFR2 790) YDUNOBLOOD, B Licensing Branch 1 84/03/01. WIESEMANN, R. A Westinghouse Electric Corp 4pp 22636 323 24X Fiche: 50-000, 84/03/01, 8403140283.
- 8403060298 Forwards equipment qualification data package for HE-1 to support justifications for interim operation Odd-numbered pages mistakenly not copied EQDP-HE-1 substitutes into in previous package
 PETRICK, N A Standard: 12 Muclear Unit Power Plant System, 84/03/05 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 22518 099 24X Fiche 50-000,84/03/05,8403060298
- 8403130342 Forwards justification for interim operation (JIO) for listed programs & draft Westinghouse Class 3 topical repts Final resolution of issues for listed JIOs expected by **850331** BETRICK.N A Standardized Nuclear Unit Power Plant System
 84/03/06 DENTON.H R Office of Nuclear Reactor Regulation,
 Director 4pp 22616 149, 24X Fiche 50-000,84/03/06,8403130342

- B403120104 Rev 2 to "Offsite Dose Calculation Manual " W/840308 ltr NEICHALFEN A P , SCHNELL, D F Union Electric Co B4/03/07 DENTON, H R Office of Nuclear Reactor Regulation, Cirector 127pp 22885 002 24x Fiche 50~483.84/03/07.8403120104
- 8403120171 Forwards revs to FSAR Section 17 2 12 re calibr performed against certified equipment of ref stds Revs resulted from recent discussions w/GA Branch personnel & will be incorporated in Rev 8 to FSAR site addendum SCHNELL.DF Union Electric Co 84/03/08 DENTON,H R Office of Nuclear Reactor Regulation. Director 5pp 22587 181 24X Fiche 50~483.84/03/08.8403120171
- 8403270240 Summary of 840217 meeting w/utils, Bechtel & Hestinghouse re slave relay testing frequency & SER open items on loss of instrument bus & boron dilution control HOLONICH, J J, O'CONNOR, P W Licensing Branch i 84/03/08 Licensing Branch i 5pp 22789 275 24X Fiche 50-000,84/03/08, 8403270240
- 8403270271 Summary of 840218 & 16 meetings w/util re rev to operational GA program Util responses received by 840221 & NRC evaluations will be reported in 85RR 3 Attender list encl HOLONICH, J Licensing Branch 1 84703708 Licensing Branch 1 5pp 22789 267 24X Fiche 50-483,84/03/08,8403270271
- 8403280129 Forwards final draft Tech Specs for review Amend to application should be submitted incorporating changes to a ccurately reflect plant, FSAR & SER analyses EISEANHUT, D 9 Division of Licensing 84703/08 SCHNELL, D F. Union Elsettic Co 469pp 22809 331 24X Fiche, 50-483, 84/03/08, 8403280129.
- 8403160323 Forwards addl responses to Generic Ltr 83-28, "Required Actions Based on Generic Implications of Salem ATW8 Events"

 Bufficient info submitted to support issuance of OL Mythrae oversize drawings Aperture cards are in FDR SCHNELL, D. F. Union Electric Co. 84/03/12 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 55pp 22662 193 24X Fiche. 50-483, 84/03/12,8403160323
- 8403190269 Forwards tables defining nuclear plant experience of shift supervisors, senior operators, reactor operators & shift technical advisors
 SCHNELL, D. F. Union Electric Co. 84/03/13 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 7pp. 22671 206 24X
 Fiche: 50-483, 84/03/13,8403190269
- 8403280015 Notification of 840315 meeting w/utils in Bethesda.MD to discuss appeal of containment purgs operation time limit given in Tech Specs Agenda encl HOLDNICH, J. Licensing Branch 1 84/03/13 YOUNGBLOOD, B.J. Licensing Branch 1 5pp 22812 326 24% Fiche 50-483.84/03/13.8403280015
- 8402090041 Board Notification 84-050 provides Commission policy statement & proposed rulemaking on environ qualifications EIBENHUT, D G Division of Licensing 84/03/14 Atomic 8afety and Licensing Board Panel 10pp 24X Fiche 30-000.84/03/14,8402090041
- B403210121 Advises of inadvertent error in Attachment 2 of 840306 ltr (ULNRC-754) appealing 500 h mini-purge limit, per Tech Spec 3, 6 1, 7 b First & second paragraphs should read as stated SCHNELL-D F Union Electric Co 84/03/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 22707 180 24X Fiche 50-483,84/03/14,8403210121
- B403220019 Forwards addl info re equipment & seismic qualification & pump & valve operability issues identified by NRC PETRICK.N A Standardized Nuclear Unit Power Plant Bystem B4/03/16 DENTON-H R Office of Nuclear Reactor Regulation, Director. 3pp. 22713 355 24X Fiche 50-000,84/03/16,8403220019
- 840322002? Responds to three NRC questions re analysis of steam generator tube rupture event, contained in FSAR Util reanalyzing condition using operator times from actual events & ANB Draft Std 58 B Rept expected by 840630 PETRICK.N.A Standardized Nuclear Unit Power Flant System 84/03/16 DENTON.H R Office of Nuclear Reactor Regulation, Director 3pp 22712.318 24X Fiche 50-000,84/03/16,8403220029
- 8403220026 Forwards requested changes to final draft Tech Specs List of Tech Specs discussed w/description of status & action required also encl PETRICK.N A Standardized Nuclear Unit Power Plant System 84/03/20 DENTON, H R Office of Nuclear Reactor Regulation, Director. 67pp. 22713,215 24X Fiche 50-000,84/03/20,8403220026

- 8403220184 Forwards implementation schedule for resolutions of supplementary survey & auxiliary shutdown panel review findings & List of addi commitments made during NRC audit Human factors items considered closed PETRICK,N A Standardized Nuclear Unit Power Plant Bystem 84/03/21 DENTON,HR Office of Nuclear Reactor Regulation, Director 7pp 22717 028 24X Fiche 50-000,84/03/21,8403220184
- 8403260282 Forwards add1 info documenting environ qualification of mechanical equipment program completion per SSER 4 for Wolf Creek
 PETRICK,N A Standardized Nuclear Unit Power Plant System
 84/03/21 DENTON:H R Office of Nuclear Reactor Regulation,
 Director 116pp 22753 034 24X Fiche 50-000.84/03/21.8403260282
- 8403270016 Requests issuance of OL in order that outlined activities for fuel load may proceed as planned Unit may be ready for fuel load as early as 840423
 SCHNELL.DF Union Electric Co 84/03/23 DENTON, HR Office of Nuclear Reactor Regulation, Director 13pp 82770 043 24X Fiche 50-483.84/03/23,8403270016
- 8403270229 Provides add1 info re 40-yr operating term commencing w/ issuance of GL SCHNELL.D F Union Electric Co 84/03/23 DENTUN.H R Office of Nuclear Reactor Regulation, Director 4pp 22772 130 24X Fiche 50-483,94/03/23,8403270229
- E NRC Safety Evaluation Report (SER), supply & correspondence
- 8403270240 Summary of 840217 meeting w/utils.Bechtel & Hestinghouse re slave relay testing frequency & SER open items on loss of instrument bys & boron dilution control HOLONICH.J.J. Licensing Branch 1 84/03/08 Licensing Branch 1 6pp 22789 275 24% Fiche 50-000.84/03/08.8403270240
- B403270271 Summary of 840215 & 16 meetings w/util re rev to operational GA program Util responses received by 840221 & NRC evaluations will be reported in SSER 3 Attender list encl HOLONICH.J.J. Licensing Branch 1 84/03/08 Licensing Branch 1 5pp 22789 267 24X Fiche 50-483,84/03/08,8403270271
- B403200050 Advises that containment pressure-high-1 setpoint complies w/TME Action Item II E 4 2. "Containment Isolation Dependability" & SER requirements PETRICK, N A Standardized Nuclear Unit Power Plant System 84/03/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22698 291 24X Fiche 30-000,84/03/15,8403200050
- F Security, medical, emergency & fire protection plans
- 84030700B1 Callaway/Fulton Counties,MD radiological emergency response plan * Callaway County, MD * Fulton, MD 83/05/11 164pp 22537 110 24X Fiche 50-483,83/05/11,8403070081
- 8403070076 Montgomery County, MD radiological emergency response plan # Montgomery County, MD 83705716 156pp 22539 274 24X Fiche 50-483, 83705716, 8403070078
- 8403070084 Qasconade County.MO radiological response plan * Qasconade County. MO 83/05/16 160pp 22547 101 24X Fiche 50-483,83/05/16.8403070084
- 8403070090 Osage County MO radiological emergency response plan * Osage County MO 83/05/16 158pp 22548 102 24X Fiche 50-483,83/05/16,8403070090
- B403070087 State of M0 nuclear accident plan * Missouri, State of 83/05/31 400pp 22540 070 24X Fiche 30-483,83/05/31,8403070087
- 8402270156 Revised emergency plan implementing procedures, including Procedures EIP-22-00202 re callout of emergency organization & EIP-22-00224 re transport of contaminated injured/ill personnel W/840216 transmittal & receipt form * Union Electric Co 84/02/16 53pp 22387 23B 24X Fiche 50-483,84/02/16,8402270156
- 8403090204 Rev 0 to Security Dept Procedure SDP-ZZ-PP005, "Protected & Vital Area Entry/Exit" W/transmittal & receipt form dtd B40302 H1001NS, T Union Electric Co B4/02/17 Sipp 22574 274 24X Fiche 50-483,84/02/17,8403090204

- B402070006 Board Notification 84-034 forwards R Voilmer 840206 memo to D Eisenhut re fire research results concerning fires in electrical cabinets in control room EISENHUT, D C Division of Licensing 84/02/23 PALLADINO, OILINSKY, ROBERTS Commissioners 1p 22576 203 24X Fiche 30-000, 84/02/23, 84020700004
- --8403080316 Recommends that info re fire research results concerning fires in electrical cabinets in control room be submitted for board notification.per NRR Ofc Ltr 19. dtd 821001 Further evaluation of test data required VOLLMER.R H Division of Engineering 84/02/06 EISENHUT.D O Division of Licensing 10pp 22576 204 24X Fiche 50-000.84/02/23.8402090006
- B403010270 Advises of design changes instituted as result of NRC fire protection review Add1 sprinkler heads will be installed in auxiliary bldg west corridors at 2.000 ft & 1.974 ft elevations
 PETRICK, N A Standardized Nuclear Unit Power Plant System 84/02/24 DENTON, H R Office of Nuclear Resctor Regulation, Director 2pp 22432 251 24X Fiche 50-000,84/02/24,8403010270
- 8403090263 Revised emergency plan implementing procedures, including Procedures EIP-22-00101 re classification of emergencies & EIP-22-00210 re in-plant radiological controls W/B40225 transmittal & receipt forms * Union Electric Co 84/02/25 200pp 22573 319 24X Fiche 50-483.84/02/25.8403090263
- 8403050016 Forwards Rev 7 to radiological emergency response plan. SCHNELL,D F Union Electric Co 84/03/01 DENTON.H R Office of Nuclear Røactor Regulation, Director 5pp 22485 304 24X Fichs.50-483,84/03/01.8403050016
- --8403050019 Rev 7 to radiological emergency response plan # Union Electric Co 84/03/01 354pp 22486 238 24 Fiche 50-483,84/03/01,8403050016
- 8403090283 Forwards State of MO & local radiological emergency response plans, for incorporation into facility application W/o encls SCHNELL, D F Union Electric Co 84/03/01 DENTON, H Office of Nuclear Reactor Regulation, Director 3pp 22574 269 24X Fiche 30-483,84/03/01,8403090283
- 8403120046 Advises of 840323 regional workshop in Resement, IL w/ali Region III licensess to discuss fire protection safe shutdown requirements of 10CFR50, App R Agenda encl SPESSARD, R L Division of Emergency Preparedness & Operational Support 84/03/06 SCHNELL, D F Union Electric Co 3pp 22589 295 24X Fiche 50~483,84/03/06,8403120046
- 8403200111 Forwards IE Emergency Preparedness Appraisal Rept 50-483/84-02 on 840109-20 & 0222 No deficiencies deviations or noncompliance noted Apps A & B re open & improvement items, respectively, also encl PAPERIELLO, C J Region 3, Office of Director 84/03/06 SCHNELL, D F Union Electric Co 17pp 22683 167 24X Fiche 50-483,84/03/06.8403200111
- --8403200119 IE Emergency Preparedness Appraisal Rept 50-483/B4-02 on 840109-20 & 0222 No deviations or noncompliance noted Major areas inspected onsite emergency preparedness involving organization, training & retraining & drills & exercises PLOSKI.T. GLOERSEN.W. Region 3, Office of Director ROHRER.D Director's Office. Office of Inspection and Enforcement 84/03/05 67pp 22683 884 24X Fiche 50-483.84/03/06.8403200111
- 8403160246 Revised emergency plan implementing procedures including Procedure EIP-ZZ-00102 re emergency implementing actions. EIP-ZZ-00201 re notifications & EIP-ZZ-00212 re protective action recommendations W/840307 transmittal. MITTENBERGER'S Union Electric Co 84/03/07 134pp 22861 226 24X Fiche 50-483.84/03/07.8403160246
- B403200237 Revised emergency implementing procedures, including Rev 2 to Health Physics Departmental Procedure HDP-ZZ-06000 re contamination guidelines & limits & Rev 1 to Health Physics Technical Procedure HTP-ZZ-02005 W/840308 ltr KANYO, J P Union Electric Co 84/03/08 40pp 22691 135 24X Fiche 50-483,84/03/08,8403200237

- 8403200253 Clarifles FSAR statement re fire protection review of seismic design of all collection devices to maintain functional integrity during postulated SSE Sys pressure boundary will remain intact PETRICK, N A Standardized Nuclear Unit Power Flant System 84/03/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 22670 207 24X Fiche 50-000, 84/03/14, 8403200253
- 8403300R09 Procedure request form & nuclear safety evaluation checklist for Rev i to Emergency Implementing Procedure ETP-ZZ-00210. "Radiological Controls During Emergencies " W/840322 Transmittal 1038 Uncontrolled copy * Union Electric Co 84/03/22 4pp 22819 327 24X Fiche 50-483,84/03/22,8403300209

G Adjudicatory correspondence

- 8403070116 Order extending time until 840312 for Commission to act to review ALAB-740, -750, -750A & -754
 CHILK,S J Dffice of the Secretary of the Commission 84/03/05
 Commissioners ip 22841 355 24X Ficha 50-483,84/03/05,
- 8403190144 Advises that time for Commission to review ALAB-740,750,750A & 754 expired Commission declined review Dacision became final agency action on 840312 CHILK,8 J Office of the Secretary of the Commission 84/03/16 Union Electric Co 1p 82666 357 24X Fiche 50-483,84/03/16,
- K Utility Final Safety Analysis Report (FSAR) & amends
- 9403050016 Forwards Rev 7 to FSAR site addendum (filed in PDR Category K) & Rev 7 to radiological emergency response plan (filed in PDR Category F)
 SCHNELL.D F Union Electric Co 84/03/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 22495 304 24X
 Fiche 50-483,84/03/01.8403050016
- --8403050018 Rev 7 to FSAR site addendum * Union Electric Co 84/03/01 289pp 22485 309 24X Fiche 50-483, 84/03/01,8403050016
- 8403200187 Forwards Rev 14 to FBAR Rev will be incorporated into applications of listed dockets by amends submitted by Kanwas Oas & Electric Co & Union Electric Co PETRICK, N A Blandardized Nuclear Unit Power Plant Bystem 84/03/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 3pp 22691 199 24X Fiche 50-000, 84/03/14, 8403200187
- ~~B403200187 Rev 14 to FSAR * Standardized Nuclear Unit Power Plant System 84/03/31 1099pp 22691 202 24X Fichs 50-000,04/03/14:8403200187

M Antitrust correspondence

- 8403070045 Apologizes for slow response to 840208 request for add1 info on wheeling contract No new add1 info available Agreement not yet in sight
 CARTER, B R Kirksville, MO 84/02/29 LAMBE, W Site Analysis
 Branch lp 22541 249 24X Fiche 50-483,84/02/27,8403070045
- G Inspection reports, IE Bulletins & correspondence
- 8403080251 Forwards IE Insp Rept 50-483/84-01 on 840104-27 % notice of violation SYREETER.J F Region 3. Office of Director 84/02/22 8CHNELL.D F Union Electric Co 2pp 22556 273 24X Fiche 50-483,84/02/22:8403080251
- --B4030B0256 Notice of violation from insp on 840104-27 STREETER, J F Region 3, Office of Director 84/02/21 2pp 22556 295 24X Fiche 50-483,84/02/22,8403080251
- --8403080261 IE Insp Rept 50-483/84-01 on 840104-27 Nancomplience identified inadequate procedures during testing & maint & inadequate test program for spent fuel cooling sys WOHLD.P R . WILLIAMS.D L . FARBER.M J Region 3, Office of Director 84/02/21 9pp 22556 297. 24X Fiche 50-483,84/02/22.8403080251
- 8403010213 Provides data supporting preservice inspiralief request re random component & piping welds.per util 840118 ltr_Listed welds require partial relief from Section XI volumetric stam requirements
 SEIKEN.S J Standardized Nuclear Unit Power Plant System 84/02/24
 DENTON.H R Office of Nuclear Reactor Regulation, Director, 4pp 22435 231 24X Fiche 50-000.84/02/24.8403010213

- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list
 - UDRDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22909 239 24X Fiche 50-000,84/02/28,8401190072
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Rays by DDT & NRC " Svc list encl GRACE.J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000.84/03/02.8402090007
- B402090008 IE Info Notice 84-16. "Failure of Automatic Sprinklar Sys Valves to Operate " Bvc list entl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000.84/03/02.8402090008
- 8402090009 IE Info Notice 84-15. "Reporting of Radiological Releases "
 Byc list encl
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc 119pp 22553 217 24X Fiche 30-000.84/03/02.8402090009
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitragen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Past 830103) 84/03/05 Consolidate Edison Co of New York Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- B403200111 Forwards IE Emergency Preparedness Appreisal Rept 50-483/84-02 on 840109-20 & 0322 No deficiencies deviations or noncompliance noted Apps A & B re open & improvement items, respectively, also encl PAPERIELLO, C J Region 3, Office of Director 84/03/06 8C(NELL, D F Union Electric Co 17pp 22683 167 24X Fiche 50-483,84/03/06,8403200111
- --8403200119 IE Emergency Preparedness Appraisal Rept 50-483/84-02 on 840109-20 & 0222 No deviations or noncompliance noted Major areas inspected onsite emergency preparedness involving organization training & retraining & drills & exercises PLOSKI.T. GLOERSEN.W Region 3. Office of Director ROHRER, D Director's Office, Office of Inspection and Enforcement 84/03/05 67pp 22683 184. 24X Fiche 50-483,84/03/06,8403200111
- B402090024 IE Info Notice 84-09, Rev 1, "Lessons Learned From Insps of Fire Protection Bafe Shutdown Bys " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/07 Consolidated Edison Co. of New York, Inc 118pp 22635 049 24X Fiche 50-000,84/03/07,8402090024
- 8402070028 IE Info Natice 84-18, "Stress Corrosion Cracking in PWR Sys" Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/07. Consolidated Edison Co of New
 York, Inc 118pp 22584 186 24% Fiche 50-000,84/03/07,8402090028
- B402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Bafety Bys," Byc list ent!
 DEYOUNG,R C. Director's Dffice, Office of Inspection and Enforcement. B4/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000,84/03/12,8402090031
- B403200279 Ack receipt of 840309 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-483/83-27 BTREETER.J F. Region 3, Office of Director, 84/03/15 BCHNELL, D F Union Electric Co. 1p 22697.093 24X Fiche 50-483,84/03/15,8403200279.
- --8403200285 Responds to NRC 840126 ltr re viplations noted in IE Insp Rept 50-483/83-27 Corrective actions test objectives section of C8-038J02 revised to Indicate changes & acceptance criteria for RRR sys verified 8CHNELL.D F. Union Electric Co. 84/03/09 STREETER.J F Region 3. Diffice of Director. 3pp 22697 094 24X Fiche, 50-483, 84/03/15,8403200279
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PHR Reactor Cavities" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fichs 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Bys." Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 135pp. 22933 001 24X Fiche 50-000,84/03/21,8402090044

- 8403290128 Suppls 840224 request for relief from ASME Section XI preservice exam requirements for component & piping syswelds, per 840308 telcon Relief requested for reactor pressure vessel weld SEIKEN.S J Standardized Nuclear Unit Pawer Plant System 84/03/26 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 22807 192 24X Fiche 50-000.84/03/26.8403290128
- R Periodic operating reports & related correspondence
- 8403020443 Forwards monthly status rept of offsite emergency preparedness for OL reviews for Jan 1984 Changes in FEMA finding dates not caused by delay due to offsite emergency planning issues

 DIRCKS.W J Office of the Executive Director for Operations
 84/02/21 PALLADING Commissioners 9pg 22492 083 24X

 Fiche 50-000, 84/02/21, 8403020443
- 8 Reportable occurrences, LERs & related correspondence
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines. Oimpel NPB-4 T&T valve, to close Encl ltr dtd 840203 sent to listed utils GE notified of affected units in DWR plants
 THEROUX.R R Terry Corp 84/02/22 WDDDRUFF.R W Director's Office, Office of Inspection and Enforcement App 22706 327 24 Fiche 50-000, 84/02/22, 8403210032
- 8403190034 Interim Deficiency Rept U-67 re missing seismic positioners on four breakers used in reactor trip switchgear supplied by Hestinghouse Initially reported on 840207 Final rept expected by 840414 SCHNELL, D.F. Union Electric Co. 84/03/08 KEPPLER, J.C. Region 3. Office of Director 2pp 22666 i23 24X Fiche 50-483, 84/03/08, 8403190034
- 8403200028 Final Deficiency Rept U-46 re structural steel boits not tightened to spec requirements Structural adequacy of connections sufficient in as-found condition Potential 10CFR80 55(e) deficiency withdrawn 8CHNELL.DF Union Electric Co 84/03/12 KEPPLER, J @ Region 3-0ffice of Director 1p 22696 341 24X Fiche 50-483,84/03/12,8403200028
- 8403230115 Final Deficiency & Part 21 Rept U-62 re failure of stator winding on NEO28 emergency diesel generator mfg by Beloit Power Bys Initially reported on 830812 Stator replaced Emergency generator installed & load tested SCHNELL.D F Union Electric Co 84/03/15 KEPPLER.J Q Region 3 Office of Director 4pp 22730 211 24X Fiche 50-483.84/03/15, 8403230115
- B403270079 Final Deficiency Rept U-34 re pipe clamp interference w/rod end of rigid sway strut assemblies supplied by Corner & Lada Initially reported on B10B13 Rework Plan FV-14 implemented to repair sway strut assemblies onsite BCHNELL.DF Union Electric Co B4/03/16 KEPPLER.J G. Region 3. Office of Director 9pp 22769 223 24X Fiche 50-483.84/03/16.8403270079
- B403270187 Interim Deficiency Rept U-59 re inconsistent installation & insp of safety-related control valve accessories & vendor supplied safety-related HVAC instrumentation Initially reported on 830727 Final rept b 840411 SCHNELL-D F Union Electric Co B4/03/16 KEFPLER, J G Region 3-Office of Director 2pp 22771 322 24X Fiche 30-483.84/03/16, 8403270187
- 8403230108 Part 21 rept re design deficiency in field-run tables to Valcor solenoid valves Initially reported on 840319 Approx 50 valves affected at each facility Mgt corrective action repts issued MEYERS.B L Bechtel Corp 84/03/19 DEYOUNG.R Director's Office. Defice of Inspection and Enforcement 2pp 22730 234 24X Fiche: 50-000, 84/03/19, 8403230108
- 8403270182 Final Deficiency & Part 21 Rept U-64 re Limitorque valve actuators BN-HV-8812A & B Initially reported on 831017 Valve failure due to improper installation of motor pinion gear All 88-2-80 actuators verified for proper gear installation 80HNELL.DF Union Electric Co 84/03/20 KEPPLER.J Q. Region 3 Office of Director 4pp 22771 331 24X Fiche 50-483,84/03/20.8403270182

V. Operator Examinations

8403190269 Forwards tables defining nuclear plant experience of shift supervisors; senior operators, reactor operators & shift tachnical advisors

SCHNELL, D.F. Union Electric Co. 84/03/13 DENTON, H.R. Uffice of Nuclear Reactor Regulation, Director 7pp 22671 206 24X

Fiche: 50-483, 84/03/13, 8403190269

- X Onsite Storage of Low Level Waste
- 8403120182 Revised "Process Control Program" W/840308 ltr HAMILTON,G W., SCHNELL.D F Union Electric Co 84/02/28 DENTON,H R Office of Nuclear Reactor Regulation, Director 22589 151 24X Fiche 50-483,84/02/28,8403120182

DOCKET STN-50-484 CALLAWAY PLANT, UNIT 2

- A Application/construction stage documents & correspondence
- B402090041 Board Notification 84-050 provides Commission policy statement & proposed rulemaking on environ qualifications EISENHUT, D.G. Division of Licensing 84/03/14 Atomic Safety and Licensing Board Panel 10pp 24X Fiche 50-000.84/03/14.8402090041
- S Reportable occurrences, LERs & related correspondence
- B403230115 Final Deficiency & Part 21 Rept U-62 re failure of stator winding on NEO28 emergency diesel generator mfg by Beloit Power Sys Initially reported on 830812 Stator replaced Emergency generator installed & load tested SCHWELL, D.F. Union Electric Co. 84/03/15 KEPPLER, J.G. Region 3, Office of Director 4pp 22730 211 24X Fiche 50-483,84/03/15,8403230115
- B403230108 Part 21 rept re design deficiency in field-run cables to Valcor solenoid valves Initially reported on 840319 Apprex 50 valves affected at each facility Mgt corrective action repts issued MEYERS, 3 L Bechtel Corp 84/03/19 DEYOUNG, R Director's Office, Office of Inspection and Enforcement 2pp 22730 234 24X Fichs 50-000,84/03/19,8403230108

DOCKET STN-50-488 PERKINS NUCLEAR STATION, UNIT 1

- A Application/construction stage documents & correspondence
- B403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of addl documents subj to request continuing FELTON, J M Division of Rules and Records B4/02/13 ANDERSON, S I Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000,84/02/13,8403080179
- --8102200029 Forwards action plan for resolution of non-TMI issues for pending CF/mfg license applications, per Dfc of Nuclear Reactor Regulation approach to resumption of licensing Safety evaluation inputs should be provided by \$10601 EISENRUT.D G Division of Licensing 80/12/31 VOLLMER, R Division of Engineering 1p 22593 277 24X Fiche 50-000,84/02/13,8403080179

DOCKET STN-50-489 PERKINS NUCLEAR STATION, UNIT 2

- A Application/construction stage documents & correspondence
- 8403080179 Fourth partial response to FOIA request for six categories of focuments re facilities Forwards App A documents App B document mitirally withheld (ref FOIA Exemption 5) Review of addl documents subj to request continuing FELTON, J M Division of Bules and Records 84/02/13 ANDERSON, S I Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000,84/02/13,8403080179
- --B102200029 Forwards action plan for resolution of non-TMI issues for pending CP/mfg license applications per Ofc of Nuclear Reactor Regulation approach to resumption of licensing Bafety evaluation inputs should be provided by B10601 EISENHUT.D O Division of Licensing 80/12/31 VOLLMER, R Division of Engineering 1p 22583-277 24X Fiche 50-000,84/02/13.8403080179

LEAR STATION, UNIT 3
tage documents & correspondence

isponse to FOIA request for six categories; Forwards App A documents App B I (re/ FOIA Exemption 5) Review of less tontinuing tules and Records 84/02/13 ANDERSON, S I & Barer 7pp 22383 226 24X

- --8102200027 Forwards action plan for resolution of non-TMI issues for pending CP/mfg license applications.per Ofc of Nuclear Reactor Regulation approach to resumption of licensing Safety avaluation inputs should be provided by 810601 EISENHUT.D G Division of Licensing 60/12/31 VOLLMER.R Division of Engineering 1p 22083 277 24X Fiche 50-000.84/02/13.8403080179
- DOCKET STN-30-493 CHEROKEE NUCLEAR STATION, UNIT 3
- Q Inspection reports, IE Bulletins & correspondence
- B402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl ORACE.J N Division of GA, Bafeguards & Inspection Programs (Post B30103) B4/03/02 consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000,84/03/02.8402090007
- DOCKET 50-496 MONTAGUE NUCLEAR POWER STATION, UNIT 1

 G Inspection reports, IE Bulletins & correspondence
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22707 237 24X Fiche. 30-000,84/02/28,8401190072
- 8402070008 IE info Notice 84-16. "Failure of Automatic Sprinkler 8ys Valves to Operate " 8vc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 2253 078 24X Fiche 50-000.84/03/02.8402070008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases "

 8vc list encl
 JORDAN, E. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc. 119pp 22553 217 24X Fichs 50-000,84/03/02,8402090009
- B402090011 IE Info Notice B4-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/03/05 Consolidated Edison Co. of New York, Inc 117pp 22553 336 24X Fitche 50-000,84/03/05,8402090011
- 8402090024 IE Info Notice 84-09 Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Bys " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635.049 24X Fichm 50-000,84/03/07,8402090024
- 8402070028 IE Info Notice 84-18, "Stress Corrosion Cracking in FWR Sys "Sys list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402070028
- 8402090031 IE Bulletin 84-02. "Failures of GE Type HFA Relays in Use in Class IE Safety Bys " Svc list encl
 DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000.84/03/12.8402090031
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl, JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc 123pp 22823 229 24X Fiche 50-000,84/03/21,8402090043
- B402090044 IE Info Notice B4-20; "Bvc Life of Relays in Bafety-Related Bys " Bvc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044
- DOCKET 50-497 MONTAGUE NUCLEAR POWER STATION, UNIT 2

 G Inspection reports, IE Bulletins & correspondence
- 8401190072 JE Info Notice 84-13. "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl.

 JCRDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 1159p. 22707 237 24X Fiche 50-000.84/02/28.8401190072.

- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl ORACE, J N Division of GA. Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000,84/03/02,8402090007
- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fishe 50-000,84/03/02,8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases"

 8vc list encl

 UDRDAN.E L Division of Emergency Preparedness & Engineering

 Response (Post 830103) 84/03/02 Consolidated Edison Co. of New

 York, Inc. 119pp 22583 217 24X Fiche 50-000.84/03/02.8402090009
- B402090011 IE Info Notice 84-17. "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000.84/03/05.8402090011
- 8402090024 IE Info Notice 84-07. Rev i, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN: E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22635 049 24X Fiche 50-000,84/03/07,8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Sys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- B402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list enc!
 DEYOUND, R. C Director's Office, Office of Inspection and Enforcement B4/03/12 Consolidated Edison Co of New York, Inc 134pp 22823-094 24X Fiche 50-000.84/03/12.8402090031
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Cansolidated Edison Co. of New York, Inc. 123pp 22823 229 24X Fiche 50-000.84/03/21.8402090043
- 8402090044 IE Info Notice 84-20. "Svc Life of Relays in Safety-Related Bys " Byc list enc! JURDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044
- DOCKET STN-50-498 SOUTH TEXAS PROJECT, UNIT 1
- A Application/construction stage documents & correspondence
- 8403010444 Summary of 831130-1202 Caseload Forecast Pane) meetings w/util at site in Matagorda County.TX re review of const progress to obtain info for use as input to OL review schedule process Viewgraphs encl
 VIETTI.A Licensing Branch 3 84/02/22 Licensing Branch 3 79pp. 22447-226 24X Fiche 50-498.84/02/22.8403010444
- B402090017 Board Notification 84-03B forwards RJ Mattson 840123 memo to DG Eisenhut providing status update of NRC actions re Wastinghouse ECCB actuation logic.
 EISENHUT, D 0 Division of Licensing 84/02/27 PALLADING Commissioners 7pp 22546 007. 24X Ficha 50-000,84/02/27,8402090017
- 8403280122 Summary of 840224 meeting w/Westinghouse Gwners Group in Bathesda,MD re proposed Westinghouse steam generator tube rupture generic program Attendee list & agenda entl NERSES,V Licensing Brench 3 84/03/07 Licensing Brench 3 35pp 22811 131 24X Fiche, 50-000, 84/03/07, 8403280122.
- 8403300125 Forwards draft, "Mitigative Techniques & Analysis of Generic Site Conditions for Groundwater Contamination Associated w/Severe Accidents " KNIGHTON, G. W. Licensing Branch 3 84/03/15 GOLDBERG, J. H. Houston Lighting & Power Co. 3pp. 22841 001 24X Fiche 50-496,84/03/15, 8403300125.
- --8403300132 Draft, "Mitigative Techniques & Analysis of Generic Bite Conditions for Groundwater Contamination Associated w/ Severe Accidents "
 SHAFER, J M , DBERLANDER, P. L. , SKAGGS, R. L. Battelle Memorial Institute, Pacific Northwest Laboratories 84/01/31 300pp 22841 004. 24X Fiche 50-498,84/03/15,8403300125

- F Security, medical, emergency & fire protection plans
- 8403090149 Submits scenario for submittal of info re emergency preparedness upgrade & maint necessary to ensure proper review & coordination w/all participant organizations COLLING.J T Region 4. Office of Director 84/02/09 OPREA.Q W Houston Lighting & Power Co. 2pp. 22484 052 24X Fiche 50-498.84/02/09.8403050149
- 8403010544 Advises that NRC will not delete privacy or proprietary info from emergency plans unless specifically requested by licensee.per 810709 Generic Ltr 81-27 W/o request entire plan will be placed in PDR KNIGHTON.G W Licensing Branch 3 84/02/14 GOLDBERG.J H Houston Lighting & Power Co 4pp 22438 339 24X Fiche 50-498.84/02/14, 8403010544
- G Adjudicatory correspondence
- B403070117 Advises that encl final rept on condition identified in 10cFR30 35e rept was submitted on 840214 Rept concludes design basis differential settlement criteria not exceeded W/o final rept Certificate of Svc encl NEWHANJR Newman & Holtzinger * Houston Lighting & Power Co 84/03/05 BECHHOEFER.C . LAMB.J C . HILL.E E Atomic Safety and Licensing Board Panel 4pp 22541 356 24X Fiche 50-478.84/03/05.840307017
- 8403140152 Motion for reconsideration of ASLB 830714 memorandum & order re 830530 suppl to motion for new contention Certificate of Svc encl SINKIN.L Citizens Concerned About Nuclear Power, Inc. 84/03/04 Atomic Safety and Licensing Board Panel 18pp. 22625 173 24X Fiche 50-498,84/03/08,8403140152
- 8403150037 Memorandum & order for parties not to respond to Concerned Citizens Against Nuclear Power 840308 motion for reconsideration of ASLB 830714 order re financial qualifications contention BECHMOEFER C Atomic Safety and Licensing Board Panel 84/03/13 Office of the Executive Legal Director 2pp 22643 082 24X Fiche 50-498.84/03/13.8403150039
- 8403150016 Partial Initial Decision LBP-84-13 (Phase 1) re OL Citizens Concerned About Nuclear Power 830808 motion to reopen Phase I record denied BECHHDEFER C , LAMB, J C , HILL, E E Atomic Safety and Licensing Board Panel B4/03/14 359pp 22644 001 24X Fiche 50-498,84/03/14.8403150016
- 840322023B Notice of change of mailing address for Judgo Hill BECHHOEFER, C Abomic Safety and Licensing Board Panel DSB 060 84/03/20 Office of the Executive Legal Director ip 22719 039 24X Fichs 50-498,84/03/20.840322023B
- 8403270025 Notice of intent to appeal Partial Initial Decision 79-421-07 OL Certificate of Svc encl SINKIN.L Citizens Concerned About Nuclear Power, Inc. DBB 119 84/03/23 2p 22770 071 24K Fiche 50-498,84/03/23 8403270025
- O Inspection reports. IE Bulletins & correspondence
- 8403010125 Further response to FOIA request for IE Rept 79-19, notice of proposed imposition of civil penalties notice of violation & order to show cause Forwards Socuments listed on App A FELTON.J M Division of Rules and Records 84/01/11 HAMLIN,J B Shaw, Pittman, Potts & Troubridge 2pp 22447 176 24X Fiche 50-498.84/01/11.8403010125
- --B403010132 Requests info re public hearing on insp of facilities SCHMARTIA R Texes. State of 80/06/03 BEYERIT.K Region 4. Dallas. Office of the Director ip 22447 179 24X Fiche 30-498,84/01/11,8403010125
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list enc!

 JDRDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) B4/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22707 237 24X Fiche 50-000,84/02/28,8401190072
- 8402090007 IE Info Notice B4-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl GRACE, J N Division of GA. Safeguards & Inspection Programs (Post B30103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 327 24X Fiche 50-000.84/03/02.8402090007.

- 8402090008 IE Info Natice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000.84/03/02,8402090008
- 8402070007 IE Info Notice 84-15, "Reporting of Radiological Releases "
 Svc list encl
 JORDAN.E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02, Consolidated Edison Co of New
 York, Inc 117pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Ni) Ductility Temp " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830(03) 84/03/05 Consolidated Edison Co of New York, Inc. 117pp 22553_336 24X Fiche 50-000,84/03/05,8402090011
- 8402090024 IE Info Notice 84-09. Rev 1. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Syc list enc! JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp. 22035 049 24X Fiche 50-000,84/03/07,8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR 902070020 IE INFO NOTICE 84-10, "Etress Carrosion Cracking in PWK Bys " 8vc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 030103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000.84/03/07.8402070028
- B402090031 IE Builetin B4-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Syc list encl DEYOUNG.R.C Director's Office: Office of Inspection and Enforcement B4/03/12 Consolidated Edison Co. of New York, Inc 134pp 22823 094 24% Fiche: 50-000, 84/03/12, 8402090031
- B402090043 IE Info Notice B4-19, "Two Events Involving Unauthorized Entries into PMR Reactor Cavities" Svc list and JORDAN-E L -Division of Emergency Preparedness & Engineering Response (Post B30103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 227 24X Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84-20. "Svc Life of Relays in Safety-Related 02090044 in into motice at all .

 Sys " Svc list end;

 JORDAN, E L. Division of Empreency Preparedness & Engineering

 Geneal(dated Edison Co. of New ORDANIE Division of Empressly Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 135pp 22933 001 24X Fiche 30-000,84/03/21,8402090044

R Periodic operating reports & related correspondence

- 8403020443 Forwards monthly status rept of offsite emergency preparedness for OL reviews for Jan 1984 Changes in FEMA finding dates not caused by delay due to offsite emergency planning issues
 DIRCKS,W J Dffice of the Executive
 B4/02/21 PALLADING Commissioners
 Fiche 50-000.84/02/21.8403020443 Office of the Executive Director for Operations 22472: 083
- 5 Reportable occurrences, LERs & related correspondence
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines. Gimpel NPS-4 FET valve, to close Encl 1tr dtd 840203 sent to listed utils GE notified of affected units in BMR plants THEROUX.R R plants
 THERQUX.R R Terry Corp 84/02/22 WOODRUFF.R W Director's
 Office Office of Inspection and Enforcement App. 22704:327
 Fiche 50~000.84/02/22,8403210032
- 8403130328 Final deficiency rept re pipe stress analysis design process Initially reported on 831228 Evaluation complete Item determined not reportable per IOCFR50 55(e) DPREA, G.W. Houston Lighting & Power Co. 84/02/29 COLLINS, J T Region 4. Office of Director 3pp. 22607 245 24X Fiche 50-498,84/02/29,8403130328
- 8403130477 Final deficiency rept re reactor containment bldg post-tensioning sys tendons Initially reported on 830826 Demaged tendons will be replaced Tendons will be mfg in time frame to preclude need for long-term storage OPREA G W Houston Lighting & Power Co 84/02/29 COLLINS, J T Region 4. Office of Director 4pp. 22613 176 24X Fichs. 50-478. 84/02/29, 8403130477.
- 8403270219 Part 21 rept re broken contact carrier in control device of 7 5 kV-15 kV.500-750 MVA:5 kV 350-3,000 & all HKV circuit breakers. Initially reported on 830223 Addends to installation & maint procedures sent to affected units DVALL:, D D Brown Boveri Corp (subs of Brown Boveri & Co , Ltd) 84/03/19 Record Services Branch (Document Control Desk) 5pp 22772 114 24% Fiche 50-000,84/03/19.8403270219

T Hearing transcripts on non-antitrust matters

- 8403010125 Further response to FOIA request for IE Rept 79-19, notice of proposed imposition of civil panelties, notice of violation & order to show cause Forwards documents listed on App A FELTON, J M APP A FELTON, J. M. Division of Rules and Records, 84/01/11 H/ Shaw, Pittman, Potts & Trowbridge 2pp 22447:176 24X Fiche 50-498,84/01/11,8403010125
- --B403010139 Transcript of B00819 public meeting in Bay City, TX, Pp 1~382 Bupporting documentation encl + Commissioners B0/08/19, 382pp 22447 181 24X Fiche 50-499, 84/01/11, 8403010125

DOCKET STN-50-499 SOUTH TEXAS PROJECT, UNIT 2

- A Application/construction stage documents & correspondence
- 8403010444 Bummary of 831130-1202 Caseload Forecast Panel destings w/util at sits in Matagorda County.TX re review of const progress to obtain info for use as input to OL review schedule process.Viewgraphs encl 3 VIETTI.A. Licensing Branch 3 84/02/22 Licensing Branch 3 79pp 22449 226 24X Fiche 50-498,84/02/22,8403010444
- 8402090017 Board Notification 84-038; forwards RJ Matteon 840123 menu to DG Eisenbut providing status update of NRC actions re Westinghouse ECCB actuation logic. EISENHUT.D G Division of Licensing 84/02/27 PALLADING Commissioners 7pp 22546 007 24X Fiche 50-000,84/02/27,
- 8403280122 Summary of 840224 meeting w/Westinghouse Owners Group in Bethesda: MD re proposed Westinghouse steam generator tube rupture generic program, Attendee list & agenda encl NERBES: V Licensing Branch 3 84/03/07 Licensing Branch 3 35pp 22811 131 24X Fiche. 50-000: 84/03/07, 8403280122
- 8403300125 Forwards draft, "Mitigative Techniques & Analysis of Generic Site Conditions for Groundwater Contamination Associated w/Severe Accidents"

 KNOHTON, O W. Licensing Branch 3 84/03/15 QOLDBERO, J H. Hous Lighting & Power Co 3pp. 22841 001 24X Fiche, 50-498, 84/03/15, 8403300125 Hoveton
- F Security, medical, emergency & fire protection plans
- 8403050147 Submits scenario for submittal of info re emergency proparedness upgrade & maint necessary to ensure proper review & coordination w/all participant organizations. COLLINS, J T Region 4, Office of Director 84/02/09 OPREA, 0, W Houston Lighting & Power Co 2pp 22484, 052, 24X Fiche 50-498,84/02/09,8403050149
- 8403010544 Advises that NRC will not delete privacy or proprietary info from emergency plans unless specifically requested by licensee, per 810707 Generic Ltr 81-27 W/o request, entire plan will be placed in PDR KNICHTON.0 W Licensing Branch 3 84/02/14 OOLDBERG. J. H Houston Lighting & Power Co 4pp 22438:337 24X Fiche. 30-478,84/02/14, B003010544 Lighting & Pawer Co 8403010544

@ Adjudicatory correspondence

- 8403070117 Advises that encl final rept on condition identified in 10CFR30 35e rept was submitted on 840216 Rept concludes design basis differential settlement criteria not exceeded, M/o final rept. Certificate of Svc encl NEHMAN, J R Neuman & Holtringer * Houston Lighting & Power Co. 84/03/05 8ECHHOEFERC . LAMB, J. C., HILL, E. E. Atomic Safety and Licensing Board Panel 4pp 22541 356 24X Fiche: 50-498, 84/03/05. Licensing Board Panel 8403070117
- 8403140152 Motion for reconsideration of ASLB 830714 memorandum & order re 830330 suppl to motion for new contention Certificate of Syc enci SINKIN, L. Citizens Concerned About Nuclear Power, Inc. 84/03/08 Atomic Safety and Licensing Board Panel 18pp 22625 173, 24X Fiche 50-498,84/03/08,8403140152 84/03/08.
- 8403150039 Memorandum & order for parties not to respond to Concerned Citizens Against Nuclear Power 840308 motion for reconsideration of ABLB 830714 order re financial qualifications contention, BECHHOEFR, C Atomic Safety and Licensing Board Panel 84/03/13. BECHHOEFR, C Atomic Safety and Licensing Board Panel 84/03/13. Because Legal Director, 2pp 22643 082 24X Fiche 50-498, 84/03/13, 8403150039

- 8403150016 Partial initial Decision LBP-84-13 (Phase I) re OL Citizens Concerned About Nuclear Power 830808 motion to reopen Phase I record denied.

 BECHNOEFER.C., LAMB.J.C., HILL.E.E. Atomic Safety and Licensing Board Panel. 84/03/14 357pp 22644 001 24X

 Fiche 50-498.84/03/14.8403150016
- 840322023B Notice of change of mailing address for Judge Hill BECHHOEFER,C Atomic Safety and Licensing Board Panel DSB 060 84/03/20 Office of the Executive Legal Director ip 22719 24X Fiche 50-49B,84/03/20,840322023B 22719 039
- 3403270025 Notice of intent to appeal Partial Initial Decision 79-421-07 GL Centificate of Byc encl SINKIN.L Citizens Concerned About Nuclear Power. Inc. DBB 119. 84/05/23 2pp. 22770 071 24X Fitchs 50-498.84/03/23, 8403270025

Inspection reports: IE Bulletins & correspondence

- 403010125 Further response to FOIA request for IE Rept 79-19, notice of proposed imposition of civil penalties, notice of violation & order to show cause Forwards documents listed on 84/01/11 HA App A.
 FELTON, J H Division of Rules and Records 84/01/1
 Shaw, Pittman, Potts & Trombridge 2pp, 22447:176
 Fiche-50-498,84/01/11,8403010125 HAMLIN, J B
- -8403010132 Requests info re public hearing on insp of facilities BCHMARTZ, A.R. Teras, State of 80/06/03 SEVERIT, K. Region 4, Dallas, Office of the Director. 1p 22447:179. 24X Fichs: 50-498,84/01/11.8403010125.
- 01190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Syc list
- enci. JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22909 239. 24X Fich+ 50-000,84/02/28,8401190072
- 02090007 IE Info Notice 84-14, "Highlights of Recent Fransport Regulatory Revs by DOT & NRC " Svc list encl GRACE,J N Division of GA, Bafeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 130pp. 22352:329, 24X Fiche 30-000,84/03/02,8402090007
- 0209000B IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys /alves to Operate." Syc list encl JORDAN.E.L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/03/02 Consolydated Edison Co of New /ork, Inc 122pp 22553-078 24X Fiche 50-000.84/03/02.8402090008
-)2090009 IE Info Notice 84-15, "Reporting of Radiological Releases"
- ye list encl

 IORDAN.E.L. Division of Emergency Preparedness & Engineering

 lesponse (Post 830103) 84/03/02 Consolidated Edison Co of New

 Tork, Inc. 117pp 22553 217 24X Fiche 50-000,84/03/02,8402070009
- 2070011 IE Info Notice 84-17. "Problems W/Liquid Nitrogen Gooling amponents Below Nil Ductility Temp " Svc list encl ORDAN,E L. Division of Emergency Preparedness & Engineering espanse (Post 830103), 84/03/05 Consolidate Edison Co of New ork, Inc. 1174p. 22553 336 24X Piche 50-000,84/03/05,8402070011
- 2090024 IE Info Notice 84-09, Rev 1. "Lessons Learned From Insps of ire Protection Sefe Shutdown Sqs " Svc list encl. DROAN, E L. Division of Emergency Preparedness & Engineering exponse (Post 830103), 84/03/07. Consolidated Edison Co of New ork, Inc. 118pp. 22635 049. 24X Fiche: 50-000, 84/03/07. 8402090024
- 2090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR rs. "Byc list encl.

 RDAN.E L. Division of Emergency Preparedness & Engineering rsponse (Post 830103), 84/03/07 Consolidated Edison Co of New rs. Inc. 118pp. 22884-186 24X Fiche 50-000.84/03/07. 8402070028
- '090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in ass IE Safety Sys " Syc list encl YDUNG,R C. Director's Office, Office of Inspection and forcement 84/03/12. Consolidated Edison Co. of New York, Inc forcement 24X Fich # 50-000,84/03/12,8402090031. 22823: 074.
- 090043 IE info Notice 84-19, "Two Events Involving Unauthorized tries into PWR Reactor Cavities." Svc list encl RDAN,E.L. Division of Emergency Preparedness & Engineering aponae (Post 830103). 84/03/21 Consolidated Edison Co of New rk, Inc. 123pp. 22823:229. 24X Fiche 50-000,84/03/21,8402090043

- 8402070044 IE Info Notice 84-20, "Syc Life of Relays in Safety-Related O20YOUNG A L INFO NOTICE BG-20, "BYE LIFE OF RELAYS IN SAFETY-KELATED Sys " Syr List earch JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22733 001 24% Fiche 50-000,84/03/21,8402090044
- S Reportable occurrences. LERs & related correspondence
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines, Cimpel NPB-4 T&T valve, to close Enci ltr dtd 840203 sent to listed utils GE notified of affected units in BMR THERRUX.R R Terry Corp. 84/02/22 MOODRUFF.R W Director's Office. Office of Inspection and Enforcement Spp. 22706 327 24X Fiche. 50-000,84/02/22,8403210032.
- 8403130328 Final deficiency rept re pipe stress abalysis design process. Initially reported on 831228 Evaluation complete. Item determined not reportable per 100FR50 55(e) OPREA: 6 H Houston Lighting & Power Co 84/02/29 COLLINS, J T Region 4. Office of Director 3pp 22407 245 24X Fiche 50-498,84/02/29,8403130328
- 8403130477 final deficiency rept re reactor containment bldg post-tensioning sys tendons Initially reported on 830826 Demaged fendons will be replaced Tendons will be mfg in time frame to preclude need for long-term storage OPREA:0 W. Houston Lighting & Power Co 84/02/29 COLLINS, J T Region 4. Optice of Director 4pp 22613 176 24X Fiche: 50-498, 84/02/29, 8403130477
- 8403270219 Part 21 rept re broken contact carrier in control device of 7 5 kV-15 kV,500-750 MVA,5 kV 350-3,000 & all HKV circuit breakers Initially reported on 830223 Addenda to installation & maint procedures sent to affected units BUVALL-D D Brown Boveri Corp (subs of Brown Boveri & Co , Ltd) 84/03/19 Record Services Branch (Document Control Desk) 3pp 22772 114 24% Fiche 50-000,84/03/19,8403270219
- T Hearing transcripts on non-antitrust matters
- 8403010125 Further response to FOIA request for IE Rept 79-19, notice of proposed imposition of civil penalties, notice of violation & order to show cause Forwards documents listed on App A FÉLTON, J M Division of Rules and Records 84/01/11 H/ Bhaw, Fittman, Potts & Trombridge 2pp 22447 176 24X Fiche: 50-498, 84/01/11, 8403010125
- --8403010139 Transcript of 800819 public meeting in Bay Cith,TX Pp 1-382 Bupporting documentation encl * Commissioners 80/08/19 382pp 22447 181 24X Fiche 50-498,84/01/11,8403010125.
- DOCKET 50-500 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 2 S Reportable occurrences, LERs & related correspondence
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines Gimpel NPS-4 T&T valve to close Encl 1tr dtd 840203 sent to listed utils GE notified of affected units in BWR plants THEROUX R R THEROUX, R R Terry Corp 84/02/22 WOODRUFF, R W Director's Office of Inspection and Enforcement 5pp 22706 327. 24X Fishe: 50-000, 84/02/22, 8403210032
- DOCKET SO-501 DAVIS-BESSE NUCLEAR POWER STATION: UNIT 3 S Reportable occurrences, LERs & related correspondence
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines. Gimpel NPS-4 T&T valve, to close Encl ltr dtd 840203 sent to listed utils GE notified of affected units in BWR plants
 THERDUX.R R Terry Corp 84/02/22 MCCDRUFF.R.W Director's
 Office, Office of Inspection and Enforcement App 22704 327, 24X
 Fiche 30-000.84/02/22.8403210032
- DOCKET BIN-50-50R NPPSS NUCLEAR PROJECT, UNIT 3 A Application/construction stage documents & correspondence
- 8403010050 Third partial response to FOIA request for six categories of documents re facility Forwards App A documents App A documents also placed in FDR App B documents will be placed in FDR upon request Review continuing FELTON.J M. Division of Rules and Records 84/01/17 ANDERSON.S Garvey, Sthubert, Adams & Barer App 22446 293 24X Fiche 50-000,84/01/17,8403010050 84/01/17 ANDERSON S ! 46 293 24%

- --B003240159 Advises of refund owed licenses to CP fees for facilities based on professional manpower extended & contractual svcs costs incurred HILLER,W Q License Fee Management Branch B0/03/03 MANION,W E Office of the Controller 2pp 22446 303 24X Fiche 50-000,84/01/17,8403010050
- --8004010752 Confirms B00229 telcon re professional manpower (152-h) provided by 800228 memo Manpower should be divided equally between two units HOLLOMAY, C. J. License Fee Management Branch 80/02/29 FITTII-C. J. Atomic Safety and Licensing Board Panel ip 22446 300 24X Fiche 50-000,84/01/17,8403010050
- --8004010759 Confirms 800226 telcon re professional mangower (18-h) provided by A Rosenthal 781002 memo Manpower should be divided equally between two units HOLLEMAY.C J License Fee Management Branch 80/02/29 BIEHOP. Atomic Safety and Licensing Appeal Panel. 1p 22446 301 24X Fiche 50-000.84/01/17.8403010050 BIEHOP, J
- --8112210133 Informs of 8 McKinney opinion that allocation of ACRB manpower for fee purposes should be divided equally for review of two units at site HOLLDMAY.C J License Fee Management Branch 79/01/22 License Fee Management Branch 50-000.84/01/17.8403010050
- --B30B100483 Discusses status of DL applications Review of encl WPPBS 830712 ltr requested in order to determine present status of Unit 3 for billing purposes M/o encl HILLER:W O License Fee Management Branch 83/08/05 FONNER.R L Regulations Division 2pp 22446 326 24X Fiche 50-000. 84/01/17,8403010050
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of addi documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, S I Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000,84/02/13.8403080179
- --8003240202 Submits review costs for facilities Hearing was uncontested Billing procedure may be completed EERKOW.H N Office of Nuclear Reactor Regulation, Director 80/02/22 MILLER, W O License Fee Management Branch 1p 22583 242 24X Fiche.50-000.84/02/13.8403080179
- --8003240207 Forwards 15 cost data worksheets for facilities No costs relacted for licensee contractor vendor inspirepts COBBLL I Executive Officer for Management & Analysis 79/01/29 MILLER, W G. License Fee Management Branch 3pp 22583 243 245 Fiche 50-000, 84/02/13, 8403080179
- --B003240219 Corrects 781028 memo re WPPSS 3 & 5 being contested Memo reflecting actual ASLB time spent on case encl FITTLC V Atomic Safety and Licensing Board Panel B0/02/28 HOLLOMAY,C J License Fee Management Branch lp 22583 248 24X Fiche 50-000,84/02/13,8403080179
- -8003240222 Submits rept of time spent since program initiated on HPPSS 3 & 5 Professional time all spent on post-hearing work regarding CP hearing LAZO,R M Atomic Safety and Licensing Board Panel 78/04/11. FITTI,C J Atomic Safety and Licensing Board Panel 3pp 22583 249 24% Fiche 50-000.84/02/13,8403080179
- -8009090797 Forwards airworthiness alert re corrosive & abrasive characteristics of volcanic ash which has fallen in Pacific Northwest Questions re ash amount-chemistry & size distribution will be forwarded to licenses W/o encl JACKSON R E Grosciences Branch 80/06/12 VI Division of Engineering 2pp 22583 258 24X Fiche 50-000,84/02/13,8403080179 VOLLMER, R H
- ~8104300020 Responds to B10414 memo re util request for clarification in use of ASME code cases Util use of code cases w/o prior NRC approval is inadvisable due to potential hardship for user BOSNAX, R J Merhanical Engineering Branch 81/04/21 YOUNGBLOOD, B. J Licensing Branch 1 ip 22583 280 24X Fiche 50-000, 84/02/13, 8403080179.
- -B107270274 Accepts use of ASME Code Case N-242-1 dtd B00410 for application in const of pipe support frames in pipe chases located in two lower elevations of reactor auxiliary bidg Conditions of use discussed KNIGHT.JP Assistant Director for Comp & Structures Engineering (Fre 830201) B1/07/21 TEDESCO.R L. Assistant Director for Licensing 1p 22583 301 24X Fiche.50-000.84/02/13,8403080179

- --810811003B Notification of 810820 meeting w/util in Bathesda, MD to discuss proposed independent design review programs HERNAN, R W Licensing Branch 4 81/07/30 ADENSAM, E Q Licensing Branch 4 3pp 22883 302 24X Fiche 50-000, 84/02/13, 8403080179
- --8110080612 Discusses proposal to use IDRs in licensing process IDRs eave be useful in certain areas, but clarification of role needed, TEDESCO.R L. Assistant Director for Licensing 81/09/23 EIBENHUT, D 0 Division of Licensing ip 22583 307 24X Fiche 50-000,84/02/13,8403080179
- --8111200219 Informs of receipt of telcon from Yakamar Indian Nation requesting that tribe be given full rights in facilities requesting that tribe be given full rights in facilities proceedings
 TEDESCO.R L. Assistant Director for Licensing. 81/10/21
 KETCHEN.E Hearings Division 10 22583 310 24X
 Fiche 50~000,84/02/13,8403080179
- ---8203180118 Forwards two relevant documents for FOIA request re WPPSS & Exxon Litigation MIRAGLIA:F J Licensing Branch 3 82/03/08 WILSON,V H. Management Analysis Branch 3pp 22583:333 24X Fichs 50-000,84/02/13,8403080179
- --8204270657 Notification of 820511 meeting w/util to discuss review process & preliminary identification of any possible unique features

 WHEELER, L L Licensing Branch 3 82/04/22 MIRAGLIA, F J Licensing Branch 3 1p. 22583 340 24X Fiche 50-000,84/02/13,8403080179
- --B206300082 Lists info not yet addressed for QL application Recomments general info be accepted for dacketing LEE, I J. Licensing Branch 3 82/06/18 WHEELER, L L Licensing Branch 3 1p. 22583 347 24X Fiche 50-000 84/02/13
- --B303100475 Forwards util 830223 submittal in response to telcon during which remaining Phase I open items of "Control of Heavy Loads -- Case Reviews," were discussed W/o encl CLEMENSON.F Auxiliary Systems Branch NRC-20-18-388 83/02/28 STICKLEY, THE 60&6, Inc. 19 22583 360, 24X Fiche 50-000,84/02/13,8403080179
- --8304060577 Requests search for documents re govt litigation w/util on five specific issues
 SLAGGIE, E. Office of the General Counsel 83/03/23,
 DIRCKS,W J. Office of the Executive Director for Operations ip
 22583 361 24X Fiche: 50-000, 84/02/13, 8403080179,
- --8403080253 Forwards summary of review costs & supporting documentation from program ofcs W/o encl HOLLOWAY.C J License Fee Management Branch 80/03/03 License Fee Management Branch 80/03/03 License Fee Management Branch 1p 22583 241 24X Fiche 50-000.84/02/13, 8403080179
- 8403050288 Fifth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App A & B documents also available in PDR Documents listed on App C & D located in Central Files & not available publicly FELTON, J M Division of Rules and Records 84/02/17 ANDERSON, S I Garvey, Schubert, Adams & Barer 7pp 22501,289 24X Fiche 50-508,84/02/17,8403050288
- --7908010232 Responds to 790405 Region 5 comments re Revision 4 to NPP88-QA-004. "Operational QA Program Description " Expresses intent to request util to delete Section 3, 3, 6 entirely HAA88.W P. Quality Assurance Branch 79/05/01 BRYAN, 8.E Division of Reactor Operations Inspections 1p 22501-305 24X Fiche 50-508,84/02/17,8403050288
- --B003240207 Discusses conversation W/R McKinney of ACRS re dual unit plants Time should be cut in half HOLLOWAY, C J Diffice of Management and Program Analysis 77/01/22, Office of Management and Program Analysis ip 22501:308 24X Fiche 50-508,84/02/17,8403050888.
- --BilO190051 Responds to BiO923 FDIA Bi-378 request for GA documents for NOTION ASSESSMENT OF THE BLACK BLACK TO GA SO WPPSE All Socuments re evaluation of licenses GA programs are in PDR HAABEN, P. Quality Assurance Branch 81/10/05, WILSON, Management Analysis Dranch 2pp 22501:310 24X Fiche 50-508,84/02/17,8403050288 WILSON, V. H.
- --Bili020578 Concludes that util & principal contractors continue to meet criteria of 10CFR50 App B Revised GA program description acceptable for design & const of facilities HAABS, W P Quality Assurance Branch. 81/10/22, TEDESCO.R.L. Assistant Director for Licensing. 1p 22501 313, 24X Ficher 50-508,84/02/17,8403050288

- --8201300236 Forwards data for fee assessment re QA Branch review of WPP68-QA-004, "Operational QA Program Description" HAABS, W P Quality Assurance Branch 82/01/14 BERKOW, H N Management Analysis Branch 2pp 22501 314 24X Fiche 50-508,84/02/17.8403050288
- 8403050219 Forwards listing of board notifications issued since 820716, per 840127 inquiry re failure to provide ASLB & parties w/notifications
 DENTON.H R Office of Nuclear Reactor Regulation, Director 84/02/28 BELL,N Coalition for Safe Power, 25pp 22700 222 24x Fiche 50-460.84/02/28,8403050219
- 8403070014 Explains why two recent board notifications re environ qualification of equipment not received List of all board notifications issued since 820716 docketing of Unit I encl DENTON: HR Diffice of Nuclear Reactor Regulation, Director 84/02/28 BELL, N Coalition for Safe Power 23pp 22563 166 24X Fiche 50-460.84/02/28.8403070014
- 8403260071 Forwards seismology questions re WPPB-3 site.accepted NRC research proposal on subduction zone undertaken by U9GB & current safety evaluation of Trojan MILLER.J R Operating Reactors Branch 3 84/03/05 WITHERS,B D Portland General Electric Co 2pp 22759 300 24X Fiche 50-000.84/03/05.8403260071
- --8403260077 Forwards request for add1 info re HPPS-3 site seismology, based on review of FSAR

 JACKSON.R E Geosciences Branch 93/04/28, KNIGHTON.G W
 Licensing Branch 3 7pp 22759 302 24X Fiche 50-000, 84/03/05, 8403260071.
- 840312019? Forwards addl info re Generic Etr 82-14, in response to NRC requests W/one oversize drawing Aperture card is available in PDR.

 SORENSEN,G C Washington Public Power Supply System 84/03/07 KNIGHTON,O W Licensing Branch 3 71pp 22585 129, 24X Fiche 50-508,84/03/07,8403120199
- D. NRC Draft/Final Environmental Statements, suppls & correspondence
- 8403130178 Forwards FR notice of extension of comment period for DES (NUREO-1033) to 840312, per 840130 ltr KNIOHTDN, G W Licensing Branch 3 84/02/27 HIRSCH, A. Environmental Protection Agency 7pp. 22662 028 24X Fiche 50-508,84/02/27,8403150198
- --8402270440 Notice of extension of comment period for DES (NUREO-1033) to 840312 KNIGHTON, G W Licensing Branch 3 84/02/24 ip 22662,035 24X Fiche: 30-308,64/02/27,8403150198
- 8403090118 Forwards comments re DES (NUREG-1033) for consideration in preparation of FES SURENBEN, C C Washington Public Power Supply System 84/03/05 KNIGHTON. OW Licensing Branch 3 5pp 22576 074 24X Fiche, 50-508, 84/03/05, 8403090118
- 8403120174 Comments on facility DES DES accurately describes project conditions & impacts existing in original licensing considerations & evolving over initial const period FITCH.W.L. Hashington, State of 84/03/06 Division of Licensing. 3pp 22589 179 24X Fiche 50-508,84/03/06.8403120174
- 8403120007 Requests explanation of process by which encl svc list composed for NRC 840227 ltr to EPA re DES.
 REYNOLDS:N S Bishop, Liberman, Cook, Purcell & Reynolds REYNOLDS:N S Washington Public Power Supply System 84/03/07 KNIGHTON:O W Licensing Branch 3 2pp 22586-258 24X Fiche: 50-508.84/03/07.8403120007.
- 8403130180 Comments on DES for operation of facility Coverage of DES adequate & no objections raised to proposed action, BURD, R. 8. Environmental Protection Agency 84/03/07 Division of Licensing 1p, 22606·128 24X Ficher 50-508, 84/03/07, 8403130180
- 8403150151 Comments on facility DES Info should be segregated into generic site-specific topics & put into laymans language if essential part of format required for DES.

 LUNDBLAD, D. Washington, State of 84/03/08. KNIOHTON, Q. Licensing Branch 3. 2pp 22639:337 24X Fichs 50-508.84/03/08.8403150151
- 8403200238 Comments on DES (NUREO-1033) Assertions resocioeconomic impacts from station operation demonstrate low level of expertise among study team or refusal to consider relevant research findings on social impacts. FREUDENBURGW Washington State Univ. Pullman, WA 84/03/12. VIETTI.A Division of Licensing 2pp 22691:111 24X Fiche. 50-508.84/03/12.8403200238

- 8403220198 Comments on DES re operation of facility Cumulative impacts on regional water use should be more explicitly evaluated DES adequate. but unnecessary as decisionmaking tool DEGENS. S. Affiliation Not Assigned 84/03/13 NRC No Detailed Affiliation Given 9pp 22718 044 24X Fiche 50-508,84/03/13. B403220198
- 8403190343 Comments on DES Long-term adequacy of underdrain sys storage capacity should be discussed Evaluation of sys long-term integrity if used to retain contaminated sump water, necessary

 BLANCHARD.B Interior, Dept of 84/03/15 Division of Licensing 1p 22675 078 24X Fiche 50-508,84/03/15,8403190343
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B documents entirely withheld (ref FOIA Exemption 5) Review of addi documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, S I Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche: 50-000, 84/02/13, 8403080179
- --B103040052 Forwards short & long-term OL & CP review schedules,in response to 801216 meeting w/USOS List of OL plant reviews for which NRC tentatively plans to seek USOS assistance is provided.

 JACKSUN,R E Geosciences Branch NRC-03-80-113 81/01/21 DEVINE,JF Interior, Dept of Geological Survey 5pp 22583 272 24X Fiche 50-000,84/02/13,8403080179
- 8403260071 Forwards seismology questions re WPPS+3 site, accepted NRC research proposal on subduction zone undertaken by USGS & current safety evaluation of Trojan MILLER.J R Operating Reactors Branch 3 84/03/05 WITHERB.B D Portland General Electric Co. 2pp 22759 300 24X Fiche 50-000, 84/03/05 8403260071
- --8403260083 Forwards draft SER input re WPP8-3 site geology & seismology Open items include possibility of large earthquake on subduction rone beneath site & possibility of unrecognized low angle thrust faults in site vicinity KNICHT.J P Assistant Director for Comp & Btructures Engineering (Post 830201) 83/11/01 NDVAK.T M Assistant Director for Licensing 18pp. 22759 311 24X Fiche 50-000.84/03/03, 8403260071
- F Security, medical, emergency & fire protection plans
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document naturely withheld (ref FOIA Exemption 5) Review of addl documents subj to request continuing FELTON. J M Division of Rules and Records 84/02/13 ANDERSON, S I Garvey. Schubert. Adams & Barer 7pp 22583 226 24X Fiche 50-000, 84/02/13.8403080179
- --8110190026 Requests that comparison of fire protection program to App R of 10CFR50 be included in overall fire protection program submittal W/o encl FR notice EIBENHUT, D G Division of Licensing 81/09/30 FERGUSON, R L Washington Public Power Supply System 2pp 22583 308 24X Fiche 50-000,84/02/13,8403080179
- 840301050B Advises that NRC will not delete privacy or proprietary info from emergency plans unless specifically requested by ticensee-per 810709 Generic Ltr Bi-27 W/o request, entire plan will be placed in PDR KNIGHTON. O W Licensing Branch 3 84/02/14 MAZUR, D W Washington Public Power Supply 89xtem, 3pp 22438 332 24X Fichs: 50-508, 84/02/14, 8403010508
- 8403130385 Forwards responses to NRC questions re security measures for physical protection of facilities using SNN Info withheld (ref 100FR73 21)
 SORENSEN. 0 C Washington Public Power Supply System 84/03/07 KNIOHTON. 0 H. Licensing Branch 3 1p 22616 091 24X Fiche 50-508.84/03/07.8403130385
- Q Adjudicatory correspondence
- B403010050 Third partial response to FOIA request for six categories of documents re facility Forwards App A documents. App A documents also placed in PDR. App B documents will be placed in PDR upon request Review continuing FELTON, J. M Division of Rules and Records 84/01/17 ANDERSON, S I Garvy, Schobert, Adams & Barer App 22446 293, 24X Fiche 50-000,84/01/17,8403010050

- --8304050552 Requests search for relevant documents re govt litigation w/util Response due by 830408 GRIMSLEV. D H 188C No Datailed Affiliation Given 83/03/29 FITTI. C Atomic Safety and Licensing Board Panel 1p 22446 314 24X Fiche 50-000.84/01/17.8403010050
- 3403060111 Memorandum & order ruling on further suppl to petition for leave to intervene & reinstating 830421 ruling MARGULIES.M B , SHON.F J , FOSTER.R F Atomic Safety and Licensing Board Panel 84/03/02 Coalition for Safe Power lipp 22518 311 24X Fiche 50-508.84/03/02.8403060111
- 3403210170 Notice of appeal of ASLB 840302 memorandum & order admitting Cualition for Safe Power as intervenor Certificate of Svc encl HARTMAN, S. L. Washington Public Power Supply System HARTMAN, S. L. Bishop, Liberman, Cock, Purcell & Reynolds DSB 003 84/03/20 Atomic Safety and Licensing Board Panel 3pp 22707 358 24X Fiche 50-508,84/03/20.8403210170
- 3403210172 Brief in support of notice of appeal of ASLB 830302 memorandum & order ASLB abused discretion by reinstating order granting petitioner intervenor status ASLB 830302 memorandum & order should be vacated W/Certificate of Svc HARTMAN. S i. Washington Public Power Supply System HARTMAN, S i. Bishop, Liberman, Cook, Purcell & Reynolds DSB 002 84/03/20 Atomic Safety and Licensing Appeal Panel 23pp 22710 324 24x Fiche 50-508.84/03/20 8403210172
- 3403210189 Motion for reconsideration of memorandum & order granting petitioner intervenor status E/or for referral or certification of question of whether limitation should be placed on petitioner participation W/Certificate of Svc HARTMAN.S L. Hashington Public Power Supply System HARTMAN.S L. Bishop, Libernan, Cook, Purcell & Reynolds DSD 001 84/03/20 Atomic Safety and Licensing Board Panel 23pp 22710 266 24% Fiche 50-508.84/03/20.8403210189
- 1 Inspection reports, 1E Bulletins & correspondence
- 3403080179 Fourth partial response to FOIA request for six categories of documents re Facilities Forwards App A documents App B document entirely withheld (ref FDIA Exemption 5) Review of add documents sub) to request continuing FELTON.J M Division of Rules and Records 84/02/13 ANDERSON.S I Garvey Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000.84/02/13.8403080179
- -8106220066 Requests that appropriate comments re Cycle 2 evaluations, per Eisenhut 810604 memo, be submitted by 810623 MIRAGLIA-F J Licensing Branch 3 81/06/18 HAASS.W 6 Quality Assurance Branch 1p 22583 291 24% Fiche 50-000, 84/02/13, 8403080179
- ~Bi07i305B1 Forwards info re impact of Mount St Helens eruptions on facilities, for use by SALP review board Comments prepared by HE Lefevre, geologist JACKSON, R E Geosciences Branch Bi/06/23 MIRAQLIA, F J Licensing Branch 3 2pp 225B3 293 24X Fiche 50-000, 84/02/13, 8407080179
- --BI07140185 Forwards Ofc of Nuclear Reactor Regulation performance evaluation in compliance w/BI0604 memo re systematic assessment of licensee performance Cycle 2 Notifies that review board meeting for facility scheduled for BI0723 MMEDLER.L Licensing Branch 3 BI/06/30 EISENHUT.D 0 Division of Licensing 1p 22583 295 24X Fiche 50-000.84/02/13, B403080179
- --8107140192 Forwards Geosciences Branch input for use by facility systematic assessment of licensee performance review board, per 810618 request JACKSDN:R E Geosciences Branch 81/06/23 MIRAGLIA.F J Licensing Branch 3 3pp 22583 278 24X Fiche 50-000,84/02/13,8403080179
- 3401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list enci JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc. 115pp 22909 239 24X Fithe 50-000,84/02/28,8401190072
- 8402090007 IE info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list enc] GRACE, JN Division of GA. Safeguards & Inspection Programs (Post B30103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 327 24X Fiche 50-000,84/03/02,8402090007

- 8402090008 IE Info Natice B4-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of Naw
 York. Inc. 122pp 22553 078 24X Fiche 50-000, 84/03/02, 8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases" Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New Yurk, Inc. 119pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidate Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402090011
- 8402090024 IE Info Notice 84-09, Rev i. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN, Et. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York Inc 118pp 22635 049 24X Fiche 50-000.84/03/07, 8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PHR Sys " Syc list and JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22584-186 24X Fichs 50-000,84/03/07,8402090028
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl DEYOUNG.R C Director's Office of Inspection and DEYOUNG.R C Director's Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000,84/03/12,8402090031
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Bvc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc 123pp 22823 227 24X Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc list ene! JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 135pp 22933 001 24X Fiche 50-000.84/03/21,8402090044
- S Reportable occurrences, LERs & related correspondence
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines. Gimpel NPS-4 T&T valve, to close Encl 1tr dtd 840203 sent to listed utils QE notified of affected units in BMR plants
 THERDUX,R R Terry Corp 84/02/22 WOODRUFF,R W Director's Office, Office of Inspection and Enforcement 6pp 22706 327 24X Fichs 50-000.84/02/22.8403210032
- T Hearing transcripts on non-antitrust matters
- 8403010113 Final response to FDIA request for five categories of infore mothballed nuclear const projects Forwards App A documents Documents also in PDR. FELTON. J M Division of Rules and Records 84/02/10 BELL.N Nuclear Information & Resource Service 2pp 22479-182 24X Fichs 50-508.84/02/10.8403010113
- --8403010114 Partial statement of JB Martin before House Committee on Energy & Commerce re mothballing of facility. MARTIN,J B NRC - No Detailed Affiliation Given 83/09/14 9pp. 22479 186 24X Fichs 50-508,84/02/10,8403010113
- U Congressional/Executive Correspondence
- B403080179 Fourth partial response to FOIA request for six categories of documents re facilities. Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of addl documents subj to request continuing FELTON, J M Division of Rules and Records B4/02/13 ANDERSON, 8 I Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000, 84/02/13, 8403080179
- --8009110203 Responds to 800702 itr re E Borhek concern about ultimate responsibility for civil penalities proposed against util. Civil penalities are imposed as enforcement action State agencies should be contacted re responsibility for payment DIRCKS.W J Office of the Executive Director for Operations. 80/08/26 JACKBON, H M Benate 4pp 22583.260 24X Fiche 50-000,84/02/13,8403080179

- --B012160531 Forwards B00625 ltr from constituent E Borhek for response Requests that duplicate rept be forwarded to B02 United States Courthouse, Soattle, NA 78104 JACKSON.H M Senete, Energy & Natural Resources B0/07/21 KAMMERER, C C Office of Congressional Affairs 2pp 22583 264 24X Fiche 30-000, 84/02/13, 8403080179
- --B101130363 Responds to 1tr forwarding M Hamilton concerns re facilities CPs issued in Apr 1978 after safety & environ reviews & ABLB public hearings Public hearings may be requested when util applies for OLs KAMMERER.C Office of Congressional Affairs B0/12/16 MAGNUSON, W Senate 1p 22583 271 24x Fiche 50-000, 84/02/13, 8407880179
- DOCKET STN-50-509 WPPSS NUCLEAR PROJECT, UNIT 5
- A Application/construction stage documents & correspondence
- 8403010050 Third partial response to FOIA request for six categories of documents re facility Forwards App A documents App A documents along A documents along the face of the following the face of t
- --8003240159 Advises of refund owed licensee re CP fees for facilities based on professional manpower extended & contractual sycs costs incurred MILLER, W O License Fee Management Branch 80/03/03 MANION, W C Office of the Controller 2pp 22446 303 24X Fiche 50-000, 84/01/17, 8403010030
- --B004010752 Confirms 800229 teleon re professional manpower (152-h) provided by 800228 memo Manpower should be divided equally between two units HOLLOMAY.C J License Fee Management Branch 80/02/29 FITTI.C J Atomic Safety and Licensing Board Panel 1p 22446 300 24% Fiche 50-000.84/01/17,8403010050
- --8004010759 Confirms 800226 telcon re professional manpower (18-h) provided by A Rosenthal 781002 memo Manpower should be divided equally between two units HOLLOMAY.C J License Fee Management Branch 80/02/29 BISHOP.J Atomic Safety and Licensing Appeal Panel. 1p 22446 301 24x Fiche 50-000,84/01/17,8403010050
- --8112210135 Informs of B McKinney opinion that allocation of ACRS manpower for fee purposes should be divided equally for review of two units at site HOLLOWAY, C J License fee Management Branch 79/01/22 License fee Management Branch 79/01/22 License fee Management Branch 1p 22446 297 24% Fiche 50-000,84/01/17,8403010050
- --8308100483 Discusses status of OL applications Review of encl HPPSS 830712 itr requested in order to determine present status of Unit 3 for billing purposes W/o encl MILLER,W O License Head Management Branch 83/08/05 FONNER,R L Regulations Division 2pp 22446 326 24% Fiche 50-000, 84/01/17,8403010050
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities: Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5). Review of add1 documents subj to request continuing FELTON. J M Division of Rules and Records 84/02/13 ANDERSON, 5 I Darvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche: 50-000, 84/02/13, 8403080179
- --8003240202 Bubmits review costs for facilities Hearing was uncontested, Billing procedure may be completed BERKOW,H N Office of Nuclear Reactor Regulation, Director 80/02/22 MILLER,W O License Fee Management Branch ip 22583; 242 24X Fichs 50-000,84/02/13,8403080179
- --8003240207 Forwards IE cost data worksheets for facilities No costs relected for licensee contractor vendor insp repts COBB, L I Executive Officer for Management & Analysis. 79/01/29 HILLER.W O License Fee Management Branch 3pp. 22583 243 24) Fiche 50-000,84/02/13,8403080179
- --8003240219 Corrects 781028 memo re MPPSB 3 & 5 being contested Memo reflecting actual ASLB time spent on case encl FITTI.C V Atomic Bafety and Licensing Board Panel 80/02/28 HOLLOWAY.C J License Fee Management Branch ip 22583:248 24: Fiche 50-000,84/02/13,8403080179.

- --8003240222 Submits rept of time spent since program initiated on WPPSS
 3 & 5 Professional time all spent on post-hearing work
 regarding CP hearing
 LAZO,R M Atomic Safety and Licensing Board Panel 78/04/11
 FITTI.C J Atomic Safety and Licensing Board Panel 3pp
 22583 249 24X Fiche 50-000,84/02/13,8403080179
- --B009090737 Forwards airworthiness alert re corrosive & abrasive characteristics of volcanic ash which has fallen in Pacific Northwest Questions re ash amount chemistry & size distribution will be forwarded to licenses W/o encl JACKBON, R E Geosciences Branch 80/06/12 VOLLMER, R H Division of Engineering 2pp 22583 258 24X Ficha 50-000, 84/02/13, 8403080179
- --8104300020 Responds to 810414 memo re util request for clarification in use of ASME code cases Util use of code cases w/o prior NRC approval is inadvisable due to potential hardship for user BOSNAK,R J Mcchanical Engineering Branch 81/04/21 YOUNOBLOOD.B J Licensing Branch 1 1p 22883 280 24X Fiche 50-000,84/02/13,8403080379
- --8107270274 Accepts use of ABME Code Case N-24R-1 dtd 800410 for application in const of pipe support frames in pipe chases located in two lower elevations of reactor auxiliary bldg Conditions of use discussed KNIGHT.JP Assistant Director for Comp & Structures Engineering (Pre 830201) B1/07/21 TEDESCO.R L Assistant Director for Licensing ip 22583 301 24X Fiche 50-000,84/02/13.8403080179
- --8108116038 Notification of 810820 meeting w/util in Bethesda, MD to discuss proposed independent design review programs. HERNAN, R W Licensing Branch 4 81/07/30 ADENSAM, E Q Licensing Branch 4 3pp 22583 302 24X Fiche 50-000, 84/02/13, 8403080179
- ---Bi10080612 Discusses proposal to use IDRs in licensing process IDRs may be useful in certain areas, but clarification of role needed TEDCBCO.R L Assistant Director for Licensing 81/09/23 EISENHUT, D @ Division of Licensing ip 22583 307 24X Fiche 50-000,84/02/13,8403080179
- ~-8111200219 Informs of receipt of telcon from Yakamar Indian Nation requesting that tribe be given full rights in facilities proceedings TEDESCO.R.I. Assistant Director for Licensing 81/10/21 KETCHEN,E Hearings Division 1p 22583 310 24X Fiche 50-000.84/02/13.8403080179
- --B2031B011B Forwards two relevant documents for FOIA request re WPPSS & Exxon Litigation MIRAGLIA,F J Litensing Branch 3 82/03/08 WILSON,V H Management Analysis Branch 3pp 22583 333 24x Fiche 50-000,84/02/13,8403080179
- ~~8204290.657 Notification of 820511 meeting w/util to discuss review process & preliminary identification of any possible unique features
 WHEELER, L. Licensing Branch 3 82/04/22 MIRAQLIA, F. J. Licensing Branch 3 1p 22583 340 24X Fiche 50-000, 84/02/13, 8403080179
- --B303100476 Forwards util B30223 submittal in response to telcon during which remaining Phase I open items of "Control of Heavy Loads Case Reviews." were discussed W/o encl CLEMENBON.F Auxiliary Systems Branch NRC-20-18-388 83/02/28 STICKLEY.T H. E00G. Inc ip 22583 360 24X Fiche 50-000.84/02/13,8403080179
- --8304060577 Requests search for documents re govt litigation w/util on five specific issues SLAGOIE.E L Office of the General Counsel 83/03/23 DIRCKS.W J Office of the Elecutive Director for Operations 19 22583 361 24X Fiche 50-000.84/02/13.8403080179
- --8403080253 Forwards summary of review costs & supporting documentation from program ofcs W/o encl HOLLOWAY: O J License Fee Management Branch 80/03/03 License Fee Management Branch ip 22583 241 24X Fiche 50-000,84/02/13, 8403080179
- 8403050288 Fifth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App A & B documents also available in PDR Documents listed on App C & D located in Central Files & not available publicly FELTON, J, M Division of Rules and Records. 84/02/17 ANDERSON, S I Garvey, Schubert, Adams & Barer 9pp 22501 289 24X Fiche 50-509,84/02/17.8403030288

- --7908010102 Forwards 770501 Haas-Bryan memo re NRR-GAB resolution of Region 5 comments re operational GA program NOLAN.F J Division of Reactor Operations Inspections 79/05/07 CREWS-J L Region 4. Dallas, Office of the Director 1p 22501 306 24X Fiche 50-509.84/02/17.840305028B
- --7908010232 Responds to 770405 Region 5 comments re Revision 4 to NPRSS-GA-CO4, "Operational GA Program Description "
 Expresses intent to request util to delete Section 3 3 6 entirely
 HAASS: W P Quality Assurance Branch 79/05/01 BRYAN, 8 E
 Division of Reactor Operations Inspections 1p 22501 305 24X
 Fiche 50-508,84/02/17,8403050288
- --8003240207 Discusses conversation w/R McKinney of ACRS re dual unit plants Time should be cut in half HOLLOWAY.C J Office of Management and Program Analysis 79/01/22 Office of Management and Program Analysis 1p 22001 308 24X Fiche 50-500.84/02/17.8403030288
- --8110170051 Responds to 810923 FUIA 81-378 request for QA documents for WPPSS All documents re evaluation of licensee QA programs are in PDR HAASS.W P Quality Assurance Branch 81/10/05 WILSON.V H Management Analysis Branch 2pp 22501 310 24% Fiche 50-508.84/02/17.8403050288
- ~-Biil020375 Concludes that util & principal contractors continue to meet criteria of 10CFR50 App B Revised GA program description acceptable for design & const of facilities HAABS.W P Quality Assurance Branch 81/10/22 TEDESCO, R L Assistant Director for Licensing 1p 22501 313 24X Fiche 50-308,84/02/17.8403030288
- --B201300236 Forwards data for fee assessment re QA Branch review of WPPSS-GA-004, "Operational QA Program Description" HAASB,W P Quality Assurance Branch 82/01/14 BERKOW.H N Management Analysis Branch 2pp 22501 314 24% Fiche 30-508,84/02/17.8403050288
- 8403120199 Forwards add1 info re Generic Ltr 82-14, in response to NRC requests W/one oversize drawing Aperture card is available in PDR SORENSEN.G C Washington Public Power Supply System 84/03/07 KNIGHTON.O W Licensing Branch 3 71pp 22585 127 24X Fiche 50-508.84/03/07.8403120199
- B403260221 Advises that Phase II of termination program in progress re locating new owners for facility & will last until at least June 1985 SOREMBEN & C. Washington Public Power Supply System 84/03/13 DIRCKS W J. Office of the Executive Director for Operations in 22751 032 24X Fiche 50-509.84/03/13.8403260221
- F Security, medical, emergency & fire protection plans
- 8403080177 Fourth partial response to FBIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FDIA Exemption 5) Review of addi documents subj to request continuing FELTON. J M Division of Rules and Records 84/02/13 ANDERSON, 9 i Garvey, Schubert, Adams & Barer 7pp 22983 226 24X Fiche 50-000.84/02/13.8403080179
- --9110190026 Requests that comparison of fire protection gragmam to App R of 10CFR50 be included in overall fire protection program submittal W/o encl FR notice EISENHUT.D G Division of Licensing 81/09/30, FEROUSON.R L Washington Public Power Supply System 2pp 22583 308 24X Fiche 50-000,84/02/13,8403080179

G Adjudicatory correspondence

- 8403010050 Third partial response to FOIA request for six categories of documents re facility Forwards App A documents App A documents also placed in FDR App B documents will be placed in FDR upon request Review continuing FELTON.J M Division of Rules and Records 84/01/17 ANDERSON.S I Garvey, Schubert, Adams & Barver 4pp. 22446 293 24X Fiche.50-000.84/01/17.8403010050
- --B305090506 Requests advice re fee assessment cutoff date for reactor CP & QL applications that are withdrawn, denied, suspended, cancelled or postponed MILLER.W Q License Fee Management Branch 83/05/04 FONNER,R L Office of the Erecutive Legal Director 3pp 22446 315 24X Fiche 50-000.84/01/17.8403010050

@ Inspection reports, IE Bulletins & correspondence

- 8403080179 Fourth partial response to FOIA request for six catagories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of addl documents sub; to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, B, I Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000.84/02/13.8403080179
- --8106220066 Requests that appropriate comments re Cycle 2 evaluations, per Eisenhut 810604 memo, be submitted by 810623 MIRAGLIA, F. J. Licensing Branch 3 81/06/18 HAASS, W.S. Quality Assurance Branch 1p 82583 291 24% Fiche 50-000, 84/02/13, 840380179
- --Bi07130381 Forwards info re impact of Mount Bt Helens eruptions on facilities, for use by BALP review board. Comments prepared by HE Lefevre, goologist JACKSON, R E Geostismes Branch. Bi/06/23 MIRAGLIA, F J Litensing Branch 3 2pp 22583 293 24X Fiche. 50-000, 84/02/13, 8403080179
- ---8107140188 Forwards Ofc of Nuclear Reactor Regulation performance evaluation in compliance w/810604 memo re systematic assessment of licensee performance Cycle 2 Notifies that review board meeting for facility scheduled for 810728, WHEELER, L. Licensing Branch 3 81/06/30 E18ENNUT.D.Q. Division of Licensing 1p 22583 275 24X Fiche.50-000,84/02/13,8403080179
- --8107140192 Forwards Geosciences Branch input for use by facility systematic assessment of licenses performance review board, per 610618 request.

 JACKSON.R E Geosciences Branch 81/06/23 MIRAQLIA,F J, Licensing Branch 3 3pp 22583,278 24% Fichs 50-000,84/02/13,8403080179
- 8 Reportable occurrences, LERs & related correspondence
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines, Oimpel NP8-4 T&T valve to close Encl 1tr dtd 840203 sent to listed utils GE notified of affected units in BHR plants
 THEROUX, R R Terry Corp 84/02/22 WOODRUFF, R. W Director's Office, Office of Inspection and Enforcement App 22706-327. 24X Fiche. 50-000, 84/02/22, 8403210032

U Congressional/Executive Correspondence

- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B documents mitirally withheld (ref FOIA Exemption 5) Review of add1 documents subj to request continuing FELTON, J K Division of Rules and Records 84/02/13 ANDERSON, S I Garvey, Schubent, Adams & Barer 7pp 22583 226 24X Fiche 50-000,84/02/13,8403080179
- --B009110203 Responds to B00702 ltr re E Borhek concern about ultimate responsibility for civil penalities proposed against util Civil penalities are imposed as enforcement action State agencies should be contacted re responsibility for payment, DIRCKG, W J Office of the Executive Director for Operations, 80/08/26 JACKBON.H M Benate 4pp 22583 260 24X fiche 50-000,84/02/13,8403080179.
- ---B012160551 Forwards B00625 ltr from constituent E Borbek for response Requests that duplicate rept be forwarded to B02 United Btates Courthouse Beattle, MA 78104. JACKBON, M M Benate, Energy & Natural Resources B0/07/21 KAMMERER, C C Office of Congressional Affairs. 2pp. 22583:264 24X Fiche 50-000.84/02/13,8403080179
- --B10130363 Responds to 1tr forwarding M Hamilton concerns re facilities CPs issued in Apr 1978 after safety & environ reviews & ABLB public hearings Public hearings may be requested when util applies for OLs. KAMMERER, C Office of Congressional Affairs B0/12/16 MAGNUSUN.W Benate ip 22583 271 24X Fiche, 50-000, 84/02/13, 8403080179

- DOCKET 50-513 WPPSS NUCLEAR PROJECT, UNIT 4
- A Application/construction stage documents & correspondence
- B40:3010050 Third partial response to FOIA request for six categories of documents re facility Forwards App A documents App A documents also placed in PDR App B documents will be placed in PDR upon request Review continuing FELTON. J M Division of Rules and Records 84/01/17 ANDERSON. S I Garvey. Schubert. Adams & Barer 4pp 22446 273 24X Fiche 50-000.84/01/17.8403010050
- --8302250083 Responds to questions re application termination Notice of termination/withdrawal not anticipated No time limitation placed on completion of Phase One review ADENSAM, E. G. Licensing Branch 4. 83/02/17 MILLER, W. G. License Fee Management Branch ip 22446 321 24X Fiche 50-000,84/01/17,8403010050
- --8308100483 Discusses status of DL applications Review of encl WPP68 830712 ltr requested in order to determine present status of Unit 3 for billing purposes, W/o encl MILLER, W O License Fee Management Branch 83/08/05 FONNER, R L Regulations Division 2pp 22446 326 24X Fiche 50-000, 84/01/17,8403010050
- B4030B0179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of addl documents subj to request continuing.
 FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, S I Garvey, Schubert, Adams & Barer. 7pp 22583 226 24X
 Fiche. 50-000, 84/02/13, 8403080179
- --B001140316 Notifies that NRC has amended regulations re implementation of resident insp program Expresses gratitude for assistance rendered Forwards final rule W/o encl
 STELLO, V Office of Inspection & Enforcement, Office of the Director 79/11/19 O'STRANDAN Washington Public Power Supply System, ip 22583 234 24x Fiche 50-000,84/02/13,8403080179
- --8009090737 Forwards airworthiness alert re corrusive & abrasive characteristics of volcanic ash which has fallen in Pacific Northwest Questions re ash amount chemistry & size distribution will be forwarded to licensees \(\mathcal{W}\)/0 encl JACKBON.R E Geosciences Branch 80/06/12 VOLLMER.R H Division of Engineering 2pp. 22583 258 24X Fiche 50-000,84/02/13,8403080179
- ---B010090260 Discusses review of applicant 800814 request for approval of proposal to substitute in-plant tests w/scale model recirculation sump tests Response to requests deferred panding NRC review of program 8PEIS.T Reactor Systems Branch 80/09/26 YUUN3BLOOD, 8 J Licensing Branch 1 ip 22583 266 24X Fiche 50-000,84/02/13,840380179
- --8104220327 Concludes that Table 3.2-2 of PBAR.re safety-related structures, sys & components, is incomplete from Geotechnical Engineering Branch viewpoint LEAR.G E Hydrologic & Geotechnical Engineering Branch 81/04/08 MA688.W P Guality Assurance Branch 2pp 22583:278 24X Fiche 50-000,84/02/13,8403080179
- --Bi04300020 Responds to Bi0414 memo re util request for clarification in use of ASME code cases Util use of code cases w/o prior NRC approval is inadvisable due to potential hardship for user BOBNAK.R J Mechanical Engineering Branch B1/04/21 YOUNGBLOOD,B J Licensing Branch i p 22583 280 24X Fiche 50-000,84/02/13,8403080179
- --8105010554 Advises that Mechanical Engineering Branch completed review of util request for authorization to use ASME Code Cases N-217 & N-287 for application in design of concrete containments Code cases acceptable KN10HT.J.P. Assistant Director for Comp & Structures Engineering (Fre B30201) 81/04/29. TEDESCO.R.L. Assistant Director for Licensing 1p 22583 281 24X Fiche 50-000.84/02/13,8403080179
- ---8105140106 Advises that info provided on 810213 & 0403 re air intake arrangements for diesel generators reviewed Diesel generator combustion air supply arrangement meets acceptance criteria in Bettion II of SRP a 5 8 Sys acceptable as designed.

 UNDARO, A R Power Systems Branch 81/05/01 YOUNGBLOUD, 8 J
 Licensing Branch 1 1p 22583: 282. 24X Fiche, 50-000, 84/02/13, 8403080179
- --8105180436 Forwards ltr from util requesting concurrence by NRC to omit Subsections 2 5 1-2.5 3 of FSAR. Review & comments requested by BIO622

 ADENBAM.E. 0 Assistant Director for Licensing 81/05/12.

 JACKSON.R E Decsciences Branch. ip 22583 283 24X
 Fiche. 50-000, 84/02/13, 8403080179

- --8105210109 Concurs w/licensee proposal to ref Sections 2 5 1-2 5 1-2 5 3 of MPPS-2 FSAR in MPPS-1/4 FSAR since both projects located in clase proximity Mods listed JACKSON R E Geosciences Branch 81/05/15 ADENSAM E 0 Licensing Branch 4 2pp 22383 286 24X Fiche 50-000, 84/02/13, 8403080179
- --B107280171 Notification of B10727 meeting w/util & 18W in Bethesda, MD to discuss method util intends to use to fulfill requirments of NUREG-0737 Item II F 2 (inadequate core cooling instrumentation)
 HERNAN, R W Licensing Branch 4 81/07/21 ADENSAM, E 9
 Licensing Branch 4 2pp 22583 305 24X Fiche 50-000, 84/02/13, 8403080179
- --Bi08110038 Notification of 810820 meeting w/util in Bethesda.MD to discuss proposed independent design review programs HERNAN.R W Licensing Branch 4 81/07/30 ADENSAM,E 0 Licensing Branch 4 3pp 22583 302 24X Fiche 50~000,84/02/13,8403080179
- --8110080612 Discusses proposal to use IDRs in licensing process IDRs may be useful in certain areas, but clarification of role needed TEDESCO.R L. Assistant Director for Licensing 81/09/23 EISENHUT.D 0 Division of Licensing 1p 22583 307 24X Fiche 50-000,84/02/13-8403080179
- --Bill060677 Notifies of util intention of sending technical team to present FSAR to review staff during wk of Bill30 Reviewers should complete attached form & confirm attendance HERNANAR W Licensing Branch 4 81/10/23 Licensing Branch 4 4pp 22583 311 24X Fiche 50-000.84/02/13,8403080179
- --Biiii30007 Submits names of D Gupa & G Stalley as technical reviewers for facility FSAR per Bii023 memo LEAR.O Hydrologic & Geotechnical Engineering Branch Bi/10/30 ADENSAM.E Licensing Branch 4 ip 22583 315 24X Fiche 50-000.84/02/13.8403080179
- --8111200217 Informs of receipt of telcon from Yakamar Indian Nation requesting that tribe be given full rights in facilities proceedings
 TEDEBCD.R t. Assistant Director for Licensing 81/10/21
 KETCHEN.E Hearings Division ip 22883 310 24X
 Fiche 50-000.84/02/13.8403080177
- --Bi12300305 Notification of Bi1211 meeting w/util in Bethesda.MD to discuss FBAR w/technical review staff at time OL application is tendered HERNAN.R W Licensing Branch 4 Bi/11/23 ADEMSAM.E 0 Licensing Branch 4 3pp 22583 318 24X Fiche 50-000.84/02/13-8403080179
- --8212070382 Ack receipt of 821109 ltr re Target Rock environ qualification testing program Info re valve upgrade & retest anticipated. HEISHMAN R F Division of Reactor Programs (Pre 830103) 82/12/01 BOUCHEY. OD Washington Public Power Supply System 1p. 22583 357 24X Fithe 50-000,84/02/13.8403080179
- --8304060577 Requests search for documents re govt litigation w/util on five specific issues SLAGOIE.E L Office of the General Counsel 83/03/23 DIRCKS.H J Office of the Executive Director for Operations 1p 22583 361 24X Fiche 50~000.84/02/13.8403080179
- 840305028B Fifth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App A & B documents also available in PDR Documents listed on App C & D located in Central Files & not available publicly FELTON, J M Division of Rules and Records 84/02/17 ANDERSON, 8 I Garvey, Schubert, Adams & Barer Ppp 22501 289 24X Fiche. 50-509, 84/02/17, 8403050288
- --7908010232 Responds to 790405 Region 5 comments re Revision 4 to NPP85-0A-004, "Operational QA Program Description "
 Expresses intent to request util to delete Section 3 3 6 entirely HAASS.WP Quality Assurance Branch 79/05/01 BRYAN, 8 E Division of Reactor Operations Inspections 1p 22501 305 24X Fiche 50-513.84/02/17.8403050288
- --8110190051 Responds to 810923 FOIA 81-378 request for GA documents for WPPSS All documents re evaluation of licensee GA programs are in FDR HAABB.W P Quality Assurance Branch 81/10/05 WILSON.V H Management Analysis Granch 2pp 22501 310 24X Fiche 50-513.84/02/17.8403050288

- --Bilo2i03i6 Informs of receipt of Bouchey/Adensam Bi0722 ltr containing util current OA program description for design & const of facilities OA program description acceptable
 HAASS, W P Quality Assurance Branch 81/10/14 TEDESCO.R L
 Assistant Director for Licensing ip 22501 312 24%
 Fiche 50-460.84/02/17.840303028B
- --B201300236 Forwards data for fee assessment re GA Branch review of WPPSS-GA-004. "Operational GA Program Description " HAASS.W P Guality Assurance Branch B2/01/14 BERKOW.H N Hanagement Analysis Branch 2pp 22501 314 24X Fiche 50-513.84/02/17.8403050288
- 8403260221 Advises that Phase II of termination program in progress relicating new owners for facility & will last until at least June 1785
 SORENSEN, G C Washington Public Power Supply System 84/03/13
 DIRCKS.W J Office of the Executive Director for Operations ip 22751 032 24x Fiche 50-509.84/03/13.8403260221
- C Utility Environmental Report (ER), amends & correspondence
- 8403080179 Fourth partial response to FDIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 3) Review of add1 documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, S I Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000,84/02/13,8403080179
- --8202260171 Requests assistance in performing acceptance review of environ rept for OL application Only portions applicable to Unit 1 need be considered since Unit 4 cancelled on 820122 ADENSAM, E 0 Licensing Branch 4 82/02/10 JACKSON, R E 0eosciences Branch 1p 22583 324 24X Fiche 50-000,84/02/13,840380179
- --B203150028 Forwards addl info requirements for review of ER for OL application per 820210 request
 BALLARD.R L Environmental Engineering Branch 82/03/02
 ADENSAM.E G Licensing Branch 4 3pp 22583 329 24X
 Fichs 50-000.84/02/13.8403380179
- --8203180004 Advises that environ rept is acceptable re radialogical impacts
 HUBSTON/R W Assistant Director for Radiation Protection
 B2/03/02 TEDESCO.R L Assistant Director for Licensing 1p
 22583 332 24% Fiche 50-000.84/02/13.8403080179
- ~-8204090099 Informs that sufficient info provided to begin meteorology review [nappropriate models & diffusion parameters used in Section 6 1 2 & accident evaluations HULMAN.L Q Accident Evaluation Branch 82/03/16 ADENSAM.E Licensing Branch 4 2pp 22583 336 24X Fiche 30-000.84/02/13, 8403080179
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of addl documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, S I Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000.84/02/13.8403080179
- --8003250477 Forwards hydrologic engineering questions re proposed waste treatment sys Response will supply necessary info re design basis for seepage & flooding Also forwards generic questions re floodplains Info will assist NRC environ review SELLS,D E Environmental Projects Branch 2 B0/03/07 RENBERGER,D L Washington Public Power Supply System Spp 22583-253 24X Fiche 50~000,84/02/13,8403080179
- --B003270142 Discusses suspension of facility preoperational aquatic monitoring program Suspension approved Operational monitoring program results should not be affected by suspension BAMMORTH.R B Environmental Specialists Branch 80/02/29 BELLS DE Environmental Projects Branch 2 2pp 22583 239 24X Fiche 50-000.84/02/13.8403080179
- NRC Safety Evaluation Report (SER), suppls & correspondence
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B documents matirely withheld (ref FOIA Exemption 5) Review of add1 documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, S I Garvey, Schubent, Adams & Barer 7pp 22583 226 24X Fiche. 50-000, 84/02/13, 8403080179

- --8103040052 Forwards short % long-term OL & CP review schedules, in response to 801216 meeting w/V865 List of OL plant reviews for which NRC tentatively plans to seek U808 assistance is provided JACKBUN, R E Geosciences Branch NRC-03-80-113 81/01/21 DEVINC. J F Interior, Dept of, Geological Survey 5pp 22583 272 24X Fiche 50-000,84/02/13,8403080179
- --Bilii20935 Forwards form which identifies Power Sys Branch electrical & methanical reviewers for project in accordance w/Bil023 memo Requests established review schedule dates when available UNGARO, A Power Systems Branch Bi/11/02 HERNAN, R W Licensing Branch 4 2pp 22583 316 24X Fiche 30-000.84/02/i3.8403080179
- F Security, medical, emergency & fire protection plans
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B documents metrely withheld (ref FOIA Exemption 5) Review of add1 documents sub, to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, S I Oarvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000, 84/02/13.8403080179
- --B201190297 Forwards Central Files version of "Description of Early Narning Sys for HPPSS Nuclear Plants 1,2 & 4," in response to NRC 810720 ltr re prompt notification in event of emergency Sys will be in place prior to OL issuance BOUCHEV, O D Hashington Public Power Supply System 82/01/11 TEDESCO, R L Assistant Director for Licensing 1p 22593 321 24X Fiche 50-000,04/02/13.8403080179
- --8202180454 Requests that Fire Protection Section perform acceptance level review of facilities' revised fire protection program prior to docketing of OL application Util aware that App R to IOCFR50 will apply ADENBAM, E. G. Licensing Branch 4 82/01/27 BENARGYA. V. Chemical Engineering Branch 1p 22583 322 24X Fiche 50-000,84/02/13,8403080179
- --8205070088 Forwards list of sys to be added to Q-list 8ys provides angoing knowledge of changes in radiation environ & ability to deal effectively w/unusually high radiation & radioactivity levels
 CONSEL.F J. Radiological Assessment Branch 82/03/23 HAASS,WP Quality Assurance Branch 2PP 22583 338 24X
 Fichs 50-000,84/02/13.8403080179
- --8208120240 Forwards Central Files version of revised page to Revision 2 of emergency plan adding local fire depts within 20 miles of facility to backup fire protection svcs
 BOUCHEY, O D Washington Public Power Supply System 82/08/05
 SCHWENCER, A Licensing Branch 2 2pp 22583 348 24X
 Fiche 50-000,84/02/13,8403080179
- --8208120248 Central Files version of revised page to Revision 2 of emergency plan re provision of backup fire protection svcs * Washington Public Power Supply Bystem 82/06/05 ip 22583 350 24X Fiche 50-000.84/02/13.8403080179
- --8203020139 Advises that listed info needed to perform acceptance review of fire protection program for conformance w/NUREG-0800, Section 9 5-1

 BENAROYA,V Chemical Engineering Branch 82/02/09 ADENSAM,E Q Licensing Branch 4 1p 22583 323 24% Fiche 50-000,84/02/13,8403080179
- 8403050288 Fifth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App A & B documents also available in PUR Documents listed on App C & D located in Central Files & not available publicly FELTON.J M Division of Rules and Records 84/02/17, ANDERSON.8 I Garvey. Schubent. Adams & Barer 9pp 22501 289 24% Fichs 50-513.84/02/17.8403050288
- --7906190142 Approves GA fire protection program description & related commitments HAASS,WP Quality Assurance Branch 79/05/10 PARR,O D Light Water Reactors Branch 3 ip 22501 309 24X Fiche 50-460.84/02/17.8403050288
- G Adjudicatory correspondence
- 8403010050 Third partial response to FOIA request for six categories of documents re facility Forwards App A documents App A documents also placed in PDR App B documents will be placed in PDR upon request Review continuing FELTON.J M Division of Rules and Records 84/01/17 ANDERSON.8 1 Garvey. Schubert, Adams & Barer 4pp 22446 273 24X Fiche 50-000,84/01/17.8403010050

- --8304060552 Requests search for relevant documents re govt litigation w/util Response due by 830408
 GRIMSLEY, D.H. NRC No Detailed Affiliation Given 83/03/29
 FITTI.C. Atomic Safety and Licensing Board Panel 1p 22446 314
 24X Fiche 50-000,84/01/17,8403010050
- --8305090506 Requests advice re fee assessment cutoff date for reactor CP & OL applications that are withdrawn denied syspended, cancelled or postponed
 MILLER, H D License Fee Management Branch 83/05/04 FONNER, R L
 Office of the Executive Legal Director 3pp 22446 315 24X
 Fiche 50-000,84/01/17,8403010050

G Inspection reports, IE Bulletins & correspondence

- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of add1 documents subj to request continuing FELTON.J M Division of Rules and Records 84/02/13 ANDERSON,9 I Garvey, Schubert, Adams & Barer 7pp 22583 224 24X Fiche 50-000,84/02/13.8403080179
- --8209280165 Forwards Cycle 3 systematic appraisal of licensee performance input for 810701 through 820730 in response to Region 5 820625 request Strong mgt evident Resolution of technical issues:responsiveness & staffing satisfactory, HERNAN:R W Licensing Branch 4 82/09/15 EISEN-NUT.D 0 Division of Licensing App. 22383 351 24X Fiche 50-000, 84/02/13:8403080179

8. Reportable occurrences: LERs & related correspondence

- B403010451 Informs Commission of problems w/emergency diesel generators még by Transamerica Delaval.Inc DERCKE.W J Office of the Executive Director for Operations BECY-83-034, 84/01/25 4pp 22438.347 24X Fiche 50-000.84/01/25.8403010451
- 8403080179 Fourth pertial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of addl documents subj to request continuing FELTON.J M Division of Rules and Records 84/02/13 ANDERSON, S 1 Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000,84/02/13,8403080179
- --B203100417 Discusses Part 21 rept re UE&C design of structural steel at facility Generic implications appear to be nonexistent since no similar design concept used at other facilities Two oversite drawings encl Aperture cards in Central Files SHEWMAKER, R E. Division of Engineering & Quality Assurance (Pre B30103) B2/02/24 DRDMERICK, A W Division of Engineering & Quality Assurance (Pre B30103) 2pp 22583 325 24X Fiche 50-000,84/02/13,8403080179
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines, Ginpel NPB-4 T&T valve, to close Encl ltr dtd 840203 sent to listed utils GE notified of affected units in BWR plants
 THERDUX: R Yerry Corp. 84/02/22 WOODRUFF, R W Director's Office, Office of Inspection and Enforcement opp 22706 327 24X Fiche 50-000, 84/02/22, 8403210032
- 8403270219 Part 21 rept re broken contact carrier in control device of 7 5 kV-15 kV,500-750 MVA.5 kV 350-3.000 & all HKV circuit breakers Initially reported on 830223 Addenda to installation & maint procedures sent to affected units DUVALL,D D Brown Boveri Corp (subs of Brown Boveri & Co , Ltd) 84/03/19 Record Services Branch (Document Control Desk) 5pp 22772-114 24X Fiche 50-000.84/03/19.8403270219

U. Congressional/Executive Correspondence

- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document antirely withheld (ref FOIA Exemption 5) Review of add1 documents sub; to request continuing FELTON, J M. Division of Rules and Records 84/02/13 ANDERSON, S I Garvey, Schubert, Adams & Bapart. 7pp 22583 226 24X Fiche: 50-000, 84/02/13, 8403080179.
- --B007110203 Responds to B00702 ltr re E Borhek concern about ultimate responsibility for civil penalities proposed against util. Civil penalities are imposed as enforcement action State agencies should be contacted re responsibility for payment DIRCKS,W J. Office of the Executive Director for Operations-B0/08/26. JACKSON.H M. Senate 4pp 22583-260 24X Fiche. 30-000, 84/02/13, 8403080179

- --8012160351 Forwards 800625 ltr from constituent E Borhok for response Requests that duplicate rept be forwarded to 802 United States Courthouse. Seattle. WA 98104 JACKSON.H M Senate, Energy & Natural Resources 80/07/21 KATMERER.C C Office of Congressional Affairs 2pp 22583 264 24X Fiche 50-000.84/02/13.8403080179
- DOCKET 50-514 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of addl documents subj to request continuing FELTON. J M Division of Rules and Records 84/02/13 ANDERSON, 9 I Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000, 84/02/13, 8403080179
- --8009090737 Forwards airworthiness alert re corrosive & abrasive characteristics of volcanic ash which has fallen in Pacific Northwest Ovestions re ash amount, chemistry & size distribution will be forwarded to licensees M/o encl JACKGON, R E Geosciences Branch BO/O6/12 VOLLMER, R H Division of Engineering 2pp 2558 258 24X Fiche 50-000,84/02/13,8403080179
- --8102200029 Forwards action plan for resolution of non-TMI issues for panding CP/mfg license applications, per Ofc of Nuclear Reactor Regulation approach to resumption of licensing Safety evaluation inputs should be provided by 810601 EIBENHUT, D O Division of Licensing 80/12/31 VOLLMER, R Division of Engineering ip 22583 277 24X Fiche 50-000,84/02/13,8403080179
- E NRC Bafety Evaluation Report (SER), supple & correspondence
- 8403080179 Fourth partial response to FDIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FDIA Exemption 9) Review of addl documents subj to request continuing FELTON. J M Division of Rules and Records 84/02/13 ANDERSON, 9 I Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fichs 50-000.84/02/13,8403080179
- --Bi03040052 Forwards Short & long-term DL & CP review schedules in response to 801216 meeting w/USGS List of DL plant reviews for which NRC tentatively plans to seek USGS assistance is provided JACKSON:R E Quesciences Branch NRC-03-80-113 81/01/21 DEVINE.J F Interior. Dept of, Geological Survey 5pp 22583 272 24X Fiche 50-000,84/02/13,8403080179

DOCKET 50-515 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 2

- A Application/construction stage documents & correspondence
- 8403080179 Fourth partial response to FOIA request for six categories of dacuments re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of addi documents subj to request continuing FELTON.JM Division of Rules and Records 84/02/13 ANDERSON.S I Garvey, Schubert, Adams & Barer 7pp 22383 226 24X Fiche 50-000,84/02/13,8403080179
- --8009090737 Forwards airworthiness alert re corrosive & abrasive characteristics of volcanic ash which has fallen in Pacific Northwest Guestions re ash amount chemistry & size distribution will be forwarded to licenses. Wo encl JACKSON.R E. Geosciences Branch 80/06/12 VOLLMER.R. H Division of Engineering 2pp 22583 258 24X Fiche 50-000.84/02/13.8403080179
- --Bi02209029 Forwards action plan for resolution of non-TMI issues for pending CP/mfg license applications.per Ofc of Nuclear Reactor Regulation approach to resumption of licensing Safety evaluation inputs should be provided by 8100601 EISENHUT.D G Division of Licensing 80/12/31 VOLLMER,R Division of Engineering 1p. 22583 277 24X Fiche 50-000.84/02/13.8403080179
- E NAC Safety Evaluation Report (SER), suppls & correspondence
- 8403080179 Fourth partial response to FOIA request for six categories of documents me facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of add1 documents sub; to request continuing FELTON. J M Division of Rules and Records 84/02/13 ANDERSON. S 1 Garvay, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000.84/02/13.8403080179

--Bi03040052 Forwards short & long-term OL & CP review schedules, in response to B01216 meeting w/USQS List of OL plant reviews for which NRC tentatively plans to seek USQS assistance is provided JACKSUM R E Geosciences Branch NRC-03-80-113 B1/01/21 DEVINE. J F Interior, Dept of, Geological Survey 5pp 22583 272 24X Fiche 50-000, B4/02/13, B4030880179

DOCKET STN-50-518 HARTSVILLE NUCLEAR PLANT, UNIT 1

- S Reportable occurrences. LERs & related correspondence
- 840301045i Informs Commission of problems w/emergency diesel generators mfg by Transamerica Delaval. Inc DIRCKS.W J Office of the Executive Director for Operations SECY-83-034 84/01/25 4pp 22438 347 24X Fiche 50-000.84/01/25.8403010451
- 8403120105 First interim deficiency meptine loose drive hubs on overspeed governor drive shaft on Transamerica Delaval, Inc diesels initially reported on 840203 Svc info memo being reviewed for approval Also reportable per Part 21 MILLS, L. M. Tennessee Valley Authority 84/03/01 G'REILLY, J. P. Region 2, Office of Director 2pp 22585 229 24X Fiche 50-000.84/03/01.8403120105
- 8403230028 Followup Part 21 rept re nuclear valve/actuator stroking time possibly lengthened beyond 15 s when using hydrocarbon-based lubricants Ltrs to affected utils encl WILSON.A K Henry Pratt Co 84/03/08 KEPPLER J O Region 3, Office of Director App 22739 30A 24X Fiche 50-000.84/03/08, 8403230028
- B400270219 Part 21 rept re broken contact carrier in control device of 7 % kV-15 kV, 500-750 MVA, 5 kV 350-3,000 & all HKV circuit breakers Initially reported on 830223 Addenda to installation & maint procedures sent to affected units DUVALL, D D Brown Boveri Corp (subs of Brown Boveri & Co. Ltd.) B4/03/19 Record Services Branch (Ducument Control Desk.) 5pp 22772 114 24X Fiche 50-000,84/03/19,8403270219

DOCKET STN-50-519 HARTSVILLE NUCLEAR PLANT, UNIT 2

8403090060 Advises that time for Commission to review ALAB-760 expired Commission declined review Decision became final agency action on 840307 CHILK.5 J Office of the Secretary of the Commission 84/03/08 Atomic Safety and Licensing Appeal Panel 1p 22576 050 24X Fiche 50-519,84/03/08.8403070060

- S Reportable occurrences, LERs & related correspondence
- 8403310451 Informs Commission of problems w/emergency diesel generators mfg by Transamerica Delaval.Inc DIRCKS.W J Office of the Executive Director for Operations SECY-83-034 84/01/25 4pp 22438 347 24X Fiche 50-000,84/01/25,8403010451
- 8403120105 First interim deficiency rept re luose drive hubs on overspeed governor drive shaft on Transamerica Delaval, Inc diesels Initially reported on 840203 Svc info momo being reviewed for approval Aiso reportable per Part 21.
 MILLS, L.M. Tennessee Valley Authority 84/03/01 0'REILLY, J.P. Region 2, Office of Director 2pp 22585 227 24X
 Fiche 50-000.84/03/01.8403120105
- 840323002B Followup Part 21 rept re nuclear valve/actuator stroking time possibly lengthened beyond 15 s when using hydrocarbon-based lubricants Ltrs to affected utilis encl MILSON, A K Henry Pratt Co 84/03/08 KEPPLER, J 0 Region 3, Office of Director App 22730 306 24% Fiche 50-000,84/03/08,840323002B
- 8403270219 Part 21 rept re broken contact carrier in control device of 7 % kV-15 kV.500-750 MVA.5 kV 350-3.000 & all MKV circuit breakers Initially reported on B30223 Addenda to installation & maint procedures sent to affected units DUVALL.D D Brown Boveri Corp (subs of Brown Boveri & Co. Ltd.) 84/03/19 Record Services Branch (Document Control Desk) 5pp 22772 114 24X Fiche 50-000,84/03/19.8403270219

- DOCKET STN-50-520 HARTSVILLE NUCLEAR PLANT, UNIT 3
- 8 Reportable occurrences. LERs & related correspondence
- 8403010451 Informs Commission of problems w/emergency diesel generators mfg by Transamerica Delaval Inc DIRCKS, W Office of the Executive Director for Operations SECY-83-034 84/01/25 4pp 22438 347 24X Fiche 50-000,84/01/25,8603010451
- 8403230028 Followup Part 21 rept re nuclear valve/actuator stroking time possibly lengthened beyond 15 s when using hydrocarbon-based lubricants Ltrs to affected utils encl WILSON.A K Henry Pratt Co 84/03/08 KEPPLER.J. G Region 3. Office of Director App 22730 306 24X Fiche 50-000.84/03/08, 88032028
- 8403270219 Part 21 rept re broken contact carrier in control device of 7 5 kV-15 kV, 500-750 MVA.5 kV 350-3.000 & all HKV circuit breakers Initially reported on 830223 Addenda to installation & maint procedures sent to affected units DUVALL.D D Brown Boveri Corp (subs of Brown Boveri & Co , Ltd } 84003/19 Record Services Branch (Document Control Desk) 5pp 22772 114 24X Fiche 50-000.84/03/19.8403270219

DOCKET STN-50-521 HARTSVILLE NUCLEAR PLANT, UNIT 4

- O Adjudicatory correspondence
- 8403090060 Advises that time for Commission to review ALAB-760 expired Commission declined review Decision became final agency action on 840307 CHILK:8 J Office of the Secretary of the Commission 84/03/08 Atomic Safety and Licensing Appeal Panel ip 22576 090 24% Fiche 50-519,84/03/08,8403090060
- 5 Reportable occurrences. LERs & related correspondence
- B403010451 Informs Commission of problems w/emergency diesel generators mfg by Transamerica Delaval, Inc DIRCKS, W J Office of the Executive Director for Operations SECY-03-034 B4/01/25 4pp 22438 347 24X Fiche 50-000,84/01/25,8403010451
- 8403230028 Followup Part 21 rept re nuclear valve/actuator stroking time possibly lengthened beyond 15 s when using hydrocarbon-based lubricants Ltrs to affected utils encl WILSON, A K Henry Pratt Co 84/03/08 KEPPLER, J G Region 3, Office of Director 6pp 22730 306 24X Fiche 50-000,84/03/08,8403330028
- B403270219 Part 21 rept re broken contact carrier in control device of 7 5 kV-15 kV, 500-750 MVA, B kV 350-3, 000 & all HKV circuit breakers Initially reported on B30223 Addenda to installation & maint procedures sent to affected units DUVALL, D D Brown Boveri Corp (subs of Brown Boveri & Co , Ltd) 84/03/19 Record Services Branch (Document Control Desk) 5pp 22772 114 24X Firhe 50-000, 84/03/19, 8403270219

DDCKET 50-522 SKAGIT NUCLEAR POWER PROJECT, UNIT 1

- A Application/construction stage documents & correspondence
- 8403080179 Fourth partial response to FOIA request for six categories of documents me facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of addi documents subj to request continuing FELTON.J M Division of Rujes and Records 84/02/13 ANDERSON.8 I Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000.84/02/13.8403080179.
- --8009090737 Forwards airworthiness alert re corrosive & abrasive characteristics of volcanic ash which has fallen in Pacific Northwast Questions re ash amount, chemistry & size distribution will be forwarded to licensees W/o encl JACKSON, R E Geosciences Branch 80/06/12 VOLLMER, R H Division of Engineering 2pp 22583 258 24X Fiche. 50-000, 84/02/13, 8403080179
- --BiO2200029 Forwards action plan for resolution of non-TMI issues for pending CP/mfg license applications.per Ofc of Nuclear Reactor Regulation approach to resumption of licensing Safety evaluation inputs should be provided by BiO601 EISENHUT.D @ Division of Licensing BO/12/31 VQLLMER.R Division of Engineering 1p. 22583 277 24X Fiche 50-000.B4/02/13.B4030B0179

- E NRC Bafety Evaluation Report (SER), suppls & correspondence
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 3) Review of add1 documents subj to request continuing FELTON.J M Division of Rules and Records 84/02/13 ANDERSON.S I Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000.84/02/13.8403080179
- --B103040052 Forwards short & long-term OL & CP review schedules, in response to 801216 meeting w/USOS List of OL plant reviews for which NRC tentatively plans to seek USOS assistance is provided JACKBON.R E Geosciences Branch NRC-03-80-113 B1/01/21 DEVINE.J F Interior, Dept of, Geological Survey 5pp 22583 272 24X Fiche 50-000,84/02/13,8403080179
- 9 Inspection reports. IE Bulletins & correspondence
- B401170072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York: Inc 115pp 22909 237 24X Fiche 50-000,84/02/28,8401170072
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE.J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24% Fiche 50-000.84/03/02,8402090007
- 8402070000 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000,84/03/02,8402070008
- 8402090009 IE Info Notice 84-15. "Reporting of Radiological Releases"
 Svc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc (19pp 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8402090011 IE Info Notice 84-i7, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co. of New York, Inc. 117pp 22953 334 24% Fiche 50-000.84/03/09.8402090011
- B402070024 IE Info Notice 84-09. Rev i. "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Past 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24% Fichs 50-000.84/03/07.8402070024
- 8402070028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Bys." Svc list encl UNRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402070028
- 8402070031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Syc list encl DEYQUNG.R C Director's Office of Inspection and Enforcement B4/03/12 Consolidated Edison Co of New York, Inc 134pp. 22823 074 24X Fiche 50-000.84/03/12.8402070031
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" 8vc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York, Inc. 123pp. 22823 229. 24X Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of New York Inc 135pp. 22933 001. 24X Fiche.50-000:84/03/21,8402090044

- DOCKET 50-523 SKAOIT NUCLEAR POWER PROJECT, UNIT 2
- A Application/construction stage documents & correspondence
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 3) Review of addi documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, S ! Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50~000.84/02/13.8403080179
- --8009090737 Forwards arrworthiness alert re corrosive & abrasive characteristics of volcanic ask which has fallen in Pacific Northwest Questions re ask amount, chemistry & size distribution will be forwarded to licensees W/o encl JACKSON, R E. Geosciences Beanch. 80/06/12 VGLLMER.R H. Division of Engineering. 2pp. 22583-238-24X. Fichs 50-000.84/02/13,8403080179
- ~-8102200029 Forwards action plan for resolution of non-TMI issues for pending CP/mfg license applications per Ofc of Nuclear Reactor Regulation approach to resumption of licensing Safety evaluation inputs should be provided by #10601 EISENHUT.D 0 Division of Licensing 80/12/31 VOLLMER.R Division of Engineering ip 22583 277 24X Fiche 50-000.84/02/13.8403080179
- E NRC Safety Evaluation Report (SER), supply & correspondence
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of addl documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, S I Garvey, Schubert, Adams & Barer 7pp 22583 224 24X Fiche 30-000.84/02/13.8403080179
- --8103040052 Forwards short & long-term DL & CP review schedules, in response to 801216 meeting w/USGS List of OL plant reviews for which NRC tentatively plans to seek USGS assistance is provided JACKSON, R E Obosciences Branch NRC-03-80-113 81/01/21 DEVINE, J F Interior, Dept of, Geological Survey 3pp 22583 272 24X Fiche 50-000,84/02/13-8403080179
- O Inspection reports: IE Bulletins % correspondence
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svt list encl UDRDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/20 Consolidated Edison Co of New York, Inc 115pp 22909 239 24X Fiche 50-000,84/02/28,8401190075
- 8402070007 IÆ Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE, J M Division of OA. Bafeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 327 24% Fiche 50-000.84/03/02,8402070007
- 8402070008 IE Info Notice 84-14. "Failure of Automatic Sprinkler Bys Valves to Operate" Svr list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of New York, Inc. 122pp 22553 078 24X Fiche 50-000,84/03/02,84020900008
- B402090009 IE Info Notice 84-15, "Reporting of Radiological Releases Byc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 119pp 22553 217 24X Fithe 50-000.84/03/02,8402090009
- 8402090011 IE Info Notice 84-17. "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Syc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103), 84/03/05 Consolidate Edison Co. of New York, Inc. 117pp 22553 336 24X Fiche 50-000.84/03/05,8402090011
- B402090024 IE Info Notice 84-09, Rev 1, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 30-000,84/03/07,8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Sys "Syc list and! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830163) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 186 24X Ficke 50-000,84/03/07,8402090028

- 8402070031 IE Bulletin 84-02. 'Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list ent!
 DEYOUNG:R C Director's Office. Office of Inspection and
 Enforcement B4/03/12 Consolidated Edison Co of New York. Inc
 134pp 22823 094 24x Fiche 50-000.84/03/12.8402070031
- 8402090043 IE Info Notice 84-19. "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list end! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Fost 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24% Fiche 50-000,84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc list enci JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc. 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044
- DOCKET STN-50-528 PALG VERDE NUCLEAR STATION: UNIT 1
- A Application/construction stage documents & correspondence
- 8403080390 Responds to FDIA request for 27 documents referenced in 1975 EIS re facilities & similiar environ documents Forwards App A Documents 1-10 Documents 11 & 12 available at NTIS FELTON, J M Division of Rules and Records 84/02/13 RYAN, J A Stratch, Cang. Weeks & Cardon 2pp 22581 180 24X Fiche 50-528,84/02/13,8403080390
- --8403080407 "Groundwater Conditions of Lower Hassayampa-Centennial A)ea, Maricopa County, AZ " Related info encl * Harshbarger & Associates R-700-74-2 74/06/30 83pp 22581 217 24X Fiche 50-528,84/02/13,8403080370
- B403060451 Forwards request for additinfo re open environ qualification of electrical equipment items for facility KNIGHTON.G W. Licensing Branch 3 B4/02/27 VAN BRUNT,E E Arizona Public Service Co. 5pp. 22550 007 24X Fiche 50-528.84/02/27,8403060451
- 8403010212 Forwards response to 840206 telcon re draft rev to FSAR Section 3A 10 concerning low preheat fillet welding Low preheat poses no concern principally due to low hardenability of base matis

 VAN BRUNT.E E Arizona Public Service Co 94/02/28 KNIGHTON.G Licensking Branch 3 4pp 22435 279 24x Fiche 50-328.84/02/28.8403010212
- 8403280043 Notification of 840320 meeting w/util & C-E in Bathesda, MD to discuss proposed testing program to demonstrate adequacy of mods to RCS pumps, thermowells, thermal sleeves & control element assembly shrouds
 LICITRALE A Licensing Branch 3 84/02/27 KNIOHTON, G W
 Licensing Branch 3 3pp 22812 361 24x Fiche 50-528,84/02/29,8402280043
- 8403090130 Advises that proposed leak rate acceptance criteria for Tech Spec limiting conditions for operation unacceptable since criteria less restrictive than 1 gpm leak rate imposed on near-term OLs KNIOHTON, 0 W Licensing Branch 3 64/03/01 VAN BRUNT, E Arizona Public Service Ca 2pp 22592 301 24X Fiche 50-528,84/03/01,8403090130
- 8403150094 Forwards outstanding item list for PDR List also submitted to util JOHKSON,P H Ragion 5, Office of Director 84/03/08 ALEXANDER,I Ragion 5, Office of Director 14pp 22641 190 24X Fiche 50-528-84/03/08.8403150094
- 8402070041 Board Notification 84-050 provides Commission policy statement & proposed rulemaking on environ qualifications EISENHUT, D 0 Division of Licensing 84/03/14 Atomic Safety and Licensing Board Panel 10pg 24% Ficha 50-000,84/03/14,8402090041
- 8403160048 Forwards updated preliminary description (Rev 1) for RCS demonstration test
 VAN DRUNT, E E , RODERS, A C Arizona Public Service Co 84/03/14 KNICHTON, Ø Licensing Branch 3 2pp 22659 169 24X Fiche: 50-528, 84/03/14, 8403160048
- --8403160052 Rev 1 to "RCS Demonstration Test"

 * Arizona Public Service Co 84/02/29 8pp 22659 171 24X
 Fiche 50-528,84/03/14,8403160048
- B403160065 Notifies that add1 info & schedule re electrical equipment environ qualification program will be submitted by B40326, per B40227 request VAN BRUNT, E E Arizona Public Service Co 84/03/14 KNIGHTON, G Licensing Branch 3 lp 22652 326 24% Fiche 50-528, B4/03/14, B403160065

- 8403270236 Forwards operations experience base, consisting of experience tables for presently licensed personnel Inadequate number of personnel meet 6-wk hot participation experience requirement VAN BRUNT.E E Arizona Public Service Co 84/03/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 17pp 22800 236 24% Fiche 50-528,84/03/23,8403270236
- C Utility Environmental Report (ER), amends & correspondence
- 8403080370 Responds to FOIA request for 27 documents referenced in 1975 EIS refacilities & similiar environ documents Forwards App A Documents 1-10 Documents 11 & 12 available at NTIS FELTON.J M Division of Rules and Records 84/02/13 RYAN.J A Streich Lang, Weeks & Cardon 2pp 22581 180 24X Fichs 50-528,84/02/13.8403080370
- --8403080400 Discusses review of environ rept re transmission lines crossing Indian reservations Tribal council consent should be obtained for right-of-way before environ rept published Related info encl > Interior, Dept of, Bureau of Indian Affairs 74/12/11 REGAN.W H Atomic Energy Commission - Deputy Director for Reactor Projects 5pp 22581 184 24X Fiche 50-528.84/02/13.8403080390
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- 8403080385 FDIA request for 27 documents referenced in 1975 EIS refacilities & similiar environ documents List & news articles enc!

 RYAN, J A Streich, Lang, Weeks & Cardon 84/01/17 Office of Administration 9pp 22381 J71 24X Fiche 50-528,84/01/17, ABO/3080388
- 8403080390 Responds to FOIA request for 27 documents referenced in 1975 EIS refacilities & similiar environ documents Forwards App A Documents 1-10 Documents 11 & 12 available at NTIB FELTON. J M Division of Rules and Records 84/02/13 RYAN, J A Streich, Lang, Weeks & Cardon 2pp 22581 180 24% Fiche 50-528,84/02/13,8403080390
- --B10B270490 Submits Geosciences Branch DEG input Updated summary of geology & seismology section FSAR will be included in BER JACKBUN R E Geosciences Branch Si/OB/14 MIRAOLIA, F Licensing Branch 3 2pp. 22581 182 24X Fiche 50-528, B4/02/13, B403080390
- --8403080406 Comment on DES, per 750414 request Statement somewhat blased toward project More detailed maps of pipeline & transmission line corridors should be provided in final statement, DUREMUS, 8 D Interior, Dept of 75/07/23 REGAN Division of Reactor Licensing (NRR-1975 only) 27pp 22581 189 24X Fiche 50-328,84/02/13.8403080390
- 8403290341 Responds to FOIA request for records re facility Ltr d#d 840117 failed to meet critoris for waiver of reproduction costs Forwards App A documents Address of Phoenix LPDR listed FELTON.J M Division of Rules and Records 84/02/27 RYAN,J A Streich. Lang, Weeks & Cardon 3pp 22815 018 24X Fiche 50-528.84/02/27,8403290341
- --8403270344 DRAFT ENVIRONMENTAL STATEMENT RELATED TO CONSTRUCTION OF PALO VERDE NUCLEAR GENERATING STATION, UNITS 1.2 & 3 Docket Nos 50-328, 80-329 & 30-330 * Office of Nuclear Reactor Regulation, Director NUREG-75/022 75/04/30 175pp 22815 301 24X Fiche 50-528,84/02/27,8403290341
- E NRC Safety Evaluation Report (SER), supple & correspondence
- B403020005 Forwards info requested in SSER 5 (NUREC-0857) re tests performed for C-E on load limiting devices in reactor vessel lower key horizontal supports
 VAN BRUNT,E E Arizona Public Service Co 84/02/10 KNIGHTUN,G Licensing Branch 3 9pp 22442 201 24X Fiche 50-528;84/02/10.8403020005
- 8403090012 Forwards "High Pressure Safety Injection Pump," mechanical environ qualification rept, per SSER 5 (NUREO-0857)
 VAN BRUNT, E E Arizona Public Service Co B4/02/29 KNIGHTON, O W Licensing Branch 3 2pp 22568.001 24X Fiche 50-528.84/02/27, 8403090012
- --8403090014 "High Pressure Safety Injection Pump:" mechanical environ qualification rept HALLER.R E Bechtel Corp V-PAK-4B1 84/01/12. 198pp 22368 004 24X Fiche 50-328,84/02/29,8403090012

- F Security, medical, emergency & fire protection plans
- 8403080145 Forwards IE Insp Rept 50-528/84-01 on 840116-20 No violations or deficiencies noted NORDERHAUO.L R Region 5. Office of Director 84/02/13 VAN BRUNT.E E Arizona Public Service Co 2pp 22559 132 24X Fiche 50-528
- --8403080152 IE Insp Rept 50-528/84-01 on 840116-20 No violations or deficiencies noted Major areas inspected followup of open items identified during insp on 830411-22 & observation of 830511 emergency preparedness exercise FISH.R F. TEMPLE.O M. SCHUBTER.H D. Region 5, Office of Director 84/02/09 12pp 22559 154 24X Fiche 50-528,84/02/13.8403080145
- 8403260014 Requests removal of App F & Q from Rev 2 to Emergency Plan Implementing Procedure 7, per Generic Ltr 81-27 & GW Knighton 840214 ltr informing that util must request withholding of private or unlisted telephone numbers VAN BRUNT, E E Arizona Public Service Co 84/03/19 KNIGHTON, O W Licensing Branch 3 2pp 22750 258 24X Fiche 50-528,84/03/19,8403260014
- Q Inspection reports, IE Bulletins & correspondence
- B402140014 FOIA request for records re NRC const assessment team (CAT) insp at facilities
 BERMABEILL Government Accountability Project B3/10/07 Office of Administration 2pp 22254 001 24X Fiche 50-528,83/10/07,8402140014
- 840214001B Responds to FOIA request for records re NRC const assessment team (CAT) insp at facilities Forwards App A documents
 Documents also in PDR App B documents listed for review to
 identify specific interest
 FELTON.J M Division of Rules and Records 83/12/20 GARDE, B P
 Government Accountability Project 18pp 22254 003 24X
 Fiche 50-528,83/12/20,8402140018
- --B402140022 Bummarizes civil insp items. Bechtel 830929 ltr re reinsp of nuclear pipe hangers (Q class) & related info encl VORDERBRUEGGEN Region 5, Office of Director 83/09/19 NARBUT, P NRC - No Detailed Affiliation Given 60pp 22254 021 24X Fichs 50-528, B3/12/20, B402140018
- --B402140026 "Insp Plan " Draft outline given to inspectors on 830906 encl.
 * NRC No Detailed Affiliation Given 83/12/20 12pp 22254 081 24X Fiche 50-528,83/12/20,8402140018
- --8402140028 Provides add1 info re 830930 exit interview meeting w/const assessment team, for preliminary roview of findings NRC criteria utilized during insp more applicable to operating plant Related info encl WODDS, TO Anizona Public Service Co 83/10/12 MARTIN, J B Region 5. Office of Director 339pp 22254.320 24X Fiche 50-528.83/12/20,8402140018
- --8402140031 Comments on review of draft writeup on NDE Rewrite requested Related info encl NARBUT.P NRC - No Detailed Affiliation Given 83/09/27 KERCH.H NRC - No Detailed Affiliation Given 41pp 22254 09/ 24X Fiche 50-528
- --8402140032 Summary of B30916 exit status mesting w/NRC const appraisal team re 830907-16 insp
 IDE:W E Arizona Public Service Co 83/09/19 ROEDEL, J A Arizona Public Service Co 6pp 22254 137 24X
 Fichs. 50-528, 83/12/20, 8402140018
- --8402140036 Forwards marked-up draft insp scope & objectives Related info encl ALBERT. W. G Region 5, Office of Director 83/09/21 YDUNO, T Region 5, Office of Director 18pp 22254 143 24X Fiche 50-528,83/12/20,8402140018
- --8402140037 Corrective action request re piping cleanliness, per Procedure WPP/GCI 204 O, Rev 2, "Piping Sys Release for Insulation." Related info encl QAITHER.C F Arizona Public Service Co. 83/09/13 23pp 22255 299 24X Fiche 50-528,83/12/20.84021400i8
- --B40214003B Forwards feeder rept rs insp activities at facility. Combined insp of concrete expansion anchor bolts & embedded plates will be written by L Vorderbruegen Radiographs reviewed will be included in H Kerch rept Related info snc! WALTON.0 A. Region i. Office of Director B3/10/07 YOUNG, T Region 5. Office of Director 153pp 22254:165. 24X Fichs 50-528,83/12/20,8402140018

- --8402140043 Provides list of NDE repts available from insplactivities completed W/NRC mobile NDE van at facility.per FOIA request Related info encl
 EBNETER.S D. Region 1. Office of Director 93/11/15
 ALEXANDER.I M. Region 5. Office of Director 97pp 22255 324
 24X Fiche 50-528.83/12/20.8402140018
- --8402140048 Rev O to "Palo Verde Station HPSI Sys Electrical & Instrumentation Const Audit Insp." final rept Related infoencl * Zytor. Inc NRC-IE-82/83-46C 83/10/04 158pp 22256 063 24X Fiche 90-528.83/12/20.8402140018
- --B402140052 Provides resolution for loose bolts on structural steel found during NRC const assessment team (CAT) insp [tem considered closed Related info ent] FORRESTER, R D Arizona Public Service Co B3/09/26 IDE, W E Arizona Public Service Co B3 2256 221 24X Fiche 50-528,83/12/20,8402140018
- B403080145 Forwards IE Insp Rept 50-528/84-01 on 840116-20 No violations or deficiencies noted NORDERHAUG, L R Region 5, Office of Director 84/02/13 VAI BRUNT.E E Arizona Public Service Co 2pp 22559 152 24X Fiche 50-528,84/02/13,8403080145
- --8403080152 IE Insp Rept 50-528/84-01 on 840116-20 No violations or deficiencies noted Major areas inspected followup of open items identified during insp on 830411-22 & observation of 830511 emergency preparedness exercise FISH, R F, TEMPLE, 9 M, SCHUSTER, M D Region 5, Office of Director 84/02/09 12pp 22559-154 24X Fiche 50-528,84/02/13,8403080145
- 8403080254 Forwards IE Insp Repts 30-528/84-02 & 50-529/84-02 on 840103-0203 No noncompliance identified BISHOP.T W Division of Resident/Reactor Project & Engineering Programs 84/02/27 VAN SRUNTE E Arizona Public Service Co 2pp 22557 104 24X Fiche 50-528/84/02/27/8403080254
- --B4030B0243 IE Insp Repts 50-528/84-02 & 50-529/84-02 on 840103-0203 No noncompliance or deviations identified Major areas inspected startup testing program, info notice reviews, GA. low pressure safety injection pumps & pressurizer heater power FIORELLI, G., YOUNG, T. Region 5, Office of Director B4/02/lo 6pp 22557 106 24X Fiche 50-528,84/02/27,8403080254
- 8401170072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22909 239 24X Fiche 50-000,84/02/28,8401190072
- B402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Reys by DOT & NRC " Svc list encl ORACE, J N Division of GA, Bafeguards & Inspection Programs (Post B30103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552 329 24X Fiche 50-000.84/03/02,8402090007
- 8402070008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valvas to Operate " Svc list and JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103), 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22583 078 24X Fiche 50-000-84/03/02.8402090008
- 8402090009 IE Info Notice 84-15, "Reporting of Radiological Releases " Bvc list encl JORDAN,E L. Division of Emergency Proparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 119pp 2253 217 24X Fiche 50-000,84/03/92,8402090009
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Past 830103) 84/03/05 Consolidated Edison Co. of New York, Inc. 117pp 22553 336 24X Fiche 50-000.84/03/05,8402090011
- B403140024 Informs that Bingham-Williamette spare flange piece will be replaced by 840415 instead of 840227, due to problems encountered w/yendom.per IE Bulletin 83-06. "Monconforming Matls Supplied By Tube-Line Corp"

 VAN BRUNTLE E Arizona Public Service Co 84/03/03 MARTIN, J B Region 5. Office of Director ip 22633 217 24X

 Fiche 50-528,84/03/05,8403140024
- B402090024 IE Info Notice 84-09. Rev i, "Lessons Learned From Imsps of Fire Protection Safe Shutdown Sys " Evc list encl JORDAN: E.L. Division of Emergency Preparedness & Engineering Response (Post 830102) 84/03/07 Consolidated Edison Co. of New York, Inc 118pp 22635 049 24X Fiche 50-000. B4/03/07. B402090024

- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Sys " Sic list encl JORDAN, E L Division
- bys "S.c list enci JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/07 Consolidated Edison Co of New York, Inc. 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list enc! DEYDUNG.R C Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000,84/03/12,8402090031
- B402090043 IE Info Notice B4-19. "Tup Events Involving Unauthorized Entries into PMR Reactor Cavities" Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/03/21 Consolidated Edison Co of New York. Inc 123pp 22823 229 24% Fishe 50-000.84/03/21.8402090043
- 8402090044 IE Info Notice 84-20. "Svc Life of Relays in Safety-Related Sys "Syc list and JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044
- 8403270135 Forwards IE Conference Rept 50~528/84~11 on 840305 re organists rotuards IE Conference Rept 50-328/84-11 on 840305 recorrective actions talen in response to IE this Rept 50-528/83-34 Response to open questions requested BIBHOP, T W Division of ResidentiReactor Project & Engineering Programs 84/03/22 MODS. T O Artisona Public Service Co 1 22769 137 24X Fishe 50-528/84/03/22/8403270135
- --8403270139 IE Conference Rept 50-528/84-11 on 840305 Major areas discussed corrective actions described in util 840/30 Ma response to IE Insp Rept 50-528/83-34 & NRC 831212 enforcement Itr
- R Persodic operating reports & related correspondence
- 8403)20443 Forwards monthly status rept of offsite emergency preparedness for OL reviews for Jan 1984 Changes in FEMA finding dates not caused by delay due to offsite emergency planning issues

 DIRCKS, W J Diffice of the Executive Director for Operations

 84/02/21 PALLADIND Commissioners 9pp 22492 083 24%

 Fiche 50-000.84/02/21.8403020443
- S Reportable occurrences, LERs & related correspondence
- 8403090087 Interim Deficiency Rept 83-81 re Schedule 160 SS pipe supplied by Gulfalloy, Inc. containing mfg min wall thickness defect Initially reported on 831128 No new info presently available Final rept expected by 840417

 VAN BRUNT, E E Arizona Public Service Co 84/02/22 BISHOP, 1 Division of Resident, Reactor Project & Engineering Programs 22575 325 24X Fiche 30-528,84/02/22,8403090087 84/02/22 BISHOP, T W
- 8403090122 Interim Potentially Reportable Deficiency Rept DER 83-69 re seismic support on Posi-Seal valves not installed per specs Due to extensive investigation.final rept delayed until 840515 VAN BRUNTLE E Arizona Public Service Co 84/02/22 BISHOP, T W Division of Resident.Reactor Project & Engineering Programs 2pp 22576 064 24% Fiche 50-528.84/02/22.8403090122
- 8403090197 Interim Deficiency Rept DER 83-82 re cables in Units 1 & 2 dissel generator control cabinets & Unit 1 dissel generator bldg w/small bend radius Initially reported on 831202 Final rept delayed until 840425 VAN BRUNT.E E Arisona Public Service Co 84/02/22 BISHOP, T W Division of Resident.Reactor Project & Engineering Programs 2pp 22574 290 24X Fiche 50-528.84/02/22.8403090197
- B40309025B Interim Deficiency Rept DER 83-75 re improperly torqued bolts securing two D01265A panel filler assemblies, supplied by Forboro No new info available at present time final rept will be submitted by B40419

 VAN BRUNT.E E Arizona Public Service Co 84/02/22 BISHOP, T W D1vision of Resident.Reactor Project & Engineering Programs 2pp 22572 211 24X Fiche 50-528,84/02/22,8403090258 84/02/22 BISHOP, T W
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines, Gimpel NPS-4 T&T valve, to close. Encl ltr dtd 840203 sent to listed utils GE notified of affected units in BMR plants THEROUX, A R THEROUX,R R Terry Corp 84/02/22 WODDRUFF,R W Director's Office. Office of Inspection and Enforcement App 22706 327 24X

- 840229000B Forwards response to listed items identified in 840125 telcon request for info generated based on preliminary review of 831230 deficiency rept re missing thermal liner in safety injection sys line Encis withheld VAN BRUNT.E E Arizona Public Survice Co 84/02/24 KNIGHTON.G Licensing Branch 3 3pp 22516 186 24X Fiche 50-528,84/02/24.8402290008
- 8403090077 Interim Deficiency Rept 83-72 re undersized worlds. In AUGUVOV/ Interim Dericiency Rept BI-72 re undersited words auxiliary bidg discovered by const appraisal team Initially reported on 831026 Due to extensive investigation & evaluation final rept will be delayed until 840315 VAN BRUNT.E E Arizona Public Service Co 84/02/24 BIBHC Region 5. Difica of Director 2pp 22575 274 24X Fiche 30-326.84/02/24.8403090077 BIBHOP, T W
- 8403090096 Deficiency Rept DER 83-73 re unqualified Foxboro power supplies installed in IE instrument cabinets Initially reported on 831027 No new info presently available Next rept will be provided by 840425 VAN BRUNT.E E Arizona Public Service Co 84/02/24 BIBHOP, Y Division of Resident. Reactor Project & Engineering Programs 25 22576 179 24X Fiche 50-528,84/02/24,8403090096
- 8403090167 Interim Deficiency Rept DER 82-80 re low insulation resistance on installed Conax electrical penetrations not meeting qualification test criteria Initially reported on 821217 Final rept delayed until 840425.

 VAN BRUNTLE E Arizona Public Service Co 84/02/24 818HOP, T W Division of Resident, Reactor Project & Engineering Programs 2pp 22575 116 24X Fiche 50-528,84/02/24,8403070167
- 8403060429 Requests add1 info needed to complete evaluations of & fires for reactor coolant pump problems encountered during hot functional testing Response requested within 2 wks KNIGHTON, 0 & Licensing Branch 3 84/02/27 VAN BRUNT, E Arizona Public Bervice Co 3pp 22552 210 24X Fiche 50-528,84/02/27,8403060429
- 8403120032 Final Deficiency Ropt DER 83-70 ra wiring in emergency response facility cabinets supplied by Energy, Inc not in conformance w/IEEE-384 critoria Initially reported on 831011 Drawings resubmitted Also reported per Part 21 VAN BRUNTLE E Arizona Public Service Co 84/02/28 BIBHUP, T Division of Resident, Reactor Project & Engineering Programs 49 22588 025 24X Fiche 50-528, 84/02/28, 8403120032 BIBNOP, T W
- B403120069 Final Deficiency Rept DER 83-10 re main steam relief valvet supplied by C-E & mfg by Dresser Industries exceeding specified 54 blowdown limit Initially reported on B3022B Deficiency determined not reportable per 10CFR90 53(e) VAN BRUNTLE E Arizona Public Service Co 84/02/28 BISHOP. T & Division of Resident, Reactor Project & Engineering Programs App 22591 129 24X Fiche 50-528.84/02/28.8403120069
- 8403130449 Potential Deficiency Rept DER 83-44 re Target Rock pressure relief valves failing to meet prerequisite tests Final rept delayed until 840402 celayed until 190902 VAN BRUNT.E E Arizona Public Service Co 84/02/28 BIBHUF Division of Resident, Reactor Project & Engineering Programa 22613 212 24X Fiche 50-528,84/02/28,8403130449 84/02/28 BISHOP, T H
- 8403130461 Potential Deficiency Rept DER 83-68 re Borg Harmer RPB1 isolation valves failing to open against NPSI A & B pump flows Final will rept delayed until 840417 VAN BRUNTE E Arizona Public Service Co 84/02/28 BISHUP, T. N Division of Resident, Reactor Project & Engineering Programs 2pp 22613 355 24X Fiche 50-528.84/02/28,8403130461
- 8403090149 Forwards request for add1 info re Deficiency Rept DER 183-35 concerning leaks in temporary water lines that distributed backfill under seismic Category I structures Responses requested within 2 wks of ltr receipt KNIOHTON, O W Licensing Branch 3 84/02/29 VAN BRUNT, E E. Arizona Public Service Co Bpp 22584 350 24X Fiche 50-328,84/02/29,8403090149
- 8403120113 Final Deficiency Rept DER 83-32 re socket welds in steam generator process piping in violation of requirements Initially reported on 830525 Condition determined not reportable per 10CFR30 55(e)
 VAN BRUNTLE E Arizons Public Service Co 84/02/29 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 5pp 22588 218 24X Fiche 50-528, 84/02/29, 8403120113
- 8403200115 Interim Deficiency Rept DER 83-80 re Anchor Darling main feedwater isolation valves closing in 20 s.violating 5 s spec requirement Initially reported on 831122 Final rept will be delayed until 840403 due to extensive investigation. VAN BRUNT, E E Arizona Public Service Co 84/03/02 BIBHOP, T W Division of Resident Reactor Project & Engineering Programs 2pp. 22685:355 24X Ficha 50-528,84/03/02,8403200115

- 8403200186 Interim Deficiency Rept DER 83-56 re discrepancies w/MSIVs mfg by Anchor-Darling Initially reported on 830808 Investigation will be finalized by 840413 at which time complete rept will be submitted VAN BRUNT, E E Arizona Public Service Co 84/03/08 BISHOP, T W Division of Resident Reactor Project & Engineering Programs 2pp 22686 359 24X Fiche 50-328.84/03/08.8403200186
- 8403200226 Interim Deficiency Rept DER 84-06 re defective absolute & deviation alarm modules supplied by Foxboro. C-E requested that all alarm modules w/date Godes 8048-8152 be inspected for potential defect Next rept by 840612

 VAN BRUNT, E E Arirona Public Service Co 84/03/09 BISHDP, T W Division of Resident. Reactor Project & Engineering Programs 3pp 22699 358 24X Fiche 50-528.84/03/09.8403200226
- 8403230039 Final Deficiency Rept DER-83-79 re ac interference spikes on 125-volt dc bus exceeding spec Initially reported on 831118 Deficiency deemed not reportable per 10GFR50 55(e) VAN SRUNT, E & Arizona Public Service Co 84/03/09 BIBHOP, T W Division of Residents Reactor Project & Engineering Programs 4pp 22730 302 244 Fiche 50-528 84/03/09. 8403230039
- 8403230113 Rev i to final Deficiency Rept 82-30 re possible damaged flexible conduit couplings between auxiliary & control bldgs in event of veismic events exceeding 3/4 inch movement Rev changes final rept disposition to reportable under 10CFR1 VAN BRUNT.E E Arizona Public Service Co 84/03/09, BISHOP,T W Division of Resident Reactor Project & Engineering Programs App 22730 215 24% Fiche 50-528,84/03/09,8403230113
- 8403230006 Final Deficiency Rept DER 83-87 re valves w/handwheel adapter not missing & rising stem supplied by Roto-Hammer. Inc lunger than operating bridle Initially reported on 840103 Condition not reportable per 10CR850 55(e) & Part 21 VAN BRUNT, E E Arizona Public Service Co. 84/03/13 818H0P,T & Division of Resident, Reactor Project & Engineering Programs & pp 22728 343 24X Fiche 50-528,84/03/13,8403230006
- 8403230099 Final Deficiency Rept DER 83-72 rs undersize welds in auxiliary bldg Initially reported on 831026 Condition determined not reportable per 10CFR50 59(e)

 VAN BRUNT, E E Arizona Public Service Co 84/03/14 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 6pp 22728 356 24X Fiche 50-528, 84/03/14, 8403230099
- 8403230019 Final Deficiency Rept DER 82-44 re ITT Berton pressure transmitters supplied by C-E not meeting overpressure requirements Caused by leakage of metallic washers & methodology error during calibr Also reported per Part 2: VAN BRUNT,E E Arizona Public Service Co 84/03/15 818HDP,T W Division of Resident Reactor Project & Engineering Programs 7pp 22724 353 24X Fiche 50-520,84/03/15,8403230019
- B403300096 Interim Deficiency Rept DER 84-08 re ITY Barton Model 763 transmitters having errors of -2 to -3% of calibr span Bechtel corresponding w/C-E to determine impact of design mods to transmitters

 VAN BRUNT, E E Arizona Public Bervice Co 84/03/16 BIBHOP, T, W Division of Resident Reactor Project & Engineering Programs 3pp 22822 010 24% Fiche 50-528,84/03/16,8403300096
- 8403300020 Rev 1 to final Deficiency Rept DER 82-46 re ITT-Barton pressure transmitters supplied by C-E failing to meet overpressure requirements Initially reported on 820824 Also reported per Part 21 VAN BRUNT,E E Arizone Public Service Co 84/03/19 818HDP,T W Division of Resident, Reactor Project & Engineering Programs 7pp 22822:171 24X Fiche 50-528.84/03/19.8403300020

V Operator Examinations

- 8403290236 Forwards operations experience base, consisting of experience tables for presently licensed personnel Inadequate number of personnel meet 6-wk hot participation experience requirement

 VAN BRUNT, E E Arizona Public Service Co 84/03/23 DENTON, H R. Office of Nuclear Reactor Regulation. Director 17pp 22800 236
 24X Fiche 50-528,84/03/23,8403290236
- DOCKET STN-50-529 PALO VERDE NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8403080390 Responds to FOIA request for 27 documents referenced in 1975 EIB re facilities & similiar environ documents Forwards App A Documents i-10 Documents ii & 12 Available at NTIS FELTON, J M Division of Rules and Records B4/02/13 RYAN, J A Btraith, Lang, Weeks & Cardon 2pp 22581*180 24X Fiche 30-528,84/02/13,8403080390

- --8403080407 "Groundwater Conditions of Lower Høssayampa-Centennial Arra. Maricapa County.AZ " Related info encl * Harshbarger & Associates R-900-74-2 74/06/30 83pp 22581 219 24X Fisha 50-528.84/02/13.8403080390
- 8403050451 Forwards request for add1 info re open environ qualification of slectrical equipment items for facility KNIGHTON, G W Licensing Branch 3 84/02/27 VAN BRUNT, E E Arizona Public Service Co 5pp 22550 007 24X Fiche 50-528.84/02/27.8403060451
- 8403010212 Forwards response to 840206 telcon re draft rev to FBAR Section 3A 10 concerning low preheat fillet welding low preheat pases no concern, principally due to low hardenability of base matis
 VAN BRUNTLE E Arizona Public Service Co 84/02/26 KNIGHTON, 0
 Licensing Branch 3 App 22439 279 24X Fiche 50-528.84/02/28, 8403010212
- 8403280043 Notification of 840320 meeting w/util & C-E in Bethesda,MD to discuss proposed testing program to demonstrate adequacy of mods to RCS pumps, thermowells, thermal sleeves & control element assembly shrouds LICITRA,E A Licensing Branch 3 84/02/29 KNIGHTON, & W Licensing Branch 3 3pp 22812 361 24X Fichs 50-528,84/02/29,8403280043
- 840309013D Advises that proposed leak rate acceptance criteria for Tech Spec limiting conditions for operation unacceptable, since criteria less restrictive than 1 gpm leak rate imposed on near-term OLs KNIGHTON, 0 W Licensing Branch 3 84/03/01 VAN GRUNT, E E Arizona Public Service Ca 2pp 22992 301 24X Fiche 50-528,84/03/01.8403091030
- 8403150094 Forwards outstanding item list for PDR List also submitted to util JOHNSON, P. H. Region 5. Office of Director 84/03/08 ALEXANDER, I Region 5. Office of Director 14pp 22441 190 24X Fiche 50-528,84/03/08,8403150094
- 8402070041 Board Notification 84-050 provides Commission policy statement & proposed rulemaking on environ qualifications EISENHUT, D O Division of Licensing 84/03/14 Atomic Safety and Licensing Board Panel 10pp 24X Fichs 50-000,84/03/14,8402070041
- 8403160048 Forwards updated preliminary description (Rev 1) for RCS demonstration test VAN BRUNT, E.E., ROGERS, A.G. Arizona Public Service Co. 84/03/14 KNIGHTUN, G. Licensing Branch 3. 2pp. 22639 [67] 24X Fiche 50-528,84/03/14,8403140048
- --8403160052 Rev 1 to "RCS Demonstration Test" * Arizona Public Service Co 84/02/29 Bpp 22659 171 24X Fiche 50-528.84/03/14.8403160048
- 8403160065 Notifies that addl info & schedule re electrical equipment environ qualification program will be submitted by 840326, per 840227 request VAN BRUNT.E E Arizona Public Service Co 84/03/14 KNIGHTON.G Licensing Branch 3 1p 22652 326 24X Fiche 50-528,84/03/14,840316065
- 8403270236 Forwards operations experience base consisting of experience tables for presently licensed personnel inadequate number of personnel meet 5-wk hot participation experience requirement VAN BRUNTLE E Ariona Public Service Co 84/03/23 DENTON, H R Office of Nuclear Reactor Regulation Director 17pp 22800 236 24X Fiche 50-528,84/03/23,8403270236
- C Utility Environmental Report (ER), amends & correspondence
- 8403080390 Responds to FDIA request for 27 documents referenced in 1975 EIB re facilities & similar environ documents Forwards App A Documents in 10 Documents in & 12 available at NTIS FELTUN J M Division of Rules and Records. 84/02/13 RYAN, J A Streich, Lang, Weeks & Cardon 2pp 22581:180 24% Fiche 50-528,84/02/13,8403080390
- --8403080400 Discusses review of environ rept re transmission lines crossing Indian reservations Tribal council consent should be obtained for right-of-way before environ rept published Related info encl

 # Interior, Dept of, Bureau of Indian Affairs 74/12/11
 REGAN.W H Atomic Energy Commission Deputy Director for Reactor Projects 5pp. 22581 184 24X Fiche 50-528,84/02/13,8403080390

- D NRC Draft/Final Environmental Statements, suppls & correspondence
- 8403080385 FDIA request for 27 documents referenced in 1975 EIS refacilities & similiar environ documents List & news articles encl
 RYANJA Streich, Løng, Weeks & Cardon 84/01/17 Office of Administration 9pp 22581 171 24X Fiche 50-528,84/01/17,8403060365
- 8403080390 Responds to FOIA request for 27 documents referenced in 1975 EIS re facilities & similiar environ documents Forwards App A Bocuments 1-10 Bocuments t1 & 12 available at NTIS FELTON, J M Division of Rules and Records 84/02/13 RYAN, J A Streich, Lang, Weeks & Cardon 2pp 22581 180 24X Fiche 50-528.84/02/13,8403080390
- --8108270490 Submits Geosciences Branch DES input Updated summary of geology & seismology section FSAR will be included in SER JACKSON.R.E. Geosciences Branch 81/08/14 MIRAGIA.F Licensing Branch 3 2pp 22581 182 24X Fiche 50-528, 84/02/13, 8403080390
- --B4030B0406 Comment on DES, per 750414 request Statement somewhat biased toward project More detailed maps of pipeline & transmission line corridors should be provided in final statement DOREMUS. B D Interior, Dept of 75/07/23 REGAN Division of Reactor Licensing (NRR-1975 only) 29pp 22581 IB9 24X Fiche 50-528,84/02/13.8403080390
- 8403290341 Responds to FOIA request for records re facility Ltr dtd 840117 failed to meet criteria for waiver of reproduction costs Forwards App A documents Address of Phoenix LFDR listed FELTON.J M Division of Rules and Records 84/02/27 RYAN.J A
 - FELTON, J.M. Division of Rules and Records 84/02/27 RYAN, J.A. Streich, Lang, Weeks & Cardon 3pp 22815 018 24x Piche 50-528,84/02/27,8403290341
- --8403290344 DRAFT ENVIRONMENTAL STATEMENT RELATED TO CONSTRUCTION OF PALD VERDE NUCLEAR GENERATING STATION UNITS 1.2 % 3 Docket Nos 50-928,50-929 % 50-530 ** Office of Nuclear Reactor Regulation, Director NURE0-75/029 75/04/30 175pp 22815 301 24X Fiche 50-528,84/02/27,8403290341
- E BRC Safety Evaluation Report (SER), suppls & correspondence
- 8403020005 Forwards info requested in SSER 5 (NUREO-0857) re tests performed for C-E on load limiting devices in reactor vessel lower key horizontal supports

 VAN BRUNTLE E Arizona Public Service Co 84/02/10 KNIGHTON, @ Licensing Branch 3 Typ 22442 201 24X Fiche 50-528, 84/02/10, 8403020005
- 8403090012 Forwards "High Pressure Safety Injection Pump," mechanical environ qualification rept, per SSER 5 (NUREQ-0857)
 VAN BRUNT-E E Arizona Fubilic Service Co 84/02/29 KNIGHTON, 0 W Licensing Branch 3 2pp 22568 001 24X Fiche 50-528.84/02/29, 8403090012
- --8403090014 "High Pressure Safety Injection Pump," mechanical environ qualification rept
 HALLER, R E Bechtel Corp V-PAK-481 84/01/12 198pp
 22568 004 24X Fiche 50-528,84/02/29,8403090012
- F Security, medical, emergency & fire protection plans
- B402090006 Board Notification 84-034 forwards R Voltmer 840206 memo to D Eisenhut re fire research results concerning fires in electrical cabinets in control room EISENHUT, D G Division of Licensing 84/02/23 PALLADING Commissioners ip 22576 203 24% Fiche 50-000,84/02/23,8402090006
- --8403080316 Recommends that info re fire research results concerning fires in electrical cabinets in control room be submitted for board notification per NRR OFC Ltr 19. dtd 82:001 Further evaluation of test data required VOLLHER.R H Division of Engineering 84/02/06 EISENHUT, D 9 Division of Licensing 10pp 22576 204 24% Fiche 50-000.84/02/23,8402090006
- 8403260014 Requests removal of App F & 0 from Rev 2 to Emergency Pian Implementing Procedure 7, per Generic Ltr 81-27 & OM Knighton 840214 1tr informing that util must request withholding of private or unlisted telephone numbers VAN SRUNT, E E Arizona Public Bervice Co 84/03/17 KNIGHTON, G W Licensing Branch 3 2pp 22750 258 24X Fiche 50-928,84/03/19,8403260014

- @ Inspection reports, IE Bulletins & correspondence
- B4G2140014 FOIA request for records re NRC const assessment team (CAT) insp at facilities

 BERNABELL Government Accountability Project 83/10/07 Office of Administration 2pp 22254 001 24X Fiche 50-528.83/10/07, B4G2140014
- 8402140018 Responds to FOIA request for records re NRC const assessment team (GAT) insp at facilities Forwards App A documents
 Documents also in PDR App B documents listed for review to identify specific interest
 FELTON.J M Division of Rules and Records 83/12/20 GARDE, B P Government Accountability Project 18pp 22294 003 24X
 Fichs 50-528,83/12/20.8402140018
- --8402140022 Summarizes civil insp items Bechtel 830929 ltr re reinsp of nuclear pipe hangers (8 tlass) & related info encl VORDERBRUEGEN Region 5, Office of Director 83/09/19 NARBUT, P NRC - No Detailed Affiliation Given 60pp 22254 021 24X Fiche 50-528,83/12/20,8402140018
- --B402140031 Comments on review of draft writeup on NDE Rewrite requested Related info encl NARBUT.P NRC - No Detailed Affiliation Given 83/09/27 KERCH.H NRC - No Detailed Affiliation Given 4ipp 22254 094 24X Fiche 50-528,83/12/20,8402140018
- --8402140032 Summary of B30916 erit status meeting w/NRC const appraisal team re 830907-16 insp IDE,W E Arizona Public Service Co 83/09/19 ROEDEL,J A Arizona Public Service Co 6pp 22254 137 24X Fiche 50-529.83/12/20.8402140018
- --8402140036 Forwards marked-up draft insp scope & objectives Related info entl ALBERT, N G. Region 5. Office of Director 83/09/21 YOUNG, T Region 5. Office of Director 18pp 22254 143 24X Fiche 50-528,83/12/20,8402140018
- --8402140043 Provides list of NDE repts available from insplactivities completed w/NRC mobile NDE van at facility, per FOIA request Related info encl EUNETER.5 D. Region i, Office of Director 83/11/15 ALEXANDER.I M. Region 5, Office of Director 97pp 22255 324 24% Fiche 50-528,83/12/20,8402140018
- --8402140048 Rev O to "Palo Verde Station HPSI Sys Electrical & Instrumentation Const Audit Insp." final rept Related info enc1
 * Zytor, Inc NRC-IE-82/83-44C 83/10/04 158pp 22256 063 24% Fiche 50-528,83/12/20,8402140018
- --8402140032 Provides resolution for loose bolts on structural steel found during NRC const assessment team (CAT) insp Item considered closed Related info encl FORRESTER, R D Arizona Public Service Co 83/09/26 IDE, W E Arizona Public Service Co 3pp 22236 221 24X Fiche 50-528,83/12/20,8402140018
- 8403080294 Forwards IE Insp Repts 50-528/84-02 & 50-529/84-02 on 840103-0203 No noncompliance identified BISHOP.T W Division of Resident: Reactor Project & Engineering Programs 84/02/27 VAN BRUNT.E E Arizona Public Service Co 2pp 22557 104 24X Fiche 50-528/84/02/27/8403080254
- --8403080263 IE Insp Repts 50-528/84-02 & 50-529/84-02 on 840103-0203 No noncompliance or deviations identified Major areas inspected startup testing program info notice reviews, GA, low pressure safety injection pumps & pressurizer heater power FIDRELLI, G, YOUNG, T Region 5. Office of Director 84/02/16 6pp 22557 106 24X Fichs 50-528,84/02/27,8403080254
- B401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list enc!

 JGRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/02/28 Consolidated Edison Co of New York, Inc 115pp 22909 239 24X Fiche 50-000,84/02/28,8401190072
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Reys by DOT & NRC " Svc list encl GRACE.J N Division of GA, Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidate Edison Co of New York, Inc 130pp 22552 327 24% Fiche 50-000,84/03/02,8402090007
- B402070008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys-Valves to Operate" Svc list enci JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) B4/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24% Fiche 50-000,84/03/02,8402070008

- 8402070007 IE Info Notice 84-15, "Reporting of Radiological Releases " Svc list encl JORDAN E L
 - Syc list enci JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 119pp 22553 217 24% Fiche 50-000,84/03/02,8402070009
- 8402090011 IE Info Notice 84-17. "Problems W/Liquid Nitragen Cooling Components Below Nil Ductility Temp " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000.84/03/05.8402070011
- B403140024 Informs that Bingham-Williamette spare flange piece will be replaced by 840415 instead of 840227, due to problems encountered w/vendor.per IE Bulletin 83-06, "Nonconforming Matis Supplied By Tube-Line Corp"

 VAN BRUNT.E E Arizona Public Service Co 84/03/05 MARTIN, J B Ragion 5, Office of Director ip 22633 217 24X

 Fiche 50-528,84/03/05,8403140024
- 8402090024 IE Info Notice 84-09, Rev 1, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22635 049 24X Fiche 50-000,84/03/07,8402090024
- 8402070028 IE Info Notice 84-18. "Stress Corresion Cracking in PWR 02079028 IE Into Novella S. Sys " Svc list encl Sys " Svc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc (18pp 22584 186 24X Fiche 50-000.84/03/07,8402070028
- 8402070031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Byc list and DEYBUNO,R C Director's Office, Office of Inspection and Enforcement B4/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24% Fiche 50-000.84/03/12.8402070031
- B402090043 IE Info Notice 84-19. "Two Events Involving Unauthorized Entries into FWR Reactor Cavities " 8vc list encl JURDAN: EL Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24X Fiche 50~000.84/03/21.8402090043
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc list encl JORDAN E L Divisi Division of Emergency Preparedness & Engineering ost 830103) 84/03/21 Consolidated Edison Co of New 135pp 22733 001 24X Fiche 50-000 84/03/21 8402070044 Response (Post 830103) Yark, Inc. 135pp. 22
- 8 Reportable occurrences, LERs & related correspondence
- 8403090087 Interim Deficiency Rept 83-81 re Schedule 160 SS pipe NOSONO A theorem were trency week 63-de re Schedule 160 as pay supplied by Gulfalloy Inc. containing mfg min wall thickness defect Initially reported on 831128 No new info presently available Final rept expected by 840417 VAN BRUNT.E E Arizona Public Service Co 84/02/22 BISHO Division of Resident, Reactor Project & Engineering Programs 22575.325 24x Fiche.50-528,84/02/22,8403090087 84/02/22 BISHOP, T W
- 8403090197 Interim Deficiency Rept DER 83-82 re cables in Units 1 & 2 diesel generator control cabinets & Unit 1 diesel generator bldg w/smell bend radius Initially reported on 831202 Final rept delayed until 840425 VAN BRUNT.E E. Aritona Public Service Co 84/02/22 BIBHOP, T W Division of Resident.Reactor Project & Engineering Programs 2pp 22574 290 24X Fiche 50-528,84/02/22.8403090197
- 8403090258 Interim Deficiency Rept DER 83-75 re improperly torqued bolts securing two D01268A panel filler assemblies, supplied by Foxboro No new info available at present time Final rept will be submitted by 840419

 VAN BRUNT. E E Arizona Public Service Co 84/02/22 BIBHOP, T & Division of Resident Reactor Project & Engineering Programs 2pp 22572: 211 24% Fiche 50-528,84/02/22,8403090258 84/02/22 BISHOP, T W
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines, Jimpel NPS-4 T&T valve, to close Encl ltr dtg 840203 sent to listed utils GE notified of affected units in BWR plants
 THERDUX.R R Terry Corp 84/02/22 WOODRUFF,R W Director's
 Office, Office of Inspection and Enforcement 6pp 22706:327
 Fichs. 50-000,84/02/22,8403210032
- 840229000B Forwards response to listed items identified in 840125 telcon request for info generated based on preliminary review of 831230 deficiency rept re missing thermal liner in safety injection sys line Encls withheld VAN BRUNT, E.E. Arizona Fublic Service Co 84/02/24 KNIGHTON, O. Licensing Branch 3. 3pp 22516 186 24X Fiche 30-528, 84/02/24, 8402270008

- 8403090096 Deficiency Rept DER 83-73 re unqualified Foxboro power supplies installed in IE instrument cabinets Initially reported on 831027 No new info presently available Next rept will be provided by 840425
 VAN BRUNT, E. E. Arizona Public Service Co. 84/02/24 BISHOP, T. Division of Resident, Reactor Project & Engineering Programs 2p 22576 179 24X Fiche 90-528,84/02/24,8403090096
- 8403090167 Interim Deficiency Rept DER 82-80 re low insulation resistance on installed Conax electrical penetrations not meeting qualification test criteria Initially reported on 821217 Final rept delayed until 840425 VAN BRUNT.E E Arizona Public Service Co 84/02/24 BISHOP.T W Division of Resident.Reactor Project & Engineering Programs 2pp 07478 114 244 51-1- 80-509 04/07/24 803090/14. 24x Fiche 50-528,84/02/24,8403090167
- B403060427 Requests add1 info needed to complete evaluations of & fixes for reactor coolant pump problems encountered during hot functional besting Response requested within 2 was KNIGHTON, O. W. Licensing Branch 3 84/02/27 VAN BRUNT, E. Arizona Public Service Co. 3pp. 22532 210 24X Fiche 50-528.84/02/27.8403060429
- 8403120032 Final Deficiency Rept DER 83-70 re wiring in emergency response facility cabinets supplied by Energy, Inc not in conformance w/IEEE-384 criteria Initially reported on 831011 Drawings resubmitted Also reported per Part 21 VAN BRUNTLE E Aritona Public Service Co 84/02/28 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 4pp 22588 025 24% Fiche 50-528,84/02/28,8403120032
- 8403120069 Final Deficiency Rept DER 83-10 re main steam relief valves supplied by C-E & mfg by Bresser Industries exceeding specified 5% blowdown limit Initially reported on 930228 Deficiency determined not reportable per 10CFR30 55(e) VAN BRUNT, E E Arizona Public Service Co 84/02/28 BISHOP, T W Division of Resident Reactor Project & Engineering Programs 4pp 22591 127 24% Fiche 50-528.84/02/28.8403120067
- 8403130449 Potential Deficiency Rept DER 83-64 re Target Rock pressure relief valves failing to meet prerequisite tests Final rept delayed until 840402 VAN BRUNT, E. Artiona Public Service Co. 84/02/28 818HOP, T.W. Division of Resident, Reactor Project & Engineering Programs 2pp 22613 212 24X Fiche 30-528,84/02/28,8403130449
- 8403130461 Potential Defictency Rept DER 83-68 re Borg Warner HPSI isolation valves failing to open against HPSI A & B pump flows Final will rept delayed until 840417 VAN BRUNT,E E Arizona Public Service Co 84/02/28 BISHOP,Y W Division of Resident, Reactor Project & Engineering Programs 2pp 22613 355 24% Fiche 50-528,84/02/28,8403130461
- B40320Dii3 Interim Deficiency Rept DER 83-80 re Anchor Darling main feedwater isolation valves closing in 20 s,violating 5 s spec requirement finitially reported on 83122 Final rept will be delayed until 840403 due to extensive investigation VAN BRUNT.E E Arisona Public Service Co 84/03/02 BISHOP.T W Division of Resident, Reactor Project & Engineering Programs 2pp 22685 355 24% Fiche 50-528,84/03/02.8403200115
- 8403200160 Interim Deficiency Rept DER 84-07 re extension of Borg Harner valve stems & failure to provide corrective action stated in Rept DER 80-21 Initially reported on 840209 Bechtel investigating corrections Final rept by 840416 VAN BRUNTLE E Arisona Public Service Co 84/03/02 BISHOP,T W Division of Resident, Reactor Project & Engineering Programs 3pp 22697 131 24X Fiche 90-527, 84/03/02,8403200160
- B403200186 Interim Deficiency Rept DER 83-56 re discrepancies w/MSIVs mfg by Anchor-Darling Initially reported on 830808 Investigation will be finalized by 840413 at which time complete rept will be submitted VAN BRUNTLE E Arizona Public Service Co 84/03/08 BISHOP, TW Division of Resident. Reactor Project & Engineering Programs 2pp 22686 359 24X Fiche 30-328.84/03/08,8403200186
- 8403200226 Interim Deficiency Rept DER 84-06 re defoctive absolute & deviation alarm modules supplied by Fexboro C-E requested that all alarm modules w/date Codes 8048-8152 be inspected for potential defect Next rept by 840612 VAN BRUNTLE E Arizona Public Service Co 84/03/09 BISHOP,T W Division of Residents Reactor Project & Engineering Programs 3pp 22699 358 24X Fiche 50-528,84/03/09.8403200226
- 8403230039 Final Deficiency Rept DER-83-79 re ac interference spikes on 125-volt dc bus exceeding spec Initially reported on 831118 Deficiency deemed not reportable per 100FR90 55(a) VAN BRUNT, E E Arixona Public Service Co 84/03/09 BISHOP, T W Division of Resident. Reactor Project & Engineering Programs 4pp 22730 302 24X Fiche 50-528,84/03/09,8403230039

- 8403230132 Final Deficiency Rept DER 83-59 re IEEE-384 separation criteria violated by wiring in post-accident control room cabinet & safety radiation monitoring cabinet Supplied by Ammen Instrumentation Item not reportable per 10CFR50 55(e) VAN BRUNT.E E Arizona Public Service Co 84/03/09 BISHUP.T W Division of Resident.Reactor Project & Engineering Programs 5pp 22730 154 24X Fiche 50-529.84/03/09.8403230132
- 8403230099 Final Deficiency Rept DER 83-72 re undersize welds in auxiliary bldg Initially reported on 831026 Condition determined not reportable per 10CFR50 55(e) VAN BRUNT, E E Arizona Public Service Co 84/03/14 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs 6pp 22728 356 24% Fiche 50-528,84/03/14,8403230099
- 8403230019 Final Deficiency Rept DER 82-46 re ITT Barton pressure transmitters supplied by C-E not meeting overpressure requirements Caused by leakage of motallic washers & nethodology error during calibr Also reported per Part 21 VAN BRUNT.E E Arizona Public Service Co 84/03/15 018H0P.T W Division of Resident, Reactor Project & Engineering Programs 7pp 22724 353 24X Fiche 50-528,84/03/15,8403230019
- 8403300096 Interim Deficiency Rept DER 84-08 re ITT Barton Model 763 transmitters having errors of -2 to -3% of calibr span Bochtel corresponding o/C-E to determine impact of design mods to transmitters

 VAN ERUNTLE E Arizona Public Service Co 84/03/16 BISHDP.T W Division of Resident. Reactor Project & Engineering Programs 3pp 22822 010 24% Fiche 50-528.84/03/16.8403300096
- 8403300020 Rev 1 to final Deficiency Rept DER 82-44 re iTY-Barton pressure transmitters supplied by C-E failing to meet overpressure requirements Initially reported on 820824 Also reported per Part 2:

 UAN BRUNT.E E Ariona Public Service Co 84/03/19 BISHOP.T W Division of Resident, Reactor Project & Engineering Programs 7p; 22822 171 24X Fiche 50-528,84/03/19,8403300020

V Operator Examinations

- 8403290236 Forwards operations exp./ ence base.consisting of experience tables for presently licensed personnel inadequate number of personnel meet 6-uk hot participation experience requirement

 VAN BRUNT.E E Arizona Public Service Co 84/03/23 DENTON,H R

 Office of Nuclear Reactor Regulation, Director 17pp 22800 236
 24X Fiche 50-528,84/03/23.8403290236
- DOCKET STN-50-530 PALG VERDE NUCLEAR STATION. UNIT 9

 A Application/construction stage documents & correspondence
- 8403080390 Responds to FOIA request for 27 documents referenced in 1973 EIS re facilities & similiar environ documents Forwards App A Documents 1-10 Documents 1-1 & 12 available at NTIS FELTON.J M Division of Rules and Records 84/02/13 RYAN, J A Etreich, Lang, Weeks & Cardon 2pp 22381 180 24x Fichs 50-528,84/02/13,8403080390
- --8403080409 "Groundwater Conditions of Lower Hassayampa-Centennial Area. Maricopa County.AZ " Related info encl * Harshbarger & Associates R-900-74-2 74/06/30 83pp 22581 219 24x Fiche 50-528,84/02/13.8403080390
- 8403060451 Forwards request for add1 info re open environ qualification of electrical equipment items for facility KNIGHTON, G W Licensing Branch 3 84/02/27 VAN BRUNT, E E Arizona Public Service Co 5pp 22550 007 24X Fiche 50-528.84/02/27,8403060451
- 8403010212 Forwards response to 840204 telcon re draft rev to FBAR Section 3A 10 concerning low preheat fillet welding Low preheat poses no concern, principally due to low hardenability of base matts

 VAN BRUNT.E E Arisona Public Service Co 84/02/28 KNIOHTGN.0 Licensing Branch 3 4pp 22435 277 24X Fiche 50-528,84/02/28,8403010212
- 8403280043 Notification of 840320 meeting w/util & C-E in Bethesda.MD to discuss proposed testing program to demonstrate adequacy of mods to RCS pumps thermowells thermal sleeves & control element assembly shrouds LIGITRA.E A Licensing Branch 3 84/02/29 KNIGHTDN, G W Licensing Branch 3 3pp 22812 34t 24X Fiche 50-528.84/02/29, 8403280043

- B403090130 Advises that proposed leak rate acceptance criteria for Tech Spec limiting conditions for operation unacceptable, since criteria less restrictive than 1 gpm leak rate imposed on near-term OLs KNIGHTON, 6 W Licensing Branch 3 84/03/01 VAN BRUNT, E Arizona Public Service Co Zpp 22592 301 24X Fiche 50-928, 84/03/01.8403090130
- 9403150094 Forwards outstanding item list for PDR List also submitted to util
 JOHNBON,P H Region 5, Office of Director 84/03/08 ALEXANDER,I
 Region 5, Office of Director 14pp 22641 190, 24X
 Fiche 50-528,84/03/08,8402150094
- 8402090041 Board Notification 84-050 provides Commission policy statement & proposed rulemaking on environ qualifications EIBENHUT.D © Division of Licensing 84/03/14 Atomic Bafety and Licensing Board Panel 10pp 24X Fiche 50-000,84/03/14/8402090041
- 8403160048 Forwards updated preliminary description (Rev 1) for RCS demonstration test VAN BRUNTLE E. ROBERS.A C Arizona Public Service Co 84/03/14 KNIGHTON.G Licensing Branch 3 2pp 22659 169 24X Fiche 50-528,84/03/14,8403160048
- --B403160052 Rev 1 to "RCS Demonstration Test" * Ariiona Public Service Co 84/02/29 8pp 22659.171, 24X Fiche 50-528 84/03/14,8403160048
- 8403160065 Notifies that addl info & schedule re electrical equipment environ qualification program will be submitted by 840326, per 840227 request VAN BRUNT.E E Artiona Public Service Co 84/03/14 KNIGHTON, 0 Licensing Branch 3 lp 22652 326 24X Fiche 50-528, 84/03/14, 840316065
- 8403270236 Forwards Operations experience base, consisting of experience tables for presently licensed personnel Inadequate number of personnel meet 6-wk hot participation experience requirement

 VAN BRUNT, E.E. Arizona Public Service Co. 84/03/23 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 17pp 22800 236 24X Fiche 50-528,84/03/23,840290236
- C Utility Environmental Report (ER), amends & correspondence
- 8403080390 Responds to FDIA request for 27 documents referenced in 1975 EIS re facilities & similiar environ documents Forwards App A Documents 1-10 Documents 11 & 12 available at NTIS FELTON.J M Division of Rules and Records 84/02/13 RYAN.J A Streich, Lang. Weeks & Cardon 2pp 22981 180 24X Fiche 50-528.84/02/13,8403080390
- ---8403080400 Discusses review of environ rept re transmission lines crossing Indian reservations Tribal council consent should be obtained for right-of-way before environ rept published Related info encl * Interior, Dept of, Bureau of Indian Affairs 74/12/11 REGAN.W H Atomic Energy Commission - Deputy Director for Reactor Projects 5pp 22581 184 24X Fiche 50-526.84/02/13.8403080390
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- 8403080385 F0IA request for 27 documents referenced in 1975 EIS refacilities & similiar environ documents List & news articles encl
 RYAN.J.A Streich, Lang, Weeks & Cardon 84/01/17 Office of Administration 9pp 22581 171 24X Fiche 50-528,84/01/17,8403080385
- 8403080390 Responds to FOIA request for 27 documents referenced in 1975 EIS re facilities & similiar environ documents Forwards App A Documents 1-10 Documents II & 12 available at NTIB FELTON.J M Division of Rules and Records 84/02/13 RYAN.J A Streich. Lang, Weeks & Cardon 2pp 22581 180 24X Fichs 50-528,84/02/13.8403080390
- --Bi08270490 Submits Geosciences Branch DES input Updated summary of geology & seismology section FSAR will be included in SER JACKSON, R E Geosciences Branch Bi/08/14 MIRAGLIA.F Licensing Granch 3 2pp 22581 182 24X Fiche 50-528,84/02/13,8403080390
- ---8403080405 Comment on DES, per 750414 request Statement somewhat blassed toward project More detailed maps of pipeline & transmission line corridors should be provided in final statement.
 DOREMUS, S.D. Interior. Dept of 75/07/23 REGAN Division of Reactor Licensing (NRR-1975 only) 27pp 22581 189 24X
 Fiche 50-528,84/02/13,8403080390

- 8403290341 Responds to FOIA request for records re facility Ltr dtd 840117 failed to meet criteria for waiver of reproduction costs Forwards App A documents Address of Phoenix LPDR listed FELTON J M Division of Rules and Records 84/02/27 RYAN, J A Streich, Lang, Weeks & Cardon 3pp 22815 018 24X Fiche 50-528.84/02/27.8403290341
- --B403290344 DRAFT ENVIRONMENTAL STATEMENT RELATED TO CONSTRUCTION OF PALD VERDE NUCLEAR GENERATING STATION, UNITS 1, 2 & 3 Docket Nos 30-528, 30-529 & 30-530
 * Office of Nuclear Reactor Regulation, Director NUREQ-75/022 75/04/30 175pp 22815 301 24% Fiche 50-528,84/02/27, B403290734
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8403020005 Forwards info requested in SSER 5 (NUREG-0857) re tests performed for C-E on load limiting devices in reactor vessel lawer key horizontal supports VAN BRUNT, E E Arizona Public Service Co 84/02/10 KNIGHTON, G Licensing Branch 3 9pp 22442 201 24X Fiche 50-528, 84/02/10, 8403020005
- 8403090012 Forwards "High Pressure Safety Injection Pump," mechanical environ qualification rept, per 88ER 5 (NUREO-0857) VAN BRUNTLE E Arizona Public Service Co 84/02/29 KNIGHTON, O W Licensing Branch 3 2pp 22968 001 24X Fiche 50-528,84/02/29, 8403090012
- --8403070014 "High Pressure Safety Injection Pump," mechanical environ qualification rept MALLER,R E Dechtel Corp V-PAK-481 84/01/12 198pp 22566 004 24% Fiche 50-528,84/02/29,8403070012
- F Security, medical, emergency & fire protection plans
- 8402090006 Board Notification 84-034 forwards R Volumer 840206 memo to D Eisenhut re fire research results concerning fires in electrical cabinets in control room EIBENHUT,D G Division of Licensing 84/02/23 PALLADING Commissioners ip 22876 203 24X Fiche 50-000,84/02/23,8402090006
- --8403080316 Recommends that info re fire research results concerning fires in electrical cabinets in control room be submitted for board notification.per NRR OFC Ltr 19.6td 821001 Further evaluation of test data required VOLLMER.R H Division of Engineering 84/02/06 EISENHUT.D G Division of Licansing 10pp 22576 204 24X Fiche 50-000.84/02/23.8402090006
- 8403260014 Requests removal of App F & 9 from Rev 2 to Emergency Plan Implamenting Procedure 7, per Generic Ltr 81-27 & GW Knighton 840214 ltr informing that util must request withholding of private or unlisted telephone numbers VAN BRUNT.E E Arizona Public Service Co 84/03/19 KNIGHTON, CW Licensing Branch 3 2pp 22750 258 24X Fiche 50-528, 84/03/19, 8403260014
- @ Inspection reports, IE Bulletins & correspondence
- B402140014 FOIA request for records re NRC const assessment team (CAT) insp at facilities
 BERNABEI.L Government Accountability Project B3/10/07 Office of Administration 2pp 22254 001 24X Fiche 50~528, B3/10/07, B402140014
- B40214001B Responds to FDIA request for records re NRC const assessment team (CAT) insp at facilities Forwards App A documents bocuments also in PDR App B documents listed for review to identify specific interest relation. J M Division of Rules and Records 83/12/20, GARDE, B P Government Accountability Project 18pp 22254 003 24X Fiche 50-528,83/12/20,8402140018
- --8402140022 Summarizes civil insp items. Bechtel 830929 ltr re reinsp of nuclear pipe hangers (Q class) & related info encl VORDERBRUEGGEN Region 3. Office of Director 83/09/19. NARBUT,P NRC - No Detailed Affiliation Given 60pp. 22254:021 24X Ficha 50-528,83/12/20,8402140018
- --8402140031 Comments on review of draft writeup on NDE Rewrite requested Related info encl NARBUT.P NRC No Detailed Affiliation Given 83/09/27 KERCH, H NRC No Detailed Affiliation Given. 41pp 22254.094 24X Fiche 50-528.83/12/20.8402140018

- --8402140032 Summary of 830916 exit status meeting w/NRC const appraisal team re 830907-16 insp IDE.W E Arizona Public Service to 83/09/19 ROEDEL, J A Arizona Public Service to 6pp 22254 137 24X Fiche 30-528,83/12/20,8402140018
- --8402140036 Forwards marked-up draft insp scope & objectives Related info enc! ALBERT.N G Region 5. Office of Director 83/07/21 Young.T Region 5. Office of Director 180p 22254 143 24X Fiche 30-528,83/12/20,8402140018
- --8402140043 Provides list of NDE repts available from insplactivities completed w/NRC mobile NDE van at facility, per FDIA request, Related info encl EDNETER, S.D. Region 1, Office of Director 83/11/15 ALEXANDER: I.M. Region 5, Office of Director 99pp 22255 324 24X Fiche 50-528,83/12/20,8402140018
- --840214004B Rev o to "Palo Verde Station HPSI Sys Electrical & Instrumentation Const Audit Insp." final rept Related info enc!

 4 Zytar. Inc NRC-IE-82/83-46C 83/10/04 158pp 22256 063 24X Fiche 50-528.83/12/20.8402140018
- --8402140052 Provides resolution for loose bolts on structural steel found during NRC const assessment team (CAT) insp Item considered closed Related info encl FORRESTER, R D Artiona Public Service Co 83/09/24 IDE.W E Artiona Public Service Co 39p 22256 221 24X Fiche 50-328,83/12/20,8402140018
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation "Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co. of New York, Inc. 115pp 22709 239 24X Fiche 50-000.84/02/28,8401190072
- 8402090007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE.J N Division of GA, Safeguards & Inspection Programs (Post B30103) 84/03/02 Compolitated Edison Co of New York, Inc 130pp 22532 327 24X Fiche 50-000,84/03/02,8402090007.
- 8402070008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Sys Valves to Operate " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 078 24X Fiche 50-000,84/03/02,8402070008
- 8402070009 IE Info Notice 84-15, "Reporting of Radiological Releases five list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 83010J) 84/03/02 Consolidated Edison Co of New York, Inc 117pp 22553 217 24X Fiche 50-000,84/03/02,8402070009
- 8402070011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Bvc list encl JORDAN.E L. Division of Energency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402070011
- 8403140024 Informs that Bingham-Williamette spare flange piece will be replaced by 840415 instead of 840229. due to problems encountered u/vendor, per IE Bulletin 83-06, "Nonconforming Matls Supplied By Tube-Line Corp"

 VAN BRUNT. E E Arizona Public Service Co 84/03/05 MARTIN, J B Region 5. Office of Director 1p 22633 217 24X

 Fiche 50-528,84/03/05,8403140024
- 8402090024 IE Info Notice 84-09. Rev 1. "Lessons Learned From Insps of Fire Protection 8afe Shutdown Sys " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000.84/03/07.8402090024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Sys " Svc list encl JORNAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22584 186 24X Fiche, 50-000, 84/03/07, 8402090028
- 8402070031 IE Bulletin 84-02. "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Syc list encl DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24X Fiche 50-000.84/03/12.8402070031

- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PMR Reactor Cavities " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 227 24X Fiche 30-000.84/03/21,8402090043
- 8402070044 IE Info Notice 84-20. "Svc Life of Relays in Safety-Related Bys " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York Inc 135pp 22733 001 24X Fiche 50-000.84/03/21.8402090044

S Reportable occurrences, LERs & related correspondence

- 8403090087 Interim Deficiency Rept BS-Bi re Schedule 160 BS pipe supplied by Gulfalloy. Inc. containing mfg min wall thickness defect Initially reported on 831128 No new info presently available Final rept expected by 840417
 VAN BRUNT, E E Arizona fublic Service Co 84/02/22 BISHOP. T W Division of Resident, Reactor Project & Engineering Programs 2pp 22575 325 24% Fiche 50-528.84/02/22.8403090087
- 8403070258 Interim Deficiency Rept DER 83-75 re improperly torqued bolts securing two DdI265A panel filler assemblies, supplied by Foxboro No new info available at present time Final rept will be submitted by 840419

 VAN BRUNT, E E Ariona Public Service Co 84/02/22 BISHOP, T W DIV(siton of Resident, Reactor Project & Engineering Programs 2pp 22572 211 24% Fiche 50-528,84/02/22,8403090258
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines, Campel NPS-4 T&T valve, to close Encl ltr dtd 840203 sent to listed utils GE notified of affected units in BWR plants
 THEROUX.R R Terry Corp 84/02/22 WOODRUFF, R W Director's Office. Office of Inspection and Enforcement 6pp 22706 327 24X Fiche 80-000.84/02/22.8403210032
- 8402270008 Forwards response to listed items identified in 840125 telcon request for info generated based on preliminary review of 831230 deficiency rept re missing thermal liner in safety injection sys line Encls withheld VAN BRUNT.E E Arisona Public Service Co 84/02/24 KNIGHTON.O Licensing Branch 3 3pp 22516 196 24X Fiche 50-528.84/02/24, 8402270008
- 8403090094 Deficiency Rept DER 83-73 re unqualified Forboro power supplies installed in IE instrument cabinets Initially reported on 831027 No new info presently available Next rept will be provided by 840425 VAN BRUNT.E E Arizona Public Service Co 84/02/24 BISHOP.T W Division of Resident.Reactor Project & Engineering Programs 2pp 22576 179 24% Fiche 50-528.84/02/24.8403090094
- 8403090167 Interim Deficiency Rept DER 82-80 re low insulation resistance on installs6 Conax electrical penetrations not meeting qualification test criteria Initially reported on 821217 Final rept delayed until 840425
 VAN BRUNT.E E Ariona Public Service Co 84/02/24 BISHOP, T W Division of Resident.Reactor Project & Engineering Programs 2pp 22575 116 24% Fiche 50-528,84/02/24,8403090167.
- B403040429 Requests add1 info needed to complete evaluations of & fixes for reactor coolant pump problems encountered during hot functional testing Response requested within 2 wits KNIGHTON. & W. Licensing Branch 3 B4/02/27 VAN BRUNT, E Arizona Public Service Co. Spp. 22552 210 24X Fiche 50-528.84/02/27, 4003060427.
- 8403120032 Final Deficiency Rept DER 83-70 re wiring in emergency response facility cabinets supplied by Energy, Inc not in conformance w/IEEE-384 criteria Initially reported on 831011 Drawings resubmitted Also reported per Part 21 VAN BRUNT.E E Arizona Public Service Co 84/02/28 BISHOP, T W Division of Resident.Reactor Project & Engineering Programs. App 22588 025 24% Fiche 50-528,84/02/28,8403120032
- 8403120069 Final Deficiency Rept DER 83-10 re main steam relief valves supplied by C-E & mfg by Dresser Industries exceeding specified 5% bloodown limit initially reported on 830228 Deficiency determined not reportable per 10CFR50, 55(e) VAN BRUNTLE E Arizona Public Service Co 84/02/28 BISHOP, T. W Division of Resident/Reactor Project & Engineering Programs 4pp 22591 129. 24X Fiche.50-528,84/02/28,8403120069
- 8403130449 Potential Deficiency Rept DER 83-64 re Target Rock pressure relief valves failing to meet prerequisite tests Final rept delayed until 840402 VAN ERUNT.E E Arizona Public Service Co 84/02/28 BISHOP, T W Division of Resident Reactor Project & Engineering Programs. 2pp 22613 212 24X Fiche 50-528,84/02/28,8403130449

- 8403130461 Potential Deficiency Rept DER 63-68 re Borg Warner HPBI isolation valves failing to open against HPBI A & B pump flows Final will rept delayed until 640417 VAN BRUNT.E E Arizona Public Service Co 84/02/28 BISHOP.T W Division of Resident.Reactor Project & Engineering Programs 2pp 22613 355 24X Fiche 50-528.84/02/28.8403130461
- 8403200115 Interim Deficiency Rept DER 83-80 re Anchor Darling main feedwater isolation valves closing in 20 s.violating 5 s spec requirement Initially reported on 831122 Final rept will be delayed until 840403 due to extensive investigation VAN BRUNT.E E Arizona Public Service CO 84/03/02 BISHOP.T W Division of Resident.Reactor Project & Engineering Programs 2pp 22485 335 24X Fiche 50-528,84/03/02.8403200115
- B403200160 Interim Deficiency Rept DER B4-07 re extension of Borg Warner va]ve stems & failure to provide corrective action stated in Rept DER 80-21 Initially reported on 840209 Bechtel investigating corrections Final rept by 840414 VAN BRUNT.E E Arizona Public Service Co 84/03/02. BISHOP, Y W DIVISION OF RESIDENT PROPERTY OF THE PR
- 8403200186 Interim Daficiency Rept DER 83-86 re discrepancies w/MSIVs mfg by Anchor-Darling Initially reported on 830808 Investigation will be finalized by 840413 at which time complete rept will be submitted VAN BRUNT, E E Arizona Public Service Co 84/03/08 BISHOP, T W Division of Resident Reactor Project & Engineering Programs 2pp 22686 357 24% Fiche 50-328,84/03/08,8403200186
- B403200226 Interim Deficiency Rept DER 84-06 re defective absolute & deviation alarm modules supplied by Foxboro C-E requested that all alarm modules w/date Codes 8048-8152 be inspected for potential defect Next rept by 840612 VAN SRUNT, E E Arizona Public Service Co 84/03/07 BISHOP, T W Division of Resident. Reactor Project & Engineering Programs 3pp 22697 338 24% Fiche 50-528,84/03/07,8403200226
- 8403230039 Final Deficiency Rept DER-83-79 re ac interference spikes on 125-volt dc bus exceeding spec Initially reported on 831118 Deficiency deemed not reportable per 10CFR80 55(e) VAN DRUNT, E E Arizona Public Service Co 84/03/09 BISHOP, T. W Division of Resident/Reactor Project & Engineering Programs 4pp 22730 302 24X Fiche 50-528.84/03/09.8403230039
- 8403230086 Final Deficiency Rept DER 83-60 re failure of wiring in Vitro main steam & feedwater activation sys to meet IEEE-384 separation criteria Condition determined not reportable per IOCFRSD 55(s)

 VAN BRUNT, E Arizona Public Service Co 84/03/07 BISHDP, T W Division of Resident, Reactor Project & Engineering Programs 4pp. 22724 339 24X Fiche 50-530, 84/03/09, 8403230086
- B403230099 Final Deficiency Rept DER B3-72 re undersize welds in auxiliary bldg Initially reported on B31026 Condition determined not reportable per 10CFR50 55(e) VAN BRUNT, E E Arizona Public Service Co 84/03/14 DISHOP, T. W Division of Resident, Reactor Project & Engineering Programs 6pp 22728:335 24X Fiche 90-528, B4/03/14:8403230099
- 8403230019 Final Deficiency Rept DER 82-45 re ITT Barton pressure transmitters supplied by C-E not meeting overpressure requirements Caused by leakage of metallic washers & methodology error during calibr Also reported per Part 21 VAN BRUNT, E. E. Arizona Public Service Co. 84/03/15 BISHOP, T W Division of Resident/Reactor Project & Engineering Programs 7pp 22724 353 24% Fiche 50-528,84/03/15,8403230019
- 8403300096 Interim Deficiency Rept DER 84-08 re ITT Barton Model 763 transmitters having errors of -2 to -3% of calibr span Bechtel corresponding w/C-E to determine impact of design mods to transmitters

 VAN BRUNT, E E Arizona Public Service Co 84/03/16 BISHOP, T W Division of Resident, Reactor Project & Engineering Programs. 3pp 22822 010. 24% Fiche 50-529,84/03/16,8403300096
- 8403300020 Rev 1 to final Deficiency Rept DER 82-46 re ITT-Barton pressure transmitters supplied by C-E failing to meet overpressure requirements Initially reported on 820824 Also reported per Part 21 VAN DRUNT.E E Arizona Public Service Co 84/03/19, BIGHOP.T W Division of Resident, Reactor Project & Engineering Programs 7pp 22822.171 24X Fiche 50-528,84/03/19,8403300020

V Operator Examinations

8403290236 Forwards operations experience base, consisting of experience tables for presently licensed personnel Inadequate number of personnel meet 6-wk hot participation experience requirement

VAN BRUNT, E E Arizona Public Service Co 84/03/23 DENTON, H R
Office of Nuclear Reactor Regulation, Director 17pp 22800 236
24X Fiche 50-528, 84/03/23, 8403290236.

DOCKET 50-537 CLINCH RIVER BREEDER REACTOR

- A Application/construction stage documents & correspondence
- 8403090219 Forwards applicant responses to Commission 811224 order on bahalf of Project Mgt Corp & TVA
 CHIPMAN 9 L Energy, Dept of 82/01/18 PALLADINO N J ,
 GILINSKY, V , ROBERTS, T F Commissioners 101pp 22574:168 24X
 Ficha 50-537,82/01/18.8403090219
- 8403020014 Partial response to FOIA request for seven categories of documents re NRC regionalization program App A documents in PDR. Review of remaining documents incomplete FELTON, J M Division of Rules and Records 83/12/16 LOWENTHAL, J Nuclear Information & Resource Service 3pp 22472 248, 24% Fichs, 50-000, 83/12/16, 8403020014
- --8403020051 Informs that MK Udall Subcommittee on Energy & Environ marked-up & reported 1984-85 NRC authorization bill to Interior Committee for future consideration NRC authorization bill HR 2510 & 830420 amends encl KAMMERER. C Office of Congressional Affairs 83/04/20 PALLADING, 01LINGKY, AMERINE Commissioners. 11pp 22493 326 24X Fiche 50-000,83/12/16.8403020014
- 8403080070 Forwards Page 15 inadvertently omitted from 840227 transmittal of draft CRBR plant redress plan. Related correspondence.

 OROSS.P. J. Energy, Dept. of, Clinch River Breeder Reactor Plant 84/03/02 KINQ.T. Clinch River Breeder Reactor Program Office 2pp 22559 265. 24X Fiche 50-537.84/03/02.8403080090
- 8403060357 Forwards "Bite Redress Plan" Minor clarifications & corrections to draft plan submitted 840227 made in response to NRC comments GAVIGAN.F X Energy, Dept of 84/03/05 KING.T Clinch River Breader Reactor Program Office 1p 22519 169 24X Fiche 30-537,84/03/05,8403060337
- --8403060360 "Site Redress Plan "

 * Energy, Dept of 84/03/31 36pp 22519 170 24x
 Fiche 50-537,84/03/05,8403060357
- 8403230216 AN ASSESSMENT OF CRBR CORE DISRUPTIVE ACCIDENT ENERGETICS THEOFANOUS.T 0 , BELL.C R. Los Alamos Scientific Laboratory Fin A-7271 NUREO/CR-3224 B4/03/31 Clinch Rivar Breeder Reactor Program Office 436pp Available at NRC 88 50 22740:001. 24X Fiche.50-537.84/03/31.8403230216

O Adjudicatory correspondence

- 840305006B Memorandum & order denying appeals of ABLB determination to limit intervenor participation in proceedings on remand to limited appearance statement. Opinion of Dr Johnson and I. TOMPRING B A Atomic Safety and Licensing Appeal Panel 84/02/29 16pp 22490 1644 24X Fiche 50-537.84/02/29.8403050068
- 8403020100 Forwards Page 15 of CRBR program redress plan, inadvertently omitted from 840227 transmittal Certificate of Svc enc. 1 ED0AR, G L. Neuman & Holtzinger ED0AR, G L. Project Management Corp 84/03/01 MILLER, M E , HAND, C. LINENBERGER, G Atomic Safety and Licensing Board Panel. 3pp 22442, 096 24X Fichs, 50-537, 84/03/01, 8403020100.
- 8403060082 Patition for review of Appeal Board 840227 mamorandum & order readmitting intervenors to proceedings Intervenor participation will protract proceeding for project which is terminated Certificate of Svc encl EDGAR, G.L. Project Management Corp LUCK, W D Energy, Dept. of, 84/03/05, 4pp 22516 345 24X Fiche 50-537,84/03/05,8403060082
- B403070056 Forwards final CRBR site radress plan for review & approval Related correspondence M/o encl GAVIGAN, F.X. Energy, Dept of 84/03/05, KIND, T. Clinch River Breeder Reactor Program Office ip 22375, 349 24X Fiche, 30-537, 84/03/05, 8403070054
- 8403090084 Confirms that ASLS intends to vacate notice of 840314 conference & reschedule later date due to delay in funding for review of redress plan & possible lack of availability of one ASLS member. Certificate of Svc encl EDGAR. G. L. Newman & Holtzinger EDGAR. G. L. Project Management Corp 84/03/08, MILLER. M. E. HAND. C., LINENBERGER. G. Atomic Safet and Licensing Board Panel. Spp. 22579:320, 24X Fiche: 50-537.84/03/08.8403090086.

- B403190047 Informs of receipt & consideration of B40305 patition for Commission review of ALAB-761 re readmitting intervenors to proceeding Staff prepared to file brief addressing issues in event Commission grants patition for review TREBY. B A Hearing Branch 1 B4703/15 CHILK. B J Office of the Secretary of the Cammission in 22666 250 24X Fiche 50-537.84/03/15.8403190047
- 8403190120 Answer to applicant petition for review of ASLB 840227 memorandum & order re CRBR LWA proceedings on site redress plan Intervenors main contern is that redress be rapid & effective W/Certificate of Svc FINAMORE.B A Natural Resources Defense Council FINAMORE.D A Sierra Club 84/03/15 Commissioners 10p 22666 276 24% Fichs 50-537,84/03/15.8403190120
- DOCKET 50-538 MEMPHIS STATE UNIV RESEARCH REACTOR

 R Periodic operating reports & related correspondence
- 8403230060 "Annual Rept of Nuclear Reactor Operations, 1983 " W/840319 ltr JUNES, D H., DIETZ, R L. Hemphis State Univ. Hemphis, TN 83/12/31 18pp. 22730:284 24X Ficha 50-538, 83/12/31,8403230060
- DOCKET STN-50-546 MARBLE HILL NUCLEAR STATION, UNIT L

 A Application/construction stage documents & correspondence
- B4030B0179 Fourth partial response to FDIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FDIA Exemption 5) Review of add1 documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, 8 1 Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000,84/02/13,84030B0179
- F Security, medical, emergency & fire protection plans
- 8403120058 Notifies of 840323 workshop on fire protection safe shutdown requirements of 10CFR50. App R in Rosemont, IL to discuss IE Info Notice 84-07 & provide addl shutdown analyses &/or mod guidance. Agenda encl SPE68ARD. R L Division of Emergency Preparedness & Operational Support 84/03/06 SHIELDS. 8 H Public Service Co of Indianalinc 3pp 22586 882 24% Fiche 50-546,84/03/04,8403120058
- @ Inspection reports: IE Bulletins & correspondence
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl URDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Editor Co of New York, Inc. 115pp 22909 239, 24X Fiche 50-000,84/02/28,8401190072
- 8402090007 IE Info Notice 84-14. "Highlights of Recent Transport Regulatory Revs by DDT & NRC " Svc list encl ORACE.J N Division of QA. Safeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc. 130pp 22552 329 24X Fiths 50-000.84/03/02,8402090007.
- 8402070008 IE Info Notice 84-16. "Failure of Automatic Sprinkler Bys Valves to Operate." Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103). B4/03/02 Consolidated Edison Co of New York, Inc 122pp 22553 098 24X Fiche 50-000,84/03/02,8402090008
- B402090009 IE Info Notice 84-15, "Reporting of Radiological Releases"
 Svc list encl.
 JORDANIE L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc. 11989 22553 217 24X Fiche 50-000,84/03/02,8402090009
- 8402070011 IE Info Notice 84-17, "Problems W/Liquid Nitragen Cooling Components Below Nil Ductility Temp " Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc. 117pp 22553 336 24X Fiche 50-000,84/03/05,8402070011
- B402070024 IE Info Notice 84-09, Rev 1. "Lessons Learned From Ineps of Fire Protection Sefs Shutdown Sys " Syc list snc1.

 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07. Consolidated Edison Co. of New York, Inc. 118pp. 22635 049. 24X Fiche. 50-000, 84/03/07, 8402070024

- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR 102070028 IE Into Novice C. Sys "Syc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 (86 24X Fiche 50-000,84/03/07,8402090028
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl DEYBUNG.R C Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823 094 24% Fiche 50-000.84/03/12.8402090031
- 8403190286 Discusses Dept of Labor decision re 830120 termination of electrical contractor personnel & forwards notice of violation KEPPLER,J G Region 3, Office of Director 84/03/14 SHI Public Service Co of Indiana, Inc 2pp 22673 196 24X Fiche 50-546,84/03/14,8403190286
- -9403190294 Notice of violation based on investigation & hearing by Dept of Labor Noncompliance noted discrimination by licenses or contractor against employee for engaging in certain protected activities KEPPLER, J G Region 3, Office of Director 84/03/14 2pp. REPPLER, J.G. Region 3, Office of Director 84/ 22673 188 24% Fiche 50-546,84/03/14,8403(90286
- 8402070043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list ancl URRDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 123pp 22823 229 24% Fiche 50-000,84/03/21,8402070043 123pp
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Svc list encl OGRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22733 001 24% Fithe 50-000,84/03/21,8402070044
- S Reportable occurrences, LERs & related correspondence
- 8493140122 Part 21 rept re status update concerning abnormal wear on linear converters Test program underway Results of investigation indicate excessive wear caused by hunting of control circuitry ODDSDN.JP Pacific Air Products Co 84/03/09 Director' Office, Office of Inspection and Enforcement 7pp 22624 06 Fiche 50-000,84/03/09,8403140122 22624 068 24X
- 8403270219 Part 21 rept re broken contact carrier in control device of 7 5 kV-15 kV,500-750 MVA.5 kV 350-3.000 & all HKV circuit breakers initially reported on 830223 Addenda to installation & maint procedures sent to affected units DUVALL,D D Brown Boveri Corp (subs of Brown Boveri Co . Ltd) 84/03/19 Record Services Branch (Oocument Control Desk). Spp 22772 114 24X Fiche 50-000,84/03/19,8403270219
- DOCKET SIN-50-547 MARBLE HILL NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of addi documents subj to request continuing FELTON.J M Division of Rules and Records 84/02/13 Garvey, Schubert, Adams & Barer 7pp 22583 226 2 Fiche 50-000.84/02/13.8403080179 la ANDERSON, S I
- F Security, medical, emergency & fire protection plans
- 8403120058 Notifies of 840323 workshop on fire protection safe shutdown requirements of iOCFR50.App R in Rosemont.IL to discuss IE Info Notice 84-09 & provide add1 shutdown analyses 5/or mod guidance Agenda enc1

 SPESSARD, R L Division of Emergency Preparedness & Operational

 Support 84/03/06 SHIELDS, S W Public Service Co of Indiana,

 Inc 3pp 2258 282 24% Fiche 50-546, 84/03/06, 8403120058
- G Inspection reports, IE Bulletins & correspondence
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Syc list JORDAN, E.L. Division of Emargency Preparedness & Engineering Response (Post 830103) 84/02/28 Consplidated Edison Co. of New York, Inc. 115pp 22909 239 24X Fiche 30-000.84/02/28,8401190072

- 8402090007 IE Info Notice 64-14. "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE. J N Division of QA. Safeguards & Inspection Programs (Post 830103) 84703/02 Consolidated Edison Co of New York. Inc 130pp 22552 329 24X Fiche 50-000.84/03/02,8402070007
- 8402090008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate" Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co. of No York, Inc. 122pp 22553 098 24% Fiche 50-000,84/03/02,8402090008
- 8402070007 IE Info Notice 84-15, "Reporting of Radiological Releases" Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Past B30103) 84/03/02 Cansolidated Edison Co of New Yark, Inc 119pp 22593 217 24X Fiche 50-000.84/03/02,8402070007
- 8402070011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling 02099011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Gelow Nil Ductility Temp "Svc list encl JARDAN. EL Division of Emergency Preparadness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fichs 50-000.84/03/05, 84020900[1
- 8402090024 JE info Notice 84-09.Rev i, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Phast 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22635 049 24X Fiche 50-000,84/03/07,8402090024
- 8402070028 I£ Info Notice 84-18. "Stress Corresion Cracking in PWR 102090028 IE Info Notice on 10.

 Bys "Svc list encl
 JUBBAN: EL Division of Emergency Preparedness & Engineering
 JUBBAN: EL Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/07 Consolidated Edison Co of New
 York, Inc 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- B402090031 IE Bulletin 84-02, "Failures of GE Type HFA Relays in Use in Class IE Safety Sys " Svc list encl DEYOUNG: R C Director's Office Office of Inspection and Enforcement B4/03/12 Consolidated Edison Co of New York
- 8403190286 Discusses Dept of Labor decision re 830120 termination of electrical contractor personnel & forwards notice of 84/03/14 8H violation KEPPLER, J G Region 3, Office of Director 84/03/14 Public Service Co of Indiana, Inc 2pp 22673 186 Fiche 50-546,84/03/14,8403190286 SHIELDS S W
- ---8403170294 Notice of violation based on investigation & hearing by 403190299 Notice of Violation based on investigation & hearin Dept of Labor Noncompliance noted discrimination by licensee or contractor against employee for engaging in certain protected activities KEFPLER, J G Region 3, Office of Director 84/03/14 2pp 22673 IBB 24X Fiche 50-546,84/03/14,8403190286
- 8402090043 IE Info Natice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities" Svc list encl JORDAN, E. L. Division of Emergency Proparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co. of P. 22823 227 24X Fiche 50-000,84/03/21,8402090043 123pp
- 8402090044 IE Info Notice 84-20, "Syc Life of Relaus in Safety-Related Byc list encl Sys " Syc list enci JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24X Fiche 50-000,84/03/21,8402090044
- S Reportable occurrences, LERs & related correspondence
- B403140122 Part 21 rept re status update concerning abnormal wear on linear converters Test program underway Results of investigation indicate excessive wear caused by hunting of Control circuitry
 DDDSON.J P Pacific Air Products Co 84/03/09 9 Director's 7pp 22624 068 24% DODSON, J.P. Pacific Air Products Co. 84/03/0 Office, Office of Inspection and Enforcement Fiche 50-000, 84/03/09,8403140122
- 8403270219 Part 21 rept re broken contact carrier in control device of 7 5 kV-15 kV.500-750 MVA.5 kV 350-3.000 & all HKV circuit breakers Initially reported on 830223 Addenda to DIVALL, D.D. Brown Boveri Corp (subs of Brown Boveri & Co., Ltd.)

 84/03/19 Record Services Branch (Document Control Desk.) 5pp. 22772 114 24X Fiche 80-000, 84/03/19, 8403270219

- DOCKET STN-50-553 PHIPPS BEND NUCLEAR STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- B403160345 Extends invitation to attend region 840316 workshop at regional ofc to discuss 100FR50. App R requirements & recent results of insp to help resolve misunderstandings associated w/requirements

 LEWIS, R C Division of Project & Resident Programs 84/03/02 PARRIS, H Q Tennessee Valley Authority 2pp 22660 083 24X Fishe 50-000.84/03/02.8403160345
- S Reportable occurrences, LERs & related correspondence
- 8403230028 Followup Part 21 rept re nuclear valve/actuator stroking time possibly lengthered beyond 15 s when using hydrocarbon-based lubricants Ltrs to affected utils encl WILSON, A K Henry Pratt Co 84/03/08 KEPPLER.J G Region 3. Office of Director App 22730 306 24X Fiche.50-000,84/03/08,8403230028
- B403270219 Part 21 rept re broken contact carrier in control device of 7 5 kV-15 kV.500-790 MVA.5 kV 350-3.000 & all HKV circuit breakers initially reported on B30223 Addenda to installation & maint procedures sent to affected units.

 DUVALL,D D Brown Boveri Corp. (subs of Brown Boveri & Co , Ltd) B4/03/19 Record Services Branch (Document Control Desk) 5pp 22772.114 24X Fiche 30-000.84/03/19.8403270219
- DOCKET 8TN-50-554 PHIPPS BEND NUCLEAR STATION, UNIT 2

 8 Reportable occurrences, LERS & related correspondence
- 8403230028 Followup Part 21 rept re nuclear valve/actuator stroking time possibly lengthened beyond 15 s when using hydrocarbon-based lubricants Ltrs to affected utils encl WILSON, A K Henry Pratt Co 84/03/08 KEPPLER, J @ Region 3, Office of Director. App 22730 306 24% Fiche 50~000,84/03/08,8403230028
- 8403270219 Part 21 rept re broken contact carrier in control device of 7.5 kV-15 kV.500-750 MVA,5 kV 350-3.000 & all HKV circuit breakers Initially reported on 830223 Addenda to installation & maint procedures sent to affected units. DUVALL,D D Brown Boveri Corp (subs of Brown Boveri & Co , Ltd) 84/03/19 Record Services Branch (Document Control Desk) 3pp 22772 i14 24X Ficha 50-000.84/03/19.8403270219

DOCKET STN-50-556 BLACK FOX STATION, UNIT 1

A Application/construction stage documents & correspondence

- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document antirely withheld (ref FOIA Exemption 5) Review of addI documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, S I Garvey, Schubert, Adams & Barer 7pp. 22583 224 24X Fiche 50-000,84/02/13,8403080179
- --Bio2200027 Forwards action glam for resolution of non-TMI issues for punding CP/mfg license applications, per Ofc of Nuclear Reactor Regulation approach to resumption of licensing Bafety evaluation inputs should be provided by 810601.
 EIBENHUT.D.G. Division of Licensing 80/12/31. VOLLMER, R Division of Engineering 1p 22583 277 24X Fiche 50-000,84/02/13,8403080179

G. Adjudicatory correspondence

- 840:301:0050 Third partial response to FOIA request for six categories of documents re facility. Forwards App A documents. App A documents also placed in PDR App 8 documents will be placed in PDR upon request Review continuing FELTON. J. M Division of Rules and Records 84/01/17 ANDERSON. S J Garvey, Schubert, Adams & Barer. 4pp 22446 273 24X Fiche. 50-000, 84/01/17, 8403010050
- ---B2(1090018 Advises that branch will wait to determine what action util plans to take in response to ABLB 820618 order before collecting prof NRC hours & contractual costs & billing util for review of withdrawn application
 MILLER, W.O. License Fee Hanagement Branch 82/10/04 License
 Fee Management Branch, ip 22446:323 24X Fichs 50-000,84/01/17, 8403010050

- --8305090504 Requests advice refee assessment cutoff date for reactor CP & OL applications that are withdrawn.denied.suspended, cancelled or postponed
 MILLER, W O License fee Management Branch 83/05/04 FONNER, R L
 Office of the Executive Legal Director 3pp 22446 315 24X
 Fiche 50-000,84/01/17,8403010050
- B403230186 Requests reconsideration of 801009 split vote to release Reed Rept & Sub-Task Force Repts Return of repts requested Separate views of Commissioner Hendrie & Certificate of Svc encl
 EDOAR.O L. Newman & Holtzinger EDOAR.O L. Oeneral Electric Co DSB 073 84/03/22 PALLADING.N J. ASSELSTINE.J K., ROBERTS.T M COMMISSIONERS 11pp 22743 061 24% Fiche 50-556.84/03/22,
- DOCKET STN-50-957 BLACK FOX STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8403080177 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of addl documents subj to request continuing FELTON. J M Division of Rules and Records 84/02/13 ANDERSON, 8 I Garvey, Schubert, Adams & Barer 7pp 22583 226 24% Fiche 50-000.84/02/13.8403080179
- ---8102200027 Forwards action plan for resolution of non-TMI issues for pending CP/mfg license applications, per Ofc of Nuclear Reactor Regulation approach to resumption of licensing Safety evaluation inputs should be provided by \$10201 EISENHUT. D 0 Division of Licensing 80/12/31 VOLLMER, R Division of Engineering 1p 22583 277 24X Fiche 50-000,84/02/13,8403080179
- O Adjudicatory correspondence
- 8403010050 Third partial response to FOIA request for six categories of documents re facility Forwards App A documents App A documents also placed in PDR App B documents will be placed in PDR upon request Review continuing FELTON.J M Division of Rules and Records 84/01/17 ANDERSON.S I Garvey, Schubert, Adams & Barer App 22446 293 24% Fiche 50-000.84/01/17.8403010050
- --B211090018 Advises that branch will wait to determine what action util plans to take in response to ASLB B20618 order before collecting prof NRC hours & contractual costs & billing util for review of withdrawn application
 MILLER, W O License Fee Management Branch 82/10/04 License Fee Management Branch 82/10/04 Cicense Fee Management Branch 1p 22446 323 24X Fiche 50-000,84/01/17,8403010050
- --B305090506 Requests advice re fee assessment outoff date for reactor CP & OL applications that are withdrawn denied suspended, cancelled or postpone6
 MILLER, W O License Fee Management Branch B3/05/04 FONNER, R L
 Office of the Executive Legal Director 3pp 22446 315 24X
 Fiche 30-000,84/01/17,8403010050
- 8403230186 Requests reconsideration of 801009 split vote to release Reed Rept & Sub-Task Force Repts Return of repts requested Separate views of Commissioner Hendrie & Certificate of Svc and I EDDAR, O L Newman & Holtzinger EDDAR, O L General Electric Co DBB 073 84703/22 PALLADIND, N J ASSELGTINE, J K RDBERTS, T M Commissioners 11pp 22743 061 24X Fiche 50-356,84/03/22, 840320186
- DOCKET STN-50-566 YELLOW CREEK NUCLEAR PLANT, UNIT i F Security, medical, emergency & fire protection plans
- 8403280233 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by license, per BiO709 Generic Ltr 81-27 W/o request entire plan will be placed in PDR KNIGHTON-0 W Licensing Branch 3 84/03/07 PARRIS.H 0 Tennessee Valley Authority 3pp. 22789 341 24X Ficher 50-566, 84/03/07, 8403280233
- 8 Reportable occurrences, LERs & related correspondence
- 8403270219 Part 21 rept re broken contact carrier in control device of 7 5 kV-15 kV, 500-750 MVA: 5 kV 350-3.000 & all HKV circuit breakers Initially reported on 830223 Addenda to installation & maint procedures sent to affected units DUVALL. D D Brown Boveri Carp. (subs of Brown Boveri & Co . Ltd ? 84/03/19 Record Services Branch (Document Control Desk) 5pp 22772 114 24X Fiche 50-000.84/03/19.8403270219

DOCKET STN-50-567 YELLOW CREEK NUCLEAR PLANT, UNIT 2 F Security, medical, emergency & fire protection plans

8403280233 Advises that NRC will not review emergency plans to delete privacy or proprietary info unless specifically requested by license per 810709 Generic Ltr 81-27 W/o request-entire plan will be placed in PDR KNIGHTON.G W Licensing Branch 3 84/03/07 PARRIS, H O Tennessee Valley Authority 3pp 22789 341 24X Fiche 50-566, 84/03/07, pagn380233

S Reportable occurrences. LERs & related correspondence

8403270219 Part 21 rept re broken contact carrier in control device of 7 5 kV-15 kV.500-750 MVA.5 kV 350-3.000 & all HKV circuit breakers initially reported on 830223 Addenda to installation & maint procedures sent to affected units DUVALL.D D Brown Boveri Corp (subs of Brown Boveri & Co., Ltd.) 84/03/19 Record Services Branch (Document Control Dest) 5pp 22772 114 24K Fiche 30-000.84/03/19.8403270219

DOMESTIC LICENSING OF SPECIAL NUCLEAR MATERIAL

BUCKET 70-0027 BABCOCK & WILCOX CO . LYNCHBURG, VA

- 8401240304 Ack receipt of 831214 ltr informing NRC of steps taten to correct violations noted in IE Insp Rept 70-0027/83-19
 D'REILLYJ P Region 2. Office of Director 84/01/10 ECKERT.J P Babcack ? Wilcox Co ip 21909 237
- --8401240315 Responds to NRC 831115 ltr re violations noted in IE Insp Rept 70-0027/83-19 Corrective actions sys of notification established when byproduct license certification requested & health physicist added to radiation control staff ECKERT.JP Babcock & Wilcox Co 83/12/14 O'REILLY.JP Region 2. Office of Director 8pp 21909 238
- 8403220167 Application for amend to License SNM-42, revising Section IV re fundamental nuclear matis control plan to provide production scheduling flexibility for research reactor fuel Amend fee enc!

 * Babcock & Wilcox Co 84/01/31 BRUWN,W B Fuel Facility Safeguards Licensing Branch ip 22491 134
- 8403090197 Requests all correspondence distributed to NRC regional ofc re SNM mat) control & accounting & physical protection Correspondence will enable more timely awareness of issues that may exist w/regional ofc BROUNN W B Fuel Facility Safeguards Licensing Branch 84/02/07 REGAN, W Babcock & Wilcox Co 2pp 22528 192
- 8403070146 Ack receipt of 830708,1007 & 1214 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0027/83-14 STOHR.JP Division of Emergency Preparedness & Materials Eafety 84/02/08 ECKERT.JP Babcock & Wilcor Co ip 22547 267
- --8403070149 Responds to NRC 831117 ltr re violations hoted in IE Insp Rept 70-0027/83-14 Corrective actions control limits for each std will be calculated from data generated for each std within one inventory period ECKERT.JP Babcock & Wilcox Cp 83/12/14 O'REILLY.JP Region 2. Office of Director 2pp 22347 288
- --8403070153 Responds to NRC 830811 litr re violations noted in IE Insp Rept 70-0027/83-14 Corrective actions control limits for finished fuel UNH dissolver feed & isotopic measurement sys recomputed ECKERT.J P Babcock & Wilcox Co 83/09/08 O'REILLY.J P Region 2. Office of Director 3pp 22547 270
- 8403300041 Forwards IE Insp Rept 70-0027/84-02 on 840123-27 STOHR.J P Division of Emergency Preparedness & Materials Safety 84/02/15 ECKERT,J P Babcock & Wilcox Co 2pp 22821 340
- --B403300044 IE Insp Rept 70-0027/B4-02 on B40123-27 Noncompliance noted failure of guards of carry all required equipment & adequately test & maintain protected area fence Details withheld ENNIS.J D Region 2. Office of Director MCOUIRE D R Division of Emergency Praparedness & Materials Bafety B4/02/14 ip. 22821 342
- 8403050205 Forwards request for add1 info re 840126 request for exemption from 10CFR70 38(1)(2) re long-term storage of scrap Encl withheld (ref 10CFR2 790)
 BROWN. H B Fuel Facslituty Safeguards Licensing Branch 84/02/21
 REGAN, N A Babcock & Wilcox Co 1p 22528 154

- 8403070326 Forwards IE Insp Rept 70~0027/84-03 on 840124-27 No violations or deviations identified STOHR, J P Division of Emergency Preparedness & Materials Safety 84/02/23 ECKERT, J P Babcock & Wilcox Co 1p 22346 328
- --B403070328 IE Insp Rept 70-0027/84-03 on 840124-27 No noncompliance noted Major areas inspected mgt of meth control sys & internal control Details withheld (ref 100FR2 790 & 73 21)

 JONES, D. W. Region 2. Office of Director MCALPINE, E. J. Division of Emergency Preparedness & Materials Safety B4/02/15 ip
- 8403050361 Responds to 840131 & 0216 ltrs re Ontario-Hydro scrap processing contract B&W will composite isotopic samples of dissolver solution on U-weighted daily basis & assay each composite for U-235 BROWN, W B Fuel Facility Bafeguards Licensing Branch 84/02/24 TRENT.L K Babcock & Wilcox Co 1p 22501 338
- 8403160286 Forwards proprietary IE Insp Rept 70-0027/84-01 on 840116-20 No violations or deviations identified Rept withheld (ref 100FR2 790 & 73 21) 8TQHR,J P Division of Emergency Preparedness & Materials Safety 84/03/07 ECKERT,J P Babcock & Wilcox Co 2pp 22660 203
- 8403260179 Forwards IE Insp Rept 70-0027/84-05 on 840312-16. No violations or deviations noted STORA, J P Division of Emergency Preparedness & Materials Safety 84/03/22 ECKERT, J P Babcock & Wilcox Co 2pp 22756 150.
- --8403260183 IE Insp Rept 70-0027/84-05 on 840312-16 No noncompliance noted Major areas inspected security organization, records & repts, locks, keys & combinations & physical barriers Details withheld (ref lock785) ENNIS.J D Region 2. Office of Director MCGUIRE, D R Division of Emergency Preparedness & Materials Safety 84/03/22 ip 22756-152
- B40330001% Ack receipt of B40315 ltr informing NRG of steps taken to correct violations noted in IE Safeguards Insp Rept 70-0027/84-02 STONR, J P Division of Emergency Preparedness & Materials Safety B4/03/86 ECKERT, J P Babcock & Wilcox Co ip 22822 137
- --8403300015 Responds to NRC 840215 ltr re violations noted in [E Safeguards Inap Ropt 70-0027/84-02 Corrective actions Withheld (ref 10CFR2 790) ECKERT.J P Babtock & Wilcox Co 84/03/15 D'REILLY.J P Region 2. Office of Director 1p 22822 138
- 8403270267 ENVIRONMENTAL IMPACT APPRAISAL FOR RENEWAL OF SPECIAL NUCLEAR MATERIAL LICENSE NO SMM-42 Docket No 70-27 (Babcock & Wilcox Company, Nava) Nuclear Fuel Division) * Division of Fuel Cycle & Material Safety NUREO-1049 84/03/31 87pp Available at NRC \$4 50 22787 233

DOCKET 70-0036 COMBUSTION ENGINEERING, INC . WINDSOR, CT

- 8403270273 Informs of issuance of Amend 1 to License SNM-33 re decommissioning of evaporation ponds PAGE,R.O Uranium Fuel Licensing Branch 84/03/08 ESKRIDGE,H E Combustion Engineering, Inc. 1p 22789 264
- DOCKET 70-0143 NUCLEAR FUEL BERVICES, INC , ERWIN, TN
- 8403030363 Grants 840117 request for 7-day extension for completing certain requirements of 10CFR70 5(e)(4) for 831228 high-enriched U physical inventory, BURNETF, RF Division of Safeguards 84/01/19 HENSLEY, K. D. Nuclear Fuel Services, Inc (subs of Getty 011 Co) 1p 22327 317
- 8403160325 Forwards IE Enforcement Conference Rept 70-0143/84-06 on 840216 Print Pri
- --B403160387 IE Enforcement Conference Rept 70-0143/84-04 on B40216 Major areas discussed nuclear criticality safety violations. KANLE, J B Region 2, Office of Director. HCALPINE, E J. Division of Emergency Preparedness & Materials Bafety 84/02/24 Opp. 22639 159

i

- 8403020196 PNO-II-84-017 on 840227, power to plant lost due to power outage caused by high winds Licensee declared unusual event & initiated plant radiological contingency plan Backup power continued to function
 KAHLE, J B , MCALPINE, E J Region 2, Office of Director 84/02/27 2pp. 22437 001
- 8403160337 Forwards IE Safeguards Insp Rept 70-0143/84-02 on 840130-0203 No violations or deviations identified 8TCHR.J P Division of Emergency Preparedness & Materials Bafety 84/02/27 GUIN.F K Nuclear Fuel Services, Inc (subs of Getty Qil Co) 2pp 22660 ii8
- --B403160353 IE Bafeguards Insp Rept 70-0143/84-02 on B40130-0204 No noncompliance noted Major areas inspected measurements & statistical controls Details withheld (ref 10CFR2 790 & 73 21) RICHARDS, B L. Region 2, Office of Director MCALPINE, E. J. Division of Emergency Preparadness & Materials Bafety 84/02/27 ip 22660 120
- 8403050220 Responds to 831221 ltr w/two requests for exemption from 10CFR70 57(b)(ii) re control charts first request approved New License Condition 4 10 to Amend MPP-1 to License SNM-124 encl Second request requires addl demonstration BROWN.W B Fuel Facility Bafeguards Licensing Branch 84/02/28 HENSLEY, K D Nuclear Fuel Services, Inc (subs of Getty Oil Co) 4pp 22028 110
- 8403160138 Ack receipt of 840201 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 70-0143/83-47 STDHR, J P Division of Emergency Preparedness & Materials Safety 84/02/28 QUINN,F K Nuclear Fuel Services, Inc (subs of Getty Dit Co) ip 22655 210
- --8403160173 Forwards IE Insp Rept 70-0143/83-47 on B31003-1202 & notice of violation Notice of violation & insp rept withheld (ref 10CFR2 770)
 STOHR, J P Division of Emergency Preparedness & Materials Safety 84/01/05 GUINN, F & Nuclear Fuel Services, Inc (subs of Getty Gil Co) 2pp 22655 214
- 8403140377 Discusses IE Enforcement Conference Rept 70-0143/84-06 on 840216. Item 3 a of licensee commitments on Page 2 of rept details changed as listed O'REILLY, J.P. Region 2. Office of Director 84/03/05 GUINN, F.K. Nuclear Fuel Services, Inc. (subs. of Oetty Oil Co.) Ip 22659 358
- --8403160386 IE Enforcement Conference Rept 70-0143/84-06 on 840216 Major areas discussed nuclear criticality safety violations identified by resident & regional inspectors KAHLE. J D. Region 2. Office of Director MCALPINE. E J. Division of Emergency Preparedness & Materials Safety 84/02/24 3pp 22639 360
- 8403160258 Forwards IE Insp Rept 70~0143/84-05 on 840214-17 No violations or deviations noted 8TDHR.J P Division of Emergency Preparedness & Materials Safety 84/03/07 OUINN.F K Nuclear Fuel Services, Inc (subs of Getty Di1 Co) 2pp 22660 205
- --8403160270 IE Insp Rept 70-0143/84-05 on 840214-17 No noncompliance noted Major areas inspected matl control & accountability Betails withheld (ref 10CFR 770 & 73 21) JONES,D W. Region 2, Office of Director MCALPINE,E.J. Division of Emergency Preparedness & Materials Safety 84/03/02 12 22660:207
- 8403290285 Ack receipt of 840301 ltr informing NRC of steps taken to correct violation noted in IE Bafaguards Insp Rapt 70-0143/83-41 Corrective actions will be examined during future insps Encis withheld (ref 100FR2 790) STCHR, J.P Division of Emergency Preparedness & Materials Safety 84/03/09, GAINN,F,K Nuclear Fuel Services, Inc. (subs of Gatty Oil Co) ip 22801 335
- 8403210151 Forwards IE Bafeguards Insp Rept 70-0143/84-09 on 840103-0302 No violations or deviations identified 8TCHR.J P Division of Emergency Preparedness & Materials Safety 84/03/19 GUINN.F.K Nuclear Fuel Services, Inc (subs of Oetto Gil Co) 2pp. 22707.102
- --B403210156 IE Bafeguards Insp Rept 70-0143/84-09 on B40103-0302 No violations noted Major areas inspected events reported by licenses, facility operation, changes & mod.rediation, environ & physical protection & matl control & accounting LEE.T D . MCALPINE.E J Region 2. Office of Director 84/03/19 App 22707:104

- DOCKET 70-0192 PURDUE UNIV , WEST LAFAYETTE, IN
- 8403170211 Forwards IE Safeguards Insp Repts 50-182/84-01 & 70-0152/84-01 on B40216-17 No noncompliance identified AKELBON,N L. Region 3. Office of Director 84/03/14 LYKOUDIS,P Purdue Univ. West Lafayette. IN 2pp 22671 109 24X Fiche 50-182.84/03/14.8403170211
- DOCKET 70-0190 CATHOLIC UNIV OF AMERICA, WASHINGTON, DC
- 0403130422 Discusses 1E Insp of Licenses SNM-164.SUD-157 & 08-02075-03 on 840126-27 & forwards notice of violation MARTIN.T T Division of Engineering & Technical Programs 84/03/08 MURPHY.J J Catholic Univ of America, Washington, DC 20p
- DDCKET 70-0371 UNG NAVAL PROBUCTS, INC , UNCASVILLE, CT
- 8403010289 Effluent monitoring rept Jul-Dec 1983 W/840126 ltr KIRK, W F United Nuclear Corp 83/12/31 MURLEY, TE Region 1, Office of Director 2pp 22434 259
- 8403190231 Ack receipt of 840224 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0371/83-08 Corrective actions will be examined during future insp STAROSTECKI. R Division of Project & Resident Programs 84/03/09 AMY.H O United Nuclear Corp ip 22672 026
- --8403190234 Responds to NRC 840126 ltr re violations noted in IE Insp Rept 70-0371/83-08 Corrective actions Feb 1984 awareness meeting & Mar 1984 annual health physics reorientation training will reemphasize exiting contamination check AMY-0 O United Nuclear Corp 84/02/24 STARGSTECKI.R Division of Project & Resident Programs Rpp 22672 027
- 8403220249 Ack receipt of 830812 application & 830915 rev re storage of fuel components Interaction analysis failed to identify physical & administrative confrols to ensure all components centrally located in common place BIDINGER.G H Uranium Fuel Licensing Branch 84/03/12 KIRK, W United Nuclear Corp 1p 22723 335

DOCKET 70-0378 ARMY, DEPT OF, ADELPHI, MD

- 8403190259 Discusses IE insp of Licenses SNM-348,19-17250-01, 19-17250-03,19-17250-04 & 19-17250-05 on 840202 No violations noted Major areas inspected interviews w/ personnel & procedures & representative records MARTIN, T T Division of Engineering & Technical Programs 84/03/14 MARCUS, S M Army, Dept of 2pp 22670 237
- DOCKET 70-0398 COMMERCE, DEPT OF, WASHINGTON, DC
- 8403270043 Forwards IF Safeguards Insp Rept 70-0398/84-01 on 840213-16 No violetions observed MARTIN,T T Division of Engineering & Technical Programs 84/02/13 PEVEY,L E Commerce, Dept of, National Bureau of Standards 2pp 22804 265
- --8403270066 IE Safeguards Insp Rept 70-0378/84-01 on 840213-16 No noncompliance noted Major areas inspected facility organization & operation, physical inventory, records & repts & mgt of nuclear matis control sys DELLA RATTA, A. JOYNER; JH Region 1, Office of Director 84/03/13 4pp 22806 267
- DOCKET 70-0474 UPSALA COLLEGE, EAST GRANGE, NJ
- 8403070264 Ack receipt of 840209 ltr re disposition of Pu-Be source under License SNM-450 License will be retired & renewal action voided QLENN, J. E. Division of Engineering & Technical Programs 84/02/27 FELDER, R. Upsala College, East Orange, N.J. ip 22546-228
- --8403070267 Informs that Pu-Be source shipped via GF Consolidiated Freightways & donated to DDE:LASL for recovery under License BNM-450 Transaction rept y bill of lading encl FELDER:R Upsala College, East Orange, NJ 84/02/07 NRC No Detailed Affiliation Given 3pp 22546 227

DOCKET 70-0553 ARMY, DEPT OF, SACRAMENTO, CA

8403200061 IE Insp Findings & Licensee Ack dtd 840206-07 of License SMM-507 Insp Findings no violations observed SMOV.D D Region 5. Office of Director 84/02/17 ip 22684 356

DOCKET 70-0687 UNION CARBIDE CORP . TUXEDO, NY

- 8403020231 Forwards final rept, "Evaluation of Seismic Response Characteristics of Mot Cells & Related Structures & Equipment at UCC Sterling Forest Research Ctr "
 ROUSE.L C Advanced Fuel & Spent Fuel Licensing Branch 84/02/16
 RUZICKA.W G Union Carbide Corp 1p 22519 215
- --BA03050032 "Evaluation of Seismic Response Characteristics of Hot Celle & Related Structures & Equipment at UCC Sterling Forest Research Ctr." final rept 3 Science Applications, Inc NRC-02-B3-035 SAI-1-148-08-781 83/11/30 NRC - No Detailed Affiliation Given 21pp 22519 217
- 8403270332 Forwards request for add1 info to complete NRC review of util 831014 license renewal application Capability needs to be strengthened in safety area to provide for audits by competent personnel w/current operating practice ROUSE,L C Advanced Fuel & Spent Fuel Licensing Branch 84/03/12 MCGOVERN,J J Union Cartide Corp 12pp 22822 238
- 8403300137 Ack receipt of 840302 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0A87/83-04
 STAROSTECKLY Division of Project & Resident Programs B4/03/27
 MCGQVERNJJ Union Carbide Corp ip 22820 347
- --8403300140 Responds to NRC 840120 ltr re violations noted in IE Insp Rept 70-0687/83-04 Corrective actions add1 criticality safety signs posted in target production lab t waste storage facility MCGGUYERN.J J Union Carbide Corp 84/03/02 STAROSTECKI.R Division of Project & Resident Programs ip 22820 348

DOCKET 70-0712 KERR-MCGEE NUCLEAR CORP . OKLAHOMA CITY, OK

- B403260116 FOLA request for five categories of documents re facilities BARNES.C Affiliation Not Assigned 83/12/02 FELTON.J M Division of Rules and Records ip 22763 333
- 8403260123 Partial response to FOIA request for five categories of documents re Kerr-McGee Oil Industries Inc Forwards documents listed on app Review of addl documents subj to request continuing FELTON, J M Division of Rules and Records 84/03/02 BARNES.C Affiliation Not Assigned 2pp 22763 334
- ~~8403260153 Discusses certification of 660426 rept re disposition of SNM, per G Waller 660602 telcon Rept should indicate that contamination limits met in order for Commission to authorize transfer of facility NUSSBAUMER.D A Atomic Energy Commission 66/06/10 LAMBERTUS.H Kerr-McGea Corp 2pp 22763 349

DOCKET 70-0734 GA TECHNOLOGIES: INC . SAN DIEGO, CA

- 8403060329 Forwards IE Safeguards Insp Rept 70-0734/84-02 on 840124-27 No noncompliance observed MCRDERHAUG.L R Region 5. Office of Director 84/03/01 PARKER, J W GA Technologies, Inc /General Atomic Co 2pp 22817 359
- --8403060331 IE Safeguards Insp Rept 70-0734/84-02 on 840124-27 No noncompliance identified Major areas inspected organization & operations-measurement controls & shipper/receiver verification Details withheld (ref 10CFR2 790) NELSON-6 B . NORDERHAUG-L R Region 5. Office of Director 84/02/27 tp 22517 361

DOCKET 70-0824 BABCOCK & WILCOX CO , LYNCHBURO, VA

B403070107 Informs of issuance of Amend 6 to License ENM-778, revising radiological contingency plan. SER encl PACE. R 6 Uranium Fuel Licensing Branch 84/02/26 QLSEN. A F Babcock & Wilcox Co 1p 22564 124

- --8403070112 SER supporting Amend 6 to License SNM-778, revising Condition 13 re radiological contingency plan KETZLACH, N Uranium Fuel Licensing Branch 84/02/28 1p 22544-125
- DOCKET 70-0920 RENSSELAER POLYTECHNIC INSTITUTE, TROY, NY
- 840305022B Requests submission of physical security plan meeting fixed site requirements of 10CFR73 67(d) for protection of SNM of moderate strategic significance Reg Guide 5 59 & addl guidance encl W/o uncl BRONN:W Fuel Facility Safeguards Licensing Branch 84/02/17 RYAN, R M. Rensselaer Polytechnic Institute, Troy, NY 1p 22327 359
- DOCKET 70-0925 KERR-MCGEE NUCLEAR CORP . OKLAHOMA CITY, OK
- 8403280028 Submits address change for Nuclear Licensing & Regulation Dept JC Stauter will serve as primary addressee for encl list of licensees SHELLEY, W. J. Kerr-McGee Corp. 84/03/21 SCHAEFFER, C. NRC - No Detailed Affiliation Given. 3pp. 22777 060
- DOCKET 70-0984 BATTELLE MEMORIAL INSTITUTE, RICHLAND, WA
- B403170159 Forwards IE Safeguards Insp Rept 70~0984/84~01 conducted on 840213~15 Noncompliance noted Notice of violation & insp rept withheld (ref 100FR2 790) NORDERHAUG, L R Region 5, Office of Director 84/03/15 OLESEN, D E Battelle Memorial Institute, Pacific Northwest Leboratories 2pp 22668 356
- DOCKET 70-1100 COMBUSTION ENGINEERING, INC , WINDSOR, CT
- 8401240337 Ack receipt of 831214 ltr informing NRC of steps taken to correct violations noted IE Insp Rept 70-1100/83-06 MARTIN:T Division of Engineering & Technical Programs 84/01/19 LICHTENBERGER Combustion Engineering. Inc. 1p. 21920 305
- ---B401240340 Responds to NRC B31129 ltr re violations noted in IE insp.
 Rept 70-1100/B3-06 Corrective actions waste shipping
 procedure revised to insure proper loading & storing of
 waste containers
 LICHTENBERGER Combustion Engineering, Inc. 83/12/14 MARTIN.T?
 Division of Engineering & Technical Programs 2pp. 21920 306
- 8403010360 Forwards IE Insp Rept 70-1100/63-07 on 831201 & notice of violation MARTIN.T T Division of Engineering & Technical Programs 84/02/lb LICHTENBERGER Combustion Engineering, Inc. 2pp 22434 084.
- --8403010362 Notice of violation from insp on 831201 * Region 1, Office of Director 84/02/16 ip 22434 086
- --8403010366 IE Insp Rept 70-1100/83-07 on 831201 Violation Identified pyrophoric math not made inert & burial site not licensed to receive untreated pyrophoric math CLEMONS.P. PAGCIAK.W. Region 1, Office of Director 84/01/16 3pp 22434 087
- 840307025B Forwards IE Safeguards Insp Rept 70-1100/84-02 on 840130-0203 No violations observed MARTIN,T T Division of Engineering & Technical Programs 64/02/17 LICHTENBERGER Combustion Engineering, Inc. 2pp 22536 273
- --8403070259 IE Safeguards Insp Rept 70-1100/84-02 on 840130-0203 No noncompliance noted Major areas inspected facility organization & operation shipper/receiver verification, internal control & records & repts SMITH 0 C . DELLA RATIA.A . DUNLAP, J M Region 1. Office of Director 84/02/16 4pp 22536 275
- 8403130472 Ack receipt of 840301 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-1100/84-01. STAROSTECKI, R Division of Project & Resident Programs 84/03/07. LICHTENBERGER Combustion Engineering, Inc. 1p. 22613 326
- --8403130476 Responds to NRC 840213 ltr re violations noted in IE Insp. Rept 70-1100/84-01 Corrective actions criticality safety analysis for nuclear matls stored on pellet shop merranine will be completed by 840316
 LICHTENDEROER Combustion Engineering. Inc. 84/03/01
 STAROSTECKI, R. Division of Project & Resident Programs. 2pp. 22613-327

DOCKET 70-1113 GENERAL ELECTRIC CO , WILMINGTON, NC

- 8403160105 Ack receipt of 830804 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-1113/83-17 Two violations correctly designated as separate violations 0'REILLY.J P Region 2, Office of Director 84/02/29 LONG, J A General Electric Co 2pp 22655 114
- E403160340 Forwards IE Safeguards Insp Rept 70-1113/84-02 on B40204-10 No violations or deviations noted STOHR, J P Division of Emergency Preparedness & Materials Safety B4/03/02 LONG, J A General Electric Co 2pp 22659 354
- --8403160348 IE Safeguards Insp Rept 70-1113/84-02 on 840206-10
 No noncompliance noted Major areas inspected measurements
 & statistical controls Details withheld (ref 10CFR2 770)
 CLAY, E.L. Region 2, Office of Director MCALPINE, E.J. Division
 of Emergency Preparedness & Materials Safety 84/02/29 ip
- 8403160375 Forwards IE Safeguards Insp Rept 70-1113/84-01 on 840206-10 No violations or deviations identified 8TCHR, JP Division of Emergency Preparedness & Materials Safety 84/03/02 LONG, JA General Electric Co 2pp 22660 189
- --8403160380 IE Safeguards Insp Rept 70-1113/84-01 on 840206-10 No noncompliance noted Major areas inspected followup on previous insp findings & verification of export shipment Details withheld (ref IOCFR2 790 & 73 21)

 BATES.J W. Region 2. Office of Director MCALPINE.E J. Division of Emergency Preparedness & Materials Safety 84/02/27 1p 22660 171
- DOCKET 70-1143 WEBTINGHOUBE ELECTRIC CORP , PITTEBURGH, PA
- B403010326 "Effluent Semiannual Rept.Jul-Dec 1983 " W/840130 1tr WODDBUM.H C Wastinghouse Electric Corp 83/12/31 2pp 22442 012
- DOCKET 70-1151 WESTINGHOUSE ELECTRIC CORP , FITTSBURGH, PA
- DOCKET 70-1193 KERR-MCGEE NUCLEAR CORP , OKLAHOMA CITY, OK
- ##403280028 Submits address change for Nuclear Licensing & Regulation Dept JC Stauter will serve as primary addresses for encl list of licenses SHELLEY.W J Kerr-McGes Corp 84/03/21 SCHAEFFER,C NRC No Detailed Affiliation Civen 3pp 22777 060
- EDICKET 70-1201 BABCOCK & WILCOX CO , LYNCHBURG, VA
- E) 403070015 Informs of issuance of Amend i to License SNM-1168, revising Condition 24 re radiological contingency plan SER encl PAGE, R 0 Uranjum Fuel Licensing Branch 84/02/28 FORD. J. T Babcock & Wilcox Co 2pp 22563 191
- ——8403070019 Bafety evaluation supporting Amend 1 to License BNM-1168, revising Condition 24 re radiological contingency plan KETZLACH, N Uranium Fuel Licensing Branch 84/02/28 1p 29543 193
- DICKET 70-1257 EXXON NUCLEAR CO , INC , RICHLAND, WA
- ### 4-03270214 Forwards IE Insp Rept 70-1257/83-10 on B31114-18 & notice of violation SCARAND, R A Division of Radiological Safety & Safeguards Program B4/01/16 NILSON: R Exxon Nuclear Co , Inc (subs. of Exxon Corp) 2pp ### 2272-144
- -- 8403270217 Notice of violation from insp on 831114-18 THOMAS.R D Region 5, Office of Director 84/01/16, 1p 22729-148

- --8403270221 IE Insp Rept 70-1257/83-10 on 831114-18 Violations noted buckets containing SNM in specialty fuels bldg separated by only 3 inches & specialty fuels bldg not posted w/sign restorage Safeguards info deleted (ref locFRZ 790) BROCK, B L , ZURAKONSKI, P R , THOMAS, R D Region 5, Office of Director 84/01/10 21pp 22772 149
- B403060416 Ack receipt of B40207 ltr informing NRC of steps taken to correct violations noted in IE insp of License SNM-1227 MENSLAMSKI.F. A Region 5, Office of Director B4/03/01 MALDDV.C W Exion Nuclear Co. Inc. (subs. of Eixon Corp.) 19
- --B403060421 Responds to NRC 840116 ltr re violations noted in IE insp of License SNM-1227 Corrective actions taped array outline replaced w/metal grid spacing arrangement to provide permanency & to keep storage buckets from pushing together MALODY.C W Exxon Nuclear Co., Inc. (subs. of Exxon Curp.) B4/02/07 THOMAS.R D Region 5, Office of Director 2pp. 22511 345
- 8403260082 Advises of issuance of Amend 15 to License SNM-1827, authorizing changes to environ monitoring program covering well monitoring SER enci
 PAGE, R. G. Uranium Fuel Licensing Branch 84/03/07 MALOBY, C. W. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) 1p. 22763 232
- --8403260084 SER supporting issuance of Amend 15 to License BNM-1227 to environ menitoring program SIDINGER.G H, GROW.W T Uranium Fuel Licensing Branch 84/03/09 2pp 22763 233
- 8403190224 Forwards IE Safeguards Insp Rept 70-1257/84-01 on 840214-17 No noncompliance noted Rept withheld (ref 10CFR2 790) NORDERHAUG. R. Region 5. Office of Director 84/03/15 NILSON. R Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) 2pp 22670 241
- 8403300293 Notifies that Sections 2 & 3 of License 5NM-(227 amended to authorize organizational changes PAGE.R G Uranium Fuel Licensing Branch 84/03/15 MALODY,C W Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) 1p. 22844-319
- --8403300277 SER supporting 831205 & 840305 applications for amends to License 6NM-1227, authorizing organizational changes BIDINGER 6 H Uranium Fuel Licensing Branch 84/03/15 1p
- DOCKET 70-1311 AIR FORCE, DEFT OF, USAF ACADEMY, CO
- 8403130401 IE Insp Findings to Licensee Ack dtd 840206 & 07 of License SHM-1285 Insp findings no violations observed SHMPENN,N M Region 4, Office of Director 84/02/07 ip
- DOCKET 70-1359 IRT CORP . SAN DIEGO. CA
- 8403200224 IE Insp Findings & Licensee Ack dtd 840124-25 of License SNM-1405 Imsp findings refresher training of authorized users not conducted every 2 yrs & annual audit not conducted.per Condition 9
 PANO, J F Region 5. Office of Director 84/01/30 ip 22700 021
- 8403230241 Forwards revised License SNM-1405 & 8ER supporting license amend Request for amend should be submitted in form of replacement pages to license application PAGE, R 0 Uranium Fuel Licensing Branch 84/03/07 MASCHKA, P R IRT Corp 1p 22759 263
- --8403230244 License SNM-1405 for IRT Corp authorizing receipt & possession of 25 g U-235.100 g Pu/8e source & 500 g Pu-239 PAGE.R Ø Uranium Fuel Licensing Branch 84/03/09 2pp 22739 264
- --B403230246 Safety evaluation supporting renewal of License SNM-1405 FOBLA, B M Uranium Fuel Licensing Branch CROW, W T Division of Fuel Cycle & Material Safety 84/03/09 4pp 22759 266
- DOCKET 70-1621 DUGUESNE LIGHT CO . PITTSBURGH, PA
- 8403010293 Forwards Endorsement 58 to MAELU Policy MF-87 & Endorsements 67 & 68 to NELIA Policy NF-226 BARNETF.JE Comover & Associates, Inc 84/02/28 DINITZ.I. Office of Nuclear Reactor Regulation, Director 4pp 22434 264

DOCKET 70-1717 NORWALK HOSP , NORWALK, CT

8403300167 IE Insp Findings % Licensee Ack dtd 840307 of Licenses 06-06941-01 & SNM-1904 Insp findings no violations observed Steps taken to correct violations noted in previous insp verified SIEARNS, C.F. Region 1, Office of Director 84/03/07 1p

DOCKET 70-2199 VETERANS ADMIN HEDICAL CENTER, WASHINGTON, DC

B403130274 Ack receipt of 830830 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-2197/83-02
MARTIN,T T Division of Engineering & Technical Programs B4/03/08
DAVAZZIA A Veterans Admin Medical Center, Washington, DC ip

--8403130302 Responds to NRC 830810 itr re violations noted in IE Insp Rept 70-2199/83-02 Corrective actions appropriate officials notified that NRC approval required to accept nuclear pacemakers GAVAZZI.A A Veterans Admin Medical Center, Washington, DC 83/08/30 MARTIN.T T Division of Engineering & Technical Programs 7ρρ 22608 040

---8403130308 Ack receipt of 830810 ltr on Circular 10-83-66 re explanted cardiac pacemaker prostheses Recission of nuclear units to Veterahs Administration facilities completed SMITH.J J Veterahs Admin Medical Center, Washington, DC B3/08/26 MARTIN.T T Division of Engineering & Technical Programs 5pp 22608 042

DOCKET 70-2946 LOUISIANA POWER & LIGHT CO , NEW ORLEANS, LA

8403060190 Forwards Endorsement 13 to NECIA Policy NF-263 COOK, K W Louisiana Power & Light Co 84/02/27 Assistant Director for State ', Licensee Relations 2pp 22519 034

DOCKET 70-2955 EDLOW INTERNATIONAL CO . WASHINGTON, DC

B403050365 Notifies that 840123, "Physical Security Plan for Protection of SNM of Low Strategic Significance" acceptable as amended, per encl provisions Encl withheld (ref 100FR2 790)
BROWN N B Fuel Facility Safeguards Licensing Branch B4/01/27
EDLOW, J Ediow International Co 3pp 22527 314

DECKET 70-2988 PHILADELPHIA ELECTRIC CO - PHILADELPHIA, PA

B403050367 Forwards request for add1 info re physical security plan for protection of SNM of low strategic significance Response requested within 30 days W/o encl BROWN,W Fuel Facility Safeguards Licensing Branch 84/01/31 BRADLEY.E G Philadelphia Electric Co ip 22527 313

8403300307 Submits items of interest Affidavit issued 840313 confirming that even if fuel pellots damaged by accident involving fuel assemblies in shipping containers, no radiological releases in violation of NRC regulations would result CUNNINGHAM, R.E. Division of Fuel Cycle & Material Safety 84/03/15 DAVIS.J C. Office of Nuclear Material Safety & Safeguards, Director ip 2844.302

PACKAGING OF RADIOACTIVE MATERIAL FOR TRANSPORT AND TRANSPORTATION OF RADIOACTIVE MATERIAL UNDER CERTAIN CONDITIONS

DOCKET 71-0511 DELTAK CORP

8403010149 Forwards revised App H to QA program for transportation of radioactive matls Organization chart from radiation safety manual added as Figure 1 JORDAN, D Deltak Corp 84/01/24 GORDON, L Transportation Certification Branch 1p 22479 250

--8403010153 GA program for transportation of radioactive matls * Deltak Corp 84/01/24 5pp 22479 231

DOCKET 71-0513 EDLOW INTERNATIONAL CO

8403140233 Forwards QA program approval for radioactive matl package O313,Rev 1 MACDONALD.C E, Transportation Certification Branch 84/03/05 PODHURST,B W Edlow International Co 1p 22636 361 --8403140238 GA program approval for radioactive matl package 0513.Rev | MACDONALD.C E Transportation Certification Branch 84/03/05 | 1p 22636 362

DOCKET 71~0514 NORTH AMERICAN INSPECTION

8403050338 Forwards QA program approval for radioactive math Package 0314 Rev O MACDDNALD, C E Transportation Certification Branch 84/02/24 BHUMMAY.R North American Insp ip 22501 319

--8403050340 QA program approval for radioactive matl Package 0514.Rev 0 MACDDNALD,C E Transportation Certification Branch 84/02/24 1p 22501 320

DOCKET 71~5450 MODEL RCC. -1, -2, -3, -4, WESTINGHOUSE ELECTRIC CORP

8403260331 Forwards Rev 19 to Certificate of Compliance 5450 for Models RCC.RCC-1, RCC-2, RCC-3 & RCC-4
MACDDONALD.C E Transportation Certification Branch 84/03/09
MEINTRAUB.A A Energy Dept of 2pp 22775 288

--8403260336 Certificate of Compliance 5450, Rev 19, for Models RCC, RCC-1, RCC-2, RCC-3 & RCC-4
MACDONALD.C E Transportation Certification Brench 84/03/09
6pp 22/75 270

DOCKET 71~6206 MODEL B. BABCOCK & WILCOX CO

84030i0i62 Application for amend to Certificate of Compliance 6206. changing Fissile Class III to Fissile Class II or III FORD.J Y Babcock & Wilcox Co 84/01/24 MACDGNALD.C E Transportation Certification Dranch 2pp 22479 219

--8403010166 Rev O to "Shipping Safety Analysis"
* Babcock & Wilcox Co 80/02/27 lipp 22479 221

DOCKET 71-6406 MODEL NONE, ENERGY, DEPT OF

B403080394 Forwards Rev 5 to Certificate of Compliance 6406 for unirradiated fuel assemblies MACDONALD.C E Transportation Certification Branch 84/02/29 ENGEL.N P Energy, Dept of ip 22581 352

--8403080395 Certificate of Compliance 6406, Rev 5, for unitradiated fuel assemblies Approval record encl MACDONALD, C E Transportation Certification Branch 84/02/29 5pp 22581 353

DOCKET 71-6601 MODEL CNB 8-120, CHEM-NUCLEAR SYSTEMS, INC

8403080312 Forwards Rev 15 to Certificate of Compliance &601 for Model CNS 8-120 MACDUNALD, C E Transportation Certification Branch B4/03/02 DEAL, R Chem-Nuclear Systems, Inc. 4pp 22577 350

---8403080314 Certificate of Compliance 6601.Rev 15 for Model CNS 8-120 Approval record encl MACDONALD.C E Transportation Certification Branch 84/03/02 4pp 22577 354

8403210212 Notification of registration as user of Models CNS 8-120 & NUPAC 14 D-2 O in response to 840221 request MACDUNALD.C E Transportation Certification Branch 84/03/09 WETHY.C M Florida Power & Light Co 1p 22709 205

B403230166 Notification of registration as user of Model CNS 8-120 in response to 840221 request MACDDNALD.C E Transportation Certification Branch B4/03/09 KELBLEY.N D Advanced Medical Systems, Inc ip 22743,348

DOCKET 71-9001 MODEL IF-300, GENERAL ELECTRIC CO

B403080397 Forwards Rev 17 to Certificate of Compliance 9001 for Model IF-300 MACDONALD, C. E. Transportation Certification Branch 84/02/29 DAMEDN, D. M. General Electric Uranium Management Corp. 2pp. 22581:342

--8403080399 Certificate of Compliance 9001.Rev 17.for Model IF-300 Approval record encl MACDONALD.C E Transportation Certification Branch 84/02/29 8pp 22581 344

DOCKET 71-9009 MODEL FL 10-1, GENERAL ELECTRIC CO

8403050574 Forwards request for add1 info re 840121 application requesting approval for Model FL 10-1 Info requested 60 days from ltr receipt MACDONALD, C E Transportation Certification Branch 84/02/29 VAUGHN, C M General Electric Co 3pp 22552 236

8403230269 Notification of registration as user of Model FL 10-1 in response to 840214 request MACDDNALD,C E Transpartation Certification Branch 84/03/09 WEINTRAUB,A A Energy, Dept of 1p 22/59 285

DOCKET 71-9027 MODEL 741 & 741E, TECHNICAL OPERATIONS, INC

8403300298 Forwards Rev 4 to Certificate of Compliance 9027 for Models 741 & 741E MACDDNALD, C E Transportation Certification Branch 84/03/1 MUNRO, J J Technical Operations, Inc. 2pp 22844 311

--8403300302 Certificate of Compliance 9027, Rev 4, for Models 741 & 741F MACDONALD.C E Transportation Certification Branch 84/03/19 3pp 22844 312

DOCKET 71-9036 MODEL C-1, SOURCE PRODUCTION & EQUIPMENT CO , INC

9403280214 Forwards Rev 4 to Certificate of Compliance 9036 for Model C-1 Model C-1 MACOUNALD.C E Transportation Certification Branch 84/03/14 DICHARRY.R F Source Production & Equipment Co . Inc. 2pp 20789 344

--8403280218 Certificate of Compliance 7036, Rev 4, for Model C-1 MACDUNALD, C E Transportation Certification Branch 84/03/14 3pp 22787 348

DOCKET 71-9071 MODEL AP-101, ANEFCO, INC

8403020227 Requests listed info to complete review of 840117 application for amend to Model AP-101 to include borosilicate & other silicate solid waste forms in steel canisters as authorized contents MACDDNALD.C E Transportation Certification Branch 84/02/22 MURPHY, J D Anefco, Inc 2pp 22493 361

DOCKET 71-9079 MODEL HN-100, SERIES 2 & 2A, HITTMAN NUCLEAR

B403210212 Notification of registration as user of Models CNS 8-120 t NUPAC 14 D-2 0 in response to 840221 request MAGDONALD, C E Transportation Certification Branch B4/03/09 WETHY.C M Florida Power & Light Co ip 22709 205

DOCKET 71-9080 MODEL HN-600, NUPAC 7-100 & CNS 7-100, HITTMAN NUCLEAR

B403080416 Forwards Rev 9 to Certificate of Compliance 9080 for Models HN-600.NUPAC 100 & CN8 7-100 MACDUNALD.C E Transportation Certification Branch 84/03/01 ROWE. I S Westinghouse Electric Corp 4pp 22547 346

--8403080418 Certificate of Compliance 9080.Rev 9, for Models HN-600, NUPAC 100 & CNS 7-100 Approval record encl MACDGNALD, C E Transportation Certification Branch 84/03/01 3pp 22567:350

DOCKET 71-9108 MODEL CNS 4-75, CHEM-NUCLEAR SYSTEMS, INC

840302042D Forwards Rev 5 to Certificate of Compliance 9108 for Model CNS 6-75 MACDONALD, C.E. Transportation Certification Branch 84/02/22, DEAL, R. Chem-Nuclear Systems, Inc. 3pp. 22491 269

--8403020423 Certificate of Compliance 9108.Rev 5.for Model CN8 6-75 MACDONALD.C E Transportation Certification Branch 84/02/22 4pp. 22491 272 DOCKET 71-7134 MODEL ETR. EXXON NUCLEAR IDAHO CO

8403300224 Forwards Rev 3 to Certificate of Compliance 9134 for Model ETR MACDOMALD, C.E. Transportation Certification Branch 84/03/15 WEINTRAUB. A.A. Energy, Dept. of 2pp. 22845-039

--8403300227 Certificate of Compliance 9134,Rev 3 for Model ETR MACDDNALD.C E Transportation Certification Branch 84/03/15 4pp 22845 041

DOCKET 71-9160 MODEL 20-VS & 40-VS, GULF NUCLEAR, INC

8403070011 Forwards request for add1 info re 840121 application requesting approval for Models 20-VS & 40-VS info requested a0 days from itr receipt MACDONALD.C & Transportation Certification Branch 84/02/29 BEVILL.M Gulf Nuclear, Inc. 2pp 22563 164

8403300229 Forwards request for addl info re 840306 application for approval of Models 20-VS & 40-V5 Addl info should be submitted in form of revised pages Submittal schedule requested within 30 days of ltr receipt MACDINALD.C E. Transportation Certification Branch 84/03/15 BEVILL.M. Gulf Nuclear, Inc. 2pp. 22844 360

DOCKET 71-9161 MODEL R. GULF NUCLEAR. INC

8403020239 Requests add1 info re 840121 application for approval of ModBI R packaging Info requested 30 days from ltr date MACDUNALD.C E Transportation Certification Branch 84/02/24 BEVILL.M Gulf Nuclear, Inc ip 22493 360

DOCKET 71-9162 MODEL GNM-20, GULF NUCLEAR, INC

8403260074 Forwards request for add: info in response to 830624 application for approval of Model GNM-20 Add info should be submitted in form of revised pages Submittal date requested within 30 days of lir date MACDONALD, C E Transportation Certification Branch 84/03/07 DEVILL.M Gulf Nuclear, Inc. 1p 22763 IBB

DOCKET 71-9175 MODEL CNS6-808, NUCLEAR PACKAGING, INC.

8403160164 Summary of 840302 meeting w/Chem-Nuclear Sys, Inc in Silver Spring, MD re application for Model CNS 6-808 packaging QDEGARDEN.R H Transportation Certification Branch 84/03/06 Transportation Certification Branch 1p 22662 265

DOCKET 71-9190 MODEL CASTOR V. GESELLSCHAFT FUER NUKLEAR SERVICE, MBH

8403070002 Forwards comments on 831107 partial application for CASTOR Vb cask Based on info submitted.NRC cannot conclude that proposed test would be adequate for approving cask design Application for QA program needed prior to next submittal MACDONALD.C E Transportation Certification Branch 84/02/23 ROLLINS.J D Gesellschaft fuer Nuklear Service, mbH 8pp 20342 344

		•
		1

8403010447 Transcript of 840224 briefing in Washington, DC rs need for & availability of experienced reactor operators for future nuclear power plants Pp 1~95 Supporting documentation & viewgraphs encl # Commissioners 84/02/24 141pp 22446 348 B403050246 Staff requirements memo re Commission B40222 meeting in Washington, DC on advance notice of rulemaking on backfitting Commission directed Regulatory Reform Task Force to reconvene & consider proposal CHILK, G J Office of the Secretary of the Commission MB40222 G4/02/27 TOURTELLOTTE, J NRC - NO Detailed Affiliation Given DIRCKG, M J Office of the Esecutive Director for Operations PLAINE, H H Uffice of the General Counsel 2pp 22527 186 8403050258 Staff requirements memo re Commission affirmation, discussion to vote in Washington DC Commission by 5-0 vote approved SECY-04-83/83A re environ qualification policy statement CHILK, 5 J Office of the Secretary of the Commission M840228A 84/02/29 PLAINE, H H Office of the General Counsel ip 27527 105 ©403050277 Transcript of 840227 briefing in Washington, DC re advanced teactors Pp 1-54 Supporting documentation encl * Commissioners 84/02/27 72pp 02501 113 E403050297 Transcript of 840227 brisfing in Washington, DC re financial qualifications & long-term rulemaking proposals Pp 1-49 * Commissioners 84/02/27 53pp 22501 211 8403050328 Transcript of 840227 affirmation/discussion & vote in Washington.DC rc SECY-D4-71A on statement policy re financial qualifications Pp 1-3 x Commissioners 84/02/27 7pp 22501 282 8403040501 Transcript of Commission B40228 affirmation/discussion & vote in Washington.DC re-publication of FR notice on equipment qualification policy statement pp 1-3 * Commissioners 84702/28 &pp 22552 177 8403070370 Commission determination statement withholding transcript of closed 830921 meeting re-motion to quash Hartman or crosses.

Subpremiss
CHILK, S J Office of the Secretary of the Commission 84/02/27

Public Document Branch | p 22547 RO1 24X Fiche 50-920,84/02/27, B403070378 Transcript of Commission B40329 briefing in Washington, DC re status of util progress toward obtaining full power DL Pp 1-93 Supporting documentation and E Commissioners B4/02/29 101pp 22967 090 24X Fiche 50-416,04/02/29,8403070378 B403070415 Transcript of Commission 840228 discussion of need for & availability of experienced reactor operators for future nuclear power plants in Washington DC Fp 96-164 F Commissioners 84/02/28 70pp 22566 303 8409180088 Staff requirements memo re 840228 discussion of operating shift experience requirements in Washinhton.DC Development of plan to achieve longer-range shift operator experience objectives requested.
CHILK, B. J. Office of the Sacretary of the Commission M8402288 84708705 DIRCKS,W. J. Office of the Executive Director for Operations in 22619 347 B403120034 Staff requirements memo re 840227 briefing in Washington DC re SAIP review of areas prior to issuance of full-power recommendation & document interpreting LER rept CHILK, B.J. Office of the Secretary of the Commission, MB40290 B4/03/02. DIRCKB, W.J. Office of the Executive Director for Operations ip 22619 346 24X Fiche 50-416.84/03/02.8403120034

100FP

COMMISSION MEETING RECORDS

8403150130 Transcript of Commission 840229 discussion & possible vote in Washington.DC re NRC recommendations on DDE repository siting guidelines Supporting documentation encl & Commissioners 84/02/39 70pp 22648 160 8403230162 Staff requirements memo re 840227 discussion & possible vote on staff recommendations on DDE repository siting guidelines in Washington, DC CHILK, GJ Uffice of the Secretary of the Commission M840227A B4/03/12 DIRCKS, WJ Office of the Executive Director for Operations 1p 22743 347 --8403230164 Advises that NRC has approved FR publication of preliminary decision re DDE repository sitzing guidelines presented in SECY-84-670, subj to listed items CHILK.B J Defice of the Secretary of the Commission 84/03/08 DIRCKS.H J Office of the Executive Director for Operations 2pp B403230195 Transcript of 840320 briefing in Washington.DC re Tech Spec requirements Pp 1-74 Supporting documentation encl * Commissioners 84/03/20 B5pp 22759 178 24X Fiche 10-416.84/03/20.8403230195 8403240334 Transcript of Commission 840321 affirmation/discussion k vote in Washington, DC re proposed order delegating authority to ASLB to hear Part 70 issues raised in Limerick proceeding Pp 1-3

* Commissioners 84/03/21 App 22775 281 24% Fiche 50-352,84/03/21,8403260334 84032703PO Transcript of Commission 840323 discussion/possible vote in Washington, DC re-full power OL for LaBalle Unit 2 Pp 1-76 Supporting documentation and ### Commissioners, 84/03/23 B4pp 22787 153 24% Fiche 50-374,84/03/23,8403270320 8403270335 Transcript of Commission 840383 affirmation/discussion to vote in Washington, DC re-request for denial of renewal of Beabrook Unit 2 CP & GECY-84-48 concerning review of ALAB-724 in matter of Met Ed Pp 1-3 * Commissioners ALAB-724 84/03/23 App 22787 336 24X Fishe 30-000, 84/03/23, 8403270335 ADVISORY COMMITTEE ON REACTOR SAFEQUARDS ACRR

- E307240034 Forwards comments on proposed priority rankings of additionable of group of generic issues discussed during ACRS 279th meeting on B30707-09 ACRS disagrees w/certain priority rankings proposed by NRC LIBARKIN.M W ACRS Advisory Committee on Reactor Safeguards B3/07/15 DIRCKS.W J Office of the Executive Director for Operations 18pp 22444 082
- ---8403010015 Submits comments & requirements re 820819 meeting on safeguards issues Safeguards country analyses, spent fuel & spent fuel strategy & safeguard goals addressed MAUSSHARDT. D D Office of Nuclear Material Safety & Safeguards. Director 82/08/20 BURNETI.R F Division of Safeguards 2pp 22444 100
- →-8403010022 Comments on safeguerds research More structuring & emphasis should be placed on investigating insider particularly coming to grips w/answer to PRA approach Shared research between DOE & NRC could work DAVIS.J © Office of Nuclear Material Safety & Safeguards. Director 83/07/14 BURNETT, R F Division of Bafeguards ip 22444 102
- --8403010029 Requests different cross cuts of data on "Insider Adversary Study" to help quantify certain aspects of malevolence risk Classified insider adversary rept requested BURNTIR F Division of Safeguards 82/10/26 CAUDLE, R. Energy, Dept of ip. 22444 103

- ~-B403010033 Forwards histograms & explanatory notes that represent most recent work in analyzing safeguards event data Malevolent intidents that challenged safety sys & incident frequencies & trends examined UNRNITIR F Division of Safeguards 82/11/05 MAUSSHARDT Office of Muclear Material Safety & Safeguards. Director 20pp 22444 104
- -0403010042 Forwards "Quantification of Risk Due to Sabotage at Power Reactors" NRC conclusion that inclusion of radiological sabotage in safety goal unfeasible BURNETFUR F Division of Safeguards 83/12/14 DAVIS, J G Office of Muclear Material Safety & Safeguards. Director 35pp 22444 124
- --B30B04057G Discusses development of safeguards goal, per 830b09 memo Probability of nuclear power plant sabotage cannot be estimated w/any confidence No good measures for predicting effectiveness of securities safeguards improvements.

 THOMPSON, M.L. Division of Human Factors Safety 83/07/26 BURNCTF.R F. Division of Safeguards 2pp 22444 206
- --B312150241 Provides concurrence on NMSS summary of EDD 830927 briefing on quantification of risk to sabotage at power reactors. Use of PRA as tonl to develop sabotage stds should be portrayed more positively THOMAS.C O btandardisation & Special Projects Branch 83/12/07 CRJCKSON.R A Licensing Folicy & Programs Branch Ip 22444 218
- --83iii40170 Comments on chronology re quantification of risk due to substage at power reactors in response to 83i027 memo SPFIS,T P Division of Safety Technology 83/11/02 EISENHUT.D G Division of Licensing 2pp 22444 219
- --8312120006 Clarifies position on quantification of risk due to sabotage Author inclines toward more positive view of role PRA techniques might play in regulatory stds development bearing upon sabotage SPEIS.TP Davision of Safety Technology 83/11/29 EISCNHUT.D & Division of Licensing 1p 22444 220
- -8403010057 Submits slx items requiring followup re status of safeguard program items Preliminary agenda for Nov 1984 & meeting notice re weekly collequia on PRA activities encl HAUSSHARDI. D Dff;ce of Nuclear Material Safety & Safeguards.Director 83/10/20 BURNETT,R F Division of Safeguards 116pp 22444 222
- --B311140250 Discusses initiatives to improve coordination, morale & training among divs on PRA-related subjs ROMSDME, F Assistant Director for Technology Review 83/09/21 SPEIS.T Division of Safety Technology 3pp 22444 338
- --8403010065 Requests conference room beginning on 831108 & every Tuesday therrafter to hold colloquia between MRR & RES members on PRA related issues ROMSUME, F Assistant Director for Technology Review 83/10/26 ISELIN.R E Building & Operations Branch 1p 22444 341
- B311140248 Pruposes program to improve coordination among divs on PRArelated subjs
 ROWSDME.F H Assistant Director for Technology Review 63/10/31 ERNST.N L Division of Risk Analysis 2pp 22444 342
- --8312170358 Forwards preliminary agenda instituting weekly collquia on tractor risk assessment Collquia series will begin on 831108 to discuss NRR FRA for FYBA ROWSUME.F Assistant Director for Technology Review 83/10/31 Assistant Director for Technology Review 1p 22444 344
- B401300121 Summarizes ACRS 285th meeting on B40112-14 re review of OL application.cantrol room design & tube degradation Investigation of allegations re GA requested EBERSON E.U.C. ACRS Advisory Committee on Reactor Safeguards B4/01/16 PALLADINO.N.J. Commissioners 3pp 22044 023 24X Fiche 50-400.84/01/16.8401300121
- 8403050346 Nptifies of reappointment to ACRS
 PALLADING, N J Commissioners 84/02/22 EBERSOLE.J C. Affiliation
 Not Assigned EBERSOLE.J C ACRS Advisory Committee on Reactor
 Safeguards 1p 22501 321

- B403050348 Natifies of reappointment to ACRB
 PALLADING,N J Commissioners 84/02/22 SIESS.C P Affiliation
 Not Assigned SIESS.C P ACRB Advisory Committee on Reactor
 Safeguards 1p 22501 322
- 8403090340 Discusses major deficiencies in "Critique of 306," pactage re inappropriate status & qualifications of training manager & low level of educ requirements Request views be presented at ACRS 831215-17 committee meetings PEARSON, R 9 North Carolina State Univ , Raleigh, NC PEARSON, R 9 ACRS Advisory Committee on Reactor Bafeguards 83/12/06 WARD. D ACRS Advisory Committee on Reactor Bafeguards 89, 22584 333
- B403130222 Transcript of ACRS Subcommittee on Braidwood Station B4030B meeting in Joliet, IL Pp 1-163 Viewgraphs and 1 **ACRS Advisory Committee on Reactor Safeguards 84/03/08 185pp 22605 195 24X Fiche 50-456, 84/03/08, 8403130222
- B40314000B Transcript of ACRB Subcommittee on Braidwood Station B40309 meeting in Joliet,il Pp 164-283 Supporting documentation encl s ACRB Advisory Committee on Reactor Bafeguards B4/03/07 379pp 22631 035 24% Fiche 50-456,84/03/09,8403140000
- 8403140302 Discusses seismology issues in OL review Extremely conservative values established for OBE & BBE Plant site is as nearly assismic as any site in eastern US MAXMELL, J C MAXWELL, J C MAXWELL, J C ACRS Advisory Committee on Reactor Safeguards 84/01/05 MERR.W ACRS Advisory Committee on Reactor Safeguards 1p 22635 317 24X Fiche 50-400, 84/01/05.
- 8403140323 Summary of ACRS Subcommittees on Reactor Radiological Effects & Site Evaluation 830718-20 meetings in Washington. DC re FPA proposed natl emission stds & radiological emergency plans * ACRS Advisory Committee on Reactor Safeguards 83/08/31 ACRS Advisory Committee on Reactor Safeguards 23pp 22635 2
- 8403140334 Forwards comments on draft "PRA Ref Document," based on brief & incomplete review Agrees that use of "bottom-line risk numbers" should be discouraged Document comprehensive & consistent GARCIA: A Lawrence Livermore Laboratory 88-84-004/117U 84701/10 OKRENID California, Univ of Los Angeles, CA OKRENID ACRS Advisory Committee on Reactor Safeguards 4pp 22035 71
- B403140339 Comments on document evaluating PRA methodology effectiveness Risk-worth tabulations for each complete PRA should be included MUELLER.C J., PEDERSEN, D.R. Argonne National Laboratory MUELLER.C J. ACRB Advisory Committee on Reactor Safeguards B4/01/06 SAVIO.R ACRB Advisory Committee on Reactor Safeguards DKRENT, D. California, Univ. of, Los Angeles, CA. 4p. 22635 249
- 8403140352 Summary of ACRS Waste Mgt Subcommittee 830908-09 meetings in Richland, WA to continue review of DDE site characterization rept for BWIP * ACRS - Advisory Committee on Reactor Safeguards 83/11/01 ACRS - Advisory Committee on Reactor Safeguards 17pp. 22635 175
- 8403140004 Transcript of ACRS Subcommittees on Reliability & PRA & Indian Point Units 2 & 3 840314 meeting in Washington, DC, Pp 1-60 Supporting documentation encl * ACRS Advisory Committee on Reactor Bafeguards 84/03/14 61pp 22653 289 24X Fiche 50-247,84/03/14,8403160004
- 8403160012 Transcript of ACRB Subcommittee on Reliability & Risk Assessment 840314 meeting in Washington DC Pp 1~54. Supporting documentation encl * ACRB Advisory Committee on Reactor Safeguards 84/03/14 6dpp
- B403160037 Transcript of ACRS Subcommittee on Maint Practices & Procedures 840314 meeting in Washington.DC Pp 1-234 Supporting documentation encl * ACRS Advisory Committee on Reactor Safeguards 84/03/14.509pp 22650 001
- 8403160046 Discusses adequacy of proposed rulemaking change to 10CFR50. App A, insuring human factor specs in design operation criteria DEDDNS: A ACRS Advisory Committee on Reactor Safeguards 83/12/21 WARD: D ACRS Advisory Committee on Reactor Safeguards 2pp 22662 322
- 8403160053 Comments on DOE B31118 final quidelines for recommendation of sites for nuclear waste repositories
 PHILBRICK, B B ACR9 Advisory Committee on Reactor Safeguards
 PHILBRICK, B B Philbrick, B S 83/12/19 MOELLER, D H ACRB -Advisory Committee on Reactor Safeguards, 2pp 22668-320

- 8403160059 Discusses B31206 meeting w/O Sheron & J Gutman re contribution of semiscale integral facility in licensing efforts Specific issues addressed w/help of semiscale listed
 - CATTON, I ACRS Advisory Committee on Reactor Safeguards 84/01/05 BOEHNERT, P ACRS - Advisory Committee on Reactor Safeguards 2pp 22662 316
- 8403160067 Transcipt of ACRS Subcommittee on Safety Philosophy. Technology & Criteria 840314 meeting in Washington, DC Pp. 1-171 Supporting documentation encl. ACRS Advisory Committee on Reactor Safeguards 84/03/14 171pp 22659 179
- B403160076 Comments on TRAC-PHR or RELAPS for future development Recommends code development be stopped Code assessment program should be conducted by final user of code CATTON: I ACRS Advisory Committee on Reactor Safeguards B4/01/06 DOEHNERT P ACRS Advisory Committee on Reactor Safeguards Spp 28662 286
- B403160085 Comments on B40103-04 site visit & DL hearing in Apex,NC Requests opportunity to view final control room & new simulator PEAREON,R 0 North Carolina State Univ. Raleigh, NC PEAREON,R 0 ACR8 Advisory Committee on Reactor Safeguards 84/01/05 KERR,H ACR8 Advisory Committee on Reactor Safeguards MAJOR,R North Carolina State Univ. Raleigh, NC 3pp 22662 276 24X Fiche: 50-400.84/01/05,8403160085
- B403170108 Transcript of ACRS 287th general meeting on B40315 in Washington DC, Pp 1-170 Supporting documentation encl * ACRS - Advisory Committee on Reactor Safeguards 84/03/15 237pp. 22668 007
- 8403210084 Transcript of 287th ACRS general meeting on 840315 in Washington, DC Pp 191-287 Supporting documentation encl * ACRS - Advisory Committee on Reactor Safeguards 84/03/15 100pp 22705 186
- 8403220064 Transcript of ACRS Subcommittee on ECCS DHR B40320 mpeting in Washington, DC Pp 1-363 Supporting documentation encl # ACRS Advisory Committee on Reactor Safeguards 84/03/20 479pp 22711:001
- B40922011B Recommends that proposed rule change to 10CFR50, App A be published for public comment & provides editorial comments Change would add human factor design criterion to general criterion.

 KEYBERLING, W. M. ACRS Advisory Committee on Reactor Safeguards B3/12/12 WAND, D. ACRS Advisory Committee on Reactor Safeguards 2pp. 82723, 255
- 8403230121 Transcript of ACRS Subcommittee on ECCS & DHR 840321 meeting in Washington, DC Pp 364-680

 * ACRS Advisory Committee on Reactor Safeguards 84/03/21 481pp. 22727 001
- 8403240297 Transcript of ACRS 840322 seminar on PRA in Washington, DC Pp 1-421 Bupporting documentation encl * ACNS - Advisory Committee on Reactor Safeguards 84/03/22 646pp. 22781 082
- 8403270005 Transcript of 840323 seminar in Washington DC to PRA Pp 422-653 Supporting documentation encl. * ACRS - Advisory Committee on Reactor Safeguards 84/03/23 370pp 22767 001
- B400280241 Questions requirements of Reg Guide 1 97 to insure instrumentation to follow course of accident, including severe accidents, Qualification requirements do not include anything beyond DBA CATTON, I. California, Univ of, Los Angeles, CA CATTON, I. ACRS Advisory Committee on Reactor Safeguards 84/02/17 CAPUCCI.A J ACRS Advisory Committee on Reactor Safeguards 1p 22808 209
- 8403280307 Summary of ACRS Subcommittee on Extreme External Phenomena 831012 maeting w/util, Westinghouse, TERA & Univ of Illinois in Washington, DC re use of tan effect methodology in geismic design analysis at Diablo Canyon, Agenda encl * ACRS Advisory Committee on Reactor Safeguards 83/11/25 ACRS Advisory Committee on Reactor Safeguards. 16pp 22808,040 24X Fiche 50-275,83/11/25,8403280307
- 8403280308 Bummary of ACRS Subcommittee on Human Factors 831130 meeting w/Westinghouse. DRL. Interlock Group & DOE in Hashington, DC re proposed revs to Reg Guides I 149. 1 B. 1 134 & 1.114 & proposed mod to 10CFR50. App A. + ACRS Advisory Committee on Reactor Bafeguards 84/02/24 ACRS Advisory Committee on Reactor Safeguards 33pp 22808 007

- 8403280310 Summary of ACRS Subcommittee on Electrical Sys B31116
 meeting in Washington.DC re FYB5-86 research programs for
 Instrumentation & Control Branch including surveillance &
 diagnostic techniques Agenda & viewgraphs encl
 # ACRS Advisory Committee on Reactor Safeguards 83/12/19
 ACRS Advisory Committee on Reactor Safeguards 17pp 22807 352
- B403280313 Summary of ACRS Subcommittee on Reliability & Probabilistic Assessment 831116 meeting w/GAD in Washington.DC re FY85-86 budget proposals & GAO 830927 ltr concerning PRA * ACRS Advisory Committee on Reactor Safeguards 84/01/23 ACRS Advisory Committee on Reactor Bafeguards 9pp 22807 343
- B403280314 Summarizes IDCDR Fission-Product/Source-ferm meeting Overall treatment given to severe accident problem commendable CORRADINI, M Wisconsin, Univ of Madison, WI CORRADINI, M ACR9 Advisory Committee on Reactor Safeguards 84/02/23 KERR, W Michigan, Univ of, Ann Arbor, MI KERR, W ACRS Advisory Committee on Reactor Safeguards 4pp 22807 337
- B403280316 Submits comments on B31221 containment meeting in Knoxville.

 TN Value of TM1-2 Action Plan as tool for reducing sovers
 accident risk debatable
 BENDER:M Guorytech, Inc. BENDER:M ACRS Advisory Committee on
 Reactor Bafeguards B4/01/31 KERR:H ACRS Advisory Committee on
 Reactor Safaguards 2pp 22797 337
- 8403280320 Summary of ACRS Subcommittees on Reactor Radiological Effects, Air Sys & Waste Mgt 831201-03 meetings w/Bechtel, DDE, Nucleonics Wk & Doub & Muntring in Washington, DC reproposed research ACRS Advisory Committee on Reactor Sefeguards 84/03/15 ACRS Advisory Committee on Reactor Sefeguards 17pp 22807 322
- 8403280326 Comments on ACRS Class 9 Subcommittee 840127 meeting re working draft of final NRC policy statement on severe reactor accidents Math should be carefully reworded to make statements precise & nonrepetitive CGRRADINI,M Micconsin, Univ of, Madison, WI CORRADINI,M ACRS -Advicory Committee on Reactor Safeguards 89/01/30 KERR,W Michigan, Univ of, Ann Arbor, MI KERR,W ACRS - Advisory Committee on Reactor Safeguards 8pp 22779 360
- O403280335 Summary of ACRS Subcommittee on RE Ginna 831116 meeting w/ utils.Gilbert Assoc.Westinghouse.KMC.Inc.Taylor Assoc & LeBoerf.Lambs.Leiby & MacRae in Washington.BC re application to convert pruvisional OL to full-term OL ACRS Advisory Committee on Reactor Safeguards 84/02/10 ACRS Advisory Committee on Reactor Safeguards 20pp 27807 239 24X Fishe 50-244.B4/02/10.G403280335
- 840328034i Forwards rept on 831129-1201 meetings at Marpers Ferry, HV re IDCOR analysis program Gecond meeting on same sub; matter, w/specific preestablished set of questions needed DENDER, M Guerytech, Inc BENDER, M ACRS Advisory Committee on Reactor Safeguards 84/01/04 KERR, W ACRS Advisory Committee on Reactor Safeguards 9pp 22807 194
- 8403280345 Summarizes ACRS Class 9 831012 meeting re 830922 rev to 830805 document, "Severe Accident Decisions for Existing Nuclear Power Plants " Regulatory questions.technical issues & direction of Future meetings addressed CORRADINI.M ACRS Advisory Committee on Reactor Gafeguards 85/10/12 KERRW ACRS Advisory Committee on Reactor Safeguards 22pp 22799 334
- 8403290002 Final response to FOIA request for four categories of documents, tests, studies & analyses referencing or pertaining to NUREG-0103, "STB for B&W PWR" App A documents encl FELTON, J M Division of Rules and Records 84/01/13 MADDEN, I J Kaye, Scholer, Fierman, Hays & Handler App 22816 127 24X Fiche. 50-000, 84/01/13, 8403290002
- --8403290068 Lists proposed reg guides that Engineering 9tds Branch plans to submit to ACRB Safety Outde Subcommittee for consideration at Feb meeting. ARLOTTO.G A Atomic Energy Commission - Directorate of Regulatory Standards 73/03/26 BURNER, ACRS - Advisory Committee on Reactor Safeguards ip 22816 337
- 8403290067 Summary of ACRS Subcommittee on Quality & QA in Design & Const 831206 meeting w/S&W.NUTECH Engineers, Inc. Sandia Labs, EEI. JDU. (asser Assoc, Taylor Assoc, Fauth Assoc, Inc & Bechtel in Waehington, DC & ACMS Advisory Committee on Reactor Safeguards 84/01/25 ACRS Advisory Committee on Reactor Safeguards 17pp 22822 171
- B403290110 Forwards J Preston B30104 memo re generic safety issues prioritization methodology for placement in PDR ROBERTB.B J ACRB - Advisory Committee on Reactor Safeguards 84/03/14 MCKNIGHT.J Distribution Services Branch lp 22822 214

- --8403P90ii3 Advises of review of generic safety issues prioritization methodology described in NUREO-0933 inherent limitations of value impact score formule discussed Use of itructured & itriative consensus judgement methodology recommended PRE510N.J ACRS Advisory Committee on Reactor Safeguards 83/01/04 BENDER.M ACRS Advisory Committee on Reactor Safeguards Safeguards 3pp 22822 215
- 8403290.352 Summary of ACRS Subcommittee on Safety Research Program
 B40111 meeting in Washington, DC to DMB final mark on NRC
 safety research program budget for FY85 & draft version of
 ACRS rept to Congress on related matter Viewgraphs encl
 # ACRS Advisory Committee on Reactor Safeguards 84/02/22
 ACRS Advisory Committee on Reactor Safeguards 22pp 22822 266
- 8403300P40 Summury of ACRS Subcommittee on Human Factors 831207 meeting in Washington. DC re status of ongoing activities in NRC human factors program plan, human reliability data base & uses & review of program budget for FYB5-86 e ACRS Advisory Committee on Reactor Safeguards 83/12/07 ACRS Advisory Committee on Reactor Safeguards 24pp 22842 320
- 8403300246 Commonts on containment performance guidelines.fifth source term meeting & severe accident program for LWR regulation CATTON.I ACRS - Advisory Committee on Reactor Safeguards 84/02/04 HANG.A ACRS - Advisory Committee on Reactor Safeguards App 22840 340

ADVCM NRC ADVISORY COMMITTEE

- 8403080410 Responds to 840214 request for 30-day extension to comment on draft suppl to programmatic EIS Due date for comments extended to 840402 DENYON, H.R. Office of Nuclear Reactor Regulation, Director 84/03/01 MORRIS, A.E. Lancaster, PA. 2pp. 22581 328 24X Fiche 50-320,04/03/01.8403080410
- --B403080412 Requests 30-day extension to comment on programmatic EIS update
 MDRRIS A E Advisory Council for Decontamination of TM1 Unit 2
 84/02/14 PALLADING N J Commissioners 2pp 2258; 327 24X
 Fiche 50-320,84/03/01,8403080410

COMMISSION NRC COMMISSIONERS

- BADDI30.393 Responds to BADIII request for development of facility public safety oversight committee Merits of committee not judged due to util intention not to complete project as nuclear plant PALLADINO, N. J. Commissioners 84/01/31 CDLLINS, M. L. Rentucky, Commonwealth nF. ip 22667 250 24X Fiche 50-398,84/01/31,8402130393
- ~-G402130397 Responds to G31212 request for development of facility public safety oversight committee Merits of committee not judged due to util intention not to complete project as nucliar plant
 PALLADINOLN J Commissioners 84/01/31 BORTZ, A Cincinnati, OH IP 272662 251 24X Fiche 50-338, 84/01/31, 8402130393
- --B402130370 Responds to 831221 request for development of facility public safety oversight committee Merits of committee not judged due to util intention not to complete project as nuclear plant PALLADINO, N J Commissioners 84/01/31 NETZENBAUM, H M Genate, Lnergy & Natural Resources ip 22662 252 24% Fishs 50-358,84/01/31,8402130393
- -8402130353 Responds to 831215 request for development of facility public safety aversight committee Merits of Committee not judged due to util intention not to complete project as huclear plant PALLABINO.N J. Commissioners 84/01/31 CELESTE.R F. Dhio. State of 4pp 22662 253 24X Fiche 50-358.84/01/31.8402130393
- --B402130393 Requests development of proposed facility public oversight cummittee Committee establishment would inspire public confidence GDLLIMS.M i Kentocky. Commonwealth of. 84/01/11 FALLADING.N Commissioners ip 22662 254 24X Fiche 50~358,84/01/31. 8402130393
- ---8402130392 Requests development of public oversight committee to review facility safety-related problems NRC & util credibility questioned as public witness cost overruns & safety flaws METZLNBAUM.H M Senate, Energy & Natural Resources 83/12/21 PALLADINO.N J Commissioners 19 P2662 257 24% Fiche 30-358,84/01/31.8402120393

- --8402130360 Requests changes in proposed facility oversight committee Changes needed to inspire public confidence in oversight process CELESTE, R F Ohio, State of 83/12/15 PALLADINO, N Commissioners ip 22662 258 24X Fiche 50-358,84/01/31, BA00130393
- B402220791 Responds to B31209 ltr in opposition to restart until all outstanding issues resolved PALLADING:N J Commissioners B4/01/31 HEINZ:J Senate lp 22584 306 24% Fiche 70-287,84/01/31.8402220291
- --8493070003 Responds to 831212 ltr expressing concern re protracted time period for resolving TMI-1 restart issue Notice to parties assued on 840127 encl W/o encl PALLADINON J Commissioners 84/01/31 KOLTER, J.P. House of Rep. 1p. 22584 305 24X Fiche 50-289,84/01/31,8402220291
- --8403090004 Responds to 831212 ltr expressing concern re protracted time period for resolving TM1-1 restart issue Notice to parties issued on 840127 encl W/o encl PALLADINO.N J Commissioners 84/01/31 MURPHY.A J House of Rep 1p 12584 307 24X Fiche 50-289.84/01/31.8402220291
- --8403070005 Responds to 831212 ltr expressing concern re protracted time period for resolving TMI-1 restart issue Notice to parties issued on 840127 encl 4/0 encl PALLADINO.N J Commissioners 84/01/31 MURTHA.JP House of Rep 1p 22584 308 24% Fiche 30-289, 84/01/31, 8402220291
- --8403090007 Responds to B31212 ltr expressing contern re protracted time period for resolving TMI-1 restart issue Notice to parties issued on 840127 enc1 W/o enc1 PALLADING, N J Commissioners 84/01/31 CLINGER, W F House of Rep ip 22584 309 24X Fiche 50-289,84/01/31,8402220291
- --840309000B Responds to 931212 ltr expressing concern re protracted time period for resolving TMI-1 restart issue Notice to parties issued on 840127 encl W/o encl PALLADIND, N J Commissioners 84/01/31 OAYDOS, J M House of Rep 1p 22584 310 24X Fiche 50-289, 84/01/31, 8402220291
- --B403090009 Responds to B31212 itr expressing concern re protracted time period for resolving TMI-1 restart issue Notice to parties issued on B40127 oncl W/o encl PALLADINO.N J Commissioners 84/01/31 RITTER,D House of Rep IP 22584 311 24X Fiche 50-289,84/01/31,8402220291
- --8403090010 Responds to 831212 its expressing concern re protracted time period for resolving FMI-1 restart issue Notice to parties issued on 840127 encl W/o encl PALLADINO, N J Commissioners 84/01/31 HARRISON, F House of Rep 1p 22584 312 24X Fiche 50-289, 84/01/31, 8402220271
- --B403090013 Expresses concern re protracted time period for resolution of issues surrounding TMI-1 restart Commission should place primary emphasis on ability of util mgt to operate plant safely GAYENS.J N. KOLTER.J P., MURPHY.A J. House of Rep. 83/12/12 PALLADINO, N., CILLINSKY, V., ROBERTS, T. Commissioners 259 22504 331 24X Fiche 50-289,84/01/31,8402220291
- --8403070011 Expresses concern re protracted time period for resolution of issues surrounding TMI-1 restart Commission should place primary emphasis on ability of util mgt to operate plant safely HARRISON.F House of Rep 83/12/13 PALLADIND.N , OILINSKY,V , ROBERTS, T Commissioners 2pp 22584 327 24X Fithe 50-289,84/01/31,8402220291
- 840:3010024 Responds to PDIA request for documents re petition for rulemaking PRM-50-31 from Citizens Task Force of Chapel Hill.NC Forwards App A documents App B documents completely withheld (ref FOIA Exemption 5) FELION.J M Division of Rules and Records 84/01/18 SHOLLY.S C Union of Concerned Scientists 4pp 22446 035
- --8403010038 Requests documents re petition for rylemaking PRM-50-31 filed by Citizens Task Force & R Bernero B30916 memo to NRC div directors re draft rylemaking on emergency preparedness MARKLY,E J House of Rep , Interior & Insular Affairs B3/09/22 PALLADINO,N J Commissioners ip 28446.040
- 84030i04/7 Responds to 8401i3 ltr re release of radioactive math into atmosphere & embrittlement of containment shells in older nuclear power plants & capability of containment structure to withstand pressurized thermal shock RENION H R Office of Nuclear Reactor Regulation, Director 84/07/15 AMBDRD, D A Affiliation Not Assigned 3pp 22438,300

- --8403010500 Expresses concern re backward shift rotation of plant operators & embrittlement of containment shells in older nuclear power plants due to constant bombardment of high levels of radiation AMDORD, D.A. Affiliation Not Assigned 84/01/13 PALLADIND, N.J. Commissioners ip 22438 303
- 8403050196 Requests to be notified if W0 Bell will continue to be state liaison officer or if new liaison officer will be appointed FALLADINON J Commissioners 84/02/22 ALLAIN,WA Mississippi, State of 2pp 22528 IBS
- B403050200 Forwards rept on administration of FOIA by NRC for CY83, per Public Law 93-502 PALLADING, N J Commissioners B4/02/24 O'NEILL, T P House of Rep. Speaker of the House 1p 22328 167
- --B403050204 Forwards rept on administration of FDIA by NRC for CY83, per Public Law 93-502 PALLADINO, N J Commissioners 84/02/24 BUSH, G H Senate, President of the Senate 14pp 22528 168
- 8403080346 Notifies of reappointment to ACRS
 PALLADING.N J Commissioners 84/02/22 EBERSOLE, J. C Affiliation
 Not Assigned EBERSOLE, J. C ACRS Advisory Committee on Reactor
 Safeguards 1p 22801 321
- 8403030348 Notifies of reappointment to ACRS
 PALLADING.N J Commissioners 84/02/22 SIESS.C P Affiliation
 Not Assigned SIESS.C P ACRS -- Advisory Committee on Reactor
 Safeguards 1p 22501 322
- 8403050362 Forwards responses to B3110B questions for inclusion in record of B30906 hearing re Southeast Interstate Low Level Radwaste Mgt Compact PALLADINO,N J Commissioners B4/02/08 THURMOND.8 Senate, Judiciary 16pp 22519 267
- 8403050379 Requests to be notified if RL Sanders will continue as state limits on officer or if new limits on will be appointed PALLADIND, N J Commissioners 84/02/22 COLLINS, M L Kentucky, Commonwealth of, 2pp 22527-256
- 8403060014 Prepared testimony of NJ Palladino to Subcommittee on Nuclear Regulation.Committee on Environ & Public Works, UB Senate re Commission budget request for FY85 PALLADINO,N J Commissioners 84/02/23 23pp 22548:260
- B40306001B Forwards NRC CYB3 summary of actions taken in response to Comptroller General recommendations. Activities fall short of intent of Recommendation 2 of GAD/RCED-B3-4 re improving reactor operator capabilities W/o encl PALLADING.N J Commissioners. 84/01/31 HATFIELD.M D Senate. Appropriations ip R2528 338
- --8403060023 Forwards NRC CY83 summary of actions taken in response to Comptroller General recommendations Activities fall short of intent of Recommendation 2 of GAD/RCED-83-4 re improving reactor operator capabilities W/o encl PALLADING.N J Commissioners 84/01/31 ROTH,W V Sonate, Governmental Affairs ip 22528 339
- --8403060030 Forwards NRC CY83 summary of actions taken in response to Comptroller General recommendations Activities fall short of intent of Recommendation 2 of GAD/RCED-83~4 re improving reactor operator capabilities W/o encl PALLADINO,N,J Commissioners 84/01/31 BRUDKS,J House of Rep., Qavernment Operations 1p 22328 340
- --8403060037 Forwards NRC CY83 summary of actions taken in response to Comptroller General recommendations Activities fall short of intent of Recommendation 2 of GAD/RCED-83-4 re improving reactor operator capabilities W/o encl PALLADINO.N J Commissioners 84/01/31 SIMP80N,A K Senate, Environment & Public Works ip 22528 341
- --B403060046 Forwards NRC CY83 summary of actions taken in response to Comptroller General recommendations Activities fall short of intent of Recommendation 2 of OAO/RCED-83-4 re improving reactor operator capabilities W/o encl.
 PALLADING,N J. Commissioners 84/01/31 UDALL,N K. House of Rep , Interior & Insular Affairs 1p. 22528 342
- --B403060061 Forwards NRC CYB3 summary of actions taken in response to Comptroller General recommendations Activities fall short of intent of Recommendation 2 of OAD/RCED-83-4 re improving reactor operator capabilities W/o ercil PALLADINO,N J. Commissioners, 84/01/31 OTTINGER,R L House of Rep., Energy & Commerce ip 22528 343

- :8403060065 Forwards NRC CYB3 summary of actions taken in response to Comptroller General recommendations Activities fall short of intent of Recommendation 2 of GAD/RCED-83-4 re improving reactor operator capabilities W/o encl PALLADING, N J Commissioners 84/01/31 WHITTCN, J House of Rep , Appropriations ip 22528 344
- --8403060071 Forwards NRC CYB3 summary of actions taken in response to Comptroller General recommendations Activities fall short of intent of Recommendation 2 of GAD/RECH-083-4 re improving reactor operator capabilities M/o enc!
 PALLADING.N J Commissioners 84/01/31 BOWSMER.C A General Accounting Office 1p 22528 345
- ---8403060074 Forwards NRC CYB3 summary of actions taken in response to Comptroller General recommendations Activities fall short of intent of Recommendation 2 of GAO/RCED-83-4 re improving reactor operator capabilities PALLADING, N J Commissioners 84/01/31 STOCKMAN, D A Office of Management & Budget 7pp 22528 346
- 84030404B7 Weekly info rept for wk ending 840224 REHM.T A Office of the Executive Director for Operations 84/03/01 45pp 22552 116
- 8403070053 Responds to 831214 ltr suggesting Commission refuse to restart Unit 1 until funding for Unit 2 cleanup in place Commission does not believe that Unit 1 restort & Unit 2 cleanup should be tied together PALLADIND, N J Commissioners 84/02/08 MORRIS, A E Advisory Council for Decontamination of TMI Unit 2 1p 22563 198 24X Fiche 50-289, 84/02/08, 8403070053
- --8403070060 Responds to 831213 ltr re criminal indictment of Met Ed % cleanup of Unit 2 Commission does not believe delaying restart would accelerate Unit 2 cleanup Unit 1 restart & Unit 2 cleanup should not be tied together PALLADING, N J Commissioners 84/02/08 MORRIS, A E House of Rep ip 22563 199 24X Fiche 50-289,84/02/08,8403070053
- --B403070069 Responds to B31207 Itr urging Commission not to authorize restart of Unit 1 Commission views on restart set forth in entl B40127 notice to parties Commission does not believe Unit 1 restart & Unit 2 cleanup related PALLADINO.N J Commissioners B470270B GEKAS, 0 W House of Rep 1p 22563 200 24X Fiche 50-289,84702708.8403070053
- --84030/0073 Urges Commission not to accept recommendation to restart Unit 1 in light of agt integrity review & criminal proceedings & slow pace of Unit 2 cleanup GENAS, 6 W House of Rep 83/12/07 PALLADING, N J Commissioners 1p 22563 217 24X Fiche 50-289,84/02/08,840370053
- --B4030/0076 Advises of convictions re Unit 1 restart Due to criminal indictments & belief that Unit 1 revenue should go directly toward Unit 2 cleanup.recommends against restart WALKER.R S House of Rep B3/12/13 PALLADIND,N , ASSELSTINE.J BERNIHAL,F Commissioners ip 22563 218 24X Fiche 50-289, 84/02/08, 84/03070053
- BAO31203/6 Responds to 840107 request for info re accident source term & emergency planning rome Final resolution will not be made until review process complete PALLADING.N J Commissioners 84/02/04 MARKEY.E J House of Rep , Interior & Insular Affairs 3pp 22619 081
- --8403120388 Responds to statements in Markey 840109 ltr re impact of Citi)ens Task Force petition on emergency prepareness rule Rev to emergency preparedness rule independent of source term reevaluation
 DIRCKS.W J Office of the Esecutive Director for Operations 84/01/24 PALLADING.N Commissioners 22pp 22619 084
- --84031P0393 Advises that draft info & documents provided in response to 830922,1028 & 1220 ltrs re offsite emergency preparedness creates impression Chairman position used to pursue politically motivated regulatory changes MARKLY.E J House of Rep., Interior & insular Affairs 84/01/09 PALLADING, N J Commissioners 5pp 22619 094
- 8403140032 Responds to 831206 ltr re Commission consideration of applicant request for Commission approval of restart Final decision will be made in near future PALLADIND,N J. Commissioners 84/03/15 UDALL,M K. House of Rep., Interior & Insular Affairs 2pp 22455 141, 24% Fiche 50-289,84/03/15,8403140032

84/03/01 - 84/03/01 PAGE 1 MONTHLY TITLE LIST U S NUCLEAR REGULATORY COMMISSION

84/03/01 - 84/03/31 PAGE MONTHLY TITLE LIST U S NUCLEAR REGULATORY COMMISSION

8403260106 Provides current status of facility licensing process in response to 840126 ltr Bince 840124 hearings.NRC has continued investigation.insp & evaluation of allegations, which will be resolved grior to low power authorization DENION, HR Office of Nuclear Reactor Regulation, Director 84/03/09 MCCARTHY.L T California, State of 4pp 82761 356 24X Fithe 50-275,84/03/07,8403260105

--84032601); Expresses concern re possibility that facility will be licensed w/o meeting safety stds
MCCARTHY.L T California, State of 84/01/26 PALLADING.N Commissioners Ip 2276; 359 24X Fiche 50-275,84/03/09,8403260106

8403280153 Forwards documents for inclusion in Cheirman 840223 testimony before Senate Subcommittee on Nuclear Regulation, Committee on Environ & Public Works

* Office of Congressional Affairs 84/03/08 Record Services Branch (Document Control Desk) ip 22809 294 24%

Fiche '0-289,84/03/08.8403280153

--B403280157 Testimony of V Gilinsky on B40223 before Subcommittee on Nuclear Regulation, Committee on Environ & Public Works re reprienting NRC toward nuclear operations & budget shifts away from research GILINSKY, V Commissioners 84/02/23 13pp 22809 295

- 8403280160 Statement of JK Asselstine on 840223 re Commission authority to issue temporary OL, review of NRC NSHC determination per tashing to steam generator repairs at TMI-1 & licensing refulm legislation
ASSELSTIME, JK Commissioners, 84/02/23 8pp 22809 308 24X
Fiche 50-289,84/03/08,8403280153

3403280248 Requests info re lack of issuance of revised proposed rule on diverse scram sys for Westinghouse reactors approved on 831103 Commissioners GILINGKY, V Commissioners 84/03/06

3403290087 Forwards rept directed by 830524 House Rept 98-217 re NRC progress on backfitting rule to replace 100F830 109 & measures to control issuance of plant-specific requirements PALLADING.N J Commissioners 84/03/12 BEVILL.T House of Rep , Appropriations 4pp 22822 210

NRC CONTRACTS AND MODIFICATIONS DATRACT

1403010003 Natification of contract execution, Mod 12. to "Technical Assistance in Repository Design" Contractor Golder Assoc BELOATCH, V Technical Assistance Contracts Branch NRC-02-81-037 B4/01/20 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director BUCKLEY, J NRC - No Detailed Affiliation Given in 22479 337

--8403010004 Mod 12.sstending period of performance to 840029 % deleting L Hartung & adding J Buckley as project officer, to "lechnical Assistance in Repository Design "
TALHOT.R Colder Associates GUSTAVE,R P Division of Contracts
NKC-02-81-037 84/01/20 lp 22479 338

1400010019 Notification of contract execution, Nod 15, to "Licensing Technical Assistance" Contractor Science Applications. Inc PAGE. M Technical Assistance Contracts Branch FIN 8-7391-3 NRC-02-60-0035 64/02/22 DAVIS. J Office of Nuclear Naterial Safety & Safeguards. Director LAYSEN, P NRC - No Detailed Affiliation Given 1p 22479 344

--8403010027 Mos 15, extending period of performance of Task Order 001 to 860121 at no addi cost to "Licensing Technical Assistance" * Science Applications, Inc GUSTAVE.R P Division of Contracts FIN 8-7391-3 NRC-02-83-035 84/02/22 Jp 22479 345

3403010035 Notification of contract execution. Mod 9, to "Carebr Counseling " Contractor Binder, Elster, Mendelson & Wheeler PERLMAN, J Administrative Contracts Branch NRC-10-62-358 84/02/21 DORIGH Office of Administration VAN SANTEN, L No Detailed Affiliation Given. 1p 22479, 346

--8403010044 Mod 9.extending period of performance to 850131 & increasing Funds, to "Career Counseling"
MENDELSON, I N. Binder, Elster, Mendelson & Wheeler, Inc.
HAGON, I F. Division of Cantracts. NRC-10-82-358 84/02/21 2pp.
22479-347

403010040 Notification of contract execution Mod 2.to "Subscription Svcs to 1983 Edition of ASME Boiler & Pressure Vessel Code " Contractor ASME WANKING D A Division of Contracts NRC-10-83-369 84/02/22 BEBAM.W J. Division of Technical Information & Document Control CONYNGHAM.M NRC ~ No Detailed Affiliation Given 1p 22479:351 ---8403010045 Nod 2.revising address in Attachment XI.to "Subscription Sycs to 1983 Edition of ASME Boiler & Pressure Vessel Code " SUKOLOHSKI.N American Society of Mechanical Engineers HARAN.T F Division of Contracts NRC-10-83-369 84/02/22 1p 22479 302

8403010051 Natification of contract execution, Mod 4, to "Technical & Engineering Support Svcs for Radio Communications "Contracts DDI MCLEAREN, T Administrative Contracts Branch NRC-10-83-352 84/02/21 CORLEY, J Division of Facilities & Operations COHEN, MEUVILLE, T NRC - No Detailed Affiliation Given ip 22479 349 CHIHEN, B

--8403010060 Mod 4, providing add! funds for FY84 & changing obligation of funds to "Technical & Engineering Support Svcs for Radio Communications" NRC-10-83-352

84030i0070 Notification of contract execution.Mod & to "Analysis of Atmosphere Diffusion Through Application of Lidar Technology "Contractor SRI Intl WDLLETI.S Technical Assistance Contracts Branch FIN 8-6793 NRC-04-81-211 84/02/10 BATSON.W Office of Nuclear Regulatory Research, Director KORNASIEWICZ NRC - No Detailed Affiliation Given 1p 22479 353

--8403010078 Mod &, extending period of performance to 850131 & changing consideration & payment, to "Analysis of Atmospheric Diffusion Through Application of Lidar Technology" HILLY, C.F. SRI International GUSTAVE, R.P. Division of Contracts FIN B-6793 NRC-04-81-211 B4/02/10 2pp 22479 354

8403010071 Notification of grant execution Mod 5, to "Experimental Phase of Development of Noninvasive Liquid Level & Density Gauge for Nuclear Power Reactor Vessels " Grantee Pennsylvania For Nuclear rower needed. ...

State Univ

UMBEL.D Technical Assistance Contracts Branch FIN 0-1029

NRC-G-04-81-024 84/02/14 BATSON.W Office of Nuclear Regulatory
Research, Director CHEN.Y NRC - No Detailed Affiliation Given

1p 22479 357

--8403010098 Mou 5.increasing funds & extending period of performancs to 840531.to "Experimental Phase of Development of Naninvasive Liquid Level & Density Gauge for Nuclear Power Reactor Versets
BABE,K Pennsylvania State Univ , University Park, PA MORTON
Technical Assistance Contracts Branch FIN 9-1053
NRC-0-04-81-024 84/02/14 1p 22479 358

8403010435 Notification of contract execution, Mod 4. to "Stenographic Reporting Sycs " Contractor Tayloe Assoc MCLEAREN, T Administrative Contracts Branch NRC-17-83-399 84/02/24 HOYLE, J C Office of the Secretary of the Commission SULLIVAN, P, MDRAN, D NRC - No Detailed Affiliation Given 1p

-8403010437 Mod 6, extending period of performance to 840315, to "Stemographic Reporting Svcs " R1LEY, A Tayloe Associates HAGAN, TF Division of Contracts NRC-17-83-399 84/02/24 ip 22449 321

8403010461 Notification of contract execution, Mod 9, to "Quantitative Classification of Two Phase Flow Regimes Using Global & Local Neutronic Perturbations II "Contractor Univ of Local Neutronic Perturbations II "Contractor Univ or Hashington UMBEL.ID Technical Assistance Contracts Branch FIN B-6324 NRC-04-78-245 84/02/10 BATSON.W Diffice of Nuclear Regulatory Research, Director SUBER.N NRC - No Detailed Affiliation Given 19 22438 283

--8403010462 Mod 9, extending period of performance to 840331, to
"Quantitative Classification of Two Phase Flow Regimes Using
Global & Local Neutronic Perturbations II"
BALDWIN,D R, Washington, Univ of, Seattle, WA GUSTAVE,R P
Division of Contracts FIN 8-6324 NRC-04-78-245 84/02/10 2pp. 22438 284

8403D1052B Notification of contract execution, Mod 2, to "Automated Library Sys" Contractor On-Line Computer Sys, Inc BASEETY, B Division of Data Automation & Management Information NRC-33-83-454 84/02/24 BROWBERO, B J Administrative Contracts Branch ZUNGOLI S NRC - No Detailed Affiliation Given 1p 22438 344

--8403010534 Mod 2.changing govt property & extending period of performance to 850101 at no add1 cost.to "Automated Library Sys" >> Online Computer Systems, Inc HAGAN,T Division of Contracts NRC-33-83-454 84/02/24 2pp 22438,345

- B403020037 Natification of contract execution "Dresden & Perry Bimulator Leasing," awarded to GE MEBSUP, B Technical Assistance Contracts Branch FIN B-B713 NRC-05-B4-159 84/02/17 HAVENS, D H Director's Office of Inspection and Enforcement 1p 22491 045 24x Fiche 50-000.84/02/17.8403020037
- --8403020043 Contract "Dresden & Perry Simulator Leasing." awarded to GE PIERCE.R L General Electric Co MORTON, K V Division of Contracts FIN 8-8713 NRC-05-84-159 84702/17 38pp 22491 046 24X Fiche 90-000.84702/17.8403020037
- 8403020069 Notification of contract execution, Mod 3. to "Technical Assistance in Defense of Appeal of TERA Advanced SVcs Corp before GSA Board of Contract Appeals " Contractor Dataflow Sys. Inc
 TOWNSEND. B L Administrative Contracts Branch NRC-10-83-368
 84/02/27 NORRY, P G Defice of Administration AVERY, R E NRC No Detailed Affiliation Given 1p 22491 187
- --8403020073 Mod 3, adding computer svcs & changing dollar amount of contract, to "Technical Assistance in Defense of Appeal of TERA Advanced Svcs Corp before OSA Board of Contract Appeals "
 DOUDNIAGOTT, B Dataflow Systems: Inc REBELLO. J E Division of Contracts NRC-10-83-368 84/02/27 1p 22491 190
- --8403020077 Submits proposal to assist in analyzing selected data collected in course of Docket 6713-NRC re NRC Contract 10-83-368 W/o consultants description of projects MALCOM.J B Dataflow Systems. Inc NRC-10-83-368 84/02/21 AVERY.R Commissioners 3pp 22491 191
- 8403050231 Notification of grant execution, Mod 3, to "Study of Steam Water Flows" Grantes Northwestern Univ UMBEL.D Technical Assistance Contracts Branch FIN G-1000 NRC-G-04-B1-020 84/02/13 BATSON, W Office of Nuclear Regulatory Research, Director ZUBER, N NRC No Detailed Affiliation Given 1p. 22527 251
- --8403050237 Mod 3, providing addl funds, extending period of performance to 840930 & changing project officer to "Study of Steam Water Flows"

 GEALY, W J Northwestern Univ , Evanston, IL MORTON, K ,

 Technical Assistance Contracts Branch FIN 0-1000

 NIC-G-04-Bi-020 84/02/13 lp 22527 252
- 8403040471 Notification of contract execution, Mod 3, to "Development of Reg Guide & Regulatory Analyses " Contractor Analysis & Technology, Inc JACOBS, A Technical Assistance Contracts Branch FIN B-8445 NRC-02-83-107 84/02/27 DENTON.H R Office of Nuclear Reactor Regulation, Director BENDER, L NRC - No Detailed Affiliation Given 1p 22552 207
- --8403040498 Mod 3,increasing funding & extending period of performance to 841031,to "Development of Reg Gusde & Regulatory Analyses" JANKGMBKI.S M Analysis & Technology, Inc MORTON, X V Division of Contracts FIN 0-8645 NRC-02-83-107 84/02/27 1g 22552 208
- B403060500 Notification of contract execution, Mad 11, to "Fission Product Transport Analysis " Contractor EMI PAGE M Technical Assistance Contracts Branch FIN B-6747 NRC-04-80-177 84/02/27 BATSON, W Office of Nuclear Regulatury Research, Director WALKER, T NRC No Detailed Affiliation Given 1p 22552 185
- ---8403060502 Mod 11, increasing funding to "Fission Product Transport Analysis" * Battelle Memorial Institute, Columbus Laboratories MORTON, K V Division of Contracts FIN 8-6747. NRC-04-80-177 84/02/27 io 22532 86
- B403070005 Notification of contract execution "Technical Assistance for Support of Const Appraisal Team Insps," awarded to Parameter, Inc WIGGINS, E. J. Technical Assistance Contracts Branch FIN B-8718 NRC-05-84-152 84/02/06 DEYOUNO, R. C. Director's Office, Office of Inspection and Enforcement BAKER, E. NRC No Detailed Affiliation Given 1p 22562 354
- --B403070009 Ltr contract "Technical Assistance for Support of Const Appraisal Team Insps." awarded to Farameter. Inc MDRTUN.K V Division of Contracts FIN B-8718 NRC-05-84-152 B4/02/06 LDFY.R A Parameter. Inc 168pp 22362-355

- 84030700.9 Notification of grant execution.Mod 2.to "Investigation of Recent Crustal Movements in State of ME" Grantes State of ME UNBEL.D Technical Assistance Contracts Branch FIN G-1041 NRC-G-04-82-009 84/02/27 BATSON.W Office of Nuclear Regulator Research Director SCHMITT.T NRC No Optacled Affiliation Given in M2563 194
- --8403070032 Mod 2.providing addl funding to "Investigation of Recent Crustal Movements in State of ME" ANDERSON, R B . ANDERSON, W A Maine, State of MORTON, K V Technical Assistance Contracts Branch FIN G-1041 NRC-G-04-82-007 84/02/27 ip 22543 195
- 0403070039 Notification of contract execution Nod 13 to "Site Suitability Assessments Based on Seepage & Groundwater Conditions Associated W/U Recovery Operations " Contractor Williams & Associated Contracts Granch NRC-02-81-039 84/02/27 SMITH.D R Uranium Recovery Field Office GARCIA.P No Detailed Affiliation Given 1p 22563 196
- ---8403070044 Mod 13.extending period of performance through 840430 at add1 cost to "Bite Suitability Assessments Based on Seepage & Groundwater Conditions Associated W/V Recovery Operations "
 WILLIAMS, R E Williams & Associates GUSTAVE, R P Division of Contracts NRC-02-81-039 84/02/27 ip 22563 197
- 8403070152 Notification of contract execution "Technical Support for Region I NDE Van," awarded to VJ Thompson, Inc TOLSON, V Region 1. Office of Director FIN 8-8361 NRC-28-D4-431 84/02/OB MCOSCAR, J Region 1, Office of Director DURR, J P Na - No Detailed Affiliation Given 1p 22364 327
- ---B403070161 Contract "Technical Support for Region 1 NDE Von," award to VJ Thompson.Inc THOMPSON.V J Vester J Thompson, Jr., Inc MORTON,K V Divisio of Contracts FIN P-B361 NRC-R8-84-431 84/02/08 8pp 228A4 328
- --8403070167 Forwards amend to original Articles of Incorporation Amenchanges name of company to Thompson Engineering Testing. Inc. & decreases par value of stock to correspond w/tax laws Requests contract be amended to reflect name change SRUMACK.JH Vester J Thompson. Jr. Inc. 84/02/08 MORTON.K.Y Technical Assistance Contracts Granch. 7pp. 22564 336
- --8403070172 Forwards Solicitation for Proposals R8-R01-84-431.
 "Technical Support for Region I NDE Van " H/encis MURTON.K V Technical Assistance Contracts Branch 83/10/11 Affiliation Not Assigned 177pp 22964 343
- 8403070319 Notification of contract execution "Structural Integrity of LWR Boundary Components II," awarded to Matls Engineering Assoc. Inc

 LDGLWORTH.P Technical Assistance Contracts Branch NRC-04-84-102

 84/02/10 FOREHAND.B Office of Nuclear Regulatory Research,
 Director VAGINS,M NRC No Detailed Affiliation Given Ip
- --B403070346 Ltr contract "Structural Integrity of LMR Boundary Components - II." awarded to Matic Engineering Assoc.Inc MORTON.K V Division of Contracts NRC-04-84-102 B4702/10 ORFERBLATT,M Materials Engineering Associates, Inc. 1p
- B40G070371 Notification of contract execution, Mod 5, to " Review, Abstract, Index & Guarterly Update Practice & Procedure Digest " Contractor Aspen Sys, Inc PERLMAN, J Administrative Contracts Branch FIN B-1588 NRC-14-82-448 84/02/29 CUNNINGHAM, G H , GRAY, J Dffice of the Executive Legal Director ip 22567 198
- --8403070373 Mod b, extending period of performance to 850228 & increasing funds, to "Review, Abstract, Index & Guarterly Update Practice & Procedure Digest"

 **Aspen Systems, Inc HAGAN.T F Division of Contracts flN B-1588 NRC-14-82-448 84/02/29 lp 22547 199
- 8403070380 Notification of contract execution Mod 5, to "Evaluation of Locations & Rates of Groundwater Discharge from Sheffield Low level Waste Disposel Facility " Contractor USGS PAGE.M Technical Assistance Contracts Branch NRC-02-80-069 84/03/01 DAVIS,J Diffice of Nuclear Material Safety & Safeguards, Director GOODE, D.J. NRC No Detailed Affiliation Oiven ip 22547 041
- --8403070383 Mod 5, changing name of project officer, to "Evaluation of Locations & Rates of Groundwater Discharge from Shaffield Low Level Waste Disposal Facility " * Interior, Dept of, Dealogical Survey SMITH, P Division of Contracts NRC-02-80-049 84/03/01 lp 22567 042

- B4030704il Notification of contract execution,flod 3, to "Major Earthquakes on East Side of New Madrid Earthquake Zone " Contractor Vanderhilt Univ PAGE,M Technical Assistance Contracts Branch FIN B-8078 NRC-04-81-195 B4702/29 BATSON.W Office of Noclear Regulatory Research, Director MURPHY, A NRC No Detailed Affiliation Give Ip 27567 020
- --8403070414 Mod 3,increasing funding to "Major Earthquakes on East Side of New Madrid Earthquake Zone" ¤ Vanderbilt Univ , Nashville, TN SMITH P Division of Contracts FIN B-8078 NRC-04-81-195 84/02/29 ip 22567 021
- 8403070133 Notification of contract execution, Mod 4, to "Non-Equilibrium West leaster to Thosphage Instrumentation " Contractor Heat Transfer & Two-Phase Instrumentation Lehigh Univ

PAGE, N Technical Assistance Contracts Branch Fin B-6794 NRC-04-81-183 84/02/27 BATSON, W Office of Nuclear Regulatory Resealth, Director YDUNG, M NRC - No Detailed Affiliation Given ip 22584 361

- --BA03090135 Mod 4, increasing funding to fully fund contract, to "Non-Equilibrium Heat Transfer & Two-Phase Instrumentation " a Lohigh Univ. Bethlehem. PA MORTON, K V Division of Contracts FIN B-6794 NRC-04-B1-183 84/02/27 19 22584 366
- 8403090138 Notification of contract execution Mod 2, to "Investigation of Alternative Means to Accomplish Goals of Diennial Calibr of Ionization Chambers " Contractor Univ of Wisconsin-MAdison
 PAGE,N Technical Assistance Contracts Branch NRC-04-83-0
 84/02/27 BATSON.W Office of Nuclear Regulatory Research,
 Director YANIV.S NRC - No Detailed Affiliation Given 1
 92598 303 NRC-04-83-002
- --8403090141 Mad 2.revising contract statement of work & schedule for deliverables at no addl cost & incorporating addl general provisions.to "Investigation of Alternative Means to Accomplish Goals of Biennial Calibr of Indization Chambers"
 EMICKSON.R W Wisconsin. Univ of, Madison. WI GUSTAVE, R P Division of Contracts NRC-04-83-002 84/02/27 5pp 22592 30 22592 304
- 840.3) 2027 Notification of contract elecution Mod 5, to "Fire Protection Review Case Work Plants (" Contractor Gage Babcock & Assoc UMBLLU Technical Assistance Contracts Branch FIN 8-8020 NRC-03-82-118 84/03/02 VOLLNER, R H Division of Engineeric NOLAN, NRC No Detailed Affiliation Given 1p 22615 358
- --8403120224 Not 5 revising Article IX re travel reimbursement to "Fire Protection Program Review Case Work Plants 1" * Gage-Dabcock Associates, Inc SMITH, P Division of Contracts FIN N-8020 NRC-03-82-118 84/03/02 ip 22615 359
- 8403120306 Notification of contract execution Mod 5, to "NRC Procurement Training for Project Officers " Contractor Graduate School, USDA PERLMAN, J Administrative Contracts Branch NRC-10-81-402 84/02/28 DDRIE: W Office of Administration UASSIN, C Management Development & Training Staff 1p 22898 357
- -8403120314 Mod 5.adding new course & increasing funds, to "NRC Procurement Training for Project Officers " VARNURLS Agriculture, Dept of Graduate Behool HAGAN, I F Bivision of Contracts NRC-10-81-402 84/02/88 2pp 22896
- 8403120340 Notification of contract execution Mod 2, to "Supervising Human Resources Course" Contractor Oraduate School.USDA PERLMAN. J Administrative Contracts Branch NRC-10-02-366 844002/22 98.DMAN. P J Management Development & Training Staff SPECTUR. A NRC No Detailed Affiliation Given Ip 22619 138
- --8403120345 Mod 2.extending period of performance to 841231 at no add1 cost.to "Supervising Human Resources Course "
 VARNIR.L S Agriculture, Dept of, Graduate School HAGAN,T F
 Division of Contracts NRC-10-82-366 84/02/22 ipp 22619 139
- 8403130474 Notification of contract execution "Page Makerup Svcs." awarded to Photograft Custom Lab. Inc Invitation for bid FIELDS, JA Administrative Contracts Branch NRC-10-84-231 84/02/83 DESAW W J Division of Technical Information & Document Control THOY-THOMPSON NRC - No Detailed Affiliation Given Sp 82634 250
- --B403130495 Solicitation.offer & award of "Page Make-up Sycs" awarded to Photograft Custom Lab. Inc. MATTIA.M J. Division of Contracts NRC-10-84-231 84/02/23 95pp 22634 258

- 8403140325 Notification of contract execution, Mod 4, to "Earthquake ACSIAUSPS Notification of contract execution, Mod 4, to "Earthquake Recurrence Intervals at Nuclear Power Plant Sites "
 Contractor Ertoc Western, Inc
 JACOBS,A Technical Assistance Contracts Branch FIN 8-7226
 ARC-04-81-167 84/03/05 BATSON,W Office of Nuclear Regulatory
 Research, Director MURPHY,A NRC - No Detailed Affiliation Given NRC-04-81-167 84/ Research, Director 1p 2P635 301
- --8403140328 Mod 4.extending period of performance to 840228 at no addl cost, to "Earthquake Recurrente Intervals at Nuclear Power cost to "Eart Plant Sites " MADSEN.S H Erter, Inc GUSTAVE,R P Division of Contracts FIN B-/P26 NRC-04~81-167 64/03/05 lp 22635 302
- 8403150174 Notification of contract execution.Mod 11. to "Memphis Area Regional Selsmic Network New Madrid " Contractor Memphis State Univ JACOBS, A Technical Assistance Contracts Branch FIN B-6276 NRC-04-78-200 84/03/05 BATSON.W Office of Nuclear Regulatory Research, Director MURPHY, A NRC No Detailed Affiliation Olven 1p 22646 266

- ---B403150196 Mod II.extending period of performance to 841130 & increasing funds, to "Memphis Area Spismic Network New Modrid "Supplemental agreement & App A encl CARPINTER.T O Memphis State Univ. Memphis. TN GUSTAVE.R P Division of Contracts FIN B-6276 NRC-04-78-200 B4/03/05 Spp 22646 267
- B403150204 Notification of contract execution, Mod 1, to "Technical Assistance to Bupport IE Personnel in Integrated Design Insp." Contractor Westec Burs, Inc EDGENURTH.P Licensing Branch 3 NRC-05-84-151 84/02/28 M Director's Office. Office of Inspection and Enforcement PARIL NRC No Detailed Affiliation Given 1p 22649 354 PARTLONIJ
- --8403150209 Ltr Contract NRC-05-84-151, Mod 1, increasing funding, to "Technical Assistance to Support IE Personnel in Integrated Design Insp " NORTON, K V Division of Contracts NRC-05-84-151, 84/02/28 BARGLNT, I K Westreco, Inc 1p 22649 355
- --B403150278 Mod 2. extending deliverable items date to 840312, to "Autoprint 1800" "F" Microfiche Printer" * Tameran, Inc. HARAN, T F Division of Contracts NRC-10-83-723 84/03/07 2pp 22662 037
- ---8403150306 Advises that, due to late delivery of Contract NRC-10-83-723, vendor offers to extend warranty period to 180 days & establishes firm delivery date of 840312

 DYBELL.J C Tameran, Inc. NRC-10-83-723 84/02/08 HAHKINB, D

 Division of Contracts 1p 22662 039
- 8403220215 Notification of contract execution, Mod 1, to "Maint & Operation of LPDRs " Contractor Perry, OH Public Library TOWNSEND, B Administrative Contracts Brench NRC-10-83-736 B4/03/12 FELTCH, J M Defice of Administration SOUDER, J No Detailed Affiliation Given ip 22721 359 NRC -
- --B403220219 Mod i, correcting serial number on microfiche reader/printer, to "Maint & Operation of LPDRs " # Purry, OH REBELLO, J E Division of Contracts NRC-10-83-735 B4/03/12 Ip 22721 360
- 8403220240 Contract "Subscription to Energy Daily," awarded to Energy Daily THOMAS.B P Energy Daily, Int MATTIA.M J Division of Contracts NRC~10-84-275 84/02/17 36pp 22739 076
- 8403220256 Notification of contract execution, Mod 1, to "Maint & Operation of LPDRs " Contractor Plymouth, MA Public Library TOWNSEND, B Administrative Contracts Branch NRC-10-83-748 84/03/12 FELTON, J M Office of Administration SCHOER, J No Detailed Affiliation Given. 1p 22723 323 NRC -
- --B403220262 Mod 1.correcting serial number on microfiche reader/printer.
 to "Naint & Operation of LPDRs"
 * Plymouth, MA NRC-10-83-748 84/03/12 1p 22723, 324
- 8403220275 Notification of contract execution, Mod 1, to "Maint & Operation of LPDRs." Contractor Univ of Wisconsin National Development of LPDRs." Contractor Univ of Wisconsin NRC-10-84-253.

 TOWNSEND. B Administrative Contracts Branch NRC-10-84-253.

 B4/03/12 FELTON, J M Office of Administration SQUBER, J No Detailed Affiliation Given ip 22723.313

- --8403220280 Mod 1, correcting serial number on microfiche reader/printer. to "Maint & Operation of LPDRs" * Wisconsin, Univ of, Green Bay, WI REBELLO, J E Division of Contracts NRC-10-84-253 84/03/12 1p 22723 314
- 8403220307 Notification of contract execution.Mod i, to "Maint & Operation of LPDRs" Contractor Greeley CO Public Library MURPHY, LE Administrative Contracts Branch NRC-10-83-742 84/03/08 FELTON, J M Office of Administration SOUDER, J No Detailed Affiliation Given 1p 22723 340 NRC -
- --B403220312 Mod 1, adding serial number for microfiche reader/printer, to "Maint & Operation of LPDRs"

 * Greely, CO REBELLD.J E Division of Contracts
 NRC-10-83-742 84/03/08 ip 22/23 341.
- 8403220316 Notification of contract execution.Mod 2. to "Maint & Operation of LPDRs" Contractor LaCrosse, WI Public Library HOPPER.A Administrative Contracts Branch NRC-10-82-685 84/03/09 FELTON.J M Office of Administration SOUDER.J NRC No Detailed Affiliation Oiven ip 22723 343
- ---B403220319 Mod 2.changing serial number for microfiche reader/printer.
 to "Maint & Operation of LPDRs"

 * La Crosse, WI REBELLO, J E Division of Contracts
 NRC-10-82-685 84/03/09 1p 22723 344
- 8403220325 Notification of contract execution, Mod 1. to "Maint & NOSCENSION OF FIGURE 10 OF CONTRACT EXECUTION, MOD 1, to "Maint & Operation of LPDRs " Contractor Penfield Library, ISseego, N Y HOYLE, A Administrative Contracts Branch NRC-10-83-749 84/03/07 FELTON, J M Office of Administration SOUDER, J NRC ~ No Detailed Affiliation Given 1p 22723 301
- --8403220327 Mod 1,changing serial number on microfiche reader/printer,to "Maint & Operation of LPDRs " * Oswego, NY REBELLO,J E Division of Contracts NRC-10-83-749 84/03/07 ip 22723 302
- B403230044 Notification of contract execution, Mod 1, to "Maint & Operation of LPDRs " Contractor Morris, IL Public Library HOYLE: A Administrative Contracts Branch NRC-10-83-735 84/03/07 FELTON, J M Office of Administration SOUDER, J NRC No Detailed Affiliation Given 1p 22742 361
- --8403230052 Mod 1,changing serial number on 3M microfiche reader printer to "Maint & Operation of LPDRs " * Morris, IL REBELLO, JE Division of Contracts NRC-10-83-738, 84/03/07 ip 22742 362
- 8403230071 Notification of grant execution. Mod 3. to "Development of Radiation Stds " Grantee ICRP UMBEL.D Technical Assistance Contracts Branch FIN 0-1035 NRC-0-04-82-004 84/03/05 BATSON Office of Nuclear Regulatory Research, Director FOULKE, J NRC No Detailed Affiliation Given 22759 280
- -8403230076 Mod B. extending period of performance to 850331 & increasing funds to "Development of Radiation Stds"

 80MBY:F International Commission on Radiological Protection.

 MORTON. K V Division of Contracts FIN 0-1035. NRC-0-04-92-004

 84/03/05 ip 22759 281
- 8403230127 Notification of contract execution "Quantification through Experimentation of Bource Term Lixely to Result from Sabotage of Spent Fuel Bipments," awarded to Battelle Sabotage of Spent Fuel Composition Columbus Labs
 JESSUP.B Division of Contracts FIN B-8997 NRC-04-84-113
 B4/03/01 FOREHAND.B Office of Resource Management, Director
 BARNOLD.A NRC - No Detailed Affiliation Given Ip 22741 307
- ~-B403230130 Contract: "Guantification through Experimentation of Source Term Likely to Result from Sabotage of Spent Fuel Shipments:" awarded to Battelle Columbus Labs BEMELL:H M Battelle Memorial Institute, Columbus Laboratories MORTON,K V Division of Contracts FIN B-8897 NRC-04-84-113 B4/03/01 37pp R2741 308
- 8403230152 Notification of contract execution.Mod 1, to "Maint & Operation of LPDRs." Contractor Crystal River.FL Public Library.
 TGMNBEND. B. Administrative Contracts Branch NRC-10-83-747
 B4/03/12 FELTON,J M Office of Administration SQUDER,J NRC No Detailed Affiliation Given 1p 22743 356
- --B403230154 Mod i,correcting serial number on microfiche reader/printer, to "Naint & Operation of LPDRs " * Crystal River, FL REBELLO, J E Division of Contracts NRC-10-83-747 84/03/12 ip 22743 357

- 8403230159 Notification of contract execution. Mod 2, to "Seismicity of Pacific Northwest (Northern State of CR) " Contractor Univ Pacific Northwest (Northern State of OR) UNDEL.D Technical Assistance Contracts Branch FIN 8-6614
 NRC-04-81-177 84/03/07 BATSON.W Office of Nuclear Reactor
 Regulation. Director ZURFLEUH.E NRC - No Detailed Affiliation
 Given 1p 22743 352
- --8403230160 Mod 2.adding funds & extending period of performance to B41130, to "Seismicity of Pacific Northwest (Northern State RYAN.J F Washington, Univ of Seattle, WA QUSTAVE.R F Division of Contracts FIN B-6614 NRC-04-81-177 84/03/07 1p 22743 353
- 8403260296 Notification of contract execution, Mod 1, to "Maint & Operation of LPDRs" Contractor Salem, NJ Free Library NURPHYLL 9 Administrative Contracts Branch NRC-10-83-752 84/03/08 FELTON.J M Office of Administration SOUDER, J NRC No Detailed Affiliation Given 1p 22759 361
- -8403260307 Mod 1.correcting serial number for microfiche reador/printer.to "Maint & Operation of LPDRs " * Balem, NJ REBELLO, J E Division of Contracts NRC-1083-752 84/03/08 Ip 22759 362
- B4U32AO31A Notification of contract execution Mod 2.to "Electrostatic Copying Svt " Contractor Literature Research Corp PERLMAN. J Administrative Contracts Branch NRC-17-82-474 84/O3/O1 HOYLE, J Office of the Secretary of the Commission KRONEBUSCH, J Public Dolument Branch 1p 22775 306
- --8403260322 Mod 2 adding govt furnished property at no add1 cost,to "Electrostatic Copying Svc " * Literature Research Co HAGAN.T F Division of Contracts NRC-17-82-474 B4/03/01 2pp 22775 307
- 8403240323 Notification of contract execution Nod 19, to "Technical Assistance in Support of NRC Reactor Licensing Actions Proquam 2" Contractor Science Applications, Inc HOLLETT. 5 Technical Assistance Contracts Branch FIN B-8011 NRC-03-82-094 84/03/04 EISENBUT. D Division of Licensing BAJWA, S NRC No Detailed Affiliation Given ip 22775 302
- --8403260941 Mod 19, incorporating award fee garned for June-Nov 1983, to "Technical Assistance in Support of NRC Reactor Licensing Actions Program 2"

 8 Stience Applications, Inc BMITH,P Division of Contracts FIN 11-8011 NRC-03-82-096 84/03/06 3pp 22775 303
- 8403240352 Notification of contract execution, Mod I, to "Maint & Operation of LPRS " Contractor Washington Univ HDPPER A Administrative Contracts Branch NRC-10-64-252 B4/03/09 FELTON J M Office of Administration SOUDER J NRC -No Detailed Affiliation Given 1p 22775 256
- --8403260396 Mod l.changing serial number for microfiche reader/printer-to "Maint & Operation of LPDRs" * Washington Univ.. Bt Louis, MO RECELLO, J E Division of Contracts NRC-10-84~252 84/03/09 ip 22775 237
- 8403260363 Notification of contract execution Mod 1, to "Maint & Operation of LPDRs " Contractor Rochester, NY Public Library HOPPER: A Administrative Contracts Branch NRC-10-83-729 84/03/08 FELTON, J M Office of Administration SQUDER, J NRC No Detailed Affiliation Given ip 22763 361
- ---8403260370 Mod 1, changing serial number of microfiche reader/printer, to "Maint & Operation of LPDRs"

 * Rochester, NY REDELLO, J E Division of Contracts
 NRC-10-83-729 84/03/08 1p 22763 362
- B403270282 Notification of contract elecution Mod I to "Maint & Operation of LPDRs," Contractor Shoreham-Wading River,NY Public Library HDYLE:A Administrative Contracts Branch NRC-10-83-728 84/03/07 FELTON,J M Division of Rules and Records. SQUDER,J NRC No Detailed Affiliation Given 1p 22789 261
- ---8403270284 Mod i changing serial number on 3M 800 microfiche reader/printer, to "Maint & Operation of LPDRs " * Bhoreham, NY REDELLO, J E Division of Contracts NRC-10-83-728 84/03/07 ip 22787 262
- 8403270286 Notification of contract execution, Mod 1, to "Radiation Monitoring Program Requirements" Contractor State of ME UMBEL.O Technical Assistance Contracts Branch FIN 8-8357 NRC-28-83-603 84/03/07 MCOSCAR.J Office of Resource Management. Director KOTTAN.J. NRC No Detailed Affiliation Given Ip 22787 252

- -8403270290 Mod Liproviding funds for CY84 & changing B&R number & NRC authorized representative to "Radiation Monitoring Program Requirements"
 - Requirements" * * Maine: State of SMITH.P A Division of Contracts FIN D-8357 NRC-28-93-603 84/03/07 ip 22787 253
- 8403270302 Notification of contract execution.Mod 1.to "Maint & Operation of LPDRs " Contractor White Plains, NY Public
- HIDYLE, A Administrative Contracts Branch NRC-10-83-730 84/03, FELION, J M Division of Rules and Records SOUDER, J NRC No Detailed Affiliation Given 1p 22787 290
- --B403270306 Mod I changing serial number on 3M 800 microfithe reader/printer to "Maint & Operation of LPDRs " + White Plains, NY REGELLO, J & Division of Contracts NRC-10-83-730 B4/03/07 ip 22789 251
- 84032/0360 Notification of contract execution, Mod 5, to "Evaluation of Matl Accounting Performances at Nuclear Fuel Cycle Facilities" Contractor NUSAC. Inc JACOBS: A Technical Assistance Contracts Branch FIN 8-7379 NRC-02-83-027 84/03/09 BAVIS: J Office of Nuclear Material Safety & Bafeguards, Director MillER, M NRC No Datailed Affiliation Given Ip 22787 342
- --8403270362 Mod 5, issuing change order to statement of work w/funds, to "Evaluation of Mat! Accounting Performances at Nuclear Fuel Cycle Facilities"

 LUMB R F NUSAC, Inc. GUSTAVE.R P Division of Contracts FIN B-7379 NRC-02-83-027 84/03/09 3pp 22/87 343
- 84032/0365 Notification of contract execution, Mod 14, to "Technical Assistance in Support of NRC Reactor Licensing Action Program 2" Contractor Franklin Research Ctr WOLLETT.S Technical Assistance Contracts Branch FIN 8-689/ NRC-03-81-130 84/03/08 EISENHUT.D 8 Division of Licensing CARRINGTON, M NRC No Betailed Affiliation Given ip 22787 339
- --84032/0368 Mod 14.incorporating award fee earned to "Technical Assistance in Support of NRC Reactor Licensing Action Program 2 "
 - * Jianklin Institute/Franklin Research Center St Division of Contracts FIN B-6891 NRC-03-81-130 2pp 22787 340 SMITH P
- 8403280049 Notification of contract execution.Mod 1.to "Criteria for Evaluating Engineered Facilities" Contractor US Army Corps of ingineers or ingineers FLEENDR.CC Technical Assistance Contracts Dranch FIN D-1001-4 NRC-02-83-046 84/03/06 DAVIS,J Office of Nuclear Material Bafety & Safeguards, Director SHAFFNER,J NRC - No Datailed Affiliation Given 1p 22812 336
- --8403200052 Nod 1-authorizing commencement of Task 2 & providing incremental funds to "Criteria for Evaluating Engineered Facilities "
- 9403290186 Notification of contract execution, Mod 1, to "Maint & Operation of LPDRs," Contractor Sacramento, CA Public Library HDYLE, A Administrative Contracts Branch NRC-10-83-737 B
- HBYLE, A Administrative Contracts Branch NRC-10-83-739 84/03/07 FELTON, J M Division of Rules and Records Science, J NRC No Detailed Affiliation Given 19 22808 212
- --8403280187 Nod i changing serial number on 3M 800 microfiche reader/ printer.td "Maint & Operation of LPDRs" * Secremento, CA REBELLO, JE Division of Contracts NRC-10-83-739 84/03/07 tp 22808 213
- 8403280260 Notification of contract execution "Installation, Deinstallation & Maint Support for High Frequency, VFF & UHF Radio Equipment Owned & Operated by NRC," awarded to Tactec Radio Equipment unner & operate = 5, Sys. Inc BAZIN.J P Administrative Contracts Branch NRC-10-84-239 84/03/09 CORLEV.J H Division of Facilities & Operations CUHEN.S NRC - No Detailed Affiliation Given 1p 22800 081
- --8403280263 Contract "Installation Deinstallation & Maint Support for High Fraquency, VHF & UHF Radio Equipment Owned & Operated by NRC: " awarded to Tactec Sys. Inc * Tacter Systems, Inc MATTIA, M J Division of Contracts NRC-10-84-239 84/03/09 41pp 22808 082
- 8403290338 Responds to FOIA request for contract & mods resulting from RFP RS-RES-83-025. Forwards documents listed on app Decuments also available in PDR FELTON.JH Division of Rules and Records 84/03/05 DAVIS,K,L Trammp11, Chase, Lambert & Martindale 2pp 22818 274

- --8403270343 Ltr Centract NRC-04-84-102, "Structural Integrity of LHR Boundary Components II." awarded to Matls Engineering Assoc.Inc MORTUN.K V Technical Assistance Contracts Branch NRC-04-84-102 84/02/10 GREENBLATT.M Materials Engineering Associates, Inc 77pp 22618 279
- 8403300309 Notification of contract execution.Mad 2, to "Ultrasensitive Bicassay Measurements Using Sputter Initiated Resonance Ionization Spectroscopy " Contractor Atom Sciences. Inc. UNIBEL. B Tochnical Assistance Contracts Branch FIN D-1127 NRC-04-83-180 84/03/20 FOREHAND.W Office of Nuclear Regulatory Research, Director NEEL.R NRC No Detailed Affiliation Given Ip 22845 035
- --8403300312 Mod 2, changing period of performance end date to 840930, to "Ultrasensitive Bidassay Measurements Using Sputter Initiated Resonance Innization Spectroscopy "
 SCHMITT,H W Atom Sciences, Inc SMITH.P A Administrative Contracts Branch FIN D-1127 NRC-04-83-180 84/03/20 lp 82849 036
- FOIA FREEDOM OF INFORMATION ACT REQUESTS AND RELEASES
- B310200141 Requests that listed documents be made available based on B31004 memo ro Board Notification B3-151 on Westinghouse ECCS actuation logic POLLANDER B Union of Concerned Scientists B3/10/18 EISENHUT, D G Division of Licensing ip 22547 292
- 8401230630 Partial response to FOIA request for IE 800103 rept re review of math false statement at facilities, associated & supporting records to rept & repts prapared in response. Forwards App A documents Review of addit records in progress FELTON. J H Division of Rules and Records 83/11/01 WINSLOW, R Hall Street Journal 2pp 21905 337 24X Fiche 50-329.83/11/01, 2001230.530 8401230630
- --B401230660 PND-79-039 on 790305, investigation concluded that GA progreator obtaining proper soil compaction of facility deficient excessive settlement observed widesol generator bldg & incorrect infe re soil foundation contained in FSAR SHEWMAKER, R E . HENDERSON, J B . THORNSURG, H D Office of Inspection & Enforcement. Office of the Director 79/03/06 2pp 21905 352 24X Fiche 50-329.83/11/01.8401230630
- 0402090003 Responds to FDIA request for const completion dates for nuclear plants currently under const & analyses containing estimates based on inclusion of Caseload Forecast Panel meetings Forwards App AB & C documents

 FELTON, J M Division of Rules and Records 83/10/31,

 ROSENDAUM, D M Technical Analysis Corp 19pp 22193 292 24X

 Fiche 50-000, 83/10/31,8402090003
- --B402090183 Handwritten notes & calculations re const activities & fuel load preparation

 * NRC - No Detailed Affiliation Given 79/07/24 5pp
 22/95 057 24X Fiche 50-000,83/10/31,8402090003
- --B402090186 Handwritten calculations & graphs re const activities & preoperational & acceptance testing Related info encl. * NRC No Detailed Affiliation Given 81/09/16 6pp 22196 191 24X Fiche 50-000,63/10/31.8402090003
- 8402:40014 FOIA request for records re NRC const assessment team (CAT) insp at facilities
 BERNABFI, L Government Accountability Project 83/10/07 Of of Administration 2pp 22254 OO1 24X Fiche 50-528,83/10/07.
- 8402140018 Responds to FOIA request for records re NRC const assessment team (CAT) insp at facilities Forwards App A documents
 Documents also in PDR App B documents listed for review to identify specific interest
 FELTON, J M Division of Rules and Records 83/12/20 GARDE, B P
 Government Accountability Project 18pp 22254 003 24X
 Fiche 50-528,83/12/20,8402140018
- --8402140022 Summarizes civil insp items Bechtel 830929 ltr re reinsp of nuclear pipe hangers (Q class) & related info encl VORDERBRUGGEN Region 5. Office of Director 83/09/19. NARBUT,P NRC No Detailed Affiliation Given. 60pp 22954,021 24X Fiche 50-528,83/12/20,8402140018
- --8402140026 "Insp Plan " Draft autline given to inspectors on 830906 encl. * NRC - No Detailed Affiliation Given 83/12/20 12pp PR254 OB1 24X Fiche 50-528,83/12/20,8402140018

- --B40214002B Provides addl info re 830730 gxit interview meeting w/const assessment team for preliminary review of findings NRC criteria utilized during insp more applicable to operating plant Related info encl WODBS.T G Arizona Public Service Co 83/10/12 MARTIN.J B Region 5. Office of Director 339pp 22254 320 24X Fiche 50-528.83/12/20.8402140018
- ---B402140031 Comments on review of draft writeup on NDE Rewrite requested Related info encl NARBUT.P NRC - No Detailed Affiliation Given 83/09/27 KERCH,H NRC - No Detailed Affiliation Given 41pp 22254 094 24X Fiche 30-528,63/12/20,8402140018
- --8402140032 Summary of B30916 exit status meeting w/NRC const appraisal team re 830907-16 insp
 IDE; W E Arizona Public Service Co 83-C-83/WEI 83/09/19
 ROEDEL, J A Arizona Public Service Co 4pp 22254 137 24X
 Fiche 50-528
- --8402140036 Forwards marked-up draft insp scape & objectives Related info encl
 ALBERT, W G Region 5, Office of Director 83/09/21 YOUNG, 1
 Region 3, Office of Director 18pp 22254 143 24X
 Fiche 50-528,83/12/20,8402140018
- --8402140037 Corrective action request re piping cleanliness.per Procedure WPP/QCI 204 O.Rev 2. "Piping Sys Release for Insulation " Related info encl GAITHER.C F Arisona Public Service Co 83/09/13 25pp 22259:299 24X Fiche 50-528.83/12/20,8402140018
- ---8402140038 Forwards feeder rept re insp activities at facility Combined insp of concrets expansion anchor bolts & embedded plates will be written by L Vorderbrueggen Radiographs reviewed will he included in H Kerch rept. Related info encl WALTON.0 A Region 1. Office of Director 83/10/07 YOUNG.T Region 5. Office of Director 155pp 22254 165 24X Fiche 50-528,63/12/20,8402140018
- ---B402140043 Provides list of NDE repts available from insplactivities completed w/NRC mobile NDE van at facility,per FOIA request Related info encl
 EBNETER 8 D Region 1, Office of Director, 83/11/15
 ALEXANDER,I M Region 5, Office of Director 99pp 22255 324
 24X Fichs 30-528,83/12/20,8402140018
- --B40214004B Rev O to "Palo Verde Station HPSI Sys Electrical & Instrumentation Const Audit Insp." final rept Related info encl * Zytor, Inc NRC-1E-82/83-44C HSB PARODO3 83/10/04 158pp 22255 063 24X Fiche 50-528,83/12/20,8402140018
- ---B402140052 Provides resolution for loose bolts on structural steel found during NRC const assessment team (CAT) insp Item considered closed Related info encl FORRESTER.R D Arizona Public Service Co 83-C-87/RDF B3/09/26 IDE.W E Arizona Public Service Co 3pp 22256 221. 24X Fiche 50-528,83/12/20,8402140018
- --8402140022 Summarizes civil insp items Bechtel 830929 ltr re reinsp of nuclear pips hangers (g class) & related info encl VORDERBRUEGGEN Region 5. Office of Director 83/09/19 NARBUT,P NRC - No Detailed Affiliation Given 60pp 22254 021 24X Fithe 50-528,83/12/20,8402140018
- ---84021400R4 "Insp Plan " Draft outline given to inspectors on 830906 encl * NRC - No Detailed Affiliation Given 83/12/20 JPpp 22254 081 24X Fiche 50-528,83/12/20,8402140018
- --8402140028 Provides add1 info re 830930 exit interview meeting w/const assessment team for preliminary review of findings NRC criteria utilized during insp more applicable to operating plant. Related info enci HQDDB, T 0 Arizona Public Bervice Co 83/10/12 MARTIN, J B, Region 5, Office of Director 339pp. 22254 320 24X Fiche. 50-528, 83/12/20, 840214/018

- ---8402140036 Forwards marked-up draft insp scope & objectives Related info encl ALBERT, W G Region 5. Office of Director 83/09/21 YOUNG, T Region 5. Office of Director 18pp 22254 143 24X Fiche 50-528,83/12/20.8402140018
- --8402140037 Corrective action request re piping cleanliness.per Procedure WPP/GCI 204 O.Rev 2. "Piping Sys Release For Insulation" Related info encl GAITHER, C F Arizona Public Service Co 83/09/13 25pp 22255 297 24X Fiche 50-528,83/12/20.8402140018
- --8402140038 Forwards feeder rept re insp activities at facility Combined insp of concrete expansion anther bolts & embedded plates will be written by L Vorderbrueggen Radiographs reviewed will be included in H Kerch rept Related info encl WALTON.G A Region I, Office of Director 83/10/07 YOUNG.T Region 5. Office of Director 155pp 22294 165 24X Fiche 50-528,83/12/20.8402140018
- --B402140043 Provides list of NDE repts available from insplactivities completed w/NRC mobile NDE van at facility, per FDIA request Related info encl
 ENNETER, S.D. Region 1, Office of Director 83/11/15
 ALEXANDER, I M. Region 5, Office of Director 97pp 22255 324
 24% Fiche 50-528, 83/12/20,8402140018
- --8402140048 Rev 0 to "Palo Verde Station HPSI Sys Electrical & Instrumentation Const Audit Insp." final rept Related info encl.

 * Zytor, Inc NRC-1E-82/83-46C HSB PAROUGS 83/10/04 158pp 22256 063 24X Fiche.50-528,83/12/20,8402140018
- --8402140052 Provides resolution for loose bolts on structural steel found during NRC const assessment team (CAT) insp Item considered closed Related info encl FORRESTER.R D. Arizona Public Service Co 83-C-87/RDF 83/09/26 IDE,W C Arizona Public Service Co 3pp 22256 221 24X Fiche, 50-528, 83/12/20, 8402140018
- 8402230207 Further response to FOIA request for documents re const flaws at facility Forwards documents listed in App A Documents also being placed in FDR & LPDR Review continuing FELTON.J M Division of Rules and Records 83/12/02 VADEN.T News & Observer/Raleigh Times. Raleigh. NC 3pp 22378 299 24X Fiche 50-400.83/12/02.8402230207
- --8104P10125 Discusses implications of Dfc of Inspector & Auditor 781012 interview w/facility ASLB Ofc of Inspector & Auditor attempted to probe thought processes of & require justification from Board re action taken in adjudication YORE, J.R. Atomic Safety and Licensing Board Panel. 78/10/19 HENRIELJ N. Commissioners. 3pp. 22378 302 24X Fiche 50-400,83/12/02,8402230207
- --8402230226 Forwards Oft of Inspector & Auditor "Inquiry into Alleged Omistion of Line Inspector Views from CP Hearing " No further distribution should be made outside of oft Rept under Commission review.

 QSSSICK,L V Office of the Executive Director for Operations 78/11/13 DENTON Office of Nuclear Reactor Regulation. Director SHAPAR Office of the Executive Legal Director DAVIS Office of Inspection & Enforcement. Office of the Director ip 22378 305 24X Fichs 50-400.83/12/OR.8402230207
- --B402230237 Discusses investigation by Ofc of Inspector & Auditor (OIA) re facility proceeding ASLAB unwilling to be interrogated by OIA Many questions in OIA interrogation of members of ASLU manifestly improper ROBENTHAL.A S Abomic Bafety and Licensing Appeal Panel 76/10/20 HENDRIE Commissioners 2pp 22/178/306/24X Fiche 50-400.83/12/02.8402230207
- --8402230239 Forwards Apps A.B.C & D to be included w/questions for Panel III re facility testimony Related info encl MURPHY, C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 78/11/16 REIB, E J Office of the Executive Legal Director Sipp 22378 308 24x Fichs 50-400, 83/12/02, 8402230207
- --8402230242 Requests that interim guidance re preparation of staff testimony in NRC adjudicatory proceedings be transmitted to all personnel involved. Ofc directors should Carefully review existing procedures for NRC testimony Related info encl GOSBICK.L V. Office of the Executive Director for Operations 79/03/30 NRC No Detailed Affiliation Given 5pp 22377 02/
- --8402230246 Ack 820310 conversation re allegations by facility employee D Jarvis, per Regional Ofc Instruction 2231. Rev 2. Paragraph 2 C (3) Case file encl MAXMELL.g. Region 2. Office of Director 82/05/10 VORSE.J NRC No Detailed Affiliation Given 2pp 22377 032 24X Fiche: 50-400, 83/12/02, 8402230207

- -8402230248 Requests that Region II civil insp personne) investigate allegations by Unidentified individual re coatings during next routine insp at site Case chronology encl MAXMCLL.6 F Region 2. Office of Director 82/07/07 VORSE, J NKC No Detailed Affiliation Given 2pp 22379 034 24X Fiche 50-400,83/12/02,8402230207
- ~8402230251 Matl maint requirements for Procedure AF-XIII-07,
 "In-Storage Insp & Haint " Equipment purchase order form
 encl
 * Carolina Power & Light Co 83/12/02 9pp 22379 040 24X
 Fiche 30~400,83/12/02,8402230207
- 402270263 Responds to FOIA request for JC Mark 801204 memo to ACRS re hydrogen burn w/igniters & documents concerning generation, combustion or control of hydrogen in reactor accidents Forwards App A documents App B documents in FDR FELION. J M Division of Rules and Records B4/01/30 HIATF, S L Ohio Littlens for Responsible Energy 7pp 22412 051 24X Fiche 50-300.84/01/30.8402270263
- -84022/0314 Forwards summary of investigations to hydrogen recombiners & roley failures in HPCI bys
 ZUKCR.D J ACRS Advisory Committee on Reactor Safeguards
 80/10/30 MOELLER.D W ACRS Advisory Committee on Reactor
 8afeguards App 22412 086 24X Fiche 50-000,84/01/30,8402270263
- 403010010 F01A request for documents re TMI-1 Restart Issues Task Forct to be placed in PDR SMOLLY.9 C Union of Concerned Scientists B3/12/12 FELTON, J M Division of Rules and Records ip 82446 056 24X Fishe 50-289, B3/12/12, B403010010
- 403010013 Further response to FDIA request for documents be PRA & evocuotion time estimates Forwards "Review & Evaluation of GFSSAR-II PRA-Containment Failure Modes & Fission Product Release "Rept partially withheld (ref FDIA Exemption 4) FCLION.J M Division of Rules and Retords 84/01/03 HIATT.S Ohio Citizens for Responsible Energy 4pp 22445 276 24X Fishe 50-447.84/01/03.8403010013
- -8308170191 "Review & Evaluation of GESSAR-II Probabilistic Risk Assersment - Containment Failure Modes & Fission Product Release," ltr rept # Byookhaven National Laboratory 83/07/27 Division of Systims Integration (post 811005) 180pp 66922 190 24X Fiche 50-447.84/01/03,8402010013
- 403010014 Partial response to FOIA request for documents Te TM1-1 Restart Issues Task Force Forwards documents listed on app Info also available in PDR IEL10N.J M Division of Rules and Records 84/01/03 SHOLLY.S C Union of Concernod Ecientists 2pp 22446 057 24X Fishe 20-287.84/01/03.8403010014
- --8305110054 Informs that reevaluation of Cycle 5 reload application, has identified two issues re nonconservative cladding swc)ling 4 repture models to IAFY/TACO penalty proposed by IRW that should be resolved prior to restart.

 RMSE-NSTEIN.L 9 Assistant Director for Core & Plant Systems TAC 1513/9 83/05/02 LAINAS, GC C Assistant Director for Operating Reactors 5pp 22445 212 24X Fiche 50-289,84/01/03,8403010014
- --G403010020 Assigns recipients to TMI-1 Restart Issues Task Force to verify that NRC requirements for restart correctly identified 8 facility treated similar to all operating plants for other NRC requirements
 EISENHUTLOG Division of Licensing STARDSTECKI, R Division of Project & Resident Programs B3/04/15 JACOBS, R Region 1, Office of Director VAN VLIET, J. DIIANNI, D Division of Licensing Ip 22446 059 24X Fiche 50-289, 84/01/03, 8403010014
- --B403010023 Responds to B30415 memo & Forwards "Rept of TNI-1 Restart Issues Task Force Members " Meeting requested to respond to questions WILLIAMS.M H IMI-1 Restart Issues Task Force 83/04/29 EISENNUT.D & Division of Licensing STARGSTECKI.R Division of Project & Resident Programs 1p 22446 060 24% Firlie 50-289.84/01/03.8403010014
- --8403010030 "Rept of TMI-1 Restart Issues Task Force Members "
 WILLIAMS.M., VAN VLIET.J., YOUNG.F TMI-1 Restart Issues Task
 Force 83/04/29 150pp 22446 061 24X Fichs 50-289,84/01/03,8403010014

- --8403010043 Forwards input to 830429 TMI-1 Restart Issues Task Force rept Info derived from ASLB partial initial decisions in restart proceedings Related info encl GCLIDERG, J R Office of the Executive Legal Director 84/01/03 HILLIAMS, M Division of Licensing 19pp 22446 274 24X Fich
- 8403010016 Further response to FOIA request for 16 categories of documents Forwards MJ Dircks 811219 ltr re 810606 sabotage event & special rept to Commonwealth of PA Info partially withheld (ref FOIA Exemption 3) FELION.J M Division of Rules and Records 84/01/04 SHDLLY,8 C Union of Concerned Scientists 2pp 22479 076 24% Fiche 50-334,84/01/04.8403010016
- --8403010032 Responds to 811021 % 1104 requests for info re 810606 sabotage event at facility Details withheld (1ef 100fR73 21)
 DIRCKS,W J Office of the Executive Director for Operations 81/12/19 TAYLOR,F R Pennsylvania, Commonwealth of, 2pp 22479 080 24% Fiche 50-334,64/01/04.8403010016
- --8403010061 "Response to Apparent Act of Sabotage at Beaver Valley, Unit i " Info partially deleted (ref 10CFR2 790(d) & 10CFR73 21)
 * NRC No Detailed Affiliation Given 84/01/04 App 22479 112 24% Fiche 50~334, 84/01/04, 8403010016
- B4030i00i8 F01A request for 1982 NUREG/CR-2815, "NRC.Natl Reliability Evaluation Program (NREP) Procedures Guide " BETCHFR.JL Northern States Power Co 83/12/15 BELTON,J Office of Administration 1p 22477 001
- 8403010021 FOIA request for documents re petition for rulemaking PRM-50-31 from Citizens Task Force of Chapel Hill.NC SHOLLY.8 C Union of Concerned Scientists B3/10/31 FELTON, J M Division of Rules and Records 1p 22446 034
- 8403010024 Responds to FOIA request for documents re petition for rulemaking PRM-50-31 from Citizens Task Force of Chapel Hill NC Forwards App A documents App B documents completely withheld (ref FOIA Exemption 5) FELTON, J M Division of Rules and Records 84/01/18 SHOLLY, S C Union of Concerned Scientists 4pp 22446 035
- --8301060420 Requests review & comments re encl draft FR notice to deny Citizens Task Force of Chapel Hill.NC petition for rulemaking (PRM-50-31) W/o encl NORBIRG, J Human Factors & Safeguards Branch 82/12/27 BASSLTT.O E Division of Accident Evaluation (Pre 840101) 2pp 22446 041
- --8305040013 Informs that reply to petition for rulemaking PRM-50-31, filed 811202, will be delayed until May 1984 since NRC is reevaluating severe accident radiation source terms & technical basis for 10-mile emergency planning rone radius PHILLIPS. J D Division of Rules and Records 83/04/13 KATB, G H Citizens' Task Force 1p 22446 039
- --8403010038 Requests documents re petition for rulemaking PRM-50-31 filed by Citizens Task Force & R Bernero 830916 memo to NRC div directors re draft rulemaking on emergency preparedness MARKEY.E J House of Rep. Interior & Insular Affairs, 83/09/22 FALLADING.N J Commissioners ip 22446-040
- --8403010046 Forwards predecisional documents re smergency preparedness per request Documents do not represent NRC proposed or actual policy Package should be restricted to subcommittee members & staff only M/o encl
 KAMMERER, C Office of Congressional Affairs 83/10/28
 OTTINGER, R L House of Rep , Energy & Commerce 1p 22446 043
- --8403010049 Forwards predecisional documents re emergency preparedness per request Documents do not represent NRC proposed or actual policy. Package should be restricted to subcommittee members & staff only W/o pncl KAMMLRER.C Office of Congressional Affairs 83/10/28, SIMPSON, A Senate, Environment & Public Works ip 22446 044
- --0403010054 Forwards predecisional documents re emergency preparedness per request Documents do not represent NRC proposed or actual policy. Package should be restricted to subcommittee members & staff only M/o anct KAMMERER. C Office of Congressional Affairs. 83/10/28 UDALL, M House of Rep , Interior & Insular Affairs. ip 22446,045.
- --8403010058 Forwards predecisional documents re emergency preparedness per request Documents do not represent NRC proposed or actual policy Package should be restricted to subcommittee members & stoff only H/o encl KAMMERER.C Office of Congressional Affairs 83/10/28 BEVILL,T House of Rep., Appropriations 1p 22446-046

- ---B403010063 Forwards predecisional documents re emergency preparedness per request Documents do not represent NRC proposed or actual policy Package should be restricted to subcommittee members & staff only W/o encl

 KAMMCRER.C Office of Congressional Affairs 83/01/28

 HATFIELD.M O Benate. Appropriations 1p 22446 047
- --8403010067 Forwards predecisional documents re emergency preparedness per request Documents do not represent NRC proposed or actual policy Package should be restricted to subcommittee members & staff only W/o encl
 KAMMEREN, C Office of Congressional Affairs 83/10/28
 DINGELL, J House of Rep., Energy & Commerce 1p 22446 048
- --B403010074 Forwards review comments on draft RES denial of petition for rulemaking on emergency planning zone at nuclear power plants, per request General comments encl HULMAN.L C Accident Evaluation Branch B3/01/07 COTA,P C Research & Standards Coordination Branch 7pp 22446 049
- B403010026 Responds to FDIA request for 1982 NUREO/CR-2815, "NRC, Natl Reliability Evaluation Program (NREP) Procedures Quide " Forwards NUREO FELTON, J M Division of Rules and Records 84/01/04 DETCHER, J L Northern States Power Co 1p 22477 002
- ---8403010041 NUREQ/CR-2815 DRFT
 Draft PROBABILIBIIC SAFETY ANALYSIS PROCEDURES QUIDE
 BARIA A . BUBLIK.A. J Brookhaven National Laboratory
 EL-DABSIDNI,A Office of Nuclear Reactor Regulation, Director
 FIN A-3382 BNL-NUREO-51559, 83/09/01 NRC No Detailed
 Affiliation Given 23ipp 22477 003
- 8403010050 Third partial response to FDIA request for six categories of documents re facility Forwards App A documents App A documents also placed in PDR App B documents will be placed in PDR upon request Review continuing FELTON.J M Division of Rules and Records 84/01/17 ANDERSON.8 I Garvey, Schubert, Adams & Barer App 22446 293 24X Fiche 50-000,84/01/17,8403010050
- ---8003240159 Advises of refund owed licensee re CP fees for facilities based on professional manpower extended & contractual sycs costs incurred.

 MILLER, W O License Fee Management Branch 80/03/03 MANION, W E Office of the Controller 2pp 22445 303 24X

 Fiche 50-000,84/01/17,8403010050
- --B004010752 Confirms 800229 telcon re professional manpower (152-h) provided by 800228 memo Manpower should be divided equally between two units HOLLOWAY, C. J. License Fee Management Branch 80/02/29 F1711, C. J. Atomic Safety and Licensing Board Panel ip 22446 300 24X Fiche 50-000,84/01/17.8403010050
- ---8004010757 Confirms B00226 telcon re professional manpower (18-h) provided by A Rosenthal 781002 mems Manpower should be divided equally between two units HULLGUMAY.C J License Fee Management Branch 80/02/27 BISHOP.J Atomic Safety and Licensing Appeal Panel ip 22446 301 24X Fiche 50-000,84/01/17,8403010050
- --8i12020204 Forwards new format for nuclear power plants const status rept, NUREO-0030 (yellow book) New format should be used to provide next update info for planned Noy 1981 publication (data as of Sept 30.1981) due 811120 M/o encl HARTFIELD,R A Office of Management and Program Analysis 81/10/30 DUNN,C N, Duquesne Light Co 9pp 22446,305 24X Fiche 50-000,84/01/17,8403010050
- ---8112210135 Informs of B McKinney opinion that allocation of ACRS manpower for fee purposes should be divided equally for reviou of two units at site HOLLOHAY, C. U License Fee Management Branch 79/01/22 License Fee Management Branch 1p 22446 297 24X Fiche 50-000,84/01/17.8403010050
- ---B2J1090018 Advises that branch will wait to determine what action util plans to take in response to ABLB 820618 order before collecting prof NRC hours & contractual costs & billing util for review of withdrawn application
 MILLER.W D License Fee Management Branch B2/10/04 License Fee Management B7-0000,84/01/17, 8403010050
- --B302250083 Responds to questions re application termination Notice of termination/withdrawal not anticipated No time limitation pleted on completion of Phase One review ADENBAME O Licensing Branch 4 83/02/17 MILLER, W.D. License Fee Management Branch ip 22446 321 R4X Fiche 50-000,84/01/17,8403010050

- --B304060552 Requests search for relevant documents re govt litigation w/util Response due by 830408 GRIMSLEY.D H NRC No Detailed Affiliation Given 83/03/29 FITT).C Atomic Safety and Licensing Board Panel 1p 22446 314 24% Fiche 50-000.84/01/17.8403010050
- --8305070506 Requests advice re fee assessment cutoff date for reactor CP & OL applications that are withdrawn denied suspended, cancelled or postponed MILLERW O License Fee Management Branch 83/05/04 FONNER, R L Office of the Executive Legal Director 3pp 22446 315 24X Fish: 50-000, 84/01/17, 8403010050
- --B30B1004B3 Discusses status of OL applications Review of encl MPPSB B30712 ltr requested in order to determine present status of Unit 3 for billing purposes W/o encl MILLER.W O License Fee Management Branch B3/08/05 FONNER.R L Regulations Division 2pp 22446 326 24X Fiche 50-000, B4/01/17, 8403010050
- 8403010068 Add1 response to FDIA request for two categories of documents re IDCDR program Forwards document Documents also available in PDR FELTON, J M Division of Rules and Records 84/01/03 SHOLLY, S C Union of Concerned Scientists 1P 22449 307
- --8403010074 Forwards core debris dispersal & vessel failure issue summary, developed at IDCOR B31129-1202 meetings in Harpers Ferry Steps taken to fulfill agreement of close cooperation among interested party in test data analyses POMERS.D A Sandia Laboratories 83/12/05 ROSENTHAL, J Office of Nuclear Reactor Regulation, Director 3pp 22449 308
- 8409010085 FOIA request for ORNL draft or final rept on severe accident precursors at US nuclear plants during 1980 & 1981 HIATT-8 L Dhia Citizens for Responsible Energy 83/12/10 FFL10N-J M Division of Rules and Records 1p 22477 234
- B403010092 Final response to FDIA request for comparative evaluation of nuclear facilities compliance w/NUREG-0578 & NUREG-0737 requirements Forwards App A documents App B document on entirely withhold (ref FDIA Exemption 5) FELTON.J M Division of Rules and Records B4/02/09 WEISB.E R Union of Concerned Scientists App 22448 190
- --B403010097 R-1208671-001
 "TNI Action Plan," computerized list
 * NRC No Detailed Affiliation Given 84/02/09 146pp
- G403010074 Responds to FOIA request for ORNL rept. "Precursors to Potential Severe Core Damage Accidents 1980-1981 Status Rept. "Forwards draft rept FELION.J M Division of Rules and Records 84/01/03 HIATE.S Onio Citizens for Responsible Energy 1p 22477 235
- --B403010102 Draft "Precursors to Potential Severe Core Damage Accidents 1980-1981 Status Rept," Vols 1 % 2 main rept & App A & B COTIRELL, W B , MAGEN, E W , HARRIS, J D Oak Ridge National Laboratory FIN B-0435 DRM_/NBIC-217 83/07/31 Office of Nuclear Regulatory Research, Director 560pp 22477 236
- B403010100 Further response to FDIA request for eight categories of records re CL amends Forwards listed documents Documents also avaitable in FDR Bearch for addl documents subj to request in progress FELTON.J M Division of Rules and Records 83/12/22 BELL.N Nuclear Information to Resource Service 2pp 22445 087
- --8311230247 Discusses Public Law 97-415 which amended Atomic Energy Act of 1954 Section 189 to authorize NRC to issue & make immediately effective amends to OL w/NSMC W/o encl DENTON.HR Office of Nuclear Reactor Regulation, Director 83/10/31 SIMPSON,A Senate 1p 22445 090
- ---8403010104 Forwards fifth monthly FR notice re CL amends, per Public Law 97-415 W/o encl DENTON, H R Office of Nuclear Reactor Regulation, Director 83/07/30 9TAFFORD, R T Senate, Environment & Public Works 1p 22/45 089.
- --8403010108 Forwards FR notice of UL amends, per Public Law 97-415 W/b encl DENTUN,H R Office of Nuclear Reactor Regulation, Director 83/12/06 SIMPSON,A, Senate, Environment & Public Works Ip 22445 091

- 8403010111 FOIA request for documents by named individuals.including repts, analyses, studies, procedures & sys for measurement of RCS leakage
 MADDEN, T. J. Kaye, Scholer, Fierman, Hays & Handler 83/12/27
 NORRY, P. G. Office of Administration 2pp 22480 024
- 8403010113 Final response to FOIA request for five categories of info re mothballed nuclear const projects Forwards App A documents Documents also in PDR FELTON.J M Division of Rules and Records 84/02/10 BELL,N Nuclear Information & Resource Service 2pp 22479 182 24X Fiche 50-508.84/02/10.8403010113
- --8403010114 Partial statement of JB Martin before House Committee on Energy & Commerce re mothballing of facility MARTIN, J B NRC No Detailed Affiliation Given 83/09/14 9pp 22479 186 24X Fichs 50-508,84/02/10,8403010113
- B403010117 Partial response to FOIA request for documents by named NUSULULI/ Partial response to Fula request for occuments by individuals re repts, analyses, studies, procedures & sys for measurement of RCS leakage App 8 documents placed in PDR App A documents already available in PDR Search continuing FELION.J N Division of Rules and Records 84/01/25 MA Kaye, Scholer, Flerman, Hays & Handler 7pp 22480 026 Fische 50-000.88/01/25.8403010117 MADDEN, T J
- -- B011070522 Summarizes results of independent evaluations of primary sys leak rate & some considered extensions Extension of specific evaluations to all FMR facilities recommended Draft procedure re evaluations will be submitted by 800715 JORDAN. E L. Division of Reactor Operations Inspections 80/08/21 MOSFLEY. N C. Division of Reactor Operations Inspections 11pp 22480 266 24X Fiche 50-000.84/01/25.8403010117
- --B103250553 Forwards draft Procedures 617278, "Preparation for Independent Measurement of RCS Leak Rates for PMR" & 617288, "Independent Measurement of RCS Leak Rate for PMR" & 617288, "Independent Measurement of RCS Leak Rate for PMR" Manual Chapters 2514 & 2515 will be revised to add procedures SNIE/EK.J H Division of Resident & Regional Reactor Inspection 81701/22 GRIERS H Region i. Philadelphia. Office of the Director CREILLY.J P Region 2. Atlanta. Office of the Director KEPPLER.J G Region 3. Chicago. Office of the Director 2200 2500 2500 2500 22pp 22400 345
- ~~B103250630 Requests that encl Procedures 617278 & 61728B be issued For trial JUMUAN,E L. Director's Difice 81/01/22 BRYAN,S E Program Development Branch 17pp 22480 328
- --Bi07160213 Forwards description of RCSLK 7 for reactor coolant leakage Resolvent coreards description of MCSLK 7 for reactor coolant lead calculation, magnetic cards & quad memory module W/o magnetic cards & quad memory MCDURUFF, R W. Hechanical, Structural & Metallurgical Section 61/06/23 CHUNG, J. Test Program Section CRLENAK, J. Reactor Projects Section 1A FIELDER, R. Test Program Section 2pp 2248J 013
- --B107160215 "RCSLK 7 " NOTIONIST THE METER TO SERVICE OF STREET OF THE PROPERTY OF TH
- --8109180036 Requests two remote computer terminals to be used in developing programs for calculational support for complex inspi SNIEZEK, J H Division of Resident & Regional Reactor Inspection BI/09/08 TROUTMAN.C R Office of Management and Program Analysis 2pp 22481 345
- --B202120295 Submits progress rept on development of computerized insp techniques, including development of RCSLKB program for ECLIPBE computer Recommends purchase of addl TX Instruments 700 portable brominal for regional afts Program encl KIRKPATRICK. D. WOODRUFF, R W Reactor Engineering Branch B1/11/17 DROMERICK, A W Reactor Engineering Branch 14pp 22481 348
- ---B203120197 Forwards RCS 820121 leak rate calculation program for Hewlett Packard 41C (RCSLK 7) consisting of plant-specific data & sample calculations Data for remaining plants data & sample calculations value for remaining plants
 requested
 BAFR R L Division of Engineering & Quality Assurance (Pre
 830103) 82/02/16 MARTIN.TT Region L Office of Director
 CLSHINSKI.J A Region 2. Defice of Director NORELUIS, C E
 Region 3. Office of Director 16pp 22481 132
- --B309150400 Comments on 930629 schedule for initial independent measurements of RCS leak nates by Region V using RCSLKB Estimate of time required to gather verify & program plant-specific data acceptable WODRUFF, R W Engineering & Generic Communications Branch B3/07/12 MCKEE, P E Division of GA, Safeguards & Inspection Programs (Post B30103) Ip 22482 019

- --B309150401 Submits scope & schedule for independent measurements of RCS leak rates of operating plants in Region V Evaluations not expected to begin until Sept or Oct 1983 MORRILL.P Region 5. Office of Director 83/06/29 BISHOP.T Region 5. Office of Director 22481 242
- --B31i1504B1 Forwards results of review of RCS leak rate test procedures & calculational methods used in 1978 at two randomly selected BMR plants.per 830920 request Deficiencies discovered during trial use period corrected DLYQUNG.R C Director's Office, Office of Inspection and Enforcement 83/11/07 DIRCKS.W J Office of the Executive Director for Operations 22pp 224B2 020 24x
 Fiche 50-000.84/01/25.8403010117
- ---8403010127 "RCSLKB "
 KIRKPATRICK,D , WOODRUFF,R W NRC No Detailed Affiliation Given 81/10/30 32pp 22481 021
- --8403010129 Table of "Pressurizer Design Data " Related info encl * Alabama Power Co 84/01/25 44pp 22480 033 24X Ficho 50-000,84/01/25,8403010117
- --B403010131 "RCSLKB"

 KIRKPATRICK,D . WODDRUFF.R W NRC -- No Detailed Affiliation Given 81/11/03 13pp 224B1 044
- --8403010137 Rev 2 to Surveillance Test Procedure FNP-1-8TP-9 0, "RCS Leakage Test " Related info entl PODLE.D L Alabama Power Co 79/03/25 22pp 22480 079 24X Firhe 50-000,84/01/25,8403010117
- --8403010138 "RCSLKB " Related info encl KIRKPATRICK,D , WOODRUFF,R W NRC No Detailed Affiliation Given 81/11/17 76pp 22481 057
- --B403010141 Rev 2 to Instrument Maint Procedure FNP-1-IMP-202 8, "Voi Control Tank Level LT-112" Related info encl MCGRACKEN.K W Alabama Power Co 78/03/07 24pp 22480 101 24X Fiche 50-000, B4/01/25, 8403010117
- --8403010146 Rev 2 to Instrument Maint Procedure FNP-1-IMP-201 22, "Pressurizer Level Control.LC-459F" * Alabama Power Co 78/06/17 30pp 22480 125 24X Fithe 50-000.84/01/25,8403010117
- --B403010151 Responds to 820503 request for application of RCS leak rate program, RC5LK7, to Ben Onofre 2 RC5LK7, as written, applies to listed conditions Directions given to prepare Hewlett MODRRILL,P Region 5, Office of Director 17pp 22481 148 82/05/05
- 8403010152 Rev 1 to Instrument Maint Procedure FNP-1-IMP-202 9, "Vol Control Tank Level LT-115" THOMAS, J. Alabama Power Co. 78/08/02 22pp 22480 156 24X Fithe 50-000,04/01/25,8403010117
- --8403010156 Rev 2 to Instrument Maint Procedure FNP-1-IMP-201 28, "Procedure FNP-1-IMP-201 28, "Procedure FNP-1-IMP-201 28, THOMAS, J. Alabama Power Co. 76/08/02 24pp 22480 178 24 Fiche 50-000,84/01/25,8403010117
- --8403010139 Discusses independent measurement of RCS leak rates for PWRs New version of program RCSLXB developed for use w/portable computer Seminar tentatively scheduled for Feb JORDAN.E L Division of Engineering & Quality Assurance (Pro B30103) B2/10/05 HAYNES.R C Region 1. Office of Director O'REILLY.J P Region 2. Office of Director KEPPLER.J G Re 3. Office of Director 2pp 22481 165 Region
- --8403010161 "RCSLK8"
 KIRKPATRICK, D . WOODRUFF, R W NRC No Detailed Affiliation Given 82/11/26 12pp 22481 167
- ---B403010163 Rev 1 to Instrument Maint Procedure FNP-1-IMP-224 2, "Reactor Copiant Drain Tank Level, LT-1003 " Related info SHIPMAN, W B Alabama Power Co 80/01/25 62pp 22480 204 Fiche 50-000, 84/01/25, 8403010117 24 X
- --84030i0i64 Discusses status of implementation of RCSLKB.
 WODDRUFF,R NRC No Detailed Affiliation Given 82/12/01
 CUNNINGHAM,J NRC No Detailed Affiliation Given 3pp

- ---840301017B "RCSLK8 RCS Leakrate Determination for PWRs," Users Guide KIRKPATRICK,D., WOODRUFF,R W NRC - No Detailed Affiliation Given 83/02/15 43pp 22481 193
- --B403010181 Informs that new version of computer program, RCSLX8, incorporates improvements suggested by regional ofcs & by IE Evaluation of Deborne completed Oaborne 1 computer & Itoh printer ordered for each regional ofc
 JORDAN, E. Division of Emergency Preparadness & Engineering
 Response (Post 830103) 83/03/04 HAYNES, R. C. Region 1, Office of Director O'REILLY, J. P. Region 2, Office of Director KEPPLER, J. Q. Region 3, Office of Director 2pp 22481 234
- --B403010184 Discusses how IE could develop capability to periodically & independently calculate identified & unidentified reactor coolant leak rates in operating water reactors by using partable calculators Description of existing program encl KIRKFATRICK, D., WOODRUFF, R NRC No Detailed Affiliation Given BD/05/29 JORDAN, E NRC No Detailed Affiliation Given 11pp 22480 277
- --B403010185 Notifies of B30413-14 seminar in Bethesda, MD for regional ofcs on use of RCBLKG, improved computer program for determining leak rates of PWR cooling sys JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post B30103) 83/04/01 HAYNEB, R C Region 1, Office of Director O'REILLY, J P Region 2, Office of Director KEPPLER, J O Region 3, Office of Director 2pp 22481 236
- ---8403010191 Discusses how IE could develop capability to periodically & independently calculate identified & unidentified reactor coolant leak rates in operating water reactors using portable calculators Description of existing program encl KIRKPATRICK, D NRC No Detailed Application Given 80/06/03 JORDAN. E Division of Reactor Operations Inspections 21pp 28480 288
- --8403010193 Informs that portable computers obtained for regional ofcs for use in independent measurement of leak rates from PMR cooling sys Draft module & user guide (NUREG-0986) encl W/o encls
 UDROAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 TAYLOR, J M Division of GA, Gafeguards & Inspection Programs (Post 830103) 4pp 22481 238
- ---8403010196 Requests authorization to conduct leak rate test at selected C-E & Westinghouse facilities. Test needed to evaluate R Woodruff & D Kirkpatrick program to independently assess leak rates W/o enci
 JORDAN.E L Division of Reactor Operations Inspections 80/06/03
 BRUNNER E J Region I, Philadelphia, Reactor Operations Nuclear Support Branch. LEWIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch Ip. 22480 309
- --8403010201 IE Change Notice 81-05, revising listed manual chapters Related info encl * Director's Office, Office of Inspection and Enforcement 81/03/11 86pp 22481 252
- 8403010205 Forwards TANK program description & program cards Program calculates & plots vol of liquid in program for RCS leak rate Requests J Chung to be coauthor of program description WQQDRUFF,R Directon's Office, Office of Inspection and Enforcement, Bl/05/22 GHUNG, Region 1. Philadelphia, Office of the Director (81/03/01), 5pp 22481,340
- --8403010206 Requests Procedures 617278 & 617288 be issued & Manual Chapters 2014 & 2015 be revised to require that Procedure 617278 be performed during hot functional testing & Procedure 617288 be performed annually JORDAN, E. L. Division of Reactor Operations Inspections 80/08/22 DRYAN, S. E. NRC No Detailed Affiliation Given 1p. 22480 310
- --8403010214 Forwards Procedures 61727B & 61728B. Procedures outline steps necessary to perform independent measurements of leak rates from RCG for PWRS Each region requested to apply both procedures to one PWR per wk starting 80101B W/o encls JORDAN, E L Division of Reactor Operations Inspections 80/08/22 Region 1. Philadelphia, Office of the Director. 3pp 22480 311
- --8403010222 Forwards progress rept on development of computerized insp techniques.W/o Bncl. SNIEZEK.J NRC - No Detailed Affiliation Given 81/11/18 DEVOUNG,D NRC - No Detailed Affiliation Given 1p 22481 347

- -B403010233 Discusses RCB leak rate calculations per 820504 telcon Mods to RCSLK7 computer program permit leak rate calculations for pressures between 1,700 % 2,100 psig w/temp between 260 % & 270 ! Plant data encl MORRILL.P J Region 5, Office of Director 82/05/05 WOODRUFF.R W Reactor Engineering Branch 17pp 22481 362 24x Fichc 50-000,04/01/25,8403010117
- --B403010239 Agrees that use of computers as insp tool needs to be explained further per B30413-14 presentation Lists recommendations based on review of RCBLRG User Guide & practical demonstration of computer program KEARNEY, J NRC No Detailed Affiliation Given 83/04/15 MDDDRUFF,R NRC No Detailed Affiliation Given 2pp 22482 01?
- --8403010257 "DKHT5-Calculated Net Power & Integral of Net Power as Function of Time After Scram " WDDDRUFF,R W NRC - No Detailed Affiliation Given B0/12/05 4pp 22480 322
- --8403010284 "RC9LK8 "
 * NRC No Detailed Affiliation Given 81/07/08 7pp
 22481 009
- --8403010287 Forwards Hewlett Peckard program cards for RCS Leak Rate Program 7 (RCSLK7) W/o encl KIRKPATRICK, D Director's Office, Office of Inspection and Enforcement 81/07/21 MORRILL.P J Reactor Projects Section 1 1p 22481 019
- --B403010292 Requests Hewlett Packard 41C data cards for plant reactor coolant leakage calculations Program being developed to run reactor coolant leakage calculations on NRC ECLIPSE computer Data cards needed to set up data base BAER, R i Reactor Engineering Branch 81/09/02 HARTIN, T I Division of Engineering & Technical Inspection OIBSON, A F Division of Engineering & Technical Inspection URRELIUS, C E Division of Engineering & Technical Inspection Ip 22481,020
- 8403010119 FDIA request for studies performed by USGS & State of CA Div of Mines & Geology re facility seismic design CALSOYAS.C D Affiliation Not Assigned 82/f1/14 NRC - Nu Detailed Affiliation Given 4pp 22444 345 24X Fiche 50-312.83/11/14.8403010119
- 8403010123 Responds to FOIA request for studies performed by USGS & State of CA Div of Mines & Geology re facility seismic design Forwards App A documents Info also available in PDK FELTON, J M Division of Rules and Records 83/12/20 GALSDYAS, C D Affiliation Not Assigned 3pp 82444 349 24X Fiche 50-312,83/12/20,8403010123
- --7906140945 Summary of telcon to provide response to 790413 ltr requesting info re seismic analysis QARNER: D Operating Reactors Branch 4 (Pre 790625) 79/04/25 REID: R W Operating Reactors Branch 4 (Pre 790625) 1p 22444 352 24X Fiche 50-312.83/12/20.8403010123
- --7906140548 Discusses review of plant earthquake design criteria & requests info re seismic analysis
 DAVIG.J F California State of 79/04/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22444 353 P4X Fiche 50-312,83/12/20,8403010123
- --7910760122 Summarizes view of recent fault data, NRC requirements & Foct that FSAR considered only three faults active Recommends that new info on fault sys be assessed MINOQUE, R II Office of Standards Development, Director 79/10/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 22444 358 24% Fiche 50-312,83/12/20,8403010123
- --7911120317 Forwards RB Minogus 791001 memo to HR Denton & evaluation of Televancy to proceedings before ASLD LIBCANUTIO G Division of Operating Reactors 79/10/19 SCUTT, S Distribution Services Branch Spp 22444 355 24X Fiche 50-312,83/12/20,8403010123
- --7911120366 Forwards seismicity rept re Sacramento County.CR & portions of 680816 CA application & 730608 safety evaluation TISON.J C Commerce, Dept of. 681077/05 FRICE,H L Atomic Energy Commission, Directorate of Regulatory Operations. Ip 22445 085 24X Fiche 50-312,83/12/20,8403010129
- --7911120370 Requests addl info to complete review of initial site examination info data form
 DEYDUNG.R C Atomic Energy Commission, Directorate of Licensing 74/12/13 DAVIB.E K Bacramento Municipal Utility District Rpp 22445 ORB 24X Fichs 50-312.83/12/20,8403010123

- --79iiiP0403 Requests initial site examination info OlAMBUSSO, A Atomic Energy Commission, Directorate of Licensing 74/08/14 DAVIS,E K Sacramento Municipal Utility District Sp 22445 034
- --7911120413 Responds to 760115 ltr re DL Kelleker 751217 concern about nuclear plant in Orville.CA vicinity No plant glanned for area Discusses UBE re plant design DIRCKS.W J NRC No Detailed Affiliation Given 76/02/06 CRANSTON, A Senate 3pp 22445 041 24x Fiche 50-312,83/12/20,8403010123
- --B001290311 Forwards response to 791001 memo re geologic & seismic reassessment of facility No immediate hazard at site Licensee should undertake program to assemble & assess new info re geology & seismology of site region JACKSON.R E Geosciences Branch 79/12/21 GAMMILL, W P Assistant Director for Standard & Advanced Reactors 7pp 22448 050 24X Fiche 50-312,83/12/20.8403010123
- --8009250342 Recommends meeting w/util to review progress of seismic assossment study JACKSON.R E Opeosciences Branch 80/09/12 REID.R W Operating Reactors Branch 4 ip 22445 057 24% Fiche 50-312,83/12/20,8403010123
- ---B007250345 Discusses util response to NRC request for seismic reassessment Seven listed areas of info should be directed to util to avoid delay in reviewing rept ALFERMAN. I B Geosciences Branch B0/09/12 JACKBON, R E Geosciences Branch 3pp 22445 058 24X Fiche 50-312, 83/12/20, B403010123
- --B403010150 Forwards evaluation of Unit 2 initial site exam info data review Site safety members participating in review listed DENION. H R Atomic Energy Commission. Directorate of Licensing 74/10/10 DHYOUNOR R Atomic Energy Commission. Directorate of Licensing 4pp 22445 046 24X Fiche 50-312.83/12/20.8403010123
- B403010125 Further response to FOIA request for IE Rept 79-19, notice of proposed imposition of civil penalties, notice of violation & order to show cause Forwards documents listed on App A
 - App A FELTON, J.M. Division of Rules and Records 84/0!/11 HAMLIN, J.E Shaw, Pittman, Potts & Trombridge 2pp 22447 176 24X Fithe 50-498,84/01/1(,8403010125
- --B403010132 Requests info re public hearing on insp of facilities SCHMARTIA R Texas, State of B0/06/03 SEYRITAK Region 4. Pallas, Office of the Director 1p 22447 179 24X Fiche 50-498,64/01/11.8403010125
- --8403010137 Transcript of 800817 public meeting in Bay City,TX Pp 1-382 Supporting documentation encl * Commissioners 80/08/19 382pp 22447 181 24X Ficht 30-499,84/01/11,8403010125.
- B40301016B Further response to FDIA request for all 1982 SECY papers to be available in PDR SECY-82-2,60,197B,197D,228,270A,334A,377A,389,394,455A,472 & 472A withheld (ref FOIA Exemption
 - 5) FELTON.J M Division of Rules and Records 83/12/21 WE185,E R Union of Concerned Scientists WE185,E R Harmon & Weiss App 22449 313
- 8403010192 FGIA request for records relevant to or generated in connection ω/831021 "Rept on Review of Diesel Generator Bldg at Midland"

 GARDE.R P Generator Accountability Project 83/11/26 Office of Administration 2pp 22445 092 24X Fiche 50-329.83/11/26.8403010192
- B40301019B Responds to FOIA request for records relevant to or generated in connection w/B31021 "Rept on Review of Diesel Generator Bldg at Midland " Forwards App B documents App A documents available in POR FELION.J M Division of Rules and Records 83/12/14 GARDE,B P Government Accountability Project App 22445 092 24% Fiche 50-329.83/12/14.8403010198
- --8310310471 Forwards task group rept. "Rept on Review of Diesel Generator Ding at Midland," Oct 1983 Large addl settlements not anticipated More accurate program to monitor cracks
 - -tural & Geotechnical Engineering Branch 83/10/21 Assistant Director for Comp & Structures Engineering 2pp. 22445 152 24X Fiche 50-329,83/12/14,
 - eview of Diesel Generator Bldg at Midland " l & Geotechnical Engineering Dranch 83/10/31 24% Fiche 30-327,83/12/14,8403010178

- --8312010004 Forwards corrected Pages 9,17,20 & 4 to App 11 to rept on review of diesel generator bldg
 KWO,P Structural & Geotechnical Engineering Granch 83/11/14
 KNIOHT.JP Assistant Director for Comp & Structures Engineering
 (Post 830201) 5pp 22445-256 24X Fiche 50-327,83/12/14,
 8403010198
- --8312050628 Requests rept re adequacy of diesel generator bldg on expedited basis as input to Congress re Landsman concerns EISENHUT,D & Division of Licensing 83/11/18 VOLLMER,R Division of Engineering ip 22445 263 24X Fiche 50-329,83/12/14,8403010198
- --B312070022 Forwards Structural & Geotechnical Engineering Branch assessment of "Rept of Review of Diesel Generator Bldg at Midland," dtd B31021 per E Adensam & W Paton requests Meeting & possible reopening of hearing recommended LEAR, 0 Structural & Geotechnical Engineering Branch 83/11/22 VOLLMER.R H Division of Engineering 2pp 22445 268 24X Fiche 50-329, B3/12/14, B403010198
- --8312070278 Discusses recommendation for suppl to Board Notifications 63-165 & 63-153 re diesel generator bldg Comments & recommendations of J Kane & F Rinaldi on task group rept & reopening of hearing provided HODD, D S Licensing Branch 4 ISSUANCES OM 83/11/22 EISENHUT, D G Division of Licensing 4pp 22445 264 24X Fiche 50-327,83/12/14,8403010198
- --8312080134 Recommends PT Kuo 831114 memo containing four corrected pages to rept re structural adequacy of diesel generator bldg be forwarded to Board as supplemental notification to BN 83-165
 HDOD, D Licensing Branch 4. ISSUANCES OL 83/11/17 EISENHUT, D Assistant Director for Licensing Ip 22445 261 24X
 Fiche 50-329, 83/12/14.8403010178
- --8403010204 Advises that info re plan to address Landsman concerns should be issued as Board Notification 83-109
 EISENHUT.D G Division of Licensing 83/07/27 NOVAK,T
 Assistant Director for Licensing 1p 22445 098 24X
 Ficke 50-329,83/12/14,8403010198
- --B403010211 Advises that attached correspondence re new schedule for review of Landsman concerns should be issued as Board Notification 83-142 W/o encl EISENHUT.D.Q Division of Licensing 83/07/20 NOVAK.T Assistant Director for Licensing Ip 22445 099 24X Fiche 50-329.83/12/14.8403010198
- --8403010217 Draft rept, "Review of Diesel Generator Bidg at Midland Plant" MILLER C A , COSTANTINO C J Brookhaven National Laboratory 83/07/23 25pp 22445 100 24X Fiche 50-329.83/12/14,8403010198
- --8403010223 Advises that encl JP Knight 830923 memo to RH Vollmer should be issued as Board Notification 83-183 M/o encl EIBENHUT.D © Division of Licensing 83/10/05 NOVAK,T Assistant Director for Licensing 1p 22445 125 24X Fiche 50-329,83/12/14,8403010178.
- --B403010227 Forwards "Ravisw of Diesel Generator Bldg at Midland Plant " REICH.M Brookhaven National Laboratory B3/10/17 KUO.P T Structural & Geotechnical Engineering Branch lp 22445 126 24X Fiche 50-327,83/12/14.6403010178
- --8403010231 "Review of Diesel Generator Bldg at Midland Flant" MILLER C A , COBTANTING C J Brookhaven National Laboratory, 83/10/17 25pp. 22445 127 24X Fiche 50-329, 83/12/14, 8403010198
- ---8403010245 Requests that encl rept on review of diesal generator bldg & util analysis requested during review be issued as Board Notification 83-165
 EISENHUT, D. G. Division of Licensing 83/10/26 NOVAK, T. Assistant Director for Licensing 6pp 22445-250 24X
 Fiche 50-329,83/12/14.8403010198
- ---8403010273 Advises that supplemental info provided in PT Kuo 831114 memo to JP Knight will be transmitted to Midland Board as suppl to Board Notification 83-165. Issue will be incorporated as Board Notification 83-165A W/o encl EISCNNUT.D C. Division of Licensing 83/11/16 NOVAK, T Assistant Director for Licensing ip 22445.262 24X Fiche 50-329,83/12/14,8403010198
- --B4030102B2 Forwards guidance for use in deciding whether to recommend that hearing be reopened Hearing should be reopened based on listed reasons

 VOLLMER.R H Division of Engineering 83/11/25 EIBENHUT, D. G. Division of Licensing. 3pp. 22445, 270. 24X Fiche 50-329, 83/12/14,8403010198

- ---8403010285 Advises that Vollmer recommended reopening Midland hearing on diesel generator bldg structural adequacy issue, based on task group rept Vollmer memo encl M/o encl ADENSAM,E NRC No Detailed Affiliation Given 83/11/25 EISENHUT.D NRC No Detailed Affiliation Given 1p 22445 273 24X Fiche 50-327,83/12/14.8403010178
- B403010262 Further response to FOIA request for documents re Sandia Contract A-1123 & bibliography used by R Dernero Forwards App A documents FELTON.J M Division of Rules and Records FIN A-1123 83/12/20 RUTLEDGE.P Carolina Environmental Study Group 2pp 22444 067 24X Fiche 50-000.83/12/20.8403010262
- --8301280380 Responds to 821108 itr & newspaper article, clarifying distorted & incomplete picture of nuclear accident probabilities & consequences & modeling uncertainties presented in article DIRCKS,W J Office of the Executive Director for Operations 82/12/27 BOGOS,L House of Rep 4pp 22444 078 24% Fiche 50-000,83/12/20.8403010262
- --840301026B Forwards preliminary draft documents re Sandia Labs work in area of siting criteria development Repts represent work being done in expanding use of probabilistic analysis in regulatory work W/o encis
 DIRCKS.W J Office of the Executive Director for Operations
 B2/04/26 GILINGKY Commissioners Spp 22444 071 24X
 Fiche 50-000,83/12/20,8403010262
- --8403010274 Discusses research rept.NUREO/CR-2239 (Sand81-1949).
 "Technical Quidance for Siting Criteria Development "
 Forwards NUREO/CR-2723 & NUREO/CR-2899 for ref use only W/o encls
 DIRCKB, W J Office of the Executive Director for Operations
 B2/11/22 PALLADINO, GILINSKY, AHEARNE Commissioners Rpp
 22444 076 24X Fiche 50-000,83/12/20.8403010262
- 8403010278 FDIA request for SECY-83-288 to be placed in PDR FEDRO.J NV8 Corp CD-16-83-535 83/11/16 Division of Rules and Records 1p 22449 137
- 8403010279 Responds to FOIA request for SECY-B3-288 to be placed in PDR Forwards SECY-B3-288. Document also available in PDR FELTON, J M Division of Rules and Records B3/12/16 PEDRO, J NUB Corp ip 22/449 138
- --8403010283 Comments on SECY-83-288 re proposed rule on pressurized thermal shock Proposed rule should address CP applicants in addition to OL applicants & operating reactors Schedule for preparation of plant-specific safety analyses acceptable ZERBE, J E Office of Policy Evaluations 83/08/01 PALLADING, GILINSKY, ROBERTS Commissioners App 22449 222
- 8403010383 Responds to FOIA request for map detailing background radiation levels, prepared as result of aerial survey conducted out of Pease Air Force Base No records subj to request located FELTON, J M Division of Rules and Records 83/12/20 DOUGHTY, J Seacoast Anti-Pollution League ip 22446 346
- 8403010385 FOIA request for add1 search of files for map detailing background radiation levels, prepared as result of aerial survey conducted out of Pease Air Force Base DOUGHTY, J Beacoast Anti-Pollution League 83/11/23 FELTON, J M Division of Rules and Records 1p 22446 347
- B403010407 Responds to FDIA request for info on Tatum salt dome tests performed in State of MS in late 1960s or early 1970s No documents available pertaining to request Info may be obtained from State of MS Dept of Natural Resources FELTON, J M Division of Rules and Records 83/12/16 LEGGETT, L H Affiliation Not Assigned 1p 22443 280
- B403010409 FOIA request for lists of all source disposal companies licensed to handle radwaste disposal GEBELE, H W Foxboro Corp 83/11/18 Office of Administration ip 22446 331
- B403010410 Responds to FOIA request for list of all source disposal companies licensed to handle radwaste disposal Forwards two lists
 FELTON, J M Division of Rules and Records B3/12/15 GEBELE, H W Foxboro Corp ip. 22446
- --8403010412 "Waste Disposal Licensess" * NRC - No Detailed Affiliation Given. 82/02/05 6pp 22446:333
- --B403010414 "Active Byproduct Licenses." * NRC - No Detailed Affiliation Given B3/12/02 7pp 22446,337

- B403010469 FOIA request for info on Tatum salt dome tests performed in State of MS in late 1960s or early 1970s LEGOETIL H Affiliation Not Assigned B3/12/02 NRC - No Detailed Affiliation Given 1p 22443 281
- 8403010474 FDIA request for info re sign posted near toilet at Argonatte reactor at Univ of Florida GROSBMAN.K Island Closeup News Service, Sag Harbor, NY 84/01/31 NRC - No Detailed Affiliation Given 1p 22443 278
- 8403010480 Responds to FOIA request for info re sign posted near toilet at Argonatte reactor at Univ of Florida FELTON, J M Division of Rules and Records 84/02/27 GROSSMAN.K Island Closeup News Service, Sag Harbor, NY 1p 22443 279
- B403010488 Appeals denial of FDIA request for T Novak notes generated by or during visit to Glen Ellyn. IL to discuss Dfc of Special Cases findings re facilities from Sept 1982 to Dec 1983 GARDE, B P Government Accountability Project 84/01/17 FELTON, J M Division of Rules and Records 1p 22443 274 24X Fiche 50-329, B4/01/17, B403010488
- 8403010497 Responds to appeal re denial of FOIA request for records in possession of T Novak on visit to Olen Ellyn. IL to discuss findings of Office of Special Cases re facilities NRC has no records subj to request DIRCKS.W J Office of the Executive Director for Operations 84/02/28 GARDE.B P Government Accountability Project 1p 22443 273 248 Fiche 50-329.84/02/28.8403010497
- 840302000B FOIA request for radiation source or device registration certificates issued by NRC to listed organizations HAMMITI.H A FOI Services 3451 84/01/26 FELTON.J M Division of Rulos and Records 3pp 22474 001
- 8403020011 Responds to FOIA request for radiation source or device registration certificates issued by NRC to organizations listed in request ltm Forwards requested documents FELTON.J M Division of Rules and Records 84/02/09 HAMMITT.H A FOI Services Ip 22494 004
- --8403020016 Registry of radioactive sealed sources & devices, safety evaluation of X-ray fluorescence cell mfg by AMP, Inc using New Ingland Nuclear Model NER-476C * NRC No Detailed Affiliation Given NR-140-D-101-5 83/07/08 5pp 22494 005
- --84030P0018 Registry of radinactive sealed sources & devices, safety evaluation of detector cell mfg by Antek Instruments, Inc using US Radium Model LAB-508-1 & New England Nuclear Model NCR-002 KLINGER, J 0 NRC No Detailed Affiliation Given TY-145-D-103-8 B2/12/17 3pp 22494 010
- --B403020023 Registry of radioactive sealed sources & devices, safety evaluation of luminous front past sight containing 3M Model EEX Army Fart B486890 for Pr-147 & Part 12002966 for tritium, distributed by US Army Armament Readiness Command # NRC No Detailed Affiliation Given NR-153-D-101-9 83/03/07 2pp 22494 013
- --8403020027 Registry of radioactive sealed sources & devices, safety evaluation of radioluminous lamp containing 3 Ci tritium. distributed by US Army Armament Matl Readiness Command P NRC No Detailed Affiliation Given NR-155-8-101-9 83/03/08 App 22494 015
- --B403020034 Registry of radioactive spaled sources & devices, safety evaluation of radioluminous lamp containing 10 Ci tritium, distributed by US Army Armament Matl Readiness Command * NRC No Detailed Affiliation Given NR-155-2-102-8 83/03/08 3pp #2494.019
- --8403020038 Registry of radioactive scaled source* & devices, safety evaluation of radioluminous lamp containing B C1 tritium, distributed by US Army Armament Matl Readiness Command

 * NRC No Detailed Affiliation Given NR-155-S-103-S 83/03/08 Jpp 22474 022
- --B403020057 Registry of radioactive sealed sources & devices, safety evaluation of radioluminous lamp containing tritium, distributed by US Army Armament Matl Readiness Command.

 * NRC No Detailed Affiliation Given NR-155-S-104-S 83/03/08 7pp. 22474 025
- ---B403020060 Registry of radioactive sealed sources & devices, safety evaluation of radioluminous lamp containing 6 Ci tritium, distributed by US Army Armament Matl Readiness Command * NRC No Detailed Affiliation Given NR-158-8-105-8 83/03/08 3pp 22494 034

- --B403020067 Registry of radioactive sealed sources % devices, safety evaluation of radioluminous lamp containing 2 2 Ci tritium, distributed by US Army Armament Matl Readiness Command

 * NRC No Detailed Affiliation Given NR-153-S-106-S 83/03/08
 3pp 22494 0.37
- --8403020070 Registry of radioactive sealed sources & devices, safety evaluation of radioluminous lamp containing & Ci tritium; distributed by US Army Armament Mati Readiness Command

 * NRC No Detailed Affiliation Given NR-155-8-107-8 83/03/08
- ---8403020074 Registry of radioactive sealed sources & devices safety evaluation of radioluminous lamp containing 4 Ci tritium, distributed by US Army Armament Matl Readiness Command * NRIC No Detailed Affiliation Given NR-155-5-108-S 63/03/01 Jpp 22494 043
- --B4030200B0 Registry of radioactive sealed sources & devices, safety evaluation of radioluminous lamp containing tritium distributed by US Army Armament Matl Readiness Command

 * NRC No Detailed Affiliation Given NR-155-S-109-S B3/03/0B
 7pp 22474 046
- --B4030200B2 Registry of radioactive smaled sources % devices, safety evaluation of mass spectrometer containing 15 mCi Ni-63 in Phemto-Chem MMS-160, distributed by PCP, Inc * NRC No Detailed Affiliation Given FL528Di02U 79/08/29 2pp 22494 222
- --84030200B7 Registry of radioactive scaled sources & devices, safety evaluation of radioluminous lamp containing 1 C₃ tritium, distributed by US Army Armament Matl Readiness Command * NRC No Detailed Affiliation Given NR-155-8-110-8 83/03/08 3pp 22474 053
- --8403020091 Registry of radioactive sealed sources & devices, safety evaluation of radioluminous lamp containing 1 2 Ci tritium, distributed by US Army Armament Matl Readiness Command * NRC No Detailed Affiliation Given NR-155-5-111-9 82/03/08 3pp 22494 056
- --8403020095 Registry of radioactive sealed sources & devices, safety evaluation of electron capture detector cell assembly containing 15 mC; NL-63 in New England Nuclear NER-002 & Nuclear Radiation Development N1001 sealed source BRDWn, J M. SINGER.B. NRC No Detaile6 Affiliation Given NRS36D0198 82/04/30 6pp 82494 234
- --8403020101 Registry of radioactive sealed sources & devices, safety evaluation of interstitial implant source & storage vessel w/15 mCi Ir-192 in Model R/i (seeds) & P-1,P-2,P-3 & P-4 containers.mfg by RAD/IRID, Inc BROWN, J M NRC No Detailed Affiliation Given NR-558-6-101-9 83/01/20 11pp 22494 240
- --8403070107 Registry of radioactive sealed sources & devices, sofety evaluation of gaseous tritium light sources (GTLS) in military fire control products mfg by Ruoff & Sons, Inc & distributed by UB Army Armament Readiness Command WRIGHT,E G., SINGER, B. NRC No. Detailed Affiliation Given NR-575-D-101-S 82/09/24 8pp 2E494 251
- --8403020110 Registry of radioactive sealed sources & devices, safety evaluation of radioluminous lamp containing 8 Ci tritium, distributed by US Army Armament Matl Readiness Command * NRC No Detailed Affiliation Given NR-155-8-112-8 83/03/08 3pp 22494 059.
- --8403020113 Registry of radioactive sealed sources & devices, safety evaluation of self-luminous compass containing 175 mCi tritium in Brandhurst Co light source Model RT/60-25/10 mfg by Suonto Dy & distributed by Sea Quest, Inc.
 BROWN, J M NRC No Detailed Affiliation Civen. NR-591-D-103-E 03/07/22 9pp 22494 259
- --B403020114 Registry of radioactive sealed sources & devices, safety evaluation of radioluminous lamp containing tritium, distributed by US Army Armament Matl Readiness Command.

 ***RRC** No Detailed Affiliation Given.** NR-155-5-113-8 B3/03/08
 366 22494 662
- --8403020116 Registry of radioactive smaled sources & devices, safety evaluation of electron capture detector cell containing 150 mCi tritium in Safety Light Corp foil source Model 508-3 mfg by Sentex Sensing Technology.

- -8403020119 Registry of radioactive sealed sources & devices, safety evaluation of radioluminous lamp containing tritium, distributed by US Army Armament Matl Readiness Command * NRC No Detailed Affiliation Given NR-155-8-114-8 83/03/08 3pp 2244 065
- --8403020120 Registry of radioactive scaled sources & devices, safety evaluation of gas chromatograph containing 20 mCi Ni-63 in US Radium LAB 784. New England Nuclear NER-004 & Amersham/ Searl NBC.mgp by Spectra-Physics WONG: 9 NRC No Detailed Affiliation Given CA615D1018 82/12/09 4pp 22494 275
- B403020124 Registry of radioactive sealed sources & devices, safety evaluation of ionization smoke detector containing 1 uCi Am-241 foil source in NRD Model A-001 or Amersham Model AM-1001H, mfg by Square D Co WRIGHT, E 0, SINGER, B NRC No Detailed Affiliation Given NR-616-D-101-E 82/09/07 Bpp 22494 279
- --8403020127 Registry of radioactive sealed sources & devices, safety evaluation of lensatic induction damped compass containing 120 mCi tritium in Stocker & Yale, Inc Model SY-183 SINGER, B NRC No Detailed Affiliation Given NR-622-D-102-E 83/01/18 Spp 22494 287
- --8403020132 Registry of radioactive sealed sources & devices, safety evaluation of calibr device containing 100 Ci Cs-137 in GRNL Drawing RD309 8, mfg & distributed by TEMCO PATRICK, D P. BURGESS J L. NRC No Detailed Affiliation Given ND631D101S 83/06/14 3pp 22474 295
- --8403020135 Registry of radioactive sealed sources & devices, safety evaluation of self-luminous source in watch models containing 200 mCi tritium in Mertz-Bentelli T4173-1 & T4175-1.mfg by Texas Instruments

 * NRC No Detailed Affiliation Given NR-632-S-102-E 82/10/08 ip 22474 298
- --8403020137 Registry of radioactive sealed sources & devices, safety evaluation of density gauge containing 230 mCi Cs-137 in Amersham Corp Model CDE 810 mfg by Tatabanyai Szenbanyak BROWN.J M NRC No Detailed Affiliation Given NR-633-D-102-8 83/08/15 Bpp 22494 299
- 8403020142 Registry of radioactive smaled sources & devices, safety evaluation of consolidation monitoring device containing 500 mCi Cs-137 in Gulf Nuclear. Inc Model CSV.mfg by Rexnord. Inc & distributed by DDT ERCHN.J M NRC No Detailed Affiliation Given NR-643-D-102-8 83/11/04 7pp 22494 307
- --B403020144 Registry of radioactive sealed sources & devices, safety evaluation of pipe wall thickness gauge containing 10 Ci Cs-137 in 3M Model 4D&L & Gulf Nuclear CSV, mfg by WB Wilson Mfg Co * NTC No Detailed Affiliation Given TX672D1065 79/07/31 3pp 22494 314
- --8403090149 Registry of radioactive sealed sources & devices, safety evaluation of sulfur-in-oil analyzer containing 550 mCi Am-241 in Amersham/Searle AMC 17. mfg by Yokugawa Electric Works & distributed by Yokugawa Corp of America * NRC No Detailed Affiliation Given GA678D1028 80/09/25 2pp 22494 317
- --8403020150 Registry of radioactive sealed sourses & devices, mafety evaluation of radioluminous lamp containing 8 Ci tritium, distributed by US Army Armament Matl Readiness Command * NRC No Detailed Affiliation Given NR-155-9-115-8 83/03/08 3pp 22494 068
- --8403020153 Registry of radipactive sealed sources & devices, safety evaluation of radioluminous lamp containing 8 Ci tritium, distributed by US Army Armament Matl Readiness Command * NRC No Detailed Affiliation Given NR-155-8-116-8 83/03/08 3pp 22494 071.
- --G403020166 Registry of radioactive sealed sources & devices, safety evaluation of radioation source assembly containing 500 mCi Cs-137 in Amersham CDC 192,809,810 & 811 mfg by Level Link, Inc.
 UDNG, 0 NRC No Detailed Affiliation Given CA423D1028 B3/04/15. 7pp 22494 165
- --8403020170 Registry of radioactive sealed sources & devices, safety evaluation of radioluminous lamp containing 2 2 Ci tritium, distributed by US Army Armament Matl Readiness Command.

 * NRC No Detailed Affiliation Oiven NR-155-8-117-8, 83/03/08 3pp 22494 074

- --8403020172 Registry of radioactive sealed sources & devices, safety evaluation of X-ray fluorescence spectrometor containing 10 mCi Fe-55 & 15 mCi Cd-109 in Isotope Products Labs Model XFD-5, distributed by Martin Marietta Corp BROWN.J M., SINGER, D. NRC No Detailed Affiliation Given NR-441-D-101-8 82/10/01 5pp 22494 172
- --B403020174 Registry of radioactive sealed sources & devices, safety evaluation of chemical agent detector.containing 250 uC; Am-241 in Amercham Corp foil source Model AMM1001, distributed by US Army Armament Matl Readiness Lammand BROWN.J M NRC No Detailed Affiliation Given NR-155-D-118-S G3/06/15 5pp 22494 077
- --B403020177 Registry of radioactive scaled sources & devices safety evaluation of UV emitting light source containing 1 C: tritium, distributed by Mb-Microtec BROWN.J M. NRC No Detailed Affiliation Oiven NR-446-S-101-S 83/09/22 App 22494 177
- --8403020179 Registry of radioactive scaled sources & devices safety evaluation of pipe monitor containing 200 mCi Cs-137 in New England Nuclear NER-370 (ANSI CS4434), distributed by Merrick-Scale Mfg

 * NRC No Detailed Affiliation Given NR452Di0IS 80/09/03 4pp 22494 IBI
- --8403020180 Registry of radioactive scaled sources & devices.safety evaluation of gamma ganging device containing 14 mCi Am-241 in Amersham Nodel AMC 24 or New England Nuclear Model NER-478C.mfg by Bedford Engineering Corp WRIGHT.E G . SINGER.D. NRC No Detailed Affiliation Given NR-182-D-101-8 82/11/10 8pp 22494 082
- ---8403020183 Registry of radioactive sealed sources & devices, safety evaluation of backscatter probe Model JLK, containing 30 mC: Am-241 in Amersham/Searle Corp AMC 66, distributed by Mettronix Co WONG, G NRC No Detailed Affiliation Given CA 457D1018 82/11/03 5pp 22494 185
- --8403020184 Amended registry of radioactive sealed sources & devices. safety evaluation of brachytherapy source & storage devices containing 30 mCi Ir-192 in Dest Model Gi-Ol seeds.mfg by Best Industries.Inc * NRC No Detailed Affiliation Given NR187DIOIS 82/12/09 10pp 22474 090
- --8403020187 Registry of radioactive scaled sources & devices, safety evaluation of bota source containing 500 mCi Pm-147 in New England Nuclear Model NER-8190 BROWN, J M , BABSIN, N NRC No Detailed Affiliation Given NR47681448 82/10/18 5pp 22494 190
- --B403020191 Registry of radioactive scaled sources & devices, safety evaluation of beta source containing 1,150 mCi Kr-85 in New England Nuclear Model NER-8180 BROWN, J M. BASSIN, N NRC NO Detailed Affiliation Given NR-474-8-149-8 82/10/18 5pp 22494 195
- --8403020193 Registry of radioactive sealed sources & devices, safety evaluation of brachytherapy sources containing 33 mCi Au-198, mfg by Bost Industries Inc SINGLR, B NRC - No Detailed Affiliation Given NR18791029 82/12/09 Bpp 22494 100
- ---84030P0194 Registry of radioactive sealed sources & devices, safety evaluation of beta source containing 2.200 mCi Kr-85 in New England Nuclear Model NER-584 WRIGHT, E G , SINGER, B NRC No Detailed Affiliation Given NR476S1468 82/03/18 6pp 22494 200
- ---B403020199 Registry of radioactive scaled sources & devices, safety evaluation of Am-241 low energy photon disc source containing 10 mci Am-241 in New England Nuclear Model NER-478H BROWN, J M , SINGER, B NRC No Detailed Affiliation Given NR47481478 82708/05 5pp 22494 206
- --8403020200 Registry of radioactive sealed sources & devices, safety evaluation of whole body counter calibr sources containing Co-60, Cs-137, I-125, I-131, Cr-91, Cd-107, Zn-65, Ba-133 & Mn-54, mfg by Bio-Nuclear Measurements, Inc BROWN, J M NRC Na Detailed Affiliation Olven NR-188-S-101-S 83/07/23 dep 22494 108
- --8403020201 Registry of radioactive scaled sources & devices.safety evaluation of low energy photon annular source containing 1.150 mCi Cd-109 in New England Nuclear Model NER-468 R & NER-468 A BROWN.J M NRC No Detailed Affiliation Given NR-476-S-148-S 82/12/27 4pp 22494-211

- 0403020208 Registry of radioactive sealed sources & devices safety evaluation of beta radiation source containing 1.150 mCi Kr-85 in New England Nuclear Model NER-8170 BRCWIN.J M NRC - No Detailed Affiliation Given NR-476-8-149-5 83/10/25 5pp 22474 215
- ---8403020210 Registry of radioactive sealod sources & devices.safety evaluation of gas aerosol detector containing 10 mCi Ni-63 in detector cell sources mfg by Ion Track Instruments or Chevron Research Co
 BROWN.J M NRC Na Detailed Affiliation Given NR-224-D-101-E 83/08/15 6pp 22494 114
- --8403020212 Registry of radioactive sealed sources & devices, safety evaluation of interstitial treatment of cancer involving 34 mCi Au in grains, distributed by Nuclear Sources & Svcs, Inc a NRC No Detailed Affiliation Given TX5085105U 78/02/28 3pp 22494 220
- --8403020215 Registry of radioactive sealed sources & devices, safety evaluation of logging tool calibr std containing 5 uci Th-232 or natural U in Nuclear Bources & Svcs Model 69-C or 65-M BASB, J T NRC No Detailed Affiliation Given TX50881060 83/11/03 3pp 22494 223
- --8403020219 Registry of radioactive sealed sources & devices, safety evaluation of desimeter irradiator containing 100 Ci Cs-13/ in DRNL Drawing RD309 B PATRICK.D P , BURGESS, J L NRC No Detailed Affiliation Given ND51881038 B3/06/14 6pp 22494 226
- --8403020224 Registry of radioactive sealed sources & devices, safety evaluation of computer sys containing smoke detector unit w/1 uCi Am-24i in Honeywell TC 100C smoke detector unit distributed by Control Data Corp
 WRIGHT.E G .NC No Detailed Affiliation Given NR-233-D-101-E G3/03/08 7pp 22494 120
- --8403020227 Registry of radinactive sealed sources & devices, safety evaluation of sample irradiator containing 100 mCi Sr-90 in Isotope Products Labs Model BF90 Ti distributed by Daybreak Nuclear & Medical Sys.Inc BROWN.J M NRC No Detailed Affiliation Given NR-250-D-101-E 83/07/05 5pp 22494 127
- --8403020232 Registry of radioactive sealed sources & devices, safety evaluation of electron capture cell containing \$0 mCi tritium in Bafety Light Corp Model 20203 or US Radium LAB-508-3, distributed by Delphi Instruments, Inc MONG. 0 C NRC No Detailed Affiliation Given CA254D1020 B3/06/28 Spp 22494 t32
- --8403020237 Registry of radioactive sealed cources & devices, safety evaluation of luminous marker switch containing 44 mCi tritium in MH il32/0/150 Model 1, distributed by Dowty Electronics Co & Baunders Roe Development * NRC No Detailed Affiliation Given NR-258-D-101-S B2/10/05 ip 22494 137
- --8403020240 Registry of radioactive sealed sources & devices, safety evaluation of X-ray fluorescence analyzer containing 100 mCs Fe-55 in New England Nuclear Model NER-461A, mfg by Texas Nuclear & distributed by Dow Chemical USA BELL, S NRC No Detailed Affiliation Given NR-260-D-101-9 83/10/18 Δρρ 22494 138
- --B403020243 Registry of radioactive scaled sources & devices, safety evaluation of gas chromatograph containing 15 mC: Ni-63, mfg by Victoreen Instrument Co & distributed by Fisher Scientific Co

 * Atomic Energy Commission NR294D101U 70/11/30 2pp 22/34 144
- ---8403020244 Registry of radioactive sealed sources & devices, safety evaluation for gas chromatography detector cell containing 15 mCi Ni-63 in Amersham/Searle foil.mfg by Victoreen Instrument Co & distributed by Fisher Beientific Co * Atomic Energy Commission NR294D102V 70/i1/26 2pp
- --BA03020251 Registry of radioactive sealed sources & devices, safety evaluation of cigarette density gauge containing 25 mCi Sr-90 in Amersham Buchler OmbH & Co kg Model 1411 mfg by Hauni-Werke & distributed by Hauni-Richmond.Inc BROWN.J M NRC No Detailed Affiliation Given NR-345-D-103-S G3/06/07 bpp 22494 148

- --8403020255 Registry of radioactive sealed sources & devices, safety evaluation of smoke detector containing I uCi Am-241 in Amerebam Model ARM-1001 mfg by Hochiki Corp & distributed by Hochiki-American Corp
 - by Hothiki-American Corp * NRC - No Detailed Affiliation Given NR-355-D-103-E 83/07/22 5pp 22494 153
- --8403020259 Registry of radioactive sealed sources & devices, safety evaluation of aerosol analyser containing 124 uCi Am-241 in Amersham Model AMMQ-2367, distributed by IITRI Research Inst

 * NRC No Detailed Affiliation Given NR-367-D-101-8 82/10/06
- --8403020264 Registry of radioactive sealed sources & devices, safety evaluation of underwater radiography containing 100 Gi Ir-192 in Oamma Industries.Inc PTL-1.distributed by
 - JG Gylvester Assoc, Inc

 * NRC No Detailed Affiliation Given NR-407-D-101-S 82/10/06
 10 2294 139.
- --8403020267 Registry of radioactive smaled sources & devices, safety evaluation of neutron generator tube containing 9 Ci tritium in Xeman I-31A-115781-000 or i-31A115782-000.mfg by Kaman Sciences Corp
- B403020014 Partial response to FOIA request for seven categories of documents re NRC regionalization program App A documents in PDR Review of remaining documents incomplete.
 FELTON.J M Division of Rules and Records B3/12/16 LOHENTHAL, J Nuclear Information & Resource Service 3pp. 22492-248 24X Fiche 50-000, B3/12/16, B403022014
- --B202220056 Summarizes decisions made on three important matters re regionalization Regionalization concept; critical skill base for regionalization of licensing & administrative efforts for regionalization are discussed DIRCKS.W J Office of the Esecutive Director for Operations B2/01/28 DENTON, HR Office of Nuclear Reactor Regulation, Director DEYQUNG, R C Director's Office, Office of Inspection and Enforcement DAVIS.J G Office of Nuclear Material Safety & Safeguards, Director Zpp 22472 251 24X Fiche 50-000, B3/12/16, B403020014
- --8210220012 Forwards plan for FYB3-FYB5 regionalization of NRR Comments should be received by 821012

 DENTON.H R Office of Nuclear Reactor Regulation, Director 82/09/30 Region 1. Office of Director ip 22492 313 24X

 Fiche 50-000,83/12/16,8403020014
- --B210220014 "FY83-FY85 Preliminary Regionalization Plan for NRR" * Office of Nuclear Reactor Regulation, Director 82/07/21 17pp 22472 314 24x Fiche 50-000,63/12/14.8403020014
- --8210220084 Forwards preliminary regionalization plan for FY83-FY85 Schematic presentation of scheduled milestones & activities provided in lieu of critical path presentation Revised plan & functional checklists to be submitted by 821015 DENTON.H R Office of Nuclear Reactor Regulation. Director 82/09/21 STELLO,V. Regional Operations & Generic Requirements 1p 22492 333 24X Fiche 50-000.83/12/16.8403020014
- --8211190102 Forwards final regionalization plan incorporating comments from regions.per 820903 request NRR will update plan periodically DENYON.H R Dffice of Nuclear Reactor Regulation. Director 82/11/01 STELLO,V Regional Operations & Generic Requirements. ip 22493-082 24% Fiche 50-000-83/12/16.8403020014
- -8211190103 "FY83-FY85 Preliminary Regionalization Plan for NRR "

 * Office of Nuclear Reactor Regulation, Director 82/10/19,
 200pp 22493 083 24X Fiche 50-000,83/12/16,8403020014
- --8212080692 Forwards FR notice amending 10CFR50 4.informing public that communications & applications should be sent to Region 4.Ltr to Congressional committees encl DENTON.HR Office of Nuclear Reactor Regulation, Director B2/12/01 FELION.JM Division of Rules and Records 2pp 22493 309 24X Fichs 50-000.83/12/16.8403020014.
- ---B212080493 "Regional Licensing Program Fort St Vrain Generating Station." 10CFR50 final rule Amend delegates responsibility for implementing licensing program to regional administrator Draft Congressional ltrs enci DIRCKS.W J. Office of the Executive Director for Operations 82/12/01 5pp 22493 311 24X Fiche, 50-000, 83/12/16, 8403020014

- --8212100130 Requests implementation of interim policy controlling requests for regional review & comment DIRCKS.W J Office of the Executive Director for Operations 82/11/29 DAVIS.J Office of Nuclear Material Safety & Safeguards, Director DENTON, H R Office of Nuclear Reactor Regulation, Director DEYDUNG, R Director's Office, Office of Inspection and Enforcement 4pp Fichs 50-000, 83/12/16, 8403020014
- --B212130052 Summary of 821116 meeting w/util onsite re delegation of licensing functions to Region 4 Uniqueness of facility & need to treat aspects differently from other LWRs discussed Draft delegation of authority memo anci for signature DENTON.H R Office of Nuclear Reactor Regulation. Director 82/11/29 DIRCKS,W J Office of the Executive Director for Operations 3pp 22493-286 24X Fiche 50-000,83/12/16, B403020014
- --B212160057 Forwards FR notice & amend to locfR50, reflecting delegation & assignment of certain licenting actions to Region 4 administrator DENTON.H R Office of Nuclear Reactor Regulation, Director B2/11/30 DIRCKS,W J Office of the Executive Director for Operations 7pp 22493 302 24X Fiche 50-000,83/12/16,8403020014
- ---B30ii404B4 Describes selected approach for transfer & maint of facility official docket files & supporting documentation to Region 4 Region 4 will assume routine document distribution on B2ii01
 FUNCHES, J L Planning & Program Analysis Staff B2/10/18
 E15FNUT. D & Division of Licensing 2pp 22472 353 24X
 Fiche 50-000, 83/12/16, 8403020014
- --B301140490 Advises that Region 4 assumes responsibility for receipt & distribution of all facility documentation, effective 821101 SCOTT.R S Document Management Branch 82/10/28 Document Management Branch 1p 22492 355 24% Fiche 50-000,83/12/16,8403020014
- --B30i140494 Advises that Region 4 assumes responsibility for receipt & dissemination of incoming licensee communications for Pacility, effective B21i01
 SCOTT.R S Document Management Branch B2/10/27 GAGLIARDO, J E Division of Resident, Reactor Project & Engineering Programs 1p 22492 356 24X Fiche 50-000, 83/12/16,8403020014
- ~-83042&0013 Forwards functional transfer checklist used to coordinate administrative aspects of transfers of NRC headquarters functions to regions. Subjs to prepare checklists for listed STELIO.V Regional Deprations & Generic Requirements. 83/04/19 DENTON.H Office of Nuclear Reactor Regulation. Director DEYOUNG.R Director's Office. Office of Inspection and Enforcement DAVIS.J Office of Nuclear Material Safety & Bafeguards.Director 3pp 22473 337 24X Fiche 50-000.83/12/16.84030220014
- --8403020021 Informs of 82:207 training & schedule review meeting re numpower reactor transfers Meeting agenda, transfer milestones & graphic schedule of transfer activities encl & SERNUT, D o Division of Licensing 82:11:05 BTAROSTECKI, R Division of Project & Resident Programs OLSHINSKI, T. Division of Engineering & Operational Programs OFESSARD, R Division of Project & Resident Programs SPESSARD, R Division of Project & Resident Programs SPESSARD, R Division of Project & Resident Programs SPESSARD, R Division of Project & Resident Programs SPP 22473 281 24X
- --8403020025 Identifies three major program area candidates for regionalization of regulatory functions enforcement program, emergency preparedness program & licensee performance appraisal program Comments in response to 811112 memo. DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 82/02/01 STELLO.V Regional Operations & Generic Requirements 7pp 22492 253 24X Fiche: 50-000.83/12/16, 8403020014
- --B403020028 Provides charter for regional coordination staff, incorporating some suggested changes Charter now in three parts according to rough time frame necessary for regions to assume various responsibilities W/o distribution list. DDN00HUE.D.J Dffice of Administration. 82/02/17 NRC No Detailed Affiliation oliven 7pp Fiche 50-000,83/12/16,8403020014.
- --B403020027 Discusses delegation & assignment to Region IV of certain licensing functions for facility.

 DIRCKB.M.J Office of the Executive Director for Operations DENTON.H R Office of Nuclear Reactor Regulation, Director.

 0128-82-5 82/11/29 COLLINS.J T Region 4. Office of Director 9pp 22493 289 24X Fiche 50-000.83/12/16.8403020014.

- --8403020032 Summary of 820901 initial planning meeting w/NRR, OELD, EDD, Region IV & Ofc of Administration re licensing transfer from NRR to Region IV Details encl Next meeting scheduled for 820915

 WESSHAN, R Assistant Director for Safety Assessment 82/09/03
 IPPOLITO, T A Assistant Director for Safety Assessment 27pp 22492 267 24X Fiche 50-000.83/12/16.8403020014
- --B403020035 Forwards final draft program guidance for FYB3-85, per NURG9-0685. "NRC Policy & Planning Guidance " Rev of current ofc operating plan, incorporating Commission Aug 1782 budget decisions & program guidance, expected by 821030 DIRCKB, W J Gffice of the Executive Director for Operations B2707/20 NRC No Detailed Affiliation Given 19pp 22492 274. RAX Fichs 30-000, B3/12/16, B403020014
- --8403020041 Informs of forthcoming FR publication of encl amend to Commission rules in 10CFR80 re implementation of facility regionalization program Amend issued as final rule effective on 821201 W/o encl
 DENTON.H R Defice of Nuclear Reactor Regulation, Director 83/12/16 UDALL, M K House of Rep. Interior & Insular Affairs ip 22493 316 24X Fiche 50-000,83/12/16.8403020014
- --B403020045 Informs of forthcoming FR publication of encl amend to Commission rules in IOCFR50 re implementation of facility regionalization program Amend issued as final rule effective on 821201 W/o encl
 DENTON, H R Office of Nuclear Reactor Regulation. Director 83/12/14 MOFFETT. T House of Rep. Government Operations ip 22473 317 24X Fiche 50-000,83/12/16.8403020014
- --8403020044 Informs of forthcoming FR publication of encl amend to Commission rules in 100FR50 re implementation of facility regionalization program Amend issued as final rule effective on 821201 W/o encl
 DENTON.H R Dffice of Nuclear Reactor Regulation, Director 83/12/16 07TINOER,R L House of Rep , Energy & Commerce 1p 22493 318 24X Fiche 50-000,83/12/16.8403020014
- --B40302004B Informs of forthcoming FR publication of encl amend to Commission rules in iOCFR50 re implementation of facility regionalization program Amend issued as final rule effective on 821201 W/o encl
 DENTON.H R Office of Nuclear Reactor Regulation, Director 83/12/16 SIMPSON.A Benate, Environment & Public Works ip 22493 319 24X Fiche 50-000.83/12/16.8403020014
- --BA03020049 Forwards list of major milestones re nonpower reactor regionalization actions for facilities in Regions I, IV & V Identification of individual responsibilities & appropriate action requested, per functional transfer checklists MINAGLIA, F. J. Assistant Director For Safety Assessment B2/10/19 BRUNNER, E. Region i. Office of Director BERNARD, H., HDEFLING, D. NRC No Detailed Affiliation Given 75pp 22492 357 24% Fiche 50-000, 83/12/16, 8403020014
- ---BA03020051 Informs that MK Udall Bubcommittee on Energy & Environ marked-up & reported 1984-85 NRC authorization bill to Interior Committee for future consideration NRC authorization bill H R 2510 & 830420 amends encl MAMMERER, C Office of Congressional AFFairs 83/04/20 PALLADINO, GILINSKY, AHEARNE Commissioners 11pp 22493, 326 24X Tiche 30-000, 83/12/14, 8403020014
- --8403020052 Provides program guidence for FY83-86 developed in support of NUREQ-0885. Issue 2. "NRC Policy & Planning Guidence 1983" Correct ofc operating plan should be revised to incorporate encl comments
 DIRCKB.W J Office of the Executive Director for Operations
 B3/05/20 NRC No Detailed Affiliation Given 20pp
 22493 340 24X Fiche 50-000.83/12/16.8403020014
- 8403020056 FOIA request for SECY-83-454 SEEGAL, J. L. Union of Concerned Scientists 83/12/22 FELTON, J M Division of Rules and Records 1p 22475 007
- 8403020062 Appeals danial of FOIA request for BECY-83-454. BEEOAL, J L Union of Concerned Scientists 84/01/12 FELTON, J M Division of Rules and Records ip 22495 008
- B403020068 Responds to appeal re denial of FOIA request for SECY-83-454 Forwards document Info partially withheld (ref FOIA Exemption 5) CHILK, 8.J Office of the Secretary of the Commission 84/02/15 BEEGAL, J. Union of Concerned Scientists 2pp 22495 009
- --B403020094 SECY-B3-454
 Approves release of substantive info in Chairmans logs, calendars & notes, per UCS request Info deleted & withheld F1709EALD, J. A. Office of the General Counsel 83/11/04 2pp

- B403020102 F01A request for records relevant to or generated in connection w/regulations re future of Ofc of Inspector & Auditor GARDE. B P Government Accountability Project 83/01/09 Office of Administration 2pp 22495 013
- B403020109 Responds to FOIA request for records relevant to or generated in connection w/regulations re future of Ofc of Inspector & Auditor NRC has no records subj to request FELTON.J M Division of Rules and Records B4/02/27 GARDE, IJ F Government Accountability Project 1p 22495 015
- 8403020392 FOIA request for Chilk 821019 memo to Direks re postaccident sampling sys (NUREG-0737, [tem 11 B 3) to be placed in PDR PEDRO, J NUS Corp CD-LIB-83-048 84/01/26 Division of Rules and Records ip 22491 285 24X Fiche 50-289,84/01/26,8403020392
- B403020395 Responds to FDIA request for Chilk B21019 memo to Dircks re SfCY-B2-384 cancerning status of TMI-1 NUREO-0737 items Forwards document Document also available in PDR FELION.J M Division of Rules and Records B4/02/15 PEDRO,J NUS Corp lp 22491 286 24% Fiche 50-289, 84/02/15, 8403020395
- 8403020400 FOIA request for NRC license issued to Atom Mechanical STEIN.9 S Advanced Medical Systems, Inc. 84/02/01 NRC - No Detailed Affiliation Given Ip 22491 279
- 8403020405 Responds to FDIA request for license issued to Atom Mechanical Forwards License 34-19854-01 dtd 820208 & Amend 1 dtd 820718 fELTON.J M Division of Rules and Records 84/02/15 STEIN.S 9 Advanced Medical Systems, Inc. 1p 22491 280
- --8403020408 Matl/Approduct License 34-19854-01. authorizing possession of Co-60 sealed sources for maint & repairs of Picker radiography & teletherapy devices GUINN, P. R. Division of Fuel Cycle & Material Safety 82/02/23 Ppp 22471 281
- --8403020412 Amend i to Mat1/Byproduct License 34-19854-01, amending license in entirety to authorize use of Co-60 sealed sources for maint & repairs of Picker radiography & taletheraphy devices, por 820312 ltr GUINN P R Division of Fuel Cycle & Material Safety 82/07/29 Epp 22491 283
- 8403020435 Further response to FOIA request for documents or constassessment team visit to plant in Aug & Sept 1983 Forwards
 listed documents
 FELTON.J M Division of Rules and Records 84/02/22 HIATT, 5 L
 Ohio Cittiens for Responsible Energy ip 22491 203 24X
 Fiche 50-440.84/02/22,8403020435
- --B403020441 Submits outline re const assessment team visit Related info enc! # NHC - No Detailed Affiliation Given 83/09/27 RDHRBACHER, R Director's Office, Office of Inspection and Enforcement 58pp 22471 204 P4X Fiche 50-440.84/02/22,8403020435
- 8403030017 FOIA request for SECY-78-569. UCID-19310. "Review of PASNY Sys Interaction Study" & records of NRC staff & consultant review of PASNY sys interaction study on Indian Point Unit 3 SHOLLY, S C Union of Concerned Scientists B3/10/20 FELTON, J M Division of Rules and Records ip 22525 097 24X Fiche 50-286, 83/10/20, 8403050017
- 8403050020 Responds to FOIA request for documents re PASNY submittal on sys interactions, repts evaluating submittal & list of repts/analyses from LLL evaluating PASNY sys interaction program Forwards App A documents FELTON.J M Division of Rules and Records B3/12/07 SHOLLY, S Union of Concerned Scientists & App 22325 098 24% Fithe 50-000, B3/12/07. 8403050020
- --7912050523 Requests comments on 791012 ACRS ltr re sys interaction Plans inhouse meeting for 791115 SCHMCNCER, A Operating Reactors Branch 1 (Pre 800428) 79/11/09 HANAUER, B Assistant Director for Plant Systems ZECH, G Division of Operating Reactors GAMMILL, W Assistant Director for Operating Reactor Projects (Pre 791030) ip 22527-146 24X Fiche 50-000, 03/12/07, 8403050020
- --8103040048 Discusses NHC requests for licensee sys interaction studies Forwards draft ltr to util documenting past advise & requesting meeting date when util can provide definition & realistic schedule for sys interaction program RUBENSTEIN, L & Assistant Director for Core & Containment Bystems 81/02/10 NOVAK, T M Assistant Director for Operating Reactors 5pp 22527 175 24X Fiche 50-000,83/12/07,8403050020.

- ~~8103050718 Responds to 800930 request re possible safety advantages of interim plant power deratings on consequences resulting from court of sys failure Deratings are not recommended Only basis for selecting level is "lower is safer"

 ROSS.D F Division of Systems Integration (pre 811005) 80/12/04

 DEMIGN.H R Office of Nuclear Reactor Regulation, Director 19pp 22527 160
- --8104220881 Summary of 810402 meeting w/util.Ebasco.LLL & BNL re status of bys interaction study ROBE.W J Operating Reactors Branch 1 81/04/09 Operating Reactors Branch 1 4pp 22526 192 24X Fiche 50-000.83/12/07.8403050020
- ~-8P01220170 Discusses program on adverse sys interactions in LWRs Sys interaction reviews to be completed at four selected plants & Indian Point Unit 3 Final guidance for interaction analyses to be based on experience w/reviews EKNST.M L Division of Safety Technology 82/01/05 TEDESCO.R L Assistant Director for Licensing 3pp 22526 242 24X Fichs 50-000,83/12/07,8403050020
- ~-BE08090277 Provides status rept on NRC evaluation of licensee sys interaction study Initial guidance delayed pending further cost/benefit analysis General program review planned for Fall 1982 GODDWIN.E F Technical Support Branch 82/07/30 FRALEY.R F ACRS ~ Advisory Committee on Reactor Safeguards 2pp 22526 265 24% Fiche 50-000.83/12/07.8403050020
- --8303080290 "Preliminary Investigation of Interconnected Sys Interactions for Safety Injection Sys of Indian Point 3" ALESSO, H P. Lawrence Livermore Laboratory 83/03/04 NRC - No Detailed Affiliation Given 33pp 22526 £39 24X Fiche 50-000, 83/12/07, 8403050020
- --8305230117 Notification of 830511 meeting w/BNL & LLL in Bethesda.MD to discuss details of contract scope for application of sys interactions analysis methods to Indian Point 3
 COFF MAN.F NRC No Detailed Affiliation Given 83/05/03
 THADANI.A Reliability & Risk Assessment Branch 23pp
 22526 268 24X Fiche 50-000.83/12/07.8403050020
- --B307290506 Notification of 830809 follow-up meeting w/util in Bethesda,MD to discuss sys interaction at facility POLK.F J Operating Reactors Branch i 83/07/22 VARGA,S A Operating Reactors Branch i 3pp 22525,248 24X Fiche 50-000,83/12/07,8403050020
- --8308040003 Forwards proposed text for ltr to PASNY requesting info for sys interaction methodology studies Timing for receipt of documents critical to plan for resolving Unresolved Bafety Issue A-17 Expedited transmittal requested THADANI.A C Reliability & Risk Assessment Branch 83/06/14 VARGA.S A Operating Reactors Branch 1 ip 22525 198 24% Fich: 50-000,83/12/07,8403050020
- --B309P20297 Requests B30805 memo be sent to Indian Point ABLB Memo will be recommended to be sent to all recipients of Board Notification B3-103 CONTAN, H. Reliability & Risk Assessment Branch B3/08/23 HORREJ E. Office of the Executive Legal Director 2pp 22525 284
- --8310170712 Identifies info required by LLL from util for contract re sys interaction study covering off normal operating procedures & check-off procedures & lists MORRIS.C Heliability & Risk Assessment Branch FIN A-0445 B3709/27 POLK.F J NRC - No Detailed Affiliation Given 28pp 22525 327 24X Fiche 50-000.B3/12/07.8403050020
- --8403050023 "Diagraph-Matrix Application on Indian Point 3 for Sys Interactions," statement of work Related info encl. a NRC - No Detailed Affiliation Given FIN A-0445 20-17-50-51-5 B3/12/07 35pp 22525 111 24X Fight 50-000,83/12/07,8403050020
- ---8403050024 Draft "Evaluation of Indian Point 3 Sys Interaction Analysis Program" + NRC - No Detailed Affiliation Given 82/02/20 7pp 22523 104 24X Fichs 30-000,83/12/07,8403050020
- ---8403050025 Informs that listed individuals will visit site during wk of 831017 Svcs requested & schedule provided Related info encl MORRIS.C Division of Systems Integration (post 811005) FIN A-0455 83/10/04 COFFMAN.F D Division of Systems Integration (post 811005) 21pp 22526 034 24X Fiche 50-000.83/12/07.

- --B403050027 Notification of 831121-23 sits visit to obtain info re sys interaction methodology study PCLK:P J Operating Reactors Branch 1 83/10/31 VARGA:9 A Operating Reactors Branch 1 2pp 22526 055 24X Fiche 50-000.83/12/07.8403050020
- --B403050028 Discusses licensed proposed review plans addressing ACRS recommendations re sys interaction study GOLLER.K R Assistant Director for Operating Reactor Projects (Pre 791030) 77/10/21 BENDER.M ACRS Advisory Committee on Reactor Safeguards 2pp 22525 146 24X Fiche 50-000.83/12/07.8403050020
- --BA03050029 NUREG/CR-2050
 SYSTEMS INTERACTION EVALUATION PROCEDURE FOR APPLICATION TO
 INDIAN POINT-3
 LIM.J J. ALESSO, H P., RICE. T R. Lawrence Livermore Laboratory
 FIN A-0405 UCRL-53024 81/04/30 NRC No Detailed
 Affiliation given 50pp 22526 0B9 24X Fiche 50-000,83/12/07,8803050020
- ---8403050031 SECY-78-569

 Recommends obtaining Commission comments &/or approval of proposed mu)ti-agency NOU re federal responses to radioactive contamination from specified foreign nuclear detonations
 GDSSICK.L V Office of the Executive Director for Operations 78/11/01 24pp 22525 174
- --B403050034 Discusses 791115 meeting re ACRS ltr on Indian Point 3 sys interactions SCHWENCER, A Operating Reactors Branch 1 (Pre B0042B) 79/12/05 EISENHUT, D 6 Division of Operating Reactors 2pp. 22527 147 24X Fiche B0-000, 83/12/07, 8403050020
- --B403050035 "Review of PASNY Sys Interaction Study."

 ALESBO. H P Lawrence Livermore Laboratory KELLY. J E Science
 Applications, Inc Bi/06/15 9pp 22526 196 24X
 Fiche 50-000, B3/12/07. 8403050020
- ---8403050037 Discusses effect of control sys failures on plant safety STOL7.J.F. Systems Interaction Branch 80/12/18 Systems Interaction Branch ip 22827 158 24X Fiche 50-000,83/12/07. 8403050020
- ---8403050038 UCID-17130 "Review of PASNY Bys Interaction Study " ALESSO. H P Lawrence Livermore Laboratory 82/03/01 7pp 22526 236 24X Fiche 30-000,83/12/07,8403050020
- --8403050042 Requests update to memos discussing probability that next major accident will occur within prescribed intervals Preliminary response requested by 821115 AHEARNE, J Commissioners 82/11/02 Office of Policy Evaluations 1p 22526 267
- B403050055 FOIA request for computer printouts of all NRC byproduct math licensees in Regions I & III & set of gummed peel-off mailing labels for each printout MCDDNALD, D O Nuclear Pharmacy, Inc 84/01/19 FELTON, J M Division of Rules and Records 1p 22528 208
- 8403050057 Responds to FOIA request for computer printouts of all NRC byproduct matl licensees in Regions I & III & set of gummed peel-off mailing labels for each printout Forwards four printouts & two sets of gummed labels H/o encl FELTON, J M Division of Rules and Records 84/02/15 MCDONALD, D G Nuclear Pharmacy, Inc. 1p 22528 209
- 8403050058 FOIA request for records re weekly colloquia on PRA activities & safeguerds goal development SHOLLY,9.C Union of Concerned Scientists 83/12/14 FELTON, J M Division of Rules and Records 2pp 22528 193
- B403050060 Partial response to FOIA request for records re weekly colloquia on PRA activities & development of safeguards goal App A documents available in PRA FELTON, J H Division of Rules and Records 84/02/22 SHOLLY, 8 C Union of Concerned Scientists. Spp 22528 195
- 8403050061 FOIA request for extant drafts of sections or portions of BER for plant & documents showing dissenting opinions of staff reviewers EDDLEMAN.W Eddleman, W 84/01/12 FELTON, J. Division of Rules and Records. 1p 22496 346 24X Fiche 50-400,84/01/12,8403050061
- 8403050064 Partial response to FOIA request for extent drafts of sections of SER for plant & documents showing dissenting opinions of staff reviewers Forwards App A documents Documents also in PDR Search for addit documents in progress FELTON, J M Division of Rules and Records 84/02/07 EDDLEMAN, W Eddleman, W 4pp. 22496, 347 24X Fiche 50-400, 84/02/07, 8403050064

- --8205120076 Forwards request for addl info re organic metls & spent Fuel pool cleanup sus FBAR sections
 BENARDYA, V Chemical Engineering Branch 82/04/27 MIRAGLIA.F.
 Licensing Branch 3 4pp 22496 351 24X Fiche 50-400, 84/02/07, 8403050064
- --B205270420 Forwards request for add1 info re fire protection program needed to complete review Info needed by 821102
 BENAROYA.V Chemical Engineering Branch 82/05/17 MIRAGLIA.F
 Licensing Branch 3 7pp 22497 015 24% Fiche 50-400,84/02/07,8403050044
- --B207140072 Submits branch input for draft SER Input assumes that clant meets design objective of App I

 AMMILL,W P Meteorology & Effluent Treatment Branch 82.

 MIRAQLIA,F J Licensing Branch 3 57pp 22501 007 24X

 Fichm 50-400,84/02/07,8403050064
- --821109000B Forwards draft SER input re SRP Sections 2 5 1 on basic geology & saismic info,2 5 2 on saismology & 2 5 2 3 on SSE No capable faults exist at or around site SSE & OBE KNIGHT, J P Assistant Director for Comp & Structures Engineering (Pre 830201) 82/10/20 NOVAK, T M Assistant Director for Operating Reactors 21pp 22496,355 24X Fiche 50-400,84/02/07,8403050064
- --8211090035 Submits Core Performence Branch input to draft SER Confirmatory & open issues listed RUBENSTEIN.L S Assistant Director for Core & Flant Systems B2/10/21 NOVAK.T M Assistant Director for Licensing 2p 22497 022 24X Fichs 50-400,84/02/07,8403030064
- --B2i1il0461 Advises that applicant has not responded to request for info re SER items concerning oil collection sys for reactor coolant pump, alternate shutdown capability, fire protection for safe shutdown & NUREG-OBOO BENAROYA, V Chemical Engineering Branch B2/10/28 KNIGHTON, O Licensing Branch 3 1p 22497, OBB 24X Fiche 50-400, B4/02/07, B403030064.
- --B211160112 Forwards draft BER input re FBAR Sections 2 5 4 2 5 6
 Request for addl info also encl Site visit necessary before
 end of yr to observe as-built conditions & implementation of
 dam safety monitoring plans.
 LEAR.G.E. Hydrologic & Geotschnical Engineering Branch B2/11/4
 KERRIOAN.J.D. Licensing Branch 3. 40pp 22497 260. 24X
 Fiche 30-400.84/02/07.8403050064 82/11/09
- --8211170249 Forwards draft SER input based on Auxiliary Sys Branch review of FBAR.Unresplyed items listed RUBENBTEIN.L 8 Assistant Director for Core & Plant Systems, 82/11/04 NOVAK,T M Assistant Director for Licensing 145pp 22497 089 24X Fiche 50~400.84/02/07.8403050064
- --B211300017 Forwards Chemical Engineering Branch draft SER input re listed sections of FBAR through Amend 2 & B20802 ltm, based on BRF (NUREG-0800) & NUREG-0737. Item II B 3 Addl info needed to complete review of post-accident sampling sys, JOHNSTON, W V Assistant Director for Matls & Qual, Engineering (Pre 830201) 82/11/17 NOVAK.T. Assistant Director For Licensing 21pp 22497 300 24X Fichs 50-400,84/02/07, 8403050064.
- --B212160163 Forwards Structural Engineering Branch summary of FBAR review & draft BER input,
 KNIGHT, J.P. Assistant Director for Comp. & Structures Engineering (Pre 830201) 82/12/06, NOVAK, T.M. Assistant Director for Licensing 16pp 22497 346 24X Fiche: 50-400, 84/02/07, 8403050064
- --B212160220 Forwards revised Hydrologic Engineering Section SER input Revised input superscedes previous submittal transmitted by B21014 memo. LEAR.9.E. Hydrologic & Geotechnical Engineering Branch. 82/12/03 KNIOHTON.9. Licensing Branch 3 25pp 22497 321 24X Fiche: 50-400, 84/02/07, 8403030064
- --B212300403 Forwards draft revised BER input to BRP Bections 2 5.1, 2,5 2 & 2.5.3 re geology & seismology. Revision includes applicant commitment to install & operate free-field accelerometers accelerometers (NIGHT), P. Assistant Director for Comp. & Structures Engineering (Pre 830201), 82/12/21 LAINAS.G.C Assistant Director for Licensing. 24pp. 22497.362 24X Fiche 50-400,84/02/07. 8403050064.
- --8301060211 Forwards draft BER input, including one open item re possible shipments of texic matls past plant site MULLER, D. R. Assistant Director for Environmental Technology (Pre 830201). 82/12/22. NOVAK, T.M. Assistant Director for Licensing 9pp. 22498, 024. 24X Fiche: 50-400, 84/02/07, 8403050064.

- --8301140474 Forwards Equipment Qualification Branch input for SER Suppl 5 to environ qualification of mechanical & electrical equipment
 - equipment JOHNSTON.W V Assistant Director for Matls & Qual Engineering (Pre 830201) 83/01/10 NOVAK.T M Assistant Director for Licensing 3pp 22498 033 24% Fiche 50-400,84/02/07,8403050064 Licensino 3pp
- ~-8301260036 Forwards Meteorology & Effluent Treatment Branch input to draft SER Assumption that draft meets 100FR50.App I objectives will be verified when fluidize bed dryer effluents calculated NUREO-0737.Item III D I I incomplete HOUSTON.R H Assistant Director for Radiation Protection 83/01/06 NUOWAK, I M Assistant Director for Licensing 58pp 22500 310 24X Fiche 50-400,84/02/07.84030500044
- -8309060390 Forwards Equipment Qualification Branch SER imput for anytoon qualification of equipment important to safety moreon of the control of t
- ---8307200478 Forwards Geotechnical Engineering Section input to SER Input based on FSAR through Amend 9 Stability of 400-ft long retaining wall still open issue LEAR, G Structural & Geotechnical Engineering Branch 83/09/02 KNIGHTON. G Licensing Branch 3 76pp 22498 188 24X Fiche 50-400.84/02/07.8403050064
- --8309210098 Forwards Power Bys Branch SER for Chapters 8-10 of FSAR Issues requiring resolution include containment electrical penetrations, use of load sequence w/offsite power & frequency of testing of turbine valves RUBENBTEINL S Assistant Director for Core & Plant Systems 83/08/31 NOVAK, T M Assistant Director for Licensing BOpp 22498-041 24X Fiche 50-400,84/02/07,8403050064
- --8309210116 Forwards SER input for FSAR Sections 4 2.4 3,4 4,15 4 1.
 15 4 2,15 4 3,15 4 7 & 15 4 B Confirmatory & open issues identified listed
 RUBENSTEIN.L S Assistant Director for Core & Plant Systems
 83/09/01 NOVAK.T M. Assistant Director for Licensing 69pp
 22498-119 24X Fiche 50-400,84/02/07.8403050064
- -8307220302 Forwards hydrologic engineering input to SER One open item 307220302 Forwards Aydrologic angineering input to SER One op exists re potential for intense local precipitation to flood safety-related structures Tech Spec defining anti-sediment deposit procedure required JUHNSTON, W V. Assistant Director for Matls, Chem & Environ Technology (Post B30201) 83/09/14 NOVAX, T M Assistant Director for Licensing 24pp 22499 188 24X Fiche 50-400.84/02/07,8403050044
- --8309260018 Forwards SER supporting geology & seismology at Pacility KN16HT, J.P. Assistant Director for Comp & Structures Engineering (Post 830201) 83/09/08 NDVAK,T M Assistant Director for Licensing. 44pp 22498 264 24X Fiche 50-400,84/02/07, 8403080044
- ---B3092A0421 Forwards structural engineering SER sections based on review of FSAR through Amend 7 Three open & one confirmatory items remain Resolution of open/confirmatory items will be addressed in subsequent SSER MNIGHT. J P Assistant Director for Comp & Structures Engineering (Post B30201) B3/09/15 NOVAN.T M Assistant Director for Licensing. 16pp 22479 212 24X Fiche 50-400, B4/02/07, B403050064
- ---8309260482 Forwards Auxiliary Bys Branch SER input based on review of all amends to FBAR up to Amend 9 & applicants 830418,0603, 30,0705,15 & 0812 responses Summary of unresolved issues to be used as basis for meeting w/applicant also encl RUBENSTEIN.L B. Assistant Director for Core & Plant Bystems 83/07/14 NOVAN.T M Assistant Director for Licensing 251pp 22478:308. 24X Fichs 50-400,84/02/07,8403050064
- --B309290412 Forwards Effluent Treatment Sys Section input to SER reflecting changes in status of open items based on B30824 meeting MULLER, D.R. Assistant Director for Radiation Protection B3/09/14, NOVAK, T.M. Assistant Director for Operating Reactors 60pp 22500:190, 24X Fiche.50-400,84/02/07,8403050064.
- --B309290474 Forwards SER on plant personnel training. Util training programs for licensed reactor operators acceptable Util inadequately addressed training of shift technical advisor (BTA) when STA absent from STA duties RUBBELL. W. Division of Human Factors Safety B3/09/R1 NOVAK. Assistant Director for Licensing. 2ipp. 22479 228 24X Fiche: 50-400, 84/02/07, 8403050044 NOVAK, T

- --8310130378 Forwards branch SER input re status of unresolved issues, in response to ALAB-444 decision Issues A-45 & A-47 listed as confirmatory items rather than open items Wo encis KNIEL, K. Generic Issues Branch ALAB-444 83/10/04 KNIGHTON, G. Licensing Branch 3 26pp 22499 247 24X Fiche 50-400,84/02/07,8403050064
- --8310170095 Forwards Chemical Engineering Branch proposed license condition re TMI Item II B 3, "Post-Accident Sampling Sys "Contents of draft SER should be used for SER JOHNSTON, W V Assistant Director for Matls, Chem & Environ Technology (Post 830201) 83/10/06 NOVAK, T M Assistant Director for Licensing 3pp 22499 279 24X Fithe 50-400,84/02/07,8403050064
- --B310190047 Forwards aerial maps as input to B21222 draft SER Item re shipment of taxic matls past plant site not resolved JOHNSTON.W V Assistant Director for Matls. Chem & Environ Technology (Post B30201) B3/10/11 NOVAK.T M Assistant Director for Licensing App 22499 331 24X Fiche 50-400, 84/02/07, 8403050064
- --B310200096 Forwards SER input on pump & valve operability assurance program & seismic & dynamic qualification of seismic Category I mechanical & electrical equipment Addl info needed for TMI Items II E 4 2 & II D i re reliability. KNIGHTJ P Assistant Director for Comp & Structures Engineering (Post 830201) 83/10/06 NGWAK, TM Assistant Director for Licensing 4pp 22479 275 24X Fiche 50-400.84/02/07,8403050064
- --8310310445 Forwards results of review of Sections 5 2 2.5 4 7.6 3 4 15 through Amend 10 of FSAR Open issues which will be summarized in later SCR suppl listed HOUSTON.R W Assistant Director for Reactor Safety B3/10/07 NOVAK.T M Assistant Director for Licensing 47pp 22499 282 24X Fitch 50-400.84/02/07.8403030044
- --B311100049 Informs that applicant is to submit calculation of ultimate strength capacity of containment bldg under internal pressure as resolution of SER outstanding confirmatory structural item Marked-up SER input encl

 LEAR.G Structural & Geotechnical Engineering Branch 83/10/28 KN1014FON.9 Licensing Branch 3 3pp 22500 024 24X Fiche 50-400,04/02/07.8403050064
- --831110263 Informs of closeout of listed sections of 830914 SER based on new info Updated sections encl Closeout of add1 open items.including NUREG-0642 info.mill take place as acceptable info made available RUBENSTEIN.L S Assistant Director for Core & Plant Bystems 83/10/28 NOVAK.T M Assistant Director for Licensing 49pp 22499 337 24X Fiche 50-400.84/02/07.8403050064
- --B3jii40:004 Advises that, due to need to coordinate affort w/Auxiliary Sys Branch, revised SER to be submitted on B3ji27 will still contain listed fire protection open items.

 JOHNSTON.W V Assistant Director for Matls, Chem & Environ Technology (Post 830201) B3/11/03 NOVAK, T Assistant Director for Licensing 2pp 22500 030 24% Fiche 50-400,84/02/07,8403050064.
- ---8311160283 Forwards revised SER input on confirmatory item re ultimate strength capacity of concrete containment bldg Item 1 esolved LFAR. G Structural & Gentechnical Engineering Branch. 83/11/14 KNICHTON.G Licensing Branch 3 Jpp 22500 047 24X Fichr 50-400.84/02/07.8403050064.
- --B311160367 Informs that draft BER Bection 17 acceptable except in area of items subj to 100CR30. App B.GA program during operations phase Info re current status & acceptability of GA program encl
 PARTION.J G. Division of GA. Safeguards & Inspection Programs
 (Post B30103) B3/11/09 Y0UNOBLODD.B J Licensing Branch I
 3pp 22500 027 24% Fiche 50-400.84/02/07.8403030064
- --8311290301 Forwards revised Hydrologic Engineering input to SER New Tech Spec requirement developed re watertight doors for safety-related bldgs
 JOHNGTON W V Division of Engineering Technology 83/11/10
 NOVAK, T M Assistant Director for Licensing 15pp 22500 032
 P4X Fiche 50-400, 84/02/07, 8403050064
- --8311270352 Updates SER re stability of retaining wall west of fuel handling bldg Based on applicant 830717 submittals, stability cannot be assured due to lack of listed info Final SER update encl
 LEAK, GE Hydrologic & Geotechnical Engineering Branch 83/11/18
 KNIGHTON.9 Licensing Branch 3 5pp 22501 047 24X
 Fiche 50-400,84/02/07.8403050064

- ~-0312020063 Forwards SSER resolving open item on toxic gas shipments past site Concurs w/findings & considers item closed OUHNITON, W V Assistant Director for Matls, Chem & Environ Technology (Post 830201) 83/11/18 NOVAK,T M Assistant Director for Licensing 2pp 22501 054 24X Fiche 30-400.04/02/07.8403050064
- --B312080188 Forwards affluent treatment sys section input to SER Open items include method for determining releases of noble gases from methonical vacuum pumps & radioactivity monitor on discharge from svc water sys MULLER, D.R. Assistant Director for Radiation Protection 83/11/18 NOWAK, T.M. Assistant Director for Licensing 51pp 22500 139 24X Fiche 50-400.84/02/07.8403050064
- --B312120002 Lists closed out open items in SER forwarded on 830714 & sections w/romaining open items
 RUBCNSTEIN.L 8 Assistant Director for Core & Plant Bystems
 83/11/17 NOVAK.T M Division of Licensing 88pp 22500 050
 24% Fiche 50-400.84/02/07.8403050064
- --8312120445 Forwards input to SER, consisting of emergency plan evaluation rept & responses to NUREG-0737. Items
 III A 1 L, III A 1 2 & III A 2 re emergency preparedness
 MATTHEMS, D B Division of Emergency Preparedness & Engineering
 Response (Post 830103) B3/11/30 KNIGHTON, G Licensing Branch
 3 36pp 22501 058 24X Fiche 50-400.84/02/07, B403050064
- ~~8312140429 Submits review of draft SER response to Open Item 47 on RCS vents Proposed design conforms w/criteria outlined in NUREO-0737 clarification pertaining to electrical power supplies to vent valves SRINIVASAN.M Power Systems Branch 83/11/23 SHERON.B Reactor Systems Branch 2pp 22501 056 24X Fiche 50-400.84/02/07, 8403050064
- 8403050283 Further response to FOIA request for records of named individuals, including repts, analyses, studies, test calculations, procedures & practices for measurement of RCS leakage. Forwards App C documents Bearch continuing FELTON, J M Division of Rules and Records 84/02/07 MADDEN, T J Kaye. Beholsr. Fierman, Hays & Handler 3pp 22476 234 24X Fiche 50-000,84/02/07,8403050223
- ---8208240003 Forwards computer program developed to analyze & measure RCS leak rates, per commitment made at 820607 meeting Program calculates inventory of water in RCS & in tanks which collect coolant leakage CUNNINOHAMIL J Division of Engineering & Quality Assurance (Pre 830103) B2/06/15, PARR. O D Auxiliary Systems Branch ip 22496 272
- ---8403050232 Forwards Hewlett Packard 41C data cards containing plantspecific data for RCS leakage calculations for all Region III PMRs together w/complete card listing All PMRs in Region III evaluated NORELIUS: C E Division of Engineering & Technical Inspection 82/01/13 BAER: R L Division of Engineering & Guality Assurance (Pre 830103), 7pp 22496 237 24X Fiche 50-000.84/02/07, 8403030203
- --8403050233 Advises that certain aspects of facility Tech Spec requirements governing RCS leakage appear to be inconsistent wistd nuclear industry practice Licensee should be requested to modify Tech Specs Related info and NURELIUS, C E Region 3, Office of Director 82/03/10 618ENHUT, D 0 Division of Engineering 11pp 22496-246 24X Ficho 50-000,84/02/07,8403050223
- ---B403050241 Forwards potentially generic issue data sheet on B00611 event re failure of BUR drywell leakage detection sys to identify significant leakage
 BRUNNER, E. J. Region 1, Philadelphia, Office of the Director-BU07710 JORDAN, E.L. Region 1, Philadelphia, Office of the Director LEWIG.R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch HEISHMAN, R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 2pp 22496 257 24X Fiche 50-000, 84/02/07, 8403050223
- --8403080245 Discusses independent measurement of RCS leak rates, Proposed leak rate calculation using programmable HP410 calculator reviewed Lists advantages of having analytical equation CAPHTON, D. Test Program Section 81/03/19 SNIEZEK, J. H Division of Resident & Regional Reactor Inspection 5pp. 22476 243.

- --8403050250 Forwards plant-specific data cards for facilities re reactor coolont leakage calculations,per 810902 request Add1 data cards for remaining plants will be sent shortly CREMS.J L Division of Resident, Reactor Projects & Engineering Inspection 81/09/16 BAER.R L Division of Resident & Regional Reactor Inspection 2pp 22496 268 24X Fiche 50-000.84/02/07, 8403050223
- --B403050254 Notifies that independent measurements of identified & unidentified RCB leak rates for all PMRs in Region III performed per Procedures 617270 & 617288 Insp findings summarized NORELIUS.C E Division of Engineering 82/03/08 JORDAN,E L Division of Engineering & Quality Assurance (Pre 830103) 2pp 22476 270 24X Fiche 50-000,84/02/07,8403050223
- --8403050266 Forwards revised computer program for determining RCS leak rates & draft insp procedure Revised computer program incorporates improvements based on suggestions received from field improvements listed KIRKPATRICK, D. WOODRUFF, R W Division of Engineering & Quality Assurance (Pre 830103) 82/08/27 JORDAN, E L Division of Engineering & Quality Assurance (Pre 830103) 4pp 22496 273
- --8403050270 "RCSLKB, Program for Calculating RCS Leak Rates for PWRs " KIRKPATRICK, D , WOODRUFF, R W Division of Engineering & Guality Assurance (Pre 830103) 82/07/30 64pp 22476 277
- --B403050274 Informs that Region I attendees at B30413 & 14 RCSLK8 seminar in Bethesda are JW Chung & PC Wen, per 830304 memo Permanent custodian of computer & printer is L Bettenhausen. Chief. Test Program Section, Engineering Programs Branch MARTIN, T T Division of Engineering & Technical Programs B3/03/16 JORDAN, E L Division of Emergency Proparadness & Engineering Response (Post B30103) Ip 22496-341
- --8403050279 Informs that LA Reyes designated custodian for Osborne computer & printer per 830304 memo MA Ring, PR Mohld & LA Reyes scheduled to attend seminar on application of RCSLKB program & computer use 8PES9ARD.R L Division of Engineering 83/03/22 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) ip 22476 342
- 8403050288 Fifth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App A & B documents also available in PDR Documents listed on App C & D located in Central Files & not available publicly FELTON, J M Division of Rules and Records 84/02/17 ANDERSON, B I Garvey, Schubert, Adams & Barer 9pp 22501 289 24X Fiche 50-509,84/02/17,8403050288
- --7906190142 Approves GA fire protection program description & related commitments
 HAASS W P. Guality Assurance Branch 77/05/10 PARR, D Light
 Water Reactors Branch 3 ip 22501 309 24X
 Fithe 50-460, 84/02/17, 8403050288
- --7908010102 Forwards 790501 Haas-Oryan memo re NRR-QAB resolution of Region 5 comments re operational QA program NDLAN.F J Division of Reactor Operations Inspections 79/05/09 CREMBJ L Region 4, Dallas, Office of the Director 1p. 22501:306 24X Fiche:50-509,84/02/17.8403050288
- --7908010232 Responds to 790405 Region 5 comments re Revision 4 to NPP88-GA-004, "Operational GA Program Description."

 Expresses intent to request util to delete Section 3 3 6 entirely.

 HAASS.W P Quality Assurance Branch 79/05/01 BRYAN, 8 E Division of Resector Operations Inspections ip 22501 305 E4X Fiche 50-397, 84/02/17, 8403050288
- --8003240209 Discusses conversation w/R McKinney of ACRB re dual unit plants Time should be cut in half HOLLCURAY.C J. Office of Management and Program Analysis 79/01/22 Qffice of Management and Program Analysis lp. 22501
- ---801i120101 Forwards results of contacts w/three NSSS vendors re level of GA controls applied to power operated relief valves & block valves for PMRs in operation & under const HAASS W.P. Quality Assurance Brench 80708726 VOLLMER, R.H. Division of Engineering 5pp 22301.300
- --Biigi90051 Responds to Bi0923 FDIA Bi-378 request for GA documents for WPPBS. All documents re evaluation of licenses GA programs are in PDR
 HAABS.W P Quality Assurance Branch 81/10/05 WILSON, V H
 Management Analysis Branch. 2pp. 22501 310. 24X
 Fiche: 50-397, 84/02/17, 8403350288

- --Bi10210316 Informs of receipt of Bouchey/Adensam 810722 ltr containing util current dA program description for design & const of facilities GA program description acceptable
 HAASS.W P Quality Assurance Branch 81/10/14 TEDESCO.R L
 Assistant Director for Licensing 1p 22501 Ji2 24X
 Fiche 50-460.84/02/17.840305028B
- --Billo20578 Concludes that util & principal contractors continue to meet criteria of 10CFR50 App B Revised QA program description acceptable for design & const of facilities HAAS5.W P Quality Assurance Branch 81/10/22 TEDESCO.R L Assistant Director for Licensing Ip 22501 313 24X Fiche 30-308.04/02/17.8403050288
- --8201300236 Forwards data for fee assessment re QA Branch review of WIPSS-QA-004, "Operational QA Program Description" HASS.W P Quality Assurance Branch 82/01/14 BERKOW.H N Management Analysis Branch 8pp 22901 314 24X Fiche 50~397,84/02/17,8403050288
- 8403060085 FOIA request for documents re Equipment Qualification Branch request to OELD for clarification of 10CFR50 49 HOLZMAN.P M Engineering Planning & Management, Inc P13503 004 83/12/28 FELTON,J M Division of Rules and Records 1p 22588 P13
- 8403060091 Responds to FDIA request for records prepared by NRC re request to DELD for clarification of IOCFR50 49 Forwards App A documents No add1 records located subj to request FEL10N.J M Division of Rules and Records 84/01/23 HOLZMAN,P M Engineering Planning & Management, Inc 2pp 22528 214
- ---B307120556 Requests comments on interpretations of Section 50 49 of IOCFR50, "Environ Qualification of Electric Equipment Important to Safety for Nuclear Power Plants "VOLLMER:R H Division of Engineering 83/08/31 OLMSTEAD,W J Regulations Division 3pp 22528 216
- --8403060095 Responds to specific questions raised in 830831 request re legal interpretation of 10CFR50 49. "Environ Gualification Rule" OLMSTEAD, W. J. Office of the Executive Legal Director 83/10/04 VOLLMER, R. H. Division of Engineering 3pp 22528 217
- B403060120 FOIA request for notices of violation issued by NRC re leak rate detection or limiting conditions of operation for leakage LCVIN.L A Affiliation Not Assigned 83/12/01 NORRY,P Q Office of Administration 2pp 22528 244
- 8403060123 Responds to FOIA request for two categories of records re RCS leakage Documents listed on App A placed in PDR FELTON.J M Division of Rules and Records 84/01/20 LEVIN.L A Affiliation Not Assigned 3pp 22528 246
- 8403060135 FOIA request for winning proposal submitted by Advanced Technology. Inc. under NRC Contract NRC-33-84-380 PADEN.R C Control Data Corp. 837/12/15 NRC - No Detailed Affiliation Given 1p 22552 213
- 840306014B Responds to FOIA request for winning proposal submitted by Advanced Technology, Inc under NRC Contract NRC-33-84-380 Forwards nonproprietary version of 830815 technical proposal best & final B31014 technical proposal FELTON.J M Division of Rules and Records NRC-33-84-380 84/01/17 PADEN.R C Control Data Corp ip 22552 214
- --8403060152 "Programming, Training, Testing, Conversion & Implementation of LPDR," best & final technical proposal

 * Advanced Technology, Inc. R8-ORM-83-462 B3/10/14 9pp
 20582 215
- ---8403060154 "Programming, Training, Testing, Conversion & Implementation of LPDR," technical proposal

 * Advanced Technology, Inc. RS-DRM-83-462 83/08/15 28pp
- 8403060158 Responds to FOIA request for 831230 FOIA request filed w/NRC by Texas Utils Generating Co (TUGC) & records requested by TUGC. Bearch revealed no documents subj to request FELTON, J M Division of Rules and Records 84/01/30 LODGE, G Dallas Morning News 1p 22528 235.
- B403060164 FDIA request for 831230 FDIA request filed w/NRC by Texas Utils Generating Co (TUGC) & all records requested by TUGC List of FDIA requests filed by 10 listed utils also requested LODGE, B Dallas Morning News B4/01/19 NRC ~ No Detailed Affiliation Given 1p 22528/236

- 8403060169 Responds to FOIA request for info re computer sys facilities operated by contractor & list identifying svc contractor name, contract value & contract number Forwards incomplete updated list
 FELTON J M Division of Rules and Records 84/01/31 MADDEN C H
 Information Handling Services 4pp 22528 237
- 84030601/1 FOIA request for info re computer sys facilities operated for NRC Info needed in order to perform marketing study MADDEN Information Handling Services 84/01/18 NRC No Detailed Affiliation Given 3pp 22328 241
- 8403060461 Appeals denial of FOIA request for SECY-82-340 HICKEY, J.P. Shaw, Pittman, Potts & Troubridge 84/02/10 CHILK, S. J. Office of the Secretary of the Commission 1: 22552-050
- B4030&0464 FD1A request for SECY-B2-340 re current Dfc of Investigations policy on board notifications HICKEY, J P Shaw, Pittman, Potts & Trowbridge B3/11/ GRIMSLIY, D H Division of Rules and Records ip 225 83/11/30
- 8403060469 Responds to appeal re denial of FOIA request for SECY-B2~ 340 Dotument placed in PDR FELTON,J M Division of Rules and Records 84/02/17 HICKEY,J P Shaw, Fittman, Potts & Troubridge 1p 22552 035
- -8209200364 SECY-82-340 EMPROUSON BECY-BE-380
 Infolms of proceedures to process board notifications
 involving allegations which may fall within investigative
 purview of Ofc of Investigations
 DIRCKS, W J Office of the Executive Director for Operations
 B2/08/17 7pp 22552 057,
- B403060486 Further response to FDIA request for documents re evaluation or review of design const.scheduling.cost & licensing of facilities from 1977 to present Rept unavailable for Categories 1 & 2 Panel records on evaluations placed in PDR FELTON, J M Division of Rules and Records 84/01/24 ZACK, A M Barris, Sott. Denn & Driker 2pp 22552 252 24X Fiche 50-329.84/01/24,8403060486
- 8403070098 FOIA request for V Stello 830803 memo re task group to study surveillance testing in Tech Specs & 830916 & 1004 ltrs from JJ Sheppard of Westinghouse Owners Group to be placed in PDR Documents referenced in NUREG-1024 PEDRO,J NUS Corp CD-LIS-83-073 84/02/02 Division of Rules and Records 1p 22541 192
- 8403070101 Responds to FDIA request for V Stello 830803 memo re task group to study surveillance testing in Tech Specs & 830916 & 1006 ltrs from JJ Sheppard to be placed in PDR Forwards documents Documents also available in PDR FECTON.J M Division of Rules and Records 84/02/16 PEDRO.J NUS Corp 1p 22561 153
- ---B30B150440 Requests nominations for task group to study design of surveillance testing required in Tech Specs One person familiar w/PWR lech Specs & one familiar W/BWR Tech Specs 83/08/03,
- --8403070106 Comments on list of Tech Spec surveillance problem areas requested at Westinghouse Owners Group subcommittee 830908 meeting List encl meeting List encl
 SHEPPARD.J J Westinghouse Operating Plants Owners Group
 SHEPPARD.J J Carolina Power & Light Co OG-103 83/09/16
 ENIEZEK.J H Regional Operations & Generic Requirements 5
- ~~B40307010B Comments on list of priority Tech Spec problem areas requested at Westinghouse Owners Group & NRC task force 830920 meeting List encl SHEPPARD. J Westinghouse Operating Plants Owners Group SHEPPARD. J Carolina Power & Light Co 09-107, 83/10/04 SNIEZEK, J H Regional Operations & Generic Requirements 3p; 2051 161
- 8403070110 Responds to FOIA request for names & addresses of various NRC matl licensees in Regions II & III Forwards two printouts fornishing into subj to request W/o Encls FELTON. J M Division of Rules and Records. 84/02/22. HIKONSKI, J. Affiliation Not Assigned ip 22564 121
- 9403070113 FDIA request for names & addresses of various NRC mati-licensees in Regions II & III MIKONSKI.J Affiliation Not Assigned 84/02/07 Office of t Executive Director for Operations 2pp. 22544-122 94/02/07 Office of the 2pp. 22564 122

- 8403070213 FOIA request for documents re 630919 meeting to discuss steam erosion issue in facility proceeding & TM Novak 830825 memo on steam erosion issue HIATT.S.L. Chio Citizens for Responsible Energy 83/12/08 FELTON, J.M. Division of Rules and Records 1p 22563 219 24X Fiche 50-440, 83/12/08, 8403070213
- 8403070215 Responds to FOIA request for documents re 830919 meeting to discuss steam erosion issue in facility proceeding & TM Novak 830828 memo on subj Forwards App A documents Documents A & 5 withheld (ref FDIA Exemption 5) FELTON, J M Division of Rules and Records 84/01/23 HIATT, 8 Ohio Citizens for Responsible Energy 3pp 22563 220 24X Fiche 50-440,84/01/23.8403070215
- --8306220210 Forwards draft staff position on Contention 19 re steam erosion Applicant has not demonstrated capability to prevent or discover effects of steam erosion Comments requested PARR.O D Auxiliary Systems Branch 83/06/14 LIAW.B Mechanical Engineering Branch ip 22563 226 24X Fiche 90-440,84/01/23,8403070215
- --B403070221 Requests confirmation on lead responsibilities for finalizing NRC position re steam erosion contention issue Responsibility should be shared by Mechanical Engineering Branch & Meteorology & Effluent Treatment Branch NUVAK.7 M Assistant Director for Licensing B3/0B/25 NNIOHT.J.P Assistant Director for Comp & Btructures Engineering (Post B30201) J0HNBTON.W.V Assistant Director for Matls. Chem & Environ Technology (Post B30201) 2pp 22563 224 24X Fiche 50-440,84/01/23,8403070215
- 8403070226 FDIA request for repts to results of investigation of failed reactor vessel holddown studs on Unit I reactor vessel PLATO, F.D. Kohl, Secrest, Wardle, Lynch, Clark & Hampton 84/01/23 KEPPLER, J.O. Region 3, Office of Director 2pp 22564 147 24X Fiche DO-329,84/01/23,8403070226
- 8403070279 Partial response to FGIA request for repts re NRC investigation of failure of reactor vessel holddown studs on Unit 1 reactor vessel Forwards App A & B documents FELTON, J H Division of Rules and Records 84/02/23 PLATO, E D Kohl. Secrest, Wardle, Lynch, Clark & Hampton App 22564 149 Fiche 50-327.84/02/23,8403070229
- --8403070234 PNO-III-064 on 791219, second reactor vessel anchor bolt found broken Teledyne Engineering Svc currently performing tests on bolt matl Results expected in near future KNOP, R C Region 3, Chicago, Office of the Director 79/12/20 3pp 22544 155
- --8403070340 Ack receipt of 791214 interim rept re broken anchor bolt in AUGUSTA ACK receipt of 77124 anterm rept re broken reactor vessel support skirt flangs FIGRELLIG Region 3. Chicago. Diffice of the Director HOWELL,8 H Consumers Power Co 10pp 22564 158 2 Fiche 50-329, 84702/23,8403070229
- --8403070343 Forwards IE Insp Repts 50-329/80-12 & 50-330/80-13 on 800301-31 No noncompliance noted Major areas inspected. exam of procedures & representative records, observations & interviews w/personnel W/o encl FIDRELLI, G Region 3, Chicago, Office of the Director 80/05/19 HOWELLS H Consumers Fower Co 2pp 22564 170 24X Fiche 50-329,84/02/23,8403070229
- --8403070345 Recommends order be issued to util requiring action to correct unacceptable anchor bolts at facility Draft ltr & order enal order encl
 KEPPLER,J 0 Region 3, Chicago, Office of the Director 80/0
 THOMPSON,D Executive Officer for Operations Support 36pp
 22564 172 24X Fiche 50-329,84/02/23,8403070229 80/06/27
- --84030/0349 Forwards depositions re preservice failure of reactor vassel studs utilized at Unit 1.Related info encl LEMIS.8 H Region 3. Office of Director 84/01/06 BERKOYTY.D M Office of the General Counsel 52pp 22564-264 24X Fiche 50-029.84/02/23.8403070229.
- --8403070351 Responds to 830901 1tr & forwards IE Investigation Repts 50-329/80-13 & 50-330/80-14 W/o encl LEHTS.8 H Region 3. Office of Director 83/09/20 MYERB.T F Garan, Lucow, Miller, Seward, Cooper & Becker ip 22564.263 24% Fiche 50-329.84/02/23.8403070229
- 8403080003 FDIA request for 10 contractor repts on generic modeling for vital area & safeguards analysis referenced in NUREO/CR-3121 RONGOVER-SIZE ONLY OF Concerned Scientists 84/01/10 FELTON, J M Division of Rules and Records 2pp 22578 001.

ī

- 8403080005 Responds to FOIA request for 10 contractor repts to be placed in PDR Forwards nine specified repts Rept identified in Item 9 of request not yet published Rept expected to be published within next 3 months FELTON.J M Division of Rules and Records 84/02/24 SHDLLY, S C Union of Concerned Scientists 1p 22578 603
- --B4030B0006 SANDB2-7220
 "Technical Basis for & Description of Function Level Generic Fault Trees for LWR Plants." contractor rept
 FINN, B. HORTON, W. Science Applications, Inc. FIN A-1060
 SAIO13B0-399LJ 83/03/31 Division of Facility Operations 200pp 22578 004
- --B4030B000B BANDBR-7032 VOI
 Vol 1 to "Generic Modeling Approach for Major Components in
 LWRs Fault Trees for Generic Modeling Approach," contractor
 rept
 HORTON, W., FINN, S. Science Applications, Inc. FIN A-1060
 SA101381-309LJ 83/03/31 Division of Facility Operations
 234pp 22578 205
- --B4030B0010 SANDB2-7219 VOI Vol 1 to "Generic Modeling Approach for Fluid Sys Found in LWRs Fault Trees for Generic Modeling Approach," contractor rept FINN, S, HORTON, W Science Applications, Inc FIN A-1060 SAI013B1-410LJ 83/03/31 Division of Facility Operations 64p 22379 079
- --B4030B0012 SANDB2-7217 VO2
 Vol 2 to "Generic Modeling Approach for Fluid Sys in LWRs.
 Guestionnaires for Application of Generic Modeling
 Approach." contractor rept
 FINN.B , HORTON.W Science Applications, Inc FIN A-1040
 SAI013B1-411LJ 83/03/31 Division of Facility Operations
 133pp 22579 144
- --8403080017 BAND82-7032 VOZ
 Vol 2 to "Generic Modeling Approach for Major Components in
 LURs Questionnaires for Application of Generic Modeling
 Approach," contractor rept
 HORTON,W, FINN.S Science Applications, Inc FIN A-1060
 SAI01381-3081, 83/03/31 Division of Facility Operations
 125pp 22579 277
- ---B4030B0019 SANDB2-7219 VO3
 Vol 3 to "Generic Modeling Approach for Fluid Sys in LWRs
 Instruction Sheets for Application of Generic Modeling
 Approach," contractor rept
 FINN: S. HORTON: W Science Applications, Inc FIN A-1060
 SAI013B1-412LJ B3/03/31 Division of Facility Operations
 165pp R2580-042
- ---8403080025 SANDBR-7032 V03
 Vol 3 to "Generic Modeling Approach for Major Components in LMRs' Instruction Sheets for Application of Generic Modeling Approach," contractor rept
 HORTON, W., FINN: 8 Science Applications, Inc. FIN A-1040
 BAJ01381-8951_J, 83/03/31 Division of Facility Operations
 R15pp R2580 R07
- --8403080027 SAND82-1457
 "Computer Automation of Generic Modeling Approach for Major Components in LWRs."
 DANIEL, B L , HIGGINS, B, J , HILL, M S Sandia Leboratories FIN A-1060 83/05/31 Division of Facility Operations 120pp 22581, 062
- 8403080016 Further response to FOIA request for lists & records re Go-40 licensees, Forwards App A documents, per Item 3 of request Portions of Documents 2 through 5 of App B deleted (ref FOIA Exemptions 6 & 7) FELTON, J M Division of Rules and Records 84/01/11, COWIE, D. J Bouck: Holloway, Kiernan & Casey, 5pp 22576 294
- --B005010203 PNO-III-B0-60 on B00318, 25 mCi Co-60 sealed source under License i2-i3720-01 fell into coke hopper Source believed to be in pile of coke in facility yard, on barge heading for Chicago or in freight car bound for Shawinigan, Quebec. SCHULTZ.H.H., DAVIB, A B Region 3. Chicago, Office of the Director B0/03/25 ip 22574 299
- --B005280995 Forwards IE Insp Rept 30-04297/B0-01 on 800327 of activities under License 12-13720-01 No noncompliance noted DAVIS,A B. Region 3, Chicago, Fuel Facility & Materials Safety Branch B0/04/17, Clark Gil & Refining Corp 2pp 22576 300.
- ---B005280798 IE Insp Rept 30-04297/80-01 on 800327 No noncompliance noted. Major areas inspected. attempt was made to relocate 6 mG; sealed source level indicator lost by licensee ADAM, W J Region 3, Chicago, Office of the Director PAPERIELLO, C J Region 3, Chicago, Pul Facility & Materials Safety Branch 80/04/14 5pp 22576 302

- --8010230503 Forwards personnel exposures measured from reconst of 800925 incident involving jamming of Co-60 teletherapy source Corrective actions procedures reviewed w/personnel & new colbait source installed and LISTER, W E , IGNATOW, S B Ft Hamilton-Hughes Memorial Hosp Center, Hamilton, OH 80/10/17 WEIL, C Region 3, Chicago, Office of the Director 6pp 22577 044
- --8101290708 Responds to 810112 telcon re 810121 meeting w/WE Lister & Kereiakes to discuss proposed corrective actions & NRC enforcement options for 800920 investigation KEPPLER. J O Region 3. Chicago. Office of the Director 81/01/16 LISTER.W E Ft Hamilton-Hughes Memorial Hosp Center, Hamilton, GH 1p 22976 319
- --BIO224003B Forwards IE Insp Rept 30-00143/BI-02 on BI0120 of activities under License 12-00912-03 No noncompliance noted FISHER. W. Region 3. Chicago. Office of the Director BI/02/09 SIBTER JEANINE Dak Park Hosp., Oak Park. IL 1p 22577 123
- --Bi022400&6 IE Insp Rept 30-00143/Bi-02 on 810120 No noncompliance noted Major areas inspected re-enactment of emergency procedures in response to 810113 teletherapy unit malfunction BURGIN.R E . BCRRLTZ.W H Region 3. Chicago, Office of the Director 81/02/03 App 22577 1P4
- --B403080033 Notifies that on B00325.25 mCi of Co-60 missing from north cokt drum at Wood River Refinery in Hartford.IL Chronological events listed Diagrams of coke drums encl # Clark Oil & Refining Corp 80/05/12 SCHULTZ.8 NRC No Detailed Affiliation Oiven 7pp 22576 307
- --8403080038 Informs of 801002 telcon w/W Lister of Fort Hamilton-Hughes Medical Ctr re agreement on immediate action ltr Lister agreed to items in ltr No final determination made of enforcement action DAVIS.A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 80/10/03 Region 3, Chicago, Fuel Facility & Materials Safety Branch 1p 22376-316
- --84030B0044 Ack receipt of B01017 ltr informing NRC of personnel exposures measured during reconstruction of incident on B007P5 & advising NRC of courses of action investigation rept re incident will be issued within next 10 wks KEPPLER.J Q Region 3, Chicago, Office of the Director B0/11/02 LIBTER.W E Ft Hamilton-Hughes Memorial Hosp Center, Hamilton, OH ip 22976 317
- --84030B004B Notification of 810121 meeting w/licensee in Glen Ellyn.IL to discuss NRC findings during recent insp of teletherapy incident & possible enforcement options

 * Rigion 3, Chicago, Office of the Director 81/01/13 Region 3, Chicago. Office of the Director 1p 22576 318
- --8403080057 Discusses 800930 & 1003 investigation re 800925 incident concerning unplanned radiation exposure Forwards draft ltr to licensee w/notice of violation & draft investigation rept Related info encl
 KEPPLER. J O Region 3, Chicago, Office of the Director 81/01/22 THOMPSON. D Director's Office, Office of Inspection and Enforcement 78pp 22574 320
- --8403080101 Forwards IE Investigation Regt 30-13020/81-01 on 800930,1003 & 810121 Violation noted
 KEPPLER, J 9 Region 3, Chicago, Office of the Director (81/03/01)
 81/03/05 LISTER, W E Ft Hamilton-Hughes Memorial Hosp Center,
 Hamilton, OH ip 22577 054
- --8403080108 IE investigation Rept 30-13020/81-01 on 800930,1003 & 810121 Violations noted failure to notify responsible personnel of equipment failure.per License Condition 23 & servicing of teletherapy unit at 5-yr intervals WELL, C. H. ADAM, W. J., BURGIN, R. E. Region 3, Chicago, Office of the Director (81/03/01) 81/03/03 20pp 22577 055
- ---B4030B0113 Requests 7-day extension to respond to 810303 ltr & notices of violation & proposed imposition of civil penalties

 RULLMAN, B D Millikin & Fitton RULLMAN, B D Ft Hamilton-Hughes
 Memorial Hosp Center, Hamilton, OH EA-B1-19

 BIELLO, V NRC No Detailed Affiliation Given ip 22577 084
- --B4030B0120 Notifies that extension until 810406 granted for submitting response to 810303 notices of violation & proposed imposition of civil penalties, per 810325 request THOMPSON, 0 Director's Office. Office of Inspection and Enforcement 81/03/31 RULLMAN.S.D Millikin & Fitton RULLMAN,S.D, Ft Hamilton-Hughes Memorial Hosp Center, Hamilton, OH 1p 22577 085

- --B4030B0127 Discusses licensee 810403 response & IE investigation rept Civil penalties should be remitted due to insufficient info Incident should be classified under Severity Level IV Braft itr & draft notice of violation encl KCPPLER, J & Region 3. Chicago, Office of the Director (81/03/01) 81/03/27 THOMPSON, D Director's Office, Office of Inspection and Inforcement 20pp 22577 OB6
- --8403080162 PNU-I-81-033A on 810307.special insp conducted to determine eitent of Co-60 contamination resulting from leaking radiography source Contaminated clothing found at employee residence will be treated as raduaste COSTCLLO.F Director's Diffice, Office of Inspection and Enforcement KINNEMAN, J. Region 1, Philadelphia, Diffice of the Director (81/03/01) B1/03/09 ip 22577 129
- --B403080170 PNA-B)-OO6 on B10714.Louisiana Nuclear Energy Div notified NRC of radiography incident occurring on barge located less than 3 miles offshore Barge captain & radiographer exposed to 11 Ci Co-60 Medical attention obtained DUDA:R J Region 4. Dallas. Office of the Director (81/03/01) 81/07/21 2pp 22577 130
- --B4030B0175 Confirms B20416 telephone agreement that EL Saenger will assist NRC by serving as medical consultant remisadministration Findings & conclusions requested within 30 days of completion of advisory efforts

 KEPPLER.J G Region 3, Office of Director B2/04/23

 SAENGER,E L Affiliation Not Assigned 2pp 20577 143
- --8403080180 Submits Chronological sequence of events re misplaced radiological source.per 820112 telton Related info encl BROHN, R T Affiliation Not Assigned 82/01/13 WIDEMAN.D NRC No Detailed Affiliation Given 12pp 22577 166
- ---8403080186 Forwards internal investigation documents prepared by energency sycs & disaster agency as result of temporary loss of Co-60 source.per request Documents should be kept confidential
 HISC.D L Illinois, State of 82/01/19 WIEDEMAN.D Region 3.
 Office of Director 17pp 22577 178
- --B4030B0171 Discusses 830411 & 12 special insp performed of licensee program in recponse to allegations made by anonymous caller Five violations identified Special insp rept written & enforcement itr will be sent to licensee MILLER, J.R. Region 3, Office of Director 83/05/03 Region 3, Office 0, O
- --8403080194 IE Special Safety Insp Rept 30-04315/63-01 on 8304/1-12 Violations noted unauthorized individuals removed source & holder from coke from 11 & five Victoreen pocket type radiation dosimeters not calibr since gurchase on 820830 * Region 3, Office of Director 83/04/15 19pp 22577 244
- --B40308019B Forwards draft ltr to licensee w/notice of violation & proposed imposition of civil penalties & IE Insp Rept 30-00418/82-01 on 820419 for review & concurrence Justifications listed for reducing proposed civil penalty WARNICK, R F Region 3, Office of Director 82/06/23 L1698/80AN, J Director's Office, Office of Inspection and Enforcement 10pp 22577 286
- --B403080202 IE Insp Rept 30-00418/82-01 on 820419 Violation noted individual in restricted area exposed in excess of premissible limits & 24 h notification of incident not made BURGIN.R E , SRENIAMSKI.D J Region 3, Office of Director 82/06/16 10pp 22577 296
- --8403080204 Submits rept re 810622 incident concerning Ca-60 medical teletherapy unit. Individual film badge showed dosage of 9 710 rems whole body Person notified & advised to avoid radiation exposure for 6 months Related info encl TIDABACK, A J Blanchard Valley Hosp Findlay, QH B2/04/06 SRENIAWSKI, D Region 3. Office of Director 12pp 22977 306
- --8403080209 Discusses IE Insp Rept 30-00374/82-01 on 820413 & 12 & forwards notice of violation NORELIUS, C E Region 3, Office of Director 82/07/21 KRIEGER, J Cleveland Clinic, Cleveland, CH 2pp 22577 318
- ~~8403080211 Notice of violation from insp on 820413-14 NORELIUS.C C Division of Emergency Preparedness & Operational Support 82/07/21 ip 22577 320
- ---B403080215 IE Insp Rept 30-00394/82-01 on 820413-14 Violation noted failure to perform full calibr using dosimetry sysicalibr by NBS or by regional calibr lab MULLAUER.J.R., MADERA.J.R., SRENIAWSKI.D.J. Region 3, Office of Birertor 82/07/09 26pg 22577 321

- --8403080217 Submits questions, per 820420 telcon re misadministration Info will be kept confidential SACNGER, E.L. NRC - No Detailed Affiliation Given 82/04/23 RODRIGUES, A. Cleveland Clinic, Cleveland, OH ip 22577 347
- B4030B0071 FDIA request for documents re NRC internal procedures or guidance for evaluating new generic requirements & for use of cost-benefit or value-impact analysis & CROR guidance or procedures on cost-benefit or value-impact analysis WEJS9.E R Union of Concerned Scientists 83/12/21 FELTON, J M Division of Rules and Records 1p 22884 114
- 8403080023 FDIA request for documents re NRC & Radiation Technology Inc.located in Rockaway.NJ Documents should include all insp correspondence from 1976 to present enforcement info from 1977 & 78 & hearing transcript re 1976 incident KASS.D E Affiliation Not Assigned 83/11/22 Office of Administration ip 22582 001
- B4030B0027 Responds to FDIA request for documents on NRC & Radiation Technology Inc.located in Rockeway, NJ Forwards App A documents FELTDN.J M Division of Rules and Records 83/12/30 KASS.D E Affiliation Not Assigned 3pp 22582 002
- ---8403080032 Forwards 1E Insp Repts 30-07022/77-03 & 30-07022/77-04 on 770923-1014 Violation noted failure to make immediate rept of personnel overexposure item of noncompliance will not be included in notice of violation GRILR.B H Region 1. Philadelphia, Office of the Director 78/01/06 WELT.M A Radiation Technology, Inc. 2pp 32582 225
- --B4030B0036 Initial prelicensing visit insprept on 701120 EPBTEIN E Atomic Energy Commission 70/11/22 10pp, 22582 005
- --8403080040 Submits clarifications & corrections to items found in IE Insp Repts 30-07022/77-03 & 30-07022/77-04 Request for meeting w/appropriate NRC personnel reiterated WEITM A Radiation Technology, Inc 78/01/18 ORIER, B H Region 1, Philadelphia, Office of the Director 5pp 22582 227
- --8403080043 Forwards IE Insp Rept 30-07022/77-06 on 771220-22 No violations noted GRIERS H Region 1. Philadelphia. Office of the Director 78/01/17 WELT.M A Radiation Technology. Inc. 3pp 22582 232
- --8403080045 Discusses inspector evaluation of License 29-13413-01 License properly categorized as E-III Extension of 12 months in reinse frequency recommended Next insp will be scheduled in Apr 1974 EPSICIN.E Atomic Energy Commission 71/05/06 NELSON.P R Atomic Energy Commission 1p 23582 015
- ---8403080046 Responds to NRC 770314 ltr re violations noted in IE insp of License 29-13613-02 Corrective actions pool water will be sampled on routine basis & NRC will be notified if reading equals or exceeds 0 05 uc/100 ml Meeting w/NRC requested WELT.M A Radiation Technology, Inc. 77/04/01 VOLQENAU.E Office of Inspection & Enforcement, Office of the Director Rpp 22-882 105
- ~~84030B0049 IE insp rept of 710427 initial insp of License 29-13613-01 Noncompliance noted sealed sources not leak tested at required intervals EPSTIM.E., NELBON, P.R. Atomic Energy Commission 71/05/06 5pp 22582 016
- --8403080050 Draft IE Insp Rept 30-07022/77-04 on 771220-22 No violations nated Major areas inspected review of nonroutine procedures for svc irradiator maint following licensee notification of planned shutdown on 771219
 SLOBODIENM J. GLENN.J E. Region 1, Philadelphia, Office of the Director NCLSON,P.R. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 78/01/18 8pp 22582 235
- --B403080051 Discusses 770419 meeting & 770420 telcon Licensee agrees to remove leaking Co-60 sources from storage pool & transfer source to authorized licenses for disposal by 770601 Meeting summary & attendance list encl
 O'REILLY, J P Region 1, Philadelphia, Office of the Director 77/05/05 WELT, M A Radiation Technology, Inc. 4pp. 22582 107
- --8403080054 Discusses insp of License 29-13613-01 on 710427 & forwards notice of violation KIRKMAN,R W Atomic Energy Commission 71/05/07 WELT.M Radiation Technology, Inc. 1p 22582-021
- --8403080055 Ack receipt of 780109 ltr re IE Insp Rept 30-07022/77-06 Clarification provided re comments raised by inspectors. WELT.M A Radiation Technology, Inc 78/01/23 QRIER, B H Region 1, Philadelphia, Office of the Director 4pp 22582 243

- --8403080056 Forwards 1E Insp Rept 30-07022/77-01 on 770527 No violations noted O'REILLY, J P Region i. Philadelphia, Office of the Director 77/06/10 WELT, M A Radiation Technology, Inc 2pp 22582 111
- --8403080058 Notice of violation from insp on 710427 Violation noted Sr-90 sealed sources not tested for leakage &/or removable contamination at 6-month intervals EPSTEIN.E Atomic Energy Commission 71/05/06 ip 22582 022
- --B403080059 Clarifies statements contained in 780118 ltr re repts written following insps in Sept & Oct 1977 Clarifications listed GRIER, B H Region i, Philadelphia, Office of the Director 78/03/20 WELT, M A Radiation Technology, Inc 5pp 22582 247
- --B4030B0060 IE Insp Rept 30-07022/77-01 on 770527 No violations noted Major areas inspected encapsulation of sealed sources, interviews w/personnel.measurements & observations of loading of sources to be sent for reencapsulation OLENN.J Region 1, Philadelphia, Office of the Director 77/06/02 12pp 22882 113
- --8403080064 Responds to NRC 710507 ltr re violations noted in insp of License 29-13613-01 Corrective actions two Sr-70 scaled sources wiped for contamination Wipe samples sent to lab for analysis Removable contamination less than 05 uCi HARAM, S A Radiation Technology, Inc 71/05/14 KIRXMAN, R W Atomic Energy Commission ip 22582 023
- --8403080066 Forwards IE Insp Rept 30-07022/77-02 on 770627-28 No violation noted O'REILLY, J P Region 1. Philadelphia, Office of the Director 77/07/18 WELT, M A Radiation Technology, Inc. 2pp 22582 12:
- ---8403080067 Ack receipt of 710514 ltr informing NRC of steps taken to correct violation noted in insp of License 29-13613-01 on 710427 Corrective actions will be reviewed during next insp KIRKMAN.R W Atomic Energy Commission 71/05/27 HARAM.S A Radiation Technology, Inc. 2pp. 22582 024
- ----B403080070 IE Insp Rept 30-07022/77-02 on 770627-28 No violation noted Major areas inspected disposal of leaking scaled sources, interviews w/personnel, measurements & observations GLENN, J E , MCCLINTOCK, R Region 1, Philadelphia, Office of the Director 77/07/05 5pp 22582 127
- --B4030B0072 Responds to 780123 Itr re inspector access to licensee facilities Difficulties encountered during insp on 771220 Procedure should be developed for inspectors to receive training in order to qualify for unescorted access GRIER, B H Region 1, Philadelphia, Office of the Director 78/03/27 WELT, M A Radiation Technology, Inc. 3pp 22882 252
- --8403080074 Discusses insp of License 29-13613-02 on 720227 % forwards notice of Violation Response requested within 20 days O'REJLLY, J P Region 2. Atlanta, Office of the Director 72/04/12, WELT, M Radiation Technology, Inc ip 22582:026
- --8403080078 Informs of possible misstatement in second paragraph of NRC 780329 ltr re inspector access to licensee facilities NRC suggestion to qualify inspector access w/o escort acceptable WELT, M Region 1, Philadelphia, Office of the Director 2pp. 22582 255
- --B4030B0079 Forwards IE Investigation Rept 30-07022/76-02 on 761022-1104 Violation noted ORIER,B.H Region 1, Philadelphia, Office of the Director. 77/09/14. WELT,M.A. Radiation Technology, Inc. 2pp. 22582 142
- --8403080082 Notice of violation from insp on 720227. Violations noted rept showing results of radiation survey not sent to Matis Branch Matis Licensing Branch & Region I.Div of Compliance within 30 days following installation of sources & Region 2, Atlanta, Office of the Director. 72/04/12 ip 22582 027
- ---B4030B0084 Responds to NRC 7B0320 ltr re issues raised in prior correspondence between ofc & vendor.

 WELT,M A. Radiation Technology, Inc. 7B/04/03 GRIER,B H
 Ragion I, Philadelphia, Office of the Director App 22582 257

- --0403080087 IE Investigation Rept 30-07022/76-02 on 761022-1104 Violations noted two employees carried film inside of biilfolds rather than wearing designed film badge holder & radioactive matl located in unrestricted area SMITH.R H. GLENN.JE. MCCLINTOCK.R D Region 1, Philadelphia. Office of the Director 76/12/13 32pp 22582 144
- --B4030B0069 Responds to NRC 720412 ltr re violations noted in insp of License 29-13613-02 Corrective actions results of radiation survey sent to AEC on 720306 W/o enc! WEIT,M A Radiation Technology, Inc 72/04/18 O'REILLY,J P Atomic Energy Commission ip 22582 028
- ---840308D092 Forwards order immediately suspending license due to overexposure reported on 770927

 VDLGENAU.F Office of Inspection & Enforcement, Office of the Director 77/09/23 WELT.N A Radiation Technology, Inc. ip 22582
- --B4030B0095 Order immediately suspending license Licensee has not taken adequate actions to comply w/Commission rules regulations & license conditions
 VOLOCINAL Office of Inspection & Enforcement, Office of the Director 77/09/23 Radiation Technology, Inc. 4pp 22582 177
- --8403080099 IE Insp Rept 30-07022/77-03 on 770923 & 27 Violations noted overoxposure of one individual to 150-300 rem & failure to evaluate hazarda associated w/operating irradiator w/maze door interlock rendered inoperable NCCLINTOCK-R O. SLOBODIEN-M J. Region I. Philadelphia, Office of the Director NELSON,P R Region I. Philadelphia, Fuel Facility & Haterials Safety Branch 77/10/20 ,16pp 22582 181
- --8403080102 IE Insp Rept 30-07022/77-04 on 771005.07.10 & 14 No violation noted Major areas inspected licenses actions in response to Commission order suspending license & subsequent mode & observation of procedures allowed by order SLORODIEN.M J , KINNEMAN, J D Region 1, Philadelphia, Office of the Director GLERN, J E Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 77/10/21 9pp 22582 197
- --8403080:107 Forwards IE Insp Rept 30-07022/77-05 on 77:1107 & 08 No violation noted GRIBER, B H Region i, Philadelphia, Office of the Director 77/11/22 WELT, M A Radiation Yechnology, Inc. 2pp 22582 206
- ---8403080109 IE Insp Rept 30-07022/77-05 on 771107-08 No violation noted Major areas inspected license actions since lifting of order suspending license on 771014, radiation & contamination surveys & safety review committee actions SLOBODIEN.M J. COSTELLO,F Region I, Philadelphia, Office of the Director NELSON.P R Region I, Philadelphia, Fuel Facility & Materials Safety Granch 77/11/18 4pp 22582 208
- --B4030B0111 Submits results of radiation survey conducted on 710721
 Results listed Results not sent to AEC due to lack of
 radiation detected in vicinity of new installation
 HARAK, 3 A Radiation Technology, Inc 72/03/04 HENDRIX, J
 Atomic Energy Commission 19 22882 029
- --B403080112 Discusses IE insp of License 29-13613-02 on 770923-1014 & forwards notice of violation
 VOLGENAUE Office of Inspection & Enforcement, Office of the Director 77/12/30 WELT.M A Radiation Technology, Inc. 2pp 22582 212
- ~-B4030B0117 Notice of violation from insp on 770P23 & 27 Violations noted individual entered in-air irradiator while nominal 500,000 C1 Co-40 tource exposed & make door interlock rendered inoperable, permitting access to irradiation room * Office of Inspection & Enforcement, Office of the Director 77/12/30 3pp 22582 214
- --8403080121 Ack receipt of 720418 ltr informing NRC of steps taken to correct violations noted in insp of License 29-13613-02 Corrective actions will be verified during next insp Field notes from insp encl O'REILLY, J P Atomic Energy Commission 72/04/25 WELT, M Radiation Technology, Inc. 7pp 22582 030
- --8403080122 Forwards order rescinding order suspending license, in response to 771012 & 13 ltrs. Addl enforcement correspondence re events & Insperior 770723-1014 will be sent VOLGENAU,E Office of Inspection & Enforcement, Office of the Director B3/12/30 WELT, MA Radiation Technology, Inc. 1p 22082:217

- --8403080124 Agrees to meet at mutually convenient time for add) discussion.per 780403 request Meeting on 780321 did not provide adequate basis for negotiating settlement of pending civil penalty case JORDAN.E L. Executive Officer for Operations Support 78/04/11 MELT.M A. Radiation Technology. Inc. 1p 22882 261
- --8403080129 Notice of violation from insp on 741212 Violations noted byproduct mat1 used by unauthorized personnel & water losses in Co-60 storage pools not routinely made up * Region 1, Philadelphia, Office of the Director 75/01/23 ip 22502 039
- --BA03080132 Order rescinding order Suspending license Licensee organized safety review committee & hired new radiation safety officer VOLOCNAU, E Office of Inspection & Enforcement, Office of the Director 77/10/11 Radiation Technology, Inc. App 22582 218
- --8403080133 IE Insp Rept 30-07022/77-01 on 790323 No violation noted Major areas inspected selective exams of procedures & representative records interviews w/personnel.measurements & observations SLO80DIEN.M. COSTELLD, F. Region 1. Philadelphia, Office of the Director 79/03/23 10pp 22582 330
- --8403080134 Responds to NRC 750123 ltr re violations noted in insp of License 29-13613-02 Corrective actions license amend will be requested to specify addl persons as designated operators. HARANS A Radiation Technology. Inc 75/02/14 NELSON,P R Region 1. Philadelphia, Office of the Director Ip 22582 040
- --B403080137 Responds to 771230 ltr re order to suspend license Suspension of license for 3 wks Unjustified Charges of gross lapses of mpt control unsubstantiated WELT, M A Radiation Technology, Inc 70/01/06 VOLGENAU, E Office of Inspection & Enforcement, Office of the Director 3ps 22502: 222
- --8403080139 Ack receipt of 750214 ltr informing NRC of steps taken to correct violations noted in imap of License 29-13613-00 Request for license amend should be expedited NELSON, PR Atomic Energy Commission 75/02/27 WELT, MA Radiation Technology, Inc. 2pp 28982 041
- --8403080144 Discusses IE Insp Repts 30-05458/75-01 & 30-07022/75-01 on 751023 & forwards notice of violation NELSON.FR Region I. Philadelphia, Fuel Facility & Materials Safuty Branch 75/11/11 WELT,M A Radiation Technology, Inc 2pp 22592 043
- --84030B0147 Notice of violation from insp on 761027 & 1101 Violations noted failure to rept 750911 leak test redults to NRC & failure to notify Region I of incident involving cobalt activity in RkD pool Enforcement history encl

 * Office of Inspection & Enforcement, Office of the Director 77/01/05 7pp 22582 073
- -B403080150 Responds to NRC 770105 ltr re violations noted in insp of License 29-13613-02 Corrective actions guidelines proposed for Co-60 concentration in pool water & for training program Civil fine of 44:800 should be withdrawn HELT.M A Radiation Technology, Inc 77/01/31 VOLGENAU,E Office of Inspection & Enforcement, Office of the Director 11pp 22582 080
- -8403080151 Notice of violation from insp on 751023 Violations noted failure to post documents specified in 10CFR19 il & failure to submit annual rept of radiation exposure incurred by personnel during 1974 Data sheet from insp encl
 * Region 1, Philadelphia, Office of the Director 75/11/11 Bpp 22582 045
- 8403080196 Ack receipt of 770131 response to notices of violation & proposed imposition of civil penalties No edequate reasons stated as to why penalties should not be imposed. Apps A & B enc. Add1 response requested.

 VILOENAU.E Office of Inspection & Enforcement. Office of the Director 77/03/14 WELT, M A Radiation Technology, Inc 10gp 22582 091
- 8403080157 Confirms 75:111 telcon between Epstein & 8 Haram re results of ARC analyses of cobalt activity existing in irradiator pool Requests analytical results in writing & action planned to identify source of leakage NELSON.P R Region i, Philadelphia, Fuel Facility & Materials Safety Branch. 75/11/12 HARAM.8 Radiation Technology. Inc Jp 22582 050

- ---8403080159 Notice of violation from insp on 810402.09,21 & 22
 Noncompliance noted operation of sealed source irradiator
 caused radiation levels exceeding 500 rems/h
 MARTIN.T T Division of Engineering & Technical Inspection
 81/07/20 2pp 22582 347
- --8403080160 Order imposing civil monetary penalties in amount of \$4,800 Payment due within 20 days of receipt of order VOLGENAU. E Office of Inspection & Enforcement, Office of the Director 77/03/14 Radiation Technology, Inc. 3pp 22582 101
- --8403080163 Responds to NRC 751111 ltr re violations noted in insp of Licenses 29-13613-01 & 29-13613-02 Corrective actions documents specified in 100FR19 11 posted & annual rept of radiation exposure incurred by personnel submitted MELT,M A Radiation Technology, Inc 75/12/02 NELSON,P R Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 1p 22582 054
- --8403080164 IE Insp Rept 30-07022/81-01 on 810402,09 & 21-22 Violations noted failure to provide exit portal w/device to detect loose sources & operation of irradiator in continuous mode under supervision of unauthorized individual COSTELLO.F, ROWE,C, BHEPHERD.R Region 1, Philadelphia, Office of the Director (81/03/01). 81/07/23 10pp 22382 351
- --8403080167 Advises of progress in handling cobelt activity in R&D pool water Activity traced to improperly weided outer encapsulation of Co-60 source pencil Pool water cleaned up by circulation through demineralizer

 * Radiation Technology, Inc 75/12/03 NELSON, P.R. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch ip 22582 035
- ~-8403080168 Requests hearing re ambiguities in interpretation of License 29-13613-02 & alleged infractions, resulting in proposed tivit penalty HELT, MA Radiation Technology, Inc. 77/04/01 VOLGENAU, E. Office of Inspection & Enforcement, Office of the Director ip 22582 104
- ~-B4030B0172 Responds to NRC 751215 ltr re violation noted in IE Insp Repts 30-0545B/75-01 & 30-07022/75-01 Corrective actions necessary regulations will remain posted & radiation exposure reporting procedures described in exposure logbook WELT, M A Radiation Technology, Inc. 75/12/19 MCCLINTOCK, R D Region 1, Philadelphia, Office of the Director ip 22582-054
- --8403080177 Discusses IE Insp Rept 30-07082/74-01 on 760618 & forwards notice of violation NELSON:P R Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 76/07/02 WELT,M A Radiation Technology. Inc 2pp 22382
- ~-84030B0iB2 Notice of violation from insp on 7404iB Violations noted licensed matls left unattended in unrestricted sample counting area & radiation levels existed in unrestricted sample counting area exceeding safe level Data sheets encl * Region i, Philadelphia, Office of the Director 76/07/02 9pp 22502 059
- ~-8403080185 Responds to NRC 760702 ltr re violations noted in IE Insp Rept 30-07022/76-01 Corrective actions any source utilized for calibr purposes will be signed out of log book MBLT.M A Radiation Technology, Inc. 76/07/12, NELSON.P.R Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 20p 22582.068
- --8403080190 Discusses IE insp of License 29-13613-02 on 761027 & 1101 & forwards notices & violation & proposed imposition of civil penalties

 VOLGENAU,E Office of Inspection & Enforcement, Office of the Director 77/01/05 WELT,M A Radiation Tachnology, Inc 3pp 82582-070
- 640308003Q Partial response to FOIA request for documents re NRC internal procedures or guidance for evaluating new generic requirements & NRC & CRGR procedures for use of cost-benefit or value-impact analysis Forwards App A documents FELTON, J M Division of Rules and Records 84/01/18 WEISS, E R Union of Concerned Scientists 2pp 22584,115.
- 8403080068 Further response to FOIA request for documents re Lixi, Inc. Lixistope of America, Inc & SA Huber Consultants, Inc. Forwards App B documents Documents also available in PDR FELTON, U.M. Division of Rules and Records 84/01/17 CAULK, 9 H Radiation Service Organization 2pp 22584 001
- --8403080098 Ack receipt of 830222 ltr re State of NV reciprocity agreement BOLLING, L A Diffice of State Programs, Director 83/03/03 SAVINI, R J LIXI, Inc ip 22584 013

- --8403080117 Forwards, to Agreement States, proposed rule establishing new category to Group VI of 10CFR35 100 for 1-125 as sealed source in portable device for bone imaging & foreign body detection Change permits use of Lixiscope W/o encl NUBSBAUMER, D A Assistant Director for State Agreements Programs 83/04/07 Affiliation Not Assigned 1p 22584 014
- --8403080128 Forwards, to Agreement States, ltr to Lixi re demonstration & industrial training in use of Lixiscope device Ltr requests clarifying informot final licensing action M/o encl NUSBBAUMER, D A Assistant Director for Btate Agreements Programs 83/06/28 Affiliation Not Assigned 1p 22584 015
- --840308013B Forwards NMSS policy to Agreement States re licensing human use of Lixiscope & bone matl analyzer Byproduct matl authorized for human use by nonphysicians (podiatrists & dentists)
 NUSSBAUMER, D A Assistant Director for State Agreements Programs 83/11/18 Affiliation Not Assigned ip 22584 016
- --8403080146 Submits policy & guidance directive re licensing Lixiscope & bone mineral analyzer for human use CUNNINGHAM.R E Division of Fuel Cycle & Material Safety 83/11/10 Region i. Office of Director 4pp 22584 017
- --B403080155 Discusses use of Lixiscope by podiatrists & dentists NRC will assume podiatrists & dentists not physicians & consider whether exemption per 10CFR30 il could be granted MILLER. V L. Division of Fuel Cycle & Material Safety B3/11/07 CUNNINGHAM.R E Division of Fuel Cycle & Material Safety 2pp
- --8403080165 Forwards IE Insp Repts 30-14668/83-01 & 30-17164/83-01 in Jan 1983 re possession & demonstration of Lixiscope JOYNER, J H. Region 1, Dffice of Director B3/06/17 MILLER, J R Region 3, Dffice of Director 2pp 22884 023
- --8403080173 IE Insp Repts 30-14648/83-01 & 30-19164/83-01 in Jan 1983 Violation noted Liriscope Models LSM-82 & 82-209 possessed &/pr used by unauthorized licensee DARDEN.T H. KINNEMAN. J D Region 1. Office of Director 30-19164/83-01 83/06/16 35pp 22584 025
- --8403080181 Requests info re Lixiscope licensing concerning number of hours & which topics to be covered in training of physicians not meeting Group VI criteria
 NUSSBAUMER, D.A. Assistant Director for State Agreements Programs
 83/09/09 MILLER, V.L. Division of Fuel Cycle & Material Safety
 1p 22584 060
- --B4030B01B9 Requests investigation of activities of Jessco Medical Supply Co to determine type of Lixiscopes in possession & when device received & whether company in compliance w/state regulations
 KINNEMAN, J D Region 1, Office of Director 83/11/23
 BRADLEY, F J Labor, Dept of 1p 22584 061
- B4030B00B5 FDIA request for SER & SSER 21 (NUREG-0675) re operation of facilities
 OARDE, B P Government Accountability Project 84/01/09. Office of Administration 2pp 22584'074 24X Fiche 50-275,84/01/09, B4030B00B5
- B40G0B0076 Partial response to FOIA request for SER re operation of facilities Forwards documents listed on app Documents also placed in PDR Review of remaining documents continuing FELTON, J M Division of Rules and Records 84/01/23 GARDE, B P Government Accountability Project. 2pp 22984 076 24X Fiche 50-275. B4/01/23, B40G0B0076.
- ---B4030B0103 Allegations 51 & 52 re NRC concern that plant personnel reluctant to come forward w/safety concerns since candor endangers Jobs * NRC No Detailed Affiliation Given. B4/01/23 2pp 22584.089 24% Fiche 50-275,84/01/23,84030B0096
- 8403080126 Further response to FOIA request for licenses & current ref supporting documents for companies & individuals licensed to perform radiation detection instrument calibr Fowards App A documents Portions deleted (ref FOIA Exemption 6) FELTON, J M Division of Rules and Records 84/03/01 MIKOWSKI, J Standard Nuclear Consultants, Ltd 2pp 22567 219
- --7904030132 Forwards application for renewal of Matl/Byproduct License 12-09160-01 Filing fee encl.
 RIVKIN.W B Health Physics Associates. Ltd 9898 79/02/2B
 Radioisotopes Licensing Branch (Pre 790501) 1p 22367 221

- --7904030135 Application for renewal of Matl/Hyproduct License
 12-09160-01 for use of licensed matls in analysis of leak
 test samples, calibr of radiation survey instruments,
 preparation of std solutions & possession of sources
 RIVAIN.W B Mpalth Physics Associates, Ltd 98998 79/02/28
 22p 22567 222
- --8101300020 Forwards application for renewal of Matl/Byproduct License 34-16779-01 CALLENDINE.O W Callendine, GW 04119 80/11/17 COOPER,J Region 3. Chicago, Office of the Diractor 1p 22567 278
- --8101300025 Application for renewal of Matl/Dyproduct License 34-16779-01 authorizing use of Sr-90.Cs-137.Co-60 & Ba-133 sealed source for test purposes to callbr radiation survey & measuring instruments CALLENDINE.G W Callending, 9 W 04119 80/11/17 2pp 32867-279
- --B4030B0149 Application for matl/byproduct license, authorizing CC Lu.
 RA Carlson, JE Carey, J Colvin, W Hack & T Mason to use &/or
 supervise use of Cs-137 sealed source in calibr of survey
 meters
 CARLEON, R A Medical Physics Consultants, Inc 81/04/20 17pp
 22547 244
- --84030B0154 Forwards addl info requested by NRC B01115 ltr re renewal of License 34-16272-01 Quarterly inventory of all sources will be maintained FERRELL, JR Nuclear Medicine Associates, Inc. 01998 61/01/09 COOPER, JW Region 3, Chicago, Office of the Director (81/03/01) 16pp 22567 261
- 8403080179 Fourth partial response to FOIA request for six categories of documents re facilities Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of addl documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, S I Gervey, Schubert, Adams & Barer 7pp 22583 226 24X Fichs 30-000,84/02/13.8403080179
- --8001140316 Notifies that NRC has amended regulations re implementation of resident insp program Expresses gratitude for assistance rendered Forwards final rule W/o encl
 STELLO. V Office of Inspection & Enforcement, Office of the Director 79/11/19 O'STRAND.N Washington Public Power Supply System 1p 22583 234 24% Fiche 50-000, 84/02/13, 8403080179
- --8003240202 Submits review costs for facilities Hearing was uncontested Billing procedure may be completed BERKOW. H N Office of Nuclear Reactor Regulation. Director 80/02/22 MILLER, W O License Fee Management Branch 1p 22583 242 24X Fiche 50-000.84/02/13.8403080179
- --8003240207 Forwards IE cost data worksheets for facilities No costs relected for licenses contractor vendor insprepts COBB.L I Executive Officer for Management & Analysis 79/01/29 MILLER.W O License Fee Management Dranch 3pp 22583 243 24X Fiche 50-000,84/02/13,8403080179
- --8003240219 Corrects 781028 memo re WPP88 3 % 5 being contested Memo reflecting actual ASLB time spent on case encl FITTI.C V Atomic Eafety and Licensing Board Panel 80/02/28 HOLLOWAY.C J License Fee Management Branch 1p 22583 248 24X Fiche 50-000.84/02/13.8403080179
- ---BO03240222 Submits rept of time spent since program initiated on WPPSS 3 & 5 Professional time all spent on post-hearing work reparding CP hearing LAZO,R M Atomic Safety and Licensing Board Panel 78/04/11 FITTI.C J Atomic Safety and Licensing Board Panel 3pp 22893 249 24% Fiche 50-000-84/02/13.8403080179
- --8003250477 Forwards hydrologic engineering questions re proposed waste treatment sys Response will supply necessary info re design basis for seepage & flooding Also forwards generic questions re floodplains Info will assist NRC environ review SELLS.D E Environmental Projects Branch 2 80/03/07 RENBERGER, D. L Washington Public Power Supply System 5pp 22583 253 24X Fiche 50-000,84/02/13,8403080179
- --8003270142 Discusses suspension of facility preoperational aquatic monitoring program Suspension approved Operational monitoring program results should not be affected by suspension SAMWURTH, R.B. Environmental Specialists Branch 80/02/29 SELLS, D.E. Chvironmental Projects Branch 2 2pp 22583 239, 24X Fiche 50-000,84/02/13,8403080179

- --8005130793 Provides status of BER inputs & acceptance reviews for OL & CP applications Schedule should be met BURKE, W C Effluent Treatment Systems Branch 80/02/06 KREGER, W E Assistant Director for Site Analysis 1p 22583 235 24X Fiche 50-000,84/02/13,8403080179
- --BOO5150677 Forwards R Ontchy review of JJ Onffman article re radiation causation of cancer in Hanford workers No new or significant info presented KREGER. H E Assistant Director for Site Analysis 80/02/07 St.AGGIE.L Office of the General Counsel ip 22883 236
- --B005150683 Reviews JH Gofman Nov 1979 article per 791226 request Analysis statistically weak Results fall within BEIR rept risk estimates NIH B00310 & 11 conference will discuss low-level ionizing radiation biological effects GDTCHY.R Division of Site Safety & Environmental Analysis B0/02/01 NURPHY, T Radiological Assessment Branch 2pp D2568 2017
- --8009090737 Forwards airworthiness alert te currosive & abrasive characteristics of volcanic ash which has fallen in Pacific Northwest Questions re ash amount, chemistry & size distribution will be forwarded to licensees W/o encl JACKSON, R E Geosciences Branch 80/06/12 VOLLMER, R H Division of Engineering 2pp 22583 258 24X Fiche 50-000,84/02/13,8403080179
- ---B009110203 Responds to B00702 ltr re E Borhek concern about ultimate responsibility for civil penaltites proposed against util Civil penalties are imposed as enforcement action. State agencies should be contacted re responsibility for payment DIRCKS.W J Diffice of the Executive Director for Operations B0/08/26 JACKBON.H M Senate 4pp 22583 260 24X Fichs 50-000.84/02/13.8403080179
- --B010070260 Discusses review of applicant B00B14 request for approval of proposal to substitute in-plant tests w/scale model recirculation sump tests Response to requests deferred pending NRC review of program
 SPEIS.1 Reactor Systems Branch B0/09/26 Y0UNGBLOOD, B J Licensing Branch 1 lp 22583 266 24X Fiche 50-000,84/02/13. B403080179
- --8012160851 Forwards 800625 ltr from constituent E Borhek for response Requests that duplicate rept be forwarded to 802 United States Courthouse. Beattle, MA 78104 JACKSIM, H M Senate. Energy & Natural Resources 80/07/21. KAMHERER, C. C. Office of Congressional Affairs 2pp 22583 264 24X Fichs. 50-000.84/02/13.8403080179.
- --B101060767 Notifies of findings of possible capable fault near facility JACKSON.R E Geosciences Branch B0/10/27 R0USE,L C Advanced Fuel & Spent Fuel Licensing Branch 1p 22383 267 24X Fiche 50-000,84/02/13,8403080179
- ---BiOli30363 Responds to 1tr forwarding M Hamilton concerns re facilities CPs issued in Apr 1978 after safety & environ reviews & ASLB public hearings Public hearings may be requested when util applies for OLs KAMMERER, C Office of Congressional Affairs 80/12/16 MAGNUSON, M Senate 1p 22583 271 24X Fiche. 50-000, 84/02/13, 8403080179
- --BiO2200029 Forwards action plan for resolution of non-TMI issues for pending CP/mfg license applications, per Ofc of Nuclear Reactor Regulation approach to resumption of licensing.

 Safety evaluation inputs should be provided by 810601

 EIBENHUT, D G Division of Licensing 80/12/31 VOLLMER, R

 Division of Engineering. 1p 22583 277 24X

 Fiche 50-000,84/02/13,8403080179
- --Bi03040052 Forwards short & long-term OL & CP review schedules, in response to 801216 meeting w/US98 List of OL plant reviews for which NRC tentatively plans to seek US98 assistance is provided JACKBON.R E Geosciences Branch NRC-03-80-113 81/01/21. DEVINE, J F Interior, Dept of, Geological Survey 5pp 22583, 272. 24X Fiche 50-000, 84/02/13, 8403080179
- --8:04820329 Concludes that Table 3.2-2 of PSAR, re safety-related structures; sys & components, is incomplete from Geotechnical Engineering Branch viewpoint LEAR, G E. Hydrologic & Geotechnical Engineering Branch 6:/04/08 HAASB, M.P. Quality Assurance Branch. 2pp 22583:278 24X Fiche 50-000,84/02/13.8403880179.
- -8104300020 Responds to 810414 memo re util request for clarification in use of ABME code cases Util use of code cases w/a prior NRC approval is inadvisable due to potential hardship for user BOSNAK.R J. Hechanical Engineering Branch. 81/04/21. YOUNGBLOOD.B. J. Licensing Branch 1 ip 22883 280 24X Fichs 50-000, 84/02/12, 8403080179.

Blue X

- --BI03010554 Advises that Mechanical Engineering Branch completed review of util request for authorization to use ABME Code Cases N-217 & N-287 for application in design of concrete containments Code cases acceptable (NT9HT.JP Assistant Director for Comp & Structures Engineering (Pre 830201) B1/04/27 TEDESCO.R L Assistant Director for Licensing 1p 22583 281 24% Fiche 50-000.84/02/13.8403080179
- --B105140106 Advises that info provided on S10213 & 0403 re air intake arrangements for diesel generators reviewed Diesel generator combustion air supply arrangement meets acceptance criteria in Section II of SRP a 5 B Sys acceptable as designed UNGARD, A R Power Systems Branch B1/05/01 YOUNGBLOOD, B J Licensing Branch i lp 22583 282 24X Fiche 50-000, 84/02/13, 8403080179
- --8105180436 Forwards ltr from util requesting concurrence by NRC to amit Subsections 2 5 1-2 5.3 of FSAR Review & comments requested by 810622 ADENSAM, E.g. Assistant Director for Licensing 81/05/12 JACKSON, R.E. Geosciences Branch ip 22583 283 24X Fiche 50-000,84/02/13,8403080179.
- --8105210109 Concurs w/licensee proposal to ref Sections 2 5.1-2 5 1-2.5 3 of WPPB-2 FSAR in WPPB-1/4 FSAR since both projects Jocated in close proximity Mods listed JACKBON, R E Geosciences Branch 81/05/15 ADENBAM, E. Q Licensing Branch 4 2pp 22583 286 24% Fiche. 50-000, 84/02/13, 8403080179
- --8106170138 Forwards results of branch review of EPRI/PWR test, per 810602 memo MIRAGLIA.F J Licensing Branch 3. 81/06/12 TEDESCO, R L Assistant Director for Licensing 1p. 22383:288
- ~-B106220066 Requests that appropriate comments re Cycle 2 evaluations, per Eisenhut 810604 memo, be submitted by 810623 MIRAGLIA, F. J. Licensing Branch 3 81/06/18 HAASB, W. S. Guality Assurance Branch 1p 22583 291 24% Fiche. 50-000, 84/02/13, 8403080179
- --Bi071305B1 Forwards info re impact of Mount St Helens eruptions on facilities, for use by SALP review board Comments prepared by HE Lefevne, geologist. JACKBON, R.E. Geosciences Branch 81/06/23 MIRACLIA, F.J. Licensing Branch 3 2pp 225B3:293 24X Fiche, 50-000, 84/02/13, 84030B0179
- --Bi07140185 Forwards Ofc of Nuclear Reactor Regulation performance evaluation in compliance w/Bi0604 memo re systematic assessment of licensee performance Cycle 2. Notifies that review board meeting for facility scheduled for Bi0723 WHEELER, L. Licensing Branch 3 81/06/30, EISENHUT, D. C. Division of Licensing ip 22583 275 24X Fichs 50-000, 84/02/13, 8403080179.
- --Bio7i40192 Forwards Geosciences Branch input for use by facility systematic assessment of licensee performance review board, per Bio6iB request JACKSON.R E Geosciences Branch. 81/06/23. MIRAGLIA.F J. Licensing Branch 3. 3pp 2298 24X Fiche, 50-000. 84/02/13. 8403080179
- ---8107270274 Accepts use of ABME Code Case N-242-1 dtd 890410 for application in const of pipe support frames in pipe chases located in two lower elevations of reactor auxiliary bldg. Conditions of use discussed KNIOHT.J.P. Assistant Director for Comp & Structures Engineering (Pre 830201) 81/07/21. TEDESCD.R L. Assistant Director for Licensing 1p 22583.301. 24X Fiche: 80-000,84/02/13,8403080179
- --B107280171 Notification of B10729 meeting w/util & B&W in Bethesda, MD to discuss method util intends to use to fulfill requirments of NUREQ-0737 Item II F 2 (inadequate core cooling instrumentation)
 HERNAN.R W Licensing Branch 4 91/07/21 ADENSAM.E Q Licensing Branch 4 2pp. 22583-305. 24X Fiche-50-000, 84/02/13, 8403080179.
- ---SigBli0038 Notification of Bi0820 meeting w/util in Bethesds, MD to discuss proposed independent design review programs, HERNAN, R.W. Licensing Branch 4 Bi/07/30, ADENBAM, E. G. Licensing Branch 4 3pp 22583 302, 24X Fiche: 50-000, B4/02/13, B403080179
- --8i10080612 Discusses proposal to use IDRs in licensing process, IDRs may be useful in certain greas, but clarification of role needed. TEDESCO.R.L. Assistant Director for Licensing 81/09/23. EIBENHUT, D 9. Division of Licensing 1p. 22583 307. 24X Fiche 50-000, 84/02/13, 8403080179.

- --Bi10170026 Requests that comparison of fire protection program to App R of 10CFR50 be included in overall fire protection program submittal W/o encl FR notice EIBENHUT,D Q Division of Licensing B1/07/30 FERGUSON,R L Washington Public Power Supply System 2pp 22583 308 24X Fiche 50-000,84/02/13.8403080179
- ---8111060697 Notifies of util intention of sending technical team to present FSAR to review staff during wk of 811130 Reviewers should complete attached form & confirm attendance HERNAN,R W Licensing Branch 4 81/10/23. Licensing Branch 4 4pp 22583,311 24X Fichs 50-000.84/02/13.8403080179
- --8111120935 Forwards form which identifies Power Sys Branch electrical & mechanical reviewers for project in accordance w/81023 memo Requests established review schedule dates when available
 UNCARG, A Power Systems Branch 81/11/02 HERNAN, R W Licensing Branch 4 2pp 22583 316 24X Fiche 50-000.84/02/13.8403080179
- ---Bilili30007 Submits names of D Gupa & G Stalley as technical reviewers for facility FBAR per Bil023 memo LEAR, G. Hydrologic & Geotechnical Engineering Branch Bi/10/30 ADENSAM, E. Licensing Branch 4 1p 22583 315 24X Fiche 50-000,84/02/13,8403080179
- --8111200219 Informs of receipt of telcon from Yakamar Indian Nation requesting that tribe be given full rights in facilities proceedings.

 TEDESCO, R L. Assistant Director for Licensing 81/10/21.

 KETCHEN, E. Heerings Division. 1p. 22583 310 24X

 Fiche: 50-000, 84/02/13.8403380179
- --B112300305 Notification of B11211 meeting w/util in Bethesda.MD to discuss FBAR w/technical review staff at time DL application is tendered.

 HERNAN, R.W. Licensing Branch 4 81/11/23 ADENSAM. E. 0
 Licensing Branch 4. 3pp 22583 318 24X Fiche 50-000, 84/02/13, 8403080179
- --B201190297 Forwards Central Files version of "Description of Early Warning Bys for WPP88 Nuclear Plants 1, 2 & 4," in response to NRC 810720 ltr re prompt notification in event of emergency. Sys will be in place prior to OL issuance BOUCHEY, 0 D Washington Public Power Bupply System 62/01/11 TEDESCO, R L Assistant Director for Licensing ip 22583 321 24X Fichs. 50-000. 84/02/13. 8403080179
- --8202180456 Requests that Fire Protection Section perform acceptance level review of facilities' revised fire protection program prior to docketing of DL application Util aware that App R to 100FR50 will apply.

 ADENSAM, E. G. Licensing Branch 4 82/01/27. BENAROYA, V Chemical Engineering Branch. 1p 22583 322 24X Fiche 30-000,84/02/13,8403080179
- --8202260171 Requests assistance in performing acceptance review of environ rept for OL application Only portions applicable to Unit 1 need be considered since Unit 4 cancelled on 820122 ADENSAM, E 0 Licensing Branch 4 82/02/10 JACKSON, R. E 9805Ciences Branch. 1p 22583 324 24X Fiche 50-000,84/02/13,840000178.
- --8203020139 Advises that listed info needed to perform acceptance review of fire protection program for conformance w/NUREG-0800, Section 9 5-1 BENAROYA, V Chemical Engineering Branch. 82/02/09 ADENSAM, E G Licensing Branch 4 ip 22583.323 24X Fiche 50-000,84/02/13,8403080179
- ---8203100570 Recommends environ rept be accepted. Add1 questions re external appearance, plant layout & socioeconomics of single unit operation will be submitted. REGAN, M. H. Biting Analysis Branch. 82/02/25 ADENSAM. E Q Licensing Branch 4 ip 22583 328, 24X Fiche: 50-000, 84/02/13, 8403080179
- --8203150028 Forwards add1 info requirements for review of ER for OL application per 820210 request.

 BALLARD,R.L. Environmental Engineering Branch 82/03/02.

 ADENBAM,E 0, Licensing Branch 4. 3pp. 22583,329 24X

 Fiche, 50-000,84/02/13,8403080179

- ---8203180004 Advises that environ rept is acceptable re radiological impacts
 HOUSTON,R W Assistant Director for Radiation Protection
 82/03/02 TEDESCO.R L Assistant Director for Licensing ip
 82583 332 24% Fishe 50-000,84/02/13.840308017
- --B2031B0110 Forwards two relevant documents for FOIA request re WPPSS & Exxon Litigation MIRAULIAF J Licensing Branch 3 82/03/08 WILBON,V H Management Analysis Branch 3pp 22923 333 24X Fiche 50-000.84/02/13.8403080179
- --B204090099 Informs that sufficient info provided to begin meteorology review inappropriate models & diffusion parameters used in Section 6 1 3 2 & accident evaluations HULMAN, L G Accident Evaluation Branch B2/03/16 ADENSAM, E Licensing Branch 4 2pp 225B3 336 24X Fiche 50-000, 84/02/13, 8403080179
- --8204270457 Notification of 820511 meeting w/util to discuss review process & preliminary identification of any possible unique features
 WHEELER, L. Licensing Branch 3 82/04/22 MIRAGLIA, F., J. Licensing Branch 3 1p. 22583 340 24% Fiche 50-000, 84/02/13, 240730178
- --B2050700B8 Forwards list of sys to be added to G-list Sys provides ongoing knowledge of changes in rediation environ & ability to deal effectively w/wnusually high radiation & radioactivity levels
 CONSEL.F J Radiological Assessment Branch 82/03/23 HAASS, W.P. Guality Assurance Branch 2pp 22583 338 24X
 Fithe 50-000, 84/02/13, 8403080179
- --B206300082 Lists info not yet addressed for OL application Recommends general info be accepted for docketing LEE,I J Licensing Branch 3 82/06/18 WHEELER,L.L Licensing Branch 3 ip 22583 347 24X Fiche 50-000.84/02/13,8403080179
- --B20B120240 Forwards Central Files version of revised page to Revision 2 of emergency plan adding local fire depts within 20 miles of facility to backup fire protection svcs
 BDUCHEY, 0 D Hashington Public Power Bupply System CD2-82-642
 B2/08/05 SCHENCER, A Licensing Branch 2 2pp 22583 348 24X
 Fiche 50-000, 84/02/13.8403080179
- --8208120248 Central Files version of revised page to Revision 2 of emergency plan re provision of backup fire protection syc5 * Washington Public Power Supply System 82/08/05 ip 22883 350 24X Fiche 50-000,84/02/13,8403080179
- --8209280165 Forwards Cycle 3 systematic appraisal of licensee performance input for BIO701 through 820730 in response to Region 5 820625 request Strong mgt evident Resolution of technical issues, responsiveness & staffing satisfactory HERNAN, R W Licensing Branch 4, 82/09/15 EIGEN-UT, D G Division of Licensing App 22583 351 24X Fiche: 50-000, 84/02/13:840380179
- --8212070382 Ack receipt of 821109 ltr re Target Rock environ qualification testing program Info re valve upgrade & retest anticipated HEISHMAN.R F Division of Reactor Programs (Pre 830103). 82/12/01 BDUCHEY.O D Washington Public Power Supply System 1p 22563 357, 24% Fiche 50-000.84/02/13.8403080179
- --8303100476 Forwards util B30223 submittel in response to telcon during which remaining Phase I open items of "Control of Heavy Loads -- Case Reviews," were discussed W/o encl CLEMENBON, F. Auxiliary Systems Branch NRC-20-18-388 83/02/28 STICKLEY, TH EG&G, Inc. 19 22583 360 24X Fiche 30-000, 84/02/13, 8403080179
- --8304060977 Requests search for documents re govt litigation w/util on five specific issues
 8LAGGIE, E.L. Office of the General Counsel 83/03/23
 DIRKNE, W.J. Office of the Executive Director for Operations ip 22583.361. 24X Fiche 50-000.84/02/13.8403080179.
- --8304070113 Recommends that radiation exposure records be retained for i yr prior to disposal Ref Murphy to Varga 801222 CONGEL, F.J. Radiological Assessment Branch 83/04/01 SCHMENCER, A Licenstry Branch 2. ip. 22583,327 24X Fiche 50-000,84/02/13,8403080179
- --8403080253 Forwards summary of review costs & supporting documentation from program ofts M/o encl
 HOLLOHAY,C.J. License Fee Management Branch. 80/03/03 License
 Fee Management Branch. 1p 22583 241 24X Fiche 50-000.84/02/13.
 8403080179

- 8403080196 FDIA request for documents re WR McAfee allegations involving facility from Mar 1977 Mar 1979.NRC open conference at site in Nov 1979 & review of util topical GA manual GARDE.B P., ANSELL.E. Government Accountability Project 83/11/21 Office of Administration 2pp 22584 162 24X Fiche 50-419.83/11/21.8403080196
- B402080200 F01A request for 2 categories of documents to NRC correspondence w/Lizi.inc & 5A Huber Consultants WIESELMAN,K LIXI. inc & 93/11/22 MILLER.V L Division of Fuel Cycle & Material Safety ip 22567 208
- B4030B02D3 Responds to FDIA request for documents from Mar 1977 Mar 1977 re HR McAfee allegations Forwards App A documents. Info also available in PDR FELTON, J M Division of Rules and Records 84/01/24 GARDE, B. P Obvernment Accountability Project. 2pp 225B4 164 24% Fichs 50-413,84/01/24,84030B0203
- --B403080212 Discusses 791113-16 interviews w/craftsmen Interviewers selected by principal inspector.per TI 2512/4 criteria. Related info encl MURPHY.C E Region 3. Chicago, Reactor Construction & Engineering Support Branch 79/12/04 THORNBURG.H D Director's Office, Office of Inspection and Enforcement. 9pp. 22584 166. 24X Fiche 50-413,84/01/24,8403080203
- B4030B0207 Responds to FDIA request for NRC correspondence w/Lixi,Inc & BA Huber Consultants Forwards documents listed on app Documents also available in FDR FELTON,J M Division of Rules and Records, 84/01/23 WIESELMAN,K LIXI, Inc 3pp 22567 209
- --7906250470 Comments on proposed Reg Guide 10 B 100 dpm limit seems very arbitrary & requires calculations to relate to individual equipment Strict application of reg guides should be avaided
 - WUBER, S A · Stan A Huber Consultants, Inc 79/02/08 Docksting & Services Branch 2PP 22567 212.
- --B403080218 Advises that 830128 memo requiring Lixiscope evaluation to include public comment period contradicts advice given at 821013 meeting Comment period will unreasonably delay license issuance & cause financial loss 8AVINI.R J. LIXI. Inc. 83/02/24 OLMSTEAD.W. Office of the Executive Legal Director 2pp 22567 214
- --8403080225 Responds to 830224 request for reconsideration of advice re public comment on proposed rule concerning addition of Lisiscope to list of devices in 100FR33 100 Public comment unnecessary for issuance of Liziscope license OLMSTEAD, H.J. Office of the Executive Legal Director, 83/03/30 SAVINI, R.J. LIXI, Inc. 3pp 22367 216
- 8403080219 Partial response to FOIA request for two categories of documents re PWR RCS & specified insp repts Document available in PDR Search for addl documents continuing FELTON.J H Division of Rules and Records 84/07/25. MADDEN.T J Kaye, Scholer, Fierman, Hays & Handler 2pp 22584.182
- 8403080226 FOIA request for two categories of documents re PMR RCS & specified insprepts MADDEN.T.J. Kays. Scholer, Fierman, Hays & Handler 83/12/12. NORRY, P.O. Office of Administration 2pp. 22584, 184
- 8403080324 FOIA request for documents considered by NRC in preparation of notice of violation & proposed imposition of civil penalty.831222 ltr transmitting violation & rept of investigation re intimidation of GA personnel HARTMAN, S.L. Debevoise & Liberman 83/12/30 FELTON, J. M. Division of Rules and Records 2pp 22583 169. 24X Fiche 50~445.83/12/30.8403080324
- 8403080325 Partial response to FOIA request for documents considered by NRG in preparation of three categories of documents concerning facilities Forwards documents listed on App A. FELTON, J H Division of Rules and Records 84/01/20. MARTMAN.S.L. Bebevoise & Liberman 2pp 22583:171, 24X Fiche 50-445.84/01/20. 840308325
- --84030B0327 Rev 27 to Procedure &I-GP-ii 4-5 re visual defects insp & dry film thickness Related info encl * Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 83/11/08 4pp. 22583.173. 24X Fiche 50-445.84/01/20.8403080325

- --B403080332 Describes commitments made to NRC in RJ Gary 830928 response to notice of violation & proposed imposition of civil penalty CLEMENTS, B R. Texas Utilities Electric Co (formerly Texas Utilities Generating Co). EA-83-064 83/11/29 COLLINS, J T Region 4, Defice of Director 11pp 22583 182 24X Fiche 50-445,84/01/20,8403080325
- --8403080333 Notification of significant licensee meeting on 831212 w/
 util in Arlington.TX to discuss potential enforcement action
 re intimidation of employees by H Williams
 * Region 4, Office of Director 8312708, Region 4, Office of
 Director ip 22583 193 24X Fiche 50-445.84/01/20.8403080325
- --8403080333 Forwards rept re investigation into allegations made by WA Dunham & concerns related to protective coatings Related documents encl GARYR J Taxas Utilities Electric Co (formerly Texas Utilities Generating Co) TXX-4087 83/12/13 COLLINS, J Region 4, Office of Director 22pp 22583 204 24X Fiche 50-445,84/01/20,8403080325
- 8403080339 Finel response to FOIA request for documents re NRC investigation of industrial accident involving burst steam pips at facility "VEPCO Investigative Board Preliminary Rept" on accident placed in FDR FELTON, J M. Division of Rules and Records 84/01/20 OARDE, B P. Government Accountability Project ip 22376-214 24X Fiche 50-280, 84/01/20, 8403080339
- --8403080341 "VEPCO Investigative Board Preliminary Rept." W/o cover sheet * Virginia Electric & Power Co 84/01/20 29pp 22576-215 24X Fiche-50-280,84/01/20,8403080339
- 8403080344 FOIA request for documents re proposed NSHC determination on license, amends for Millstone 2 & entry into operational mode for conducting final tests of pressurizer safety valves at Trojan
 ADATO, M. Union of Concerned Scientists 84/02/02 FELTON, J. M. Division of Rules and Records 1p 22583 038. 24X
 Fiche 50-000, 84/02/02, 8403080344
- B403080344 Appeals denial of FOIA request for "Borssele Rept " Rept discussed in Board Notification BN-83-151, "Westinghouse ECCS Actuation Logic"
 WEISSLER Union of Concerned Scientists. 84/01/05 DIRCKE,W J Office of the Executive Director for Operations 3pp. 22567:288
- 8403080347 Partial response to FOIA request for documents re proposed NSHC determinations for Millstone 2 & entry into operational mode for conducting final tests of pressurizer safety valves at Trojan Forwards App 8 documents
 FELTON.J.M Division of Rules and Records 84/03/02 ADATO, M Union of Concerned Scientists 4pp 22583 039 24X
 Fiche 50-000,84/03/02,8403080347
- --8307180403 Initial NSHC determination & noticing action re util 630524 application to amend License NPF-1.clarifying purpose of auxiliary hoist & testing of hoist & manipulator crane.
 TRAMMELL.C. NRC No Detailed Affiliation Given 83/06/27 2pp 22583 043 24X Fichs 50-000,84/03/02.8403080347.
- --B307180414 Requests FR publication of notice of consideration of issuance of amend to License NPF-1 & proposed NBHC determination & opportunity for hearing re 830324 request to heat up to hot standby mode CLARK, R. A Operating Reactors Branch 3 83/07/06, KREUTZER, PM Operating Reactors Branch 3 83/07/06, KREUTZER, PM Ficher 50-000, 84/03/02, 8403080347
- --8312230261 Evaluates util 831102 arguments to support validity of previous LUCA analyses for removal of thermal shield from core barrel Resensiysis of small break LUCAs not required Restart approved subj to confirmation of peak clad temp HDUSTONIR W Assistant Director for Resector Safety. TAC 51969 83/12/13 LAIMAB. O.C. Assistant Director for Operating Resectors. 2pp 22583.060. 24X Fiche 50-000.84/03/02.8403080347.
- --8403080352 Returns request for publication in FR of notice of consideration of issuance of amend to OL & proposed NSHC determination re Tech Bpec changes resulting from Cycle 6 refueling considerations Revs requested M/o encl. ROTHSCHILD.M.U. Office of the Executive Legal Director. 83/06/13 CLARK.R A Operating Reactors Branch 3 1p 22583 059, 24X Fiche. 50-000, 84/03/02, 8403080347.
- 8403080350 Responds to 831018 & 1201 requests for "Borssele Rept."
 "Borssele Rept" submitted in confidence to Commission by
 foreign source & exempt from public disclosure per
 10CFR2. 770

 DENTON: H R Defice of Nuclear Reactor Regulation, Director
 83/12/22 POLLARD.R. Union of Concerned Scientists 1p
 82/12/22 POLLARD.R.

- 8403080354 Requests assistance in obtaining reply to 831018 ltr to D Eisenhut requesting "Borssele Rept" POLLARD, R D Union of Concerned Scientists 83/12/01 DIRCKS, W J Office of the Executive Director for Operations. 1p 22567 293
- 8403080357 Responds to appeal we denial of FDIA request for "Borssele Rept" Forwards two repts on Borssele Nuclear Power Station FELTON, J M Division of Rules and Records 84/01/17 WEIGB.E R Union of Concerned Scientists 1p 22567 294
- --B4030B0360 Forwards two repts, "Steam Generator Tube Rupture Procedure at Borssele Nuclear Power Station" & "Natural Circulation & Heat Transfer Tests in Dorssele Nuclear Power Plant "
 VAN DAATSELAAR Natherlands, Govt of B3/08/02 LAFLEUR, J D
 Office of International Programs, Director. 19 22567 295
- --8403080364 "Steam Generator Tube Rupture Procedure at Borssele Nuclear Power Station, Implementation of Lessons From TMI, DOEL & Ginna "
 - VAY881ER, Q Netherlands, Govt of 93/06/30 17pp 22567-296
- --8403060366 "Natural Circulation & Heat Transfer Tests in Borssele Nuclear Power Plant " KALVERBOER.C Netherlands, Govt of. 83/07/11 18pp 22567 312
- --8403080364 "Steam Generator Tube Rupture Procedure at Borssele Nuclear Power Station, Implementation of Lessons From TMI, DOEL & Ginna "VAYBBIER, G. Natherlands, Govt of. 83/06/30 17pp 22567 296
- ---8403080366 "Natural Circulation & Heat Transfer Tests in Borssele Nuclear Fower Plant." KALVERBOER, C. Netherlands, Govt of 83/07/11 1808 22567 312
- 8403080363 FDIA request for documents re BWR Intergranular Stress Corrosion Cracking Guners Group meeting on or about 811028 HAFNERS B. Suffolk Nuclear Study Group. 83/11/26 Office of Administration 1p 22583 007. 24X Fiche 50-322,83/11/26,
- 8403080367 Responds to FOIA request for documents re BHR Integranular Stress Corrosion Cracking Dwners Group meeting on or about 811028, Forwards App A documents, Records also in PDR FELTON, J. M Division of Rules and Records 84/02/28 HAFNER, B 80ffolk Nuclear Study Group 2pp. 22583 008 24X Fiche, 50-000, 84/02/28, 8403080367
- ~-B308090070 Advises that Div of Licensing responsible for developing plan for coordination of BMR pipe crack activities Review & input to encl proposed draft of activities list requested by B30729 CABE.E. Q. Office of Nuclear Reactor Regulation, Director B3/07/28. ARLOTTO, Q. A. Division of Engineering Technology JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post B3003). MATTBON, R. Division of Systems Integration (post B11005). 3pp. 22583 016.
- --8309210434 Requests evaluation of Grand Gulf & Shorehem 830817 & 23 responses; respectively re intergranular stress corresion cracking in EMR piping. Response requested by 830916 W/o encl.

 EISENHUT, D.Q. Division of Licensing. 83/07/06, VOLLMER, R. Division of Engineering. 1p. 22583.010, 24X Fiche: 50-000,84/02/28,8403080367
- 8403080370 Appeals denial of FOIA request for draft IE Insp Repts 50-424/83-13 & 50-425/83-13.

 8DMBY, A H. Troutmen, Sanders, Lockermen & Ashmore 83/11/14
 Office of the Executive Director for Operations. 2pp 22576:244
 24X Fiche: 50-425,83/11/14,8403080370.
- B4030B0372 Responds to appeal re denial of FOIA request for draft IE Insp Repts 50-424/83-13 & 50-425/83-13. Forwards documents FELTON, J. M. Division of Rules and Records. B4/01/31 DOMBY, A. H. Troutman, Bandars, Lockerman & Ashmore. ip 22576-246. 24X Fichs: 50-424,84/01/31,8403080372
- --8403080377 Forwards IE Insp Repts 50-424/83-13 & 50-425/83-13 on 830621-0720 & notice of violation.

 LGWIS.R.C. Division of Project & Resident Programs 83/10/14 KELLEY.R.J. Qeorgia Power Co 2pp. 22576:247. 24X Fiche, 50-424, 84/01/31, 8403080372

- --8403080381 Notice of violation from insp on B30621-0720 * Region 2, Office of Director 50-425/83-13 B3/10/14 3pp 2276 247 24X Fiche 50-424,84/01/31.8403080372
- --8403080384 IE Insp Repts 50-424/83-13 & 50-425/83-13 on 830621-0720 Violations noted failure to implement pips support control documents & provide appropriate concrete expansion anchor & structural steel acceptance criteria
 BROWNLEE, V L., BANDERS, H. F., JACKSON, L. H. Region 2, Office of Director 50-425/83-13 83/10/11 36pp 22576-252 24X Fiche 50-424,84/01/31,8403080372
- --8403080377 Forwards 1E Insp Repts 50-424/83-13 & 50-425/83-13 on 830621-0720 & notice of violation LEMIS,R C Division of Project & Resident Programs 83/10/14 KELLEY,R J Georgia Power Co 2pp. 22576 247 24X Fiche 50-424,84/01/31,8403080372
- --8403080381 Notice of violation from insp on 830621-0720 * Region 2. Office of Director 50-425/83-13 83/10/14. 3pp. 22576: 249 24X Fiche: 50-424,84/01/31,8403080372
- --B4030803B4 1E Insp Repts 50-424/83-13 & 50-425/83-13 on 830621-0720 Violations noted failure to implement sipe support control documents & provide appropriate concrete expansion enchor & structural steel acceptance criteria BROWNLEE.V L , BANDERB.W F , JACKSON,L H Region 2, Office of Director 50-425/83-13 83/10/11 36pp 22376 252 24X Fiche: 30-424,B4/01/31,B403080372
- B403080375 Final response to FUIA request for SECYs 83-32,988,228A,226A,240,246 & 261 to be placed in PDR Attachment 3 to SECY-83-228 w/associated enci placed in PDR Attachment 4 to SECY-83-228 partially withheld (ref FUIA Exemption 5) FELTON, J M Division of Rules and Records B4/02/17 GRABER, L D NUS Corp. 2pp 22567 330
- --8301140173 Provides responses to 821220 questions re SECY-82-489, "Licensing of Gunsights Illuminated by Bugraduct Mati " DIRCKS.W J Office of the Executive Director for Operations 83/01/05 AHEARNE.J F Commissioners 3pp 22567 334
- --B403080379 Requests comments on whether public distribution of illuminated gunsights would contravene any existing faderal regulation or policy re firearms or accessories Response requested by 830218 H/o SECY-82-489
 MALSCH, M G Office of the General Counsel 83/01/19 OL8ON, T B Justice. Dept of 2pp 22367 332
- ---B4030B03B3 Responds to inquiry re NRC review of solicy concerning licenting of gunsights illuminated by nuclear byproduct matl Contact w/criminal div of DDJ & FBI may provide insight re firearms control Info deleted SHANKS, R. B. Justice, Dept. of, 83/06/03 MALSCH, M. G. Office of the General Counsel 3pp. 22567-337
- B403080385 FOIA request for 27 documents referenced in 1975 EIB re facilities & similiar environ documents List & news articles encl. RYAN.J A Streich, Lang. Weeks & Cardon 84/01/17 Office of Administration 9pp 22581 171 24X Fiche 50-528.84/01/17, B403080388
- 8403080388 FOIA request for documents re landfill located in Middletown Township, Bucks County, PA MILL, S. White & Hilliams 84/02/13 FELTON, J Office of Administration Ip 22881 326
- 8403080390 Responds to FOIA request for 27 documents referenced in 1975 EIB re facilities & similiar environ documents Forwards App A Documents 1-10 Documents 11 & 12 available at NTIS FELTON.J M Division of Rules and Records, 84/02/13 RYAN.J A Streich, Lang, Wreks & Cardon 2pp 22581 180 24x Fiche 50-528,84/02/13,8403080390
- --8108270490 Bubmits Geosciences Branch DES input Updated summary of geology & seismology section FBAR will be included in BER.
 JACKSON.R E Geosciences Branch 81/08/14 MIRAGLA.F.
 Licensing Branch 3 2pp. 22581 182 24X Fiche 50-528,84/02/13,8403880390
- --B4030B0400 Discusses review of environ rept re transmission lines crossing Indian reservations Tribal council consent should be obtained for right-of-way before environ rept published. Related info encl

 # Interior. Dept of, Bureau of Indian Affairs 74/12/11
 REOAN, M. H. Atomic Energy Commission Deputy Director for Reactor Projects 5pp 225B1 184. 24X Fiche 50-528,84/02/13,8403080390

- --8403080406 Comment on DEB, per 750414 request Statement somewhat biased toward project More detailed maps of pipeline & transmission line corridors should be provided in final statement DOREMUB, S D Interior, Dept of 7915 75/07/23 REGAN Division of Reactor Licensing (NRR-1975 only) 29pp 22581 189 24X Fiche 50-528,84/02/13,8403090390
- --8403080409 R-900-74-2
 "Groundwater Conditions of Lower Hassayampa-Centennial Area,
 Haricopa County, AZ " Related info enc!
 Harshbarger & Associates 74/06/30 B3pp 2258; 219 24X
 Fiche 50-528,84/02/13,8403080390
- 8403080391 Responds to FOIA request for info re landfill located in Middletoun Township, Bucks County, PA Forwards J Kinneman 840207 ltr to Korman Corp M/o encl. FELTON, J N Division of Rules and Records 84/03/02 MILL, 8 White & Williams ip. 22581:327
- 8403080393 Forwards DL Jensen 830517 ltr to N Palladino re BGJ investigation of TMI. Document subj to Voigt 830526 FDIA request & 830919 appeal Document should be placed in PDR SWEENEY, M Office of the General Counsel 84/01/27 POGL, M J NRC -- No Detailed Affiliation Given. 1p 22567 354. 24X Fiche 50-289,84/01/27,8403080393
- --B403080425 Responds to B30411 ltr re TMI-1 restart & DDJ investigation into allegations re mgt competence Investigation being pursued diligently but will not be completed by requested date

 JENSEN: D L Justice. Dept of B3/05/17 PALLADINO, N J
 Commissioners 4pp 22567.335 24X Fiche 50-289.84/01/27.
 B403080393
- 8403080398 Responds to FOIA request for info on nuclear freeze NRC has no documents subj to request Suggests that DOD be contacted at listed address for info FELTON, J M Division of Rules and Records 84/02/28. ENOS, B Affiliation Not Assigned ip 22567.361
- B403080401 FOIA request for info re nuclear freeze ENDS,B Affiliation Not Assigned. 84/02/05 Office of Administration 1p 22567 362
- 8403080402 F01A request for info or sources of info re nuclear waste JDNES,F H Affiliation Not Assigned 84/02/14 F6LTON.J Division of Rules and Records 1p 22547:359
- B4030B0404 Responds to FOIA request for info re nuclear waste Forwards listed documents W/o enris FELTON,J M Division of Rules and Records 84/02/23 JONES,F H Affiliation Not Assigned ip 22567 360
- 8403080405 Further response to FGIA request for documents re BER related to operation of facilities Forwards App B documents App A & B documents available in PDR Review of remaining documents subj to request in progress FELTON, J M Division of Rules and Records. 84/03/02 QARDE, B P Government Accountability Project. 4pp 22583:073 24X Fiche D0-275,84/03/02,8403080405
- --B312230256 Forwards responses to Allegations 7.9 & 48, per 831130 request SPEIS.TP Division of Safety Technology B3/12/09 KNIGHTON. & Office of Nuclear Reactor Regulation. Director. 12pp. 22583:111 24X Fiche. 50-275.84/03/02.8403080405
- --8403080411 Forwards response to Allegation RV-83-A-0034.per ON Knighton 831122 note Temporarily exempting licenses from maintaining physical security & safeguards contingency plans did not increase risk of radiological sabstage MCCORKLE.O M. Power Reactor Safeguards Licensing Branch 83/12/01 THOMAS.C O. Standardization & Special Projects Branch 4pp 22583 077. 24% Fiche. 50-275.84/03/02.8403080405
- --8403080420 Forwards response to Allegation RV-83-A-0034, per GW Knighton B21122 note Temporarily exempting licensee from maintaining physical security & mafeguards contingency plans did not increase risk of radiological sabotage BURNETT.R F. Division of Safeguards 83/12/08, EISENHUT.D G. Division of Licensing. 3pp 22583 084 24X Fiche 50-275, 84/03/02,8403080405

- --B4030B042; Requests assistance in addressing improper design activities re use of U-bolts & code break (code boundary) design.per affidavit re allegations
 BIBHOP, TW Division of Resident.Reactor Project & Engineering
 Programs 63/11/27 EISENHUT.D & Division of Licensing 15pp
 22583 093 24X Fiche 50-275.84/03/02.8403080405
- --8403080422 Forwards input on Allegations 51 & 52 Fuel loading addressed in 831108 Memorandum & Order CLI-83-27 No significant safety concerns matl to fuel loading & precriticality testing warrant continuation or suspension of activities BURNS.8 Office of the Executive Legal Director CLI-83-27 83/12/09 KNIGHTON, G Office of Nuclear Reactor Regulation, Director 3pp 22583 108 24X Fichs 50-275.84/03/02.8403080405
- --8403080426 Forwards safety evaluations for Allegations 8,10,11,14,15, 16,17,27,28,27,31,32,33,35,36,55,85 & 86 Licensee approach for determining containment stability against tilting acceptable VOLLMER,R H Division of Engineering IEB-80-11 83/12/09 E18EMUT.D © Division of Licensing 31pp 22583 132 24X Fiche 50-275,84/03/02,8403080405
- --840308043; Forwards SBER input re Allegation 68 Programmatic breakdown in Pullman Power Products GA program not indicated Installed hardware safety concerns not identified LIEBERHAN. J Office of the Executive Legal Director 83/12/27 EISENHUT. D Division of Licansing 4pp 22583-163, 24X Fiche 50-275,84703/02,8403080405
- B4030B040B F0IA request for repts of insp carried out under Condition 2 of Nuclear Energy Liability policies for fscilities CALBOYAS, C Affiliation Not Assigned 84/02/07 Region 5, Office of Director 4pp 22567 341. 24X Fiche 50-000,84/02/07,8403080408
- B403080419 Responds to FDIA request for repts of insp carried out under Condition 2 to Nuclear Energy Liability policies for facilities NRC does not have repts FELTON, J M Division of Rules and Records 84/02/22 CALSOYAB, C D. Affiliation Not Assigned. 1p 22567 345 24X Fiche 50-000,84/02/22,8403080417
- B403090006 Further response to FOIA request for all 1982 SECY papers to be made available SECY-82-37 & SECY-82-37A placed in PDR FELTON,J M Division of Rules and Records 84/02/22 WEISB,E R Union of Concerned Scientists 1p 22991 218.
- --BE03050065 SECY-B2-037
 Informs of receipt of Executive Branch final draft rept
 to Congress per Section 601 of Nuclear Non-proliferation
 Act of 1978 Rept generally accurate No areas warrant
 formal NRC Lomment
 DIRCKS,W J Office of the Executive Director for Operations,
 B2/01/29 100pp 22591,220
- --8204160230 SECY-82-037A
 Informs Commission of receipt of final varsion of rept to congress re Section 601 of Nuclear Nonproliferation Act DIRCKS.W J Office of the Executive Director for Operations 82/03/27. 64pp 22591,317.
- B403070015 F0IA request for SECY-B3-445 to be placed in PDR
 BUCKLES,R NUS Corp. CD-L15-B3-058, B4/01/26 Division of Rules
 and Records Ip 22592 311
- B403070016 FQIA request for documents re background radiation survey at BNL.
 GROSHAN, K Island Closeup News Service, Sag Harbor, NY 84/02/15
 FELTON NRC No Detailed Affiliation Given 1p 22572:343
- B403070017 Responds to FOIA request for SECY-83-445 to be placed in PDR Forwards SECY-83-445 Dacument also in PDR FELTON, J M Division of Rules and Records, 84/02/28 BUCKLES, R. NUB Corp 1p. 22592; 312.
- ---8403070019 SECY-83-445
 Responds to Commission request for human factors program
 plan quarterly repts cited in Chilk 830216 staff
 requirements memo
 DIRCKS.W J Diffice of the Executive Director for Operations,
 83/10/28 16pp 22592,313
- B40309001B Responds to FDIA request for documents re BNL background radiation survey DDE preparing Shoreham & BNL site repts. When printed Shoreham rept will be available from NRC & BNL rept will be available from DDE FELYON, J M Division of Rules and Records 84/03/02, OROBEMAN, K Island Closeup News Service, Sag Harbor, NY. 1p. 22592:344, 24X Fiche:50-322,84/03/02,840309001B

- B403090020 FOIA request for Nov 1983 document re resolution of Generic Issue 50. "Reactor Vessel Level Instrumentation in BWRs." CHAPMAN.N. 9 Bechtel Corp B4/02/01 FELTON. J M Division of Rules and Records 1p 22592 340
- 8403090021 Responds to FOIA request for documents proposing resolution of Generic Issue 50. "Reactor Vessel Level Instrumentation in BHRs." Documents entirely withheld (ref FGIA Exemption 5) FELTON, U M Division of Rules and Records 84/03/02 CHAPMAN, N O Bechtel Corp 2pp 22592 341
- 8403090027 FOIA request for records re 1977 Nuclear Svcs Corp audit of Pullman Power Products. REYNOLDS.J Center for Law in the Public Interest 84/01/20 Office of Administration. 2pp 22592 329 24X Fiche. 50-275, 84/01/20
- 8403090028 Partial response to FOIA request for records re 1977 Nuclear Evcs Corp audit of Pullman Power Products Documents entirely withheld (ref FOIA Exemption 5). Review of remaining documents subj. to request in progress FELTON, J M Division of Rules and Records 84/03/01 REYNOLDS, J Center for Law in the Public Interest 2pp. 22592 331 24% Fiche: 50-275,84/03/01,8403090028
- 8403090032 Final response to FOIA request for five categories of documents re facility. Forwards add1 documents listed on App A.
 - A. FELTON.J M Division of Rules and Records 84/03/02. LYON,V F Lyon & Kurz 2pp 22592.333 24X Fiche.50-382.84/03/02.8403090032
- --8403090038 Lists areas of concern at facility requiring investigation.
 Ebasco & util failed to address & resolve deficiencies
 identified by many personnel, including GA documentation
 reviewers.
 # Louistana Power & Light Co 84/03/02, NRC No Detailed
 Affiliation Given 2pp. 22592, 336, 24X Fiche 50-382,84/03/02,
 8403090032.
- B403260116 FDIA request for five categories of documents re facilities BARNEB.C Affiliation Not Assigned 83/12/02, FELTON.J M Division of Rules and Records 1p 22763 333
- BA03260123 Partial response to FOIA request for five categories of documents rs Kerr-McGee Dil Industries. Inc Forwards documents listed on app. Review of addl documents subj to request continuing.
 FELTON, J. M. Division of Rules and Records 84/03/02 BARNES, C. Affiliation Not Assigned 2pp 22763 334.
- --B403240129 Repts 660207 explosion due to accumulation of hydrogen gas, killing operator & injuring two other employees. Operation of thorium process line terminated WULLER, 2.E. Kerr-McOee Corp. 66/03/03 PRICE, E R Atomic Energy Commission 2pp 22763.336
- ---8403260136 Forwards investigation rept re 660207 explosion at facility Licenses evaluation of hazards involved in processing source mat1 should be reviewed. W/o stated encls. DUBINDEKI, L. Atomic Energy Commission 66/08/02 PAGE, R O Atomic Energy Commission 4pp 22763 340
- --8403260141 Confirms that Enforcement Branch will not communicate w/licensee re compilance investigation rept concerning explosion on 660207. No items of noncompliance noted during investigation PAGE.R. 9. Atomic Energy Commission 66/08/17 Atomic Energy Commission 1 p 22763:344
- --840326014B Forwards Region IV 660729 memo re results of survey of licensee facility at Cushing,OK. Licensee measurements, as reported in 660609 ltr. substantiated by Region IV findings RDY.W Atomic Energy Commission, 66/08/08 NUSSBAUMER, D A Atomic Energy Commission, 1p 22763 345.
- --8403260153 Discusses certification of 660426 rept re disposition of BNM, per 9 Waller 660602 telcon Rept should indicate that contemination limits met in order for Commission to authorize transfer of facility, NUSSBAUMER, D. A. Atomic Energy Commission, 66/06/10 LAMBERTUS, H. Kerr-McGee Corp. 2pp 22763:348.
- ---8403260158 Confirms 660207 chemical explosion at Cushing OK thorium processing plant per 660207 telcon Investigation complete LAMBERTUS.H. Kerr-McGee Corp. 66/02/08 WALKER,N I. Atomic Energy Commission. 3pp. 22763.352
- 8403280076 FOIA request for seven categories of documents HIATT.S L Ohio Citizens for Responsible Energy. 83/11/30 FELTON.J.M. Division of Rules and Records 1p. 22808:243.

- 8403280080 Partial response to FOIA request for seven categories of documents Forwards App A documents responsive to Items 1, 2, 5, 6 & 7 of request NUREG-0386, "NRC Practice & Procedures Manual," presently being updated FELTON, J M Division of Rules and Records 84/01/17 HIATT, 8 Ohio Citizens for Responsible Energy 2pp 22808 244
- --8107200104 Responds to NRC request for legality of providing free transcripts of adjudicatory proceedings NRC may use funds appropriated by Energy & Water Development Appropriation Act 1781 to provide free hearing transcript to all parties VAN CLEVE, H D General Accounting Office B-200585 81/05/11 Commissioners 4pp 22808 266
- --8409280081 Discusses costs of intervention & legal authority to provide financial assistance to intervenors in NRC proceedings KELLER, R F General Accounting Office 76/02/19 General Accounting Office 16pp 22808 246
- 8403280163 Second partial response to FOIA request for documents re NRC internal procedures or guidance for evaluating new generic requirements Forwards App A document App B documents available in PDR. Bearch for addl documents continuing FELTON.J M Division of Rules and Records 84/02/17 WEISS.E R Union of Concerned Scientists 3pp 22789:351
- --8312150232 Outlines formal NRR procedures to ensure timely feedback & closure on CRGR reviews of generic issues developed by NRR Director's ofc will distribute meeting minutes to div directors

 DENTON, HR Office of Nuclear Reactor Regulation, Director 83/12/06 EISENHUT, D. G. Division of Licensing 2pp 22789.355
- 8403280146 FOIA request for radiation source or device registration certificates issued to JL Sheperd & Assoc & Alpha Omega & application for device registration from JL Bheperd HAMMITH. A. FOI Services 3449 84/02/07 FELION, J M Division of Rules and Records 1p. 22807 203
- 8403280167 Responds to FOIA request for radiation source or device registration certificates issued to JL Sheperd & Assoc & Alpha Omega Forwards certificates Application for device registration available from State of CA Dept of Health Svcs FELTON, J M Division of Rules and Records 84/02/22 HAHMITT, H A FOI Services ip. 22807:204
- --8403280170 Registry of radioactive sealed sources & devices, safety evaluation of calibrator mfg by JL Sheperd & Assoc using 13,500 mCi Cs-137 in Mark IV TL desimeter irradiator ** NRC No Detailed Affiliation Given CA598D1058 80/05/07 3pp. 22807 205.
- ---8403280174 Registry of radioactive sealed sources & devices, safety evaluation of instrument calibrator & gamma irradiator mfg by JL Shepers & Assoc using various sealed source model designations containing 300 Ci Cs-137 & 33 Ci Co-60 w NRC No Datailed Affiliation Given CA598D106U 80/06/23 4pp. 22807 208.
- --84032B0177 Amended registry of radioactive sealed sources & devices, safety evaluation of instrument calibrator & gamma irradiator mfg by JL Sheperd & Assoc using various swaled source model designations containing Cs-137 & Co-60 % NRC No Detailed Affiliation Given CA598D107U 83/01/31 App. 22807 212
- --B403280182 Amended registry of radioactive smaled sources & devices, safety evaluation of calibr range mfg by JL Sheperd & Assoc using sources in 78 or 28 series calibrators containing 440 Gi Cs-137 ** NRC No Detailed Affiliation Given CA598D108U 83/01/31 3pp 22807:216.
- --B403280185 Registry of radioactive sealed sources & devices, safety evaluation of neutron detector calibrator mfg by JL Sheperd & Assoc using Monsanto 27228 258,27278 & 2765 containing Pu-238/Be, Am-241/Be & Cf-252 ** NRC No Detailed Affiliation Given CA598D109U 80/10/06 3pp 22807:219.
- --8403280188 Registry of radioactive sealed sources & devices, safety evaluation of portable calibrator mfg by JL Sheperd & Assoc using Industrial Reactor Lab Beries 2,3M Co 4P6E & Isotope Products Lab 193 containing 390 mCi Cs-137
 WONO, G J NRC No Detailed Affiliation Given. CA598D1108
 81/06/29. 5pp 22807.222
- --8403280191 Registry of radioactive scaled sources & davices, safety evaluation of gamma irradiator mfg by JL Sheperd & Assoc using JL Sheperd & Assoc Model 7810 & Gamma Industries Type VDHP (ANSI 46515) containing 4,011 Cl Co-60. ECKBERO:8 R. NRC No Detailed Affiliation Given CA598Dil98. 83/09/21 6pp 22807 227

- --8403280197 Registry of radioactive sealed sources & devices, sapety evaluation of dosimeter calibrator mfg by JL Sheperd & Assoc using Isotope Reactor Lab Series 2.1sotope Products Lab Model 225 & 3M Co Model 4F&E containing 25 mCi Cs-137 HONG.6 NRC No Detailed Affiliation Given CA598D1129 82/12/02 6pp 22807 233
- 8403280211 FDIA request for documents re falsification of QA/QC records by M Annas at facility BELL.N Nuclear Information & Resource Service 84/01/05 Office of Administration 2pp 22799 326 24X Fiche 50-482.84/01/05. 8403280211
- 8403280216 Partial response to FDIA request for documents refalsification of GA/GC records by M Annas at facility Forwards App A documents Documentation also available in PDR FELTON, J M Division of Rules and Records 84/03/07 BELL.N Nuclear Information & Resource Service 2pp 22799 328 24X Fiche 50-482,84/03/07.8403280216
- ~-8403280285 Discusses review of closed & open files re alleged falsification of traveler records A Gauthier "spread sheet" shows Files 82-10 & 82-13 as closed & assigned to J Sinclair Region IV had nothing in files.
 BOMERS: H Office of Inspector & Auditor B3/03/16 CUMMINGS: J J Office of Inspector & Auditor B3/03/16 CUMMINGS: J Fiche 50-482.84/03/07.8403280216
- --8403280329 Forwards IE investigation rept re facility.per telcon request W/o encl. CUMMINGS.J J Office of Inspector & Auditor 82/01/12 MORRISSETTE, K Justice, Dept of 1p 22799 331 24X Ficho 50-482,84/03/07.8403280214
- --B4032B0235 Responds to Region IV 810722 & IE 811014 memos re improper duplication of safety-related pipe hanger DQJ contacted & advised that no objection raised to IE issuing investigation rept
 SCHMCDELENIA Office of Inspector & Auditor B1/12/23
 THOMPSDN.Q Enforcement & Investigation Staff (Pre 820201) ip 22/79 332 24% Fitche 50-482.84/03/07,8403280216
- --8403280240 Discusses improper duplication of safety-related pipe hanger K Morrissette, DDJ, apprised on 811208 of contents of Region IV investigation rept re fabrication of safety-related pipe hanger DDJ had no objections to rept issuance SINCLAIR, J R Office of Inspector & Auditor B1/12/23 OFFIce of Inspector & Auditor & Au
- B403290002 Final response to FOIA request for four categories of documents, tests, studies & analyses referencing or pertaining to NURCG-0103, "BIS for OAM PWR" App A documents encl FELTON, J M Division of Rules and Records 84/01/13 MADDEN.T J Kaye, Scholer, Fierman, Hays & Handler App 22816 127 24X Fishe 50~000, 84/01/13, 8403290002
- --8403270004 Speech entitled "RCPB Leakage Detection Sys "
 POMERGY,D L. Atomic Energy Commission. Directorate of Regulatory
 Operations 84701/13 5pg 22817 003 24X Fiche 50-000.
 84701/13.8403270002
- --8403P90006 Discusses 730115 Draft & of proposed safety guide entitled.
 "RCPB Leakage Detection Sys "
 ROGERS, L. Atomic Energy Commission Directorate of Regulatory
 Standards 73/01/17 SHAW,M Atomic Energy Commission ip
 22817 008
- ---8403290007 Forwards draft safety guide re leakage detection sys Guide suitable for publication PAWLICKI.8 8 Atomic Energy Commission - Directorate of Regulatory Standards 72/03/16 MINDGUE, R Atomic Energy Commission -Directorate of Regulatory Standards ip 22814 135
- --8403290007 Discusses Reg Guide 1 45 re RCPB leakage detection sys & rept on leakage observed at plant in Germany PORSE: 1 Atomic Energy Commission Directorate of Regulatory Standards 73/05/17 MURLEY, T E Atomic Energy Commission 1p 22817 009
- --8403290010 Draft safety guide, "RCPB Leakage Døtection" * Atomic Energy Commission 72/03/15 9pp 22816 136.
- --8403270011 Requests comments on encl Draft 2 of safety guide re RCPB leakage detection sys by 730119 PORSE, L Atomic Energy Commission. 73/01/15 PAHLICKI,S 8., KLECKER,R W. MAASS,W.P. Atomic Energy Commission 2pp 22817

- --8403290012 Forwards Surveillance & Noise Diagnostics Program Planning 760607 meeting minutes FARMER,W S NRC - No Detailed Affiliation Qiven 79/06/26 BROWN,E , JABBUR,K NRC - No Detailed Affiliation Qiven HENDERSON,J Office of Inspection & Enforcement, Office of the Director 36pp 22816 145
- --8403290014 Draft 2 to safety guide. "RCPB Leakage Detection Sys "
 * Atomic Energy Commission 73/01/15 11pp 22817 012
- --8403290016 Forwards Draft 1 to 721219 proposed safety guide entitled, "RCPB Leakage Detection Sys " W/o encl ROGERS.L. Atomic Energy Commission Directorate of Regulatory Standards 72/12/20 FRALEY.R F Atomic Energy Commission. 1p 20817 083
- --8403290018 Notification of 730110 meeting w/ACRS Subcommittee on Safety Guides in Washington,DC to discuss Draft 1 of 721219 proposed reg guides re RCPB leakage detection sys ARLOTTO.G A Atomic Energy Commission - Directorate of Regulatory Standards 73/01/04 ROGERBL Atomic Energy Commission -Directorate of Regulatory Standards 1p 22817 024
- --8403290020 Discusses draft safety guide re RCPB leakage detection sys Editorial changes suggested PORBE: L. Atomic Energy Commission - Directorate of Regulatory Standards 72/12/04, ARLOTTO, G.A. Atomic Energy Commission. 4pp 22817-025.
- --8403270021 Task II B.Draft 3 to proposed rule requiring inerting of Mark I & II containment structures & hydragen control measures to deal w/accident conditions involving large emounts of hydrogen generation in BWR containment vessels # NRC No Detailed Affiliation Given 80/03/05 12pp. 22816 201
- --8403290022 Summarizes comments on seismic quelification for leakage detection instruments & equipment PRISE.L About Energy Commission Directorate of Regulatory Standards 72/11/10 ARLOTTO.0 A Atomic Energy Commission App 22017,029
- --8403270023 Forwards ballot change re ISA draft Std 67 03, Rev N,
 "Std for Light Mater Power RCPB Leak Detection"
 WENZINGER.E C Office of Standards Development, Director,
 80/12/10 Instrument Society of America 1p 22816:213
- --8403290024 Requests assistance in reviewing draft safety guide,
 "Leakage Detection Sys."
 MINDGUE,R.B. Atomic Energy Commission Directorate of Regulatory
 Standards 72/09/28 HANAUER,S.H., KRUESI,F.E., HENDRIX,J.M.
 Atomic Energy Commission ip 22817.035.
- ~~8403270025 Forwards positive ballot re draft Std &7 03,Rev N, "8td for Light Water Power RCPB Leak Detection"
 WENZINGER,E C Office of Standards Development, Director 80/11/03 Instrument Society of America 1p. 22816,214.
- --B403290028 Discusses proposed safety guide, "RCPB Leakage Detection" Comments & decision on whether to proceed w/guide requested PORSE. L Atomic Energy Commission Directorate of Regulatory Standards 72/04/25 ARLOTTO.9 A Atomic Energy Commission 2pp 22817 036
- --8403290031 Advises that draft safety guide forwarded to S Pawlicki, R Klecker & D Pomeroy to enlist preliminary comments prior to formal request for review & Comments, PORSE. L Atomic Energy Commission Directorate of Regulatory Standards 72/09/25 Atomic Energy Commission Directorate of Regulatory Standards 12 22817 038
- ~~8403270034 Discusses Reg Guide 1 45.18A draft Std 867.03 & ANSI draft Std N 41 21 Suggested items clarifying reg guide listed. MCGUEEN, M M Affiliation Not Assigned 77/07/29 Atomic Energy Commission Directorate of Regulatory Standards. 15pp. 22817 039
- --B403290035 Requests comments to ISA draft Btd 47 03, Rev N. "Std for Light Water Power RCPB Leak Detection." Response requested by 801001 Related documents encl.
 HORRISON, W. Assistant Director for General Engineering Standards 80/08/22 MURLEY.T.E. Office of Nuclear Regulatory Research, Director MOSELEY, N.C. Division of Reactor Operations Inspections THORNBURG.H D. Division of Reactor Construction Inspection 82pp 22814-220
- --8403290036 Distusses rev to Reg Quide 1 45 re RCPB leakage detection tys PORSE; i. NRC - No Detailed Affiliation Given. 79/02/26. ANDERSON,W F NRC - No Detailed Affiliation Given. 4pp. DPRI7 054

- --8403290040 Discusses Rev I to Reg Guide I 45, "RCPB Leak Detection Bys " Decision to revise reg guide not yet made PORSEL. Atomic Energy Commission - Directorate of Regulatory Btandards 74/10/07 Atomic Energy Commission - Directorate of Regulatory Standards Ip 22816 302
- --B403290041 Forwards ISA draft Std 967 03,Rev K(11) & ballot on std Recommends 967 03 be adopted as replacement for Reg Guide 1 45 ROSZTOCZY, Z R Analysis Branch 79/01/19 TEDESCO, R L Assistant Director for Reactor Safety 172pp 22017 058
- --8403290044 Discusses study of primary sys leakage detection monitors Related info encl FAIRTILE,N D Atomic Energy Commission 71/09/10 PAWLICKI,S Atomic Energy Commission 96pp 22817 230
- --8403290045 Discusses Q Reed 730301 ltr to Q Arlotto re RCPB leakage detection sys Method for detecting slow departure from normal indications of leakage detection sys provided in util monitoring charts
 PURSE, L Atomic Energy Commission Directorate of Regulatory Standards, 73/03/09 WICHMAN, K Atomic Energy Commission 2pp 22816 303 24K Fiche 50-000,84/01/13.8403290002
- --8403290046 Submits proposed response to SH Bush 730310 comments on guides reviewed at ACRS Subcommittee on Leakage Detection Sys & Loading Combinations Feb 1973 meeting MICHMAN,K R. Atomic Energy Commission Directorate of Regulatory Standards 73/03/20 WICHMAN,K R. Atomic Energy Commission Directorate of Regulatory Standards 4pp 22817 326
- --8403290048 Notifies of ANSI-N274 committee meeting to include requirements of App J in ANSI Std N45 4 Related info encl ARLOTTO.6 A Atomic Energy Commission Directorate of Regulatory Standards 74/04/18 TEDESCO.R L Atomic Energy Commission. Directorate of Licensing MACCARY.R R Atomic Energy Commission. Deputy Director for Technical Review (Pre-1975) GRIER, B H Atomic Energy Commission. Directorate of Regulatory Operations 4pp 22816 305
- --B403270049 Forwards info describing RCS leakage monitoring. Related info encl REED, 0 A Wisconsin Electric Power Co 73/03/01 ARLUTTO, 0 Atomic Energy Commission - Directorate of Regulatory Standards 40pp. 22B17 330 24X Fiche 50-000, 84/01/13, 8403270002
- --8403270051 Forwards FR notice of issuance & availability of six reg guides classified as power reactor guides ROGERS.L Atomic Energy Commission - Directorate of Regulatory Standards 73/05/21 KARAS.F W Atomic Energy Commission ip
- ---8403290052 Forwards listed info re NUTEC moisture leak detection sys Sys applications considered at various facilities include piping of ECCS & welds of main steam lines TELLOCK.H C Nutec. Inc 72/07/14 PORSE. L Atomic Energy Commission - Directorate of Regulatory Standards 229pp 22818-008.
- --840329054 Notice of issuance & availability of six reg guides, including Reg Guides i 43 re stainless steel weld cladding of low alloy steel components & i 44 re control & use of sensitized stainless steel ROSERS. Atomic Energy Commission Directorate of Regulatory Standards 73/05/18 5pp 22816-314
- --8403270055 Comments on Reg Quids 1 45,RCPB leakage detection sys Editorial changes suggested KEELEY, 0 8 Consumers Power Co KEEL 115-73 73/07/18 Atomic Energy Commission ip 22818-237
- --8403270058 Forwards draft reg guide. "RCPS Leakage Detection Sys." for comment Comments will be incorporated into guide prior to issuance ROGERS, L. Atomic Energy Commission Directorate of Regulatory Standards 73/03/19 RAMEY Atomic Energy Commission ip 22816 319
- --8403290059 Comments on Reg Quide 1 45, "RCPB Leakage Detection Sys "Calibr of leakage detection sys during shutdown sufficient Related info encl SALVATORI,R, Westinghouse Electric Corp NB-RS-112 73/12/12 MUNTZING,L,M Atomic Energy Commission Directorate of Regulatory Standards, 23pp 22818 238.
- --8403270061 Discusses issuance of six reg guides categorized as power reactor guides Ouides delineate techniques used to evaluate problems or postulated accidents & provide guidance re info næeded in review Documents encl ROPERS.L Atomic Energy Commission Directorate of Regulatory Standards. 73/05/21 BAUSER,E J Congress (Joint & Rotating Committees, etc.). 14pp 22816-320

- --B403290063 Discusses comments on reg guide re RCPB leakage detection sys PORSC,L Atomic Energy Commission - Directorate of Regulatory Standards 73/04/04 WICHMAN.KR Atomic Energy Commission 1p 22814 334
- ---8403270045 Comments on guides reviewed in feb by ACRS Subcommittee on Leakage Detection Sys & Loading Combination Becondary effects (thermal) from transients may cause valve body distortion & impair operability WICHMAN.K R Atomic Energy Commission Directorate of Regulatory Standards 73/03/20 ARLOTTO, G A Atomic Energy Commission 2pp 22816 335
- --8403270068 Lists proposed reg guides that Engineering Stds Branch plans to submit to ACRS Safety Guide Subcommittee for consideration at Feb meeting ARLOTTO, G A Atomic Energy Commission - Directorate of Regulatory Standards 73/01/26 DURNS,W ACRS - Advisory Committee on Reactor Safeguards ip 22816 337
- --B403290070 Marked-up Draft 2 to safety guide, "RCPB Leakage Detection Siys" * Atomic Energy Commission 73/12/26 14pp 22816 338
- --8403290073 Forwards Draft 1 to proposed safety guide entitled,
 "RCPB Leakage Detection Sys," dtd 721219
 ROOTRS. L Atomic Energy Commission Directorate of Regulatory
 Standards 72/12/20 FRALEY,R F NRC No Detailed Affiliation
 Given 1p 22816 352
- --B403270075 Draft 1 to safety guide, "RCPB Leakage Detection Sys" * Atomic Energy Commission 72/12/19 12pp 22816 353
- 8403290334 FOIA request for contract & mods resulting from RFP R8-RES-83-025 DAYIS:K L. Trammell, Chase, Lambert & Martindale 84/02/14 Office of Administration 1p 22818 273
- 840329033B Responds to FOIA request for contract & mods resulting from RFP RS-RES-83-025 Forwards documents listed on app Dacuments also available in PDR FELTON.J M Division of Rules and Records 84/03/05 DAVIS.K L Trammell, Chase, Lambert & Martindale 2pp 22018 274
- --8403270342 Advises that contract performance may exceed current funding.per Mod 13 to Contract NRC-04-82-102 ENSA unable to obtain firm price for disposal of radwaste HAASS, M Affiliation Not Assigned NRC-04-82-013 B4/02/14 GUSTAVE.R NRC - No Detailed Affiliation Given 1p 22818 276
- --8403290343 Ltr Contract NRC-04-84-i02, "Structural Integrity of LWR Boundary Components II," awarded to Matls Engineering Assoc. Inc MORTON. K V Technical Assistance Contracts Branch NRC-04-84-i02 84/02/10 GREENBLATT.M Materials Engineering Associates, Inc 77pp 22818 279
- B403290341 Responds to FOIA request for records re facility Ltr dtd 840117 failed to meet criteria for waiver of reproduction costs Forwards App A documents Address of Phoenix LPDR listed FELTON.J M Division of Rules and Records B4/02/27 RYAN, J A Streith, Lang, Weeks & Cardon 3pp \$2815 018 24x Fiche 50-528.84/02/27.8403270341
- --8403290344 NUREG-75/022

 DRAFT ENVIRONMENTAL STATEMENT RELATED TO CONSTRUCTION OF PALO VERDE NUCLEAR GENERATING STATION, UNITS 1.2 & 3 Docket Nos 50-528, 50-529 & 30-530

 * Office of Nuclear Reactor Regulation, Director 75/04/30 175pp 22815 301 24% Fiche 50-528, 84/02/27, 8403290341

GEN TEC 18 GENERIC TECHNICAL IBSUES

B31207035B Notification of CROR Meeting 51 on B31123 to review exemption from CROR review of Unresolved Safety Issue A-1 "Mater Hammer" & proposed rev to Reg Guide 1 28, "GA Program Requirements (Design & Const)"

STELLO,V Committee to Review Generic Requirements 63/ii/10 MATTSON.R J Office of Nuclear Reactor Regulation, Director JORDAN.E L Director's Office, Office of Inspection and Enforcement CUNNINGHAM.R E Office of Nuclear Material Safety & Safeguards, Director 2pp 22481 332

- 8401250468 Forwards engineering evaluation rept, "Temporary Loss of All AC Power due to Relay Failures in Diesel Generator Load Shedding Circuitry "Practice of running emergency power sources in parallel w/offsite power sys may be prevalent HELTEMES.C J Director's Office 84/01/06 DENTON.H R Office of Nuclear Reactor Regulation. Director 3pp 22437 349 24X Fiche 50-267.84/02/21,8402270004
- 8403010279 Responds to FOIA request for SECY-83-288 to be placed in PDR Forwards SECY-83-298 Document also available in PDR FELTON, J M Division of Rules and Records 83/12/16 PEDRO, J NUS Corp ip 22449 138
- --8403010283 Comments on SECY-B3-288 re proposed rule on pressurized thermal shock Proposed rule should address CP applicants in addition to UL applicants & operating reactors Schedule for preparation of plant-specific tafety analyses acceptable ZERDE, J E Office of Policy Evaluations B3/08/01 PALLADINO, GJLINSKY, ROBERTS Commissioners 4pp 22449, 222
- B4030(0477 Responds to B40113 ltr re release of radioactive matl into atmosphere & embrittlement of containment shells in older nuclear gower plants & capability of containment structure to withstand pressurized thermal shock DENTON, H R Office of Nuclear Reactor Regulation, Director 84/02/15 AMBORD, D A Affiliation Not Assigned. 3pp 22436 300
- B403020313 Forwards addl comments to Quidelines 5a.7a & 7b of technical evaluation rapt in response to NRC 820630 ltr re control of heavy loads.per Generic Ltr 81-07 MILLS.L M Tennessee Valley Authority QL-81-07. B4/02/28 ADENSAM,E Licensing Branch 4 11pp 22439 190 24X Fiche: 50-327.84/02/28.8403020313
- 840303D020 Responds to FDIA request for documents re PABNY submittal on sys interactions, repts evaluating submittal & list of repts/analyses from LLL evaluating PABNY sys interaction program Forwards App A documents
 FELTON.J M Division of Rules and Records 83/12/07 SHOLLY, S Union of Coherened Scientists App 22525 098 24X
 Fiche 50-000,83/12/07,8403050020
- --B308040003 Forwards proposed text for ltr to PASNY requesting info for sys interaction methodology studies. Timing for receipt of documents critical to plan for resolving Unresolved Bafety Issue A-17 Expedited transmittal requested THADANI.A C Reliability & Risk Assessment Branch B3/06/14 VARGA.S A Operating Reactors Branch I p 22525 198 24X Fiche 50-000.83/12/07.8403050020
- --8403050023 "Diagraph-Matrix Application on Indian Point 3 for Sys Interactions," statement of work Related info encl * NRC - No Detailed Affiliation Given FIN A-0445 20-19-80-51-5 83/12/07 33pp 22525 111. 24X Fiche 50-000,83/12/07,8403050020
- ---8403050024 Draft "Evaluation of Indian Point 3 Sys Interaction Analysis Program" * NRC - No Detailed Affiliation Given 82/02/20 7pp 22525 104 24X Fiche: 50-000, 83/12/07, 8403050020
- --8403050034 Discusses 791115 meeting re ACRS 1tr on Indian Point 3 sys interactions SCHWENCER, A Deprating Reactors Branch 1 (Pre 800428), 79/12/05 EISCNHUT, D C Division of Operating Reactors, 2pp 22527 147 24X Fiche 50-000,83/12/07.8403050020
- B403070135 Brief on conflict posed by legal requirement of timeliness & equitable considerations ASLB should issue ruling allowing patitioners contentions that address new fuel core design, changes in Tech Specs & reduction in safety margins HODDER, H H Center for Nuclear Responsibility OLA 84/03/03 11pp 22538 265 24X Fiche 50-250,84/03/03,8403070135.
- --8403070143 Forwards applicant 630325 ltr w/encl re util pressurized thermal shock & flux reduction program per 640228 request. W/o ltr HODDER: M H HODDER: M H Center for Nuclear Responsibility OLA 64/03/03 Atomic Sefety and Licensing Board Penel. 7pp 22538:278 24X Fiche 50-250.84/03/03.
- 8403080020 Forwards integral neutron source data for evaluating k verifying flux reduction per 84117 request Data for Cycle 9 core actent time averaged relative power density, critical weld peaking factor & perigheral assembly pin power encl HILLIAMO.J.W. Florida Power & Light Co. L-84-54. 84/03/01 VARQA.S A Operating Reactors Branch 1 10pp 22559:229 24X Fiche 50-250.84/03/01.8403080020

- 8403080179 Fourth partial response to FOIA request for aix categories of documents re facilities Forwards App A documents. App B document entirely withheld (ref FOIA Exemption 3) Review of add1 documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERBON, 8 I, Garvey, Schubert, Adams & Barer 7pp 22383 226 24X Fiche 50-000, 84/02/13, 8403080179
- --8303100476 Forwards util 830223 submittal in response to telcon during which remaining Phase I open items of "Control of Heavy Loads Case Reviews." were discussed W/o encl CLEMENBON, F Auxiliary By stems Branch NRG-20-18-388. 83/02/28 8TICKLEY, T H E080, Inc. 19 22583 360 24X Fishs 50-000,84/02/13,8403080179
- 8403120081 Forwards safety evaluation re Sections 5 i 1 & 5 3 of NUREG-0612. "Control of Heavy Loads at Nuclear Power Plants " Guidelines satisfied Phase I acceptable JOHNSON, E. H. Region 4. Office of Director 84/03/06 LEE.O. R Public Service Co. of Colorado 2pp 22590: 168 24X Fiche. 80-267. 84/03/06. 8403120081
- --8403120086 Bafety evaluation re NUREO-0612, "Control of Heavy Loads," Phase I Quidelines satisfied Research Phase I Quidelines satisfied Research Research Phase I Quidelines satisfied Research Resear
- --8402280725 EGG-HS-6294 RO3
 "Control of Heavy Loads at Nuclear Power Plants, Fort St
 Vrain Nuclear Generating Station, Phase I, "technical
 evaluation rept
 STICKLEY, T H EG&G, Inc FIN A-6457 84/01/31, NRC No
 Detailed Affiliation Given 27pp, 22590, 172 24X
 Fiche 50-267, 84/03/06, 8403120081
- 8403130190 Forwards response to NRC 801222 request for review of controls for handling heavy loads as committed to in 830809 ltr Response to items in Section 21 of 801222 ltr also encl
 BOOKER, J E Gulf States Utilities Co R89-17168 84/03/01.
 DENTON, H R Office of Nuclear Reactor Regulation, Director. 63pp. 22606-063 24X Fiche 50-458.84/03/01.8403130190
- 8403140019 Clarifies Sept 1983 draft technical evaluation rept of Phase II submitted of control of heavy loads, per 840109 telcon. Safe load paths for reactor bldg closed loop cooling water pumps revised MCCAFFREY, B R Long Island Lighting Co SNRC-1012, 84/03/05 DENTON, H R Office of Nuclear Reactor Regulation, Director. App 22633 218 24% Fiche 50-322,84/03/05,8403140019
- B403140191 Forwards technical guidelines required by NUREQ-0737, Suppl 1, including guidance on station blackout conditions (Unresolved Barety Issue A-44), to be considered as response to Generic Ltr 81-04.

 CODK.K W Louisians Power & Light Co. W3P84-0494 84/03/05 KNIGHTON.O W Licensing Branch 3 337pp 22621 001 24X Fiche 50-382, 84/03/05, 8403140191
- B403140279 Forwards request for add1 info re control of heavy loads Response requested within 60 days MILLER, J R Operating Reactors Branch 3 84/03/06, ORIFFIN, J. H. Arkansas Fower & Light Co 2pp 22635 327, 24X Fiche 50-313,84/03/06,6403140299.
- 8403160131 Forwards draft "Status of Vessel Failure Mode Analyses Feasibility Study & Preliminary Evaluations," to satisfy agreement reached during NRC 840112 meeting w/BNML PEDERSON,L T Battelle Memorial Institute: Pacific Northwest Laboratories FIN 8-2510. 84/02/24 HOODS,R. Generic Issues Branch 165pp. 22662 324
- 8403190003 Notifies of CROR Mesting 45 on 830817 to discuss results of NRR study of electromagnetic pulse & proposed exemptions from regulations in implementation of Multi-Plant Action D-10 (Unresolved Issue A-2)
 8TELLD, V Committee to Review Generic Requirements 83/08/04 MATTSDN, R J Division of Systems Integration (post 811005).
 JORDAN, E L Division of Emergency Properedness & Engineering Response (Post 830103) CUNNINGHAM, R.E. Office of Nuclear Material Safety & Safeguards, Director 3pp 22664:347.
- 8403190031 Notifies of CRGR Meeting 44 on 830802 in Bethesde, MD to discuss NUREG-0978, re behavior of BHR Mark III containment & commission paper re integrated safety assessment program STELLO, V Committee to Review Generic Requirements, 85/07/22. MATTSON, R J Division of Systems Integration (post 81005), ORDIAN, E L Director's Office Office of Inspection and Enforcement CUNNINGHAM, R E Division of Fuel Cycle & Material Safety, 2pp.

- 8403170037 Natifies of CROR Mesting 43 on 830727 in Bethesda.MD to discuss Unresolved Safety Issue A-12. "Steam Generator & Reactor Coolant Pump Bupport Toughness" & Generic Issue B-36 re diesel generator requirements

 STELLO, V Committee to Review Generic Requirements B3/07/18

 MATTSON.R J Division of Systems Integration (post B11005)

 JORDAN.E L Director's Office, Office of Inspection and Enforcement CUNNINGHAM.R E Division of Fuel Cycle & Material Safety 2pp
 28266, 233
- 8403190081 Notifies of CROR Meeting 59 on 840328 in Bethesda, MD to discuss proposed resolution of Unresolved Safety Issue A-44 re station blackout & Generic Issue B-56 re diesel generator reliability STELLO, V Committee to Review Generic Requirements 84/03/14 MATTSON,R J Office of Nuclear Reactor Regulation, Director JORDAN,E L Director's Office, Office of Inspection and Enforcement CUNNINGHAM,R.E. Office of Nuclear Material Safety & Bafeguards, Director ip 22669 362
- 8403190103 Notifies of CRGR Meeting 60 on 840411 to discuss activities of NRC Piping Review Committee & proposed resolution of Generic Issue A-30. "Adequacy of Sefety-Related DC Power Supply "
 BTELLO.V Committee to Review Generic Requirements 84/03/14 MATTSOM,R J Office of Nuclear Reactor Regulation, Director JORDAN.E.L Director's Office, Office of Inspection and Enforcement CUNNINGHAM,R E Office of Nuclear Material Safety & Safeguards, Director. 2pp. 22669 310
- B403190146 Notifies of CROR Meeting 47 on B30923 in Bethesda, MD to discuss proposed exemptions to regulations in implementation of Multi-Plant Action D-10 (Unresolved Bafety Issue A-2) & Rev 2 to Reg Ouide 1,105
 BTELLO, V Committee to Review Generic Requirements B3/09/15
 MATTSON, R J Office of Nuclear Reactor Regulation, Director JORDAN, E L. Director's Office, Office of Inspection and Enforcement CUNNINGHAM, R E Office of Nuclear Material Safety & Bafeguards, Director 2pp 22664 359.
- B403190171 Response to petitioners 840303 brief re consolidating two sets of license amends issued in late 1983 in support of new fuel assemblies ABLB should confine proceeding to 841007 amends.

 BAUSER, M A Florida Power & Light Co. BAUSER, M.A Newman & Holtzinger DLA 84/03/14 Atomic Safety and Licensing Board Panel. 15pp 22670 265 24X Ficher 50-250,84/03/14,8403190171
- ---8403190179 Affidavit of DC Poteralski on patitioners 840303 brief re conflict posed by legal requirement of timeliness & equitable considerations Util 830720 amends not part of pressurized thermal shock program W/Certificate of 8vc POTERALSKI, D C Florida Fower & Light Co A-49 84/03/09 17pp 22670:280, 24X Fiche 50-250:84/03/14.8403190171
- 8403200005 Responds to 840227 request for add1 action to varify aspects of overhead crane design at facility.per NUREO-0612 guidelines. Crane safety & reliability satisfactory QUCHA.L.T. Georgia Power Co NED-84-129 84/03/12. STOLZ.J F Operating Reactors Branch 4 2pp 22685 209 24X Fiche' 50-321.84/03/12.8403200005
- B403200099 Forwards schedule for implementation of activities for control of heavy loads, per NRC requests re NUREQ-0612 Cask pit gate listing lugs will be modified by B41015 HUMILL.H D General Public Utilities GPU Service Corp 5211-84-2072 B4/03/15 EISENHUT.D G Division of Licensing Gpp R2685-313. 24X Fiche.50-289,84/03/15,8403200099
- 8403200225 Advises that similarity of Unit 1 & 2 175-ton polar crane verified by noting that cranes purchased under same contract w/same vendor.using identical procurement specs.per NUREO-0612 & 840223 telcon MILLB.L M. Tennessee Valley Authority. 84/03/14 ADENBAM.E Licensing Branch 4. 2pp R2699-361 24X Fiche 50-390.84/03/14.
- B403210029 Comments on proposed rule 10CFR50 re slimination of thermal annealing requirements of App 9.Bection IV B re pressurized thermal shock Supports rule Requirements not needed FAY. C. W. Wisconsin Electric Power Co. 49FR4498 002 B4/03/15 CHILK. S. J. Office of the Secretary of the Commission 2pp. 22704-1388.
- 8403210116 Forwards addl info re power distributions as part of pressurized thermal shock program to effect flux reduction; per 830930 submittal; in response to 840301 telcon ZIPMERMAN,8 R Carolina Power & Light Go NL8-84-115 84/03/12 VARGA,8. A Operating Reactors Branch 1 3pp 22705 064 24X Fiche: 50-261,84/03/12,8403210116

- 8403220192 Forwards "Control of Heavy Loads.Phase II " Rept result of review of crane operation, design & maint, including analysis of load drop risk to safety-related equipment beneath travel paths Confirms defense-in depth.per NOREO-0612 WHITTIER, O D Maine Yankee Atomic Power Co GDW-84-33 84/03/19 MILLER, J R Operating Reactors Branch 3 2pp 22717 048 24X Fiche 50-309,84/03/19,8403220192
- --8403220199 "Control of Heavy Loads. Phase II" # Maine Yankee Atomic Power Co 2763L-SEN 84/03/19 124pp 22717 050 24% Fiche 50-309,84/03/19,8403220192
- 8403220326 NUREG-0978 FC
 MARK IJI LOCA-RELATED HYDRODYNAMIC LOAD DEFINITION Generic
 Technical Activity B-10
 * Division of Bystems Integration (post 811005) 84/02/29. 75pp
- 8403260212 Forwards revised info re monorail paths.updating util 840206 1tr responding to Generic Ltr 81-07 concerning NUREO-0612, "Control of Heavy Loads at Nuclear Power Plants "Field investigation will be provided I month prior to fuel load. MILLS.L M Tennessee Valley Authority QL-81-07 84/03/20 ADENBAM.E Licensing Branch 4 2pp 22756 164 24X Fiche 50-390.84/03/20,8403260212.
- 8403290083 Responds to 840221 request for addl info re control of heavy loads Initial load testing performed for head strongback, dryer separator sling & spent fuel cask yoke ZIMMERMAN.8 R Carolina Power & Light Co NLB-84-094 84/03/20 VASSALLD.D D Operating Reactors Branch 2 Rpp 22806-325 24X Fiche 50-324,84/03/20,8403290083
- B403270110 Forwards J Preston B30104 memo re generic safety issues prioritization methodology for placement in PDR ROBERTS, B J ACRS Advisory Committee on Reactor Safeguards 84/03/14 MCKNIGHT, J Distribution Services Branch 1p 22822.214
- --8403290113 Advises of review of generic safety issues prioritization methodology described in NUREO-0933 Inherent limitations of value impact score formula discussed Use of structured & iterative consunsus judgement methodology recommended PRESTON. J. ACRS Advisory Committee on Reactor Safeguards 83/01/04 BENDER.M. ACRS Advisory Committee on Reactor Safeguards 3pp. 22822 215
- 8403290295 Provides justification why limiting use of 6-inch containment vent sys considered unnecessary Based on info provided vent sys demonstrated capable of performing intended isolation function under transient conditions MEDFORD, M O Southern California Edison Co 84/03/27 CRUTCHIFIELD, D Operating Reactors Branch 5 Spp 22800:037. 24x Fichs 50-206,84/03/27,8403270295
- 8403300288 Requests remittance of fee for review of 840210 rept summarizing available reactor vessel matts data in response to pressurized thermal shock concerns DIGGS,R M License Fee Management Branch 84/03/15 UMRIG,R E Florida Power & Light Co 1p 22844 329 24X Fiche 50-250, 84/03/15,8403300288

INSPECTION AND ENFORCEMENT

- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN, E L Division of Emergency Preparadness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22709 239 24X Fiche 50-000,84/02/28,8401190072
- 8401230630 Partial response to FOIA request for IE 800103 rept re review of mat1 false statement at facilities associated & supporting records to rept & repts prepared in response Forwards App A documents Review of addirecords in progress FELTON, J M Division of Rules and Records 83/11/01 WINSLOW, R Wall Street Journal 2pp. 21705 337
- --8401230660 PND-77-039 on 790305, investigation concluded that QA program for obtaining proper soil compaction of facility deficient excessive settlement observed w/dissel generator hidg & incorrect info re soil foundation contained in FSAR SHEWMAKER, R. E. Office of Inspection & Enforcement, Office of the Director 79/03/06 2pp 21905 352
- 8402090007 IE Info Natice 84-14, "Highlights of Recent Transport Regulatory Revs by DDT & NRC." Svc list encl GRACE, JN Division of GA, Safeguards & Inspection Programs (Post 830103), 84/03/02 Consolidated Edison Co of New York, Inc 130pp 22552; 329 24X Fiche 50-000,84/03/02,8402090007.

- 8402090008 IE info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate " Syc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 122gp 22553 098 24X Fiche 50~000,84/03/02,8402090008
- B402090009 IE lnfg Notice 84-15. "Reporting of Radiological Releases" Svc list good provided the state of the
- 8402070011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Components Below Nil Ductility Temp " Svc list encl JURDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fiche 50-000,84/03/05,8402070011
- 8402070074 IE Info Notice 84-07, Rev 1, "Lessons Learned From Insps of Fire Protection Safe Shutdown Sys " Svc list encl JBRDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York Inc 118pp 22835 049 24X Fishe 50-000,84/03/07,8402070024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Bys " Svc list encl JURDAN, E L Bivision of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co of New York, Inc 118pp 22584 184 24X Fiche 50-000,84/03/07,8402090028
- 8402090031 IE Bulletin 84-02, "Failures of GE Type HFA Reley; in Use in Class IE Safety Sys " Syc list encl DEYOUNG: R C Director's Office. Office of Inspection and Enfortement B4/03/12 Consolidated Edison Co of New York, Inc 134pp 67245 275 24x Fiche 50-000.84/03/12,8402090031
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/21 Consol
- 8402090044 IE Info Notice 84-20, "Svc Life of Relays in Safety-Related Sys " Bvc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B4/03/21 Consolidated Edison Co of New York, Inc 135pp 22733 001 24X Fiche 50-000.84/03/21,8402070044
- 8402210133 PNO-1-84-014 on 840111. New England Nuclear truck carrying radiopharms & research products ran off Interstate 90 No breakage or leakage of radioactive contents found & radiation levels within PDT requirements FRIEDMAN. GLENN, J., JOYNER, J. Region 1, Office of Director 84/02/13 19 22314 318
- 8403010363 EX-84-005 on 840229; natice of violation & proposed imposition of civil penalties to be issued in amount of #40,000 Action based on five violations re open containment isolation valves CRAIG.J. AXELRAD.J Director's Office. Office of Inspection and Enforcement 84/02/24. 2pp 22433 DI3 24X Fiche.50-289,84/02/24.8403010363.
- 8403010375 EN-83-065A on 84022B suspension & order modifying license rescinded Action based on licensee responses to order to show cause Licensee & State of MY will be notified FLACK.F. AXELRAD.J. Director's Office, Office of Inspection and Enforcement 84/02/28 ip 22434 083
- 840302019A PNO-II-84-017 on 840227, power to plant lost due to power outage caused by high winds Licensee declared unusual event & initiated plant radiological contingency plan Backup power continued to function KAHLE.J B , MCALPINE.E J Region 2, Office of Director. 84/02/27 2pp 22439 001
- 3403020235 PNO-II-84-019 on 840228 trip occurred, interrupting electric svc Caused by lightening errestor failing on 230-tV line due to voltage transient sensed by reactor coolent pump power monitors Svc restored within 30 minutes R000E.J.F., PANCIERA.V Region 2, Office of Director 84/02/28 2pp P2440 079 24X Fiche 50-302,84/02/28,8403020235
- 403020238 PNO-II-84-020 labor contract w/intl Brotherhood of Electrical Horkes expires at midnight on 840229 Possibility exists that workers will reject contract & not rept to work on 840302 Supervisory personnel will continue operations GRECNMAN.E Region 2. Office of Director LIPINSKI, D Region 1. Office of Director 84/02/29 ip 22440-093 24X Fiche-50-213,84/02/29,8403020238

- 8403020248 PNO-II-84-018 on 840227. units shut down following failure of Siemens-Allis breaker to trip during functional test of 4-kV electrical breakers for nonsafety-related electrical bus 3G Insp & repair underway DANCE.H C , LEMIS.R C Region 2, Diffice of Director 84/02/28 2pp 22440-101 24X Fiche 50-250,84/02/28,8403020248
- B40302031i PNO-I-84-019 on B40228 Region I advised of contamination at facility Decontamination activities halted until approved plan developed JOYNER. J Region i. Office of Director 84/02/29 2pp 22439 188
- 8403050074 EN-84-006 on 840302, notice of violation & proposed imposition of civil penalty in amount of \$8,000 to be issued. Action based on failure to equip two radiography rooms w/audjele & visible alarms
 FLACK, E., AXELRAD. J Director's Office, Office of Inspection and Enforcement 84/02/28 ip 22488 066
- 8403050103 PNO-TMI-84-002 licenses pleaded guilty to one count of using incorrect procedure to determine RCS water inventory & nois contenders on six of remaining 10 counts, subj to final acceptance by count on 840227 FASAND, A. BARRETT, L. TMI Program Office 84/02/29 ip. 22517 018 24X Fichs 50-320,84/02/29,8403060103
- 8403060110 PND-THI-84-003 on 840229, load test of reactor bldg polar crane scheduled Load test will qualify crane to lift 170 ton reactor vessel head NRC plans to continue monitoring events
 MDSLAK.T. GASAND.A. RARRETT.
 - events MOSLAN.T., GASANO.A.: BARRETT.L. TMI Program Office 84/02/29 1p 22518 310 24x Fiche 50-320:84/02/29:8403060110
- B403060119 EN-84-008 on B40302, order to show cause & order temporarity suspending license issued Action based on B40223 contemination incident resulting from employee repackaging radwaste FLACK, E. , AXELRAD, J. Director's Office, Office of Inspection and Enforcement 84/03/02 ip 22516; 327
- 8403060144 PNO-TMI-84-002A on 840229, court accepted licensee plea of guilty to one count of using incorrect procedure to determine RCS water inventory & plea of nois contenders on six of remaining 10 counts
 FASAND, A. BARRETT, L. TMI Program Office 84/02/29 ip 22513 330 24X Fiche 50-320,84/02/29,8403060144
- 8403040215 PND-V-B4-011 on 840221, reactor trip breaker 8 undervoltage device inoperable Caused by metal shavings in one control room manual reactor trip pushbutton On 840228, four leads in plant protection sys cabinets found disconnected CANTER: H Region 5, Office of Director 84/02/29 ip 22517-230 24X Fiche 50-361, 84/02/29, 8403060215
- 8403060435 PND-TMI-84-003A on 840829, qualification load test of reactor bldg polar crane completed Load test qualified crane to lift 170 ton reactor vestel head scheduled for summer MDSLAK-T. FASAND.A. BARRETT, L. THI Program Office 84/03/01. 1p 22511 362 24X Fiche 50-320,84/03/01,8403060435
- B403070263 PND-II-B4-020 on B40301, radioagraphic tests confirmed feedwater nozzle crack indications on all three steam generators Component replacements under active consideration IE & NRR informed BLAKE, J J, BUTCHER, R C Region 2, Office of Director IEB-79-13, 84/03/02 2pp. 22547 298, 24% Fiche 50-34B, 84/03/02, 8403070263.
- B403070283 PNO-I-B4-021 on B40301 radiographer working at field site could not fully retract 24 i Ci Ir-192 to safe shielded position Caused by improperly connecting pigtail to guidetube Whole body dose read 40 mrem ROWE.C., GLENN, J. Region i, Office of Director 84/03/02, ip 22546 359 24x Fiche 50-293,84/03/02,8403070283
- 8403080016 Further response to FOIA request for lists & records re Co-60 licenses Forwards App A documents.per Item 3 of request Portions of Documents 2 through 5 of App B deleted (ref FOIA Exemptions 6 & 7)
 FELTON.J H Division of Rules and Records. 84/01/11 COWIE,D J Bouck, Holloway, Kiernan & Casey 5pp 22576,274
- --B4030B0170 PNA-B1-O06 on B10714. Louisiana Nuclear Energy Div notified NRC of radiography incident occurring on barge located less than 3 miles offshore Barge captain & radiographer exposed to 11 C1 C0-60. Medical attention obtained DODA, R. J. Region 4, Dallas, Office of the Director (B1/03/01), B1/07/21 2pp. 22577 130

- ---8403080162 PNO-I-BI-033A on 810307, special insp conducted to determine extent of Co-60 contamination resulting from leaking radiography source Contaminated Clothing Found at employee residence will be treated as radwaste COSTELLD, F Director's Office, Office of Inspection and Enforcement KINNEMAN, J Region i, Philadelphia, Office of the Director (81/03/01) 81/03/07 ip. 22577 129
- --8005010203 PNO-III-80-60 on 800318,25 mCi Co-60 sealed source under License 12-13720-01 fell into cake hopper Source believed to be in pile of cake in facility yard on barge heading for Chicago or in freight car bound for Shawinigan, Guebec SCHULTZ, W H , DAVIS, A B Region 3, Chicago, Office of the Director 80/03/25 ip 22576 279
- 8403080213 EN-84-007 on 840307, notice of violation & proposed imposition of civil penalties in amount of \$40,000 to be issued Action based on failure to control access into vital area due to guard leaving post ROBAND, R, AXELRAD, J Director's Office, Office of Inspection and Enforcement. 84/03/02 ip 22560 021 24X Fiche 50-259,84/03/02,8403080213
- 8403080233 PND-III-84-017A several cracks discovered in stainless steel piping sections in LPCI sys & jet pump instrument seal Stainless steel sections & jet pump instrument seal lines will be replaced.

 DEFAYETTE, R. CHRISSOTINGS, N. SHAFER, W. Region 3, Office of Director IEB-83-02 B4/03/01 ip 22540 125, 24X Fichs, 50-263, 84/03/01, 8403080233
- 8403080257 PNO-III-84-012.on 840129.Campbell Pacific moisture/density gauge containing 10 mCi Cs-137 & 50 mCi Am-241 sealed sources stolen from back of pickup truck in Norwood.OH Suspect in custody
 LASUK, B R , AXELSON, H L Region 3. Office of Director 84/01/30 ip. 22557.092
- B403090224 PNO-I-84-022 on 840303, reactor scrammed from 74% power Caused by fast closure of main turbine control valve during surveillance on hydraulic detector. Buspect relays in detector test instrumentation replaced JACOBS. R. KELLY.E. Region 1, Office of Director 84/03/05 1p 22575 077 24% Fiche 50-387,84/03/05,8403090224
- 8403120063 Updated PNO-V-84-QiiA discovered manual pushbutton not imperable as result of metal shavings in contacts Only operability of undervoltage trip on RTB-8 affected Source of metal flakes undetermined DDDB0R T Region 5. Office of Director 84/03/05 ip 22586 288 24X Fiche 50-361, 84/03/05, 8403120063
- 8403120078 Updated PND-III-84-020A three reactor depressurization system valves failed. Caused by binding of disc in seat resulting from increase in closing air pressure Reactor restarted & in situ testing conducted DEFAYETTE, R. Region 3, Office of Director 84/03/04 ip 22586:305 24X Fiche DO-135,84/03/06,8403120078
- B403130208 PNO-I-B4-023 on 840306 worker repairing lights in turbine bldg sustained radioactive contamination on waist & head Incident investigated & critiqued. Corrective actions being reviewed by specialist.

 NIMITZ.R.L. BHANBAKY.M., BELLAMY.R. Region 1, Office of Director B4/03/07 1, 128605-036. 24X Fiche 50-219.84/03/07,8403130208.
- 8403130235 PNO-III-84-023 on 840305 HPCI sys declared inoperable when surveillance test revealed excessive laskage on main pump outboard bearing. During test of automatic depressurization sys, electromatic relief valve E failed to open. CHRISSOTIMOS.N. SHAFER,W Region 3. Office of Director 84/03/06 ip. 22617:278. 24X Fiche 50-254,84/03/06.8403130235
- B403130275 PNO-III-B4-021: on 840302; MSIV closure tripped reactor Cause unknown Safety valve stuck open following pressure reduction Incident response ctr in standby mode JACKIRI. BOYD, D. Region 3. Office of Director 84/03/02 ip. 22607:139 24X Fiche: 50-346,84/03/02,8403130275
- B403130310 PNO-III-B4-024: from 840130-0305, patient administered 8,700 rads to midling-brain rather than prescribed 6,000 rads Treatment stopped upon discovery of misadministration NRC medical consultant will review case.

 SIMMONS.T., SRENIAMKSI.D. Region 3, Office of Director. 84/03/07.

 1p. 22613 335
- 8403130336 PNO-III-84-021A on 840303 MBIV replaced & steam generator 2 refilled following 840302 reactor trip Generator isolated during refilling to protect against release of radioactivity in event of steam generator tube feilure, JACKIW I. BOYD, D. Region 3, Office of Director 84/03/05, 2pp. 22607:243. 24x Fiche 50-346.84/03/05.8403130336

- B403130379 PND-III-84-022 in response to IE Info Notice 82-29, exam identified 67 of 74 control rod drive support pins w/crack indications Licensee & Westinghouse evaluating exam findings to determine required action

 JORDAN, M., JACKIW, I., SHAFER, N. Region 3, Office of Director IEIN-82-29 B4/03/02 ip 22616 092 24% Fiche 50-266, 84/03/02, 84/03/30379
- 8403130408 EN-84-010 notice of violation & proposed imposition of civil penalties in amount of \$2,000 will be issued on 840312 Action based on multiple failures to comply w/NRC requirements re-radiation safety FLACK.C. AXELRAD.J Director's Office, Office of Inspection and Enforcement 84/03/07 1p 22616 050
- 8403130423 PND-III-84-017B on 840308 during visual insp.four J mozzles on feedwater spangers of reactor vessel found cracked Decision on repair & replacement pending more detailed exam State of MN notified DEFAYETTE, R , WALKER, R , SHAFER, W Region 3, Office of Director 84/03/08 ip 22413 090 24X Fichs 50-263, 84/03/08, 8403130423
- 8403130445 EN-84-009 on 840312, notice of violation & proposed imposition of civil penalty in amount of \$30,000 will be issued based on Failure of Tech Specs procedures re entry into locked high radiation area FLACK, Γ, ΑΧΕLRAD, J Director's Diffice, Office of Inspection and Enforcement EA-009 B4/03/07 2pp 22813 138 24X Fiche 50-261,84/03/07,8403130445
- B403130456 PND-I-B4-024 on B40306 during resin replacement operation, unplanned release of gaseous radioactivity occured Saveral workers slightly contaminated w/Rb-B8 No activity detected State of ME informed BICEHOUSE, H . SHANBAKY, M , BELLAMY. R Region 1. Office of Director B4/03/07 1p 226/3 329 24X Fiche 30-309, B4/03/07, B403130456
- 8403150073 EN-84-012 on 840313 notice of violation & proposed imposition of civil penalty in amount of \$40,000 will be issued to license Action based on violation of Tech Spacs re containment spray sys inoperability GRAIGJ, AXELRAD, J Director's Office, Office of Inspection and Enforcement 84/03/08 ip 22641 248 24X Fiche 50-247,84/03/08,8403150093
- 8403150121 PNO-V-84-013 on 840307, Bechtel laborer suffered heart attack while working in auxiliary bldg Medical attention provided to individual at site Individual pronounced dead upon arrival at Sierra Vista Hosp DDDB8.R T Region 5. Office of Director 84/03/07 ip 22640 218 24X Fiche 50-275,84/03/07,8403150121
- 8403160001 EN-84-013 notice of violation & proposed imposition of civil penalty in amount of \$3,000 will be issued by 840315 re three violations concerning loss of well logging source FLACK, E. AXELRAD. J. Director's Office. Office of Inspection and Enforcement 84/03/12 ip 22655 209
- B403160039 PNO-II-84-021 crack indications identified in all 14 12-inch riser elbows in replacement recirculation piping scheduled to be installed Caused by improper forming temps used during bending process,
 BLAKE, J. J. ROGGE, J. F. Region 2. Office of Director 84/03/12
 2pp 22655 134 24X Fiche 50-366,84/03/12,84003160039
- B403160051 EN-B4-011 notice of violation & proposed imposition of civil penalty in amount of \$20,000 to be issued Action based on failure to control access to vital area ROSANO,R, AXELRADIJ Director's Office, Office of Inspection and Enforcement B4/03/OB ip 22652 019 24X Fiche 50-331.84/03/OB. 8403160051
- 8403190013 PNO-III-84-025 on 840310, unit achieved initial criticality Agreement observed between actual conditions & predicted conditions MALKER, R. BHAFER, W. Region 3, Office of Director 84/03/12 ip. 22665-353 24X Fiche: 50-374,84/03/12,8403190013
- 8403170071 PNO-III-84-026 on 840313, during insp to verify support plate integrity after tube-pulling activities, damage observed to auxiliary feedwater sparger piping in both steam generators Damage may delay May 1984 startup
 DEFAVETTE, R. BDYD. D. Region 3, Office of Director 84/03/13 ip 22669 227 24X Fiche: 50-235,84/03/13,8403190091
- 8403190135 PN8-1-84-002 on 840312, bomb threat received from unidentified caller. Site amergency & safeguards contingency plan requirements implemented Public areas & site protected area searched w/negative findings.

 MADDEN, B. JOYNEN, J. Region 1, Office of Director 84/03/12 1p 22674 352 24X Fiche: 50-220, 84/03/12, 8403190135

- 8403;90284 PND-II-84-022 tircumferential crack found on one of four feedwater notiles during exam of feedwater notiles per NUREQ-0691 Corrective action being evaluated Inspectors monitoring licensee work on regular basis CROMLEY, B R, PANCIERA-V Region 2, Office of Director 64/03/14 ip 22672 279 24X Fiche 50-366.84/03/14,8403190284
- B403170285 PND~I-84-025 on 840313 licenses found crack in emergency diesel generator 103 engine block between cylinders 4 & 5 Crack being investigated through Use of eddy current ineptechniques
 PETRONE. C., EGELOROTH, P. Region I. Office of Director 84/03/14
 Ip 22672 278 24X Fiche 30-322 84/03/14 8403190285
- B403190335 EN-B4-014 on B40316, notice of violation & proposed imposition of civil penalty in amount of \$6.000 issued to licensee Action based on violations involving radiological occurrence w/patential for radiation exposures FLACK.E. AXELRAD.J. Director's Office. Office of Inspection and Enforcement B4/03/13 2pp 22675 027
- 8403190376 PNS-V-84-004 on 840314 licensee notified that results of chemical tests performed on contractor employees suspected of possession or use of controlled substances while onsite indicated positive in two of four tests.

 SCHMANLC A , NORDERHAUG, L R Region 5. Office of Director 84/03/15 ip 22675 216 24X Fische 50-206,84/03/15.8403190376
- 8403200132 Updated PNO-V-84-012A on 840304, radiographer received estimated 3 8 rems to whole body & 72 rems to left hand Caused by radiographer negligence Independent evaluation of incident in progress THOMAS, R D : PANG, J F Region 5. Office of Director 84/03/16 1, 22665 354
- 8403200286 PND-III-84-024A on 840130-0305, patient undergoing Co-60 teletherapy treatments received therapeutic radiation exposure to head 45% in excess of prescribed dose New procedure instituted Region III reviewing case SRENAHKI, D. AXELSON, W. Region 3. Office of Director 84/03/15 2pp 22676 174
- 8403210040 Updated PNO-J-84-021A on 840301, radiographer working at Pilgrim site received radiation overexposure of 550 millifrems Caused by recaupling of source guide tube Enforcement action being evaluated ROME, C . KINNEMAN, J Region 1. Office of Director 84/03/05 ip 22707 015
- 8403210i33 PND-II-84-023 on 840312. State of SC advised of possible overexposure of radiographer & assistant radiographer Caused by assistant radiographer performing duties as radiographer Exposures of 5,000 to 10,000 rem possible TROJANOMERIAR, WOODRUFF,R L. Region 2, Office of Director 84/03/16 2pp 22707 236
- 8403220075 EN-84-D15: on 840320, notice of violation & proposed imposition of civil penalties in amount of #180.000 will be issued to licensee Action based on failure to maintain containment integrity & failure to conduct surveillance CRAIG.J. AXELRAD.J Director's Office, Office of Inspection and Enforcement 84/03/15 2pp 22712 308 24X Fiche: 50-220,84/03/15.8403220075
- 8403230023 PNO-III-84-027; on 840318, diver working on fuel assembly upender received radiation dose to right thigh of 4 5 rems Caused by licenses failure to identify localized high radiation field near upender GREGER, L. R., PAPERIELLO, C. Region 3, Office of Director, 84/03/19 ip 22726 318 24% Fiche 50-255,84/03/19,8403230023
- 8403230094 FNO-I-84-026 on 840313; crack discovered in emergency diesel generator engine, Ultrasonic & eddy current examindicated crack depth of 1 inch & length of 2 inches. State of NY informed PETRONE, C., ESELOROTH, P. Region 1, Office of Director 84/03/20 ip 22724 345 24X Fiche 50-322,84/03/20,8403230094
- 8403230117 PNO-V-84-016 on 840319 hydrogen explosion occurred in main generator Caused by circuit breaker trip shutting down hydrogen seal oil pump, resulting in hydrogen leak Manual safety injection to seal oil tank initiated NARBUT. P. ECKHARDT.J. Region 5, Office of Director. 84/03/20 ip 22730 335 24X Fiche, 50-312, 84/03/20, 8403230117
- 8400270114 EN-83-076A: on B40323, order imposing civil monetary penalties in amount of \$80,000. Action based on failure to classify torus-to-drywell vacuum breaker actuation arm shaft seals under App B. Mitigation of 831115 penalty unwarranted.

 KLINGLER.0. AXELRAD.J Director's Office. Office of Inspection and Enfarcement. 84/03/23. 1p 22774-051 24% Fiche 30-237,84/03/23.

: 1

- 8403290008 PNO-I-84-027 on 840323, through-wall crack discovered on weld on condensate return line from south isolation condenser. No repair or replacement plans formulated Facility currently shut down for refueling & mod TRIPP.L. KEINIG.R. Region 1, Office of Director. 84/03/23. 1p 22803:282 24X Fiche 50-219,84/03/23,8403290008
- 8403300045 PNO-III-84-028 on 840322,Cs-137 source,part of industrial gauge.lost Inspector dispatched to waste treatment plant to review gauge removal & shipment circumstances State personnel sent to facility to search for missing source SRENIAWEKI.D , AXELSON,W Region 3, Office of Director 84/03/23. 1p 22821 102
- 8403300074 PNS-1-84-003 on 840324.male phoned Jersey Central Power & Light Gustomer Svc Ctr & notified that FFA will start demolishing plants Oyster Creek implemented emergency contingency plan & TMI increased security awareness MADDEN. W. JOYNER. J. Region 1. Office of Director 84/03/26. 1p 22822 OBB 24X Fiche 50-000.84/03/26.8403300074
- 8403300112 PNO-II-84-024 on 840326. State of TN informed Region II that state licenses. Guadrex Co. suspected as source of sawer line contentnation detected by DOE State investigation underway TRDJANDWSKI, R Region 2. Office of Director 84/03/27 ip

MISC PUBLIC DOCUMENT ROOM MISCELLANEOUS

- 8310060076 Forwards AEOD engineering evaluation rept, "Review of Events Involving Failures of Power Supply in Instrumentation & Control Sys " Rept should be forwarded to Regions II & III CHIRAMAL, M Reactor Operations Analysis Branch AEOD/E324 83/09/21 SEYFRIT, K V Reactor Operations Analysis Branch ip, 22775 172
- --8310060077 AEOD/E324
 "Review of Events Involving Failures of Fower Supply in
 Instrumentation & Control Sys." engineering evaluation rept
 CHIRAMALIM Director's Office AEOD/E324 83/09/21. 32pp.
- B4030204R4 Responds to 840123 ltr re original issuance & subsequent revs to SRP 9 5 1 & associated branch technical position Matrix of SRP fire protection chronology & SRP revs ancliper telcon M/o SRP revs.

 SPEIS, T P Division of Safety Technology B4/02/17, FLORA, J. W. Flora, J W 3pp 22491 264
- B403050330 Forwards A Lakner 840214 differing prof opinion on reliability matters for transmittal to PDR FLORY.S Office of Nuclear Regulatory Research, Director 84/02/27, Record Services Branch (Document Control Dask), ip 22501:316,
- ---E403050935 Requests NRC reconsider differing prof opinion on reliability matters by appointing peer review group composed of competent & impartial members Reasons for request provided LAKNER, A A Lakner Associates 84/02/14 MINOQUE, R. B Office of Nuclear Regulatory Research, Director. 2pp 22501, 317
- 8403060529 Responds to 840214 memo re 8100 series of insp procedures applicable to power reactor & fuel facility security insp programs Review indicated procedures provide satisfactory working tool for NRC inspectors EISENHUT, D G Division of Licensing 84/02/17. PARTLOW, J. O Division of OA, Safeguards & Inspection Programs (Post 830103) ip 20549 355.
- ---8402030555 Forwards index of 8100 series insp procedures applicable to power reactor & fuel facility security insp programs previously developed by LLL Review & comments requested by 840224 PARTLOW, J © Division of GA, Safeguards & Inspection Programs (Post 830103) B4/01/24 MARTIN.T T Division of Engineering & Technical Programs STOHR, J P. Division of Emergency Preparedness & Materials Safety. HIND, J A Division of Emergency Preparedness & Operational Support, 3pp 22547, 356.
- 8403070103 Responds to 840130 request for NRR assistance in defining components subsua & sys sub; to NRRDS reporting under general description of reactor protective sys/ESF actuation sys
 DENTON, H R Office of Nuclear Reactor Regulation, Director, 84/02/23 HELTEMES, C. J Director's Office. ip 22561:164

- --8402160020 Informs of review of NPRDS data collection for reactor protection sys/ESF actuation sys instrumentation IEEE 8td 603, "IEEE 8td for Safety Sys for Nuclear Power Generating Station," should be used to establish boundaries ROSA: F Instrumentation & Control Systems Branch 84/02/08 MDLAHAN.G M Operating Reactors Assessment Branch 2pp
- --8402240387 Forwards response to Feb memo re NPRDS data collection for ESF actuation sys SPEIS.TP Division of Safety Technology 84/02/13 EIBENHUT.D G. Division of Licensing 3pp 22561 167
- --8402130042 Requests assistance in defining reportable components for use by licensees in reporting engineering & failure data for reactor protection sys/EBF actuation sys instrumentation to MPRDB
 HELTEMES, C. J. Director's Office 84/01/30 DENTON, H.R. Office of Nuclear Reactor Regulation, Director MINOQUER, B. Office of Nuclear Regulatory Research, Director DEYQUNO, R.C. Director's Office, Office of Inspection and Enforcement 2pp 22361 170
- 8403080106 Requests NRC prepare proposed rule on use of high enriched U & plan & schedule for development of steps to improve security measures at domestic nonpower reactors using high enriched U fuel by 84030 for Commission consideration CHILK, B J. Office of the Secretary of the Commission 84/02/23 DIRCKS, M. J. Office of the Executive Director for Operations App 20584, 091
- 8403080271 Recommends that backfitting of anticipatory trips in custom Tech Specs, per JA Dishinski 630727 memo to D0 Eisenhut, be treated as unique generic issue in accordance w/NRR Ofc Ltr 40 Supporting info for anticipatory trip issue encl MIRAGLIA.F. J Assistant Director for Bafety Assessment 84/02/23 MINNERS, W. Safety Program Evaluation Branch Spp 22584 066
- 8403130300 Responds to questions in 831125 ltm to State of NJ Dept of Environ Protection me former Westinghouse facility in Bloomfield, NJ, Contemination memoved. MARTIN, T.T Division of Engineering & Technical Programs 84/02/23 PENN, J. Affiliation Not Assigned. 2pp 22607 124
- --8403130312 Requests response to enc1 831125 ltr to State of NJ Dept of Environ Protection re use of former Westinghouse facility in Bloomfield, NJ PENN, J. Affiliation Not Assigned 84/02/11 ALLAN, J M Region 1. Office of Director 3pp 22607 126.
- 840G140233 Comments on proposed revs to 10CFR73 71 re safeguards reporting requirements Requirements can be relaxed w/o changing NRC ability to respond to incidents on possible generic safeguards problems
 DENTON.H R Office of Nuclear Reactor Regulation, Director 84/03/05 DAVIS.J.Q Office of Nuclear Material Safety & Safeguards, Director 2pp. 22638,021
- 8403150160 Forwards "Trends & Patterns Program Plan, FY84-86 " Analysis of responses yielded listed conclusions from 830802 request for comments on draft version of plan HELTEMES.C.J. Director's Office. AEDD/P402 84/03/02 DENTON, H.R. Office of Nuclear Reactor Regulation, Director DEYOUNG.R.C. Director's Office, Office of Inspection and Enforcement MINOQUE.R.B. Office of Nuclear Regulatory Research, Director. 2pp. 22648 307.
- ---8403130164 "Trends & Patterns Program Plan, FY84-86" ** Director's Office AEOD/P402. 84/03/31. 25pp. 22648 309
- BAC3260134 Requests deletion of C Sedky name from mailing list
 HAMILTON,P Kirkpatrick, Lockhart, Hill, Christopher & Phillips
 B4/03/R2, NRC No Detailed Affiliation Given. 1p. 22758 149
- 8403270155 Informs that as result of review, of 520 items identified in 840215 ltr re-products furnished by Bohney Forge. Carlinville Plant, 510 are sock-o-lets or nip-o-lets. 2-inch nominal pipe size & Chemical Analysis NCA3867. 4 does not apply GERMIN.E F. Pullman, Inc. 84/03/21 JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 4pp. 22769. 151.

- B403270280 Ack receipt of 840227 ltr re leak rate testing proposal Requests meeting w/technical evaluators of "Containment Sys Leakage Testing Requirements" on 840312 Decision on four other proposals should be made as soon as possible REYTBLATT. Z Extran. Inc 84/03/02 THOMPSON.R D Administrative Contracts Branch 3pp 22789 263
- 8403280270 Forwards preliminary case study rept re breaching of encapsulation of sealed well logging sources Comments re technical accuracy requested within 30 days of ltr receipt HELIEMES.C J Director's Office 84/03/07 LEE,J Dresser Atlas Export Sales 1p 22008 068
- --8403280273 Forwards preliminary case study rept re breaching of encapsulation of sealed well logging sources Comments re technical accuracy requested within 30 days of 1tr receipt HELTEMES, C. J. Director's Office 84/03/07 ACREE, E. H. Qulf Nuclear, Inc. 1p 22808 069
- --B4032B027B Forwards preliminary case study rept re breaching of encapsulation of scaled well logging sources Comments re technical accuracy requested within 30 days of itr receipt HELTEMES, C. J. Director's Office B4/03/07 SHELTON, C. D. Shelwell Services, Inc. ip 22808 070
- --8403280282 Forwards preliminary case study rept re breathing of encapsulation of sealed well logging sources Comments re technical accuracy requested within 30 days of ltr receipt HELTEMES.C J Director's Office 84/03/07 SELF,D M Consolidation Coal Co 1p 22808 071
- --8403280288 Forwards preliminary case study rept re breaching of encapsulation of sealed well logging sources Comments retechnical accuracy requested within 30 days of itr receipt HELTEMES,C.J. Director's Defice 84/03/07 SMITH,D A Professional Logging Services, Inc. 1p. 22808 072
- --8403280274 Forwards preliminary case study rept re breaching of encapsulation of sealed well logging sources Preliminary findings, conclusions & recommendations provided to give complete picture of rept Comments requested within 30 days HELTEMES.C.J. Director's Office 84/03/07 DAVIB,J.G. Office of Nuclear Material Safety & Safeguards, Director DEVENDAR, R.C. Director's Office, Office of Inspection and Enforcement MINOGUE,R B. Office of Nuclear Regulatory Research, Director Spp. 22808 073
- --8403280296 Forwards preliminary case study rept re breaching of encapsulation of well logging sources Requests rept be forwarded to States of KY.CO.TX & other states w/large number of well logging licenses HELTEMES.C J Director's Office 84/03/07 KERR.G W Office of State Programs. Director ip 22808 076
- --8403280301 "Preliminary Case Study Rept on Breaching of Encapsulation of Sealed Well Logging Sources " PETTIJOHN,S L Director's Office 84/03/31 47pp 22808 124

NUREO NUREO REPORTS AND RELATED CORRESPONDENCE

- 8402070302 Notifies that Rev 2 to "Rept of Independent Review of Environ Qualification Programs to NUREO-0588" not complete reissue.per 840201 ltr Several rept apps had no changes PETRICK,N A. Standardized Nuclear Unit Power Plant System SLNRC 84-0025 84/02/07 DENTON,H R Office of Nuclear Regulation, Director 1p 22160 174 24X Fiche 50-000,84/02/07,8402090302
- B403010016 Further response to FOIA request for 16 catagories of documents Forwards MJ Dircks B11219 ltr re B10806 sabotage event & special rept to Commonwealth of PA Info partially withheld (ref FOIA Exemption 3) FELTON, J M Division of Rules and Records B4/01/04 SHOLLY, S C Union of Concerned Scientists 2pp 22479 076 24X Fithe 50-334,84/01/04,8403010016
- B403010017 Forwards BSER 4 (NUREC-0887) re operation of facilities W/D encl YOUNGBLOOD, B J Licensing Branch i B4/02/17 EDELMAN. M P Cleveland Electric Illuminating Co 3pp 22479 341 24X Fiche 50-440,84/02/17.8403010017
- BA03010024 Responds to FOIA request for documents re patition for rulemaking PRM-30-31 from Citizens Task Force of Chapel Hill NC Forwards App A documents App B documents completely withheld (ref FOIA Exemption 5) FELTON.J M Division of Rules and Records 84/01/18 SHOLLY, S C Union of Concerned Scientists 4pp 22444 035

- --8403010074 Forwards review comments on draft RES denial of petition for rulemating on emergency planning zone at nuclear power plants.per request General comments encl HULMAN.L G Accident Evaluation Branch 83/01/07 COTA.P C Research & Standards Coordination Branch 7pp 22446 049
- 8403010026 Responds to FDIA request for 1982 NUREO/CR-2815, "NRC, Natl Reliability Evaluation Program (NREP) Procedures Guide " Forwards NUREO FELTON.J M Division of Rules and Records 84/01/04 BETCHER.J L Northern States Fower Co 1p 22477 002
- --8403010041 NUREC/CR-2815 DRFT
 Draft PROBABILISTIC SAFETY ANALYSIS PROCEDURES GUIDE
 BARIA A BUSLIK, A J Brookhaven National Laboratory
 EL-BASSIONI. A Office of Nuclear Reactor Regulation, Director
 FIN A-3382 BNL-NUREC-51559 83/09/01 NRC No Detailed
 Affiliation Given 231pp 22477 003
- B403010050 Third partial response to FOIA request for six categories of documents re facility Forwards App A documents App A documents also placed in PDR App B documents will be placed in PDR upon request Review continuing FELTON, J M Division of Rules and Records B4/01/17 ANDERSON, S I Garvey, Schubert, Adams & Barer App 22446 293 24X Fiche 50-000,84/01/17,8403010050
- --Bil2020204 Forwards new format for nuclear power plants const status rept. NUREG-0030 (yellow book) New format should be used to provide next update info for planned Nov 1981 publication (data as of Sept 30.1981) due Bil120 W/o encl HARTITELD.R A Office of Management and Program Analysis Bi/10/30 DUNN, C N Duquesne Light Co 9pp 22446.305 2AX Fiche 50-000,84/01/17.8403010050
- 8403010066 Forwards safety evaluation to 821223 response to Generic Ltr 82~16 concerning NUREG-0737 Tech Specs Two items closed Items I A 1 1 3 & II E 4 1 under consideration Response acceptable VARGA-S A Operating Reactors Branch 1, Gt.-82~16 84/02/10 OIESLER.C W Wisconsin Public Service Corp 7pp 22480 001 24X Fiche 50~305,84/02/10.8403010064
- 8403010072 Final response to FOIA request for comparative evaluation of nuclear facilities compliance w/NUREG-0578 & NUREG-0737 requirements Forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) FELTON.J M Division of Rules and Records 84/02/09 WEISS.E R Union of Concerned Scientists 4pp 22448 190
- B403010117 Partial response to FDIA request for documents by named individuals re repts, analyses, studies, procedures & sys for measurement of RCS leakage App B documents placed in PDR App A documents already available in PDR Search continuing FELTON, J M Division of Rules and Records 84/01/25 MADDEN, T J Kaye, Scholer, Fierman, Hays & Handler 7pp 22480 026 24% Fiche 50-000,84/01/25,8403010117
- --8403010193 Informs that portable computers obtained for regional ofcs for use in independent measurement of leak rates from PMR cooling sys Draft module & user guide (NUREG-0986) encl M/o encls
 UCRDAN.E*L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/31 TAYLOR, J M Division of GA, Safeguards & Inspection Programs (Post 830103) 4pp 22481:238
- 8403010120 Forwards add1 info to B31230 submittal re NUREO-0737, ltem III. D 1 1. "Frimary Coolant Outside Containment " Rev identifies portions of sys not to be tested & responds to NRC comments Info should close SER Confirmatory Issue 28 TRAMM.TR Commonwealth Edison Co B177N 84/02/22 DENYON, H R Office of Nuclear Reactor Regulation. Director 8pp 22432 002 24X Fiche 50-000.84/02/22,8403010120
- B403010173 Forwards order confirming licenses commitments to implement post-TMI related items per Suppl 1 to NUREO-0737 Schedular commitments reasonable, achievable & will provide timely upgrading of emergency response capability VARGA, & A Operating Reactors Branch I GL-82-33 B4/02/23 HILLIAMS. J J Florida Power & Light Co 4pp 22479 207 24X Fiche 50-250.84/02/23.8403010173
- --B4030101BO Drder confirming licensee commitments to upgrade emergency response capability.per Suppl 1 to NUREG-0737 (Generic Ltr 82-33)
 EISENHUT.D G Division of Licensing QL-82-33 84/02/23, Florida Power & Light Co 6pp 22479 213 24X
 Fiche 50-250,84/02/23,8403010173

- 8403010203 Forwards licensee 840120 & 24 ltrs on Christa-Maria Subcontention 9(4) which questions adherence to guidance of NUREO-0737 re radiation monitoring sys Related correspondence OALLO, J Isham Lincoln & Beale OALLO, J Consumers Power Co ISSUANCES GLA 84/02/27 BLOCH P B, PARIS, O H, SHON, F J Atomic Safety and Licensing Board Panel 4pp 22435 283 24X Fiche 50-155,84/02/27.8403010203
- 8403010235 Submits info or NUREQ-0737. Items II E 1 2. "Safety Grads Auxiliary Feedwater Sys Initiation & Flow Indication" & II K 3 3. "Reporting of Safety & Relief Valve Failures & Challenges." per util 821230 ltr & Generic Ltr 82-16 COUNSIL,W G Northeast Nuclear Energy Co (subs of Northeast Utilities) GOUNSIL,W G Northeast Utilities A03616 84/02/21. MILLER, JR Operating Reactors Branch 3 3pp 22434 188 24% Fiche 50-336, 84/02/21, 8403010235
- 8403010262 Further response to FOIA request for documents re Sandia Contract A-1123 & bibliography used by R Bernero Forwards App A documents FELTON.J H Division of Rules and Records FIN A-1123 83/12/20 RUTLEDGE,P Carolina Environmental Study Group 2pp 22444.069 24X Fiche 50-000,83/12/20,8403010262
- --8403010274 Discusses research rept: NUREO/CR-2239 (Sand81-1549).
 "Technical Guidance for Siting Criteria Development "
 Forwards NUREO/CR-2723 & NUREO/CR-2899 for ref use only, W/o
 encls
 DIRCKS, W J Office of the Executive Director for Operations
 82/11/22 PALLADINO, OILINSKY, AHEARNE Commissioners 2pp.
 22444 076 24X Fichs 50-000.83/12/20,8403010262
- 8403010306 Application for amend to Licenses DPR-33, DPR-52 & DPR-68, changing Tech Espect to lower Group I isolation setpoint for reactor lower water level Wyroprietary NEDE-30012, " MSIV Water Level "Rept withheld (ref iOCFR2 790)
 MILLS.L M' Tennessee Valley Authority TVA BFNP TB 196 84/02/22 DENTON,H R Office of Nuclear Reactor Regulation, Director 3pp 22433 042 24% Fiche 50-259,84/02/22,8403010306
- --8403010313 Proposed changes to Tech Beecs lowering Group 1 isolation setpoint for reactor lower water level W/affidavit * Tennessee Valley Authority 84/02/22 29pp 22433.045 24% Fiche 50-259.84/02/22.8403010306
- 8403010347 Forwards status & justification for nine listed NUREG-0737 & Reg Guide 1 97 items, per 840222 request Analysis of safety parameter display sys will be submitted by 840430 HUKILL.H D General Public Utilities GPU Service Corp 5211-84-2045 84/02/27 E18EM-UT, D G Division of Licensing 2ipp 22433 018 24X Fiche 50-287,84/02/27,8403010347.
- B403010351 Summary of B40209 meeting w/util, Science Applications, Inc.

 MPR Assoc & MIT re NRC comments on detailed control room
 design review program plan, per requirements of Suppl 1 to
 NVREG-0737 Viewgraphs encl
 PAULSBN.W A Operating Reactors Branch 5 LSD5-B4-02-057
 B4/02/29 Operating Reactors Branch 5 36pp 22432·329 24X
 Fiche: 50-255, 84/02/29, 8403010351
- B4030103B4 Forwards SER for SEP Topic II-3 C, "UHS " Issue adequately resolved based on review of B31114 ltr Resolution will be incorporated in suppl to integrated plant safety assessment rept (NUREO-0824) CRUTCHFIELD.D. Operating Reactors Branch 5 LGO5-84-02-036 B4/02/2B CDUNBIL: WO Northeast Nuclear Energy Co (subs of Northeast Utilities) App 22434 061 24% Fiche 50-213.84/02/28, 8403010384
- B403010371 Summarizes findings from audit of TMI action items during wk of 831024 Item II B 3, "Post-Accident Sampling Sys (PASS)." findings are of most concern Corrective actions listed COUNSIL, W G , GPERA, J F Connecticut Yankse Atomic Power Co B10757 B3/11/23 MURLEY.T E Region 1, Office of Director App 22434 068 24x Fichs.50-213,83/11/23,8403010371
- B403010400 Submits info re pressurizer heater transformer barrier design, per License Condition 2 C.7 Missile protection structure will be seismically anchored on concrete floor slab HILLIAMS, J W Florida Power & Light Co L-84-44 B4/02/27 EISENHUT, D G Division of Licensing 3pp 22434 026 24X Fiche 50-389,84/02/27,8403010400
- 8403010516 Summary of 840130-31 meetings w/util at site in Dauphin County.PA re status, schedule & scope of implementation of selected NUREG-0737 action items Agenda & viewgraphs encl
 VAN VLIET, J Operating Reactors Branch 4, 84/02/22 Operating Reactors Branch 4 130pp 22443 303 24X Fiche 50-289,84/02/22;8403010516

- 8403020005 Forwards info requested in SSER 5 (NUREO-0857) re testa performed for C-E on load limiting devices in reactor vessel lower key horizontal supports VAN BRUNTLE E Arizona Public Service Co ANPP-28836-WFG/84020/10 KNIGHTON.0 Licensing Branch 3 9pp 22442 201 24) Fiche 50-528,84/02/10,8403020005
- 8403020014 Partial response to FOIA request for seven categories of documents re NRC regionalization program App A documents in PDR. Review of remaining documents incomplete FELTON, J M Division of Rules and Records 83/12/16 LOWENTHAL, J Nuclear Information & Resource Service 3pp 22492 248 24X Fiche 50-000, 83/12/16, 8403020014
- --8403020035 Forwards final draft program guidance for FY83-85, per NURCO-0885, "NRC Policy & Planning Guidance " Rev of current ofc operating plan, incorporating Commission Aug 1982 budget decisions & program guidance.expected by 821030 DIRCKS, W J Office of the Executive Director for Operations 82/09/20 NRC No Detailed Affiliation Given 19pp 22492 294 24 Fiche 50-000,83/12/16,8403020014
- --8403020032 Provides program guidance for FY83-86, developed in support of NUREQ-0885, Issue 2, "NRC Policy & Plenning Quidance 1983" Correct of operating plan should be revised to incorporate encl comments
 DIRCKB.W J Defice of the Executive Director for Operations
 63/05/20. NRC NO Detailed Affiliation Given. 20pp
 22493 340 24X Fiche 50-000,83/12/16,8403020014.
- 8403020145 NUREG-0936 VO2 NO4 NRC REQULATORY AGENDA Quarterly Report, October-December 1983
 - # Division of Rules and Records 84/02/27 180pp 22482 212
- B403020171 Forwards order confirming util commitments to implement requirements of Suppl 1 to NUREO-0737 Order based on B30418 & 0823 ltrs in response to Generic Ltr 82-33.

 VAROA.8 A. Operating Reactors Branch 1 GL-82-33 84/02/21 BAYNE.J P. Power Authority of the State of New York 4pp R2491:091 24X Fiche 50-286,84/02/21.8403020171.
- --8403020175 Order confirming licensee 830418 & 0823 commitments on emergency response capability.per requirements of Suppl 1 to NUREO-0787 & Generic Ltr 83-33 EISCHUT, D O Division of Licensing GL-82-33 84/02/21 Power Authority of the State of New York 6pp 22471 075 24X Fiche 50-286, 84/02/21, 8403020171
- 8403020184 Requests identification of any potential problems or items that cannot be met within time frame required to mest Sept 1984 goal for completion of NUREO-0737 items VARQA: B. A Operating Reactors Branth i. 84/02/22, WILLIAMS, J Florida Power & Light Co 2pp 22495 005 24X Fiche: 50-250,84/02/22,8403020184
- B403020207 Forwards order confirming licensee commitments on emergency response capability, based on info provided in util 830414 & 0825 responses to Generic Ltr B2-33, Buppl 1 to NUREG-0737 BCHMENCER, A. Licensing Branch 2 GL-B2-33 B4702/21 FARRAR, D. Commonwealth Edison Co. 2pp 22474 324 24X Fiche 50-373,84/02/21,84/03/202007
- --8403020221 Order confirming licensee 830414 & 0825 commitments on emergency response capability, per Generic Ltr 82-33, 8uppl 1 to NUREG-0737 EISENHUT, D G. Division of Licensing GL-82-33, 84/02/21 Commonwealth Edison Co 7pp 22494-326 24X Fiche. 50-373, 84/02/21, 8403020207
- 8403020287 Forwards "Rept on Special Lifting Devices," per 831111 response to SER Open Item 59 Rept covers design. Fabrication & initial acceptance testing of six special lifting devices listed in Table 3 of 810717 ltr.

 MCCAFFREY.B R. Long Island Lighting Co SNRC-1007 84/02/21 DENTON, H R. Office of Nuclear Resctor Regulation, Director 3pp 22441.268. 24X Fiche.80-322.84/02/21.8403020287
- B403020289 Forwards resolution of SER Confirmatory Issus 11 re util B30218 & 0316 submittals concerning TMI Action Items I C 2 & I.C.5.
 YOUNGBLOOD, B J. Licensing Branch 1 84/02/21 GARY, R.J Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 3pp. 22492:241. 24% Fiche. 50-445, 84/02/21,8403020289
- 8403020295 Natifies that proposed Tech Spec for certain NUREG-0737 items per Generic Ltr 83-37 will be submitted by 840401.
 GIESLER.C.W. Wisconsin Public Service Corp NRC-84-33. 84/02/28 EISENHUT, D. 0. Division of Licensing 2pp 22440 066 24X Fithe: 50-305: 84/02/28. 8403020295

- 8403020313 Forwards add1 comments to Quidelines 5a,7a & 7b of technical evaluation rept in response to NRC 820630 ltr re control of heavy loads, per Generic Ltr 81-07
 MILLS,L M Tennessee Valley Authority GL-81-07 B4/02/28
 ADENSAM,E Licensing Branch 4 lipp 22439 190 24%
 Fiche 50-327,84/02/28,8403020313
- 8403020317 Forwards Rev 10 to "Analysis of Hydrogen Control Measures at McOuirc Nuclear Station," per SSER 7 (NUREG-0422) TUCKER.H B Duke Power Co 84/02/29 DENTON,H R Office of Nuclear Reaction Regulation, Director 2pp 22441 216 24X Fiche 50-000.84/02/29,8403020317
- --8403020321 Rev 10 to "Analysis of Hydrogen Control Measures at McGuire Nuclear Station" * Duke Power Co 84/02/29 50pp 22441 218 24X Fiche 50-000,84/02/29,8403020317
- B403020327 Requests that completion date of emergency operations facility be extanded from B50201 to B50628, per B30415 & OB24 ltrs & NUREO-0737, Buppl 1 Completion date dues not cover safety parameter display sys installation BAYNE, J P Power Authority of the State of New York JPN-84-15 B4/02/27 VABGALLO, D B Operating Reactors Branch 2 2pp 22439 205 24X Fiche 50-333,84/02/29,8403020327
- 8403020343 Forwards BALP rept for Oct 1982 Sept 1983 Maint of low personnel error rate merits continued attention MURLEY.T E Region 1. Office of Director 84/02/29 LUNDVALL.A E Baltimore Gas & Electric Co 3pp 22439 217 24X Fiche 50-317.84/02/29.8403020343
- --8403020345 SALP rept for Oct 1982 Sept 1983 * Region 1, Office of Director IEB-83-04 83/12/12 57pp 22439 220 24X Fiche 50-317,84/02/27,8403020343
- 8403020392 FOIA request for Chilk 821019 memo to Dircks re postaccident sampling sys (NUREQ-0737. Item II 8 3) to be placed in PDR PEDRO, J NUS Corp CD-LIS-83-048 84/01/26 Division of Rules and Records ip 22491 285 24X Fiche 50-289.84/01/26.8403020392
- 8403020375 Responds to FOIA request for Chilk 821019 memo to Dircks re 8ECY-82-384 concerning status of TMI-1 NUREG-0737 items Forwards document Document also available in PDR FELTON.J M Division of Rules and Records 84/02/15 PEDRO,J NU Carp 1p 22491 286 24% Fiche 50-287,84/02/15,8403020395
- 8403020440 NUREC-0072 RD1 EDO PROCEDURES MANUAL. * Office of the Executive Director for Operations 84/01/31 135pp. 22491 288
- 8403050009 Forwards request for addl info re NUREG-0737. Item II B 3. "Post-Accident Sampling Sys." to complete review Requests response within 45 days of ltr receipt CRUTCHIELD, D Operating Reactors Branch 5 LS05-84-02-057 84/02/29 LINDER.F Dairyland Power Cooperative 3pp 22490 187 24% Fiche 50-409.84/02/29,8403050009
- 8403050016 Forwards Rev 7 to FSAR site addendum (filed in PDR Category K) & Rev 7 to radiological emergency response plan (filed in PDR Category F)
 9CHNELL, D F Union Electric Co ULNRC-751 B4/03/01 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 5pp 22485 304
 24X Fiche: 50~483, 84/03/01, 8403050016
- --8403050019 Rev 7 to radiological emergency response plan * Union Electric Co 84/03/01 354pp 22486 238 24X Fiche 50-483,84/03/01,8403050016
- 8403050020 Responds to FOIA request for documents re PASNY submittal on sys interactions, repts evaluating submittal & list of repts/analyses from LLL evaluating PASNY sys interaction program Forwards App A documents FELTON, J M Division of Rules and Records 83/12/07 SHOLLY, S Union of Concerned Scientists 6pp, 22525 098 24X Fiche, 50-000, 83/12/07, 8403050020
- -8403050029 NUREG/CR-2050
 SYSTEMS INTERACTION EVALUATION PROCEDURE FOR APPLICATION TO
 INDIAN POINT-3
 LIM.J J. ALESSO, H F., RICE, T R. Lawrence Livermore Laboratory
 FIN A-0405. UCRL-53024 B1/04/30 NRC No Detailed
 AFFIliation Given 50pp 22526 089 24X Fiche. 30-000, 83/12/07,
 8403050020
- 8403050053 Summary of 840203 meeting w/util at site re review of NUREG-0737 items Agenda, attendance list & handouts encl VISSING, 6 S. Operating Reactors Branch 4 84/02/23 Operating Reactors Branch 4 24pp 22527 332 24x Fiche 50-346, 84/02/23, 8403050053

- 8403050085 Discusses analyses on 22 safety relief valve (SRV) discharge lines per 821229 request to address questions re SRV test program per FMI Item II D I Analyses indicate supports & piping geometry adequate OUCHA.L T Georgia Power Co NEO-84-040 84/02/10 STOLZ, J F Operating Reactors Branch 4 2pp 22490 007 24X Fiche 50-321,84/02/10.8403050085
- 840305009B Forwards "Rept on Task 0508B, Pressurizer Relief Valve Discharge Piping Qualification for Calvert Cliffs, Unit 2, " per IMI Item II D 1 LUNDVALL, A E Baltimore Gas & Electric Co 84/02/29 MILLER, J R Operating Reactors Branch 3 3pp 22484 167 24X Fiche 50-318.84/02/29,8403050098
- --8403050100 "Rppt on Task 05088,Pressurizer Relief Valve Discharge Piping Gualification for Calvert Cliffs,Unit 2 " Approx nine of 84 existing pipe supports may experience stress PATELR B Bechtel Corp 84/02/14 162pp 22484 170 24X Fiche 50-318,84/02/29,8403050098
- --8403050103 CEN-248(B) R02
 Rev 2 to "Pressuriter Bafety Valve Operability Rept"
 * Combustion Engineering, Inc 84/01/31 50pp 22484 332 24X
 Fiche 50-318,84/02/29,8403050098
- 8403050105 Advises that operability testing of RCS vent valves will be performed per requirements of ASME. Section XI. Subsection IMV-3410. for Category B valves.per NUREO-0737. Item II B I COUNSIL. W G Connecticut Yankee Atomic Power Co COUNSIL. W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL. W G Northeast Utilities B II 043 84/02/21 MILLER, J R Operating Reactors Branch 3 CAUTCHFIELD. D Operating Reactors Branch 5 29p 22488 043 24X Fiche 50-000, 84/02/21, 8403050105
- 8403050107 Forwards "Abnormal Transient Operating Quidelines.Fart I Procedural Ouidelines." "Part II-Vol 1 Fundamentals of Reactor Control "&" Part II-Vol 2 ," per 830415 schedule for completing Buppl 1 to NUREQ-0737 requirements CROUSC.R P Toledo Edison Co 1030 84/03/01 EISENHUT.D Q Division of Licensing 35pp 22523 221 24X Fiche 50-346.84/03/01.8403050107
- --8403050110 Procedure 74-1125531-00, "Abnormal Transient Operating Guidelines.Part I Procedural Guidelines " * Bubcock & Wilcox Co 82/10/12 Bapp 22523 256 24X Fishe 50-346,84/03/01,8403050107
- --8403050114 Procedure 74-1125331-00. "Abnormal Transient Operating Guidelines.Part II-Vol 1 Fundamental of Reactor Control for Abnormal Transients " * Bebtock k Wilcox Co 82/07/06 245pg 22523 342 24X Ficho 50-346.84/03/01.8403050107
- --8403050118 Procedure 74-1125531-00. "Abnormal Transient Operating Guidelines:Part II-Vol 2 Discussion of Selected Transients " * Babcock & Wilcox Co 82/07/06 230pp 22384 227 24X Fiche 50-344,84/03/01.8403050107
- B403050121 Forwards notice of consideration of issuance of amend to License DER-6, based on B11215 % revised B31216 applications Amend changes Tech Spaces re stack gas monitoring sys CRUTCHF1ELD, D. Operating Reactors Branch 5 LSOS-B4-02-048 B4/02/32 VANDEWALLE, D. J. Consumers Power Co. 4pp. 22488 032 248 Fiche 50-155, 84/02/32, 8403030121
- 8403050161 Forwards "Structural Steel Survivability Evaluation." in response to 840209 request for add1 info (RAI 280 26), per SER Open Item 14

 KEMPER, J. S. Philadelphia Electric Co. GDVT 1-1 84/02/29.

 8CHWENCER, A. Licensing Branch 2. 3pp. 22483-037 24X

 Fiche 50-352,84/02/29,8403050161
- --B403050163 "Structural Steel Survivability Evaluation " Rev 1 to "Comparison of Philadelphia Electric Co Heat Balance Model w/NURCG/CR-3192" enc! # Philadelphia Electric Co 84/02/24 372pp 22483 040 24X Fiche 50-352,84/02/29.8403050J61
- 8403050229 Submits review of postraccident sampling sys, Item II B 3 Ten of 11 criteria met Remaining criterion re procedure for estimating extent of core damage based on radionuclide evaluation, acceptable on interim basis
 MILLER, R Operating Reactors Branch 3 84/02/27 STEWART, W L Virginia Electric & Power Co dpp 22528 001 24X
 Fichs 50-000,84/02/27,8403050229

- 8403050233 Notifies that Class IV rather than Class III fee appropriate for review of 840127 application for amend to License DPR-49, changing Tech Specs re NUREG-0737 & min staffing requirements
 DIGGS.R M License Fee Management Branch 84/02/29 ARNOLD, B. Iowa Electric Light & Power Co 122527 357 24X
 Fiche 50-331,84/02/29,8403080233
- 8403050238 Forwards Amends 68 & 62 to Licenses DFR-42 & DFR-60, respectively & safety evaluation Amends revise Tech Epecs re emergency air treatment sys & electric hydrogen recombiners DIIANNI.D C Operating Reactors Branch 3 84/02/21 MUSOLF, D H Northern States Power Co 2pp 22527 188 24X Fiche 50-282,84/02/21.8403050238
- B403050273 Requests provision of alternative surveillance to replace requirement presently in Tech Specs re turbine overspeed protection Proposed alternative maint, calibr & testing program should assure that protection sys operable YOUNOBLOOD B. J. Licensing Branch 1 B4/02/27 GARY, R. J. Teras. Utilities Electric Co. (Formerly Texas Utilities Generating Co.). 4pp 22501 109 24X Fishe 50-445,84/02/29,8403050273.
- 8403050369 Summary of 840202 meeting w/util, HTI. Easex & Bechtel in Bethesda. MD re control room design review.per Suppl 1 to NURSEO-0737 Further clarification required in task analysis area Viewgraphs encl WAGNER. D H Liconsing Branch 2 84/02/24 Licensing Branch 2 25pp 22527 284 24X Fiche 50-354.84/02/24.8403050369
- B403040039 Board Notification 84-041 forwards util 840202 updated proposed resolutions & commitments per integrated assessment of plant Several issues under litigation before ABLB reproposed expansion of spent fuel pool storage capacity MIRAGLIA.F J Assistant Director for Safety Assessment 84/02/24 BLOCH.P B . PARIS.O H . SHON.F J Atomic Safety and Literasing Board Panel 5pp 22548 283 24x Fiche 50-155,84/02/24.8403060039
- 8403060044 Forwards SER for NUREO-0737, Item II B 2 2 re plant shielding Actions taken or planned for post-accident vital area access satisfy requirements of NUREO-0737 VARGA, S A Operating Reactors Branch 1 84/02/28 BAYNE, J P Power Authority of the State of New York App 22528:318 24% Fichs 50-286,84/02/28,8403060044
- 8403040085 FOIA request for documents re Equipment Qualification Branch request to DELD for clarification of 10CFR50 49, HOLIMAN.P M Engineering Planning & Management, Inc P13503.004 83/12/28 FELTON.J M Division of Rules and Records 1p 22528 213
- B403060086 Approves state & local plans & preparedness for elerting & protecting public in event of radiological emergency Approval conditional on verification of alert & notification sige per criteria of App 3 of NURECO-0534/FEMA-REP-1: Rev 1. SPECK. S W Foderal Emergency Management Agency 84/02/15 DIRCKS W J Office of the Executive Director for Operations 1p 22516 300 24X Fiche 50-250.84/02/15,8403060086
- 840306009: Responds to FOIA request for records prepared by NRC re request to OELD for clarification of iOCFR50 49 Forwards App A documents No addl records located subj to request FELION.J M Division of Rules and Records 84/01/23 HOLZMAN.P M Engineering Planning & Management, Inc. 2pp 22528 214
- --8309120556 Requests comments on interpretations of Section 50 49 of 10CFR50. "Environ Qualification of Electric Equipment Important to Bafety for Nuclear Power Plants"
 VOLLMER,R H Division of Engineering 83/08/31 DLM9TEAD,W J Regulations Division 3pp 22528 216
- --8403060095 Responds to specific questions raised in 830831 request re legal interpretation of 10CFR50 49, "Environ Qualification Rule." OLMSTEAD, W. J. Office of the Executive Legal Director 83/10/04 VOLLMER, R. H. Division of Engineering 3pp 22528, 219
- --8309120556 Requests comments on interpretations of Section 50 49 of 10CFR50, "Environ Gualification of Electric Equipment Important to Safety for Nuclear Power Plants"
 VDLLMER, R M Division of Engineering 63/08/31, OLMBTEAD, W J Regulations Division Spp 22528 216

- 8403060112 Forwards "Safety Parameter Display Sys Parameter Selection Evaluation & Implementation Plan." per Generic Ltr 82-33.
 "Buppl 1 to NUREO-0737 Requirements for Emergency Response Capability"
 WILLIAMS, J W Florida Power & Light Co L-84-48 84/03/01 EIBENHUT.D 0 Division of Licensing 1p 22518 322 24X Fishe 50-335.84/03/01.8403060112
- --B403060116 "Safety Parameter Display Sys Parameter Selection Evaluation & Implementation Plan"

 * Florida Power & Light Co GL-82-33 84/03/01 10pp
 22518 323 24X Fiche 50-335,84/03/01,8403060112
- 8403060125 Forwards summary of identified technical avaluation rept deficiencies re environ qualification of safety-related slectrical equipment, defined by IE Bullstin 79-018 & NOREG-058B, respectively Encl withheld (ref 100FR2 790) CLAYTON, F. L. Alabama Power Co. IEB-79-018 84/02/29 VAROA, S. A. Office of Nuclear Reactor Regulation, Director 4pp 22519 036 24X Fiche 50-348,84/02/29,8403060125
- 8403060160 Forwards results of chemical analysis techniques performed on std test matrix solution as required by NUREG-0737. Action Item II.8. 3.per util 831122 ltm. Response to Criterion 10 of draft 8ER complete HUKILL, H D General Public Utilities GPU Service Corp 8211-84-2035 84/02/29 870LZ, J F Operating Reactors Branch 4 8pp 22516 263 24X Fiche 50-289, 84/02/29, 8403060160
- 8403060167 Advises that NUREG-0737. Action Items II K 3 30 & II K 3 31 considered complete, based on 840104 telcon between NRC & GE Licensee need only identify to NRC ref on docket to GE Topical Rept NED0-20366 or NED0-20366P ZIMMERMAN, S R. Carolina Power & Light Co NLB-84-076 84/02/27 VASBALLO, D 8 Operating Reactors Branch 2, 2pp 22518 334 24X Fiche: 50-324, 84/02/27, 8403060167
- 8403060186 Forwards safety parameter display sys implementation plan & parameter selection rept.per 830415 commitment Rept meets requirements of Generic Ltr 82-33 re Suppl 1 to NUREG-0737 WILLIAMS, J. W Florida Power & Light Co L-84-47 84/03/01 ETSENHUT, D Q Division of Licensing ilpp 22517 001 24X Fiche, 50-389, 84/03/01,8403060184
- 8403060233 Forwards design info, instrument accuracy & response times to assist in post-implementation review of containment water level monitoring (NURE9-0737, Item II F. i), per 830719 request MUKILL.H.D. General Public Utilities GPU Service Corp 5211-84-2043 84/03/01 STOLZ, J F. Operating Reactors Branch 4 App. 22517:317 24X Fiche 50-289,84/03/01,8403060233
- 8403060264 Forwards "Program Plan for Detailed Control Room Design Review: "including proposed schedule for implementation. per NUREO-0737, Suppl 1 requirements PILANT, J M Nebraska Public Power District NLS8400074 84/03/01 EISENHUT, D 9 Division of Licensing ip 22515 225 24X Fiche. 50-298.84/03/01,8403060264
- ---8403060274 "Program Plan for Detailed Control Room Design Review "
 * Nebraska Public Power District 84/02/29 65pp 22515 226
 24X Fiche 50-298,84/03/01,8403060264
- 8403060297 Lists concerns re operator license exam review process. Proper security measures can be taken to prevent dissemination of questions to license applicants during exam Requests NRC reconsider new guidance.per NURE9-1021 CAREY.J J Duquesne Light Co 84/02/24 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 22511 134 24X Fiche: 50-334, 84/02/24, 8403060297
- 8403040313 Provides comments on DEB (NUREO-1026) Justification for not providing design analysis of seismic event requested ETCHISON,D Illinois, State of, Dept. Nuc Safety (formerly Dept Public Health) 84/02/22 Division of Licensing 3pp 22515.330 24X Fiche 50-456.84/02/22.8403060313
- 8403060323 Notification of CROR Meeting 38 on 840315 to discuss proposed NUREO-0801, "Evaluation Criteria for Detailed Control Room Design Review " Requests of directors limit attendance of staff at CROR meetings.

 STELLO, V. Committee to Review Generic Requirements 84/03/02 MATTBON, R. J. Office of Nuclear Reactor Regulation, Director, JORDAN, E. Director's Office, Office of Inspection and Enforcement, CUNNINGHAM, R. Office of Nuclear Material Safety & Safeguards, Director ip, 22513 335
- 8403060354 Forwards descriptions of Reg Quide 1 97 requirements & schedule for implementation of emergency response capability; per MUREG-0737, Suppl 1 PILANT, J. M. Nebraska Public Fower District NLS8400073 84/03/01 EISENHUT, D. 0. Division of Licensing 19pp 22515 311 24X Fiche: 50-298, 84/03/01, 8403060354

- B403060364 Revised application for amend to License DPR-72, changing Tech Specs to reflect addition of two independent, in-place hydrogen monitors Certificate of Svc encl WESTAFER, G R Florida Power Corp 3F0284-13 B4/02/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp 22512 297 24x Fiche 50-302.84/02/24, B403060364
- --B403060368 Proposed Tech Specs reflecting addition of two independent, in-place hydrogen monitors, in response to NURE9-0737, Item II F 1

 * Florida Power Corp GL-83-37 B4/02/24 9pp 22511 303 24X Fiche 50-302,84/02/24,8403060364
- 8403060399 Provides add1 info re reactor coolant gas vent sys, per NUREC-0737. Item II B ! Sys used to purge nitrogen accumulated in reactor vessel head on 831118 RCS will be vented periodically to reduce nitrogen pressure MEDFORD M O Southern California Edison Co 84/03/02 CRUTCHFIELD. D Operating Reactors Branch 5 3pp 22518, 271 24x Fiche 50-206, 84/03/02.8403060399
- B403060430 Provides preliminary estimates for emergency operations facility mode to raise radiation protection factor to greater than or equal to five.per NUREO-0696, in response to NRC 840214 request Util will not implement mods MARSHALL.J R Arkenses Power & Light Co OCANO28413 84/02/29 STOLZ.J F. Operating Reactors Branch 4 MILLER.J R Operating Reactors Branch 4 Fig. 18 Operating Reactors Branch 4 Fig. 18 Operating Reactors Branch 4 Fig. 18 Operating Reactors Branch 3 2pp 22518 192 24X Fiche.50-313.84/02/29, 8403060430
- B403060439 Forwards marked-up procedures generation package for implementing symptom-based emergency operating procedures, per Suppl 1 to NUREG-0737, for comment LEMPGLS,T E Niagara Mohawk Power Corp 84/03/01 VASSALLO,D B Operating Reactors Branch 2 122pp 22508 143 24X Fiche 50-220,84/03/01,8403D40439
- 8403060447 Forwards rev to 830314 order, changing completion dates for NUREO-0737, Items II F 1 1, "Noble Cas Effluent Monitors" & II F 1 2, "Iodine Monitors," from 831231 to startup for fuel Cycle 7
 MILLER, J R. Operating Reactors Branch 3 84/02/21 WITHERB, B D Portland General Electric Co 3pp 22552 023 24X
 Fiche 50-344, 84/02/21, 8403060447
- --B403060449 Rev to B30314 order extending completion date for Items
 II F i i k II F i 2 from B31231 to startup for 1984
 refuging outage
 EISENHUF.D G Division of Licensing B4/02/21 Partland
 General Electric Co 4pp 22552 026 24X Fiche 50-344,84/02/21,
 RB403060A44
- 8403060470 Discusses negotiations w/licensee on NUREG-0737 items re emergency operating procedures.per 830601 k 0712 memos REGUA.0 Operating Reactors Branch 1 83/09/09 EISENHUT.D G Division of Licensing 1p 22549 326 24% Fiche 50-261.83/09/09. 8403060470
- B403060473 Requests espected completion dates for NUREG-0737 items & justification for proposed schedule for items that will not be completed by June 1984 by 840227 EIBENHUT, D © Division of Licensing 84/02/22 HUKILL, H D Ceneral Public Utilities 0PU Service Corp. 4pp 28552 325 24X Fiche. 50-289;84/02/22.84-03060473
- 8403060476 Requests expected response date for each TMI action item listed in encl within 10 days EJBENNUT, D 0 Division of Licensing 84/02/21 HUKILL, H D General Public Utilities — GPU Service Corp 5pp 22552 320 24X Fiche, 50-289, 84/02/21, 84033060476
- B4030604/7 Natification of 840313 meeting w/util in York County, BC to conduct confirmatory site visit per Section 13 & of BRP (NURED-OBGO). JABBDUR, K N Licensing Branch 4 84/02/24 ADENSAM, E 0 Licensin Branch 4 3pp 2254
- B403060508 Forwards order confirming util commitments to implement requirements of Suppl 1 to NUREO-0737 Order based on commitments contained in util 840415 & 830824 responses to 821217 Generic Ltr 82-33 VARQA: 8 A Operating Reactors Branch 1 QL-82-33 B4/02/21 UTLEY; E Carolina Power & Light Co 3pp 22552 165 24X Fiche 50-261; 84/02/21, 8403060508
- --B403060510 Order confirming licensee commitments on emergency response capability, per Generic Ltr 82-33, Suppl 1 to NUREO-0737 E1BENHUT, D & Division of Licensing, GL-82-33 64/02/21, Carolina Power & Light Co 6pp 22552,168 24X Fiche, 50-261,84/02/21,8403060508

6403060533 NUREC/CR-3067 CALIBRATION SOURCES FOR THE C-M COUNTER USED WITH THE BNL AIR SAMPLER AIR SAMPLER
HUCHTON.R L , BIRD,8 K , TKACHYK.J W Exxon Nuclear Co ,
of Exxon Corp) FIN A-6347 ENICO-1125 84/02/29
Farility Operations 52pp 22522-064 Division of

8403060534 Notification of 840315-16 meetings w/util in Sweetwater, TN to conduct confirmatory site visit per Section 13 6 of SRP (NUREC-OBOO)
KENYON, T. J. Licensing Branch 4 84/02/28 ADENSAM, E 0 Licensing Branch 4 3pp 22552 317 24X Fiche 50-390,84/02/28,8403060534

DADSOYANGS NUREO/CB-SACS

403070093 NUREC/CR-3607
RADIONUCLIDE DISTRIBUTIONS AND MIGRATION MECHANISMS AT
SHALLOW LAND BURIAL SITES 1982 Annual Report of Research
Investigations On The Distribution, Migration And Containment
Of Radionuclides At Marey Flats, Kentucky
KIRBY, L. J. Battelle Memorial Institute, Pacific Northwest
Laboratories FIN B-2291 84/02/29 Division of Health, Siting &
Waste Management 80pp Available at NRC \$5.50 22563 229

8403070098 FDIA request for V Stello 830803 memo re task group to study surveillance testing in Tech Specs & 830916 & 1004 ltrs from JJ Sheppard of Hestinghouse Duners Group to be placed in PDR Documents referenced in NUREO-1024 PEDROJ NUS Corp CD-LIS-83-073 84/02/02 Division of Re and Records. 1p. 22561 152 Division of Rules

BADDO70104 NUREC-0675 S17

BAFETY EVALUATION REPORT RELATED TO THE OPERATION OF DIABLO CANYON NUCLEAR POWER PLANT, UNITS 1 AND 2 Docket Nos 50-275 And 50-323 (Parific Gas And Electric Company)

* Division of Licensing B4/02/29 22p. Available at NRC CANTER AVAILable AT NRC CANTER S14/02/29, 8403070104

8403070109 NUREG/CR-3401 MANAGEMENT AND URGANIZATIONAL ASSESSMENTS A REVIEW OF MANAGERINI AND DROAMIZATIONAL ASSESSMENTS. A REVIEW OF SELECTED ORGANIZATIONS NADEL, M V , KERWIN, C M Battelle Human Affairs Research Centers Battelle Memorial Institute, Pacific Northwest Laboratories FIN B-2360 PNL-4813 84/02/29 Division of Human Factors Safety 42pp Available at NRC. \$3 75 22561 172 FIN

8403070114 NUREC/CR-3649 (03070]]A NORG/CK-3649
DYNAMIC TESTING OF AS-BUILT CIVIL ENGINEERING STRUCTURES A REVIEW AND EVALUATION
SRINIVASAN.M G , KOT.C A , HSIEH.B J Argonne National Lebore
FIN A-2217 ANL-83-20 84/01/31 Division of Engineering
Technology 117pp 22562 055 Argonne National Laboratoru

B403070115 NUREG/CR-3091 VO3
REVIEW OF WASTE PACKAGE VERIFICATION TEBTS Semiannual Report
Covering The Period April-September 1983
SOO, P. Brookhaven National Laboratory FIN A-3167
BNL-NURGG-51630, 84/02/29 Division of Waste Management 164pp
Available at NRC 85 50 22562 176

8403070118 NUREG/CR-3449 403070118 NOREG/CH-3449
LABORATORY EVALUATION OF LIMESTONE AND LIME NEUTRALIZATION
OF ACIDIC URANIUM MILL TAILINGS SOLUTION Progress Report
OP172.8 E DODSON.M E . SERNER J Battelle Memorial Institute,
Pacific Northwest Laboratories FIN B-2370 84/02/29 Division
of Health, Siting & Waste Management 50pp Available at NRC
44 00 22562 004

8403070121 NUREG-J022 801 LICENSEE EVENT REPORT SYSTEM Description Of System And Guidelines For Reporting HEBDON.F J. Director's Office 84/02/29 58pp Available at NRC 44 80. 22561 308

8403070157 Application supplementing 820316,830623 & 0906 requests for amend to Licenses DPR-62 & DPR-71.consisting of Tech Spec changes for Item 9 re isolation of HPC1 & RCIC mod (NUREO-0737.Action Item II X.3 15) & Generic Ltr 83-02 HOWE.P W Carolina Power & Light Co GL-83-02 84/02/28 VASSALUO.D B Operating Reactors Branch 2 2pp 22538 316 24X Fiche 50-324,84/02/28,8403070157.

-8403070162 Proposed Teck Spec changes for Item 9 re isolation of HPCI & RCIC mod (NUREO-0737. Action Item II K 3 15) & Generic Ltr 83-02 .02 Carolina Power & Light Co GL-83-02 B4/02/ i38-318 24X Fiche:50-324,84/02/28:8403070157 B4/02/28 31pp 22538-318

8403070215 Responds to FOIA request for documents re 830717 meeting to discuss steam erosion issue in facility proceeding & TM Novak 830825 memo on subj Forwards App A documents Documents 4 & 5 withheld (ref FOIA Exemption 5) FELTON, J. M Division of Rules and Records 84/01/23 HIATT, S Ohio Citizens for Responsible Energy 3pp 22563 220

--B403070221 Requests confirmation on lead responsibilities for NGGO/0221 Requests confirmation on lead responsibilities for finalling NRC position re steam erosion contention issue Responsibility should be shared by Machanical Engineering Branch Meteorology & Effluent Treatment Branch NGVAK.TM Assistant Director for Licensing 83/08/25 KNIGHT.JP Assistant Director for Comp & Btructures Engineering (Post 830201) 2pp 22563 224

8403070255 Application for amend to Licenses DPR-24 & DPR-27 Amend incorporates changes to Tech Specs re accident monitoring instrumentation to be installed per MUREQ-0737 requirement FAY, C W Hisconsin Electric Power Co GL-83-37 84/02/29 DENTON.H R Office of Nuclear Reactor Regulation, Director MILLER, JR Operating Reactors Branch 5 4pp 22536 179 24X Fiche 50-266,84/02/29,8403070255

--8403070257 Proposed Tech Specs incorporating changes re accident monitoring instrumentation to be installed per NUREG-0737 requirement
* Historian Electric Power Co 84/02/29 10pp 22536 183 24X Fiche 50-266.84/02/29.8403070255

8403070282 Forwards IE Insp Rept 50-289/83-32 on 831101-840112 No violations noted

STAROSTECKI, R Division of Project & Resident Programs 84/02/21,
HUKILL, H D General Public Utilities - GPU Service Corp 4pp
22047 079 24% Fiche 50-289,84/02/21,8403070282

--8403070287 IE Insp Rept 50-289/83-32 on 831101-840112 No violations noted Major areas inspected actions on previous insp findings, plant operations (long-term shutdown). Tech Spec surveillance test program & update to NUREQ-0680, Suppl 4 YOUNG, F. BAUNACK, W., CONTE, R. Region 1, Office of Director ALAB-729 84/02/06. 15pp 22547 083 24X Fiche 50-289,84/02/21, 8403070282

8403070307 Forwards IE Insp Repts 50-324/83-42 & 50-325/83-42 on 831215-840115 No violations or deviations noted VERRELLI,D M Division of Project & Resident Programs 84/02/06 UTLEV,E E Carolina Power & Light Co 2pp 22546-175 24X Fiche 50-324,84/02/06,8403070307

-8403070310 IE Insp Repts 50-324/83-42 & 50-325/83-42 on 831215-840115 NOSOVOJO IE Insp Repts 50-324/83-42 & 50-322/83-42 on 831215-84011
No violations or deviations noted Major areas inspected
surveillance, maintipperational safety verification, ESF sys
walkdown, LER review, independent insp & plant transients
WYERS, D D. GARNER, L. W. Region 2, Office of Director BEMIS, P. R.
Division of Project & Resident Programs 50-325/83-42 84/02/03
Spp. 22546 177 24X Fichs 50-324,84/02/06,8403070307

8403070395 NUREA-1039 NOSCULOR NOTECH TOST THE NUCLEAR REGULATORY COMMISSION
SAFETY RESEARCH PROGRAM FOR FISCAL YEAR 1985

+ ACRS - Advisory Committee on Reactor Safeguards 84/02/29. 74pp
Available at NRC \$4 50 22861 234.

8403070392 NUREC/CR-2000 VO3 NI LICENSEE EVENT REPORT (LER) COMPILATION For Month Of January 1784 * Oak Ridge National Laboratory FIN A-9135 ORNL, 84/02/29 Director's Office 123pp 22554 092 ORNL/NSIC-200

8403070397 NUREG/BR-0059 ROI ER SMALL BUSINESS INNOVATION RESEARCH PROGRAM Program Solicitation FY1984 # Office of Nuclear Regulatory Research, Director 84/02/21 ip 22567 022

8403070401 NUREG-0304 VOB NO4 REGULATORY AND TECHNICAL REPORT Compilation For 1983 * Division of Technical Information & Document Control 84/02/29 569pp 22554 217

8403080003 FOIA request for 10 contractor repts on generic modeling for vital area & safeguards analysis referenced in NUREO/CR-3121 SHDLLY,5 C Union of Concerned Scientists 84/01/10, FELTON, J. H Division of Rules and Records 2pp 22578 001

8403080039 Lists planned submittal dates for eight action items.per

8403080083 Forward's order modifying implementation date for TMI Action Item Il F i i, "Noble Gas Steam Effluent Monitor," per NUREC-0737 Order provides new completion date of 841231 W/o enc]
MILLER, J.R. Operating Reactors Branch G. 84/03/02 LUNDVALL, A E Baltimore Gas & Electric Co. App. 22584 095 24X
Fiche 50-317,84/03/02,8403080083

- 8403080095 FOIA request for SER & SSER 21 (NVREQ-0675) re operation of facilities
 6ARDE, 8.P Government Accountability Project 84/01/09 Office
 6A Administration 2pp 22584 074
- B4030B0179 Fourth partial response to FOIA request for six categories of documents re facilities forwards App A documents App B document entirely withheld (ref FOIA Exemption 5) Review of add1 documents subj to request continuing FELTON, J M Division of Rules and Records 84/02/13 ANDERSON, B I Garvey, Schubert, Adams & Barer 7pp 22583 226 24X Fiche 50-000,84/02/13,8403080179
- --8107280171 Notification of 810729 meeting w/util & B&W in Bethesda.MD to discuss method util intends to use to fulfill requirments of NUREO-0737 Item II F 2 (inadequate core cooling instrumentation)
 HERNAN.R W Licensing Branch 4 81/07/21 ADENBAM, E G Licensing Branch 4 2pp 22383 305 24X Fiche 50~000, 84/02/13, 8403080179
- --8209280165 Forwards Cycle 3 systematic appraisal of licensee performance input for BiO701 through 820730 in response to Region 5 820625 request Strong mgt evident Resolution of technical issues. responsiveness & staffing satisfactory HERNAN.R W. Licensing Branch 4 82/09/15 EIBENNUT.D.0 Division of Licensing Opp. 22583 351 24X Fiche 50-000, 84/02/13,8403080179
- B4030B0227 Lists concerns on proposed water supply sys discussed in Dec 1983 DES (NUREO-1026), including degradation of water quality from cooling water discharge to Kankakee River GALLAOHER, J R Will County, IL. B4/03/02 Division of Licensing 1p 22561.031, 24X Fiche 30-456.84/03/02,84030B0227
- 8403080264 Forwards "Control Room Design Review Program Plan for North Anna & Surry Power Stations." in response to Suppl 1 to NUREG-0737 Review expected to be completed by 850830

 BIEWART.W L Virginia Electric & Power Co 087 84/03/01.

 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22557-275 24X Fiche 50-000.84/03/01.8403080264
- --B4030B0269 "Control Room Design Review Program Plan for North Anna & Burry Power Stations," in response to Suppl 1 to NAREO-0737 # Virginia Electric & Power Co 84/03/01 111pp. 22557 279 24X Fiche 50-000.84/03/01.84030B0264
- B403080265 Forwards three repts re facility safety parameter display sys (BFDB), per requirements of Suppl 1 to NUREG-0737 BFDS will be installed during upcoming recirculation piping replacement outage PILANT, J M Nebraska Public Power District LGA8400069 B4/03/01 EISENHUT, D G Division of Licensing 2pp 22558 050 24X Fiche 50-278, 84/03/01,8403080265
- 8403080405 Further response to FOIA request for documents re BER related to operation of facilities Forwards App B documents. App A & B documents available in PDR. Review of remaining documents subj to request in progress FELTON, J M Division of Rules and Records 84/03/02 GARDE, B P Government Accountability Project 4pp 22583 073
- --8312230256 Forwards responses to Allegations 7.9 & 48,per 831130 request.

 SPEIB,T P Division of Safety Technology. 83/12/09 KNIGHTON, 0 Office of Nuclear Reactor Regulation, Director 12pp 22983 111
- --8403080426 Forwards safety evaluations for Allegations 8.10.11.14.15.16.17.27.28.29.31.32.33.35.36.55.85 & 86 Licensee approach for determining containment stability against tilting acceptable.

 VOLLMER.R. H Division of Engineering IEB-80-11 83/12/09 EISENHUT.D 0. Division of Licensing 31pp 22583 132.
- 8403090012 Forwards "High Pressure Bafsty Injection Pump," mechanical environ qualification rept.per BSER 5 (NUREO-0857).

 VAN BRUNT: E E. Arizona Public Bervice Co. ANPR-28970-WFG/.
 84/02/29. KNIOHTON.Q W Licensing Branch 3 2pp 22568 001 24X F1che: 50-528,84/02/29,8403090012
- 8403070081 Forwards Suppl 4 to response to IE Bulletin 83-02, consisting of rept, "Recirculation, RHR Shutdown Cooling, Head Spray Line Reactor Info (Rev 2) "
 DALTROFF, S L. Philadelphia Electric Co. IEB-83-02 84/02/21
 MURLEY, T. E. Region 1, Office of Director 3pp 22575 153 24X
 Fiche 50-277,84/02/21,8403070081.
- 8403090095 Forwards application to amend License DPR-26 consisting of proposed Tack Spac changes, incorporating requirements of Item II B i of NUREG-0737, "Reactor Coolant Vent Sys" O'TDOLE, J. D. Consolidated Edison Co. of New York, Inc. QL-83-37 84/02/28. VARGA, S. A. Operating Reactors Branch i 2pp 22576 007 24X Fiche 50-247,84/02/28,8403090095.

- --8403090098 Application for amend to License DPR-26, revising Tech Specs to incorporate requirements for reactor coolant vent sys O'TODLE, J D Consolidated Edison Co of New York, Inc 84/02/28 2pp 22576 009 24X Fiche 80-247,84/02/28,8403090095
- 8403090100 Application for amend to License DPR-16.changing Tech Specs re fire detection instruments to comply w/NUREO-0737 (Generic Ltr 63-34).Items II B J. II B J. II F I & II D J 4 KUNCL, L 0 Nebraske Public Power District NLS 8400076 84/02/29 VASSALLD, D B Operating Reactors Branch 2 App 22571 116 24X Fiche 50-298.84/02/29.8403090100
- --B403090116 Proposed radiological Tech Spacs per NUREG-0737 (Generic Ltr 83-36) re fire detection instrumentation * Nebraska Public Power District GL-83-36 84/02/29 16pg 22571 122 24X Fiche 36-278,84/02/27,8403090100
- B40309011B Forwards comments re DES (NUREC-1033) for consideration in preparation of FES SORENSEN.G C. Washington Public Power Supply System GD3-B4-131 B4/03/05 KNIGHTON.G W. Licensing Branch 3 5pp 22576 074 24X Fiche,50-508.84/03/05.840309011B
- 8403090121 Advises that 24 h homidity test of three safety-related components per 85ER 4 (NUREO-0892) satisfactorily completed SORENSEN. 9 C Washington Public Power Supply Bystem GD2-84-108 84/03/01 BCHMENCER. A Licensing Branch 2 1p 22576 066 24) Fiche 50-397,84/03/01.8403090121
- 8403090145 Requests submittal of documentation re NUREG-0737 items within 30 days to complete technical reviews & implementation.excluding Suppl 1.by Sept 1984 VARGA.S A Operating Reactors Branch 1 84/03/02 FARRAR,D L Commonwealth Edison Co 2pp 22592 309 24X Fiche 50-295,84/03/02,8403090145
- B403090153 Notifies that goal for completion of technical reviews & implementation of NUREO-0737 items.excluding Suppl 1, is Sept 1984 All required documents must be provided & Tech Specs in place to meet goal VARGA.B A D
- 8403090179 Forwards supplemental info re core exit thermocouples (CET) for inadequate core cooling interim operation, per 840210 telcon CET sys complies w/most NUREG-0737, Item II f 2 requirements

 MARSHALL.J R Arkansas Fower & Light Co 1CAN038401 84/03/07 STOLZ.J F Operating Reactors Branch 4 5pp 22573 267 24% Fiche 50-313,84/03/07,84030970179
- 8403090210 Advises that util 840220 proposed variance for high-range stack gas monitors unacceptable Sys should be modified to meet display guidance of NUREO-0737. Item II F 1(1), "Addl Accident Monitoring Instrumentation"

 CRUTCHTIELD.D Operating Reactors Branch 5 LSD5-84-03-007

 84/03/07 VANDEWALLE,D J Consumers Power Co 5pp 22574 358

 24X Fiche 50-000.84/03/07.8403090210
- 8403090252 Application to amend Licenses DPR-71 & DPR-62, revising Tech Specs re accident monitoring instrumentation per NUREG-0737 & Generic Ltr 83-36 HOME.P W Carolina Power & Light Co NLS-84-074 84/03/02 VASSALLO.D B Operating Reactors Branch 2 7pp 22571 192 24X Fiche 50-324,84/03/02.8403090252
- --8403090240 Proposed Tech Spacs re limiting conditions for operation & surveillance requirements for accident monitoring instrumentation per NUREO-0737 & Generic Ltr 83-35 * Carolina Power & Light Co 0L-83-36 84/03/02 21pp 22571,179 24X Fiche 50-324,84/03/02,8403090252
- B403090272 Notifies that submittal date for ST6 addressing NUREG-0737 items.per Generic Ltr B3-37, rescheduled for B40305 COUNBIL.W O Connecticut Yankee Atomic Power Co COUNBIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNBIL.W O Northeast Utilities A03610 B4/02/24 EISENHUT, D G Division of Licensing. 2pp 22572 196 24X Fiche 50-336,84/02/24, B403090272
- B403120004 Reevaluates response to NUREG-0737, Item III D 3 4. "Control Room Habitability." based on PRA technique for onsite & offsite sources App R mods will assure adequate smoke detection in control room HUKILLH D General Public Utilities GPU Service Corp B211-84-1036 B4/03/02 STOLZ, J F Operating Reactors Branch 4 2pp 22586 306 24% Fiche 50-287,84/03/02,8403120004

- 8403120042 "Annual Rept of Facility Changes.Tests.Experiments & Safety & Relief Valve Failures & Challenges.1983 " W/840301 ltr MINECK.D L. Towa Electric Light & Power Co. DAEC-84-129 83/12/31 KEPPLER.J O Region 3. Office of Director 73pp 22591 145 24X Fiche 50-331,83/12/31.8403120042
- 8403120059 Forwards results of safety evaluation of NUREO-0737, Item IJ K 3 iB concluding that eliminating high drywell pressure permissive could increase severity of loss of fredwater transient by attuating automatic depressurization sys MANGAN.C V Niagara Mohawk Power Corp 84/03/06 VASSALLO,D 8 Decrating Reactors Branch 2 Spp 22586 285 24X Fiche 50-220.84/03/06.8403120059
- 840312008) Forwards safety evaluation re Sections 5 1.1 & 5 3 of NUREG-0612, "Control of Heavy Loads at Nurisar Power Plants " Guidelines satisfied Phase I acceptable JUHNSON,E H Region 4, Office of Director 84/03/06 LEE,O R Public Service Co of Colorado 2pp 22590 168 24X Fiche 50-267.84/03/06,8403120081
- --8403120086 Safety evaluation re NUREO-0612, "Control of Heavy Loads," Phase I Guidelines satisfied ** NRC No Detailed Affiliation Given 84/03/06 2pp 22590 170 24X Fiche 50-267,84/03/06.8403120081
- --8402280725 EOG-HS-6294 RO3
 "Control of Heavy Loads at Nuclear Power Plants, Fort St
 Vrain Nuclear Operating Station, Phase I," technical
 evaluation rept
 STICKLEY, THE EG&G, Inc FIN A-6457 84/01/31 NRC No
 Detailed Affiliation Given 27ap 22590 172, RAX
 Fiche 50-267,64/03/06.8403120081
- 8403120130 Comments on NUREG-0737. Item II B 1, "RCS Vents" Six listed jtems completed.per B30903 BER RCS vent sys solenoid valves not susceptible to common mode Failure No corrective action necessary MESTAFER.G R Florida Power Corp 3F0384-04 84/03/07 STDLZ, J F Operating Reactors Branch 4 3pp 22588 202 24X Fichs 50-302.84/03/07.8403120130
- 8403120157 Advises that due to delays in delivery & installation of auxiliary safety instrumentation panels (ASIPs), installation of six accident monitors addressed in NOREG-0737. Items II F J 1 through II F I 6 will not be completed by 840630 FAY.C W Hisconsin Electric Power Co 84/03/05 DENTON.H R Office of Nuclear Reactor Regulation. Director MILLER, J R Operating Reactors Branch 3 3pp 22586 250 24% Fiche 50-266.84/03/05.8403120157
- 8403120179 Forwards info supporting util position that implementation of add1 insp criteria provides no add1 increase in safety, per SER (NUREG-0847)
 MILLS.L. M Tennessee Valley Authority 84/03/07 ADENSAM.E
 Licensing Branch 4. 3pp 22590 205 24X Fiche 50-390.84/03/07.
 RAD3120179
- 8403120183 Forwards application for amend to License DPR-40, revising Tech Specs to add limiting conditions for operation, surveillance requirements & administrative requirements, per NUREO-0737

 * LeBoeuf, Lamb, Leiby & MacRae. * Omaha Public Power District
 - NOREW-0/3/ * LeBouf, Lamb, Leiby & MacRae. * Omaha Public Power District 84/03/09 DENTON.H Office of Nuclear Reactor Regulation. Director 3pp 22585 200 24X Fiche 50-285,84/03/09,8403120183
- --8403120192 Application for amend to License DPR-40.revising Tech Specs to add limiting conditions for operation, surveillance requirements & administrative requirements.per NUREQ-0737 JONES, W C Dmaha Public Power District 84/03/08 2pp 22585 203 24% Fiche: 50-285,84/03/09,8403120183
- --B403120195 Proposed Tech Specs re limiting conditions for operations surveillance requirements & administrative requirements * Omaha Public Power District 84/03/09. 14pp 22585 205 24X Fiche 50-285.84/03/09.8403120183
- 8403120186 Requests that NUREQ-0737. Item II E 4 2 re containment pressure setpoint be closed in mext SBER. Facility will employ 17 i pais setpoint per Tech Specs.

 CODK.K W Louisiana Power & Light Co W3F84-0602 84/03/05 KNIGHTON.O W Licensing Branch 3 ip 22585 001 24X Picks 50-382, B4/03/05.8403120186
- B403120302 Requests remittal of Class III fee for review of 840123 application for Tech Spec charges re NUREG-0737 requirements
 DIGGS.R M License Fee Management Branch 84/03/01 RODRIGUEZ,R J
 Sacramento Municipal Utility District ip 22596 360 24X
 Fiche 50-312,84/03/01.8403120302

- 8403120339 Forwards order confirming util commitments to implement post-TMI-related items set forth in Suppl 1 to NUREQ-0737, "Requirements for Emergency Response Capability " Order based on util 821217 response to Generic Ltr 82-33 STOLZ, J F Operating Reactors Branch 4 OL-82-33, 84/02/21 RODRIGUEZ, R J Sacramento Municipal Utility District 3pp. 22615 320 24X Fiche 30-312,84/02/21,8403120339
- ---8403120342 Order confirming licensee commitments on emergency response capability, per Suppl 1 to NUREQ-0737.
 EISENNUT.D O. Division of Licensing 84/02/21 Sacramenta Municipal Utility District 6pp 22615 323 24X
 Fiche 50-318,84/02/21,8403120339
- 8403120354 Forwards order confirming licensee commitments to implement post-TMI-related items set forth in Suppl 1 to NUREG-0737, "Requirements for Emergency Response Capability." Order based on util responses to 821213 Generic Ltr 82-33 STOLZ, JF. Operating Reactors Branch 4 GL-82-33 84/02/21, WILGUS H S Florida Power Corp 3pp 22615-329 24X Fiche 50-302,84/02/21,8403120354.
- --B403120359 Order confirming licensee commitments on emergency response capability.per Suppl 1 to NUMEG-0737.
 EISENHUT.D.G. Division of Licensing B4/02/21 Florida Power Corp opp. 22615 332 24X Ficher 0-302.84/02/21,8403120354.
- 8403120379 Forwards rept of results of in-progress audit for facility detailed control room design review per Suppl 1 to NUREO-0737 conducted on 831212-16 MILLER, J R Operating Reactors Branch 3 84/02/29, WITHERS, B, D Portland General Electric Co 73pp. 22619.008 24X Fichs 50-344,84/02/29,8403120379
- 8403130007 Forwards response to Generic Ltr 83-36 re NUREG-0737 Tech Specs MILLS,L M Tennessee Valley Authority QL-83-36 84/03/07 DENTON,H R Office of Nuclear Reactor Regulation, Director 3PP. 22613.349 24x Fiche.50-259,84/03/07.8403130007
- 8403130057 Comments on DEB (NUREQ-102A) for facility DEB does not completely describe fuel cycls impact & should contain statement re range of nonfatal cancer injuries & birth defects induced by fuel cycle Rn-222 DDHERTY, J. F. Doherty, J. F. 84/03/07 STEVENS, J. A. Division of Licensing 2pp 22601 117. 24X Fiche. 50~456, 84/03/07, 8403130057.
- B403130066 Advises that request to revise Tech Bpecs to provide requirements for overtime limits & reporting of relief & safety valve failures will be submitted per Generic Ltr B2-16 (NUREO-0737) by B40515 HILLIAMS.J W Fjoride Power & Light Co. QL-82-16 84/03/08 MILLER, J R. Operating Reactors Branch 3, ip 22601-252 24X Fiche 50-335,84/03/08,8403130066
- 8403130155 Advises that state & local plans & preparedness for radiological emergencies adequate Approval conditional on FEMA verification of adequacy of alerting & notification system app 3 of Rev 1 to NUREG-0604/FEMA-REP-1.

 SPECK, S W Federal Emergency Management Agency, 84/03/02 DIRCKB, W J Optice of the Executive Director for Operations 26, 22608 229 24X Fiche. 50-254, 84/03/02, 8403130155
- 8403130185 Discusses evaluation of State of IL & local plans & preparedness for facilities Plans adequate to protect health & safety of public Approval of public alert notification sys conditional on verification of criteria of NUREO-054.

 SPECK.S W Federal Emergency Management Agency. 84/03/02 DIRCKS, W.J Defice of the Executive Director for Operations 122613 316 24% Fiche 50-295,84/03/02.8403130185
- B403130190 Forwards response to NRC 801222 request for review of controls for handling heavy loads, as committed to in 830809 ltr.Response to items in Section 2 1 of 801222 ltr also encl.

 BODKER, J E Gulf States Utilities Co. RBG-17168, 84/03/01, DENTON, H R. Office of Nuclear Reactor Regulation, Director 63pp 22606 063, 24X Fiche; 50-438,84/03/01,8403130190.
- 8403130194 Responds to NRC comments on detailed control room design review program plan, per 831223 ltr Control room inventory requirements will be satisfied, per Suppl 1 to NUREO-0737 & Generic Ltr 83-18 during Apr 1984 task analysis review EDELMAN, M R Cleveland Electric Illuminating Co PY-CEI/NRR-0095, 84/02/29 YOUNGBLOOD, B. J. Licensing Branch 1. 7pp. 22617:300, 24X Fiche 30-440,84/02/27,8403130194.
- B403130199 Forwards info in response to NRC B20630 ltm re NUREC-0737.

 Item 1].B. 3. "Post-Accident Bampling Sys." W/three oversize drawings Apenture cards are available in PDR.

 FIEDLER,P.B. General Public Utilities GPU Service Corp. B4/03/06 CRUTCHFIELD.D Operating Reactors Branch 5 35pp. 22608:246 24: Fiche: 50-219.84/03/06.8403130199.

- 8403130227 Forwards info re shift experience, per DF Schnell 840301

 1th & SER (NVREG-0892) Licensed classroom training & exam
 conducted

 SORENSEN, Q C Washington Public Power Supply System G02-84-127

 84403/09 DENTON, HR Office of Nuclear Reactor Regulation,
 Director 7pp 22608 231 24X Fiche 30-397, 84/03/09, 8403130227
- B403130234 Disagrees w/util 840207 ltr concluding that no Tech Spec revs required to finalize NUREG-0737 itums presented in Generic Ltrs 83-36 & 83-37 Changes needed for conformance to NUREG-0737 encl Commitments requested within 20 days JDHNSON, E H Region 4, Office of Director GL-83-36 84/03/08 LEE, O R Fublic Service Co of Colorado 3pp 22617 265 24X Fiche: 50-267,84/03/08,8403130234
- B4031302B7 Requests exemption from 10CFR50 44(c)(ii)(B), specifying requirements for containment penetrations designated for use as post-accident hydrogen recombinaryby 840405 KAY, J A Yankee Atomic Electric Co FYR 84-31 84/03/06 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 22614 146 24X Fiche 50-029,84/03/06,84031302B7
- 8403130270 Forwards response to Section 4.4 of NUREG-0827.SEP Tapic II-3 C. "Safety-Related Water Supply (UHB) " Submittal of applicable Tech Spec changes rescheduled for 840401 LINDER.F Dairyland Power Cooperative LAC-7627 84/03/08 CRUTCHFIELD.D Operating Reactors Branch 5 5pp 22608 034 24X Fiche: 50-407,84/03/08,8403130270
- 8403130298 Provides implementation ltr rept for reactor vessel level instrumentation sys.per NRC 840116 ltr & TMI Action Item II F 2. Requests NRC approve use of installed reactor vessel level instrumentation based on previous acceptance STEWART, W L Virginia Electric & Power Co 047A 84/03/07 DENTON.H R. Office of Nuclear Reactor Regulation, Director EISENHUT, D Q Division of Licensing 3pp 22607 360 24X Fichs 50-338,84/03/07,8403130298
- 8403130340 Forwards offsite dose calculation manual, per proposed radiological effluent Tech Spec dtd 840201 Response to Franklin Research Ctr comments re 830301 offsite dose calculation manual also encl
 LEMPGES.TE Nisgara Mohauk Power Corp 84/03/07 VASSALLO.D B Operating Reactors Branch 2 App 22607 154 24X
 Fiche 50-220,84/03/07,8403130340
- --8403130349 "Offsite Dose Calculation Manual "
 * Niegara Mohawk Power Corp 84/03/01 83pp 22607 160 24X
 Fiche: 50-220, 84/03/07, 8403130340
- B403130353 Documents present resolution of SER open items & deficiencies noted in Franklin Research Ctr technical evaluation rept re environ qualification of safety-related electrical equipment RYBAK.B Commonwealth Edison Co 8121N 84/02/29 DENTON, H R Office of Nuclear Reactor Regulation, Director 40pp 22617 080 24X Fichs 50-254,84/02/29,8403130353
- 8403130386 Forwards response to 840112 request for addi info re NURGO-0737, Item II B 3, "Post-Accident Sampling Bys " Emergency Procedure EPP-9, "Determination of Core Damage Under Accident Conditions" also encl HANGAN.C.V Niagara Mohawk Power Corp 84/03/08 VARBALLO.D B Operating Reactors Branch 2 19pp 22605 010 24X Fiche.50-220,84/03/08,8403130386
- 8403130480 Advises of effort to determine effect of dead leg piping extending into secondary containment, per NUREO-0737, Item II. 8 2 % util 830916 ltr re environ qualification of safety-related equipment.

 SORENSEN, 0 C Washington Public Power Supply System GD2-84-112 84703/05. SCHWENCER, A Licensing Branch 2 2pp 22613.214 24X Fichm.50-397.64/03/05,8403130480
- B403130486 Forwards addl info re Generic Ltr 82-33, "Suppl 1 to NUREG-0737 - Requirements for Emergency Response Capability " Info suppls emergency operating procedures generation package submitted B30831. BDOMER.J.E. Gulf States Utilities Co. RBG-17137 84/02/27 DENTON.H R Office of Nuclear Reactor Regulation, Director. 4pp 22614:009. 24X Fiche: 50-458, 84/02/27. 8403130486
- B403130494 Forwards comments on 830930 detailed control room design review program plan per Buppl 1 to NUREQ-0737 Specific areas of plan not described in enough detail to ensure that plan will meet requirements in-progress audit suggested VASBALLO, D.B. Operating Reactors Branch 2 84/02/22 RHODE, Q K Nisgara Hohawk Power Corp 13pp 22619 348, 24X Fiche 50-220,84/02/22,8403130496

- B403140001 Forwards comments on DES (NUREG-1026) Comments submitted for consideration by Commission per 10CFR51 MCDCNOUGH, C L Commonwealth Edison Co 4342E 84/03/12 Division of Licensing 13pp 22633 251 24X Fiche 50~456,84/03/12.8403140001
- 8403140019 Clarifies Sept 1983 draft technical evaluation rept of Phase II submittal of control of heavy loads.per 840109 telcon Safe load paths for reactor bldg closed loop cooling water pumps revised MCCAFFREY.B R Long Island Lighting Co SNRC-1012 84/03/05 DENTON.H R Office of Nuclear Reactor Regulation, Director 4pp 22633 218 24X Fichs 50-322.84/03/05,8403140019
- 8403140040 Comments of JF Doberty on DES (NUREG-1026) Statement must clarify iff.in analysis of environ impatts of postulated accidents any credit given for applicant compilance w/any TMI-related requirements Related correspondence DOHERTY.JF Affiliation Not Assigned 84/03/07 STEVENS.JA Division of Licensing 2pp 22633 120 24X Fithe 50-456.84/03/07, 8803140040
- B403140185 Forwards SER on NUREO-0737. Item II D 1 re performance testing of BMR relief & safety valves Item satisfactorily resolved VASSALLO, D B Operating Reactors Branch 2 84/02/24 MUSOLF, D M Northern States Power Co 17pp 22638 004 24X Fiche 50-263, 84/02/24, 8403140185
- S40314019: Forwards technical guidelines required by NUREQ-0737, Buppl 1, including guidance on station blackout conditions (Unresolved Safety Issue A-44), to be considered as response to Generic Ltr 81-04
 COOK, K W Louisiane Power & Light Co W3P84-0494 84/03/05 X000H10910 W Licensing Branch 3 337pp 22621 001 24X Fiche 50-382, 84/03/05, 8403140191
- B403140177 Forwards draft BER (NUREC-1057) re operation Proposed schedule for submittal of written response to open items should be provided by B40330 KNIGHTON, C W Licensing Branch 3 84/03/01 WDQLEVER, E J Duquesne Light Co 3ilpp 22636 001 24% Fiche 50-412, B4/03/01, 8403140177
- 8403140236 Forwards order confirming licenses commitments on emergency response capability VASSALLO,D B Operating Reactors Branch 2 84/02/22 UTLEY,E E Carolina Power & Light Co 2pp 22636 353 24X Fiche 50-324,84/02/22,8403140236
- --8403140239 Order confirming licensee commitment on emergency response capability per Generic Ltr 82-33 (Suppl 1 to NUREG-0737) EIBENHUTD 6 Division of Licensing 0L-82-33 84/02/22 Carolina Pawer & Light Co 5pp 22636 355 24x Fiche 50-324,84/02/22,8403140236
- 8403140246 Forwards comments on detailed control room design review program plan per Suppl | to NUREC-0737 Specific areas of plan not described in enough detail to provide assurance that applicable requirements will be met VASSALLO, D B Operating Reactors Branch 2 84/02/22 BAYNE, J P Power Authority of the State of New York 10pp 22636 343 24X Fiche 50-333, 84/02/22,8403140246
- B403140252 Forwards order confirming licensee 830415.0711 & 28 & 1230 commitments to comply w/Suppl 1 to NUREG-0737 re emergency response capability VASSALLO,D B Operating Reactors Branch 2 84/02/22 PILANT,J M Nebraska Public Power District 2pp 22636 332 24X Fiche 50-298.84/02/22.8403140252
- --8403140256 Order confirming licenses commitments to comply w/Suppl 1 to NUREG-0737 (Generic Ltr 82-33) re emergency response capability CISCNHUT.D G Division of Licensing GL-82-33 84/02/22 Nebraska Public Power District App 22636 334 24% Fiche 80-278,84/02/22,8403140252
- 8403140285 Informs that onsite & offsite emergency preparedness adequate & emergency plans upgraded per NUREG-0737. Item III A 2 I Reasonable assurance exists that prompt protective measures will be taken to protect public VASSALLO.D B Operating Reactors Branch 2 84/02/22 SINCLAIR.J B Vermont Yankes Nuclear Power Corp 3pp 22636 320 24X Fiche 50-271.84/02/22.8403140285
- 8403140288 Forwards SBER re TMI Action Plan Items I C 1 & J C 8 of SER Confirmatory Issue 5 concerning guidance for evaluation & development of procedures for transients & accidents YOUNGBLGOD. B J Licensing Branch 1 GL-82-33 84/03/06 GARY.R J Texas Utilities Clectric Co (formerly Texas Utilities Generating Co) 6pp 22636 312 24X Fiche 50-445,84/03/06,8403140288

- 8403140273 Provides clarification of NRC favorable findings re SER Confirmatory Issue II for THI Action Plan Item I G 1 Util should either commit to perform natural circulation bornon mixing test or ref boron nixing test at Diablo Canyon YOUNGELOOD B J Licensing Branch I 84/03/06 GARY,R J Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 3pp 22635 333 24X Fiche 50-445.84/03/06.8403140273
- 8403140297 Forwards request for add3 info re control of heavy loads Response requested within 60 days MILLER, JR Operating Reactors Branch 3 84/03/06 GRIFFIN, J M Arkansas Power & Light Co. 2pp. 22635 327 24X Fiche 50-313
- 8403150040 Forwards request for add1 info to support conclusions re current design codes & criteria & load combinations in 820802 ltr per integrated plant safety assessment rept (NUREC-0823) CRUTCHFIELD. D. Operating Reactors Branch 5 LS05-84-03-010 84/03/09 FARRAR, D. L. Commonwealth Edison Co. 8pp. 22643 084 24X Fische 50-237,84/03/09,8403150040
- 8403150058 NUREQ-0020 VOB NOI LICENSED OPERATING REACTORS STATUS SUMMARY REPORT Data As De December 31.1963 (Grey Book) * Management Information Branch 84/02/29 396pp 22647 001
- 8403150092 Forwards results of in-progress audit of detailed control room design review Util pursuing course of review which NRC believes will satisfy requirements of Suppl 1 to NUREC-0737 CRUTCHFIELD. D Operating Reactors Branch 5 LS05-84-03-014 84/03/14 FARRAR, D.L. Commonwealth Edison Co 11pp 22643 002 24x Fiche 50-237.84/03/14.8403150092
- 8403150146 Forwards IE Insp Rept 50-286/84-02 on 840116-0215 & notice of violation STARDSTECKI.R Division of Project & Resident Programs 84/03/01 BRONS.J C Power Authority of the State of New York 2pp 22643 027 24X Fiche 50-286,84/03/01,8403150146
- --8403150166 IE Insp Rept 50-286/84-02 on 840116-0215 Violation noted RHR sys changes not delineated on sys print or sys checkoff list & safety evaluation not performed KENNY, T J. ROSSBACH. L W Region J. Office of Director NORRHOLM. L Division of Engineering & Technical Programs IEB-79-15 84/02/22 13pp 22643 030 24X Fiche 50-286, 84/03/01.8403150146

8403150175 RIL-139 Research Info Ltr 139 provides appraisal of U dioxide fuel oxidation phenomena & potential impacts on transportation of irradiated power reactor fuel assemblies Potential for occupational exposures during unloading major impact MINOGUE.R B Diffice of Nuclear Regulatory Research. Director 84/03/05 DAVIS.J G Office of Nuclear Material Safety & Safeguards. Director Sipp 22646 311

- 8403150198 forwards FR notice of extension of comment period for DES (NURE6-1033) to 840312.por 840130 ltr MNIGHTON,G W Licensing Branch 3 84/02/27 HIRSCH, A Environmental Protection Agency 7pp 22662 028 24X Fiche 50-508
- ~-8402270440 Notice of extension of comment period for DEG (NUREG-1033) to 840312 KNIGHTON.O W Licensing Branch 3 84/02/24 1p 22662 035 24X Fiche 50-508,84/02/27,8403150198
- B403150211 NUREG-0885 103
 US NUCLEAR REGULATORY COMMISSION POLICY AND PLANNING
 GUIDANCE 1984

 Commissioners B4/01/31 23pp Available at NRC \$3 00
 22662 139
- B403150R14 NUREG/CR-3605
 EVALUATION OF NUCLEAR FACILITY DECOMMISSIONING PROJECTS
 Summary Report Plum Brook Feactor Facility
 DERROE, D. H. MILLER, R. United Nuclear Corp. FIN B-7568
 B4/02/29 Division of Engineering Technology 34pp Available at
 NRC \$4 25 22649 052 24X Fiche 50-030, 84/02/29, 8403180214
- B403150219 NUREG/CR-3422 VD2
 AEROSOL RELEASE AND TRANSPORT FROGRAM Quarterly Progress
 Report For April-June 1983
 ADAMS, K E. TOBAIS,M L Oak Ridge National Laboratory FIN E-0121
 DRML/TM-8849/V2 84/02/29 Division of Accident Evaluation
 5299 22662 087

- 8403150243 Forwards order confirming commitments to implement post-TMI-related items set forth in Suppl 1 to NUREG-0737. "Requirements for Emergency Response Capability," based on util 821217 response to Generic Ltr 82-33
- ---B403150246 Forwards order confirming licensee commitments to emerging response capability for transmittal to Ofc of FR for publication

 Operating Reactors Branch 4 QL-82-33 84/02/21 Docketing Services Branch 2pp 22649 002 24X Fiche 50-346.84/02/21.8403150243
- 8403160020 Informs that facility will employ 17 i psid setpoint for containment isolation as reflected in current draft Tech Specs, per Item II E 4 2 of NUREG-0737 Item should be closed in next SSER COOK, K W Louisiana Power & Light Co W3P84-0615. 84/03/12, KNIOHTON, O W Licensing Branch 3 2pp 22653 351 24X Fiche 50-382,84/03/12,8403160020
- B403160026 Notifies that Natl Ctr for Devices & Radiological Health h no comment re postulated plant accidents described in DEB (NUREP-0-974)

 VILLFORTH. J C Food & Drug Administration 84/02/10, BCHWENCER, A Licensing Branch 2 1p 22654 346 24X Fiche: 50-352, 84/02/10, 8403160024
- 8403160080 Submits addl info on Generic Ltr 82-33 schedule requiremen for emergency response capabilities. Vendor of new computer sys requested i-yr delay to June 1985 for delivery, affecting schedular commitments made to MRC FAY, C H Wisconsin Electric Power Co QL-82-33, 84/03/08 DENTON, HR Office of Nuclear Reactor Regulation, Director 4pp. 22652 327 24X Fiche 50-266,84/03/08,8403160080
- 8403160214 Forwards IE Insp Repts 30-390/83-56 & 50-391/83-44 on 831225-840120 No violations or deviations identified VERRELLI, D M Division of Project & Resident Programs 84/02/17 PARRISH 9 Tennesses Valley Authority 2pp 22661 067 24X Fiche 50-370,84/02/17,8403160214
- ~~8403160222 IE Insp Repts 50~390/83~56 & 50~391/83~44 on 831225-8401:
 No violation or deviations identified Major areas inspected;
 action on previous enforcement matters & insp items, Pollowup
 on licensee identified items & verification of as-builts.
 SHYMLGCK, M B , BMAN, W B , HOLLAND, W E. Region 2, Office of
 Director 50~391/83~44 84/02/16 7pp 22661*069, 24X
 Fishe 50~390, 84/02/17, 8403160214
- 8403160237 Forwards IE Insp Rept 50-390/84-09 on 840130-0203. No violations or deviations noted VERRELLI,D M Division of Project & Resident Programs. 84/02/27. PARRIS.H G Tennessee Valley Authority 2pp 22660-315 24X Fiche 50-390.84/02/27.8403160237
- --B403160240 IE Insp Rept 30-390/84-07 on B40130-0203 No violations of deviations noted. Major areas inspected const status & as-built configuration for radioactive resin transfer sys & preoperational testing of radwaste sys HOSEY.C M Region 2. Office of Director BARR, K P. Division of Engineering & Operational Programs. B4/02/23 Bpp 22660; 317. 24X Fiche 50-390, 84/02/27, 8403160237
- B403140249 Ack receipt of B40217 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-261/83-35. Implementation of corrective actions will be examined during future insps.

 LEW19.R C Division of Project & Resident Programs 84/02/29. UTLEY.E E Carolina Power & Light Co ip 22660-299. 24X Fiche 50-261.84/02/29.8403160249
- --8403160262 Responds to NRC 84011B ltr re violations noted in IE Insp. Rept 50-261/83-35 Corrective actions Emergency Procedure PEP-105 will be revised to implement recommendations of IE Info Notice 83-28 & NUREO-0654 MORRANNE Carolina Power & Light Co. IEIN-83-28, 84/02/17 O'REILLY, J P' Region 2, Office of Director 3pp. 22660 300 24 Fiche 50-261,84/02/29,8403160249

- --8403140300 IE Insp Rept 50-261/83-35 on 831205-07 Violation noted IE Info Notice 83-28 guidance not incorporated into Emergency Procedure PEP-105. "Emergency Control General Emergency " STODDART.P G Region 2. Office of Director JENKINS, 0 R Division of Emergency Preparedness & Materials Safety IEIN-83-28 84/01/11 7pp 22660 305 24X Fiche 50-261,84/02/27,8403160249
- 8403160264 Forwards IE Insp Repts 50-335/83-42 & 50-389/83-70 on 831101-1210 No violations or deviations noted DANCE: H C Division of Project & Resident Programs 84/02/24 WILLIAMS. J W Florida Power & Light Co 2pp 22660 335 24X Fichs 50-335,84/02/24,8403160264
- ---84031&0268 IE Insp Repts 50-335/83-42 & 50-389/83-70 on 831111-1210 No violations or deviations noted Major areas inspected maint & surveillance observation, plant operations, LERs & IE info notices
 BIBB, H & Region 2, Office of Director & ELROD, S A Division of
- 8403160338 Ack receipt of 840206 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/83-32 & 50-366/83-34

 DANCE, H. C. Division of Project & Resident Programs 84/03/07

 KELLY, R. J. Georgia Power Co. ip 22660 015 24X

 Fichs 50-321,84/03/07,8403160338
- --8403160365 Notice of deviation from insp on 831114-18
 * Region 2, Office of Director 50-366/83-34 84/01/06 1p
 22660 020 24% Fiche 50-321,84/03/09,8403160338
- --8403160372 IE Insp Repts 50-321/83-32 & 50-366/83-34 on 83114-18 Deviation noted failure to stectronically calibr high range drywell radiation monitors, per NUREO-0737. Item II F I WRAY. J R Region 2, Diffice of Director BARR.K P Division of Engineering & Operational Programs 50-366/83-34 84/01/04 7p 22660 021 24X Fichs 50-321,84/03/09.8403160338
- 8403190008 Submits mod to agenda for CRGR Meeting 45 on 830817 in Bethesda, MD to discuss NUREQ-0737, Suppl 1 control room design review & NRR study of electromagnetic pulse BTELLO.V Committee to Review Generic Requirements 83/08/15 MATTSON, R J Division of Systems Integration (post 811005) JRDAN, E. L Director's Office. Office of Inspection and Enforcement CUNNINGHAM, R E Office of Nuclear Material Safety & Bafeguards, Director 2pp 22664 361
- 8403190009 Notifies of CRQR Mesting 58 on 840315 to discuss proposed NUREQ-0801, "Evaluation Criteria for Detailed Control Room Design Review "
 8TELLO: V. Committee to Review Generic Requirements 84/03/02 MATTSON: R J Division of Systems Integration (post 811005), JORDAN: E L Director's Office, Diffice of Inspection and Enforcement CUNNINGHAM: R E Office of Nuclear Material Bafety & Safeguards, Director ip 22665:352
- 8403190018 Forwards Calvert Cliffs Instruction CCI-310, "Emergency Operating Procedure Writers Quide," implementation schedule, validation verification plan & training plan per Suppl 1 to NNR6-0737 LUNDVALL.A E Baltimore Qas & Electric Co 84/03/14 MILLER, J R Operating Reactors Branch 3 Dpp 22666 001 24X Fiche 50-317,84/03/14,8403190018
- 8403190029 Notifies of CRGR Meeting 57 on 840213 to discuss proposed NUREG-0801, "Evaluation Criteria for Detailed Control Room Design Review" & NUREG-0835, "Human Factors Review Guidelines for Safety Parameter Display Sys "
 STELLD: V Committee to Review Generic Requirements 84/02/07 MATTSON: R J Division of Bystems Integration (post 811005), JORDAN.E.L. Director's Office, Office of Inspection and Enforcement CUNNINGHAM, R E Office of Nuclear Material Safety & Bafeguards, Director ip 22665 362
- 8403190031 Notifies of CRGR Meeting 44 on 830802 in Bethesda, MD to discuss NUREG-0978, re-behavior of BWR Mark III containment & commission paper re-integrated safety assessment program STELLO. V Committee to Review Generic Requirements 83/07/22 MATTSDN.R.J. Division of Systems Integration (post 81:005) JORDAN, E.L. Director's Office, Office of Inspection and Enforcement CUNNINGHAM, R.E. Division of Fuel Cycle & Material Safety 2pp 22666, 113
- 8403i90048 Informs that util postponed ultrasonic test/insp of safe-end, nozzle bore & blend regions of feedwater nozzle per NUREO-06i9, due to installation of low flow feedwater controller COUNSIL.W.O Northeast Nuclear Energy Co (subs of Northeast Utilities). COUNSIL.W.O Northeast Utilities Bi1056 84/03/05 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 22666 251 24% Fiche: 50-245.84/03/05.8403190048

- B403190052 Informs that local emergency operations facilities at North Anna & Surry Power Stations will be functional, except for data communications & display-by B50731,per NUREG-0737, Suppl 1 BTEWART, W L Virginia Electric & Power Co 137 84/03/14 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22666 173 24X Fiche 30-000.84/03/14.8403190052
- 8403190055 NUREQ/CR-3645
 A GUIDE TO LITERATURE RELEVANT TO THE ORGANIZATION AND
 ADMINISTRATION OF NUCLEAR POWER PLANTS
 SOMMERB,P Battelle Human Affairs Research Centers * Battelle
 Memorial Institute, Pacific Northwest Laboratories FIN B-2360
 PNL-4906 84/02/27 Division of Health, Siting & Waste
 Management 656pp 22678 001
- 840319056 Responds to constituent RE Burks 840123 request for info re accident Forwards "Population Dose & Health Impact of Accident at TMI Station." (NUREG-0558) W/o encl BIRCKS,W J Office of the Executive Director for Operations 84/03/05 HEFLIN.H Senate 3pp 22681 317 24X Fiche 50-320.84/03/05.8403190056
- 8403190073 Forwards questions for FEMA witnesses to assist in preparation of testimony on offsite emergency planning contentions All testimony will be required to be filed on 840406 & 69 Hearing will commence on 840424 W/a encl MCGURRCN.H J Hearing Branch 3 84/03/15 PERRY,S Federal Fmergency Management Agency ip 22666 135 24X Fiche 50-413.84/03/15.8403190073
- 8403190178 Forwards safety evaluation approving util response to NUREO-0737. Item II K 3 44, "Evaluation of Anticipated Transients W/Singla Failura to Verify No Fuel Failura "Issue resolved CRUTCHTIELD, D Operating Reactors Branch 5 L505-84-03-020 84/03/15 VANDEWALL, D J Consumera Power Co App 22671 167 24X Ficha 50-155,84/03/15,8403190178
- 8403170251 Submits agenda mods for CRGR Meeting 55 on 840125 re proposed IE bulletin on GE HFA relays & NUREG-0801 on criteria for detailed control room design STELLO. V Regional Operations & Generic Requirements 84/01/31 MATTSON.R J Office of Nuclear Reactor Regulation. Director JURDAN.E L Director's Office of Fise of Inspection and Enforcement CUNNINGHAM. R E Office of Nuclear Material Safety & Bafeguards. Director 1p 22672 270
- --8403190256 Notifies of CRQR Meeting 55 on 840125 in Bethesda.MD to discuss draft IE bulletin, "Failure of GE Type HFA Relays in Use in Class IE Bafety Sys," NUREG-08015 NUREG-0805 STELLO, V Regional Deparations & Generic Requirements 84/01/09 MATTBON.R J Office of Nuclear Reactor Regulation, Director JORDAN.E L Director's Diffice, Office of Inspection and Enforcement CUNNINOHAM.R E Office of Nuclear Material Safety & Safeguards, Director 2pp 22672 271
- 8403170258 Ack receipt of 840214 ltr informing NRC of steps taken to correct violations noted in IE Emergency Preparedness Appraisal Rept 50-286/81-05 MARTIN, T T Division of Engineering & Technical Programs 84/03/13 BRONS, J C Pawer Authority of the State of New York 2pp 22672 221 24X Fiche 50-286,84/03/13.8403190258
- --8403190265 Responds to NRC Billip ltr re violations noted in IE
 Emergency Preparedness Appraisal Rept 50-986/81-05
 Corrective actions, post-accident instrumentation & sampling
 requirements per NUREO-0737 & Reg Guide i 97 implemented
 BRONS, J C Power Authority of the State of New York B4/02/14
 MARTIN, T T Division of Engineering & Technical Programs 2pp
 22672 223 24X Fiche 50-286,84/03/13,8403190258
- B403170276 Responds to B40208 request for info re emergency operations facility (EDF), specifically preliminary cost estimate for upgrade to overall radiation protection factor of five Existing EOF meets Suppl 1 to NUREG-0737 requirements BAYNE, J. P. Consolidated Edison Co. of New York. Inc. INP-B4-10 B4/03/14 VARGA, S. A. Operating Reactors Branch 1 2pp. 22674 334 24X Fiche 50-286,84/03/14,8403190296.
- 0403190314 Forwards IE Insp Repts 50-295/83-27 & 50-304/83-28 on 831122-1228 & 040202 & notice of Volation Concerns re mgt control inadequacies, per TMI Action Plan Item II F 1 1, "Noble Cas Effluent Monitor," expressed HIND, J A Division of Radiological & Materials Safety Programs 84/03/01 REED, C Commonwealth Edison Co 2pp 22673 176 24X Fiche 50-295,84/03/01,8403190314
- --8403190334 IE Insp Repts 30-295/83-27 & 50-304/83-28 on 831122-840202 Violation noted failure to follow plant procedures re source handling, to evaluate radiological hazards & to control access to high radiation area LOVENDALE, P C Region 3, Office of Director 50-304/83-28 84/02/27 14pp 22673 201 24X Fiche 50-295.84/03/01.8403190314

- 84031903P5 Informs that requested info re core exit thermocouples & subcooling margin monitors ger NUREG-0737 & Generic Ltr 82-28 will be provided by 841231 WITHERS D Portland General Clectric Co GL-82-28 84/03/12 FISENHUT D 0 Division of Licensing 1p 22673 239 24X Fiche 70-344,84/03/12,8403190325
- B40.3190245 Forwards clarification of previous responses to NRC Questions 8, 7, 12 & 13 re discharge piping sys & "EPRI PWR Safety & Relief Valve Test Program Guide" Info satisfies requirements of TMI Item II D I MEDFORU, M O Gouthern California Edison Co B4/03/14 KNICHTON, O W Licensing Branch 3 lipp 22679 079 24X Fiche 50-361, 84/03/14, 8403190345
- B403190355 Forwards revised schedule re safety assessment sys/safety parameter display sys per Suppl 1 to NUREG-0737 Assessment indicates contractor capable of completing job 0.700LE.J D Consolidated Edison Co of New York, Inc 84/03/12 EBENNUT.D 0 Division of Licensing 4pp 22675 176 24X Fiche 50-247,84/03/12,8403190355
- B403190363 Forwards evaluation of LILCO transition plan per NUREG-0654/ FEMA-REP-1.Rev 1 Deficiencies noted SPECK.S W Federal Emergency Management Agency 84/03/15 DIRCKS.W J Opfice of the Executive Director for Operations 719p 22673 081 24X Fiche 50-322,84/03/15,8403190363
- B403190379 Forwards IE Insp Rept 50-305/83-17 on 031216-040215 No noncompliance noted SHAFER W D Region 3, Office of Director 84/02/27 GIESLER.C W Wisconsin Public Service Corp 2pp 22675 209 24X Fiche 50-305.04/02/27.8403190379
- --8403190384 IE Insp Rept 50-305/83-17 on 831219-040215 No noncompliance noted Major areas inspected maint.surveillance, independent insperegional requests & operational safety NELSON, R C., JACKIN, I N. Region 3. Office of Director 84/02/24 5pp 22675 211 24X Fiche 50-305.84/02/27,8403190379
- 840319039? Provides updated info re mods required by NUREO-0737. Item
 11 D 1 2 re safety & relief valve performance Unit 1 piping
 & supports will be installed during meit refueling outage
 scheduled for 850105
 MUSDLF.D Northern States Power Co 84/03/14 Office of Nuclear
 Reputul Regulation. Director 1p 22675 192 24X
 Fiche 50-282.84/03/14.8403190397
- 8403190437 NUREG/CR-3646
 ASSESSMENT OF THE IMPLICATIONS OF CONVERSION OF UNIVERSITY RESEARCH AND TRAINING REACTORS TO LOW ENRICHMENT URANIUM FUEL
 HARKIS, D.R. BURN, R.R. CLARK, L. Rensselaer Polytechnic Institute,
 1 Troy, NY FIN D-1126 84/02/29 Division of Accident Evaluation 165pp Available at NRC \$5.50 22690.001
- 8403190444 NUREG/CR-3508
 STANDARD SETTING STANDARDS A SYSTEMATIC APPROACH TO
 MANADING PUBLIC HEALTH AND SAFETY RISKS
 FISHCHOFF, D Decision Research. Inc * Dak Ridge National
 Laboratory FIN B-0424 DRNL/SUB-7576/3 84/02/29 Division of
 Risk Analysis Adop 22681 004
- BAOB190449 NUREG/CR-3573
 PERSONNEL EXPOSURE FROM RIGHT CYLINDRICAL SOURCES (PERCS)
 The Theory.The Code And Examples
 REECE.W D. HADLEY.R T. HARDTY.R Battelle Memorial Institute.
 Pacific Northwest Laboratories FIN B-2412 PNL-4923 B4/01/31
 Division of Engineering Technology 173pp Available at NRC 45 50 22680 170
- 8403200005 Responds to 840227 request for add1 action to verify aspects of overhead crane design at facility.per NUREC-0612 guidelines Crane safety & reliability satisfactory GUCHA,L T Georgia Power Co NED-84-127 84/03/12 STOLZ.J F Operating Reactors Granck 4 2pp 22685 207 24X Fiche 50-321.84/03/12.8403200003
- 8403200053 Forwards monthly operating repts for Feb 1984 & revised monthly operating repts for Aug 1983 Jan 1984 Revs reflect values reserved from beginning of commercial operation, per NUREG-0020
 HAYNES, J 9 Southern California Edison Co 84/03/15 Office of Resource Management, Director 19, 22685 001 24X Fiche 50-351,84/03/15,8403200053
- 8403200099 Forwards schedule for implementation of 'Ltivities for control of heavy loads.per NRC requests re NU-FO-0612 Cask pit gete listing lugs will be modified by 84 015 HUKILL. H D General Public Utilities GPU 'Lrvice Corp 3211-84-2072 84/03/15 EISENHUT. D O Division of Licensing Opp 22685 313 24X Fiche 50-289,84/03/15.84032000079

- 84032001/7 Forwards comparison of proposed radiological effluent Tech Specs (RETS) w/model BMR RETS & comparison of proposed offsite dose calculation manual w/NRC generic guidelines & NUREO-0133 CRUTCHTIELD.D Operating Reactors Branch 5 LS03-84-03-021 84/03/15 VANDEWALLE,D J Consumers Power Co 157pp. 22697 206 24X Fiche 50-135,84/03/15,8403200177
- 8403200185 Affirms resolution of TMI Action Plan Item II, K 3 31 re small break LOCA analysis No further action necessary JENS, H H Detroit Edison Co GL-83-35 84703714 YOUNGBLOOD, B, J Licensing Brench i 2pp 22686 338 24X Fiche 50-341.84703714, 8403200185
- B403200223 Application for amend to Licenses DPR-58 & DPR-74.revising Tech Specs re reactor coolant vent sys per TMI Item II B 1 Justification for NSHC provided in 840120 ltr still applicable ALEXICH.M P Indiana & Michigan Electric Co AEP NRC 0584C 84/03/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 22670 170 24X Fiche 50-315.84/03/15,8403200223
- ---B403200228 Revised proposed Tech Specs for reactor coolant vent sys per THI Item II B i w Indiana & Michigan Electric Co 84/03/15 7pp 22690 192 24X Fiche 50-315.84/03/15,8403200223
- 8403200225 Advises that similarity of Unit 1 & 2 175-ton polar crane verified by noting that cranes purchased under same contract w/same vendor.using identical procurement specs.per NUREG-0612 & 840223 telcon MILLS.L M Tennessee Valley Authority 84/03/14 ADENSAM.E Licensing Branch 4 2pp 22699 361 24% Fiche 50-390.84/03/14, 8403200225
- B40320023B Comments on DES (NUREO-1033) Assertions re socioeconomic impacts from station operation demonstrate low level of expertise among study team or refusal to consider relevant research findings on social impacts
 FREUDENBURG, W. Washington State Univ , Pullman, WA 84/03/12, VIETTIA Division of Licensing 2pp 22691 111 24X
 Fiche 50-508,84/03/12,8403200238
- 8403200261 Advises that control equipment for air operators CSP-AD-5, CSP-AD-6 & CSP-AD-9, listed on Table B of 10CFR50 49 justification for interim operation revised to not qualified Status to be upgraded by 850331 commitment date SDRENSEN, 6 C Washington Public Power Supply System 6D2-84-131, 84/03/14 SCHWENCER, A Licensing Branch 2 2pp 22690 199, 24X Fiche: 50-397, 84/03/14, 8403200261
- 8403200358 NUREG/CR-3501
 THE EFFECTS OF DELAYING THE OPERATION OF A NUCLEAR POHER
 PLANT
 HILL,L J, RAINEY,J A, TEPEL,R C Oak Ridge National Laboratory,
 FIN B-0472 ORNL/TM-8684 84/01/31 Division of Health, Siting &
 Waste Management 47pp 22707 010
- 8403210030 Forwards justification for exemption from Type C leak testing, list of isolation valves within easential sys & penetration isometric drawings re finalization of Tech Bpecs in preparation for OL COOK, K W Louisiana Power & Light Co W3PB4-0577 84/03/16. KNIGHTON, G W Licensing Branch 3 17pp 22707 016 24X Fiche 50-382,84/03/16. 8403210030
- 8403210061 Forwards response to 840202 request for add1 info re NUREG-0737, Items II F 1 4, "Containment Pressure Monitor Syt," II F 1 5, "Containment Water Level Monitor Sys" & II F 1 6, "Containment Hydrogen Monitor Sys" & ZIMERMAN, S R Caroline Power & Light Co NLS-84-111 84/03/09, VASSALLO, D B Operating Reactors Branch 2 20pp 22705 001, 24X Fiche 50-324.84/03/09,8403210061
- 8403210068 "1983 Annual Rept " W/840301 ltr HEIDER,L.H Yankee Atomic Electric Co FYR 84-27 83/12/31. NURLEY.T E Region 1. Office of Director 9pp. 22705'043 24X Fiche 50-029,83712/31,8403210068
- 8403210129 Responds to 840202 request re TMI Action Item II. K. 3. 18 concerning automatic depressurization sys (ADS) logic mods High drivestly permissive eliminated & manual inhibit switches to ADS logic added HOME.P W Carolina Power & Light Co NLS-84-102 84/03/09 VASSALQ,D B Operating Reactors Branch 2 lp 22707.235 24X Fiche 50-324,84/03/09,8403210129
- 8403210175 Forwards HD Hukill B40222 & 27 ltrs re emergency feedwater sys flow instrumentation & NUREO-0737 selective item status, respectively Svr list encl
 BAXIERIT A Shaw, Pittman, Potts & Trowbridge BAXTERITA,
 Metropolitan Edison Co DS8 005 84/03/20 CHILK,S, J Office of the Secretary of the Commission 27pp 22710 104 24X
 Fiche 50-269.84/03/20,8403210175

- 8403210195 Requests identification of any potential problems in completing NUREG-0737 items by Sept 1984 Response requested within 30 days of itr receipt VARGA.8 A Operating Reactors Branch 1 84/03/02 CLAYTON,F L Alabama Power Co 2pp 22709 176 24X Fiche 50-348,84/03/02,8403210195
- B403220012 Forwards responses to listed B31207 requests for info re environ qualification of electrical equipment including resolution of deficiencies & TMI action plan items (NUREG-0737) to be installed at end of Cycle iO outage FIEDLER.P B General Public Utilities GPU Service Corp 84/03/16 CRUTCHFIELD. D Operating Reactors Branch 5 18pp 22712 343 24X Fiche 50-217,84/03/16,8403220012
- 8403220093 Ack receipt of 840306 ltr informing NRC of corrective actions re deviation from commitment & resolution of revised emergency plan SER clarification items noted in IE Insp Repts 50-266/83-25 & 50-301/83-25 FAPERIELLO, C J Region 3, Office of Director 84/03/19 BURBIELIN, 8 Wisconsin Electric Power Co ip 22716 324 24X Fiche 50-266.84/03/19,8403220093
- --8403220099 Responds to NRC 840202 ltr forwarding revised emergency plan BER & request for clarification of listed items & deviation from commitment Corrective actions Procedure EP 5 0. "Organizational Control of Emergencies," revised FAY.C W Wisconsin Electric Power Co 84703/06 KEPPLER, J G Region 3. Office of Director 7pp 22716 325 24X Fiche 50-266,84703/19,8403220093
- B403220074 Forwards IE Insp Repts 50-454/84-10 & 50-455/84-08 on B40131,0201-03 & 07-10 No noncompilance noted PAPERIELLO. C J Region 3, Office of Director 84/03/07 REED.C Commonwealth Edison Co 2pp 22716 311 24X Fiche 50-454.84/03/07.
- --8403220097 IE Insp Repts 50-454/84-10 & 50-455/84-08 on 840131,0201-03 & 07-10 No noncompliance noted Major areas inspected preoperational radiation protection program. Including organization, staffing, training & NUREQ-0737 items HUETER: L J . OREOER, L R Region 3. Office of Director 50-455/84-08 84/03/07 ilp 22716 313 24X Fiche 50-454,84/03/07.8403220094
- 8403220107 Forwards safety evaluation re TMI Item II K 2 17.
 "Potential for Voiding in RCB During Transients " Safety
 evaluation documenting completion of item encl
 STDL7.JF Operating Reactors Branch 4 84/03/05 HUKILL.H D
 General Public Utilities GPU Service Corp 4pp 22723, 288 24X
 Fiche 50-289.84/03/05.8403220107
- B403220143 Forwards IE Insp Rept 50-322/B4-02 on 840123-0226 No violations found BTAROSTECKI,R Division of Project & Resident Programs 84/03/04 POLLOCK,M S Long Island Lighting Co 2pp 22714.317 24X Fiche: 50-322, 84/03/04, 8403220143
- --8403220160 IE Insp Rept 50-322/84-02 on 840123-0226 No violations found Major areas inspected IE Bulletin 80-07 (Detail 3), TMI action items, review of empreency diesel generator testing & previously identified insp findings PETRONE.C., SHEDLOSKY.T. MCCABER.E C Region 1, Office of Director IEB-80-07 84/02/28 10pp 22714 317 24X Fiche 50-322,84/03/06,8403220143
- 8403220162 Application to amend Licenses DPR-24 & DPR-27, changing Tech Specs to add add1 restrictions on heavy loads over spent fuel pool & making additions & deletions re safety-related snubbers; per IE Bulletin 79-14 & Item II D i FAY, C. W. Wisconsin Electric Power Co IEB-79-14 84/03/16 DENTON: HR Office of Nuclear Reactor Regulation, Director MILLER, T R Operating Reactors Branch 3 4pp 22718 057 24X Fiche. 50-266, 84/03/16, 8403220162
- 8403220189 NUREQ-0430 V04 N01 LICENSED FUEL FACILITY STATUS REPORT Inventory Difference Data, January 1983 - June 1983 (Grey Book) ** Director's Office, Office of Inspection and Enforcement 84/03/31 14pp 22721.097
- 8403220192 Forwards "Control of Heavy Loads, Phase II " Rept result of review of crane operation, design & maint including analysis of load drop risk to safety-related equipment beneath travel paths Confirms defense—in depth, per NUREG-0612.

 WHITTIER O D. Mains Yankee Atomic Power Co GDW-84-33. 84/03/19 MILLER, J R Operating Reactors Branch 3 2pp 22717 048 24X Fiche. 50-309. 84/03/19, 8403220192
- ---8403220199 "Control of Heavy Loads, Phase II"

 * Maine Yanker Atomic Power Co 2763L-SEN 84/03/19 124pp
 22717:050, 24X Fiche 50-309,84/03/19,8403220192.

- B403220215 Notification of B40327 meeting w/Westinghouse & Westinghouse Owners Group Procedures Subcommittee in Bethesda.MD to discuss how EPG task analysis addressed operator info & control needs.per NUREG-0737.Suppl 1 CLAYTON.H B Procedures & Systems Review Branch GL-82-33 G4703705 ZIEMANN.D L Procedures & Systems Review Branch 2pp 22721 361
- 8403220301 Forwards interim draft SER (NUREQ-1047) identifying unresolved issues as open items Complete draft SER expected to be reissued in May 1984 Detailed agenda aimed at resolving open items requested SCHWENCER. A Licensing Branch 2 84/03/08 RHODE. Q K Niagara Hohawk Power Corp 456pp 22720 001 24X Fithe 50-410,84/03/08,8403220301
- B403220326 NUREG-097B FC
 MARK 111 LOCA-RELATED HYDRODYNAMIC LOAD DEFINITION Generic
 Technical Activity B-10
 * Division of Systems Integration (pust 811005) 84/02/29 75pp
- B403230007 Ack receipt of B40221 order confirming commitments to implement post-TMI-related items in Suppl 1 to NUREG-0737 re emergency response capability status for completing each basis requirement submitted CROUSE, R P Toledo Edison Co 1033 84/03/20 EISENHUT, D G Division of Licensing App 22730 133 24X Fiche 50-344,84/03/20,840320009
- 840323002? Forwards response to request for add1 info concerning Suppl 1 to NUREG-0737 re procedures generation package & Rev 1 to emergency procedures guidelines COUNSIL.W 0 SEARS.C F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W 0 Northeast Utilities A03666 84/03/09 CRUICHFIELD.D Depending Reactors Branch 5 44pp 22728 210 24X Fiche 50-245.84/03/09.8403230029
- 8403230040 Responds to NUREG-0737. Item II D 1 re relief & safety valve testing.per 840215 Itr Facility adequately represented by EPRI valve tests Precaution of 1.000 psig overly conservative HUXILL.H D General Public Utilities GPU Service Corp 5211-84-2073 84/03/20 STOLZ.JF Operating Reactors Branch 4 ip 22724 331 24X Fiche 50-289,84/03/20,8403230040
- 8403230057 NUREQ/CR-3622
 A PROBABILISTIC MODEL OF ANNULAR-DISPERSED FLOW IN A REACTOR SUBCHANNEL AS SEEN BY CYL.INDRICAL GEOMETRY IMPEDANCE PROBES ALLGODD, O O . ROBERTS, M J Oak Ridge National Laboratory FIN B-0414 DRNL/IM-8841 84/02/29 Division of Accident Evaluation 49aa 22742 300
- B403230068 LER 84-001-00 on 840223, pipe snubber ID 2H9-M75 removed for NUREG-0737 mod prior to obtaining Tech Spec change allowing removel Snubber reinstalled within 72 h Tech Spec change to delete snubber initiated W/640315 ltr
 FAY.C W Wisconsin Electric Power Co 84/03/15 KEPPLER, J G Region J, Office of Director 3pp 22726 324 24X
 Fiche 50-301,84/03/15.8403230068
- 8403230085 Forwards safety evaluation of BWR Owners Group generic response to NUREG-0737. Item II K 3 45 re depressurization w/other than automatic depressurization sys (ABS) No mods to plant design & operation required GRUTCHFIELD.D Operating Reactors Branch 5 L805-84-03-027 84/03/20 COUNSIL,W 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) Opp 22726 335 24X Fiche 50-245,84/03/20,8403230985
- B403230131 NUREG/CR-3145 VO2
 GEOPHYSICAL INVESTIGATION OF THE WESTERN OHIO INDIANA
 REGION Annual Report, October 1982 September 1983
 PULLACK, H N . CRRIBTENSEN, D Michigan, Univ of, Ann Arbor, MI
 B4/03/30 Division of Health, Siting & Waste Management. 64pp
 22/39 232
- 8403230133 NUREG/CR-3829
 REVIEW OF THE ARKANSAS NUCLEAR ONE GENERATING STATION UNI:
 NO 1 EMERGENCY FEEDWATER SYSTEM RELIABILITY ANALYSIS
 YOUNGBLOOD, R. PAPAZOGOLOU, I A Brookhaven National Laboratory
 BNL-NUREG-5172! 84/02/29 Division of Safety Technology 104;
 22739 130 24X Fiche 50-313,84/02/29,8403230133
- B403230143 Forwards corrected safety evaluation re NUREC-0737.

 Item 11 K 3 44, "Evaluation of Anticipated Transients w/Single Failure to Verify No Fuel Failure " Item resolved for facility CRUTCHFIELD.D Operating Reactors Branch 5 LS05-B4-03-031 B4/03/22 VANDEWALLE.D J Consumers Power Co 5pp 22730 142 P4X Fichs 50-155.84/03/22.8403230143

8403230173 NUREG/CR-3560 403230173 NUREGYCR-3560
EVALUATION METHODS FOR THE CONSEQUENCES OF BELOW WATER TABLE
HINE DISPOSAL OF URANIUM MILL TAILINGS
MCKEON.T J. NELSON.R W Battelle Hemorial Institute. Pacific
Northwest Laboratories FIN B-2370 PNL-4904 84/01/31
Division of Health. Siting & Waste Management 90pp 22742 217

8403230177 NUREG/CR-3104 AQUIFER RESTORATION TECHNIQUES FOR IN-SITU LEACH URANIUM

mines DEUTSCH.W J . BELL.N E . MERCER.B W Battelle Memorial Institute, Pacific Northwest Laboratories FIN B-2379 PNL-4583 84/02/29 Pacific Northwest Labbratories FIN B-2379 PNL-4583 84/02/29 Division of Health. Siting & Haste Hanagement 58pp Available at NRC \$4 50 22739 121

8403230183 NUREQ-0750 V18 NO4

NUCLEAR REGULATORY COMMISSION ISSUANCES October 1983 Pages 743-1/137 + Division of Technical Information & Document Control B3/10/31

22813 040

B403230190 NUREG-1015 STATE SURVEILLANCE OF RADIDACTIVE MATERIAL TRANSPORTATION

Sinal Report
SALOMON,S N Office of State Programs, Director 84/02/29 72pp
Available at NRC \$4 50 22759 048

8403230197 NUREG/CR-3390

DDCUMENTATION AND USER'S GUIDE UNSAT2 - VARIABLY SATURATED FLOW MODEL (Including 4 Example Problems)
DAVIS.1. A NEUMANN.S P Hater, Waste & Land, Inc FIN B-7361
WHL/TM-1791-1 B3/12/31 Division of Waste Management 218

8403230200 NUREG/CR-3621 SAFETY SYSTEM STATUS MONITORING LEMIS.J.R. MORGENSTERN.M., RIDEOUT.T B Battelle Memorial
Institute, Pacific Northwest Laboratories FIN 8-2360 PNL-4832
84/03/31 Division of Human Factors Safety 129pp Available at
NRC \$5.50 22741 077

8403230207 NUREG/CR-3674
DESIGNING VEGETATION COVERS FOR LONG-TERM STABILIZATION DESIGNING VENERATION CUVERS FOR LANGUIGN GRADILITATION OF URANIUM HILL TAILINGS
BEEDLOW, P A Battelle Memorial Institute, Pacific Northwest
Laboratories FIN 8-2370 PML-4986 84/03/31 Division
Health, Siting & Waste Management 103pp 22741 207 Division of

B403230208 NUREG/CR-3661
PROTOTYPICAL STEAM GENERATOR (MB-2) TRANSIENT TESTING
PROGRAM Task Plan/Scaling Analysis Report
VOUNG.M , TAKEUCHI.K , MENDLER.J
B-B252 EPRI NP-3494 B4/03/31 Division of Accident Eval
196pp Available at NRC \$6 00 03/31 Division of Accident Evaluation \$6.00 22743 096

8403230212 NUREG-0606 VO& ND1 UNRESD VED SAFETY ISSUES SUMMARY Data As of February 17.1984 (Aqua Book) * Management Information Branch 84/02/29 55pp 22743 294

8403230216 NUREG/CR-3224
AN ASSESSMENT OF CREW CORE DISRUPTIVE ACCIDENT ENERGETICS
THEOFANOUS.T G. BELL.C R Los Alamos Scientific Laboratory FIN
A-7271 LA-9716-MS 84/03/31 Clinch River Breader Reactor
Program Office 436pp Available at NRC \$8 50 22740 001 24X
Fiche 50-537.84/03/31.8403230216

8403230238 Advises that, based on review of 831125 submittal of detailed control room design, specific areas of program plan do not meet requirements of Suppl i to NUREG-0737 Meeting requested to resolve deficiencies STOLZ.JF Operating Reactors Branch 4 84/03/06 GRIFFIN.JM Arkansas Power & Light Co 2pp 22739 278 24X Fichm 50-313.84/03/06.8403230238

B403260006 Informs that functional training for personnel necessary to staff requirements per Table B-1 of NUREG-0654 & staff key emergency program positions not included in Table B-1 complete, per License Condition 24 & SSER 4 SDRENSEN.0 C Washington Public Power Supply System. G02-84-154 B4/03/19 SCHMENCER.A Licensing Branch 2 1p 22747 357 24X Fiche 50-397,84/03/19.8403260006

8403250050 Requests identification of any potential problems or items re completion of NUREG-0737 items by Sept 1984 Response requested within 30 days of ltr receipt VARGA.8 A Operating Reactors Branch 1 84/03/02 UDERITZ.R A Public Service Electric & Gas Co of New Jersey 3pp 22763 281 24X Fichs 50-272.84/03/02.8403250050

8403260051 Application to amend Licenses DPR-51 & NPF-6, changing Twch Specs re RCS vents, post-accident sampling, long-term auxiliary feedwater sys evaluation, noble gas monitor & iodine particulate sampling, per NUREG-0707 items. ORIFFIN.J M Ariansas Power & Light Co QL-83-37 84/03/16, STOLT, J F Operating Reactors Branch 4 MILLER, J R. Operating Reactors Branch 3 9pp 22750 293 24X Fiche 50-313, 84/03/16, 260729.051

--8403260157 Proposed Tech Spec changes to RCS vont post-accident sampling, long-term auxiliary feedwater sys evaluation, noble gas monitors, iodine particulate sampling & containment water level monitor * Ariansas Power & Light Co B Fiche 50-313,84/03/16,8403260051 84/03/16 27pp 22750: 302. 24X

B403260056 NUREG/BR-0051 V05 N5 POWER REACTOR EVENTS September-October 1983. MASSARO, S A Director's Office 84/02/29 37pp 227A3:190.

8403240069 Forwards evaluation of 830718 request for deletion of steam electric station license condition re low-pressure turbine disc insp NRC maintains position in SER (NUMEQ-0797) that insp must be conducted YOUNOBLOOD B J Licensing Branch I 84/02/28 GARY, R J, Texas Utilities Electric Co. (Formerly Texas Utilities Generating Co). 2pp 22763 235 24X Fiche 50-445,84/02/28,84032400049

8403260078 Forwards IE Insp Rept 50-382/84-05 on 840123-27. No violations or deviations identified Status of actions taken re previously identified insp findings examined JOHNSON.E H Region 4, Office of Director 84/02/27, LEDDICK, R 9 Louisians Power & Light Co 2pp. 22758; 274. 24X Fiche 50-382,84/02/27,8403260078

--8403260087 IE Insp Rept 50-382/84-05 on 840123-27 No violations or deviations identified Major areas inspected radiation protection program & implementing actions for NUREO-0737 action items CHANEY.H D , MURRAY.B , CROSSMAN.W A Region 4, Office of Director 84/02/27 13pp 22758-276, 24X Fiche 50-382,84/02/27,8403260078

8403260113 Forwards FEMA review of Rev 3 to util transition plan for offsite emergency preparedness.per NUREQ-0654.
MARTIN.T T Division of Engineering & Technical Programs. 84/03/PDLLOCK, M S Long Island Lighting Co 3pp 22758:001 24X Fichs 50-382.84/03/20.8403260113

-8403260117 Review of Rev 3 to util transition plan for offsite emergency preparedness, per NUREG-0654.

* Federal Emergency Management Agency, 84/02/10 64pp
22758 004 24X Fiche 50-322,84/03/20,8403260113.

B403240143 Forwards general position statement on Reg Guide 1 97.Rev 2 re justification of significant generic deviations: per NUREO-0737. Suppl 1 COUNSIL.W 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) SEARS.C F Connecticut Yankee Atomic Power Co. COUNSIL.W 0 Northeast Utilities. A02959 B4/02/29 HILLER, J R. Operating Reactors Branch 3 3pp 22758-162 24X Fiche 50-000.84/02/29,8403260143

B4032601B2 Clarifies NUREG-0737, Item II, K 3 3i, in response to Generic Ltr 83-35 Westinghouse Owners Group authorized program to demonstrate conservatism of WFLASH small break LOCA analyses, per Item II K 3 30
BARNES, Pt. Commonwealth Edison Co. GL-83-35, 84/03/2i, EISENHUT, D G Division of Licensing 1p. 22756, 170, 24x
Fiche 50-000, 84/03/2i, 8403260182

8403260200 Comments on Issue 3 of NUREG-0885, "NRC Policy & Planning Guidance, 1984 " Seven themes identified represent important objectives for industry CDUNSIL, H 9 North-set Utilities 811048, 84/03/12, DIRCKS, H J. Office of the Executive Director for Operations. 4pp. 22756-204. 24X Fiche 50-000, 84/03/12, 8403260200.

B40326020B Corrects erroneous statement from B30425 response to Generic Ltr B3-02. "NUREG-0737 Tech Specs." re Action Item II E.4 i, "Dedicated Hydrogen Penetration " Purge/repressurization sysused as backup for combustible gas control MCGAUGHY, RW I Gow Electric Light & Power Co. GL-83-02. 84/03/20 DENTON, H Office of Nuclear Reactor Regulation. Director. 1p. 22756 166 24% Fiche 50-331,84/03/20,8403260208

8403260212 Forwards revised info re monorail paths.updating util 840206 ltr responding to Generic Ltr Bi-07 concerning NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants." Field investigation will be provided I month prior to fuel load, MILLS,L M Tennessee Valley Authority QL-81-07, 84/03/20 ADENSAM,E Licensing Branch 4 2pp 22736-164, 24% Fiche 50-390,84/03/20,8403260212.

- 8403260261 Forwards order confirming licensee commitment to implement post-TMI-related itmes in NUREG-0737. Suppl 1 (Generic Ltr 82-33), "Requirements for Emergency Response Capability " BTOLZ.J F Operating Reactors Branch 4 QL-82-33 84/02/21 BECKHAM.J T Qeorgia Power Co 3pp 22763 179 24X Fiche 50-321,84/02/21,8403260261
- --8403260265 Order confirming licensee commitments on emergency response capability requirements set forth in NUREG-0737, Suppl 1 (Generic Ltr 82-33) EISENHUT, D. O Division of Licensing OL-82-33 84/02/21 Georgia Fower Co App 22763 182 24X Fiche 50-321,84/02/21,8403260261
- B403260280 NUREC/BR-0025 V10 N2 INFORMATION REPORT ON STATE LEGISLATION LANDAU.M Office of State Programs, Director 84/03/10 7pp 22761 307
- 8403260286 NUREG/CR-3153 CALCULATION OF FLUID CIRCULATION PATTERNS IN THE VICINITY OF SUBMERGED JETS USING ORBHAC PARK, J E , CROSS, K E Oak Ridge National Laboratory FIN B-DRNL/TH-8653 B3/12/31 Division of Health, Siting & Wast FIN R-OLAR DRNL/TM-8653 B3/12/31 Division of Health, Siting & Waste Hanagement 130pp Available at NRC \$6.50 22761 176
- 8403260289 NUREG-0540 VOS NIZ TITLE LIST OF DOCUMENTS MADE PUBLICLY AVAILABLE December
- 8403260305 Forwards draft NUREG-1042. "Tech Specs, Susquehanna Steam Electric Station" CURTIE, N W Pennsylvania Power & Light Co PLA-2114 84/03/20 DENTON.H R Office of Nuclear Reactor Regulation, Director 480, 22753 158 24X Fiche 50-388,84/03/20,8403260305
- 8403270003 Responds to open item identified in util integrated assessment (NUREO-0825), SEP Topic III-5. A Analysis performed per ANSI/ANS 58 2 to determine force imparted on electrical penetration Blister 12E from break on Steam Generator 2 KAY, J. A Yankee Atomic Electric Co FYR 84-36 84/03/23 CRUTCHFIELD. D Operating Reactors Branch 5 3pp 22769 346 Fiche 50-029,84/03/23,8403270003
- 8403270007 Responds to open item identified in util integrated assessment (NUREG-0825). Topic III-10 A Util established criterion per Rag Guide i 106 for thermal overload protection for motor operated valves
 KAY, J A Yankee Atomic Electric Co FYR 84-37 84/03/22 CRUTCHFIELD.D Operating Reactors Branch 5 3pp 22769 350 Fiche: 50-029, 84/03/22, 84/03/20007 22769 350 24X
- 840327000B Informs that util will provide info re planned deviations from Suppl I to NUREQ-0737 by 840501 Detay has no effect on schedules for implementation of Suppl I to NUREQ-0737 COUNSIL, W Q Connecticut Yankee Atomic Power CO SEARS, C F Mortheast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W Q, Northeast Utilities A02795 84703/16 EISENHUT, D C Division of Licensing 2pp 22770 011 24X Fiche 30-000,84/03/16. B403270008
- 8403270043 Informs that ultrasonic test exams of blend radii area & magnetic particle sxam conducted by vessel mfg to determine degree of conformance to NOREG-0619 No recordable indications found utilizing either technique JENS.W H Detroit Edison Co EF2-67,715 84/03/21 YOUNOBLOOD, B J Licensing Branch 1 1p 22769'315 24X Fiche 50-341,84/03/21,8403270043
- 8403270103 Forwards test exemptions required to perform NUREQ-0737, Item I Q I, "Natural Circulation Testing "Exemptions need to be included in Tech Specs TUCKER,H B. Duke Power Co. 84/03/21 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAN,E Q Licensing Branch 4, 5pp. 22766 341 24X Fiche 50-413,84/03/21,8403270103
- 8403270106 Forwards BER for SEP outstanding hydrologic issues identified during review of integrated plant safety assessment rept (NUREG-0828) Issues include local plant flooding from PMP & flood energency plan CRUTCHFIELD.D Operating Reactors Branch 5 L605-84-03-032 84/03/22 VANDEMALLE,D J Consumers Power Co 3pp 22774: 24X Fiche 50-155,84/03/22,8403270106 22774: 032
- 8403270183 Forwards portion of combustible gas control Tech Open surveillance requirement inadvertently omitted from util 840118 response to Generic Ltr 83-37, "NUREG-0737 Tech Specs "
 DIXON, O W South Carolina Electric & Gas Co QL-83-37. 84/03/22 DENTON: HR Office of Nuclear Reactor Regulation, Director 22771 123 24X Fiche 50-395,84/03/22,8403270183

- --8403270188 Proposed change to Tech Spec 4 6 5 1 re combustible gas control hydrogen monitors * South Carolina Electric & Gas Co GL-83-37 B4/03/22 Ip 22771 125 24% Fiche 50-395, B4/03/22, 8403270183
- 8403270173 Notifies that util will provide addl info re performance testing of relief & safety valves.per Item II D i of NUREG-0737.by 840615, per 84030B agreement O'TODLE.J D Consolidated Edison Co of New York, Inc 84/03/16 VARGA, S A Operating Reactors Branch i ip 22771 102 24X Fiche 50-247, 84/03/16, 8403270193
- 8403270209 Forwards Rev 4 to util response to NUREQ-0737. Suppl 1. including control room review implementation priority schedule TUCKER, H B Duke Power Co 84/03/23 DENTON, H R Df Nuclear Reactor Regulation, Director 9pp 22772 088 Fiche 50-269,84/03/23,8403270209
- 8403270215 Provides followup to 840228 telcon re Suppl 1 to NUREG-0737. "Development of Emergency Operating Procedures." from generic Hustinghouse emergency response guidelines Development will continue as described CAREY.J J Duquesne Light Co 01-82-33 84/03/14 VARGA, S A Operating Reactors Branch 1 3pp 22770 270 24X Fiche 50-334,84/03/14,8403270215
- 8403270220 Advises that equipment qualification program & RCIC sys reviewed.per NUREG-0892, BER Dutstanding Issue 1 7(9), mods to automatic depressurization sys RCIC valves required for containment isolation remain in qualification program SGRENSEN.0 C Washington Public Power Supply System GO2-84-160 84703772 SCHMENCER.A Licensing Branch 2 1p 22770 269 24 Fithe 50-397,84/03/22,8403270220 GO2-84-160
- 8403270267 NUREG-1049 O3270267 NUREG-1049
 ENVIRONNENTAL IMPACT APPRAISAL FOR RENEHAL OF SPECIAL
 NUCLEAR MATERIAL LICENSE NO SNM-42 Docket No 70-27
 (Babcock & Wilcor Company, Naval Nuclear Fuel Division)
 ** Division of Fuel Cycle & Material Safety 84/03/31
 Avoilable at NRC \$4 50 22787 235 84/03/31 B7pp
- 64032/0269 NUREG-074B VO4 NO1

 OPERATING REACTORS LICENSING ACTIONS SUMMARY Data As Of
 January 31, 1984 (Orange Book)

 * Office of Resource Management, Director 84/03/31 332pp.
 22780 001
- B403270315 Advises that emergency plan, documented in NUREG-0746, "Emergency Preparedness Evaluation for THI-1" & Suppl 1. NUREG-0737. Item III A 2 1. complete for facility STOLZ-JF Operating Reactors Branch 4 B4/03/09 HUKILL.H I General Public Utilities QPU Service Corp 5pp 22789 241 Fiche 50-289. B4/03/09, B403270315 HUKILE H D
- 8403280048 Forwards response to 831205 request for add1 info re NUREG-0737 Item II D 1. "Performance Testing of Relief & Safety Valves " Microfiche of RELAPS/ADLPIPE computer marety varyes "natroliche briket.mb/ADLPIPE tomputer analyses encl GIESLER.C W Hisconsin Public Service Corp NRC-84-48 (VARGA, S A Operating Reactors Branch 1 36pp 22776 282 Fiche 50-305,84/03/23.8403280048 64/03/23
- 8403280066 Forwards safety evaluation re NUREO-0737.TMI Action Item
 11 K 3 44, "Evaluation of Anticipated Transients W/Single
 Failures " Facility in conformance w/NUREO-0737 position &
 evaluation acceptable
 CRUTCHFIELD.D Operating Reactors Branch 5 LSO-84-03-033
 84/03/P6 LINDER F Dairyland Power Cooperative 5pp 22776 349 24X Fiche 50-409,84/03/24,8403280065
- 8403280076 FOIA request for seven categories of documents HIATT.8 L Ohio Citizens for Responsible Energy 83/11/30 FELTON.J M Division of Rules and Records 1p 22808 243
- 8409280080 Partial response to FDIA request for seven categories of documents Forwards App A documents responsive to Items 1.2, 5.6 & 7 of request NUREO-0386. "NRC Practice & Procedures Manual," presently being updated FELTON.J M Division of Rules and Records 84/01/17 HIATT.8 Ohio Citizens for Responsible Energy 2pp 22808 244
- 8403280329 Forwards comments on detailed control room design review program plan.per 831031 submittal Plan does not comply fully w/Suppl 1 to NUREG-0737 requirements Recommends meeting in Mar or Apr 1964 VARGA.S A Operating Reactors Branch 1 84/03/09 CLAYTON.F L Alabama Power Co 17pp 22807 288 24X Fiche 50-348,84/03/09,8402980329

- 8403270002 Final response to FOIA request for four categories of documents, tests, studies & analyses referencing or pertaining to NUREG-0103, "818 for B&W PIME "App A documents enc! FELTON, J M Division of Rule4 and Record* 84/01/13 MADDEN, T J Kaye, Scholer, Fierman, Hays & Handler &pp 22816 127 24X Fiche 50-000.84/01/13.8403270002
- 8403290038 Forwards revised responses to B31123 & B40109 ltrs re approval of proposed license amend re post-accident sampling for facilities. TMI Item II B 3 MILLS.L M Tennessee Valley Authority B4/03/23 ADENSAM.E Licensing Branch 4 9pp 22806 237 24X Fiche 50-327,84/03/23,8403290038
- 8403290069 Ack receipt of 840208 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-269/83-36, 50-270/83-37 & 50-287/83-36 Implementation of corrective actions will be examined during future insp. DANCE.H C Division of Project & Resident Programs 84/03/20 TUCKER.H B Duke Power Co 1p 22807 011 24X Fiche 50-269.84/03/20.8403290069
- --8403270108 1E Insp Repts 50-269/83-36,50-270/83-37 & 50-287/83-36 on 831111-1210 Violation noted Failure to Follow Maint Procedure 270/83-37-01 re quality performed on Reactor Coolant Pump 282 BRYANT, J Region 2, Office of Director 50-287/83-36 84/01/09 10pp 22807 017 24% Fiche 50-289,84/03/20,8403270069
- 8403270078 Ack receipt of 840308 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-348/84-03 & 50-364/84-03 VERRELLI, D M Division of Project & Resident Programs. 64/03/14 MCDDNALD, R P Alabama Power Co to 22806-311 24X Fiche 50-348/84/03/14 8603290078
- --8403270103 IE Insp Repts 50-348/84-03 & 50-364/84-03 on 840111-0205 Violation found failure to implement procedures for control of maint activities. BRADFORD W,H Region 2, Office of Director 50-364/84-03 84/02/15 8pp 22806 317 24X Fiche 50-348,84/03/14,8403270078
- 8403290083 Responds to B4022i request for addl info re control of heavy loads Initial load testing performed for head strongback, Gryer separator sling & spent fuel cask yoke IIMMERNAN.B R Carolina Power & Light Co NLS-84-094 84/03/20 VASSALLO.D B Operating Reactors Branch 2 2pp 22806 325 24X Fiche 50-324.84/03/20,8403290083
- B403290100 Informs that util expects to complete commitment on NUREO-0737. Item 11 B 3 re post-accident sampling sys by June 1985
 BAYNE.J P Power Authority of the State of New York. IPN-84-11
 B4/03/23 VARQA.S A Deprating Reactors Branch 1 Ip 22806 356
 24% Fiche 50-286.84/03/23.8403290100
- 8403290110 Forwards J Preston B30104 memo re generic safety issues prioritization methodology for placement in PDR RDBERTS.B J ACRS Advisory Committee on Reactor Safeguards 84/03/14 MCKNIGHT.J Distribution Services Branch 1p. 22822-214
- --B403290113 Advises of review of generic safety issues prioritization methodology described in NUREO-0933 Inherent limitations of value impact score formula discussed Use of structured & iterative consensus judgement methodology recommended PRESTON. J ACRS Advisory Committee on Reactor Safeguards B3/01/04 BENDER. M ACRS Advisory Committee on Reactor Safeguards 3pp 22822 215
- 8403270250 Ack receipt of 840304 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-338/83-31 & 50-339/83-31 & EAST-STATE OF THE STATE OF THE ST
- ---8403270271 IE Insp Repts 50-338/83-31 & 50-339/83-31 on 831204-840105 Noncompliance noted failure to maintain procedures re insp of wall & failure to inspect fire barriers LUEHMAN, J G Region 2. Office of Director 50-339/83-31 84/02/06 9pp 22802.040 24X Fiche 50-338,84/03/14,8403290250
- 8403290289 Forwards IE Insp Repts 50-338/84-01 & 50-339/84-01 on 840104-0205 No violations or deviations identified DANCE: H C Division of Project & Resident Programs. 84/03/05 STEHART, W.L Virginia Electric & Power Co 2pp. 22800.048 24 Fiche 50-338,84/03/05,8403290289.

- --B403290294 IE Insp Repts 50-338/84-01 & 50-339/84-01 on 840106-0205 No violations or deviations identified Major areas inspected onsite areas of surveillance & maint activities, previous insp findings & identified items & safety sys walkdowns BRANCH, M W , LUEHMAN, J Ø Region R, Office of Director ELROD, 8 Division of Project & Resident Programs 50-339/84-01 84/03/02 10pp 22800 050 24% Fichs 50-338,84/03/05,8403290289
- B403270296 Comments on proposed rule 10CFR60 & NUREQ-1046 re disposal of high level radwastes in unsaturated zone HILLIAMB.R E Williams & Associates NRC-02-82-046 49FR5934 003 84703/15 PONLE: J Division of Waste Management 2pp. 22800 178
- 8403290317 Forwards IE Insp Repts 50-335/84-05 & 50-389/84-07 on B40206-10 No violations or deviations noted DANCE,H C Division of Project & Resident Programs 84/02/29 HILLIAMB.J W Florida Power & Light Co 2pp 22802 052 24) Fichs 50-335,84/02/29,8403290317
- --8403290320 IE Inap Repts 50-335/84-03 & 50-389/84-07 on 840206-10 No violations or deviations noted Major areas inspected health physics instrumentation, action on NUREO-0737 items, ALARA activities & followup on previous items HRAY. J R Region 2, Office of Director, BARR. P Division of Engineering & Operational Programs 50-389/84-07 84/02/22 8pp 22802 054 24% Fiche 50-335,84/02/29,8403270317
- 8403290331 Informs that NUREG-0737. Item II K 2 17. "Voiding in RCB During Transients" complete, based on util endorsement of CEN-199. "Effects of Vessel Head Voiding During " ENGHTON, G W Licensing Branch 3 84/03/08 BASKIN, K P Bouther California Edison Co. HOLCOMBE, J C San Diego Gas & Electric Co. 9pp 22822 220 24% Fichs 50-361.84/03/08,8403290331
- 8403270341 Responds to FDIA request for records re facility Ltr dtd 840117 failed to meet criteria for waiver of reproduction costs Forwards App A documents Address of Phoenix LPDR listed FELTON, J M Division of Rules and Records 84/02/27 RYAN, J. A Streich, Lang, Weeks & Cardon 3pp 22815.018
- --8403290344 NUREQ-75/022
 DRAFT ENVIRONMENTAL STATEMENT RELATED TO CONSTRUCTION OF PALO VERDE NUCLEAR GENERATING STATION, UNITS 1, 2 & 3 Docket Nos 50-528, 50-529.

 # Office of Nuclear Reactor Regulation, Director 75/04/30 17550 22815 301
- 8403300038 Forwards responses to NRC 840214-14 audit findings re util equipment qualification program.per NUREO-0847 (SER) 9/84 oversize drawings Aperture cards are available in PDR MILLS.L M Tennessee Valley Authority. 84/03/20 ADENSAM.E Licensing Branch 4 138pp 22824 146 24X Fiche 50-390.84/03/20.8403300038
- 8403300149 Forwards application for amend to License NFF-3, revising Tech Specs to reflect changes in post-accident sampling sys & post-accident instrumentation for in-core thermocouple, per NURGE-0737 & Generic LTR B3-37 GROUSE, R P Toledo Edison Co GL-83-37 84/03/22 8TOL2, J F Operating Reactors Branch 4 3pp 22821 002, 24X Fiche 50-346,84/03/22,8403300149
- --8403300156 Application for amend to License NPF-3, revising Tach Specs to reflect changes in post-accident sampling sys & post-accident instrumentation for in-core thermocouple & reactor coolant hot leg level CRDUSE, R P Toledo Edison Co OL-83-37 84/03/22. 7pp 22821-004 24X Fiche, 50-346.84/03/22.8403300149
- 8403300192 Forwards draft Rev 5 to Procedure OP-3838 re low voltage on Emergency Bus 1 or 6-3 480-volt bus, draft Rev 5 to OP-3844 re low voltage on Emergency Bus 2 or 4-1 480-volt bus & draft Rev 5 to OP-3845, per SEP Topic VIII-1, a. KAY, J A Yankee Atomic Electric Co FYR 84-39, 84/03/28, CRUICHFIELD, D Operating Reactors Branch 5 12pp 22819-251 24X Fiche 50-029,84/03/28,8403300192
- 8403300231 Advises that goal for completion of technical reviews & implementation of all NUREQ-0737 items.sxcluding Suppl i.is Sept 1984 Requests to be advised of potential problems within 30 days.

 VARGA, S. A. Operating Reactors Branch 1 84/03/13 0/TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 2pp. 22844, 338, 24% Fiche 50-247, 84/03/13, 8403300231
- 8403300232 Forwards staff comments on detailed control room design review program plan.per NUREQ-0737.Suppl 1 Some areas of plan require further description VASSALLO.D B Operating Reactors Branch 2 84/03/06 MARRIMOTON.W D Boston Edison Co. 18pp 22844 264, 24X fiche 50-293,84/03/06.8403300239

- 8403300233 Forwards comments on detailed control room design review Plan demonstrates commitment to meet requirements of Suppl 1 to NUREG-0737, however, add1 info required Meeting should be beld in Apr or May 1984 to discuss comments VARQA.5 A Operating Reactors Branch 1 84/03/13 DDLAN, J Indiana & Michigan Electric Co 12pp 22842 350 24X Fiche: 50-315,84/03/13,8403300233
- 8402300240 Summary of ACRS Bubcommittee on Human Factors 831207 meeting in Washington.DC re status of ongoing activities in NRC human factors program plan.human reliability data base & uses & review of program budget for FY85-86 # ACRS Advisory Committee on Reactor Safeguards 83/12/07 ACRS Advisory Committee on Reactor Safeguards 24pp 22842 320
- B403300261 NUREQ/CR-2896 VO1
 CONMIX-1A A THREE-DIMENSIONAL TRANSIENT SINGLE-PHASE
 COMPUTER PROGRAM FOR THERMAL HYDRAULIC ANALYBIS OF SINGLE
 AND MULTICOMPONET SYSTEMS Volume I User's Manual
 DOMANUS,H M , SCHMITT,R C , SHA.W T Argonne National Laboratory
 FIN A-2045 ANL-82-25 VO1 B4/03/31 Division of Accident
 Evaluation 327pp 22839,217
- B400300285 NUREG/CR-2896 VO2
 CDMMIX-1A A THREE-DIMENSIONAL TRANSIENT SINGLE-PHASE
 COMPUTER PROGRAM FOR THERMAL HYDRAULIC ANALYSIS OF SINGLE
 AND MULTICOMPONENT SYSTEMS Volume II Assessment And
 Verification
 DDMANUS;H N SCHMITT,R C , SHA;W T Argonne National Laboratory
 FIN A-2045 ANL-82-25 VOZ 84/02/27
 Division of Accident
 Evaluation 95pp 22840 182.
- 8403300294 NUREQ/CR-3427 VO3
 LONG-TERM PERFORMANCE OF MATERIALS USED FOR HIGH-LEVEL WASTE
 PACKAGING Third Quarterly Report October- December 1983
 STAML.D. MILLER.N E Battelle Hemorial Institute, Columbus
 Laboratories FIN 8-6744, 84/03/31 Division of Health, Siting &
 Waste Management 90pp Available at NRC \$4.75 22826 203
- B403300296 Advises that goal for completion of technical reviews & implementation of all NUREO-0737 items.excluding Suppl i.is Sept 1984 Requests to be advised of potential problems within 30 days
 VARGA.B A Operating Reactors Branch 1 '84/03/13 DDLAN.J Indiana & Michigan Electric Co. DDLAN.J American Electric Power Service Corp 2pp 22844.316 24X Fiche 50-315.84/03/13.
- 8403300300 NUREQ-0675 522
 BAFETY EVALUATION REPORT RELATED TO THE OPERATION OF DIABLO CANYON NUCLEAR POWER PLANT, Units 1 AND 2 Docket Nos 50-275
 And 50-323 (Facific Gas and Electric Company)

 Division of Licensing 84/03/31 400pp Available at NRC \$11 00, 22843 001. 24X Fichs 50-275,84/03/31,8403300300
- 8403300303 Notification of 840327 meeting w/util in Bethesda.MD to discuss detailed control room design review items relative to requirements of NUREO-0737, Suppl 1
 SILVER, H. Operating Reactors Assessment Branch 84/03/20
 STDLZ, J. F. Operating Reactors Branch 4 2pp 22844 307 24X
 Fiche: 50-287, 84/03/20, 8403300303
- 8403300306 NUREO/CR-3523
 A RANKING SCHEME FOR MAKING DECIBIONS ON THE RELATIVE TRAINING IMPORTANCE OF POTENTIAL NUCLEAR POWER PLANT MALFUNCTIONS
 SELBY, D L : HENBLEY, W T. Oak Ridge National Laboratory FIN 8-0466
 ORNL/TM-8750 84/02/27 Division of Facility Operations 12ipp 22842:190
- 840330030B Board Notification 84-054 forwards NRC evaluation & conclusion re util variance from NUREG-0737 guidance concerning high renge stack gas monator (TMI Item II.F. 1.1)
 MIRAQLIA.F.J. Assistant Director for Safety Assessment. 84/03/14
 BLOCH.F.B., PARIB.O H., SHON.F.J. Atomic Safety and Licensing Board Panel. 7pp 22844.282, 24X Fiche.50-155,84/03/14,8403300308
- 8403300317 NUREQ/CR-3334 VO3
 HEAVY-SECTION STEEL TECHNOLOGY PROGRAM GUARTERLY PROGRESS
 REPORT FOR JULY-SEPTEMBER 1983.
 RUGH, C.E. Oak Ridge National Laboratory FIN 8-0119.
 URNL/TH-8787/V3, B4/03/31 Division of Engineering Technology
 120pp. 22826-067
- 8403300318 NUREO/CR-3549
 EVALUATION OF CONTAINMENT LEAK RATE TESTING CRITERIA
 DOUGAN.J.R. Dak Ridge National Laboratory. FIN B-0489
 ORNL/TH-8909. 84/03/31. Division of Engineering Technology
 56pp. 22826,303

- 8403300325 NUREG/CR-3275
 JOB ANALYSIS OF THE ELECTRICIAN POSITION FOR THE NUCLEAR
 POWER PLANT MAINTENANCE PERSONNEL RELIABILITY MODEL
 FEDERMAN,P J. DARTTER.W D. SIECEL.A I Applied Science Associates,
 Inc FIN B-0461 ORNL/TM-8755 84/02/29 Division of Facility
 Operations 191pp 22842 007
- 8403300342 NUREO/CR-3307
 A SIMULATOR-BASED STUDY OF HUMAN ERRORS IN NUCLEAR POWER
 PLANT CONTROL ROOM TAEKS
 BEARE.A N . DORRIS, R E . DOVELL C R General Physics Corp FIN
 A-1188 SANDE3-7075 84/01/31 Division of Facility Operations
 190pp. 22844 070
- ORG CORRESPONDENCE WITH OTHER ORGANIZATIONS
- 8401190072 IE Info Notice 84-13, "Potential Deficiency in Motor Operated Valve Control Circuits & Annunciation " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 84/02/28 Consolidated Edison Co of New York, Inc 115pp 22909 239 24X Fiche 80-000,84/02/28,840119007
- 8402070007 IE Info Notice 84-14, "Highlights of Recent Transport Regulatory Revs by DOT & NRC " Svc list encl GRACE, J N Division of GA, Bafeguards & Inspection Programs (Post 830103) 84/03/02 Consolidated Edison Co of New York, Inc 130pp. 22552 329 24X Fishe 50-000.84/03/02,8402070007
- B402070008 IE Info Notice 84-16, "Failure of Automatic Sprinkler Sys Valves to Operate" Syc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/03/02 Consolidated Edison Co of New York, Inc 122pp 22553-098 24% Fiche 50-000.84/03/02,8402070008
- 8402070007 IE Info Notice 84-15, "Reporting of Radiological Releases"
 Svc list encl
 JURDANNE L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 84/03/02 Consolidated Edison Co of New
 York, Inc 117pp 22559 217 24X Fiche 50-000.84/03/02.8402070007
- 8402090011 IE Info Notice 84-17, "Problems W/Liquid Nitrogen Cooling Companents Below Nil Ductility Temp " Svc list encl JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Past 830103) 84/03/05 Consolidated Edison Co of New York, Inc 117pp 22553 336 24X Fithe 50-000,84/03/05,8402090011
- 8402070024 IE Info Notice 84-07, Rev 1. "Lessons Learned From Insps of Fire Protection Bafe Shutdown Sys " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Past 830103) B4/03/07 Combalidated Edison Co of New York, Inc 1188pp 22635 049 24X Fiche 30-000.84/03/07, 8402070024
- 8402090028 IE Info Notice 84-18, "Stress Corrosion Cracking in PWR Sys " Syc list and. JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/03/07 Consolidated Edison Co. of New York, Inc. 118pp 22584 186 24X Fiche 50-000,84/03/07,8402090028
- 8402090031 IE Bulletin 84-02, "Failures of GE Tupo HFA Relays in Use in Class IE Bafety Sys " Eve list encl DEYOUNG.R C Director's Office, Office of Inspection and Enforcement 84/03/12 Consolidated Edison Co of New York, Inc 134pp 22823:094 24X Fiche 50-000.84/03/12, 8402090031.
- 8402090043 IE Info Notice 84-19, "Two Events Involving Unauthorized Entries into PWR Reactor Cavities " Svc list encl JORDAN: E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 84/03/21 Consolidated Edison Co of New York, Inc. 123pp 22823-229 24X Fiche 50-000:84/03/21,8402090043
- 8402090044 IE Info Notice 84-20, "Byt Life of Relays in Safety-Related Sys " Byt list entl. JORDAN.E.L Division of Emergency Preparedness & Engineering Response (Post 830103). 84/03/21 Consolidated Edison Co of New York, Inc 135pp 22933 001 24% Fiche 50-000,84/03/21,8402090044
- 8403020378 Forwards request for OMB review & supporting statement re 10CFR180 concerning export & import of nuclear equipment & matls NORRY.P 9 Office of Administration 84/02/28, MACRAE, J B Office of Management & Budget 1p 22492 181
- 8403020380 Responds to approval request for info collection re-physical inventory listing Request approved through 850331 under OMB 3150-0058, per Paperwork Reduction Act MACRAE, J B Office of Management & Budget OMB 3150-0058 84/02/27 SCOTT, S Document Management Branch 2pp 22492.092

- B4030203B1 Responds to approval request for info collection re 10CFR55 concerning operator licenses Request approved through 870229 under OMB 3130-001B.per Paperwork Reduction Act MACRAE, J B Office of Management & Budget OMB 3130-001B. 84/02/19 SCOTT.S Document Management Branch 2pp 22492 074
- 8403020383 Responds to approval request for info collection re registration certificate for in vitro testing w/byproduct matl under general license Request approved through 870131 under OME 3150-0038, per Paperwork Reduction Act MACRAE. J B Diffice of Management & Budget. OMB 3150-0038 84/02/27 SCOTT. S Document Management Branch. 2pp. 22492 096
- 8403020385 Responds to approval request for info collection re 100FR95 concerning security facility approval & safeguarding of nat1 security info & restricted data Request approved through 860229 under DMB 3150-0047, per Paperwork Reduction Act, MACRAE.J B Office of Management & Budget DMB 3150-0047 84/02/17 SCDTT.8 Document Management Branch 2pp. 22492 098
- 84030203B7 Responds to approval request for info collection re 100FR75 concerning safeguards on nuclear mabl-implementation of US/ 1AEA agreement Request approved through 870131 under OHB 3150-0055, per Paperwork Reduction Act MACRAE, J 8 Office of Management & Budget OHB 3150-0055 84/02/27 SCOTT.S Document Management Branch 2pp 22492,100
- B403020388 Responds to approval request for info collection re data effort on spouse contamination. Request approved through B70229 under OMB 3150-0026, per Paperwork Reduction Act MACRAE, J B Office of Management & Budget OMB 3150-0026 B4/02/27 SCOTT. S Document Management Branch 2pp 22492 102
- 8403050004 Forwards FEMA 840206 ltm & final exercise evaluations on 830914 offsite emergency preparedness exercise. Recommendations from rest do not affect approval of plan PAPERIELLO.C. J. Region 3. Office of Director 84/02/29 REED.C. Componwealth Edison Co. 2pp 22490:240 24X Fiche 50-237,84/02/27,840305004
- 8403050125 Ack receipt of FEMA 840130 ltr & associated final exercise evaluations of \$31101 emergency preparedness exercise No deficiencies affecting public health & safety identified hased on performance of offsite agencies PAPERIELLO.C J. Region 3. Office of Director 84/02/29, 01ESLER.C W. wisconsin Public Service Corp 2pp 22489.109 24X Fiche 50-305,84/02/29,8403050125
- B403050128 Forwards "Perry Nuclear Power Station Offsite Radiological Emergency Planning," interim rept Exercise to test plans scheduled for 841128 KRIMMR W Federal Emergency Management Agency 84/03/01. JRBDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) ip 22488 223 24X Fichs 50-440.84/03/01, 8403050128
- --B403050131 "Perry Nuclear Power Station Radiological Emergency Planning," interia rept * Federal Emergency Management Agency 84/01/10. 192pp. 224BB 224 24% Ficha 50-440.84/03/01/8403050128
- B403080148 Forwards "Evaulation of Southern California Edison Site-Specific Offsite Radiological Emergency Preparedness Prompt Alert & Notification Sys Evaluation." Sys adequate to alert & notify public in event of accident SPECK. W Federal Emergency Management Agency. B4/01/31 DIRCKS W J Office of the Executive Director for Operations 1: 22487 314 24X Fiche 50-206,84/01/31,8403050148
- ---8403050172 "Evaluation of Southern California Edison Bite-Specific Offsite Radiological Emergency Preparedness Prompt Alert & Notification Bys " * Federal Emergency Management Agency 84/01/05, 61pp 22487 315 24X Fiche 50-206,84/01/31,8403030148
- 8403050162 Forwards FEMA 840201 ltr.final exercise evaluations on B31115 offsite emergency preparedness exercise & interim finding recommendations re-offsite emergency response plan for area around facility No deficiencies identified. PAPER1ELLO.C J Region 3. Office of Director 84/02/29 REED.C Commonwealth Edison Co. 2pp 22485.061, 24X Fichs 50-454.84/02/29, 8403050162
- 840306086 Approves state & local plans & preparedness for sterting & protecting gublic in event of radiological emergency.
 Approval conditional on verification of alert & notification susper criteria of App 3 of NURGO-0654/FEMA-REP-1, Rev 1
 SPECK, 8 W Federal Emergency Management Agency. 84/02/15
 DIRCKGR W J Diffice of the Executive Director for Operations 1p.
 22516 300 24X Fische 50-250,84/02/15,8403060086.

- B403060458 Responds to approval request for info collection re Sales ATMS events Request approved through 850930 under OMB 3150-0119, per Paperwork Reduction, 4c Budget OMB 3150-0119, B4/02/27 SCOTT.S Document Management Branch. 2pp 22549 319.
- 8403050460 Responds to approval request for info collection re 10CFR70 concerning domestic licensing of SMM Request approved through 870229 under OMB 3150-0009, per Paperwork Reduction Act MACRAE, J B Office of Management & Budget OMB 3150-0009. 84/02/27 SCOTT, S Document Management Branch 2pp 22549 336
- 8403040463 Responds to approval request for info collection re 10CFR31 concerning domestic licensees for hyproduct matl Request approved through 870229 under OMB 3150-0016, per Paperwork Reduction Act
 MACRAE.J B Office of Management & Budget DMB 3150-0016
 84/02/17. SCOTT, B Document Management Branch 2pp, 22549:338
- 8403070363 Forwards FEMA comments on Draft 2 of public info brochurs, for review & consideration YOUNDELOOD B J Licensing Branch 1 84/02/29 EDELMAN, M R. Clevelend Electric Illuminating Co 3pp 22567 205, 24X Fiche. 50-440
- 8403080238 Forwards "Monticello Nuclear Power Plant Bite-Specific Offsits Radiological Emergency Preparedness Evaluation" & "Monticello Nuclear Power Plant Full-Scale Joint Emergency Exercise on 830223," final rept KRIMM.R.W Federal Emergency Management Agency 84/03/05, Federal Emergency Management Agency. 3pp 22560,127 24X Fiche, 50-263,84/03/05,8403080238
- --B4030B0242 "Monticello Nuclear Power Plant Bite-Specific Diffsite Radiological Emergency Preparedness State of MN & Sherburne & Wright Counties," regional directors avaluation * Federal Emergency Management Agency 84/01/26 32pp. 22560 130 24X Fiche 50-263,84/03/05.8403080238
- ---8403080244 "Monticello Nuclear Power Plant Full-Scale Joint Emergency Exercise on 830223," final rept # Federal Emergency Management Agency 84/03/05 ilOpp. 22560 255 24X Fiche 50-263,84/03/05.8403080238
- 8403090218 Forwards evaluation rept of offsite radiological emergency preparedness exercise conducted on 830726 Deficiencies observed did not detract from overall demonstrated capability to protect public KRIM,R W Federal Emergency Management Agency 84/03/06 JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 7pp 22571:142 24X Fiche: 50-195.84/03/06.840309218
- --8403090221 Evaluation of State of MI, Charlevoix & Emmet Counties offsite radiological emergency preparadness exercise for Big Rock Point Nuclear Power Station * Federal Emergency Management Agency 83/07/26 43pp 22571 149 24X Fiche 50-155,84/03/06.8403090218
- 8403090219 Forwards applicant responses to Commission 811224 order, on behalf of Project Mgt Corp & TVA CHIPMAN, 0 L. Energy, Dept of B2/01/18, PALLADING, N. J., GILINSKY, V., ROBERTS, T.F. Commissioners, 101pp 22574:168 24X Fiche 50-537, 82/01/18, 8403090219.
- 8403130155 Advises that state & local plans & preparedness for radiological emergencies adequate Approval conditional on FEMA verification of adequacy of alerting & notification sys.per App 3 of Rev i to NUREO-0654/FEMA-REP-1.

 SPECK, S. W. Federal Emergency Management Agency. 84/03/02 DIRCKS, W J Office of the Executive Director for Operations. 2cp. 22608 229 24X Fiche 50-254,84/03/02,8403130155
- 8403130163 Forwards final rept re small-scale offsite radiological emergency preparedness exercise on 821014 No deficiencies noted KRIMH,R W. Federal Emergency Management Agency. 84/03/05. JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) App. 82599.307. 24X Fiche 50-282.84/03/05.840330163
- --8403130172 Final rept of small-scale joint emergency exercise on BR1014
 * Federal Emergency Management Agency. 82/12/17. 82pp 22599, 313 24X Fiche, 50-282, 84/03/05, 8403130163.
- B40313017: Forwards FEMA post-exercise assessment for 831026 joint exercise of State of DE & local radiological emergency preparedness plans for facility.

 MARTIN.T T Division of Engineering & Technical Programs. B4/03/0 UDERITZ.R A Public Service Electric & Oas Co of New Jersey. 39 22599, 223 24X Fiche: 80-272, 84/03/07, 8403130171.

į ¹

- --8403130178 Evaluation of 831026 joint exercise of State of DE & local radiological emergency preparedness plans for facility * Federal Emergency Management Agency 83/11/25 72pp 22599 226 24X Fiche 50-272.84/03/07.8403130171
- 8403130185 Discusses evaluation of State of IL & local plans & preparedness for facilities Flans adequate to protect health & safety of public Approved of public alert notification sys conditional on verification of criteria of NURED-0654 SPECK.S W Federal Emergency Management Agency 84/03/02 DIRCKS.W.J Diffice of the Executive Director for Operations ip 22613:316. 24X Fiche 50-275,84/03/02,8403130185
- 8403130198 Forwards evaluation of State of MN & Shelburne & Wright Counties emergency preparedness plan for 830223 full-scale exercise Identified deficiencies corrected KRIMM:R W Federal Emergency Management Agency 84/03/05 JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103). 7pp 22413 256 24X Fiche 30-263.84/03/05.8403130198
- --B403130209 Evaluation of State of MN & Shelburne & Wright Counties emergency preparedness plan for B30223 full-scale exercise # Federal Emergency Management Agency 84/03/05 63pp 22613 263 24% Fiche 50-263.84/03/05.8403130198
- 8403130419 Forwards Rev 1 of Ouidance Memo 17 Rev addresses concerns of NRC & FEMA regional staff re conducting preexercise & postressercise activities

 KRIMM, R. W. Federal Emergency Management Agency 84/03/05

 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 10pp 22608 273
- B403150018 Informs that FEMA will transmit, on or before 840402, proposal re further review of issues concerning evacuation time estimates for population, including work program estimate of resources & schedule for completion of major components.

 KRIMM.R.W Federal Emergency Management Agency 84/03/09

 JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Fost B30103) ip 22640 330. 24X Fiche 50-273,84/03/09,8403150018
- 8403150052 Forwards State of LA 831227 request for examption from full participation at 840410 annual radiological emergency preparedness exercise FEMA supports exemption based on State of LA full participation in Waterford exercise KRIMM, W Faderal Emergency Management Agency, 84/03/09.

 JDRDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 3pp 22641 355 24X Fiche 50-416,84/03/09,8403150052
- 8403150106 Forwards FEMA final exercise rept for 820319 joint exercise of state & local radiological emergency preparedness plans for facility Rept of 831005 exercise will be forwarded MARTIN, T. T. Division of Engineering & Technical Programs 84/03/09 COUNSIL.W 9 Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 22640-142 24X Fiche 50-336.84/03/09.8403150106
- 8403130113 Forwards exercise repts of 820319 & 830316 joint exercises of offsite redicingical emergency preparedness plans for Arkansas Nuclear One Power Station Deficiencies observed at both exercises, Approval under FEMA Rule 440FR330 in effect.

 KRIMM.R W. Federal Emergency Management Agency 84/03/09

 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 2pp. 22640:001 24X Fiche 50-313,84/03/09,8403150113
- --8403150119 Exercise repts of B20519 & B30316 joint exercises of affite radiological emergency preparedness plan for Arkansas Nuclear One Power Station KRIMIS R Federal Emergency Management Agency. 84/03/09 49pp 22640:003 24X Fichs. 50-313, 84/03/09, 8403150113
- 8403150200 Forwards draft final exercise rept for 840125 joint radiological emergency preparadness exercise, State of MI & Berriem County demonstrated capability to protect public in event of radiological emergency (KRIMM, R. W. Federal Emergency Management Agency (B4/03/09 JORDAN, E. L. Division of Emergency Preparadness & Engineering Response (Post 830103), 2pp 22642,001 24% Fiche 50-315,84/03/09,8403150200
- --8403150203 Draft evaluation of util, State of MI & Berrien County 840125 Joint exercise # Federal Emergency Management Agency. 84/02/22 42pp 22642:003. 24X Fiche. 50-315, 84/03/09, 8403150200
- 8403170131 Discusses findings & determinations on LTLCO transition plan. Key to Regional Assistance Committee (RAC) 840210 review & consolidated RAC review encl SPECK, S. W. Federal Emergency Management Agency OL-3, 84/03/15 DIRCKB, W. J. Office of the Executive Director for Operations 70pp 22668: 258, 24X Fiche 50-322,84/03/15,8403170131

- 8403190363 Forwards evaluation of LILCO transition plan per NUREG-0654/ FEMA-REP-1.Rev | Deficiencies noted SPECK.S W Federal Emergency Management Agency 84/03/15 DIRCKS,W J Office of the Executive Director for Operations 71pp 22673-081 24X Fiche 50-322,84/03/15,8403190363
- 8403200029 Forwards FEMA evaluation of Town of Lusby Calvert County, MD post-exercise radiological emergency preparedness plans for facilities Schedule for corrective actions re offsite emergency preparedness deficiencies requested MARTIN. T T Division of Engineering & Technical Programs 84/03/15 LUNDVALL. A E Baltimore Gas & Electric Co 3pp 22697-234 24X Fiche 50-317.84/03/15.8403200029
- --B403200035 Evaluation of Town of Lusby, Calvert County, MD post-exercise radiological emergency preparedness plans for facilities * Federal Emergency Management Agency B2/10/13 56pp 22697 237 24% Fiche 50-317,84/03/15.8403200029
- 840320007B Forwards final exercise rept prepared by FEMA for 830629 joint exercise of state & local radiological emergency preparedness plans MARTIN.TT Division of Engineering & Technical Programs 84/03/15 HARRINGTON.W D Boston Edison Co 3pp 22699 099 24X Fiche 50-293.84/03/15.8403200098
- 84032001&& Forwards FEMA 820&09 final post-exercise assessment for 82021B joint radiological emergency preparedness exercise Rept for 830921 exercise will be issued shortly MARTIN.T T. Division of Engineering & Technical Programs. 84/03/15 MURPHY.W P Vermont Yankee Nuclear Power Corp 3pp 22&98 041 24X Fiche 50-271.84/03/15.84032001&&
- 8403230079 Responds to approval request for info collection re 10CFR70 concerning domestic licensing of SNN Request approved through 870331 under OMB 3150-0009, per Paperwork Reduction Act
 MACRAE, J B Office of Management & Budget OMB 3150-0009 84/03/14 SCOTT, B Document Management Branch 2pp 22739.046
- 84032300B0 Responds to approval request for info collection re 10CFR32 concerning specific domestic licenses to mfg or transfer certain items containing byproduct matl Request approved through 870331 under OMB 3150-0001 MACRAE. J B Office of Management & Budget CMB 3150-0001 B4/03/15 SCOTT.8 Document Management Branch 2pp 22759 044
- 8403230120 Notifies that State of PA eligible for biennial frequency for participation in radiological emergency preparedness exercise Change from annual exercise requirement would be supported if requested by util XRIMR N Federal Emergency Management Agency 84/03/15 JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) ip. 22730-336 24X Fiche 50-387.84/03/15, 8403230120
- B403260037 Responds to approval request for info collection re 10CFR110 concerning export & import of nuclear equipment & mat1 Request approved through 861231 under OMB 3150-0036, per Paperwork Reduction Act MACRAE, J B Office of Management & Budget OMB 3150-0036 B4/03/14 SCOTT, S Document Management Branch 2pp. 22763 298
- 84032&0113 Forwards FEMA review of Rev 3 to util transition plan for affsite emergency preparedness.per NUREO-0.654
 MARTIN. J T Division of Engineering & Technical Programs 84/03/20
 POLLOCK.M S Long Island Lighting Co 3pp. 22758 001 24X
 Fiche 50-322,84/03/20,84032&0113
- --B403260117 Review of Rev 3 to util transition plan for offsite emergency preparedness, per NUREG-0654 * Federal Emergency Management Agency 84/02/10 66pp 22758 004 24% Ficher 50-322,84/03/20,8403260113
- B403270104 Requests extension until Oct 1984 for annual emergency preparedness exercise Extension would allow inclusion of offsite plans & use of proposed alternate emergency facility location DALTROFF.8 L Philadelphia Electric Co B4/03/20 EISENHUT.D G Division of Licensing opp 22769:217 24X Fiche 50-277,84/03/20,8403270104
- 8403270117 Forwards FEMA final rept for 831015-16 emergency exercise VERRELLI.D M Division of Project & Resident Programs 84/03/20 PARRIS.H 0 Tennessee Valley Authority 1p. 22607 027 24X Fiche 50-259,84/03/20,8403270117
- 8403290184 Forwards FEMA final rept for 830618 emergency exercise DANCE.H C Division of Project & Resident Programs 84/03/19 STEHART,W L Virginia Electric & Power Co ip 22802 174 24X Fichs.50-338.84/03/19.8403270184

8403300265 Forwards request for CMB review & supporting statement re NRC Form 313, "Application for Matl License." concerning 10CFR30, 33-35 & 40 NORRY.P & Bffice of Administration 84/03/28 MACRAE.J B Office of Management & Budget ip 22844 336

R PROPOSED RULE

- 8403070105 Comments on proposed rule 10CFR20 re accreditation of personnel dosimetry processors Requirement should provide degree of consistency & accuracy in personnel exposure dusimetry Supports rule MOBLEY.M H Tennessee, State of 49FR1205 025 84/02/16 CHILK:S J Office of the Secretary of the Commission 1p 22576 178
- 8403090106 Package of four comments supporting proposed rule 10CFR20 re improved personnel dosimetry processing WARD, J D California, State of JERRETT, L E Florida, State of VILLFORTH, J C Maryland, State of 49FR1205 84/03/05 CHILK, S J Office of the Secretary of the Commission 5pp 22576 069
- 8403090159 Comments on proposed rule 10CFR20 re accredited dosimeter processors Supports rule PARIS:R D Oregon, State of 49FR1205 028 84/02/24 Docketin & Services Branch Ip 22575 072
- 8403070176 Comments on proposed rules 10CFR2 & 72 re hybrid hearing procedures for expansion of onsite spent fuel storage capacity at civilian nuclear power reactors Recommends NRC establish stringent threshold for new contentions ZIMMERMAN, 8 R Carolina Power & Light Co 48FR54479 017 84/03/05 CHILM.S J Office of the Secretary of the Commission 2pp 2278, 310
- 8403090178 Forwards comments on proposed rule iCCFR20 re improving personnel dosimetry processing Personnel & area monitoring of exposures to ionizing radiation principal foundation for control of radiation RUMMERFIELD.P. Applied Radiation Protection Services. 49FR1205 035-84/03/02 PALLADING, N Commissioners ip 22573 312
- --8403090183 Comments on proposed rule 10CFR20 re improvement of personnel dosimetry processing Vendor among best providers of accurate readouts for persons exposed to low energy photons in diagnostic radiology.

 RUMMERFIELD,P Applied Radiation Protection Services 49FR1205-84/03/02 Docketing & Services Branch 6pp 22573-313
- 8402070199 Advises recipients of comments on proposed rule 10CFR2 that Comment 12 miscoded Number 12 will not be used again * Pocketing & Bervices Branch 48FR90550 84/02/23 Docketing & Services Branch. 1p 22573 115
- 8403090201 Comments on proposed rules 10CFR2 & 72 re hybrid hearing procedures for expansions of onsite spent fuel storage capacity at civilian nuclear power reactors Suggests procedures as alternative to Commission options RAHE.E P Westinghouse Electric Corp 4BFR54499 016 84/02/21 Docketing & Services Branch 4pp 22575 073
- 8403070208 Comments on proposed rule 10CFR20 re improving personnel dosimetry processing Extending accreditation to Feb 1984 questioned JACOBSON.N League Against Nuclear Dangers 49FR1205 026 84/02/25 Docketing & Services Branch 2pp 22574 356
- B403090212 Comments on proposed rule 10CFR20 re improved dosimetry processing Opposes rule. Rule allows no differentiation between performance testing requirements for large commercial processor & in-house programs MASSE, F X Massachusetts Institute of Technology, Cambridge, MA 49FR1205 027. 84/02/27 Docketing & Services Branch 2pp 22574 272
- B403090214 Package of two comments supporting proposed rule 10CFR20 re improving personnel dosimetry processing TAPERT, A C Delaware, State of EISENHOWER, E H Commerce, Dept of, National Bureau of Standards 49FR1205 84/03/06 Docketing & Services Branch 4pp 22575 085
- 8403130203 Comments on proposed rule 10CFR20 re improved personnel desimptry processing Opposes rule SQRENSEN.G C Washington Public Power Supply System 49FR1205 040 84/03/07 Doctating & Services Branch 2pp. 22617 317
- B403130R18 Comments on proposed rule 10CFR20 re improved dosinetry processing Opposes rule EVDOMINOPR, V N Boston Univ Medical Center, Boston, MA 49FR1205 037 84/03/05 Docksting & Services Branch 1p 22617:291

- 8403130236 Package of four comments supporting proposed rule 10CFR20 re improved personnel dosimetry processing RESH.D L Maryland. State of 'BRADLEY.F J. New York. State of BRICH.R South Dakota, State of 49FR1205 84/03/09 Docketing & Services Branch 5pp 22617 260
- 8403130282 Comments on proposed rules 10CFR2 & 72 re hybrid hearing procedures for expansions of onsite spent fuel storage capacity at civilian nuclear power reactors Supports Option 2.w/mod SHERHUDD, Q. General Electric Co 49FR54499 017, 84/03/02 Docketing & Services Branch 3pp 22614 188
- 8403130327 Package of three comments supporting proposed rule 10CFR20 re improved personnel dosimetry processing SKIERKOMSKI.P Oblahoma, Univ. of. Norman, OK THOMADBEN.B R. Wisconsin Clinic Cancer Center, Madison, WI GOLLNICK.D.A. Pacific Radiation Corp 49FR1205 84/03/08 Docketing & Services Branch Bpp 22617 122
- B40313036B Comments on proposed rule 10CFR20 re improved personnel dosimetry processing Supports rule KEARNEY.J J Edison Electric Institute, 49FR1205 043 84/03/06 CHILK.S J Office of the Secretary of the Commission 3pp. 22616 244
- 8403130378 Comments on proposed rule 100FR20 re licensee requirement to utilize only personnel monitoring svc certified by nat1 calibr svc Rule unnecessarily complicated & overly restrictive TANNER.R.L. Nurnberger Radiation Protection Service 49FR1205 044 84/02/06 Docketing & Services Branch 2pp 23616 274.
- 8403140137 Comments on proposed rule 10GFR20 re improved personnel dosimetry processing Add1 dosimetry processor accreditation guidance required before implementation of rule HITHERS, B D Portland General Electric Co 49FR1205 056 84/03/09. Docketing & Services Branch 2pp 22624 111
- 8403i40i44 Comments on proposed rule 10CFR20 re improved personnel dosimetry processing Requests, under FOIA, contract between NBB & Univ of Michigan re 8107i7 interagency agreement to administer dosimeter program SCHUTZ, D F Teledyne Isotopes. 49FR1205 053 84/03/09 Docketing & Services Branch 3pp 22623 360
- 8403140147 Comments on proposed rule 10CFR20 re improved personnel dosimetry processing Supports Alternatives 2 or 3.0ption A as acceptable approach for obtaining competent results from dose measurements CLEMENTS, B R Texas Utilities Electric Co (formerly Texas Utilities Generating Co) 49FR1205 035 84/03/07 Docketing & Services Branch ip 22620 332
- 8403140149 Comments on proposed rule 10GFR20 re improved personnel dosimetry processing Prefers Alternative 2 re use of dosimetry provider in GA program Alternative 3 B also acceptable although somewhat restrictive MILSON, E.F. Arkansas, State of. 49FR1205 050. 84/03/09, Docketing & Services Branch 1p 22620, 263
- 8403140151 Package of four comments supporting proposed rule 10CFR20 re improved personnel dosimetry processing FARRAR, D. L. Commonwealth Edison Co. WISENBURG, M. R. Houston Lighting & Power Co. PLATO, P. Michigan, Univ. of, Ann Arbor, MI. 47FR1205 84/03/12 Docketing & Services Branch 9pp 22624 026
- 8403140153 Package of two comments supporting Alternative 3, Option B in Netl Voluntary Lab Accreditation Program on proposed rule 10CFR20 re improved personnel dosimetry processing.

 BAYNE, J P Power Authority of the State of New York. SCHUYLER, J O Pacific Qas & Electric Co. 49FR1205 84/03/12 CHILK, S. J. Office of the Secretary of the Commission 4pp 22620:334.
- 8403140156 Forwards Frontier Airlines comments on proposed rule 10CFR20 re personnel dosimetry processing. Frontier Airlines does not fayor change in current requirements.

 BALLENGER, V. W. Air Transport Association 49FR1205 062, 84/03/08 Docketing & Services Branch 2pp. 22620:233.
- 8403140160 Comments on proposed rule 10CFR60 re high level radwastss in unsaturated zone Application of same std of measure to all rock types & all sites essential DOVER.B Affiliation Not Assigned 48FR5934 001 84/03/06. Office of the Secretary of the Commission. 1p 22620.362.
- 8403140166 Comments on proposed rule 10CFR20 re improved personnel dosimetry processing Dosimetry accreditation will impact on dosimetry research & upgrade BNM. "Quidelines for Calibr of Personnel Dosimeters" and for review. DEAL, L. J. Energy, Dept. of 49FR1205 047. 84/03/09 Docketing & Services Branch. 5pp 22624, 113.

- --8403140170 PNL-4515
 "Quidelines for Calibr of Personnel Dosimeters "
 ROBERSON.P L , HOLBROOK, K L Battelle Memorial Institute, Pacific
 Northwest Laboratories UC-41 84/01/31 45pp 22624 118
- B403140172 Package of four comments on proposed rule 10CFR20 re 903140172 Package of four comments on proposed rule 10CFR20 re improved dosimetry processing Opposes rule in present form BAKANAUSKAB.J Massachusetts. Univ of Hedical School DRIBCOLL,F Tufts Univ, School of Medicine, Medford, MA JOHNSON,R U Harvar Univ., Cambridge, MA 49FR1205 84/03/12. Docketing & Services Branch. Bpp 22620 244
- 8403170280 Comments on proposed rule 10CFR20 re improved personnel desimetry processing Subj should be addressed by reg guide CDUMSIL.W G Connecticut Yankse Atomic Power Co CDUMSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities), CDUMSIL.W O Northeast Utilities Service Co (subs of Northeast Utilities) Utilities A9FR1205 064 84/03/12 CHILK.S J Docketing & Services Branch, 2pp 22672 273
- 8403190289 Package of three comments supporting proposed rule 10CFR20 re improved parsonnel dominetry processing TUCKER: H B Duke Power Co WISENBURG, H R Houston Lighting & Power Co SUDBLOH, Q i Environmental Protection Agency 49FR1205 84/03/14 Docketing & Services Branch 11pp 22673 244
- 8403190295 Package of two comments opposing proposed rule 10CFR20 re HUSIVEYS Parkage of two comments opposing proposed rule 10CFR20 improved personnel dosimetry processing HCQAUGHY.R.W. Inwa Electric Light & Power Co. PRICE.K.W. Yale Univ., New Heven, CT. 49FR1205. 84/03/14 CHILK.S.J. Docketin Bervices Branch. App. 22675 312.
- B403190317 Package of four comments supporting Alternative 3, Option B of proposed rule 10CFR20 re improved personnel dosimetry of proposed rule lourney of improved processing.

 BZALAY, R. Atomic Industrial Forum DOLECEK, E. H., WYNVEEN, R. A.

 Argonne National Laboratory 49FR1205 84/03/16 Docketing

 Bervices Branch App 226/5 001 Docketing &
- B403190326 Comments on proposed rule 10CFR20 re improved personnel dosimetry processing Supports Alternative 3.Option B NBS logical administrative unit to establish stds for processing

 DELAND,F.H Vet Admin Hosp Lexington,KY 49FR1205 065

 84/02/24 CUNNINGHAM.R.E Division of Fuel Cycle & Material Safety

 ip. 22673:165
- 8403190369 Comments on proposed rule 10CFR20 re improved personnel dosimetry processing Recommends further consideration be given to other methods of certifying dosimetry processors MILLES.LM Tennessee Valley Authority 49FR1205 016 84/03/12 Docketing & Services Branch. 2pp 22675,307
- B403190387 Package of three comments supporting proposed rule 10CFR20 voluments supporting proposed rule local relations approved proposed rule local relations proposed rule local relations proposed rule local relations processing VAN BRUNT, E E Arizona Public Service Co THORPE, J. R. General Public Utilities - GPU Service Corp. EURE, J. A. Iowa, State of 49FR;205. 84/03/15 Docketing & Services Branch Spp. 22675, 309.
- 8403190405 Comments on proposed rule 10CFR20 re improved personnel dosimetry processing Supports rule.

 KENYON B D. Pannsylvania Power & Light Co. 49FR1205 063 84/00 CHILKs B J. Docketing & Services Branch 1p 22674 356
- 8403210004 Comments on proposed rule 10CFR20 re improved personnel dosimetry processing Supports Alternative G.Option B re NBS lab accreditation programs.
 BROWN, R. W. Malinckrodt. Inc. 49FR1205 0BD 84/03/14 Docket Bervices Branch 2pp 22706.334
- 8403210009 Package of three comments supporting proposed rule 10CFR20 re improved personnel dosimetry processing GIEBLER, C. W. Hisconsin Public Service Corp. DIXON, O. W. Southern California Edison Co. REED, J. D. Standard Oil Co. of Indiana (see also AMOCO). 49FR1205. 84/03/19 Docketing & Services Branch. 5pp. 22706:336
- B403210012 Comments on proposed rule iOCFR20 re improved personnel dosimetry processing. Recommends range of 50% plus or minus for dosimeters.
- ITON, D. W. American College of Radiology 49FR Docketing & Services Branch, 2pp, 22706-344. LINTON, D. W. 49FR1205 083 84/03/15.
- B40321001B Comments on proposed rule 10CFR60 re waste burial in saturated & unsaturated zones. Buggests containment be shaped like pyramid to withstand earthquakes, tornadoss & concussion from bomb blasts.

 NEMETHY.E Affiliation Not Assigned. 49FR5934 002. 84/03/14. Docketing & Services Branch. 1p. 22706-349.

- 84032:0022 Comments on proposed rule 10CFR110 re export/import of nuclear matl Questions why Soviet Union is not on list of embargoed or restricted destinations NEMETHY.E Affiliation Not Assigned 49FR7572 001 84/03/15 Docksting & Services Granch 1p 22705 086
- B403210029 Comments on proposed rule 10CFR50 re elimination of thermal annealing requirements of App 0. Section IV. B re preasurized thermal shock Supports rule Requirements not needed FAY. C W Misconsin Electric Power Co. 49FR4478 002 B4/03/15 CHILK.S J Office of the Secretary of the Commission 2pp
- 8403230058 Comments on proposed rule 10CFR20 re improved personnel dosimetry processing Supports Alternative 3.0ption B re utilization of NBS lab accreditation program THRON.R W Minnesota. State of 49FR1205 084 84/03/14 Docketing & Services Branch IP 22724 362
- 8403290002 Final response to FOIA request for four categories of documents:tests, studies & analyses referencing or pertaining to NURES-0103, "STS for I&W PHR" App A documents enci PELTON.J.M Division of Rules and Records 84/01/13 MADDEN.T J Kays, Scholer, Fierman, Hays & Handler App 22816 127. 24X Fiche 80-000, 84/01/13, 8403270002
- --BA09290034 Discusses Reg Quide 1 45, IBA draft Std 867 03 t AN91 draft Btd N 41 21 Suggested items clarifying reg guide listed MCGUEEN.N M. Affiliation Not Assigned 79/07/23 Atomic Energy Commission Directorate of Regulatory Standards 15pp
- 8403270242 Comments on proposed rule 10CFR20 re improved personnel dosimetry processing Seriously questions need for change Prefers current sys SDRENSEN,0 C Washington Public Power Supply System 49FR1205 087 84/03/07 Docketing & Services Branch 2pp. 22900,227
- 8403290252 Advises recipients of comments on proposed rule 10CFR20 that Comment 69 duplicate of Comment 60 Number 69 will not be used again * Docketing & Services Branch 49FR1205 84/03/26 Services Branch 1p 22800 064 Dacketina &
- 8403290255 Comments on proposed rules 10CFR2 & 72 re hybrid hearing procedures for expansions of onsite spent fuel storage capacity at civilian nuclear power reactors Prefers Option 2 W/mod. SHERMOOD, G G General Electric Co 49FR34499 018 84/03/02 Docketing & Sorvices Branch 3pp 22800 072
- 8403290863 Comments on proposed rule 10CFR20 re specifying residual radioactive contamination limits for decommissioning Adoption of 50 mrem per yr effective dose equivalent for limiting value acceptable TEDFORD.CF Arizona, State of 49FR1205 OBB 84/03/21 CHILK.S J Office of the Secretary of the Commission 1p 202000 OTB
- 8403270277 Comments on proposed rule 10CFR20 re improved personnel dosimetry processing. Concurs w/EEI comments to minimize unnecessary paper work & to provide suggested definition of dosimetry processor MITTLER L Public Service Electric & Gas Co of New Jersey 49FR1205 085 84/03/12 CHILK.J Office of the Secretary of the Commission 1p 22814 080 Commission
- B403270276 Comments on proposed rule 10CFR60 & NUREO-1046 re disposel of high level radwastes in unsaturated zone HILLIAMS.R E Williams & Associates NRC-02-82-046 49FR5934 003 84/03/15 PDHLE.J Division of Waste Management 2pp 22800 198
- B403290277 Comments on proposed rule 10CFR20 re improved personnel dosimetry processing Concurs w/actions to improve accuracy & reliability of dosimetry sys. Suggests NRC clarify intent of rule to licensee
 HUGHEG, T J Navy, Dept of 49FR1205 086 84/03/22 Docket:
 Services Branch 1p 22800 036 Docketing &
- 8403270321 Advises that encl 840309 ltr commenting on proposed rule 103290321 Advises that encl 840309 ltr commenting on proposed 105FR90 re improved dosimetry processing not comments by J Bakeneuskas Bignature forged Comments should be withdrawn from consideration Forged 1tr dtd 840307 encl. 840404 RAMANUSKAS, J Massachusetts, Univ of Medical School. 4584403/20. Docketing & Services Branch 2pp. 22602 065 49FR1205

PRM PETITION FOR RULEMAKING

- 8403010024 Responds to FOIA request for documents to potition for rulemaking PRM-50~50-31, from Citizens Task Force of Chapel Hill NC Forwards App A documents App B documents completely withheld (ref FOIA Exemption 5), FELTON, J M Division of Rules and Records 84/01/18 SHOLLY-8 C. Union of Concerned Scientists 4pp 22446 035
- --B301060420 Requests review & comments re encl draft FR notics to deny Citizens Task Force of Chapel Hill.NC pstition for rulemaking (PRM-50-31) W/a encl NORBERO. J. Human Factors & Safeguards Branch 82/12/27.
 BASSETT. D E Division of Accident Evaluation (Pre 840101) 2pp. 22446 041
- ~-840301003B Requests documents re patition for rulemaking PRM-50-31 filed by Citizens Task Force & R Servero 830916 memo to NRC div directors re draft rulemaking on emergency preparedness House of Rep . Interior & Insular Affairs 83/09/22 PALLADINO,N J Commissioners 1p 22446/040.
- 8403090075 Comments on petition for rulemaking PRM-20-14 re disposal of short-lived radionuclides No comments offered. BZYMCZAK.g. Firex Corp 49FR3467. 84/02/27 FELTON, J.M. Division of Rules and Records ip. 22575 293
- 8403090173 Commants on petition for rulemaking PRN-20-14 re disposal of very low level radwaste Supports rulemaking MARTIN.JB Affiliation Not Assigned 49FR3647 009. 84/02/28 CHILK.S J Office of the Secretary of the Commission 4pp. 22575 137
- 8403090180 Comments on petition for rulemaking PRM-20-14 re short-lived radionuclides Company does not use short-lived radionuclides JOHNSON'S M Sangamo Weston, Inc. 49FR3667, 84/02/16 FELTON'J M Division of Rules and Records 1p. 22574 272
- B403090184 Comments on petition for rulemaking PRM-20-14 re deregulation of radionuclides w/less than 100 days physical half-life Supports petition Waste would be toxic & should be burned CABTRONOVO,F Massachusetts General Hosp., Boston, MA 49FR366 007 B4/02/27 Docketing & Services Branch. 1p 22573:309
- B403090186 Comments on petition for rulemaking PRM-20-14 re disposal of short-lived low level radwaste Supports rule Change would resolve low level waste disposal problem since airborne radiation hazard will be negligible OUT, M. Worcester Foundation for Experimental Biology 49FR3667 008 84703701 Dacketing & Services Branch 1p. 22573:275
- 8403130249 Comments on petition for rulemaking PRM-20-14 re disposal of very low concentrations of short-lived radioactive mat1 Supports amend proposed by Univ of Utah WIEN.80 Wien Laboratories. Inc. 49FR3647 010 83/03/05 Docketing & Services Branch 2pp 22617:255
- 8403140189 Comments on petition for rulemaking PRM-20-14 re disposal of very low concentrations of short-lived radioactive matl. Emphasis should be placed on disposal of truly hazardous chemical waste HADE.L Texas, Univ of Austin, TX 49FR3667 011 84/03/09 Docketing & Services Branch. 19 22620 215.
- 8403140821 Comments on petition for rulemaking FRM-20-14 re proposed extension of scintillation vial exemption to include short-lived isotopes Supports proposed rule GLAS9.D J Biotechnica International Inc 49FR3667 OIR 84/03/09 Docketing & Services Branch. 3pp. 82631,052
- 8403170362 Comments on patition for rulemaking PRM-20-14 re disposal of short-lived radionuclides. Supports rulemaking JOHNSON.R U Harvard Univ , Cambridge , MA. 49FR3667 013 84/03/05 Docketing & Services Branch 2pp 22675 235.
- 8403210107 Package of four comments supporting petition for rulemaking PRM-20-14 re disposal of very low level concentrations of short-lived radionuclides.

 MILES,H L. Army, Dept of LIETO,R.P. Henry Ford Hosp. Detroit, MILANCIONE, 9 Millipore Corp. 49FR3667. 84/03/19 Docketing & Services Branch. 5pp 22706:135
- 8403230069 Comments on patition for rulemaking PRM-20-14 submitted by Univ of Utah re current restrictions on waste disposal. Supports rulemaking MADE: L Health Physics Society 49FR3667 018, 84/03/09. Docketing & Services Branch Ip 22726 327.

- 8403290238 Package of two comments on patition for rulemaking PRM-20-14 re disposal of short-lived radionuclides by burial DURKDSH:E D Pittsburgh, Univ of. Pittsburgh: PA GRUNEWALD.R. Hisconsin, Univ. of. Miwaukee. H. 49FR3667 84/03/26 Docksting & Services Branch 10pp 22800:176
- B403290253 Comments on petition for rulemaking PRM-35-5 re restricting use of bone mineral analyzer to qualified & trained physician. Suggests increase in min number of hours from 8 to 16 Supports petition
 KRISHMANURTHY Vet Admin. Hosp. Portland.OR 49FR8621. 84/03/20, Office of the Secretary of the Commission 1p 22800.175.
- 8403290257 Package of thrse comments opposing patition for rulemaking PRM-35-5 submitted by Nuclear Radiation Consultants on use of 04-153 bone mineral analyzer.

 SILEBRAFIEIN, E. Cincinnati, Univ of, Hosp., Cincinnati, UH LLAURADD, J. Ø Vet. Admin Hosp Lome Linda, CA ZIELONKA, J. 8 Vaterans Admin Medical Center, Wood, WI 49FR6821 84/03/26 CHIKKS. J. Office of the Secretary of the Commission. Spp. 22800.005
- 8403290272 Comments on patition for rulemaking PRM-20-14 re burial of certain radioactive matl in hazardous waste landfills.
 Opposes rulemaking SALZMANL Friends of the Earth, 49FR3667 025. 84/03/19.
 Docksting & Sarvices Branch ip 22814'078.
- 8403290301 Package of two comments on petition for rulemaking PRN-20-14 re disposal of short-lived radionuclides. KANELH S Brandels Univ Maithem, MA DDERGES.J.E. Wyoming, Univ of, Larmie, MY 49883667, 84/03/23 Docksting & Services Branch 5pp. 22800:043.
- 84032703il Package of two comments on patition for rulemaking PRM-20-14 re disposal of short-lived radionuclides. Supports patition, w/rev, '
 HOLLEMAN, D Alaska, Univ of, Fairbanks, TUTTLE, H. K. Vet. Admin Hosp. Portland, OR. 49FR3667. 84/03/23 Office of the Secretary of the Commission Spp. 22802.096

PROJ PROJECTS - PREDOCKET LICENSING

- 8403010123 Responds to FDIA request for studies performed by USGS & State of CA Div of Himes & Geology re facility seismic design. Forwards App A documents Info also available in PDR, FELTON, J. M Division of Rules and Records. 83/12/20 CALSOYAS, C. D Affiliation Not Assigned 3pp 22444, 349, 24X Fiche, 50-312, 83/12/20, 8403010123
- ---79:1120370 Requests add1 info to complete review of initial site examination info data form
 DEYOUNG:R C Atomic Energy Commission, Directorate of Licensing-74/12/13 PAVIS.E.K Secramento Municipal Utility District. 2pp
 22445 028 24X Fiche 50-312.83/12/20.8403010123.
- --7911120403 Requests initial site examination info. GIAMBUSBO.A Atomic Energy Commission, Directorate of Licensing 74/08/14. DAVIS.E K Secremento Municipal Utility District Spp. 22445 024
- --7911120413 Responds to 760115 ltr re DL Kelleker 751217 concern about nuclear plant in Orville, CA vicinity, No plant planned for area Discusses DBE re plant design DIRCKS, W J. NRC No Detailed Affiliation Given. 76/02/06 CRANSTON, A Benate 3pp. 22445, 041. 24X Fiche, 50-312, 63/12/20, 8403010123
- ---B403010150 Forwards evaluation of Unit 2 initial site exam info data review Site safety members participating in review listed, DENTON-H.R. Atomic Energy Commission, Directorate of Licensing 74/10/10 DEYOUNG.R.C. Atomic Energy Commission, Directorate of Licensing 4pp 22445:046 24X Fiche:50-312,83/12/20,8403010123

PT21 NONCOMPLIANCE REPORTS AND RELATED CORRESPONDENCE

- 8402090020 Board Notification 84-044: forwards Part 21 rept re Transamerica Delaval. Inc turbocharger thrust bearing Jubrication defect resulting in engine nonavailability. EISENHUY.D. 9 Division of Licensing. 84/02/29. PALLADINO Commissioners. 4pp 22541.263 24% Fiche: 50-000.84/02/29. 8402090020.
- 8402270274 Third interim deficiency rept, Item 111 re seismic qualification test failure of Transamerica Delaval, Inc starting air check for emergency dissel engine generator sets Also reportable per Part 21, Next rept by 840025 PARSONS; R M. Carolina Power & Light Co NRC-181 84/02/15 0'RECLLY,J P. Region 2. Office of Director. 4pp 22391: 304 24X Fiche: 50-400, 84/02/15, 8402270274.

- B402290274 Interim deficiency rept re loose flexible coupling drive hubs on components supplied by Transamerica Delaval, Inc Initially reported on 840120 Next rept by 840531 Also reported per Part 21 EDELMAN, H R Cleveland Electric Illuminating Co 84/02/17 KEPPLER, J G Region 3, Office of Director 2pp 22426 299 24X Fiche: 50-440, 84/02/17, 8402290274
- 8403010350 Interim deficiency rept. Item 158 re Pullman Const Industries/Ebasco design interface HVAC ductwork. Differences impacting seismic qualification may exist between design & fabrication documents Also reportable per Part 21 PARSONS, R M Carolins Power & Light Co 158 84/02/17 0'REILLY, J P. Region 2. Office of Director 1p 22432-328. 24X Fiche. 50-400, 84/02/17, 8403010350
- 8403010374 Deficiency & Part 21 repts, Item 157 re Ruskin Mfg Co supplied actuators failing to meet functional test requirements of GH Bettis Co. Initially reported on 831221 Next rept will be submitted by 840323 PARSONS.R M. Carolins Power & Light Co. NRC-182 84/02/17. 07REILLY.J P. Region 2. Office of Director 1p 22434 046 24X Fiche. 50-400, 84/02/17, 8403010394
- B403050120 Responds to NRC B40126 ltr re deviation noted in QA Program Insp Rept 99900330/83-02. Corrective actions specified max value reevaluated. Exceeding value did not adversely affect performance of UVTD Condition not reportable per Part 21, BAUTER, D M Westinghouse Electric Corp 84/02/23 PGTAPDVS, U Vendor Program Branch. 2pp. 22488 030
- 8403050170 Part 21 rept re potential degradation of actuator stroking times re slapsed time from original mfg Caused by ethylene propolene seal absorbing hydrocarbons from grease UPTONR T GH-Bettis CO 84/02/20 SEYFRIT, C Region 4, Office of Director 18pp 22485:210
- B403060311 Part 21 final design rept re inadequacy of svc water & circulating water pump house structure Analysis completed Repair const activities in progress.
 KREIDER:H.O. United Engineers & Constructors, Inc (subs. of Raytheon Co.). B4/02/28, Director's Office: Office of Inspection and Enforcement. 3pp 22515 335 24X Fiche 50-443.84/02/28, E403060311
- B403070256 Followup Part 21 rept re defective mechanical anubber capstan springs supplied by Pacific Scientific Affected utils listed. Purchasers have been notified & advised to work directly w/Pacific Scientific in disposition.
 HOVI.L. NPB Industries, Inc. NPSI-01-3825, 84/02/24 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 2pp 22536:279 24X Fiche 50-000,84/02/24,8403070256
- B403070285 Fifth interim deficiency & Part 21 repts Item 117 re usiding defects on Class IE 6 9 kV circuit breakers Initially reported on B3021i. All Class IE breakers at site returned to Biemens-Allis Final rept expected by B40331. PARSONS, R M. Carolina Power & Light Co NRC-188. 84/02/29 0'REILLY, J P. Region D. Office of Director 4pp. 22547.075 24X Fiche: 50-400, 84/02/29, 8403070285
- B403070286 Final deficiency rept re Parsons-Peebles emergency diesel generator 28-8 rear bearing problem Initially reported on 830627 Generator, repaired to be used as spare Also reported per Part 21 MILLS.L.M. Tennessee Valley Authority 84/02/29. O'REILLY, J P Region 2, Office of Director 4pp 22546 224. 24X Fishe: 50-390, 84/02/29, 8403070286
- 8403070290 Fourth interim deficiency rept. Item 77 re seismic Class I cable tray, conduit & HVAC hangers supplied by Peden Steel Intitially reported on B20802, Component reinsp in progress, Next rept by 840701. Also reported per Pert 21 PARSONS, R M Carolina Power & Light Co 77 84/02/24 Great Conduction of Director. 4pp. 22547 067 24X Fiche: 50-400, 84/02/24, 8403070290
- B403070297 First interim deficiency rept re numerous deficiencies on E-max panels Initially reported on B40131. Incorrect connected wires will be repaired. Next rept by 840607 Also reportable per Part 21 MILLS. L.M. Tennesse Valley Authority. 84/02/29. G'REILLY, J.P. Region 2, Office of Director. 2pp. 22546-357. 24X Fiche: 50-438. 84/02/29. 8403070297
- 8403070329 First interim deficiency rept re adaptor keyway on 8-inch Borg-Harner globe velves, Initially reported on 840131, Vendor will provide corrective section & identify addl valves requiring mods, Also reportable per Part 21.

 MILLS, L.M. Tennesses Velley Authority. NCR 2787 84/02/29, 0'AEILLY, J.P. Region 2: 0ffice of Director. 2pp. 22546, 313 24X Fiche: 50-438, 84/02/29, 8403070329

- B4030B0240 Part 21 rept re failure of Pacific Air Products linear converter Initially reported on B40117 Failure due to excessive wear of brass shaft guides on input & output shafts Investigation underway HALL, D P Illinois Power Co U-10132 B4/02/29 KEPPLER, J Q Region 3. Office of Director 2pp 22554 289 24X Fiche 50-441,84/02/29,8403080240
- 8403090082 Fourth interim & Part 21 repts, Item 101 re defective governor drive coupling supplied by Transamerica Delaval Initially reported on 820909 Couplings to be replaced final rept by 840525
 PARSONS, R M Carolina Power & Light Co NRC-185 84/02/24
 O'REILLY, J P Region 2. Office of Director 4pp 22575 299 24X
 Fiche 50-400,84/02/24,8403090082
- 8403090181 Twelfth interim deficiency rept re main steam line feilure due to main feedwater overfill Initially reported on 800319 Field change package submitted by B&W Next rept by 840822 Also reportable per Part 21.

 MILLSL M Tennesses Valley Authority 84/02/27 O'REILLY, J P Region 2. Office of Director. Spp 22573 272 24X Fiche 50-438,84/02/27,8403090181
- B40309019B Forwards two ltrs referenced in B30916 ltr.representing entire dialogue w/NRC re GC breakdown All future correspondence will be forwarded to IE & will be routed through author ofc KALE.D L. Quif & Western Industries. Inc B4/01/17 ANDERSON,W F Director's Office. Office of Inspection and Enforcement ip 22574 273.
- ---B403070200 Potential Part 21 rept reviewing documentation re all nuclear component shipments Based on review, quality problem nonexistent & Part 21 inapplicable KALE.D L. Gulf & Western Industries, Inc. B3/09/16 O'REI
- --8403070202 Advises of potential quality program breakdown re metallic pipe fittings Thorough internal investigation underway KALE,D L Quif & Western Industries, Inc. 83/03/1i O'REILLY,J P Region 2, Office of Director 1p 22574 277
- --B403090203 Submits followup rept to 830311 initial notification of potential quality program breakdown Areas of concern include traceability of matl through mfg mill test repts & heat treatment of matl
 KALE,D L Quif & Western Industries, Inc. 83/04/11
 O'REILLY,J P Region 2, Office of Director 12pp 22574 278
- 8403090265 Final Deficienty Rept PRD 83/08 re inability to maintain pressurized water supply to RHR pumps & discharge piping supplied by Bechtel. Initially reported on 830415, Hardware mods implemented Also reportable per Part 21 MCGAUGHY, J. P. Mississippi Pawer & Light Co. PRD 83/08 84/03/02 07/REILLY, J. P. Region 2. Office of Director. 4pp. 22572,144 24X Fichs 50-416,84/03/02,8403090265
- B403120032 Final Deficienty Rept DER 83-70 re wiring in emergency response facility cabinets supplied by Energy, Inc not in conformance w/IEEE-384 criteria Initially reported on 83101) Drawings resubmitted Also reported per Part 21 VAN BRUNT.E E Arizona Public Service Co DER 63-70 84/02/28 818HDP.T W Division of Resident, Reactor Project & Engineering Programs 4pp 22588 025. 24X Fiche 50-528 84/02/28 8403120032
- B403120105 First interim deficiency rept re loose drive hubs on overspeed governor drive shaft on Transamerica Delaval. Inc diesels Initially reported on B40203 Svc info memo being reviewed for approval Also reportable per Part 21.

 MILLSIL M. Tennessee Valley Authority B4/03/01 O'REILLY, J P Region 2, Office of Director 2pp. 22585, 229 24X

 Fichs. 50-000, B4/03/01, B403120105
- 8403120136 Part 21 rept re Westinghouse Type SA-1 DSR or DSRV standby diesel generator differential relay defect Relay problem reported in 840213 Buppl 1 to IE Info Notice 83-63 RTE Delta requested to review defect & recommend correction.

 BOYER: R E Transamerica Delaval, Inc. IEIN-83-63 84/03/07 Director's Office, Office of Inspection and Enforcement 2pp 22985:219 24X Fiche 50-416.84/03/07.8403120136
- B403120163 First interim deficiency mept resetting of shutdown voltage for vital inverters by Intl Power Machines Initially reported on B40209. Corrective action requested from vendor Next mept by B40592. Also reported per Part 21 MILLSIL M Tennessee Valley Authority B4703/01 O'REILLY, J P Region 2, Opfice of Director 2pp 20589 207. 24X Fiche 50-438,84/03/01.8403120163

- 8403130237 Interim deficiency & Part 21 repts, Item 139 re flexible coupling drive shaft in overspeed powernor & fuel transfer pump drive of standby diesel generator Initially reported on 840206 Final rept will be submitted by 840416 PARSONS, RM Carolina Power & Light Co NRC-190 84/03/02 07REILLY, JP Region 2, Office of Director 1p 22617 277 24 Fiche 50-400,84/03/02,8403130237 24 X
- B4031303B7 Part 21 rept re stop tab breakage in SBM type control switches Replacement fromt plates will be furnished to Affected customers

 MANKOFF, L. General Electric Co 84/03/02 DEVOUNG, R

 Office, Office of Inspection and Enforcement 3pp 2261

NG.R Director's 22613 323

- 8403130378 Fifth interim deficiency rept. Item 53 re potential for Mestinghouse mfg gate valves failing to fully close/open under design conditions Also reportable per Part 21 Hardware changes completed Final rept expected by 840415 PARSONS.R M Carolina Power & Light Co NRC-187 84/03/01 0'REILLY.J P Region 2. Office of Director. 10pp 22616 283 Fiche 50-400.84/03/01.8403130378 24 X
- 8403140122 Part 21 rept re status update concerning abnormal wear on linear converters Test program underway Results of investigation indicate excessive wear caused by hunting of control circuitry
 DDDSON.J.P. Pacific Air Products Co. 84/03/09. 9. Director's 7pp 22624 066 Office, Office of Inspection and Enforcement Fiche 50-000,84/03/09,8403140122
- 8403140138 Part 21 rept re matls shipped from Carlinville plant lacking chemical overcheck requirement Affected items listed Ltrs sent to affected vendors encl KALE.D L. Gulf & Western Industries, Inc. PY21-84-133-000 84/02/17 DEYOUNG.R Director's Office, Office of Inspection and Enforcement 33pp 22520 298
- 8403140042 First interim deficiency rept re ITT Grinnel pipe supports designed w/sway struts instead of required gaps. Initially reported on 84010B Alternate analysis load tables will be revised Also reportable per Part 21 Next rept by 840828 MICLS,L M Tennessee Valley Authority 84/03/06 0'REILLY, J P Region 2, Office of Director 2pp 22655 126 24X Fiche 50-438,84/03/06,8403140042
- B403190036 Interim deficiency & Part 21 repts re status on open items KOESTER.G L Kansas Gas & Electric Co KMLNRC 84-025 84/03/05 GAGLIARDO, J E Region 4. Office of Director 18pp 22666 215 2 Fiche 50-482,84/03/05,8403190036
- 8403190051 Interim deficiency rept re failure of linear converters on multi-blade dampers supplied by Pacific Air Products, Co utilized in safety-related HVAC sys Initially reported on 840216 final rept by 840710 Also reported per Part 21 EDELMAN, M R Cleveland Electric Illuminating Co RDC 94(84) 84/03/09 KEPPLEN, J O Region 3, Office of Director 2pp 22666 186 24% Fiche 50-440,84/03/09,8403190051
- 8403170101 Part 21 rept re apparent design deficiency in Siemens Allis Nodel Ma-2058 stored energy circuit breaker Greaker insp & hold down device orientation will be complete by 840401 Determination of permanent fix & implementation by 840501 JUHNSON, B D , VANDEWALLE, D J Consumers Power Co 84/02/29 KEPPLER, J G Region 3, Office of Director 5pp 22669 305 24X Fiche 50-255,84/02/29,8403190101
- B403190248 Supplemental Part 21 rept re failed engine thrust bearing Flugs properly installed in both units Units free of potential defect MDRIARTY, JM Colt Industries, Inc. 84/03/08 KEPPLER, J. G. Regi 3, Défice of Director ip. 22675-045 24X Fiche. 30-006, 84/03/08. 3, Office of Director 8403190248
- B403190287 Third interim Deficiency Rept NCR 2393 re Bingham-Willamette makeup/HPI pump vibration Initially reported on 830622 Next rept expected by 840723 Item also reportable under Part 21 MILLS,L N Tennessee Velley Authority NCR 2393 B4/03/12 O'REILLY,J P Region 2, Office of Director. 3pp 22472 275 24X Fiche 50-438,84/03/12,8403190287
- 8403190329 Forwards Vendor Program Insp Repts 99900231/83-01 & 99900231/84-01 on 831115-17 & 840114-20, respectively, closing out Part 21 rept re seepage of oil from Okonite cables POTAPOUS.U PDTAPOUS.U Region 4. Office of Director B4/03/15 ND Division of Project & Resident Programs ip 22675 026 Fiche 50-461.84/03/15.8403190329 NORELIUS: C E

- 8403190374 Part 21 rept re failed engine thrust bearing Initially reported on 800502 Field insp of Colt-Pielstick Type PC-2 diesel generator sets completed using revised drawings Unit in compliance w/insp procedure & free of potential defect MORIARTY.J M Colt Industries, Inc 84/03/08 KEPPLER.J Q Regi 3, Defice of Director 1p 22674 353 24X Fiche 50-443,84/03/08.8403190374
- 8403200203 Interim deficiency rept. Item 101 & Part 21 rept re defective governor drive coupling Correct ltr date is 840224, not 830224 E40224.not 830224
 PARSONS.R M Carolina Power & Light Co NRC-192 84/03/09
 D'REILLY.J F Region 2, Office of Director 1p 22699 347
 Fiche: 50-400.84/03/09.8403200203
- 8403210032 Part 21 rept re failure of auxiliary feedwater pump drive turbines. Oimpel NPB-4 T&T valve, to close Encl 1tr dtd 840203 sent to listed utils OE notified of affected units in BWR Plants
 THEROUX,R R Terry Corp PT21 84-140-000 B4/02/22 W
 Director's Office, Office of Inspection and Enforcement
 R2706 S27 24X Fiche 50-000,84/02/22,8403210032 WOODRUFF, R W
- 840321004i Final deficiency rept re incorrect operation of Div I & II diesel generator load shedding sequencing sys panels Initially reported on B3092i Circuit cards & card recks returned for mad Reinstellation expected by 840427 MCGAUCHY. J P Mississippi Power & Light Co AECM-84/0148 84/03/15 0'REILLY. J.P. Region 2. Office of Director 5pp 22707 032 24X Fiche 50-417,84/03/15,8403210041
- 8403210046 First interim deficiency rept re ITT Orinnel pipe supports designed w/sway struts instead of required caps. Initially reported on 840216 Next rept by 850213 Also reportable per MILLS.L M Tennessee Valley Authority 84/03/13 Region 3, Office of Director 2pp. 22704 328 24% Fiche. 50-438, 84/03/13, 8403210046
- B403210075 Part 21 rept re nonconformance of metal hose assemblies for ABME. Section III. Class 2 & 3 svc. Status of nonconforming items shipped entl AlI customers notified LALIKOS. J M Titeflex Corp PT21 B3-141-000. B3/12/16. Director's Office. Office of Inspection and Enforcement 4pp 22704 324 24% Fiche 50-000.83/12/16.8403210095
- 8403210125 Final deficiency rept re cavitation of jet pumps due to induction heating stress improvement cooling, Initially reported on 831206 No erostion found Also reportable per Part 21 Item not reportable per 10CFR50 55(s) CURTIS.N W Pennsylvania Power & Light Co. PLA-2103 84/03/06 MURLEY, T E Region 1, Office of Director 4pp. 22707,228 24; Fiche: 50-388,84/03/06,8403210125
- 8403210136 Interim deficiency rept re Anchor Darling HPCS sys valve vibration loosening anti-rotational set screws. Initially reported on 840127 & reported by GE per Part 21 Investigation in progress. Final rept by 840723 MANGAN, C V Niagara Mohawk Power Corp 8113 84/02/27 STAROSTECKI, R. Division of Project & Resident Programs. 2pp 22707 272 24x Fiche 50-410,84/02/27,8403210136
- B403210145 Final deficiency & Part 21 repts re safety parameter display sys Technology Energy Corp Model 155 isolators Initially reported on 840106. Non-IE power supply will be provided for isolator prior to end of first refueling CURTIS.N W Pennsylvania Power & Light Co. PLA-2089 84/02/27 MURLEY.T E Region 1. 0 Pfices of Director 4pp. 22707'281. 24X Fichs 50-388.84/02/27.8403210145.
- 8403210192 Final deficiency rept re anti-rotational setscrews in Anchor Darling glove valves. Initially reported on 840213, Setscrew tightened & stem collar threads staked using ctr punch. Also reported per Part 21 for Unit 1.

 MCGAUGHY, J P. Mississippi Power & Light Co AECH-84/0159
 84/03/14 D'REILLY, J P. Region 2, Office of Director, 5pp
 22707 257 26% Fichs: 50-416, 84/03/14,8803210152
- B403230019 Final Deficiency Rept DER 82-46 re ITT Barton pressure transmitters supplied by C-E not meeting overpressure requirements Caused by leakage of metallic washers & methodology error during calibr Also reported per Part 21, VAN BRUNT.E E Arizona Public Service Co. DER 82-46. 84/03/15. BISHOP, T W Division of Resident. Reactor Project & Engineering Programs 7pp 22724 353 24% Fiche. 50-528, 84/03/15, 8403230019
- 8403230028 Followup Part 21 rept re nuclear valve/actuator stroking time possibly lengthaned beyond 15 s when using hydrocarbon-based lubricants Ltrs to affected utils and HILBONA K Henry Pract Co CAR 0023 84/03/08 KEPPLER, J. G Region 3, Office of Director App. 28730:306. 24X Fichs: 50-000, 84/03/08, 8403230028.

ı

DOCKETED ITEMS

- 8403230056 Part 21 rept re Westinghouse mechanically interlocked full voltage reversing starters not maintaining required relative positions. Caused by assemblers incorrectly removing backing plates.
 RODRIGUEZ, R. J. Sacramento Municipal Utility District RJR 84-054 84/02/15. MARTIN, J. B. Region 5, Dffice of Director 5pp 22726.045 24x Fiche 30-312,84/02/15,8403230056
- B403230095 Second interim deficiency rept re improper relief valve setting, design pressures & design temp within several sys Initially reported on B31118 Spec M-199 revised & code data repts amended, Also reported per Part 21 CORTIS,N.W. Pannsylvania Power & Light Co. PLA-2075 B4/03/02 MURIEV,T E Region 1, Office of Director 14pp 22726 277 24X Fiche 50-388,84/03/02,8403230095
- B403230108 Part 21 rept re design deficiency in field-run cables to Valcor solemnid valves Initially reported on 840319 Approx 50 valves affected at each facility Mgt corrective action repts issued MEYERB, B. L. Bechtel Corp. 84/03/19 DEYOUNG, R. Director's Office, Office of Inspection and Enforcement. 2pp 22730 234 24% Fiche; 50-000, 84/03/19, 8403230108.
- 8403230113 Rev i to final Deficiency Rept 82-50 re possible damaged flexible conduit couplings between auxiliary & control bldgs in event of seismic events exceeding 3/4 inch movement. Rev changes final rept disposition to reportable under 10CFR21. VAN BRUNTLE E Arizona Public Service Co. DER 82-50 84/03/09 BIBHOP.T.W Division of Residents Reactor Project & Engineering Programs. 4pp. 22730:215. 24X Fiche 50-528.84/03/09.8403230113
- 8403230115 Final Deficiency & Part 21 Rept U-62 re failure of stator winding on NEO28 emergency diesel generator mfg by Beloit Fower Bys Initially reported on 830812 Stator replaced. Emergency generator installed & load tested BCHNELL, D. F. Union Electric Co ULNRC-766 84/03/15 KEPPLER, J. 9 Region 3, Office of Director 4pp. 22730, 211. 24X Ficher 50-483, 84/03/15, 8403230115
- B403260233 Forwards summary list of deficiencies identified per 10CFR50, 55(e), Part 21 & potential generic ltr repts for comments
 BTARDSTECKIR Division of Project & Resident Programs. 84/02/28
 Region 1, Office of Director 7 pp. 22756.065. 24X
 Fiche 50-000.84/02/28.8403260233
- 8403270039 Interim significant const deficiency rept. Item 100 reterminations to Knox fuse blocks, 9E 4, 160 kV switchgear All Knox fuse block terminations reinspected Next rept will be submitted by 840406 Also reported per Part 21 GERRETS, T.F. Louisians Power & Light Co. 100. 84/03/12. COLLINS, J.T. Region 4, Office of Director. 3pp 22766 159, 24% Ficher 50-382, 84/03/12, 8403270059
- 8403270182 Final Deficiency & Part 21 Rept U-64 re Limitorque valve actuators BN-HV-8812A & B Initially reported on 831017 Valve failure due to improper installation of motor pinion gear. All 88-2-80 actuators verified for proper gear installation BCHMELL, D. F. Union Electric Co. ULNRC-749, 84/03/20, KEPPLER, J Q Region 3, Dffice of Director 4pp 22771; 331. 24% Fichs: 50-483,84/03/20,8403270182
- 8403270219 Part 21 rept re broken contect carrier in control device of 7.5 kV-15 kV.500-750 MVA,5 kV 350-3,000 & all HKV circuit breakers. Initially reported on 830223 Addenda to installation & maint procedures sent to affected units DUVALL.D.D. Brown Boveri Corp. (subs. of Brown Boveri & Co , Ltd). 84/03/19. Record Services Branch (Document Control Desk) 5pp 22772:114. 24X Fiche 50-000.84/03/19.8403270219
- 8403300020 Rev i to final Daficiancy Rept DER 82-46 re ITT-Barton pressure transmitters supplied by C-E failing to meet overpressure requirements. Initially reported on 820824. Also reported per Part 21 VAN SRUNT, E. E. Arizona Public Service Co. ANPP-29099-BBK/. 84/03/19. BISHOP, T.M. Division of Resident. Reactor Project & Engineering Programs. 7pp, 22822 171. 24X Fiche 50-528,84/03/19,84/230020
- 8403300034 Interim deficiency rept. Item 157 re GH Bettis operators on Ruskin-supplied HVAC dampers failing to meet functional test requirements. Initially reported on SG1221. Required info unavailable. Nax rept by 840321. Also reported per Part 21. PARSONS, R.M. Capolina Power & Light Co. NRC-158 84/03/23. 0'461Lty.J.P. Region 2. Office of Director ip. 22821:311, 24X Fichs: 50-400, 84/03/23, 8403300034.
- 8403300043 Third interim deficiency rept, Item 95 re shop welding defects in Beismic I pipe hangers supplied by Bergen-Patterson & Item 72 re undersized skewed toe fillet weld on hangers. Final rept by 841201 Also reported per Part 21 PARBONS, R. M. Carolina Power & Light Co NRC-195, 84/03/21, 0/REILLY, J.P. Region 2, Office of Director. Spp 22819 315 24X Fiche: 50-400, 84/03/21, 8403300043

- 8403300054 Fifth interim deficiency rept re defects in raw cooling water chiller unit flow control valves mfg by Metrex Valve Corp Initially reported on 821126 Investigation in progress Next rept by 850421 Also reportable per Part 21 MILLS.L M Tennesses Valley Authority 84/03/22 O'REILLY.J P Region 2. Office of Director 2pp 22821 264 24X Fiche 50-438,64/03/22,8403300054
- B403300079 Suppl to Gould B30926 Part 21 rept re potential defects in mplded case for 100 ampere frame.multi-pole E & HE series circuit breakers, clarifying part distribution & affiliation arrangement BRADLEY, R D Siemans-Allis, Inc 83/11/17 MURLEY, T E Region 1. Office of Director 1p 22821.360.
- 840330010? First interim deficienty rept re new defects in Barton pressure transmitters supplied by Westinghouse Institution reported on 840223 Westinghouse will define corrective action by 840331 Also reportable under Part 21 MILBAL M Tennessee Valley Authority 84/03/22 O'REILLY, J P Region 2. Office of Director 2pp 22821 223 24X Fiche 50-390.84/03/22.6403300109

QA999 GUALITY ASSURANCE INSPECTIONS

- B40201017B Ack receipt of B31223 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900743/83-01 PGTAPOVB, U Region 4, Office of Director 84/01/25 BUVALL, D Brown Boveri Corp (subs. of Brown Boveri & Co , Ltd) ip 22038:335
- ---8402010185 Responds to NRC 831202 ltr re nonconformance noted in GA Program Insp Rept 97900743/83-01 Corrective actions Engineering Drawing 605143 revised w/appropriate dates & signatures

 DUVALL, D. D. Brown Boveri Corp. (subs of Brown Boveri & Co., Ltd.) 83/12/23 POTAPOVS, U. Region 4. Office of Director ip 22038 336
- 8402150211 Forwards GA Program Insp Rept 99900519/83-03 on 831031-1104 Implementation of GA program failed to meet certain NRC requirements, POTAPOVB.U Region 4. Office of Director 83/12/28 KOMEB.J M Bechtel Corp 2pp 22244 121
- ---8402150216 Notice of nonconformance from insp on 831031-1104 * Region 4. Office of Director 83/12/28 lp 22244 123
- --B402150226 GA Program Insp Rept 99900519/83-03 on B31031-1104 Noncompliance noted sight pipe whip restraints requested by mechancial group to civil group, specified in FBAR but not installed. CGBTCLLOJ R , MADSEN, G L Region 4, Office of Director B3/12/23. 12pp 22044 124
- B403010075 Responds to NRC B40126 ltr re nonconformance noted in GA Program Insp Rept 99900255/83-01 Corrective actions suppliers of code exempt items will be evaluated on basis of quality sys questionmairs & performance review THOMSEN,E R Pacifit Scientifit 6000-QB-52-94, B4/02/14 POTAPDVB.U. Region 4, Office of Director 13pp. 22436 098
- 8403010079 Responds to 840123 ltr informing of nonconformances noted in GA Program Insp Rept 99900378/83-01. Insp Procedures NSP20-0005-000B revised, issued & implemented. BHANBONIN E Acme-Claveland Co 84/02/17, POTAPOVS.U Vendor Program Branch. 1p. 82436 114
- 8403010122 Responds to NRC 830721 & 1205 ltrs re viplations & homconformances noted in GA Program Insp Repts 99900277/83-01,99900277/83-02 & 79900277/83-04 Corrective actions tests will be performed on Class IE cable types LITTLEHALES.0, Rockbestos Co. 84/02/14, POTAPOVS,U Region 4, Office of Director 25pp. 22435;253
- 8403050086 Confirms GA program insp at Philadelphia, PA facility on 840305-09, per 840216 telcon, POTAPOVS. U. Vendor Program Branch 84/02/23 CURNANE, R. A United Engineers & Constructors, Inc. (subs. of Raytheon Co.), 1p. 22490,006.

- 8403050089 Confirms QA program insp at Grove City,PA plant on 840312-16,per 840217 telcon PDTAPOVS,U Vendor Program Branch 84/02/24 STQLBA,F B Cooper Industries, Inc. 1p 22490 013
- 8403050102 Clarifies items mentioned in QA Program Insp Rept 99900820/83-01 Formal training conducted in Nov 1983 included personnel performing quality affecting activities Omega Engineering certified calibr of equipment performed MCCRONE.J Fluorocarban Co 84/02/17 POTAPDVS,U Vendor Program Branch 3pp 22485 230
- 8403050120 Responds to NRC 840126 ltr re deviation noted in QA Program Insp Rept 99700330/83-02 Corrective actions specified max value reevaluated Exceeding value did not adversely affect performance of UVID Condition not reportable per Part 21 SAUTER D N Westinghouse Electric Corp 84/02/23 PDTAPOVS, U Vendor Program Branch 2pp 22488 030
- 8403050126 Confirms GA program insp at Willimantic.CT plant on 840312-16.per 840213 telcon POTAPOV8.U Vendor Program Branch 84/02/27 ROSERTS.L B Brand-Rex Co 1p 22489 158
- B403050130 Confirms GA program insp at Lynchburg, VA plant on B40312-16, per 840224 telcon PDTAP0VS,U Vendor Program Branch Babcock & Hilcox Co ip 22489 171
- 8403050176 Confirms QA program insp at State of DR ofc on 840305-09, per 840216 telcon POTAPOVS,V Vendor Program Branch 84/02/24 WALTERS.C H Oregon. State of ip 22489 065
- 8403060006 Confirms GA program insp at Colorado Springs.CO plant on 840312-16.per 840224 telcon PDTAPOVS.U Vendor Program Branch 84/03/01 PIRAIND.D Kaman Co 1p 22513 362
- 8403060092 Ack receipt of 831013 & 840131 ltrs informing NRC of steps taken to correct violation & nonconformance noted in GA Program Insp Rept 99900330/83-01 POTAPOUS.U Region 4. Office of Director 84/03/01 SAUTER, D M Westinghouse Electric Corp 1p 22516 309
- --8403060096 Responds to NRC 840109 ltr re monconformance noted in QA Program Insp Rept 99900330/83-01 Corrective actions each undervoltage trip device assigned unique serial number JONES, D I , SAUTER, D M Westinghouse Electric Corp 84/01/31 POTAPGVS.U Region 4, Office of Director 1p 22516 310
- --8403060098 Ack receipt of 831013 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900330/83-01 Addl info required for Item C of notice of nonconformance re undervoltage trip devices POTAPDVS,V Region 4. Office of Director 84/01/09 SAUTER,D M Westinghouse Clectric Corp 1p 22516 311
- ~-BAQ3060101 Responds to NRC 830913 ltr re violation & nonconformance noted in GA Program Insp Rept 99700330/83~01 Corrective actions revised poster w/revs promulgated up to 830110 completed & revised poster will be posted promptly JDNEG.D B . SAUTER.D M Westinghouse Electric Corp 83/10/13 POTAPOVS.U Region 4. Office of Director 5pp 22516 312
- 84030±0157 Ack receipt of 840202 ltr informing NRC steps taken to correct nonconformance noted in 0A Program Insp Rept 99900002/83-02 POTAPOVS.U Region 4, Office of Director 84/03/01 LICHTENBERGER Combustion Engineering. Inc. 1p 22528 210
- --8403060161 Responds to NRC 840109 ltr re nonconformance noted in 0A Program Insp Rept 99900002/83-02 Corrective actions individuals responsible for review & approval of certification data alerted to discrepancies observed LICHTENDERGER Combustion Engineering, Inc. NGA 84-003 84/02/02 FOTAPOVS, U. Region 4. Office of Director. 2pp 22528 211
- 8403060187 Responds to NRC 840124 ltr re nonconformance noted in GA Program Insp Rept 99900231/83-01 Corrective actions 810922 ltr from Isomedix confirmed applicability of Parts 21 & 50 for prior work BRODEUR, R I Okonite Co 84/02/14. POTAPOVS, U Region 4, Office of Director 1p 22518 361
- 8403060219 Ack receipt of 840125 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900519/88-03 POTAPOVS, U Vendor Program Branch 84/02/16 KOMES, J M Dechtel Coro ip 22908 264

- --8403060228 Responds to NRC 831228 ltr re nonconformance noted in GA Program Insp Rept 99900519/83-Q3 Corrective actions Engineering Dept Procedure EDP 5 1 revised to require interdiscipline communications of significant nature KONES, J M Bechtel Corp. DAS-84/030 84/01/25 POTAPOVS, U. Vendor Program Branch Spp 22508 265
- 8403060251 Confirms GA program insp at Tulsa,OX plant on 840326-30,per 840228 telcon POTAPOVS,U Vendor Program Branch 84/03/01 DUVALL,D.D. Brown Boveri Corp (subs of Brown Boveri & Co , Ltd) 1p 22515 194
- 8403060262 Responds to NRC 831220 ltr re nonconformances noted in GA Program Insp Rept 97900277/83-03 Corrective actions GC supervisor responsible for followup to assure irradiation unit calibr completed on schedule & stickers in order LITLEHALES, G Rockbestos Co 84/02/27 POTAPOVS, U, Region 4. Office of Director 3pp 22517 129
- 8403040282 Confirms GA program insp at ABME administration ofc on 840326-30, per 840227 telcon POTAPUS U Region 4, Office of Director 84/03/02 GREEN, MR American Society of Mechanical Engineers ip. 22519, 070.
- 8403060287 Confirms GA program insp at Beloit.WI plant on 840326-30, per 840301 telcon POTAPUVS.U Vendor Program Branth 84/03/02 MORIARTY.J M Colt Industries, Inc. ip 22518 362
- 8403040348 Ack receipt of B31123 & 840217 ltrs informing NRC of steps taken to correct deviations & nonconformancs noted in GA Program Insp Rept 97900820/83-01. PGTAPOUS.U Vendor Program Branch. 84/03/02 MCCRONE, J Fluorocarbon Co 1p 22508 054
- --8403060352 Ack receipt of 831108 & 23 ltrs informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 97900820/83-01 Addl info re training & surveys requested within 25 days of itr date PUTAPOVB.U Vendor Program Branch 84/01/23 MCCRONE, J Fluorocarbon Co ip 22508 055
- --8403060355 Requests delay in submitting response to 831012 ltr re nonconformance noted in GA Program Insp Rept 99900820/83-01 Response expected by 831118 MCCROME, J Fluorocarbon Co 83/11/08 CDNWAY, J T Region 4: Office of Director 1p 22508 056
- ---8403060361 Responds to NRC 831012 ltr re nonconformance noted in GA Program Insp Rept 99906820/83-01 Corrective actions Section 206,FCD GA Procedure CGCP-013 & 830831 10CFR21 notice posted MCCROME,J, Fluorocarbon Co 83/11/23 POTAPOVE,V Region 4, Gffice of Director App 22508 057
- --8403060365 Rev O to Procedure CGCF-013, "Procedure for Reporting Defects & Noncompliance" SHIBLER,E Fluorscarbon Co 83/11/17 Bpp 22508 061.
- --8403060369 Rev O to Procedure OCP-014. "Indoctrination & Training Procedure for GC Personnel"
 SHIBLER,E Fluorocarbon Co 83/09/28 App 22508 069
- --8403040372 Rev O to Procedure QCP-017, "Qualification of Personnel for NDT" SHIBLER.E Fluorecarbon Co 83/11/17 24pp 22508:073
- --B403060374 Rev O to Procedure CMP-047, "Weld Removal Procedure "
 BHISLER,E Fluorocarbon Co 83/11/17 30pp 22508 097.
- --8403060376 Rev 1 to Procedure CPB-023, "Weld Aging Procedure for Nuclear O-Rings" PRINTZ, M Fluorocarbon Co 83/11/17 7pp 22508 127
- --8403060379 Rev 1 to Procedure QCP-020, "Training Procedures for Radiographers "
 SHISLER,E Fluorocarbon Co. 83/11/17, 9pp 22508.134.
- 8403120036 Ack receipt of 840217 ltr informing NRC of steps taken to correct nonconformance noted in 84 Program Insp Rept 97900378/83-01 implementation of corrective actions will be reviewed during future insp POTAPOVS, U Vendor Program Branch. 84/03/05 SHANSON, N. E. Acme-Cleveland Co ip 22589:270

- B403120043 Respands to NRC B40124 ltr re nonconformance noted in GA Program Insp Rept 99900702/B3-01 Corrective actions Engineering Change Proposal 6717 instigated to activate Engineering Change Notice 8712 voided 820702 JONES, W.F. Morrison-Knudsen Co., Inc. 84/02/28 POTAPOVS, U Vendor Program Branch 7pp 22587 279
- 8403120108 Ack receipt of 840203 ltr informing NRC of notification to customers re potential loosening of globe valve anti-rotation collar set screws & recommended corrective action per GA Program Insp Rept 99790053/93-03 POTAPOVS.U Vendor Program Branch 84/03/05 CARDN.A E Anchor/Darling Valve Co (subs of Anchor/Darling Industries, Inc.) ip 22588 122
- --8403120114 Forwards sample ltr.w/attachments & cover ltrs dtd 831017-840130.sent to customers having Anchor/Darling globe valves w/nonrotating stems per QA Program Insp Rept 99700053/83-03 KNIEBER.Q W Anchor/Darling Valve Co (subs of Anchor/Darling Industries, Inc) 84/02/03 KELLEY.W Vendor Program Branch 3700 22588 123
- B403120117 Responds to NRC 1tr re nonconformance noted in QA Program Insp Rept 99700394/83-02 on B31215 Corrective actions Rejection Rept 04660 paperwork corrected & memo issued rerequirements for recording rejection rept numbers BHAFER, J C Metal Bellows Corp 84/02/24 POTAPOVS, U Vendor Program Branch 4pp 22589 214
- 8403130026 Responds to NRC 840131 ltr re nonconformance noted in GA Program Insp Rept 997007861/83-02 Corrective actions annual GA audit will confirm documentation for set-up & operator training & qualification, per GA manual requirements DIXON.D J General Electric Co 84/03/01 POTAPOVS, U Vendor Program Branch 9pp 22615 114
- 8403130032 Forwards GA Program Insp Rept 99900273/83-02 on 831205-09 & hotice of honconformance POTAPOUS,U Vendor Program Branch 84/02/02 SCHMIDT.W T Wastinghouse Electric Corp 2pp 22614.308
- --8403130036 Notice of nonconformance from insp on 831205-09 * Vendor Program Branch 84/02/02 1p 22614 310
- ---8403130042 GA Pregram Insp Rept 97900273/83-02 on 831205-09
 Noncompliance noted internal audits not performed prior to
 current NRC insp & correct suffix not applied to style
 numbers on SA-1 relay nameplates for current relay units
 SUTTON.J W , HALE.C. Vendor Program Branch 84/01/30 13pp
 22614 311
- 8403130046 Ack receipt of undated ltr received on 840126 informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 97900400/83-02 POTAPOVS,U Vendor Program Branch 84/02/16 GUILBERT,D E Babcock & Wilcox Co 19 22615 247
- ---B40313005B Responds to NRC B31117 & 1223 ltrs re nonconformance noted in GA Program Insp Rept 99900400/83-02 Corrective actions STALUM computer program users manual updated & B&W Calculation Document 32-457B-00 will be revised QUILBERT,D E Babcock & Wilcox Co 84/01/26 POTAPOVS,U Vendor Program Branch App 22615 248
- ---B40313006B Forwards correct encls to B31117 transmittal ltr.consisting of GA Program Insp Rept 97900400/83-02 on B31004-07 & notice of nonconformance W/o encls POTAPOUS,U Region 4, Office of Director B3/12/23 QUILBERT,D & Babcock & Wilcox Co ip 22615 254
- --8403130076 Advises that NRC 831117 ltr forwarded GA program insp rept of another company Original ltr & rept enci. KOBIBA,R E Babcock & Wilcox Co B3/11/28 POTAPOVS,U Region 4. Office of Director 1p 22615 255
- ---B403130089 Forwards GA Program Insp Rept 99900400/B3-02 on 831004-07 & notice of nonconformance. W/o correct encls POTAPOVS, U Region 4, Office of Director B3/11/17 QUILBERT, D E, Babcock & Wilcox Co 2pp 22615 256
- 8403130055 Ack receipt of 840201 ltr informing NRC of steps taken to correct nonconformances noted in GA Program Insp Rept 79900403/83-04 POTAPOVB, U. Vendor Program Branch 84/02/07. BRUGGEMAN, W H General Electric Co 1p 22415 214
- --8403130064 Responds to NRC B40109 1tr re nonconformances noted in GA Program Insp Rept 99700403/83-04 Corrective actions design change documentation initiated database updated & audit initiated to preclude recurrence BOHL, L. 8 General Electric Co 84/02/01 POTAPDVS, U Vendor Program Branch. 2pp. 22615 217.

- 8403130169 Responds to NRC 831206 ltr re nonconformance noted in GA Program Insp Rept 99900224/83-02 Corrective actions Instruction 1766-03-01 re contact for unknown customers revised Related info encl HOME: H Bailey Controls Co (subs of Babcock & Wilcox Co) 84702/29 POTAPOVS.U Vendor Program Branch 31pp 22608 ild
- B403130244 Responds to NRC B31223 ltr re nonconformance & violation noted in GA Program Insp Rept 99900539/B3-01 Corrective actions procedures for evaluating deviations reviewed & Section 206 of Energy Reorganization Act posted ALLENR D MATSCO (subs of Multi-Amp Corporation) B4/01/10 POTAPOVS, U Region 4. Office of Director 3pp 22617 273
- B403130268 Forwards OA Program Insp Rept 99900616/84-01 on 840116-18 No noncompliance noted POTAPUS,U Vendor Program Branch 84/02/17 GREEN,M American Society of Mechanical Engineers 2pp 22604 350
- --8403130432 GA Program Insp Rept 99900616/84-01 on 840116-18 No noncompliance noted Major areas inspected program survey, manual review & acceptance criteria.program implementation & certificate of authorization status SUTTON.J W., HALE.C J. Vendor Program Branch 84/02/17 5pp 22604 352
- 8403130276 Forwards GA Program Insp Rept 99900522/84-01 on 840116-19 & notice of nonconformance POTAPOVS, U Vendor Program Branch 84/02/08 STRATTON, C D Bechtel Corp 2pp 22417 167
- --8403130281 Notice of nonconformance from insp on 840116-19 * Vendor Program Branch 84/02/08 2pp 22417 169
- --B403130291 QA Program Insp Rept 99900522/84-01 on 840116-19
 Noncompliance noted faiture to include preaudit & post-audit conference w/project audit & incorporate all design changes into design documents by required due date
 CQSTELLO, J. R., NADSEN, Q. Vendor Program Branch 84/02/07 25pp 22417 171
- 8403130884 Responds to NRC 840208 ltr re nonconformance noted in GA Program Insp Rept 99900522/8--01 Corrective actions senior person designated in each engineering discipline group to be responsible to project engineer for document followop STATION.C D Bechtel Corp 84/03/01 POTAPOVS, U Vendor Program Branch 6pp 22614 140
- 8403130309 Forwards QA Program Insp Rept 99900616/84-02 on 840123-25 No moncompliance nuted POTAPOVS.U Vendor Program Branch 84/02/14 OREEN, M American Society of Mechanical Engineers 2pp 22614 132
- --8403130325 QA Program Insp Rept 99900616/84-02 on 840123-25 No noncompliance noted Major areas inspected program survey, manual review & acceptance criteria, program implementation & certificate of authorization status

 OLLER, R E , HALE, C J Vendor Program Dranch 84/02/16 4ρp
- 8403130314 Responds to NRC 840117 ltr re nonconformances noted in QA Program Insp Repts 97900334/83-02 & 97900334/83-03 Corrective actions QA manual & assembly route sheet revised & training class for inspectors will be held BOYER.R E Transamerica Delaval, Inc. 84/03/02 POTAPOUS.U Vendor Program Branch 18pp 22608 063
- 8403130317 Ack receipt of 840104 & 0214 ltrs informing NRC of steps taken to correct monconformance noted in GA Program Insp Rept 99900255/83-01 POTAPOVS.U Vendor Program Branch 84/03/05 HADNAOY,P A Pacific Scientific ip 22614 120
- --B403130329 Ack receipt of B40104 ltr in response to GA Program Insp Rept 99900255/83-01 Addl info requested re manner by which suppliers of non-ABME Code items qualified & approved & GA manual revised to exempt non-ABME vendors POTAPOVB.U Vendor Program Branch B4/01/26 HADNAGY, P A Pacific Scientific ip 22614 121
- --840313033B Responds to NRC B31204 ltr re nonconformance noted in GA Program Insp Rept 99900255/63-01 Corrective actions calibr technician advised to exercise greater care in maintaining certifications THOMBEN,E R Pacific Scientific 4000-GS-43-84 84/01/04 POTAPOVB,U Region 4. Office of Director 4pp 22614 122
- 8403130407 Forwards GA Program Insp Rept 99900400/83-02 on 831004-07 & notice of nonconformance POTAPOVS, U Region 4, Office of Director 83/11/17 GUILBERT, D E Babcock & Wilcox Co 2pp 22608 276

- --8403130414 Notice of nonconformance from insp on 831004-07 # Region 4, Office of Director 83/11/17. 2pp 22608 278
- --8403130425 GA Program Insp Rept 99900400/83-02 on 831004-07
 Noncompliance noted full certified Version 17 0 of STALUM
 computer program did not have controlled program manual &
 failure to identify incorrect values in stiffness matrix
 RRICKLEY, R H . HALE, C J Region 4. Office of Director 83/11/17
 130s 22408 280
- 8403130441 Forwards QA Program Insp Rept 79700530/84-01 on 840123-26 & notice of nonconformance POTAPOVS,U Vendor Program Branch 84/02/17 SHULMAN,M Cygna Energy Services 2pp 22614 051
- --8403130444 Notice of nonconformance from insp on 840123-26 * Vendor Program Branch 84/02/17 ip 22614 053
- --B403130460 GA Program Insp Rept 99900530/84-01 on B40123-24

 Nonconformance noted quality std operating procedures in GA
 dept procedures manual did not indicate effective data &
 four procedures did not contain preparer signature or data

 BRICKLEY, R H , HALE, C J Vendor Program Branch 84/02/17 10pp
 22614 054
- B403160119 Forwards vendor insp mepts identifying concerns based on Vendor Program Dranch insps of vendor activities Bignificance of findings re quality & acceptability of product or svc provided by vendor should be evaluated GAOLIANDBUJE Region 4. Office of Director 84/03/13 KDESTER. O. L. Kansas Oss & Electric Co 2pp 22455 116 24X Fiche, 50-482, 84/03/13, 8403160119
- B403160235 Forwards vendor insp rmpts identifying concerns found by Vendor Program Branch during insp of vendor activities Evaluation of significance of findings re quality & acceptability of product or svc requested JOHNSON.E H Region 4, Office of Director B4/03/13 CAHILL, W B Gulf States Utilities Co. 2pp 22661 043 24X Fiche 50-458,84/03/13,8403160235
- B403160242 Forwards vendor insp repts identifying concerns found by Vendor Program Branch during insp of vendor activities Evaluation of findings requested acceptability of groduct or syc by vendors requested JOHNSON, E H Region 4, Office of Director B4/03/13 LEDDICK, R B Louisiama Power & Light Co 3pp 22661 026 24% Fiche 50-382,84/03/13,8403160242
- B403190041 Confirms QA program insp at Alexandria.LA plant on B40326-30.per B40302 telcon POTAPOVB.U Region 4. Office of Director B4/03/09. SCHAUB.R L. Dresser Industries. Inc. 1p. 22664-245
- 8403190046 Confirms QA program insp at Apex.NC lab on 840319-23.per 840301 telcon FOTAPDVB.V Region 4. Office of Director, 84/03/08 YOW.J.R Corporate Consulting & Development Co. Ltd 1p 22666 249
- 8403170070 Ack receipt of B40224 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 97900394/83-02 PDTAPGWS,U Region 4, Office of Director 84/03/07. SCHAFER, J C Metal Hellows Corp 1p 22666:134
- B403190078 Ack receipt of B40301 ltr informing NRC of steps taken to correct monconformance noted in QA Program lnsp Rept 99900522/84-01 PGTAPUB.U Region 4, Office of Director B4/03/08 STATTON, C. D Bechtel Corp 1p 22669 361
- 8403190112 Forwards Vendor Program Insp Rept 99900100/84-01 on 840130-0203 Insp rept closes out tack welding of motor shaft deficiency POTAPOUS U Region 4, Office of Director 84/03/15. LEWIS.R C. Division of Project & Resident Programs ip 22669 218

o NRC 840202 ltr re nonconformance noted in GA '900273/83-02 Corrective actions.1983 div te, all audit repts on file in GA ofc & onducted --- cyctric Corp 84/03/02, POTAPOVS.U in 22666,315,

informing NRC of steps taken to noted in GA Program Insp of corrective actions

irector 84/03/08 VIQGIANO, V A.

- E4031701B3 Forwards QA Program Insp Rept 97900100/B4-01 to B40130-0203 & notice of nonconformance POTAPOVS.U Region 4. Office of Director B4/03/02 MIGNOGNA.T. Limitorque Corp 3pp 22670 323
- ~-8403190165 Notice of nonconformence from insp on 840130-0203 * Region 4, Office of Director 84/03/02, 2pp. 22670 326.
- ---B403190190 GA Program Insp Rept 99700100/84-01 on B40130-0203.

 Nonconformance noted: corrective action in training non-QC
 personnel inadequate
 MCNEILL.W H. HALE, C. J. Region 4, Office of Director 84/03/01.

 26pp 22670 328.
- 8403170203 Confirms 840307 telcon request to withhold info in NRC B40229 let & GA Program Insp Rept 997000840/83-01 FIEDLER, D.C. Cardinal Industrial Products Corp 84/03/12, POTAFOV8, U. Region 4, Office of Director ip 22671 131
- 8403190206 Discusses closeout of AITS F02700410 re inadequate GA program at Limitorque Corp. addressed in encl Vendor Program Branch Insp Rept 99700100/84-01 on 840130-0203 TVA audit conclusions valid Limitorque GA program inadequate. W/o encl POTAPOVB. U Region 4. Office of Director 84/03/14 LEWIS,R.C. Division of Project & Resident Programs. PARTLOW, J.O. Division of GA. Sefeguards & Inspection Programs (Post 830103). 2pp 22670:361
- B403190209 Forwards QA Program Insp Rept 99900231/84-01 on 840116-20 & notice of nonconformance POTAPOVB, U Region 4, Office of Director. 84/02/23 VIGGIAND, V. A Dixoste Co 2pp 22670 297.
- --8403190210 Notice of nonconformance from insp on 840116-20.

 * Region 4, Office of Director 84/02/23 ip. 22670.299.
- 8403190218 Forwards GA Program Insp Rept 99900904/83-01 on 831213-16. No noncompliance noted. POTAPUS,U Region 4. Office of Director 84/02/24 MIGNOGNA.T Limitorque Corp 2pp 22670 248
- --8403190221 QA Program Insp Rept 97900904/83-01 on 831213-16. No noncompliance noted Major areas inspected environ qualification test plan & action on previously identified findings re nuclear qualification facility QA manual JOHNBON, A R. PHILLIPS H 8 Region 4. Office of Director 84/02/23. 15pp 22670 250
- B403190254 Confirms GA program inspa at Chalfont, Horsham & Spring House, PA plants on B40416-19, per 840309 telcon POTAPOVS. U. Region 4, Office of Director 84/03/14 DUVALL, D D Brown Boveri Corp (subs of Brown Boveri & Co., Ltd.), 1p 22671 298
- B403190328 Forwards GA Program Insp Rept 99900781/84-01 on 840116-20 & notices of violation & nonconformance POTAPOVS.U Region 4, Office of Director. 84/02/24 JANDL.J.C. Lone Star Screw Co. 3pp 22675-007
- --8403190330 Notice of violation from insp on 840116-20, * Region 4, Office of Director. 84/02/24. 1p. 22675 010.
- ---B403190333 Notice of nonconformance from insp on 840116-20 * Region 4, Office of Director B4/02/24 5pp. 22675.011.
- --B403190340 QA Program Insp Rept 99900781/84-01 on 840116-20 Violations & noncompliance noted lack of appropriate procedures to evaluate deviations & review of records revealed eye exam record missing for 1981 for Level II examiner. CONMAY, J T, BARNES-1, Region 4. Office of Director. B4/02/24, 10pp. 22675 016.
- 8403190327 Forwards Vendor Program Insp Repts 99900231/83-01 & 99900231/84-01 on 831115-17 & 840116-20 respectively, closing out Part 21 rept re seepage of oil from Okonite cables.

 POTAPOVS, U Region 4, Office of Director, 84/03/15, NORELIUS, C E Division of Project & Resident Programs, 1p, 22675,026, 24X Fiche: 50-461,84/03/15,8403190329.
- B403190337 Confirms GA program insp at Los Angeles, CA plant on G40326-30, per B40307 telcon.
 POTAPOVS, U. Region 4, Office of Director, B4/03/09, PATTERSON, R. L. Bachtel Corp. 1p. 22675: 029

- 8403190338 Discusses insp on 840130-0203 re failure of Limitorque spring compensator housings Results of insp documented in encl Vendor Program Branch Insp Rept 97900100/84-01
 Westinghouse evaluation continuing Wo encl
 POTAPDUS,U Region 4. Office of Director VITS 84-031
 LEWIS.R C Division of Project & Resident Programs 1p 22673 285
- B403190342 Confirms QA program insp at Salam, MA plant on 840402-06, per B40301 telcon POTAPOVS, U Region 4. Office of Director 84/03/15 COVEY, J Atwood & Morrill Co . Inc (subs of Foster Wheeler Corp) 1p 22675 044
- 8403170364 Discusses insp on 840130-0203 re Limitorque cracked/broken limit switch rotors Results of insp documented in encl Vendor Program Branch Insp Rept 97900100/84-01 Evaluation of condition continuing W/o encl.
 POTAPOVB, U Region 4, Office of Director VITS 83-184 84/03/15 NORELIUS, C E Division of Project & Resident Programs 1p 22675 234
- 8403190380 Ack receipt of 840214 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900230/83-01 Implementation of corrective actions will be reviewed during future insp POTAPOVS, U Region 4, Office of Director 84/03/07 CARDELLO.F S Anaconda Co (subs of Atlantic-Richfield Co) 1p 28674 220
- B403200072 Ack receipt of B31219 & 840229 ltrs informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99700224/B3-02 POTAPOVB, U Region 4, Office of Director 84/03/15 KEYEB, M A Bailey Controls Co (subs of Babcock & Wilcox Co) ip 22685 031
- --8403200076 Responds to NRC 831206 ltr re nonconformance noted in GA Program Insp Rept 97900224/83-02 Requests 30-day extension of response time due to personnel on vacation & facility closed 831223-840102.

 HOME, H Bailey Controls Co (subs of Babcock & Milcox Co) 83/12/17 POTAPOVS, U Region 4, Office of Director (p 22685 032
- 8403200138 Ack receipt of 831017,1108 & 840228 ltrs informing NRC of steps taken to correct violations & nonconformance noted in GA Program Insp Rept 99700702/83-01 Implementation of corrective actions will be reviewed during future insp POTAPOVS.U. Region 4, Office of Director 84/03/07 JONES.W F. Morrison-Knudsen Co , Inc. 1p. 22697 075.
- --8403200142 Ack receipt of 831017 & 1108 ltrs informing NRC of steps taken to correct nonconformance noted in GA Program Insp. Rept 99700702/83-01 Add1 info re seismic capability of valve requested within 25 days. POTAPOVE.U Region 4. Office of Director 84/01/24 JONES,W F. Morrison-Knudsen Co., Inc. 1p. 22697-076
- ---B403200150 Responds to NRC 830930 ltr re violations & nonconformance noted in GA Program Insp Rept 99900702/B3-01 Corrective actions:personnel involved w/data acquistition & Part 21 repts instructed on need for describing violations JONES,F Morrison-Knudsen Co., Inc. 83/10/17. Region 4, Office of Director App. 22697 077.
- --8403200157 Forwards Morrison-Knudsen Co.Inc 831017 response to GA Program Insp Rept 99700702/83-01. STAUBER.R. H Morrison-Knudsen Go . Inc 83/11/08 POTAPOVS.U Region 4. Office of Director 1p 22697 083
- 8403260052 Confirms QA program insp at Tempe, AZ plant on 840409-13, per 840306 telcon, POTAPOVB, U. Region 4, Office of Director 84/03/19 SAYLOR, K Tobar, Inc. 1p. 22748, 362.
- 8403270050 Ack receipt of 840111 ltr informing NRC of corrections to GA Program Insp Rept 99900932/83-01 POTAPOVS.U. Region 4. Office of Director 84/03/21 SEMMLER,R. W Eaton Corp. ip 22769:309
- --8403270054 Responds to NRC 840103 ltr re QA Program Insp Rept 99900932/83-01. Errors found in rept listed SEMMLER, R.W. Eaton Corp 84/01/11. POTAPOVS, U Region 4, Office of Director. 2pp. 22769: 310
- 8403270087 Responds to NRC 840223 ltr re nonconformance noted in GA Program Insp Rept 99900231/84-01. Corrective actions nuclear qualification repts revised re temp-pressure profile & test vessel modified.

 BRODEUR, R. I. Okonita Co 84/03/14 POTAPOVS, U Region 4, Office of Director. ip 22766: 247.

- 8403270072 Ack rereipt of B40202 ltr informing NRC of staps taken to correct nonconformance noted in GA Program Insp Rept 97900053783-03
 POTAPOVS, U Region 4, Office of Director 84/03/21 CARDN, A E Anchor/Darling Valve Co (subs of Anchor/Darling Industries, Inc.) ip 22766 333
- --B403270097 Responds to NRC B40112 ltr re nonconformance noted in GA Program Insp Rept 99904053/83-03 Corrective actions training session conducted on importance of checking radii for backface on valve bonnet flanges
 KNIFSER, G W Anchor/Darling Valve Co (subs of Anchor/Darling Industries, Inc.) B4/02/02 PDTAPOVS, V Region 4, Office of Director 2pp 22766 334
- B40327010B Responds to B40307 request for add1 info re measures taken or to be taken to preclude recurrence of nonconformance w/ASME Code requirements identified in GA Program Insp Rept 99900845/83-01 Titeflex Corp nonconformance regt encl LALIMOS.J M Titeflex Corp 84/03/12 PDTAPOVS.U Region 4, Office of Director 3pp 22774 029
- 8403270115 Responds to NRC 840217 ltr re nonconformance identified in GA Program Insp Rept 99900330/84-01 Corrective actions all quality std operating procedures reviewed & corrections issued
- SHULMAN, M N Cygna Energy Services 84/03/12 POTAPOVS, U Region 4. Office of Director 3pp 22774 052
- 8403270142 Confirms GA program insp at Ban Diego, GA plant on 840402-06, per 840319 talcon POTAPOVS, U Region 4, Office of Director 84/03/22 COLANDRA, T R GA Jechnologies, Inc /General Atomic Co ip 22769 145
- 8403270148 Responds to 9A Program Insp Rept 99900371/83-01 & 840307
 Itr Bolt lists are not drawings & do not require checking
 Bolt lists prepared as convenience for preparing summaries
 in procurement & for convenience of erector
 CDRRIN,R J Bristol Steel & Iron Works, Inc 84/03/14 POTAPOVS,U
 Region 4. Office of Director 2pp 22769 146
- 8403270168 Confirms OA program insp at Richland.WA plant on 840403-05, per 840320 telcon Insp concerns implementation of QA program re control of computer codes SLOTRAX & PTWPHR2 POTAPOUS.U Region 4, Office of Director 84/03/22 VOLMER,C J Exxon Nuclear Co , Inc (subs of Exxon Corp) ip 22772 IBi
- 8403270174 Confirms GA program insp survey at administrative of of Factory Mutual Engineering Assoc on 840416-20, per 840319 telcon NRC representative will be JW Button POTAPURS U Region 4. Office of Director 84/03/21 WHELAN, M Factory Mutual Engineering Corp Ip 22771 308
- 8403270178 Forwards GA Program Insp Rept 99900616/84-03 on 840213-15 PDTAPDVS, U Region 4, DPFice of Director 84/03/07 GREEN, M American Society of Mechanical Engineers 2pp 22772 139
- --B403270184 GA Program Insp Rept 97900616/84-03 on 840213-15 Major areas inspected. ASME audit activities during Newport News Shipbuilding & Dry Dock Co GA program audit DLLER, R. E. + HALE, C. J. Region 4. Dffice of Director 84/03/06 3pp. 22772 141
- B403270222 Responds to NRC telcon request re nonconformance noted in GA Program Insp Rept 99700732/83-02 Corrective actions items reinspected & individually marked Preliminary stress analysis rept returned for correction of minor errors OIESLER.J V Robert Shaw Controls Co 84/03/13 POTAPOVS.U Region 4. Office of Director Ip 22772 086
- 8403270228 Forwards QA Program Insp Rept 97900884/83-01 on 831205-09 & notice of nonconformance POTAPOVS.U. Region 4. Office of Director 84/03/02 BLANKLEY.W Ametek.Inc. 2pp 22772-045
- --8403270234 Notice of nonconformance from insp on 831205-09
 * Region 4, Office of Director 84/03/02 5pp 22772 067
- ---8403270241 QA Program Insp Rept 97900884/83-01 on 831205-09
 Noncompliance noted ASME Code requirements not certified on
 mat! manufecturer certified mat! test repts to vendor
 CONHAY.J T , HAMILTON.J . BARNES, I Region 4. Office of Director
 84/02/08 9pp 22772.072

REGGD REGULATORY GUIDES

- 8312070358 Notification of CRGR Meeting 51 on 831123 to review exemption from CRGR review of Unresolved Safety Issue A-1 "Mater Hanmer" & proposed rev to Reg Guide 1 28, "GA Program Requirements (Design & Const)"
 STELLO, V Committee to Review Generic Requirements B3/11/10 MATTSON,R J. Office of Nuclear Reactor Regulation, Director JORDAN,E L. Director's Office, Diffice of Inspection and Enforcement CUNNINGRAM,R E. Office of Nuclear Material Safety & Safeguards, Director 2pp 22681 352
- 8403010347 Forwards status & justification for mine listed NUREG-0737 & Reg Guide 1 97 Items.per B40222 request Analysis of safety parameter display sys will be submitted by B40430 MUXILL.H O General Public Utilities GPU Service Corp 5211-84-2045 84/02/27 EISEN-WIT, D G Division of Licensing 21pp 22433 018 24X Fiche 50-289,84/02/27.8403010347
- 8403020225 Reg Guide 5 53.Rev 1.Tast 86 049-4, "Gualification.Calibr & Error Estimation Methods for Nondestructive Assay "

 # Office of Nuclear Regulatory Research, Director 84/02/29 11pp 22491 008
- 8403020329 Responds to request for schedule for completion of Reg Quide 1 97 requirements Exceptions to Billia ltr re equipment replacement will be addressed in Hay 1984, in response to Generic Ltr 82-33 CURTIS, N W Pennsylvania Power & Light Co PLA-2081 84/02/29 SCHMENCER, A Licensing Branch 2 ip 22439 207 24X Fiche 50-387,84/02/29,8403020329
- 8403060354 Forwards descriptions of Reg Guide 1.97 requirements & schedule for implementation of emergency response capability, ser NAREG-0737, Suppl 1 PILANT, JM Nebraska Public Power District NLS8400073 84/03/01 EISENHUT, D & Division of Licensing 17pp 22515 311 24X Fiche 50-298.84/03/01.8403040354
- 8403060494 Reg Guide 5 23, Rev 1. Task SG 045-4. "In Situ Assay of Pu Residual Holdup " * Office of Nuclear Regulatory Research, Director 84/02/29 18pp 20552 187
- --8403060499 Value/impact statement of Reg Guide 5 23,Rev 1,Task SC 045-4, "In Situ Assay of Pu Residual Holdup " * Office of Nuclear Regulatory Research, Director 84/02/29 ip
- 8403080378 Forwards responses to NRC 840105 questions re FSAR revs.
 including info re training staff qualifications, GA staff
 qualifications, fire protection training & conformance to
 Reg Guide B 13 Proposed revs to FSAR also encl
 BOOKER, J E Guif States Utilities Co R80-17.082 B4/02/17
 DENIGN, HR Office of Nuclipar Reactor Regulation, Director 42pp
 22356 200 24X Fiche 50-436.84/02/17.8403080378
- 8403150070 Responds to 831230 requests for response to items identified in ECkG technical evaluation rept on conformance to Reg Guide 1 97 & comments on any assumptions that surpass util Billi3 submittal CURTIS, N W Permsylvania Power & Light Co PLA-2099 84/03/13 BCHWENCER, A Licensing Branch 2 8pp 22643 183 24X Fiche 50-387,84/03/13,8403190070
- B403190146 Notifies of CRGR Meeting 47 on 830923 in Sethesda, MD to discuss proposed exemptions to regulations in implementation of Multi-Plant Action D-10 (Unresolved Safety Issue A-2) & Rev P to Reg Guide I 105
 STELLD.V Committee to Review Generic Requirements 83/09/15
 MATTSON.R J Office of Nuclear Reactor Regulation, Director JURDBAN.E L Director's Office of Proposition and Enforcement CUNNINGHAM, R E Office of Nuclear Material Safety & Safeguards, Director 2pp 22666 359
- B403190176 Notifies of CRGR Meeting 48 on 831020 in Bethesda, MD to discuss exemption of Category 2 personnel from 10CPR50 55a. "Codes & Stds." proposed rulemaking & proposed rev to Reg Guide 1 105
 STELLO, V Regional Operations & Generic Requirements B3/10/14
 NATISDN:R J Office of Nuclear Reactor Regulation, Director JDRDAN, E L Director's Office, Office of Inspection and Enforcement CUNINDRAN, RE Office of Nuclear Haterial Safety & Safeguards, Director 2pp 22471 163

- 8403190260 Notifies of CRGM Meeting 54 on 840118 in Bethesda, MD to discuss Rev I to Reg Guide 1 89, "Environ Qualification of Electric Equipment Important to Safety for Nuclear Power Plants " STELLD. V Regional Operations & Generic Requirements IEB-79-018. B3/12/27 MATTSON.R J Office of Nuclear Reactor Regulation, Director JORDAN.E L Director's Office, Office of Inspection and Enforcement CUNNINGHAM, R E Office of Nuclear Material Safety & Safeguards. Director Ip 22672 058
- 8403170372 Notifies of CRGR Meeting 53 on 840111 in Bethesda. MD to discuss revs to IOCFR51 & 73 & Reg Guide 1 105 re instrument setpoints for safety-related sys STELLO, V Regional Operations & Generic Requirements 83/12/19 MATTSON.R J Office of Nuclear Reactor Regulation, Director JORDAN.E L Director's Office, Office of Inspection and Enforcement CUNNINGHAM.R E Office of Nuclear Material Safety & Safeguards, Director 2pp 22675 218
- 8403220138 Forwards revised schedule for supplying info re emergency response capabilities requested by Generic Ltr 82-33, per 840223 telcon Reg Guide i 97 rept will be completed by 850228

 REEY.H L Public Service Co of Colorado QL-82-33 84/03/09 COLLIN.J T Region 4. Office of Director 3pp 22714'285. 24X Fiche 50-267.84/03/09.8403220138
- 8403280024 Forwards MA McDuffie 840216 response to 830119 request for additional antitrust info to continue review of OL application. Per Reg Guide 9 3 Recipient inadvertently omitted from list ZIMMERMAN, 8 R Carolina Power & Light Co NL8-84-128 84/03/19 VOOLER, B NRC No Detailed Affiliation Given 1p 22777:087 24X Fiche 50-400,84/03/19,8403280024
- B4092B0241 Questions requirements of Reg Quide 1.97 to insure instrumentation to follow course of accident including severe accidents Qualification requirements do not include anything beyond DBA CATTON. I California. Univ of, Los Angeles, CA CATTON, I. ACRB Advisory Committee on Reactor Bafeguards B4/02/17 CAPUCCI, A J ACRB Advisory Committee on Reactor Bafeguards 1p 22808 209
- 8403280308 Summary of ACRS Subcommittee on Human Factors 831130 meeting w/Mestinghouse.BNL.Interlock Group & DOE in Hashington.DC re proposed revs to Reg Guides 1.149.1 8.1 134 & 1 114 & proposed mod to 10CFR30.App A ACRS Advisory Committee on Reactor Safeguards 84/02/24 ACRS Advisory Committee on Reactor Safeguards 33pp 22808:097
- 8403270002 Final response to FOIA request for four categories of documents, tests, studies & analyses referencing or pertaining to NUREQ-0103, "STS for B&H PHR" App A documents encl FELTON, J M Division of Rules and Records 84/01/13 MADDEN, T J. Kaye, Scholer, Fierman, Hays & Handler opp 22816 127. 24X Fiche 50-000,84/01/13,8403270002
- --BA03290054 Notice of issuance & availability of six reg guides, including Reg Ovides 1 43 re stainless steel weld cladding of low alloy steel components & 1 44 re control & use of sensitized stainless steel RODERS.L Atomic Energy Commission Directorate of Regulatory Standards 73/05/18 5pp 22816 314
- --8403290009 Discusses Reg Guide : 45 re RCPB leakage detection sys & rept on leakage observed at plant in Germany.
 PORSE, L. Atomic Energy Commission Directorate of Regulatory Standards 73/05/17 MURLEY.T E Atomic Energy Commission. 1p. 22817 009
- --8403290034 Discusses Reg Guide 1 45. ISA draft Std 867 03 & ANSI draft Std N 41 21 Suggested items clarifying reg guide listed MCGUEEN, M N Affiliation Not Assigned 79/07/23 Atomic Energy Commission - Directorate of Regulatory Standards 15pp 32817 039
- --B403290036 Discusses ray to Reg Quide 1 45 re RCPB leakage detection sys PORBE, L NRC - No Detailed Affiliation Given 79/02/26. ANDERBON. F NRC - No Detailed Affiliation Given 4pp. 22817-054
- --8403290040 Discusses Rev 1 to Reg Ouide 1 45. "RCP8 Leak Detection Sys " Decision to revise reg guide not ust made. PORSE.L Atomic Energy Commission - Directorate of Regulatory Standards 74/L0/07 Atomic Energy Commission - Directorate of Regulatory Standards 1p 22816 302
- --8403290055 Comments on Reg Quide 1 45,RCPB leakage detection sys Editorial changes suggested KEELLEY.0 S. Consumers Power Co. KEEL 115-73 73/07/18. Atomic Energy Commission ip 22818 237

---8403270059 Comments on Reg Quide 1 45, "RCPB Leakage Detection Sys "
Calibr of leakage detection sys during shutdown sufficient
Related info encl
SALVATORI,R Westinghouse Electric Corp NB-RG-112 73/12/12
MUNTZING,L M Atomic Energy Commission - Directorate of Regulatory
Standards 23pp 22818 238

RESEARCH AND TECHNICAL ASSISTANCE REPORTS

- 8403050227 "Radionuclide Release Under Specific LWR Accident Conditions," Vol III, "Mark III Design" @IESEKE.J A , CYBULSKIS.P , DENNING.R S Battelle Memorial Institute, Columbus Laboratories 84/02/27 Office of Nuclear Regulatory Research, Director 104pp 22528-007
- 8403050230 "Radionuclide Ralease Under Specific LWR Accident Conditions," Vol V. "PWR-Large, Dry Containment (Surry Recalculations)"

 GIESEKE, J.A., CYBULSKIS, P., DENNING, R.S. Battelle Memorial Institute, Columbus Laboratories 84/01/12 Office of Nuclear Regulatory Research, Director 212pp 22502 001 24X Fiche 50-280,84/01/12,8403050230
- 8403050242 "Radionuclide Release Under Specific LWR Accident Conditions," Vol II, "BWR.Mark I Design " GIESEKE.J A., CYBULBKIB.F. , DENNING.R S Battelle Memorial Institute, Columbus Laboratories. 84/02/29 Defice of Nuclear Regulatory Research, Director 222pp 22503 079
- 8403120255 "Generic Study of Recycle of Contaminated Matis," monthly progress rept for Jan 1984 O'DONNELL, FR Oak Ridge National Laboratory FIN 8-0824. NRC-50-10-01-05 84/02/15 SOUBERO, DE Transportation & Materials Risk Branch. 4pp. 22615 338
- B403120257 "Severe Accident Research Program," quarterly rept for Feb 1984, * Battelle Memorial Institute, Columbus Laboratories B4/02/29 NRC - No Detailed Affiliation Given Sipp 22619 156
- 8403180175 RIL-139
 Research Info Ltr 139 provides appraisal of U dioxide fuel oxidation phenomena & potential impacts on transportation of irradiated power reactor fuel assemblies Potential for occupational exposures during unloading major impact MINGOUE, R.B. Office of Nuclear Regulatory Research, Director 84/03/05, DAVIG.J.O. Office of Nuclear Material Safety & Bafeguards, Director. 31pp. 22646 311
- B403270329 "FRAP-T6 Calculations for Intl Btd Program 14 " WAGDNER, S. R., LAATS, E. T. EG&C, Inc. FIN A-6046 EQC-BAAM-6499 B3/12/G1 NRC - No Datailed Affiliation Olven 30pp. 22788 333
- 8403300120 Procedure "Chemtron Users Manual " MILLER, C. W. Lawrence Berkeley Laboratory FIN 8-3040 LBL-16152 83/03/31 Division of Health, Biting & Waste Management 150pp 22822:274

REVIEW ORP NRC REBEARCH REVIEW GROUPS

- 8312070358 Notification of CROR Meeting 51 on 831123 to review exemption from CROR review of Unresolved Sefety Issue A-1 "Water Hammer" & proposed rev to Reg Guide 1 28, "GA Program Reguli-memnts (Design & Gonst)"

 STELLO, V Committee to Review Generic Requirements 83/11/10 MATISON.R.J Office of Nuclear Reactor Regulation, Director JORDAN.E.L Director's Office, Office of Inspection and Enforcement CUNNINGNAM,R E Office of Nuclear Material Safety & Safeguards, Director 2pp 22681 352
- B403010109 Forwards revised CROR charter, Rev reflects Commission directions contained in 840106 memo DIRCKS, W. J. Office of the Executive Director for Operations 84/02/24. PALLADINO, GILINSKY, ROBERTS Commissioners 16pp 22436:063
- B403010329 Forwards Rev 1 to CROR charter dtd B40131, DIRCKS,H.J. Office of the Executive Director for Operations B4/02/24. DENTON,H R, DAVIS,J G, DEYDUNG,R.C NRC - No Detailed Affiliation Given. 3pp 22432:054
- ---8403010334 Rev 1 of CROR charter # Committee to Review Generic Requirements 84/01/06. 14pp 22432:059.

- B4030A0323 Notification of CROR Meeting 58 on B40315 to discuss proposed NURGO-0801. "Evaluation Criteria for Detailed Control Roam Design Review " Requests of directors limit attendance of staff at CROR meetings STELLO, V Committee to Review Generic Requirements B4/03/02 MATTSON, R J Office of Nuclear Reactor Regulation, Director JORDAN, E L Director's Office, Office of Inspection and Enforcement CUNNINGHAM, R E Office of Nuclear Material Safety & Safeguards, Director 1p 22513 335
- B403170003 Notifies of CRGR Meeting 45 on B30B17 to discuss results of NRR study of electromagnetic pulse & proposed exemptions from regulations in implementation of Multi-Plant Action D-10 (Unresolved Issue A-2) STELLO.V Committee to Review Generic Requirements B3/0B/04 MATTSON.R J Division of Systems Integration (post 811005) JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) CUNNINGHAM.R E Office of Nuclear Material Safety & Safeguards, Director 3pp 22664 347
- B403170005 Notifies of CRGR Meeting 47 on B31024 in Bethesda, MD to discuss proposed requirements for reinsp of BMR piping & repair of cracked piping STELLO, V Committee to Review Generic Requirements B3/10/17 MATTSON, R J Office of Nuclear Reactor Regulation, Director JORDAN, E Director's Office, Office of Inspection and Enforcement CUNNINGHAM, R E. Office of Nuclear Material Bafety & Safeguards, Director 2pp 22664 350
- 8403190008 Submits mod to agenda for CROR Meeting 45 on 830817 in Buthesda. MD to discuss NUREG-0737. Suppl 1 control room design review & NRR study of electromagnetic pulse 8TELLO, V Committee to Review Generic Requirements 83/08/15 HATTSON, R J Division of Systems Integration (post 811005) JORDAN, E L Director's Office, Office of Inspection and Enforcement CUNNINGHAM, R E Office of Nuclear Material Safety & Safeguards, Director 2pp 22644 361.
- 8403190009 Notifies of CRGR Meeting 58 on 840315 to discuss proposed NUREO-0801, "Evaluation Critoria for Detailed Control Room Design Review "
 STELLD, V Committee to Review Generic Requirements 84/03/02 MATTSDN, R J Division of Systems Integration (post 811005) JORDAN, E L Director's Diffice, Office of Inspection and Enforcement CUNNINGHAM, R E Office of Nuclear Material Safety & Bafeguards, Director 1p. 22665:352
- 8403190012 Notifies that CROR Meeting 52 on 831209 in Dethesda, MD rescheduled for 831207 Mod to agenda discussed STELLD, V Committee to Review Generic Requirements 83/11/25 MATTSON, R J Office of Nuclear Reactor Regulation, Director JORDAN, E L. Director's Office, Office of Inspection and Enforcement CUNNINGHAM, R Office of Nuclear Material Safety & Safeguards, Director 2pp 22665 335
- 8403190019 Notifies of CRGR Meeting 56 on 840203 to discuss evaluation & conclusions re need for PDRVs for C-E plants STELLO.V Committee to Review Generic Requirements 84/01/23 MATTSON, R J Division of Bystems Integration (post 811005) JURDAN.E L. Director's Office, Office of Inspection and Enforcement CUNNINGHAM. R E Office of Nuclear Material Safety & Safeguards.Director. 1p. 22666 052
- 840319029 Notifies of CROR Meeting 57 on 840213 to discuss proposed NUREO-0801, "Evaluation Criteria for Detailed Control Room Design Review" & NUREO-0835, "Human Factors Review Quidelines for Safety Parameter Display 8ys "STELLO,V Committee to Review Generic Requirements 84/02/07 MATTSIN, R J Division of Systems Integration (post 811005) JURDAN, E L Director's Office, Office of Inspection and Enforcement CUNNINGHAM, R E Office of Nuclear Material Safety & Safeguards, Director 1p. 22665, 362
- B403170031 Notifies of CRGR Meeting 44 on B30802 in Bethesda.MD to discuss NUREG-0978, re behavior of BWR Mark III containment & commission paper re integrated safety assessment program BTELLO, V Committee to Review Generic Requirements B3/07/22 MATTBON.R J Division of Systems Integration (post B11005) JURDAN.E L Director's Office. Office of Inspection and Enforcement CUNNINGHAM.R E Division of Fuel Cycle & Material Safety 2pp P2666 113
- B403170037 Notifies of CROR Meeting 43 on B30727 in Bethesda,MD to discuss Unresolved Safety Issue A-12, "Steam Generator & Reactor Goolant Pump Support Toughness" & Generic Issue B-36 re diesel generator requirements
 STELLO,V Committee to Review Generic Requirements 83/07/18
 MATTSON,R J. Division of Bystems Integration (post 81005)
 JURDAN,E L. Director's Office, Office of Inspection and Enforcement CUNNINGHAM,R.E. Division of Fuel Cycle & Material Safety 2pp 22665 233

840319008: Notifies of CRQR Meeting 59 on 840328 in Bethesda,MD to discuss proposed resolution of Unresolved Safety Issue A-44 re station blackout & Generic Issue B-56 re diesel generator reliability STELLO.V Committee to Review Generic Requirements 84/03/14. MATTSON.R J Office of Nuclear Reactor Regulation. Director JORDAN,E L Director's Défice, Office of Inspection and Enforcement CUNNINGHAM.R E Office of Nuclear Material Safety & Safeguards.Director 1p 22669 362

8403190103 Notifies of CRGR Meeting 60 on B40411 to discuss activities of NRC Piping Review Committee & proposed resolution of Generic Issue A-30. "Adequacy of Safety-Related BC Power Supply "
STELLD,V Committee to Review Generic Requirements 84/03/14. MATIBON.R J Office of Nuclear Reactor Regulation, Director JURDAN,E L Director's Office, Office of Inspection and Enforcement CUNNINGHAM.R E Office of Nuclear Material Safety & Safeguards, Director 2pp 22669 310

8403190146 Notifies of CRGR Meeting 47 on B30923 in Bethesda.MD to discuss proposed exemptions to regulations in implementation of Multi-Plant Action D-10 (Unresolved Safety Issue A-2) & Rev 2 to Reg Quide 1 105
STELLD.V Committee to Review Generic Requirements B3/09/15
MATTBON.R J Office of Nuclear Reactor Regulation, Director JGRDAN,E L Director's Office, Office of Inspection and Enforcement CUNNINGHAM.R E Office of Nuclear Material Safety & Safeguards, Director 2pp 22666 359

B403190176 Notifies of CROR Meeting 48 on 831020 in Bethesda,MD to discuss exemption of Category 2 personnel from 10CFR30.55a. "Cades & Stds," proposed rulemaking & proposed rev to Reg Guide 1 105
STELLO,V Regional Operations & Generic Requirements 83/10/14
MATTSON.R J Office of Nuclear Reactor Regulation, Director JORDAN.E L Director's Office, Office of Inspection and Enforcement CUNNINOHAM.R E Office of Nuclear Naterial Safety & Safeguards,Director 2pp 22671 163

8403170251 Submits agenda mods for CRGR Maeting 55 on 840125 re proposed IE bulletin on GE HFA relays & NUREG-0801 on criteria for detailed control room design STELLO.V Regional Operations & Generic Requirements B4/01/31 MATTSON,R J Office of Nuclear Reactor Regulation, Director JURDANIE L Director's Office, Office of Inspection and Enforcement CUNNINGHAM,R E Office of Nuclear Material Safety & Safeguards, Director 19 22672 270

--8403190256 Notifies of CRGR Meeting 55 on 840125 in Bethesda.MD to discuss draft IE bulletin, "Failure of GE Type HFA Releys in Use in Class IE Safety Sys," NUREG-0801 & NUREG-0835 STELLO.V Regional Operations & Generic Requirements. 84/01/09 MATTOON.R J Office of Nuclear Reactor Regulation, Director JORDAN.EL Director's Office, Office of Inspection and Enforcement CUNNINOHAM.R E Office of Nuclear Material Safety & Safeguards, Director 2pp 22672 271

8403190260 Notifies of CRGR Meeting 54 on 840118 in Bethesda.MD to discuss Rev 1 to Reg Guide | 89. "Environ Qualification of Electric Equipment Important to Safety for Nuclear Power Plant."

STELLO.V Regional Operations & Generic Requirements | 188-79-018 83/12/27 MATTSON.R J Office of Nuclear Reactor Regulation. Director JORDAN.E L Director's Office. Office of Inspection and Enforcement CUNNINOHAM.R E Office of Nuclear Material Safety & Safeguards.Director | 1p 22672 058

8403190866 Forwards proposed rev to 10CFR72. "Licensing Requirements for Storage of Spent Fuel in ISF81." for review comment & recommendations CAO should participate in review for listed items W/o encl
SNEZEK, J H Regional Operations & Generic Requirements 84/01/12
TRINER.E G Division of Budget & Analysis 19 22672 225

8403190372 Notifies of CROR Meeting 53 on 840111 in Bethesda, MD to discuss revs to 10CFR51 & 73 & Reg Guide I 105 re instrument setpoints for safety-related sys STELLG, V Regional Operations & Generic Requirements 83/12/19 MATTSON, R J Office of Nuclear Reactor Regulation, Director JORDAN, E L Director's Office, Office of Inspection and Enforcement CUNNINGHAM, R E Office of Nuclear Material Safety & Safeguards, Director 2pp 22475 218

SECY POSITION PAPERS DEFORE THE COMMISSION

8402220050 SECY-84-047
Provides Commission w/draft preliminary document to focus on whether to grant or withhold concurrence in DOE general guidelines for recommendations of sites for nuclear waste repositories
DIRCKS, H. J. Office of the Executive Director for Operations 84/02/09 45pp 22646,183

840:3010277 Responds to FOIA request for SECY-83-288 to be placed in PDR Forwards SECY-83-288 Document also available in PDR FELTON. J M Division of Rules and Records 83/12/16 PEDRO, J NUS Corp 1p 22449 138

---8403010283 Comments on SECY-B3-288 re proposed rule on pressurized thermal shock Proposed rule should address CP applicants in addition to OL applicants & operating reactors Schedule for preparation of plant-specific safety enalyses acceptable ZERBE.J E Office of Policy Evaluations B3/OB/Oi PALLADING, GILINSKY, ROBERTS Commissioners App 22449 222

B403010451 SECY-B3-034
Informs Commission of problems w/emergency diesel generators mfg by Transamerica Delaval. Inc
DJRCKG, W J Office of the Executive Director for Operations
B4/01/25 4pp 2243B 347 24X Fiche 50-000, 84/01/25, 8403010451.

B40302006B Responds to appeal re denial of FOIA request for BECY-B3-454 Forwards document Info partially withheld (ref FOIA Examption 5).
CHILK, S J Office of the Secretary of the Commission 84/02/15 SEEGAL.J Union of Concerned Scientists 2pp 22475.009

--B403020094 BECY-B3-454
Approves release of substantive info in Chairmans logs, calendars & notes.per UCS request info deleted & withheld, FITZOERALD. J.A. Office of the General Counsel B3/11/04 2pp. 22495 011

8403060469 Responds to appeal re-denial of FOIA request for SECY-B2-340 Document placed in PDR FELTON.J M Division of Rules and Records 84/02/17 HICKEY, J P. Bhaw Pittman, Fotts & Troubridge ip 22552 036

--8209200364 SECY-82-340
Informs of procedures to process board notifications involving allegations which may fall within investigative purview of Ofc of Investigations
DIRCAS.W.J. Office of the Executive Director for Operations 82/08/17 7pp 22552 057

8403080041 SECY-84-095
Requests Commission review of proposed issuance of License XU-8586 approving export of natural U to EURATOM countries, to Braunkohle Transport USA
DIRCKB, W J Office of the Executive Director for Operations 84/02/24 15pp 22584 099

B403080436 BECY-84-067A
Provides update to preliminary draft document re DDE general guidelines for recommendation of sites for nuclear waste repositories, dtd B3iilB. to assist Commission in deciding whether to grant or withhold concurrence DIRCK9.W J Office of the Executive Director for Operations B4/02/22 49pp 22646 i34

8403070006 Further response to FOIA request for all 1982 SECY papers to be made available SECY-82-37 & SECY-82-37A placed in PDR FELTON, J M Division of Rules and Records 84/02/22 WEISB, E. R. Union of Concerned Scientists 1p 22591 218

---8203050065 BECY-82-037
Informs of receipt of Executive Branch final draft rept to Congress per Section A01 of Nuclear Non-proliferation Act of 1978 Rept generally accurate No areas warrant formal NRC Lomment DIRCKS, W J Office of the Executive Director for Operations 82/01/29 100pp 22591 220

---8204160230 SECY-82-037A
Informs Commission of receipt of final version of rept to
congress re Section 601 of Nuclear Nonproliferation Act
DIRCKS.W J Office of the Executive Director for Operations,
82/03/29 64pp 22591 317

B403090017 Responds to FOIA request for SECY-B3-445 to be placed in PDR Forwards SECY-B3-445 Document also in PDR FELION.J M Division of Rules and Records B4/02/28 BUCKLEB,R. NUS Corp ip 22592 312

--B403090019 BECY-B3-445
Responds to Commission request for human factors program
plan quarterly repts cited in Chilk B30216 staff
requirements memo
DIRCKS.W J Office of the Executive Director for Operations
B3/10/28 14pp, 22592 313

- 8403140244 Board Notification 84-066 forwards SECY-84-104 re NRC insp of Nuclear Svcs Corp audit of Pullman Power Products at site, including draft IE Insp Rept 50-275/83-37 & 840229 final rept EISENHUT, D 9 Division of Licensing OL 84/03/28 BUCK, J H , MODRE, T 8 , JOHNSON, W R Atomic Safety and Licensing Appeal Panel 3pp. 22747 070 24% Fiche 50-275,84/03/28,8403140244
- --B403200301 Provides info to Commissioners of circumstances surrounding documentation of NRC insp of 1977 Nuclear Svcs Corp audit of Pullman Power Products Co DIRCK8.H J Office of the Executive Director for Operations B4/03/02 124pp 22947 073 24x Fichs 50-275,84/03/28,8403140244

BTATE PROG STATE PROGRAMS

- 8402230176 Forwards revised State of CA nuclear power plant emergency response plan MEDFORD, M Q Southern California Edison Co 84/02/16 EISENHUT, D @ Division of Licensing 383pp 22353 001 24X Fiche: 50-000,84/02/16,8402230176
- --8403020117 Revised State of CA nuclear power plant emergency response plan.

 * California: State of 83/04/30 2901pp 22353 003 24X Fiche 50-000:84/02/16:8402230176
- 8403020174 Notifies of upcoming meetings List will be updated weekly TAYLOR, T. J. Environmental Protection Agency 84/02/17 MILLER, H. NRC No Detailed Affiliation Given ip 22491 090
- 8403020206 Requests list of waste mgt documents from 831014 to present re Nevada Test Site project & info concerning process by which future documents can be received JOHNSON.C A Nevada, Blate of. 84/02/03 RUSSELL.C F Division of Waste Management. 27pp 22494 333
- B403020332 Forwards H Sheely B30210 ltr containing State of EC comments on Chem-Nuclear topical rept, "Polyethylene High Integrity Containers"

 NUBSBAUMER, D A Assistant Director for State Agreements Programs 84/02/16. HigginBOTHAM, L Low-Level Waste & Uranium Recovery Projects Branch. ip R2492, 236
- ---B403020339 Comments on Chem-Nuclear topical rept. "Polyethylene High Integrity Containers." per NRC B31227 & 840123 requests.

 Container acceptable for use at Barnuell site.

 BHEALY.H Q. South Carolina. State of 84/02/10 NUBSBAUMER, D A
 Assistant Director for State Agreements Programs 2pp 22492 239
- 8403050107 Forwards responses to technical comments from NRC review of State of NH U licensing program per 831216 ltr Addl personnel unavailable for U licensing & licensing & registration sections due to budgetary restrictions BUHLJT New Hexico, State of 8 84/02/15, COLLINS, J.T. Region 4, Office of Director 14pp 22488 045
- B403050196 Requests to be notified if W0 Bell will continue to be state liaison officer or if new liaison officer will be appointed PALLADINO,N J Commissioners, 84/02/22 ALAIN,H.A Mississippi, State of 2pp .22028-185
- 8403030362 Forwards responses to 831108 quastions for inclusion in record of 830906 hearing re Southeast Interstate Low Level Radwaste Mgt Compact PALLADINO, N. J Commissioners, 84/02/08, THURMOND, S Senate, Judiciary 16pp 22519 267.
- 8403050379 Requests to be notified if RL Banders will continue as state liaison officer or if new liaison will be appointed. PALLADING, N J Commissioners. 84/02/22 COLLINS, M L. Kentucky, Commonwealth of.. 2pp 22527.256.
- 8403070029 Notification of grant execution, Mod 2.to "Investigation of Recent Crustal Movements in State of ME." Grantee State of ME. UMBEL, D. Technical Assistance Contracts Branch FIN G-1041. NRC-0-04-82-009, 84/02/27, BATSON, W. Office of Nuclear Regulatory Research, Director, SCHMITT, T NRC No Detailed Affiliation Given. ip. 22569 194
- --B403070032 Mod 2, providing add1 funding, to "Investigation of Recent Crustal Movements in State of ME." ANDERBON, R. B., ANDERBON, W. A. Maine, State of. MORTON, K. V. Technical Assistance Contracts Branch. FIN 9-1041 NRC-0-04-82-009 84/02/27 lp. 22363, 195.

- 8403070087 State of MO nuclear accident plan * Missouri. State of 83/05/31 400pp 22540 070 24X Fiche 50-483,83/05/31,8403070087
- 840308001& Further response to FQIA request for lists & records re Co-60 licensees Forwards App A documents, per Item 3 of request Portions of Documents 2 through 5 of App B deleted (ref FQIA Exemptions 6 & 7) FELTON, J M Division of Rules and Records 84/01/11 COHIE, D J Bouck, Holloway, Kiernan & Casey 5pp 22576 274
- ---8403080170 PNA-81-006 on 810714, Louisiana Nuclear Energy Div notified NRC of radiography incident occurring on barge located less than 3 miles offshore Barge captain & radiographer exposed to 11 Ci Co-60 Medical attention obtained.

 DDDA-R J Region 4, Dallas, Office of the Director (81/03/01) 81/07/21 2pp. 22377 130
- 84030800AB Further response to FOIA request for documents re Lixi.Inc. Lixiscope of America.Inc & SA Huber Consultants.Inc Forwards App 8 documents Documents also available in PDR FELTON.J M Division of Rules and Records 84/01/17 CAULK.C H Radiation Service Organization. 2pp 22584.001
- --8403080117 Forwards to Agreement States, proposed rule establishing ne category to Group VI of 10CFR35 10O for I-125 as sealed source in portable device for bone imaging & foreign bady detection Change permits use of Lixiscope. H/a enci NUSSBAUMER, D A Assistant Director for State Agreements Programs 83/04/07 Affiliation Not Assigned Ip. 22884 014.
- --8403080128 Forwards, to Agreement States, ltr to Lixi re demonstration industrial training in use of Lixistope device Ltr requests clarifying info.not final licensing action. W/o encl NUSSIAUMER, D.A. Assistant Director for State Agreements Programs 83/06/28 Affiliation Not Assigned 19. 22584-015
- --B40308D13B Forwards NMSS policy to Agreement States re licensing huma use of Liviscope & bone matl analyser. Byproduct matl authorized for human use by nonphysicians (podiatrists & dentists) NUSSBAUMER, D. A. Assistant Director for Btate Agreements Programs 83/11/18 Affiliation Not Assigned ip 22584-016
- --B403080181 Requests info re Liriscope licensing concerning number of hours & which topics to be covered in training of physicians not meeting Group VI critaria
 NUSBRAUMER, D.A. Assistant Director for State Agreements Programs
 83/09/09 MILLER, V.L. Division of Fuel Cycle & Material Safety
 1p. 22584-040
- --8403080098 Ack receipt of 830222 ltr re State of NV reciprocity agreement BOLLING.L A Office of State Programs, Director 83/03/03 SAVINI.R J. LIXI, Inc. lp 22584:013.
- B40312024B Responds to request for technical assistance in evaluating Nuclear Packaging. Inc FL50 high integrity container (HIC). HIC design can be approved for continued use provided vendor submits further info.

 NUBSEAUMER.D. Assistant Director for State Agreements Programs 84/02/27 STRONO.T R. Washington. State of Dept of Social & Health Services 3pp 22618 357.
- 8403150125 Discusses IE insp on 831220-21 & forwards notice of violation MARTIN.T T Division of Engineering & Technical Programs 84/02/28, EISENBUD, M. New York Univ Medical Center, New York, NY 2pp. 22640-317 24X Fiche 50-320,84/02/28,8403150125
- --B403150132 Notice of violation from insp on 831220-21. Violation noted 5.8 mCi Ce-144 squrce transported to & possessed at facility not authorized by specific or general license * Region i, Office of Director. 84/02/28 ip. 22440 319 24X Fiche 50-320,84/02/28,8403150125
- 8403150221 Forwards study of soil samples collected during drilling of well located 100 ft south of Beatty sits Requests any comments on study be submitted to State of NV NUSSBAUMER, D. A. Assistant Director for State Agreements Programs 84/03/07 HIOGINBOTHAM, L. Low Level Waste Licensing Branch 1p 22648, 287.
- --8403150222 Forwards study made on soil samples collected during drilling of wall 100 ft south of Beatty site. According to date, sorption of selected ions decreases below 290 ft. VADEN, J. Nevada, State of. 84/02/21. NUBERAUMER, D.A. Assistant Director for State Agreements Programs ip 22648 288

- B403190065 Forwards State of NC & Chatham, Harnett, Les & Wake Counties amorgency response plan Plan forwarded to ASLAB for use in hearings by separate itr dtd B4022B MCDUFFIE.M A Caroline Power & Light Co NLS-B4-104 B4/03/12 DENION H & Office of Nuclear Reactor Regulation, Director 1p 22663 130 24X Fiche 50-400, 04/03/12, 8403190065
- --8403190067 Emergency response plan # North Carolina, State of 84/02/29 454pp 22663 131 24X Fiche 50-400,84/03/12,8403190065
- 8403190420 Reviews responses to NRC comments on high integrity container design for TMI EPICOR-II prefilter wastes Approval of design recommended following resolution of listed comments

 NUSSBAUMER, D A Assistant Director for State Agreements Programs

 84/02/01 KIRNER, N Washington, State of 2pp 22681,342
- 8403190447 Forwards trip rept of 840130-0203 visit to Golden & Fort Collins, CO to attend NRC Agreement States meeting, quarterly meeting of UMIRAP participants & sixth symposium on mgt of U tailings, low level waste & hazardous waste WEDER, M F Geotechnical Branch (Post 831001) 84/02/15 KNAPP, M R Geotechnical Branch (Post 831001) 60pp 22679-297
- 8403210133 PNO-II-84-023 on 840312. State of 8C advised of possible overexposure of radiographer & assistant radiographer Caused by assistant radiographer performing duties as radiographer Exposures of 5.000 to 10.000 rem possible TROJANOMSKI.R., Woodpruff, R. L. Region 2, Office of Director. 84/03/16 2pp 22707 236
- 8403230188 List of State of WA Dept of Ecology high level nuclear waste mpt legislative proposals.as of 840302 ** Washington, State of 00695 84/03/02 2pp 22759 119
- 8403230190 NUREG-1015 STAYE SURVEILLANCE OF RADIOACTIVE MATERIAL TRANSPORTATION Finel Report SALDMON.S N Office of State Programs, Director 84/02/29 72pp Available at NRC \$4 50 22759 048
- 8403230250 Bummary of State of WA High Level Nuclear Waste Advisory Council 840120 meeting w/listed attendees re forthcoming public info program w/Ofc of High Level Nuclear Waste Mgt * Washington, State of 00686 84/01/20 Washington, State of, 35pp 22739 327
- B403260203 Advises that proposed license amend re spent fuel storage expansion submitted on 840314 forwarded to state designee for State of FL, in accordance w/iOCFR50 91(b)(1) WILLIAMS, J W Florida Power & Light Co L-84-74 84/03/16 EISCHHUT, D O Division of Licensing ip 22756 209 24X Fiche: 50-230, 84/03/16, 8403260203
- 8403260280 NUREG/BR-0025 V10 N2 INFORMATION REPORT ON STATE LEGISLATION LANDAU.M Office of State Programs, Director 84/03/10 9pp 22761 307
- B403270286 Notification of contract execution.Mod 1, to "Radiation Monitoring Program Requirements" Contractor State of ME. UMBEL.O Technical Assistance Contracts Branch FIN B-8357. NRC-28-83-603 84/03/07 MCGSCAR.J Office of Resource Management, Director KOTTAN.J NRC No Detailed Affiliation Given ip 22789.252
- ---B403270290 Mod i,providing funds for CYB4 & changing B&R number & NRC authorized representative, to "Radiation Monitoring Program Requirements" * Maine. State of SMITH,P A Division of Contracts FIN B-B357 NRC-28-83-603 84/03/07 ip 22789 253.
- 8403280221 Requests response to author 840201 ltr re sources of funding in 1984 for cleanup of facility Svc list encl
 SALTZMAN, J Assistant Director for State & Licenses Relations 84/03/12 GRAMM, J Q General Public Utilities GPU Service Corp
 2pp 22789.344 24X Fiche 50-320,84/03/12,8403280221
- 8400280254 Forwards draft itr incorporating conclusions & recommendation re technical assistance to State Of WA on NUPAC high integrity container design Add1 into required recorrosion performance of F255 welds & pitting corrosion H1601NBOTHAM-L Low-Level Waste & Uranium Recovery Projects Branch 84/02/16. NUSSAUMER, D Assistant Director for State Agreements Proprams 7pp 22808 182

- 84032903i6 Comments on petition for rulemaking re DDE general guidelines for recommendation of sites for nuclear waste repositories NRC concurrence decision offers some improvement to DDE guidelines KALITUMEKI.T Minnesota, State of 49FR9450 006 84/03/20, PALLADING, N S Commissioners 3pp 22802 062
- B403300112 PNO-II-B4-024 on B40326. State of TN informed Region II that state licenses. Quadrex Co. suspected as source of sewer line contamination detected by DDE State investigation underway. TROUANGHERIR Region 2. Office of Director. 84/03/27 Ip 20801 230
- TOPREP VENDOR REPORTS AND RELATED CORRESPONDENCE
- 8305190492 Forwards technical review rapt on undetectable failure in Westinghouse solid-state protection sys. CHIRAMAL M Reactor Operations Analysis Branch. AEOD/T308, 83/04/20 SEYFRIT.K V Reactor Operations Analysis Branch ip 22789 285
- ---B305190497 AEDD/T308

 "Undetectable Failure in Westinghouse Solid State Protection
 Bys (SSP8)." technical review rept
 CHIRAMAL M Reactor Operations Analysis Branch, 83/04/20, 6pp
- 8401120525 Forwards nonproprietary version of topical rept, "
 "Title 10CFR61, Waste Form Certification Cement."
 STAEHR.JP., POPPE, LK Chem-Nuclear Bystems. Inc., 83/11/30,
 JOHNSON.T NRC No Debailed Affiliation Given. 1p. 21803:111
- --8401120550 CNSI-WF-C-01-NP
 Nonproprietary version of "Title 10CFR61, Waste Form
 Certification Cement."

 * Chem-Nuclear Systems, Inc 83/11/30 105pp 21803:113
- 8401130363 Comments on proposed new SRP 5 3 4 re fracture toughness of steam generator & reactor coolant supports No addl regulatory guidance necessary CAHN.A L. Bechtel Corp. 64/01/07 DENTON.H R. Office of Nuclear Reactor Regulation, Director 2pp 21799 360.
- 8401190217 Notification of rescheduled 840130 meeting w/Hestinghouse in Bethesda: MD to discuss nine topical repts to be published in CY84 re BHR fuel reloads Meeting originally scheduled on 840113 MORAN. D H Standardization & Special Projects Branch. 83/12/22, THOMAS. C O Standardization & Special Projects Branch. 1p 21870-2288
- 8402070020 Board Notification 84-044 forwards Part 21 rept re Transamerica Delaval Inc turbocharger thrust bearing lubrication defect resulting in angine nonavailability. EIBENHUIS D. Division of Licensing 84/02/29 PALLADIND Commissioners 4pp. 22541 263 24X Fichs 50-000,84/02/27, 8402090020
- 8402070021 Board Notification 84-039 discusses NRC 840210 & 16 meetings w/Transamerica Delaval. Inc Emergency Diesel Generators Duners Group Meeting scheduled on 840308 for finalization of generic program plan prior to NRC review.

 EIBENHUT, D @ Division of Licensing. 84/02/28 PALLADIND Commissioners 5pp 22546,003 24x Fiche: 50-000,84/02/28, 840020021
- 8402090033 Board Notification 84-047: forwards Transamerica Delaval, Inc Owners Group piston skirt rept & task descriptions EISENHUT, D @ Division of Licensing, 84/03/07 PALLADINO Commissioners 4pp. 22674, 221. 24X Fiche: 50-000, 84/03/07, 8402090033.
- 8402070035 Board Notification 84-053 forwards "Emergency Diesel Generator Component Tracking Sys," facility component data base for design review & quality revalidation effort of Transamerica Delaval Owners Group program plan, EISEMHUT,D © Division of Licensing, 84/03/12 PALLADINO, OILINEXY, RUBERTS Commissioners, 4pp. 67218:079, 24X Fiche: 50-322, 84/03/12, 8402090035
- --8403190385 "Emergency Diesel Generator Component Tracking Sys "
 * TDI (Transamerica Delayal, Inc.) Gunera Group. 84/02/29,
 515pp 22675-322. 24% Fiche: 50-322, 84/03/12, 8402090035.
- 8402090038 Board Notification 84-051 forwards "Transamerica Delaval, Inc (TDI) Diessl Generators Owners Group Program Flan, " EISENHUT, D Q Division of Licensing. 84/03/12 PALLADIND Commissioners 5pp 22688, 214 24X Ficha 50-000, 84/03/12, 8402090038

- 8402090039 Board Notification 84-052 forwards meeting summaries containing transcripts of 840210 & 16 meetings between NRC & Transamerica Delaval, Inc (TDI) Owners Group Distribution list encl
 - EIBENHUT, D 9 Division of Licensing 84/03/12 PALLADINO Commissioners 5pp 22708 001 24% Fiche 50-000,84/03/12,8402090039
- ~-8403060536 Forwards summary of 840210 meeting w/Transamerica Delaval.
 Inc Owners Group in Bethesda.MD re problems w/emergency
 dissel generators
 CARUSO.R Licensing Branch 2 84/02/27 O'REILLY.J.P NRC No
 Detailed Affiliation Given App 22708 006 24X ,
 Fiche 50-000.84/03/12.8402090039
- --B403060584 Transcript of B40210 meeting w/Transamerica Delaval, Inc Owners Group in Bethesda, Mb re problems w/emergency diesel generators * NRC - No Detailed Affiliation Given 84/02/10 147pp 67201 008 24X Ficher 50-000, 84/03/12,8402090039
- ~-8403070409 Summary of 840R16 meeting w/Transamerica Delaval, Inc Owners Oroup in Wading River, NY re program plan to establish reliability of diesel generators Agenda, meeting transcript & attendance list encl
 MILLER, M.A. Licensing Branch 4 84/02/27 Licensing Branch 4 8pp 22708-161 24X Fiche 50-000,84/03/12,8402090039
- --8403070423 Transcript of 840216 conference in Wading River, NY re Transamerica Delaval.inc diesel generators Pp 1-82 * Commissioners 84/02/16 84pp 22708 169 24x Fiche. 30-000, 84/03/12, 8402099039
- 8402100259 Forwards proprietary "Probability of Missile Generation in GE Nuclear Turbines." per 830428 commitment Rept will be presented at 840207 mesting in Bethesda.MD Affidavit encl Rept withheld (ref 10CFR2, 790)
 TIMO.D P General Electric Co 84/02/06 IPPOLITO.T A Operating Reactors Branch 2 9pp 22181 266
- B403010105 Summary of 820209 meeting w/Westinghouse & Wastinghouse
 Owners Group re generic emergency operating procedure
 technical guidelines Viewgraphs encl
 CLAYTON:H B Procedures & Systems Review Branch B2/02/24
 ZIEMANN:D L. Procedures & Systems Review Branch 36pp 22479 301
- 8403010115 Forwards revs to organization for GA dept,reflecting listed changes KELLY.R B Stone & Webster Engineering Corp 84/02/10 POTAPOVS.U Vendor Program Branch. App 22436 022
- B403010207 Forwards "Investigation of Types AF & AE Piston Skirts," per Transamerica Delawal, Inc Gumers Group program commitments Rept evaluates cracks in AF piston skirts in Shoreham & Grand Gulf Nuclear Power Stations MUSELER, W. J. TDI (Transamerica Delawal, Inc.) Gumers Group IDI-2 84/02/27, DENTON, H. R. Diffits of Nuclear Reactor Regulation, Director. 3pp 22434.090. 24X Fiche. 50-000.84/02/27, 8403010207
- ---B403010446 FAAA-B4-2-14
 "Investigation of Types AF & AE Piston Skirts"
 * Failure Analysis Associates. FME-R-6/7376 84/02/27. 83pp.
 22434'093 24X Fiche: 50-000, 84/02/27, 8403010207.
- B40301021B Forwards task descriptions for 16 known problems re Transamerica Delaval, Inc emergency diesel generators, MUSELER.W J TDI (Transamerica Delaval, Inc.) Guners Group TDI-1 84/02/28, DENTON, H R Office of Nuclear Reactor Regulation, Director 42pp. 22435,177 24X Fichs.50-600,84/02/28,8403010218
- 8403010306 Application for amend to Licenses DPR-33, DPR-52 & DPR-68, changing Tech Specs to lower Group i isolation setpoint for reactor lower mater level W/proprietery NEDE-30012, "...MSIV Hater Level ... "Rept withheld (ref 10CFR2 790) MILLS, L.M. Tennesses Valley Authority. TVA BFNP TS 196. 84/02/22 DENTON, NR Office of Nuclear Reactor Regulation, Director, 3pp 22433:042 24X Fiche 50-259,84/02/22,8403010306.
- 8403010451 SECY-B3-034
 Informs Commission of problems w/emergency diesal generators mfg by Transamerica Deleval.Inc.
 DIRCKS.M.J. Office of the Executive Director for Operations 84/01/25, 4pp 22438:347. 24X Fiche.50-000.84/01/25,8403010481.

- 8403020175 Forwards addl info to complete review of Topical Rept VEP-FRD-41, "VEPCO Reactor Sys Transient Analysis Using RETRAN Computer Code." in response to NRC 1982 informal request STEWART.W L Virginia Electric & Power Co 060 04/02/27 DENTON.H R OPPice of Nuclear Reactor Regulation, Director 16pg 22443 257 24% Fiche 50-000.84/02/27.8403020195
- 8403020226 Requests that CRGR consider merits of NRC position recontainment isolation requirements for post-LOCA hydrogen recombiner lines, per 830908 appeal meeting NRC position extends beyond clarification of intent of BRP 6.24
 HELMIS D R BWR Dwners Group BWR09-8403 84/02/27 DENTON, H R
 Office of Nuclear Reactor Regulation, Director 2pp 22439 215
- 8403020275 Responds to reliability survey questions re diesel generator startup & operation Responses to NRC request for addl info re Transamerica Delaval amengency diesel generators will be submitted by 840801 MEDFORD.M D Southern California Edison Co 84/02/29 CRUICHFIELD.D Operating Reactors Branch 5 Spg 22440.074 24X Fiche 50-206,84/02/29,8403020275
- 8403020406 Advises that draft "Final Rept on Div 1 & II Transamerica Delaval Inc Diesel Generators," forwarded to NRC on 840216 will be submitted in final form on 840221 HOUSTON: M D Licensing Branch 2 84/02/21. Licensing Branch 2 3pp 22492 104 24X Fithe 50-416.84/02/21.8403020406
- ---B403020410 Draft "Final Rept on Div I & II Transamerica Delaval.Inc Diesel Generators " * Mississippi Power & Light Co 84/02/15 74pp 22492 107 24X Fiche 50-416.84/02/21.8403020406
- 8403050098 Forwards "Rept on Task 05088 Pressurizer Relief Valve Discharge Piping Qualification for Calvert Cliffs, Unit 2," per TMI Item II D 1 LUNDVALL, A E Baltimore Qas & Electric Co 84/02/29 MILLER, J R. Operating Reactors Dranch 3 3pp 22484 167 24X Fiche 50-318,84/02/29,8403050098
- --8403050103 CEN-248(B) RO2 Rev 2 to "Pressurizer Safety Valve Operability Rept " * Combustion Engineering, Inc 84/01/31 50pp 22484 332 24X Fiche 50-318,84/02/29,8403050098
- 8403050215 Notifies of fee due for review of NEBO-24934, "Emergency Procedure Guidelines Rept.Rev 2"
 MILLER.H G License Fee Management Branch GL-83-05 84/02/22 GUIRK.J F. General Electric Co ip 22528 143
- B403050222 Informs of fee due for review of 811130 Westinghouse Owners Group emergency response guidelines rept. MILLER, W.O. License Fee Management Branch 84/02/22 RAHE, E.P. Westinghouse Electric Carp. 1p. 22527 361
- 8403080225 Advises of fee due for review of CEN-152, "C-E Emergency Procedure Quidelines Rept" MILLER,W O License Fee Management Branch 84/02/22 BCHERER.A E Combustion Engineering, Inc. 1p 22527 360
- 8403060011 Informs that NRR completed review of B&W Owners Group rept on emergency procedures & response guidelines Div of Finance & Accounting will forward bill MILLER, W O Licenes Fee Management Branch 84/02/22 TAYLOR, J H Babcock & Wilcox Co 1p 22928 353
- 8403040147 Advises that NUREO-0737. Action Items II K 3 30 & II K, 3 31 considered complete, based on 840104 telcon between NRC & 0E Licenses need only identify to NRC ref on docket to GE Topical Rept NEOD-20364 or NEOD-20364 P ZIMMERMAN, S. R. Caroline Power & Light Co NLS-84-096 84/02/27 VASSALLO, D B Operating Reactors Branch 2 2pp 22518.334 24% Fiche. 50-324, 84/02/29,8403060167
- 8403040174 Confirms CASE QA program insp at Arizona Public Svc Co in Phoenix.AZ & Aerojet Mfg Co in Bacramento,CA on 830305-07 & O8-07, respectively,per 840216 telcon POTAPOVS,U Vendor Program Branch. 84/02/27 MARSH,R N Florida Power & Light Co ip. 22518:344
- 8403060325 Forwards WCAP-10433, "Determination of Copper Content of Longitudinal Weld Smams in Intermediate Shell Region of Haddam Neck Reactor Vessel," confirming past estimates of copper content & through-wall distribution COUNSIL-W 9. Connecticut Yankee Atomic Power Co Bil040 B4/02/17 CRUTCHFIELD.D Operating Reactors Branch 5. ip 22513 320. 24X Fiche. 50-213, 84/02/17,8403040325

- --B403060326 WCAP-10433 Potermination of Copper Content of Longitudinal Wald Seams in Intermediate Shell Region of Haddam Neck Reactor Vessel "BUGGS.R B. YANICHKO.S E Hestinghouse Electric Corp. 83/11/30-11pp 22513-321 24X Fiche 50-213.84/02/17,8403060325
- B403060338 Advises of problem compromising integrity of design review/ quality revalidation of emergency digsel generators mfg by Transamerica Delaval. Inc Util involvement in review represents conflict of interest BROWN, H. H. Kirkpatrick, Lockhart, Hill, Christopher & Phillips BROWN, H. H. Suffolk County, NY 84703/01 DENTON, H.R. Office of Nuclear Reactor Regulation, Director App. 22519 088 24X Fiche 50-322,84/03/01,8403060338
- 8403040367 Forwards Endorsement 127 to NEL1A Policy NF-34 ASHBURN,D J Marsh & McLennan, Inc. 84/02/28 SALTZMAN, J Assistant Director for State & Licensee Relations 2pp 22511 357
- 8403060375 Forwards Endorsements 62 & 63 to NELIA Policy NF-193 & Endorsement 33 to MARLU Policy MF-94 ASHBURN, D.J. Marsh & McLennan, Inc. 84/02/28 SALTZMAN, J. Assistant Director for State & Licensee Relations. 4pp. 22518,203
- 8403060409 Transmits Rev O to Rept 84-3, "Mark I Wetwell to Trywell Vacuum Breaker Load Methodology," per Mark I/NRC 831215 meeting Afridavit anci Rept withheld PFEFFERLEN.H C General Electric Co MFN-025-84, 84/03/02 VASSALLO.D B Operating Reactors Branch 2 5pp 22518 215
- 8403060453 Discusses deficiencies discovered in Delaval emergency diesel generators Written submittal requested giving details of enhancement program to justify interim operation EISENHUT, D. G. Division of Licensing 84/02/24 RICHARD. J. B. Mississippi Power & Light Co. 4pp. 22550 003 24X Fiche 30-416.84/02/24.8403060453
- 8403070127 Forwards proprietary Rev 1. Amend 1 "Exxon Nuclear Analysis of Power Distribution Measurement Uncertainty for Heatinghouse PHRs "Rept withheld (ref 10CFR2. 790) CMANDLER. J C. Exxon Nuclear Co , Inc. (subs. of Exxon Corp.), 84/02/03 THOMAS. C O Standardization & Special Projects Branch 1p. 22541 360
- 8403080205 Forwards proprietary & nonproprietary info supporting application for Tech Spec changes for Cycle 5 reload Proprietary repts withheld CHANDLER, J.C. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) JCC, 040 84 84/03/02 DENTON, H.R. Diffice of Nuclear Reactor Regulation, Director 5pp 22558 224. 24X Fiche 50-316, 84/03/02, 34000005 8403080205
- ---B4030B0210 XN-NF-B3-B5 B01
 Suppl 1 to "DC Cosk Unit 2, Cycle 5 BAR "
 COPELAND, R A , STOUY, R B , WILLIAMSON, H E . Exxon Nuclear Co . Inc (subs of Exxon Corp). 84/02/23 15pp 22558 227 24X
 Fiche 50-31& 84/03/02.8403080205.
- --B403080216 XN-NF-84-21 (NP)
 NonProprietary "DC Cook Unit 2 Cycle 5 5% Steam Generator
 Tube Plugging Limiting Break LOCA/ECCS Analysis."
 ADES: M. J. BRAUN, D J. FAUBZ, N. F. Exxon Nuclear Co., Inc. (subs
 of Exxon Corp.) 84/03/01 65pp. 22558 244 24%
 Fiche. 50-316.84/03/02:8403080205.
- --8403080220 XN-NF-B3-85 #DC Cost Unit 2.6ycle 5 8AR "
 #DC Cost Unit 2.6ycle 5 8AR "
 #IMPY.P D . SKOGEN,F B . WILLIAMBON.H E Exxon Nuclear Co., Inc
 (subs of Exxon Corp) 83/10/24 34pp 22558 310 24X
 Fiche. 30-316.84/03/02.8403080205
- --B4030B0223 XN-NF-B2-32 (NP) RO2
 Nonproprietary Rev 2 to "Plant Transient Analysis for DC Cook Unit 2 Reactor at 3,425 MHT Operation W/5% Steam Generator Tube Flugging "
 ADAMS.F T , KAYSER,W V , CHANDLER, J. C Exxon Nuclear Co., (subs of Exxon Cop.) B4/03/03 114pp 22558:345, 24X Fiche.50-316,84/03/02,8403080205
- 8403090198 Forwards two ltrs referenced in 830916 ltr.representing entire dialogue w/NRC rs GC breakdown. All future correspondence will be forwarded to IE & will be routed through author ofc.
 KALE.D L. Gulf & Western Industries, Inc. 84/01/17 ANDERSON, W F Director's Office, Office of Inspection and Enforcement. 1p 22574. 273
- 8403090255 Forwards "Analysis of Capsule U From Alabama Power Co JM Farley Unit I Reactor Vessel Radiation Surveillance Program "
- Program "
 .CLAYTON,F.L Alabama Power Co. 84/03/01. VARGA,8 A Office of Nuclear Reactor Regulation, Director 2pp 22568:201 24X
 Fiche: 50-348,84/03/01,8403090255

- HOGOTORDY MCAP-10474

 "Analysis of Capsule U From Alabama Power Co JM Farley Unit
 I Reactor Vessel Radiation Surveillance Program."

 BJ096; R B ; YANICHKO B E ; CHENEY, C A Westinghouse Electric Corp.

 84/02/29 90pp 22568 204 24X Fiche 50-348,84/03/01;

 B403090255 -- 8403070259 WCAP-10474
- 8403070314 Forwards repts re passive containment sys & comments on ALO-137, "Evaluation of Passive Containment Sys," by Sandia Natl Labs
 FALLS.O B NucleDyne Engineering Corp 83/09/30 DENTON, H R
 Office of Nuclear Reactor Regulation, Director THOMAS.C O
 Standardization & Special Projects Branch 3pp 22368.349
- --8403090315 NEC-6 "Passive Containment Sys for Nuclear Power Plant" * NucleDyne Engineering Corp 83/09/30 66pp, 22568 351.
- ~-8403090319 NEC-10 Wesponse to Comments on Passive Containment Sys made at Meeting of ACRS Subcommittee on Fluid Dynamics " * NucleDyna Engineering Corp. 81/05/15. 59pp 22568 352.
- --8403070322 NEC-9 "Response to Comments on Passive Containment Sys made at Meeting of ACRS Subcommittee on Fluid Dynamics" * NucleDyne Engineering Corp 81/01/30 161pp 22567:055.
- --B403090324 "Presentation to ACRS Bubcommittee on Improved Reactor Safety," on 770626
 * NucleDyne Engineering Corp 79/06/26. 33pp 22549-116
- --8403070318 NEC-8 "Passive Containment Sys Overcomes Class 7 Accidents " * NucleDyne Enginearing Corp. 83/09/30 34pp 22569, 216
- ---8403090323 "Bafety Improvements W/Passive Containment Sys."

 * NucleDyne Engineering Corp. 78/06/12 37pp 22569 256
- ---8403090328 Paper entitled "Passive Containment Sys in High Earthquake Motion," presented at 770730-0804 meetings in Sun Valley, ID. KLEIMOLA,F W., FALLS, O. B. NucleDyne Engineering Corp. 77/07/30 18pp 22367 270
- --B403090330 "Accessibility Into Fassive Containment Sys "
 KLEIMOLA, F W., FALLE, D. B., NucleDyne Engineering Corp. B3/09/30
 35pp 22569 327
- --8403090316 "Inservice Insp & Plant Surveillance w/Passive Containment Bys " KLEIMDLA,F W , FALLS,O.B NucleDyne Engineering Corp. 78/01/23 D3pp 22569.345.
- ---8403070321 Spacch entitled "Recommissioning -- an Alternate to Decommissioning," presented at ANS winter meeting in Decommissioning, presented at the willow more more publication. BC HLEIMDLA, F. W., FALLS, O. B. NucleDune Engineering Corp. 78/11/30 28pp 22570.019
- --B403090325 Speech entitled "Passive Containment Sys, New Concept to Bolve Safety Concerns," presented at American Power conference on 790424 in Chicago IL FALLS, O.B., KLEIMDLA, F. W. NucleDyne Engineering Corp. 79/04/24. 33pp. 22570 072
- --8403070327 Spach entitled "ALARA Considerations w/Passive Containment Sys." presented at ANS 830613 annual meeting in Detroit, MI FALLE. 0 B , KLEIMOLA, F. W NucleDyne Engineering Corp. 83/06/13 17pp. 22370:100.
- --8403090329 ALD-137 "Evaluation of Nucledyne Passive Containment Sys," * Gilbert Associates, Inc. * Westinghouse Electric Corp. Bi/04/30, 1ipp. 22570 133,
- ---8403090332 "Eyaluation of Passive Containment Bys Concept as Applied to PMR Nuclear Power Plent." LEININGER,H J, COLEMAN,J H, MERRELL,H H. Ebasco Services, Inc. (subs. of Enserch Corp.) 80/01/25 206pp. 22570:160
- 8403120105 First interim deficiency rept re loose drive hubs on overspred governor drive shaft on Transamerica Delaval, Inc diesels, Initially reported on 840203. Svc info memo being reviewed for approval, Also reportable per Part 21.
 MILLS, L.M. Tennessee Valley Authority, 84/03/01, 0'REILLY, J. P. Region 2, Office of Director 2pp 22585, 229 24X
 Fiche: 50-000, 84/03/01, 8403120105.

1

- 8403120127 Informs of cooperation of BMR Owners Group on intergranular stress corrosion cracking issue & w/EPRI & LLL on NRC-supported studies on double-edged guillotine break CURTIS, N W Pennsylvania Power & Light Co 84/03/06 DENTON.H R. Diffice of Nuclear Reactor Regulation, Director ip 22588 205
- 8403120136 Part 21 rept re Westinghouse Tupo SA-1 DBR or DBRV standby diesel generator differential relay defect Relay problem reported in 840215 Suppl 1 to IE Info Notice 83-63 RTE Delta requested to review defect & recommend correction SOVER, RE Transamerica Delavel, Inc. IEIN-83-63 84/03/07 Director's Office, Office of Inspection and Enforcement 2pp 22585 219 24X Fiche, 50-416, 84/03/07, 8403120136
- 8403120180 Responds to NRC 840214 request for info re Transamerica Delaval diesel engines Response to Items 1 & 2 will be provided within required 30 days Owners group working to develop info to satisfy Items 3.4 & 5 BIXBY, D T Transamerica Delaval, Inc. 84/03/02 EISENHUT, D. & Division of Licensing 2pp 22587 173
- 8403130112 Forwards tentative schedule for responding to NRC questions re Transamerica Delayal diesel generators.per 840131 ltr. Delays or changes in owners group quelification program could change schedule.

 RODRIQUEZ,R.J. Bacramento Municipal Utility District. RJR 84-084
 84/03/05 STOLZ.J.F Operating Reactors Branch 4 3pp 22615-292
 24X Fiche. 50-312.84/03/05.8403130112
- 8403130175 Interim Deficiency Rept DR-163 re set screw over key on drive hub for overspeed governor fuel transfer pump drive in standby diesel generator A supplied by Transamerica Delaval, Inc. Investigation incomplete Next rept by 840430 BOOKER, J. E Gulf States Utilities Co DR-163 84/03/02, COLLINS, J. T. Region 4, Defice of Director. 1p 22615.298, 24X Fiche: 50-458,84/03/02,8403130175
- 8403130237 Interim deficiency & Part 21 repts. Item 159 re flexible coupling drive shaft in overspeed governor & fuel transfer pump drive of standby diesel generator Initially reported on 840206, Final rept will be submitted by 840416 PARSONS: R.M. Carolina Power & Light Co. NRC-190, 84/03/02, 0'RECLLY,J.P. Region 2. Office of Director. 1p. 22617 277 24) Ficher 50-400, 84/03/02, 8403130237
- 8403130277 Forwards proprietary & nonproprietary "Response to NRC Request Number i for Addl Info on C-E Rept CEN-203-NP, Revi-NP, 'Further Response to NRC Action Plan Item II.K 3 30 "Proprietary rept withheld (ref 10CFR2, 790) MELLE, R. W. C-E Operating Plants Owners Group WELLS, R. W. Northeast Utilities. RW-84-12 B4/02/28 THOMAS, C 0 Standardization & Special Projects Branch 2pp. 22404-002
- ---B403130273 CEN-203-NP R01 801
 Rev 1 to Suppl 1 to nonproprietary "Response to NRC Request Number 1 for Add1 Info on C-E Rept CEN-203-NP, Rev 1-NP 'Further Response to NRC Action Plan Item II K 3 30, Justification of Small Break LOCA Methods."

 * Combustion Engineering, Inc B4/02/29 321pp. 22603 246
- 8403130285 Forwards proprietary draft Rev 1 to "GESTR-LOCA & SAFER Models for Evaluation of LOCA," Vol 3, "BAFER/GESTR Application Methodology," Affidavit encl. Rept withheld (ref 10CFR2 790)
 GUIRK.J.F General Electric Co. MFN-023, 84/02/27, THOMAS.C.O Btandardization & Special Projects Branch App. 22614.182,
- B403130342 Forwards justification for interim operation (JID) for listed programs & draft Westinghouse Class 3 topical rapts. Final resolution of issues for listed JIOs expected by 850331. PETRICK, N. A. Btandardized Nuclear Unit Fower Plant System. SLNRC 84-0040, 84/03/06. DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 4pp 22616-149. 24X Fiche: 50-000, 84/03/06.
- ---8403130338 WCAP-8387 R4ESE-13D
 Draft "Equipment Qualification Data Package," Rev 4 to EQDP-ESE-13, "Process Protection Bys."
 RAME, E. P. Westinghouse Electric Corp. EQDP-ESE-13, 83/06/30 22pp. 22616:153, 24X Fiche 50-482,84/03/06,8403130342.
- --8403130375 WCAP-8587 ROESE-47AD
 Draft "Equipment Qualification Data Package," Rev 0 to
 EGDP-ESE-47A, "Boron Dilution Fix Source/Intermediate
 Range Nautron Detector,"
 RAME, E. P. Hestinghouse Electric Corp. EGDP-ESE-47A 83/05/31,
 20pp. 22616;175 24X Fiche:30-482,84/03/06,8403130342.

- --8403130389 MCAP-8587 ROHE-108 D
 Draft "Equipment Qualification Data Package." Rev 0 to
 EGDP-HE-108, "Head Vent Sys Electronic Control Hodule
 (HE-108)"
 RAHE, £ P. Westinghouse Electric Corp EGDP-HE-108 83/10/31
 28pp 22616-195 24X Fiche 50-482,84/03/06,8403130342
- B403140004 Forwards Rev 2 to NEDE-24011-P-A-2, "GE Generic Reload Fuel Application," issued in Jul 1981 W/o encl ENGEL.R E General Electric Co. HFN-022-B2 B2/02/17 BERGGREN, J S Standardization & Special Projects Branch ip 22632 129
- 840314004B Forwards "Grand Gulf Component Tracking Sys," "Shoreham Component Tracking Sys" & "Transamerica Delaval, Inc Diesel Generators Owners Group Program Plan," to resolve concerns w/emergency diesel generators MUSELER, W.J. Long Island Lighting Co TDI-3 84/03/02 DENTON, H.R. Office of Nuclear Reactor Regulation. Director 2pg 22626 062 24X Fiche 50-000,84/03/02,8403140048
- ---8403140080 "Grand Gulf Component Tracking Sys " * Long Island Lighting Co. 84/02/29 879pp. \$2525.064 24X Fiche: 50-000, 84/03/02, 8403140048
- --8403140091 "Bhorsham Component Tracking Sys " * Long Island Lighting Co. 84/02/29 516pp 22627.069 24X Fiche 50-000.84/03/02.8403140048
- --8403140095 "Transamerica Delaval. Int Dissel Generators Dwners Group Program Flan " * TDI (Transamerica Delaval. Int) Dwners Group. 84/03/02 261pp. 22628:223 24X Fiche:50-000,84/03/02.8403140048
- 8403140050 Forwards "Design Review of Connecting Rod Bearing Shells for Transamerica Delayal Enterprise Engines" for Shoreham & Grand Quif dissal generators.

 MUSELER, W. J. Long Itland Lighting Co. 84/03/12. DENTON, H.R. Office of Nuclear Reactor Regulation. Director 2pp 22632 074 24% Fiche. 50-000. 84/03/12. 8403140050
- --8403140086 PAO 7396
 "Design Review of Connecting Rod Bearing Shells for Transamerica Delayal Enterprise Engines"
 * Failure Analysis Associates FAAA-84-3-1 84/03/12 5ipp 28632 076. 24X Fiche: 50-000.84/03/12,8403140050
- 8403140072 Documents B&W Owners Group Leak-Before-Break Task Force 840117 meeting w/NRC in Bethesda MD. Owners group intention to apply leak-before-break concept to reactor vessel core flood nozzles discussef, danda & handouts encl pAYKIN.H W Babcock & Wilcox Operating Flants Guners Group DAYKIN.H W Consumers Power Co 84/03/06 KADAMBI,P NRC No Detailed Affiliation Given. 30pp 22634:190.
- E403140126 Forwards comments on PNL drafts, "Proposed Quidelines for Util Organization Plan" & "Proposed Workbook for Assessment of Organization & Administration of Utils Seeking OL for Nuclear Power Plant " Drafts well prepared & thorough. E18ENHUT.D 0 Division of Licensing. 84/03/02 THOMPBON, H Division of Human Factors Safety. 14ipp 22637 001
- 8403140131 Forwards "Justification of Trip Two/Leave Two Reactor Coolant Pump Strategy During Transient," to assist NRC & owners group utils in resolution of TMI Action Item II. K. 3.5 per Generic Ltr 83-10A HELLS,R W. C-E Operating Plants Owners Group HELLS,R. W. Northeast Utilities RHM-84-13 84/02/29 EISENHUT, D. 9 Division of Licensing 2pp. 22620 001.
- B403140203 Forwards "Operating History Overview for Diesel Generators in Nuclear Syc," comparing Transamerica Delaval, Inc generators w/generators and by other vendors HEBDON, F.J. Program Technology Branch, AEGD/P401 B4/02/27 BERLINGER.C.H NRC No Detailed Affiliation Given 1p 22538 319 24X Fiche: 50-000.84/02/27,8403140203
- ---B403140205 "Operating History Overview for Diesel Generators in Nuclear Byc." * Director's Office. AEOD/P401 84/02/29. 65pp. 22638:320 24% Fichs.50-000,84/02/27,8403140203.

- B403140340 Summary of B31215 meeting w/GE & Mark I Owners Group in Bathesda. MD re Mark I containment watwall-drywell vacuum breaker design methodology SIEGEL, BL Operating Reactors Branch 2 84/02/21 Operating Reactors Branch 2 51pp 22635 198 24% Fiche 50-000,84/02/21,8403140340
- 840315002B Responds to 840105 Generic Ltr 84-01 re NRC use of terms important to safety & safety-related Meeting to discuss important to safety issue requested after 840401 Definition of important to safety unresolved CUTTER. A B Carolina Power & Light Co GL-84-01 84/03/12 TAYLOR. J M Director's Office, Office of Inspection and Enforcement ip 22640 331
- 8403150085 Forwards "B&W 177 Fuel Assembly Duners Group Safe End Task Force Rept on Generic Investigation of HPI/MU Nozzle Cracking, " summarizing util involvement in cracking program CROUSE, R P Toledo Edison Co 1027. 84/03/07 STOLZ, J F Operating Reactors Branch 4 2pp 22639 055 24X Fiche 50-346.84/03/07,8403180085
- 8403150097 Forwards comproprietary version of XN-NF-82-90(NP), Suppl 1: "Potential Radiological Consequences of Incidents Involving High Exposure Fuel:" which supports application for Tech Spec changes for Cycle 5 reload CHANDLER.J C Exxon Nuclear Co . Inc (subs of Exxon Corp) UCC-048 84 B4/03/13 DENTON:H R Office of Nuclear Reactor Regulation, Director 6pp 22639 024 24X Fiche: 50-314, 84/03/13, 8403150097
- --B403150104 XN-NF-B2-90 (NP) S01
 "Potential Radiological Consequences of Incidents Involving
 High Exposure Fuel, BC Cook, Unit 2 "
 COPELAND.R A , KAYEER.W V , STOUT.R B Exxon Nuclear Ca , Inc
 (subs of Exxon Corp) XN-NF-B2-90(NP) B4703/31 24pp
 22637 030 24X Fichs 50-316.B4/03/13,8403150097.
- 8403150107 Suppls add1 info submitted in 840127 ltr re fuel surveillance program.per request Insp of nonleakers not performed on routine basis unless info of special interest can be obtained CHARNLEY, J & General Electric Co MFN-024-84 84/02/27 RUGENSTEIN.L & Assistant Director for Core & Plant Systems 2pp 2012 2012
- B403150133 Forwards "Transamerica Delaval. Inc Diesel Generator Rocker Arm Capscrew Stress Analysis Rept " Capscrew design adequate for applicable engines & svc conditions MUSELER, W J TDI (Transamerica Delaval, Inc.) Gwners Group TDI-5 84/03/13 DENTON. HR Office of Nuclear Reactor Regulation, Director 2pp 22639 270 24X Fiche 50-000,84/03/13,8403150133
- --8403150154 "Emergency Diesel Generator Rocker Arm Capscrew Stress Analysis," prepared for Transamerica Delaval, Inc Owners Group * Stone & Wøbster, Inc 84/03/31. 27pp 22637 272. 24X Fiche 30-000,84/03/13.8403150133
- 8403160055 Notification of 840314 meeting w/Westinghouse, BMNL & ANL in Bethesda, HD to discuss Westinghouse research program reultrasonic testing of cast stainless steel pipe LIAN, B D Materials Engineering Branch 84/03/06 JGHNSTON, W V Assistant Director for Matls, Chem & Environ Technology (Post 830201) 2pp 22663 128
- 8403160090 Forwards SMECO 7703, "Missile-Barrier Interaction," submitted per 840227 response to Action Item 18 of structural design audit HOOLEVER, E. J. Duquesne Light Co. 2NRC-4-024 84/03/09 KNIGHTON. 9 W. Licensing Branch 3 1p 22653.001 24X Fiche 50-412,84/03/09,8403160090
- --8403160096 SWECO 7703

 "Missile-Barrier Interaction."

 JANKOV. Z D , SHANAHAN. J A , WHITE. H P Stone & Webster Engineering Corp EMTR-801. 77/09/30 223pp. 22653 002 24X

 Fiche 50-412,84/03/09,8403160090
- 8403160369 Advises that 831209 description of proposed techniques for inerting & packaging Zircalou meths reviewed & found acceptable Restrictions contained in confirmation action itr dtd 830819 withdrawn BTOHR.J.P. Division of Emergency Preparedness & Materials Sefety, CAL 84/01/20 BRITTON.W H Westinghouse Electric Corp. 1p. 22660 082
- 8403190241 Forwards Rev 2 to BAW-1543, "Integrated Reactor Vessel Matl Surveillance Program" Rev reflects modified capsule withdrawal schedule IAYLOR, J. H. Babcock & Hilcox Co. ESC-164, 84/03/14 MORAN, D. Office of Nuclear Reactor Regulation, Director 2pp 22672 321

Sign N

- --8403170246 BAW-1543 RO2 Rev 2 to "Integrated Reactor Vessel Matl Surveillance Program" LOME: A L , MOORE, K E , AADLAND, J D Babcock & Wilcox Co 84/02/29 65pp 22672 323
- 8403190257 Forwards "Steam Pressure Suppression Characteristics of Water-Soluble Plastic Membrane Shielded Ice for Ice Condenser Containment Nuclear Power Plants "
 TUCKER: H D Duke Power Co 84/03/07 DENTON, H R Office of Nuclear Reactor Regulation. Director 7pp 22672 102 24X Fiche 50-000:84/03/07.8403190257
- --B403170261 "Steam Pressure Suppression Characteristics of Water-Boluble Plastic Membrane Shielded Ice for Ice Condenser Containment Nuclear Power Plants " Supporting documentation encl SCRABIS, C M Westinghouse Electric Corp B3/06/30 125pp 22672 109 24X Fichs 50-000,84/03/07,8403170257
- 8403190394 Forwards nonproprietary & proprietary "Technical Basis for Eliminating Pressurizer Surge Line Ruptures as Structural Design Basis for Catawba, Units 1 & 2 " Revised FSAR pages also encl Proprietary rept withheld (ref 10CFR2 790) TUCKER, H B Duke Power Co 84/02/29 DENTON, H R Office of Nuclear Reactor Regulation, Director. ADENSAME G Licensing Branch 4 3pp 22674 089 24X Fiche 50~413,84/02/29,8403190394
- --B403170377 Application for withholding proprietary rept WCAP-104B7.
 "Technical Basis for Eliminating Pressurizer Surge Line
 Ruptures as Structural Design Basis "
 WIESEMANN: R A Westinghouse Electric Corp CAW-84-13 84/02/15
 DENTON: H R Office of Nuclear Reactor Regulation, Director 9pp
 22674 092 24X Fiche 50-413,84/02/29,8403170394
- ~-B403190404 WCAP-104B8 (NP)

 Nonproprietary "Technical Basis for Eliminating Pressurizer Surge Line Ruptures as Structural Design Basis for Catawba Units 1 & 2 "

 SHAMY.8 A . YANG, C Y , SANE, A D Wastinghouse Electric Corp B4/02/10 107pp 22674 101 24X Fiche 50-413, B4/02/27, B403190394
- 8403200100 Forwards Rev 1 to XN-NF-83-85, Suppl 1, "DC Cook Unit 2, Cycle 5 84R "
 CHANDLER, J C Exxon Nuclear Co , Inc (subs of Exxon Corp)
 JCC 052 84 84/03/16 DENTON, H R Office of Nuclear Reactor
 Regulation, Director ip 22699 186 24X Fiche 50-316, 84/03/16, 8403200100
- --8403200101 XN-NF-83-85 R01 801
 Rev 1. Buppl 1. to "DC Cook Unit 2. Cycle 5 SAR "
 COPELAND.R A . WILLIAMSON.H E . STOUT.R B Exxon Nuclear Co . Inc
 (subs of Exxon Corp) 84/03/15, 12pp 22699 187 24X
 Fiche 50-316,84/03/16,8403200100
- 8403200129 Advises that QE control rod drive (CRD) tests indicated unanalyzed load in design & analysis of CRD sys Newly identified load does not represent condition reportable under Part 21 HELMIG. DR BWR Dwners Group BWRDG-8405 84/03/13 EISENHUT. D Q Division of Licensing 2pp 22697 041.
- 8403200182 Forwards Topical Rept 7703 on missile barrier interaction W/o rept EMERSON.H.F Stone & Webster Engineering Corp 84/03/06. DOOLITTLE.E L Licensing Branch 1 1p 22686:340 24X Fiche 50-423.84/03/06.8403200182
- 8403200184 Forwards procurement spec to which Transamerica Delaval standby diesel generators ordered, in response to NRC 840131 request ROBRIGUEZ, R. J. Sacramento Municipal Utility District RJR 84-99 84/03/15 STOLZ, J.F. Operating Reactors Branch 4 337pp 22686 001 24X Fiche 50-312,84/03/15,8403200184
- B400200222 Responds to B40214 Requests for Info 1 % 2 re R-4 series engines List indicating engine number model & svc number, customer name & address, rating date shipped & date started encl MATHEMS, C S Transamerica Delaval, Inc B4/03/16 EISENHUT, D 0. Division of Licensing 20pp 22691.179 24X Fichs 50-000, 84/03/16;
- 8403200271 Affidayit of Q Sherwood requesting NEDE-20592-6P, "STR Bundle Submittal, Millstone-1 Segmented Test Rod Bundle, Suppl A," dtd Jul 1982; be withheld from public disclosure SHERMODD, 0 G General Electric Co B3/06/02, 3pp. 22676, 171 24X Fiche 50-245,83/06/02,8403200271.

- 10015 Forwards proprietary response to 040222 telcon request for 1 info on MCAP-10107 (P). "CONDOR-A Thermal-Hydraulic formance Code for BWRs " Response withheld (ref
- FR2 790)

 E.E.P. Westinghouse Electric Corp. NS-EPR-2894 84/03/09

 ASC 0 Standardization & Special Projects Branch 2pp

 AS 346
- 3210020 Requests that response to request for addl info on WCAP-2107 (P). "CONDUR-A Thermal-Hydraulic Performance Code &T BWRs." per EP Rahe B40309 ltr.be withheld per OCFRR 790 & 9 5 JESEMANN.R A Westinghouse Electric Corp AW-84-17 B4/03/09 HOMAS.C O Standardization & Special Projects Branch 1p 2706 348
- 10053 Endorses SH Hobbs Feb 1984 Ltr HON-015 to HR Denton in planse to NRC 831208 request for add1 info re Mydrogen! trol Commers Group (HCOG) test program Guestions to be were db HCOG & util, respectively, listed E-L F Hississippi Power & Light Co AECH-84/0091 84/03/09 TON-HR Office of Nuclear Reactor Regulation. Director 2pp D4:344 24X Fiche 50-416.84/03/09,8403210053
- 10075 Forwards add1 info re BWR steady-state analysis methods, per 840117 request Answers provided to 12 of 15 questions goed by NRC GE will provide input to Questions 4.8 & 13

 1 responses will be submitted by 840321

 MERMAN.S R Carolina Power & Light Co NLB-84-112 84/03/15.

 BALLO.D B Operating Reactors Branch 2 2pp 22705-122 24X ps 50-324,84/03/15,8403210075.
- 3210080 NF-1583 04-1 A01
 mend 1 to "Verification of Carolina Power & Light Ref BHR
 hermal-Hydraulic Methods Using FIBHR Code"
 JMITA-R K Carolina Power & Light Code B4/03/31 41pp
 2705 124 24X Fiche 50-324,84/03/15.8403210075
- 20215 Notification of B40329 meeting w/Westinghouse & Westinghouse ers Group Procedures Bubcommittee in Bethesés MD to cuss how EPG task analysis addressed operator info & trol needs per NMEG-0737. Suppl 1 YTON, H B Procedures & Systems Review Branch GL-82-33 D3/05. ZIEMANN, D L Procedures & Bystems Review Branch 2pp 21:361
- 30093 Application for amend to License DPR-20, consisting of posed Tech Spec change request to revise accident & ssient analyses due to steam generator tube plugging as III amend fee encl. Heatup scheduled for 840508 vision. B D Consumers Power Co 84/03/16 CRUTCHFIELD, D. rating Reactors Branch 5 18pp 22731 099 24X ne 50-255,84/03/16,8403230093.
- 9230102 XN-NF-84-14

 Palisades Cycle & Setpoint Verification W/30X Bleam
 prevator Tube Plugging "
 EMDBUIST.T R. NUTT.W T. Exxon Nuclear Co., Inc. (≤ubs. of Exxol
 pr) 84/03/09 43pp 22731 158 24X Fiche 50-255,84/03/16,
 ₹03230093
- 3230104 XN-NF-84-18

 Tant Transiant Analysis for Palisades Nuclear Power Plant

 T30X Steam Generator Plugging "
 ENDQUIST.T R , NUTT,W T Exxon Nuclear Co. , Inc (subs. of Exxon arp) 84/03/09 150pp 22731.202 24X Fiche 50-255,84/03/16,8-0323093
- >OO24 Forwards "Justification of Manuel RCP Trip For Small Break Events," Westinghouse Owners Group response to Generic B B3-10C & D *PARD.J J. Westinghouse Operating Plants Owners Group *PARD.J J. Carolina Power & Light Co. 9L-83-10C 84/03/09 FBON.R J Division of Systems Integration (post 811005), 134pp 30,017
- > 0093 Summary of 840214 mesting W/OE, Westinghouse & Bechtel repower uprating program Attendee list & agenda encl * *EY, V. L. Operating Reactors Branch 2. 84/02/29, VASSALLO.D. B. *ating Reactors Branch 2. 20pp. 22761:317.
- *O170 Forwards Endorsement 127 to NELIA Policy NF-1.

 INS.J 0 Marsh & McLennan, Inc 84/03/07. SALTZMAN.J.

 stant Director for State & Licenses Relations. 2pp. 22750:357

- 8403260219 Corrects Suppl 1 to Rev 2 to XN-NF-79-71(P), "Methodology for Including Code Uncertainties in Determining Operating Limits for Rapid Pressurization." to indicate broken line curves as COTRANSA & solid line curves as DATA CHANDLER. J C Exxon Nuclear Co. Inc (subs of Exxon Corp.) JCC 054 84 84/03/19 THOMAS.C D Standardization & Special Projects Branch 1p 22756 153
- 8403270010 Application for amend to License DPR-35, consisting of Proposed Tech Spec Change 84-02 allowing increased core flow HARRINGTON, W.D. Boston Edison Co. BECO 84-045 84/03/20 VASSALLO, D.B. Operating Reactors Granch 2 3pp. 22769 165 24) Fiche 50-293,84/03/20.8403270010
- --B403270022 NEDO-30242

 "Safety Review of Pilgrim Nuclear Power Station.Unit 1 at
 Core Flow Conditions Above Rated Flow Throughout Cycle 6 "
 FISCHER.D L , GRIDLEY.R L General Electric Co 83/08/31 34pp
 22769 170 24X Fiche 50-293.84/03/20.8403270010
- --B403270024 NEDO-30242 SO1
 Suppl 1 to "Safety Review of Pilgrim Nuclear Power Station
 Unit 1 at Care Flow Conditions Above Rated Flow for End-ofCycle 6 "
 FISCHER, D L , GRIDLEY, K L General Electric Co B3/09/30 15pp
 22769 201 24% Fiche 50-293, B4/03/20,B403270010
- 8403270130 Application for amend to License DPR-25 thanging Tach Specs to extend certain MAPLHGR curves to 40,000 MWd/8T RYBAK.B Commonwealth Edison Co 8282N 84/03/19 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp, 22774 129 24X Fichs 50-000,84/03/19,8403270130
- --8403270135 NEDO-24145A ERR 09 Errata & Addonda Sheet 9. replacing Page 4-14 to "LOCA Analysis Rept for Drosden Units 2 & 3 & Guad Cities 1 & 2 Nuclear Power Stations " * General Electric Co 79NED273 83/01/31 2pp 22774
- 8403270132 Forwards "Emergency Diesel Generator Air Start Valve Capscrew Dimension & Stress Analysis," prepared by S&W for Transamerica Delayal, Inc (TDI) Diesel Generator Dumers Group MUSELER,W J TDI (Transamerica Delayal, Inc.) Owners Group TDI~ 84/03/23 DENTON, H.R. Office of Nuclear Reactor Regulation. Director & Rp. 22774 OOI 24X Fiche 50-000.84/03/23,8403270132
- --8403270107 "Emargency Diesel Generator Air Start Valve Capscrew Dimension & Stress Analysis." prepared for Transamerica Delaval. Inc (TDI) Diesel Generator Owners Group # Stone & Webster Engineering Corp 84/03/31 23pp 22774 003 24X Fiche-50-000.84/03/23.8403270102
- 8403270134 Requests meeting on 840418 to discuss short-term & long-term corrective actions & investigations re Transamerica Delaval diesel generators List of suggested meeting topics encl.

 MCGAUGHY, J P TDI (Transamerica Delaval, Inc.) Owners Group AECM 84/0187 84/03/23. DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 22769 133 24X Fiche 50-000, 84/03/23, 8403270134
- 8403280043 Notification of 840320 meeting w/util & C-E in Bethesda,MD to discuss proposed testing program to demonstrate adequacy of mods to RCS pumps, thermouells, thermal sleeves & control element assembly shrouds
 LICITRA,E A Licensing Branch 3 84/02/29 KNIGHTON, 9 W Licensing Branch 3. 3pp 22812.361 24X Fiche 50-528,84/02/29,8403280043
- 8403280122 Summary of 840224 meeting w/Hestinghouse Gwmers Group in Bethesda. MD re proposed Westinghouse steam generator tube rupture generic program Attendee list & agenda encl NERSEG, V Licensing Branch 3 84/03/07 Licensing Branch 3 35pp 22811 131. 24X Fiche: 50-000.84/03/07.8403280122
- 8403280242 Summarizes 840222 meeting w/Westinghouse re evaluation methodology for ECCS & convolution of LOCA uncertainties Westinghouse presented WCAP-10375(P), "Bitatistical Evaluation of LOCA Heat Source Uncertainties"

 MDRAN.D H Standardization & Special Projects Branch 84/03/16
 THOMAS.C O Standardization & Special Projects Branch. 3pp 22808:206
- 8403280248 Requests info re lack of issuance of revised proposed rule on diverse scram sys for Westinghouse reactors approved on 831103 GIL INSKY, V Commissioners 84/03/06 Commissioners. ip 22806:189.

- 8403290267 Rev to 831212 application for amend to Licenses NPF-9 & NPF-12, changing listed Tech Spac bases, per Y Hsii & MS Dunenfeld 840315 & 16 tolons, respectively Westinghouse proprietary info withheld (ref 100FR2 790)
 TUCKER.Η Β Duke Power Co 84/03/23 DENTON, Η R Office of Nuclear Reactor Regulation, Director ADENBAM, E Q Licensing Branch 4 3pp 22800 092 24X Fiche 50-369,84/03/23,8403290267.
- --8403290279 Requests withholding of proprietary info requested by util from public disclosure (ref 100FR2 790) Affidavit AM-76-60 dtd 761202 encl
 HIESEMANN,R A Westinghouse Electric Corp CAM-84-18 B4/03/14
 DENTIN,H R Office of Nuclear Reactor Regulation, Director 10pp 22800 100 24X Fiche 50-369,84/03/23,8403290267
- --8403270282 Nongroprietary info reflecting use of Rosemount resistance temp detector
 + Hestinghouse Electric Corp 84/03/23 59pp 22800 110 24X
 Fiche 50-369,84/03/23.8403270267
- 8403300088 Advises that fee reluctantly paid to Div of Accounting & Finance for review of Topical Rept NEDE-23785-1-P,Vols 1-3 NRC incorrectly termed Vol 3 as separate rept GUIRK.) F General Electric Co MFN-033-84, 84/03/23. MILLER,W D License Fee Management Branch 2pp 22821 361
- B403300107 Forwards proprietary & nonproprietary versions of:
 "Methodology for Addressing Superheated Steam Releases to
 Ice Condenser Containments " Proprietary version withheld
 (ref 100FR2 790).
 TUCKER, H B Duke Power Co B4/03/28 DENION, H R Office of
 Nuclear Reactor Regulation, Director ADENSAM, E Q Licensing Branch
 4 2pp 22817-001 24X Fiche 50-413,84/03/28,8403300107
- ~~8403300116 Requests proprietary "Methodology for Addressing Superheated Steam Releases to Ice Condenser Containments," be withheld from public disclosure per ICCFR2 790 HIESEHANN, R. A. Westinghouse Electric Corp. CAM-84-24 84/03/26 DENIGN, H. R. Office of Nuclear Reactor Regulation, Director. Spp. 22819 003 24X Fiche 50-413,84/03/28,8403300107.
- --8403300119 Nonproprietary, "Methodology for Addressing Superheated Steam Releases to Ice Condenser Containments" • Westinghouse Electric Corp 84/03/28 240pp 22819.011 24X Fiche 50-413,84/03/28.8403300107
- 8403300170 Requests that Transamerica Delaval, Inc dissel review program be stopped promptly due to improper role of util in directing review New independent review should be established in consultation w/Buffoli County JONES, F. Suffolk County, NY 84/03/23 DENTON, H.R. Office of Nuclear Reactor Regulation, Director. 2pp 22820,047 24X Fiche 50-322,84/03/23,8403300170
- 8403300179 Requests that Issues Mgt Program document, transmitted on 840208, be classified proprietary. Affidavit will be submitted separately. Updated list of cognitant contacts between 8kW Buners Group & NRC encl IAYLOR.J H Babcock & Wilcox Co 84/03/19 DENTON, H R. Diffice of Nuclear Reactor Regulation, Director. 2pp. 22820 331.
- 8403300235 Responds to request for review of add1 info re NucleDyne passive containment sys design Review must be preceded by application for std design approval DENTON. HR Opfice of Nuclear Reactor Regulation, Director 84/03/13 FALLS 0 B NucleDyne Engineering Corp. 2pp 22842:34
- --8403300237 Forwards response to rept re review of NucleDune Engineering Corp containment sys design, M/o encl. FALLS, 0 B NucleDune Engineering Corp. 84/02/17, DENTON, H R. Office of Nuclear Reactor Regulation, Director, 2pp 22842-348
- 8403300251 Bummary of 840221 meeting w/util in Bethesda, MD re datails of util proposed onsite/offsite electrical power reliability program for Transamerica Delayal, Inc diesel generators Attendance list & vieugraphs encl HOUSTON, M D. Licensing Branch 2 84/03/06 Licensing Branch 2 21pp 22845:001 24X Ficha 50-416.84/03/06.8403300251.

WASH REGULATORY PUBLICATIONS - PRE-NURED SERIES

8403010024 Responds to FDIA request for documents re petition for rulemaking PRM-80-31 from Citizens Task Force of Chape! Hill-NG Forwards App & documents completely withheld (ref FDIA Exemption 5). FELTON.J.H. Division of Rules and Records. 84/01/18. SHULLY, S. C. Union of Concerned Scientists 4pp. 22446:035.

--84030i0074 Forwards review comments on draft RES denial of patition for rulemaking on emergency planning zone at nuclear power plants, per request General comments encl HULMANL G Accident Evaluation Branch 83/01/07 COTA, P C Research & Stendards Coordination Branch 7pp 22446.049.

WASTE MOT NUCLEAR WASTE MANAGEMENT

- 8401120325 Forwards nonproprietary version of topical rept."
 "Title 10CFR61. Maste Form Certification Cement "
 STAEHR. J P. PDPPE, L K. Chem-Nuclear Systems, Inc. 83/11/30,
 JOHNSON, T. NRC No Detailed Affiliation Given ip 21803.11:
- --8401120550 CNSI-WF-C-01-NP Nonproprietary version of "Title 10CFR61, Waste Form Certification - Cement" & Chem-Nuclear Systems, Inc 83/11/30 105pp. 21803; 113.
- 8402170325 Forwards UMTRA project EIS & environ assessment revised schedules
 ARTHUR.J Energy, Dept. of. 84/01/26. PENNFILL.R NRC No Detailed Affiliation Given 5pp 22313 198
- 8402270471 Forwards evaluation requested by 840127 memo re Shiprock, NM site seismicity assessment as part of remedial action plan for stabilization of inactive U mill tellings. Level of conservatism for assessment not specified, per request JACKBON, R. E. Geosciences Branch. 84/02/16, JUSTUS, P. B. Geotechnical Branch (Post 83:001) 4pp 67:89, 211
- B403010356 Requests results/comments on review of encl analysis of water samples OA program by 840229
 WHITE: N G Emergy, Dept of 84/02/16 KNAPP, M NRC No Detailed Affiliation Given 12pp 22449.336
- 8403020174 Notifies of upcoming meetings.List will be updated weekly TAYLOR, T J. Environmental Protection Agency. 84/02/17. MILLER, M. NRC NO Detailed Affiliation Given CHRISTOFFERSON Utah, State of FRISHMAN, S Texas, State of 1p 2249:070.
- 8403020185 Lists Div of Wasts Mpt representatives chosen to be located at sites under investigation by DDE as potential repositories for geologic disposal of high lavel wasts, per JO Davis 830729 memo.

 BROWNING.R.E. Division of Wasts Management 84/01/16, KEPPLER, J. G. Region 3, Office of Director MARTIN, J. B. Region 5, Office of Director 2pp. 22495 003.
- B403020204 Requests list of waste mgt documents from 63:014 to present re Nevada Test Site project & info concerning process by which future documents can be received JOHNSON,C A Nevada, State of 84/02/03, RUSSELL,C.F. Division of Waste Management 27pp 22494,333
- 8403020332 Forwards H Sheely 830210 ltr containing State of EC comments on Chem-Nuclear topical rept. "Polyethylene High Integrity Containers."

 NUSSBAUMER, D A Assistant Director for State Agreements Programs 84/02/16 HiggInBotham, L Low-Level Waste & Uranium Recovery Projects Branch. 1p 22492-238.
- --8403020339 Comments on Chem-Nuclear topical rept, "Polyethylene High Integrity Containers," per NRC 831227 & 840123 requests. Container acceptable for use at Barnwell site. SHEALY, H O Bouth Caroline, State of 84/02/10 NUSSBAUMER, D A Assistant Director for State Agreements Programs, 2pp. 22492 239.
- 840302034A Forwards summary of 830627-28 meetings w/DOE/NPO in Silver Spring.MD re preparation of site characterization plan for salt site.per 830711 telcon. COPLAN.S.M High Level Waste Technical Development Branch. 83/07/21 VIETH D L. Energy, Dept of. 13pp. 22492: 225.
- 8403020374 "Procedures for Field Chemical Analyses of Water Bamples," KORTE, N., EALEY, D. Bendix Corp KORTE, N. Energy, Dept. of, Idaho Operations Office UC-70A, 83/12/31, 32pp 22492-190.
- B403050315 Forwards "Data for Qeochemical Investigation of UNTRAP Designated at Salt Lake City.UT " ", at Grand Junction, Co: " ", ... at Shiprock, NM" & " ... at Mexican Hat, UT " BUSH, K J. Geochemistry & Environmental Chemistry Research, Inc GEOR-90/2-84/2, 84/02/08 HEBER, M NRC No Detailed Affiliation Given. 1p. 22505:031

1

- --B403050318 R-B217

 "Data for Geochamical Investigation of UMTRAP Designated Site at Balt Lake City, UT "

 MARKOB, G. BUSH, K. J. Geochamistry & Environmental Chemistry Research, Inc. DOE/UMT/0236 B4/02/08 63pp 22505 032
- --8403050319 R-8215
 "Data for Geochemical Investigation of UMTRAP Designated
 Site at Grand Junction, CO"
 MARKOS, G. BUSH.K. J. Geochemistry & Environmental Chemistry
 Research, Inc. DDE/UMT/0232 84/02/08 73pp 22505 095
- --8403050322 R-8216
 "Data for Geochemical Investigation of UMTRAP Designated Site at Shiprock.NM"
 MARKOS.O . BUSH.K J Geochemistry & Environmental Chemistry Research. Inc DD&/UMT/0234 84/02/08 65pp 22505 168
- --B403050323 R-B212
 "Data for Ceochemical Investigation of UMTRAP Designated Site at Mexican Hat.UT "
 MARKOS.O , BUSH.K J Geochemistry & Environmental Chemistry Research, Inc UMTRA-DOE/ALO- B4/02/08. 128pp 22505 233
- B403060432 Forwards Design Section comments on draft Site Technical Position NNHSI BTP-I O. "Groundwater Issues For Nevada Nuclear Haste Storage Investigations "Marked-up copy encl providing general & specific comments OREEVES.J T High Level Waste Technical Development Branch B3/0B/17 POHLE.J A High Level Waste Technical Development Branch 17pp 22552:030
- 8403060450 Forwards current schedule of DDE/NRC technical meetings on repository licensing. Schedule being updated & distributed at least biweekly to reflect changes
 MILLER, H J Repository Projects Branch (Post 831001) 84/02/01
 BROWNING, R, BELL, M, BUNTING, J NRC No Detailed Affiliation Given 4pp. 22552 019
- 8403060519 Forwards "Remedial Actions at Former Vitro Chemical Co Site South Salt Lake Preliminary FES," for review & comment MORLEY, J A Energy, Dept of 84/02/24 HIGGINBUTHAM, L , MARTIN, D NRC - NO Detailed Affiliation Given GRGELSEMA, D Energy, Dept of 3pp 22550 012
- --8403060521 UMTRA-DDE/AL-0099-F
 "Remedial Actions at Former Vitro Chemical Co Site South Salt Lake.Preliminary FES"
 * Energy. Dept of 84/02/29 724pp. 22550 013
- 8403120241 Draft annotated agenda for 840315-16 meetings w/DGE in Richland. NA to discuss geology of BNIP * NRC - No Detailed Affiliation Given 00687 84/02/15 NRC -No Detailed Affiliation Given 5pp 82619-232
- 8403120248 Responds to request for technical assistance in evaluating Nuclear Packaging, Inc. FL50 high integrity container (HIC) HIC design can be approved for continued use provided vendor submits further info NUSBBAUMER, D. Assistant Director for State Agreements Programs 8402/29, STRONG, T.R. Washington, State of, Dept. of Social & Health Services, 3pp. 22618, 359
- 8403140027 Forwards comments on NRC proceeding for concurrence in DDE guidelines for recommendation of sites of nuclear waste repositories & interpretation of available evidence MATHESON, B M Utah, State of 48FR50432, 84/03/09, PALLADING, N J Commissioners 8pp 22633.301
- 8403i40i32 Discusses 840227 telcon w/B Cook re Hovis itr concerning data collection effort at Hanford that involved L Lehman & availability of data.

 DELLIGATTI.M Repository Projects Branch (Post 831001), 84/02/28, WRIGHT, R. Repository Projects Branch (Post 831001), 1p 22637 355
- B403140312 Forwards monthly update detailing project activities covering contacts w/States of PA.UT.WY.& OR & plan for implementing EPA Stos at UNTRAP sites MORLEY.J.A Energy. Dept. of. 84/03/01 HIGGINBOTHAM,L Low Level Waste Licensing Branch. 5pp 22635.308
- B403150221 Forwards study of soil samples collected during drilling of well located 100 ft south of Beatty site. Requests any comments on study be submitted to State of NV NUBBBAUHER, D.A. Assistant Director for State Agreements Progrems. B4/03/07 HiggINBOTHAM, L. Low Level Waste Licensing Branch | Ip. 22648 227

- --8403150222 Forwards study made on soil samples collected during drilling of well 100 ft south of Beatty site According to data, sorption of selected ions decreases below 290 ft VADEN.J Novade, State of 84/02/21 NUSSBAUMER.D A Assistant Director for State Agreements Programs ip 22648 288
- --B403150223 "Sorption of Selected lons in Alluvial Profile " HEIDKER,J C Neveda, Univ of 84/02/21 18pp 22648 289
- 8403150300 Suggests meeting of groundwater hydrologists re proposed exploration program at Lakeview OR UMTRAP site Exploratory program should provide groundwater info required for NRC concurrence in NEPA documents & radiologica) assessment HIGGINBOTHAM, L. Low-Level Waste & Uranium Recovery Projects Branch 84/02/14 MATHEWS, M. Energy, Dept of ip 22647-316
- B403150315 Forwards repts of telcons held w/NRC re BWIP ABH.E B Rockwell International Corp 685 84/02/16 DL80N.O L Energy, Dept of 5pp 22649 309
- B403160056 Trip rept of B40201-03 visit to Fort Collins,CO to attend conference on mgt of U mill tailings.low level waste & hazardous waste ODODE.D Geotechnical Branch (Post B31001) 84/02/28 KNAPP.M R Geotechnical Dranch (Post B31001) 2pp 22662 318
- B403160072 Requests written concurrence on DDE/State of WY & Nava;o Indian Tribe cooperative agreements to provide record of review process HIGGINNOTHAM, L Low-Level Waste & Uranium Recovery Projects Branch B4/02/2B FONNER, R L Regulations Division ip 22662 309
- 8403160073 Forwards J Fields rept summarizing effects of two changes on ouput of NHTT/DVM graphics package HISE.M J Repository Projects Branch (Post 831001) 84/02/16 Repository Projects Branch (Post 831001) 21pp 22662 288
- B403190420 Reviews responses to NRC commonts on high integrity container design for TMI EPICOR-II prefilter wastes Approval of design recommended following resolution of listed comments
 NUSSBAUMER, D. A. Assistant Director for State Agreements Programs B4/02/01 KIRNER, N. Washington, State of 2pp 22681 342
- 8403170422 Notifies of 840306-07 meetings w/onsite licensing representatives in Silver Spring.ND to discuss activities required to provide timely guidance to DGE Agenda entl BROWNING.R E Division of Waste Management 00393 84/02/24 CODK.F R. PRESTROLT,P T., VERMA.T R Division of Waste Management 4pp 22681-332
- 8403190447 Forwards trip rept of 840130-0203 visit to Golden & Fort Collins,CO to attend NRC Agreement States meeting, quarterly meeting of UMTRAP participants & sixth symposium on mgt of U tailings.low level waste & hazardous waste WEBER,M F Geotechnical Branch (Post 831001) 84/02/13 KNAPP,M R Geotechnical Branch (Post 831001) 60pp 22679 297
- 8403200312 Responds to 840130 memo requesting review of Shiprock remedial action plan for UNTRAP Due to limited resources, assistance requested from Seismology Section in reviewing & commenting on plan Seismologist comments encl
 JUBTUS.P.S Gentechnical Branch (Post 831001) 84/02/27
 HIGGINBOTHAML Low-Level Waste & Uranium Recovery Projects Branch
 ip 22709 168
- 8403200314 Forwards notice of upcoming meetings as result of 830719-20 meetings Notice will be updated weekly TAYLOR, T J Energy, Dept of 00388 84/02/24 MILLER, H NRC No Detailed Affiliation Given CHRISTOFFERSON Utah, State of FRISHMAN, S Texas, State of 1p. 22709-167
- B403200331 Notification of U subcommittee & U administrative group organization B40207 meeting in Richmond, VA Resolution passed by State of VA Coal & Energy Commission encl CATON, B. J. Virginia. Commonwealth of. 84/01/24 Virginia. Commonwealth of. 799 22709 132
- 8403200345 Forwards current list of technical meetings on repository licensing tentatively established w/DQE Several addl meetings being scheduled & organized MILLER, H. J. Repository Projects Branch (Post 831001) 00693 84/02/16 BROWNING, R., BELL, M., MILLER, H. NRC No Detailed Affiliation Given 4pp 82709 110
- 8403200348 Announces fifth bimonthly sait states/NRC meeting in Columbus, DH Forwards draft agenda for next meeting scheduled for 840329-30
 NEFF, J. O Energy, Dept of 84/02/27 JOHNSON, R NRC No Detailed Affiliation Given 3pp. 22709 107

- 8403200331 Discusses DOE request for meeting to discuss dreft comments on Durango preliminary DES Comments should be sent by 830215 List of attendees & handouts from 840214-25 meetings attached PENNIFILLS Uranium Recovery Licensing Branch 84/02/21 MARTIN D E Uranium Recovery Licensing Branch 27pp 22709 073
- 8403200354 Forwards environ assessment preparation schedule fulfilling OPS Plan Commitments 53141211.53141221 & 53141231 & reflecting current scheduling for site workshops, data review & products KNAPP. H R Geotechnical Branch (Post B31001) B4/02/17 BROWNING.R E Division of Waste Management. 2pp 22708 361
- 8403200356 "Ra-226 Analysis for Shiprock Site Tailings Samples " * Bendix Corp. 83/08/09 10pp 22709 065
- 8403200370 Forwards questions & comments re review of surface water hydrology, erosion & long-term stabilization aspects of draft remedial action plan JOHNSON.T L Gentechnical Branch (Post 831001). 84/02/28 PENNIFILL.R Low-Level Waste & Uranium Recovery Projects Branch 500 22708 301
- 8403210034 Comments on petition for rulemaking re DOE guidelines for recommendation of sites for nuclear waste repositories FINN.D F Affiliation Not Assigned 49FR9450 002 84/03/15 Docketing & Services Branch 3pp. 22706 360
- 8403210038 Forwards State of NV comments on patition for rulemaking reconcurrence in DDE guidelines for recommendation of sites for nuclear waste repositories MURPHY. MR Murphy & Davenport 49FR7650 001 84/03/16 PALLADING.N Commissioners 4pp. 22707 011
- 8403220112 Submits notice of upcoming meetings of salt state representatives & onsite representatives TAYLOR, J Energy, Dept of 00398 84/03/02. MILLER, H NRC No Detailed Affiliation Given FRISHMAN, B Texas, State of FORSYTHE, R Mississippi, State of 19 22723 287
- 8403220122 Forwards schedule for review of Topical Rept CNSI-HIC-14871-01: "Polythlene High Integrity Containers " JUNGLING,T L. Engineering Branch (Post 831001). 84/02/27. PDPFE,L.K. Chem-Nuclear Systems, Inc. 2pp. 22723
- 8403220193 Trip rept of attendance at 840109 & 13 class re geotechnical aspects & reclamation of tallings impoundments PENNIFILL, R Uranium Recovery Licensing Branch B4/02/21 MARTIN, D E Uranium Recovery Licensing Branch 1p 22723 280
- B403220R05 Provides process for dealing w/irregularities, both technical & procedural, in hydrologic test methods
 HRIGHT,R J Repository Projects Branch (Post 831001) 00699
 84/02/23 MHLLER,H J Repository Projects Branch (Post 831001)
 2pp 22723 275
- 8403220225 0J-04(83)
 "Environ Assessment of Preliminary Cleanup Activities at Offsite Properties Contaminated by Tailings from Grand Junction Inactive U Millsite, Grand Junction. CO."
 # Bendix Corp 83/04/30 28pp 22719 309
- 8403220228 Informs of review of listed sections of Shiprock remedial action plan Plan acceptable upon receipt of adequate response to encl comments & questions YOUNG, Y Division of Haste Management 84/03/02 PENNIFILL, R Division of Waste Management 5pp 22723 353.
- BA03220231 Confirms verbal advice that ELD reviewed & approved cooperative agreements negotiated between DOE & State of MY & Navajo Nation.for reclamation & cleanup of U mill tailings disposal sites FONNER.R L. Regulations Division. B4/03/07 HIGOINBOTHAM.L Low-Level Waste & Uranium Recovery Projects Branch ip. 22719 359
- 840322023 Confirms info on NRC plans & preparations for review of draft environ assessments presented at 831115-16 meetings R Browning 831130 ltr & 8 Caplan 831116 ltr anci LINEHAN, J Repository Projects Branch (Post 831001) 00402 84/02/24. NEFF, J O Energy, Dept of, 3pp 22719,360
- 8403220274 Ack receipt of 840111 response to 830615 ltr re exploratory shaft const & sealing.List of requested refs encl. LINEHAN.J J. Repository Projects Brench (Post 831001). 00401. 84702/27 NEFF.J. Q Energy, Dept of 4pp 22728 315

- B403220277 Forwards Hydrology Team proposed action plan for reviewing data on sait hydrology prior to environ assessment release Comments requested by 830227 CDDKE, B A Gentechnical Branch (Post B31001) 00403 B4/02/21 JDHNSON, R L Repository Projects Branch (Post B31001) 2pp 22723 311
- 8403220303 Forwards description of hydrogeological exploration test program per 840223 telcon Meeting should be deferred until after exploration program initiated in late Mar MATHEWS.M L Energy. Dept of 84/03/02 HIGOINBOTHAM.L Low-Level Waste & Urenium Recovery Projects Branch 14pp 22730 344
- 8403230025 Comments on petition for rulemaking re DDE guidelines for recommendation of sites for nuclear waste repositories Concurs w/seven points in preliminary decision FRISHMAN.S Texas, Btate of 49FR9550 004 84/03/19. CHILK, B J Office of the Secretary of the Commission 1p. 22728-349.
- 8403230030 Suppls comments on petition for rulemaking re DDE guidelines for recommendation of sites for nuclear waste repositories. Requests serious action be taken on DOE failure to provide peer environ program FINN. D F Affilation Not Assigned 49FR650 003 84/03/17 Docketing & Services Branch 2pp 22724 333.
- 8403230050 Comments on petition for rulemaking re compliance w/DDE guidelines for recommendation of sits for nuclear waste repositories Generally supports Commission position.

 JIM.R. Yakima Indian Nation 49FR7450 005 84/03/20.

 PALLADINO.N J Commissioners ip 22726 343.
- 8403230188 List of State of WA Dept of Ecology high level nuclear waste mgt legislative proposals as of 840302 * Washington, State of 00495 84/03/02 2pp 22759:119
- 8403230193 Forwards documents re high level nuclear waste repository issue.per 840206 request Clarification of some documents listed W/o encl MATEON.D R Policy & Program Control Branch (Post 831001) 00394 84/02/24 DRIVER.D M Utah, State of 2pp. 22741 361
- B403230245 Forwards agenda for NRC/DDE B40313-15 brisfing on gaological sciences investigation in Richland, WA OLBON, O. L. Energy, Dept of 00694 84/03/01. WRIGHT, R. J. Repository Projects Branch (Post 831001) 4pp 22741 357.
- 840H230250 Summary of State of WA High Level Nuclear Waste Advisory Council 840H20 meeting w/listed attendees re forthcoming public infe program w/OFc of High Level Nuclear Waste Mgt # Washington State of 00686 84/01/20. Washington State of 35nm 20779:32 20779:32 6
- B403260043 Informs that preliminary version of NUS topical rept,
 "Qualifications of Cement Solidification Process for
 Stabillring Waste Forms," cannot be processed for detailed
 review due to absence of incomplete info
 HIGGINBOTHAM.L Low-Level Waste & Uranium Recovery Projects Branch.
 WM-84047 84/02/17 POWELL.R. NUS Corp 1p 22763-296,
- 8403260344 Summarizes 840123-26 data review visit at eite Review process consisted of conveying preliminary observations, review & analysis of data & performance of sensitivity analyses & analysis of test data NATARAJAM S Engineering Branch (Post 831001), 84/02/27 HRIGHT,R J Repository Projects Branch (Post 831001) Sipp. 22775 315
- --B403260347 RHO-BM-8A-286 P
 "Design & Const of Block Test in Closely Jointed Rock "
 BLACK, M T , CRAMER, M L Rockwell International Corp 83/06/30
 124pp 22776.034
- --8403260350 Forwards data obtained or requested from DDE during 840124-26 data review visit RAJARAN.V Engineers International, Inc. 84/01/31. SEAMANS, T. Engineering Branch (Post 831001) 17pp 22776, 161
- --8403260353 Forwards draft rock mechanics data review checklist, FORTRAN listing of algorithm to calculate displacements from extensometer data & sample input data instruction for plots generated by data aquisition sys.

 WAHI.K.K. Samdia Laboratories 84/01/31 NATARAJA, N. S.
 Engineering Branch (Post 831001) 49pp 22776 180.
- 8403280253 Trip rept of attendance at Third Workshop on Region-to-Area Screening Methodology for Crystalline Repository Project on 840221-24 in Atlanta: GA. Registration list and LOGSDON, M J Repository Projects Branch (Post 831001). MATTSON, D R. Policy & Program Control Branch (Post 831001) 84/03/07 BROWNING.R E Division of Waste Management 10pp. 22808 190.

- 8403280254 Forwards draft ltr incorporating conclusions & recommendation re technical assistance to State Of MA on NUPAC high integrity container design Addl info required recorrosion performance of F255 welds & pitting corrosion HIGGINBOTHANL Low-Level Waste & Uranium Recovery Projects Branch 84/02/16 NUSSBAUMER.D Assistant Director for State Agreements Programs 7pp 22808 IB2
- 8403280257 Trip rept of attendance at Sixth Symposium on Mgt of U Mill Tailings.Low Level Waste & Hazardous Waste on 840201-03 in Fort Collins.CO Agenda encl
 PEARRING, J R Engineering Branch (Post 831001) B4/0
 OREEVES, J T Engineering Branch (Post 831001), 7pp B4/03/04 22808 175
- B403280259 Trip rept of participation at working session on DDE UMTRAP document, "Vicinity Properties Mgt & Implementation Manual "FLORY, C. Low-Lavel Waste & Uranžum Recovery Projects Branch B4/03/07 HQ01N80THAM, L. Low-Lavel Waste & Uranjum, Recovery Projects Branch. 4pp 22808:173.
- 8403280267 Forwards info re geotechnical engineering topics suggested for consideration in development of UMYRAP remedial action plans. Plan should include sufficient info to indicate that bases for conclusions & findings are well founded GREEVES. J T Engineering Branch (Post 831001) 84/03/02 HIGOINBOTHAM.L, Low-Level Waste & Uranium Recovery Projects Branch. 4pp 22808.077
- 8403290316 Comments on patition for rulemaking re DDE general guidelines for recommendation of sites for nuclear waste repositories NRC concurrence decision offers some improvement to DDE guidelines
 KALITOWSKI,T Minnesota, State of 49FR9650 006, 84/03/20
 PALLADINO,N S. Commissioners, 3pp 22B02 062
- 8403300239 Forwards K Schmader 840119 ltr to prospective offerors re Amend 1 to RFP E512-08400R & cover ltr & std order for work dtd 831230, W/o encl, NEFF, J. D. Energy, Dept of 00057 84/03/14 LINEHAN, J L Repository Projects Branch (Post 831001) 2pp. 22842, 344
- 8403300243 Requests listed documents re BWIP be forwarded to Yakima Indian Nation,
 TOUSLEY, D R. Harmon & Weiss 00703 84/03/08 BUNTING, J
 Division of Waste Management, 2pp 22840,359.
- 8403300248 Rev O to Procedure SD-BWI-PMP-003, "Project Mgt Plan For Hydrothermal Testing of Waste-Barrier-Rock Interactions Using Fully Radwaste Project "DE-JU,R.A Rockwell International Corp EVANB.E.A Westinghouse Electric Corp CHIKALLA.T.D Battelle Memorial Institute, Pacific Northwest Laboratories 00709 62/10/31 67pp 22840 281

XPORTLIC EXPORT AND IMPORT LICENSES

- 8402020431 Amend 2 to Edlow Intl Co export license, extending expiration date to 860101
 PETERBON, M R Assistant Director for Export/Import & International Bafaguards. 84/01/16. 1p 22062 182.
- 8403010084 Application to amend export license, extending expiration date to 870331. WILBON, B. D. General Electric Co BDW-13-84. 84/02/06. HEMBY, E O Office of International Programs, Director ip 22479:356.
- 8403010338 License for Mitsui & Co. Inc to export 189, 750 lbs Zr-2 & Zr-4 trax to Japan ZIMMERMAN, J. V. As V. Assistant Director for Export/Import & International B03-236. 84/02/24. ip. 22449 355
- 8403010346 License for Westinghouse to export one proportional counter, Type 23744, to France ZIMMERMAN, J V. Assistant Director for Export/Import & International Bafeguards. ZE 40190. 84/02/21. 1p 22449, 352.
- 8403010364 License for Sandvik Special Metals Corp to export 200,000 1bs Zircaloy 4 part pilgered cladding to Camada. ZIMMERMAN.J. V. Assistant Director for Export/Import & International Safeguards. SSM-31016. 84/02/21 1p. 22479-173.
- 8403010369 License for Westinghouse to export six compensated ionization chambers. Type 23944, to France.

 IIMMERMAN, J. V. Assistant Director for Export/Import & International Bafeguards ZE 40189. 84/02/21. ip 22449:362.
- 8403010418 Amend i to Reactor Experiments, Inc export license, increasing quantity of U-235 to 15 g & U to 16.84 g ZIMMERMAN, J. V Assistant Director for Export/Import & International Bafeguerds 1464 84/02/24, 1p 22449-335.

- B403010421 Forwards application for export license for minor nuclear export Ltr of assurance required W/o encl
 ZIMMERHANJ V Assistant Director for Export/Import & International Bafeguards B4/02/23 STOIBER.C R State, Dept of Bureau of Oceans & Intl Environ & Scientific Affairs 1p 22449 334
- 8403010425 License for Westinghouse to export four direction fuel tubes, top end plugs, bottom end plugs & stainless steel springs to Belgium ZimmeRMAN, J V Assistant Director for Export/Import & International Safeguards MMH-453 84/02/21 ip 22449 333
- 8403010432 License for Mitsui & Co. Inc to export 164,450 lbs 7r-2 trex to Japan ZIMMERMAN.J V Assistant Director for Export/Import & International Bafeguards 803-250 84/02/24 1p 22449-322
- 8403010454 Forwards application to export 200 Zircalog channel blank strips to Japan STREET. L. Edicw International Co WUI 64387 NRC -- No Detailed Affiliation Given ip 2244 4387 84/02/16 MOORE,N 22444 067
- --8403010454 Application for license to export 200 Zircaloy channel blank strips to Japan BTREET, L.L. Edlow International Co. ABEA B4/02/15 lp 22444 DAR
- B403010459 Application for license to export 10 kg thorium fluoride powder, containing 7 54 kg thorium to Italy CDLTON.E Cerac. Inc. B4/02/15 HEMBY, E NRC No Detailed Affiliation Given 1p. 22444 066.
- 8403010463 Application for license to export three BF3 proportional counters, two compensated ion chambers & two startup assemblies to Switzerland.

 HEETHERS H Westinghouse Electric Corp ZE 10597 84/02/21 1p 22438 282
- 8403010464 Ltr of assurance re export of 13 c U-235, contained in 325 q Usto Japan SHIRAKAHA,T Japan, Govt of 84/02/08 RAYMOND, J F Energy, Dept. of 1p. 22443 301.
- 8403010465 Forwards application to export 571 kg U-235,enriched to 3 40% U hexafluoride, to Japan SKIMA: 8 Mitsubishi International Corp (subs of Mitsubishi Corp.) 84/02/10. Assistant Director for Export/Import & International Safeguards 2pp 22443 298
- --8403010468 Application for license to export 751 kg U-235, enriched to 3 40% U hexafluoride to Japan SHIMA, B Hitsubishi International Corp (subs of Mitsubishi Corp) 84/02/21 ip 22443 300.
- 8403010466 Forwards application to export 20 g PU (metal) to Japan NAKAMURA, N Marubani America Corp (subs of Marubani Corp) 84/02/15 WRIOHT, B L Assistant Director For Export/Import & International Safeguards 1p 22438 286
- --- E403010467 Application for license to export 20 g Pu (meta) to Japan End use statement encl YAMADA.K. Merubeni America Corp (subs of Marubeni Corp) ZH--0119 84/02/15 3pp. 22438 287
- 8403010470 Forwards application to export slightly enriched U hexafluorids to Japan

 BHIMA, B Hitsubishi International Corp (subs. of Mitsubishi Corp.)

 HBA-5483-10, 84/02/10 Assistant Director for Export/Import &

 International Safeguards, 2pp. 22443:295
- --8403010473 Application for license to export 583 kg U-235, enriched to 3,40% U hexafiluoride, to Japan SHIMA, 8 Mitsubishi International Corp (subs. of Mitsubishi Corp.). HSA-5483-10. 84/02/10 ip 22443 297.
- 8403010471 Ltr of assurance re export of 302 kg U-235, contained in 9,993 kg U.to Japan BHIRAKAMA,7 Japan, Govt of 64/02/22. RAYMUND.J.F Dept. of 1p. 22438 362
- B403010478 Application to amend export license extending expiration date to 870331.
 WILBON, B. D. General Electric Co. BDW-12-84. B4/02/06 HEMBY, E O Office of International Programs, Director. 1p. 22498;361

- 8403810479 Requests Executi/e Branch position re Nissho Iwai American Corp application for amends to licenses to export increasing quantity of U authorized for export to Japan ZIMMERMAN.J V Assistant Director for Export/Import & International Safepuards 84/02/17 STOISER.C State, Dept of, Byreau of Oceans & Intl Environ & Scientific Affairs 1p 22443 287.
- 8403010484 Application to amend export licenses, increasing quantity of Australian origin hexafluoride, contained in fuel rods/assys, for export to Korea HERSCH.M M Westinghouse Electric Corp. MMH-460. 84/02/17 ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 2pp 22438 304
- 8403010487 Ltr of assurance re application for amend to license to export 16 84 g high enriched U metal.containing 15 7 g U-235 to Japan SHIRAKAMA:T Japan, Govt. of 84/02/22 RAYMOND, J.F. Energy. Dept of 1p 22438 360
- B403010490 Application for license to export 002 g CP-252 to India BENSON, EC Isotope Products Laboratories W/O 10274 83/11/02 1p 22438 359
- 8403010491 Requests Executive Branch position re 840221 application for license to export 1.000.000 Ci tritium in bulk gaseous form, to United Kingdom W/o encl ZIMMERHAN, J V Assistant Director for Export/Import & International Safeguards 84/02/23 STOIBER.C R State, Dept. of, Bureau of Oceans & Intl Environ & Scientific Affairs. 1p 22438,358
- 8403010495 Forwards application for export license for minor nuclear export to Canada Ltr of assurance required W/o encl ZIMMCRMAN.J V Assistant Director for Export/Import & International Safeguards 84/02/24 RAYMDND.J Energy, Dept of ip 22438 357
- 8403010497 Application for license to export 25 pieces of zirconium tubing matl to West Germany WILSON B D General Electric Co 8DM-28-84. 84/02/16 ip 22438 356
- 8403010502 Advises that Westinghouse 840221 application for license to export miscellaneous fuel assembly components to Italy for weld qualification tests issued w/o normal 15-day waiting period ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 84/02/24 Assistant Director for Export/Import & International Safeguards. 1p 22438:335
- 8402010505 Application for license to export 150 kg U dioxide:as powder or pellets to Taiwan # General Electric Co BDW-27-84 84/02/14 1p 22438 307
- B403010512 Forwards application to export 322 kg U-235, enriched to 2 40% U hexafluoride, to Japan SHIMA-S Mitsubishi International Corp (subs of Mitsubishi Corp) B4/02/10 Assistant Director for Export/Import & International Safeguards 2pp 22438 336
- ---8403010517 Application for license to export 322 kg U-235, enriched to 2 40% U hexafluoride, to Japan SHIMA, S Mitsubishi International Corp (subs of Mitsubishi Corp) HSA-5483-08 B4/02/01. lp 22438 338
- B403010522 Forwards newsletter on Contibus sys describing GEDAC plant monitoring & display sys per 840208 discussion & 840201 application for export license H/o encl WILSON, B D General Electric Co. BDM-21-84 84/02/08 PETERSON M R Office of International Programs, Director ip 22438 352
- --B403010546 Forwards application to export plant monitoring & display sys, consisting of three VAX & two GEDAC sys, to Finland. WILSON B D General Electric Co BDW-09-84 B4/02/01 WRISHT, B.L. Diffice of International Programs, Director ip. 22438 353
- --8403010950 Application for license to export plant monitoring & display sys, consisting of three VAX & two GEDAC sys, to Finland.

 ** General Electric Co BDH-08-84. 84/02/01 ip 22438 354
- 8403010539 Application to amend export license.extending expiration date to 870930, increasing quantity to 150 pieces & changing description of equipment.
 WILSON.B D General Electric Co. 84/02/17, HEMBY.E.O Office of International Programs, Director. 1p 22438 343

Ž.

- 8403010540 Application to amend export license, extending expiration date to 870331 HILSON.B D General Electric Co BDM-11-B4 84/02/06 HEMBY.E (Office of International Programs, Director 1p 22438 351.
- 8403010545 Application for license to export fuel assembly tubes, zirconium plugs, stainless steel springs & Inconel.to Italy HERSCH, M M Westinghouse Electric Corp 84/02/23 1p 22443-302
- 8403020015 Forwards Transnuclear, Inc 840202 application for amend to export license increasing quantity to 1.348 354 kg U-235, contained in 36,643 kg U ZIMHERNAN, J V Assistant Director for Export/Import & International Safeguerds 84/02/09 RAYMOND, J Energy, Dept. of ip 30401 004
- --8403020024 Application to amend export license, increasing quantity to 1.348 354 kg U-235, contained in 36,643 kg U HANNETT, B A Transnuclear, Inc RBU-394. 84/02/02 MODRE, R. N. Dffice of International Programs. Director Ip. 22491; 085
- 8403020079 Application for license to export miscellaneous designed primary pump components to Spain PEARSON. A Borg-Warner Corp 836-V-2258 84/02/06 ip 22491 188
- 8403020087 Application to amend export license, extending expiration date to 870331.

 HILSON, B D General Electric Co BDW-17-84. B4/02/06 HEMBY, E O Office of International Programs. Director ip 22491:183
- 8403020112 Forwards application to export spent nickel/U catalyst NUA-21:containing 7% U & 11% nickel.to Canada VANDERSTEEO.F Parkans International Inc. 84/02/14 MODRE.R.M. Office of International Programs, Director 1p 22491 177
- --8403020115 Application for license to export spent nickel/U catalyst NUA-21.containing 7% U & 11% nickel, to Canada * Parkans International, Inc 84/02/10 ip 22491,178.
- B403020151 License for Westinghouse to export miscellanceous fuel assembly components to Italy ZIMMERNAN.J V Assistant Director for Export/Import & International Safeguards B4/02/24 lp 22491'156
- 8403020154 License for Teledyne Wah Chang Albany to export 60,000 lb Zirceloy-2 trex to West Germany ZIMMERMAN.U Assistant Director for Export/Import & International Bafeguards 3350 (JFM) 84/02/21 ip 22491.155.
- 8403020157 Application to amend license to export, increasing quantity by add1 250 kg & extending expiration date to 860501 LUCENA,S Interactive Radiation, Inc 84/02/17 HEMBY,E 0 NRC No Detailed Affiliation Given ip 22491 149.
- B403020422 Application for license to export 164,450 lb Zr-2 TREX to Japan End use statement and * Mitsuf & Co (USA). Inc (subs of Mitsuf & Co , Ltd) 803-205. B4/02/03 2pp 22491 267
- 8403020428 Application for license to export compounds, containing deuterium, equivalent to 5 kg deuterium liquid over 2-yr period, to India 8 Sigma Chamical Co. D-112 84/02/07 ip 22491, 249
- 8403020451 Forwards application for export license for minor nuclear export. Ltr of assurance required IIMMERMAN, J V Assistant Director for Export/Import & International Bafeguards. 84/02/10 BTAIBER, C R State, Dept of, Bureau of Oceans & Intl Environ & Scientific Affairs 1p. 22491.197.
- --8403020453 Application to amend export license, adding ATLAS, AS as Fabricator/manufacturer of fuel elements. End use statement encl.

 HANNCTT, B A Transnuclear, Inc NUK-420. 84/02/02 MOORE, R. N. Office of International Programs, Director, 2pp 22491:198
- 8403050026 Amend 3 to GE export license, extending expiration date to B70331
 ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards DDW 14-84 84/02/10 ip 22496:345
- 8403050033 Application for license to export 187,750 lb Zr-2 & Zr-4 trex to Japan.
 EVIRA, M. Hitsui & Co. (USA), Inc (subs of Hitsui & Co., Ltd.).
 803-236 84/02/03 2pp 22527 330

- 8403050036 Application to amend license to export, extending expiration date to 851231 MOZNIAK, D.R. Carpenter Technology Corp. 84/02/01 HEMBY, E. Assistant Director for Export/Import & International Safeguards ip 22527 329
- 8403050039 Application to amend license to export, extending expiration date to 870331 HISBN B General Electric Co BDW-15-84 84/02/06 HEMBY, E O Office of International Programs, Director ip 22527 328
- 8403050044 Application for license to export two compensated ionization chambers, Type 6377, to France
 HEETHER, W H Westinghouse Electric Corp ZE40195 84/02/21 ip
- 8403050045 Amend 2 to GE export license, extending expiration date to
- 870331 ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguerda BDW 17-84 84/02/10 ip 22527 322
- 8403050047 Application for license to export 3,233 kg U-235, contained in 97,957 kg U, to Belgium HERBCH, M, M Westinghouse Electric Corp MMH-435 84/01/31 ip
- 8403050050 Application for license to export 225 kg U-235.as U oxida
- powder, to Belgium, HERSCH, M M Westinghouse Electric Corp MMH-454 84/01/31 1p
- 8403050188 Advises that Reuter-Stokes 840221 application for license to export two fission counters to Japan issued w/o normal 15-day waiting period 2IMMERMAN, J V Assistant Director for Export/Import & International
- Safeguards 84/02/24 Assistant Director for Export/Import & International Safeguards 1p 22528 192
- 8403050190 License for 8&W to export 13 g U-235, contained in 325 g U.
 - to Japan. ZIMMERHAN,J V Assistant Director for Export/Import & International Safeguards. 84/02/28 2pp 228/8 190
- 8403050193 License for Byron Jackson Pump Div to export miscellaneous specially designed primery pump components to Spain ZIMMERMAN, J. V. Assistant Director for Export/Import & International Bafeguards 836-V-2258 84/02/27 ip 22528:189
- 8403030209 License for Westinghouse to export three proportional counters, Model 6998, to Italy ZIMMERMAN, J V. Assistant Director for Export/Import & International Bafeguards ZE-40193 84/02/29 ip 22528 151
- 8403050213 Amend 1 to license for GE to import 17 kg U.contained in ,250 kg U-235 & 110 kg Pu metal clad fuel segments, from
- ZIMMERMAN, J. V TIMMERMAN, J. V Assistant Director for Export/Import & International Bafeguards 84/02/24. 1p 22528 144
- 8403050261 Application to amend licente to export, extending expiration date to 870331. HEMRY. F IN
- uste to B/USSI. MILSON, B.D. General Electric Co BDW-16-84 84/02/06. |-Office of International Programs, Director 1p 22527 184
- 8403050276 Amend 2 to GE export license, extending expiration date to
- B70331. ZINHERMAN,JV. Assistant Director for Export/Import & International Bafeguards. BDM-16-84. 84/02/10. 1p 22501:186
- B403050282 Amend 2 to QE export license, extending expiration date
- TO 87031
 ZIMMERMAN, J. V Assistant Director for Export/Import & International Safeguards. BDW 12-84. 84/02/10 1p. 22501,187.
- 8403050286 Amend 2 to QE export licenss, extending expiration date to
- 870331. STATEMENTAN, J. V. Assistant Director for Export/Import & International Safeguards BDW 12-84. 84/02/10 ip. 22501-206
- 8403050320 Forwards application for export license for minor nuclear export, Ltr of assurance required.

 ZIMMERMAN, J. V. Assistant Director for Export/Import & International Bafeguards 84/02/28 RAYMOND, J. Energy, Dept. of. 1p. 22501-275.
- --8403050327 Forwards application for license to export 13,129 kg U, contained in 322 kg U-235, to Jepan.

 SHIMALB. Mitsubishi International Corp. (subs of Mitsubishi Corp.) HBA-3483-08. 84/02/10 Assistant Director for Export/Import & International Safeguards. 2pp 22501:276

- ---B403050333 Application for license to export 13.127 kg U.contained in 322 kg U-235, to Japan SHIMA.S mitsubishi International Corp (subs of Mitsubishi Corp) 84/02/01 ip 22501 278
- 8403050358 Requests Executive Branch position re Marubeni America Co application for license to export 20 g for to Japan ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards 84/02/28 STOIBER C R Energy, Dept of 1p
- --8403050364 Forwards application to renew expired Licanse XBNM-1617 to export 20 g Pu to Japan NAKAMURA.N Harubeni America Corp (subs of Marubeni Corp) 84702/15 WRIGHT.B L. Assistant Director for Export/Import & Internationa) Safeguerds ip 22501 340
- --8403050366 Application for license to export 20 g Pu to Japan NAKAMURA:N Harubeni America Corp (subs of Marubeni Corp) ZH-Q119 84/02/15 3pp 22501 341
- 8403050359 Requests Executive Brench position re NRD Biv application for license to export 60.000 Ci tritium in bulk gaseous form to Switzerland W/o anci ZIMMERMAN.J V Assistant Director for Export/Import & Internationa
 - TIMMERMAN.J V Assistant Director for Export/Import & International Safeguards 84/02/27 STOIMER.C R State, Dept of, Bureau of Oceans & Intl Environ & Scientific Affairs ip 22501 337
- 8403050368 Forwards application for export license for minor nuclear export Ltr of assurance required ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards 84/02/28 RAYMOND.J Energy, Dept of 1p
- --B403050373 Forwards application for license to export slightly enriched U hexafluoride to Japan SHIMA.5 Mitsubishi International Corp (subs of Mitsubishi Corp) HSA-5485-10 84/02/10. Assistant Director for Export/Import & International Safeguards 2pp 22527 310
- --B403050376 Application for license to export 16,884 kg U.contained in 883 kg U-235, to Japan SHIMA.8 Mitsubishi International Corp (subs of Mitsubishi Corp) HBA-5483-10 B4/02/10 lp 22827 312
- 8403060035 License for Mitsui & Co. Inc to export 302 kg U-235, contained IN 9.973 to U. to Japan
 ZIMMERMAN, J V Assistant Director for Export/Import & International
 Safeguards MGK-2F1-R3 (B) 84/02/27 2pp 22528 329
- 8403040038 License for Reuter-Stakes, Inc to export two fission counters, Model R8-P4-0805-134, to Japan ZIMMERNAN, J V Assistant Director for Export/Import & International Safeguards D-1055 84/02/24 ip 22849 349
- B403060075 Application to amend license to export increasing quantity to 22,560 kg U for export to West Germany DUB018, D European Communities. Commission of RBU-428 B4/01/20 RAYMOND.J Energy, Dept of 1p 22528 292
- 6403040087 Forwards Westinghouse 840221 ltr withdrawing application for license to export four fission chambers to Argentina IMMERMANJ V Assistant Director for Export/Import & International Safeguards 840/02/27 STOIBER.C R State, Dept of, Bursau of Oceans & Intl. Environ & Scientific Affairs ip 22528 287
- B403040549 Requests waiving 15-day waiting period to expedite issuance of export license as shipment scheduled for B40301 PDMELL, C Reuter-Stokes, Inc 84/02/21 HEMOY, E. NRC No Detailed Affiliation Given 1p 22352 239
- --B403060573 Application for license to export 2 Model RB-P0-0805-134 finsion counters to Japan POHELL.C Router-Stokes, Inc B-0153 84/02/21 19 R2552 260
- 8403070004 Amend 2 to 9E export license extending expiration date to 870331 ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards. BDW 13-84 84/02/10. 1p. 22542 353
- 8403070353 Application to amend export license, extending expiration date to 870331.
 WILSON,B D General Electric Co. BDW-14-84 84/02/06 HEMBY,E D
 Office of International Programs, Director. 1p 22564 316.
- B403070377 Forwards Westinghouse B40217 application for amend to export license Assistance in obtaining required approvals per US/Australian Agreement requested ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards. B4/02/27. HART.T. Energy, Dept of ip 22567-194

22646 265

- --8403070381 Requests assistance in obtaining itr of assurance from Australia to reexport Australian-origin matl HERSCH.M M General Electric Co MMH-460 84/02/17 ZIMERMAN.J V Assistant Director for Export/Import & International Safeguards ip 22567 195
- 8403070424 Forwards application for export license for minor nuclear export Ltr of assurance required
 LINNERMAN, J V Assistant Director for Export/Import & International Safeguands 84/02/28 RAYMOND. J Energy, Dept of 1p
 22566 225
- --8403070425 Forwards application to export slightly enriched U herafluoride to Japan
 SHIMA, S Mitsubishi International Corp (subs of Mitsubishi
 Corp | HSA-5483-ii 84/02/17 Assistant Director for
 Export/Import & International Safeguards 2pp 22566 296
- --8403070426 Application for license to export 34,489 kg U herafluoride, contained in 1,104 kg U-235 to Japan GHIMA,8 Mitsubishi International Corp (subs of Mitsubishi Corp) HSA-5483-11 84/02/17 2pp 22566 298
- 8403080i15 Forwards application for export license for minor nuclear export Ltr of assurance required ZIMMERHAN,J V Assistant Director for Export/Import & International Safeguards 84/02/28 RAYMOND,T Energy, Dept of ip
- 8403140229 Forwards application for export license for minor nuclear export Ltr of assurance required

 IMMERMAN.J V Assistant Director for Export/Import & International Safeguards 84/03/04 STOIBER.C R. State. Dept. of, Bureau of Oceans & Intl Environ & Scientific Affairs 19 22637 350
- 8403140307 Forwards Transnuclear, Inc 840224 application to amend export license to include CERCA, Romano-sur-Isere, France, as intermediate consignee for fabrication of fuel elements ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 84/03/07 STOISER.C State, Dept of Suresu of Oceans & Intl Environ & Scientific Affairs ip 22635 313
- --8403140308 Application to amend license to include CERCA,Romano-sur-lsere,France.as intermediate consignee for fabrication of fuel elements
 HANNLTT.8 A Transnuclear, Inc NUK-408 84/02/24 MDORE
 Office of International Programs, Director ip 22635 314 MOORE, R N
- 8403140315 Forwards Marubeni America Corp application to export 24,355 kg U hexafluoride,containing 717 kg U-235 to Japan Assistance in obtaining required approvals per US-Australia Agreement requested
 7.IMMERMAN, V Assistant Director for Export/Import & International
 84-003/06 HART.T Energy, Dept of 1p 22635 298
- B403150129 Informs that license for Nt Industries. Inc to export 10,582 3 kg depleted U to Canada, issued u/o 15-day waiting period

 ZIMMERMAN, J V Assistant Director for Export/Import & International

 Safeguards 84/03/01 Assistant Director for Export/Import &

 International Safeguards ip 22646 353
- 8403150134 Forwards application to export 15 kg U.enriched to 5% U herafluoride to West Germany HARMON,D W Braunkoble Transport & Storage, Inc. HEX-EX-4 84/02/28 WRIGHT.B Assistant Director for Export/Import & International Safeguards ip 22646 349
- --B403150142 Application for license to export 15 kg U.enriched to 5% U hexafluoride, to West Germany.
 HARMON, D W Breunkohle Transport & Storage, Inc HEX-EX-4, 84/02/28 ip 22646 350.
- 8403150153 Application to amend export license, extending expiration date for 2 add1 yrs
 MORGENSTERNA Sigma Chemical Co 84/03/01 HEMBY, E Assistant Director for Export/Import & International Safeguards ip 22646 352
- 8403150158 Application to amend export license, adding miscellaneous special designed primary pump components for export to Spain PEARBUN.A Borg-Harner Corp. 84/03/01 HEMBY NRC No Detailed Affiliation Given 1p 22446 351
- 8403150169 Application to amend export license, dtd 820713, to include GERCA, Romans-sur-lisere, as possible intermediate consignee for fabrication of fuel elements
 HANNETT, B A Transnuclear, Inc NUK-408, 84/02/24 MOORE, R. N
 Office of International Programs, Director, 1p 22646 344.

- 8403150174 License for NL Industries, Inc to export 10,582 3 kg depleted U to Canada
 ZIMMERMAN, J V Assistant Director for Export/Import & International 84/03/01 2pp 22646 342
- 8403150195 Requests discontinuation of further investigation re export license Order canceled & export license no longer required TERMILLIGER L Mestinghouse Electric Corp 84/02/21 Assistant Director for Export/Import & International Safeguards ip
- B403150197 Forwards application to Export 3 9 kg natural thorium & 26 kg depleted U-238.as coated particles & oxide particulates to West Germany MDHRY.W R GA Technologies, Inc /General Atomic Co IEL-5086 84/02/29. ZINMERMAN, J, HENBY.E Assistant Director for Export/Import & International Bafeguards 1p 22646 263
- --8403150199 Application for license to export 3 9 kg natural thorium & 26 kg depleted U-238, as coated particles & oxide particulates, to Nest Germany MORY, H R GA Technologies, Inc /General Atomic Co IEL-5086 84/02/29 ip 22646 264
- B403150241 License for CERAC. Inc to export 7 540 kg thorium, contained in 10 00 kg thorium fluoride powder, to Italy ZIMMERHAN, J V Assistant Director for Export/Import & International Safeguards TLX 8429 84/03/07 2pp. 22649 352
- 8403140169 Forwards application to export 2,002 mCi Cf-252 in cormet wire to France HANNETT, B A Transnuclear, Inc TNP-443 84/02/29 MOORE, N Office of International Programs, Director ip 22662 263
- --8403160184 Application for license to export 2,002 mCi Cf-252 in cermet wire to France HANNETT,B A Transnuclear, Inc TNP-443 84/02/29 1p 22662 264
- 8403200305 Ltr of assurance notifying that employer name changed from Elsinore Shipyard to Atlas AS Installation & personnel identical DUBO18.D European Communities, Commission of 84/03/05 NEAL Assistant Director for Export/Import & International Safeguards
- 84032037; Withdraws application for license to export 29.33 g deuterium to South Africa NOVAKOVICH.D Air Products & Chemicals, Inc. 84/02/28, MARTIN, N Assistant Director for Export/Import & International Safeguards, 22708
- B403200373 Application for license to export 31,000 lb depleted U tetrafluoride.containing 23,281 lb depleted U to Canada POTTER.A NL Industries, Inc 84/02/27 MDORE,N Assistant Director for Export/Import & International Safaguards Ip 2270B 344
- B403200392 Informs that License XBNM-2098 may be issued. No math changed circumstances since issuance of License XBNM-2097 MODRE, R N Assistant Director for Export/Import & International Safeguards 84/02/22 Assistant Director for Export/Import & International Safeguards 19 22708 309.
- 8403200395 Executive Branch position re Westinghouse application to export 10 g U-235, contained in 220 g U, to Spain License should be issued should be issued
 DEVINE.J B State, Dept of, Bureau of Oceans & Intl, Environ &
 Scientific Affairs 84/03/06 SHEALJR Diffice of International
 Programs, Director 4pp 22708 305
- 8403200394 License for Natl Nuclear Corp to import 20 238 kg U, enriched to 4% U-235, from United Kingdom ZIMMERMAN, J Assistant Director for Export/Import & International Safeguards 84/03/09 1p 22708 304
- 8403200398 License for Braunkohle Transport USA to export 15 kg U-235 contained in 307 kg U to West Germany.
 ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards HEX-EX-4 84/02/29. 2pp 22707 359.
- 8403220197 Ltr of assurance re export of 757 kg U-235, contained in 21.932 kg U to Japan SHIRAKAWA.T Japan, Govt, of 84/02/28 RAYMOND, J. F. Energy, Dept of 1p. 22723 278
- B403220201 License for Westinghouse to export two compansated ionization chambers. Type 4377. to France ZIMMERMAN. J V. Assistant Director for Export/Import & International Bafeguards. ZE40175 B4/03/20 ip. 22723, 277

- 8403220230 Ltr of assurance re export of 15 kg U-235, contained in 307kg U, to the Netherlands, United Kingdom France & Nest Germany DUBOIS, D European Communities, Commission of HEX-EX-4 B4/02/28 RAYHOND, J Energy, Dept of 1p 22723 353
- 8403220264 Consents to proposed retransfer of nuclear matl to Japan Questions whether matl is of South African or Australian origin GORDON, R. Australia, Govt of 84/01/03 NIELBEN, C. Office of Nuclear Material Safety & Safeguards, Director HART, T. Energy, Dept of ip 22723 322
- Dept of 1p 22/23/32/2

 8403220279 Consents to proposed retransfer of nuclear mati to Japan Questions whether mati is of South African or Australian

origin GORDON,R Australia, Govt of 84/01/03 NIELSEN,C Office of Nuclear Material Safety & Safeguards, Director HART, T Energy, Dept of ip 22723 310

- B403220283 Amend 2 to GE export license, increasing quantity to 150 pieces tirconium tubing, revising description of matl & extending expiration date to B70730 ZIMMERMAN, J. Assistant Director for Export/Import & International Bafeguards BDW-26-84 84/03/08 1p 22723 309
- 8403220284 Ltr of assurance re export of 3 9 kg natural thorium & 0 26 kg depleted U-238 to West Germany DUBOIS.D European Communities. Commission of IEL-8594 84/03/07 RAYMOND.J Energy. Dept of 1p 22723 308
- B403220286 Amend 1 to Interactive Radiation, Inc export license, increasing quantity to 250 kg deuterium oxide ZIMMERMAN,J Assistant Director for Export/Import & International Bafeguards BL-4-81 84/03/07 ip 22723 307
- 8403220289 Forwards application for amend to export licenses for minor nuclear export Ltr of assurance required ZIMMERMAN, J Assistant Director for Export/Import & International Safeguards 84/02/27 HART, T Energy Dapt of ip 22723 303
- --84032R0274 Requests authorization to reexport Australian origin U
 hexafluoride to permit export license amend request to
 increase quantity of matl to be processed
 HERSCH,M M Hestinghouse Electric Corp MMH-460 84/02/17
 ZIMMERMAN,J Assistant Director for Export/Import & International
 Safeguards ip 22723 304
- 8403220299 License for QA Technologies, Inc to export 3 9 kg natural thorium & 0 26 kg depleted U. to West Germany ZIMMERMAN, J Assistant Director for Export/Import & International Bafeguards IEL-5086 84703709 ip 22723 348
- 8403220304 License for QE to expert 25 pieces rirconium tubing mat1 to West Germany ZIMMERMAN, J Assistant Director for Export/Import & International Bafeguards BDM-28-84 84/03/08 ip 22723 342
- 8403220314 License for Parkans Intl.Inc to export 15,876 kg natural U. contained in matl to be smelted for recovery of spent nickle content only, to Canada.

 ZIMMERMAN, J. Assistant Director for Export/Import & International Safeguards PISC-711 84/03/08 1p 22723 339
- B403220315 License for Westinghouse to export three proportional counters, two compensated ionization chambers & two startup assemblies to Suitzerland ZIMMERMAN.J Assistant Director for Export/Import & International Safeguards 84/03/09 ip 22723 345
- 8403220322 Forwards application to export Pu, containing approx 10-12X weight Pu-240.tq Switterland CEJA,8 N Energy, Dept of 84/03/02 Assistant Director for Export/Import & International Safaguards ip 22723 349
- --8403220324 Application for license to export Pu.containing approx 10-12% weight Pu-240 to Suitzerland CEJA,8 N Energy, Dept of. 79/12/20 ip 22723 350
- 8403220328 Application for license to export five Model RS-C4-1100-241 local power range assemblies to Sweden POMELL, C Reuter-Stokes, Inc. B-0152 84/03/02 ip 22723:351
- 8403230179 Discusses 0A Technologies, Inc 840227 application for export license to return small quantity of source math to West Ogrmany License issued w/o normal 15-day waiting period.

 ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 84/03/09. Assistant Director for Export/Import & International Safeguards. ip 22743 347

- 8403260011 Application to amend export lacense, adding NUKEM OmbH & CERCA as intermediate consignees DUBDIS,D European Communities, Commission of NUK-408 84/02/24 RAYHOND,U Energy, Dept of 1p 22763 332
- 8403260027 Forwards application to export 10 504 kg U-235,contained in 52 650 kg U-to various EURATOM countries
 HANNETT, B A Transnucleor, Inc NUK-442 84/03/05 MOORE, N
 Office of International Programs, Director 1p 22763 302
- --8403260030 Application for license to export 10 504 kg U-235, contained in 52 650 kg U, to various EURATOM countries End use statement encl
 HANNCTT.B A Transnuclear, Inc MUK-442 84/03/05 3pp 22763 303
- B400260037 Forwards application to export 24.850 kg U,enriched to 3 80% U-235.to Taiwan XIEL.GR Exzon Nuclear Co. Inc. (subs of Exxon Corp.) 84/02/23 ZIMMER Assistant Director for Export/Import & International Bafeguards 1p 22763 300
- --B403260042 Application for license to export 24.850 kg V.enriched to 3 80% U-235, to Taiwan KIEL,O R Exxon Nuclear Co , Inc (subs of Exxon Corp) 84/02/24 tp 22763 301
- B403260041 Ltr of assurance re export of 1,109 kg U-235, contained in 32,123 kg U.to Japan BHIRAKAWA.T Japan Govt of 84/02/28 RAYMOND.J F Energy, Dept of 1p 22763 297
- 8403260370 Ltr of assurance re export of 749 kg U-235,contained in 21,688 kg-U,to Japon BHIRAKAMA,T Japon, Govt of 84/02/28 RAYMOND,J G Energy, Dept of 1p 22775 255
- 8403280050 Forwards application for export license for minor nuclear export Ltr of assurance required ZIMHERMAN.J V Assistant Director for Esport/Import & International Safeguards 84/03/13 RAYMOND.J Energy Dept of Ip
- --B403280055 Application for license to export 52 650 kg U.in form of UF6, to EURATOM countries End use statement encl HANNLTF, B A Transnuclear, Inc. MUK-442 84/03/05 3pp 22812 347
- B402280057 Application to amend license to reexport three i 5 microgram sources of Cf-292 to Israel
 RAVENSCROFT.N Edlow International Co 84/03/09 HEMBY.E
 Assistant Director for Export/Import & International Safeguards ip
- B403280072 Executive Branch position re QE application to export U densitometer.w/Cs-137 source, for use in automatic measurement of fuel pellet density, to Spain License should be granted DEVINE, J B State, Dept of, Bureau of Oceans & Intl. Environ & Brientific Affairs 84/03/12 SKEA, J R Office of International Programs, Director 1p 22811 360
- 8403280147 Forwards Air Products 840228 ltr advising that export license for proposed shipment of deuterium of Bouth Africa origin no longer required ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 84/03/08 87018ER.C R State, Dept of, Bureau of Oceans & Intl Environ & Boientific Affairs 1p 22809 329
- --8403280151 Informs of withdrawal of export license application for shipment of 29 23 g deuterium to South Africa.
 NOVAKOVICH, D. Air Products & Chemicals, Inc. 84/02/28 MARTIN, N. Assistant Director for Export/Import & International Safeguards ig. 22809:330
- 8403280k30 License for Mitsubishi Intl Corp to export 749 kg U-235, contained in 21,688 kg U.to Japan ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards MBA-0483-04, 84/09/19 3pp 22789 357
- 8403280252 License for Reuter-Btokes Inc to export five Model RB-PG-0805-134 fission counters to Finland ZIMMERMAN.J V. Assistant Director for Export/Import & International Safeguards B-0046 84/03/13 ip. 22808 201.
- 8403280272 License for Mitsubishi Intl Carp to export 1 109 kg U-235, contained in 32.123 kg V, to Japan ZIMMERMAN,J V Assistant Director for Export/Import & International Bafeguards H8A-5483-05 84703/13 3pp 22808 065

- 8403280327 Amend 1 to Transnuclear Inc export license increasing quantity of U-235 to 793 3735 kg. contained in 22,560 kg U ZINMERNAN J V Assistant Director for Export/Import & International Safeguards RBU-428 84/03/12 lp 22797 359
- 8403280337 Informs that Amend I to License X8NM-2002 may be issued No matl changed circumstances since issuance of License X8NM-2043 SANM-2043 Assistant Director for Export/Import & International Safeguards 84/03/02 Assistant Director for Export/Import & International Safeguards 1p 22799 356

- 8403290129 Discusses Natl Nuclear Corp 840217 application for license authorizing import of up to 20 258 kg U.enriched to 4 0% U-235. From United Kingdom License should be issued MDDRE,R N Assistant Director for Export/Import & International Safeguards 84/03/08 Assistant Director for Export/Import & International Safeguards 1p 22822 218
- 8403290325 Requests Executive Branch position re Exxon Nuclear Co.Inc application for license to export SNM to Taiwan IIMMERNAN.J V Assistant Director for Export/Import & International Safeguards 84/03/09 STDIBER.C R State, Dept of, Rurray of Oceans & Int) Environ & Scientific Affairs 1p 22822 219
- 8403290327 Application for license to export 2,133 pieces Zircaley-4 thimble & instrument tubes to Japan DANGERTER. D H Sandvik Special Hetals Corp SSM-41095/41098 84/03/06 2pp 22818 361

- B403290340 Forwards DOE ltr requesting amend to export license to increase quantity of Pu to be exported from 3 13 kg to 3 5 kg M/o enc!

 ZIMMERMAN, J V Assistant Director for Export/Import & International Bafeguards 84/03/09 STOIBER.C R State, Dept of, Bureau of Oceans & Intl Environ & Scientific Affairs ip 22822 252
- 8403290403 forwards Mitsubishi Intl Corp 840217 application for license to export Australian prigin matl to Japan Requests assistance in obtaining required approvals, per US-Australia Agreement for Peaceful Uses of Nuclear Energy ZIMMERMAN, J V. Assistant Director for Export/Import & International Safeguards 84/03/12 HART, T Energy, Dept of 1p 22818 356
- 8403290404 Forwards ltr of assurance re export of five fission counters to Finland SYDIBEN.C.R State. Dept of. Burfau of Oceans & Intl Environ & Scientific Affairs B4/03/08 ZIMMERNAN.JV Assistant Director for Export/Import & International Safeguards 2pp 22822 188
- --8403270405 Ack receipt of retransfer assurance from Govt of Finland re export license application Due to error in translation, word "retransfer" was replaced w/ "retransformation" HEMBY.E O NRC No Detailed Affiliation Given B4/03/07 NRC No Detailed Affiliation Given ip 22822 190
- B403300311 Informs that license to export UFA heels to EURATOM countries being issued \$\to\$ 15-day waiting period ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards B4708/29 Assistant Director for Export/Import & International Safeguards 1p 22840 362

PERSONAL AUTHOR INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
AADLAND, J D	8403170246*	TOPREP	ANDERSON, C J	8403070242*	50~387 0	AXELRAD, J	8403190335	40-86B1
AAHODT, N D	B403130013	50-287 Q	ANDERSON, C J	6403070242W	50-354 Q	AXELRAD, J	8403220075	50-220 B
AAMODT, N O	8403220242	50-287 0	ANDERSON: C J	8403220071*	50-277 Q	AXELRAD, J	8403270114	50-237 0
ABELSON, H I	8403300250	50-333 P	ANDERSON, C J	B403290071*	50-271 Q	AXELRAD, M	8403300272	50-344 0
ABELSON, H. I	8403300250	50-333 P		8402030344*	50-206 F	AXELRAD, M	8403300272	50-344 G
ABELOUM, M. I	8403300232	50-333 P	ANDERSON, C K	6402030344*	50-20a F	HACLEMAN	54053G0E7E	
ACGUARIO, W J	8403040226*	50-322 T	ANDERBON, C R	B403040124*	50-244 P	AXELROD, D AXELSON, W	8403020233 8403200284	50-322 0
ACGUARID. H J	8403060246*	50-322 T	ANDERGON	19005E048	50-284 S	AXELSON W	8403300045	I&E
ADAM: W. J	8005280998#	FÖIA	ANDERSON, J J	8403260257	50-286 8	AXELSON, W L	B403010336	50~454 Q
ADAM, N. J.	8403080108*	FOIA	ANDERBON, M T	8403R70181*	20-585 d	AXELSON, W. L.	8403040185	50-263 F
ADAMS, F T	8403080223*	50-316 P	ANDERSON, P H	8403020182	50~400 O	MACLEUM W. L	0402040103	•
ADAMS, R.E.	8403150219	NURE9 50-336 P	ANDERBON, P H	8403020182	50-40D Q	AXELSON.W.L. AXELSON.W.L.	84030800B9 8403080257	50-305 F 1&E
ADATO, M	8403080344		ANDERSON, P. H.	8403020188*	50-400 Q		8403130145	50-331 F
ADENBAM, E.	6403010265*	50-327 A	ANDERSON P H	#8810Z0E018	50-400 G	AXELBON: W L	8403190211	50~182 G
ADENBAM, E &	B105180434*	50-460 A	ANDERSON, P H	8403130156	50-400 G	AXELBON: W L	8403190239*	50-331 0
ADENSAM, E G	8202180456*	50-460 F	ANDERSON, P H	8403130154	50-400 G	AXELBON; W. L.	B403140534*	20-331 d
ADENSAM. E O.	8202260171*	50-460 C	ANDERSON, R. B.	#SE0070035#	CONTRACT	AXELSON, W 1.,	8403240019 8403010098*	50-346 O CONTRACT
ADENSAM, E O	8302250083*	50-513 A	ANDRUS, N J	8403200325*	40-4492	BABE, K	6403140077*	50-155 G
ADENSAM E O	6403120210	50-369 P	ANDRUS, N. J.	8403220045	40-4492	BACHMANN, R G BACHMANN, R G	0403140077*	50~155 W
ADENSAM, E. C	8403120213*	50-369 P 50-316 P	ANSELL,E	6403080174	50-413 A	DAER, R E	8403260250*	50-382 Q
ADES, M. J	8403080216*	50-316 P	ANTHONY, R L	8403170132	50-352 G	מאבתיות ב	H402E00400*	
AHEARNE, J	B403050042*	FOIA	ANTHONY, R L.	6403170132	50-352 Q	BAER, R. L	8203120197*	FOIA
ALBERT, W. Q	8402140036#	50-528 G	ANTHONY, R L	640319013B¥	50~352 0	BAER, R L	8403010272*	FOIA
ALBERTIN, R D	8403060226#	50-322 T	ANTHONY, R L	B403170138*	50-352 0	DAILEY, R J	@403220010*	50-272 G
ALBERTIN, R D.	8403060246*	50-322 T	ANTHONY, R L	8403190142*	50-353 Q	DAIR. O	8403010355	50-344 8
ALDEN: H. M	.8403050117	50-277 R	ANTHONY, R. L.	#403190142*	50-353 G	BAIR, G	8403260216	50~344 8
ALDEN, W. M.	8403170178	50-277 R	ARCHITZEL, R	B403220103*	50-309 G	BAIRD, J.B.	8403130402*	50-313 0
ALESSI, T A.	8403060177*	50-341 Q	ARIAB, J.	8402270125	50-250 B	BAIRD, J B	840319028B*	50-313 Q
ALESSO, H P	8303080290#	50-286 P	ARIAS, J	640319009	50-251 9	BAKANAUSKAS, J	8403140172	PR
ALEBSO, H. P.	8403050029*	50-286 P	ARIAB, J	B403220104	50-250 8	DAKANAUSKAS, J	8403290321	PR
ALESSO, H P	8403050035*	50-286 P	ARLOTTO: 9. A	B403270018*	FOIA	DAKER, C	8403280110	50-250 F
ALESBO, H P.	8403050038*	50-286 P	ARLOTTO, G. A	8403270048*	FOIA	DAKER, E	0403010430*	50-423 Q
ALEXICH H P	8403060191	50-316 P	ARLUTTO: 9. A.	B403270068#	FOIA	BAKER.K R	Ø403200217	50-316 B
ALEXICH, M. P	8403060195	50-315 P	ARTHUR, J	8402170325	WASTE MOT	BAKER, P E	8403230015	50-373 8
ALEXICH, M. P.	8403060315*	50-315 Q	ASH, E B	8403150315	HASTE MOT	BAKER, P. E	8403230017	50-373 6
ALEXICH, M P.	8403080169	50-315 R	ASHBURN, D. J.	8403060367	TOPREP	BAKER, P. E	8403230027	50-373 S
ALEXICH, M, P	8403080214*	50-315 0	ASHOURN, D. J.	B403040375	TOPREP	DAKER, R	8403010241	50-333 \$
ALEXICH, M. P	8403130202	50-315 F	ASHBURN, D. J.	B403060377	50~397 J	BALCH, L.	8403300152	50-155 R
ALEXICH, M. P	B403160034	50-315 G	ABHE, F	8211110578	50-27 B	BALCH, L. L	Ø4030200BB	50~155 R
ALEXICH, M P.	8403200210	50-316 P	ASHE, F	8211150076	50-272 B	BALDA98ARRA, C	6403140180*	50-373 F
ALEXICH, M P	8403200223	50-315 P	ABHE, F	8403230125	50-317 8	BALDASBARRA, C.	B403140184#	50-373 F
ALEXICH, M P	8403220050*	50-315 Q	ASHE, F.	8403230128*	50-317 8	BALDWIN.D.R	8403010462*	CONTRACT
ALEXICH, M. P	8403230138*	50-315 0	ABBELSTINE, J. K.	6403260150*	50-289 T	BALLARD, M F	8403200062*	50-217 G
ALEXICH, M P.	B403260002	50-315 P	AULUCK, R.	8403050292	50-397 P	BALLARD, R. L.	8203120058#	50-460 C
ALEXICH, M. P	8403260178	50-315 F	AUSTIN, Q.	8403190156	50-275 R	BALLENGER, V N	8403140154	PR
ALEXICH, M. P.	B403270047	50-315 G	AUSTIN, P N.	B403010102*	FOIA	BALLINGER, P L.	8403020083	50-298 R
ALEXICH, M P.	8403270110	50-316 P	AXELRAD, J	8403010363	50-289 0	BALLINGER.P L	8403300150	50-278 R
ALLEN, M. T.	8403010135	50-324 B	AXELRAD, J.	B403010323	1&E	BANGERTER, D H	8403270327	XPORTLIC
ALLEN, M. T	8403210139	50-325 S	AXELRAD, J	8403050094	IRE	BARAKIA J.	B403170172*	50-329 A
ALLEN, R. D	8403130244	0A999	AXELRAD, J.	8403060119	146	BARAN, R	B403020128	50-219 R
ALLENMAN, S. A	8403050253*	50-382 F	AXELRAD, J	8403080213	50-259 G	BARAN, R.	B403300001	50-219 R
ALL980D, 9. 0	8403230057	NUREO	AXELRAD, J.	8403130408	I&E	BARI, R A	8403010041*	FOIA
ALTERMAN, I. B.	B009250345*	50-312 P	AXELRAD, J	6403130445	50-261 5	BARKHURBT R P	8403050253*	50-382 F
ALIERMANII, B.	8403010500*	COMMISSION	AXELRAD, J.	8403150073	50-247 S	BARKHURST, R. P	8403260154	50-382 A
AMY, Q. D	8403190234*	70-371	AXELRAD, J.	B403160001	IAE	BARNEB, C	8403260116	40-1478
ANDERSON, C.	8403160157*	50-272 Q	AXELRAD, J	8403160001	50-331 S	BARNEB, I.	B403190340*	0A777
DUPEKBOUI O'	~10316010*	~~ A/A ~	TARLES O	CACOTOCO.				

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGORY
Barnes, I Barnes, P Barnes, P Barnes, P Barnes, P Barnes, P	8403270241+ 8403050119 8403260182 8403260196 8403270111	GA779 50-237 P 50-295 P 50-237 G 50-454 G	Bayne, J P. Bayne, J P	8403170274 8403200074 8403240171 8403270185 8403270180	50-284 F 50-333 P 50-333 P 50-333 F 50-286 P	BISHOP, T W BISHOP, T W BISHOP, T W BISHOP, T W BISHOP, T W	8403130343 8403130136* 8403130144* 8403130132* 8403130139*	50-312 Q 50-275 T 50-275 T 50-275 T 50-275 T
BARNETT, J E Barrik Barrik P Barrik P Barrik P	8403010293 8403290234* 8403070072* 8403070248* 8403160240*	70-1621 50-302	Bayne, J P Dazin, J P Beach, F J Beare, A N Beaudoin, D E	8403290152 8403280240 8403130091* 8403300342 8403220025	50-286 P CONTRACT 50-322 G NUREO 50-329 A	BISHOP, T W BISHOP, T W BISSETT, P BITOWF, T B BIXBY, D T	8403190114# 8403270135 8403290150# 8403240253# 8403120180	50-275 0 50-528 0 50-252 0 50-252 E TOPREP
DARRIK P BARRIK P BARRIK P BARRETTIL BARRETTIL	8403160372* 8403270220* 8403270320* 8403060103 8403060110	50-321 0 50-259 0 50-335 0 50-320 8 50-320 8	BEAVER, JR BECHHOEFER, C BECHHOEFER, C BECHHOEFER, C BECHHOEFER, C	8403130118 8403130114 8403130014 8403150039 8403220238	50-320 F 50-329 0 50-498 0 50-498 0 50-498 0	BLACK, M. T BLACKBURN, J D BLAKE, E L BLAKE, E L BLAKE, E L	8403260347# 8403130207# 8403070025 8403070025 8403070129	HASTE NOT 50-400 G 50-287 G 50-287 G \$0-287 G
BARRETT.L BARRETT.L DARRETT.L H BARRETT.L H BARRETT.L H	8403050144 8403050435 8403120253 8403120334 8403130467	50-320 G 50-320 R 50-320 R 50-320 G	BECHHDEFER, G BECICA, I J BECKHAM, J T BECKHAM, J T. BECKHAM, J T	8403220244 8403120244* 8403090067 8403090187 8403130346	50-327 G 50-335 G 50-321 F 50-321 P 50-321 F	BLAKE, J J, BLAKE, J, J BLAKE, J, J BLAKE, J J BLAKE, J J	8403070105* 8403070263 8403160037 8403160120* 8403160178*	50-400 0 50-348 8 50-364 8 50-367 0 50-324 0
Barth.c A Barth.c A Darth.c A Barth.c A Barth.c A	8403190053 8403190058* 8403190141* 8403210120 8403270321	50-400 G 50-400 G 50-400 G 50-400 G 50-400 G	Beckham, J. T Beedloh, P. A Beghian, L Behrens, D. W Beinecke, P. J.	8403270194* 8403230207 8403300169* 8403230141* 8403270109	50-366 G NUREO 50-223 G 50-275 R 50-275 S	BLAKE, J J. BLAKE, J J BLAKE, J J BLAKE, J J BLAKE, J J	8403160279* 8403160363* 8403160383* 8403190247* 8403290173*	50-370 Q 50-413 Q 50-370 Q 50-254 Q 50-400 Q
Darthic A Barton, J M Bartter, W D. Daskin, K P, Baskin, K P	8403270333 8403070264 8403300325 8403070177 8403070227*	50~400 0 50~320 F NURE9 50~361 P 50~361 P	Beinecke.p J. Belible.g A. Bell.c R. Bell. J Bell.n	8403270265 8403160319* 8403230216 8403130471* 8403220049	50-295 S 50-413 G 50-537 A 50-320 G 50-460 G	BLAKE, J J BLANCHARD, B BLANCHARD, B BLATT, M BLATT, M	8403290219* 8403020277 8403190343 8403020155 8403130405	50-321 Q 50-320 P 50-508 D 50-247 R 50-247 S
Baskin, k p Baskin, k p Baskin, k p Bassij t Bassett, h	8403070233* 8403070236* 8403220018 8403020215* 8403010528	50-361 P 50-361 P 50-206 F FOIA CONTRACT	BELL, N BELL, N E BELL, S. BELLAMY, R BELLAMY, R	8403280211 8403230177 8403020240* 8403130208 8403130456	50-482 Q NUREG FGIA 50-219 8 50-309 8	BLATT, M BLATT, M. BLIND, A A BLOCH, P. B BLOCH, P. B	8403210154 8403270166 8403130121 8403080110 8403070077	50-247 8 50-247 R 50-315 F 50-155 9 50-448 9
DASSIN, N BASSOLL F BATEMAN, W H DATES, J W	8403020187* 8403020191* 8403130039 8403220089* 8403180380*	FD1A FD1A 50-318 S 50-354 G 70-1113	BELLAMY,R,R BELMORE,C 1 BELSER,A L BEMIS,P R BEMIS,P.R	8403070070 8403230112* 8403200015 8403070199* 6403070310*	50-219 G 50-219 R 50-352 G 50-400 G 50-324 G	BLOCH, P B BLOCH, P B BLOCH, P, B BLOCH, P, B BLOCH, P, B	8403090132 8403190002 8403190028 8403200065 8403280342	50-155 9 50-445 9 50-445 9 50-445 9 50-445 9
BAUER, E Q BAUNACK, W BAUSER, D B DAUSER, D B BAUSER, D B	B403150140* 8403070287* 8403200046 8403200066 8403210187	50-277 P 50-287 G 50-287 G 50-287 G 50-287 G	Bemis, p. r Bemis, p. r Benardya, v Benardya, v Benardya, v	8403160385* 8403270072* 8203020137* 8203120075* 8205270420*	50-261 G 50-324 G 50-460 F 50-400 E 50-400 E	BLOCH, P. B BLOCK, B BLOOM, J. Q BLOOM, J. Q BLOOBOM, J. N	8403300242 8403270338* 8403240341 8403240341 8403150102	50-440 9 50-400 9 50-456 9 50-456 0 40-8452
BAUSER, D. B. GAUSER, M. A. BAUSER, M. A. BAXTER, T. A. BAXTER, T. A.	8403210187 8403190171 8403190171 8402290081 8403070134	50-289 0 50-250 0 50-250 0 50-400 0 50-400 0	BENAROYA. V BENDER, M. BENDER, M BENDER, M BENDER, M	8211110461* 8403280316 8403280316 8403280341 8403280341	50-400 E ACRB ACRB ACRB ACRB	BLOSSOM, J N BLOUGH, A R BLOUGH, A R BLUBAUGH, R E. BLUBAUGH, R E	8403150224 8403010322* 8403150043* 8401120171 8403150280	40~8452 50~277
BAXTER,T,A BAXTER,TA BAXTER,TA BAXTER,TA BAXTER,TA	8403070134 8403070225 8403070225 8403140018 8403140018	50-400 G 50-400 G 50-400 G 50-400 G 50-400 G	DENNETT, D D BENBON, E C BERG, R £ BERGAN, G W BERKOW, H N	8403150031 8403010490 8403240213 8403270054 8003240202*	50-206 F XPDRTLIC 40-8585 50-237 B 50-308 A	BLUBAUGH:R E BGARDMAN:J R BDARDMAN:J R. BOGDEN:G BGGGB:R B	6403230247 6403050184* 6403260232* 6403150215 6403060324*	40-3453 50-482 0 50-313 0 40-8684 50-213 P
BAXTER,T A. BAXTER,T A BAXTER,T A BAXTER,T A BAXTER,T A	8403200030 8403200030 8403210175 8403210175 8403210193	50-400 G 50-400 G 50-289 G 50-289 G 50-289 G	Bernabel, L Bernard, H Bess, J e Betcher, J L. Bettenhausen, L.	8402140014 8403070412 8403260177* 8403010018 8403150034*	50-528	BOGOS, R S BOHL, L S. BOITEL, E C. BOLCH, M E BOLLING, L A	8403070259# 8403130064# 8403060405 8403280102 8403080078#	50-348 P GA979 50-30 R 50-413 F FDIA
BAXTER.T A BAXTER.T A BAXTER.T A BAXTER.T A BAXTER.T A	8403210193 8403260328 8403260328 8403260348 8403260348	50-287 0 50-400 0 50-400 0 50-400 0 50-400 0	BETTENHAUSEN.L. BEHLEY.E K BIBB.H E BIBB.H E. BIBB.H E	8403290191* 8403200003 8403160268* 8403290132* 8403290180*	50-289 0 50-317 R 50-335 0 50-335 0 50-335 0	BOLON, A. E BOOKER, J. E BOOKER, J. E BOOKER, J. E	8403170088* 8403080370 8403010073 8403010228 8403010321	50-123 0 50-425 0 50-458 8 50-458 8 50-458 A
BAXTER, T A BAXTER, T A BAXTER, T, A BAXTER, T A BAXTER, T A	8403240354* 8403240354* 8403270327 8403270327 8403270386	50-400 G 50-400 G 50-400 G 50-400 G 50-269 G	Bicehouse, H Bicehouse, H Bidinger, G H Bidinger, G, H	8403130456 8403150017# 8403220249 8403260084# 8403300297#	50-309 8 50-219 0 70-371 70-1257 70-1257	BOOKER, J E BOOKER, J E BOOKER, J E BOOKER, J E	8403010379 8403020294 8403080078 8403060320 8403070010	50-458 B 50-458 A 50-458 A 50-458 S 50-458 A
Baxter, T A Bay, J. H Bayless, P D Bayless, P D	8403270386 8403200021 8403200021 8403280117 8403280124	50-289 0 50-142 0 50-142 0 50-368 5 50-368 8	BIELAWSKI,A P BIELAWSKI,A P BIEMILLER, B BIEMILLER, B A BIRD, B K	8403020181 #403020181 8403020065 8403300162 8403060533	50-454 0 50-454 0 50-309 R 50-309 R NURE9	BOOKER, J. E BOOKER, J. E. BOOKER, J. E. BOOKER, J. E.	8403070052 8403070061 8403070062 8403080378 8403130069	50-458 A 50-458 A 50-458 E 50-458 A 50-458 E
BAYNE, J. P BAYNE, J. P BAYNE, J. P. BAYNE, J. P.	8401200078 8403020327 8403020351 8403070287 8403120024	50-286 V 50-333 F 50-333 P 50-286 P 50-333 P	BISHOP, T. W BISHOP, T W BISHOP, T W BISHOP, T W BISHOP, T W.	8403040025 8403040131 8403040138 8403040207 8403040341	50-206 @ 50-275 @ 50-275 @ 50-275 @ 50-344 @	BOOKER, J. E. BOOKER, J. E. BOOKER, J. E. BOOKER, J. E. BOOKER, J. E.	8403130175 8403130190 8403130264 8403130486 8403160310	50-458 8 50-458 A 50-458 B 50-458 F 50-458 8
PAYNE, JP. BAYNE, JP. BAYNE, JP. BAYNE, JP. PAYNE, JP.	8403130162 8403130466 8403140153 8403160007 8403160017*	50-284 F 50-333 G FR 50-286 P 50-286 P	BISHOP, T W. BISHOP, T W. BISHOP, T. W. BISHOP, T. W. BISHOP, T. W	8403040401 8403080254 8403080266 8403080274 8403080421+	50-312 0 50-588 0 50-397 0 50-312 0 50-275 8	BOOKER, J E BOOKER, J E BOOKER, J E BOOKER, J. E BOOKER, J E.	8403170017 8403200034 8403210067 8403220207 8403260271	50-458 E 50-458 A 50-458 A 50-458 A 50-458 A

PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGOR
BOOKER, J. E BOOKER, J. E BOOKER, J. E BOOKER, J. E BOOKER, J. E BOOKER, J. F.	8403270026 8403270037 8403270045 8403270201 8403150073*	50-458 8 50-458 8 50-458 8 50-458 8 50-273 @	BRIGHT, G O BRINKMAN, B BRITT, L F BROCK, B L BRODEUR, R 1	8403300262 8403200113 8403010220 8403270221* 8403060187	50-440 Q 50-334 S 50-322 Q 70-1257 QA999	BURNETT R F BURNETT R F BURNETT R F BURNETT R F BURNETT R F	8403010033* 8403010037* 8403010042* 84030503A3 8403080420*	ACRS ACRS ACRS 70-143 50-275
BORDENICK, B M BORDENICK, B M BORDENICK, B M BORDENICK, B M	8403140037 8403140100 8403140114 8403140136 8403140135	50-322	BRODEUR, R 1 BRONS, J C BRONS, J C BRONS, J C BRONS, J C.	84032700B7 8403120152 8403130256 8403150047 8403150050	6A999 50-286 S 50-286 R 50-286 S 50-286 S	BURNB, E M BURNB, B BURSTEIN, C H BURHELL, B B BUSH, K J	8403120029* 8403080422* 8403080130 8403300249 8403050315	50-275 50-275 50-382 50-445 WASTE MG
BORDENICK, B M BORDENICK, B M BORDENICK, B M BORDENICK, B M BORDENICK, B M	8403140158 8403140161 8403190124 8403190169 8403210100	50-322	Brone, J C Brone, J C Brone, J C Brone, J, C.	8403170265* 8403210047 8403210113 8403260071 8403260257	50-284 G 50-284 S 50-284 R 50-286 S 50-286 S	DUSLIK, A J BUSH, K J BUSH, K J	8403050318# 8403050319# 8403050322# 8403050323# 8403010041#	WASTE HO WASTE HO WASTE HO WASTE HO FOIA
BORDENICK, B M BORDENICK, B. M. BORST, F. J. BORST, F. J. BORST, F. J.	8403280340 8403280362 8403010118 8403040307 8403130177	50-322 0 50-322 0 50-267 R 50-267 R 50-267 P	erdns, J.C. Brons, J.C. Bronski, D Bronzan, B Brown, C.H.	8403300159 8403300175 8403120038 8403270352 8403120145#	50-284 R 50-284 0 50-204 H 50-275 9 50-263 0	BUTCHER, R C BUTCHER, R C BUTCHER, R C. BUTLER, B D BUTLER, B D	8403070136* 8403070263 8403160282* 8403070163* 8403160225*	50~395 50~348 50~259 50~327 50~327
Bosnak, R. J. Bosnak, R. J. Bouchey, G. D. Bouchey, G. D. Bournia, A.	B104300020* 8403070390* 8201190297* B20B120240* 8403140350	50-397 A 50-315 P 50-397 F 50-397 F 50-374 F	97,044, E. J. BROWN, E. J. BROWN, H. H. BROWN, H. H. BROWN, J. M	8303170014 8303170017* 8403040338 8403040338 8403020095*	50-315 8 50-315 8 50-322 6 50-322 8 FOIA	BYRD, R. BYRD, R BYRD, R BYRD, R BYRD, R	8403130192 8403130274 8403190033 8403200017 8403260244	50-416 50-416 50-416 50-416 50-416
BOURNIA, A. BOVELL, C. R. BOWERB, H. BOWMAN, C. E. BOWMAN, D. C.	8403300226 8403300342 8403280225# 8403120027 8403210001	50-374 P NUREQ 50-482 G 50-293 R 40-4920	BLOMN'N W BLOMN'N W BLOMN'N W BLOMN'N W	8403020101* 8403020113* 8403020116* 8403020137* 8403020142*	FOIA FOIA FOIA FOIA FOIA	BYRD. R BYRD. R BYRD. R BYRD. R BYRD. R	9403300027 8403300037 8403300113 8403300117 8403070071	50-416 50-416 50-416 50-416 50-416
BOWMAN, D. C. BOYD, D. BOYD, D. BOYD, D. BOYD, D.	9403300008 8403130275 8403130336 8403190091 8403220165#	40~4920 50~344	8 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	8403020172* 8403020176* 8403020177* 8403020187* 8403020191*	FOIA FOIA FOIA FOIA FOIA	BYRD:R W CAHILL:W J. CAHILL:W J. CAHILL:W J	8403200064 8403220114* 8403130393 8403130448* 8403270076*	50-414 50-341 50-458 50-458 50-458
BDYER, L ROYER, R. E. BOYER, R. E. BOYER, V. S. BOYER, V. S.	8403200033 8403120134 8403130316 8403010144 8403020105*	50-324 F 50-416 S 64999 50-352 E 50-352 Q	R GNONN T W BUDIN' Y' W BUDIN' Y W BUDIN' Y' W	8403020179# 840302020# 8403020201# 8403020208# 8403020210#	FOIA FOIA FOIA FOIA FOIA	CAHILL, W J. CAHN, A L CALDWELL, R A CALDWELL, R A CALDWELL, R A	8403280032 8401130343 8403260167* 8403260214* 8403260240*	50-458 TOPREF 50-247 50-445 50-298
BOYER, V S BOYER, W, J. BRADFORD, W H. BRADFORD, W H BRADHAM, O, S	8403270017 8403270048* 8403160284* 8403270103* 8403130397	50-352 G 50-352 T 50-348 G 50-348 G 50-395 F	BRDWN, J. M. BROWN, J. M BROWN, R. T BROWN, R. W BRDWN, W.	8403020227* 8403020251* 8403080180* 8403210004 8403050228	FOIA FOIA FOIA PR 70-420	CWABBEFFE T CWFEDAVE C D CWFEDAVE C D CWFFEDAVE G M	8101300020* 8101300025* 8403010119 8403080408 8403060249	FOIA FOIA 50-312 , 50-206 (50-295
BRADLEY, E. J.	8403020257 8403150036 8403150140* 8403210045 8403260054	50-352 A 50-352 C 50-277 P 50-277 P 50-277 J	BROWN, W BROWN, W. B. BROWN, W. B BROWN, W. B. BROWN, W. B.	8403050367 8403050179 8403050205 8403050220 8403050361	70-2988 70-27 70-27 70-143 70-27	CAMPBELL, R D CAMPBELL, R M CAMPBELL, R M CANTER, H CANTER, H L	8403200152* 8403270175 8403150034* 8403060215 8403060027*	50-423 . 50-387 50-388 : 50-341 50-204 :
BRADLEY, E J. BRADLEY, F J BRADLEY, R. D BRADY, J. A. BRADY, J. A	8403260333 8403130236 8403300099 8403030131 8403080178	50-352 0 PR PT21 50-320 F 50-320 F	Brown, w B Browning, r E. Browning, r. E. Browning, r. E. Brownlee, v L	8403050365 8403020185 8403190422 8403220218 8403080384*	70-2955 WASTE MOT WASTE MOT 27-39 50-424 Q	CANTER, H L CANTER, H L CANTER, H L CANTER, H, L CANTER, H, L	8403060142* 8403060143* 8403060146* 8403060147* 8403080277*	50-275 (50-275 (50-275 (50-275 (50-312 (
BRADY, J.A. BRADY, J.A. BRAMLETT, L. S BRAMLETT, L. S. BRANCH, M. W.	8403140088 8403270073 8403020081 8403300164 8403270274*	50-287 F 50-320 F 50-348 R 50-348 R 50-338 Q	BROUNLEE, V. E. BRUNNER, J. E BRUNNER, J. E BRUNNER, J. E	8403290108* 8403050241* 8403060073 8403120037 8403190166	50-269 0 50-271 S 50-329 0 50-329 0 50-329 0	CANTRELL, F 8	8403070088* 8403079136* 8403160186* 8403160282* 8403160284*	50-395 (50-395 (50-259 (50-259 (50-348 (
BRANT, K. T. BRAUN, D J. BREJSMEISTER, F. BRENNER, L. BRENNER, L	8403130295 8403080216* 8403120010* 8403060097 8403190040	50-317 8 50-314 P 50-275 9 50-352 9 50-352 9	BRURG, R L BRUSVEN, A D BRYANT, J. BRYANT, J BUCKLEB, R.	84030602B5 8403290115 8403070369* 840329010B* 8403090015	50-263 F 50-263 I 50-267 Q 50-267 Q FGIA	CANTRELL: F 8 CAPHTON, D. L. CAREY, J J CAREY, J J. CAREY, J J	8403270103* 8403050245* 8403020086 8403060297 8403070243	50-348 ° F01A 50-334 ° 50-334 V 50-334 R
BRENNER, L. BRENNER, L. BRENNER, L. BRENNER, L. BRENNER, L.	8403190153 8403200070 8403270045 8403280331 8403280350	50-352 0 50-352 0 50-352 0 50-352 0 50-322 0	BUCKLEY, B. C. BUCKLEY, B. C. BUCKLEY, B. C. BUHL, T. BURD, R. B.	8403020084 8403020076 8403280070 8403050107 8403130180	50-400 M 50-400 M 50-400 A State Frog 50-508 D	CAREY, J. J. CAREY, J. J. CAREY, J. J. CAREY, J. J.	8403070269 8403070344* 8403120172* 8403170276 8403170317*	50-334 R 50-334 G 50-334 G 50-334 R 50-334 R
Brenner, L. Brenner, L. Brenner, L. Brenner, L. Brewer, R.	8403280354 8403290373 8403290393 8403300009 8403020241*	50-352 0 50-322 9 50-352 0 50-352 T 50-250 0	BURDOIN, J, BURDOIN, J F, BURDOIN, J, F, BURGER, F, J, BURGEBS, J L,	8403270139* 8403060223* 8403060406* 8403190086 8403020132*	50-528 0 50-323 0 50-312 0 50-271 R FDIA	CAREY, J. J. CAREY, J. J. CAREY, J. J. CAREY, J. J. GAREY, J. J.	8403260160 8403270215 8403280017 8403300062 8403300181	50-334 R 50-334 F 50-334 F 50-412 A 50-334 R
BREY, H. L. BREY, H. L. BREY, H. L. BREZINBKI, M. B. BRICH, R.	8403010304 8403130376 8403220138 8403140183* 8403130236	50-247 Q 50-247 R 50-247 F 50-373 F PR	BURGESS: J L BURGIN, R. E BURGIN, R E, BURGIN, R E, BURKE: D J.	8403020219* 8102240064* 8403080108* 8403080202* 8403070253*	FOIA FOIA FOIA FOIA 50-280 Q	Carlbon, D M Carlbon, D M. Carlbon, D, M. Carlbon, R, A Carpenter, J H	8403010260* 8403010265* 8403190014* 8403080147* 8403190025	50-142 9 50-142 9 50-142 9 FOIA 50-400 9
BRICKLEY, RH. BRICKLEY, RH BRICHT, Q. C, BRIGHT, Q. C, BRIGHT, Q. C,	8403130425* 8403130460* 8403170025 8403210051 8403260003	GA999 GA999 50-400 G 50-400 G 50-142 G	BURNE,W C BURN,R,R, BURNETT,P,T BURNETT,P,T, BURNETT,R,F	8005130793* 8403190437 8402140193* 8403160108* 8403010029*	50-387 E NUREG 50-261 G 50-416 G ACRB	CARPENTER, J H CARPENTER, T G. CARR, A. V. CARR, A. V. CARR, A. V.	8403210051 8403150176* 8403130071 8403130077* 8403200007	50-400 Q CONTRACT 50-413 Q 50-413 Q 50-413 Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
CARR, A V CARROW, H CARROW, H CARROW, H CARTER, B R	8403200007 8403200117 8403200135 8403200135 8403200135	50-413 G 50-400 G 50-400 G 50-400 G 50-400 M	CHILK, 8 J CHILK, 8 J CHILK, 8 J CHILK, 8 J	8403230164* 8403260001 8403280343 8403280348 8403290381	10CFR 50~293 Q 50~289 Q 50~329 Q 50~279 C	CLAYTON: F L CLAYTON: F L CLAYTON: F L CLAYTON: F L CLAYTON: F L	8403130455 8403140210 8403150055 8403150084 8403160265*	50-348 P 50-348 F 50-348 Q 50-348 B 50-348 B
CARTER, R. E CARTER, S CARTER, S D CARUSO, R. CASE, E Q.	8403010255* 8403200171 8403020325 8403040536* 8308090070*	50~142 0 50~260 9 50~257 S 50~322 B FOIA	CHILK, 8 J CHILK, 9 J CHIMAN, 9 L CHIRANAL, M	8403300002 8403300017 8403270203 8403070217 8211120254	50-293	CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L	8403230134 8403240017 8403240227 8403280037 8403290084*	50-348 P 50-348 8 50-349 P 50-349 P 50-349 Q
CASSEL.D W CASSEL.D W CASSIDY.B.P CASTIGLIONE.L CASTRONOVO.F	8403140017 8403140017 8403070020 8403270044 8403070184	50-454 0 50-454 0 50-443 0 50-155 8 PRH	CHIRAMAL,M CHIRAMAL,M CHIRAMAL,M CHIRAMAL,M CHIRAMAL,M	8211220027 8302020107 8305170472 8305170497* 8305200133	50-282 B 50-255 B TOPREP TOPREP 50-219 B	CLAYTON, F. L. CLAYTON, F. L. CLAYTON, F. L. CLAYTON, F. L. CLAYTON, H. B.	8403290319 8403300077 8403300134 8403300172 8403010105	50-348 0 50-348 P 50-364 R 50-348 R TOPREP
CATON, B J CATTON, I CATTON, I CATTON, I CATTON, I	8403200331 8403160057 8403160076 8403280241 8403280241	MASTE MOT ACRS ACRS ACRS ACRS	CHIRAMAL, M CHIRAMAL, M CHIRAMAL, M CHIRAMAL, M CHIRAMAL, M,	8305270051 8310040074 8310040077* 8401250496* 8401250510*	50-338 8 MISC MISC 50-267 P 50-267 P	CLAYTON, H, B CLEMENSON, F CLEMENTS, B, R CLEMENTS, B R, CLEMENTS, B R	8403220215 8303100476* 8403080332* 8403130160 8403140147	TOPREP 50-397 A 50-445 Q 50-445 Y PR
CATTON, I CAVADAS, K. J CAYOT, R F CEARLEY, J E CEJA, 9 N	8403300246 8403120140 8403230141* 8403170317 8403220322	ACR8 50-255 R 50-275 R PR XPERTLIC	CHOULES, N C CHOULES, N C CHRISSOTIMOS, N CHRISSOTIMOS, N CHRISSOTIMOS, N	8403040174# 8403080188# 8403080233 8403120137# 8403130235	50-266 0 50-461 0 50-269 8 50-237 0 50-254 S	CLEMENTS, B. R CLEMENTS, W. L. CLEMETT, J CLEMETT, J	8403230059 8403200195* 8403010366* 8403060303* 8403060303*	50-445 H 50-287 0 70-1100 50-275 0 50-275 0
CEJA,9 N CELESTE,R F CELIA,N.9 CERNE,A C. CESARS,J &	8403220324* 8402130360* 8403070304 8403020308* 8403020047	XPORTLIC 50~358 U 50~245 P 50~443 Q 50~416 R	CHRISTENSEN, D CHRISTMAN, J N CHRISTMAN, J N CHRISTMAN, J N CHRISTMAN, J, N	8403230131 8403010175 8403010175 8403060245 8403130070#	20-355 6 20-355 6 20-355 6 20-355 6 Wineg	CLEMETT, J. CLEMETT, J. CLINE, W CLINE, W. E	8403150010 8403150010 8403260364 8403160146* 8403160111*	50-275 9 50-275 0 50-275 0 50-248 0 50-369 0
CEBARE, J. 0 CHAFFEE, A. E CHAILLE, C E CHAMBERLAIN, D CHANDLER, J C	8403220147 8403060027* 8403220024* 8403120072* 8403070127	50-416 R 50-206 Q 50-206 F 50-459 Q TOPREP	CHRISTMAN, J N CHRISTMAN, J N CHRISTMAN, J N CHRISTMAN, J, N CHRISTMAN, J N	8403130090* 8403130119* 8403130119* 8403200031 8403200031	20-325 0 20-355 0 20-355 0 20-355 0	CLINE, W. E COBB, L I, COFFMAN, F COHEN, I, COLBURN, T Q.	8403160141* 8003240207* 8305230119* 8403210016* 8403060575	50-269 9 50-508 A 50-286 P 50-317 0 50-266 P
CHANDLER: J C CHANDLER: J C CHANDLER: J C CHANDLER: J C CHANDLER: J C	8403080205 8403080223* 8403150097 8403200100 8403260219	50-314 P 50-316 P 50-316 P 50-316 P TOPREP	CHRIBIMAN, J N CHRIBIMAN, J N CHRIBIMAN, J N CHRIBIMAN, J N	8403200037* 8403200037* 8403300254 8403300256 8403080125*	50-322	COLBURN, T. Q COLE, R. F COLEMAN, J H. COLEY, J L COLLING, J T	8403220254 8403060097 8403090332* 8403160279* 8403210338	50~246 P 50~352 9 TOPREP 50~390 0 50~285 4
CHANDLER: L J CHANDLER: L J CHANDLER: L J CHANDLER: L J CHANDDLA: V	8403190100 8403210033 8403210114 8403270298 8403080009#	50-275 0 50-275 0 50-275 0 50-275 0 50-27 P	CHRISTNOT,E CHURCHILL,B W CHURCHILL,B,W, CHURCHILL,B W CHURCHILL,B W	8403190076* 8403010009 8403010009 8403010187 8403010187	50-373 G 50-287 G 50-287 G 50-382 G 50-382 G	COLLING, J. T.	8403050137 8403050138 8403050141 8403050142 8403050145	50-382 F 50-285 F 50-278 F 50-313 F 50-458 F
CHAPHAN, N CHAPHAN, M CHAPHAN, H CHAPEY, H D	8403130148# 8403240087# 8403020103 8403300137# 8403070020	50-267 @ 50-382 @ 50-259 R 50-259 R FDIA	CHURCHILL, B W CHURCHILL, B W CHURCHILL, B W, CHURCHILL, B W CILIMBERO, R L	8403060084 8403060084 8403130443 8403130443 8403170208*	50-289 9 50-289 9 50-289 9 50-289 9 50-234 9	COLLING, J, T, COLLING, J T COLLING, J, T COLLING, J, T, COLLING, M, L,	8403050146 8403050149 8403050152 8403260187 8402130395#	50-445 F 50-498 F 50-462 F 40-6681 50-358 V
CHARLTON, T R CHARNLEY, J E CHARNLEY, J, B CHARNDEF, G. CHARNDEF, G.	8403280332 8403070318# 8403150107 8403070191 8403070191	50-33B 8 50-325 0 TOPREP 50-445 0 50-445 0	CILIMEERG.R L CINTULA,T C CINTULA,T,C CIPOLLA,A J CLARDY,L S.	8403170354* 8210120303 8212010501 8403230097 8403120133*	50-440 0 50-335 8 50-361 8 40-3392 50-331 0	COLLINS, S. J. COLLINS, S. J COLLINS, S. J COLLINS, S. J.	8403010006 8403070316# 8403130021# 8403150101# 8403170425	50-410 9 50-333 9 50-220 9 50-410 9 50-244 V
CHARNOFF.C. CHAUDHARY.S K CHENEY.C A CHENG.T M CHIKALLA.T.D	8403270385 8403070319* 8403070259* 8403160078 8403300248	40-2041 50-352 G 50-348 P 50-204 P Warte Mat	CLARK, B. L. CLARK, B. L. CLARK, B. L. CLARK, B. L. CLARK, B. L.	8403010358 8403120019 8403120085 8403120175 8403130158	50-277 8 50-278 8 50-277 8 50-276 8 50-278 8	COLOMBO: R. COLOMBO: R W COLOMBO: R W. COLOMBO: R W COLTON, E.	6403200045 8403060452 8403060467 8403200001 8403010459	50-312 R 50-312 B 50-312 B 50-312 P XPORTLIC
Chilk, 8, J Chilk, 8, J Chilk, 8, J Chilk, 8, J	8403280156* 8402220157 8403010238 8403020068 8403050066	50-250 H 50-10 0 50-10 0 FOIA 50-358 0	CLARK, B. L CLARK, D. CLARK, D. CLARK, D. G. CLARK, J. R	8403200017 8403120107 8403200106 8403160027 8403010226	50-277 8 50-265 8 50-265 8 50-265 8 50-259 8	CON, V. CONGEL, F J. CONLON, T. E. CONLON, T E.	8403120252* 8205070088* 8304070113* 8403160092* 8403160212*	50-335 Q 50-460 F 50-397 A 50-413 Q 50-424 Q
CHILK, B. J. CHILK, B. J. CHILK, B. J. CHILK, B. J.	8403050244 8403050258 8403070116 8403070370 8403080104	10CFR 10CFR 50-483 0 50-320 0 M18C	CLARK,L CLARK,L, CLARK,P R. CLARK,R A CLARK,R,J.	8402130347 8403190437 8403090264 8307180414* 8403050051	50-20 F NUREO 50-320 F 50-344 P 50-296 S	CONLON, T, E, CONLON, T, E, CONNER, E CONNER, E, L CONNER, E L,	8403270156* 8403270177* 8403070287* 8403070317* 8403130280*	50-416 Q 50-400 Q 50-269 Q 50-352 Q 50-219 Q
CHILK:8 J. CHILK:8 J. CHILK:8 J. CHILK:8 J.	8403070050 8403070052 8403070057 8403070074 8403070113	50-517 0 50-443 0 50-10 0 50-10 0 50-10 0	CLAMBON, C A. GLAMBON, C A CLAMBON, C A. CLAMBON, C, A, CLAY, E. L	8403070150* 8403070154* 8403070204* 8403260379* 8403160348*	50-322 T 50-322 T 50-322 T 50-322 T 70-1113	CONNER, T. B.	8403150020 8403150020 8403150022* 8403150022* 8403200018	50-354 0 50-354 0 50-354 0 50-354 0 50-416 0
CHILK'S 7 CHILK'S 7 CHILK'S 7 CHILK'S 7	8403120028 8403120034 8403140028 8403140102 8403140005	100FR 50-416 G 50-354 G 50-400 G 50-320 G	CLAYTON, F. L. CLAYTON, F. L. CLAYTON, F. L. CLAYTON, F. L. CLAYTON, F. L.	8403010417 8403060125 8403080077 8403080081 8403080148	50-344 8 50-348 9 50-348 F 50-348 P 50-348 P	CONNER, T. B.	8403200018 8403200102 8403210072 8403210072 8403210178	50-414 9 50-354 9 50-352 9 50-358 9
CHILK, B. J. Chilk, B. J. Chilk, B. J. Chilk, B. J. Chilk, B. J.	8403160014 8403190144 8403210180 8403230005 8403230162	50-275 0 50-483 0 50-382 0 50-352 0 10CFR	CLAYTON: F. L CLAYTON: F. L CLAYTON: F. L. CLAYTON: F. L. CLAYTON: F. L	8403080158 8403080272 8403090243 8403090255 8403130031	50-348 P 50-348 P 50-348 S 50-348 P 50-348 P	CONNER, T. B. CONNER, T B CONNER, T B CONNER, T, B. CONNER, T, B.	8403210178 8403260349 8403260349 8403300270 8403300270	50-358 0 50-352 0 50-352 9 50-354 0 50-354 9

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSIDM NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CA:EQDRY
CONRAN, H CONSTABLE, O L CONTE, R. CONHAY, J, T CONHAY, J T	8307220297* 8403130140* 8403170287* 8403170340* 8403270241*	5 50~382 Q 50~289 Q 6 QA799 6 QA999	CDRRADINI M CORRADINI M CORRADINI M CORRADINI M CORRIN R J	8403280314 8403280326 8403280324 8403280345 8403270148	ACRE ACRE ACRE ACRE GA999	COUNBIL, W C COUNBIL, W C COUNBIL, W C COUNBIL, W C	8403260147 8403260162 8403260181 8403260181 8403260195	50-423 E 50-213 P 50-423 A 50-423 A 50-245 F
COOK, J. W COOK, J. W COOK, J. W COOK, J. W, COOK, J. W	8403130350 8403060104 8403060269 8403060272 8403070008	50-333 R 50-329 S 50-329 S 50-329 B 50-329 R	COBGROVE, P F COBBAR, A G, COBTANTING, C J COBTANTING, C J COBTALLG, F	8403040322* 8403220119 8403010217* 8403010231* 8403080109*	50-322 T 50-309 H 50-329 A 50-329 A FOIA	COUNSIL, W G COUNSIL, W G COUNSIL, W G COUNSIL, W G	8403240175 8403240200 8403240252 8403270008 8403270008	50-245 F 50-213 P 50-213 P 50-213 F 50-213 F
CODK: J. W. CODK: J. W. CODK: J. W.	8403080171 8403080222 8403140021 8403140032 8403220016	50-329 8 50-329 5 50-329 A 50-329 A 50-329 G	CORTELLO, F CORTELLO, F CORTELLO, F CORTELLO, J R CORTELLO, J. R	8403080133* 84030801&2* 84030801&6* 8402150224* 8403130291*	FOIA FOIA FOIA GA999 GA999	CDUNBIL, W O CDUNBIL, W O CDUNBIL, W O CDUNBIL, W O	8403270008 8403270048 8403270081 8403270081 8403270112	50-213 F 50-213 F 50-336 P 50-336 P 50-423 A
COOK, J, W COOK, J, W, COOK, K, W COOK, K, W,	8403220067 8403220108 8403020205 8403020333 8403050065	50-329 B 50-329 B 50-382 A 50-382 E	COTTER, B. P COTTER, B. P COTTER, B. P COTTRELL W. B COUNSIL, W. C	8403210163 8403270027 8403300025 8403010102* 8403010235	50-354 9 50-352 0 50-458 0 FOIA 50-336 P	COUNSIL, W O. COUNSIL, W O COUNSIL, W O. COUNSIL, W O.	8403290112 8403290230 8403290230 8403290278 8403300092*	50-423 A 50-336 P 50-336 P 50-213 P 50-245 Q
COOK, K. W. COOK, K. W. COOK, K. W. COOK, K. W.	8403040190 8403040293 8403040304 8403040337 8403120148	70-2946 50-382 E 50-382 E 50-382 E 50-382 A	COUNBIL, W C COUNBIL, W C COUNBIL, W C COUNBIL, W C	8403010235 8403010340 8403010371 8403050001 8403050001	50-336 P 50-213 P 50-213 P 50-423 D 50-423 D	COUNBIL, W G COUNBIL, W G COUNBIL, W G COUNBIL, W G.	8403300072* 8403300144 8403300144 8403300144 8403300166*	50-245
COOK, K. W COOK, K. W. COOK, K. W COOK, K. W COOK, K. W.	8403120169 8403120186 8403130105 8403130170 8403130331	50-382 A 50-382 E 50-382 G 50-382 A 50-382 Q	CDUNBIL, W Q COUNBIL, W Q COUNBIL, M. Q COUNBIL, M. Q	8403050105 8403050105 8403050105 8403060325 8403070273	50-213 P 50-213 P 50-213 P 50-213 P 50-423 C	COUNTE, M COMAN, K. D COMAILL, C COWOILL, C	8403130377 8403020077 8403300056 8403130280* 8403130060*	50-395 F 50-397 R 50-397 R 50-217 G 50-387 Q
CODK, K. W COOK, K. W, COOK, K. W COOK, K. W COOK, K. W.	8403130445 9403140191 8403150046 8403150075 8403160020	50-382 A 50-382 F 50-382 A 50-382 F \$0-382 A	COUNSIL. H & COUNSIL H	8403070273 8403070277 8403070279 8403070336* 8403070336*	50-423 C 50-423 A 50-423 A 50-423 G 50-423 G	COWLEY.P J COX.J H. COYLE.L. COYLE.L CRAIG,J	8403230200 8403280102 8403260223 8403260260 8403010363	NUREQ 50-413 F 50-237 B 50-237 B 50-289 Q
CODK, K, W. CODK, K, W CODK, K, W. CODK, K, W.	8403200161 8403200168 8403200209 8403210030 8403270154	50-382 F 50-382 A 50-382 A 50-382 A 50-382 A	COUNBIL, W. O COUNBIL, W. O COUNBIL, W. O COUNBIL, W. O COUNBIL, W. O	8403090137 8403090257 8403090257 8403090272 8403090272	50-213 0 50-336 P 50-336 P 50-336 P	CRAIO, J CRAIO, J CRAMER: M L CRANE: F A. CRANE: F A.	8403150093 8403220075 8403260347* 8403060178 8403270063	50-247 S 50-220 S MASTE MOT 50-123 J 50-275 Q
CODK, K, W, CODK, R, J CODK, T L, CODK, T. L, CODKE, B. A	8403300048 8403230046* 8403070395* 8403260335 8403220277	50-382 F 50-327 R 50-315 P 50-416 P WASTE MOT	COUNSIL, W G COUNSIL, W G COUNSIL, W G COUNSIL, W G	8403090272 8403120135 8403120135 8403130027 8403130027	50-836 P 50-245 R 50-245 R 50-213 P 50-213 P	CRANE,PA CRANE,PA CRAWLEY,DE CREED,JR CREED,JR	B4032B0033 B4032B0051 B403260277 B40301034B* B403170239*	50-275 J 50-133 I 50-327 F 50-454 Q 50-331 Q
COONER, T B, COONEY, M, J COPELAND, R, A COPELAND, R, A COPELAND, R, A	8403200102 8403070285 8403080210* 8403150104* 8403200101*	50-354 Q 50-277 F 50-316 P 50-316 P 50-316 P	CDUMBIL, W Q, CDUMBIL, W, Q CDUMBIL, W, Q CDUMBIL, W, Q	8403130027 8403130213 8403130283 8403130360 8403130360	50-213 P 50-423 B 50-213 R 50-423 C	CREED, J R. CREWS, J L. CREWS, J L. CREWS, J L CRLENJAK, R Y	8403260023* 8403050250* 8403170126* 8403170130* 8403270197*	50-346 Q 50-312 P 50-275 Q 50-275 G 50-366 Q
COPELAND, V COPELAND, V COPLAN, B. M CORDARO, M. C. CORDARO, M. C.	8403060192* 8403060192* 8403020344 8403070150* 8403070154*	50-155 @ 50-155 @ HABTE HOT 50-322 T 50-322 T	CDUMBIL, W G COUMBIL, W. G COUMBIL, W. G COUMBIL, W. G	8403140014 8403140101 8403140101 8403160272 8403160272	50-213 P 50-423 K 50-423 K 50-423 E 50-423 E	CROCKER, H. W CROCKER, H. W CROCKER, H. W CROCKER, H. W CROCKER, H. W	B403020342* B403020357* B403210016* B403210054* B403210105*	50-247 Q 50-284 Q 50-317 Q 50-320 Q 50-334 Q
CORDARO, M. C CORDARO, M. C. CORDARO, M. C. CORDARO, M. C. GORDARO, M. C.	8403070158* 8403070160* 8403070165* 8403070171* 8403070178*	50-322 T 50-322 T 50-322 T 50-322 T 50-322 T	COUNBIL, W Q, COUNBIL, W Q COUNBIL, W Q COUNBIL, W Q	8403170048 8403170048 8403170155* 8403170280 8403170280	50-245 P 50-245 P 50-213 Q PR PR	CROSS, K. E CROSSMAN, H. A CROSSMAN, H. A CROSSMAN, H. A CROSSMAN, W. A	8403260286 8403050134* 8403050186* 8403120072* 8403130140*	NUREQ 50~458 G 50~458 G 50~458 G 50~382 G
GORDARO, M. C. GORDARO, M. C. GORDARO, M. C. GORDARO, M. C. GORDARO, M. C.	8403070183* 8403070190* 8403070195* 8403070198* 8403070201*	50-322 T 50-322 T 50-322 T 50-322 T	COUNSIL, W. G COUNSIL, W. G COUNSIL, W. G COUNSIL, W. G. COUNSIL, W. G.	8403170280 8403200147 8403200147 8403210011 8403210011	PR 50-423 A 50-423 A 50-423 G 50-423 G	CRDSSMAN, W A CROSSMAN, W A CROSSMAN, W A CROSSMAN, W A CROSSMAN, W A	8403260068* 8403260087* 8403260220* 8403260232* 8403260250*	50-458 0 50-382 0 50-458 0 50-313 0 50-382 0
CORDARD, M. C.	9403070204* 8403070207* 8403070211* 8403070214* 8403070217*	50-322 T 50-322 T 50-322 T 50-322 T 50-322 T	COUNBIL.W &. COUNBIL.W O. COUNBIL.W O. COUNBIL.W O	8403210161 8403220148 8403220148 8403230022 8403230022	50-423	CROUBE, R P CROUBE, R P CROUBE, R P CROUBE, R P GROUBE, R P	8403080107 8403130133 8403130429 8403150085 8403150349*	50-346 P 50-346 P 50-346 P 50-346 B
CORDARD, M. C.	8403070231#	50-322 T 50-322 T 50-322 T 50-322 T 50-322 T	COUNSIL, W. O. COUNSIL, W. O. COUNSIL, W. O. COUNSIL, W. O.	8403230022 8403230029 8403230029 8403230033 8403230033	50-213 R 50-245 F 50-245 F 50-423 G 50-423 G	CROUBE,R P CROUBE,R P CROUBE,R P, CROUBE,R P, CROUBE,R P	840320008 8403200046 840323009 8403300149 8403300156*	50-346 P 50-346 P 50-346 P 50-346 P 50-346 P
CORDARO, M. C. CORDARO, M. C. CORDARO, M. C. CORDARO, M. C. CORDARO, M. C.	840323003B 840323004B	50-322 T 50-322 T 50-322 T 50-322 T 50-322 T	COUNSIL, H. G.	8403230136 8403260143 8403260143 8403260143 8403260145	50-213 G 50-213 F 50-213 F 50-213 F 50-234 P	CROUSE, R P GROUSE, R, P GROW, W, T, GROW, W T GROW, W T.	8403300178 8403010513# 8403060490	50-346 P 50-346 J 40-8027 40-481 40-8027
CORDARD, M. C. CORDARD, M. C CORMIER. W. H. GORMIER, W. H. CORRADINI, M	8403260379# 8403140087 8403260380	50-322 T 50-322 T 50-142 G 50-142 G ACRS	COUNBIL, H 0. COUNBIL, H 0. COUNBIL, H 0. COUNBIL, H 0. COUNBIL, H. 0	8403260145 8403260146 8403260146 8403260146 8403260149	50-336 P 50-213 F 50-213 F 50-213 F 50-423 E	CROW, W T. CROW, W T CROWLE, D. B CROWLEY, B. R CROWLEY, B. R	8403260084* 8403300342 8403160198*	70-1359 70-1257 NUREO 50-321 Q 50-366 8

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
CROWLEY, B R.	8403270217*	50-321 0	CUTTER, A B	84030&0140	50-324 P	DANCE: H C	8403160264	50-335 G
CROY, P A	8402030338	50-204 F		8403130093	50-261 P	DANCE: H C	8403160306	50-250 G
CROY, P A	8402150031	50-206 F		8403150028	TOPREP	DANCE: H C	8403160334	50-302 F
CROYCHFIELD, D	8403010331	50-29 0		8403210093	50-261 P	DANCE: H C	8403160338	50-321 G
CRUTCHFIELD, D.	8403010372*	50-255 P		8403270235	50-261 P	DANCE: H C	8403160343	50-413 G
CRUTCHFIELD.D CRUTCHFIELD.D CRUTCHFIELD.D CRUTCHFIELD.D	8403010384 8403050005 84030500004* 8403050009 8403050121	50-213 P 50-155 P 50-155 P 50-407 P 50-155 P	CYBULBKIB: P CYBULBKIB: P B'ANOELD: A DALE: L F.	8403050227 8403050230 8403050242 8403060029* 8403010121	REB 50-280 P REB 50-206 G 50-416 B	DANCE, H C DANCE, H C DANCE, H C DANCE, H C DANCE, H C	8403160356* 8403160359* 8403160360 8403290069 8403290090*	50-413
CRUTCHFIELD, D	8403060321	50-155 P	DALE,L F	8403020047	50-416 R	DANCE, H C	8403290109	50-335 0
CRUTCHFIELD, D	8403060327	50-219 P	DALE,L F	8403070057	50-416 G	DANCE, H C	8403290124*	50-335 0
CRUTCHFIELD, D	8403060454	50-245 P	DALE,L F	8403070173*	50-416 G	DANCE, H C	8403290143	50-413 0
CRUTCHFIELD, D	8403060457*	50-245 P	DALE,L F.	8403070176*	50-416 G	DANCE, H C	8403290174	50-335 0
CRUTCHFIELD, D	8403080094	50-219 P	DALE,L F	8403070180*	50-416 G	DANCE, H C	8403290184	50-336 F
CRUTCHFIELD.D. CRUTCHFIELD.D. CRUTCHFIELD.D. CRUTCHFIELD.D.	8403070210 8403070297 8403130216 8403130225 8403140133	50-155 P 50-219 P 50-206 P 50-244 P 50-249 P	DALE: L F. DALE: L F DALE: L. F. DALE: L F DALE: L. F.	8403070189* 8403070268 8403090091 8403090192 8403090215	50-416 G 50-416 G 50-416 B 50-416 B 50-416 P	DANCE, H C DANCE, H C DANCE, H C DANCE, H C DANCE, H C	8403270208 8403270215* 8403270231 8403270262 8403270275	50-321 0. 50-321 0 50-302 0 50-302 0
CRUTCHFIELD, D.	8403140143*	50-249 P	DALE, L F	8403120037	50-416 P	DANCE,H C	8403270287	50-338 Q
CRUTCHFIELD, D.	8403150040	50-237 P	DALE, L F.	8403120148	50-416 S	DANCE,H C.	8403270317	50-335 Q
CRUTCHFIELD, D.	8403150072	50-237 F	DALE, L F	8403120159	50-416 S	DANIEL,S L.	8403080027#	FDIA
CRUTCHFIELD, D	8403170074	50-249 Q	DALE, L F.	8403130095	50-416 B	DANIELB,Q H	8403040124#	50-244 P
CRUTCHFIELD, D	8403170178	50-155 P	DALE, L F	8403130192	50-416 B	DANIELSON,D H	8403080302#	50-315 Q
CRUTCHFIELD, D	8403200177	50-155 P	DALE,L F	8403130248	50-416 8	DANIELBON, DH	8403170208*	50-254 Q
CRUTCHFIELD, D	8403210070	50-245 P	DALE,L F	8403130253	50-416 8	DANIELBON, DH	8403170305*	50-454 Q
CRUTCHFIELD, D	8403210079*	50-245 P	DALE,L F,	8403130274	50-416 8	DANIELBON, DH	8403170354*	50-440 Q
CRUTCHFIELD, D.	8403210135	50-244 P	DALE,L F	8403130464	50-416 8	DARDEN, TH	8403080173*	FOIA
CRUTCHFIELD, D.	8403210143*	50-244 P	DALE,L F	8403140121	50-416 J	DARWIBH, M	8403150045*	50-237 P
CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	6403220021 8403220027 640323065 6403230143 8403270106	50-155 F 50-237 P 50-245 P 50-155 P 50-155 P	DALE, L. F. DALE, L. F. DALE, L. F. DALE, L. F.	8403190033 8403190043 8403190059 8403190115 8403190216	50-416 S 50-416 S 50-416 S 50-416 S 50-416 S	DAVENPORT, K E DAVERID, C A DAVERID, C A DAVERID, C, A DAVERIO, C A	8403160238* 8403070150* 8403070154* 8403070158* 8403070165*	50-257 Q 50-322 T 50-322 T 50-322 T 50-322 T
CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CULVER, M W. CUMMINGS, J, J	8403280005 8403280011 84032800&6 84031&0036 8403280229#	50-217	DALE, L. F. DALE, L. F DALE, L. F DALE, L. F DALE, L. F	8403170272 8403170331 8403200014 8403200017 8403200044	50-416 8 50-416 8 50-416 8 50-416 8 50-416 8	DAVERIO,C A DAVERIO,C A DAVERIO,C,A DAVERIO,C A DAVERIO,C,A	8403070178* 8403070183* 8403070217* 8403230014 8403230032	50-322 T 50-322 T 50-322 T 50-322 T 50-322 T
CUNNINGHAM, A L. CUNNINGHAM, A L. CUNNINGHAM, O E CUNNINGHAM, O E CUNNINGHAM, O H	8403160202*	50-390 0	DALE, L. F	6403210053	50-416 P	DAVERIO,C A	8403230048	50-322 T
	8403290237*	50-259 0	DALE, L. F,	6403210109	50-416 P	DAVERIO,C A	8403230073	50-322 T
	8403150072	50-73 R	DALE, L. F	6403210140	50-416 E	DAVERIO,C A	8403260379*	50-322 T
	8403200242	50-70 R	DALE, L. F	6403220147	50-416 R	DAVIS,A B.	8005010203*	FOIA
	8403140141	50-322 0	DALE, L. F.	8403220156	50-416 X	DAVIS,A B	8005280995*	FOIA
Cunningham, 0 H Cunningham, L J Cunningham, R E Cunningham, R E Cudmo, M	8403140182 8208240003* 8403080144* 8403300307 8403020123	50-322	DALE, L.F. DALE, L.F. DALE, L.F. DALE, L.F. DALE, L.F.	8403240244 8403240094 8403240306 8403300027	50-416 B 50-416 P 50-416 G 50-416 B 50-416 B	DAVIS:A B DAVIS:C B DAVIS:J F. DAVIS:J G. DAVIS:J G.	8403080038* 8403280113 7906140348* 8403010022* 8403140240*	FOIA 50-313 8 50-312 P ACRB MISC
CURRAN, D.	8403020173	50-443 0	DALE: L F	B403300037	50-416 S	DAVIB:K L	8403290334	FOIA
CURRAN, D.	8403020173	50-443 0	DALE: L F.	B403300082	50-416 S	DAVIB:L.A	8403230197	NUREO
CURRAN, D.	8403070232	50-443 0	DALE: L F.	B403300097	50-416 P	DAVIB:M J	8403070253*	50-280 G
CURRAN, D.	8403070232	50-443 0	DALE: L F.	B403300113	50-416 S	DAYKIN:H.W	8403140072	TOPREP
CURRAN, D.	8403300263	50-443 0	DALE: L, F.	B403300114	50-416 S	DAYKIN:H.W.	8403140072	TOPREP
CURTIS, D. J.	8403120010*	50-275 0	DALE,L.F	8403300117	50-416 S	DE AGAZIO, A. DE QRASSI. 0 DEAL. L. J DEBONB. A DEBS, B. T.	8403260378	50-346 F
CURTIS, D. J	8403120023*	50-275 0	DALE,L F	8403300118	50-416 S		8403200067*	50-219 G
CURTIS, N. W	8403010294	50-388 E	DALE,L F	8403300124	50-416 S		8403140166	PR
CURTIS, N. W	8403020327	50-387 P	DALTROFF,S L	8403070361	50-352 F		8403160046	ACRS
CURTIS, N. W	8403050108	50-387 P	DALTROFF,S L	8403070081	50-277 Q		8403070072*	50-259 G
CURTIS: N W.	8403050116 8403050122* 8403060175 8403060437 8403120127	50-387 P 50-387 P 50-387 Q 50-387 J 10PREP	DALTROFF, S.L DALTROFF, S.L DALTROFF, S.L DALTROFF, S.L DALTROFF, S.L	8403090131 8403090290 8403150905 8403150137 8403210028	50-277	DEBB, B. T DECKER, T. R. DECKER, T. R. DECKER, T. R. DEFAYETTE, R	8403270220* 8403070145* 8403160244* 8403270027* 8403080233	50-259 0 50-335 0 50-259 9 50-348 9 50-263 8
CURTIS, N W. CURTIS, N W. CURTIS, N W. CURTIS, N W. CURTIS, N. W.	8403120127 8403130111 8403130150 8403150070 8403150232	TOPREP 50-387 P 50-388 V 50-387 P 50-387 F	DALTROFF, S L DALTROFF, S L DANCE, H C DANCE, H C DANCE, H C,	8403270104 8403270250 8403020248 8403050177 8403070012	50-277 F 50-277 0 50-250 S 50-413 Q 50-413 Q	DEFAYETTE, R. DEFAYETTE, R. DEFAYETTE, R DEGENS, S. DEHOLLANDER, Q	8403120078 8403130423 8403170071 8403220178 8403200374*	50-155 8 50-263 8 50-255 8 50-368 D 40-8681
CURTIS, N W	8403170345	50~387 P	DANCE, H. C	8403070018	50-424 Q	DEJU,R A	8403300248	WASTE MOT
CURTIS, N W	8403200006	50~388 A	DANCE, H. C.	8403070140	50-335 Q	DELAND,F.H.	8403190326	PR
CURTIS, N W	8403200071	50~388 E	DANCE, H. C.	8403070205	50-413 Q	DELANEY.C.E	8403020141	50-354 9
CURTIS, N W,	8403200073	50~387 P	DANCE, H. C.	8403070230	50-280 Q	DELGEDRGE,L D	8403010083	50-454 9
CURTIS, N W	8403200103	50~387 F	DANCE, H. C	8403070327	50-413 Q	DELLA RATTA,A	8403070259*	70-1100
CURTIS, N W,	8403210072	50-387 K	Dance, H. C.	8403070334*	50-413 Q	DELLA RATTA,A.	8403270066*	70-398
CURTIS, N H	8403210081*	50-387 K	Dance, H. C.	8403080384*	FDIA	DELLIGATTI,M	8403140132	HASTE MOT
CURTIS, N, W	8403210125	50-388 8	Dance, H. C.	8403150099	50-280 Q	DELO,H.A.	8403060231	SO-219 H
CURTIS, N, W	8403210145	50-389 S	Dance, H. C.	8403160086	50-413 Q	DELOATCH,V.	8403010003	CONTRACY
CURTIS, N H	8403220040	50-388 A	Dance, H. C	8403160101	50-369 Q	DEMOGS,G T	8403270188*	SO-244 P
CURTIS, N W	8403220069	50-387 0	Dance, H C.	8403160110	50-367 Q	DENISE, R.P.	8403120071	50-267 8
CURTIS, N W.	8403220102	50-387 P	Dance, H C.	8403160134	50-269 Q	DENNING, R. B.	8403050227	REB
CURTIS, N W.	8403230075	50-388 S	Dance, H C.	8403160176	50-321 Q	DENNING, R. S.	8403050230	50-280 P
CURTIS, N W.	8403260305	50-388 A	Dance, H C	8403160206	50-335 Q	DENNING, R. S.	8403050242	REB
CURTIS, N W	8403270175	50-387 I	Dance, H. C	8403160207	50-424 Q	DENTON, H. R	621 <i>0</i> 220012*	FOIA

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	ROHITUA	ACCESSION NUMBER	SATEON
DENTON, H R DENTON, H R DENTON, H R. DENTON, H R DENTON, H R	8210220084* 8211170102* 8212080672* 8212130052* 8212160059*	FDIA FDIA 50-267 F 50-267 P 50-267 P	Diederich 0 J Diederich 0 J Diederich 0 J Diederich 0 J Diederich 0 J	8403190117 8403200032 8403200204 8403200212 8403230015	50-373 S 50-373 S 50-373 S 50-374 S 50-374 S	DIRCKE'M O DIRCKE'M O DIRCKE'M O DIRCKE'M O	8403150334 8403170054 8403200301* 8403200304 8403200341	50-272 50-320 50-275 50-320 50-320
DENTON; H R DENTON; H, R DENTON; H R. DENTON; H R DENTON; H R	8311230247* 8312150232* 8403010104* 8403010108* 8403010150*	FOIA FOIA FOIA FOIA 50-312 P	DIEDERICH.G. J DIEDERICH.G J DIEDERICH.G J DIEDERICH.G J DIETZ.C.R	8403230017 8403230027 8403280023 8403280073 8403010133	50-373 8 50-373 8 50-374 8 50-374 8 50-325 8	DIXON'D M DIXON'O M DIXON'O M DIXON'D A DIUCKR'M A	8403280149 8403130024 840302039 8403020297 8403040128	50-250 0A979 50-395 50-395 50-395
DENTON: H R DENTON: H R. DENTON: H. R DENTON: H. R. DENTON: H. R. DENTON: H. R.	8403010477 8403010525 8403020029* 8403020041* 8403020045*	CDMMI8910N 50-275 H 50-267 P 50-267 P 50-267 P	DIETZ.C R. DIETZ.C R DIETZ.C R DIETZ.C R. DIETZ.C R.	8403010135 8403010202 8403010279 8403010375 8403070023	50-324 S 50-325 S 50-324 S 50-324 S 50-324 S	DIXON'O M DIXON'O M DIXON'O M DIXON'O M	8403040242 8403040351 8403070040 8403070129* 8403070337	50-395 50-395 50-395 50-395 50-395
DENTON, H. R DENTON, H. R. DENTON, H. R DENTON, H. R DENTON, H. R.	8403020046* 8403020048* 8403050219 8403060059 8403070014	50-267 P 50-267 P 50-460 A 50-265 P 50-460 A	DIETZ, C R DIETZ, C. R. DIETZ, C R. DIETZ, C R. DIETZ, C R.	8403070205 9403070235 8403130047 8403130078 8403130152	50-325 8 50-324 8 50-325 8 50-324 8 50-324 8	DIXON, O. H DIXON, O. H DIXON, O. H DIXON, O. H	8403080153 8403070052 8403070247 8403070271 8403130260	50-395 50-395 50-395 50-395 50-395
DENTON, H. R. DENTON, H. R	8403070103 8403080350 8403080410 8403120261 8403140233	MISC FOIA 50-320 P 50-320 P MISC	DIETZ, C. R DIETZ, G. R DIETZ, C. R DIETZ, C. R. DIETZ, G. R	8403130301 8403130323 8403130333 8403130404 8403150035	50-324 S 50-325 S 50-324 R 50-324 S 50-325 S	DIXON, O. W. DIXON, O. W. DIXON, O. W. DIXON, O. W.	8403130371 8403130397 8403150042 8403210007 8403270183	50-395 50-395 50-395 PR 50-395
DENTON, H R DENTON, H. R DENTON, H R. DENTON, H R. DENTON, H R. DENTON, H R.	8403150345# 8403170107 8403220076 8403260106 8403280045	50-305 F 50-249 Q 50-275 P 50-275 U 50-341 H	DIETZ, C R. DIETZ, C R. DIETZ, C R. DIETZ, C R. DIETZ, C, R.	8403150177 8403150186 8403190302 8403200207 8403200273	50-324 S 50-324 S 50-325 S 50-324 E 50-324 S	BIXON, O. W DIXON, O. W. DODA, R. J DODAS, R. T DODDS, R. T	8403270223 8403300145 8403380170* 8403080344* 8403080270*	50-395 50-395 FOIA 50-344 50-397
DENTON, H. R. DERKS, P. S. DERKS, P. S DEUTSCH, W. J DEVINCENTIS, J	8403300235 8403020006 8403300075 8403230177 8403130468	TOPREP 50-133 R 50-133 R NUREQ 50-443 B	DIETZ, C R. DIETZ, C R. DIETZ, C R DIETZ, R L DIGOB, R M	8403210123 8403210139 8403270266 8403230060 8403020222	50-324 B 50-325 S 50-324 B 50-538 R 50-206 P	DODDS, R. T. DODDS, R. T. DODSE, R. E. DODSDN, J. P. DODSDN, M. E	8403120043 8403150121 8403300081 8403140122 8403070118	50-341 50-275 50-244 50-220 MAREO
DEVINCENTIS, J DEVINCENTIS, J DEVINCENTIS, J DEVINCENTIS, J DEVINCENTIS, J	8403150100 8403150100 8403160256 8403160256 8403210097	50-443 8 50-443 8 50-443 F 50-443 F 50-443 A	Digob.r M Digob.r M Digob.r M. Digob.r M Digob.r M	8403020230 8403050233 8403070003 8403120270 8403120302	90-413 A 60-331 P 50-213 P 50-278 P 50-312 P	DDERFLEIN, L.T. DDERGE, D. H DDERGES, J. E DDERING, J. DDHERTY, J. F	840307031&# 8403150214 8403290301 8403270048# 8403130057	50-333 ; 50-30 ; FRM 50-352 50-456 ;
DEVINCENTIS, J DEVINCENTIS, J. DEVINCENTIS, J. DEVINCENTIS, J.	8403210099 8403210142 8403210142 8403220005 8403220005	50-443 A 50-443 A 50-443 A 50-443 B 50-443 B	Diors, R. M Diors, R. M. Diors, R. M. Digos, R. M Diors, R. M	8403140222 8403300241 8403300288 8403300295 8403300323	50-336 P 50-220 P 50-250 P 50-220 Q 50-243 P	DOHERTY, J. F BOHERTY, J. F DOLECEK, E. H DOMANUS, H. M DOMANUS, H. M	8403140040 8403270002 8403190317 8403300241 8403300285	50-456 (50-443 (PR NUREQ NUREQ
DEVINCENTIS, J DEVINCENTIS, J DEVINCENTIS, J DEVINCENTIS, J	8403220150 8403220150 8403220164 8403220164 8403230061	50-443 B 50-443 S 50-443 B 50-443 B 50-443 A	Dignan, T. G Dignan, T. G. Dignan, T. G. Dignan, T. G. Dignan, T. G.	8403080142 8403080142 8403090093 8403090093 8403090124	50-443	DOMBY, A H DONLON, W J DONOFRIO, M. DONOCHUE, D J DOOLITTLE, E, L	8403090370 8403290177 8403090289 8403020028# 8401120455	50-4R4 (50-2R0 i 50-213 ; FDIA 50-4R3 ;
DEVINCENTIE, J DEVINCENTIE, J DEVINCENTIE, J, DEVINE, J, B, DEVINE, J B,	8403230061 8403270121 8403270121 8403200395 8403280072	50-443 A 50-443 A 50-443 A XPORTLIC XPORTLIC	Dignan, T o. Dignan, T. o Dignan, T o. Diianni, D c Dircks, W J	8403090124 8403300269 8403300269 8403350238 7911120413*	50-443	DOOLITYLE, E, L DOREMUS, R R, DOREMUS, S D DOROSHOW, J DORRIS, R, E	8403280286 8403230008 8403080406* 8403130065 8403300342	50-423 50-322 50-528 50-287 Nurse
DEVINE, T. DEVINE, T. DEVINE, T DEVINE, T DEVINE, T.	B403150010 B403200133 B403200133 B403260364 B403260364	50-275 Q 50-275 Q 50-275 Q 50-275 Q 50-275 Q	DIRCKS, W. J. DIRCKS, W. J DIRCKS, W. J DIRCKS, W. J. DIRCKS, W. J.	8007110203# 8202220056# 8203050065# 8204160230# 8207200364#	50-397 U FOIA FOIA FOIA FOIA	DOSS, K. C. DOTY, R. L. DOUDNIKOTT, B DOUDAN, J. R. DOUDHERTY, F. A	8403120027# 8403130057 84030300318 8403320022#	50-275 P 50-387 R CONTRACT NUREO 50-327 R
DEVINE, T M DEVINE, T. M DEVLIN, J W, DEWEY, L. B, DEYDUNG, R. C	8403060303* 8403060303* 8403080087* 8403190164 7911120370*	50~275	DIRCKS, H. J DIRCKS, H. J DIRCKS, H. J DIRCKS, H. J	8212080693* 8212100130* 8301140173* 830128038 <i>0</i> * 8312140347*	50-267 P FOIA FOIA 50-382 A 50-275 E	DOUGHTY, J. DOUGLAS, M. DOVER, B DOVER, R P. DOYLE, J.	8403010385 8403010254 8403140160 8403070219* 8403070108*	FOIA 50-219 B PR 50-413 A 50-448 T
DEYOUNG, R. C.	8311130481# 8401250456# 8402090031 8403020025# 8403120234	50-312 P 50-267 P 50-3 G FDIA 40-6920	DIRCKB, W. J. DIRCKB, W. J. DIRCKB, W. J. DIRCKB, W. J. DIRCKB, W. J.	8312280099# 8402220050 8403010032# 8403010109 840301026#	50-275 E SECY 50-334 B REVIEW GRP 50-247 P	DRAGOUN, T. DRAPER, D. M. DRAMBRIDGE, B. L. DRISCOLL, F. DRUMMOND, F. J.	8403150017* 8403800283 8403800215 8403140172 8403120014	50-217 9 50-315 9 50-27 8 PR 50-382 F
DEYDUNG, R. C DEYDUNG, R. C. DEYDUNG, R. C DEYDUNG, R. C DEYDUNG, R. C	8403120242# 8403120305 8403120308# 8403120311# 8403220245	40-6920 50-293 F 50-293 F 50-293 F 50-454 Q	DIRCKS, W J. DIRCKS, W J. DIRCKS, W J. DIRCKS, W J.	8403010274* 8403010329 8403010451 8403010497 8403020027*	FDIA REVIEW ORP 50-206 8 50-329 A 50-247 P	DUBINBRI, L. DUBGIS, D. DUBGIS, D DUBGIS, D DUBGIS, D	8403260136* 8403060075 8403200305 8403220230 8403220284	AO-1478 XPORTLIC XPORTLIC XPORTLIC XPORTLIC
Dick, Q.F Diederich, Q.J. Diederich, Q.J. Diederich, Q.J. Diederich, Q.J.	8403040290 8403020138 8403040150 8403120020 8403120047	50-244 F 50-373 R 50-373 R 50-373 8 50-374 8	DIRCKS, W. J. DIRCKS, W. J. DIRCKS, W. J. DIRCKS, W. J DIRCKS, W. J	8403020035# 8403020052# 8403020443 8403050236 8403080011	FDIA FDIA 50-275 R 50-416 P 50-254 B	DUBDIB, D. DUCK, J. R. DUCK, J. R. DUCK, J. R. DUCK, J. R.	8403260011 8403060224 8403060234 8403060277 8403060281	XPORTLIC 50-327 J 50-335 J 50-390 J 50-321 J
DIEDERICH, 0, J. DIEDERICH, 0, J. DIEDERICH, 0 J. DIEDERICH, 0 J. DIEDERICH, 0, J	8403120054 8403120080 8403120075 8403160261 8403160266	50-373 8 50-373 8 50-373 8 50-373 R 50-374 8	DIRCKS, W. J DIRCKS, W. J. DIRCKS, W. J. DIRCKS, W. J DIRCKS, W. J	8403080041 8403080434 8403090019* 8403120388* 8403140204	SECY SECY FOIA COMMISSION 50~382 U	DUCK, J. R. DUCK, J. R. DUCK, J. R. DUCK, J. R. DUCK, J. R.	8403060332 8403060334 8403060353 8403060413 8403060448	50-250 J' 50-259 J 50-302 J' 50-438 J 50-348 J

AUTHER	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY
DUCK, J R DUCK, J R DUCK, J R	8403070175 8403140044 8403280038 8403280053 8403020147	50-327 J 50-348 J 50-321 J 50-348 J 50-327 B	EDELMAN, M R EDGAR, G L EDGAR, G L EDGAR, G L EDGAR, G L	8403270224 8403020100 8403020100 8403040082 8403070086	50-440 G 50-537 G 50-537 G 50-537 G 50-537 G	ELLIS' ? ELTIS' ? ELTIS' ? ELTIS' ?	8403070177 8403070182* 8403070104 8403070128 8403140034	50-445 Q 50-445 T 50-445 T 50-445 Q 50-445 Q
DUGGIN, G DUGGIN, G DUGGIN, G DUGGIN, G	8403050080 8403040274 6403150079 8403190121 8403190365	50-327 8 50-327 8 50-327 8 50-327 5 50-327 5	EDGAR. G L EDGAR. G L EDGAR. G L EDGEWORTH. P EDGEWORTH, P	8403070086 8403230186 8403230186 8403070339 8403150206	50-537 G 50-556 G 50-556 G CONTRACT CONTRACT	ELLIS, J ELLIS, J ELLIS, J ELLIS, J	8403170006 8403190024 8403170032 8403200007 8403200012	50-445 Q 50-445 Q 50-445 Q 50-445 Q 50-445 Q
DUGGIN.G DUGGIN.G DUGSTAD.D. DUNAWAY.F R DUNLAP.J M	8403300073 8403300204 8403300095 8403220165= 8403070259=	50-327 8 50-328 8 50-282 R 50-295 9 70-1100	EDWARDS, D L. EDWARDS, D L EISENHOWER, E H EISENHUT, D Q EISENHUT, D Q	8403150242 8403150264 8403070214 7911120317* 8102200027*	40-3453 40-3453 PR 50-312 P 50-466 A	ELLIS: J ELLIS: J ELLIS: J ELLIS: J	8403200025 8403200026 8403200049 8403200073 8403200114	50-445 Q 50-445 Q 50-445 Q 50-445 Q 50-445 Q
DUNLAP, J M DUPONT. S & DURDEL, R R DURKOSH, E D DURR, J	8403270205* 8403300057* 8403270167 8403270238 8403270104*	50-320 G 50-341 G 50-346 F PRM 50-217 G	EISENHUT, D Q EISENHUT, D Q EISENHUT, D Q EISENHUT, D Q	B110170026* B307210434* B312050628* B401120425 B401120428*	50-508 F 50-322 A 50-329 A 50-445 A 50-445 A	ETTIS' I S ETTIS' I ETTIS' I ETTIS' I ETTIS' I ETTIS' I	8403200118 8403200126 8403200147 8403010242 8403010242	50-445 Q 50-445 Q 50-445 Q 50-322 Q 50-322 Q
DURR. J P DURR. J P DURR. J P DURR. J P DURR. J P	8403020272* 8403020307* 8403070322* 8403220062* 8403270062*	50-293 0 50-277 0 50-277 0 50-309 0 50-334 0	EISENHUT.D G EISENHUT.D G EISENHUT.D G EISENHUT.D G	8402070004 8402070006 8402070012 8402070017 8402070020	50-275 P 50-247 F 50-275 Q 50-275 P 50-322 8	ELLIS, T, S ELLIS, T S ELROD, S ELROD, S ELROD, S	8403010249 8403010249 8403070259* 8403270132* 8403270271*	50-322 9 50-322 9 50-280 9 50-335 0 50-338 0
DURR.J P DURR.J P DURR.J P DUS.R S DUVALL.D D	B403290292* B403300076* B403300103* B403200204 B402010185*	50-29 0 50-322 0 50-354 0 50-373 8 GA999	EIBENHUT, D G EISENHUT, D G EISENHUT, D G EISENHUT, D G	8402070021 8402070022 8402070030 8402070032 8402070033	50-322 8 50-275 G 50-275 E 50-275 T 50-322 8	ELROD, S. ELROD, S. A ELROD, S. A ELRAD, S. A ELBABSER, T. C ELBABSER, T. C	8403270274* 8403160268* 6403270180* 8403010404* 8403020305*	50-338 0 50-335 0 50-335 0 50-213 0 50-54 0
DUVALL, D D DYNNER, A R DYNNER, A R EALEY, D	8403270219 8403130306* 8403220250 8403220250 8403020374	50-204 B CONTRACT 50-322 0 50-322 0 WASTE MOT	EIBENHUT.D G EIBENHUT.D G EIBENHUT.D G EIBENHUT.D G	8402070035 8402070038 8402070037 8402070041 8402140527	50-322	EMCH, R. L. EMCH, R. L. EMERBON, W. F. EMERY, R. B. ENGEL, R. E.	8403160122 8403280034 8403200182 8403190409* 8403140006	50-155 P 50-155 P 50-429 A 50-317 Q TOPREP
EARLEY, A F EARLEY, A F EARLEY, A F EBERBOLE. J C EUNETER. S D	8403210177 8403210177 8403280043 8401300121 8402140043*	50-322 0 50-322 0 50-322 0 50-400 0 50-528 0	EISENHUT.D G EISENHUT.D G EISENHUT.D G EISENHUT.D G	8402140536* 8403010020* 8403010180* 8403010204* 8403010211*	50-331 P 50-289 P 50-250 F 50-329 A 50-329 A	ENNIB' O D ENGTE' T B ENGTE' T B ENGTE' T B	8403050198 8403210203 8403220208 8403260273 8403150109#	50-338 P 50-338 P 50-338 P 50-338 P 50-280 Q
EBNETER, B D ECKDERO, S R ECKERT, J P ECKERT, J P ECKERT, J P	8403150034* 8403280191* 8401240315* 8403070149* 8403070153*	50-388 0 FOIA 70-27 70-27 70-27	EISENHUT.D G EISENHUT.D G EISENHUT.D G EISENHUT.D G	9403010223# 8403010245# 8403010273# 8403010501 8403020021#	50-329 A 50-327 A 50-329 A 50-275 P FDIA	ENDIS, J ENDS, B ENDIS, J ENDIS, J ENDIS, J D	8403260183* 8403300044* 8403080401 8403080036* 8403080045*	70-27 70-27 FOIA FOIA FOIA
ECKERT, J P ECKHARDT, J ECONOMOS, N EDDINOS, M G EDDLEMAN, W	8403300015# 8403230117 8403160363* 8403300154 84030050061	70-27 50-312 S 50-413 G 50-327 R 50-400 E	EISENHUT.D G EISENHUT.D G EISENHUT.D G EISENHUT.D G	8403020175* 8403020221* 8403050127 8403050341* 8403040009*	50-286 F 50-373 F 50-206 F 50-265 P 50-261 P	EPSTEIN,E. EPSTEIN,E ERICKBON,J. ERICKBON,R W ERNST,M L.	8403080047* 8403080058* 8403150210 8403070141* 8201220170*	FOIA FDIA 40-299 CONTRACY FDIA
EDDLEMAN, W EDDLEMAN, W EDDLEMAN, W EDDLEMAN, W, EDDLEMAN, W	8403130001 8403130186 8403130196* 8403130220* 8403130230*	50~400 0 50~400 0 50~400 0 50~400 0 50~400 0	EISENHUT.D G EISENHUT.D G EISENHUT.D G EISENHUT.D G	8403040449* 8403040453 8403040464* 8403040473 8403060474	50-344 P 50-416 B 50-338 F 50-289 P 50-289 P	ebelgroth, P Ebelgroth, P Ebhelman, E. M Etchibon, D Etzler, R D	8403170285 8403230074 8403130277 8403060313 8403120018*	50-322 8 50-322 8 50-317 8 50-456 D 50-275 9
EDDLEMAN, W EDDLEMAN, W EDDLEMAN, W EDDLEMAN, W EDDLEMAN, W	8403200048 8403220222 8403220227 8403220265 8403220265	50-400 0 50-400 0 50-400 0 50-400 0 50-400 0	EISENHUT, D. G EISENHUT, D. G EISENHUT, D. G EISENHUT, D. G	8403040510* 8403040529 8403070354 8403070368 8403120342*	50-261 F MISC 50-416 P 50-313 P 50-312 F	ETZLER, R. D. EURE, J. A EVANB, C. A EVANB, C. D. EVANB, C. D.	8403120029* 8403170387 8403260220* 8403120145* 8403170076*	50-275 9 PR 50-458 9 50-263 9 50-973 9
EDDLEMAN, W EDDLEMAN, W EDDLEMAN, W EDDLEMAN, W EDDLEMAN, W	8403220270 8403220270 8403280344 8403280347 8403280349	50-400 0 50-400 0 50-400 0 50-400 0 50-400 0	EISENHUT.D.G EISENHUT.D.G EISENHUT.D.G EISENHUT.D.G	8403120359* 8403140128 8403140239* 8403140244 840314025&*	50-302 F TOPREP 50-324 F 50-275 Q 50-278 F	EVANS,E A EVDOKIMOFF,V.N EVERETT,R R FAILLA,C.V. FAIR,J.R	8403300248 8403130218 8403260109* 8403260342* 8403190116*	MASTE NOT PR 40-1341 50-322 T 50-275 0
EDDLEMAN, W EDDLEMAN, W EDDLEMAN, W EDDLEMAN, W EDELMAN, M R	8403280351 8403280360 8403280361 8403280361 8402270274	50-400 0 50-400 0 50-400 0 50-400 0 50-440 8	EIBENHUT, D. G EIBENHUT, D. G EIBENHUT, D. G EIBENHUT, D. G EIBENHUT, D. G	8403140290 8403140306# 8403150250# 8403150268 8403150275	50-271 F 50-250 Q 50-346 F 50-388 A 50-10 P	FAIRTILE, M B FAKLER, J, L. FALCONER, D FALCONER, D FALEVITS, Z	8403270044* 8403060322* 8403070369* 8403270108* 8403170076*	FDIA 50-382 T 50-269 Q 50-269 Q 50-373 Q
EDELMAN, M.R. EDELMAN, M.R. EDELMAN, M.R. EDELMAN, M.R. EDELMAN, M.R.	8403060181 8403120052 8403120076 8403120126* 8403130072	50-440 A 50-440 S 50-440 S 50-440 Q 50-440 A	EIGENHUT, D. G EIGENHUT, D. G EIGENHUT, D. G EIGENHUT, D. G	8403150295* 8403150343 8403170433 8403220023* 8403260265*	50-346 P 50-305 F 50-272 F 50-155 F 50-321 F	FALLB, O.B. FALLB, D.B. FALLB, D.B FALLB, O.B. FALLB, O.B.	8403070314 8403070316* 8403070321* 8403070325* 8403070327*	TOPREP TOPREP TOPREP TOPREP TOPREP
EDELMAN, M R EDELMAN, M R EDELMAN, M R EDELMAN, M R EDELMAN, M R,	8403130174 8403170051 8403170375 8403170371 8403230011	50-440 F 50-440 B 50-440 A 50-440 A 50-440 S	ELBENHUT, D G ELBENHUT, D G ELBENHUT, D. G ELBENHUT, D. G EJIMA, M	8403260308* 8403280127 8403280283 8403280287 8403050033	50-344 F 50-483 A 50-397 P 50-374 P XPORTLIC	FALLB, Q.B. FALLB, O.B. FALLB, O.B FALZONE, R FALZONE, R.R	8403070328* 8403070330* 8403300237* 8403130012 8403130012	TOPREP TOPREP TOPREP 50-322 9 50-322 9
EDELMAN, M. R. EDELMAN, M. R. EDELMAN, M. R. EDELMAN, M. R. EDELMAN, M. R.	8403230045 8403230047 8403230083 8403230101 8403250247	50-440 S 50-440 A 50-440 S 50-440 S	EL-BASSIONI, A ELDER, M L ELLIOTF, C W ELLIOTF, C W. ELLIOTT, C W	8403010041* 8403270314 8403270060 8403270069* 8403300129	FOIA 50-270 P 50-352 0 50-352 0 50-352 0	FALZÖNE, R. R. FALZÖNE, R. R FALZÖNE, R. R. FALZÖNE, R. R FARBER, M. J.	8403130109* 8403130109* 8403260377 8403260377 8403080261*	50-322 9 50-322 9 50-322 T 50-322 T 50-483 0

AUTHOR	ACCESSION NUMBER	SUBJE		AUTHOR	ACCESSION NUMBER	SUBJECT CATEODR	Y	AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGORY
FARMER, W. B FARRAR, D FARRAR, D. L FARRAR, D. L FARRAR, D. L	8403290012; 8403020131 8403050171; 8403050174; 8403140151	50-295 50-373	a	FELTON, J M FELTON, J M FELTON, J M FELTON, J. M FELTON, J. M	8403040467 8403040484 8403070101 8403070110 8403070215	FOIA 50-329 FOIA FOIA 50-440	A A	FINN, 8 FINN, 8 FINN, 8 FINN, 8 FINN, 8	B403080010* 8403080012* 8403080017* 8403080017* 8403080025*	FOIA FOIA FOIA FOIA
FARRAR, D. L. FARRAR, D. L. FARRAR, D. L. FARRAR, J. P. FARRELL, E. V.	8403190090± 8403200041 8403260237± 8403010397 8403130426	50-373	Q F Q R B	FELTON, J M FELTON, J, M FELTON, J, M FELTON, J M FELTON, J M	B403070⊒27 6403080003 6403060014 6403060027 6403080030	50-327 FOIA FOIA FOIA FOIA	8	FIORELLI.0 FIORELLI.0 FIORELLI.0 FIORELLI.0 FIBCHER.D L	8403070340* 8403070343* 6403080263* 8403270139* 8403270022*	50~329 B 50~329 G 50~528 G 50~528 G
FARRELL, R E FABAND, A. FABAND, A FABAND, A FABOND, A.	8403050134* 8403060103 8403060144 8403060435 8403130471*	50-458 50-320 50-320 50-320 50-320	G 5 5 9	FELTON, J M FELTON, J. M FELTON, J M FELTON, J M FELTON, J M	8403080068 8403080096 8403080126 8403080179 8403080203		E A Q	FISCHER, D L FISH, R F FISHCHOFF, D FISHER, R FISHER, W L	8403274024* 8403080152* 8403190444 8403150340* 8102240058*	50-273 P 50-528 Q NUREO 40-8927 FOIA
FAURZIN F. FAMELLIT.W. FAYIC.W FAYIC.W FAYIC W.	8403080214* 8403020130 8403060358 8403070255 8403120066	50-316 40-2061 50-266 50-266	P :	FELTON, J. M. FELTON, J. M FELTON, J. M. FELTON, J. M. FELTON, J. M	8403080207 8403080219 8403080325 8403080339 8403080347	50-280	g g P	FITCH.W L. FITTI.C V. FITZOERALD.J A FITZPATRICK,B FLACK.E	8403120174 8003240217* 8403020094* 84030130023* 8403010375	50-508 D 50-508 A FOIA 50-246 G
FAY, G. W FAY, G. W. FAY, G. W FAY, G. W FAY, G. W.	8403120157 8403130005 8403140139 8403160054 8403160080	50-266 50-266 50-266 50-266 50-266	P R P F	FELTON, J. M.	8403080357 8403080367 8403080372 8403080375 8403080376	50-424 FDIA	A Q D	FLACK, E. FLACK, E FLACK, E FLACK, E. FLACK, E.	8403050094 8403060119 8403130408 8403130445 8403160001	196 20-591 8 196 196 196
FAY, C. W FAY, C. W. FAY, C. W. FAY, C. W FAY, C. W.	8403210029 8403210077 8403220099* 8403220162 8403230068	PR 50-266 50-266 50-266 50-301	8 6 5	FELTON, J. M FELTON, J. M. FELTON, J. M. FELTON, J. M. FELTON, J. M	8403080391 8403080378 8403080404 8403080405 8403080419		E O	FLACK, E FLEENDR, C FLEIBCHMANN, R FLIPPO, T A FLORY, C,	8403280049 8403280012 8403280012 8403130140* 8403280259	40-8681 CONTRACT 50-171 R 50-382 Q Waste Mot
FAY, C. W FAY, C. W FAY, C. W FAY, C. W FEDERMAN, P. J	8403240072 8403270078 8403270125 8403270237 8403300325	50-266 50-266 50-266 50-266 NUREQ	9 P P	FELTON, J. M FELTON, J. M FELTON, J. M FELTON, J. M FELTON, J. M.	8403070006 8403070017 8403070018 8403070021 8403070028	FOIA FOIA 50-322 FOIA 50-275	A	FLORY, 9, FLOWER, M FLYNN, 8 F FLYNN, 8, F FOLAHEE, J B,	8403050330 8403140233* 8403170137 8403170141* 8403170071	M18C 50-267 P 50-400 Q 50-400 Q 50-155 I
FEHRINGER, J. M FEIERABEND, C FEIERABEND, C. D FEITKNECHT, C, FELDER, R.	8403260335 8403290180* 8403190042* 8403010126 8403070267*	50-416 50-335 50-282 50-334 70-474	P G R	FELTON, J, M.	8403070032 8403250123 8403280080 8403280163	50-382 / 40-1478 FOIA FOIA FOIA	4	FOLEY, W J FONMER, R L FORD, E, J FORD, J T	8403080199* 8403220231 8403070163* 8403160225* 8403010162	50-275 G WASTE MOT 50-327 G 50-327 G 71-6206
FELTON, J. M.	8401230630 8401260161 8402090003 8402140018 8402230207	50-329 50-264 50-352 50-528 50-400	Q F A Q A	FELTON, J. M. FELTON, J. M. FELTON, J. M. FELTON, J. M. FEROUSON, C. E.	8403280216 8403270002 8403270338 8403270341 8403270102*	50-482 C 50-266 F FOIA 50-528 E 50-461 I)	FORNEY, W.L. FORRESTER, P.D. FOSTER, D.D. FOSTER, D.D. FOSTER, D.D.	8403170323* 8402140052* 8403010317 8403010354 8403070077	50-358 Q 50-528 Q 50-424 K 50-424 B 50-424 B
FELTON: J M, FELTON: J M FELTON: J. M. FELTON: J. M. FELTON: J. M.	8402270263 8403010013 8403010014 8403010016 8403010024	50-321 50-447 50-289 50-334 FDIA	O A P S	FERKIN, Z. Q. FERKIN, Z. Q FERRELL, J. R. FEY, F. L FEY, F. L.	8403120001 8403300122 8403080154* 8403060285 8403090207	50-352 G 50-352 G FOIA 50-243 F 50-282 F	.	FOSTER, D. O. FOSTER, D. O. FOSTER, D. O. FOSTER, D. O. FOSTER, D. O.	8403120146 8403150023 8403150038 8403150043 8403150069	50-424 8 50-424 H 50-424 V 50-424 B 50-424 B
FELTON, J. M.	8403010026 8403010050 8403010068 8403010092 8403010094	FDIA 50-309 FDIA FDIA	A	FEY,F L FEY,F.L. FEY,F L FIEDLER,D G FIEDLER,P.	8403130079 8403130245 8403300130 8403190203 8403160057	50-263 R 50-282 R 50-282 P GAP99 50-219 R		FOSTER, D G FOSTER, D. O. FOSTER, E R FOSTER, J. FOSTER, J	8403190105 8403290037 8403010219 8403050106 8403070332	50-424 8 50-424 0 50-336 6 50-367 F 50-367 F
FELTON, J M, FELTON, J, M, FELTON, J, M, FELTON, J, M, FELTON, J, M,	8403010100 8403010113 8403010117 8403010123 8403010125	FDIA 50-508 50-348 50-312 50-498	T P P Q	FIEDLER, P. B FIEDLER, P. B FIEDLER, P. B. FIEDLER, P. B. FIEDLER, P. B.	8403010256 8403010261* 8403020128 8403080231 8403090073*	50-217 8 50-217 8 50-217 R 50-217 V 50-217 Q		FOBTER, L. FOBTER, L. E. FOBTER, R. F FOBTER, R. F FOX, C. D	8403160319# 8403130499# 8403060111 8403200042 8403070120	50-413 Q 50-312 Q 50-506 Q 50-413 Q 50-461 Q
FELTON, J. M.	8403010168 8403010178 8403010262 8403010277 8403010383	FDIA 50-329 50-247 FDIA FDIA	Å	FIEDLER, P. B FIEDLER, P. B FIEDLER, P. B. FIEDLER, P. B. FIEDLER, P. B.	8403130177 8403150083 8403160208* 8403170063 8403200056	50-219 P 50-219 P 50-219 Q 50-219 F 50-219 Q		FOX;C D. FDY;J.M FRAGOLA,J FRANCE,G.M FRANKLIN;L.A	8403070120 8403070120* 8403010041* 8403130094* 8403290234*	50-461 0 50-461 0 FOIA 40-3392 50-302 Q
FELTON, J. M FELTON, J. M. FELTON, J. M. FELTON, J. M. FELTON, J. M.	8403010407 8403010410 8403010480 8403020011 8403020014	FOIA FOIA FOIA FOIA 50-267	P	FIEDLER,P.B FIEDLER,P.B. FIEDLER,P.B. FIEDLER,P.B. FIEDLER,P.B.	8403220002 8403220012 8403220152 8403230110 8403230119	50-219 P 50-219 P 50-219 P 50-219 R		Freeman, M. D Freeman, M. D Freeman, M. D Freeman, B. D Freudenburo, W	8403010071 6403150272 6403150274 6403200057 6403200236	40-8768 40-8785 40-8785 50-259 Q 50-508 D
FELTON, J. M. FELTON, J. M. FELTON, J. M. FELTON, J. M. FELTON, J. M.	8403020109 8403020395 8403020405 8403020435 8403050020	FOIA 50-289 FOIA 50-440 50-286	P A P	FIEDLER, P.B. FIEDLER, P.B. FIEDLER, P.B. FIELDB, D. FIELDB, J.A.	8403260074 8403270165 8403300001 8403060283 8403130494	50-219 R 50-219 P 50-219 R 50-302 R CONTRACT		FRIEDMAN FRIEND, H. B. FRIBHMAN, S. FRITZ, D. M FRIZZLE, C. D	8402210133 8403120022* 8403230025 8403150212 8403300160	1&E 50-275 Q WASTE MOT 40-8463 50-309 G
FELTON, J. M.	8403050057 8403050060 8403050064 8403050223 8403050288	50-305 50-509	E P A	FIELDS: J. B FINAMORE. B. A. FINAMORE. B. A FINKEL: A. FINKEL: A	8403070232 8403170120 8403170120 8403070242+ 8403070043+	50-387 S 50-537 G 50-337 G 50-387 G 50-354 G		FRYE, D. L. FRYE, D. L. FRYE, J. H FRYE, J. H.	8403010155# 8403010167# 8403070079 8403070119 8403170177	50-267 8 50-267 8 40-2061 40-2061 50-142 0
FELTON, J. M. FELTON, J. M. FELTON, J. M. FELTON, J. M FELTON, J. M	8403060091 8403060123 8403060148 8403060158 8403060169	FDIA FOIA FOIA FDIA		FINLAYBON, F. C, FINN, D. F. FINN, D. F. FINN, B, FINN, B	8403220305* 8403210034 8403230030 8403080006* 8403080008*	50-322 T HASTE HOT HASTE HOT FDIA FOIA		FRYE, J. H. FUJITA, N. FULLER, C FULTON, J. P. FULTON, J. F.	8403260003 8403080009# 8403170344 8403270188# 8403270189#	50-149 0 50-27 P 50-267 R 50-244 P 50-244 P

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATERORY
FUNCHEB.J L FURR.B J FURBE.M C FURBE.M C FURBE.M C	8301140486* 8403150070 8403040168 8403040168 8403040202*	50-267 P 50-324 S 50-155 G 50-155 G 50-155 G	GAYNDR.R K GEALY.W J GEBELE,H W GEKAS.G W GERDEMAN,F W	8403020377 8403050237* 8403010409 8403070073* 8403150813	27-48 CONTRACT FDIA 50-269 U 40-8698	QLASSPIEGEL, H GLENN, J GLENN, J GLENN, J GLENN, J E	8403060280* 8402210133 8403070283 8403080060* 8403070264	50-440 Ø 1&E 50-293 Ø FOIA 70-474
FURSE,M C FURSE,M C GAD,R K GAD,R,K GAD,R,K	9403060202* 9403120035 8403070042 8403070042 8403080142	50-155 G 50-155 G 50-443 G 50-443 G 50-443 G	GERDEMAN,F W GERDEMAN,F W GERETY,H F GERNER,L GERNETS,T F	8403150249 8403220183 8403280010 8403090894 8403010069	40-8698 40-8698 50-269 J 50-254 F 50-382 8	GLOERBEN. W GLENN, J E GLENN, J E GLENN, J E	8403080050* 8403080070* 8403080087* 8403080102* 8403200119*	FOIA FOIA FOIA FOIA 50-483 Q
GAD, R K GAD, R K GAD, R K GAD, R K	8403080142 8403210101* 8403210101* 8403230180 8403230180	50-443	CERRETS, T F	8403060196 8403060258 8403060339 8403130267 8403130303	50-382 8 50-382 8 50-382 8 50-382 8 50-382 8	GLDVER: M 8 GLOVER: M 8 GODDARD: R GODDARD: R J GODDARD: R J	8403070276 8403140231 8403070123* 8403140057 8403140076	50-369 F 50-369 F 50-461 G 50-461 G 50-155 G
GAD.R.K GAD.R K GAGLIARDO.J E GAGLIARDO.J E GAGLIARDO.J E	8403300267 8403300269 8402210343* 8402210348* 8403050179	50-443	GERRETS,T F GERRETS,T F GERRETS,T F GERRETS,T F GERRETS,T F	8403130311 8403130337 8403130427 8403130436 8403170250	50-382 8 50-382 8 50-382 8 50-382 8	GDDDARD,R J GDDDARD,R J GDDDARD,R J GDDDARD,R J GDDDARD,R J	8403140097* 8403140106 8403140126 8403140135 8403140142	50-155 Q 50-461 Q 50-322 Q 50-461 Q 50-461 Q
GAGLIARDO, J E GAGLIARDO, J E GAGLIARDO, J E GAGLIARDO, J E GAGLIARDO, J E	8403060198 8403120147 8403130120 8403130250 8403130320	50-313 @ 50-285 @ 50-313 @ 50-482 @ 50-482 @	CERRETS.T F CERRETS.T F CERRETS.T F CERRETS.T F CERRETS.T F	8403170253 8403170262 8403170272* 8403170368 8403200022	50-362 B 50-382 S 50-382 0 50-382 S 50-382 S	GODDARD.R J GODDARD.R J GODY.A T GODY.A T GODY.A T	8403170217 8403170220* 8403020220* 8403020377* 8403270150*	50-416 Q 50-416 Q 50-388 Q 50-293 Q 50-352 Q
GAGLIARDO, J E GAGLIARDO, J E GAGLIARDO, J E GAGLIARDO, J E QAGLIARDO, J E	8403130390 8403130395 8403140119 8403190057 8403190225	50-482	GERRETS.T F GERRETS.T F GERRETS.T F GERRETS.T F GERRETS.T F	8403200267 8403200276 8403270040 8403270046 8403270059	50-382 8 50-382 8 50-382 8 50-382 8 50-382 8	ODLDBERG, JR. ODLDBERG, JR ODLDBERG, SM. ODLDEN, MP ODLDEN, MP	8403010043* 8403210024 8403130499* 8403260197 8403280058	50-289 P 50-289 Q 50-312 Q 50-272 J 50-272 J
GAGLIARDD. J E GAGLIARDD. J E GAGLIARDD. J E GAGLIARDD. J E GAGLIARDD. J E	8403190277 8403190279 8403190283* 8403200149 8403200178	50-313	GERRETS,T F GERRETS.T F GERRETS.T F GERRETS.T F GERRETS.T F	8403270095 8403270102 8403270161 8403270202 8403270206	50-382 8 50-382 8 50-382 8 50-382 8	GODE, D GODDE, D	8403050028* 8403130327 8403210078 8403160056 8403160077	50-275 Q PR 50-322 Q WASTE MOT 27-39
GAGLIARDO, J E GAGLIARDO, J E GAGLIARDO, J E GAGLIARDO, J E GAGLIARDO, J E	8403220185 8403260090 8403260168 8403260230 8403300046	50-313 F 50-313 Q 50-285 Q 50-313 Q 50-313 Q	GERWIN, E F. GIACOBBE, F. B GIAMBUSSO, A GIANGI, Q J GIBBONS, T D	8403270155 8403130451* 7711120403* 8403270232 8403060252*	MISC 50-289 0 FOIA 50-289 F 50-322 T	ODDDIE, J 9 ODDDLING, B ODDDMAN, L. B ODDDMAN, L. B ODDDMAN, L S	8403010344 8403210137 8403020161 8403200163 8403300131	27-39 50-289 @ 50-409 R 50-409 B 50-409 R
GAITHER.C F GALLAGHER.J R GALLO,J GALLO,J	8402140037* 8403090055 8403080227 8403010203 8403010203	50-528 0 50-352 0 50-454 D 50-155 0 50-155 0	D T.ENDEBIO L.NDEBIO L.NDEBIO D M.NDEBIO O M.NDEBIO	8403270154* 8403020133 8403300080 8403270303 8403280107	50-416 G 50-336 R 50-336 R 50-348 F 50-348 F	GODDWIN, E F GORDON, C Z GORDON, R GORDON, R GOBCH, C	8208070297* 8403210054* 8403220264 8403220279 8403130106*	50-286 0 50-320 0 XPORTLIC XPORTLIC 50-440 A
GALLO, J GALLO, J GALLO, J GALLO, J	8403060192* 8403060192* 8403060202* 8403060202* 8403160011	50-135 9 50-135 0 50-155 0 50-155 9 50-136 0	A C. SABESIO O LESEME, J O LESEME, J O LESEME, C W O REALER, C W O REALER, C W	8403050227 8403050230 8403050242 8402170104 8403020295	REB 50-280 P REB 50-305 P 50-305 P	GOSCH, C. GOSCH, C. GOSSICK, L V GOSSICK, L V	8403130118* 8403130128* 8403130138* 8402230226* 8402230242*	50-440 A 50-440 A 50-440 A 50-400 A FOIA
GVFFO' J GVFFO' J GVFFO' J GVFFO' J	8403160011 8403160023 8403160023 8403190004 8403190004	50-456 0 50-456 0 50-456 0 50-155 0 50-155 0	GIESLER,C W GIESLER,C W GIESLER,C W GIESLER,C W GIESLER,C W	8403040408 8403130147 8403130188 8403140278 8403140327	50-305 R 50-305 R 50-305 P 50-305 J 50-305 P	GDSSICK, L V GDTCHY, R GDULD, T. L GRACE, J. N GRADY, D	8403050031# 8005150683* 8403280006 8402090007 8403280125	FOIA FOIA 50-320 8 50-3 G 50-280 F
GALLO, J GALLO, J GALLO, R. GALLO, R. M GAMMIE, G. B	8403200130 8403200130 8403150073* 8403020308* 8403140036	50-155	GIEGLER, C, W GIEGLER, C W GIEGLER, C, W GIEGLER, C W GIEGLER, C W	8403200016 8403200154 8403210007 8403270030 8403280048	50-305 Q 50-305 P PR 50-305 P 50-305 P	GRAESBER, K. L. GRAESSER, K. L. GRAESSER, K. L. GRAESBER, K. L. GRAESBER, K. L.	8403060217 8403060249 8403080174 8403090164 8403090174	50-275 R 50-275 S 50-304 O 50-275 S 50-304 S
GAMMILL.W P GANT, R E. GARCIA, A A GARCIA, P. J GARCIA, P. J	8207140072* 8403270107* 8403140334 8403060465 8403170431	50-400 E 50-461 I ACRS 40-3453 40-3453	GIESLER, J V GILBERT, G D GILINSKY, V GILINSKY, V	8403270222 8403090274 8403200043 8403200075 8403280157#	GA999 50-349 F 50-454 U 50-454 U CDMMISSION	Graesber, K. L Graesber, K. L Graesber, K. L Graesber, K. L Graesber, K. L	8403190156 8403200173 8403270035 8403270109 8403270203	50-295 R 50-304 B 50-295 B 50-295 B 50-295 B
GARCIA.P.J GARDE.B P GARDE.B P GARDE.B P GARDE.B P	8403200379 8403010172 8403010488 8403020102 8403080085	40-3453 50-329 A 50-329 A FUIA 50-275 E	GILINSKY,V GILLEN,D,M GILLET,W T GILLETT,W T	8403280248 8403200372 8403080007 8403080044 8403300155	CDMM1981DN 40-8829 50-316 R 50-315 R 50-316 R	ORAEBBER, K.L. ORAHAM, D. ORAHAM, D. ORAHAM, J. O. ORAMM, R.A.	8403270265 8403060283 8403160036 8403220175 8403150101*	50-295 B 50-302 R 50-302 R 50-320 P 50-410 Q
GARDE, B P GARDER, B P GARDNER, R, N GARNER, D GARNER, L, W	8403080196 8403270173 8403060398* 7906140545* 8403070310*	50-413 A 50-445 H 50-329 Q 50-312 P 50-324 Q	GILLETT, W T GILDMEN, B R GILDMEN, B R. GILDMEN, B, R GILDMEN, B R.	8403300157 8403020146* 8403020146* 8403200011 8403200011	50-315 R 50-295 0 50-295 0 50-329 0 50-329 0	GRANGE, G Grange, G. J Grange, G. J Grant, N. H Grant, N. H.	8403270073 8403140088 8403150118 8403020033 8403300185*	50-320 F 50-289 F 50-320 F 50-250 R 50-250 R
GARMER, L. W GARY, R J. GARY, R J. GARY, R J. GARY, R J.	8403270072* 8403060135 8403080335* 8403160077 84031600213	50-324 Q 50-445 A 50-445 Q 50-445 A 50-445 S	GILONEN, B R. GILOMEN, B R. GILECLON, J M GLASS, D. J GLASS, J.	8403270020 8403270020 8403120027# 8403140221 8403170447	50-329 0 50-329 0 50-275 0 PRM NUREQ	ORANT, N W. ORANT, W B. ORAVES, R. H. GRAVES, R. H ORAY, E. H	8403300173* 8403200291* 8403020073 8403300176 8403020379*	50-250 R 50-263 G 50-213 R 50-213 R 50-293 G
GABANDIA. GAVAZZIA A GAVIÇAN.F X. GAVIÇAN.F X GAVDOB.J.M	8403050110 8403130302* 8403050357 8403090055 8403090013*	50-320 8 70-2199 50-537 A 50-537 0 50-289 U	GLASSER.D GLASSPIEGEL.H GLASSPIEGEL.H GLASSPIEGEL.H GLASSPIEGEL.H	8403230038 8403040237 8403040257 8403040275 8403040275	50-322 T 50-440 G 50-440 G 50-440 G 50-440 G	ORAY, E. H. ORAY, E. H. ORAY, E. H. ORAY, E. H. ORAY, E. H.	8403150034* 8403290062* 8403290104* 8403290191* 8403290292*	50-388 0 50-334 0 50-219 0 50-289 0 50-29 0

AUTHOR	ACCESSION NUMBER	BUBJE		AUTHOR	ACCESSION	BUBJEC CATEGO		AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
GRAY, J. R GRAY, J. R GREENMAN, E. GREENMAN, E. Q GREEVEB, J. T	8403190022# 8403270300 8403020238 8403220103# 8403040432	50-289 50-210	7 0 3 B 7 G	Haass, W P Haass, W P Haass, W P Haass, W P Haass, W P	7708010232* 8011120101* 811019051* 8110210316* 8111020578*	50-397 FOIA 50-397 50-460 50-508	A A A	HARRAN. 0 HARRELL. E H HARRELL. E H HARRIGAN. N F HARRINGTON. T E	8403300135 8403060153 8403140010 8403060118 8403150008	50-245 50-336 50-336 40-2061 50-273
GREEVEB, J T GREGER, L R GREGER, L R GREGER, L. R GREGER, L R.	8403280267 8403130094# 8403190334# 8403200291# 8403220097#	WASTE 40-335 50-295 50-263 50-454	72 5 Q 9 Q	HAASS,W P HACKNEY,C A HACKNEY,C A HADLEY,R T HAEHL,J,G	8201300236* 6403130402* 6403130402* 6403190266* 6403170449 6403270177	50-397 50-313 50-313 NUREG 50-220	A G G	HARRINGTON, W D	8403010324 8403070341* 8403070047 8403070147 8403070152	50-273 . 50-273 . 50-273 . 50-273 .
GREGER, L. R. GREGER, L. R. GRIDLEY, K. L. GRIDLEY, R. L. GRIER, B. H.	8403230023 8403270242* 8403270024* 8403270022* 8403080032*	50-255 50-409 50-293 50-293 FDIA) (t	Hafner, B Hagan, T. Hagan, T. F Hagan, T. F Hagan, T. F	8403080363 8403010534* 8403010044* 8403010045* 8403010060*	50-322 CONTRACT CONTRACT CONTRACT	ा इ	HARRINGTON, W D HARRINGTON, W D HARRINGTON, W D HARRINGTON, W D HARRINGTON, W D	B403130255 B403140107 B403150117* B403150177 B403200164	50-293 ; 50-293 ; 50-293 ; 50-293 ;
ORIER, B. H ORIER, B. H. ORIER, B. H ORIER, B. H ORIER, B. H.	8403080043* 6403080059* 8403080072* 8403080079* 8403080107*	FOIA FOIA FOIA FOIA		HAGAN, T. F HAGAN, T. F HAGAN, T. F HAGAN, T. F. HAGAN, T. F.	8403010437* 8403070373* 8403120314* 8403120345* 8403150278*	CONTRACT CONTRACT CONTRACT CONTRACT	r r r	HARRINGTON, H D HARRINGTON, H D. HARRINGTON, H D HARRIS, D HARRIS, D	8403240317* 8403270010 8403270035 8403040204 8403040310*	50-293 (50-293 ; 50-293 ; 50-225 ; 50-322 ;
ORIFFIN, J M ORIFFIN, J M. ORIFFIN, J. M ORIMES, C. I. ORIMSLEY, D H	9403060199 8403150037 8403260051 8403160074 8304060552*	50-313 50-313 50-313 50-409 50-397	P P P	HAGAN, T.F. HAGEN, E.W HAGER, G.W HAGUE, R.L. HAIRSTON, W.G	8403260322* 8403010102* 8403130137 8403130023* 8403010422*	CONTRACT FDIA 50-320 50-264 50-364	r e s	HARRIS, D HARRIS, D R HARRIS, D R HARRIS, D R, HARRIS, H G,	8403220310* 8403190437 8403200229 8403260156 8403120244#	50-322 NUREO 50-225 50-235
Ordbe, J.A. Ordbe, P.J Ordbeman, H Ordbeman, K. Ordbeman, K.	8403120145# 8403080090 8403060102 8403010474 8403090016	50-263 50-537 50-416 FDIA FDIA	g A o	HAIRSTON, W C. HAIRSTON, W C. HAIRSTON, W. C HAIRSTON, W C HAIRSTON, W C	8403010428* 8403070243 8403130084 8403260026* 8403260032*	50-364 50-348 50-348 50-348 50-348	8 8 8 8	HARRIS.H G HARRIS.J.D HARRIS.JR HARRIS.R H HARRISON.F	8403120252* 8403010102* 8403290179* 8403150034* 8403090011*	50-335 i FOIA 50-400 a 50-388 ii 50-289 ii
GROTENHUIS, M GROTENHUIS, M GRUNEWALD, R GUADAGNO, V GUCWA, L. T	8403150124 8403300254 8403270238 8403220173* 8403050085	50-324 50-324 PAM 40-8824 50-321	Р Р \$	HAIRSTON, W. C. HAIRSTON, W. C. HAIRSTON, W. C. HAIRSTON, W. C. HALE, C.	8403240040* 8403240044* 8403300134 8403300172 8403130042*	50-348 50-348 50-364 50-348 04779	8 8 R R	Harrison, F Harrison, G Harrison, G Harrison, J Harrison, J	8403130333 8403270346 8403300287 8403010276 8403060288	50-324 R 50-461 A 50-461 F 50-329 A 50-329 ö
GUCHA, L. T. GUCHA, L. T GUCHA, L. T GUCHA, L. T. GUCHA, L. T	8403070251 8403160349* 8403200005 8403200262 8403290212*	50-321 50-321 50-321 50-344 50-321	9 9 9 0	HALE, C J HALE, C J HALE, C, J HALE, C J HALE, C J	8403130325# 8403130425# 8403130432# 8403130440# 8403190190#	GA979 GA979 GA999 GA999 GA999		L C.NOSIBRAH L C.NOSIBRAH L C.NOSIBRAH L C.NOSIBRAH L C.NOSIBRAH	8403040398* 8403130153 8403130482 8403200084 8403220082	50-327 0 50-327 A 50-327 A 50-327 A
QUCWA, L. T. QUEHRING, J. B. QUERRY, J. E. QUILBERT, D. E. QUILD, R.	8403300104 8403050156* 8403050111 8403130058* 8403070037*	50-321 40-472 50-238 64999 50-413	\$ R O	HALE, C. J. HALL, B. L. HALL, D. P. HALL, D. P. HALL, D. P.	8403270184* 8403160388* 8403080240 8403190175* 8403190398	GA999 50-302 50-461 50-461 50-461	G B Q A	HARRIBON, 8 F HARTFIELD, R A HARTGEN, D T HARTIGAN, N F HARTMAN, 8 L	9403130289 8112020204* 8403130071* 8403070027 8403080324	50-358 A 50-412 A 50-322 Q 40-2061 50-445 Q
QUILD, R. QUILD, R QUILD, R QUILD, R. QUILD, R.	8403070037* 8403070112 8403070112 8403070115* 8403070115*	50-413 50-413 50-413 50-413 50-413	0 0 0 0	HALL, D.P. HALL, D.P HALL, R.E HALL, R.E HALL, R.E.	8403200193* 8403260255 8402140325 8403010041* 8403260068*	50-461 50-461 40-8102 FOIA 50-458	A B G	HARTMAN, B L HARTMAN, B L HARTMAN, B L HARTMAN, B L HARTMAN, S L	8403210170 8403210170 8403210172 8403210172 8403210189	50-508 Q 50-508 Q 50-508 Q 50-508 Q 50-508 Q
GUILD, R GUILD, R. GUILD, R. GUILD, R. GUILD, R.	8403220233 8403220233 8403220233 8403290379 8403290379	50-413 50-413 50-413 50-413 50-413	0 0 0 0	HALL.R E HALL.R.E HALL.R E. HALLER.R.E HAMEL.D B.	8403260077* 8403260102 8403260138 8403070014* 8403120137	50-313 40-1341 40-8102 50-528 50-331	e e	HARTMAN, B. L HARTMANN, F. L HARTZMAN, M HARVEY, R. C. HASHINOTO, P. S	8403210187 8403170042* 8403170106* 8403200270* 8403200152*	50-50B 0 50-282 0 50-275 0 50-29 P 50-423 A
OUILD, R QUILD, R, QUILD, R, QUILD, R QUINN, P, R,	8403270382 8403270388 8403270388 8403270388 8403020408*	50-412 50-413 50-413 50-413 FOIA	000	Hamid, a a Hamid, a. a. Hamilton, g. W Hamilton, J. Hamilton, p	8403120244* 8403120252* 8403120182 8403270241* 8403200164	50-335 50-335 50-483 0A999 50-293	G G A	HABBE:R A, HABBELL,D F HATHAWAY,Q H HATHAWAY,Q,H HAUGHEY,M F	8403040174# 8403140075 8403130008 8403300138 8403010298	50-266 G 50-329 O 50-341 A 50-341 A 50-410 A
QUINN, F. R. QULBRANSEN, E. A. QULDEMOND, W. Q. QUMBLE, F. W QUMBLE, F. W	8403020412* 8403160041 8403190076* 8403120152 8403150047	FOTA 50-320 50-373 50-286 50-286	ዶ G S S	HAMILTON, P. HAMMER, M. F. HAMMITT, H. A. HAMMITT, H. A. HAMMOND, E.	8403260134 8403130365 8403020008 8403280166 8403130487*	FOIA FOIA	8 F	HAUGHEY, M.F. HAUGHEY, M.F. HAVERKAMP, D. HAWKING, D. A.	8403050371* 8403060539 8403270394 8403070287* 8403010040	50-410 A 50-410 A 50-410 A 50-289 G CONTRACT
OUMBLE, F. W OUMBLE, F. W OURLEY, M. K. OUSTAVE, R. P. OUSTAVE, R. P.	8403150050 8403210047 8403060366# 8403010004# 8403010027#	50-266 50-266 50-302 CONTRACT		HANCOCK, J A HANNETT, B A HANNETT, B A HANNETT, B A HANNETT, B A	8403300115* 8403020024* 8403020453* 8403140308* 8403150149	50-302 XPORTLIC XPORTLIC XPORTLIC XPORTLIC	8	Hawkins.e Hawkins.e Hawkins.e Hawkins.e Hawkins.e	8403150270 8403200320 8403190415 8403190418 8403200335*	CONTRACT 40-8829 40-8829 40-8829 40-1341
QUSTAVE, R. P. QUSTAVE, R. P. QUSTAVE, R. P. QUSTAVE, R. P. QUSTAVE, R. P.	8403010078* 8403010462* 8403070046* 8403070141* 8403140328*	CONTRACT CONTRACT CONTRACT CONTRACT	r r	HANNETT, B. A. HANNETT, B. A. HANNETT, B. A HANNETT, B. A HANNETT, B. A	8403160169 8403160184* 8403260027 8403260030* 8403280035*	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC		Hawking, e.f. Hawking, e.f. Hawking, e.f. Hawking, e.f Hawking, e.f	8403200355 8403200360 8403200363 8403200375 8403220182	40-874B 40-8481 40-8481 40-8748 40-8768
QUBTAVE, R. P. QUBTAVE, R. P. QUBTAVE, R. P. QUT, M. QUTHRIE, B. C.	8403150176* 8403230160* 8403270362* 8403070186 8403170076*	CONTRACT CONTRACT CONTRACT PRM 50-373	7	HARAM, B. A. HARAM, B. A. HARAM, B. A. HARD, J. E. HARDEN, K. G.	8403080044* 8403080111* 8403080134* 8403170042* 8403150340*	FOIA FOIA FOIA 50-282 40-8829	a	HAWKINB, E.F. HAWKINB, E.F. HAWKINB, E.F HAWKHURBT, J.J HAYDEN, T.	8403220190 8403220194 8403230157# 8403210016# 8403270364	40-8829 40-8502 40-8745 50-317 Q 50-275 P
QUTHRIE, W. L. QUTTMAN, D. QWYNN, T. P. MAABB, M. HAABS, W. P.	8403270304* 8403270176 8403170323* 8403270342* 7706170142*	50-250 50-458 50-358 FDIA 50-460	O M Q	HARDOROVE, T W HARDTY, R HARMON, D W HARMON, D. W. HARRAN, Q.	8403150342 8403190449 8403150134 8403150142# 8403020055	40-2259 NUREO XPORTLIC XPORTLIC 50-245	R	MAYES, B. B HAYES, D. W. HAYNES, J. Q. HAYNES, J. Q HAYNES, J. Q	8403280339 8403130430* 8403020010 8403020218 8403050003	50-445 Q 50-461 Q 50-361 R 50-206 R 50-361 B

AUTHOR	NUMBER ACCESSION	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUB-JECT CATEGORY
Haynes, J. C Haynes, J. Q Haynes, J. Q Haynes, J. Q Haynes, J. Q.	8403060174 8403060378 8403060403 8403060438 840308044	50-206 8 50-361 8 50-361 8 50-206 R 50-361 8	HIGOINBOTHAM, L HIGOINBOTHAM, L HIGOINBOTHAM, L, HIGOINB, B J HIGOINB, T	8403160072 8403260043 8403280254 8403080027* 8403090204	HASTE MOT HASTE MOT HASTE MOT FOIA 50-483 F	HORIN, W.A HORIN, W.A HORIN, W.A HORTON, W HORTON, W	8403140013 8403140020 8403140020 8403080006# 8403080008#	50-445 9 50-445 9 50-445 9 FDIA
Hayneb, J O.	8403150033	50-361 8	HILDENBRAND, P	8403200355	40-8768	HORTON; W	8403080010*	FOIA
	8403150057	50-361 8	HILDENBRAND, P	8403200360	40-8681	HORTON; W	8403080012*	FOIA
	8403150074	50-361 8	HILDENBRAND, P.	8403200363	40-8681	HORTON; W	8403080017*	FOIA
	8403200053	50-361 R	HILDENBRAND, P	8403200375	40-8768	HORTON; W,	8403080019*	FOIA
	8403200175	50-362 8	HILL, C, Z.	8403280039	40-8584	HORTON; W,	8403080025*	FOIA
HAYNEB, J O	8403200194	50-361 8	HILL, E.E.	8403150016	50-498 0	HOBEY, C. M	8403160240*	50~390 Q
HAYNEB, J O	8403210065	50-206 8	HILL, L.J	8403200358	Nureo	HOUSTON, M. D	8403020406	50~416 8
HAYNEB, J O	8403270164	50-362 8	HILL, M.B	8403080029*	Foia	HOUSTON, M. D	8403230273	50~416 P
HAYNEB, J O	8403270856	50-264 F	HILL, M.H	8403190323*	50-358 0	HOUSTON, M. D	8403300251	50~416 P
HAYNEB, J, O	8403280002	50-361 8	HILLMAN, R.E	8403230112*	50-219 r	HOUSTON, R. W	8203180004*	50~460 C
HAYNES, J Q HEALD, A F HEATON, T. H HEBDON, F. J HEBDON, F. J	8403300003 8403210107 8403260088* 8403070121 8403140203	50-204 R PRM 50-344 P NUREO 50-206 S	HILLY, C. F HINCKLEY, D. Q HIND, J. A HIND, J. A. HIND, J. A	8403010078* 8403130497* 8403170314 8403170321* 8403170321*	CONTRACT 50-312 G 50-295 G 50-295 G	HOUBTON, R. W HOUBTON, R. W HOVI, L HOUE, H	8301260036* 8310310445* 8312230261* 8403070256 8403130167	50-400 E 50-400 E 50-336 P 50-217 B GA999
HEDGLON, M	8403210019	40-2061	HIND, J A. HIND, J A. HIND, J A. HIND, J A. HIND, J A	840327008&	40-8760	HOWE: H.	8403200076*	GA999
HEDGLON, M	8403290389*	40-2061		8403270233	50-409 G	HOWE: P. W.	8403060276	50-324 P
HEETHER, W. H	8403010463	XPORTLIC		8403270238*	50-409 G	HOWE: P. W.	8403060300	50-324 P
HEETHER, W. H	8403050044	XPORTLIC		8403270255*	50-454 G	HOWE: P. W	8403070137	50-324 P
HEFLIN, H	8403190060*	50-320 H		8403270263*	50-454 G	HOWE: P. W.	8403070200	50-324 Q
HEHL, C, W, HEIDER, L, H HEIDER, L, H. HEIDER, L H HEIDER, L H	8403070136# 8403020072 8403020272 8403219068 8403300083	50-395 @ 50-29 R 50-29 R 50-29 R 50-29 R	HIRBCH, D HOBBS, N.A. HOBBS, N.A HOBBS, N.A HOBBS, N.A.	8403260365 8403070165* 8403070178* 8403070170* 8403070222*	50-142 0 50-322 T 50-322 T 50-322 T 50-322 T	HOWE, P. W. HOWE, P. W. HOWE, P. W. HOWE, P. W. HOWE, P. W.	8403070315 8403070252 8403130452 8403210127 8403230047	50-325 4 50-324 P 50-325 P 50-325 P
Heidker, J C Keinz, J. Heinz, J Heibhman, R, F Heitner, K L	8403150223* 8402220288 8402220303* 8212070382* 8403210208	WASTE HOT 50-287 U 50-289 U 50-440 A 50-309 0	HOCH, J. B HODDER, M. H HODDER, M. H HODDER, M. H HODDER, M. H	8403120027* 8403070135 8403070137* 8403070143* 8403070143*	50-275 0 50-250 0 50-250 0 50-250 0 50-250 0	HOYLE, A HOYLE, A HOYLE, A. HOYLE, A.	8403220325 8403230044 8403270282 8403270302 8403280186	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
Heltemes. C. J.	8401250448*	50-267 P	HODDER, M. H	8403140017	50-250 @	HOYT, H, F,	8403090107	50-443 9
Heltemes. C. J	8402130042*	Misc	HODDER, M. H.	8403140017	50-250 @	HOYT, H F	8403190182	50-170 9
Heltemes. C. J	8403130140	Misc	HODDER, M. H.	8403140023*	50-250 @	HOYT, H F,	8403260343	50-443 9
Heltemes. C. J	8403280270	Misc	FRODDER, M. H	8403140023*	50-250 @	HBIEH, B, J,	8403070114	NUREO
Heltemes. C. J	8403280273*	Misc	HODGDON, A. F	8403140110	50-352 @	HBIEH, B B,	8403290189*	50-244 P
HELTEMES, C, J HELTEMES, C, J HELTEMES, C, J HELTEMES, C, J HELTEMES, C J,	8403280278* 8403280282* 8403280288* 8403280294* 8403280296*	Misc Misc Misc Misc	HODODON, A, P HODODON, A, P HODODON, A, P HODODON, A, P HOFFMAN, D, A	8403140115 8403210128 8403210167 8403270374 8403060301*	50-352	HUBBARD, Q. T HUBER, B. A HUCHTON, R. L HUDBON, B. D. HUDBPETH, J. B.	8403140214* 7406250470* 8403060533 8403130021* 8403140212	GA799 FDIA NUREG 50-220 G 50-348 F
HELWIG, D. R	8403020224	TOPREP	HOFFMAN, D P	8403020088	50-155 R	HUETER, L. J.	8403220097*	50-454 Q
HELWIG, D. R.	8403200127	TOPREP	HOFFMAN, D P	8403300152	50-155 R	HUFFMAN, Q. N.	8403290266*	50-302 Q
HEMBY, E. D.	8403270405*	XPORTLIC	HOFFMAN, J	8403140015	50-375 J	HUGHES, T. J.	8403290297	PR
HEMBERSON, J. 8,	8401230660*	50-329 B	HOFFMAN, J	8403280064	50-146 J	HUKILL, H. D.	8403010347	50-289 F
HEMBLEY, W. T.	8403300306	NUREG	HOFFMAN, T. E	8403150286	40-8829	HUKILL, H. D.	8403060133	50-289 F
HERBERT, R. J.	8403200113	50-336 S	HOGAN, R.	8403290120*	50-387 Q	HUKILL, H. D	8403060159	50-289 F
HERBORN, D. J.	8403130193	50-461 A	HOLBROOK, K. L	8403140170*	PR	HUKILL, H. D.	8403060160	50-289 P
HERBORN, D. I	8403130089	50-461 A	HOLDEN, C	8403220103*	50-309 Q	HUKILL, H. D.	8403060222	50-289 P
HERBORN, D. I	8403290093	50-461 I	HOLDER, E. T.	8403200213	50-259 S	HUKILL, H. D	8403060229*	50-289 P
HERING, R. F	8403200202	50-315 Q	HOLLAND, W. E	8403160222*	50-390 Q	HUKILL, H. D	8403060233	50-289 P
HERMANN, R. A	8403120224	50-220 P	HOLLAR, D. E. HOLLAR, D. E. HOLLAR, D. E. HOLLEHAN, D. HOLLEY, H. L	8403070051	50-400 Q	HUKILL, H. D.	8403080039	50-287 P
HERNAN, R.	8403190427	50-302 P		8403070055	50-400 Q	HUKILL, H. D.	8403090125	50-289 P
HERNAN, R. W	8107280171*	50-460 A		8403070058*	50-400 Q	HUKILL, H. D.	8403090244	50-289 0
HERNAN, R. W	8108110038*	50-460 A		8403290311	PRM	HUKILL, H. D.	8403120004	50-289 P
HERNAN, R. W.	8111060697*	50-460 A		8403260172*	50-285 Q	HUKILL, H. D.	8403120016	50-289 V
HERNAN: R. W. HERNAN: R. W HERNANDEZ: Q. M. HERR: J. C. HERR: J. C.	8112300305* 8209280165* 8403060149* 8403290188* 8403290189*	50-460 A 50-460 Q 50-275 Q 50-244 P 50-244 P	NOLLEY, W.L. HOLLOWAY, C.J. HOLLOWAY, C.J. HOLLOWAY, C.J. HOLLOWAY, C.J.	8403240250* 8003240207* 8004010752* 8004010757* 8112210135*	50-382 Q 50-508 A 50-508 A 50-508 A 50-508 A	HUKILL, H, D HUKILL, H, D, HUKILL, H, D, HUKILL, H, D,	8403120056 8403130286 8403150141 8403160006 8403160022*	50-289 P 50-289 F 50-289 R 50-289 P 50-289 P
HERR, P. B	8403060259*	50-322 T	HOLLOWAY, C, J	8403080253*	50-508 A	HUKILL, H D.	8403160024	50-287 F
HERR, P. B.	8403060289*	50-322 T	HOLLY, J T,	8402170107*	50-205 P	HUKILL, H, D	8403200068	50-287 F
HERR, P. B.	8403060307*	50-322 T	HOLMEB-RAY, P	8403290197*	50-266 G	HUKILL, H, D	8403200099	50-287 F
HERBCH, M. M	8403010484	XPORTLIC	HOLONICH, J J,	8403270240	50-482 A	HUKILL, H, D	8403210076	50-287 R
HERBCH, M. M	8403010545	XPORTLIC	HOLLOWICH, J, J	8403270271	50-483 A	HUKILL, H D.	8403210138	50-289 R
HERSCH, M. M.	8403050047	XFORTLIC	HOLONICH, J. J.	9403290015	50-483 A	HUMILL, H D.	8403230001	50-287 H
HERSCH, M. M.	8403050050	XFORTLIC	HOLTZ, J. J	8403020084	50-334 R	HUMILL, H D.	8403230040	50-287 P
HERSCH, M. M.	8403070381 *	XFORTLIC	HOLTZ, J. L.	8403300181	50-334 R	HUMILL, H, D.	8403230053	50-287 P
HERSCH, M. M.	8403220294 *	XFORTLIC	HOLZMAN, P. M.	8403060085	FOIA	HUMILL, H D.	8403270146	50-287 H
HEWARD, R. W	8403070203	SO-219 R	HOLZMER, M.	8403120137*	50-237 G	HULMAN, L. Q.	8204070079#	50-460 C
HIATT, B.L. HIATT, S.L. HIATT, S.L. HICKEY, J.P. HICKEY, J.P.	8403010085 8403070213 8403280074 8403060461 8403060464	FOIA 50-440 A FOIA FOIA	HOLZMER, M M. HOOD, D. HOOD, D. B. HOPKINB, G. HOPKINB, J. B.	8403220165* 8312080134* 8312070278* 8403230208 8403220101	50-275 Q 50-327 A 50-327 A MREG 50-375 P	HULMAN, L. 0 HULBEY, S. A HUMNICUTT, D. M HUMNICUTT, D. M HUMNICUTT, D. M.	8403010074# 8403160063 8403050186# 8403060184# 8403060373#	FOIA 50-206 H 50-482 G 50-445 G 50-445 G
Hietala, J. J. Higginbotham, L. Higginbotham, L. Higginbotham, L	8403120047 8403130201* 8403150283 8403150300 8403150317	50-374 8 27-48 27-48 HASTE MQT 27-48	HOPKING, R. HOPPER, A. HOPPER, A. HOPPER, A. HORIN, W. A.	8403140035 8403220316 8403260352 8403260363 8403140013	50-454 Q CONTRACT CONTRACT CONTRACT 50-445 Q	HUNNICUTT, D. M HUNNICUTT, D. M HUNNICUTT, D. N HUNNICUTT, D. M HUNNICUTT, D. M.	8403130148# 6403130219# 8403130453# 8403260107# 8403260167#	50-267 @ 50-445 @ 50-445 @ 50-267 @ 50-267 @

	ACCESSION	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJE CATEO
AUTHOR	NUMBER	CATEGORY 50-267 Q	JENKINS, O R	8403070145*	50-335 G	JOHNSON, © TE	8403270322 8403150073*	50-413 50-293
HUNNICUTT, D M HUNNICUTT, D M	8403260177* 8403260211*	50-267 0	JENKINB, C R	8403160111* 8403160141*	50-349 G 50-269 G	אספאאסטע א פּ אי אספאאמטע פּ	8403130376	50~267
HUNNIGUTT, D. M. HUNNIGUTT, D. M	8403260214# 8403260240#	50-445 G 50-298 G	JENKINS, O. R JENKINS, O. R	8403150145#	50-34B G	M P ANDENHOU DH P ANDENHOU	8403090270 8403150094	50-282 50-528
HUNTER, D. R	8403060176*	20-366 0	Jenkins, Q. R	#P493140244*	= ' '		8403140172	PR
HUNTER, D R	8403080188#	50~461 G 50~29 P	JENKINS.OR JENKINS.OR	8403150300* 8403290027*	50-261 G 50-348 G	JOHNSON, R U	84031903A2 84030A0384	PRM 50-344
HUBAIN, A. IDE, H. E.	8403200270# 8402140032#	50~528 G	Jenking, G. R Jenking, G. R	8403290244* 8403290290*	50-302 Q 50-369 G	H B'NOBNHOL	8403220247	50-344
IGNATONIS, A IGNATONIS, A J	8403070369# 8403070088#	50~247 G 50~275 G	JENNINGS, R T	8403300100	50-317 S	JOHNSON'S W	8403090180	PRM
IONATON: 8 B	8010230503#	FOIA	JENB' # H	8403020121	50-341 A	JOHNSON, T L	8493200370 8493200372	WASTE : 40-8629
ILBERG, D	8403010041# 8305230539	FOIA 50-327 B	JENB, W H	8403090188 8403090247	50-341 V 50-341 A	JOHNSON, T L	8403140180* 8403140183*	50-373 50-373
IMARO, E IMARO, E.	8403230171	50-317 S 50-318 S	JENB, W H JENB, W. H	8403150021 8403200185	50-341 V 50-341 A	JOHNBON, W A	8403140184#	50-373
IMBRO, E V.	8311020249	••	JENB. W H	8403210048	50-341 A	JOHNSDN, H D	B402210348*	50-285
IMBRD, E, V IMBRD, E, V.	8311020253* 8403230175*	50-318 B 50-317 B	JENS, W. H.	8403210074	50-341 A 50-341 A	JOHNSON, W. D	8403050186# 8403130402#	50~482 50~313
IMLER, R.	8403060220 8403140012*	50~287 H 50~458 9	JENB'M H JENB'M H	8403230018 8403270043	50-341 A	JOHNSON, W D.	8403190288# 8403260099#	50-313 50-313
irvino, 8, m. Irvin, d H	8403210107	PRM	JENSEN. D L	8403080425*	50-287 P	JOHNBON, W D	8403260172*	50~285
IRNIN, D. P	8403010221	50-463 <i>0</i> 50-463 <i>0</i>	JERRETT, LE JESBUP, B.	8403090105 8403020037	PR 50~10 P	JOHNBON, W. D.	8403260232*	50-313 50-313
irwin, d. p. Yrwin, d. p	8403010221 8403010227#	50-463 9	JESSUP, B	8403230129 8403200335*	CONTRACT 4D~1341	U W NORNHOL W D NOTBNHOL	8403300050# 8403060344#	50-344
IRWIN, D. P IRWIN, D. P.	8403010229* 8403020168	50-463 <i>Q</i> 50-322 <i>Q</i>	JIERREE.C.C JIERREE.C.C	8403260109*	40-1341	V W MOTENHOL	Ø21:300017#	50-400
	8403130022	50-322 0	JIH: R	8403230050	WASTE HOT	JOHNSTON, N. V.	9301140474* 9307220302*	50~400 50~400
IRWIN, D. P. IRWIN, D. P.	8403130022	50-322 Ø	JOHNBON, A. R.	8403070053 8403140061	50~482 Q 50~482 Q	UDHNBTON, W V.	0310170095 *	50~400 50~400
IRWIN.D.P. IRWIN.D P.	8403200069 8403200069	50-322 0	A MOBNHOL	8403190221* 8403040356	0A999 50-155 P	JOHNSTON, W. V JOHNSTON, W. V	8310190067* 8311140004*	50-400
IRHIN, D P	8403270292	50-322 0		8403080184	50-255 R	JOHNSTON, W. Y	B311290301*	50~400
irwin, D. P. Iverson, O. N	8403270292 8403200255	50-322 0 50-263 8	NOHNBON'B D NOHNBON'B D	B4030B020 <i>6</i>	50-255 R	JOHNSTON, W V	8312020049* 8312230276*	50~400 50~400
JABBOUR, K. N	8403050377	50-413 E 50-413 A	JOHNSON, B. D. JOHNSON, B. D	8403120041 8403120131	50-255 R 50-155 G	JOHNSTON, W. V. JOLLEY, J. R.	8403150071 8403300182	50~317 50~317
JABBOUR, K. N JABBOUR, K. N	8403040477 8403070422	50-413 E	JOHNSON, B, D	8403150145	50-255 P	JOLLEY, J R		በ ለዮዎዎ
JABLONSKI,F J.	8403130430#	50-461 G	. a a Mashkov D a Mosnkov	8403170101 8403220076	50-255 B 50-255 P	JONES, D. B JONES, D. B.	8403060076# 8403060101#	0A779
JACKIW, I JACKIW, I	9403130275 9403130334	50~346 B 50~346 B	JOHNBON, B D	E403230093	50-255 P WASTE HOT	JONES, D. W. JONES, D. W	8403070328* 8403160270*	70-27 70-140
JACKIW, I.	8403130377 8403130023*	50-246 B 50-246 G	NOHNBON'D NOHNBON'C V	8403020206 8403260173*	50-334 G	JONES, D. H	8403230040	50~538
JACKIN, I. N.		50-282 G	JOHNSON, E	8403260245	50-362 0	JONES, F	8403200150*	0A479 50~322
Jackin, I. N Jackin, I. N.	8403170042# 8403170384#	50-3D5 Q	JOHNSON, E K	8403050071 8403050129	50-298 G 50-459 G	JONES, F. F JONES, F. H	8403300170 8403080402	FOIA
JACKSON, H. H. JACKSON, L. H.	8012160551* 8403080384*	50-397 U 50-424 G	JOHNSON, E. H. JOHNSON, E. H.	6403050153	50-267 Q 50-445 Q	JONES, O T JONES, C T.	84030102R4 8403010371	50-259 50-259
JACKSON, P. D	6403020216	TON STRAM	JOHNSON, E H	8403060180		JONES, O T.	B403020103	50-259
JACKSON R E.	8001270311*	50-312 P 50-344 P	JOHNSON, E. H.	8403040371 8403120045	50-445 G 50-458 G	JONES, G. T.	8403020325	50-259 50-259
JACKSON, R. E. JACKSON, R. E.	8007070737 * 8007250342*	50-312 P	JOHNSON, E. H JOHNBON, E. H	8403120081 8403130122	50-267 P 50-267 G	JONES, O T. JONES, O T	8403060244 8403070085	50-257
JACKBON, R. E JACKBON, R. E	8101060767* 8103040052*	50-397 A 50-397 E	JOHNBON, E. H	8403130131	50-382 G	JONES, O T	8403070245	50-259
JACKBON, R. E	B105210109*	50-460 A	JOHNBON, E. H.	8403130183 8403130231	50~445 Q 50~267 P	JONES, G. T. JONES, G. T	8403090253 8403130181	50~259 50~260
JACKSON, R. E	8107130581* 8107140172*	50-50B 0 50-50B 0	JOHNSON, E. H.	8403130234	50-267 P	JUNES, G T	8403130205 8403170125	50~259 50~259
JACKSON, R. E. JACKSON, R. E.	B108270490*	50-528 D HASTE MOT	JOHNSON, E. H	8403130257# 8403130307	50-247 P 50-298 Q	JONES, G. T.	8403190971	50-257
JACKBON, R. S	8402290471		JOHNSON, E. H.	8403130438	50~458 G	JONES, O T.	8403200087	50~276 50~260
JACKOON, R. E. JACOBB, A.	8403260077* 8403060491	CONTRACT	JOHNSON, E. H. JOHNSON, E. H	8403130442 8403160235	50-445 G 50-458 G	JONES, O. T. JONES, O. T	8403200171 8403200213	50-237
JACOBBIA. JACOBBIA	8403140325 8403150174	CONTRACT CONTRACT	JOHNBON, E. H	8403160242 8403160255	50-382 Q 50-278 Q	JONES, Q. T JONES, Q. T.	8403220046 8403220159	50~257 50~260
JACOBS, A.	8403270360	CONTRACT	JOHNSON, E. H.	-,	50-247 P	JONES, Q T	8403300133	50~259
JACOBS, R	B403090224	50-397 6 50-397 0	JOHNSON'E H	8403190087* 8403190271	50~382 G	JONES, R. A.	6403130114 8403130313	50-445 50-445
Jacobb, R Jacobb, R	8403150060* 8403270155*	50-367 0	JOHNSON, E. H JOHNSON, E. H	9403190320 9403190404	50-247 P 50-445 G	JONES, R A JONES, V H.	8403020057#	50~280
JACOBBON: M. J. JACOBBON: N	8403120010* 8403070208	50-275 0 PR	JOHNBON, E. H.	0403200125	50-445 G	JONES, W. C	8402170166*	50-285
JAFFE, D. H.	8403050305	50-317 P	MHNBON, E H	8403200247 8403220031	50-382 Q 50-298 Q	DONES! H C.	8402210357* 8403010312	50~205 50~205
JANECEK, R. F.	8403070174* 8403160076*	50-237 P 50-412 A	TOHNBON'E H	6403260060	50-458 G 50-392 G	JONEB, W C. JONEB, W C	8403050079 8403050124	50-285 50-285
JANKOV, Z. D JANKOWSKI, S. M.	8403040495*	CONTRACT 40-2061	JOHNBON, E. H.	6403260078 6403260100	50-267 G	JONES, M. C	8403050135	50-285
JANUSKA, A. O.	8403130117*		JOHNSON, E. H.	8403240141	50-247 G	JONES, W C.	8403060396	50-285 50-285
JANUSKA, A. G. JAPE, F	8403220140* 84021401 <i>9</i> 3*	50-261 0	JOHNBON, E. H	8403260174 8403260205	50-267 G 50-267 G	JONES, W.C.	8403070234 8403120172*	50-285
JAPE: F. JAPE: F.	8403070017* 8403070338*	50-413 G 50-413 G	JOHNSON, E. H	8403260206 8403260217	50-445 G 50-458 G	JONES' M' C' JONES' M' C	8403130200 8403130458	50~265 50~265
JAPE, F.	8403140108*	50-416 G	JOHNSON, E. H		50-278 Q	JONES, W. C.	B403170061*	50-285
JAPE: F.	8403160210*	50-335 G 50-413 G	Odhabon' e' h Odhabon' e' h	8403260235 8403270070	50-458 G	JONES, W C.	8403190154	50-285 50-285
JAPE: F. JAPE: F.	8403160224* 8403160238*	50-259 G	JOHNSON, O. E JOHNSON, O. E	8403010209 8403140043	50-413 0 50-413 0	nones M. C Nones M. C	8403170281* 8403200176	50-285
JAPE, F. JAPE, F.	8403160314# 8403160339#	50-250 G 50-259 G	JOHNSON, G. E.	8403140046	50-413 0	Jones, H. C.	8403270249	50-285
JAPE, F	8403150370*	50-413 G	JOHNSON, O. E.	8403140123 8403140124	50-413 0 50-413 0	JONES, W. C.	8403280165 8403280173	50-265 50-265
JAPE, F.	8403270207# 8403260177#	50-370 G 50-267 G	JOHNSON, Q. E.	8403140150	50-413 0 50-413 0	JONES, W. F JORDAN, D.	8403120043 8403010149	0A999 71-511
JAUDON, J. P. JEFFERB, Q. J.	8403220272*	50-322 T	JOHNBON, G. E. JOHNBON, G. E.	8403140169 8403190174	50-413 0	JORDAN, E. L.	6011070522*	50-317
Jenkins, O. R.	8403070013*	90-a70 d	*					

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY
RDAN, E L	8103250630*	F01A	KARMAN M	8403270326	50-482 0	KELLY, M J	8403150237	40-1341
RDAN, E L	8401190072	50-3 G	KARR, J E	8403060411	50-329 8	KELLY, R B	8403010115	TOPREP
RDAN, E. L	8402020073*	50-293 F	KARR, J E	8403060442*	50-329 6	KELLY, T.	8403200173	50-304 8
RDAN, E L	8402090008	50-3 G	KARR, J E	8403060444*	50-329 0	KELLY, W. J	8403020004	50-275 R
RDAN, E L	8402090009	50-3 G	KARR, J E	8403060445*	50-329 0	KELLY, W J	8403300141	50-275 R
RDAN, E L	00702070	50-3 G	KARR, J E	8403080172	50-327 8	KEMPER, J 8	8401240207	50-352 A
RDAN, E L	0070204	50-3 G	Karr, J E	8403080221	50-327 9	KEMPER, J 8	8403020104	50-352 A
RDAN, E L	00070208	50-3 G	Karr, J E	8403080250	50-327 8	KEMPER, J 8	8403020266#	50-352 A
RDAN, E L	000702048	50-3 G	Karr, J E	8403130074	50-327 8	KEMPER, J 8	8403050161	50-352 E
RDAN, E L	000702048	50-3 G	Karr, J E	8403130173	50-327 8	KEMPER, J 8	8403070281#	50-352 Q
RDAN,E L RDAN,E L RDAN,E L RDAN,E L RDAN,E L	8403010157* 8403010181* 8403010185* 8403010193* 8403010196*	FOIA FOIA FOIA FOIA	E KARRA J E KARRA J E KARRA J E KARRA E KARRA E	8403130194 8403130195 8403130238 8403130271 8403130297	50-329 8 50-329 8 50-329 8 50-329 8 50-329 0	KEMPER, J S KEMPER, J S KEMPER, J S KEMPER, J S KEMPER, J. S.	8403130084 8403160192 8403190197 8403200144 8403260249	50~352 B 50~352 A 50~352 A 50~352 Q 50~352 E
RDAN, E L	8403010206*	FOIA	e L.RRAK	8403130321	50-329 8	KEMPER, J S	8403270071	50-352 0
RDAN, E L	8403010214*	FOIA	E L.RRAM	8403130388	50-329 A	KEMPER, J S,	8403270172	50-352 A
RDAN, E L.	8403080124*	FOIA	E L.RRAM	8403130470	50-329 A	KEMPER, J, B	8403280353	50-352 0
RDAN, M	8403130377	50-266 S	E L.RRAM	8403130479	50-329 B	KENDALL, J M	8403080009*	50-27 P
RDAN, M J	8403050176*	50-266 Q	E L.RRAM	8403270042	50-329 R	KENNEDY, D	8403060083	50-320 H
RDAN.W H RDAN.W S RDAN.W S YNER, J YNER, J	8403190002 8403020173 8403020173 8408210133 8403020311	50-445 G 50-443 G 50-443 G I&E I&E	Marr, J E Marr, J E Marr, J E Marr, J E Marr, J E	8403270093 8403270094 8403270227 8403300004 8403300035	50-329 8 50-329 8 50-329 6 50-329 6 50-329 8	KENYON, B. D. KENYON, B. D. KENYON, B. D.	8403130474 8403150166* 8403020036 8403120026 8403130059	50~456 D 50~286 G 50~387 R 50~388 A 50~387 R
INER. J INER. J INER. J II INER. J H INER, J H	8403190135 8403300074 8403070259* 8403080165* 8403220010*	50-220 8 50-219 B 70-1100 FOIA 50-272 Q	Kass, D e Kassakatig, L d Kassakatig, L d Kassakatig, L d Kassakatig, L d	8403080023 8403070187 8403130337 8403200105 8403200237	FOIA 50-397 8 50-397 8 50-397 8 50-397 8	KENYON, B D KENYON, B D KENYON, B, D KENYON, B, D	8403170366* 8403170405 8403200250 8403200272 8403210112	50-387 g PR 50-387 F 50-387 F 50-387 R
(NER, J H	64032900&6*	70-378	Kassakatig, L. D	8403260025	50-397 8	KENYON, B, D	8403220041*	50-387 Q
(NER, J. H	6403290205*	50-320 G	Kassakatig, L. D	8403280003	50-397 8	KENYON, B, D	8403220135*	50-387 Q
-IAN, C A	8403070163*	50-327 G	Kassakatig, L. D	8403280007	50-397 8	KENYON, B, D	8403300067*	50-387 G
-IAN, C A	8403070216*	50-416 G	Kassaer, O	6403070164	50-295 8	KENYON, B D,	8403300147	50-387 R
IAN, C A	8403160222*	50-370 G	Kasturi, B	8403150014*	50-440 9	KENYON, T J	8403060534	50-390 A
IAN.C A	8403160225*	50-327 G	KAUFMAN.P D	8403170354*	50-440 G	KEPPLER, J G	B10129070B*	FOIA
IGE, M	8403060107	50-318 S	Kay.J a	8403080007	50-27 P	KEPPLER, J G	B403070345*	50-329 B
OLING.T.L	8403220122	WASTE MOT	Kay.J a	8403120123	50-27 P	KEPPLER, J. G	B4030B0044*	FOIA
TUS, P S	8403200312	WASTE MOT	Kay.J a	8403120181	50-29 R	KEPPLER, J G.	B4030B0057*	FOIA
ILE, J B	8403020176	70-143	Kay.J a	8403130287	50-27 P	KEPPLER, J G	B4030B0101*	FOIA
LE.J B LE.J B, U.H E.D L	8403070248* 8403140386* 8403140387* 8403240347* 8403270178	50-416 @ 70-143 70-143 50-275 @ PT21	KAY, JA KAY, JA KAY, JA KAY, JA KAY, JA,	8403200284 8403200288* 8403270003 8403270007 8403270214	50-29 P 50-29 P 50-29 P 50-29 P 50-29 J	KEPPLER, J G KEPPLER, J G KEPPLER, J. G KEPPLER, J G KEPPLER, J. G.	8403080127* 8403080175* 8403080208 8403080247 8403120116	FOIA FOIA 50-315 G 50-155 B 50-315 G
E.D.L	8403070200*	PT21	Kayija	8403300192	50-27 P	KEPPLER, J O	8403130380	50-346 S
E.D.L	8403070202*	PT21	Kayberih V	8403080223*	50-314 P	KEPPLER, J O	8403170180	50-327 A
E.D.L	8403070203*	PT21	Kayberih V.	8403180104*	50-316 P	KEPPLER, J O	8403170236	50-331 G
E.D.L	8403140138	PT21	Xearneyij.	8403010239*	FOIA	KEPPLER, J O	8403170286	50-546 Q
ITOWSKI,T	8403270316	WASTE MGT	Kearneyij.	6403130348	PR	KEPPLER, J O	8403170274*	50-546 G
Ivianakis, n Ivianakis, n Ivianakis, n Ivianakis, n	8403040113 8403120107 8403130382 8403150019 8403140027	50-254 R 50-265 S 50-254 R 50-254 R 50-255 S	MEARNEY, J P MEATING, D E KEATING, D E. MEELEY, O S MEIMIG, R.	8403130497* 8403080302* 8403190305* 8403290055* 8403290008	50-312 Q 50-315 Q 50-494 Q FOIA 50-217 B	KEPPLER, J. G. Keppler, J. G. Keppler, J. G. Keppler, J. G Keppler, J. G	8403170341 8403200170 8403230088 8403260065 8403270246	50-344 8 50-441 A 50-10 9 50-358 A 50-454 9
IVIANAKIE, N	840320010 <i>6</i>	50-265 8	Keiber, H W.	8403020253	50-387 8	Kerch, H W	8403020309#	50-277 G
IVIANAKIE, N	8403200188	50-265 8	Keiber, H W.	8403020317	50-387 8	Kerch, H W.	8403150034#	50-388 G
/ERBDER, C	8403080366*	F01A	Keiber, H W	8403040108	50-387 8	Kerekeb, W A	8403010303#	50-388 E
YER, D. S	8403070092	50-370 9	Keiber, H W	8403040253	50-387 8	Kerwin, C. M	8403070109	NUREG
YER, D. S	8403070271	50-257 9	Keiber, H W	8403140011	50-387 8	Kebbinger, W W	8403220044	50-275 S
1ERER, C	8101130353*	50-508 U	Keiber, H. W	8403140018	50-387 8	KETZLACH, N.	8403070019#	70-1201
1ERER, C	8403010046*	FDIA	Keiber, H. W	8403140177	50-387 8	KETZLACH, N.	8403070112#	70-824
1ERER, C	8403010049*	FDIA	Keith. H. N	8403240224	50-387 8	KETZLACH, N	8403190160	50-952 0
1ERER, C	8403010054*	FDIA	Keith. H. N	8403070025	50-333 8	KEYSERLING, H M	8403220118	ACRS
1ERER, C.	8403010058*	FDIA	Keith. H. N	8403200231	50-333 8	KIEL, G. R	8403260037	XPDRTLIC
1ERER, C	8403010063*	F01A	KEITH, H N	8403290246	50-333 8	Kiel, O R	8403260042*	XPORTLIC
1ÉRER, C	8403010067*	F01A	KEITH, H. R	8403060145	50-331 8	Kinneman, J.	8403080162*	FOIA
1ERER, C	8403020051*	30-537 A	KELLER, M.	8403120033	50-263 8	Kinneman, J.	8403080166*	FOIA
, M S	8403270301	PRM	KELLER, M.	8403220003	50-263 8	Kinneman, J.	8403210040	I&E
JA, B. K	8403020318	50-320 P	KELLER, R F	8403280081#	FOIA	Kinneman, J D	8403080102*	FOIA
A, B K. A, B K. IA, B K IA, B K A, B K	8403080257 8403090035 8403120102* 8403130428 8403130475	50~320 P 50~320 G 50~320 G 50~320 P 50~320 R	MELLEY, D L MELLEY, J. L. MELLEY, J L. MELLEY, H. J	8403130453* 8403190025 8403200042 8403210051 8403290098*	50-445 G 50-400 C 50-413 C 50-400 C 50-441 I	Kinneman, J. D Kinneman, J. D Kinney, H. H Kinter, E. E. Kintner, L. L.	8403080173* 8403080189* 8403020305* 8403270123 8403160189	FOIA FOIA 50~54 G 50~320 P 50~352 A
A.B. K A.B. K A.B. K. A.B. K. A.B. K	8403170217* 8403200201 8403210057 8403270210 8403280006	50-320 Q 50-320 P 50-320 R 50-320 P 50-320 S	KELLY, J. A KELLY, J. A. KELLY, J. A.	8403240214* 8403240214* 8403240048* 8403240097* 8403240220*	50-387 8 50-445 Q 50-458 Q 50-313 Q 50-458 Q	KINTNER, L. L. KIRBY, L. J. KIRK, Q. B. KIRK, Q. B. E KIRK, W. F.	8403300305 8403070073 8403260164 8403020244 8403010289	50-416 P NUREO 50-327 9 50-327 8 70-371
A, B, K	8403300031	50-320 P	KELLY, J. A. F.	8403260167#	50-247 Q	KIRKMAN, R. W	8403080004*	FOIA
LEY, J P	8403260284	50-245 S	KELLY, J. A. F.	8403260240*	50-298 Q	KIRKMAN, R. W.	8403080067*	FOIA
O, J, P,	8403200237	50-483 F	KELLY, J. E.	8403030035#	50-286 P	KIRKPATRICK, D.	8107160215*	FOIA
AN, H	8403190123	50-482 0	KELLY, L.	8403300159	50-286 R	KIRKPATRICK, D.	8202120275*	FOIA
AN, M,	8403190158	50-482 0	KELLY, M. J.	8403150230	40-1341	KIRKPATRICK, D	8403010127*	FOIA

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEODR
KIRKPATRICK, D KIRKPATRICK, D KIRKPATRICK, D KIRKPATRICK, D KIRKPATRICK, D	8403010131*	FOIA	KDESTER, O L	8403070225	50-482 V	Lainas, o c	8403200324	50-324
	8403010138*	FOIA	KDESTER, O L	8403130197	50-482 A	Lakner, a a	8403050335*	M18C
	8403010141*	FOIA	KDESTER, O L	8403130215	50-482 B	Lalikos, j m	8403210095	50-346
	8403010178*	FOIA	KDESTER, O L	8403130345*	50-482 G	Lalikos, j. m	8403270108	GA777
	8403010184*	FOIA	KDESTER, O L	8403130399*	50-482 G	Lamb, j c	8403150016	50-478
KIRKPATRICK, D	8403010171*	FOIA	KGESTER, O L	8403150064	50-482 A	LAMBERTUB, H	8403260158*	40-1478
KIRKPATRICK, D	8403010252*	FOIA	KGESTER, O L	8403170036	50-482 8	LAMOUREAUX, T H	8403010175*	50-344
KIRKPATRICK, D	8403010287*	FOIA	KGESTER, O L	8403170227*	50-482 A	LANCIONE, G	8403210107	PRM
KIRKPATRICK, D	8403050264*	FOIA	KGESTER, O L	8403170316	50-482 S	LANDAGORA, M	8403280079	40-8584
KIRKPATRICK, D	8403050270*	FOIA	KGESTER, O L	8403200252	50-482 A	LANDAU, M	8403260280	NURES
KIRBCH, D. F.	8403060149*	50-275 0	KOESTER, O L	8403200257	50-482 E	LANDGRAF,L C	8403130044	50-341
KIRBCH, D F	8403060214*	50-275 d	KOESTER, O L	8403210073	50-482 A	LANDORAF,L C	8403130044	50-341
KIRBCH, D F.	8403060223*	50-223 0	KOESTER, O L	8403270105	50-482 S	LANE,V M	8403200110	50-352
KIRBCH, D F.	8403060406*	50-312 0	KOESTER, O L	8403270151	50-482 S	LANE,V M	8403300287	50-352
KITTAN, J J	8403150078*	50-272 0	KOESTER, O, L	8403270163	50-482 S	LANKEBURY,R D	8403190299*	50-373
KLEIMOLA, F. W. KLEIMOLA, F. W KLEIMOLA, F. W KLEIMOLA, F. W KLEIMOLA, F. W	8403070316* 8403070321* 8403070325* 8403070327* 8403070328*	TOPREP TOPREP TOPREP TOPREP TOPREP	KOESTER, & L KOESTER, & L KOLTER, J. P KONKLIN, J E	8403270179 8403270268 8403070013* 8403060228* 8403220114*	50-482 8 50-482 8 50-289 U GA979 50-341 G	LANKSBURY,R D LANNING,H D LANPHER,L C LANPHER,L C LANPHER,L,C	8403300057* 8403240013 8403040208 8403040208 8403040268	50-341 50-334 50-322 50-322 50-322
KLEIMOLA, F W	8403070330*	TOPREP	KONWINSKI, O. R	8403200343	40-1162	LANPHER, L C	8403060268	20-355
KLEIN, T. J.	9403150228	40-8584	KONWINSKI, O. R	8403200377	40-6659	LANPHER, L C	8403130146	20-355
KLEIN, T J	8403220048	40-8584	KOON, A. R.	8403060242	50-395 8	LANPHER, L C	8403130146	20-355
KLEIN, T J	8403220117	40-8584	KOON, A. R.	8403060351	50-395 8	LANPHER, L C	8403200004	20-355
KLEINBORGE, W P	8403070105*	50-400 Q	KOON, A. R.	8403080153	50-395 8	LANPHER, L C	8403200004	20-355
KLEINSORGE, W P	8403170247*	50-266 Q	KOON, A.R.	8403070052	50-375 8	LANPHER, L C	8403200128	50-322
KLEINSORGE, W F	8403270173*	50-400 Q	KOON, A.R.	8403070247	50-375 8	LANPHER, L C	8403200128	50-322
KLINE, D A.	8403270048*	50-352 T	KOON, A.R.	8403130371	50-375 8	LANPHER, L C	8403210184	50-322
KLINE, J R.	8403300262	50-440 Q	KOON, A.R.	8403130042	50-375 8	LANPHER, L. C	8403210184	50-322
KLINGER, J Q	8403020016*	FOIA	KOOPE, R.H	8403070057#	50-400 9	LANPHER, L C	8403270248	50-322
KLINOLER, O	8403270114	50-237 G	KORTE, N	8403020374	WASTE MOT	LANPHER, L C	8403270248	50-322
KNAPP, M R	8403200384	Waste Mot	KORTE, N	8403020374	WASTE MOT	LARSEN, G J	8403080281*	50-275
KNIEL, K.	8310130378*	50-400 E	KOSIBA, R. E	8403130076*	QA999	LARSON, C E	8403170064	50-263
KNIEBER, O W	8403120114*	Ga977	KOSLA, B M.	8403140217*	40-8027	LARSON, C E	8403170200	50-282
KNIEBER, O W	8403270097*	Ga999	KOSLA, B, M	8403230246*	70-1359	LASH, T R	8403200317	27-39
KNIGHT, J P	8105010554*	50-460 A	KOT, C.A.	8403070114	NUREQ	Lasukis, r	8403080257	16E
KNIGHT, J P	8107270274*	50-508 A	KOTTAN, J. J	8403010314*	50-352 G	Latham d W	8403220080	50-317
KNIGHT, J P	8211970008*	50-400 E	KOTTAN, J. J	8403270120*	50-387 G	Latham W	8403080007	50-312
KNIGHT, J P	8212160163*	50-400 E	KOVACH, D.	8403270073	50-320 F	Latham W X	8403060141	50-312
KNIGHT, J P	6212300403*	50-400 E	KOVAK, T. J	8403070274	50-254 F	Laurenson J A	8403010174	50-322
KNIGHT,JP. 9 C.THGINN 9 C.THGINN 14 C.THGINN 15 C.THGINN 16 C.THGINN	8309040390* 8309240018* 8309240421* 8310200094* 8403190102*	50-400 E 50-400 E 50-400 E 50-400 E 50-275 G	KOZINBKY,E J KRANZDORF,R. KRAUSE,D. KREGER,W.E KREIDER,H.O.	8403300342 8401040010* 8403130121 8005150477* 8403040311	NUREO 50-275 E 50-315 F FOIA 50-443 S	LAURENSON, J A LAURENSON, J A LAURENSON, J A LAURENSON, J A	8403010215 8403010225 8403010232 8403010267 8403060114	50-322 50-322 50-322 50-322 50-322
KNIGHT,J P KNIGHTON,G W KNIGHTON,G W, KNIGHTON,G W KNIGHTON,G W	8403240083* 8402270440* 8403010508 8403010544 8403040427	50-344 P 50-508 D 50-508 F 50-498 F 50-528 8	KREIL ING, R. T KREN, J L. KRICH, R M KRICH, R M KRICH, R M	8403060318* 8403070013* 8403080131 8403080141 8403270066	50-322 T 50-395 Q 50-155 R 50-155 R 50-155 S	LAURENSON, J A LAURENSON, J A LAURENSON, J A LAURENSON, J A	8403070083 8403130097 8403130107 8403140005 8403200095	20-355 20-355 20-355 20-355 30-355
KNIGHTON: G W	8403060451	50-528 A	KRICH,R M	8403270187	50-155 P	LAURENSON, JA	8403210083	50-322
KNIGHTON: G: W	8403060559	50-443 F	KRIGH,R.M.	8403270249	50-155 P	LAURENSON, JA	8403210150	50-322
KNIGHTON: G: W	8403060561	50-382 F	KRIEGER,R W	8403070254	50-206 P	LAHTON, MB	8403150808	40-8084
KNIGHTON: G: W.	8403060564	50-275 E	KRIEGER,R W.	8403140251	50-206 P	LAYARUS, H, J	8403150101*	50-410
KNIGHTON: G: W	8403090130	50-528 A	KRIEGER,R.W.	8403230118	50-361 Q	LAZO, L	8403270369	50-412
Knightan, g. W	8403070147	50-52B 8	KRIMH, R. W.	8403050128	50-440 F	LAZO, L	8403280054	50-412
Knightan, g. W	8403140177	50-412 E	KRIMH, R. W.	8403080238	50-263 F	LAZO, L	8403280060	50-412
Knightan, g. W,	8403150165	50-275 P	KRIMH, R. W.	8403070218	50-155 F	LAZO, L	8403280067	50-412
Knightan, g. W	8403150198	50-50B D	KRIMH, R. W.	8403130143	50-282 F	LAZO, R M	8003240222*	50-508
Knightan, g. W,	8403270357	50-412 F	KRIMH, R. W.	8403130178	50-263 F	LAZO, R. M	8403130034	50-250
KNIGHTON, O. W.	9403270372	30-412 C	KRIMI, R. W.	8403130419	ORG	LAZD, R. M	8403130262	50209
KNIGHTON, O. W.	8403280233	30-366 F	KRIMI, R. W.	8403150018	50-293 F	LAZD, R. M	8403270277	50250
KNIGHTON, O. W.	8403290331	50-361 P	KRIMI, R. W.	8403150052	50-416 F	LEACH, E W	8403130371*	50220
KNIGHTON, R. O.	8403300125	50-498 A	KRIMI, R. W.	8403150113	50-313 F	LEAR, G	8111130007*	50460
KNIGHTON, R. O	8403060226*	50-322 T	KRIMI, R. W.	8403150119#	50-313 F	LEAR, G.	8307200478*	50400
Knighton, R. G	8403050246*	50-322 T	KRIMM, R. W	8403150200	50-315 F	LEAR: Q	9311100047*	50-400
Knop, R. C.	8403060170	50-341 Q	KRIMM, R. W	8403230120	50-387 F	LEAR: Q.	8311140283*	50-400
Knop, R. C	8403070234*	FOIA	KRISHNAMURTHY	8403270253	FRM	LEAR: Q	8312070022*	50-329
Knop, R. C.	8403130416	50-461 Q	KRUG, H. E.	8403160210*	50-335 G	LEAR: Q E.	8104220327*	50-460
Knop, R. C	8403220107	50-341 Q	KRUG, H. E	8403160316*	50-250 G	LEAR: Q E	8211140112*	50-400
KNOF, R. C.	8403220111*	50-341 9	KRUMPOS, P. J.	8403270181*	50-282 Q	LEAR, Q.E.	8212140220*	50-400
KNUTSON, J. A.	8403010532*	50-275 H	KUCZYNSKI, L. A	8403020036	50-387 R	LEAR, Q.E	8311270352*	50-400
KOBER, R.	8403280069	50-244 P	KUCZYNSKI, L. A	8403020253	50-387 S	LEDDICK, R. 8	8403050248	50-382
KOBER, R. W	8403060115	50-244 P	KUCZYNSKI, L. A,	8403300147	50-387 R	LEDDICK, R. 8	8403120164	50-382
KOBER, R. W.	8403130132	50-244 R	KUEGHLE, C. W.	8403070174	50-304 S	LEE, A.	8403260018	50-454
Kober, R. W. Kober, R. W Kober, R. W Kober, R. W Kocher, C. W.	8403240198 8403270150 8403270152 8403290185 8401260167*	50-244 P 50-244 Q 50-244 Q 50-244 P 50-264 F	KUNCL, L, Q, KUNITA, R, K KUO, P KUO, P KUZO, Q, B,	8403070100 8403210080* 8310310471* 8312010004* 8403160307*	50-298 P 50-324 P 50-329 A 50-329 A 50-395 Q	FEE' Y Y' FEE' Y FEE' Y FEE' Y	8403260057 8206300082* 8403160015 8403220242 8403020122	50 - 454 50 - 508 50 - 287 50 - 287 50 - 338
KOCHER, C. W.	8403050012	50-264 F	KUZO, Q B	8403140327#	50-369 0	LEE, J. N	8403300055	50-338
KOENIO, R.	8403160264	50-374 B	KUZO, Q, B,	8403270147#	50-413 0	LEE, O. R.	8403130435	50-267
KOENIO, R	8403200212	50-374 B	Laats, E T,	8403270329	RES	LEE, O. R	8403170350	50-267
KOESTER, O. L.	8403010145	50-482 B	Lagey, W S,	8403060134	50-334 B	LEE, O. R	8403170357*	50-267
KOESTER, O. L.	8403020274	50-482 A	Laggart, M W.	8403160203	50-219 P	LEE, O. R	8403270187	50-267

AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEOORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY
LEE,T D	8403210156*	70-143	LEWIS, R C	8403160162	50-259 Q	LINDER	8403300131	50-409 R
LEECH.P H	8403140272	50-293 P	LEWIS, R C	8403160178*	50-259 Q	LINDER, F	8403020161	50-409 R
LEGGETT,L H	8403010469	FOIA	LEWIS, R C	8403160194	50-400 Q	LINDER, F,	8403080031	50-409 R
LEHBERGER.N	8403130100*	50-327 G	LEWIS, R C	8403160211	50-413 Q	LINDER, F	8403080236	50-409 R
LEHR.J.C	8403140168*	50-400 G	LEWIS, R C	8403160218	50-259 Q	LINDER, F	8403120083	50-409 G
LEININGER.W J	8403090332*	TOPREP	LEHIB.R.C	8403160220*	50-413 Q	LINDER, F	8403130270	50-409 P
LEHPOES, T E	8403060437	50-220 F	LEHIB.R.C	8403160226	50-321 P	LINDER, F	8403130335*	50-409 Q
LEHPOES, T E	8403070174	50-220 R	LEHIB.R.C	8403160227	50-259 V	LINDER, F	8403160047	50-409 F
LEHPOES, T E	8403120044	50-220 G	LEHIS.R.C	8403160230*	50-259 Q	LINDER, F	8403200163	50-409 B
LEHPOES, T E.	8403130124	50-410 V	LEHIS.R.C	8403160231	50-302 P	LINDER, F.	8403230002	50-409 R
Lempoes, T e. Lempoes, T e. Lempoes, T e Lempoes, T e Lempoes, T e	8403130340 8403150051 8403210043 8403220129 84032260270	50-220 P 50-220 R 50-220 S 50-220 P 50-220 G	LEWIS,R C LEWIS,R C LEWIS,R C LEWIS,R C	8403160245 8403160247 8403160249 8403160252 8403160254	50-249 F 50-259 P 50-261 G 50-417 A 50-250 F	LINDER, F. LINDER, F LINDGUIST, T R LINDGUIST, T R LINDSEY, D J.	8403270283 8403300087 8403230102* 8403230106* 8403060173	50-409 P 50-409 P 50-255 P 50-255 P 50-333 B
LEMPOES, TE	8403270177	50-220 1	LEHIB, R C	8403160257	50-348	LINEHAN, J.	8403220237	WASTE MOT
LEMPOES, T. E	8403300151	50-220 0	LEHIB, R C	8403160269		LINEHAN, J J	8403220274	WASTE MOT
LENAHAN, J. J	8403070017*	50-413 0	LEHIB, R C	8403160272*		LINENBERGER, G	8403130394	50-424 O
LEMPHAN, J. J	8403080384*	FOIA	LEHIB, R, C	8403160275*		LINTON, D. W.	8403210012	PR
LEMPKE, H	8403120012*	50-275 0	LEHIB, R C	8403160276		LINVILLE, J C	8403220115*	50-272 G
LEPPKE, M E.	8403120010*	50-275	LEHIS,R C	8403160278	50-269 F	LINVILLE, J. C.	B403270139*	50-272 Q
LETSCHE, K	8403200157*		LEHIS,R C	8403160281	50-416 F	LIPINSKI, D.	B40302023B	50-213 B
LETSCHE, K	8403200157*		LEHIS,R C	8403160283	50-261 F	LISENG, R	B403010365	50-333 B
LETSCHE, K	8403270370		LEHIS,R C	8403160285	50-302 F	LISTER, W E	B010230503*	FDIA
LETSCHE, K	8403270370		LEHIS,R C	8403160293	50-413 Q	LITTLE, W. 8	B4030B0114	50-373 Q
LETSCHE, KJ LETSCHE, KJ LETSCHE, KJ LETSCHE, KJ LETSCHE, KJ	8403010234 8403010234 8403010237 8403010237 8403060254	50-322 0 50-322 0 50-322 0 50-322 T	LEHIS,R C LEHIS,R C. LEHIS,R C LEHIS,R C LEHIS,R C.	8403160296 8403160297 8403160304* 8403160307* 8403160308	50-395 F 50-369 G 50-369 G 50-413 G 50-259 G	LITTLE, W S LITTLE, W S. LITTLE, W S LITTLE, W, S LITTLE, W S	8403080277 8403120122 8403170207 8403170240 8403170244*	50-315 Q 50-440 Q 50-254 Q 50-266 Q 50-266 Q
LETSCHE, K J LETSCHE, K J LETSCHE, K J LETSCHE, K J. LETSCHE, K J.	8403040254 8403130003 8403130003 8403130029 8403130029	50-322	LEWIB, R C. LEWIB, R C LEWIB, R C. LEWIB, R, C. LEWIB, R C.	8403160317* 8403160328* 8403160330 8403160335 8403160345	50-349	LITTLE, W.S. LITTLE, W.S. LITTLE, W.S LITTLE, W.S LITTLEHALES, Q	8403190248 8403190297 8403190348 8403260228 8403010122	50-454 G 50-454 G 50-440 G 50-454 G GA997
LETECHE, K J LETECHE, K J LETECHE, K J LETECHE, K J LETECHE, K J	8403200136* 8403200136* 8403220288 8403220288 8403280346	50-322 0 50-322 T 50-322 T 50-322 O	LEWIS,R C. LEWIS,R C. LEWIS,R C. LEWIS,R C. LEWIS,R C	8403160354 8403190136 8403190172* 8403210115 8403290013	50-348 F 50-259 G 50-259 G 50-416 G 50-366 B	LITTLEHALES, Q LIU, W. LIU, W. C LLAURADD, J. Q. LOBNER, P	8403060262 8403080384* 8403160383* 8403270257 8403080268*	GA999 50-424 G 50-390 G PRM 50-298 F
LETSCHE, K J. LETSCHE, K J LETSCHE, K J LETSCHE, K J LETSCHE, K J	9403280346 8403280357 8403280357 8403290377 8403290377	20-322 G 20-325 G 20-325 G 20-325 G	LEWIS, R C LEWIS, R C. LEWIS, R, C. LEWIS, R, C. LEWIS, R C.	8403270178 8403270172 8403270173 8403270175* 8403270203*	50-259	LOBNER, P. LODGE, B LODGE, T. J LOFGREN, E. LOFY, R. A.	8403080304* 8403060164 8403270075 8403010041* 8403080193*	50-278 F FDIA 50-440 Q FDIA 50-275 G
LETSCHE,K J	8403270383	50-322 0	LEWIS.R C.	8403270211*	50-259 Q	LOFY, R A	8403080179*	50-275 G
LETSCHE,K J	8403270383	50-322 0	Lewis.R.C.	8403270213	50-259 V	LOGSDON, M J	8403280253	WARTE MOT
LEVIN,H A	8403060370	50-329 A	Lewis.R C	8403270250	50-338 Q	LOGUE, R H	8403010358	50-277 S
LEVIN,H A	8403080260	50-329 A	Lewis.R C.	8403270267*	50-338 Q	LOIGNON, G A	8403020039	50-395 R
LEVIN,H A	8403220013	50-329 R	Lewis.R C.	8403270270	50-413 Q	LOIGNON, G, A	8403300145	50-395 R
LEVIN, H. A LEVIN, H. A. LEVIN, L. A. LEVINE, J. M	9403220100 8403220113 8403270159 8403040120 840307035B	50-329 A 50-329 A 50-329 A FOIA 50-313 F	Lewis, R.C. Lewis, R.C. Lewis, B.H. Lewis, S.H. Liang, C.Y	8403270322 8403300022 8403070349* 8403070351* 8403170119*	50-259 V 50-369 F 50-329 8 50-329 0 50-275 Q	LOMBARDO, J J LOVENDALE, P C LOVETT, B LOWE, A L LUCENA, B.	8403010290 8403190334# 8403130457 8403190246# 8403020157	50-217 P 50-295 G 50-424 O TUPREP XPORTLIC
LEVINE, J. M LEVY, B LEVY, B LEWIS, J. R	8403090301 8403260005 8403260375 8403260378 8403230200	50-313 F 50-275 Q 50-275 Q 50-275 Q NUREQ	LIAW, B, D LIBARKIN, M W LICHTENBERGER LICHTENBERGER LICHTENBERGER	8403160055 8307260036 8401240340# 8403060161# 8403130476#	TOPREP ACRB 70-1100 0A999 70-1100	LUCKS: A. S. LUCKS: A. S. LUCKS: A. S. LUCKS: A. S.	8403060407# 8403060407# 8403060413# 8403060420# 8403060423#	50-537 Q 50-329 Q 50-329 Q 50-329 Q 50-329 Q
LEWIS, M I	8403160049*	50-320 P	LICITRA,E A	8403280043	50-328 A	LUCKS, A B,	8403060428*	50-329 Q
LEWIS, M I	8403160291	50-289 H	Liden, E. A	8403060312	50-272 V	LUEBKE, E, A,	8403260003	50-142 Q
LEWIS, M I	8403190038	50-352 G	Liden, E. A	8403070260	50-272 R	LUEHMAN, J Q	8403270271*	50-338 Q
LEWIS, R C	8403010154	50-327 F	Liden, E. A	8403090049	50-272 P	LUEHMAN, J, G,	8403270274*	50-338 Q
LEWIS, R C	8403010247	50-83 F	Liden, E. A	8403130017	50-272 P	LUMB, R F.	8403270362*	CONTRACT
LEWIS, R C.	8403020204	50-250 @	Liden, E. A.	8403130108	50~311 P	LUNDBLAD, D	8403150151	50-508 D
LEWIS, R C.	8403020248	50-250 B	Liden, E. A	8403220036	50-272 Q	LUNDVALL, A. E.	8403020346*	50-317 Q
LEWIS, R. C.	8403020254	50-259 F	Liden, E. A	8403270281	50-272 P	LUNDVALL, A. E.	8403050078	50-318 P
LEWIS, R. C.	8403020285	50-250 @	Liden, E. A	8403300085	50-272 P	LUNDVALL, A. E.	8403060263	50-317 P
LEWIS, R C.	8403070125	50-375 @	Liden, E. A	8403300177*	50-272 Q	LUNDVALL, A. E.	8403060400	50-317 P
LEWIS, R C. LEWIS, R C. LEWIS, R C. LEWIS, R C.	8403070131* 8403070239 8403070344 8403080377* 8403120110	50-395 @ 50-260 @ 50-247 @ 50-424 @ 50-369 F	LIDEN, E.A. LIDEN, E.A. LIEBERMAN, E.B. LIEBERMAN, E.B. LIEBERMAN, E.B.	8403300183# 8403300186# 8403070158# 8403070171# 8403070178#	50-272 9 50-311 0 50-322 T 50-322 T 50-322 T	LUNDVALL, A. E.	8403130305 8403150049 8403160040 8403190018 8403190408	50-317 R 50-317 Q 50-317 P 50-317 F 50-317 Q
LEWIS, R. C.	8403120119	50-269 F	Lieberman, e B	8403070201*	50-322 T	LUNDVALLIA E.	8403220052	50-317 F
LEWIS, R. C.	8403130033	50-302 F	Lieberman, e, B,	8403070207*	50-322 T	LUNDVALLIA E.	8403240112#	50-317 Q
LEWIS, R. C.	8403130377	50-327 F	Lieberman, e B	8403230020	50-322 T	LUNDVALLIA.E	8403240234	50-317 P
LEWIS, R. C.	8403130484	50-259 F	Lieberman, e, B	8403230066	50-322 T	LUNDVALLIA.E.	8403300070	50-317 P
LEWIS, R. C	8403130485	50-259 F	Lieberman, J	8403080431*	50-275 E	LUPTAKIA.	8403220103#	50-309 Q
LEWIS, R. C.	8403160025	50-259 F	LIETO,R P.	8403210107	PRM	LYDNS; J, L.	8403010012	40-299
LEWIS, R. C.	8403160035	50-327 F	LIM,J J.	8403050029*	50-286 P	LYDNS; J, L.	8403150284	40-299
LEWIS, R. C.	8403160137	50-327 F	LIM,T H.	8403150115	50-224 R	MACDONALD; C E.	8403020229	71-9071
LEWIS, R. C.	8403160140	50-438 Q	LIM,D	8403160261	50-373 R	MACDONALD; C, E	8403020239	71-9161
LEWIS, R. C.	8403160150	50-321 F	LIM,D L.	8403020138	50-373 R	MACDONALD; C E.	8403020420	71-9108

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY
MACDONALD, C E	8403020423*	71-9108	MARGULIES, M B	8403130374	50-424 G	MARTIN, T T	8403150106	50-336
	8403050338	71-314	MARKEY, E J	8403010038*	FOIA	MARTIN, T T	8403150125	50-320
	8403050340*	71-514	MARKEY, E J	8403120393*	COMMIGBION	MARTIN, T T	8403160152	50-272
	8403060574	71-9009	MARKIN, K M	8403010371	50-257 S	MARTIN, T. T	8403160205	50-219
	8403070002	71-9190	MARKOS, O	8403050318*	WASTE MOT	MARTIN, T T	8403160241	50-352
MACDONALD, C E	8403070011	71-9160	MARKOB, O	8403050319*	Waste Mgt	MARTIN, T T	8403190151	50-213
	8403080312	71-6601	MARKOB, O	8403050322*	Waste Mgt	MARTIN, T T	8403190215	50-320
	8403080314*	71-6601	MARKOB, G	8403050323*	Waste Mgt	MARTIN, T T	8403190258	50-266
	8403080374	71-6406	MAROSE, R	8403200112*	50-409 F	MARTIN, T T	8403190259	70-378
	8403080396*	71-6406	MARSHALL, J R	8403020075	50-313 R	MARTIN, T T	8403190310	40-7455
MACDONALD, C E	8403080397	71-9001	MARSHALL, J R	8403020081	50~34B R	MARTIN, T T	9403190360	50-387
	8403080399*	71-9001	MARSHALL, J R	8403050158	50~313 P	MARTIN, T T	8403200029	50-317
	8403080416	71-9080	MARSHALL, J R	8403060203*	50~313 Q	MARTIN, T T	8403200098	50-293
	8403080418*	71-9080	MARSHALL, J, R	8403060308	50~313 R	MARTIN, T T	8403200166	50-271
	8403140235	71-513	MARSHALL, J R	8403060350	50~313 F	MARTIN, T T	8403210006	50-317
MACDONALD, C E	8403140238*	71-513	MARSHALL: J R	8403060430	50-313 F	MARTIN, T T	8403210047	50-320
	8403210212	71-6601	MARSHALL: J R	8403070137	50-368 B	MARTIN, T. T	8403210097	50-334
	8403230166	71-6601	MARSHALL: J, R	8403070177	50-313 P	MARTIN, T T	8403220006	50-272
	8403230269	71-9009	MARSHALL: J R	8403120011	50-313 F	MARTIN, T. T	8403220034	50-20
	8403260094	71-9162	MARSHALL: J R	8403130024	50-368 B	MARTIN, T. T	8403220056	50-307
MACDONALD, C. E	8403260331	71-5450	MARSHALL, J R.	8403130324	50-348 8	MARTIN, T T	8403220083	50-277
MACDONALD, C. E	8403260336*	71-8450	MARSHALL, J R	8403130347	50-348 8	MARTIN, T T	8403220085*	50-277
MACDONALD, C. E	8403280214	71-9036	MARSHALL, J R	8403130437	50-313 0	MARTIN, T T	8403220070	40-472
MACDONALD, C. E	8403280218*	71-9036	MARSHALL, J R	8403130473	50-313 F	MARTIN, T T	8403220128	50-387
MACDONALD, C. E	8403300224	71-9134	MARSHALL, J R	8403200174	50-313 F	MARTIN, T T	8403220170	40-8824
MACDONALD, C E	8403300227*	71-9134	MARSHALL, J R	8403200179	50-313 F	MARTIN, T T	8403260104	50-317
MACDONALD, C E	8403300227	71-9160	MARSHALL, J R	8403200246	50-313 F	MARTIN, T T	8403260113	50-322
MACDONALD, C E	8403300278	71-9027	MARSHALL, J, R	8403220020	50-368 8	MARTIN, T T	8403270043	70-398
MACDONALD, G E	8403300302*	71-9027	MARSHALL, J R	8403230071	50-313 P	MARTIN, T T	8403270053	50-334
MACKAY, B	8403020118	50-324 F	MARSHALL, J R	8403260137	50-368 @	MARTIN, T T,	8403270064	50-271
MACKAY, B	8403260089	50-324 F	MARBHALLIJR	8403270258	50-348 8	MARTIN.T T	8403290099	50-219
MACKAY, B D,	8403020159	50-324 F	MARBHALLIJR	8403280094	50-313 F	MARTIN.T T	8403290116	50-387
MACRAE, J B	8403020380	ORG	MARBHALLIJR	8403290127	50-348 8	MARTIN.T T	8403290144	50-352
MACRAE, J B,	8403020381	ORG	MARBHALLIJR.	8403300068	50-313 R	MARTIN.T T.	8403290186	50-289
MACRAE, J B	8403020383	ORG	MARBHALLIJR	8403300164	50-348 R	MARTIN.T.T	8403290202	50-320
MACRAE, J. B.	8403020385	0R@	Martin, J. B	8403010114*	50-508 T	MARTIN,T T. MARTIN,T T MARTIN,T T MARTIN,T.T. MARTIN,T.T.	8403270206	50-272
MACRAE, J. B.	8403020387	0R@	Martin, J. B	8403090173	PRM		8403270251	50-3
MACRAE, J. B.	8403020388	0R@	Martin, J. D.	8403020097	50-397 R		8403270286	50-27
MACRAE, J. B.	8403060458	0R@	Martin, J. D	8403070187	50-397 B		8403300063	50-387
MACRAE, J. B.	8403060460	0R@	Martin, J. D	8403130337	50-397 B		8403300065	50-271
MACRAE: J B MACRAE: J. B. MACRAE: J B MACRAE: J B. MADDEN	8403060463 8403230079 8403230080 8403260039 8403060171	ORG ORG ORG DRG FDIA	D C'NITRAM D C'NITRAM D C'NITRAM D C'NITRAM	8403200237 8403240025 8403280003 8403280007 8403300054	50-397 8 50-397 8 50-397 8 50-397 8 50-397 8	MARTIN,T.T MARTIN,TT MARTIN,T.T MARTIN,TT MARTIN,TT	8403300072 8403300084 8403300086 8403300078 8403300121	50-322 50-245 50-245 50-354 50-354
MADDEN, B.	8403190135	50-220 B	MARTIN.J P	8403200105	50~397 B	MARTIN, T.T.	8403300142	50-271
MADDEN, T. J.	8403010111	FOIA	MARTIN.T J	8403070080	50~272 G	Martin, T.T.	8403300161	50-213
MADDEN, T J.	8403080226	FOIA	MARTIN.T J.	8403130014*	50~354 G	Mabetantonid; A	8403270296	50-352
MADDEN, W	8403300074	50-219 B	MARTIN.T J	8403130372*	50~354 G	Mabon, C.C.	8403020002	50-327
MADDEN, W J.	8403220010*	50-272 G	MARTIN.T J	8403130108	50~354 B	Mason, C.C.	8403020147	50-327
MADEDA: T J	8403010348*	50-454 G	MARYIN,T J	8403210118	50-354 8	Mason, C, C	B403020244	50-327
MADEDA: T J.	8403170237*	50-331 G	MARTIN,T T	8401240337	70-1100	Mason, C, C	B403050080	50-327
MADERA: J R.	8403060210*	40-8830	MARTIN,T T	8403010301	50-317 F	Mason, C, C	B403060276	50-327
MADERA: J. R	8403080215*	FDIA	MARTIN,T T	8403010307	50-352 9	Mason, C, C	B403150079	50-327
MADERA: Q	8403130271*	GA999	MARTIN,T,T	8403010360	70-1100	Mason, C, C	B403190121	50-327
MADBEN, O L	8402150226#	GA799	MARTIN,T T	8403020214	50-388 G	Maedn. C C	8403190365	50-327
MADBEN, B H.	8403140328#	CONTRACT	MARTIN,T T	8403020262	50-293 G	Maedn. C C	8403260164	50-327
MAIER, J E.	8403300191#	50-244 G	MARTIN,T.T.	8403020306	50-277 G	Maedn. C C	8403300073	50-327
MAKAY, E.	8403190282#	50-312 G	MARTIN,T T	8403020315	50-293 G	Maedn. C C	8403300154	50-327
MALCOM, J B	8403020077#	CONTRACT	MARTIN,T T	8403020331	40-6920	Maedn. C. C.	8403300204	50-328
Maliddy, C. W.	8403060421*	70-1257	MARTIN, T T	840302034 1	50-247 G	MABBARD: 8 A	8403260056	NUREG
Malech, M. G.	8403080379*	FDIA	MARTIN, T. T.	8403020353	50-286 G	MABBE: F X.	8403070212	FR
Mangan, C. V.	8403060221	50-220 P	MARTIN, T. T.	840305001 4	50-247 G	MATHENY: K A	8403130106*	50-440
Mangan, C. V.	8403060247	50-220 P	MARTIN, T T	8403050134	40-672	MATHENY: K. A	8403130118*	50-440
Mangan, C. V.	8403060446	50-220 P	MARTIN, T. T	8403050274*	FDIA	MATHENY: K. A.	8403130128*	50-440
MANGAN, C. V.	8403090040	50-220 P	MARTIN, T T	8403070240	50-387 Q	MATHENY, K. A	8403130138*	50-440
MANGAN, G. V.	8403090146	50-220 P	MARTIN, T. T.	8403070258	70-1100	MATHESON, B. M	8403140027	Warte Ma
MANGAN, C. V.	8403120059	50-220 P	MARTIN, T T	8403070276	50-352 Q	MATHENS, C. S	8403200222	50-206
MANGAN, G. V.	8403130363	50-410 S	MARTIN, T T	8403070278	50-309 F	MATHENS, M. L.	8403220303	Warte Mg
MANGAN, C. V	8403130386	50-220 P	MARTIN, T T.	8403070301	50-387 Q	MATHENS, T. P.	8403200176	50-288
Mangan; C. V.	8403200002	50-220 P	MARTIN, T T.	8403070320	50-277 Q	MATTHEMBID.B	8312120445*	50-400
Mangan; C. V.	8403200232	50-410 A	MARTIN, T T	8403070333	50-423 Q	MATTIA.M J.	8403130495*	CONTRACT
Mangan; C. V	840321013 <i>6</i>	50-410 S	MARTIN, T. T.	8403080159*	FOIA	MATTIA.M J.	8403220240	CONTRACT
Mangan; C. V	8403220177	50-220 P	MARTIN, T. T	8403090037	50-354 Q	MATTIA.M J.	8403280263*	CONTRACT
Mangan; C. V.	8403230078	50-220 P	MARTIN, T T.	8403090143	50-443 F	MATTIMDE.J J	8403060452	50-312
Mangan, C. V.	8403230114	50-220 F	MARTIN,T.T	8403070231	50-387 F	MATTINDE, J. J.	8403060467	50-312
Mangan, C. V.	8403270174	50-220 P	MARTIN,T.T	8403120101	50-320 G	MATTIMDE, J. J.	8403260124	50-312
Mangan, C. V.	8403300058	50-220 P	MARTIN,T T	8403130009	50-354 G	MATTEON, D. R.	8403230173	WASTE M
Mangoba, L. B.	8403120015*	50-275 G	MARTIN,T T.	8403130171	50-272 F	MATTEON, D. R.	8403280253	WASTE M
Mankoff, L. L.	8403130387	PT21	MARTIN,T T.	8403130294	70-2179	MATTEON, R. J.	8402010508#	50-275
MANOLY, K.	8403300103*	50-354 G	MARTIN, T. T.	8403130300	M18C	MATUSEWIC, 8 M,	8403200020	50-156
MANOLY, K. A.	8403020272*	50-293 G		8403130422	40-6327	MAURA, F. A	8403170277*	50-373 ;
MANOLY, K. A.	8403150034*	50-388 G		8403150012	50-217 G	MAUSEWARDT, D. B	8403010015*	ACRS
MARANTE, R. J.	8403200067*	50-219 G		8403150027	50-388 G	MAUSEWARDT, D. B	8403010057*	ACRS
MARGULIES, M. B.	8403060111	50-508 G		8403150068	50-272 G	MAXWELL, C,	8402230244*	50-400

AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MAXWELL, 0 F MAXWELL, 0 F MAXWELL, J C MAXWELL, J C MAXWELL, R	6402230248* 6403070199* 6403140302 6403140302 6403060235	50-400 A 50-400 G 50-400 D 50-400 D 50-259 F	MCGAUGHY, J P MCGAUGHY, J. P MCGAUGHY, J. P MCGAUGHY, J P	84030 90265 8403210041 8403210057 8403210192 8403230084	50-416 S 50-417 S 50-416 P 50-416 B 50-416 P	MEDFORD, M O MEDFORD, M O MEDFORD, M O MEDFORD, M O MEDFORD, M O	8403230074 8403280030 8403270122 8403270182 8403270217	50-341 R 50-204 F 50-206 F 50-206 P 50-361 P
MAYER, M MAYER, M MAZUR, D H MCALPINE, E J MCALPINE, E J	8403040310# 8403220310# 8403240274 8403020194 8403070328#	50-322 T 50-322 T 50-397 P 70-143 70-27	HCQAUQUAGOM HCQACQUAGOM HCQACQUAGOM HCQACQUAGOM HCQACQUAGOM HCQACQOM	8403230087* 8403270134 8403270134 8403270030 8403020108	50-416 P 50-206 B 50-205 B 50-416 Q 50-331 P	MEDFORD, M O MEDLOCK, R L MEDLOCK, R L MEDLOCK, R L MENDELE, D J	8403290295 8403150235 8403150245 8403190436 8403090270	50-206 P 40-8452 40-8452 40-8452 50-282 F
MCALPINE,E J MCALPINE,E J MCALPINE,E J MCALPINE,E J MCALPINE,E J	8403160270* 8403160348* 8403160353* 8403160380* 8403160386*	70-143 70-1113 70-143 70-1113 70-143	MCGAUGHY,R W MCGAUGHY,R H MCGAUGHY,R H MCGAUGHY,R H	8403040136 8403070088 8403070262 8403130144 8403150087	50-331 F 50-331 P 50-331 P 50-331 P 50-331 P	MENDELSON, I N MENDEZ, R MENDLER, J. MENGE, R C MERCER, B W	8403010044* 8403200300* 8403230208 8403230216 8403230177	CONTRACT 50-454 G NUREO 50-315 B NUREO
MCALPINE,E J MCALPINE,E J MCBAY,L Q MCBREARTY,R MCBREARTY,R A	8403160389* 8403210156* 8403090189 8403020399* 8403020272*	70-143 70-143 50-424 C 50-273 G 50-273 G	MCGAUGHY:R W MCGAUGHY:R W MCGAUGHY:R W. MCGAUGHY:R W MCGAUGHY:R W.	8403190295 8403190300 8403200192 8403230004 8403230105	PR 50-331 P 50-331 P 50-331 P 60-331 Q	MERRELL, W. W MERRIWEATHER, N MERSCHOFF, E W METZENBAUM, H M MEYERS, B L	8403070332* 8403160212* 8403010430* 8402130372* 8403230108	TOPREP 50-424 Q 50-423 Q 50-358 U 50-482 S
MCBREARTY,R A MCBREARTY,R.A MCBREARTY,R.A MCBRIDE,L M MCBRIDE,L M	8403150034* 8403220062* 8403270062* 8403010185* 8403010167*	50-368	MCGNOWNY W MCGONEWY J J MCGOVEWY J J MCGOVEWY J J	8403260208 8403220043 8403300140* 8403140210 8403010141*	50-331 P 50-54 I 70-687 50-348 F 50-348 P	MICHEL, E J MICHEL, E J MICHEL, E J MICHELSON, C MIDURA, H J	8403060289# 8403060295# 8403060307# 8104220046 8403070305	50-322 T 50-322 T 50-322 T 50-335 B 50-272 R
MCBRIDE, M MCCABE, E C MCCABE, E C MCCABE, E C MCCABE, E C	B403150073# B403010390# B403150060# 8403220089# 8403220160#	50-293 0 50-322 0 50-387 0 50-354 0 50-322 0	MCGUIRE, DR MCGUIRE, DR MCGUIRE, DR MCGUIRE, DR MCGUIRE, DR	8402130404# 8403020241# 8403050178# 8403150109# 8403140016#	50-348 Q 50-250 Q 50-413 Q 50-260 Q 50-390 Q	MIELE, M. L. MIELE, M. L., MIELE, M. L. MIELE, M. L. MIELE, M. L.	8403070183* 8403070217* 8403070231* 8403230016 8403230020	50-322 T 50-322 T 50-322 T 50-322 T 50-322 T
MCCABE, E C MCCAFFREY, B R MCCAFFREY, B R MCCAFFREY, B R MCCAFFREY, B R	8403270155* 8403020139 8403020287 8403140019 8403190127	50-387 G 50-322 A 50-322 E 50-322 A 50-322 S	MCGUIRE, D R MCGUIRE, D R MCGUIRE, D R MCGUIRE, D R MCGUIRE, P	8403140388* 8403190188* 8403240183* 8403300044* 8403040289*	50-302 G 50-259 G 70-27 70-27 50-322 T	MIELE, M L MIELE, M L MIELE, M L MIELE, M L MIELKE, F, W	8403230032 8403230038 8403230048 8403230073 8403280051	50-322 T 50-322 T 50-322 T 50-322 T 50-133 I
MCCAFFREY.B R MCCAFFREY.B R MCCAFFREY.B R MCCAFFREY.B R MCCAFFREY.B R	8403200227 8403200302 8403270119 8403270197 8403280029	50-322 A 50-322 A 50-322 R 50-322 G 50-322 F	MCGUIRE,P MCGURREN,H J MCGURREN,H J MCKAY,L.R MCKAY,L R	8403040295# 8403190073 8403190100 8403280018# 8403280025#	50-322 T 50-413 9 50-275 0 50-416 P	MIKLOB, J MIKOWSKI, J MILES, H L MILETI, D S MILETI, D S	8403140151 8403070113 8403210107 8403010244 8403230032	PR FOIA PRM 50-322 T 50-322 T
MCCARTHY, L T MCCLESKEY, K E MCCLESKEY, K E MCCLESKEY, K E	8403240111# 8403010183 8403010183 8403070147 8403070147	50-275 U 50-322 0 50-322 G 50-322 T 50-322 T	MCKEE,PF MCKENNA.E MCKENNA.E MCKENNA.E M MCKEON.T J	8403130499# 8403060156 8403220001 8403230070 8403230173	50-312 @ 50-204 P 50-204 P 50-204 P NUREO	MILL.8 MILLER.A MILLER.C A MILLER.C A MILLER.C W	8403080388 8403080178 8403010217# 8403010231# 8403300120	FOIA 50-320 F 50-329 A 50-329 A RES
MCCLESKEY, K E MCCLESKEY, K E MCCLESKEY, K E	8403130030* 8403130030* 8403230013 8403230013	50-322	McLaughlin, L. McLearen, T McLearen, T McMurray, C M McMurray, C M	8403040390 8403010051 8403010435 8403150026 8403150026	50-389 B CONTRACT CONTRACT 50-322 G 50-322 G	MILLER, D. E. MILLER, D. J. MILLER, D. W. MILLER, H. J. MILLER, H. J.	8403130094* 8403200040 8403050090 8403060450 8403200345	40-3392 50-334 F 50-387 F WASTE MOT WASTE MOT
MCCLESKEY, K E MCCLINTOCK, R MCCLINTOCK, R O MCCLINTOCK, R O MCCLINTOCK, R O	8403300277 8403080070* 8403080087* 8403080099* 8403080102*	50-322 G FOIA FOIA FOIA	McHurray, c m McMurray, c m McMurray, c m McMurray, c m, McMurray, c m	8403200131 8403200131 8403200134* 8403200134* 8403200131*	50-322	MILLER, J.L MILLER, J.R. MILLER, J.R. MILLER, J.R. MILLER, J.R.	8403140125# 8402210294 8403010112 8403010253# 8403020283	50-400 F 50-335 P 50-344 P 50-142 G 50-307 P
1CCOLLOM, K A 1CCONNELL, T 1CCORKLE, G W 1CCORKLE, G W 1CCRACKEN, C E	8403170002 8403070352 8403080411= 8403080417+ 8403170189+	50-445	McMurray.c m McMurray.c m McMurray.c m McNamara,a e McNeill,c a	8403200151* 8403200155* 8403200155* 8403020202 8403010241	50-322	MILLER, J.R. MILLER, J.R. MILLER, J.R. MILLER, J.R. MILLER, J.R.	8403050203 8403050208 8403050226 8403050227 8403050243*	50-317 0 50-266 F 50-344 P 50-280 P 50-282 P
ICCNWBER' ? I ICCUONE' ? ICCUONE' ? ICCUONE' ? ICCUONE' ?	8403210173* 8403050102 8403060355* 8403060361* 8403020065	50-289 G GA999 GA999 GA999 GA999 50-309 R	MCNEILL, C A MCNEILL, C A MCNEILL, C A MCNEILL, C A MCNEILL, C A	8403010365 8403010413 8403010420 8403060193 8403090025	50-333	MILLER, JR, Miller, JR Miller, JR, Miller, JR, Miller, JR,	8403050352 8403050354 8403050355 8403050380 8403060080*	50-336 Q 50-335 P 50-309 P 50-309 P 50-335 P
ICCUMBER. J T ICDONALD. B A ICDONALD. D 0 ICDONALD. D. O ICDONALD. D. O	8403300142 8403060106 8403010160 8403050055 8403120038	50~309 R 50~349 F 50~250 P FDIA 50~204 H	Moneill, c a Moneill, c a Moneill, c a Moneill, c a Moneill, c a	8403130137 8403130350 8403200231 8403220081* 8403270246	50-933 R 50-333 R 50-333 B 50-333 G 50-333 S	MILLER, J. R MILLER, J. R. MILLER, J. R MILLER, J. R. MILLER, J. R	8403060447 8403060456 8403060462 8403060512 8403060551	50-344 P 50-344 Q 50-338 F 50-285 F 50-388 P
CDONDUGH, C, L CDUFFIE, M A CDUFFIE, M A CDUFFIE, M. A CDUFFIE, M A	8403140001 8403130062 8403140120 8403140174 8403190065	50-456 D 50-400 E 50-400 F 50-400 G 50-400 F	MCNEILL,W M MCGUEEN,M M MEDFORD,M D. MEDFORD,M O. MEDFORD,M.O	8403170170* 8403270034* 8402230176 8403020040 8403020092	GA999 FDIA 50-133 F 50-341 R 50-341 P	MILLER, J R MILLER, J R. MILLER, J R. MILLER, J R. MILLER, J, R.	8403080083 8403080191* 8403120082 8403120214 8403120217*	50-317 P F01A 50-348 P 50-335 P 50-335 P
CDUFFIE,M A CDUFFIE,M A CDUFFIE,M A CGARRY,J M CGARRY,J M	8403210131 8403260009 8403290134 8403070048 8403070048	50-400 A 50-400 M 50-400 E 50-413 Q 50-413 Q	MEDFORD, M O	8403020275 8403050140 8403060363 8403060397 8403060424	50-204 8 50-204 8 50-204 X 50-206 8 50-361 P	MILLER, J.R. MILLER, J.R. MILLER, J.R. MILLER, J.R. MILLER, J.R.	8403120240 8403120379 8403140299 8403150290 8403150333	50-335 Q 50-344 F 50-313 P 50-282 P 50-309 P
COARRY, J M COARRY, J M COARRY, J M COARRY, J P	8403140029 8403140029 8403240347 8403240347 8403070325	50-413 0 50-413 0 50-413 0 50-413 0 50-414 P	MEDFORD, M. O MEDFORD, M. O MEDFORD, M. O MEDFORD, M. O MEDFORD, M. O	8403090127 8403130134 8403190345 8403200097 8403220121	50-361 Q 50-361 P 50-361 P 50-204 F 50-206 P	MILLER, J. R MILLER, J. R MILLER, J. R MILLER, J. R MILLER, J. R	9403170417 8403210204* 8403220212* 8403220257* 8403220071	50-266 P 50-338 P 50-338 P 50-266 P 50-344 P

AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MILLER, J R MILLER, J R MILLER, L K MILLER, L K MILLER, M A	8403240302 8403280183 8403220142 8403220174 8403050311	50-944 F 50-285 P 50-311 R 50-272 R 50-424 A	MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8403160223* 8403160318* 8403160364* 8403160373 8403190054	50~259	MONTOGMERY, D M MONTOGMERY, D M MONTOGMERY, D M MONTOGMERY, D M MONTOGMERY, J M MONTOGMERY, J A	8403160309* 8403160329* 8403290147* 8403290239* 8403060426	50-395 50-349 50-413 50-259 50-320
MILLER,M A MILLER,M E MILLER,M I MILLER,M I MILLER,M I	8403070409# 8403200108# 8403210087 8403200122 8403200122	50-322 S 50-354 G 50-354 G 50-454 G 50-454 G	MILLS, L M MILLS, L M MILLS, L M MILLS, L M	8403190099 8403190149* 8403190161* 8403190287 8403190358	50-390 8 50-259 9 50-259 9 50-438 8 50-390 8	MDONFY, J A MOGNEY, J A MOGNEY, J A MOGNE, D E MOGNE, D E	8403150003 8403200027 8403200039 8402130404* 8403050178*	50-329 50-329 50-329 50-348 50-413
MILLER,M L MILLER,M S MILLER,M S MILLER,M S MILLER,M S	8403010316 8403130174 8403130174 8403200140* 8403200140*	50-263 5 50-322 0 50-322 0 50-322 0 50-322 0	MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8403170347 8403170370 8403200170 8403200225 8403210037	PR 50-327 F 50-259 P 50-390 A 50-390 S	MODRE, J E MODRE, J E MODRE, J E MODRE, J E MODRE, J E	8403120010* 8402070054 8403140159 8403140163* 8403270317	50-275 50-400 50-400 50-400 50-400
MILLER,M 8 MILLER,M 8 MILLER,M 8 MILLER,M 8 MILLER,N E	8403200145* 8403200145* 8403200146* 8403200146* 8403800894	50-322 0 50-322 0 50-322 0 50-322 0	MILLS, L M MILLS, L M MILLS, L M MILLS, L M	8403210042 8403210046 8403210066 8403210086 8403210132	50-438 S 50-438 S 50-390 S 50-390 B 50-438 S	MDORE, K E MODRE, R N MODRE, R N MODRE, R N MORAN, D H	8403170244# 8403200372 8403280337 8403270127 8403170217	TOPREP XPORTLIC XPORTLIC XPORTLIC TOPREP
MILLER,R L MILLER,V.L. MILLER,W A MILLER,W H MILLER,W O	8403150214 8403080155* 8402070384* 8403160072* 8003240157*	50-30 W FDIA 50-390 F 50-413 G 50-508 A	MILLS.L M MILLS.L M MILLS.L M	8403220220 8403240212 8403240218 8403240229 8403240227	40-1341 50-390 A 50-390 A 50-289 P 50-327 F	MDRAN, D H MORELAND, P E MORELAND, P E MOROAN, R E MORGAN, R E	B403280242 8403210005* B403210010* B403080135 B40308025B	TOPREP 40-6920 40-6920 50-261 50-261
MILLER, W D MILLER, W O MILLER, W O MILLER, W O MILLER, W O	8211070018* 830507050&* 8308100483* 8403050215 8403050222	30-556 Q 50-509 Q 50-397 A TOPREP TOPREP	MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8403270145 8403270218 8403270026 8403270036 8403270183*	50-390 F 50-390 E 50-327 P 50-327 P 50-259 Q	MORGAN, R. E MORGAN, R. E MORGAN, R. E MORGAN, R. E MORGENSTERN, A	8403150098 8403160262* 8403200245 8403230127 8403150153	50-241 50-241 50-241 50-241 XPORTLIC
MILLER, W. D MILLER, W. D. MILLER, W. D. MILLER, W. D MILLER, W. D	8403050225 8403060011 8403070001 8403120237 8403200371	TOPREP TOPREP 50-338 P 50-266 P 50-277 F	MILLS,L M MILLS,L M MILLS,L M MILLS,L M	8403270207* 8403300004 8403300021 8403300038 8403300039	50-259 0 50-438 S 50-438 S 50-370 E 50-438 B	MORGENBTERN, M MORIARTY, J M MORIARTY, J M MORKIN, K M MORKIN, K M	8403230200 8403190248 8403190374 8403060244 8403220159	NUREQ 50-395 50-443 50-259 50-260
MILLER, W D MILLER, W D MILLER, W D MILLER, W D MILLER, W D,	8403270358 8403270371 8403300225 8403300279 8403300299	50-206 P 50-389 P 50-261 P 50-331 P 50-324 P	MILLB:L M MILLB:L M MINARICK:J W MINECK:D L MINECK:D L	8403300054 8403300109 8403010102* 8403050145 8403120042	50-43B 8 50-370 8 FOIA 50-331 8 50-331 R	MORLEY, J A MORLEY, J A MORRILL, P MORRILL, P J MORRILL, P J	8403060519 8403140312 8309150401* 8403010833* 8403210119*	WASTE MOT WASTE MOT FOIA 50-312 50-275
MILLER, W O MILLE, L. M MILLE, L. M MILLE, L. M MILLE, L. M.	8403300304 8402090380 8403010095 8403010306 8403010339	50-219 P 50-390 F 50-438 B 50-259 P 50-390 S	MINECK.D L MINECK.D L MINECK.D L MINECK.B L MINER.8	8403120071 8403120139 8403130488# 8403220017 8403010374	50-331 8 50-331 8 50-331 F 50-331 R 50-312 P	MORRIB, A E MORRIS, C MORRIS, C MORRIS, C A MORRIS, C A	8403080412# 8310170712# 8403050025# 8403020010 8403020218	50-320 50-286 50-286 50-361 50-206
MILLB,L M. MILLB,L M MILLB,L M MILLB,L M MILLB,L M	8403010376 8403020236 8403020313 8403020334 8403060147	50-438 8 50-390 F 50-327 P 50-390 F 50-259 F	MINER, S MINOGUE, R B. MINOGUE, R B. MINOGUE, R B. MINOR, G C	8403150350 7910260122# 8403150175 8403270024# 8403220305#	50-213 P 50-312 P REG FOIA 50-322 T	MORRIS, C A MORRIS, C A MORRIS, C A MORRIS, C A MORRIS, C A	8403200057* 8403200074* 8403200077* 8403200082* 8403200086*	50-361 50-361 50-361 50-361 50-361
MILLE, L M MILLE, L, M MILLE, L, M, MILLE, L, M, MILLE, L M.	8403040238 8403040391 8403070023 8403070054 8403070064	50-259 F 50-327 F 50-259 G 50-259 G 50-438 G	MINOR.Q C MIRAGLIA,F.J MIRAGLIA,F J MIRAGLIA,F J MIRAGLIA,F J	8403220313* 8106170138* 8106220066* 8203180118* 8403020049*	50-322 T FOIA 50-308 Q 50-308 A FOIA	MORRIS, C. A MORRIS, C. A MORRIS, C. A MORRIS, P. A MORRIS, P. A	8403200088* 8403200091* 8403300003 8403060097 8403200070	50-361 50-361 50-206 50-352 50-352
MILLB, L M MILLB, L M MILLB, L M MILLB, L M MILLB, L, M	8403070089 8403070155* 8403070174 8403070224* 8403070230	50-438 Q 50-327 Q 50-390 B 50-438 Q 50-390 Q	MIRAGLIA:F J MIRAGLIA:F J MIRAGLIA:F J MIRAGLIA:F J MIRAGLIA:F J	8403050132* 8403060037 8403080271 8403090195 8403270245	50-204 F 50-155 P MISC 50-206 P 50-322 F	MORRIS, P A MORRISON, W M MORTON MORYON, K L MORTON, K L	8403280354 8403276035# 8403010078# 8403020075 8403300068	50-352
MILLS, L M. MILLS, L. M MILLS, L. M. MILLS, L. M. MILLS, L. M	8403070235 8403070237 8403070241 8403070245 8403070286	50-370 @ 50-257 @ 50-438 @ 50-370 @ 50-370 B	MIRAGLIA.F J MIROCHNA.R. MIBAK.A MITTENBERGER.B MITTL.R L.	8403300308 8403230076 8403130382 8403160246 8403140113	50-155 P 50-237 8 50-254 R 50-463 F 50-354 A	MORTON, K. V MORTON, K. V MORTON, K. V, MORTON, K. V MORTON, K. V	8403020043* 8403050237* 8403040495* 8403060502* 8403070009*	50-10 , CONTRACT CONTRACT CONTRACT CONTRACT
MILLB, L, M, MILLB, L, M MILLB, L, M, MILLB, L, H, MILLB, L, H	8403070274 8403070297 8403070329 8403070024 8403070050	50-438 8 50-438 8 50-438 9 50-438 8 50-370 8	MITTL:R L. MITTL:R L MITTL:R L MITTL:R L MIZUND:9.8	8403210036 8403230041 8403270277 8403270302 8403140055	50-354 A 50-354 C PR 50-354 A 50-445 0	MORTON, K V.	8403070032* 8403070141* 8403070172* 8403070346* 8403070135*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
MILLB, L, M MILLB, L, M MILLB, L, M, MILLB, L, M MILLB, L, M	8403090163 8403090181 8403090206 8403120105 8403120163	50-438 8 50-438 8 50-390 8 50-438 8 50-438 8	MOBLEY, M. H MONAGHAN, J. A MONAGHAN, J. A MONAGHAN, J. A MONAGHAN, J. A	8403070105 8403130018* 8403130018* 8403130041* 8403130041*	PR 50~382 0 50~382 0 50~382 0	MORTON,K V, MORTON,K V. MORTON,K V. MORTON,K V. MOSLAK,T.	8403150207* 8403230076* 8403230130* 8403290343* 8403060110	CONTRACT CONTRACT CONTRACT FOIA 50-320
MILLB, L M MILLB, L M MILLB, L M, MILLB, L, H MILLB, L M,	8403120179 8403130007 8403130025 8403130088 8403150007	50-390 E 50-259 P 50-259 P 50-327 Q 50-439 S	MONACHAN, J.A. MONACHAN, J.A. MONACHAN, J.A. MONACHAN, J.A. MONACHAN, J.A. MONACHAN, J.A.	8403130053* 8403130053* 8403130063* 8403130063* 8403130073*	50~322 0 50~322 0 50~322 0 50~322 0	MOSLAK, T MOSLAK, T. MOTES, B. G. MOWRY, W R MOWRY, W R.	8403060435 8403130471* 8403060533 8403150197 8403150197*	50-320 6 50-320 6 NAMEG XPORTLIC XPORTLIC
MILLB, L M MILLB, L M. MILLB, L, M MILLB, L, M. MILLB, L, M	8403150059 8403150127 8403150229 8403160042 8403160171#	50-438 8 50-390 9 40-1341 50-438 8 50-259 0	MDNAQHAN, J A MONTEITH, J. L MONTEITH, J L MONTOOMERY, D MONTOOMERY, D, M	8403130073* 8403060287* 8403060275* 8403270030* 8403160202*	50-322 Q 50-322 T 50-322 T 50-370 Q 50-370 Q	MADCZKA, E. J MADGZKA, E. J MADGZKA, E. J MADGZKA, E. J MADGZKA, E. J	8403010217 8403010217 8403020055 8403020133 8403020133	50-336 50-336 50-245 " 50-336 "

AVTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY
MROCZKA, E. J	84032001J3	50-336 S	MYRABD, A.L.	8403020197	50-243 R	NOREL 1UB, C E	8403080211#	FDIA
MROCZKA, E. J	8403260284	50-245 S	MYRABD, A.L	8403300087	50-243 R	NOREL 1UB, C E	8403120070	50-237 Q
MROCZKA, E. J	8403300080	50-336 R	NADEL, M.V	8403070109	NUREG	NOREL 1UB, C. E	8403120073#	50-237 Q
MROCZKA, E. J	8403300080	50-336 R	NA IDU, K.	8403190076*	50-373 Q	NOREL 1UB, C. E	8403120120	50-331 Q
MROCZKA, E. J	8403300135	50-245 R	NAKAMURA, N	8403010466	XPORTLIC	NOREL 1UB, C E	8403120124#	50-315 Q
MROCZKA, E. J	B403300135	50-245 R	NAKAMURA, N	8403050364*	XFORTLIC	NORELIUS, C, E	B403120125#	50-331 0
MUDD, C. H	B4032E0107	50-348 F	NAKAMURA, N	8403050364*	XFORTLIC	NORELIUS, C E	B403130204	50-440 0
MUELLER, C. J	B403140339	ACRS	NAPIER, J J.	8403306100	50-317 S	NORELIUS, C, E	B4031700B5	50-123 0
MUELLER, C. J	B403140337	ACRS	NAPUDA, Q	8403020220*	50-388 Q	NORELIUS, C E	B403170074#	50-123 0
MUFFETT, J	B4030B0302#	50-315 Q	NARDUT, P	8402140031*	50-528 Q	NORELIUS, C E	B403230137	50-315 0
HULLAUER, JR	8403080215*	FOIA	NARBUT,P.	8403230117	50-312 8	NORMAN, D	8403010430#	50-423
MULLER, D. R	8301040211*	50-400 E	NARBUT,P.P.	8403270139*	50-528 0	NORRHOLM, L.	8403150166#	
MULLER, D. R	8309290412*	50-400 E	NARDOCI,P.B.	8403060232	50-370 8	NORRHOLM, L. J	8403220115#	
MULLER, D. R	8312080188*	50-400 E	NARDOCI,P.B.	8403120150	50-370 8	NORRHOLM, L. J	8403270139#	
MULLER, K.	8403150253	40-8786	NARDOCI,P.B.	8403120173	50-370 8	NORRIS, H, R	8403080135	
MULLER, M. MUNBON, L. F MURLEY, T. E MURLEY, T. E MURLEY, T. E	8403150240 8403170447 8403010472 8403010483* 8403020343	40-8784 NUREQ 40-6920 40-6920 50-317 G	NARDOCI:P B NARDOCI:P B NARDOCI:P B NARROH:L NARROH:L	8403130167 8403130332 8403150138 8403020272* 8403070322*	50-370 8 50-369 8 50-370 8 50-293 0 50-277 0	NORRIE, H R. NORRIE, J. A. NORRIE, J. A. NORRY, P. G. NORRY, P. G	8403080258 8403280090 8403120326 8403020378 8403300265	50-241 R 50-275 F 50-275 F DR9 DR9
MURLEY, T E MURLEY, T E MURLEY, T E MURLEY, T E MURLEY, T, E	8403080403 8403080407* 8403130212 8403150111 8403170243	50-289 Q 50-289 Q 50-293 Q 50-293 P 50-3 F	NARVER, R. B NATARAJA, M S NEFF, J. O NEFF, J. O NEICHALFEN, A P	8403140026* 8403260344 8403260348 8403300237 8403120104	50-329 A Waste Mot Waste Mot Waste Mot 50-483 A	NORTH, H B, NORTON, B. NORTON, B NORTON, B NORTON, B.	8403080075* 8403070044 8403070044 8403120006 8403120006	50-312 @ 50-275 @ 50-275 @ 50-275 @ 50-275 @
MURLEY, T E MURPHY, A J MURPHY, C E MURPHY, C E MURPHY, L, E	840322013A	50-213 G	NEIGHBORB, J D	8403020054	50-280 P	NOTARO, J A	B403270116	50-322 A
	8403070013*	50-289 U	NELBON, Q. B	8403010266#	50-142 Q	NOVACHEK, F.	B403010116	50-247 S
	8402230239*	50-400 A	NELBON, Q B	8403060331#	70-734	NOVACHEK, F	B403010155#	50-247 S
	8403080212*	50-413 G	NELBON, P R	8403080049#	FOIA	NOVACHEK, F	B403010167#	50-247 S
	8403220307	CONTRACT	NELBON, P R.	8403080050#	FOIA	NOVACHEK, F	B403220063	50-247 S
MURPHY, L. 0	8403260296	CONTRACT	NELBON, P, R	8403080099*	FOIA	NOVAK, T. M.	B402090016	50-413 A
MURPHY, M R	8403210038	WASTE HGT	NELBON, P R	8403080102*	FOIA	NOVAK, T. M	B403070221*	50-440 A
MURPHY, H P	8403020247	50-271 P	NELBON, P, R	8403080109*	FOIA	NOVAK, T. M.	B403190186*	50-329 A
MURPHY, W P.	8403170086	50-271 R	NELBON, P R	8403080123*	FOIA	NOVAKOVICH, D	B403200371	XPORTLIC
MURPHY, W P.	8403200156	50-271 Q	NELBON, P R	8403080139*	FOIA	NOVAKOVICH, D	B403280151*	XPORTLIC
MURPHY, W P	8403230063	50-271 F	NELSON, P R,	B4030B0144*	FOIA	Nugent, E. L.	8403120251	40-2259
MURPHY, W P	8403270190	50-271 P	NELSON, P R	B4030B0157*	FOIA	Nugbbaumer, D	8403120248	Waste Mot
MURPHY, W P.	8403300071*	50-271 Q	NELSON, P R	B4030B0177*	FOIA	Nugbbaumer, D. A	8403020332	Waste Mot
MURPHY, W P.	8403300146*	50-271 Q	NELSON, R	B403300030*	50-454 G	Nugbbaumer, D. A	8403080119#	Foia
MURPHY, W P.	8403300153	50-271 Q	NELSON, R L	B403190384*	50-305 G	Nugbbaumer, D. A.	8403080128#	Foia
MURRAY, B	8403060184*	50-443 Q	NELSON,R W	8403230173	NUREC	NUSSBAUMER, DA	8403080138#	FDIA
MURRAY, B	8403130148*	50-267 Q	NEMETHY,E	8403210018	PR	NUSSBAUMER, DA	8403080181#	FDIA
MURRAY, B	8403260087*	50-382 Q	NEMETHY,E	8403210022	PR	NUSSBAUMER, DA	8403150221	WASTE MOT
MURRAY, B	8403260107*	50-267 Q	NGRSES,Y	8403280122	50-244 P	NUSSBAUMER, DA	8403190420	WASTE MOT
MURRAY, B	8403260178*	50-285 Q	NEUMANN,S P	8403230197	NUREC	NUSSBAUMER, DA	8403260153#	40-1478
MURRAY, B MURRAY, B MURRAY, T MURRAY, T MURRAY, T D	8403240211* 8403240250* 8403300050* 8401140250 8403020078	50-267 0 50-382 0 50-313 0 50-346 8 50-346 R	NEWMAN, J R NEWMAN, T C NICHOLAB, J, B NICHOLB, N, N NICHOLB, N N	B403070117 8403080281* B403060184* B403150024 B403150024	50-498 Q 50-275 E 50-445 Q 50-352 Q 50-352 Q	NUTT, W.T. NUTT, W.T NYKIRK, J.W. O'CONNELL, J O'CONNOR, P.W.	8403230102* 8403230104* 8403140082 8403270347 8403270240	50-255 F 50-255 F 50-295 F 50-275 G 50-482 A
MURRAY, T. D	8403070251	50-346 R	NICHOLBON, N	8403170334*	90-295	O'CONNOR, P. W.	8403270283	50-492 A
MURRAY, T D	8403130274	50-346 F	NICHOLBON, W O	8403020050		O'CONNOR, P. W	8403270351	50-482 A
MURRAY, T D	8403170107	50-346 R	NIGHTINGALE, E	8403170323*		O'DONNELL, F. R	8403120255	RES
MURRAY, T D	8403170213	50-346 R	NIMITZ, R. L.	8403070306*		O'NEILL, J.	8403260360	50-155 Q
MURRAY, T D	8403270147	50-346 F	NIMITZ, R. L.	8403130208		O'NEILL, J. H	8403010263	50-400 Q
MURRAY, T D. MUSELER, W J MUSELER, W J MUSELER, W J MUSELER, W J MUSELER, W J.	8403300184 8403010207 8403010207 8403010218 8403010218	50-346 R 50-322 8 50-322 8 50-206 8	NIMITZ.R L. NIX.H C NIX.H C. NIX.H C NIX.H C	8403290210* 8403010330 8403090228 8403090282 8403120031	50-272 0 50-321 B 50-321 B 50-321 F 50-324 S	A 'Y 'Y INIAN, O H C'NEITF' O H C'NEIFN, O H C'NEIFF' 'Y' H	8403010263 8403130447 8403130447 8403130459# 8403130459#	50-400 9 50-400 0 50-400 9 50-400 9
Museler, W.J. Museler, W.J. Museler, W.J. Museler, W.J. Museler, W.J.	8403140048 8403140050 8403150133 8403150133 8403270132	50-322 8 50-322 8 50-322 8	NIX, H C NIX, H, C, NIX, H C NIX, H, C NIX, H, C	8403150071 8403160031 8403160044 8403190026 8403260086	50-321 R 50-366 S 50-321 S 50-366 S 50-366 S	O'NEILL,J H. O'REILL,J,H, O'REILLY,J,P O'REILLY,J,P O'REILLY,J	8403220261 8403220261 8401240304 8403070067 8403070151	50-400 0 50-400 0 70-27 50-259 0 50-327 0
MUBELER, W. J.	8403270132	50-322 8	NIX,H C.	8403260119	30-366 B	O'REILLY, J. P	8403070156*	50-327 0
MUSOLF, D	8403010316	50-263 8	NIX,H,C	8403260191	50-366 B	O'REILLY, J. P	8403070279	50-280 0
MUSOLF, D,	8403020197	50-263 R	NIX,H C	8403300339	50-321 F	O'REILLY, J. P,	8403080051*	FOIA
MUSOLF, D,	8403060425	50-262 P	NOBLEB,L M.	8403260277	50-327 F	O'REILLY, J. P	8403080056*	FOIA
MUSOLF, D	8403120033	50-263 8	NOLAN,F J	7908010102*	50-509 A	O'REILLY, J. P.	8403080066*	FOIA
MUBOLF, D MUBOLF, D, MUBOLF, D MUBOLF, D, MUBOLF, D	8403120088 8403130365 8403170388 8403170377 8403200255	50-243 8 50-243 8 50-282 0 50-282 P 50-263 8	Norberg, J Norderhaug, L. Norderhaug, L. R. Norderhaug, L. R Norderhaug, L. R	8301040420* 8403120185* 8403040321* 8403040331*	FOIA 50-361	D'REILLY, J. P. O'REILLY, J P. O'REILLY, J P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P.	8403080074* 8403080121* 8403160105 8403160267 8403160273	FOIA FOIA 70-1113 50-261 0 50-259 0
MUSOLF, D.	8403220003	50-263 B	Norderhaug, L. R.	8403120184	50-361 0	D'REILLY, J P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P.	8403160325	70-143
MUSOLF, D	8403230051	50-282 P	Norderhaug, L. R.	8403170157	70-984		8403160377	70-143
MUSOLF, D	8403270049	50-263 P	Norderhaug, L. R.	8403170224	70-1257		8403290047	50-257 G
MUSOLF, D	8403270170	50-282 Q	Norderhaug, L. R.	8403170376	50-206 8		8403290097	50-250 G
MUSOLF, D	8403300087	50-263 R	Norel Jus, C. E.	8403010380	50-373 8		8403290181	50-335 F
MUSDLF, D,	8403300095	50-282 R	NORELIUS, C. E	8403050232#	FOIA	O'REILLY, J. P.	8403270170#	50-259 Q
MUTO, N, J	8403220302*	50-322 T	NORELIUS, C. E.	8403050235#	50-305 P	O'REILLY, J. P.	8403270274	50-280 Q
MYERS, D,	8403160385*	50-261 G	NORELIUS, C. E	8403050256#	50-255 Q	O'REILLY, J. P.	8403270315	50-250 G
MYERS, D, O	8403070310*	50-324 G	NORELIUS, C. E.	8403060250	50-374 P	O'REILLY, J. P.	8403300324	50-261 Q
MYERS, D, O,	8403270092*	50-324 G	NORELIUS, C. E.	8403080209#	FOIA	O'REILLY, J. P	8403300327#	50-261 Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY
0'TOOLE, J D 0'TOOLE, J D 0'TOOLE, J D 0'TOOLE, J D	8403020155 8403050015* 8403070075 8403070078* 8403070288	50-247 R 50-247 G 50-247 P 50-247 P 50-247 P 50-3 F	PALLADIND, N J	8403060061* 8403060065* 8403060071* 8403060074* 8403070053	COMMISSION COMMISSION COMMISSION COMMISSION 50-287 P	PARSONS, R M.	8403130237 8403130378 8403200203 8403270071 8403270166*	50-400 9 50-400 9 50-400 9 50-400 9 50-400 9
O'TOOLE, J. D O'TOOLE, J. D. O'TOOLE, J. D. O'TOOLE, J. D.	8403130405 8403150027 8403170067 8403170355 8403200124	50-247 8 50-247 0 50-3 F 50-247 F 50-247 P	PALLADINO; N J	8403070060* 8403070069* 8403070003* 8403070004* 8403070005*	50-289 U 50-289 U 50-289 U 50-289 U 50-289 U	PARSONS,R M PARSONS,R M PARTLOW,J G PARTLOW,J G PARTLOW,J G	840330034 840330043 8311460367* 8402030555* 8403010427	50-400 8 50-400 8 50-400 E MISC 50-423 0
O'TOOLE, J. D. O'TOOLE, J. D. O'TOOLE, J. D. O'TOOLE, J. D.	8403210154 8403230135 8403260120 8403270186 8403270193	50-247 S 50-3 R 50-3 R 50-247 R 50-247 P	PALLADINO, N J	8403090007* 8403090008* 8403090009* 8403090010* 8403120376	50-287 U 50-287 U 50-287 U COMMIBBION	Partlow. J G Pabciak. W Pabciak. W J Pabciak. W J Pabciak. W. J	8403130478 8403010366* 8403010314* 8403150078* 8403160248*	50-312 G 70-1100 50-352 G 50-272 G 50-352 G
O'TOOLE, J.D. O'TOOLE, J.D. O'TOOLE, J.D. O'TOOLE, J.D. OBERO, C.R.	8403270204 8403270170 8403270172 8403270268 8403060373*	50-247 S 50-247 P 50-247 Q 50-247 Q 50-445 Q	PALLADINO, N J PALMER, B	8403160032 8403200171 8403200178* 8403270087 8403270014	50-287 0 50-287 0 50-287 9 COMMISSION 50-327 A	PASCIAK, W J PASTVA, M. J PASTVA, M. J PASTVA, M. J PASTVA, M. J	8403270120* 8403010133 8403010202 8403130047 8403130152	50-387 0 50-325 8 50-325 8 50-325 8 50-324 8
DBERG, C. T. OBERLANDER, F. L. ODEGAARDEN, R. H. ODELL, W. H. DEBTMARN, M. J.	8403060210# 8403300132# 8403160164 8403260180 8403170313#	40-8830 50-498 A 71-9175 50-458 A 50-341 G	FALMER, B FALOMINO, F. Q. FANCIERA, V. FANCIERA, V. PANCIERA, V.	8403300070 8403230010 8403020235 8403070024* 8403170284	50-327 A 50-322 0 50-302 8 50-424 0 50-366 8	M, AVTBAP H, AVTBAP H, M, AVTBAP J, M, AVTBAP L, M, AVTBAP	8403130323 8403150035 8403170302 8403200273 8403210123	50-325 8 50-325 8 50-325 8 50-324 8 50-324 8
DESTMANN, M, J. DESTMANN, M. J DLIVEIRA, W. DLLER, R E DLLER, R E	8403300033# 8403300040# 8403270150# 8403130325# 8403270184#	50-456 Q 50-262 Q 50-352 Q GA999 QA999	PANCIERA, V. W. PANETTA, L. E PANO, J. F. PANO, J. F. PANGBURN, Q. C	8403270197* 8312280102* 8403200132 8403200224 8403200350	50-346	PASTVA,M.J PATEL,R B PATRICK,D P PATRICK,D P. PATRISBI,G A	8403270266 8403050100* 8403020132* 8403020219* 8402030344*	50-324 8 50-318 P FOIA FOIA 50-206 F
OLMBTEAD, W. J OLMBTEAD, W. J OLBON, D. L. OMAN, R. OMAN, R. G.	8403060095# 8403080225# 8403230245 8403120012# 8403120010#	FOIA FOIA WABTE MGT 50-275 0 50-275 0	PANGDURN, Q C PAOLINO, R. J. PAPAZOGLOU, I A. PAPERIELLO, C PAPERIELLO, C, J	8403200380 8403150034* 8403230133 8403230023 8003280778*	40-8102 50-388 0 50-313 P 50-255 9 FDIA	Patterbon, C. Patterbon, C Patterbon, J. Patterbon, R. Patterbon, W. F	8403170188* 8403270072* 8403200117* 8403120027* 8403140052	50-259 0 50-324 0 50-483 0 50-275 0 50-443 0
OPEKA, J. F. OPEKA, J. F. OPEKA, J. F. OPEKA, J. F. OPEKA, J. F.	8403010391 8403090137 8403090237 8403090257 8403090272	50-213 P 50-213 Q 50-336 P 50-336 P 50-336 P	PAPERIELLO, C J. PAPERIELLO, C, J. PAPERIELLO, C J PAPERIELLO, C J PAPERIELLO, C J	8403050004 8403050047 8403050072 8403050125 8403050142	50-237 F 50-346 0 50-254 0 50-305 F 50-454 F	PATTERBON, W. F PATTIBON, R 8 PAUL, R A PAULES, J PAULITZ, F	8403280355 8403150274 8403270242* 8403140088 8403070043*	50-155
OPEKAJJF OPEKAJJF. OPEKAJJF OPITZJBE OPREAJOW.	8403090272 8403120135 8403120135 8403070118 8403130328	50-334 P 50-245 R 50-245 R NUREO 50-498 8	PAPERIELLO, C J.	8403050305 8403130083 8403130101 8403130478 8403190309	50-315 0 40-3392 40-2041 50-331 F 50-341 0	PAULK, G L PAULSON, W A PAULSON, W A. PAULSON, W A.	8403160186* 8403010351 8403010368 8403080232 8403270166	50-259 Q 50-255 F 50-255 P 50-255 P 50-255 P
DPREA, 0 W ORBER, C. E. PADEN, R. C PAGE, M. PAGE, M.	8403130477 8403050081* 8403060135 8403010019 8403060300	50-478 B 50-458 A FUIA CONTRACT CONTRACT	PAPERIELLO, C. J.	8403200109 8403200111 8403200119* 8403200287 8403220050	50-409 F 50-403 0 50-403 0 50-243 0 50-243 0	PAULBON, W. A PAWLICKI, B B PAYNE, M T PAYNE, M T. PAYNE, M T	8403300064 8403270007* 8403120002 8403120002 8403120002	50~255 P FDIA 50~400 9 50~400 9 50~400 9
Page, H Page, H. Page, H Page, R. O.	8403070380 8403070411 8403070133 8403070138 8403010307	27-39 CONTRACT CONTRACT CONTRACT 40-8027	PAPERIELLO, C. J.	8403220093 8403220094 8403220134 8403270177 8403300026	50-246 0 50-454 0 50-305 0 50-461 0 50-456 0	PEACOR.D.H. PEAX.Q.J. PEARRING.J.R PEARSON.A. PEARSON.A	8403150031 8403020007 8403280257 8403020079 8403150158	50-205 F 50-316 R WASTE MOT XPORTLIC XPORTLIC
Page, R.O. Page, R.O Page, R.O. Page, R.O. Page, R.O.	8403070015 8403070107 8403070348 8403140215 8403200327	70-1201 70-824 40-8820 40-8027 40-2061	PAPERIELLO, C J. PAPERIELLO, C J. PAPERIELLO, C J. PARIB, O H. PARIB, O H	8403300036 8403300042 8403300047* 8403080110 8403070132	50-282	Pearson, R. Q. Pedersen, D. R.	8403090340 8403090340 8403160085 8403160085 8403140339	ACRS ACRS 50-400 d 50-400 u ACRS
PAGE, R. O. PAGE, R. O PAGE, R. G. PAGE, R. G. PAGE, R. G.	8403230241 8403230244* 8403260082 8403260141* 8403270273	70-1359 70-1359 70-1257 40-1478 70-36	PARIB: D. H PARIB: R D. PARK: J. E. PARKER: J PARKER: J	8403130394 8403090159 8403260286 8403010121 8403120148	50-424 0 PR NUREG 50-416 8 50-416 8	PEDERBEN, D. R PEDERBEN, R. L. PEDERBEN, R. L. PEDERBON, L, T PEDRO, J	8403140339 8403010186 8403070394 8403160131 8403010278	ACRS 50-247 50-247 GEN TEC IS FDIA
PAGE, R. G. PALLADING, N. J. PALLADING, N. J. PALLADING, N. J. PALLADING, N. J	8403300273 8402130353# 8402130370# 8402130373 8402130377#	70-1257 50-358 U 50-358 U 50-358 U 50-358 U	PARKER, J. PARKER, J. PARKER, J. PARKER, M E PARKINSON, T. F.	8403130464 8403170057 8403300118 8403220114* 8403170437	30-416 8 50-416 8 50-416 8 50-341 9 NUREG	PEDRO,J. PEDRO,J. PELLET,J. PELLET,J L. PELLET,J L.	8403020372 8403070078 8403280077* 8304270367 8305040147	50-287 FOTA 50-366 50-364 50-273
Palladino, N. J.	8402220291 8403050194 8403050196 8403050200 8403050204#	50-289 U 50-346 M COMMISSION COMMISSION COMMISSION	Parks, B Parr, G. D Parrish, B G Parry, G. M. Parsons, C. H	8403130035 8306220210* 8403230279 8403260253* 8403270314	50-387 S 50-440 A 50-424 Q 50-352 E 50-270 P	PELLETIER: JP PELLETIER: JP. PELLETIER: JP. PENN: J PENNIFILL: R	6403020322 8403020326# 8403020326# 8403130312# 8403200351	50-271 50-271 50-271 MISC WASTE MOT
PALLADINO, N. J.	8403050346 8403050348 8403050362 8403050377 8403060014	COMMISSION COMMISSION COMMISSION COMMISSION	PARSONS, R. M. PARSONS, R. M PARSONS, R. M PARSONS, R. M PARSONS, R. M.	8402270274 8403010350 8403010394 8403070095* 8403070096*	50-400 8 50-400 8 50-400 8 50-400 0 50-400 0	PENNIFILL,R. PERCH.R. PERCH.R L. PERCH.R L. PEREZ.O.P.	8403220193 8403010254 8403150232 8403150321 8403080279#	HABTE MOT 50-387 50-388 50-388
PALLADINO, N. J.	8403060018 8403060023# 8403060037# 8403060037# 8403060046#	COWNISSION COWNISSION COWNISSION COWNISSION	Parsons, R. M. Parsons, R. M. Parsons, R. M Parsons, R. M Parsons, R. M.	8403070184* 8403070285 8403070290 8403070082 8403120084	50-400 Q 50-400 S 50-400 S 50-400 S	PERLIS, R. O PERLIS, R. G. PERLIS, R. G PERLIS, R. G. PERLMAN, J.	8403140051 8403140134 8403190124 8403210194 8403010035	50-443 50-295 50-322 50-443 CONTRACT

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
Perlman, J	8403070371	CONTRACT	POLK, P J	8307270506#	50-286 P	POTERALSKI,D C	8403190179*	50-250 Q
Perlman, J	8403120306	CONTRACT	POLK, P J	8403020064	50-286 P	POTTER,A.	8403200373	XPORTLIC
Perlman, J	8403120340	CONTRACT	POLK, P J	8403020352	50-286 F	POULK,R M	8403010299	50-324 B
Perlman, J	8403240316	CONTRACT	POLK, P J,	8403050027#	50-286 P	POWELL,C	8403060569	XPORTLIC
Perry, P. A	8403190071	50-155 1	POLK, P J	8403050041	50-286 P	POWELL,C	8403060573*	XPORTLIC
PERBINXO, D PERSON, R T PETERB, M A PETERBON, L S PETERBON, M R	8403160158 8403270192 8403120095 8403300106 8402020431	50-244 P 50-267 I 50-373 S 50-344 R XPORTLIC	POLK, P. J. POLLACK, H. N. POLLARD, R. B. POLLARD, R. D. POMEROY, D. L.	8403050298 8403230131 8310200141 8403080354 8403290004*	50-286 P NUREQ FDIA FOIA 50-247 P	POWELL, C PRELL, J PRELL, J PRESLEY, K E	8403220328 8403010076* 8403020220* 8403270150* 8403120080	XPORTLIC FOIA 50-368 G 50-352 G 50-373 B
PETRICK, N A	8402070302 8403010270 8403010406 8403040298 8403130342	50-482 A 50-482 F 50-482 A 50-482 A 50-482 A	POOLE.D L POPPE.L K PORSE.L PORSE.L PORSE.L	8403010137* 8401120525 8403290007* 8403290011* 8403290020*	50-348 P Wagte mot Foia Foia Foia	PRESTON, J. PREVATTE, R L PRIGE, K W, PRINTZ, M PUDLICK, L	8403290113* 8403070199* 8403190295 8403060376* 8403120088	ACR9 50-400 G PR GA979 50-263 8
PETRICK, N A	8403200050 8403200187 8403200283 8403220019 8403220026	50-482 E 50-482 K 50-482 F 50-482 A 50-482 A	PORSE, L PORSE, L PORSE, L PORSE, L PORSE, L	8403270022# 8403270028# 8403270031# 8403270036* 8403270040*	FOIA FOIA FOIA FOIA	PULLANI, S PULLANI, S V PULLANI, B, V PURDOM, P W PURPLE, R A	B403160157# 8403220091# 8403290071# 8403200042 8403190077#	50-272 0 50-277 G 50-271 G 50-413 0 50-249 G
PETRICK, N A PETRICK, N A PETRICK, N A PETRILAK, R W PETRUNE, C.	8403220027	50-482 A	PORBE, L	8403270045*	50-266 P	PUTNAM, K. B	8403220017	50-331 R
	8403220184	50-482 A	PORBE, L	8403270063*	FDIA	PYRIH, L. B	8403160187*	50-352 9
	8403260282	50-482 A	PORTER, 8 W	8403230048	50-322 T	QUAMME, D. L	8403080245	50-327 8
	8403220297*	50-322 T	POTAPOVS, U.	84032310178	QAYYY	QUAMME, D. L	8403080248	50-327 A
	8403010390*	50-322 G	POTAPOVS, U.	8402010178	GAYYY	QUAMME, D. L	8403130168*	50-327 A
PETRONE, C	8403170285	50-322 \$ 50-322 0 50-322 6 40-4472 40-3453	POTAPOVS, U	8403010430*	50-423 G	GUAMME, D. L	8403130261	50-329 A
PETRONE, C	8403220160*		POTAPOVS, U	840305086	Ga777	GUAMME, D. L	8403190098	50-329 A
PETRONE, C	8403230074		POTAPOVS, U	840305089	Ga777	GUAMME, D. L	8403220007	50-329 A
PETTENGILL, H	8403230323		POTAPOVS, U	8403050126	Ga777	GUAMME, D. L,	8403230031	50-329 A
PETTENGILL, H. J	8403040465		POTAPOVS, U	8403050130	Ga777	QUAMME, D. L	8403230114	50-329 A
PETTENGILL, H J PETTENGILL, H J PETTENGILL, H J	8403170413	40-8084	POTAPOVS, U.	6403050174	QA777	GUAMME, D L	8403270199	50-329 Q
	8403170414	40-6622	POTAPOVS, U	8403040004	QA777	GUIRK, J F.	8403130285	TOPREP
	8403170431	40-2453	POTAPOVS, U.	8403040092	QA777	GUIRK, J F	840330008	TOPREP
	8403170443	40-2259	POTAPOVS, U.	8403040098*	QA777	RADER, R M	8403300129	50-352 Q
	8403200343	40-1162	POTAPOVS, U.	8403040157	QA777	RADER, R. M.	8403300129	50-352 Q
PETTENGILL, H J PETTENGILL, H J PETTENGILL, H J PETTENGILL, H J	8403200350	40-8452	POTAPOVS, U	8403060174	TDPREP	RADFORD, E, P	8403220305*	50~322 T
	8403200377	40-6659	POTAPOVS, U.	8403060217	GA979	RAFEEDIE, D. P	8403150071	50~321 R
	8403200380	40-8602	POTAPOVS, U.	8403060251	GA979	RAHE, E. P.	8403090201	PR
	8403200397	40-6622	POTAPOVS, U.	8403060282	GA979	RAHE, E. P	8403130358*	50~482 A
	8403200399	40-3453	POTAPOVS, U	8403060282	GA979	RAHE, E P	8403130375*	50~482 A
PETTENGILL, H J	8403220210	40-8602	POTAPOVS, U.	8403050348	GA979	RAHE, E P	8403130389*	50-482 A
PETTIJOHN, S L	8403280301*	Misc	POTAPOVS, U	8403050352*	GA979	RAHE, E P.	8403210015	TOPREP
PFAFF, B J	8403260242	40-6659	POTAPOVS, U	8403120035	GA979	RAINEY, J A.	8403200358	NUREO
PFEFFERLEN, H C	8403060409	Toprep	POTAPOVS, U	8403120108	GA979	RAJARAM, V	8403260350*	HASTE MOT
PHILDRICK, S S	8403160033	Acrs	POTAPOVS, U	8403130032	GA979	RAMAB. S. L	8403130479*	50-312 Q
PHILLIPS, H P PHILLIPS, H S PHILLIPS, J D PHILLIPS, M P	8403140053 8403170214* 8403170221* 8305040013* 8403200117*	ACRS Ga999 Ga999 Foia 50-483 Q	POTAPOVB, U POTAPOVB, U, POTAPOVB, U, POTAPOVB, U POTAPOVS, U	8403130046 8403130055 8403130068* 8403130089* 8403130268	(14797 (14797 (14797 (14797 (14797	RAPKIN, A RAPKIN, A RAPKIN, A, RAPKIN, A RAPKIN, A,	8403060124* 8403070030* 8403200083 8403200087* 8403300238	40~2061 40~2061 40~2061 40~2061 40~2061
PHILLIPS, M P PHILLIPS, M P. PIERCE, J W PIERCE, R L PIGOIT, D.	8403270180*	50-461 G	POTAPOVS, U	8403130276	04777	RATHSAM, R	9403270035	50-295 8
	8403300051*	50-315 G	POTAPOVS, U	8403130309	04777	RAVENBCROFT, N	8403280057	XPDRTLIC
	8403140012*	50-458 G	POTAPOVS, U	8403130317	04777	RAWSON, R J	8403140048	50-454 0
	8403020043*	50-10 P	POTAPOVS, U	8403130329*	04777	RAWSON, R, J	8403140081	50-322 0
	8403070126	50-445 G	POTAPOVS, U	8403130407	04777	RAWSON, R J,	8403140129	50-454 0
PIGOTT, D	840307012 <i>6</i>	50-445 Q	U , EVOPATOR	8403130441	Ga979	RAWSON: R. J	8403140146	50-454 0
PILANT, J M	8403050075*	50-278 Q	POPATOR	8403170041	Ga977	RAWSON: R. J	8403140148	50-454 0
PILANT, J M	8403060237	50-278 F	U , SVOPATOR	8403170046	Ga975	RAWSON: R. J	8403190124	50-322 0
PILANT, J, M	8403060264	50-278 F	U , EVOPATOR	8403170070	Ga979	RAWSON: R. J.	8403210024	50-287 0
PILANT, J, M	8403060346	50-278 F	U , EVOPATOR	8403170078	Ga979	READ: J. J.	8403060301*	50-322 T
PILANT, J M	8403040354	50~298 F	POTAPOVS, U	8403190112	Ga999	REAVIS, J. A	8402210150	50~349 R
PILANT, J M	8403040392	50~298 G	POTAPOVS, U	8403190145	Ga999	REAVIS, J. A	8403200010	50~249 R
PILANT, J M	8403080265	50~298 F	POTAPOVS, U	8403190183	Ga999	REAVIS, T A.	8403200123	50~349 R
PILANT, J M	8403150168	50~298 P	POTAPOVS, U	8403190206	Ga999	REBELLO, J. E	8403020073*	CONTRACT
PILANT, J M	8403140260*	50~298 Q	POTAPOVS, U	8403190209	Ga999	REBELLO, J. E	8403220217*	CONTRACT
PILANTIJ M PILANTIJ M PILANTIJ M PILANTIJ M	8403170087 8403200167 8403200254 8403220042* 8403220055	50~298 F 50~298 F 50~298 P 50~298 Q 50~298 F	POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	84031 70218 84031 70254 84031 70328 84031 70327 84031 70337	GA999 GA979 GA999 50-461 G GA999	REBELLO, J E REBELLO, J E REBELLO, J, E REBELLO, J, E, REBELLO, J E,	8403220280* 8403220312* 8403220317* 8403220327* 8403230052*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
PILANT.J M	8403270013	50-298 F	POTAPOVS: U.	8403190338	GA999	REBELLO, J E.	8403230154*	CONTRACT
PIRTLE.O L	8403170239*	50-331 0	POTAPOVS: U	8403190342	GA999	REBELLO, J, E.	8403260307*	CONTRACT
PIRTLE.O L	8403260023*	50-346 0	POTAPOVS: U,	8403190364	GA999	REBELLO, J, E.	8403260356*	CONTRACT
PLAINE.H H.	8403200205*	30-289 0	POTAPOVS: U	8403190380	GA999	REBELLO, J. E.	8403260370*	CONTRACT
PLATO.E D	8403070226	50-329 8	POTAPOVS: U	8403200072	GA999	REBELLO, J E.	8403270284*	CONTRACT
PLATO, P	8403140151	PR	POTAPOVS, U	8403200138	(14999	REBELLO, J, E	8403270306*	CONTRACT
PLIML, Q	8403140082	50-295 F	POTAPOVS, U	8403200142*	(14999	REBELLO, J E,	8403280187*	CONTRACT
PLIML, Q	8403210089	50-295 F	POTAPOVS, U,	8403260052	(14999	REECE, W, D,	8403190449	NUREQ
PLIML, Q	8403230124	50-295 F	POTAPOVS, U	8403270050	(14999	REED, C,	8403060394	50-454 A
PLIML, Q	8403280119	50-295 F	POTAPOVS, U,	8403270092	(14999	REED, C,	8403130359*	50-373 G
PLISCO, L.	8403150060*	50-367 G	PDTAPDVS, U	8403270142	GA999	REED, C.	8403260194	50-374 A
PLISCO, L.	8403290155*	50-367 G	POTAPDVS, U	8403270148	GA999	REED, J. A.	8403290049*	50-266 P
PLOSKI, T	8403200119*	50-463 G	POTAPDVS, U	8403270174	GA999	REED, J. D	8403210009	PR
POIDHURST, B. W	8403270094*	40-6760	POTAPDVS, U	8403270178	GA999	REED, L. Q.	8403200104	50-456 D
POLICH, T.	8403060146*	50-275 Q	POTAPDVS, U,	8403270228	GA999	REED, L. L.	8403150072	50-73 R

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
reeveb, e	8403010210	50-348 P	RILEY, J	8403070033	50-413	ROSA, F	8403170122*	50-275 G
reeveb, e	8403020440	50-348 P	RILEY, J L	8403070037*		ROSANO, R	8403080213	50-259 G
reeveb, e	8403070359	50-348 P	RILEY, J L	8403220237		ROSANO, R	8403160051	50-331 S
reeveb, e	8401120594	50-348 P	RING, M	8403300030*		ROSENTHAL, A S	8402230237*	50-400 G
reeveb, e a	8403070379	50-348 P	RITBHER, J A	8403150080		ROSS, D F	8103050718*	FOIA
REEVES, E. A	8403260326	50-34B P	RITBHER, J A	8403150080	50-443 A	ROSS, T. M	8403040149*	50-275 Q
REGAN, W H	8203100370*	50-397 C	RIVENBARK, G	8403010110	50-321 P	ROSS, W J	8104220881*	50-286 P
REGAN, W H	8403080278	50-413 M	RIVENBARK, G	8403060436	50-321 P	ROSS, W J	8403160120*	50-369 Q
REGAN, W H	8403080283*	50-413 M	RIVENBARK, G W	8401120456	50-321 P	ROSSBACH, L W	8403150164*	50-286 Q
REGAN, W H	8403220271	50-458 M	RIVKIN, W B.	7704030132*	FOIA	ROSSI, A R	8403220272*	50-322 T
REGAN,W H REGENBBURG,K J REGENBBURG,K J REGENBBURG,K J REGENBBURG,K J	8403280161	50-458 M	Rivkin.W B	7904030135*	FDIA	ROSZTOCZY, Z R	8403270041*	FDIA
	8403060266*	50-322 T	Roach, P. A	8403160038	50-251 8	ROTELLA, T S	8403220070	50-335 S
	8403060270*	50-322 T	Roach, P. A.	8403160038	50-250 8	ROTH, W V	8403150341*	50-272 U
	8403060278*	50-322 T	Robbins, J. G	8403140003	50-322 J	ROTHSCHILD, M U	8403080352*	50-336 P
	8403060487	COMMISSION	Robbins, J. G	8403140037	50-413 J	ROUSE, L C	8403020231	70-687
REICH,M.	8403010227*	50-329 A	ROBERTO, R C	8403260170	TOPREP	RDUGE, L C	8403290332	70-487
REICHEL,N I	8403130354	50-329 8		8403140170*	PR	ROWE, C	8403070283	50-293 S
REICHEL,N I	8403130362	50-329 8		8403270110	ACRE	ROWE, C	8403080166#	FOIA
REICHEL,N I	8403130491	50-329 8		8403230057	NUREO	ROWE, C	8403210040	I&E
REIS,E.J.	8403270295	50-322 0		8403040289*	50-322 T	ROWBOME, F	8311140250*	ACRS
REIB, E J	8403280356	50-322 0	ROBERTS,R C	8403040275*	50-322 T	ROWBOME, F	8312170358*	ACRB
REIB, J. B	8403200032	50-373 S	ROBERTS,R C	8403040301*	50-322 T	ROWBOME, F	8403010065*	ACRB
REIB, J. B.	8403280023	50-374 S	ROBERTS,R C	8403040317*	50-322 T	ROWBOME, F H	8311140248*	ACRB
REIB, J. B.	8403280073	50-374 S	ROBERTS,R G	8403280178	50-348 F	ROY, W	8403260148*	40-1478
RENZ, W. F	8403070165*	50-322 T	ROBERTSON,J A	8403020305*	50-54 Q	ROZAK, B	8403300040*	50-282 G
RENZ, W F.	8403070178*	50-322 T	ROBINSON, E D	8403070140*	50-322 T	ROZEAR, C. J	8403130208	50-257 8
RENZ, W F	8403070170*	50-322 T	ROBINSON, E D	8403070195*	50-322 T	ROZEAR, C. J.	8403170125	50-257 8
RENZ, W. F.	8403070222*	50-322 T	ROBINSON, E D	8403070204*	50-322 T	ROZEAR, C. J	8403220046	50-257 9
REPKA, D. A	8403140042	50-322 G	ROBINSON, E. D	8403070207*	50-322 T	RUBENSTEIN, L. S	8103040048*	50-286 P
REPKA, D. A	8403140045	50-322 T	ROBINSON, E D	8403070211*	50-322 T	RUBENSTEIN, L. S	8211070035*	50-400 E
REPKA, D. A. REPKA, D. A. REPKA, D. A. REPKA, D. A. REPKA, D. A.	8403140165 8403190092 8403190124 8403210100 8403210104	20-355 6 20-355 6 20-355 6 20-355 6 20-355 6	ROBINBON, E D ROBINBON, E D ROBINBON, E D ROBINBON, E D, ROCCO, J.	8403070214* 8403070227* 8403230020 8403230038 8403060395	50-322 T 50-322 T 50-322 T 50-322 T 50-206 J	RUBENSTEIN, L S RUBENSTEIN, L S RUBENSTEIN, L S RUBENSTEIN, L S	8211170249* 8305110054* 8309210098* 8309210116* 8309260482*	50-400 E 50-289 P 50-400 E 50-400 E
REQUA, Q REQUA, Q. REQUA, Q RESH, D L REVELEY, W. T	8403010230 8403060005 8403060470 8403130236 8403130129	50-261 P 50-261 P PR 50-322 G	ROCKHOLD, H C ROCKHOLD, H, C RODRIQUEZ, R J, RODRIQUEZ, R J RODRIQUEZ, R J	8403070395* 8403240335 8403010388 8403020350 8403060387	50-315 P 50-416 P 50-312 P 50-312 P 50-312 F	RUBENSTEIN, L 8 RUBENSTEIN, L 8 RUBIN, A RUBIN, S RUBIN, S D	8311110263* 8312120002* 8403200267* 8310280188* 8310280186	50-400 E 50-400 E 50-482 A 50-298 B 50-298 S
REVELEY, W T REVELEY, W T. REVELEY, W T REYES, L. A. REYES, L. A	8403130129 8403210181* 8403210181* 8403080241* 8403170297*	50-322 0 50-322 0 50-322 0 50-483 0 50-373 0	RODRIGUEZ,R J RODRIGUEZ,R J RODRIGUEZ,R J RODRIGUEZ,R J	8403130112 8403130125 8403170275 8403200045 8403200184	50-312 8 50-312 P 50-312 0 50-312 R 50-312 8	RUBIN, 8 D RUBIN, 8 D RUFF, A B RUGH, C F RUITER, 8 H	8403230178 8403230181* 8403080384* 8403300317 8403130147	50-305 S 50-305 S 50-424 G NUREO 50-305 R
REYEB, LA.	8403300030*	50-454 G	RODRIGUEZ,R J	8403230054	50-312 8	RULAND, W H	8403160284*	50-348 G
REYEB, LA.	8403300057*	50-341 G	RODRIGUEZ,R J	8403240215	50-312 P	RULAND, W H	8403290103*	50-348 G
REYNOLDB, J.	8403090027	50-275 P	ROGERO,A C	8403140048	50-528 A	RULLMAN, B D	8403080113*	POIA
REYNOLDB, JR	8403070128	50-275 G	ROGERO,L.	8403290004*	FOIA	RULLMAN, B D	8403080113*	FOIA
REYNOLDB, JR	8403070128	50-275 G	ROGERO,L,	8403290014*	FOIA	RUMMERFIELD, F	8403090178	PR
BEANOIDB' ? B BEANOIDB' ?' B BEANOIDB' ?' B BEANOIDB' ? B BEANOIDB' ?' B	8403080118 8403080118 8403170011 8403170011 8403170014#	50-275	ROGERS, L. ROGERS, L. ROGERS, L. ROGERS, L. ROGERS, L	8403270051* 8403270054* 8403270058* 8403270061* 8403270073*	FOIA FOIA FOIA FOIA	RUMMERFIELD, P RUNKLE, J RUNKLE, J RUNKLE, J D RUPP, J.	8403090183* 8403200054 8403220223 8403190141* 8403080013	PR 50-400 9 50-400 0 50-400 9 50-272 8
REYNOLDS, J. R. REYNOLDS, J. R. REYNOLDS, J. R. REYNOLDS, J. R.	8403190016* 8403220106 8403220106 8403220110* 8403220110*	50-275 0 50-275 0 50-275 0 50-275 0 50-275 0	Rogers, P Rogers, P Rogers, P Rogers, P Rogers, P	8403070139 8403130024 8403130324 8403130347 8403220020	50-368 8 50-368 8 50-368 8 50-368 8 50-368 6	RUPP, J RUPP, J RUPP, J L RUPP, J L, RUPP, J L	8403080245 8403080252 8402100176 8403130384 8403220037	50-272 8 50-272 8 50-272 8 50-311 8 50-311 8
REYNOLDB, J. R	8403260368	50-275 G	ROGER BIF	8403270258	50-3AB S	RUPP, J L	8403220151	50-311 S
REYNOLDB, J. R	8403260368	50-275 G	ROGER BIF	8403270127	50-3AB B	RUPP, J L	8403270099	50-311 B
REYNOLDB, N. S	8403120007	50-508 D	ROGGE, J. F	8403020235	50-3AB B	RUPP, J, L	8403270244	50-272 B
REYNOLDB, N. S	8403120007	50-508 D	ROGGE, J F	8403160037	50-3AA B	RUSHMORF, J W	8403280036	50-220 J
REYNOLDB, N. S,	8403140020	50-445 G	ROHRER, D.	8403200117*	50-4A3 Q	RUSHMORE, J W	8403280047	50-220 J
REYNOLDS, N. S REYNOLDS, N. S REYNOLDS, N. S REYNOLDS, N. S REYNOLDS, N. S.	8403140020 8403150032 8403150032 8403270031 8403270031	50-445 Q 50-445 Q 50-445 Q 50-445 Q 50-445 Q	ROLFE, R M. ROLFE, R. M ROLFE, R. M. ROLFE, R M ROLFE, R M	8403020143 8403020143 8403060105 8403060105 8403060107*	50-322 0 50-322 0 50-322 0 50-322 0	RUSBELL.L B RUSBELL.L B RUSBELL.L B RUSBELL.L B RUSBELL.L B	8403020300 8403060109 8403130039 8403130081 8403130098	50-317 F 50-318 S 50-318 S 50-318 S 50-317 S
REYNOLDB, B D	8403150034*	50-388 G	ROLFE,R M	8403040107*	50-322 0	RUBBELL,L B	8403130252	50-317 S
REYNOLDB, B. D.	8403170110*	50-275 O	ROLFE,R,M	8403270074	50-322 0	RUBBELL,L B	8403130279	50-317 S
REYTBLATT, Z	8403270280	MISC	ROMAN,T W	8403130391*	50-220 P	RUBBELL,L B,	8403130275	50-317 S
RHODE, Q. K.	8403070078	50-410 B	ROMAN,T W	8403130051	50-220 R	RUBBELL,L B	8403130279	50-317 S
RHODEB, M.	8403010513*	40-8027	ROMANO,F.	8403220234*	50-352 0	RUBBELL,L B	8403130356	50-317 S
RHODES, R. K. RIGE, T. R. RICHARD, A W. RICHARDS, B. L. RICHARDS, S. A.	8403120029# 8403050029# 8403050124 8403160353# 8403060344#	50-275 Q 50-284 P 50-285 8 70-143 50-344 Q	ROMANO, F. R ROMANO, F. R ROMANO, F. R. ROMANO, F. R ROMANO, F. R	8403220226 8403220229* 8403270375 8403270375	50-352 0 50-352 0 50-352 0 50-352 0	RUSSELL.L B. RUSSELL.L B RUSSELL.L B RUSSELL.L B RUSSELL.L B	8403130413 8403130426 8403130430 8403140228 8403300100	50-318 8 50-317 8 50-318 8 50-317 F 50-317 8
RICHLEY, E. A	8403060405	50-30 R	RONK, D F.	8403270236	50-327 B	RUSBELL, W	8309290474*	50-400 E
RIDEOUT, T B.	8403230200	NUREO	ROOD, H	8403270370	50-341 P	RUTBERG, J	8403140071	50-275 G
RIDGWAY, K R	8403170096*	50-123 G	ROONEY, V L	8403260093	TOPREP	RUTBERG, J	8403140179	50-275 G
RILEY, A.	8403010437*	CONTRACT	ROPBON, D J	8402170107*	50-305 P	RUTBERG, J	8403190100	50-275 G
RILEY, J.	8403070033	50-413 O	ROBA, F	8402160020*	MISC	RUTBERG, J	8403270301	50-352 G

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
UZICKA, W. G YAN, J. A YAN, J. F YBAK, B. YBAK, B	8403130045 8403080385 8403230140* 8403010089 8403040273	50-54 P 50-528 D CONTRACT 50-254 P 50-254 P	SCHNELL, D F BCHNELL, D F BCHNELL, D F BCHNELL, D F BCHNELL, D F BCHROEDER, B	8403270079 8403270182 8403270187 8403270229 8403230094	50-483 9 50-483 9 50-483 8 50-483 A 50-237 9	SCOTT, D. J SCOTT, D. J SCOTT, P. S SCOTT, P. S SCOTT, P. S	8403270036 8403270089 8403080197 8301140490# 8301140494#	50-237 8 50-237 8 50-10 R 50-267 P 50-267 P
YBAK. B	8403090185	50-237 P	SCHROEDER, B. A	8403130015	50-237 R	BCDWN, K	8403060146#	50-275 Q
YBAK. B	8403090191*	50-237 P	SCHROEDER, C. W	8403050063	50-373 F	BCRABIB, C M	8403190261#	50-349 P
YBAK. B	8403130070	50-237 P	SCHROEDER, C. W	8403140175	50-373 F	BEARB, C. F	8403070273	50-423 C
YBAK. B	8403130102	50-245 P	SCHROEDER, C. W	8403140001	50-247 Q	BEARB, C F	8403070273	50-423 C
YBAK. B,	8403130353	50-254 P	SCHROEDER, C. W	8403200013	50-373 P	BEARB, C F	8403070336#	50-423 Q
үвак, в	8403130370	50-249 G	SCHROEDER, C W	8403200256	50-373 Q	Bearb, C f	8403070336#	50-423 G
үвак, в	8403130400	50-237 P	SCHROEDER, C W	8403210085	50-373 K	Searb, C. F	8403130027	50-213 P
үвак, в	8403130410	50-237 P	SCHROEDER, C W	8403220123	50-373 F	Searb, C f	8403130027	50-213 P
үвак, в	8403190075	50-254 G	SCHROEDER, C W	8403230081*	50-373 Q	Searb, C f	8403130027	50-213 P
үвак, в	8403200196	50-249 G	SCHROEDER, C W	8403230087*	50-373 Q	Searb, C. F	8403130213	50-423 S
ybak, B	8403220120	50-10 R	SCHROEDER, C W	8403260122	50-373 P	Searb, C. F.	8403130283	50-213 R
ybak, B.	8403220133	50-237 P	BCHROEDER, C W	8403260225	50-373 Q	Searb, C. F.	8403140014	50-213 P
ybak, B	8403270130	50-249 P	BCHULTZ, G R	8403140180*	50-373 F	Searb, C. F.	8403160292	50-423 E
ybak, B	8403270175	50-254 Q	BCHULTZ, G R	8403140183*	50-373 F	Searb, C. F.	8403160292	50-423 E
taegert, 8	8403050314*	50-322 T	BCHULTZ, G R	8403140184*	50-373 F	Searb, C. F.	8403210011	50-423 G
IAEGERT, S	8403050314*	50-322 T	BCHULTZ, W H	8005010203#	FOIA	Bearb, C. F.	8403210011	50-423 9
IAENGER, E. L.	8403080217*	FDIA	BCHULTZ, W H	8102240046*	FOIA	Bearb, C. F.	8403210161	50-423 F
IAGER, D. A.	8403050340	50-335 F	SCHULZ, R D	8403080186*	50-461 G	Bearb, C. F	8403220148	50-423 F
ALAH, S.	8305050337	50-324 B	BCHUMACHER, M C	8403130117*	40-2061	Bearb, C. F	8403220148	50-423 F
ALAH, S.	8403230148	50-416 B	BCHUMACHER, M C	8403190313*	50-341 G	Bearb, C. F.	8403230022	50-213 R
ALAH: S.	8403230150*	50-416 8	BCHUMACHER, M C	8403220140*	50-305 Q	Bearb, C F	8403230022	50-213 R
ALAH: S	8403260411	50-325 8	SGHUMACHER, M. C.	8403300033*	50-456 Q	Bearb, C. F.	8403230029	50-245 F
TALOHON: S. N	8403230190	NUREO	BCHUMACHER, M C	8403300040*	50-282 Q	Bearb, C. F	8403230029	50-245 F
ALTZMAN: J.	8403280221	50-320 P	BCHUBTER, M D	8403080152*	50-328 Q	Searb, C F	8403230033	50-423 Q
ALVATORI: R	8403290059*	FOIA	BCHUBTER, M D	8403130381	50-344 F	Bearb, C F.	8403230033	50-423 Q
ALVEBEN, R. S	8403140007	50-354 A	SCHUSTER, M D	B403290240	30-344 F	Searb, C. F.	8403230134	50-213 0
TALYARDS: L. E	8403130356	50-317 S	SCHUSTER, M D	B403290264	50-275 F	Searb, C. F	8403240143	50-213 F
ALYERS: E. M	8403060397	50-280 F	SCHUYLER, J, D,	B403140144	PR	Searb, C. F.	8403240143	50-213 F
ALYERS: E. M.	8403090131	50-280 F	SCHUYLER, J, D,	B403070075	50-275 P	Searb, C. F.	8403240144	50-213 F
ALYERS: E. M	8403230146	50-280 F	SCHUYLER, J, D	B403070079*	50-275 P	Searb, C. F.	8403240144	50-213 F
ALZMAN, L.	8403290272	PRM	SCHYLER, J. D. BCHYLER, J. D. BCHYLER, J. D. BCHYLER, J. D. BCHYLER, J. D.	8403070284	50-275 P	Bearb, C. F.	8403260149	50-423 E
AMANTA, P. K	8403010041#	FDIA		8403070288*	50-275 P	Bearb, C. F.	8403260149	50-423 E
MAMPLE, M.	8403140231	50-369 F		8403070355	50-275 F	Bearb, C. F.	8403260195	50-245 F
MAMPORTH, R. B	8003270142#	50-397 D		8403080413	50-275 P	Bearb, C. F.	8403260195	50-245 F
MANDERS, W. (*	8403070024#	50-424 G		8403080414*	50-275 P	Bearb, C. F.	8403270008	50-213 F
ANDERS, W. F TANDGUIST, G ANDGUIST, G M ANDGUIST, G M TANE, A D	8403080384* 8403140145 8403200281 8403200293* 8403190404*	50-424 G 50-407 F 50-72 F 50-72 F 50-413 A	SCHUYLER, J. D SCHUYLER, J. D SCHUYLER, J. D. SCHUYLER, J. D.	8403090172 8403120129 8403140153 8403150011 8403150013	50-275 F 50-275 P PR 50-275 P 50-277 P	Searb, C. F. Searb, C. F. Searb, C. F. Bedlack, M. S Seegal, J. L.	8403270008 8403270068 8403300166* 8403070277* 8403020056	50-213 F 50-213 F 50-213 G 50-331 P FDIA
ARSOUR, B.	8403020078	50-344 R	SCHUYLER, J O	8403150048	50-323 S	Beegal, J L	8403020062	FOIA
ARSOUR, B.	8403070251	50-346 R	SCHUYLER, J O	8403150062	50-275 Q	Beigerman, V. K.	8403010170	50-247 H
ARSOUR, B.	8403300184	50-346 R	SCHUYLER, J O	8403150147	50-275 E	Beiken, B J	8403010213	50-482 Q
AUTER, D M	8403050120	GA999	SCHUYLER, J O	8403200218	50-275 P	Seiken, B. J.	8403270128	50-482 G
AUTER, D M	8403060096*	GA999	SCHUYLER, J, O	8403220035	50-275 P	Belby, D. L.	8403300306	NUREG
AUTER, D. M. BAVIGNAC, N. AVINI, R. J. BCALETTI, D. BCARAND, R. A.	8403040101*	GA977	8CHUYLER, J. O	8403220172	50-275 E	Selby, J D.	8403190071	50-155 I
	8401120180*	40-3453	8CHUYLER, J. O	8403230191	50-275 0	Sellb, D. E.	8003250477*	50-397 D
	8403080218*	FOIA	8CHUYLER, J. O	8403260176	50-275 P	Sellb, D. E.	8403060077	50-395 P
	8403300214	50-447 A	8CHUYLER, J. O	8403270004	50-133 G	Semmler, R. W.	8403270054*	GA999
	8403270214	70-1257	8CHUYLER, J. O	8403270003	50-133 G	Serne, R. J	8403070118	NUREO
SCHEIDT, D. J	8403280358	50-322 0	BCHUYLER, J. O	8403270033	50-275 P	SERNE, R. J.	8409230177	NUREO
SCHEIDT, D. J	8403280358	50-322 0	BCHUYLER, J. O	8403270205	50-133 F	SEWELL, H M	8409230130*	CONTRACT
SCHEINERT, R. L	8403060285	50-263 F	BCHUYLER, J. O	8403280001	50-275 F	SEYFRIT, K V	8310060317*	50-285 Q
ICHERER, A. E	8403010276	50-470 E	BCHUYLER, J. O	8403280114	50-275 F	SHA, W. T.	8403300261	NUREO
ICHERER, A. E.	8403200081	50-470 K	BCHUYLER, J. O	8403300078	50-275 E	SHA, W T	8403300285	NUREO
ICHERER, A. E	8403270107	50-470 E	BCHUYLER, J. O	8403300148	50-275 E	Shackelford, 8	8403280051	50-133 I
ICHTERLING, H	8403170134*	50-275 Q	BCHWYLER, J. P.	8403150004	50-275 Q	Shade, J. U.	8403230177	NUREQ
ICHTEFHACHER, W	8403070165*	50-322 T	BCHWAR, C. A	8403190374	50-206 E	Shafer, J. C	8403120117	GA999
ICHTEFHACHER, W	8403070190*	50-322 T	BCHWARTZ, A R	8403010132*	50-498 Q	Shafer, J. M.	8403300132*	50-498 A
ICHTEFHACHER, W	8403070222*	50-322 T	BCHWENCER, A.	7912050523*	50-286 D	Shafer, N.	8403130379	50-266 B
SCHMIDT,H C,	8403060299	50-445 A	SCHWENCER, A	840301013&	30-416 P	SHAFER, W.	8403080233	50-263 8
SCHMIDT,H C	8403150103	50-445 E	BCHWENCER, A.	8403010143*	50-416 P	SHAFER, W.	8403130235	50-254 8
SCHMIDT,W,J	8403190139	GA999	BCHWENCER, A.	8403020207	50-373 F	SHAFER, W.	8403130423	50-263 8
SCHMITT,H,W	8403300312*	CONTRACT	BCHWENCER, A.	8403050034*	50-286 D	SHAFER, W.	8403170013	50-374 8
SCHMITT,R,C	8403300261	NUREQ	BCHWENCER, A.	8403050370	50-410 A	SHAFER, W. D.	8403120124*	50-315 0
SCHMITT.R.C	8403300285	NUREO	Schwencer, a	8403070350	50-458 A	SHAFER: W D.	8403120134	50-237 Q
BCHNEBELEN,A.	8403280235*	50-482 Q	Schwencer, a	8403140296	50-387 F	SHAFER: W D	8403120141	50-243 Q
BCHNELL,D.F	8403050016	50-483 K	Schwencer, a	8403150262	50-352 A	SHAFER: W. D.	8403130002	50-244 Q
BCHNELL,D.F	8403090283	50-483 F	Schwencer, a	8403220301	50-410 E	SHAFER: W. D.	8403130011#	50-246 Q
BCHNELL,D.F,	8403120104	50-483 A	Schwencer, a.	8403220308	50-354 E	SHAFER: W. D.	8403130326	50-409 Q
SCHNELL, D. F	8403120171	50-483 A	BCHWENCER, A.	8403270314	50-410 E	SHAFER, W. D.	8403190020	50-282 0
BCHNELL, D. F	8403120182	50-483 A	SCHWENCER, A.	8403280236	50-410 E	SHAFER, W. D.	8403190068	50-373 0
IGHNELL, D. F	8403160323	50-483 A	SCHWENCER, A.	8403300244	50-373 F	SHAFER, W. D.	8403190072*	50-373 0
BCHNELL, D. F	8403170034	50-483 B	SCOTT, A. E	8403080135	50-261 R	SHAFER, W. D.	8403190084	50-373 0
SCHNELL, D. F.	8403170269	50-483 A	SCOTT, A. E	8403080258	50-261 R	SHAFER, W. D.	8403190379	50-305 0
SCHNELL, D. F. SCHNELL, D. F SCHNELL, D. F SCHNELL, D. F. SCHNELL, D. F.	8403200028 8403200285* 8403210121 8403230115 8403270016	50-483 9 50-483 0 50-483 A 50-483 5 50-483 A	9011, D, J, 9011, D, J, 9011, D, J, 9011, D, J,	8403060099 8403130015 8403230096 8403260223 8403260260	50-10 R 50-237 R 50-237 B 50-237 B 50-237 S	SHAFER, W. D. SHAFFNER, J. A. SHAFFNER, J. A. SHAFFNER, J. A. SHAFFNER, J. A. SHAH, V. L.	8403220161 8403160077 8403160094 8403220235 8403300261	50-295 0 27-39 27-48 27-48 NURES

AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
Shah, V L Shahabian, R L Shanahan, J A, Shanbaky, M Shanbaky, M	8403300285 8403010303* 8403160076* 8403130208 8403130456	NUREO 50-388 E 50-412 A 50-219 8 50-309 S	SHOLLY, S C SHOLLY, S C SHOLLY, S C SHOLLY, S C	8403010010 8403010021 8403050017 8403050058 8403080003	50-289 P F01A 50-286 P F01A F01A	SMITH.P SMITH.P A SMITH.P A SMITH.P. A SMITH.P. A	8403260341* 8403270270* 8403270368* 8403280052* 8403300312*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
EHANBAKY, M,	8403150017*	50-219 Q	SHON, FJ	8403050111	30-50B	SMITH, R. D	8403070367	40-3453
BHANBAKY, M M	8403070306*	50-387 Q	SHON, FJ	8403080110		SMITH, R. D	8403190414	40-4492
BHANDAKY, M M	8403270210*	50-272 Q	SHON, FJ	8403090132		SMITH, R. D	8403200328*	40-4492
BHANCEY, R E	8403130028	50-289 H	SHOPENN, N M	8403130401		SMITH, R. D	8403200333	40-1341
BHANKB, R B	8403080383*	FOIA	SHORTRIDGE, E W	8403070265		SMITH, R. D	8403200389	40-8681
BHANNON, J B	8402140327#	40-8102	SHULMAN, M N SHUBTERMAN, A SHUBTERMAN, A	8403270115	GA999	SMITH, R D	8403230156	40-8745
BHANNON, J B	8403260142#	40-8102		8403070167*	CONTRACT	SMITH, R D	8403280127	40-8768
BHANNON, T E	8403270048#	50-352 T		8403050081*	50-458 A	SMITH, R H	8403080087*	FDIA
BHARPE, C	8403260005	50-275 Q		8403120017*	50-275 G	SMITH, R H	8403210105*	50-334 (
BHARPE, C	8403260375	50-275 Q		8403160222*	50-390 G	SMITH, W F	8403050186*	50-482 (
SHARPE, C	8403260378	50-275 G	SIEBER, J D	8403200233	50-334 F	SMITH.W F	8403130453*	50-445 (
SHAUB, T	8403020399*	50-293 G	SIEGEL, A I	8403300325	NUREQ	SMITH.W C	8403020044	50-315 n
SHEA, J, J,	8403090240	50-220 P	SIEGEL, B	8403090240	50-220 P	SMITH.W C	8403130257	50-315 n
SHEA, J J	8403190045	50-245 G	SIEGEL, B L	8403140340	50-219 P	SMITH.W C	8403200217	50-316
SHEA, J J,	8403190383	50-245 P	BILBERG, J E	8403020104	50-440 Q	SMITH.W C	8403200283	50-315
SHEA, K H	840326062	50-331 J	SILBERO, J E	8403020106	50-440 G	SMITH, W C	8403300155	50-316
BHEALY, H G	8403020339*	WARTE MOT	SILBERO, J E	8403190035	50-482 G	SMITH, W C	8403300157	
SHEARIN, R V,	8403060240	50-413 9	SILBERG, J F	8403190035	50-482 G	SMITH, W M	8403130121	
SHEARIN, R V,	8403130164*	50-400 9	SILBERG, J E	8403260325	50-482 G	SMOLEN, H	8403010271	
SHEARIN, R, V	8403270011	50-413 9	SILBERO, J, E	8403260325	50-482 G	SMOLEN, H	8403010275#	
SHEDLOSKY, T SHELLEY, W. J SHELLEY, W. J SHEPHERD, R	8403220140* 8403150332 8403280028 8403280103* 8403080146*	50322	Bilberstein, E Silver, H. Binclair, J B Binclair, J B	8403290259 8403300303 8403130310 8403120003 8403130481	PRM 50-289 F I&E 50-271 P 50-271 R	EMOLEN, H SMYTH, C W SNELL, W C. SNELL, W O. SNIEZEK, J.	8403040127 8403200048 8403270180* 8403300011* 8403010222*	50-352 ğ 50-289 R 50-461 Q 50-315 Q FOIA
SHEPPARD, J J	8403070106*	FOIA	Sinclair. J B	8403230140	50-271	BNIEZEK, J H	8103250553*	FOIA
SHEPPARD, J J,	8403070106*	FOIA	Binclair. J B	8403230140		BNIEZEK, J H	8107180034*	FOIA
SHEPPARD, J J	8403070108*	FOIA	Binclair. J R	8403280240*		BNIEZEK, J H	8403170244	REVIEW GRP
SHEPPARD, J J	8403070108*	FOIA	Bincer, B.	8403020075*		SNOW, B A	8403020202	50-244 R
SHEPPARD, J, J,	8403240024	TOPREP	Sincer, B.	8403020107*		BNOW, B, A	8403300081	50-244 R
SHEPPARD, J SHERMAN, C I SHERMAN, C I SHERR, T S SHERR, T S	8403260024 8403060017* 8403060172* 8403280205 8403290328	TOPREP 50-204 @ 50-113 @ 50-2 F 50-62 F	Binger, B. Binger, B Binger, B Binger, B. Binger, B.	8403020124# 8403020127# 8403020172# 8403020180# 8403020193#	FOIA FOIA FOIA FOIA FOIA	SNOW, R A SNOW, R A SNYDER, B J SNYDER, B J	8403060266* 8403060270* 8403060278* 840315031 [8403230240	20-350 b 20-350 b 20-355 1 20-355 1
BHERWDOD, O. G BHERWDOD, O. O BHEWMAKER, R. E SHEWMAKER, R. E.	8403130282 8403200271 8403270255 8203100417* 8401230660*	PR 50-245 P PR 50-440 8 50-329 8	SINGER.B SINGER.B SINISI.J M SINISI.J M SINISI.J.M.	8403020194# 8403020199# 8403140029 8403140031 8403140033	FDIA FDIA 50-293 J 50-245 J 30-27 J	SNYDER.B J SOKOLOWSKI,W SOMERVILLE,K G SOMMERS,P	8403280243 8403010045* 8403170411 8403170412 8403170055	50-320 F CONTRACT 40-8783 40-8783 NUREG
SHIFFER, J. D. SHIFFER, J. D SHIFFER, J. D SHIMA, S SHIMA, S	8403120027* 8403150025 8403220066 8403010465 8403010468*	50~275 0 50~275 9 50~275 8 XPORTLIC XPORTLIC	SINKIN'T SINKE'G'Y' SINISI'Y W SINISI'Y W	8403140078 8403140072 8403140114 8403150272 8403140152	50-244 J 50-213 J 50-213 J 40-8784 50-498 Ø	SOD: P SORENSEN: O. C SORENSEN: Q. C SORENSEN: O. C SORENSEN: O. C	8403070115 8403020330 8403070118 8403070121 8403070236	NUREG 50-397 P 50-508 D 50-397 E 50-397 P
Shima, B	8403010470	XPORTLIC	SINKIN, L	8403270025	50-478 0	SDRENSEN, O C	8403120199	50-50B A
Ghima, B	8403010473*	XPORTLIC	SISK, K D	8403290179	50-322 0	SORENSEN, O C	8403130203	PR
Bhima, B,	8403010512	XPORTLIC	SISK, K D.	8403290179	50-322 0	SORENSEN, O C	8403130227	50-377 V
Shima, B,	8403010517*	XPORTLIC	SJOBLOM, G L	8403290289	PR	SORENSEN, O C	8403130316	50-397 P
Bhima, B	8403050327*	XPORTLIC	SKAGGS, R L	8403300132*	50-478 A	SORENSEN, O C	8403130385	50-50B F
Shima, B.	8403050333*	XPORTLIC	BKIERKOWBKI, P	8403130327	PR	SORENSEN, G. C	8403130480	50-397 P
Shima, S.	8403050373*	XPORTLIC	SKOQEN, F B	8403080220*	50-314 P	BORENSEN, G. C	8403200236	50-397 P
Shima, B.	8403050376*	XPORTLIC	SKOV, D D	8403200061	70-553	BORENSEN, G. C	8403200261	50-397 P
Shima, B.	8403070425*	XPORTLIC	SKOV, D, D	8403200107	40-8107	BORENSEN, G. C	8403220061	50-397 P
Shima, B.	8403070426*	XPORTLIC	BLAGGIE, E L	8304060577*	50-397 A	BORENSEN, G. C	8403260006	50-397 F
SHIPLEY, L E SHIPMAN, W B SHIRAKAWA, T, SHIRAKAWA, T, SHIRAKAWA, T	B403120010* B403010163* B403010464 B403010471 B403010487	50-275 0 50-348 P XPORTLIC XPORTLIC XPORTLIC	SLAWINSKI,W J SLAWINSKI,W J SLIGER,E K SLIGER,E K	8403190313* 8403220140* 8403300033* 8403080235 8403080133*	50-341 Q 50-305 Q 50-456 Q 50-259 F FOIA	Sorensen, o c Sorensen, o c Sorensen, o c Sorensen, o c Sorensen, o c	8403260165 8403260221 8403260292 8403270118 8403270141	50-397 P 50-509 A 50-397 P 50-397 Q 50-397 F
BHIRAKAWA, T. BHIRAKAWA, T BHIRAKAWA, T BHIBLER, E. BHIBLER, E	8403220197 8403260041 8403260390 8403060365* 84030603694	XPORTLIC XPORTLIC XPORTLIC GA999 GA999	SMITH, C SLOBODIEN, M. J SLOBODIEN, M. J SLOBODIEN, M. J	8403080050* 8403080079* 8403080102* 8403080109* 8403160319*	FOIA FOIA FOIA FOIA 50-413 Q	SORENSEN, Q C SORENSEN, Q C SORENSEN, Q C SORENSON, J, SORENSON, J H	8403270207 8403270220 8403270242 8403130278* 8403010244	50-397 J 50-397 E PR 50-282 R 50-322 T
SHISLER, E.	8403040372*	GA799	SMITH, DE,	8403190424	40-8681	SORLIE, 0	8403140228	50-397 D
SHISLER, E	8403040374*	GA999	SMITH, DE,	8403090085	50-257 8	SORRELL, E, C	8403070282	50-321 F
SHISLER, E.	8403040379*	GA999	SMITH, D.L.	8403130181	50-260 8	SORRELL, E C	8403130004	50-321 F
SHOEMAKER, C. J.	8403070030	50-419 D	SMITH, DE,	8403190371	50-257 8	SORRELL, E C.	8403130145	50-321 F
SHOEMAKER, C. J.	8403070188	50-275 G	SMITH, GC	8403070259*	70-1100	SORRELL, E C.	8403240150	50-321 F
SHOEMAKER, C. J. SHOEMAKER, C. J. SHOEMAKER, C. J. SHOEMAKER, C. J. SHOEMAKER, C. J.	8403090059 8403090102 8403140004 8403140041 8403190129	50~322	Smith, q. d Smith, J. C, Smith, J. F. Smith, J. H. Smith, J. J.	8403280025* 8403120091 8403080076* 8403060126* 8403130308*	50-416 P 50-331 B FOIA 50-244 P 70-2199	BORRELL, E. C. BORRELL, E. C BOWBY, F BPECK, B. W BPECK, B. W	8403300143 8403300337 8403230076* 8403050148 8403040084	50-321 F 50-321 F CONTRACT 50-206 F 50-250 F
SHOEMAKER, C. J.	8403210159	50-275	SMITH, J.L.	8403290160	50-922 F	SPECK, S. W.	8403130185	50-254 F
SHOEMAKER, C. J.	8403230276		SMITH, J.T.	8403220302*	50-922 T	SPECK, S. W.	8403130185	50-295 F
SHOEMAKER, C. J.	8403260007		SMITH, P.	8403070383*	27-99	SPECK, S. W.	8403190131	50-322 Q
SHOEMAKER, C. J	8403280359		SMITH, P.	8403070414*	CONTRACT	SPECK, S. W.	8403190343	50-322 F
SHOEMAKER, C. J	8403300278		SMITH, P.	8403120226*	CONTRACT	SPECTER, A.	8403200200*	50-287 Q

AUTHOR	ACCESSION NUMBER	SUBJECT CATEOGRY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
ECTER, A	8403200211*	50-289 0	STAROSTECKI, R	8403190231	70-371	STEWART, W L	8403300055	50-338 R
EIS, T	8010070240*	50-440 A	STAROSTECKI, R	8403190267	50-29 P	STEWART, W L	8403300060	50-260 R
EIS, T P	8311140170*	ACRS	STAROSTECKI, R	8403220014	50-317 P	STICKLEY, T H	8402280725*	50-267 P
EIS, T P	8312120006*	ACRS	STAROSTECKI, R	8403220033	50-387 Q	STIETZEL, J F	8403130259	50-315 R
EIS, T P	8312230256*	50-275 P	STAROSTECKI, R	8403220079	50-383 Q	STILE, V R	8403060266*	50-322 T
EIS, T. P	8402240387*	M18C	STAROSTECKI,R	8403220086	50-354 G	STILE.V R	8403040270*	50-322 T
'EIS, T. P	8403020424	M18C	STAROSTECKI,R	8403220075	50-309 G	STILE.V R	8403040278*	50-322 T
'ENCER, D A	8403120054	50-373 S	STAROSTECKI,R	8403220105	50-272 G	STILL.J	8403150315	27-47
ESSARD, R L	8403050279*	FOIA	STAROSTECKI,R	8403220131	50-412 G	STILWELL,T C	8403150045*	50-237 P
'ESSARD, R L	8403060151	50-266 O	SYAROSTECKI,R	8403220143	50-322 G	STITES.S J	8403140040*	50-461 Q
ESSARD, R L	8403040162*	50-264 0	STAROSTECKI, R.	8403260165	50-334 0	STODDART, P Q	B403070013*	50-395 0
ESSARD, R L	8403120008	50-456 F	STAROSTECKI, R.	8403260233	50-3 8	STODDART, P Q	B403160244*	50-259 0
ESSARD, R L.	8403120021	50-315 F	STAROSTECKI, R.	8403260313	50-293 0	STODDART, P. G	B403160300*	50-261 0
ESSARD, R L	8403120025	50-373 F	STAROSTECKI, R.	8403270135	50-272 0	STODDART, P Q.	B403290290*	50-369 0
ESSARD, R L	8403120045	50-266 F	STAROSTECKI, R.	8403270140	50-387 0	STODDART, P Q.	B403070146	70-27
ESSARD, R L	8403120046	50-483 F	STAROSTECKI, R	B403270200	50-412 G	9 T.SHOTB	8403070324	70-27
ESSARD, R L	8403120048	50-305 F	STAROSTECKI, R	B403300137	70-687	9 T.SHOTB	8403140043	70-1151
ESSARD, R L	8403120049	50-341 F	STAROSTECKI, R.	B403300165	50-223 G	9 T.SHOTB	8403140138	70-143
ESSARD, R L	8403120051	50-275 F	STAROSTECKI, R.	B403300171	50-272 G	9 T.SHOTB	8403160173*	70-143
ESSARD, R L	8403120053	50-10 F	STAROSTECKI, R	B403300187	50-423 A	9 T.SHOTB	8403160258	70-143
ESSARD, R L	8403120057	50-331 F	STANDSTECKI, R	B4033001B7	50-244 G	4 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	8403160286	70-27
ESSARD, R L	8403120058	50-546 F	STABEK, S	B403120079*	50-237 G		8403160337	70-143
ESSARD, R L	8403120060	50-263 F	STATTON, C. D	B4031302B4	GA999		8403160340	70-1113
ESSARD, R L	8403120074	50-409 F	STAUS, W P	B403150205	40-8781		8403160369	TOPREP
ESSARD, R L	8403120077	50-461 F	STAUSER, R H	B403200157*	GA999		8403160375	70-1113
ESSARD, R. L.	8403120073	50-35B F	STEARNS, C F	BA03300167	70-1717	STOHR, J, P	8403210151	70-143
ESSARD, R. L.	8403120077	50-155 F	STEFANG, J, J	BA03010246	50-440 A	STOHR, J P	8403260177	70-27
ESSARD, R. L.	8403120100	50-346 F	STEFANG, J J	BA03050350	50-440 H	STOHR, J P,	8403270285	70-143
ESSARD, R. L.	8403120103	50-327 F	STEIN, S S	BA03020400	FOIA	STOHR, J P,	8403300011	70-27
ESSARD, R. L.	8403120104	50-282 F	STELLO, V	B001140316*	50-460 A	STOHR, J P	8403300041	70-27
ESBARD, R L ESBARD, R L ESBARD, R L ESBARD, R L ESBARD, R L	8403120109 8403120112 8403120115 8403120149 8403130348	50-454 F 50-440 F 50-255 F 50-254 F 50-373 0	STELLO, V STELLO, V STELLO, V STELLO, V	8304240013* 8308150440* 8312070358 8403040323 8403170003	50-267 P FDIA REVIEW GRP REVIEW GRP REVIEW GRP	STOIBER, C. R STORES, C STOLZ, J. F. STOLZ, J. F. STOLZ, J. F.	8403270404 8403170021* 8403010124* 8403010377* 8403010474	XPDRTLIC 50-275 & 50-321 P 50-312 P 50-312 P
ESSARDIR L ESSARDIR L ESSARDIR L ESSARDIR L ITIBERGID B	8403190170 8403200295 8403200277* 8403230075 8403240109*	50-461 G 50-454 G 50-454 G 50-373 G 40-1341	STETTO'A STETTO'A STETTO'A STETTO'A	84031 70005 84031 70008 84031 70009 84031 70012 84031 70017	REVIEW ORP REVIEW ORP REVIEW ORP REVIEW ORP REVIEW ORP	STOLZ,J F. STOLZ,J F STOLZ,J F. STOLZ,J F. BTOLZ,J F	B403020169 B403050037* B403060440* B403070137 B403070141*	50-289 P 50-286 P 50-321 P 50-277 P 50-277 P
ROAT, E F ENAWSKI, D ENIAWSKI, D ENIAWSKI, D ENIAWSKI, D J	8403270048* 8403200286 8403130310 8403300045 8403080202*	50-352 T I&E I&E FOIA	BTELLO, V STELLO, V STELLO, V STELLO, V	8403170027 8403170031 8403170037 8403170081 8403170103	REVIEW ORP REVIEW ORP REVIEW ORP REVIEW ORP REVIEW ORP	STOLZ, J F STOLZ, J F STOLZ, J, F STOLZ, J F STOLZ, J F	8403070357 8403120310 8403120339 8403120354 8403150243	50-321 P 50-289 P 50-312 F 50-302 F 50-346 F
ENIAWSKI, D J ENSSON, B. A INIVASAN, M INIVASAN, M O LAURENT, N	8403080215* 8403130259 8312140429* 8403070114 8403020292	FOIA 50-315 R 50-400 E NUREG 50-29 R	Bieffo'a Bieffo'a Bieffo'a Bieffo'a	84031 70146 64031 70176 84031 70251 84031 70256* 84031 70260	REVIEW ORP REVIEW ORP REVIEW ORP REVIEW ORP REVIEW ORP	STOLZ, J F STOLZ, J. F. STOLZ, J F STOLZ, J F STOLZ, J F	8403150263 8403150328 8403150335* 8403220107 8403230238	50-344 P 50-269 P 50-269 P 50-269 P 50-313 F
LAURENT, N N	8403090175	50-29 8	STELLO, V.	8403190372	REVIEW ORP	STOLZ, J. F.	8403260045	50-321 F
LAURENT, N N	8403200215	50-29 8	STEPTOE, PP	8403020134	50-275 0	STOLZ, J. F.	8403260045*	50-321 F
NEIR, J P	8401120525	HASTE MOT	STEPTOE, PP	8403020134	50-275 0	STOLZ, J. F.	6403260261	50-321 F
NHL, D	8403300294	NUREO	STEPTOE, PP	8403020140	50-275 0	STOLZ, J. F	8403270315	50-289 F
AMIRIG, D	8403140119	50-329 0	STEPTOE, PP	8403020140	50-275 0	STOUT, D. M	8403150319	40-8829
AMIRIS.B	8403200139	50-329	BTEMART, J P	8403040029*	50-206 G	STOUT, R B	8403080210#	50-316 P
"NLEY, L.	8403270046*		BTEMART, M.	8403200245*	50-482 A	STOUT, R, B.	8403150104#	50-316 P
ANSBURY.P S	8403160186*		STEMART, W L	8401130314	50-280 P	STOUT, R B	8403270101#	50-316 P
ARLING, J	8403280009		BTEMART, W. L	8403020001	50-338 G	BTRACK, R. A	8403270198	50-54 R
AROSTECKI	8403300180		STEMART, W L	8403020042	50-338 P	STREET, L L	8403010454	XPORTLIC
AROSTECKI.R	8403010020*	50~289 P	STEWART, W L	8403020053	50-280 R	STREET, L. L	8403010456*	XPORTLIC
AROSTECKI.R	8403010310	50~277 G	STEWART, W L	8403020122	50-338 R	STREETER, J F.	8403050168	50-373 Q
AROSTECKI.R	8403010381	50~322 G	STEWART, W. L	8403020195	50-280 P	STREETER, J F	8403080108*	FDIA
AROSTECKI.R	8403010397	50~213 G	STEWART, W L	8403080071	50-337 P	STREETER, J F	8403080176	50-461 Q
AROSTECKI.R	8403020288	50~443 G	STEWART, W L	8403080091	50-280 F	STREETER, J F	8403080251	50-483 Q
AROSTECKI.R AROSTECKI.R AROSTECKI.R AROSTECKI.R AROSTECKI.R	8403020298 8403020347* 8403020348 8403070282 8403070203	50-54	STEWART, W.L. STEWART, W.L. STEWART, W.L. STEWART, W.L. STEWART, W.L.	8403080244 8403070242 8403130298 8403160154 6403170052	50-280 F 50-280 F 50-336 P 50-280 Q 50-280 F	STREETER, J F STREETER, J. F STREETER, J F. STREETER, J F STREETER, J F	8403080256* 8403130351 8403190290 8403190293* 8403200279	50-483 Q 50-305 V 50-373 Q 50-373 Q 50-483 Q
AROSTECKI, R	8403070312	50-333	STEWART, W. L	8403170201	50-337 P	STREETER, J. F	8403300017	50-454 0
AROSTECKI, R	8403070314		STEWART, W. L	8403170263	50-280 F	STREETER, J. F	8403300023*	50-454 0
AROSTECKI, R	8403070330		STEWART, W. L	8403170377	50-339 P	STREETER, J. F	8403300053	50-341 0
AROSTECKI, R	8403070342		STEWART, W. L.	8403200116	50-280 F	STRUCKMEYER, R.	8403160248*	50-352 0
AROSTECKI, R	8403120170		STEWART, W. L.	8403220028	50-338 P	STRUMMASSER, M	8403060260	50-275 0
Ardstecki.r	8403130006	50-220 0	STEWART, W. L.	8403220077	50-338 P	Subudhi, M.	8403260022*	50-454 A
Ardstecki.r	8403130269	50-219 0	STEWART, W. L.	8403260105	50-280 P	Subudhi, M	8403260061*	50-454 A
Ardstecki.r	8403130355	50-354 0	STEWART, W. L.	8403270021	50-280 Q	Sugarman, R. J	8403130411	50-352 G
Ardstecki.r	8403130472	70-1100	STEWART, W. L.	8403270208	50-338 P	Sugarman, R. J	8403130411	50-352 G
Ardstecki.r	8403150053	50-287 0	STEWART, W. L.	8403270248	50-337 P	Summerb, R. J.	8403220115*	50-272 G
ROSTECKI.R	8403150054	50-277 G	STEWART, W L	8403280125	50-280 F	BUND, H J. BUNSER, J J. BUTTON, J. W. BUTTON, J. W. BVENBBON, B A.	8403070318*	50-325 Q
ROSTECKI.R	8403150067	50-293 G	STEWART, W L	8403270157	50-280 G		8403070063	50-220 F
ROSTECKI.R	8403150076	50-410 G	STEWART, W L	8403270260*	50-338 G		8403130042*	0A777
ROSTECKI.R	8403150105	50-309 P	STEWART, W L	8403300005	50-338 P		8403130432*	0A777
ROSTECKI.R	8403150146	50-284 G	STEWART, W L	8403300028	50-338 P		8403020007	50-316 R

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	BUBJEC CATEGO	
SHAMY, BA SHAN, HB. BHANSON, N.E BHARTS, DJ SHARTZ, ED	8403190404* 8403160222* 8403019079 8403080136 8403120013	50-413 A 50-390 Q GA999 50-410 G 50-456 S	THOMAB.C O THOMAB.E B THOMAB.E B THOMAB.E B THOMAB.E,B	8403270387 8403130104* 8403130118* 8403130128* 8403130138*	50-322	TRIPP.L TRIPP.L E. TRIPP.L E. TRIPP.L E. TROJANOWSKI,R	8403270008 8403010322* 8403150063* 8403220137* 8403210133	50-219 50-277 50-277 50-277 50-412 1&E	8 0 0
SWARTZ, E. D. SWARTZ, E. D. SWEENEY, M. SWETLAND, P. SWETLAND, P.	8403190193 8403170274* 8403080393 8403220103* 8403010404*	50-454 8 50-454 9 50-287 P 50-307 0 50-213 9	Thomas, J Thomas, J Thomas, M. Thomas, N Thomas, R	8403010182* 8403010134* 8403270207* 8403080273* 8403200132	50-348 P 50-348 P 50-370 G 50-298 F 14E	TROJANOWSKI,R TROSKOSKI,W M TROUP,G.L TROUP,G.L TROWBRIDGE,G F	8403300112 8403260173* 8403160307* 8403290050* 8403060090	1&E 50-334 50-395 50-390 50-424	0 0 0
SWIDER, M. A. SWIDER, M. A SWIDER, M. A. SWIDER, M. A. SWIDER, M. A.	8403130010 8403130010 8403130139 8403130139 8403130403	50-440 0 50-440 9 50-440 9 50-440 9 50-440 9	T REAMONT D. GEAMONT M. GEAMONT M	8403270217* 8403270221* 8312140351* 8403270367 8403020083	70-1257 70-1257 50-275 E 50-275 U 50-279 R	THOWERIDOE, OF TROWERIDOE, OF, TROWERIDOE, OF, TROWERIDOE, OF TROWERIDOE, OF	8403040090 8403080105 8403080105 8403200055 8403200055	50-424 50-287 50-287 50-287 50-287	000
Shiqer, M. A Shiqer, M. A. Shiqer, M. A Shiqer, M. A Shiqer, M. A.	8403130403 8403150001 8403150001 8403150009 8403150009	50-440 Q 50-440 Q 50-440 Q 50-440 Q 50-440 Q	Thomason, P. V Thomason, P. V Thomberg, R. C Thomberg, R. C Thompson, D	84031900B9 8403300150 8403070355 8403280114 8403080120*	50-298 F 50-298 R 50-275 F 50-275 F FDIA	TROWBRIDGE, G. F YROHBRIDGE, G F TUCKER, H B. TUCKER, H B. TUCKER, H. B	8403200120 8403200120 8403210130 8403010140 8403010308	50~289 50~289 50~369 50~413 50~269	G R B
Shiger, M. A. Shiger, M. A Shiren, B. J. Sydnor, R. B Sydnor, R. B.	8403260327 8403260327 8403070022* 8403130081 8403130098	50-400 0 50-400 0 50-443 0 50-318 8 50-317 8	THOMPBON, D. J. THOMPBON, H. L. THOMPBON, T. THOMPBON, V. J. THOMBEN, E., R.	840327004B* 830804057B* 8401160250 8403070161* 8403010075	50-352 T ACRE 50-346 S CONTRACT GA999	TUCKER, H. B TUCKER, H. B. TUCKER, H. B. TUCKER, H. B TUCKER, H. B.	8403010335 8403020317 8403040104 8403040225 8403040232	50-413 50-369 50-369 50-269 50-370	2 4 4 4 4
SYDNOR, R. B BYDNOR, R. B. BYDNOR, R. B SYDNOR, R. B BZALAY, R.	8403130252 8403130279 8403130413 8403130450 8403190317	50-317 8 50-317 8 50-318 8 50-318 8 PR	THOMBEN, E. R THONUS, L. THONUS, L. THORNBERRY, R C THORNBERRY, R C	8403130338* 8403130471* 8403150135* 8403020004 8403120027*	0A799 50-320	TUCKER, H. B. TUCKER, H. B. TUCKER, H. B. TUCKER, H. B. TUCKER, H. B	B403060292 8403060336 B403060419 B403060422 B403070185	50-249 50-413 50-413 50-413 50-413	P F A A
SZYMCZAK, G. TAHVILI, T. TAKEUCHI, K. TALBOT, R. TAM, P.	8403090075 8403230111* 8403230208 8403010004* 8403070387	PRM 30-255 P NUREO CONTRACT 50-334 P	THORNBERRY, R. C THORNBURG, H D. THORPE, J R THORPE, J. R THORPE, J R.	8403300141 8401230260* 8403050070 8403170387 8403270015	50-275 R 50-329 S 50-219 P PR 50-219 H	TUCKER, H B. TUCKER, H. B TUCKER, H. B TUCKER, H. B TUCKER, H. B	8403070210* 8403070352 840308023 <i>9</i> 8403090222 8403090226	50-413 50-369 50-269 50-269 50-413	0 F V F 8
TAM, P. 8. TAMBLING, T. N TAM, C. P. TANNER, J. E. TANNER, R. L	8403160061 8403190096# 8310310475# 8403190449 8403130378	50-334 P 50-123 G 50-329 A NUREG PR	THRON, R. W TIDABACK, A. J. TIETZ, G. TILLMAN, A. TILLMAN, A.	8403230058 8403080204* 8403070274 8403020241* 8403170188*	PR FOIA 50-234 F 50-250 G 50-259 G	TUCKER, H. B TUCKER, H. B. TUCKER, H. B TUCKER, H. B TUCKER, H. B	8403070241 8403070254 8403070276 8403120150 8403120153	50-413 50-269 50-369 50-370 50-413	8 F B E
TAPERT, A. C. TAUZIN, B. TAYLOR, D. F. TAYLOR, J. A. TAYLOR, J. A.	B403090214 B403140208* B403190346 B403090213 B403120174	PR 50-382 U 50-387 F 50-338 B 50-338 P	TIMO,D P. TIPPB, 8 D. TIPPB, 8 B. TIPPB, 8 B. TIPPB, 8 B. TIPPB, 8 B.	8402100259 8403120031 8403140031 8403140044 8403190024	TOPREP 50-346 8 50-346 8 50-321 9 50-346 9	TUCKER, H. B TUCKER, H. B. TUCKER, H. B TUCKER, H. B. TUCKER, H. B.	8403120173 8403130086 8403130104 8403130167 8403130332	50-370 50-413 50-413 50-370 50-369	8 A A B
TAYLOR, J.A. TAYLOR, J.A. TAYLOR, J.H TAYLOR, J.H TAYLOR, J.J	8403190080 8403190394 8403190241 8403300179 8403220112	50-338 B 50-338 B TOPREP TOPREP WASTE MOT	TIPPS, B. B TIPPS, B. B TIPPB, B. B TISON, J. C. TKACHYK, J. W.	8403240086 8403260119 8403260191 7911120366* 8403060533	50-366 B 50-366 B 50-366 B 50-312 F NUREO	TUCKER, H, B TUCKER, H, B TUCKER, H, B, TUCKER, H, B, TUCKER, H, B	8403130341 8403140231 8403150065 8403150128 8403150138	50-370 50-369 50-413 50-413 50-370	P F 6 8
TAYLOR, P. A. TAYLOR, P. A TAYLOR, R. Q. TAYLOR, T. J. TAYLOR, T. J.	8403160224* 8403160370* 8403130219* 8403020174 8403200314	50-413 Q 50-413 Q 50-445 Q HASTE MOT WASTE MOT	Tobias, M L. Tobin, W Toll, J. S. Tolson, V. Tompking, B. A.	8403130217 8403160016* 8403210124 8403070152 8403030068	NUREQ 50-390 G 50-164 P CONTRACT 50-537 G	TUCKER, H B TUCKER, H, B. TUCKER, H, B. TUCKER, H, B TUCKER, H, B	840315015& 8403160028 8403160143 8403160177 8403160216*	50-369 50-413 50-413 50-413 50-413	P G A G
TEDESCO, R. L. TEDESCO, R. L. TEDFORD, C. F. TEDFORD, C. F. TEICHMANN, T	8110080612* 8111200217* 8403070106 8403270263 8403010041*	50-460 A 50-397 A PR PR FOIA	TOMPKINB, B. A TOMOUE, T. TOMOUE, T. M. TOTH, A D TOUSLEY, D. R	8403060179 8403120137* 8403120079* 8403080270* 8403300243	50-275 Q 50-237 Q 50-237 Q 50-397 Q WASTE MOT	TUCKER.H.B. TUCKER.H B. TUCKER.H B TUCKER.H B. TUCKER.H B	8403160253 8403160299* 8403160313* 8403190257 8403190289	50-413 50-413 50-369 50-369 PR	0 0 P
TELLOCK, H. C TEMPLE, Q. M. TEPEL, R. C. TEPER, D. C. TERC, N. M.	8403270032 * 8403080152 * 8403200358 8403020124 8403210054 *	FOIA 50-528 G NUREG 50-424 G 50-320 G	TOWNSEND, B TOWNSEND, B. TOWNSEND, B. TOWNSEND, B. TOWNSEND, B. L	8403220216 8403220256 8403220275 8403230152 8403020067	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B	8403190303 8403190394 8403200010 8403200078 8403200123	50-370 50-413 50-269 50-413 50-369	8 R E R
TERWILLIGER, L, THADANI, A. C, THEOFANOUS, T. Q, THEROUX, R. R. THIES, A. C,	8403150195 8308040003* 8403230216 8403210032 8403070331*	XPORTLIC 50-284 P 50-537 A 50-280 S 50-413 G	TRAHM, T. R.	8403010105 8403010120 8403010130 8403010285 8403060245	50-454 A 50-454 E 50-454 G 50-454 E 50-454 G	TUCKER, H. B TUCKER, H. B TUCKER, H. B TUCKER, H. B TUCKER, H. B	8403200165 8403200221 8403220038 8403220074 8403260034	50-413 50-413 50-367 50-413 50-413	A F A A
THOM, T. THOM, T. THOMADSEN, B. R. THOMAS, B THOMAS, B	8403020103 8403300134* 8403130327 8403050002 8403050043	50-259 R 50-259 R PR 50-254 G 50-10 G	TRAMM, T. R. TRAMM, T. R. TRAMM, T. R. TRAMM, T. R TRAMMELL, C, TREBY, B. A.	8403060345 8403220133 8403260132 8307180403* 8403190047	50-454 E 50-454 A 50-454 E 50-344 P 50-537 Q	TUCKER, H B TUCKER, H. B. TUCKER, H B TUCKER, H. B TUCKER, H. B.	8403260073 8403270103 8403270209 8403270213 8403270230	50-413 50-413 50-269 50-413 50-369	A H H A F
THOMAS, B. THOMAS, B. P. THOMAS, C. D. THOMAS, C. D. THOMAS, C. D. THOMAS, C. O.	8403230107# 8403220240 8312180241# 8403020162 8403070360	50-10 G CONTRACY ACRS 50-13 P 50-5 F	TREBY, B. A TREBY, B. A TREBY, B. A. TREHAN, N TREHAN, N K	8403170118 8403170148 8403210102 8403280121* 8305160260	50-445 0 50-445 0 50-445 0 50-281 8	TUCKER, H.B. TUCKER, H.B. TUCKER, H.B. TUCKER, H.B TUCKER, H.B.	8403270243 8403280102 8403270082* 8403270148 8403270244	50-369 50-413 50-269 50-369 50-413	P G P S
THOMAS, C. O. THOMAS, C. O	8403120274 8403150176 8403260340 8403280065 8403280068*	50-54 P 50-54 P 50-139 F 50-83 P 50-83 P	TREHAN, N.K. TREHAN, N.K. TREMBLAY, P. TRESLER, M. TRIPP, L.	8307240510* 8307260515 8403050284 8403120012* 8403260173*	50-311 8 50-311 8 50-346 9 50-275 9 50-334 9	TUCKER, H B. TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H, B.	8403290247 8403290274# 8403300079 8403300107 8403300124	50-369 50-413 50-413 50-413 50-413	P G E A B

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT	
KER,H B AND,M J AND,M J KANIS,M M NER,S E	8403306188 8403060287* 8403060295* 8403080076* 8403060366*	50-413 A 50-322 T 50-322 T FOIA 50-302 P	VANDEWALLE, D. J. VANDEWALLE, D. J. VARELA, A. A. VARGA, S. A. VARGA, S. A.	8403190101 8403260115 8403300076* 8401120597* 8403010066	50-255 8 50-255 P 50-322 0 50-348 P 50-305 P	VAYSSIER.Q VERRELLI.D M VERRELLI.D M VERRELLI.D.M. VERRELLI.D M	B403080364* B402130400 8402140189 B403070007 B403070085	FOIA 50-348 50-261 50-395 50-395	0 0 0
TLE, W K ETON, D R RITZ, R A RICH, W T RICH, W T	8403290311 8403230177 8403300190* 8403120019 8403120085	PRM NURE9 50-311 d 50-278 S 50-277 S	VARGA, SA VARGA, SA VARGA, SA VARGA, SA VARGA, SA.	8403010171* 8403010173 8403010174* 8403020038* 8403020156	50-250 P 50-250 F 50-247 P 50-280 P 50-348 P	VERRELLID M VERRELLID M VERRELLID M VERRELLID M VERRELLID, M	8403070094 8403070100* 8403070148 8403070179 8403070186*	50-400 50-400 50-416 50-400 50-416	Q: Q: Q: Q:
RICH, W T RICH, W T RICH, W T RICH, W T RICH, W T	8403120175 8403130158 8403170178 8403200017 8403270064	50-278 8 50-278 8 50-277 R 50-277 8 50-277 P	VARGA-S A VARGA-S A VARGA-S A VARGA-S A VARGA-S A	8403020171 8403020178 8403020184 8403020190 8403050217	50-284 F 50-247 P 50-250 P 50-315 P 50-261 P	VERRELLI, D. M.	8403070193* 8403070206* 8403070218 8403070247 8403070307	50-400 50-416 50-438 50-416 50-324	0 0 0
EL.D EL.D EL.D EL.D, EL.P	8403010091 8403010461 8403050231 8403070029 8403120221	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	Varga, e a Varga, e a Varga, e a Varga, e a Varga, e a	8403060012* 8403060044 8403060504 8403060508 8403070321	50-261 P 50-286 P 50-305 P 50-261 F 50-305 P	VERRELLI, D. M. VERRELLI, D. M VERRELLI, D. M VERRELLI, D. M VERRELLI, D. M.	8403160008 8403160100 8403160142 8403160201 6403160207	50-390 50-416 50-348 50-390 50-390	0: 0: 0: 0: F
EL.D EL.D EL.D EL.O EL.O	8403230071 8403230159 8403300309 8403070039 8403270286	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	VARGA, S A VARGA, S A VARGA, S A VARGA, S A VARGA, S A	8403070382* 8403070389* 8403070398* 8403090145 8403090153	50-346 P 50-334 P 50-247 P 50-275 P 50-334 P	VERRELLI, D. M.	B403160214 B403160217 B403160232 B403160237 B403160271	50-390 50-327 50-259 50-390 50-390	G G G G
ARD, A ARO, A R KEWICZ, 8 ONE, A IGHT, C.	8111120735* 8105140104* 6403020073 8403200267* 8403160317*	50-460 E 50-460 A 50-213 R 50-482 A 50-413 Q	VARGA, B A VARGA, B A VARGA, B A VARGA, B A VARGA, B A	8403140179 8403140200* 8403140224 8403140225 8403140300	50-260 G 50-260 G 50-315 P 50-305 P 50-250 G	VERRELLI, D, M VERRELLI, D, M VERRELLI, D, M VERRELLI, D, M VERRELLI, D, M,	8403160274* 8403160305 8403160336 8403160350 8403160374*	50-241 50-395 50-416 50-390 50-390	0 0 F 0
>N.R T , V. , V. , V.	8403050170 8403020300 8403140228 8403150110 8403150155	PT21 50-317 F 50-317 F 50-317 F 50-317 F	Varga, 9. a Varga, 9. a Varga, 9. a Varga, 9. a Varga, 9. a	8403190150 8403190429 8403190450 8403210195 8403210197	50-250 P 50-250 F 50-315 P 50-348 P 50-247 P	VERRELLID M VERRELLID M VERRELLID M VERRELLID M VERRELLID M	8403140382 8403270019 8403270042 8403270078 8403270084	50-241 50-348 50-370 50-348 50-324	Q Q Q Q
EY.E E EY.E E EY.E E EN.J BRUNT.E.E	8403070874 8403120074 8403150161 8403150222* 8402270008	50-261 F 50-400 V 50-261 P WASTE MOT 50-328 S	Varga, 5 a Varga, 6 a Varga, 5 a Varga, 9 a Varga, 6 a	8403210200* 8403260050 8403260294 8403280101* 8403280108*	50-247 P 50-272 P 50-334 P 50-295 P 50-295 P	VERRELLI, D. M VERRELLI, D. M VERRELLI, D. M. VERRELLI, D. M. VERRELLI, D. M.	8403270087* 8403270117 8403270151 8403270163 8403270163*	50-348 50-257 50-416 50-400 50-400	G G G
BRUNT, E E BRUNT, E E BRUNT, E E BRUNT, E E BRUNT, E E	8403010212 8403020005 8403070012 8403070077 8403070087	50-528 A 50-528 E 50-528 E 50-528 S 50-528 B	Varga. S A Varga. S A Varga. S A Varga. S A Varga. S A.	8403280329 8403280329 8403300231 8403300233 8403300294	50-334 P 50-348 F 50-247 P 50-315 F 50-315 P	VERRELLID. M VERRELLID. M VERRELLID M VERRELLID M. VESELY, W.	8403270178 8403270201 8403270237 8403270284 8403010041*	50~400 50~370 50~259 50~395 FOIA	9 9 9 V
BRUNT, E. E. BRUNT, E. E BRUNT, E. E. BRUNT, E. E. BRUNT, E. E.	8403070076 8403070122 8403070167 8403070177 8403070258	50-32B	VARLEY: R A VARNER: L S VARNER: L S VASSALLO: D, B VASSALLO: D B	8403070171* 8403120314* 8403120345* 8403050337 8403060022	50-322 T CONTRACT CONTRACT 50-265 P 50-271 F	VIETTI, A. VILLFORTH, J C VILLFORTH, J. C. VISSING, G. B VITG, D.	8403010444 8403090106 8403160026 8403050053 8403270171*	50-498 PR 50-352 50-346 50-289	A D P Q
BRUNT, E E BRUNT, E E BRUNT, E E BRUNT, E E	8403120032 8403120069 8403120113 8403130449 8403130461	50-528 \$ 50-528 \$ 50-528 \$ 50-528 \$ 50-528 \$	VASSALLO, D. B VASSALLO, D. B. VASSALLO, D. B. VASSALLO, D. B. VASSALLO, D. B.	B403060034 B403060036 B403060041 B403060045 B403060050	50-293 F 50-220 F 50-263 F 50-333 F 50-331 P	VOGLER, B. H VOGLER, B. H. VOGLER, B. H. VOGLER, B. H. VOGLER, B. H.	8403140115 8403140118 8403190173 8403290376 8403290399	50-352 50-352 50-352 50-454 50-352	0 0 X 0
BRUNT.E E BRUNT.E E BRUNT.E E BRUNT.E E BRUNT.E E	8403140024 8403140048 8403160045 8403170387 8403200115	50-528 G 50-528 A 50-528 A PR 50-528 S	VASBALLO, D. B. VASBALLO, D. B. VASBALLO, D. B. VASBALLO, D. B. VASBALLO, D. B.	B403060053 B403060063 B403060067 B403060069 B403060073	50-324 P 50-254 F 50-324 P 50-324 P 50-324 P	VOBLER, B. H VOKAL, D. J. VOKAL, D. J. VOKAL, D. J VOLGENAU, E	8403270400* 8403130050 8403130254 8403130272 8403080075*	50-352 50-329 50-329 50-329 FOIA	9 0 8
BRUNT, E E BRUNT, E E BRUNT, E E BRUNT, E E BRUNT, E E	8403200160 8403200186 8403200226 8403230006 8403230019	50-529 8 50-528 8 50-528 8 50-528 8 50-528 8	VASSALLO, D. B. VASSALLO, D. B. VASSALLO, D. B. VASSALLO, D. B. VASSALLO, D. B.	8403060076 8403060471 8403060550 8403060567 8403060571	50-259 P 50-298 F 50-331 F 50-324 F 50-259 F	VOLGENAU, E. VOLGENAU, E VOLGENAU, E. VOLGENAU, E.	8403080112# 8403080122# 8403080132# 8403080156# 8403080160#	FOIA FOIA FOIA FOIA	
BRUNT, E E BRUNT, E E BRUNT, E E BRUNT, E E BRUNT, E E	8403230039 8403230084 8403230099 8403230113 8403230132	50-528 \$ 50-530 \$ 50-528 \$ 50-528 \$ 50-528 \$	VASBALLO, D. B. VASBALLO, D. B. VASBALLO, D. B. VASBALLO, D. B. VASBALLO, D. B	84030700&6 8403130476 8403140185 8403140236 8403140246	50-324 F 50-220 F 50-263 P 50-324 F 50-333 F	VOLGENAU, E. VOLOENAU, F VOLLMER, R. H VOLLMER, R. H VOLLMER, R. H.	8403080190* 8403080072* 8307120336* 8403010282* 8403080316*	FOIA FOIA FOIA 50-329 50-247	â
BRUNT, E E BRUNT, E E BRUNT, E E, BRUNT, E E CLEVE, H D	8403260014 8403270236 8403300020 8403300076 8107200104#	50-528 F 50-528 A 50-528 S 50-528 S FDIA	VASSALLO, D B, VASSALLO, D B VASSALLO, D B VASSALLO, D B VASSALLO, D B	8403140248 8403140252 8403140276 8403140285 8403140287	50-293 F 50-298 F 50-296 P 50-271 F 50-324 P	VOLLMER, R. H VORDERBRUEGOEN VORDERBRUEGOEN VUMBACO, F. J VUMBACO, F. J.	8403080426* 8402140022* 8403270139* 8403050144* 8403050150*	50-275 50-528 50-528 40-672 40-672	Р О
DAATBELAAR DYKE, J. W VLIET, J. VLIET, J VLIET, J	8403080360* 8403200358 8403010030* 8403010116 8403020418	F01A NUREC 50-287 P 50-287 P 50-287 P	VASSALLO, D B VASSALLO, D B, VASSALLO, D, B, VASSALLO, D B, VASSALLO, D, B	8403140271 8403140304 8403140313 8403140317 8403150323	50-324 Q 50-333 P 50-331 P 50-331 Q 50-259 P	YUMBACO, F. J Wade, L Wade, L Waner, A. G. Waner, D	8403220072* 8403140189 8403230069 8403070216* 8403060552	40-672 PRM PRM 50-416 50-354	Q A
VLIET.V DENBERG, D DENBURGH, C, DERSTEEG, F DEWALLE, D, J,	8403050472 8403120140 840330030* 8403020112 8403070300	50-287 P 50-255 R 50-454 G XPORTLIC 50-255 G	VASSALLO, D, B VASSALLO, D, B VASSALLO, D, B. VAUGHAN. C, M VAUGHAN. T. E.	8403300232 8403300266 8403300268 8403140172 8403060225	50~293 F 50~333 P 50~271 P PR 50~269 F	MAGNER, D. H. MAGNER, D. H. MAGNER, M. E. MAGNER, M. E. MAGNER, M. E.	8403050369 8403150259 8403140111 8403160007 8403190187	50-354 50-354 50-289 50-289 50-289	F A G G G

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
WAGNER, M E WAGNER, M E WAGNER, M E WAGNER, M E WAGNER, P C	8403210165 8403210169 8403270304 8403270318 8403130251	50-416 G 50-289 G 50-289 G 50-416 G 50-267 P	WEISB.E R WEISB.E R WEISB.E R WELCH.S E WELLS.D.A	8403240382 8403270005 8403300257 8403270271 8403060173*	50-289	WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J	8403070238* 6403150024 6403150024 6403160010 8403160010	50-352 (50-352 (50-352 (50-352 (
Wagner, P C Hagoner, B R Wahi, K, K Haite, R S Walker, J. B	8403170083 8403270327 8403240353* 8403080270* 8403070245	50-267 P RES Waste Mot 50-397 Q 50-259 S	WELLS,DA WELLS,DA WELLS,DA WELLS,DA	8403060177* 8403120009 8403120068 8403120155 8403120160	50-341	WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J	8403200060 8403200060 8403200070 8403200070 8403210103	50-352 (50-352 (50-352 (50-352 (
WALKER, J B WALKER, J B WALKER, R. WALKER, R WALKER, R	8403070253 8403200087 8403130423 8403170013 8403170076*	50-259 S 50-296 S 50-263 S 50-374 S 50-373 Q	WELLS,D.A WELLS,D.A WELLS,R.W WELLS,R.W WELLS,R.W	8403190079 8403260127 8403130277 8403130277 8403140131	50-341 S 50-341 G TOPREP TOPREP TOPREP	WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J	8403210103 8403270012 8403270012 8403270042 8403270042	50-352 u 50-352 u 50-352 ü 50-352 i 50-352 i
WALKER, R, D WALKER, R D WALKER, R. D WALKER, R D, WALKER, R. F	8403120079* 8403120133* 8403120137* 8403120145* 8403270192	50-237 Q 50-331 Q 50-237 Q 50-243 Q 50-247 I	WELLS,R W WELT,M A WELT,M A WELT,M A	8403140131 8403080040* 8403080055* 8403080058*	TOPREP FOIA FOIA FOIA FOIA	WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J	8403270040 8403270384 8403270384 8403270392 8403270372	50-352 9 50-352 9 50-352 9 50-458 9 50-458 9
WALKER, R. S WALLER, W. K. WALLING, G E WALLO, E. W. WALSH, M	8403070076* 8403010349 8403020258 8403150045* 8403070181*	50-289 U 27-48 50-389 S 50-237 P 50-445 O	WELT, M A WELT, M A WELT, M A WELT, M A	8403080084* 8403080089* 8403080137* 8403080150* 8403080163*	FOIA FOIA FOIA FUIA FOIA	WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J	8403300127 8403300127 8403300128 8403300128 8403300271	50-352 9 50-352 9 50-352 9 50-352 9
WALTON, O A. WALTON, O A. WARD, J O, WARD, K, D, WAREMBOURG, D,	8402140038* 8403220137* 8403070106 8403170208* 8403010116	50-528 Q 50-412 Q PR 50-254 Q 50-267 S	WELT, M A WELT, M A WEN, P WENNER, T J	8403080168* 8403080172* 8403080185* 8403290191* 8403070318*	FOIA FOIA FOIA 50-289 G 50-325 G	WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WHEELER, L WHEELER, L	8403300271 8403300274* 8403300274* 8107140185* 8204290657*	50-352 Q 50-352 Q 50-352 Q 50-508 Q 50-508 A
Warembdurg, D Warembdurg, D Warembdurg, D Warembdurg, D Warembdurg, D,	8403010134 8403160227 8403170344 8403220063 8403270172	50-267 S 50-267 P 50-267 R 50-267 S 50-267 I	WENSLAWSKI, FA WENSLAWSKI, FA WENSLAWSKI, FA WENSLAWSKI, FA	8403060008 8403060019* 8403060165 8403060172* 8403060416	50-206 Q 50-206 Q 50-113 Q 50-113 Q 70-1257	М С,ЯЗНОІНЫ М С,ЯЗНОІНЫ М С,ЯЗНОІНЫ М С,ЯЗНОІНЫ М С,ЯЗНОІНЫ	8403060079 8403160002 8403160002 8403160019 8403160019	50-454 Q 50-454 Q 50-454 Q 50-454 Q 50-454 Q
Harembourg, D. W.	8403010101 8403010107 8403030112 8403160303 8403160326	50-267 P 50-267 G 50-267 G 50-267 G 50-267 G	WENSLAWSKI, FA WENSLAWSKI, FA WENSLAWSKI, FA WENSLAWSKI, FA	8403080061 8403080075* 8403190367 8403190373* 8403270221*	50-312	WHICHER, J M WHICHER, J M WHIPPLE, S WHIPPLE, S WHIPPLE, B WHITE, M G	8403240351 8403240351 8403020072 8403300083 8403010354	50-454 Q 50-454 Q 50-27 R 50-27 R WABTE MOT
HARNICK:R F HARNICK:R.F HARNICK:R F. HARNICK:R F HARRICK:J W	8403060385 8403080198* 8403190315 8403230043 8403230139	50-329 G FDIA 50-358 G 50-329 R 50-275 R	WENZINGER, E C WENZINGER, E C WENCOTT, H, M WENLEY, D A WENLEY, D A	8403270023* 8403270025* 8403020308* 8403140024* 8403200152*	FDIA FDIA 50-443 Q 50-329 A 50-423 A	WHITE,M P WHITE,W H WHITENER,H L WHITENER,H L WHITENER,H L	8403140096* 8403120010* 8403070017* 8403070338* 8403160339*	50-412 A 50-275 Q 50-413 Q 50-413 Q 50-259 Q
HABTLER, B. L WATKINB, L. B WATKINB, L. B. WATKINB, L. B. WATT, E.	8403230157* 8403140007 8403140012* 8403140012* 8403300130	40-8745 50-458 @ 50-458 @ 50-458 @ 50-282 F	Webbman, R Webt. J M. Webtafer. G. R. Webtafer. G. R Webtafer. G. R	8403020032* 8403200085* 8402040417 8403010072 8403040283	50~267 P 50~470 K 50~302 P 50~302 F 50~302 R	WHITMAN, D WHITTIER, G D WHITTIER, G D WHITTIER, G D WHITTIER, G D	8403270013 8403060094 8403130047 8403220192 8403230036	50-276 F 50-307 P 50-307 R 50-307 P 50-307 P
MATTS, R. J. WATTS, R. J. WATTS, R. J WATTS, R. J WEBER, J.	8403230016 8403230032 8403230048 8403230073 8403080281#	50-322 T 50-322 T 50-322 T 50-322 T 50-275 E	WESTAFER.O.R WESTAFER.O.R WESTAFER.O.R WESTAFER.O.R WESTAFER.O.R	8403060343 8403060359 8403060364 8403060402 8403090193	50-302 P 50-302 P 50-302 P 50-302 Q 50-302 S	WHITTIER, O D WHITTIER, O D WHITTIER, O D WICHMAN, K R WICHMAN, K R	8403230042 8403270138 8403270236 8403270046* 8403270065*	50-309 P 50-309 P 50-309 R FOIA FOIA
WZBER, M F. WEEKS, E, D. WEEKS, E, D WEIL, C. H WEINER, B, R,	8403170447 8403020006 8403300075 8403080108# 8403130236	WARTE MOT 50-199 R 50-199 R FOIA FR	WEBTAFER, OR WEBTAFER, OR WEBTAFER, OR WEBTAFER, OR WEBTAFER, OR	8403120130 8403160036 8403160315 8403200038 8403200265	50-302 P 50-302 R 50-302 P 50-302 P 50-302 P	Wicks, F. Wicks, F Wicks, F Widner, T & Wiechmann, 8 M	8403060204 8403200229 8403260156 8403130059 8403280022	50-225 F 50-225 R 50-225 R 50-387 R 50-344 J
Heinkam, e. J. Heinkam, e. J. Heise, g. Heismantle, J. Heismantle, J. A.	8403140194 8403300292 8403160385* 8403070231* 8403070158*	50-458 F 50-458 A 50-261 Q 50-322 T 50-322 T	HEBTAFER, OR HEBTAFER, OR. HEBTAFER, OR. HEBTAFER, OR. HEBTBERO, R.	8403230014 8403230062 8403270159 8403300111 8403060176*	50-302 P 50-302 P 50-302 B 50-266 G	Wiechmann, B M Wiedeman, D G Wiedeman, D, G Wiedeman, D G Wieder, A V	8403280041 8403060201 8403060210* 8403080108* 8403120185*	50-344 J 40-8830 40-8830 FDIA 50-341 Q
HEISMANTLE, J. A HEISMANTLE, J. A. HEISMANTLE, J. A HEISMANTLE, J. A. HEISMANTLE, J. A.	8403070160* 8403070171* 8403070170* 8403070175* 8403070176*	50-322 T 50-322 T 50-322 T 50-322 T	WEBTOVER, A. J WEBTPHAL, B. B. WESTPHAL, B. B WETHY, C. N. WESTERHAHN, M.	8403280054* 8403120020 8403190117 8403040340 8403040081	50-341 H 50-373 S 50-373 S 50-335 F 50-352 G	HIEHE, J Wien, B. O Wiener, J. L Wieselman, K Wiesemann, R	8403130471* 8403130249 8403270211 8403080200 8403070302*	50-320 Q PRM 50-416 H FDIA 50-423 Å
HEISMANTLE, J.A. HEISMANTLE, J.A. HEISMANTLE, J.A. HEISMANTLE, J.A. HEISMANTLE, J.A.	8403070201* 8403070204* 8403070207* 8403070211* 8403070214*	50-322 T 50-322 T 50-322 T 50-322 T 50-322 T	WETTERHAHN, M. WETTERHAHN, M. J. WETTERHAHN, M. J. WETTERHAHN, M. J. WETTERHAHN, M. J.	8403040081 8403020077 8403020125 8403020125 8403020127	50-352 G 50-352 G 50-352 G 50-352 T	Wiesemann, R.A. Wiesemann, R.A. Wiesemann, R.A. Wiesemann, R.A. Wiesemann, R.A.	8403190399* 8403210020* 8403260201* 8403290279* 8403300114*	50-413 A TOPREP 50-244 P 50-367 P 50-413 A
WEISMANTLE, J.A. WEISMANTLE, J.A. WEISMANTLE, J.A. WEISMANTLE, J.A. WEISMANTLE, J.A.	8403070220* 8403070222* 8403070227* 8403230020 8403230038	50-322 T 50-322 T 50-322 T 50-322 T 50-322 T	WETTERHAHN, M. J. WETTERHAHN, M. J. WETTERHAHN, M. J. WETTERHAHN, M. J. WETTERHAHN, M. J.	8403020129 8403020163 8403020163 8403060248 8403060248	50-352 T 50-352 o 50-352 o 50-352 o 50-352 o	Wiggins, E. J. Wiggins, J. T Wigginton, D. Wilborn, L. Wilborn, L.	8403070005 8403070319* 8403300247 8403260107* 8403260211*	CONTRACT 50-352 G 50-315 P 50-267 G 50-267 G
WEISMANTLE, J A WEISB, E R. WEISB, E, R. WEISB, E, R. WEISB, E, R.	84032300& 84030800&1 840308034& 8403210014 8403260382	50-322 T FDIA FDIA 50-289 G 50-289 G	WETTERHAHN, M J. WETTERHAHN, M J. WETTERHAHN, M, J WETTERHAHN, M, J WETTERHAHN, M J.	8403070142 8403070142 8403070236 8403070236 8403070238*	50-352 G 50-352 G 50-352 G 50-352 G 50-352 G	WILBORN,L WILCOVE,M N WILCOVE,M N, WILKIE,W H WILKIE,W,H.	8403300030* 8403140085 8403140154 8403020172* 8403130164*	50-313 Q 50-352 Q 50-327 Q 50-400 Q 50-400 Q

AUTHOR	ACCESSION NUMBER	SUBJE CATEG		ROHTUA	ACCESSION NUMBER	SUBJEC CATEGO		AUTHOR	ACCESSION NUMBER	SUBJECT CATEOORY	u .
WILKINS, W B WILKS, B L WILLIAM, P L WILLIAMS, C C	8403010082 8403020319 8403040253 8403070123*	GA979 50-387 50-387 50-461 50-373	8 5 0	Wimpy, P D Windham, R Wise, D L Wise, M J Wise, R	8403080220* 8403270013 8403080186* 8403160073 8403060184*	50-316 50-298 FO1A WASTE N	P F WOT O	WDZNIAK,DR WDZNIAK,SF WRAY,JR WRAY,JR WRIGHT,EP	8403050036 8402170107* 8403160372* 8403270320* 8403020107*	XPORTL 10 50-305 50-321	
HILLIAMS, C C WILLIAMS, D WILLIAMS, D L WILLIAMS, E H WILLIAMS, J	8403200300* 8403300030* 8403080261* 8403270108* 8403230104	50-454 50-454 50-483 50-441 50-358	0 0 1 0	HISENBURG.M R HISENBURG.M R HITHERS.B D HITHERS.B D HITHERS.B D	8403140151 8403190289 8403040382 8403140137 8403190325	PR PR 50-344 PR 50-344	P P	WRIGHT, E G WRIGHT, E C, WRIGHT, E G WRIGHT, E G WRIGHT, G	8403020124* 8403020180* 8403020194* 8403020224* 8403190299*	FOIA FOIA FOIA FOIA 50-373	œ
WILLIAMS, J H	8403060168 8403010322* 8403150063* 8401130182 8401130294	50-250 50-277 50-277 50-389 50-335	P G B P	WITHERS, B D WITHERS, B D WITHERS, B D WOESSNER, J D WOHLD, P R	8403200141 8403200197 8403300168 8403130499* 8403080261*	50~344 50~344 50~344 50~312 50~483	G P G G	A NITHDIRW A NITHDIRW A NITHDIRW A NITHDIRW U RITHDIRW U	8403140105 8403210067 8403210076 8403300129 8403220205	50-352 50-352 50-352 50-352 HABTE MOT	0 0 0 0
WILLIAMS, J W WILLIAMS, J W WILLIAMS, J W WILLIAMS, J W	8401130319 8402270125 8403010297 8403010302+ 8403010400	50-389 50-250 50-389 50-389 50-389	운 S P P	MOTEE'S 7 MOTEE'S 8 MOTMENICX'I MOTMES'E 7	8403020342* 8403020357* 8403270089 8403140244 8403060182	50-247 50-284 50-237 50-483 50-289	0 8 F 0	WRIGHT, 8 V WU, P. C WU, P. C WULLER, G. E WYNGARDEN, S. D	8403010341 8403170189* 8403210173* 8403240129* 8403070317	27-48 50-289 50-289 40-1478 40-6940	90
WILLIAMS, J W WILLIAMS, J W WILLIAMS, J W WILLIAMS, J W WILLIAMS, J W	8403020033 8403020258 8403020278 8403020288* 8403040112	50-250 50-387 50-250 50-250 50-335	R S V G F	WOLFE, S J WOLFE, S J WOLFE, S J WOLFE, S J WOLFE, S J	8403060243 8403140002 8403140030 8403260332 8403260337	50-289 50-482 50-482 50-289 50-289	G G G G	HYNVEEN,R A YAMADA,K YANG,C Y YANICHKO,S E YANICHKO,S E	8403190317 8403010467* 8403190404* 8403060326* 8403090259*	50-213	A P P
WILLIAMS, J W W L. RMAILLIW W L. RMAILLIW W L. RMAILLIW W L. RMAILLIW	8403040186 8403060241 8403060291 8403060390 8403070034	50-389 50-389 50-250 50-389 50-335	F P Q S Q	WDLFE,8 J WGLLETT,8 WOLLETT,8 WOLLETT,8 WOLTNER,E	8403280334 8403010070 8403260323 8403270365 8403210054*	50-482 CONTRAC CONTRAC CONTRAC 50-320	7	YEDVAB, J YDDER, R C YDRE, J, R. YDUNG, F. YDUNG, F	8403230038 8403140151 8104210125* 8403010030* 8403070287*	PR 50~400	T Q P
HILLIAMS, J W WILLIAMS, J W WILLIAMS, J W WILLIAMS, J W WILLIAMS, J W	8403070249 8403080020 8403080164 8403070280 8403120040	50-389 50-250 50-335 50-389	0 У F Р	HOLTNER, E HONG, G HONG, G HONG, G	8403210105* 8403020120* 8403020166* 8403020183* 8403280177*	50-334 FOIA FOIA FOIA FOIA	Q	YDUNG, K YDUNG, M YDUNG, T, YDUNG, T YDUNG, T	8403200121 8403230208 8403080243* 8403080274* 8403080279*	NURE9 50-528 50-312	F G G
MITCIAWS'O M MITCIAWS'O M MITCIAWS'O M MITCIAWS'O M	8403120089 8403130035 8403130066 8403160013 8403160038	50-387 50-387 50-335 50-387 50-251	р 9 Р 8	HONG. 6 C. HODD. D C HODD. D C	8403020232* 8403280188* 8403140011 8403140018 8403260226	FOIA FOIA 50-387 50-387 50-387	8 8	AONWOBFOOD' B ? AONWOBFOOD' B ? AONWO' A AONWO' I	8403270139* 8403220228 8403140283 8401120437* 8403010017	WABTE MOT 50-482 50-445	G A A E
WILLIAMS, J W WILLIAMS, J W WILLIAMS, J W WILLIAMS, J W WILLIAMS, J W	8403160058 8403160067 8403170227 8403170386 8403200264	50-250 50-251 50-369 50-335 50-250	9 9 F P	WOODHEAD, C. WOODHEAD, C. P WOODHEAD, C P WOODHEAD, C P WOODHEAD, C P	8403140064 8403010248 8403140176 8403140010 8403170015*	50-142 50-142 50-440 50-142 50-142	0 0 0 0	YOUNGBLOOD, B J YOUNGBLOOD, B J YOUNGBLOOD, B J YOUNGBLOOD, B J	8403020148 8403020158 8403020164 8403020198 8403020289	50-423 50-341 50-454	A A A F E
WILLIAMS, J W WILLIAMS, J W WILLIAMS, J W WILLIAMS, J W WILLIAMS, J W	8403220070 8403220104 8403260203 8403270247 8403280110	50-335 50-250 50-250 50-335 50-250	9 9 F F	WOODHEAD, C. P WOODHEAD, C P WOODHEAD, C P WOODHEAD, C P WOODRUFF, R	8403190042 8403190044 8403190157 8403210027 8403010151*	50-250 50-440 50-142 50-142 FOIA	Q Q Q Q	AONABEGOD' B ? AONABEGOD' B ? AONABEGOD' B ? AONABEGOD' B ?	8403050273 8403050353 8403040431 8403070130 8403070363	50-483 50-445 50-423	A A G E F
HILLIAMS, J W W L. SMALLIIW W LEMALLIIW M LEMALLIIW H M LEMALLIIW	8403270114* 8403270123 8403300173 8403010030* 8403010023*	50-335 50-250 50-250 50-269 50-269	о о к Р	WODDRUFF, R WOODRUFF, R WOODRUFF, R WOODRUFF, R WOODRUFF, R L	8403010164* 8403010184* 8403010205* 8403210133 8107140213*	FOIA FOIA FOIA I&E FOIA		YOUNGBLOOD, B J.	8403070308 8403120247 8403120315 8403120320 8403120320	50-483 50-482 50-423	A A A A
WILLIAMS.R E WILLIAMS.R E WILLIAMSON.H E WILLIAMSON.H E WILLIAMSON.H E	8403070046* 8403270276 8403080220* 8403080220* 8403200101*	CDNTRAC1 PR 50-316 50-316 50-316	P P P	HOODRUFF, R W HOODRUFF, R W HOODRUFF, R, W HOODRUFF, R W, HOODRUFF, R W	8107160215* 8202120295* 9309150400* 8403010127* 8403010131*	FOIA FOIA FOIA FOIA		YOUNGBLOOD, B J YOUNGBLOOD, B J YOUNGBLOOD, B J YOUNGBLOOD, B J	8403140288 8403140273 8403170421 8403260067 8403260277	50~445 50~482 50~445	E A Q A
MITSON' B D MITSON' B D MITSON' B D	8403230028 8403010084 8403010478 8403010479 8403010322	50-389 XPORTLIC XPORTLIC XPORTLIC		WOODRUFF, R W	8403010138* 8403010161* 8403010178* 8403010252* 8403010257*	FOIA FOIA FOIA FOIA		YOUNGBLOOD, B. J. YOUNGBLOOD, B. J. YOUNGBLOOD, R. YOUNGBLOOD, R. W.	8403270345 8403280237 8403270357 8403230133 8403010041*	50-341 50-440	E A E P
WILSON, B D WILSON, B D WILSON, B D WILSON, B D	8403010539 8403010540 8403010546* 8403020089 8403050039	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC		HDODRUFF, R W WOODRUFF, R W WOODS, T O WOODSUM, H C WOOLEVER, E J	8403050266* 8403050270* 8402140028* 8403010324 8403010387	FOIA FOIA 50-528 70-1143 50-412	g A	YUHAS, 0 P. YUNDT, C. P. YUNDT, C. P. YUNDT, C. P. YUNDT, C. P.	8403170373* 8403010355 8403020050 8403260216 8403300106	50-344 50-344 50-344	0 8 8 8
WILSON, B D WILSON, D L WILSON, D L	8403050261 8403070353 8403200047 8403200051 8403200121	XPORTLIC XPORTLIC 50-331 50-331 50-331	F F	WODLEVER, E J WODLEVER, E J WOOLEVER, E, J WOOLEVER, E, J,	8403070298 8403070308* 8403130374 8403150095 8403160090	50-412 50-412 50-412 50-412 50-412	8 G B C A	ZABEL: B A ZAHLER: R. E. ZAHLER: R. E ZAHLER: R. E. ZAHLER: R. E	8403070123* 8403080140 8403080140 8403260345 8403260345	50-440 50-440 50-289	0 H H 0 0
WILSON, D. L. WILSON, E. F. WILSON, J. WILSON, J. WILSON, J.	8403200183 8403140149 8403020059* 8403280125 8403300060	50-331 PR 50-280 50-280 50-280	F R F R	WOOLEVER, E J WOOLEVER, E J WOOLEVER, E, J WOOLEVER, E, J WOOLEVER, E, J	8403160170 8403170152 8403200234 8403210058 8403210130	50-412 50-412 50-412 50-412 50-412	A A A 8 8	ZAHNLEUTER, R J ZAHNLEUTER, R J ZAHNLEUTER, R J. ZAHNLEUTER, R J ZAHNLEUTER, R. J	8403020123 8403040212 8403130043 8403130085 8403210179	50-322 50-322 50-322	e T e e
HILSON, J. H HILSON, J. H HILSON, J. L WILSON, J. U WILSON, J. W,	8403050269 8403280062 8403090223 8403090250 8403130424	50-382 50-382 50-280 50-280 50-280	A A S S	WOOLEVER, E. J WOOLEVER, E. J WOOLEVER, E. J WOOLEVER, E. J WOOLSEY, R. T	8403260059 8403290145 8403290204* 8403300200 8403190443	50-412 50-412 50-412 50-412 40-2259	с с а	ZAHNLEUTER, R J ZAHNLEUTER, R J ZAHNLEUTER, R J ZERBE, J E ZEUGIN, L, B	8403210188 8403210201 8403260338 8403010283* 8403130082*	50-322	0 0 T

AUTHOR	ACCESSION NUMBER	BUBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
ZEUGIN, L B	8403130082* 8403130077* 8403130097* 8403150004 8403150004	50-322 0 50-322 0 50-322 0 50-322 0	ZUKOR, D. J. ZUPKO, J. M.	8403150181 8402100196 8403080013 8403080246 8403080252	50-327 50-272 50-272 50-272 50-272
ZIBULSKY, H ZIBULSKY, H ZIBULSKY, H ZIELONKA, J S ZIMMERMAN, J,	8403010314* 8403150078* 8403290120* 8403290259 8403200394	50-352 Q 50-272 Q 50-387 Q PRM XPORTLIC	ZUPKO, J M ZUPKO, J M ZUPKO, J H ZUPKO, J H	8403130384 8403220037 8403220142 8403220151 8403220174	50-311 50-311 50-311 50-311 50-272
zimmerman, j zimmerman, j zimmerman, j zimmerman, j zimmerman, j	8403220283 8403220284 8403220287 8403220279 8403220304	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	ZUPKO,J M ZUPKO,J H ZURAKOHSKI,P R	8403270099 8403270244 8403270221*	50-311 50-272 70-1257
ZIMMERMAN, J ZIMMERMAN, J ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V	8403220314 8403220315 8403010338 8403010344 8403010344	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC			
ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V	8403010369 8403010418 8403010421 8403010425 8403010432	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC			
ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V	8403010479 8403010491 8403010495 8403010502 8403020015	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC			
ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V	8403020151 8403020154 8403020451 8403050026 8403050045	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC			
ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J, V	8403050188 8403050190 8403050193 8403050209 8403050213	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC			
ZIMMERMAN, J V ZIMMERMAN, J. V ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V	8403050276 8403050282 8403050286 8403050320 8403050358	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC			
ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V	8403050359 8403050368 8403060035 8403060038 8403060087	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC			
ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V.	8403070004 8403070377 8403070424 8403080115 8403140229	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC			
ZIMMERMAN, J V ZIMMERMAN, J V, ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V	8403140307 8403140315 8403150129 8403150174 8403150241	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC			
ZIMMERMAN, J, V. ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J, V	8403200378 8403220201 8403230179 8403280050 8403280147	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC			
ZIMMERMAN, J V ZIMMERMAN, J, V ZIMMERMAN, J V, ZIMMERMAN, J V ZIMMERMAN, J, V,	8403280200 8403280252 8403280272 8403280327 8403290325	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC			
ZIMMERMAN, J V ZIMMERMAN, J, V, ZIMMERMAN, J V ZIMMERMAN, B R ZIMMERMAN, B R	8403270340 8403270403 8403300311 8403060167 8403070176	XPORTLIC XPORTLIC XPORTLIC 50-324 P PR			
ZIMMERMAN, BR ZIMMERMAN, BR ZIMMERMAN, BR. ZIMMERMAN, BR. ZIMMERMAN, BR.	8403210061 8403210075 8403210116 8403280024 8403290083	50-324 P 50-324 P 50-261 P 50-400 M 50-324 P			
ZITBER, B. B. ZITZER, P. ZUKOR, A ZUKOR, D. J ZUKOR, D. J	8403140025 8403280334 8403150183* 8211110514 8402270314*	50-443			

A			

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

######################
Cleveland Co S403202042 50-289 Vanced Mpdical Systems, Inc 8403010077 6A999 Vanced Technology, Inc 84030400192* FOIA FOIA 8403120314* FOIA FOIA 8403120314* CONTRACT FOID 8403120324* CONTRACT FOID 8403120314* CONTRACT
Cleveland Co Vanced Medical Systems, Inc Vanced Trchnology, Inc ### Hospital Systems, Inc Wanced Trchnology, Inc ### Hospital Systems, Inc Wanced Trchnology, Inc ### Hospital Systems, Inc ### Hosp
Vanced Medical Systems, Inc 8403020400 FOIA 8403060152* FOIA 8403060152* FOIA 8403120314* FOIA FOIA 8403120314* CONTRACT 8403120345* CONTRACT 8403120345* CONTRACT 8403200371 XPORTLIC 8403200371 XPORTLIC 8403200371 XPORTLIC 840320026* SO-352 8403220226* SO-352 8403220227* SO-352 8403220227* SO-352 8403220227* SO-352 8403220227* SO-352 8403220227* SO-352 8403220237* SO-352 840329037* SO-352 8403010127* SO-348 8403010141* SO-348 8403010141* SO-348 8403010141* SO-348 8403010146* SO-348
Vanced Trchnology, Inc 8403040152* FGIA 8403040154* FGIA 8403120348* FGIA 8403120348* FGIA 8403120348* FGIA 8403120348* FGIA 8403120348* FGIA 8403200371 FFORTLIC 8403200371 FFORTLIC 8403200151* FORTLIC 8403200151* FORTLIC 8403200224 FORTLIC 8403200234 FORTLIC 8403200234 FORTLIC 840320034 FORTLIC 840320034 FORTLIC 840320034 FORTLIC 840320034 FORTLIC 840320037 FOR
Products & Chemicals, Inc ### Section
riculture, Dept of, Graduate School 8403120314* CONTRACT 8403120345* RATRACT 8403200371 RDRILECT Products & Chemicals, Inc 8403200371 RDRILECT 8403280151* XPORTLIC 8403280151* XPORTLIC RATE RATE RATE RATE RATE RATE RATE RATE
Products & Chemicals, Inc ### 8403120345
r Products & Chemicals, Inc 8403240371
B403280151* XPORTLIC ### Polition Patrol
r and Water Pollution Patrol 8403220226 50-352 8403220226 50-352 8403220227 50-352 8403220227 50-352 8403220227 50-352 8403220227 50-352 8403220227 50-352 840320237 50-352 840320237 50-352 840329037 50-352 840329037 50-352 840329037 50-352 840329037 50-352 840329037 50-352 840329037 50-352 840329037 50-352 8403010127 50-348 8403010141 50-348 8403010141 50-348 8403010146 50-348
Power Co ####
Power Co ## ## ## ## ## ## ## ## ## ## ## ##
8403280289* 50-352 8403280234* 50-352 8403280234* 50-352 8403290378 50-352 8403290378 50-352 8403290379 50-352 8403290377 50-352 8403010127* 50-348 8403010141* 50-348 8403010146* 50-348
B403280234* 50-352 B403280234* 50-352 B403290378 50-352 B403290379 50-352 B403290377 50-352 B403290377* 50-352 B403010127* 50-348 B403010141* 50-348 B403010146* 50-348
B403220234* 50-352 B403290378 50-352 B403290379 50-352 B403290397 50-352 B403290397* 50-352 B403290397* 50-352 B40301012** 50-348 B40301014* 50-348 B403010146* 50-348
B403290378 50-352 B403290379 50-352 B403290395 50-352 B403290397* 50-352 B403010129* 50-348 B403010141* 50-348 B403010146* 50-348
B403290378 50-352 B403290395 50-352 B403290397* 50-352 abama Power Co B403010129* 50-348 B403010137* 50-348 B403010141* 50-348 B403010146* 50-348
8403290395 50-352 8403290397* 50-352 8403010127* 50-348 8403010141* 50-348 8403010146* 50-348
abema Power Co 8403010127* 50-352 8403010127* 50-348 8403010141* 50-348 8403010141* 50-348 8403010146* 50-348
abama Power Co 8403010127# 50-348 8403010137# 50-348 8403010141# 50-348 8403010146# 50-348
8403010137* 50~348 8403010141* 50~348 8403010146* 50~348
8403010141* 50-348 8403010146* 50-348
8403010146* 50-348
9403010142* 50-349
B403010152# 50~34B
8403010156# 50-348
8403010156* 50~348
9403010163* 50-34B
8403010417 50-364
8403010422* 50-364
8403010428* 50-364
8403040125 50-348
8403040125 50-348
8403090077 50-348
8403080077 50-348
8403080081 50-348
8403080081 50-348 8403080086* 50-348
8403080086* 50~348
840308014B 50~34B
840308014B 50~34B
8403080148 50~348 8403080158 50~348
8403080158 50-34B
8403080195* 50~348 8403080195* 50~348
8403080272 50~348 8403080272 50~348
8403090255 50-348
8403090303 50~34B
840313 00 31 50∽348
8403130031 50- 348
8403130038* 50~348

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	840313003B* 8403130455 8403130455 8403130463*	50-348 50-348 50-348 50-348
	B403130463*	50-348
	8403140210 8403140212	50-348 50-348
	Ø403150055	50-349
	8403150084	50-348
	8403160265*	50-34Ø
	8403230134 8403260017	50-348 50-348
	B403260024	50-348 50-348
	8403260032*	50~348
	8403260040*	50-348
	#403260046#	50-348
	8403260227	50-349
	8403260227	50-349
	9403260234* 9403260234*	50-348 50-348
	PTUJEOUEST#	00-37B
	@403280037	50-346
	0403280037	50-34B
	6403260044*	50-346
	0403280044# 0403280109	50-348 50-348
	640326017B	50-348 .
	#4032700B4*	50~348
	Ø403290319	50-346
	Ø403300077	50-348
	B403300134	50-364 .
	8403300172	50~348
Alaska, Univ of Fairbanks	6403270311	PRM
Allied Chemical Corp.	8403230097	40-3372
	8403230100# 8403210012	40-3392 PR
American College of Radiology		
American Nuclear Corp.	8403200325* 8403220045	40-4472 40-4472
American Sociaty of Mechanical Engineers	B403010045*	CONTRACT
Anaconda Co. (subs. of Atlantic-Richfield		94 777
Co.) Analysis & Technology, Inc.	8403040495×	CONTRACT
Anchor/Darling Valve Co (subs of	B403120114#	GA99 9
Anchor/Darling Industries, Inc.)	8403270097*	0A999
Anthony, R. L.	8403190132	50~352
•	8403190138*	50-352
	8403190142*	50-353
Applied Radiation Protection Services	8403090178	PR
White sentential Classerson estates	8403090183*	PR
Applied Science Associates, Inc	6403300325	NUREO
Argonne National Laboratory	8403070114	NUREO
	8403140339	ACRE
	8403190317	PR
	B403300261	NUREO
	8403300285	NUREO

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC		AUTHOR AFFILIATION	ACCEBBION NUMBER	BUBJECT CATEGORY
Arizona Public Service Co	8402140028* 8402140032* 8402140037* 8402140052* 8402270008	50-528 50-528 50-528 50-528 50-528	() () () () ()		840305015B 6403040199 8403040203* 8403040205* 8403040308	50-313 P 50-313 P 50-313 Q 50-313 P 50-313 R
	8402270008 8402270008 8403010212 8403010212	50-528 50-528 50-528 50-528 50-528	8 A A A		8403060324 8403060350 8403060430 8403060430 8403090139	50-313 F 50-313 F 50-313 F 50-313 F 50-368 S
	8403020005 8403090012 8403090012 8403090012 6403090077	50-528 50-528 50-528 50-528 50-528	6 6 8		8403090179 8403090301 8403120011 8403120011 8403130024	50-313 P 50-313 F 50-313 F 50-313 F 50-368 8
	8403070087 8403070087 8403070087 8403070094 8403070094	50-528 50-528 50-528 50-528 50-528	9 9 9 9 9		8403130324 8403130347 8403130437 8403130473 8403150037	50-368 8 50-368 8 50-313 0 50-313 F 50-313 P
	8403090096 8403090122 8403090167 8403090167 8403090167	50-528 50-528 50-528 50-528 50-528	8 8 8		8403150041* 8403200174 8403200179 8403200179 8403200180*	50-313 P 50-313 F 50-313 F 50-313 F 50-313 F
	8403090197 8403090197 8403090258 8403090258 8403090258	50-528 50-528 50-528 50-528 50-528	8 8 9 9		8403200180* 8403200181* 8403200181* 3403200244 8403200251*	50-313 F 50-313 F 50-313 F 50-313 F
	8403120032 8403120032 8403120032 8403120049 8403120049	50-528 50-528 50-528 50-528 50-528	9 8 9 8		8403200251* 8403200258* 8403200258* 8403220020 8403220020	50-313 F 50-313 F 50-313 F 50-368 9 50-313 P
	8403120049 8403120113 8403130449 8403130449 8403130449	50-528 50-528 50-528 50-528 50-528	9 9 9 9		8403260051 8403260051 8403260137 8403260157* 8403260157*	50-313 P 50-313 P 50-368 Q 50-313 P 50-313 P
	B403130461 B403130461 B403130461 B403140024 B40316004B	50-528 50-528 50-528 50-528 50-528	9 9 0 A		8403270258 8403280074 8403280094 8403290127 8403300068	50-368 B 50-313 F 50-313 F 50-368 S 50-313 R
	8403160048 8403160048 8403160052* 8403160052* 8403160052*	50-528 50-528 50-528 50-528 50-528	A A A A	Arkonsas, State of Army, Dept of Army, Dept of, Corps of Engin Aspen Bystems, Inc	9403300164 9403140149 9403210107 9403280052* 9403070379*	50-368 R FR FRM CONTRACT CONTRACT
	84031 60065 84031 60065 84031 60065 84031 90387 84032001 15	50-528 50-528 50-528 PR 50-528	A A A S	Atlas Minerals, Inc	8401120171 8401120180# 8403150242 8403150264 8403150280	40-3453 40-3453 40-3453 40-3453 40-3453
	8403200115 8403200160 8403200160 8403200186 8403200226	50-528 50-529 50-529 50-528 50-528	9 9 9	Atom Sciences, Inc Atomic Industrial Forum Australia, Govt of	8403230267 8403300312* 8403170317 8403220264 8403220279	40-3453 CONTRACT PR XPORTLIC XPORTLIC
	8403200226 8403200226 8403230006 8403230019 8403230039	50-528 50-528 50-528 50-528 50-528	9 9 9	Automation Industries, Inc BWR Owners Group	8403210001 8403210005+ 8403210010+ 8403300008 8403020226	40-6920 40-6920 40-6920 40-6920 Toprep
	8403230039 8403230039 8403230086 8403230099 8403230099	50-528 50-528 50-530 50-528 50-528	8 8 8	Babcack & Wilcox Co	8403120127 8403200127 8401240315* 8403010162 8403010164*	TOPREP TOPREP 70-27 71-4206 71-6206
	8403230099 8403230113 8403230132 8403240014 8403240014	50-528 50-528 50-529 50-528 50-528	9 9 F		8403020167 8403050110* 8403050114* 8403050118* 8403070149*	70-27 50-346 F 50-346 F 50-346 F 70-27
	8403260014 8403270236 8403300020 8403300020 8403300020	50-528 50-528 50-528 50-528 50-528	F A 9 8		8403070153* 8403130058* 8403130076* 8403190241 8403190246*	70-27 GA979 GA979 TOPREP TOPREP
Arizona, State of Arkansas Power & Light Co	8403300076 8403090106 8403290263 8403020075 8403020081	50-528 PR PR 50-313 50-368	R R	Babcock & Wilcox Operating Plan Group Bailey Controls Co (subs. of Ba Wilcox Co)		70-27 TOPREP TOPREP GA997

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEODR'
Baltimore Qas & Electric Co	8403200076+ 8403020300 8403020346+ 8403050078 8403060109	QA999 50-917 50-317 50-318 50-318	F G P B	Bechtel Corp	8403150245 8401130363 8403050100* 8403060228* 8403070014*	40-8452 TOPREP 50-318 GA999 50-528
	8403060263 8403060263 8403060400 8403060400 8403130039	50-317 50-317 50-317 50-317 50-318	P P P 명		8403090020 8403120015* 8403120015* 8403120017* 8403120017*	F01A 50-275 50-275 50-275 50-275
	8403130081 8403130078 8403130252 8403130277 8403130275	50-318 50-317 50-317 50-317 50-317	9 9 8 9	Bendix Corp	8403120023* 8403120030* 8403130284 8403230108 8403020374	50-275 50-388 GA999 50-482 WASTE MOT
	8403130299 8403130305 8403130305 8403130314* 8403130314*	50-317 50-317 50-317 50-317 50-317	8 R R R	Bergen Pines Hosp Paramus, NJ Binder, Elster, Mendelson & Wheeler, Inc Biotechnica International, Inc	8403200356 8403220225 8403230038 8403010044* 8403140221	WASTE MGT WASTE MGT 30-322 CONTRACT PRM
	0403130322* 0403130334* 0403130334* 0403130356 0403130413	50-317 50-317 50-317 50-317 50-318	R R R S S	Bishop, Liberman, Cook, Purcell & Reynolds	8403070048 8403120007 8403140013 8403140013	50-413 50-50B 50-445 50-445
	8403130426 8403130450 8403140036 8403140228 8403150049	50-317 50-318 50-317 50-317 50-317	8 9 J F 0		8403140020 8403140020 8403150032 8403140029 8403200007	50-445
	8403150047 8403150071 8403150110 8403150110 8403150155	50-317 50-317 50-317 50-317 50-317	Q F F F		8403210172 8403210189 8403240367 8403240367	50-50B (50-50B (50-50B (50-413 (50-445 (
	8403150155 8403160040 8403160040 8403190018 8403190018	50-917 50-317 50-317 50-317 50-317	F የ የ	Blanchard Valley Hosp Findlay, DH Borg-Warner Corp Boston Edison Co	8403080204* 8403020079 8403150158 8403010324 8403010327*	FOIA XPORTLIC XPORTLIC 50-293 , 50-293 ,
	8403190023* 8403190023* 8403190408 8403200003 8403200003	50-317 50-317 50-317 50-317 50-317	F G R R		8403070341* 8403070047 8403070147 8403070152 8403120027	50-293 (50-293 (50-293 (50-293 (
	8403220052 8403220052 8403220080 8403240112* 8403240234	50-317 50-317 50-317 50-317 50-317	F F G G P		8403130255 8403140107 8403140279* 8403150008 8403150117*	50-293 , 50-293 , 50-293 , 50-293 , 50-293 ,
Battelle Human Affairs Research Centers	8403260248* 8403300070 8403300100 8403300102 8403070107	50-317 50-317 50-317 50-317 NUREO	P P S F		8403150177 8403200164 8403260317* 8403270010 8403270015*	50-273 P 50-273 P 50-273 P 50-273 P 50-273 P 50-273 P
Battelle Memorial Institute, Columbus Laboratories	8403190055 8403050227 8403050230 8403050242 8403060502*	NUREO RES 50-280 RES CONTRACI	t.	Boston Univ Medical Center, Boston, MA Brandeis Univ Waltham, MA Braunkohle Transport & Storage, Inc	8403270055 8403270143* 8403130218 8403150134 8403150142*	50-293 P 50-293 P PR PRH XPGRTLIC XPGRTLIC
Battelle Memorial Institute, Pacific	8403120R57 8403230130* 8403300294 8403010041*	RES CONTRACT NUREO FOIA		Bristol Steel & Iron Works, Inc. Brookheven National Laboratory	B403270148 8308170191* 8403010041* 6403010217* 6403010227*	0A777 50-447 A FOIA 50-327 A 50-327 A
Northwest Laboratories	8403020216 8403070073 8403070109 8403070118 8403140170*	NUREQ NUREQ NUREQ PR			6403010227* 8403010231* 8403010231* 8403070115 8403230133	50-329 A 50-329 A 50-329 A NUREO 50-313 P
	8403140131 8403190055 8403190449 8403230112*	OEN TEC NUREO NUREO 50-219	R	Brown Boveri Corp (subs of Brown Boveri & Co., Ltd)	8403260022* 8403260061* 8402010185*	50-454 A 50-454 A GA979
	8403230173 8403230177	NUR EQ		Buffalo, NY	840327021 <i>9</i> 8403080136	50-206 B 50-410 G
Bear Creek Uranium Co.	8403230200 8403230207 8403300132* 8403300248 8403150102	NUREO NUREO 50-478 WASTE MO 40-8452		Businessmen for the Public Interest C-E Operating Plants Owners Group CONOCO, Inc. (Continental Oil Co.)	8403060079 8403260351 8403130277 8403140131 8403190317	50-454 G 50-454 G TOPREP TOPREP PR
Bearfoot Corp.	8403170436 8403150226 8403150235	40-8452 40-8452 40-8452		California Institute of Technology. Pasadena, CA California, State of	8403260088# 7906140548#	50-344 P 50-312 P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEOD	
	8403020117* 8403060240 8403090104 8403240111* 8403270347	50-133 50-275 PR 50-275 50-275	F 0 U		8403090176 8403090205 8403090235 8403090252 8403090252	PR 50-325 50-324 50-324 50-324	8 P P
	8403270347 8403270352 8403270352 8403270366 8403270366	50-275 50-275 50-275 50-275 50-275	G G G P P		8403090260# 8403090260# 8403120039 8403120076 8403120084	50-324 50-324 50-329 50-400 50-400	Р 6 6 8
California, Univ of, Berkeley, CA California, Univ of, Los Angeles, CA Callaway County, MO	8403150115 8403140089 8403260380 8403280241 8403070081	50-224 50-142 50-142 ACRS 50-483	R C G F		8403130049 8403130062 8403130078 8403130093 8403130152	50-325 50-400 50-324 50-261 50-324	\$ \$ \$ 8
Callendine, G W Cardinal Industrial Products Corp Carolina Environmental Study Group	8101300020* 8101300025* 8403190203 8403070033 8403070033	FOIA FOIA GA999 50-413	a		8403130156 8403130156 8403130164* 8403130164* 8403130237	50-400 50-400 50-400 50-400 50-400	0 0 0
	8403070037* 8403070037* 8403220233 8403220237 8403290379	50-413 50-413 50-413 50-413 50-413	e o o o		8403130301 8403130301 8403130323 8403130333 8403130333	50-324 50-324 50-325 50-324 50-324	9 8 R
Carolina Power & Light Co	8403270369 8402230251 * 8402270274 8402270081 8402270081	50-413 50-400 50-400 50-400 50-400	G A B G G		8403130398 8403130406 8403130447 8403130447 8403130452	50-400 50-324 50-400 50-400 50-325	8 9 9 P
	8403010133 8403010135 8403010202 8403010263 8403010263	50-325 50-324 50-325 50-400 50-400	8 8 9 9		8403130459* 8403130459* 8403130465* 8403140120 8403140125*	50-400 50-400 50-325 50-400 50-400	9 9 F F
	8403010299 8403010350 8403010394 8403010395 8403020182	50-324 50-400 50-400 50-324 50-400	S S S S S		8403140174 8403140178* 8403150028 8403150035 8403150070	50-400 50-400 TOPREP 50-325 50-324	9 8 8
	8403020182 8403020188* 8403020188* 8403020192* 8403020192*	50-400 50-400 50-400 50-400 50-400	0 G G		8403150078 8403150161 8403150163* 8403150177 8403150186	50-261 50-261 50-261 50-324 50-324	8 P 8 8
	8403060140 8403060140 8403060167 8403060167 8403060296	50-324 50-324 50-324 50-324 50-324	թ թ թ		8403160018 8403160262# 8403190065 8403190137 8403190137	50-400 50-261 50-400 50-400 50-400	9 F 9
	8403040294 8403040300 8403040302* 8403040302*	50-324 50-324 50-324 50-324 50-324	P P P P		8403190141* 8403190141* 8403190302 8403200030 8403200030	50-400 50-400 50-325 50-400 50-400	9 9
	8403070051 8403070051 8403070055 8403070055 8403070058#	50-400 50-400 50-400 50-400 50-400	G Q Q G G		8403200033 8403200033 8403200117 8403200117 8403200135	50-324 50-324 50-400 50-400 50-400	F Q Q
	8403070058* 8403070059* 8403070059* 8403070095* 8403070096*	50-400 50-400 50-400 50-400 50-400	e G G G		8403200135 8403200203 8403200207 8403200245 8403200273	50-400 50-400 50-324 50-261 50-324	9 9 F
	8403070106# 8403070108# 8403070134 8403070134 8403070157	FOIA FOIA 50-400 50-400 50-324	0 0 P		8403210061 8403210061 8403210075 8403210080# 8403210093	50-324 50-324 50-324 50-324 50-261	P P P P
	8403070137 8403070162* 8403070162* 8403070184* 8403070200	50-324 50-324 50-324 50-400 50-324	P P Q Q		8403210116 8403210123 8403210129 8403210129 8403210131	50-261 50-324 50-324 50-324 50-400	P 9 P A
	8403070225 8403070225 8403070285 6403070290 8403070315	50-400 50-400 50-400 50-400 50-325	0 0 8 8 0		8403210139 8403220261 8403230049 8403230054#	50-325 50-400 50-400 50-325 50-325	9 0 0 P P
	8403080135 8403080258 8403090023 8403090082 8403090094	50-261 50-261 50-324 50-400 50-261	R R S S F		8403230127 8403260009 8403260024 8403260327 8403260327	50-26) 50-400 TOPREP 50-400 50-400	F H O O

AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEGOS		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8403260326 8403260326 8403260346 8403260348 8403260354*	50-400 50-400 50-400 50-400 50-400	9 0 0 0	Citizens Concerned About Nuclear Power,	8403200147 8403200147 8403140152 8403270025	50-445 50-445 50-498 50-498
	8403260354* 8403270091 8403270235 8403270239* 8403270266	50-400 50-400 50-261 50-261 50-324	9 8 P P 9	Clark Oil & Refining Corp Cleveland Electric Illuminating Co	8403080033# 8402290274 8403020106 8403020106 8403060181	FOIA 50-440 50-440 50-440 50-440
	8403270327 8403280024 8403270083 8403270134 8403270166*	50~400 50~400 50~324 50~400 50~400	Q M P E G		8403060181 8403060257 8403060257 8403060275 8403060275 8403060280*	50-440
Carpenter Technology Corp Center for Law in the Public Interest	8403300034 8403300043 8403050036 8403070128 8403080118	50-400 50-400 XPORTL IO 50-275 50-275	B C C C		8403060280* 8403080140 8403120052 8403120096 8403120096	50-440 50-440 50-440 50-440 50-440
	8403090027 8403190011 8403190011 8403190016* 8403190016*	50-275 50-275 50-275 50-275 50-275	P 9 0 0		8403120124* 8403130010 8403130010 8403130092 8403130106*	50-440 (50-440 (50-440 (50-440 (
	8403220106 8403220106 8403220110* 8403220110* 8403260368	50-275 50-275 50-275 50-275 50-275	G G G G		8403130104* 8403130118* 8403130118* 8403130128* 8403130128*	50-440 / 50-440 / 50-440 / 50-440 /
Center for Nuclear Responsibility	8403070135 8403070135 8403070139* 8403070139* 8403070143*	50-250 50-250 50-250 50-250 50-250	0 0 0 0		8403130138* 8403130138* 8403130139 8403130139 8403130194	50-440 ^ 50-440 f 50-440 f 50-440 g
	8403070143# 8403140017 8403140017 8403140023# 8403140023#	50-250 50-250 50-250 50-250 50-250	0 0 0 0		8403130194 8403130403 8403130403 8403150001 8403150009	50-440 F 50-440 G 50-440 G 50-440 G
Cerac. Inc Chem-Nuclear Systems: Inc	8403010459 8401120525 8401120550* 8403120156* 8403120156*	XPORTLIC HABTE MG HABTE MG 50-413 50-413	OT OT E E		8403150009 8403190051 8403190051 8403190375 8403190375	50-440 9 50-440 S 50-440 S 50-440 A
Cincinnati Gas & Electric Co Cincinnati, Univ of, Hosp., Cincinnati, OH	8403120161* 8403150316 8403210178 8403230104 8403290259	50-413 27-47 50-358 50-358 FRM	E 0 9		8403190391 8403190391 8403230011 8403230011 8403230045	50-440 A 50-440 A 50-440 S 50-440 S 50-440 S
Citizens Association for Sound Energy	8403070177 8403070177 8403070181* 8403070182* 8403070182*	50-445 50-445 50-445 50-445 50-445	0 0 0 0		8403230045 8403230047 8403230083 8403230083 8403230101	50-440 S 50-440 A 50-440 S 50-440 S
	8403090104 8403090104 8403090108* 8403090128 8403090128	50-445 50-445 50-445 50-445 50-445	T T T C		8403230101 8403260247 8403260247 8403270224 8403270224	50-440 9 50-440 9 50-440 9 50-440 0
	8403140034 8403170006 8403170024 8403170024 8403170032	50-445 50-445 50-445 50-445 50-445	G G G G	Clinton, IL Coalition for Bafe Power Colorado State Univ , Ft Collins, CD Colt Industrios, Inc.	8403140040* 8403220049 8403130394 8403230032 8403190248	50-461 9 50-460 9 50-267 R 50-322 T 50-375 S
	8403170032 8403200007 8403200007 8403200012 8403200012	50-445 50-445 50-445 50-445 50-445	e 0 0 0	Combustion Engineering, Inc	8403190374 8401240340* 8403010276 8403020335* 8403020335*	50-443 S 70-1100 50-470 E 50-362 A 50-362 A
	8403200025 8403200025 8403200026 8403200026 8403200047	50-445 50-445 50-445 50-445 50-445	e e e e		8403050103* 8403040161* 8403130293* 8403130476* 8403140140*	50-318 P GA979 TOPREP 70-1100 TOPREP
	8403200049 8403200073 8403200073 8403200114 8403200114	50-445 50-445 50-445 50-445 50-445	0 0 0 0	Commerce, Dept of, Commerce, Dept of, Maritime Administrat ion	8403200081 8403200085* 8403270107 7911120366* 8403050111	50-470 K 50-470 K 50-470 E 50-31P P 50-23B R
	8403200118 8403200118 8403200126 8403200126	50-445 50-445 50-445 50-445	e e e e	Commerce. Dept of, National Bureau of Standards Committee to Bridge the Gap	840309Q214 840320Q021	PR 50-142 G

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEOOR		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEOD	
Commonwealth Edison Co	8403010083 8403010083 8403010087* 8403010087* 8403010089	50-454 50-454 50-454 50-454 50-254	G G G G		8403060113 8403060117# 8403060121# 8403060127# 8403060127#	50-254 50-254 50-254 50-254 50-254	R R R
	8403010093* 8403010106 8403010106 8403010106 8403010106	50-254 50-454 50-454 50-454 50-454	P A A A		8403060150 8403060150 8403060217 8403060217 8403060245	50-373 50-373 50-295 50-295 50-454	R R R G
	8403010106 8403010120 8403010120 8403010120 8403010120	50-454 50-454 50-454 50-454 50-454	A E E E		8403060245 8403060245 8403060245 8403060245 8403060249	50-454 50-454 50-454 50-454 50-295	9 9
	8403010120 8403010130 8403010286 8403010286 8403010286	50-454 50-454 50-454 50-454 50-454	E G E E		8403060267* 8403060273 8403060279* 8403060345 8403060345	50-454 50-254 50-254 50-454 50-454	0 P E E
	8403010284 8403010403 8403010403 8403020003 8403020131	50-454 50-454 50-454 50-275 50-275	는 는 E		8403060374 8403060374 8403060374 8403060374 8403060374	50-454 50-454 50-454 50-454 50-454	* * * * *
	8403020131 8403020134 8403020134 8403020138 8403020140	50-275 50-275 50-275 50-373 50-275	P G R G		8403070347 8403070347 8403080174 8403080197 8403080197	50-454 50-454 50-304 50-10	F Q R H
	8403020140 8403020146# 8403020146# 8403020181 8403020181	50-295 50-295 50-295 50-454 50-454	0 0 0 0 0		8403080197 8403080197 8403080197 8403080197 8403080197	50-10 50-10 50-10 50-10 50-10	R R R R
	8403050002 8403050002 8403050043 8403050043 8403050043	50-254 50-254 50-10 50-10 50-10	a a a a		8403080197 8403080197 8403080197 8403090164 8403090174	50-10 50-10 50-10 50-275 50-304	R R R B
	8403050043 8403050043 8403050043 8403050043 8403050043	50-10 50-10 50-10 50-10 50-10	Q Q Q Q Q		8403090185 8403090191* 8403090194* 8403090294 8403120013	50-237 50-237 50-237 50-254 50-456	P P F 8
	8403050043 8403050043 8403050043 8403050043 8403050043	50-10 50-10 50-10 50-10 50-10	Q Q Q Q		8403120020 8403120047 8403120054 8403120080 8403120095	50-373 50-374 50-373 50-373 50-373	8 8 8 8
	8403050043 8403050046* 8403050046* 8403050046* 8403050046*	50-10 50-10 50-10 50-10 50-10	0 0 0 0		8403120107 8403120128 8403120128 8403120162 8403120162	50-265 50-373 50-373 50-454 50-454	9 2 4 4 6
	8403050046* 8403050046* 8403050046* 8403050046* 8403050046*	50-10 50-10 50-10 50-10 50-10	0 0 0 0 0		8403130015 8403130015 8403130070 8403130070 8403130102	50-237 50-237 50-237 50-237 50-265	R P P
	8403050046* 8403050046* 8403050046* 8403050046* 8403050063	50-10 50-10 50-10 50-10 50-373	a a a F		8403130353 8403130353 8403130359* 8403130370 8403130382	50-254 50-254 50-373 50-249 50-254	P 0 0 8
	8403050119 8403050119 8403050119 8403050119	50-237 50-237 50-237 50-237 50-237	P P P P		8403130382 8403130400 8403130400 8403130400 8403130410	50-254 50-237 50-237 50-237 50-237	P P P
	8403050119 8403050119 8403050119 8403050119 8403050119	50-237 50-237 50-237 50-237 50-237	P P P P		8403130410 8403130418+ 8403130418+ 8403140001 8403140001	50-237 50-237 50-237 50-456 50-456	# # 0 0
	8403050117 8403050119 8403050117 8403050117 8403050117	50-237 50-237 50-237 50-237 50-237	P P P P		8403140082 8403140151 8403140175 8403140190 8403140190	50-295 PR 50-373 50-454 50-454	F F F
	8403050171* 8403050174* 8403060099 8403060099 8403060099	50-373 50-373 50-10 50-10 50-10	ር Q R R R		8403150019 8403150019 8403150044 8403160011 8403160011	50-254 50-254 50-454 50-456 50-456	R R F Q

AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEOOR
	8403160023 8403160023 8403160027 8403160261 8403160266	50-456 50-456 50-265 50-373 50-374	0 0 5 R 8		8403230126* 8403230126* 8403230126* 8403230126* 8403230126*	50-10 50-10 50-10 50-10 50-10
	8403190001 8403190075 8403190090* 8403190090* 8403190117	50-249 50-254 50-373 50-373 50-373	0 G G F		8403230126# 8403260122 8403260132 8403260132	50-10 50-373 50-454 50-454 50-454
	8403170154 8403170154 8403170173 8403170173 8403170175	50-275 50-275 50-456 50-456 50-275	R R 8 5 F		8403260132 8403260132 8403260182 8403260182 8403260174	50-454 50-454 50-295 50-295 50-374
	8403190274* 8403190308 8403200013 8403200013 8403200032	50-454 50-454 50-373 50-373 50-373	0 F P 8		8403260176 8403260176 8403260176 8403260176 8403260223	50-237 50-237 50-237 50-237 50-237
	8403200041 8403200106 8403200122 8403200173 8403200188	50-373 50-245 50-454 50-304 50-265	F 8 9 8 8		8403260225 84032602374 8403260260 8403260346 8403260346	50-373 50-454 50-237 50-454 50-454
	8403200196 8403200204 8403200206 8403200212 8403200256	50-249 50-373 50-373 50-374 50-373	0 8 F 8 Q		8403260361 8403270035 8403270056 8403270089 8403270109	50-454 50-295 50-237 50-237 50-295
	8403200256 8403200263* 8403200263* 8403210085 8403210085	50-373 50-373 50-373 50-373 50-373	а а к к к		8403270111 8403270111 8403270130 8403270130 8403270144*	50-454 50-454 50-249 50-249 50-249
	8403210089 8403210091* 8403220120 8403220120 8403220120	50-295 50-373 50-10 50-10 50-10	F K R R		8403270144* 8403270175 8403270203 8403270265 8403280023	50-249 . 50-254 : 50-275 50-275 50-374
	8403220120 8403220120 8403220120 8403220120 8403220120	50-10 50-10 50-10 50-10 50-10	R R R R	Connecticut Yanker Atomic Power Co	8403280073 8403280119 8403010340 8403010391 8403020093	50-374 50-295 , 50-213 , 50-213 ,
	8403220120 8403220120 8403220123 8403220123 8403220127*	50-10 50-10 50-373 50-373 50-373	R R F F		8403050105 8403040325 8403090137 8403090272 8403090289	50-213 ; 50-213 ; 50-213 ; 50-336 ; 50-213 ;
	8403220127* 8403220133 8403220153 8403220153 8403220158*	50-373 50-454 50-237 50-237 50-237	F A P P P		8403130027 8403130027 8403130283 8403130289* 8403140014	50-213 , 50-213 , 50-213 , 50-213 ,
	8403220158* 8403230015 8403230017 8403230027 8403230081*	50-237 50-373 50-373 50-373 50-373	P 9 8 9 9		8403140116 8403190155* 8403190280 8403230022 8403230022	50-213 ; 50-213 ; 50-213 ; 50-213 ;
	8403230087 * 8403230096 8403230107 * 8403230107 * 8403230107 *	50-373 50-237 50-10 50-10 50-10	0 9 0 0		8403230136 8403260143 8403260143 8403260143 8403260143	50-213 (50-213 , 50-213 , 50-213 ,
	8403230107* 8403230107* 8403230107* 8403230107* 8403230107*	50-10 50-10 50-10 50-10 50-10	0 0 0 0 0		8403260146 8403260146 8403260146 8403260151* 8403260151*	50-213 ; 50-213 ; 50-213 ; 50-213 F 50-213 F
	8403230107* 8403230107* 8403230107* 8403230107* 8403230107*	50-10 50-10 50-10 50-10 50-10	0 0 0		8403260151* 8403260162 8403260252 8403270008 8403270068	50-213 F 50-213 P 50-213 P 50-213 F 50-213 F
	8403230107* 8403230124 8403230124 8403230126* 8403230126*	50-10 50-295 50-295 50-10 50-10	G F F G	Connecticut, State of	8403270278 8403300144 8403300164* 8403300176 8403140025	50-213 P 50-213 G 50-213 G 50-213 R 50-443 G
	8403230126* 8403230126* 8403230126* 8403230126* 8403230126*	50-10 50-10 50-10 50-10 50-10	0 0 0 0 0	Conner & Wetterhahn	8403020099 8403020099 8403020125 8403020125 8403020129	50-352

AUTHOR AFF]LIATION	ACCESSION NUMBER	CATEGO GUBJE C		AUTHER AFFILIATION	ACCEBBION NUMBER	CATEODS	
	8403020163 8403020163 8403040081 8403040081 8403040248	50-352 50-352 50-352 50-352 50-352	0 0 0 0		8403080024 8403080131 8403080141 8403080171 8403080171	50-329 50-155 50-155 50-329 50-329	9 R R 8
	8403060248 8403070142 8403070142 8403070236 8403070236	50-352 50-352 50-352 50-352 50-352	0 0 0		8403080184 8403080187 8403080187 8403080206 8403080222	50-255 50-329 50-329 50-255 50-329	R S R S
	8403070238* 8403070238* 8403150020 8403150022* 8403150024	50-352 50-352 50-354 50-354 50-352	9		8403080222 8403080230 8403080230 8403080235 8403080235	50-329 50-329 50-329 50-329 50-329	8 A 8 8
	B403160010 B403160010 B403200018 B403200060 B403200090	50-352 50-352 50-416 50-352 50-352	0 0 0		8403080241 8403080241 8403080245 8403080245 8403080247	50-329 50-329 50-329 50-329 50-329	A 8 8
	8403200070 8403200102 8403210092 8403210092 8403210103	50-352 50-354 50-352 50-352 50-352	G G G		8403080247 8403080248 8403080248 8403080259 8403080259	50-329 50-329 50-329 50-329 50-329	8 A B B
	8403210103 8403210178 8403260349 8403270012 8403270042	50-352 50-358 50-352 50-352 50-352	0 0 0 0 T		8403080242 8403080242 8403090229 8403120035 8403120041	50-329 50-329 50-155 50-155 50-255	A A F Q R
	8403290384 8403290384 8403290392 8403300127 8403300127	50~352 50~352 50~458 50~352 50~352	9 9 9		8403120131 8403120131 8403120140 8403130050 8403130050	50-155 50-155 50-255 50-329 50-329	0 0 R 8 8
	8403300128 8403300128 8403300127 8403300127 8403300270	50-352 50-352 50-352 50-352 50-354	0 0 0		8403130161 8403130161 8403130168* 8403130168* 8403130189	50-329 50-329 50-329 50-329 50-329	B A A
Consert Associates, Inc Conselidated Edison Co. of New York, Inc	8403300271 8403300271 8403010293 8403020155 8403050015*	50-352 50-352 70-1621 50-247 50-247	Q Q R Q		8403130187 8403130210 8403130210 8403130254 8403130254	50-329 50-329 50-329 50-329 50-329	A 9 0 0
	8403070075 8403070078* 8403070101* 8403070288 8403130405	50-247 50-247 50-247 50-3 50-247	Р Р Е		8403130241 8403130241 8403130272 8403130272 8403130354	50-329 50-329 50-329 50-329 50-329	A 8 8
	8403150029 8403190069 8403190296 8403190355 8403200124	50-247 50-3 50-286 50-247 50-247	0 F F P		8403130354 8403130362 8403130362 8403130471 8403130471	50-329 50-329 50-329 50-329 50-329	8 8 8 8
	8403210154 8403230135 8403230135 8403260120 8403260120	50-247 50-3 50-3 50-3 50-3	8 R R R		8403140021 8403140021 8403140032 8403140072 8403150003	50-329 50-329 50-329 TOPREP 50-329	A A B
	8403270185 8403270193 8403270204 8403290170 8403290172	50-247 50-247 50-247 50-247 50-247	R 9 9 0		8403150003 8403150145 8403170004 8403170071 8403170071	50-327 50-255 50-155 50-155 50-155	e I
Consumers Power Co	8403270268 8403010203 8403020088 8403060073 8403060073	50-247 50-155 50-155 50-329 50-329	0 F1 O		8403190071 8403190098 8403190098 8403190101 8403190166	50-155 50-329 50-329 50-255 50-329	A A B
	8403040104 8403040104 8403040188 8403040192* 8403040202*	50-329 50-329 50-155 50-155 50-155	\$ 9 9		8403190166 8403200011 8403200011 8403200027 8403200039	50-329 50-329 50-329 50-329 50-329	0 0 A
	8403060269 8403060269 8403060272 8403060272 8403060356	50-329 50-329 50-329 50-329 50-155	8 8 8 9		8403200037 8403200130 8403220007 8403220016 8403220016	50-329 50-155 50-329 50-329 50-329	A Q
	84030A042A 84030A042A 8403070008 8403070300 840308002A	50-320 50-320 50-329 50-255 50-329	8 9 8		8403220025 8403220025 8403220047 8403220047 8403220072	50-329 50-329 50-329 50-329 50-329	A B 9

AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEGOR		AUTHOR Affiliation	ACCESSION NUMBER	SUBJEC CATEGO	
	8403220072 8403220078 8403220108 8403220108 8403220179	50-329 50-255 50-329 50-329 50-329	8 P 8 8 A		8403190079 8403200185 8403210048 8403210074 8403210078*	50-341 50-341 50-341 50-341 50-341	8 A A A
	8403220179 8403220202 8403220202 8403220203 8403230093	50-329 50-329 50-329 50-329 50-255	A A G P		8403230018 8403230021* 8403240127 8403270043 8403300138	50-341 50-341 50-341 50-341 50-341	A G A A
	8403230098* 8403230114 8403230114 8403240115 8403270009	50-255 50-329 50-329 50-255 50-329	P A A P	Doberty, J F Dow Chemical Go	8403130057 8403270002 8401260167* 8403050012 8403050013*	50-456 50-443 50-264 50-264 50-264	D F F F
	8403270007 8403270014 8403270014 8403270020 8403270020	50-329 50-329 50-329 50-329 50-329	A A O O	Drezel Univ . Philadelphie. PA	8403120244* 8403120252* 8402210150 8403010140 8403010308	50-335 50-335 50-367 50-413 50-269	0 R 8 0
	8403270023 8403270023 8403270029 8403270029 8403270064	50-327 50-329 50-329 50-329 50-155	5 8 9 8 8		8403010335 8403020317 8403020317 8403020317 8403020317	50-413 50-369 50-369 50-369 50-369	# E E
	8403270169 8403270169 8403270199 8403270199 8403270236	50-329 50-329 50-329 50-329 50-329	8 0 9		8403020317 8403020321* 8403020321* 8403020321* 8403020321*	50-369 50-369 50-369 50-369 50-369	E E E
	8403270234 8403270055* 8403270187 8403270247 8403200070	50-327 FOIA 50-155 50-155 50-329	Р Р А		8403020321* B403060106 8403060225 B403060232 B403060240	50-369 50-369 50-269 50-370 50-413	E F 9 0
Control Data Corp Cressp. McCormick & Paget Crustal River. FL Cygna Energy Services	8403300152 8403060135 8403140038* 8403230154* 8403070126	50-155 FOIA 50-329 CONTRACT 50-445	R A G		8403060240 8403060272 8403060336 8403060417 8403060417	50-413 50-269 50-413 50-413 50-413	6 4 4 6
Dairyland Power Cooperative	8403270115 8403020161 8403080031 8403080236 8403120083	GA999 50-409 50-409 50-409 50-409	R R G		8403050422 8403070048 8403070048 8403070185 8403070202*	50-413 50-413 50-413 50-413 50-413	A G A
	8403130290 8403130335* 8403160047 8403200112* 8403200163	50-409 50-409 50-409 50-409 50-409	P G F F S		8403070210* 8403070217* 8403070331* 8403070352 8403080237	50-413 50-413 50-413 50-349 50-269	G G F V
	8403230002 8403290283 8403290287* 8403300089 8403300093*	50-409 50-409 50-409 50-409 50-409	R P P P		8403080239 8403080239 8403090222 8403090222 8403090222	50-269 50-269 50-269 50-269 50-269	V F F
Dallas Morning News Dames & Moore Dataflow Systems, Inc.	8403300131 8403060164 8403060347* 8403020073* 8403020077*	50-409 FOIA 50-454 CONTRACT			8403090224 8403090224 8403090241 8403090254 8403090276	50-413 50-413 50-413 50-269 50-369	8 8 F F
DeKelb Area Alliance for Responsible Energy Debeyoise & Liberman	8403160002 8403160002 8403160019 8403160019 8403080324	50-454 50-454 50-454 50-454 50-455	0 0 0 0		8403120150 8403120153 8403120173 8403130071 8403130071	50-370 50-413 50-370 50-413 50-413	8 8 9 9
Decision Research, Inc Del-Aware Unlimited, Inc. Delaware, State of	8403170444 8403130411 8403020141 8403070214 8403010147	NUREQ 50-352 50-354 PR 71-511	G G		8403130077* 8403130077* 8403130086 8403130104 8403130142*	50-413 50-413 50-413 50-413 50-244	0 А А В
Detroit Edison Co.	8403010153* 8403020121 8403060173* 8403060177* 8403090188	71-511 50-341 50-341 50-341 50-341	A G G		8403130149* 8403130157* 8403130167 8403130332 8403130341	50-244 50-244 50-370 50-369 50-370	R R B P
	8403070247 8403120007 8403120068 8403120155 8403120160	50-341 50-341 50-341 50-341 50-341	A 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5		8403130344* 8403140231 8403150065 8403150128 8403150128	50-370 50-369 50-413 50-413 50-413	P F 8 8
	8403130008 8403130044 8403130060* 8403130021	50-341 50-341 50-341 50-341	A K K V		8403150138 8403150154 8403160028 8403160029 8403160029	50-370 50-369 50-413 50-413 50-413	8 4 9

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEGORY
	8403160143 8403160143 8403160197 8403160216* 8403160253	50-413 50-413 50-413 50-413 50-413	G G A G		9403170317* 8403170324* 8403200040 8403200233 8403200234	50-334 R 50-334 R 50-334 F 50-334 F 50-412 A
	8403140253 8403140299* 8403140313* 8403190257 8403190257	50-413 50-413 50-369 50-369 50-369	0 0 0 Р Р		8403210058 8403210130 8403240059 8403240140 8403270215	50-412 8 50-412 8 50-412 C 50-334 R 50-334 F
	8403170287 8403170303 8403170394 8403170394 8403200007	PR 50-370 50-413 50-413 50-413	B A A G		8403280017 8403270145 8403270146* 8403270204* 8403300062	50-334 F 50-412 C 50-412 C 50-412 Q 50-412 A
	8403200010 8403200010 8403200010 8403200078 8403200123	50-269 50-269 50-269 50-413 50-369	R R R E R	EG&G, Inc	8403300181 8403300200 8402280725* 8403070395* 8403240335	50-334 R 50-412 Q 50-267 P 50-315 P 50-416 P
	8403200123 8403200145 8403200165 8403200221 8403200221	50-349 50-413 50-413 50-413	R A F F		8403270329 8403280113 8403280117 8403280124 8403280332	RES 50-313 9 50-348 8 50-348 8 50-338 8
	8403220038 8403220038 8403220044*	50-369 50-369 50-369	P P	Eaton Corp. Ebasco Bervices, Inc. (subs. of Enserch Corp.)	8403270034* 8403070332*	GA999 TOPREP
	8403220044* 8403220074 8403220074	50-369 50-413 50-413	P A A	Ecologica) Analysts, Inc Eddleman, W	8403230123* 8403050061 8403130001	50-219 R 50-400 E 50-400 9
	0403250034 8403250073 8403250080* 8403250139*	50-413 50-413 50-413 50-413	A A A		8403130184 8403130176* 8403130220* 8403130230* 8403200048	50-400 Q 50-400 Q 50-400 Q 50-400 Q 50-400 Q
	8403240347 8403240367 8403270011 8403270103 8403270207	50-413 50-413 50-413 50-413 50-249	9 9 9 A F		8403220222 8403220227 8403220265 8403220270 8403280344	50-400 9 50-400 9 50-400 9 50-400 9
	8403270213 8403270213 8403270230 8403270230 8403270243	50-413 50-413 50-369 50-369 50-369	А Р Р		8403280347 8403280349 8403280351 8403280360 8403280361	50-400 Q 50-400 Q 50-400 Q 50-400 Q 50-400 Q
	8403270243 8403280102 8403270082* 8403270148 8403270148	50-349 50-413 50-249 50-349 50-349	р Г С Р Р	Edelstrin & Payne Edison Electric Institute Ediow International Co	8403120002 8403130368 8403010454 8403010456* 8403270074*	50-400 0 PR XPORTL IC XPORTL IC 40-8760
	8403290154* 8403290164* 8403290244 8403290244 8403290267	50-349 50-369 50-413 50-413 50-349	P P 요 8 8 8 P	Energy Daily, Inc Energy Fuels Nuclear, Inc Energy Research & Consultants Corp Energy Dept of	8403280057 8403220240 8403190424 8403190282* 8402170325	XPORTLIC CONTRACT 40-8481 50-312 G WASTE MOT
	8403270267 8403270273* 8403270273* 8403270276* 8403270314	50-369 50-369 50-369 50-413 50-270	면 면 면		8403010356 8403060082 8403060357 8403060360* 8403060517	WASTE MOT 50-537 Q 50-537 A 50-537 A WASTE MOT
	8403300079 8403300079 8403300107 8403300126 8403300188	50-413 50-413 50-413 50-413 50-413	대 E A B A		8403040521* 8403070054 8403070217 8403140146 8403140312	WASTE MOT 50-597 Q 50-537 A PR WASTE MOT
ագսահոք Light Co	8403010124 8403010387 8403020084 8403060134 8403060297	50-334 50-412 50-334 50-334 50-334	R A R S V		8403200314 8403200348 8403220112 8403220303 8403220322	WASTE MOT WASTE MOT WASTE MOT WASTE MOT
	8403070243 8403070244* 8403070249 8403070298 8403070308*	50-334 50-334 50-334 50-412 50-412	R R R S G	Energy, Dept of, Clinch River Breeder	8403220324* 8403230245 8403300237 8403080090	XPORTLIC XPORTLIC WASTE MGT WASTE MGT 50-537 A
	8403070344* 8403070346* 8403120172* 8403130051* 8403130374	50-334 50-334 50-334 50-341 50-412	Q R G K S	Reactor Plant Energy, Dept of, Idaho Operations Office Engineering Planning & Management, Inc Engineers International, Inc Environmental Protection Agency	8403040085 8403240350* 8403020174	WASTE MOT FOIA WASTE MOT WASTE MOT
	8403150095 8403160090 8403160190 8403190152 8403190276	50-412 50-412 50-412 50-412 50-334	C A A A R	Ertec, Inc. European Communities, Commission of	8403130180 8403190289 8403200104 8403140328* 8403040075	50-508 D PR 50-456 D CONTRACT XPORTLIC

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	IY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC.	
Extran, Inc	8403200305 8403220230 8403220284 8403240011 8403270280	XPORTLIC XPORTLIC XPORTLIC XPORTLIC MISC			8403060168 8403060186 8403060241 8403060291 8403060291	50-250 50-389 50-389 50-250 50-230	P F Q Q
Exxon Corp Exxon Nuclear Co , Inc (subs of Exxon Corp)	8402140327# 8403260142# 8403060421#	40-8102 40-8102 70-1257			8403040340 8403040370 8403070034 8403070249	50-335 50-389 50-335 50-389	ቻ G G
·	8403040533 8403070127	NUREQ TOPREP			8403080020 8403080020	50-250 50-250	P P
	8403080205 8403080210* 8403080216* 8403080220* 8403080223*	50-316 50-316 50-316 50-316	P P P		8403080164 8403080164 8403070280 8403120040	50-335 50-335 50-335 50-389	V V F P
	8403150097 8403150104* 8403200100 8403200101* 8403230102*	50-314 50-314 50-314 50-314 50-255	P P P P		8403120087 8403130035 8403130066 8403160013 8403160013	50-397 50-397 50-335 50-389 50-389	ե 8 8
	8403230106* 8403230111* 8403240037 8403240042* 8403260219	50~255 50~255 XPORTLIC XPORTLIC TOPREP			8403140038 8403140058 8403140069 8403190171 8403190171	50-251 50-250 50-251 50-250 50-250	6 9 9 8 8
FOI Services Failure Analysis Associates Federal American Partners	8403020008 8403280166 8403010446# 8403140086# 8403200374	FOIA FOIA 50-322 50-322 40-4492	ទ ម		8403170177# 8403190177# 8403190227 8403190228* 8403190386	50-250 50-250 50-389 50-389 50-335	0 P P
Pederal Emergency Management Agency	8403220054* 8403050121 8403050131* 8403050148 8403050172*	40-4492 50-440 50-440 50-206 50-206	н Б Б		8403190386 8403200264 8403200264 8403200266* 8403200266*	50-250 50-250 50-250 50-250 50-250	F P P
	8403040086 8403070020 8403070020 8403070022# 8403070022#	50-250 50-443 50-443 50-443 50-443	F G O G		8403200270* 8403200270* 8403220070 8403220104 8403230014	50-250 50-250 50-335 50-250 50-302	ր 9 9
	8403080238 8403080242* 8403080244* 8403070218 8403070221*	50-263 50-263 50-263 50-155 50-155	F F F F		8403240203 8403270247 8403280110 8403290114* 8403270114*	50-250 50-335 50-250 50-335 50-335	Р Г О
	8403130155 8403130163 8403130172* 8403130178* 8403130185	50-254 50-262 50-262 50-272 50-275	Г Е Е		8403290123 8403300173 8403300173 8403300173 8403300173	50-250 50-250 50-250 50-250 50-250	0 R R R
	8403130198 8403130209* 8403130419 8403130018 8403130052	50-263 50-263 ORQ 50-273 50-416	F F		8403300173 8403300185* 8403300185* 8403300185*	50-250 50-250 50-250 50-250 50-250	R R R R
	8403150113 8403150113 8403150119* 8403150119* 8403150200	50-313 50-313 50-313 50-313 50-315	F F	Florida flower Corp	8403300185* 8403300193* 8403300193* 8402060419 8402060421*	50-250 50-250 50-250 50-302 50-302	R R R P
	8403150203* 8403170131 8403170343 8403200035* 8403230120	50-315 50-322 50-322 50-317 50-387	F G F F		8403010072 8403060283 8403060343 8403060359 8403060362*	50-302 50-302 50-302 50-302	F R P P
Firex Corp Fisher, Harden & Fisher Floride Power & Light Co.	8403240117* 8403070075 8403150340* 8401130182	50-322 PRM 40-8829 50-389	F		8403060364 8403060366* 8403060368* 8403060402 8403070173	50-302 50-302 50-302 50-302	Р Р О В
	8401130319 8401270125 8403010297 8403010302#	50-335 50-387 50-250 50-387 50-387	₽ 8 P P		8403120130 8403160036 8403160315 8403160320* 8403200038	50-302 50-302 50-302 50-302 50-302	P የ P P
	8403020033 8403020258 8403020258 8403020278 8403020288*	50-387 50-250 50-387 50-250 50-250	P R S V Q		8403200044* 8403200265 8403230062 8403230057* 8403270159	50-302 50-302 50-302 50-302 50-302	P P P P
	8403040112 8403040116* 8403040148 8403040148	50-335 50-250 50-250 50-250 50-250	F P P P	Fjorida, State of Fjuorocarbor Co	8403270162* 8403300111 8403300153* 8403070106 8403050102	50-302 50-302 50-302 PR GA999	р 8 9

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	PRY .	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	
	8403060355* 8403060361* 8403060365* 8403060369* 8403060372*	0A999 0A999 0A999 0A999 0A999			8403060236* 8403070203 8403080039 8403080178 8403080231	50-267 50-219 50-269 50-320 50-219	P P P F V
Food & Drug Administration Forboro Corp	B403060374* B403060376* B403060379* B403160026 B403010409	9A999 9A999 9A999 50-352 FOIA	D		8403080267 8403090036 8403090073* 8403090125 8403090244	50-320 50-320 50-219 50-289 50-289	р О Р
Franklin Institute/Franklin Research Center	8403120244#	50-335	Q.		8403070264 8403120004	50-320 50-299	F P
Friends of the Earth	8403120252* 8403150045* 8403270368* 8403190132	50-335 50-237 CONTRAC 50-352	0 P CT 0		8403120016 8403120056 8403120102#	50-287 50-287 50-320 50-287	Y Q F
Ft Hamilton-Hughes Memorial Hosp	8403170138* 8403170142* 8403270272 8010230503*	50-352 50-353 PRM FOIA	9 0		8403130197 8403130286 8403130428 8403130439*	50-219 50-289 50-320 50-320	₽ ₽ ₽
Center, Hamilton, OH	8403080113*	FOLA			8403130475 8403130483*	50-320 50-320	R R
Fulton, MD GA Technologies, Inc./General Atomic Co OH-Dettis Co	8403070081 8403150197 8403150199* 8403050170	50-403 XPORTLI XPORTLI PT21	IC .		8403130487# 8403140088 8403150083	50-320 50-289 50-219	R F P
Gage-Babcott Associates. Inc Dasconade County. MO	8403120226* 8403070084	CONTRAC 50-483			B403150118 B403150141 B403160006	50-320 50-289 50-289	F R P
General Accounting Office General Electric Co	8107200104* 8403280081* 8402100259	FOIA FOIA TOPREP			8403160022* 8403160024	50-289 50-289	P P
ueneral executic co	8403010084 8403010478 8403010479	XPORTLI XPORTLI XPORTLI	ı c		8403160057 8403160203 8403160204* 8403160208*	50-217 50-219 50-219 50-219	ጽ P 0
	8403010505 8403010522 8403010539	XPORTLI XPORTLI XPORTLI	i c		8403170063 8403170217#	50-219 50-320	F G
	8403010540 8403010546* 8403010550*	XPORTL I XPORTL I XPORTL I	c c c		8403170387 8403200076 8403200068 8403200077	PR 50-219 50-289 50-289	Q Rt P
	8403020043* 8403020089	50-10 XPORTL I			8403200201 8403200208#	50-320 50-320	P P
	8403050037 8403050241 8403060393* 8403060407 8403070353	XPORTL I XPORTL I 50-278 TOPREP XPORTL I	a a		8403210059 8403210064# 8403210071* 8403210076	50-320 50-320 50-320 50-289	R R R
	8403070381# 840313002& 8403130044#	XPORTLI Gay99 Gay99			8403210082* 8403210088* 8403210138 8403210141	50-267 50-269 50-269 50-289	R R R
	8403130262 8403130265	PR TOPREP			8403210146# 8403210146#	50-269 50-269	R
	8403130387 8403140006 8403140172 8403150072 8403150107	PT21 TOPREP PR 50-73	R		8403220002 8403220012 8403220141 8403220152	50-219 50-219 50-289	የ F #
	8403150189*	TOPREP 50-352	e -		8403220155* 8403220195	50-217 50-320	P P H
	8403200242 8403200244 8403200271	50-70 50-18 50-245	R R P		8403230001 8403230040	50-289 50-289	₽
	8403230186 8403270022* 8403270024* 8403270136*	50-554 50-293 50-293 50-249	6 6 6		8403230053 8403230110 8403230119 8403230122* 8403240074	50-289 50-219 50-219 50-219 50-219	P R R R
	8403270255 8403300088	PR TOPREP	•		8403270073 8403270123	50-320 50-320	F P
Qeneral Physics Corp Qeneral Public Utilities - QPU Service Corp	8403300342 8403010256 8403010241*	NUREO 50-219 50-219	9		8403270127* 8403270127* 8403270144	50-320 50-320 50-269	Р Р Н
	8403010347 8403020128	50-217 50-287 50-219	F R		8403270165 8403270210	50-219 50-320	P
	8403020318 8403020323*	50-320 50-320	p P		8403270212* 8403270232 8403280006	50-320 50-289 50-320	р F 9
	8403050070 8403050097 8403050151	50-219 50-289 50-320	P F F		8403280010 8403280010	50-289 50-289	J
	9403050133 9403050133 9403050157	50-287 50-287 50-287	F F P		8403270015 8403270386 8403300001	50-219 50-299 50-219	H Q R
	8403060160 8403060222	50-269 50-269	P P	Geochemistry & Environmental Chemistry	8403300031 8403050315	SO-320 STBAW	
	8403060229* 8403060233	50-289 50-289	P P	Research, Inc.	8403050318* 8403050319*	WASTE	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC		AUTHOR AFFILIATION	ACCESSION NUMBER	CATEG	
Georgia Power Co	8403050322* 8403050323* 8403010319 8403010319 8403010325*	WASTE M WASTE M 50-424 50-424 50-424		guild, R	8403070037* 8403090112 8403090112 8403090115* 8403090115*	50-413 50-413 50-413 50-413 50-413	0 0
	8403010325* 8403010330 8403010354 8403050085 8403060090	50-424 50-321 50-424 50-321 50-424	Х 9 Р 0	Qulf & Western Industries, Inc	8403220233 8403270377 8403270388 8403070178 8403070200*	50-413 50-413 50-413 PT21 PT21	G G
	9403070251 9403070251 9403070067 8403070097 9403070097	50-321 50-321 50-321 50-424 50-424	P F S S	Qulf States Utilities Co	8403070202* 6403070203* 6403140136 8403010073 8403010228	PT21 PT21 PT21 50-458 50-458	93
	8403090187 8403090187 8403090196* 8403090196* 8403090228	50-321 50-321 50-321 50-321 50-321	р Р Р В		8403010321 8403010321 8403010379 8403020294 8403050078	50-458 50-458 50-458 50-458 50-458	A B A A
	8403090282 8403120031 8403120146 8403130004 8403130165	50-321 50-366 50-424 50-321 50-321	F 8 F F		8403050078 8403040320 8403070010 8403070052 8403070052	50-458 50-458 50-458 50-458 50-458	A A A
	8403130165 8403130346 8403130346 8403150023 8403150038	50-321 50-321 50-321 50-424 50-424	F F H V		8403070061 8403070061 8403070062 8403080378 8403080378	50-458 50-458 50-458 50-458 50-458	A E A
	84031 50038 84031 50043 84031 50043 84031 50049 84031 50049	50-424 50-424 50-424 50-424 50-424	> :: :: :: :: :: :: :: :: :: :: :: :: ::		8403130069 8403130175 8403130190 8403130264 8403130393	50-458 50-458 50-458 50-458 50-458	E A S F
	8403150071 8403150071 8403160031 8403160044 8403160349*	50-321 50-321 50-344 50-321 50-321	R R S Q		8403130448* 8403130486 8403130486 8403130497* 8403160310	50-458 50-458 50-458 50-458 50-458	0 F F S
	8403160349* 8403190026 8403190105 8403190105 8403200005	50-321 50-366 50-424 50-424 50-321	9 8 8 9 9		8403170017 8403200034 8403210069 8403220207 8403260180	50-458 50-458 50-458 50-458 50-458	E A A A
	8403200005 8403200242 8403240086 8403260117 8403260150	50~321 50~366 50~366 50~366	8 8 6 6		8403250291 8403270026 8403270039 8403270045 8403270076*	50-458 50-458 50-458 50-458 50-458	A 9 8 0
	8403260191 8403290037 8403290194* 8403290194* 8403290212*	50~366 50~424 50~366 50~366 50~321	8 0 0 0	Harmon & Weiss	8403270201 8403280032 8403270372 8403020173 8403070147	50-458 50-458 50-458 50-443 50-322	5 M G G T
	8403270219# 8403300104 8403300104 8403300143 8403300143	50~321 50~321 50~321 50~321 50~321	0 8 8 F F		8403070232 8403240382 8403290005 8403300243 8403300259	50-443 50-289 50-289 WASTE M 50-289	0 F 9T G
Georgia, State of Georgians Against Nuclear Energy Getty/Petrotomics Co. Gilbert Associates, Inc	8403300337 8403130457 8403020126 8403260242 8403060414#	50~321 50~424 50~424 40~6659 50~302	F G G	Harshbarger & Associates Harvard Univ , Cambridge, NA Health Physics Associates, Ltd	8403300263 8403080409* 8403140172 8403190362 7904030132*	50-449 50-528 PR PRM FDIA	G A
Colder Associates Government Accountability Project	8403090329* 8403290188* 8403290189* 8403010004* 8402140014	TOPREP 50-244 50-244 CONTRAC 50-528	P P T	Health Physics Society Helgeson Nuclear Dervices, Inc Henry Ford Hosp , Detroit, MI Henry Pratt Co	7904030135* 8403230069 8403050156* 8403210107 8403230028	FOIA PRM 40-672 PRM 50-389	8
	8403010192 8403010488 8403020102 8403040303* 8403080085	50-327 50-329 F01A 50-275 50-275	A G E	Hodder, M H	8403070143* 8403140017 8403140017 8403140023* 8403140023*	50~250 50~250 50~250 50~250 50~250	0 0 0
	8403080196 8403150010 8403200133 8403260364 8403260364	50-413 50-275 50-275 50-275 50-275	A G G G	House of Rep	8312140351* 8312280102* 8403070073* 8403070074* 8403070076*	50-275 50-275 50-289 50-289 50-289	E U U U
Greely, CO	8403240345 8403270004 8403270004 8403270173 8403220312*	50-142 50-275 50-275 50-445 CONTRAC	а е р н		8403070011* 8403070013* 8403140208* 8403210137 8403270367	50-287 50-287 50-362 50-287 50-275	บ บ ย บ

AUTHOR AFFILIATION	ACCESSION	SUBJECT CATEGO		AU AFFIL	THOR IATION	ACCESSION NUMBER_	SUBJECT CATEGOR	
House of Rep , interior & Insular Affairs Houston Lighting & Power Co	840301003B* 8403120393* 8403070117 8403130328 8403130328	FOTA COMMISS 50-498 50-498	70N 9 8			8403020044 8403040191 8403040195 8403040195 8403040197*	50-315 50-316 50-315 50-315 50-316	# P P
Hunton & Williams	8403130477 8403130477 8403140151 8403190289 8403010183	50-498 50-498 PR PR 50-322	8 8			8403040200* 8403040200* 8403040315* 8403040315* 8403080149	50-315 50-315 50-315 50-315 50-315	P G G R
	8403010195 8403010221 8403010221 8403010229* 8403010229*	50~322 50~463 50~463 50~463 50~463	0 0 0			84030801A9 8403080214* 84030902A8 8403130121 8403130202	50-315 50-315 50-315 50-315 50-315	R G F F
	8403010242 8403010249 8403020143 8403040105 8403040107*	50-322 50-322 50-322 50-322 50-322	9999			8403130202 8403130259 8403130259 8403130420* 8403130420*	50-315 50-315 50-315 50-315 50-315	F R R R
	8403130012 8403130018* 8403130032 8403130030* 8403130041*	50-322 50-322 50-322 50-322 50-322	000			8403160034 8403160034 8403200202 8403200202 8403200210	50-315 50-315 50-315 50-315 50-316	0 0 0 P
	8403130053* 8403130063* 8403130073* 8403130082* 8403130090*	50-322 50-322 50-322 50-322 50-322	0000			8403200214* 6403200216 6403200217 6403200223 8403200223	50-316 50-315 50-316 50-315 50-315	P 8 9 P
	8403130099* 8403130109* 8403130119* 8403130129 8403150004	50-322 50-322 50-322 50-322 50-322	00000			8403200228* 8403200288* 6403200283 8403220040* 8403220040*	50-315 50-315 50-315 50-315 50-315	P P S Q
	8403200031 8403200037* 8403200049 8403210177 8403210181*	50-322 50-322 50-322 50-322 50-322	0000			6403230138* 6403230136* 6403260002 8403260178 6403260178	50-315 50-315 50-315 50-315 50-315	0 P F F
	8403230013 8403260377 8403270292 8403270177 8403300256	50-322 50-322 50-322 50-322 50-322	G T G G			8403270047 8403270110 8403270271 8403300155 8403300157	50-315 50-314 50-315 50-316 50-315	Q: P F R
ICI Americas, Inc Idaho, Univ of, Hoscow, ID Illinois Fower Co	8403300277 8403210107 8403150207* 8403070120 8403070123*	50-322 PAM 40-8781 50-461 50-461	G G	Indiana & Michigan Information Handlin Interactive Radiati Interior, Dept of	g Bervices	8403090281 8403040171 8403020157 8403010040* 8403080277	50-315 FOIA XPORTLIC CONTRACT 50-320	
	8403080240 8403090277* 8403130193 8403150089 8403140175*	50-461 50-331 50-461 50-461 50-461	9 P A Q	Interior, Dept of, Affairs Interior, Dept of,		8403080406* 8403170343 8403080400* 8403070189	50-526 50-506 50-528 50-424	D D C
	B403170396	30-461	A	Service Interior, Dept of,		8403070383*	27-39	
	8403200193* 8403260255 8403290093	50-461 50-461 50-461	A S I	International Commi Protection	ssion on Radiological	8403230076*	CONTRACT	Г
Illinois, State of	8403290098* 8403010344 8403040118 8403040124*	50-461 27-39 40-2061 40-2061	Ī	Iowa Electric Light	& Power Co	8403020108 8403020111* 8403040136 8403040145	50-331 50-331 50-331 50-331	8 F 8
	8403070027 8403070030* 8403070123* 8403080184*	40-2061 40-2061 50-461 FDIA	G			8403090088 8403090092# 8403090262 8403120042 8403120091	50-331 50-331 50-331 50-331	P P R 8
	8403130037 8403130474 8403200083 8403200089*	50-456 50-456 40-2061 40-2061	D O			8403120139 8403130144 8403130488# 8403150087	50-331 50-331 50-331 50-331	B P F
	8403200317 8403300258	27~39 40-2061				8403190295	PR	
Illinois. State of, Dept Nuc Safety (formerly Dept Public Health) Impell Corp	8403040313 8403010303* 8403150014*	50-456 50-388 50-440	D E G			8403170300 8403170306* 8403200047 8403200051 8403200121	50-331 50-331 50-331 50-331	P P F F
	8403200062* 8403200062* 84032000269* 8403230016	50-217 50-217 50-482 50-322	G A T			8403200183 8403200192 8403220017 8403230004 8403230007*	50-331 50-331 50-331 50-331 50-331	FPRPP
tric Co	8403230032 8403230048 8403233073 8403020007	50-322 50-322 50-314	T T FR			8403230105 8403260208	50-331 50-331	Q P

AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJEC'	RY	AUTHOR Affiliation	ACCESSION NUMBER	SUBJECT CATEGO	IRΥ
Iowa. State of I≋ham. Lincoln & Beale	8403190387 8403010203 8403020134	PR 50-155 50-275	 G G	Kentucky, Commonwealth of,	8402130395* 8403210019	50-358 40-2061	U
	8403020134 8403020140	50-275 50-275	G G	Kerr-McGee Carp	8403150272 8403150274 8403150332	40-8764 40-8764 40-8564	
	8403020140 8403020146* 8403020146* 8403020181 8403060188	50-275 50-275 50-275 50-494 50-155	6 6 6		8403260129* 8403260158* 8403280028 8403280099 8403280103*	40-1478 40-1478 40-2061 40-8586 40-8586	
	8403040192* 8403040202* 8403140011 8403140011	50-155 50-155 50-454 50-456	G G G	Kirkpatrick, Lockbart, Hill, Christopher & Phillips	8403290389* 8403010234	40-2061 50-322	G
	8403140023 8403140023	50-454 50-454	9		8403010237 8403060208 8403060254	50-322 50-322 50-322	G G T
	8403190004 8403200011 8403200011 8403200122	50-155 50-329 50-329 50-454	9 9 9		8403060268 8403060338 8403130003 8403130029	50-322 50-322 50-322	G G G
Island Closeup News Bervice, Sag Harbor, NY	8403200130 8403240361 8403270020 8403270020 8403010474	50-155 50-456 50-327 50-329 FOLA	6 6 9		8403130146 8403130174 8403150026 8403200004 8403200128 8403200131	50-322 50-322 50-322 50-322 50-322 50-322	G G G G
Isotope Products Laboratories Japan: Covt of	8403090016 8403010490 8403010464 8403010471 8403010487	FOIA XPORTLIC XPORTLIC XPORTLIC XPORTLIC	C C		8403200134* 8403200134* 8403200140* 8403200145* 8403200146*	50-322 50-322 50-322 50-322	0 0 0
Joint Intervenors - Diablo Canyon	8403220197 6403240041 6403240390 6403060118 6403190011	XPORTL 10 XPORTL 10 XPORTL 10 50-275 50-275	:		8403200151* 8403200155* 8403200159* 8403210186 8403220250	50-322 50-322 50-322 50-322 50-322	G G G
	8403190011 8403190016* 8403190016* 8403190021* 8403280106	50-275 50-275 50-275 50-275 50-275	0 0 0 0		8403220289 8403260134 8403280346 8403280357 8403280358	50-322 50-322 50-322 50-322	T G G
	8403280104 8403280110* 8403280110* 8403240348 8403240349*	50-275 50-275 50-275 50-275 50-275	0 0 0		8403270248 8403270377 8403270383 8403270390 8403070045	50-322 50-322 50-322 50-322 50-483	A G G O M
Joint Intervenors - River Bend Joint Intervenors - Shearon Harris	8403140012* 8403120002 8403190141* 8403200054 8403220223	50-458 50-400 50-400 50-400 50-400	9 9 9 9	Hampton Kudiu Alliance LIXI, Inc	8403070226 8403120002 8403080200	50-329 50-400 FOIA	9
Joint Intervenors - Waterford	8403220223 8403220265 8403220270 8403280361 8403080130	50-400 50-400 50-400 50-400 50-382	0 0 0 0	La Crosse, WI Labor, Dept of Larey Township, NJ Lahner Associates	8403080218* 8403220319* 8403130235 8403050231 8403050335* 8403200240*	FOIA CONTRACT PR 50-217 MISC 50-410	H A
Joint Petitioners — TMI Justice, Dept. of . KLD Associates, Inc Kansas Gas & Electric Co	8403220242 8403080383* 8403080425* 8403230020 8403010145	50-289 FOIA 50-289 50-322 50-482	0 P T 8	Lawrence Derkaley Laboratory Lawrence Livermore Laboratory	8403300120 8303080290* 8403050029* 8403050035* 8403050038*	RES	P P P
	8403020274 8403090225 8403130197 8403130215 8403130345*	50-482 50-482 50-482 50-482 50-482	A V A B Q	LeBoeuf, Lomb, Leiby & MacRae (League Agoinst Nuclear Dangers	8403140334 8402170155 8403120183 8403130044 8403090208	ACRB 50-285 50-285 50-341 PR	P P K
	8403130399* 8403150064 8403190035 8403190036 8403190229*	50~482 50~482 50~482 50~482 50~482	0 A 0 8 A	Lewis, M E Limerick Ecology Action	3403090135* 3403160049* 3403160291 3403190038 3403190140	50-320 50-289 50-352 50-352	P H G
	8403190316 8403200252 8403200257 8403200260* 8403200269*	50-482 50-482 50-482 50-482 50-482	8 A A A		9403270060 8403270069* 8403280336 8403300014* 8403300129	50-352 50-352 50-352 50-352	о О Т О
	8403210073 8403240325 8403270105 8403270151 8403270163	50-482 50-482 50-482 50-482 50-482	A 8 8	Literature Research Co. Long Island Lighting Co	8403260322* 8403010183 8403010195 8403010207 8403010207	50-322 50-322 50-322 50-322 50-322	335
Xaye, Scholer, Fierman, Hays & Handler	8403270179 8403270268 8403010111 8403080226	50-482 50-482 FOIA FOIA	9		8403010218 8403010218 8403010220	50-206	5 9

AUTHÖR AFFILIATION	ACCEBBION NUMBER	SUBJECT CATEGOR	Υ	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	8403010242 8403010247 8403020137 8403020143 8403020148	50-322 50-322 50-322 50-322 50-322	0 0 A 0	Los Alamos Scientific Laboratory Louisiana Power & Light Co	8403300256 8403300277 8403230216 8403010069 8403010187	50-322 50-322 50-337 50-382	0 A 8 6
	8403020287 8403060105 8403060107* 8403060265 8403070147	50-322 50-322 50-322 50-322 50-322	E G G T		84030202033 8403020333 8403050045 8403050248 8403050251*	50-362 50-362 50-382	A A E F
	8403070150* 8403070154* 8403070158* 8403070160* 8403070165*	50-322 50-322 50-322 50-322 50-322	T T T T		8403050253* 8403060190 8403060196 8403060258 8403060293	70-2946 50-382 50-382	F 8 8 5
	8403070171* 8403070178* 8403070183* 8403070190* 8403070195*	50-322 50-322 50-322 50-322 50-322	ፕ ፕ ፕ ፕ		8403040304 8403040337 8403040339 8403090038* 8403120014	50-382 50-382 50-382	E 8 A F
	8403070198* 8403070201* 8403070204* 8403070207* 8403070211*	50-322 50-322 50-322 50-322 50-322	T T T T		8403120164 8403120165* 8403120167* 8403120168 8403120169	50-382 50-382 50-382	F F A A
	8403070214* 8403070217* 8403070220* 8403070222* 8403070227*	50-322 50-322 50-322 50-322 50-322	T T T T		8403120186 8403130105 8403130170 8403130267 8403130303	50~382 50~382 50~382	E G A B
	8403070231* 8403130012 8403130018* 8403130022 8403130030*	50-322 50-322 50-322 50-322 50-322	T G G		8403130311 8403130331 8403130337 8403130427 8403130434	50-382 50-382 50-382	8 0 8 9 F
	8403130041* 8403130053* 8403130063* 8403130073* 8403130082*	50-322 50-322 50-322 50-322 50-322	ଜ ଜ ଜ ଜ ଜ		8403130436 8403130446 8403140191 8403150046 8403150075	50~382 50~382 50~382	B A F A F
	8403130070* 8403130079* 8403130107* 8403130117* 8403130129	50-322 50-322 50-322 50-322	G G G		8403140020 8403170250 8403170253 8403170262 8403170272*	50~382 50~382 50~382	A 8 8 0
	8403140017 8403140048 8403140048 8403140050 8403140050	90-322 90-322 90-322 90-322	A 8 8 9		8403170348 8403200022 8403200141 8403200148 8403200209	50~382 50~382	S F A
	8403140080* 8403140080* 8403140071* 8403150004 8403150133	50-204 50-322 50-322 50-322	\$ \$ \$ \$		8403200267 8403200276 8403210030 8403260154 8403270040	50-362 50-362 50-362	8 A A S
	8403190127 8403200004 8403200031 8403200037* 8403200069	50-322 50-322 50-322 50-322 50-322	9 6 6		8403270046 8403270059 8403270075 8403270102 8403270154	50-382 50-382 50-382	9 8 8 A
	8403200227 8403200302 8403210177 8403210181* 8403230008	50-322 50-322 50-322 50-322	A G G		8403270161 8403270202 8403270206 8403300048 8403300049#	50-382 50-382 50-382	8 8 F F
	8403230013 8403230016 8403230020 8403230032 8403230038	50-322 50-322 50-322 50-322 50-322	G T T T T	Louisiana Btate Univ Lowell. Univ of. Lowell. MA MATECO (subs of Multi-Amp Corporation) MPR Associates, Inc	8403050081* 8403300167* 8403130244 8403170351* 8403220004*	50-223 GA979 50-361	A Q P
	8403230048 8403230066 8403230073 8403260377 8403260379*	50-322 50-322 50-322 50-322 50-322	T T T T	Maine Yankee Atomic Fower Co	8403020065 8403060094 8403130047 8403220192 8403220199*	50-907 50-909 50-909	# # # #
	8403270074 8403270116 8403270119 8403270132 8403270197	50-322 50-322 50-322 50-322	G A R S G		8403230034 8403230042 8403270138 8403270256 8403300160	50-309 50-309	P P R O
	8403270272 8403280027 8403290160 8403290165* 8403290179	50-322 50-322 50-322 50-322	8 F F G	Maine, State of Mallinckrodt, Inc Marsh & McLennan, Inc.	8403300162 8403070032* 8403270290* 8403210004 8403060224	50-307 CONTRACT CONTRACT PR 50-327	J

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	
	8403040234 8403040234 8403040277 8403040281 8403040281	50-335 50-335 50-370 50-321 50-321	7 7 7 7		8403090172 8403090215 8403090265 8403090265 8403120037	50-416 50-416 50-416 50-416 50-416	8 P 8 S
	8403060332 8403060334 8403060353 8403060367 8403060375	50-259 50-259 50-302 TOPREP TOPREP	n n		8403120148 8403120157 8403130075 8403130172 8403130248	50-416 50-416 50-416 50-416 50-416	9 9 9 9 9
	8403060377 8403060377 8403060413 8403060448 8403070175	50-397 50-397 50-438 50-348 50-327	7		8403130253 8403130274 8403130464 8403140121 8403140121	50-416 50-416 50-416 50-416 50-416	8 5 7
	8403140003 8403140015 8403140029 8403140031 8403140033	50-322 50-375 50-273 50-245 50-27	ე ე		8403170033 8403170043 8403170057 8403170115 8403170216	50-416 50-416 50-416 50-416 50-416	9 9 9
	8403140037 8403140044 8403140078 8403140092 8403240170	50-413 50-348 50-244 50-213 TOPREP	7 7 7		8403170272 8403170331 8403200014 8403200017 8403200018	50-416 50-416 50-416 50-416 50-416	8 8 8 9
	8403250197 8403280038 8403280053 8403280058 8403280054	50-272 50-321 50-348 50-272 50-146	7 7 7		8403200064 8403210041 8403210053 8403210057 8403210062*	50-416 50-417 50-416 50-416 50-416	8 8 8 8
Marubeni America Corp (subs of Marubeni Corp.)	8403010467* 8403050364* 8403050366*	XPORTLIC XPORTLIC XPORTLIC XPORTLIC	C		8403210109 8403210140 8403210140 8403210192 8403220147	50-416 50-416 50-416 50-416 50-416	P E E S R
Maryland, State of Maryland, Univ of, College Park, MD	B403070104 B403130157 B403130234 B403210124 B403210124*	PR 50-320 PR 50-166 50-166	P P		8403220156 8403230084 8403230087* 8403230072* 8403260244	50-416 50-416 50-416 50-416 50-416	8 P P
Massachusetts General Hosp , Boston, MA Massachusetts Institute of Technology, Cambridge, MA	8402130347	PRM 50-20	F		8403270134 8403280007 8403280014* 8403280018*	50-206 50-416 50-416 50-416	9 9 9
Massachusetts. Univ of. Medical School Maxwell, J C	8403070212 8403140172 8403270321 8403140302	PR PR PR 50-400	ø		8403290025* 8403270030 8403270030	50-416 50-416 50-416	9 0
Medical Physics Consultants, Inc Memphis State Univ., Memphis, TN Metal Bellows Corp Metropolitan Edison Co.	8403080149* 8403150196* 8403230060 8403120117 8403010009	FDIA CONTRACT 50-538 GA999 50-289	T R		8403270074 8403270304 8403300007	50-416 50-416 50-416	8 8
	8403040084 8403070025 8403080105 8403070129	50-287 50-287 50-287 50-289	G G G		8403300037 8403300082 8403300097 8403300113	50-416 50-416 50-416	8 8 8
	8403130443 8403130451* 8403200055 8403200066 8403200120	50-287 50-289 50-289 50-289 50-289	6 6 6	Missouri, State of	8403300114 8403300117 8403300118 8403300124 8403070087	50-416 50-416 50-416 50-416 50-483	8 8 8
	8403210175 8403210187 8403210193	50-287 50-287 50-289	G G	Missouri. Univ of. Rolla. ND Mitsubishi International Corp (subs of Mitsubishi Corp)	8403170088* 8403010465 8403010468*	SO-123 XPORTLIC XPORTLIC	:
Michigan, State of Michigan, Univ. of, Ann Arbor, MI	8403260345 8403170172* 8403140151	50-287 50-329 PR	Ä		8403010470 8403010473* 8403010512	XPORTLIC XPORTLIC	:
Millikin & Fitton Millipare Corp Minerals Exploration Co. (subs. of Union Oil Co of California)	8403230131 8403080113* 8403210107 8403150228	NUREG FOIA PRM 40-8584			8403010517* 8403050327* 8403050333* 8403050373*	XPORTLIC XPORTLIC XPORTLIC	
Minnesota, State of	8403230058	PR			8403050376* 8403070425*	XPORTLIC	3
Mississippi Power & Light Co	8403290316 8403010121 8403020047 8403020410*	WASTE MG 50-416 50-416 50-416	9T \$ R 8	Mítsuí & Co (USA), Inc (subs of Mitsui & Co , Ltd.)	8403070426* 8403020422 8403050033	XPORTLIC XPORTLIC	2
	8403070057 8403070173* 8403070176* 9403070180* 8403070189*	50-416 50-416 50-416 50-416 50-416	Q Q Q	Monros County, MI Montgomery County, MO Morris, II Morrison-Knudsen Co , Inc	8403280054* 8403070078 8403230052* 8403120043 8403200150*	50~341 50~483 CONTRACT QA999 QA999	H F
	8403070268 8403070325 8403070091	50-416 50-416 50-416	Q P S	Murphy & Davenport Mutual Atomic Energy Liability Underwrit ers	8403200157* 8403210038 8403140065	GA999 WASTE NO 50-280	

AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	CATEGO!	
NL Industries, Inc NPB Industries, Inc NUB Corp	8403200373 8403070256 8403010278 8403020372 8403070098	FOIA	S P	<u> </u>	8403130349* 8403130363 8403130366 8403130391* 8403130051	50-220 50-410 50-220 50-220 50-220	P 9 P P R
NUSAC, Inc NUTECH Engineers, Inc National Aeronautics & Space Admin	8403090015 8403260253* 8403270362* 8403070318* 8403060405	CONTRACT 50-325	e 0 R		8403200002 8403200232 8403200243* 8403200248* 8403210043	50-220 50-410 50-410 50-410 50-220	4 4 4 8
National Board of Boiler & Pressure Vesse) Inspectors Natural Resources Defense Council	8403050410* 8403130288 8403190120	50-35B 50-537	R A G		8403210136 8403220129 8403220177 8403230078	50-410 50-220 50-220 50-220	8 P P
Navy, Pept of Nebrasia Public Power District	8403290297 8403020083		R		8403230116 8403260270	50-220 50-220	F
	8403050075* 8403060239 8403060264 8403060274* 8403060346	50-298 50-298 50-298	0 F F F		8403270176 8403280036 8403280047 8403290177	50-220 50-220 50-220 50-220	P J I
	8403060354 8403060392 8403080265 8403090100 8403090116*	50-298 50-298 50-298	F G F P	North Carolina State Univ , Raleigh, NC North Carolina, State of	8403300058 8403300151 8403070340 8403140085 8403190047*	50-220 50-220 ACRB 50-400 50-400	р О Б
	8403150168 8403150171*	50-298	Р	Northeast Nuclear Energy Co (subs of Northeast Utilities)	8403010219 8403010235	50-334 50-334	9 P
	8403150173* 8403160260* 8403190089	50-278 50-278	P Q F		8403020055 8403020133 8403050001	50-245 50-336 50-423	R R D
	8403200167 8403200254 8403220042* 8403220055 8403270013	50-278 50-278 50-278	F 9 9 F F		8403050105 8403050105 8403070273 8403070275* 8403070277	50-213 50-213 50-423 50-423 50-423	P C C A
Netherlands, Govt of Nevada, State of	8403300150 8403080360# 8403080364# 8403080366* 8403020206	50-298 FOIA FOIA FOIA WASTE MOT	R		8403070336* 8403070257 8403070272 8403120135 8403120138*	50-423 50-334 50-334 50-245 50-245	0 9 8 8
Nevada, Univ of New England Coalition on Nuclear Pollution	8403150222# 8403150223# 8403020173	WASTE MOT WASTE MOT			8403120138# 8403130027 8403140101 8403140109#	50-245 50-213 50-423 50-423	R P K K
New Mexico, State of	8403070232 8403050109	50-443 State Pro	g g		8403160292 8403190048	50~423 50~245	E
New York Univ , New Yerk, NY New York, State of	8403060314* 8403020123 8403020233 8403060212 8403060226*	50-322 50-322 50-322	T 0 6 T T		8403170280 8403200113 8403200147 8403210011	PR 50~334 50~423 50~423	s A 0
	8403060246* 8403060252* 8403130043 8403130085 8403130091*	50-322 50-322 50-322 50-322	T T G G		8403220148 8403230022 8403230022 8403230022 8403230029	50-423 50-213 50-213 50-213 50-245	F R R F
	8403130236 8403210179 8403210188 8403210201 8403230010	PR 50-322 50-322 50-322	6 0 0		8403230033 8403230034* 8403230037* 8403260143 8403260143	50-423 50-245 50-423 50-213 50-213	0 6 F F
Newman & Holtzinger	8403260338 8403260342* 8403020100 8403070117 8403090086	50-322 50-322 50-537 50-498	T T G G		8403260143 8403260143 8403260145 8403260146 8403260146	50-213 50-213 50-334 50-213 50-213	F P F
Niagara Mohawk Power Corp.	8403170171 8403230184 8403240062 8403300272 84033040221	50~250 50~554 50~331 50~344	0 G J O		8403260149 8403260151* 8403260151* 8403260151*	50-423 50-213 50-213 50-213 50-213	E F F
	8403060247 8403060439 8403060446 8403070194 8403070040	50-220 50-220 50-220 50-220	P F P R P		8403250191 8403250195 8403250284 8403270008 8403270008	50-423 50-245 50-245 50-213 50-213	A F F F
	8403090063 8403090078 8403090146 8403120044 8403120050#	50-220 (50-410 (50-220 (50-220 (F 8 P		840327008 8403270081 8403270112 8403270230 8403200080	50-213 50-336 50-423 50-336 50-336	F A P R
	8403120050# 8403120059 8403130124 8403130340	50-220 I	Q P V P		8403300072* 8403300072* 8403300135 8403300144	50-245 50-245 50-245 50-213	O O R G

AUTHOR AFFILIATION	ACCESSION NUMBER	CATEGO		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJE C CATEGO	RY
Northeast Utilities	8403010219 8403010235 8403020133 8403050001 8403050105	50-336 50-336 50-336 50-423 50-213	8 P R D		8403290115 8403290115 8403290115 6403300087 8403300095	50-263 50-263 50-263 50-263 50-263	I I R R
	8403050105 8403070273 8403070279 8403070336* 8403070335	50-213 50-423 50-423 50-423 50-336	P C A O P	Northwestern Univ . Evanston. IL Norton. Burke. Berry & French	8403300095 8403300130 8403300130 8403050237* 8403070044	50-282 50-282 50-282 CONTRAC 50-275	R F F T O
	8403070272 8403120135 8403130027 8403130213 8403130277	50-336 50-245 50-213 50-423 TOPREP	P R 9	NucleDune Engineering Corp	8403120006 8403070314 8403070315* 8403070316* 8403070318*	50-275 TOPREP TOPREP TOPREP	G
	8403130340 8403130367* 8403130374* 8403140101 8403140131	50-423 50-423 50-423 50-423 TOPREP	C C K		8403070319* 8403070321* 8403070322* 8403070323* 8403070324*	TOPREP TOPREP TOPREP TOPREP	
	6403160272 8403190048 8403200149 8403210011 8403210161	50-423 50-245 50-423 50-423 50-423	E P A Q 8		8403070325* 8403070327* 8403070328* 8403070330* 8403300237*	TOPREP TOPREP TOPREP TOPREP TOPREP	
	8403220148 8403230022 8403230029 8403230033	50-423 50-213 50-245	두 유 단 0	Nuclear Awareness Network Nuclear Energy Liability Insurance	8403090053 8403140061 8403140047	50-482 50-482 50-338	0 0 J
	8403260143 8403260143	50-423 50-213 50-213	F F	Association	8403140054 8403140059	50-280 50-280	n n
	8403260145 8403260146 8403260146 8403260149	50-336 50-213 50-213 50-423	E E E	Nuclear Information & Resource Service Nuclear Law Center Nuclear Medicine Associates, Inc Nuclear Metals, Inc	8403140047 8403280211 8403200021 8403080154+ 8403050144*	50-280 50-482 50-142 FOIA 40-672	J G G
	8403260181 8403260195 8403260200 8403270008	50-213 50-423 50-245 50-213 50-213	F A F P F		8403050150* 8403220072* 8403050055 8312280107* 8403070252*	40-672 40-672 FOIA 50-275 50-321	E P
	8403270008 8403270081 8403290112 8403290230 8403300080	50-213 50-334 50-423 50-336 50-336	F A P R	Nurnbarger Radiation Protection Service Nutec, Inc O'Nell1, J Oak Ridge National Laboratory	8403130378 8403290052* 8403260360 8403010102* 8403070392	PR FOIA 50-155 FOIA NUREO	Q
Northeast Utilities Service Co (subs of Northeast Utilities)	8403300092* 8403300092* 8403300135 8403300144 9403130360	50-245 50-245 50-245 50-213 50-423	0 R Q C		8403120255 8403150205 8403150219 8403150230 8403150237	REB 40-8781 NUREG 40-1341 40-1341	
Northern States Power Co	8403010018 8403010316 8403010316 8403020197 8403040285	PR FOIA 50-263 50-263 50-263	8 R F		8403170444 8403200358 8403230057 8403260286 8403300306	NUREG NUREG NUREG NUREG NUREG	
	8403060425 8403060425 8403090207 8403090270 8403120033	50-282 50-282 50-282 50-282 50-243	P F S	Office of Management & Budget	8403300317 8403300318 8403300325 8403020380 8403020381	NUREG NUREG NUREG ORG ORG	
	8403120088 8403130079 8403130087* 8403130076* 8403130103*	50-243 50-243 50-243 50-243	91 P R R		8403020383 8403020385 8403020387 8403020388 8403060458	GRG GRG GRG GRG GRG	
	8403130245 8403130258* 8403130258* 8403130270* 8403130270*	50-282 50-282 50-282 50-282 50-282	R R R R		B403060460 B403060463 B403230077 B403230080 B403260037	ORO ORO ORO ORO ORO	
	8403130278* 8403130365 8403190064 8403190200 8403190388	50-282 50-243 50-243 50-282 50-282	R G G	Ohio. State of	8403010085 8403070213 8403280076 8402130340* 8403130327	F01A 50-440 F01A 50-358 PR	A U
	8403190388 8403190397 8403200255 8403220003 8403230051	50-262 50-262 50-263 50-263 50-263	0 P 9 8	Omaha Public Power District	8403060187 8403270087 8402170156 8402170166* 8402170176*	QA999 QA999 50-265 50-265 50-265	р р Р
	8403270049 8403270170 8403270181* 8403290115	50-263 50-282 50-282 50-263	Р О І		8402210357* 8403010312 8403050099 8403050124	50-285 50-285 50-285 50-285	0 P F 8

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC.	₹Y	AUTHOR AFFILIATION	ACCEBBION NUMBER	SUBJECT	
<u> </u>	8403050135 8403050376 8403090234 8403120062 8403120183	50-285 50-285 50-285 50-285 50-285	R P F F	•	8403280051 8403280114 8403300075 8403300078 8403300141	50-133 50-275 50-133 50-275 50-275	1 # # E #
	8403120192* 8403120195* 8403130200 8403130458 8403170061*	50-285 50-285 50-285 50-285 50-285	P 0 0	Pacific Radiation Corp Pacific Scientific Palmetto Alliance	8403300148 8403130327 8403010075 8403130338* 8403070033	50-275 PR GA979 GA999 50-413	E
	8403170154 8403170281* 8403200176 8403270247 8403270253*	50-285 50-285 50-285 50-285 50-285	F G R G		8403070033 8403070037* 8403070037* 8403090112 8403090112	50-413 50-413 50-413 50-413 50-413	0 0 0
Gnline Computer Systems, Inc Oregon, State of Orrick, Herrington & Butcliffe	8403280165 8403280193 8403010534* 8403090159 8403090126	50-285 50-285 CONTRAC PR 50-445	F F T		8403090115* 8403090115* 8403220233 8403290377 8403290382	50-413 50-413 50-413 50-413 50-413	0000
Osage County, MD Oswego, NY Pacific Air Products Co Pacific Gas & Electric Co	8403070090 8403820327* 8403140122 8403020004 8403020006	50-483 CONTRAC 50-220 50-275 50-133	F T \$ R R	Parameter, Inc	8403270382 8403270388 8403270388 8403080173* 8403080177*	50-413 50-413 50-413 50-275 50-275	0000
	8403050178 8403070044 8403070044 8403070075 8403070077*	50-133 50-275 50-275 50-275 50-275	у С Р Р	Parkans International, Inc Pathfinder Mines Corp Pennsylvania Power & Light Co	8403020112 8403020115* 8403120251 8403150342 8403010294	XPORTL IC XPORTL IC 40-2259 40-2259 50-388	
	6403070083* 6403070284 6403070286* 6403070292* 6403070355	50-275 50-275 50-275 50-275 50-275	P P P F		8403020034 8403020253 8403020317 8403020327 8403020327	50-387 50-387 50-387 50-387 50-387	A 8 9 9
	0403080201* 0403080413 0403080414* 0403080415* 0403090172	50-275 50-275 50-275 50-275 50-275	E P P F		8403050090 8403050090 8403050108 8403050108 8403050116	50-387 50-387 50-387 50-387 50-387	4 4 4
	8403120006 8403120006 8403120010* 8403120010* 8403120012*	50-275 50-275 50-275 50-275 50-275	6 6 8		8403050122* 8403040108 8403040175 8403040175 8403040253	50-387 50-387 50-387 50-387 50-387	P G G
	8403120012* 8403120018* 8403120018* 8403120022* 8403120022*	50-275 50-275 50-275 50-275 50-275	6 6 6 6		8403040437 8403040437 8403070358 8403070209 8403090232	50-387 50-387 50-313 50-387 50-387	日はこれ
	8403120029* 8403120029* 8403120129 8403140153 8403150006	50-275 50-275 50-275 PR 50-275	Б		8403090239* 8403090239* 8403120024 8403120127 8403130020	50-387 50-387 50-388 TOPREP 50-397	8 8 A F
	8403150011 8403150013 8403150025 8403150048 8403150082	50-275 50-277 50-275 50-323 50-275	P 9 9 0		8403130059 8403130111 8403130150 8403140011 8403140018	50-397 50-397 50-399 50-397 50-397	R 7 日 日
	8403130147 8403200218 8403200220* 8403220035 8403220066	50-275 50-275 50-275 50-275 50-275	8 P P		8403150070 8403150070 8403150126 8403150126 8403160179	50-387 50-387 50-387 50-387 50-387	P F B
	6403220172 8403230139 8403230141* 8403230191 8403240174	50-275 50-275 50-275 50-275 50-275	E R G P		8403190232 8403190242 8403190242 8403190346* 8403190346*	50-387 50-387 50-387 50-387 50-387	F F 0
	8403250176 8403270004 8403270004 8403270004 8403270004	50-275 50-133 50-133 50-133 50-133	P 0 0 0		8403190395 8403190395 8403190405 8403200004 8403200071	50-387 50-387 PR 50-388 50-388	P P A E
	8403270037 8403270053 8403270057* 8403270063 8403270205	50-133 50-275 50-275 50-275 50-133	9 P P F		8403200073 8403200073 8403200103 8403200103 8403200250	50-397 50-397 50-397 50-397 50-397	4 4 4
	8403270205 8403270205 8403270205 8403280001 8403280033	50-133 50-133 50-133 50-275 50-275	F F F J		8403200292 8403210072 8403210072 8403210081* 8403210081*	50-387 50-387 50-387 50-387 50-387	F K K K

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO				AUTHOR AFFILIATION		ACCESSION NUMBER	SUBJEC CATEOD	
	8403210090* 8403210090* 8403210112 8403210125 8403210145	50-387 50-387 50-387 50-388 50-388	K K R S	 -	4 40 - 0 40 40 40		77) And 150, 150, 150, 150, 150, 150, 150, 150,	9403120175 9403130094 9403130158 9403150005 9403150024	50-276 50-352 50-276 50-277 50-252	8 8 8
	8403220040 8403220041 * 8403220067 8403220067 8403220102	50-388 50-387 50-387 50-387 50-387	A G G P					8403150024 8403150036 8403150036 8403150137 8403150137	50-352 50-352 50-352 50-277 50-277	0 C P P
	8403220102 8403220135# 8403220135# 8403220137 8403230095	50-387 50-387 50-387 50-387 50-388	P G P S					8403150140# 8403150140# 8403150143# 8403150143# 8403160010	50-277 50-277 50-277 50-277 50-252	6 6 6
	8403260226 8403260305 8403270195 8403300069* 8403300069*	50-387 50-388 50-387 50-387 50-387	8 A I G G					8403160010 8403160187* 8403160187* 8403160192 8403160192	50-052 50-052 50-052 50-052 50-052	0 0 0 A
Pannsylvania State Univ , University Park, PA Pannsylvania, Commonwealth of,	8403300147 8403010098* 8403040083 8403120001 8403190346	50-387 CONTRAC 50-320 50-352 50-387	R T H Q F					8403190197 8403190197 8403190198 8403200019 8403200060	50-352 50-352 50-277 50-277 50-352	A R S G
Petry, CH Philadelphia Electric Co	8403200015 8403300122 8403220219* 8401240207 8401240211*	50-352 50-352 50-352 50-352 50-352	G G					8403200060 8403200090 8403200090 8403200144 8403200144	50-352 50-352 50-352 50-352 50-352	0000
	8403010144 8403010144 8403010221 8403010221 8403010227*	50-352 50-352 50-463 50-463 50-463	E E O O					8403210028 8403210028 8403210045 8403210045 8403210055*	50-352 50-352 50-277 50-277 50-277	F P P
	8403010229# 8403010358 8403020104 8403020104 8403020105#	50-463 50-277 50-352 50-352 50-352	0 8 A A 0					8403210055* 8403210063* 8403210063* 8403210092 8403210092	50-277 50-277 50-277 50-352 50-352	P P 0 0
	8403020105* 8403020125 8403020125 8403020129 8403020129	50-352 50-352 50-352 50-352 50-352	0 0 T T					8403210103 8403210103 8403230012 8403260054 8403260054	50-352 50-352 50-171 50-277 50-277	0 R J J
	8403020136* 8403020136* 8403020163 8403020163 8403020257	50-352 50-352 50-352 50-352 50-352	T T G G					8403260249 8403260249 8403260333 8403260333 8403260349	50-352 50-352 50-352 50-352 50-352	E 0 0
	8403020257 8403020266* 8403020266* 8403020270* 8403020270*	50-352 50-352 50-352 50-352 50-352	A A C C					8403270012 8403270012 8403270017 8403270017 8403270042	50-352 50-352 50-352 50-352 50-352	G G G T
	8403020273# 8403020273# 8403050117 8403050141 8403050141	50-352 50-352 50-277 50-352 50-352	Ж Я Е Е					8403270042 8403270048* 8403270048* 8403270060 8403270064	50-352 50-352 50-352 50-352 50-277	T T C P
	8403050163* 8403060081 8403060081 8403060248 8403060248	50-352 50-352 50-352 50-352 50-352	E 9 9 9					8403270064 8403270067* 8403270067* 8403270071 8403270104	50-277 50-277 50-277 50-352 50-277	P P C F
	8403070142 8403070142 8403070234 8403070234 8403070238*	50-352 50-352 50-352 50-352 50-352	00000					8403270172 8403270250 8403280353 8403280353 8403270384	50-352 50-277 50-352 50-352 50-352	A G G G
	8403070238* 8403070281* 8403070361 8403070361 8403070055	50-352 50-352 50-352 50-352 50-352	0 F G					8403270384 8403300014* 8403300127 8403300127 8403300128	50-352 50-352 50-352 50-352 50-352	0 0 0
	8403090055 8403090081 8403090089* 8403090131 8403090285	50-352 50-277 50-277 50-277 50-277	Q Q Q B					8403300128 8403300129 8403300129 8403300271 8403300271	50~352 50~352 50~352 50~352	000
	8403070270 8403070270 8403120017 8403120085	50-352 50-352 50-278 50-277	F 8 8	Phi	ladelphia. i	PA		8403300274* 6403300274* 6403010271 8403010271 8403010275*	50~352 50~352 50~352 50~352 50~352	0 0 0

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT SOBJECT ROOSTAD	
Philbrick, S S Photocraft Custom Lab, Inc	8403010275* 8403040127 8403190007 8403160053 8403130495*	50-352 50-352 50-352 ACRS CONTRACT	G G G		8403050112 8403060309 8403130177 8403130396 8403130435	50-247 50-247 50-247 50-247 50-247	O R P R
Pittsburgh, Univ of, Pittsburgh, PA Plateau Resources, Ltd	8403150041 8403290238 8403150213 8403150249 8403220183	50-320 PRM 40-8698 40-8698 40-8698	Þ		8403160229 8403160233* 8403160303 8403160326 8403190344	50-267 50-267 50-267 50-267 50-267	P G G R
Plymouth. MA Porter Consultants, Inc Portland General Electric Co	8403220187* 8403220191 8403220262* 8403230048 8403010175*	40-8698 40-8674 CONTRACT 50-322 50-344	т р		8403190350 8403190357* 8403190359* 8403220063 8403220138	50-267 50-267 50-267 50-267 50-267	P P P 8 F
	8403010355 8403020050 8403060382 8403060384 8403140137	50-344 50-344 50-344 50-344 PR	S R P H	Public Service Co of New Hampshire	8403270189 8403270191* 8403270192 8403270194* 8403070042	50-267 50-267 50-267 50-267 50-443	Р Г Р
	B403190325 B403190378 B403200141 B403200197 B403220247	50-344 50-344 50-344 50-344 50-344	P F G J G		8403070042 8403080142 8403080142 8403090093 8403090093	50-443 50-443 50-443 50-443 50-443	0 0
	8403260216 8403280022 8403280041 8403300106 8403300168	50-344 50-344 50-344 50-344 50-344	5 J R P		8403090124 8403090124 8403130468 8403150080 8403150100	50-443 50-443 50-443 50-443 50-443	0 9 4
Posi-Seal Valves International Power Authority of the State of New York	8403300272 8403040304* 8401200078 8403010241 8403010365	50-344 50-324 50-286 50-333 50-333	G P V 8 8		8403160256 8403160256 8403160263* 8403210099 8403210099	50-443 50-443 50-443 50-443 50-443	F F A A
	8403010413 8403010420 8403020327 8403020351 8403060193	50-333 50-333 50-333 50-333 50-333	R R F P S		8403210101* 8403210142 840322005 8403220150 8403220150	50-443 50-443 50-443 50-443 50-443	A 9 9
	8403070025 8403070211 8403070267 8403120024 8403120152	50-333 50-286 50-286 50-333 50-286	9 F P		8403220164 8403230164 8403230061 8403230180 8403230180	50-443 50-443 50-443 50-443 50-443	8 A Q
	8403130137 8403130162 8403130256 8403130350 8403130412*	50-333 50-286 50-286 50-333 50-286	저 F R R	Public Service Electric & Gas Co of New Jersey	2107270121 1210725048 7420055048 40210012048	50-443 50-443 50-443 50-272	A A Q B
	8403130466 8403140153 8403150047 8403150050 8403160009	50-233 PR 50-286 50-286 50-286	9 8 9 9		8403040312 8403070240 8403070240 8403070241* 8403070241*	50-272 50-272 50-272 50-272 50-272	V R R R
	8403160017* 8403160021* 8403190265* 8403200094 8403200096*	50-286 50-286 50-286 50-333 50-333	P B B P P		8403070305 8403070305 8403080013 8403080246 8403080252	50-272 50-272 50-272 50-272 50-272	R R B S
	8403200231 8403210049 8403210113 8403220081* 8403260091	50-333 50-286 50-286 50-333 50-286	S S H Q S		8403090049 8403090080 8403090080 8403090080 8403090080	50-272 50-272 50-272 50-272 50-272	P G G
	8403250171 8403250257 8403270185 8403290100 8403290152	50-233 50-284 50-333 50-284 50-286	P 5 F P		8403130014* 8403130017 8403130108 8403130372* 8403130384	50-354 50-272 50-311 50-354 50-311	0 P 0 8
Prairie Alliance Project Management Corp	8403290246 8403300159 8403300175 8403070123* 8403020100	50-333 50-284 50-284 50-441 50-537	8 R O O		8403140007 8403140113 8403140117* 8403140117*	50-354 50-354 50-354 50-354 50-354	A A A A
Public Service Ca of Colorado	8403050082 8403090086 8403010101 8403010107 8403010116	50-537 50-537 50-267 50-267 50-267	C G P G G		8403150020 8403150022* 8403150108 8403200102 8403210036	50-354 50-354 50-354 50-354 50-354	9 9 8 9
	8403010118 8403010134 8403010155* 8403010167* 8403010304	50-267 50-267 50-267 50-267 50-267	8 5 5 0		8403210118 8403220036 8403220036 8403220039	50-354 50-272 50-272 50-311	8 0 0

Ľ

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8403220142 8403220151 8403220174 8403230041 8403270099	50-311 R 50-311 S 50-272 R 50-254 C 50-311 S		8403060387 8403060452 8403060467 8403130112 8403130125	50-312 F 50-312 9 50-312 8 50-312 8 50-312 P
	8403270244 8403290277 8403290281 8403290281 8403290302	50-272 S PR 50-272 P 50-272 P 50-354 A		8403190275 8403200001 8403200045 8403200184 8403230056	50-312 Q 50-312 P 50-312 R 50-312 B 50-312 B
	8403300085 8403300085 8403300121 8403300177# 8403300183#	50-272 P 50-272 P 50-354 Q 50-272 Q 50-272 Q	Sacramento, CA Salem, NJ San Diego Gas & Electric Co	8403260124 8403260215 8403280187* 8403260307* 8403160063	50-312 J 50-312 P CONTRACT CONTRACT 50-206 H
Pullman, Inc Querytech, Inc	8403300186* 8403300190* 8403300270 8403270155 8403280316	50-311 0 50-311 0 50-354 0 MISC ACRE	San Luis Obispo Mothers for Peace Sandia Laboratories	8403060303* 8403150010 8403200133 8403260364 8403010076*	50-275 G 50-275 G 50-275 G 50-275 G FOIA
Radiation Technology, Inc	8403280341 8403080040* 8403080046* 8403080055* 8403080064*	ACRS FOIA FOIA FOIA FOIA	Sandvik Special Metals Corp Sangamo Weston, Inc	84030B0029# 8403260353* 8403360342 8403290327 8403290180	FOIA WASTE NOT NUREG XPORTLIC PRM
	8403080076* 8403080078* 8403080084* 8403080089* 8403080111*	FDIA FOIA FOIA FOIA FOIA	Sargent & Lundy, Inc Schiff, Hardin & Waite Schirmer Engineering Corp	8403190278* 8403070120 8403140180* 8403140183* 8403140184*	50-454
	8403080134* 8403080137* 8403080150* 8403080163* 8403080167*	FOIA FOIA FOIA FOIA FOIA	Science Applications, Inc	8209030161* 8403010027* 8403010041* 8403010102* 8403050032*	90-280 () CONTRACT FOIA FOIA 70-687
Rensselaer Polytechnic Institute, Troy, NY	8403080148* 8403080172* 8403080185* 8403040204	FDIA FOIA FOIA 50-225 F		8403050035* 8403080006* 8403080010* 8403080012*	50-286 P FOIA FOIA FOIA FOIA
Rauter-Stokes, Inc	8403190427 8403260229 8403260156 8403040369 8403040573* 8403220328	NUREG 50-225 R 50-225 R XPORTLIC XPORTLIC XPORTLIC		8403080017* 8403080017* 8403080025* 8403080268* 8403080273*	FOIA FOIA FOIA 50-278 F 50-278 F
Rio A)gom, Lt¢ Robert Bhaw Controls Co Rochester Gas & Electric Corp	8403150208 8403150274 8403270282 8403080202 8403080115	40-8084 40-8084 9A979 50-244 R 50-244 P	Seacnast Anti-Pollution League Senote	8403080306* 8403240341* 8403010385 8402220288 8402220303*	50-298 F CDNTRACT FOIA 50-289 U 50-287 U
	84030&012&* 8403130132 84032&0198 84032&0243 8403270150	50-244 P 50-244 R 50-244 P 50-244 F 50-244 G		8403150341* 8403170040* 8403200200* 8403200211* 8403280156*	50-272 U 50-320 H 50-289 G 50-289 G
	8403270152 8403280049 8403290185 8403300081 8403300191*	50-244 0 50-244 P 50-244 P 50-244 R 50-244 Q	Senate, Energy & Natural Resources Sequoyah Fyels Corp Shaw, Pittman, Potts & Trowbridge	8012140551* 8402130392* 8403010071 8403010009 8403010187	50-397 U 50-358 U 40-8768 50-289 G 50-382 G
Rochester, NY Rocklestes Co Rockland County, NY Rockwell International Corp	8403260370# 8403010128 8403060262 8403010170 8403150315	CONTRACT GA979 GA979 SO-247 H WABTE MGT		8403010263 8403020106 8403020106 8403020182 8403020182	50-400 6 50-440 6 50-440 6 50-400 6 50-400 6
Ropes & Gray	8403260347* 8403300248 8403070042 8403080142 8403080142	WASTE MGT WASTE MGT 50-443 G 50-443 G		8403020188* 8403020188* 8403060084 8403060090 8403060257	50-400 0 50-400 0 50-287 0 50-424 0 50-440 0
	8403090093 8403090093 8403090124 8403090124 8403150080	50-443		8403060275 8403060275 8403060461 8403060464 8403070025	50-440 G 50-440 G FOIA FOIA 50-269 G
SRI International Bacramento Municipal Utility District	8403210101* 8403230180 8403300247 8403010078* 8403010388	50-443 A 50-443 Q 50-443 Q CDNTRACT 50-312 P		8403070134 8403070134 8403070191 8403070225 8403070225	50-400 G 50-400 G 50-445 G 50-400 G
	8403020350 8403050007 8403050008# 8403060141	50-312 P 50-312 P 50-312 P 50-312 J		8403080105 8403080140 8403130010 8403130139 8403130139	30-267 9 50-440 M 50-440 Q 50-440 Q 50-440 Q

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEOD		AUTHOR AFFILIATION	ACCESSION NUMBER	CATEODI SUBJEC	
	8403130156 8403130156 8403130403 8403130403 8403130443	50-400 50-400 50-440 50-440 50-289	G G G G		8403050003 8403050140 8403050143+ 8403060174 8403060363	50-361 50-206 50-206 50-206 50-206	S S S X
	8403130447 8403130447 8403130457* 8403130459* 8403150001	50-400 50-400 50-400 50-400 50-440	0 0 0		8403040343 8403040363 8403040378 8403040395 8403040395	202-06 202-06 202-06 202-06 202-06	7 8 X
	8403150009 8403150009 8403160018 8403190035 8403200030	50-440 50-440 50-400 50-482 50-400	G G G		8403060395 8403060399 8403060403 8403060424 8403060424	50-206 50-206 50-361 50-361 50-361	J 8 P P
	8403200055 8403200066 8403200120 8403200135 8403210175	50-287 50-287 50-287 50-400 50-287	0 0 0		8403060427* 8403060427* 8403060438 8403060438 8403070254	50-361 50-361 50-206 50-206 50-206	P P R P
	8403210187 8403210193 8403220261 8403240325 8403260327	50-287 50-287 50-400 50-482 50-400	9 9 9		8403090127 8403090127 8403090177 8403090177 8403090227#	50-361 50-361 50-361 50-361 50-361	0 0 P P
	8403260327 8403260328 8403260328 8403260345 8403260348	50-400 50-400 50-400 50-289 50-400	9		8403090230* 8403090233* 8403090238* 8403120044 8403130134	50-361 50-361 50-361 50-361 50-361	6 6 6
	8403260348 8403260354* 8403260354* 8403270327 8403270385	50-400 50-400 50-400 50-400 40-2061	G G G		B403150031 B403150033 B403150057 B403150074 B403140251	50-206 50-361 50-361 50-361 50-206	F 8 8 8
Shoreham, NY Signans-Allis, Ing Sierra Club	8403290386 8403270284* 8403300099 8403120038 8403190120	50-287 CONTRAC PT21 50-204 50-537	T H		8403170345 8403170345 8403200053 8403200053 8403200057*	50-361 50-361 50-361 50-361 50-361	P R R
Signa Chemical Co Silver King Mines, Inc Bouth Carolina Electric & Gas Co	8403020428 8403150153 8403200390 8403020039 8403020297	XPDRTL I XPORTL I 40-8402 50-395 50-395	C		9403200057# 9403200074# 8403200074# 8403200077# 8403200082#	50-361 50-361 50-361 50-361 50-361	R R R R
	8403060128 8403060130* 8403060242 8403060351 8403070040	50~375 50~375 50~375 50~375 50~375	P 8 8		8403200086* 8403200088* 8403200091* 8403200097 8403200097	50-361 50-361 50-361 50-206 50-206	R R F F
	8403070129* 8403070337 8403080153 8403070052 8403070249	50-375 50-375 50-375 50-375 50-375	0 8 8 8		8403200097 8403200175 8403200194 8403210009 8403210065	50-205 50-362 50-361 PR 50-205	F 9 8
	8403070271 8403130260 8403130371 8403130397 8403150042	50-395 50-395 50-395 50-395 50-395	9 5 8		8403220018 8403220018 8403220018 8403220024* 8403220027*	50-206 50-206 50-206 50-206 50-206	F F F
	8403270183 8403270188* 8403270223 8403270225* 8403300145	50-395 50-395 50-395 50-395 50-395	12 12 13 14 14 15 15 16 16 16 16 16 16 16 16 16 16 16 16 16		8403220027* 8403220027* 8403220121 8403220125* 8403230074	50-206 50-206 50-206 50-206 50-361	F P P R
South Carolina, State of South Dakota, State of Southern California Edison Co	8403020339# 8403050113# 8403130236 8402030338 8402030338	Waste M 50-238 Pr 50-204 50-204	70 R1 F		8403230118 8403270164 8403270256 8403270256 8403270256	50-361 50-362 50-206 50-206 50-206	Q F F F
	8402030338 8402030344* 8402030344* 8402030344* 8402230176	50~206 50~206 50~206 50~206 50~133	구 두 두 루		8403280002 8403280030 8403270122 8403270182 8403270217	50-361 50-206 50-206 50-206 50-361	8 F P P
	8403020010 8403020010 8403020040 8403020040 8403020092	50-341 50-341 50-341 50-341 50-341	R R R R	Eculand Power Cooperative, Inc. Spiegel & McDiarmid Stamiris, D	8403270275 8403300003 8403270102* 8403270176 8403140117	50-206 50-206 50-461 50-458 50-329	P R I H
	8403020092 8403020098* 8403020098* 8403020218 8403020275	50-361 50-361 50-361 50-206 50-206	P P R S	Stan A, Huber Consultants, Inc Standard Oil Co of Indiana (see also AMGO) Standardized Nuclear Unit Power Plant	8403200139 7906230470* 8403210009 8402090302	50-329 FOIA PR 50-482	Q A
				Sustem			

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC' CATERO!		AUTHOR AFF]LIATION	ACCESSION NUMBER	SUBUFC CATEGO
·	8403010213 8403010213 8403010213 8403010270 8403010270	50 - 482 50 - 482 50 - 482 50 - 482 50 - 482	 a a a F F	Suffolk County, NY	8403200152* 8403010234 8403010237 8403010244 8403040208	50-423 50-322 50-322 50-322 50-322
	8403010270 8403010406 8403060298 8403130342 8403200050	50-482 50-482 50-482 50-482 50-482	F A A E		8403060254 8403060259* 8403060266* 8403060268 8403060270*	50-322 50-322 50-322 50-322
	8403200187 8403200187 8403200187 8403200189* 8403200253	50 - 482 50 - 482 50 - 482 50 - 482 50 - 482	K K K F		8403040278* 8403060287* 8403060275* 8403040301*	50-322 50-322 50-322 50-322 50-322
	8403200253 8403200253 8403220019 8403220019 8403220019	50-482 50-482 50-482 50-482 50-482	F A A		8403040310* 8403040314* 8403040318* 8403040319*	50-322 50-322 50-322 50-322 50-322
	8403220026 8403220029 8403220029 8403220029 8403220184	50-482 50-482 50-482 50-482 50-482	A A A A		8403040338 8403130003 8403130029 8403130146 8403130174	50-322 50-322 50-322 50-322 50-322
	8403220184 8403220184 8403240282 8403240282 8403240282	50-482 50-482 50-482 50-482 50-482	A A A A		8403150026 8403200128 8403200131 8403200134* 8403200136*	50-322 50-322 50-322 50-322 50-322
State, Dept of, Bureau of Oceans & Intl Environ & Scientific Affairs	8403290128 8403200395 8403280072	50~482 XPORTL I (XPORTL I (8403200140* 8403200145* 8403200146* 8403200151*	50-322 50-322 50-322 50-322
Stone & Webster Engineering Corp	8403290404 8403010115 8403020290#	XPORTL IC TOPREP			8403200155* 8403200159* 8403210186	50-322 50-322 50-322
	8403160096* 8403200182 8403270122* 8403270157*	50-412 50-423 50-322 50-322	A A R S		8403220250 8403220288 8403220292*	50-322 50-322 50-322
Stone & Webster, Inc	8403300035 8403360407* 8403360411 8403360415* 8403360420*	50-329 50-329 50-329 50-329 50-329	8 8 8 9		8403220397* 8403220302* 8403220305* 8403220310* 8403220313*	50-322 50-322 50-322 50-322
	8403060423# 8403060428# 8403060442# 8403060444# 8403060445*	50-327 50-329 50-329 50-329 50-329	Q Q Q Q Q		8403280346 8403280357 8403280358 8403290248 8403290377	50-322 50-322 50-322 50-322 50-322
	8403080172 8403080172 8403080221 8403080221 8403080250	50-329 50-329 50-329 50-329 50-329	9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9	Suffulk Nuclear Study Group Sugamman & Denworth	8403290383 8403290390 8403300170 8403080363 8403130411	50-352 50-322 50-322 50-322
	8403080250 8403130074 8403130173	50-329 50-329 50-329	8 8	Sunflower Alliance TDI (Transomerica Delaval, Inc.) Owners Group	8403270075 8403010207 8403010218	50-440 50-322 50-206
	8403130173 8403130184 8403130184	50-329 50-329 50-329	9 9		8403140075* 8403150133 8403170385*	50-322 50-206 50-222
	8403130195 8403130238 8403130238 8403130271	50-329 50-329 50-329 50-329	. s s s s s		8403200143* 8403270132 8403270132 8403270132	90-355 90-355 90-355
	8403130297 8403130297 8403130321 8403130321 8403130388	50-329 50-329 50-329 50-329 50-329	Q Q S S A		8403270132 8403270132 8403270132 8403270132 8403270132	50-322 50-322 50-322 50-322 50-322
	8403130388 8403130470 8403130470 8403130479 8403150154*	50-329 50-329 50-329 50-329 50-206	A A A S S		8403270132 8403270132 8403270132 8403270132 8403270132	50-322 50-322 50-322 50-322 50-322
	8403270062 8403270062 8403270093 8403270096 8403270096	50-329 50-329 50-329 50-329 50-329	r r 8 8 8		8403270132 8403270132 8403270132 8403270132 8403270132	50-322 50-322 50-322 50-322
Streich, Lang, Werks & Cardon Structural Mechanics Associates	8403270227 8403300006 9403080385 8403140026*	50-329 50-329 50-528 50-329	s s d a		8403270132 8403270132 8403270132 8403270132	50-322 50-322 50-322 50-322

AUTHOR AFFILIATION	ACCEB810N NUMBER	SUBJECT CATEGGS		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	Y
	8403270132 8403270134 8403270134 8403270134 8403270134	50-322 50-206 50-206 50-206 50-206	8 9 9 8 8		8403060189* 8403060189* 8403060189* 8403060189* 8403060189*	50-259 50-259 50-259 50-259 50-259	두 후 두
	8403270134 8403270134 8403270134 8403270134 8403270134	50-206 50-206 50-206 50-206 50-206	5 9 9 9 8		8403060189* 8403060189* 8403060189* 8403060206* 8403060206*	50-257 50-257 50-257 50-257 50-257	F F F F
	8403270134 8403270134 8403270134 8403270134 8403270134	50~206 50~206 50~206 50~206 50~206	ទ ម ខ ខ ខ ខ ខ ខ ខ ខ ខ ខ ខ ខ ខ ខ ខ ខ ខ ខ		8403060206* 8403060206* 8403060206* 8403060206* 8403060206*	50-259 50-259 50-259 50-259 50-259	# # #
	8403270134 8403270134 8403270134 8403270134 8403270134	50-206 50-206 50-206 50-206 50-206	8 8 8 8		8403040206* 8403060235 8403040238 8403060244 8403060276	50-259 50-259 50-259 50-259 50-327	F F 80 83
TERA Cory	8403270134 8403270134 8403270134 8403270134 8403050010*	50-206 50-206 50-206 50-206 50-312	មាន មេ ម		8403060391 8403070023 8403070054 8403070066 8403070089	50-327 50-259 50-259 50-438 50-438	6 0 0
	8403060370 8403080260 8403220013 8403220013 8403220022*	50-329 50-329 50-329 50-329 50-329	А А Я Я		8403070092 8403070155* 8403070174 8403070174 8403070224*	50-390 50-327 50-390 50-390 50-438	0 9 9 8
	8403220022* 8403220100 8403220100 8403220113 8403270159	50-329 50-329 50-329 50-329 50-329	R A A A		8403070230 8403070235 8403070237 8403070241 8403070245	50-390 50-390 50-259 50-438 50-390	0 0 0 0
Tactec Systems, Inc Tameran, Inc Target Research, Inc	8403270159 8403280263* 8403150278* 8403150306* 8403220173*	50-329 CONTRACT CONTRACT CONTRACT 40-8824	ř .		8403070271 8403070286 8403070286 8403070274 8403070274	50-257 50-390 50-390 50-438 50-438	9 8 8
Tayloe Associates Technical Operations, Inc Teledyne Engineering Services Teledyne Isotopes Tennessee Valley Authority	8403010437* 8403140151 8403070304 8403140144 8402070360	CONTRACT PR 50-245 PR 50-370	г Р Г		8403070295 8403070295 8403070297 8403070297 8403070329	50-327 50-327 50-438 50-438 50-438	R R S S
	8402070380 8402090384* 8403010095 8403010226 8403010306	50-370 50-370 50-438 50-257 50-257	F 5 9 9		8403070327 8403070024 8403070050 8403070050 8403070085	50-438 50-438 50-370 50-370 50-259	9 9 9
	8403010306 8403010306 8403010313* 8403010313* 8403010313*	50-259 50-259 50-259 50-259 50-259	역 명 명 명		8403090143 8403090143 8403090181 8403090181 8403090206	50-438 50-438 50-438 50-438 50-370	8 8 8
	8403010339 8403010371 8403010376 8403020002 8403020002	50-390 50-259 50-438 50-327 50-327	5 \$ 8 R R		8403090204 8403090245 8403090253 8403120105 8403120105	50-390 50-259 50-259 50-438 50-438	9 9 9 6
	8403020103 8403020103 8403020147 8403020236 8403020236	50-259 50-259 50-327 50-390 50-390	R R S F		8403120105 8403120163 8403120179 8403130007 8403130007	50-438 50-438 50-390 50-259 50-259	6 6 8
	8403020244 8403020313 8403020313 8403020325 8403020334	50-327 50-327 50-327 50-259 50-390	e e e		8403130007 8403130025 8403130025 8403130025 8403130088	50-259 50-259 50-259 50-259 50-327	P P G
	8403050080 8403060147 8403060147 8403060147 8403060147	50-327 50-259 50-259 50-259 50-259	8 F F F		8403130100# 8403130181 8403130205 8403150007 8403150059	50-327 50-260 50-259 50-439 50-438	0 8 8 8
	8403060147 8403060147 8403060143* 8403060163* 8403060163*	50-259 50-259 50-259 50-259 50-259	F F F		8403150079 8403150127 8403150229 8403160042 8403160171*	50-327 50-370 40-134 50-438 50-259	9
	8403040143* 8403040143* 8403040143* 8403040143*	50-259 50-259 50-259 50-259 50-259	Р F F F		8403140171* 8403160171* 8403160223* 8403160318* 8403160318*	50-259 50-259 50-259 50-259 50-259	G G

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEOOF		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8403160318# 8403160364# 8403160373 8403160373	50-259 50-259 50-259 50-259 50-259	Q Q P P		8403070191 8403080327* 8403080332* 8403080335* 8403130116	50-445 G 50-445 G 50-445 G 50-445 G 50-445 F
	8403160373 8403160373 8403190054 8403190054 8403190099	50-259 50-259 50-390 50-390 50-390	P 8 9 9		8403130116 8403130126* 8403130126* 8403130136* 8403130160	50-445 F 50-445 F 50-445 F 50-445 V
	8403190121 8403190125 8403190149* 8403190149* 8403190149*	50-327 50-259 50-259 50-259 50-259	8 9 0 0		8403130160 8403130313 8403130313 8403130319* 8403140013	50-445 F 50-445 F 50-445 F 50-445 G
	8403190161* 8403190287 8403190358 8403190358 8403190365	50-259 50-438 50-390 50-390 50-327	0 6 8 8 8		8403140013 8403140020 8403140020 8403140147 8403150032	50-445 G 50-445 G 50-445 G PR 50-445 G
	8403190369 8403190370 8403190371 8403200059 8403200059	PR 50-327 50-259 50-259 50-259	F 8 0		8403150103 8403140079 8403140079 8403140083* 8403140213	50-445 E 50-445 A 50-445 A 50-445 B
	8403200059 8403200087 8403200170 8403200170 8403200171	50-259 50-296 50-259 50-259 50-260	0 8 P 8	Texas, State of Texas, Univ. of, Austin, TX	8403230057 8403270031 8403010132* 8403230025 8403140189	50-445 H 50-445 G 50-478 G WASTE MOT FRM
	8403200213 8403200225 8403210037 8403210037 8403210042	50-259 50-390 50-390 50-390 50-438	S A 8 B B	Three Mile Island Alert Titeflex Corp Toledo Edison Co	8403130065 8403260382 8403210095 8403270108 8401160250	50-287 0 50-287 0 50-346 8 0A797 50-346 8
	8403210042 8403210046 8403210066 8403210066 8403210086	50~438 50~438 50~390 50~390 50~390	ទ ទ ទ ទ		8403020078 8403050107 8403050251 8403130133 8403130143*	50-346 R 50-346 F 50-346 R 50-346 P 50-346 P
	8403210132 8403210132 8403220046 8403220159 8403220220	50-438 50-438 50-259 50-260 40-1341	ន ន ន		8403130154# 8403130276 8403130427 8403150085 8403170107	50-346 P 50-346 P 50-346 P 50-346 P 50-346 R
	8403220224* 8403260164 8403260212 8403260212 8403260218	40-1341 50-327 50-390 50-390 50-390	8 A A		8403170213 8403170311 8403170347# 8403200008 8403200046	50-346 R 50-346 F 50-346 9 50-346 0 50-346 F
	8403260218 8403260229 8403260277 8403270145 8403270145	50-370 50-257 50-327 50-370 50-370	A P F F		8403200052* 8403200058* 8403200063* 8403230009 8403270167	50-344 P 50-344 P 50-344 P 50-344 F 50-346 F
	8403270218 8403270218 8403270024 8403270038 8403270183*	50-390 50-390 50-327 50-327 50-259	E P G		8403300149 8403300156* 8403300158* 8403300163 8403300178	50-346 P 50-346 P 50-346 P 50-346 J
	8403270183* 8403270183* 8403270207* 8403300004 8403300004	50-259 50-259 50-259 50-438 50-438	0 0 8 8	Trammell, Chase, Lambert & Martindale Transamerica Delaval, Inc	8403300184 8403270334 8403120136 8403120180 8403130316	50-346 R FDIA 50-416 B TOPREP GA999
	8403300021 8403300021 8403300038 8403300038 8403300039	50-438 50-438 50-370 50-390 50-438	8 E B	Transnuclear, Inc.	8403200222 8403070024* 8403020453* 8403140308* 8403150169	50-204 B XPORTLIC XPORTLIC XPORTLIC
	8403300037 8403300054 8403300073 8403300107 8403300133	50-438 50-438 50-327 50-370 50-259	8 8 8 8 R		8403150167 8403150184* 8403250027 8403250030* 8403280055*	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
	8403300133 8403300136* 8403300139* 8403300154	50-257 50-257 50-257 50-327	R R R	Troutman, Sanders, Lockerman & Ashmore Tofts Univ , School of Medicine, Medford, MA U S Ecology, Inc. (formerly Nuclear	8403080370 8403140172 8403010341	50-424 () PR 27-40
Tunnesses, State of	8403300154 8403300204	50-328 PR	# #	Engineering, Inc.)	8403010341 8403010349 8403020377	27-48 27-48 27-48
Terry Corp. Terms Utilities Electric Co. (formerly Terms Utilities Generating Co.)	8403210032 8403040155 8403040299	50-260 50-445 50-445	A A	Union 76 Minerals Exploration Co Union Carbide Corp.	840322006B 8403220071* 8403010012	40-8584 40-8584 40-299

AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJEC CATEGO	DRY	AUTHOR AFFILIATION		ACCESSION NUMBER	BUBJECT	
	8403070266 8403130045 8403130052# 8403150284 8403200374#	40-277 50-54 50-54 40-277 40-868	P P	Vester J Thompson, Jr , Inc		8403300071# 8403300144# 8403300153 8403070161# 8403070167#	50-271 50-271 50-271 CONTRACT	
Union Electric Co	8403220043 8403270178 8403300140* 8402270156 8403050014	50~54 50~54 70~687 50~483 50~483	r K	Vet Admin Hosp Lexington,KY Vet Admin Hosp Lome Linda,CA Vet Admin Hosp Portland.DR Veterans Admin Medical Center, Washington, DC		8403170326 8403270257 8403270253 8403270311 8403130302*	PR PRM PRM PRM 70-2199	
	8403050018* 8403050019* 8403090204 8403090263 8403090283	50~483 50~483 50~483 50~483 50~483	K F F F	Veterans Admin Medical Center, Virginia Electric & Power Co	Waad, WI	8403130308* 8403290259 8401130314 8403020001 8403020001	70-2199 PRM 50-280 50-338 50-338	P Q Q
	8403120104 8403120171 8403120182 8403130409 8403160246	50~483 50~483 50~483 50~483 50~483	A A F F			8403020042 8403020042 8403020053 8403020059* 8403020063*	50-338 50-338 50-280 50-280 50-280	P P R R
	8403150323 8403170034 8403170267 8403200028 8403200028	50~493 50~483 50~483 50~483 50~483	A S A S S			8403020066* 8403020071* 8403020076* 8403020085* 8403020070*	50-280 50-280 50-280 50-280 50-280	R R R R
	8403200237 8403200285* 8403210121 8403230115 8403270014	50-483 50-483 50-483 50-483 50-483	P Q A B A			8403020122 8403020195 8403040153 8403040397 8403040397	50-338 50-280 50-338 50-280 50-280	R P B F
	8403270079 8403270182 8403270187 8403270229 8403300209	50-483 50-483 50-483 50-483 50-483	8 8 A F			8403080071 8403080091 8403080091 8403080091 8403080091	50-339 50-280 50-280 50-280 50-280	111141
Union Minerals Union of Concerned Scientists	8403220117 8403220124* 8403280059 8310200141 8403010010	40-8584 40-8584 40-8584 FOIA 50-289				8403080091 8403080264 8403080264 8403080264 8403080264	50-280 50-280 50-280 50-260 50-260	# # # # #
	8403010021 8403020052 8403020082 8403050017 8403050058	FOIA FOIA FOIA 50-286 FOIA	q			8403080264 8403080267* 8403080267* 8403080267* 8403080267*	50-280 50-280 50-280 50-280 50-280	FFFF
	8403080003 8403080021 8403080344 8403080346 8403080334	FOIA 50-336 FOIA FOIA	Þ			8403080269* 8403080341* 8403090151 8403090151 8403090213	50-280 50-280 50-280 50-280 50-338	FOFFS
United Engineers & Constructors, Inc	8403210014 8403060311	50-289 50-443	e 8			8403090213	50-338	9
(subs of Raytheon Co) United Nuclear Corp	8403010289 8403150214 8403190234#	70-371 50-30 70-371	u			8403070223 8403070242 8403070250 8403120174	50-280 50-280 50-280 50-336	8 F B P
Upsala College, East Orange, NJ Uranerz USA, Inc Utah, State of Utah, Univ of, Salt Lake City, UT	8403070267* 8403170411 8403170412 8403140027 8403140145	70-474 40-8783 40-8783 WASTE MG 50-407	τα ≄			8403120176 8403130278 8403130278 8403130424 8403140010	50-338 50-338 50-338 50-260 50-338	Р Р В В
	9403200281 8403200281 8403200293* 8403200293* 8403200296*	50-72 50-72 50-72 50-72 50-72	न म म म			8403140184 8403140184 8403140184 8403140184 8403140184	50-280 50-280 50-280 50-280 50-280	9
Utility Safety Classification Group Validyne Engineering Corp Vanderbilt Univ , Nashville, TN	8403200296# 8403280063 8403290305# 8403290308# 8403070414#	50-72 50-322 50-354 50-354 CONTRAC	F G A A			8403190052 8403190080 8403190201 8403190204* 8403190263	50-280 50-338 50-339 50-339 50-280	F 8 P F
Vermont Yankee Nuclear Power Corp	8403020247 8403020322 8403020326* 8403020328* 8403120003	50-271 50-271 50-271 50-271 50-271	6 8 8 8			8403190263 8403190377 8403190377 8403190381# 8403190381#	50-290 50-338 50-338 50-338 50-338	F P P
	8403120005* 8403130481 8403170086 8403200156 8403200274	50-271 50-271 50-271 50-271 50-271	P R G G			8403190396 8403190396 8403200116 8403210117 8403210117	50-338 50-338 50-280 50-280 50-280	9 8 F F
	8403200277* 8403230063 8403230140 8403270190	50-271 50-271 50-271 50-271	Q F R P			9403220028 8403220028 8403220032* 8403220032*	50-338 50-338 50-338 50-338	р Р Р

AUTHOR AFFILIATION	ACCESSION NUMBER	BURJEC	DRY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8403220077 8403220077 8403230146 8403260105 8403260105	50-338 50-338 50-280 50-280 50-280	P # P P	West Chicago, IL Wastern Illinois Power Cooperative, I Wastern Nebraska Resources Council Wastern Nuclear, Inc (subs of Phelp Dodge Corp)	8403150286	40-2061 50-461 40-8829 40-8684
	8403240110*	20-580	P	Western Water Consultants, Inc	8403150212	40-8663
	8403240110# 8403270021 8403270021 8403270021	50-280 50-280 50-280 50-280 50-338	P G G G	Hestinghouse Electric Carp	8403010326 8403010463 8403010484 8403010545 8403050044	70-1149 XPORTLIC XPORTLIC XPORTLIC XPORTLIC
	8403270208 8403270248 8403280125 8403290157	50-338 50-337 50-280 50-280	P P F a		8403050047 8403050050 8403050120 8403060076# 8403060101#	XPORTLIC XPORTLIC GA999 GA999 GA999
	8403290240* 8403300003 8403300028 8403300028 8403300055	50-338 50-338 50-338 50-338 50-338	G P P R		8403060326* 8403070302* 8403090201 8403090259*	50-213 . 50-423 . PR 50-348 .
Virginia, Commonwealth of, Virginia, Univ. of, Charlottasville, VA	8403300055 8403300040 8403300040 8403200331 8403010397	50-338 50-280 50-280 WASTE M 50-62	원 원 곳 19T 문		8403070327# 8403120027# 8403130358* 84031303875* 8403130389* 8403150195	TOPREP 50-275 ' 50-482 ' 50-482 '
Washington Public Power Supply System	6201190297* 6208120240* 6208120240* 6208120240* 6208120240*	50-397 50-397 50-397 50-397 50-513	F F F F		8403170139 8403170261* 8403170377* 8403170404* 8403210015	GA999 50-369 . 50-413 .
	8208120248* 8208120248* 8208120248* 8208120248* 8403020097	50-397 50-397 50-397 50-513 50-397	F F F R		8403210020 + 8403220294 + 8403230208 8403240075 + 8403240201 +	TOPREP XPORTLIC NURSES 50-266 50-244
-	8403020330 8403070187 8403070118 84030901R1 8403090236	50-397 50-397 50-508 50-397 50-397	<u>፡</u> ፡፡ ፡፡ ፡፡ ፡፡ ፡፡ ፡፡ ፡፡ ፡፡ ፡፡ ፡፡ ፡፡ ፡፡ ፡		8403240213 8403270059* 8403270279* 8403270282* 8403200114*	40~8585 FBIA 50~369 50~369 50~413
	8403120007 8403120199 8403130203 8403130227 8403130318	50-508 50-509 PR 50-397 50-397	D A V P	Hestinghouse Operating Plants Owners	B403300119* B403300248 B403070104*	50-413 Waste Mgt Foia
	#05120330*	50-397	P	Group	8403070108* 8403260024	FDIA TOPREP
	8403130337 8403130385 8403130480 8403200105	50-397 50-508 50-397 50-397	8 F P B	Hhicher, J M	8403160002 8403160002 8403160019 8403160019	50-454 50-454 50-454 50-454
	8403200234 8403200239 8403200241* 8403200261 8403210170	50-397 50-397 50-397 50-397 50-50B	P 8 P P G	White & Williams White Plains NY Wien Laboratories, Inc. Will County, IL	8403260351 8403080388 8403270306* 8403130247	50-454 FOIA CONTRACT PRM 50-456
	8403210172 8403210189	50-50B 50-50B	0 0	Williams & Associates	8403080227 8403070046*	CONTRACT
	8403220061 8403260006 8403260025	50-397 50-397 50-397	P F \$	Wisconsin Clinic Cancer Center, Madis	B403290296 B403130327	PR PR
	8403260165 8403260221 8403260274	50-397 50-509 50-397	F A P	w. Wisconsin Alectric Power Co	8403040358 8403040358 8403070255	50-246 50-246
	8403240272 8403270118 8403270141 8403270207 8403270220	50-397 50-397 50-397 50-397	r G F J E		8403070255 8403070257* 8403070257* 8403120066 8403120066	50-266 50-266 50-266 50-266 50-266
	8403280007 8403280007	50-397 50-397 50-397 PR	8		8403120157 8403120157 8403130005 8403140137	50-266 50-266 50-266
Washington State Univ., Pullman, WA Washington Univ., St Louis, MO Washington, State of	8403300056 8403200238 8403260356# 8403120174	50~397 50~508 CONTRAC 50~508	D		8403140139 8403160054 8403160080 8403210029	30-266 30-266 PR
Washington, Univ. of Seattle, WA	8403150151 8403160228 8403230188 8403230250 8403010462*	50-508 50-397 WASTE MI CONTRACT	OT .		8403210077 8403220099* 8403220162 8403220162	50-266 50-266 50-266
Hater, Weste & Land, Inc. Hatkins, L.B.	8403230160* 8403230197 8403140009 8403140012*	CONTRACT NURED 50~458 50~458			8403220167* 8403220167* 8403230068 8403260072	50-266 50-266 50-301 50-266
Haynesboro, OA	8403230279	50~424	å		B40327007B	30-266

AUTHOR AFFILIATION	ACCESBION NUMBER	SUBJECT CATEGORY
Wistonsin Public Service Corp	8403270125 8403270237 8403270247* 8402170104 8402170107*	50-266 P 50-266 P 50-305 P 50-305 P
	8403020295 8403050408 8403070169 8403130147 8403130188	50-305 P 50-305 R 50-305 R 50-305 R 50-305 P
	8403140298 8403140327 8403140331* 8403200014 8403200154	50-305 P 50-305 P 50-305 P 50-305 G 50-305 P
	8403210009 8403270030 8403270032* 8403270038* 8403280048	PR 50-305 P 50-305 P 50-305 P 50-305 P
Hisconsin, Univ of, Green Bay, WI Hisconsin, Univ of, Madison, WI	8403220280* 8403070141* 8403200020 8403280314 8403280326	CONTRACT CONTRACT 50-156 H ACRS ACRS
Wisconsin, Univ of, Milwaukee, WI Worcester Foundation for Experimental Biology	8403290238 8403090186	PRM PRM
Myoming Fuel Co Myoming, State of	8403150319 8403150210 8403150253	40~8829 40~299 40~8786
Wyoming, Univ of, Laramie, WY Yakima Indian Nation Yale Univ . New Haven, CT Yankee Atomic Electric Co	8403150240 8403270301 8403230050 8403170275 8403020072	40-9786 PRM WASTE MGT PR 50-29 R
	8403020292 8403080007 8403080009* 8403090175 8403120123	50-27 R 50-27 P 50-27 P 50-27 S 50-27 P
	8403120181 8403130287 8403150100 8403160256 8403160256	50-27 R 50-27 P 50-443 S 50-443 F 50-443 F
	8403200215 8403200284 8403200288* 8403200270* 8403210048	50-27 B 50-27 P 50-27 P 50-27 P 50-27 R
	8403210077 8403210077 8403210142 8403220005 8403220150	50-443 A 50-443 A 50-443 A 50-443 S 50-443 S
	8403220164 8403230061 8403270003 8403270007 8403270121	50-443 8 50-443 A 50-27 P 50-27 P 50-443 A
Zetec, Inc. Zytor, Inc.	8403870216 8403300083 8403300192 8403190409* 8402140048*	50-27 R 50-27 R 50-27 P 50-317 Q 50-528 Q

REPORT NUMBER INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

REPORT	ACCESSION	SUBJECT	OTHER REPORT
NUMBER	NUMBER	CATEGORY	NUMBER
02-0140-1102 R02	8403010303*	50-388 E	IEB-BO-11
02-0370-1132 R00	8403200062*	50-219 G	
02-0370-1139 R00	8403200067*	50-219 G	
04-5079-204 R00	8403060414*	50-302 G	
108025 RA	8403130128*	50-440 A	
11600,02	8403020270*	50-322 E	
13737-2-007-102 R05	8403130439*	50-320 P	
323258L-001	8403060304*	50-324 P	
503-8500000-76	8403080268*	50-298 F	
548-8854-2 R8	8403130138*	50-440 A	
8403050227	8403050227	RE8	NRC-60-10-01-05
8403050230	8403050230	50-280 P	
8403050242	8403050242	RE8	
8403120255	8403120255	RE8	
8403120237	8403120257	RE8	
8403270329 8403300120 AE0D/E324 AE0D/T308 AL9-137	8403270329 8403300120 8310060077* 8305190497* 8403090329*	REB REB MISC TOPREP TOPREP	E09-BAAM-6499 LBL-16152
BAH-1549 R02	8403170246*	TOPREP	
CC-74-133 R00	8403130106*	50-440 A	
CEN-203-NP R01 S01	8403130273*	TOPREP	
CEN-248(B) R02	8403050103*	50-318 P	
CEN-259	8403020335*	50-382 A	
CEN-26B	8403140140*	TOPREP	
CN8I-WF-C-01-NP	8401120550*	WASTE MOT	
CFL-13-103 ROO	8403070318*	50-325 G	
DC-1362	8403050143*	50-204 S	
EGG-EA-6413	8403070395*	50-315 P	
EQG-EA-4542	8403250335	50-416 P	TAC 54185
EGG-HG-6274 RO3	8402280725*	50-267 P	
EQG-NTAP-4309	8403280117	50-368 S	
EQG-BAAM-6381	8403280113	50-313 S	
EGG-BAAM-6415	8403280124	50-368 S	
ERCO-693 ES-1000 RB FAAA-84-2-14 GAI 2499 GAI 2512	8403170282* 8403130118* 8403010444* 8403270187* 8403270188*	50-312 G 50-440 A 50-322 S 50-244 P	43706-2 FME-R-6/7396
QJ-04(83)	8403220225	WASTE MOT	
MPR-794	8403220004*	50-219 P	
NEC-10	8403070317*	TOPREP	
NEC-6	8403070315*	TOPREP	
NEG-8	8403070318*	TOPREP	
NEC-9 NEDO-24146A ERR 09 NEDO-30242 NEDO-30242 501 NF-1583.04-1 A01	8403070322* 8403270136* 8403270022* 8403270024* 8403210080*	TOPREP	79NED273
NUREG-0020 VOB NO1	8403150058	NUREG	
NUREG-0072 RO1	8403020460	NUREG	
NUREG-0304 VOB NO4	8403070401	NUREG	
NUREG-0430 VO4 NO1	8403220189	NUREG	
NUREG-0540 VO5 N12	8403260289	NUREG	

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEOUR	Y	OTHER REPORT NUMBER
NUREG-0606 V06 NO1	8403230212	NUREG		
NURE9-0675 817	8403070104	50-275	E	
NUREG-0675 522	8403300300	50-275	E	
NUREG-074B V04 N01	8403270269	NUREG	_	
NUREG-0750 V18 NO4	8403230183	NUREG		
NURE0-0885 103	8403150211	NUREG		
NUREG-0936 VO2 NO4	8403020165	NUREO		
NURE9-0978 FC	8403220326	NUREO		
NUREQ-1015	8403230190	NUREG		
NUREG-1022 SO1	8403070121	NUREG		
	#4ADATABAE	MUREO		
NUREG-1037	8403070385	NUREQ 70-27		
NUREG-1049	8403270267	50-528	D	
NUREO-75/022	8403290344*	NUREG	D	
NUREC/DR-0025 V10 N2	0403260280	NUREO		
NUREG/BR-0051 V05 N5	8403260056	NUMEU		
NUREG/9R-0059 R01 ER	8403070397	NUREG		ABLE MINTO AAA
NUREO/CR-2000 V03 N1	8403070392	NUREO	-	ORNL/NSIC-200
NUREO/CR-2050	8403050029	50-284	۳	UCRL-53024
NUREG/CR-2815 DRFT	8403010041#	FOIA		BNL-NUREG-51559
NUREG/CR-2876 VO1	8403300241	NUREG		ANL-82-25 VO1
NUREG/CR-2896 V02	8403300285	NUREG		ANL-82-25 VOR
NURE0/CR~3067	B403060533	NUREG		ENICO-1125
NUREG/CR-3091 V03	8403070115	NUREO		BNL-NUREG-51430
NUREG/CR-3104	8403230177	NUREO		PNL-4583
NURE9/CR-3145 VO2	8403230131	NUREG		
NUREQ/CR-3153	8403260286	NUREO		ORNL/TM-8653
NURE0/CR-3224	8403230216	50~537	A	LA-9714-HS
NUREQ/CR-3275	8403300325	NUREG		DRNL/TM-8755
NUREQ/CR-3309	8403300342	NUREG		SANDB3-7095
NUREO/CR-3334 VO3	8403300317	NUREG		ORNL/TM-8767/V3
NUREG/CR-3390	8403230197	NUREO		WWL/TM-1791-1
NUREGICE-3422 VD2	B403150219	NUREG		DRNL/TH-8849/VR
NUREO/CR-3427 VO3	8403300294	NUREG		
NUREQ/CR-3449	8403070118	NUREO		
NUREG/CR-3501	B403200358	NUREG		GRNL/TM-8694
NUREG/CR-3508	8403170444	NUREG		ORNL/SUB-7576/3
NUREO/CR-3523	8403300306	NUREG		ORNL/TM-8950
	8403230133	50-313	Р	BNL-NUREG-51721
NUREG/CR-3529 NUREG/CR-3549	8403300318	NUREG	•	ORNL/TM-8909
NUREO/CR-3560	8403230173	NUREG		PNL-4904
NUMBER (AR., SETS)	B403190449	NUREG		PNL~4923
NUREG/CR-3573	B403170447	NUREG		PNL-4813
NUREO/CR-3601	B403070109 B403150214	50-30	٨	
NUREG/CR-3605	8403070093	NUREG	r	
NUREG/CR-3607 NUREG/CR-3621	8403230200	NUREG		PNL-4832
NUREO/CR-3622	8403230057	NUREG NUREG		ORNL/TM-8841 PNL-4906
NUREO/CR-3645	8403190055	NUREG		ANL-83-20
NUREG/CR-3649	8403070114	NUREG		EPRI NP-3494
NUREO/CR-3661 NUREO/CR-3666	9403230208 9403170437	NUREO		
	-	bu (nee		DN -4004
NURE0/CR-3674	8403230207	NUREQ	_	PNL-4986
NUS-4507	8403260253*	50~352 50~493	Ę.	
01-0780-1269 RO1	8403200269*	50-482 50-352	Ä	
P-281/2	8401240211* 8403140086*	50-332		FAAA-84-3-1
PAO 7396				

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER
PNL-4515 PGP-124 GTR 82-003 9TR-82-010 R-1208671-001	8403140170* 8403080199* 8403290308* 8403290305* 8403010097*	PR 50-275 Q 50-354 A 50-354 A FOIA	UC-41 NRC/IE-82/83
R-8212 R-8215 R-8216 R-8217 R-900-74-2	8403050323* 8403050317* 8403050322* 8403050318* 8403080407*	WASTE MOT WASTE MOT WASTE MOT WASTE MOT 50-528 A	UMTRA-DDE/ALD- DDE/UMT/0232 DDE/UMT/0234 DDE/UMT/0234
RERR-151 RHO-8W-SA-286 P RIL-139 SAI-1-148-08-781 SAI-186-028-20	8403070261# 8403260347# 8403150175 8403050032# 8209030161#	50-272 R WASTE MOT RES 70-687 50-280 Q	HERR-15I
SANDBR-1457 SANDBR-7032 VO1 SANDBR-7032 VOR SANDBR-7032 VOR BANDBR-7219 VO1	8403080027# 8403080008# 8403080017# 8403080025# 8403080010#	FOIA FOIA FOIA FOIA FOIA	SAI01381-307LJ SAI01381-308LJ SAI01381-275LJ SAI01381-410LJ
EAND82-7219 VO2 BAND82-7219 VO3 SAND82-7220 SECY-78-569 BECY-82-037	8403080012# 8403080017# 8403080006# 8403050031# 8203050065#	FOIA FOIA FOIA FOIA FOIA	SAI01381-411LJ SAI01381-412LJ SAI01580-379LJ
SECY-82-037A SECY-82-340 SECY-83-034 SECY-83-445 SECY-83-445	8204160230# 8207200364# 8403010451 8403070017# 8403020074#	FOIA FOIA 50-206 S FOIA FOIA	
SECY-84-067 SECY-84-067A SECY-84-095 SMA 13701 05R003 VIO SMA 20601 01-R1-0	8402220050 8403080434 8403080041 8403140026* 8403200152*	BECY BECY BECY 50-329 A 50-423 A	
SS-152 EWECO 7703 TER-C5506-425 UCID-19130 UMTRA-DDE/AL-0077-F	8403060366* 8403160076* 8403150045* 8403050038* 8403060521*	50-302 P 50-412 A 50-237 P 50-286 P WASTE MOT	EMTR-801 TAC 49361
UTEC ME 84-0205 V-PAK-481 MCAP-10433 WCAP-10474 MCAP-10488 (NP)	8403200293* 8403070014* 8403060326* 8403070259* 8403170404*	50-72 F 50-528 E 50-213 P 50-348 P 50-413 A	
WCAP-8587 ROESE-47AD WCAP-8587 ROHE-108 D WCAP-8587 R4E8E-13D XN-NF-82-32 (NP) R02 XN-NF-82-70 (NP) S01	8403130375* 8403130389* 8403130358* 8403080223* 8403150104*	50-482 A 50-482 A 50-482 A 50-316 P 50-316 P	EGDP-ESE-47A EGDP-HE-10B EGDP-ESE-13 XN-NF-B2-90(NP)
XN-NF-83-85 XN-NF-83-85 RO1 SO1 XN-NF-83-85 SO1 XN-NF-84-14 XN-NF-84-18	8403080220* 8403200101* 8403080210* 8403230102* 8403230106*	50-314 P 50-316 P 50-316 P 50-255 P 50-255 P	
KN-NF-84-21 (NP) KN-NF-84-24 KN-NF-84-24 KN-NF-84-24	8403080216# 8403230111# 8403080009#	50-316 P 50-255 P 50-29 P	

Items listed as enclosures are those indicated by an asterisk following the accession number in the indexes. The second column gives the accession number of the principal document under which the enclosure is listed. Knowing the accession number of the principal document, the date issued, and the category enables locating the title listing of the enclosure.

ACCESSION NUMBER

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

	PRINCIPAL.	DATE	SUBJEC	:T		PRINCI
ENCLOBURE	DOCUMENT	ISSUED	CATEO		ENCLOSURE	DOCUM
7904030132	9810805048	04 (02 (0)	FOIA		0.00040540	
7904030135	8403080126	84/03/01			8103040046	840305
7906140545		B4/03/01	FOIA	_	8103040052	840309
7906140548	8403010123	83/12/20	50-312	7	8103050718	840305
	8403010123	83/15/50	50-312	P	6103250553	840301
7906190142	8403050288	B4/02/17	50-440	F	8103250630	840301
7906250470	8403080207	84/01/23	FDIA		B104210125	840223
7908010102	8403050288	B4/02/17	50-509	A	8104220327	840300
7908010232	8403050288	84/02/17	50-397	Ä	8104220881	840305
7910260122	B403010123	83/12/20	50-312	P	8104300020	840306
7911120317	E403010123	83/12/20	50-312	P	8105010554	B40308
7911120366	74575 / B / D =			_		
	8403010123	83/12/20	20-315	P	8105140106	B40308
7911120370	8403010123	83/12/20	50-312	P	8105180434	840306
7911120403	B403010123	63/12/20	FOIA		\$105210109	840308
7911120413	8403010123	83/12/20	50-312	P	B10A170138	840308
7912050523	8403050020	83/12/07	50-284		8106820066	840306
8001140316	8403080179	84/02/13	50-460	Α	8107130581	840300
8001270311	8403010123	63/12/20	50-312	þ	8107140185	840306
8003240159	8403010050	84/01/17	50-508		8107140192	B40306
6003240202	B403080179	84/02/13	50-508	Ą		
8003240207	8403080179			Ą	8107140213	840301
GUUDRAURUT	6403080179	84/02/13	50-508	Α	8107140215	840301
8003240207	8403050298	84/02/17	50-508	Α	8107200104	840328
6003240219	8403080179	84/02/13	50-508	Α	8107270274	640308
8003240222	8403080179	B4/02/13	50-508	Α	8107280171	840309
B003250477	8403080179	84/02/13	50-397	Ď	8108110038	840308
8003270142	8403080179	B4/02/13	50-397	D	8108270490	840308
B004010752	8403010050	84/01/17	30-50B	A	8109180036	840301
6004010759	8403010030	E4/01/17	50-508		8110080512	840308
B005010203	B4030B0016			Α		
8005130793	84030800179	84/01/11	FOIA 50-387	E	8110170026	840308
8005150477	B403080179	84/02/13		=	8110190051	840305
50051506//	5403090179	84/02/13	FOIA		8110210314	840305
B005150483	8403080179	84/02/13	FOIA		8111020578	B40305
B005280995	8403080016	84/01/11	FOIA		8111060697	840308
8005280978	8403080016	84/01/11	FOIA		8111120935	840308
8007070737	8403080179	84/02/13	50-344	Р	6111130007	840308
B009110203	8403080179	84/02/13	50-397	U	8111200217	840309
8009250342	8403010123	93/12/20	50-312	P	n. 1000001	840301
B007250345	B403010123	63/12/20	50-312	P	81 12020204 81 12210135	840301
8010090260	B4030B0179					
B010230503	B4030B0016	84/02/13	50-460	Α	8112300305	B4030B
		84/01/11	FOIA	_	9201170277	840308
6011070522	B403010117	84/01/25	50~317	P	6201220170	840305
8011120101	8403050288	84/02/17	FOIA		8201300236	840305
8012190551	8403080179	B4/02/13	50-397	U	9202120295	840301
8101060767	8403080179	B4/02/13	50~397	Ā	8202180456	840308
B101130363	8403080179	84/02/13	50-50B	Ü	9202220056	840302
8101290708	8403080016	B4/01/11	FOIA	-	8202260171	B4030B
8101300020	8403080126	B4/03/01	FOIA		-	****
B101300025					9203020139	#4030B
8102200029	8403080124	B4/03/01	FOIA		9203050045	B40309
	8403080179	84/02/13	50-466	Α	9203100419	B40308
8102240058	8403080014	B4/01/11	FOIA		8203100570	840308
6102240066	8403080014	84/01/11	FOIA		9203120197	B40301

	DESTAIR TO A L	DATE	CUM ICA	-
	PRINCIPAL	DATE	SUBJEC.	
ENCLOSURE	DOCUMENT	IASUED	CATEGO	RY
~				
8103040048	8403050020	83/12/07	50-286	P
		67/15/0/		
6103040052	8403080179	84/02/13	50-397	Æ
810305071B	8403050020	83/12/07	FOIA	
6103250553	8403010117	84/01/25	FOIA	
8103250430	8403010117	84/01/25	FOIA	
				_
B104210125	8402230207	83/12/02	50~400	9
8104220329	8403000179	84/02/13	50~460	A
8104220881	8403050020	83/12/07	50-286	p
8104300020	8403080179	84/02/13	50~397	A
0105010554	B403080179	84/02/13	50-460	Α
8105140106	8403080179	84/02/13	50~460	Α
8105180434	8403080179	84/02/13	50-440	Α
8105210109			50-460	
	8403080179	84/02/13		A
B106170138	8403090179	84/02/13	FOIA	
8106220066	8403090179	84/02/13	50~50B	a
DODDARDOLD	0404040177	G-7/OE/13	40-306	•
8107130581	8403080179	84/02/13	50-50B	G
8107140185	8403080177	84/02/13	50-508	Q.
8107140192	8403080179	84/02/13	50-50B	G.
8107140213	8403010117	84/01/25	FDIA	
8107160215		84/01/25	FOIA	
910,150812	8403010117	84/01/83	LOTH	
8107200104	8403280080	84/01/17	FOIA	
8107270274	8403080179	84/02/13	50-508	Α
8107280171	0403090179	84/02/13	50~460	Α
8108110038	8403080179	B4/02/13	50~460	Α
8108270490	8403080370	B4/02/13	50-528	D
8109180036	8403010117	84/01/25	FOIA	
				_
8110080612	8403080179	B4/02/13	50-460	Α
8110170026	8403080179	84/02/13	50~508	F
8110190051	8403050288	B4/02/17	50-397	Α
8110210314	8403050288	84/02/17	50~460	Α
8111020578	B403050288	84/02/17	50-50B	Α
B:11060697	8403080179	84/02/13	50-460	Α
0111120935	8403080179	B4/02/13	50-460	Е
0111130007	8403080179	B4/02/13	50-460	Α
8111200219	8403080179	B4/02/13	50-397	Α
6112020204	8403010050	B4/01/17	50-412	Α
8112210135	8403010050	84/01/17	50-508	A
8112300305	8403080179	84/02/13	50~460	A
9201170297	8403080179	84/02/13	50-397	F
8201220170	8403050020	B3/12/07	FOIA	
B201300236	8403050288	B4/02/17	50-397	Α
				••
8202120275	8403010117	B4/01/25	FOIA	
8202180456	8403080179	84/02/13	50~460	F
8202220056	8403020014	83/12/16	FOIA	
9202260171	8403080179	84/02/13	50-460	C
9203020139	8403080179	84/02/13	50-460	F
				•
9203050045	B403090006	84/02/22	FOIA	
9203100417	B403080179	84/02/13	50-460	6
8203100570	B403080179	84/02/13	50-397	C
8203120177				-
RMODIKO141	B403010117	84/01/25	FOIA	

ACCESSION NUMBER

ACCE9810	N NUMBER					N NUMBER			
ENCLOSURE	PRINCIPAL DDCUMENT	DATE ISSUED	SUBJEC CATEOD		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT	
8203150028 8203180004 8203180118 8204070097 8204160230	8403080179 8403080179 8403080179 8403080179 8403090006	84/02/13 84/02/13 84/02/13 84/02/13 84/02/22	50-460 50-460 50-508 50-460 FOIA	C A C	8309210098 8309210116 830921034 8309220297 8309220302	8403050064 8403050064 8403080367 8403050020 8403050064	84/02/07 84/02/07 84/02/28 83/12/07 84/02/07	50-400 50-400 50-322 FDIA 50-400	E
B204290657 B205070088 B205120076 B205270420 B2063000B2	8403080179 8403080179 8403050064 8403050064 8403080179	84/02/13 84/02/13 84/02/07 84/02/07 84/02/13	50-508 50-460 50-400 50-400 50-508	A E E A	8309260018 8309260421 8309260510 8309260510 8309270412	8403050064 8403050064 8403050064 8309260515 8403050064	84/02/07 84/02/07 84/02/07 83/09/08 84/02/07	50-400 50-400 50-400 50-311 50-400	E 85
8207140072 8208070297 8208120240 8208120248 8208240003	8403050064 8403050020 8403080179 8403080179 8403050223	84/02/07 83/12/07 84/02/13 84/02/13 84/02/07	50-400 50-286 50-397 50-397 FOIA	E 0 F F	8309290474 8310040077 8310040317 8310130378 8310170095	8403050064 8310060076 8402210338 8403050064 8403050064	84/02/07 83/09/21 84/02/10 84/02/07	50-400 MISC 50-285 50-400 50-400	E G E E
820 9030 141 820 9200364 820 9280 145 821 0220012 821 0220014	8403140177 8403060467 8403080177 8403020014 8403020014	84/02/28 84/02/17 84/02/13 83/12/16 83/12/16	50-280 F01A 50-460 F01A F01A	q q	8310170712 8310190067 8310200696 8310280188 8310310445	8403050020 8403050064 8403050064 8310280186 8403050064	83/12/07 84/02/07 84/02/07 83/09/08 84/02/07	50-286 50-400 50-400 50-298 50-400	PEES
B210220084 B211090008 B211090018 B211090035 B211110461	8403020014 8403050064 8403010050 8403050064 8403050064	B3/12/16 B4/02/07 B4/01/17 B4/02/07 B4/02/07	FDIA 50-400 50-556 50-400 50-400	E E E	8310310471 8310310475 8311040253 8311100047 8311110263	8403010178 8403010178 8311020247 8403050064 8403050064	83/12/14 83/12/14 83/09/08 84/02/07 84/02/07	50~329 50~329 50~318 50~400 50~400	AASEE
B211160112 B211170247 B211170102 B211170103 B211300017	8403050064 8403050064 8403020014 8403020014 8403050064	84/02/07 84/02/07 83/12/16 83/12/16 84/02/07	50-400 50-400 FOIA FOIA 50-400	E	8311140004 8311140170 8311140248 8311140250 8311110481	8403050064 8307260036 8307260036 8307260036 8403010117	84/02/07 83/07/15 83/07/15 83/07/15 84/01/25	50-400 ACRS ACRS ACRS 50-312	E
8212070382 8212080692 8212080693 8212100130 8212130052	8403080177 8403020014 8403020014 8403020014 8403020014	84/02/13 83/12/16 83/12/16 83/12/16 83/12/16	50-460 50-267 50-267 FOIA 50-267	A P P	8311160283 8311160283 8311230247 8311270301 8311270332	8403050064 8403050064 8403010100 8403050064 8403050064	84/02/07 84/02/07 83/12/22 64/02/07 84/02/07	50-400 50-400 FOIA 50-400 50-400	E
8212140059 8212140143 8212140220 8212300403 8301040211	8403020014 8403050064 8403050064 8403050064 8403050064	83/12/16 84/02/07 84/02/07 84/02/07	50-267 50-400 50-400 50-400 50-400	P 医 E E	8312010004 8312020063 8312050628 8312070022 8312070229	8403010198 8403050064 8403010198 8403010198 8403010198	83/12/14 84/02/07 83/12/14 83/12/14 83/12/14	50-329 50-400 50-329 50-329 50-329	A A A A
B301050420 B301140173 B301140474 B301140486 B301140490	8403010024 8403080375 8403050064 8403020014 8403020014	84/01/18 94/02/17 84/02/07 83/12/14 83/12/14	FOIA FOIA 50-400 50-267 50-267	E P	8312080134 8312080188 8312120002 831212004 8312120445	8403010198 8403050064 8403050064 8307260036 8403050064	83/12/14 84/02/07 84/02/07 83/07/15 84/02/07	50-329 50-400 50-400 ACRB 50-400	A E E
8301140494 8301260036 8301280380 8302250083 8303080290	8403020014 8403050064 8403010262 8403010050 8403050020	83/12/14 84/02/07 83/12/20 84/01/17 83/12/07	50-267 50-400 50-382 50-513 50-286	P A A P	8312140347 8312140351 8312140459 8312150232 8312150241	8402090030 8402090030 8403030064 8403280163 8307260036	84/03/02 84/03/02 84/02/07 84/02/17 83/17/15	50-275 50-275 50-400 FOIA ACRS	E
8303100476 8303170017 8304040552 8304040577 8304070113	8403080179 8303170014 8403010050 8403080179 8403080179	84/02/13 83/03/02 84/01/17 84/02/13 84/02/13	50-397 50-315 50-397 50-397 50-397	A G A A	8312190358 8312202561 8312202261 831220278 831228099	8307260036 8403080347 8403080347 8403050064 8402090030	83/07/15 84/03/02 84/03/02 84/02/07 84/03/02	ACRB 50-275 50-336 50-400 50-275	P E E
8304260013 8305040013 8305040155 8305060342 8305090506	8403020014 8403010024 8305040149 8305060337 8403010030	93/12/16 94/01/19 93/04/19 93/04/25 84/01/17	50-267 FOIA 50-293 50-324 50-509	P 8 8 6	8312280102 8312280107 8401040010 8401120180 8401120428	8402070030 8402070030 8402070030 8401120171 8401120425	84/03/02 84/03/02 84/03/02 83/09/16 83/12/30	50-275 50-275 50-275 40-3453 50-445	E
8305110054 8305190497 8305230119 8305230546 8305270056	8403010014 8305190472 8403050020 8403230539 8305270051	84/01/03 83/04/20 83/12/07 84/03/28 83/04/25	50~289 TOPREP 50~286 50~327 50~338	P 9 8	8401120433 8401120437 8401120530 8401120597 8401120600	8401 120425 8401 120425 8401 120525 8401 120594 8401 120594	83/12/30 83/12/30 83/11/30 83/12/30 83/12/30	50-445 50-445 Waste Mg 50-346 50-348	A A P P
8306220210 8307180403 8307180414 8307290506 8308040003	8403070215 8403080347 8403080347 8403050020 8403050020	84/01/23 84/03/02 84/03/02 83/12/07 83/12/07	50-440 50-344 50-344 50-286 50-286	A P P P	8401230660 8401240211 8401240315 8401240340 8401250456	8401230630 8401240207 8401240304 8401240337 8402270004	83/11/01 84/01/18 84/01/10 84/01/19 84/02/21	50-327 50-352 70-27 70-1100 50-247	8 A P
830804057B 8308040070 8308100483 8308150440 8308170191	8307250036 8403080367 8403010050 8403070101 8403010013	83/07/15 84/02/28 84/01/17 64/02/14 84/01/03	ACRS FOIA 50-397 FOIA 50-447	A	8401250468 8401250476 8401250510 8401250167 8402010185	8402290004 8402290004 8402290004 8401260161 8402010178	84/02/21 84/02/21 84/02/21 84/01/19 84/01/25	50-267 50-267 50-267 50-264 GA999	P P P F
8307040370 8307120554 8307150400 8307150401 8307200478	8403050064 8403060091 8403010117 8403010117 8403050064	84/02/07 84/01/23 84/01/25 84/01/25 84/02/07	50-400 FDIA FDIA FDIA 50-400	E	8402010508 840202093 8402030344 840203055 8402040421	8402070017 8403120305 8402030338 8403060527 8403060417	84/02/27 84/02/27 84/01/27 84/02/17 84/01/30	50-275 50-293 50-206 MISC 50-302	P F P

AGCE881 ON	NUMBER				ACCESS I DN				
ENCLOBURE	PRINCIPAL DOCUMENT	DATE 198UED	SUBJECT CATEGOR		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR	Υ
8402070057 8402090183 8402090184 8402090384 8402130042	8402070054 8402090003 8402090003 8402090380 8402090380	84/01/31 83/10/31 83/10/31 84/02/06 84/02/23	50-400 50-352 50-443 50-390 MISC	 0 A A F	8403010077 8403010078 8403010102 8403010104 8403010108	8403010092 8403010091 8403010094 8403010100 8403010100	B4/02/07 B4/02/14 B4/01/03 B3/12/22 B3/12/22	FOIA CONTRACT FOIA FOIA	
8402130353 8402130360 8402130390 8402130392 8402130395	8402130373 8402130373 8402130373 8402130373 8402130373	84/01/31 84/01/31 84/01/31 84/01/31 84/01/31	50~358 50~358 50~358 50~359 50~359	ບ ບ ບ ບ	8403010114 8403010124 8403010127 8403010128 8403010129	8403010113 8403010110 8403010117 8403010110 6403010117	84/02/10 84/02/22 84/01/23 84/02/22 84/01/23	50-508 50-321 FOIA 50-321 50-348	T P P
8402130399 8402130404 8402140022 8402140026 8402140028	8402130393 8402130400 8402140018 8402140018	84/01/31 84/02/08 83/12/20 83/12/20 83/12/20	50-358 50-348 50-528 50-528 50-528	U G G G	8403010131 8403010132 8403010137 8403010138 8403010139	8403010117 8403010125 8403010117 8403010117 8403010125	84/01/25 64/01/11 84/01/25 84/01/25 84/01/11	FOIA 50-498 50-348 FOIA 50-498	GI P T
8402140031 8402140032 8402140036 8402140037 8402140038	8402140018 8402140018 8402140018 8402140018 8402140018	83/12/20 83/12/20 83/12/20 83/12/20 83/12/20	50-528 50-528 50-528 50-528 50-528	G G G G	8403010141 8403010143 8403010144 8403010147 8403010150	8403010117 8403010136 8403010117 8403010136 8403010123	84/01/25 84/02/21 84/01/25 84/02/21 83/12/20	50-348 50-414 50-348 50-414 50-312	P P P P
8402140043 8402140048 8402140052 8402140193 8402140327	8402140018 8402140018 8402140018 8402140189 8402140325	83/12/20 83/12/20 83/12/20 84/01/10 84/02/08	50-528 50-528 50-528 50-261 40-8102	G G G	8403010151 8403010152 8403010153 8403010155 8403010156	8403010117 8403010117 8403010149 8403010134 8403010117	84/01/25 84/01/25 84/01/24 84/02/16 84/01/25	FDIA 50-348 71-511 50-267 50-348	P S P
8402140536 8402150216 8402150226 8402160020 8402170107	8402140527 8402150211 8402150211 8403070103 8402170104	84/01/17 83/12/28 83/12/28 84/02/23 84/02/14	50-331 GA777 GA777 MISC 50-305	P	8403010159 8403010161 8403010163 8403010164 8403010166	8403010117 8403010117 8403010117 8403010117 8403010162	84/01/25 84/01/25 84/01/25 84/01/25 84/01/24	FDIA FOIA 50-348 FOIA 71-6206	р
8402170166 8402170176 8402210343 8402210348 8402210357	8402170156 8402170156 8402210338 8402210338 8402210338	84/02/14 84/02/14 84/02/10 84/02/10 84/02/10	50-265 50-265 50-265 50-265 50-265	P G G G	B403010147 B403010171 B403010175 B403010177 B403010178	8403010134 8403010140 8403010117 8403010140 8403010117	84/02/14 84/02/22 84/01/25 84/02/22 84/01/25	50-267 50-250 50-344 50-250 FOIA	8 P P
B402220303 B402230226 B402230237 B402230239 B402230242	8402220288 8402230207 8402230207 8402230207 8402230207	84/02/14 83/12/02 83/12/02 83/12/02 83/12/02	50-289 50-400 50-400 50-400 FOIA	U A G A	8403010180 8403010181 8403010184 8403010185 8403010191	8403010173 8403010117 8403010117 8403010117 8403010117	B4/02/23 B4/01/25 B4/01/25 B4/01/25 B4/01/25	50-250 FOIA FOIA FOIA FOIA	F
6402230246 6402230249 6402230251 6402240367 6402270314	8402230207 8402230207 8402230207 8403070103 8402270263	83/12/02 83/12/02 83/12/02 84/02/23 84/01/30	50~400 50~400 50~400 MISC 50~321	A A A	B403010173 B403010174 B403010176 B403010177 B403010201	8403010117 8403010186 8403010117 8403010186 8403010117	84/01/25 84/02/21 84/01/25 84/02/21 84/01/25	FD1A 50-247 F01A 50-247 F01A	P P
8402280725 8402290440 8403010004 8403010015 8403010020	8403120081 8403110178 8403010003 8307260036 8403010014	84/03/06 84/02/27 84/01/20 83/07/15 84/01/03	50-267 50-508 CONTRACT ACR8 50-287	P D	8403010204 8403010205 8403010206 8403010211 8403010214	8403010178 8403010117 8403010117 8403010198 8403010117	83/12/14 84/01/25 84/01/25 83/12/14 84/01/25	50-329 FOIA FOIA 50-329 FOIA	A
8403010022 8403010023 8403010027 8403010029 8403010030	8307260036 8403010014 8403010017 8307260036 8403010014	83/07/15 84/01/03 84/02/22 83/07/15 84/01/03	ACRB 50-287 CONTRACT ACRB 50-287	P	8403010217 8403010222 8403010223 8403010227 8403010227	8403010198 8403010117 8403010198 8403010198 8403010221	83/12/14 84/01/25 83/12/14 83/12/14 84/02/27	50-329 FOIA 50-329 50-329 50-463	A A O
8403010032 8403010033 8403010035 8403010037 8403010038	8403010014 8307240034 8403010014 8307240034 8403010024	84/01/04 83/07/15 84/01/03 83/07/15 84/01/18	50-334 ACRS 50-289 ACRS FOIA	8 P	8403010231 8403010233 8403010239 8403010245 8403010252	8403010179 8403010117 8403010117 8403010176 8403010117	83/12/14 84/01/25 84/01/25 83/12/14 84/01/25	50-329 50-312 FOIA 50-329 FOIA	A P
8403010041 8403010042 8403010043 8403010044 8403010045	8403010026 8307260036 8403010014 8403010035 8403010040	84/01/04 83/07/15 84/01/03 84/02/21 84/02/22	FOIA ACRE 50-287 CONTRACT CONTRACT	P	8403010253 8403010255 8403010257 8403010260 8403010261	8403010248 8403010248 8403010117 8403010248 8403010254	84/01/10 84/01/10 84/01/25 84/01/10 84/02/24	50-142 50-142 FOIA 50-142 50-219	G G G
8403010046 8403010049 8403010054 8403010057 8403010058	8403010024 8403010024 8403010024 8307260036 8403010024	84/01/18 84/01/18 84/01/18 83/07/15 84/01/18	FOIA FOIA FOIA ACRB FOIA		8403010265 8403010266 8403010268 8403010273 8403010274	8403010248 6403010248 8403010262 8403010178 8403010262	84/01/10 84/01/10 83/12/20 83/12/14 83/12/20	50-142 50-142 50-247 50-329 FOIA	0 6 P A
B403010060 B403010061 B403010063 B403010065 B403010067	8403010051 8403010016 8403010024 8307260036 8403010024	84/02/21 84/01/04 84/01/18 83/07/15 84/01/18	CONTRACT 50-334 FOIA ACRB FOIA	8	8403010275 8403010282 8403010283 8403010284 8403010285	8403010271 8403010198 8403010279 8403010117 8403010198	84/02/28 83/12/14 83/12/16 84/01/25 83/12/14	50-352 50-327 Foia Foia 50-327	Q A
8403010074 8403010076 8403010087 8403010087 8403010093	8403010024 8403010048 8403010070 8403010083 8403010087	84/01/18 84/01/03 84/02/10 84/02/24 84/02/21	FOIA FOIA CONTRACT 50-454 50-254	Q P	8403010287 8403010292 8403010302 8403010303 8403010313	8403010117 8403010117 8403010297 8403010294 8403010306	84/01/25 84/01/25 84/02/24 84/02/27 84/02/22	FDIA FDIA 50-389 50-259	P E P

ACCESS10	N NUMBER				ACCES910	N NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 1980ED	SUBJECT CATEGOS		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISBUED	SUBJEC	
8403010314 8403010315 8403010322 8403010325 8403010327	8403010307 8403010310 8403010310 8403010319 8403010324	84/02/16 84/02/16 84/02/16 84/02/16 84/02/24	50-352 50-277 50-277 50-424 50-293	0 0 0 X	8403020101 8403020105 8403020107 8403020110 8403020111	8403020011 8403020099 8403020011 8403020011 8403020108	84/02/09 84/02/29 84/02/09 84/02/09 84/02/27	FOIA 50-352 FOIA FOIA 50-331	Q P
8403010334 8403010348 8403010342 8403010344 8403010372	8403010327 8403010336 8403010360 8403010360 8403010369	84/02/24 84/02/26 84/02/16 84/02/16 84/02/26	REVIEW 6 50-454 70-1100 70-1100 50-255	G G	8403020113 8403020114 8403020115 8403020116 8403020117	8403020011 8403020011 8403020112 8403020011 8402230176	84/02/07 84/02/09 84/02/14 84/02/16	AIOR AIOR LITROPX AIOR EEI-OG	c F
8403010373 8403010377 8403010378 8403010382 8403010390	8403010348 8403010374 8403010374 8403010381 8403010381	84/02/20 84/02/22 84/02/22 84/02/16 84/02/16	50-255 50-312 50-312 50-322 50-322	P P Q Q	B403020119 B403020120 B403020124 B403020127 B403020132	8403020011 6403020011 6403020011 6403020011 6403020011	84/02/07 84/02/07 84/02/07 84/02/07 84/02/07	FOIA FOIA FOIA FOIA FOIA	
8403010404 8403010412 8403010414 8403010422 8403010428	8403010397 8403010410 8403010410 8403010417 8403010417	84/02/16 63/12/15 83/12/15 84/02/27 84/02/27	50-213 FOIA FOIA 50-364 50-364	G 6 9	8403020135 8403020135 8403020137 8403020142 8403020144	8403020011 8403020129 8403020011 8403020011 8403020011	84/02/09 84/02/28 84/02/09 84/02/09 84/02/09	FOIA 50-352 FOIA FOIA FOIA	т
8403010430 8403010437 8403010446 8403010456 8403010462	8403010427 8403010435 8403010207 8403010454 8403010461	84/02/02 84/02/24 84/02/27 84/02/16 84/02/10	50~423 CONTRACT 50~322 XPORTLIC CONTRACT	5	8403020146 8403020147 8403020130 8403020152 8403020153	8403020140 8403020011 8403020011 8403020148 8403020011	84/02/28 84/02/09 84/02/09 84/02/21 84/02/09	50-295 FOIA FOIA 50-445 FOIA	Q A
8403010467 8403010468 8403010473 8403010483 8403010500	8403010466 8403010465 8403010470 8403010472 8403010477	84/02/15 84/02/10 84/02/10 84/02/16 84/02/15	XPORTLIC XPORTLIC XPORTLIC 40-6920 COMMISSI	:	B403020166 8403020170 B403020172 8403020173 8403020176	8403020011 8403020011 8403020011 8403020171 8403020011	84/02/09 84/02/09 84/02/09 84/02/21 84/02/09	FOIA FOIA FOIA 50-286 FOIA	F
8403010513 8403010517 8403010532 8403010534 8403010546	8403010507 8403010512 8403010525 8403010528 8403010522	84/02/16 84/02/10 84/02/15 84/02/24 84/02/08	40-8027 XPORTLIC 50-275 CONTRACT XPORTLIC	н	8403020177 8403020179 8403020180 8403020183 8403020184	8403020011 8403020011 8403020011 8403020011	84/02/09 84/02/09 84/02/09 84/02/09 84/02/09	FOIA FOIA FOIA FOIA	
8403010550 8403020016 8403020018 8403020021 8403020023	8403010522 8403020011 8403020011 8403020014 8403020011	84/02/08 84/02/09 84/02/09 83/12/16 84/02/09	XPORTLIC FOIA FOIA FOIA FOIA	•	8403020187 8403020188 8403020191 8403020192 8403020193	8403020011 8403020182 8403020011 8403020182 8403020011	84/02/09 84/02/27 84/02/09 84/02/27 84/02/09	FOIA 50-400 FOIA 50-400 FOIA	0
8403020024 8403020025 8403020027 8403020028 8403020029	8403020015 8403020014 8403020011 8403020014 8403020014	84/02/09 83/12/16 84/02/09 83/12/16 83/12/16	XFORTLIC FOIA FOIA FOIA 50-247	P	8403020174 8403020179 8403020200 8403020201 8403020208	8403020011 8403020011 8403020011 8403020011	84/02/09 84/02/09 84/02/09 84/02/09	FOIA FOIA FOIA FOIA	
8403020032 8403020034 8403020035 8403020038 8403020041	8403020014 8403020011 8403020014 8403020011 8403020014	83/12/16 84/02/09 83/12/16 84/02/09 83/12/16	50-267 FOIA FOIA FOIA 50-267	P P	8403020210 8403020212 8403020215 8403020219 8403020220	8403020011 8403020011 8403020011 8403020011 8403020214	84/02/09 84/02/09 84/02/09 84/02/09 84/02/17	FOIA FOIA FOIA FOIA 50-388	Q.
8403020043 8403020045 8403020046 8403020048 8403020049	8403020037 8403020014 8403020014 8403020014 8403020014	84/02/17 83/12/16 83/12/16 83/12/16 83/12/16	50-10 50-247 50-247 50-247 FDIA	P P P	8403020221 8403020224 8403020227 8403020232 8403020237	8403020207 8403020011 8403020011 8403020011	84/02/21 84/02/07 84/02/07 84/02/07 84/02/09	50-973 FDIA FDIA FOIA FOIA	F
B403020051 B403020052 B403020057 B403020056 B403020057	8403020014 8403020014 8403020011 8403020054 8403020053	83/12/16 83/12/16 84/02/09 84/02/24 84/02/14	50-537 FOIA FOIA 50-280 50-280	A F R	8403020240 8403020241 8403020243 8403020246 8403020251	8403020011 8403020204 8403020011 8403020011 8403020011	84/02/09 84/01/25 84/02/09 84/02/09 84/02/09	FOIA 50-250 FOIA FOIA	a
8403020060 8403020061 8403020063 8403020066 8403020067	8403020011 8403020054 8403020053 8403020053 8403020011	84/02/09 84/02/24 84/02/14 84/02/14 84/02/09	FDIA 50-280 50-280 50-280 FDIA	P R R	8403020255 8403020255 8403020264 8403020264 8403020265	8403020011 8403020011 8403020011 8403020257 8403020011	84/02/09 84/02/09 84/02/09 84/02/29 84/02/09	FOIA FOIA FOIA 50-352 FOIA	A
8403020070 8403020071 8403020073 8403020074 8403020076	8403020011 8403020053 8403020069 8403020011 8403020053	84/02/09 84/02/14 84/02/27 84/02/09 84/02/14	FOIA 50-280 CONTRACT FOIA 50-280	R R	8403020270 8403020272 8403020273 840302028 8403020290	8403020257 8403020262 8403020257 8403020285 8403020287	84/02/27 84/02/09 84/02/27 84/02/29 84/02/21	50-352 50-293 50-352 50-250 50-322	C G K G E
8403020080 8403020080 8403020082 8403020085 8403020087	8403020049 8403020011 8403020011 8403020053 8403020011	84/02/27 84/02/09 84/02/09 84/02/14 84/02/09	CONTRACT FOIA FOIA 50-280 FOIA	R	8403020301 8403020305 8403020309 8403020309 8403020309	8403020298 8403020298 8403020282 8403020304 8403020317	84/02/17 84/02/16 84/02/17 84/02/17 84/02/29	50-443 50-54 50-443 50-277 50-369	0 0 0
8403020090 8403020091 8403020094 8403020095 8403020098	8403020053 8403020011 8403020068 8403020011 8403020072	84/02/14 84/02/07 84/02/15 84/02/09 84/02/29	50-280 FOIA FOIA FOIA 50-361	R P	8403020323 8403020324 8403020328 8403020335 8403020337	8403020318 8403020322 8403020322 8403020333 8403020332	84/02/24 84/02/27 84/02/27 84/02/29 84/02/16	50-320 50-271 50-271 50-382 WASTE MG	P S S A

ACCESSION					ACCESSION	NUMBER			
ENCLOSURE	PRINGIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY			PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR	Υ
8403020342 8403020345 8403020346 8403020347 8403020357	8403020341 8403020343 8403020343 8403020343 8403020353	84/02/17 84/02/29 84/02/29 84/02/29 84/02/21	50~247 0 50~317 0 50~317 0 50~317 0 50~286 0	840 840 840	03050333 03050335 03050340 03050341	8403050320 8403050330	84/02/28 84/02/27 84/02/24 84/02/15 94/02/15	XPORTLIC MISC 71-514 50-265 50-265	P P
8403020399 8403020408 8403020410 8403020412 8403020423	8403020315 8403020405 8403020406 8403020405 8403020420	84/02/17 84/02/15 84/02/21 84/02/15 84/02/22	50-293 0 F01A 50-416 £ F01A 71-9108	840 840 840	03050366 03050371 03050373	8403050358 8403050358 8403050370 8403050368 8403050368	84/02/28 84/02/28 84/02/29 84/02/28 84/02/28	XPORTLIC XPORTLIC 50-410 XPORTLIC XPORTLIC	A
8403020441 8403020453 8403050006 840305000B 8403050010	8403020435 8403020451 8403050005 8403050007 8403050007	84/02/22 84/02/10 84/02/22 84/02/28 84/02/28	50-440 / XPORTLIC 50-155 / 50-312 / 50-312 /	840 840 840	03060019 03060019	8403060005 8403060005 8403060008 8403060018 8403060025	84/02/28 84/02/38 84/02/36 84/01/31 84/02/07	50-261 50-261 50-266 COMMISSIO 50-206	P G ON O
8403050013 8403050015 8403050018 8403050017 8403050023	8403050012 8403050014 8403050016 8403050016 8403050020	84/03/01 84/02/24 84/03/01 84/03/01 83/12/07	50-264 F 50-247 C 50-483 F 50-483 F 50-286 F	940 940 940	03060037 03060046 03060056	8403060018 8403060018 8403060018 8403060018	84/01/31 84/01/31 84/01/31 84/02/10 84/01/31	COMMISSIO COMMISSIO COMMISSIO 50-324 COMMISSIO	NO ON P
6403050024 6403050025 6403050027 6403050028 6403050029	8403050020 8403050020 8403050020 8403050020 8403050020	83/12/07 83/12/07 83/12/07 83/12/07	50-286 F 50-286 F 50-295 G 50-295 G	840 940 940	03060071 03060074 03060080	8403060018 8403060018 8403060018 8403060077 8403060071	84/01/31 84/01/31 84/01/31 84/02/24 84/01/23	LOIV COWWIERIO COWWIERIO COWWIERIO	ON
8402050031 8403050032 8403050034 8403050035	8403050020 8403020231 8403050020 8403050020	83/12/07 84/02/16 83/12/07 83/12/07 83/12/07	FDIA 70~687 50~286 50~286 50~286	846 846 840	03040078	8403040092 8403040092 8403040092 8403040105 8403040112	84/03/01 84/03/01 84/03/01 84/03/01 84/03/01	0A999 0A999 0A999 50-322 50-335	g F
B40305003B B403050042 B403050044 B403050049 B403050074	8403050020 8403050020 8403050043 8403050047 8403050072	83/12/07 83/12/07 64/02/24 64/02/29 84/02/29	50-286 FOIA 50-10 6 50-346 6 50-254 6	840 840 840	03060117 03060121 03060124 03060126 03060127	8403060113 8403060113 8403060118 8403060115 8403060113	84/02/07 84/02/07 84/02/29 84/02/29 84/02/07	50-254 50-254 40-2041 50-244 50-254	R R P R
8403050081 8403050095 8403050100 8403050103 8403050110	8403050078 8403050091 8403050098 8403050098 8403050107	84/03/01 84/02/24 84/02/27 84/02/27 84/03/01	50-458 / 50-278 (50-318 (50-318 (50-344 (840 840 840	03060130 03060142 03060143 03060146 03060149	8403050128 8403050138 8403050131 8403050138 8403050131	84/02/29 84/02/03 84/02/29 84/02/03 84/02/29	50-375 50-275 50-275 50-275 50-275	P G G
8403050113 8403050114 8403050118 8403050122 8403050131	8403050111 8403050107 8403050107 8403050116 8403050128	84/02/29 84/03/01 84/03/01 84/03/01	50-238 50-346 50-346 60-387 50-440	946 946 946	03060192 03060154 03060161 03060162 03060163	8403060148 8403060157 8403060157 8403060151 8403060147	84/01/17 84/01/17 84/03/01 84/02/21 84/02/28	FOIA FDIA GA779 50-266 50-259	a F
8403050132 8403050134 8403050143 8403050144 8403050150	8403050127 8403050127 8403050140 8403050136 8403050136	64/02/29 64/02/14 84/03/01 84/02/24 64/02/24	50-206 50-458 50-206 40-672 40-672	840 840 940	03040172 03060173 03060176 03060177 03060184	8403050165 8403050170 8403050151 8403050170 8403050180	84/02/03 84/03/01 84/02/21 84/03/01 84/02/17	50-113 50-341 50-266 50-341 50-445	G G G G
8403050154 8403050163 8403050171 8403050172 8403050174	8403050136 8403050161 8403050168 8403050148 8403050168	84/02/24 84/02/29 84/02/27 84/01/31 84/02/27	40-672 50-352 50-373 50-206 50-373	84 84 84	030401B9 03040192 03040197 03040200 03040202	84030A0147 84030A0188 84030A0171 84030A0175 84030A0188	84/02/28 84/03/01 84/03/01 84/03/01 84/03/01	50-259 50-155 50-316 50-315 50-155	F 0 P 0
8403050178 8403050180 8403050182 8403050184 8403050204	8403050177 8403050179 8403050179 8403050179 8403050200	84/03/01 84/02/14 84/02/14 84/02/14 84/02/24	50-413 50-482 50-482 50-482 COMMI 8810	84 84 84	03040203 03040205 03040204 03040210 03040214	8403060198 8403060199 8403060147 8403060201 8403060207	84/02/27 84/02/27 84/02/28 84/03/01 84/02/17	50-313 50-313 50-257 40-8830 50-275	Q P F
8403050232 8403050235 8403050237 8403050241 8403050243	8403050223 8403050223 8403050231 8403050223 8403050238	84/02/07 84/02/07 84/02/13 84/02/07 84/02/21	FOIA 50-305 CONTRACT 50-271 50-282	84 84 84	03070537 03070554 03070558 03070558	8403060207 8403060212 8403060219 8403060222 8403060222	B4/02/17 B4/03/01 B4/02/16 B4/02/17 B4/02/17	50-323 50-322 9A777 50-287 50-287	Q T P P
8403050245 8403050247 8403050250 8403050251 8403050253	8403050223 8403050238 8403050223 8403050248 6403050248	84/02/07 84/02/21 84/02/07 84/01/30 84/01/30	FOIA 50-282 50-382 50-382	84 84 84	03060245 03060252 03060259 03060266 03060267	8403060212 8403060212 8403060254 8403060254 8403060245	84/03/01 84/03/01 84/03/02 84/03/02 84/02/28	50-322 50-322 50-322 50-322 50-454	T T T T Q
8403050256 8403050266 8403050270 8403050274 8403050279	8403050223 8403050223 8403050223 8403050223 8403050223	84/02/07 84/02/07 84/02/07 84/02/07 84/02/07	50~255 FOIA FOIA FOIA FOIA	84 84 84	103040270 103040274 103040278 103040277 103040280	8403060254 8403060264 8403060254 8403060273 8403060275	84/03/02 84/03/01 84/03/02 84/02/28 84/02/29	50-322 50-278 50-322 50-254 50-440	T F T P
8403050318 8403050319 8403050322 8403050323 8403050327	8403050315 8403050315 8403050315 8403050315 8403050320	84/02/08 84/02/08 84/02/08 84/02/08 84/02/28	WARTE MOT WARTE MOT WARTE MOT WARTE MOT XPORTLIC	84 84 84	03040287 103040295 103040301 103040302 103040303	B403060354 B403060254 B403060254 B403060300 B402090012	64/03/02 84/03/02 64/03/02 64/02/28 64/02/29	50-322 50-322 50-322 50-324 50-275	T T P Q

ACCESSIO	N NUMBER				ACCESSI	ON NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	EUBJECT CATEGOR		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT	
8403060304	8403060296	84/02/29	50-324	P	8403070104	8403070101	84/02/16	FOIA	
8403060307 8403060310	8403060254	B4/03/02	50-322	Ţ	8403070108	8403070101	84/02/16	FOIA	
8403060314	8403060254 8403060254	84/03/02 84/03/02	50-322 50-322	F T	8403070112 8403070123	8403070107 8403070120	84/02/26 84/03/02	70-824 50-461	
8403040315	B403060305	84/03/01	50-315	á	8403070129	8403070125	84/02/24	50-395	Q
840304031B 8403040317	8403060254 8403060254	84/03/02 84/03/02	50~322 50~322	T T	6403070131 8403070133	8403070125	84/02/24	50-395	g
B403060322	8403060254	84/03/02	50-322	Ť	B403070134	8403070125 8403070125	84/02/24 84/02/24	50-395 50-395	Q Q
8403060326 8403060328	8403060325 8403060327	84/02/17 84/03/05	50-213 50-219	P	8403070139 8403070141	8403070135 8403070137	84/03/03 84/02/24	50+250 50-277	Ģ P
B403060331	B403060329	84/03/01	70-734		8403070143	8403070135	84/03/03	50~250	٥
8403060344 8403060347	8403050341 8403050345	84/02/07 84/02/28	50-344 50-454	Q E	8403070144	8403070137	84/02/24	50-277	P
8403060352	Ø40306034B	B4/03/02	QA999	=	8403070145 8403070147	8403070140 8403070146	84/02/13 84/02/08	50-335 70-27	Q
8403060355	B403060348	84/03/02	0A999		8403070150	8403070147	84/03/02	50-322	T
8403060360 8403060361	84030603 57 8403060348	84/03/05 84/03/02	50-537 QA999	Α	8403070153 8403070154	8403070146 8403070147	84/02/08 84/03/02	70-27	_
8403060362	B403060359	84/02/24	50-302	P	6403070155	8403070151	84/02/27	50-322 50-327	Œ
8403060365 8403060366	8403060348 8403060357	84/03/02 84/02/24	GA999 50~302	P	8403070156	8403070151	84/02/27	50-327	a
8403060368	8403060364	84/02/24	50-302	, b	8403070138	8403070147	84/03/02	50-322	T
B403040369	8403060348	84/03/02	0A999		8403070159 8403070160	8403070151 8403070147	84/02/27 84/03/02	50-327 50-322	Q. T
8403060372 8403060373	8403060348	84/03/02	QA999	_	B403070161	8403070152	84/02/08	CONTRACT	•
8403060374	8403060371 8403060348	84/02/21 84/03/02	50-445 GA999	G	8403070162 8403070163	8403070157 8403070151	84/02/28 84/02/27	50-324 50-327	P
B403060376	640306034B	84/03/02	QA999		8403070145	B403070147	84/03/02		G _
8403060379	8403060348	84/03/02	9A999		B403070167	8403070152	84/03/02 84/02/08	50-322 Contract	Т
8403060393 8403060398	8403060392 8403060385	84/03/01 84/03/01	50-276 50-324	9	8403070171 8403070172	8403070147	84/03/02	50-322	Ţ
8403060406	6403060401	84/02/17	50-312	ã	8403070173	8403070152 8403070168	84/02/08 84/02/22	CONTRACT 50-414	g
8403060407	8403060395	84/03/01	50-329	G	8403070176	8403070169	84/02/22	50-416	a
8403060410 8403060414	8403040405 8403040402	84/03/01 84/02/29	50-30 50-302	R	8403070178	8403070147	84/03/02	50-322	Ť
8403060415	B403060395	84/03/01	50-329	G.	8403070180 8403070181	840307016B 8403070177	84/02/22 84/02/29	50-416 50-445	G.
8403060420	84030403B5	84/03/01	50-329	G	8403070182	B403070177	84/02/29	90-445	Ğ
B403050421 B403050423	8403060416 8403060385	84/03/01 84/03/01	70-1257 50-329	a	B403070183	8403070147	84/03/02	50-322	т
8403060427	8403060424	84/03/02	50-361	P	84030701 <i>6</i> 4 64030701 <i>6</i> 4	8403070179 8403070168	84/02/22 84/02/22	50-400 50-416	Q Q
8403060428 8403060440	84030603B5 8403060436	84/03/01 84/02/21	50-329 50-321	Q. P	8403070187 8403070190	840307016B 8403070147	84/02/22 84/03/02	50-416 50-322	ä
8403060442	8403060385	84/03/01	50~329	Q	B403070193	8403070179	84/02/22	50~400	o.
B403060444	8403060385	84/03/01	50-329	a	B403070195	8403070147	B4/03/02	50-322	Ť
8403060445 8403060449	8403060385 8403060447	84/03/01 84/02/21	50-329 50-344	g P	8403070197 8403070198	8403070179 8403070147	84/02/22	50~400 50~322	9
B403040459	8403060454	84/02/16	50-245	P)	B403070199	8403070179	84/03/02 84/02/22	50-400	T G
B403060466	8403040442	84/02/23	50-338	F	8403070201	B403070147	84/03/02	50-322	T
8403060495 8403060499	8403060491 8403060494	84/02/27 84/02/29	CONTRACT REGGD		8403070202 8403070204	8403070185	84/62/28	50-413	A
8403040502	8403040500	84/02/27	CONTRACT		8403070204 8403070204	8403070147 8403070168	84/03/02 84/02/22	50-322 50-414	O.
8403060510	B40306050B	B4/02/21		F	8403070207	8403070147	B4/03/02	50-322	т
8403060521 8403060527	8403060519 8403060077	84/02/24 84/02/24	Waste Mot 50-335	P	9403070208 8403070209	8403070168 8403070168	84/02/22 84/02/22	50-416 50-416	a a
8403060536 8403060554	8402070039 8402070037	B4/03/12	50-322 50-322	5 9	B403070210	B403070205	84/02/24	50-413	Q
8403060573	8403060569	84/03/12 84/02/21	XPORTLIC	0	8493070211 8403070214	8403070147 8403070147	84/03/02 84/03/02	90-322 90-322	Ţ
8403070009	B403070005	84/02/06	CONTRACT		8403070216	8403070168	84/02/22	50-416	a
8403070013 8403070017	8403070007 8403070012	84/02/10 84/02/13	50-395 50-413	a a	8403070217	8403070147	84/03/02	50-322	Ţ
B403070017	6403070015	84/02/28	70-1201		8403070219 8403070220	8403070185 8403070147	84/02/28 84/03/02	50-413 50-322	A T
8403070022	8403070020	84/02/29	50-443	G	8403070221	8403070215	84/01/23	50-440	Á
8403070024 8403070030	8403070018 8403070027	84/02/10 84/02/29	50-424 40-2061	O O	8403070222	8403070147	84/03/02	90-355	Ţ
8403070032	8403070029	84/02/27	CONTRACT		6403070224 6403070227	8403070218 8403070147	84/02/23 84/03/02	50-438 50-322	Q T
8403070037 8403070046	8403070033 8403070039	B4/02/29 84/02/27	50-413 CONTRACT	C	8403070231 8403070234	8403070147 8403070229	84/03/02	50-322	τ
8403070058	8403070055	84/02/28		e	8403070238		84/02/23 84/02/03	FOIA	_
8403070057	8403070055	84/02/26	50-400	Q.	8403070242	8403070236 8403070240	84/03/02 84/02/17	50~387	G G
8403070060 8403070067	8403070053 8403070053	84/02/08 84/02/08		U	8403070244 8403070246	8403070243 8403070239	84/02/22		Ħ
8403070072	8403070067	84/01/11		ă	840307024B	8403070237 8403070247	83/11/25 84/02/09	50-280 50-416	g Q
8403070073	8403070053	84/02/08		Ų	8403070252	8403070251	84/02/29		P
840307007& 8403070079	8403070053 8403070075	84/02/08 84/02/29		U P	8403070253 8403070257	8403070250 8403070255	84/02/10	50-280	G .
8403070083	8403070075	84/02/29	50~275	P	8403070257	8403070255 8403070258	84/02/29 84/02/17	50-266 70-1100	P
8403070088	8403070085	B4/02/07		a	8403070261	8403070240	84/02/29		R
6403070095 6403070096	8403070094 8403070094	84/02/23 84/02/23		a a	B403070267 B403070275	9403070264 8403070273	84/02/27	70-474	c
8403070100	8403070094	84/02/23	50-400	D D	8403070gB1	8403070276	84/03/01 84/02/28		C G
8403070102 8403070105	8403070094 8403070094	84/02/23 84/02/23		a G	B403070287 8403070288	8403070282 8403070284	B4/02/21	50-289	Q P
		_ ,			9402070200	27V3U/U#04	84/02/29	50-275	r

ACCESSIO	N NUMBER					IN NUMBER			
ENCLOBURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT	łΥ	ENGLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT	RY
8403070292 8403070302 8403070306 8403070308 8403070310	8403070284 8403070297 8403070301 8403070303 8403070307	84/02/27 84/02/16 84/02/21 84/02/28 84/02/06	50-275 50-423 50-387 50-412 50-324	P Q Q Q	8403080078 8403080079 8403080082 8403080084 8403080086	8403080027 8403080027 8403080027 8403080027 8403080081	83/12/30 83/12/30 83/12/30 83/12/30 84/03/02	FOIA FOIA FOIA FOIA 50-348	р
8403070318 8403070318 8403070319 8403070322 8403070323	8403070312 8403070315 8403070314 8403070320 8403070321	84/02/23 84/02/27 84/02/22 84/02/22 84/02/23	50-333 50-325 50-352 50-277 50-305	9 9 9 P	8403080087 8403080092 8403080092 8403080093 8403080098	8403080027 8403080027 8403080027 8403080027 8403080048	83/12/30 83/12/30 83/12/30 83/12/30 84/01/17	FOIA FOIA FOIA FOIA	
B403070328 B403070331 B403070334 B403070335 B403070336	8403070324 8403070327 8403070327 8403070327 8403070333	84/02/23 84/02/22 84/02/22 84/02/22 84/02/28	70-27 50-413 50-413 50-413 50-423	a a a	8403080079 8403080101 8403080102 8403080103 8403080103	8403080027 8403080014 8403080027 8403080076 8403080027	83/12/30 84/01/11 83/12/30 84/01/23 83/12/30	FOIA FOIA FOIA 50-275 FOIA	E
8403070338 8403070340 8403070341 8403070343 8403070344	8403070327 8403070229 8403070330 8403070229 8403070342	84/02/22 84/02/23 84/02/28 84/02/23 84/02/28	50-413 50-329 50-293 50-329 50-334	G G G	8403080108 8403080109 8403080111 8403080112 8403080113	8403080016 8403080027 8403080027 8403080027 8403080016	84/01/11 83/12/30 83/12/30 83/12/30 84/01/11	FDIA FDIA FDIA FDIA FDIA	
8403070345 8403070346 8403070349 8403070351 8403070362	8403070229 8403070239 8403070229 8403070229 8403070360	84/02/23 84/02/10 84/02/23 84/02/23 84/02/27	50-329 CONTRACT 50-329 50-329 50-5	9 9 6 F	8403080117 8403080119 8403080120 8403080121 8403080122	8403080027 8403080048 8403080016 8403080027 8403080027	83/12/30 84/01/17 84/01/11 83/12/30 83/12/30	FOIA FOIA FOIA FOIA	
8403070366 8403070369 8403070373 8403070381 8403070382	8403070269 8403070364 8403070371 8403070377 8403070379	84/02/15 83/06/02 84/02/29 84/02/27 84/02/27	50-334 50-269 CONTRACT XPORTLIC 50-348		8403080123 8403080124 8403080125 8403080127 8403080128	8403080027 8403080027 8403080114 8403080018 8403080048	83/12/30 83/12/30 84/02/23 84/01/11 84/01/17	FOIA FOIA 50-373 FOIA FOIA	œ
B403070383 B403070384 B403070389 B403070390 B403070391	8403070380 8403070379 8403070387 8403190450 8403070387	84/03/01 84/02/29 84/02/27 84/03/05 84/02/27	27-39 50-348 50-334 50-315 50-334	P P P	8403080127 8403080132 8403080133 8403080134 8403080137	8403080027 8403080027 8403080027 8403080027 8403080027	83/12/30 83/12/30 83/12/30 83/12/30	FOIA FOIA FOIA FOIA	
8403070395 8403070398 8403070402 8403070409 8403070414	8403190450 8403070394 8403070394 8402090039 8403070411	84/03/05 84/02/29 84/02/29 84/03/12 84/02/29	50-315 50-247 50-247 50-322 CONTRACT	8 8	8403080138 8403080137 8403080144 8403080144 8403080144	8403080048 8403080027 8403080027 8403080048 8403080027	84/01/17 83/12/30 83/12/30 84/01/17 83/12/30	FOIA FOIA FOIA FOIA	
8403070423 8403070425 8403070426 8403080006 8403080008	8402090039 8403070424 8403070424 8403080005 8403080005	84/03/12 84/02/28 84/02/28 84/02/24 84/02/24	50-322 XPORTLIC XPORTLIC FOIA FOIA	ន	8403080149 8403080150 8403080151 8403080152 8403080154	8403080126 8403080027 8403080027 8403080145 8403080126	84/03/01 83/12/30 83/12/30 84/02/13 84/03/01	FOIA FOIA FOIA 50-528 FOIA	a
8403080007 8403080010 8403080012 8403080017 8403080017	8403080007 8403080005 8403080005 8403080005	84/03/02 84/02/24 84/02/24 84/02/24 84/02/24	50-29 FOIA FOIA FOIA	P	8403080155 8403080157 8403080157 8403080159 8403080160	8403080068 8403080027 8403080027 8403080027 8403080027	84/01/17 83/12/30 83/12/30 83/12/30 83/12/30	FOIA FOIA FOIA FOIA	
8403080025 8403080029 8403080032 8403080033 8403080036	8403080005 8403080005 8403080016 8403080027	84/02/24 84/02/24 83/12/30 84/01/11 83/12/30	FOIA FOIA FOIA FOIA FOIA		8403080162 8403080165 8403080165 8403080166 8403080167	8403080016 8403080027 8403080068 8403080027 8403080027	84/01/11 83/12/30 84/01/17 83/12/30 83/12/30	FOIA FOIA FOIA FOIA	
84 03080038 84 03080040 84 03080043 84 03080044 84 03080045	8403080016 8403080027 8403080027 8403080016 8403080027	84/01/11 83/12/30 83/12/30 84/01/11 83/12/30	FOIA FOIA FOIA FOIA		8403080149 8403080170 8403080172 8403080173 8403080173	8403080027 8403080016 8403080027 8403080048 8403080016	83/12/30 84/01/11 83/12/30 84/01/17 84/01/11	FOIA FOIA FOIA FOIA FOIA	
8403080046 8403080049 8403080050 8403080051	8403080027 8403080016 8403080027 8403080027 8403080027	83/12/30 84/01/11 83/12/30 83/12/30 83/12/30	FOIA FOIA FOIA FOIA		8403080177 8403080180 8403080181 8403080182 8403080182	8403080027 8403080016 8403080068 8403080027 8403080027	83/12/30 84/01/11 84/01/17 83/12/30 83/12/30	FOIA FOIA FOIA FOIA	
8403080054 8403080055 8403080056 8403080057 8403080058	8403080027 8403080027 8403080027 8403080016 8403080027	83/12/30 83/12/30 83/12/30 84/01/11 63/12/30	FOIA FOIA FOIA FOIA		8403080186 6403080189 8403080189 8403080190 8403080191	840308001& 840308017& 84030800&8 8403080027 8403080016	84/01/11 84/02/23 84/01/17 83/12/30 84/01/11	FGIA 50-461 FGIA FGIA FGIA	G
B4030B0059 B4030B0060 B4030B0064 B4030B0066 B4030B0069	8403080027 8403080027 8403080027 8403080027 8403080027	83/12/30 83/12/30 83/12/30 83/12/30 83/12/30	FOIA FOIA FOIA FOIA		8403080193 8403080193 8403080195 8403080198 8403080197	8402090022 8403080016 8403080158 8403080016 8402090022	84/03/05 84/01/11 84/03/02 84/01/11 84/03/05	50-275 FOIA 50-348 FOIA 50-275	Q P Q
B403080070 B403080072 B403080074 B403080075 B403080076	8403080027 8403080027 8403080027 8403080041 8403080027	83/12/30 83/12/30 83/12/30 84/02/21 83/12/30	FOIA FOIA FOIA 50-312 FOIA	a	B4030B0202 B4030B0204 B4030B0209 B4030B0210 B4030B0211	8403080016 8403080016 8403080016 8403080205 8403080016	84/01/11 84/01/11 84/01/11 84/03/02 84/01/11	FOIA FOIA 50-316 FOIA	P

ACCESS10					ACCESSION				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE (SSUED	SUBJECT CATEGOR		ENCLOSURE	PRINCIPAL DOCUMENT	DATE 198VED	SUBJECT CATEGOR'	Y
8403080212 8403080214 8403080215 8403080216 8403080217	8403080203 8403080208 8403080016 6403080205 8403080016	84/01/24 84/03/05 84/01/11 84/03/02 84/01/11	50-413 50-315 FOIA 50-316 FOIA	9 9 P	B403090116 B403090135 B403090141 B4030901B3 B403090191	8403090100 8403090133 8403090138 8403090178 8403090185	84/02/29 84/02/27 84/02/27 84/03/02 84/02/13	20-298 CONTRACT CONTRACT PR 70-297	P P
8403080218 8403080220 8403080223 8403080225 8403080242	8403080207 8403080205 8403080205 8403080207 8403080238	84/01/23 84/03/02 84/03/02 84/03/05	FOIA 50-316 50-316 FOIA 50-263	P P	8403090194 8403090196 8403090200 8403090202 8403090203	8403090185 8403090187 8403090198 8403090198 8403090198	84/02/15 84/02/04 84/01/17 84/01/17 84/01/17	50-237 50-321 PT21 PT21 PT21	P
8403080244 8403080253 8403080254 8403080261 8403080263	8403080238 8403080179 8403080251 8403080251 8403080254	84/03/05 84/02/13 84/02/22 84/02/22 84/02/27	50-243 50-508 50-483 50-483 50-528	F 0 0	8403090221 8403090227 8403090230 8403090233 8403090238	8403090218 8403090177 8403090177 8403090177 8403090177	84/03/06 84/03/07 84/03/07 84/03/07 84/03/07	50-155 50-361 50-361 50-361 50-361	PPP
8403060269 8403080269 8403080270 8403080273 8403080276	8403080265 8403080264 8403080266 8403080265 8403080274	84/03/01 84/03/01 84/02/22 84/03/01 84/02/23	50-298 50-280 50-397 50-298 50-312	F G P G	8403070239 8403070259 8403070260 8403070277 8403090315	8403090232 8403090255 8403090252 8403090262 8403090314	84/03/06 84/03/01 84/03/02 84/02/29 83/09/30	50~387 50~348 50~324 50~331 TOPREP	8 P P
8403080277 8403080281 8403080283 8403080302 8403080304	8403080274 6402090030 6403080278 8403080299 6403080245	84/02/23 84/03/02 84/02/29 84/02/24 84/03/01	50-312 50-275 50-413 50-315 50-298	0 E M G F	8403090316 8403090318 8403090319 8403090321 8403090322	8403070314 8403070314 8403070314 8403070314 8403070314	83/09/30 83/09/30 83/09/30 83/09/30 83/09/30	TOPREP TOPREP TOPREP TOPREP TOPREP	
8403080314 8403080316 8403080327 8403080332 8403080333	8403080312 8402070006 8403080325 8403080325 8403080325	84/03/02 84/02/23 84/01/20 84/01/20 84/01/20	71-6601 50-247 50-445 50-445 50-445	F 01 01 02	8403070323 8403070324 8403070325 8403070327 8403070328	8403070314 8403070314 8403070314 8403070314	83/09/30 83/09/30 83/09/30 83/09/30 83/09/30	TOPREP TOPREP TOPREP TOPREP	
8403080335 8403080341 8403080352 8403080360 8403080364	8403080325 8403080339 8403080347 8403080357 8403080357	84/01/20 84/01/20 84/03/02 84/01/17 84/01/17	50-445 50-280 50-336 FOIA FOIA	G G P	8403070327 8403070330 8403070332 8403120005 8403120010	8403090314 8403090314 8403090314 8403120003 8403120004	83/09/30 83/09/30 83/09/30 84/03/05 84/03/06	TOPREP TOPREP TOPREP 50-271 50-275	P G
8403080346 8403080377 8403080379 8403080381 8403080383	8403080357 8403080372 8403080375 8403080372 8403080375	84/01/17 84/01/31 84/02/17 84/01/31 84/02/17	F01A 50-424 F01A 50-424 F01A	e e	6403120012 6403120015 6403120017 6403120018 6403120082	8403120006 8403120006 8403120006 8403120006 8403120006	84/03/06 84/03/06 84/03/06 84/03/06 84/03/06	50-275 50-275 50-275 50-275 50-275	0000
8403080384 8403080375 8403080377 8403080400 8403080404	8403080372 8403080394 8403080397 8403080390 8403080390	84/01/31 84/02/29 84/02/29 84/02/13 84/02/13	50-424 71-6406 71-9001 50-528 50-528	G C D	8403120023 8403120027 8403120030 8403120080 8403120080	9403120004 9403120004 8403120024 8403120044 9403120065	84/03/06 84/03/06 84/03/07 84/03/07 84/02/22	50-275 50-275 50-386 50-220 50-458	G G A G
8403080407 8403080407 8403080411 8403080412 8403080414	8403080403 8403080390 8403080405 8403080410 8403080413	84/02/29 84/02/13 84/03/02 84/03/01 84/02/29	50~287 50~528 50~275 50~320 50~275	Q A F P	8403120072 8403120073 8403120079 8403120086 8403120102	8403120045 8403120070 8403120070 8403120081 8403120101	84/02/22 84/02/24 84/02/24 84/03/06 84/03/02	50-458 50-237 50-237 50-247 50-320	0 0 0 P
8403080415 8403080417 8403080418 8403080420 8403080421	8403080413 8403080405 8403080416 8403080405 8403080405	84/02/29 84/03/02 84/03/01 84/03/02 84/03/02	50-275 50-275 71-7080 50-275 50-275	ዎ ቻ 5	8403120114 8403120124 8403120125 8403120126 8403120133	8403120108 8403120116 8403120120 8403120122 8403120120	84/03/05 84/02/24 84/02/23 84/03/06 84/02/23	0A777 50~315 50~331 50~440 50~331	0 0 0
8403080422 8403080425 8403080424 8403080431 8403090003	8403080393 8403080393 8403080405 8403080405 8408280291	84/03/02 84/01/27 84/03/02 84/03/02 84/01/31	50-275 50-289 50-275 50-275 50-289	Р Р Е U	8403120137 8403120138 8403120145 8403120156 8403120158	8403120135 8403120135 8403120141 8403120153 8403120153	84/02/23 84/02/28 84/02/23 83/10/28 83/10/28	50-237 50-245 50-263 50-413 50-413	0 R 0 E E
E403070004 8403070005 8403070007 8403070008 8403070007	8402220271 8402220271 8402220271 8402220271 8402220271	84/01/31 84/01/31 84/01/31 84/01/31	50-289 50-289 50-289 50-289 50-289	0 U U U	8403120161 8403120165 8403120167 8403120172 8403120185	8403120153 8403120164 8403120164 8403120170 8403120184	83/10/28 84/03/08 84/03/08 84/03/05 84/03/06	50-413 50-382 50-384 50-344 50-341	E F O O
8403090010 8403090011 8403090013 8403090014 8403090019	8402220291 8402220291 8402220291 8403090012 8403090017	84/01/31 84/01/31 84/01/31 84/02/29 84/02/28	50-289 50-289 50-289 50-528 FOIA	U U E	8403120172 8403120175 8403120213 8403120216 8403120217	8403120183 8403120183 8403120210 8403120210 8403120214	84/03/09 84/03/09 84/02/29 84/02/29 84/03/01	50-285 50-285 50-369 50-369 50-335	P
8403090039 8403090039 8403090043 8403090073 8403090089	8403070032 8403070037 8403070037 8403070070 8403070081	84/03/02 84/02/22 84/02/22 84/03/05 84/02/21	50-382 50-354 50-354 50-219 50-277	A G G G	8403120219 8403120226 8403120242 8403120244 8403120252	8403120214 8403120221 8403120234 8403120240 8403120240	84/03/01 84/03/02 84/03/02 84/02/29 84/02/27	50-335 CONTRACT 40-4920 50-335 50-335	P G G
8403070092 8403070098 8403070101 8403070108 8403070115	8403070088 8403070075 8403070075 8403070104 8403070112	84/03/05 84/02/28 84/02/28 84/03/05 84/03/06	50-331 50-247 50-247 50-445 50-413	P P T G	8403120308 8403120311 8403120314 8403120342 8403120345	8403120305 8403120305 8403120304 8403120339 8403120340	84/02/27 84/02/27 84/02/28 84/02/21 84/02/22	50~293 50-293 CONTRACT 50-312 CONTRACT	F F

	N NUMBER					DN NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	CATEG	DRY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJEC CATEGO	
8403120357 8403120388 8403120393 8403130011 8403130014	8403120354 8403120376 8403120376 8403130002 8403130007	84/02/21 84/02/06 84/02/06 84/02/22 84/03/07	50-302 COMMIS COMMIS 50-246 50-354		8403130327 6403130330 8403130334 8403130335 8403130338	8403130317 8403130318 8403130305 8403130326 8403130317	84/03/05 84/03/09 84/03/01 84/03/05 84/03/05	0A999 50-397 50-317 50-409 0A999	P R G
8403130018 8403130021 8403130023 8403130036 8403130036	8403130012 8403130006 8403130002 8403130012 8403130032	84/03/09 84/02/27 84/02/22 84/03/09 84/02/02	0A777 50-322 50-322 50-322	0 0 0	8403130344 8403130345 8403190359 8403130352	8403130341 8403130320 8403130340 8403130343 8403130342	84/02/08 84/03/08 84/03/07 84/03/09 84/03/06	50-370 50-482 50-220 50-312 50-482	P G A
8403130038 8403130041 8403130042 8403130051 8403130052	8403130031 8403130012 8403130032 8403130044 8403130045	94/03/01 84/03/09 84/02/02 84/03/09 84/03/01	50-348 50-322 0A979 50-341 50-34	P K P	8403130359 8403130347 8403130347 8403130372 8403130375	8403130348 8403130343 8403130360 8403130365 8403130342	84/03/06 84/03/09 84/02/03 84/03/08 84/03/06	50-373 50-312 50-423 50-354 50-482	0 0 0 A
8403130053 8403130058 8403130060 8403130063 8403130064	8403130012 8403130046 8403130044 8403130012 8403130055	84/03/09 84/02/16 84/03/09 84/03/09 84/02/07	50-322 GA799 50-341 50-322 GA999	K O	8403130376 8403130379 8403130379 8403130379 8403130402	8403130340 8403130342 8403130386 8403130390 8403130395	84/02/03 84/03/06 84/03/08 84/03/08 84/02/16	50-423 50-482 50-220 50-482 50-313	С Р О
8403130068 8403130073 8403130076 8403130077 8403130082	8403130046 8403130012 8403130046 8403130071 8403130012	84/02/16 84/03/09 84/02/16 84/03/11 84/03/09	9A999 50-322 9A999 50-413 50-322	0 0 0	8403130412 8403130418 8403130418 8403130420 8403130421	8403130254 8403130407 8403130410 8403080149 8403130414	84/02/27 83/11/17 84/03/05 84/03/01 84/02/21	50-286 08799 50-237 50-315 50-461	R P R G
8403130087 8403130087 8403130090 8403130091 8403130094	8403130079 8403130046 8403130012 8403130085 8403130083	84/03/01 84/02/16 84/03/07 84/03/08 84/02/23	50-243 0A999 50-322 50-322 40-3392	R	B403130425 8403130430 8403130432 8403130433 8403130433	8403130407 8403130414 8403130268 8403130422 8403130428	83/11/17 84/02/21 84/02/17 84/03/08 84/03/09	GA999 50-461 GA999 40-6329 50-320	Q P
8403130076 8403130077 8403130100 8403130103 8403130106	8403130079 8403130012 8403130088 8403130079 8403130092	84/03/01 84/03/09 84/03/07 84/03/01 84/03/07	50-263 50-322 50-327 50-263 50-440	R G R A	8403130444 8403130445 8403130451 8403130453 8403130459	8403130441 8403130438 8403130443 8403130442 8403130447	84/02/17 84/03/08 84/03/08 84/02/22 84/03/09	0A999 50-458 50-289 50-445 50-400	0 0 0
8403130109 8403130117 8403130118 8403130119 8403130126	8403130012 8403130101 8403130072 8403130012 8403130116	84/03/09 84/02/27 84/03/07 84/03/09 83/09/13	50-322 40-2041 50-440 50-322 50-445	O O F	8403130460 8403130463 8403130460 8403130471 8403130476	8403130441 8403130455 8403130452 8403130467 8403130472	84/02/17 84/03/01 84/02/29 84/02/27 84/03/07	0A999 50-348 50-325 50-320 70-1100	Р О
8403130128 8403130135 8403130136 8403130138 8403130140	8403130092 8403130122 8403130116 8403130092 8403130131	84/03/07 84/01/25 83/09/13 84/03/07 84/01/18	50-440 50-267 50-445 50-440 50-382	A G F A Q	8403130483 8403130487 8403130488 8403130487 8403130487	8403130475 8403130486 8403130478 8403130475 8403130474	84/02/29 84/02/27 84/03/08 84/02/29 84/02/23	50-320 50-458 50-331 50-320 CONTRACT	R F R
8403130142 8403130143 8403130148 8403130149 8403130154	8403130132 8403130133 8403130122 8403130132 8403130133	84/03/02 84/02/28 84/01/25 84/03/02 84/02/28	50-244 50-346 50-267 50-244 50-346	R P Q R P	8403130497 8403140012 8403140023 8403140024 8403140038	8403130498 8403140009 8403140017 8403140021 8403140032	84/02/17 84/03/09 84/03/07 84/03/01 84/03/07	50-312 50-458 50-250 50-329 50-329	0 0 4 A
8403130157 8403130164 8403130168 8403130172 8403130178	8403130132 8403130155 8403130153 8403130163 8403130171	84/03/02 84/03/09 84/03/08 84/03/05 84/03/07	50-244 50-400 50-329 50-282 50-272	R Q A F F	8403140060 8403140080 8403140091 8403140091 8403140095	8403140057 8403140048 8403140050 8403140048 8403140048	84/93/05 84/93/02 84/93/12 84/93/02 84/93/02	50-441 50-322 50-322 50-322 50-322	9 5 5 5
8403130176 8403130201 8403130207 8403130207 8403130217	8403130184 8403150283 8403130184 8403130198 8403130183	84/03/07 84/02/27 84/03/07 84/03/05 84/02/28	50-400 27-48 50-400 50-263 50-445	0 F 0	8403140099 8403140109 8403140117 8403140125 8403140140	8403140096 8403140101 8403140113 8403140120 8403140131	84/03/01 84/03/07 84/03/05 84/03/08 84/02/28	50-155 50-423 50-354 50-400 TDPREP	C K A F
8403130220 8403130230 8403130257 8403130258 8403130263	8403130196 8403130186 8403130251 8403130245 8403130251	84/03/07 84/03/07 84/03/02 84/03/01 84/03/02	50-400 50-400 50-247 50-262 50-247	9 P R	B403140143 B403140148 B403140168 B403140170 8403140178	8403140133 8403140159 8403140159 8403140166 8403140174	84/03/09 84/03/05 84/03/05 84/03/09 84/03/07	50-249 50-400 50-400 PR 50-400	P Q Q
6403130270 6403130272 6403130276 6403130280 6403130281	8403130245 8403130267 8403130245 8403130269 8403130276	84/03/01 84/02/27 84/03/01 84/02/27 84/02/08	50-262 50-219 50-219 50-219 6A999	R G G	8403140180 8403140180 8403140184 8403140188 8403140200	8403140175 8403140175 8403140175 8403140175 8403140133	84/03/09 84/03/09 84/03/09 84/03/09 84/02/28	50-373 50-373 50-373 50-249 50-280	F F B O
8403130289 8403130291 8403130293 8403130302 8403130308	8403130283 8403130276 8403130277 8403130294 8403130294	84/03/01 84/02/08 84/02/28 84/03/08 84/03/08	50-213 QA999 TOPREP 70-2199 70-2199	R	B403140202 B403140204 B403140205 B403140208 B403140208	8403140177 8403140179 8403140203 8403140205 8403140215	84/02/28 84/02/28 84/02/27 84/03/06 83/12/16	50-280 50-280 50-204 50-382 40-8027	0 0 9 U
8403130312 8403130314 8403130319 8403130322 8403130325	8403130300 8403130305 8403130313 8403130305 8403130307	84/02/23 84/03/01 83/09/13 84/03/01 84/02/16	MISC 50-317 50-445 50-317 GA999	R F R	B403140239 B403140239 8403140240 B403140256 B403140279	8403140235 8403140236 8403140233 8403140252 8403140272	84/03/05 64/02/22 64/03/05 64/02/22 64/02/22	71-513 50-324 MISC 50-298 50-293	F F

ACCESS10	N NUMBER					ACCESSION	NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUDJECT CATEGORY	,	ENG	LOSURE	PRINCIPAL DOCUMENT	DATE IBSUED	SUBJECT CATEGOR	
84031 4030 6 84031 40309 84031 40328 84031 5001 4 84031 5001 7	8403140300 8403140307 8403140325 8403150007 8403150012	84/03/01 84/03/07 84/03/05 84/03/09 84/03/01		a 0 0	940 840 840 840	03160202 03160204 03160208 03160210 03160212	8403140201 8403140203 8403140205 8403140204 8403140207	84/02/14 84/03/12 84/03/07 84/02/21 84/02/23	50-390 50-219 50-219 50-335 50-424	Q Q Q
84031 50022 84031 50030 84031 50034 84031 50041 84031 50045	8403150027 8403150027 8403150027 8403150037 8403150040	84/03/13 84/02/28 84/02/28 84/02/29 84/03/09	50~388 50~313	0 0 0 P P	840 840 840	03160223 03206160 03206160 03160226 03160226	8403160211 8403160211 8403160211 8403160214 8403160218	84/03/05 84/03/05 84/03/05 84/02/17 84/03/01	50-413 50-413 50-413 50-390 50-259	0
8403150060 6403150063 6403150073 6403150078 8403150101	84031 50053 84031 50054 84031 50067 84031 50066 84031 50074	84/03/09 84/02/27 84/03/01 84/02/28 84/03/01	50-277 50-273 50-272	0 0 0 0	940 940 940	03160224 03160225 03160230 03160233 03160238	8403160211 8403140217 8403160218 8403160229 8403160232	84/03/05 84/02/15 84/03/01 84/03/09 84/02/16	50-413 50-327 50-259 50-267 50-259	0 0 0 P
8403150104 8403150107 8403150117 8403150119 8403150132	8403150097 8403150099 8403150111 8403150113 8403150125	84/03/13 84/03/09 84/03/09 84/03/09 84/02/28	50-280 50-293 50-313	P Q ይ F G	840 840 840	03160239 03160240 03160244 03160248 03160260	8403160218 8403160237 8403160218 8403160241 8403160255	84/03/01 84/02/27 84/03/01 84/03/02 84/03/12	50-259 50-390 50-259 50-352 50-298	9
8403150135 8403150136 8403150140 8403150148 8403150143	8403150125 8402070032 8403150137 8403150134 8403150137	84/02/28 84/03/13 84/03/07 84/02/28 84/03/07	50-275 50-277 XPDRTL10	Q Т Р	840 840 840	3140262 3140263 3160265 3160268 3160270	8403140249 8403140254 8403140257 8403140254 8403140258	84/02/29 84/03/14 84/03/05 84/02/24 84/03/07	50-261 50-443 50-348 50-335 70-143	G G G
8403150144 8403150149 8403150152 8403150154 8403150159	8402070032 8403150146 8402070032 8403150133 8402070032	84/03/13 84/03/01 84/03/13 84/03/13 84/03/13	50-286 50-275 50-206	T Q T S T	840 840 840	3160272 3160274 3160275 3160277 3160279	8403160257 8403160267 8403160249 8403160257 8403160271	84/03/05 84/03/07 84/02/29 84/03/05 84/03/15	50-348 50-261 50-261 50-348 50-390	0 0 0
8403150162 8403150163 8403150164 8403150166 8403150171	8402070032 8403150161 8403150160 8403150146 8403150168	84/03/13 84/03/09 84/03/02 84/03/01 84/03/07	50-241 MISC 50-264	T P a P ,	840 840 840	31 60282 31 60284 31 60299 31 60300 31 60304	8403160273 8403160257 8403160273 8403160247 8403160277	84/03/08 84/03/05 84/03/08 84/02/29 84/03/07	50-259 50-348 50-413 50-261 50-369	000
8403150173 8403150183 8403150194 8403150197 8403150203	8403150168 8403150181 8403150194 8403150197 8403150200	84/03/07 84/02/28 84/03/05 84/02/29 84/03/09	50-327 CONTRACT XPORTLIC	P 5 F	840 840 840	3160307 3160307 3160313 3160314 3160316	8403160293 8403160305 8403160297 8403160293 8403160306	84/03/08 84/02/15 84/03/07 84/03/08 84/02/21	50-413 50-375 50-369 50-413 50-250	9
8403150207 8403150207 8403150222 8403150223 8403150246	8403150205 8403150204 8403150221 8403150221 8403150243	84/01/14 84/02/28 84/03/07 84/03/07 84/02/21	40-8781 CONTRACT WASTE MOT WASTE MOT 50-346	F	840 840 840	31 40317 31 40318 31 40317 31 40320 31 40322	8403160297 8403160308 8403160293 8403160315 8403160297	84/03/07 84/03/05 84/03/08 84/03/12 84/03/07	50-369 50-259 50-413 50-302 50-369	9 9 9 9
8403150250 8403150278 8403150273 8403150275 8403150275	8403150243 8403150270 8403150290 8403150263 8403150270	84/02/21 84/03/07 84/03/06 84/02/27 84/03/07	CONTRACT 50-282	F P	640 640 640	31 60328 31 60327 31 60331 31 60332 31 60337	8403160308 8403160297 8403160327 8403160308 8403160308	84/03/05 84/03/07 84/03/13 84/03/05 84/03/05	50-259 50-369 50-305 50-259 50-259	0 0 0
8403150335 8403150340 8403150341 8403150344 8403150345	8403150328 8403150319 8403150336 8403150328 8403150343	84/03/02 83/10/21 84/03/06 84/03/02 84/02/27	40-8629 50-272 50-269	P ሀ P F	640 640 840	01 60348 91 60347 91 60353 91 60356 91 60357	84031 60340 84031 60338 84031 60337 84031 60343 84031 60338	84/03/02 84/03/09 84/02/27 84/02/17 84/03/09	70-1113 50-321 70-143 50-413 50-321	G G
8403150347 8403160016 8403160017 8403160021 8403160028	8403150343 8403160008 8403160009 8403160009 8403160006	84/02/29 84/03/13 84/03/12 84/03/12 84/03/12	50-390 50-296 50-286	F Q P P P	840 840 840	31 60363 31 60364 31 60365 31 60370 31 60372	84031 60343 84031 60350 84031 60338 84031 60360 84031 60336	84/02/17 84/03/05 84/03/09 84/02/24 84/03/09	50-413 50-390 50-321 50-413 50-321	9
8403160049 8403160052 8403160093 8403160092 8403160096	8403160048 8403160048 8403160079 8403160086 8403160090	84/03/02 84/03/14 84/03/08 84/02/27 84/03/09	50-528 50-445 50-413	P A A Q A	840 840 840	3160374 3160378 3160380 3160383 3160383	8403160350 8403160350 8403160375 8403160350 8403160382	84/03/05 84/03/05 84/03/02 84/03/05 84/02/17	50-390 50-390 70-1113 50-390 50-261	G G
8403160108 8403160111 8403160120 8403160141 8403160146	8403160100 8403160101 8403160110 8403160134 8403160142	84/02/15 84/02/16 84/02/15 84/02/16 84/02/15	50-369 (50-369 (50-269 (0 0 0 9	840 840 840	3140384 3140388 3140387 3190014 3190015	8403160377 8403160335 8403160325 8403170010 8403170010	84/03/05 84/03/08 84/02/24 84/03/09 84/03/09	70-143 50~302 70-143 50-142 50-142	0
8403160157 8403160171 8403160173 8403160178 8403160181	8403160152 8403160162 8403160138 8403160162 8403160162	84/03/02 84/02/29 84/02/28 84/02/29 84/02/29	50-259 (70-143 50-259 (0 9 0 0	840 840 840	3190016 3190021 3190022 3190023 3190042	8403170011 8403170011 8403170010 8403170018 8403170020	84/03/15 84/03/15 84/03/09 84/03/14 84/03/01	50-275 50-275 50-142 50-317 50-282	GGF
8403160184 8403160186 8403160187 8403160188 8403160198	8403160169 8403160162 8403160010 6403160010 8403160196	84/02/29 84/02/29 84/03/13 84/03/13 84/02/24	50-35R (a 9 9	840 840 840	3190058 3190040 3190041 3190047 3190072	8403170053 8403170056 8403170057 8403170065 8403170068	84/03/15 84/03/05 84/03/08 84/03/12 84/03/02	50-400 50-320 50-285 50-400 50-373	G G F



ACCESSIO	N NUMBER					ON NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE Daved	SUBJE(enclosure	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEOD	
8403190076 8403190077 8403190082 8403190087 6403190088	8403190048 8403190074 8403190074 8403190083 8403190085	84/03/02 84/03/15 84/03/15 84/03/08 84/03/14	50-373 50-249 50-249 50-267 50-123	0 0 0 P	84031 90373 84031 90381 84031 90381 84031 90385 84031 90399	8403190367 8403190377 8403190379 8402090035 8403190394	84/03/01 84/03/15 84/02/27 84/03/12 84/02/29	50-206 50-338 50-305 50-322 50-413	0 P G S
8403170070 8403170073 8403170074 8403170076 8403170102	8403190084 6403190083 8403190085 8403190085 8403190100	84/03/13 84/03/08 84/03/14 84/03/14 84/03/15	50-373 50-267 50-123 50-123 50-275	0 0 0	B403190404 B403190407 B40320035 B40320037 B40320044	8403190394 8403190408 8403200029 8403200031 8403200038	84/02/29 84/03/06 84/03/15 84/03/16 84/03/12	50-413 50-317 50-317 50-322 50-302	A G F
8403170105 8403170110 8403170113 8403170114 8403170116	8403190100 8403190100 8403190107 8403190100 8403190100	84/03/15 84/03/15 84/03/15 84/03/15 84/03/15	50-275 50-275 50-249 50-275 50-275	0 0 0	8403200052 8403200057 8403200058 8403200042 8403200042	8403200046 8403200053 8403200046 8403200056 8403200046	84/03/15 84/03/15 84/03/15 84/03/14 84/03/15	50-346 50-341 50-346 50-219 50-346	P R P Q P
8403190119 8403190122 8403190126 8403190130 8403190134	8403190100 8403190100 8403190100 8403190100 8403190100	84/03/15 84/03/15 84/03/15 84/03/15	50-275 50-275 50-275 50-275 50-275	0 0 0	B403200067 B403200074 B40320076 G403200077 B403200082	84032000 54 84032000 53 84032000 72 84032000 53 84032000 53	84/03/14 84/03/15 84/03/15 84/03/15 84/03/15	50-219 50-361 0A999 50-361 50-361	QI R R
8403170138 8403170141 8403170142 8403170147 8403170155	8403170132 8403170137 8403170132 8403170136 8403170151	84/03/13 84/03/14 84/03/13 84/03/14 84/03/13	50-352 50-400 50-353 50-259 50-213	0 0 0 0	8403200085 8403200084 840320088 840320089 8403200071	8403200081 8403200053 8403200053 8403200083 8403200053	94/03/16 84/03/15 84/03/15 84/03/14 84/03/15	50-470 50-361 50-361 40-2061 50~361	K R R
0403170161 0403170172 0403170175 0403170179 0403170105	8403190136 8403190136 8403190170 8403190171 8403190183	84/03/14 84/03/14 84/03/14 84/03/14 84/03/02	50-259 50-259 50-461 50-250 GA979	0 0 0	8403200096 8403200101 8403200108 8403200119 8403200119	8403200094 8403200100 8403200109 8403200111	84/03/15 84/03/16 84/03/16 84/03/16 84/03/06	50-333 50-316 50-354 50-407 50-463	P G F G
8403190186 8403190188 8403190187 8403190190 8403190192	8403170180 8403170136 8403170187 8403170183 8403170180	84/03/09 84/03/14 84/03/15 84/03/02 84/03/07	50-329 50-259 50-289 GA999 50-329	A G G	8403200124 8403200136 8403200142 8403200142 8403200143	8403200131 8403200131 8403200131 8403200138 8403200138	84/03/16 84/03/16 84/03/16 84/03/07 84/03/12	50~322 50~322 50~322 0A979 50~322	9
8403190204 8403190208 8403190210 8403190214 8403190217	8403170201 8403170207 8403170209 8403170209 8403170215	84/03/19 84/03/01 84/02/23 84/02/23 84/03/13	50-337 50-254 GA777 GA777 50-320	р 0:	8403200145 8403200146 8403200150 8403200151 8403200152	8403200131 8403200131 8403200138 8403200131 8403200149	84/03/16 84/03/16 84/03/07 84/03/14 84/03/13	50-322 50-322 GA979 50-322 50-423	9 9 A
8403170220 8403170221 8403170228 8403170227 8403170234	8403190219 8403190218 8403190227 8403190225 8403190231	84/03/16 84/02/24 84/03/13 84/03/13 84/03/09	50-414 GA979 50-389 50-482 70-371	O P A	8403200155 8403200157 8403200159 8403200180 8403200181	8403200131 8403200138 8403200131 8403200179 8403200179	84/03/16 84/03/07 84/03/16 84/03/15 84/03/15	50~322 0A999 50~322 50~313 50~313	0 0 F F
8403190239 8403190244 8403190246 8403190247 8403190256	8403170236 8403170240 8403170241 8403170240 8403170251	84/03/13 84/03/05 84/03/14 84/03/05 84/01/31	50-331 50-266 TOPREP 50-266 REVIEW G	G G RP	8403200187 8403200193 8403200198 8403200198 8403200200	8403200187 8403200190 8403200191 8403200191 8403200191	84/03/14 84/03/16 84/03/19 84/03/19	50~482 50~441 50~287 50~287 50~289	K A 0 0
8403190261 8403190265 8403190272 8403190274 8403190278	8403190257 8403190258 8403190271 8403190268 8403190268	84/03/07 84/03/13 84/03/08 84/03/08 84/03/08	50-347 50-284 50-382 50-454 50-454	P G G G	8403200205 8403200208 840320021 8403200214 8403200220	8403200191 8403200201 8403200191 8403200210 8403200218	84/03/19 84/03/15 84/03/19 84/03/15 84/03/12	50~287 50~320 50~287 50~316 50~275	С Р С Р
8403170281 8403170282 8403170283 8403170288 8403170273	8403190278 8403190275 8403190277 8403190277 8403190290	84/03/13 84/03/17 84/03/08 84/03/08 84/02/29	50-285 50-312 50-313 50-313 50-373	0 0 0 0	8403200223 6403200240 8403200243 6403200243 6403200248	6403200223 6403200232 8403200234 8403200232 8403200232	84/03/15 84/03/15 84/03/13 84/03/15 84/03/15	50-315 50-410 50-397 50-410 50-410	P A P A
8403170274 8403170277 8403170305 8403170306 8403170313	8403170286 8403170270 8403170297 8403170300 8403170307	84/03/14 84/02/29 84/03/05 84/03/12 84/03/01	50-546 50-373 50-454 50-331 50-341	а а Р а	8403200251 8403200259 8403200260 8403200263 8403200263	8403200246 8403200246 8403200252 8403200256 8403200264	94/03/14 84/03/14 84/03/14 84/03/13 84/03/14	50-313 50-313 50-482 50-373 50-250	F A Q P
8403170317 8403170321 8403170321 8403170323 8403170324	8403170276 8403170314 8403170314 8403170315 8403170276	84/03/05 84/03/01 84/03/01 84/02/29 84/03/05	50-334 50-275 50-275 50-358 50-334	R G G R	8403200269 8403200277 8403200277 8403200285 8403200288	8403200252 8403200264 6403200274 8403200279 8403200284	84/03/14 84/03/14 84/03/13 84/03/15 84/03/19	50-482 50-250 50-271 50-483 50-29	A P Q Q P
8403170330 8403170333 8403170334 8403170340 8403170347	8403170328 8403170328 8403170314 8403170328 8403170341	84/02/24 84/02/24 84/03/01 84/02/24 84/03/14	GA999 GA999 50-295 GA999 50-346	G	8403200290 8403200291 8403200293 8403200295 8403200297	8403200284 8403200287 8403200281 8403200281 8403200295	84/03/17 84/03/04 84/03/14 84/03/14 84/03/06	50-29 50-263 50-72 50-72 50-484	P G F G
8403190354 8403190357 8403190359	8403170345 8403170348 8403170350 8403170350 8403170350	84/03/14 84/02/28 84/03/04 84/03/04 84/03/13	50-361 50-440 50-267 50-267 50-387	P G P Q	8403200300 8403200301 8403200302 8403200328 8403200335	8403200295 8403140244 8403200323 8403200323 8403200333	84/03/06 84/03/28 84/02/23 84/02/23 84/02/27	50-454 50-275 40-4492 40-4492 40-1341	g g

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESS10						ON NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATÉ ISSUED	CATEG		ENCLOBURE	PRINCIPAL DOCUMENT	DATE 186UED	SUBJECT CATEGOR	
8403200374 8403210005	84032003B7 8403210001	84/02/16 84/03/14	40-8691 40-6920		8403220246		84/03/12	CONTRACT	
8403210010 8403210016	8403210001 8403210006	84/03/14 84/03/09	40-6920 50-317		8403220280 8403220294	8403220288	84/03/12 84/03/21	CONTRACT	Т
8403210020	B403210015	84/03/09	TOPREP	v	84.03220294 84.03220297		84/02/27 84/03/21	XPORTLIC 50-322	т
8403210054 8403210055	8403210047 8403210045	84/03/09 84/03/16	50-320 50-277	g P	840322030x 8403220303		84/03/21 84/03/21	50-322 50-322	Ţ
8403210062 8403210063	8403210057 8403210045	84/03/18 84/03/14	50-416 50-277	P P	8403220310	6403220288	84/03/21	20-355	Ŧ
8403210064	8403210059	84/02/28	50-320	R	8403220312 8403220312		84/03/08 84/03/21	CONTRACT	7
8403210071 8403210078	8403210059 8403210074	84/02/28 84/03/14	50-320 50-341	R	8403220319		84/03/09	CONTRACT	
6403210077	B403210070	84/03/19	50~245	P	8403220324 8403220327		84/03/02 84/03/07	XPORTLIC CONTRACT	
8403210080 8403210081	840321 0 075 840321 0 072	84/03/15 84/03/09	50-324 50-387	ĸ	8403230007 840323002£		84/03/16 84/03/14	50-331 50-341	P A
8403210082 8403210088	8403210076 8403210076	B4/03/01 B4/03/01	50-289 50-289	R	8405230034		84/03/09	50~245	F
B403210090	8403210072	84/03/09	50-387	ĸ	8403230037 8403230046		84/03/20 84/03/19	50-423 50-329	Q R
8403210091 8403210101	8403210085 8403210097	84/03/15 84/03/14	50-373 50-443	K A	8403230052 8403230054	8403230044 8403230049	84/03/07 84/01/31	CONTRACT 50-325	 P
8403210105 8403210119	8403210097 8403210114	84/03/09	50-334 50-275	0	8403230067	8403230062	84/03/20	50-302	P
8403210122	8403210115	84/03/16 84/01/11	50-416	Q	8403230074 8403230081	8403230071 8403230075	84/03/05 84/03/19	CONTRACT 50-373	G
8403210126 84032101 4 3	8403210124 8403 <u>2</u> 10135	84/03/15 84/03/19	50-146 50-244	P	8403230087 8403230089	8403230075 8403230084	84/03/19 84/03/20	50-373 50-416	G P
8403210146	8403210138	B4/03/01	50~289	R	8403230072	8403230084	84/03/20	50-416	r P
8403210156 8403210173	8403210151 8403210169	84/03/19 84/03/20	70~143 50~289	G	8403230099 8403230100	8403230093	84/03/16	50-255	P
8403210181 8403210200	8403210177 8403210197	84/03/20 84/03/07	50-322 50-247	G P	8403230102 8403230102	8403230097 8403230093 8403230093	84/02/29 84/03/16	40-339 <u>2</u> 50-255	P
0403210206	8403210203	84/03/04	50-338	P	8403230107	8403230088	B4/03/16	50-255	P
8403220004 8403220010	8403220002 8403220006	84/03/13 84/03/08	50-219 50-272	e G	8400230111	8403230093	84/03/20 84/03/16	50-10 50-255	Q P
8403220022	8403220013	84/03/16	50-329	R	8403230112 8403230122	8403230110 8403230119	84/03/16 84/02/29	50-219 50-219	R
8403220023	8403220021 8403220018	84/03/20 84/03/19	50-155 50-204	F	8403230123	8403230119	84/02/29		R
8403220027	6403220018	84/03/17	50~206	F	8403230126 8403230128	8403230088 8403230125	84/03/20 83/05/24		Q B
8403220032 8403220041	8403220028 8403220033	84/03/16 84/03/15	50-338 50-387	P G	8403230130	8403230129	84/03/01	CONTRACT	
8403220042	8403220031	84/03/19	50-278	a	840323013B 8403230141	8403230137 8403230137	84/03/19 84/02/28		G R
8403220044 8403220054	8403220038 8403220045	84/03/20 84/02/27	50-349 40-4492	P	8403230150	8403230148	83/10/07		8
8403220060	8403220050 8403220054	84/03/19	50~315	a	8403230154 8403230157	8403230152 8403230156	84/03/12 84/02/27	CONTRACT 40-8745	
8403220062 8403220071	8403220068	84/03/07 84/02/28	50-309 40-8584	a	8403230160 8403230164	8403230159 8403230162	84/03/07 84/03/12	CONTRACT 100FR	
8403220081 8403220085	8403220079 8403220083	84/03/15 84/03/12	50-333 50-277	G G	8403230175	8403230171	83/05/24	50-317	8
8403220087	8403220083	84/03/12	50-277	G	9493239181 8493239244	840323017B 8403230241	83/05/11 84/03/09	50-305 70-1359	8
8403220087 8403220091	8403220086 8403220083	84/03/04 84/03/12	50-354 50-277	O O	8403230246 8403260022	8403230241 8403260018	84/03/09 84/03/05	70-1359	A
8403220092 8403220097	8403220090 8403220094	84/03/09 84/03/07	40-472 50-454	a	8403260023	8403250019	84/03/16		 a
8403220098	8403220095	84/03/07	50-309	Q	8403260026 8403260030	9003260017 8403260027	84/03/21 84/03/05	SO-34B XPORTLIC	8
8403220077 8403220103	8403220073 8403220075	84/03/19 84/03/07	50-266 50-309	a a	8403260032 8403260040	8403260017 8403260017	84/03/21 84/03/21	50-348	9 8
8403220110	8403220104	B4/03/20	50-275	0	8403260042	8403260037	84/02/23	XPORTLIC	_
8403220111 8403220114	8403220107 8403220107	84/03/05 84/03/05	50-341 50-341	G G	8403260046 8403260048	8403260017 8403260045	84/03/21	50-346	8
8403220115 8403220124	8403220105 8403220117	84/03/06 84/02/28	50-272 40-8584	a	84032A0041 84032A0048	8403260057 8403260060	84/03/06 84/03/05 84/01/12		r A Q
8403220125 8403220127	8403220121	84/03/20	50-206	Ę	B4032 60075	8403260072	84/03/19		8
8403220127 8403220135	8403220123 8403220128	84/03/15 84/03/13	50-373 50-387	fa	8403260077 8403260080	8403260071 8403260073	84/03/05	50-344	P
8403220137 8403220140	8403220131 8403220134	84/03/08 84/03/08	50-412 50-305	Q. Q.	84032,60081 84032,60083	8403260069	84/03/20 84/02/28	50~445	A G
8403220155	8403220152	84/03/13	50-219	P	8403250084	84032 <u>6</u> 0071 84032 <u>6</u> 0082	84/03/05		P
8403220158 8403220160	6403220153 8403220143	84/03/15 84/03/06	50-237 50-322	P G	B4032600B7	840326007日	84/03/09 64/02/27		9
8403220165 8403220167	8403220161 8403220162	84/03/07 84/03/16	50~295 50~246	a P	9403250098 8403250099	8403260071 8403260090	B4/03/05 B4/03/05		p De
6403220173	8403220170	84/03/15	40-8824	•	8403260107	8403260100	84/02/14		3
8403220187	8403220183	84/02/27	40~8498	_	8403260109 8403260110	8403260102 8403260105	84/02/22 84/03/22	40~1341 50-280 f	.
8403220199 8403220212	8403220172 8403220208	84/03/19 84/03/06	50~309 50~338	P P	8403260111	8403260106	84/03/09	50-275 (J
8403220213	8403220208	84/03/04	50~338	P	8403260117	8403260104 8403260113	84/03/15 84/03/20		3
8403220217 8403220224	8403220214 8403220220	84/03/12 84/01/15	CONTRACT		8403260129	B403260123	84/03/02	40-1478	
8403220227 8403220234	8403220226 8403220226	84/03/19 84/03/19	50-352 50-352	a a	84032&D13& 84032&0137	8403260123 8403260034	84/03/02 84/03/15	40~147B 50~413 /	۹
Ø403220257	8403220254	84/03/01	50-266	þ	8403240141 8403240142	8403260123 8403260138	84/03/02 84/01/18	40-1478 40-8102	
								VE	

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION					ACCESSIO				
	PRINCIPAL	DATE	SUBJECT			PRINCIPAL	DATE	SUBJECT	
ENCLOSURE	DOCUMENT	ISSUED	CATEGOR		ENCLOSURE	DOCUMENT	186VED		
8403260148 8403260151	8403260123 8403260143	84/03/02 84/02/29	40-1478 50-213	F	8403270252 8403270253	8403270246 8403270249	84/03/22 84/03/19	50~454 50~265	Q G
8403240153	8403260123	84/03/02	40~1478		8403270255 8403270260	840327024 <i>6</i> 840327024 <i>6</i>	84/03/22 84/03/22	50-454 50-454	G G
8403260157 8403260158	8403260051 8403260123	84/03/16 84/03/02	50-313 40-1478	P	8403270263	8403270246	84/03/22	50-454	Ğ
8403260167	8403260161	84/02/03	50~267	œ.	8403270284	B403270282	B4/03/07	CONTRACT	
8403260172	8403260168	84/01/19	50-285	æ	8403270290 8403270306	8403270284 8403270302	84/03/07 84/03/07	CONTRACT	
8403260173 8403260177	8403260166 8403260174	84/03/12 84/03/08	50-334 50-267	Q Q	8403270338	8403270333	84/03/23	50-400	0
8403260183	8403260179	84/03/22	70-27		8403270350	0302020107	83/01/19	50-255	8
8403260201	8403260198	84/03/19	50-244 50-267	P G	8403270362 840327036B	8403270360 8403270365	84/03/09 84/03/08	CONTRACT	
8403260209 8403260211	8403260205 8403260205	84/03/05 84/03/05	50-267	a	8403280014	8403280009	84/02/21	50-416 50-416	P P
8403260214 8403260220	8403260206 8403260217	84/02/03 84/02/06	50-445 50-458	G G	8403280018 8403280023	84032&0009 84032&0009	84/02/21 84/02/21	50-416	P
			50-313	a	8403280044	8403280037	84/03/23	50-349	P
8403260232 8403260234	8403260230 8403260227	84/03/08 84/03/22	50-346	P	8403280052	8403280049 8403280045	84/03/06 84/03/12	CONTRACT 50-341	н
8403260237 8403260238	8403240228 8403240235	84/03/21 84/02/17	50-454 50-298	Q Q	8403280054 8403280055	8403280050	84/03/13	XPORTLIC	
8403260240	8403260235	84/02/17	50~278	G	8403280068	8403280045	B4/03/06	50-83	P
B403260248	8403260236	84/02/27	50-317	P	B402280071	8403280045 8304270367	84/03/06 83/04/13	50-83 50-366	P B
8403260250 8403260253	8403260245 8403260249	84/02/14 84/03/22	50-352 50-362	Œ	8403290079 8403280081	8403280080	B4/01/17	FOIA	_
8403260265	8403260261	84/02/21	50-321	F	8403260101 8403280103	8403280070 8403280077	84/03/12 83/11/21	50-295 40-8586	P
8403260281	8403260273	84/03/06	50-338		8403280106	8403280090	84/03/12	50-275	Р
B403260304 B403260307	8403260302 8403260276	84/03/05 84/03/08	50-344 CONTRACT	F	8403280108	8403280070	84/03/12	50-295	P
8403260308	8403260302	84/03/05	50-344	F	8403280121 8403280151	8305160260 8403280147	83/05/05 84/03/08	50-291 XPDRTLIC	8
8403260317 8403260322	8403260313 8403260316	84/03/20 84/03/01	50-293 CDNTRACT	·	8403280156	8403280149	B4/03/07	50~250	Н
8403260329	8403260326	84/03/08	50-34B	P	8403280197	8403280153	84/03/0B	COMM18810	
8403260336	8403260331	84/03/09	71-5450	•	8403280160 8403280170	8403280153 8403280167	84/03/08 84/02/22	50~289 FOIA	Т
8403260341 8403260342	8403260323 8403260338	84/03/06 84/03/21	CONTRACT 50-322	T	8403280174	8403280167	84/02/22 84/02/22	FOIA FOIA	
8403260347	8403260344	84/02/27	WARTE MG	T	8403280177	8403280167			
8403260350 6403260353	8403260344	84/02/27 84/02/27	WASTE MG		8403280182 8403280185	8403280167 8403280167	84/02/22 84/02/22	FOIA FOIA	
B403260354	8403260344 8403260348	84/03/23	50-400	Ġ	8403280187 840328018B	8403280186 8403280167	84/03/07 84/02/22	CONTRACT FOIA	
8403260356 8403260369	8403260352 8403260368	84/03/09 84/03/22	CONTRACT 50-275	Ģ	8403280171	8403280167	B4/02/22	FOIA	
B403260370	8403260363	84/03/08	CONTRACT		8403280197	8403280167	84/02/22	FOIA	
E403260379	8403260377	84/03/22	50-322	Ţ	8403280218 8403280225	8403280214 8403280216	84/03/14 84/03/07	71-9036 50-482	œ.
8403260414 8403270015	8403260411 8403270010	83/03/23 84/03/20	50-325 50-293	S P	8403280229	8403280216	B4/03/07 B4/03/07	50-482 50-482	G G
8403270022	8403270010	84/03/20	50-293	P	8403280235	8403280216			_
8403270024	8403270010	84/03/20	50~293	P	8403280240 8403280263	8403280216 8403280260	84/03/07 84/03/09	50-482 CONTRACT	a
8403270032 8403270038	8403270030 8403270030	84/03/16 84/03/16	50-305 50-305	P	B403280273	6403260270 8403260270	84/03/07 84/03/07	MISC MISC	
8403270048 8403270054	8403270042 8403270050	84/03/21 84/03/21	50-352 GA999	T	8403280278 8403280282	64032B0270	84/03/07	MISC	
B403270057	8403270053	84/03/21	50-275	р	9403280298	B4032B0270	84/03/07	MISC	
8403270047	8403270064	84/03/08	50-277	P	8403280294 8403280295	8403280270 8403280270	84/03/07 84/03/07	MISC MISC	
B403270069 B403270076	8403270065 8403270070	84/03/19 84/03/23	50-352 50-458	Q Q	8403280301	8403280270	84/03/07	HIBC	_
8403270094	8403270086	84/03/22	40-8760		8403290004	8403270002	84/01/13	50-247	P
8403270097	B403270092	84/03/21	QA999		8403270006 8403270007	8403270002 8403270002	84/01/13 84/01/13	FOIA FOIA	
8403270113 8403270122	8403270106 8403270119	84/03/22 84/03/1 5	50-155 50-322	P R	8403270009 8403270010	6403270002 6403270002	84/01/13 84/01/13	FOIA FOIA	
8403270127 8403270129	8403270123 8403270123	84/03/22 84/03/22	50-320 50-320	P P	8403270010 8403270011	8403270002 8403270002	84/01/13	FOIA	
8403270136	8403270130	84/03/19	50-249	P	8403270012	8403270002	84/01/13	FOIA	
8403270139	8403270135	84/03/19 84/03/22	50-528	a	4100925048 4100925048	8403270002 8403270002	84/01/13 84/01/13	FOIA FOIA	
8403270143 8403270144	8403270055 8403270130	84/03/20 84/03/17	50-293 50-249	P P	8403270018	8403270002	84/01/13	FOIA	
8403270157	8403270132	84/03/23	50-322	s	8403270020	8403270002	84/01/13	FOIA	
8403270180	8403270177	84/03/09	50-461 50-200	a	8403270021 8403270022	8403270002 8403270002	84/01/13 84/01/13	FOIA FOIA	
8403270181 8403270184	8403270170 8403270178	84/03/23 84/03/07	50-282 QA999	a	8403270023 8403270024	8403270002	84/01/13 84/01/13	FOIA FOIA	
8403270188 8403270191	8403270183 8403270189	84/03/22 84/03/14	50-395 50-267	P	8403240052	8403270002 8403270002	B4/01/13	FOIA	
B403270194	8403270189	B4/03/14	50-267	P	8403290027	8403270017	B4/02/29	50-348	Q
8403270212	8403270210	84/03/22	50-320	þ	8403270028 8403270031	8403270002 8403270002	84/01/13 84/01/13	FOIA FOIA	
B403270217 B403270221	6403270214 6403270214	84/01/16 84/01/16	70-1257 70-1257		8403290034	8403270002	84/01/13	FDIA FDIA	
B403270225	8403270223	64/03/22	50-395	P	8403270035	8403270002	B4/01/13		
B403270234	8403270228	84/03/02	GA999		8403290035 8403290040	8403270002 8403270002	84/01/13 84/01/13	FOIA FOIA	
B403270238 B403270239	8403270233 8403270235	84/03/09 84/03/21	50-409 50-241	Q P	8403270041	8403270002	84/01/13	FOIA FOIA	
B403270241 B403270242	8403270228 8403270233	84/03/02 84/03/09	GA797 50-409	a	8403290044 8403290045	8403270002 8403270002	84/01/13 84/01/13	50-266	P
- Tone LATA	_ ,	_ ,, ,		-					

CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSIC							NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	CATEGO!	RY	ENCLOSU		PRINCIPAL DOCUMENT	DATE ISBUED	SUBJECT CATEGOR	Y
8403270046 8403270048 8403270047	8403270002 8403270002 8403270002	84/01/13 84/01/13 84/01/13	FOIA FOIA 50-266	 p	8403290 8403290 8403290	220 234	8403290178 8403290231 8403290237	84/03/20 84/02/27 84/03/05	50~259 50~302 50~259	9
8403290050 8403290051	8403270042 8403270002	84/03/06 84/01/13	50-390 FDIA	a	84 032 90 84 032 90	246 240	8403270250 8403270262	84/03/14 84/03/01	50~338 50~302	0
8403270052 8403270054 8403270055 8403270057	8403270002 8403270002 8403270002 8403270053	84/01/13 84/01/13 84/01/13 84/03/13	FOIA FOIA FOIA 50-334	Q	84 03290 84 03290 84 03290 84 03290)273)276	8403270250 8403270267 8403270270 8403270267	84/03/15 84/03/23 84/03/15 84/03/23	50-338 50-369 50-413 50-369	9 9 9
8403270059 8403270059	8403290002 B403290002	84/01/13 84/01/13	FOIA	u	8403290 8403290	280	8403290250 8403290267	84/03/16 84/03/23	50-338 50-369	Q P
8403290061 8403290062 8403290063	8403290002 8403290053 8403290002	84/01/13 84/03/13 84/01/13	F01A 50-334 F01A	Q.	8403270 8403270 8403270	297 290	8403270283 8403270275 8403270250	84/03/21 84/03/01 84/03/16	50~409 50~349 50~338	P G
8403290066	8403290002 8403290043	84/01/13 84/03/15	F01A 70-398		8403290 8403290	272	8403270284 8403270287	84/03/13 84/03/05	50-29 50-338	o o
8403270068 8403270070 8403270071	8403290002 8403290002 8403290064	84/01/13 84/01/13 84/03/13	FOIA FOIA 50-271	a	8403290 8403290 8403290	304 305	8403270277 8403270302 8403270302	84/03/27 84/03/16 84/03/16	50-250 50-354 50-354	Q A
8403290073 8403290075	8403290002 8403290002	84/01/13	FOIA	•	8403290 8403290	320	8403270317 8403270338	84/02/29 84/03/05	50-335 FOIA	A G
8403270062 8403270084	8403290049 8403290078	84/03/20 84/03/14	50-249 50-348	G G	8403270 8403270	343 344	8403270338 8403270338	84/03/05 84/03/05	FOIA 50-528	D
8403270097 8403270070	8403290078 8403290049	84/03/14 84/03/20	50-348 50-269	a a	8403290 8403290	397	6403270385 6403270395	84/03/27 84/03/25	40-2061 50-352	Q
8403270072 8403270075 8403270076	8403270086 8403270067 8403270078	84/03/07 84/03/20 84/03/14	50-32 4 50-259 50-348	() ()	8403290 8403290 8403300	405	8403270377 8403270404 8403300007	84/03/28 84/03/08 84/03/27	50-352 XPORTLIC 50-352	G T
8403270078 8403270102	8403270073 8403270073	84/03/23 84/03/23	50-461 50-461	I	8403300 8403300	015	8403300011 8403300017	84/03/26 84/03/13	70-27 50-454	q
8403290103 8403290104 8403290107	8403270078 8403270097 8403270093	84/03/14 84/03/13	50-348 50-219 50-461	0 0 1	8403300 8403300	033	8403300017 8403300026	84/03/13 84/03/16	50-454 50-456 50-282	G G
8403270109 8403270113	8403290069 8403290110	84/03/23 84/03/20 84/03/14	50-269 ACRS	ò	8403300 8403300 8403300	044	8403300036 8403300041 8403300042	84/03/15 84/02/15 84/03/14	70-27 50-315	Q Q
8403290114 8403290119	8403270107 8403270116	84/03/19 84/03/13	50-335 50-387 50-387	a	8403300 8403300	050	8403300048 8403300046	84/03/28 84/01/31	50-382 50-313	F G
8403270120 8403270124 8403270126	8403270116 8403270107 8403270109	84/03/13 84/03/19 84/03/19	50-335 50-335	0 0	B403300 B403300 B403300	057	8403300042 8403300053 8403300063	84/03/14 84/03/15 84/03/21	50-315 50-341 50-397	G G
8403890132 8403290139 8403290142	8403270107 8403270135 8403270140	84/03/19 84/03/22 84/03/14	50~335 50~272 50~367	Q	8403300 8403300 8403300	076	8403300065 8403300072 8403300086	84/03/23 84/03/16 84/03/23	50-271 50-322 50-245	0 0
8403290146 8403290147	8403290145 8403290143	84/03/19 84/02/28	50-412 50-413	Ċ	8403300 8403300	1073	8403300089 8403300098	84/03/20 84/03/16	50-409 50-354	e e
8403290147 8403290150 8403290154	8403290140 8403290144 8403290148	84/03/14 84/03/13 84/03/16	50-387 50-352 50-369	о О Р	8403300 8403300 8403300	0116	8403300111 8403300107 8403300107	84/03/24 84/03/28 84/03/28	50-302 50-413 50-413	8 A A
8403290155 8403290156	8403290140 8403290151	84/03/14 84/03/05	50-367 50-416	a Q	8403300 8403300	135	8403300125 8403300133	84/03/15 84/03/07	50-498 50-259	A
8403290162 8403290164 8403290165	8403290159 8403290148 8403290160	84/03/22 84/03/16 83/12/21	50-302 50-369 50-322	የ	8403300 8403300 8403300	1140	8403300133 8403300137 8403300142	84/03/09 84/03/27 84/03/23	50~259 70-697 50~271	R G
8403290166 8403290169	8403290163 8403290163	84/03/20 84/03/20	50-400 50-400	G G	8403300 8403300	155	8403300149 8403300149	84/03/22 84/03/22	50-346 50-346	P
8403270171 8403270173 8403270180	8403290163 8403290163 8403290174	84/03/20 84/03/20 84/03/02	50~400 50~400 50~335	0 0	840330£ 840330£ 840330£	169	8403300161 8403300165 8403300171	84/03/23 84/03/24 84/03/23	50-213 50-223 50-272	G G
8403270183 8403270188	840329017B 8403290185	84/03/20 84/03/25	50~25 <i>9</i> 50~244	G P	840330C 840330C	183	8403300171 8403300173	84/03/23 84/03/15	50-272 50-250	Q R
8403270187 8403270170 8403270171	8403270185 8403270178 8403270186	84/03/26 84/03/20 84/03/13	50~244 50~257 50~289	Р О	8403300 8403300 8403300	190	8403300180 8403300180 8403300189	94/03/23 94/03/23 84/03/23	50~311 50~311 50~244	G G
8403270174 8403270175	8403270193 84 0 3270193	84/03/15 84/03/15	50~364 50~364	0	8403300 8403300	193	8403300173 8403300224	84/03/15 84/03/15	50~250 71-9134	R
8403290196 8403290197 8403290199	8403290193 8403290193 8403290198	84/03/15 84/03/15 84/03/06	50~366 50~366 50~400	Q Q	8403300 8403300 8403300	274	8403300235 8403300271 84033002 7 3	84/03/13 84/03/27 84/03/15	TOPREP 50-352 70-1257	ø
8403270203 8403270204	8403270178 8403270200	84/03/20 84/03/22	50-259 50-412	ā	8403300 8403300	302	840330029B 8403300309	84/03/19 84/03/20	71-9027 CONTRACT	
8403270205 8403270207 8403270207	8403270202 8403270178 8403270201	84/03/15 84/03/20 84/03/01	50-320 50-259 50-390	G G	B40330C	327	8403300324	84/03/13	50-261	Œ
8403270210 8403270211	8403290206 8403290178	84/03/15 84/03/20	50-272 50-259	G G						
8403290212 8403290214 8403290215	8403270208 8403270178 8403270208	84/03/19 84/03/20 84/03/19	50-321 50-259 50-321	Q Q						
8403290216 8403290217	840327020B 840327020B	84/03/19 84/03/19	50-321 50-321	G G						

APPENDIX A

DEFINITIONS OF DOCKET 50 CATEGORIES

A. APPLICATION/CONSTRUCTION STAGE DOCUMENTS AND CORRESPONDENCE

This category follows the application from submission to the day preceding the issuance of an operating license. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are

- 1 Application for construction permit.
- 2. General Information submitted with construction permit application.
- 3 Amendments and changes to items 1 and 2.
- 4. NRC questions, requests for additional information, and applicant responses.
- 5 Correspondence and documents relating to unresolved design and construction issues.
- 6. Meeting announcements and summaries of meeting discussions on issues of item 5.
- 7. Correspondence regarding the Preliminary Safety Analysis Report (PSAR).
- 8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
- 9. Construction Permit, amendments, and correspondence relating to the construction permit.
- 10. Scheduling of license application submission or review,
- 11. Environmental review information.
- 12. Application for operating license.
- 13. General Information submitted with operating license application.
- 14. Amendments and changes to items 12 and 13.
- 15. Correspondence regarding the Final Safety Analysis Report (FSAR)
- 16. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility, not covered by an IE Bulletin.
- 17. Reports of site visits
- 18. Backup technical documents (e.g., topical reports) submitted in support of the application.

B UTILITY PRELIMINARY SAFETY ANALYSIS REPORT (PSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence is filed in Category A.

- 1. Preliminary Safety Analysis Report (PSAR) submitted by utility (formerly called Hazards Summary Report or Safety Analysis Report).
- 2. Amendments and changes to the PSAR.

- 3 Transmittal and acknowledgement letters
- 4 Certificates of service to the PSAR

C. UTILITY ENVIRONMENTAL REPORT (ER), AMENDMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are filed in Categories A, D, M, P or R

- 1. Environmental Report (ER) submitted by the utility
- 2 Amendments and supplements to the ER
- 3 Transmittal and acknowledgement letters
- 4 Information on scheduling of submittal or review of ER
- 5 NRC questions, requests for additional information, and applicant responses.
- 6 Federal register notices citing the availability of items 1 and 2.
- 7. Correspondence relating to the review of ER
- 8 Meeting announcements or reports of meetings where the primary subject of discussion is the ER

D. NRC DRAFT AND FINAL ENVIRONMENTAL (IMPACT) STATEMENTS (DES AND FES), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are in categories A, C, M, P or R

- I Draft and Final Environmental (Impact) Statements (DES and FES) prepared by the NRC.
- 2 Supplements to the DES and FES.
- 3. Correspondence relating to the DES and FES.
- 4 Comments from other federal, state and local government agencies.
- 5. Transmittal and acknowledgement letters
- Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements.
- 7. Backup technical documents submitted in connection with above.
- 8. Federal register notice citing availability of items 1 and 2.
- 9 Site visits to obtain information for DES or FES
- 10. Meeting announcements or reports of meetings where the primary subject of discussion is the DES or FES

E. NRC SAFETY EVALUATION REPORT (SER), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other documents dealing with safety related issues are filed in categories A, P or W, depending on the phase of the licensing process.

- Safety Evaluation Report (SER) prepared by the NRC (formerly called NRC-AEC Hazard Analysis Report)
- 2 Supplements to SER
- 3 Correspondence relating to SER
- 4 Federal register notices citing availability of items 1 and 2
- 5 Information on scheduling of SER submittals and review
- 6 Requests for additional information for use in preparing SER, responses to such requests
- 7. Meeting announcements or reports of meetings where the primary subject of discussion is the SER.
- 8 Transmittal and acknowledgement letters

F. SECURITY, MEDICAL, EMERGENCY AND FIRE PROTECTION PLANS

All plans in this category are individual submissions. Information submitted as part of the PSAR or FSAR is excluded

- 1. Fire Hazard Protection Plan and surveys.
- 2 Plant evacuation correspondence.
- 3 Safeguards Contingency Plans
- 4 Review of Health Physics Program.
- 5 Correspondence relating to aforementioned plans
- 6 Supplements, changes and revisions to plans.

G. LEGAL AND ADJUDICATORY CORRESPONDENCE

This category contains all non-antitrust legal and adjudicatory documentation, except for transcripts, briefings and testimony, which are filed in category T.

- Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) hearing related documents.
- 2. Federal register notices regarding hearings.
- 3 Requests to make appearances at hearings
- 4. Motions, briefs, arguments, statements and related correspondence filed by participants for hearings.
- 5 Transmittal of supporting documents (e.g., SER, FES) to the boards.
- 6. Correspondence to and from intervenors
- 7 Board orders and decisions.
- 8 Petitions for Commission action.
- 9 Legal filings and Commission orders and decisions resulting from item 8.

H GENERAL CORRESPONDENCE

This category includes documents with little or no bearing on the status of the application or license ftems that have no substantive technical content or meaning for the status of the license or application are included

- 1 Change of address notifications
- 2. Changes in structure of organization
- 3 Changes in service lists.
- 4 NRC requests to applicant for additional copies of documents.
- 5 Correspondence from the public requesting information about the facility and NRC responses.
- 6 Correspondence on strictly administrative matters.
- 7 Letters of support, concern or opposition to the facility
- 8 Correspondence regarding the Local Public Document Rooms (LPDRs)
- 9 Professional qualification statements not pertaining to the hearing process.

I. FINANCIAL INFORMATION

This category contains all financial information except that submitted as part of the application or its amendments or relating to the imposition of civil penalties

- 1 Company annual reports
- 2 Separately submitted financial information and related correspondence

J. INSURANCE AND INDEMNITY INFORMATION

- I. Indemnity agreements and amendments
- 2 Endorsements insurance policies.
- 3. Other correspondence regarding indemnity and insurance matters.

K. UTILITY FINAL SAFETY ANALYSIS REPORT (FSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence falls in category A or P

- 1 Final Safety Analysis Report (FSAR) (formerly called Final Hazards Summary Report)
- 2. Amendments and changes to the FSAR.
- 3. Federal register notices citing availability of items 1 and 2.
- 4. Transmittal and acknowledgement letters.
- 5. Certificates of service to the FSAR.

L. LIMITED WORK AUTHORIZATION (LWA) AND RELATED CORRESPONDENCE

This category is limited to documents pertaining to Limited Work Authorizations (LWA) whereby applicants can carry out limited site preparation and construction prior to the granting of a construction permit

- Limited Work Authorizations (LWA) and amendments
- 2 Correspondence pertaining to work performed under LWA's

M. ANTITRUST REVIEW AND ANTITRUST CORRESPONDENCE

- Document submitted as part of the applications for a construction permit and operating license entitled "Information Requested by the Attorney General for Antitrust Review"
- 2 Correspondence where the primary topic of discussion is antitrust matters
- 3 All antitrust proceeding related documents except for hearing transcripts, testimony and briefings, which are filed in category N

N. ANTITRUST HEARING TRANSCRIPTS, TESTIMONY AND BRIEFINGS

This category contains word-for-word transcripts of hearings, testimony and briefings in antitrust matters. Related correspondence falls in category M

O. ADVISORY COMMITTEE ON REACTOR SAFEGUARDS (ACRS) REPORTS AND CORRESPONDENCE

- 1. Correspondence and letter reports relating to Advisory Committee on Reactor Safeguards (ACRS) reviews.
- 2. Correspondence from ACRS
- 3 Announcement of ACRS meetings
- 4 Transmittal and acknowledgement letters.
- 5. ACRS reports.
- 6. Statements and written testimony by ACRS members or presented by individuals at ACRS proceedings.
- 7. Minutes at ACRS Subcommittee Meetings

P OPERATING LICENSE STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Application/Construction Stage (category A) file for general technical items dated from the issuance of the operating license to the application for termination of the license.

- 1. Operating license, amendments, proposed amendments, changes and related correspondence
- Technical specifications and changes.

- 3 Backup technical documents (e.g., topical reports) submitted in support of items 1 and 2.
- 4. Federal register notices citing availability of items 1 and 2
- 5 Correspondence regarding the Final Safety Analysis Report (FSAR)
- 6. All general technical correspondence, meeting announcements or meeting summaries relating to technical specifications, the operating license or technical issues arising after the issuance of the operating license
- 7 Correspondence regarding codes (e.g., ASME), regulations, laws or changes in policy that may affect plant operation or bear on the operating license
- 8. Information on the Standard Review Plan (STP)
- 9 Results of surveys or tests conducted in accordance with the technical specifications (not periodic reports, which fall in category R).
- 10. Correspondence relating to NRC's Systematic Evaluation Program (SEP)
- 11. Owner's group meeting announcements and reports.
- 12 Quality assurance information.
- 13 Environmental matters (technical).
- 14. Emergency core cooling system documents
- 15. Radioactive waste information.
- 16. Correspondence regarding expansion of spent fuel storage pool
- 17. Start-up test reports.
- 18. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 19. Reports of site visits

Q. INSPECTION REPORTS; IE BULLETINS, CIRCULARS AND INFORMATION NOTICES; CIVIL PENALTIES AND RELATED CORRESPONDENCE

- 1 Inspection reports.
- 2. IE Bulletins (formerly called Regulatory Operations (RO) Bulletins), Circulars and Information Notices.
- 3. Responses by applicant to IE correspondence
- 4. Applicant's determination of proprietary nature of inspection reports.
- 5. Letters concerning areas of noncompliance.
- 6. Pre-service and in-service inspections and procedures.
- 7 Correspondence and orders relating to imposition and payment of civil penalties, including Notification of Significant Enforcement Actions (ENs)
- 8 Any correspondence relating to inspection and enforcements that does not specifically relate to incidents or events as defined in category S.

R PERIODIC OPERATING REPORTS AND RELATED CORRESPONDENCE

This category includes periodic reports of a routine nature

- Monthly, semiannual, or annual operating reports (other than financial)
- 2 Periodic environmental monitoring, effluent testing, or similar reports
- 3 Periodic personnel exposure reports.
- 4 Operational Logbooks

Logbooks on Environmental Data Logbooks on Radiological Data Operations Log on Plant Systems Core Plant Status Summary Sheets

5 Correspondence or other documents relating to the above listed items.

S. REPORTABLE OCCURRENCES, PNOS, PNSs AND RELATED CORRESPONDENCE

This category contains all materials relating to abnormal, unusual, reportable or nonroutine occurrences or events. This includes

- All 24-hour, 10-day, 30-day, interim and final Licensee Event Reports (LER's) and follow-up correspondence (also called incident reports, abnormal occurrence reports and reportable occurrences)
- 2 Potential or possible reportable deficiency reports and related correspondence
- 3 Personnel exposure reports.
- 4 Construction deficiency reports submitted under 10 CFR 50.55e
- 5 Preliminary Notification of Occurrence (PNOs) and Preliminary Notification of Safeguards Events (PNs)
- 6. Environmental Technical Specifications violation reports and Environmental Event reports
- 7 Part 21 Reports of defects and noncomphance
- 8. Correspondence or other documents relating to items 1-7

T. TRANSCRIPTS, TESTIMONY AND BRIEFINGS ON NON-ANTITRUST MATTERS

This category contains all word-for-word transcripts, except for antitrust matters (category N), testimony and briefings, and congressional matters (category U),

- Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) transcripts
- 2. Testimony and statements submitted to ASLB and ASLAB
- 3 Commission meeting transcripts.
- 4. NRC staff briefings to the Commission
- 5. Statements and written testimony submitted at Commission meeting or hearings.
- 6 Transcripts of utility briefs to NRC staff.
- 7 Advisory Committee on Reactor Safeguards (ACRS) meeting transcripts
- 8. Corrections to above items

U CONGRESSIONAL/EXECUTIVE CORRESPONDENCE

This category contains correspondence on substantive matters. Routine responses to constituent inquiries are filed in category H

- Statements and testimony before Congress or before bodies/committees appointed by the Executive or Legislative Branches
- 2 Preparatory and backup documents for item 1
- 3 Correspondence to and from NRC Office of Congressional Affairs Congress and the Executive Branch on other than constituent response matters

V. LICENSING OPERATORS AND RELATED CORRESPONDENCE

- 1 Operator licenses or administrative information bearing on licensing of operators
- 2. NRC examination results
- 3. Power plant examination summary sheet

W. DECOMMISSIONING STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Operating License Stage (category P) file for general technical items from the application for termination of the operating license onward

- 1. Application for authority to voluntarily surrender license
- 2. Application to dismantle the facility and dispose of component parts.
- 3 Technical documents submitted in support of items 1 and 2, such as: Decommissioning Plan Dismantling Plan, Environmental Report on Dismantling Safety Analysis Report on Decommissioning
- 4. Documents relating to disposal of radioactive material and decontamination of the site.
- 5. Other correspondence relating to above items
- 6 All documentation relating to the ongoing operation of the plan, formerly filed in category P.

X. ONSITE LOW-LEVEL WASTES STORAGE

This category contains items related to the onsite storage of low-level radioactive wastes generated onsite.

Y. INDEPENDENT SPENT FUEL STORAGE INSTALLATIONS (ISFSI)

This category contains documents with an NMSS license and/or a Docket-72 number. For installations on a reactor site, the associated Docket-50 number will also be identified.

- 1. License applications, licenses, amendments and proposed amendments to possess power reactor spent fuel and other radioactive materials associated with spent storage in an independent spent fuel storage installation. (Such spent fuel storage installations may be on a reactor site or at a separate site.)
- All related correspondence and reports to the above.

APPENDIX B

DEFINITIONS OF NONDOCKETED CATEGORIES

10CFR - Commission Meeting Records

This category contains documentation pertaining to open and closed Commission meetings. It includes

- 1 Sunshme Act Federal Register notices
- 2 Full written explanation of closed meetings
- 3. Certification of General Counsel on closed meetings
- 4 Commission Determination Statements regarding the public disclosure of transcripts of Commission meetings
- 5 Verbatim unofficial and official transcripts or portions of transcripts of open and closed Commission meetings made publicly available in accordance with provisions of 10CFR Part 9 the Sunshine Act, and Commission policies.
- Enclosures to released transcripts, including applicable viewgraphs, staff papers, and staff correspondence
- Staff requirements memoranda for open meetings, memoranda to record, record of votes of Commissioners on items under consideration at meetings

ACRS - Advisory Committee on Reactor Safeguards

This category contains documentation pertaining to the responsibilities of the Advisory Committee on Reactor Safeguards. ACRS serves as an independent advisory committee to the Commission in safety-related areas. The committee provides advice with respect to the hazards of new or existing nuclear facilities and the adequacy of related safety standards. The documents in this category are

- 1. Verbatim transcripts of ACRS subcommittee and full committee meetings relating to facility license applications and safety-related matters
- 2. ACRS meeting announcements description of meeting agendas.
- 3 ACRS-generated reports, memoranda and correspondence that are publicly available
- 4. ACRS consultant reports, comments and related correspondence
- ACRS and NRC technical correspondence pertaining to safety matters under review by the Advisory Committee on Reactor Safeguards.

ADVCM - NRC Advisory Committees

This category contains documentation pertaining to the responsibilities of all NRC advisory committees, other than the Advisory Committee on Reactor Safeguards. The documents in this category are:

- 1. Charters of each advisory committee.
- 2. Verbatim transcripts of committee meetings.

- 3. Meeting announcements; description of meeting agendas.
- 4. Committee generated reports, memoranda, and correspondence that are publicly available.
- 5. Committee related correspondence.

COMMISSION - NRC Commissioners

This category contains documentation pertaining to the daily conduct of Commission business in the Office of the Commissioners, including

- 1. Incoming and outgoing correspondence to and from the Commissioners relating to official NRC business, including reports and other enclosures.
- 2. Travel vouchers, telephone logs and official appointment calendars of individual Commissioners.
- 3. Weekly Information Reports (SECY series number) prepared by the Executive Director for Operations (EDO) for the Commissioners, providing a summary of key events and items of interest undertaken by individual staff and program offices.

NOTE: For transcripts of Commission meetings, see 10CFR category. For all other staff papers with a SECY series designation prepared for Commission review, see SECY category.

CONTRACT - NRC Contracts and Modifications

This category contains documentation pertaining to ALC and NRC contracts and Interagency Agreements, including:

- 1. Notifications of issuance of request for proposal (RFP) and invitations for bid (IFB)
- 2. Solicitations (RFP or IFB) issued by the NRC.
- 3. Notifications of contract execution, specifying contract number, project title, contractor name, contract type, funding, and period of performance.
- 4. Contractual documents and contract modifications, if any,

DISCLOSURE - Financial Disclosure Information

This category contains financial disclosure information in accordance with the Ethics in Government Act of 1978.

FOIA - Freedom of Information Act Requests and Releases

This category contains requests for agency records and records released in accordance with the provisions of the Freedom of Information Act (FOIA). Documents in this category include:

- 1. Requests made by any member of the public (assigned an identifying number YY-NNN for last two digits of the year numerical sequence) for NRC records made in accordance with the provisions of the Freedom of Information Act.
- 2. Correspondence between the NRC and the requester relevant to the processing, appeal, denial or granting of an FOIA request.
- 3. Records or portions of records released in response to specific requests made under FOIA.

GEN TECH IS - Generic Technical Issues

This category contains records pertaining to unresolved safety issues of a generic nature that are being analyzed by the Division of Nuclear Reactor Regulation

- Dialit reports of action plans to accomplish generic tasks in the regulatory program.
- 2 Correspondence with industry and internal correspondence regarding the methodologies, analyses, and programmatic and technical aspects of issues
- 3 Meeting notifications and minutes.
- 4. Interim findings and status reports on generic tasks addressing related aspects of generic technical issues.

I&E - Inspection and Enforcement

This category contains bulletins, circulars and information notices that are issued by the Office of Inspection and Enforcement. These issuances describe particular events that occur at a facility that may require some follow-up action on the part of licensees. Also included in this category are preliminary notifications of events (PNOs).

- [4] I&I Circulars, which describe an event at a licensed facility and are info; mational in nature.
- 2 I&I Information Notices, which are similar to circulars but are preliminary in nature and issued shortly after an event has occurred.
- 3 I&I Bulletins, which describe an event at a licensed facility and request all recipients to perform certain actions as a result of this event
- 4 Preliminary Notifications of Events (PNOs), which provide updated information of an event of safety or public interest significance
- NOTE I or letters forwarding the above issuances, utility responses to such issuances, and related correspondence, see Category Q of individual docket categories

MISC - Public Document Room Miscellaneous

This category contains documents that do not fall into the scope of the other non-docketed categories

NUREG - NUREG Reports and Related Correspondence

These documents are formal reports issued by the U.S. Nuclear Regulatory Commission which carry the NURLG series code and correspondence pertaining to those reports. NURLG reports are accounts of work performed either by the NRC staff or by NRC contractors.

- These reports are normally final work products and are characterized by the following criteria
 - a They are predecisional documents which present information to be considered in Commission licensing and policy decisions
 - b. They present the results of Commission licensing and policy decisions
 - c. They present the results of technical research conducted for the Commission.
- 2. Correspondence from industry, government and interested members of the public commenting on reports or requesting clarification or interpretation.
- 3 Internal NRC memoranda summarizing meetings or discussions pertaining to the content of the reports

ORG - Correspondence with Other Organizations

This category contains correspondence with professional organizations and associations, records other than Regulatory Guides that pertain to the activities of NRC's Office of Standards Development, and emergency petitions not assigned Petition for Rulemaking (PRM) numbers that request the Commission to take immediate action on some issue. Included are

- 1. Meeting summaries and technical correspondence between NRC and professional associations and international bodies, such as the Atomic Industrial Forum and the International Atomic Energy Agency.
- Correspondence between NRC's Office of Standards Development and other government agencies in which both parties have joint regulatory responsibility, e.g., EPA has authority to control all radioactive pollutants emitted into the air
- 3. Internal memoranda, correspondence between NRC and Congress, and other technical correspondence dealing with the role and activities of the Office of Standards Development.
- 4. Statements, motions, orders and correspondence dealing with emergency petitions filed by parties on such topics as fire protection and re-analysis of the capacity of operating U.S. plants to withstand earthquakes.

NOTE: For Regulatory Guides and comments to Regulatory Guides issued by the NRC Office of Standards Development, see the REGGD category.

For petitions for rule makings filed by the public to amend, rescind or change an NRC regulation, see the PRM category.

PR - Proposed Rule

This category contains records dealing with NRC staff proposals to adopt, amend or repeal a Commission regulation. Proposed Rules (PRs) are normally the result of a Commission determination that sufficient grounds exist for it to proceed with a petition for change in an NRC regulation (PRM) filed by an outside party or person. The documents in this category are

- 1. Federal Register notices stating the terms or substance of the proposed rule or a specification of the subject and issues involved.
- 2. Text of the Proposed Rule (PR).
- 3. Comments, statements, information, opinions or arguments on the proposed change to a part of the Code of Federal Regulations, Title 10.
- 4. Requests from the nuclear industry, organizations and other parties for written interpretations of the PR.

PRM - Petition for Rulemaking

This category contains records dealing with petitions filed with the Commission by an outside party to issue, amend or rescind an NRC regulation. Included are:

- 1. Petitions filed by any interested person or party to issue, amend or rescind an NRC regulation.
- 2. Federal Register cause notices of the filing of the petition.

- 3 Correspondence between NRC and the petitioner regarding the status and substance of the petition
- 4. Comments from the nuclear industry, professional associations, public interest groups and others in favor of or in opposition to the PRM.

NOTE For staff recommendations to the Commissioners on whether the PRM should be denied or issued as a Proposed Rule, see the SECY category.

For Commission review of staff recommendations, see the 10CFR category.

PROJ - Projects-Predocket Licensing

This category contains records pertaining to two classes of projects: (1) commercial nuclear power plants for which NRC has full licensing responsibilities, and (2) government-owned reactors for which NRC provides technical expertise and occasional review. Both classes are identified with a "P" prefix, followed by a series of numbers.

1. "Pre-docketed" commercial nuclear power plants

This category contains all documentation up until the time that the NRC considers the application and the Preliminary Safety Analysis Report (PSAR) is submitted by the utility for staff review. The unit is then assigned a docket number, and transferred to the Docket 50 category.

These documents are grouped together in categories, designated by alphabetic characters. These are the same categories as those used for the Docket 50 series.

- A. Application/Construction Stage
 - 1. Application submitted by the utility.
 - 2. Meeting notices, summaries and correspondence discussing the completeness and adequacy of the PSAR.
 - 3. Applicant's Quality Assurance Manual.
 - 4. Early site review information.
 - 5. Backup technical documents submitted in support of the application.
 - 6. Early site visits.
- B. Utility PSAR and Amendments
 - 1. PSARs submitted by the utility.
 - 2. Amendments and changes to the PSAR.
 - 3. Transmittal letters,
 - 4. Letters acknowledging receipt of the PSAR.
- G. Adjudicatory Correspondence
 - 1. Motions, briefs, orders, et al. pertaining to pre-hearing conferences, if any.
- M Antitrust Correspondence
 - 1. Submittals and related material pertaining to the antitrust review.

O. Inspection Reports

- l Inspection reports of the applicant's quality assurance program.
- 2. Notices of deviations.
- 3. Follow-up correspondence resolving deviations cited.

2. Government-owned reactors

Meeting summaries and technical correspondence between NRC and other government technical personnel related to test reactors, critical experiments, and DOD reactors on navy ships and other sites.

PT21 - Noncompliance Reports and Related Correspondence

Deficiency reports are performed in compliance with Part 21 of Title 10 of the Code of Federal Regulations and include:

- 1. Reports by firms involved in the nuclear industry concerning noncompliance with NRC regulations or the existence of defects which could create a substantial safety hazard.
- 2. Correspondence pertaining to the NRC review of reports to assess the possibility of generic defects.
- 3. NRC inspection reports of defects cited
- 4. Correspondence specifying appropriate follow-up actions taken by the Agency.

QA999 - Quality Assurance Inspections

This category contains inspection reports of vendors' quality assurance programs and follow-up correspondence. Each vendor facility is assigned a docket number and is part of the QA999 series.

Vendors are defined here as companies, both U.S. and foreign, that are engaged in the design or the manufacture of nuclear components for plants licensed by NRC. QA comprises all those planned and systematic actions necessary to provide adequate confidence that a structure, system or component being manufactured will perform satisfactorily once it is put in service. The controlling criteria are 10 CFR Part 50, Appendix B, vendor QA topical reports, and the PSAR and FSAR submitted by utilities for specific facilities. Documents in this category include.

- NRC inspection reports, conducted on a quarterly or semi-annual basis, of vendor sites. Inspections may cover the design, fabrication, construction and testing of structural systems and components.
- 2. Notices of deviations.
- 3. Vendor corrective actions and other follow-up correspondence associated with the resolution of inspection findings.

REGGD - Regulatory Guides

This category contains new and revised regulatory guides issued by the Commission and related correspondence. These guides describe for the industry and the public methods acceptable to the NRC

staff for implementing specific parts of the NRC's regulations. They also delineate techniques used by the staff in evaluating specific problems or postulated accidents, or provide guidance to applicants. Included are

- 1. Federal Register notices announcing the issuance and availability of a proposed regulatory guide.
- 2. Revised or newly issued Regulatory Guides.
- 3. NRC value/impact assessment and industry codes, when applicable, that pertain to the issuance of a specific Regulatory Guide.
- 4. Comments submitted by the nuclear industry and interested members of the public regarding a proposed Regulatory Guide.
- 5 Summary of meetings held in the NRC to discuss proposed Regulatory Guides.

NOTE For documentation pertaining to other work products and activities of the NRC Office of Standards Development, see the Organization category.

RES - Research and Technical Assistance Reports

This category contains reports, generally of an interim nature, submitted by NRC contractors providing research and technical assistance to the Commission. It also includes documentation pertaining to research activities of the Commission. Included are

- 1. Project description documents.
- 2. Letter reports of accomplishments and data reports: for example,
 - a. model documentation reports
 - b. code documentation reports
 - c. code verification reports
- 3 Pre-test prediction reports.
- 4, "Quick look" reports.
- 5. Informal experimental data reports and post-irradiation examination analyses.
- 6. Conceptual design descriptions.
- 7. Letter reports of foreign travel and site visits by contractors.
- 8. Letter, monthly, quarterly, interim or annual status or progress reports on other research projects contracted for by the NRC.
- 9. Meeting summaries and correspondence dealing with technical matters relating to research and technical assistance contracts.
- 10. Staff Research Information Letters (RILs) transmitting the documented results from completed research programs.

NOTE: For final reports of research conducted by contractors, see also NUREG reports.

REVIEW GRP - NRC Research Review Groups

This category contains records pertaining to the activities of NRC Research Review Groups. Such groups provide a broad base of technical expertise to aid management in reviewing research in

defined technical areas. They review and comment on research plans and predicted results of major experiments, the validity and applicability of research results, the possible redirection of research projects, new research projects, and priorities within the technical areas covered by the research review group. Documents in this category are

- 1 Agendas for quarterly review group meetings.
- 2 Summary minutes of review group meetings representing views expressed, including dissenting views.
- 3 Research plans and predicted results of major experiments; presentations by research contractors
- 4 Comments on meetings from attendees, including representatives from contractors, universities, vendors and other agencies.
- 5. Internal memoranda relating to topics under discussion,

RM - Rulemakings

This category contains records pertaining to public hearings held on proposed changes (PRs) to the Commission's regulations. Hearings are instituted at the discretion of the Commission based on the importance and the magnitude of the subject under consideration. Documents in this category include

- 1. Designations of the presiding officer and any special directions for the conduct of the hearing.
- 2. Notifications of hearing board meetings.
- 3. Petitions, motions, testimony and statements submitted by parties to the hearings.
- 4. Hearing board orders and rulings.
- 5. Technical reports submitted as evidence in the proceeding.
- 6. Reports if any, of the special board to the Commission regarding a rulemaking proceeding.

SECY - Position Papers Before the Commission

This category consists of staff papers prepared for the information or approval of the Commissioners which are assigned a SECY report series code. Included are:

- 1. Commission Action papers, which normally include alternatives and recommendations by the staff on a given issue and require Commission action.
- 2. Consent Calendar items and Policy Session items.

NOTE For Weekly Information Reports prepared by EDO to the Commissioners providing a summary of key events and items of interest undertaken by staff and program offices, see the NRC Commissioners category.

STATE PROG - State Programs

This category contains records that pertain to the Commission's activities and interaction with State governments. Areas covered include. (1) the State Agreements Program, whereby States may assume certain of the NRC's regulatory authority over nuclear materials, (2) the Agency's role in assisting

State and local governments in planning responses to radiological emergencies, and (3) a wide range of haison and cooperative activities regarding such functions as licensing and siting. It includes

- Correspondence between and among NRC Office of State Programs and State officials, mostly State haison officers, regarding.
 - a. cooperative programs in such technical areas as radiation control, emergency response planning to radiological incidents, water quality and transportation surveillance.
 - b technical assistance to Agreement States in reviewing applications, compliance actions, developing regulations, and other areas
- Agendas, reports and transcripts of regional workshops and training programs on current matters of policy and regulations, i.e. decommissioning and facility siting
- 3. State Legislative Reports.
- 4 Agreement State Licensing Statistics Reports

NOTE: For specific uranium milling and mining projects in which the Agency is providing technical assistance to States, see the Projects category

TOPREP - Vendor Reports and Related Correspondence

This category contains topical reports, generally of a technical generic nature, submitted by vendors, and correspondence pertaining to the NRC review of these reports. General vendor related correspondence that is not docket specific is also included in this category

- 1. Topical reports, dealing with such technical matters as specifications, testing and safety submitted by architect, engineers and other vendors.
- 2. Revisions, modifications and amendments to topical reports.
- 3. Correspondence between NRC and vendors pertaining to the review of submittals.
- 4. Meeting agendas, summaries, minutes and correspondence pertinent to vendor activities, programs, methodologies and design criteria

NOTE For reports submitted by utilities that are written by vendors on their behalf and that relate to docketed cases, see the categories for the Docket 50 series.

WASTE MGT - Nuclear Waste Management

This category is topical in nature and contains records dealing with the activities of the NRC Division of Waste Management. Each topic has been assigned a number, with the series designated by a WM prefix. These documents deal primarily with NRC's interaction with DOE and its future role in licensing and regulating DOE facilities designed for the disposal of high-level waste in geologic repositories. This category will be enlarged later to include records dealing with low-level waste issues and tasks. The documents in this category are

- 1. Meeting agenda and minutes of DOE/NRC meetings in which DOE presents information on their geological exploration program to identify sites for nuclear waste repositories.
- 2. Briefings by DOE on research being conducted on spent fuel storage and nuclear waste management.

- 3 Correspondence pertaining to NRC's advisory role in providing DOE with technical assistance in the Waste Isolation Pilot Plan (WIPP) for burial of defense wastes.
- 4. NRC draft staff guides for developing positions on the content and format of environmental reports for geological repositories.

XPORTLIC - Export and Import Licenses

This category contains records relating to the issuance of licenses to export or import nuclear facilities and materials. Included are

- License applications and amendments to export or import special nuclear material, source material, byproduct material, reactors, nuclear facility components or reactor materials.
- 2. Correspondence between NRC and applicant or licensee pertaining to the review or status of a pending application or license amendment.
- 3. Commission letters requesting Executive Branch views.
- 4. Review and findings of the Executive Branch on whether issuance of a license would be inimical to U.S. common defense and security.
- 5. Correspondence from foreign governments, international organizations, and members of the public.
- 6 Staff position papers (SECY series code) prepared for Commissioners review of import or export licenses.
- 7. Filings pursuant to hearing requests or intervention petitions, if any.
- 8 Hearing records and decisions.
- 9. Memoranda from the Office of the Secretary to the Executive Director for Operations regarding the Commission decision on issuance of a proposed license.
- 10. Licenses, license amendments and license renewals for types specified in item 1.

NOTE: For transcripts of Commission meetings and papers submitted for Commissioner consideration or information, see 10CFR category.

NRC FORM 335 U.S NUCLEAR REGULATORY COMMISSION BIBLIOGRAPHIC DATA SHEET		NUREG-054			
4 TITLE AND SUBTITLE (Add Volume No , if appropriate)		2 (Leave blank)	<u> </u>		
Title List of Documents Made Publicly Availab					
March 1-31, 1984	3 RECIPIENT'S A	CCESSION NO			
7 AUTHOR(S)		5 DATE REPORT	COMPLETED		
		молтн	YEAR		
9 PERFORMING ORGANIZATION NAME AND MAILING ADDRESS (Include	e Zip Code)	DATE REPORT	ISSUED		
Division of Technical Information and Documen	MONTH YEAR				
Office of Administration	May 6 (Leave blank)	1984			
U.S. Nuclear Regulatory Commission Washington, DC 20555	G (Ecare Diality)				
		8 (Leave blank)			
12 SPONSORING ORGANIZATION NAME AND MAILING ADDRESS (Includ	e Zip Codel	10 PROJECT/TASK	WORK UNIT NO		
Same as 9, above.		11 FIN NO	<u></u>		
13 TVP OF REPORT	1:	· · · · · · · · · · · · · · · · · · ·			
13 TYPE OF REPORT	PERIOD COVERE				
Monthly	March 1-	31, 1984			
15 SUPPLEMENTARY NOTES		14 (Leave Dlank)			
16 ABSTRACT (200 words or less)	<u></u>				
material associated with civilian nuclear power active materials, and (2) nondocketed material pertinent to its role as a regulatory agency. Personal Author Index, Corporate Source Index, Reference to Principal Documents Index.	l received an The followi	d generated ng indexes a	by NRC re included:		
17 KEY WORDS AND DOCUMENT ANALYSIS	1/A DESCRIPTORS				
17th IDENTIFIERS. OPEN ENDED TERMS					
8 AVAILABILITY STATEMENT		CLASS (I ms report)	21 NO OF PAGES		
Unlimited	Unclass 20 SECURITY C	LASS IT IEU	22 PRICE		